NRC FORM 366
(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N J S G S 2 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)

7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0 1 | REPORT SOURCE L (6) | 0 5 0 0 0 3 1 1 (7) | 0 9 2 9 8 2 (8) | 1 0 2 0 8 2 (9)

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On September 29, 1982, during routine surveillance, it was discovered that No. 2C

0 3 | Vital Bus undervoltage relay failed to drop out on decreasing voltage. The channel

0 4 | was declared inoperable, placed in the tripped condition, and Limiting Condition for

0 5 | Operation 3.3.2.b Action 14 was entered. The redundant undervoltage channels were

0 6 | operable throughout the occurrence. The event constituted operation in a degraded

0 7 | mode in accordance with Technical Specification 6.9.1.9.b.

0 8 | (82-094, 82-031, 82-005, 81-124, 80-011).

7 8 9 80

SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP. SUBCODE | VALVE SUBCODE

0 9 | S H (11) | C (12) | Z (13) | R E L A Y X (14) | D (15) | Z (16)

7 8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER | EVENT YEAR | SEQUENTIAL REPORT NO. | OCCURRENCE CODE | REPORT TYPE | REVISION NO.

8 2 | — | 1 1 8 | / | 0 3 | L | — | 0

21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS (22) | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER

E (18) | C (19) | Z (20) | Z (21) | 0 0 0 0 | Y (23) | Y (24) | A (25) | G 0 8 4 (26)

33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The relay stop lever was found to be out of adjustment. The lever was adjusted, the

1 1 | undervoltage channel was satisfactorily tested and the action statement was terminated.

1 2 | Due to a number of similar occurrences, a new relay is on order and will be installed

1 3 | upon receipt.

1 4 |

7 8 9 80

FACILITY STATUS | % POWER | OTHER STATUS (30) | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION (32)

1 5 | E (28) | 0 8 4 (29) | NA | B (31) | Surveillance Testing

7 8 9 10 12 13 44 45 46 80

ACTIVITY RELEASED | CONTENT OF RELEASE | AMOUNT OF ACTIVITY (35) | LOCATION OF RELEASE (36)

1 6 | Z (33) | Z (34) | NA | NA

7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES: NUMBER | TYPE | DESCRIPTION (39)

1 7 | 0 0 0 (37) | Z (38) | NA

7 8 9 11 12 13 80

PERSONNEL INJURIES: NUMBER | DESCRIPTION (41)

1 8 | 0 0 0 (40) | NA

7 8 9 11 12 80

LOSS OF OR DAMAGE TO FACILITY: TYPE | DESCRIPTION (43)

1 9 | Z (42) | NA

7 8 9 10 80

PUBLICITY: ISSUED | DESCRIPTION (45)

2 0 | N (44) | NA

7 8 9 10 68 69 80

8211060149 821020
PDR ADOCK 05000311
S PDR

NRC USE ONLY

NAME OF PREPARER R. Frahm PHONE 609/935-6000 Ext 3078

G-01 7-926