NRC FORM 366 (12-81)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

APPROVED BY OMB 3150-0011 EXPIRES 4-30-82

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | P A S E S 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T

01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 8 7 (7) | 0 9 2 9 8 2 (8) | 1 0 2 9 8 2 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During startup testing, the Reactor Building Special Particulate Iodine Noble
03 | Gas Monitor pump tripped off and would not restart. This is reportable per
04 | 6.9.1.9.b. No adverse consequences existed in that the proper corrective
05 | actions were taken.
06 |
07 |
08 |

09 | SYSTEM CODE B B (11) | CAUSE CODE E (12) | CAUSE SUBCODE A (13) | COMPONENT CODE M O T O R X (14) | COMP. SUBCODE H (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 2 — SEQUENTIAL REPORT NO. 0 3 3 / OCCURRENCE CODE 0 3 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN B (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0 0 0 0 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER P 0 5 4 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The SPING pump failed due to a motor problem. The motor was sent out to be
11 | rewound. When returned to service, the motor worked properly, however, the
12 | pump required work. The pump was rebuilt and returned to service.
13 |
14 |

15 | FACILITY STATUS B (28) | % POWER 0 0 1 (29) | OTHER STATUS (30) n/a | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) operator observation

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) n/a | LOCATION OF RELEASE (36) n/a

17 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) n/a

18 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) n/a

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) n/a

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) n/a

NRC USE ONLY

8211060352 821029
PDR ADOCK 05000387
S PDR

D.G. Mitchell

PHONE: (717) 542-2181 X524