NRC FORM 366
(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NJSGS2 (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 05000311 (7) | 101082 (8) | 102782 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On October 10, 1982, during routine surveillance, the Control Room Operator dis-
03 covered that service water flow to No. 21 Containment Fan Coil Unit (CFCU) was
04 2400 GPM, less than the 2500 GPM required in low speed operation. No. 21 CFCU was
05 declared inoperable and Action Statement 3.6.2.3.a was entered. Both containment
06 spray systems were operable. The event constituted operation in a degraded mode in
07 accordance with Technical Specification 6.9.1.9.b.
08

09 SYSTEM CODE: SB (11) | CAUSE CODE: C (12) | CAUSE SUBCODE: Z (13) | COMPONENT CODE: INSTRU (14) | COMP. SUBCODE: C (15) | VALVE SUBCODE: Z (16)

(17) LER RO REPORT NUMBER: EVENT YEAR 82 — SEQUENTIAL REPORT NO. 123 — OCCURRENCE CODE 03 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN: E (18) | FUTURE ACTION: H (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS (22): 0000 | ATTACHMENT SUBMITTED: Y (23) | NPRD-4 FORM SUB.: N (24) | PRIME COMP. SUPPLIER: A (25) | COMPONENT MANUFACTURER: F120 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Investigation of the problem revealed that the setpoint on the flow controller at
11 the local service water control panel was low. The controller tested satisfactorily,
12 the setpoint was readjusted to the proper flow, and the action statement was
13 terminated.
14

15 FACILITY STATUS: E (28) | % POWER: 082 (29) | OTHER STATUS (30): NA | METHOD OF DISCOVERY: A (31) | DISCOVERY DESCRIPTION (32): Operator Observation

16 ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): NA | LOCATION OF RELEASE (36): NA

PERSONNEL EXPOSURES
17 NUMBER: 000 (37) | TYPE: Z (38) | DESCRIPTION (39): NA

PERSONNEL INJURIES
18 NUMBER: 000 (40) | DESCRIPTION (41): NA

LOSS OF OR DAMAGE TO FACILITY (43)
19 TYPE: Z (42) | DESCRIPTION: NA

PUBLICITY
20 ISSUED: N (44) | DESCRIPTION (45): NA

8211120389 821027
PDR ADOCK 05000311
S PDR

NRC USE ONLY

NAME OF PREPARER: R. Frahm PHONE: 609/935-6000 Ext 3078