LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 CASO2 (2) 00-00000-00 (3) 4 1 1 1 1 (4) (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T 01 REPORT SOURCE L (6) 05000361 (7) 101082 (8) 110982 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With the plant in Mode 4 during routine Control Room inspection, mainsteam trap
03 isolation valve 2HV-8249 was observed to have lost position indication and was
04 declared inoperable. Since the penetration was isolated by de-energization of the
05 valve to its closed position, there was no impact on health and safety of plant
06 personnel or the public.
07
08

09 SYSTEM CODE SD (11) CAUSE CODE E (12) CAUSE SUBCODE B (13) COMPONENT CODE INSTRU (14) COMP. SUBCODE S (15) VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 — SEQUENTIAL REPORT NO. 126 — OCCURRENCE CODE 03 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN E (18) FUTURE ACTION Z (19) EFFECT ON PLANT Z (20) SHUTDOWN METHOD Z (21) HOURS (22) 0000 ATTACHMENT SUBMITTED N (23) NPRD-4 FORM SUB. N (24) PRIME COMP. SUPPLIER A (25) COMPONENT MANUFACTURER T020 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Loss of position indication was due to loosening of the reed switch assembly 2ZSL-8249-2
11 on the valve stem. The loosening of this magnetic reed switch assembly allowed it to
12 rotate causing the close limit switch to open due to its misalignment. After rotating
13 the assembly to its proper alignment and tightening, the valve was declared operable.
14 As corrective action, all valves of this type will be examined for proper reed switch assembly alignment and tightness.

15 FACILITY STATUS B (28) % POWER 000 (29) OTHER STATUS (30) NA METHOD OF DISCOVERY B (31) DISCOVERY DESCRIPTION (32) Control Room Inspection

16 ACTIVITY RELEASED Z (33) CONTENT OF RELEASE Z (34) AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA

17 PERSONNEL EXPOSURES NUMBER 000 (37) TYPE Z (38) DESCRIPTION (39) NA

18 PERSONNEL INJURIES NUMBER 000 (40) DESCRIPTION (41) NA

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) DESCRIPTION (43) NA

8211190252 821109
PDR ADOCK 05000361
S PDR

20 PUBLICITY ISSUED N (44) DESCRIPTION (45) NA

NRC USE ONLY

NAME OF PREPARER H. B. Ray PHONE 714/492-7700