RC FORM 366.
(-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: |　|　|　|　|　| ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | P | A | B | V | S | 1 ② 0 0 - 0 0 0 0 0 - 0 0 ③ 4 1 1 1 1 ④ |　|　| ⑤
LICENSEE CODE　LICENSE NUMBER　LICENSE TYPE　CAT

CON'T
0 1 REPORT SOURCE L ⑥ 0 5 0 0 0 3 3 4 ⑦ 1 0 1 3 8 2 ⑧ 1 1 0 1 8 2 ⑨
DOCKET NUMBER　EVENT DATE　REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

0 2 | On 10/13/82, Pressurizer Level Channel I indicator (LI-RC-459) was

0 3 | recorded to be out of its 4% tolerance band. In accordance with

0 4 | technical specification 3.3.1.1 the pressurizer high level (Channel I)

0 5 | reactor trip bistable 459A-1 was tripped within 1 hour. There were no

0 6 | safety implications resulting from this incident since a reactor trip

0 7 | signal from this channel would have occurred prior to the actual

0 8 | pressurizer level exceeding its 92% trip setpoint.

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
0 9	I A ⑪	E ⑫	E ⑬	I N S T R U ⑭	T ⑮	Z ⑯

		EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.
⑰	LER/RO REPORT NUMBER	8 2	— 0 4 7	/ 0 3	L	— 0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS ㉒	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
A ⑱	Z ⑲	Z ⑳	Z ㉑	0 0 0 0	Y ㉓	N ㉔	A ㉕	B 0 8 0 ㉖

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ㉗

1 0 | Instrument valve (LT-RC-459-1) was leaking which caused a slight loss of

1 1 | level in the reference leg of (LT-RC-459). This resulted in the

1 2 | differential pressure across the transmitter D/P cell to decrease and the

1 3 | observed level indication to increase. The valve internals were replaced

1 4 | and the channel was returned to service at 1730 hours on 10/18/82.

	FACILITY STATUS	% POWER	OTHER STATUS ㉚	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION ㉜
1 5	E ㉘	0 9 9 ㉙	N/A	A ㉛	Operator Observation

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY ㉟	LOCATION OF RELEASE ㊱
1 6	Z ㉝	Z ㉞	N/A	N/A

	PERSONNEL EXPOSURES NUMBER	TYPE	DESCRIPTION ㊳
1 7	0 0 0 ㊲	Z ㊳	N/A

	PERSONNEL INJURIES NUMBER	DESCRIPTION ㊶
1 8	0 0 0 ㊵	N/A

	LOSS OF OR DAMAGE TO FACILITY ㊸ TYPE	DESCRIPTION
1 9	Z ㊷	N/A

8211230051 821104
PDR ADOCK 05000334
S PDR

	PUBLICITY ISSUED ㊹	DESCRIPTION ㊺
2 0	N ㊹	N/A

NRC USE ONLY

No further information is available or needed to satisfy the reporting requirement.