NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

# LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | M D C C N 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 1 7 (7) | 1 0 0 7 8 2 (8) | 1 1 0 5 8 2 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 1630, during normal operation, reactor protective system channel D
03 trip units for highpower, thermal margin/low pressure and axial shape
04 index were bypassed for corrective maintenance (T.S. 3.3.1.1). Replaced
05 a shorted "Delta T pwr not selected" light bulb and returned all instru-
06 ments to service at 1730. The three redundant channels remained operable
07 during this event. Similar events: none.
08

09 SYSTEM CODE: I A (11) | CAUSE CODE: E (12) | CAUSE SUBCODE: X (13) | COMPONENT CODE: I N S T R U (14) | COMP. SUBCODE: I (15) | VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 2 | — | SEQUENTIAL REPORT NO. 0 5 9 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN: A (18) | FUTURE ACTION: Z (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS (22): 0 0 0 0 | ATTACHMENT SUBMITTED: N (23) | NPRD-4 FORM SUB.: N (24) | PRIME COMP. SUPPLIER: A (25) | COMPONENT MANUFACTURER: G 2 7 2 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Troubleshooting revealed the cause for this event to be a shorted, Delta
11 T power not selected, indicator lamp. The shorted 28VAC lamp via trans-
12 former blew the drawer's 120VAC protective fuse. The lamp was replaced.
13 Since the channel is checked each shift and functionally tested each
14 month, no further preventive action is deemed necessary.

15 FACILITY STATUS: E (28) | % POWER: 1 0 0 (29) | OTHER STATUS (30): N/A | METHOD OF DISCOVERY: A (31) | DISCOVERY DESCRIPTION (32): Operator Observation

16 ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): N/A | LOCATION OF RELEASE (36): N/A

17 PERSONNEL EXPOSURES — NUMBER: 0 0 0 (37) | TYPE: Z (38) | DESCRIPTION (39): N/A

18 PERSONNEL INJURIES — NUMBER: 0 0 0 (40) | DESCRIPTION (41): N/A

19 LOSS OF OR DAMAGE TO FACILITY (43) — TYPE: Z (42) | DESCRIPTION: N/A

20 PUBLICITY — ISSUED: N (44) | DESCRIPTION (45): N/A

8211230139 821105
PDR ADOCK 05000317
S PDR

NRC USE ONLY

NAME OF PREPARER J. S. Lagiewski/J. W. Raynor PHONE: 301-269-4747/4713

GPO 917-926