NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NCBEP2 (2) | 00-000-00 (3) | 41111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 05000-034 (7) | 101982 (8) | 111582 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 Routine surveillance during plant operation revealed control rod 38-39 had simultaneous
03 "full-in" and "full-out" position indication while fully withdrawn. Actual rod
04 position was verified by alternate methods in accordance with technical specifications.
05 This event did not affect the health and safety of the public.
06 Technical Specifications 3.1.3.7, 6.9.1.9b
07
08

09 SYSTEM CODE IB (11) | CAUSE CODE E (12) | CAUSE SUBCODE A (13) | COMPONENT CODE INSTRU (14) | COMP. SUBCODE X (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 — SEQUENTIAL REPORT NO. 114 — OCCURRENCE CODE 03 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER G080 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The duel position indication resulted from a defective IC chip on the rod position
11 indication probe circuitry buffer card input to the rod full-in indication lamp. The
12 defective chip, Model No. PD993659, was replaced and position indication of the rod
13 was returned to normal. As this failure doesn't constitute a safety hazard and occurs
14 occassionally, no further action regarding this event is planned.

15 FACILITY STATUS E (28) | % POWER 065 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator Surveillance

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES
17 NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES
18 NUMBER 000 (40) | DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY (43)
19 TYPE Z (42) | DESCRIPTION NA

PUBLICITY
20 ISSUED N (44) | DESCRIPTION (45)

8211230332 821115
PDR ADOCK 05000324
S PDR

NRC USE ONLY

NAME OF PREPARER M. J. Pastva, Jr. PHONE: 919-457-9521

GPO 917-926