NRC FORM 366 (7-77) Update Report-Previous Report Date 12/1/82

U. S. NUCLEAR REGULATORY COMMISSION

Attachment to AECM-83/0155
Page 1 of 1

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | MSGGS1 (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE (9–14) LICENSE NUMBER (15–25) LICENSE TYPE (26–30) CAT (57–58)

CON'T 01 | REPORT SOURCE L (6) | 05000416 (7) | 102682 (8) | 030783 (9)
DOCKET NUMBER (60–68) EVENT DATE (69–74) REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 In the process of repairing cables in the Control Room, several fire dams were broken.
03 These dams provided a fire barrier between the Control Room and the Computer Room
04 below. An hourly fire watch was established as required by T.S.3.7.7. This event
05 had no effect on the health and safety of the public and did not constitute a threat
06 to plant safety. This report was initially submitted as a Special Report pursuant
07 to T.S.3.7.7.
08

09 SYSTEM CODE AB (11) | CAUSE CODE X (12) | CAUSE SUBCODE Z (13) | COMPONENT CODE ZZZZZZ (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 | — | SEQUENTIAL REPORT NO. 126 | / | OCCURRENCE CODE 99 | REPORT TYPE X | — | REVISION NO. 1

ACTION TAKEN X (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER Z (25) | COMPONENT MANUFACTURER Z999 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The fire barriers were removed to replace a damaged cable. Hourly fire watches
11 were conducted for the duration of the event. The cables were replaced and the
12 fire dams were restored. The penetrations were resealed on December 14, 1982. This
13 is submitted as a final report.
14

15 FACILITY STATUS B (28) | % POWER 000 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Corrective Maintenance

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 PERSONNEL EXPOSURES: NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 PERSONNEL INJURIES: NUMBER 000 (40) | DESCRIPTION (41) NA

19 LOSS OF OR DAMAGE TO FACILITY: TYPE Z (42) | DESCRIPTION (43) NA

20 PUBLICITY: ISSUED N (44) | DESCRIPTION (45) NA

8303160455 830307
PDR ADOCK 05000416
S PDR

NRC USE ONLY

NAME OF PREPARER Matthew V. Rohrer and Boyd Shingleton PHONE:

GPO 917-926