LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | TNSNP1 (2) | 00-00000-00 (3) | 4111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT 58

CON'T
01 | REPORT SOURCE L (6) | 05000327 (7) | 082182 (8) | 091782 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 Unit 1 in mode 1 at 100% power. At 0020 hours on 08/21/82, the axial flux
03 difference (AFD) was discovered to be outside the target band of ±5%. Forty-five
04 minutes of penalty time was accumulated. This caused entry into LCO 3.2.1. There
05 was no effect on public health or safety. Previous occurrences - one (SQRO-50-327/
06 80204).
07
08

09 SYSTEM CODE RC (11) | CAUSE CODE X (12) | CAUSE SUBCODE Z (13) | COMPONENT CODE ZZZZZZ (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 | — | SEQUENTIAL REPORT NO. 106 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN X (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT B (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER Z (25) | COMPONENT MANUFACTURER Z999

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The number three heater drain tank pump (HDTP) tripped causing operators to
11 reduce power manually. An auto turbine runback also occurred and power was reduced
12 to 65%. This caused the AFD to be outside of limits for approximately ten
13 minutes. Action statement requirements were met and AFD was back within the
14 target band at 0105 hours as power was increased and HDTP was restarted.

15 FACILITY STATUS F (28) | % POWER 100 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator observation

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 PERSONNEL EXPOSURES: NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 PERSONNEL INJURIES: NUMBER 000 (40) | DESCRIPTION (41) NA

19 LOSS OF OR DAMAGE TO FACILITY (43): TYPE Z (42) | DESCRIPTION NA

20 PUBLICITY: ISSUED N (44) | DESCRIPTION (45) NA

NRC USE ONLY

8209220227 820917
PDR ADOCK 05000327
S PDR

Name of Preparer: A. M. Carver /M. R. Harding Phone: (615) 751-0349