NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NJSGS1 (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 05000272 (7) | 081682 (8) | 090882 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On August 16, 1982, Westinghouse issued a report to Public Service Electric and Gas
03 (PSE&G) Company of a potential problem associated with the Solid State Protection
04 System (SSPS) in service at Salem Station Units 1 & 2.
05
06
07
08

09 | SYSTEM CODE IA (11) | CAUSE CODE X (12) | CAUSE SUBCODE Z (13) | COMPONENT CODE ZZZZZZ (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER RO REPORT NUMBER: EVENT YEAR 82 — SEQUENTIAL REPORT NO. 064 — OCCURRENCE CODE 03 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN X (18) | FUTURE ACTION G (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER Z (25) | COMPONENT MANUFACTURER Z999 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Nuclear Engineering is evaluating the Westinghouse report for applicability to Salem
11 Station. Upon completion of the evaluation and procedure revisions, a Supplemental
12 Report will be submitted.
13
14

15 | FACILITY STATUS Z (28) | % POWER ZZZ (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY D (31) | DISCOVERY DESCRIPTION (32) Vendor Notification

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

PERSONNEL EXPOSURES
17 | NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

PERSONNEL INJURIES
18 | NUMBER 000 (40) | DESCRIPTION (41) N/A

LOSS OF OR DAMAGE TO FACILITY (43)
19 | TYPE Z (42) | DESCRIPTION N/A

8209220336 820908
PDR ADOCK 05000272
S PDR

PUBLICITY
20 | ISSUED N (44) | DESCRIPTION (45) N/A | NRC USE ONLY

NAME OF PREPARER R. Heller PHONE: 609/935-6000 Ext. 3078

GPO 917-926