Appendix

NOTICE OF VIOLATION

City of Cleveland License No. 34-13574-05

As a result of the inspection conducted on March 4, 1983, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

License Condition No. 14 states that each chromatograph detector cell containing nickel-63 shall be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above, the Hewlett Packard Detector Cell Model No. 2-6195 containing nickel-63 has not been leak tested since at least April 1981, an interval that exceeds six months.

This is a Severity Level V violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

3/17/83
Dated

for S. R. Lasuk
D. J. Sreniawki, Chief
Materials Radition Protection
Section 2

8303220126 830317
NMS LIC30
34-13574-05 PDR