NRC FORM 366
(7 77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N E C P R 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
0 1 | REPORT SOURCE L (6) | 0 5 0 0 0 2 9 8 (7) | 0 2 1 8 8 3 (8) | 0 3 1 7 8 3 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 Tech. Spec. Table 4.2.C (Note 2) to test SRM rod blocks not completed prior to hot
0 3 startup. Due to vagueness of startup procedure, 2.1.2, all the required surveillance
0 4 procedures to conduct hot startup were not specified. No adverse consequences from the
0 5 standpoint of public health and safety resulted from this occurrence.
0 6
0 7
0 8

0 9 | SYSTEM CODE I E (11) | CAUSE CODE D (12) | CAUSE SUBCODE Z (13) | COMPONENT CODE Z Z Z Z Z Z (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 3 | — | SEQUENTIAL REPORT NO. 0 0 2 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN G (18) | FUTURE ACTION H (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER Z (25) | COMPONENT MANUFACTURER Z 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Inadequate procedure resulted in failure to test SRM rod blocks prior to startup as
1 1 required by Table 4.2.C of Technical Specifications. Procedure 2.1.2 revised to remove
1 2 ambiguity and prevent recurrence.
1 3
1 4

1 5 | FACILITY STATUS C (28) | % POWER 0 0 0 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Operator Observation

1 6 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

1 7 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

1 8 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION NA

2 0 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

8303250011 830317
PDR ADOCK 05000298
S PDR

NAME OF PREPARER Keith Wire PHONE 402-825-3811