NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | CAS02 | 00-0000-00 (3) | 41111 (4) | (5)
LICENSEE CODE (14) | LICENSE NUMBER (25) | LICENSE TYPE (30) | CAT (58)

CON'T 01 | REPORT SOURCE L (6) | 05000361 (7) | 091682 (8) | 101582 (9)
DOCKET NUMBER (68) | EVENT DATE (74) | REPORT DATE (80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While in Mode 2 Control Element Assembly (CEA) #47 slipped and dropped in excess
03 of 7 inches (indicated position) in violation of Technical Specification 3.1.3.1.
04 This event has no effect on public health and safety since it did not affect the
05 ability of the CEA to insert into the core whenever required.
06
07
08

09 SYSTEM CODE IA (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE CRDRVE (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 | — | SEQUENTIAL REPORT NO. 115 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN B (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER C490 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of the slippage was due to a defective timing card. The affected solid
11 state chip was replaced. No additional corrective actions are necessary since this
12 was an isolated incident.
13
14

15 FACILITY STATUS B (28) | % POWER 000 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Low Power Physics Testing

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 PERSONNEL EXPOSURES: NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 PERSONNEL INJURIES: NUMBER 000 (40) | DESCRIPTION (41) NA

19 LOSS OF OR DAMAGE TO FACILITY (43): TYPE Z (42) | DESCRIPTION NA

8210250218 821015
PDR ADOCK 05000361
S PDR

20 PUBLICITY: ISSUED N (44) | DESCRIPTION (45) NA

NRC USE ONLY

NAME OF PREPARER H. B. Ray PHONE 714/492-7700