LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 | N Y I P S 2 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

2 | REPORT SOURCE L (6) | 0 5 0 0 0 2 4 7 (7) | 1 0 2 9 8 2 (8) | 1 1 2 8 8 2 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

3 During the ongoing refueling maintenance outage three of the first ten snubbers tested
4 as part of the Hydraulic Snubber Functional Test Program did not meet the acceptance
5 criteria for lock-up rate and bleed. The functional test program is continuing.
6 Previous Events: LER 78-9, LER 80-17.
7
8
9
10

9 | SYSTEM CODE X X (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE S U P O R T (14) | COMP. SUBCODE D (15) | VALVE SUBCODE Z (16)

(17) LER RO REPORT NUMBER: EVENT YEAR 8 2 | — | SEQUENTIAL REPORT NO. 0 4 4 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN X (18) | FUTURE ACTION C (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER B 2 0 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Preliminary results of the Functional Test Program indicated 3 of the first 10 Bergen
11 Patterson Hydraulic Snubbers Model HSSA-3-6, did not meet the acceptance criteria.
12 Defective snubbers will be replaced. A revised LER will be submitted following test
13 program completion indicating the cause of failure and any further corrective actions
14 considered necessary.

15 | FACILITY STATUS H (28) | % POWER 0 0 0 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Surveillance Testing

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION NA (43)

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA

8212080311 821128
PDR ADOCK 05000247
S PDR

NRC USE ONLY

NAME OF PREPARER Garry Hinrichs PHONE: (914) 526-5475

GPO 917-926