NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

Attachment to AECM-82/575
Page 1 of 1

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | M S G G S 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T 01 | REPORT SOURCE L (6) | 0 5 0 0 0 4 1 6 (7) | 1 1 0 2 8 2 (8) | 1 2 0 1 8 2 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (16)

02 While conducting the Division III diesel generator surveillance test on November 2,
03 1982, it was observed that the air start receiver pressure was less than the required
04 175 psig. The plant was in cold shutdown and the suppression pool was drained. This
05 condition constituted entering an LCO per Technical Specification 3.8.1.2. There was
06 no effect on the health and safety of the public. This event did not constitute a threat
07 to plant safety. The LCO was in effect for 30 minutes. This is submitted as an
08 interim report.

09 SYSTEM CODE E E (11) | CAUSE CODE X (12) | CAUSE SUBCODE Z (13) | COMPONENT CODE C K T B R K (14) | COMP. SUBCODE A (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 2 | — | SEQUENTIAL REPORT NO. 1 0 9 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN X (18) | FUTURE ACTION X (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER K 2 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The circuit breaker to the air dryer was open, preventing the compressor from charging
11 the air receiver. The open breaker was closed, allowing the compressor to charge the
12 air receiver to greater than 175 psig. The cause of the breaker being open is unknown.
13 The surveillance procedure was successfully completed. An updated report with results
14 of an investigation on the open breaker will be submitted by February 2, 1983.

15 FACILITY STATUS B (28) | % POWER 0 0 0 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Surveillance Test

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES: NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

17

PERSONNEL INJURIES: NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

18

LOSS OF OR DAMAGE TO FACILITY (43): TYPE Z (42) | DESCRIPTION NA

19

8212090081 821201
PDR ADOCK 05000416
S PDR

PUBLICITY: ISSUED N (44) | DESCRIPTION (45) NA

20

NRC USE ONLY

NAME OF PREPARER Original signed by Matthew V. Rohrer PHONE

GPO 917-926