DCD/DCB

FEB 25 1991

Specialized Imaging Services, Inc.
ATTN: Roger Wheat
Radiation Safety Officer
McRoy Building
1206 E. National Avenue
Brazil, IN 46135

License No. 13-26112-01
Docket No. 030-31322

Gentlemen:

This refers to the routine safety inspection conducted by Mr. D. R. Gibbons of this office on February 11, 1991 of activities authorized by NRC Byproduct Material License No. 13-26112-01 and to the discussion of our findings with Mr. Steven Perkins and you by telephone at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

William H. Schultz, Chief
Nuclear Materials Safety
Section 1

Enclosure: Notice of Violation

cc w/enclosure:
DCD/DCB (RIDS)

RIII
D. Gibbons/cs

RIII
W. Schultz
2-29-91

9103060087 910226
REG3 LIC30
13-26112-01 PDR

IE07