NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

Attachment to AECM-83/0120
Page 1 of 1

CONTROL BLOCK: (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | MSGGS1 (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE (9–14) | LICENSE NUMBER (15–25) | LICENSE TYPE (26–30) | CAT (57–58)

CON'T
01 | REPORT SOURCE L (6) | 05000416 (7) | 011883 (8) | 022383 (9)
DOCKET NUMBER (61–68) | EVENT DATE (69–74) | REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On January 18, 1983, the supervision system for fire rated door 1A211 in the
03 Auxiliary Building and fire rated doors OC103, OC410, and OC706 in the Control
04 Building alarmed with the doors closed. The doors were declared inoperable and fire
05 watches were established in accordance with T.S.3.7.7. The event had no effect on
06 health and safety of the public and did not constitute a threat to plant safety. This
07 is submitted as a Special Report in accordance with T.S.3.7.7.
08

09 SYSTEM CODE AB (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE INSTRU (14) | COMP. SUBCODE S (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 83 | — | SEQUENTIAL REPORT NO. 033 | / | OCCURRENCE CODE 99 | REPORT TYPE X | — | REVISION NO. 0

ACTION TAKEN E (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER P302 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause was due to limit and magnetic switches being out of adjustment. Door OC410,
11 however, was found operable when maintenance personnel investigated. Switches were
12 adjusted, the supervision system was functionally checked, and all doors were
13 restored to operability by January 31, 1983. This is submitted as a final report.
14

15 FACILITY STATUS G (28) | % POWER 000 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Alarmed Condition

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) NA

8303010201 830223
PDR ADOCK 05000416
S PDR

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA

20 PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

NAME OF PREPARER Ron Byrd and Boyd Shingleton PHONE:

GPO 917-926