LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| 0 | 1 | N | C | B | E | P | 2 | (2) | 0 | 0 | – | 0 | 0 | 0 | 0 | 0 | – | 0 | 0 | (3) | 4 | 1 | 1 | 1 | 1 | (4) | (5) |

LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE 30 — 57 CAT 58

CON'T

| 0 | 1 | REPORT SOURCE | L | (6) | 0 | 5 | 0 | – | 0 | 3 | 2 | 4 | (7) | 0 | 1 | 1 | 9 | 8 | 3 | (8) | 0 | 2 | 1 | 8 | 8 | 3 | (9) |

DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

| 0 | 2 | During plant operation, it was discovered that both doors of the Reactor Building 20'

| 0 | 3 | elevation personnel air lock were simultaneously opened. Both doors were immediately

| 0 | 4 | closed and access was restricted through the air lock until the problem was corrected.

| 0 | 5 | This event did not affect the health and safety of the public.

| 0 | 6 |

| 0 | 7 | Technical Specifications 3.6.5.1, 6.9.1.9b

| 0 | 8 |

| 0 | 9 | SYSTEM CODE | S | A | (11) | CAUSE CODE | E | (12) | CAUSE SUBCODE | X | (13) | COMPONENT CODE | P | E | N | E | T | R | (14) | COMP. SUBCODE | A | (15) | VALVE SUBCODE | Z | (16) |

| (17) LER/RO REPORT NUMBER | EVENT YEAR | 8 | 3 | — | SEQUENTIAL REPORT NO. | 0 | 1 | 0 | — | OCCURRENCE CODE | 0 | 3 | REPORT TYPE | L | — | REVISION NO. | 0 |

| ACTION TAKEN | E | (18) | FUTURE ACTION | X | (19) | EFFECT ON PLANT | Z | (20) | SHUTDOWN METHOD | Z | (21) | HOURS | 0 | 0 | 0 | 0 | (22) | ATTACHMENT SUBMITTED | N | (23) | NPRD-4 FORM SUB. | Y | (24) | PRIME COMP SUPPLIER | A | (25) | COMPONENT MANUFACTURER | X | 9 | 9 | 9 | (26) |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

| 1 | 0 | Misalignment of the inner door, attributed to wear from normal use, prevented proper

| 1 | 1 | engagement of the door interlock system bolt whenever the door was closed. The door,

| 1 | 2 | manufactured by Sonic Bar, was adjusted for proper engagement of the interlock system

| 1 | 3 | bolt and was returned to service. No further action regarding this event is planned.

| 1 | 4 |

| 1 | 5 | FACILITY STATUS | E | (28) | % POWER | 0 | 8 | 0 | (29) | OTHER STATUS | NA | (30) | METHOD OF DISCOVERY | A | (31) | DISCOVERY DESCRIPTION (32) | Operational Event |

| 1 | 6 | ACTIVITY RELEASED | Z | (33) | CONTENT OF RELEASE | Z | (34) | AMOUNT OF ACTIVITY (35) | NA | LOCATION OF RELEASE (36) | NA |

| 1 | 7 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | (37) | TYPE | Z | (38) | DESCRIPTION (39) | NA |

| 1 | 8 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | (40) | DESCRIPTION (41) | NA |

| 1 | 9 | LOSS OF OR DAMAGE TO FACILITY (43) TYPE | Z | (42) | DESCRIPTION |

8303010400 830218
PDR ADOCK 05000324
S   PDR

| 2 | 0 | PUBLICITY ISSUED | N | (44) | DESCRIPTION (45) | NA | NRC USE ONLY | | | | | | | | | | | | |

NAME OF PREPARER M. J. Pastva, Jr.   PHONE: 919-457-9521

GPO 917-926