TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401
1750 Chestnut Street Tower II

NRC REGION II
ATLANTA, GEORGIA
83 MAR 7 A11 : 27

March 3, 1983

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street, NW
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE REPORT SQRO-50-327/83021

The enclosed report provides details concerning the failure of one channel of heat tracing of the 4-inch line to the boron injection tank (BIT) and the BIT outlet 1-inch relief line to the holdup tank. This report is submitted in accordance with Sequoyah unit 1 Technical Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. J. Green

H. J. Green
Director of Nuclear Power

Enclosure
cc (Enclosure):
Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Inspector, Sequoyah

8303140548 830303
PDR ADOCK 05000327
S PDR

OFFICIAL COPY

IE 22