LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | TNSNP1 (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 05000327 (7) | 020283 (8) | 030283 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With unit 1 in mode 1 (60% power) at 0747 on 02/02/83, the rod position indicator
03 (RPI) for rod D-14 of shutdown bank A was declared inoperable due to the bottom
04 light going on and off. This required entry into action statement (a) of LCO 3.1.3.
05 There was no effect upon public health and safety. Previous occurrences - two
06 (SQRO-50-328/82032 and SQRO-50-327/80186).
07
08

09 SYSTEM CODE ID (11) | CAUSE CODE X (12) | CAUSE SUBCODE Z (13) | COMPONENT CODE XXXXXX (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 83 — SEQUENTIAL REPORT NO. 019 — OCCURRENCE CODE 03 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN X (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER Z (25) | COMPONENT MANUFACTURE Z99

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Investigation revealed that rod D-14 RPI primary cable circuit was open. This
11 was caused by a loose connector on the reactor head. A 500-volt DC voltage was
12 applied to the primary side which caused the connector to make up. The RPI was
13 returned to service at 1530 CST on 02/02/83. No additional action is planned.
14

15 FACILITY STATUS E (28) | % POWER 060 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator observation

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES
17 NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES
18 NUMBER 000 (40) | DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY (43)
19 TYPE Z (42) | DESCRIPTION NA

PUBLICITY
20 ISSUED N (44) | DESCRIPTION (45) NA

8303210308 830302
PDR ADOCK 05000327
S PDR

NRC USE ONLY

Name of Preparer: D. A. Kulisek /M. R. Harding Phone: (615) 751-0349