NUREG-0540
Vol. 5, No. 3

# Title List of Documents Made Publicly Available

March 1-31, 1983

Office of Administration
U.S. Nuclear Regulatory Commission

8307110275 830630
PDR NUREG
0540 R PDR

Available from

NRC/GPO Sales Program

Superintendent of Documents
Government Printing Office
Washington, D. C. 20402

A year's subscription consists of 12 issues for
this publication.

Single copies of this publication
are available from National Technical
Information Service, Springfield, VA 22161

Microfiche of single copies are
available from NRC/GPO Sales Program
Washington, D. C. 20555

NUREG-0540
Vol. 5, No. 3

# Title List of Documents Made Publicly Available

March 1-31, 1983

Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

## CONTENTS


Preface ..... v
Arrangement of Items by Docket Number ..... ix
Alphabetic Arrangement of Docket Items by Facility Name ..... xv
Docketed Items
- Low Level Radwaste Disposal Sites — Docket 27 ..... 1
- Domestic Licensing of Source Material — Docket 40 ..... 2
- Domestic Licensing of Production and Utilization Facilities — Docket 50 ..... 9
- Domestic Licensing of Special Nuclear Material — Docket 70 ..... 442
- Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71 ..... 452
- Licensing of Independent Spent Fuel Storage — Docket 72 ..... 459

Nondocketed Items
- 10 CFR — Commission Meeting Records ..... 461
- ACRS — Advisory Committee on Reactor Safeguards ..... 462
- COMMISSION — NRC Commissioners ..... 463
- CONTRACT — NRC Contracts and Modifications ..... 464
- FOIA — Freedom of Information Act Requests and Releases ..... 473
- GEN TECH IS — Generic Technical Issues ..... 482
- I&E — Inspection and Enforcement ..... 482
- MISC — Public Document Room Miscellaneous ..... 484
- NUREG — NUREG Reports and Related Correspondence ..... 484
- ORG — Correspondence with Other Organizations ..... 489
- PR — Proposed Rule ..... 490
- PRM — Petition for Rulemaking ..... 491
- PROJ — Projects - Predocket Licensing ..... 491
- PT 21 — Noncompliance Reports and Related Correspondence ..... 492
- QA999 — Quality Assurance Inspections ..... 492
- REGGD — Regulatory Guides ..... 497
- RES — Research and Technical Assistance Reports ..... 497
- REVIEW GROUP — NRC Research Review Groups ..... 499
- SECY — Position Papers Before the Commission ..... 500
- STATE PROG — State Programs ..... 501
- TOPREP — Vendor Reports and Related Correspondence ..... 505
- WASTE MGT — Nuclear Waste Management ..... 508
- XPORTLIC — Export and Import Licenses ..... 514

Personal Author Index ..... 523
Corporate Source Index ..... 561
Report Number Index ..... 599
- Cross Reference of Enclosures to Principal Documents ..... 603

Appendix A — Definitions of Docket 50 Categories ..... A-1
Appendix B — Definitions of Nondocketed Categories ..... B-1

## PREFACE

The *Title List of Documents Made Publicly Available* is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, *docketed* does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

### DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

A. Application/construction stage documents and correspondence
B. Utility Preliminary Safety Analysis Report (PSAR), amendments
C. Utility Environmental Report (ER), amendments and correspondence
D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
E. NRC Safety Evaluation Report (SER), supplements and correspondence
F. Security, medical, emergency and fire-protection plans
G. Adjudicatory correspondence
H. General correspondence
I. Financial information
J. Insurance and indemnity information
K. Utility Final Safety Analysis Report (FSAR) and amendments
L. Limited work authorization and related correspondence
M. Antitrust correspondence
N. Antitrust hearing transcripts
O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
P. Operating license stage documents and correspondence
Q. Inspection reports, IE Bulletins and correspondence
R. Periodic operating reports and related correspondence
S. Reportable occurrences, LERs and related correspondence
T. Hearing transcripts on non-antitrust matters
U. Congressional/executive correspondence
V. Licensing operators and related correspondence

W. Decommissioning stage documents and correspondence
X. Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

(1) P. Operating license stage documents & correspondence

(2) (3)
8203090028 Responds to 820201 ltr requesting documents re environ qualification of electrical equipment. All nonproprietary repts will be provided to Franklin Research Ctr by 820408. Proprietary repts will be provided to NRC by 820510.
(4) MILLS, L.M. (5) Tennessee Valley Authority. (6) 82/03/04. (7) VASSALLO, D.B. Operating Reactors Branch 2. (8) 1p. 1216:254. 24XFiche: 50-259, 82/03/04, 8203090028.

(12) (9) (10) (11)

1. NRC/PDR Document category (see Appendix A).
2. NRC Accession Number (year, month, day, and sequence number of item).
3. Description of information contained in the document.
4. Personal author(s). An asterisk in this position indicates that there is no personal author.
5. Corporate, agency or nonindividual source.
6. Date of document described.
7. Recipient of document and NRC or corporate affiliation.
8. Pages in this document.
9. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
10. This three-digit portion of this entry is the number of the frame on which this document starts.
11. The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
12. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

**NONDOCKETED ITEMS**

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISCLOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases
GEN TECH IS — Generic Technical Issues

I&E — Inspection and Enforcement
MISC — Public Document Room Miscellaneous
NUREG — NUREG Reports and Related Correspondence
ORG — Correspondence with Other Organizations
PR — Proposed Rule
PRM — Petition for Rulemaking
PROJ — Projects—Predocket Licensing
PT21 — Noncompliance Reports and Related Correspondence
QA999 — Quality Assurance Inspections
REGGD — Regulatory Guides
RES — Research and Technical Assistance Reports
REVIEW GRP — NRC Research Review Groups
RM — Rulemakings
SECY — Position Papers Before the Commission
STATE PROG — State Programs
TOPREP — Vendor Reports and Related Correspondence
WASH — Regulatory Publications—Pre-NUREG Series
WASTE MGT — Nuclear Waste Management
XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:




1. Nondocketed category
2. NRC Accession Number (year, month, day, and sequence number of item)
3. NRC Report Number
4. Title and description of information contained in the document
5. Personal author(s). An asterisk in this position indicates that there is no personal author.
6. Corporate, agency or other nonindividual source.
7. Contract or financial (FIN) number (if any). If the document has a sceondary report number, it will appear following this entry.
8. Secondary report number assigned by originator.
9. Date of document described.
10. NRC organizational recipient.
11. Pages in document.
12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
13. Price for which NRC sells the document.

14. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
15. This three-digit portion of this entry is the number of the frame on which this document starts.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

   Director
   Division of Technical Information and Document Control
   U.S. Nuclear Regulatory Commission
   Washington, D.C. 20555

   To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

   National Technical Information Service
   Springfield, Virginia 22161

   To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order.

3. The address for the PDR is:

   1717 H Street, N.W.
   Washington, D.C. 20555

   To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

   Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is $0.05 per page except for oversized documents and engineering drawings, which vary from $0.50 to $1.00 per square foot; (2) microform to paper is $0.05 a page for pages on microfiche and is $0.20 a square foot for a full-size print or $0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is $0.10 per microfiche and $0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials.

   Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018.

# ARRANGEMENT OF ITEMS BY DOCKET NUMBER


| Docket | Name | Page |
|---|---|---|
| **Low Level Radwaste Disposal Sites — Docket 27** | | |
| 27-039 | Sheffield, IL, U.S. Ecology, Inc. | 1 |
| 27-047 | Barnwell, SC, Chem-Nuclear Systems, Inc. | 1 |
| 27-048 | Richland, WA, U.S. Ecology, Inc. | 1 |
| **Domestic Licensing of Source Material — Docket 40** | | |
| 40-0017 | Dow Chemical Co., Midland, MI | 2 |
| 40-0086 | W. R. Grace & Co., Pompton Plains, NJ | 2 |
| 40-0299 | Union Carbide Corp., Grand Junction, CO | 2 |
| 40-1162 | Western Nuclear, Inc., Jeffrey City, WY | 2 |
| 40-1341 | Tennessee Valley Authority, Chattanooga, TN | 3 |
| 40-1478 | Spencer Chemical Co., Kansas City, MO | 3 |
| 40-2061 | Kerr-McGee Chemical Corp., Oklahoma City, OK | 3 |
| 40-2259 | Pathfinder Mines Corp., Riverton, WY | 4 |
| 40-3453 | Atlas Mineral, Inc., Denver, CO | 4 |
| 40-4492 | Federal-American Partners, Riverton, WY | 4 |
| 40-6622 | Pathfinder Mines Corp., Shirley Basin, WY | 5 |
| 40-6659 | Getty Oil Co. — Petrotomics Co., Shirley Basin, WY | 5 |
| 40-6940 | Kawecki Berylco Industries Inc., Boyertown, PA | 5 |
| 40-7097 | Molycorp, Inc., White Plains, NY | 5 |
| 40-7138 | Yankee Atomic Electric Co., Westborough, MA | 5 |
| 40-7455 | Whittaker Metals, Los Angeles, CA | 5 |
| 40-7869 | Plateau Resources, Ltd., Grand Junction, CO | 5 |
| 40-8027 | Kerr-McGee Nuclear Corp., Oklahoma City, OK | 5 |
| 40-8064 | Exxon Minerals Co. USA, Houston, TX | 5 |
| 40-8084 | Rio Algom Corp., Moab, UT | 6 |
| 40-8102 | Exxon Co. USA, Houston, TX | 6 |
| 40-8452 | Bear Creek Uranium Co., Casper, WY | 6 |
| 40-8502 | Wyoming Mineral Corp., Lakewood, CO | 6 |
| 40-8578 | TRI-Weld, Inc., Cleveland, OH | 6 |
| 40-8584 | Minerals Exploration Co., Los Angeles, CA | 6 |
| 40-8585 | Wyoming Mineral Corp., Lakewood, CO | 6 |
| 40-8602 | Silver King Mines, Inc., Casper, WY | 6 |
| 40-8663 | Nuclear Dynamics, Inc., Phoenix, AZ | 7 |
| 40-8674 | Plateau Resources, Ltd., Grand Junction, CO | 7 |
| 40-8681 | Energy Fuels Nuclear, Inc., Denver, CO | 7 |
| 40-8698 | Plateau Resources, Ltd., Grand Junction, CO | 7 |
| 40-8713 | Navy, Dept. of, San Diego, CA | 7 |
| 40-8714 | Cleveland-Cliffs Iron Co., Cleveland, OH | 8 |
| 40-8722 | Brush Wellman, Inc., Cleveland, OH | 8 |
| 40-8724 | Chemetron Corp., Chicago, IL | 8 |
| 40-8728 | Teton Exploration Drilling Co., Inc., Casper, WY | 8 |
| 40-8743 | Conoco, Inc., Denver, CO | 8 |
| 40-8745 | Ogle Petroleum, Inc., Casper, WY | 8 |
| 40-8752 | Pinal Minerals & Mining, Ltd., Miami, AZ | 9 |
| 40-8768 | Kerr-McGee Nuclear Corp., Oklahoma City, OK | 9 |
| 40-8773 | Precise Tool & Die Co., Wickliffe, OH | 9 |
| 40-8783 | Uranerz USA, Inc., Casper WY | 9 |
| 40-8786 | Uranium Resources, Inc., Richardson, TX | 9 |
| 40-8820 | Amax Environmental Services, Inc., Golden, CO | 9 |
| 40-8829 | Wyoming Fuel Co., Lakewood, CO | 9 |
| **Domestic Licensing of Production and Utilization Facilities — Docket 50** | | |
| 50-2 | Univ. of Michigan Research Reactor | 9 |
| 50-3 | Indian Point Station, Unit 1 | 9 |
| 50-10 | Dresden Nuclear Power Station, Unit 1 | 10 |
| 50-16 | Enrico Fermi Atomic Power Plant, Unit 1 | 12 |
| 50-18 | Vallecitos Boiling Water Reactor | 12 |

| Docket | Name | Page |
|---|---|---|
| 50-20 | Massachusetts Institute of Technology Research Reactor | 12 |
| 50-29 | Yankee-Rowe Nuclear Power Station | 12 |
| 50-30 | Plum Brook Research Reactor Facility | 15 |
| 50-54 | Union Carbide Research Reactor | 15 |
| 50-57 | State Univ. of New York Research Reactor | 15 |
| 50-59 | Texas A&M Univ. Research Reactor | 16 |
| 50-70 | General Electric Test Reactor | 16 |
| 50-72 | Univ. of Utah Research Reactor | 16 |
| 50-73 | General Electric Nuclear Test Reactor | 16 |
| 50-77 | Catholic Univ. of America Research Reactor | 16 |
| 50-83 | Univ. of Florida Training Reactor | 16 |
| 50-87 | Westinghouse Critical Experiment | 17 |
| 50-111 | North Carolina State Univ. Research Reactor | 17 |
| 50-112 | Univ. of Oklahoma Research Reactor | 17 |
| 50-124 | Virginia Polytech Institute Training Reactor | 17 |
| 50-128 | Texas A&M Univ. Research Reactor | 17 |
| 50-131 | Omaha Veterans Administration Hospital Research Reactor | 18 |
| 50-133 | Humboldt Bay Power Plant, Unit 3 | 18 |
| 50-141 | Stanford Univ. Research Reactor | 18 |
| 50-142 | UCLA Training Reactor | 19 |
| 50-146 | Saxton Nuclear Experimental Facility | 19 |
| 50-151 | Univ. of Illinois Research Reactor | 19 |
| 50-155 | Big Rock Point Nuclear Plant | 20 |
| 50-170 | National Naval Medical Center | 22 |
| 50-171 | Peach Bottom Atomic Power Station, Unit 1 | 23 |
| 50-183 | Vallecitos Experimental Superheat Reactor | 23 |
| 50-184 | National Bureau of Standards Reactor | 23 |
| 50-185 | Plum Brook Reactor — Mock-Up | 23 |
| 50-186 | Univ. of Missouri Research Reactor | 23 |
| 50-187 | Space Radiation Research Reactor | 24 |
| 50-192 | Univ. of Texas Research Reactor | 24 |
| 50-193 | Rhode Island & Providence Plantations AEC | 24 |
| 50-201 | West Valley Reprocessing Plant | 24 |
| 50-206 | San Onofre Nuclear Station, Unit 1 | 24 |
| 50-213 | Haddam Neck Plant | 28 |
| 50-219 | Oyster Creek Nuclear Power Plant | 31 |
| 50-220 | Nine Mile Point Nuclear Station, Unit 1 | 33 |
| 50-224 | Univ. of California Research Reactor | 35 |
| 50-225 | RPI Critical Experiment | 35 |
| 50-237 | Dresden Nuclear Power Station, Unit 2 | 35 |
| 50-241 | Mississippi State Univ. Research Reactor | 38 |
| 50-244 | Robert Emmet Ginna Nuclear Plant, Unit 1 | 39 |
| 50-245 | Millstone Nuclear Power Station, Unit 1 | 41 |
| 50-247 | Indian Point Station, Unit 2 | 45 |
| 50-249 | Dresden Nuclear Power Station, Unit 3 | 51 |
| 50-250 | Turkey Point Plant, Unit 3 | 53 |
| 50-251 | Turkey Point Plant, Unit 4 | 57 |
| 50-254 | Quad-Cities Station, Unit 1 | 61 |
| 50-255 | Palisades Nuclear Plant | 65 |
| 50-259 | Browns Ferry Nuclear Power Station, Unit 1 | 67 |
| 50-260 | Browns Ferry Nuclear Power Station, Unit 2 | 70 |
| 50-261 | H. B. Robinson Plant, Unit 2 | 72 |
| 50-263 | Monticello Nuclear Generating Plant | 75 |
| 50-265 | Quad-Cities Station, Unit 2 | 78 |
| 50-266 | Point Beach Nuclear Plant, Unit 1 | 81 |
| 50-267 | Fort St. Vrain Nuclear Generating Station | 84 |
| 50-269 | Oconee Nuclear Station, Unit 1 | 87 |
| 50-270 | Oconee Nuclear Station, Unit 2 | 90 |
| 50-271 | Vermont Yankee Nuclear Power Station | 92 |
| 50-272 | Salem Nuclear Generating Station, Unit 1 | 95 |
| 50-275 | Diablo Canyon Nuclear Power Plant, Unit 1 | 100 |
| 50-277 | Peach Bottom Atomic Power Station, Unit 2 | 105 |
| 50-278 | Peach Bottom Atomic Power Station, Unit 3 | 109 |
| 50-280 | Surry Power Station, Unit 1 | 113 |
| 50-281 | Surry Power Station, Unit 2 | 116 |
| 50-282 | Prairie Island Nuclear Station, Unit 1 | 120 |
| 50-285 | Fort Calhoun Station, Unit 1 | 122 |
| 50-286 | Indian Point Station, Unit 3 | 124 |
| 50-287 | Oconee Nuclear Station, Unit 3 | 130 |
| 50-288 | Reed College Research Reactor | 133 |
| 50-289 | Three Mile Island Nuclear Station, Unit 1 | 133 |

| Docket | Name | Page |
|---|---|---|
| 50-293 | Pilgrim Nuclear Power Station, Unit 1 | 139 |
| 50-294 | Michigan State Univ. Research Reactor | 141 |
| 50-295 | Zion Nuclear Power Station, Unit 1 | 141 |
| 50-296 | Browns Ferry Nuclear Power Station, Unit 3 | 145 |
| 50-297 | North Carolina State Univ. PULSTAR Reactor | 147 |
| 50-298 | Cooper Nuclear Station | 147 |
| 50-301 | Point Beach Nuclear Plant, Unit 2 | 149 |
| 50-302 | Crystal River Nuclear Plant, Unit 3 | 152 |
| 50-304 | Zion Nuclear Power Station, Unit 2 | 155 |
| 50-305 | Kewaunee Nuclear Power Plant | 159 |
| 50-306 | Prairie Island Nuclear Station, Unit 2 | 161 |
| 50-309 | Maine Yankee Atomic Power Plant | 163 |
| 50-311 | Salem Nuclear Generating Station, Unit 2 | 166 |
| 50-312 | Rancho Seco Nuclear Generating Station | 169 |
| 50-313 | Arkansas Nuclear One, Unit 1 | 172 |
| 50-315 | Donald C. Cook Nuclear Power Plant, Unit 1 | 178 |
| 50-316 | Donald C. Cook Nuclear Power Plant, Unit 2 | 181 |
| 50-317 | Calvert Cliffs Nuclear Power Plant, Unit 1 | 184 |
| 50-318 | Calvert Cliffs Nuclear Power Plant, Unit 2 | 187 |
| 50-320 | Three Mile Island Nuclear Station, Unit 2 | 190 |
| 50-321 | Edwin I. Hatch Nuclear Plant, Unit 1 | 193 |
| 50-322 | Shoreham Nuclear Power Station | 197 |
| 50-323 | Diablo Canyon Nuclear Power Plant, Unit 2 | 203 |
| 50-324 | Brunswick Steam Electric Plant, Unit 2 | 205 |
| 50-325 | Brunswick Steam Electric Plant, Unit 1 | 208 |
| 50-327 | Sequoyah Nuclear Plant, Unit 1 | 211 |
| 50-328 | Sequoyah Nuclear Plant, Unit 2 | 214 |
| 50-329 | Midland Plant, Unit 1 | 218 |
| 50-330 | Midland Plant, Unit 2 | 223 |
| 50-331 | Duane Arnold Energy Center | 229 |
| 50-332 | Barnwell Reprocessing Plant | 232 |
| 50-333 | James A. Fitzpatrick Nuclear Power Plant | 232 |
| 50-334 | Beaver Valley Power Station, Unit 1 | 234 |
| 50-335 | St. Lucie Plant, Unit 1 | 237 |
| 50-336 | Millstone Nuclear Power Station, Unit 2 | 240 |
| 50-338 | North Anna Power Station, Unit 1 | 244 |
| 50-339 | North Anna Power Station, Unit 2 | 246 |
| 50-341 | Enrico Fermi Atomic Power Plant, Unit 2 | 249 |
| 50-344 | Trojan Nuclear Plant | 251 |
| 50-346 | Davis-Besse Nuclear Power Station, Unit 1 | 253 |
| 50-348 | Joseph M. Farley Nuclear Plant, Unit 1 | 257 |
| 50-352 | Limerick Generating Station, Unit 1 | 260 |
| 50-353 | Limerick Generating Station, Unit 2 | 264 |
| 50-354 | Hope Creek Nuclear Station, Unit 1 | 266 |
| 50-355 | Hope Creek Nuclear Station, Unit 2 | 268 |
| 50-358 | William H. Zimmer Nuclear Station, Unit 1 | 269 |
| 50-361 | San Onofre Nuclear Station, Unit 2 | 272 |
| 50-362 | San Onofre Nuclear Station, Unit 3 | 277 |
| 50-364 | Joseph M. Farley Nuclear Plant, Unit 2 | 282 |
| 50-366 | Edwin I. Hatch Nuclear Plant, Unit 2 | 285 |
| 50-367 | Bailly Generating Station | 288 |
| 50-368 | Arkansas Nuclear One, Unit 2 | 288 |
| 50-369 | William B. McGuire Nuclear Station, Unit 1 | 293 |
| 50-370 | William B. McGuire Nuclear Station, Unit 2 | 296 |
| 50-373 | LaSalle County Station, Unit 1 | 299 |
| 50-374 | LaSalle County Station, Unit 2 | 303 |
| 50-375 | Nuclear Examination Reactor | 306 |
| 50-382 | Waterford Generating Station, Unit 3 | 306 |
| 50-387 | Susquehanna Steam Electric Station, Unit 1 | 310 |
| 50-388 | Susquehanna Steam Electric Station, Unit 2 | 315 |
| 50-389 | St. Lucie Plant, Unit 2 | 317 |
| 50-390 | Watts Bar Nuclear Plant, Unit 1 | 321 |
| 50-391 | Watts Bar Nuclear Plant, Unit 2 | 324 |
| 50-395 | Virgil C. Summer Nuclear Station, Unit 1 | 327 |
| 50-397 | WPPSS Nuclear Project, Unit 2 | 331 |
| 50-400 | Shearon Harris Nuclear Power Plant, Unit 1 | 334 |
| 50-401 | Shearon Harris Nuclear Power Plant, Unit 2 | 337 |
| 50-409 | La Crosse Boiling Water Reactor | 341 |
| 50-410 | Nine Mile Point Nuclear Station, Unit 2 | 342 |
| 50-412 | Beaver Valley Power Station, Unit 2 | 343 |
| 50-413 | Catawba Nuclear Station, Unit 1 | 344 |
| 50-414 | Catawba Nuclear Station, Unit 2 | 347 |

| Docket | Name | Page |
|---|---|---|
| 50-416 | Grand Gulf Nuclear Station, Unit 1 | 350 |
| 50-417 | Grand Gulf Nuclear Station, Unit 2 | 355 |
| 50-423 | Millstone Nuclear Power Station, Unit 3 | 357 |
| 50-424 | Alvin W. Vogtle Nuclear Plant, Unit 1 | 358 |
| 50-425 | Alvin W. Vogtle Nuclear Plant, Unit 2 | 359 |
| 50-426 | Alvin W. Vogtle Nuclear Plant, Unit 3 | 360 |
| 50-427 | Alvin W. Vogtle Nuclear Plant, Unit 4 | 360 |
| STN-50-437 | Floating Nuclear Plant | 360 |
| 50-438 | Bellefonte Nuclear Plant, Unit 1 | 361 |
| 50-439 | Bellefonte Nuclear Plant, Unit 2 | 363 |
| 50-440 | Perry Nuclear Power Plant, Unit 1 | 364 |
| 50-441 | Perry Nuclear Power Plant, Unit 2 | 368 |
| 50-443 | Seabrook Nuclear Station, Unit 1 | 372 |
| 50-444 | Seabrook Nuclear Station, Unit 2 | 377 |
| 50-445 | Comanche Peak Steam Electric Station, Unit 1 | 382 |
| 50-446 | Comanche Peak Steam Electric Station, Unit 2 | 386 |
| STN-50-447 | GESSAR-238 | 390 |
| STN-50-454 | Byron Station, Unit 1 | 391 |
| STN-50-455 | Byron Station, Unit 2 | 395 |
| STN-50-456 | Braidwood Station, Unit 1 | 399 |
| STN-50-457 | Braidwood Station, Unit 2 | 401 |
| 50-458 | River Bend Station, Unit 1 | 403 |
| 50-459 | River Bend Station, Unit 2 | 405 |
| 50-460 | WPPSS Nuclear Project, Unit 1 | 407 |
| 50-461 | Clinton Power Station, Unit 1 | 408 |
| 50-462 | Clinton Power Station, Unit 2 | 410 |
| STN-50-470 | CESSAR System 80 | 410 |
| 50-471 | Pilgrim Nuclear Power Station, Unit 2 | 411 |
| STN-50-482 | Wolf Creek Generating Station | 411 |
| STN-50-483 | Callaway Plant, Unit 1 | 414 |
| STN-50-486 | Callaway Plant, Unit 2 | 416 |
| STN-50-488 | Perkins Nuclear Station, Unit 1 | 416 |
| STN-50-489 | Perkins Nuclear Station, Unit 2 | 416 |
| STN-50-490 | Perkins Nuclear Station, Unit 3 | 416 |
| STN-50-491 | Cherokee Nuclear Station, Unit 1 | 416 |
| 50-496 | Montague Nuclear Power Station, Unit 1 | 416 |
| 50-497 | Montague Nuclear Power Station, Unit 2 | 417 |
| STN-50-498 | South Texas Project, Unit 1 | 417 |
| STN-50-499 | South Texas Project, Unit 2 | 418 |
| 50-500 | Davis-Besse Nuclear Power Station, Unit 2 | 420 |
| 50-501 | Davis-Besse Nuclear Power Station, Unit 3 | 420 |
| STN-50-508 | WPPSS Nuclear Project, Unit 3 | 420 |
| STN-50-509 | WPPSS Nuclear Project, Unit 5 | 422 |
| 50-510 | Blue Hills Station, Unit 1 | 422 |
| 50-511 | Blue Hills Station, Unit 2 | 422 |
| 50-513 | WPPSS Nuclear Project, Unit 4 | 422 |
| 50-514 | Pebble Springs Nuclear Plant, Unit 1 | 422 |
| 50-515 | Pebble Springs Nuclear Plant, Unit 2 | 422 |
| STN-50-518 | Hartsville Nuclear Plant, Unit 1 | 423 |
| STN-50-519 | Hartsville Nuclear Plant, Unit 2 | 423 |
| STN-50-520 | Hartsville Nuclear Plant, Unit 3 | 423 |
| STN-50-521 | Hartsville Nuclear Plant, Unit 4 | 423 |
| 50-522 | Skagit Nuclear Power Project, Unit 1 | 423 |
| 50-523 | Skagit Nuclear Power Project, Unit 2 | 424 |
| STN-50-528 | Palo Verde Nuclear Station, Unit 1 | 425 |
| STN-50-529 | Palo Verde Nuclear Station, Unit 2 | 428 |
| STN-50-530 | Palo Verde Nuclear Station, Unit 3 | 432 |
| 50-537 | Clinch River Breeder Reactor | 435 |
| 50-538 | Memphis State Univ. Research Reactor | 437 |
| STN-50-546 | Marble Hill Nuclear Station, Unit 1 | 437 |
| STN-50-547 | Marble Hill Nuclear Station, Unit 2 | 439 |
| STN-50-556 | Black Fox Station, Unit 1 | 440 |
| STN-50-557 | Black Fox Station, Unit 2 | 441 |
| STN-50-566 | Yellow Creek Nuclear Plant, Unit 1 | 441 |
| STN-50-567 | Yellow Creek Nuclear Plant, Unit 2 | 442 |
| STN-50-592 | Palo Verde Nuclear Station, Unit 4 | 442 |
| STN-50-599 | Carroll Facility I | 442 |
| STN-50-600 | Carroll Facility II | 442 |

**Domestic Licensing of Special Nuclear Material — Docket 70**

| | | |
|---|---|---|
| 70-0025 | Rockwell International Corp., Canoga Park, CA | 442 |
| 70-0027 | Babcock & Wilcox Co., Lynchburg, VA | 442 |
| 70-0033 | Texas Instruments, Inc., Attleboro, MA | 443 |
| 70-0036 | Combustion Engineering, Inc., Windsor, CT | 443 |
| 70-0053 | Yale Univ., New Haven, CT | 443 |
| 70-0113 | Pennsylvania State Univ., University Park, PA | 443 |

| Docket | Name | Page |
|---|---|---|
| 70-0124 | Teledyne Isotopes, Inc., Westwood, NJ | 443 |
| 70-0135 | Babcock & Wilcox Co., Apollo, PA | 443 |
| 70-0143 | Nuclear Fuel Services, Inc., Erwin, TN | 444 |
| 70-0146 | Spencer Chemical Co., Kansas City, MO | 445 |
| 70-0359 | Pittsburgh, Univ. of, Pittsburgh, PA | 445 |
| 70-0364 | Babcock & Wilcox Co., Apollo, PA | 446 |
| 70-0371 | UNC Naval Products, Inc., Uncasville, CT | 446 |
| 70-0553 | Army, Dept. of, Sacramento, CA | 446 |
| 70-0734 | GA Technologies, Inc., San Diego, CA | 446 |
| 70-0754 | General Electric Co., Pleasanton, CA | 447 |
| 70-0820 | United Nuclear Corp., Wood River Junction, RI | 447 |
| 70-0824 | Babcock & Wilcox Co., Lynchburg, VA | 447 |
| 70-1062 | Todd Shipyards Corp., Galveston, TX | 448 |
| 70-1100 | Combustion Engineering, Inc., Windsor, CT | 448 |
| 70-1113 | General Electric Co., Wilmington, NC | 448 |
| 70-1143 | Westinghouse Electric Corp., Pittsburgh, PA | 448 |
| 70-1151 | Westinghouse Electric Corp., Pittsburgh, PA | 448 |
| 70-1193 | Kerr-McGee Nuclear Corp., Oklahoma City, OK | 449 |
| 70-1201 | Babcock & Wilcox Co., Lynchburg, VA | 449 |
| 70-1216 | Navy, Dept. of, San Diego, CA | 449 |
| 70-1257 | Exxon Nuclear Co., Inc., Richland, WA | 449 |
| 70-1308 | General Electric Co., San Jose, CA | 449 |
| 70-1507 | Henry Ford Hospital, Detroit, MI | 450 |
| 70-1621 | Duquesne Light Co., Pittsburgh, PA | 450 |
| 70-2322 | Edlow International Co., Washington, DC | 450 |
| 70-2684 | Baystate Medical Center, Springfield, MA | 450 |
| 70-2786 | General Electric Co., San Jose, CA | 450 |
| 70-2837 | Morningside College, Sioux City, IA | 450 |
| 70-2910 | Tennessee Valley Authority, Chattanooga, TN | 450 |
| 70-2917 | Tennessee Valley Authority, Chattanooga, TN | 450 |
| 70-2920 | Alabama Power Co., Birmingham, AL | 450 |
| 70-2926 | Detroit Edison Co., Detroit, MI | 450 |
| 70-2928 | Tennessee Valley Authority, Chattanooga, TN | 451 |
| 70-2932 | Texas Utilities Generating Co., Dallas, TX | 451 |
| 70-2941 | Tennessee Valley Authority, Chattanooga, TN | 451 |
| 70-2945 | Union Electric Co., St. Louis, MO | 451 |
| 70-2946 | Louisiana Power & Light Co., New Orleans, LA | 451 |
| 70-2949 | Arizona Public Service Co., Phoenix, AZ | 451 |
| 70-2950 | Washington Public Power Supply System, Richland, WA | 451 |
| 70-2957 | Florida Power & Light Co., Miami, FL | 451 |
| 70-2960 | Kansas Gas & Electric Co., Wichita, KS | 452 |
| 70-2964 | Consumers Power Co., Jackson, MI | 452 |
| 70-2965 | Consumers Power Co., Jackson, MI | 452 |
| 70-2968 | Cleveland Electric Illuminating Co., Cleveland, OH | 452 |

**Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71**

| | | |
|---|---|---|
| 71-0004 | General Electric Co. | 452 |
| 71-0086 | Alpha-Omega Services, Inc. | 452 |
| 71-0423 | H & H X-Ray Services, Inc. | 452 |
| 71-0492 | California Polytechnic State Univ. | 452 |
| 71-4909 | Model: GE 21PF-1, General Electric Co. | 452 |
| 71-4986 | Model: RA-2, RA-3, RA-J, General Electric Co. | 452 |
| 71-5026 | Model: CNS 14-190, Chem-Nuclear Systems, Inc. | 452 |
| 71-5088 | Model: D34710-1, D34710-2, Rockwell International | 453 |
| 71-5364 | Model: NPI-67-0442, Neutron Products, Inc. | 453 |
| 71-5450 | Model: RCC, -1, -2, -3, -4, Westinghouse Electric Corp. | 453 |
| 71-5580 | Model: S5W Power Unit, Energy, Dept. of | 453 |
| 71-5757 | Model: S5W, Refuel Srce, Energy, Dept. of | 453 |
| 71-5758 | Model: S5W, Energy, Dept. of | 453 |
| 71-5796 | Model: 181375, 181361, Advanced Medical Systems, Inc. | 453 |
| 71-5805 | Model: CNS-3-55, Chem-Nuclear Systems, Inc. | 453 |
| 71-5874 | Model: WAPD-40, Energy, Dept. of | 453 |
| 71-5939 | Model: GE-1500, General Electric Co. | 453 |
| 71-5942 | Model: GE-700, General Electric Co. | 453 |
| 71-6002 | Model: S3W/S4W New Sub, Energy, Dept. of | 453 |
| 71-6058 | Model: B-3, U.S. Ecology | 453 |
| 71-6144 | Model: B-2, U.S. Ecology | 453 |
| 71-6244 | Model: 6244, Chem-Nuclear Systems, Inc. | 453 |

| Docket | Name | Page |
|---|---|---|
| 71-6272 | Model: 6272, U.S. Ecology | 454 |
| 71-6294 | Model: UNC-2901, Combustion Engineering Co., Inc. | 454 |
| 71-6346 | Model: FSV-1, General Atomic Co. | 454 |
| 71-6375 | Model: CNS 4-45, Chem-Nuclear Systems, Inc. | 454 |
| 71-6387 | Model: 60, Battelle Memorial Institute, Pacific Northwest Lab | 454 |
| 71-6568 | Model: LL-60-150, Tennessee Valley Authority | 454 |
| 71-6574 | Model: HN-200, Hittman Nuclear & Development Corp. | 454 |
| 71-6601 | Model: CNS 8-120, Chem-Nuclear Systems, Inc. | 454 |
| 71-6639 | Model: MH-1A, Army, Dept. of | 454 |
| 71-6642 | Model: 4.5 Ton CF, Energy, Dept. of | 454 |
| 71-6679 | Model: 6679, U.S. Ecology | 454 |
| 71-6698 | Model: NFS-4, Nuclear Fuel Services, Inc. | 454 |
| 71-6717 | Model: 6717-B, Gamma Industries | 455 |
| 71-6722 | Model: BS-33-180, Tennessee Valley Authority | 455 |
| 71-6744 | Model: 6744, U.S. Ecology | 455 |
| 71-9001 | Model: IF-300, General Electric Co. | 455 |
| 71-9006 | Model: 500-SU, Automation Industries, Inc. | 455 |
| 71-9010 | Model: NLI-1/2, NL Industries, Inc. | 455 |
| 71-9015 | Model: TN-8, -8L, No Users | 455 |
| 71-9033 | Model: 660 & 660E, Technical Operations, Inc. | 455 |
| 71-9044 | Model: GE-1600, General Electric Co. | 456 |
| 71-9070 | Model: N-55, Energy, Dept. of | 456 |
| 71-9071 | Model: AP-101, ANEFCO, Inc. | 456 |
| 71-9073 | Model: OH-142, Nuclear Packaging, Inc. | 456 |
| 71-9074 | Model: AP-100, ANEFCO, Inc. | 456 |
| 71-9079 | Model: HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp. | 456 |
| 71-9080 | Model: 9080, Hittman Nuclear & Development Corp. | 456 |
| 71-9081 | Model: CNSI 1-13C, Chem-Nuclear Systems, Inc. | 456 |
| 71-9086 | Model: HN-100, Series 1, Hittman Nuclear & Development Corp. | 456 |
| 71-9089 | Model: HN-100S, Hittman Nuclear & Development Corp. | 457 |
| 71-9092 | Model: HN-300, Hittman Nuclear & Development Corp. | 457 |
| 71-9093 | Model: HN-400, Hittman Nuclear & Development Corp. | 457 |
| 71-9094 | Model: CNS 14-195-H, Chem-Nuclear Systems, Inc. | 457 |
| 71-9096 | Model: CNS 21-300, Chem-Nuclear Systems, Inc. | 457 |
| 71-9101 | Model: CNSI-1-184-409, Chem-Nuclear Systems, Inc. | 457 |
| 71-9105 | Model: Rad-Waste CR. I, Chem-Nuclear Systems, Inc. | 457 |
| 71-9108 | Model: AL-33-90, Chem-Nuclear Systems, Inc. | 457 |
| 71-9111 | Model: CNS 6-80-2, Chem-Nuclear Systems, Inc. | 458 |
| 71-9119 | Model: BAPL 5910 BRDCG, Energy, Dept. of | 458 |
| 71-9122 | Model: 18-450, Chem-Nuclear Systems, Inc. | 458 |
| 71-9133 | Model: C-10, Gamma Industries | 458 |
| 71-9138 | Model: 78-D-1458, Navy, Dept. of | 458 |
| 71-9139 | Model: 589, General Electric Co. | 458 |
| 71-9144 | Model: SGC-1, Chem-Nuclear Systems, Inc. | 458 |
| 71-9151 | Model: HN-100, Series 3, Hittman Nuclear & Development Corp. | 458 |
| 71-9152 | Model: CNS 1-13CII, Chem-Nuclear Systems, Inc. | 458 |
| 71-9159 | Model: NUPAC Series A, Nuclear Packing, Inc. | 458 |
| 71-9160 | Model: 20-VS & 40-VS, Gulf Nuclear, Inc. | 458 |
| 71-9161 | Model: R, Gulf Nuclear, Inc. | 459 |
| 71-9162 | Model: GNM-20, Gulf Nuclear, Inc. | 459 |
| 71-9163 | Model: GNG-20, Gulf Nuclear, Inc. | 459 |
| 71-9166 | Model: 864, Type B, Technical Operations, Inc. | 459 |
| 71-9167 | Model: 3206B, 3227B & 3218, Amersham Corp. | 459 |
| 71-9783 | Model: S5W, ITR, Energy, Dept. of | 459 |
| 71-9855 | Model: ORNL DOT Spec 6M Special Form Package, Energy, Dept. of | 459 |

**Licensing of Independent Spent Fuel Storage**

| | | |
|---|---|---|
| 72-0001 | Morris Operations, General Electric Co. | 459 |
| 72-0002 | Virginia Electric & Power Co. | 460 |

# ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME


| Name | Docket | Page |
|---|---|---|
| **Low Level Radwaste Disposal Sites — Docket 27** | | |
| Barnwell, SC, Chem-Nuclear Systems, Inc. | 27-047 | 1 |
| Richland, WA, U.S. Ecology, Inc. | 27-048 | 1 |
| Sheffield, IL, U.S. Ecology, Inc. | 27-039 | 1 |
| **Domestic Licensing of Source Material — Docket 40** | | |
| Amax Environmental Services, Inc., Golden, CO | 40-8820 | 9 |
| Atlas Mineral, Inc., Denver, CO | 40-3453 | 4 |
| Bear Creek Uranium Co., Casper, WY | 40-8452 | 6 |
| Brush Wellman, Inc., Cleveland, OH | 40-8722 | 8 |
| Chemetron Corp., Chicago, IL | 40-8724 | 8 |
| Cleveland-Cliffs Iron Co., Cleveland, OH | 40-8714 | 8 |
| Conoco, Inc., Denver, CO | 40-8743 | 8 |
| Dow Chemical Co., Midland, MI | 40-0017 | 2 |
| Energy Fuels Nuclear, Inc., Denver, CO | 40-8681 | 7 |
| Exxon Co., USA, Houston, TX | 40-8102 | 6 |
| Exxon Minerals Co., USA, Houston, TX | 40-8064 | 5 |
| Federal-American Partners, Riverton, WY | 40-4492 | 4 |
| Getty Oil Co. — Petrotomics Co., Shirley Basin, WY | 40-6659 | 5 |
| Kawecki Berylco Industries, Inc., Boyertown, PA | 40-6940 | 5 |
| Kerr-McGee Chemical Corp., Oklahoma City, OK | 40-2061 | 3 |
| Kerr-McGee Nuclear Corp., Oklahoma City, OK | 40-8027 | 5 |
| Kerr McGee Nuclear Corp., Oklahoma City, OK | 40-8768 | 9 |
| Minerals Exploration Co., Los Angeles, CA | 40-8584 | 6 |
| Molycorp, Inc., White Plains, NY | 40-7097 | 5 |
| Navy, Dept. of, San Diego, CA | 40-8713 | 7 |
| Nuclear Dynamics, Inc., Phoenix, AZ | 40-8663 | 7 |
| Ogle Petroleum, Inc., Casper, WY | 40-8745 | 8 |
| Pathfinder Mines Corp., Riverton, WY | 40-2259 | 4 |
| Pathfinder Mines Corp., Shirley Basin, WY | 40-6622 | 5 |
| Pinal Minerals & Mining, Ltd., Miami, AZ | 40-8752 | 9 |
| Plateau Resources, Ltd., Grand Junction, CO | 40-7869 | 5 |
| Plateau Resources, Ltd., Grand Junction, CO | 40-8674 | 7 |
| Plateau Resources, Ltd., Grand Junction, CO | 40-8698 | 7 |
| Precise Tool & Die Co., Wickliffe, OH | 40-8773 | 9 |
| Rio Algom Corp., Moab, UT | 40-8084 | 6 |
| Silver King Mines, Inc., Casper, WY | 40-8602 | 6 |
| Spencer Chemical Co., Kansas City, MO | 40-1478 | 3 |
| Tennessee Valley Authority, Chattanooga, TN | 40-1341 | 3 |
| Teton Exploration Drilling Co., Inc., Casper, WY | 40-8728 | 8 |
| TRI-Weld, Inc., Cleveland, OH | 40-8578 | 6 |
| Union Carbide Corp., Grand Junction, CO | 40-0299 | 2 |
| Uranerz USA, Inc., Casper, WY | 40-8783 | 9 |
| Uranium Resources, Inc., Richardson, TX | 40-8786 | 9 |
| W. R. Grace & Co., Pompton Plains, NJ | 40-0086 | 2 |
| Western Nuclear, Inc., Jeffrey City, WY | 40-1162 | 2 |
| Whittaker Metals, Los Angeles, CA | 40-7455 | 5 |
| Wyoming Fuel Co., Lakewood, CO | 40-8829 | 9 |
| Wyoming Mineral Corp., Lakewood, CO | 40-8502 | 6 |
| Wyoming Mineral Corp., Lakewood, CO | 40-8585 | 6 |
| Yankee Atomic Electric Co., Westborough, MA | 40-7138 | 5 |
| **Domestic Licensing of Production and Utilization Facilities — Docket 50** | | |
| Alvin W. Vogtle Nuclear Plant, Unit 1 | 50-424 | 358 |
| Alvin W. Vogtle Nuclear Plant, Unit 2 | 50-425 | 359 |

| Name | Docket | Page |
|---|---|---|
| Alvin W. Vogtle Nuclear Plant, Unit 3 | 50-426 | 360 |
| Alvin W. Vogtle Nuclear Plant, Unit 4 | 50-427 | 360 |
| Arkansas Nuclear One, Unit 1 | 50-313 | 172 |
| Arkansas Nuclear One, Unit 2 | 50-368 | 288 |
| Bailly Generating Station | 50-367 | 288 |
| Barnwell Reprocessing Plant | 50-332 | 232 |
| Beaver Valley Power Station, Unit 1 | 50-334 | 234 |
| Beaver Valley Power Station, Unit 2 | 50-412 | 343 |
| Bellefonte Nuclear Plant, Unit 1 | 50-438 | 361 |
| Bellefonte Nuclear Plant, Unit 2 | 50-439 | 363 |
| Big Rock Point Nuclear Plant | 50-155 | 20 |
| Black Fox Station, Unit 1 | STN-50-556 | 440 |
| Black Fox Station, Unit 2 | STN-50-557 | 441 |
| Blue Hills Station, Unit 1 | 50-510 | 422 |
| Blue Hills Station, Unit 2 | 50-511 | 422 |
| Braidwood Station, Unit 1 | STN-50-456 | 399 |
| Braidwood Station, Unit 2 | STN-50-457 | 401 |
| Browns Ferry Nuclear Power Station, Unit 1 | 50-259 | 67 |
| Browns Ferry Nuclear Power Station, Unit 2 | 50-260 | 70 |
| Browns Ferry Nuclear Power Station, Unit 3 | 50-296 | 145 |
| Brunswick Steam Electric Plant, Unit 1 | 50-325 | 208 |
| Brunswick Steam Electric Plant, Unit 2 | 50-324 | 205 |
| Byron Station, Unit 1 | STN-50-454 | 391 |
| Byron Station, Unit 2 | STN-50-455 | 395 |
| Callaway Plant, Unit 1 | STN-50-483 | 414 |
| Callaway Plant, Unit 2 | STN-50-486 | 416 |
| Calvert Cliffs Nuclear Power Plant, Unit 1 | 50-317 | 184 |
| Calvert Cliffs Nuclear Power Plant, Unit 2 | 50-318 | 187 |
| Carroll Facility I | STN-50-599 | 442 |
| Carroll Facility II | STN-50-600 | 442 |
| Catawba Nuclear Station, Unit 1 | 50-413 | 344 |
| Catawba Nuclear Station, Unit 2 | 50-414 | 347 |
| Catholic Univ. of America Research Reactor | 50-77 | 16 |
| CESSAR System 80 | STN-50-470 | 410 |
| Cherokee Nuclear Station, Unit 1 | STN-50-491 | 416 |
| Clinch River Breeder Reactor | 50-537 | 435 |
| Clinton Power Station, Unit 1 | 50-461 | 408 |
| Clinton Power Station, Unit 2 | 50-462 | 410 |
| Comanche Peak Steam Electric Station, Unit 1 | 50-445 | 382 |
| Comanche Peak Steam Electric Station, Unit 2 | 50-446 | 386 |
| Cooper Nuclear Station | 50-298 | 147 |
| Crystal River Nuclear Plant, Unit 3 | 50-302 | 152 |
| Davis-Besse Nuclear Power Station, Unit 1 | 50-346 | 253 |
| Davis-Besse Nuclear Power Station, Unit 2 | 50-500 | 420 |
| Davis-Besse Nuclear Power Station, Unit 3 | 50-501 | 420 |
| Diablo Canyon Nuclear Power Plant, Unit 1 | 50-275 | 100 |
| Diablo Canyon Nuclear Power Plant, Unit 2 | 50-323 | 203 |
| Donald C. Cook Nuclear Power Plant, Unit 1 | 50-315 | 178 |
| Donald C. Cook Nuclear Power Plant, Unit 2 | 50-316 | 181 |
| Dresden Nuclear Power Station, Unit 1 | 50-10 | 10 |
| Dresden Nuclear Power Station, Unit 2 | 50-237 | 35 |
| Dresden Nuclear Power Station, Unit 3 | 50-249 | 51 |
| Duane Arnold Energy Center | 50-331 | 229 |
| Edwin I. Hatch Nuclear Plant, Unit 1 | 50-321 | 193 |
| Edwin I. Hatch Nuclear Plant, Unit 2 | 50-366 | 285 |
| Enrico Fermi Atomic Power Plant, Unit 1 | 50-16 | 12 |
| Enrico Fermi Atomic Power Plant, Unit 2 | 50-341 | 249 |
| Floating Nuclear Plant | STN-50-437 | 360 |
| Fort Calhoun Station, Unit 1 | 50-285 | 122 |
| Fort St. Vrain Nuclear Generating Station | 50-267 | 84 |
| General Electric Nuclear Test Reactor | 50-73 | 16 |
| General Electric Test Reactor | 50-70 | 16 |
| GESSAR-238 | STN-50-447 | 390 |
| Grand Gulf Nuclear Station, Unit 1 | 50-416 | 350 |
| Grand Gulf Nuclear Station, Unit 2 | 50-417 | 355 |
| H. B. Robinson Plant, Unit 2 | 50-261 | 72 |
| Haddam Neck Plant | 50-213 | 28 |
| Hartsville Nuclear Plant, Unit 1 | STN-50-518 | 423 |
| Hartsville Nuclear Plant, Unit 2 | STN-50-519 | 423 |
| Hartsville Nuclear Plant, Unit 3 | STN-50-520 | 423 |
| Hartsville Nuclear Plant, Unit 4 | STN-50-521 | 423 |
| Hope Creek Nuclear Station, Unit 1 | 50-354 | 266 |

| Name | Docket | Page |
|---|---|---|
| Hope Creek Nuclear Station, Unit 2 | 50-355 | 268 |
| Humboldt Bay Power Plant, Unit 3 | 50-133 | 18 |
| Indian Point Station, Unit 1 | 50-3 | 9 |
| Indian Point Station, Unit 2 | 50-247 | 45 |
| Indian Point Station, Unit 3 | 50-286 | 124 |
| James A. Fitzpatrick Nuclear Power Plant | 50-333 | 232 |
| Joseph M. Farley Nuclear Plant, Unit 1 | 50-348 | 257 |
| Joseph M. Farley Nuclear Plant, Unit 2 | 50-364 | 282 |
| Kewaunee Nuclear Power Plant | 50-305 | 159 |
| La Crosse Boiling Water Reactor | 50-409 | 341 |
| LaSalle County Station, Unit 1 | 50-373 | 299 |
| LaSalle County Station, Unit 2 | 50-374 | 303 |
| Limerick Generating Station, Unit 1 | 50-352 | 260 |
| Limerick Generating Station, Unit 2 | 50-353 | 264 |
| Maine Yankee Atomic Power Plant | 50-309 | 163 |
| Marble Hill Nuclear Station, Unit 1 | STN-50-546 | 437 |
| Marble Hill Nuclear Station, Unit 2 | STN-50-547 | 439 |
| Massachusetts Institute of Technology Research Reactor | 50-20 | 12 |
| Memphis State Univ. Research Reactor | 50-538 | 437 |
| Michigan State Univ. Research Reactor | 50-294 | 141 |
| Midland Plant, Unit 1 | 50-329 | 218 |
| Midland Plant, Unit 2 | 50-330 | 223 |
| Millstone Nuclear Power Station, Unit 1 | 50-245 | 41 |
| Millstone Nuclear Power Station, Unit 2 | 50-336 | 240 |
| Millstone Nuclear Power Station, Unit 3 | 50-423 | 357 |
| Mississippi State Univ. Research Reactor | 50-241 | 38 |
| Montague Nuclear Power Station, Unit 1 | 50-496 | 416 |
| Montague Nuclear Power Station, Unit 2 | 50-497 | 417 |
| Monticello Nuclear Generating Plant | 50-263 | 75 |
| National Bureau of Standards Reactor | 50-184 | 23 |
| National Naval Medical Center | 50-170 | 22 |
| Nine Mile Point Nuclear Station, Unit 1 | 50-220 | 33 |
| Nine Mile Point Nuclear Station, Unit 2 | 50-410 | 342 |
| North Anna Power Station, Unit 1 | 50-338 | 244 |
| North Anna Power Station, Unit 2 | 50-339 | 246 |
| North Carolina State Univ. PULSTAR Reactor | 50-297 | 147 |
| North Carolina State Univ. Research Reactor | 50-111 | 17 |
| Nuclear Examination Reactor | 50-375 | 306 |
| Oconee Nuclear Station, Unit 1 | 50-269 | 87 |
| Oconee Nuclear Station, Unit 2 | 50-270 | 90 |
| Oconee Nuclear Station, Unit 3 | 50-287 | 130 |
| Omaha Veterans Administration Hospital Research Reactor | 50-131 | 18 |
| Oyster Creek Nuclear Power Plant | 50-219 | 31 |
| Palisades Nuclear Plant | 50-255 | 65 |
| Palo Verde Nuclear Station, Unit 1 | STN-50-528 | 425 |
| Palo Verde Nuclear Station, Unit 2 | STN-50-529 | 428 |
| Palo Verde Nuclear Station, Unit 3 | STN-50-530 | 432 |
| Palo Verde Nuclear Station, Unit 4 | STN-50-592 | 442 |
| Peach Bottom Atomic Power Station, Unit 1 | 50-171 | 23 |
| Peach Bottom Atomic Power Station, Unit 2 | 50-277 | 105 |
| Peach Bottom Atomic Power Station, Unit 3 | 50-278 | 109 |
| Pebble Springs Nuclear Plant, Unit 1 | 50-514 | 422 |
| Pebble Springs Nuclear Plant, Unit 2 | 50-515 | 422 |
| Perkins Nuclear Station, Unit 1 | STN-50-488 | 416 |
| Perkins Nuclear Station, Unit 2 | STN-50-489 | 416 |
| Perkins Nuclear Station, Unit 3 | STN-50-490 | 416 |
| Perry Nuclear Power Plant, Unit 1 | 50-440 | 364 |
| Perry Nuclear Power Plant, Unit 2 | 50-441 | 368 |
| Pilgrim Nuclear Power Station, Unit 1 | 50-293 | 139 |
| Pilgrim Nuclear Power Station, Unit 2 | 50-471 | 411 |
| Plum Brook Reactor — Mock-Up | 50-185 | 23 |
| Plum Brook Research Reactor Facility | 50-30 | 15 |
| Point Beach Nuclear Plant, Unit 1 | 50-266 | 81 |
| Point Beach Nuclear Plant, Unit 2 | 50-301 | 149 |
| Prairie Island Nuclear Station, Unit 1 | 50-282 | 120 |
| Prairie Island Nuclear Station, Unit 2 | 50-306 | 161 |
| Quad-Cities Station, Unit 1 | 50-254 | 61 |
| Quad-Cities Station, Unit 2 | 50-265 | 78 |
| Rancho Seco Nuclear Generating Station | 50-312 | 169 |
| Reed College Research Reactor | 50-288 | 133 |
| Rhode Island & Providence Plantations AEC | 50-193 | 24 |
| River Bend Station, Unit 1 | 50-458 | 403 |

| Name | Docket | Page |
|---|---|---|
| River Bend Station, Unit 2 | 50-459 | 405 |
| Robert Emmet Ginna Nuclear Plant, Unit 1 | 50-244 | 39 |
| RPI Critical Experiment | 50-225 | 35 |
| Salem Nuclear Generating Station, Unit 1 | 50-272 | 95 |
| Salem Nuclear Generating Station, Unit 2 | 50-311 | 166 |
| San Onofre Nuclear Station, Unit 1 | 50-206 | 24 |
| San Onofre Nuclear Station, Unit 2 | 50-361 | 272 |
| San Onofre Nuclear Station, Unit 3 | 50-362 | 277 |
| Saxton Nuclear Experimental Facility | 50-146 | 19 |
| Seabrook Nuclear Station, Unit 1 | 50-443 | 372 |
| Seabrook Nuclear Station, Unit 2 | 50-444 | 377 |
| Sequoyah Nuclear Plant, Unit 1 | 50-327 | 211 |
| Sequoyah Nuclear Plant, Unit 2 | 50-328 | 214 |
| Shearon Harris Nuclear Power Plant, Unit 1 | 50-400 | 334 |
| Shearon Harris Nuclear Power Plant, Unit 2 | 50-401 | 337 |
| Shoreham Nuclear Power Station | 50-322 | 197 |
| Skagit Nuclear Power Project, Unit 1 | 50-522 | 423 |
| Skagit Nuclear Power Project, Unit 2 | 50-523 | 424 |
| South Texas Project, Unit 1 | STN-50-498 | 417 |
| South Texas Project, Unit 2 | STN-50-499 | 418 |
| Space Radiation Research Reactor | 50-187 | 24 |
| St. Lucie Plant, Unit 1 | 50-335 | 237 |
| St. Lucie Plant, Unit 2 | 50-389 | 317 |
| Stanford Univ. Research Reactor | 50-141 | 18 |
| State Univ. of New York Research Reactor | 50-57 | 15 |
| Surry Power Station, Unit 1 | 50-280 | 113 |
| Surry Power Station, Unit 2 | 50-281 | 116 |
| Susquehanna Steam Electric Station, Unit 1 | 50-387 | 310 |
| Susquehanna Steam Electric Station, Unit 2 | 50-388 | 315 |
| Texas A&M Univ. Research Reactor | 50-128 | 17 |
| Texas A&M Univ. Research Reactor | 50-59 | 16 |
| Three Mile Island Nuclear Station, Unit 1 | 50-289 | 133 |
| Three Mile Island Nuclear Station, Unit 2 | 50-320 | 190 |
| Trojan Nuclear Plant | 50-344 | 251 |
| Turkey Point Plant, Unit 3 | 50-250 | 53 |
| Turkey Point Plant, Unit 4 | 50-251 | 57 |
| UCLA Training Reactor | 50-142 | 19 |
| Union Carbide Research Reactor | 50-54 | 15 |
| Univ. of California Research Reactor | 50-224 | 35 |
| Univ. of Florida Training Reactor | 50-83 | 16 |
| Univ. of Illinois Research Reactor | 50-151 | 19 |
| Univ. of Michigan Research Reactor | 50-2 | 9 |
| Univ. of Missouri Research Reactor | 50-186 | 23 |
| Univ. of Oklahoma Research Reactor | 50-112 | 17 |
| Univ. of Texas Research Reactor | 50-192 | 24 |
| Univ. of Utah Research Reactor | 50-72 | 16 |
| Vallecitos Boiling Water Reactor | 50-18 | 12 |
| Vallecitos Experimental Superheat Reactor | 50-183 | 23 |
| Vermont Yankee Nuclear Power Station | 50-271 | 92 |
| Virgil C. Summer Nuclear Station, Unit 1 | 50-395 | 327 |
| Virginia Polytech Institute Training Reactor | 50-124 | 17 |
| Waterford Generating Station, Unit 3 | 50-382 | 306 |
| Watts Bar Nuclear Plant, Unit 1 | 50-390 | 321 |
| Watts Bar Nuclear Plant, Unit 2 | 50-391 | 324 |
| West Valley Reprocessing Plant | 50-201 | 24 |
| Westinghouse Critical Experiment | 50-87 | 17 |
| William B. McGuire Nuclear Station, Unit 1 | 50-369 | 293 |
| William B. McGuire Nuclear Station, Unit 2 | 50-370 | 296 |
| William H. Zimmer Nuclear Station, Unit 1 | 50-358 | 269 |
| Wolf Creek Generating Station | STN-50-482 | 411 |
| WPPSS Nuclear Project, Unit 1 | 50-460 | 407 |
| WPPSS Nuclear Project, Unit 2 | 50-397 | 331 |
| WPPSS Nuclear Project, Unit 3 | STN-50-508 | 420 |
| WPPSS Nuclear Project, Unit 4 | 50-513 | 422 |
| WPPSS Nuclear Project, Unit 5 | STN-50-509 | 422 |
| Yankee-Rowe Nuclear Power Station | 50-29 | 12 |
| Yellow Creek Nuclear Plant, Unit 1 | STN-50-566 | 441 |
| Yellow Creek Nuclear Plant, Unit 2 | STN-50-567 | 442 |
| Zion Nuclear Power Station, Unit 1 | 50-295 | 141 |
| Zion Nuclear Power Station, Unit 2 | 50-304 | 155 |

| Name | Docket | Page |
|---|---|---|
| **Domestic Licensing of Special Nuclear Material — Docket 70** | | |
| Alabama Power Co., Birmingham, AL | 70-2920 | 450 |
| Arizona Public Service Co., Phoenix, AZ | 70-2949 | 451 |
| Army, Dept. of, Sacramento, CA | 70-0553 | 446 |
| Babcock & Wilcox Co., Apollo, PA | 70-0135 | 443 |
| Babcock & Wilcox Co., Apollo, PA | 70-0364 | 446 |
| Babcock & Wilcox Co., Lynchburg, VA | 70-0824 | 447 |
| Babcock & Wilcox Co., Lynchburg, VA | 70-1201 | 449 |
| Babcock & Wilcox Co., Lynchburg, VA | 70-0027 | 442 |
| Baystate Medical Center, Springfield, MA | 70-2684 | 450 |
| Cleveland Electric Illuminating Co., Cleveland, OH | 70-2968 | 452 |
| Combustion Engineering, Inc., Windsor, CT | 70-1100 | 448 |
| Combustion Engineering, Inc., Windsor, CT | 70-0036 | 443 |
| Consumers Power Co., Jackson, MI | 70-2964 | 452 |
| Consumers Power Co., Jackson, MI | 70-2965 | 452 |
| Detroit Edison Co., Detroit, MI | 70-2926 | 450 |
| Duquesne Light Co., Pittsburgh, PA | 70-1621 | 450 |
| Edlow International Co., Washington, DC | 70-2322 | 450 |
| Exxon Nuclear Co., Inc., Richland, WA | 70-1257 | 449 |
| Florida Power & Light Co., Miami, FL | 70-2957 | 451 |
| GA Technologies, Inc., San Diego, CA | 70-0734 | 446 |
| General Electric Co., Pleasanton, CA | 70-0754 | 447 |
| General Electric Co., San Jose, CA | 70-2786 | 450 |
| General Electric Co., San Jose, CA | 70-1308 | 449 |
| General Electric Co., Wilmington, NC | 70-1113 | 448 |
| Henry Ford Hospital, Detroit, MI | 70-1507 | 450 |
| Kansas Gas & Electric Co., Wichita, KS | 70-2960 | 452 |
| Kerr-McGee Nuclear Corp., Oklahoma City, OK | 70-1193 | 449 |
| Louisiana Power & Light Co., New Orleans, LA | 70-2946 | 451 |
| Morningside College, Sioux City, IA | 70-2837 | 450 |
| Navy, Dept. of, San Diego, CA | 70-1216 | 449 |
| Nuclear Fuel Services, Inc., Erwin, TN | 70-0143 | 444 |
| Pennsylvania State Univ., University Park, PA | 70-0113 | 443 |
| Pittsburgh, Univ. of, Pittsburgh, PA | 70-0359 | 445 |
| Rockwell International Corp., Canoga Park, CA | 70-0025 | 442 |
| Spencer Chemical Co., Kansas City, MO | 70-0146 | 445 |
| Teledyne Isotopes, Inc., Westwood, NJ | 70-0124 | 443 |
| Tennessee Valley Authority, Chattanooga, TN | 70-2928 | 451 |
| Tennessee Valley Authority, Chattanooga, TN | 70-2910 | 450 |
| Tennessee Valley Authority, Chattanooga, TN | 70-2941 | 451 |
| Tennessee Valley Authority, Chattanooga, TN | 70-2917 | 450 |
| Texas Instruments, Inc., Attleboro, MA | 70-0033 | 443 |
| Texas Utilities Generating Co., Dallas, TX | 70-2932 | 451 |
| Todd Shipyards Corp., Galveston, TX | 70-1062 | 448 |
| UNC Naval Products, Inc., Uncasville, CT | 70-0371 | 446 |
| Union Electric Co., St. Louis, MO | 70-2945 | 451 |
| United Nuclear Corp., Wood River Junction, RI | 70-0820 | 447 |
| Washington Public Power Supply System, Richland, WA | 70-2950 | 451 |
| Westinghouse Electric Corp., Pittsburgh, PA | 70-1143 | 448 |
| Westinghouse Electric Corp., Pittsburgh, PA | 70-1151 | 448 |
| Yale Univ., New Haven, CT | 70-0053 | 443 |
| **Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71** | | |
| Alpha-Omega Services, Inc. | 71-0086 | 452 |
| California Polytechnic State Univ. | 71-0492 | 452 |
| General Electric Co. | 71-0004 | 452 |
| H & H X-Ray Services, Inc. | 71-0423 | 452 |
| Model: 18-450, Chem-Nuclear Systems, Inc. | 71-9122 | 458 |
| Model: 181375, 181361, Advanced Medical Systems, Inc. | 71-5796 | 453 |
| Model: 20-VS & 40-VS, Gulf Nuclear, Inc. | 71-9160 | 458 |
| Model: 3206B, 3227B & 3218, Amersham Corp. | 71-9167 | 459 |
| Model: 4.5 Ton CF, Energy, Dept. of | 71-6642 | 454 |
| Model: 500-SU, Automation Industries, Inc. | 71-9006 | 455 |
| Model: 589, General Electric Co. | 71-9139 | 458 |
| Model: 60, Battelle, Memorial Institute, Pacific Northwest Lab | 71-6387 | 454 |
| Model: 6244, Chem-Nuclear Systems, Inc. | 71-6244 | 453 |
| Model: 6272, U.S. Ecology | 71-6272 | 454 |
| Model: 660 & 660E, Technical Operations, Inc. | 71-9033 | 455 |
| Model: 6679, U.S. Ecology | 71-6679 | 454 |
| Model: 6717-B, Gamma Industries | 71-6717 | 455 |

| Name | Docket | Page |
|---|---|---|
| Model: 6744, U.S. Ecology | 71-6744 | 455 |
| Model: 78-D-1458, Navy, Dept. of | 71-9138 | 458 |
| Model: 864 Type B, Technical Operations, Inc. | 71-9166 | 459 |
| Model: 9080, Hittman Nuclear & Development Corp. | 71-9080 | 456 |
| Model: AL-33-90, Chem-Nuclear Systems, Inc. | 71-9108 | 457 |
| Model: AP-100, ANEFCO, Inc. | 71-9074 | 456 |
| Model: AP-101, ANEFCO, Inc. | 71-9071 | 456 |
| Model: B-2, U.S. Ecology | 71-6144 | 453 |
| Model: B-3, U.S. Ecology | 71-6058 | 453 |
| Model: BAPL 5910, BRDCG, Energy, Dept. of | 71-9119 | 458 |
| Model: BS-33-180, Tennessee Valley Authority | 71-6722 | 455 |
| Model: C-10, Gamma Industries | 71-9133 | 458 |
| Model: CNS 1-13CII, Chem-Nuclear Systems, Inc. | 71-9152 | 458 |
| Model: CNS 14-190, Chem-Nuclear Systems, Inc. | 71-5026 | 452 |
| Model: CNS 14-195-H, Chem-Nuclear Systems, Inc. | 71-9094 | 457 |
| Model: CNS 21-300, Chem-Nuclear Systems, Inc. | 71-9096 | 457 |
| Model: CNS 4-45, Chem-Nuclear Systems, Inc. | 71-6375 | 454 |
| Model: CNS 6-80-2, Chem-Nuclear Systems, Inc. | 71-9111 | 458 |
| Model: CNS 8-120, Chem-Nuclear Systems, Inc. | 71-6601 | 454 |
| Model: CNS 3-55, Chem-Nuclear Systems, Inc. | 71-5805 | 453 |
| Model: CNSI 1-13C, Chem-Nuclear Systems, Inc. | 71-9081 | 456 |
| Model: CNSI-1-184-409, Chem-Nuclear Systems, Inc. | 71-9101 | 457 |
| Model: D34710-1, D34710-2, Rockwell International | 71-5088 | 453 |
| Model: FSV-1, General Atomic Co. | 71-6346 | 454 |
| Model: GE 21PF-1, General Electric Co. | 71-4909 | 452 |
| Model: GE-1500, General Electric Co. | 71-5939 | 453 |
| Model: GE-1600, General Electric Co. | 71-9044 | 456 |
| Model: GE-700, General Electric Co. | 71-5942 | 453 |
| Model: GNG-20, Gulf Nuclear, Inc. | 71-9163 | 459 |
| Model: GNM-20, Gulf Nuclear, Inc. | 71-9162 | 459 |
| Model: HN-100, Series 1, Hittman Nuclear & Development Corp. | 71-9086 | 456 |
| Model: HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp. | 71-9079 | 456 |
| Model: HN-100, Series 3, Hittman Nuclear & Development Corp. | 71-9151 | 458 |
| Model: HN-100S, Hittman Nuclear & Development Corp. | 71-9089 | 457 |
| Model: HN-200, Hittman Nuclear & Development Corp. | 71-6574 | 454 |
| Model: HN-300, Hittman Nuclear & Development Corp. | 71-9092 | 457 |
| Model: HN-400, Hittman Nuclear & Development Corp. | 71-9093 | 457 |
| Model: IF-300, General Electric Co. | 71-9001 | 455 |
| Model: LL-60-150, Tennessee Valley Authority | 71-6568 | 454 |
| Model: MH-1A, Army, Dept. of | 71-6639 | 454 |
| Model: N-55, Energy, Dept. of | 71-9070 | 456 |
| Model: NFS-4, Nuclear Fuel Services, Inc. | 71-6698 | 454 |
| Model: NLI-1/2, NL Industries, Inc. | 71-9010 | 455 |
| Model: NPI-67-0442, Neutron Products, Inc. | 71-5364 | 453 |
| Model: NUPAC Series A, Nuclear Packing, Inc. | 71-9159 | 458 |
| Model: OH-142, Nuclear Packaging, Inc. | 71-9073 | 456 |
| Model: ORNL DOT Spec 6M Special Form Package, Energy, Dept. of | 71-9855 | 459 |
| Model: R, Gulf Nuclear, Inc. | 71-9161 | 459 |
| Model: RA-2, RA-3, RA-J, General Electric Co. | 71-4986 | 452 |
| Model: Rad-Waste CR. I, Chem-Nuclear Systems, Inc. | 71-9105 | 457 |
| Model: RCC, -1, -2, -3, -4, Westinghouse Electric Corp. | 71-5450 | 453 |
| Model: S3W/S4W New Sub, Energy, Dept. of | 71-6002 | 453 |
| Model: S5W ITR, Energy, Dept. of | 71-9783 | 459 |
| Model: S5W Power Unit, Energy, Dept. of | 71-5580 | 453 |
| Model: S5W, Energy, Dept. of | 71-5758 | 453 |
| Model: S5W, Refuel Srce, Energy, Dept. of | 71-5757 | 453 |
| Model: SGC-1, Chem-Nuclear Systems, Inc. | 71-9144 | 458 |
| Model: TN-8, -8L, No Users | 71-9015 | 455 |
| Model: UNC-2901, Combustion Engineering Co., Inc. | 71-6294 | 454 |
| Model: WAPD-40, Energy, Dept. of | 71-5874 | 453 |

**Licensing of Independent Spent Fuel Storage — Docket 72**

| | | |
|---|---|---|
| Morris Operations, General Electric Co. | 72-0001 | 459 |
| Virginia Electric & Power Co. | 72-0002 | 460 |

# DOCKETED ITEMS

## LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL, U S ECOLOGY, INC

8303160099 Forwards trip rept of 821201-02 tour of facility by R Scarano & J Shaffner.
SHAFFNER, J A Low Level Waste Licensing Branch 83/02/24
HAWKINS, E F Low Level Waste Licensing Branch 1p 17614:320

--8303160102 Trip rept of 821201-02 visit to Sheffield Low Level Waste Disposal Facility re site closure & decommissioning.
SCARANO, R A , SHAFFNER, J A Low Level Waste Licensing Branch
82/12/02 Low Level Waste Licensing Branch 2pp 17614:321

8303180588 Responds to 830218 ltr requesting info re Jan meetings on Sheffield Site tritium migration study Encl trip rept summarizes meeting of steering committee & site visit W/o encl.
SIEFKEN, D L Low Level Waste Licensing Branch 83/02/25
FINALDI, L Sierra Club 1p 17640:123

DOCKET 27-047 BARNWELL, SC, CHEM-NUCLEAR SYSTEMS, INC

8303040115 Forwards info re improper shipment of radwaste matl from ME Yankee Atomic Power Co to Barnwell, SC in response to 830120 ltr.
DIRCKS, W J Office of the Executive Director for Operations
83/02/24 MITCHELL, G J Senate 2pp 17424:272 24X Fiche 50-309, 83/02/24, 8303040115

--8303040120 Forwards State of SC 821220 investigation rept re improper shipment of radwaste matl from ME Yankee Atomic Power Co to Barnwell, SC.
GIBSON, A F Division of Engineering & Radiological Safety Programs 83/01/04 JOYNER, J H Division of Engineering & Technical Programs 7pp 17424:275 24X Fiche 50-309, 83/02/24, 8303040115

--8303040125 Requests all available info re improper shipment of radwaste matl from ME Yankee Atomic Power Co to Barnwell, SC.
MITCHELL, G J Senate 83/01/20 KAMMERER, C Office of Congressional Affairs 1p 17424:281 24X Fiche 50-309, 83/02/24, 8303040115

DOCKET 27-048 RICHLAND, WA, U S ECOLOGY, INC

8303020200 Forwards Amend 3 to License 16-19204-01, authorizing receipt & disposal of SNM at burial site in Hanford, WA.
SCARANO, R A Low Level Waste Licensing Branch 83/01/28
SCOVILLE, J J US Ecology, Inc (Formerly Nuclear Engineering) 1p 17358:259

--8303020206 Amend 3 to License 16-19204-01 authorizing US Ecology, Inc to receive, transport, possess, package, overpack, store & dispose of SNM at facility in Benton County, WA.
HAWKINS, E F Low Level Waste Licensing Branch 83/01/28 23pp 17358:260

8303010326 Forwards corrected copy L Amend 3 to License 16-19204-01
HAWKINS, E F Low Level Waste Licensing Branch 83/02/16 Low Level Waste Licensing Branch 1p 17348:362

--8303010336 Corrected Amend 3 to License 16-19204-01, permitting US Ecology, Inc to receive, transport, possess, package, overpack, store & dispose of SNM.
HAWKINS, E F Low Level Waste Licensing Branch 83/02/16 24pp 17355:038

8303180052 Requests clarification of paragraph of Amend 3 to License 16-19204-01 re authority of State of WA to regulate SNM quantities.
SCOVILLE, J J US Ecology, Inc (Formerly Nuclear Engineering)
83/02/18 BROWNING, R E Division of Waste Management 2pp 17625:255

8303010376 PNO-V-83-008 on 830216, shipment of low level waste received from Comm Ed, Dresden Plant Radiation level inside truck cab was 3 0 mr/hr State of WA banned Comm Ed from use of burial site & suspended permit.
THOMAS, R D Region 5, Office of Director 83/02/23 1p 17345:104

8303180064 Forwards notice of issuance of Amend 3 to License 16-19204-01 authorizing receipt & disposal of SNM at Hanford Reservation.
HAWKINS, E F Low Level Waste Licensing Branch 83/02/23
FELTON, J M Division of Rules and Records 1p 17625:233

--8303180068 Notice of issuance of Amend 3 to License 16-19204-01, allowing receipt & disposal of SNM at low level waste disposal facility at Hanford Reservation.
HAWKINS, E F Low Level Waste Licensing Branch 83/02/23 4pp 17625:234

8303170003 Forwards, for review & approval, "Richland WA Low Level Radwaste Disposal Facility Site Stabilization & Closure Plan."
SCOVILLE, J J US Ecology, Inc (Formerly Nuclear Engineering)
83/02/25 HAWKINS, E Low Level Waste Licensing Branch 2pp 17623:075

--8303170004 "Richland WA Low Level Radwaste Disposal Facility Site Stabilization & Closure Plan."
* US Ecology, Inc (Formerly Nuclear Engineering) 83/02/25
209pp 17623:077

8303280143 Advises of major amend fee requirement, specified in Fee Category 4A & Footnote 1(d) of 10CFR170 31 for Amend 3 to License 16-19204-01, issued 830128.
WEISS, D License Fee Management Branch 83/02/28 SCOVILLE, J J US Ecology, Inc (Formerly Nuclear Engineering) 1p 17713:318

8303080343 Forwards Waste Packaging Insp Rept 15000046/83-02 on 830114 & 17 & 0207 Noncompliance noted.
BOOK, H E Division of Radiological Safety & Safeguards Program
83/03/04 GRELLA, A Safeguards & Materials Program Branch 1p 17453:220

--8303080350 Waste Packaging Insp Rept 15000046/83-02 on 830114 & 17 & 0207 Noncompliance noted: failure to provide strong tight packages to prevent leakage of radioactive matl.
ELSEN, M J , BOOK, H E Division of Radiological Safety & Safeguards Program THOMAS, R D Region 5, Office of Director 83/03/03
9pp 17453:221

--8303080360 PNO-V-83-006 on 830114, shipment received from Teledyne Isotopes contained 10 drums w/loose bung caps & seven drums w/loose ring bolts Burial permit suspended effective 830117.
THOMAS, R D Region 5, Office of Director 83/02/02 3pp 17453:230

8303280081 Forwards WA State burial rept which indicates that no SNM received at Richland, WA site.
WRIGHT, S V US Ecology, Inc (Formerly Nuclear Engineering)
83/03/10 HAWKINS, E Low Level Waste Licensing Branch 1p 17713:362

8303300263 PNO-V-83-016 on 830324, shipment of low level waste from JA Fitzpatrick Nuclear Plant received w/one box having loose lid exposing compacted waste State of WA has banned licensee from use of burial site & suspended burial permit.
THOMAS, R D Region 5, Office of Director 83/03/24 1p 17733:023

## DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0017 DOW CHEMICAL CO., MIDLAND, MI

8303220475 Forwards 821005 decommissioning ltr for Dow/Wellman Foundry Site. All thoriated matl removed from Bldg 10.
OLSON, R.A. Dow Chemical Co. 83/02/08 SCHUMACHER, M. Region 3, Office of Director 1p 17670:282.

--8303220479 Forwards summary & conclusions of decommissioning work at Dow/Wellman Foundry Site. NRC criteria for unrestricted area met.
OLSON, R.A. Dow Chemical Co. 82/10/08 SCHUMACHER, M. Region 3, Office of Director 3pp 17670:283.

DOCKET 40-0086 W.R. GRACE & CO., POMPTON PLAINS, NJ

8303040369 Summary of 830208 meeting w/DOE & Aerospace Corp re remedial action responsibilities for various licensed or formerly licensed sites under provisions of Title II of U Mill Tailings Radiation Control Act of 1978.
NIXON, W.A. Uranium Fuel Licensing Branch 83/02/17 Uranium Fuel Licensing Branch 2pp 17426:319.

8303160635 Submits info re issuance of License SNM-1913 on 830210. 830209 meeting w/WR Grace in Pompton Plains, NJ re site contamination & 830210 meeting w/United Nuclear Corp in Wood River Junction, RI re site decontamination.
PAGE, R.G. Uranium Fuel Licensing Branch 83/02/17 DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director 2pp 17603:191.

8303250132 Discusses items of interest for listed facilities. Meeting notices for 830316 & 22 meetings encl.
PAGE, R.G. Uranium Fuel Licensing Branch 83/03/17 DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director.
CUNNINGHAM, R.E. Division of Fuel Cycle & Material Safety 3pp 17700:325.

DOCKET 40-0299 UNION CARBIDE CORP., GRAND JUNCTION, CO

8303090356 Informs that Amend 19 to License SUA-648 exempt from fees based on NRC request for cleanup of contaminated area containing windblown tailings.
WOOLSEY, R.T., PETTENGILL, H.J. Uranium Recovery Field Office 83/02/10 MILLER, W.O. License Fee Management Branch 1p 17484:205.

8303090106 Forwards cost estimate for decommissioning Gas Hills Mill in order to complete bonding requirements update.
WONG, T. Union Carbide Corp. 83/02/14 WOOLSEY, R. Uranium Recovery Licensing Branch 2pp 17465:011.

8303090042 Summarizes 830127 & 28 telcons w/licensee, Union Carbide Corp & State of WY, Div of Environ Quality re issuance of license condition on removal & disposal of soil contaminated by mill tailings. All parties concurred in condition issuance.
PETTENGILL, H.J. Uranium Recovery Field Office 83/02/16 Uranium Recovery Field Office 1p 17465:362.

8303090111 Summary of 830216 meeting w/Union Carbide Corp re stipulations applicable to permit revs.
KEARNEY, B. Wyoming, State of 83/02/17 Wyoming, State of 2pp 17464:361.

8303090500 Forwards inactive tailings area reclamation schedule. Consultant will be hired to conduct addl geotechnical work. Sys will be installed to remove water entrained in sands behind tailings dam. Monitoring plan expected by 830801.
WONG, T. Union Carbide Corp. 83/02/24 WOOLSEY, R. Uranium Recovery Licensing Branch 3pp 17482:333.

8303140684 Lists reasons why imposition of cleanup around Gas Hills tailings area under Amend 19 to License SUA-648 is premature. Reconsideration of amend or postponement pending promulgation of EPA stds requested.
BEVERLY, R.G. Union Carbide Corp. 83/02/25 SMITH, R.D. Uranium Recovery Licensing Branch 2pp 17548:355.

8303180125 Argues that Amend 19 to License SUA-648 provision re imposition of cleanup around Gas Hills tailings area premature. Reconsideration of amend requested since EPA has not yet issued cleanup stds.
BEVERLY, R.G. Union Carbide Corp. 83/02/25 SMITH, D. Uranium Fuel Licensing Branch 2pp 17625:162.

8303240030 Forwards "Semiannual ALARA Rept, Second Half 1982."
WONG, T. Union Carbide Corp. 83/02/25 LYONS, P.J. Union Carbide Corp. 1p 17697:001.

--8303240033 "Semiannual ALARA Rept, Second Half 1982."
* Union Carbide Corp. 83/02/25 540pp 17697:002.

8303240090 Forwards "Reporting Requirements of 10CFR40.65 & Condition 76 in Amend 9 to License SUA-648 for Fourth Quarter 1982."
WONG, T. Union Carbide Corp. 83/02/25 BROWN, G.D. Uranium Recovery Field Office 2pp 17695:001.

--8303240095 "Reporting Requirements of 10CFR40.65 & Condition 76 in Amend 9 to License SUA-648 for Fourth Quarter 1982."
* Union Carbide Corp. 83/02/25 298pp 17695:003.

8303180140 Reviews licensee Third Quarter 1982 rept per 10CFR40.65. Rept did not include data on groundwater radionuclide & monitor well sample.
WOOLSEY, R.T., PETTENGILL, H.J. Uranium Recovery Field Office 83/03/03 Uranium Recovery Field Office 7pp 17625:105.

8303170058 Advises that item of noncompliance noted in 820831-0902 insp of License SUA-648 does not merit rev to license.
WOOLSEY, R.T., PETTENGILL, H.J. Uranium Recovery Field Office 83/03/07 Uranium Recovery Field Office 1p 17615:359.

8303210435 Forwards fuel cycle & matls LER summary for Feb 1983.
BROWN, G.D. Division of Vendor & Technical Programs 83/03/16 DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director.
MICHELSON, C. Director's Office 3pp 17634:134.

DOCKET 40-1162 WESTERN NUCLEAR, INC., JEFFREY CITY, WY

8303090426 Comments on licensee 821110 response to 821015 request for addl info. No further action necessary re high levels of sulfate in total dissolved solids in Well 6. Review of high sulfate levels in Wells 19 & 25 awaits receipt of addl data.
GARCIA, P.J., PETTENGILL, H.J. Uranium Recovery Field Office 83/02/04 Uranium Recovery Field Office 2pp 17484:068.

8303090049 Forwards rept of semiannual audit/ALARA proceedings on 820920-24.
BOGDEN, G. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) 83/02/10 PETTENGILL, H.J. Uranium Recovery Licensing Branch 20pp 17466:056.

8303090024 Suppls 830210 ltr transmitting semiannual audit/ALARA rept for 820920-24 proceedings. Comments listed by license condition.
BOGDEN, G. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) 83/02/15 PETTENGILL, H.J. Uranium Recovery Licensing Branch 2pp 17466:169.

8303170579 Reviews data on two potential seepage pathways, provided in licensee 821216 Third Quarter 1982 groundwater monitoring data rept. No significant increasing trends exist which would cause concern.
GARCIA, P.J., PETTENGILL, H.J. Uranium Recovery Field Office 83/02/25 Uranium Recovery Field Office 3pp 17615:203.

8303180511 Forwards "Semiannual Environ Monitoring Rept, Jul-Dec 1982."
BOGDEN, G. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) 83/02/28 PETTENGILL, H.J. Uranium Recovery Licensing Branch 2pp 17638:276.

--8303180519 "Semiannual Environ Monitoring Rept, Jul-Dec 1982."
* Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) 83/02/28. 341pp 17638:278.

8303300236 Forwards response to RJ0112 request for addl info re 821025 dry loma leach reclamation const rept.
BOGDEN, G. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) 83/02/28 PETTENGILL, H.J. Uranium Recovery Licensing Branch 5pp 17754:136.

8303180145 "Groundwater & Surface Water Sampling Results for Third Quarter 1982."
BOGDEN, G. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) 83/03/01 GARCIA, P. Uranium Fuel Licensing Branch 8pp 17637:003.

8303180129 Forwards requested info re filter sites/types for perimeter & stack air sampling.
BOGDEN, G. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) 83/03/02 GARCIA, P. Uranium Fuel Licensing Branch 2pp 17625:140.

8303300145 Forwards annual operation & maint insp rept for Green Mountain IX NPDES Permit WY-0024490 per Condition 75 of License SUA-56.
BOGDEN, G. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 83/03/09. PETTENGILL, H. J. Uranium Recovery Licensing Branch. 8pp. 17751:030.

8303210435 Forwards fuel cycle & matls LER summary for Feb 1983.
BROWN, Q. D. Division of Vendor & Technical Programs. 83/03/16. DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 17634:134.

DOCKET 40-1341 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN

8303160613 Forwards "Edgemont U Mill Decommissioning Rept 1 Preliminary Results of Geotechnical Investigation Proposed Disposal Area" & "Edgemont U Mill Decommissioning Rept 2 Contaminated Matls Handling & Disposal Considerations."
MILLS, L. M. Tennessee Valley Authority. 83/01/28. SMITH, R. D. Uranium Recovery Field Office. 2pp. 17604:099.

--8303160619 "Edgemont U Mill Decommissioning Rept 1 Preliminary Results of Geotechnical Investigation Proposed Disposal Area." W/three oversize figures Aperture cards are available in PDR.
* MacLaren Engineers, Inc. * Golder Associates. * Arix Engineers, Architects & Planners. 82/10/31. 12pp. 17604:101.

--8303160623 "Edgemont U Mill Decommissioning Rept 2 Contaminated Matls Handling & Disposal Considerations."
* MacLaren Engineers, Inc. * Golder Associates. * Arix Engineers, Architects & Planners. 82/10/31. 17pp. 17604:116.

8303090349 Forwards SER for decommissioning Edgemont U Mill.
FLORY, C. A. Low Level Waste Licensing Branch. PETTENGILL, H. J. Uranium Recovery Field Office. 83/01/31. Low Level Waste Licensing Branch. 1p. 17484:206.

--8303090352 SER supporting decommissioning Edgemont U Mill.
* Division of Waste Management. 83/01/31. 12pp. 17484:207.

8303180055 Responds to 821228 ltr re cleanup stds proposed in FES on decommissioning Edgemont U Mill. Details of 830125 meeting w/EPA discussed. Cleanup criteria for residual contamination will be modeled after Title I stds.
SMITH, R. D. Uranium Recovery Field Office. 83/03/01. CAHILL, P. Environmental Protection Agency. 2pp. 17625:252.

DOCKET 40-1478 SPENCER CHEMICAL CO., KANSAS CITY, MO

8303230507 FOIA request for documents re Spencer Chemical Co.
BARNES, C. Affiliation Unknown. 83/01/24. FELTON, J. M. Division of Rules and Records. 1p. 17677:227.

8303230503 Responds to FOIA requests for addl documents re Spencer Chemical Co. Requested records not located. All documents re Spencer Chemical Co provided per previous FOIA requests.
FELTON, J. M. Division of Rules and Records. 83/02/24. BARNES, C. Affiliation Unknown. 1p. 17677:226.

DOCKET 40-2061 KERR-MCGEE CHEMICAL CORP., OKLAHOMA CITY, OK

8303010030 Summarizes demolition activities at factory site in response to W Nilon info request. Bldg contamination conducted neatly w/minimal offsite impact.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 83/01/19. PAGE, R. G. Uranium Fuel Licensing Branch. 2pp. 17322:340.

8303020101 Submits addl info re operating history of Kerr-McGee facility in West Chicago, IL. Minutes of Board of Directors 550322 meeting encl.
RHINELANDER, J. Shaw, Pittman, Potts & Trowbridge. 83/01/27. FONNER, R. L. Office of the Executive Legal Director. 48pp. 17360:145.

8303010046 Forwards supplemental info re Kerr-McGee Chemical Corp. West Chicago Rare Earths Facilities License Amends 5 & 6. Certificate of Svc encl.
ZAHLER, R. E. Shaw, Pittman, Potts & Trowbridge. 83/02/04. MAUSSHARDT, D. B. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 17348:001.

--8303010070 Supplemental info requested in connection w/License Amends 5 & 6 Exhibits 1 - 8 encl.
CHARNOFF, G., RHINELANDER, J., ZAHLER, R. E. Shaw, Pittman, Potts & Trowbridge. 83/02/04. 129pp. 17348:004.

8303180553 Responds to 830204 telcon re technical points of encl to 830103 ltr. Specific areas of misunderstanding re EPA air monitoring around site will be deleted.
WILDE, R. M. Division of Fuel Cycle & Material Safety. 83/02/07. JENSEN, L. Environmental Protection Agency. 3pp. 17639:327.

8303020129 Repudiates EPA estimates of Pb-212 air concentrations on certain sampling days. Original assessment that interim abatement measures would eliminate unwarranted inhalation risks to citizens reaffirmed.
ADAMKUS, V. V. Environmental Protection Agency. 83/02/08. DENNY, I. L. Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.). 2pp. 17359:315.

8303220388 Forwards citizen petition opposing radwaste site.
RENNELS, A. E. West Chicago, IL. 83/02/16. CUNNINGHAM, R. E. Division of Fuel Cycle & Material Safety. 8pp. 17673:001.

8303040369 Summary of 830208 meeting w/DOE & Aerospace Corp re remedial action responsibilities for various licensed or formerly licensed sites under provisions of Title II of U Mill Tailings Radiation Control Act of 1978.
NIXON, W. A. Uranium Fuel Licensing Branch. 83/02/17. Uranium Fuel Licensing Branch. 2pp. 17426:319.

8303110444 Forwards revised Item 6 of 801205 submittal to NRC re incinerator to be constructed at facility. Vacuum sys added to ash collection design in replacement of water spray mist. W/one oversize drawing. Aperture card available in PDR.
SHELLEY, W. J. Kerr-McGee Corp. 83/02/21. NIXON, W. A. Uranium Fuel Licensing Branch. 2pp. 17523:114.

8303220384 Forwards summary of analyses of samples taken during systematic radiological survey along Kress Creek.
RICE, G. B. Kerr-McGee Corp. 83/02/22. CUNNINGHAM, R. E. Division of Fuel Cycle & Material Safety. 3pp. 17673:115.

8303220375 Forwards revised P 8 to radiological health program plan, replacing 830103 counterpart. Rev inadvertently omitted.
SHELLEY, W. J. Kerr-McGee Corp. 83/03/03. NIXON, W. A. Uranium Fuel Licensing Branch. 1p. 17673:122.

--8303220377 Revised P 8 to radiological health program plan.
* Kerr-McGee Corp. 83/03/03. 1p. 17673:123.

8303220079 Confirmatory action ltr re onsite measurements of airborne Pb-212 concentrations. Based on 830315 discussions, vendor commits to install addl sampling stations & sample for Pb-212 within 14 days.
KEPPLER, J. G. Region 3, Office of Director. 83/03/16. SHELLEY, W. J. Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.). 2pp. 17652:210.

8303220271 PNO-III-83-019 on 830317, confirmatory action ltr issued due to discovery of excessive Pb-212 levels at station 20 ft from site boundary.
PAPERIELLO, C., HIND, J. Region 3, Office of Director. 83/03/17. 1p. 17656:214.

8303250132 Discusses items of interest for listed facilities. Meeting notices for 830316 & 22 meetings encl.
PAGE, R. G. Uranium Fuel Licensing Branch. 83/03/17. DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director. CUNNINGHAM, R. E. Division of Fuel Cycle & Material Safety. 3pp. 17700:325.

8303310375 Issues Amend 7 to License STA-583, incorporating radiological health program plan dtd 820103 & health physics manual.
PAGE, R. G. Uranium Fuel Licensing Branch. 83/03/22. SHELLEY, W. J. Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.). 1p. 17796:048.

--8303310379 Safety evaluation supporting Amend 7 to License STA-583, incorporating radiological health program plan.
NIXON, W. A., CROW, W. T. Uranium Fuel Licensing Branch. 83/03/22. 9pp. 17796:049.

8303220399 Requests that encl Shaw, Pittman, Potts & Trowbridge 821221 ltr re West Chicago Rare Earths facility be placed in PDR. Ltr & attachments contain social security numbers which are normally withheld from public disclosure.
PAGE, R. G. Uranium Fuel Licensing Branch. 83/03/28. SCOTT, S. Document Management Branch. 1p. 17672:242.

--8303220405 Forwards updated tables of contents to be inserted w/new proceeding matls re Amends 5 & 6 to License STA-583.
RHINELANDER, J. Shaw, Pittman, Potts & Trowbridge. 82/12/21. MAUSSHARDT, D. B. Office of Nuclear Material Safety & Safeguards, Director. 8pp. 17672:243.

# DOCKETED ITEMS

--8303220410 Discusses 821102 telcon w/HJ Spelman re possible date for site visit during wk of 821115.
MAUSSHARDT, D. B. NRC - No Detailed Affiliation Given. 82/11/02
NRC - No Detailed Affiliation Given. 1p. 17672:251.

--8303220415 Discusses 821103 telcon w/G Charnoff & J Rhinelander re suitable date for site visit to inspect bldg identified in Amends 5 & 6 to License STA-583.
MAUSSHARDT, D. B. NRC - No Detailed Affiliation Given. 82/11/03
NRC - No Detailed Affiliation Given. 1p. 17672:252.

--8303220418 Confirms 821102 & 05 telcons w/W Shelley re 821117 site visit.
NIXON, W. A. Uranium Fuel Licensing Branch. 82/11/08. Uranium Fuel Licensing Branch. 1p. 17672:253.

--8303220423 Discusses 821112 telcon w/HJ Spelman re 821117 site meeting to discuss Amends 5 & 6 to License STA-583.
MAUSSHARDT, D. B. NRC - No Detailed Affiliation Given. 82/11/12
NRC - No Detailed Affiliation Given. 1p. 17672:254.

--8303220427 Confirms 821108 meeting w/Kerr-McGee to obtain info on schedule for completion of FES & discuss preferred alternative for decommissioning.
NIXON, W. A. Uranium Fuel Licensing Branch. 82/11/16. Uranium Fuel Licensing Branch. 1p. 17672:255.

--8303220433 Confirms 821115 telcon w/Kerr-McGee to ensure that purpose of 821117 site visit would be limited in scope per NRC 821108 ltr.
NIXON, W. A. Uranium Fuel Licensing Branch. 82/11/16. Uranium Fuel Licensing Branch. 1p. 17672:256.

--8303220437 Forwards trip rept of 821117 site visit.
MAUSSHARDT, D. B. NRC - No Detailed Affiliation Given. 82/11/30.
RENNELS, A. E. West Chicago, IL. RAPKIN, A., MOOR, J. S. Illinois, State of. 3pp. 17672:266.

--8303220442 Forwards addl facility data including surface water sample analyses, airborne exposure & personal dosimetry repts.
SHELLEY, W. J. Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.). 82/12/02. NIXON, W. A. Uranium Fuel Licensing Branch. 15pp. 17672:339.

8303300279 Order extending time until 830429 for Commission to act to review presiding officer 830315 decision re Amends 5 & 6.
CHILK, S. J. Office of the Secretary of the Commission. 83/03/28.
Commissioners. 1p. 17735:161.

DOCKET 40-2259 PATHFINDER MINES CORP., RIVERTON, WY

8303090044 Informs that licensee is exempt from fees for Amend 16 to License SUA-672, requiring rev to bioassay & air particulate sampling program. Licensee request in response to violations.
SOLLENBERGER, D. Low Level Waste Licensing Branch. PETTENGILL, H. J. Uranium Recovery Field Office. 83/02/07. MILLER, W. O. License Fee Management Branch. 1p. 17465:361.

8303090626 Ack receipt of 830126 ltr re amend to License Conditions 25, 27 & 35. Need to respond prior to 830326 recognized.
NUGENT, E. L. Pathfinder Mines Corp. 83/02/10. SMITH, R. D. Uranium Recovery Field Office. 1p. 17480:294.

8303090046 Advises that comments on Lucky Mc U Mill renewal application will be submitted within 30 days. Comments will be in area of tailings seepage monitoring & reclamation.
ACKERMAN, W. C. Wyoming, State of. 83/02/11. SMITH, D. Division of Waste Management. 1p. 17466:076.

8303230441 Reviews licensee Third Quarter 1982 dose evaluations & 40CFR190 compliance evaluation. Mill complies w/40CFR190 std.
SOLLENBERGER, D., MARTIN, D. E. Low Level Waste Licensing Branch. 83/02/18. Low Level Waste Licensing Branch. 3pp. 17674:105.

8303090584 Forwards "Quarterly Effluent Monitoring Rept, Oct-Dec 1982," per Condition 34 to License SUA-672.
POYSER, R. W. Pathfinder Mines Corp. 83/02/22. WOOLSEY, R. T. Uranium Recovery Field Office. 1p. 17480:152.

--8303090591 "Quarterly Effluent Monitoring Rept, Oct-Dec 1982."
* Pathfinder Mines Corp. 83/02/22. 5pp. 17480:153.

8303160034 Forwards updated reclamation bond summary & correspondence verifying that ltrs of credit are in force to cover obligations, per Condition 42 of License SUA-672.
POYSER, R. W. Pathfinder Mines Corp. 83/02/22. WOOLSEY, R. T. Region 4, Office of Director. 7pp. 17615:033.

8303210769 Comments on licensee 821130 submittal of Third Quarter 1982 environ monitoring data. Info acceptable. No further action required at present time. Compliance rept for 10CFR40.190 will be covered in separate memo.
WOOLSEY, R. T., PETTENGILL, H. J. Uranium Recovery Field Office. 83/03/08. Uranium Recovery Field Office. 3pp. 17640:289.

DOCKET 40-3453 ATLAS MINERAL, INC., DENVER, CO

8303170682 Forwards engineering details & one oversize map for interim operation phase mods, per revised License Condition 16 in 820903 Amend 9 to license. Mods expected to be complete by 830601.
BLUBAUGH, R. E. Atlas Minerals. 82/10/26. SMITH, R. D. Uranium Recovery Licensing Branch. 3pp. 17615:217.

8303090071 Application for amend to License SUA-917, extending until 830601 date for submittal of water balance study.
BLUBAUGH, R. E. Atlas Minerals. 83/02/08. SMITH, R. D. Uranium Recovery Licensing Branch. 2pp. 17466:054.

8303090038 Annual survey of land use within 2 miles of plant.
EDWARDS, D. L. Atlas Minerals. 83/02/17. SMITH, D. NRC - No Detailed Affiliation Given. 2pp. 17466:077.

8303090030 Forwards "Gamma Survey of Tailings Pond & Perimeter, Fourth Quarter 1982."
EDWARDS, D. L. Atlas Minerals. 83/02/22. SMITH, R. D. Uranium Recovery Licensing Branch. 1p. 17466:085.

--8303090031 "Gamma Survey of Tailings Pond & Perimeter, Fourth Quarter 1982."
* Atlas Minerals. 83/02/22. 74pp. 17466:086.

8303180162 Comments on Atlas Minerals rept on ongoing site hydrology study. Five new monitoring wells installed, per Condition 53 to License SUA-917. Water balance study underway.
GARCIA, P. J., PETTENGILL, H. J. Uranium Recovery Field Office. 83/02/24. Uranium Recovery Field Office. 2pp. 17625:361.

8303180097 Amends License SUA-917 re final reclamation phase mods to Moab Wash, per licensee 821026 & 830208 submittals.
SMITH, R. D. Uranium Recovery Field Office. 83/02/28. Atlas Minerals. 2pp. 17625:197.

--8303180102 Recommends amends to Conditions 16 & 53 to License SUA-917 re final reclamation phase mods to Moab Mill.
GARCIA, P. J., PETTENGILL, H. J. Uranium Recovery Field Office. 83/02/28. Uranium Recovery Field Office. 3pp. 17625:199.

--8303180106 Recommends Condition 16 to License SUA-917 be modified to require implementation of engineering plans outlined in licensee 821026 submittal.
JOHNSON, T. L., PETTENGILL, H. J. Uranium Recovery Field Office. 83/02/22. Uranium Recovery Field Office. 2pp. 17625:202.

DOCKET 40-4492 FEDERAL-AMERICAN PARTNERS, RIVERTON, WY

8303090390 Application for amend to License SUA-667, changing method for monitoring radon gas from Tedlar Bag to Tracketch method.
ANDRUS, N. J. Federal American Partners. 83/02/07. SMITH, R. D. Uranium Recovery Field Office. 1p. 17484:122.

8303090513 Forwards "Environ TLD Summary for Jul-Dec 1982," "Soil Sampling Results for June 1982," "Vegetation Sample Results," & water & low vol air sampling results for Third & Fourth Quarters 1982, per 10CFR40.65.
COX, E. J., WATTS, R., LUCAS, J. W. Federal American Partners. 83/02/23. Region 4, Office of Director. 1p. 17483:084.

--8303090526 "Environ TLD Summary for Jul-Dec 1982," "Soil Sampling Results for June 1982," "Vegetation Sample Results," & water & low vol air sampling results for Third and Fourth Quarters 1982.
* Federal American Partners. 83/02/23. 38pp. 17483:085.

8303140687 Informs that w/o prior NRC approval to reclaim Tailings Pond 2 & assurances that reclamation will satisfy final requirements, work on pond cannot proceed.
ANDRUS, N. J. Federal American Partners. 83/02/25. SMITH, R. D. Region 4, Office of Director. SUNDIN, R. Wyoming, State of. 1p. 17548:357.

8303180173 Forwards "Detailed Seepage Investigation of Mill Waste Disposal Alternatives, West Gas Hills, WY." addendum rept per 821124 request for addl info re sensitivity & applicability of computer model in groundwater hydraulic studies.
ANDRUS, N. J. Federal American Partners. 83/03/01. ACKERMAN, W. C. Wyoming, State of. 6pp. 17625:001.

--8303180180 "Detailed Seepage Investigation of Mill Waste Disposal Alternatives, West Gas Hills, WY." addendum rept.
SHARMA, D. Dames & Moore. 83/02/14. 98pp. 17625:007.

8303220428 Documents 830302 discussions w/State of WY Dept of Environ Quality & NRC re Federal American Partners request for approval of startup of reclamation on Tailings 2.
FREUDENTHAL, N., FRANCIS, E. Wyoming, State of. 83/03/02. GILLEN, D. NRC - No Detailed Affiliation Given. 2pp. 17672:238.

DOCKET 40-6622 PATHFINDER MINES CORP., SHIRLEY BASIN, WY

8303090010 Requests addl info specified in encl "Principal Parameters for Radiological Assessment." All major changes in mill or tailings pond operation should be specifically noted w/o encl.
PETTENGILL, H. J. Uranium Recovery Field Office. 83/02/10.
RUSSELL, J. E. Pathfinder Mines Corp. 1p. 17466:193.

8303170172 Reviews 820812 groundwater sampling data for Pathfinder Shirley Basin Mill. Need for seepage mitigation measures or changes in groundwater monitoring program will be determined following groundwater study review.
GARCIA, P. J., PETTENGILL, H. J. Uranium Recovery Field Office. 83/02/18. Uranium Recovery Field Office. 2pp. 17623:361.

8303170303 Comments on licensee 821209 results of Third Quarter 1982 environ monitoring per Condition 37 to License SUA-442. Monitoring rept acceptable.
GARCIA, P. J. Uranium Recovery Field Office. 83/02/25. Uranium Recovery Field Office. 5pp. 17623:293.

DOCKET 40-6659 GETTY OIL CO. - PETROTOMICS CO., SHIRLEY BASIN, WY

8303180239 Forwards IE Insp Rept 40-6659/82-01 on 820928-30. No noncompliance noted.
BROWN, G. D. Region 4, Office of Director. 82/11/17. WHITMAN, J. H. Getty Oil Co. (Petrotomics). 2pp. 17621:103.

--8303180243 IE Insp Rept 40-6659/82-01 on 820928-30. No noncompliance noted. Major areas inspected: mgt & training, internal exposure control, external exposure & contamination control & independent measurements.
SHOPENN, N. M., BROWN, R. C., EVERETT, R. J. Region 4, Office of Director. 82/11/08. 13pp. 17621:105.

DOCKET 40-6940 KAWECKI BERYLCO IND., INC., BOYERTOWN, PA

8303040369 Summary of 830208 meeting w/DOE & Aerospace Corp re remedial action responsibilities for various licensed or formerly licensed sites under provisions of Title II of U Mill Tailings Radiation Control Act of 1978.
NIXON, W. A. Uranium Fuel Licensing Branch. 83/02/17. Uranium Fuel Licensing Branch. 2pp. 17426:319.

DOCKET 40-7097 MOLYCORP, INC., WHITE PLAINS, NY

8303040369 Summary of 830208 meeting w/DOE & Aerospace Corp re remedial action responsibilities for various licensed or formerly licensed sites under provisions of Title II of U Mill Tailings Radiation Control Act of 1978.
NIXON, W. A. Uranium Fuel Licensing Branch. 83/02/17. Uranium Fuel Licensing Branch. 2pp. 17426:319.

DOCKET 40-7138 YANKEE ATOMIC ELECTRIC CO., WESTBOROUGH, MA

8303090365 Forwards "Yankee Personnel & Man-Rem By Work & Duty Function Rept, 1982."
HEIDER, L. H. Yankee Atomic Electric Co. 83/02/28. HAYNES, R. C. Region 1, Office of Director. 1p. 17471:327. 24X
Fiche 50-029, 83/02/28, 8303090365.

--8303090370 "Yankee Personnel & Man-Rem By Work & Duty Function Rept, 1982."
e. Yankee Atomic Electric Co. 83/02/24. 1p. 17471:328. 24X
Fiche 50-029, 83/02/28, 8303090365.

DOCKET 40-7455 WHITTAKER METALS, LOS ANGELES, CA

8303040369 Summary of 830208 meeting w/DOE & Aerospace Corp re remedial action responsibilities for various licensed or formerly licensed sites under provisions of Title II of U Mill Tailings Radiation Control Act of 1978.
NIXON, W. A. Uranium Fuel Licensing Branch. 83/02/17. Uranium Fuel Licensing Branch. 2pp. 17426:319.

DOCKET 40-7869 PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO

8303090021 Notifies of change in 820907 decommissioning submittal re tailings removal & loading. Three-drum slusher will be installed in addition to loader.
GERDEMAN, F. W. Plateau Resources, Ltd. 83/02/21. JOHNSON, T. Division of Waste Management. 3pp. 17466:171.

8303090115 Forwards revised organization chart for Shootaring Canyon Processing Facility. Chart represents present mgt & reporting structure.
GERDEMAN, F. Plateau Resources, Ltd. 83/02/22. JOHNSON, T. Division of Waste Management. 1p. 17465:064.

8303170320 Confirms telcon w/TL Johnson re effluent monitoring program rept for Jul-Dec 1982. Rept will be submitted later than time imposed in 10CFR40.65 due to unavoidable circumstances.
GERDEMAN, F. W. Plateau Resources, Ltd. 83/03/02. SMITH, R. D. NRC - No Detailed Affiliation Given. 1p. 17615:355.

DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK

8303020251 Forwards EIS re underground injected disposal of other industrial wastes, in response to NRC 821105 ltr. Integrity of disposal well & monitoring sys satisfactory to issue 5-yr permit to vendor.
HENSCH, D. A. Oklahoma, State of. 83/01/24. CROW, W. T. Uranium Fuel Licensing Branch. 12pp. 17355:319.

8303210082 Comments on "Underground Injected Disposal of Other Industrial Waste at Kerr-McGee Nuclear Facility Near Gore, OK." Rept submitted to NRC.
SHELLEY, W. J. Kerr-McGee Corp. 83/02/04. HENSCH, D. Oklahoma, State of. 3pp. 17660:115.

8303220452 Submits results of analysis of U & soluble U in fluoride sludge. No justification for addl treatment w/aluminum coating given. Copy of NPDES permit encl.
SHELLEY, W. J. Kerr-McGee Corp. 83/03/03. PAGE, R. G. Uranium Fuel Licensing Branch. 30pp. 17670:066.

8303170306 Trip rept of 830214-18 unannounced site insp re organization, mgt, training, internal & external exposure control, environ monitoring & waste mgt. Areas requiring addl info include demonstration of raffinate fertilizer program.
KOSLA, B. Uranium Fuel Licensing Branch. 83/03/04. CROW, W. T. Uranium Fuel Licensing Branch. 1p. 17623:292.

8303180667 Responds to 830224 request to reopen LPDR at Sallisaw City Library in OK. Reopening date will be considered 830224 & all correspondence will be forwarded from that date on.
CROW, W. T. Uranium Fuel Licensing Branch. 83/03/15. SHELLY, W. J. Kerr-McGee Corp. 1p. 17637:121.

--8303180669 Requests PDR at Sallisaw City Library in OK be maintained to provide local source of info relevant to facility operations.
SHELLEY, W. J. Kerr-McGee Corp. 83/02/24. CROW, W. T. Uranium Fuel Licensing Branch. 1p. 17637:122.

DOCKET 40-8064 EXXON MINERALS CO. USA, HOUSTON, TX

8303160664 Forwards proposed reclamation bond currently being reviewed by WY Dept of Environ Quality, per Condition 17 of License SUA-1064. Project currently bonded by Ltr of Credit I-12897 submitted on 820408.
SHANNON, J. B. Exxon Corp. 83/02/08. KALMAN, K. Uranium Recovery Licensing Branch. 2pp. 17600:293.

8303230133 Summarizes 830209 telcon w/F Ross re acceptable restoration levels for Wellfield 1.
SMITH, M. A. Wyoming, State of. 83/02/18. Wyoming, State of. 1p. 17690:067.

# DOCKETED ITEMS

DOCKET 40-8084 RIO ALGOM CORP., MOAB, UT

8303100054 Submits semiannual survey of land use.W/one oversize map. Aperture card is available in PDR.
PATTISON,R.S. Rio Algom, Ltd 83/02/15 SMITH,R.D. Uranium Recovery Licensing Branch 1p 17492:195.

8303090605 "Semiannual Environ Monitoring Rept for Jul-Dec 1982."
LAWTON,M.D. Rio Algom, Ltd 83/02/24 39pp 17480:175.

8303210435 Forwards fuel cycle & matls LER summary for Feb 1983.
BROWN,G.D. Division of Vendor & Technical Programs. 83/03/16.
DAVIS,J.G. Office of Nuclear Material Safety & Safeguards,Director. 3pp 17634:134.

DOCKET 40-8102 EXXON CO. USA, HOUSTON, TX

8303180010 Forwards "Summary of Airborne Emissions of Principal Radionuclides From Highland U Mill During Period Jul-Dec 1982" & "Semiannual ALARA Rept for Jul-Dec 1982."
YARNICK,T.P. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 83/02/25 Uranium Recovery Licensing Branch 1p 17625:277.

--8303180015 "Airborne Emissions of Principal Radionuclides From Highland U Mill During Period Jul-Dec 1982."
* Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 83/02/25 4pp 17625:278.

--8303180019 "Semiannual ALARA Rept for Jul-Dec 1982."
* Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 83/02/25 36pp 17625:282.

8303180169 Forwards Pp D5-D19 to App D,inadvertently omitted from semiannual ALARA rept.
CLARK,D.E. Exxon Corp. 83/03/01 Uranium Fuel Licensing Branch 1p 17626:017.

--8303180172 Pp D5-D19 to App D semiannual ALARA rept.
* Exxon Corp. 83/03/01 15pp 17626:018.

DOCKET 40-8452 BEAR CREEK URANIUM CO., CASPER, WY

8303180132 Reviews dose calculations & compliance evaluations for Third Quarter 1982,submitted by licensee 821206 ltr.Mill complies w/40CFR190 std.
SOLLENBERGER,D., MARTIN,D.E. Low Level Waste Licensing Branch 83/03/03 Low Level Waste Licensing Branch 3pp 17625:131.

8303220460 Forwards "Quarterly Environ Monitoring Rept for Oct-Dec 1982."
BLOSSOM,J.N. Bear Creek Uranium Co. 83/03/04 Uranium Recovery Licensing Branch 1p 17670:157.

--8303220464 "Quarterly Environ Monitoring Rept for Oct-Dec 1982."
* Bear Creek Uranium Co. 83/03/04 19pp 17670:158.

DOCKET 40-8502 WYOMING MINERAL CORP., LAKEWOOD, CO

8303090062 Discusses NRC concern re State of WY,Dept of Environ Quality selection of monitoring wells for restoration & degree of restoration required in coal zone.WY will evaluate criteria in Spring 1983.
ACKERMAN,W.C. Wyoming, State of 83/01/24 SMITH,R.D. Uranium Recovery Field Office 1p 17466:220.

8303170221 Forwards "Irigaray Mine Site Semiannual Activity & Monitoring Rept,Jul-Dec 1982."
RUTLEDGE,C. Wyoming Mineral Corp. 83/02/15 BROWN,G. Region 4, Office of Director 1p 17623:341.

--8303170225 "Irigaray Mine Site Semiannual Activity & Monitoring Rept, Jul-Dec 1982."
* Wyoming Mineral Corp. 83/02/15 10pp 17623:342.

8303210435 Forwards fuel cycle & matls LER summary for Feb 1983.
BROWN,G.D. Division of Vendor & Technical Programs. 83/03/16.
DAVIS,J.G. Office of Nuclear Material Safety & Safeguards,Director. 3pp 17634:134.

DOCKET 40-8578 TRI-WELD, INC., CLEVELAND, OH

8303220066 IE Insp Findings & Licensee Ack dtd 830303 of License SUC-1255.Insp findings no violations observed.
* Region 3, Office of Director 83/03/03 1p 17652:264.

DOCKET 40-8584 MINERALS EXPLORATION CO., LOS ANGELES, CA

8303090632 Requests meeting to exchange views & concerns re review of Minerals Exploration modified tailings proposal by late Mar or early Apr.
ACKERMAN,W.C. Wyoming, State of 83/02/07 SMITH,R.D. Uranium Recovery Field Office 1p 17480:284.

8303090344 Reviews Minerals Exploration Co 820528 submittal re groundwater quality variations in several tailings pond monitoring wells at Sweetwater Mill site.Recommends data from routine monitoring program be reinspected.
JOHNSON,T.L. Uranium Recovery Field Office 83/02/10.
PETTENGILL,H.J. Uranium Recovery Field Office 3pp 17484:219.

8303090554 Requests addl info to complete review of 820528 submittal re tailings pond monitor well water quality fluctuations.
PETTENGILL,H.J. Uranium Recovery Field Office 83/02/10.
SNYDER,H.L. Minerals Exploration Co. (subs. of Union Oil Co. of California) 1p 17483:163.

8303090027 Forwards geotechnical review of application for amend to SNM-1350.Exploration & sampling techniques valid.
HOWARD,T.R. R.E.Williams & Associates,Inc. 83/02/18. GARCIA,P.
NRC - No Detailed Affiliation Given 9pp 17466:160.

8303090601 "Sweetwater U Project - Mill Tailings Disposal Pond E," review of plans & specs.
BERRETH,A.J. Wyoming, State of 83/02/18 2pp 17480:158.

8303090622 Forwards addl info required for continued review of tailings submittal re amend to License SUA-1350.
SNYDER,H.L. Union Minerals. 83/02/18. PETTENGILL,H. Uranium Recovery Licensing Branch 11pp 17480:295.

8303240059 Forwards addl info requested for use in review of application for amend to License SUA-1350.
SNYDER,H.L. Affiliation Unknown. 83/02/18. PETTENGILL,H. Uranium Recovery Licensing Branch 97pp 17698:219.

8303170050 Summarizes review of 1982 annual land use survey.Regional population within 5 miles of mill relatively unchanged.No new residences built within 5 miles of mill.Further action unnecessary.
BRANSCOME,J.M., PETTENGILL,H.J. Uranium Recovery Field Office. 83/02/23. Uranium Recovery Field Office 2pp 17615:360.

8303220469 Forwards summary of environ monitoring & meteorological conditions,per License Conditions 34,43 & 48.Subsurface soil sampling continued during operational monitoring.
SNYDER,H.L. Union Minerals. 83/02/28 Uranium Recovery Licensing Branch 93pp 17670:189.

8303230125 Responds to 830117 request for addl info.Tables depicting primary tailings alternatives const cost comparison encl.
SNYDER,H.L. Union Minerals. 83/03/01 GARCIA,P. Uranium Recovery Field Office. 9pp 17690:073.

DOCKET 40-8585 WYOMING MINERAL CORP., LAKEWOOD, CO

8303300215 Forwards "Semiannual Effluent Monitoring Rept,Jul-Dec 1982," per 10CFR40.65 & Condition 27 of License SUA-1315.
BERG,R.E. Wyoming Mineral Corp. 83/03/07 Region 4, Office of Director 1p 17749:282.

--8303300222 "Semiannual Effluent Monitoring Rept,Jul-Dec 1982."
* Wyoming Mineral Corp. 83/03/07 1p 17749:283.

DOCKET 40-8602 SILVER KING MINES, INC., CASPER, WY

8303140646 Forwards "Preoperational Radiological Environ Monitoring Program Rept,Jul-Dec 1982."
WOLFF,C.E. Silver King Mines, Inc. 83/02/28 PETTENGILL,H.J. Uranium Recovery Licensing Branch 3pp 17569:059.

--8303140650 "Preoperational Radiological Environ Monitoring Program Rept,Jul-Dec 1982."
* Silver King Mines, Inc. 83/02/28 106pp 17569:062.

8303110586 Forwards "Annual Land Use Survey, Project Area - 5 Mile Radius, 1982."
WOLFF, C.E. Silver King Mines, Inc. 83/02/28. SCARANO, R.A. Uranium Recovery Licensing Branch. 1p. 17522:344.

--8303110598 "Annual Land Use Survey, Project Area - 5 Mile Radius, 1982." W/one oversize drawing. Aperture card is available in PDR.
* Silver King Mines, Inc. 83/02/28. 3pp. 17522:345.

8303210236 Comments on licensee 820223 submittal of 1982 land use survey rept. No changes in existing monitoring program nor licensing action required at present time.
WOOLSEY, R.T., PETTENGILL, H.J. Uranium Recovery Field Office. 83/03/11. Uranium Recovery Field Office. 2pp. 17640:356.

DOCKET 40-8663 NUCLEAR DYNAMICS, INC., PHOENIX, AZ

8303180103 Recommends acceptance of groundwater restoration & release of wellfield. NRC approval not yet obtained.
MOONEY, G. Wyoming, State of. 83/03/04. SUNDIN, R.E. Wyoming, State of. 1p. 17625:190.

DOCKET 40-8674 PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO

8303090617 Notifies that RJ Carr formally assigned as radiological safety officer for Blanding Ore Buying Station. Requisite radiation protection training completed.
GERDEMAN, F.W. Plateau Resources, Ltd. 83/02/21. JOHNSON, T.L. NRC - No Detailed Affiliation Given. 1p. 17481:151.

8303170324 Confirms telcon w/TL Johnson re effluent monitoring program rept for Jul-Dec 1982. Rept will be submitted later than time limit imposed in 10CFR40.65 due to unavoidable circumstances.
GERDEMAN, F.W. Plateau Resources, Ltd. 83/03/03. SMITH, R.D. NRC - No Detailed Affiliation Given. 1p. 17615:354.

DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC., DENVER, CO

8303300231 Requests all correspondence & telcons re White Mesa source matl license (SUA-1358) be directed to DK Sparling, to avoid confusion & delays.
VINCELETTE, M.D. Energy Fuels Nuclear, Inc. 83/02/08. SMITH, D. NRC - No Detailed Affiliation Given. 2pp. 17749:354.

8303080015 Discusses IE insp on 821102-04 & forwards notice of violation & proposed imposition of civil penalty.
COLLINS, J.T. Region 4, Office of Director. 83/02/22.
VINCELETTE, M.D. Energy Fuels Nuclear, Inc. 3pp. 17455:324.

--8303080020 Notice of violation & proposed imposition of civil penalty in amount of $4,000. Noncompliance noted: failure to perform evaluations of weekly worker exposures to airborne soluble U from Nov 1981 - Mar 1982.
COLLINS, J.T. Region 4, Office of Director. 83/02/22. 5pp. 17455:327.

8303180154 Reviews Third Quarter 1982 10CFR40.65 environ monitoring rept. All required data submitted. No significant variations from previous environ data evident. Reported data within applicable limits.
GILLEN, D.M., LINEHAN, J.J. Uranium Recovery Field Office. 83/02/25. Uranium Recovery Field Office. 3pp. 17626:004.

8303140692 Forwards "Effluent & Monitoring Rept, White Mesa Project, Oct-Dec 1982," per Condition 30 to License SUA-1358.
ROBERTS, H.R. Energy Fuels Nuclear, Inc. 83/02/28. GILLEN, D. Uranium Recovery Licensing Branch. 1p. 17569:179.

--8303140695 "Effluent & Monitoring Rept, White Mesa Project, Oct-Dec 1982."
* Energy Fuels Nuclear, Inc. 83/03/01. 34pp. 17569:180.

8303230388 Forwards "Const Rept Second Phase Tailings Mgt Sys," per Amend 1, Condition 26b of license.
ROBERTS, H.R. Energy Fuels Nuclear, Inc. 83/03/04. GILLEN, D. Uranium Recovery Licensing Branch. 1p. 17677:271.

--8303230391 "Const Rept Second Phase Tailings Mgt Sys." W/three oversize figures. Aperture cards are available in PDR.
* Energy Fuels Nuclear, Inc. 83/03/31. 64pp. 17677:272.

8303300242 Forwards payment for processing of 830208 administrative amend to License SUA-1358 changing notification address.
ROBERTS, H.R. Energy Fuels Nuclear, Inc. 83/03/10. GILLEN, D. Uranium Recovery Licensing Branch. 1p. 17751:360.

DOCKET 40-8698 PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO

8303090064 Forwards "Outlier Explanations & Submittal of Seep Water Quality Data," in response to 831028 ltr.
GERDEMAN, F.W. Plateau Resources, Ltd. 83/02/08. PETTENGILL, H.J. Uranium Recovery Licensing Branch. 1p. 17466:211.

--8303090068 "Outlier Explanations & Submittal of Seep Water Quality Data."
* Plateau Resources, Ltd. 83/02/28. 8pp. 17466:212.

8303090134 Forwards "Effluent Monitoring Rept, Jul-Sept 1982."
GERDEMAN, F.W. Plateau Resources, Ltd. 83/02/15. Region 4, Office of Director. 1p. 17465:036.

--8303090141 "Effluent Monitoring Rept, Jul-Sept 1982."
* Plateau Resources, Ltd. 83/02/15. 26pp. 17465:037.

8303040679 Discusses IE insp on 821123 & forwards notice of violation & proposed imposition of civil penalty.
COLLINS, J.T. Region 4, Office of Director. 83/02/22. FISHER, B.O. Plateau Resources, Ltd. 3pp. 17411:010.

--8303030687 Notice of violation & proposed imposition of civil penalty in amount of $4,000.00. Noncompliance noted: evaluations of weekly worker exposure to airborne soluble U not performed.
COLLINS, J.T. Region 4, Office of Director. 83/02/22. 3pp. 17411:013.

8303160655 Forwards revised pages to effluent monitoring rept submitted by 830215 ltr. Revised pages identify parameters as radionuclides instead of locations & delete confusing digits in air particulate monitoring site identification numbers.
GERDEMAN, F.W. Plateau Resources, Ltd. 83/02/22. Region 4, Office of Director. 1p. 17600:307.

--8303160658 Revised pages to effluent monitoring rept for Jul-Sept 1982.
* Plateau Resources, Ltd. 83/02/22. 3pp. 17600:308.

8303300188 Forwards revised "Organization Chart - Shootaring Canyon Processing Facility." Chart represents present mgt & reporting structure for facility.
GERDEMAN, F.W. Plateau Resources, Ltd. 83/03/01. SMITH, R.D. Division of Waste Management. 1p. 17754:334.

8303170331 Confirms telcon w/TL Johnson re effluent monitoring program rept for Jul-Dec 1982. Rept will be submitted later than time limit imposed in 10CFR40.65. Delay due to unavoidable circumstances.
GERDEMAN, F.W. Plateau Resources, Ltd. 83/03/02. SMITH, R.D. NRC - No Detailed Affiliation Given. 1p. 17615:221.

8303220435 Forwards "Effluent Monitoring Rept, Oct-Dec 1982."
GERDEMAN, F.W. Plateau Resources, Ltd. 83/03/08. Region 4, Office of Director. 1p. 17672:215.

--8303220440 "Effluent Monitoring Rept, Oct-Dec 1982."
* Plateau Resources, Ltd. 83/03/08. 19pp. 17672:216.

8303210435 Forwards fuel cycle & matls LER summary for Feb 1983.
BROWN, G.D. Division of Vendor & Technical Programs. 83/03/16.
DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 17634:134.

8303310283 Forwards payment of civil penalty issued 830222.
FISHER, B.O. Plateau Resources, Ltd. 83/03/24. DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 1p. 17756:001.

--8303310296 Responds to NRC 830222 ltr re notice of violations & proposed imposition of civil penalty. Corrective actions: shift supervisors & operators assigned to packaging area to receive training re time distribution accuracy.
YOUNGDAHL, R.C. Plateau Resources, Ltd. 83/03/24. DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 8pp. 17756:002.

DOCKET 40-8713 NAVY, DEPT. OF, SAN DIEGO, CA

8303140499 Ack receipt of 830125 ltr informing NRC of steps taken to correct violations noted in IE insp rept.
BOOK, H.E. Division of Radiological Safety & Safeguards Program. 83/03/09. MONROE, P. Navy, Dept. of. 2pp. 17540:192.

# DOCKETED ITEMS

--8303140508 Forwards 830125 ltr re violations noted in IE insp rept.
HORTON, J. D. Navy, Dept. of. 83/02/17. Region 5, Office of Director. 1p. 17540:194.

--8303140513 Responds to NRC 821230 ltr re violations noted in IE insp rept. Corrective actions: all incoming source matl logged on work in process inventory control sys. Source matl for disposal contained in covered metal container.
LYNCH, L. M. Navy, Dept. of. 83/01/25. Region 5, Office of Director. 2pp. 17540:195.

8303290592 Ack receipt of 830125 ltr & updated ltr received 830321 informing NRC of steps taken to correct violation noted in IE insp of License SMB-1346 on 821210.
BOOK, H. E. Region 5, Office of Director. 83/03/25. MONROE, P. Navy, Dept. of. 1p. 17724:001.

--8303290600 Responds to NRC 830309 ltr re violation noted in IE insp of License SMB-1346. Corrective actions: occupational safety & health manager will audit implemented mgt controls quarterly.
TINSTON, W. J. Navy, Dept. of. 83/03/21. Region 5, Office of Director. 1p. 17724:002.

DOCKET 40-8714 CLEVELAND-CLIFFS IRON CO., CLEVELAND, OH

8303170314 Requests that Water Quality Div Permit 79-682 be terminated & that decommissioning of final surface reclamation of drain field area be approved.
LOUDERBACK, T. E. Cleveland-Cliffs Iron Co. 82/11/12. LINEHAN, J. J. Uranium Recovery Licensing Branch. MUELLER, T.; CHANCELLOR, R. A. Wyoming, State of. 5pp. 17623:286.

8303110033 Forwards "Quarterly Rept, Oct-Dec 1982."
WODEK, D. J. Cleveland-Cliffs Iron Co. 83/01/31. LINEHAN, J. Uranium Recovery Licensing Branch. 1p. 17546:314.

--8303110039 "Quarterly Rept, Oct-Dec 1982." W/two oversize figures. Aperture cards are available in PDR.
* Cleveland-Cliffs Iron Co. 83/01/31. 34pp. 17546:315.

8303090019 Documents 830215 telcons w/Getty Petrotomics (GP) & NRC re disposal of Collins Draw in situ mine & processing wastes at GP facilities.
LOUDERBACK, T. E. Cleveland-Cliffs Iron Co. 83/02/15. ROSS, F. Uranium Recovery Licensing Branch. 1p. 17466:174.

8303090547 Reviews quarterly rept for Jul-Sept 1982. No followup actions required. Review of restoration data will be completed separately.
ROSS, F. W. Uranium Recovery Field Office. 83/02/22. Uranium Recovery Field Office. 2pp. 17483:164.

8303220002 Discusses groundwater restoration & monitor well pumping at Collins Draw Site. Addl restoration should be performed. Monitoring recommended for stabilization.
OGLE, K. M. Wyoming, State of. 83/02/24. Cleveland-Cliffs Iron Co. 10pp. 17672:354.

8303170334 Summarizes 830223 meeting in Cheyenne, WY re status of wellfield restoration at Collins Draw Project. Conclusions listed.
MOONEY, G. Wyoming, State of. 83/02/28. LOUDERBACK, T. Cleveland-Cliffs Iron Co. 2pp. 17615:215.

8303210435 Forwards fuel cycle & matls LER summary for Feb 1983.
BROWN, G. D. Division of Vendor & Technical Programs. 83/03/16. DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director. MICHELSON, C. Director's Office. 3pp. 17634:134.

DOCKET 40-8722 BRUSH WELLMAN, INC., CLEVELAND, OH

8303210435 Forwards fuel cycle & matls LER summary for Feb 1983.
BROWN, G. D. Division of Vendor & Technical Programs. 83/03/16. DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 17634:134.

DOCKET 40-8724 CHEMETRON CORP., CHICAGO, IL

8303250132 Discusses items of interest for listed facilities. Meeting notices for 830316 & 22 meetings encl.
PAGE, R. G. Uranium Fuel Licensing Branch. 83/03/17. DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 17700:325.

DOCKET 40-8728 TETON EXPLORATION DRILLING CO., INC., CASPER, WY

8303090012 Comments on rept of restoration of M zone wellfield, based on licensee 820809, 1015 & 830118 submittals. Licensee adequately restored M ore zone wellfield area by returning groundwater to highest potential premining use.
ROSS, F. W.; LINEHAN, J. J. Uranium Recovery Field Office. 83/02/22. Uranium Recovery Field Office. 9pp. 17466:181.

8303180110 Advises that Leuenberger R&D N ore zone restoration & post-restoration stability data reviewed. N ore zone restored to original potential use condition. No addl restoration required by NRC.
SMITH, R. D. Uranium Recovery Field Office. 83/02/28. Teton Exploration Drilling Co., Inc. 1p. 17625:181.

--8303180114 Discusses Leuenberger R&D N ore zone final restoration review. Licensee met NRC objectives for restoration. N ore zone production, injection & observation wells may be abandoned.
ROSS, F. W. Uranium Recovery Field Office. 83/02/28. Uranium Recovery Field Office. 3pp. 17625:182.

DOCKET 40-8743 CONOCO, INC., DENVER, CO

8303090595 Submits trip rept of 830224 meeting w/State of WY, Dept of Environ Quality & Dept of Land Quality re Cononco Sand Rock Mill Project.
WILLIAMS, R. E. R. E. Williams & Associates, Inc. 83/02/25. PETTENGILL, H. Uranium Recovery Licensing Branch. 3pp. 17480:160.

DOCKET 40-8745 OGLE PETROLEUM, INC., CASPER, WY

8303290555 Forwards "Third Semiannual Rept, 820825-830218, for Bison Basin Project In Situ Leach U Mine."
CATCHPOLE, G. J. Ogle Petroleum, Inc. 83/03/10. SMITH, R. D. Uranium Recovery Field Office. 1p. 17743:047.

--8303290561 "Third Semiannual Rept, 820825-830218, for Bison Basin Project In Situ Leach U Mine."
* Ogle Petroleum, Inc. 83/03/10. 151pp. 17743:048.

8303090127 Requests rev to estimated reclamation costs, approved plan & Item IX of 1982 annual rept to show decontamination cost included in bond.
FRANCIS, E. Wyoming, State of. 83/02/08. CATCHPOLE, G. Ogle Petroleum, Inc. 1p. 17465:063.

8303170299 Addresses concern re licensing fees charged to Ogle Petroleum, Inc, arising from Congressman Cheney inquiry on proposed revised fee schedule. Licensee not overcharged.
DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director. 83/02/10. DIRCKS, W. J. Office of the Executive Director for Operations. 5pp. 17623:298.

8303090017 "Semiannual ALARA Audit, Jul-Dec 1982," submitted per License Condition 17.
BROWN, K. J. Ogle Petroleum, Inc. 83/02/15. Uranium Recovery Field Office. 3pp. 17466:175.

8303090011 Documents review of Ogle Petroleum, Inc second semiannual rept for in situ solution mining for period 820222-0824 & 820827 annual rept. Info satisfies requirements of License Condition 75.
YOUNG, Y. A.; LINEHAN, J. J. Uranium Recovery Field Office. 83/02/18. Uranium Recovery Field Office. 3pp. 17466:190.

8303090033 Notifies that computer analysis of leaky artesian aquifer test completed. Ratio method should be utilized for determination of vertical saturated hydraulic conductivity of confining layers.
WILLIAMS, R. E. R. E. Williams & Associates, Inc. 83/02/21. ROSS, F. Division of Waste Management. 3pp. 17466:082.

8303090589 Forwards corrected copies of tables for Wells M-43 & M-48. Encl tables reflect proper carbonate plus bicarbonate upper control limit & specific conductance for sample round four.
CATCHPOLE, G. J. Ogle Petroleum, Inc. 83/02/24. SMITH, R. D.; ROSS, F. Region 4, Office of Director. 3pp. 17480:144.

8303180060 Advises of amend to License SUA-1396, deleting Condition 21 to allow discontinuation of monthly personnel monitoring for external radiation. Periodic site monitoring still required.
SMITH, R. D. Uranium Recovery Field Office. 83/03/01. Ogle Petroleum, Inc. 1p. 17625:241.

--8303180065 Reviews Jan-June 1982 semiannual ALARA rept; in-plant radiation data & external radiation data repts. Semiannual rept fails to discuss performance of exposure & effluent control equipment & ways to reduce personnel exposure. YOUNG, Y. A. ; LINEHAN, J. J. Uranium Recovery Field Office. 83/02/15. Uranium Recovery Field Office. 6pp. 17625:242.

8303210435 Forwards fuel cycle & matls LER summary for Feb 1983. BROWN, G. D. Division of Vendor & Technical Programs. 83/03/16. DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director. MICHELSON, C. Director's Office. 3pp. 17634:134.

DOCKET 40-8752 PINAL MINERALS & MINING, LTD. ; MIAMI, AZ

8303180233 Forwards IE Insp Rept 40-8752/82-01 on 820922-23. No noncompliance noted. BROWN, G. D. Region 4, Office of Director. 83/01/19. CLARY, T. Pinal Minerals & Mining, Ltd. 2pp. 17616:163.

--8303180237 IE Insp Rept 40-8752/82-01 on 820922-23. No noncompliance noted. Major areas inspected: status of operation & efforts to contact individuals responsible for conduct of licensed activities. SPITZBERG, D. B. ; EVERETT, R. J. Region 4, Office of Director. 83/01/10. 4pp. 17616:165.

DOCKET 40-8768 KERR-MCGEE NUCLEAR CORP. ; OKLAHOMA CITY, OK

8303110041 Forwards application for amend of License SUA-1387, covering expansion of existing U recovery plant & addl R&D in-situ recovery well field to recover U from known U deposits. SHELLEY, W. J. Kerr-McGee Corp. 83/01/21. SMITH, R. D. Uranium Recovery Licensing Branch. 1p. 17526:217.

--8303110044 Application for amend of License SUA-1387, covering expansion of existing U recovery plant & addl R&D in-situ recovery well field to recover U from known U deposits W/two oversize figures. Aperture cards are available in PDR. * Kerr-McGee Corp. 83/01/31. 61pp. 17526:218.

8303090075 Forwards "Q-Sand In Situ U Recovery R&D Project, Fourth Quarter 1982." SHELLEY, W. J. Kerr-McGee Corp. 83/02/08. SCARANO, R. A. Division of Waste Management. 1p. 17466:001.

--8303090081 "Q-Sand In Situ U Recovery R&D Project, Fourth Quarter 1982." * Kerr-McGee Corp. 83/02/08. 51pp. 17466:002.

8303210435 Forwards fuel cycle & matls LER summary for Feb 1983. BROWN, G. D. Divis on of Vendor & Technical Programs. 83/03/16. DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 17634:134.

DOCKET 40-8773 PRECISE TOOL & DIE CO. ; WICKLIFFE, OH

8303220091 IE Insp Findings & Licensee Ack dtd 830310 of License SUC-1383. Insp findings: no violations observed. * Region 3, Office of Director. 83/03/10. 1p. 17650:052.

DOCKET 40-8783 URANERZ USA, INC. ; CASPER, WY

8303100040 Forwards "Const Rept Ruth Island Retention Ponds, Johnson County, WY." SOMERVILLE, K. G. Uranerz USA, Inc. 83/02/15. LINEHAN, J. J. Uranium Recovery Licensing Branch. 1p. 17492:196.

--8303100047 "Const Rept Ruth Island Retention Ponds, Johnson County, WY." W/three oversize figures. Aperture cards are available in PDR. * Chen & Associates, Inc. 82/09/10. 56pp. 17492:197.

DOCKET 40-8786 URANIUM RESOURCES, INC. ; RICHARDSON, TX

8303090421 Reviews ALARA rept for U Resources, Inc, North Platte Island R&D Project, Feb-Jul 1982. Presentation should include info for listed items of Condition 35 to License SUA-1400. WESTBROOK, K. B. ; LINEHAN, J. J. Uranium Recovery Field Office. 83/01/21. Uranium Recovery Field Office. 4pp. 17484:080.

8303170292 Forwards S. McArt diploma from Dept of Labor Natl Mine Health & Safety Academy radiation monitoring course. PELIZZA, M. S. Uranium Resources, Inc. 83/02/07. LINEHAN, J. J. Uranium Recovery Field Office. 2pp. 17623:203.

DOCKET 40-8820 AMAX ENVIRONMENTAL SERVICES, INC. ; GOLDEN, CO

8303020232 Submits results of first insp of Wood County, WV site after const of stabilization plan. Well monitoring & physical condition of site discussed. KERRIGAN, J. E. AMAX Environmental Services, Inc. (subs. of AMAX, Inc.). 83/02/10. NIXON, W. Uranium Fuel Licensing Branch. 9pp. 17355:334.

8303040369 Summary of 830208 meeting w/DOE & Aerospace Corp re remedial action responsibilities for various licensed or formerly licensed sites under provisions of Title II of U Mill Tailings Radiation Control Act of 1978. NIXON, W. A. Uranium Fuel Licensing Branch. 83/02/17. Uranium Fuel Licensing Branch. 2pp. 17426:319.

DOCKET 40-8829 WYOMING FUEL CO. ; LAKEWOOD, CO

8303230128 Forwards 830303 meeting attendee list. JONES, P. C. Wyoming Fuel Co. 83/03/08. SMITH, D. Uranium Recovery Field Office. 2pp. 17690:071.

8303220455 Expresses appreciation for attending 830303 meetings. NRC presence significantly added to discussion & created appropriate atmosphere at public meeting. JONES, P. C. Wyoming Fuel Co. 83/03/09. SMITH, D. Region 4, Office of Director. 1p. 17670:113.

## DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV. OF MICHIGAN RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8303030435 Submits proposed route for advanced approval. Route runs from Ann Arbor, MI to ID Falls, ID. KERR, W. Michigan, Univ. of. 83/01/18. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 17419:272. 24X Fiche: 50-002, 83/01/18, 8303030435.

8303140349 Forwards IE Safeguards Insp Rept 50-002/83-01 on 830223-25. No noncompliance noted. MILLER, J. R. Region 3, Office of Director. 83/03/09. KERR, W. Michigan, Univ. of. 2pp. 17544:141. 24X Fiche: 50-002, 83/03/09, 8303140349.

--8303140357 IE Safeguards Insp Rept 50-002/83-01 on 830223-25. No noncompliance noted. Major areas inspected: organization & operation, measurement & statistical controls & storage & internal controls. Details withheld (ref 10CFR2.790). MADEDA, T. J. ; PIRTLE, G. L. ; CREED, J. R. Region 3, Office of Director. 83/03/09. 1p. 17544:143. 24X Fiche: 50-002, 83/03/09, 8303140349.

Q. Inspection reports, IE Bulletins & correspondence

8303140349 Forwards IE Safeguards Insp Rept 50-002/83-01 on 830223-25. No noncompliance noted. MILLER, J. R. Region 3, Office of Director. 83/03/09. KERR, W. Michigan, Univ. of. 2pp. 17544:141. 24X Fiche: 50-002, 83/03/09, 8303140349.

--8303140357 IE Safeguards Insp Rept 50-002/83-01 on 830223-25. No noncompliance noted. Major areas inspected: organization & operation, measurement & statistical controls & storage & internal controls. Details withheld (ref 10CFR2.790). MADEDA, T. J. ; PIRTLE, G. L. ; CREED, J. R. Region 3, Office of Director. 83/03/09. 1p. 17544:143. 24X Fiche: 50-002, 83/03/09, 8303140349.

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8303110252 Advises that full-scale radiological emergency preparedness exercise planned for 830308, per Section IV.F of App E to 10CFR50. O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 82/11/09. NOVAK, T. M. Assistant Director for Operating Reactors. 2pp. 17520:053. 24X Fiche: 50-003, 82/11/09, 8303110252.

8303230047 Forwards schedule of activities associated w/830309 full-scale emergency preparedness exercise.
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/02/23.
HAYNES, R. C. Region 1, Office of Director. 6pp. 17665:041. 24X
Fiche: 50-003, 83/02/23, 8303230047.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

G. Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

R. Periodic operating reports & related correspondence

8303100199 Forwards "Personnel Whole Body Exposures for CY82."
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/03/01.
HAYNES, R. C. Region 1, Office of Director. 1p. 17488:358. 24X
Fiche: 50-003, 83/03/01, 8303100199.

--8303100203 "Personnel Whole Body Exposures for CY82."
* Consolidated Edison Co. of New York, Inc. 83/03/01. 2pp. 17488:359. 24X Fiche: 50-003, 83/03/01, 8303100199.

8303150551 Forwards "Effluent & Waste Disposal Semiannual Rept, Third & Fourth Quarter 1982."
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/03/01.
HAYNES, R. C. Region 1, Office of Director. 1p. 17568:064. 24X
Fiche: 50-003, 83/03/01, 8303150551.

--8303150569 "Effluent & Waste Disposal Semiannual Rept, Third & Fourth Quarter 1982."
* Consolidated Edison Co. of New York, Inc. 83/03/01. 46pp. 17568:065. 24X Fiche: 50-003, 83/03/01, 8303150551.

S. Reportable occurrences, LERs & related correspondence

8303240010 PNO-IE-83-004 informs of Rockland County Legislature resolutions prohibiting County officials from participating in 830309 exercise & requesting NY Governor to order plant shutdown.
CROCKER, H. W. Region 1, Office of Director. CUNNINGHAM, L. J. Director's Office, Office of Inspection and Enforcement. 83/03/07. 1p. 17681:101. 24X Fiche: 50-003, 83/03/07, 8303240010.

8303280170 Part 21 rept re transfer switches 3368180. Five transfer switches inspected & adjusted as necessary. New requirements added to test & adjustment procedure to review subassemblies for proper function. No other plants affected.
NAUMANN, H. R. Automatic Switch Co. 83/03/10. Region 4, Office of Director. 1p. 17706:318. 24X Fiche: 50-003, 83/03/10, 8303280170.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8303010595 Ack receipt of 830124 ltr identifying 1983 dates for emergency preparedness exercises within State of IL. Dates determined to be within required exercise frequency.
HIND, J. A. Region 3, Office of Director. 83/02/24. JONES, E. E. Illinois, State of. 2pp. 17336:208. 24X Fiche: 50-000, 83/02/24, 8303010595.

--8303010618 Submits 1983 dates scheduled for emergency preparedness exercises for facilities within State of IL.
JONES, E. E. Illinois, State of. 83/01/24. KEPPLER, J. Region 3, Office of Director. 2pp. 17336:210. 24X Fiche: 50-000, 83/02/24, 8303010595.

8303240587 Forwards IE Insp Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24 on 821203-05. No noncompliance noted. Summary of significant deficiencies encl.
KEPPLER, J. G. Region 3, Office of Director. 83/03/11. REED, C. Commonwealth Edison Co. 3pp. 17683:087. 24X Fiche: 50-010, 83/03/11, 8303240587.

--8303240597 IE Insp Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24 on 821203-05. No noncompliance noted. Major areas inspected: generating station emergency plan alert caused by flooding conditions.
TONGUE, T. M., STASEK, S., GULDEMOND, W. G. Region 3, Office of Director. 83/03/02. 12pp. 17683:090. 24X Fiche: 50-010, 83/03/11, 8303240587.

8303230143 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/16. Document Management Branch. 1p. 17687:120. 24X Fiche: 50-010, 83/03/16, 8303230143.

--8303230149 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 500-6, "Quarterly Operational Support Ctr Inventory (Primary Responsibility - Generating Station Emergency Plan Coordinator)."
SCOTT, D. J. Commonwealth Edison Co. 83/03/05. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17687:121. 24X Fiche: 50-010, 83/03/16, 8303230143.

--8303230155 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 500-6, "Quarterly Operational Support Ctr Inventory (Primary Responsibility - Generating Station Emergency Plan Coordinator)." W/revised index.
* Commonwealth Edison Co. 83/03/02. 5pp. 17687:122. 24X Fiche: 50-010, 83/03/16, 8303230143.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director. 83/03/22. Commonwealth Edison Co. 2pp. 17690:316. 24X Fiche: 50-000, 83/03/22, 8303240440.

8303310124 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/25. Document Management Branch. 1p. 17775:184. 24X Fiche: 50-000, 83/03/25, 8303310124.

--8303310130 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure EQ-1, "Coordination of Environs Group Activities by Environs Director."
* Commonwealth Edison Co. 83/03/17. Director's Office, Office of Inspection and Enforcement. 1p. 17775:185. 24X Fiche: 50-000, 83/03/25, 8303310124.

--8303310146 Public version of Rev 3 to Emergency Plan Implementing Procedure EQ-1, "Coordination of Environs Group Activities by Environs Director."
PAJOWSKI, J E. Commonwealth Edison Co. 83/03/08. 87pp.
17775:186. 24X Fiche: 50-000, 83/03/25, 8303310124.

8303300532 Releases public version of request for return of listed controlled copies of emergency plan.
PELTON, J M. Division of Rules and Records. 83/03/28. Document Management Branch. 1p. 17763:178. 24X Fiche: 50-000, 83/03/28, 8303300532.

--8303300561 Submits public version of request for return of listed controlled copies of emergency plan.
FLESSNER, R A. Commonwealth Edison Co. 83/03/15. DENTON, H R. Office of Nuclear Reactor Regulation, Director. 1p. 17763:179. 24X Fiche: 50-000, 83/03/28, 8303300532.

H. General correspondence

8303030528 Informs that DL Farrar has replaced LD DelGeorge as Director of Nuclear Licensing for util. Rev of current NRC distribution list requested.
FARRAR, D L. Commonwealth Edison Co. 83/02/02. DENTON, H R. Office of Nuclear Reactor Regulation, Director. 1p. 17409:048. 24X Fiche: 50-000, 83/02/02, 8303030528.

I. Financial information

8303070135 Forwards Annual Financial Rept 1982.
BRESEMANN, R W. Commonwealth Edison Co. 83/02/28. Division of Licensing. 1p. 17433:001. 24X Fiche: 50-000, 83/02/28, 8303070135.

--8303070151 Annual Financial Rept 1982.
O'CONNOR, J J. Commonwealth Edison Co. 83/02/03. 13pp.
17433:002. 24X Fiche: 50-000, 83/02/28, 8303070135.

J. Insurance & indemnity information

8303080197 Forwards Endorsements 74 & 61 to NELIA Policy NF-187 & MAELU Policy MF-54, respectively & Endorsements 141, 142, 119 & 120 to NELIA Policy NF-43 & MAELU Policy MF-22, respectively.
OSTER, J. Commonwealth Edison Co. 83/03/02. SALTZMAN, J. Antitrust & Economic analysis Branch (Utility Finance). 7pp. 17457:325. 24X Fiche: 50-000, 83/03/02, 8303080197.

8303160578 Forwards Endorsements 143, 75, 62 & 24 to NELIA Policies NF-43, NF-187, NF-201 & NF-253, respectively.
OSTER, J. Commonwealth Edison Co. 83/03/09. SALTZMAN, J. Assistant Director for State & Licensee Relations. 5pp. 17587:017. 24X Fiche: 50-000, 83/03/09, 8303160578.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J G. Region 3, Office of Director. 83/03/03. Commonwealth Edison Co. 2pp. 17492:014. 24X Fiche: 50-000, 83/03/03, 8303100364.

8303110246 Forwards Rev 23 to CE-1-A, "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments.
SWARTZ, E D. Commonwealth Edison Co. 83/03/04. HAASS, W P. Quality Assurance Branch. 1p. 17515:357. 24X Fiche: 50-000, 83/03/04, 8303110246.

--8303110279 Rev 23 to "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments.
SHEWSKI, W J. Commonwealth Edison Co. CE-1-A Rev 23. 83/03/07. 5pp.
17515:358. 24X Fiche: 50-000, 83/03/04, 8303110246.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

Q. Inspection reports, IE Bulletins & correspondence

8303030439 Forwards IE Insp Repts 50-010/82-22, 50-237/82-31 & 50-249/82-32 on 821202-830103 & 06. No noncompliance noted.
STREETER, J F. Division of Project & Resident Programs. 83/02/16. REED, C. Commonwealth Edison Co. 2pp. 17410:086. 24X Fiche: 50-010, 83/02/16, 8303030439.

--8303030446 IE Insp Repts 50-010/82-22, 50-237/82-31 & 50-249/82-32 on 821202-830103 & 06. No noncompliance noted. Major areas inspected: licensee action on previous insp findings, headquarters request, operational safety & maint.
TONGUE, T M., JORDAN, M J., STASEK, S. Division of Project & Resident Programs. 83/02/15. 13pp. 17410:088. 24X Fiche: 50-010, 83/02/16, 8303030439.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303170532 Forwards IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al., on 830126. No noncompliance noted.
DAVIS, A B. Region 3, Office of Director. 83/02/25. REED, C. Commonwealth Edison Co. 2pp. 17610:143. 24X Fiche: 50-000, 83/02/25, 8303170532.

--8303170557 IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al., on 830126. No noncompliance noted. Major areas discussed: proposed guidelines util personnel should use for providing info to Region III inspectors.
GULDEMOND, W G., WALKER, R D. Division of Project & Resident Programs. 83/02/15. 4pp. 17610:145. 24X Fiche: 50-000, 83/02/25, 8303170532.

8303180391 Forwards IE Insp Repts 50-010/83-02, 50-237/83-02 & 50-249/83-02 on 830112-14. No noncompliance noted.
LITTLE, W S. Region 3, Office of Director. 83/02/25. REED, C. Commonwealth Edison Co. 2pp. 17621:351. 24X Fiche: 50-010, 83/02/25, 8303180391.

--8303180396 IE Insp Repts 50-010/83-02, 50-237/83-02 & 50-249/83-02 on 830112-14. No noncompliance noted. Major areas inspected: licensee action on previous findings, licensed & nonlicensed employee training & employee requalification training.
FARRELL, R E., HAWKINS, F C. Region 3, Office of Director. 83/02/16. 4pp. 17621:353. 24X Fiche: 50-010, 83/02/25, 8303180391.

8303030580 Clarifies NRC position re procedures for admitting NRC personnel to facilities. Site orientation re issuance of badges, escort duties & emergency evacuation for personnel listed in Encls 1 & 2 requested.
KEPPLER, J G. Region 3, Office of Director. 83/02/28. REED, C. Commonwealth Edison Co. 6pp. 17409:340. 24X Fiche: 50-010, 83/02/28, 8303030580.

8303170371 Forwards IE Insp Repts 50-010/83-05, 50-237/83-05 & 50-249/83-04 on 830104-0202 & notice of violation.
STREETER, J F. Division of Project & Resident Programs. 83/03/04. REED, C. Commonwealth Edison Co. 2pp. 17610:057. 24X Fiche: 50-010, 83/03/04, 8303170371.

--8303170375 Notice of violation from insp on 830104-0202.
STREETER, J F. Division of Project & Resident Programs. 83/03/04. 1p. 17610:059. 24X Fiche: 50-010, 83/03/04, 8303170371.

--8303170377 IE Insp Repts 50-010/83-05, 50-237/83-05 & 50-249/83-04 on 830104-0202. Noncompliance noted: failure to incorporate Tech Specs issued w/Amend 71 to License DPR-19 into current copy of Tech Specs.
TONGUE, T M., JORDAN, M J., STASEK, S. Region 3, Office of Director. 83/02/23. 9pp. 17610:060. 24X Fiche: 50-010, 83/03/04, 8303170371.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303240587 Forwards IE Insp Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24 on 821203-05 No noncompliance noted. Summary of significant deficiencies encl.
KEPPLER, J. G. Region 3, Office of Director 83/03/11 REED, C.
Commonwealth Edison Co 3pp 17683:087 24X Fiche: 50-010, 83/03/11, 8303240587.

--8303240597 IE Insp Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24 on 821203-05 No noncompliance noted. Major areas inspected: generating station emergency plan alert caused by flooding conditions.
TONGUE, T. M., JORDAN, M. J., WALKER, R. D. Region 3, Office of Director 83/03/02 12pp 17683:090 24X Fiche: 50-010, 83/03/11, 8303240587.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

R. Periodic operating reports & related correspondence

8303110241 Forwards monthly operating repts for Feb 1983.
SCOTT, D. J. Commonwealth Edison Co. 83/03/01 Director's Office, Office of Inspection and Enforcement 1p 17520:174 24X
Fiche: 50-010, 83/03/01, 8303110241.

--8303110248 Monthly operating repts for Feb 1983.
SCHROEDER, R. A. Commonwealth Edison Co. 83/03/01 13pp
17520:175 24X Fiche: 50-010, 83/03/01, 8303110241.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp 24X Fiche: 50-000, 83/02/24, 8302250505.

8303040631 Forwards listing of projected operator licensing exam dates including type of exam & probable number of candidates, in response to 830111 Generic Ltr 83-01.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/01 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 4pp 17367:209 24X
Fiche: 50-000, 83/03/01, 8303040631.

DOCKET 50-16 ENRICO FERMI ATOMIC POWER PLANT, UNIT 1

J. Insurance & indemnity information

8303300203 Forwards Endorsement 102 to NELIA Policy NF-92.
MATERS, B. R. Detroit Edison Co. 83/03/25 DINITZ, I. Office of State Programs, Director 2pp 17732:280 24X
Fiche: 50-016, 83/03/25, 8303300203.

W. Decommissioning Stage Documents & Correspondence

8303220413 EVALUATION OF NUCLEAR DECOMMISSIONING PROJECTS Project Summary Report, Enrico Fermi-1 Reactor.
MILLER, R. L., LINK, B. W. United Nuclear Corp. FIN B-7568.
NUREG/CR-3116 83/02/28 Division of Engineering Technology 28pp Available at NRC $4.75 17667:142 24X
Fiche: 50-016, 83/02/28, 8303220413.

DOCKET 50-18 VALLECITOS BOILING WATER REACTOR

R. Periodic operating reports & related correspondence

8303170374 Forwards "Vallecitos BWR Annual Rept 18 (Deactivated), 1982."
CUNNINGHAM, G. E. General Electric Co. 83/02/11 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 17609:314 24X
Fiche: 50-018, 83/02/11, 8303170374.

--8303170395 "Vallecitos BWR Annual Rept 18 (Deactivated), 1982."
TITUS, G. W. General Electric Co. 83/02/11 4pp 17609:315 24X
Fiche: 50-018, 83/02/11, 8303170374.

## DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-20 MASSACHUSETTS INST. OF TECH. RES. REACTOR

P. Operating license stage documents & correspondence

8303100487 Responds to 821213 ltr re transfer of nonpower reactor licensing functions to regional ofcs. Transfer delayed pending input from public meetings w/licensees & research, test & reactor community.
DIRCKS, W. J. Office of the Executive Director for Operations 83/03/02 CLARK, L. Massachusetts Institute of Technology 4pp
17503:151 24X Fiche: 50-020, 83/03/02, 8303100487.

--8303100490 Expresses concern over possible detriments of regionalizing nonpower reactor licensing functions. Regionalization may cause inconsistent application of regulatory requirements. NRC should seek nonpower reactor licensee input.
CLARK, L. Massachusetts Institute of Technology 82/12/13.
PALLADINO, N. J. Commissioners. 2pp 17503:155 24X
Fiche: 50-020, 83/03/02, 8303100487.

8303230218 Forwards Amend 23 to License R-37 & safety evaluation. Amend authorizes changes in frequency of surveillance testing of ECCS & charcoal filters in bldg pressure relief sys.
THOMAS, C. O. Standardization & Special Projects Branch 83/03/15
CLARK, L. Massachusetts Institute of Technology 3pp 17686:202
24X Fiche: 50-020, 83/03/15, 8303230218.

--8303230223 Amend 23 to License R-37, changing Tech Specs to authorize change in frequencies of surveillance testing of ECCS & charcoal filters in bldg pressure relief sys.
THOMAS, C. O. Standardization & Special Projects Branch 83/03/15
6pp 17686:205 24X Fiche: 50-020, 83/03/15, 8303230218.

--8303230226 Safety evaluation supporting Amend 23 to License R-37.
* Office of Nuclear Reactor Regulation, Director 83/03/15 7pp
17686:211 24X Fiche: 50-020, 83/03/15, 8303230218.

8303280003 Ack receipt of 830315 ltr forwarding Amend 23 to License R-37. Word "sys" should be inserted after ECS spray nozzle in Tech Spec 4.1-1.
CLARK, L. Massachusetts Institute of Technology 83/03/23.
THOMAS, C. O. Standardization & Special Projects Branch 1p.
17707:350 24X Fiche: 50-020, 83/03/23, 8303280003.

Q. Inspection reports, IE Bulletins & correspondence

8303160477 Forwards IE Insp Rept 50-020/83-01 on 830125-28 & notice of violation.
STAROSTECKI, R. Division of Project & Resident Programs 83/03/03.
CLARK, L. Massachusetts Institute of Technology 2pp 17593:013.
24X Fiche: 50-020, 83/03/03, 8303160477.

--8303160481 Notice of violation from insp on 830125-28.
* Division of Project & Resident Programs 83/03/03 1p.
17593:015 24X Fiche: 50-020, 83/03/03, 8303160477.

--8303160488 IE Insp Rept 50-020/83-01 on 830125-28 Noncompliance noted: failure to have procedures for & to perform containment differential pressure instrument calibr & annual verification of interlock trip point.
KINNEY, W. W., KEIMIG, R. R. Division of Project & Resident Programs
83/03/01 12pp 17593:016 24X Fiche: 50-020, 83/03/03, 8303160477.

DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION

F. Security, medical, emergency & fire protection plans

8303110199 Identifies completed SEP Topics II-4.E re dam integrity, III-7.B re design criteria, VI-1 re organic matls & post-accident chemistry, IX-6 re fire protection & XV-2 re steam sys piping failures.
CRUTCHFIELD, D. Operating Reactors Branch 5 83/01/27 KAY, J. A.
Yankee Atomic Electric Co. 3pp 17517:358 24X
Fiche: 50-029, 83/01/27, 8303110199.

8303090637 Releases public version of page to revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records 83/03/02 Document Management Branch 1p 17480:280 24X Fiche: 50-029, 83/03/02, 8303090637.

--8303090644 Forwards public version of P 12-10 to Rev 3 to Emergency Plan Implementing Procedure 12.0, "Maintaining Preparedness." Receipt form encl.
MARKT, D. Yankee Atomic Electric Co. 83/02/15 Document Management Branch 1p 17480:281 24X Fiche: 50-029, 83/03/02, 8303090637.

--8303090664 Public version of P 12-10 to Rev 3 to Emergency Plan Implementing Procedure 12.0, "Maintaining Preparedness."
* Yankee Atomic Electric Co. 83/01/31. 2pp. 17480:282. 24X
Fiche: 50-029, 83/03/02, 8303090637.

8303090671 Releases public version of rev to emergency plan implementing procedures table of contents.
FELTON, J. M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17480:236. 24X Fiche: 50-029, 83/03/02, 8303090671.

--8303090674 Forwards public version of Rev 22 to emergency plan implementing procedures table of contents. Receipt form encl.
MARKT, D. Yankee Atomic Electric Co. 83/02/11. Document Management Branch. 1p. 17480:237. 24X Fiche: 50-029, 83/03/02, 8303090671.

--8303090679 Public version of Rev 22 to emergency plan implementing procedures table of contents.
* Yankee Atomic Electric Co. 83/02/08. 2pp. 17480:238. 24X
Fiche: 50-029, 83/03/02, 8303090671.

8303100541 Releases public version of revised emergency plan implementing procedure table of contents.
FELTON, J. M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17521:270. 24X Fiche: 50-029, 83/03/02, 8303100541.

--8303100546 Forwards public version of Rev 23 to emergency plan implementing procedure table of contents.
MARKT, D. I. Yankee Atomic Electric Co. 83/02/17. NRC - No Detailed Affiliation Given. 1p. 17521:271. 24X
Fiche: 50-029, 83/03/02, 8303100541.

--8303100550 Public version of Rev 23 to emergency plan implementing procedure table of contents.
* Yankee Atomic Electric Co. 83/02/15. 2pp. 17521:272. 24X
Fiche: 50-029, 83/03/02, 8303100541.

8303160516 Forwards IE Insp Rept 50-029/83-02 on 830101-0207. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/03. HEIDER, L. H. Yankee Atomic Electric Co. 2pp. 17592:253. 24X
Fiche: 50-029, 83/03/03, 8303160516.

--8303160526 IE Insp Rept 50-029/83-02 on 830101-0207. No noncompliance noted. Major areas inspected: action on previous items, operational safety verification reviews, plant maint & surveillance observation & IE bulletin followup.
COLLINS, S. J. Region 1, Office of Director. GALLO, R. M. Division of Project & Resident Programs. 83/03/01. 17pp. 17592:255. 24X
Fiche: 50-029, 83/03/03, 8303160516.

8303160524 Forwards IE Safeguards Insp Rept 50-029/83-01 on 830117-20. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/04. HEIDER, L. H. Yankee Atomic Electric Co. 2pp. 17587:221. 24X
Fiche: 50-029, 83/03/04, 8303160524.

--8303160544 IE Safeguards Insp Rept 50-029/83-01 on 830117-20. No noncompliance noted. Major areas inspected: security plan & implementing procedures & program audit records. Safeguards info deleted (ref 10CFR73.21 or 10CFR9.5(a)(4)).
DUNLAP, J. M., GODY, A. T. Region 1, Office of Director. 83/03/02. 4pp. 17587:223. 24X Fiche: 50-029, 83/03/04, 8303160524.

8303240115 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/21. Document Management Branch. 1p. 17700:247. 24X Fiche: 50-029, 83/03/21, 8303240115.

--8303240118 Forwards public version of Rev 2 to Emergency Plan Implementing Procedure DP-3344, "Security Force Actions Under Emergency Conditions."
MARKT, D. Yankee Atomic Electric Co. 83/03/14. NRC - No Detailed Affiliation Given. 2pp. 17700:248. 24X
Fiche: 50-029, 83/03/21, 8303240115.

--8303240123 Public version of Rev 2 to Emergency Plan Implementing Procedure DP-3344, "Security Force Actions Under Emergency Conditions." Revised index encl.
* Yankee Atomic Electric Co. 83/03/09. 6pp. 17700:250. 24X
Fiche: 50-029, 83/03/21, 8303240115.

## J. Insurance & indemnity information

8303140290 Forwards Endorsement 103 to NELIA Policy NF-76.
BINISI, J. M. Marsh & McLennan, Inc. 83/03/08. SALTZMAN, J. D. Assistant Director for State & Licensee Relations. 2pp. 17535:056. 24X Fiche: 50-029, 83/03/08, 8303140290.

## P. Operating license stage documents & correspondence

8303110199 Identifies completed SEP Topics II-4.E re dam integrity, III-7.B re design criteria, VI-1 re organic matls & post-accident chemistry, IX-6 re fire protection & XV-2 re steam sys piping failures.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/01/27. KAY, J. A. Yankee Atomic Electric Co. 3pp. 17517:358. 24X
Fiche: 50-029, 83/01/27, 8303110199.

8302220002 Forwards SERs referenced in App E of integrated plant safety assessment rept (NUREG-0825), for use in review of NUREG.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/02/10. KAY, J. J. ACRS - Advisory Committee on Reactor Safeguards. 1p. 17459:122. 24X Fiche: 50-029, 83/02/10, 8302220002.

--8303090067 Forwards draft safety evaluation re SEP Topic III-1, "Quality Group Classification of Components & Sys." Remaining open items not expected to pose significant hazard for continued operation. Response requested within 30 days.
CARUSO, R. Operating Reactors Branch 5. 82/06/18. KAY, J. A. Yankee Atomic Electric Co. 7pp. 17461:072. 24X
Fiche: 50-029, 83/02/10, 8302220002.

--8303090076 Forwards final evaluation of SEP Topic III-4.A, "Tornado Missiles." Sys & components at facility sufficiently protected from tornado missiles.
CARUSO, R. Operating Reactors Branch 5. 82/08/31. KAY, J. A. Yankee Atomic Electric Co. 25pp. 17462:022. 24X
Fiche: 50-029, 83/02/10, 8302220002.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303030134 Forwards Amend 80 to License DPR-3, safety evaluation & notice of issuance & availability. Amend incorporates changes developed to keep releases of radioactive matl to unrestricted areas ALARA.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/02/16. KAY, J. A. Yankee Atomic Electric Co. 3pp. 17413:233. 24X
Fiche: 50-029, 83/02/16, 8303030134.

--8303030141 Amend 80 to License DPR-3, incorporating changes developed to keep releases of radioactive matl to unrestricted areas ALARA.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/02/16. 102pp. 17413:237. 24X Fiche: 50-029, 83/02/16, 8303030134.

--8303030145 Safety evaluation supporting Amend 80 to License DPR-3.
* Office of Nuclear Reactor Regulation, Director. 83/02/16. 7pp. 17413:339. 24X Fiche: 50-029, 83/02/16, 8303030134.

--8212020263 "Radiological Effluent Tech Spec Implementation (A-2), Yankee Rowe Atomic Power Station," technical evaluation rept.
CHEN, S. Y. Franklin Inst. ute/Franklin Research Center. NRC-03-81-130. TER-C5506 117. 82/11/30. CONGEL, F. NRC - No Detailed Affiliation Given. 30pp. 17413:346. 24X
Fiche: 50-029, 83/02/16, 8303030134.

--8303030153 Notice of issuance & availability of Amend 80 to License DPR-3.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/02/16. 2pp. 17414:014. 24X Fiche: 50-029, 83/02/16, 8303030134.

8303090683 INTEGRATED PLANT SAFETY ASSESSMENT REPORT, SYSTEMATIC EVALUATION PROGRAM-YANKEE NUCLEAR POWER STATION. Docket No. 50-029. (Yankee Atomic Electric Company)
* Division of Licensing. NUREG-0825. 83/02/28. 548pp. Available at NRC $12.00. 17474:001. 24X Fiche: 50-029, 83/02/28, 8303090683.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303110045 Provides addl info on changes to primary vent stack monitoring sys. Listed mods to be implemented by 830301.
KAY, J. A. Yankee Atomic Electric Co. 83/03/04. HAYNES, R. C. Region 1, Office of Director. 2pp. 17506:361. 24X Fiche: 50-029, 83/03/04, 8303110045.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176 24X
Fiche: 5 1-000, 83/03/07, 8303040005

8303150322 Requests relief from requirement to install reactor vessel water level sys per Generic Ltr 82-28. Justification & details discussion on existing inadequate core cooling instrumentation & procedures provided.
HEIDER, L. H. Yankee Atomic Electric Co. 83/03/10. CRUTCHFIELD, D. Operating Reactors Branch 5. 35pp. 17562:317 24X
Fiche: 50-029, 83/03/10, 8303150322

8303150509 Forwards Rev 12 to operational QA program addressing organizational changes.
JOHNSON, W. P. Yankee Atomic Electric Co. 83/03/11. HAASS, W. P. Division of Engineering & Quality Assurance (Pre 830103). 1p. 17560:118 24X Fiche: 50-000, 83/03/11, 8303150509.

--8303150518 Rev 12 to operational QA program for facilities.
MARTIN, R. L.; PIKE, D. B.; SHEPARD, A. M. Yankee Atomic Electric Co. YQAP-1-A R12. 83/03/11. 131pp. 17560:119 24X
Fiche: 50-000, 83/03/11, 8303150509.

8303170261 Forwards order confirming licensee commitments to implement post-TMI related items in NUREG-0737, per 820317 & 0505 responses to Generic Ltrs 82-05 & 82-10, respectively. Util proposed implementation schedule acceptable.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/03/14. KAY, J. A. Yankee Atomic Electric Co. 3pp. 17606:163 24X
Fiche: 50-029, 83/03/14, 8303170261.

--8303170271 Order confirming licensee commitments on post-TMI related issues. Lists of licensee commitments on applicable NUREG-0737 requirements from Generic Ltrs 82-05 & 82-10 encl.
EISENHUT, D. G. Division of Licensing 83/03/14 Yankee Atomic Electric Co. 8pp. 17606:166 24X Fiche: 50-029, 83/03/14, 8303170261.

8303240413 Forwards "Core XVI Startup Program," per Tech Spec Section 6.9.1.
KAY, J. A. Yankee Atomic Electric Co. 83/03/14. HAYNES, R. C. Region 1, Office of Director. 1p. 17678:297 24X Fiche: 50-029, 83/03/14, 8303240413.

--8303240415 "Core XVI Startup Program."
WILLIAMS, F. N.; MORRISSEY, K. J.; HENDERSON, T. K. Yankee Atomic Electric Co. 83/03/11. 44pp. 17678:298 24X
Fiche: 50-029, 83/03/14, 8303240413.

8303280033 Forwards addl info on SEP Topic VI-4, "Containment Isolation," supplementing 821223 ltr. All test vent & drain lines meet min requirements of at least one sealed-closed valve per line.
KAY, J. A. Yankee Atomic Electric Co. 83/03/16. CRUTCHFIELD, D. Operating Reactors Branch 5. 6pp. 17707:211 24X
Fiche: 50-029, 83/03/16, 8303280033.

8303280021 Extends gratuitous remarks for NRC correction of erroneous statement re scram breaker classification which appeared in 830316 Washington Post.
EDWARDS, D. M. Yankee Atomic Electric Co. 83/03/23. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17707:345 24X Fiche: 50-029, 83/03/23, 8303280021.

## Q. Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303160516 Forwards IE Insp Rept 50-029/83-02 on 830101-0207. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/03. HEIDER, L. H. Yankee Atomic Electric Co. 2pp. 17592:253 24X
Fiche: 50-029, 83/03/03, 8303160516.

--8303160526 IE Insp Rept 50-029/83-02 on 830101-0207. No noncompliance noted. Major areas inspected: action on previous items, operational safety verification reviews, plant maint & surveillance observation & IE bulletin followup.
COLLINS, S.; Region 1, Office of Director. GALLO, R. M. Division of Project & Resident Programs. 83/03/01. 17pp. 17592:255 24X
Fiche: 50-029, 83/03/03, 8303160516.

8303160524 Forwards IE Safeguards Insp Rept 50-029/83-01 on 830117-20. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/04. HEIDER, L. H. Yankee Atomic Electric Co. 2pp. 17587:221 24X
Fiche: 50-029, 83/03/04, 8303160524.

--8303160544 IE Safeguards Insp Rept 50-029/83-01 on 830117-20. No noncompliance noted. Major areas inspected: security plan & implementing procedures & program audit records. Safeguards info deleted (ref 10CFR73.21 or 10CFR9.5(a)(4)).
DUNLAP, J. M.; GODY, A. T. Region 1, Office of Director. 83/03/02. 4pp. 17587:223 24X Fiche: 50-029, 83/03/04, 8303160524.

8303170164 Responds to IE Bulletin 83-01 re failure of Westinghouse DB-50 breakers to open on automatic trip signal. Facility does not use Westinghouse DB-type breakers in reactor protective sys applications.
HEIDER, L. H. Yankee Atomic Electric Co. 83/03/04. HAYNES, R. C. Region 1, Office of Director. 1p. 17609:081 24X
Fiche: 50-029, 83/03/04, 8303170164.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8303180009 Requests rev to inservice insp program, Section 3.10, "Personnel Qualification Requirements." Exemption from Section XI of ASME Code will be permanent addition to inservice insp program for hydrostatic exams.
KAY, J. A. Yankee Atomic Electric Co. 83/03/15. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 17618:127 24X
Fiche: 50-029, 83/03/15, 8303180009.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

## R. Periodic operating reports & related correspondence

8303080361 Forwards monthly operating rept for Dec 1982.
HEIDER, L. H. Yankee Atomic Electric Co. 83/01/11. Office of Resource Management, Director. 1p. 17453:249 24X
Fiche: 50-029, 83/01/11, 8303080361.

--8303080369 Monthly operating rept for Dec 1982.
BATTERSON, S. Yankee Atomic Electric Co. 83/01/11. 5pp. 17453:250 24X Fiche: 50-029, 83/01/11, 8303080361.

8303150549 Forwards monthly operating rept for Jan 1983.
HEIDER, L. H. Yankee Atomic Electric Co. 83/02/07. Office of Resource Management, Director. 1p. 17568:323 24X
Fiche: 50-029, 83/02/07, 8303150549.

--8303150556 Monthly operating rept for Jan 1983.
BATTERSON, S. Yankee Atomic Electric Co. 83/02/07. 5pp. 17568:324 24X Fiche: 50-029, 83/02/07, 8303150549.

8303090365 Forwards "Yankee Personnel & Man-Rem By Work & Duty Function Rept, 1982."
HEIDER, L. H. Yankee Atomic Electric Co. 83/02/28. HAYNES, R. C. Region 1, Office of Director. 1p. 17471:327 24X
Fiche: 50-029, 83/02/28, 8303090365.

--8303090370 "Yankee Personnel & Man-Rem By Work & Duty Function Rept, 1982."
* Yankee Atomic Electric Co. 83/02/24. 1p. 17471:328 24X
Fiche: 50-029, 83/02/28, 8303090365.

8303100311 Forwards annual rept 1982 describing facility changes, tests & experiments conducted w/o NRC prior approval & summary of safety & relief valve failures & challenges required by TMI Item II.K.3.3.
HEIDER, L. H. Yankee Atomic Electric Co. 83/03/01. HAYNES, R. C. Region 1, Office of Director. 1p. 17489:266 24X
Fiche: 50-029, 83/03/01, 8303100311.

--8303100321 Annual rept 1982.
* Yankee Atomic Electric Co. 83/03/01. 15pp. 17489:267 24X
Fiche: 50-029, 83/03/01, 8303100311.

8303100375 Forwards "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1982."
HEIDER, L. H. Yankee Atomic Electric Co. 83/03/01 HAYNES, R. C.
Region 1, Office of Director. 1p. 17488:270. 24X
Fiche: 50-029, 83/03/01, 8303100375.

--8303100376 "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1982."
* Yankee Atomic Electric Co. 83/03/01 11pp. 17488:271. 24X
Fiche: 50-029, 83/03/01, 8303100375.

B. Reportable occurrences, LERs & related correspondence

8303010402 Forwards LER 83-004/03L-0.
AUTIO, H. A. Yankee Atomic Electric Co. 83/02/18. HAYNES, R. C.
Region 1, Office of Director. 1p. 17343:354. 24X
Fiche: 50-029, 83/02/18, 8303010402.

--8303010404 LER 83-004/03L-0 on 830119, during Mode 3, primary vent stack airborne radioactivity monitor failed. Caused by frozen sample lines due to missing pipe insulation. Insulation installed. Moisture removal sys being upgraded.
RICE, D. A. Yankee Atomic Electric Co. 83/02/18 Region 1, Office of Director. 1p. 17343:355. 24X Fiche: 50-029, 83/02/18, 8303010402.

8303010629 Forwards LER 83-002/03L-0.
AUTIO, H. A. Yankee Atomic Electric Co. 83/02/18. HAYNES, R. C.
Region 1, Office of Director. 1p. 17336:136. 24X
Fiche: 50-029, 83/02/18, 8303010629.

--8303010638 LER 83-002/03L-0 on 830119, containment air lock leakage rate exceeded Tech Spec 3.6.1.3b Caused by ice interfering w/sealing surface. Ice removed. Seating surface & O-ring inspected & retested.
FRENCH, L. D. Yankee Atomic Electric Co. 83/02/18 Region 1, Office of Director. 1p. 17336:137. 24X Fiche: 50-029, 83/02/18, 8303010629.

8303010674 Forwards LER 83-003/03L-0.
AUTIO, H. A. Yankee Atomic Electric Co. 83/02/18. HAYNES, R. C.
Region 1, Office of Director. 1p. 17336:179. 24X
Fiche: 50-029, 83/02/18, 8303010674.

--8303010679 LER 83-003/03L-0 on 830119, during recovery from reactor scram while in Mode 3, coolant sys subcooling margin monitor failed. Caused by loss of one of eight in-core thermocouple inputs. Thermocouple replaced.
MAY, E. L. Yankee Atomic Electric Co. 83/02/18 Region 1, Office of Director. 1p. 17336:180. 24X Fiche: 50-029, 83/02/18, 8303010674.

8303040450 Forwards LER 83-005/03L-0.
AUTIO, H. A. Yankee Atomic Electric Co. 83/02/22. HAYNES, R. C.
Region 1, Office of Director. 1p. 17368:006. 24X
Fiche: 50-029, 83/02/22, 8303040450.

--8303040456 LER 83-005/03L-0 on 830123, while in Mode 1, primary vent stack noble gas & particulate monitors failed. Caused by moisture in detectors as result of in-line air dryers inability to remove moisture. Noble gas detector rebuilt.
RICE, D. A. Yankee Atomic Electric Co. 83/02/22 Region 1, Office of Director. 1p. 17368:007. 24X Fiche: 50-029, 83/02/22, 8303040450.

8303090139 Forwards LER 83-006/03L-0.
AUTIO, H. A. Yankee Atomic Electric Co. 83/02/25. HAYNES, R. C.
Region 1, Office of Director. 1p. 17472:360. 24X
Fiche: 50-029, 83/02/25, 8303090139.

--8303090224 LER 83-006/03L-0 on 830128, fire protection carbon dioxide sys in manhole 3 taken out of svc during corrective maint on manhole sump pump for personnel safety reasons. Caused by carbon dioxide health hazard at sys design concentration.
MAY, E. L. Yankee Atomic Electric Co. 83/02/25 Region 1, Office of Director. 1p. 17472:361. 24X Fiche: 50-029, 83/02/25, 8303090139.

8303140529 Forwards LER 83-007/03L-0.
AUTIO, H. A. Yankee Atomic Electric Co. 83/03/04. HAYNES, R. C.
Region 1, Office of Director. 1p. 17541:060. 24X
Fiche: 50-029, 83/03/04, 8303140529.

--8303140538 LER 83-007/03L-0 on 830204, zone 1 & special hazards header alarm check valve isolated alternately to repair alarm port auxiliary valve. Caused by improper alarm port valve operation. Auxiliary valve disc replaced.
MAY, E. L. Yankee Atomic Electric Co. 83/03/04 Region 1, Office of Director. 1p. 17541:061. 24X Fiche: 50-029, 83/03/04, 8303140529.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-30 PLUM BROOK RESEARCH REACTOR FACILITY

R. Periodic operating reports & related correspondence

8303160213 Forwards rept of reactor dismantling status for 1982.
BOITEL, E. C. National Aeronautics & Space Admin. 83/03/09.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp.
17596:298. 24X Fiche: 50-030, 83/03/09, 8303160213.

--8303160219 Rept of reactor dismantling status for 1982.
* National Aeronautics & Space Admin. 83/02/03. 7pp. 17596:300.
24X Fiche: 50-030, 83/03/09, 8303160213.

W. Decommissioning Stage Documents & Correspondence

8303160213 Forwards rept of reactor dismantling status for 1982.
BOITEL, E. C. National Aeronautics & Space Admin. 83/03/09.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp.
17596:298. 24X Fiche: 50-030, 83/03/09, 8303160213.

--8303160219 Rept of reactor dismantling status for 1982.
* National Aeronautics & Space Admin. 83/02/03. 7pp. 17596:300.
24X Fiche: 50-030, 83/03/09, 8303160213.

DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR

P. Operating license stage documents & correspondence

8303300179 Forwards Amend 19 to License R-81 & safety evaluation. Amend deletes Note D to Tech Spec removing requirement that ion chamber of third channel be operable prior to reactor startup.
THOMAS, C. O. Standardization & Special Projects Branch. 83/03/22.
MCGOVERN, J. Union Carbide Corp. 2pp. 17763:088. 24X
Fiche: 50-054, 83/03/22, 8303300179.

--8303300186 Amend 19 to License R-81, deleting note D to Tech Spec removing requirement that ion chamber of third channel be operable prior to reactor startup.
THOMAS, C. O. Standardization & Special Projects Branch. 83/03/22.
4pp. 17763:090. 24X Fiche: 50-054, 83/03/22, 8303300179.

--8303300192 Safety evaluation supporting Amend 19 to License R-81.
* Office of Nuclear Reactor Regulation, Director. 83/03/22. 2pp.
17763:094. 24X Fiche: 50-054, 83/03/22, 8303300179.

DOCKET 50-57 STATE UNIV. OF NEW YORK RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8303090168 Forwards revised security plan. Rev withheld (ref 10CFR2.790).
ORLOSKY, P. M. New York, State Univ. of, Buffalo. 83/02/11. Office of Nuclear Material Safety & Safeguards, Director. 1p. 17471:319.
24X Fiche: 50-057, 83/02/11, 8303090168.

8303160425 Forwards revised security plan. Rev conforms w/10CFR73.67(f) & Reg Guide 5.59 W/o encl.
HENRY, L. Q. New York, State Univ. of, Buffalo. 83/03/11.
THOMAS, C. O. Standardization & Special Projects Branch. 1p.
17592:341. 24X Fiche: 50-057, 83/03/11, 8303160425.

P. Operating license stage documents & correspondence

8303160345 Forwards partial response to 830121 questions in support of application for renewal of License R-77. Radiological release data for 1978 - 1982 also encl.
HENRY, L. Q. New York, State Univ. of, Buffalo. 83/03/10.
THOMAS, C. O. Standardization & Special Projects Branch. 61pp.
17595:256. 24X Fiche: 50-057, 83/03/10, 8303160345.

# DOCKETED ITEMS

8303160437 Forwards partial response to 830121 questions re application for renewal of OL. Complete answers will be submitted within 2 wks. W/o encl.
HENRY, L. G. New York, State Univ. of, Buffalo. 83/03/11.
THOMAS, C. O. Standardization & Special Projects Branch. 1p.
17592:338. 24X Fiche: 50-057, 83/03/11, 8303160437.

R Periodic operating reports & related correspondence

8303160345 Forwards partial response to 830121 questions in support of application for renewal of License R-77. Radiological release data for 1978 - 1982 also encl.
HENRY, L. G. New York, State Univ. of, Buffalo. 83/03/10.
THOMAS, C. O. Standardization & Special Projects Branch. 6lpp.
17595:256. 24X Fiche: 50-057, 83/03/10, 8303160345.

DOCKET 50-59 TEXAS A&M UNIV. RESEARCH REACTOR

H General correspondence

8303140212 Informs that DE Feltz has accepted position of director of Nuclear Science Ctr.
ERDMAN, C. A. Texas A&M Univ., College Station, TX. 83/03/08.
BERNARD, H. Standardization & Special Projects Branch. 1p.
17540:078. 24X Fiche: 50-059, 83/03/08, 8303140212.

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

Q Adjudicatory correspondence

8303240593 Decision ALAB-720, affirming ASLB 820816 Initial Decision LBP-82-64. Deflected soil displacement is not major safety concern.
SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 83/03/23.
10pp. 17683:072. 24X Fiche: 50-070, 83/03/23, 8303240593.

P Operating license stage documents & correspondence

8303040653 Forwards Amend 11 to License TR-1, safety evaluation & notice of issuance & availability. Amend deletes requirements for maintaining containment calibr testing requirements.
EISENHUT, D. G. Division of Licensing. 83/02/23. DARMIZEL, R. W. General Electric Co. 2pp. 17429:245. 24X Fiche: 50-070, 83/02/23, 8303040653.

--8303040654 Amend 11 to License TR-1, deleting requirements for maintaining containment calibr testing in Tech Specs 3.2 & 11.1.
EISENHUT, D. G. Division of Licensing. 83/02/23. 5pp. 17429:247. 24X Fiche: 50-070, 83/02/23, 8303040653.

--8303040655 Safety evaluation supporting Amend 11 to License TR-1.
* Office of Nuclear Reactor Regulation, Director. 83/02/23. 2pp. 17429:252. 24X Fiche: 50-070, 83/02/23, 8303040653.

--8303040656 Notice of issuance & availability of Amend 11 to License TR-1.
EISENHUT, D. G. Division of Licensing. 83/02/23. 2pp. 17429:254. 24X Fiche: 50-070, 83/02/23, 8303040653.

Q Inspection reports, IE Bulletins & correspondence

8303150511 Forwards IE Insp Repts 50-070/83-02 & 50-073/83-01 on 830207-10. No noncompliance noted.
BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs. 83/02/23. DARMITZEL, R. W. General Electric Co. 2pp. 17568:234. 24X Fiche: 50-070, 83/02/23, 8303150511.

--8303150533 IE Insp Repts 50-070/83-02 & 50-073/83-01 on 830207-10. No noncompliance noted. Major areas inspected: organization, logs & records, review & audit functions, operator requalification training, facility procedures & LER followup.
STEWART, J. P., ELIN, J. O. Region 5, Office of Director. KIRSCH, D. F. Division of Resident, Reactor Project & Engineering Programs. 83/02/22. 7pp. 17568:236. 24X Fiche: 50-070, 83/02/23, 8303150511.

R Periodic operating reports & related correspondence

8303170457 Forwards "GE Test Reactor Annual Rept 24."
CUNNINGHAM, G. E. General Electric Co. 83/03/08. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17610:341. 24X Fiche: 50-070, 83/03/08, 8303170457.

--8303170465 "GE Test Reactor Annual Rept 24."
TITUS, G. W. General Electric Co. 83/03/08. 7pp. 17610:342. 24X Fiche: 50-070, 83/03/08, 8303170457.

DOCKET 50-72 UNIV. OF UTAH RESEARCH REACTOR

R Periodic operating reports & related correspondence

8303110223 Forwards "Annual Operating Rept 1982 for AGN 201 M Reactor."
JACOBS, J. R. Utah, Univ. of. 83/02/14. SEIDLE, W. C. Region 4, Office of Director. 1p. 17518:350. 24X Fiche: 50-072, 83/02/14, 8303110223.

--8303110229 "Annual Operating Rept 1982 for AGN 201 M Reactor."
* Utah, Univ. of. 82/12/31. 1p. 17518:351. 24X Fiche: 50-072, 83/02/14, 8303110223.

DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

Q Inspection reports, IE Bulletins & correspondence

8303150511 Forwards IE Insp Repts 50-070/83-02 & 50-073/83-01 on 830207-10. No noncompliance noted.
BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs. 83/02/23. DARMITZEL, R. W. General Electric Co. 2pp. 17568:234. 24X Fiche: 50-070, 83/02/23, 8303150511.

--8303150533 IE Insp Repts 50-070/83-02 & 50-073/83-01 on 830207-10. No noncompliance noted. Major areas inspected: organization, logs & records, review & audit functions, operator requalification training, facility procedures & LER followup.
STEWART, J. P., ELIN, J. O. Region 5, Office of Director. KIRSCH, D. F. Division of Resident, Reactor Project & Engineering Programs. 83/02/22. 7pp. 17568:236. 24X Fiche: 50-070, 83/02/23, 8303150511.

DOCKET 50-77 CATHOLIC UNIV. OF AMERICA RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8303290377 Forwards IE Safeguards Insp Rept 50-077/83-01 on 830209. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/15.
WHANG, Y. C. Catholic Univ. 2pp. 17718:092. 24X Fiche: 50-077, 83/03/15, 8303290377.

--8303290381 IE Safeguards Insp Rept 50-077/83-01 on 830209. No noncompliance noted. Major areas inspected: physical protection measures for protecting SNM of low strategic significance.
SMITH, G. C., GODY, A. T. Region 1, Office of Director. 83/03/10.
2pp. 17718:094. 24X Fiche: 50-077, 83/03/15, 8303290377.

Q Inspection reports, IE Bulletins & correspondence

8303290377 Forwards IE Safeguards Insp Rept 50-077/83-01 on 830209. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/15.
WHANG, Y. C. Catholic Univ. 2pp. 17718:092. 24X Fiche: 50-077, 83/03/15, 8303290377.

--8303290381 IE Safeguards Insp Rept 50-077/83-01 on 830209. No noncompliance noted. Major areas inspected: physical protection measures for protecting SNM of low strategic significance.
SMITH, G. C., GODY, A. T. Region 1, Office of Director. 83/03/10.
2pp. 17718:094. 24X Fiche: 50-077, 83/03/15, 8303290377.

DOCKET 50-83 UNIV. OF FLORIDA TRAINING REACTOR

Q Inspection reports, IE Bulletins & correspondence

8303210494 Forwards IE Insp Rept 50-083/83-01 on 830208-11. No noncompliance noted.
VERRELLI, D. M. Division of Project & Resident Programs. 83/02/25.
WETHINGTON, J. A. Florida, Univ. of, Gainesville. 2pp. 17631:235.
24X Fiche: 50-083, 83/02/25, 8303210494.

--8303210501 IE Insp Rept 50-083/83-01 on 830208-11. No noncompliance noted. Major areas inspected: organization, logs & records, requalification training, surveillance, experiments, audit functions, procedures & previous enforcement issues.
HARDIN, A. R. Region 2, Office of Director. BEMIS, P. R. Division of Project & Resident Programs. 83/02/25. 4pp. 17631:237. 24X Fiche: 50-083, 83/02/25, 8303210494.

V. Operator Examinations

8303310238 Forwards operator requalification & recertification program plan for Jul 1983 - June 1985.
VERNETSON, W. G. Florida, Univ. of, Gainesville 83/02/20 WILSON, B
Region 2, Office of Director 1p 17755:345 24X
Fiche: 50-083, 83/02/28, 8303310238.

--8303310242 Univ of FL training reactor operator requalification & recertification program plan, Jul 1983 - June 1985.
* Florida, Univ. of, Gainesville 83/02/28 9pp 17755:346
24X Fiche: 50-083, 83/02/28, 8303310238.

DOCKET 50-87 WESTINGHOUSE CRITICAL EXPERIMENT

F. Security, medical, emergency & fire protection plans

8303140321 Forwards IE Safeguards Insp Rept 50-087/83-01 on 830214-15. No noncompliance noted. Rept withheld (ref 10CFR2.790).
MILLER, J. R. Region 3, Office of Director 83/02/25 SCHOLAND, G. W.
Westinghouse Electric Corp. 2pp 17544:146 24X
Fiche: 50-087, 83/02/25, 8303140321.

8303100278 Forwards IE Safeguards Insp Rept 50-087/83-02 on 830214-15. No noncompliance noted.
MILLER, J. R. Region 3, Office of Director 83/03/04 SCHOLAND, G. W.
Westinghouse Electric Corp. 2pp 17489:350 24X
Fiche: 50-087, 83/03/04, 8303100278.

--8303100283 IE Safeguards Insp Rept 50-087/83-02 on 830214-15. No noncompliance noted. Major areas inspected: site orientation, review of security plan/implementing procedures & security organization. Details withheld (ref 10CFR2.790).
STAPLETON, B. W., CREED, J. R. Region 3, Office of Director
83/03/03 1p 17489:352 24X Fiche: 50-087, 83/03/04, 8303100278.

G. Inspection reports, IE Bulletins & correspondence

8303140321 Forwards IE Safeguards Insp Rept 50-087/83-01 on 830214-15. No noncompliance noted. Rept withheld (ref 10CFR2.790).
MILLER, J. R. Region 3, Office of Director 83/02/25 SCHOLAND, G. W.
Westinghouse Electric Corp. 2pp 17544:146 24X
Fiche: 50-087, 83/02/25, 8303140321.

8303100278 Forwards IE Safeguards Insp Rept 50-087/83-02 on 830214-15. No noncompliance noted.
MILLER, J. R. Region 3, Office of Director 83/03/04 SCHOLAND, G. W.
Westinghouse Electric Corp. 2pp 17489:350 24X
Fiche: 50-087, 83/03/04, 8303100278.

--8303100283 IE Safeguards Insp Rept 50-087/83-02 on 830214-15. No noncompliance noted. Major areas inspected: site orientation, review of security plan/implementing procedures & security organization. Details withheld (ref 10CFR2.790).
STAPLETON, B. W., CREED, J. R. Region 3, Office of Director
83/03/03 1p 17489:352 24X Fiche: 50-087, 83/03/04, 8303100278.

DOCKET 50-111 NORTH CAROLINA STATE UNIV. RESEARCH REACTOR

W. Decommissioning Stage Documents & Correspondence

8303310396 Forwards final survey re radiation & removable contamination of R-3 reactor bay after biological shield demolished. Final survey shows compliance w/criteria established by RW Reid 810304 ltr to JL Thomas. Removable contamination survey encl.
COCKRELL, R. D. North Carolina State Univ. 83/03/29 CRUTCHFIELD, D.
Operating Reactors Branch 5 2pp 17755:056 24X
Fiche: 50-111, 83/03/29, 8303310396.

--8303310400 Forwards final survey of R-3 reactor bay after removing R-3 reactor biological shield. Area above crane track shows no greater deviation of radiological cleanliness than area below crane. No swipes on area above crane necessary.
CROSS, R. D. North Carolina State Univ. 83/03/16 PEERY, W.
Division of Engineering & Radiological Safety Programs 23pp
17755:058 24X Fiche: 50-111, 83/03/29, 8303310396.

DOCKET 50-112 UNIV. OF OKLAHOMA RESEARCH REACTOR

P. Operating license stage documents & correspondence

8303040110 Advises that revised operator requalification program, submitted w/830104 ltr, satisfies requirements of 10CFR55, App A & acceptable.
EISENHUT, D. G. Division of Licensing 83/02/23 TERRELL, C. W.
Oklahoma, Univ. of 1p 17424:342 24X Fiche: 50-112, 83/02/23, 8303040110.

G. Inspection reports, IE Bulletins & correspondence

8303010554 Ack receipt of 821210, 15 & 830214 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-112/82-01.
MADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs 83/02/25 EGLE, D. M. Oklahoma, Univ. of 1p 17337:262
24X Fiche: 50-112, 83/02/25, 8303010554.

--8303010560 Responds to NRC 830118 ltr re violations noted in IE Insp Rept 50-112/82-01. Corrective actions: copies of reactor safety committee (RCS) new charter will be forwarded to Region IV. RCS audit function redefined.
EGLE, D. M. Oklahoma, Univ. of 83/02/14 MADSEN, G. L. Division of
Resident, Reactor Project & Engineering Programs 4pp 17337:263
24X Fiche: 50-112, 83/02/25, 8303010554.

DOCKET 50-124 VIRGINIA POLYTECH INST. TRAINING REACTOR

P. Operating license stage documents & correspondence

8303220167 Forwards remaining Tech Spec changes for amend to License R-62. Actual connection & testing contingent on N-16 calculations & approved test procedures. Table listing summary of specific changes encl.
PARKINSON, T. F. Virginia Polytechnic Institute 83/03/15
THOMAS, C. O. Standardization & Special Projects Branch 2pp
17658:268 24X Fiche: 50-124, 83/03/15, 8303220167.

--8303220175 Confirms that proposal for Tech Spec change has been reviewed & approved by reactor safety committee.
* Virginia Polytechnic Institute 83/03/17 Division of
Licensing 2pp 17658:270 24X Fiche: 50-124, 83/03/15, 8303220167.

--8303220178 Application to amend License R-62 revising Tech Specs re secondary coolant sys to remove existing HX supplied by city water.
HOLIAN, P. D. Virginia Polytechnic Institute 82/11/03
THOMAS, C. O. Standardization & Special Projects Branch 2pp
17658:273 24X Fiche: 50-124, 83/03/15, 8303220167.

--8303220182 Proposed Tech Spec changes re secondary cooling sys.
* Virginia Polytechnic Institute 82/11/03 13pp 17658:275
24X Fiche: 50-124, 83/03/15, 8303220167.

--8303220187 SAR re manual withdrawal of control rod for control rod drop time measurements & analysis for Tech Specs.
* Virginia Polytechnic Institute 83/01/11 7pp 17658:287
24X Fiche: 50-124, 83/03/15, 8303220167.

--8303220189 Proposed Tech Spec changes to License R-62, App A.
* Virginia Polytechnic Institute 83/03/15 15pp 17658:294
24X Fiche: 50-124, 83/03/15, 8303220167.

R. Periodic operating reports & related correspondence

8303020045 Forwards "Annual Rept for VA Polytechnic Inst & State Univ Research Reactor, 1982."
HOLIAN, P. D. Virginia Polytechnic Institute 83/02/22 NRC - No
Detailed Affiliation Given 1p 17352:193 24X
Fiche: 50-124, 83/02/22, 8303020045.

--8303020049 "Annual Rept for VA Polytechnic Inst & State Univ Research Reactor, 1982."
HOLIAN, P. D., SMITHWICK, T. S., PARKINSON, T. F. Virginia Polytechnic Institute 83/02/22 66pp 17352:195 24X Fiche: 50-124, 83/02/22, 8303020045.

DOCKET 50-128 TEXAS A&M UNIV. RESEARCH REACTOR

H. General correspondence

8303140212 Informs that DE Feltz has accepted position of director of Nuclear Science Ctr.
ERDMAN, C. A. Texas A&M Univ., College Station, TX 83/03/08
BERNARD, H. Standardization & Special Projects Branch 1p
17540:078 24X Fiche: 50-059, 83/03/08, 8303140212.

P. Operating license stage documents & correspondence

8303150396 Forwards post-damage test program for FLIP TRIGA core. Program submitted for reactor safety board review on 830128.
ROGERS, D. Texas A&M Univ., College Station, TX 83/01/26
COLLINS, J. T. Region 4, Office of Director 1p 17561:288 24X
Fiche: 50-128, 83/01/26, 8303150396.

# DOCKETED ITEMS

DOCKET 50-131 OMAHA VET. ADMIN. HOSP. RESEARCH REACTOR

P. Operating license stage documents & correspondence

8303090280 Forwards questions developed by LASL while reviewing documentation re application for renewal of TRIGA reactor license.
THOMAS, C. O. Standardization & Special Projects Branch 83/02/28
BLOTCKY, A. J. Vet. Admin. Hosp. Omaha, NE 4pp 17466:334 24X
Fiche: 50-131, 83/02/28, 8303090280

8303240200 Notification of 830411-15 meetings w/Veterans Administration Hosp Research Reactor Group in Omaha, NE to review & evaluate reactor facility in connection w/renewal of OL.
CARTER, R. E. Standardization & Special Projects Branch 83/03/21
THOMAS, C. O. Standardization & Special Projects Branch 2pp
17496:347 24X Fiche: 50-131, 83/03/21, 8303240200

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

Q. Adjudicatory correspondence

8303290023 Forwards Commission 830314 "Policy Statement on Safety Goals for Operation of Nuclear Power Plants," containing preliminary safety goals & numerical design objectives.
YOUNG, M. A. Hearing Branch 4 83/03/25 LAZO, R. M., SCHINK, D. R., LINENBERGER, G. Atomic Safety and Licensing Board Panel 11pp
17723:118 24X Fiche: 50-133, 83/03/25, 8303290023

I. Financial information

8303290345 Forwards Annual Financial Rept 1982.
CRANE, P. A. Pacific Gas & Electric Co. 83/03/25 Office of Nuclear Reactor Regulation, Director 1p 17718:123 24X
Fiche: 50-000, 83/03/25, 8303290345

--8303290349 Annual Financial Rept 1982.
* Pacific Gas & Electric Co. 83/02/16 40pp 17718:124 24X
Fiche: 50-000, 83/03/25, 8303290345

J. Insurance & indemnity information

8303280132 Forwards Endorsement 100 to NELIA Policy NF-113.
CRANE, P. A. Pacific Gas & Electric Co. 83/03/24 SALTZMAN, J. D. D. Assistant Director for State & Licensee Relations 2pp 17706:343
24X Fiche: 50-133, 83/03/24, 8303280132

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X
Fiche: 50-000, 83/02/16, 8302170082

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc 5pp 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005

8303280027 Responds to Generic Ltr 83-02 Facility in cold shutdown. License amend will be submitted to revise Tech Specs should operation be resumed.
CRANE, P. A. Pacific Gas & Electric Co. 83/03/22 EISENHUT, D. G. Division of Licensing 1p 17707:190 24X Fiche: 50-133, 83/03/22, 8303280027

8303300121 Responds to Generic Ltr 82-33 requesting schedule for completing requirements for identified items. Facility in cold shutdown. Schedule for return to power operation not established.
CRANE, P. A. Pacific Gas & Electric Co. 83/03/25 EISENHUT, D. G. Division of Licensing 1p 17735:306 24X Fiche: 50-133, 83/03/25, 8303300121

Q. Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 111pp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367

8303090226 Advises that no Bunker Ramo hard epoxy electrical penetration assemblies installed or planned to be installed at facility, in response to IE Bulletin 82-04, "Deficiencies in Containment Electrical Penetrations."
BRAND, D. A., CRANE, P. A. Pacific Gas & Electric Co. 83/03/03
KNIGHTON, G. W. Licensing Branch 3 2pp 17492:109 24X
Fiche: 50-133, 83/03/03, 8303090226

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 11?pp 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 11?pp 24X Fiche: 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12?pp 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387

R. Periodic operating reports & related correspondence

8303080175 Forwards monthly operating for Dec 1982.
WEEKS, E. D. Pacific Gas & Electric Co. 83/01/05 Division of Data Automation & Management Information 1p 17457:332 24X
Fiche: 50-133, 83/01/05, 8303080175

--8303080181 Monthly operating rept for Dec 1982.
DERKS, P. S. Pacific Gas & Electric Co. 83/01/04 4pp 17457:333
24X Fiche: 50-133, 83/01/05, 8303080175

8303150552 Forwards monthly operating rept for Jan 1983.
WEEKS, E. D. Pacific Gas & Electric Co. 83/02/03 Division of Data Automation & Management Information 1p 17568:111 24X
Fiche: 50-133, 83/02/03, 8303150552

--8303150561 Monthly operating rept for Jan 1983.
DERKS, P. S. Pacific Gas & Electric Co. 83/02/03 4pp 17568:112
24X Fiche: 50-133, 83/02/03, 8303150552

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp 24X Fiche: 50-000, 83/02/24, 8302250505

8303080440 Submits schedule of anticipated requests for site visits to conduct operator licensing & instructor verification exams through 85123) per Generic Ltr 83-01.
CRANE, P. A. Pacific Gas & Electric Co. 83/02/28 EISENHUT, D. G. Division of Licensing 2pp 17454:241 24X Fiche: 50-133, 83/02/28, 8303080440

DOCKET 50-141 STANFORD UNIV. RESEARCH REACTOR

G. Inspection reports, IE Bulletins & correspondence

8303290474 Forwards IE Insp Rept 50-141/82-02 on 820916-1105. No noncompliance noted.
BOOK, H. E. Region 5, Office of Director 83/03/11 FINSTON, R. A. Stanford Univ. 2pp 17724:310 24X Fiche: 50-141, 83/03/11, 8303290474

--8303290480 IE Insp Rept 50-141/82-02 on 820916-1105. No noncompliance noted. Major areas inspected: review of records, interviews w/personnel & independent radiation & contamination measurements.
GARCIA, E. M., TEMPLE, G. M., WENSLAWSKI, F. Region 5, Office of Director 83/03/10 12pp 17724:312 24X Fiche: 50-141, 83/03/11, 8303290474

DOCKET 50-142 UCLA TRAINING REACTOR

Q. Adjudicatory correspondence

8303140267 Notice of appearance in proceeding.
BAY, J. H. Committee to Bridge the Gap. BAY, J. H. Nuclear Law Center. 82/06/29. 1p. 17535:030. 24X Fiche: 50-142, 82/06/29, 8303140267.

8303140273 Notice of appearance in proceeding.
THOMPSON, D. Committee to Bridge the Gap. THOMPSON, D. Nuclear Law Center. 82/06/29. 1p. 17535:115. 24X Fiche: 50-142, 82/06/29, 8303140273.

8303080044 Requests refund of copying charges for discovery documents since correct charges should be four cents instead of twenty cents per page.
HIRSCH, D. Committee to Bridge the Gap. 83/03/01. CORMIER, W. California, Univ. of, Los Angeles. 2pp. 17454:351. 24X Fiche: 50-142, 83/03/01, 8303080044.

8303070106 Memorandum & order stating ASLB intent to rule on motions for summary disposition of Contentions XVIII & XX. Committee to Bridge the Gap response re Contention XVIII due 830316. NRC & UCLA responses re Contention XX due by 830316 & 23.
FRYE, J. H. Atomic Safety and Licensing Board Panel. 83/03/04. California, Univ. of, Los Angeles. 2pp. 17430:346. 24X Fiche: 50-142, 83/03/04, 8303070106.

8303100151 Forwards BNWL & BNL studies re Argonaut-UTRs w/o encl.
WOODHEAD, C. P. Hearing Branch 1. 83/03/08. CORT, G. E. Los Alamos Scientific Laboratory. 1p. 17485:242. 24X Fiche: 50-142, 83/03/08, 8303100151.

8303180413 Expresses concern about being left out of 830309 conference call & about inadequate notice of 830311 conference call. Views on topics discussed during calls explained. Related correspondence.
NALIBOFF, L. G. Santa Monica, CA. 83/03/13. FRYE, J. H., LUEBKE, E. A., PARIS, O. H. Atomic Safety and Licensing Board Panel. 7pp. 17622:029. 24X Fiche: 50-142, 83/03/13, 8303180413.

8303220203 Requests ASLB ruling on Committee to Bridge the Gap motion for partial summary disposition of Contention XVII. No matl facts are in dispute. Related correspondence.
HIRSCH, D. Committee to Bridge the Gap. 83/03/15. FRYE, J. H., PARIS, O. H., LUEBKE, E. A. Atomic Safety and Licensing Board Panel. 4pp. 17656:157. 24X Fiche: 50-142, 83/03/15, 8303220203.

--8303220208 Memorandum & motion re hearing scheduling matters. Preserves Committee to Bridge the Gap objections to matters which substantially & adversely affect Gap ability to represent interests.
HIRSCH, D. Committee to Bridge the Gap. 83/03/15. Atomic Safety and Licensing Board Panel. 9pp. 17656:161. 24X Fiche: 50-142, 83/03/15, 8303220203.

--8303220325 Motion for expedited ruling on Committee to Bridge the Gap 820907 motion for partial summary disposition of Contention XIII & for setting May 1983 hearing date for remaining portions of Contention XIII. Declaration of Svc encl.
HIRSCH, D. Committee to Bridge the Gap. 83/03/15. Atomic Safety and Licensing Board Panel. 10pp. 17656:170. 24X Fiche: 50-142, 83/03/15, 8303220203.

8303220220 Reply opposing Committee to Bridge the Gap response to NRC 820421 motion for summary disposition of Contention XX. Gap misread univ inventory records & misinterpreted other fuel quantity info. Certificate of Svc encl.
CORMIER, W. H. California, Univ. of, Los Angeles. 83/03/16. Atomic Safety and Licensing Board Panel. 14pp. 17657:027. 24X Fiche: 50-142, 83/03/16, 8303220220.

8303240245 Response to ASLB 830304 order requesting response re Contention XX on possession of SNM. Util possesses less than formula quantity of 5,000 g. Committee to Bridge the Gap overestimated quantity of SNM. Certificate of Svc encl.
WOODHEAD, C. P. Hearing Branch 1. 83/03/23. Atomic Safety and Licensing Board Panel. 5pp. 17680:031. 24X Fiche: 50-142, 83/03/23, 8303240245.

8303290510 Prehearing conference memorandum & order memorializing 830223 conference in Los Angeles, CA & 830309 & 11 telcons re inherent safety issue & contentions.
LUEBKE, E. A., FRYE, J. H. Atomic Safety and Licensing Board Panel. 83/03/23. 25pp. 17723:017. 24X Fiche: 50-142, 83/03/23, 8303290510.

8303310357 Forwards seven SNM accounting records & four nuclear matl transaction journals, per 830323 commitment.
WOODHEAD, C. P. Hearing Branch 4. 83/03/29. FRYE, J. H., LUEBKE, E. A., PARIS, O. H. Atomic Safety and Licensing Board Panel. 10pp. 17755:002. 24X Fiche: 50-142, 83/03/29, 8303310357.

P. Operating license stage documents & correspondence

8303150128 Forwards Amend 11 to License R-71 & safety evaluation. Amend decreases U-235 inventory to 5,000 g (enriched to 93%).
EISENHUT, D. G. Division of Licensing. 83/03/02. WEGST, W. F. California, Univ. of, Los Angeles. 3pp. 17600:165. 24X Fiche: 50-142, 83/03/02, 8303150128.

--8303150135 Amend 11 to License R-71, decreasing U-235 inventory to 5,000 g (enriched to 93%).
EISENHUT, D. G. Division of Licensing. 83/03/02. 2pp. 17600:168. 24X Fiche: 50-142, 83/03/02, 8303150128.

--8303150140 Safety evaluation supporting Amend 11 to License R-71.
* NRC - No Detailed Affiliation Given. 83/03/02. 2pp. 17600:170. 24X Fiche: 50-142, 83/03/02, 8303150128.

T. Hearing transcripts on non-antitrust matters

8303010240 Transcript of 830223 prehearing conference in Los Angeles, CA. Pp. 794-990.
* Atomic Safety and Licensing Board Panel. 83/02/23. 197pp. 17334:198. 24X Fiche: 50-142, 83/02/23, 8303010240.

DOCKET 50-146 SAXTON NUCLEAR EXPERIMENTAL FACILITY

H. General correspondence

8303020073 Requests copy of proposed issuance of order authorizing dismantling of facility & Reg Guide 1.86.
BAUGHMAN, J. D. Broad Top Bulletin. Saxton, PA. 82/09/27.
ERIKSEN, P. B. NRC - No Detailed Affiliation Given. 1p. 17352:084. 24X Fiche: 50-146, 82/09/27, 8303020073.

8303160012 Forwards Reg Guide 1.86, "Termination of OLs for Nuclear Reactors," re dismantling & decommissioning of reactor at Elk River, in response to 830217 request. W/o encl.
CARTER, R. E. Standardization & Special Projects Branch. 83/03/04.
ELDER, J. H. The Coalition - Concerned Citizens Coalition of Solano County. 1p. 17615:070. 24X Fiche: 50-146, 83/03/04, 8303160012.

I. Financial information

8303030110 Forwards financial statement for CY82.
MONTGOMERY, C. R. Saxton Nuclear Experimental Corp. 83/02/23.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 17412:358. 24X Fiche: 50-146, 83/02/23, 8303030110.

J. Insurance & indemnity information

8303010286 Forwards Endorsement 79 to NELIA Policy NF-107.
MONTGOMERY, C. R. Saxton Nuclear Experimental Corp. 83/02/23.
Antitrust & Economic analysis Branch (Utility Finance). 2pp. 17341:061. 24X Fiche: 50-146, 83/02/23, 8303010286.

S. Reportable occurrences, LERs & related correspondence

8303090276 RO on 830118: 4.5 cm water found in containment vessel sump, below elevation 765 ft. 8 inches concentrations of Cs-134, Cs-137 & Sr-90 confirmed. Pressure of water caused by condensation on inside water. No release to environ.
MONTGOMERY, C. R. Saxton Nuclear Experimental Corp. 83/02/10.
Region 1, Office of Director. 2pp. 17492:156. 24X Fiche: 50-146, 83/02/10, 8303090276.

DOCKET 50-151 UNIV. OF ILLINOIS RESEARCH REACTOR

R. Periodic operating reports & related correspondence

8303030212 Forwards "Annual Rept IL Advanced TRIGA, 1982."
BECK, G. P., WEHRING, B. W., MILEY, G. H. Illinois, Univ. of, Urbana-Champaign. 83/02/24. Division of Licensing. 1p. 17411:276. 24X Fiche: 50-151, 83/02/24, 8303030212.

--8303030214 "Annual Rept IL Advanced TRIGA, 1982."
* Illinois, Univ. of, Urbana-Champaign. 83/02/24. 6pp. 17411:277. 24X Fiche: 50-151, 83/02/24, 8303030212.

# DOCKETED ITEMS

DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

8303090281 Summary of 830202-03 meeting w/util in Charlevoix, MI re intrusion detection sys at util Safeguards details withheld (ref 10CFR73.21).
* NRC - No Detailed Affiliation Given. 83/02/03. NRC - No Detailed Affiliation Given. 1p. 17466:333. 24X Fiche: 50-155, 83/02/03, 8303090281.

8303030190 Forwards Amend 58 to License DPR-6, safety evaluation & notice of issuance & availability Amend revises frequency of audits of emergency preparedness & security plans by Safety & Audit Review Board.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/02/28.
VANDEWALLE, D. J. Consumers Power Co. 3pp. 17410:314. 24X Fiche: 50-155, 83/02/28, 8303030190.

--8303030197 Amend 58 to License DPR-6, revising frequency of audits of emergency preparedness & security plans by Safety & Audit Board.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/02/28. 4pp. 17410:317. 24X Fiche: 50-155, 83/02/28, 8303030190.

--8303030203 Safety evaluation supporting Amend 58 to License DPR-6.
* Office of Nuclear Reactor Regulation, Director. 83/02/28. 2pp. 17410:321. 24X Fiche: 50-155, 83/02/28, 8303030190.

--8303030207 Notice of issuance & availability of Amend 58 to License DPR-6.
WAMBACH, T. V. Operating Reactors Branch 5. 83/02/28. 2pp. 17410:323. 24X Fiche: 50-155, 83/02/28, 8303030190.

8303210150 Forwards Rev 7 to security plan & justification. Rev & justification withheld (ref 10CFR73.21(c)).
VANDEWALLE, D. J. Consumers Power Co. 83/03/04. CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 17630:259. 24X Fiche: 50-155, 83/03/04, 8303210150.

8303140471 Forwards exemption from certain requirements of App R to 10CFR50 per 820928 request Exemption forwarded to OFC of FR for publication Safety evaluations providing basis for action on exemption requests also forwarded.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/03/08.
VANDEWALLE, D. J. Consumers Power Co. 3pp. 17540:274. 24X Fiche: 50-155, 83/03/08, 8303140471.

--8303140481 Exemption from requirements of App R to 10CFR50 for six items listed.
EISENHUT, D. G. Division of Licensing. 83/03/08. Consumers Power Co. 9pp. 17540:277. 24X Fiche: 50-155, 83/03/08, 8303140471.

--8303140487 Safety evaluation supporting licensee request for exemption from Section III G.1 of App R re repair of control rod drive pump & booster pump.
* Office of Nuclear Reactor Regulation, Director. 83/03/08. 12pp. 17540:286. 24X Fiche: 50-155, 83/03/08, 8303140471.

--8303140498 Safety evaluation supporting licensee exemption requests re emergency condenser inlet valves in control room & containment per App R to 10CFR50.
* Office of Nuclear Reactor Regulation, Director. 83/03/08. 7pp. 17540:298. 24X Fiche: 50-155, 83/03/08, 8303140471.

8303240379 Releases public version of replacement coversheet to Vol 9A of site emergency plan implemenmting procedures.
FELTON, J. M. Division of Rules and Records. 83/03/16. Document Management Branch. 1p. 17693:278. 24X Fiche: 50-155, 83/03/16, 8303240379.

--8303240384 Forwards public version of replacement coversheet to Vol 9A of site emergency plan implementing procedures.
* Consumers Power Co. 83/03/04. Office of Nuclear Reactor Regulation, Director. 2pp. 17693:290. 24X Fiche: 50-155, 83/03/16, 8303240379.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director. 83/03/22. Commonwealth Edison Co. 2pp. 17690:316. 24X Fiche: 50-000, 83/03/22, 8303240440.

G. Adjudicatory correspondence

8303010073 Protests licensee distribution of matl not in record & matl not yet complete. Presentation of W Brooks & D Fieno 830218 deposition prejudiced appeal. Certificate of Svc encl.
SEMMEL, H. Antioch School of Law, Washington, DC. SEMMEL, H. Christa-Maria. 83/02/24. MOORE, T. S., BUCK, J. H., KOHL, C. N. Atomic Safety and Licensing Appeal Panel. 7pp. 17335:077. 24X Fiche: 50-155, 83/02/24, 8303010073.

8303020041 Reply to NRC 830214 motion for extension of time to answer util 830121 final response to ASLB 820914 partial initial decision. Agrees to extension even though need for extension not stated in filing.
GALLO, J. Consumers Power Co. GALLO, J. Isham, Lincoln & Beale. 83/02/25. BLOCH, P. B., PARRIS, O. H., SHON, F. J. Atomic Safety and Licensing Board Panel. 2pp. 17352:185. 24X Fiche: 50-155, 83/02/25, 8303020041.

8303040445 Informs that J Gallo will represent util at 830324 oral argument.
GALLO, J. Isham, Lincoln & Beale. GALLO, J. Consumers Power Co. 83/03/01. MOORE, T. S., BUCK, J. H., KOHL, C. N. Atomic Safety and Licensing Board Panel. 1p. 17367:201. 24X Fiche: 50-155, 83/03/01, 8303040445.

8303080121 Advises that intervenors Christa-Maria, JA Bier & J Mills do not intend to waive right to file reply on emergency planning issues by 830312. Ltr constitutes motion for extension of time to file if separate motion required.
WIKTOR, D. L. Antioch School of Law, Washington, DC. 83/03/03. BLOCH, P. B., SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel. 2pp. 17458:246. 24X Fiche: 50-155, 83/03/03, 8303080121.

8303140362 Supports provisional motion made by D Wikter for Christa-Maria, J Bier & J Mills re emergency planning issues.
O'NEILL, J. O'Neill, J. 83/03/09. BLOCH, P. B., PARIS, O. H., SHON, F. J. Atomic Safety and Licensing Board Panel. 1p. 17543:308. 24X Fiche: 50-155, 83/03/09, 8303140362.

8303140444 Responds to licensee 830218 ltr transmitting 821229 deposition of WL Brooks & 830110 deposition of DB Fieno & to intervenor 830224 opposition to deposition distribution. Depositions cannot be considered substantively in appeal.
BACHMANN, R. G. Hearing Branch 1. 83/03/10. MOORE, T. S., BUCK, J. H., KOHL, C. N. Atomic Safety and Licensing Appeal Panel. 2pp. 17542:186. 24X Fiche: 50-155, 83/03/10, 8303140444.

8303140514 Advises that RG Bachmann will present argument re spent fuel pool mod at 830324 oral argument. Counsel for licensee should be granted 30 minutes for argument, per 830301 request to ASLAB.
BACHMANN, R. G. Hearing Branch 1. 83/03/11. SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 1p. 17540:342. 24X Fiche: 50-155, 83/03/11, 8303140514.

8303170509 Reply opposing Christa-Maria 830224 ltr complaining of util filing depositions. Subj matter of depositions pertinent to matter on appeal of O'Neill Contention II E-3. Assertion of bias unsubstantiated. Certificate of Svc encl.
GALLO, J. Consumers Power Co. GALLO, J. Isham, Lincoln & Beale. 83/03/11. 6pp. 17610:200. 24X Fiche: 50-155, 83/03/11, 8303170509.

8303220290 Reply to licensee response to ASLB 820914 order. Response inadequate in areas of evacuation of educational & day care type facilities, training, hosp evacuation & evacuation of persons w/o vehicles. Certificate of Svc encl.
WIKTOR, D., SEMMEL, H. Christa-Maria. SEMMEL, H. Antioch School of Law, Washington, DC. 83/03/14. 10pp. 17656:131. 24X Fiche: 50-155, 83/03/14, 8303220290.

8303230246 Forwards util & MHB Technical Assoc ltrs re remote makeup line that should have been attached to 830131 appeal brief. H Semmel motion to prevent depositions re criticality from being entered into record supported.
O'NEILL, J. O'Neill, J. 83/03/17. MOORE, T. S., BUCK, J. H., KOHL, C. N. Atomic Safety and Licensing Appeal Panel. 1p. 17662:029. 24X Fiche: 50-155, 83/03/17, 8303230246.

--8303230250 Attachments to 830131 appeal brief re remote makeup line inadvertently omitted.
O'NEILL, J. O'Neill, J. 83/03/17. Atomic Safety and Licensing Appeal Panel. 4pp. 17662:030. 24X Fiche: 50-155, 83/03/17, 8303230246.

8303230215 Forwards J O'Neill 830314 remarks on evacuation plans for distribution to ASLB & interested parties. Document filed on time. Delay due to attempt to reproduce illegible telecopy.
GODDARD, R. J. Hearing Branch 3. 83/03/22. BLOCH, P. B., PARIS, O. H., SHON, F. J. Atomic Safety and Licensing Board Panel. 2pp. 17665:121. 24X Fiche: 50-155, 83/03/22, 8303230215.

--8303230217 Comments on proposed evacuation plans.Hosp & poor people w/o transportation should be considered.
O'NEILL, J. O'Neill, J. 83/03/14 Atomic Safety and Licensing Board Panel 2pp 17665:123 24X Fiche:50-155,83/03/22, 8303230215.

8303290530 Forwards corrected P.I to util 830321 motion for leave to respond to intervenor reply.
COPELAND,V.G. Isham, Lincoln & Beale COPELAND,V.G. Consumers Power Co. 83/03/22 BLOCH,P., PARRIS,O.H., SHON,F.J. Atomic Safety and Licensing Board Panel 1p 17724:354 24X
Fiche:50-155,83/03/22,8303290530.

--8303290533 Corrected P.I to util 830321 motion for leave to respond to intervenor 830317 reply to licensee response to ASLB 820914 order.
* Consumers Power Co. 83/03/22 Atomic Safety and Licensing Board Panel 1p 17724:355 24X Fiche:50-155,83/03/22, 8303290530.

8303240554 Order denying intervenor motion to remand case to ASLB.Util 830201 ltr w/depositions does not seek to reopen record & does not purport to be new evidence.Documents are not part of record.
SHOEMAKER,C.J. Atomic Safety and Licensing Appeal Panel 83/03/23
CHRISTA-MARIA Christa-Maria O'NEIL,J. O'Neill, J. 3pp
17682:218 24X Fiche:50-155,83/03/23,8303240554.

I. Financial information

8303210279 Forwards Annual Financial Rept 1982.
PERRY,P.A. Consumers Power Co. 83/03/15 GIAMBUSSO,A. Division of Licensing 1p 17632:003 24X Fiche:50-000,83/03/15,8303210279.

--8303210286 Annual Financial Rept 1982.
SELBY,J.P., FALAHEE,J.B. Consumers Power Co. 83/02/04 29pp
17632:004 24X Fiche:50-000,83/03/15,8303210279.

J. Insurance & indemnity information

8303220306 Forwards Endorsement 95 to NELIA Policy NF-117.
FROUNFELKER,R. Consumers Power Co. 83/03/18 SALTZMAN,J. Antitrust & Economic analysis Branch (Utility Finance) 2pp
17656:108 24X Fiche:50-155,83/03/18,8303220306.

P Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982.Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal.Svc list encl.
EISENHUT,D.G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X
Fiche:50-000,83/02/16,8302170082.

8303010575 Forwards Amend 57 to License DPR-6,safety evaluation & notice of issuance & availability.Amend approves deletion of Tech Spec provisions requiring certain area radiation monitors.
CRUTCHFIELD,D. Operating Reactors Branch 5 83/02/18
VANDEWALLE,D. Consumers Power Co. 3pp 17336:067 24X
Fiche:50-155,83/02/18,8303010575.

--8303010603 Amend 57 to License DPR-6,approving deletion of Tech Spec provisions requiring certain area radiation monitors.
CRUTCHFIELD,D. Operating Reactors Branch 5 83/02/18 7pp
17336:070 24X Fiche:50-155,83/02/18,8303010575.

--8303010609 Safety evaluation supporting Amend 57 to License DPR-6.
* Office of Nuclear Reactor Regulation, Director 83/02/18 2pp
17336:077 24X Fiche:50-155,83/02/18,8303010575.

--8303010613 Notice of issuance & availability of Amend 57 to License DPR-6.
CRUTCHFIELD,D. Operating Reactors Branch 5 83/02/18 2pp
17336:079 24X Fiche:50-155,83/02/18,8303010575.

8303030190 Forwards Amend 58 to License DPR-6,safety evaluation & notice of issuance & availability.Amend revises frequency of audits of emergency preparedness & security plans by Safety & Audit Review Board.
CRUTCHFIELD,D. Operating Reactors Branch 5 83/02/28
VANDEWALLE,D.J. Consumers Power Co. 3pp 17410:314 24X
Fiche:50-155,83/02/28,8303030190.

--8303030197 Amend 58 to License DPR-6,revising frequency of audits of emergency preparedness & security plans by Safety & Audit Board.
CRUTCHFIELD,D. Operating Reactors Branch 5 83/02/28 4pp
17410:317 24X Fiche:50-155,83/02/28,8303030190.

--8303030203 Safety evaluation supporting Amend 58 to License DPR-6.
* Office of Nuclear Reactor Regulation, Director 83/02/28 2pp
17410:321 24X Fiche:50-155,83/02/28,8303030190.

--8303030207 Notice of issuance & availability of Amend 58 to License DPR-6.
WAMBACH,T.V. Operating Reactors Branch 5 83/02/28 2pp
17410:323 24X Fiche:50-155,83/02/28,8303030190.

8303040339 Responds to NRC 830127 ltr requesting util position re SEP topics differing from current licensing criteria.Util opines that NRC conclusions on differences between criteria & present plant designs adequate.
TONER,K.A. Consumers Power Co. 83/02/28 CRUTCHFIELD,D. Operating Reactors Branch 5 16pp 17422:005 24X Fiche:50-155,83/02/28, 8303040339.

8303040423 Forwards revised final SER re SEP Topic III-10.A, "Thermal Overload Protection for Motors of Motor Operated Valves." Plant equivalent to current licensing criteria.
CRUTCHFIELD,D. Operating Reactors Branch 5 83/02/28
VANDEWALLE,D.J. Carolina Power & Light Co. 5pp 17374:292 24X
Fiche:50-155,83/02/28,8303040423.

8303070057 Forwards addl info to substantiate radiation environ for equipment qualification.Total integrated dose over 30 days 7.78E+05.Integrated dose presented in "Environ Qualification of Safety-Related Electrical Equipment," acceptable.
JOHNSON,B.D. Consumers Power Co. 83/03/01 CRUTCHFIELD,D. Operating Reactors Branch 5 4pp 17435:003 24X
Fiche:50-155,83/03/01,8303070057.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys.Svc list encl.
EISENHUT,D.G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X
Fiche:50-000,83/03/02,8303020321.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/ electronic networking sys.
KEPPLER,J.G. Region 3, Office of Director 83/03/03
Commonwealth Edison Co. 2pp 17492:014 24X Fiche:50-000,83/03/03, 8303100364.

8303090123 Concludes that study & sys mods requested in NUREG-0737, TMI Action Item II.K.3.16, "Challenges & Failures of Relief Valves," not applicable.Overpressure protection provided by emergency condenser & spring loaded safety valves.
CRUTCHFIELD,D. Operating Reactors Branch 5 83/03/04
VANDEWALLE,D.J. Consumers Power Co. 3pp 17470:297 24X
Fiche:50-155,83/03/04,8303090123.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT,D.G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp 17660:176 24X
Fiche:50-000,83/03/07,8303040005.

8303170098 Forwards legible pages of static-o-ring pressure switch test results,clarifying B01031 submittal re environ qualification of safety-related equipment.
BORDINE,T.C. Consumers Power Co. 83/03/10 CRUTCHFIELD,D. Operating Reactors Branch 5 5pp 17607:123 24X
Fiche:50-155,83/03/10,8303170098.

8303180352 Forwards response to SEP Topic VIII-3.B re station battery charger transfer & equalizing charge.Rev changes procedures controlling charger transfer such that info on condition of battery connections can be observed & recorded.
TONER,K.A. Consumers Power Co. 83/03/10 CRUTCHFIELD,D. Operating Reactors Branch 5 7pp 17620:123 24X Fiche:50-155,83/03/10, 8303180352.

8303170096 Forwards response to 820902 final SER for SEP Topic VII-1.A, "Isolation of Reactor Protection Sys From Nonsafety Sys, Including Qualification of Isolation Devices." Response jus' fies licensee position re sys motor generator sets.
TONER,K.A. Consumers Power Co. 83/03/11 CRUTCHFIELD,D. Operating Reactors Branch 5 39pp 17609:105 24X Fiche:50-155,83/03/11, 8303170096.

8303180514 Summary of 830225 meeting w/util in Bethesda,MD re expansion of SEP integrated assessment.
EMCH,R. Operating Reactors Branch 5 83/03/11 Operating Reactors Branch 5 4pp 17621:332 24X Fiche:50-155,83/03/11, 8303180514.

# DOCKETED ITEMS

8303220363 Forwards order confirming util commitments to implement post-TMI related issues contained in NUREG-0737 & in responses to Generic Ltrs 82-05 & 82-10.
CRUTCHFIELD, D. Operating Reactors Branch 5 83/03/14
VANDENBALLE, D. J. Consumers Power Co 4pp 17648.342 24X
Fiche 50-155.83/03/14.8303220363

--8303220376 Order confirming util commitment to implement post-TMI related issues contained in NUREG-0737 & in responses to Generic Ltrs 82-05 & 82-10.
EISENHUT, D. G. Division of Licensing 83/03/14 Consumers Power Co 9pp 17648.346 24X Fiche 50-155.83/03/14.8303220363

8303210157 Discusses position that adoption of GE STS unwarranted per NRC 820915 final SER for SEP Topic XV-18, "Radiological Consequences of Main Steam Line Failure Outside Containment."
VANDENBALLE, D. J. Consumers Power Co 83/03/15 CRUTCHFIELD, D.
Operating Reactors Branch 5 3pp 17630.251 24X
Fiche 50-155.83/03/15.8303210157

8303280029 Submits proposal for comprehensive integrated assessment of open issues re environ equipment qualification & Generic Ltr 82-33.
VANDENBALLE, D. J. Consumers Power Co 83/03/18 CRUTCHFIELD, D.
Operating Reactors Branch 5 3pp 17707.191 24X
Fiche 50-155.83/03/18.8303280029

## 9. Inspection reports. IE Bulletins & correspondence

8303210269 Confirms scheduled 821028 meeting in Glen Ellyn, IL to discuss SALP.
SPESSARD, R. L. Division of Project & Resident Programs 82/09/23
DEWITT, R. B. Consumers Power Co 1p 17634.353 24X
Fiche 50-000.82/09/23.8303210269

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11pp 17521.001 24X Fiche 50-000.83/02/25.8212060367

8303030460 Clarifies NRC position re procedures for admitting NRC personnel to facility. Site orientation re issuance of badges, escort duties & emergency evacuation for personnel listed in Encls 1 & 2 requested.
KEPPLER, J. G. Region 3, Office of Director 83/02/28 DEWITT, R. B.
Consumers Power Co 6pp 17409.264 24X Fiche 50-155.83/02/28.
8303030460

8303040427 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetrations." No Bunker-Ramo electrical penetrations in use at facilities.
JOHNSON, B. D. Consumers Power Co 83/02/28 CRUTCHFIELD, D.
Operating Reactors Branch 5 2pp 17371.180 24X
Fiche 50-000.83/02/28.8303040427

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 11pp 17611.070 24X Fiche 50-000.83/03/11.8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 11pp 24X Fiche 50-000.83/03/18.8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12lpp 17774.352 24X Fiche 50-000.83/03/21.8212060387

## R. Periodic operating reports & related correspondence

8303280161 Forwards "Radioactive Effluent Release, Jan-June 1982."
BORDINE, T. C. Consumers Power Co. 82/08/30 KEPPLER, J. G. Region 3, Office of Director 1p 17709.254 24X Fiche 50-155.82/08/30.
8303280161

--8303280166 "Radioactive Effluent Release, Jan-June 1982."
Consumers Power Co 82/08/30 10pp 17709.255 24X
Fiche 50-155.82/08/30.8303280161

8303080028 Forwards monthly operating rept for Dec 1982.
HOFFMAN, D. P. Consumers Power Co 83/01/05 Director's Office, Office of Inspection and Enforcement 1p 17458.195 24X
Fiche 50-155.83/01/05.8303080028

--8303080033 Monthly operating rept for Dec 1982.
AMSTUTZ, S. Consumers Power Co 83/01/05 4pp 17458.196 24X
Fiche 50-155.83/01/05.8303080028

8303150514 Forwards monthly operating rept for Jan 1983.
HOFFMAN, D. P. Consumers Power Co 83/02/04 Director's Office, Office of Inspection and Enforcement 1p 17568.170 24X
Fiche 50-155.83/02/04.8303150514

--8303150529 Monthly operating rept for Jan 1983.
AMSTUTZ, S. Consumers Power Co 83/02/01 6pp 17568.171 24X
Fiche 50-155.83/02/04.8303150514

## T. Hearing transcripts on non-antitrust matters

8303280220 Transcript of 830324 oral argument in Bethesda, MD re spent fuel pool mod. Pp 1-83.
* Atomic Safety and Licensing Appeal Panel 83/03/24 85pp
17708.047 24X Fiche 50-155.83/03/24.8303280220

## V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NRR vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp 24X Fiche 50-000.83/02/24.
8302250505

8303040512 Submits proposed dates between 830111 & 831231 for operator licensing instructor certification exams which would require NRC site visit, in response to 830111 Generic Ltr 83-01.
JOHNSON, B. D. Consumers Power Co 83/02/28 EISENHUT, D. G. Division of Licensing 1p 17373.275 24X Fiche 50-000.83/02/28.8303040512

## DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

## F. Security, medical, emergency & fire protection plans

8303180046 Comments on 820910 changes to physical security plan. Changes acceptable.
THOMAS, C. O. Standardization & Special Projects Branch 83/03/14
ADCOCK, B. National Naval Medical Center, Bethesda, MD 1p
17625.260 24X Fiche 50-170.83/03/14.8303180046

8303300383 Forwards IE Safeguards Insp Rept 50-170/83-01 on 830210. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs 83/03/17
ADCOCK, B. R. Armed Forces Radiobiological Research Institute 2pp
17731.004 24X Fiche 50-170.83/03/17.8303300383

--8303300392 IE Safeguards Insp Rept 50-170/83-01 on 830210. No noncompliance noted. Major areas inspected: physical protection measures for protecting SNM of low strategic significance.
SMITH, G. C.; GODY, A. T. Region 1, Office of Director 83/03/16
2pp 17731.006 24X Fiche 50-170.83/03/17.8303300383

## 9. Adjudicatory correspondence

8303010163 Motion for summary disposition of Contentions 1, 2 & 4 - 10. No genuine issue of matl fact exists. Schedule for disposition of Contention 3 should be established. Affidavits & Certificate of Svc encl. Related correspondence.
RICKARD, D. C. Defense, Dept of, Defense Nuclear Agency 83/02/25
Atomic Safety and Licensing Board Panel 145pp 17333.001 24X
Fiche 50-170.83/02/25.8303010163

## P. Operating license stage documents & correspondence

8303250129 Informs of upcoming planned actions. Major renovation of mechanical & electrical sys & replacement of cooling tower among activities planned for FY84-85.
ADCOCK, B. R. Defense, Dept of, Defense Nuclear Agency 83/03/24
Standardization & Special Projects Branch 2pp 17692.098 24X
Fiche 50-170.83/03/24.8303250129

## 9. Inspection reports. IE Bulletins & correspondence

8303300383 Forwards IE Safeguards Insp Rept 50-170/83-01 on 830210. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs 83/03/17
ADCOCK, B. R. Armed Forces Radiobiological Research Institute 2pp
17731.004 24X Fiche 50-170.83/03/17.8303300383

--8303300392 IE Safeguards Insp Rept 50-170/83-01 on 830210 No noncompliance noted Major areas inspected physical protection measures for protecting SNM of low strategic significance
SMITH, G C , GODY, A T Region 1, Office of Director 83/03/16
2pp 17731 006 24X Fiche 50-170, 83/03/17, 8303300383

U Congressional/Executive Correspondence

8303040142 Ack receipt of 830119 ltr re OL renewal Discussions w/Citizens for Nuclear Reactor Safety continuing
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/02/28 MORELLA, C A Maryland, State of 5pp 17425 039 24X Fiche 50-170, 83/02/28, 8303040142

--8303040147 Encourages continued discussions w/Citizens for Nuclear Reactor Safety re OL renewal
MORELLA, C A Maryland, State of 83/01/19 Commissioners
2pp 17425 043 24X Fiche 50-170, 83/02/28, 8303040142

DOCKET 50-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT 1

I Financial information

8303170159 Forwards Annual Financial Repts 1982 & 1983
BRADLEY, E J Philadelphia Electric Co 83/03/14 SALTZMAN, J Assistant Director for State & Licensee Relations 7pp 17605 183 24X Fiche 50-000, 83/03/14, 8303170159

--8303170169 Annual Financial Rept 1982
SMITH, R I , SONN, H W Public Service Electric & Gas Co of New Jersey 83/02/14 52pp 17605 191 24X Fiche 50-000, 83/03/14, 8303170159

--8303170182 Annual Financial Rept 1982
EVERETT, J L , AUSTIN, J H Philadelphia Electric Co 83/03/14
41pp 17605 243 24X Fiche 50-000, 83/03/14, 8303170159

--8303170193 Annual Financial Rept 1982
WEIMER, R D , CURTIS, N M Delmarva Power & Light Co 83/02/04
44pp 17605 287 24X Fiche 50-000, 83/03/14, 8303170159

--8303170206 Annual Financial Rept 1982
FEEHAN, J D Atlantic Electric of New Jersey 83/03/14 42pp
17605 333 24X Fiche 50-000, 83/03/14, 8303170159

DOCKET 50-183 VALLECITOS EXPERIMENTAL SUPERHEAT REACTOR

R Periodic operating reports & related correspondence

8303170399 Forwards "Esada Vallecitos Experimental Superheat Reactor Annual Rept 15 (Deactivated), 1982 "
CUNNINGHAM, G E General Electric Co 83/02/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17610 086 24X
Fiche 50-183, 83/02/11, 8303170399

--8303170404 "Esada Vallecitos Experimental Superheat Reactor Annual Rept 15 (Deactivated), 1982 "
TITUS, G W General Electric Co 83/02/11 4pp 17610 087 24X
Fiche 50-183, 83/02/11, 8303170399

DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

F Security, medical, emergency & fire protection plans

8303290325 Forwards IE Safeguards Insp Rept 50-184/83-02 on 830208 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/03/15
CARTER, R S Commerce, Dept of, National Bureau of Standards 2pp
17716 152 24X Fiche 50-184, 83/03/15, 8303290325

--8303290331 IE Safeguards Insp Rept 50-184/83-02 on 830208 No noncompliance noted Major areas inspected physical protection measures for protecting SNM of moderate strategic significance
SMITH, G C , GODY, A T Region 1, Office of Director 83/03/10
2pp 17716 154 24X Fiche 50-184, 83/03/15, 8303290325

Q Inspection reports, IE Bulletins & correspondence

8303290325 Forwards IE Safeguards Insp Rept 50-184/83-02 on 830208 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/03/15
CARTER, R S Commerce, Dept of, National Bureau of Standards 2pp
17716 152 24X Fiche 50-184, 83/03/15, 8303290325

--8303290331 IE Safeguards Insp Rept 50-184/83-02 on 830208 No noncompliance noted Major areas inspected physical protection measures for protecting SNM of moderate strategic significance
SMITH, G C , GODY, A T Region 1, Office of Director 83/03/10
2pp 17716 154 24X Fiche 50-184, 83/03/15, 8303290325

R Periodic operating reports & related correspondence

8303310243 Forwards "Operations Rept 34, Jul-Dec 1982 "
CARTER, R S Commerce, Dept of, National Bureau of Standards
83/03/18 THOMAS, C O Standardization & Special Projects Branch
1p 17763 041 24X Fiche 50-184, 83/03/18, 8303310243

--8303310245 "Operations Rept 34, Jul-Dec 1982 "
CARTER, R S Commerce, Dept of, National Bureau of Standards
83/03/18 7pp 17763 042 24X Fiche 50-184, 83/03/18, 8303310243

DOCKET 50-185 PLUM BROOK REACTOR - MOCK-UP

R Periodic operating reports & related correspondence

8303160213 Forwards rept of reactor dismantling status for 1982
BOITEL, E C National Aeronautics & Space Admin 83/03/09
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
17596 298 24X Fiche 50-030, 83/03/09, 8303160213

--8303160219 Rept of reactor dismantling status for 1982
* National Aeronautics & Space Admin 83/02/03 7pp 17596 300
24X Fiche 50-030, 83/03/09, 8303160213

W Decommissioning Stage Documents & Correspondence

8303160213 Forwards rept of reactor dismantling status for 1982
BOITEL, E C National Aeronautics & Space Admin 83/03/09
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
17596 298 24X Fiche 50-030, 83/03/09, 8303160213

--8303160219 Rept of reactor dismantling status for 1982
* National Aeronautics & Space Admin 83/02/03 7pp 17596 300
24X Fiche 50-030, 83/03/09, 8303160213

DOCKET 50-186 UNIV OF MISSOURI RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8303090150 Forwards replacement page for security plan Page withheld (ref 10CFR73 21)
MCGINTY, D M Missouri, Univ of, Columbia 83/01/05 Physical Security Licensing Branch 1p 17469 353 24X
Fiche 50-186, 83/01/05, 8303090150

8303030683 Forwards IE Insp Rept 50-186/83-01 on 830201-03 No noncompliance noted
MILLER, J R Region 3, Office of Director 83/02/25 ALGER, D M Missouri, Univ of, Columbia 2pp 17411 016 24X
Fiche 50-186, 83/02/25, 8303030683

--8303030690 IE Insp Rept 50-186/83-01 on 830201-03 No noncompliance noted Major areas inspected security plan implementing procedures, security organization, testing & maint & locks, keys & combinations Details withheld (ref 10CFR73 21)
STAPLETON, B W , CREED, J R Region 3, Office of Director
83/02/24 1p 17411 018 24X Fiche 50-186, 83/02/25, 8303030683

P Operating license stage documents & correspondence

8302220396 Ack receipt of 821220 & 830203 ltrs Records of transfers of low level radwaste before 830430 should be documented, per 830210 telcon
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/14 ALGER, D Missouri, Univ of, Columbia 1p
17473 098 24X Fiche 50-186, 83/02/14, 8302220396

Q Inspection reports, IE Bulletins & correspondence

8302220396 Ack receipt of 821220 & 830203 ltrs Records of transfers of low level radwaste before 830430 should be documented, per 830210 telcon
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/14 ALGER, D Missouri, Univ of, Columbia 1p
17473 098 24X Fiche 50-186, 83/02/14, 8302220396

# DOCKETED ITEMS

--8303090324 Provides commitment that administrative procedures dealing w/transfer of low level waste from reactor license to byproduct license will be established & records of transfers will be maintained by 830430.
ALGER, D. M. Missouri, Univ. of, Columbia. 83/02/03. MILLER, J. R.
Region 3, Office of Director. 1p. 17473:099. 24X
Fiche: 50-186, 83/02/14, 8302220396.

--8303090407 Advises that reactor produced byproduct matls can be stored at site under byproduct license, per 821206 telcon. No action will be taken as result of Item 3 of 820915 notice of violation.
ALGER, D. M. Missouri, Univ. of, Columbia. 82/12/20. MILLER, J. R.
Region 3, Office of Director. 1p. 17473:100. 24X
Fiche: 50-186, 83/02/14, 8302220396.

8303030683 Forwards IE Insp Rept 50-186/83-01 on 830201-03. No noncompliance noted.
MILLER, J. R. Region 3, Office of Director. 83/02/25. ALGER, D. M.
Missouri, Univ. of, Columbia. 2pp. 17411:016. 24X
Fiche: 50-186, 83/02/25, 8303030683.

--8303030690 IE Insp Rept 50-186/83-01 on 830201-03. No noncompliance noted. Major areas inspected: security plan implementing procedures; security organization; testing & maint & locks, keys & combinations. Details withheld (ref 10CFR73.21).
STAPLETON, B. W., CREED, J. R. Region 3, Office of Director.
83/02/24. 1p. 17411:018. 24X Fiche: 50-186, 83/02/25, 8303030683.

DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR

R Periodic operating reports & related correspondence

8303220083 Forwards "Natural Environ Radioactivity Survey for Period Sept 1981 - Aug 1982."
AVANT, D. W. Northrop Corp. 83/03/14. Region 5, Office of Director. 5pp. 17649:289. 24X Fiche: 50-187, 83/03/14, 8303220083.

--8303220090 "Natural Environ Radioactivity Survey for Period Sept 1981 - Aug 1982."
AVANT, D., COZEN, G., WOODS, J. Northrop Corp. 83/03/14. 10pp.
17649:295. 24X Fiche: 50-187, 83/03/14, 8303220083.

DOCKET 50-192 UNIV. OF TEXAS RESEARCH REACTOR

E NRC Safety Evaluation Report (SER), suppls & correspondence

8303160266 Forwards revised Tech Specs re potential channel failure per 830301-04 discussions re SER. Info resolves questions re License R-92 renewal.
BAUER, T. L. Texas, Univ. of. 83/03/11. BERNARD, H. Standardization & Special Projects Branch. 21pp. 17597:083. 24X
Fiche: 50-192, 83/03/11, 8303160266.

--8303160271 Revised Tech Specs changing wording re potential channel failure.
* Texas, Univ. of. 83/03/31. 41pp. 17597:104. 24X
Fiche: 50-192, 83/03/11, 8303160266.

DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC

R Periodic operating reports & related correspondence

8303290481 Annual rept of changes, tests & experiments for FY ending 820630.
DIMEGLIO, A. F. Rhode Island, State of. 83/03/10. Region 1, Office of Director. 1p. 17725:001. 24X Fiche: 50-193, 83/03/10, 8303290481.

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

G Adjudicatory correspondence

8303170485 Order confirming denial of NRC 820510 motion for clarification. Proceeding terminated. ASLB does not clarify final decision at request of party.
BRENNER, L. Atomic Safety and Licensing Board Panel. 83/03/14. 3pp.
17610:123. 24X Fiche: 50-201, 83/03/14, 8303170485.

P Operating license stage documents & correspondence

8303030003 Forwards Rev 2 to "Comparison of High Level Radwastes at West Valley Demonstration Project & Savannah River Project."
HANNUM, W. H. Energy, Dept of, Idaho Operations Office. 83/01/26.
CLARK, A. T. Advanced Fuel & Spent Fuel Licensing Branch. 1p.
17426:163. 24X Fiche: 50-201, 83/01/26, 8303030003.

--8303030006 Rev 2 to "Comparison of High Level Radwastes at West Valley Demonstration Project & Savannah River Project."
* Energy, Dept of. 83/01/21. 28pp. 17426:164. 24X
Fiche: 50-201, 83/01/26, 8303030003.

8303180452 Informs of plans to seal permanently all wells drilled by NRC contractors except wells w/value to site operator, DOE or NY State Energy R&D Authority for site monitoring.
CUNNINGHAM, R. E. Division of Fuel Cycle & Material Safety. 83/03/07.
LAROCCA, J. New York, State of. 1p. 17640:268. 24X
Fiche: 50-201, 83/03/07, 8303180452.

8303290260 Forwards response to 830214 comments re West Valley QA program & manual. NRC QA monitoring visit scheduled for 830308-10.
HANNUM, W. H. Energy, Dept of, Idaho Operations Office. 83/03/08.
CLARK, A. T. Advanced Fuel & Spent Fuel Licensing Branch. 5pp.
17729:038. 24X Fiche: 50-201, 83/03/08, 8303290260.

8303180542 Forwards comments on "Comparison of High Level Radwastes at West Valley Demonstration Project & Savannah River Plant." Application of annulus vacuum maint process will not produce acceptable waste form.
CLARK, A. T. Office of Nuclear Material Safety & Safeguards, Director.
83/03/10. HANNUM, W. H. Energy, Dept of. 4pp. 17639:280. 24X
Fiche: 50-201, 83/03/10, 8303180542.

DOCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8303030668 Responds to 821221 submittal re Rev 8 to physical security plan. Changes acceptable.
KNIGHTON, G. W. Licensing Branch 3. 83/02/23. DIETCH, R. Southern California Edison Co. COTTON, G. D. San Diego Gas & Electric Co.
4pp. 17364:013. 24X Fiche: 50-206, 83/02/23, 8303030668.

8303090282 Forwards executed & confirmed application for Amend 110 to License DPR-13 & Proposed Change 121. Amend revises App A Tech Spec 6.5 re requirements for review & audit of emergency & security plans.
DIETCH, R. Southern California Edison Co. 83/03/04. DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. 1p. 17473:166. 24X
Fiche: 50-206, 83/03/04, 8303090282.

--8303090288 Application for Amend 110 & Proposed Change 121 to License DPR-13, revising App A re review & audit requirements for emergency & security plans. Certificate of Svc encl.
DIETCH, R. Southern California Edison Co. COTTON, G. D. San Diego Gas & Electric Co. 83/03/04. 7pp. 17473:167. 24X
Fiche: 50-206, 83/03/04, 8303090282.

--8303090296 Proposed Change 121 to Tech Specs, revising App A re review & audit requirements for emergency & security plans.
* Southern California Edison Co. 83/03/04. 3pp. 17473:174. 24X
Fiche: 50-206, 83/03/04, 8303090282.

8303250012 Forwards Rev 9 to physical security plan. Rev withheld (ref 10CFR73.21).
BASKIN, K. P. Southern California Edison Co. 83/03/23. Division of Licensing. 1p. 17692:125. 24X Fiche: 50-206, 83/03/23, 8303250012.

8303250029 Forwards Rev 2 to security force training & qualification plan. Rev withheld (ref 10CFR73.21).
BASKIN, K. P. Southern California Edison Co. 83/03/23. Office of Nuclear Reactor Regulation, Director. 1p. 17692:271. 24X
Fiche: 50-206, 83/03/23, 8303250029.

8303300223 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/25. Document Management Branch. 1p. 17750:001. 24X Fiche: 50-206, 83/03/25, 8303300223.

--8303300232 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP SO1-VIII-1 re recognition & classification of emergencies & EPIP SO123-VIII-10 re emergency coordinator duties.
BASKIN, K. P. Southern California Edison Co. 83/03/17.
EISENHUT, D. G. Office of Nuclear Reactor Regulation, Director. 1p.
17750:002. 24X Fiche: 50-206, 83/03/25, 8303300223.

--8303300239 Public version of revised emergency plan implementing procedures, including Procedures EPIP SO1-VIII-1 re recognition & classification of emergencies & EPIP SO123-VIII-10 re emergency coordinator duties.
MCCLOSKEY, D. P. Southern California Edison Co. 83/03/01. 316pp.
17750:003. 24X Fiche: 50-206, 83/03/25, 8303300223.

P Operating license stage documents & correspondence

8303020001 FOIA request for info re efforts to make facility more earthquake resistant
WHARTON, R. J. San Diego, Univ. of. 82/12/14 FELTON, J. M. Division of Rules and Records. 2pp. 17360:009. 24X Fiche. 50-206. 82/12/14. 8303020001.

8303020005 Responds to FOIA request for info re NRC efforts to make facility more earthquake resistant. Forwards documents listed in app. Search for addl documents in progress.
FELTON, J. M. Division of Rules and Records. 83/01/17. WHARTON, R. J. San Diego, Univ. of. 3pp. 17360:011. 24X Fiche. 50-206. 83/01/17. 8303020005.

--8111180081 Advises that Structural Engineering Branch believes slab on ground can be considered to provide sufficient restraint for column base connections based on max loads postulated. Forwards rough calculations of investigation.
KNIGHT, J. P. Assistant Director for Comp. & Structures Engineering (Pre 830201). 81/10/30. LAINAS, G. C. Assistant Director for Safety Assessment. 5pp. 17360:014. 24X Fiche. 50-206. 83/01/17. 8303020005.

--8201220233 Requests assistance in reviewing evaluation of masonry walls. Review to be completed by 820129 per GC Lainas 811207 request.
SCHAUER, F. P. Structural Engineering Branch. 81/12/28. RUSSELL, W. T. Systematic Evaluation Program Branch. 2pp. 17360:019. 24X Fiche. 50-206. 83/01/17. 8303020005.

--8202110128 Summarizes agreements reached at 820112 meeting re review responsibilities for masonry walls & structures. Structural Engineering Branch responsible for review of methodology criteria & results re adequacy of masonry walls.
RUSSELL, W. T. Systematic Evaluation Program Branch. 82/01/18. SCHAUER, F. Structural Engineering Branch. 1p. 17360:036. 24X Fiche. 50-206. 83/01/17. 8303020005.

--8202240261 Advises that NRC cannot accept licensee proposed nonlinear inelastic time history analysis methodology as sole basis for evaluation & qualification of masonry walls at facility. Proposed method of proof has shortcomings.
KNIGHT, J. P. Assistant Director for Comp. & Structures Engineering (Pre 830201). 82/02/04. LAINAS, G. C. Assistant Director for Safety Assessment. 8pp. 17360:021. 24X Fiche. 50-206. 83/01/17. 8303020005.

--8205190297 Comments on draft safety evaluation on seismic design. Facility should remain shutdown until criteria & mods are implemented.
MATTSON, R. J. Division of Systems Integration (post 811005). 82/05/14. LAINAS, G. Assistant Director for Safety Assessment. 1p. 17360:088. 24X Fiche. 50-206. 83/01/17. 8303020005.

--8205200343 Requests investigation into circumstances of late notification by util to NRC of significant seismic design deficiencies at facility.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 82/05/13. FITZGERALD, J. A. Director's Office, Office of Inspection and Enforcement. 3pp. 17360:092. 24X Fiche. 50-206. 83/01/17. 8303020005.

--8205200351 Comments on draft safety evaluation. Elastic piping portion of WECAN verified for response spectrum analysis per IE Bulletin 79-07 requirements. No structures w/gaps independently analyzed & compared w/WECAN results.
KNIGHT, J. P. Assistant Director for Comp. & Structures Engineering (Pre 830201). 82/05/13. LAINAS, G. C. Assistant Director for Safety Assessment. 1p. 17360:089. 24X Fiche. 50-206. 83/01/17. 8303020005.

--8205270550 Forwards draft safety evaluation re seismic design, updating Bulletin safety evaluation. Draft address concerns over plants ability to meet original design basis to safety shutdown in event of earthquake.
LAINAS, G. C. Assistant Director for Safety Assessment. 82/05/10. KNIGHT, J. P. Assistant Director for Comp. & Structures Engineering (Pre 830201). 25pp. 17360:063. 24X Fiche. 50-206. 83/01/17. 8303020005.

--8205280028 Notes editorial corrections for Reg Guide 5.59, Revision 1.
GOLLER, K. R. Division of Facility Operations. 82/05/18. BURNETT, R. F. Division of Safeguards. 2pp. 17360:045. 24X Fiche. 50-206. 83/01/17. 8303020005.

--8205280058 Informs of review of Section III.E, "Masonry Walls in Spent Fuel Bldg & Ventilation Equipment Bldg," draft safety evaluation will be completed by 820528.
KNIGHT, J. P. Assistant Director for Comp. & Structures Engineering (Pre 830201). 82/05/18. LAINAS, G. C. Assistant Director for Safety Assessment. 2pp. 17360:090. 24X Fiche. 50-206. 83/01/17. 8303020005.

--8208120377 Responds to 820621, 0702 & 16 memos requesting comments on emergency procedures guidelines for B&W, C-E & BWR owners group. Branch input unnecessary. Procedures & Test Review Branch should be included in review.
SRINIVASAN, M. Power Systems Branch. 82/07/29. SHERON, B. Reactor Systems Branch. 2pp. 17360:048. 24X Fiche. 50-206. 83/01/17. 8303020005.

--8302040612 Forwards Franklin Research Ctr review questions re Masonry Wall Test Program & fuel storage bldg seismic review, per agreement reached at 821213 conference call. Addl comments & seismic design adequacy questions encl.
SCHAUER, F. P. Structural Engineering Branch. 82/12/28. RUSSELL, W. T. Systematic Evaluation Program Branch. 5pp. 17360:058. 24X Fiche. 50-206. 83/01/17. 8303020005.

--8303020040 Outlines evaluation of licensee 820315 proposal & summarizes telcons re masonry wall evaluation. Proposal unacceptable due to listed reasons. Also lists technical concerns re inelastic spectrum methodology.
CHOKSHI, N. Structural Engineering Branch. 82/04/06. PAULSON, W. Operating Reactors Branch 5. 3pp. 17360:050. 24X Fiche. 50-206. 83/01/17. 8303020005.

--8303020155 Forwards completed evaluation of proposed masonry wall test program. Program intended to provide relevant test data for validation of proposed nonlinear inelastic time history analysis methodology.
KNIGHT, J. P. Assistant Director for Comp. & Structures Engineering (Pre 830201). 82/09/10. LAINAS, G. C. Assistant Director for Safety Assessment. 5pp. 17360:053. 24X Fiche. 50-206. 83/01/17. 8303020005.

8303240214 Requests negotiations w/DOE to complete & execute contract for disposal of spent nuclear fuel & high level radwaste.
BRIDENBECKER, R. Southern California Edison Co. 83/02/02.
HODEL, D. P. Energy, Dept. of. 2pp. 17682:186. 24X Fiche. 50-206. 83/02/02. 8303240214.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche. 50-000. 83/02/16. 8302170082.

8303010002 Notification of contract execution, Mod 3 to "Followon Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station." Contractor: MIT.
LITTLE, M. Administrative Contracts Branch. FIN B-6898. 83/02/17. VOLLMER, R. Division of Engineering. JACKSON, R. NRC - No Detailed Affiliation Given. 1p. 17322:350. 24X Fiche. 50-206. 83/02/17. 8303010002.

--8303010003 Mod 3, extending period of performance to 831230 & adding requirement of monthly business ltr, to "Followon Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station."
AKI, K. Massachusetts Institute of Technology. REBELLO, J. E. Division of Contracts. FIN B-6898. 83/02/17. 3pp. 17322:351. 24X Fiche. 50-206. 83/02/17. 8303010002.

8303070018 Clarifies response to Item 6 of 830119 ltr re review of emergency operating procedures to verify appropriate isolation of letdown flow, per NUREG-0737, Item II.B.2, "Post-Accident Shielding." Warnings posted in control room.
BASKIN, K. P. Southern California Edison Co. 83/02/22.
CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 17434:321. 24X Fiche. 50-206. 83/02/22. 8303070018.

8303010550 Advises that SEP Topics VI-2.D, "Mass & Energy Release for Possible Pipe Break Inside Containment," VI-3, "Containment Pressure & Heat Removal Capability," & VIII-3.B, "DC Power Sys Bus Voltage Monitoring & Annunciation," closed.
PAULSON, W. A. Operating Reactors Branch 5. 83/02/24. DIETCH, R. Southern California Edison Co. 1p. 17337:267. 24X Fiche. 50-206. 83/02/24. 8303010550.

8303070064 Forwards responses to NRC 810828 & 1117 requests for addl info re SEP Topics VI-10.A, "Testing of Reactor Trip Sys & ESFs" & VII-2, "ESF Sys Control Logic & Design," respectively.
KRIEGER, R. W. Southern California Edison Co. 83/02/28.
CRUTCHFIELD, D. Operating Reactors Branch 5. 18pp. 17435:253. 24X Fiche. 50-206. 83/02/28. 8303070064.

8303070079 Forwards description of methods for combination of seismic anchor movement & seismic intertia responses of piping, per 830217 meeting & SEP Topic III-6, "Seismic Design Considerations."
BASKIN, K. P. Southern California Edison Co. 83/02/28.
CRUTCHFIELD, D. Operating Reactors Branch 5. 11pp. 17435:277. 24X Fiche. 50-206. 83/02/28. 8303070079.

# DOCKETED ITEMS

8303070102 Advises of schedule to close out open action items re inservice testing program for pumps & valves.Required info will be submitted by 830601.
KRIEGER,R W. Southern California Edison Co. 83/02/28.
CRUTCHFIELD,D. Operating Reactors Branch 5. 1p. 17435:271. 24x
Fiche: 50-206:83/02/28,8303070102.

8303070084 Comments on NRC 820423 final evaluation of SEP Topic III-7.D, "Containment Structural Integrity Test." Evaluation should be rewritten to reflect new peak pressure re design basis main steam line break accident.
KRIEGER,R W. Southern California Edison Co. 83/03/01.
CRUTCHFIELD,D. Operating Reactors Branch 5. 1p. 17435:002. 24x
Fiche: 50-206,83/03/01,8303070084.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys.Svc list encl.
EISENHUT,D G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000,83/03/02,8303020321.

8303070020 Forwards evaluation results of pressure & temp values resulting from pipe breaks outside containment.Calculated values incorporated into environ qualification program for equipment identified in util 801031 submittal.
BASKIN,K P. Southern California Edison Co. 83/03/02.
CRUTCHFIELD,D. Operating Reactors Branch 5. 33pp. 17435:179. 24x
Fiche: 50-206,83/03/02,8303070020.

8303070073 Forwards responses to NRC 830103 questions & comments re masonry wall test program per SEP Topic III-6.NRC approval of test program requested by 830314 to proceed w/testing of first wall specimen.
BASKIN,K P. Southern California Edison Co. 83/03/02.
CRUTCHFIELD,D. Operating Reactors Branch 5. 19pp. 17435:230. 24x
Fiche: 50-206,83/03/02,8303070073.

8303080261 Responds to 830217 request for addl info re containment ventilation isolation valve leakage rate test program & necessary Tech Spec changes.Proposed Tech Spec change incorporating test interval will be submitted by 830415.
KRIEGER,R W. Southern California Edison Co. 83/03/04.
CRUTCHFIELD,D. Operating Reactors Branch 5. 1p. 17446:340. 24x
Fiche: 50-206,83/03/04,8303080261.

8303090282 Forwards executed & confirmed application for Amend 110 to License DPR-13 & Proposed Change 121.Amend revises App A Tech Spec 6.5 re requirements for review & audit of emergency & security plans.
DIETCH,R. Southern California Edison Co. 83/03/04. DENTON,H R. Office of Nuclear Reactor Regulation, Director. 1p. 17473:166. 24x
Fiche: 50-206,83/03/04,8303090282.

--8303090288 Application for Amend 110 & Proposed Change 121 to License DPR-13,revising App A re review & audit requirements for emergency & security plans.Certificate of Svc encl.
DIETCH,R. Southern California Edison Co. COTTON,G D. San Diego Gas & Electric Co. 83/03/04. 7pp. 17473:167. 24x
Fiche: 50-206,83/03/04,8303090282.

--8303090296 Proposed Change 121 to Tech Specs,revising App A re review & audit requirements for emergency & security plans.
* Southern California Edison Co. 83/03/04. 3pp. 17473:174. 24x
Fiche: 50-206,83/03/04,8303090282.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12).
Svc list encl.
EISENHUT,D G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X
Fiche: 50-000,83/03/07,8303040005.

8303100361 Forwards final topic safety evaluation re SEP Topic V-5, "RCPB Leakage Detection." Need for plant mods to leakage detection sys will be determined during integrated assessment.
PAULSON,W A. Operating Reactors Branch 5. 83/03/07. DIETCH,R. Southern California Edison Co. 7pp. 17490:347. 24x
Fiche: 50-206,83/03/07,8303100361.

8303150477 Forwards corrected Table 3 per 820816 evaluation of seismic safety margins in Facility seismic re-evaluation program. Conclusions of previous evaluation remain unchanged. Nonlinear evaluation of reactor coolant loop not affected.
BASKIN,K P. Southern California Edison Co. 83/03/11.
CRUTCHFIELD,D. Operating Reactors Branch 5. 2pp. 17568:251. 24X
Fiche: 50-206,83/03/11,8303150477.

8303150584 Forwards one oversize sequencer logic drawing in response to NRC request.Aperture card is available in PDR.
KRIEGER,R W. Southern California Edison Co. 83/03/11.
PAULSON,W A., MCKENNA,E. NRC - No Detailed Affiliation Given. 1p. 17568:298. 24X Fiche: 50-206,83/03/11,8303150584.

8303170170 Forwards Amend 67 to Provisional License DPR-13 & notice of issuance & availability.Amend deletes nonradiological water quality-related requirements from Tech Specs.
CRUTCHFIELD,D. Operating Reactors Branch 5. 83/03/11. DIETCH,R. Southern California Edison Co. 5pp. 17606:060. 24X
Fiche: 50-206,83/03/11,8303170170.

--8303170203 Amend 67 to Provisional License DPR-13,deleting nonradiological water quality-related requirements from Tech Specs.
CRUTCHFIELD,D. Operating Reactors Branch 5. 83/03/11. 5pp. 17606:065. 24X Fiche: 50-206,83/03/11,8303170170.

--8303170211 Notice of issuance of Amend 67 to Provisional License DPR-13.
CRUTCHFIELD,D. Operating Reactors Branch 5. 83/03/11. 2pp. 17606:070. 24X Fiche: 50-206,83/03/11,8303170170.

8303160140 Forwards final topic evaluation concluding that facility design meets criteria of SEP Topic XV-5, "Loss of Normal Feedwater Flow."
PAULSON,W. Operating Reactors Branch 5. 83/03/14. DIETCH,R. Southern California Edison Co. 6pp. 17597:069. 24X
Fiche: 50-206,83/03/14,8303160140.

8303170305 Forwards order confirming util commitments to implement post-TMI related items set forth in NUREG-0737 per Generic Ltrs 82-05 & 82-10.
CRUTCHFIELD,D. Operating Reactors Branch 5. 83/03/14. DIETCH,R. Southern California Edison Co. 3pp. 17605:133. 24X
Fiche: 50-206,83/03/14,8303170305.

--8303170308 Order confirming licensee commitments on post-TMI related issues contained in NUREG-0737.
EISENHUT,D G. Division of Licensing. 83/03/14. Southern California Edison Co. 8pp. 17605:136. 24X Fiche: 50-206,83/03/14, 8303170305.

8303220009 Summary of 821216 meeting w/util,EDS Nuclear & Bechtel re method of analysis of piping stresses due to seismic anchor movements per SEP Topic III-6.
PAULSON,W A. Operating Reactors Branch 5. 83/03/15. Operating Reactors Branch 5. 3pp. 17652:119. 24X Fiche: 50-206,83/03/15, 8303220009.

8303220248 Summary of 821217 meeting w/util,Bechtel & Westinghouse re analysis criteria concerning seismic re-evaluation of plant concerning SEP Topic III-6.Viewgraphs encl.
PAULSON,W A. Operating Reactors Branch 5. 83/03/15. Operating Reactors Branch 5. 29pp. 17656:300. 24X Fiche: 50-206,83/03/15, 8303220248.

8303210107 Submits proposed rev to SEP Topic XV-10, "Chemical & Vol Control Sys Malfunction that Results in Decrease in Boron Concentration in Reactor Coolant." Rev corrects audible count rate generated by ex-core detectors.
KRIEGER,R W. Southern California Edison Co. 83/03/17.
CRUTCHFIELD,D. Operating Reactors Branch 5. 1p. 17629:280. 24X
Fiche: 50-206,83/03/17,8303210107.

8303220001 Forwards addl procedure directly establishing requirements to monitor refueling water storage tank level on weekly basis per 830228 ltr commenting on final SER of SEP Topics VI-10.A & VII-2.
KRIEGER,R W. Southern California Edison Co. 83/03/18.
CRUTCHFIELD,D. Operating Reactors Branch 5. 1p. 17652:182. 24X
Fiche: 50-206,83/03/18,8303220001.

--8303220006 Rev 0 to "Tech Spec Level Surveillances."
* Southern California Edison Co. 82/12/07. 8pp. 17652:183. 24X
Fiche: 50-206,83/03/18,8303220001.

8303230241 Summary of 830217 meeting w/utils,EG&G,Bechtel & EDS Nuclear re proposed resolution of outstanding issues concerning SEP Topic III-6, "Seismic Design Considerations." Viewgraphs encl.
PAULSON,W A. Operating Reactors Branch 5. 83/03/18. Operating Reactors Branch 5. 45pp. 17661:102. 24X Fiche: 50-206,83/03/18, 8303230241.

8303250097 Forwards addl info re SEP Topics VI-10.A & VII-2 per NRC request.W/two oversize drawings.Aperture cards are available in PDR.
KRIEGER,R W. Southern California Edison Co. 83/03/22.
PAULSON,W A., MCKENNA,E. NRC - No Detailed Affiliation Given. 4pp. 17692:064. 24X Fiche: 50-206,83/03/22,8303250097.

8303250087 Informs that 821118 requested Tech Spec change re TMI Action Item II.E.1.2, "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication," will be submitted 90 days prior to startup from current outage.
KRIEGER, R.W. Southern California Edison Co. 83/03/23.
CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 17693:068. 24X Fiche: 50-206, 83/03/23, 8303250087.

8303280010 Advises that new proposed version of 801201 Amend 94 re DHR capability will be submitted by 830601, due to substantial changes & various required in-house reviews.
KRIEGER, R.W. Southern California Edison Co. 83/03/23.
CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 17707:154. 24X Fiche: 50-206, 83/03/23, 8303280010.

G. Inspection reports, IE Bulletins & correspondence

8303110058 Responds to FOIA request for rept by Ofc of Inspector & Auditor & associated records. Forwards documents listed in 3pp. Documents partially withheld (ref FOIA Exemptions 6 & 7). Denial may be appealed within 30 days from ltr receipt.
FELTON, J.M. Division of Rules and Records. 83/02/03.
EMSHWILLER, J.R. Wall Street Journal. 3pp. 17520:189. 24X Fiche: 50-206, 83/02/03, 8303110058.

--8303110066 "Paul P. Narbut: Release of Draft Rept to License," rept of investigation. Personally identifiable info deleted.
GAMBLE, D.H., RESNER, M.E. Office of Inspector & Auditor. 82/06/15. 57pp. 17520:192. 24X Fiche: 50-000, 83/02/03, 8303110058.

--8303110166 Recommends civil penalties not be imposed. Reasons why strong enforcement ltr should be issued listed.
SPENCER, G. Division of Radiological Safety & Safeguards Program. 82/03/17. LIEBERMAN, J. Director's Office, Office of Inspection and Enforcement. 9pp. 17520:342. 24X Fiche: 50-000, 83/02/03, 8303110058.

8303040404 Forwards IE Insp Repts 50-206/83-01, 50-361/83-01 & 50-362/83-01 on 830103-21. No noncompliance noted.
BISHOP, T.W. Division of Resident, Reactor Project & Engineering Programs. 83/02/15. PAPAY, L.T. Southern California Edison Co. 2pp. 17374:309. 24X Fiche: 50-206, 83/02/15, 8303040404.

--8303040414 IE Insp Repts 50-206/83-01, 50-361/83-01 & 50-362/83-01 on 830103-21. No noncompliance noted. Major areas inspected: surveillance program review, design changes & mods, circulars & bulletins & power ascention test procedures.
STEWART, J.P., KIRSCH, D.F. Division of Resident, Reactor Project & Engineering Programs. 83/02/15. 10pp. 17374:311. 24X Fiche: 50-206, 83/02/15, 8303040404.

8303100028 Addl response to FOIA request for documents re 82113C special insp rept. App A documents available in PDR under FOIA-82-528. Forwards documents listed in Apps B & C. App C documents partially withheld (ref FOIA Exemption 6).
FELTON, J.M. Division of Rules and Records. 83/02/15. GARDE, B. Government Accountability Project. 5pp. 17493:007. 24X Fiche: 50-206, 83/02/15, 8303100028.

--8303100033 Structural details w/handwritten notes indicating violations at facilities.
* Affiliation Unknown. 82/11/16. 3pp. 17493:016. 24X Fiche: 50-206, 83/02/15, 8303100028.

--8303100037 Summarizes investigation re E Kent allegations concerning deficient equipment/piping at facilities. Three interviews conducted w/E Kent. No evidence of willful violation of NRC rules found. No further action warranted.
JOUKOFF, P.V. Region 5, Office of Director. 82/10/29. Region 5, Office of Director. 1p. 17493:019. 24X Fiche: 50-206, 83/02/15, 8303100028.

--8303100041 Submits handwritten notes re E Kent allegations concerning welding at facilities.
SHACKLETON, O.C. NRC - No Detailed Affiliation Given. 82/10/12.
FOSTER, J. NRC - No Detailed Affiliation Given. 2pp. 17493:020. 24X Fiche: 50-206, 83/02/15, 8303100028.

--8303100045 Submits handwritten memo discussing directives from headquarters on action to be taken re E Kent allegations concerning facilities.
SHACKLETON, O.C. NRC - No Detailed Affiliation Given. 82/10/14.
NRC - No Detailed Affiliation Given. 1p. 17493:022. 24X Fiche: 50-206, 83/02/15, 8303100028.

--8303100050 Forwards WV Johnston 821117 memo to TM Novak transmitting SER re E Kent allegations concerning adequacy of weldments at facilities, per 821029 request. Allegations unsubstantiated & no further action recommended.
EISENHUT, D.G. Division of Licensing. 82/11/28. CREWS, J.L. Division of Resident, Reactor Project & Engineering Programs. 1p. 17493:023. 24X Fiche: 50-206, 83/02/15, 8303100028.

--8303100067 Forwards EE Kent statement obtained on 821016 & modified statement, per 821019 telcon. W/o encls.
SHACKLETON, O.C. NRC - No Detailed Affiliation Given. 82/10/20.
SMITH, D. Materials Engineering Branch. 1p. 17493:040. 24X Fiche: 50-206, 83/02/15, 8303100028.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000, 83, J2/25, 8212060367.

8303070009 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Two power & control penetration & nine instrumentation penetrations mfg by Bunker-Ramo installed. Details listed.
HAYNES, J.G. Southern California Edison Co. 83/03/03. MARTIN, J.B. Region 5, Office of Director. 4pp. 17434:332. 24X Fiche: 50-206, 83/03/03, 8303070009.

8303290453 Forwards IE Insp Repts 50-206/83-04, 50-361/83-06 & 50-362/83-06 on 830103-0212 & IE Insp Rept 50-361/83-08 on 830207-11.
CREWS, J.L. Division of Resident, Reactor Project & Engineering Programs. 83/03/04. PAPAY, L.T. Southern California Edison Co. 4pp. 17725:285. 24X Fiche: 50-206, 83/03/04, 8303290453.

--8303290462 IE Insp Repts 50-206/83-04, 50-361/83-06 & 50-362/83-06 on 830103-0212. No noncompliance noted. Major areas inspected: monthly mains & surveillance activities, followup of LERs, unresolved item & notice of violation.
CHAFFEE, A.E., MILLER, L., KIRSCH, D.F. Region 5, Office of Director. 83/03/04. 17pp. 17725:289. 24X Fiche: 50-206, 83/03/04, 8303290453.

--8303290468 IE Insp Rept 50-361/83-08 on 830207-11. No noncompliance noted. Failure to have operable post-accident sampling sys & fully implemented post-accident sampling program & failure to rept violation of License Condition 2.G.
YUHAS, G.P., SHERMAN, C.I., WENSLAWSKI, F. Region 5, Office of Director. 83/03/04. 12pp. 17725:306. 24X Fiche: 50-206, 83/03/04, 8303290453.

8303100272 Responds to IE Bulletin 83-01. Unit currently shut down w/no immediated plans for resuming operations. Testing of undervoltage trip function independent of shunt trip actually performed 830307. All breakers performed acceptably.
DIETCH, R. Southern California Edison Co. 83/03/08. ENGELKEN, R.H. Region 5, Office of Director. 3pp. 17490:185. 24X Fiche: 50-206, 83/03/08, 8303100272.

8303290273 Forwards IE Insp Rept 50-206/83-05 on 830213-28. No noncompliance noted.
BISHOP, T.W. Region 5, Office of Director. 83/03/10. PAPAY, L.T. Southern California Edison Co. 2pp. 17716:113. 24X Fiche: 50-206, 83/03/10, 8303290273.

--8303290279 IE Insp Rept 50-206/83-05 on 830213-28. No noncompliance noted. Major areas inspected: plant operations during long-term shutdown, monthly maint & surveillance activities & followup of LERs & inspector identified items.
MILLER, L., KIRSCH, D.F. Region 5, Office of Director. 83/03/09. 5pp. 17716:115. 24X Fiche: 50-206, 83/03/10, 8303290273.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8303220085 Discusses results of scram breaker testing per 830308 response to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Breakers successfully operated.
KRIEGER, R.W. Southern California Edison Co. 83/03/18.
ENGELKEN, R.H. Region 5, Office of Director. 2pp. 17652:212. 24X Fiche: 50-206, 83/03/18, 8303220085.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

R. Periodic operating reports & related correspondence

8303080156 Forwards monthly operating rept for Dec 1982.
RAY, H. B. Southern California Edison Co. 83/01/14. Division of Data Automation & Management Information. 1p. 17457:013. 24X Fiche: 50-206, 83/01/14, 8303080156.

--8303080161 Monthly operating rept for Dec 1982.
FRANCIS, J. Southern California Edison Co. 83/01/14. 4pp. 17457:014. 24X Fiche: 50-206, 83/01/14, 8303080156.

8303150589 Forwards monthly operating rept for Jan 1983.
RAY, H. B. Southern California Edison Co. 83/02/15. Office of Resource Management, Director. 1p. 17567:317. 24X Fiche: 50-206, 83/02/15, 8303150589.

--8303150591 Monthly operating rept for Jan 1983.
SPEER, M. Southern California Edison Co. 83/02/15. 5pp. 17567:318. 24X Fiche: 50-206, 83/02/15, 8303150589.

S. Reportable occurrences, LERs & related correspondence

8303220111 PNO-V-83-014 on 830316. Inadvertent loss of instrument air to saltwater cooling sys occurred. Caused by careless const worker inadvertently drilling through instrument air line. Temporary repairs made.
KIRSCH, D. F. Region 5, Office of Director. 83/03/17. 1p. 17649:273. 24X Fiche: 50-206, 83/03/17, 8303220111.

U. Congressional/Executive Correspondence

8303170015 Responds to 830119 ltr re steam generator tube degradation caused by caustic induced intergranular attack. Sleeving prolongs life of severely degraded steam generator tubes.
PALLADINO, N. J. Commissioners. 83/03/07. PATTERSON, J. M. House of Rep. 8pp. 17624:320. 24X Fiche: 50-206, 83/03/07, 8303170015.

--8303170018 Requests info re steam generator leaks as followup to Subcommittee on Oversight & Investigations of House Committee on Interior & Insular Affairs 821213 hearing.
PATTERSON, J. M. House of Rep. 83/01/19. PALLADINO, N. J. Commissioners. 2pp. 17624:329. 24X Fiche: 50-206, 83/03/07, 8303170015.

8303290232 Responds to 830119 ltr re steam generator leaks. Leaks caused by earlier operation of unit w/phosphate chemistry secondary water treatment sys, resulting in sludge deposits in tube sheets. Chemistry control program employed.
PALLADINO, N. J. Commissioners. 83/03/07. PATTERSON, J. M. House of Rep. 3pp. 17727:322. 24X Fiche: 50-206, 83/03/07, 8303290232.

--8303290241 Requests info re steam generator leaks & generator tube degradation. Congressman unable to attend 821213 subcommittee hearing where info was presented.
PATTERSON, J. M. House of Rep. 83/01/19. PALLADINO, N. J. Commissioners. 2pp. 17727:325. 24X Fiche: 50-206, 83/03/07, 8303290232.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303070039 Identifies all requests for site visits to conduct operator licensing exams or instructor certification exams, in response to Generic Ltr 83-01.
BASKIN, R. P. Southern California Edison Co. 83/03/03. EISENHUT, D. G. Division of Licensing. 2pp. 17435:288. 24X Fiche: 50-206, 83/03/03, 8303070039.

DOCKET 50-213 HADDAM NECK PLANT

F. Security, medical, emergency & fire protection plans

8303040205 Advises that changes to plant suitability training & qualification plan contained in 821122 ltr acceptable. Encl to util ltr withheld (ref 10CFR73.21).
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/01/27. COUNSIL, W. G. Connecticut Yankee Atomic Power Co. 2pp. 17427:357. 24X Fiche: 50-213, 83/01/27, 8303040205.

8303240455 Forwards IE Insp Rept 50-213/83-01 on 830103-0206. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/01. COUNSIL, W. G. Connecticut Yankee Atomic Power Co. 2pp. 17678:077. 24X Fiche: 50-213, 83/03/01, 8303240455.

--8303240461 IE Insp Rept 50-213/83-01 on 830103-0206. No noncompliance noted. Major areas inspected: review of periodic & special repts, shift logs & operating records, site seismic monitoring & shipment of radioactive matl.
REGELOWSKI, T., BRIGGS, L. Region 1, Office of Director. ELSASSER, T. C. Division of Project & Resident Programs. 83/02/25. 11pp. 17678:079. 24X Fiche: 50-213, 83/03/01, 8303240455.

8303090233 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17484:335. 24X Fiche: 50-213, 83/03/02, 8303090233.

--8303090240 Forwards public version of Rev 2 to Emergency Plan Implementing Procedure EPP 1.5-40-D, "Post-Accident Sampling of Containment Atmosphere" & Rev 6 to EPIP 1.5-33-C, "Shift Supervisor Staff Assistant."
COUNSIL, W. G., SEARS, C. F. Connecticut Yankee Atomic Power Co. 83/02/10. EISENHUT, D. G. Division of Licensing. 1p. 17484:336. 24X Fiche: 50-213, 83/03/02, 8303090233.

--8303090249 Public version of Rev 2 to Emergency Plan Implementing Procedure EPP 1.5-40-D, "Post-Accident Sampling of Containment Atmosphere" & Rev 6 to EPIP 1.5-33-C, "Shift Supervisor Staff Assistant."
* Connecticut Yankee Atomic Power Co. 83/01/28. 33pp. 17484:337. 24X Fiche: 50-213, 83/03/02, 8303090233.

8303160456 Forwards IE Safeguards Insp Rept 50-213/83-04 on 830131-0204. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/02. COUNSIL, W. G. Connecticut Yankee Atomic Power Co. 2pp. 17587:279. 24X Fiche: 50-213, 83/03/02, 8303160456.

--8303160467 IE Safeguards Insp Rept 50-213/83-04 on 830131-0204. No noncompliance noted. Major areas inspected: physical barriers (protected & vital areas), security sys power supply, lighting, alarm station training & qualification plan.
DUNLOP, J. M., MADDEN, W. J., GODY, A. T. Region 1, Office of Director. 83/02/25. 4pp. 17587:281. 24X Fiche: 50-213, 83/03/02, 8303160456.

8303220096 Forwards draft exercise controller manual for 830423 emergency preparedness exercise. Limited distribution of encl manual requested. W/o encl.
COUNSIL, W. G., WERNER, R. P. Connecticut Yankee Atomic Power Co. 83/03/09. HAYNES, R. C. Region 1, Office of Director. 2pp. 17650:053. 24X Fiche: 50-213, 83/03/09, 8303220096.

8303180500 Forwards App C to "Emergency Preparedness Evaluation Rept," per NUREG-0654.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/14. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 1p. 17622:078. 24X Fiche: 50-213, 83/03/14, 8303180500.

--8303180506 App C to "Emergency Preparedness Evaluation Rept."
* Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/14. 36pp. 17622:079. 24X Fiche: 50-213, 83/03/14, 8303180500.

8303290058 Releases public version of rept of emergency plan media briefing session.
FELTON, J. M. Division of Rules and Records. 83/03/21. Document Management Branch. 1p. 17730:290. 24X Fiche: 50-000, 83/03/21, 8303290058.

--8303290064 Forwards public version of rept of 830113 emergency plan media briefing session.
COUNSIL, W. G. Connecticut Yankee Atomic Power Co. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities Service Co. 83/03/11. CLARK, R. A. Operating Reactors Branch 3. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 17730:291. 24X Fiche: 50-000, 83/03/21, 8303290058.

P. Operating license stage documents & correspondence

8303030077 Forwards SEP Topic III-6, "Seismic Design Considerations," providing details on methodology & analysis results of mechanical & electrical equipment selected for evaluation. Info should be considered in developing final SER.
COUNSIL, W. G. Connecticut Yankee Atomic Power Co. 83/02/09. CRUTCHFIELD, D. Operating Reactors Branch 5. 149pp. 17411:335. 24X Fiche: 50-213, 83/02/09, 8303030077.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303010598 Forwards safety evaluation & technical evaluation rept, "Design Codes, Design Criteria & Loading Combinations (SEP III-7B)" & "Structural Review of CT Yankee Nuclear Generating Plant, Containment Structure Under Combined . . ."
CRUTCHFIELD, D. Operating Reactors Branch 5 83/02/23 COUNSIL, W. G. Connecticut Yankee Atomic Power Co. 12pp. 17337:001. 24X
Fiche: 50-213, 83/02/23, 8303010598.

--8209030274 "Structural Review of CT Yankee Nuclear Generating Plant, Containment Structure Under Combined Loads," final rept.
LIAW, C. Y. EG&G, Inc. TSAI, N. C., PAZARGADI, S. NCT Engineering, Inc. FIN A-0436. SRD-316. 82/08/31. Systematic Evaluation Program Branch. 57pp. 17818:309. 24X Fiche: 50-213, 83/02/23, 8303010598.

8303040178 Responds to 830128 ltr re simulator program & commends util commitment to provide plant-specific simulators for use in training nuclear power plant operators.
THOMPSON, H. L. Division of Human Factors Safety 83/02/25.
COUNSIL, W. G. Northeast Utilities. 4pp. 17427:018. 24X
Fiche: 50-000, 83/02/25, 8303040178.

--8303040187 Discusses use of plant simulators to train nuclear power plant operators. Util committed to procurement & use of plant-specific simulators.
COUNSIL, W. G. Connecticut Yankee Atomic Power Co. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
COUNSIL, W. G. Northeast Utilities. 83/01/28. DIRCKS, W. J. Office of the Executive Director for Operations. 3pp. 17427:022. 24X
Fiche: 50-000, 83/02/25, 8303040178.

8303040604 Forwards SER re SEP Topic III-6, "Seismic Design Considerations, Haddam Neck Plant." Facility generally capable of withstanding postulated seismic loads, except for listed structures & supports.
CRUTCHFIELD, D. Operating Reactors Branch 5 83/02/25. COUNSIL, W. G. Connecticut Yankee Atomic Power Co. 17pp. 17368:028. 24X
Fiche: 50-213, 83/02/25, 8303040604.

--8303040610 Rev 1 to "Safety-Related Piping Seismic Qualification Program," criteria document.
MAWSON, T. J., MAGID, A. F., DEBARBA, E. A. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 82/08/10. 216pp. 17368:129. 24X
Fiche: 50-213, 83/02/25, 8303040604.

8303080317 Advises that proposed schedule for completion of mods per NUREG-0737, Item III.D.3.4, "Control Room Habitability," will be postponed until 841231.
COUNSIL, W. G. Connecticut Yankee Atomic Power Co. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
COUNSIL, W. G. Northeast Utilities. 83/02/28. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 17449:318. 24X
Fiche: 50-000, 83/02/28, 8303080317.

8303080335 Revised application for amend to License DPR-61 consisting of proposed change to Tech Specs incorporating results of analysis using conservative fluence model to determine min temp required for hydrostatic & leak tests.
COUNSIL, W. G. Connecticut Yankee Atomic Power Co. COUNSIL, W. G. Northeast Utilities. 83/02/28. CRUTCHFIELD, D. Operating Reactors Branch 5. 3pp. 17441:358. 24X Fiche: 50-213, 83/02/28, 8303080335.

--8303080342 Revised Tech Spec Figure 3.4-1, incorporating results of analysis using conservative fluence model to determine min temp required for hydrostatic & leak rate tests.
* Northeast Utilities. 83/02/28. 1p. 17441:362. 24X
Fiche: 50-213, 83/02/28, 8303080335.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303080110 Forwards Amend 52 to License DPR-61, safety evaluation & notice of issuance & availability. Amend revises Tech Specs to permit operation in Cycle 12 following refueling.
CRUTCHFIELD, D. Operating Reactors Branch 5 83/03/03 COUNSIL, W. G. Connecticut Yankee Atomic Power Co. 2pp. 17458:119. 24X
Fiche: 50-213, 83/03/03, 8303080110.

--8303080118 Amend 52 to License DPR-61, revising Tech Specs to permit operation in Cycle 12 following refueling.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/03/03. 9pp. 17458:121. 24X Fiche: 50-213, 83/03/03, 8303080110.

--8303080123 Safety evaluation supporting Amend 52 to License DPR-61.
* Office of Nuclear Reactor Regulation, Director. 83/03/03. 9pp. 17458:130. 24X Fiche: 50-213, 83/03/03, 8303080110.

--8303080127 Notice of issuance & availability of Amend 52 to License DPR-61.
WAMBACH, T. V. Operating Reactors Branch 5. 83/03/03. 2pp. 17458:139. 24X Fiche: 50-213, 83/03/03, 8303080110.

8303090256 Forwards Amend 53 to License DPR-61, safety evaluation & notice of issuance & availability. Amend allows hydrostatic & leak testing of primary sys at lower temps.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/03/04. COUNSIL, W. G. Connecticut Yankee Atomic Power Co. 2pp. 17473:348. 24X
Fiche: 50-213, 83/03/04, 8303090256.

--8303090262 Amend 53 to License DPR-61, allowing hydrostatic & leak testing of primary sys at lower temps.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/03/04. 6pp. 17473:350. 24X Fiche: 50-213, 83/03/04, 8303090256.

--8303090266 Safety evaluation supporting Amend 53 to License DPR-61.
* Office of Nuclear Reactor Regulation, Director. 83/03/04. 2pp. 17473:356. 24X Fiche: 50-213, 83/03/04, 8303090256.

--8303090271 Notice of issuance & availability of Amend 53 to License DPR-61.
WAMBACH, T. V. Operating Reactors Branch 5. 83/03/04. 2pp. 17473:358. 24X Fiche: 50-213, 83/03/04, 8303090256.

8303290198 Documents util position re 10CFR50.44(c)(3)(ii) requiring LWRs relying on purge/repressurization sys as primary means for controlling combustible gases following design basis LOCA w/internal recombiner or external capability.
COUNSIL, W. G. Connecticut Yankee Atomic Power Co. COUNSIL, W. G. Northeast Utilities. 83/03/04. CRUTCHFIELD, D. Operating Reactors Branch 5. 50pp. 17722:256. 24X Fiche: 50-213, 83/03/04, 8303290198.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303150023 Notification of 830308 meeting w/util in Bethesda, MD to discuss integrated assessment of facility.
BROWN, S. Systematic Evaluation Program Branch. 83/03/07.
RUSSELL, W. T. Systematic Evaluation Program Branch. 3pp. 17586:320. 24X Fiche: 50-213, 83/03/07, 8303150023.

8303180405 Clarifies intended completion date, per response to SER for environ qualification of safety-related electrical equipment. Replacement of containment isolation valve MOV-200 rescheduled for first refueling outage.
COUNSIL, W. G., SEARS, C. F. Connecticut Yankee Atomic Power Co. 83/03/11. CRUTCHFIELD, D. Operating Reactors Branch 5. 6pp. 17622:004. 24X Fiche: 50-213, 83/03/11, 8303180405.

8303180475 Forwards Amend 54 to License DPR-61 & notice of issuance & availability. Amend deletes App B ETS re nonradiological water quality-related requirements.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/03/11. COUNSIL, W. G. Connecticut Yankee Atomic Power Co. 3pp. 17621:227. 24X
Fiche: 50-213, 83/03/11, 8303180475.

--8303180485 Amend 54 to License DPR-61, deleting App B ETS re nonradiological water quality-related requirements.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/03/11. 17pp. 17621:230. 24X Fiche: 50-213, 83/03/11, 8303:90475.

--8303180493 Notice of issuance & availability of Amend 54 to License DPR-61.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/03/11. 2pp. 17621:247. 24X Fiche: 50-213, 83/03/11, 8303180475.

8303210303 Responds to Generic Ltr 82-10 re NUREG-0737, Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps." Submittal of plant-specific analysis by 831231 will satisfy commitments for TMI Action Plan Items II.K.3.5, II.K.3.30 & II.K.3.31.
COUNSIL, W. G. Connecticut Yankee Atomic Power Co. 83/03/11.
EISENHUT, D. G. Division of Licensing. 2pp. 17632:047. 24X
Fiche: 50-213, 83/03/11, 8303210303.

8303230044 Forwards info re inadequate core cooling instrumentation sys in response to Generic Ltr 82-28 & TMI Action Item II.F.2. Core exit thermocouples & subcooled margin monitors installed or upgraded.
COUNSIL,W.G. Connecticut Yankee Atomic Power Co. COUNSIL,W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
COUNSIL,W.G. Northeast Utilities. 83/03/11. EISENHUT,D.G. Division of Licensing. 18pp. 17663:204. 24X Fiche:50-000,83/03/11, 8303230044.

8303220201 Forwards orders confirming licensee commitments on post-TMI related items set forth in NUREG-0737 per util 820317 & 0503 responses to Generic Ltrs 82-05 & 82-10, respectively. Util proposed implementation schedule delays acceptable.
CRUTCHFIELD,D. Operating Reactors Branch 5. 83/03/14. COUNSIL,W.G. Connecticut Yankee Atomic Power Co. 3pp. 17657:001. 24X Fiche:50-000,83/03/14,8303220201.

--8303220209 Order confirming licensee commitments on post-TMI-related issues.Lists of licensee commitments on applicable NUREG-0737 requirements from Generic Ltrs 82-05 & 82-10 encl.
EISENHUT,D.G. Division of Licensing. 83/03/14. Connecticut Yankee Atomic Power Co. 8pp. 17657:004. 24X Fiche:50-000,83/03/14,8303220201.

--8303220255 Order confirming licensee commitments on post-TMI-related issues.Lists of licensee commitments on applicable NUREG-0737 requirements from Generic Ltrs 82-05 & 82-10 encl.
EISENHUT,D.G. Division of Licensing. 83/03/14. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 9pp. 17657:012. 24X Fiche:50-000,83/03/14,8303220255.

8303220133 Forwards addl info to resolve SEP integrated assessment open items,per 830308 meeting.Info modifies 821229 response to 820930 items.
COUNSIL,W.G. Connecticut Yankee Atomic Power Co. 83/03/15.
CRUTCHFIELD,D. Operating Reactors Branch 5. 21pp. 17649:225. 24X Fiche:50-213,83/03/15,8303220133.

8303290443 Informs that schedule for completion of qualification of electrical equipment will be submitted by 830520.Ninety-day responses requested in NRC 821213 ltr superseded by issuance of 10CFR50.49,final rule.
COUNSIL,W.G. Connecticut Yankee Atomic Power Co. COUNSIL,W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
COUNSIL,W.G. Northeast Utilities. 83/03/18. CLARK,R.A. Operating Reactors Branch 3. CRUTCHFIELD,D. Operating Reactors Branch 5. 2pp. 17725:350. 24X Fiche:50-000,83/03/18,8303290443.

8303300027 Responds to 830224 request for backfit costs,source,time of action & whether action resulted from new requirement.W/o encl.
DIRCKS,W.J. Office of the Executive Director for Operations. 83/03/18. ZERBE,J. Office of Policy Evaluations. 1p. 17751:166. 24X Fiche:50-000,83/03/18,8303300027.

--8303300032 Responds to 830224 request for assistance in determining source of backfits at facilities & assessment of costs. Tables encl provide approx time of action,source & whether action resulted from new requirement.W/o encl.
DIRCKS,W.J. Office of the Executive Director for Operations. 83/03/08. ZERBE,J. Office of Policy Evaluations. 1p. 17751:167. 24X Fiche:50-000,83/03/18,8303300027.

--8303300038 Requests assistance in identifying source & time period backfit costs.Response requested by 830315.
ZERBE,J. Office of Policy Evaluations. 83/02/24. DIRCKS,W. Office of the Executive Director for Operations. 4pp. 17751:169. 24X Fiche:50-000,83/03/18,8303300027.

8303290195 Forwards comments on 830128 draft generic ltr to PWR licensees addressing NUREG-0737 items scheduled for implementation after 811231.Basis for extension of response time to 120 or 150 days provided.
COUNSIL,W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL,W.G. Connecticut Yankee Atomic Power Co.
COUNSIL,W.G. Northeast Utilities. 83/03/24. EISENHUT,D.G. Division of Licensing. 5pp. 17722:251. 24X Fiche:50-000,83/03/24, 8303290195.

8303310311 Withdraws request for hearing re environ qualification of safety-related electrical equipment.Withdrawal based on interpretations of 10CFR50.49,final rule re qualification criteria & replacement equipment.
COUNSIL,W.G. Connecticut Yankee Atomic Power Co. COUNSIL,W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
COUNSIL,W.G. Northeast Utilities. 83/03/24. EISENHUT,D.G. Division of Licensing. 2pp. 17755:139. 24X Fiche:50-000,83/03/24, 8303310311.

8303310321 Responds to NRC 830119 ltr requesting condition be placed in OL to require implementation of secondary water chemistry program.Reasons why condition not appropriate listed.
COUNSIL,W.G. Connecticut Yankee Atomic Power Co. 83/03/24.
CRUTCHFIELD,D. Operating Reactors Branch 5. 2pp. 17755:045. 24X Fiche:50-213,83/03/24,8303310321.

## O. Inspection reports, IE Bulletins & correspondence.

8303040368 Responds to request to review IE Bulletin 82-04 re applicability of deficiencies in primary containment electrical penetration assemblies.No assemblies mfg by Bunker-Ramo in svc or planned for use at plants.
COUNSIL,W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL,W.G. Northeast Utilities. COUNSIL,W.G. Connecticut Yankee Atomic Power Co. 83/02/22. HAYNES,R.C. Region 1, Office of Director. 2pp. 17420:014. 24X Fiche:50-000,83/02/22, 8303040368.

8303140223 Forwards IE Insp Rept 50-213/83-02 on 830125-28 & notice of violation.
MARTIN,T.T. Division of Engineering & Technical Programs. 83/02/22.
COUNSIL,W.G. Connecticut Yankee Atomic Power Co. 2pp. 17544:131. 24X Fiche:50-213,83/02/22,8303140223.

--8303140225 Notice of violation from insp on 830125-28.
* Division of Engineering & Technical Programs. 83/02/22. 1p. 17544:133. 24X Fiche:50-213,83/02/22,8303140223.

--8303140229 IE Insp Rept 50-213/83-02 on 830125-28.Noncompliance noted: failure to perform audit per 10CFR50 App B re transportation packages since 790801.
CLEMONS,P., SHANBAKY,M. Region 1, Office of Director. 83/02/18. 4pp. 17544:134. 24X Fiche:50-213,83/02/22,8303140223.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche:50-000,83/02/25,8212060367.

8303240455 Forwards IE Insp Rept 50-213/83-01 on 830103-0206.No noncompliance noted.
STARGTECKI,R. Division of Project & Resident Programs. 83/03/01.
COUNSIL,W.G. Connecticut Yankee Atomic Power Co. 2pp. 17678:077. 24X Fiche:50-213,83/03/01,8303240455.

--8303240461 IE Insp Rept 50-213/83-01 on 830103-0206.No noncompliance noted.Major areas inspected:review of periodic & special repts,shift logs & operating records,site seismic monitoring & shipment of radioactive matl.
REBELOWSKI,T., BRIGGS,L. Region 1, Office of Director.
ELSASSER,T.C. Division of Project & Resident Programs. 83/02/25. 11pp. 17678:079. 24X Fiche:50-213,83/03/01,8303240455.

8303160456 Forwards IE Safeguards Insp Rept 50-213/83-04 on 830131-0204.No noncompliance noted.
MARTIN,T.T. Division of Engineering & Technical Programs. 83/03/02.
COUNSIL,W.G. Connecticut Yankee Atomic Power Co. 2pp. 17587:279. 24X Fiche:50-213,83/03/02,8303160456.

--8303160467 IE Safeguards Insp Rept 50-213/83-04 on 830131-0204.No noncompliance noted.Major areas inspected:physical barriers (protected & vital areas),security sys power supply, lighting,alarm station training & qualification plan.
DUNLOP,J.M., MADDEN,W.J., GODY,A.T. Region 1, Office of Director. 83/02/25. 4pp. 17587:281. 24X Fiche:50-213,83/03/02,8303160456.

8303180297 Responds to IE Bulletin 83-01 re failures of Westinghouse DB-type circuit breakers.Millstone Unit 2 does not use subj circuit breakers.Testing at Haddam Neck demonstrated no abnormal conditions present.
COUNSIL,W.G. Connecticut Yankee Atomic Power Co. COUNSIL,W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
COUNSIL,W.G. Northeast Utilities. 83/03/04. HAYNES,R.C. Region 1, Office of Director. 2pp. 17616:007. 24X Fiche:50-000,83/03/04, 8303180297.

8303240439 Forwards IE Insp Rept 50-213/83-06 on 830127 & notice of violation.
MARTIN,T.T. Division of Engineering & Technical Programs. 83/03/08.
COUNSIL,W.G. Connecticut Yankee Atomic Power Co. 2pp. 17679:025. 24X Fiche:50-213,83/03/08,8303240439.

--8303240443 Notice of violation from insp on 830127.
* Region 1, Office of Director. 83/03/08. 1p. 17679:027. 24X Fiche:50-213,83/03/08,8303240439.

--8303240449 IE Insp Rept 50-213/83-06 on 830127 Noncompliance noted: transfer of byproduct matl in form recipient not authorized to receive & delivery of shipment of licensed matl in improper packaging.
CLEMONS, P. ; SHANBAKY, M. Region 1, Office of Director. 83/03/04. 6pp. 17679:028. 24X Fiche: 50-213, 83/03/08, 8303240439.

8303240369 Forwards IE Insp Rept 50-213/83-03 on 830124-28 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/09. COUNSIL, W. G. Connecticut Yankee Atomic Power Co. 2pp. 17682:007. 24X Fiche: 50-213, 83/03/09, 8303240369.

--8303240371 Notice of violation from insp on 830124-28.
* Region 1, Office of Director. 83/03/09. 2pp. 17682:009. 24X Fiche: 50-213, 83/03/09, 8303240369.

--8303240373 IE Insp Rept 50-213/83-03 on 830124-28 Noncompliance noted: failure to adequately establish test of boric acid pumps.
SHAUB, E. T. ; BISSETT, P. H. Region 1, Office of Director. CAPHTON, D. L. Division of Engineering & Technical Programs. 83/03/08. 10pp. 17682:011. 24X Fiche: 50-213, 83/03/09, 8303240369.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 8301U3). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson S'd Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

R. Periodic operating reports & related correspondence

8303080018 Forwards monthly operating rept for Dec 1982.
GRAVES, R. H. Connecticut Yankee Atomic Power Co. 83/01/13. Division of Data Automation & Management Information. 1p. 17455:332. 24X Fiche: 50-213, 83/01/13, 8303080018.

--8303080022 Monthly operating rept for Dec 1982.
ELMS, A. Connecticut Yankee Atomic Power Co. 83/01/31. 9pp. 17455:333. 24X Fiche: 50-213, 83/01/13, 8303080018.

8303150524 Forwards monthly operating rept for Jan 1983.
GRAVES, R. H. Connecticut Yankee Atomic Power Co. 83/02/13. Office of Resource Management, Director. 1p. 17568:215. 24X Fiche: 50-213, 83/02/13, 8303150524.

--8303150525 Monthly operating rept for Jan 1983.
ELMS, A. Connecticut Yankee Atomic Power Co. 83/01/31. 9pp. 17568:216. 24X Fiche: 50-213, 83/02/13, 8303150524.

8303240407 Forwards "Haddam Neck Plant & Millstone Station Units 1 & 2 Annual Rept, 1982," containing summary of challenges to relief valves, per util 800610 commitment.
COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Connecticut Yankee Atomic Power Co. COUNSIL, W. G. Northeast Utilities. 83/03/01. HAYNES, R. C. Region 1, Office of Dirvctor. 1p. 17679:130. 24X Fiche: 50-000, 83/03/01, 8303240407.

--8303240408 "Haddam Neck Plant & Millstone Station Units 1 & 2 Annual Rept, 1982."
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). * Connecticut Yankee Atomic Power Co. * Northeast Utilities. 83/03/01. 183pp. 17679:131. 24X Fiche: 50-000, 83/03/01, 8303240407.

S. Reportable occurrences: LERs & related correspondence

8303030135 Forwards LER 83-004/03L-0.
GRAVES, R. H. Connecticut Yankee Atomic Power Co. 83/02/22. HAYNES, R. C. Region 1, Office of Director. 1p. 17412:349. 24X Fiche: 50-213, 83/02/22, 8303030135.

--8303030143 LER 83-004/03L-0 on 830126, during containment leak rate testing, five valves failed or contributed to exceeding acceptance criteria. Cause unknown. Investigation underway.
WARNER, M. E. Connecticut Yankee Atomic Power Co. 83/02/22. Region 1, Office of Director. 2pp. 17412:350. 24X Fiche: 50-213, 83/02/22, 8303030135.

8303210658 PNO-I-83-020 on 830315, during low power physics testing, "all rods out - just critical" boron concentration indicated variation of 70 ppm from predicted concentrations. Plant placed in cold shutdown for insp.
ELSASSER, Region 1, Office of Director. 83/03/17. 1p. 17636:049. 24X Fiche: 50-213, 83/03/17, 8303210658.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

D. NRC Draft/Final Environmental Statements; supplis & correspondence

8303280133 Forwards summary of conclusions section of FES for license conversion. Response provides status of action taken to comply w/license conditions.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/03/21. CRUTCHFIELD, D. Operating Reactors Branch 5. 15pp. 17706:322. 24X Fiche: 50-219, 83/03/21, 8303280133.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8303100107 Forwards NRR response to ACRS recommendations following 271st & 272nd meetings, per 821208 & 830107 memos.
GOODWIN, E. F. Technical Support Branch. 83/02/15. FRALEY, R. F. ACRS - Advisory Committee on Reactor Safeguards. 5pp. 17504:036. 24X Fiche: 50-000, 83/02/15, 8303100107.

--8212290442 Forwards follow-up list of requests made at 271st ACRS meetings on 821104-05, per decision to prepare summary of "Actions, Agreements, Assignments & Requests" after each meeting.
FRALEY, R. F. ACRS - Advisory Committee on Reactor Safeguards. 82/12/08. DIRCKS, W. J. Office of the Executive Director for Operations. 2pp. 17504:060. 24X Fiche: 50-219, 83/02/15, 8303100107.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303110101 Forwards methodology & results of evaluation of aircraft impact on plant, per SEP Topic III-4D, "Aircraft Hazards." Probability of aircraft strike on plant for all categories extremely low.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/03/04. CRUTCHFIELD, D. Operating Reactors Branch 5. 6pp. 17506:355. 24X Fiche: 50-219, 83/03/04, 8303110101.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303170285 Advises that util position on NUREG-0737, Item II.E.4.2, "Containment Isolation Dependability," remains same as stated in 820225 ltr. Any NRC proposed mods cannot be made until Cycle 11 refueling outage.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/03/10. CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 17606:078. 24X Fiche: 50-219, 83/03/10, 8303170285.

8303170294 Notifies that Capsule 2 of reactor vessel matl surveillance program will be removed from current Cycle 10 refueling outage to obtain info re matl properties, per SEP Topic V-6, "Reactor Vessel Integrity."
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/03/10
CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 17605:127. 24X
Fiche: 50-219. 83/03/10. 8303170294.

8303170145 Forwards order confirming commitments to implement post-TMI related items in NUREG-0737. Order based on util responses to Generic Ltrs 82-05 & 82-10.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/03/14. FIELDER, P. B. General Public Utilities - GPU Service Corp. 3pp. 17609:034. 24X
Fiche: 50-219. 83/03/14. 8303170145.

--8303170151 Order confirming licensee commitments on post-TMI related Items II. B. 2 & II. F. 1 from NUREG-0737.
EISENHUT, D. G. Division of Licensing. 83/03/14. General Public Utilities - GPU Service Corp. 10pp. 17609:037. 24X
Fiche: 50-219. 83/03/14. 8303170151.

8303220313 Forwards Rev 1 to Chapter 7 to response re environ qualification of electrical equipment. Rev justifies continued operation w/equipment w/o complete documentation qualification, per NRC 821130 ltr.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/03/16.
CRUTCHFIELD, D. Operating Reactors Branch 5. 24pp. 17648:031. 24X
Fiche: 50-219. 83/03/16. 8303220313.

8303250098 Forwards application for amend to License DPR-16, proposing Tech Spec Change Request 102, revising Section 6.5 to implement new safety review & audit program, adding new position to Figure 6.2.2(3) & editing three paragraphs.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/03/18.
CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 17692:341. 24X
Fiche: 50-219. 83/03/18. 8303250098.

--8303250104 Application for amend to License DPR-16, proposing Tech Spec Change Request 102 to revise Section 6 re administrative controls. Certificate of Svc & discussion of changes encl.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/03/18. 5pp. 17692:343. 24X Fiche: 50-219. 83/03/18. 8303250098.

--8303250108 Proposed Tech Spec Section 6, revising Section 6.5 to implement new safety review & audit program, adding new position to Figure 6.2.2(3) & editing Paragraphs 6.5.3.1(a) (b) & (c).
* General Public Utilities - GPU Service Corp. 83/03/18. 25pp. 17692:348. 24X Fiche: 50-219. 83/03/18. 8303250098.

8303290363 Informs that containment purge & vent valves will be replaced during Cycle 11 outage. Description of valve qualification program will be provided following installation.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/03/24.
CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 17716:192. 24X
Fiche: 50-219. 83/03/24. 8303290363.

9. Inspection reports, IE Bulletins & correspondence

8303010434 Forwards IE Insp Rept 50-219/83-02 on 830116-20. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/02/15.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 2pp. 17343:065. 24X Fiche: 50-219. 83/02/15. 8303010434.

--8303010440 IE Insp Rept 50-219/83-02 on 830116-20. No noncompliance noted. Major areas inspected: control of radioactive sources, leak test records, spent fuel pool inventory, personnel selection & external exposure control.
COLLINS, D. J., SHANBAKY, M. M. Division of Engineering & Technical Programs. 83/02/08. 6pp. 17343:067. 24X Fiche: 50-219. 83/02/15. 8303010434.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521:001. 24X Fiche: 50-000. 83/02/25. 8212060367.

8303040517 Completes response to IE Bulletin 82-03 re demonstration of intergranular stress corrosion cracking detection capability. Common decibel level provided for calibr & ultrasonic test procedure sensitivity increased.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/02/25.
HAYNES, R. C. Region 1, Office of Director. 1p. 17374:194. 24X
Fiche: 50-219. 83/02/25. 8305040517.

8303150372 Ack receipt of 830217 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/82-29.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/08.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 1p. 17561:145. 24X Fiche: 50-219. 83/03/08. 8303150372.

--8303150380 Responds to NRC 830118 ltr re violations noted in IE Insp Rept 50-219/82-29. Corrective actions memo issued on 821116 to all operating shifts requiring performance of all shift turnovers in strict accordance w/Procedure 106.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/02/17. STAROSTECKI, R. Division of Project & Resident Programs. 4pp. 17561:146. 24X Fiche: 50-219. 83/03/08. 8303150372.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000. 83/03/11. 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering.
Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000. 83/03/18. 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering.
Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000. 83/03/21. 8212060387.

R. Periodic operating reports & related correspondence

8303080341 Forwards monthly operating rept for Dec 1982.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/01/18.
Office of Resource Management, Director. 1p. 17453:201. 24X
Fiche: 50-219. 83/01/18. 8303080341.

--8303080347 Monthly operating rept for Dec 1982.
BARAN, R. General Public Utilities - GPU Service Corp. 83/01/06.
15pp. 17453:202. 24X Fiche: 50-219. 83/01/18. 8303080341.

8303150428 Forwards monthly operating rept for Jan 1983.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/02/16.
Division of Data Automation & Management Information. 1p. 17561:158. 24X Fiche: 50-219. 83/02/16. 8303150428.

--8303150431 Monthly operating rept for Jan 1983.
BARAN, R. General Public Utilities - GPU Service Corp. 83/02/03.
10pp. 17561:159. 24X Fiche: 50-219. 83/02/16. 8303150428.

8303040581 Forwards "Ecological Studies at Oyster Creek Nuclear Generating Station, Progress Rept for Sept 1981 - Aug 1982."
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/02/25.
HAYNES, R. C. Region 1, Office of Director. 1p. 17372:259. 24X
Fiche: 50-219. 83/02/25. 8303040581.

--8303040587 "Ecological Studies at Oyster Creek Nuclear Generating Station, Progress Rept for Sept 1981 - Aug 1982."
* Ecological Analysts, Inc. JCP-31-A. 83/02/28. 63pp. 17372:261. 24X Fiche: 50-219. 83/02/25. 8303040581.

8303240403 Forwards Battelle New England Marine Research Lab, "Study of Woodborer Populations in Relation to Oyster Creek Generating Station for 821121-830120," 31st quarter progress rept & corrected Table 2 from 30th quarterly rept.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/03/15.
HAYNES, R. C. Region 1, Office of Director. 2pp. 17679:314. 24X
Fiche: 50-219. 83/03/15. 8303240403.

--8303240405 "Study of Woodborer Populations in Relation to Oyster Creek Generating Station for 821121-830120," 31st quarter progress rept.
HILLMAN, R. E., NELMORE, C. I. Battelle New England Marine Research Laboratory. 15173. 83/02/28. 21pp. 17679:317. 24X
Fiche: 50-219. 83/03/15. 8303240403.

8303160303 Forwards "GPU Nuclear Corp Oyster Creek Nuclear Generating Station Effluent Release Rept, June-Dec 1982."
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/03/16.
HAYNES, R. C. Region 1, Office of Director. 1p. 17595:001. 24X
Fiche: 50-219. 83/03/16. 8303160303.

--8303160309 "GPU Nuclear Corp Oyster Creek Nuclear Generating Station Effluent Relase Rept, June-Dec 1982."
* General Public Utilities - GPU Service Corp. 83/03/16. 197pp. 17595:004. 24X Fiche: 50-219. 83/03/16. 8303160303.

S. Reportable occurrences, LERs & related correspondence

8302250327 Forwards ROs 83-1-1, 83-2-1 & 83-3-1.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/02/14.
HAYNES, R. C. Region 1, Office of Director. 1p. 17291:002. 24X
Fiche: 50-219, 83/02/14, 8302250327.

--8302250330 RO 83-1-1 on 830113, dilution pump 1-2 removed from svc. Caused by insufficient seal water flow. Long-term corrective action includes program designed to improve pump reliability.
* General Public Utilities - GPU Service Corp. 83/02/14. 2pp. 17291:003. 24X Fiche: 50-219, 83/02/14, 8302250327.

--8302250332 RO 83-2-1 on 830118, dilution pump 1-1 removed from svc due to steam around flex packing gland. Caused by wearing in of new packing. Long-term corrective actions include upgrading dilution pump seal.
* General Public Utilities - GPU Service Corp. 83/02/14. 2pp. 17291:005. 24X Fiche: 50-219, 83/02/14, 8302250327.

--8302250335 RO 83-3-1 on 830123, dilution pumps 1-2 & 1-3 tripped off. Caused by failed electrical terminations (stress cones). Terminations replaced.
* General Public Utilities - GPU Service Corp. 83/02/14. 3pp. 17291:007. 24X Fiche: 50-219, 83/02/14, 8302250327.

8303140383 Forwards LER 83-001/03L-0. Detailed event analysis encl.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/02/25.
HAYNES, R. C. Region 1, Office of Director. 4pp. 17542:078. 24X
Fiche: 50-219, 83/02/25, 8303140383.

--8303140384 LER 83-001/03L-0 on 830123, chemical waste storage tank B overflowed into surrounding concrete vault causing unmonitored release outside radwaste bldg. Caused by malfunction of level instrumentation.
HAGER, C. General Public Utilities - GPU Service Corp. 83/02/25.
Region 1, Office of Director. 1p. 17542:082. 24X
Fiche: 50-219, 83/02/25, 8303140383.

8303160197 Forwards LER 83-005/03L-0. Detailed event analysis encl.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/03/04.
HAYNES, R. C. Region 1, Office of Director. 3pp. 17596:277. 24X
Fiche: 50-219, 83/03/04, 8303160197.

--8303160209 LER 83-005/03L-0 on 830126, while performing containment spray sys automatic actuation test, high drywell pressure switches 1P15A, B & C tripped at value greater than Tech Spec limit. Cause not determined. Pressure switches readjusted.
SOBEL, C. P. General Public Utilities - GPU Service Corp. 83/03/04.
Region 1, Office of Director. 1p. 17596:280. 24X
Fiche: 50-219, 83/03/04, 8303160197.

8303160214 Forwards LER 83-002/03L-0. Detailed event analysis encl.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/03/04.
HAYNES, R. C. Region 1, Office of Director. 3pp. 17596:307. 24X
Fiche: 50-219, 83/03/04, 8303160214.

--8303160222 LER 83-002/03L-0 on 830123, startup banks removed from svc due to dilution plant main breaker cable termination failure. Cause under investigation. Dilution pump power feed terminations replaced.
DICKENSON, A. C. General Public Utilities - GPU Service Corp.
83/03/04. Region 1, Office of Director. 1p. 17596:310. 24X
Fiche: 50-219, 83/03/04, 8303160214.

8303160225 Forwards LER 83-006/03L-0. Detailed event analysis encl.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/03/04.
HAYNES, R. C. Region 1, Office of Director. 3pp. 17596:342. 24X
Fiche: 50-219, 83/03/04, 8303160225.

--8303160232 LER 83-006/03L-0 on 830206, all automatic valves not lined up properly during execution of standby gas treatment sys 10 h operability test. Caused by condensation in Fan 1-9 low flow sensing lines. Lines cleaned.
MURDOCK, R. J. General Public Utilities - GPU Service Corp.
83/03/04. Region 1, Office of Director. 1p. 17596:345. 24X
Fiche: 50-219, 83/03/04, 8303160225.

8303250090 Forwards LER 83-009/01T-0. Detailed event analysis encl.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/03/15.
HAYNES, R. C. Region 1, Office of Director. 3pp. 17693:069. 24X
Fiche: 50-219, 83/03/15, 8303250090.

--8303250094 LER 83-009/01T-0 on 830222, during local leak rate testing, MSIVs NS04A & NS04B failed to meet acceptance criteria. Caused by leakage through valve packing. MSIV packing replacement planned for current refueling/maint outage.
HUTKO, K. General Public Utilities - GPU Service Corp. 83/03/15.
Region 1, Office of Director. 1p. 17693:072. 24X
Fiche: 50-219, 83/03/15, 8303250090.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8303170213 Forwards safety evaluation re proposed mods & alternate safe shutdown capability to comply w/App R requirements. Mods & alternate safe shutdown capability acceptable.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/03. RHODE, G. K.
Niagara Mohawk Power Corp. 2pp. 17624:342. 24X
Fiche: 50-220, 83/03/03, 8303170213.

--8303170216 Safety evaluation supporting 10CFR50, App R proposed mods & alternate safe shutdown capability.
* Office of Nuclear Reactor Regulation, Director. 83/03/03. 13pp. 17624:344. 24X Fiche: 50-220, 83/03/03, 8303170213.

8303180341 Discusses structural features of alternate emergency operations facility - Niagara Mohawk Svc Ctr in Town of Volney, Oswego County, per NRC request. Bldg normally used as electrical maint svc ctr.
MANGAN, C. V. Niagara Mohawk Power Corp. 83/03/11. VASSALLO, D. B.
Operating Reactors Branch 2. 1p. 17521:036. 24X
Fiche: 50-220, 83/03/11, 8303180341.

P. Operating license stage documents & correspondence

8303160151 Responds to NRC 821220 ltr requesting addl info re environ qualification of safety-related equipment. Info will be provided by 830301.
MANGAN, C. V. Niagara Mohawk Power Corp. 83/01/24. VASSALLO, D. B.
Operating Reactors Branch 2. 1p. 17596:361. 24X
Fiche: 50-220, 83/01/24, 8303160151.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303070099 Forwards draft Tech Specs consisting of STS per NUREG-0473, Rev 2 & NUREG-0473, Rev 3 & offsite dose calculation manual. Tech Spec changes consist of alterations & deletions re gaseous effluents & instrument surveillance.
MANGAN, C. V. Niagara Mohawk Power Corp. 83/03/01. VASSALLO, D. B.
Operating Reactors Branch 2. 3pp. 17431:001. 24X
Fiche: 50-220, 83/03/01, 8303070099.

--8303070104 Proposed Tech Spec changes consisting of alterations & deletions of definitions & required gaseous effluents & instrument surveillance making proposed changes compatible w/current App A specs.
* Niagara Mohawk Power Corp. 83/03/01. 89pp. 17431:005. 24X
Fiche: 50-220, 83/03/01, 8303070099.

--8303070105 Offsite dose calculation manual.
* Niagara Mohawk Power Corp. 83/03/01. 56pp. 17431:091. 24X
Fiche: 50-220, 83/03/01, 8303070099.

8303090145 Informs that 30 & 90-day repts re environ equipment qualification will be provided by 830415 & 830520, respectively.
MANGAN, C. V. Niagara Mohawk Power Corp. 83/03/01. VASSALLO, D. B.
Operating Reactors Branch 2. 1p. 17470:351. 24X
Fiche: 50-220, 83/03/01, 8303090145.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

# DOCKETED ITEMS

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp. 17660.176 24X
Fiche 50-000, 83/03/07, 8303040005.

8303110288 Forwards responses to NRC 830104 plant-specific questions re BWR Owners Group NEDE-24988-P, "Analysis of Generic BWR Safety/Relief Valve Operability Test Results," per TMI Action Plan Item II.D.1.
MANGAN, C. V. Niagara Mohawk Power Corp. 83/03/07 VASSALLO, D. B. Operating Reactors Branch 2. 16pp. 17517.269 24X
Fiche 50-220, 83/03/07, 8303110288.

8303150507 Advises that some of original assumptions for TMI Action Item III.D.3.4, "Control Room Habitability," may have been nonconservative Assumptions currently under re-evaluation.
MANGAN, C. V. Niagara Mohawk Power Corp. 83/03/11. VASSALLO, D. B. Operating Reactors Branch 2. 1p. 17560.112 24X
Fiche 50-220, 83/03/11, 8303150507.

8303290021 Forwards Amend 51 to License DPR-63 & notice of issuance & availability. Amend deletes App B ETS re nonradiological water quality-related requirements.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/11. RHODE, G. K. Niagara Mohawk Power Corp. 3pp. 17729.317 24X
Fiche 50-220, 83/03/11, 8303290021.

--8303290030 Amend 51 to License DPR-63, deleting App B ETS nonradiological water quality-related requirements.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/11. 44pp. 17729.320 24X Fiche 50-220, 83/03/11, 8303290021.

--8303290034 Notice of issuance & availability of Amend 51 to License DPR-63.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/11. 2pp. 17730.001 24X Fiche 50-220, 83/03/11, 8303290021.

8303290211 Forwards order confirming commitment to implement post-TMI-related items set forth in NUREG-0737 for which NRC requested completion on or after 810701. Review may identify alterations to util implementation schedule.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/14. RHODE, G. K. Niagara Mohawk Power Corp. 3pp. 17729.164 24X
Fiche 50-220, 83/03/14, 8303290211.

--8303290218 Order confirming licensee commitment to implement post-TMI-related items set forth in NUREG-0737. Hearing may be requested within 20 days of publication of order.
PURPLE, R. A. Division of Licensing. 83/03/14. Niagara Mohawk Power Corp. 9pp. 17729.167 24X Fiche 50-220, 83/03/14, 8303290211.

8303220072 Advises of high carbon content in longitudinal welds of branch piping to be welded into recirculation sys. Intergranular stress corrosion cracking may result. Inlay of corrosion resistant cladding added to weld.
MANGAN, C. V. Niagara Mohawk Power Corp. 83/03/15. VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 17652.196 24X
Fiche 50-220, 83/03/15, 8303220072.

8303300041 Forwards analysis of reactor bldg wall crack, supplementing 801215 evaluation. Reactor bldg structural integrity maintained for all postulated design basis events.
MANGAN, C. V. Niagara Mohawk Power Corp. 83/03/25. VASSALLO, D. B. Operating Reactors Branch 2. 9pp. 17731.191 24X
Fiche 50-220, 83/03/25, 8303300041.

8303300613 Informs of resolution of TMI Item II.E.4.1, "Dedicated Hydrogen Penetrations," & acceptance of NUREG-0578 item re hydrogen control.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/28. RHODE, G. K. Niagara Mohawk Power Corp. 2pp. 17766.360 24X
Fiche 50-220, 83/03/28, 8303300613.

## G. Inspection reports, IE Bulletins & correspondence

8303100068 Responds to FOIA request for NUREG-0313, results of stress ratio index tests on welds & info re intergranular stress corrosion cracking & performance of weld overlay patches. Forwards App A documents. App B documents available in PDR.
FELTON, J. M. Division of Rules and Records. 83/02/15. VAN ALLEN, S. E. Northern Sun Alliance. 4pp. 17494.148 24X
Fiche 50-000, 83/02/15, 8303100068.

--8303100089 Forwards updated status of indications found in recirculation sys piping at facility.
HAYNES, R. C. Region 1, Office of Director. 82/08/12. O'REILLY, J. P. Region 2, Office of Director. KEPPLER, J. G. Region 3, Office of Director. COLLINS, J. T. Region 4, Office of Director. 1p. 17494.278 24X Fiche 50-000, 83/02/15, 8303100068.

--8303100102 Discusses degradation & cracking in thick-wall large diameter stainless steel piping at BWR plants per IE Bulletin 82-03 & NRR generic responsibilities. Guidelines for review of pipe crack problem listed.
DIRCKS, W. J. Office of the Executive Director for Operations. 82/12/08. Region 1, Office of Director. 4pp. 17494.326 24X
Fiche 50-000, 83/02/15, 8303100068.

8303030401 Forwards IE Insp Rept 50-220/83-01 on 830101-31. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs. 83/02/16. RHODE, G. K. Niagara Mohawk Power Corp. 2pp. 17410.127 24X
Fiche 50-220, 83/02/16, 8303030401.

--8303030408 IE Insp Rept 50-220/83-01 on 830101-31. No noncompliance noted. Major areas inspected: licensee action on previous insp findings, plant tours, observation of physical security, plant maint, LERs, IE bulletins & circulars.
HUDSON, S. D., ZIMMERMAN, R. P., KISTER, H. B. Division of Project & Resident Programs. 83/02/15. 11pp. 17410.129 24X
Fiche 50-220, 83/02/16, 8303030401.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521.001 24X Fiche 50-000, 83/02/25, 8212060367.

8303090444 Notification of 830228 Meeting 83-14 w/licensee in King of Prussia, PA to discuss issues re emergency diesel generator investigation.
CAPHTON, D. L. Region 1, Office of Director. 83/02/25. Region 1, Office of Director. 1p. 17483.179 24X Fiche 50-220, 83/02/25, 8303090444.

8303080004 Confirms plan to begin independent verification insp of recent const using NDE van & contractor technicians beginning 830323. Const activities & matls will be sampled through NDE as suppl to existing ongoing insp efforts.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/02. RHODE, G. K. Niagara Mohawk Power Corp. 2pp. 17454.347 24X
Fiche 50-220, 83/03/02, 8303080004.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611.070 24X Fiche 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774.352 24X Fiche 50-000, 83/03/21, 8212060387.

8303290444 Informs that second vessel matl surveillance sample capsule will be used to perform insps required at one quarter of vessel svc life since first capsule lost. Remaining capsule will be removed per Section 4.2.2 of Tech Specs.
MANGAN, C. V. Niagara Mohawk Power Corp. 83/03/23. VASSALLO, D. B. Operating Reactors Branch 2. 1p. 17725.349 24X
Fiche 50-220, 83/03/23, 8303290444.

## R. Periodic operating reports & related correspondence

8303160136 Forwards "Quarterly Task Person-Rem Rept, Jul-Sept 1982."
MANGAN, C. V. Niagara Mohawk Power Corp. 82/10/29. EISENHUT, D. G. Division of Licensing. 1p. 17597.043 24X Fiche 50-220, 82/10/29, 8303160136.

--8303160143 "Quarterly Task Person-Rem Rept, Jul-Sept 1982."
* Niagara Mohawk Power Corp. 82/10/29. 25pp. 17597.044 24X
Fiche 50-220, 82/10/29, 8303160136.

8303110026 Forwards "Radioactive Effluent Release Semiannual Rept, Jul-Dec 1982."
LEMPGES, T. E. Niagara Mohawk Power Corp. 83/03/01. HAYNES, R. C. Region 1, Office of Director. 1p. 17520.002 24X
Fiche 50-220, 83/03/01, 8303110026.

--8303110030 "Radioactive Effluent Release Semiannual Rept, Jul-Dec 1982."
* Niagara Mohawk Power Corp. 83/03/01. 50pp. 17520.003 24X
Fiche 50-220, 83/03/01, 8303110026.

8303170210 Forwards monthly operating rept for Feb 1983.
LEMPGES, T. E. Niagara Mohawk Power Corp. 83/03/07 Director's Office, Office of Inspection and Enforcement. 1p. 17606:072. 24X Fiche: 50-220, 83/03/07, 8303170210.

--8303170212 Monthly operating rept for Feb 1983.
ROMAN, T. W. Niagara Mohawk Power Corp. 83/03/07. 4pp. 17606:073. 24X Fiche: 50-220, 83/03/07, 8303170210.

B. Reportable occurrences, LERs & related correspondence

8303010670 Forwards LER 83-001/04L-0.
LEMPGES, T. E. Niagara Mohawk Power Corp. 83/02/18. HAYNES, R. C. Region 1, Office of Director. 1p. 17336:181. 24X Fiche: 50-220, 83/02/18, 8303010670.

--8303010676 LER 83-001/04L-0 on 830122, while performing environ surveillance testing, 30 ft wind direction sensor alignment azimuth indicator found high. Caused by improperly installed mounting plate. Sensor readjusted.
BURGMEIER, M. J. Niagara Mohawk Power Corp. 83/02/18. Region 1, Office of Director. 1p. 17336:182. 24X Fiche: 50-220, 83/02/18, 8303010670.

8303180414 Forwards LER 83-002/04L-0.
LEMPGES, T. E. Niagara Mohawk Power Corp. 83/03/11. HAYNES, R. C. Region 1, Office of Director. 1p. 17622:036. 24X Fiche: 50-220, 83/03/11, 8303180414.

--8303180416 LER 83-002/04L-0 on 821018, while analyzing quarterly canal water samples, tritium concentration in inlet sample was 39.2 times control result. Caused by normal intake & discharge tunnels operating in reverse flow mode.
BURGMEIER, M. J. Niagara Mohawk Power Corp. 83/02/17. Region 1, Office of Director. 4pp. 17622:037. 24X Fiche: 50-220, 83/03/11, 8303180414.

8303210710 PND-1-83-018 on 830315, while filling reactor water cleanup sys (RWCU), both channels of reactor bldg ventilation monitor alarmed. Caused by overflow of RWCU filter sludge tank. Standby gas treatment sys started & bldg evacuated.
KISTER, GALLO Region 1, Office of Director. 83/03/15. 1p. 17635:153. 24X Fiche: 50-220, 83/03/15, 8303210710.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-224 UNIV. OF CALIFORNIA RESEARCH REACTOR

R. Periodic operating reports & related correspondence

8303140337 Forwards "Berkeley Research Reactor Annual Rept of Operations."
LIM, T. H. California, Univ. of, Berkeley. 83/03/08. MILLER, J. A. Standardization & Special Projects Branch. 1p. 17534:217. 24X Fiche: 50-224, 83/03/08, 8303140337.

--8303140339 "Berkeley Research Reactor Annual Rept of Operations for 1982."
LIM, T. H. California, Univ. of, Berkeley. 83/03/08. 11pp. 17534:218. 24X Fiche: 50-224, 83/03/08, 8303140337.

DOCKET 50-225 RPI CRITICAL EXPERIMENT

R. Periodic operating reports & related correspondence

8303240483 Submits "Annual Rept of Tests & Experiments, Mar 1982 - Feb 1983."
WICKS, F. E., HARRIS, D. P. Rensselaer Polytechnic Inst. 83/03/01. Division of Licensing. 2pp. 17678:022. 24X Fiche: 50-225, 83/03/01, 8303240483.

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8303010595 Ack receipt of 830124 ltr identifying 1983 dates for emergency preparedness exercises within State of IL. Dates determined to be within required exercise frequency.
HIND, J. A. Region 3, Office of Director. 83/02/24. JONES, E. E. Illinois, State of. 2pp. 17336:208. 24X Fiche: 50-000, 83/02/24, 8303010595.

--8303010618 Submits 1983 dates scheduled for emergency preparedness exercises for facilities within State of IL.
JONES, E. E. Illinois, State of. 83/01/24. KEPPLER, J. Region 3, Office of Director. 2pp. 17336:210. 24X Fiche: 50-000, 83/02/24, 8303010595.

8303100350 Errata to proposed amend to License DPR-19 Tech Specs re review of hydrogen injection sys design. Sys complies w/Branch Technical Position CMEB 9.5-1, "Guidelines for Fire Protection for Nuclear Plants."
SCHROEDER, C. Commonwealth Edison Co. 83/03/07. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17492:011. 24X Fiche: 50-237, 83/03/07, 8303100350.

8303240587 Forwards IE Insp Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24 on 821203-05. No noncompliance noted. Summary of significant deficiencies encl.
KEPPLER, J. G. Region 3, Office of Director. 83/03/11. REED, C. Commonwealth Edison Co. 3pp. 17683:087. 24X Fiche: 50-010, 83/03/11, 8303240587.

--8303240597 IE Insp Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24 on 821203-05. No noncompliance noted. Major areas inspected: generating station emergency plan alert caused by flooding conditions.
TONGUE, T. M., STASEK, S., GULDEMOND, W. G. Region 3, Office of Director. 83/03/02. 12pp. 17683:090. 24X Fiche: 50-010, 83/03/11, 8303240587.

8303230143 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/16. Document Management Branch. 1p. 17687:120. 24X Fiche: 50-010, 83/03/16, 8303230143.

--8303230149 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 500-6, "Quarterly Operational Support Ctr Inventory (Primary Responsibility - Generating Station Emergency Plan Coordinator)."
SCOTT, D. J. Commonwealth Edison Co. 83/03/05. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17687:121. 24X Fiche: 50-010, 83/03/16, 8303230143.

--8303230155 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 500-6, "Quarterly Operational Support Ctr Inventory (Primary Responsibility - Generating Station Emergency Plan Coordinator)." W/revised index.
* Commonwealth Edison Co. 83/03/02. 5pp. 17687:122. 24X Fiche: 50-010, 83/03/16, 8303230143.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director. 83/03/22. Commonwealth Edison Co. 2pp. 24X Fiche: 50-000, 83/03/22, 8303240440.

8303310124 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/25. Document Management Branch. 1p. 17775:184. 24X Fiche: 50-000, 83/03/25, 8303310124.

--8303310130 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure EQ-1, "Coordination of Environs Group Activities by Environs Director."
* Commonwealth Edison Co. 83/03/17. Director's Office, Office of Inspection and Enforcement. 1p. 17775:185. 24X Fiche: 50-000, 83/03/25, 8303310124.

--8303310146 Public version of Rev 3 to Emergency Plan Implementing Procedure EQ-1, "Coordination of Environs Group Activities by Environs Director."
PAJOWSKI, J. E. Commonwealth Edison Co. 83/03/08. 87pp. 17775:186. 24X Fiche: 50-000, 83/03/25, 8303310124.

8303300532 Releases public version of request for return of listed controlled copies of emergency plan.
FELTON, J. M. Division of Rules and Records. 83/03/28. Document Management Branch. 1p. 17763:178. 24X Fiche: 50-000, 83/03/28, 8303300532.

# DOCKETED ITEMS

--8303300561 Submits public version of request for return of listed controlled copies of emergency plan.
FLESSNER,R A Commonwealth Edison Co 83/03/15 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 17763:179 24X Fiche 50-000,83/03/28,8303300532

H. General correspondence

8303030528 Informs that DL Farrar has replaced LO DelGeorge as Director of Nuclear Licensing for util Rev of current NRC distribution list requested.
FARRAR,D L Commonwealth Edison Co 83/02/02 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 17409:048 24X Fiche 50-000,83/02/02,8303030529

I. Financial information

8303070135 Forwards Annual Financiel Rept 1982.
BRESEMANN,R W Commonwealth Edison Co 83/02/28 Division of Licensing 1p 17433:001 24X Fiche 50-000,83/02/28,8303070135

--8303070151 Annual Financial Rept 1982.
O'CONNOR,J J Commonwealth Edison Co 83/02/03 13pp 17433:002 24X Fiche 50-000,83/02/28,8303070135

J. Insurance & indemnity information

8303240226 Forwards summons & complaint re overexposure of C Rexroat on 810305 while working as millwright for Lindblad Const Co at facility Medical exam following exposure failed to disclose injury.
HARWARD,J E American Nuclear Insurers 83/03/11 SALTZMAN,J Assistant Director for State & Licensee Relations 6pp 17682:188 24X Fiche 50-237,83/03/11,8303240226

O. Advisory Committee on Reactor Safeguards reports & correspondence

8303160637 Summary of ACRS Subcommittee on SEP 821130 meeting in Washington,DC re SEP review for facilities.
* ACRS - Advisory Committee on Reactor Safeguards 83/01/04 ACRS - Advisory Committee on Reactor Safeguards 16pp 17603:272 24X Fiche 50-000,83/01/04,8303160637

8303100107 Forwards NRR response to ACRS recommendations following 271st & 272nd meetings, per 821208 & 830107 memos.
GOODWIN,E F Technical Support Branch 83/02/15 FRALEY,R F ACRS - Advisory Committee on Reactor Safeguards 5pp 17504:036 24X Fiche 50-000,83/02/15,8303100107

--8301180041 Forwards list of requests made at 272nd ACRS meeting on 821209-11 per agreement to provide summary of actions, agreements, assignments & requests made at each full ACRS meeting.
FRALEY,R F ACRS - Advisory Committee on Reactor Safeguards 83/01/05 DIRCKS,W J Office of the Executive Director for Operations 4pp 17504:041 24X Fiche 50-000,83/02/15,8303100107

P. Operating license stage documents & correspondence

8302040188 Summary of 830124 meeting w/util & Exxon in Bethesda,MD re local stability analysis & other issues connected w/proposed use of lead assemblies in Cycle 9 reload core.
GILBERT,R A Operating Reactors Branch 5 83/01/31 Operating Reactors Branch 5 5pp 17020:298 24X Fiche 50-237,83/01/31,8302040188

8303080401 Forwards suppl to proposed amend to App A Tech Spec to support operation w/fuel supplied by Exxon, per 830124 request. Draft local stability test & cycle monitoring program encl. Proprietary analysis withheld (ref 10CFR2.790).
RYBAK,B Commonwealth Edison Co 83/02/24 DENTON,H R Office of Nuclear Reactor Regulation, Director 16pp 17454:258 24X Fiche 50-237,83/02/24,8303080401

8303090709 INTEGRATED SAFETY ASSESSMENT SYSTEMATIC EVALUATION PROGRAM, DRESDEN NUCLEAR POWER STATION UNIT 2 Docket No. 50-237. (Commonwealth Edison Company)
* Division of Licensing NUREG-0823 83/02/28 590pp 17478:003 24X Fiche 50-237,83/02/28,8303090709

8303080247 Submits outline for repair program for 28-inch diameter furance sensitized safe ends. Topical repts re crack growth analysis & hydrogen injection encl. Repts withheld (ref 10CFR2.790).
RYBAK,B Commonwealth Edison Co 83/03/01 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 17446:348 24X Fiche 50-237,83/03/01,8303080247

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT,D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700:303 24X Fiche 50-000,83/03/02,8303020321

8303070149 Summary of 830208 meeting w/util, GE, EPRI & ANL in Bethesda, MD re issues relating to 1-inch crack discovered by NDT in 28-inch B recirculation suction line safe-end to elbow piping. Viewgraphs encl.
GILBERT,R A Operating Reactors Branch 5 83/03/02 Operating Reactors Branch 5 31pp 17433:123 24X Fiche 50-237,83/03/02,8303070149

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER,J G Region 3, Office of Director 83/03/03 Commonwealth Edison Co 2pp 17492:014 24X Fiche 50-000,83/03/03,8303100364

8303110246 Forwards Rev 23 to CE-1-A, "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments.
SWARTZ,E D Commonwealth Edison Co 83/03/04 HAASS,W F Quality Assurance Branch 1p 17515:357 24X Fiche 50-000,83/03/04,8303110246

--8303110279 Rev 23 to "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments.
SHEWSKI,W J Commonwealth Edison Co CE-1-A R23 83/03/07 5pp 17515:358 24X Fiche 50-000,83/03/04,8303110246

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT,D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 51pp 17660:176 24X Fiche 50-000,83/03/07,8303040005

8303100350 Errata to proposed amend to License DPR-19. Tech Specs re review of hydrogen injection sys design. Sys complies w/Branch Technical Position CMEB 9.5-1, "Guidelines for Fire Protection for Nuclear Plants."
SCHROEDER,C Commonwealth Edison Co 83/03/07 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 17492:011 24X Fiche 50-237,83/03/07,8303100350

8303150377 Suppl to 821212 application for amend to License DPR-19, revising core loading plan by relocating position of one GE bundle.
RYBAK,B Commonwealth Edison Co 83/03/10 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 17562:032 24X Fiche 50-237,83/03/10,8303150377

--8303150383 Proposed Tech Spec Figure 4.2, revising core loading plan by relocating position of one GE bundle.
* Commonwealth Edison Co 83/03/10 1p 17562:034 24X Fiche 50-237,83/03/10,8303150377

8303170487 Documents acceptance of imposed min critical power ratio limits in proposed amend to App A Tech Spec to support operation w/BxBR fuel supplied by Exxon Nuclear Co.
RYBAK,B Commonwealth Edison Co 83/03/11 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 17610:121 24X Fiche 50-237,83/03/11,8303170487

8303220362 Forwards order confirming licensee commitments on post-TMI-related issues (Generic Ltrs 82-05 & 82-10).
CRUTCHFIELD,D Operating Reactors Branch 5 83/03/14 FARRAR,D Commonwealth Edison Co 3pp 17656:004 24X Fiche 50-237,83/03/14,8303220362

--8303220367 Order confirming licensee commitmnt on post-TMI-related issues.
EISENHUT,D G Division of Licensing 83/03/14 Commonwealth Edison Co .Opp 17656:007 24X Fiche 50-237,83/03/14,8303220362

8303170064 Forwards request for addl info re IE Bulletin 80-01 & NUREG-0737, Item II.K.3.28, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves." Response due by 830512.
CRUTCHFIELD,D Operating Reactors Branch 5 83/03/16 FARRAR,D L Commonwealth Edison Co 4pp 17609:098 24X Fiche 50-000,83/03/16,8303170064

8303280268 Forwards requests for addl info re responses to draft integrated plant safety assessment rept (NUREG-0823), Sections 4.5.4 & 4.7.4 on tornado missiles & pipe break inside containment, respectively. Response due in 30 days. CRUTCHFIELD, D. Operating Reactors Branch 5. 83/03/16. FARRAR, D L. Commonwealth Edison Co. 5pp. 17706:284. 24X Fiche 50-237. 83/03/16. 8303260268.

8303220068 Confirmatory action ltr re mechanical snubber damage inside drywell. Util will test, examine, visually inspect, repair, replace or modify all snubbers before placing unit in power operation. Util commitments based on 830314 telcon. KEPPLER, J G. Region 3, Office of Director. 83/03/17. REED, C. Commonwealth Edison Co. 2pp. 17652:191. 24X Fiche 50-237. 83/03/17. 8303220068.

8303240184 Forwards proprietary NEDE-30081, "Evaluation of Crack Indications in Recirculation Riser Elbow Welds" & repair program for recirculation risers. Flood drain leakage program listed. Proprietary rept withheld (ref 10CFR2.790). RYBAK, B. Commonwealth Edison Co. 83/03/18. DENTON, H R. Office of Nuclear Reactor Regulation, Director. 2pp. 17724:046. 24X Fiche. 50-237. 83/03/18. 8303240184.

8303240184 Forwards proprietary NEDE-30081, "Evaluation of Crack Indications in Recirculation Riser Elbow Welds" & repair program for recirculation risers. Flood drain leakage program listed. Proprietary rept withheld (ref 10CFR2.790). RYBAK, B. Commonwealth Edison Co. 83/03/18. DENTON, H R. Office of Nuclear Reactor Regulation, Director. 2pp. 17724:046. 24X Fiche. 50-237. 83/03/18. 8303240184.

--8303290567 Rev 4 to COM-52-003, "Repair Program for Recirculation Risers." SMITH, J F., GAVULA, J J., HORLEY, E C. NUTECH Engineers, Inc. 83/03/10. 11pp. 17724:052. 24X Fiche 50-237. 83/03/18. 8303240184.

8303280150 Forwards safety evaluation of NUREG-0737, Item II.B.2.2, "Design Review of Plant Shielding-Access to Vital Areas." Mods completed & acceptable. NORELIUS, C E. Division of Project & Resident Programs. 83/03/24. EISENHUT, D G. Division of Licensing. 2pp. 17706:339. 24X Fiche. 50-237. 83/03/24. 8303280150.

8303280270 Requests that petition for hearing on environ qualification of safety-related electrical equipment be withdrawn based on listed interpretations. Significant improvements in final rule 10CFR50.49 obviate hearings. STEPTOE, P P. Isham, Lincoln & Beale. STEPTOE, P P. Commonwealth Edison Co. 83/03/24. EISENHUT, D G. Division of Licensing. 2pp. 17706:289. 24X Fiche 50-000. 83/03/24. 8303280270.

G. Inspection reports, IE Bulletins & correspondence

8303030439 Forwards IE Insp Repts 50-010/82-22, 50-237/82-31 & 50-249/82-32 on 821202-830103 & 06. No noncompliance noted. STREETER, J F. Division of Project & Resident Programs. 83/02/16. REED, C. Commonwealth Edison Co. 2pp. 17410:086. 24X Fiche. 50-010. 83/02/16. 8303030439.

--8303030446 IE Insp Repts 50-010/82-22, 50-237/82-31 & 50-249/82-32 on 821202-830103 & 06. No noncompliance noted. Major areas inspected: licensee action on previous insp findings, headquarters request, operational safety & maint. TONGUE, T. M., JORDAN, M. J., STASEK, S. Division of Project & Resident Programs. 83/02/15. 13pp. 17410:088. 24X Fiche. 50-010. 83/02/16. 8303030439.

8303220112 Forwards IE Insp Rept 50-237/82-22 on 821004-1208. KEPPLER, J. G. Region 3, Office of Director. 83/02/16. O'CONNOR, J. J. Commonwealth Edison Co. 2pp. 17649:279. 24X Fiche 50-237. 83/02/16. 8303220112.

--8303220116 IE Insp Rept 50-237/82-22 on 821004-1208. Noncompliance noted: failure to maintain primary containment integrity & failure to make appropriate notifications. TONGUE, T. M., STASEK, S., WALKER, R. D. Region 3, Office of Director. 83/02/15. 5pp. 17649:281. 24X Fiche. 50-237. 83/02/16. 8303220112.

8303240368 Forwards IE Insp Repts 50-237/82-20, 50-254/82-16, 50-249/82-21 & 50-265/82-10 on 820816-1103. KEPPLER, J. G. Region 3, Office of Director. 82/02/16. O'CONNOR, J. J. Commonwealth Edison Co. 2pp. 17682:021. 24X Fiche 50-000. 83/02/16. 8303240368.

--8303240372 IE Insp Repts 50-237/82-20, 50-249/82-21, 50-254/82-16 & 50-265/82-10 on 820816-1103. Noncompliance noted: failure to control distribution of supplemental safety classification lists & to control parts not conforming to requirements. CHRISSOTIMOS, N., DUPONT, S. G., TONGUE, T. M. Region 3, Office of Director. 83/02/15. 8pp. 17682:023. 24X Fiche. 50-000. 83/02/16. 8303240368.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl. DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche 50-000. 83/02/25. 8212060367.

8303170532 Forwards IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al. on 830126. No noncompliance noted. DAVIS, A B. Region 3, Office of Director. 83/02/25. REED, C. Commonwealth Edison Co. 2pp. 17610:143. 24X Fiche 50-000. 83/02/25. 8303170532.

--8303170557 IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al. on 830126. No noncompliance noted. Major areas discussed: proposed guidelines util personnel should use for providing info to Region III inspectors. GULDEMOND, W G., WALKER, R D. Division of Project & Resident Programs. 83/02/15. 4pp. 17610:145. 24X Fiche 50-000. 83/02/25. 8303170532.

8303180391 Forwards IE Insp Repts 50-010/83-02, 50-237/83-02 & 50-249/83-02 on 830112-14. No noncompliance noted. LITTLE, W S. Region 3, Office of Director. 83/02/25. REED, C. Commonwealth Edison Co. 2pp. 17621:351. 24X Fiche 50-010. 83/02/25. 8303180391.

--8303180396 IE Insp Repts 50-010/83-02, 50-237/83-02 & 50-249/83-02 on 830112-14. No noncompliance noted. Major areas inspected: licensee action on previous findings, licensed & nonlicensed employee training & employee requalification training. FARRELL, R E., HAWKINS, F C. Region 3, Office of Director. 83/02/16. 4pp. 17621:353. 24X Fiche 50-010. 83/02/25. 8303180391.

8303030580 Clarifies NRC position re procedures for admitting NRC personnel to facilities. Site orientation re issuance of badges, escort duties & emergency evacuation for personnel listed in Encls 1 & 2 requested. KEPPLER, J G. Region 3, Office of Director. 83/02/28. REED, C. Commonwealth Edison Co. 6pp. 17409:340. 24X Fiche 50-010. 83/02/28. 8303030580.

8303070036 Forwards responses to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Bunker-Ramo electrical penetrations installed in LaSalle Unit 2, Byron Unit 2 & Braidwood Unit 2. SHARTZ, E D. Commonwealth Edison Co. 83/03/03. KEPPLER, J G. Region 3, Office of Director. 13pp. 17435:290. 24X Fiche 50-000. 83/03/03. 8303070036.

8303170371 Forwards IE Insp Repts 50-010/83-05, 50-237/83-05 & 50-249/83-04 on 830104-0202 & notice of violation. STREETER, J F. Division of Project & Resident Programs. 83/03/04. REED, C. Commonwealth Edison Co. 2pp. 17610:057. 24X Fiche. 50-010. 83/03/04. 8303170371.

--8303170375 Notice of violation from insp on 830104-0202. STREETER, J F. Division of Project & Resident Programs. 83/03/04. 1p. 17610:059. 24X Fiche. 50-010. 83/03/04. 8303170371.

--8303170377 IE Insp Repts 50-010/83-05, 50-237/83-05 & 50-249/83-04 on 830104-0202. Noncompliance noted: failure to incorporate Tech Specs issued w/Amend 71 to License DPR-19 into current copy of Tech Specs. TONGUE, T. M., JORDAN, M. J., STASEK, S. Region 3, Office of Director. 83/02/23. 9pp. 17610:060. 24X Fiche. 50-010. 83/03/04. 8303170371.

8303150343 Responds to NRC 830216 ltr re violations noted in IE Insp Repts 50-237/82-20, 50-249/82-21, 50-254/82-16 & 50-265/82-10. Extension of 30 days requested for preparation of detailed written statement re alleged violations, per 830309 telcon. REED, C. Commonwealth Edison Co. 83/03/08. KEPPLER, J G. Region 3, Office of Director. 1p. 17566:254. 24X Fiche. 50-000. 83/03/08. 8303150343.

8303140385 Summary of 830302 meeting w/util, GE, Nutech & EG&G ID in Bethesda, MD re six crack indications found ultrasonically during outage inservice insp program in six recirculation inlet riser elbow weld joints. GILBERT, R A. Operating Reactors Branch 5. 83/03/09. Operating Reactors Branch 5. 37pp. 17542:083. 24X Fiche. 50-237. 83/03/09. 8303140385.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl. DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070. 24X Fiche. 50-000. 83/03/11. 8212060380.

8303240587 Forwards IE Insp Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24 on 821203-05 No noncompliance noted. Summary of significant deficiencies encl.
KEPPLER, J. G. Region 3, Office of Director 83/03/11 REED, C. Commonwealth Edison Co. 3pp. 17683:087. 24X Fiche: 50-010, 83/03/11, 8303240587.

--8303240597 IE Insp Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24 on 821203-05 No noncompliance noted. Major areas inspected: generating station emergency plan alert caused by flooding conditions.
TONGUE, T. M., JORDAN, M. J., WALKER, R. D. Region 3, Office of Director 83/03/02 12pp. 17683:090. 24X Fiche: 50-010, 83/03/11, 8303240587.

8303170064 Forwards request for addl info re IE Bulletin 80-01 & NUREG-0737, Item II.K.3.28, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves." Response due by 830512.
CRUTCHFIELD, D. Operating Reactors Branch 5 83/03/16 FARRAR, D. L. Commonwealth Edison Co. 4pp. 17609:098. 24X Fiche: 50-000, 83/03/16, 8303170064.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303240330 Responds to IE Bulletin 82-03, "Stress Corrosion Cracking in Thick Wall, Large Diameter Stainless Steel Recirculation Sys Piping." Cracks found in 10 welds. Description of augmented insp & tabular summary of welds inspected encl.
RYBAK, B. Commonwealth Edison Co. 83/03/23 KEPPLER, J. G. Region 3, Office of Director 19pp. 17680:012. 24X Fiche: 50-237, 83/03/23, 8303240330.

8303310211 Forwards addl info in response to IE Bulletin 81-03 re methods to control Corbicula. "Environ Studies of Braidwood Cooling Pond 1982," encl.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 17pp. 17755:095. 24X Fiche: 50-000, 83/03/28, 8303310211.

--8303310233 Draft Vol 1 to "Environ Studies of Braidwood Cooling Pond, 1982."
LARIMORE, R. W., SKELLY, T. M. Illinois, State of 82/12/31 27pp. 17755:112. 24X Fiche: 50-000, 83/03/28, 8303310211.

8303310229 Commits to mid-cycle insp re repair program for 12-inch recirculation riser elbow welds. Ultrasonic insp will be conducted on two welds which had crack indications but were not weld overlayed.
RYBAK, B. Commonwealth Edison Co. 83/03/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p. 17763:038. 24X Fiche: 50-237, 83/03/28, 8303310229.

R. Periodic operating reports & related correspondence

8303110241 Forwards monthly operating repts for Feb 1983.
SCOTT, D. J. Commonwealth Edison Co. 83/03/01 Director's Office, Office of Inspection and Enforcement 1p. 17520:174. 24X Fiche: 50-010, 83/03/01, 8303110241.

--8303110248 Monthly operating repts for Feb 1983.
SCHROEDER, R. A. Commonwealth Edison Co. 83/03/01 13pp. 17520:175. 24X Fiche: 50-010, 83/03/01, 8303110241.

S. Reportable occurrences: LERs & related correspondence

8303080090 Forwards updated LER 83-002/03X-1.
SCOTT, D. J. Commonwealth Edison Co. 83/02/10 KEPPLER, J. G. Region 3, Office of Director 1p. 17457:192. 24X Fiche: 50-237, 83/02/10, 8303080090.

--8303080099 Updated LER 83-002/03X-1 on 830103, valve MO 2-1501-19A failed to close during test. Caused by loose wire 19A-CR109CD in combination starter. Terminal tightened & valve successfully cycled from control room.
COYLE, L. Commonwealth Edison Co. 83/02/10 Region 3, Office of Director 2pp. 17457:193. 24X Fiche: 50-237, 83/02/10, 8303080090.

8303080316 Forwards LER 83-010/03L-0.
SCOTT, D. J. Commonwealth Edison Co. 83/02/24 KEPPLER, J. G. Region 3, Office of Director 1p. 17449:327. 24X Fiche: 50-237, 83/02/24, 8303080316.

--8303080326 LER 83-010/03L-0 on 830129, during refueling outage, turbine exhaust pressure switch 23688 tripped & did not pickup designated relay. Caused by inadvertent wiring error at junction box 2202-29 TB2. Box rewired. Sys tested.
ANANDAPPA, A. Commonwealth Edison Co. 83/02/24 Region 3, Office of Director 1p. 17449:328. 24X Fiche: 50-237, 83/02/24, 8303080316.

8303150611 RO 83-016 on 830207, contaminated water from drain & refill of 2/3A heating boiler inadvertently released to storm sewer sys. Caused by oprator not realizing floor drain led to storm sewer sys, not radwaste sys. Tech Specs not violated.
SCOTT, D. J., GILMAN, T., SCHROEDER, C. Commonwealth Edison Co. 83/03/09 KEPPLER, J. G. Region 3, Office of Director 3pp. 17569:023. 24X Fiche: 50-237, 83/03/09, 8303150611.

8303170322 Forwards LER 83-012/01T-0.
SCOTT, D. J. Commonwealth Edison Co. 83/03/09 KEPPLER, J. G. Region 3, Office of Director 1p. 17605:162. 24X Fiche: 50-237, 83/03/09, 8303170322.

--8303170327 LER 83-012/01T-0 on 830210, main steam line mechanical snubbers 50, 51, 46, 53 & 44 found inoperable. Caused by dynamic overload of snubbers. Future corrective action will be determined based on results of current investigation.
RHEE, S. Commonwealth Edison Co. 83/03/09 Region 3, Office of Director 6pp. 17605:163. 24X Fiche: 50-237, 83/03/09, 8303170322.

8303240388 Forwards updated LER 82-043/01X-2.
SCOTT, D. J. Commonwealth Edison Co. 83/03/17 KEPPLER, J. G. Region 3, Office of Director 2pp. 17679:052. 24X Fiche: 50-237, 83/03/17, 8303240388.

--8303240396 Updated LER 82-043/01X-2 on 821002, sightglass isolation & vent valves reported open w/no indication of excess make up. Caused by operator error. Valves immediately closed. Sightglass isolation valves locked closed.
HOLLAND, P. Commonwealth Edison Co. 83/03/17 Region 3, Office of Director 2pp. 17679:054. 24X Fiche: 50-237, 83/03/17, 8303240388.

8303290284 Forwards LER 83-014/03L-0.
SCOTT, D. J. Commonwealth Edison Co. 83/03/21 KEPPLER, J. G. Region 3, Office of Director 1p. 17716:174. 24X Fiche: 50-237, 83/03/21, 8303290284.

--8303290297 LER 83-014/03L-0 on 830222, during refueling outage, time recorded for offgas discharge valve A02-5406 to fully close exceeded 15 minute Tech Spec limit. Cause unknown. Timer readjusted. Valve timed to close at 14 minutes, 16 s.
TURNQUEST, L. Commonwealth Edison Co. 83/03/17 Region 3, Office of Director 2pp. 17716:175. 24X Fiche: 50-237, 83/03/21, 8303290284.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303040631 Forwards listing of projected operator licensing exam dates including type of exam & probable number of candidates, in response to 830111 Generic Ltr 83-01.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/01 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 4pp. 17367:209. 24X Fiche: 50-000, 83/03/01, 8303040631.

DOCKET 50-241 MISSISSIPPI STATE UNIV. RESEARCH REACTOR

J. Insurance & indemnity information

8303170258 Returns bill for indemnity fee. Licensee has disposed of 100-watt homogeneous reactor under NRC 790323 order. Reactor shipped to Barnwell, SC in Spring 1982.
CARLEY, C. T. Mississippi State Univ. 83/03/04 RODRIGUEZ, J. M. Division of Accounting & Finance 3pp. 17606:160. 24X Fiche: 50-241, 83/03/04, 8303170258.

DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8303030129 Forwards IE Insp Rept 50-244/83-01 on 830103-07 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/02/18
MAIER, J E Rochester Gas & Electric Corp 2pp 17412:352 24X
Fiche 50-244, 83/02/18, 8303030129

--8303030136 IE Insp Rept 50-244/83-01 on 830103-07 No noncompliance noted Major areas inspected physical barrier areas, security sys power supply, lighting, assessment aids, access control, detection aids area & IE Bulletin 79-16
MADDEN, W , DUNLAP, J M , GODY, A T Region 1, Office of Director 83/02/16 4pp 17412:354 24X Fiche 50-244, 83/02/18, 8303030129

8303080415 Forwards IE Insp Rept 50-244/83-02 during Jan 1983 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/02/22
MAIER, J E Rochester Gas & Electric Corp 2pp 17453:273 24X
Fiche 50-244, 83/02/22, 8303080415

--8303080428 IE Insp Rept 50-244/83-02 during Jan 1983 No noncompliance noted Major areas inspected plant operations, surveillance testing, plant maint, followup of IE bulletins & circulars & followup of licensee actions on previous insp findings
ZIMMERMAN, R P , BAUNACK, W H , KISTER, H B Division of Project & Resident Programs 83/02/18 10pp 17453:275 24X
Fiche 50-244, 83/02/22, 8303080415

8303100279 Ack receipt of 830127 & 0217 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/82-24
STAROSTECKI, R Division of Project & Resident Programs 83/03/04
MAIER, J E Rochester Gas & Electric Corp 1p 17490:246 24X
Fiche 50-244, 83/03/04, 8303100279

--8303100287 Supplx 830127 response to NRC 821228 ltr re violations noted in IE Insp Rept 50-244/82-24 Corrective actions mods implemented in Jan to post fire watch & perform surveillance test
MAIER, J E Rochester Gas & Electric Corp 83/02/17 HAYNES, R C
Region 1, Office of Director 2pp 17490:247 24X
Fiche 50-244, 83/03/04, 8303100279

--8303100302 Responds to NRC 821228 ltr re violations noted in IE Insp Rept 50-244/82-24 Corrective actions revised fire signal sys detection zone disconnect/reconnect Procedure SC-3.16.2.4 for fire detection sys SD1, SD3 & SD4 implemented on 830125
MAIER, J E Rochester Gas & Electric Corp 83/01/27 HAYNES, R C
Region 1, Office of Director 3pp 17490:249 24X
Fiche 50-244, 83/03/04, 8303100279

8303100386 Discusses SALP rept for Jul 1981 - June 1982 & 820921 mgt meeting Assessment of offsite dose during 820125 performed rapidly & accurately Overall performance high
HAYNES, R C Region 1, Office of Director 83/03/04 MAIER, J E
Rochester Gas & Electric Corp 4pp 17488:295 24X
Fiche 50-244, 83/03/04, 8303100386

--8303100390 SALP Rept for Jul 1981 - June 1982
* Region 1, Office of Director 82/09/07 32pp 17488:299 24X
Fiche 50-244, 83/03/04, 8303100386

--8303100398 Comments on 820907 SALP rept Ref to Tech Spec limits should be removed from rept Offsite dose assessment performed rapidly & accurately, but no credit given in evaluation
MAIER, J E Rochester Gas & Electric Corp 82/10/06 HAYNES, R C
Region 1, Office of Director 3pp 17488:332 24X
Fiche 50-244, 83/03/04, 8303100386

8303310044 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/03/25 Document Management Branch 1p 17777:089 24X Fiche 50-244, 83/03/25, 8303310044

--8303310048 Forwards public version of Rev 2 to Emergency Plan Implementing Procedure SC-4.1, "Low Screenhouse Water Level "
MAIER, J E Rochester Gas & Electric Corp 83/03/17 HAYNES, R C
Region 1, Office of Director 1p 17777:090 24X
Fiche 50-244, 83/03/25, 8303310044

--8303310054 Public version of Rev 2 to Emergency Plan Implementing Procedure SC-4.1, "Low Screenhouse Water Level "
* Rochester Gas & Electric Corp 83/02/23 4pp 17777:092 24X
Fiche 50-244, 83/03/25, 8303310044

J Insurance & indemnity information

8303140256 Forwards Endorsement 85 to NELIA Policy NF-170
SINISI, J M Marsh & McLennan, Inc 83/03/08 SALTZMAN, J
Assistant Director for State & Licensee Relations 2pp 17534:267 24X Fiche 50-244, 83/03/08, 8303140256

P Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492:033 24X
Fiche 50-000, 83/02/16, 8302170082

8303010388 Application for amend to License DPR-18, changing Tech Specs 5.3-1, 5.3-2 & 5.4-1 to permit insertion of fuel assembly into spent fuel racks Forwards "Criticality Analysis for Spent Fuel Storage Racks "
MAIER, J E Rochester Gas & Electric Corp 83/02/23 DENTON, H
Office of Nuclear Reactor Regulation, Director 1p 17343:198 24X
Fiche 50-244, 83/02/23, 8303010388

--8303010391 Proposed changes to Tech Specs 5.3-1, 5.3-2 & 5.4-1 to permit insertion of fuel assemblies into spent fuel racks
* Rochester Gas & Electric Corp 83/02/23 5pp 17343:199 24X
Fiche 50-244, 83/02/23, 8303010388

--8303010392 "Criticality Analysis for Spent Fuel Storage Racks "
ROBBINS, T R Pickard, Lowe & Garrick, Inc 82/11/30 27pp 17343:204 24X Fiche 50-244, 83/02/23, 8303010388

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700:303 24X
Fiche 50-000, 83/03/02, 8303020321

8303080333 Forwards supplemental response to NRC 820819 technical evaluation rept, "Control of Heavy Loads - NUREG-0612 " Part 2 response will be submitted 830201 Util will develop load handling procedures for 10 sys within NUREG scope
MAIER, J E Rochester Gas & Electric Corp 83/03/02 CRUTCHFIELD, D
Operating Reactors Branch 5 33pp 17449:264 24X
Fiche 50-244, 83/03/02, 8303080333

8303080460 Informs that due to various valve failures, implementation of operational post-accident sampling sys per NUREG-0737, Item II.B.3 will be delayed from mid-Feb 1983 to 830630
MAIER, J E Rochester Gas & Electric Corp 83/03/03 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 17453:134 24X
Fiche 50-244, 83/03/03, 8303080460

8303090072 Forwards Rev 1 to "Offsite Dose Calculating Manual " Rev incorporates changes resulting from Franklin Research Ctr review
MAIER, J E Rochester Gas & Electric Corp 83/03/04 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 17467:025 24X
Fiche 50-244, 83/03/04, 8303090072

--8303090074 Rev 1 to "Offsite Dose Calculating Manual "
* Rochester Gas & Electric Corp 83/03/04 36pp 17467:026 24X Fiche 50-244, 83/03/04, 8303090072

8303110316 Forwards "PWR Safety & Relief Valve Adequacy Rept " & "Pressurizer Safety Relief Line Evaluation Summary Rept " per 821202 commitment Valves will operate under design operating condition TMI Item II.D.1 requirements complete
MAIER, J E Rochester Gas & Electric Corp 83/03/04 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 17518:001 24X
Fiche 50-244, 83/03/04, 8303110316

--8303110320 "PWR Safety & Relief Valve Adequacy Rept for Rochester Gas & Electric Corp, RE Ginna Unit 1 "
* Rochester Gas & Electric Corp 83/01/14 39pp 17518:002 24X Fiche 50-244, 83/03/04, 8303110316

--8303110324 "Pressurizer Safety & Relief Line Evaluation Summary Rept, Rochester Gas & Electric Corp, Ginna Station "
SMITH, L C , ACCORNERO, K F , CHANG, K C Westinghouse Electric Corp 83/02/28 77pp 17518:040 24X Fiche 50-244, 83/03/04, 8303110316

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303110338 Summarizes activities required to resolve NUREG-0737, Item III.D.3.4, "Control Room Habitability," requested in NRC 821018 ltr. Redundant dampers will be installed in control room intake & exhaust ducts direct to atmosphere.
MAIER, J. E. Rochester Gas & Electric Corp. 83/03/07 CRUTCHFIELD, D. M. Operating Reactors Branch 5 1p 17506:349 24X
Fiche: 50-244, 83/03/07, 8303110338.

8303100301 Forwards rationale for loss of tension in containment vessel tendons presented in GAI Rept 2347 transmitted by 830201 ltr. Predictions re expected behavior of retensioned wire should be provided.
CRUTCHFIELD, D. Operating Reactors Branch 5 83/03/08 MAIER, J. E. Rochester Gas & Electric Corp. 6pp 17491:208 24X
Fiche: 50-244, 83/03/08, 8303100301.

8303170161 Advises that util plans to install reactor vessel water level sys & upgrade core exit thermocouples for inadequate core cooling instrumentation sys, per Generic Ltr 82-12. Regulatory commitment schedules under re-evaluation.
MAIER, J. E. Rochester Gas & Electric Corp. 83/03/10 CRUTCHFIELD, D. M. Operating Reactors Branch 5 3pp 17609:011 24X
Fiche: 50-244, 83/03/10, 8303170161.

8303220003 Responds to 830223 ltr re operability of containment purge valves. Valve stops set to restrict valves to max of 50 degrees open in Dec 1979 to ensure structural integrity following closure from postulated LOCA.
MAIER, J. E. Rochester Gas & Electric Corp. 83/03/11 CRUTCHFIELD, D. M. Operating Reactors Branch 5 4pp 17652:076 24X
Fiche: 50-244, 83/03/11, 8303220003.

8303220092 Forwards order confirming licensee commitments on post-TMI related items set forth in NUREG-0737 per util 820317 & 0505 responses to Generic Ltrs 82-05 & 82-10, respectively. Util proposed implementation schedule delays acceptable.
CRUTCHFIELD, D. Operating Reactors Branch 5 83/03/14 MAIER, J. E. Rochester Gas & Electric Corp. 3pp 17650:076 24X
Fiche: 50-244, 83/03/14, 8303220092.

--8303220113 Order confirming licensee commitments on post-TMI related issues. Lists of licensee commitments on applicable NUREG-0737 requirements from Generic Ltrs 82-05 & 82-10 encl.
EISENHUT, D. G. Division of Licensing 83/03/14 Rochester Gas & Electric Corp. 10pp 17650:079 24X Fiche: 50-244, 83/03/14, 8303220092.

8303230232 Forwards response to 830311 request for info re mod to safety injection pump 1C logic. Submittal consists of design criteria & electrical schematics.
MAIER, J. E. Rochester Gas & Electric Corp. 83/03/15 CRUTCHFIELD, D. M. Operating Reactors Branch 5 8pp 17661:197 24X
Fiche: 50-244, 83/03/15, 8303230232.

8303230244 Responds to 820222 request for addl info resulting from review of SER for SEP Topic III-5.A, "Effect of Pipe Break on Sys Structures & Components Inside Containment." Rerouting of certain instrumentation circuits warranted.
MAIER, J. E. Rochester Gas & Electric Corp. 83/03/16 CRUTCHFIELD, D. M. Operating Reactors Branch 5 4pp 17661:205 24X
Fiche: 50-244, 83/03/16, 8303230244.

8303280065 Approves request to withhold Rept 12-1135119-01, "Steam Generator Rapid Sleeving Program Design Verification Rept, RE Ginna Nuclear Power Plant," from public disclosure per 10CFR2.790. B&W justification for withholding listed.
CRUTCHFIELD, D. Operating Reactors Branch 5 83/03/22 MAIER, J. E. Rochester Gas & Electric Corp. 3pp 17707:283 24X
Fiche: 50-244, 83/03/22, 8303280065.

8303290470 Forwards resolution of open issues for SEP Topic III-5.B re pipe break outside containment, including issues concerning screenhouse, relay room, air handling room, intermediate bldg & auxiliary bldg.
MAIER, J. E. Rochester Gas & Electric Corp. 83/03/22 CRUTCHFIELD, D. M. Operating Reactors Branch 5 4pp 17722:353 24X
Fiche: 50-244, 83/03/22, 8303290470.

## G. Inspection reports, IE Bulletins & correspondence

8303030129 Forwards IE Insp Rept 50-244/83-01 on 830103-07. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs 83/02/18 MAIER, J. E. Rochester Gas & Electric Corp. 2pp 17412:352 24X
Fiche: 50-244, 83/02/18, 8303030129.

--8303030136 IE Insp Rept 50-244/83-01 on 830103-07. No noncompliance noted. Major areas inspected: physical barrier areas, security sys power supply, lighting, assessment aids, access control, detection aids area & IE Bulletin 79-16.
MADDEN, W. J. DUNLAP, J. M. GODY, A. T. Region 1, Office of Director 83/02/16 4pp 17412:354 24X Fiche: 50-244, 83/02/18, 8303030129.

8303080415 Forwards IE Insp Rept 50-244/83-02 during Jan 1983. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs 83/02/22 MAIER, J. E. Rochester Gas & Electric Corp. 2pp 17453:273 24X
Fiche: 50-244, 83/02/22, 8303080415.

--8303080428 IE Insp Rept 50-244/83-02 during Jan 1983. No noncompliance noted. Major areas inspected: plant operations, surveillance testing, plant maint, followup of IE bulletins & circulars & followup of licensee actions on previous insp findings.
ZIMMERMAN, R. P. BAUNACK, W. H. KISTER, H. B. Division of Project & Resident Programs 83/02/18 10pp 17453:275 24X
Fiche: 50-244, 83/02/22, 8303080415.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11lpp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303100279 Ack receipt of 830127 & 0217 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/82-24.
STAROSTECKI, R. Division of Project & Resident Programs 83/03/04 MAIER, J. E. Rochester Gas & Electric Corp. 1p 17490:246 24X
Fiche: 50-244, 83/03/04, 8303100279.

--8303100287 SupplS 830127 response to NRC 821228 ltr re violations noted in IE Insp Rept 50-244/82-24. Corrective actions: mods implemented in Jan to post fire watch & perform surveillance test.
MAIER, J. E. Rochester Gas & Electric Corp. 83/02/17 HAYNES, R. C. Region 1, Office of Director 2pp 17490:247 24X
Fiche: 50-244, 83/03/04, 8303100279.

--8303100302 Responds to NRC 821228 ltr re violations noted in IE Insp Rept 50-244/82-24. Corrective actions: revised fire signal sys detection zone disconnect/reconnect Procedure SC-3.16.2.4 for fire detection sys S01, S03 & S04 implemented on 830125.
MAIER, J. E. Rochester Gas & Electric Corp. 83/01/27 HAYNES, R. C. Region 1, Office of Director 3pp 17490:249 24X
Fiche: 50-244, 83/03/04, 8303100279.

8303100386 Discusses SALP rept for Jul 1981 - June 1982 & 820921 mgt meeting. Assessment of offsite dose during 820125 performed rapidly & accurately. Overall performance high.
HAYNES, R. C. Region 1, Office of Director 83/03/04 MAIER, J. E. Rochester Gas & Electric Corp. 4pp 17488:295 24X
Fiche: 50-244, 83/03/04, 8303100386.

--8303100390 SALP Rept for Jul 1981 - June 1982.
* Region 1, Office of Director 82/09/07 32pp 17488:299 24X
Fiche: 50-244, 83/03/04, 8303100386.

--8303100393 Forwards SALP rept re review & evaluation of performance activities conducted on 820907. Site meeting to discuss assessment scheduled for 820921.
STAROSTECKI, R. Division of Project & Resident Programs 82/09/15 MAIER, J. E. Rochester Gas & Electric Corp. 1p 17488:331 24X
Fiche: 50-244, 83/03/04, 8303100386.

--8303100398 Comments on 820907 SALP rept. Ref to Tech Spec limits should be removed from rept. Offsite dose assessment performed rapidly & accurately, but no credit given in evaluation.
MAIER, J. E. Rochester Gas & Electric Corp. 82/10/06 HAYNES, R. C. Region 1, Office of Director 3pp 17488:332 24X
Fiche: 50-244, 83/03/04, 8303100386.

8303110217 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Preventive maint performed each refueling outage & bulletin is required reading for operators.
MAIER, J. E. Rochester Gas & Electric Corp. 83/03/04 HAYNES, R. C. Region 1, Office of Director 2pp 17518:341 24X
Fiche: 50-244, 83/03/04, 8303110217.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 11?pp 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12lpp 17774.352 24X Fiche: 50-000, 83/03/21, 8212060387.

R. Periodic operating reports & related correspondence

8303080213 Forwards monthly operating rept for Dec 1982.
SNOW, B. A. Baltimore Gas & Electric Co. 83/01/06 Division of Data Automation & Management Information 1p 17457.094 24X Fiche: 50-244, 83/01/06, 8303080213.

--8303080217 Monthly operating rept for Dec 1982.
MCNAMARA, A. E. Baltimore Gas & Electric Co. 83/01/06 5pp 17457.095 24X Fiche: 50-244, 83/01/06, 8303080213.

8303150516 Forwards monthly operating rept for Jan 1983.
SNOW, B. A. Rochester Gas & Electric Corp. 83/02/04 Office of Resource Management, Director 1p 17560.250 24X Fiche: 50-244, 83/02/04, 8303150516.

--8303150519 Monthly operating rept for Jan 1983.
ANGERT, E. Rochester Gas & Electric Corp. 83/02/04 5pp 17560.251 24X Fiche: 50-244, 83/02/04, 8303150516.

8303140426 Forwards "Rept of Radioactive Effluents, 1982" & "Std Rept of Personnel & Man-Rem By Work & Job Function, 1982."
WHITE, L. D. Rochester Gas & Electric Corp. 83/02/28 HAYNES, R. C. Region 1, Office of Director 3pp 17542.211 24X Fiche: 50-244, 83/02/28, 8303140426.

--8303140434 "Rept of Radioactive Effluents, 1982."
* Rochester Gas & Electric Corp. 83/02/28 9pp 17542.214 24X Fiche: 50-244, 83/02/28, 8303140426.

--8303140441 "Std Rept of Personnel & Man-Rem By Work & Job Function, 1982."
* Rochester Gas & Electric Corp. 83/02/28 2pp 17542.223 24X Fiche: 50-244, 83/02/28, 8303140426.

S. Reportable occurrences, LERs & related correspondence

8303010365 Forwards LER 83-005/03L-0.
MAIER, J. E. Rochester Gas & Electric Corp. 83/02/16 HAYNES, R. C. Region 1, Office of Director 1p 17344.360 24X Fiche: 50-244, 83/02/16, 8303010365.

--8303010372 LER 83-005/03L-0 on 830117, I-131 spike occurred in RCS after unit tripped from 100% power. Caused not stated. I-131 concentration returned to normal levels by normal letdown.
BODINE, J. C. Rochester Gas & Electric Corp. 83/02/16 Region 1, Office of Director 1p 17344.361 24X Fiche: 50-244, 83/02/16, 8303010365.

8303010462 Forwards LER 83-007/03L-0.
MAIER, J. E. Rochester Gas & Electric Corp. 83/02/16 HAYNES, R. C. Region 1, Office of Director 1p 17343.279 24X Fiche: 50-244, 83/02/16, 8303010462.

--8303010470 LER 83-007/03L-0 on 830117, water level in pressurizer dropped below 12% level. Caused by RCS cooldown following trip. Level returned to 19.5% within 15 minutes.
BODINE, J. C. Rochester Gas & Electric Corp. 83/02/16 Region 1, Office of Director 1p 17343.280 24X Fiche: 50-244, 83/02/16, 8303010462.

8303010478 Forwards LER 83-009/03L-0.
MAIER, J. E. Rochester Gas & Electric Corp. 83/02/16 HAYNES, R. C. Region 1, Office of Director 1p 17343.319 24X Fiche: 50-244, 83/02/16, 8303010478.

--8303010487 LER 83-009/03L-0 on 830119, boric acid transfer pump B tripped immediately after start. Caused by failed control power fuses. Fuses replaced.
BODINE, J. C. Rochester Gas & Electric Corp. 83/02/16 Region 1, Office of Director 1p 17343.320 24X Fiche: 50-244, 83/02/16, 8303010478.

8303040342 Forwards Figures 14-1 & 2 inadvertently omitted from 821122 response to NUREG-0916, "Response to Long-Term Commitments, Ginna Restart SER, Steam Generator Tube Rupture Incident."
WHITE, L. D. Rochester Gas & Electric Corp. 83/02/28 CRUTCHFIELD, D. Operating Reactors Branch 5 3pp 17374.035 24X Fiche: 50-244, 83/02/28, 8303040342.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8303030189 Forwards IE Insp Repts 50-245/83-02 & 50-336/83-02 on 830109-29. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs 83/02/18 COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 2pp 17410.298 24X Fiche: 50-245, 83/02/18, 8303030189.

--8303030201 IE Insp Repts 50-245/83-02 & 50-336/83-02 on 830109-29. No noncompliance noted. Major areas inspected: evaluations of plant operations, startup testing, radiation protection, physical security, fire protection & plant operating records.
SHEDLOSKY, J. T., LIPINSKI, D. R., ELSASSER, T. C. Division of Project & Resident Programs 83/02/14 14pp 17410.300 24X Fiche: 50-245, 83/02/18, 8303030189.

8303090317 Responds to 820817 ltr re changes submitted as Rev 10 to modified amended security plan. Changes acceptable.
CRUTCHFIELD, D. Operating Reactors Branch 5 83/02/18 COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 1p 17484.239 24X Fiche: 50-245, 83/02/18, 8303090317.

8303160258 Notification of 830318 meeting w/util in Bethesda, MD to discuss proposed fire protection exemption requests.
LEECH, P. H. Operating Reactors Branch 3 83/03/09 CLARK, R. A. Operating Reactors Branch 3 2pp 17604.353 24X Fiche: 50-245, 83/03/09, 8303160258.

8303300462 Forwards IE Insp Repts 50-245/83-05 & 50-336/83-06 on 830130-0226. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs 83/03/16 COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 2pp 17731.013 24X Fiche: 50-245, 83/03/16, 8303300462.

--8303300475 IE Insp Repts 50-245/83-05 & 50-336/83-06 on 830130-0226. No noncompliance noted. Major areas inspected: startup testing, equipment alignments & readiness, radiation protection, physical security & surveillance testing & mod.
SHEDLOSKY, J. T., LIPINSKI, D. R., GRAY, E. H. Region 1, Office of Director 83/03/15 13pp 17731.015 24X Fiche: 50-245, 83/03/16, 8303300462.

8303290058 Releases public version of rept of emergency plan media briefing session.
FELTON, J. M. Division of Rules and Records 83/03/21 Document Management Branch 1p 17730.290 24X Fiche: 50-000, 83/03/21, 8303290058.

--8303290064 Forwards public version of rept of 830113 emergency plan media briefing session.
COUNSIL, W. G. Connecticut Yankee Atomic Power Co., COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities), COUNSIL, W. G. Northeast Utilities Service Co. 83/03/11 CLARK, R. A. Operating Reactors Branch 3, CRUTCHFIELD, D. Operating Reactors Branch 5 2pp 17730.291 24X Fiche: 50-000, 83/03/21, 8303290058.

8303290235 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 83/03/21 Document Management Branch 1p 17727.214 24X Fiche: 50-245, 83/03/21, 8303290235.

--8303290243 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 4201 re radiological dose assessment, EPIP 4207 re radiological sampling & EPIP 4220 re radiological communications.
COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 83/03/04 EISENHUT, D. G. Division of Licensing 2pp 17727.215 24X Fiche: 50-245, 83/03/21, 8303290235.

--8303290251 Public version of revised emergency plan implementing procedures, including Procedures EPIP 4201 re radiological dose assessment, EPIP 4207 re radiological sampling & EPIP 4220 re radiological communications.
MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 83/02/28 105pp 17727.217 24X
Fiche: 50-245, 83/03/21, 8303290235

J. Insurance & indemnity information

8303080211 Endorsements 84 & 85 to NELIA Policy NF-173 & Endorsements 76 & 77 to MAELU Policy MF-52.
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/02/22 NRC - No Detailed Affiliation Given 4pp 17457.090 24X Fiche: 50-245, 83/02/22, 8303080211

8303140244 Forwards Endorsement 86 to NELIA Policy NF-173.
SINISI, J. M. Marsh & McLennan, Inc. 83/03/07 SALTZMAN, J. D. Assistant Director for State & Licensee Relations 2pp 17539.001 24X Fiche: 50-245, 83/03/07, 8303140244

8303140231 Forwards Endorsement 74 to NELIA Policy NF-151.
SINISI, J. M. Marsh & McLennan, Inc. 83/03/08 SALTZMAN, J. D. Assistant Director for State & Licensee Relations 2pp 17538.335 24X Fiche: 50-245, 83/03/08, 8303140231

O. Advisory Committee on Reactor Safeguards reports & correspondence

8303160637 Summary of ACRS Subcommittee on SEP 821130 meeting in Washington, DC re SEP review for facilities.
* ACRS - Advisory Committee on Reactor Safeguards. 83/01/04. ACRS - Advisory Committee on Reactor Safeguards. 16pp 17605.272 24X Fiche: 50-000, 83/01/04, 8303160637

8303100107 Forwards NRR response to ACRS recommendations following 271st & 272nd meetings, per 821208 & 830107 memos.
GOODWIN, E. F. Technical Support Branch 83/02/15 FRALEY, R. F. ACRS - Advisory Committee on Reactor Safeguards 5pp 17504.036 24X Fiche: 50-000, 83/02/15, 8303100107

--8301180041 Forwards list of requests made at 272nd ACRS meeting on 821209-11 per agreement to provide summary of actions, agreements, assignments & requests made at each full ACRS meeting.
FRALEY, R. F. ACRS - Advisory Committee on Reactor Safeguards. 83/01/05 DIRCKS, W. J. Office of the Executive Director for Operations. 4pp 17504.041 24X Fiche: 50-000, 83/02/15, 8303100107

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492.033 24X
Fiche: 50-000, 83/02/16, 8302170082

8303010386 Application to amend Licenses DPR-21 & DPR-65, deleting water quality limits & related monitoring programs from ETS.
COUNSIL, W. G.; WERNER, R. P. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities 83/02/16. CRUTCHFIELD, D. Operating Reactors Branch 5. CLARK, R. A. Operating Reactors Branch 3. 3pp 17343.175 24X Fiche: 50-245, 83/02/16, 8303010386

--8303010390 Proposed Tech Spec changes, deleting water quality limits & related monitoring programs.
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/02/28 17pp 17343.178 24X Fiche: 50-245, 83/02/16, 8303010386

8303080102 Discusses evaluation of leakage detection capability & operating station location for specified remote manual valves listed in Section 4.20.3 of NUREG-0824, per util 821227 ltr & SEP Topic VI-4, "Containment Isolation Sys."
COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/02/23. CRUTCHFIELD, D. Operating Reactors Branch 5. 3pp 17458.192 24X Fiche: 50-245, 83/02/23, 8303080102

8303040178 Responds to 830128 ltr re simulator program & commends util commitment to provide plant-specific simulators for use in training nuclear power plant operators.
THOMPSON, H. L. Division of Human Factors Safety 83/02/25. COUNSIL, W. G. Northeast Utilities. 4pp 17427.018 24X
Fiche: 50-000, 83/02/25, 8303040178

--8303040187 Discusses use of plant simulators to train nuclear power plant operators. Util committed to procurement & use of plant-specific simulators.
COUNSIL, W. G. Connecticut Yankee Atomic Power Co. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/01/28 DIRCKS, W. J. Office of the Executive Director for Operations. 3pp 17427.022 24X
Fiche: 50-000, 83/02/25, 8303040178

8303080176 Discusses proposed design changes considered for preventing future isolation condenser water hammer events. Reactor level setpoint setdown feature unnecessary & would complicate already complex feedwater regulating injection sys.
COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/02/28. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp 17457.337 24X
Fiche: 50-245, 83/02/28, 8303080176

8303080317 Advises that proposed schedule for completion of mods per NUREG-0737, Item III.D.3.4, "Control Room Habitability," will be postponed until 841231.
COUNSIL, W. G. Connecticut Yankee Atomic Power Co. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/02/28. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp 17449.318 24X
Fiche: 50-000, 83/02/28, 8303080317

8303230417 INTEGRATED PLANT SAFETY ASSESSMENT SYSTEMATIC EVALUATION PROGRAM-MILLSTONE NUCLEAR POWER STATION, UNIT 1, Docket No. 50-245. (Northeast Nuclear Energy Company)
* Division of Licensing. NUREG-0824. 83/02/28. 540pp. Available at NRC $12.00 17675.281 24X Fiche: 50-245, 83/02/28, 8303230417

8303040546 Submits addl info to allow continued evaluation of containment purging & venting, in response to 811231 request.
COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/03/01. CRUTCHFIELD, D. Operating Reactors Branch 5. 5pp 17424.167 24X
Fiche: 50-245, 83/03/01, 8303040546.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700.303 24X
Fiche: 50-000, 83/02/02, 8303020321

8303080465 Submits addl info re containment purge & vent valve operability in response to NRC 821005 ltr. Probability of 18 inch valves being open during seismic event & not failing closed extremely low.
COUNSIL, W. G.; WERNER, R. P. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/03/02. CRUTCHFIELD, D. Operating Reactors Branch 5. 3pp 17453.118 24X
Fiche: 50-245, 83/03/02, 8303080465.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp 17660.176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303150345 Provides addl info re SEP Topic VI-10.A, "Testing of Reactor Trip Sys & ESFs, Including Response Time Testing," Control room daily log revised to provide for channel checks for average power & intermediate-range monitors.
COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/03/10. CRUTCHFIELD, D. Operating Reactors Branch 5. 1p 17563.016 24X
Fiche: 50-245, 83/03/10, 8303150345.

8303160264 Advises that OPS Form 6P2 1-1 has been revised to indicate large flood door to gas turbine bldg should be normally closed. Position of large flood door will be verified monthly, per SEP Topic II-3.B.
COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/03/10. CRUTCHFIELD, D. Operating Reactors Branch 5. 1p 17596.334 24X
Fiche: 50-245, 83/03/10, 8303160264.

8303160550 Responds to 830217 ltr requesting info on presence of federally listed & proposed endangered or threatened species in plant area. Except for occasional transient individuals, no species identified in project impact areas.
BECKETT, G. E. Interior, Dept. of, Fish & Wildlife Service. 83/03/10. YOUNGBLOOD, B. J. Licensing Branch 1. 2pp 17597.260 24X
Fiche: 50-245, 83/03/10, 8303160550.

8303230421 Forwards Amends 89 & 81 to Licenses DPR-21 & DPR-65, respectively & notice of issuance & availability. Amends delete App B ETS re nonradiological water quality-related requirements.
CLARK, R A Operating Reactors Branch 3 83/03/11 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 17674:108 24X Fiche: 50-245, 83/03/11, 8303230421

--8303230429 Amends 89 & 81 to Licenses DPR-21 & DPR-65, respectively, deleting App B ETS re nonradiological water quality-related requirements.
CRUTCHFIELD, D Operating Reactors Branch 5 CLARK, R A Operating Reactors Branch 3 83/03/11 2pp 17674:112 24X Fiche: 50-245, 83/03/11, 8303230421

--8303230435 Notice of issuance & availability of Amends 89 & 81 to Licenses DPR-21 & DPR-65, respectively.
CLARK, R A Operating Reactors Branch 3 83/03/11 2pp 17674:138 24X Fiche: 50-245, 83/03/11, 8303230421

8303220201 Forwards orders confirming licensee commitments on post-TMI rrlated items set forth in NUREG-0737, per util 820317 & 0505 responses to Generic Ltrs 82-05 & 82-10, respectively. Util proposed implementation schedule delays acceptable.
CRUTCHFIELD, D Operating Reactors Branch 5 83/03/14 COUNSIL, W G Connecticut Yankee Atomic Power Co 3pp 17657:001 24X Fiche: 50-000, 83/03/14, 8303220201

--8303220255 Order confirming licensee commitments on post-TMI-related issues. Lists of licensee commitments on applicable NUREG-0737 requirements from Generic Ltrs 82-05 & 82-10 encl.
EISENHUT, D G Division of Licensing 83/03/14 Northeast Nuclear Energy Co (subs of Northeast Utilities) 9pp 17657:012 24X Fiche: 50-000, 83/03/14, 8303220201

8303290443 Informs that schedule for completion of qualification of electrical equipment will be submitted by 830520. Ninety-day responses requested in NRC 821213 ltr superseded by issuance of 10CFR50.49 final rule.
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/03/18 CLARK, R A Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 17725:350 24X Fiche: 50-000, 83/03/18, 8303290443

8303290560 Responds to Generic Ltr 83-02 re discussion & guidance on NUREG-0737 items requiring Tech Specs. No addl changes per 10CFR50.90 prepared.
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/03/18 EISENHUT, D G Division of Licensing 14pp 17723:345 24X Fiche: 50-245, 83/03/18, 8303290560

8303300027 Responds to 830224 request for backfit costs, source, time of action & whether action resulted from new requirement. W/o encl.
DIRCKS, W J Office of the Executive Director for Operations 83/03/18 ZERBE, J Office of Policy Evaluations 1p 17751:166 24X Fiche: 50-000, 83/03/18, 8303300027

--8303300032 Responds to 830224 request for assistance in determining source of backfits at facilities & assessment of costs. Tables encl provide approx time of action, source & whether action resulted from new requirement. W/o encl.
DIRCKS, W J Office of the Executive Director for Operations 83/03/08 ZERBE, J Office of Policy Evaluations 1p 17751:167 24X Fiche: 50-000, 83/03/18, 8303300027

--8303300038 Requests assistance in identifying source & time period & backfit costs. Response requested by 830315.
ZERBE, J Office of Policy Evaluations 83/02/24 DIRCKS, W Office of the Executive Director for Operations 4pp 17751:169 24X Fiche: 50-000, 83/03/18, 8303300027

8303290313 Forwards addl info re NUREG-0737, Item II D 1, "Safety/Relief Valve Testing." Valve operability not affected by safety relief valve discharge transient anticipated at facility.
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/03/22
CRUTCHFIELD, D Operating Reactors Branch 5 16p 17716:206 24X Fiche: 50-245, 83/03/22, 8303290313

8303290495 Forwards info demonstrating adequacy of recirculation pump against seismic loadings per 820713 commitment. Info should resolve concerns re SEP Topic III-6.
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/03/24
CRUTCHFIELD, D Operating Reactors Branch 5 15pp 17725:034 24X Fiche: 50-245, 83/03/24, 8303290495

8303310311 Withdraws request for hearing re environ qualification of safety-related electrical equipment. Withdrawal based on interpretations of 10CFR50.49, final rule re qualification criteria & replacement equipment.
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/03/24 EISENHUT, D G Division of Licensing 2pp 17755:139 24X Fiche: 50-000, 83/03/24, 8303310311

8303280128 Requests investigation of effect of facility on historic properties potentially eligible for inclusion in Natl Register of Historic Places.
KLIMA, D L Advisory Council on Historic Preservation 83/03/25
BYKOSKI, L NRC - No Detailed Affiliation Given 1p 17706:358 24X Fiche: 50-245, 83/03/25, 8303280128

G. Inspection reports, IE Bulletins & correspondence

8303040468 Forwards IE Investigation Rept 50-245/82-75 on 820825-1207. No basis found to support allegation of disposal of contaminated matl in unrestricted area.
STAROSTECKI, R Division of Project & Resident Programs 83/02/15
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 17422:035 24X Fiche: 50-245, 83/02/15, 8303040468

--8303040473 IE Investigation Rept 50-245/82-75 on 820825-1207 re alleged disposal of contaminated matl in unrestricted area. Allegation unsubstantiated. Proprietary details deleted (ref 10CFR2.790).
SHEPHERD, R E , CHRISTOPHER, R Region 1, Office of Director
FITZGERALD, J A Office of Investigation 82/12/15 18pp 17422:038 24X Fiche: 50-245, 83/02/15, 8303040468

8303030172 Forwards IE Insp Repts 50-245/82-23 & 50-336/82-25 on 821121-830108 & notice of violation.
STAROSTECKI, R Division of Project & Resident Programs 83/02/18
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 17410:153 24X Fiche: 50-245, 83/02/18, 8303030172

--8303030177 Notice of violation from insp on 821121-830108.
* Region 1, Office of Director 83/02/18 2pp 17410:155 24X Fiche: 50-245, 83/02/18, 8303030172

--8303030184 IE Insp Repts 50-245/82-23 & 50-336/82-25 on 821121-830108. Noncompliance noted: failure to implement test procedures & failure to follow procedures re quality & testing.
SHEDLOSKY, J T , LIPINSKI, D R , ELSASSER, T C Division of Project & Resident Programs 83/01/25 26pp 17410:157 24X Fiche: 50-245, 83/02/18, 8303030172

8303030189 Forwards IE Insp Repts 50-245/83-02 & 50-336/83-02 on 830109-29. No noncompliance noted.
STAROSTECKI, R Division of Project & Resident Programs 83/02/18
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 17410:298 24X Fiche: 50-245, 83/02/18, 8303030189

--8303030201 IE Insp Repts 50-245/83-02 & 50-336/83-02 on 830109-29. No noncompliance noted. Major areas inspected: evaluations of plant operations, startup testing, radiation protection, physical security, fire protection & plant operating records.
SHEDLOSKY, J T , LIPINSKI, D R , ELSASSER, T C Division of Project & Resident Programs 83/02/14 14pp 17410:300 24X Fiche: 50-245, 83/02/18, 8303030189

8303040368 Responds to request to review IE Bulletin 82-04 re applicability of deficiencies in primary containment electrical penetration assemblies. No assemblies mfg by Bunker-Ramo in svc or planned for use at plants.
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities COUNSIL, W G Connecticut Yankee Atomic Power Co 83/02/22 HAYNES, R C Region 1, Office of Director 2pp 17420:014 24X Fiche: 50-000, 83/02/22, 8303040368

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 111pp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367

8303160612 Forwards IE Insp Repts 50-245/83-03 & 50-336/83-04 on 830208-11. No noncompliance noted.
MARTIN, T T Division of Engineering & Technical Programs 83/03/04
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 17587:213 24X Fiche: 50-245, 83/03/04, 8303160612

--8303160616 IE Insp Repts 50-245/83-03 & 50-336/83-04 on 830208-11. No noncompliance noted. Major areas inspected: mgt controls; licensee program for QC & analytical measures & followup action on previous environ insp findings.
JANG, J. C. ; PASCIAK, W. J. Region 1, Office of Director. 83/02/28. 6pp. 17587:215. 24X Fiche. 50-245, 83/03/04, 8303160612.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche. 50-000, 83/03/11, 8212060380.

8303280207 Forwards IE Insp Repts 50-245/83-04 & 50-336/83-05 on 830208-11. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/14.
COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 17706:293. 24X Fiche. 50-245, 83/03/14, 8303280207.

--8303280214 IE Insp Repts 50-245/83-04 & 50-336/83-05 on 830208-11. No noncompliance noted. Major areas inspected: previously identified items; exposure control; radiation protection program implementation & personnel qualification & training.
ROWE, C. ; MCBRIDE, M. ; SHANBAKY, M. Region 1, Office of Director. 83/03/10. 5pp. 17706:295. 24X Fiche. 50-245, 83/03/14, 8303280207.

8303300462 Forwards IE Insp Repts 50-245/83-05 & 50-336/83-06 on 830130-0226. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/16.
COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 17731:013. 24X Fiche. 50-245, 83/03/16, 8303300462.

--8303300475 IE Insp Repts 50-245/83-05 & 50-336/83-06 on 830130-0226. No noncompliance noted. Major areas inspected: startup testing; equipment alignments & readiness; radiation protection; physical security & surveillance testing & mod.
SHEDLOSKY, J. T. ; LIPINSKI, D. R. ; GRAY, E. H. Region 1, Office of Director. 83/03/15. 13pp. 17731:015. 24X Fiche. 50-245, 83/03/16, 8303300462.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche. 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 12lpp. 17774:352. 24X Fiche. 50-000, 83/03/21, 8212060387.

R Periodic operating reports & related correspondence

8303080120 Forwards monthly operating rept for Dec 1982 & revised monthly operating rept for Nov 1982.
MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA, E. J. Northeast Utilities. 83/01/14.
Division of Data Automation & Management Information. 1p.
17458:338. 24X Fiche. 50-245, 83/01/14, 8303080120.

--8303080133 Revised monthly operating rept for Nov 1982.
HARRAN, G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/01/06. 1p. 17458:339. 24X Fiche. 50-245, 83/01/14, 8303080120.

--8303080144 Monthly operating rept for Dec 1982.
HARRAN, G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/01/06. 13pp. 17458:340. 24X Fiche. 50-245, 83/01/14, 8303080120.

8302150420 Forwards monthly operating rept for Jan 1983.
MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA, E. J. Northeast Utilities. 83/02/15. Office of Resource Management, Director. 1p. 17561:193. 24X Fiche. 50-245, 83/02/15, 8303150420.

--8303150421 Monthly operating rept for Jan 1983.
HARRAN, G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/02/11. 6pp. 17561:194. 24X Fiche. 50-245, 83/02/15, 8303150420.

8303080208 Forwards "Semiannual Radioactive Effluents Release Rept, Jul-Dec 1982."
COUNSIL, W. G. ; SEARS, C. F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/02/18.
HAYNES, R. C. Region 1, Office of Director. 1p. 17439:166. 24X Fiche. 50-245, 83/02/18, 8303080208.

--8303080218 "Semiannual Radioactive Effluents Release Rept, Jul-Dec 1982."
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/02/18. 121pp. 17439:167. 24X Fiche. 50-245, 83/02/18, 8303080208.

8303240407 Forwards "Haddam Neck Plant & Millstone Station Units 1 & 2 Annual Rept, 1982," containing summary of challenges to relief valves, per util 800610 commitment.
COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Connecticut Yankee Atomic Power Co. COUNSIL, W. G. Northeast Utilities. 83/03/01. HAYNES, R. C. Region 1, Office of Director. 1p. 17679:130. 24X Fiche. 50-000, 83/03/01, 8303240407.

--8303240408 "Haddam Neck Plant & Millstone Station Units 1 & 2 Annual Rept, 1982."
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). * Connecticut Yankee Atomic Power Co. * Northeast Utilities. 83/03/01. 183pp. 17679:131. 24X Fiche. 50-000, 83/03/01, 8303240407.

S Reportable occurrences, LERs & related correspondence

8303080070 Forwards LER 83-005/03L-0. Detailed event analysis encl.
MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA, E. J. Northeast Utilities. 83/02/24.
HAYNES, R. C. Region 1, Office of Director. 2pp. 17457:247. 24X Fiche. 50-245, 83/02/24, 8303080070.

--8303080076 LER 83-005/03L-0 on 830207, pressure switch 261-30D tripped at 824 psig. Caused by setpoint drift. Switch reset & tested satisfactorily.
THULL, T. S. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/02/24. Region 1, Office of Director. 1p.
17457:249. 24X Fiche. 50-245, 83/02/24, 8303080070.

8303080345 Forwards LER 83-006/03L-0. Detailed event analysis encl.
MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA, E. J. Northeast Utilities. 83/02/24.
HAYNES, R. C. Region 1, Office of Director. 2pp. 17453:217. 24X Fiche. 50-245, 83/02/24, 8303080345.

--8303080354 LER 83-006/03L-0 on 830125, switch 261-16B tripped high during steam tunnel high temp functional test. Caused by setpoint drift. Switch recalibr.
THULL, T. S. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/02/24. Region 1, Office of Director. 1p.
17453:219. 24X Fiche. 50-245, 83/02/24, 8303080345.

8303140253 Forwards LER 83-004/03L-0. Detailed event analysis encl.
MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA, E. J. Northeast Utilities. 83/03/03.
HAYNES, R. C. Region 1, Office of Director. 2pp. 17538:330. 24X Fiche. 50-245, 83/03/03, 8303140253.

--8303140263 LER 83-004/03L-0 on 830207, while performing diesel generator operational readiness demonstration, generator failed to start. Caused by failure of air start solenoids to open. Piston assemblies cleaned & reassembled.
THULL, T. S. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/03/07. Region 1, Office of Director. 1p.
17538:332. 24X Fiche. 50-245, 83/03/03, 8303140253.

8303140393 Forwards LER 83-003/03L-0. Detailed event analysis encl.
MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA, E. J. Northeast Utilities. 83/03/03.
HAYNES, R. C. Region 1, Office of Director. 2pp. 17542:127. 24X Fiche. 50-245, 83/03/03, 8303140393.

--8303140394 LER 83-003/03L-0 on 830203, Meletron Model 372 pressure switch 263-39A failed to trip within allowable setpoint range. Caused by setpoint drift. Switch recalibr.
THULL, T. S. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/03/03. Region 1, Office of Director. 1p.
17542:129. 24X Fiche. 50-245, 83/03/03, 8303140393.

8303180340 Forwards LER 83-007/03L-0. Detailed event analysis encl.
MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA, E. J. Northeast Utilities. 83/03/11.
HAYNES, R. C. Region 1, Office of Director. 2pp. 17619:282. 24X Fiche. 50-245, 83/03/11, 8303180340.

--8303180343 LER 83-007/03L-0 on 830216, while performing MSIV closure functional test, 1-MS-2C failed to de-energize relay 390-102D at 10% closed position. Cause unknown. MSIV 1-MS-2C will be inspected & reworked during next cold shutdown.
THULL, T. S. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/03/11. Region 1, Office of Director. 1p.
17619:284. 24X Fiche. 50-245, 83/03/11, 8303180340.

8303240572 Forwards LER 83-008/03L-0. Detailed event analysis encl.
MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA, E. J. Northeast Utilities. 83/03/15.
HAYNES, R. C. Region 1, Office of Director. 2pp. 17683:165. 24X
Fiche: 50-245, 83/03/15, 8303240572.

--8303240581 LER 83-008/03L-0 on 830215, while performing isolation condenser isolation instrument functional & calibr test, pressure switch 1350B tripped above allowable setpoint. Caused by setpoint drift. Pressure switch recalibr.
THULL, T. S. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/03/15. Region 1, Office of Director. 1p. 17683:167. 24X Fiche: 50-245, 83/03/15, 8303240581.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8303110252 Advises that full-scale radiological emergency preparedness exercise planned for 830308, per Section IV.F of App E to 10CFR50.
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 82/11/09.
NOVAK, T. M. Assistant Director for Operating Reactors. 2pp. 17520:053. 24X Fiche: 50-003, 82/11/09, 8303110252.

8303230047 Forwards schedule of activities associated w/830309 full-scale emergency preparedness exercise.
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/02/23.
HAYNES, R. C. Region 1, Office of Director. 6pp. 17665:041. 24X Fiche: 50-003, 83/02/23, 8303230047.

8303230422 Notification of contract execution, Mod 3 to "Indian Point Fire Risk Analysis." Contractor: NBS.
FLEENOR, C. Technical Assistance Contracts Branch. NRC-03-82-122. 83/02/24. SPEIS, T. P. Division of Safety Technology. BUCHBINDER, B. NRC - No Detailed Affiliation Given. 1p. 17674:170. 24X Fiche: 50-247, 83/02/24, 8303230422.

--8303230430 Mod 3, extending period of performance to 830415, to "Indian Point Fire Risk Analysis."
SHREVE, D. B. Commerce, Dept. of, National Bureau of Standards.
GUSTAVE, R. P. Division of Contracts. NRC-03-82-122. 83/02/24. 1p. 17674:171. 24X Fiche: 50-247, 83/02/24, 8303230422.

8303150378 Forwards FEMA 830307 ltr to NRC, updating status of pre-exercise activities re 830309 emergency planning exercise.
HASSELL, D. F. Hearing Branch 1. 83/03/11. GLEASON, J. P. SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel. 4pp. 17562:028. 24X Fiche: 50-247, 83/03/11, 8303150378.

8303300317 Forwards IE Insp Rept 50-247/83-06 on 830201-0301. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/16.
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 2pp. 17734:207. 24X Fiche: 50-247, 83/03/16, 8303300317.

G. Adjudicatory correspondence

8303010605 Motion for ASLB order directing that Parents Concerned About Indian Point be permitted to present witnesses at hearings in Croton-on-Hudson during wk of 830314.
RODRIGUEZ, P. Parents Concerned About Indian Point. 83/02/22. Atomic Safety and Licensing Board Panel. 2pp. 17336:265. 24X Fiche: 50-247, 83/02/22, 8303010605.

8303010141 Telecopy message of order addressing NY City Council testimony. Testimony must address issue of adequacy of offsite emergency plans. Other testimony stricken or partially admissable as listed.
GLEASON, J. P. Atomic Safety and Licensing Board Panel. 83/02/25. New York, NY. 5pp. 17345:022. 24X Fiche: 50-247, 83/02/25, 8303010141.

8303010151 Order directing NY PIRG 830222 motion for discovery to permit entry on land controlled by licensee to appropriate ASLB.
CHILK, S. J. Office of the Secretary of the Commission. 83/02/25. Public Interest Research Group, New York. 1p. 17336:003. 24X Fiche: 50-247, 83/02/25, 8303010151.

8303020026 Memorandum re scheduling of testimony under Commission Questions 3 & 4. Proposal in PASNY 830207 motion to establish schedule & limit scope should be adopted. Certificate of Svc encl. Related correspondence.
MORGAN, C. Power Authority of the State of New York. MORGAN, C. Morgan Associates. 83/02/25. 25pp. 17352:264. 24X Fiche: 50-247, 83/02/25, 8303020026.

8303020046 Notice of D Gurin, J Friedman & R McCarthy 830228 deposition in New York, NY re testimony on Commission Questions 3 & 4. Related Correspondence.
BRANDENBURG, B. Consolidated Edison Co. of New York, Inc. MORGAN, C. Power Authority of the State of New York. MORGAN, C. Morgan Associates. 83/02/25. 2pp. 17354:273. 24X Fiche: 50-247, 83/02/25, 8303020046.

--8303020052 Notice of S Meshnick 830226 deposition in New York, NY re testimony on Commission Questions 3 & 4. Certificate of Svc encl.
BRANDENBURG, B. Consolidated Edison Co. of New York, Inc.
MORGAN, C. Power Authority of the State of New York. MORGAN, C. Morgan Associates. 83/02/25. 6pp. 17354:275. 24X Fiche: 50-247, 83/02/25, 8303020046.

8303020061 Memorandum & order memorializing 830224 conference call re licensee motions to strike NY City Council member prefiled testimony on Commission Questions 3 & 4. Testimony on listed issue accepted. Other testimony rejected.
GLEASON, J. P. Atomic Safety and Licensing Board Panel. 83/02/25. 4pp. 17352:139. 24X Fiche: 50-247, 83/02/25, 8303020061.

8303030433 Motion for extension of deadlines of investigatory hearings to complete record on emergency planning issues in Commission Questions 3 & 4. Addl time necessary to provide complete record.
POTTERFIELD, A. Public Interest Research Group, New York.
POTTERFIELD, A. Union of Concerned Scientists. POTTERFIELD, A. Parents Concerned About Indian Point. 83/02/28. Commissioners. 3pp. 17410:110. 24X Fiche: 50-247, 83/02/28, 8303030433.

8303070110 Motion to strike SR Meshnik prefiled testimony under Commission Questions 3 & 4. Testimony fails to discuss probability of type of accident presumed in testimony. Certificate of Svc encl.
BRANDENBURG, B. Consolidated Edison Co. of New York, Inc. MORGAN, C. Power Authority of the State of New York. MORGAN, C. Morgan Associates. 83/02/28. Atomic Safety and Licensing Board Panel. 9pp. 17432:337. 24X Fiche: 50-247, 83/02/28, 8303070110.

8303070113 Motion to amend svc list to change A Potterfield address.
POTTERFIELD, A. Public Interest Research Group, New York. 83/02/28. Atomic Safety and Licensing Board Panel. 1p. 17430:312. 24X Fiche: 50-247, 83/02/28, 8303070113.

8303070161 Memorandum re scheduling of testimony on Commission Questions 3 & 4.
POTTERFIELD, A. Public Interest Research Group, New York. 83/02/28. 48pp. 17433:155. 24X Fiche: 50-247, 83/02/28, 8303070161.

8303040470 Forwards revs to Westchester County radiological emergency plan. W/o encl. Certificate of Svc encl. Related correspondence.
FEINBERG, J. D. New York, State of, Energy Office. 83/03/01.
GLEASON, J. P., SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel. 4pp. 17373:319. 24X Fiche: 50-247, 83/03/01, 8303040470.

8303070125 Notice of S Sholly & other unidentified witnesses deposition re testimony on Commission Question 5. Certificate of Svc encl.
BRANDENBURG, B. Consolidated Edison Co. of New York, Inc.
COLARULLI, P. F. Power Authority of the State of New York.
COLARULLI, P. F. Morgan Associates. 83/03/01. 6pp. 17433:356. 24X Fiche: 50-247, 83/03/01, 8303070125.

8303070134 Notice of F Rowsome, R Blond & other unidentified witnesses deposition re testimony on Commission Question 5. Certificate of Svc encl.
BRANDENBURG, B. Consolidated Edison Co. of New York, Inc.
COLARULLI, P. F. Power Authority of the State of New York.
COLARULLI, P. F. Morgan Associates. 83/03/01. 6pp. 17432:350. 24X Fiche: 50-247, 83/03/01, 8303070134.

8303090287 Presents Resolution 159, memorializing County request that NY Governor Cuomo direct NY State Ofc of Disaster Preparedness not to impose state radiological evacuation plan on Rockland County.
SEIGERMAN, V. K. Rockland County, NY. 83/03/01. NRC - No Detailed Affiliation Given. 2pp. 17492:154. 24X Fiche: 50-247, 83/03/01, 8303090287.

8303090293 Presents Resolution 156 directing Rockland County not to participate in four-county radiological response drill.
SEIGERMAN, V K. Rockland County, NY. 83/03/01. NRC - No Detailed Affiliation Given. 2pp. 17492:148. 24X Fiche: 50-247, 83/03/01, 8303090293.

8303110192 Clarifies & documents independence from issues re probabilistic safety study, before being engaged as ASLB technical consultant.
AMICO, P J. Applied Risk Technology Corp. 83/03/01. GLEASON, J P., SHON, F J., PARIS, O H. Atomic Safety and Licensing Board Panel. 1p. 17520:138. 24X Fiche: 50-247, 83/03/01, 8303110192.

8303040623 Schedule for rebuttal testimony on source terms, submitted per ASLB 830216 order. Testimony of R Bernero will be filed on 830322. R Bernero will be available for cross-examination on 830405. Certificate of Svc encl.
MOORE, J E. Hearing Branch 1. 83/03/03. 5pp. 17374:231. 24X Fiche: 50-247, 83/03/03, 8303040623.

8303090314 Notice of appearance in proceeding. Certificate of Svc encl.
TOLSON, J G. Power Authority of the State of New York. 83/03/03. 4pp. 17471:125. 24X Fiche: 50-247, 83/03/03, 8303090314.

8303090321 Supplemental response to 820621 interrogatories on Contention 6.2, transmitting form for recording continuous type releases. Certificate of Svc encl.
PRATT, C. Power Authority of the State of New York. PRATT, C. Morgan Associates. 83/03/03. Parents Concerned About Indian Point. 8pp. 17473:204. 24X Fiche: 50-247, 83/03/03, 8303090321.

8303070142 Recommended decision re fair & efficient method for receiving evidence on Commission Questions 3 & 4 to accomplish expedited hearing schedule.
LAURENSON, J A. Atomic Safety and Licensing Board Panel. 83/03/04. 19pp. 17430:313. 24X Fiche: 50-247, 83/03/04, 8303070142.

8303080109 Motion to compel further responses from Greater NY Council on Energy to first set of interrogatories & to document requests under Commission Question 6. Certificate of Svc encl. Related correspondence.
BRANDENBURG, B. Consolidated Edison Co. of New York, Inc. PRATT, C M. Power Authority of the State of New York. PRATT, C M. Morgan Associates. 83/03/04. Atomic Safety and Licensing Board Panel. 31pp. 17458:141. 24X Fiche: 50-247, 83/03/04, 8303080109.

8303090319 Discusses FIRG of NY 830222 motion for State of NY to preserve & produce documents re 830309 exercise. Revs of offsite emergency plans sent to all parties w/o offsite scenario for 830224 training session. W/Certificate of /
FEINBERG, J D. New York, State of, Energy Office. 83/ / 04.
POTTERFIELD, A. Public Interest Research Group, New York. 5pp. 17473:212. 24X Fiche: 50-247, 83/03/04, 8303090319.

8303090329 Forwards radiological offsite emergency revs, inadvertently omitted from revs supplied to FEMA on 820722. Matls should be incorporated into NY State proposed Exhibit 6.
FEINBERG, J D. New York, State of, Energy Office. 83/03/04.
GLEASON, J P., SHON, F J., PARIS, O H. Atomic Safety and Licensing Board Panel. 25pp. 17473:179. 24X Fiche: 50-247, 83/03/04, 8303090329.

8303090307 Telecopy memorandum & order delineating schedule for hearing on Commission Questions 3 & 4.
GLEASON, J P. Atomic Safety and Licensing Board Panel. 83/03/07. 1p. 17471:238. 24X Fiche: 50-247, 83/03/07, 8303090307.

8303090376 Order amending svc list, changing A Potterfield address & deleting alternate ASLB member JA Laurenson.
GLEASON, J P. Atomic Safety and Licensing Board Panel. 83/03/07. 1p. 17472:131. 24X Fiche: 50-247, 83/03/07, 8303090376.

8303100232 Delineates job responsibilities as independent consultant to ASLB on PRA.
GLEASON, J P. Atomic Safety and Licensing Board Panel. 83/03/07.
AMICO, P J. Applied Risk Technology Corp. 1p. 17485:292. 24X Fiche: 50-247, 83/03/07, 8303100232.

8303100242 Opposes schedule for hearing evacuation planning testimony of six intervenors in 5 days.
RODRIGUEZ, P. Parents Concerned About Indian Point. 83/03/07. Commissioners. 1p. 17485:296. 24X Fiche: 50-247, 83/03/07, 8303100242.

8303100238 Notice of appearance in proceeding.
SANOFF, B L. Consolidated Edison Co. of New York, Inc. *Kronish, Lieb, Shainswit, Weiner & Hillman. 83/03/08. 1p. 17485:293. 24X Fiche: 50-247, 83/03/08, 8303100238.

8303100261 Expresses strong & vehement objections to scheduling order allowing Rockland County only 1/2 day to present testimony. Three full days needed.
THORSEN, E D., PARRIS, M L. Rockland County, NY. 83/03/08.
PALLADINO, N J. Commissioners. 1p. 17490:304. 24X Fiche: 50-247, 83/03/08, 8303100261.

8303100271 Motion for mod of ASLB 830307 order adopting alternate ASLB member Laurenson recommended decision on scheduling. Ruling should be clarified re time to hear post-exercise FEMA testimony. Certificate of Svc encl.
BRANDENBURG, B. Consolidated Edison Co. of New York, Inc. 83/03/08. Atomic Safety and Licensing Board Panel. 10pp. 17490:288. 24X Fiche: 50-247, 83/03/08, 8303100271.

8303110198 Memorandum & order clarifying 830207 order. Deletion of mention of public util employees in reformulated Contention 3.2 does not exclude consideration of response of employees during emergency.
GLEASON, J P. Atomic Safety and Licensing Board Panel. 83/03/08. 2pp. 17517:361. 24X Fiche: 50-247, 83/03/08, 8303110198.

8303140335 Motion to strike UCS, PIRG of NY & Parents Concerned About Indian Point witness KT Erikson 830221 supplemental testimony. Testimony is beyond scope of Commission questions & is based on inadmissible hearsay. Certificate of Svc encl.
MORGAN, C. Power Authority of the State of New York. MORGAN, C. Morgan Associates. 83/03/08. Atomic Safety and Licensing Board Panel. 10pp. 17534:207. 24X Fiche: 50-247, 83/03/08, 8303140335.

8303140343 Motion to modify & clarify ASLB order on schedule for hearing Commission Questions 3 & 4. Arbitrary limits on cross-examination prejudicing parties should be rejected. Use of panels should be clarified. Certificate of Svc encl.
MORGAN, C. Power Authority of the State of New York. MORGAN, C. Morgan Associates. 83/03/08. Atomic Safety and Licensing Board Panel. 10pp. 17534:233. 24X Fiche: 50-247, 83/03/08, 8303140343.

8303100277 Response opposing intervenor 830228 motion for extension of deadlines to complete record on emergency planning issues in Commission Questions 3 & 4. ASLB resolved scheduling question. Certificate of Svc encl.
BRANDENBURG, B. Consolidated Edison Co. of New York, Inc.
COLARULLI, P F. Power Authority of the State of New York.
COLARULLI, P F. Morgan Associates. 83/03/09. Commissioners. 32pp. 17490:252. 24X Fiche: 50-247, 83/03/09, 8303100277.

8303150393 Motion to strike KT Erikson 830221 supplemental testimony. Testimony irrelevant to any issue before ASLB & is unreliable hearsay which would preclude cross-examination by licensees. Certificate of Svc encl.
BRANDENBURG, B. Consolidated Edison Co. of New York, Inc. 83/03/09. Atomic Safety and Licensing Board Panel. 8pp. 17561:355. 24X Fiche: 50-247, 83/03/09, 8303150393.

8303150378 Forwards FEMA 830307 ltr to NRC, updating status of pre-exercise activities re 830309 emergency planning exercise.
HASSELL, D F. Hearing Branch 1. 83/03/11. GLEASON, J P., SHON, F J., PARIS, O H. Atomic Safety and Licensing Board Panel. 4pp. 17562:028. 24X Fiche: 50-247, 83/03/11, 8303150378.

8303150408 Motion to amend svc list to include AP O'Rourke, new Westchester County executive. Certificate of Svc encl.
VETERE, L A. Westchester County, NY. 83/03/11. Atomic Safety and Licensing Board Panel. 2pp. 17561:263. 24X Fiche: 50-247, 83/03/11, 8303150408.

8303150415 Intervenors joint list of witnesses to be presented on 830315-18 & 22 re Commission Questions 3 & 4.
* Union of Concerned Scientists. * Public Interest Research Group, New York. * Parents Concerned About Indian Point. 83/03/11. 3pp. 17561:245. 24X Fiche: 50-247, 83/03/11, 8303150415.

8303170279 Motion to strike certain intervenor prefiled testimony under Commission Questions 3 & 4 re emergency planning filed on 830311. Licensees denied any meaningful right to discovery from witnesses. Certificate of Svc encl.
BRANDENBURG, B. Consolidated Edison Co. of New York, Inc. 83/03/14. Atomic Safety and Licensing Board Panel. 33pp. 17606:019. 24X Fiche: 50-247, 83/03/14, 8303170279.

8303180144 Forwards intervenor refined witness list for Commission Questions 3 & 4 for presentation on 830315-18 & 22. List does not include witnesses subj to stipulation by licensees & NRC.
POTTERFIELD, A. Public Interest Research Group, New York.
POTTERFIELD, A. Parents Concerned About Indian Point. POTTERFIELD, A. Westchester Peoples Action Coalition, Inc. 83/03/14. 4pp. 17617:275. 24X Fiche: 50-247, 83/03/14, 8303180144.

8303180217 Answer opposing PASNY motion to strike KT Erikson testimony. Testimony relevant to Contentions 3.2 & 3.7 & is based on Erikson personal knowledge.
POTTERFIELD, A. Public Interest Research Group, New York
POTTERFIELD, A. Union of Concerned Scientists POTTERFIELD, A. Parents Concerned About Indian Point 83/03/14 Atomic Safety and Licensing Board Panel 15pp. 17618:078 24X Fiche: 50-247, 83/03/14, 8303180217.

--8303180227 Response opposing licensee motion to compel Greater NY Council on Energy further response to interrogatories. Motion inappropriate & unnecessary. Interrogatories were unclear & burdensome. Certificate of Svc encl.
CORREN, D. R. Greater New York Council on Energy 83/03/14 Atomic Safety and Licensing Board Panel 6pp. 17618:093 24X Fiche: 50-247, 83/03/14, 8303180217.

8303180235 Motion to strike selected intervenor testimony. Objects to intervenor 830311 witness list for Commission Questions 3 & 4, presenting 99 witnesses in 5 days. Testimony is cumulative, conclusory, hearsay or w/o foundation. W/Certificate of Svc.
MORGAN, C. Power Authority of the State of New York MORGAN, C. Morgan Associates 83/03/14 Atomic Safety and Licensing Board Panel 16pp. 17621:121 24X Fiche: 50-247, 83/03/14, 8303180235.

8303180245 Motion for waiver of requirement to distribute Indian Point 3 emergency plan & emergency planning implementation procedures document to all parties. Plans are voluminous & expensive to produce.
MORGAN, C. Power Authority of the State of New York MORGAN, C. Morgan Associates 83/03/14 Atomic Safety and Licensing Board Panel 4pp. 17621:099 24X Fiche: 50-247, 83/03/14, 8303180245.

8303180277 Motion to compel West Branch Conservation Assoc & Parents Concerned About Indian Point further responses to licensee first set of interrogatories under Commission Question 6. W/ Certificate of Svc. Related correspondence.
BRANDENBURG, B. Consolidated Edison Co. of New York, Inc. PRATT, C. M. Power Authority of the State of New York PRATT, C. M. Morgan Associates 83/03/14 Atomic Safety and Licensing Board Panel 36pp. 17616:125 24X Fiche: 50-247, 83/03/14, 8303180277.

8303180393 Requests ASLB direct PJ Amico, independent consultant to ASLB, to file complete resume. Amico 830301 ltr raises questions of independence which must be resolved.
WEISS, E. R. Union of Concerned Scientists 83/03/14 GLEASON, J. P., SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel 3pp. 17621:348 24X Fiche: 50-247, 83/03/14, 8303180393.

8303180029 Response opposing intervenor 830228 motion for extension of deadlines to complete record on emergency planning issues in Commission Questions 3 & 4. Intervenors fail to establish why current schedule should be changed. W/Certificate of Svc.
MOORE, J. E. Hearing Branch 1 83/03/16 Commissioners 9pp. 17618:069 24X Fiche: 50-247, 83/03/16, 8303180029.

8303220261 Informs of licensee understanding of status of addl mitigation testimony. Licensees will file one piece of testimony addressing all NRC post-Question 2 mitigation measures when NRC completes filings.
BRANDENBURG, B. Consolidated Edison Co. of New York, Inc.
COLARULLI, P. F. Power Authority of the State of New York
COLARULLI, P. F. Morgan Associates 83/03/16 GLEASON, J. P., SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel 8pp. 17656:180 24X Fiche: 50-247, 83/03/16, 8303220261.

8303220231 Motion for waiver of exhibit distribution of draft "Methodology to Calculate Evacuation Travel Time Estimates for Indian Point Emergency Planning Zone." Nov 1981 Rept voluminous. Copying would be costly. Certificate of Svc encl.
BRANDENBURG, B. Consolidated Edison Co. of New York, Inc. MORGAN, C. Power Authority of the State of New York MORGAN, C. Morgan Associates 83/03/17 Atomic Safety and Licensing Board Panel 8pp. 17657:300 24X Fiche: 50-247, 83/03/17, 8303220231.

8303230176 Motion to impose sanctions against D Corren & R Rosen of Greater NY Council on Energy & Energy Sys Research Group, Inc for failure to respond to interrogatories. Certificate of Svc encl.
BRANDENBURG, B. Commonwealth Edison Co. PRATT, C. M. Power Authority of the State of New York PRATT, C. M. Morgan Associates 83/03/17 Atomic Safety and Licensing Board Panel 19pp. 17665:240 24X Fiche: 50-247, 83/03/17, 8303230176.

--8303230179 Affidavit of CM Pratt supporting licensee motion to impose sanctions on D Corren & R Rosen of Greater NY Council on Energy & Energy Sys Research Group, Inc for failure to respond to interrogatories. Document request encl.
PRATT, C. M. Power Authority of the State of New York 83/03/17 3pp. 17665:270 24X Fiche: 50-247, 83/03/17, 8303230176.

8303220272 Forwards "Economics of Closing Indian Point Nuclear Power Plants," sent to util on 830317. W/o encl. Related correspondence.
PRATT, C. M. Power Authority of the State of New York 83/03/18
GLEASON, J. P., SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel 1p. 17656:188 24X Fiche: 50-247, 83/03/18, 8303220272.

8303230207 Motion for time to present evidence re 830309 radiological emergency response planning exercise. Presentation needed to complete record. Certificate of Svc encl.
POTTERFIELD, A. Public Interest Research Group, New York POSNER, P. Parents Concerned About Indian Point 83/03/18 Atomic Safety and Licensing Board Panel 18pp. 17665:194 24X Fiche: 50-247, 83/03/18, 8303230207.

8303230238 Proposed order of testimony. Affidavit of Svc encl. Related correspondence.
PASELTINER, E. Affiliation Unknown 83/03/18 3pp. 17662:003 24X Fiche: 50-247, 83/03/18, 8303230238.

8303240601 Cross-examination plan for wk commencing 830322. County will cross-examine D Davidoff representing NY State & Parsons, Brinckerhoff, Quade & Douglas representing licensees. Affidavit of Svc encl.
* Rockland County, NY 83/03/21 4pp. 17683:060 24X Fiche: 50-247, 83/03/21, 8303240601.

8303310303 Motion to strike portions of testimony of some Rockland County witnesses on Questions 3 & 4. Testimony conclusory & w/o supporting factual basis. Foundation does not exist for factual matl introduction. Certificate of Svc encl.
BRANDENBURG, B. Consolidated Edison Co. of New York, Inc. 83/03/21. Atomic Safety and Licensing Board Panel 6pp. 17755:015 24X Fiche: 50-247, 83/03/21, 8303310303.

8303240399 Order amending svc list by adding AP O'Rourke, Westchester County Executive.
GLEASON, J. P. Atomic Safety and Licensing Board Panel 83/03/22 1p. 17679:062 24X Fiche: 50-247, 83/03/22, 8303240399.

8303300303 Notice of 830330 deposition of R Rosen & other witnesses testifying on behalf of Greater NY Counsil on Energy on Commission Question 6, in New York, NY. Related correspondence.
SANOFF, B. Consolidated Edison Co. of New York, Inc. PRATT, C. M. Power Authority of the State of New York 83/03/22 2pp. 17735:133 24X Fiche: 50-247, 83/03/22, 8303300303.

--8303300307 Notice of B Commoner & R Schrader 830324 deposition in New York, NY re testimony under Commission Question 6. Related correspondence.
SANOFF, B. Consolidated Edison Co. of New York, Inc. PRATT, C. M. Power Authority of the State of New York 83/03/22 2pp. 17735:135 24X Fiche: 50-247, 83/03/22, 8303300303.

--8303300313 Notice of DA Schlissel 830413 deposition in New York, NY re testimony under Commission Question 6. Related correspondence.
SANOFF, B. Consolidated Edison Co. of New York, Inc. PRATT, C. M. Power Authority of the State of New York 83/03/22 2pp. 17735:137 24X Fiche: 50-247, 83/03/22, 8303300303.

--8303300319 Notice of deposition of V Taylor & all other witnesses testifying on behalf of UCS/PIRG of NY & Greater NY Counsil on Energy on Commission Question 6, in New York, NY. Related correspondence.
SANOFF, B. Consolidated Edison Co. of New York, Inc. PRATT, C. M. Power Authority of the State of New York 83/03/22 2pp. 17735:139 24X Fiche: 50-247, 83/03/22, 8303300303.

--8303300322 Notice of deposition of witnesses testifying on behalf of NRC on Commission Question 6. Certificate of Svc encl. Related correspondence.
SANOFF, B. Consolidated Edison Co. of New York, Inc. PRATT, C. M. Power Authority of the State of New York 83/03/22 5pp. 17735:141 24X Fiche: 50-247, 83/03/22, 8303300303.

8303300326 Notice of deposition of all persons testifying for Parents Concerned About Indian Point on Commission Question 6. Certificate of Svc encl. Related correspondence.
SANOFF, B. Consolidated Edison Co. of New York, Inc. PRATT, C. M. Power Authority of the State of New York 83/03/22 5pp. 17735:128 24X Fiche: 50-247, 83/03/22, 8303300326.

8303300374 Suppl to motion to impose sanctions against D Corren, Greater NY Council on Energy & Energy Sys Research Group, Inc for failure to produce Oct 1982 study, "Economics of Closing Indian Point Nuclear Power Plants." Related correspondence.
SANOFF, B. Consolidated Edison Co. of New York, Inc. PRATT, C. M. Power Authority of the State of New York 83/03/23 Atomic Safety and Licensing Board Panel 17pp. 17731:033 24X Fiche: 50-247, 83/03/23, 8303300374.

8303300489 Forwards Energy Sys Research Group, Inc Oct 1982 study & study received in Mar 1983, supporting licensee motion to impose sanctions. Nonproduction of study prejudicial to licensees. Discovery should be allowed on nonproduction.
PRATT, C. M. Power Authority of the State of New York 83/03/24
GLEASON, J. P. ; SHON, F. J. ; PARIS, O. H. Atomic Safety and Licensing Board Panel 2pp 17731:148 24X Fiche: 50-247, 83/03/24, 8303300489

8303300417 Requests permission to file supplemental responsive testimony through 830416 re matters raised in prospective NY City Council witness DA Schlissel 830413 deposition. Related correspondence.
PRATT, C. M. Power Author ty of the State of New York 83/03/25
GLEASON, J. P. ; SHON, F. J. ; PARIS, O. H. Atomic Safety and Licensing Board Panel 2pp 17731:079 24X Fiche: 50-247, 83/03/25, 8303300417

8303300494 Forwards UCS/PIRG of NY Exhibit 16 addressing info needs of non-English speakers in 10-mile emergency planning zone, per A Potterfield request at 830323 hearing.
FEINBERG, J. D. New York, State of, Energy Office 83/03/25
GLEASON, J. P. ; SHON, F. J. ; PARIS, O. H. Atomic Safety and Licensing Board Panel 5pp 17731:139 24X Fiche: 50-247, 83/03/25, 8303300494

8303310300 Telecopy order ruling on util motions to compel responses from intervenors & motion for sanctions against Greater NY Council on Energy. Util request to depose D Corren & A Rosen granted to determine if Council aware of cost study rept.
GLEASON, J. P. Atomic Safety and Licensing Board Panel 83/03/29
Consolidated Edison Co. of New York, Inc. 2pp 17756:031 24X
Fiche: 50-247, 83/03/29, 8303310300

H. General correspondence

8303030345 Responds to concerns re transportation of radwaste in & through Putnam County, NY. W/o encl. FR notices for 10CFR71.73, 73.21, NUREG-0794 & NUREG-0923.
HAYNES, R. C. Region 1, Office of Director 83/03/25 BRAATZ, R. L. Putnam County, NY 2pp 17410:032 24X Fiche: 50-247, 83/02/25, 8303030345

--8303030350 Requests info re transportation of nuclear waste in & through Putnam County, NY.
BRAATZ, R. L. Putnam County, NY 83/02/10 Region 1, Office of Director 1p 17410:034 24X Fiche: 50-247, 83/02/25, 8303030345

P. Operating license stage documents & correspondence

8303010385 Forwards application for amend to License DPR-26, changing Tech Specs Sections 1, 2, 3, 4, 5 & 6 to address generic & plant-specific areas, in response to NRC requests. Affidavit of Svc encl.
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/02/14
VARGA, S. A. Operating Reactors Branch 1 3pp 17344:148 24X
Fiche: 50-247, 83/02/14, 8303010385

--8303010395 Application for amend to License DPR-26, changing Tech Specs Sections 1, 2, 3, 4, 5 & 6 to address generic & plant-specific areas, in response to NRC requests.
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/02/14
2pp 17344:151 24X Fiche: 50-247, 83/02/14, 8303010385

--8303010397 Proposed changes to Tech Specs Sections 1, 2, 3, 4, 5 & 6 to address generic & plant-specific areas, in response to NRC requests. Safety assessment encl.
* Consolidated Edison Co. of New York, Inc. 83/02/28 139pp
17344:153 24X Fiche: 50-247, 83/02/14, 8303010385

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X
Fiche: 50-000, 83/02/16, 8302170082

8303080312 Forwards response to 820907 request for clarification of capabilities & limitations of variable setpoint low temp overpressure protection sys Tech Spec change request dtd 830214 submitted due to revs to heatup & cooldown curves.
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/02/25
VARGA, S. A. Operating Reactors Branch 1 15pp 17449:335 24X
Fiche: 50-247, 83/02/25, 8303080312

8303140215 Confirms original 821223 commitment to complete NUREG-0737, Item II.B.3 activities by 830331. Final design details for post-implementation review of post-accident sampling sys will be submitted by 830601.
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/03/01
VARGA, S. A. Operating Reactors Branch 1 1p 17540:079 24X
Fiche: 50-247, 83/03/01, 8303140215

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005

8303210538 Forwards United Engineers & Constructors containment seismic design calculations & revised probabilistic safety study c[illegible]lations by Structural Mechanics Assoc to determine ca.acity of containments.
PERLA, H. F. Pickard, Lowe & Garrick, Inc. 83/03/14 HANNON, J. NRC - No L.tailed Affiliation Given 140pp 17630:266 24X
Fiche: 50-247, 83/03/14, 8303210538

8303290009 Forwards order confirming commitments on post-TMI related issues per NUREG-0737. Proposed schedule exceptions & delays acceptable. Order based on commitments per responses to Generic Ltrs 82-05 & 82-10.
VARGA, S. A. Operating Reactors Branch 1 83/03/18 O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 3pp 17730:043 24X
Fiche: 50-247, 83/03/18, 8303290009

--8303290011 Order confirming licensee commitments on post-TMI related issues per NUREG-0737.
PURPLE, R. A. Division of Licensing 83/03/18 Consolidated Edison Co. of New York, Inc. 9pp 17730:046 24X
Fiche: 50-247, 83/03/18, 8303290009

8303290498 Forwards response to Generic Ltr 82-28, "Inadequate Core Cooling Instrumentation Sys." Guidance items addressed can only be carried out in conjunction w/NUREG-0737, Suppl 1. Subcooling margin monitor installed per NUREG-0578.
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/03/23
VARGA, S. A. Operating Reactors Branch 1 17pp 17724:063 24X
Fiche: 50-247, 83/03/23, 8303290498

Q. Inspection reports, IE Bulletins & correspondence

0212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11lpp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367

8303080327 Forwards response to questions re inservice insp program. Addl provisions re duration & temp of hydrostatic tests & QA program controls applicable to pump & valve testing program encl.
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/02/25
VARGA, S. A. Operating Reactors Branch 1 10pp 17447:353 24X
Fiche: 50-247, 83/02/25, 8303080327

8303150602 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Reactor protection logic channel functional test successfully performed on 830225.
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/03/07
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 5pp 17567:293 24X Fiche: 50-247, 83/03/07, 8303150602

8303240418 Forwards response to Action Item 4 of IE Bulletin 82-02, "Degradation of Threaded Fastners in RCPB of PWR Plants." Insp program for threaded fastners in sys containing borated water will be continued through next refueling outage.
O'TOOLE, R. C. Consolidated Edison Co. of New York, Inc. 83/03/08
HAYNES, R. C. Region 1, Office of Director 7pp 17678:290 24X
Fiche: 50-247, 83/03/08, 8303240418

8303240518 Forwards IE Insp Rept 50-247/83-07 on 830214-18. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs 83/03/09
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 2pp
17682:255 24X Fiche: 50-247, 83/03/09, 8303240518

--8303240528 IE Insp Rept 50-247/83-07 on 830214-18. No noncompliance noted. Major areas inspected: review of Cycle 6 startup physics test program & results & facility tours.
PULLANI, S. V. ; WEN, P. ; NORRHOLM, L. J. Region 1, Office of Director 83/03/04 11pp 17682:257 24X Fiche: 50-247, 83/03/09, 8303240518

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303290337 Forwards IE Insp Rept 50-247/83-04 on 830131-0204 & notice of violation.
MARTIN, T. T. Region 1, Office of Director. 83/03/15. O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 2pp. 17716:242. 24X Fiche: 50-247, 83/03/15, 8303290337.

--8303290340 Notice of violation from insp on 830131-0204.
* Region 1, Office of Director. 83/03/15. 2pp. 17716:244. 24X Fiche: 50-247, 83/03/15, 8303290337.

--8303290346 IE Insp Rept 50-247/83-04 on 830131-0204 Noncompliance noted: inadequate control of procedures & drawings.
BLUMBERG, N. J. Region 1, Office of Director. CAPHTON, D. L. Division of Engineering & Technical Programs. 83/03/03. 9pp. 17716:246. 24X Fiche: 50-247, 83/03/15, 8303290337.

8303300317 Forwards IE Insp Rept 50-247/83-06 on 830201-0301. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/16. O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 2pp. 17734:207. 24X Fiche: 50-247, 83/03/16, 8303300317.

--8303300321 IE Insp Rept 50-247/83-06 on 830201-0301 No noncompliance noted. Major areas inspected: licensee actions on previous findings, plant operations review, plant trips, physical security & ESF operability.
FOLEY, T., KOLTAY, P. Region 1, Office of Director. KISTER, H. Division of Project & Resident Programs. 83/03/10. 11pp. 17734:209. 24X Fiche: 50-247, 83/03/16, 8303300317.

8303300433 Forwards IE Insp Rept 50-247/83-05 on 830209-10 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/17. O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 2pp. 17731:085. 24X Fiche: 50-247, 83/03/17, 8303300433.

--8303300444 Notice of violation from insp on 830209-10.
* Region 1, Office of Director. 83/03/17. 2pp. 17731:087. 24X Fiche: 50-247, 83/03/17, 8303300433.

--8303300455 IE Insp Rept 50-247/83-05 on 830209-10 Noncompliance noted: failure to review & approve transport packaging procedures & failure to maintain records of advanced notification to waste site.
CLEMONS, P., SHANBAKY, M. Region 1, Office of Director. 83/03/14. 4pp. 17731:089. 24X Fiche: 50-247, 83/03/17, 8303300433.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 12?pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303250072 Ack receipt of 830309 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/83-01.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/21. O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 1p. 17692:331. 24X Fiche: 50-247, 83/03/21, 8303250072.

--8303250077 Responds to NRC 830207 ltr re violations noted in IE Insp Rept 50-247/83-01. Corrective actions: storage cabinet for flammable liquid properly relocated & secured & station Administrative Order 114 being revised.
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/03/09. STAROSTECKI, R. Division of Project & Resident Programs. 3pp. 17692:332. 24X Fiche: 50-247, 83/03/21, 8303250072.

8303280203 Ack receipt of 830306 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/83-02.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/23. O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 1p. 17708:191. 24X Fiche: 50-247, 83/03/23, 8303280203.

--8303280210 Responds to NRC 830204 ltr re violations noted in IE Insp Rept 50-247/83-02. Corrective actions: general employee training program expanded & revised to incorporate all station employees. Programs will be implemented by 830314.
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/03/06. MARTIN, T. T. Division of Engineering & Technical Programs. 4pp. 17708:192. 24X Fiche: 50-247, 83/03/23, 8303280203.

R. Periodic operating reports & related correspondence

8303100199 Forwards "Personnel Whole Body Exposures for CY82."
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/03/01. HAYNES, R. C. Region 1, Office of Director. 1p. 17488:358. 24X Fiche: 50-003, 83/03/01, 8303100199.

--8303100203 "Personnel Whole Body Exposures for CY82."
* Consolidated Edison Co. of New York, Inc. 83/03/01. 2pp. 17488:359. 24X Fiche: 50-003, 83/03/01, 8303100199.

8303150551 Forwards "Effluent & Waste Disposal Semiannual Rept, Third & Fourth Quarter 1982."
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/03/01. HAYNES, R. C. Region 1, Office of Director. 1p. 17568:064. 24X Fiche: 50-003, 83/03/01, 8303150551.

--8303150569 "Effluent & Waste Disposal Semiannual Rept, Third & Fourth Quarter 1982."
* Consolidated Edison Co. of New York, Inc. 83/03/01. 46pp. 17568:065. 24X Fiche: 50-003, 83/0J/01, 8303150551.

8303220291 Forwards monthly operating rept for Feb 1983.
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/03/15. MCDONALD, W. G. Division of Data Automation & Management Information. 1p. 17654:303. 24X Fiche: 50-247, 83/03/15, 8303220291.

--8303220297 Monthly operating rept for Feb 1983.
EICH, E. F. Consolidated Edison Co. of New York, Inc. 83/03/07. 7pp. 17654:304. 24X Fiche: 50-247, 83/03/15, 8303220291.

S. Reportable occurrences, LERs & related correspondence

8303140387 Forwards LER 83-002/03L-0.
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/02/24. HAYNES, R. C. Region 1, Office of Director. 1p. 17542:122. 24X Fiche: 50-247, 83/02/24, 8303140387.

--8303140390 LER 83-002/03L-0 on 830125, during full power, all 53 control RPIs shifted downscale by approx 24% Caused by anomalous condition on Westinghouse Proteus 2500 computer signal input cards during removal of ac power.
MOONEY, J. Consolidated Edison Co. of New York, Inc. 83/02/24. Region 1, Office of Director. 2pp. 17542:123. 24X Fiche: 50-247, 83/02/24, 8303140387.

8303160156 Forwards LER 83-003/01T-0.
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/02/27. HAYNES, R. C. Region 1, Office of Director. 1p. 17597:023. 24X Fiche: 50-247, 83/02/27, 8303160156.

--8303160168 LER 83-003/01T-0 on 830213, RCS leakage exceeded Tech Spec levels Caused by failed valve gland packing Valve repacked & satisfactorily tested.
HINRICH, G. Consolidated Edison Co. of New York, Inc. 83/02/27. Region 1, Office of Director. 2pp. 17597:022. 24X Fiche: 50-247, 83/02/27, 8303160156.

8303160249 RO on 830301, shaft matl found in square motor housing RHR pump 22 was carbon steel instead of stainless steel Change does not involve unreviewed safety question based on use for fewer than 24 calender months Equipment will be replaced.
JACKSON, C. W. Consolidated Edison Co. of New York, Inc. 83/03/02. HAYNES, R. C. Region 1, Office of Director. 1p. 17596:330. 24X Fiche: 50-247, 83/03/02, 8303160249.

8303240010 PNO-IE-83-004 informs of Rockland County Legislature resolutions prohibiting County officials from participating in 830309 exercise & requesting NY Governor to order plant shutdown.
CROCKER, H. W. Region 1, Office of Director. CUNNINGHAM, L. J. Director's Office, Office of Inspection and Enforcement. 83/03/07. 1p. 17681:101. 24X Fiche: 50-003, 83/03/07, 8303240010.

8303280170 Part 21 rept re transfer switches 3868180 Five transfer switches inspected & adjusted as necessary New requirements added to test & adjustment procedure to review subassemblies for proper function No other plants affected.
NAUMANN, H. R. Automatic Switch Co. 83/03/10. Region 4, Office of Director. 1p. 17706:318. 24X Fiche: 50-003, 83/03/10, 8303280170.

T. Hearing transcripts on non-antitrust matters

8303020093 Forwards supplemental testimony of SZ Gdanski, B Flicker, D Hastings, JF Kralik, DP McGuire, R Northrup, H Reisman, L Scharf & R Wein Related correspondence.
THORSEN, E. D. Rockland County, NY. 83/02/22. GLEASON, J. P., SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel. 1p. 17349:114. 24X Fiche: 50-247, 83/02/22, 8303020093.

--8303020096 Supplemental testimony of DP McGuire re emergency planning. Recent developments in preparing emergency plan discussed. Related correspondence.
MCGUIRE, D. P. Rockland County, NY 83/02/22 4pp 17349:115 24X Fiche: 50-247, 83/02/22, 8303020093

--8303020100 Supplemental testimony of H Reisman re current state of Rockland County radiological planning. If serious incident occurred, County would not be able to react to safeguard citizens or property. Related correspondence.
REISMAN, H. Rockland County, NY 83/02/22 3pp 17349:119 24X Fiche: 50-247, 83/02/22, 8303020093

--8303020105 Supplemental testimony of SZ Gdanski re Rockland County radiological planning. Expresses doubt that plan will protect health, safety & welfare of public. Related correspondence.
GDANSKI, S. Z. Rockland County, NY 83/02/22 3pp 17349:122 24X Fiche: 50-247, 83/02/22, 8303020093

--8303020110 Supplemental testimony of D Hastings re Rockland County emergency preparedness plan. Plan developing quickly. Related correspondence.
HASTINGS, D. Rockland County, NY 83/02/22 2pp 17349:125 24X Fiche: 50-247, 83/02/22, 8303020093

--8303020116 Supplemental testimony of R Northrup re Rockland County emergency plan. Evacuation of individuals who receive personal care svcs discussed. Related correspondence.
NORTHRUP, R. Rockland County, NY 83/02/22 4pp 17349:127 24X Fiche: 50-247, 83/02/22, 8303020093

--8303020120 Supplemental testimony of L Spiegel re use of buses during evacuation. No evacuation training conducted. Related correspondence.
SPIEGEL, L. Rockland County, NY 83/02/22 2pp 17349:131 24X Fiche: 50-247, 83/02/22, 8303020093

--8303020124 Supplemental testimony of JK Kralik re Rockland County emergency plan. No addl equipment or training received to implement plan. Related correspondence.
KRALIK, J. F. Rockland County, NY 83/02/22 2pp 17349:133 24X Fiche: 50-247, 83/02/22, 8303020093

--8303020126 Supplemental testimony of R Wein re evacuation of blind people. Number of blind people in crucial areas increased. Related correspondence.
WEIN, R. Rockland County, NY 83/02/22 2pp 17349:135 24X Fiche: 50-247, 83/02/22, 8303020093

--8303020130 Supplemental testimony of L Scharf re Rockland County emergency planning. County lacks info to prepare schools for emergency. Related correspondence.
SCHARF, L. Rockland County, NY 83/02/22 3pp 17349:137 24X Fiche: 50-247, 83/02/22, 8303020093

--8303020133 Supplemental testimony of B Flicker re Rockland County emergency plan. Info being gathered re evacuation of school children. Affidavit of Svc encl. Related correspondence.
FLICKER, B. Rockland County, NY 83/02/22 4pp 17349:140 24X Fiche: 50-247, 83/02/22, 8303020093

8303030017 Transcript of 830228 special conference in New York, NY. Pp 1-134.
* Atomic Safety and Licensing Board Panel 83/02/28 136pp 17412:198 24X Fiche: 50-247, 83/02/28, 8303030017

8303030211 Transcript of 830301 hearing in New York, NY. Pp 8,959-9,161. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel 83/03/01 247pp 17411:029 24X Fiche: 50-247, 83/03/01, 8303030211

8303040576 Transcript of 830302 hearing in New York, NY. Pp 9,162-9,374. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel 83/03/02 251pp 17369:322 24X Fiche: 50-247, 83/03/02, 8303040576

8303070130 Transcript of 830303 hearing in New York, NY. Pp 9,375-9,548. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel 83/03/03 224pp 17431:147 24X Fiche: 50-247, 83/03/03, 8303070130

8303100172 Forwards SA Schwartz testimony, adopting BR Grimes testimony due to change in personnel positions. Testimony not substantively changed.
HASSELL, D. F. Hearing Branch 1 83/03/08 GLEASON, J. P., SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel 1p 17485:197 24X Fiche: 50-247, 83/03/08, 8303100172

--8303100178 Testimony of SA Schwartz re emergency planning contentions on Commission Questions 3 & 4. Emergency plans consider both fair & adverse weather conditions & range of accident conditions including Class 9 accidents.
SCHWARTZ, S. A. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/08 9pp 17485:198 24X Fiche: 50-247, 83/03/08, 8303100172

8303170218 Transcript of 830315 hearing in White Plains, NY. Pp 9,549-9,805. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel 83/03/15 304pp 17606:179 24X Fiche: 50-247, 83/03/15, 8303170218

8303210567 Transcript of 830316 hearing in White Plains, NY. Pp 10,038-10,153. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel 83/03/16 130pp 17631:046 24X Fiche: 50-247, 83/03/16, 8303210567

8303210343 Transcript of 830317 hearing in White Plains, NY. Pp 10,154-10,452. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel 83/03/17 380pp 17633:018 24X Fiche: 50-247, 83/03/17, 8303210343

8303220284 Transcript of 830318 hearing in White Plains, NY. Pp 10,453-10,736. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel 83/03/18 378pp 17654:321 24X Fiche: 50-247, 83/03/18, 8303220284

8303230230 Forwards testimony of F Rowsome & R Blond re Commission Question 5 on comparative risk & of RM Bernero re severe accident source terms.
MOORE, J. E. Hearing Branch 1 83/03/22 GLEASON, J. P., SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel 1p 17661:239 24X Fiche: 50-247, 83/03/22, 8303230230

--8303230233 Testimony of F Rowsome & R Blond re Commission Question 5 on comparative risk.
ROWSOME, F. Assistant Director for Technology Review BLOND, R. Reactor Risk Branch 83/03/22 112pp 17661:240 24X Fiche: 50-247, 83/03/22, 8303230230

--8303230237 Testimony of RM Bernero re severe accident source terms. Prof qualifications encl.
BERNERO, R. M. Division of Risk Analysis 83/03/22 13pp 17661:352 24X Fiche: 50-247, 83/03/22, 8303230230

8303240545 Testimony of SC Sholly on Commission Question 5 re plant risk. Sandia siting study demonstrates Indian Point is one of very few reactor sites for which large consequences possible. Certificate of Svc encl. Related correspondence.
SHOLLY, S. C. Union of Concerned Scientists SHOLLY, S. C. Public Interest Research Group, New York 83/03/22 76pp 17682:337 24X Fiche: 50-247, 83/03/22, 8303240545

8303250145 Testimony of TE Potter on Commission Question 5 re NUREG/CR-2239, "Technical Guidance for Siting Criteria Development." NUREG should not be used alone to assess risks from existing plants. Related correspondence.
POTTER, T. E. Consolidated Edison Co. of New York, Inc. POTTER, T. E. Power Authority of the State of New York POTTER, T. E. Pickard, Lowe & Garrick, Inc. 83/03/22 19pp 17691:022 24X Fiche: 50-247, 83/03/22, 8303250145

--8303250149 Testimony of DC Bley, DF Paddleford, TE Potter & DC Richardson on Commission Question 5. Risks of plant in relation to NRC safety goals & in comparison to other plants discussed. Prof qualifications & Certificate of Svc encl.
BLEY, D. C., PADDLEFORD, D. F., POTTER, T. E. Consolidated Edison Co. of New York, Inc. 83/03/22 43pp 17691:041 24X Fiche: 50-247, 83/03/22, 8303250145

8303290374 Transcript of 830322 hearing in White Plains, NY. Pp 10,737-11,117. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel 83/03/22 614pp 17720:284 24X Fiche: 50-247, 83/03/22, 8303290374

8303300146 Transcript of 830323 hearing in White Plains, NY. Pp 11,118-11,513. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel 83/03/23 460pp 17735:316 24X Fiche: 50-247, 83/03/23, 8303300146

8303300134 Transcript of 830325 hearing in White Plains, NY. Pp 11,671-11,953. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel 83/03/25 400pp 17731:230 24X Fiche: 50-247, 83/03/25, 8303300134

U. Congressional/Executive Correspondence

8303020377 Responds to 830119 ltr re 821223 decision permitting continued interim operation w/o FEMA-approved offsite emergency plans. Emergency response exercise scheduled for second wk in Mar.
PALLADINO, F. J. Commissioners. 83/02/18. OTTINGER, R. L. House of Rep., Energy & Commerce. 1p. 17357:342. 24X Fiche: 50-247, 83/02/18, 8303020377.

8303290083 Responds to 830207 ltr re emergency preparedness issues. Comprehensive appraisal of onsite emergency preparedness contained in SECY-82-199. Notices of violations issued to licensees failing to install prompt notification sys.
PALLADINO, N. J. Commissioners. 83/03/08. MARKEY, E. J. House of Rep., Interior & Insular Affairs. 3pp. 17728:325. 24X Fiche: 50-247, 83/03/08, 8303290083.

--8303290116 Communicates dismay & displeasure over recent Commission decision re lack of emergency preparedness at facility. Commission failed to act in manner consistent w/regulations & sense of issue importance.
MARKEY, E. J. House of Rep., Interior & Insular Affairs. 83/02/07.
PALLADINO, N. J. Commissioners. 2pp. 17728:341. 24X
Fiche: 50-247, 83/03/08, 8303290083.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18p. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303080260 Responds to Generic Ltr 83-01 requesting estimate of requests for site visits to conduct operator licensing or instructor certification exams. Schedule of individuals proposed for certification listed.
O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/02/28.
EISENHUT, D. G. Division of Licensing. 1p. 17446:339. 24X
Fiche: 50-247, 83/02/28, 8303080260.

DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

8303240587 Forwards IE Insp Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24 on 821203-05. No noncompliance noted. Summary of significant deficiencies encl.
KEPPLER, J. G. Region 3, Office of Director. 83/03/11. REED, C. Commonwealth Edison Co. 3pp. 17682:087. 24X Fiche: 50-010, 83/03/11, 8303240587.

--8303240597 IE Insp Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24 on 821203-05. No noncompliance noted. Major areas inspected: generating station emergency plan alert caused by flooding conditions.
TONGUE, T. M., MADISON, A. L., CHRISSOTIMOS, N. Region 3, Office of Director. 83/03/02. 12pp. 17683:090. 24X Fiche: 50-010, 83/03/11, 8303240587.

8303230143 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/16. Document Management Branch. 1p. 17687:120. 24X Fiche: 50-010, 83/03/16, 8303230143.

--8303230149 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 500-6, "Quarterly Operational Support Ctr Inventory (Primary Responsibility - Generating Station Emergency Plan Coordinator)."
SCOTT, D. J. Commonwealth Edison Co. 83/03/05. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17687:121. 24X
Fiche: 50-010, 83/03/16, 8303230143.

--8303230155 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 500-6, "Quarterly Operational Support Ctr Inventory (Primary Responsibility - Generating Station Emergency Plan Coordinator)." W/revised index.
* Commonwealth Edison Co. 83/03/02. 5pp. 17687:122. 24X
Fiche: 50-010, 83/03/16, 8303230143.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director. 83/03/22. Commonwealth Edison Co. 2pp. 17690:316. 24X Fiche: 50-000, 83/03/22, 8303240440.

8303310124 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/25. Document Management Branch. 1p. 17775:184. 24X Fiche: 50-000, 83/03/25, 8303310124.

--8303310130 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure EQ-1, "Coordination of Environs Group Activities by Environs Director."
* Commonwealth Edison Co. 83/03/17. Director's Office, Office of Inspection and Enforcement. 1p. 17775:185. 24X
Fiche: 50-000, 83/03/25, 8303310124.

--8303310146 Public version of Rev 3 to Emergency Plan Implementing Procedure EQ-1, "Coordination of Environs Group Activities by Environs Director."
PAJOWSKI, J. E. Commonwealth Edison Co. 83/03/08. 87pp. 17775:186. 24X Fiche: 50-000, 83/03/25, 8303310124.

8303300532 Releases public version of request for return of listed controlled copies of emergency plan.
FELTON, J. M. Division of Rules and Records. 83/03/28. Document Management Branch. 1p. 17763:178. 24X Fiche: 50-000, 83/03/28, 8303300532.

--8303300561 Submits public version of request for return of listed controlled copies of emergency plan.
FLESSNER, R. A. Commonwealth Edison Co. 83/03/15. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17763:179. 24X Fiche: 50-000, 83/03/28, 8303300532.

H. General correspondence

8303030528 Informs that DL Farrar has replaced LD DelGeorge as Director of Nuclear Licensing for util. Rev of current NRC distribution list requested.
FARRAR, D. L. Commonwealth Edison Co. 83/02/02. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17409:048. 24X
Fiche: 50-000, 83/02/02, 8303030528.

I. Financial information

8303070135 Forwards Annual Financial Rept 1982.
BRESEMANN, R. W. Commonwealth Edison Co. 83/02/28. Division of Licensing. 1p. 17433:001. 24X Fiche: 50-000, 83/02/28, 8303070135.

--8303070151 Annual Financial Rept 1982.
O'CONNOR, J. J. Commonwealth Edison Co. 83/02/03. 13pp. 17433:002. 24X Fiche: 50-000, 83/02/28, 8303070135.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J. G. Region 3, Office of Director. 83/03/03.
Commonwealth Edison Co. 2pp. 17492:014. 24X Fiche: 50-000, 83/03/03, 8303100364.

8303110246 Forwards Rev 23 to CE-1-A, "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/04. HAASS, W. P. Quality Assurance Branch. 1p. 17515:357. 24X Fiche: 50-000, 83/03/04, 8303110246.

--8303110279 Rev 23 to "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments.
SHEWSKI, W. J. Commonwealth Edison Co. CE-1-A R23. 83/03/07. 5pp. 17515:358. 24X Fiche: 50-000, 83/03/04, 8303110246.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12) Svc list encl.
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 51pp 17660 176 24X
Fiche 50-000, 83/03/07, 8303040005

8303220362 Forwards order confirming licensee commitments on post-TMI-related issues (Generic Ltrs 82-05 & 82-10)
CRUTCHFIELD, D Operating Reactors Branch 5 83/03/14 FARRAR, D
Commonwealth Edison Co 3pp 17656 004 24X Fiche 50-237, 83/03/14, 8303220362

--8303220367 Order confirming licensee commitment on post-TMI-related issues
EISENHUT, D G Division of Licensing 83/03/14 Commonwealth Edison Co 10pp 17656 007 24X Fiche 50-237, 83/03/14, 8303220362

8303170064 Forwards request for addl info re IE Bulletin 80-01 & NUREG-0737, Item II K 3 28, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves." Response due by 830512.
CRUTCHFIELD, D Operating Reactors Branch 5 83/03/16 FARRAR, D L
Commonwealth Edison Co 4pp 17609 098 24X Fiche 50-000, 83/03/16, 8303170064

8303280150 Forwards safety evaluation of NUREG-0737, Item II B 2 2, "Design Review of Plant Shielding-Access to Vital Areas." Mods completed & acceptable.
NORELIUS, C E Division of Project & Resident Programs 83/03/24
EISENHUT, D G Division of Licensing 2pp 17706 339 24X
Fiche 50-237, 83/03/24, 8303280150

8303280270 Requests that petition for hearing on environ qualification of safety-related electrical equipment be withdrawn based on listed interpretations Significant improvements in final rule 10CFR50 49 obviate hearings.
STEPTOE, P P Isham, Lincoln & Beale STEPTOE, P P Commonwealth Edison Co 83/03/24 EISENHUT, D G Division of Licensing 2pp 17706 289 24X Fiche 50-000, 83/03/24, 8303280270

## D Inspection reports, IE Bulletins & correspondence

8303030439 Forwards IE Insp Repts 50-010/82-22, 50-237/82-31 & 50-249/82-32 on 821202-830103 & 06 No noncompliance noted.
STREETER, J F Division of Project & Resident Programs 83/02/16
REED, C Commonwealth Edison Co 2pp 17410 086 24X
Fiche 50-010, 83/02/16, 8303030439

--8303030446 IE Insp Repts 50-010/82-22, 50-237/82-31 & 50-249/82-32 on 821202-830103 & 06 No noncompliance noted Major areas inspected licensee action on previous insp findings, headquarters request, operational safety & maint.
TONGUE, T M , JORDAN, M J , STASEK, S Division of Project & Resident Programs 83/02/15 13pp 17410 088 24X Fiche 50-010, 83/02/16, 8303030439

8303240368 Forwards IE Insp Repts 50-237/82-20, 50-254/82-16, 50-249/82-21 & 50-265/82-18 on 820816-1103.
KEPPLER, J G Region 3, Office of Director 82/02/16 O'CONNOR, J J
Commonwealth Edison Co 2pp 17682 021 24X Fiche 50-000, 83/02/16, 8303240368

--8303240372 IE Insp Repts 50-237/82-20, 50-249/82-21, 50-254/82-16 & 50-265/82-18 on 820816-1103 Noncompliance noted failure to control distribution of supplemental safety classification lists & to control parts not conforming to requirements.
CHRISSOTIMOS, N , DUPONT, S G , TONGUE, T M Region 3, Office of Director 83/02/15 8pp 17682 023 24X Fiche 50-000, 83/02/16, 8303240368

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 11lpp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367

8303170532 Forwards IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03 et al on 830126 No noncompliance noted.
DAVIS, A B Region 3, Office of Director 83/02/25 REED, C
Commonwealth Edison Co 2pp 17610 143 24X Fiche 50-000, 83/02/25, 8303170532

--8303170557 IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03 et al on 830126 No noncompliance noted Major areas discussed proposed guidelines util personnel should use for providing info to Region III inspectors.
GULDEMOND, W G , WALKER, R D Division of Project & Resident Programs 83/02/15 4pp 17610 145 24X Fiche 50-000, 83/02/25, 8303170532

8303180391 Forwards IE Insp Repts 50-010/83-02, 50-237/83-02 & 50-249/83-02 on 830112-14 No noncompliance noted.
LITTLE, W S Region 3, Office of Director 83/02/25 REED, C
Commonwealth Edison Co 2pp 17621 351 24X Fiche 50-010, 83/02/25, 8303180391

--8303180396 IE Insp Repts 50-010/83-02, 50-237/83-02 & 50-249/83-02 on 830112-14 No noncompliance noted Major areas inspected licensee action on previous findings, licensed & nonlicensed employee training & employee requalification training.
FARRELL, R E , HAWKINS, F C Region 3, Office of Director 83/02/16 4pp 17621 353 24X Fiche 50-010, 83/02/25, 8303180391

8303030580 Clarifies NRC position re procedures for admitting NRC personnel to facilities Site orientation re issuance of badges, escort duties & emergency evacuation for personnel listed in Encls 1 & 2 requested.
KEPPLER, J G Region 3, Office of Director 83/02/28 REED, C
Commonwealth Edison Co 6pp 17409 340 24X Fiche 50-010, 83/02/28, 8303030580

8303070036 Forwards responses to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Bunker-Ramo electrical penetrations installed in LaSalle Unit 2, Byron Unit 2 & Braidwood Unit 2.
SWARTZ, E D Commonwealth Edison Co 83/03/03 KEPPLER, J G Region 3, Office of Director 13pp 17435 290 24X Fiche 50-000, 83/03/03, 8303070036

8303170371 Forwards IE Insp Repts 50-010/83-05, 50-237/83-05 & 50-249/83-04 on 830104-0202 & notice of violation.
STREETER, J F Division of Project & Resident Programs 83/03/04
REED, C Commonwealth Edison Co 2pp 17610 057 24X
Fiche 50-010, 83/03/04, 8303170371

--8303170377 IE Insp Repts 50-010/83-05, 50-237/83-05 & 50-249/83-04 on 830104-0202 Noncompliance noted failure to incorporate Tech Specs issued w/Amend 71 to License DPR-19 into current copy of Tech Specs.
TONGUE, T M , JORDAN, M J , STASEK, S Region 3, Office of Director 83/02/23 9pp 17610 060 24X Fiche 50-010, 83/03/04, 8303170371

8303150343 Responds to NRC 830216 ltr re violations noted in IE Insp Repts 50-237/82-20, 50-249/82-21, 50-254/82-16 & 50-265/82-18. Extension of 30 days requested for preparation of detailed written statement re alleged violations, per 830308 telcon.
REED, C Commonwealth Edison Co 83/03/08 KEPPLER, J G Region 3, Office of Director 1p 17566 254 24X Fiche 50-000, 83/03/08, 8303150343

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc 117pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380

8303240587 Forwards IE Insp Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24 on 821203-05 No noncompliance noted Summary of significant deficiencies encl.
KEPPLER, J G Region 3, Office of Director 83/03/11 REED, C
Commonwealth Edison Co 3pp 17683 087 24X Fiche 50-010, 83/03/11, 8303240587

--8303240597 IE Insp Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24 on 821203-05 No noncompliance noted Major areas inspected generating station emergency plan alert caused by flooding conditions.
TONGUE, T M , JORDAN, M J , WALKER, R D Region 3, Office of Director 83/03/02 12pp 17683 090 24X Fiche 50-010, 83/03/11, 8303240587

8303170064 Forwards request for addl info re IE Bulletin 80-01 & NUREG-0737, Item II K 3 28, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves." Response due by 830512.
CRUTCHFIELD, D Operating Reactors Branch 5 83/03/16 FARRAR, D L
Commonwealth Edison Co 4pp 17609 098 24X Fiche 50-000, 83/03/16, 8303170064

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 121pp 17774 352 24X Fiche 50-000, 83/03/21, 8212060387

8303310211 Forwards addl info in response to IE Bulletin 81-03 re methods to control Corbicula. "Environ Studies of Braidwood Cooling Pond, 1982," encl.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 17pp. 17755:095. 24X Fiche: 50-000, 83/03/28, 8303310211.

R Periodic operating reports & related correspondence

8303110241 Forwards monthly operating repts for Feb 1983.
SCOTT, D. J. Commonwealth Edison Co. 83/03/01. Director's Office, Office of Inspection and Enforcement. 1p. 17520:174. 24X Fiche: 50-010, 83/03/01, 8303110241.

--8303110248 Monthly operating repts for Feb 1983.
SCHROEDER, R. A. Commonwealth Edison Co. 83/03/01. 13pp. 17520:175. 24X Fiche: 50-010, 83/03/01, 8303110241.

S Reportable occurrences, LERs & related correspondence

8302280475 Forwards LER 83-005/01T-0.
SCOTT, D. J. Commonwealth Edison Co. 83/02/17. KEPPLER, J. G. Region 3, Office of Director. 1p. 17309:084. 24X Fiche: 50-249, 83/02/17, 8302280475.

--8302280487 LER 83-005/01T-0 on 830208, diesel generator failed to start. Caused by failure of air starter motor vanes to engage. Ingersoll-Rand air starter motors, air filter & air regulating valve replaced.
RHEE, S. Commonwealth Edison Co. 83/02/15. Region 3, Office of Director. 2pp. 17309:085. 24X Fiche: 50-249, 83/02/17, 8302280475.

8303080093 Forwards LER 83-004/03L-0.
SCOTT, D. J. Commonwealth Edison Co. 83/02/24. KEPPLER, J. G. Region 3, Office of Director. 1p. 17457:356. 24X Fiche: 50-249, 83/02/24, 8303080093.

--8303080100 LER 83-004/03L-0 on 830204, while disc operations sys 1600-1 valve timing test in progress, MO-3-1301-3 failed to open. Caused by valve disc wedged too tightly against seat. Valve cycled from control & successfully timed.
COYLE, L. Commonwealth Edison Co. 83/02/24. Region 3, Office of Director. 2pp. 17457:357. 24X Fiche: 50-249, 83/02/24, 8303080093.

8303080138 Forwards LER 83-008/01T-0.
SCOTT, D. J. Commonwealth Edison Co. 83/02/24. KEPPLER, J. G. Region 3, Office of Director. 1p. 17456:361. 24X Fiche: 50-249, 83/02/24, 8303080138.

--8303080147 LER 83-008/01T-0 on 830212, during normal operations, core spray pump 1401-3A failed to start during test. Caused by circuit breaker recharging motor toggle switch inadvertently left in off position. Switch changed to on position.
ANANDAPPA, A. N. Commonwealth Edison Co. 83/02/24. Region 3, Office of Director. 2pp. 17456:362. 24X Fiche: 50-249, 83/02/24, 8303080138.

8303150389 Forwards LER 83-006/03L-0.
SCOTT, D. J. Commonwealth Edison Co. 83/03/07. KEPPLER, J. G. Region 3, Office of Director. 1p. 17562:013. 24X Fiche: 50-249, 83/03/07, 8303150389.

--8303150395 LER 83-006/03L-0 on 830208, while performing DOS 1500-1 (LPCI valve operability test), torus spray isolation valve MO3-1501-18A failed in open position. Caused by auxiliary contact in control circuitry of valve. Contact replaced.
COYLE, L. Commonwealth Edison Co. 83/02/15. Region 3, Office of Director. 1p. 17562:014. 24X Fiche: 50-249, 83/03/07, 8303150389.

8303150611 RO 83-016 on 830207, contaminated water from drain & refill of 2/3A heating boiler inadvertently released to storm sewer sys. Caused by operator not realizing floor drain led to storm sewer sys, not radwaste sys. Tech Specs not violated.
SCOTT, D. J.; GILMAN, T.; SCHROEDER, C. Commonwealth Edison Co. 83/03/09. KEPPLER, J. G. Region 3, Office of Director. 3pp. 17569:023. 24X Fiche: 50-237, 83/03/09, 8303150611.

8303220093 RO 83-014 on 830219, contaminated demineralized water released into condenser, allowing 0.7 mCi to steam out of vent. Caused by personnel error. Operator opened valve MO-3-1301-10 instead of valve MO-3-4399-74.
SCOTT, D. J.; COYLE, L. Commonwealth Edison Co. 83/03/15. KEPPLER, J. G. Region 3, Office of Director. 4pp. 17650:068. 24X Fiche: 50-249, 83/03/15, 8303220093.

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303040631 Forwards listing of projected operator licensing exam dates including type of exam & probable number of candidates, in response to 830111 Generic Ltr 83-01.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/01. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 17367:209. 24X Fiche: 50-000, 83/03/01, 8303040631.

DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

8303010660 Forwards RC Lewis 821112 ltr transmitting SALP Repts 50-250/82-33, 50-251/82-33 & 50-335/82-37 for May 1980 - June 1982 & 50-389/82-56 for Sept 1980 - June 1982. Overall performance satisfactory.
O'REILLY, J. P. Region 2, Office of Director. 83/01/18. UHRIG, R. E. Florida Power & Light Co. 2pp. 17341:106. 24X Fiche: 50-000, 83/01/18, 8303010660.

--8303010678 SALP Repts 50-250/82-33, 50-251/82-33 & 50-335/82-37 for May 1980 - June 1982 & 50-389/82-56 for Sept 1980 - June 1982. Overall performance satisfactory.
* Region 2, Office of Director. 82/11/12. 50pp. 17341:110. 24X Fiche: 50-000, 83/01/18, 8303010660.

8303020203 Forwards "Post-Fire Safe Shutdown Capability," technical evaluation rept. Encl identifies potential problem areas which deviate from App R to 10CFR50 if exemption request denied & dedicated shutdown capability required.
MCDONALD, D. G. Operating Reactors Branch 1. 83/02/14. UHRIG, R. E. Florida Power & Light Co. 2pp. 17358:244. 24X Fiche: 50-250, 83/02/14, 8303020203.

--8303020207 "Post-Fire Safe Shutdown Capability," technical evaluation rept.
THOMAS, H. J.; MACDOUGALL, E. A. Brookhaven National Laboratory. 83/02/14. NRC - No Detailed Affiliation Given. 10pp. 17358:246. 24X Fiche: 50-250, 83/02/14, 8303020203.

8303030554 Responds to 830106, 14 & 0218 ltrs by confirming agreements of 830223 meeting that util will suppl fire protection proposals to reflect recent work showing addl compliance w/App R requirements. Suppls to be submitted by 830408.
UHRIG, R. E. Florida Power & Light Co. 83/03/01. EISENHUT, D. G. Division of Licensing. 1p. 17412:362. 24X Fiche: 50-000, 83/03/01, 8303030554.

8303110055 Forwards Amends 92 & 86 to Licenses DPR-31 & DPR-41, respectively, & notice of issuance & availability. Amends change Tech Specs requiring audit of emergency & safeguards contingency plans at least once per yr.
VARGA, S. A. Operating Reactors Branch 1. 83/03/01. UHRIG, R. E. Florida Power & Light Co. 3pp. 17526:343. 24X Fiche: 50-250, 83/03/01, 8303110055.

--8303110063 Amends 92 & 86 to Licenses DPR-31 & DPR-86, respectively, changing Tech Specs to require audit of emergency & safeguards contingency plans at least once per yr.
VARGA, S. A. Operating Reactors Branch 1. 83/03/01. 6pp. 17526:346. 24X Fiche: 50-250, 83/03/01, 8303110055.

--8303110071 Notice of issuance & availability of Amends 92 & 86 to Licenses DPR-31 & DPR-41, respectively.
VARGA, S. A. Operating Reactors Branch 1. 83/03/01. 2pp. 17526:352. 24X Fiche: 50-250, 83/03/01, 8303110055.

8303160257 Advises of withdrawal of request for exemption from certain requirements of 10CFR73.21, per 811222 ltr. Facilities in compliance w/applicable sections.
UHRIG, R. E. Florida Power & Light Co. 83/03/10. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17596:340. 24X Fiche: 50-000, 83/03/10, 8303160257.

8303280349 Discusses request for exemptions from certain requirements of 10CFR73.21 Sections (d)(2) & (e) re marking & storage of safeguards matl. Request to withdraw exemption request acceptable, per util 830310 ltr.
VARGA, S. A. Operating Reactors Branch 1. 83/03/21. UHRIG, R. E. Florida Power & Light Co. 2pp. 17713:101. 24X Fiche: 50-000, 83/03/21, 8303280349.

# DOCKETED ITEMS

8303290424 Ack receipt of 830311 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-250/83-02 & 50-251/83-02.
DANCE, H. C. Division of Project & Resident Programs. 83/03/25.
UHRIG, R. E. Florida Power & Light Co. 1p. 17726:299. 24X
Fiche: 50-250, 83/03/25, 8303290424.

--8303290433 Responds to violations noted in IE Safeguards Insp Repts 50-250/83-02 & 50-251/83-02. Corrective actions withheld (ref 10CFR73.21).
UHRIG, R. E. Florida Power & Light Co. 83/03/11. O'REILLY, J. P. Region 2, Office of Director. 1p. 17726:300. 24X
Fiche: 50-250, 83/03/25, 8303290424.

--8303290440 Forwards IE Safeguards Insp Repts 50-250/83-02 & 50-251/83-02 on 830117-20 & notice of violation. Notice of violation withheld (ref 10CFR73.21).
DANCE, H. C. Division of Project & Resident Programs. 83/02/09.
UHRIG, R. E. Florida Power & Light Co. 2pp. 17726:301. 24X
Fiche: 50-250, 83/03/25, 8303290424.

--8303290450 IE Safeguards Insp Repts 50-250/83-02 & 50-251/83-02 on 830116-20. Noncompliance noted: failure to provide audible alarm signal in alarm stations. Details withheld (ref 10CFR73.21).
MOORE, D. E. Region 2, Office of Director. MCGUIRE, D. R. Division of Emergency Preparedness & Materials Safety. 83/02/08. 1p. 17726:303. 24X Fiche: 50-250, 83/03/25, 8303290424.

## Q. Adjudicatory correspondence

8303230132 Addl response to FOIA request for five categories of documents. Forwards SECY-82-87, SECY-82-396 & SECY-82-396A, identified as Item 1 of request.
FELTON, J. M. Division of Rules and Records. 83/02/23. HIATT, S. L. Ohio Citizens for Responsible Energy. 1p. 17684:292. 24X
Fiche: 50-000, 83/02/23, 8303230132.

--8203120424 Informs of lawsuit filed w/DC Circuit Court of Appeals, wherein J. Lorion seeks review of Director's Decision 81-21 which denied 10CFR2.206 petition to shut down reactors for steam generator insp.
FITZGERALD, J. A. Office of the General Counsel. SECY-82-087. 82/03/02. 2pp. 17684:294. 24X Fiche: 50-000, 83/02/23, 8303230132.

--8203120425 Petition for review of Director's Decision 81-21 denying 10CFR2.206 petition to shut down reactors for steam generator insp. Certificate of Svc encl.
LORION, J. Affiliation Unknown. 82/02/08. U.S. Court of Appeals for District of Columbia Circuit. 2pp. 17684:296. 24X
Fiche: 50-000, 83/02/23, 8303230132.

--8203120426 Advises that 811109 ltr was not intended as 10CFR2.206 petition & thus, Director's Decision 81-21 should be rescinded.
LORION, J. Center for Nuclear Responsibility. 81/11/12.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17684:299. 24X Fiche: 50-000, 83/02/23, 8303230132.

## H. General correspondence

8303040338 Advises of current mailing address, effective Jul 1982.
UHRIG, R. E. Florida Power & Light Co. 83/02/25. EISENHUT, D. G. Division of Licensing. 1p. 17420:072. 24X Fiche: 50-000, 83/02/25, 8303040338.

## J. Insurance & indemnity information

8303290339 Forwards Endorsement 63 to NELIA Policy NF-185.
DUCK, J. R. Marsh & McLennan, Inc. 83/03/15. SALTZMAN, J. Assistant Director for State & Licensee Relations. 2pp. 17716:156. 24X
Fiche: 50-250, 83/03/15, 8303290339.

## P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303040111 Requests assessment of large diameter Pratt purge & vent valve operability & intentions to maintain valves sealed closed in accordance w/SRP & operable in event of DBA-LOCA.
VARGA, S. A. Operating Reactors Branch 1. 83/02/16. UHRIG, R. E. Florida Power & Light Co. 5pp. 17424:337. 24X
Fiche: 50-250, 83/02/16, 8303040111.

8303030703 Notification of 830307 meeting w/utils & NUS Corp in Bethesda, MD to discuss proposed rev to 10CFR40, Ap. A (Tech. Specs).
BRINKMAN, D. S. Standardization & Special Projects Branch. 83/02/22.
THOMAS, C. O. Standardization & Special Projects Branch. 2pp. 17363:227. 24X Fiche: 50-000, 83/02/22, 8303030703.

8303040267 Forwards draft final technical evaluation rept, "Control of Heavy Loads (C-10), Turkey Point Units 3 & 4" & summary of unresolved items to be used as agenda for meeting.
MCDONALD, D. G. Operating Reactors Branch 1. 83/02/22. UHRIG, R. E. Florida Power & Light Co. 2pp. 17427:041. 24X
Fiche: 50-250, 83/02/22, 8303040267.

--8302090307 "Control of Heavy Loads (C-10), Turkey Point Units 3 & 4," draft technical evaluation rept. Request for addl info encl.
BOMBERGER, C., VITO, D. J. Franklin Institute/Franklin Research Center. NRC-03-81-130. TER-C5506-399/400 DR. 83/01/06.
CLEMENSON, F. NRC - No Detailed Affiliation Given. 38pp. 17427:043. 24X Fiche: 50-250, 83/02/22, 8303040267.

8303040400 Forwards addl details re discrepancies in Tech Spec requirements for ESF channel operability & blocking of steam line high differential pressure safety injection during cooldown. Response requested within 30 days.
VARGA, S. A. Operating Reactors Branch 1. 83/02/22. UHRIG, R. E. Florida Power & Light Co. 5pp. 17426:344. 24X
Fiche: 50-250, 83/02/22, 8303040400.

8303040619 Submits info re post-TMI requirements Items II.B.3, "Post-Accident Sampling Sys," II.F.1.1, "Noble Gas Monitors," II.F.1.2, "Iodine Particulate Sampling" & II.F.1.6, "Containment Hydrogen Monitors."
UHRIG, R. E. Florida Power & Light Co. 83/02/28. VARGA, S. A. Operating Reactors Branch 1. 3pp. 17374:226. 24X
Fiche: 50-250, 83/02/28, 8303040619.

8303080051 Notifies that review & justification for proprietary classification of info contained in technical evaluation rept for environ qualification of electrical equipment will be submitted by 830429.
UHRIG, R. E. Florida Power & Light Co. 83/03/01. VARGA, S. A. Operating Reactors Branch 1. 1p. 17455:295. 24X
Fiche: 50-250, 83/03/01, 8303080051.

8303080399 Forwards justification for continued plant operation w/Catagory II.B electrical equipment. Justifications for equipment in Categories IB & IIA to be completed by 830331.
UHRIG, R. E. Florida Power & Light Co. 83/03/01. VARGA, S. A. Operating Reactors Branch 1. 10pp. 17454:230. 24X
Fiche: 50-250, 83/03/01, 8303080399.

8303110055 Forwards Amends 92 & 86 to Licenses DPR-31 & DPR-41, respectively, & notice of issuance & availability. Amends change Tech Specs requiring audit of emergency & safeguards contingency plans at least once per yr.
VARGA, S. A. Operating Reactors Branch 1. 83/03/01. UHRIG, R. E. Florida Power & Light Co. 3pp. 17526:343. 24X
Fiche: 50-250, 83/03/01, 8303110055.

--8303110063 Amends 92 & 86 to Licenses DPR-31 & DPR-86, respectively, changing Tech Specs to require audit of emergency & safeguards contingency plans at least once per yr.
VARGA, S. A. Operating Reactors Branch 1. 83/03/01. 6pp. 17526:346. 24X Fiche: 50-250, 83/03/01, 8303110055.

--8303110071 Notice of issuance & availability of Amends 92 & 86 to Licenses DPR-31 & DPR-41, respectively.
VARGA, S. A. Operating Reactors Branch 1. 83/03/01. 2pp. 17526:352. 24X Fiche: 50-250, 83/03/01, 8303110055.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303100352 Advises that 821117 commitment to install debris screens withdrawn pending resolution of large-diameter Pratt butterfly valve operability concerns.
UHRIG, R. E. Florida Power & Light Co. 83/03/04. VARGA, S. A. Operating Reactors Branch 1. 1p. 17492:013. 24X
Fiche: 50-250, 83/03/04, 8303100352.

8303110287 Forwards Rev 1 to "Containment Isolation/Purge Valve Analysis: 48-Inch RIA W/Bettis Actuator" & Rev 1 to "Containment Isolation/Purge Valve Analysis: 54-Inch RIA Valve W/Pratt 2 Plate Cylinder Operator."
UHRIG, R. E. Florida Power & Light Co. 83/03/04. VARGA, S. A. Operating Reactors Branch 1. 3pp. 17513:098. 24X
Fiche: 50-250, 83/03/04, 8303110287.

--8303110292 Rev 1 to "Containment Isolation/Purge Valve Analysis 48-Inch RIA Valve W/Bettis Actuator." W/one oversize drawing Aperture card is available in PDR.
KAZA, R. N. Henry Pratt Co. 81/09/15 99pp 17515:101 24X
Fiche: 50-250, 83/03/04, 8303110287.

--8303110303 Rev 1 to "Containment Isolation/Purge Valve Analysis 54-Inch RIA Valve W/Pratt 2 Plate Cylinder Operator." W/one oversize drawing Aperture card is available in PDR.
ZO, R. N. Henry Pratt Co. 81/09/16 99pp 17515:200 24X
Fiche: 50-250, 83/03/04, 8303110287.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303140204 Informs that discussion topics for evaluation of control room habitability per post-TMI requirements expected by 830831. Completion of mods expected by 830701.
UHRIG, R. E. Florida Power & Light Co. 83/03/07 VARGA, S. A. Operating Reactors Branch 1. 1p 17539:305 24X
Fiche: 50-250, 83/03/07, 8303140204.

8303140521 Forwards revised pump & valve inservice test program. Program applicable from 830907-930907.
UHRIG, R. E. Florida Power & Light Co. 83/03/07 VARGA, S. A. Operating Reactors Branch 1. 1p 17534:052 24X
Fiche: 50-250, 83/03/07, 8303140521.

--8303140527 Revised pump & valve inservice test program.
* Florida Power & Light Co. 83/03/07 118pp 17534:053 24X
Fiche: 50-250, 83/03/07, 8303140521.

8303150062 Notification of 830318 meeting w/Franklin Research Ctr & licensee in Bethesda, MD to discuss open items in technical evaluation rept re control of heavy loads.
MCDONALD, D. G. Operating Reactors Branch 1 83/03/09 VARGA, S. Operating Reactors Branch 1 2pp 17586:300 24X
Fiche: 50-250, 83/03/09, 8303150062.

8303160267 Forwards responses to Generic Ltr 82-28 re inadequate core cooling instrumentation sys for facilities W/nine oversize drawings. Aperture cards are available in PDR.
UHRIG, R. E. Florida Power & Light Co. 83/03/10 EISENHUT, D. G. Division of Licensing 38pp 17591:227 24X Fiche: 50-250, 83/03/10, 8303160267.

--8303160276 Rev 0 to "Functional Design Spec for Qualified Safety Parameter Display Sys Display."
KHALSA, K. S. ; CASTAGNO, J. G. ; FOSTER, R. G. Combustion Engineering, Inc. NPRDD-ICE-3202 R00. 82/02/11 29pp 17591:265 24X
Fiche: 50-250, 83/03/10, 8303160267.

--8303160282 Rev 0 to "Functional Design Description for Qualified Safety Parameter Display Sys for Turkey Point Units 3 & 4."
STARKWEATHER, G. ; CASTAGNO, J. G. ; RONDE, K. R. Combustion Engineering, Inc. 16081-ICE-3218 R00. 82/10/06 8pp 17591:294 24X
Fiche: 50-250, 83/03/10, 8303160267.

--8303160295 Rev 0 to "Data Base Description for Qualified Safety Parameter Display Sys for Turkey Point Units 3 & 4."
STARKWEATHER, G. ; MATHIES, B. L. ; RONDE, K. R. Combustion Engineering, Inc. 16081-ICE-3219 R00. 83/01/13 28pp 17591:302 24X
Fiche: 50-250, 83/03/10, 8303160267.

--8303160304 Rev 0 to "Functional Design Spec for Qualified Safety Parameter Display Sys Displays for Turkey Point Units 3 & 4."
STARKWEATHER, G. ; MATHIES, B. L. ; RONDE, K. R. Combustion Engineering, Inc. 16081-ICE-3220 R00. 83/02/15 44pp 17591:330 24X
Fiche: 50-250, 83/03/10, 8303160267.

--8303160313 Rev 0 to "Interface Design Requirements for Qualified Safety Parameter Display Sys/Safety Assessment Sys Data Communications for Turkey Point Units 3 & 4."
EARLES, J. W. ; FEENEY, M. W. ; FOSTER, R. G. Combustion Engineering, Inc. 16081-ICE-3111 R00. 83/01/21 32pp 17592:012 24X
Fiche: 50-250, 83/03/10, 8303160267.

8303230396 Forwards Amends 93 & 87 to Licenses DPR-31 & DPR-41, respectively & notice of issuance & availability. Amends delete App B ETS re nonradiological water quality-related requirements.
VARGA, S. A. Operating Reactors Branch 1 83/03/11 UHRIG, R. E. Florida Power & Light Co. 3pp 17675:239 24X
Fiche: 50-250, 83/03/11, 8303230396.

--8303230401 Amends 93 & 87 to Licenses DPR-31 & DPR-41, respectively, deleting App B ETS re nonradiological water quality-related requirements.
VARGA, S. A. Operating Reactors Branch 1 83/03/11 11pp 17675:242 24X Fiche: 50-250, 83/03/11, 8303230396.

--8303230407 Notice of Issuance & availability of Amends 93 & 87 to Licenses DPR-31 & DPR-41, respectively.
VARGA, S. A. Operating Reactors Branch 1 83/03/11 2pp 17675:253 24X Fiche: 50-250, 83/03/11, 8303230396.

8303290005 Forwards order confirming commitments on post-TMI related issues per NUREG-0737. Proposed schedule exceptions & delays acceptable. Order based on commitments per responses to Generic Ltrs 82-05 & 82-10.
VARGA, S. A. Operating Reactors Branch 1 83/03/14 UHRIG, R. E. Florida Power & Light Co. 2pp 17730:055 24X
Fiche: 50-250, 83/03/14, 8303290005.

--8303290007 Order confirming licensee commitments on post-TMI related issues per NUREG-0737.
PURPLE, R. A. Division of Licensing 83/03/14 Florida Power & Light Co. 10pp 17730:057 24X Fiche: 50-250, 83/03/14, 8303290005.

8303170504 Forwards "Evaluation of Acceptability of Reactor Vessel Head Lift Rig, Reactor Vessel Internals Lift Rig, Load Cell, Load Cell Linkage & Reactor Coolant Pump Motor Lift Sling to Requirements of NUREG-0612," in response to 820222 ltr.
UHRIG, R. E. Florida Power & Light Co. 83/03/15 VARGA, S. A. Operating Reactors Branch 1 6pp 17607:133 24X
Fiche: 50-250, 83/03/15, 8303170504.

--8303170516 "Evaluation of Acceptability of Reactor Vessel Head Lift Rig, Reactor Vessel Internals Lift Rig, Load Cell, Load Cell Linkage & Reactor Coolant Pump Motor Lift Sling to Requirements of NUREG-0612."
SANDNER, H. H. ; LEDUC, R. J. Westinghouse Electric Corp. WCAP-10168. 82/12/31 195pp 17607:139 24X Fiche: 50-250, 83/03/15, 8303170504.

8303240296 Forwards SER indicating that analog rod position indication accuracy requirements may be relaxed during hot shutdown, cold shutdown or refueling.
VARGA, S. A. Operating Reactors Branch 1 83/03/15 UHRIG, S. A. Florida Power & Light Co. 2pp 17693:328 24X
Fiche: 50-250, 83/03/15, 8303240296.

--8303240316 SER indicating that analog rod position indication accuracy requirements may be relaxed during hot shutdown, cold shutdown or refueling.
* NRC - No Detailed Affiliation Given. 83/03/15 4pp 17693:330 24X Fiche: 50-250, 83/03/15, 8303240296.

8303290586 Forwards exemption from requirements of Section 50.71(e) of 10CFR50 permitting 4-month extension for submitting annual rev to FSAR per 830202 request.
VARGA, S. A. Operating Reactors Branch 1 83/03/16 UHRIG, R. E. Florida Power & Light Co. 2pp 17743:291 24X
Fiche: 50-250, 83/03/16, 8303290586.

--8303290591 Exemption from requirements of Section 50.71(e) of 10CFR50 permitting 4-month extension for submitting annual rev to FSAR per 830202 request.
PURPLE, R. A. Division of Licensing 83/03/16 Florida Power & Light Co. 3pp 17743:292 24X Fiche: 50-250, 83/03/16, 8303290586.

8303240357 Forwards corrected Page 3 to 830315 submittal, "Control of Heavy Loads," technical evaluation rept.
UHRIG, R. E. Florida Power & Light Co. 83/03/18 VARGA, S. H. Operating Reactors Branch 1 2pp 17679:354 24X
Fiche: 50-250, 83/03/18, 8303240357.

8303290107 Forwards Amends 94 & 88 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availability. Amends update offsite mgt organization to reflect current corporate structure.
MCDONALD, D. G. Operating Reactors Branch 1 83/03/18 UHRIG, R. E. Florida Power & Light Co. 2pp 17729:188 24X
Fiche: 50-250, 83/03/18, 8303290107.

--8303290117 Amends 94 & 88 to Licenses DPR-31 & DPR-41, respectively, updating offsite mgt organization to reflect current corporate structure.
VARGA, S. A. Operating Reactors Branch 1 83/03/18 8pp 17729:190 24X Fiche: 50-250, 83/03/18, 8303290107.

--8303290122 Safety evaluation supporting Amends 94 & 88 to Licenses DPR-31 & DPR-41, respectively.
* Office of Nuclear Reactor Regulation, Director 83/03/18 3pp 17729:198 24X Fiche: 50-250, 83/03/18, 8303290107.

# DOCKETED ITEMS

--8303290132 Notice of issuance & availability of Amends 94 & 88 to Licenses DPR-31 & DPR-41, respectively.
VARGA, S. A. Operating Reactors Branch 1 83/03/18 2pp
17729 201 24X Fiche: 50-250, 83/03/18, 8303290107.

8303250075 Informs that projected operability dates for air ejector effluent radiation monitors of 830321 & 0915 will not be met. Progress rept on moisture accumulation problem expected by 830601.
UHRIG, R. E. Florida Power & Light Co. 83/03/21 VARGA, S. A.
Operating Reactors Branch 1 1p 17693 273 24X
Fiche: 50-250, 83/03/21, 8303250075.

8303300301 Forwards info presented at 830126 meeting re plans & schedules to resolve pressurized thermal shock at facilities, in response to NRC 830201 request. Util plans to focus effort on flux reduction to reactor vessel inner wall.
UHRIG, R. E. Florida Power & Light Co. 83/03/25 VARGA, S. A.
Operating Reactors Branch 1 61pp 17734 220 24X
Fiche: 50-250, 83/03/25, 8303300301.

8303300398 Forwards corrected pages from util 830103 ltr re adequacy of station electric distribution sys voltages covering ESF setpoints.
UHRIG, R. E. Florida Power & Light Co. 83/03/25 VARGA, S. A.
Operating Reactors Branch 1 3pp 17731 001 24X
Fiche: 50-250, 83/03/25, 8303300398.

## 9. Inspection reports, IE Bulletins & correspondence

8303210622 Supplis 820227 ltr re IE Insp Repts 50-250/81-29 & 50-251/81-29 concerning safety classification of components. Revised G-list withdrawn to resolve internal comments & concerns. Each sys will be resolved individually.
UHRIG, R. E. Florida Power & Light Co. 82/12/28 O'REILLY, J. P.
Region 2, Office of Director 1p 17636 283 24X
Fiche: 50-250, 82/12/28, 8303210622.

8303010660 Forwards RC Lewis 821112 ltr transmitting SALP Repts 50-250/82-33, 50-251/82-33 & 50-335/82-37 for May 1980 - June 1982 & 50-389/82-56 for Sept 1980 - June 1982. Overall performance satisfactory.
O'REILLY, J. P. Region 2, Office of Director 83/01/18 UHRIG, R. E.
Florida Power & Light Co. 2pp 17341 106 24X
Fiche: 50-000, 83/01/18, 8303010660.

--8303010672 Forwards SALP Repts 50-250/82-33, 50-251/82-33 & 50-335/82-37 for May 1980 - June 1982 & 50-389/82-56 for Sept 1980 - June 1982. Evaluation will be discussed at 821123 meeting in Miami, FL.
LEWIS, R. C. Division of Project & Resident Programs 82/11/12
UHRIG, R. E. Florida Power & Light Co. 2pp 17341 108 24X
Fiche: 50-000, 83/01/18, 8303010660.

--8303010678 SALP Repts 50-250/82-33, 50-251/82-33 & 50-335/82-37 for May 1980 - June 1982 & 50-389/82-56 for Sept 1980 - June 1982. Overall performance satisfactory.
* Region 2, Office of Director 82/11/12 50pp 17341 110 24X
Fiche: 50-000, 83/01/18, 8303010660.

8303010597 Ack receipt of 830203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/82-37 & 50-251/82-37.
LEWIS, R. C. Division of Project & Resident Programs 83/02/18
UHRIG, R. E. Florida Power & Light Co. 1p 17336 091 24X
Fiche: 50-250, 83/02/18, 8303010597.

--8303010604 Responds to NRC 821221 ltr re violations noted in IE Insp Repts 50-250/82-37 & 50-251/82-37. Corrective actions upgrading of clearance review during startup under review & will be submitted in followup response on 830319.
UHRIG, R. E. Florida Power & Light Co. 83/02/03 O'REILLY, J. P.
Region 2, Office of Director 3pp 17336 092 24X
Fiche: 50-250, 83/02/18, 8303010597.

--8302010610 Requests 14-day extension for responding to IE Insp Repts 50-250/82-37 & 50-251/82-37 in order to clarify positions.
UHRIG, R. E. Florida Power & Light Co. 83/01/28 O'REILLY, J. P.
Region 2, Office of Director 1p 17336 095 24X
Fiche: 50-250, 83/02/18, 8303010597.

--8303010619 Forwards IE Insp Repts 50-250/82-37 & 50-251/82-37 on 821026-1125 & notice of violation.
LEWIS, R. C. Division of Project & Resident Programs 82/12/21
UHRIG, R. E. Florida Power & Light Co. 2pp 17336 096 24X
Fiche: 50-250, 83/02/18, 8303010597.

--8303010623 Notice of violation from insp on 821026-1125.
* Division of Project & Resident Programs 82/12/21 1p
17336 098 24X Fiche: 50-250, 83/02/18, 8303010597.

--8303010630 IE Insp Repts 50-250/82-37 & 50-251/82-37 on 821026-1125. Noncompliance noted: failure to perform safety evaluation for plant changes & sys mods.
VOGT-LOWELL, R. ; JULIAN, C. Division of Project & Resident Programs
82/12/17 7pp 17336 099 24X Fiche: 50-250, 83/02/18, 8303010597.

8303010677 Ack receipt of 830201 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/82-29 & 50-251/82-29.
DANCE, H. C. Division of Project & Resident Programs 83/02/22
UHRIG, R. E. Florida Power & Light Co. 1p 17336 176 24X
Fiche: 50-250, 83/02/22, 8303010677.

--8303010681 Revises response to NRC 820929 ltr re violations noted in IE Insp Repts 50-250/82-29 & 50-251/82-29. Corrective actions: danger tag removed, operator counseled & Procedure 0103.4 revised to better describe where to place clearance.
UHRIG, R. E. Florida Power & Light Co. 83/02/01 O'REILLY, J. P.
Region 2, Office of Director 2pp 17336 177 24X
Fiche: 50-250, 83/02/22, 8303010677.

8303210735 Forwards IE Insp Repts 50-250/82-41 & 50-251/82-41 on 821125-830114. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs 83/02/22
UHRIG, R. E. Florida Power & Light Co. 2pp 17635 280 24X
Fiche: 50-250, 83/02/22, 8303210735.

--8303210743 IE Insp Repts 50-250/82-41 & 50-251/82-41 on 821125-830114. No noncompliance noted. Major areas inspected: followup on previous insp findings, LERs, IE circulars & surveillance tests & plant operations.
VOGT-LOWELL, R. ; JULIAN, C. Division of Project & Resident Programs
83/02/17 6pp 17635 282 24X Fiche: 50-250, 83/02/22, 8303210735.

8303010145 Ack receipt of 830201 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/82-36 & 50-251/82-36.
DANCE, H. C. Division of Project & Resident Programs 83/02/23
UHRIG, R. E. Florida Power & Light Co. 1p 17345 001 24X
Fiche: 50-250, 83/02/23, 8303010145.

--8303010153 Responds to NRC 830103 ltr re violations noted in IE Insp Repts 50-250/82-36 & 50-251/82-36. Corrective actions: nonconformance rept issued on 821203 to remove nitrogen purge & purge adequately re-established. No proprietary info.
UHRIG, R. E. Florida Power & Light Co. 83/02/01 O'REILLY, J. P.
Region 2, Office of Director 2pp 17345 002 24X
Fiche: 50-250, 83/02/23, 8303010145.

--8303010166 Forwards IE Insp Repts 50-250/82-36 & 50-251/82-36 on 821130-1203 & notice of violation.
DANCE, H. C. Division of Project & Resident Programs 83/01/03
UHRIG, R. E. Florida Power & Light Co. 2pp 17345 004 24X
Fiche: 50-250, 83/02/23, 8303010145.

--8303010183 Notice of violation from insp on 821130-1203.
* Division of Project & Resident Programs 83/01/03 1p
17345 006 24X Fiche: 50-250, 83/02/23, 8303010145.

--8303010195 IE Insp Repts 50-250/82-36 & 50-251/82-36 on 821130-1203. Noncompliance noted: failure to maintain protective environ inside steam generator lower assemblies.
ECONOMOS, N. ; BLAKE, J. J. Division of Project & Resident Programs
82/12/30 6pp 17345 007 24X Fiche: 50-250, 83/02/23, 8303010145.

8303210582 Forwards IE Insp Repts 50-250/83-03 & 50-251/83-03 on 830117-18. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs 83/02/23
UHRIG, R. E. Florida Power & Light Co. 2pp 17632 240 24X
Fiche: 50-250, 83/02/23, 8303210582.

--8303210588 IE Insp Repts 50-250/83-03 & 50-251/83-03 on 830117-18. No noncompliance noted. Major areas inspected: Unit 4 steam generator repair program.
DEBS, B. T. ; BARR, K. P. Region 2, Office of Director 83/02/18
3pp 17632 242 24X Fiche: 50-250, 83/02/23, 8303210582.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc.
111pp 17521 001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210549 Ack receipt of 820816 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/82-19 & 50-251/82-19. NRC records revised to reflect that no violation of sampling methodology occurred.
LEWIS, R. C. Division of Project & Resident Programs 83/02/28
UHRIG, R. E. Florida Power & Light Co. 2pp 17632 265 24X
Fiche: 50-250, 83/02/28, 8303210549.

8303140232 Forwards owners data repts for inservice insp (Form NIS-1) & repairs/replacement (Form NIS-2), per provisions of ASME Code.
UHRIG, R E Florida Power & Light Co 83/03/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 17538:338 24X
Fiche: 50-250, 83/03/07, 8303140232

8303210645 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Surveillance test of undervoltage trip function revealed no problems.
UHRIG, R E Florida Power & Light Co 83/03/07 O'REILLY, J P Region 2, Office of Director 3pp 17636:270 24X
Fiche: 50-250, 83/03/07, 8303210645

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche: 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387

8303290424 Ack receipt of 830311 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-250/83-02 & 50-251/83-02.
DANCE, H C Division of Project & Resident Programs 83/03/25
UHRIG, R E Florida Power & Light Co 1p 17726:299 24X
Fiche: 50-250, 83/03/25, 8303290424

--8303290433 Responds to violations noted in IE Safeguards Insp Repts 50-250/83-02 & 50-251/83-02. Corrective actions withheld (ref 10CFR73.21).
UHRIG, R E Florida Power & Light Co 83/03/11 O'REILLY, J P Region 2, Office of Director 1p 17726:300 24X
Fiche: 50-250, 83/03/25, 8303290424

--8303290440 Forwards IE Safeguards Insp Repts 50-250/83-02 & 50-251/83-02 on 830117-20 & notice of violation. Notice of violation withheld (ref 10CFR73.21).
DANCE, H C Division of Project & Resident Programs 83/02/09
UHRIG, R E Florida Power & Light Co 2pp 17726:301 24X
Fiche: 50-250, 83/03/25, 8303290424

--8303290450 IE Safeguards Insp Repts 50-250/83-02 & 50-251/83-02 on 830116-20. Noncompliance noted: failure to provide audible alarm signal in alarm stations. Details withheld (ref 10CFR73.21).
MOORE, D E Region 2, Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 83/02/08 1p 17726:303 24X Fiche: 50-250, 83/03/25, 8303290424

R Periodic operating reports & related correspondence

8303080402 Forwards monthly operating repts for Dec 1982.
WILLIAMS, J W Florida Power & Light Co 83/01/17 Office of Resource Management, Director 1p 17454:034 24X
Fiche: 50-000, 83/01/17, 8303080402

--8303080408 Monthly operating repts for Dec 1982.
PACE, P Florida Power & Light Co 83/01/17 13pp 17454:035 24X Fiche: 50-000, 83/01/17, 8303080402

8303150539 Forwards monthly operating repts for Jan 1983 & corrected monthly operating repts for May-Dec 1982 for St Lucie Unit 1.
WILLIAMS, J W Florida Power & Light Co 83/02/14 Office of Resource Management, Director 1p 17568:034 24X
Fiche: 50-000, 83/02/14, 8303150539

--8303150546 Monthly operating repts for Jan 1983.
PACE, P Florida Power & Light Co 83/02/14 12pp 17568:035 24X Fiche: 50-000, 83/02/14, 8303150539

--8303150558 Corrected monthly operating repts for May-Dec 1982.
PACE, P Florida Power & Light Co 83/02/14 8pp 17568:047 24X Fiche: 50-000, 83/02/14, 8303150539

8303080389 Forwards "Radioactive Effluent Release Data, Jul-Dec 1982."
UHRIG, R E Florida Power & Light Co 83/03/01 EISENHUT, D G Division of Licensing 1p 17454:008 24X Fiche: 50-250, 83/03/01, 8303080389

--8303080391 "Radioactive Effluent Release Data, Jul-Dec 1982."
* Florida Power & Light Co 83/03/01 17pp 17454:009 24X
Fiche: 50-250, 83/03/01, 8303080389

S Reportable occurrences, LERs & related correspondence

8303210550 Forwards LER 83-003/03L-0.
WILLIAMS, J W Florida Power & Light Co 83/02/28 O'REILLY, J P Region 2, Office of Director 1p 17632:313 24X
Fiche: 50-250, 83/02/28, 8303210550

--8303210557 LER 83-003/03L-0 on 830128, local indication of emergency diesel generator B showed low starting air pressure of 150 psig. Caused by loose tension spring nut on low starting air pressure alarm sensing switch. Setpoint adjusted.
ARIAS, J Florida Power & Light Co 83/02/28 Region 2, Office of Director 2pp 17632:314 24X Fiche: 50-250, 83/02/28, 8303210550

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp 24X Fiche: 50-000, 83/02/24, 8302250505

8303080318 Responds to Generic Ltr 83-01, identifying all requests for site visits to conduct operator licensing exams or instructor certification exams, through 1985.
UHRIG, R E Florida Power & Light Co 83/03/01 EISENHUT, D G Division of Licensing 2pp 17449:316 24X Fiche: 50-250, 83/03/01, 8303080318

DOCKET: 50-251 TURKEY POINT PLANT, UNIT 4

F Security, medical, emergency & fire protection plans

8303010660 Forwards RC Lewis 821112 ltr transmitting SALP Repts 50-250/82-33, 50-251/82-33 & 50-335/82-37 for May 1980 - June 1982 & 50-389/82-56 for Sept 1980 - June 1982. Overall performance satisfactory.
O'REILLY, J P Region 2, Office of Director 83/01/18 UHRIG, R E Florida Power & Light Co 2pp 17341:106 24X
Fiche: 50-000, 83/01/18, 8303010660

--8303010678 SALP Repts 50-250/82-33, 50-251/82-33 & 50-335/82-37 for May 1980 - June 1982 & 50-389/82-56 for Sept 1980 - June 1982. Overall performance satisfactory.
* Region 2, Office of Director 82/11/12 50pp 17341:110 24X
Fiche: 50-000, 83/01/18, 8303010660

8303020203 Forwards "Post-Fire Safe Shutdown Capability," technical evaluation rept. Encl identifies potential problem areas which deviate from App R to 10CFR50 if exemption request denied & dedicated shutdown capability required.
MCDONALD, D G Operating Reactors Branch 1 83/02/14 UHRIG, R E Florida Power & Light Co 2pp 17358:244 24X
Fiche: 50-250, 83/02/14, 8303020203

--8303020207 "Post-Fire Safe Shutdown Capability," technical evaluation rept.
THOMAS, H J, MACDOUGALL, E A Brookhaven National Laboratory 83/02/14 NRC - No Detailed Affiliation Given 10pp 17358:246 24X Fiche: 50-250, 83/02/14, 8303020203

8303030554 Responds to 830106, 14 & 0218 ltrs by confirming agreements of 830223 meeting that util will suppl fire protection proposals to reflect recent work showing addl compliance w/App R requirements. Supplis to be submitted by 830408.
UHRIG, R E Florida Power & Light Co 83/03/01 EISENHUT, D G Division of Licensing 1p 17412:362 24X Fiche: 50-000, 83/03/01, 8303030554

8303110055 Forwards Amends 92 & 86 to Licenses DPR-31 & DPR-41, respectively & notice of issuance & availability. Amends change Tech Specs requiring audit of emergency & safeguards contingency plans at least once per yr.
VARGA, S A Operating Reactors Branch 1 83/03/01 UHRIG, R E Florida Power & Light Co 3pp 17526:343 24X
Fiche: 50-250, 83/03/01, 8303110055

--8303110063 Amends 92 & 86 to Licenses DPR-31 & DPR-86, respectively, changing Tech Specs to require audit of emergency & safeguards contingency plans at least once per yr.
VARGA, S A Operating Reactors Branch 1 83/03/01 6pp
17526:346 24X Fiche: 50-250, 83/03/01, 8303110055

--8303110071 Notice of issuance & availability of Amends 92 & 86 to Licenses DPR-31 & DPR-41, respectively.
VARGA, S. A. Operating Reactors Branch 1. 83/03/01. 2pp.
17526:352. 24X Fiche: 50-250. 83/03/01. 8303110055.

8303160257 Advises of withdrawal of request for exemption from certain requirements of 10CFR73.21 per 811222 ltr. Facilities in compliance w/applicable sections.
UHRIG, R. E. Florida Power & Light Co. 83/03/10. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17594:340. 24X
Fiche: 50-000. 83/03/10. 8303160257.

8303280349 Discusses request for exemptions from certain requirements of 10CFR73.21 Sections (d)(2) & (e) re marking & storage of safeguards matl. Request to withdraw exemption request acceptable per util 830310 ltr.
VARGA, S. A. Operating Reactors Branch 1. 83/03/21. UHRIG, R. E.
Florida Power & Light Co. 2pp. 17712:101. 24X
Fiche: 50-000. 83/03/21. 8303280349.

8303290424 Ack receipt of 830311 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-250/83-02 & 50-251/83-02.
DANCE, H. C. Division of Project & Resident Programs. 83/03/25.
UHRIG, R. E. Florida Power & Light Co. 1p. 17726:299. 24X
Fiche: 50-250. 83/03/25. 8303290424.

--8303290433 Responds to violations noted in IE Safeguards Insp Repts 50-250/83-02 & 50-251/83-02. Corrective actions withheld (ref 10CFR73.21).
UHRIG, R. E. Florida Power & Light Co. 83/03/11. O'REILLY, J. P.
Region 2, Office of Director. 1p. 17726:300. 24X
Fiche: 50-250. 83/03/25. 8303290424.

--8303290440 Forwards IE Safeguards Insp Repts 50-250/83-02 & 50-251/83-02 on 830117-20 & notice of violation. Notice of violation withheld (ref 10CFR73.21).
DANCE, H. C. Division of Project & Resident Programs. 83/02/09.
UHRIG, R. E. Florida Power & Light Co. 2pp. 17726:301. 24X
Fiche: 50-250. 83/03/25. 8303290424.

--8303290450 IE Safeguards Insp Repts 50-250/83-02 & 50-251/83-02 on 830116-20. Noncompliance noted: failure to provide audible alarm signal in alarm stations. Details withheld (ref 10CFR73.21).
MOORE, D. E. Region 2, Office of Director. 83/02/08. 1p.
17726:303. 24X Fiche: 50-250. 83/03/25. 8303290424.

9 Adjudicatory correspondence

8303230132 Addl response to FOIA request for five categories of documents. Forwards SECY-82-87, SECY-82-396 & SECY-82-396A, identified as Item 1 of request.
FELTON, J. M. Division of Rules and Records. 83/02/23. HIATT, S. L.
Ohio Citizens for Responsible Energy. 1p. 17684:292. 24X.
Fiche: 50-000. 83/02/23. 8303230132.

--8203120424 Informs of lawsuit filed w/DC Circuit Court of Appeals, wherein J. Lorion seeks review of Director's Decision 81-21 which denied 10CFR2.206 petition to shut down reactors for steam generator insp.
FITZGERALD, J. A. Office of the General Counsel. SECY-82-087.
82/03/02. 2pp. 17684:294. 24X Fiche: 50-000. 83/02/23. 8303230132.

--8203120425 Petition for review of Director's Decision 81-21 denying 10CFR2.206 petition to shut down reactors for steam generator insp. Certificate of Svc encl.
LORION, J. Affiliation Unknown. 82/02/08. U.S. Court of Appeals for District of Columbia Circuit. 2pp. 17684:296. 24X
Fiche: 50-000. 83/02/23. 8303230132.

--8203120426 Advises that 811109 ltr was not intended as 10CFR2.206 petition & thus, Director's Decision 81-21 should be rescinded.
LORION, J. Center for Nuclear Responsibility. 81/11/12.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp.
17684:299. 24X Fiche: 50-000. 83/02/23. 8303230132.

H General correspondence

8303040338 Advises of current mailing & dress, effective Jul 1982.
UHRIG, R. E. Florida Power & Light Co. 83/03/25. EISENHUT, D. G.
Division of Licensing. 1p. 17420:072. 24X Fiche: 50-000. 83/03/25.
8303040338.

J Insurance & indemnity information

8303290339 Forwards Endorsement 63 to NELIA Policy NF-185.
DUCK, J. R. Marsh & McLennan, Inc. 83/03/15. SHAPIRO, J. Assistant Director for State & Licensee Relations. 2pp. 17716:156. 24X
Fiche: 50-250. 83/03/15. 8303290339.

P Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000. 83/02/16. 8302170082.

8303040111 Requests reassessment of large diameter Pratt purge & vent valve operability & intentions to maintain valves sealed closed in accordance w/SRP & operable in event of DBA-LOCA.
VARGA, S. A. Operating Reactors Branch 1. 83/02/16. UHRIG, R. E.
Florida Power & Light Co. 5pp. 17424:337. 24X
Fiche: 50-250. 83/02/16. 8303040111.

8303030703 Notification of 830307 meeting w/utils & NUS Corp in Bethesda, MD to discuss proposed rev to 10CFR40.36 (Tech Specs).
BRINKMAN, D. S. Standardization & Special Projects Branch. 83/02/22.
THOMAS, C. O. Standardization & Special Projects Branch. 2pp.
17363:227. 24X Fiche: 50-000. 83/02/22. 8303030703.

8303040267 Forwards draft final technical evaluation rept, "Control of Heavy Loads (C-10), Turkey Point Units 3 & 4" & summary of unresolved items to be used as agenda for meeting.
MCDONALD, D. G. Operating Reactors Branch 1. 83/02/22. UHRIG, R. E.
Florida Power & Light Co. 2pp. 17427:041. 24X
Fiche: 50-250. 83/02/22. 8303040267.

--8302090307 "Control of Heavy Loads (C-10), Turkey Point Units 3 & 4," draft technical evaluation rept. Request for addl info encl.
BOMBERGER, C., VITO, D. J. Franklin Institute/Franklin Research Center. NRC-03-81-130. TER-C5506-399/400 DR. 83/01/06.
CLEMENSON, F. NRC - No Detailed Affiliation Given. 38pp.
17427:043. 24X Fiche: 50-250. 83/02/22. 8303040267.

8303040400 Forwards addl details re discrepancies in Tech Spec requirements for ESF channel operability & blocking of steam line high differential pressure safety injection during cooldown. Response requested within 30 days.
VARGA, S. A. Operating Reactors Branch 1. 83/02/22. UHRIG, R. E.
Florida Power & Light Co. 5pp. 17426:344. 24X
Fiche: 50-250. 83/02/22. 8303040400.

8303040619 Submits info re post-TMI requirements Items II.B.3, "Post-Accident Sampling Sys," II.F.1.1, "Noble Gas Monitors," II.F.1.2, "Iodine Particulate Sampling" & II.F.1.6, "Containment Hydrogen Monitors."
UHRIG, R. E. Florida Power & Light Co. 83/02/28. VARGA, S. A.
Operating Reactors Branch 1. 3pp. 17374:226. 24X
Fiche: 50-250. 83/02/28. 8303040619.

8303090051 Notifies that review & justification for proprietary classification of info contained in technical evaluation rept for environ qualification of electrical equipment will be submitted by 830429.
UHRIG, R. E. Florida Power & Light Co. 83/03/01. VARGA, S. A.
Operating Reactors Branch 1. 1p. 17455:295. 24X
Fiche: 50-250. 83/03/01. 8303090051.

8303080399 Forwards justification for continued plant operation w/Category II.B electrical equipment. Justifications for equipment in Categories IB & IIA to be completed by 830331.
UHRIG, R. E. Florida Power & Light Co. 83/03/01. VARGA, S. A.
Operating Reactors Branch 1. 10pp. 17454:230. 24X
Fiche: 50-250. 83/03/01. 8303080399.

8303110055 Forwards Amends 92 & 86 to Licenses DPR-31 & DPR-41, respectively, & notice of issuance & availability. Amends change Tech Specs requiring audit of emergency & safeguards contingency plans at least once per yr.
VARGA, S. A. Operating Reactors Branch 1. 83/03/01. UHRIG, R. E.
Florida Power & Light Co. 3pp. 17526:343. 24X
Fiche: 50-250. 83/03/01. 8303110055.

--8303110063 Amends 92 & 86 to Licenses DPR-31 & DPR-96, respectively, changing Tech Specs to require audit of emergency & safeguards contingency plans at least once per yr.
VARGA, S. A. Operating Reactors Branch 1. 83/03/01. 6pp.
17526:346. 24X Fiche: 50-250. 83/03/01. 8303110055.

--8303110071 Notice of issuance & availability of Amends 92 & 86 to Licenses DPR-31 & DPR-41, respectively.
VARGA, S. A. Operating Reactors Branch 1. 83/03/01. 2pp.
17526:352. 24X Fiche: 50-250. 83/03/01. 8303110055.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys.Svc list encl
EISENHUT,D.G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X
Fiche:50-000,83/03/02,8303020321

8303100352 Advises that 821117 commitment to install debris screens withdrawn pending resolution of large-diameter Pratt butterfly valve operability concerns.
UHRIG,R.E. Florida Power & Light Co. 83/03/04 VARGA,S.A.
Operating Reactors Branch 1 1p 17492:013 24X
Fiche:50-250,83/03/04,8303100352

8303110287 Forwards Rev 1 to "Containment Isolation/Purge Valve Analysis 48-Inch RIA W/Bettis Actuator" & Rev 1 to "Containment Isolation/Purge Valve Analysis 54-Inch RIA Valve W/Pratt 2 Plate Cylinder Operator."
UHRIG,R.E. Florida Power & Light Co. 83/03/04 VARGA,S.A.
Operating Reactors Branch 1 3pp 17515:098 24X
Fiche:50-250,83/03/04,8303110287

--8303110292 Rev 1 to "Containment Isolation/Purge Valve Analysis: 48-Inch RIA Valve W/Bettis Actuator." W/one oversize drawing.Aperture card is available in PDF
KAZA,R.N. Henry Pratt Co. 81/09/15 99pp 17515:101 24X
Fiche:50-250,83/03/04,8303110287

--8303110303 Rev 1 to "Containment Isolation/Purge Valve Analysis: 54-Inch RIA Valve W/Pratt 2 Plate Cylinder Operator." W/one oversize drawing.Aperture card is available in PDR
ZO,R.N. Henry Pratt Co. 81/09/16 99pp 17515:200 24X
Fiche:50-250,83/03/04,8303110287

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12) Svc list encl
EISENHUT,D.G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp 17660:176 24X
Fiche:50-000,83/03/07,8303040005

8303140204 Informs that discussion topics for evaluation of control room habitability per post-TMI requirements expected by 830831.Completion of mods expected by 830701
UHRIG,R.E. Florida Power & Light Co. 83/03/07 VARGA,S.A.
Operating Reactors Branch 1 1p 17539:305 24X
Fiche:50-250,83/03/07,8303140204

8303140521 Forwards revised pump & valve inservice test program.Program applicable from 830907-930907
UHRIG,R.E. Florida Power & Light Co. 83/03/07 VARGA,S.A.
Operating Reactors Branch 1 1p 17534:052 24X
Fiche:50-250,83/03/07,8303140521

--8303140527 Revised pump & valve inservice test program.
* Florida Power & Light Co. 83/03/07 118pp 17534:053 24X
Fiche:50-250,83/03/07,8303140521

8303150062 Notification of 830318 meeting w/Franklin Research Ctr & licensee in Bethesda,MD to discuss open items in technical evaluation rept re control of heavy loads
MCDONALD,D.G. Operating Reactors Branch 1 83/03/09 VARGA,S.
Operating Reactors Branch 1 2pp 17586:300 24X
Fiche:50-250,83/03/09,8303150062

8303160267 Forwards responses to Generic Ltr 82-28 re inadequate core cooling instrumentation sys for facilities.W/nine oversize drawings.Aperture cards are available in PDR
UHRIG,R.E. Florida Power & Light Co. 83/03/10 EISENHUT,D.G.
Division of Licensing 38pp 17591:227 24X Fiche:50-250,83/03/10,8303160267

--8303160276 Rev 0 to "Functional Design Spec for Qualified Safety Parameter Display Sys Display."
KHALSA,K.S., CASTAGNO,J.G., FOSTER,R.G. Combustion Engineering, Inc. NPROD-ICE-3202 R00 82/02/11 29pp 17591:265 24X
Fiche:50-250,83/03/10,8303160267

--8303160282 Rev 0 to "Functional Design Description for Qualified Safety Parameter Display Sys for Turkey Point Units 3 & 4."
STARKWEATHER,G., CASTAGNO,J.G., RONDE,K.R. Combustion Engineering, Inc. 16081-ICE-3218 R00 82/10/06 8pp 17591:294 24X
Fiche:50-250,83/03/10,8303160267

--8303160295 Rev 0 to "Data Base Description for Qualified Safety Parameter Display Sys for Turkey Point Units 3 & 4."
STARKWEATHER,G., MATHIES,B.L., RONDE,K.R. Combustion Engineering, Inc. 16081-ICE-3219 R00 83/01/13 28pp 17591:302 24X
Fiche:50-250,83/03/10,8303160267

--8303160304 Rev 0 to "Functional Design Spec for Qualified Safety Parameter Display Sys Displays for Turkey Point Units 3 & 4."
STARKWEATHER,G., MATHIES,B.L., RONDE,K.R. Combustion Engineering, Inc. 16081-ICE-3220 R00 83/02/15 44pp 17591:330 24X
Fiche:50-250,83/03/10,8303160267

--8303160313 Rev 0 to "Interface Design Requirements for Qualified Safety Parameter Display Sys/Safety Assessment Sys Data Communications for Turkey Point Units 3 & 4."
EARLES,J.W., FEENEY,M.W., FOSTER,R.G. Combustion Engineering, Inc. 16081-ICE-3111 R00 83/01/21 32pp 17592:012 24X
Fiche:50-250,83/03/10,8303160267

8303230396 Forwards Amends 93 & 87 to Licenses DPR-31 & DPR-41, respectively & notice of issuance & availability.Amends delete App B ETS re nonradiological water quality-related requirements
VARGA,S.A. Operating Reactors Branch 1 83/03/11 UHRIG,R.E.
Florida Power & Light Co. 3pp 17675:239 24X
Fiche:50-250,83/03/11,8303230396

--8303230401 Amends 93 & 87 to Licenses DPR-31 & DPR-41, respectively, deleting App B ETS re nonradiological water quality-related requirements.
VARGA,S.A. Operating Reactors Branch 1 83/03/11 11pp
17675:242 24X Fiche:50-250,83/03/11,8303230396

--8303230407 Notice of issuance & availability of Amends 93 & 87 to Licenses DPR-31 & DPR-41, respectively.
VARGA,S.A. Operating Reactors Branch 1 83/03/11 2pp
17675:253 24X Fiche:50-250,83/03/11,8303230396

8303290005 Forwards order confirming commitments on post-TMI related issues per NUREG-0737.Proposed schedule exceptions & delays acceptable.Order based on commitments per responses to Generic Ltrs 82-05 & 82-10.
VARGA,S.A. Operating Reactors Branch 1 83/03/14 UHRIG,R.E.
Florida Power & Light Co. 2pp 17730:055 24X
Fiche:50-250,83/03/14,8303290005

--8303290007 Order confirming licensee commitments on post-TMI related issues per NUREG-0737.
PURPLE,R.A. Division of Licensing 83/03/14 Florida Power & Light Co. 10pp 17730:057 24X Fiche:50-250,83/03/14,8303290005

8303170504 Forwards "Evaluation of Acceptability of Reactor Vessel Head Lift Rig,Reactor Vessel Internals Lift Rig,Load Cell,Load Cell Linkage & Reactor Coolant Pump Motor Lift Sling to Requirements of NUREG-0612," in response to 830228 ltr.
UHRIG,R.E. Florida Power & Light Co. 83/03/15 VARGA,S.A.
Operating Reactors Branch 1 6pp 17607:133 24X
Fiche:50-250,83/03/15,8303170504

--8303170516 "Evaluation of Acceptability of Reactor Vessel Head Lift Rig,Reactor Vessel Internals Lift Rig,Load Cell,Load Cell Linkage & Reactor Coolant Pump Motor Lift Sling to Requirements of NUREG-0612."
SANDNER,H.H., LEDUC,R.J. Westinghouse Electric Corp. WCAP-10168, 82/12/31 195pp 17607:138 24X Fiche:50-250,83/03/15, 8303170504

8303240296 Forwards SER indicating that analog rod position indication accuracy requirements may be relaxed during hot shutdown, cold shutdown or refueling
VARGA,S.A. Operating Reactors Branch 1 83/03/15 UHRIG,R.E.
Florida Power & Light Co. 2pp 17693:328 24X
Fiche:50-250,83/03/15,8303240296

--8303240916 SER indicating that analog rod position indication accuracy requirements may be relaxed during hot shutdown, cold shutdown or refueling.
* NRC - No Detailed Affiliation Given 83/03/15 4pp
17693:330 24X Fiche:50-250,83/03/15,8303240296

8303290586 Forwards exemption from requirements of Section 50.71(e) of 10CFR50 permitting 4-month extension for submitting annual rev to FSAR per 830202 request
VARGA,S.A. Operating Reactors Branch 1 83/03/16 UHRIG,R.E.
Florida Power & Light Co. 2pp 17743:291 24X
Fiche:50-250,83/03/16,8303290586

--8303290591 Exemption from requirements of Section 50.71(e) of 10CFR50 permitting 4-month extension for submitting annual rev to FSAR per 830202 request.
PURPLE,R.A. Division of Licensing 83/03/16 Florida Power & Light Co. 3pp 17743:293 24X Fiche:50-250,83/03/16,8303290586

8303240357 Forwards corrected Page 3 to 830315 submittal, "Control of Heavy Loads," technical evaluation rept.
UHRIG,R.E. Florida Power & Light Co. 83/03/18 VARGA,S.H.
Operating Reactors Branch 1 2pp 17679:354 24X
Fiche:50-250,83/03/18,8303240357

# DOCKETED ITEMS

8303290107 Forwards Amends 94 & 88 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availability. Amends update offsite mgt organization to reflect current corporate structure.
MCDONALD, D. G. Operating Reactors Branch 1 83/03/18 UHRIG, R. E.
Florida Power & Light Co. 2pp 17729:185 24X
Fiche: 50-250, 83/03/18, 8303290107.

--8303290117 Amends 94 & 88 to Licenses DPR-31 & DPR-41, respectively, updating offsite mgt organization to reflect current corporate structure.
VARGA, S. A. Operating Reactors Branch 1 83/03/18 8pp
17729:190 24X Fiche: 50-250, 83/03/18, 8303290107.

--8303290122 Safety evaluation supporting Amends 94 & 88 to Licenses DPR-31 & DPR-41, respectively.
* Office of Nuclear Reactor Regulation, Director 83/03/18 3pp
17729:198 24X Fiche: 50-250, 83/03/18, 8303290107.

--8303290132 Notice of issuance & availability of Amends 94 & 88 to Licenses DPR-31 & DPR-41, respectively.
VARGA, S. A. Operating Reactors Branch 1 83/03/18 2pp
17729:201 24X Fiche: 50-250, 83/03/18, 8303290107.

8303250075 Informs that projected operability dates for air ejector effluent radiation monitors of 830321 & 0915 will not be met. Progress rept on moisture accumulation problem expected by 830601.
UHRIG, R. E. Florida Power & Light Co. 83/03/21 VARGA, S. A.
Operating Reactors Branch 1 1p 17692:273 24X
Fiche: 50-250, 83/03/21, 8303250075.

8303300301 Forwards info presented at 830126 meeting re plans & schedules to resolve pressurized thermal shock at facilities, in response to NRC 830201 request. Util plans to focus effort on flux reduction to reactor vessel inner wall.
UHRIG, R. E. Florida Power & Light Co. 83/03/25 VARGA, S. A.
Operating Reactors Branch 1 61pp 17734:220 24X
Fiche: 50-250, 83/03/25, 8303300301.

8303300398 Forwards corrected pages from util 830103 ltr re adequacy of station electric distribution sys voltages covering ESF setpoints.
UHRIG, R. E. Florida Power & Light Co. 83/03/25 VARGA, S. A.
Operating Reactors Branch 1 3pp 17731:001 24X
Fiche: 50-250, 83/03/25, 8303300398.

9. Inspection reports, IE Bulletins & correspondence

8303210622 Supplis 820227 ltr re IE Insp Repts 50-250/81-29 & 50-251/81-29 concerning safety classification of components. Revised G-list withdrawn to resolve internal comments & concerns. Each sys will be resolved individually.
UHRIG, R. E. Florida Power & Light Co. 82/12/28 O'REILLY, J. P.
Region 2, Office of Director 1p 17636:283 24X
Fiche: 50-250, 82/12/28, 8303210622.

8303010660 Forwards RC Lewis 821112 ltr transmitting SALP Repts 50-250/82-33, 50-251/82-33 & 50-335/82-37 for May 1980 - June 1982 & 50-389/82-56 for Sept 1980 - June 1982. Overall performance satisfactory.
O'REILLY, J. P. Region 2, Office of Director 83/01/18 UHRIG, R. E.
Florida Power & Light Co. 2pp 17341:106 24X
Fiche: 50-000, 83/01/18, 8303010660.

--8303010672 Forwards SALP Repts 50-250/82-33, 50-251/82-33 & 50-335/82-37 for May 1980 - June 1982 & 50-389/82-56 for Sept 1980 - June 1982. Evaluation will be discussed at 821123 meeting in Miami, FL.
LEWIS, R. C. Division of Project & Resident Programs 82/11/12
UHRIG, R. E. Florida Power & Light Co. 2pp 17341:108 24X
Fiche: 50-000, 83/01/18, 8303010660.

--8303010678 SALP Repts 50-250/82-33, 50-251/82-33 & 50-335/82-37 for May 1980 - June 1982 & 50-389/82-56 for Sept 1980 - June 1982 Overall performance satisfactory.
* Region 2, Office of Director 82/11/12 50pp 17341:110 24X
Fiche: 50-000, 83/01/18, 8303010660.

8303010597 Ack receipt of 830203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/82-37 & 50-251/82-37.
LEWIS, R. C. Division of Project & Resident Programs 83/02/18
UHRIG, R. E. Florida Power & Light Co. 1p 17336:091 24X
Fiche: 50-250, 83/02/18, 8303010597.

--8303010604 Responds to NRC 821221 ltr re violations noted in IE Insp Repts 50-250/82-37 & 50-251/82-37. Corrective actions: upgrading of clearance review during startup under review & will be submitted in followup response on 830319.
UHRIG, R. E. Florida Power & Light Co. 83/02/03 O'REILLY, J. P.
Region 2, Office of Director 3pp 17336:092 24X
Fiche: 50-250, 83/02/18, 8303010597.

--8303010610 Requests 14-day extension for responding to IE Insp Repts 50-250/82-37 & 50-251/82-37 in order to clarify positions.
UHRIG, R. E. Florida Power & Light Co. 83/01/28 O'REILLY, J. P.
Region 2, Office of Director 1p 17336:095 24X
Fiche: 50-250, 83/02/18, 8303010597.

--8303010619 Forwards IE Insp Repts 50-250/82-37 & 50-251/82-37 on 821026-1125 & notice of violation.
LEWIS, R. C. Division of Project & Resident Programs 82/12/21
UHRIG, R. E. Florida Power & Light Co. 2pp 17336:096 24X
Fiche: 50-250, 83/02/18, 8303010597.

--8303010623 Notice of violation from insp on 821026-1125.
* Division of Project & Resident Programs 82/12/21 1p
17336:098 24X Fiche: 50-250, 83/02/18, 8303010597.

--8303010630 IE Insp Repts 50-250/82-37 & 50-251/82-37 on 821026-1125. Noncompliance noted: failure to perform safety evaluation for plant changes & sys mods.
VOGT-LOWELL, R. , JULIAN, C. Division of Project & Resident Programs
82/12/17 7pp 17336:099 24X Fiche: 50-250, 83/02/18, 8303010597.

8303010677 Ack receipt of 830201 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpts 50-250/82-29 & 50-251/82-29.
DANCE, H. C. Division of Project & Resident Programs 83/02/22
UHRIG, R. E. Florida Power & Light Co. 1p 17336:176 24X
Fiche: 50-250, 83/02/22, 8303010677.

--8303010681 Revises response to NRC 820929 ltr re violations noted in IE Insp Repts 50-250/82-29 & 50-251/82-29. Corrective actions: danger tag removed, operator counseled & Procedure 0103.4 revised to better describe where to place clearance.
UHRIG, R. E. Florida Power & Light Co. 83/02/01 O'REILLY, J. P.
Region 2, Office of Director 2pp 17336:177 24X
Fiche: 50-250, 83/02/22, 8303010677.

8303210735 Forwards IE Insp Repts 50-250/82-41 & 50-251/82-41 on 821125-830114. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs 83/02/22
UHRIG, R. E. Florida Power & Light Co. 2pp 17635:280 24X
Fiche: 50-250, 83/02/22, 8303210735.

--8303210743 IE Insp Repts 50-250/82-41 & 50-251/82-41 on 821125-830114. No noncompliance noted. Major areas inspected: followup on previous insp findings, LERs, IE circulars & surveillance tests & plant operations.
VOGT-LOWELL, R. , JULIAN, C. Division of Project & Resident Programs
83/02/17 6pp 17635:282 24X Fiche: 50-250, 83/02/22, 8303210735.

8303010145 Ack receipt of 830201 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/82-36 & 50-251/82-36.
DANCE, H. C. Division of Project & Resident Programs 83/02/23
UHRIG, R. E. Florida Power & Light Co. 1p 17345:001 24X
Fiche: 50-250, 83/02/23, 8303010145.

--8303010153 Responds to NRC 830103 ltr re violations noted in IE Insp Repts 50-250/82-36 & 50-251/82-36. Corrective actions: nonconformance rept issued on 821203 to remove nitrogen purge & purge adequately re-established. No proprietary info.
UHRIG, R. E. Florida Power & Light Co. 83/02/01 O'REILLY, J. P.
Region 2, Office of Director 2pp 17345:002 24X
Fiche: 50-250, 83/02/23, 8303010145.

--8303010166 Forwards IE Insp Repts 50-250/82-36 & 50-251/82-36 on 821130-1203 & notice of violation.
DANCE, H. C. Division of Project & Resident Programs 83/01/03
UHRIG, R. E. Florida Power & Light Co. 2pp 17345:004 24X
Fiche: 50-250, 83/02/23, 8303010145.

--8303010183 Notice of violation from insp on 821130-1203.
* Division of Project & Resident Programs 83/01/03 1p
17345:006 24X Fiche: 50-250, 83/02/23, 8303010145.

--8303010195 IE Insp Repts 50-250/82-36 & 50-251/82-36 on 821130-1203. Noncompliance noted: failure to maintain protective environ inside steam generator lower assemblies.
ECONOMOS, N. , BLAKE, J. J. Division of Project & Resident Programs
82/12/30 6pp 17345:007 24X Fiche: 50-250, 83/02/23, 8303010145.

8303210582 Forwards IE Insp Repts 50-250/83-03 & 50-251/83-03 on 830117-18. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs 83/02/23
UHRIG, R. E. Florida Power & Light Co. 2pp 17632:240 24X
Fiche: 50-250, 83/02/23, 8303210582.

--8303210588 IE Insp Repts 50-250/83-03 & 50-251/83-03 on 830117-18. No noncompliance noted. Major areas inspected: Unit 4 steam generator repair program.
DEBS, B. T. , BARR, K. P. Region 2, Office of Director 83/02/18
3pp 17632:242 24X Fiche: 50-250, 83/02/23, 8303210582.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210549 Ack receipt of 820816 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/82-19 & 50-251/82-19. NRC records revised to reflect that no violation of sampling methodology occurred.
LEWIS, R. C. Division of Project & Resident Programs 83/02/28.
UHRIG, R. E. Florida Power & Light Co. 2pp. 17632:265. 24X
Fiche: 50-250, 83/02/28, 8303210549.

8303210645 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Surveillance test of undervoltage trip function revealed no problems.
UHRIG, R. E. Florida Power & Light Co. 83/03/07. O'REILLY, J. P.
Region 2, Office of Director. 3pp. 17636:270. 24X
Fiche: 50-250, 83/03/07, 8303210645.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp. 17641:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303290424 Ack receipt of 830311 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-250/83-02 & 50-251/83-02.
DANCE, H. C. Division of Project & Resident Programs. 83/03/25.
UHRIG, R. E. Florida Power & Light Co. 1p. 17726:299. 24X
Fiche: 50-250, 83/03/25, 8303290424.

--8303290433 Responds to violations noted in IE Safeguards Insp Repts 50-250/83-02 & 50-251/83-02. Corrective actions withheld (ref 10CFR73.21).
UHRIG, R. E. Florida Power & Light Co. 83/03/11. O'REILLY, J. P.
Region 2, Office of Director. 1p. 17726:300. 24X
Fiche: 50-250, 83/03/25, 8303290424.

--8303290440 Forwards IE Safeguards Insp Repts 50-250/83-02 & 50-251/83-02 on 830117-20 & notice of violation. Notice of violation withheld (ref 10CFR73.21).
DANCE, H. C. Division of Project & Resident Programs. 83/02/09.
UHRIG, R. E. Florida Power & Light Co. 2pp. 17726:301. 24X
Fiche: 50-250, 83/03/25, 8303290424.

--8303290450 IE Safeguards Insp Repts 50-250/83-02 & 50-251/83-02 on 830118-20. Noncompliance noted: failure to provide audible alarm signal in alarm stations. Details withheld (ref 10CFR73.21).
MOORE, D. E. Region 2, Office of Director. MCGUIRE, D. R. Division of Emergency Preparedness & Materials Safety. 83/02/08. 1p.
17726:303. 24X Fiche: 50-250, 83/03/25, 8303290424.

R. Periodic operating reports & related correspondence

8303080402 Forwards monthly operating repts for Dec 1982.
WILLIAMS, J. W. Florida Power & Light Co. 83/01/17. Office of Resource Management, Director. 1p. 17454:034. 24X
Fiche: 50-000, 83/01/17, 8303080402.

--8303080408 Monthly operating repts for Dec 1982.
PACE, P. Florida Power & Light Co. 83/01/17. 13pp. 17454:035.
24X Fiche: 50-000, 83/01/17, 8303080402.

8303150539 Forwards monthly operating repts for Jan 1983 & corrected monthly operating repts for May-Dec 1982 for St Lucie Unit 1.
WILLIAMS, J. W. Florida Power & Light Co. 83/02/14. Office of Resource Management, Director. 1p. 17568:034. 24X
Fiche: 50-000, 83/02/14, 8303150539.

--8303150546 Monthly operating repts for Jan 1983.
PACE, P. Florida Power & Light Co. 83/02/14. 12pp. 17568:035.
24X Fiche: 50-000, 83/02/14, 8303150539.

8303080389 Forwards "Radioactive Effluent Release Data, Jul-Dec 1982."
UHRIG, R. E. Florida Power & Light Co. 83/03/01. EISENHUT, D. G.
Division of Licensing. 1p. 17454:008. 24X Fiche: 50-250, 83/03/01, 8303080389.

--8303080391 "Radioactive Effluent Release Data, Jul-Dec 1982."
* Florida Power & Light Co. 83/03/01. 17pp. 17454:009. 24X
Fiche: 50-250, 83/03/01, 8303080389.

8303150318 Forwards "Steam Generator Repair Program Radiological Progress Rept 2 for 821203-830202."
UHRIG, R. E. Florida Power & Light Co. 83/03/10. EISENHUT, D. G.
Division of Licensing. 1p. 17567:091. 24X Fiche: 50-251, 83/03/10, 8303150318.

--8303150321 "Steam Generator Repair Program, Radiological Progress Rept 2 for 821203-830202."
* Florida Power & Light Co. 83/03/10. 31pp. 17567:092. 24X
Fiche: 50-251, 83/03/10, 8303150318.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303080318 Responds to Generic Ltr 83-01, identifying all requests for site visits to conduct operator licensing exams or instructor certification exams through 1985.
UHRIG, R. E. Florida Power & Light Co. 83/03/01. EISENHUT, D. G.
Division of Licensing. 2pp. 17449:316. 24X Fiche: 50-250, 83/03/01, 8303080318.

DOCKET 50-254 QUAD-CITIES STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8303160593 Forwards "Quad Cities Nuclear Power Station Small-Scale Joint Emergency Exercise" & "Evaluation of Implementation of IA State & Local Radiological Emergency Response Plans," final rept for 820824 exercise.
KRIMM, R. W. Federal Emergency Management Agency. 83/02/16.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 7pp. 17587:085. 24X Fiche: 50-254, 83/02/16, 8303160593.

--8303160596 "Quad Cities Nuclear Power Station Small-Scale Joint Emergency Exercise," final rept for 820824 exercise.
* Federal Emergency Management Agency. 82/10/12. 63pp.
17587:092. 24X Fiche: 50-254, 83/02/16, 8303160593.

--8303160600 "Evaluation of Implementation of IA State & Local Radiological Emergency Response Plans," final rept for exercise conducted on 820824.
* Federal Emergency Management Agency. 83/03/04. 13pp.
17587:155. 24X Fiche: 50-254, 83/02/16, 8303160593.

8303010595 Ack receipt of 830124 ltr identifying 1983 dates for emergency preparedness exercises within State of IL. Dates determined to be within required exercise frequency.
HIND, J. A. Region 3, Office of Director. 83/02/24. JONES, E. E.
Illinois, State of. 2pp. 17336:208. 24X Fiche: 50-000, 83/02/24, 8303010595.

--8303010618 Submits 1983 dates scheduled for emergency preparedness exercises for facilities within State of IL.
JONES, E. E. Illinois, State of. 83/01/24. KEPPLER, J. Region 3, Office of Director. 2pp. 17336:210. 24X Fiche: 50-000, 83/02/24, 8303010595.

8303100075 Release to public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17493:098. 24X Fiche: 50-254, 83/03/02, 8303100075.

--8303100083 Forwards public version of Rev 14 to Emergency Plan Implementing Procedure QEP 530-0, "Exercises & Drills" & Rev 5 to QEP 530-S1, "Monthly NARS (ESDA) Drill, Quad Cities Station."
* Commonwealth Edison Co. 83/02/07. DENTON, H. R. NRC - No Detailed Affiliation Given. 2pp. 17493:099. 24X
Fiche: 50-254, 83/03/02, 8303100075.

# DOCKETED ITEMS

--8303100090 Public version of Rev 14 to Emergency Plan Implementing Procedures QEP 530-0, "Exercises & Drills" & Rev 5 to QEP 530-S1, "Monthly NARS (ESDA) Drill-Quad Cities Station."
* Commonwealth Edison Co. 83/02/07. 2pp. 17493:101. 24X Fiche: 50-254, 83/03/02, 8303100075.

8303140573 Confirms 830318 meeting in Glen Ellyn, IL to discuss actions to resolve offsite emergency preparedness concerns & Byron preoperational test program. Meeting notice encl.
KEPPLER, J. G. Region 3, Office of Director. 83/03/08. REED, C. Commonwealth Edison Co. 3pp. 17534:001. 24X Fiche: 50-254, 83/03/08, 8303140573.

8303150601 Forwards IE Insp Repts 50-254/83-07 & 50-265/83-07 on 830225. No noncompliance noted.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 83/03/10. REED, C. Commonwealth Edison Co. 2pp. 17569:013. 24X Fiche: 50-254, 83/03/10, 8303150601.

--8303150606 IE Insp Repts 50-254/83-07 & 50-265/83-07 on 830225. No noncompliance noted. Major areas inspected: actions on previously identified items during emergency preparedness implementation appraisal.
PHILLIPS, M. P., GLOERSEN, W. B. Region 3, Office of Director. AXELSON, W. L. Division of Emergency Preparedness & Operational Support. 83/03/09. 5pp. 17569:015. 24X Fiche: 50-254, 83/03/10, 8303150601.

8303240074 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/21. Document Management Branch. 1p. 17694:128. 24X Fiche: 50-254, 83/03/21, 8303240074.

--8303240078 Forwards public version of revised emergency plan implementing procedures, including Procedures QEP 310-0 re notification of responsible authorities & QEP 310-T3 re prioritized notification listing.
JESSEN, D. Commonwealth Edison Co. 83/03/04. NRC - No Detailed Affiliation Given. 2pp. 17694:129. 24X Fiche: 50-254, 83/03/21, 8303240074.

--8303240085 Public version of revised emergency plan implementing procedures, including Procedures QEP 310-0 re notification of responsible authorities & QEP 310-T3 re prioritized notification listing.
* Commonwealth Edison Co. 83/03/07. 41pp. 17694:131. 24X Fiche: 50-254, 83/02/21, 8303240074.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director. 83/03/22. Commonwealth Edison Co. 2pp. 17690:316. 24X Fiche: 50-000, 83/03/22, 8303240440.

8303280307 Forwards IE Safeguards Insp Repts 50-254/83-08 & 50-265/83-08 on 830228-0304. No noncompliance noted.
MILLER, J. R. Region 3, Office of Director. 83/03/23. REED, C. Commonwealth Edison Co. 2pp. 17706:162. 24X Fiche: 50-254, 83/03/23, 8303280307.

--8303280321 IE Safeguards Insp Repts 50-254/83-08 & 50-265/83-08 on 830228-0304. No noncompliance noted. Major areas inspected: security program audit, physical barriers, security sys power supply & lighting. Details withheld (ref 10CFR73.21).
KNICELEY, J. R., BELANGER, J. L., CREED, J. R. Region 3, Office of Director. 83/03/23. 1p. 17706:164. 24X Fiche: 50-254, 83/03/23, 8303280307.

8303300008 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/23. Document Management Branch. 1p. 17751:265. 24X Fiche: 50-254, 83/03/23, 8303300008.

--8303300011 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure QEP 700-T3, "Supplemental Phone Listing."
* Commonwealth Edison Co. 83/02/24. NRC - No Detailed Affiliation Given. 1p. 17751:266. 24X Fiche: 50-254, 83/03/23, 8303300008.

--8303300017 Public version of Rev 3 to Emergency Plan Implementing Procedure QEP 700-T3, "Supplemental Phone Listing." Revised table of contents encl.
* Commonwealth Edison Co. 83/02/24. 2pp. 17751:267. 24X Fiche: 50-254, 83/03/23, 8303300008.

8303310124 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/25. Document Management Branch. 1p. 17775:184. 24X Fiche: 50-000, 83/03/25, 8303310124.

--8303310130 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure EQ-1, "Coordination of Environs Group Activities by Environs Director."
* Commonwealth Edison Co. 83/03/17. Director's Office, Office of Inspection and Enforcement. 1p. 17775:185. 24X Fiche: 50-000, 83/03/25, 8303310124.

--8303310135 Public version of Rev 3 to Emergency Plan Implementing Procedure EQ-1, "Coordination of Environs Group Activities by Environs Director."
PAJOHSKI, J. E. Commonwealth Edison Co. 83/03/08. 87pp. 17775:186. 24X Fiche: 50-000, 83/03/25, 8303310124.

8303300532 Releases public version of request for return of listed controlled copies of emergency plan.
FELTON, J. M. Division of Rules and Records. 83/03/28. Document Management Branch. 1p. 17763:178. 24X Fiche: 50-000, 83/03/28, 8303300532.

--8303300561 Submits public version of request for return of listed controlled copies of emergency plan.
FLESSNER, R. A. Commonwealth Edison Co. 83/03/15. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17763:179. 24X Fiche: 50-000, 83/03/28, 8303300532.

8303300738 Releases public version of rev to emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/28. Document Management Branch. 1p. 17765:200. 24X Fiche: 50-254, 83/03/28, 8303300738.

--8303300744 Forwards public version of Rev 6 to Emergency Plan Implementing Procedure QEP 700-0, "Telephone Directories" & Rev 3 to QEP 700-T3, "Supplemental Phone List." Receipt form encl.
GERNER, L., KOVACK, T. J. Commonwealth Edison Co. 83/02/24. NRC - No Detailed Affiliation Given. 2pp. 17765:201. 24X Fiche: 50-254, 83/03/28, 8303300738.

--8303300756 Public version of Rev 6 to Emergency Plan Implementing Procedure QEP 700-0, "Telephone Directories" & Rev 3 to QEP 700-T3, "Supplemental Phone List."
* Commonwealth Edison Co. 83/02/24. 2pp. 17765:203. 24X Fiche: 50-254, 83/03/28, 8303300738.

## H. General correspondence

8303030528 Informs that DL Farrar has replaced LD DelGeorge as Director of Nuclear Licensing for util. Rev of current NRC distribution list requested.
FARRAR, D. L. Commonwealth Edison Co. 83/02/02. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17409:048. 24X Fiche: 50-000, 83/02/02, 8303030528.

## I. Financial information

8303070135 Forwards Annual Financial Rept 1982.
BRESEMANN, R. W. Commonwealth Edison Co. 83/02/28. Division of Licensing. 1p. 17433:001. 24X Fiche: 50-000, 83/02/28, 8303070135.

--8303070151 Annual Financial Rept 1982.
O'CONNOR, J. J. Commonwealth Edison Co. 83/02/03. 13pp. 17433:002. 24X Fiche: 50-000, 83/02/28, 8303070135.

## J. Insurance & indemnity information

8303080197 Forwards Endorsements 74 & 61 to NELIA Policy NF-187 & MAELU Policy MF-54, respectively & Endorsements 141, 142, 119 & 120 to NELIA Policy NF-43 & MAELU Policy MF-22, respectively.
OSTER, J. Commonwealth Edison Co. 83/03/02. SALTZMAN, J. Antitrust & Economic Analysis Branch (Utility Finance). 7pp. 17457:325. 24X Fiche: 50-000, 83/03/02, 8303080197.

8303160578 Forwards Endorsements 143, 75, 62 & 24 to NELIA Policies NF-43, NF-187, NF-201 & NF-253, respectively.
OSTER, J. Commonwealth Edison Co. 83/03/09. SALTZMAN, J. Assistant Director for State & Licensee Relations. 5pp. 17587:017. 24X Fiche: 50-000, 83/03/09, 8303160578.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl. EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/15, 8302170082.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl. EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys. KEPPLER, J. G. Region 3, Office of Director 83/03/03 Commonwealth Edison Co. 2pp. 17492:014. 24X Fiche: 50-000, 83/03/03, 8303100364.

8303110246 Forwards Rev 23 to CE-1-A, "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments. SWARTZ, E. D. Commonwealth Edison Co. 83/03/04 HAASS, W. P. Quality Assurance Branch 1p. 17515:357. 24X Fiche: 50-000, 83/03/04, 8303110246.

--8303110279 Rev 23 to "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments. SHEWSKI, W. J. Commonwealth Edison Co. CE-1-A R23 83/03/07 5pp. 17515:358. 24X Fiche: 50-000, 83/03/04, 8303110246.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl. EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303300026 Forwards order confirming implementation of post-TMI items in NUREG-0737 based on commitments in response to Generic Ltrs 82-05 & 10. VASSALLO, D. B. Operating Reactors Branch 2 83/03/14 FARRAR, D. L. Commonwealth Edison Co. 3pp. 17751:172. 24X Fiche: 50-254, 83/03/14, 8303300026.

--8303300034 Order confirming licensee commitments on post-TMI related issues in NUREG-0737. PURPLE, R. A. Division of Licensing 83/03/14 Commonwealth Edison Co. 10pp. 17751:175. 24X Fiche: 50-254, 83/03/14, 8303300026.

8303170064 Forwards request for addl info re IE Bulletin 80-01 & NUREG-0737, Item II. K. 3. 28, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves." Response due by 830512. CRUTCHFIELD, D. Operating Reactors Branch 5 83/03/16 FARRAR, D. L. Commonwealth Edison Co. 4pp. 17609:098. 24X Fiche: 50-000, 83/03/16, 8303170064.

8303290663 Forwards safety evaluation re NUREG-0737, Item II. K. 3. 13, "Separate HPCI & RCIC Initiation Levels," & mod of RCIC initiation logic causing RCIC restart on low reactor vessel water level. Initiation level separation issue complete. VASSALLO, D. B. Operating Reactors Branch 2 83/03/16 FARRAR, D. L. Commonwealth Edison Co. 3pp. 17742:027. 24X Fiche: 50-254, 83/03/16, 8303290663.

8303280270 Requests that petition for hearing on environ qualification of safety-related electrical equipment be withdrawn based on listed interpretations. Significant improvements in final rule (10CFR50.49) obviate hearings. STEPTOE, P. P. Isham, Lincoln & Beale 83/03/24 EISENHUT, D. G. Division of Licensing 2pp. 17706:289. 24X Fiche: 50-000, 83/03/24, 8303280270.

8303280272 Forwards safety evaluation of NUREG-0737, Item II. B. 2. 2, "Design Review of Plant Shielding-Access to Vital Areas." Licensee has completed mods. NORELIUS, C. E. Division of Project & Resident Programs 83/03/24 EISENHUT, D. G. Division of Licensing 5pp. 17706:206. 24X Fiche: 50-254, 83/03/24, 8303280272.

Q. Inspection reports, IE Bulletins & correspondence

8303030504 Summarizes list of software changes that will be made to improve multiplet analysis capability of automated analytical instrument sys in response to inspt rept open items. Schedule of changes will be submitted by 830615. RYBAK, B. Commonwealth Edison Co. 83/02/14 KEPPLER, J. G. Region 3, Office of Director 2pp. 17409:062. 24X Fiche: 50-254, 83/02/14, 8303030504.

8303240368 Forwards IE Insp Repts 50-237/82-20, 50-254/82-16, 50-249/82-21 & 50-265/82-18 on 820816-1103. KEPPLER, J. G. Region 3, Office of Director 82/02/16 O'CONNOR, J. J. Commonwealth Edison Co. 2pp. 17682:021. 24X Fiche: 50-000, 83/02/16, 8303240368.

--8303240372 IE Insp Repts 50-237/82-20, 50-249/82-21, 50-254/82-16 & 50-265/82-18 on 820816-1103. Noncompliance noted: failure to control distribution of supplemental safety classification lists & to control parts not conforming to requirements. CHRISSOTIMOS, N., DUPONT, S. G., TONGUE, T. M. Region 3, Office of Director 83/02/15 8pp. 17682:023. 24X Fiche: 50-000, 83/02/16, 8303240368.

8303140259 Forwards IE Insp Repts 50-254/83-02 & 50-265/83-02 on 830201-04. No noncompliance noted. PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 83/02/24 REED, C. Commonwealth Edison Co. 2pp. 17534:246. 24X Fiche: 50-254, 83/02/24, 8303140259.

--8303140265 IE Insp Repts 50-254/83-02 & 50-265/83-02 on 830201-04. No noncompliance noted. Major areas inspected: effluent releases, records & repts & control instrumentation, solid radwaste & transportation. MILLER, D. E., PECK, C. C., GREGER, L. R. Region 3, Office of Director 83/02/22 12pp. 17534:248. 24X Fiche: 50-254, 83/02/24, 8303140259.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/28 Consolidated Edison Co. of New York, Inc. 111pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303170532 Forwards IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al. on 830126. No noncompliance noted. DAVIS, A. B. Region 3, Office of Director 83/02/25 REED, C. Commonwealth Edison Co. 2pp. 17610:143. 24X Fiche: 50-000, 83/02/25, 8303170532.

--8303170557 IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al. on 830126. No noncompliance noted. Major areas discussed: proposed guidelines util personnel should use for providing info to Region III inspectors. GULDEMOND, W. G. Division of Project & Resident Programs 83/02/15 4pp. 17610:145. 24X Fiche: 50-000, 83/02/25, 8303170532.

8303030441 Clarifies NRC position re procedures for admitting NRC personnel to facilities. Lists of NRC inspectors & personnel likely to visit facility two or more times per yr & at anytime encl. Lists will be updated every 6 months. KEPPLER, J. G. Region 3, Office of Director 83/02/28 REED, C. Commonwealth Edison Co. 6pp. 17410:080. 24X Fiche: 50-254, 83/02/28, 8303030441.

8303170546 Forwards IE Insp Repts 50-254/83-01 & 50-265/83-01 on 830107-0218. No noncompliance noted. STREETER, J. F. Division of Project & Resident Programs 83/03/01 REED, C. Commonwealth Edison Co. 2pp. 17610:150. 24X Fiche: 50-254, 83/03/01, 8303170546.

--8303170551 IE Insp Repts 50-254/83-01 & 50-265/83-01 on 830107-0218. No noncompliance noted. Major areas inspected: operational safety, maint, surveillance, audit program, reactor scram, licensee monthly repts, LERs & IE info notices. CHRISSOTIMOS, N. Region 3, Office of Director WALKER, R. D. Division of Project & Resident Programs 83/02/28 10pp. 17610:152. 24X Fiche: 50-254, 83/03/01, 8303170546.

8303070036 Forwards responses to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Bunker-Ramo electrical penetrations installed in LaSalle Unit 2, Byron Unit 2 & Braidwood Unit 2. SWARTZ, E. D. Commonwealth Edison Co. 83/03/03 KEPPLER, J. G. Region 3, Office of Director 13pp. 17435:290. 24X Fiche: 50-000, 83/03/03, 8303070036.

8303090102 Ack receipt of 830214 ltr informing NRC of improvements in automated analytical instrumentation sys discussed in IE Insp Repts 50-254/82-13 & 50-265/82-15. PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 83/03/04 RYBAK, B. Commonwealth Edison Co. 1p. 17469:350. 24X Fiche: 50-254, 83/03/04, 8303090102.

--8303090107 Responds to NRC 821001 ltr re automated analytical instrumentation sys discussed in IE Insp Repts 50-254/82-13 & 50-265/82-15. Peak search algorithm used in measuring radioactivity will include resolution of multiplet peaks.
RYBAK, B. Commonwealth Edison Co. 83/02/14. KEPPLER, J. G. Region 3, Office of Director. 2pp. 17469:351. 24X Fiche: 50-254, 83/03/04, 8303090102.

8303150343 Responds to NRC 830216 ltr re violations noted in IE Insp Repts 50-237/82-20, 50-249/82-21, 50-254/82-16 & 50-265/82-18. Extension of 30 days requested for preparation of detailed written statement re alleged violations per 830308 telcon.
REED, C. Commonwealth Edison Co. 83/03/08. KEPPLER, J. G. Region 3, Office of Director. 1p. 17566:254. 24X Fiche: 50-000, 83/03/08, 8303150343.

8303240602 Forwards IE Insp Repts 50-254/82-24 & 50-265/82-28 on 821212-17 & 830110. No noncompliance noted.
SPESSARD, R. L. Region 3, Office of Director. 83/03/09. REED, C. Commonwealth Edison Co. 2pp. 17683:052. 24X Fiche: 50-254, 83/03/09, 8303240602.

--8303240607 IE Insp Repts 50-254/82-24 & 50-265/82-28 on 821213-17 & 830110. No noncompliance noted. Major areas inspected: integrated primary containment leak rate test.
REIMANN, F. W., REYES, L. Region 3, Office of Director. 83/02/24. 6pp. 17683:054. 24X Fiche: 50-254, 83/03/09, 8303240602.

8303150601 Forwards IE Insp Repts 50-254/83-07 & 50-265/83-07 on 830225. No noncompliance noted.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 83/03/10. REED, C. Commonwealth Edison Co. 2pp. 17569:013. 24X Fiche: 50-254, 83/03/10, 8303150601.

--8303150606 IE Insp Repts 50-254/83-07 & 50-265/83-07 on 830225. No noncompliance noted. Major areas inspected: actions on previously identified items during emergency preparedness implementation appraisal.
PHILLIPS, M. P., GLOERSEN, W. B. Region 3, Office of Director. AXELSON, W. L. Division of Emergency Preparedness & Operational Support. 83/03/09. 5pp. 17569:015. 24X Fiche: 50-254, 83/03/10, 8303150601.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303170064 Forwards request for addl info re IE Bulletin 80-01 & NUREG-0737, Item II.K.3.28, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves." Response due by 830512.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/03/16. FARRAR, D. L. Commonwealth Edison Co. 4pp. 17609:098. 24X Fiche: 50-000, 83/03/16, 8303170064.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303280307 Forwards IE Safeguards Insp Repts 50-254/83-08 & 50-265/83-08 on 830228-0304. No noncompliance noted.
MILLER, J. R. Region 3, Office of Director. 83/03/23. REED, C. Commonwealth Edison Co. 2pp. 17706:162. 24X Fiche: 50-254, 83/03/23, 8303280307.

--8303280321 IE Safeguards Insp Repts 50-254/83-08 & 50-265/83-03 on 830228-0304. No noncompliance noted. Major areas inspected: security program audit, physical barriers, security sys power supply & lighting. Details withheld (ref 10CFR73.21).
KNICELEY, J. R., BELANGER, J. L., CREED, J. R. Region 3, Office of Director. 83/03/23. 1p. 17706:164. 24X Fiche: 50-254, 83/03/23, 8303280307.

8303280215 Responds to 821028 ltr requesting reduction in IE Bulletin 80-13 frequency for insp of core spray spargers & elimination of requirement for video resolution to be checked w/one mil wire. Evaluation underway.
NORELIUS, C. E. Division of Project & Resident Programs. 83/03/24. REED, C. Commonwealth Edison Co. 1p. 17708:215. 24X Fiche: 50-254, 83/03/24, 8303280215.

8303310211 Forwards addl info in response to IE Bulletin 81-03 re methods to control Corbicula. "Environ Studies of Braidwood Cooling Pond, 1982," encl.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/28. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 17pp. 17755:095. 24X Fiche: 50-000, 83/03/28, 8303310211.

R Periodic operating reports & related correspondence

8303170424 Correction to total man-rem exposure rept for 1981. Correct exposure should read 1,470 man-rem not 1470.00 man-rem.
WAGNER, G. P. Commonwealth Edison Co. 83/02/24. KEPPLER, J. G. Region 3, Office of Director. 1p. 17610:120. 24X Fiche: 50-254, 83/02/24, 8303170424.

8303150439 Forwards listing of changes, tests & experiments completed during Feb 1983. Safety evaluation summary reported per 10CFR50.59.
KALIVIANAKIS, N. Commonwealth Edison Co. 83/03/02. CASE, E. G. Office of Nuclear Reactor Regulation, Director. 6pp. 17562:261. 24X Fiche: 50-254, 83/03/02, 8303150439.

8303160389 Forwards monthly operating repts for Feb 1983.
KALIVIANAKIS, N. Commonwealth Edison Co. 83/03/02. Director's Office, Office of Inspection and Enforcement. 1p. 17595:201. 24X Fiche: 50-254, 83/03/02, 8303160389.

--8303160391 Monthly operating repts for Feb 1983.
BUSS, R. D. Commonwealth Edison Co. 83/03/02. 21pp. 17595:202. 24X Fiche: 50-254, 83/03/02, 8303160389.

S Reportable occurrences, LERs & related correspondence

8303080254 Forwards LER 83-006/03L-0.
KALIVIANAKIS, N. Commonwealth Edison Co. 83/02/23. KEPPLER, J. Region 3, Office of Director. 1p. 17446:346. 24X Fiche: 50-254, 83/02/23, 8303080254.

--8303080269 LER 83-006/03L-0 on 830213, during monthly surveillance test on conuenser pit 5-ft trip circuits, level switch 1-4441-25B failed to give circulating water pump trip signal. Caused by broken wire in switch mechanism. Switch replaced.
WILGUS, D. Commonwealth Edison Co. 83/02/23. Region 3, Office of Director. 2pp. 17446:347. 24X Fiche: 50-254, 83/02/23, 8303080254.

8303140436 Forwards LER 83-008/03L-0.
KALIVIANAKIS, N. Commonwealth Edison Co. 83/03/02. KEPPLER, J. G. Region 3, Office of Director. 1p. 17542:229. 24X Fiche: 50-254, 83/03/02, 8303140436.

--8303140447 LER 83-008/03L-0 on 830210, during Functional Test GIS 35-2, fuel pool radiation monitor 1-1705-16A failed to trip upscale. Caused by instrument calibr drift. Monitor recalibr & function test completed satisfactorily.
CARNEY, G. Commonwealth Edison Co. 83/03/02. Region 3, Office of Director. 1p. 17542:230. 24X Fiche: 50-254, 83/03/02, 8303140436.

8303170468 Forwards LER 83-011/03L-0.
KALIVIANAKIS, N. Commonwealth Edison Co. 83/03/08. KEPPLER, J. G. Region 3, Office of Director. 1p. 17610:206. 24X Fiche: 50-254, 83/03/08, 8303170468.

--8303170473 LER 83-011/03L-0 on 830225, during low condenser vacuum calibr & functional test, pressure switch PS-1-503A tripped at 20.9 inches Hg vacuum. Caused by setpoint drift. Switch recalibr & functionally tested.
HEBEL, C. Commonwealth Edison Co. 83/03/08. Region 3, Office of Director. 1p. 17610:207. 24X Fiche: 50-254, 83/03/08, 8303170468.

8303170378 Forwards LER 83-007/03L-0.
KALIVIANAKIS, N. Commonwealth Edison Co. 83/03/09. KEPPLER, J. Region 3, Office of Director. 1p. 17610:071. 24X Fiche: 50-254, 83/03/09, 8303170378.

--8303170379 LER 83-007/03L-0 on 830214, suppression chamber nitrogen purge valve AO-1-1601-56 failed to isolate during maint on drywell high radiation monitors. Caused by failure of solenoid pilot valve. Valve replaced.
RUSTICK, R. Commonwealth Edison Co. 83/03/09. Region 3, Office of Director. 3pp. 17610:072. 24X Fiche: 50-254, 83/03/09, 8303170378.

8303240541 Forwards revised LER 82-026/03L-2.
KALIVIANAKIS, N. Commonwealth Edison Co. 83/03/18. KEPPLER, J. Region 3, Office of Director. 1p. 17682:331. 24X Fiche: 50-254, 83/03/18, 8303240541.

--8303240547 Revised LER 82-026/03L-2 on 820706, listed valves & penetrations failed Tech Spec local leak rate test criteria. Valve MO-1-220-1 replaced w/oversized disc to compensate for gap created by repetitive lapping.
CLARK, D. Commonwealth Edison Co. 83/03/18. Region 3, Office of Director. 1p. 17682:332. 24X Fiche: 50-254, 83/03/18, 8303240541.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303040631 Forwards listing of projected operator licensing exam dates including type of exam & probable number of candidates, in response to 830111 Generic Ltr 83-01.
SHARTZ, E. D. Commonwealth Edison Co. 83/03/01. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 17367:209. 24X Fiche: 50-000, 83/03/01, 8303040631.

8303240355 Requests approval to delay implementation of TMI Item I.A.1.3.2, "Shift Manning," until 830731 due to lack of personnel. At present time, util has three senior reactor operator-licensed SCRE.
RYBAK, B. Commonwealth Edison Co. 83/03/21. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17682:001. 24X Fiche: 50-254, 83/03/21, 8303240355.

DOCKET 50-255 PALISADES NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

8303180492 Forwards revised emergency preparedness booklet w/addendum, distributed on 830201. W/o encl.
VANDEWALLE, D. J. Consumers Power Co. 83/02/23. KEPPLER, J. G. Region 3, Office of Director. 1p. 17622:117. 24X Fiche: 50-255, 83/02/23, 8303180492.

8303030472 Forwards IE Safeguards Insp Rept 50-255/83-04 on 830204. No noncompliance noted.
MILLER, J. R. Region 3, Office of Director. 83/02/25. DEWITT, R. B. Consumers Power Co. 2pp. 17409:064. 24X Fiche: 50-255, 83/02/25, 8303030472.

--8303030473 IE Safeguards Insp Rept 50-255/83-04 on 830204. No noncompliance noted. Major areas inspected: circumstances surrounding possible acts of vandalism of nonsafety-related equipment. Details withheld (ref 10CFR73.21).
BELANGER, J. L., MADEDA, T. J., CREED, J. R. Region 3, Office of Director. 83/02/24. 1p. 17409:066. 24X Fiche: 50-255, 83/02/25, 8303030472.

8303210123 Ack receipt of 830223 ltr providing addendum to emergency preparedness booklet. Addendum adequately corrects technical errors identified by NRC 821105 ltr.
PAPERIELLO, C. J. Region 3, Office of Director. 83/03/16. DEWITT, R. B. Consumers Power Co. 1p. 17630:260. 24X Fiche: 50-255, 83/03/16, 8303210123.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director. 83/03/22. Commonwealth Edison Co. 2pp. 17690:316. 24X Fiche: 50-000, 83/03/22, 8303240440.

I. Financial information

8303210279 Forwards Annual Financial Rept 1982.
PERRY, P. A. Consumers Power Co. 83/03/15. GIAMBUSSO, A. Division of Licensing. 1p. 17632:003. 24X Fiche: 50-000, 83/03/15, 8303210279.

--8303210286 Annual Financial Rept 1982.
SELBY, J. P., FALAHEE, J. B. Consumers Power Co. 83/02/04. 29pp. 17632:004. 24X Fiche: 50-000, 83/03/15, 8303210279.

J. Insurance & indemnity information

8303220310 Forwards Endorsement 77 to NELIA Policy NF-179.
FROUNFELKER, R. Consumers Power Co. 83/03/18. SALTZMAN, J. Antitrust & Economic analysis Branch (Utility Finance). 2pp. 17654:299. 24X Fiche: 50-255, 83/03/18, 8303220310.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303070035 Forwards action plan & schedule to resolve SEP Topic III-7.B, "Design Codes, Design Criteria & Load Combinations." Action plan will be completed & summary rept submitted by 830826.
TONER, R. A. Consumers Power Co. 83/02/28. CRUTCHFIELD, D. Operating Reactors Branch 5. 5pp. 17434:296. 24X Fiche: 50-255, 83/02/28, 8303070035.

8303290797 "SER, Pump & Valve Inservice Testing Program, Palisades Nuclear Plant," interim rept.
RANSOM, C. B., ROCKHOLD, H. C. EG&G, Inc. FIN A-6445. 8303290797. 83/02/28. PAGE, J. E. Division of Engineering. 41pp. 17748:109. 24X Fiche: 50-255, 83/02/28, 8303290797.

8303040494 Submits summary of intent to satisfy each criterion of NUREG-0737, Item II.B.3 re post-accident sampling sys (PASS), in response to 820630 request. PASS designed by Sentry Equipment Corp.
JOHNSON, B. D. Consumers Power Co. 83/03/01. CRUTCHFIELD, D. Operating Reactors Branch 5. 6pp. 17373:348. 24X Fiche: 50-255, 83/03/01, 8303040494.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J. G. Region 3, Office of Director. 83/03/03. Commonwealth Edison Co. 2pp. 17492:014. 24X Fiche: 50-000, 83/03/03, 8303100364.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 31pp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303180167 Responds to Generic Ltr 82-28 re inadequate core cooling instrumentation. Reactor coolant inventory sys will use Westinghouse reactor vessel level instrumentation sys design per NUREG/CR-2628 w/listed deviations.
JOHNSON, B. D. Consumers Power Co. 83/03/10. CRUTCHFIELD, D. Operating Reactors Branch 5. 3pp. 17617:235. 24X Fiche: 50-255, 83/03/10, 8303180167.

8303170282 Forwards order confirming licensee commitments to implement post-TMI related items set forth in NUREG-0737 per Generic Ltrs 82-05 & 82-10.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/03/14. VANDEWALLE, D. J. Consumers Power Co. 3pp. 17605:086. 24X Fiche: 50-255, 83/03/14, 8303170282.

--8303170289 Order confirming licensee commitments on post-TMI related issues.
EISENHUT, D. G. Division of Licensing. 83/03/14. Consumers Power Co. 9pp. 17605:089. 24X Fiche: 50-255, 83/03/14, 8303170282.

8303220099 Forwards application for amend to License DPR-20 requesting changes to Tech Spec to incorporate requirements of SEP Topic VIII-3.A re periodic station battery svc & performance discharge tests.
VANDEWALLE, D. J. Consumers Power Co. 83/03/14. CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 17656:238. 24X Fiche: 50-255, 83/03/14, 8303220099.

--8303220143 Application for amend to License DPR-20 requesting change to Tech Specs to incorporate requirements of SEP Topic VIII-3.A re periodic station battery svc & performance discharge tests.
VANDEWALLE, D. J. Consumers Power Co. 83/03/14. 2pp. 17656:239. 24X Fiche: 50-255, 83/03/14, 8303220099.

# DOCKETED ITEMS

--8303220298 Proposed Tech Specs incorporating requirements of SEP Topic VIII-3.A re periodic station battery svc & performance discharge tests.
* Consumers Power Co. 83/03/14. 3pp. 17656:241. 24X
Fiche: 50-255, 83/03/14, 8303220099.

8303220151 Forwards oath or affirmation statement for util 830310 response to Generic Ltr 82-28 re inadequate core cooling instrumentation sys.
JOHNSON, B.D.; DEWITT, R.B. Consumers Power Co. 83/03/15.
CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 17659:027. 24X
Fiche: 50-255, 83/03/15, 8303220151.

8303280250 Advises that Generic Ltr 83-10B will be addressed by 830701 w/C-E Owners Group program for resolution of TMI Action Plan Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps."
JOHNSON, B.D. Consumers Power Co. 83/03/23. EISENHUT, D.G. Division of Licensing. 1p. 17708:139. 24X Fiche: 50-255, 83/03/23, 8303280250.

G. Inspection reports, IE Bulletins & correspondence

8303080295 Informs of Jan 1983 insp of valves & other controls for engineered safety sys in compliance w/791109 order. Insp verified compliance w/limiting conditions of operation requirements of Tech Specs.
JOHNSON, B.D. Consumers Power Co. 83/02/15. KEPPLER, J.G. Region 3, Office of Director. 1p. 17454:293. 24X Fiche: 50-255, 83/02/15, 8303080295.

8303030624 Forwards IE Insp Rept 50-255/83-03 on 830103-31 & notice of violation.
STREETER, J.F. Division of Project & Resident Programs. 83/02/17.
DEWITT, R.B. Consumers Power Co. 2pp. 17409:079. 24X
Fiche: 50-255, 83/02/17, 8303030624.

--8303030630 Notice of violation from insp on 830103-31.
STREETER, J.F. Division of Project & Resident Programs. 83/02/17.
1p. 17409:081. 24X Fiche: 50-255, 83/02/17, 8303030624.

--8303030650 IE Insp Rept 50-255/83-03 on 830103-31 Noncompliance noted: failure to follow corrective action procedure by not implementing event rept when iodine removal hydrazine tank T-102 cover gas pressure fell below limit.
JORGENSEN, B.L.; HELLER, J.K.; HOLZMER, M.M. Region 3, Office of Director. 83/02/16. 6pp. 17409:082. 24X Fiche: 50-255, 83/02/17, 8303030624.

8303040519 Forwards IE Insp Rept 50-255/83-01 on 830104-07 & notice of violation.
LITTLE, W.S. Division of Engineering. 83/02/22. DEWITT, R.B. Consumers Power Co. 2pp. 17374:197. 24X Fiche: 50-255, 83/02/22, 8303040519.

--8303040521 Notice of violation from insp on 830104-07.
LITTLE, W.S. Division of Engineering. 83/02/17. 1p. 17374:199. 24X Fiche: 50-255, 83/02/22, 8303040519.

--8303040587 IE Insp Rept 50-255/83-01 on 830104-07 Noncompliance noted: failure to maintain controlled documents in QA manual in accurate rev status.
HASSE, R.A.; SUTPHIN, R.N.; HAWKINS, F.C. Region 3, Office of Director. 83/02/15. 10pp. 17374:200. 24X Fiche: 50-255, 83/02/22, L303040519.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303030472 Forwards IE Safeguards Insp Rept 50-255/83-04 on 830204. No noncompliance noted.
MILLER, J.R. Region 3, Office of Director. 83/02/25. DEWITT, R.B. Consumers Power Co. 2pp. 17409:064. 24X Fiche: 50-255, 83/02/25, 8303030472.

--8303030473 IE Safeguards Insp Rept 50-255/83-04 on 830204. No noncompliance noted. Major areas inspected: circumstances surrounding possible acts of vandalism of nonsafety-related equipment. Details withheld (ref 10CFR73.21).
BELANGER, J.L.; MADEDA, T.J.; CREED, J.R. Region 3, Office of Director. 83/02/24. 1p. 17409:066. 24X Fiche: 50-255, 83/02/25, 8303030473.

8303030445 Clarifies NRC position re procedures for admitting NRC personnel to facilities. Lists of NRC inspectors & personnel likely to visit facility two or more times per yr & at anytime encl. Lists will be updated every 6 months.
KEPPLER, J.G. Region 3, Office of Director. 83/02/28. DEWITT, R.B. Consumers Power Co. 4pp. 17410:068. 24X Fiche: 50-255, 83/02/28, 8303030445.

8303040427 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetrations." No Bunker-Ramo electrical penetrations in use at facilities.
JOHNSON, B.D. Consumers Power Co. 83/02/28. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 17371:180. 24X
Fiche: 50-000, 83/02/28, 8303040427.

8303080283 Submits addl info re planning & scheduling activities for regulatory performance improvement program per 821217 commitment. All periodic activities incorporated into computerized scheduling tool.
JOHNSON, B.D. Consumers Power Co. 83/03/01. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 17442:356. 24X
Fiche: 50-255, 83/03/01, 8303080283.

8303180021 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." No Westinghouse DB-50 circuit breakers in use at facility.
JOHNSON, B.D. Consumers Power Co. 83/03/08. KEPPLER, J.G. Region 3, Office of Director. 2pp. 17615:100. 24X Fiche: 50-255, 83/03/08, 8303180021.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303170147 Provides addl info re evaluation of util 810914 unacceptable response to IE Bulletin 80-06, per NRC 830113 ltr. Info demonstrates that existing engineered safety sys should remain unchanged.
JOHNSON, B.D. Consumers Power Co. 83/03/11. CRUTCHFIELD, D. Operating Reactors Branch 5. 12pp. 17609:047. 24X
Fiche: 50-255, 83/03/11, 8303170147.

8303220059 Ack receipt of 830214 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-255/82-28.
STREETER, J.F. Region 3, Office of Director. 83/03/17. DEWITT, R.B. Consumers Power Co. 1p. 17652:266. 24X Fiche: 50-255, 83/03/17, 8303220059.

--8303220065 Responds to NRC 830114 ltr re violations noted in IE Insp Rept 50-255/82-28. Corrective actions: checklist revised to reflect proper position of valve MV-709-FW & responsibility for updating checklists assigned to shift supervisor.
VANDEWALLE, D.J. Consumers Power Co. 83/02/14. KEPPLER, J.G. Region 3, Office of Director. 3pp. 17652:267. 24X
Fiche: 50-255, 83/03/17, 8303220059.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8303220267 Forwards safety evaluation & referenced portions of IE Insp Rept 50-255/82-01, documenting completed review of NUREG-0737, Item II.B.2.2, "Plant Shielding Access to Vital Areas."
NORELIUS, C.E. Division of Project & Resident Programs. 83/03/18.
EISENHUT, D.G. Division of Licensing. 2pp. 17656:215. 24X
Fiche: 50-255, 83/03/18, 8303220267.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303280026 Responds to IE Bulletin 83-04. Util uses contactors in reactor protection sys rather than reactor trip breakers & associated undervoltage trip devices. Latest vendor recommendations on preventative maint obtained.
VANDEWALLE, D.J. Consumers Power Co. 83/03/21. CRUTCHFIELD, D. Operating Reactors Branch 5. 5pp. 17707:340. 24X
Fiche: 50-255, 83/03/21, 8303280026.

8303210269 Confirms scheduled 821028 meeting in Glen Ellyn, IL to discuss SALP.
SPESSARD, R.L. Division of Project & Resident Programs. 82/09/23.
DEWITT, R.B. Consumers Power Co. 1p. 17634:353. 24X
Fiche: 50-000, 82/09/23, 8303210269.

R. Periodic operating reports & related correspondence

8303080500 Forwards monthly operating rept for Dec 1982.
KENNEDY, D.M. Consumers Power Co. 83/01/10. NRC - No Detailed Affiliation Given. 1p. 17450:315. 24X Fiche: 50-255, 83/01/10, 8303080500.

--8303080505 Monthly operating rept for Dec 1982.
PETERSON, D. Consumers Power Co. 83/01/03. 3pp. 17450:316. 24X Fiche: 50-255, 83/01/10, 8303080500.

8303140320 Forwards monthly operating rept for Feb 1983.
KENNEDY, D. M. Consumers Power Co. 83/03/02. NRC - No Detailed Affiliation Given. 1p. 17543:303. 24X Fiche: 50-255, 83/03/02, 8303140320.

--8303140323 Monthly operating rept for Feb 1983.
PETERSON, D. A. Consumers Power Co. 83/03/01. 3p. 17543:304. 24X Fiche: 50-255, 83/03/02, 8303140320.

8303140410 Forwards "10CFR50.59 Annual Rept, 1982."
JOHNSON, B. D. Consumers Power Co. 83/03/04. KEPPLER, J. G. Region 3, Office of Director. 1p. 17542:177. 24X Fiche: 50-255, 83/03/04, 8303140410.

--8303140415 "10CFR50.59 Annual Rept, 1982."
* Consumers Power Co. 83/03/04. 8pp. 17542:178. 24X Fiche: 50-255, 83/03/04, 8303140410.

S. Reportable occurrences, LERs & related correspondence

8303080153 Forwards LER 83-010/03L-0.
JOHNSON, B. D. Consumers Power Co. 83/02/25. KEPPLER, J. G. Region 3, Office of Director. 1p. 17455:361. 24X Fiche: 50-255, 83/02/25, 8303080153.

--8303080160 LER 83-010/03L-0 on 830127, during QA audit of completed Tech Spec surveillances, quarterly check of diesel fire pump batteries for May 1982 found to have exceeded due date by 2 days. Caused by personnel error.
* Consumers Power Co. 83/02/25. Region 3, Office of Director. 1p. 17455:362. 24X Fiche: 50-255, 83/02/25, 8303080153.

8303080193 Forwards LER 83-009/03L-0.
JOHNSON, B. D. Consumers Power Co. 83/02/25. KEPPLER, J. G. Region 3, Office of Director. 1p. 17457:360. 24X Fiche: 50-255, 83/02/25, 8303080193.

--8303080199 LER 83-009/03L-0 on 830127, PCS sample revealed dose equivalent I-131 exceeded Tech Specs. Caused by normal fuel leakage. Procedures to be revised to increase letdown purification flow following trip.
* Consumers Power Co. 83/02/25. Region 3, Office of Director. 1p. 17457:361. 24X Fiche: 50-255, 83/02/25, 8303080193.

8303080476 Forwards LER 83-008/01T-0.
JOHNSON, B. D. Consumers Power Co. 83/02/25. KEPPLER, J. G. Region 3, Office of Director. 1p. 17452:274. 24X Fiche: 50-255, 83/02/25, 8303080476.

--8303080488 LER 83-008/01T-0 on 830209, thermal overload for one engineered safeguards room cooler fan tripped based on evaluation & testing activities. Cause not stated. Tripped overload reset.
* Consumers Power Co. 83/02/25. Region 3, Office of Director. 1p. 17452:275. 24X Fiche: 50-255, 83/02/25, 8303080476.

8303080456 Forwards LER 83-011/03L-0.
JOHNSON, B. D. Consumers Power Co. 83/02/28. KEPPLER, J. G. Region 3, Office of Director. 1p. 17452:361. 24X Fiche: 50-255, 83/02/28, 8303080456.

--8303080473 LER 83-011/03L-0 between 830131 & 0213, during normal operations, safety injection tank B level reached Tech Specs limit of 198 inches on four occasions. Caused by minor leakage past loop check valve & tank check valve.
* Consumers Power Co. 83/02/28. Region 3, Office of Director. 1p. 17452:362. 24X Fiche: 50-255, 83/02/28, 8303080456.

8303080219 Forwards LER 83-012/03L-0.
JOHNSON, B. D. Consumers Power Co. 83/03/01. KEPPLER, J. G. Region 3, Office of Director. 1p. 17457:103. 24X Fiche: 50-255, 83/03/01, 8303080219.

--8303080228 LER 83-012/03L-0 on 830130, sample from T-82D (safety injection tank D) showed boron concentration below Tech Spec limit of 1,720 ppm. Caused by boron dilution due to minor leak past check valve. Primary coolant leak rate monitored.
* Consumers Power Co. 83/03/01. Region 3, Office of Director. 1p. 17457:104. 24X Fiche: 50-255, 83/03/01, 8303080219.

8303140510 Forwards LER 83-013/03L-0.
JOHNSON, B. D. Consumers Power Co. 83/03/02. KEPPLER, J. G. Region 3, Office of Director. 1p. 17540:346. 24X Fiche: 50-255, 83/03/02, 8303140510.

--8303140531 LER 83-013/03L-0 on 830204, two field voltage readings & one phase current reading exceeded acceptance criteria during emergency diesel generator 1-1 first line supervisory review. Caused by meter malfunction. Meters to be replaced.
* Consumers Power Co. 83/03/02. Region 3, Office of Director. 1p. 17540:346. 24X Fiche: 50-255, 83/03/02, 8303140510.

8303220141 Forwards Amend 1 to LER 83-09 re primary coolant sys iodine exceeding spec due to oversight. Amend provides detailed rept per Tech Spec 3.1.4.
JOHNSON, B. D. Consumers Power Co. 83/03/14. KEPPLER, J. G. Region 3, Office of Director. 5pp. 17659:029. 24X Fiche: 50-255, 83/03/14, 8303220141.

8303240014 Telecopy RO on 830312, w/safety injection tank T-82D inoperable due to low boron concentration, addl safety injection tank T-82B became inoperable due to low boron level. Operability restored.
KRICH, R. M. Consumers Power Co. 83/03/14. Region 3, Office of Director. 1p. 17681:248. 24X Fiche: 50-255, 83/03/14, 8303240014.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303040512 Submits proposed dates between 830111 & 831231 for operator licensing instructor certification exams which would require NRC site visit, in response to 830111 Generic Ltr 83-01.
JOHNSON, B. D. Consumers Power Co. 83/02/28. EISENHUT, D. G. Division of Licensing. 1p. 17373:275. 24X Fiche: 50-000, 83/02/28, 8303040512.

DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8303010293 Responds to NRC 820727 ltr re violations noted in IE Insp Repts 50-259/82-20, 50-260/82-20 & 50-296/82-20. Corrective actions security program audit will be performed by 830130.
MILLS, L. M. Tennessee Valley Authority. 82/12/28. O'REILLY, J. P. Region 2, Office of Director. 1p. 17374:086. 24X Fiche: 50-259, 82/12/28, 8303010293.

8303210772 Notice of violation from insp on 821126-1225.
* Region 2, Office of Director. 83/01/19. 2pp. 17635:052. 24X Fiche: 50-259, 83/03/02, 8303210756.

--8303210775 IE Insp Repts 50-259/82-46, 50-260/82-46 & 50-296/82-46 on 821126-1225. Noncompliance noted failure to have control room emergency pressurization sys operable & to perform maint per plant instructions.
PAULK, G. L. Region 2, Office of Director. 83/01/18. 8pp. 17635:054. 24X Fiche: 50-259, 83/03/02, 8303210756.

8303250092 Confirms understanding of App R evaluation criteria re availability of offsite power, manual operator actions & unit trip, per NRC 830318 telcon.
MILLS, L. M. Tennessee Valley Authority. 83/03/22. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17693:073. 24X Fiche: 50-259, 83/03/22, 8303250092.

Q. Adjudicatory correspondence

8303110228 Advises that time for Commission to review ALAB-711 expired. Commission declined review. Decision became final agency action on 830302.
CHILK, S. J. Office of the Secretary of the Commission. 83/03/10. Tennessee Valley Authority. 1p. 17518:357. 24X Fiche: 50-259, 83/03/10, 8303110228.

J. Insurance & indemnity information

8303290341 Forwards Endorsement 64 to NELIA Policy NF-198.
DUCK, J. R. Marsh & McLennan, Inc. 83/03/15. SALTZMAN, J. Assistant Director for State & Licensee Relations. 2pp. 17716:255. 24X Fiche: 50-259, 83/03/15, 8303290341.

# DOCKETED ITEMS

P. Operating license stage documents & correspondence

8303030063 Forwards Amends 86, 83 & 57 to Licenses DPR-33, DPR-52 & DPR-68, respectively, safety evaluation & notice of issuance & availability. Amends change Tech Specs by reducing duration of leak rate tests.
VASSALLO, D. B. Operating Reactors Branch 2 83/02/14 PARRIS, H. G.
Tennessee Valley Authority 2pp 17365.305 24X
Fiche: 50-259, 83/02/14, 8303030063

--8303030068 Amends 86, 83 & 57 to Licenses DPR-33, DPR-52 & DPR-68, respectively, changing Tech Specs by reducing duration of leak rate tests.
VASSALLO, D. B. Operating Reactors Branch 2 83/02/14 38pp
17365.307 24X Fiche: 50-259, 83/02/14, 8303030063

--8303030075 Safety evaluation supporting Amends 86, 83 & 57 to Licenses DPR-33, DPR-52 & DPR-68, respectively.
* Office of Nuclear Reactor Regulation, Director 83/02/14 3pp
17365.345 24X Fiche: 50-259, 83/02/14, 8303030063

--8303030085 Notice of issuance & availability of Amends 86, 83 & 57 to Licenses DPR-33, DPR-52 & DPR-68, respectively.
VASSALLO, D. B. Operating Reactors Branch 2 83/02/14 2pp
17365.348 24X Fiche: 50-259, 83/02/14, 8303030063

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated
Edison Co. of New York, Inc. 18pp 17492.033 24X
Fiche: 50-000, 83/02/16, 8302170082

8303040341 Responds to technical evaluation rept, "Safety Evaluation for Environ Qualification of Safety-Related Electrical Equipment." Ongoing investigations still in progress re Item 87.
MILLS, L. M. Tennessee Valley Authority 83/02/28 VASSALLO, D. B.
Operating Reactors Branch 2 164pp 17372.087 24X
Fiche: 50-259, 83/02/28, 8303040341

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated
Edison Co. of New York, Inc. 17pp 17700.303 24X
Fiche: 50-000, 83/03/02, 8303020321

8303100295 Requests refund re 800121 & 1124 application for amends to OLs. Amends authorizing onsite storage of radwaste applicable to 10CFR30 licenses. Amend fee not required.
MILLS, L. M. Tennessee Valley Authority 83/03/03 MILLER, W. O.
License Fee Management Branch 1p 17489.295 24X
Fiche: 50-000, 83/03/03, 8303100295

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated
Edison Co. of New York, Inc. 51pp 17660.176 24X
Fiche: 50-000, 83/03/07, 8303040005

8303140036 Forwards response to Item 87 from Franklin Research Ctr rept, per NRC 830111 safety evaluation for environ qualification of safety-related electrical equipment, justifying continued operation.
KAMPER, D. S. Tennessee Valley Authority 83/03/07 VASSALLO, D. B.
Operating Reactors Branch 2 15pp 17544.117 24X
Fiche: 50-259, 83/03/07, 8303140036

8303300094 Forwards Region II SER re util response to NUREG-0737, Item II.B.2.2, "Plant Shielding Mods for Vital Area Access." Requirements met.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/08 PARRIS, H. G.
Tennessee Valley Authority 2pp 17749.173 24X
Fiche: 50-259, 83/03/08, 8303300094

--8303300102 SER re util response to NUREG-0737, Item II.B.2.2, "Plant Shielding Mods for Vital Area Access." Shield design & emergency operating procedures acceptable.
* Region 2, Office of Director 83/03/08 2pp 17749.175 24X
Fiche: 50-259, 83/03/08, 8303300094

8303300299 Forwards Amends 87, 84 & 53 to Licenses DPR-33, DPR-52 & DPR-68, respectively & notice of issuance & availability. Amends delete App B ETS re nonradiological water quality-related requirements.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/11 PARRIS, H. G.
Tennessee Valley Authority 3pp 17749.129 24X
Fiche: 50-259, 83/03/11, 8303300299

--8303300308 Amends 87, 84 & 53 to Licenses DPR-33, DPR-52 & DPR-68, respectively, deleting App B ETS pertaining to nonradiological water quality-related requirements required by Federal Water Pollution Control Act Amends of 1972.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/11 32pp
17749.132 24X Fiche: 50-259, 83/03/11, 8303300299

--8303300325 Notice of issuance & availability of Amends 87, 84 & 53 to Licenses DPR-33, DPR-52 & DPR-68, respectively.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/11 2pp
17749.164 24X Fiche: 50-259, 83/03/11, 8303300299

8303300219 Forwards Amend 88 to License DPR-33, safety evaluation & notice of issuance & availability. Amend changes Tech Spec to allow operation w/increased core flow during remainder of Cycle 5.
CLARK, R. J. Operating Reactors Branch 2 83/03/14 PARRIS, H. G.
Tennessee Valley Authority 2pp 17749.284 24X
Fiche: 50-259, 83/03/14, 8303300219

--8303300228 Amend 88 to License DPR-33, changing Tech Specs to allow operation w/increased core flow during remainder of Cycle 5.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/14 7pp
17749.286 24X Fiche: 50-259, 83/03/14, 8303300219

--8303300234 Safety evaluation supporting Amend 88 to License DPR-33.
* Office of Nuclear Reactor Regulation, Director 83/03/14 5pp
17749.293 24X Fiche: 50-259, 83/03/14, 8303300219

--8303300241 Notice of issuance & availability of Amend 88 to License DPR-33.
ROONEY, V. L. Operating Reactors Branch 2 83/03/14 2pp
17749.298 24X Fiche: 50-259, 83/03/14, 8303300219

8303180454 Responds to NRC 830302 & 08 conference calls requesting addl info re RETRAN Methodology Repts TVA-TR81-01 & TVA-MDS-553. Immediate approval of submittal requested.
MILLS, L. M. Tennessee Valley Authority 83/03/15 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 9pp 17621.259
24X Fiche: 50-259, 83/03/15, 8303180454

8303240447 Confirms verbal requirement to submit NPDES permit changes or violations requiring notification per NRC 830311 request.
MILLS, L. M. Tennessee Valley Authority 83/03/22 VASSALLO, D. B.
Operating Reactors Branch 2 1p 17678.343 24X
Fiche: 50-259, 83/03/22, 8303240447

8303310420 Application to amend OLs, revising Tech Specs re drywell leakage in response to IE Bulletin 82-03, "Stress Corrosion Cracking in Thick Wall Large Diameter Stainless Steel Recirculation Sys Piping at BWR Plants."
MILLS, L. M. Tennessee Valley Authority 83/03/25 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 3pp 17755.081
24X Fiche: 50-259, 83/03/25, 8303310420

--8303310424 Proposed Tech Spec changes re drywell leakage.
* Tennessee Valley Authority 83/03/25 11pp 17755.084 24X
Fiche: 50-259, 83/03/25, 8303310420

O. Inspection reports, IE Bulletins & correspondence

8303010448 Responds to NRC 820517 ltr re violations noted in IE Insp Repts 50-259/82-13, 50-260/82-13 & 50-296/82-13. Corrective actions: complete rev of sys operating instructions will be delayed from 830101 to 830201.
MILLS, L. M. Tennessee Valley Authority 82/12/16 O'REILLY, J. P.
Region 2, Office of Director 1p 17343.052 24X
Fiche: 50-259, 82/12/16, 8303010448

8303010293 Responds to NRC 820727 ltr re violations noted in IE Insp Repts 50-259/82-20, 50-260/82-20 & 50-296/82-20. Corrective actions: security program audit will be performed by 830130.
MILLS, L. M. Tennessee Valley Authority 82/12/28 O'REILLY, J. P.
Region 2, Office of Director 1p 17334.086 24X
Fiche: 50-259, 82/12/28, 8303010293

8303010428 Forwards results of mechanical snubber insps required by IE Bulletin 81-01. All Intl Nuclear Safeguards Corp mechanical snubbers installed in Unit 2 replaced w/Pacific Scientific Corp snubbers.
MILLS, L. M. Tennessee Valley Authority 83/02/16 O'REILLY, J. P.
Region 2, Office of Director 2pp 17343.269 24X
Fiche: 50-259, 83/02/16, 8303010428

8303010541 Ack receipt of 830207 ltr & remittance wired on 830216 in payment of civil penalties proposed in 830103 ltr. Corrective actions described in ltr will be examined during future insps.
AXELRAD, J. A. Director's Office, Office of Inspection and Enforcement 83/02/24 PARRIS, H. G. Tennessee Valley Authority
2pp 17342.259 24X Fiche: 50-259, 83/02/24, 8303010541

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521.001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210756 Ack receipt of 830222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-46, 50-260/82-46 & 50-296/82-46.
LEWIS, R. C. Division of Project & Resident Programs. 83/03/02.
PARRIS, H. G. Tennessee Valley Authority. 1p. 17635.044. 24X Fiche: 50-259, 83/03/02, 8303210756.

--8303210765 Responds to NRC 830119 ltr re violations noted in IE Insp Repts 50-259/82-46, 50-260/82-46 & 50-296/82-46. Corrective actions: charcoal trays in control room emergency ventilation sys replaced.
MILLS, L. M. Tennessee Valley Authority. 83/02/22. O'REILLY, J. P. Region 2, Office of Director. 5pp. 17635.045. 24X Fiche: 50-259, 83/03/02, 8303210756.

--8303210771 Forwards IE Insp Repts 50-259/82-46, 50-260/82-46 & 50-296/82-46 on 821126-1225 & notice of violation.
LEWIS, R. C. Division of Project & Resident Programs. 83/01/19.
PARRIS, H. G. Tennessee Valley Authority. 2pp. 17635.050. 24X Fiche: 50-259, 83/03/02, 8303210756.

--8303210772 Notice of violation from insp on 821126-1225.
* Region 2, Office of Director. 83/01/19. 2pp. 17635.052. 24X Fiche: 50-259, 83/03/02, 8303210756.

--8303210775 IE Insp Repts 50-259/82-46, 50-260/82-46 & 50-296/82-46 on 821126-1225 Noncompliance noted: failure to have control room emergency pressurization sys operable & to perform maint per plant instructions.
PAULK, G. L. Region 2, Office of Director. CANTRELL, F. S. Division of Project & Resident Programs. 83/01/18. 8pp. 17635.054. 24X Fiche: 50-259, 83/03/02, 8303210756.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611.070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774.352. 24X Fiche: 50-000, 83/03/21, 8212060367.

8303310420 Application to amend OLs, revising Tech Specs re drywell leakage in response to IE Bulletin 82-03, "Stress Corrosion Cracking in Thick Wall Large Diameter Stainless Steel Recirculation Sys Piping at BWR Plants."
MILLS, L. M. Tennessee Valley Authority. 83/03/25. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 17755.081. 24X Fiche: 50-259, 83/03/25, 8303310420.

--8303310424 Proposed Tech Spec changes re drywell leakage.
* Tennessee Valley Authority. 83/03/25. 11pp. 17755.084. 24X Fiche: 50-259, 83/03/25, 8303310420.

R Periodic operating reports & related correspondence

8303080016 Forwards monthly operating repts for Dec 1982.
JONES, O. T. Tennessee Valley Authority. 83/01/11. Office of Resource Management, Director. 1p. 17458.072. 24X Fiche: 50-259, 83/01/11, 8303080016.

--8303080021 Monthly operating repts for Dec 1982.
THOM, T. Tennessee Valley Authority. 83/01/07. 40pp. 17458.073. 24X Fiche: 50-259, 83/01/11, 8303080016.

8303150490 Forwards monthly operating repts for Jan 1983.
JONES, O. T. Tennessee Valley Authority. 83/02/09. Office of Resource Management, Director. 1p. 17560.349. 24X Fiche: 50-259, 83/02/09, 8303150490.

--8303150496 Monthly operating repts for Jan 1983.
SWINDELL, J. E., THOM, T. Tennessee Valley Authority. 83/02/01. 40pp. 17560.350. 24X Fiche: 50-259, 83/02/09, 8303150490.

8303160216 Central emergency control ctr meteorological data statistics for Oct-Dec 1982, reported per util commitment to NUREG-0737, Item III.A.2.1.
MILLS, L. M. Tennessee Valley Authority. 83/03/09. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17596.323. 24X Fiche: 50-000, 83/03/09, 8303160216.

8303170463 Forwards monthly operating repts for Feb 1983.
JONES, O. T. Tennessee Valley Authority. 83/03/10. Division of Data Automation & Management Information. 1p. 17609.213. 24X Fiche: 50-259, 83/03/10, 8303170463.

--8303170467 Monthly operating repts for Feb 1983.
JONES, O. T., THOM, T. Tennessee Valley Authority. 83/03/01. 44pp. 17609.214. 24X Fiche: 50-259, 83/03/10, 8303170463.

S Reportable occurrences: LERs & related correspondence

8303040492 Forwards LER 83-005/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/02/24. O'REILLY, J. P. Region 2, Office of Director. 1p. 17374.182. 24X Fiche: 50-259, 83/02/24, 8303040492.

--8303040497 LER 83-005/03L-0 on 830126, trouble alarm sounded for control bay elevation 593 fire protection panel 1-25-325, Zone 14. Caused by power loss to some of 16 smoke detectors. Broken nylon insulating screw caused detector to short circuit.
MURPHY, D. Tennessee Valley Authority. 83/02/24. Region 2, Office of Director. 2pp. 17374.183. 24X Fiche: 50-259, 83/02/24, 8303040492.

8303040558 Forwards updated LER 82-013/01X-3.
GREEN, H. J. Tennessee Valley Authority. 83/02/28. O'REILLY, J. P. Region 2, Office of Director. 1p. 17374.185. 24X Fiche: 50-259, 83/02/28, 8303040558.

--8303040569 Updated LER 82-013/01X-3 on 820202, trip setpoint of all 12 degraded voltage relays found low. Caused by setpoint drift. Relays recalibr.
CHRISTOPHER, W. Tennessee Valley Authority. 83/02/28. Region 2, Office of Director. 3pp. 17374.186. 24X Fiche: 50-259, 83/02/28, 8303040558.

8303140601 Forwards LER 83-007/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/03/04. O'REILLY, J. P. Region 2, Office of Director. 1p. 17534.025. 24X Fiche: 50-259, 83/03/04, 8303140601.

--8303140604 LER 83-007/03L-0 on 830205, MSRV 1-1-22 failed to close & drywell unidentified leakage exceeded 5 gpm. Caused by damaged vacuum relief valve failing to reseat. Valve replaced. Mod planned during next refueling outage.
HOLDER, E. T. Tennessee Valley Authority. 83/03/04. Region 2, Office of Director. 2pp. 17534.026. 24X Fiche: 50-259, 83/03/04, 8303140601.

8303150185 Forwards LER 83-009/01T-0.
GREEN, H. J. Tennessee Valley Authority. 83/03/08. O'REILLY, J. P. Region 2, Office of Director. 1p. 17550.282. 24X Fiche: 50-259, 83/03/08, 8303150185.

--8303150193 LER 83-009/01T-0 on 830223, design review of emergency diesel generator engine coolers revealed coolers may not be capable of maintaining cooling water below alarm setpoint. Caused by design error in sizing coolers.
ELY, J. O. Tennessee Valley Authority. 83/03/08. Region 2, Office of Director. 3pp. 17550.283. 24X Fiche: 50-259, 83/03/08, 8303150185.

8303150300 Forwards LER 83-008/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/03/08. O'REILLY, J. P. Region 2, Office of Director. 1p. 17567.067. 24X Fiche: 50-259, 83/03/08, 8303150300.

--8303150306 LER 83-008/03L-0 on 830210, secondary containment breached when turbine bldg to reactor bldg doors opened simultaneously. Caused by failure of interlock sys. Reactor bldg doors not closed far enough to engage strike.
CARTER, S. D. Tennessee Valley Authority. 83/03/08. Region 2, Office of Director. 2pp. 17567.068. 24X Fiche: 50-259, 83/03/08, 8303150300.

8303210423 Forwards updated LER 82-031/03X-3.
GREEN, H. J. Tennessee Valley Authority. 83/03/15. O'REILLY, J. P. Region 2, Office of Director. 1p. 17634.252. 24X Fiche: 50-259, 83/03/15, 8303210423.

--8303210434 Updated LER 82-031/03X-3 on 820510, deuterium analyzer B discovered inoperable due to failure of sample inlet pump to run. Caused by erratic handswitch, GE Model 273A8686G1X2 & Allen Bradley relay. Handswitch & relay replaced.
CARTER, S. Tennessee Valley Authority. 83/03/15. Region 2, Office of Director. 2pp. 17634:253. 24X Fiche: 50-259, 83/03/15, 8303210423.

8303220176 Forwards updated LER 82-068/03X-2.
GREEN, H. J. Tennessee Valley Authority. 83/03/16. O'REILLY, J. P. Region 2, Office of Director. 1p. 17657:117. 24X Fiche: 50-259, 83/03/16, 8303220176.

--8303220179 Updated LER 82-068/03X-2 on 820902, hydrogen analyzer A became inoperable. Caused by personnel error. Engineer inadvertently lifted wires to 1-FSV-76-57. Hydrogen sample inlet pump A po.er relay contacts failed on return to svc.
CARTER, S. D. Tennessee Valley Authority. 83/03/16. Region 2, Office of Director. 2pp. 17657:118. 24X Fiche: 50-259, 83/03/16, 8303220176.

8303240598 Forwards LER 83-011/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/03/17. O'REILLY, J. P. Region 2, Office of Director. 1p. 17683:066. 24X Fiche: 50-259, 83/03/17, 8303240598.

--8303240605 LER 83-011/03L-0 on 830217, radiation monitor RM-90-259A setpoint found above Tech Spec limit. Caused by setpoint drift. Monitor calibr, functionally tested & returned to svc.
BASS, G. W. Tennessee Valley Authority. 83/03/17. Region 2, Office of Director. 2pp. 17683:067. 24X Fiche: 50-259, 83/03/17, 8303240598.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303080442 Submits schedule for NRC operator licensing exam site visits through 1985, in response to Generic Ltr 83-01. Exams on 830815-19 for Watts Bar requested to be postponed due to delay in final fuel loading date.
MILLS, L. M. Tennessee Valley Authority. 83/02/28. ADENSAM, E. Licensing Branch 4. 2pp. 17454:256. 24X Fiche: 50-000, 83/02/28, 8303080442.

X. Onsite Storage of Low Level Waste

8303100295 Requests refund re 800121 & 1124 application for amends to OLs. Amends authorizing onsite storage of radwaste applicable to 10CFR30 licenses. Amend fee not required.
MILLS, L. M. Tennessee Valley Authority. 83/03/03. MILLER, W. O. License Fee Management Branch. 1p. 17489:295. 24X Fiche: 50-000, 83/03/03, 8303100295.

DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8303010293 Responds to NRC 820727 ltr re violations noted in IE Insp Repts 50-259/82-20, 50-260/82-20 & 50-296/82-20. Corrective actions security program audit will be performed by 830130.
MILLS, L. M. Tennessee Valley Authority. 82/12/28. O'REILLY, J. P. Region 2, Office of Director. 1p. 17334:086. 24X Fiche: 50-259, 82/12/28, 8303010293.

8303210772 Notice of violation from insp on 821126-1225.
* Region 2, Office of Director. 83/01/19. 2pp. 17635:052. 24X Fiche: 50-259, 83/03/02, 8303210756.

--8303210775 IE Insp Repts 50-259/82-46, 50-260/82-46 & 50-296/82-46 on 821126-1225. Noncompliance noted: failure to have control room emergency pressurization sys operable & to perform maint per plant instructions.
PAULK, G. L. Region 2, Office of Director. 83/01/18. 8pp. 17635:054. 24X Fiche: 50-259, 83/03/02, 8303210756.

8303250092 Confirms understanding of App R evaluation criteria re availability of offsite power, manual operator actions & unit trip, per NRC 830318 telcon.
MILLS, L. M. Tennessee Valley Authority. 83/03/22. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17693:073. 24X Fiche: 50-259, 83/03/22, 8303250092.

Q. Adjudicatory correspondence

8303110228 Advises that time for Commission to review ALAB-711 expired. Commission declined review. Decision became final agency action on 830302.
CHILK, S. J. Office of the Secretary of the Commission. 83/03/10. Tennessee Valley Authority. 1p. 17518:357. 24X Fiche: 50-259, 83/03/10, 8303110228.

J. Insurance & indemnity information

8303290341 Forwards Endorsement 64 to NELIA Policy NF-198.
DUCK, J. R. Marsh & McLennan, Inc. 83/03/15. SALTZMAN, J. Assistant Director for State & Licensee Relations. 2pp. 17716:255. 24X Fiche: 50-259, 83/03/15, 8303290341.

P. Operating license stage documents & correspondence

8303030063 Forwards Amends 86, 83 & 57 to Licenses DPR-33, DPR-52 & DPR-68, respectively, safety evaluation & notice of issuance & availability. Amends change Tech Specs by reducing duration of leak rate tests.
VASSALLO, D. B. Operating Reactors Branch 2. 83/02/14. PARRIS, H. G. Tennessee Valley Authority. 2pp. 17365:305. 24X Fiche: 50-259, 83/02/14, 8303030063.

--8303030068 Amends 86, 83 & 57 to Licenses DPR-33, DPR-52 & DPR-68, respectively, changing Tech Specs by reducing duration of leak rate tests.
VASSALLO, D. B. Operating Reactors Branch 2. 83/02/14. 38pp. 17365:307. 24X Fiche: 50-259, 83/02/14, 8303030063.

--8303030075 Safety evaluation supporting Amends 86, 83 & 57 to Licenses DPR-33, DPR-52 & DPR-68, respectively.
* Office of Nuclear Reactor Regulation, Director. 83/02/14. 3pp. 17365:345. 24X Fiche: 50-259, 83/02/14, 8303030063.

--8303030085 Notice of issuance & availability of Amends 86, 83 & 57 to Licenses DPR-33, DPR-52 & DPR-68, respectively.
VASSALLO, D. B. Operating Reactors Branch 2. 83/02/14. 2pp. 17365:348. 24X Fiche: 50-259, 83/02/14, 8303030063.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303040341 Responds to technical evaluation rept, "Safety Evaluation for Environ Qualification of Safety-Related Electrical Equipment." Ongoing investigations still in progress re Item 87.
MILLS, L. M. Tennessee Valley Authority. 83/02/28. VASSALLO, D. B. Operating Reactors Branch 2. 164pp. 17372:087. 24X Fiche: 50-259, 83/02/28, 8303040341.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303100295 Requests refund re 800121 & 1124 application for amends to OLs. Amends authorizing onsite storage of radwaste applicable to 10CFR30 licenses. Amend fee not required.
MILLS, L. M. Tennessee Valley Authority. 83/03/03. MILLER, W. O. License Fee Management Branch. 1p. 17489:295. 24X Fiche: 50-000, 83/03/03, 8303100295.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303140036 Forwards response to Item 87 from Franklin Research Ctr rept, per NRC 830111 safety evaluation for environ qualification of safety-related electrical equipment, justifying continued operation.
KAMMER, D. S. Tennessee Valley Authority. 83/03/07. VASSALLO, D. B. Operating Reactors Branch 2. 15pp. 17544:117. 24X Fiche: 50-259, 83/03/07, 8303140036.

8303300094 Forwards Region II SER re util response to NUREG-0737, Item II.B.2.2, "Plant Shielding Mods for Vital Area Access." Requirements met.
VASSALLO, D.B. Operating Reactors Branch 2 83/03/08 PARRIS, H.G.
Tennessee Valley Authority 2pp 17749:173 24X
Fiche: 50-259, 83/03/08, 8303300094.

--8303300102 SER re util response to NUREG-0737, Item II.B.2.2, "Plant Shielding Mods for Vital Area Access." Shield design & emergency operating procedures acceptable.
* Region 2, Office of Director 83/03/08 2pp 17749:175 24X
Fiche: 50-259, 83/03/08, 8303300094.

8303300299 Forwards Amends 87, 84 & 53 to Licenses DPR-33, DPR-52 & DPR-68, respectively & notice of issuance & availability. Amends delete App B ETS re nonradiological water quality-related requirements.
VASSALLO, D.B. Operating Reactors Branch 2 83/03/11 PARRIS, H.G.
Tennessee Valley Authority 3pp 17749:129 24X
Fiche: 50-259, 83/03/11, 8303300299.

--8303300308 Amends 87, 84 & 53 to Licenses DPR-33, DPR-52 & DPR-68, respectively, deleting App B ETS pertaining to nonradiological water quality-related requirements required by Federal Water Pollution Control Act Amends of 1972.
VASSALLO, D.B. Operating Reactors Branch 2 83/03/11 32pp
17749:132 24X Fiche: 50-259, 83/03/11, 8303300299.

--8303300325 Notice of issuance & availability of Amends 87, 84 & 53 to Licenses DPR-33, DPR-52 & DPR-68, respectively.
VASSALLO, D.B. Operating Reactors Branch 2 83/03/11 2pp
17749:164 24X Fiche: 50-259, 83/03/11, 8303300299.

8303180454 Responds to NRC 830302 & 08 conference calls requesting addl info re RETRAN Methodology Repts TVA-TRB1-01 & TVA-MDS-553. Immediate approval of submittal requested.
MILLS, L.M. Tennessee Valley Authority 83/03/15 DENTON, H.R.
Office of Nuclear Reactor Regulation, Director 9pp 17621:259
24X Fiche: 50-259, 83/03/15, 8303180454.

8303240447 Confirms verbal requirement to submit NPDES permit changes or violations requiring notification, per NRC 830311 request.
MILLS, L.M. Tennessee Valley Authority 83/03/22 VASSALLO, D.B.
Operating Reactors Branch 2 1p 17678:343 24X
Fiche: 50-259, 83/03/22, 8303240447.

8303310420 Application to amend OLs, revising Tech Specs re drywell leakage, in response to IE Bulletin 82-03, "Stress Corrosion Cracking in Thick Wall Large Diameter Stainless Steel Recirculation Sys Piping at BWR Plants."
MILLS, L.M. Tennessee Valley Authority 83/03/25 DENTON, H.R.
Office of Nuclear Reactor Regulation, Director 3pp 17755:081
24X Fiche: 50-259, 83/03/25, 8303310420.

--8303310424 Proposed Tech Spec changes re drywell leakage.
* Tennessee Valley Authority 83/03/25 11pp 17755:084 24X
Fiche: 50-259, 83/03/25, 8303310420.

G. Inspection reports, IE Bulletins & correspondence

8303010448 Responds to NRC 820517 ltr re violations noted in IE Insp Repts 50-259/82-13, 50-260/82-13 & 50-296/82-13. Corrective actions: complete rev of sys operating instructions will be delayed from 830101 to 830201.
MILLS, L.M. Tennessee Valley Authority 82/12/16 O'REILLY, J.P.
Region 2, Office of Director 1p 17343:052 24X
Fiche: 50-259, 82/12/16, 8303010448.

8303010293 Responds to NRC 820727 ltr re violations noted in IE Insp Repts 50-259/82-20, 50-260/82-20 & 50-296/82-20. Corrective actions: security program audit will be performed by 830130.
MILLS, L.M. Tennessee Valley Authority 82/12/28 O'REILLY, J.P.
Region 2, Office of Director 1p 17334:086 24X
Fiche: 50-259, 82/12/28, 8303010293.

8303010428 Forwards results of mechanical snubber insps required by IE Bulletin 81-01. All Intl Nuclear Safeguards Corp mechanical snubbers installed in Unit 2 replaced w/Pacific Scientific Corp snubbers.
MILLS, L.M. Tennessee Valley Authority 83/02/16 O'REILLY, J.P.
Region 2, Office of Director 2pp 17343:269 24X
Fiche: 50-259, 83/02/16, 8303010428.

8303010541 Ack receipt of 830207 ltr & remittance wired on 830216 in payment of civil penalties proposed in 830103 ltr. Corrective actions described in ltr will be examined during future insps.
AXELRAD, J.A. Director's Office, Office of Inspection and Enforcement 83/02/24 PARRIS, H.G. Tennessee Valley Authority
2pp 17342:259 24X Fiche: 50-259, 83/02/24, 8303010541.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc.
11lpp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210756 Ack receipt of 830222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-46, 50-260/82-46 & 50-296/82-46.
LEWIS, R.C. Division of Project & Resident Programs 83/03/02
PARRIS, H.G. Tennessee Valley Authority 1p 17635:044 24X
Fiche: 50-259, 83/03/02, 8303210756.

--8303210765 Responds to NRC 830119 ltr re violations noted in IE Insp Repts 50-259/82-46, 50-260/82-46 & 50-296/82-46. Corrective actions: charcoal trays in control room emergency ventilation sys replaced.
MILLS, L.M. Tennessee Valley Authority 83/02/22 O'REILLY, J.P.
Region 2, Office of Director 5pp 17635:045 24X
Fiche: 50-259, 83/03/02, 8303210756.

--8303210771 Forwards IE Insp Repts 50-259/82-46, 50-260/82-46 & 50-296/82-46 on 821126-1225 & notice of violation.
LEWIS, R.C. Division of Project & Resident Programs 83/01/19
PARRIS, H.G. Tennessee Valley Authority 2pp 17635:050 24X
Fiche: 50-259, 83/03/02, 8303210756.

--8303210772 Notice of violation from insp on 821126-1225.
* Region 2, Office of Director 83/01/19 2pp 17635:052 24X
Fiche: 50-259, 83/03/02, 8303210756.

--8303210775 IE Insp Repts 50-259/82-46, 50-260/82-46 & 50-296/82-46 on 821126-1225. Noncompliance noted: failure to have control room emergency pressurization sys operable & to perform maint per plant instructions.
PAULK, G.L. Region 2, Office of Director CANTRELL, F.S. Division of Project & Resident Programs 83/01/18 8pp 17635:054 24X
Fiche: 50-259, 83/03/02, 8303210756.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc.
117pp 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12lpp 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

8303310420 Application to amend OLs, revising Tech Specs re drywell leakage, in response to IE Bulletin 82-03, "Stress Corrosion Cracking in Thick Wall Large Diameter Stainless Steel Recirculation Sys Piping at BWR Plants."
MILLS, L.M. Tennessee Valley Authority 83/03/25 DENTON, H.R.
Office of Nuclear Reactor Regulation, Director 3pp 17755:081
24X Fiche: 50-259, 83/03/25, 8303310420.

--8303310426 Proposed Tech Spec changes re drywell leakage.
* Tennessee Valley Authority 83/03/25 11pp 17755:084 24X
Fiche: 50-259, 83/03/25, 8303310420.

R. Periodic operating reports & related correspondence

8303080016 Forwards monthly operating repts for Dec 1982.
JONES, O.T. Tennessee Valley Authority 83/01/11 Office of Resource Management, Director 1p 17458:072 24X
Fiche: 50-259, 83/01/11, 8303080016.

--8303080021 Monthly operating repts for Dec 1982.
THOM, T. Tennessee Valley Authority 83/01/01 40pp 17458:073
24X Fiche: 50-259, 83/01/11, 8303080016.

8303150490 Forwards monthly operating repts for Jan 1983.
JONES, O.T. Tennessee Valley Authority 83/02/09 Office of Resource Management, Director 1p 17560:349 24X
Fiche: 50-259, 83/02/09, 8303150490.

--8303150496 Monthly operating repts for Jan 1983.
SWINDILL, J.E., THOM, T. Tennessee Valley Authority 83/02/01
40pp 17560:350 24X Fiche: 50-259, 83/02/09, 8303150490.

8303160216 Central emergency control ctr meteorological data statistics for Oct-Dec 1982 reported per util commitment to NUREG-0737, Item III.A.2.1.
MILLS,L.M. Tennessee Valley Authority 83/03/09 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 2pp 17596.323 24X Fiche 50-000,83/03/09,8303160216.

8303170463 Forwards monthly operating repts for Feb 1983.
JONES,O.T. Tennessee Valley Authority 83/03/10 Division of Data Automation & Management Information 1p 17609.213 24X Fiche 50-259,83/03/10,8303170463.

--8303170467 Monthly operating repts for Feb 1983.
JONES,O.T.; THOM,T. Tennessee Valley Authority 83/03/01 44pp 17609.214 24X Fiche 50-259,83/03/10,8303170463.

S Reportable occurrences, LERs & related correspondence

8303040426 Forwards LER 83-001/03L-0.
GREEN,H.J. Tennessee Valley Authority 83/02/25 O'REILLY,J.P. Region 2, Office of Director 1p 17374.289 24X Fiche 50-260,83/02/25,8303040426.

--8303040433 LER 83-001/03L-0 on 830128, interlock providing rod withdrawal block inoperable when refuel platform moved over core.Caused by failure of limit switch 2 due to stuck plunger.
HOLDER,E.T. Tennessee Valley Authority 83/02/25 Region 2, Office of Director 2pp 17374.290 24X Fiche 50-260,83/02/25, 8303040426.

8303140509 Forwards LER 83-004/01T-0.
GREEN,H.J. Tennessee Valley Authority 83/03/03 O'REILLY,J.P. Region 2, Office of Director 1p 17540.207 24X Fiche 50-260,83/03/03,8303140509.

--8303140520 LER 83-004/01T-0 on 830220, reactor water level switch setpoints discovered out-of-tolerance.Caused by setpoint drift in Barton 288 switches.Switches recalibr & will be replaced per DCR 1396.
BASS,G. Tennessee Valley Authority 83/03/03 Region 2, Office of Director 3pp 17540.208 24X Fiche 50-260,83/03/03, 8303140509.

8303160419 Forwards LER 83-003/03L-0.
GREEN,H.J. Tennessee Valley Authority 83/03/11 O'REILLY,J.P. Region 2, Office of Director 1p 17587.293 24X Fiche 50-260,83/03/11,8303160419.

--8303160423 LER 83-003/03L-0 on 830213, during refueling, continuous air monitor 2-RM-90-250 rendered inoperable due to broken drive belt.Caused by normal wear due to continuous operation.Std V-belt for Schwitzer Model 325 air pump replaced.
CLARK,J.R. Tennessee Valley Authority 83/03/11 Region 2, Office of Director 2pp 17587.294 24X Fiche 50-260,83/03/11, 8303160419.

8303220086 Forwards LER 83-005/03L-0.
GREEN,H.J. Tennessee Valley Authority 83/03/16 O'REILLY,J.P. Region 2, Office of Director 1p 17650.057 24X Fiche 50-260,83/03/16,8303220086.

--8303220097 LER 83-005/03L-0 on 830216, during integrated leak rate test while in refueling outage, primary containment leak rate exceeded Tech Specs.Caused by leak around flange of 2-FCV-64-20 at gasket.Flange bolts tightened.
HOLDER,E. Tennessee Valley Authority 83/03/16 Region 2, Office of Director 2pp 17650.058 24X Fiche 50-260,83/03/16, 8303220086.

8303220318 Forwards updated LER 82-021/03X-1.
GREEN,H.J. Tennessee Valley Authority 83/03/16 O'REILLY,J.P. Region 2, Office of Director 1p 17656.153 24X Fiche 50-260,83/03/16,8303220318.

--8303220324 Updated LER 82-021/03X-1 on 820720, while performing SI4.7.D.1.B-1(A), hydrogen analyzer B became inoperable. Caused by failed solenoid valve due to Valcor Engineering Corp zener P/N V52676-529 failure.Zeners removed.
CARTER,S.D. Tennessee Valley Authority 83/03/16 Region 2, Office of Director 3pp 17656.154 24X Fiche 50-260,83/03/16, 8303220318.

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT,D.G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp 24X Fiche 50-000,83/02/24, 8302250505.

8303080442 Submits schedule for NRC operator licensing exam site visits through 1985, in response to Generic Ltr 83-01. Exams on 830815-19 for Watts Bar requested to be postponed due to delay in final fuel loading date.
MILLS,L.M. Tennessee Valley Authority 83/02/28 ADENSAM,E. Licensing Branch 4 2pp 17454.256 24X Fiche 50-000,83/02/28, 8303080442.

X Onsite Storage of Low Level Waste

8303100295 Requests refund re 800121 & 1124 application for amends to OLs.Amends authorizing onsite storage of radwaste applicable to 10CFR30 licenses.Amend fee not required.
MILLS,L.M. Tennessee Valley Authority 83/03/03 MILLER,W.O. License Fee Management Branch 1p 17489.295 24X Fiche 50-000,83/03/03,8303100295.

DOCKET 50-261 H. B. ROBINSON PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8302280359 Provides updated status on four App R exemption requests denied in draft SER & transmits clarifying info per NRC request W/two aperture cards.Aperture cards are available in PDR.
FURR,B.J. Carolina Power & Light Co. 83/02/23 VARGA,S.A. Operating Reactors Branch 1 2pp 17313.037 24X Fiche 50-261,83/02/23,8302280359.

8303150565 Forwards IE Safeguards Insp Rept 50-261/83-04 on 830207-11. No noncompliance noted.
VERRELLI,D. Division of Project & Resident Programs 83/03/04 UTLEY,E.E. Carolina Power & Light Co. 2pp 17568.031 24X Fiche 50-261,83/03/04,8303150565.

--8303150578 IE Safeguards Insp Rept 50-261/83-04 on 830207-11.No noncompliance noted.Major areas inspected:security plan & implementing procedures & security organization-mgt.Details withheld (ref 10CFR73.21).
TOBIN,W.J.; HALL,B.L. Region 2, Office of Director MCGUIRE,D.R. Division of Emergency Preparedness & Materials Safety 83/03/03 1p 17568.033 24X Fiche 50-261,83/03/04,8303150565.

8303210590 Ack receipt of 830224 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/82-31.
LEWIS,R.C. Division of Project & Resident Programs 83/03/14 UTLEY,E.E. Carolina Power & Light Co. 1p 17636.332 24X Fiche 50-261,83/03/14,8303210590.

--8303210602 Responds to NRC 820922 ltr re violations noted in IE Insp Rept 50-261/82-31.Corrective actions:routine radiation work permit for decontamination work revised to allow general decontamination in all but three areas.
STARKEY,R.B. Carolina Power & Light Co. 83/02/24 O'REILLY,J.P. Region 2, Office of Director 2pp 17636.333 24X Fiche 50-261,83/03/14,8303210590.

8303280011 Submits info re planned vent sys design for emergency operating facilities.Vent sys provides slight positive pressure to bldg,ensuring that any leakage would be from inside bldg to outside atmosphere.
ZIMMERMAN,S.R. Carolina Power & Light Co. 83/03/22 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 2pp 17707.230 24X Fiche 50-000,83/03/22,8303280011.

Q Adjudicatory correspondence

8303040485 Suppl to petition to intervene delineating contentions. Affidavit of Svc encl.
KIRVEN,J. Affiliation Unknown 83/03/01 Atomic Safety and Licensing Board Panel 7pp 17374.001 24X Fiche 50-261,83/03/01, 8303040485.

8303080128 Suppl to Hartsville Group petition to intervene & request for hearing; listing contentions.Affidavit of Svc encl.
MATTHEWS,B.A. Affiliation Unknown 83/03/01 Commissioners 11pp 17458.217 24X Fiche 50-261,83/03/01,8303080128.

8303170475 Advises that response to Hartsville Group & Concerned Fools of Darlington County supplS to petitions to intervene will be filed separately Util final steam generator repair rept encl W/o encl
TROWBRIDGE, G F Shaw, Pittman, Potts & Trowbridge TROWBRIDGE, G F Carolina Power & Light Co 83/03/14 MARGULIES, M B , KLINE, J R Atomic Safety and Licensing Board Panel HETRICK, D L Arizona, Univ of 2pp 17610 243 24X Fiche 50-261, 82 03/14, 8303170475

8303170488 Response opposing Concerned Fools of Darlington County 830301 suppl to petition to intervene, containing contentions No contentions identified No basis stated for any contention
TROWBRIDGE, G F Carolina Power & Light Co TROWBRIDGE, G F Shaw, Pittman, Potts & Trowbridge 83/03/14 Atomic Safety and Licensing Board Panel 1p 17610 265 24X Fiche 50-261, 83/03/14, 8303170488

--8303170496 Response to Hartsville Group 830301 suppl to petition to intervene Opposes Contentions 1, 4, 5, 6, 7, 8, 9 & portion of 3 Contentions 2 & portion of 3 are allowable Suggests contentions be rewritten Certificate of Svc encl
TROWBRIDGE, G F Carolina Power & Light Co TROWBRIDGE, G F Shaw, Pittman, Potts & Trowbridge 83/03/14 Atomic Safety and Licensing Board Panel 13pp 17610 266 24X Fiche 50-261, 83/03/14, 8303170488

8303170496 Response to Hartsville Group 830301 suppl to petition to intervene Opposes Contentions 1, 4, 5, 6, 7, 8, 9 & portion of 3 Contentions 2 & portion of 3 are allowable Suggests contentions be rewritten Certificate of Svc encl
TROWBRIDGE, G F Carolina Power & Light Co 83/03/14 Atomic Safety and Licensing Board Panel 13pp 17610 266 24X Fiche 50-261, 83/03/14, 8303170496

8303220252 Response opposing all Concerned Fools of Darlington County contentions & Hartsville Group Contentions 4, 5, 7, 8, 9 & portion of Contention 3 Contention 1 should be reworded & consolidated w/Contention 6 Certificate of Svc encl
KARMAN, M Hearings Division 83/03/18 Atomic Safety and Licensing Board Panel 11pp 17656 348 24X Fiche 50-261, 83/03/18, 8303220252

8303280016 Advises that 830317 ltr requesting placement on svc list sent to Ofc of Secretary, Docketing & Svc Section
MCDOW, J Atomic Safety and Licensing Board Panel 83/03/22
LONG, K E North Carolina, State of 1p 17707 286 24X
Fiche 50-261, 83/03/22 8303280016

J. Insurance & indemnity information

8303150192 Forwards MAELU Certificate M-21 & Endorsements 1, 2 & 3 to MAELU Master Policy 1
BARHAM, C D Carolina Power & Light Co 83/03/11 SALTZMAN, J Assistant Director for State & Licensee Relations 10pp 17555 170 24X Fiche 50-261, 83/03/11, 8303150192

8303150197 Forwards NELIA Certificate N-21 & Endorsements 1, 2 & 3 to NELIA Master Policy 1
BARHAM, C D Carolina Power & Light Co 83/03/11 SALTZMAN, J Assistant Director for State & Licensee Relations 10pp 17555 153 24X Fiche 50-261, 83/03/11, 8303150197

8303150308 Forwards Endorsement 58 to MAELU Policy MF-49
BARHAM, C D Carolina Power & Light Co 83/03/11 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 17567 015 24X Fiche 50-261, 83/03/11, 8303150308

8303150315 Forwards Endorsement 72 to NELIA Policy NF-180
BARHAM, C D Carolina Power & Light Co 83/03/11 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 17566 270 24X Fiche 50-261, 83/03/11, 8303150315

8303220344 Submits info re present level & source of onsite property damage insurance
ZIMMERMAN, B R Carolina Power & Light Co 83/03/18 EISENHUT, D G Division of Licensing 2pp 17648 357 24X Fiche 50-000, 83/03/18, 8303220344

P. Operating license stage documents & correspondence

8303030306 Forwards tables showing results of applying ORIGEN-S code & Shielding Analytical Sequence 2 of SCALE sys to computation of quantities of heavy metal isotopes in discharged fuel
HERMANN, O W Union Carbide Corp 79/04/20 LOWENBERG, H Office of Nuclear Material Safety & Safeguards, Director 12pp 17365 177 24X Fiche 50-261, 79/04/20, 8303030306

8303030325 Forwards revised comparison table of experimental & ORIGEN-S computed isotopic compositions of facility reactor discharged fuel Table displays predominant reason for deviation in results of each isotope
HERMANN, O W Union Carbide Corp 79/05/02 LOWENBERG, H Assistant Director for Operations & Technology 3pp 17365 131 24X Fiche 50-261, 79/05/02, 8303030325

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24X
Fiche 50-000, 83/02/16, 8302170082

8303040057 Forwards EIA & negative declaration re proposed disposal procedure for slight contaminated sediment from two settling ponds within restricted area
VARGA, S A Operating Reactors Branch 1 83/02/18 UTLEY, E E Carolina Power & Light Co 3pp 17425 081 24X
Fiche 50-261, 83/02/18, 8303040057

--8303040062 EIA supporting Tech Spec re proposed disposal procedure for radioactively contaminated sediment from two settling ponds
NEHEMIAS, J , LEE, J Operating Reactors Branch 1 83/02/18 7pp 17425 084 24X Fiche 50-261, 83/02/18, 8303040057

--8303040076 Negative declaration supporting proposed Tech Specs for License DPR-23 re disposal procedure for radioactively contaminated sediment from two settling ponds
VARGA, S A Operating Reactors Branch 1 83/02/18 2pp 17425 091 24X Fiche 50-261, 83/02/18, 8303040057

8303010044 Notification of 830311 meeting w/util in Bethesda, MD to discuss relief thermal margins for Cycle 10 core reload design
REGUA, G Operating Reactors Branch 1 83/02/22 VARGA, S A Operating Reactors Branch 1 2pp 17322 338 24X
Fiche 50-261, 83/02/22, 8303010044

8303030703 Notification of 830307 meeting w/utils & NUS Corp in Bethesda, MD to discuss proposed rev to 10CFR40 36 (Tech Specs)
BRINKMAN, D S Standardization & Special Projects Branch 83/02/22
THOMAS, C O Standardization & Special Projects Branch 2pp 17363 227 24X Fiche 50-000, 83/02/22, 8303030703

8303110091 Forwards Amend 75 to License DPR-23, safety evaluation & notice of issuance & availability Amend revises Tech Specs to provide 72 h to make operable essential features of auxiliary feedwater pumps
REGUA, G Operating Reactors Branch 1 83/02/25 UTLEY, E E Carolina Power & Light Co 2pp 17526 202 24X
Fiche 50-261, 83/02/25, 8303110091

--8303110104 Amend 75 to License DPR-23, revising Tech Specs to provide 72 h to make operable essential features of auxiliary feedwater pumps & clarify conditions under which at least one pressurizer safety relief valve must be operable
VARGA, S A Operating Reactors Branch 1 83/02/25 7pp 17526 204 24X Fiche 50-261, 83/02/25, 8303110091

--8303110109 Safety evaluation supporting Amend 75 to License DPR-23
* Office of Nuclear Reactor Regulation, Director 83/02/25 2pp 17526 211 24X Fiche 50-261, 83/02/25, 8303110091

--8303110117 Notice of issuance & availability of Amend 75 to License DPR-23
VARGA, S A Operating Reactors Branch 1 83/02/25 2pp 17526 213 24X Fiche 50-261, 83/02/25, 8303110091

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/03/0 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X
Fiche 50-000, 83/03/02, 8303020321

8303160671 Requests response to NRC concern re blocking of steam line high differential pressure safety injection signal during cooldown Info due in 30 days
VARGA, S A Operating Reactors Branch 1 83/03/04 UTLEY, E E Carolina Power & Light Co 4pp 17600 283 24X
Fiche 50-261, 83/03/04, 8303160671

# DOCKETED ITEMS

8303220053 Submits justification for continued operation per NRC 830105 SER & Franklin Research Ctr technical evaluation rept. Items 16 & 17 re GEMS transmitters, Models XM-36495 & XM-52495.
ZIMMERMAN, S. R. Carolina Power & Light Co. 83/03/04 VARGA, S. A.
Operating Reactors Branch 1. 4pp. 17652:162. 24X
Fiche: 50-261, 83/03/04, 8303220053.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303300031 Forwards order confirming util commitment to implement post-TMI items set forth in NUREG-0737 & Generic Ltrs 82-05 & 82-10.
VARGA, S. A. Operating Reactors Branch 1. 83/03/14 UTLEY, E. E. Carolina Power & Light Co. 2pp. 17751:142. 24X
Fiche: 50-261, 83/03/14, 8303300031.

--8303300040 Order confirming util commitment to implement post-TMI-related items set forth in NUREG-0737 & Generic Ltrs 82-05 & 82-10. Hearing may be requested within 20 days of order publication.
PURPLE, R. A. Division of Licensing. 83/03/14 Carolina Power & Light Co. 9pp. 17751:144. 24X Fiche: 50-261, 83/03/14, 8303300031.

8303220101 Responds to NRC 830210 request for addl info re NUREG-0737, Items I. A. 1. 2. 1. 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training & Qualification" & II. B. 4, "Training For Mitigating Core Damage."
ZIMMERMAN, S. R. Carolina Power & Light Co. 83/03/17 VARGA, S. A.
Operating Reactors Branch 1. 4pp. 17650:060. 24X
Fiche: 50-261, 83/03/17, 8303220101.

8303220327 Responds to NRC 830105 ltr re possible proprietary status of SER for environ qualification of safety-related electrical equipment. Listed info identified by item & page number deemed proprietary by Westinghouse.
ZIMMERMAN, S. R. Carolina Power & Light Co. 83/03/18 VARGA, S. A.
Operating Reactors Branch 1. 2pp. 17655:339. 24X
Fiche: 50-261, 83/03/18, 8303220327.

8303250142 Forwards "Supplemental Info for Degraded Grid Voltage Analysis," in response to NRC 830118 request re electrical distribution sys voltages. Util does not plan to complete implementation of emergency bus alarms.
EURY, L. W. Carolina Power & Light Co. 83/03/23 VARGA, S. A.
Operating Reactors Branch 1. 1p. 17691:159. 24X
Fiche: 50-261, 83/03/23, 8303250142.

--8303250143 "Supplemental Info for Degraded Grid Voltage Analysis."
NARAYANI, I. V.; FIELDS, W. W.; MORELAND, R. Ebasco Services, Inc. (subs. of Enserch Corp.). 83/03/03. 134pp. 17691:161. 24X
Fiche: 50-261, 83/03/23, 8303250142.

8303290491 Withdraws request for hearing re NRC order imposing environ qualification requirements for facilities. Withdrawal predicated on interpretation of final rule on environ qualification. Notification to contrary requested by 830524.
UTLEY, E. E. Carolina Power & Light Co. 83/03/24 EISENHUT, D. G. Division of Licensing. 2pp. 17724:338. 24X Fiche: 50-000, 83/03/24, 8303290491.

## G. Inspection reports, IE Bulletins & correspondence

8303010414 Forwards IE Insp Rept 50-261/83-01 on 830110-14. No noncompliance noted.
VERRELLI, D. M. Division of Project & Resident Programs. 83/02/03.
UTLEY, E. E. Carolina Power & Light Co. 2pp. 17343:163. 24X
Fiche: 50-261, 83/02/03, 8303010414.

--8303010416 IE Insp Rept 50-261/83-01 on 830110-14. No noncompliance noted. Major areas inspected: QC & confirmatory measurements, including review of QC program, audit results & comparison of licensee & NRC mobile lab analyses of split samples.
EVANS, C. D.; MONTGOMERY, D. M. Division of Engineering & Radiological Safety Programs. 83/02/01. 8pp. 17343:165. 24X
Fiche: 50-261, 83/02/03, 8303010414.

8303010466 Forwards IE Insp Rept 50-261/83-03 on 830118-21. No noncompliance noted.
VERRELLI, D. M. Division of Project & Resident Programs. 83/02/07.
UTLEY, E. E. Carolina Power & Light Co. 2pp. 17343:297. 24X
Fiche: 50-261, 83/02/07, 8303010466.

--8303010471 IE Insp Rept 50-261/83-03 on 830118-21. No noncompliance noted. Major areas inspected: liquid & gaseous radwaste.
ALBRIGHT, R. H. Region 2, Office of Director. BARR, K. P. Division of Emergency Preparedness & Materials Safety. 83/02/04. 3pp. 17343:300. 24X Fiche: 50-261, 83/02/07, 8303010466.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210371 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Penetrations mfg by Crouse-Hinds Co to Westinghouse design & spec.
FURR, B. J. Carolina Power & Light Co. 83/03/03. O'REILLY, J. P. Region 2, Office of Director. 1p. 17634:149. 24X
Fiche: 50-261, 83/03/03, 8303210371.

8303150565 Forwards IE Safeguards Insp Rept 50-261/83-04 on 830207-11. No noncompliance noted.
VERRELLI, D. Division of Project & Resident Programs. 83/03/04.
UTLEY, E. E. Carolina Power & Light Co. 2pp. 17568:031. 24X
Fiche: 50-261, 83/03/04, 8303150565.

--8303150578 IE Safeguards Insp Rept 50-261/83-04 on 830207-11. No noncompliance noted. Major areas inspected: security plan & implementing procedures & security organization-mgt. Details withheld (ref 10CFR73.21).
TOBIN, W. J.; HALL, B. L. Region 2, Office of Director. MCGUIRE, D. R. Division of Emergency Preparedness & Materials Safety. 83/03/03. 1p. 17568:033. 24X Fiche: 50-261, 83/03/04, 8303150565.

8303210367 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Operators instructed to rept reactor trip breaker failure as significant event as of 830301.
HURFORD, W. J. Carolina Power & Light Co. 83/03/04. O'REILLY, J. P. Region 2, Office of Director. 3pp. 17631:349. 24X
Fiche: 50-261, 83/03/04, 8303210367.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303210376 Ack receipt of 830304 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/82-42.
LEWIS, R. C. Division of Project & Resident Programs. 83/03/11.
UTLEY, E. E. Carolina Power & Light Co. 1p. 17631:330. 24X
Fiche: 50-261, 83/03/11, 8303210376.

--8303210379 Responds to NRC 830202 ltr re violations noted in IE Insp Rept 50-261/82-42. Corrective actions: all safety-related instruments added or altered by mods will be reviewed to ensure correct info is on calibr sheet.
STARKEY, R. B. Carolina Power & Light Co. 83/03/04. O'REILLY, J. P. Region 2, Office of Director. 5pp. 17631:331. 24X
Fiche: 50-261, 83/03/11, 8303210376.

--8303210381 Forwards IE Insp Rept 50-261/82-42 on 821211-830109 & notice of violation.
LEWIS, R. C. Division of Project & Resident Programs. 83/02/02.
UTLEY, E. E. Carolina Power & Light Co. 2pp. 17631:336. 24X
Fiche: 50-261, 83/03/11, 8303210376.

--8303210383 Notice of violation from insp on 821211-830109.
* Region 2, Office of Director. 83/02/02. 2pp. 17631:338. 24X
Fiche: 50-261, 83/03/11, 8303210376.

--8303210386 IE Insp Rept 50-261/82-42 on 821211-830109. Noncompliance noted: low temp overpressure protection sys incapable of meeting design bases & failure to establish adequate calibr values.
WEISE, S. Region 2, Office of Director. BEMIS, P. Division of Project & Resident Programs. 83/01/24. 9pp. 17631:340. 24X
Fiche: 50-261, 83/03/11, 8303210376.

8303210590 Ack receipt of 830224 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/82-31.
LEWIS, R. C. Division of Project & Resident Programs. 83/03/14.
UTLEY, E. E. Carolina Power & Light Co. 1p. 17636:332. 24X
Fiche: 50-261, 83/03/14, 8303210590.

--8303210602 Responds to NRC 820922 ltr re violations noted in IE Insp Rept 50-261/82-31. Corrective actions: routine radiation work permit for decontamination work revised to allow general decontamination in all but three areas.
STARKEY, R. B. Carolina Power & Light Co. 83/02/24. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17636:333. 24X
Fiche: 50-261, 83/03/14, 8303210590.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12lpp. 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

R. Periodic operating reports & related correspondence

8303150564 Forwards monthly operating rept for Feb 1983.
STARKEY, R. B. Carolina Power & Light Co. 83/03/10 DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 1p. 17568:014 24X Fiche: 50-261, 83/03/10, 8303150564.

--8303150570 Monthly operating rept for Feb 1983.
NORRIS, H. B. Carolina Power & Light Co. 83/03/02 3pp. 17568:015 24X Fiche: 50-261, 83/03/10, 8303150564.

S. Reportable occurrences, LERs & related correspondence

8303210598 RO-82-009 re failure of motor operated valve RHR-759A. Due to larger than anticipated work scope, completion date for corrective actions revised. Insp & testing of torque switch will be completed by end of next refueling outage.
STARKEY, R. B. Carolina Power & Light Co. 83/02/28 O'REILLY, J. P. Region 2, Office of Director 2pp. 17636:328 24X Fiche: 50-261, 83/02/28, 8303210598.

8303240385 Forwards LER 83-002/03L-0.
STARKEY, R. B. Carolina Power & Light Co. 83/03/17 O'REILLY, J. P. Region 2, Office of Director 1p. 17679:109 24X Fiche: 50-261, 83/03/17, 8303240385.

--8303240391 LER 83-002/03L-0 on 830215, safety injection pump A tripped after being started for routine filling of accumulators. Caused by faulty pump breaker overcurrent trip device replaced. Evaluation of event continuing.
COX, H. T. Carolina Power & Light Co. 83/03/17 Region 2, Office of Director 2pp. 17679:110 24X Fiche: 50-261, 83/03/17, 8303240385.

T. Hearing transcripts on non-antitrust matters

8303310032 Transcript of 830324 proceedings in Florence, SC. Pp. 1-91.
* Atomic Safety and Licensing Board Panel 83/03/24 91pp. 17756:158 24X Fiche: 50-261, 83/03/24, 8303310032.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303090350 Submits projected requests for site visits to conduct operator license exams through Dec 1985 in response to Generic Ltr 83-01.
ZIMMERMAN, S. P. Carolina Power & Light Co. 83/03/02 EISENHUT, D. G. Division of Licensing 2pp. 17472:138 24X Fiche: 50-000, 83/03/02, 8303090350.

DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

F. Security, medical, emergency & fire protection plans

8303090685 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 83/03/02 Document Management Branch 1p. 17480:242 24X Fiche: 50-263, 83/03/02, 8303090685.

--8303090691 Forwards public version of revised emergency plan implementing procedures, including Procedures A.2-406 re offsite dose projection & A.2-422 re stack iodine/particulate sampling & analysis.
WARD, P. E. Northern States Power Co. 83/02/08 Region 3, Office of Director 1p. 17480:243 24X Fiche: 50-263, 83/03/02, 8303090685.

--8303090698 Public version of revised emergency plan implementing procedures, including Procedures A.2-406 re offsite dose projection & A.2-422 re stack iodine/particulate sampling & analysis.
ROY, R., FEY, F. L. Northern States Power Co. 83/02/02 22pp. 17480:244 24X Fiche: 50-263, 83/03/02, 8303090685.

8303100180 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 83/03/02 Document Management Branch 1p. 17495:148 24X Fiche: 50-000, 83/03/02, 8303100180.

--8303100186 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1.10 re offsite surveys, EPIP 1.1.11 re accident assessment & EPIP 1.1.14 re vendor & consultant svcs.
WARD, E. C. Northern States Power Co. 83/02/17 Region 3, Office of Director 1p. 17495:149 24X Fiche: 50-000, 83/03/02, 8303100180.

--8303100193 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1.10 re offsite surveys, EPIP 1.1.11 re accident assessment & EPIP 1.1.14 re vendor & consultant svcs.
HUDSON, G., WARD, E. C. Northern States Power Co. 83/02/17 62pp. 17495:150 24X Fiche: 50-000, 83/03/02, 8303100180.

8303230305 Responds to 821230 ltr re Rev 12 to security plan. Section 5.2.2 changes decrease security effectiveness & are inconsistent w/provisions of 10CFR50.54(p). Remaining changes consistent & acceptable.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/15 MUSOLF, D. M. Northern States Power Co. 3pp. 17686:179 24X Fiche: 50-263, 83/03/15, 8303230305.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director 83/03/22 Commonwealth Edison Co. 2pp. 17690:316 24X Fiche: 50-000, 83/03/22, 8303240440.

8303280216 Discusses actions to be taken re disposition of unresolved App R exemption requests. Previous request for relief from requirements to upgrade structural steel in fire zone 1C withdrawn.
MUSOLF, D. Northern States Power Co. 83/03/22 Office of Nuclear Reactor Regulation, Director 1p. 17706:292 24X Fiche: 50-263, 83/03/22, 8303280216.

8303300679 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 83/03/28 Document Management Branch 1p. 17764:074 24X Fiche: 50-263, 83/03/28, 8303300679.

--8303300681 Forwards public version of revised emergency plan implementing procedures, including Procedures A.2-001 re emergency organization, A.2-101 re classification of emergencies & A.2-108 re access control during emergencies.
WARD, E. C. Northern States Power Co. 83/02/26 Region 3, Office of Director 1p. 17764:075 24X Fiche: 50-263, 83/03/28, 8303300679.

--8303300685 Public version of revised emergency plan implementing procedures, including Procedures A.2-001 re emergency organization, A.2-101 re classification of emergencies & A.2-108 re access control during emergencies.
* Northern States Power Co. 83/02/22 131pp. 17764:076 24X Fiche: 50-263, 83/03/28, 8303300679.

I. Financial information

8303280039 Forwards Annual Financial Rept 1982.
BRUSVEN, A. D. Northern States Power Co. 83/03/23 Office of Nuclear Reactor Regulation, Director 1p. 17707:107 24X Fiche: 50-000, 83/03/23, 8303280039.

--8303280044 Annual Financial Rept 1982.
* Northern States Power Co. 82/12/31 43pp. 17707:108 24X Fiche: 50-000, 83/03/23, 8303280039.

8303300123 Forwards suppl to Annual Financial Rept 1982.
BRUSVEN, A. D. Northern States Power Co. 83/03/25 Office of Nuclear Reactor Regulation, Director 1p. 17734:330 24X Fiche: 50-000, 83/03/25, 8303300123.

--8303300133 Suppl to Annual Financial Rept 1982.
* Northern States Power Co. 83/03/31 21pp. 17734:331 24X Fiche: 50-000, 83/03/25, 8303300123.

P. Operating license stage documents & correspondence

8303100065 FOIA request for NUREG-0313, results of stress ratio index tests on welds at facility & info re intergranular stress corrosion cracking & performance of weld overlay patches. VAN ALLEN, S.E. Northern Sun Alliance. 82/01/17. Office of Administration. 1p. 17494:147. 24X Fiche: 50-263, 83/01/17, 8303100065.

8303230298 FOIA request for three categories of documents. VAN ALLEN, S.E. Northern Sun Alliance. 83/01/17. Division of Rules and Records. 1p. 17686:182. 24X Fiche: 50-263, 83/01/17, 8303230298.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl. EISENHUT, D.G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303230302 Partial response to FOIA request for three categories of documents. Addl info needed in order to locate EDS Rept 01-0910-1137, "Environ Effects Due to Pipe Rupture," Dec 1980. Document C withheld (ref FOIA Exemption 4). FELTON, J.M. Division of Rules and Records. 83/02/23. VAN ALLEN, S.E. Northern Sun Alliance. 2pp. 17686:183. 24X Fiche: 50-263, 83/02/23, 8303230302.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in BTS on ESF cleanup sys. Svc list encl. EISENHUT, D.G. Division of Licensing. 83/02/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/02/02, 8303020321.

8303100160 Responds to request for addl info re environ qualification of safety-related electrical equipment, originally submitted on 830208. Valve actuators found to function as required during accident conditions. MUSOLF, D. Northern States Power Co. 83/02/03. Office of Nuclear Reactor Regulation, Director. 7pp. 17485:232. 24X Fiche: 50-263, 83/03/03, 8303100160.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys. KEPPLER, J.G. Region 3, Office of Director. 83/03/03. Commonwealth Edison Co. 2pp. 17492:014. 24X Fiche: 50-000, 83/03/03, 8303100364.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl. EISENHUT, D.G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303170500 Forwards duplicates of util 821116, 08 & 0721 ltrs re implementation of TMI items not previously received by NRC. MUSOLF, D. Northern States Power Co. 83/03/11. Office of Nuclear Reactor Regulation, Director. 1p. 17610:297. 24X Fiche: 50-263, 83/03/11, 8303170500.

--8303170512 Forwards addl info in response to Generic Ltr 82-12 & NUREG-0737, Item I.A.1.3. Overtime will be limited for all plant personnel so that total work time does not exceed 16 h in any 24 h period. MUSOLF, D. Northern States Power Co. 82/11/16. Office of Nuclear Reactor Regulation, Director. 2pp. 17610:298. 24X Fiche: 50-263, 83/03/11, 8303170500.

--8303170521 Forwards addl info in response to NUREG-0737, Item II.B.3, "Post-Accident Sampling" & Item II.F.1, "Containment Hydrogen Monitors." Relief also required for Item II.B.2. MUSOLF, D. Northern States Power Co. 82/11/16. Office of Nuclear Reactor Regulation, Director. 1p. 17610:300. 24X Fiche: 50-263, 83/03/11, 8303170500.

--8303170527 Requests addl schedule relief for NUREG-0737, Item II.B.3, "Post-Accident Sampling," until 821231. MUSOLF, D. Northern States Power Co. 82/11/08. Office of Nuclear Reactor Regulation, Director. 2pp. 17610:301. 24X Fiche: 50-263, 83/03/11, 8303170500.

--8303170536 Requests addl schedule relief for liquid sampling portion of post-accident sampling sys described in NUREG-0737, Items II.B.2 & II.B.3. MUSOLF, D. Northern States Power Co. 82/07/21. Office of Nuclear Reactor Regulation, Director. 2pp. 17610:303. 24X Fiche: 50-263, 83/03/11, 8303170500.

8303180014 Forwards response to six concerns re NUREG-0737, Item II.D.1, "Relief & Safety Valve Test Requirements," in response to NRC 830104 ltr. MUSOLF, D. Northern States Power Co. 83/03/11. Office of Nuclear Reactor Regulation, Director. 20pp. 17618:136. 24X Fiche: 50-263, 83/03/11, 8303180014.

8303180531 Provides addl commitment re equipment Items 16, 17 & 19 per 830303 ltr re environ qualification of electrical equipment. Procedures revised to include guidance for operators during high energy line breaks. Revs will be completed by 830430. MUSOLF, D. Northern States Power Co. 83/03/11. Office of Nuclear Reactor Regulation, Director. 1p. 17621:338. 24X Fiche: 50-263, 83/03/11, 8303180531.

8303290100 Forwards order confirming commitment to implement post-TMI-related items set forth in NUREG-0737 for which NRC requested completion on or after 810701. Review may identify alterations to util implementation schedule. VASSALLO, D.B. Operating Reactors Branch 2. 83/03/14. MUSOLF, D.M. Northern States Power Co. 3pp. 17729:212. 24X Fiche: 50-263, 83/03/14, 8303290100.

--8303230159 Order confirming licensee commitment to implement post-TMI-related items set forth in NUREG-0737. Hearing may be requested within 20 days of publication. PURPLE, R.A. Division of Licensing. 83/03/14. Northern States Power Co. 10pp. 17686:193. 24X Fiche: 50-263, 83/03/14, 8303290100.

--8303290114 Order confirming licensee commitment to implement post-TMI-related items set forth in NUREG-0737. Hearing may be requested within 20 days of publication of order. PURPLE, R.A. Division of Licensing. 83/03/14. Northern States Power Co. 10pp. 17729:215. 24X Fiche: 50-263, 83/03/14, 8303290100.

8303280174 Forwards portions of IE Insp Repts 50-263/81-16 & 81-21 & safety evaluation of NUREG-0737, Item I.A.2.1.4, "Upgrading of Reactor Operator & Senior Reactor Operator Training," & Item II.B.4, "Training to Mitigate Core Damage." NORELIUS, C.E. Division of Project & Resident Programs. 83/03/24. EISENHUT, D.G. Division of Licensing. 6pp. 17709:288. 24X Fiche: 50-263, 83/03/24, 8303280174.

8303280218 Forwards safety evaluation of NUREG-0737, Item II.B.2.2, "Design Review of Plant Shielding-Access to Vital Areas," per request. Portions of IE Insp Rept 50-263/83-04 documenting review also encl. NORELIUS, C.E. Division of Project & Resident Programs. 83/03/24. EISENHUT, D.G. Division of Licensing. 6pp. 17708:155. 24X Fiche: 50-263, 83/03/24, 8303280218.

G. Inspection reports, IE Bulletins & correspondence

8303030456 Forwards IE Insp Rept 50-263/83-04 on 830124-28. No noncompliance noted. PAPERIELLO, C.J. Division of Emergency Preparedness & Operational Support. 83/02/15. LARSON, C.E. Northern States Power Co. 2pp. 17409:246. 24X Fiche: 50-263, 83/02/15, 8303030456.

--8303030457 IE Insp Rept 50-263/83-04 on 830124-28. No noncompliance noted. Major areas inspected: radiation protection program, audits, training, radiation protection procedures, status of TMI action items & previous findings. GRANT, W.B., GREGER, L.R. Region 3, Office of Director. 83/02/15. 8pp. 17409:248. 24X Fiche: 50-263, 83/02/15, 8303030456.

8303100068 Responds to FOIA request for NUREG-0313, results of stress ratio index tests on welds & info re intergranular stress corrosion cracking & performance of weld overlay patches. Forwards App A documents. App B documents available in PDR. FELTON, J.M. Division of Rules and Records. 83/02/15. VAN ALLEN, S.E. Northern Sun Alliance. 4pp. 17494:148. 24X Fiche: 50-000, 83/02/15, 8303100068.

--8303100093 Agenda for 821014 meeting w/util to review insp program & discuss 22-inch recirculation ring header end cap indications & 12-inch recirculation riser indications. * NRC - No Detailed Affiliation Given. 82/10/14. NRC - No Detailed Affiliation Given. 36pp. 17494:290. 24X Fiche: 50-000, 83/02/15, 8303100068.

--8303100102 Discusses degradation & cracking in thick-wall large diameter stainless steel piping at BWR plants per IE Bulletin 82-03 & NRR generic responsibilities Guidelines for review of pipe crack problem listed.
DIRCKS, W. J. Office of the Executive Director for Operations. 82/12/08. Region 1, Office of Director. 4pp. 17494:326. 24X
Fiche: 50-000, 83/02/15, 8303100068.

8303080023 Forwards IE Insp Rept 50-263/82-15 on 821031-830101 & notice of violation.
STREETER, J. F. Division of Project & Resident Programs. 83/02/18.
LARSON, C. E. Northern States Power Co. 2pp. 17455:342. 24X
Fiche: 50-263, 83/02/18, 8303080023.

--8303080032 Notice of violation from insp on 821031-830101.
STREETER, J. F. Division of Project & Resident Programs. 83/02/18.
1p. 17455:344. 24X Fiche: 50-263, 83/02/18, 8303080023.

--8303080042 IE Insp Rept 50-263/82-15 on 821031-83010. Noncompliance noted: failure to establish adequate provisions assuring affected equipment returned to acceptable status upon completion of work on containment spray relays.
BROWN, C. H., WALKER, R. D. Division of Project & Resident Programs. 83/02/18. 6pp. 17455:345. 24X Fiche: 50-263, 83/02/18, 8303080023.

8303010202 Forwards "Inservice Insp Exam Summary 820830-1201." Rept identifies components examined, exam methods used, exam number & summarizes results. Several intergranular stress corrosion cracks in weld heat revealed.
MUSOLF, D. Northern States Power Co. 83/02/23. Office of Nuclear Reactor Regulation, Director. 1p. 17332:208. 24X
Fiche: 50-263, 83/02/23, 8303010202.

--8303010211 "Inservice Insp Exam Summary, 820830-1201."
DAHLMAN, L. C., KRUMPOS, P. J. Northern States Power Co. 83/02/10.
137pp. 17332:209. 24X Fiche: 50-263, 83/02/23, 8303010202.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc.
111pp. 1/521.001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303170490 Forwards IE Insp Rept 50-263/83-02 on 830202-29. No noncompliance noted.
STREETER, J. F. Division of Project & Resident Programs. 83/02/25.
GILBERTS, D. E. Northern States Power Co. 2pp. 17610:305. 24X
Fiche: 50-263, 83/02/25, 8303170490.

--8303170495 IE Insp Rept 50-263/83-02 on 830202-29. No noncompliance noted. Major areas inspected: surveillance, LERs, evaluation of potentially generic issues, onsite review committee & operational safety.
BROWN, C. H. Region 3, Office of Director. WALKER, R. D. Division of Project & Resident Programs. 83/02/23. 5pp. 17610:307. 24X
Fiche: 50-263, 83/02/25, 8303170490.

8303030448 Clarifies NRC position re procedures for admitting NRC personnel to facilities. Lists of NRC inspectors & personnel likely to visit facility two or more times per yr & at anytime encl. Lists will be updated every 6 months.
KEPPLER, J. G. Region 3, Office of Director. 83/02/28. LARSON, C. E.
Northern States Power Co. 6pp. 17410:055. 24X
Fiche: 50-263, 83/02/28, 8303030448.

8303040399 Forwards response to IE Bulletin 79-01B, Suppl 3, "Qualification of TMI Action Plan Equipment," covering containment monitors.
MUSOLF, D. Northern States Power Co. 83/02/28. Office of Nuclear Reactor Regulation, Director. 21pp. 17420:073. 24X
Fiche: 50-263, 83/02/28, 8303040399.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc.
117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303290246 Forwards addl response to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Sys Components by Corbicula Sp (Asiatic Clam) & Mytilus (Mussel)." Program to periodically check basin & river initiated. No Asiatic clam found.
LARSON, C. E. Northern States Power Co. 83/03/21. KEPPLER, J. G.
Region 3, Office of Director. 1p. 17716:161. 24X
Fiche: 50-263, 83/03/21, 8303290246.

8303280218 Forwards safety evaluation of NUREG-0737, Item II B.2.2, "Design Review of Plant Shielding-Access to Vital Areas," per request. Portions of IE Insp Rept 50-263/83-04 documenting review also encl.
NORELIUS, C. E. Division of Project & Resident Programs. 83/03/24.
EISENHUT, D. G. Division of Licensing. 6pp. 17708:155. 24X
Fiche: 50-263, 83/03/24, 8303280218.

8303290484 Ack receipt of 830317 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-263/82-15.
STREETER, J. F. Region 3, Office of Director. 83/03/24. LARSON, C. E.
Northern States Power Co. 1p. 17723:359. 24X Fiche: 50-263, 83/03/24, 8303290484.

--8303290486 Responds to NRC 830218 ltr re violations noted in IE Insp Rept 50-263/82-15. Corrective actions: diesel generator shut down, respective auto start relay reset & control switch returned to auto.
LARSON, C. E. Northern States Power Co. 83/03/17. KEPPLER, J. G.
Region 3, Office of Director. 2pp. 17723:360. 24X
Fiche: 50-263, 83/03/24, 8303290484.

R. Periodic operating reports & related correspondence
---

8303080464 Forwards monthly operating repts for Dec 1982.
MUSOLF, D. Northern States Power Co. 83/01/10. Director's Office, Office of Inspection and Enforcement. 1p. 17453:196. 24X
Fiche: 50-263, 83/01/10, 8303080464.

--8303080469 Monthly operating rept for Dec 1982.
MYRABO, A. L. Northern States Power Co. 83/01/05. 4pp. 17453:197.
24X Fiche: 50-263, 83/01/10, 8303080464.

8303150604 Forwards monthly operating rept for Jan 1983.
MUSOLF, D. Northern States Power Co. 83/02/09. Division of Data Automation & Management Information. 1p. 17569:029. 24X
Fiche: 50-263, 83/02/09, 8303150604.

--8303150607 Monthly operating rept for Jan 1983.
MYRABO, A. L. Northern States Power Co. 83/02/02. 4pp. 17569:030.
24X Fiche: 50-263, 83/02/09, 8303150604.

8303150295 Forwards "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1982."
MUSOLF, D. Northern States Power Co. 83/03/01. Region 3, Office of Director. 1p. 17567:018. 24X Fiche: 50-263, 83/03/01, 8303150295.

--8303150307 "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1982."
* Northern States Power Co. 83/03/01. 19pp. 17567:019. 24X
Fiche: 50-263, 83/03/01, 8303150295.

S. Reportable occurrences, LERs & related correspondence
---

8303240433 Forwards LER 83-005/03L-0.
MUSOLF, D. Northern States Power Co. 83/03/17. Region 3, Office of Director. 1p. 17678:357. 24X Fiche: 50-263, 83/03/17, 8303240433.

--8303240436 LER 83-005/03L-0 on 830216, RHR pump 14 made inoperable to investigate head capacity reduction. Caused by mophead in pump suction, probably entering RHR sys during maint or const projects. Mophead removed.
OVERLID, T. W. Northern States Power Co. 83/03/17. Region 3, Office of Director. 1p. 17678:358. 24X Fiche: 50-263, 83/03/17, 8303240433.

V. Operator Examinations
---

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303040478 Submits schedule for operator licensing exams in response to Generic Ltr 83-01. Plans based on current rate of turnover & anticipated exam needs.
MUSOLF, D. M. Northern States Power Co. 83/02/28. Office of Nuclear Reactor Regulation, Director. 2pp. 17373:361. 24X
Fiche: 50-000, 83/02/28, 8303040478.

DOCKET 50-265 QUAD-CITIES STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8303160593 Forwards "Quad Cities Nuclear Power Station Small-Scale Joint Emergency Exercise" & "Evaluation of Implementation of IA State & Local Radiological Emergency Response Plans," final rept for 820824 exercise.
KRIMM, R. W. Federal Emergency Management Agency. 83/02/16.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 7pp. 17587:085. 24X Fiche: 50-254, 83/02/16, 8303160593.

--8303160596 "Quad Cities Nuclear Power Station Small-Scale Joint Emergency Exercise," final rept for 820824 exercise.
* Federal Emergency Management Agency. 82/10/12. 63pp. 17587:092. 24X Fiche: 50-254, 83/02/16, 8303160593.

--8303160600 "Evaluation of Implementation of IA State & Local Radiological Emergency Response Plans," final rept for exercise conducted on 820824.
* Federal Emergency Management Agency. 83/03/04. 13pp. 17587:155. 24X Fiche: 50-254, 83/02/16, 8303160593.

8303010595 Ack receipt of 830124 ltr identifying 1983 dates for emergency preparedness exercises within State of IL. Dates determined to be within required exercise frequency.
HIND, J. A. Region 3, Office of Director. 83/02/24. JONES, E. E. Illinois, State of. 2pp. 17336:208. 24X Fiche: 50-000, 83/02/24, 8303010595.

--8303010618 Submits 1983 dates scheduled for emergency preparedness exercises for facilities within State of IL.
JONES, C. E. Illinois, State of. 83/01/24. KEPPLER, J. Region 3, Office of Director. 2pp. 17336:210. 24X Fiche: 50-000, 83/02/24, 8303010595.

8303100075 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17493:098. 24X Fiche: 50-254, 83/03/02, 8303100075.

--8303100083 Forwards public version of Rev 14 to Emergency Plan Implementing Procedure QEP 530-0, "Exercises & Drills" & Rev 5 to QFP 530-S1, "Monthly NARS (ESDA) Drill, Quad Cities Station."
* Commonwealth Edison Co. 83/02/07. DENTON, H. R. NRC - No Detailed Affiliation Given. 2pp. 17493:099. 24X Fiche: 50-254, 83/03/02, 8303100075.

--8303100090 Public version of Rev 14 to Emergency Plan Implementing Procedures QEP 530-0, "Exercises & Drills" & Rev 5 to QEP 530-S1, "Monthly NARS (ESDA) Drill, Quad Cities Station."
* Commonwealth Edison Co. 83/02/07. 2pp. 17493:101. 24X Fiche: 50-254, 83/03/02, 8303100075.

8303140573 Confirms 830318 meeting in Glen Ellyn, IL to discuss actions to resolve offsite emergency preparedness concerns & Byron preoperational test program. Meeting notice encl.
KEPPLER, J. G. Region 3, Office of Director. 83/03/08. REED, C. Commonwealth Edison Co. 3pp. 17534:001. 24X Fiche: 50-254, 83/03/08, 8303140573.

8303150601 Forwards IE Insp Repts 50-254/83-07 & 50-265/83-07 on 830225. No noncompliance noted.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 83/03/10. REED, C. Commonwealth Edison Co. 2pp. 17569:013. 24X Fiche: 50-254, 83/03/10, 8303150601.

--8303150606 IE Insp Repts 50-254/83-07 & 50-265/83-07 on 830225. No noncompliance noted. Major areas inspected: actions on previously identified items during emergency preparedness implementation appraisal.
PHILLIPS, M. P. Region 3, Office of Director. 83/03/09. 5pp. 17569:015. 24X Fiche: 50-254, 83/03/10, 8303150601.

8303240074 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/21. Document Management Branch. 1p. 17694:128. 24X Fiche: 50-254, 83/03/21, 8303240074.

--8303240078 Forwards public version of revised emergency plan implementing procedures, including Procedures QEP 310-0 re notification of responsible authorities & QEP 310-T3 re prioritized notification listing.
JESSEN, D. Commonwealth Edison Co. 83/03/04. NRC - No Detailed Affiliation Given. 2pp. 17694:129. 24X Fiche: 50-254, 83/03/21, 8303240074.

--8303240085 Public version of revised emergency plan implementing procedures, including Procedures QEP 310-0 re notification of responsible authorities & QEP 310-T3 re prioritized notification listing.
* Commonwealth Edison Co. 83/03/07. 41pp. 17694:131. 24X Fiche: 50-254, 83/03/21, 8303240074.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director. 83/03/22. Commonwealth Edison Co. 2pp. 17690:316. 24X Fiche: 50-000, 83/03/22, 8303240440.

8303280307 Forwards IE Safeguards Insp Repts 50-254/83-08 & 50-265/83-08 on 830228-0304. No noncompliance noted.
MILLER, J. R. Region 3, Office of Director. 83/03/23. REED, C. Commonwealth Edison Co. 2pp. 17706:162. 24X Fiche: 50-254, 83/03/23, 8303280307.

--8303280321 IE Safeguards Insp Repts 50-254/83-08 & 50-265/83-03 on 830228-0304. No noncompliance noted. Major areas inspected: security program audit, physical barriers, security sys power supply & lighting. Details withheld (ref 10CFR73.21).
KNICELEY, J. R. Region 3, Office of Director. 83/03/23. 1p. 17706:164. 24X Fiche: 50-254, 83/03/23, 8303280307.

8303300008 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/23. Document Management Branch. 1p. 17751:265. 24X Fiche: 50-254, 83/03/23, 8303300008.

--8303300011 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure QEP 700-T3, "Supplemental Phone Listing."
* Commonwealth Edison Co. 83/02/24. NRC - No Detailed Affiliation Given. 1p. 17751:266. 24X Fiche: 50-254, 83/03/23, 8303300008.

--8303300017 Public version of Rev 3 to Emergency Plan Implementing Procedure QEP 700-T3, "Supplemental Phone Listing." Revised table of contents encl.
* Commonwealth Edison Co. 83/02/24. 2pp. 17751:267. 24X Fiche: 50-254, 83/03/23, 8303300008.

8303310124 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/25. Document Management Branch. 1p. 17775:184. 24X Fiche: 50-000, 83/03/25, 8303310124.

--8303310130 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure EQ-1, "Coordination of Environs Group Activities by Environs Director."
* Commonwealth Edison Co. 83/03/17. Director's Office, Office of Inspection and Enforcement. 1p. 17775:185. 24X Fiche: 50-000, 83/03/25, 8303310124.

--8303310146 Public version of Rev 3 to Emergency Plan Implementing Procedure EQ-1, "Coordination of Environs Group Activities by Environs Director."
PAJOWSKI, J. E. Commonwealth Edison Co. 83/03/08. 87pp. 17775:186. 24X Fiche: 50-000, 83/03/25, 8303310124.

8303300532 Releases public version of request for return of listed controlled copies of emergency plan.
FELTON, J. M. Division of Rules and Records. 83/03/28. Document Management Branch. 1p. 17763:178. 24X Fiche: 50-000, 83/03/28, 8303300532.

--8303300561 Submits public version of request for return of listed controlled copies of emergency plan.
FLESSNER, R. A. Commonwealth Edison Co. 83/03/15. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17763:179. 24X Fiche: 50-000, 83/03/28, 8303300532.

8303300738 Releases public version of rev to emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/28. Document Management Branch. 1p. 17765:200. 24X Fiche: 50-254, 83/03/28, 8303300738.

--8303300744 Forwards public version of Rev 6 to Emergency Plan Implementing Procedure QEP 700-0, "Telephone Directories" & Rev 3 to QEP 700-T3, "Supplemental Phone List." Receipt form encl.
GERNER, L., KOVACK, T. J. Commonwealth Edison Co. 83/02/24. NRC - No Detailed Affiliation Given. 2pp. 17765:201. 24X Fiche: 50-254, 83/03/28, 8303300738.

--8303300756 Public version of Rev 6 to Emergency Plan Implementing Procedure GEP 700-0, "Telephone Directories" & Rev 3 to GEP 700-T3, "Supplemental Phone List."
* Commonwealth Edison Co. 83/02/24. 2pp. 17765:203. 24X Fiche: 50-254, 83/03/28, 8303300738.

H. General correspondence

8303030528 Informs that DL Farrar has replaced LO DelGeorge as Director of Nuclear Licensing for util. Rev of current NRC distribution list requested.
FARRAR, D. L. Commonwealth Edison Co. 83/02/02. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17409:048. 24X Fiche: 50-000, 83/02/02, 8303030528.

I. Financial information

8303070135 Forwards Annual Financial Rept 1982.
BRESEMANN, R. W. Commonwealth Edison Co. 83/02/28. Division of Licensing. 1p. 17433:001. 24X Fiche: 50-000, 83/02/28, 8303070135.

--8303070151 Annual Financial Rept 1982.
O'CONNOR, J. J. Commonwealth Edison Co. 83/02/03. 13pp. 17433:002. 24X Fiche: 50-000, 83/02/28, 8303070135.

P. Operating license stage documents & correspondence

8303100068 Responds to FOIA request for NUREG-0313, results of stress ratio index tests on welds & info re intergranular stress corrosion cracking & performance of weld overlay patches. Forwards App A documents App B documents available in PDR.
FELTON, J. M. Division of Rules and Records. 83/02/15. VAN ALLEN, S. E. Northern Sun Alliance. 4pp. 17494:148. 24X Fiche: 50-000, 83/02/15, 8303100068.

--8303100082 "Evaluations of Reactor Water Cleanup Line Repairs, Quad Cities Nuclear Power Station Unit 2."
RICCARDELLA, P., WENNER, T. J., SEELEY, G. T. NUTECH Engineers, Inc. COM-39-001. 82/01/29. 99pp. 17494:153. 24X Fiche: 50-000, 83/02/15, 8303100068.

--8303100087 "Evaluation of 4-Inch Weld Overlay Repair, Quad Cities Unit 2 Reactor Water Cleanup Suction Line."
NIU, L. C., EDWARDS, G. R., RICCARDELLA, P. NUTECH Engineers, Inc. COM-39-002. 82/02/05. 7pp. 17494:254. 24X Fiche: 50-000, 83/02/15, 8303100068.

--8303100109 "Administrative Procedure for Unit Two Reactor Water Cleanup Pipe Repair Upstream of MO-2-1201-2."
* Commonwealth Edison Co. 83/02/15. 16pp. 17494:360. 24X Fiche: 50-265, 83/02/15, 8303100068.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303180069 Forwards Amend 78 to License DPR-30, safety evaluation & notice of issuance & availability. Amend changes Tech Specs re reactor protection sys delay & response times.
BEVAN, R. B. Operating Reactors Branch 2. 83/02/17. DELGEORGE, L. Commonwealth Edison Co. 2pp. 17625:219. 24X Fiche: 50-265, 83/02/17, 8303180069.

--8303180073 Amend 78 to License DPR-30, changing Tech Specs re reactor protection sys delay & response times & average power range monitor gain adjustment.
VASSALLO, D. B. Operating Reactors Branch 2. 83/02/17. 8pp. 17625:221. 24X Fiche: 50-265, 83/02/17, 8303180069.

--8303180085 Safety evaluation supporting Amend 78 to License DPR-30.
* Office of Nuclear Reactor Regulation, Director. 83/02/17. 2pp. 17625:229. 24X Fiche: 50-265, 83/02/17, 8303180069.

--8303180093 Notice of issuance & availability of Amend 78 to License DPR-30.
VASSALLO, D. B. Operating Reactors Branch 2. 83/02/17. 2pp. 17625:231. 24X Fiche: 50-265, 83/02/17, 8303180069.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J. G. Region 3, Office of Director. 83/03/03. Commonwealth Edison Co. 2pp. 17492:014. 24X Fiche: 50-000, 83/03/03, 8303100364.

8303300648 Forwards Amend 79 to License DPR-30, safety evaluation & notice of issuance & availability. Amend revises Tech Specs to allow temporary increase in linear heat generation rate for certain barrier fuel test assemblies.
BEVAN, R. B. Operating Reactors Branch 2. 83/03/03. FARRAR, D. L. Commonwealth Edison Co. 2pp. 17770:241. 24X Fiche: 50-265, 83/03/03, 8303300648.

--8303300653 Amend 79 to License DPR-30, revising Tech Specs to allow temporary increase in linear heat generation rate from 13.4 to 14.7 Kw/ft for certain barrier fuel test assemblies present in core.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/03. 4pp. 17770:243. 24X Fiche: 50-265, 83/03/03, 8303300648.

--8303300658 Safety evaluation supporting Amend 79 to License DPR-30.
* Office of Nuclear Reactor Regulation, Director. 83/03/03. 6pp. 17770:247. 24X Fiche: 50-265, 83/03/03, 8303300648.

--8303300660 Notice of issuance & availability of Amend 79 to License DPR-30.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/03. 2pp. 17770:253. 24X Fiche: 50-265, 83/03/03, 8303300648.

8303110246 Forwards Rev 23 to CE-1-A, "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/04. HAASS, W. P. Quality Assurance Branch. 1p. 17515:357. 24X Fiche: 50-000, 83/03/04, 8303110246.

--8303110279 Rev 23 to "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments.
SHEWSKI, W. J. Commonwealth Edison Co. CE-1-A R23. 83/03/07. 5pp. 17515:358. 24X Fiche: 50-000, 83/03/04, 8303110246.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303300026 Forwards order confirming implementation of post-TMI items in NUREG-0737 based on commitments in response to Generic Ltrs 82-05 & 10.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/14. FARRAR, D. L. Commonwealth Edison Co. 3pp. 17751:172. 24X Fiche: 50-254, 83/03/14, 8303300026.

--8303300034 Order confirming licensee commitments on post-TMI related issues in NUREG-0737.
PURPLE, R. A. Division of Licensing. 83/03/14. Commonwealth Edison Co. 10pp. 17751:175. 24X Fiche: 50-254, 83/03/14, 8303300026.

8303170064 Forwards request for addl info re IE Bulletin 80-01 & NUREG-0737, Item II.K.3.28, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves." Response due by 830512.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/03/16. FARRAR, D. L. Commonwealth Edison Co. 4pp. 17609:098. 24X Fiche: 50-000, 83/03/16, 8303170064.

8303290663 Forwards safety evaluation re NUREG-0737, Item II.K.3.13, "Separate HPCI & RCIC Initiation Levels," & mod of RCIC initiation logic causing RCIC restart on low reactor vessel water level. Initiation level separation issue complete.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/16. FARRAR, D. L. Commonwealth Edison Co. 3pp. 17742:027. 24X Fiche: 50-254, 83/03/16, 8303290663.

8303280270 Requests that petition for hearing on environ qualification of safety-related electrical equipment be withdrawn based on listed interpretations. Significant improvements in final rule 10CFR50.49 obviate hearings.
STEPTOE, P. P. Isham, Lincoln & Beale. 83/03/24. EISENHUT, D. G. Division of Licensing. 2pp. 17706:289. 24X Fiche: 50-000, 83/03/24, 8303280270.

8303280272 Forwards safety evaluation of NUREG-0737, Item II.B.2.2, "Design Review of Plant Shielding-Access to Vital Areas." Licensee has completed mods.
NORELIUS, C.E. Division of Project & Resident Programs 83/03/24
EISENHUT, D.G. Division of Licensing 5pp. 17706:206 24X
Fiche: 50-254, 83/03/24, 8303280272.

Q. Inspection reports, IE Bulletins & correspondence

8303030504 Summarizes list of software changes that will be made to improve multiplet analysis capability of automated analytical instrument sys in response to insp rept open items. Schedule of changes will be submitted by 830615.
RYBAK, B. Commonwealth Edison Co. 83/02/14 KEPPLER, J.G. Region 3, Office of Director 2pp. 17409:062 24X Fiche: 50-254, 83/02/14, 8303030504.

8303240368 Forwards IE Insp Repts 50-237/82-20, 50-254/82-16, 50-249/82-21 & 50-265/82-18 on 820816-1103.
KEPPLER, J.G. Region 3, Office of Director 82/02/16 O'CONNOR, J.J. Commonwealth Edison Co. 2pp. 17682:021 24X Fiche: 50-000, 83/02/16, 8303240368.

--8303240372 IE Insp Repts 50-237/82-20, 50-249/82-21, 50-254/82-16 & 50-265/82-18 on 820816-1103 Noncompliance noted: failure to control distribution of supplemental safety classification lists & to control parts not conforming to requirements.
CHRISSOTIMOS, N., WALKER, R.D. Region 3, Office of Director 83/02/15 8pp. 17682:023 24X Fiche: 50-000, 83/02/16, 8303240368.

8303140259 Forwards IE Insp Repts 50-254/83-02 & 50-265/83-02 on 830201-04. No noncompliance noted.
PAPERIELLO, C.J. Division of Emergency Preparedness & Operational Support 83/02/24 REED, C. Commonwealth Edison Co. 2pp. 17534:246 24X Fiche: 50-254, 83/02/24, 8303140259.

--8303140265 IE Insp Repts 50-254/83-02 & 50-265/83-02 on 830201-04. No noncompliance noted. Major areas inspected: effluent releases, records & repts & control instrumentation, solid radwaste & transportation.
MILLER, D.E., PECK, C.C., GREGER, L.R. Region 3, Office of Director 83/02/22 12pp. 17534:248 24X Fiche: 50-254, 83/02/24, 8303140259.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11pp. 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303170532 Forwards IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al. on 830126. No noncompliance noted.
DAVIS, A.B. Region 3, Office of Director 83/02/25 REED, C. Commonwealth Edison Co. 2pp. 17610:143 24X Fiche: 50-000, 83/02/25, 8303170532.

--8303170557 IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al. on 830126. No noncompliance noted. Major areas discussed: proposed guidelines util personnel should use for providing info to Region III inspectors.
GULDEMOND, W.G. Division of Project & Resident Programs 83/02/15 4pp. 17610:145 24X Fiche: 50-000, 83/02/25, 8303170532.

8303030441 Clarifies NRC position re procedures for admitting NRC personnel to facilities. Lists of NRC inspectors & personnel likely to visit facility two or more times per yr & at anytime encl. Lists will be updated every 6 months.
KEPPLER, J.G. Region 3, Office of Director 83/02/28 REED, C. Commonwealth Edison Co. 6pp. 17410:080 24X Fiche: 50-254, 83/02/28, 8303030441.

8303170546 Forwards IE Insp Repts 50-254/83-01 & 50-265/83-01 on 830107-0218. No noncompliance noted.
STREETER, J.F. Division of Project & Resident Programs 83/03/01
REED, C. Commonwealth Edison Co. 2pp. 17610:150 24X Fiche: 50-254, 83/03/01, 8303170546.

--8303170551 IE Insp Repts 50-254/83-01 & 50-265/83-01 on 830107-0218. No noncompliance noted. Major areas inspected: operational safety, maint, surveillance, audit program, reactor scram, licensee monthly repts, LERs & IE info notices.
CHRISSOTIMOS, N. Region 3, Office of Director WALKER, R.D. Division of Project & Resident Programs 83/02/28 10pp. 17610:152 24X Fiche: 50-254, 83/03/01, 8303170546.

8303070036 Forwards responses to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Bunker-Ramo electrical penetrations installed in LaSalle Unit 2, Byron Unit 2 & Braidwood Unit 2.
SWARTZ, E.D. Commonwealth Edison Co. 83/03/03 KEPPLER, J.G. Region 3, Office of Director 13pp. 17435:290 24X Fiche: 50-000, 83/03/03, 8303070036.

8303090102 Ack receipt of 830214 ltr informing NRC of improvements in automated analytical instrumentation sys discussed in IE Insp Rpts 50-254/82-13 & 50-265/82-15.
PAPERIELLO, C.J. Division of Emergency Preparedness & Operational Support 83/03/04 RYBAK, B. Commonwealth Edison Co. 1p. 17469:350 24X Fiche: 50-254, 83/03/04, 8303090102.

--8303090107 Responds to NRC 821001 ltr re automated analytical instrumentation sys discussed in IE Insp Repts 50-254/82-13 & 50-265/82-15. Peak search algorithm used in measuring radioactivity will include resolution of multiplet peaks.
RYBAK, B. Commonwealth Edison Co. 83/02/14 KEPPLER, J.G. Region 3, Office of Director 2pp. 17469:351 24X Fiche: 50-254, 83/03/04, 8303090102.

8303150343 Responds to NRC 830216 ltr re violations noted in IE Insp Repts 50-237/82-20, 50-249/82-21, 50-254/82-16 & 50-265/82-18. Extension of 30 days requested for preparation of detailed written statement re alleged violations per 830308 telcon.
REED, C. Commonwealth Edison Co. 83/03/08 KEPPLER, J.G. Region 3, Office of Director 1p. 17566:254 24X Fiche: 50-000, 83/03/08, 8303150343.

8303240602 Forwards IE Insp Repts 50-254/82-24 & 50-265/82-28 on 821212-17 & 830110. No noncompliance noted.
SPESSARD, R.L. Region 3, Office of Director 83/03/09 REED, C. Commonwealth Edison Co. 2pp. 17683:052 24X Fiche: 50-254, 83/03/09, 8303240602.

--8303240607 IE Insp Repts 50-254/82-24 & 50-265/82-28 on 821213-17 & 830110. No noncompliance noted. Major areas inspected: integrated pr.mary containment leak rate test.
REIMANN, F.W., REYES, L. Region 3, Office of Director 83/02/24 6pp. 17683:054 24X Fiche: 50-254, 83/03/09, 8303240602.

8303150601 Forwards IE Insp Rapts 50-254/83-07 & 50-265/83-07 on 830225. No noncompliance noted.
PAPERIELLO, C.J. Division of Emergency Preparedness & Operational Support 83/03/10 REED, C. Commonwealth Edison Co. 2pp. 17569:013 24X Fiche: 50-254, 83/03/10, 8303150601.

--8303150606 IE Insp Repts 50-254/83-07 & 50-265/83-07 on 830225. No noncompliance noted. Major areas inspected: actions on previously identified items during emergency preparedness implementation appraisal.
PHILLIPS, M.P., GLOERSEN, W.B. Region 3, Office of Director AXELSON, W.L. Division of Emergency Preparedness & Operational Support 83/03/09 5pp. 17569:015 24X Fiche: 50-254, 83/03/10, 8303150601.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8303170064 Forwards request for addl info re IE Bulletin 80-01 & NUREG-0737, Item II.K.3.28, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves." Response due by 830512.
CRUTCHFIELD, D. Operating Reactors Branch 5 83/03/16 FARRAR, D.L. Commonwealth Edison Co. 4pp. 17609:098 24X Fiche: 50-000, 83/03/16, 8303170064.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12?pp. 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

8303280307 Forwards IE Safeguards Insp Repts 50-254/83-08 & 50-265/83-08 on 830228-0304. No noncompliance noted.
MILLER, J.R. Region 3, Office of Director 83/03/23 REED, C. Commonwealth Edison Co. 2pp. 17706:164 24X Fiche: 50-254, 83/03/23, 8303280307.

--8303280321 IE Safeguards Insp Repts 50-254/83-08 & 50-265/83-03 on 830228-0304. No noncompliance noted. Major areas inspected: security program audit, physical barriers, security sys power supply & lighting. Details withheld (ref 10CFR73.21).
KNICELEY, J.R., BELANGER, J.L., CREED, J.R. Region 3, Office of Director 83/03/23 1p. 17706:164 24X Fiche: 50-254, 83/03/23, 8303280307.

8302280215 Responds to 821028 ltr requesting reduction in IE Bulletin 80-13 frequency for insp of core spray spargers & elimination of requirement for video resolution to be checked w/one mil wire. Evaluation underway.
NORELIUS, C. E. Division of Project & Resident Programs 83/03/24.
REED, C. Commonwealth Edison Co. 1p. 17708:215. 24X
Fiche: 50-254, 83/03/24, 8302280215.

8303310211 Forwards addl info in response to IE Bulletin 81-03 re methods to control Corbicula. "Environ Studies of Braidwood Cooling Pond, 1982," encl.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/28. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 17pp. 17755:095. 24X
Fiche: 50-000, 83/03/28, 8303310211.

R Periodic operating reports & related correspondence

8303170424 Correction to total man-rem exposure rept for 1981. Correct exposure should read 1.470 man-rem not 1470.00 man-rem.
WAGNER, G. P. Commonwealth Edison Co. 83/02/24. KEPPLER, J. G. Region 3, Office of Director. 1p. 17610:120. 24X Fiche: 50-254, 83/02/24, 8303170424.

8303150439 Forwards listing of changes, tests & experiments completed during Feb 1983 Safety evaluation summary reported per 10CFR50.59.
KALIVIANAKIS, N. Commonwealth Edison Co. 83/03/02. CASE, E. G. Office of Nuclear Reactor Regulation, Director. 6pp. 17562:261. 24X Fiche: 50-254, 83/03/02, 8303150439.

8303160389 Forwards monthly operating repts for Feb 1983.
KALIVIANAKIS, N. Commonwealth Edison Co. 83/03/02. Director's Office, Office of Inspection and Enforcement. 1p. 17595:201. 24X Fiche: 50-254, 83/03/02, 8303160389.

--8303160391 Monthly operating repts for Feb 1983.
BUSS, R. D. Commonwealth Edison Co. 83/03/02. 21pp. 17595:202. 24X Fiche: 50-254, 83/03/02, 8303160389.

S Reportable occurrences, LERs & related correspondence

8303100068 Responds to FOIA request for NUREG-0313, results of stress ratio index tests on welds & info re intergranular stress corrosion cracking & performance of weld overlay patches. Forwards App A documents. App B documents available in PDR.
FELTON, J. M. Division of Rules and Records. 83/02/15. VAN ALLEN, S. E. Northern Sun Alliance. 4pp. 17494:148. 24X
Fiche: 50-000, 83/02/15, 8303100068.

--8202100501 Summary of 820123 conference call w/util re reactor water cleanup sys pipe cracks.
BEVAN, R. Operating Reactors Branch 2. 82/01/26. NOVAK, T. M. Assistant Director for Operating Reactors. 3pp. 17494:152. 24X
Fiche: 50-000, 83/02/15, 8303100068.

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303040631 Forwards listing of projected operator licensing exam dates including type of exam & probable number of candidates, in response to 830111 Generic Ltr 83-01.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/01. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 17367:209. 24X
Fiche: 50-000, 83/03/01, 8303040631.

8303240355 Requests approval to delay implementation of TMI Item I.A.1.3.2, "Shift Manning," until 830731 due to lack of personnel. At present time, util has three senior reactor operator-licensed SCRE.
RYBAK, B. Commonwealth Edison Co. 83/03/21. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17682:001. 24X
Fiche: 50-254, 83/03/21, 8303240355.

DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8303140112 Requests that comments on 830114 draft SER re App R exemption requests be submitted as soon as possible to allow preparation for early meeting to review technical info.
CLARK, R. A. Operating Reactors Branch 3. 83/02/23. FAY, C. W. Wisconsin Electric Power Co. 2pp. 17548:303. 24X
Fiche: 50-266, 83/02/23, 8303140112.

8303040622 Forwards technical evaluations of NRC 830114 draft safety evaluation & BNL evaluation re util requests for exemption from 10CFR50, App R, Section III.G requirements. All requested exemptions should be granted.
FAY, C. W. Wisconsin Electric Power Co. 83/02/25. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 144pp. 17369:178. 24X Fiche: 50-266, 83/02/25, 8303040622.

8303140402 Forwards IE Mgt Meeting Repts 50-266/83-02 & 50-301/83-02 on 830110. No noncompliance noted.
LITTLE, W. S. Region 3, Office of Director. 83/02/28. BURSTEIN, S. Wisconsin Electric Power Co. 2pp. 17542:190. 24X
Fiche: 50-266, 83/02/28, 8303140402.

--8303140406 IE Mgt Meeting Repts 50-266/83-02 & 50-301/83-02 on 830110. No noncompliance noted. Major areas discussed previously identified unresolved issues including fire protection.
RAMSEY, C., ULIE, J., WILLIAMS, C. C. Region 3, Office of Director. 83/02/12. 3pp. 17542:192. 24X Fiche: 50-266, 83/02/28, 8303140402.

8303240242 Forwards IE Insp Repts 50-266/83-01 & 50-301/83-01 on 830131-0225 & notice of violation.
PAPERIELLO, C. J. Region 3, Office of Director. 83/03/08.
BURSTEIN, S. Wisconsin Electric Power Co. 2pp. 17682:139. 24X
Fiche: 50-266, 83/03/08, 8303240242.

--8303240248 Notice of violation from insp on 830131-0225.
PAPERIELLO, C. J. Region 3, Office of Director. 83/03/07. 1p. 17682:141. 24X Fiche: 50-266, 83/03/08, 8303240242.

--8303240259 IE Insp Repts 50-266/83-01 & 50-301/83-01 on 830131-0225. Noncompliance noted: inadequate emergency preparedness implementation procedures to assure notification of state & local govt agencies within 15 minutes.
PAGLIARO, J. A., SNELL, W. G., AXELSON, W. L. Region 3, Office of Director. 83/03/05. 16pp. 17682:142. 24X Fiche: 50-266, 83/03/08, 8303240242.

8303170445 Forwards IE Safeguards Insp Repts 50-266/83-05 & 50-301/83-05 on 830207-11 & notice of violation. Notice of violation & rept details withheld (ref 10CFR73.21).
HIND, J. A. Region 3, Office of Director. 83/03/14. BURSTEIN, S. Wisconsin Electric Power Co. 2pp. 17609:204. 24X
Fiche: 50-266, 83/03/14, 8303170445.

--8303170459 IE Safeguards Insp Repts 50-266/83-05 & 50-301/83-05 on 830207-11. Noncompliance noted: documentation not available for access control & test penetration not detected by intrusion alarm sys. Details withheld (ref 10CFR73.21).
PIRTLE, G. L., CHRISTOFFER, G., CREED, J. R. Region 3, Office of Director. 83/03/10. 2pp. 17609:206. 24X Fiche: 50-266, 83/03/14, 8303170445.

8303240001 Notification of 830322 meeting w/util & BNL in Bethesda, MD to discuss technical info associated w/requested exemptions from 10CFR50, App R.
COLBURN, T. G. Operating Reactors Branch 3. 83/03/14. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17694:356. 24X
Fiche: 50-266, 83/03/14, 8303240001.

8303280006 Application for amends to Licenses DPR-24 & DPR-27 incorporating changes to Tech Specs which provide that independent audit of emergency preparedness program be carried out in accordance w/10CFR50.54(t).
FAY, C. W. Wisconsin Electric Power Co. 83/03/21. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17707:155. 24X
Fiche: 50-266, 83/03/21, 8303280006.

--8303280007 Proposed Tech Specs incorporating changes re independent audit of emergency preparedness program.
* Wisconsin Electric Power Co. 83/03/21. 2pp. 17707:157. 24X
Fiche: 50-266, 83/03/21, 8303280006.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director. 83/03/22. Commonwealth Edison Co. 2pp. 17690:316. 24X Fiche: 50-000, 83/03/22, 8303240440.

Q Adjudicatory correspondence

8303230257 Brief supporting WI Environ Decade 830211 exceptions to ASLB initial decision. ASLB refused to make prerequisite findings on degree of assurance necessary to protect public safety. Affidavit of Mailing encl.
ANDERSON, P. Wisconsin's Environmental Decade. 83/03/16. Commissioners. 12pp. 17661:170. 24X Fiche: 50-266, 83/03/16, 8303230257.

8303240383 Decision ALAB-719, affirming ASLB 821210 Special Prehearing Conference Order LBP-82-108 dismissing WI Environ Decade petition to intervene. Sanction of dismissal commensurate w/Decade failure to fulfill hearing obligation.
SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 83/03/22 19pp. 17679:090 24X Fiche: 50-266, 83/03/22, 8303240383.

8303240400 Order requesting util provide info on differences between old & new steam generators since tubes of new steam generators will be hydraulically expanded & generators will have ferritic stainless steel tube support plates.
SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 83/03/22
Wisconsin Electric Power Co 6pp. 17679:056 24X
Fiche: 50-266, 83/03/22, 8303240400.

J. Insurance & indemnity information

8303310035 Forwards Endorsement 70 to NELIA Policy NF-17R.
DUNDAS, W. J. Wisconsin Electric Power Co 83/03/28 NRC - No Detailed Affiliation Given. 2pp. 17763:050 24X
Fiche: 50-266, 83/03/28, 8303310035.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp. 17492:033 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303090260 Ack misinterpretation of util requests for relief from requirements re inservice testing of safety class components. Relief extended to Unit 2. Requested relief from frequency of visual exams denied. Corrected Tech Specs encl.
CLARK, R. A. Operating Reactors Branch 3 83/02/17 FAY, C. W. Wisconsin Electric Power Co 3pp. 17485:182 24X
Fiche: 50-266, 83/02/17, 8303090260.

--8303090268 Corrected Table 1 re Class 1 components, to Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively.
* Operating Reactors Branch 3 83/02/17 3pp. 17485:185 24X
Fiche: 50-266, 83/02/17, 8303090260.

8303010652 Summarizes 830127 meeting w/NRC at site re ALARA & radiation training program during steam generator replacement. Radiation protection program to be implemented during replacement presented.
FAY, C. W. Wisconsin Electric Power Co 83/02/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 24pp. 17336:144 24X Fiche: 50-266, 83/02/22, 8303010652.

8303010697 Forwards info identifying proprietary portions of Franklin Research 821222 safety & technical evaluation repts on environ qualification of safety-related electrical equipment per request. Proprietary portions deleted.
FAY, C. W. Wisconsin Electric Power Co 83/02/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director CLARK, R. A. Operating Reactors Branch 3 47pp. 17341:165 24X
Fiche: 50-266, 83/02/22, 8303010697.

8303160162 Forwards addl info re NUREG-0737, Item II.F.1.4, "Containment Pressure Monitor," Item II.F.1.5, "Containment Water Level Monitor" & Item II.F.1.6, "Containment Hydrogen Monitor," in response to NRC 830202 ltr.
FAY, C. W. Wisconsin Electric Power Co 83/02/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director CLARK, R. A. Operating Reactors Branch 3 19pp. 17597:001 24X
Fiche: 50-266, 83/02/28, 8303160162.

8303080430 Forwards Amend 1 to "Steam Generator Repair Rept."
FAY, C. W. Wisconsin Electric Power Co 83/03/01 CLARK, R. A. Operating Reactors Branch 3 1p. 17454:067 24X
Fiche: 50-266, 83/03/01, 8303080430.

--8303080435 Amend 1 to "Steam Generator Repair Rept."
* Wisconsin Electric Power Co 83/03/01 89pp. 17454:068 24X
Fiche: 50-266, 83/03/01, 8303080430.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303090130 Forwards NFS 770506 ltr confirming title to spent fuel assemblies stored at West Valley facility in response to 830302 request.
FAY, C. W. Wisconsin Electric Power Co 83/03/03 DENTON, H. R. Office of Nuclear Reactor Regulation, Director CLARK, R. A. Operating Reactors Branch 3 5pp. 17470:301 24X
Fiche: 50-266, 83/03/03, 8303090130.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J. G. Region 3, Office of Director 83/03/03
Commonwealth Edison Co. 2pp. 17492:014 24X Fiche: 50-000, 83/03/03, 8303100364.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp. 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303150333 Mod to application for amend to Licenses DPR-24 & DPR-27, changing Tech Spec Change Request 69 to revise Section 15.3.1.C & Table 15.4.1-2 re max coolant activity & min frequencies for equipment & sampling tests, respectively.
FAY, C. W. Wisconsin Electric Power Co 83/03/09 DENTON, H. R. Office of Nuclear Reactor Regulation, Director CLARK, R. A. Operating Reactors Branch 3 1p. 17563:026 24X
Fiche: 50-266, 83/03/09, 8303150333.

--8303150338 Proposed revised Tech Spec Section 15.3.1.C & Table 15.4.1-2 re max coolant activity & min frequencies for equipment & sampling tests, respectively.
* Wisconsin Electric Power Co 83/03/09 7pp. 17563:027 24X
Fiche: 50-266, 83/03/09, 8303150333.

8303240350 Forwards Amends 69 & 74 to Licenses DPR-24 & DPR-27, respectively, & notice of issuance & availability. Amends delete ETS nonradiological water quality-related requirements.
CLARK, R. A. Operating Reactors Branch 3 83/03/11 FAY, C. W. Wisconsin Electric Power Co 5pp. 17694:038 24X
Fiche: 50-266, 83/03/11, 8303240350.

--8303240353 Amends 69 & 74 to Licenses DPR-24 & DPR-27, respectively, deleting ETS nonradiological water quality-related requirements.
CLARK, R. A. Operating Reactors Branch 3 83/03/11 9pp. 17694:043 24X Fiche: 50-266, 83/03/11, 8303240350.

--8303240361 Notice of issuance & availability of Amends 69 & 74 to Licenses DPR-24 & DPR-27, respectively.
CLARK, R. A. Operating Reactors Branch 3 83/03/11 2pp. 17694:052 24X Fiche: 50-266, 83/03/11, 8303240350.

8303210111 Application for amend to Licenses DPR-24 & DPR-27, revising limitations & bases re use of Westinghouse 14x14 optimized fuel assembly design.
FAY, C. W. Wisconsin Electric Power Co 83/03/14 DENTON, H. R. Office of Nuclear Reactor Regulation, Director CLARK, R. A. Operating Reactors Branch 3 4pp. 17629:246 24X
Fiche: 50-266, 83/03/14, 8303210111.

--8303210116 Proposed Tech Spec Change 87, revising Westinghouse 14x14 optimized fuel assembly design.
* Wisconsin Electric Power Co 83/03/14 38pp. 17629:250 24X
Fiche: 50-266, 83/03/14, 8303210111.

8303220137 Supplis 791012 & 810601 responses to requests for addl info re offsite power distribution sys. NRC safety analysis concluded that ac auxiliary power sys adequate & physical & electrical separation of power sys acceptable.
FAY, C. W. Wisconsin Electric Power Co 83/03/14 DENTON, H. R. Office of Nuclear Reactor Regulation, Director CLARK, R. A. Operating Reactors Branch 3 2pp. 17657:245 24X
Fiche: 50-266, 83/03/14, 8303220137.

8303230071 Forwards order confirming commitments to implement post-TMI items scheduled for completion on or after 820701, based on responses to Generic Ltrs 82-05 & 82-10.
CLARK, R. A. Operating Reactors Branch 3 83/03/14 FAY, C. W. Wisconsin Electric Power Co. 3pp. 17688:062 24X
Fiche: 50-266, 83/03/14, 8303230071.

--8303230079 Order confirming licensee commitments to implement & maintain post-TMI issues.
PURPLE, R. A. Division of Licensing 83/03/14 Wisconsin Electric Power Co. 14pp. 17688:065 24X Fiche: 50-266, 83/03/14, 8303230071.

8303230231 Agrees that present licenses need not be modified to authorize possession & storage of spent fuel assemblies in spent fuel storage pools. Disposal of spent fuel should be included in arrangements w/DOE.
CLARK, R. A. Operating Reactors Branch 3. 83/03/14. FAY, C. W. Wisconsin Electric Power Co. 3pp. 17686:065. 24X
Fiche: 50-266, 83/03/14, 8303230231.

8303280006 Application for amends to Licenses DPR-24 & DPR-27 incorporating changes to Tech Specs which provide that independent audit of emergency preparedness program be carried out in accordance w/10CFR50.54(t).
FAY, C. W. Wisconsin Electric Power Co. 83/03/21. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17707:155. 24X
Fiche: 50-266, 83/03/21, 8303280006.

--8303280007 Proposed Tech Specs incorporating changes re independent audit of emergency preparedness program.
* Wisconsin Electric Power Co. 83/03/21. 2pp. 17707:157. 24X
Fiche: 50-266, 83/03/21, 8303280006.

8303280037 Forwards response to Generic Ltr 82-28, "Inadequate Core Cooling Instrumentation Sys," including response to NUREG-0737, Item II.F.2.
FAY, C. W. Wisconsin Electric Power Co. 83/03/21. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 22pp. 17707:315. 24X
Fiche: 50-266, 83/03/21, 8303280037.

8303300127 Application for amend to Licenses DPR-24 & DPR-27, modifying 820427 Tech Spec Change Request 77 re loss of voltage protective relays.
FAY, C. W. Wisconsin Electric Power Co. 83/03/23. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17731:207. 24X
Fiche: 50-266, 83/03/23, 8303300127.

--8303300132 Proposed Tech Specs, modifying 820427 Tech Spec Change Request 77 re loss of voltage protective relays.
* Wisconsin Electric Power Co. 83/03/23. 1p. 17731:209. 24X
Fiche: 50-266, 83/03/23, 8303300127.

8303290258 Discusses differing concepts of operability re auxiliary feedwater sys. Procedural & hardware mods to sys presently being studied in order to resolve differences in interpretation. Tech Specs should be modified as stated.
FAY, C. W. Wisconsin Electric Power Co. 83/03/24. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 3pp. 17716:001. 24X
Fiche: 50-266, 83/03/24, 8303290258.

8303300293 Withdraws request for hearing on NRC 801024 order imposing requirements re environ qualification of safety-related electrical equipment, based on interpretation of qualification criteria & replacement equipment.
FAY, C. W. Wisconsin Electric Power Co. 83/03/24. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. EISENHUT, D. G. Division of Licensing. 2pp. 17734:284. 24X Fiche: 50-266, 83/03/24, 8303300293.

8303310013 Informs that Amends 69 & 74 to Licenses DPR-24 & DPR-27, respectively, deleting nonradiological water quality surveillance requirements from Tech Specs exempt from fees. NRC will refund previously submitted fees.
MILLER, W. O. License Fee Management Branch. 83/03/28. FAY, C. W. Wisconsin Electric Power Co. 1p. 17777:354. 24X
Fiche: 50-266, 83/03/28, 8303310013.

## 9. Inspection reports, IE Bulletins & correspondence

8303030591 Forwards IE Insp Repts 50-266/83-03 & 50-301/83-03 on 830125-27. No noncompliance noted.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 83/02/16. BURSTEIN, S. Wisconsin Electric Power Co. 2pp. 17410:001. 24X Fiche: 50-266, 83/02/16, 8303030591.

--8303030598 IE Insp Repts 50-266/83-03 & 50-301/83-03 on 830125-27. No noncompliance noted. Major areas inspected: effluent control instrumentation, testing of air cleaning sys, licensee audits, radiation protection procedures, posting & exposure control.
LOVENDALE, P. C., GREGER, L. R. Region 3, Office of Director. 83/02/16. 8pp. 17410:003. 24X Fiche: 50-266, 83/02/16, 8303030591.

8303090260 Ack misinterpretation of util requests for relief from requirements re inservice testing of safety class components. Relief extends to Unit 2. Requested relief from frequency of visual exams denied. Corrected Tech Specs encl.
CLARK, R. A. Operating Reactors Branch 3. 83/02/17. FAY, C. W. Wisconsin Electric Power Co. 3pp. 17485:182. 24X
Fiche: 50-266, 83/02/17, 8303090260.

--8303090268 Corrected Table 1 re Class 1 components, to Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively.
* Operating Reactors Branch 3. 83/02/17. 3pp. 17485:185. 24X
Fiche: 50-266, 83/02/17, 8303090260.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303030443 Clarifies NRC position re procedures for admitting NRC personnel to facilities. Lists of NRC inspectors & personnel likely to visit facility two or more times per yr & at anytime encl. Lists will be updated every 6 months.
KEPPLER, J. G. Region 3, Office of Director. 83/02/28. BURSTEIN, S. Wisconsin Electric Power Co. 6pp. 17410:074. 24X
Fiche: 50-266, 83/02/28, 8303030443.

8303140402 Forwards IE Mgt Meeting Repts 50-266/83-02 & 50-301/83-02 on 830110. No noncompliance noted.
LITTLE, W. S. Region 3, Office of Director. 83/02/28. BURSTEIN, S. Wisconsin Electric Power Co. 2pp. 17542:190. 24X
Fiche: 50-266, 83/02/28, 8303140402.

--8303140406 IE Mgt Meeting Repts 50-266/83-02 & 50-301/83-02 on 830110. No noncompliance noted. Major areas discussed: previously identified unresolved issues including fire protection.
RAMSEY, C., ULIE, J., WILLIAMS, C. C. Region 3, Office of Director. 83/02/12. 3pp. 17542:192. 24X Fiche: 50-266, 83/02/28, 8303140402.

8303080271 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers to Open on Automatic Trip Signal." Plant Procedure ICP 2.3 changed to meet surveillance requirements & log entries verified.
FAY, C. W. Wisconsin Electric Power Co. 83/03/03. KEPPLER, J. G. Region 3, Office of Director. 2pp. 17449:352. 24X
Fiche: 50-266, 83/03/03, 8303080271.

8303170369 Forwards IE Insp Repts 50-266/82-24 & 50-301/82-22 on 821201-830131. No noncompliance noted.
STREETER, J. F. Division of Project & Resident Programs. 83/03/03. BURSTEIN, S. Wisconsin Electric Power Co. 2pp. 17609:319. 24X
Fiche: 50-266, 83/03/03, 8303170369.

--8303170408 IE Insp Repts 50-266/82-24 & 50-301/82-22 on 821201-830131. No noncompliance noted. Major areas inspected: maint, surveillance, LERs, IE bulletins, NFBD relay failures, plant trips, previous insp findings & operational safety.
HAQUE, R. L., FITZPATRICK, B. Region 3, Office of Director. JACKIW, I. N. Division of Project & Resident Programs. 83/03/03. 8pp. 17609:321. 24X Fiche: 50-266, 83/03/03, 8303170369.

8303240242 Forwards IE Insp Repts 50-266/83-01 & 50-301/83-01 on 830131-0225 & notice of violation.
PAPERIELLO, C. J. Region 3, Office of Director. 83/03/08. BURSTEIN, S. Wisconsin Electric Power Co. 2pp. 17682:139. 24X
Fiche: 50-266, 83/03/08, 8303240242.

--8303240248 Notice of violation from insp on 830131-0225.
PAPERIELLO, C. J. Region 3, Office of Director. 83/03/07. 1p. 17682:141. 24X Fiche: 50-266, 83/03/08, 8303240242.

--8303240259 IE Insp Repts 50-266/83-01 & 50-301/83-01 on 830131-0225. Noncompliance noted: inadequate emergency preparedness implementation procedures to assure notification of state & local govt agencies within 15 minutes.
PAGLIARO, J. A. Region 3, Office of Director. 83/03/05. 16pp. 17682:142. 24X Fiche: 50-266, 83/03/08, 8303240242.

--8303240259 IE Insp Repts 50-266/83-01 & 50-301/83-01 on 830131-0225. Noncompliance noted: inadequate emergency preparedness implementation procedures to assure notification of state & local govt agencies within 15 minutes.
PAGLIARO, J. A., SNELL, W. G., AXELSON, W. L. Region 3, Office of Director. 83/03/05. 16pp. 17682:142. 24X Fiche: 50-266, 83/03/08, 8303240242.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303170445 Forwards IE Safeguards Insp Repts 50-266/83-05 & 50-301/83-05 on 830207-11 & notice of violation. Notice of violation & rept details withheld (ref 10CFR73.21).
HIND, J. A. Region 3, Office of Director. 83/03/14. BURSTEIN, S. Wisconsin Electric Power Co. 2pp. 17609:204. 24X
Fiche: 50-266, 83/03/14, 8303170445.

--8303170459 IE Safeguards Insp Repts 50-266/83-05 & 50-301/83-05 on 830207-11 Noncompliance noted documentation not available for access control & test penetration not detected by intrusion alarm sys Details withheld (ref 10CFR73.21) PIRTLE, G L., CHRISTOFFER, G., CREED, J R Region 3, Office of Director 83/03/10 2pp 17609.206 24X Fiche 50-266, 83/03/14, 8303170445

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list / JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp 17774.352 24X Fiche 50-000, 83/03/21, 8212060367

R Periodic operating reports & related correspondence

8303040530 Forwards "Semiannual Monitoring Rept, Jul-Dec 1982." Rept contains info re plant releases, new fuel receipts, environ radiological monitoring & leak testing of sources. FAY, C W Wisconsin Electric Power Co 83/02/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17366.139 24X Fiche 50-266, 83/02/25, 8303040530

--8303040538 "Semiannual Monitoring Rept, Jul-Dec 1982." * Wisconsin Electric Power Co 83/02/25 15pp 17366.140 24X Fiche 50-266, 83/02/25, 8303040530

8303160569 Forwards monthly operating repts for Feb 1983. FAY, C W Wisconsin Electric Power Co 83/03/10 NRC - No Detailed Affiliation Given 1p 17587.004 24X Fiche 50-266, 83/03/10, 8303160569

--8303160577 Monthly operating repts for Feb 1983. FAY, C W Wisconsin Electric Power Co 83/03/07 7pp 17587.005 24X Fiche 50-266, 83/03/10, 8303160569

S Reportable occurrences, LERs & related correspondence

8303240086 Advises that measures taken to retrieve loose parts from steam generators & to assess & correct related tube damage in acceptable manner, per LERs 82-017/01T-0, 82-022/01T-0, 82-022/01T-1 & 82-017/01T-1 CLARK, R A Operating Reactors Branch 3 83/03/08 FAY, C W Wisconsin Electric Power Co. 2pp 17694.103 24X Fiche 50-266, 83/03/08, 8303240086

--8303240088 Safety evaluation supporting util measures to retrieve loose parts from steam generators & to correct any related tube damage * NRC - No Detailed Affiliation Given 83/03/08 8pp 17694.105 24X Fiche 50-266, 83/03/08, 8303240086

8303310152 Forwards licensee 830318 ltr to State of WI Dept of Natural Resources re 830207 violation of State of WI PDES Submittal confirms commitment to rept permit violations, per Amends 69 & 74 to Licenses DPR-24 & DPR-27, respectively. FAY, C W Wisconsin Electric Power Co 83/03/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17763.057 24X Fiche 50-266, 83/03/25, 8303310152

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 10pp 24X Fiche 50-000, 83/02/24, 8302250505

8303080515 Submits schedule for requested NRC site visits to conduct operator licensing exams through Oct 1985 per Generic Ltr 83-01. FAY, C W Wisconsin Electric Power Co 83/03/02 EISENHUT, D G Division of Licensing 1p 17452.280 24X Fiche 50-266, 83/03/02, 8303080515

DOCKET 50-267 FORT ST. VRAIN NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

8303150450 Forwards IE Safeguards Insp Rept 50-267/82-30 on 821213-16. No noncompliance noted. MADSEN, G L Region 4, Office of Director 83/02/23 LEE, O R Public Service Co. of Colorado 2pp 17561.056 24X Fiche 50-267, 83/02/23, 8303150450

--8303150455 IE Safeguards Insp Rept 50-267/82-30 on 821213-16 No noncompliance noted. Major areas inspected assessment aids, access control - personnel, packages, vehicles, alarm stations & communications. Details withheld (ref 10CFR2.790). CALDWELL, R A., KELLY, J A F Region 4, Office of Director 83/02/14 1p 17561.058 24X Fiche 50-267, 83/02/23, 8303150450

8303010411 Requests assistance in determining optimal locations for emergency notification sys & health physics network (HPN) phones in emergency response facilities, supplementing NUREG-0696 Replacement of HPN lines w/FTS lines considered. COLLINS, J T Region 4, Office of Director 83/02/24 LEE, O R Public Service Co. of Colorado 2pp 17346.232 24X Fiche 50-267, 83/02/24, 8303010411

8303100020 Releases public version of radiological emergency response plan implementing procedures. FELTON, J M Division of Rules and Records 83/03/02 Document Management Branch 1p 17493.198 24X Fiche 50-267, 83/03/02, 8303100020

--8303100025 Forwards public version of radiological emergency response plan implementing procedures, including Procedures RERP-HOME, "Home Packet for Off-Shift Notifications" & RERP-VC, "Visitor's Ctr Procedure." WAREMBOURG, D W Public Service Co. of Colorado 83/01/20 ROHRER, D Director's Office, Office of Inspection and Enforcement COLLINS, J T Region 4, Office of Director EISENHUT, D G Division of Licensing 3pp 17493.200 24X Fiche 50-267, 83/03/02, 8303100020

--8303100030 Public version of radiological emergency response plan implementing procedures, including Procedures RERP-HOME, "Home Packet for Off-Shift Notifications" & RERP-VC, "Visitor's Ctr Procedures." Revised indices encl WAREMBOURG, D Public Service Co. of Colorado 83/01/21 30ipp 17493.203 24X Fiche 50-267, 83/03/02, 8303100020

8303150319 Advises that 821108 request for exemption from requirements of 10CFR11, "Criteria & Procedures for Determining Eligibility for Access to or Control Over SNM," granted, subj to required mod of security plan. GAGLIARDO, J E Division of Resident, Reactor Project & Engineering Programs 83/03/07 LEE, O R Public Service Co. of Colorado 2pp 17566.265 24X Fiche 50-267, 83/03/07, 8303150319

--8303150324 Exemption granting relief from requirements of 10CFR11, "Criteria & Procedures for Determining Eligibility for Access to or Control Over SNM," relative to matl access authorizations for personnel at facility. EISENHUT, D G Division of Licensing 83/03/02 Public Service Co. of Colorado 3pp 17566.267 24X Fiche 50-267, 83/03/07, 8303150319

8303240422 Ack receipt of 830214 ltr. Revised procedures will be reviewed during future insp. COLLINS, J T Region 4, Office of Director 83/03/10 LEE, O R Public Service Co. of Colorado 1p 17678.282 24X Fiche 50-267, 83/03/10, 8303240422

--8303240427 Ack receipt of 830214 ltr clarifying assignment of S Gotlib. Expanded guidance re qualification for unescorted access should alleviate future miscommunications. COLLINS, J T Region 4, Office of Director 83/03/10 KELLY, R B Stone & Webster, Inc 1p 17678.283 24X Fiche 50-267, 83/03/10, 8303240422

8303280036 Forwards Class III fee for Amend 30 to security plan re compliance w/10CFR73.45 & balance of Class III fee for Amend 31 to Facility Tech Specs re temporary change to Limiting Conditions for Operation 4.4.1. WAREMBOURG, D Public Service Co. of Colorado 83/03/14 DIGGS, R M License Fee Management Branch 1p 17707.217 24X Fiche 50-267, 83/03/14, 8303280036

8303290038 Notifies of repts received from several utils re telephone inquiries from unidentified persons re plant security sys. Investigation revealed that individual was personnel recruiter. Individual cautioned. COLLINS, J T Region 4, Office of Director 83/03/25 LEE, O R Public Service Co. of Colorado 2pp 17723.115 24X Fiche 50-267, 83/03/25, 8303290038

P Operating license stage documents & correspondence

8303010540 Requests exemption from simulator requirements per HR 3809-A2 Economic impact of developing site-specific simulator for only HTGR in US questionable
LEE,O R Public Service Co of Colorado 83/02/08 COLLINS,J T
Region 4, Office of Director 2pp 17337:256 24X
Fiche:50-267,83/02/08,8303010540

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT,D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492:033 24X
Fiche:50-000,83/02/16,8302170082

8303070108 Informs that,based on review of util 830209 ltr,licensee approach to power-to-flow integral requirements in Safety Limit 3.1 of Tech Specs acceptable
MADSEN,G L Division of Resident, Reactor Project & Engineering Programs 83/02/18 LEE,O R Public Service Co of Colorado 1p 17430:348 24X Fiche:50-267,83/02/18,8303070108

8303080088 Forwards application for amend to License DPR-34,changing Tech Specs re inservice insp & testing programs
LEE,O R Public Service Co of Colorado 83/02/22 COLLINS,J T
Region 4, Office of Director 2pp 17452:001 24X
Fiche:50-267,83/02/22,8303080088

--8303080096 Application for amend to License DPR-34,consisting of proposed changes to Tech Specs updating inservice insp & testing programs
LEE,O R Public Service Co of Colorado 83/02/22 9pp
17452:003 24X Fiche:50-267,83/02/22,8303080088

--8303080101 Proposed mods to Tech Specs,updating inservice insp & test programs.
* Public Service Co of Colorado 83/02/22 16lpp 17452:012 24X Fiche:50-267,83/02/22,8303080088

8303210664 Comments on LASL evaluation of GA-A16764, "Radiochemical Analysis of First Plateout Probe From Fort St Vrain HTGR." LASL assumptions do not hold up under scrutiny Further clarification re use of plateout probe necessary
BREY,H L Public Service Co of Colorado 83/02/24 COLLINS,J T
Region 4, Office of Director 4pp 17636:273 24X
Fiche:50-267,83/02/24,8303210664

8303110114 Forwards reviews of neutronic aspects of GA-A13954 & GA-D15474 Analytical techniques employed to obtain decalibr factors & trip setpoints acceptable Request for addl info due in 30 days,also encl W/o encl
MADSEN,G L Division of Resident, Reactor Project & Engineering Programs 83/02/28 LEE,O R Public Service Co of Colorado 3pp 17517:323 24X Fiche:50-267,83/02/28,8303110114

8303110256 Accepts 830210 commitment for destructive post-irradiation exam of Segment 2 fuel rod & of fuel rod from fuel test element FTE-2 Contingency on DOE funding of destructive exam unacceptable
MADSEN,G L Division of Resident, Reactor Project & Engineering Programs 83/02/28 LEE,O R Public Service Co of Colorado 2pp 17515:355 24X Fiche:50-267,83/02/28,8303110256

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT,D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700:303 24X
Fiche:50-000,83/03/02,8303020321

8303080320 Responds to 830210 ltr re unrestricted area limits for radioactivity in oil Limits of 10CFR20,App B,apply only to air & water Perusal of encl IE Info Notice 83-05 suggested for further clarification W/o encl
COLLINS,J T Region 4, Office of Director 83/03/04 LEE,O R
Public Service Co of Colorado 1p 17452:360 24X
Fiche:50-267,83/03/04,8303080320

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl
EISENHUT,D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 51pp 17660:176 24X
Fiche:50-000,83/03/07,8303040005

8303150001 Forwards Amend 33 to License DPR-34,safety evaluation & notice of issuance & availability Amend revises Tech Specs to update various surveillance requirements re inservice insp & testing program
WAGNER,P C Division of Resident, Reactor Project & Engineering Programs 83/03/08 LEE,O R Public Service Co of Colorado 2pp 17550:173 24X Fiche:50-267,83/03/08,8303150001

--8303150004 Amend 33 to License DPR-34,revising Tech Specs to update various surveillance requirements re inservice insp & testing program contained in Subsections 5.1,5.2 & 5.3
MADSEN,G L Division of Resident, Reactor Project & Engineering Programs 83/03/08 84pp 17550:175 24X Fiche:50-267,83/03/08,8303150001

--8303150002 Safety evaluation supporting Amend 33 to License DPR-34.
* Region 4, Office of Director 83/03/08 14pp 17550:259 24X Fichr:50-267,83/03/08,8303150001

--8303150008 Notice of issuance & availability of Amend 33 to License DPR-34
WESTERMAN,T F Division of Resident, Reactor Project & Engineering Programs 83/03/08 2pp 17550:273 24X Fiche:50-267,83/03/08,8303150001

8303150340 Advises of 830405 meeting w/licensees & major contractors at Dallas/Fort Worth,TX to provide info & guidance re 10CFR50 QA & Tech Spec deviations & discuss decentralization policy Questions should be submitted in writing by 830321
COLLINS,J T Region 4, Office of Director 83/03/10 Public Service Co of Colorado 12pp 17562:291 24X
Fiche:50-000,83/03/10,8303150340

8303150392 Confirms 830310 telephone authorization for rev to Tech Spec Limiting Condition for Operation 4.6.1a,to allow continued operation while repairs to unit auxiliary transfer completed License amend & FR notice to follow.
GAGLIARDO,J E Division of Resident, Reactor Project & Engineering Programs 83/03/10 LEE,O R Public Service Co of Colorado 2pp 17562:001 24X Fiche:50-267,83/03/10,8303150392

8303150330 Advises of 830405 meeting w/licensees & major contractors at Dallas/Fort Worth,TX to provide info & guidance re 10CFR50 QA & Tech Spec deviations & discuss decentralization policy Specific questions should be submitted in writing by 830321
COLLINS,J T Region 4, Office of Director 83/03/11 LEE,O R
Public Service Co of Colorado 3pp 17563:038 24X
Fiche:50-267,83/03/11,8303150330

8303250093 Advises that requirements of NUREG-0737, Item II.B.2, "Plant Shielding," satisfied SER encl
MADSEN,G L Region 4, Office of Director 83/03/14 LEE,O R
Public Service Co of Colorado 5pp 17692:336 24X
Fiche:50-267,83/03/14,8303250093

8303250135 Requests analyses or proposed mods to control room habitability sys which demonstrate that sys is capable of functioning w/single failure of active component,in compliance w/NUREG-0737, Item III.D.3.4
MADSEN,G L Region 4, Office of Director 83/03/14 LEE,O R
Public Service Co of Colorado 3pp 17693:015 24X
Fiche:50-267,83/03/14,8303250135

8303280036 Forwards Class III fee for Amend 30 to security plan re compliance w/10CFR73.45 & balance of Class III fee for Amend 31 to facility Tech Specs re temporary change to Limiting Conditions for Operation 4.4.1
WAREMBOURG,D Public Service Co of Colorado 83/03/14 DIGGS,R M
License Fee Management Branch 1p 17707:217 24X
Fiche:50-267,83/03/14,8303280036

8303250112 Forwards draft nonradiological environ protection plan (EPP) & EIA in response to 810102 application Simpler vegetation damage surveillance program should replace current program. EPP should be incorporated into Tech Specs.
MADSEN,G L Region 4, Office of Director 83/03/17 LEE,O R
Public Service Co of Colorado 3pp 17693:080 24X
Fiche:50-267,83/03/17,8303250112

--8303250115 Draft environ protection plan (nonradiological),App B to DPR-34.
* Region 4, Office of Director 83/03/17 9pp 17693:083 24X
Fiche:50-267,83/03/17,8303250112

--8303250120 Preliminary EIA supporting proposal to delete terrestrial environ monitoring requirements.
* Site Analysis Branch 83/03/17 8pp 17693:092 24X
Fiche:50-267,83/03/17,8303250112

8303310014 Informs that portion of 810102 application to amend License DPR-34 deleting nonradiological water quality requirements exempt from fees per 10CFR170.11(b) Class III fee required for portion re environ radiological surveillance changes. MILLER, W. O. License Fee Management Branch 83/03/23 LEE, O. R. Public Service Co. of Colorado 2pp 17777:352 24X Fiche: 50-267, 83/03/23, 8303310014.

Q. Inspection reports, IE Bulletins & correspondence

8303180215 Forwards IE Insp Rept 50-267/82-21 on 820830-0903. No noncompliance noted. MADSEN, G. L. Region 4, Office of Director 83/01/06 LEE, O. R. Public Service Co. of Colorado 2pp 17618:029 24X Fiche: 50-267, 83/01/06, 8303180215.

--8303180223 IE Insp Rept 50-267/82-21 on 820830-0903. No noncompliance noted. Major areas inspected: transportation activities, radiation protection operation & select NUREG-0737 items. BAER, R. E. ; HOLLEY, W. L. ; MURRAY, B. Region 4, Office of Director. 82/12/22 38pp 17618:031 24X Fiche: 50-267, 83/01/06, 8303180215.

8303070075 Forwards IE Insp Rept 50-267/83-01 during Jan 1983. No noncompliance noted. MADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs 83/02/10 LEE, O. R. Public Service Co. of Colorado 2pp 17435:134 24X Fiche: 50-267, 83/02/10, 8303070075.

--8303070088 IE Insp Rept 50-267/83-01 during Jan 1983. No noncompliance noted. Major areas inspected: operational safety verification, surveillance, maint, followup of previous insp findings, IE bulletin followup, reserve shutdown sys & core safety limit. DICKERSON, M. W. ; WESTERMAN, T. F. Division of Resident, Reactor Project & Engineering Programs. PLUMLEE, G. L. Division of Resident, Reactor Project & Engineering Programs. 83/02/08 13pp 17435:136 24X Fiche: 50-267, 83/02/10, 8303070075.

8303080323 Responds to NRC 830121 ltr re violations noted in IE Insp Rept 50-267/82-31. Corrective actions deviation written per administrative procedures to add test equipment & to indicate voltage verification method used for Step 5.2.1. LEE, O. R. Public Service Co. of Colorado 83/02/18 COLLINS, J. T. Region 4, Office of Director 5pp 17446:357 24X Fiche: 50-267, 83/02/18, 8303080323.

8303080088 Forwards application for amend to License DPR-34, changing Tech Specs re inservice insp & testing programs. LEE, O. R. Public Service Co. of Colorado 83/02/22 COLLINS, J. T. Region 4, Office of Director 2pp 17452:001 24X Fiche: 50-267, 83/02/22, 8303080088.

--8303080096 Application for amend to License DPR-34, consisting of proposed changes to Tech Specs updating inservice insp & testing programs. LEE, O. R. Public Service Co. of Colorado 83/02/22 9pp 17452:003 24X Fiche: 50-267, 83/02/22, 8303080088.

--8303080101 Proposed mods to Tech Specs, updating inservice insp & test programs. * Public Service Co. of Colorado 83/02/22 16lpp 17452:012 24X Fiche: 50-267, 83/02/22, 8303080088.

8303150450 Forwards IE Safeguards Insp Rept 50-267/82-30 on 821213-16. No noncompliance noted. MADSEN, G. L. Region 4, Office of Director 83/02/23 LEE, O. R. Public Service Co. of Colorado 2pp 17561:056 24X Fiche: 50-267, 83/02/23, 8303150450.

--8303150455 IE Safeguards Insp Rept 50-267/82-30 on 821213-16. No noncompliance noted. Major areas inspected: assessment aids, access control - personnel, packages, vehicles, alarm stations & communications. Details withheld (ref 10CFR2.790). CALDWELL, R. A. ; KELLY, J. A. F. Region 4, Office of Director. 83/02/14 1p 17561:058 24X Fiche: 50-267, 83/02/23, 8303150450.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11lpp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303250019 Forwards IE Insp Rpts 50-267/83-04 on 830207-11. No noncompliance noted. MADSEN, G. L. Region 4, Office of Director 83/03/01 LEE, O. R. Public Service Co. of Colorado 2pp 17693:257 24X Fiche: 50-267, 83/03/01, 8303250019.

--8303250022 IE Insp Rept 50-267/83-04 on 830207-11. No noncompliance noted. Major areas inspected: QA program, audit implementation & previously identified items. REDANO, R. T. ; WESTERMAN, T. F. Region 4, Office of Director. 83/02/28 6pp 17693:259 24X Fiche: 50-267, 83/03/01, 8303250019.

8303150001 Forwards Amend 33 to License DPR-34, safety evaluation & notice of issuance & availability. Amend revises Tech Specs to update various surveillance requirements re inservice insp & testing program. WAGNER, P. C. Division of Resident, Reactor Project & Engineering Programs 83/03/08 LEE, O. R. Public Service Co. of Colorado 2pp 17550:173 24X Fiche: 50-267, 83/03/08, 8303150001.

--8303150004 Amend 33 to License DPR-34, revising Tech Specs to update various surveillance requirements re inservice insp & testing program contained in Subsections 5.1.5.2 & 5.3. MADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs 83/03/08 84pp 17550:175 24X Fiche: 50-267, 83/03/08, 8303150001.

--8303150002 Safety evaluation supporting Amend 33 to License DPR-34. * Region 4, Office of Director 83/03/08 14pp 17550:259 24X Fiche: 50-267, 83/03/08, 8303150001.

--8303150008 Notice of issuance & availability of Amend 33 to License DPR-34. WESTERMAN, T. F. Division of Resident, Reactor Project & Engineering Programs 83/03/08 2pp 17550:273 24X Fiche: 50-267, 83/03/08, 8303150001.

8303240422 Ack receipt of 830214 ltr. Revised procedures will be reviewed during future insp. COLLINS, J. T. Region 4, Office of Director 83/03/10 LEE, O. R. Public Service Co. of Colorado 1p 17678:282 24X Fiche: 50-267, 83/03/10, 8303240422.

--8303240427 Ack receipt of 830214 ltr clarifying assignment of S. Gotlib. Expanded guidance re qualification for unescorted access should alleviate future miscommunications. COLLINS, J. T. Region 4, Office of Director 83/03/10 KELLY, R. B. Stone & Webster, Inc. 1p 17678:283 24X Fiche: 50-267, 83/03/10, 8303240422.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 11?pp 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 11?pp 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12lpp 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

R. Periodic operating reports & related correspondence

8303010273 Forwards monthly operating rept for Jan 1983. WAREMBOURG, D. Public Service Co. of Colorado 83/02/11. GAMMILL, W. P. Assistant Director for Operating Reactors 2pp 17345:171 24X Fiche: 50-267, 83/02/11, 8303010273.

--8303010389 Monthly operating rept for Jan 1983. MCBRIDE, L. M. Public Service Co. of Colorado 83/02/08 8pp 17345:173 24X Fiche: 50-267, 83/02/11, 8303010273.

8303210641 Forwards "Environ Radiation Surveillance Program Summary Rept, Third & Fourth Quarters 1982." BREY, H. L. Public Service Co. of Colorado 83/02/28 COLLINS, J. T. Region 4, Office of Director 3pp 17636:064 24X Fiche: 50-267, 83/02/28, 8303210641.

--8303210651 "Environ Radiation Surveillance Program Summary Rept, Third & Fourth Quarters 1982." JOHNSON, J. E. ; BORST, F. J. ; JOHNS, J. R. Colorado State Univ. 83/02/23 135pp 17636:067 24X Fiche: 50-267, 83/02/28, 8303210641.

8303080056 Forwards summary of personnel radiation exposures for 1982. Info submitted in lieu of annual occupational exposure rept described in Tech Specs since max radiation exposure received by individual less than 100 mrem through yr. WAREMBOURG, D. Public Service Co. of Colorado 83/03/01. COLLINS, J. T. Region 4, Office of Director 2pp 17436:281 24X Fiche: 50-267, 83/03/01, 8303080056.

8303150235 Forwards "Rept of Changes, Tests & Experiments Not Requiring Prior Commission Approval Per 10CFR50.59(a), 1982."
WAREMBOURG, D. Public Service Co. of Colorado. 83/03/01.
COLLINS, J. T. Region 4, Office of Director. 2pp. 17556:030. 24X
Fiche: 50-267, 83/03/01, 8303150235.

--8303150241 "Rept of Changes, Tests & Experiments Not Requiring Prior Commission Approval Per 10CFR50.59(a), 1982."
* Public Service Co. of Colorado. 83/03/01. 38pp. 17556:032.
24X Fiche: 50-267, 83/03/01, 8303150235.

8303250006 Forwards monthly operating rept for Feb 1983.
WAREMBOURG, D. Public Service Co. of Colorado. 83/03/08.
Director's Office, Office of Inspection and Enforcement. 1p.
17692:119. 24X Fiche: 50-267, 83/03/08, 8303250006.

--8303250009 Monthly operating rept for Feb 1983.
MCBRIDE, L. M. Public Service Co. of Colorado. 83/03/08. 5pp.
17692:120. 24X Fiche: 50-267, 83/03/08, 8303250006.

8303150348 Forwards monthly operating rept for Feb 1983.
WAREMBOURG, D. Public Service Co. of Colorado. 83/03/11.
Director's Office, Office of Inspection and Enforcement. 1p.
17563:111. 24X Fiche: 50-267, 83/03/11, 8303150348.

--8303150350 Monthly operating rept for Feb 1983.
MCBRIDE, L. M. Public Service Co. of Colorado. 83/03/08. 8pp.
17563:112. 24X Fiche: 50-267, 83/03/11, 8303150348.

## S. Reportable occurrences, LERs & related correspondence

8303150247 Forwards LER 83-004/03L-0. Detailed event analysis encl.
WAREMBOURG, D. Public Service Co. of Colorado. 83/03/04.
COLLINS, J. T. Region 4, Office of Director. 5pp. 17556:022. 24X
Fiche: 50-267, 83/03/04, 8303150247.

--8303150253 LER 83-004/03L-0 on 830203-04, five Class I snubbers found inoperable. Caused by leaking seals & O-rings or broken oil reservoir. Snubbers rebuilt & tested or replaced w/tested qualified spares & reinstalled.
FULLER, C. Public Service Co. of Colorado. 83/03/04. Region 4, Office of Director. 1p. 17556:027. 24X Fiche: 50-267, 83/03/04, 8303150247.

8303210546 Forwards LER 83-005/03L-0. Detailed event analysis encl.
WAREMBOURG, D., CLAYTON, O. J., FULLER, C. F. Public Service Co. of Colorado. 83/03/09. COLLINS, J. T. Region 4, Office of Director. 6pp. 17636:027. 24X Fiche: 50-267, 83/03/09, 8303210546.

--8303210559 LER 83-005/03L-0 on 830207, reactor dewpoint exceeded limits. Caused by buffer helium sys upset due to 830128 trip. Dewpoint reduced w/helium purification sys.
FULLER, C. Public Service Co. of Colorado. 83/03/08. Region 4, Office of Director. 1p. 17636:033. 24X Fiche: 50-267, 83/03/09, 8303210546.

8303210629 Forwards LER 83-009/01T-0. Detailed event analysis encl.
WAREMBOURG, D., CLAYTON, O. J., FULLER, C. Public Service Co. of Colorado. 83/03/09. COLLINS, J. T. Region 4, Office of Director. 5pp. 17636:217. 24X Fiche: 50-267, 83/03/09, 8303210629.

--8303210635 LER 83-009/01T-0 on 830223, four masonry walls found to have inadequate structural strength to withstand design criteria load combination. Caused by lack of Dur-O-Wall Mod reinforcing walls w/steel bar straps completed.
FULLER, C. Public Service Co. of Colorado. 83/03/09. Region 4, Office of Director. 2pp. 17636:222. 24X Fiche: 50-267, 83/03/09, 8303210629.

8303280240 Forwards RO 83-007 & LER 83-007/03L-0.
WAREMBOURG, D. Public Service Co. of Colorado. 83/03/17.
COLLINS, J. T. Region 4, Office of Director. 2pp. 17705:265. 24X
Fiche: 50-267, 83/03/17, 8303280240.

--8303280249 RO 83-007 on 830215, instrument power inverter 1B failed. Caused by blown 150 amp fuse. Reactor manually scrammed. Instrument bus re-energized & blown fuse replaced.
NOVACHEK, F. J., FULLER, C., HILL, E. D. Public Service Co. of Colorado. 83/03/17. 3pp. 17705:267. 24X Fiche: 50-267, 83/03/17, 8303280240.

--8303280257 LER 83-007/03L-0 on 830215, instrument power invertor 1B failed. Caused by blown 150 amp fuse. Reactor manually scrammed, instrument bus 2 re-energized & fuse replaced.
FULLER, C. Public Service Co. of Colorado. 83/03/17. Region 4, Office of Director. 1p. 17705:270. 24X Fiche: 50-267, 83/03/17, 8303280240.

8303280254 Forwards LER 83-006/03L-0. Detailed event analysis encl.
WAREMBOURG, D. Public Service Co. of Colorado. 83/03/17.
COLLINS, J. T. Region 4, Office of Director. 5pp. 17706:256. 24X
Fiche: 50-267, 83/03/17, 8303280254.

--8303280265 LER 83-006/03L-0 on 830215, loop 2 PCRV cooling water temp exceeded 120 F. Caused by blown instrument bus 2 power inverter fuse. Instrument bus re-energized & power inverter repaired.
FULLER, C. Public Service Co. of Colorado. 83/03/17. Region 4, Office of Director. 1p. 17706:261. 24X Fiche: 50-267, 83/03/17, 8303280254.

## V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

## DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

## F. Security, medical, emergency & fire protection plans

8303160121 Forwards Amends 118, 118 & 115 to Licenses DPR-38, DPR-47 & DPR-55, respectively & notice of issuance & availability. Amend requires yearly review of station emergency & security plans by nuclear safety review board.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/04. TUCKER, H. B. Duke Power Co. 3pp. 17604:338. 24X Fiche: 50-269, 83/03/04, 8303160121.

--8303160125 Amends 118, 118 & 115 to Licenses DPR-38, DPR-47 & DPR-55, respectively, requiring yearly review of station emergency & security plans by nuclear safety review board.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/04. 8pp.
17604:341. 24X Fiche: 50-269, 83/03/04, 8303160121.

--8303160135 Notice of issuance & availability of Amends 118, 118 & 115 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/04. 2pp.
17604:349. 24X Fiche: 50-269, 83/03/04, 8303160121.

8303160082 Responds to 821112 ltr re changes submitted in Rev 9 of security plan. Rev acceptable.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/08. TUCKER, H. B. Duke Power Co. 2pp. 17614:343. 24X Fiche: 50-269, 83/03/08, 8303160082.

8303290475 Requests exemption from 10CFR50 App E, Item IV.F.h & 10CFR50.47.b(14) re active participation of crisis mgt ctr personnel for each station during annual emergency preparedness exercise.
TUCKER, H. B. Duke Power Co. 83/03/09. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E. G. Licensing Branch 4. 3pp. 17724:324. 24X Fiche: 50-000, 83/03/09, 8303290475.

8303240113 Releases public version of revised crisis mgt plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/21. Document Management Branch. 1p. 17700:029. 24X Fiche: 50-000, 83/03/21, 8303240113.

--8303240120 Forwards public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.1 re recovery manager & immediate staff group plan & 5.3.4 re scheduling/planning support group.
TUCKER, H. B. Duke Power Co. 83/03/08. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17700:030. 24X Fiche: 50-000, 83/03/21, 8303240113.

--8303240127 Public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.1 re recovery manager & immediate staff group plan & 5.3.4 re scheduling/planning support group.
* Duke Power Co. 83/02/28. 215pp. 17700:032. 24X
Fiche: 50-000, 83/03/21, 8303240113.

8303280131 Ack receipt of 830304 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01.
DANCE, H. C. Division of Project & Resident Programs. 83/03/22.
TUCKER, H. B. Duke Power Co. 1p. 17707:001. 24X
Fiche: 50-269, 83/03/22, 8303280131.

# DOCKETED ITEMS

--8303280138 Responds to NRC 830208 ltr re violations noted in IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01. Corrective actions withheld (ref 10CFR73.21).
TUCKER, H. B. Duke Power Co. 83/03/04 O'REILLY, J. P. Region 2, Office of Director. 2pp. 17707.002. 24X Fiche. 50-269, 83/03/22, 8303280131.

--8303280144 Forwards IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01 on 830110-14 & notice of violation. Notice of violation withheld (ref 10CFR73.21).
DANCE, H. C. Division of Project & Resident Programs. 83/02/08.
TUCKER, H. B. Duke Power Co. 2pp. 17707.004. 24X Fiche. 50-269, 83/03/22, 8303280131.

--8303280148 IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01 on 830110-14. Noncompliance noted in area of access control of designated vehicles. Details withheld (ref 10CFR73.21).
TILLMAN, A. Region 2, Office of Director. 83/02/04 1p.
17707.006. 24X Fiche. 50-269, 83/03/22, 8303280131.

## I. Financial information

8303080084 Forwards annual financial rept, 1981 Financial forecast for 1982-84 also encl.
TUCKER, H. B. Duke Power Co. 83/03/01 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 6pp. 17452.174. 24X Fiche. 50-000, 83/03/01, 8303080084.

--8303080092 Annual financial rept, 1981.
HORN, C. ; LEE, W. S. Duke Power Co. 82/02/15 44pp. 17452.180.
24X Fiche. 50-000, 83/03/01, 8303080084.

## P. Operating license stage documents & correspondence

8303030194 Forwards Unresolved Safety Issue A-47 task action plan & list of addl estimates & assumptions for parameters used in ORNL model of facility. For comment, in order to encourage participation in resolution of safety issue.
EISENHUT, D. G. Division of Licensing. 83/02/14 TUCKER, H. B. Duke Power Co. 12pp. 17419.158. 24X Fiche. 50-269, 83/02/14, 8303020194.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492.033. 24X Fiche. 50-000, 83/02/16, 8302170082.

8303010698 Notification of 830118 meeting w/B&W Owners Group & B&W in Bethesda, MD to discuss plans in developing study re frequency & severity of potential pressurized thermal shock events applicable to all B&W plants.
VISSING, G. Operating Reactors Branch 4. 83/02/18. STOLZ, J. Operating Reactors Branch 4. 3pp. 17348.334. 24X Fiche. 50-000, 83/02/18, 8303010698.

8303030405 Expresses concern re whether util justification for operability provides required assurance that large diameter Pratt butterfly valves will close in event of DBA LOCA. NRC must be notified in 30 days if understanding incorrect.
STOLZ, J. F. Operating Reactors Branch 4. 83/02/18. TUCKER, H. B. Duke Power Co. 5pp. 17419.204. 24X Fiche. 50-269, 83/02/18, 8303030405.

8303070141 Forwards "Procedures Generation Package," "Technical Verification of Nuclear Station Emergency Procedures & Guidelines," "Writers Guide for Emergency & Abnormal ..." & "Control Room Review Plan," per NUREG-0737, Suppl 1.
TUCKER, H. B. Duke Power Co. 83/02/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E. G. Licensing Branch 4. 2pp. 17432.011. 24X Fiche. 50-000, 83/02/28, 8303070141.

--8303070169 "Control Room Review Plan for Oconee, McGuire & Catawba Nuclear Stations, Duke Power Co."
* Duke Power Co. C/1800023 R03. 83/02/15. 38pp. 17432.065.
24X Fiche. 50-000, 83/02/28, 8303070141.

8303080294 Forwards revised "Offsite Dose Calculation Manual for Duke Power Nuclear Stations."
TUCKER, H. B. Duke Power Co. 83/02/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E. G. Licensing Branch 4. 1p. 17455.196. 24X Fiche. 50-000, 83/02/28, 8303080294.

--8303080324 Revised "Offsite Dose Calculation Manual for Duke Power Nuclear Stations."
BIRCH, M. L. ; MCINTOSH, M. D. Duke Power Co. 83/02/28. 96pp.
17455.198. 24X Fiche. 50-000, 83/02/28, 8303080294.

8303090163 Submits changes to 821115 status rept of NUREG-0737, Items II.B.3, "Post-Accident Sampling," & II.F.1, "Accident Monitoring."
TUCKER, H. B. Duke Power Co. 83/03/01 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 17471.317. 24X Fiche. 50-269, 83/03/01, 8303090163.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700.303. 24X Fiche. 50-000, 83/03/02, 8303020321.

8303160121 Forwards Amends 118, 118 & 115 to Licenses DPR-38, DPR-47 & DPR-55, respectively, & notice of issuance & availability. Amend requires yearly review of station emergency & security plans by nuclear safety review board.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/04. TUCKER, H. B. Duke Power Co. 3pp. 17604.338. 24X Fiche. 50-269, 83/03/04, 8303160121.

--8303160125 Amends 118, 118 & 115 to Licenses DPR-38, DPR-47 & DPR-55, respectively, requiring yearly review of station emergency & security plans by nuclear safety review board.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/04. 8pp.
17604.341. 24X Fiche. 50-269, 83/03/04, 8303160121.

--8303160135 Notice of issuance & availability of Amends 118, 118 & 115 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/04. 2pp.
17604.349. 24X Fiche. 50-269, 83/03/04, 8303160121.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp. 17660.176. 24X Fiche. 50-000, 83/03/07, 8303040005.

8303160510 Provides addl info re ECCS calculations utilizing cladding models contained in NUREG-0630.
TUCKER, H. B. Duke Power Co. 83/03/07 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 17592.323. 24X Fiche. 50-269, 83/03/07, 8303160510.

8303170136 Summary of 830223 meeting w/B&W Regulatory Response Group in Bethesda, MD re small break LOCA procedures & maintaining proper steam generator water level.
VAN VLIET, J. Operating Reactors Branch 4. 83/03/08 Operating Reactors Branch 4. 43pp. 17615.224. 24X Fiche. 50-000, 83/03/08, 8303170136.

8303210120 Informs that NRC resident inspector will be obtaining info on valve failure on loss of power data. Info needed to resolve Unresolved Safety Issue A-47.
EISENHUT, D. G. Division of Licensing. 83/03/09 TUCKER, H. B. Duke Power Co. 3pp. 17660.129. 24X Fiche. 50-269, 83/03/09, 8303210120.

8303150483 Forwards response to 821210 order re NUREG-0737, Item II.F.2, "Instrumentation to Detect Inadequate Core Cooling." Design approval of sys described in encl requested prior to final design & procurement efforts initiation.
TUCKER, H. B. Duke Power Co. 83/03/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Reactors Branch 4. 108pp. 17557.311. 24X Fiche. 50-269, 83/03/10, 8303150483.

8303210006 Forwards Amends 119, 119 & 116 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability. Amends revise Tech Specs re heatup, cooldown & inservice test limitations for RCS.
CONNER, E. L. Operating Reactors Branch 4. 83/03/11. TUCKER, H. B. Duke Power Co. 2pp. 17659.344. 24X Fiche. 50-269, 83/03/11, 8303210006.

--8303210009 Amends 119, 119 & 116 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs re heatup, cooldown & inservice test limitations for RCS.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/11. 22pp.
17659.346. 24X Fiche. 50-269, 83/03/11, 8303210006.

--8303210013 Safety evaluation supporting Amends 119, 119 & 116 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation, Director. 83/03/11. 4pp.
17660.006. 24X Fiche. 50-269, 83/03/11, 8303210006.

--8303210015 Notice of issuance & availability of Amends 119, 119 & 116 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/11. 2pp.
17660.010. 24X Fiche. 50-269, 83/03/11, 8303210006.

8303300733 Summary of 830303 meeting w/utils, B&W Owners Group & Natl Nuclear Corp in Bethesda, MD re plans concerning frequency & severity of pressurized thermal shock events for B&W plants. Viewgraphs encl.
VISSING, G. S. Operating Reactors Branch 4 83/03/15 Operating Reactors Branch 4 174pp 17765.013 24X Fiche 50-000, 83/03/15, 8303300733.

8303300028 Forwards order confirming licensee commitments to implement post-TMI-related items set forth in NUREG-0737. Order based on licensee responses to Generic Ltrs 82-05 & 82-10.
STOLZ, J. F. Operating Reactors Branch 4 83/03/16 TUCKER, H. B. Duke Power Co. 3pp. 17751.153 24X Fiche 50-269, 83/03/16, 8303300028.

--8303300036 Order confirming licensee commitments on post-TMI-related issues in NUREG-0737.
PURPLE, R. A. Division of Licensing 83/03/18 Duke Power Co. 10pp. 17751.156 24X Fiche 50-269, 83/03/16, 8303300028.

8303240270 Confirms NRC understandings re maintaining containment purge valves closed whenever reactor not in cold shutdown or refueling mode, presented in 830218 ltr. Description of mods to purge sys encl.
TUCKER, H. B. Duke Power Co. 83/03/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4 3pp. 17682.125 24X Fiche 50-269, 83/03/17, 8303240270.

8303240465 Responds to Generic Ltr 83-10 re resolution of TMI Action Plan Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps." Plans & schedule for resolution of issue will be provided by 830701.
TUCKER, H. B. Duke Power Co. 83/03/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director EISENHUT, D. G. Division of Licensing 1p. 17678.042 24X Fiche 50-269, 83/03/17, 8303240465.

8303280194 Application for amend to Licenses DPR-38, DPR-47 & DPR-55, extending limiting conditions for operation of startup transformers & establishing allowable degraded conditions & required action statements.
TUCKER, H. B. Duke Power Co. 83/03/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 17709.201 24X Fiche 50-269, 83/03/17, 8303280194.

--8303280200 Proposed Tech Specs, revising limiting condition for operation of startup transformers & establishing allowable degraded conditions & required action statements.
* Duke Power Co. 83/03/17 16pp. 17709.203 24X Fiche 50-269, 83/03/17, 8303280194.

8303280032 Advises that addl info requested by NRC 830110 ltr on NUREG-0737, Items II.F.1.4, II.F.1.5 & II.F.1.6 re containment monitors difficult to collate. Delay caused by extensive util/vendor interface. Info will be submitted by 830525.
TUCKER, H. B. Duke Power Co. 83/03/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4 1p. 17709.306 24X Fiche 50-269, 83/03/18, 8303280032.

8303300010 Forwards safety evaluation & EG&G technical evaluation re adequacy of station electric distribution sys voltages. Voltage analysis acceptable. Unit 3 test results acceptable for Units 1 & 2.
STOLZ, J. F. Operating Reactors Branch 4 83/03/21 TUCKER, H. B. Duke Power Co. 2pp. 17751.246 24X Fiche 50-269, 83/03/21, 8303300010.

--8303300015 Safety evaluation supporting adequacy of station electric distribution sys voltages subj to implementation of Tech Spec change prohibiting use of one startup transformer for more than one unit.
* NRC - No Detailed Affiliation Given. 83/03/21 5pp. 17751.248 24X Fiche 50-269, 83/03/21, 8303300010.

--8303300021 "Adequacy of Station Electric Distribution Sys Voltages, Oconee Nuclear Station, Units 1, 2 & 3," technical evaluation rept.
UDY, A. C. EG&G, Inc. FIN A-6429 EGG-EA-6131 83/01/31 NRC - No Detailed Affiliation Given. 12pp. 17751.253 24X Fiche 50-269, 83/03/21, 8303300010.

8303300173 Forwards request for addl info needed to complete review of neutron dosimetry provided in BAW-1697 & BAW-1699. Neutron dosimetry analysis schedule due in 60 days.
STOLZ, J. F. Operating Reactors Branch 4 83/03/22 TUCKER, H. B. Duke Power Co. 6pp. 17763.096 24X Fiche 50-269, 83/03/22, 8303300173.

8303290217 Withdraws request for hearing re order imposing environ qualification requirements. Withdrawal contingent upon util understanding of final rule on environ qualification.
CARR, A. V. Duke Power Co. 83/03/24 EISENHUT, D. G. Division of Licensing 2pp. 17722.242 24X Fiche 50-269, 83/03/24, 8303290217.

8303310551 Notification of 830407 meeting w/B&W Owners Group in Bethesda, MD to review progress, schedules & typical event analyses re study of pressurized thermal shock.
VISSING, G. S. Operating Reactors Branch 4 83/03/25 STOLZ, J. F. Operating Reactors Branch 4 2pp. 17780.360 24X Fiche 50-000, 83/03/25, 8303310551.

8303300108 "RELAP5 Analysis of Oconee-1 PWR Transients for Pressurized Thermal Shock Integration Study," interim rept.
BOLANDER, M. A., FLETCHER, C. D., STITT, B. D. EG&G, Inc. FIN A-6047 8303300108 83/03/31 ODAR, F. Division of Accident Evaluation 120pp. 17753.037 24X Fiche 50-269, 83/03/31, 8303300108.

8303300164 "Adequacy of Station Electric Distribution Sys Voltages, Oconee Nulear Station, Units 1, 2 & 3," interim rept.
UDY, A. C. EG&G, Inc. FIN A-6429 8303300164 83/03/31 EMANI, J. Division of Systems Integration (post 811005) 14pp. 17753.022 24X Fiche 50-269, 83/03/31, 8303300164.

## 9. Inspection reports, IE Bulletins & correspondence

8303010666 Responds to NRC ltr re violations noted in IE Insp Repts 50-269/82-09, 50-270/82-09 & 50-287/82-09. Corrective actions: mods to computer alarms & statalarms to include Group 8 position limits will be implemented by 830114.
TUCKER, H. B. Duke Power Co. 82/12/17 O'REILLY, J. P. Region 2, Office of Director 1p. 17341.076 24X Fiche 50-269, 82/12/17, 8303010666.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 111pp. 17521.001 24X Fiche 50-000, 83/02/25, 8212060367.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp. 17611.070 24X Fiche 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp. 17774.352 24X Fiche 50-000, 83/03/21, 8212060387.

8303230220 Forwards response to 830311 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." AK2 breaker maint program conforms w/GE Svc Advice Ltr 175(CPDD)9.3 guidance. Program in place since Feb 1979.
TUCKER, H. B. Duke Power Co. 83/03/21 O'REILLY, J. P. Region 2, Office of Director 4pp. 17665.189 24X Fiche 50-269, 83/03/21, 8303230220.

8303280131 Ack receipt of 830304 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01.
DANCE, H. C. Division of Project & Resident Programs 83/03/22 TUCKER, H. B. Duke Power Co. 1p. 17707.001 24X Fiche 50-269, 83/03/22, 8303280131.

--8303280138 Responds to NRC 830208 ltr re violations noted in IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01. Corrective actions withheld (ref 10CFR73.21).
TUCKER, H. B. Duke Power Co. 83/03/04 O'REILLY, J. P. Region 2, Office of Director 2pp. 17707.002 24X Fiche 50-269, 83/03/22, 8303280131.

--8303280144 Forwards IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01 on 830110-14 & notice of violation. Notice of violation withheld (ref 10CFR73.21).
DANCE, H. C. Division of Project & Resident Programs 83/02/08 TUCKER, H. B. Duke Power Co. 2pp. 17707.004 24X Fiche 50-269, 83/03/22, 8303280131.

--8303280148 IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01 on 830110-14. Noncompliance noted in area of access control of designated vehicles. Details withheld (ref 10CFR73.21).
TILLMAN, A., MCGUIRE, D. R. Region 2, Office of Director 83/02/04 1p. 17707.006 24X Fiche 50-269, 83/03/22, 8303280131.

# DOCKETED ITEMS

R Periodic operating reports & related correspondence

8303080353 Forwards monthly operating repts for Dec 1982.
TUCKER, H B Duke Power Co 83/01/14 Director's Office, Office of Inspection and Enforcement 1p 17453 348 24X
Fiche 50-269, 83/01/14, 8303080353.

--8303080364 Monthly operating repts for Dec 1982.
REAVIS, J A Duke Power Co 83/01/14 16pp 17453 349 24X
Fiche 50-269, 83/01/14, 8303080353.

8303180379 Forwards monthly operating repts for Feb 1983.
TUCKER, H B Duke Power Co 83/03/15 Director's Office, Office of Inspection and Enforcement 1p 17622 266 24X
Fiche 50-269, 83/03/15, 8303180379.

--8303180386 Monthly operating repts for Feb 1983.
REAVIS, J A Duke Power Co 83/03/15 16pp 17622 267 24X
Fiche 50-269, 83/03/15, 8303180379.

S Reportable occurrences, LERs & related correspondence

8303160555 Forwards LER 83-001/03L-0 Detailed event analysis encl.
TUCKER, H B Duke Power Co 83/03/04 O'REILLY, J P Region 2, Office of Director 3pp 17587 264 24X Fiche 50-269, 83/03/04, 8303160555.

--8303160560 LER 83-001/03L-0 on 830203, alarm received indicating high lower motor bearing temp on HPI 2A pump. Caused by loss of oil due to leakage. Pump motor replaced.
GUILL, P F Duke Power Co 83/03/04 Region 2, Office of Director 1p 17587 267 24X Fiche 50-269, 83/03/04, 8303160555.

8303160565 Forwards LER 83-004/03L-0. Detailed event analysis encl.
TUCKER, H B Duke Power Co 83/03/04 O'REILLY, J P Region 2, Office of Director 2pp 17587 001 24X Fiche 50-269, 83/03/04, 8303160565.

--8303160572 LER 83-004/03L-0 on 830202, 70 ampere circuit breaker failed to trip causing 350 ampere circuit breaker to trip resulting in loss of power to SY-1 battery charger. Caused by procedure & component failure. Breaker replaced.
GUILL, P F Duke Power Co 83/03/04 Region 2, Office of Director 1p 17587 003 24X Fiche 50-269, 83/03/04, 8303160565.

8303180404 Forwards LER 83-006/01T-0.
TUCKER, H B Duke Power Co 83/03/09 O'REILLY, J P Region 2, Office of Director 1p 17622 001 24X Fiche 50-269, 83/03/09, 8303180404.

--8303180408 LER 83-006/01T-0 on 830224, operability of emergency power path not checked within 8 h of initial operability check. Caused by personnel error. Operability verified & control room operators counseled.
GUILL, P Duke Power Co 83/03/09 Region 2, Office of Director 2pp 17622 002 24X Fiche 50-269, 83/03/09, 8303180404.

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000, 83/02/24, 8302250505.

DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8303160121 Forwards Amends 118, 118 & 115 to Licenses DPR-38, DPR-47 & DPR-55, respectively & notice of issuance & availability. Amend requires yearly review of station emergency & security plans by nuclear safety review board.
STOLZ, J F Operating Reactors Branch 4 83/03/04 TUCKER, H B Duke Power Co 3pp 17604 338 24X Fiche 50-269, 83/03/04, 8303160121.

--8303160125 Amends 118, 118 & 115 to Licenses DPR-38, DPR-47 & DPR-55, respectively, requiring yearly review of station emergency & security plans by nuclear safety review board.
STOLZ, J F Operating Reactors Branch 4 83/03/04 8pp 17604 341 24X Fiche 50-269, 83/03/04, 8303160121.

--8303160135 Notice of issuance & availability of Amends 118, 118 & 115 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
STOLZ, J F Operating Reactors Branch 4 83/03/04 2pp 17604 349 24X Fiche 50-269, 83/03/04, 8303160121.

8303160082 Responds to 821112 ltr re changes submitted in Rev 9 of security plan. Rev acceptable.
STOLZ, J F Operating Reactors Branch 4 83/03/08 TUCKER, H B Duke Power Co 2pp 17614 343 24X Fiche 50-269, 83/03/08, 8303160082.

8303290475 Requests exemption from 10CFR50 App E, Item IV.F.h & 10CFR50.47 b(14) re active participation of crisis mgt ctr personnel for each station during annual emergency preparedness exercise.
TUCKER, H B Duke Power Co 83/03/09 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 3pp 17724 324 24X Fiche 50-000, 83/03/09, 8303290475.

8303240113 Releases public version of revised crisis mgt plan implementing procedures.
FELTON, J M Division of Rules and Records 83/03/21 Document Management Branch 1p 17700 029 24X Fiche 50-000, 83/03/21, 8303240113.

--8303240120 Forwards public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.1 re recovery manager & immediate staff group plan & 5.3.4 re scheduling/planning support group.
TUCKER, H B Duke Power Co 83/03/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17700 030 24X
Fiche 50-000, 83/03/21, 8303240113.

--8303240127 Public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.1 re recovery manager & immediate staff group plan & 5.3.4 re scheduling/planning support group.
* Duke Power Co 83/02/28 215pp 17700 032 24X
Fiche 50-000, 83/03/21, 8303240113.

8303280131 Ack receipt of 830304 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01.
DANCE, H C Division of Project & Resident Programs 83/03/22
TUCKER, H B Duke Power Co 1p 17707 001 24X
Fiche 50-269, 83/03/22, 8303280131.

--8303280138 Responds to NRC 830208 ltr re violations noted in IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01. Corrective actions withheld (ref 10CFR73.21).
TUCKER, H B Duke Power Co 83/03/04 O'REILLY, J P Region 2, Office of Director 2pp 17707 002 24X Fiche 50-269, 83/03/22, 8303280131.

--8303280144 Forwards IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01 on 830110-14 & notice of violation. Notice of violation withheld (ref 10CFR73.21).
DANCE, H C Division of Project & Resident Programs 83/02/08
TUCKER, H B Duke Power Co 2pp 17707 004 24X
Fiche 50-269, 83/03/22, 8303280131.

--8303280148 IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01 on 830110-14. Noncompliance noted in area of access control of designated vehicles. Details withheld (ref 10CFR73.21).
TILLMAN, A Region 2, Office of Director 83/02/04 1p 17707 006 24X Fiche 50-269, 83/03/22, 8303280131.

I Financial information

8303080084 Forwards annual financial rept, 1981. Financial forecast for 1982-84 also encl.
TUCKER, H B Duke Power Co 83/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 17452 174 24X
Fiche 50-000, 83/03/01, 8303080084.

--8303080092 Annual financial rept, 1981.
HORN, C, LEE, W S Duke Power Co 82/02/15 44pp 17452 180 24X Fiche 50-000, 83/03/01, 8303080084.

P Operating license stage documents & correspondence

8303020194 Forwards Unresolved Safety Issue A-47 task action plan & list of addl estimates & assumptions for parameters used in ORNL model of facility, for comment, in order to encourage participation in resolution of safety issue.
EISENHUT, D G Division of Licensing 83/02/14 TUCKER, H B Duke Power Co 12pp 17419 158 24X Fiche 50-269, 83/02/14, 8303020194.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303010698 Notification of 830118 meeting w/B&W Owners Group & B&W in Bethesda, MD to discuss plans in developing study re frequency & severity of potential pressurized thermal shock events applicable to all B&W plants.
VISSING, G. Operating Reactors Branch 4 83/02/18 STOLZ, J. Operating Reactors Branch 4 3pp 17348:334 24X
Fiche: 50-000, 83/02/18, 8303010698.

8303030405 Expresses concern re whether util justification for operability provides required assurance that large diameter Pratt butterfly valves will close in event of DBA LOCA. NRC must be notified in 30 days if understanding incorrect.
STOLZ, J. F. Operating Reactors Branch 4 83/02/18 TUCKER, H. B. Duke Power Co. 5pp 17419:204 24X Fiche: 50-269, 83/02/18, 8303030405.

8303070141 Forwards "Procedures Generation Package," "Technical Verification of Nuclear Station Emergency Procedures & Guidelines," "Writers Guide for Emergency & Abnormal " & "Control Room Review Plan," per NUREG-0737, Suppl 1.
TUCKER, H. B. Duke Power Co. 83/02/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17432:011 24X
Fiche: 50-000, 83/02/28, 8303070141.

--8303070169 "Control Room Review Plan for Oconee, McGuire & Catawba Nuclear Stations, Duke Power Co."
* Duke Power Co. C/1800023 R03 83/02/15 38pp 17432:065
24X Fiche: 50-000, 83/02/28, 8303070141.

8303080294 Forwards revised "Offsite Dose Calculation Manual for Duke Power Nuclear Stations."
TUCKER, H. B. Duke Power Co. 83/02/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 17455:196 24X
Fiche: 50-000, 83/02/28, 8303080294.

--8303080324 Revised "Offsite Dose Calculation Manual for Duke Power Nuclear Stations."
BIRCH, M. L. Duke Power Co. 83/02/28 96pp 17455:198 24X
Fiche: 50-000, 83/02/28, 8303080294.

8303090163 Submits changes to 821115 status rept of NUREG-0737, Items II. B. 3, "Post-Accident Sampling," & II. F. 1, "Accident Monitoring."
TUCKER, H. B. Duke Power Co. 83/03/01 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4 2pp 17471:317 24X Fiche: 50-269, 83/03/01, 8303090163.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303160121 Forwards Amends 118, 118 & 115 to Licenses DPR-38, DPR-47 & DPR-55, respectively & notice of issuance & availability. Amend requires yearly review of station emergency & security plans by nuclear safety review board.
STOLZ, J. F. Operating Reactors Branch 4 83/03/04 TUCKER, H. B. Duke Power Co. 3pp 17604:338 24X Fiche: 50-269, 83/03/04, 8303160121.

--8303160125 Amends 118, 118 & 115 to Licenses DPR-38, DPR-47 & DPR-55, respectively, requiring yearly review of station emergency & security plans by nuclear safety review board.
STOLZ, J. F. Operating Reactors Branch 4 83/03/04 8pp
17604:341 24X Fiche: 50-269, 83/03/04, 8303160121.

--8303160135 Notice of issuance & availability of Amends 118, 118 & 115 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
STOLZ, J. F. Operating Reactors Branch 4 83/03/04 2pp.
17604:349 24X Fiche: 50-269, 83/03/04, 8303160121.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303160510 Provides addl info re ECCS calculations utilizing cladding models contained in NUREG-0630.
TUCKER, H. B. Duke Power Co. 83/03/07 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4 2pp 17592:323 24X Fiche: 50-269, 83/03/07, 8303160510.

8303170136 Summary of 830223 meeting w/B&W Regulatory Response Group in Bethesda, MD re small break LOCA procedures & maintaining proper steam generator water level.
VAN VLIET, J. Operating Reactors Branch 4 83/03/08 Operating Reactors Branch 4 43pp 17615:224 24X Fiche: 50-000, 83/03/08, 8303170136.

8303210120 Informs that NRC resident inspector will be obtaining info on valve failure on loss of power data. Info needed to resolve Unresolved Safety Issue A-47.
EISENHUT, D. G. Division of Licensing 83/03/09 TUCKER, H. B. Duke Power Co. 3pp 17660:129 24X Fiche: 50-269, 83/03/09, 8303210120.

8303150483 Forwards response to 821210 order re NUREG-0737, Item II. F. 2, "Instrumentation to Detect Inadequate Core Cooling." Design approval of sys described in encl requested prior to final design & procurement efforts initiation.
TUCKER, H. B. Duke Power Co. 83/03/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4 108pp 17557:311 24X Fiche: 50-269, 83/03/10, 8303150483.

8303210006 Forwards Amends 119, 119 & 116 to Licenses DPR-38, DPR-47 & DPR-55, respectively; safety evaluation & notice of issuance & availability. Amends revise Tech Specs re heatup, cooldown & inservice test limitations for RCS.
CONNER, E. L. Operating Reactors Branch 4 83/03/11 TUCKER, H. B. Duke Power Co. 2pp 17659:344 24X Fiche: 50-269, 83/03/11, 8303210006.

--8303210009 Amends 119, 119 & 116 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs re heatup, cooldown & inservice test limitations for RCS.
STOLZ, J. F. Operating Reactors Branch 4 83/03/11 22pp.
17659:346 24X Fiche: 50-269, 83/03/11, 8303210006.

--8303210013 Safety evaluation supporting Amends 119, 119 & 116 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation, Director 83/03/11 4pp.
17660:006 24X Fiche: 50-269, 83/03/11, 8303210006.

--8303210015 Notice of issuance & availability of Amends 119, 119 & 116 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
STOLZ, J. F. Operating Reactors Branch 4 83/03/11 2pp.
17660:010 24X Fiche: 50-269, 83/03/11, 8303210006.

8303300733 Summary of 830303 meeting w/utils, B&W Owners Group & Natl Nuclear Corp in Bethesda, MD re plans concerning frequency & severity of pressurized thermal shock events for B&W plants. Viewgraphs encl.
VISSING, G. S. Operating Reactors Branch 4 83/03/15 Operating Reactors Branch 4 174pp 17765:013 24X Fiche: 50-000, 83/03/15, 8303300733.

8303300028 Forwards order confirming licensee commitments to implement post-TMI-related items set forth in NUREG-0737. Order based on licensee responses to Generic Ltrs 82-05 & 82-10.
STOLZ, J. F. Operating Reactors Branch 4 83/03/16 TUCKER, H. B. Duke Power Co. 3pp 17751:153 24X Fiche: 50-269, 83/03/16, 8303300028.

--8303300036 Order confirming licensee commitments on post-TMI-related issues in NUREG-0737.
PURPLE, R. A. Division of Licensing 83/03/18 Duke Power Co.
10pp. 17751:156 24X Fiche: 50-269, 83/03/16, 8303300028.

8303240270 Confirms NRC understandings re maintaining containment purge valves closed whenever reactor not in cold shutdown or refueling mode, presented in 830218 ltr. Description of mods to purge sys encl.
TUCKER, H. B. Duke Power Co. 83/03/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4 3pp 17682:125 24X Fiche: 50-269, 83/03/17, 8303240270.

8303240465 Responds to Generic Ltr 83-10 re resolution of TMI Action Plan Item II. K. 3. 5, "Automatic Trip of Reactor Coolant Pumps." Plans & schedule for resolution of issue will be provided by 830701.
TUCKER, H. B. Duke Power Co. 83/03/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director EISENHUT, D. G. Division of Licensing 1p 17678:042 24X Fiche: 50-269, 83/03/17, 8303240465.

8303280194 Application for amend to Licenses DPR-38, DPR-47 & DPR-55, extending limiting conditions for operation of startup transformers & establishing allowable degraded conditions & required action statements.
TUCKER, H. B. Duke Power Co. 83/03/17. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17709:201. 24X
Fiche: 50-269, 83/03/17, 8303280194.

--8303280200 Proposed Tech Specs revising limiting condition for operation of startup transformers & establishing allowable degraded conditions & required action statements.
* Duke Power Co. 83/03/17. 16pp. 17709:203. 24X
Fiche: 50-269, 83/03/17, 8303280194.

8303280032 Advises that addl info requested by NRC 830110 ltr on NUREG-0737, Items II.F.1.4, II.F.1.5 & II.F.1.6 re containment monitors difficult to collate. Delay caused by extensive util/vendor interface. Info will be submitted by 830525.
TUCKER, H. B. Duke Power Co. 83/03/18. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Reactors Branch 4. 1p. 17709:306. 24X Fiche: 50-269, 83/03/18, 8303280032.

8303300010 Forwards safety evaluation & EG&G technical evaluation re adequacy of station electric distribution sys voltages. Voltage analysis acceptable. Unit 3 test results acceptable for Units 1 & 2.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/21. TUCKER, H. B. Duke Power Co. 2pp. 17751:246. 24X Fiche: 50-269, 83/03/21, 8303300010.

--8303300015 Safety evaluation supporting adequacy of station electric distribution sys voltages subj to implementation of Tech Spec change prohibiting use of one startup transformer for more than one unit.
* NRC - No Detailed Affiliation Given. 83/03/21. 5pp. 17751:248. 24X Fiche: 50-269, 83/03/21, 8303300010.

--8303300021 "Adequacy of Station Electric Distribution Sys Voltages, Oconee Nuclear Station, Units 1, 2 & 3." technical evaluation rept.
UDY, A. C. EG&G, Inc. FIN A-6429. EGG-EA-6131. 83/01/31. NRC - No Detailed Affiliation Given. 12pp. 17751:250. 24X
Fiche: 50-269, 83/03/21, 8303300010.

8303300173 Forwards request for addl info needed to complete review of neutron dosimetry provided in BAW-1697 & BAW-1699. Neutron dosimetry analysis schedule due in 60 days.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/22. TUCKER, H. B. Duke Power Co. 6pp. 17763:096. 24X Fiche: 50-269, 83/03/22, 8303300173.

8303290217 Withdraws request for hearing re order imposing environ qualification requirements. Withdrawal contingent upon util understanding of final rule on environ qualification.
CARR, A. V. Duke Power Co. 83/03/24. EISENHUT, D. G. Division of Licensing. 2pp. 17722:242. 24X Fiche: 50-269, 83/03/24, 8303290217.

8303310551 Notification of 830407 meeting w/B&W Owners Group in Bethesda, MD to review progress, schedules & typical event analyses re study of pressurized thermal shock.
VISSING, G. S. Operating Reactors Branch 4. 83/03/25. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 17780:360. 24X
Fiche: 50-000, 83/03/25, 8303310551.

8303300164 "Adequacy of Station Electric Distribution Sys Voltages, Oconee Nulear Station, Units 1, 2 & 3," interim rept.
UDY, A. C. EG&G, Inc. FIN A-6429. 8303300164. 83/03/31. EMANI, J. Division of Systems Integration (post 811005). 14pp. 17753:022. 24X Fiche: 50-269, 83/03/31, 8303300164.

## Q. Inspection reports, IE Bulletins & correspondence

8303010666 Responds to NRC ltr re violations noted in IE Insp Repts 50-269/82-09, 50-270/82-09 & 50-287/82-09. Corrective actions: mods to computer alarms & statalarms to include Group 8 position limits will be implemented by 830114.
TUCKER, H. B. Duke Power Co. 82/12/17. O'REILLY, J. P. Region 2, Office of Director. 1p. 17341:076. 24X Fiche: 50-269, 82/12/17, 8303010666.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303230220 Forwards response to 830311 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." AK2 breaker maint program conforms w/GE Svc Advice Ltr 175(CPDD)9.3 guidance. Program in place since Feb 1979.
TUCKER, H. B. Duke Power Co. 83/03/21. O'REILLY, J. P. Region 2, Office of Director. 4pp. 17665:189. 24X Fiche: 50-269, 83/03/21, 8303230220.

8303280131 Ack receipt of 830304 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01.
DANCE, H. C. Division of Project & Resident Programs. 83/03/22.
TUCKER, H. B. Duke Power Co. 1p. 17707:001. 24X
Fiche: 50-269, 83/03/22, 8303280131.

--8303280138 Responds to NRC 830208 ltr re violations noted in IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01. Corrective actions withheld (ref 10CFR73.21).
TUCKER, H. B. Duke Power Co. 83/03/04. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17707:002. 24X Fiche: 50-269, 83/03/22, 8303280131.

--8303280144 Forwards IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01 on 830110-14 & notice of violation. Notice of violation withheld (ref 10CFR73.21).
DANCE, H. C. Division of Project & Resident Programs. 83/02/08.
TUCKER, H. B. Duke Power Co. 2pp. 17707:004. 24X
Fiche: 50-269, 83/03/22, 8303280131.

--8303280148 IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01 on 830110-14. Noncompliance noted in area of access control of designated vehicles. Details withheld (ref 10CFR73.21).
TILLMAN, A., MCGUIRE, D. R. Region 2, Office of Director. 83/02/04. 1p. 17707:006. 24X Fiche: 50-269, 83/03/22, 8303280131.

## R. Periodic operating reports & related correspondence

8303080353 Forwards monthly operating repts for Dec 1982.
TUCKER, H. B. Duke Power Co. 83/01/14. Director's Office, Office of Inspection and Enforcement. 1p. 17453:348. 24X
Fiche: 50-269, 83/01/14, 8303080353.

--8303080364 Monthly operating repts for Dec 1982.
REAVIS, J. A. Duke Power Co. 83/01/14. 16pp. 17453:349. 24X
Fiche: 50-269, 83/01/14, 8303080353.

8303180379 Forwards monthly operating repts for Feb 1983.
TUCKER, H. B. Duke Power Co. 83/03/15. Director's Office, Office of Inspection and Enforcement. 1p. 17622:266. 24X
Fiche: 50-269, 83/03/15, 8303180379.

--8303180386 Monthly operating repts for Feb 1983.
REAVIS, J. A. Duke Power Co. 83/03/15. 16pp. 17622:267. 24X
Fiche: 50-269, 83/03/15, 8303180379.

## V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

## DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

## F. Security, medical, emergency & fire protection plans

8303210129 Forwards Rev 7 to security plan. Rev withheld (ref 10CFR73.21).
SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 83/01/28.
VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 17630:263. 24X
Fiche: 50-271, 83/01/28, 8303210129.

8303090420 Forwards exemption from annual schedule requirement for emergency preparedness exercise.
ROONEY, V. L. Operating Reactors Branch 2 83/03/01 SINCLAIR, J. B.
Vermont Yankee Nuclear Power Corp. 2pp. 17484:084 24X
Fiche: 50-271, 83/03/01, 8303090420.

--8303090431 Exemption from annual schedule requirement for emergency preparedness exercise.
PURPLE, R. A. Division of Licensing 83/03/01 Vermont Yankee Nuclear Power Corp. 3pp. 17484:086 24X Fiche: 50-271, 83/03/01, 8303090420.

8303140465 Discusses SALP rept for Jul 1980 - June 1981. High level of mgt attention & involvement in decisionmaking process for plant safety noted. Shortcomings observed in emergency preparedness. Assessment revised per 820928 meeting.
HAYNES, R. C. Region 1, Office of Director 83/03/09 CONWAY, W. F.
Vermont Yankee Nuclear Power Corp. 3pp. 17541:195 24X
Fiche: 50-271, 83/03/09, 8303140465.

--8303140469 SALP rept for Jul 1980 - June 1981. Performance shortcomings observed in area of emergency preparedness. LER synopsis encl.
* Region 1, Office of Director 82/08/23 34pp. 17541:198 24X
Fiche: 50-271, 83/03/09, 8303140465.

8303160076 Responds to 821110 ltr re changes to training & qualification plan for security personnel. Changes acceptable.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/09 SINCLAIR, J. B.
Vermont Yankee Nuclear Power Corp. 2pp. 17614:348 24X
Fiche: 50-271, 83/03/09, 8303160076.

8303300259 Confirms 830314 telcon re final design of alternate safe shutdown sys. Sys only required for fire in control room & cable vault. Loss of either room will not impair ability to shutdown w/other safety sys.
SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 83/03/23
VASSALLO, D. B. Operating Reactors Branch 2 2pp. 17733:123 24X
Fiche: 50-271, 83/03/23, 8303300259.

P. Operating license stage documents & correspondence

8303150292 Forwards response to NRC 820802 request for certain design info re reactor protection sys power monitoring sys mod. Proposed Tech Specs will be forwarded under separate cover.
SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 83/02/15
VASSALLO, D. B. Operating Reactors Branch 2 4pp. 17567:056 24X
Fiche: 50-271, 83/02/15, 8303150292.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp. 17492:033 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303090245 Forwards Amend 75 to License DPR-28, safety evaluation & notice of issuance & availability. Amend changes Tech Specs re limiting conditions of operation for standby liquid control sys.
ROONEY, V. L. Operating Reactors Branch 2 83/02/17 SINCLAIR, J. B.
Vermont Yankee Nuclear Power Corp. 2pp. 17484:317 24X
Fiche: 50-271, 83/02/17, 8303090245.

--8303090257 Amend 75 to License DPR-28, changing Tech Specs re limiting conditions of operation for standby liquid control sys & administrative controls.
VASSALLO, D. B. Operating Reactors Branch 2 83/02/17 11pp.
17484:319 24X Fiche: 50-271, 83/02/17, 8303090245.

--8303090264 Safety evaluation supporting Amend 75 to License DPR-28.
* Office of Nuclear Reactor Regulation, Director 83/02/17 3pp.
17484:330 24X Fiche: 50-271, 83/02/17, 8303090245.

--8303090270 Notice of issuance & availability of Amend 75 to License DPR-28.
VASSALLO, D. B. Operating Reactors Branch 2 83/02/17 2pp.
17484:333 24X Fiche: 50-271, 83/02/17, 8303090245.

8303020411 Requests addl info re 810911 & 820401 submittals on control of heavy loads. Meeting scheduled for 830302 to obtain info. "Control of Heavy Loads (C-10)," technical evaluation rept encl.
VASSALLO, D. B. Operating Reactors Branch 2 83/02/22 SINCLAIR, J. B.
Vermont Yankee Nuclear Power Corp. 2pp. 17357:250 24X
Fiche: 50-271, 83/02/22, 8303020411.

--8302090302 "Control of Heavy Loads (C-10) VT Yankee Nuclear Power Station," draft technical evaluation rept. Request for addl info encl.
BOMBERGER, C. Franklin Institute/Franklin Research Center
NRC-03-81-130 TER-C5506-401 82/11/30 CLEMENSON, F. NRC - No Detailed Affiliation Given 38pp. 17357:252 24X
Fiche: 50-271, 83/02/22, 8303020411.

8303020025 Application for amend to App A of License DPR-28 revising Tech Spec Pages 190-a, 192 & 193 re change in title of shift technical advisors to shift engineers.
HEIDER, L. H. Vermont Yankee Nuclear Power Corp. 83/02/28 Office of Nuclear Reactor Regulation, Director 2pp. 17354:200 24X
Fiche: 50-271, 83/02/28, 8303020025.

--8303020031 Proposed Change 112 to Tech Specs, revising Pages 190-a, 192 & 193 re change in title of shift technical advisors to shift engineers.
* Vermont Yankee Nuclear Power Corp. 83/02/28 3pp. 17354:202 24X Fiche: 50-271, 83/02/28, 8303020025.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp. 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303150509 Forwards Rev 12 to operational QA program addressing organizational changes.
JOHNSON, W. P. Yankee Atomic Electric Co. 83/03/11 HAASS, W. P.
Division of Engineering & Quality Assurance (Pre 830103) 1p
17560:118 24X Fiche: 50-000, 83/03/11, 8303150509.

--8303150518 Rev 12 to operational QA program for facilities.
MARTIN, R. L., PIKE, D. B., SHEPARD, A. M. Yankee Atomic Electric Co.
YQAP-1-A R12. 83/03/11 131pp. 17560:119 24X
Fiche: 50-000, 83/03/11, 8303150509.

8303300014 Forwards order confirming implementation of post-TMI-related items in NUREG-0737 based on commitments in response to Generic Ltrs 82-05 & 10.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/14 SINCLAIR, J. B.
Vermont Yankee Nuclear Power Corp. 3pp. 17751:226 24X
Fiche: 50-271, 83/03/14, 8303300014.

--8303300022 Order confirming licensee commitments on post-TMI-related issues from NUREG-0737.
PURPLE, R. A. Division of Licensing 83/03/14 Vermont Yankee Nuclear Power Corp. 10pp. 17751:229 24X Fiche: 50-271, 83/03/14, 8303300014.

8303300405 Forwards proprietary responses to NRC 820222 questions re Yankee Atomic Electric Co Fuel Performance Code FROSSTEY, supplementing YAEC-1249 & YAEC-1265P. Encl withheld (ref 10CFR2.790).
HEIDER, L. H. Vermont Yankee Nuclear Power Corp. 83/03/17
EISENHUT, D. G. Division of Licensing 2pp. 17731:167 24X
Fiche: 50-271, 83/03/17, 8303300405.

8303280019 Advises that need for scram discharge vol vent cross-connect line unnecessary. Two independent scram discharge instrument vols will be installed during 1983 refueling outage to assure continuous draining, per util 810127 commitment.
SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 83/03/22
VASSALLO, D. B. Operating Reactors Branch 2 1p 17707:153 24X
Fiche: 50-271, 83/03/22, 8303280019.

Q. Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11pp. 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303160167 Provides status of program to upgrade analyses for seismic piping in response to IE Bulletins 79-14 & 79-02. Schedule for completing seismic reanalysis program overly optimistic. Completion rescheduled for 830701.
SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 83/03/01
HAYNES, R. C. Region 1, Office of Director 2pp. 17597:020 24X
Fiche: 50-271, 83/03/01, 8303160167.

8303140465 Discusses SALP rept for Jul 1980 - June 1981 High level of mgt attention & involvement in decisionmaking process for plant safety noted Shortcomings observed in emergency preparedness Assessment revised per 820928 meeting.
HAYNES, R. C. Region 1, Office of Director 83/03/09 CONWAY, W. F. Vermont Yankee Nuclear Power Corp 3pp 17541:195 24X
Fiche: 50-271, 83/03/09, 8303140465.

--8303140469 SALP rept for Jul 1980 - June 1981 Performance shortcomings observed in area of emergency preparedness LER synopsis encl.
* Region 1, Office of Director 82/08/23 34pp 17541:198 24X
Fiche: 50-271, 83/03/09, 8303140465.

--8303140476 Advises of meeting during wk of 820905 to discuss results of SALP performed 820823 for Jul 1980 - June 1981.
STAROSTECKI, R. Division of Project & Resident Programs 82/08/26
CONWAY, W. F. Vermont Yankee Nuclear Power Corp. 1p 17541:232
24X Fiche: 50-271, 83/03/09, 8303140465.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

R. Periodic operating reports & related correspondence

8303140503 Forwards "Effluent & Waste Disposal Semiannual Rept - Radiological Impact on Man for Third & Fourth Quarters, 1982."
SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 83/03/03
HAYNES, R. C. Region 1, Office of Director 1p 17540:218 24X
Fiche: 50-271, 83/03/03, 8303140503.

--8303140511 "Effluent & Waste Disposal Semmiannual Rept - Radiological Impact on Man for Third & Fourth Quarters, 1982."
* Vermont Yankee Nuclear Power Corp. 83/03/03 51pp 17540:220
24X Fiche: 50-271, 83/03/03, 8303140503.

8303180294 "Personnel Exposure Rept for 1982."
SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 83/03/08
HAYNES, R. C. Region 1, Office of Director 2pp 17617:152 24X
Fiche: 50-271, 83/03/08, 8303180294.

8303160363 Forwards monthly operating rept for Feb 1983.
MURPHY, W. P. Virginia Electric & Power Co. 83/03/09 Office of Resource Management, Director 1p 17595:323 24X
Fiche: 50-271, 83/03/09, 8303160363.

--8303160367 Monthly operating rept for Feb 1983.
BURGER, F. J. Virginia Electric & Power Co. 83/03/09 6pp
17595:324 24X Fiche: 50-271, 83/03/09, 8303160363.

8303240336 Forwards annual operating rept describing facility changes, tests & experiments conducted w/o prior NRC approval during 1982.
SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 83/03/16
HAYNES, R. C. Region 1, Office of Director 1p 17680:008 24X
Fiche: 50-271, 83/03/16, 8303240336.

--8303240342 Annual operating rept for 1982.
* Vermont Yankee Nuclear Power Corp. 83/03/16 3pp 17680:009
24X Fiche: 50-271, 83/03/16, 8303240336.

S. Reportable occurrences, LERs & related correspondence

8303030045 Forwards updated LER 76-020/01X-0.
PELLETIER, J. P. Vermont Yankee Nuclear Power Corp. 83/02/16
HAYNES, R. C. Region 1, Office of Director 1p 17412:126 24X
Fiche: 50-271, 83/02/16, 8303030045.

--8303030064 Updated LER 76-020/01X-0 on 760706, air operator plunger on relief valve S/N 12 did not move when air pressure was applied. Caused by diaphragm matl deterioration due to exposure to elevated temp. Diaphragms replaced.
PELLETIER, J. P. Vermont Yankee Nuclear Power Corp. 83/02/16
Region 1, Office of Director 3pp 17412:127 24X
Fiche: 50-271, 83/02/16, 8303030045.

8303010436 Forwards LER 83-005/01T-0.
PELLETIER, J. P. Vermont Yankee Nuclear Power Corp. 83/02/18
HAYNES, R. C. Region 1, Office of Director 1p 17343:135 24X
Fiche: 50-271, 83/02/18, 8303010436.

--8303010441 LER 83-005/01T-0 on 830[illegible]3, nitrogen makeup flow found high during normal operation. Caused by ferrous metal particles collected on magnet used to provide valve position indication. Y-strainer installed upstream of valves.
PELLETIER, J. P. Vermont Yankee Nuclear Power Corp. 83/02/18
Region 1, Office of Director 2pp 17343:136 24X
Fiche: 50-271, 83/02/18, 8303010436.

8303010446 Forwards LER 83-004/03L-0.
PELLETIER, J. P. Vermont Yankee Nuclear Power Corp. 83/02/18
HAYNES, R. C. Region 1, Office of Director 1p 17343:053 24X
Fiche: 50-271, 83/02/18, 8303010446.

--8303010455 LER 83-004/03L-0 on 830120, flowmeter on containment air monitor read zero due to leakage past detector O-ring seal into reactor bldg. Cause not determined. O-ring reseated.
PELLETIER, J. P. Vermont Yankee Nuclear Power Corp. 83/02/18
Region 1, Office of Director 1p 17343:054 24X
Fiche: 50-271, 83/02/18, 8303010446.

8303030080 PNO-I-83-012 on 830224, during testing of RCIC sys, motor operated valve in line from condensate storage tank to RCIC pump suction failed to close upon manual command. Caused by mechanical interference from mechanical interlocks.
RAYMOND, W., WIGGINS, J., GALLO, R. Region 1, Office of Director 83/02/28 1p 17412:339 24X Fiche: 50-271, 83/02/28, 8303030080.

8303140442 Forwards LER 83-006/01P-0.
PELLETIER, J. P. Vermont Yankee Nuclear Power Corp. 83/02/28
HAYNES, R. C. Region 1, Office of Director 2pp 17541:176 24X
Fiche: 50-271, 83/02/28, 8303140442.

--8303140454 LER 83-006/01P-0 on 830225, valve V13-18 failed to close during valve lineup for surveillance testing. Caused by cover of starter cubicle binding interlock mechanism between open & closed contactors. Cover screws replaced.
PELLETIER, J. P. Vermont Yankee Nuclear Power Corp. 83/02/28
Region 1, Office of Director 2pp 17541:177 24X
Fiche: 50-271, 83/02/28, 8303140442.

8303140465 Discusses SALP rept for Jul 1980 - June 1981 High level of mgt attention & involvement in decisionmaking process for plant safety noted. Shortcomings observed in emergency preparedness. Assessment revised per 820928 meeting.
HAYNES, R. C. Region 1, Office of Director 83/03/09 CONWAY, W. F. Vermont Yankee Nuclear Power Corp. 3pp 17541:195 24X
Fiche: 50-271, 83/03/09, 8303140465.

--8303140469 SALP rept for Jul 1980 - June 1981. Performance shortcomings observed in area of emergency preparedness. LER synopsis encl.
* Region 1, Office of Director 82/08/23 34pp 17541:198 24X
Fiche: 50-271, 83/03/09, 8303140465.

8303240511 PNO-I-83-021 on 830317, Region I informed util that Hydro-Nuclear Svcs received hydro-lasing pump w/detectable radioactive contamination. Pump unit transferred to Salem on 830318 for decontamination.
WHITE, J. R., GALLO, R. Region 1, Office of Director 83/03/18 1p
17690:315 24X Fiche: 50-271, 83/03/18, 8303240511.

8303290367 PNO-I-83-022 on 830321, secondary containment integrity compromised by technician rendering automatic startup logic for both trains of standby gas treatment sys along w/reactor bldg ventilation isolation logic inoperable.
WIGGINS, J., GALLO, R. Region 1, Office of Director 83/03/23 1p
17716:197 24X Fiche: 50-271, 83/03/23, 8303290367.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp 24X Fiche: 50-000, 83/02/24, 8302250505.

8303040552 Forwards operator licensing & instructor certification exam schedule through 851231 per 830111 Generic Ltr 83-01.
MURPHY, W. P. Vermont Yankee Nuclear Power Corp. 83/03/01
EISENHUT, D. G. Division of Licensing 2pp 17424:126 24X
Fiche: 50-271, 83/03/01, 8303040552.

DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8303140614 Ack receipt of 821122 ltr & payment of civil penalty proposed in NRC 821027 notice of violation. Proposed security program improvements will be examined during future NRC insp. NRC should be notified of future changes.
HAYNES, R. C. Region 1, Office of Director 82/12/30 UDERITZ, R. A.
Public Service Electric & Gas Co. of New Jersey 2pp. 17569:304
24X Fiche: 50-272, 82/12/30, 8303140614

--8303140621 Responds to NRC 821027 ltr, notice of violation & proposed imposition of civil penalty. Addl security mgt improvement programs initiated. Corrective actions withheld (ref 10CFR73.21).
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey.
82/11/22 DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 2pp. 17569:306 24X Fiche: 50-272, 82/12/30, 8303140614.

8303100202 Forwards IE Mgt Meeting Repts 50-272/83-07 & 50-311/83-06 on 830208. Util agreement to conduct Security Measure 1 on second shift confirmed, per 830210 telcon.
STAROSTECKI, R. Division of Project & Resident Programs 83/02/23
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 2pp
17492:027 24X Fiche: 50-272, 83/02/23, 8303100202.

--8303100210 IE Mgt Meeting Repts 50-272/83-07 & 50-311/83-06 on 830208. Major areas discussed: security improvement program & addl measures per Confirmatory Action Ltr 82-22. Safeguards info deleted (ref 10CFR73.21).
NORRHOLM, L. J., TRIPP, L. E. Division of Project & Resident Programs
83/02/15 4pp. 17492:029 24X Fiche: 50-272, 83/02/23, 8303100202.

8303240290 Ack receipt of 821101 transmittal of Rev 7 to security plan. Changes acceptable. Encls to ltr withheld (ref 10CFR73.21).
VARGA, S. A. Operating Reactors Branch 1 83/03/18 UDERITZ, R. A.
Public Service Electric & Gas Co. of New Jersey 2pp. 17694:358
24X Fiche: 50-272, 83/03/18, 8303240290.

8303290437 Forwards response to NRC 830224 ltr requesting corrective action re effectiveness review of nuclear security program. Response withheld.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey
83/03/23 VARGA, S. A. Operating Reactors Branch 1 1p. 17725:361
24X Fiche: 50-272, 83/03/23, 8303290437.

I. Financial information

8303170159 Forwards Annual Financial Repts 1982 & 1983.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/14 SALTZMAN, J.
Assistant Director for State & Licensee Relations 7pp. 17605:183
24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170169 Annual Financial Rept 1982.
SMITH, R. I. Public Service Electric & Gas Co. of New Jersey.
83/02/14 52pp. 17605:191 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170182 Annual Financial Rept 1982.
EVERETT, J. L. Philadelphia Electric Co. 83/03/14 41pp.
17605:243 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170193 Annual Financial Rept 1982.
WEIMER, R. D. Delmarva Power & Light Co. 83/02/04 44pp.
17605:287 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170206 Annual Financial Rept 1982.
FEEHAN, J. D. Atlantic Electric of New Jersey 83/03/14 42pp.
17605:333 24X Fiche: 50-000, 83/03/14, 8303170159.

P. Operating license stage documents & correspondence

8303110006 Addl response to FOIA request for 22 categories of documents. Forwards documents listed in App A. Addl documents undergoing review for safeguards info.
FELTON, J. M. Division of Rules and Records 83/01/31 SHOLLY, S. C.
Union of Concerned Scientists 4pp. 17547:028 24X
Fiche: 50-000, 83/01/31, 8303110006.

8303280331 "Evaluation of Salem Generating Station."
* Institute of Nuclear Power Operations 83/01/31 33pp.
17713:123 24X Fiche: 50-272, 83/01/31, 8303280331.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated
Edison Co. of New York, Inc. 18pp. 17492:033 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303040418 Responds to NRC 830119 & 21 ltrs requesting rationale & justification for protection of proprietary info concerning SER for safety-related equipment. Reasons for declaration are provided in affidavit attached to util 830203 ltr.
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey.
83/02/16 VARGA, S. A. Operating Reactors Branch 1 2pp. 17374:299
24X Fiche: 50-272, 83/02/16, 8303040418.

8303160539 Responds to Franklin Research Ctr request for addl info re NRC Categories 1B, 2A & 2B regarding justification for continued operation not previously submitted. Justification submitted.
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey.
83/02/25 VARGA, S. A. Operating Reactors Branch 1 2pp. 17587:250
24X Fiche: 50-272, 83/02/25, 8303160539.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated
Edison Co. of New York, Inc. 17pp. 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated
Edison Co. of New York, Inc. 5ipp. 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303160065 Forwards 830309 interim draft "Salem Restart Rept."
FISCHER, D. C. Operating Reactors Branch 1 83/03/09 VARGA, S. A.
Operating Reactors Branch 1 1p. 17604:314 24X
Fiche: 50-272, 83/03/09, 8303160065.

--8303160068 Interim draft "Salem Restart Rept."
* Operating Reactors Branch 1 83/03/09 23pp. 17604:315 24X
Fiche: 50-272, 83/03/09, 8303160065.

8303280322 Forwards Amends 51 & 18 to Licenses DPR-70 & DPR-75, respectively, & notice of issuance & availability. Amends delete App B, ETS, re nonradiological water quality-related requirements.
VARGA, S. A. Operating Reactors Branch 1 83/03/11 UDERITZ, R. A.
Public Service Electric & Gas Co. of New Jersey 4pp. 17713:202
24X Fiche: 50-272, 83/03/11, 8303280322.

--8303280324 Amends 51 & 18 to Licenses DPR-70 & DPR-75, respectively, deleting App B, ETS, re nonradiological water quality-related requirements.
VARGA, S. A. Operating Reactors Branch 1 83/03/11 26pp.
17713:206 24X Fiche: 50-272, 83/03/11, 8303280322.

--8303280327 Notice of issuance & availability of Amends 51 & 18 to Licenses DPR-70 & DPR-75, respectively.
VARGA, S. A. Operating Reactors Branch 1 83/03/11 2pp.
17713:232 24X Fiche: 50-272, 83/03/11, 8303280322.

8303290157 Forwards order confirming licensee commitments to implement NUREG-0737 items required for completion on or after 810701, per Generic Ltrs 82-05 & 82-10. Proposed licensee delays acceptable.
VARGA, S. A. Operating Reactors Branch 1 83/03/14 UDERITZ, R. A.
Public Service Electric & Gas Co. of New Jersey 3pp. 17730:221
24X Fiche: 50-272, 83/03/14, 8303290157.

--8303290163 Order confirming licensee commitments to implement NUREG-0737 items required for completion on or after 810701, per Generic Ltrs 82-05 & 82-10.
PURPLE, R. A. Division of Licensing 83/03/14 Public Service
Electric & Gas Co. of New Jersey 8pp. 17730:224 24X
Fiche: 50-272, 83/03/14, 8303290157.

Q. Inspection reports, IE Bulletins & correspondence

8303140614 Ack receipt of 821122 ltr & payment of civil penalty proposed in NRC 821027 notice of violation. Proposed security program improvements will be examined during future NRC insp. NRC should be notified of future changes.
HAYNES, R. C. Region 1, Office of Director 82/12/30 UDERITZ, R. A.
Public Service Electric & Gas Co. of New Jersey 2pp. 17569:304
24X Fiche: 50-272, 82/12/30, 8303140614.

# DOCKETED ITEMS

--8303140621 Responds to NRC 821027 ltr, notice of violation & proposed imposition of civ[illegible]lty. Addl security mgt improvement programs initiate[illegible]tive actions withheld (ref 10CFR73.21).
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 82/11/22. DEYOUNG, R. C. Director's Office. Office of Inspection and Enforcement. 2pp. 17569:306. 24X Fiche: 50-272. 82/12/30. 8303140614.

8303110006 Addl response to FOIA request for 22 categories of documents. Forwards documents listed in App A. Addl documents undergoing review for safeguards info.
FELTON, J. M. Division of Rules and Records. 83/01/31. SHOLLY, S. C. Union of Concerned Scientists. 4pp. 17547:028. 24X Fiche: 50-000. 83/01/31. 8303110006.

--8303110010 Chronological record of inquiry or investigation re potential sabotage of hydrazine tanks for feedwater.
* NRC - No Detailed Affiliation Given. 80/09/15. 2pp. 17547:036. 24X Fiche: 50-000. 83/01/31. 8303110006.

--8303110023 Forwards IE Investigation Rept 50-272/80-22 on 800916-18, 23 & 24.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 80/10/22. THOMPSON, D. Executive Officer for Operations Support. 2pp. 17547:041. 24X Fiche: 50-000. 83/01/31. 8303110006.

--8303110031 IE Investigation Rept 50-272/80-22 on 800916-18, 23 & 24. Major areas investigated: apparent intentional introduction of sodium & chloride into hydrazine injection sys. Chemical analysis confirmed evidence of salt-like substance in tank.
SHEPHERD, R. E., KEIMIG, R. R. Region 1, Philadelphia, Office of the Director. ALLAN, J. M. Public Service Electric & Gas Co. of New Jersey. 80/10/20. 35pp. 17547:043. 24X Fiche: 50-000. 83/01/31. 8303110006.

--8303110081 Investigation status sheets.
* Director's Office, Office of Inspection and Enforcement. 83/01/31. 22pp. 17547:218. 24X Fiche: 50-000. 83/01/31. 8303110006.

8303010646 Forwards IE Insp Repts 50-272/82-36 & 50-311/82-33 on 821222-830125 & notice of violation.
STAROSTECKI, R. Division of Project & Resident Programs. 83/02/15. UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 2pp. 17341:081. 24X Fiche: 50-272. 83/02/15. 8303010646.

--8303010654 Notice of violation from insp on 821222-830125.
* Division of Project & Resident Programs. 83/02/15. 1p. 17341:083. 24X Fiche: 50-272. 83/02/15. 8303010646.

--8303010667 IE Insp Repts 50-272/82-36 & 50-311/82-33 on 821222-830125. Noncompliance noted: daily grab samples not taken & analyzed for gross radioactivity while vent gross radioactivity monitor inoperable.
NORRHOLM, L. J., SUMMERS, R. J., TRIPP, L. E. Division of Project & Resident Programs. 83/02/09. 15pp. 17341:084. 24X Fiche: 50-272. 83/02/15. 8303010646.

8303030644 Forwards IE Insp Repts 50-272/83-04 & 50-311/83-03 on 830124-28. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/02/16. UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 2pp. 17410:354. 24X Fiche: 50-272. 83/02/16. 8303030644.

--8303030662 IE Insp Repts 50-272/83-04 & 50-311/83-03 on 830124-28. No noncompliance noted. Major areas inspected: procedure review, test witnessing & results evaluation of local leak rate testing & review of preparation & schedule for next test.
PULLANI, S. V., NORRHOLM, L. J. Division of Engineering & Technical Programs. 83/02/15. 6pp. 17410:356. 24X Fiche: 50-272. 83/02/16. 8303030644.

8303030156 Forwards IE Insp Repts 50-272/83-05 & 50-311/83-04 on 830124-28. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/02/18. UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 2pp. 17412:342. 24X Fiche: 50-272. 83/02/18. 8303030156.

--8303030166 IE Insp Repts 50-272/83-05 & 50-311/83-04 on 830124-28. No noncompliance noted. Major areas inspected: in-plant radiation protection implementation, respiratory protection program, personnel selection & training & exposure control.
ROWE, C. A., SHANBAKY, M. Region 1, Office of Director. 83/02/18. 5pp. 17412:344. 24X Fiche: 50-272. 83/02/18. 8303030156.

8303100202 Forwards IE Mgt Meeting Repts 50-272/83-07 & 50-311/83-06 on 830208. Util agreement to conduct Security Measure 1 on second shift confirmed per 830210 telcon.
STAROSTECKI, R. Division of Project & Resident Programs. 83/02/23. UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 2pp. 17492:027. 24X Fiche: 50-272. 83/02/23. 8303100202.

--8303100210 IE Mgt Meeting Repts 50-272/83-07 & 50-311/83-06 on 830208. Major areas discussed: security improvement program & addl measures per Confirmatory Action Ltr 82-22. Safeguards info deleted (ref 10CFR73.21).
NORRHOLM, L. J., TRIPP, L. E. Division of Project & Resident Programs. 83/02/15. 4pp. 17492:029. 24X Fiche: 50-272. 83/02/23. 8303100202.

8303100319 Forwards IE Insp Rept 50-272/82-34 on 821228-29. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/02/23. UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 2pp. 17489:158. 24X Fiche: 50-272. 83/02/23. 8303100319.

--8303100322 IE Insp Rept 50-272/82-34 on 821228-29. No noncompliance noted. Major areas inspected: licensee activities to analyze failure mechanism & repair or replace corroded portions of piping sys.
REYNOLDS, S. D., DURR, J. Region 1, Office of Director. 83/02/17. 8pp. 17489:160. 24X Fiche: 50-272. 83/02/23. 8303100319.

8303100336 Forwards IE Insp Rept 50-272/83-02 on 830118-21 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/02/23. UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 2pp. 17490:356. 24X Fiche: 50-272. 83/02/23. 8303100336.

--8303100339 Notice of violation from insp on 830118-21.
* Division of Engineering & Technical Programs. 83/02/25. 1p. 17490:358. 24X Fiche: 50-272. 83/02/23. 8303100336.

--8303100344 IE Insp Rept 50-272/83-02 on 830118-21. Noncompliance noted: performance of liquid penetrant exams by uncertified technician.
MCBREARTY, R. A., NARROW, L. Region 1, Office of Director. 83/02/10. 7pp. 17490:359. 24X Fiche: 50-272. 83/02/23. 8303100336.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521:001. 24X Fiche: 50-000. 83/02/25. 8212060367.

8307140438 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." No Bunker-Ramo electrical penetration used or planned for use at facilities.
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey. 83/03/01. HAYNES, R. C. Region 1, Office of Director. 2pp. 17737:057. 24X Fiche: 50-272. 83/03/01. 8303140438.

8303160429 Forwards IE Insp Repts 50-272/83-01 & 50-311/83-01 on 830103-07 & IE Mgt Meeting Repts 50-272/83-10 & 50-311/83-09 on 830215. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/04. UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 3pp. 17592:287. 24X Fiche: 50-272. 83/03/04. 8303160429.

--8303160431 IE Insp Repts 50-272/83-01 & 50-311/83-01 on 830103-07. No noncompliance noted. Major areas inspected: licensee action on previous insp findings, QA organizations, audits & QC.
MEYER, G. W., BISSETT, P. Region 1, Office of Director. CAPHTON, D. L. Division of Engineering & Technical Programs. 83/02/17. 9pp. 17592:290. 24X Fiche: 50-272. 83/03/04. 8303160429.

--8303160433 IE Mgt Meeting Repts 50-272/83-10 & 50-311/83-09 on 830215. Major areas discussed: questionable calibr of test meter, 821019 notice of violation item & apparent inaccurate util 821119 response.
MEYER, G. W. Region 1, Office of Director. BETTENHAUSEN, L. Division of Engineering & Technical Programs. 83/02/16. 4pp. 17592:299. 24X Fiche: 50-272. 83/03/04. 8303160429.

8303240521 Forwards IE Insp Repts 50-272/83-09 & 50-311/82-08 conducted by State of WA Dept of Social & Health Svcs on 830117 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/10. UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 2pp. 17690:338. 24X Fiche: 50-272. 83/03/10. 8303240521.

--8303240527 Notice of violation from insp on 830117.
* Region 1, Office of Director. 83/03/10. 1p. 17690:340. 24X Fiche: 50-272. 83/03/10. 8303240521.

--8303240535 IE Insp Repts 50-272/83-09 & 50-311/83-08 conducted by State of WA Dept of Social & Health Svcs on 830117. Noncompliance noted: bracing not provided to prevent shift of lading.
CLEMONS, P., SHANBAKY, M. Region 1, Office of Director. 83/03/04. 4pp. 17690:341. 24X Fiche: 50-272. 83/03/10. 8303240521.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11 Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303280258 Forwards IE Insp Repts 50-272/82-33 & 50-311/82-31 on 821109-1221.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/14.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 2pp.
17706:211. 24X Fiche: 50-272, 83/03/14, 8303280258.

--8303280267 IE Insp Repts 50-272/82-33 & 50-311/82-31 on 821109-1221. Noncompliance noted: limiting condition for operation for containment isolation instrumentation exceeded.
NORRHOLM, L. J., SUMMERS, R. J., WHITE, J. R. Region 1, Office of Director. 83/02/23. 17pp. 17706:213. 24X Fiche: 50-272, 83/03/14, 8303280258.

8303170250 Advises that IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal," addressed in 830301, 08, 14 & 15 submittals. Affidavit encl.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 83/03/15. HAYNES, R. C. Region 1, Office of Director. 4pp. 17606:137. 24X Fiche: 50-272, 83/03/15, 8303170250.

8303250082 Informs that util responded to 830222 & 25 reactor trip breaker failures & IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal," in 830301, 08, 14 & 15 ltrs. Affidavit encl.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 83/03/15. HAYNES, R. C. Region 1, Office of Director. 4pp. 17693:274. 24X Fiche: 50-272, 83/03/15, 8303250082.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303230229 EN-83-018 on 830324, notice of violation & proposed imposition of civil penalty in amount of $20,000 will be issued re inoperability of containment gaseous, particulate & iodine radiation monitor.
BARBER, G., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 83/03/21. 1p. 17661:238. 24X Fiche: 50-272, 83/03/21, 8303230229.

8303300468 Ack receipt of 830204 & 0309 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-272/82-28.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/24.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 1p. 17731:106. 24X Fiche: 50-272, 83/03/24, 8303300468.

--8303300473 Responds to NRC 830107 ltr re violations noted in IE Insp Rept 50-272/82-28. Corrective actions related chemistry procedures for Units 1 & 2 will be reviewed & revised by 830501. Revised effluent monitoring program audited.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 83/02/04. HAYNES, R. C. Region 1, Office of Director. 20pp. 17731:107. 24X Fiche: 50-272, 83/03/24, 8303300468.

--8303300477 Responds to NRC 830228 telcon re violations noted in IE Insp Rept 50-272/82-28. Corrective actions Rev 5 to Procedure PD-3.9.016 re gaseous radwaste release calculations reviewed & approved at 830115 operations review committee meeting.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 83/03/09. HAYNES, R. C. Region 1, Office of Director. 2pp. 17731:127. 24X Fiche: 50-272, 83/03/24, 8303300468.

R. Periodic operating reports & related correspondence

8303040390 Forwards NPDES discharge monitoring repts for Jan 1983.
MILLER, L. K. Public Service Electric & Gas Co. of New Jersey. 83/02/10. BAKER, R. A. Environmental Protection Agency. 2pp. 17369:156. 24X Fiche: 50-272, 83/02/10, 8303040390.

--8303040634 NPDES discharge monitoring rept for Jan 1983.
MILLER, L. K. Public Service Electric & Gas Co. of New Jersey. 83/02/10. 19pp. 17369:158. 24X Fiche: 50-272, 83/02/10, 8303040390.

8303150284 Forwards tabulated rept of personnel exposure during 1982 according to work & job functions. Rept labeled Unit 0 represents work common to both units.
ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey. 83/02/23. HAYNES, R. C. Region 1, Office of Director. 1p. 17567:047. 24X Fiche: 50-272, 83/02/23, 8303150284.

--8303150290 Rept of personnel exposure during 1982.
* Public Service Electric & Gas Co. of New Jersey. 83/02/23. 6pp. 17567:048. 24X Fiche: 50-272, 83/02/23, 8303150284.

8303280279 Forwards "Semiannual Radioactive Effluent Release Rept, Jul-Dec 1982."
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey. 83/03/03. HAYNES, R. C. Region 1, Office of Director. 2pp. 17706:111. 24X Fiche: 50-272, 83/03/03, 8303280279.

--8303280286 "Semiannual Radioactive Effluent Release Rept, Jul-Dec 1982." * Public Service Electric & Gas Co. of New Jersey. RERR-131. 83/03/31. 46pp. 17706:113. 24X Fiche: 50-272, 83/03/03, 8303280279.

8303170494 Forwards monthly operating rept for Feb 1983.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey. 83/03/10. Director's Office, Office of Inspection and Enforcement. 1p. 17611:019. 24X Fiche: 50-272, 83/03/10, 8303170494.

--8303170499 Monthly operating rept for Feb 1983.
MILLER, L. K. Public Service Electric & Gas Co. of New Jersey. 83/03/10. 31pp. 17611:020. 24X Fiche: 50-272, 83/03/10, 8303170494.

S. Reportable occurrences, LERs & related correspondence

8303110006 Addl response to FOIA request for 22 categories of documents. Forwards documents listed in App A. Addl documents undergoing review for safeguards info.
FELTON, J. M. Division of Rules and Records. 83/01/31. SHOLLY, S. C. Union of Concerned Scientists. 4pp. 17547:028. 24X Fiche: 50-000, 83/01/31, 8303110006.

--8303110013 Discusses 800910 potential act of sabotage. Hydrazine injected into steam generator due to plant trip. Personnel advised by anonymous telcon that sodium had been added to hydrazine tank injection sys.
DEVLIN, J. W. NRC - No Detailed Affiliation Given. 80/09/13. NRC - No Detailed Affiliation Given. 1p. 17547:038. 24X Fiche: 50-000, 83/01/31, 8303110006.

--8303110017 Forwards rept re possible act to commit industrial sabotage.
LIBRIZZI, F. P. Public Service Electric & Gas Co. of New Jersey. 80/09/05. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 1p. 17547:039. 24X Fiche: 50-000, 83/01/31, 8303110006.

--8303110021 RO on 800912, sample analysis taken from hydrazine addition tank indicated sodium chloride in tank. Anonymous telcon indicated salt may have been added prior to labor strike by unknown persons.
* Public Service Electric & Gas Co. of New Jersey. 80/09/25. 1p. 17547:040. 24X Fiche: 50-000, 83/01/31, 8303110006.

--8303110096 Discusses 820903 incident involving unplanned release of radioactive gas. Inquiry conducted to determine if manual drain valve intentionally opened. Licensee assesses that valve accidently opened.
CHRISTOPHER, R. Region 1, Office of Director. 83/01/31. Region 1, Office of Director. 40pp. 17547:315. 24X Fiche: 50-000, 83/01/31, 8303110006.

8303030276 RO on 830210, tagging error discovered on circuit breakers for accumulator motor operated valves. Associated tags verified for proper placement. Addl verification of safety significant tagging will be performed.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 83/02/15. HAYNES, R. C. Region 1, Office of Director. 2pp. 17410:352. 24X Fiche: 50-272, 83/02/15, 8303030276.

8303030118 Forwards LER 83-003/04L-0. Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey. 83/02/16. HAYNES, R. C. Region 1, Office of Director. 4pp. 17412:133. 24X Fiche: 50-272, 83/02/16, 8303030118.

--8303030126 LER 83-003/04L-0 on 830121, during commencement of refueling shutdown for Unit 2, Unit 1 restart delayed approx 7 wks. Caused by problems w/steam generator nozzle dams & degradation of welds in svc water piping.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey. 83/02/09. Region 1, Office of Director. 1p. 17412:137. 24X Fiche: 50-272, 83/02/16, 8303030118.

8303030292 Forwards LER 83-004/03L-0. Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
83/02/18. HAYNES, R. C. Region 1, Office of Director. 3pp.
17410:149. 24X Fiche: 50-272, 83/02/18, 8303030292.

--8303030308 LER 83-004/03L-0, on 830124, equipment operator discovered leak on diesel generator 1B jacket water sys. Caused by cracked piping nipple due to personnel standing on jacket water sys piping. Cracked nipple replaced.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey.
83/02/17. Region 1, Office of Director. 1p. 17410:152. 24X
Fiche: 50-272, 83/02/18, 8303030292.

8303030257 Forwards LER 83-005/03L-0. Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
83/02/22. HAYNES, R. C. Region 1, Office of Director. 4pp.
17410:196. 24X Fiche: 50-272, 83/02/22, 8303030257.

--8303030272 LER 83-005/03L-0, on 830121, RHR sys automatic isolation function not tested prior to placing RHR sys in operation. Caused by procedure problems & personnel inexperience. Procedures revised.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey.
83/02/17. Region 1, Office of Director. 1p. 17410:200. 24X
Fiche: 50-272, 83/02/22, 8303030257.

8303110304 Discusses attempts to reduce reporting of occurrences involving routine entry into Tech Spec action statements during expected plant transients. List of specific action statements failing in category encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
83/02/22. HAYNES, R. C. Region 1, Office of Director. 4pp.
17520:072. 24X Fiche: 50-272, 83/02/22, 8303110304.

8303090238 Forwards LER 83-007/03L-0. Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
83/02/24. HAYNES, R. C. Region 1, Office of Director. 3pp.
17492:105. 24X Fiche: 50-272, 83/02/24, 8303090238.

--8303090247 LER 83-007/03L-0, on 830129, control room operator discovered low flow through number 14 reactor coolant loop resistance thermometer detector bypass. Caused by obstruction in hot leg flowpath. Hot leg cycled & bypass flow restored to normal.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey.
83/02/23. Region 1, Office of Director. 1p. 17492:108. 24X
Fiche: 50-272, 83/02/24, 8303090238.

8303010680 LER 83-011/01P-0, on 830225, reactor trip breakers failed to open in response to reactor trip signal. Caused by low-low water level in steam generator 12. Reactor manually tripped & being maintained in Mode 3.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
83/02/25. HAYNES, R. C. Region 1, Office of Director. 1p.
17341:105. 24X Fiche: 50-272, 83/02/25, 8303010680.

8303030025 PNO-I-83-011A, on 830225, reactor trip breakers failed to open on trip signal. Caused by binding in vertical latch bar of undervoltage relay due to excessive friction. Investigation continuing.
SUMMERS, R., JACOBS, R., TRIPP, L. Region 1, Office of Director.
83/02/25. 1p. 17412:197. 24X Fiche: 50-272, 83/02/25, 8303030025.

8303030027 PNO-I-83-011, on 830225, reactor trip breakers failed to open on trip signal. Caused by excessive friction. Westinghouse representative on site to analyze malfunction.
SUMMERS, R., JACOBS, R., TRIPP, L. Region 1, Office of Director.
83/02/25. 1p. 17412:196. 24X Fiche: 50-272, 83/02/25, 8303030027.

8303090175 Forwards LER 83-006/03L-0. Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
83/02/25. HAYNES, R. C. Region 1, Office of Director. 5pp.
17470:354. 24X Fiche: 50-272, 83/02/25, 8303090175.

--8303090185 LER 83-006/03L-0, on 830126 & 28 nonseismically qualified components & power boxes discovered installed in dc control power feeds to emergency diesel generators. Caused by personnel oversight. Power box components replaced.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey.
83/02/23. Region 1, Office of Director. 1p. 17470:359. 24X
Fiche: 50-272, 83/02/25, 8303090175.

8303030060 Telecopy message of LER 83-012/01P-0 on 830222, both reactor trip breakers failed to open. Cause not yet determined. Investigation underway.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
83/02/28. HAYNES, R. C. Region 1, Office of Director. 1p.
17413:232. 24X Fiche: 50-272, 83/02/28, 8303030060.

8303140576 Forwards LER 83-013/99T-0. Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
83/03/02. HAYNES, R. C. Region 1, Office of Director. 4pp.
17534:005. 24X Fiche: 50-272, 83/03/02, 8303140576.

--8303140583 LER 83-013/99T-0, on 830215, calculated moderator temp coefficient (MTC) value for all control rods withdrawn found more positive than Tech Spec allowance but within expected deviation. Limitation on withdrawal will be maintained.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey.
83/03/01. Region 1, Office of Director. 1p. 17534:009. 24X
Fiche: 50-272, 83/03/02, 8303140576.

8303150620 Board Notification 83-26: forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys. Info may affect conclusions re probability of/corrective measures for ATWS.
EISENHUT, D. G. Division of Licensing. 83/03/03. PALLADINO, N., GILINSKY, V., AHEARNE, J. Commissioners. 24pp. 17584:097. 24X
Fiche: 50-000, 83/03/03, 8303150620.

--8303150642 Documents actions initiated by Westinghouse Owners Group (WOG) Regulatory Response Group re 830225 failure of reactor trip breakers to open on automatic trip signal & effective generic measures to be taken.
SHEPPARD, J. J. Westinghouse Operating Plants Owners Group.
SHEPPARD, J. J. Carolina Power & Light Co. 83/03/01. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17584:168.
24X Fiche: 50-000, 83/03/03, 8303150620.

--8303150646 RO on 830222 & 25, reactor trip breakers failed to open on receipt of trip signal from reactor protection sys. Caused by lack of proper latch lubrication. Corrective actions include Tech Spec review & new procedure development.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey.
83/03/01. EISENHUT, D. G. Division of Licensing. 5pp. 17584:170.
24X Fiche: 50-000, 83/03/03, 8303150620.

8303140545 Forwards supplemental LER 82-081/01X-1. Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
83/03/04. HAYNES, R. C. Region 1, Office of Director. 3pp.
17533:357. 24X Fiche: 50-272, 83/03/04, 8303140545.

--8303140568 Supplemental LER 82-081/01X-1 on 821104, 16 1,000-kip steam generator snubbers found out of spec on bleed test & six snubbers failed acceleration test. Caused by flattened piston seal rubber matl due to aging. Seals rebuilt.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey.
83/03/03. Region 1, Office of Director. 1p. 17533:360. 24X
Fiche: 50-272, 83/03/04, 8303140545.

8303110128 Staff requirements memo re 830302 briefing in Washington, DC on reactor trip breaker failure & corrective actions.
CHILK, S. J. Office of the Secretary of the Commission. 83/03/07.
DIRCKS, W. J. Office of the Executive Director for Operations. 2pp.
17526:080. 24X Fiche: 50-272, 83/03/07, 8303110128.

8303160189 Confirms 830225 telcon agreement that Unit 1 will not be taken critical w/o prior NRC approval. Agreement will be superseded when issues associated w/830222-25 malfunction of automatic scram sys resolved.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/07.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 2pp.
17596:281. 24X Fiche: 50-272, 83/03/07, 8303160189.

8303160234 Supplis 830301 ltr providing documentation of investigation & proposed corrective actions re 830222 & 25 reactor trip breaker failures. Formalized post-reactor trip/safety injection review procedure established.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey.
83/03/08. STAROSTECKI, R. Division of Project & Resident Programs.
5pp. 17596:350. 24X Fiche: 50-272, 83/03/08, 8303160234.

8303180361 Forwards LER 83-010/03L-0. Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
83/03/08. HAYNES, R. C. Region 1, Office of Director. 3pp.
17620:077. 24X Fiche: 50-272, 83/03/08, 8303180361.

--8303180368 LER 83-010/03L-0: from 821016-830205, during testing of Type B & C components, three containment isolation valves exhibited leakage rates in excess of test equipment range. Valves 1CC215 & 1VCB restroked. Valve 14GB4 reworked.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey.
83/03/07. Region 1, Office of Director. 1p. 17620:080. 24X
Fiche: 50-272, 83/03/08, 8303180361.

8303180305 Forwards LER 83-014/03L-0. Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
83/03/10. HAYNES, R. C. Region 1, Office of Director. 3pp.
17619:359. 24X Fiche: 50-272, 83/03/10, 8303180305.

--8303180314 LER 83-014/03L-0, on 830209, auxiliary alarm typewriter failed. Caused by failed circuit board in auxiliary annunciator sys. Board replaced & separate annunciators for sump sys being installed.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey.
83/03/07. Region 1, Office of Director. 1p. 17619:362. 24X
Fiche: 50-272, 83/03/10, 8303180305.

8303210522 Forwards LER 83-016/03L-0. Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
83/03/10. HAYNES, R. C. Region 1, Office of Director. 3pp.
17632:286. 24X Fiche: 50-272, 83/03/10, 8303210522.

--8303210530 LER 83-016/03L-0 on 830211, containment air particulate monitor indicated off-scale low. Caused by signal lead to scintillation detector open in detector cable connector. Cable apparently strained during maint. Connector replaced.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey.
83/03/07. Region 1, Office of Director. 1p. 17632:289. 24X Fiche: 50-272, 83/03/10, 8303210522.

8303230320 Provides interim draft rept on current status of evaluation of failure to scram automatically events. NRC to meet w/util on 830310 to discuss draft NRC status rept.
DIRCKS, W. J. Office of the Executive Director for Operations.
SECY-83-098. 83/03/10. 25pp. 17677:331. 24X Fiche: 50-272, 83/03/10, 8303230320.

8303180319 Forwards LER 83-011/01T-0. Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
83/03/11. HAYNES, R. C. Region 1, Office of Director. 2pp.
17619:343. 24X Fiche: 50-272, 83/03/11, 8303180319.

--8303180324 LER 83-011/01T-0 on 830225, reactor trip breakers failed to open automatically on receipt of trip signal. Cause not stated. Supplemental rept will be submitted.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey.
83/03/10. Region 1, Office of Director. 1p. 17619:345. 24X Fiche: 50-272, 83/03/11, 8303180319.

8303180419 Forwards LER 83-015/03L-0. Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
83/03/11. HAYNES, R. C. Region 1, Office of Director. 4pp.
17622:064. 24X Fiche: 50-272, 83/03/11, 8303180419.

--8303180420 LER 83-015/03L-0 on 830210, during surveillance testing of diesel generator 1A, jacket water high temp alarm received. Caused by missing handwheel on flow transmitter high side isolation valve. Handwheel replaced.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey.
83/03/10. Region 1, Office of Director. 1p. 17622:068. 24X Fiche: 50-272, 83/03/11, 8303180419.

8303180423 Forwards LER 83-012/01T-0. Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
83/03/11. HAYNES, R. C. Region 1, Office of Director. 2pp.
17622:073. 24X Fiche: 50-272, 83/03/11, 8303180423.

--8303180425 LER 83-012/01T-0 on 830222, during startup, reactor manually tripped. Caused by rapidly decreasing steam generator levels. Manual trip obscured failure of trip breakers to open automatically. Plant cooldown commenced.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey.
83/03/10. Region 1, Office of Director. 1p. 17622:075. 24X Fiche: 50-272, 83/03/11, 8303180423.

8303210627 Forwards LER 83-017/03L-0. Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
83/03/11. HAYNES, R. C. Region 1, Office of Director. 3pp.
17636:203. 24X Fiche: 50-272, 83/03/11, 8303210627.

--8303210633 LER 83-017/03L-0 on 830215, containment sump pumps 11 & 12 found running continuously. To prevent damage, pumps de-energized & tagged out. Caused by level detector LD-7749 malfunctioning due to binding in magnetic sleeve assembly.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey.
83/03/07. Region 1, Office of Director. 1p. 17636:206. 24X Fiche: 50-272, 83/03/11, 8303210627.

8303210160 Summary of 830228 meeting w/util, GE, Westinghouse & Westinghouse Owners Group re failure of both trip breakers to open following receipt of trip signal from automatic protection sys.
FISCHER, D. Operating Reactors Branch 1. 83/03/14. Operating Reactors Branch 1. 22pp. 17659:126. 24X Fiche: 50-272, 83/03/14, 8303210160.

8303230332 Provides rept on current status of NRC evaluation of 830222 & 25 automatic scram events & NRC action plan for authorizing restart. Show cause order should be issued.
DIRCKS, W. J. Office of the Executive Director for Operations.
SECY-83-098A. 83/03/14. 37pp. 17675:020. 24X Fiche: 50-272, 83/03/14, 8303230332.

8303170122 Submits info inadvertently omitted from 830314 ltr describing corrective actions re 830222 & 25 reactor trip breaker failures. Nonsafety-related work orders written since issuance of master equipment list under review.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey.
83/03/15. EISENHUT, D. G. Division of Licensing. 1p. 17609:025. 24X Fiche: 50-272, 83/03/15, 8303170122.

8303170250 Advises that IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal," addressed in 830301, 08, 14 & 15 submittals.
Affidavit encl.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey.
83/03/15. HAYNES, R. C. Region 1, Office of Director. 4pp.
17606:137. 24X Fiche: 50-272, 83/03/15, 8303170250.

8303160730 Forwards TA Rehm memos listing & appending 100 info items re facility event provided to Congressman Udell. Requests placement in PDR.
SCOTT, R. S. Document Management Branch. 83/03/16. Public Document Branch. 1p. 17611:288. 24X Fiche: 50-272, 83/03/16, 8303160730.

--8303160738 Forwards documents pursuant to Congressman Udell request re facility event. Listed draft documents & documents en route from Region I omitted.
REHM, T. A. Office of the Executive Director for Operations.
83/03/14. KAMMERER, C. Office of Congressional Affairs. 1p.
17611:289. 24X Fiche: 50-272, 83/03/16, 8303160730.

--8303160745 Forwards addl documents re facility event pursuant to Congressman Udell 830309 request.
REHM, T. A. Office of the Executive Director for Operations.
83/03/15. KAMMERER, C. Office of Congressional Affairs. 1000pp.
17611:290. 24X Fiche: 50-272, 83/03/16, 8303160730.

8303240157 Forwards NUREG-0977, "NRC Fact-Finding Rept on ATWS Event at Salem on 830225."
MATTSON, R. J. Salem Generic Implications Task Force. 83/03/18.
DENTON, H. R., CASE, E., VOLLMER, R. Office of Nuclear Reactor Regulation, Director. 72pp. 17696:257. 24X Fiche: 50-272, 83/03/18, 8303240157.

8303290144 Submits updated info re investigation of reactor trip switchgear malfunctions. Technical bulletin recommending independent testing of undervoltage & shunt trip attachments for manual reactor trip expected by 830325.
RAHE, E. P. Westinghouse Electric Corp. 83/03/22. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 18pp. 17730:252. 24X Fiche: 50-272, 83/03/22, 8303290144.

8303290802 Notification of 830401 meeting w/util group on ATWS to discuss implications of Salem incident on proposed rule PRM-50-29.
ERNST, M. L. Division of Risk Analysis. 83/03/23. BAER, R. Office of Nuclear Regulatory Research, Director. BARANOWSKY, P., BERNERO, R. Division of Risk Analysis. 2pp. 17748:093. 24X Fiche: 50-272, 83/03/23, 8303290802.

8303310358 NRC FACT-FINDING TASK FORCE REPORT ON THE ATWS EVENT AT SALEM NUCLEAR GENERATING STATION, UNIT 1, ON FEBRUARY 22 AND 25, 1983.
* Region 1, Office of Director. NUREG-0977. 83/03/31. 731pp.
Available at NRC $13.00. 17799:099. 24X Fiche: 50-272, 83/03/31, 8303310358.

T. Hearing transcripts on non-antitrust matters

8303160627 Transcript of 830302 public meeting in Washington, DC re failure of reactor to trip. Pp 1-124.
* Commissioners. 83/03/02. 169pp. 17603:290. 24X Fiche: 50-272, 83/03/02, 8303160627.

8303230138 Transcript of 830315 briefing in Washington, DC re reactor trip breaker failures at facility. Pp 1-116. V Gilinsky 830315 memo to Commission & viewgraphs encl.
* Commissioners. 83/03/15. 165pp. 17689:262. 24X Fiche: 50-272, 83/03/15, 8303230138.

8303290399 Transcript of 830324 meeting in Washington, DC re briefing on plant post-trip rept. Pp 1-89. Twelve viewgraphs encl.
* Commissioners. 83/03/24. 104pp. 17727:103. 24X Fiche: 50-272, 83/03/24, 8303290399.

V. Operator Examinations

8303090178 Forwards projected schedule for operator licensing exam/instructor certificate exam site visits, in response to Generic Ltr 83-01.
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey.
83/02/23. VARGA, S. A. Operating Reactors Branch 1. 2pp. 17469:361. 24X Fiche: 50-272, 83/02/23, 8303090178.

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." 8vc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8303040409 Forwards IE Insp Repts 50-275/83-03 & 50-323/83-02 on 830102-29. No noncompliance noted.
BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs 83/02/11 CRANE, P. A. Pacific Gas & Electric Co. 2pp. 17374:301. 24X Fiche: 50-275, 83/02/11, 8303040409.

--8303040421 IE Insp Repts 50-275/83-03 & 50-323/83-02 on 830102-29. No noncompliance noted. Major areas inspected: plant operations, surveillance testing, physical security, maint, LER followup & TMI Action Plan Item II.E.4.2.
CARLSON, J. D., MENDONCA, M. M., KIRSCH, D. F. Division of Resident, Reactor Project & Engineering Programs 83/02/10 4pp. 17374:303. 24X Fiche: 50-275, 83/02/11, 8303040409.

8303010419 Ack receipt of 830211 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-275/82-40.
BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs 83/02/22 CRANE, P. A. Pacific Gas & Electric Co. 1p. 17343:159. 24X Fiche: 50-275, 83/02/22, 8303010419.

--8303010421 Responds to NRC 830112 ltr re violations noted in IE Insp Rept 50-275/82-40. Corrective actions: Procedure M-17 for functional test of emergency dc lighting sys & communication sys revised & missing fire extinguishers replaced.
CRANE, P. A. Pacific Gas & Electric Co. 83/02/11 ENGELKEN, R. H. Region 5, Office of Director 3pp. 17343:160. 24X Fiche: 50-275, 83/02/22, 8303010419.

8303010285 Forwards License Amend Request 83-02 re security plan, Class III amend fee encl. Request withheld (ref 10CFR73.21).
CRANE, P. A. Pacific Gas & Electric Co. 83/02/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 17335:198. 24X Fiche: 50-275, 83/02/25, 8303010285.

8303080521 Advises that util will submit rept by 830515 documenting previous exemptions & justifying differences between existing or proposed fire protection features & features specified in Sections III.G, III.J, III.L & III.O of App R.
CRANE, P. A. Pacific Gas & Electric Co. 83/03/02 EISENHUT, D. G. Division of Licensing 2pp. 17450:302. 24X Fiche: 50-275, 83/03/02, 8303080521.

8303180618 Forwards exemption & Amend 4 to License DPR-76. Exemption & amend grant temporary relief from requirements of portions of 10CFR73 re maintaining approved physical security plan.
EISENHUT, D. G. Division of Licensing 83/03/11 CRANE, P. A. Pacific Gas & Electric Co. 3pp. 17626:335. 24X Fiche: 50-275, 83/03/11, 8303180618.

--8303180623 Exemption from requirements of certain portions of 10CFR73 re maintaining approved physical security plan.
EISENHUT, D. G. Division of Licensing 83/03/11 Pacific Gas & Electric Co. 5pp. 17626:338. 24X Fiche: 50-275, 83/03/11, 8303180618.

--8303180629 Amend 4 to License DPR-76, granting temporary exemption from requirements of portions of 10CFR73 re maintaining approved physical security plan.
EISENHUT, D. G. Division of Licensing 83/03/11 3pp. 17626:343. 24X Fiche: 50-275, 83/03/11, 8303180618.

8303210254 Declines NRC 821228 invitation to participate in pilot in-plant drill program. Participation not feasible w/scheduled workload & existing staffing levels.
SCHUYLER, J. O. Pacific Gas & Electric Co. 83/03/14 EISENHUT, D. G. Division of Licensing 2pp. 17632:175. 24X Fiche: 50-275, 83/03/14, 8303210254.

8303300691 Releases public version of updates to detailed emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 83/03/28 Document Management Branch 1p. 17764:207. 24X Fiche: 50-275, 83/03/28, 8303300691.

--8303300697 Forwards public version of updates to detailed emergency plan implementing procedures, including Procedures EP M-6 re nonradiological fire, EP OR-1 re offsite support & EP G-2 re onsite emergency organization.
CRANE, P. A. Pacific Gas & Electric Co. 83/02/10 ENGELKEN, R. H. Region 5, Office of Director 2pp. 17764:208. 24X Fiche: 50-275, 83/03/28, 83033000691.

--8303300702 Public version of updates to detailed emergency plan implementing procedures, including Procedures EP M-6 re nonradiological fire, EP OR-1 re offsite support & EP G-2 re onsite emergency organization.
* Pacific Gas & Electric Co. 83/02/04 60pp. 17764:210. 24X Fiche: 50-275, 83/03/28, 8303300691.

G. Adjudicatory correspondence

8303030462 Advises that LJ Chandler will represent NRC at 830316 oral argument, per ASLAB 830223 order.
CHANDLER, L. J. Hearing Branch 2 83/03/02 SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 1p. 17409:263. 24X Fiche: 50-275, 83/03/02, 8303030462.

8303080061 Advises that J Reynolds will represent Joint Intervenors at 830316 oral argument.
REYNOLDS, J. R. Center for Law in the Public Interest REYNOLDS, J. R. Joint Intervenors-Diablo Canyon 83/03/04 MOORE, T., REED, W., BUCK, J. H. Atomic Safety and Licensing Appeal Panel 1p. 17452:173. 24X Fiche: 50-275, 83/03/04, 8303080061.

8303080073 Advises that MJ Strumwasser will represent State of CA at 830316 oral argument.
STRUMWASSER, M. California, State of 83/03/04 SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 1p. 17456:262. 24X Fiche: 50-275, 83/03/04, 8303080073.

8303080114 Advises that B Norton will present argument in response to ASLAB 830223 order.
CRANE, P. A. Pacific Gas & Electric Co. 83/03/04 MOORE, T. S. Atomic Safety and Licensing Appeal Panel 1p. 17458:245. 24X Fiche: 50-275, 83/03/04, 8303080114.

8303110200 Order rescheduling 830316 oral arguments on appeals from ASLB 820831 initial decision & two motions to reopen record, for 830414, in Bethesda, MD.
TOMPKINS, B. A. Atomic Safety and Licensing Appeal Panel 83/03/09 2pp. 17517:353. 24X Fiche: 50-275, 83/03/09, 8303110200.

8303290296 Notice of change of address, effective 830321. Certificate of Svc encl.
NORTON, B. Pacific Gas & Electric Co. NORTON, B. Norton, Burke, Berry & French 83/03/24 3pp. 17716:178. 24X Fiche: 50-275, 83/03/24, 8303290296.

H. General correspondence

8303090258 Requests that MJ Strumwasser be placed on distribution list & HH Brown & BS Georgiou be deleted from list, per 830128 notice of substitution.
CRANE, P. A. Pacific Gas & Electric Co. 83/02/07 COOPER, W. E. Teledyne Engineering Services 1p. 17473:345. 24X Fiche: 50-275, 83/02/07, 8303090258.

8303040137 Responds to concerns expressed in 821224 ltr re discharge of radiation into atmosphere & radioactive releases to Pacific Ocean.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 83/02/18 EVANS, M. California, State of 17pp. 17425:057. 24X Fiche: 50-275, 83/02/18, 8303040137.

--8303040151 Requests further response to concerns re discharge of radiation into atmosphere & radioactive releases to Pacific Ocean.
EVANS, M. California, State of 82/12/24 PALLADINO, N. J. Commissioners 3pp. 17425:070. 24X Fiche: 50-275, 83/02/18, 8303040137.

8303090254 Requests that RB Hubbard be reinstated on independent design verification program distribution list.
STRUMWASSER, M. California, State of 83/02/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ENGELKEN, R. H. Region 5, Office of Director MANEATIS, G. A. Pacific Gas & Electric Co. 2pp. 17473:360. 24X Fiche: 50-275, 83/02/22, 8303090254.

8303300368 Forwards summary of allegations received from anonymous plant personnel re containment structure tilting & classification of platform, on behalf of Joint Intervenors.
FLEISCHAKER, D. Affiliation Unknown 83/03/28 EISENHUT, D. Division of Licensing 3pp. 17731:028. 24X Fiche: 50-275, 83/03/28, 8303300368.

I. Financial information

8303290345 Forwards Annual Financial Rept 1982.
CRANE, P. A. Pacific Gas & Electric Co. 83/03/25 Office of Nuclear Reactor Regulation, Director 1p. 17718:123. 24X Fiche: 50-000, 83/03/25, 8303290345.

--8303290349 Annual Financial Rept 1982.
* Pacific Gas & Electric Co. 83/02/16 40pp. 17718:124. 24X Fiche: 50-000, 83/03/25, 8303290345.

P. Operating license stage documents & correspondence

8303020147 Forwards voided cover sheet for TES EP-1-007. All copies of procedure previously transmitted should be destroyed or voided. Cover sheet w/attached procedure should be retained in files.
COOPER, W.E. Teledyne Engineering Services 83/02/08 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p 17359:145 24X Fiche: 50-275, 83/02/08, 8303020147

8303020115 Forwards BNL 830202 ltr requesting addl info re buried oil storage tank study. Response requested within 10 days of ltr receipt.
KNIGHTON, G.W. Licensing Branch 3 83/02/10 CRANE, P.A. Pacific Gas & Electric Co. 2pp 17360:195 24X Fiche: 50-275, 83/02/10, 8303020115.

--8303020119 Requests addl info re oil storage tank confirmatory studies contained in Harding-Lawson Assoc 820412 rept.
REICH, M. Brookhaven National Laboratory 83/02/02 KUO, P.T. Structural Engineering Branch 1p 17360:197 24X
Fiche: 50-275, 83/02/10, 8303020115.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D.G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303090291 Updates progress on modeling of PG&E Problem 8-11B & Westinghouse Problem RHR Loop 4 (6-4, 6-7). PG&E problem essentially complete. Document package for Westinghouse problem insufficient. Addl info requested.
REICH, M. Brookhaven National Laboratory 83/02/16 HARTZMAN, M. NRC - No Detailed Affiliation Given 2pp 17492:150 24X
Fiche: 50-275, 83/02/16, 8303090291.

8303030747 Board Notification 83-13: Forwards EG&G draft rept, "Identification & Ranking of Nuclear Plant Structures, Sys & Components & Graded QA Guidelines."
EISENHUT, D.G. Division of Licensing 83/02/17 PALLADINO, N., GILINSKY, V., ASSELSTINE Commissioners 24pp 17364:037 24X
Fiche: 50-000, 83/02/17, 8303030747.

--8303030765 Draft "Identification & Ranking of Nuclear Plant Structures, Sys & Components & Graded QA Guidelines."
WILHOIT, J.M., NITSCHKE, R.L., KUBICEK, L.D. EG&G, Inc FIN A-6479
EGG-EA-6109 DRFT. 82/11/30 HAASS, W. Division of Engineering
128pp 17364:061 24X Fiche: 50-275, 83/02/17, 8303030747.

8303030710 Board Notification 83-17: Forwards JH Conran 830209 affidavit re changes to previous testimony on Unresolved Safety Issue A-17, "Sys Interaction in Nuclear Power Plants."
EISENHUT, D.G. Division of Licensing 83/02/18 PALLADINO, N.J., GILINSKY, V., AHEARNE, J. Commissioners 6pp 17363:317 24X
Fiche: 50-000, 83/02/18, 8303030710.

8303020102 Forwards Rev 0 to "Diablo Canyon Unit 1 Independent Design Verification Program, Valves," Interim Technical Rept 37.
DENISON, E. Robert L. Cloud Associates, Inc 83/02/23 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ENGELKEN, H.R. Region 5, Office of Director MANEATIS, G.A. Pacific Gas & Electric Co. 1p 17349:071 24X Fiche: 50-275, 83/02/23, 8303020102.

--8303020109 Rev 0 to "Diablo Canyon Unit 1 Independent Design Verification Program, Valves," Interim Technical Rept 37.
DENISON, E. Robert L. Cloud Associates, Inc WRAY, R. Teledyne Engineering Services P 105-4-839-037 R00. 83/02/23. 40pp
17349:073 24X Fiche: 50-275, 83/02/23, 8303020102.

8303030382 Forwards status summary of evaluation efforts in progress for independent design verification program. Critical element in completing activities is design verification of containment annulus steel structure & mods to structure.
DIRCKS, W.J. Office of the Executive Director for Operations 83/02/23 PALLADINO, N.J., GILINSKY, V., AHEARNE, J.F. Commissioners
8pp 17365:009 24X Fiche: 50-275, 83/02/23, 8303030382.

--8303030391 Responds to 830111 ltr re concerns of residents near plant on requirements to be satisfied prior to authorization to load fuel. High level of confidence required on const & design prior to decision to authorize operation.
PALLADINO, N.J. Commissioners 83/02/17 UDALL, M.K. House of Rep., Interior & Insular Affairs 7pp 17365:016 24X
Fiche: 50-275, 83/02/23, 8303030382.

--8303030395 Expresses constituent concerns over possibility of allowing fuel load w/o adequate overall assessment of plant safety.
UDALL, M.K. House of Rep., Interior & Insular Affairs 83/01/11
PALLADINO, N.J. Commissioners 4pp 17365:037 24X
Fiche: 50-275, 83/02/23, 8303030382.

--8303030400 Forwards board notification re adequacy of design of component cooling water sys. New review of sys should be undertaken. Determinations to be provided in SER listed w/o encl.
EISENHUT, D.G. Division of Licensing 83/02/18 MATTSON, R. Division of Systems Integration (post 811005) 3pp 17365:041
24X Fiche: 50-275, 83/02/23, 8303030382.

--8207050037 Requests that Commission be briefed prior to NRR approval for Phase II reverification plan. Monthly status rept also requested.
CHILK, S.J. Office of the Secretary of the Commission 82/07/27
DIRCKS, W.J. Office of the Executive Director for Operations 2pp
17365:044 24X Fiche: 50-275, 83/02/23, 8303030382.

8303040645 Board Notification 83-22: Forwards info re design verification program for facility.
EISENHUT, D.G. Division of Licensing 83/02/23 PALLADINO, N., GILINSKY, V., AHEARNE, J. Commissioners 4pp 17429:256 24X
Fiche: 50-275, 83/02/23, 8303040645.

--8303040646 Advises that no open item repts issued since Jan semimonthly rept.
KRECHTING, J.E. Stone & Webster Engineering Corp. 83/02/11
DENTON, H.R. Office of Nuclear Reactor Regulation, Director
ENGELKEN, R.H. Region 5, Office of Director MANEATIS, G.A. Pacific Gas & Electric Co. 1p 17429:312 24X
Fiche: 50-275, 83/02/23, 8303040645.

--8303040647 Trip rept of 830126 visit to Berkeley, CA re meeting w/ RL Cloud & Assoc to obtain clarification & number of items concerning ITR 12 (DCI-IDVP-Piping) & ITR 17 (DCI-IDVP-Piping Addl Samples).
HARTZMAN, M. Mechanical Engineering Branch 83/02/14 BOSNAK, R.J. Mechanical Engineering Branch 6pp 17430:070 24X
Fiche: 50-275, 83/02/23, 8303040645.

--8303040649 Transcript of 830215 conference in Bethesda, MD. Pp 1-47. Supporting documentation encl.
* NRC - No Detailed Affiliation Given 83/02/15 75pp
17430:071 24X Fiche: 50-275, 83/02/23, 8303040645.

--8303040651 Summary of 830204 meeting w/util, Teledyne Engineering Svcs & BNL in San Francisco, CA re structural analyses for facility. Doubts that structural mod can be designed & installed in accordance w/projected fuel load date.
POLK, H. Structural & Geotechnical Engineering Branch
SCHIERLING, H. Licensing Branch 3 83/02/18 LEAR, G.E. Structural & Geotechnical Engineering Branch 3pp 17430:030
24X Fiche: 50-275, 83/02/23, 8303040645.

8303090389 Requests addl info to clarify technical questions & complete confirmatory evaluations for RHR loop 4 & Piping Problems 8-11B, per 830223 telcon w/Westinghouse, PG&E & NRC.
REICH, M. Brookhaven National Laboratory 83/02/24 HARTZMAN, M. NRC - No Detailed Affiliation Given 1p 17471:361 24X
Fiche: 50-275, 83/02/24, 8303090389.

8303010285 Forwards License Amend Request 83-02 re security plan. Class III amend fee encl. Request withheld (ref 10CFR73.21).
CRANE, P.A. Pacific Gas & Electric Co. 83/02/25 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 17335:198
24X Fiche: 50-275, 83/02/25, 8303010285.

8303040531 Forwards info in response to NRC 830119 ltr necessary to calculate pressure & temp transients in area GE of auxiliary bldg resulting from steam line break in area GW. Info relative to FLUD 6 computer code.
CRANE, P.A. Pacific Gas & Electric Co. 83/02/25 EISENHUT, D.G. Division of Licensing 3pp 17366:136 24X Fiche: 50-275, 83/02/25, 8303040531.

8303100229 Forwards Rev 0 to "Independent Design Verification Program, Soils - Intake Structure Bearing Capacity & Lateral Earth Pressure," Interim Technical Rept 39.
DENISON, E. Robert L. Cloud Associates, Inc 83/02/25 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ENGELKEN, R.H. Region 5, Office of Director MANEATIS, G.A. Pacific Gas & Electric Co. 1p 17491:244 24X Fiche: 50-275, 83/02/25, 8303100229.

--8303100235 Rev 0 to "Independent Design Verification Program, Soils - Intake Structure Bearing Capacity & Lateral Earth Pressure," Interim Technical Rept 39.
MCNEILL, R., WRAY, R., DENISON, E. Robert L. Cloud Associates, Inc.
83/02/25 42pp 17491:246 24X Fiche: 50-275, 83/02/25, 8303100229.

8303140564 Forwards BNL 830216 & 24 requests for addl info re util & Westinghouse piping problems. Info requested within 10 days of receipt of ltr.
KNIGHTON, G.W. Licensing Branch 3 83/02/25 CRANE, P.A. Pacific Gas & Electric Co. 2pp 17546:358 24X Fiche: 50-275, 83/02/25, 8303140564.

# DOCKETED ITEMS

--8303140571 Informs that modeling of PG&E Problem B-11B & Westinghouse problem RHR Loop 4 progressing. Submitted document package for PG&E problem essentially complete. Package for Westinghouse insufficient to allow complete verification.
REICH, M. Brookhaven National Laboratory 83/02/16 HARTZMAN, M.
NRC - No Detailed Affiliation Given 2pp 17546:360 24X
Fiche: 50-275, 83/02/25, 8303140564.

--8303140579 Lists items needing clarification to facilitate accurate & timely completion of confirmatory evaluations for RHR Loop 4 & Problem B-11B piping problems.
REICH, M. Brookhaven National Laboratory 83/02/24 HARTZMAN, M.
NRC - No Detailed Affiliation Given. 1p 17546:362 24X
Fiche: 50-275, 83/02/25, 8303140564.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303080212 Forwards revised schedule for fuel loading, low power testing & full power operation. Fuel loading scheduled by 830630.
CRANE, P. A. Pacific Gas & Electric Co. 83/03/02 EISENHUT, D. G.
Division of Licensing 4pp 17457:078 24X Fiche: 50-275, 83/03/02, 8303080212.

8303080307 Forwards addl info re piping analysis in response to 830223 conference call w/NRC & BNL.
CRANE, P. A. Pacific Gas & Electric Co. 83/03/02 EISENHUT, D. G.
Division of Licensing 2pp 17449:350 24X Fiche: 50-275, 83/03/02, 8303080307.

8303080280 Forwards Interim Technical Repts 36 & 38, "Final Rept on Const QA Evaluation of Guy F Atkinson Co." & "Const QA Evaluation of Wismer & Becker," respectively.
SESTAK, F. Stone & Webster Engineering Corp 83/03/03 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director ENGELKEN, R. H.
Region 5, Office of Director MANEATIS, G. A. Pacific Gas & Electric Co. 1p 17473:058 24X Fiche: 50-275, 83/03/03, 8303080280.

--8303080285 "Final Rept on Const QA Evaluation of Guy F Atkinson Co." Interim Technical Rept 36.
SESTAK, F. Stone & Webster Engineering Corp. 36 R00 83/02/25
14pp. 17473:059 24X Fiche: 50-275, 83/03/03, 8303080280.

--8303090112 Rev 0, to "Status Rept on Const QA Evaluation of Wismer & Becker," Interim Technical Rept 38.
SESTAK, F. Stone & Webster Engineering Corp. 38 R00 83/03/01
24pp. 17473:074 24X Fiche: 50-275, 83/03/03, 8303080280.

8303110466 Board Notification 83-30: discusses changes to util schedule supporting licensing actions for facility. Plant readiness for fuel loading projected for 830630.
EISENHUT, D. G. Division of Licensing 83/03/03 PALLADINO, N.,
GILINSKY, V., AHEARNE, J. Commissioners 4pp 17522:354 24X
Fiche: 50-275, 83/03/03, 8303110466.

--8303110506 Forwards revised estimated schedule for completion of activities requ.red for fuel loading, low power testing & full power operation.
CRANE, P. A. Pacific Gas & Electric Co. 83/03/02 EISENHUT, D. G.
Division of Licensing 5pp 17522:358 24X Fiche: 50-275, 83/03/03, 8303110466.

8303080388 Informs that qualified monitors & electrical cable installed to fulfill B21129 commitment to upgrade vent radioactive gas & particulate monitoring sys.
CRANE, P. A. Pacific Gas & Electric Co. 83/03/04 KNIGHTON, G. W.
Licensing Branch 3 1p 17454:168 24X Fiche: 50-275, 83/03/04, 8303080388.

8303080448 Forwards addl info re FLUD 6 computer code steam blowdown input data necessary to calculate pressure & temp transients for pipe break outside containment per NRC 830119 request. Calculation M-287 supplS M-222 sent 830204.
CRANE, P. A. Pacific Gas & Electric Co. 83/03/04 EISENHUT, D. G.
Division of Licensing 2pp 17453:290 24X Fiche: 50-275, 83/03/04, 8303080448.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303090372 Notifies of 830317 meeting in Waltham, MA to discuss Phase II addl verification & engineering open item review.
COOPER, W. E., CRAGIN, J. G. Teledyne Engineering Services 83/03/09
NRC - No Detailed Affiliation Given 1p 17471:360 24X
Fiche: 50-275, 83/03/09, 8303090372.

8303230450 Forwards draft technical evaluation rept based on util responses to generic ltr on control of heavy loads (NUREG-0612). Comments requested by 830509.
KNIGHTON, G. W. Licensing Branch 3 83/03/09 CRANE, P. A. Pacific Gas & Electric Co. 4pp 17674:045 24X Fiche: 50-275, 83/03/09, 8303230450.

--8302160446 "Control of Heavy Loads at Nuclear Power Plants, Diablo Canyon Unit 1," draft technical evaluation rept.
JENSEN, S. A. EG&G, Inc. 83/01/31 NRC - No Detailed Affiliation Given 37pp 17674:049 24X Fiche: 50-275, 83/03/09, 8303230450.

8303180618 Forwards exemption & Amend 4 to License DPR-76. Exemption & amend grant temporary relief from requirements of portions of 10CFR73 re maintaining approved physical security plan.
EISENHUT, D. G. Division of Licensing 83/03/11 CRANE, P. A. Pacific Gas & Electric Co. 3pp 17626:335 24X Fiche: 50-275, 83/03/11, 8303180618.

--8303180623 Exemption from requirements of certain portions of 10CFR73 re maintaining approved physical security plan.
EISENHUT, D. G. Division of Licensing 83/03/11 Pacific Gas & Electric Co 5pp 17626:338 24X Fiche: 50-275, 83/03/11, 8303180618.

--8303180629 Amend 4 to License DPR-76, granting temporary exemption from requirements of portions of 10CFR73 re maintaining approved physical security plan.
EISENHUT, D. G. Division of Licensing 83/03/11 3pp 17626:343 24X Fiche: 50-275, 83/03/11, 8303180618.

8303170348 Notifies that WCAP-9804, "Probabilistic Analysis & Operational Data in Response to Item II K 3.2 for Westinghouse NSSS Plants," contains info & conclusions applicable to both units to satisfy Item II K 3.2.
CRANE, P. A. Pacific Gas & Electric Co. 83/03/14 KNIGHTON, G. W.
Licensing Branch 3 2pp 17605:179 24X Fiche: 50-275, 83/03/14, 8303170348.

8303220304 Submits addl info requested at 830128 meeting w/NRC re leak rate assumptions of C loop & design heat removal capabilities of component cooling water sys. Results of analyses expected by 830318.
CRANE, P. A. Pacific Gas & Electric Co. 83/03/15 EISENHUT, D. G.
Division of Licensing 2pp 17654:301 24X Fiche: 50-275, 83/03/15, 8303220304.

8303240513 Forwards addl piping info requested by BNL on 830216, 24 & 28, per NRC 830225 request. Matl contains info proprietary to Westinghouse. Attachments withheld (ref 10CFR2.790).
CRANE, P. A. Pacific Gas & Electric Co. 83/03/18 EISENHUT, D. G.
Division of Licensing 5pp 17682:247 24X Fiche: 50-275, 83/03/18, 8303240513.

8303290692 Board Notification 83-35 forwards info on status of activities performed under independent design verification program. Info relevant to design adequacy safety issue per Order CLI-81-30.
EISENHUT, D. G. Division of Licensing 83/03/18 PALLADINO, N. J.,
GILINSKY, V., AHEARNE, J. Commissioners 4pp 17741:001 24X
Fiche: 50-275, 83/03/18, 8303290692.

8303280042 Informs that final results of temp & pressure vs time curves for pipe break outside containment will be submitted 830411 instead of 830318.
CRANE, P. A. Pacific Gas & Electric Co. 83/03/22 EISENHUT, D. G.
Division of Licensing 1p 17707:229 24X Fiche: 50-275, 83/03/22, 8303280042.

8303280137 Comments on Board Notification 83-38 re failure of GE AK-2 reactor trip breakers. Info may affect NRC conclusions re probability/corrective measures for transients w/o scram events (Unresolved Safety Issue A-9).
EISENHUT, D. G. Division of Licensing 83/03/22 PALLADINO, N.,
AHEARNE, J. F., ASSELSTINE, T. Commissioners 20pp 17709:310 24X
Fiche: 50-000, 83/03/22, 8303280137.

8303240419 Notifies of 830317 & 0329-30 meeting w/S&W & RL Cloud Associates, Inc in Boston, MA & San Francisco, CA to discuss Phase II addl verification & engineering open items & structural review, respectively.
COOPER, W. E., CRAGIN, J. G. Teledyne Engineering Services 83/03/24
NRC - No Detailed Affiliation Given. 2pp 17678:288 24X
Fiche: 50-275, 83/03/24, 8303240419.

8303290315 Confirms plans to submit schedule for resolution of TMI Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps," by end of May 1983 per Generic Ltr 83-10C.
SCHUYLER, J.O. Pacific Gas & Electric Co. 83/03/24 EISENHUT, D.G. Division of Licensing 2pp 17716:150 24X Fiche:50-275,83/03/24. 8303290315.

8303300030 Provides plan for data collection re ECCS component outages, per B10213 commitment to satisfy NUREG-0737, Item II.K.3.17 requirements.
CRANE, P.A. Pacific Gas & Electric Co. 83/03/25 KNIGHTON, G.W. Licensing Branch 3 2pp 17731:189 24X Fiche:50-275,83/03/25. 8303300030.

8303300035 Responds to BNL request for clarification of info re diesel fuel oil storage tanks, per 830322 telcon & ltr. Backfill properties applicable for inside & outside of trench.
CRANE, P.A. Pacific Gas & Electric Co. 83/03/25 EISENHUT, D.G. Division of Licensing 2pp 17735:309 24X Fiche:50-275,83/03/25. 8303300035.

8303300115 Submits schedule for furnishing addl info re component cooling water sys. Seismic analysis of reactor coolant pump upper & lower bearing oil coolers will be supplied by 830415.
CRANE, P.A. Pacific Gas & Electric Co. 83/03/25 EISENHUT, D.G. Division of Licensing 2pp 17735:307 24X Fiche:50-275,83/03/25. 8303300115.

G Inspection reports, IE Bulletins & correspondence

8303040409 Forwards IE Insp Repts 50-275/83-03 & 50-323/83-02 on 830102-29. No noncompliance noted.
BISHOP, T.W. Division of Resident, Reactor Project & Engineering Programs 83/02/11 CRANE, P.A. Pacific Gas & Electric Co. 2pp 17374:301 24X Fiche:50-275,83/02/11. 8303040409.

--8303040421 IE Insp Repts 50-275/83-03 & 50-323/83-02 on 830102-29. No noncompliance noted. Major areas inspected: plant operations, surveillance testing, physical security, maint, LER followup & TMI Action Plan Item II.E.4.2.
CARLSON, J.D., MENDUNCA, M.M., KIRSCH, D.F. Division of Resident, Reactor Project & Engineering Programs 83/02/10 4pp 17374:303 24X Fiche:50-275,83/02/11. 8303040409.

8303040447 Forwards IE Insp Repts 50-275/83-04 & 50-323/83-03 on 830125-27. No noncompliance noted.
BISHOP, T.W. Division of Resident, Reactor Project & Engineering Programs 83/02/11 CRANE, P.A. Pacific Gas & Electric Co. 2pp 17374:015 24X Fiche:50-275,83/02/11. 8303040447.

--8303040454 IE Insp Repts 50-275/83-04 & 50-323/83-03 on 830125-27. No noncompliance noted. Major areas inspected: independent verification program, implementation of QA programs & project procedures.
MORRILL, P.J., ECKHARDT, J.H., KIRSCH, D.F. Division of Resident, Reactor Project & Engineering Programs 83/02/11 5pp 17374:017 24X Fiche:50-275,83/02/11. 8303040447.

8303110355 Board Notification 83-14: forwards followup info on apparent deficiencies in Midland-Ross super-strut matl.
EISENHUT, D.G. Division of Licensing 83/02/18 PALLADINO, N., GILINSKY, V., AHEARNE, J. Commissioners 24pp 17546:205 24X Fiche:50-000,83/02/18. 8303110355.

8303010419 Ack receipt of 830211 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-275/82-40.
BISHOP, T.W. Division of Resident, Reactor Project & Engineering Programs 83/02/22 CRANE, P.A. Pacific Gas & Electric Co. 1p 17343:139 24X Fiche:50-275,83/02/22. 8303010419.

--8303010421 Responds to NRC 830112 ltr re violations noted in IE Insp Rept 50-275/82-40. Corrective actions: Procedure M-17 for functional test of emergency dc lighting sys & communication sys revised & missing fire extinguishers replaced.
CRANE, P.A. Pacific Gas & Electric Co. 83/02/11 ENGELKEN, R.H. Region 5, Office of Director 3pp 17343:160 24X Fiche:50-275,83/02/22. 8303010419.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 111pp 17521:001 24X Fiche:50-000,83/02/25. 8212060367.

8303290262 Forwards IE Insp Repts 50-275/83-06 & 50-323/83-05 on 830215-18. No noncompliance noted.
BISHOP, T.W. Region 5, Office of Director 83/03/07 CRANE, P.A. Pacific Gas & Electric Co. 2pp 17716:082 24X Fiche:50-275,83/03/07. 8303290262.

--8303290271 IE Insp Repts 50-275/83-06 & 50-323/83-05 on 830215-18. No noncompliance noted. Major areas inspected: licensee actions on previously identified items, mods to structural steel & electrical raceway & pipe supports.
BURDOIN, J.F., ZWETZIG, G.B. Region 5, Office of Director 83/03/03 5pp 17716:084 24X Fiche:50-275,83/03/07. 8303290262.

8303140446 Responds to IE Bulletin 83-01 re operation of reactor trip breakers. Surveillance testing of undervoltage trip function independent of shunt trip performed on 830228. Results satisfactory.
MANEATIS, G.A. Pacific Gas & Electric Co. 83/03/09 ENGELKEN, R.H. Region 5, Office of Director 4pp 17542:240 24X Fiche:50-275,83/03/09. 8303140446.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp 17611:070 24X Fiche:50-000,83/03/11. 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche:50-000,83/03/18. 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp 17774:352 24X Fiche:50-000,83/03/21. 8212060387.

8303290544 Notifies of 830407 mgt meeting in San Francisco, CA to discuss SALP for Jul 1981 - Dec 1982.
CREWS, J.L. Division of Resident, Reactor Project & Engineering Programs 83/03/25 CRANE, P.A. Pacific Gas & Electric Co. 3pp 17725:063 24X Fiche:50-275,83/03/25. 8303290544.

--8303290546 SALP rept for Jul 1981 - Dec 1982.
* Region 5, Office of Director 83/03/25 35pp 17725:066 24X Fiche:50-275,83/03/25. 8303290544.

--8302250060 Forwards NRR input to Cycle 3 SALP evaluation for Jul 1981 - Dec 1982. Overall performance rating of Category 2 determined. Evaluation matrix encl.
BUCKLEY, B. Licensing Branch 3 83/02/15 EISENHUT, D.G. Division of Licensing 8pp 17725:101 24X Fiche:50-275,83/03/25. 8303290544.

R Periodic operating reports & related correspondence

9303080173 Forwards monthly operating rept for Dec 1982.
THORNBERRY, R.C. Pacific Gas & Electric Co. 83/01/04 Division of Data Automation & Management Information 1p 17458:114 24X Fiche:50-275,83/01/04. 8303080173.

--8303080177 Monthly operating rept for Dec 1982.
KELLY, W.J. Pacific Gas & Electric Co. 83/01/04 4pp 17458:115 24X Fiche:50-275,83/01/04. 8303080173.

8303090259 Forwards program manager rept for Jan 1982. Individuals assigned to independent design verification program completed acceptable statement re potential or apparent conflicts of interest.
REEDY, R.F. Reedy, Herbert, Gibbons & Associates 83/01/28 COOPER, W.E. Teledyne Engineering Services 6pp 17473:339 24X Fiche:50-275,83/01/28. 8303090259.

8303150508 Forwards monthly operating rept for Jan 1983.
THORNBERRY, R.C. Pacific Gas & Electric Co. 83/02/04 Office of Resource Management, Director 1p 17560:113 24X Fiche:50-275,83/02/04. 8303150508.

--8303150512 Monthly operating rept for Jan 1983.
KELLY, W.J. Pacific Gas & Electric Co. 83/02/04 4pp 17560:114 24X Fiche:50-275,83/02/04. 8303150508.

8303090304 Submits Semimonthly Progress Rept 24 for 830114-0211. No open items repts issued for independent design verification program.
REEDY, R.F. R.F. Reedy, Inc. 83/02/16 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ENGELKEN, R.H. Region 5, Office of Director MANEATIS, G.A. Pacific Gas & Electric Co. 2pp 17471:243 24X Fiche:50-275,83/02/16. 8303090304.

8303090335 Advises that "Independent Design Verification Program Semimonthly Rept" issued on 830302 instead of 830223 as originally planned.Change made to ensure that rept reflects all work conducted in Feb 1983.
COOPER,W.E. Teledyne Engineering Services 83/02/24 DENTON,H.R. Office of Nuclear Reactor Regulation, Director MANEATIS,G.A. Pacific Gas & Electric Co. ENGELKEN,R.H. Region 5, Office of Director 2pp. 17473.176 24X Fiche:50-275,83/02/24,8303090335.

8303100241 Forwards "Design Verification Program," 32nd semimonthly status rept.
CRANE,P.A. Pacific Gas & Electric Co. 83/02/25 DENTON,H.R. Office of Nuclear Reactor Regulation, Director ENGELKEN,R.H. Region 5, Office of Director. 1p. 17485.297 24X Fiche:50-275,83/02/25,8303100241.

--8303100247 "Design Verification Program," 32nd semimonthly status rept for 830208-22.
* Pacific Gas & Electric Co. 83/02/25 58pp. 17485.298 24X Fiche:50-275,83/02/25,8303100241.

8303080031 Forwards revised tables consisting of NPDES data, including heavy metal analysis results, inadvertently omitted from annual rept.
THORNBERRY,R.C. Pacific Gas & Electric Co. 83/03/02 JONES,R.H. California, State of 2pp. 17456.355 24X Fiche:50-275,83/03/02,8303080031.

--8303080036 Revised tables consisting of NPDES data, including heavy metal analysis, inadvertently omitted from annual rept.
* Pacific Gas & Electric Co. 83/03/02 4pp. 17456.357 24X Fiche:50-275,83/03/02,8303080031.

8303090384 Forwards "Diablo Canyon Nuclear Power Plant Independent Design Verification Program Semimonthly Rept,Feb 1983."
COOPER,W.E. Teledyne Engineering Services 83/03/02 DENTON,H.R. Office of Nuclear Reactor Regulation, Director ENGELKEN,R.H. Region 5, Office of Director MANEATIS,G.A. Pacific Gas & Electric Co. 1p. 17471.001 24X Fiche:50-275,83/03/02,8303090384.

--8303090388 "Diablo Canyon Nuclear Power Plant Independent Design Verification Program Semimonthly Rept,Feb 1983." Phase 1 of program covers restoration of low power license & considers util Hosgri seismic-related efforts.
* Teledyne Engineering Services 83/02/25 78pp. 17471.002 24X Fiche:50-275,83/03/02,8303090384.

8303160337 Forwards "Independent Design Verification Program Soils Rept - Intake Structure Sliding Resistance," Interim Technical Rept 40.
DENISON,E. Robert L. Cloud Associates, Inc. 83/03/10 DENTON,H.R. Office of Nuclear Reactor Regulation, Director ENGELKEN,R.H. Region 5, Office of Director MANEATIS,G.H. Pacific Gas & Electric Co. 1p. 17595.226 24X Fiche:50-275,83/03/10,8303160337.

--8303160342 "Independent Design Verification Program Soils Rept - Intake Structure Sliding Resistance," Interim Technical Rept 40.
MCNEILL,R. DENISON,E. Robert L. Cloud Associates, Inc. P 105-4-839-040 R00 83/03/09 28pp. 17595.227 24X Fiche:50-275,83/03/10,8303160337.

8303170118 Forwards Open Item Rpts 1114,1115 & 1116,Rev 0,for Mar 1983.Corporate employees completed acceptance statement re potential or apparent conflicts of interest.
DENISON,E. Robert L. Cloud Associates, Inc. 83/03/10 DENTON,H.R. Office of Nuclear Reactor Regulation, Director ENGELKEN,R.H. Region 5, Office of Director MANEATIS,G.H. Pacific Gas & Electric Co. 4pp. 17609.026 24X Fiche:50-275,83/03/10,8303170118.

8303220067 Advises that no open items re const QA evaluation issued since Feb semimonthly rept.
SESTAK,F. Stone & Webster Engineering Corp. 83/03/11 DENTON,H.R. Office of Nuclear Reactor Regulation, Director ENGELKEN,R.H. Region 5, Office of Director MANEATIS,G.A. Pacific Gas & Electric Co. 1p. 17652.193 24X Fiche:50-275,83/03/11,8303220067.

8303220074 Submits Mar 1983 semimonthly rept.One open item rept form issued since last semimonthly rept encl.
KRECHTING,J.E. Stone & Webster Engineering Corp. 83/03/11 DENTON,H.R. Office of Nuclear Reactor Regulation, Director ENGELKEN,R.H. Region 5, Office of Director MANEATIS,G.A. Pacific Gas & Electric Co. 2pp. 17652.202 24X Fiche:50-275,83/03/11,8303220074.

8303250061 Forwards "Diablo Canyon Verification Program," Semimonthly Rept 33 for 830223-0307.
CRANE,P.A. Pacific Gas & Electric Co. 83/03/11 DENTON,H.R. Office of Nuclear Reactor Regulation, Director ENGELKEN,R.H. Region 5, Office of Director 1p. 17692.274 24X Fiche:50-275,83/03/11,8303250061.

--8303250064 "Diablo Canyon Verification Program," Semimonthly Report 33 for 830223-0307.
* Pacific Gas & Electric Co. 83/03/11 56pp. 17692.275 24X Fiche:50-275,83/03/11,8303250061.

8303250079 Forwards "Phase II Status Rept,Design Verification Program, Diablo Canyon Power Plant," for restoration of license for fuel loading,per util 830302 licensing schedule.
CRANE,P.A. Pacific Gas & Electric Co. 83/03/11 EISENHUT,D.G. Division of Licensing 1p. 17692.126 24X Fiche:50-275,83/03/11,8303250079.

--8303250081 "Phase II Status Rept,Design Verification Program,Diablo Canyon Power Plant."
* Pacific Gas & Electric Co. 0041L/0077P 83/03/31 76pp. 17692.127 24X Fiche:50-275,83/03/11,8303250079.

8303290365 Forwards sections & tables in Part 2 of Phase I final rept re bldgs,structures & supports for design verification program.
CRANE,P.A. Pacific Gas & Electric Co. 83/03/15 EISENHUT,D.G. Division of Licensing 539pp. 17716.273 24X Fiche:50-275,83/03/15,8303290365.

8303240409 Submits Semimonthly Progress Rept 25 for 830214-0311.No open item repts issued.Acceptable statement re potential or apparent conflicts of interest completed.
REEDY,R.F. R.F. Reedy, Inc. 83/03/16 DENTON,H.R. Office of Nuclear Reactor Regulation, Director ENGELKEN,R.H. Region 5, Office of Director MANEATIS,G.A. Pacific Gas & Electric Co. 2pp. 17679.046 24X Fiche:50-275,83/03/16,8303240409.

8303230054 Forwards Rev 1 to "Final Rept on Const QA Evaluation of Wismer & Becker," Interim Technical Rept 38.
SESTAK,F. Stone & Webster Engineering Corp. 83/03/18 DENTON,H.R. Office of Nuclear Reactor Regulation, Director MANEATIS,G.A. Pacific Gas & Electric Co. ENGELKEN,R.H. Region 5, Office of Director. 1p. 17663.164 24X Fiche:50-275,83/03/18,8303230054.

--8303230059 Rev 1 to "Final Rept on Const QA Evaluation of Wismer & Becker," Interim Technical Rept 38.
SESTAK,F. Stone & Webster Engineering Corp. 83/03/16 33pp. 17663.165 24X Fiche:50-275,83/03/18,8303230054.

8303290002 Forwards "Diablo Canyon Nuclear Power Plant Independent Design Verification Program," semimonthly rept for Mar 1983.
COOPER,W.E. Teledyne Engineering Services 83/03/25 DENTON,H.R. Office of Nuclear Reactor Regulation, Director ENGELKEN,R.H. Region 5, Office of Director MANEATIS,G.A. Pacific Gas & Electric Co. 1p. 17723.130 24X Fiche:50-275,83/03/25,8303290002.

--8303290004 "Diablo Canyon Nuclear Power Plant Independent Design Verification Program," semimonthly rept for Mar 1983.
* Teledyne Engineering Services 83/03/25 112pp. 17723.131 24X Fiche:50-275,83/03/25,8303290002.

8303290469 Clarifies distribution of interim semimonthly technical rept to designated other parties for Oct 1982 Procedure DCNPP-IDVP-PP-007, "Interface Between IDVP Participants,DCP & Designated Other Parties," updated.
CRAGIN,J.G. Teledyne Engineering Services 83/03/25 DENTON,H.R. Office of Nuclear Reactor Regulation, Director ENGELKEN,R.H. Region 5, Office of Director MANEATIS,G.A. Pacific Gas & Electric Co. 2pp. 17722.357 24X Fiche:50-275,83/03/25,8303290469.

## S Reportable occurrences, LERs & related correspondence

8303010625 Forwards LER 83-002/03L-0.
SHIFFER,J.D. Pacific Gas & Electric Co. 83/02/14 ENGELKEN,R.H. Region 5, Office of Director 1p. 17336.269 24X Fiche:50-275,83/02/14,8303010625.

--8303010635 LER 83-002/03L-0 on 830113,prior to fuel load,liquid radwaste effluent flow recorder discovered inoperable during discharge of tank in liquid radwaste sys.Caused by out of tolerance flow transmitter.Transmitter cleaned.
KELLY,W.J. Pacific Gas & Electric Co. 83/02/14 Region 5, Office of Director 1p. 17336.270 24X Fiche:50-275,83/02/14,8303010625.

8303150620 Board Notification 83-26:Forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys.Info may affect conclusions re probability of/corrective measures for ATWS.
EISENHUT,D.G. Division of Licensing 83/03/03 PALLADINO,N. Commissioners 24pp. 17584.097 24X Fiche:50-000,83/03/03,8303150620.

8303180482 PNO-V-83-012 on 830311. Five guards received radiation exposure from X-ray machines used for searching packages brought into protected area. Guards rode through X-ray machine as prank. Four individuals dismissed. GARCIA, E. ; WENSLAWSKI, F. Region 5 Office of Director 83/03/11 1p 17622 125 24X Fiche: 50-275, 83/03/11, 8303180482.

T. Hearing transcripts on non-antitrust matters

8303010709 Staff requirements memo re 830217 affirmation/discussion & vote on SECY-82-400: "Review of ALAB-691" & SECY-83-35: "UCS Objection to Ex Parte Communications in TMI-1 Proceeding." CHILK, S. J. Office of the Secretary of the Commission 83/02/18 PLAINE, H. H. E. Office of the General Counsel 2pp 17348 318 24X Fiche: 50-275, 83/02/18, 8303010709.

8303040645 Board Notification 83-22 forwards info re design verification program for facility. EISENHUT, D. G. Division of Licensing 83/02/23 PALLADINO, N. ; GILINSKY, V. ; AHEARNE, J. Commissioners 4pp 17429 256 24X Fiche: 50-275, 83/02/23, 8303040645.

--8303040649 Transcript of 830215 conference in Bethesda, MD. Pp. 1-47. Supporting documentation encl. * NRC - No Detailed Affiliation Given 83/02/15 75pp 17430 071 24X Fiche: 50-275, 83/02/23, 8303040645.

8303080006 Forwards QA Maneatis testimony to be delivered before House of Representatives Committee on Interior & Insular Affairs, Subcommittee on Energy & Environ. on 830308. * Pacific Gas & Electric Co. 83/03/07 NRC - No Detailed Affiliation Given 1p 17455 298 24X Fiche: 50-275, 83/03/07, 8303080006.

--8303080017 Testimony of QA Maneatis re NRC procedures for restoring authority to load fuel, before House of Representatives, Committee on Interior & Insular Affairs, Subcommittee on Energy & Environ. Related correspondence. MANEATIS, G. A. Pacific Gas & Electric Co. 83/03/08 18pp 17455 299 24X Fiche: 50-275, 83/03/07, 8303080006.

U. Congressional/Executive Correspondence

8303030347 Forwards response to concerns expressed in 830111 ltr re safety-related requirements to be met prior to authorization for fuel loading. Operation will not be authorized until reasonable assurance provided that public safety protected. PALLADINO, N. J. Commissioners 83/02/17 UDALL, M. K. House of Rep., Interior & Insular Affairs 10pp 17365 047 24X Fiche: 50-275, 83/02/17, 8303030347.

--8303030355 Expresses concerns of individuals living in area near facility re safety-related requirements to be met prior to authorization for fuel loading. UDALL, M. K. House of Rep., Interior & Insular Affairs 83/01/11 PALLADINO, N. J. Commissioners 1p 17365 074 24X Fiche: 50-275, 83/02/17, 8303030347.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp 24X Fiche: 50-000, 83/02/24, 8302250505.

8303090330 Submits estimate of anticipated requests for site visits to conduct operator license exams through Jul 1985 per Generic Ltr 83-01. CRANE, P. A. Pacific Gas & Electric Co. 83/02/28 EISENHUT, D. G. Division of Licensing 1p 17473 178 24X Fiche: 50-275, 83/02/28, 8303090330.

DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8301310278 Forwards IE Insp Repts 50-277/82-24 & 50-278/82-23 on 821213-16 & notice of violation. MARTIN, T. T. Division of Engineering & Technical Programs 83/01/18 DALTROFF, S. L. Philadelphia Electric Co. 2pp 16969 115 24X Fiche: 50-277, 83/01/18, 8301310278.

--8301310290 IE Insp Repts 50-277/82-24 & 50-278/82-23 on 821213-16. Noncompliance noted: failure to meet fire brigade training requirements. PLISCO, L. R. ; ANDERSON, C. J. Division of Engineering & Technical Programs 83/01/10 11pp 16969 119 24X Fiche: 50-277, 83/01/18, 8301310278.

8303040523 Requests exemption from schedule requirements of 10CFR50.48(c)(2) & (c)(3) to permit completion of fire protection mods identified in 820628 safe shutdown rept. Proposed mod schedule, revised Section 6 & mod tabulations encl. GALLAGHER, J. W. Philadelphia Electric Co. 83/02/25 EISENHUT, D. G. Division of Licensing 19pp 17367 342 24X Fiche: 50-277, 83/02/25, 8303040523.

8303090454 Notification of 830309 meeting w/util & consultant in Bethesda, MD to discuss App. R exemption requests. GEARS, G. Operating Reactors Branch 4 83/03/01 STOLZ, J. Operating Reactors Branch 4 3pp 17483 170 24X Fiche: 50-277, 83/03/01, 8303090454.

8303080359 Ack receipt of 830217 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/82-24 & 50-278/82-23. MARTIN, T. T. Division of Engineering & Technical Programs 83/03/02 DALTROFF, S. L. Philadelphia Electric Co. 1p 17453 335 24X Fiche: 50-277, 83/03/02, 8303080359.

--8303080373 Responds to NRC 830118 ltr re violations noted in IE Insp Repts 50-277/82-24 & 50-278/82-23. Corrective actions: individuals missing fire brigade training scheduled for next available class. Fire brigade program updated. DALTROFF, S. L. Philadelphia Electric Co. 83/02/17 MARTIN, T. T. Division of Engineering & Technical Programs 4pp 17453 336 24X Fiche: 50-277, 83/03/02, 8303080359.

8303150371 Forwards application for amend to Licenses DPR-44 & DPR-56, changing Tech Specs to correct listing of smoke detectors & revise requirements for control of high radiation area keys for clarification & consistency. BRADLEY, E. J. Philadelphia Electric Co. 83/03/11 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 17562 118 24X Fiche: 50-277, 83/03/11, 8303150371.

--8303150379 Application for amend to Licenses DPR-44 & DPR-56, changing Tech Specs to correct listing of smoke detectors & revise requirements for control of high radiation area keys for clarification & consistency. DALTROFF, S. L. ; BAUER, E. G. ; BRADLEY, E. J. Philadelphia Electric Co. 83/03/11 8pp 17562 119 24X Fiche: 50-277, 83/03/11, 8303150371.

--8303150385 Proposed changes to Tech Specs correcting list of smoke detectors & revising requirements for control of high radiation area keys for clarification & consistency. * Philadelphia Electric Co. 83/03/11 5pp 17562 127 24X Fiche: 50-277, 83/03/11, 8303150371.

8303250052 Forwards IE Insp Repts 50-277/83-02 & 50-278/83-02 on 830111-0224 & notice of violation. STAROSTECKI, R. Division of Project & Resident Programs 83/03/11 DALTROFF, S. L. Philadelphia Electric Co. 2pp 17691 295 24X Fiche: 50-277, 83/03/11, 8303250052.

--8303250058 Notice of violation from insp on 830111-0224. * Region 1, Office of Director 83/02/28 1p 17691 297 24X Fiche: 50-277, 83/03/11, 8303250052.

--8303250070 IE Insp Repts 50-277/83-02 & 50-278/83-02 on 830111-0224. Noncompliance noted: inadequate design control of containment atmosphere dilution ref gas supply & failure to keep fire doors closed. BLOUGH, A. R. ; MCCABE, E. C. Region 1, Office of Director 83/03/07 22pp 17691 298 24X Fiche: 50-277, 83/03/11, 8303250052.

8303280271 Forwards IE Insp Repts 50-277/83-01 & 50-278/83-01 on 830110-14. No noncompliance noted. MARTIN, T. T. Division of Engineering & Technical Programs 83/03/14 DALTROFF, S. L. Philadelphia Electric Co. 2pp 17706 237 24X Fiche: 50-277, 83/03/14, 8303280271.

--8303280283 IE Insp Repts 50-277/83-01 & 50-278/83-01 on 830110-14. No noncompliance noted. Major areas inspected: followup of emergency preparedness items from 811207-17 appraisal. TERC, N. M. ; COHEN, I. ; CROCKER, H. W. Region 1, Office of Director 83/03/09 15pp 17706 239 24X Fiche: 50-277, 83/03/14, 8303280271.

8303290541 Summary of 830309 meeting w/util re App. R exemption requests. Supporting info necessary for NRC determination outlined. Alternative safe shutdown capability proposed. GEARS, G. Operating Reactors Branch 4 83/03/21 Operating Reactors Branch 4 3pp 17740 358 24X Fiche: 50-277, 83/03/21, 8303290541.

8303280277 Identifies correspondence providing util response to unresolved items discussed in NRC 801124 ltr. Addl info re fire detector installation to meet 10CFR50, App R provided & exemption from fire detection requirements requested.
DALTROFF, S. L. Philadelphia Electric Co. 83/03/24. STOLZ, J. F. Operating Reactors Branch 4. 4pp. 17706:230. 24X
Fiche: 50-277, 83/03/24, 8303280277.

8303300581 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/24. Document Management Branch. 1p. 17765:333. 24X Fiche: 50-277, 83/03/24, 8303300581.

--8303300588 Forwards public version of revised Emergency Plan Implementing Procedures EP-103, "Alert Response," EP-104, "Site Emergency Response" & EP-105, "General Emergency Response."
DALTROFF, S. L. Philadelphia Electric Co. 83/02/14. HAYNES, R. C. Region 1, Office of Director. 2pp. 17765:334. 24X
Fiche: 50-277, 83/03/24, 8303300581.

--8303300594 Public version of revised Emergency Plan Implementing Procedures EP-103, "Alert Response," EP-104, "Site Emergency Response" & EP-105, "General Emergency Response." Revised index encl.
* Philadelphia Electric Co. 83/01/12. 32pp. 17765:336. 24X
Fiche: 50-277, 83/03/24, 8303300581.

8303300389 Discusses problems associated w/emergency notification sys siren located adjacent to R Eshleman property in Nottingham, PA. No response required.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/25. DALTROFF, S. L. Philadelphia Electric Co. 2pp. 17731:070. 24X
Fiche: 50-277, 83/03/25, 8303300389.

## G. Adjudicatory correspondence

8303020063 Response opposing util motion to strike C Kepford supplemental affidavit re qualifications as expert witness. Intervenors unable to respond in detail since motion never received. Certificate of Svc encl.
JOHNSRUD, J. H. Environmental Coalition on Nuclear Power. 83/02/24. Commissioners. 2pp. 17352:136. 24X Fiche: 50-000, 83/02/24, 8303020063.

## I. Financial information

8303170159 Forwards Annual Financial Repts 1982 & 1983.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/14. SALTZMAN, J. Assistant Director for State & Licensee Relations. 7pp. 17605:183. 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170169 Annual Financial Rept 1982.
SMITH, R. I., SONN, H. W. Public Service Electric & Gas Co. of New Jersey. 83/02/14. 52pp. 17605:191. 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170182 Annual Financial Rept 1982.
EVERETT, J. L., AUSTIN, J. H. Philadelphia Electric Co. 83/03/14. 41pp. 17605:243. 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170193 Annual Financial Rept 1982.
WEIMER, R. D., CURTIS, N. M. Delmarva Power & Light Co. 83/02/04. 44pp. 17605:287. 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170206 Annual Financial Rept 1982.
FEEHAN, J. D. Atlantic Electric of New Jersey. 83/03/14. 42pp. 17605:333. 24X Fiche: 50-000, 83/03/14, 8303170159.

## J. Insurance & indemnity information

8303080205 Forwards Endorsement 100 to NELIA Policy NF-140 & Endorsement 54 to MAELU Policy MF-67.
BRADLEY, E. J. Philadelphia Electric Co. 83/02/28. SALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp. 17457:075. 24X Fiche: 50-277, 83/02/28, 8303080205.

8303100358 Requests indemnity fee refund reflecting reduction in annual fee.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/07. SALTZMAN, J. Assistant Director for State & Licensee Relations. 2pp. 17488:293. 24X Fiche: 50-277, 83/03/07, 8303100358.

8303290350 Forwards Endorsements 101 & 7 to NELIA Policy NF-140 & Master Policy 1, respectively.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/23. SALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp. 17716:163. 24X Fiche: 50-277, 83/03/23, 8303290350.

## P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303040385 Forwards safety evaluation of util response to NUREG-0737, Item I.A.2.1.4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & Item II.B.4.1, "Training for Mitigating Core Damage." Item closed.
STOLZ, J. F. Operating Reactors Branch 4. 83/02/17. BAUER, E. G. Philadelphia Electric Co. 2pp. 17426:321. 24X
Fiche: 50-277, 83/02/17, 8303040385.

--8303040391 Safety evaluation supporting util response to NUREG-0737, Item I.A.2.1.4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & Item II.B.4.1, "Training for Mitigating Core Damage."
HAVERKAMP, D. R. Operating Reactors Branch 4. 83/02/17. 5pp. 17426:323. 24X Fiche: 50-277, 83/02/17, 8303040385.

--8208310332 "Improvements in Training & Requalification Programs as Required by TMI Action Items I.A.2.1 & II.B.4 for Peach Bottom Atomic Power Station," technical evaluation rept.
* Science Applications, Inc. NRC-03-82-096. SAI-186-029-48. 82/08/26. NRC - No Detailed Affiliation Given. 14pp. 17426:328. 24X Fiche: 50-277, 83/02/17, 8303040385.

8303020420 Forwards Amend 87 to Licenses DPR-44 & DPR-56, safety evaluation & notice of issuance & availability. Amend changes Tech Specs re surveillance requirements to permit alternate method for performing core spray loop flow rate test.
GEARS, G. E. Operating Reactors Branch 4. 83/02/18. BAUER, E. G. Philadelphia Electric Co. 3pp. 17357:290. 24X
Fiche: 50-277, 83/02/18, 8303020420.

--8303020423 Amend 87 to Licenses DPR-44 & DPR-56, changing Tech Specs re surveillance requirements to permit alternate method for performing core spray loop flow rate test.
STOLZ, J. F. Operating Reactors Branch 4. 83/02/18. 10pp. 17357:293. 24X Fiche: 50-277, 83/02/18, 8303020420.

--8303020426 Safety evaluation supporting Amend 87 to Licenses DPR-44 & DPR-56.
* Office of Nuclear Reactor Regulation, Director. 83/02/18. 2pp. 17357:303. 24X Fiche: 50-277, 83/02/18, 8303020420.

--8303020429 Notice of issuance & availability of Amend 87 to Licenses DPR-44 & DPR-56.
STOLZ, J. F. Operating Reactors Branch 4. 83/02/18. 2pp. 17357:305. 24X Fiche: 50-277, 83/02/18, 8303020420.

8303110151 Forwards Amend 90 to Licenses DPR-44 & DPR-56, safety evaluation & notice of issuance & availability. Amend provides operability & surveillance requirements for scram discharge vol vent & drain isolation valves.
GEARS, G. E. Operating Reactors Branch 4. 83/03/01. BAUER, E. G. Boston Edison Co. 2pp. 17523:118. 24X Fiche: 50-277, 83/03/01, 8303110151.

--8303110154 Amend 90 to Licenses DPR-49 & DPR-56, providing operability & surveillance requirements for scram discharge vol vent & drain isolation valves.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/01. 12pp. 17523:120. 24X Fiche: 50-277, 83/03/01, 8303110151.

--8303110157 Safety evaluation supporting Amend 90 to Licenses DPR-44 & DPR-56.
* Office of Nuclear Reactor Regulation, Director. 83/03/01. 2pp. 17523:132. 24X Fiche: 50-277, 83/03/01, 8303110151.

--8303110159 Notice of issuance & availability of Amend 90 to Licenses DPR-44 & DPR-56.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/01. 2pp. 17523:134. 24X Fiche: 50-277, 83/03/01, 8303110151.

8303110509 Forwards Amends 89 to Licenses DPR-44 & DPR-56, safety evaluation & notice of issuance & availability. Amends change core spray sparger differential alarm setpoint requirement to 1 plus/minus 1.5 psid.
GEARS, G. E. Operating Reactors Branch 4. 83/03/01. BAUER, E. G. Philadelphia Electric Co. 3pp. 17523:097. 24X
Fiche: 50-277, 83/03/01, 8303110509.

--8303110525 Amends 89 to Licenses DPR-44 & DPR-56, changing core spray sparger differential setpoint requirement to 1 plus/minus 1.5 psid.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/01. 8pp.
17523:100. 24X Fiche 50-277, 83/03/01, 8303110509.

--8303110534 Safety evaluation supporting Amends 89 to Licenses DPR-44 & DPR-56.
* Office of Nuclear Reactor Regulation, Director. 83/03/01. 4pp.
17523:108. 24X Fiche 50-277, 83/03/01, 8303110509.

--8303110544 Notice of issuance & availability of Amends 89 to Licenses DPR-44 & DPR-56.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/01. 2pp.
17523:112. 24X Fiche 50-277, 83/03/01, 8303110509.

8303150683 Forwards Amend 88 to Licenses DPR-44 & DPR-56, safety evaluation & notice of issuance & availability. Amends provide limiting conditions for operation & surveillance requirements for scram discharge vol valves.
GEARS, G. Operating Reactors Branch 4. 83/03/01. BAUER, E. G.
Philadelphia Electric Co. 2pp. 17584:001. 24X
Fiche 50-277, 83/03/01, 8303150683.

--8303150692 Amend 88 to Licenses DPR-44 & DPR-56, providing limiting conditions for operation & surveillance requirements for scram discharge vol valves.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/01. 21pp.
17584:003. 24X Fiche 50-277, 83/03/01, 8303150683.

--8303150697 Safety evaluation supporting Amend 88 to Licenses DPR-44 & DPR-56.
* Office of Nuclear Reactor Regulation, Director. 83/03/01. 3pp.
17584:025. 24X Fiche 50-277, 83/03/01, 8303150683.

--8112240161 "BWR Scram Discharge Vol Long-Term Mods," technical evaluation rept.
MUCHA, E. Franklin Institute/Franklin Research Center.
NRC-03-81-130. TER-C5506-68/72. 81/12/31. 67pp. 17584:028. 24X
Fiche 50-277, 83/03/01, 8303150683.

--8303150705 Notice of issuance & availability of Amend 88 to Licenses DPR-44 & DPR-56.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/01. 2pp.
17584:095. 24X Fiche 50-277, 83/03/01, 8303150683.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated
Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche 50-000, 83/03/02, 8303020321.

8303090418 Notification of 830323 meeting w/util & GE in Bethesda, MD to discuss GE Hybrid I control rod assembly & Unit 3 reload.
GEARS, G. Operating Reactors Branch 4. STOLZ, J.
Operating Reactors Branch 4. 2pp. 17482:336. 24X
Fiche 50-277, 83/03/02, 8303090418.

8303070071 Forwards addl info re safety-relief valve operability test required by NUREG-0737, Item II.D.1, "Reliability Engineering," per NRC 830105 request.
DALTROFF, S. L. Philadelphia Electric Co. 83/03/03. STOLZ, J. F.
Operating Reactors Branch 4. 19pp. 17434:302. 24X
Fiche 50-277, 83/03/03, 8303070071.

8303110329 Forwards info on NUREG-0737, Item 2.F.1.4, "Containment Pressure Monitor," Item 2.F.1.5, "Containment Water Level Monitor" & Item 2.F.1.6, "Containment Hydrogen Monitor," in response to NRC 830105 request.
DALTROFF, S. L. Philadelphia Electric Co. 83/03/04. STOLZ, J. F.
Operating Reactors Branch 4. 15pp. 17512:339. 24X
Fiche 50-277, 83/03/04, 8303110329.

8303150571 Forwards corrected Pp 186 & 187 for 821215 amend application, adding addl primary containment isolation valves. P 186 indicates change w/vertical bar. P 187 corrects error re designation for valve MO-10-39A.
ALDEN, W. M. Philadelphia Electric Co. 83/03/04. GEARS, G. E. NRC -
No Detailed Affiliation Given. 1p. 17568:027. 24X
Fiche 50-277, 83/03/04, 8303150571.

--8303150577 Corrected Table 3.7.4 re primary containment testable isolation valves.
* Philadelphia Electric Co. 83/03/04. 3pp. 17568:028. 24X
Fiche 50-277, 83/03/04, 8303150571.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated
Edison Co. of New York, Inc. 5lpp. 17660:176. 24X
Fiche 50-000, 83/03/07, 8303040005.

8303150371 Forwards application for amend to Licenses DPR-44 & DPR-56, changing Tech Specs to correct listing of smoke detectors & revise requirements for control of high radiation area keys for clarification & consistency.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/11. DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. 1p. 17562:118. 24X
Fiche 50-277, 83/03/11, 8303150371.

--8303150379 Application for amend to Licenses DPR-44 & DPR-56, changing Tech Specs to correct listing of smoke detectors & revise requirements for control of high radiation area keys for clarification & consistency.
DALTROFF, S. L., BAUER, E. G., BRADLEY, E. J. Philadelphia Electric Co.
83/03/11. 8pp. 17562:119. 24X Fiche 50-277, 83/03/11, 8303150371.

--8303150385 Proposed changes to Tech Specs correcting list of smoke detectors & revising requirements for control of high radiation area keys for clarification & consistency.
* Philadelphia Electric Co. 83/03/11. 5pp. 17562:127. 24X
Fiche 50-277, 83/03/11, 8303150371.

8303180130 Summary of 830303 meeting w/util re util findings of failure of electrical control switches of type used for ECCS room coolers, during environ qualification testing.
GEARS, G. Operating Reactors Branch 4. 83/03/11. Operating
Reactors Branch 4. 3pp. 17625:137. 24X Fiche 50-277, 83/03/11,
8303180130.

8303170339 Provides reason for sys design change & proposes new functional test frequency for degraded grid voltage protection. Addl auxiliary relay added to each tripping scheme to facilitate sys testing of units at power.
DALTROFF, S. L. Philadelphia Electric Co. 83/03/14. STOLZ, J. F.
Operating Reactors Branch 4. 3pp. 17605:176. 24X
Fiche 50-277, 83/03/14, 8303170339.

8303290398 Forwards order confirming util commitment to implement post-TMI items contained in NUREG-0737 & in responses to Generic Ltrs 82-05 & 82-10.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/14. BAUER, E. G.
Philadelphia Electric Co. 3pp. 17729:023. 24X
Fiche 50-277, 83/03/14, 8303290398.

--8303290405 Order confirming util commitment to implement post-TMI items contained in NUREG-0737 & in responses to Generic Ltrs 82-05 & 82-10.
PURPLE, R. A. Division of Licensing. 83/03/14. Philadelphia
Electric Co. 8pp. 17729:026. 24X Fiche 50-277, 83/03/14,
8303290398.

8303180327 Provides info & justification for continued operation re failure of electrical control stations of type used for ECCS room coolers during environ qualification testing, per 830303 meeting.
DALTROFF, S. L. Philadelphia Electric Co. 83/03/16. STOLZ, J. F.
Operating Reactors Branch 4. 6pp. 17619:297. 24X
Fiche 50-277, 83/03/16, 8303180327.

8303280085 Forwards safety evaluations re RCIC & HPCI initiation level separation & proposed mod to RCIC sys to allow automatic restart following sys trip per TMI Action Item II.K.3.13, in response to 801001 & 1229 ltrs, respectively.
STOLZ, J. Operating Reactors Branch 4. 83/03/16. BAUER, E. G.
Philadelphia Electric Co. 3pp. 17726:337. 24X
Fiche 50-277, 83/03/16, 8303280085.

--8303280088 Safety evaluation re BWR Owners Group 801001 response on separation of HPCI & RCIC sys initiation levels. NRC concurs w/GE analysis.
* Office of Nuclear Reactor Regulation, Director. 83/03/16. 3pp.
17726:340. 24X Fiche 50-277, 83/03/16, 8303280085.

--8303280089 Safety evaluation re BWR Owners Group 801229 proposed change for RCIC sys automatic restart. Proposed change to logic circuits of RCIC sys acceptable.
* Office of Nuclear Reactor Regulation, Director. 83/03/16. 7pp.
17726:343. 24X Fiche 50-277, 83/03/16, 8303280085.

8303310021 Requests supplemental response to NRC 821220 environ qualification safety evaluation to justify continued operation of all safety-related electrical equipment. Response requested within 30 days. Guidelines encl.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/22. BAUER, E. G.
Philadelphia Electric Co. 6pp. 17777:346. 24X
Fiche 50-277, 83/03/22, 8303310021.

# DOCKETED ITEMS

8303290303 Forwards Rev 1 to "Improved Dynamic Vacuum Breaker Valve Response for Peach Bottom," per Generic Ltr 83-08 Wetwell/drywell vacuum breakers will perform design function w/o further mod.
KEMPER, J. S. Philadelphia Electric Co. 83/03/25. EISENHUT, D. G. Division of Licensing. 1p. 17718:101. 24X Fiche: 50-277, 83/03/25, 8303290303.

--8303290305 Rev 1 to "Improved Dynamic Vacuum Breaker Valve Response for Peach Bottom."
* Continuum Dynamics, Inc. 82-10 R01. 82/09/30. 21pp. 17718:102. 24X Fiche: 50-277, 83/03/25, 8303290303.

G. Inspection reports, IE Bulletins & correspondence

8301310278 Forwards IE Insp Repts 50-277/82-24 & 50-278/82-23 on 821213-16 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/01/18.
DALTROFF, S. L. Philadelphia Electric Co. 2pp. 16969:115. 24X Fiche: 50-277, 83/01/18, 8301310278.

--8301310284 Notice of violation from insp on 821213-16.
* Division of Engineering & Technical Programs. 83/01/18. 2pp. 16969:117. 24X Fiche: 50-277, 83/01/18, 8301310278.

--8301310290 IE Insp Repts 50-277/82-24 & 50-278/82-23 on 821213-16. Noncompliance noted: failure to meet fire brigade training requirements.
PLISCO, L. R., ANDERSON, C. J. Division of Engineering & Technical Programs. 83/01/10. 11pp. 16969:119. 24X Fiche: 50-277, 83/01/18, 8301310278.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303080359 Ack receipt of 830217 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/82-24 & 50-278/82-23.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/02.
DALTROFF, S. L. Philadelphia Electric Co. 1p. 17453:335. 24X Fiche: 50-277, 83/03/02, 8303080359.

--8303080373 Responds to NRC 830118 ltr re violations noted in IE Insp Repts 50-277/82-24 & 50-278/82-23. Corrective actions: individuals missing fire brigade training scheduled for next available class. Fire brigade program updated.
DALTROFF, S. L. Philadelphia Electric Co. 83/02/17. MARTIN, T. T. Division of Engineering & Technical Programs. 4pp. 17453:336. 24X Fiche: 50-277, 83/03/02, 8303080359.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303250052 Forwards IE Insp Repts 50-277/83-02 & 50-278/83-02 on 830111-0224 & notice of violation.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/11.
DALTROFF, S. L. Philadelphia Electric Co. 2pp. 17691:295. 24X Fiche: 50-277, 83/03/11, 8303250052.

--8303250058 Notice of violation from insp on 830111-0224.
* Region 1, Office of Director. 83/02/28. 1p. 17691:297. 24X Fiche: 50-277, 83/03/11, 8303250052.

--8303250070 IE Insp Repts 50-277/83-02 & 50-278/83-02 on 830111-0224. Noncompliance noted: inadequate design control of containment atmosphere dilution ref gas supply & failure to keep fire doors closed.
BLOUGH, A. R., MCCABE, E. C. Region 1, Office of Director. 83/03/07. 22pp. 17691:298. 24X Fiche: 50-277, 83/03/11, 8303250052.

8303280271 Forwards IE Insp Repts 50-277/83-01 & 50-278/83-01 on 830110-14. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/14.
DALTROFF, S. L. Philadelphia Electric Co. 2pp. 17706:237. 24X Fiche: 50-277, 83/03/14, 8303280271.

--8303280283 IE Insp Repts 50-277/83-01 & 50-278/83-01 on 830110-14. No noncompliance noted. Major areas inspected: followup of emergency preparedness items from B11207-17 appraisal.
TERC, N. M., COHEN, I., CROCKER, H. W. Region 1, Office of Director. 83/03/09. 15pp. 17706:239. 24X Fiche: 50-277, 83/03/14, 8303280271.

8303240443 Ack receipt of 830225 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/82-25 & 50-278/82-24.
STAPOSTECKI, R. Division of Project & Resident Programs. 83/03/15.
DALTROFF, S. L. Philadelphia Electric Co. 1p. 17678:010. 24X Fiche: 50-277, 83/03/15, 8303240443.

--8303240450 Responds to NRC 830128 ltr re violations noted in IE Insp Repts 50-277/82-25 & 50-278/82-24. Corrective actions: individual restraint secured checkoff will be required for each seismic bottle & surveillance test personnel counseled.
GALLAGHER, J. W. Philadelphia Electric Co. 83/02/25.
STAROSTECKI, R. Division of Engineering & Technical Programs. 3pp. 17678:011. 24X Fiche: 50-277, 83/03/15, 8303240443.

8303220211 Submits addl info re IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel)," per 830121 request. Velocity profile at intake structure minimizes intrusion.
DALTROFF, S. L. Philadelphia Electric Co. 83/03/17. JORDAN, E. L. Division of Engineering & Quality Assurance (Pre 830103). 2pp. 17657:135. 24X Fiche: 50-277, 83/03/17, 8303220211.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 12?pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303280043 EN-83-019 on 830329, notice of violation & proposed imposition of civil penalty in amount of $140,000 to be issued. Action based on failure to maintain mgt attention at level necessary to assure adherence to plant procedures.
FLACK, E., KLINGLER, G., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 83/03/24. 1p. 17707:313. 24X Fiche: 50-277, 83/03/24, 8303280043.

R. Periodic operating reports & related correspondence

8303080452 Forwards monthly operating repts for Dec 1982.
COONEY, M. J. Philadelphia Electric Co. 83/01/10. Director's Office, Office of Inspection and Enforcement. 1p. 17453:136. 24X Fiche: 50-277, 83/01/10, 8303080452.

--8303080458 Monthly operating repts for Dec 1982.
ALDEN, W. M. Philadelphia Electric Co. 83/01/10. 10pp. 17453:137. 24X Fiche: 50-277, 83/01/10, 8303080452.

8303090118 Forwards "Semiannual Effluent Releases Rept 14, Peach Bottom Atomic Power Station, Units 2 & 3, Jul-Dec 1982."
ALDEN, W. M. Philadelphia Electric Co. 83/02/28. HAYNES, R. C. Region 1, Office of Director. 1p. 17470:284. 24X Fiche: 50-277, 83/02/28, 8303090118.

--8303090122 "Semiannual Effluent Releases Rept 14, Peach Bottom Atomic Power Station, Units 2 & 3, Jul-Dec 1982."
* Philadelphia Electric Co. 83/02/28. 12pp. 17470:285. 24X Fiche: 50-277, 83/02/28, 8303090118.

8303160559 Forwards "Annual Occupational Exposure Rept 7, 1982."
ALDEN, W. M. Philadelphia Electric Co. 83/02/28. HAYNES, R. C. Region 1, Office of Director. 1p. 17587:079. 24X Fiche: 50-277, 83/02/28, 8303160559.

--8303160567 "Annual Occupational Exposure Rept 7, 1982."
FLEISCHMANN, R. Philadelphia Electric Co. 83/02/28. 5pp. 17587:080. 24X Fiche: 50-277, 83/02/28, 8303160559.

8303160332 Forwards monthly operating repts for Feb 1983.
COONEY, M. J. Philadelphia Electric Co. 83/03/11. Director's Office, Office of Inspection and Enforcement. 1p. 17596:049. 24X Fiche: 50-277, 83/03/11, 8303160332.

--8303160338 Monthly operating repts for Feb 1983.
ALDEN, W. M. Philadelphia Electric Co. 83/03/10. 9pp. 17596:050. 24X Fiche: 50-277, 83/03/11, 8303160332.

S. Reportable occurrences, LERs & related correspondence

8303080385 Forwards LER 83-001/01X-1. Detailed event analysis submitted.
COONEY, M. J. Philadelphia Electric Co. 83/02/18. HAYNES, R. C. Region 1, Office of Director. 3pp. 17452:353. 24X Fiche: 50-277, 83/02/18, 8303080385.

--8303080395 LER 83-001/01X-1 on 830104, switch similar to type used in ECCS room coolers failed during environ qualification test. Caused by embrittled & cracked nylon cam matl on switch. Switch jumpered. Replacement considered.
COONEY, M. J. Philadelphia Electric Co. 83/02/18. Region 1. Office of Director. 1p. 17452:356. 24X Fiche: 50-277, 83/02/18, 8303080385.

8303030761 Notification of 830303 meeting w/util & Franklin Research Ctr in Bethesda, MD to discuss failure of electrical control switch during high radiation environ qualification testing.
GEARS, G. Operating Reactors Branch 4. 83/02/25. STOLZ, J. Operating Reactors Branch 4. 2pp. 17363:225. 24X Fiche: 50-277, 83/02/25, 8303030761.

8303160190 LER 83-003/03L-0 on 830206, coolant leak discovered in cooling sys of diesel driven fire pump. Caused by leaking water pump shaft seal. Replacement pump placed in svc on 830209.
COONEY, M. J. Philadelphia Electric Co. 83/03/04. HAYNES, R. C. Region 1, Office of Director. 1p. 17596:170. 24X Fiche: 50-277, 83/03/04, 8303160190.

8303280238 Part 21 rept re discovery of failed switch operator cam 14 within position selector switch 4, operating ECCS pump room cooler. Initially reported on 830104. Caused by cam matl fracturing into small pieces. Jumpers installed.
DALTROFF, S. L. Philadelphia Electric Co. 83/03/23. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 6pp. 17708:161. 24X Fiche: 50-277, 83/03/23, 8303280238.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NOSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303030079 Responds to Generic Ltr 83-01 re operator licensing exam site visits through 1985.
GALLAGHER, J. W. Philadelphia Electric Co. 83/02/24. EISENHUT, D. G. Division of Licensing. 3pp. 17413:229. 24X Fiche: 50-000, 83/02/24, 8303030079.

DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

8301310278 Forwards IE Insp Repts 50-277/82-24 & 50-278/82-23 on 821213-16 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/01/18. DALTROFF, S. L. Philadelphia Electric Co. 2pp. 16969:115. 24X Fiche: 50-277, 83/01/18, 8301310278.

--8301310290 IE Insp Repts 50-277/82-24 & 50-278/82-23 on 821213-16. Noncompliance noted: failure to meet fire brigade training requirements.
PLISCO, L. R. Division of Engineering & Technical Programs. 83/01/10. 11pp. 16969:119. 24X Fiche: 50-277, 83/01/18, 8301310278.

8303040523 Requests exemption from schedule requirements of 10CFR50.48C (2) & (c)(3) to permit completion of fire protection mods identified in 820628 safe shutdown rept. Proposed mod schedule, revised Section 6 & mod tabulations encl.
GALLAGHER, J. W. Philadelphia Electric Co. 83/02/25. EISENHUT, D. G. Division of Licensing. 19pp. 17367:342. 24X Fiche: 50-277, 83/02/25, 8303040523.

8303090454 Notification of 830309 meeting w/util & consultant in Bethesda, MD to discuss App R exemption requests.
GEARS, G. Operating Reactors Branch 4. 83/03/01. STOLZ, J. Operating Reactors Branch 4. 3pp. 17483:170. 24X Fiche: 50-277, 83/03/01, 8303090454.

8303080359 Ack receipt of 830217 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/82-24 & 50-278/82-23.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/02. DALTROFF, S. L. Philadelphia Electric Co. 1p. 17453:335. 24X Fiche: 50-277, 83/03/02, 8303080359.

--8303080373 Responds to NRC 830118 ltr re violations noted in IE Insp Repts 50-277/82-24 & 50-278/82-23. Corrective actions: individuals missing fire brigade training scheduled for next available class. Fire brigade program updated.
DALTROFF, S. L. Philadelphia Electric Co. 83/02/17. MARTIN, T. T. Division of Engineering & Technical Programs. 4pp. 17453:336. 24X Fiche: 50-277, 83/03/02, 8303080359.

8303150371 Forwards application for amend to Licenses DPR-44 & DPR-56, changing Tech Specs to correct listing of smoke detectors & revise requirements for control of high radiation area keys for clarification & consistency.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/11. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17562:118. 24X Fiche: 50-277, 83/03/11, 8303150371.

--8303150379 Application for amend to Licenses DPR-44 & DPR-56, changing Tech Specs to correct listing of smoke detectors & revise requirements for control of high radiation area keys for clarification & consistency.
DALTROFF, S. L. Philadelphia Electric Co. 83/03/11. 8pp. 17562:119. 24X Fiche: 50-277, 83/03/11, 8303150371.

--8303150385 Proposed changes to Tech Specs correcting list of smoke detectors & revising requirements for control of high radiation area keys for clarification & consistency.
* Philadelphia Electric Co. 83/03/11. 5pp. 17562:127. 24X Fiche: 50-277, 83/03/11, 8303150371.

8303250052 Forwards IE Insp Repts 50-277/83-02 & 50-278/83-02 on 830111-0224 & notice of violation.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/11. DALTROFF, S. L. Philadelphia Electric Co. 2pp. 17691:295. 24X Fiche: 50-277, 83/03/11, 8303250052.

--8303250058 Notice of violation from insp on 830111-0224.
* Region 1, Office of Director. 83/02/28. 1p. 17691:297. 24X Fiche: 50-277, 83/03/11, 8303250052.

--8303250070 IE Insp Repts 50-277/83-02 & 50-278/83-02 on 830111-0224. Noncompliance noted: inadequate design control of containment atmosphere dilution ref gas supply & failure to keep fire doors closed.
BLOUGH, A. R. Region 1, Office of Director. 83/03/07. 22pp. 17691:298. 24X Fiche: 50-277, 83/03/11, 8303250052.

8303280271 Forwards IE Insp Repts 50-277/83-01 & 50-278/83-01 on 830110-14. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/14. DALTROFF, S. L. Philadelphia Electric Co. 2pp. 17706:237. 24X Fiche: 50-277, 83/03/14, 8303280271.

--8303280283 IE Insp Repts 50-277/83-01 & 50-278/83-01 on 830110-14. No noncompliance noted. Major areas inspected: followup of emergency preparedness items from 811207-17 appraisal.
TERC, N. M. Region 1, Office of Director. 83/03/09. 15pp. 17706:239. 24X Fiche: 50-277, 83/03/14, 8303280271.

8303290541 Summary of 830309 meeting w/util re App R exemption requests. Supporting info necessary for NRC determination outlined. Alternative safe shutdown capability proposed.
GEARS, G. Operating Reactors Branch 4. 83/03/21. Operating Reactors Branch 4. 3pp. 17740:358. 24X Fiche: 50-277, 83/03/21, 8303290541.

8303280277 Identifies correspondence providing util response to unresolved items discussed in NRC 801124 ltr. Addl info re fire detector installation to meet 10CFR50, App R provided & exemption from fire detection requirements requested.
DALTROFF, S. L. Philadelphia Electric Co. 83/03/24. STOLZ, J. F. Operating Reactors Branch 4. 4pp. 17706:230. 24X Fiche: 50-277, 83/03/24, 8303280277.

8303300581 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/24. Document Management Branch. 1p. 17765:333. 24X Fiche: 50-277, 83/03/24, 8303300581.

--8303300588 Forwards public version of revised Emergency Plan Implementing Procedures EP-103, "Alert Response," EP-104, "Site Emergency Response" & EP-105, "General Emergency Response."
DALTROFF, S. L. Philadelphia Electric Co. 83/02/14. HAYNES, R. C. Region 1, Office of Director. 2pp. 17765:334. 24X Fiche: 50-277, 83/03/24, 8303300581.

--8303300594 Public version of revised Emergency Plan Implementing Procedures EP-103, "Alert Response," EP-104, "Site Emergency Response" & EP-105, "General Emergency Response." Revised index encl.
* Philadelphia Electric Co. 83/01/12. 32pp. 17765:336. 24X Fiche: 50-277, 83/03/24, 8303300581.

8303300389 Discusses problems associated w/emergency notification sys siren located adjacent to R Eshleman property in Nottingham, PA. No response required.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/25. DALTROFF, S. L. Philadelphia Electric Co. 2pp. 17731:070. 24X Fiche: 50-277, 83/03/25, 8303300389.

Q. Adjudicatory correspondence

8303020063 Response opposing util motion to strike C Kepford supplemental affidavit re qualifications as expert witness. Intervenors unable to respond in detail since motion never received. Certificate of Svc encl.
JOHNSRUD, J. H. Environmental Coalition on Nuclear Power 83/02/24, Commissioners 2pp 17352:136 24X Fiche: 50-000, 83/02/24, 8303020063.

I. Financial information

8303170139 Forwards Annual Financial Repts 1982 & 1983.
BRADLEY, E. J. Philadelphia Electric Co 83/03/14 SALTZMAN, J. Assistant Director for State & Licensee Relations 7pp 17605:183 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170169 Annual Financial Rept 1982.
SMITH, R. I. , SONN, H. W. Public Service Electric & Gas Co. of New Jersey 83/02/14 52pp 17605:191 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170182 Annual Financial Rept 1982.
EVERETT, J. L. , AUSTIN, J. H. Philadelphia Electric Co 83/03/14 41pp 17605:243 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170193 Annual Financial Rept 1982.
WEIMER, R. D. , CURTIS, N. M. Delmarva Power & Light Co 83/02/04 44pp 17605:287 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170206 Annual Financial Rept 1982.
FEEHAN, J. D. Atlantic Electric of New Jersey 83/03/14 42pp 17605:333 24X Fiche: 50-000, 83/03/14, 8303170159.

J. Insurance & indemnity information

8303080205 Forwards Endorsement 100 to NELIA Policy NF-140 & Endorsement 54 to MAELU Policy MF-67.
BRADLEY, E. J. Philadelphia Electric Co 83/02/28 SALTZMAN, J. Assistant Director for State & Licensee Relations 3pp 17457:075 24X Fiche: 50-277, 83/02/28, 8303080205.

8303100358 Requests indemnity fee refund reflecting reduction in annual fee.
BRADLEY, E. J. Philadelphia Electric Co 83/03/07 SALTZMAN, J. Assistant Director for State & Licensee Relations 2pp 17488:293 24X Fiche: 50-277, 83/03/07, 8303100358.

8303290350 Forwards Endorsements 101 & 7 to NELIA Policy NF-140 & Master Policy 1, respectively.
BRADLEY, E. J. Philadelphia Electric Co 83/03/23 SALTZMAN, J. Assistant Director for State & Licensee Relations 3pp 17716:163 24X Fiche: 50-277, 83/03/23, 8303290350.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X Fiche: 50-000, 83/02/16, 8302170082.

8303040385 Forwards safety evaluation of util response to NUREG-0737, Item I.A.2.1.4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & Item II.B.4.1, "Training for Mitigating Core Damage." Item closed.
STOLZ, J. F. Operating Reactors Branch 4 83/02/17 BAUER, E. G. Philadelphia Electric Co. 2pp 17426:321 24X Fiche: 50-277, 83/02/17, 8303040385.

--8303040391 Safety evaluation supporting util response to NUREG-0737, Item I.A.2.1.4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & Item II.B.4.1, "Training for Mitigating Core Damage."
HAVERKAMP, D. R. Operating Reactors Branch 4 83/02/17 5pp 17426:323 24X Fiche: 50-277, 83/02/17, 8303040365.

--8208310332 "Improvements in Training & Requalification Programs as Required by TMI Action Items I.A.2.1 & II.B.4 for Peach Bottom Atomic Power Station," technical evaluation rept.
* Science Applications, Inc NRC-03-82-096 SAI-186-029-48 82/08/26 NRC - No Detailed Affiliation Given 14pp 17426:328 24X Fiche: 50-277, 83/02/17, 8303040385.

8303020420 Forwards Amend 87 to Licenses DPR-44 & DPR-56, safety evaluation & notice of issuance & availability. Amend changes Tech Specs re surveillance requirements to permit alternate method for performing core spray loop flow rate test.
GEARS, G. E. Operating Reactors Branch 4 83/02/18 BAUER, E. G. Philadelphia Electric Co. 3pp 17357:290 24X Fiche: 50-277, 83/02/18, 8303020420.

--8303020423 Amend 87 to Licenses DPR-44 & DPR-56, changing Tech Specs re surveillance requirements to permit alternate method for performing core spray loop flow rate test.
STOLZ, J. F. Operating Reactors Branch 4 83/02/18 10pp 17357:293 24X Fiche: 50-277, 83/02/18, 8303020420.

--8303020426 Safety evaluation supporting Amend 87 to Licenses DPR-44 & DPR-56.
* Office of Nuclear Reactor Regulation, Director 83/02/18 2pp 17357:303 24X Fiche: 50-277, 83/02/18, 8303020420.

--8303020429 Notice of issuance & availability of Amend 87 to Licenses DPR-44 & DPR-56.
STOLZ, J. F. Operating Reactors Branch 4 83/02/18 2pp 17357:305 24X Fiche: 50-277, 83/02/18, 8303020420.

8303110151 Forwards Amend 90 to Licenses DPR-44 & DPR-56, safety evaluation & notice of issuance & availability. Amend provides operability & surveillance requirements for scram discharge vol vent & drain isolation valves.
GEARS, G. E. Operating Reactors Branch 4 83/03/01 BAUER, E. G. Boston Edison Co. 2pp 17523:118 24X Fiche: 50-277, 83/03/01, 8303110151.

--8303110154 Amend 90 to Licenses DPR-49 & DPR-56, providing operability & surveillance requirements for scram discharge vol vent & drain isolation valves.
STOLZ, J. F. Operating Reactors Branch 4 83/03/01 12pp 17523:120 24X Fiche: 50-277, 83/03/01, 8303110151.

--8303110157 Safety evaluation supporting Amend 90 to Licenses DPR-44 & DPR-56.
* Office of Nuclear Reactor Regulation, Director 83/03/01 2pp 17523:132 24X Fiche: 50-277, 83/03/01, 8303110151.

--8303110159 Notice of issuance & availability of Amend 90 to Licenses DPR-44 & DPR-56.
STOLZ, J. F. Operating Reactors Branch 4 83/03/01 2pp 17523:134 24X Fiche: 50-277, 83/03/01, 8303110151.

8303110509 Forwards Amends 89 to Licenses DPR-44 & DPR-56, safety evaluation & notice of issuance & availability. Amends change core spray sparger differential alarm setpoint requirement to 1 plus/minus 1.5 psid.
GEARS, G. E. Operating Reactors Branch 4 83/03/01 BAUER, E. G. Philadelphia Electric Co. 3pp 17523:097 24X Fiche: 50-277, 83/03/01, 8303110509.

--8303110525 Amends 89 to Licenses DPR-44 & DPR-56, changing core spray sparger differential setpoint requirement to 1 plus/minus 1.5 psid.
STOLZ, J. F. Operating Reactors Branch 4 83/03/01 8pp 17523:100 24X Fiche: 50-277, 83/03/01, 8303110509.

--8303110534 Safety evaluation supporting Amends 89 to Licenses DPR-44 & DPR-56.
* Office of Nuclear Reactor Regulation, Director 83/03/01 4pp 17523:108 24X Fiche: 50-277, 83/03/01, 8303110509.

--8303110544 Notice of issuance & availability of Amends 89 to Licenses DPR-44 & DPR-56.
STOLZ, J. F. Operating Reactors Branch 4 83/03/01 2pp 17523:112 24X Fiche: 50-277, 83/03/01, 8303110509.

8303150680 Forwards Amend 88 to Licenses DPR-44 & DPR-56, safety evaluation & notice of issuance & availability. Amends provide limiting conditions for operation & surveillance requirements for scram discharge vol valves.
GEARS, G. Operating Reactors Branch 4 83/03/01 BAUER, E. G. Philadelphia Electric Co. 2pp 17584:001 24X Fiche: 50-277, 83/03/01, 8303150683.

--8303150692 Amend 88 to Licenses DPR-44 & DPR-56, providing limiting conditions for operation & surveillance requirements for scram discharge vol valves.
STOLZ, J. F. Operating Reactors Branch 4 83/03/01 21pp 17584:003 24X Fiche: 50-277, 83/03/01, 8303150683.

--8303150697 Safety evaluation supporting Amend 88 to Licenses DPR-44 & DPR-56.
* Office of Nuclear Reactor Regulation, Director 83/03/01 3pp 17584:025 24X Fiche: 50-277, 83/03/01, 8303150683.

--8112240161 "BWR Scram Discharge Vol Long-Term Mods." technical evaluation rept.
MUCHA, E. Franklin Institute/Franklin Research Center. NRC-03-81-130. TER-C5506-68/72. 81/12/31. 67pp. 17584:028. 24X Fiche: 50-277, 83/03/01, 8303150683.

--8303150705 Notice of issuance & availability of Amend 88 to Licenses DPR-44 & DPR-56.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/01. 2pp. 17584:095. 24X Fiche: 50-277, 83/03/01, 8303150683.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303090418 Notification of 830323 meeting w/util & GE in Bethesda, MD to discuss GE Hybrid I control rod assembly & Unit 3 reload.
GEARS, G. Operating Reactors Branch 4. 83/03/02. STOLZ, J. Operating Reactors Branch 4. 2pp. 17482:336. 24X Fiche: 50-277, 83/03/02, 8303090418.

8303070071 Forwards addl info re safety-relief valve operability test required by NUREG-0737, Item II.D.1, "Reliability Engineering," per NRC 830105 request.
DALTROFF, S. L. Philadelphia Electric Co. 83/03/03. STOLZ, J. F. Operating Reactors Branch 4. 19pp. 17434:302. 24X Fiche: 50-277, 83/03/03, 8303070071.

8303110329 Forwards info on NUREG-0737, Item 2.F.1.4, "Containment Pressure Monitor," Item 2.F.1.5, "Containment Water Level Monitor" & Item 2.F.1.6, "Containment Hydrogen Monitor," in response to NRC 830105 request.
DALTROFF, S. L. Philadelphia Electric Co. 83/03/04. STOLZ, J. F. Operating Reactors Branch 4. 15pp. 17512:339. 24X Fiche: 50-277, 83/03/04, 8303110329.

8303150571 Forwards corrected Pp 186 & 187 for 821215 amend application, adding addl primary containment isolation valves. P 186 indicates change w/vertical bar. P 187 corrects error re designation for valve MO-10-39A.
ALDEN, W. H. Philadelphia Electric Co. 83/03/04. GEARS, G. E. NRC - No Detailed Affiliation Given. 1p. 17568:027. 24X Fiche: 50-277, 83/03/04, 8303150571.

--8303150577 Corrected Table 3.7.4 re primary containment testable isolation valves.
* Philadelphia Electric Co. 83/03/04. 3pp. 17568:028. 24X Fiche: 50-277, 83/03/04, 8303150571.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303150371 Forwards application for amend to Licenses DPR-44 & DPR-56, changing Tech Specs to correct listing of smoke detectors & revise requirements for control of high radiation area keys for clarification & consistency.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/11. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17562:118. 24X Fiche: 50-277, 83/03/11, 8303150371.

--8303150379 Application for amend to Licenses DPR-44 & DPR-56, changing Tech Specs to correct listing of smoke detectors & revise requirements for control of high radiation area keys for clarification & consistency.
DALTROFF, S. L., BAUER, E. G., BRADLEY, E. J. Philadelphia Electric Co. 83/03/11. 8pp. 17562:119. 24X Fiche: 50-277, 83/03/11, 8303150371.

--8303150385 Proposed changes to Tech Specs correcting list of smoke detectors & revising requirements for control of high radiation area keys for clarification & consistency.
* Philadelphia Electric Co. 83/03/11. 3pp. 17562:127. 24X Fiche: 50-277, 83/03/11, 8303150371.

8303180130 Summary of 830303 meeting w/util re util findings of failure of electrical control switches of type used for ECCS room coolers during environ qualification testing.
GEARS, G. Operating Reactors Branch 4. 83/03/11. Operating Reactors Branch 4. 3pp. 17625:137. 24X Fiche: 50-277, 83/03/11, 8303180130.

8303170339 Provides reason for sys design change & proposes new functional test frequency for degraded grid voltage protection Addl auxiliary relay added to each tripping scheme to facilitate sys testing of units at power.
DALTROFF, S. L. Philadelphia Electric Co. 83/03/14. STOLZ, J. F. Operating Reactors Branch 4. 3pp. 17605:176. 24X Fiche: 50-277, 83/03/14, 8303170339.

8303290398 Forwards order confirming util commitment to implement post-TMI items contained in NUREG-0737 & in responses to Generic Ltrs 82-05 & 82-10.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/14. BAUER, E. G. Philadelphia Electric Co. 3pp. 17729:023. 24X Fiche: 50-277, 83/03/14, 8303290398.

--8303290405 Order confirming util commitment to implement post-TMI items contained in NUREG-0737 & in responses to Generic Ltrs 82-05 & 82-10.
PURPLE, R. A. Division of Licensing. 83/03/14. Philadelphia Electric Co. 8pp. 17729:026. 24X Fiche: 50-277, 83/03/14, 8303290398.

8303180327 Provides info & justification for continued operation re failure of electrical control stations of type used for ECCS room coolers during environ qualification testing, per 830303 meeting.
DALTROFF, S. L. Philadelphia Electric Co. 83/03/16. STOLZ, J. F. Operating Reactors Branch 4. 6pp. 17619:297. 24X Fiche: 50-277, 83/03/16, 8303180327.

8303280085 Forwards safety evaluations re RCIC & HPCI initiation level separation & proposed mod to RCIC sys to allow automatic restart following sys trip per TMI Action Item II.K.3.13, in response to 801001 & 1229 ltrs, respectively.
STOLZ, J. Operating Reactors Branch 4. 83/03/16. BAUER, E. G. Philadelphia Electric Co. 3pp. 17726:337. 24X Fiche: 50-277, 83/03/16, 8303280085.

8303310021 Requests supplemental response to NRC 821220 environ qualification safety evaluation to justify continued operation of all safety-related electrical equipment. Response requested within 30 days. Guidelines encl.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/22. BAUER, E. G. Philadelphia Electric Co. 6pp. 17777:346. 24X Fiche: 50-277, 83/03/22, 8303310021.

8303290303 Forwards Rev 1 to "Improved Dynamic Vacuum Breaker Valve Response for Peach Bottom," per Generic Ltr 83-08. Wetwell/drywell vacuum breakers will perform design function w/o further mod.
KEMPER, J. S. Philadelphia Electric Co. 83/03/25. EISENHUT, D. G. Division of Licensing. 1p. 17718:101. 24X Fiche: 50-277, 83/03/25, 8303290303.

--8303290305 Rev 1 to "Improved Dynamic Vacuum Breaker Valve Response for Peach Bottom."
* Continuum Dynamics, Inc. 82-10 R01. 82/09/30. 21pp. 17718:102. 24X Fiche: 50-277, 83/03/25, 8303290303.

Q. Inspection reports, IE Bulletins & correspondence

8301310278 Forwards IE Insp Repts 50-277/82-24 & 50-278/82-23 on 821213-16 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/01/18. DALTROFF, S. L. Philadelphia Electric Co. 2pp. 16969:115. 24X Fiche: 50-277, 83/01/18, 8301310278.

--8301310284 Notice of violation from insp on 821213-16.
* Division of Engineering & Technical Programs. 83/01/18. 2pp. 16969:117. 24X Fiche: 50-277, 83/01/18, 8301310278.

--8301310290 IE Insp Repts 50-277/82-24 & 50-278/82-23 on 821213-16. Noncompliance noted: failure to meet fire brigade training requirements.
PLISCO, L. R., ANDERSON, C. J. Division of Engineering & Technical Programs. 83/01/10. 11pp. 16969:119. 24X Fiche: 50-277, 83/01/18, 8301310278.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303080359 Ack receipt of 830217 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/82-24 & 50-278/82-23.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/02. DALTROFF, S. L. Philadelphia Electric Co. 1p. 17453:335. 24X Fiche: 50-277, 83/03/02, 8303080359.

--8303080373 Responds to NRC 830118 ltr re violations noted in IE Insp Repts 50-277/82-24 & 50-278/82-23. Corrective actions: individuals missing fire brigade training scheduled for next available class. Fire brigade program updated.
DALTROFF, S. L. Philadelphia Electric Co. 83/02/17. MARTIN, T. T. Division of Engineering & Technical Programs. 4pp. 17453:336.
24X Fiche: 50-277, 83/03/02, 8303080359.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 1/611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303250052 Forwards IE Insp Repts 50-277/83-02 & 50-278/83-02 on 830111-0224 & notice of violation.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/11.
DALTROFF, S. L. Philadelphia Electric Co. 2pp. 17691:295. 24X
Fiche: 50-277, 83/03/11, 8303250052.

--8303250058 Notice of violation from insp on 830111-0224.
* Region 1, Office of Director. 83/02/28. 1p. 17691:297. 24X
Fiche: 50-277, 83/03/11, 8303250052.

--8303250070 IE Insp Repts 50-277/83-02 & 50-278/83-02 on 830111-0224. Noncompliance noted: inadequate design control of containment atmosphere dilution ref gas supply & failure to keep fire doors closed.
BLOUGH, A. R., MCCABE, E. C. Region 1, Office of Director. 83/03/07. 22pp. 17691:298. 24X Fiche: 50-277, 83/03/11, 8303250052.

8303280271 Forwards IE Insp Repts 50-277/83-01 & 50-278/83-01 on 830110-14. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/14.
DALTROFF, S. L. Philadelphia Electric Co. 2pp. 17706:237. 24X
Fiche: 50-277, 83/03/14, 8303280271.

--8303280283 IE Insp Repts 50-277/83-01 & 50-278/83-01 on 830110-14. No noncompliance noted. Major areas inspected: followup of emergency preparedness items from 811207-17 appraisal.
TERC, N. M., COHEN, I., CROCKER, H. W. Region 1, Office of Director. 83/03/09. 15pp. 17706:239. 24X Fiche: 50-277, 83/03/14, 8303280271.

8303240443 Ack receipt of 830225 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/82-25 & 50-278/32-24.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/15.
DALTROFF, S. L. Philadelphia Electric Co. 1p. 17678:010. 24X
Fiche: 50-277, 83/03/15, 8303240443.

--8303240450 Responds to NRC 830128 ltr re violations noted in IE Insp Repts 50-277/82-25 & 50-278/82-24. Corrective actions: individual restraint secured checkoff will be required for each seismic bottle & surveillance test personnel counseled.
GALLAGHER, J. W. Philadelphia Electric Co. 83/02/25.
STAROSTECKI, R. Division of Engineering & Technical Programs. 3pp.
17678:011. 24X Fiche: 50-277, 83/03/15, 8303240443.

8303220211 Submits addl info re IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp. (Asiatic Clam) & Mytilus Sp. (Mussel)," per 830121 request. Velocity profile at intake structure minimizes intrusion.
DALTROFF, S. L. Philadelphia Electric Co. 83/03/17. JORDAN, E. L. Division of Engineering & Quality Assurance (Pre 830103). 2pp.
17657:135. 24X Fiche: 50-277, 83/03/17, 8303220211.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303280043 EN-83-019 on 830329, notice of violation & proposed imposition of civil penalty in amount of $140,000 to be issued. Action based on failure to maintain mgt attention at level necessary to assure adherence to plant procedures.
FLACK, E., KLINGLER, G., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 83/03/24. 1p. 17707:313. 24X
Fiche: 50-277, 83/03/24, 8303280043.

R. Periodic operating reports & related correspondence

8303080452 Forwards monthly operating repts for Dec 1982.
COONEY, M. J. Philadelphia Electric Co. 83/01/10. Director's Office, Office of Inspection and Enforcement. 1p. 17455:136. 24X
Fiche: 50-277, 83/01/10, 8303080452.

--8303080458 Monthly operating repts for Dec 1982.
ALDEN, W. M. Philadelphia Electric Co. 83/01/10. 10pp. 17453:137.
24X Fiche: 50-277, 83/01/10, 8303080452.

8303090118 Forwards "Semiannual Effluent Releases Rept 14, Peach Bottom Atomic Power Station, Units 2 & 3, Jul-Dec 1982."
ALDEN, W. M. Philadelphia Electric Co. 83/02/28. HAYNES, R. C. Region 1, Office of Director. 1p. 17470:284. 24X Fiche: 50-277, 83/02/28, 8303090118.

--8303090122 "Semiannual Effluent Releases Rept 14, Peach Bottom Atomic Power Station, Units 2 & 3, Jul-Dec 1982."
* Philadelphia Elrctric Co. 83/02/28. 12pp. 17470:285. 24X
Fiche: 50-277, 83/02/28, 8303090118.

8303160559 Forwards "Annual Occupational Exposure Rept 7, 1982."
ALDEN, W. M. Philadelphia Electric Co. 83/02/28. HAYNES, R. C. Region 1, Office of Director. 1p. 17587:079. 24X Fiche: 50-277, 83/02/28, 8303160559.

--8303160567 "Annual Occupational Exposure Rept 7, 1982."
FLEISCHMANN, R. Philadelphia Electric Co. 83/02/28. 5pp.
17587:080. 24X Fiche: 50-277, 83/02/28, 8303160559.

8303160332 Forwards monthly operating repts for Feb 1983.
COONEY, M. J. Philadelphia Electric Co. 83/03/11. Director's Office, Office of Inspection and Enforcement. 1p. 17596:049. 24X
Fiche: 50-277, 83/03/11, 8303160332.

--8303160338 Monthly operating repts for Feb 1983.
ALDEN, W. M. Philadelphia Electric Co. 83/03/10. 9pp. 17596:050.
24X Fiche: 50-277, 83/03/11, 8303160332.

S. Reportable occurrences, LERs & related corresponuence

8303030761 Notification of 830303 meeting w/util & Franklin Research Ctr in Bethesda, MD to discuss failure of electrical control switch during high radiation environ qualification testing.
GEARS, G. Operating Reactors Branch 4. 83/02/25. STOLZ, J. Operating Reactors Branch 4. 2pp. 17363:225. 24X
Fiche: 50-277, 83/02/25, 8303030761.

8303140311 LER 83-003/03L-0 on 830127, HEA relay on emergency safeguard bus E23 tripped normal supply & locked out backup & diesel supplies. Caused by operation of relay on bus E23. Activating devices may be defective & will be bench tested.
* Philadelphia Electric Co. 83/02/25. HAYNES, R. C. Region 1, Office of Director. 1p. 17544:140. 24X Fiche: 50-278, 83/02/25, 8303140311.

8303140530 Forwards LER 83-008/01T-0. Detailed event analysis submitted.
COONEY, M. J. Philadelphia Electric Co. 83/02/28. HAYNES, R. C. Region 1, Office of Director. 3pp. 17534:184. 24X
Fiche: 50-278, 83/02/28, 8303140530.

--8303140537 LER 83-008/01T-0 on 830214, inboard main steam drain valve MO-2-74 & inboard MSIVs 80 A, C & D failed to meet Tech Spec leak test limits. Cause not known. Failed valves scheduled for maint. Thirty-day followup rept to be submitted after maint.
COONEY, M. J. Philadelphia Electric Co. 83/02/28. Region 1, Office of Director. 1p. 17534:187. 24X Fiche: 50-278, 83/02/28, 8303140530.

8303100327 PNO-I-83-015 on 830303, false low reactor water level signal caused start of two RHR pumps. Pumps injected 40,000 gallons of water to reactor vessel resulting in overflow & escape of radioactive water into plant storm drain.
ARCHITZEL, R., KEIMIG, R. R. Region 1, Office of Director. 83/03/04. 2pp. 17489:196. 24X Fiche: 50-278, 83/03/04, 8303100327.

8303290388 Updated LER 82-026/03X-1 on 821223, HPCI sys declared inoperable to investigate delayed opening of turbine stop valve upon sys initiation. Caused by failure of corroded steam trap to drain inlet steam line. Trap rebuilt.
COONEY, M. J. Philadelphia Electric Co. 83/03/14. HAYNES, R. C. Region 1, Office of Director. 1p. 17725:272. 24X
Fiche: 50-278, 83/03/14, 8303290388.

8303280238 Part 21 rept re discovery of failed switch operator cam 14 within position selector switch 4, operating ECCS pump room cooler. Initially reported on 830104. Caused by cam matl fracturing into small pieces. Jumpers installed.
DALTROFF, S. L. Philadelphia Electric Co. 83/03/23. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 6pp.
17708:161. 24X Fiche: 50-277, 83/03/23, 8303280238.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for CPs, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303030079 Responds to Generic Ltr 83-01 re operator licensing exam site visits through 1985.
GALLAGHER, J. W. Philadelphia Electric Co. 83/02/24 EISENHUT, D. G. Division of Licensing 3pp. 17413:229. 24X Fiche: 50-000, 83/02/24, 8303030079.

DOCKET 50-280 SURRY POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8303010634 Forwards IE Insp Repts 50-280/82-35 & 50-281/82-35 during Dec 1982. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs 83/01/28
STEWART, W. L. Virginia Electric & Power Co. 2pp. 17336:123. 24X
Fiche: 50-280, 83/01/28, 8303010634.

--8303010645 IE Insp Repts 50-280/82-35 & 50-281/82-35 during Dec 1982. No noncompliance noted. Major areas inspected: plant operations, operating records, maint & security, followup of events & LERs.
BURKE, D. J., DAVIS, M. J., JULIAN, C. Division of Project & Resident Programs. 83/01/27 6pp. 17336:125 24X Fiche: 50-280, 83/01/28, 8303010634.

8303110122 Forwards Amends 82 & 83 to Licenses DPR-32 & DPR-37, respectively, & notice of issuance & availability. Amends revise Tech Specs to incorporate plant staff working hours & increase frequency of emergency plan audits.
VARGA, S. A. Operating Reactors Branch 1 83/03/01 STEWART, W. L. Virginia Electric & Power Co. 3pp. 17526:088 24X
Fiche: 50-280, 83/03/01, 8303110122.

--8303110131 Amends 82 & 83 to Licenses DPR-32 & DPR-37, respectively, revising Tech Specs to incorporate requirements re plant staff working hours & increase frequency of emergency & security program audits.
VARGA, S. A. Operating Reactors Branch 1 83/03/01 8pp.
17526:091. 24X Fiche: 50-280, 83/03/01, 8303110122.

--8303110138 Notice of issuance & availability of Amends 82 & 83 to Licenses DPR-32 & DPR-37, respectively.
VARGA, S. A. Operating Reactors Branch 1 83/03/01 2pp.
17526:099. 24X Fiche: 50-280, 83/03/01, 8303110122.

8303290389 Forwards IE Safeguards Insp Repts 50-280/83-07 & 50-281/83-06 on 830228-0304. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs 83/03/23
STEWART, W. L. Virginia Electric & Power Co. 2pp. 17725:318. 24X
Fiche: 50-280, 83/03/23, 8303290389.

--8303290403 IE Safeguards Insp Repts 50-280/83-07 & 50-281/83-06 on 830228-0304. No noncompliance noted. Major areas inspected: review of security plan implementation, records & repts & physical barriers. Details withheld (ref 10CFR73.21).
TILLMAN, A. Region 2, Office of Director MCGUIRE, D. R. Division of Emergency Preparedness & Materials Safety. 83/03/23 1p.
17725:320. 24X Fiche: 50-280, 83/03/23, 8303290389.

8303290725 Releases public version of revised corporate emergency response plan & implementing procedures.
FELTON, J. M. Division of Rules and Records 83/03/23 Document Management Branch. 1p. 17746:219. 24X Fiche: 50-000, 83/03/23, 8303290725.

--8303290732 Forwards public version of Rev 2 to corporate emergency response plan & implementing procedures.
STEWART, W. L. Virginia Electric & Power Co. 83/03/15.
O'REILLY, J. P. Region 2, Office of Director 1p. 17746:220. 24X
Fiche: 50-000, 83/03/23, 8303290725.

--8303290739 Public version of Rev 2 to corporate emergency response plan.
MARTIN, J. W. Virginia Electric & Power Co. 83/03/11 72pp.
17746:221. 24X Fiche: 50-000, 83/03/23, 8303290725.

--8303290743 Public version of Rev 2 to corporate plan implementing procedures, including Procedures CPIP-3.0 re administrative svc manager callout/activation, CPIP-3.2 re immediate action items & CPIP-3.3 re message handling. Revised index encl.
e. Virginia Electric & Power Co. 83/02/15 18pp. 17746:292. 24X
Fiche: 50-000, 83/03/23, 8303290725.

8305290361 Advises that certain changes proposed in 820811 & 1209 Rev 6 to security plan unacceptable as identified in encl per 10CFR50.54(p). Remaining changes acceptable. Encl containing safeguards info withheld (ref 10CFR73.21).
VARGA, S. A. Operating Reactors Branch 1 83/03/25 STEWART, W. L. Virginia Electric & Power Co. 2pp. 17725:172. 24X
Fiche: 50-280, 83/03/25, 8305290361.

8303300197 Responds to 830202 ltr submitting Rev 6 to security program. Changes consistent w/provisions of 10CFR50.54(p) & acceptable.
VARGA, S. A. Operating Reactors Branch 1 83/03/25 STEWART, W. L. Virginia Electric & Power Co. 2pp. 17754:332. 24X
Fiche: 50-280, 83/03/25, 8303300197.

J. Insurance & indemnity information

8303110207 Forwards Endorsements 42 & 69 to NELIA Policies NF-240 & NF-186, respectively.
WILSON, J. M. Marsh & McLennan, Inc. 83/03/08 DINITZ, I. Antitrust & Economic analysis Branch (Utility Finance) 3pp. 17513:360. 24X
Fiche: 50-000, 83/03/08, 8303110207.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303070007 Requests extension until 830415 to implement NUREG-0737, Item II.F.1.6, to perform addl testing & to procure & replace heat tracing circuits.
STEWART, W. L. Virginia Electric & Power Co. 83/03/01 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. EISENHUT, D. G. Division of Licensing. 1p. 17434:336. 24X Fiche: 50-280, 83/03/01, 8303070007.

8303100396 Forwards Amends 83 & 84 to Licenses DPR-32 & DPR-37, respectively, & notice of issuance & availability. Amends revise Tech Specs to add limiting conditions for operation & surveillance requirements re containment purge valves.
VARGA, S. A. Operating Reactors Branch 1 83/03/01 STEWART, W. L. Virginia Electric & Power Co. 3pp. 17521:357. 24X
Fiche: 50-280, 83/03/01, 8303100396.

--8303100401 Amends 83 & 84 to Licenses DPR-32 & DPR-37, respectively, revising Tech Specs to add limiting conditions for operation & surveillance requirements re containment purge valves.
VARGA, S. A. Operating Reactors Branch 1 83/03/01 11pp.
17521:360. 24X Fiche: 50-280, 83/03/01, 8303100396.

--8303100404 Notice of issuance & availability of Amends 83 & 84 to Licenses DPR-32 & DPR-37, respectively.
VARGA, S. A. Operating Reactors Branch 1 83/03/01 2pp.
17522:009. 24X Fiche: 50-280, 83/03/01, 8303100396.

8303110122 Forwards Amends 82 & 83 to Licenses DPR-32 & DPR-37, respectively, & notice of issuance & availability. Amends revise Tech Specs to incorporate plant staff working hours & increase frequency of emergency plan audits.
VARGA, S. A. Operating Reactors Branch 1 83/03/01 STEWART, W. L. Virginia Electric & Power Co. 3pp. 17526:088 24X
Fiche: 50-280, 83/03/01, 8303110122.

--8303110131 Amends 82 & 83 to Licenses DPR-32 & DPR-37, respectively, revising Tech Specs to incorporate requirements re plant staff working hours & increase frequency of emergency & security program audits.
VARGA, S. A. Operating Reactors Branch 1 83/03/01 8pp.
17526:091. 24X Fiche: 50-280, 83/03/01, 8303110122.

--8303110138 Notice of issuance & availability of Amends 82 & 83 to Licenses DPR-32 & DPR-37, respectively.
VARGA, S. A. Operating Reactors Branch 1 83/03/01 2pp.
17526:099. 24X Fiche: 50-280, 83/03/01, 8303110122.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/02/02, 8303020321.

8303070048 Submits addl info re technical evaluation repts on environ qualification of safety-related electrical equipment in response to NRC 830126 request Info supplis 830223 ltr re RCS wide-range pressure transmitters.
STEWART, W L Virginia Electric & Power Co 83/03/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 2pp 17435 011 24X
Fiche 50-280, 83/03/02, 8303070048

8303080183 Notifies that source to perform final in situ calibr of containment high-range radiation monitors will be available for compliance w/840930 completion date Status of NUREG-0737, Item II F 3 will be updated 830331
STEWART, W L Virginia Electric & Power Co 83/03/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 1p 17457 350 24X Fiche 50-280, 83/03/03, 8303080183

8303150071 Forwards Amends 84 & 85 to Licenses DPR-32 & DPR-37, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs to remove restriction on moving spent fuel case into fuel bldg
NEIGHBORS, J D Operating Reactors Branch 1 83/03/04 STEWART, W L
Virginia Electric & Power Co 2pp 17586 280 24X
Fiche 50-280, 83/03/04, 8303150071

--8303150079 Amends 84 & 85 to Licenses DPR-32 & DPR-37, respectively, changing Tech Specs to remove restriction on moving spent fuel case into fuel bldg
VARGA, S A Operating Reactors Branch 1 83/03/04 8pp
17586 282 24X Fiche 50-280, 83/03/04, 8303150071

--8303150085 Safety evaluation supporting Amends 84 & 85 to Licenses DPR-32 & DPR-37, respectively
* Office of Nuclear Reactor Regulation, Director 83/03/04 7pp
17586 290 24X Fiche 50-280, 83/03/04, 8303150071

--8303150092 Notice of issuance & availability of Amends 84 & 85 to Licenses DPR-32 & DPR-37, respectively
VARGA, S A Operating Reactors Branch 1 83/03/04 2pp
17586 297 24X Fiche 50-280, 83/03/04, 8303150071

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 5lpp 17660 176 24X
Fiche 50-000, 83/03/07, 8303040005

8303110280 Corrects date of 830303 ltr re NUREG-07737, Item II F 1 3 to 830301
STEWART, W L Virginia Electric & Power Co 83/03/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 1p 17517 350 24X Fiche 50-280, 83/03/07, 8303110280

8303150399 Application for amend to Licenses DPR-32 & DPR-37, adding Tech Spec 4 17c to revise schedule for functional testing of 50 kips & above category snubbers, Class III & I amend fees encl
STEWART, W L Virginia Electric & Power Co 83/03/08 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 2pp 17561 276 24X
Fiche 50-280, 83/03/08, 8303150399

--8303150404 Proposed Tech Spec change adding Tech Spec 4 17c to revise schedule for functional testing of 50 kips & above category snubbers
* Virginia Electric & Power Co 83/03/08 7pp 17561 278 24X
Fiche 50-280, 83/03/08, 8303150399

8303110282 Responds to NRC 830126 ltr re justification for continued operation & info for NRC Categories I B.1 A & B re SER for environ qualification of safety-related electrical equipment Thirty-day response completed
STEWART, W L Virginia Electric & Power Co 83/03/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 2,106pp 17507 001 24X
Fiche 50-280, 83/03/09, 8303110282

--8303110286 "Continental Wire & Cable Co 600 & 1,000V Cables w/Silicone Rubber Installation & Hypalon Jacket," Rev 1 qualification review package, Surry Unit 1
* NUS Corp GDR-5437-47-01 82/09/21 94pp 17507 219 24X
Fiche 50-280, 83/03/09, 8303110282

--8303110291 "Continental Wire & Cable Co 600 Volt & 1,000 Volt Cables w/Silicone Rubber Installation & Hypalon Jacket "
* NUS Corp GDR-5437-131-01 82/09/21 92pp 17507 313 24X
Fiche 50-280, 83/03/09, 8303110282

--8303110297 "Cutler Hammer 480-Volt Motor Control Ctrs "
* NUS Corp GDR-5437-17-01 82/03/15 46pp 17508 045 24X
Fiche 50-280, 83/03/09, 8303110282

--8303110302 "Rosemount Transmitters Model 1152DP & AP (PT-LM-101A, PT-LM-101B) "
* NUS Corp GDR-5437-201-01 82/04/30 80pp 17508 092 24X
Fiche 50-280, 83/03/09, 8303110282

--8303110353 "Rosemount Transmitters Model 1152DP & AP (PT-LM-101A, PT-LM-101B) "
* NUS Corp GDR-5437-241-01 82/04/30 83pp 17508 173 24X
Fiche 50-280, 83/03/09, 8303110282

--8303110356 "Cutler-Hammer 480-Volt Motor Control Ctrs "
* NUS Corp GDR-5437-78-01 82/03/15 46pp 17508 256 24X
Fiche 50-280, 83/03/09, 8303110282

--8303110358 "Valcor Valves & Gordos Limit Switches "
* NUS Corp GDR-5437-205-01 82/05/28 723pp 17508 302 24X
Fiche 50-280, 83/03/09, 8303110282

--8303110359 "Valcor Valves & Gordos Limit Switches "
* NUS Corp GDR-5437-245-01 82/05/28 722pp 17510 305 24X
Fiche 50-280, 83/03/09, 8303110282

8303160172 Supplis 830223 & 0302 ltrs re environ qualification of RCS wide-range pressure transmitters Rosemount 1153 Series D pressure transmitter successfully completed qualification test Final rept should be available by 830531
STEWART, W L Virginia Electric & Power Co 83/03/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 1p 17597 033 24X
Fiche 50-280, 83/03/09, 8303160172

8303160198 Requests 60-day extension, until 830509, to respond to Generic Ltr 82-20 re inadequate core cooling instrumentation sys, in order to complete review
STEWART, W L Virginia Electric & Power Co 83/03/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 1p 17596 291 24X Fiche 50-000, 83/03/10, 8303160198

8303150285 Forwards "Surry Unit 1 Cycle 6 Core Performance Rept "
STEWART, W L Virginia Electric & Power Co 83/03/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 1p 17563 120 24X
Fiche 50-280, 83/03/11, 8303150285

--8303150288 "Surry Unit 1 Cycle 6 Core Performance Rept "
HARTSFIELD, T C Virginia Electric & Power Co VEP-NOS-1
83/03/31 50pp 17563 121 24X Fiche 50-280, 83/03/11, 8303150285

8303170523 Informs that final in situ calibr of containment high-range radiation monitors, per NUREG-0737, Item II F 1 3, can be completed during 831015 & 1130 maint outages for Units 1 & 2, respectively
STEWART, W L Virginia Electric & Power Co 83/03/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 1p 17610 264 24X Fiche 50-280, 83/03/11, 8303170523

8303290639 Forwards Amends 85 & 86 to Licenses DPR-32 & DPR-37, respectively & notice of issuance & availability Amends delete Tech Specs re nonradiological water quality-related requirements
VARGA, S A Operating Reactors Branch 1 83/03/11 STEWART, W L
Virginia Electric & Power Co 3pp 17743 014 24X
Fiche 50-280, 83/03/11, 8303290639

--8303290647 Amends 85 & 86 to Licenses DPR-32 & DPR-37, respectively, deleting Tech Specs re nonradiological water quality-related requirements
VARGA, S A Operating Reactors Branch 1 83/03/11 7pp
17743 017 24X Fiche 50-280, 83/03/11, 8303290639

--8303290670 Notice of issuance & availability of Amends 85 & 86 to Licenses DPR-32 & DPR-37, respectively
VARGA, S A Operating Reactors Branch 1 83/03/11 2pp
17743 024 24X Fiche 50-280, 83/03/11, 8303290639

8303170365 Notifies that results of 830305 fuel exam program revealed three assemblies scheduled for return to Cycle 7 core contain fuel defects Westinghouse instructed to proceed w/development or alternate core loading pattern for Cycle 7
STEWART, W L Virginia Electric & Power Co 83/03/14 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 2pp 17609 329 24X
Fiche 50-280, 83/03/14, 8303170365

8303290080 Forwards order confirming commitments on post-TMI related issues per NUREG-0737. Proposed schedule exceptions & delays acceptable. Order based on commitments per responses to Generic Ltrs 82-05 & 82-10.
VARGA, S. A. Operating Reactors Branch 1. 83/03/15. STEWART, W. L. Virginia Electric & Power Co. 2pp. 17729:247. 24X Fiche: 50-280, 83/03/15, 8303290080.

--8303290087 Order confirming licensee commitments on post-TMI-related issues per NUREG-0737.
PURPLE, R. A. Division of Licensing. 83/03/15. Virginia Electric & Power Co. 9pp. 17729:249. 24X Fiche: 50-280, 83/03/15, 8303290080.

8303210617 Requests relief from ASME Section XI hydrostatic test requirements. Alternate testing proposed provides necessary insp & integrity insurance for all affected welds.
STEWART, W. L. Virginia Electric & Power Co. 83/03/16. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARGA, S. A. Operating Reactors Branch 1. 3pp. 17636:233. 24X Fiche: 50-280, 83/03/16, 8303210617.

8303300138 Informs that util has decided not to request public hearing on orders for mod of license re qualification of safety-related electrical equipment.
CHRISTMAN, J. N. Hunton & Williams. 83/03/24. EISENHUT, D. G. Division of Licensing. 2pp. 17735:296. 24X Fiche: 50-000, 83/03/24, 8303300138.

G. Inspection reports, IE Bulletins & correspondence

8303010634 Forwards IE Insp Repts 50-280/82-35 & 50-281/82-35 during Dec 1982. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/01/28. STEWART, W. L. Virginia Electric & Power Co. 2pp. 17336:123. 24X Fiche: 50-280, 83/01/28, 8303010634.

--8303010645 IE Insp Repts 50-280/82-35 & 50-281/82-35 during Dec 1982. No noncompliance noted. Major areas inspected: plant operations, operating records, maint & security, followup of events & LERs.
BURKE, D. J., DAVIS, M. J., JULIAN, C. Division of Project & Resident Programs. 83/01/27. 6pp. 17336:125. 24X Fiche: 50-280, 83/01/28, 8303010634.

8303010643 Ack receipt of 830202 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/82-34 & 50-281/82-34.
LEWIS, R. C. Division of Project & Resident Programs. 83/02/18. STEWART, W. L. Virginia Electric & Power Co. 1p. 17336:212. 24X Fiche: 50-280, 83/02/18, 8303010643.

--8303010655 Responds to NRC 830112 ltr re violations noted in IE Insp Repts 50-280/82-34 & 50-281/82-34. Corrective actions: operations dept instructed on potential of tank filling overpressurization & filling methods to prevent problem.
STEWART, W. L. Virginia Electric & Power Co. 83/02/02. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17336:213. 24X Fiche: 50-280, 83/02/18, 8303010643.

--8303010661 Forwards IE Insp Repts 50-280/82-34 & 50-281/82-34 on 821101-30 & notice of violation.
LEWIS, R. C. Division of Project & Resident Programs. 83/01/12. STEWART, W. L. Virginia Electric & Power Co. 2pp. 17336:218. 24X Fiche: 50-280, 83/02/18, 8303010643.

--8303010665 Notice of violation from insp on 821101-30.
* Region 2, Office of Director. 83/01/12. 1p. 17336:220. 24X Fiche: 0-280, 83/02/18, 8303010643.

--8303010673 IE Insp Repts 50-280/82-34 & 50-281/82-34 on 821101-30. Noncompliance noted: failure to perform or maintain written safety evaluation when mod to component cooling water syst implemented.
BURKE, D. J., DAVIS, M. J., JULIAN, C. Division of Project & Resident Programs. 83/01/07. 10pp. 17336:221. 24X Fiche: 50-280, 83/02/18, 8303010643.

8303210678 Forwards IE Insp Repts 50-280/83-03 & 50-281/83-03 on 830131-0204. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/02/23. STEWART, W. L. Virginia Electric & Power Co. 2pp. 17635:257. 24X Fiche: 50-280, 83/02/23, 8303210678.

--8303210693 IE Insp Repts 50-280/83-03 & 50-281/83-03 on 830131-0204. No noncompliance noted. Major areas inspected: review of lab QC program & comparison of analyses of split samples analyzed by licensee & Region II mobile lab.
EVANS, C. D., KUZO, G. B., MONTGOMERY, D. Region 2, Office of Director. 83/02/22. 8pp. 17635:259. 24X Fiche: 50-280, 83/02/23, 8303210678.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210342 Forwards IE Insp Repts 50-280/83-04 & 50-281/83-04 on 830103-0131. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/03/01. STEWART, W. L. Virginia Electric & Power Co. 2pp. 17634:282. 24X Fiche: 50-280, 83/03/01, 8303210342.

--8303210346 IE Insp Repts 50-280/83-04 & 50-281/83-04 on 830103-31. No noncompliance noted. Major areas inspected: plant operations & operating records, plant maint & surveillance, plant security & followup of previous events & LERs.
BURKE, D. J., DAVIS, M. J. Region 2, Office of Director. JULIAN, C. A. Division of Project & Resident Programs. 83/02/28. 6pp. 17634:284. 24X Fiche: 50-280, 83/03/01, 8303210342.

8303210523 Forwards response to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Operators reviewed Salem event. Operability tests performed.
STEWART, W. L. Virginia Electric & Power Co. 83/03/04. O'REILLY, J. P. Region 2, Office of Director. 4pp. 17632:219. 24X Fiche: 50-000, 83/03/04, 8303210523.

8303110323 Submits suppl info re draft SER on inservice insp relief requests. Hydrostatic tests impractical in portions of sys such as component cooling, spent fuel pit cooling, svc water & boric acid transfer.
STEWART, W. L. Virginia Electric & Power Co. 83/03/07. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARGA, S. A. Operating Reactors Branch 1. 2pp. 17520:078. 24X Fiche: 50-280, 83/03/07, 8303110323.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303210617 Requests relief from ASME Section XI hydrostatic test requirements. Alternate testing proposed provides necessary insp & integrity insurance for all affected welds.
STEWART, W. L. Virginia Electric & Power Co. 83/03/16. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARGA, S. A. Operating Reactors Branch 1. 3pp. 17636:233. 24X Fiche: 50-280, 83/03/16, 8303210617.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303230225 EN-83-016 on 830324, notice of violation & proposed imposition of civil penalty in amount of $20,000 will be issued re inoperable chemical addition tank in containment spray sys.
BARBER, G., AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 83/03/21. 1p. 17665:187. 24X Fiche: 50-280, 83/03/21, 8303230225.

8303290389 Forwards IE Safeguards Insp Repts 50-280/83-07 & 50-281/83-06 on 830228-0304. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/03/23. STEWART, W. L. Virginia Electric & Power Co. 2pp. 17725:318. 24X Fiche: 50-280, 83/03/23, 8303290389.

--8303290403 IE Safeguards Insp Repts 50-280/83-07 & 50-281/83-06 on 830228-0304. No noncompliance noted. Major areas inspected: review of security plan implementation, records & rpts & physical barriers. Details withheld (ref 10CFR73.21).
TILLMAN, A. Region 2, Office of Director. MCGUIRE, D. R. Division of Emergency Preparedness & Materials Safety. 83/03/23. 1p. 17725:320. 24X Fiche: 50-280, 83/03/23, 8303290389.

R. Periodic operating reports & related correspondence

8303080035 Forwards monthly operating repts for Dec 1982.
STEWART, W. L. Virginia Electric & Power Co. 83/01/14. HALLER, N. M. Office of Management and Program Analysis. 2pp. 17456:001. 24X Fiche: 50-280, 83/01/14, 8303080035.

# DOCKETED ITEMS

--8303080037 Monthly operating repts for Dec 1982.
WILSON, J. ; DUNN, S. D. ; COSTELLO, D. J. Virginia Electric & Power Co.
83/01/06 52pp. 17456 003 24X Fiche: 50-280, 83/01/14, 8303080035.

8303150370 Forwards monthly operating rpts for Jan 1983.
STEWART, W. L. Virginia Electric & Power Co. 83/02/15 HALLER, N. M.
Office of Resource Management, Director 1p. 17562 132 24X
Fiche: 50-280, 83/02/15, 8303150370.

--8303150376 Monthly operating repts for Jan 1983.
JONES, V. H. ; WILSON, J. Virginia Electric & Power Co. 83/02/03
42pp. 17562 133 24X Fiche: 50-280, 83/02/15, 8303150370.

S. Reportable occurrences, LERs & related correspondence

8303010460 Forwards LER 83-003/01T-0.
WILSON, J. L. Virginia Electric & Power Co. 83/02/23 O'REILLY, J. P.
Region 2, Office of Director 1p. 17343 272 24X
Fiche: 50-280, 83/02/23, 8303010460.

--8303010469 LER 83-003/01T-0 on 830209, MOV-SW-103A, B, C & D &
MOV-SW-203A, C & D failed to open upon demand from control
room. Caused by corrosion on motors of MOV-SW-103C & 203C &
torque switch of 103B Valves repaired.
WILSON, J. L. Virginia Electric & Power Co. 83/02/23 Region 2,
Office of Director 3pp. 17343 273 24X Fiche: 50-280, 83/02/23,
8303010460.

8303140542 Forwards LERs 83-004/03L-0 & 83-005/03L-0.
WILSON, J. L. Virginia Electric & Power Co. 83/02/25 O'REILLY, J. P.
Region 2, Office of Director 1p. 17534 186 24X
Fiche: 50-280, 83/02/25, 8303140542.

--8303140551 LER 83-004/03L-0 on 830202, w/Units 1 & 2 at 88% & 100%
respectively, emergency diesel generator 3 declared
inoperable due to leaking cooling water pump. Caused by worn
shaft seal. Seal replaced & generator tested satisfactorily.
WILSON, J. L. Virginia Electric & Power Co. 83/02/25 Region 2,
Office of Director 2pp. 17534 189 24X Fiche: 50-280, 83/02/25,
8303140542.

--8303140560 LER 83-005/03L-0 on 830204, 10 & 11 w/unit at 85% & effluent
release in progress, radiation recorder RR-100 began printing
erratically. Caused by poor electrical connection on erratic
recorder. Recorder swapped w/properly functioning unit.
WILSON, J. L. Virginia Electric & Power Co. 83/02/25 Region 2,
Office of Director. 2pp. 17534 191 24X Fiche: 50-280, 83/02/25,
8303140542.

8303040568 Forwards LER 83-006/03L-0.
WILSON, J. L. Virginia Electric & Power Co. 83/02/28 O'REILLY, J. P.
Region 2, Office of Director. 1p. 17374 191 24X
Fiche: 50-280, 83/02/28, 8303040568.

--8303040584 LER 83-006/03L-0 on 830129, w/Unit 1 at 94% power & Unit 2
at 100% power, boric acid transfer pump 1-CH-P-2B tripped
on high amperes while running & pump 1-CH-P-2D tripped
while attempting to start. Caused by boric acid crystals.
WILSON, J. L. Virginia Electric & Power Co. 83/02/28 Region 2,
Office of Director. 2pp. 17374 192 24X Fiche: 50-280, 83/02/28,
8303040568.

8303150138 Forwards LERs 83-007/03L-0, 83-008/03L-0 & 83-009/03L-0.
WILSON, J. L. Virginia Electric & Power Co. 83/03/04 O'REILLY, J. P.
Region 2, Office of Director. 1p. 17555 208 24X
Fiche: 50-280, 83/03/04, 8303150138.

--8303150166 LER 83-007/03L-0 on 830204, at 85% power, latch mechanism of
fire door 20 taped over, causing fire barrier to be
inoperable. Caused by const personnel error. Tape removed &
door returned to operable status.
WILSON, J. L. Virginia Electric & Power Co. 83/03/04 Region 2,
Office of Director. 2pp. 17555 209 24X Fiche: 50-280, 83/03/04,
8303150138.

--8303150175 LER 83-008/03L-0 on 830204, during 85% power, results of
PT-2.26 indicated that PCV-1455C would not cycle. Caused by
apparent valve binding. Valve will be inspected & repaired as
necessary during current outage.
WILSON, J. L. Virginia Electric & Power Co. 83/03/04 Region 2,
Office of Director. 2pp. 17555 211 24X Fiche: 50-280, 83/03/04,
8303150138.

--8303150184 LER 83-009/03L-0 on 830204, during 85% power, PT-2.26 revealed
that MOV-1535 & MOV-1536 would not fully cycle. Cause
undetermined. Valves will be inspected during current outage.
WILSON, J. L. Virginia Electric & Power Co. 83/03/04 Region 2,
Office of Director. 2pp. 17555 213 24X Fiche: 50-280, 83/03/04,
8303150138.

8303160194 Forwards LERs 83-010/03L-0 & 83-011/03L-0.
WILSON, J. L. Virginia Electric & Power Co. 83/03/04 O'REILLY, J. P.
Region 2, Office of Director. 1p. 17596 180 24X
Fiche: 50-280, 83/03/04, 8303160194.

--8303160201 LER 83-010/03L-0 on 830207, activity samples of RCS indicated
dose equivalent I-131 level greater than Tech Spec following
reactor trip. Caused by fuel element defect in reactor core.
Accelerated sampling frequency implemented.
WILSON, J. L. Virginia Electric & Power Co. 83/03/04 Region 2,
Office of Director. 4pp. 17596 181 24X Fiche: 50-280, 83/03/04,
8303160194.

--8303160211 LER 83-011/03L-0 on 830211, instrument air check valve to
PORV found installed backwards. Caused by installation error
during implementation of Design Change 79-53. Valve removed &
reinstalled in correct orientation.
WILSON, J. L. Virginia Electric & Power Co. 83/03/04 Region 2,
Office of Director. 2pp. 17596 185 24X Fiche: 50-280, 83/03/04,
8303160194.

8303240559 Forwards LER 83-012/03L-0.
WILSON, J. L. Virginia Electric & Power Co. 83/03/10 O'REILLY, J. P.
Region 2, Office of Director. 1p. 17683 202 24X
Fiche: 50-280, 83/03/10, 8303240559.

--8303240573 LER 83-012/03L-0 on 830209, w/unit at cold s[illegible]own &
overpressure mitigating sys enabled, both pressurizer PORVs,
PCV 1455C & 1456, declared inoperable. Caused by low air
pressure in backup bottle air supply.
WILSON, J. L. Virginia Electric & Power Co. 83/03/10 Region 2,
Office of Director. 2pp. 17683 203 24X Fiche: 50-280, 83/03/10,
8303240559.

8303240504 Forwards LER 83-013/03L-0.
WILSON, J. L. Virginia Electric & Power Co. 83/03/14 O'REILLY, J. P.
Region 2, Office of Director. 1p. 17690 323 24X
Fiche: 50-280, 83/03/14, 8303240504.

--8303240510 LER 83-013/03L-0 on 830215, during cold shutdown, valve
MOV-SW-102B would not cycle. Caused by damaged gears linking
motor to valve actuator. Gears replaced.
WILSON, J. L. Virginia Electric & Power Co. 83/03/14 Region 2,
Office of Director. 3pp. 17690 324 24X Fiche: 50-280, 83/03/14,
8303240504.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees,
applicants for OL, holders of CPs & NSSS vendors re issuance
of NRC Form 398, "Personal Qualifications Statement -
Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated
Edison Co. of New York, Inc. 18pp 24X Fiche: 50-000, 83/02/24,
8302250505.

Y. Dry Cask Independent Spent Fuel Storage Installations

8303020215 Forwards suppl to ISFSI SAR, which reflects actual submittal
of C-E Topical Rept CENPD-270 describing design for dry
storage casks appropriate for use in storage.
STEWART, W. L. Virginia Electric & Power Co. 83/01/25
CUNNINGHAM, R. E. Office of Nuclear Material Safety &
Safeguards, Director. 3pp. 17357 357 24X Fiche: 50-280, 83/01/25,
8303020215.

8303280315 Comments on util application for ISFSI. Topical rept review
comments to C-E encl to keep util appraised of progress of
review of C-E rept. "Dry Storage Cask for ISFSI," dtd Oct
1982.
ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch 83/03/16
STEWART, W. L. Virginia Electric & Power Co. 37pp 17713 251 24X
Fiche: 50-280, 83/03/16, 8303280315.

DOCKET 50-281 SURRY POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8303010634 Forwards IE Insp Repts 50-280/82-35 & 50-281/82-35 during
Dec 1982 No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs 83/01/28
STEWART, W. L. Virginia Electric & Power Co. 2pp. 17336 123 24X
Fiche: 50-280, 83/01/28, 8303010634.

--8303010645 IE Insp Repts 50-280/82-35 & 50-281/82-35 during Dec 1982. No
noncompliance noted. Major areas inspected: plant operations,
operating records, maint & security, followup of events &
LERs.
BURKE, D. J. Division of Project & Resident Programs 83/01/27
6pp. 17336 125 24X Fiche: 50-280, 83/01/28, 8303010634.

8303110122 Forwards Amends 82 & 83 to Licenses DPR-32 & DPR-37, respectively & notice of issuance & availability. Amends revise Tech Specs to incorporate plant staff working hours & increase frequency of emergency plan audits.
VARGA, S. A. Operating Reactors Branch 1. 83/03/01. STEWART, W. L. Virginia Electric & Power Co. 3pp. 17526:088. 24X
Fiche: 50-280, 83/03/01, 8303110122.

--8303110131 Amends 82 & 83 to Licenses DPR-32 & DPR-37, respectively, revising Tech Specs to incorporate requirements re plant staff working hours & increase frequency of emergency & security program audits.
VARGA, S. A. Operating Reactors Branch 1. 83/03/01. 8pp. 17526:091. 24X Fiche: 50-280, 83/03/01, 8303110122.

--8303110138 Notice of issuance & availability of Amends 82 & 83 to Licenses DPR-32 & DPR-37, respectively.
VARGA, S. A. Operating Reactors Branch 1. 83/03/01. 2pp. 17526:099. 24X Fiche: 50-280, 83/03/01, 8303110122.

8303290389 Forwards IE Safeguards Insp Repts 50-280/83-07 & 50-281/83-06 on 830228-0304. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/03/23.
STEWART, W. L. Virginia Electric & Power Co. 2pp. 17725:318. 24X
Fiche: 50-280, 83/03/23, 8303290389.

--8303290403 IE Safeguards Insp Repts 50-280/83-07 & 50-281/83-06 on 830228-0304. No noncompliance noted. Major areas inspected: review of security plan implementation, records & repts & physical barriers. Details withheld (ref 10CFR73.21).
TILLMAN, A. Region 2, Office of Director. 83/03/23. 1p. 17725:320. 24X Fiche: 50-280, 83/03/23, 8303290389.

8303290725 Releases public version of revised corporate emergency response plan & implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/23. Document Management Branch. 1p. 17746:219. 24X Fiche: 50-000, 83/03/23, 8303290725.

--8303290732 Forwards public version of Rev 2 to corporate emergency response plan & implementing procedures.
STEWART, W. L. Virginia Electric & Power Co. 83/03/15.
O'REILLY, J. P. Region 2, Office of Director. 1p. 17746:220. 24X
Fiche: 50-000, 83/03/23, 8303290725.

--8303290739 Public version of Rev 2 to corporate emergency response plan.
MARTIN, J. W. Virginia Electric & Power Co. 83/03/11. 72pp. 17746:221. 24X Fiche: 50-000, 83/03/23, 8303290725.

--8303290743 Public version of Rev 2 to corporate plan implementing procedures, including Procedures CPIP-3.0 re administrative svc manager callout/activation, CPIP-3.2 re immediate action items & CPIP-3.3 re message handling. Revised index encl.
* Virginia Electric & Power Co. 83/02/15. 18pp. 17746:292. 24X
Fiche: 50-000, 83/03/23, 8303290725.

8303290361 Advises that certain changes proposed in 820811 & 1209 Rev 6 to security plan unacceptable as identified in encl, per 10CFR50.54(p). Remaining changes acceptable. Encl containing safeguards info withheld (ref 10CFR73.21).
VARGA, S. A. Operating Reactors Branch 1. 83/03/25. STEWART, W. L. Virginia Electric & Power Co. 2pp. 17725:172. 24X
Fiche: 50-280, 83/03/25, 8303290361.

8303300197 Responds to 830202 ltr submitting Rev 8 to security program. Changes consistent w/provisions of 10CFR50.54(p) & acceptable.
VARGA, S. A. Operating Reactors Branch 1. 83/03/25. STEWART, W. L. Virginia Electric & Power Co. 2pp. 17754:332. 24X
Fiche: 50-280, 83/03/25, 8303300197.

J. Insurance & indemnity information

8303110207 Forwards Endorsements 42 & 69 to NELIA Policies NF-240 & NF-186, respectively.
WILSON, J. M. Marsh & McLennan, Inc. 83/03/08. DINITZ, I. Antitrust & Economic analysis Branch (Utility Finance). 3pp. 17513:360. 24X
Fiche: 50-000, 83/03/08, 8303110207.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303070007 Requests extension until 830415 to implement NUREG-0737, Item II.F.1.6, to perform addl testing & to procure & replace heat tracing circuits.
STEWART, W. L. Virginia Electric & Power Co. 83/03/01. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. EISENHUT, D. G. Division of Licensing. 1p. 17434:336. 24X Fiche: 50-280, 83/03/01, 8303070007.

8303100396 Forwards Amends 83 & 84 to Licenses DPR-32 & DPR-37, respectively & notice of issuance & availability. Amends revise Tech Specs to add limiting conditions for operation & surveillance requirements re containment purge valves.
VARGA, S. A. Operating Reactors Branch 1. 83/03/01. STEWART, W. L. Virginia Electric & Power Co. 3pp. 17521:357. 24X
Fiche: 50-280, 83/03/01, 8303100396.

--8303100401 Amends 83 & 84 to Licenses DPR-32 & DPR-37, respectively, revising Tech Specs to add limiting conditions for operation & surveillance requirements re containment purge valves.
VARGA, S. A. Operating Reactors Branch 1. 83/03/01. 11pp. 17521:360. 24X Fiche: 50-280, 83/03/01, 8303100396.

--8303100404 Notice of issuance & availability of Amends 83 & 84 to Licenses DPR-32 & DPR-37, respectively.
VARGA, S. A. Operating Reactors Branch 1. 83/03/01. 2pp. 17522:009. 24X Fiche: 50-280, 83/03/01, 8303100396.

8303110122 Forwards Amends 82 & 83 to Licenses DPR-32 & DPR-37, respectively & notice of issuance & availability. Amends revise Tech Specs to incorporate plant staff working hours & increase frequency of emergency plan audits.
VARGA, S. A. Operating Reactors Branch 1. 83/03/01. STEWART, W. L. Virginia Electric & Power Co. 3pp. 17526:088. 24X
Fiche: 50-280, 83/03/01, 8303110122.

--8303110131 Amends 82 & 83 to Licenses DPR-32 & DPR-37, respectively, revising Tech Specs to incorporate requirements re plant staff working hours & increase frequency of emergency & security program audits.
VARGA, S. A. Operating Reactors Branch 1. 83/03/01. 8pp. 17526:091. 24X Fiche: 50-280, 83/03/01, 8303110122.

--8303110138 Notice of issuance & availability of Amends 82 & 83 to Licenses DPR-32 & DPR-37, respectively.
VARGA, S. A. Operating Reactors Branch 1. 83/03/01. 2pp. 17526:099. 24X Fiche: 50-280, 83/03/01, 8303110122.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303070048 Submits addl info re technical evaluation repts on environ qualification of safety-related electrical equipment, in response to NRC 830126 request. Info supplS 830223 ltr re RCS wide-range pressure transmitters.
STEWART, W. L. Virginia Electric & Power Co. 83/03/02. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARGA, S. A. Operating Reactors Branch 1. 2pp. 17435:011. 24X
Fiche: 50-280, 83/03/02, 8303070048.

8303080183 Notifies that source to perform final in situ calibr of containment high-range radiation monitors will be available for compliance w/840930 completion date. Status of NUREG-0737, Item II.2.F.3 will be updated 830331.
STEWART, W. L. Virginia Electric & Power Co. 83/03/03. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. EISENHUT, D. G. Division of Licensing. 1p. 17457:350. 24X Fiche: 50-280, 83/03/03, 8303080183.

8303150071 Forwards Amends 84 & 85 to Licenses DPR-32 & DPR-37, respectively, safety evaluation & notice of issuance & availability. Amends revise Tech Specs to remove restriction on moving spent fuel case into fuel bldg.
NEIGHBORS, J. D. Operating Reactors Branch 1. 83/03/04. STEWART, W. L. Virginia Electric & Power Co. 2pp. 17586:280. 24X
Fiche: 50-280, 83/03/04, 8303150071.

--8303150079 Amends 84 & 85 to Licenses DPR-32 & DPR-37, respectively, changing Tech Specs to remove restriction on moving spent fuel case into fuel bldg.
VARGA, S. A. Operating Reactors Branch 1. 83/03/04. 8pp. 17586:282. 24X Fiche: 50-280, 83/03/04, 8303150071.

--8303150085 Safety evaluation supporting Amends 84 & 85 to Licenses DPR-32 & DPR-37, respectively.
* Office of Nuclear Reactor Regulation, Director. 83/03/04. 7pp. 17586:290. 24X Fiche: 50-280, 83/03/04, 8303150071.

--8303150092 Notice of issuance & availability of Amends 84 & 85 to Licenses DPR-32 & DPR-37, respectively.
VARGA, S. A. Operating Reactors Branch 1. 83/03/04. 2pp.
17586:297. 24X Fiche: 50-280, 83/03/04, 8303150071.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 31pp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303110280 Corrects date of 830303 ltr re NUREG-07737, Item II.F.1.3 to 830301.
STEWART, W. L. Virginia Electric & Power Co. 83/03/07. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. EISENHUT, D. G. Division of Licensing. 1p. 17517:350. 24X Fiche: 50-280, 83/03/07, 8303110280.

8303150399 Application for amend to Licenses DPR-32 & DPR-37, adding Tech Spec 4.17c to revise schedule for functional testing of 50 k ps & above category snubbers. Class III & I amend fees encl.
STEWART, W. L. Virginia Electric & Power Co. 83/03/08. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARGA, S. A. Operating Reactors Branch 1. 2pp. 17561:276. 24X
Fiche: 50-280, 83/03/08, 8303150399.

--8303150404 Proposed Tech Spec change adding Tech Snec 4.17c to revise schedule for functional testing of 50 kips & above category snubbers.
* Virginia Electric & Power Co. 83/03/08. 7pp. 17561:278. 24X
Fiche: 50-280, 83/03/08, 8303150399.

8303110282 Responds to NRC 830126 ltr re justification for continued operation & info for NRC Categories I.B.1.A & B re SER for environ qualification of safety-related electrical equipment. Thirty-day response completed.
STEWART, W. L. Virginia Electric & Power Co. 83/03/09. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARGA, S. A. Operating Reactors Branch 1. 2,106pp. 17507:001. 24X
Fiche: 50-280, 83/03/09, 8303110282.

--8303110291 "Continental Wire & Cable Co 600 Volt & 1,000 Volt Cables w/Silicone Rubber Installation & Hypalon Jacket."
* NUS Corp. QDR-5437-131-01. 82/09/21. 92pp. 17507:313. 24X
Fiche: 50-280, 83/03/09, 8303110282.

--8303110353 "Rosemount Transmitters Model 1152DP & AP (PT-LM-101A, PT-LM-101B)."
* NUS Corp. QDR-5437-241-01. 82/04/30. 83pp. 17508:173. 24X
Fiche: 50-280, 83/03/09, 8303110282.

--8303110356 "Cutler-Hammer 480-Volt Motor Control Ctrs."
* NUS Corp. QDR-5437-78-01. 82/03/15. 46pp. 17508:256. 24X
Fiche: 50-280, 83/03/09, 8303110282.

--8303110358 "Valcor Valves & Gordos Limit Switches."
* NUS Corp. QDR-5437-205-01. 82/05/28. 723pp. 17508:302. 24X
Fiche: 50-280, 83/03/09, 8303110282.

--8303110359 "Valcor Valves & Gordos Limit Switches."
* NUS Corp. QDR-5437-245-01. 82/05/28. 722pp. 17510:305. 24X
Fiche: 50-280, 83/03/09, 8303110282.

8303160172 Supplis 830223 & 0302 ltrs re environ qualification of RCS wide-range pressure transmitters. Rosemount 1153 Series D pressure transmitter successfully completed qualification test. Final rept should be available by 830531.
STEWART, W. L. Virginia Electric & Power Co. 83/03/09. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARGA, S. A. Operating Reactors Branch 1. 1p. 17597:033. 24X
Fiche: 50-280, 83/03/09, 8303160172.

8303160198 Requests 60-day extension, until 830509, to respond to Generic Ltr 82-28 re inadequate core cooling instrumentation sys, in order to complete review.
STEWART, W. L. Virginia Electric & Power Co. 83/03/10. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. EISENHUT, D. G. Division of Licensing. 1p. 17596:291. 24X Fiche: 50-000, 83/03/10, 8303160198.

8303170523 Informs that final in situ calibr of containment high-range radiation monitors, per NUREG-0737, Item II.F.1.3, can be completed during 831015 & 1130 maint outages for Units 1 & 2, respectively.
STEWART, W. L. Virginia Electric & Power Co. 83/03/11. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. EISENHUT, D. G. Division of Licensing. 1p. 17610:264. 24X Fiche: 50-280, 83/03/11, 8303170523.

8303290639 Forwards Amends 85 & 86 to Licenses DPR-32 & DPR-37, respectively & notice of issuance & availability. Amends delete Tech Specs re nonradiological water quality-related requirements.
VARGA, S. A. Operating Reactors Branch 1. 83/03/11. STEWART, W. L. Virginia Electric & Power Co. 3pp. 17743:014. 24X
Fiche: 50-280, 83/03/11, 8303290639.

--8303290647 Amends 85 & 86 to Licenses DPR-32 & DPR-37, respectively, deleting Tech Specs re nonradiological water quality-related requirements.
VARGA, S. A. Operating Reactors Branch 1. 83/03/11. 7pp.
17743:017. 24X Fiche: 50-280, 83/03/11, 8303290639.

--8303290670 Notice of issuance & availability of Amends 85 & 86 to Licenses DPR-32 & DPR-37, respectively.
VARGA, S. A. Operating Reactors Branch 1. 83/03/11. 2pp.
17743:024. 24X Fiche: 50-280, 83/03/11, 8303290639.

8303290080 Forwards order confirming commitments on post-TMI related issues per NUREG-0737. Proposed schedule exceptions & delays acceptable. Order based on commitments per responses to Generic Ltrs 82-05 & 82-10.
VARGA, S. A. Operating Reactors Branch 1. 83/03/15. STEWART, W. L. Virginia Electric & Power Co. 2pp. 17729:247. 24X
Fiche: 50-280, 83/03/15, 8303290080.

--8303290087 Order confirming licensee commitments on post-TMI-related issues per NUREG-0737.
PURPLE, R. A. Division of Licensing. 83/03/15. Virginia Electric & Power Co. 9pp. 17729:249. 24X Fiche: 50-280, 83/03/15, 8303290080.

8303300138 Informs that util has decided not to request public hearing on orders for mod of license re qualification of safety-related electrical equipment.
CHRISTMAN, J. N. Hunton & Williams. 83/03/24. EISENHUT, D. G. Division of Licensing. 2pp. 17735:296. 24X Fiche: 50-000, 83/03/24, 8303300138.

## Q. Inspection reports, IE Bulletins & correspondence

8303010634 Forwards IE Insp Repts 50-280/82-35 & 50-281/82-35 during Dec 1982. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/01/28.
STEWART, W. L. Virginia Electric & Power Co. 2pp. 17336:123. 24X
Fiche: 50-280, 83/01/28, 8303010634.

--8303010645 IE Insp Repts 50-280/82-35 & 50-281/82-35 during Dec 1982. No noncompliance noted. Major areas inspected: plant operations, operating records, maint & security, followup of events & LERs.
BURKE, D. J., DAVIS, M. J., JULIAN, C. Division of Project & Resident Programs. 83/01/27. 6pp. 17336:125. 24X Fiche: 50-280, 83/01/28, 8303010634.

8303010643 Ack receipt of 830202 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/82-34 & 50-281/82-34.
LEWIS, R. C. Division of Project & Resident Programs. 83/02/18.
STEWART, W. L. Virginia Electric & Power Co. 1p. 17336:212. 24X
Fiche: 50-280, 83/02/18, 8303010643.

--8303010655 Responds to NRC 830112 ltr re violations noted in IE Insp Repts 50-280/82-34 & 50-281/82-34. Corrective actions: operations dept instructed on potential of tank filling overpressurization & filling methods to prevent problem.
STEWART, W. L. Virginia Electric & Power Co. 83/02/02.
O'REILLY, J. P. [illegible], Region 2, Office of Director. 2pp. 17336:213. 24X
Fiche: 50-280, 83/02/18, 8303010643.

--8303010661 Forwards IE Insp Repts 50-280/82-34 & 50-281/82-34 on 821101-30 & notice of violation.
LEWIS, R. C. Division of Project & Resident Programs. 83/01/12.
STEWART, W. L. Virginia Electric & Power Co. 2pp. 17336:218. 24X
Fiche: 50-280, 83/02/18, 8303010643.

--8303010673 IE Insp Repts 50-280/82-34 & 50-281/82-34 on 821101-30. Noncompliance noted: failure to perform or maintain written safety evaluation when mod to component cooling water sys implemented.
BURKE, D. J., DAVIS, M. J., JULIAN, C. Division of Project & Resident Programs. 83/01/07. 10pp. 17336:221. 24X Fiche: 50-280, 83/02/18, 8303010643.

8303210678 Forwards IE Insp Repts 50-280/83-03 & 50-281/83-03 on 830131-0204. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/02/23.
STEWART, W. L. Virginia Electric & Power Co. 2pp. 17635:257. 24X
Fiche: 50-280, 83/02/23, 8303210678.

--8303210693 IE Insp Repts 50-280/83-03 & 50-281/83-03 on 830131-0204. No noncompliance noted. Major areas inspected: review of lab QC program & comparison of analyses of split samples analyzed by licensee & Region II mobile lab.
EVANS, C. D., KUZO, G. B., MONTGOMERY, D. Region 2, Office of Director. 83/02/22. 8pp. 17635:259. 24X Fiche: 50-280, 83/02/23, 8303210678.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210342 Forwards IE Insp Repts 50-280/83-04 & 50-281/83-04 on 830103-0131. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/03/01.
STEWART, W. L. Virginia Electric & Power Co. 2pp. 17634:282. 24X Fiche: 50-280, 83/03/01, 8303210342.

--8303210346 IE Insp Repts 50-280/83-04 & 50-281/83-04 on 830103-31. No noncompliance noted. Major areas inspected: plant operations & operating records, plant maint & surveillance, plant security & followup of previous events & LERs.
BURKE, D. J., DAVIS, M. J. Region 2, Office of Director. JULIAN, C. A. Division of Project & Resident Programs. 83/02/28. 6pp. 17634:284. 24X Fiche: 50-280, 83/03/01, 8303210342.

8303210523 Forwards response to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Operators reviewed Salem event. Operability tests performed.
STEWART, W. L. Virginia Electric & Power Co. 83/03/04. O'REILLY, J. P. Region 2, Office of Director. 4pp. 17632:219. 24X Fiche: 50-000, 83/03/04, 8303210523.

8303110323 Submits suppl info re draft SER on inservice insp relief requests. Hydrostatic tests impractical in portions of sys such as component cooling, spent fuel pit cooling, svc water & boric acid transfer.
STEWART, W. L. Virginia Electric & Power Co. 83/03/07. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARGA, S. A. Operating Reactors Branch 1. 2pp. 17520:078. 24X Fiche: 50-280, 83/03/07, 8303110323.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 82-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 12lpp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303290389 Forwards IE Safeguards Insp Repts 50-280/83-07 & 50-281/83-06 on 830228-0304. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/03/23.
STEWART, W. L. Virginia Electric & Power Co. 2pp. 17725:318. 24X Fiche: 50-280, 83/03/23, 8303290389.

--8303290403 IE Safeguards Insp Repts 50-280/83-07 & 50-281/83-04 on 830228-0304. No noncompliance noted. Major areas inspected: review of security plan implementation, records & repts & physical barriers. Details withheld (ref 10CFR73.21).
TILLMAN, A. Region 2, Office of Director. MCGUIRE, D. R. Division of Emergency Preparedness & Materials Safety. 83/03/23. 1p. 17725:320. 24X Fiche: 50-280, 83/03/23, 8303290389.

## R. Periodic operating reports & related correspondence

8303080035 Forwards monthly operating repts for Dec 1982.
STEWART, W. L. Virginia Electric & Power Co. 83/01/14. HALLER, N. M. Office of Management and Program Analysis. 2pp. 17456:001. 24X Fiche: 50-280, 83/01/14, 8303080035.

--8303080037 Monthly operating repts for Dec 1982.
WILSON, J., DUNN, S. D., COSTELLO, D. J. Virginia Electric & Power Co. 83/01/06. 52pp. 17456:003. 24X Fiche: 50-280, 83/01/14, 8303080035.

8303150370 Forwards monthly operating repts for Jan 1983.
STEWART, W. L. Virginia Electric & Power Co. 83/02/15. HALLER, N. M. Office of Resource Management, Director. 1p. 17562:132. 24X Fiche: 50-280, 83/02/15, 83031503/0.

--8303150376 Monthly operating repts for Jan 1983.
JONES, V. H., WILSON, J. Virginia Electric & Power Co. 83/02/03. 42pp. 17562:133. 24X Fiche: 50-280, 83/02/15, 8303150370.

## S. Reportable occurrences, LERs & related correspondence

8303140523 Forwards LERs 83-003/03L-0 & 83-004/03L-0.
WILSON, J. L. Virginia Electric & Power Co. 83/02/25. O'REILLY, J. P. Region 2, Office of Director. 1p. 17533:346. 24X Fiche: 50-281, 83/02/25, 8303140523.

--8303140532 LER 83-003/03L-0 on 830202, w/unit at 100% power & emergency diesel generator 3 out of svc for maint, containment vacuum pump, 2-CV-P-1A, failed to develop flow. Caused by binding of sliding vanes in pump rotor. Pump replaced w/shop spare.
WILSON, J. L. Virginia Electric & Power Co. 83/02/25. Region 2, Office of Director. 3pp. 17533:347. 24X Fiche: 50-281, 83/02/25, 8303140523.

--8303140540 LER 83-004/03L-0 on 830204, w/unit at 100% power, amp reading for panel 9, circuit 20C below Tech Spec limits, due to failure of heat tracing circuit. Caused by open thermostat. Thermostat replaced & heat tracing circuit returned to svc.
WILSON, J. L. Virginia Electric & Power Co. 83/02/25. Region 2, Office of Director. 2pp. 17533:350. 24X Fiche: 50-281, 83/02/25, 8303140523.

8303160149 Forwards LERs 83-005/03L-0 & 83-006/03L-0.
WILSON, J. L. Virginia Electric & Power Co. 83/03/04. O'REILLY, J. P. Region 2, Office of Director. 1p. 17597:078. 24X Fiche: 50-281, 83/03/04, 8303160149.

--8303160157 LER 83-005/03L-0 on 830211, during Full Power Test PT-15.1C, turbine driven auxiliary feed pump ran intermittently. Caused by corrosion piston of pump governor regulator. Piston cleaned.
WILSON, J. L. Virginia Electric & Power Co. 83/03/04. Region 2, Office of Director. 2pp. 17597:079. 24X Fiche: 50-281, 83/03/04, 8303160149.

--8303160165 LER 83-006/03L-0 on 830214, during full power, trip valve TV-DA-200B failed to close when containment sump pump stopped. Caused by defective solenoid-operated valve. Valve replaced.
WILSON, J. L. Virginia Electric & Power Co. 83/03/04. Region 2, Office of Director. 2pp. 17597:081. 24X Fiche: 50-281, 83/03/04, 8303160149.

8303240464 Forwards LER 83-007/03L-0.
WILSON, J. L. Virginia Electric & Power Co. 83/03/17. O'REILLY, J. P. Region 2, Office of Director. 1p. 17678:043. 24X Fiche: 50-281, 83/03/17, 8303240464.

--8303240472 LER 83-007/03L-0 on 830217, operators discovered heat tracing panels 8 & 9 circuit 2 & 13 tagged out & de-energized. Caused by operator improperly performing tagout procedure. Circuits energized & verified operable.
WILSON, J. L. Virginia Electric & Power Co. 83/03/17. Region 2, Office of Director. 1p. 17678:044. 24X Fiche: 50-281, 83/03/17, 8303240464.

## V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

## Y. Dry Cask Independent Spent Fuel Storage Installations

8303020215 Forwards suppl to ISFSI SAR, which reflects actual submittal of C-E Topical Rept CENPD-270 describing design for dry storage casks appropriate for use in storage.
STEWART, W. L. Virginia Electric & Power Co. 83/01/25.
CUNNINGHAM, R. E. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 17357:357. 24X Fiche: 50-280, 83/01/25, 8303020215.

8303280315 Comments on util application for ISFSI. Topical rept review comments to C-E encl to keep util appraised of progress of review of C-E rept, "Dry Storage Cask for ISFSI," dtd Oct 1982.
ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch. 83/03/16.
STEWART, W. L. Virginia Electric & Power Co. 37pp. 17713:251. 24X Fiche: 50-280, 83/03/16, 8303280315.

# DOCKETED ITEMS

DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8303100180 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 83/03/02 Document Management Branch 1p 17495:148 24X Fiche 50-000, 83/03/02, 8303100180

--8303100186 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1.10 re offsite surveys, EPIP 1.1.11 re accident assessment & EPIP 1.1.14 re vendor & consultant svcs.
WARD, E. C. Northern States Power Co. 83/02/17 Region 3, Office of Director 1p 17495:149 24X Fiche 50-000, 83/03/02, 8303100180

--8303100193 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1.10 re offsite surveys, EPIP 1.1.11 re accident assessment & EPIP 1.1.14 re vendor & consultant svcs.
HUDSON, G., WARD, E. C. Northern States Power Co. 83/02/17 62pp 17495:150 24X Fiche 50-000, 83/03/02, 8303100180

8303210090 Forwards IE Insp Repts 50-282/83-03 & 50-306/83-02 on 830131-0204. No noncompliance noted.
PAPERIELLO, C. J. Region 3, Office of Director 83/03/02
LARSON, C. E. Northern States Power Co. 2pp 17630:174 24X
Fiche 50-282, 83/03/02, 8303210090

--8303210097 IE Insp Repts 50-282/83-03 & 50-306/83-02 on 830131-0204. No noncompliance noted. Major areas inspected: action taken re NRC 811217 confirmation of action ltr & emergency preparedness appraisal improvement items.
PATTERSON, J. P., GLOERSEN, W. S., AXELSON, W. L. Region 3, Office of Director 83/02/28 12pp 17630:176 24X Fiche 50-282, 83/03/02, 8303210090

8303150703 Responds to 821230 request for changes submitted as Rev 8 to security plan. Changes consistent w/provisions of 10CFR50.54 & do not decrease effectiveness of plan except for change re rotation of locks.
CLARK, R. A. Operating Reactors Branch 3 83/03/10 MUSOLF, D. M.
Northern States Power Co. 2pp 17586:240 24X
Fiche 50-282, 83/03/10, 8303150703

8303170215 Requests relief from fixed suppression sys installation requirement of 10CFR50.48, Paragraph b, for Fire Areas 58, 59, 73 & 74.
MUSOLF, D. Northern States Power Co. 83/03/11 Office of Nuclear Reactor Regulation, Director 38pp 17606:079 24X
Fiche 50-282, 83/03/11, 8303170215

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director 83/03/22 Commonwealth Edison Co. 2pp 17690:316 24X Fiche 50-000, 83/03/22, 8303240440

I. Financial information

8303280039 Forwards Annual Financial Rept 1982.
BRUSVEN, A. D. Northern States Power Co. 83/03/23 Office of Nuclear Reactor Regulation, Director 1p 17707:107 24X
Fiche 50-000, 83/03/23, 8303280039

--8303280044 Annual Financial Rept 1982.
* Northern States Power Co. 82/12/31 43pp 17707:108 24X
Fiche 50-000, 83/03/23, 8303280039

8303300123 Forwards suppl to Annual Financial Rept 1982.
BRUSVEN, A. D. Northern States Power Co. 83/03/25 Office of Nuclear Reactor Regulation, Director 1p 17734:330 24X
Fiche 50-000, 83/03/25, 8303300123

--8303300133 Suppl to Annual Financial Rept 1982.
* Northern States Power Co. 83/03/31 21pp 17734:331 24X
Fiche 50-000, 83/03/25, 8303300123

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X
Fiche 50-000, 83/02/16, 8302170082

8303090265 Forwards safety evaluation re reactor physics & reload safety evaluation methods, based on review of 821213 submittal of Technical Repts NSPNAD-8101P, Rev 1 & NSPNAD-8102P, Rev 1. Methods acceptable.
CLARK, R. A. Operating Reactors Branch 3 83/02/17 MUSOLF, D. M.
Northern States Power Co. 2pp 17485:098 24X
Fiche 50-282, 83/02/17, 8303090265

--8303090272 Safety evaluation supporting reactor physics & reload safety evaluation methods addressed in Technical Repts NSPNAD-8101P & 8102P. Methods acceptable.
* Office of Nuclear Reactor Regulation, Director 83/02/17 82pp 17485:100 24X Fiche 50-282, 83/02/17, 8303090265

8303140077 Forwards Amends 62 & 56 to Licenses DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & availability. Amends revise Tech Specs for compliance w/ testing requirements of 10CFR50, App J.
DIIANNI, D. C. Operating Reactors Branch 3 83/02/23 MUSOLF, D. M.
Northern States Power Co. 2pp 17548:002 24X
Fiche 50-282, 83/02/23, 8303140077

--8303140082 Amends 62 & 56 to Licenses DPR-42 & DPR-60, respectively, revising Tech Specs for compliance w/testing requirements of 10CFR50, App J.
CLARK, R. A. Operating Reactors Branch 3 83/02/23 17pp 17548:004 24X Fiche 50-282, 83/02/23, 8303140077

--8303140089 Safety evaluation supporting Amends 62 & 56 to Licenses DPR-42 & DPR-60, respectively. Technical evaluation rept encl.
* Office of Nuclear Reactor Regulation, Director 83/02/23 19pp 17548:022 24X Fiche 50-282, 83/02/23, 8303140077

--8203290497 "Containment Leakage Rate Testing."
DELGAIZO, T. J. Franklin Institute/Franklin Research Center, NRC-03-79-118 TER-C5257-43/44 82/03/25 HUANG, Y. S. NRC - No Detailed Affiliation Given 21pp 17548:041 24X
Fiche 50-282, 83/02/23, 8303140077

--8303140115 Notice of issuance & availability of Amends 62 & 56 to Licenses DPR-42 & DPR-60, respectively.
CLARK, R. A. Operating Reactors Branch 3 83/02/23 2pp 17548:061 24X Fiche 50-282, 83/02/23, 8303140077

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X
Fiche 50-000, 83/03/02, 8303020321

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J. G. Region 3, Office of Director 83/03/03
Commonwealth Edison Co. 2pp 17492:014 24X Fiche 50-000, 83/03/03, 8303100364

8303140250 Advises that TMI Action Item III.D.3.4, "Control Room Habitability Mod" will be completed on 830531. Delay due to design changes to test procedures.
MUSOLF, D. Northern States Power Co. 83/03/03 Office of Nuclear Reactor Regulation, Director 1p 17538:337 24X
Fiche 50-282, 83/03/03, 8303140250

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp 17660:176 24X
Fiche 50-000, 83/03/07, 8303040005

8303180131 Notification of 830318 meeting w/util & Franklin Research Ctr in Bethesda, MD to discuss resolution of open items in technical evaluation rept re control of heavy loads.
DIIANNI, D. C. Operating Reactors Branch 3 83/03/10 CLARK, R. A.
Operating Reactors Branch 3 2pp 17625:134 24X
Fiche 50-282, 83/03/10, 8303180131

8303170381 Forwards response to Generic Ltr 82-28 requesting submittal of info re inadequate core cooling instrumentation per revised post-TMI requirements.
MUSOLF, D. Northern States Power Co. 83/03/14 Office of Nuclear Reactor Regulation, Director 9pp 17610:075 24X
Fiche 50-282, 83/03/14, 8303170381

8303230153 Forwards order confirming commitments to implement post-TMI related items scheduled for completion on or after 820701, based on Generic Ltrs 82-05 & 82-10.
CLARK, R A Operating Reactors Branch 3 83/03/14 MUSOLF, D M Northern States Power Co 3pp 17686:190 24X
Fiche: 50-282, 83/03/14, 8303230153.

--8303230159 Order confirming licensee commitments to implement & maintain post-TMI related issues.
PURPLE, R A Division of Licensing 83/03/14 Northern States Power Co 10pp 17686:193 24X Fiche: 50-282, 83/03/14, 8303230153.

8303210058 Provides addl info re NUREG-0737, Item II.D.1.2, "Relief & Safety Valve Performance." Westinghouse & Crosby Valve working on scheme to optimize valve ring settings. Fluor Power investigating effects of increased support loadings.
MUSOLF, D Northern States Power Co 83/03/15 Office of Nuclear Reactor Regulation, Director 2pp 17630:254 24X
Fiche: 50-282, 83/03/15, 8303210058.

8303310281 Forwards proprietary info presented at 830223 meeting w/NRC in Bethesda, MD re fuel assembly failure. Info withheld (ref 10CFR2.790).
MUSOLF, D Northern States Power Co 83/03/22 Office of Nuclear Reactor Regulation, Director 1p 17756:151 24X
Fiche: 50-282, 83/03/22, 8303310281.

--8303310287 Authorizes utilization of encl Affidavit AW-77-47 in support of Northern States Power request to withhold proprietary info per 10CFR2.790.
WIESEMANN, R A Westinghouse Electric Corp 83/03/17 THOMAS, C O Standardization & Special Projects Branch 6pp 17756:152 24X
Fiche: 50-282, 83/03/22, 8303310281.

## G. Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 11lpp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303030450 Clarifies NRC position re procedures for admitting NRC personnel to facilities. Lists of NRC inspectors & personnel likely to visit facility two or more times per yr & at anytime encl. Lists will be updated every 6 months.
KEPPLER, J G Region 3, Office of Director 83/02/28 LARSON, C E Northern States Power Co 6pp 17410:049 24X
Fiche: 50-282, 83/02/28, 8303030450.

8303210090 Forwards IE Insp Repts 50-282/83-03 & 50-306/83-02 on 830131-0204. No noncompliance noted.
PAPERIELLO, C J Region 3, Office of Director 83/03/02
LARSON, C E Northern States Power Co 2pp 17630:174 24X
Fiche: 50-282, 83/03/02, 8303210090.

--8303210097 IE Insp Repts 50-282/83-03 & 50-306/83-02 on 830131-0204. No noncompliance noted. Major areas inspected, action taken re NRC 811217 confirmation of action ltr & emergency preparedness appraisal improvement items.
PATTERSON, J P ; GLOERSEN, W B ; AXELSON, W L Region 3, Office of Director 83/02/28 12pp 17630:176 24X Fiche: 50-282, 83/03/02, 8303210090.

8303150269 Responds to IE Bulletin 83-01 Testing of reactor main trip breakers accomplished. Breaker maint program reviewed & found to conform to vendor recommendation. Operators advised of Salem event & appropriate actions.
LARSON, C E Northern States Power Co 83/03/04 KEPPLER, J G Region 3, Office of Director 1p 17567:229 24X
Fiche: 50-282, 83/03/04, 8303150269.

8303110299 Forwards "Inservice Insp - Exam Summary Prairie Island Nuclear Generating Plant - Unit 1 821115 to 830110."
MUSOLF, D Northern States Power Co 83/03/07 Office of Nuclear Reactor Regulation, Director 2pp 17517:117 24X
Fiche: 50-282, 83/03/07, 8303110299.

--8303110301 "Inservice Insp - Exam Summary Prairie Island Nuclear Generating Plant - Unit 1 821115 to 830110."
ANDERSON, M T ; COLEMAN, R J ; SCHANEN, J F Northern States Power Co 83/02/10 146pp 17517:119 24X Fiche: 50-282, 83/03/07, 8303110299.

8303240538 Forwards IE Insp Repts 50-282/83-01 & 50-306/83-01 on 830124-27 & notice of violation.
STREETER, J F Region 3, Office of Director 83/03/09 LARSON, C E Northern States Power Co 2pp 17682:322 24X
Fiche: 50-282, 83/03/09, 8303240538.

--8303240546 Notice of violation from insp on 830124-27.
STREETER, J F Region 3, Office of Director 83/03/09 2pp 17682:324 24X Fiche: 50-282, 83/03/09, 8303240538.

--8303240556 IE Insp Repts 50-282/83-01 & 50-306/83-01 on 830124-27. Noncompliance noted: failure to establish required log & procedures implementing Sections 5.7.9 & 10 of ANSI N45.2.11-1974 & to implement 10CFR21.6(a) & 31.
BRICKLEY, R H ; JACKIW, I N Region 3, Office of Director 83/03/07 3pp 17682:326 24X Fiche: 50-282, 83/03/09, 8303240538.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc 117pp 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 121pp 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

8303290454 Responds to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Sys Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel)." No abnormal buildup of clams identified. Flow monitoring instrumentation installed.
LARSON, C E Northern States Power Co 83/03/22 KEPPLER, J G Region 3, Office of Director 2pp 17725:329 24X
Fiche: 50-282, 83/03/22, 8303290454.

## R. Periodic operating reports & related correspondence

8303080049 Forwards monthly operating repts for Dec 1982.
MUSOLF, D Northern States Power Co 83/01/12 Director's Office, Office of Inspection and Enforcement 1p 17454:354 24X
Fiche: 50-282, 83/01/12, 8303080049.

--8303080053 Monthly operating repts for Dec 1982.
DUGSTAD, D Northern States Power Co 83/01/05 8pp 17454:355 24X Fiche: 50-282, 83/01/12, 8303080049.

8303150460 Forwards monthly operating repts for Jan 1983.
MUSOLF, D Northern States Power Co 83/02/10 Office of Resource Management, Director 1p 17561:044 24X Fiche: 50-282, 83/02/10, 8303150460.

--8303150462 Monthly operating repts for Jan 1983.
DUGSTAD, D Northern States Power Co 83/02/04 8pp 17561:045 24X Fiche: 50-282, 83/02/10, 8303150460.

8303150277 Forwards "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1982."
MUSOLF, D Northern States Power Co 83/03/01 Region 3, Office of Director 1p 17567:138 24X Fiche: 50-282, 83/03/01, 8303150277.

--8303150280 "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1982."
* Northern States Power Co 83/03/01 20pp 17567:139 24X
Fiche: 50-282, 83/03/01, 8303150277.

## S. Reportable occurrences, LERs & related correspondence

8303110513 Summary of 830223 meeting w/util & Westinghouse in Bethesda, MD re fuel assembly failure in spent fuel pool.
DIIANNI, D C Operating Reactors Branch 3 83/03/04 Operating Reactors Branch 3 6pp 17522:348 24X Fiche: 50-282, 83/03/04, 8303110513.

8303220213 Forwards revised LER 82-021/03X-1.
MUSOLF, D Northern States Power Co 83/03/14 Region 3, Office of Director 1p 17656:250 24X Fiche: 50-282, 83/03/14, 8303220213.

--8303220219 Revised LER 82-021/03X-1 on 821027, following sampling procedure, hot leg loop B sample inside containment isolation valve failed to remain closed. Caused by fault in connector supplying electrical power to Valcor 3/8-inch solenoid.
HUNSTAD, A A Northern States Power Co 83/03/14 Region 3, Office of Director 2pp 17656:251 24X Fiche: 50-282, 83/03/14, 8303220213.

V. Operator Examinations

8302250505 Generic Ltr 82-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche 50-000, 83/02/24, 8302250505.

8303040478 Submits schedule for operator licensing exams in response to Generic Ltr 83-01 Plans based on current rate of turnover & anticipated exam needs.
MUSOLF, D. M. Northern States Power Co. 83/02/28 Office of Nuclear Reactor Regulation, Director 2pp. 17373:361 24X Fiche 50-000, 83/02/28, 8303040478.

DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8303280224 Notifies that emergency notification sys telephone will be installed in permanent emergency operations facility per 821119 request Health physics network telephone will not be installed due to changeover to FTS.
SEIDLE, W. C. Region 4, Office of Director 83/01/17 JONES, W. C. Omaha Public Power District 2pp. 17708:218 24X Fiche 50-285, 83/01/17, 8303280224.

--8303280234 Requests that health physics network & emergency notification sys telephones be installed in permanent emergency operations facility by 830101.
JONES, W. C. Omaha Public Power District 82/11/19 SEIDLE, W. C. Region 4, Office of Director 1p. 17708:220 24X Fiche 50-285, 83/01/17, 8303280224.

8303210673 Forwards IE Insp Rept 50-285/83-04 on 830124-28 No noncompliance noted.
SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 83/02/16 JONES, W. C. Omaha Public Power District 2pp. 17635:246 24X Fiche 50-285, 83/02/16, 8303210673.

--8303210683 IE Insp Rept 50-285/83-04 on 830124-28 No noncompliance noted Major areas inspected licensee action on previously identified items, fire prevention implementation, requalification training & training.
JAUDON, J. P., MURPHY, M. E., JOHNSON, W. D. Region 4, Office of Director 83/02/16 9pp. 17635:248 24X Fiche 50-285, 83/02/16, 8303210673.

8303010413 Requests assistance in determining optimal locations for emergency notification sys & health physics network (HPN) phones in emergency response facilities, supplementing NUREG-0696 Replacement of HPN lines w/FTS lines considered.
COLLINS, J. T. Region 4, Office of Director 83/02/24 JONES, W. C. Omaha Public Power District 2pp. 17343:361 24X Fiche 50-285, 83/02/24, 8303010413.

8303100097 Releases public version of revised radiological emergency response plan.
FELTON, J. M. Division of Rules and Records 83/03/02 Document Management Branch 1p. 17496:175 24X Fiche 50-285, 83/03/02, 8303100097.

--8303100101 Forwards public version of Rev 1 to radiological emergency response plan Receipt form encl.
JONES, W. C. Omaha Public Power District 83/02/16 COLLINS, J. T. Region 4, Office of Director 2pp. 17496:176 24X Fiche 50-285, 83/03/02, 8303100097.

--P8303100123 Public version of Rev 1 to radiological emergency response plan.
* Omaha Public Power District 83/01/31 56pp. 17496:178 24X Fiche 50-285, 83/03/02, 8303100097.

8303100562 Releases public version of licensee request for return of copies of emergency response plan & implementing procedures.
FELTON, J. M. Division of Rules and Records 83/03/02 Document Management Branch 1p. 17521:354 24X Fiche 50-285, 83/03/02, 8303100562.

--8303100565 Submits public version of request for return of Copies 157-164 of radiological emergency response plan & implementing procedures Recent rev to 10CFR50.54(q) & App E reduces number of copies required to be submitted.
JONES, W. C. Omaha Public Power District 83/02/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p. 17521:355 24X Fiche 50-285, 83/03/02, 8303100562.

8303100566 Releases public version of emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 83/03/02 Document Management Branch 1p. 17521:351 24X Fiche 50-285, 83/03/02, 8303100566.

--8303100569 Forwards public version of emergency plan implementing procedures W/o encl.
JONES, W. C. Omaha Public Power District 83/01/25 COLLINS, J. T. Region 4, Office of Director 1p. 17521:352 24X Fiche 50-285, 83/03/02, 8303100566.

8303250002 Forwards IE Insp Rept 50-285/83-02 on 830110-14 Notice of violation withheld (ref 10CFR73.21).
SEIDLE, W. C. Division of Project & Resident Programs 83/03/22 JONES, W. C. Omaha Public Power District 2pp. 17692:116 24X Fiche 50-285, 83/03/22, 8303250002.

--8303250008 IE Insp Rept 50-285/83-02 on 830110-14 Noncompliance noted violation identified in security program audit Details withheld (ref 10CFR73.21).
EVANS, C. A., KELLY, J. A. F. Region 4, Office of Director 83/02/14 1p. 17692:118 24X Fiche 50-285, 83/03/22, 8303250002.

8303290493 Clarifies repts re telephone inquiries about security sys from unidentified persons during Jan 1983 Inquiries violated protection of safeguards info Investigation determined that personnel recruiter unknowingly asked questions.
COLLINS, J. T. Region 4, Office of Director 83/03/25 JONES, W. C. Omaha Public Power District 2pp. 17725:032 24X Fiche 50-285, 83/03/25, 8303290493.

J. Insurance & indemnity information

8303280183 Submits onsite property damage & decontamination insurance rept as of 830401, per 10CFR50.54(W)(4).
PETERSEN, H. E. Omaha Public Power District 83/03/23 SALTZMAN, J. Assistant Director for State & Licensee Relations 1p. 17709:184 24X Fiche 50-285, 83/03/23, 8303280183.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp. 17492:033 24X Fiche 50-000, 83/02/16, 8302170082.

8302230355 Forwards responses to Part A of 830201 request for addl info re Cycle 8 reload application Responses withheld (ref 10CFR2.790).
JONES, W. C. Omaha Public Power District 83/02/18 CLARK, R. A. Operating Reactors Branch 3 6pp. 17248:157 24X Fiche 50-285, 83/02/18, 8302230355.

8303030091 Summary of 830217 meeting w/util & C-E in Bethesda, MD re Cycle 8 reload application.
TOURIGNY, E. G. Operating Reactors Branch 3 83/02/18 Operating Reactors Branch 3 5pp. 17365:296 24X Fiche 50-285, 83/02/18, 8303030091.

8303110431 Forwards Amend 67 to License DPR-40, safety evaluation & notice of issuance & availability Amend revises limits for reactor coolant & steam generator coolant radioactivity.
TOURIGNY, E. G. Operating Reactors Branch 3 83/02/23 JONES, W. C. Omaha Public Power District 3pp. 17523:001 24X Fiche 50-285, 83/02/23, 8303110431.

--8303110434 Amend 67 to License DPR-40, revising limits for reactor coolant & steam generator coolant radioactivity.
CLARK, R. A. Operating Reactors Branch 3 83/02/23 15pp. 17523:004 24X Fiche 50-285, 83/02/23, 8303110431.

--8303110436 Safety evaluation supporting Amend 67 to License DPR-40.
* Office of Nuclear Reactor Regulation, Director 83/02/23 3pp. 17523:019 24X Fiche 50-285, 83/02/23, 8303110431.

--8303110440 Notice of issuance & availability of Amend 67 to License DPR-40.
CLARK, R. A. Operating Reactors Branch 3 83/02/23 2pp. 17523:022 24X Fiche 50-285, 83/02/23, 8303110431.

8303090399 Forwards Amend 68 to License DPR-40, safety evaluation & notice of issuance & availability Amend adds limiting conditions for operation & surveillance requirements for containment purge isolation valves.
TOURIGNY, E. G. Operating Reactors Branch 3 83/02/24 JONES, W. C. Omaha Public Power District 4pp. 17484:099 24X Fiche 50-285, 83/02/24, 8303090399.

--8303090402 Amend 68 to License DPR-40, adding limiting conditions for operation & surveillance requirements for containment purge isolation valves.
CLARK, R. A. Operating Reactors Branch 3. 83/02/24. 9pp.
17484:103. 24X Fiche: 50-285, 83/02/24, 8303090399.

--8303090406 Safety evaluation supporting Amend 68 to License DPR-40.
* Office of Nuclear Reactor Regulation, Director. 83/02/24. 4pp.
17484:112. 24X Fiche: 50-285, 83/02/24, 8303090399.

--8303090409 Notice of issuance & availability of Amend 68 to License DPR-40.
CLARK, R. A. Operating Reactors Branch 3. 83/02/24. 2pp.
17484:116. 24X Fiche: 50-285, 83/02/24, 8303090399.

8303010228 Forwards Part B of response to NRC 830201 request for addl info re util Cycle 6 reload application. Part A response provided 830218. C-E retained to perform independent verification of methodology/computer codes.
JONES, W. C. Omaha Public Power District. 83/02/25. CLARK, R. A.
Operating Reactors Branch 3. 5pp. 17335:062. 24X
Fiche: 50-285, 83/02/25, 8303010228.

8303090204 Forwards replacement pages to 821122 application to amend License DPR-40, changing Tech Spec limit on total planar radial peak factor.
JONES, W. C. Omaha Public Power District. 83/02/28. CLARK, R. A.
Operating Reactors Branch 3. 1p. 17492:141. 24X
Fiche: 50-285, 83/02/28, 8303090204.

--8303090209 Replacement pages to 821122 application to amend License DPR-40, changing Tech Spec limit on total planar radial peak factor.
* Omaha Public Power District. 83/02/28. 4pp. 17492:142. 24X
Fiche: 50-285, 83/02/28, 8303090204.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303110082 Advises that fee submitted w/821222 application for amend to License DPR-40 re changes to operation at nominal reactor core power level will be refunded.
MILLER, W. O. License Fee Management Branch. 83/03/03. JONES, W. C.
Omaha Public Power District. 1p. 17526:289. 24X
Fiche: 50-285, 83/03/03, 8303110082.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 31pp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303090181 Forwards util application for amend to License DPR-40, revising RCS heatup & cooldown limits for operation through end of Cycle 6. Certificate of Svc & justification encl w/o stated application.
* LeBoeuf, Lamb, Leiby & MacRae. * Omaha Public Power District. 83/03/07. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 15pp. 17467:001. 24X Fiche: 50-285, 83/03/07, 8303090181.

8303150665 Forwards SER of util response to TMI Action Item II.B.2.2, "Plant Shielding Mods for Vital Area Access." NUREG-0737 requirements met.
CLARK, R. A. Operating Reactors Branch 3. 83/03/07. JONES, W. C.
Omaha Public Power District. 4pp. 17586:258. 24X
Fiche: 50-285, 83/03/07, 8303150665.

8303160026 Forwards request for addl info re adequacy of station electric distribution sys voltages. Response requested within 45 days of ltr receipt.
CLARK, R. A. Operating Reactors Branch 3. 83/03/07. JONES, W. C.
Omaha Public Power District. 4pp. 17615:050. 24X
Fiche: 50-285, 83/03/07, 8303160026.

8303150196 Submits status & updated schedule for completion of mods required per NUREG-0737, Item III.D.3.4, "Control Room Habitability." Schedule for installation of toxic gas monitors revised from 840101 to 840630.
JONES, W. C. Omaha Public Power District. 83/03/08. CLARK, R. A.
Operating Reactors Branch 3. 2pp. 17551:188. 24X
Fiche: 50-285, 83/03/08, 8303150196.

8303150205 Submits addl status update on environ qualification testing of Conax electrical containment penetrations. Abnormal leakage during electrical penetration testing consequence of testing method.
JONES, W. C. Omaha Public Power District. 83/03/08. CLARK, R. A.
Operating Reactors Branch 3. 2pp. 17568:336. 24X
Fiche: 50-285, 83/03/08, 8303150205.

8303150222 Forwards response to Generic Ltr 82-28 re inadequate core cooling instrumentation sys. C-E heated junction thermocouple sys will be installed to monitor RCS inventory.
JONES, W. C. Omaha Public Power District. 83/03/08. CLARK, R. A.
Operating Reactors Branch 3. 9pp. 17556:071. 24X
Fiche: 50-285, 83/03/08, 8303150222.

8303150340 Advises of 830405 meeting w/licensees & major contractors at Dallas/Fort Worth, TX to provide info & guidance re 10CFR50 QA & Tech Spec deviations & discuss decentralization policy. Questions should be submitted in writing by 830321.
COLLINS, J. T. Region 4, Office of Director. 83/03/10. Public Service Co. of Colorado. 12pp. 17562:291. 24X
Fiche: 50-000, 83/03/10, 8303150340.

8303150281 Notifies of 830405 public meeting at Dallas/Ft Worth, TX Airport to discuss decentralization policy & 10CFR50 reporting requirement.
COLLINS, J. T. Region 4, Office of Director. 83/03/11. JONES, W. C.
Omaha Public Power District. 3pp. 17567:159. 24X
Fiche: 50-285, 83/03/11, 8303150281.

8303180012 Forwards addl info re in-core detector string operability, in response to NRC 830202 ltr. In-core detector sys not required nor designed to measure off-normal power distribution due to dropped control element assembly.
JONES, W. C. Omaha Public Power District. 83/03/11. CLARK, R. A.
Operating Reactors Branch 3. 3pp. 17618:133. 24X
Fiche: 50-285, 83/03/11, 8303180012.

8303240020 Forwards request for addl info to complete review of 830121 submittal re spent fuel mod for increased storage capacity. Response requested within 30 days.
CLARK, R. A. Operating Reactors Branch 3. 83/03/11. JONES, W. C.
Omaha Public Power District. 7pp. 17694:331. 24X
Fiche: 50-285, 83/03/11, 8303240020.

8303240315 Forwards Amend 69 to License DPR-40 & notice of issuance & availability. Amend deletes App B ETS re nonradiological water quality-related requirements of Federal Water Pollution Control Act.
CLARK, R. A. Operating Reactors Branch 3. 83/03/11. JONES, W. C.
Omaha Public Power District. 4pp. 17690:345. 24X
Fiche: 50-285, 83/03/11, 8303240315.

--8303240323 Amend 69 to License DPR-40, deleting App B ETS re nonradiological water quality-related requirements.
CLARK, R. A. Operating Reactors Branch 3. 83/03/11. 3pp.
17690:349. 24X Fiche: 50-285, 83/03/11, 8303240315.

--8303240333 Notice of issuance & availability of Amend 69 to License DPR-40.
CLARK, R. A. Operating Reactors Branch 3. 83/03/11. 2pp.
17690:352. 24X Fiche: 50-285, 83/03/11, 8303240315.

8303220467 Forwards order confirming commitments to implement NUREG-0737 post-TMI items scheduled for completion on or after 810701. Order based on commitments contained in responses to Generic Ltrs 82-05 & 82-10.
CLARK, R. A. Operating Reactors Branch 3. 83/03/14. JONES, W. C.
Omaha Public Power District. 3pp. 17670:177. 24X
Fiche: 50-285, 83/03/14, 8303220467.

--8303220476 Order confirming licensee commitments to implement & maintain post-TMI issues per response to Generic Ltrs 82-05 & 82-10.
PURPLE, R. A. Division of Licensing. 83/03/14. Omaha Public Power District. 9pp. 17670:180. 24X Fiche: 50-285, 83/03/14, 8303220467.

8303300144 Forwards Amend 70 to License DPR-40, safety evaluation & notice of issuance & availability. Amend revises Tech Specs to be consistent w/Cycle 6 reload analysis.
TOURIGNY, E. G. Operating Reactors Branch 3. 83/03/15. JONES, W. C.
Omaha Public Power District. 4pp. 17750:346. 24X
Fiche: 50-285, 83/03/15, 8303300144.

--8303300151 Amend 70 to License DPR-40, revising Tech Specs to be consistent w/Cycle 6 reload analysis.
CLARK, R. A. Operating Reactors Branch 3. 83/03/15. 20pp.
17750:350. 24X Fiche: 50-285, 83/03/15, 8303300144.

--8303300160 Safety evaluation supporting Amend 70 to License DPR-40.
* Office of Nuclear Reactor Regulation, Director. 83/03/15.
20pp. 17751:008. 24X Fiche: 50-285, 83/03/15, 8303300144.

# DOCKETED ITEMS

--8303300166 Notice of issuance & availability of Amend 70 to License DPR-40.
CLARK, R. A. Operating Reactors Branch 3. 83/03/15. 2pp.
17791:028. 24X Fiche: 50-285, 83/03/15, 8303300144.

8303310673 Concurs that automatic action will be required to detect toxic hydrogen fluoride levels & isolate control room per review of 830103 ltr re update to habitability study. Mods will be completed per schedule in confirming order.
CLARK, R. A. Operating Reactors Branch 3. 83/03/21. JONES, W. C.
Omaha Public Power District. 2pp. 17780:299. 24X
Fiche: 50-285, 83/03/21, 8303310673.

Q. Inspection reports, IE Bulletins & correspondence

8303180221 Forwards IE Insp Rept 50-285/82-21 on 831011-15. No noncompliance noted but one unresolved & 11 open items identified.
SEIDLE, W. C. Region 4, Office of Director. 83/01/19. JONES, W. C.
Omaha Public Power District. 2pp. 17618:001. 24X
Fiche: 50-285, 83/01/19, 8303180221.

--8303180225 IE Insp Rept 50-285/82-21 on 831011-15. No noncompliance noted. Major areas inspected: radiochemistry program, sample treatment & analysis, lab instrument calibr & QC of analytical measurements.
NICHOLAS, J. B., WISE, R., MURRAY, B. Region 4, Office of Director.
83/01/10. 26pp. 17618:003. 24X Fiche: 50-285, 83/01/19, 8303180221.

8303180224 Forwards IE Insp Rept 50-285/82-26 on 821025-29. No noncompliance noted.
SEIDLE, W. C. Region 4, Office of Director. 83/01/26. JONES, W. C.
Omaha Public Power District. 2pp. 17621:289. 24X
Fiche: 50-285, 83/01/26, 8303180224.

--8303180244 IE Insp Rept 50-285/82-26 on 821025-29. No noncompliance noted. Major areas inspected: radiation protection program during operations, transportation activities & select NUREG-0737 items.
BAER, R., HOLLEY, W., MURRAY, B. Region 4, Office of Director.
83/01/18. 40pp. 17621:291. 24X Fiche: 50-285, 83/01/26, 8303180224.

8303180288 Responds to request from 821014 insp by providing results of aliquot sample of monitor tank liquid. Results acceptable.
JONES, W. C. Omaha Public Power District. 83/02/04. SEIDLE, W. C.
Division of Resident, Reactor Project & Engineering Programs. 2pp.
17617:150. 24X Fiche: 50-285, 83/02/04, 8303180288.

8303010223 Forwards IE Insp Rept 50-285/83-01 during Jan 1983 & notice of violation.
SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs. 83/02/11. JONES, W. C. Omaha Public Power District. 2pp.
17333:311. 24X Fiche: 50-285, 83/02/11, 8303010223.

--8303010224 Notice of violation from insp during Jan 1983.
*. Division of Resident, Reactor Project & Engineering Programs.
83/02/11. 1p. 17333:313. 24X Fiche: 50-285, 83/02/11, 8303010223.

--8303010230 IE Insp Rept 50-285/83-01 during Jan 1983. Noncompliance noted: failure to enter temporary jumpers into jumper log per Surveillance Procedure ST-CONT-7.
YANDELL, L. A., JOHNSON, W. D. Division of Resident, Reactor Project & Engineering Programs. 83/02/10. 6pp. 17333:314. 24X
Fiche: 50-285, 83/02/11, 8303010223.

8303210673 Forwards IE Insp Rept 50-285/83-04 on 830124-28. No noncompliance noted.
SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs. 83/02/16. JONES, W. C. Omaha Public Power District. 2pp.
17635:246. 24X Fiche: 50-285, 83/02/16, 8303210673.

--8303210683 IE Insp Rept 50-285/83-04 on 830124-28. No noncompliance noted. Major areas inspected: licensee action on previously identified items, fire prevention implementation, requalification training & training.
JAUDON, J. P., MURPHY, M. E., JOHNSON, W. D. Region 4, Office of Director. 83/02/16. 9pp. 17635:248. 24X Fiche: 50-285, 83/02/16, 8303210673.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc.
11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc.
117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303250002 Forwards IE Insp Rept 50-285/83-02 on 830110-14. Notice of violation withheld (ref 10CFR73.21).
SEIDLE, W. C. Division of Project & Resident Programs. 83/03/22.
JONES, W. C. Omaha Public Power District. 2pp. 17692:116. 24X
Fiche: 50-285, 83/03/22, 8303250002.

--8303250008 IE Insp Rept 50-285/83-02 on 830110-14. Noncompliance noted: violation identified in security program audit. Details withheld (ref 10CFR73.21).
EVANS, C. A., KELLY, J. A. F. Region 4, Office of Director. 83/02/14.
1p. 17692:118. 24X Fiche: 50-285, 83/03/22, 8303250002.

R. Periodic operating reports & related correspondence

8303040466 Forwards "Annual Rept for Tech Spec Section 5.9.1.b & App B, 1982 & Semiannual Rept for Tech Spec Section 5.9.4 Jul-Dec 1982, Inclusive."
JONES, W. C. Omaha Public Power District. 83/03/01. Director's Office, Office of Inspection and Enforcement. 1p. 17422:056. 24X
Fiche: 50-285, 83/03/01, 8303040466.

--8303040471 "Annual Rept for Tech Spec Section 5.9.1.b & App B, 1982 & Semiannual Rept for Tech Spec Section 5.9.4 Jul-Dec 1982, Inclusive."
GATES, W. G. Omaha Public Power District. 83/03/01. 183pp.
17422:057. 24X Fiche: 50-285, 83/03/01, 8303040466.

8303180317 Forwards monthly operating rept for Feb 1983.
JONES, W. C. Omaha Public Power District. 83/03/14. DEYOUNG, R. C.
Director's Office, Office of Inspection and Enforcement. 1p.
17619:346. 24X Fiche: 50-285, 83/03/14, 8303180317.

--8303180325 Monthly operating rept for Feb 1983.
MATTHEWS, T. P. Omaha Public Power District. 83/03/08. 12pp.
17619:347. 24X Fiche: 50-285, 83/03/14, 8303180317.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303080438 Responds to NRC 830111 ltr requesting info re operator licensing exam schedules through 851231. Present schedule listed.
JONES, W. C. Omaha Public Power District. 83/03/04. EISENHUT, D. G.
Office of Nuclear Reactor Regulation, Director. 2pp. 17454:166.
24X Fiche: 50-285, 83/03/04, 8303080438.

DOCKET 50-286 INDIAN POINT STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

8303030298 Forwards IE Insp Rept 50-286/83-01 on 830111-14 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/02/17.
BRONS, J. C. Power Authority of the State of New York. 2pp.
17410:140. 24X Fiche: 50-286, 83/02/17, 8303030298.

--8303030312 IE Insp Rept 50-286/83-01 on 830111-14. Noncompliance noted: failure to post radiation exposure authorization at contractor control point.
CLEMONS, P., ROWE, C., SHANBAKY, M. Region 1, Office of Director.
83/02/16. 6pp. 17410:143. 24X Fiche: 50-286, 83/02/17, 8303030298.

8303030396 Summary of 830114 meeting w/util in Bethesda, MD re outstanding licensing items, including steam generator sleeving/plugging, girth weld repairs, auxiliary feedwater sys seismic design & fire protection interim measures.
POLK, P. J. Operating Reactors Branch 1. 83/02/18. Operating Reactors Branch 1. 8pp. 17419:309. 24X Fiche: 50-286, 83/02/18, 8303030396.

8303230422 Notification of contract execution,Mod 3 to "Indian Point Fire Risk Analysis." Contractor:NBS.
FLEENOR,C. Technical Assistance Contracts Branch NRC-03-82-122 83/02/24. SPEIS,T.P. Division of Safety Technology BUCHBINDER,B NRC - No Detailed Affiliation Given. 1p. 17674:170. 24X
Fiche:50-247,83/02/24,8303230422.

--8303230430 Mod 3,extending period of performance to 830415,to "Indian Point Fire Risk Analysis."
SHREVE,D.B. Commerce, Dept. of, National Bureau of Standards.
GUSTAVE,R.P. Division of Contracts NRC-03-82-122 83/02/24.
1p. 17674:171. 24X Fiche:50-247,83/02/24,8303230422.

8303180032 Requests confirmation of info tabulated from 830126 response re emergency operating facilities (EOF),especially distance from permanent backup EOF.
VARGA,S.A. Operating Reactors Branch 1 83/03/04. SINCLAIR,L.W. Power Authority of the State of New York. 3pp. 17625:266. 24X
Fiche:50-286,83/03/04,8303180032.

8303150378 Forwards FEMA 830307 ltr to NRC,updating status of pre-exercise activities re 830309 emergency planning exercise.
HASSELL,D.F. Hearing Branch 1 83/03/11. GLEASON,J.P. Atomic Safety and Licensing Board Panel. 4pp. 17562:028. 24X
Fiche:50-247,83/03/11,8303150378.

Q. Adjudicatory correspondence

8303010605 Motion for ASLB order directing that Parents Concerned About Indian Point be permitted to present witnesses at hearings in Croton-on-Hudson during wk of 830314.
RODRIGUEZ,P. Parents Concerned About Indian Point 83/02/22. Atomic Safety and Licensing Board Panel. 2pp. 17336:265. 24X
Fiche:50-247,83/02/22,8303010605.

8303010141 Telecopy message of order addressing NY City Council testimony. Testimony must address issue of adequacy of offsite emergency plans.Other testimony stricken or partially admissable as listed.
GLEASON,J.P. Atomic Safety and Licensing Board Panel 83/02/25. New York, NY. 5pp. 17345:022. 24X Fiche:50-247,83/02/25, 8303010141.

8303010151 Order directing NY PIRG 830222 motion for discovery to permit entry on land controlled by licensee to appropriate ASLB.
CHILK,S.J. Office of the Secretary of the Commission 83/02/25. Public Interest Research Group, New York 1p. 17336:003. 24X
Fiche:50-247,83/02/25,8303010151.

8303020026 Memorandum re scheduling of testimony under Commission Questions 3 & 4.Proposal in PASNY 830207 motion to establish schedule & limit scope should be adopted.Certificate of Svc encl.Related correspondence.
MORGAN,C. Power Authority of the State of New York MORGAN,C. Morgan Associates 83/02/25. 25pp. 17352:264. 24X
Fiche:50-247,83/02/25,8303020026.

8303020046 Notice of D Gurin,J Friedman & R McCarthy 830228 deposition in New York,NY re testimony on Commission Questions 3 & 4. Related Correspondence.
BRANDENBURG,B. Consolidated Edison Co. of New York, Inc. MORGAN,C. Power Authority of the State of New York MORGAN,C. Morgan Associates. 83/02/25. 2pp. 17354:273. 24X Fiche:50-247,83/02/25, 8303020046.

--8303020052 Notice of S Meshnick 830226 desposition in New York,NY re testimony on Commission Questions 3 & 4.Certificate of Svc encl.
BRANDENBURG,B. Consolidated Edison Co. of New York, Inc.
MORGAN,C. Power Authority of the State of New York. MORGAN,C. Morgan Associates. 83/02/25. 6pp. 17354:275. 24X
Fiche:50-247,83/02/25,8303020046.

8303020061 Memorandum & order memorializing 830224 conference call re licensee motions to strike NY City Council member prefiled testimony on Commission Questions 3 & 4.Testimony on listed issue accepted.Other testimony rejected.
GLEASON,J.P. Atomic Safety and Licensing Board Panel. 83/02/25. 4pp. 17352:139. 24X Fiche:50-247,83/02/25,8303020061.

8303030433 Motion for extension of deadlines of investigatory hearings to complete record on emergency planning issues in Commission Questions 3 & 4.Addl time necessary to provide complete record.
POTTERFIELD,A. Public Interest Research Group, New York.
POTTERFIELD,A. Union of Concerned Scientists. POTTERFIELD,A. Parents Concerned About Indian Point. 83/02/28. Commissioners. 3pp. 17410:110. 24X Fiche:50-247,83/02/28,8303030433.

8303070110 Motion to strike SR Meshnik prefiled testimony under Commission Questions 3 & 4.Testimony fails to discuss probability of type of accident presumed in testimony. Certificate of Svc encl.
BRANDENBURG,B. Consolidated Edison Co. of New York, Inc. MORGAN,C. Power Authority of the State of New York. MORGAN,C. Morgan Associates. 83/02/28. Atomic Safety and Licensing Board Panel. 9pp. 17432:337. 24X Fiche:50-247,83/02/28,8303070110.

8303070113 Motion to amend svc list to change A Potterfield address.
POTTERFIELD,A. Public Interest Research Group, New York. 83/02/28 Atomic Safety and Licensing Board Panel. 1p. 17430:312. 24X
Fiche:50-247,83/02/28,8303070113.

8303070161 Memorandum re scheduling of testimony on Commission Questions 3 & 4.
POTTERFIELD,A. Public Interest Research Group, New York. 83/02/28. 48pp. 17433:155. 24X Fiche:50-247,83/02/28,8303070161.

8303040470 Forwards revs to Westchester County radiological emergency plan.W/o encl.Certificate of Svc encl.Related correspondence.
FEINBERG,J.D. New York, State of, Energy Office. 83/03/01.
GLEASON,J.P., SHON,F.J., PARIS,O.H. Atomic Safety and Licensing Board Panel. 4pp. 17373:319. 24X Fiche:50-247,83/03/01,8303040470.

8303070125 Notice of S Sholly & other unidentified witnesses deposition re testimony on Commission Question 5.Certificate of Svc encl.
BRANDENBURG,B. Consolidated Edison Co. of New York, Inc.
COLARULLI,P.F. Power Authority of the State of New York.
COLARULLI,P.F. Morgan Associates. 83/03/01. 6pp. 17433:356. 24X
Fiche:50-247,83/03/01,8303070125.

8303070134 Notice of F Rowsome,R Blond & other unidentified witnesses deposition re testimony on Commission Question 5.Certificate of Svc encl.
BRANDENBURG,B. Consolidated Edison Co. of New York, Inc.
COLARULLI,P.F. Power Authority of the State of New York.
COLARULLI,P.F. Morgan Associates. 83/03/01. 6pp. 17432:350. 24X
Fiche:50-247,83/03/01,8303070134.

8303090287 Presents Resolution 159,memorializing County request that NY Governor Cuomo direct NY State Ofc of Disaster Preparedness not to impose state radiological evacuation plan on Rockland County.
SEIGERMAN,V.K. Rockland County, NY. 83/03/01. NRC - No Detailed Affiliation Given. 2pp. 17492:154. 24X Fiche:50-247,83/03/01, 8303090287.

8303090293 Presents Resolution 156 directing Rockland County not to participate in four-county radiological response drill.
SEIGERMAN,V.K. Rockland County, NY. 83/03/01. NRC - No Detailed Affiliation Given. 2pp. 17492:148. 24X Fiche:50-247,83/03/01, 8303090293.

8303110192 Clarifies & documents independence from issues re probabilistic safety study,before being engaged as ASLB technical consultant.
AMICO,P.J. Applied Risk Technology Corp. 83/03/01. GLEASON,J.P., SHON,F.J., PARIS,O.H. Atomic Safety and Licensing Board Panel. 1p. 17520:138. 24X Fiche:50-247,83/03/01,8303110192.

8303040623 Schedule for rebuttal testimony on source terms,submitted per ASLB 830216 order. Testimony of R Bernero will be filed on 830322.R Bernero will be available for cross-examination on 830405.Certificate of Svc encl.
MOORE,J.E. Hearing Branch 1 83/03/03. 5pp. 17374:231. 24X
Fiche:50-247,83/03/03,8303040623.

8303090314 Notice of appearance in proceeding.Certificate of Svc encl.
TOLSON,J.Q. Power Authority of the State of New York. 83/03/03. 4pp. 17471:125. 24X Fiche:50-247,83/03/03,8303090314.

8303090321 Supplemental response to 820621 interrogatories on Contention 6.2,transmitting form for recording continuous type releases.Certificate of Svc encl.
PRATT,C. Power Authority of the State of New York. PRATT,C. Morgan Associates. 83/03/03. Parents Concerned About Indian Point. 8pp. 17473:204. 24X Fiche:50-247,83/03/03,8303090321.

8303070142 Recommended decision re fair & efficient method for receiving evidence on Commission Questions 3 & 4 to accomplish expedited hearing schedule.
LAURENSON,J.A. Atomic Safety and Licensing Board Panel 83/03/04. 19pp. 17430:313. 24X Fiche:50-247,83/03/04,8303070142.

8303080109 Motion to compel further responses from Greater NY Council on Energy to first set of interrogatories & to document requests under Commission Question 6.Certificate of Svc encl.Related correspondence.
BRANDENBURG,B. Consolidated Edison Co. of New York, Inc. PRATT,C.M. Power Authority of the State of New York PRATT,C.M. Morgan Associates. 83/03/04. Atomic Safety and Licensing Board Panel. 31pp. 17458:141. 24X Fiche:50-247,83/03/04,8303080109

8303090319 Discusses PIRG of NY 830222 motion for State of NY to preserve & produce documents re 830309 exercise.Revs of offsite emergency plans sent to all parties.W/o offsite scenario for 830224 training session.W/Certificate of Svc
FEINBERG,J.D. New York, State of, Energy Office. 83/03/04.
POTTERFIELD,A. Public Interest Research Group, New York. 5pp. 17473:212. 24X Fiche:50-247,83/03/04,8303090319.

8303090329 Forwards radiological offsite emergency revs, inadvertently omitted from revs supplied to FEMA on 820722. Matls should be incorporated into NY State proposed Exhibit 6.
FEINBERG,J.D. New York, State of, Energy Office. 83/03/04.
GLEASON,J.P.; SHON,F.J.; PARIS,O.H. Atomic Safety and Licensing Board Panel. 25pp. 17473:179. 24X Fiche:50-247,83/03/04, 8303090329.

8303090307 Telecopy memorandum & order delineating schedule for hearing on Commission Questions 3 & 4.
GLEASON,J.P. Atomic Safety and Licensing Board Panel. 83/03/07. 1p. 17471:238. 24X Fiche:50-247,83/03/07,8303090307.

8303090376 Order amending svc list,changing A Potterfield address & deleting alternate ASLB member JA Laurenson.
GLEASON,J.P. Atomic Safety and Licensing Board Panel. 83/03/07. 1p. 17472:131. 24X Fiche:50-247,83/03/07,8303090376.

8303100232 Delineates job responsibilities as independent consultant to ASLB on PRA.
GLEASON,J.P. Atomic Safety and Licensing Board Panel. 83/03/07.
AMICO,P.J. Applied Risk Technology Corp. 1p. 17485:292. 24X Fiche:50-247,83/03/07,8303100232.

8303100242 Opposes schedule for hearing evacuation planning testimony of six intervenors in 5 days.
RODRIGUEZ,P. Parents Concerned About Indian Point. 83/03/07
Commissioners. 1p. 17485:296. 24X Fiche:50-247,83/03/07, 8303100242.

8303100238 Notice of appearance in proceeding.
SANOFF,B.L. Consolidated Edison Co. of New York, Inc. + Kronish, Lieb, Shainswit, Weiner & Hillman. 83/03/08. 1p. 17485:293. 24X Fiche:50-247,83/03/08,8303100238.

8303100261 Expresses strong & vehement objections to scheduling order allowing Rockland County only 1/2 day to present testimony. Three full days needed.
THORSEN,E.O.; PARRIS,M.L. Rockland County, NY. 83/03/08.
PALLADINO,N.J. Commissioners. 1p. 17490:304. 24X Fiche:50-247,83/03/08,8303100261.

8303100271 Motion for mod of ASLB 830307 order adopting alternate ASLB member Laurenson recommended decision on scheduling.Ruling should be clarified re time to hear post-exercise FEMA testimony.Certificate of Svc encl.
BRANDENBURG,B. Consolidated Edison Co. of New York, Inc. 83/03/08.
Atomic Safety and Licensing Board Panel. 10pp. 17490:288. 24X Fiche:50-247,83/03/08,8303100271.

8303110198 Memorandum & order clarifying 830207 order.Deletion of mention of public util employees in reformulated Contention 3.2 does not exclude consideration of response of employees during emergency.
GLEASON,J.P. Atomic Safety and Licensing Board Panel. 83/03/08. 2pp. 17517:361. 24X Fiche:50-247,83/03/08,8302110198.

8303140335 Motion to strike UCS,PIRG of NY & Parents Concerned About Indian Point witness KT Erikson 830221 supplemental testimony.Testimony is beyond scope of Commission questions & is based on inadmissible hearsay.Certificate of Svc encl.
MORGAN,C. Power Authority of the State of New York. MORGAN,C.
Morgan Associates. 83/03/09. Atomic Safety and Licensing Board Panel. 10pp. 17534:207. 24X Fiche:50-247,83/03/08,8303140335.

8303140343 Motion to modify & clarify ASLB order on schedule for hearing Commission Questions 3 & 4.Arbitrary limits on cross-examination prejudicing parties should be rejected.Use of panels should be clarified.Certificate of Svc encl.
MORGAN,C. Power Authority of the State of New York. MORGAN,C.
Morgan Associates. 83/03/08. Atomic Safety and Licensing Board Panel. 10pp. 17534:233. 24X Fiche:50-247,83/03/08,8303140343.

8303100277 Response opposing intervenor 830228 motion for extension of deadlines to complete record on emergency planning issues in Commission Questions 3 & 4 ASLB resolved scheduling question.Certificate of Svc encl.
BRANDENBURG,B. Consolidated Edison Co. of New York, Inc.
COLARULLI,P.F. Power Authority of the State of New York.
COLARULLI,P.F. Morgan Associates. 83/03/09. Commissioners. 32pp. 17490:252. 24X Fiche:50-247,83/03/09,8303100277.

8303150393 Motion to strike KT Erikson 830221 supplemental testimony. Testimony irrelevant to any issue before ASLB & is unreliable hearsay which would preclude cross-examination by licensees.Certificate of Svc encl.
BRANDENBURG,B. Consolidated Edison Co. of New York, Inc. 83/03/09.
Atomic Safety and Licensing Board Panel. 8pp. 17561:355. 24X Fiche:50-247,83/03/09,8303150393.

8303150378 Forwards FEMA 830307 ltr to NRC updating status of pre-exercise activities re 830309 emergency planning exercise.
HASSELL,D.F. Hearing Branch 1. 83/03/11. GLEASON,J.P.; SHON,F.J.; PARIS,O.H. Atomic Safety and Licensing Board Panel. 4pp. 17562:028. 24X Fiche:50-247,83/03/11,8303150378.

8303150408 Motion to amend svc list to include AP O'Rourke,new Westchester County executive.Certificate of Svc encl.
VETERE,L.A. Westchester County, NY. 83/03/11. Atomic Safety and Licensing Board Panel. 2pp. 17561:263. 24X Fiche:50-247,83/03/11, 8303150408.

8303150415 Intervenors joint list of witnesses to be presented on 830315-18 & 22 re Commission Questions 3 & 4.
+ Union of Concerned Scientists. + Public Interest Research Group, New York. + Parents Concerned About Indian Point. 83/03/11. 3pp. 17561:245. 24X Fiche:50-247,83/03/11,8303150415.

8303170279 Motion to strike certain intervenor prefiled testimony under Commission Questions 3 & 4 re emergency planning filed on 830311.Licensees denied any meaningful right to discovery from witnesses.Certificate of Svc encl.
BRANDENBURG,B. Consolidated Edison Co. of New York, Inc. 83/03/14.
Atomic Safety and Licensing Board Panel. 33pp. 17606:019. 24X Fiche:50-247,83/03/14,8303170279.

8303180144 Forwards intervenor refined witness list for Commission Questions 3 & 4 for presentation on 830315-18 & 22.List does not include witnesses subj to stipulation by licensees & NRC.
POTTERFIELD,A. Public Interest Research Group, New York.
POTTERFIELD,A. Parents Concerned About Indian Point. POTTERFIELD,A. Westchester Peoples Action Coalition,Inc. 83/03/14. 4pp. 17617:275. 24X Fiche:50-247,83/03/14,8303180144.

8303180217 Answer opposing PASNY motion to strike KT Erikson testimony. Testimony relevant to Contentions 3.2 & 3.7 & is based on Erikson personal knowledge.
POTTERFIELD,A. Public Interest Research Group, New York.
POTTERFIELD,A. Union of Concerned Scientists. POTTERFIELD,A. Parents Concerned About Indian Point. 83/03/14. Atomic Safety and Licensing Board Panel. 15pp. 17618:078. 24X Fiche:50-247,83/03/14, 8303180217.

--8303180227 Response opposing licensee motion to compel Greater NY Council on Energy further response to interrogatories.Motion inappropriate & unnecessary.Interrogatories were unclear & burdensome.Certificate of Svc encl.
CORREN,D.R. Greater New York Council on Energy. 83/03/14.
Atomic Safety and Licensing Board Panel. 6pp. 17618:093. 24X Fiche:50-247,83/03/14,8303180217.

8303180235 Motion to strike selected intervenor testimony.Objects to intervenor 830311 witness list for Commission Questions 3 & 4,presenting 99 witnesses in 5 days.Testimony is cumulative, conclusory,hearsay or w/o foundation.W/Certificate of Svc.
MORGAN,C. Power Authority of the State of New York. MORGAN,C.
Morgan Associates. 83/03/14. Atomic Safety and Licensing Board Panel. 16pp. 17621:121. 24X Fiche:50-247,83/03/14,8303180235.

8303180245 Motion for waiver of requirement to distribute Indian Point 3 emergency plan & emergency planning implementation procedures document to all parties.Plans are voluminous & expensive to produce.
MORGAN,C. Power Authority of the State of New York. MORGAN,C.
Morgan Associates. 83/03/14. Atomic Safety and Licensing Board Panel. 4pp. 17621:099. 24X Fiche:50-247,83/03/14,8303180245.

8303180277 Motion to compel West Branch Conservation Assoc & Parents Concerned About Indian Point further responses to licensee first set of interrogatories under Commission Question 6.W/ Certificate of Svc.Related correspondence.
BRANDENBURG,B. Consolidated Edison Co. of New York, Inc. PRATT,C.M. Power Authority of the State of New York. PRATT,C.M. Morgan Associates. 83/03/14. Atomic Safety and Licensing Board Panel. 36pp. 17616:125. 24X Fiche:50-247,83/03/14,8303180277.

8303180393 Requests ASLB direct PJ Amico, independent consultant to ASLB, to file complete resume. Amico 830301 ltr raises questions of independence which must be resolved.
WEISS, E. R. Union of Concerned Scientists. 83/03/14. GLEASON, J. P., SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel. 3pp. 17621:348. 24X Fiche: 50-247, 83/03/14, 8303180393.

8303180029 Response opposing intervenor 830228 motion for extension of deadlines to complete record on emergency planning issues in Commission Questions 3 & 4. Intervenors fail to establish why current schedule should be changed. W/Certificate of Svc.
MOORE, J. E. Hearing Branch 1. 83/03/16. Commissioners. 9pp. 17618:069. 24X Fiche: 50-247, 83/03/16, 8303180029.

8303220261 InForms of licensee understanding of status of addl mitigation testimony. Licensees will file one piece of testimony addressing all NRC post-Question 2 mitigation measures when NRC completes filings.
BRANDENBURG, B. Consolidated Edison Co. of New York, Inc.
COLARULLI, P. F. Power Authority of the State of New York.
COLARULLI, P. F. Morgan Associates. 83/03/16. GLEASON, J. P., SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel. 6pp. 17656:180. 24X Fiche: 50-247, 83/03/16, 8303220261.

8303220231 Motion for waiver of exhibit distribution of draft "Methodology to Calculate Evacuation Travel Time Estimates for Indian Point Emergency Planning Zone." Nov 1981 Rept voluminous. Copying would be costly. Certificate of Svc encl.
BRANDENBURG, B. Consolidated Edison Co. of New York, Inc. MORGAN, C. Power Authority of the State of New York. MORGAN, C. Morgan Associates. 83/03/17. Atomic Safety and Licensing Board Panel. 8pp. 17657:300. 24X Fiche: 50-247, 83/03/17, 8303220231.

8303230176 Motion to impose sanctions against D Corren & R Rosen of Greater NY Council on Energy & Energy Sys Research Group, Inc for failure to respond to interrogatories. Certificate of Svc encl.
BRANDENBURG, B. Commonwealth Edison Co. PRATT, C. M. Power Authority of the State of New York. PRATT, C. M. Morgan Associates. 83/03/17. Atomic Safety and Licensing Board Panel. 19pp. 17665:240. 24X Fiche: 50-247, 83/03/17, 8303230176.

--8303230179 Affidavit of CM Pratt supporting licensee motion to impose sanctions on D Corren & R Rosen of Greater NY Council on Energy & Energy Sys Research Group, Inc for failure to respond to interrogatories. Document request encl.
PRATT, C. M. Power Authority of the State of New York. 83/03/17. 3pp. 17665:270. 24X Fiche: 50-247, 83/03/17, 8303230176.

8303220272 Forwards "Economics of Closing Indian Point Nuclear Power Plants," sent to util on 830317. W/o encl. Related correspondence.
PRATT, C. M. Power Authority of the State of New York. 83/03/18.
GLEASON, J. P., SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel. 1p. 17656:188. 24X Fiche: 50-247, 83/03/18, 8303220272.

8303230207 Motion for time to present evidence re 830309 radiological emergency response planning exercise. Presentation needed to complete record. Certificate of Svc encl.
POTTERFIELD, A. Public Interest Research Group, New York. POSNER, P. Parents Concerned About Indian Point. 83/03/18. Atomic Safety and Licensing Board Panel. 18pp. 17665:194. 24X Fiche: 50-247, 83/03/18, 8303230207.

8303230238 Proposed order of testimony. Affidavit of Svc encl. Related correspondence.
PASELTINER, E. Affiliation Unknown. 83/03/18. 3pp. 17662:003. 24X Fiche: 50-247, 83/03/18, 8303230238.

8303240601 Cross-examination plan for wk commencing 830322. County will cross-examine D Davidoff representing NY State & Parsons, Brinckerhoff, Quade & Douglas representing licensees. Affidavit of Svc encl.
* Rockland County, NY. 83/03/21. 4pp. 17683:060. 24X Fiche: 50-247, 83/03/21, 8303240601.

8303310303 Motion to strike portions of testimony of some Rockland County witnesses on Questions 3 & 4. Testimony conclusory & w/o supporting factual basis. Foundation does not exist for factual matl introduction. Certificate of Svc encl.
BRANDENBURG, B. Consolidated Edison Co. of New York, Inc. 83/03/21. Atomic Safety and Licensing Board Panel. 8pp. 17755:015. 24X Fiche: 50-247, 83/03/21, 8303310303.

8303240399 Order amending svc list by adding AP O'Rourke, Westchester County Executive.
GLEASON, J. P. Atomic Safety and Licensing Board Panel. 83/03/22. 1p. 17679:062. 24X Fiche: 50-247, 83/03/22, 8303240399.

8303300303 Notice of 830330 deposition of R Rosen & other witnesses testifying on behalf of Greater NY Counsil on Energy on Commission Question 6, in New York, NY. Related correspondence.
SANOFF, B. Consolidated Edison Co. of New York, Inc. PRATT, C. M. Power Authority of the State of New York. 83/03/22. 2pp. 17735:133. 24X Fiche: 50-247, 83/03/22, 8303300303.

--8303300307 Notice of B Commoner & R Schrader 830324 deposition in New York, NY re testimony under Commission Question 6. Related correspondence.
SANOFF, B. Consolidated Edison Co. of New York, Inc. PRATT, C. M. Power Authority of the State of New York. 83/03/22. 2pp. 17735:135. 24X Fiche: 50-247, 83/03/22, 8303300303.

--8303300313 Notice of DA Schlissel 830413 deposition in New York, NY re testimony under Commission Question 6. Related correspondence.
SANOFF, B. Consolidated Edison Co. of New York, Inc. PRATT, C. M. Power Authority of the State of New York. 83/03/22. 2pp. 17735:137. 24X Fiche: 50-247, 83/03/22, 8303300303.

--8303300319 Notice of deposition of V Taylor & all other witnesses testifying on behalf of UCS/PIRG of NY & Greater NY Counsil on Energy on Commission Question 6, in New York, NY. Related correspondence.
SANOFF, B. Consolidated Edison Co. of New York, Inc. PRATT, C. M. Power Authority of the State of New York. 83/03/22. 2pp. 17735:139. 24X Fiche: 50-247, 83/03/22, 8303300303.

--8303300322 Notice of deposition of witnesses testifying on behalf of NRC on Commission Question 6. Certificate of Svc encl. Related correspondence.
SANOFF, B. Consolidated Edison Co. of New York, Inc. PRATT, C. M. Power Authority of the State of New York. 83/03/22. 5pp. 17735:141. 24X Fiche: 50-247, 83/03/22, 8303300303.

8303300326 Notice of deposition of all persons testifying for Parents Concerned About Indian Point on Commission Question 6. Certificate of Svc encl. Related correspondence.
SANOFF, B. Consolidated Edison Co. of New York, Inc. PRATT, C. M. Power Authority of the State of New York. 83/03/22. 5pp. 17735:128. 24X Fiche: 50-247, 83/03/22, 8303300326.

8303300374 Suppl to motion to impose sanctions against D Corren, Greater NY Council on Energy & Energy Sys Research Group, Inc for failure to produce Oct 1982 study, "Economics of Closing Indian Point Nuclear Power Plants." Related correspondence.
SANOFF, B. Consolidated Edison Co. of New York, Inc. PRATT, C. M. Power Authority of the State of New York. 83/03/23. Atomic Safety and Licensing Board Panel. 17pp. 17731:033. 24X Fiche: 50-247, 83/03/23, 8303300374.

8303300489 Forwards Energy Sys Research Group, Inc Oct 1982 study & study received in Mar 1983, supporting licensee motion to impose sanctions. Nonproduction of study prejudicial to licensees. Discovery should be allowed on nonproduction.
PRATT, C. M. Power Authority of the State of New York. 83/03/24.
GLEASON, J. P., SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel. 2pp. 17731:148. 24X Fiche: 50-247, 83/03/24, 8303300489.

8303300417 Requests permission to file supplemental responsive testimony through 830416 re matters raised in prospective NY City Council witness DA Schlissel 830413 deposition. Related correspondence.
PRATT, C. M. Power Authority of the State of New York. 83/03/25.
GLEASON, J. P., SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel. 2pp. 17731:079. 24X Fiche: 50-247, 83/03/25, 8303300417.

8303300494 Forwards UCS/PIRG of NY Exhibit 16 addressing info needs of non-English speakers in 10-mile emergency planning zone, per A Potterfield request at 830323 hearing.
FEINBERG, J. D. New York, State of, Energy Office. 83/03/25.
GLEASON, J. P., SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel. 5pp. 17731:139. 24X Fiche: 50-247, 83/03/25, 8303300494.

8303310300 Telecopy order ruling on util motions to compel responses from intervenors & motion for sanctions against Greater NY Council on Energy. Util request to depose D Corren & A Rosen granted to determine if Council aware of cost study rept.
GLEASON, J. P. Atomic Safety and Licensing Board Panel. 83/03/29. Consolidated Edison Co. of New York, Inc. 2pp. 17756:031. 24X Fiche: 50-247, 83/03/29, 8303310300.

H. General correspondence

8303030345 Responds to concerns re transportation of radwaste in & through Putnam County, NY. W/o encl FR notices for 10CFR71.73, 73.21, NUREG-0794 & NUREG-0923.
HAYNES, R. C. Region 1, Office of Director. 83/02/25. BRAATZ, R. L., Putnam County, NY. 2pp. 17410:032. 24X Fiche: 50-247, 83/02/25, 8303030345.

--8303030350 Requests info re transportation of nuclear waste in & through Putnam County, NY.
BRAATZ, R. L. Putnam County, NY 83/02/10 Region 1, Office of Director 1p 17410:034 24X Fiche: 50-247, 83/02/25, 8303030345.

8303080443 Informs that portion of headquarters staff has relocated. New address listed.
BAYNE, J. P. Power Authority of the State of New York 83/03/04
VASSALLO, D. B. Operating Reactors Branch 2 VARGA, S. A. Operating Reactors Branch 1 2pp. 17452:351 24X Fiche: 50-000, 83/03/04, 8303080443.

J. Insurance & indemnity information

8303080297 Forwards Endorsements 62 & 63 to NELIA Policy NF-208 & Endorsements 53 & 54 to MAELU Policy MF-77.
GOLDEN, M. P. Marsh & McLennan, Inc. 83/03/02 SALTZMAN, J. Assistant Director for State & Licensee Relations 5pp. 17447:345 24X Fiche: 50-000, 83/03/02, 8303080297.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp. 17492:033 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303030396 Summary of 830114 meeting w/util in Bethesda, MD re outstanding licensing items, including steam generator sleeving/plugging, girth weld repairs, auxiliary feedwater sys seismic design & fire protection interim measures.
POLK, P. J. Operating Reactors Branch 1 83/02/18 Operating Reactors Branch 1 8pp. 17419:309 24X Fiche: 50-286, 83/02/18, 8303030396.

8303030703 Notification of 830307 meeting w/utils & NUS Corp in Bethesda, MD to discuss proposed rev to 10CFR40 36 (Tech Specs).
BRINKMAN, D. S. Standardization & Special Projects Branch 83/02/22
THOMAS, C. O. Standardization & Special Projects Branch 2pp. 17363:227 24X Fiche: 50-000, 83/02/22, 8303030703.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303110245 Confirms that NRC & ASLB will be informed of any interactions identified by sys interaction study which may impact results of probabilistic safety study.
BAYNE, J. P. Power Authority of the State of New York 83/03/04
VARGA, S. A. Operating Reactors Branch 1 1p. 17520:062 24X
Fiche: 50-286, 83/03/04, 8303110245.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp. 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303170207 Confirms conclusions reached during 821223 telcon re assumptions to be used in performing analysis concerning main steam line break w/continued feedwater addition. Analysis expected by 830331.
BAYNE, J. P. Power Authority of the State of New York 83/03/07
VARGA, S. A. Operating Reactors Branch 1 1p. 17606:077 24X
Fiche: 50-286, 83/03/07, 8303170207.

8303210538 Forwards United Engineers & Constructors containment seismic design calculations & revised probabilistic safety study calculations by Structural Mechanics Assoc to determine capacity of containments.
PERLA, H. F. Pickard, Lowe & Garrick, Inc. 83/03/14 HANNON, J. NRC - No Detailed Affiliation Given 140pp. 17630:266 24X
Fiche: 50-247, 83/03/14, 8303210538.

8303180479 Forwards response to Generic Ltr 82-28 re instrumentation for inadequate core cooling, NUREG-0737, Item II.F.2.
BAYNE, J. P. Power Authority of the State of New York 83/03/15
EISENHUT, D. G. Division of Licensing 37pp. 17621:190 24X
Fiche: 50-286, 83/03/15, 8303180479.

8303290027 Forwards order confirming commitments on post-TMI related issues per NUREG-0737. Proposed schedule exceptions & delays acceptable. Order based on commitments per responses to Generic Ltrs 82-05 & 82-10.
VARGA, S. A. Operating Reactors Branch 1 83/03/18 SINCLAIR, L. W. Power Authority of the State of New York 3pp. 17729:305 24X
Fiche: 50-286, 83/03/18, 8303290027.

--8303290036 Order confirming licensee commitments on post-TMI related issues per NUREG-0737.
PURPLE, R. A. Division of Licensing 83/03/18 Power Authority of the State of New York 9pp. 17729:308 24X
Fiche: 50-286, 83/03/18, 8303290027.

Q. Inspection reports, IE Bulletins & correspondence

8303030298 Forwards IE Insp Rept 50-286/83-01 on 830111-14 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs 83/02/17
BRONS, J. C. Power Authority of the State of New York 2pp. 17410:140 24X Fiche: 50-286, 83/02/17, 8303030298.

--8303030305 Notice of violation from insp on 830111-14.
* Division of Engineering & Technical Programs 83/02/17 1p. 17410:142 24X Fiche: 50-286, 83/02/17, 8303030298.

--8303030312 IE Insp Rept 50-286/83-01 on 830111-14 Noncompliance noted: failure to post radiation exposure authorization at contractor control point.
CLEMONS, P., ROWE, C., SHANBAKY, M. Region 1, Office of Director 83/02/16 6pp. 17410:143 24X Fiche: 50-286, 83/02/17, 8303030298.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11pp. 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303160392 Forwards IE Insp Rept 50-286/83-02 on 830116-0215. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs 83/03/01
BRONS, J. C. Power Authority of the State of New York 2pp. 17593:001 24X Fiche: 50-286, 83/03/01, 8303160392.

--8303160404 IE Insp Rept 50-286/83-02 on 830116-0215. No noncompliance noted. Major areas inspected: plant operation, including shift logs & records; plant tour; surveillance; maint; QA/QC administration program & followup on IE bulletins.
KENNY, T. J. Region 1, Office of Director KISTER, H. Division of Project & Resident Programs 83/02/28 9pp. 17593:003 24X
Fiche: 50-286, 83/03/01, 8303160392.

8303160247 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Westinghouse breakers used at facilities. All licensed operators notified of event.
BRONS, J. C. Power Authority of the State of New York 83/03/07
HAYNES, R. C. Region 1, Office of Director 3pp. 17596:327 24X
Fiche: 50-286, 83/03/07, 8303160247.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8303300332 Forwards IE Insp Rept 50-286/83-03 on 830222-24. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs 83/03/17
BRONS, J. C. Power Authority of the State of New York 2pp. 17734:198 24X Fiche: 50-286, 83/03/17, 8303300332.

--8303300340 IE Insp Rept 50-286/83-03 on 830222-24. No noncompliance noted. Major areas inspected: review status of repair operations for cracked upper shell to transition cone closure weld on four steam generators.
REYNOLDS, S. D., BURR, J. Region 1, Office of Director 83/03/14 6pp. 17734:201 24X Fiche: 50-286, 83/03/17, 8303300332.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12?pp. 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

R. Periodic operating reports & related correspondence

8303150532 Forwards monthly operating rept for Jan 1983.
BRONS, J. C. Power Authority of the State of New York. 83/02/09.
Office of Resource Management, Director. 1p. 17568:198. 24X
Fiche: 50-286, 83/02/09, 8303150532.

--8303150536 Monthly operating rept for Jan 1983.
KELLY, L. Power Authority of the State of New York. 83/02/01.
6pp. 17568:199. 24X Fiche: 50-286, 83/02/09, 8303150532.

8303160374 Forwards "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1982," re gaseous & liquid effluents, solid waste, radiological impact on man & meterological data.
BRONS, J. C. Power Authority of the State of New York. 83/03/02.
HAYNES, R. C. Region 1, Office of Director. 1p. 17595:333. 24X
Fiche: 50-286, 83/03/02, 8303160374.

--8303160377 "Effluent & Waste Disposal Semiannual Rept, Jul-Dec," re gaseous & liquid effluents, solid waste, radiological impact on man & meterological data.
* Power Authority of the State of New York. 83/03/02. 47pp.
17595:334. 24X Fiche: 50-286, 83/03/02, 8303160374.

8303150437 Submits annual rept re safety & relief valve failures & challenges per NUREG-0737, Item II.K.3.3. No valve failures or challenges experienced during CY82.
BAYNE, J. P. Power Authority of the State of New York. 83/03/07.
VARGA, S. A. Operating Reactors Branch 1. 1p. 17562:284. 24X
Fiche: 50-286, 83/03/07, 8303150437.

8303250055 Forwards summary rept of personnel radiation exposure for 1982.
BRONS, J. C. Power Authority of the State of New York. 83/03/15.
HAYNES, R. C. Region 1, Office of Director. 1p. 17692:272. 24X
Fiche: 50-286, 83/03/15, 8303250055.

--8303250057 Summary rept of personnel radiation exposure for 1982.
* Power Authority of the State of New York. 83/03/15. 1p.
17692:273. 24X Fiche: 50-286, 83/03/15, 8303250055.

S. Reportable occurrences, LERs & related correspondence

8303240010 PND-1E-83-004 informs of Rockland County Legislature resolutions prohibiting County officials from participating in 830309 exercise & requesting NY Governor to order plant shutdown.
CROCKER, H. W. Region 1, Office of Director. 83/03/07. 1p.
17681:101. 24X Fiche: 50-286, 83/03/07, 8303240010.

8303280170 Part 21 rept re transfer switches 3868180. Five transfer switches inspected & adjusted as necessary. New requirements added to test & adjustment procedure to review subassemblies for proper function. No other plants affected.
NAUMANN, H. R. Automatic Switch Co. 83/03/10. Region 4, Office of Director. 1p. 17706:318. 24X Fiche: 50-003, 83/03/10, 8303280170.

T. Hearing transcripts on non-antitrust matters

8303020093 Forwards supplemental testimony of SZ Gdanski, B Flicker, D Hastings, JF Kralik, DP McGuire, R Northrup, H Reisman, L Scharf & R Wein. Related correspondence.
THORSEN, E. O. Rockland County, NY. 83/02/22. GLEASON, J. P., SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel. 1p.
17349:114. 24X Fiche: 50-247, 83/02/22, 8303020093.

--8303020096 Supplemental testimony of DP McGuire re emergency planning. Recent developments in preparing emergency plan discussed. Related correspondence.
MCGUIRE, D. P. Rockland County, NY. 83/02/22. 4pp. 17349:115.
24X Fiche: 50-247, 83/02/22, 8303020093.

--8303020100 Supplemental testimony of H Reisman re current state of Rockland County radiological planning. If serious incident occurred, County would not be able to react to safeguard citizens or property. Related correspondence.
REISMAN, H. Rockland County, NY. 83/02/22. 3pp. 17349:119. 24X
Fiche: 50-247, 83/02/22, 8303020093.

--8303020105 Supplemental testimony of SZ Gdanski re Rockland County radiological planning. Expresses doubt that plan will protect health, safety & welfare of public. Related correspondence.
GDANSKI, S. Z. Rockland County, NY. 83/02/22. 3pp. 17349:122.
24X Fiche: 50-247, 83/02/22, 8303020093.

--8303020110 Supplemental testimony of D Hastings re Rockland County emergency preparedness plan. Plan developing quickly. Related correspondence.
HASTINGS, D. Rockland County, NY. 83/02/22. 2pp. 17349:125. 24X
Fiche: 50-247, 83/02/22, 8303020093.

--8303020116 Supplemental testimony of R Northrup re Rockland County emergency plan. Evacuation of individuals who receive personal care svcs discussed. Related correspondence.
NORTHRUP, R. Rockland County, NY. 83/02/22. 4pp. 17349:127. 24X
Fiche: 50-247, 83/02/22, 8303020093.

--8303020120 Supplemental testimony of L Spiegel re use of buses during evacuation. No evacuation training conducted. Related correspondence.
SPIEGEL, L. Rockland County, NY. 83/02/22. 2pp. 17349:131. 24X
Fiche: 50-247, 83/02/22, 8303020093.

--8303020124 Supplemental testimony of JK Kralik re Rockland County emergency plan. No addl equipment or training received to implement plan. Related correspondence.
KRALIK, J. F. Rockland County, NY. 83/02/22. 2pp. 17349:133. 24X
Fiche: 50-247, 83/02/22, 8303020093.

--8303020126 Supplemental testimony of R Wein re evacuation of blind people. Number of blind people in crucial areas increased. Related correspondence.
WEIN, R. Rockland County, NY. 83/02/22. 2pp. 17349:135. 24X
Fiche: 50-247, 83/02/22, 8303020093.

--8303020130 Supplemental testimony of L Scharf re Rockland County emergency planning. County lacks info to prepare schools for emergency. Related correspondence.
SCHARF, L. Rockland County, NY. 83/02/22. 3pp. 17349:137. 24X
Fiche: 50-247, 83/02/22, 8303020093.

--8303020133 Supplemental testimony of B Flicker re Rockland County emergency plan. Info being gathered re evacuation of school children. Affidavit of Svc encl. Related correspondence.
FLICKER, B. Rockland County, NY. 83/02/22. 4pp. 17349:140. 24X
Fiche: 50-247, 83/02/22, 8303020093.

8303030017 Transcript of 830228 special conference in New York, NY. Pp 1-134.
* Atomic Safety and Licensing Board Panel. 83/02/28. 136pp.
17412:198. 24X Fiche: 50-247, 83/02/28, 8303030017.

8303030211 Transcript of 830301 hearing in New York, NY. Pp 8,959-9,161. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 83/03/01. 247pp.
17411:029. 24X Fiche: 50-247, 83/03/01, 8303030211.

8303040576 Transcript of 830302 hearing in New York, NY. Pp 9,162-9,374. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 83/03/02. 251pp.
17369:322. 24X Fiche: 50-247, 83/03/02, 8303040576.

8303070130 Transcript of 830303 hearing in New York, NY. Pp 9,375-9,548. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 83/03/03. 224pp.
17431:147. 24X Fiche: 50-247, 83/03/03, 8303070130.

8303100172 Forwards SA Schwartz testimony, adopting BR Grimes testimony due to change in personnel positions. Testimony not substantively changed.
HASSELL, D. F. Hearing Branch 1. 83/03/08. GLEASON, J. P., SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel. 1p. 17485:197.
24X Fiche: 50-247, 83/03/08, 8303100172.

--8303100178 Testimony of SA Schwartz re emergency planning contentions on Commission Questions 3 & 4. Emergency plans consider both fair & adverse weather conditions & range of accident conditions including Class 9 accidents.
SCHWARTZ, S. A. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/08. 9pp. 17485:198. 24X
Fiche: 50-247, 83/03/08, 8303100172.

8303170218 Transcript of 830315 hearing in White Plains, NY. Pp 9,549-9,805. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 83/03/15. 304pp.
17606:179. 24X Fiche: 50-247, 83/03/15, 8303170218.

8303210567 Transcript of 830316 hearing in White Plains, NY. Pp 10,038-10,153. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 83/03/16. 130pp.
17631:046. 24X Fiche: 50-247, 83/03/16, 8303210567.

8303210343 Transcript of 830317 hearing in White Plains, NY. Pp 10,154-10,452. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 83/03/17. 380pp.
17633:018. 24X Fiche: 50-247, 83/03/17, 8303210343.

8303220284 Transcript of 830318 hearing in White Plains, NY. Pp 10,453-10,736. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 83/03/18. 378pp.
17654:321. 24X Fiche: 50-247, 83/03/18, 8303220284.

8303230230 Forwards testimony of F Rowsome & R Blond re Commission Question 5 on comparative risk & of RM Bernero re severe accident source terms.
MOORE, J. E. Hearing Branch 1. 83/03/22 GLEASON, J. P. ; SHON, F. J. ; PARIS, D. H. Atomic Safety and Licensing Board Panel 1p. 17661:239 24X Fiche: 50-247, 83/03/22, 8303230230.

--8303230233 Testimony of F Rowsome & R Blond re Commission Question 5 on comparative risk.
ROWSOME, F. Assistant Director for Technology Review BLOND, R. Reactor Risk Branch 83/03/22. 112pp. 17661:240. 24X Fiche: 50-247, 83/03/22, 8303230230.

--8303230237 Testimony of RM Bernero re severe accident source terms.Prof qualifications encl.
BERNERO, R. M. Division of Risk Analysis 83/03/22 13pp. 17661:352 24X Fiche: 50-247, 83/03/22, 8303230230.

8303240545 Testimony of SC Sholly on Commission Question 5 re plant risk.Sandia siting study demonstrates Indian Point is one of very few reactor sites for which large consequences possible.Certificate of Svc encl.Related correspondence.
SHOLLY, S. C. Union of Concerned Scientists SHOLLY, S. C. Public Interest Research Group, New York 83/03/22. 7pp. 17682:337. 24X Fiche: 50-247, 83/03/22, 8303240545.

8303250145 Testimony of TE Potter on Commission Question 5 re NUREG/CR-2239, "Technical Guidance for Siting Criteria Development." NUREG should not be used alone to assess risks from existing plants.Related correspondence.
POTTER, T. E. Consolidated Edison Co. of New York, Inc. POTTER, T. E. Power Authority of the State of New York. POTTER, T. E. Pickard, Lowe & Garrick, Inc 83/03/22. 19pp. 17691:022. 24X Fiche: 50-247, 83/03/22, 8303250145.

--8303250149 Testimony of DC Bley, DF Paddleford, TE Potter & DC Richardson on Commission Question 5 Risks of plant in relation to NRC safety goals & in comparison to other plants discussed.Prof qualifications & Certificate of Svc encl.
BLEY, D. C. ; PADDLEFORD, D. F. ; POTTER, T. E. Consolidated Edison Co. of New York, Inc. 83/03/22. 43pp. 17691:041. 24X Fiche: 50-247, 83/03/22, 8303250145.

8303290374 Transcript of 830322 hearing in White Plains, NY.Pp 10,737-11,117.Supporting documentation encl.
* Atomic Safety and Licensing Board Panel 83/03/22 614pp. 17720:284 24X Fiche: 50-247, 83/03/22, 8303290374.

8303300146 Transcript of 830323 hearing in White Plains, NY.Pp 11,118-11,513.Supporting documentation encl.
* Atomic Safety and Licensing Board Panel 83/03/23 460pp. 17735:316. 24X Fiche: 50-247, 83/03/23, 8303300146.

8303300134 Transcript of 830325 hearing in White Plains, NY.Pp 11,671-11,953.Supporting documentation encl.
* Atomic Safety and Licensing Board Panel 83/03/25 400pp. 17731:230. 24X Fiche: 50-247, 83/03/25, 8303300134.

U. Congressional/Executive Correspondence

8303290083 Responds to 830207 ltr re emergency preparedness issues. Comprehensive appraisal of onsite emergency preparedness contained in SECY-82-199.Notices of violations issued to licensees failing to install prompt notification sys.
PALLADINO, N. J. Commissioners. 83/03/08. MARKEY, E. J. House of Rep. ; Interior & Insular Affairs 3pp. 17728:325. 24X Fiche: 50-247, 83/03/08, 8303290083.

--8303290116 Communicates dismay & displeasure over recent Commission decision re lack of emergency preparedness at facility. Commission failed to act in manner consistent w/regulations & sense of issue importance.
MARKEY, E. J. House of Rep. ; Interior & Insular Affairs 83/02/07. PALLADINO, N. J. Commissioners. 2pp. 17728:341 24X Fiche: 50-247, 83/03/08, 8303290083.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp. 247 Fiche: 50-000, 83/02/24, 8302250505.

8303080322 Submits info re operator licensing exam site visits, in response to 830111 Generic Ltr 83-01.
BAYNE, J. P. Power Authority of the State of New York 83/03/02. EISENHUT, D. G. Division of Licensing 2pp. 17449:314 24X Fiche: 50-286, 83/03/02, 8303080322.

DOCKET 50-287 OCONEE NUCLEAR STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

8303160121 Forwards Amends 118, 118 & 115 to Licenses DPR-38, DPR-47 & DPR-55, respectively & notice of issuance & availability. Amend requires yearly review of station emergency & security plans by nuclear safety review board.
STOLZ, J. F. Operating Reactors Branch 4 83/03/04 TUCKER, H. B. Duke Power Co. 3pp. 17604:338. 24X Fiche: 50-269, 83/03/04, 8303160121.

--8303160125 Amends 118, 118 & 115 to Licenses DPR-38, DPR-47 & DPR-55, respectively, requiring yearly review of station emergency & security plans by nuclear safety review board.
STOLZ, J. F. Operating Reactors Branch 4 83/03/04 8pp. 17604:341. 24X Fiche: 50-269, 83/03/04, 8303160121.

--8303160135 Notice of issuance & availability of Amends 118, 118 & 115 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
STOLZ, J. F. Operating Reactors Branch 4 83/03/04 2pp. 17604:349. 24X Fiche: 50-269, 83/03/04, 8303160121.

8303160082 Responds to 821112 ltr re changes submitted in Rev 9 of security plan.Rev acceptable.
STOLZ, J. F. Operating Reactors Branch 4 83/03/08 TUCKER, H. B. Duke Power Co. 2pp. 17614:343. 24X Fiche: 50-269, 83/03/08, 8303160082.

8303290475 Requests exemption from 10CFR50 App E, Item IV.F.h & 10CFR50.47.b(14) re active participation of crisis mgt ctr personnel for each station during annual emergency preparedness exercise.
TUCKER, H. B. Duke Power Co. 83/03/09 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENSAM, E. G. Licensing Branch 4. 3pp. 17724:324 24X Fiche: 50-000, 83/03/09, 8303290475.

8303240113 Releases public version of revised crisis mgt plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/21. Document Management Branch. 1p. 17700:029. 24X Fiche: 50-000, 83/03/21, 8303240113.

--8303240120 Forwards public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.1 re recovery manager & immediate staff group plan & 5.3.4 re scheduling/planning support group.
TUCKER, H. B. Duke Power Co. 83/03/08 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 17700:030 24X Fiche: 50-000, 83/03/21, 8303240113.

--8303240127 Public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.1 re recovery manager & immediate staff group plan & 5.3.4 re scheduling/planning support group.
* Duke Power Co. 83/02/28. 215pp. 17700:032. 24X Fiche: 50-000, 83/03/21, 8303240113.

8303280131 Ack receipt of 830304 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01.
DANCE, H. C. Division of Project & Resident Programs. 83/03/22. TUCKER, H. B. Duke Power Co. 1p. 17707:001. 24X Fiche: 50-269, 83/03/22, 8303280131.

--8303280138 Responds to NRC 830208 ltr re violations noted in IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01.Corrective actions withheld (ref 10CFR73.21).
TUCKER, H. B. Duke Power Co. 83/03/04 O'REILLY, J. P. Region 2, Office of Director. 2pp. 17707:002. 24X Fiche: 50-269, 83/03/22, 8303280131.

--8303280144 Forwards IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01 on 830110-14 & notice of violation.Notice of violation withheld (ref 10CFR73.21).
DANCE, H. C. Division of Project & Resident Programs. 83/02/08. TUCKER, H. B. Duke Power Co. 2pp. 17707:004. 24X Fiche: 50-269, 83/03/22, 8303280131.

--8303280148 IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01 on 830110-14.Noncompliance noted in area of access control of designated vehicles.Details withheld (ref 10CFR73.21).
TILLMAN, A. Region 2, Office of Director 83/02/04. 1p. 17707:006. 24X Fiche: 50-269, 83/03/22, 8303280131.

I. Financial information

8303080084 Forwards annual financial rept, 1981, Financial forecast for 1982-84 also encl.
TUCKER, H. B. Duke Power Co. 83/03/01 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 6pp. 17452:174. 24X Fiche: 50-000, 83/03/01, 8303080084.

--8303080092 Annual financial rept, 1981.
HORN, C. ; LEE, W. S. Duke Power Co. 82/02/15. 44pp. 17452:180. 24X Fiche: 50-000, 83/03/01, 8303080084.

P. Operating license stage documents & correspondence

8303020194 Forwards Unresolved Safety Issue A-47 task action plan & list of addl estimates & assumptions for parameters used in ORNL model of facility, for comment, in order to encourage participation in resolution of safety issu
EISENHUT, D. G. Division of Licensing 83/0 14 TUCKER, H. B. Duke Power Co. 12pp. 17419:158. 24X Fiche: 50-269, 83/02/14, 8303020194.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303010698 Notification of 830118 meeting w/B&W Owners Group & B&W in Bethesda, MD to discuss plans in developing study re frequency & severity of potential pressurized thermal shock events applicable to all B&W plants.
VISSING, G. Operating Reactors Branch 4 83/02/18. STOLZ, J. Operating Reactors Branch 4 3pp. 17348:334. 24X Fiche: 50-000, 83/02/18, 8303010698.

8303030405 Expresses concern re whether util justification for operability provides required assurance that large diameter Pratt butterfly valves will close in event of DBA LOCA. NRC must be notified in 30 days if understanding incorrect.
STOLZ, J. F. Operating Reactors Branch 4 83/02/18. TUCKER, H. B. Duke Power Co. 5pp. 17419:204. 24X Fiche: 50-269, 83/02/18, 8303030405.

8303070141 Forwards "Procedures Generation Package," "Technical Verification of Nuclear Station Emergency Procedures & Guidelines," "Writers Guide for Emergency & Abnormal " & "Control Room Review Plan," per NUREG-0737, Suppl 1.
TUCKER, H. B. Duke Power Co. 83/02/28. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 17432:011. 24X Fiche: 50-000, 83/02/28, 8303070141.

--8303070169 "Control Room Review Plan for Oconee, McGuire & Catawba Nuclear Stations, Duke Power Co."
* Duke Power Co. C/1800023 R03. 83/02/15. 38pp. 17432:065. 24X Fiche: 50-000, 83/02/28, 8303070141.

8303080294 Forwards revised "Offsite Dose Calculation Manual for Duke Power Nuclear Stations."
TUCKER, H. B. Duke Power Co. 83/02/28. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p. 17455:196. 24X Fiche: 50-000, 83/02/28, 8303080294.

--8303080324 Revised "Offsite Dose Calculation Manual for Duke Power Nuclear Stations."
BIRCH, M. L. Duke Power Co. 83/02/28. 96pp. 17455:198. 24X Fiche: 50-000, 83/02/28, 8303080294.

8303090163 Submits changes to 821115 status rept of NUREG-0737, Items II. B. 3, "Post-Accident Sampling," & II. F. 1, "Accident Monitoring."
TUCKER, H. B. Duke Power Co. 83/03/01 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4 2pp. 17471:317. 24X Fiche: 50-269, 83/03/01, 8303090163.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303160121 Forwards Amends 118, 118 & 115 to Licenses DPR-38, DPR-47 & DPR-55, respectively & notice of issuance & availability. Amend requires yearly review of station emergency & security plans by nuclear safety review board.
STOLZ, J. F. Operating Reactors Branch 4 83/03/04 TUCKER, H. B. Duke Power Co. 3pp. 17604:338. 24X Fiche: 50-269, 83/03/04, 8303160121.

--8303160125 Amends 118, 118 & 115 to Licenses DPR-38, DPR-47 & DPR-55, respectively, requiring yearly review of station emergency & security plans by nuclear safety review board.
STOLZ, J. F. Operating Reactors Branch 4 83/03/04 8pp. 17604:341. 24X Fiche: 50-269, 83/03/04, 8303160121.

--8303160135 Notice of issuance & availability of Amends 118, 118 & 115 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
STOLZ, J. F. Operating Reactors Branch 4 83/03/04 2pp. 17604:349. 24X Fiche: 50-269, 83/03/04, 8303160121.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303160510 Provides addl info re ECCS calculations utilizing cladding models contained in NUREG-0630.
TUCKER, H. B. Duke Power Co. 83/03/07. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 17592:323. 24X Fiche: 50-269, 83/03/07, 8303160510.

8303170136 Summary of 830223 meeting w/B&W Regulatory Response Group in Bethesda, MD re small break LOCA procedures & maintaining proper steam generator water level.
VAN VLIET, J. Operating Reactors Branch 4 83/03/08 Operating Reactors Branch 4 43pp. 17615:224. 24X Fiche: 50-000, 83/03/08, 8303170136.

8303210120 Informs that NRC resident inspector will be obtaining info on valve failure on loss of power data. Info needed to resolve Unresolved Safety Issue A-47.
EISENHUT, D. G. Division of Licensing 83/03/09 TUCKER, H. B. Duke Power Co. 3pp. 17660:129. 24X Fiche: 50-269, 83/03/09, 8303210120.

8303150483 Forwards response to 821213 order re NUREG-0737, Item II. F. 2, "Instrumentation to Detect Inadequate Core Cooling." Design approval of sys described in encl requested prior to final design & procurement efforts initiation.
TUCKER, H. B. Duke Power Co. 83/03/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4 108pp. 17557:311. 24X Fiche: 50-269, 83/03/10, 8303150483.

8303240228 Application for amend to License DPR-55, revising Tech Specs to expand storage capacity of spent fuel pool from 474 to 825 spaces by reracking spent fuel pool w/poison racks.
TUCKER, H. B. Duke Power Co. 83/03/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4. 3pp. 17680:057. 24X Fiche: 50-287, 83/03/10, 8303240228.

--8303240235 Proposed Tech Specs expanding storage capacity of spent fuel pool from 474 to 825 spaces by reracking spent fuel pool w/poison racks.
* Duke Power Co. 83/03/10. 61pp. 17680:060. 24X Fiche: 50-287, 83/03/10, 8303240228.

8303210006 Forwards Amends 119, 119 & 116 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability. Amends revise Tech Specs re heatup, cooldown & inservice test limitations for RCS.
CONNER, E. L. Operating Reactors Branch 4. 83/03/11. TUCKER, H. B. Duke Power Co. 2pp. 17659:344. 24X Fiche: 50-269, 83/03/11, 8303210006.

--8303210009 Amends 119, 119 & 116 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs re heatup, cooldown & inservice test limitations for RCS.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/11. 22pp. 17659:346. 24X Fiche: 50-269, 83/03/11, 8303210006.

--8303210013 Safety evaluation supporting Amends 119, 119 & 116 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
* Office of Nuclear Reactor Regulation, Director. 83/03/11. 4pp. 17660:006. 24X Fiche: 50-269, 83/03/11, 8303210006.

--8303210015 Notice of issuance & availability of Amends 119, 119 & 116 to Licenses DPR-38, DPR-47 & DPR-55, respectively.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/11. 2pp. 17660:010. 24X Fiche: 50-269, 83/03/11, 8303210006.

8303300733 Summary of 830303 meeting w/utils, B&W Owners Group & Natl Nuclear Corp in Bethesda, MD re plans concerning frequency & severity of pressurized thermal shock events for B&W plants. Viewgraphs encl.
VISSING, G. S. Operating Reactors Branch 4. 83/03/15. Operating Reactors Branch 4. 174pp. 17765:013. 24X Fiche: 50-000, 83/03/15, 8303300733.

8303300028 Forwards order confirming licensee commitments to implement post-TMI-related items set forth in NUREG-0737. Order based on licensee responses to Generic Ltrs 82-05 & 82-10.
STOLZ, J. F. Operating Reactors Branch 4 83/03/16 TUCKER, H. B. Duke Power Co. 3pp. 17751:153 24X Fiche: 50-269, 83/03/16, 8303300028.

--8303300036 Order confirming licensee commitments on post-TMI-related issues in NUREG-0737.
PURPLE, R. A. Division of Licensing 83/03/18 Duke Power Co. 10pp. 17751:156 24X Fiche: 50-269, 83/03/16, 8303300028.

8303240270 Confirms NRC understandings re maintaining containment purge valves closed whenever reactor not in cold shutdown or refueling mode, presented in 830218 ltr. Description of mods to purge sys encl.
TUCKER, H. B. Duke Power Co. 83/03/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4 3pp. 17682:125 24X Fiche: 50-269, 83/03/17, 8303240270.

8303240465 Responds to Generic Ltr 83-10 re resolution of TMI Action Plan Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps." Plans & schedule for resolution of issue will be provided by 830701.
TUCKER, H. B. Duke Power Co. 83/03/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director EISENHUT, D. G. Division of Licensing 1p. 17678:042 24X Fiche: 50-269, 83/03/17, 8303240465.

8303280194 Application for amend to Licenses DPR-38, DPR-47 & DPR-55, extending limiting conditions for operation of startup transformers & establishing allowable degraded conditions & required action statements.
TUCKER, H. B. Duke Power Co. 83/03/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 17709:201 24X Fiche: 50-269, 83/03/17, 8303280194.

--8303280200 Proposed Tech Specs, revising limiting condition for operation of startup transformers & establishing allowable degraded conditions & required action statements.
* Duke Power Co. 83/03/17 16pp. 17709:203 24X Fiche: 50-269, 83/03/17, 8303280194.

8303280032 Advises that addl info requested by NRC 830110 ltr on NUREG-0737, Items II.F.1.4, II.F.1.5 & II.F.1.6 re containment monitors difficult to collate. Delay caused by extensive util/vendor interface. Info will be submitted by 830525.
TUCKER, H. B. Duke Power Co. 83/03/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4 1p. 17709:306 24X Fiche: 50-269, 83/03/18, 8303280032.

8303300010 Forwards safety evaluation & EG&G technical evaluation re adequacy of station electric distribution sys voltages. Voltage analysis acceptable. Unit 3 test results acceptable for Units 1 & 2.
STOLZ, J. F. Operating Reactors Branch 4 83/03/21 TUCKER, H. B. Duke Power Co. 2pp. 17751:246 24X Fiche: 50-269, 83/03/21, 8303300010.

--8303300015 Safety evaluation supporting adequacy of station electric distribution sys voltages subj to implementation of Tech Spec change prohibiting use of one startup transformer for more than one unit.
* NRC - No Detailed Affiliation Given. 83/03/21 5pp. 17751:248 24X Fiche: 50-269, 83/03/21, 8303300010.

--8303300021 "Adequacy of Station Electric Distribution Sys Voltages, Oconee Nuclear Station, Units 1, 2 & 3," technical evaluation rept.
UDY, A. C. EG&G, Inc. FIN A-6429 EGG-EA-6131 83/01/31 NRC - No Detailed Affiliation Given. 12pp. 17751:253 24X Fiche: 50-269, 83/03/21, 8303300010.

8303300173 Forwards request for addl info needed to complete review of neutron dosimetry provided in BAW-1697 & BAW-1699. Neutron dosimetry analysis schedule due in 60 days.
STOLZ, J. F. Operating Reactors Branch 4 83/03/22 TUCKER, H. B. Duke Power Co. 6pp. 17763:096 24X Fiche: 50-269, 83/03/22, 8303300173.

8303290217 Withdraws request for hearing re order imposing environ qualification requirements. Withdrawal contingent upon util understanding of final rule on environ qualification.
CARR, A. V. Duke Power Co. 83/03/24 EISENHUT, D. G. Division of Licensing 2pp. 17722:242 24X Fiche: 50-269, 83/03/24, 8303290217.

8303310551 Notification of 830407 meeting w/B&W Owners Group in Bethesda, MD to review progress, schedules & typical event analyses re study of pressurized thermal shock.
VISSING, G. S. Operating Reactors Branch 4 83/03/25 STOLZ, J. F. Operating Reactors Branch 4 2pp. 17780:360 24X Fiche: 50-000, 83/03/25, 8303310551.

8303300164 "Adequacy of Station Electric Distribution Sys Voltages, Oconee Nulear Station, Units 1, 2 & 3," interim rept.
UDY, A. C. EG&G, Inc. FIN A-6429 8303300164 83/03/31 EMANI, J. Division of Systems Integration (post 811005) 14pp. 17753:022 24X Fiche: 50-287, 83/03/31, 8303300164.

## Q. Inspection reports, IE Bulletins & correspondence

8303010666 Responds to NRC ltr re violations noted in IE Insp Repts 50-269/82-09, 50-270/82-09 & 50-287/82-09. Corrective actions, mods to computer alarms & statalarms to include Group 8 position limits will be implemented by 830114.
TUCKER, H. B. Duke Power Co. 82/12/17 O'REILLY, J. P. Region 2, Office of Director 1p. 17341:076 24X Fiche: 50-269, 82/12/17, 8303010666.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 111pp. 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp. 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp. 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

8303230220 Forwards response to 830311 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." AK2 breaker maint program conforms w/GE Svc Advice Ltr 175(CPDD)9.3 guidance. Program in place since Feb 1979.
TUCKER, H. B. Duke Power Co. 83/03/21 O'REILLY, J. P. Region 2, Office of Director 4pp. 17665:189 24X Fiche: 50-269, 83/03/21, 8303230220.

8303280131 Ack receipt of 830304 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01.
DANCE, H. C. Division of Project & Resident Programs 83/03/22
TUCKER, H. B. Duke Power Co. 1p. 17707:001 24X
Fiche: 50-269, 83/03/22, 8303280131.

--8303280138 Responds to NRC 830208 ltr re violations noted in IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01. Corrective actions withheld (ref 10CFR73.21).
TUCKER, H. B. Duke Power Co. 83/03/04 O'REILLY, J. P. Region 2, Office of Director 2pp. 17707:002 24X Fiche: 50-269, 83/03/22, 8303280131.

--8303280144 Forwards IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01 on 830110-14 & notice of violation. Notice of violation withheld (ref 10CFR73.21).
DANCE, H. C. Division of Project & Resident Programs 83/02/08
TUCKER, H. B. Duke Power Co. 2pp. 17707:004 24X
Fiche: 50-269, 83/03/22, 8303280131.

--8303280148 IE Insp Repts 50-269/83-01, 50-270/83-01 & 50-287/83-01 on 830110-14. Noncompliance noted in area of access control of designated vehicles. Details withheld (ref 10CFR73.21).
TILLMAN, A. , MCGUIRE, D. R. Region 2, Office of Director 83/02/04
1p. 17707:006 24X Fiche: 50-269, 83/03/22, 8303280131.

## R. Periodic operating reports & related correspondence

8303080353 Forwards monthly operating repts for Dec 1982.
TUCKER, H. B. Duke Power Co. 83/01/14 Director's Office, Office of Inspection and Enforcement 1p. 17453:348 24X
Fiche: 50-269, 83/01/14, 8303080353.

--8303080364 Monthly operating repts for Dec 1982.
REAVIS, J. A. Duke Power Co. 83/01/14 16pp. 17453:349 24X
Fiche: 50-269, 83/01/14, 8303080353.

8303180379 Forwards monthly operating repts for Feb 1983.
TUCKER, H. B. Duke Power Co. 83/03/15 Director's Office, Office of Inspection and Enforcement 1p. 17622:266 24X
Fiche: 50-269, 83/03/15, 8303180379.

--8303180386 Monthly operating repts for Feb 1983.
REAVIS, J. A. Duke Power Co. 83/03/15. 16pp. 17622:267. 24X
Fiche: 50-269, 83/03/15, 8303180379.

S. Reportable occurrences, LERs & related correspondence

8303180332 Forwards LER 83-001/01T-0. Detailed event analysis encl.
TUCKER, H. B. Duke Power Co. 83/03/09. O'REILLY, J. P. Region 2,
Office of Director. 2pp. 17619:331. 24X Fiche: 50-287, 83/03/09,
8303180332.

--8303180338 LER 83-001/01T-0 on 830223. HPI train 3A made inoperable when control power fuses for 3HP-24 & 3HP-26 found blown. Caused by component failure & design deficiency. Power reduced & blown fuses replaced.
QUILL, P. Duke Power Co. 83/03/09. Region 2, Office of
Director. 1p. 17619:333. 24X Fiche: 50-287, 83/03/09, 8303180332.

8303220023 RO on 830225, reactor protective sys pump power monitor sys failed to meet operability requirements. Investigation incomplete at present time. Rept will be submitted by 830325.
TUCKER, H. B. Duke Power Co. 83/03/11. O'REILLY, J. P. Region 2,
Office of Director. 1p. 17652:110. 24X Fiche: 50-287, 83/03/11,
8303220023.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated
Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24,
8302250505.

DOCKET 50-288 REED COLLEGE RESEARCH REACTOR

Q. Inspection reports, IE Bulletins & correspondence

8303290441 Forwards IE Insp Rept 50-288/83-01 on 830215-17. No noncompliance noted.
STERNBERG, D. M. Region 5, Office of Director. 83/03/09. BRAGDON, P.
Reed College. 2pp. 17725:352. 24X Fiche: 50-288, 83/03/09,
8303290441.

--8303290446 IE Insp Rept 50-288/83-01 on 830215-17. No noncompliance noted. Major areas inspected: organization, logs & records, review & audit, requalification training, procedures, surveillance, experiments & followup on previous insp items.
MALMROS, M. H., DODDS, R. T. Region 5, Office of Director. 83/03/09.
4pp. 17725:354. 24X Fiche: 50-288, 83/03/09, 8303290441.

DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8303100553 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/02. Document
Management Branch. 1p. 17521:329. 24X Fiche: 50-289, 83/03/02,
8303100553.

--8303100557 Forwards public version of Rev 6 to Emergency Plan Implementing Procedure 1004.8, "Callout of Onsite & Offsite Duty Roster Personnel."
NASH, B. General Public Utilities - GPU Service Corp. 83/02/17.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p.
17521:330. 24X Fiche: 50-289, 83/03/02, 8303100553.

--8303100560 Public version of Rev 6 to Emergency Plan Implementing Procedure 1004.8, "Callout of Onsite & Offsite Duty Roster Personnel."
GRANGE, G. J. General Public Utilities - GPU Service Corp.
83/02/09. 15pp. 17521:331. 24X Fiche: 50-289, 83/03/02, 8303100553.

8303160461 Forwards IE Safeguards Insp Rept 50-289/83-03 on 830110-14. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/02.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 2pp.
17592:308. 24X Fiche: 50-289, 83/03/02, 8303160461.

--8303160482 IE Safeguards Insp Rept 50-289/83-03 on 830110-14. No noncompliance noted. Major areas inspected: site orientation, security plan & implementing procedures & physical barriers. Safeguards info deleted (ref 10CFR73.21 or 10CFR9.5(a)(4)).
SMITH, G., BAILEY, R., KUSHNEV, W. Region 1, Office of Director.
83/02/24. 4pp. 17592:310. 24X Fiche: 50-289, 83/03/02, 8303160461.

8303180128 Responds to 820701 request for schedular exemptions from 10CFR50.48(c) fire protection implementation dates. Request denied due to lack of detailed info.
EISENHUT, D. G. Division of Licensing. 83/03/02. HUKILL, H. D.
General Public Utilities - GPU Service Corp. 6pp. 17625:142. 24X
Fiche: 50-289, 83/03/02, 8303180128.

8303180473 Notification of 830315 meeting w/util in Bethesda, MD to discuss licensee appeal of fire protection exemption requests denied in 830114 SER.
VAN VLIET, J. A. Operating Reactors Branch 4. 83/03/14. STOLZ, J. F.
Operating Reactors Branch 4. 3pp. 17640:173. 24X
Fiche: 50-289, 83/03/14, 8303180473.

8303300442 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/24. Document
Management Branch. 1p. 17754:035. 24X Fiche: 50-289, 83/03/24,
8303300442.

--8303300451 Public version of Rev 7 to Emergency Plan Implementing Procedure 1004.1, "Unusual Event" & Rev 8 to 1004.3, "Site Emergency." Revised indices encl.
GRANGE, G. General Public Utilities - GPU Service Corp. 83/02/28.
66pp. 17754:036. 24X Fiche: 50-289, 83/03/24, 8303300442.

8303300781 Releases public version of rev to emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/28. Document
Management Branch. 1p. 17765:259. 24X Fiche: 50-289, 83/03/28,
8303300781.

--8303300784 Public version of Rev 2 to Emergency Plan Implementing Procedure 1004.16, "Contaminated Injuries/Radiation Overexposure."
* General Public Utilities - GPU Service Corp. 83/03/08. 10pp.
17765:260. 24X Fiche: 50-289, 83/03/28, 8303300781.

8303310160 Releases public version of rev to emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/28. Document
Management Branch. 1p. 17775:149. 24X Fiche: 50-289, 83/03/28,
8303310160.

--8303310163 Public version of Rev 5 to Emergency Plan Implementing Procedure EPIP 1004.7, "Offsite/Onsite Dose Projections."
* General Public Utilities - GPU Service Corp. 83/03/08. 24pp.
17775:150. 24X Fiche: 50-289, 83/03/28, 8303310160.

Q. Adjudicatory correspondence

8303010305 Order extending time until 830303 for Commission to act to review ALAB-705.
CHILK, S. J. Office of the Secretary of the Commission. 83/02/23.
Commissioners. 1p. 17333:331. 24X Fiche: 50-289, 83/02/23,
8303010305.

8303020080 Notice of 830307 hearing. Licensee & NRC will present direct evidence. UCS will cross-examine first, followed by licensee or NRC.
SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 83/02/28.
2pp. 17352:129. 24X Fiche: 50-289, 83/02/28, 8303020080.

8303070093 Responds to 830224 request for TMI-1 procedures. Four procedures provided on 830225 & five procedures encl. Matl not relevant to reopened proceeding. Svc list encl. Related correspondence w/o encl.
BAXTER, T. A. Shaw, Pittman, Potts & Trowbridge. BAXTER, T. A.
Metropolitan Edison Co. 83/03/02. WEISS, E. R. Harmon & Weiss.
WEISS, E. R. Union of Concerned Scientists. 4pp. 17434:325. 24X
Fiche: 50-289, 83/03/02, 8303070093.

8303080068 Request of Commonwealth of PA Dept of Environ Resources to participate as interested state in reopened proceeding. Svc list encl.
ADLER, R. W. Pennsylvania, Commonwealth of. 83/03/02. EDLES, G. J.,
BUCK, J. H., GOTCHY, R. L. Atomic Safety and Licensing Appeal Panel.
3pp. 17457:244. 24X Fiche: 50-289, 83/03/02, 8303080068.

8303070083 Forwards B&W "Evaluation of Small Break LOCA Operating Procedures & Effectiveness of Emergency Feedwater Spray for B&W Designed Operating NSSS." Svc list encl. Related correspondence.
BAXTER, T. A. Shaw, Pittman, Potts & Trowbridge. BAXTER, T. A.
Metropolitan Edison Co. 83/03/03. EDLES, G. J., BUCK, J. H.,
GOTCHY, R. L. Atomic Safety and Licensing Appeal Panel. 90pp.
17435:044. 24X Fiche: 50-289, 83/03/03, 8303070083.

8303080314 Order extending time until 830310 for Commission to act to review ALAB-705.
CHILK, S. J. Office of the Secretary of the Commission 83/03/03
Commissioners 1p 17449:329 24X Fiche: 50-289, 83/03/03, 8303080314.

8303070139 Forwards motion to defer reopened hearing pending resolution of Board Notification 83-21 & further discovery. New info likely to alter NRC position re adequacy of boiler-condenser to assure natural circulation.
WEISS, E. R., JORDAN, W. S. Union of Concerned Scientists 83/03/04
EDLES, G. J., GOTCHY, R. L., BUCK, J. H. Atomic Safety and Licensing Appeal Panel 2pp 17430:332 24X Fiche: 50-289, 83/03/04, 8303070139.

--8303070145 Motion to defer reopened hearing pending resolution of Board Notification 83-21 & further discovery. Hearing should be deferred until NRC resolves differences between position & board notification re DHR. Certificate of Svc encl.
WEISS, E. R., JORDAN, W. S. Union of Concerned Scientists WEISS, E. R. Harmon & Weiss 83/03/04 Atomic Safety and Licensing Appeal Panel 9pp 17430:334 24X Fiche: 50-289, 83/03/04, 8303070139.

8303080427 Order informing that UCS motion to defer indefinitely reopened hearing pending resolution of issue re efficacy of boiler condenser process will be first order of business at 830307 reopened proceeding.
SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 83/03/04
3pp 17453:268 24X Fiche: 50-289, 83/03/04, 8303080427.

8303080459 Joint motion to extend until 830401 date for filing comments per ASLAB 830217 order. Certificate of Svc encl.
ZAHLER, R. E. Metropolitan Edison Co ZAHLER, R. E. Shaw, Pittman, Potts & Trowbridge 83/03/04 Atomic Safety and Licensing Appeal Panel 5pp 17453:129 24X Fiche: 50-289, 83/03/04, 8303080459.

8303080471 Order CLI-83-5, denying UCS 830107 motion re ex parte communications. Seismic issues are unrelated to 790328 accident & therefore, to restart hearing. Communications about seismic issues are not ex parte.
CHILK, S. J. Office of the Secretary of the Commission 83/03/04
Union of Concerned Scientists 2pp 17453:148 24X
Fiche: 50-289, 83/03/04, 8303080471.

8303140700 Staff requirements memo re 830303 affirmation/discussion & vote in Washington, DC on SECY-83-61 re UCS objection to NRC meeting on seismic concerns as violating ex parte prohibition.
CHILK, S. J. Office of the Secretary of the Commission 83/03/04
PLAINE, H. E. Office of the General Counsel 1p 17569:173 24X
Fiche: 50-289, 83/03/04, 8303140700.

8303140260 Advises that time for Commission to review ALAB-705 expired. Commission declined review. Decision became final agency action on 830310.
CHILK, S. J. Office of the Secretary of the Commission 83/03/11
WEISS, E. R. Harmon & Weiss WEISS, E. R. Union of Concerned Scientists 1p 17534:245 24X Fiche: 50-289, 83/03/11, 8303140260.

8303140319 Forwards followup rept re Board Notification BN-83-21, per ASLAB 830307 request. W/o encl.
CUTCHIN, J. M. Hearing Branch 4 83/03/11 EDLES, G. J., GOTCHY, R. L., BUCK, J. H. Atomic Safety and Licensing Appeal Panel 1p 17543:302
24X Fiche: 50-289, 83/03/11, 8303140319.

8303150310 Volunteers Ornstein as addl witness immediately following completion of presently scheduled witness testimony. Ornstein may not appear as UCS witness because NRC may not assist intervenors in NRC proceedings.
CUTCHIN, J. M. Hearing Branch 4 83/03/11 EDLES, G. J., GOTCHY, R. L., BUCK, J. H. Atomic Safety and Licensing Appeal Panel 2pp
17567:071 24X Fiche: 50-289, 83/03/11, 8303150310.

8303170431 Motion for leave to suppl RC Jones & LC Lanese testimony in response to ALAB-708 re reliance on feed & bleed cooling. Certificate of Svc encl.
BAXTER, T. A. Metropolitan Edison Co BAXTER, T. A. Shaw, Pittman, Potts & Trowbridge 83/03/11 Atomic Safety and Licensing Appeal Panel 7pp 17605:001 24X Fiche: 50-289, 83/03/11, 8303170431.

8303170447 Opposition to licensee 830311 motion for leave to suppl testimony. Licensee fails to meet stds for late-filed submission or for reopening record. Certificate of Svc encl.
WEISS, E. R. Union of Concerned Scientists WEISS, E. R. Harmon & Weiss 83/03/14 Atomic Safety and Licensing Appeal Panel 3pp
17609:260 24X Fiche: 50-289, 83/03/14, 8303170447.

8303170458 Order granting util motion to present addl testimony re safety & relief valves & EPRI safety & relief valve test program. Testimony will be limited to matters upon which UCS cross-examined earlier.
SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 83/03/15
Metropolitan Edison Co 2pp 17609:258 24X
Fiche: 50-289, 83/03/15, 8303170458.

8303180377 Advises that parties may submit written comments on Commission staff analysis of GPU vs B&W case trial transcript which is expected by 830328. Comments due 15 days after svc of analysis.
STUCKY, S. W. Docketing & Services Branch 83/03/16 Office of the Executive Legal Director 1p 17621:075 24X Fiche: 50-289, 83/03/16, 8303180377.

8303230204 Order CLI-83-7, taking two issues for review. Issues are responsibility for radiological assessment during first 4 h of emergency declaration & ASLAB requirement that NRC modify final emergency response plans prior to restart.
CHILK, S. J. Office of the Secretary of the Commission 83/03/21
5pp 17663:199 24X Fiche: 50-289, 83/03/21, 8303230204.

J. Insurance & indemnity information

8303150418 Forwards Endorsements 1 & 2 to NELIA Binders N-56 & N-65 & MAELU Binder M-56, respectively.
GERETY, H. F. General Public Utilities - GPU Service Corp. 83/03/07
SALTZMAN, J. Antitrust & Economic analysis Branch (Utility Finance)
37pp 17561:201 24X Fiche: 50-289, 83/03/07, 8303150418.

8303180360 Forwards Endorsement 55 to MAELU Policy MF-73 & Endorsement 63 to NELIA Policy NF-220.
GERETY, H. F. General Public Utilities - GPU Service Corp. 83/03/07
SALTZMAN, J. Assistant Director for State & Licensee Relations 3pp
17620:074 24X Fiche: 50-289, 83/03/07, 8303180360.

8303220089 Forwards Endorsements 56 & 57 to MAELU Policy MF-73.
GERETY, H. F. General Public Utilities - GPU Service Corp. 83/03/16
SALTZMAN, J. Antitrust & Economic analysis Branch (Utility Finance)
3pp 17649:286 24X Fiche: 50-289, 83/03/16, 8303220089.

P. Operating license stage documents & correspondence

8303280341 Notification of contract execution, Mod 4 to "Reanalysis of Existing Data From Telephone Surveys Concerning TMI." Contractor: PA State Univ.
FIELDS, J. A. Technical Assistance Contracts Branch NRC-03-82-123
83/01/03 VOLLMER, R. H. Division of Engineering REGAN, W. NRC - No Detailed Affiliation Given 1p 17713:103 24X
Fiche: 50-289, 83/01/03, 8303280341.

--8303280346 Mod 4, revising address for submitting invoices & incorporating revised Manual Chapter 3202, to "Reanalysis of Existing Data From Telephone Surveys Concerning TMI."
FULGINITI, S. A. Pennsylvania State Univ HAGAN, T. F. Division of Contracts 83/01/03 1p 17713:104 24X Fiche: 50-289, 83/01/03, 8303280341.

8302150368 Forwards table indicating status of Tech Spec change requests pending action. Resolution of five pending requests needed for restart.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/02/09
STOLZ, J. F. Operating Reactors Branch 4 2pp 17157:280 24X
Fiche: 50-289, 83/02/09, 8302150368.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303030747 Board Notification 83-13: Forwards EG&G draft rept, "Identification & Ranking of Nuclear Plant Structures, Sys & Components & Graded QA Guidelines."
EISENHUT, D. G. Division of Licensing 83/02/17 PALLADINO, N., GILINSKY, V., ASSELSTINE Commissioners 24pp 17364:037 24X
Fiche: 50-000, 83/02/17, 8303030747.

8303010698 Notification of 830118 meeting w/B&W Owners Group & B&W in Bethesda, MD to discuss plans in developing study re frequency & severity of potential pressurized thermal shock events applicable to all B&W plants.
VISSING, G. Operating Reactors Branch 4 83/02/18 STOLZ, J.
Operating Reactors Branch 4 3pp 17348:334 24X
Fiche: 50-000, 83/02/18, 8303010698.

8303030710 Board Notification 83-17: Forwards JH Conran 830209 affidavit re changes to previous testimony on Unresolved Safety Issue A-17, "Sys Interaction in Nuclear Power Plants."
EISENHUT, D. G. Division of Licensing 83/02/18 PALLADINO, N. J., GILINSKY, V., AHEARNE, J. Commissioners 6pp 17363:317 24X
Fiche: 50-000, 83/02/18, 8303030710.

8303030731 Board Notification 83-21 provides info re transient & accident reliance on DHR by steam generators.
EISENHUT, D. G. Division of Licensing 83/02/18 PALLADINO, N. J.; GILINSKY, V.; AHEARNE, J. Commissioners 5pp 17363:252 24X
Fiche: 50-289, 83/02/18, 8303030731

--8303030735 Requests ASLB notification of encl info re transient & accident reliance on DHR by steam generators.
MATTSON, R. J. Division of Systems Integration (post 811005).
THOMPSON, H. L. Division of Human Factors Safety 83/02/18
EISENHUT, D. G. Division of Licensing 4pp 17363:257 24X
Fiche: 50-289, 83/02/18, 8303030731

--8303030741 Reviews B&W-GPU trial record re technical adequacy of small break loss-of-coolant & natural circulation procedures. NRR assigned technical aspects evaluation. Lahey testimony encl.
DIRCKS, W. J. Office of the Executive Director for Operations.
83/02/17 PALLADINO, N. J.; GILINSKY, V.; AHEARNE, J. Commissioners.
56pp 17363:261 24X Fiche: 50-289, 83/02/18, 8303030731.

8303090110 Board Notification 83-20: forwards 830210 memo providing results of review of licensee demonstration of RCS pressure control using HPI sys. Memo relates to natural circulation & feed & bleed modes of cooling.
EISENHUT, D. G. Division of Licensing 83/02/18 PALLADINO, N.; GILINSKY, V.; AHEARNE, J. Commissioners 5pp 17465:001 24X
Fiche: 50-289, 83/02/18, 8303090110.

--8303090117 Forwards excerpt from IE Insp Rept 50-289/83-01 documenting results of site review re RCS pressure control testing. Info pertinent to reopened hearing on adequacy of reactor core cooling. Board notification recommended.
STAROSTECKI, R. Division of Project & Resident Programs 83/02/10
EISENHUT, D. G. Division of Licensing 5pp 17465:006 24X
Fiche: 50-289, 83/02/18, 8303090110.

8303110414 Forwards Amend 80 to License DPR-50, safety evaluation & notice of issuance & availability. Amend eliminates use of sodium thiosulfate as spray additive in reactor bldg spray sys.
VAN VLIET, J. Operating Reactors Branch 4 83/02/24 HUKILL, H. D.
General Public Utilities - GPU Service Corp 4pp 17523:024 24X
Fiche: 50-289, 83/02/24, 8303110414.

--8303110419 Amend 80 to License DPR-50, eliminating use of sodium thiosulfate as spray additive in reactor bldg spray sys.
STOLZ, J. F. Operating Reactors Branch 4 83/02/24 8pp
17523:028 24X Fiche: 50-289, 83/02/24, 8303110414.

--8303110424 Safety evaluation supporting Amend 80 to License DPR-50.
* Office of Nuclear Reactor Regulation, Director 83/02/24 4pp
17523:036 24X Fiche: 50-289, 83/02/24, 8303110414.

--8303110428 Notice of issuance & availability of Amend 80 to License DPR-50.
STOLZ, J. F. Operating Reactors Branch 4 83/02/24 2pp.
17523:040 24X Fiche: 50-289, 83/02/24, 8303110414.

8303140197 Forwards "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1982," Rev 1 to "Process Control Program" & Rev 2 to "Offsite Dose Calculation Manual."
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/02/28
HAYNES, R. C. Region 1, Office of Director 1p 17528:177 24X
Fiche: 50-289, 83/02/28, 8303140197.

--8303140202 Rev 1 to "Process Control Program."
* Hittman Nuclear & Development Corp (subs. Hittman Corp.).
82/12/06 51pp 17528:195 24X Fiche: 50-289, 83/02/28, 8303140197.

--8303140203 Rev 2 to "Offsite Dose Calculation Manual."
WILLIAMS, S. E. General Public Utilities - GPU Service Corp.
82/12/22 89pp 17528:246 24X Fiche: 50-289, 83/02/28, 8303140197.

8303160104 Forwards Amend 81 to License DPR-50, safety evaluation & notice of issuance & availability. Amend adds special test exceptions, permitting Tech Spec suspension during restart low power natural circulation test.
STOLZ, J. F. Operating Reactors Branch 4 83/02/28 HUKILL, H. D.
General Public Utilities - GPU Service Corp. 3pp 17614:304 24X
Fiche: 50-289, 83/02/28, 8303160104.

--8303160108 Amend 81 to License DPR-50, adding special test exceptions which permit Tech Spec suspension during restart low power natural circulation test.
STOLZ, J. F. Operating Reactors Branch 4 83/02/28 7pp.
17614:307 24X Fiche: 50-289, 83/02/28, 8303160104.

--8303160110 Safety evaluation supporting Amend 81 to License DPR-50.
* Office of Nuclear Reactor Regulation, Director 83/02/28 4pp
17614:314 24X Fiche: 50-289, 83/02/28, 8303160104.

--8303160114 Notice of issuance & availability of Amend 81 to License DPR-50.
STOLZ, J. F. Operating Reactors Branch 4 83/02/28 2pp.
17614:318 24X Fiche: 50-289, 83/02/28, 8303160104.

8303090189 Forwards matrix indicating misunderstandings for NRC Categories I.B, II.A & II.B noted in Franklin Research Ctr technical evaluation rept re environ qualification of Class IE electrical equipment, per NRC 821210 request.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/03/01
STOLZ, J. F. Operating Reactors Branch 4 2pp 17472:134 24X
Fiche: 50-289, 83/03/01, 8303090189.

8303160638 Forwards Amend 82 to License DPR-50 & notice of issuance & availability. Amend requires updated submittal of probability analysis 60 days following issuance of 1984 rept on aircraft movements at Harrisburg Intl Airport.
STOLZ, J. F. Operating Reactors Branch 4 83/03/01 HUKILL, H. D.
General Public Utilities - GPU Service Corp. 4pp 17600:331 24X
Fiche: 50-289, 83/03/01, 8303160638.

--8303160641 Amend 82 to License DPR-50, requiring updated aircraft probability analysis be submitted 60 days following issuance of 1984 rept on aircraft movement at Harrisburg Intl Airport.
STOLZ, J. F. Operating Reactors Branch 4 83/03/01 4pp
17600:335 24X Fiche: 50-289, 83/03/01, 8303160638.

--8303160644 Notice of issuance & availability of Amend 82 to License DPR-50.
STOLZ, J. F. Operating Reactors Branch 4 83/03/01 2pp.
17600:339 24X Fiche: 50-289, 83/03/01, 8303160638.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303070083 Forwards B&W "Evaluation of Small Break LOCA Operating Procedures & Effectiveness of Emergency Feedwater Spray for B&W Designed Operating NSSS." Svc list encl. Related correspondence.
BAXTER, T. A. Shaw, Pittman, Potts & Trowbridge BAXTER, T. A.
Metropolitan Edison Co. 83/03/03 EDLES, G. J.; BUCK, J. H.; GOTCHY, R. L. Atomic Safety and Licensing Appeal Panel 90pp
17435:044 24X Fiche: 50-289, 83/03/03, 8303070083.

8303090051 Forwards Accident Evaluation Branch review & evaluation of GPU 830202 request for relief from ASLB partial initial decision requiring new ESF filter sys at facility. Request should be denied for reasons stated.
MULLER, D. R. Assistant Director for Radiation Protection 83/03/03
LAINAS, G. Assistant Director for Operating Reactors 6pp
66675:020 24X Fiche: 50-289, 83/03/03, 8303090051.

8303100016 Notification of 830310 meeting w/util & consultants in Bethesda, MD to discuss RCS desulfurization program & steam generator review questions.
VAN VLIET, J. A. Operating Reactors Branch 4 83/03/03 STOLZ, J. F.
Operating Reactors Branch 4 2pp 17493:184 24X
Fiche: 50-289, 83/03/03, 8303100016.

8303100337 Forwards updated summaries of status of restart work items. Two items requiring NRC certification under 790809 order slipped to Apr due to technical difficulties encountered during mod completion.
ARNOLD, R. C. General Public Utilities - GPU Service Corp. 83/03/04
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp
17489:223 24X Fiche: 50-289, 83/03/04, 8303100337.

8303100494 Informs of NRC conclusions re LOFT Test L3-6 analysis of acceptability of ECCS evaluation model for predicting small break LOCAs & of criteria for resolution of TMI Action Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps."
EISENHUT, D. G. Division of Licensing 83/03/04 HUKILL, H. D.
General Public Utilities - GPU Service Corp. 17pp 17503:134 24X
Fiche: 50-289, 83/03/04, 8303100494.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303100127 Forwards info re pressurized thermal shock flux reduction. NRC in-depth review of B&W Owners Group programs will reveal acceptably low level of risk.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/03/07.
STOLZ, J. F. Operating Reactors Branch 4. 9pp. 17485:277. 24X.
Fiche: 50-289, 83/03/07, 8303100127.

8303110249 Forwards response to 830105 request for addl info re impact of Unit 2 water inleakage & water processing on Unit 1 storage capacity & justification that condensate storage tank not required for future water storage capacity.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/03/07.
STOLZ, J. F. Operating Reactors Branch 4. 2pp. 17520:063. 24X.
Fiche: 50-289, 83/03/07, 8303110249.

8303170136 Summary of 830223 meeting w/B&W Regulatory Response Group in Bethesda, MD re small break LOCA procedures & maintaining proper steam generator water level.
VAN VLIET, J. Operating Reactors Branch 4. 83/03/08. Operating Reactors Branch 4. 43pp. 17615:224. 24X. Fiche: 50-000, 83/03/08, 8303170136.

8303150265 Forwards Rev 0 to "Safety Evaluation of TMI-1 RCS Cleaning."
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/03/09.
EISENHUT, D. G. Division of Licensing. 1p. 17567:231. 24X.
Fiche: 50-289, 83/03/09, 8303150265.

--8303150272 Rev 0 to "Safety Evaluation of TMI-1 RCS Cleaning."
GRAHAM, M. J., GREENAWAY, W., THORPE, J. R. General Public Utilities - GPU Service Corp. TR-010 R00. 83/03/04. 28pp. 17567:232. 24X.
Fiche: 50-289, 83/03/09, 8303150265.

8303150677 Notification of 830318 meeting w/util & Commonwealth of PA in Bethesda, MD to discuss licensee proposed alternative to ventilation separation program (Phase II).
VAN VLIET, J. A. Operating Reactors Branch 4. 83/03/09. STOLZ, J. F. Operating Reactors Branch 4. 3pp. 17586:250. 24X.
Fiche: 50-289, 83/03/09, 8303150677.

8303160530 Forwards application for amend to License DPR-50, App A, requesting approval of Tech Spec Change Request 124 adding four new snubbers as result of restart piping mods or sys upgrade, in response to IE Bulletin 79-14.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/03/09.
STOLZ, J. F. Operating Reactors Branch 4. 1p. 17587:227. 24X.
Fiche: 50-289, 83/03/09, 8303160530.

--8303160537 Application for amend to License DPR-50, App A, provided by Tech Spec Change Request 124 adding four new snubbers as result of restart piping mods or sys upgrade, in response to IE Bulletin 79-14.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/03/09. 2pp. 17587:228. 24X. Fiche: 50-289, 83/03/09, 8303160530.

--8303160541 Proposed Tech Spec Change Request 124 adding four new snubbers as result of restart piping mods or sys upgrade, in response to IE Bulletin 79-14.
* General Public Utilities - GPU Service Corp. 83/03/09. 4pp. 17587:230. 24X. Fiche: 50-289, 83/03/09, 8303160530.

8303180559 Forwards NRR safety evaluation re review of TMI-1 Phase I ventilation separation test program. Satisfactory test program implemented.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/09. HUKILL, H. D. General Public Utilities - GPU Service Corp. 3pp. 17640:032. 24X.
Fiche: 50-289, 83/03/09, 8303180559.

--8303180563 Safety evaluation re review of TMI-1 Phase I ventilation separation test program. Satisfactory test program implemented.
* Operating Reactors Branch 4. 83/03/09. 2pp. 17640:035. 24X.
Fiche: 50-289, 83/03/09, 8303180559.

8303150316 Forwards "Inadequate Core Cooling Sys Evaluation for TMI-1," per NUREG-0737, Item II.F.2, in response to 821210 order for mod of license. Concurrence on RCS inventory trending sys conceptual design requested prior to 830515.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/03/10.
EISENHUT, D. G. Division of Licensing. 2pp. 17566:272. 24X.
Fiche: 50-289, 83/03/10, 8303150316.

--8303150327 "Inadequate Core Cooling Sys Evaluation for TMI-1." Evaluation includes RCS hot leg & reactor vessel head, reactor coolant pump motor current & NUREG-0737 evaluation of inadequate core cooling sys.
* General Public Utilities - GPU Service Corp. 83/03/10. 98pp. 17566:274. 24X. Fiche: 50-289, 83/03/10, 8303150316.

8303180592 Board Notification 83-34 forwards NRC 830304 ltr to util informing of NRC conclusions on LOFT Test L3-6, ECCS evaluation model for predicting small break LOCAs w/reactor coolant pump & criteria for resolving TMI Item II.K.3.5.
EISENHUT, D. G. Division of Licensing. 83/03/11. PALLADINO, N. J., GILINSKY, V., AHEARNE, J. Commissioners. 4pp. 17640:126. 24X.
Fiche: 50-289, 83/03/11, 8303180592.

8303210018 Board Notification 83-21A forwards memo providing NRC evaluation & conclusions re concerns previously identified in Board Notification 83-21 for TMI-1 only. Info does not adversely affect present conclusions re DHR.
EISENHUT, D. G. Division of Licensing. 83/03/11. PALLADINO, N. J., GILINSKY, V., AHEARNE, J. F. Commissioners. 4pp. 17660:073. 24X.
Fiche: 50-209, 83/03/11, 8303210018.

--8303210025 Provides followup evaluation of Board Notification BN-83-21 for TMI-1. Info does not adversely affect present conclusions re ability of TMI-1 to achieve & maintain DHR by natural circulation through steam generators.
MATTSON, R. J. Division of Systems Integration (post 811005). THOMPSON, H. Division of Human Factors Safety. 83/03/11.
EISENHUT, D. G. Division of Licensing. 17pp. 17660:077. 24X.
Fiche: 50-289, 83/03/11, 8303210018.

--8303210033 Provides explanation as to why pool boiling-condensation natural circulation in TMI-2 was not established due to erroneous steam generator secondary side water level setpoints.
SHERON, B. W. NRC Three Mile Island Task Force. 79/07/23.
ROSZTOCZY, Z. R. NRC Three Mile Island Task Force. 2pp. 17660:094. 24X. Fiche: 50-289, 83/03/11, 8303210018.

8303210165 Forwards Amend 83 to License DPR-50 & notice of issuance & availability. Amend deletes App B ETS re nonradiological water quality-related requirements.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/11. HUKILL, H. D. General Public Utilities - GPU Service Corp. 6pp. 17659:115. 24X.
Fiche: 50-289, 83/03/11, 8303210165.

--8303210184 Amend 83 to License DPR-50, deleting App B ETS re nonradiological water quality-related requirements.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/11. 3pp. 17659:121. 24X. Fiche: 50-289, 83/03/11, 8303210165.

--8303210191 Notice of issuance & availability of Amend 83 to License DPR-50.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/11. 2pp. 17659:124. 24X. Fiche: 50-289, 83/03/11, 8303210165.

8303210222 Notification of 830324 meeting w/util in Middletown, PA to discuss util plans & procedures re qualification of training instructors to resolve restart certification item.
VAN VLIET, J. A. Operating Reactors Branch 4. 83/03/15. STOLZ, J. F. Operating Reactors Branch 4. 3pp. 17659:112. 24X.
Fiche: 50-289, 83/03/15, 8303210222.

8303240099 Forwards request for addl info re qualification of instructors needed to complete review of TMI training manual Procedure 6210-ADM-1340.05, "Operator Training Instructor - Indoctrination/Qualification Training Program."
STOLZ, J. F. Operating Reactors Branch 4. 83/03/15. HUKILL, H. D. General Public Utilities - GPU Service Corp. 4pp. 17698:359. 24X.
Fiche: 50-289, 83/03/15, 8303240099.

8303300733 Summary of 830303 meeting w/utils, B&W Owners Group & Natl Nuclear Corp in Bethesda, MD re plans concerning frequency & severity of pressurized thermal shock events for B&W plants. Viewgraphs encl.
VISSING, G. S. Operating Reactors Branch 4. 83/03/15. Operating Reactors Branch 4. 174pp. 17765:013. 24X. Fiche: 50-000, 83/03/15, 8303300733.

8303300711 Board Notification 83-21B forwards ltr transmitting B&W regulatory response rept re emergency feedwater spray effectiveness & small break LOCA operating procedure.
EISENHUT, D. G. Division of Licensing. 83/03/16. PALLADINO, N. J., GILINSKY, V., AHEARNE, J. F. Commissioners. 2pp. 17764:275. 24X.
Fiche: 50-000, 83/03/16, 8303300711.

--8303300717 Forwards "Evaluation of Small Break LOCA Operating Procedures & Effectiveness of Emergency Feedwater Spray for B&W-Designed Operating NSSS."
CROUSE, R. P. Babcock & Wilcox Co. CROUSE, R. P. Toledo Edison Co. 83/03/07. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 17764:276. 24X. Fiche: 50-000, 83/03/16, 8303300711.

--8303300721 "Evaluation of Small Break LOCA Operating Procedures & Effectiveness of Emergency Feedwater Spray for B&W-Designed Operating NSSS."
* Babcock & Wilcox Co. 77-1141270-00. 83/02/28. 85pp. 17764:281. 24X. Fiche: 50-000, 83/03/16, 8303300711.

8303220314 Forwards Figures 1,2,3 & 4 inadvertently omitted from 830307 ltr re pressurized thermal shock flux reduction.
HUKILL,H.D. General Public Utilities - GPU Service Corp. 83/03/17.
STOLZ,J.F. Operating Reactors Branch 4. 5pp. 17655:359. 24X
Fiche: 50-289,83/03/17,8303220314.

8303300773 Board Notification 83-36 Forwards util 830218 ltr advising of util inability to install seismically qualified digital saturation meter required by restart safety evaluation; NUREG-0680. Util contends that such indicators do not exist.
EISENHUT,D.G. Division of Licensing. 83/03/17. PALLADINO,N.J.;
GILINSKY,V.; AHEARNE,J. Commissioners. 4pp. 17765:248. 24X
Fiche: 50-289,83/03/17,8303300773.

8303250169 Forwards suppl to 830204 response to Item 8 re emergency feedwater seismic qualification. Unit can be safely shut down following seismic event concurrent w/small break LOCA or loss of feedwater event.
HUKILL,H.D. General Public Utilities - GPU Service Corp. 83/03/22.
STOLZ,J.F. Operating Reactors Branch 4. 3pp. 17691:134. 24X
Fiche: 50-289,83/03/22,8303250169.

8303290082 Notification of 830325 meeting w/util & Commonwealth of PA in Bethesda,MD to discuss ventilation separation program (Phase II).
VAN VLIET,J.A. Operating Reactors Branch 4. 83/03/22. STOLZ,J.F.
Operating Reactors Branch 4. 1p. 17729:245. 24X
Fiche: 50-289,83/03/22,8303290082.

8303300608 Notification of 830405 meeting w/util in Bethesda,MD to discuss steam generator repair program. Topics include plugging & stabilizing,leak-before-break,operating guidelines & sulfur deposition on other RCS components.
VAN VLIET,J. Operating Reactors Branch 4. 83/03/23. STOLZ,J.
Operating Reactors Branch 4. 2pp. 17766:357. 24X
Fiche: 50-289,83/03/23,8303300608.

8303280101 Clarifies 821202 proposed change to licensed operator requalification program per NRC 830303 ltr. Exams given in Dec 1982 conform w/10CFR55,App A,Item 4. Change to wording of program Section 4.5.1.1 proposed. Section 4.2.1.1 encl.
HUKILL,H.D. General Public Utilities - GPU Service Corp. 83/03/24.
STOLZ,J.F. Operating Reactors Branch 4. 4pp. 17707:244. 24X
Fiche: 50-289,83/03/24,8303280101.

8303310551 Notification of 830407 meeting w/B&W Owners Group in Bethesda,MD to review progress,schedules & typical event analyses re study of pressurized thermal shock.
VISSING,G.S. Operating Reactors Branch 4. 83/03/25. STOLZ,J.F.
Operating Reactors Branch 4. 2pp. 17780:360. 24X
Fiche: 50-000,83/03/25,8303310551.

G. Inspection reports, IE Bulletins & correspondence

8303090110 Board Notification 83-20 Forwards 830210 memo providing results of review of licensee demonstration of RCS pressure control using HPI sys. Memo relates to natural circulation & feed & bleed modes of cooling.
EISENHUT,D.G. Division of Licensing. 83/02/18. PALLADINO,N.;
GILINSKY,V.; AHEARNE,J. Commissioners. 5pp. 17465:001. 24X
Fiche: 50-289,83/02/18,8303090110.

--8303090117 Forwards excerpt from IE Insp Rept 50-289/83-01 documenting results of site review re RCS pressure control testing. Info pertinent to reopened hearing on adequacy of reactor core cooling. Board notification recommended.
STAROSTECKI,R. Division of Project & Resident Programs. 83/02/10.
EISENHUT,D.G. Division of Licensing. 5pp. 17465:006. 24X
Fiche: 50-289,83/02/18,8303090110.

8303090105 Board Notification 83-09A Forwards R Starostecki 830209 ltr providing revised table for SALP rept. Table does not alter SALP rept nor affect findings of ASLAB.
EISENHUT,D.G. Division of Licensing. 83/02/23. PALLADINO,N.;
GILINSKY,V.; AHEARNE,J. Commissioners. 5pp. 17465:013. 24X
Fiche: 50-289,83/02/23,8303090105.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc.
111pp. 17521:001. 24X Fiche: 50-000,83/02/25,8212060367.

8303160461 Forwards IE Safeguards Insp Rept 50-289/83-03 on 830110-14. No noncompliance noted.
MARTIN,T.T. Division of Engineering & Technical Programs. 83/03/02.
HUKILL,H.D. General Public Utilities - GPU Service Corp. 2pp.
17592:308. 24X Fiche: 50-289,83/03/02,8303160461.

--8303160482 IE Safeguards Insp Rept 50-289/83-03 on 830110-14. No noncompliance noted. Major areas inspected: site orientation; security plan & implementing procedures & physical barriers. Safeguards info deleted (ref 10CFR73.21 or 10CFR9.5(a)(4)).
SMITH,G.; BAILEY,R.; KUSHNEV,W. Region 1, Office of Director.
83/02/24. 4pp. 17592:310. 24X Fiche: 50-289,83/03/02,8303160461.

8303140195 Board Notification 83-28 Forwards 830131 memo & rept re Aug 1979 Operator VV certification incident. IE investigating incident.
EISENHUT,D.G. Division of Licensing. 83/03/04. PALLADINO,N.J.;
GILINSKY,V.; AHEARNE,J. Commissioners. 4pp. 17548:262. 24X
Fiche: 50-289,83/03/04,8303140195.

8303160260 Responds to IE Bulletin 83-01 re failure of reactor trip breakers. No Westinghouse breakers used. Addl info to be provided at 830308 meeting w/NRC & B&W Regulatory Response Group.
HUKILL,H.D. General Public Utilities - GPU Service Corp. 83/03/07.
HAYNES,R.C. Region 1, Office of Director. 1p. 17596:341. 24X
Fiche: 50-289,83/03/07,8303160260.

8303160530 Forwards application for amend to License DPR-50, App A, requesting approval of Tech Spec Change Request 124 adding four new snubbers as result of restart piping mods or sys upgrade, in response to IE Bulletin 79-14.
HUKILL,H.D. General Public Utilities - GPU Service Corp. 83/03/09.
STOLZ,J.F. Operating Reactors Branch 4. 1p. 17587:227. 24X
Fiche: 50-289,83/03/09,8303160530.

--8303160537 Application for amend to License DPR-50, App A, provided by Tech Spec Change Request 124 adding four new snubbers as result of restart piping mods or sys upgrade, in response to IE Bulletin 79-14.
HUKILL,H.D. General Public Utilities - GPU Service Corp.
83/03/09. 2pp. 17587:228. 24X Fiche: 50-289,83/03/09,8303160530.

--8303160541 Proposed Tech Spec Change Request 124 adding four new snubbers as result of restart piping mods or sys upgrade, in response to IE Bulletin 79-14.
* General Public Utilities - GPU Service Corp. 83/03/09. 4pp.
17587:230. 24X Fiche: 50-289,83/03/09,8303160530.

8303240582 Forwards IE Insp Rept 50-289/83-02 on 830101-0204. No noncompliance noted.
MARTIN,T.T. Division of Engineering & Technical Programs. 83/03/10.
HUKILL,H.D. General Public Utilities - GPU Service Corp. 2pp.
17683:138. 24X Fiche: 50-289,83/03/10,8303240582.

--8303240591 IE Insp Rept 50-289/83-02 on 830101-0204. No noncompliance noted. Major areas inspected: licensee action on previous insp findings; steam generator tube kinetic expansion performance & preoperational & startup testing.
NICHOLAS,H.; GRAY,E.; RICHARDS,S. Region 1, Office of Director.
83/03/03. 18pp. 17683:140. 24X Fiche: 50-289,83/03/10,8303240582.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc.
117pp. 17611:070. 24X Fiche: 50-000,83/03/11,8212060380.

8303280181 Forwards IE Insp Rept 50-289/83-05 on 830131-0228 & notice of violation.
STAROSTECKI,R. Division of Project & Resident Programs. 83/03/14.
HUKILL,H.D. General Public Utilities - GPU Service Corp. 2pp.
17709:266. 24X Fiche: 50-289,83/03/14,8303280181.

--8303280184 Notice of violation from insp on 830131-0228.
* Region 1, Office of Director. 83/03/14. 1p. 17709:268. 24X
Fiche: 50-289,83/03/14,8303280181.

--8303280191 IE Insp Rept 50-289/83-05 on 830131-0228. Noncompliance noted: failure to meet license condition on inservice pump/valve testing.
CONTE,R.; YOUNG,F.; KEIMIG,R. Region 1, Office of Director.
83/03/10. 6pp. 17709:269. 24X Fiche: 50-289,83/03/14,8303280181.

8303220232 Forwards errata sheets to IE Insp Repts 50-289/82-17, 50-289/82-19 & 50-289/82-21 correcting several typographical errors.
STAROSTECKI,R. Division of Project & Resident Programs. 83/03/17.
HUKILL,H.D. General Public Utilities - GPU Service Corp. 2pp.
17656:290. 24X Fiche: 50-289,83/03/17,8303220232.

--8303220239 Errata sheet to IE Insp Rept 50-289/82-17.
* Region 1, Office of Director. 83/03/17. 1p. 17656:292. 24X
Fiche: 50-289,83/03/17,8303220232.

--8303220244 Errata sheet to IE Insp Rept 50-289/82-19.
* Region 1, Office of Director. 83/03/17. 1p. 17656:293. 24X
Fiche: 50-289,83/03/17,8303220232.

--8303220247 Errata sheet to IE Insp Rept 50-289/82-21.
* Region 1, Office of Director 83/03/17 1p 17656:294 24X
Fiche 50-289, 83/03/17, 8303220232

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/18 Consolidated Edison Co. of New
York, Inc. 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8303290242 Responds to IE Bulletin 83-01 re failure of reactor trip
breakers. IE Bulletin 83-01 requirements do not apply, since
Westinghouse DB breakers not used. Breakers tripped by
undervoltage device identified in IE Bulletin 79-09.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/03/18.
HAYNES, R. C. Region 1, Office of Director 2pp 17716:080 24X
Fiche 50-289, 83/03/18, 8303290242

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-
Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/21 Consolidated Edison Co. of New
York, Inc. 121pp 17774:352 24X Fiche 50-000, 83/03/21, 8212060387

8303250155 Forwards response to IE Bulletin 83-04 re failure of reactor
trip breakers to open during testing of undervoltage trip
function.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/03/22.
HAYNES, R. C. Region 1, Office of Director 2pp 17691:111 24X
Fiche 50-289, 83/03/22, 8303250155

R. Periodic operating reports & related correspondence

8303090085 Forwards "Aircraft Movements at Harrisburg Intl Airport,
1982."
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/02/28.
HAYNES, R. C. Region 1, Office of Director 1p 17469:338 24X
Fiche 50-289, 83/02/28, 8303090085

--8303090090 "Aircraft Movements at Harrisburg Intl Airport, 1982."
* General Public Utilities - GPU Service Corp. 83/02/28 3pp
17469:339 24X Fiche 50-289, 83/02/28, 8303090085.

8303140197 Forwards "Effluent & Waste Disposal Semiannual Rept,
Jul-Dec 1982," Rev 1 to "Process Control Program" & Rev 2
to "Offsite Dose Calculation Manual."
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/02/28.
HAYNES, R. C. Region 1, Office of Director 1p 17528:177 24X
Fiche 50-289, 83/02/28, 8303140197.

--8303140198 "Effluent & Waste Semiannual Rept, Jul-Dec 1982."
* General Public Utilities - GPU Service Corp. 83/02/28 17pp
17528:178 24X Fiche 50-289, 83/02/28, 8303140197.

--8303140202 Rev 1 to "Process Control Program."
* Hittman Nuclear & Development Corp. (subs. Hittman Corp.)
82/12/06 51pp 17528:195 24X Fiche 50-289, 83/02/28, 8303140197.

--8303140203 Rev 2 to "Offsite Dose Calculation Manual."
WILLIAMS, S. E. General Public Utilities - GPU Service Corp.
82/12/22 89pp 17528:246 24X Fiche 50-289, 83/02/28, 8303140197.

8303220030 Forwards monthly operating rept for Feb 1983.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/03/15.
MCDONALD, W. C. Office of Resource Management, Director 1p
17652:285 24X Fiche 50-289, 83/03/15, 8303220030.

--8303220033 Monthly operating rept for Feb 1983.
SMYTH, C. W. General Public Utilities - GPU Service Corp. 83/03/15
12pp 17652:286 24X Fiche 50-289, 83/03/15, 8303220030.

S. Reportable occurrences, LERs & related correspondence

8303140484 Forwards LER 83-002/03L-0.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/03/02.
HAYNES, R. C. Region 1, Office of Director 1p 17540:334 24X
Fiche 50-289, 83/03/02, 8303140484.

--8303140496 LER 83-002/03L-0 on 830201, 1A ES 480-volt motor control ctr
tripped, de-energizing associated circuits & rendering
radiation monitors RM-A4, A6 & A9 inoperable. Caused by
failure of conductor insulation in cable CG-2.
STEPHENSON, C. General Public Utilities - GPU Service Corp.
83/03/02 Region 1, Office of Director 3pp 17540:335 24X
Fiche 50-289, 83/03/02, 8303140484.

8303180422 Forwards LER 83-003/01T-0.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/03/07.
HAYNES, R. C. Region 1, Office of Director 1p 17622:069 24X
Fiche 50-289, 83/03/07, 8303180422.

--8303180426 LER 83-003/01T-0 on 830211, pilot valve disc found stuck open
& main valve stuck closed. PORV removed for special insp
to ensure that corrosion found in previously installed PORV
had not occurred.
STEPHENSON, C. General Public Utilities - GPU Service Corp.
83/03/07 Region 1, Office of Director 3pp 17622:070 24X
Fiche 50-289, 83/03/07, 8303180422.

T. Hearing transcripts on non-antitrust matters

8303150103 Transcript of 830303 affirmation/discussion & vote in
Washington, DC re UCS objection to NRC meeting on seismic
concerns as violating ex parte prohibition. Pp 1-3.
* Commissioners 83/03/03 7pp 17600:174 24X
Fiche 50-289, 83/03/03, 8303150103.

8303090173 Transcript of 830307 restart hearing in Bethesda, MD.
Pp 1-173. Supporting documentation encl.
* Atomic Safety and Licensing Appeal Panel 83/03/07 265pp
17469:073 24X Fiche 50-289, 83/03/07, 8303090173.

8303100211 Transcript of 830308 restart hearing in Bethesda, MD. Pp 174-
363. Supporting documentation encl.
* Atomic Safety and Licensing Appeal Panel 83/03/08 207pp
17491:001 24X Fiche 50-289, 83/03/08, 8303100211.

8303180171 Transcript of 830316 restart proceeding in Bethesda, MD.
Pp 364-545.
* Atomic Safety and Licensing Appeal Panel 83/03/16 213pp
17619:069 24X Fiche 50-289, 83/03/16, 8303180171.

8303210131 Transcript of 830317 restart hearing in Bethesda, MD. Pp 547-
791.
* Atomic Safety and Licensing Appeal Panel 83/03/17 245pp
17629:289 24X Fiche 50-289, 83/03/17, 8303210131.

8303290239 Transcript of 830317 affirmation/discussion & vote in
Washington, DC re SECY-83-74, review of ALAB-698. Pp 1-5.
* Commissioners 83/03/17 7pp 17727:207 24X
Fiche 50-289, 83/03/17, 8303290239.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees,
applicants for OL, holders of CPs & NSSS vendors re issuance
of NRC Form 398, "Personal Qualifications Statement -
Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated
Edison Co. of New York, Inc. 18pp 24X Fiche 50-000, 83/02/24,
8302250505.

8303100511 Acs receipt of 821202 ltr identifying changes to licensed
operator requalification program involving mod of exam
topics & reduction of exam categories for reactor operator &
senior reactor operator licenses. Response due in 60 days.
STOLZ, J. F. Operating Reactors Branch 4 83/03/03 HUKILL, H. D.
General Public Utilities - GPU Service Corp. 4pp 17521:316 24X
Fiche 50-289, 83/03/03, 8303100511.

8303140195 Board Notification 83-28 forwards 830131 memo & rept re Aug
1979 Operator VV certification incident. IE investigating
incident.
EISENHUT, D. G. Division of Licensing 83/03/04 PALLADINO, N. J.,
GILINSKY, V., AHEARNE, J. Commissioners 4pp 17548:262 24X
Fiche 50-289, 83/03/04, 8303140195.

8303180656 Board Notification 83-33: Forwards NRC 830303 ltr to util
informing of NRC conclusions re two util changes to licensed
operator requalification program. One change acceptable & one
change unacceptable.
EISENHUT, D. G. Division of Licensing 83/03/11 PALLADINO, N. J.,
GILINSKY, V., AHEARNE, J. Commissioners 4pp 17637:126 24X
Fiche 50-289, 83/03/11, 8303180656.

8303290701 Board Notification 83-28A informs that Board Notification
83-28 transmitted only portion of investigator rept on Aug
1979 Operator VV certification incident. Util to submit
entire rept to Commission, ASLAB & parties within 2 wks.
EISENHUT, D. G. Division of Licensing 83/03/16 PALLADINO, N. J.,
GILINSKY, V., AHEARNE, J. Commissioners 4pp 17730:352 24X
Fiche 50-289, 83/03/16, 8303290701.

8303280101 Clarifies 821202 proposed change to licensed operator
requalification program per NRC 830303 ltr. Exams given in
Dec 1982 conform w/10CFR55, App A, Item 4. Change to wording of
program Section 4.5.1.1 proposed. Section 4.2.1.1 encl.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/03/24.
STOLZ, J. F. Operating Reactors Branch 4 4pp 17707:244 24X
Fiche 50-289, 83/03/24, 8303280101.

8303300379 Comments on procedure for routine sampling & review of exam answers for evidence of cheating, per ASLB 830207 partial initial decision. Re-evaluation of procedure requested.
STOLZ, J. F. Operating Reactors Branch 4 83/03/25 HUKILL, H. D. General Public Utilities - GPU Service Corp. 3pp. 17754:283 24X Fiche: 50-289, 83/03/25, 8303300379.

DOCKET: 50-293 PILGRIM NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8303030181 Forwards IE Insp Rept 50-293/82-31 on 821213-16. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs 83/02/18
HARRINGTON, W. D. Boston Edison Co. 2pp. 17410:183 24X
Fiche: 50-293, 83/02/18, 8303030181.

--8303030185 IE Insp Rept 50-293/82-31 on 821213-16. No noncompliance noted. Major areas inspected: physical barriers, security sys power supply, lighting, assessment aids, access control, alarm stations, detection aids & communications.
MADDEN, W., DUNLAP, J., GODY, A. T. Region 1, Office of Director 83/02/16 4pp. 17410:185 24X Fiche: 50-293, 83/02/18, 8303030181.

8303110293 Forwards fee for 821215 application for Tech Spec changes re penetration fire barrier.
HOWARD, J. E. Boston Edison Co. 83/03/04 DIGGS, R. M. License Fee Management Branch 1p. 17515:352 24X Fiche: 50-293, 83/03/04, 8303110293.

8303150363 Ack receipt of 830204 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/82-29. Corrective actions withheld (ref 10CFR73.21).
STAROSTECKI, R. Division of Project & Resident Programs 83/03/08
HARRINGTON, W. D. Boston Edison Co. 3pp. 17562:358 24X
Fiche: 50-293, 83/03/08, 8303150363.

8303170316 Responds to NRC 830117 ltr re proposed design for alternate safe shutdown. Suppression pool temp & level indication will be provided as part of App R mod effort currently scheduled for completion by June 1987.
HARRINGTON, W. D. Boston Edison Co. 83/03/11 VASSALLO, D. B. Operating Reactors Branch 2 2pp. 17610:325 24X
Fiche: 50-293, 83/03/11, 8303170316.

8303170330 Requests NRC reconsider denial of exemption Requests 7, 8 & 10 from requirements of 10CFR50.48 & Section III of App R contained in util 820625 ltr.
HARRINGTON, W. D. Boston Edison Co. 83/03/11 EISENHUT, D. G. Division of Licensing 2pp. 17605:170 24X Fiche: 50-293, 83/03/11, 8303170330.

G. Adjudicatory correspondence

8303040448 Requests rept describing circumstances surrounding high TLD reading & subsequent evaluation within 30 days of ltr date. Request concerns notification of claim.
MARTIN, T. T. Division of Engineering & Technical Programs 83/02/15
HARRINGTON, W. D. Boston Edison Co. 2pp. 17374:022 24X
Fiche: 50-293, 83/02/15, 8303040448.

I. Financial information

8303100214 Annual Financial Rept 1982.
GALLIGAN, T. J. Boston Edison Co. 83/02/15 37pp. 17491:334 24X
Fiche: 50-293, 83/02/15, 8303100214.

J. Insurance & indemnity information

8303080198 Forwards Endorsements 74 & 75 to NELIA Policy NF-188 & Endorsements 59 & 60 to MAELU Policy MF-58.
SINISI, J. M. Marsh & McLennan, Inc. 83/02/28 SALTZMAN, J. Antitrust & Economic analysis Branch (Utility Finance) 5pp.
17457:300 24X Fiche: 50-293, 83/02/28, 8303080198.

8303140289 Forwards Endorsement 76 to NELIA Policy NF-188.
SINISI, J. M. Marsh & McLennan, Inc. 83/03/07 SALTZMAN, J. D. Assistant Director for State & Licensee Relations 2pp. 17535:058 24X Fiche: 50-293, 83/03/07, 8303140289.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 16pp. 17492:033 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303070115 Application for amend to License DPR-35, resulting from commitment made in response to IE Insp Rept 50-293/82-22.
HARRINGTON, W. D. Boston Edison Co. 83/02/25 VASSALLO, D. B. Operating Reactors Branch 2 1p. 17430:355 24X
Fiche: 50-293, 83/02/25, 8303070115.

--8303070121 Proposed Tech Spec adding new item to App A, Section 3.6.F, "Jet Pump Flow Mismatch."
* Boston Edison Co. 83/02/25 3pp. 17430:356 24X
Fiche: 50-293, 83/02/25, 8303070115.

8303040547 Forwards "Structural Analysis of Pilgrim Vessel Head Drop, Shroud Head Assembly Drop & Steam Dryer Assembly Drop Conditions." Rept redefining project scope of NUREG-0612 experience expected by 830715.
HARRINGTON, W. D. Boston Edison Co. 83/02/28 EISENHUT, D. G. Division of Licensing 2pp. 17424:128 24X Fiche: 50-293, 83/02/28, 8303040547.

--8303040555 "Structural Analysis of Pilgrim Vessel Head Drop, Shroud Head Assembly Drop & Steam Dryer Assembly Drop Conditions."
SKOGG, E. E., DELAURENTIS, L., RANGANATH, S. General Electric Co. 82/10/31 37pp. 17424:130 24X Fiche: 50-293, 83/02/28, 8303040547.

8303040548 Advises of discontinuation of annual aerial photographic survey to monitor structural integrity of main breakwater except under delineated circumstances. Aerial survey too expensive & gathers only redundant data.
HARRINGTON, W. D. Boston Edison Co. 83/02/28 VASSALLO, D. B. Operating Reactors Branch 2 2pp. 17374:154 24X
Fiche: 50-293, 83/02/28, 8303040548.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303150446 Mod to 821025 application for amend to License DPR-35, revising Tech Spec Figure 6.2.2 (P 210) & Section 6.5.A.5 (P 213) re organization & records, respectively. Functional responsibility of ALARA not designated under specific group.
HARRINGTON, W. D. Boston Edison Co. 83/03/02 VASSALLO, D. B. Operating Reactors Branch 2 2pp. 17561:062 24X
Fiche: 50-293, 83/03/02, 8303150446.

--8303150449 Proposed revised Tech Spec Figure 6.2.2 (P 210) & Section 6.5.A.5 (P 213) re organization & records, respectively. Discussion on responsibility & authority aspects of ALARA program encl.
* Boston Edison Co. 83/03/02 4pp. 17561:064 24X
Fiche: 50-293, 83/03/02, 8303150446.

8303090412 Requests remittance of Class III fee in payment for 821025 application for organizational changes at util.
DIGGS, R. M. License Fee Management Branch 83/03/03 MORISI, A. V. Boston Edison Co. 1p. 17484:091 24X Fiche: 50-293, 83/03/03, 8303090412.

8303110293 Forwards fee for 821215 application for Tech Spec changes re penetration fire barrier.
HOWARD, J. E. Boston Edison Co. 83/03/04 DIGGS, R. M. License Fee Management Branch 1p. 17515:352 24X Fiche: 50-293, 83/03/04, 8303110293.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303170380 Forwards addl info re NUREG-0737, Item II.D.1, "Relief & Safety Valve Test Requirements," in response to NRC 830104 ltr. Safety/relief valve discharge piping configurations utilizes tee quencher at pipe exit.
HARRINGTON, W. D. Boston Edison Co. 83/03/11 VASSALLO, D. B. Operating Reactors Branch 2 11pp. 17609:303 24X
Fiche: 50-293, 83/03/11, 8303170380.

8303290188 Forwards Amend 67 to License DPR-35 & notice of issuance & availability. Amend deletes App B ETS re nonradiological water quality-related requirements.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/11 MORISI, A. V. Boston Edison Co. 3pp. 17730:184 24X Fiche: 50-293, 83/03/11, 8303290188.

--8303290193 Amend 67 to License DPR-35 deleting App B ETS re nonradiological water quality-related requirements.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/11 3pp.
17730:187 24X Fiche 50-293, 83/03/11, 8303290188

--8303290201 Notice of issuance & availability of Amend 67 to License DPR-35.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/11 2pp.
17730:190 24X Fiche 50-293, 83/03/11, 8303290188

8303280107 Forwards order confirming licensee commitments on post-TMI-related issues. Order based on util commitments in responses to Generic Ltrs 82-05 & 82-10.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/14 MORISI, A. V.
Boston Edison Co 3pp 17713:341 24X Fiche 50-293, 83/03/14, 8303280107

--8303280115 Order confirming licensee commitments on post-TMI-related issues.
PURPLE, R. A. Division of Licensing 83/03/14 Boston Edison Co.
10pp 17713:344 24X Fiche 50-293, 83/03/14, 8303280107

8303290603 Forwards safety evaluation re NUREG-0737, Item II. K. 3. 13, "Separate HPCI & RCIC Initiation Levels," & mod of RCIC initiation logic causing RCIC restart on low reactor vessel water level. Initiation separation issue complete.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/16 MORISI, A. V.
Boston Edison Co 3pp 17744:268 24X Fiche 50-293, 83/03/16, 8303290603

--8303290607 Safety evaluation re BWR Owners Group generic response to separation of HPCI & RCIC sys initiation levels.
* NRC - No Detailed Affiliation Given 83/03/16 3pp.
17744:271 24X Fiche 50-293, 83/03/16, 8303290603

--8303290611 Safety evaluation re BWR Owners Group proposed change for RCIC sys automatic restart.
* NRC - No Detailed Affiliation Given 83/03/16 7pp.
17744:274 24X Fiche 50-293, 83/03/16, 8303290603

8303280242 Notifies that util has withdrawn request for hearing re environ qualification of safety-related electrical equipment.
GAD, R. K. Ropes & Gray 83/03/24 EISENHUT, D. G. Division of Licensing 1p 17709:305 24X Fiche 50-293, 83/03/24, 8303280242

Q. Inspection reports, IE Bulletins & correspondence

8303040513 Updates 821022 supplemental response to IE Insp Repts 50-293/82-04 & 50-293/82-19. Corrective actions, sketches associated w/Procedure 8.7.1.5 verified & valve checklists of affected sys will be updated. Status rept due by 830630.
HARRINGTON, W. D. Boston Edison Co. 83/02/17 STAROSTECKI, R.
Division of Project & Resident Programs 3pp 17374:211 24X
Fiche 50-293, 83/02/17, 8303040513

8303030181 Forwards IE Insp Rept 50-293/82-31 on 821213-16. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs 83/02/16
HARRINGTON, W. D. Boston Edison Co. 2pp 17410:183 24X
Fiche 50-293, 83/02/18, 8303030181

--8303030185 IE Insp Rept 50-293/82-31 on 821213-16. No noncompliance noted. Major areas inspected: physical barriers, security sys power supply, lighting, assessment aids, access control, alarm stations, detection aids & communications.
MADDEN, W., DUNLAP, J., GODY, A. T. Region 1, Office of Director
83/02/16 4pp. 17410:185 24X Fiche 50-293, 83/02/18, 8303030181

8303020314 Notification 83-11 of 830304 mgt meeting w/util in King of Prussia, PA to discuss licensee response to NRC order.
ELSASSER, T. Region 1, Office of Director 83/02/22 Region 1, Office of Director 1p 17355:283 24X Fiche 50-293, 83/02/22, 8303020314

8303100293 Forwards IE Insp Rept 50-293/83-02 on 830118-21. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs 83/02/23
HARRINGTON, W. D. Boston Edison Co. 2pp. 17490:305 24X
Fiche 50-293, 83/02/23, 8303100293

--8303100305 IE Insp Rept 50-293/83-02 on 830118-21. No noncompliance noted. Major areas inspected: implementation & status of NUREG-0737 items, including post-accident primary coolant & drywell atmosphere sampling.
WHITE, J. R., NIMITZ, R. L., SHANBAKY, M. M. Region 1, Office of Director 83/02/10 17pp 17490:307 24X Fiche 50-293, 83/02/23, 8303100293

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc.
111pp. 17521:001 24X Fiche 50-000, 83/02/25, 8212060367

8303070115 Application for amend to License DPR-35, resulting from comm.tment made in response to IE Insp Rept 50-293/82-22.
HARRINGTON, W. D. Boston Edison Co 83/02/25 VASSALLO, D. B.
Operating Reactors Branch 2 1p 17430:355 24X
Fiche 50-293, 83/02/25, 8303070115

--8303070121 Proposed Tech Spec adding new item to App A, Section 3.6.F, "Jet Pump Flow Mismatch."
* Boston Edison Co. 83/02/25 3pp. 17430:356 24X
Fiche 50-293, 83/02/25, 8303070115

8303140226 Responds to request for addl info re IE Bulletin 81-03 re results of chlorine minimization study for control of Mytilus edulis (blue mussel) per 830121 ltr. Orion chlorination & side-stream mussel monitors to be relocated.
HARRINGTON, W. D. Boston Edison Co 83/02/28 JORDAN, E. L. Region 1, Office of Director 3pp. 17538:225 24X Fiche 50-293, 83/02/28, 8303140226.

--8303140233 "Biofouling Control Studies at Pilgrim Nuclear Power Station, Apr 1981 - Apr 1982," final rept.
* Marine Research, Inc. 83/02/02 85pp. 17538:228 24X
Fiche 50-293, 83/02/28, 8303140226

8303150363 Ack receipt of 830204 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/82-29. Corrective actions withheld (ref 10CFR73.21).
STAROSTECKI, R. Division of Project & Resident Programs 83/03/08
HARRINGTON, W. D. Boston Edison Co. 3pp. 17562:358 24X
Fiche 50-293, 83/03/08, 8303150363.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc.
117pp. 17611:070 24X Fiche 50-000, 83/03/11, 8212060380.

8303300311 Forwards IE Insp Rept 50-293/83-01 on 830117-21. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs 83/03/16
HARRINGTON, W. D. Boston Edison Co. 2pp. 17754:288 24X
Fiche 50-293, 83/03/16, 8303300311.

--8303300323 IE Insp Rept 50-293/83-01 on 830117-21. No noncompliance noted. Major areas inspected: licensee action on previous insp findings & implementation of NUREG-0737, Item II.B.2, "Plant Shielding Design Review."
BRIGGS, L., EAPEN, P., HAVERKAMP, D. Region 1, Office of Director
83/02/22 8pp. 17734:290 24X Fiche 50-293, 83/03/16, 8303300311.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche 50-000, 83/03/16, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp. 17774:352 24X Fiche 50-000, 83/03/21, 8212060387

R. Periodic operating reports & related correspondence

8303080510 Forwards monthly operating rept for Dec 1982.
MATHIS, C. J. Boston Edison Co. 83/01/13 Office of Resource Management, Director 1p. 17455:001 24X Fiche 50-293, 83/01/13, 8303080510.

--8303080513 Monthly operating rept for Dec 1982.
WHITNEY, G. G. Boston Edison Co. 83/01/14 6pp. 17455:002 24X
Fiche 50-293, 83/01/13, 8303080510.

8303040401 Forwards "Personnel & Man-Rem Exposure by Work & Job Function," annual rept for 1982.
MATHIS, C. J. Boston Edison Co. 83/02/14 Region 1, Office of Director 1p. 17374:353 24X Fiche 50-293, 83/02/14, 8303040401.

--8303040408 "Personnel & Man-Rem Exposure by Work & Job Function," annual rept for 1982.
* Boston Edison Co. 83/02/14 3pp 17374:354 24X
Fiche 50-293, 83/02/14, 8303040401.

8303150575 Forwards monthly operating rept for Jan 1983.
MATHIS, C. J. Boston Edison Co. 83/02/14. Office of Resource Management, Director. 1p. 17568:329. 24X Fiche: 50-293, 83/02/14, 8303150575.

--8303150580 Monthly operating rept for Jan 1983.
WHITNEY, G. G. Boston Edison Co. 83/02/07. 6pp. 17568:330. 24X Fiche: 50-293, 83/02/14, 8303150575.

8303020103 Forwards "Pilgrim Nuclear Power Station 1982 Evaluation."
BRUNNER, E. J. Division of Project & Resident Programs. 83/02/22.
TAYLOR, J. M. Operating Reactors Program Branch. CASE, E. G. NRC - No Detailed Affiliation Given. 1p. 17349:009. 24X Fiche: 50-293, 83/02/22, 8303020103.

--8303020114 "Pilgrim Nuclear Power Station 1982 Evaluation."
* Institute of Nuclear Power Operations. 83/01/31. 62pp. 17349:010. 24X Fiche: 50-293, 83/02/22, 8303020103.

8303140226 Responds to request for addl info re IE Bulletin 81-03 re results of chlorine minimization study for control of Mytilus edulis (blue mussel) per 830121 ltr. Orion chlorination & side-stream mussel monitors to be relocated.
HARRINGTON, W. D. Boston Edison Co. 83/02/28. JORDAN, E. L. Region 1, Office of Director. 3pp. 17538:225. 24X Fiche: 50-293, 83/02/28, 8303140226.

--8303140233 "Biofouling Control Studies at Pilgrim Nuclear Power Station, Apr 1981 - Apr 1982." final rept.
* Marine Research, Inc. 83/02/02. 85pp. 17538:228. 24X Fiche: 50-293, 83/02/28, 8303140226.

8303290476 Forwards "Radioactive Effluent & Waste Disposal Rept. Including Radiological Impact on Humans, Jul-Dec 1982."
HOWARD, J. E. Boston Edison Co. 83/03/08. HAYNES, R. C. Region 1, Office of Director. 1p. 17724:235. 24X Fiche: 50-293, 83/03/08, 8303290476.

--8303290478 "Radioactive Effluent & Waste Disposal Rept, Including Radiological Impact on Humans, Jul-Dec 1982."
BOWMAN, C. E., SOWDON, T. L. Boston Edison Co. 83/03/01. 73pp. 17724:236. 24X Fiche: 50-293, 83/03/08, 8303290476.

B. Reportable occurrences, LERs & related correspondence

8303010658 LER 83-005/01X-0 on 830216, verification that plant had operated within Tech Spec required shutdown margin of 0.25% delta k w/rod 10-31 inoperable not obtainable. Cause under investigation.
WHITNEY, G. G. Boston Edison Co. 83/02/17. HAYNES, R. C. Region 1, Office of Director. 1p. 17336:257. 24X Fiche: 50-293, 83/02/17, 8303010658.

8303140392 Forwards LER 83-005/01T-0.
MATHIS, C. J. Boston Edison Co. 83/02/25. HAYNES, R. C. Region 1, Office of Director. 1p. 17534:021. 24X Fiche: 50-293, 83/02/25, 8303140392.

--8303140398 LER 83-005/01T-0 on 830216, determined that for period prior to 830211, plant operated w/o Tech Spec required shutdown margin w/control rod 10-31 inoperable. Meeting w/OE scheduled for 830301 to discuss cause & corrective action.
WHITNEY, G. G. Boston Edison Co. 83/02/25. Region 1, Office of Director. 1p. 17534:022. 24X Fiche: 50-293, 83/02/25, 8303140392.

8303180497 Forwards LER 83-006/03L-0.
MATHIS, C. J. Boston Edison Co. 83/03/04. HAYNES, R. C. Region 1, Office of Director. 1p. 17622:115. 24X Fiche: 50-293, 83/03/04, 8303180497.

--8303180504 LER 83-006/03L-0 on 830212, carbon samples from one bank of standby gas treatment sys A train indicated methyl iodine removal less than Tech Spec requirement. Probably caused by filter failure. Twelve filters replaced in bank.
WHITNEY, G. G. Boston Edison Co. 83/03/04. Region 1, Office of Director. 1p. 17622:116. 24X Fiche: 50-293, 83/03/04, 8303180497.

8303250068 Forwards LER 83-009/03L-0.
MATHIS, C. J. Boston Edison Co. 83/03/15. HAYNES, R. C. Region 1, Office of Director. 1p. 17693:271. 24X Fiche: 50-293, 83/03/15, 8303250068.

--8303250074 LER 83-009/03L-0 on 830215, during surveillance, belt driven fuel pump brkte on diesel generator A caused by normal wear. Belts replaced.
WHITNEY, G. G. Boston Edison Co. 83/03/15. Region 1, Office of Director. 1p. 17693:272. 24X Fiche: 50-293, 83/03/15, 8303250068.

8303250118 Forwards LER 83-008/03L-0.
MATHIS, C. J. Boston Edison Co. 83/03/16. HAYNES, R. C. Region 1, Office of Director. 1p. 17692:065. 24X Fiche: 50-293, 83/03/16, 8303250118.

--8303250121 LER 83-008/03L-0 on 830214, deviation from Tech Spec fire barrier requirements found during conversion of instrumentation & control lab to ofc space. Caused by failure to change existing conditions during retrofit.
WHITNEY, G. G. Boston Edison Co. 83/03/16. Region 1, Office of Director. 1p. 17692:061. 24X Fiche: 50-293, 83/03/16, 8303250118.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303040432 Responds to 830111 Generic Ltr 83-01, "Operator Licensing Exam Site Visit," identifying requests for site visits to conduct licensing exams to be submitted Jan 1983 - Dec 1985.
HARRINGTON, W. D. Boston Edison Co. 83/02/28. EISENHUT, D. G. Division of Licensing. 2pp. 17371:176. 24X Fiche: 50-293, 83/02/28, 8303040432.

DOCKET 50-294 MICHIGAN STATE UNIV. RESEARCH REACTOR

R. Periodic operating reports & related correspondence

8303150267 "Annual Operating Rept, 1982."
WILKINSON, B. W. Michigan State Univ. 83/03/08. Director's Office, Office of Inspection and Enforcement. 1p. 17568:319. 24X Fiche: 50-294, 83/03/08, 8303150267.

DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8303140270 Forwards IE Insp Rpts 50-295/83-01 & 50-304/83-01 on 830117-20. No noncompliance noted.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 83/02/11. REED, C. Commonwealth Edison Co. 3pp. 17543:351. 24X Fiche: 50-295, 83/02/11, 8303140270.

--8303140314 IE Insp Rpts 50-295/83-01 & 50-304/83-01 on 830117-20. No noncompliance noted. Major areas inspected: emergency preparedness exercise involving observations of key functions & locations during exercise.
PHILLIPS, M. P., PLOSKI, T. J., PATTERSON, J. P. Region 3, Office of Director. 83/02/09. 9pp. 17543:354. 24X Fiche: 50-295, 83/02/11, 8303140270.

8303010595 Ack receipt of 830124 ltr identifying 1983 dates for emergency preparedness exercises within State of IL. Dates determined to be within required exercise frequency.
HIND, J. A. Region 3, Office of Director. 83/02/24. JONES, E. E. Illinois, State of. 2pp. 17336:208. 24X Fiche: 50-000, 83/02/24, 8303010595.

--8303010618 Submits 1983 dates scheduled for emergency preparedness exercises for facilities within State of IL.
JONES, E. E. Illinois, State of. 83/01/24. KEPPLER, J. Region 3, Office of Director. 2pp. 17336:210. 24X Fiche: 50-000, 83/02/24, 8303010595.

8303040489 Forwards info re proposed installation mod of instrumentation to monitor source range neutron flux & cold leg temp at remote shutdown panel to complete util compliance w/App R to 10CFR50 re fire protection.
LENTINE, F. G. Commonwealth Edison Co. 83/02/25. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 17373:354. 24X Fiche: 50-295, 83/02/25, 8303040489.

8303140296 Ack receipt of 830210 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rpts 50-295/82-31 & 50-304/82-28.
MILLER, J. R. Region 3, Office of Director. 83/03/07. REED, C. Commonwealth Edison Co. 1p. 17535:043. 24X Fiche: 50-295, 83/03/07, 8303140296.

--8303140304 Responds to NRC 830111 ltr re violations noted in IE Safeguards Insp Rpts 50-295/82-31 & 50-304/82-28. Corrective actions withheld (ref 10CFR73.21).
FARRAR, D. L. Commonwealth Edison Co. 83/02/10. KEPPLER, J. G. Region 3, Office of Director. 1p. 17535:044. 24X Fiche: 50-295, 83/03/07, 8303140296.

8303230102 Forwards exemption from requirements of 10CFR50, App R, Item III.G.2 re cable trains & equipment necessary to achieve & maintain safe shutdown.
VARGA, S.A. Operating Reactors Branch 1 83/03/07 FARRAR, D.L. Commonwealth Edison Co 2pp 17687:129 24X Fiche: 50-295, 83/03/07, 8303230102.

--8303230107 Exemption from requirements of 10CFR50, App R, Item III.G.2 re equipment necessary to achieve & maintain safe shutdown.
EISENHUT, D.G. Division of Licensing 83/03/07 Commonwealth Edison Co 4pp 17687:131 24X Fiche: 50-295, 83/03/07, 8303230102.

--8303230111 Safety evaluation supporting exemption from requirements of 10CFR50, App R, Item III.G.2 re equipment necessary to achieve & maintain safe shutdown.
* Office of Nuclear Reactor Regulation, Director 83/03/07 22pp 17687:135 24X Fiche: 50-295, 83/03/07, 8303230102.

8303300248 Summarizes review of licensee 820416,0702 & 30 descriptions of safe shutdown in event of fire & proposed mods to meet App R to 10CFR50, Items III.G.3 & III.L Facility in compliance w/App R.
VARGA, S.A. Operating Reactors Branch 1 83/03/17 FARRAR, D.L. Commonwealth Edison Co 2pp 17751:358 24X Fiche: 50-295, 83/03/17, 8303300248.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition.Appropriate planning should take place to prevent possible transmission errors.
HIND, J.A. Region 3, Office of Director 83/03/22 Commonwealth Edison Co 2pp 17690:316 24X Fiche: 50-000, 83/03/22, 8303240440.

8303310124 Releases public version of revised emergency plan implemynting procedure.
FELTON, J.M. Division of Rules and Records 83/03/25 Document Management Branch 1p 17775:184 24X Fiche: 50-000, 83/03/25, 8303310124.

--8303310130 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure EG-1, "Coordination of Environs Group Activities by Environs Director."
* Commonwealth Edison Co 83/03/17 Director's Office, Office of Inspection and Enforcement 1p 17775:185 24X Fiche: 50-000, 83/03/25, 8303310124.

--8303310146 Public version of Rev 3 to Emergency Plan Implementing Procedure EG-1, "Coordination of Environs Group Activities by Environs Director."
FAJOWSKI, J.E. Commonwealth Edison Co 83/03/08 87pp 17775:186 24X Fiche: 50-000, 83/03/25, 8303310124.

8303300532 Releases public version of request for return of listed controlled copies of emergency plan.
FELTON, J.M. Division of Rules and Records 83/03/28 Document Management Branch 1p 17763:178 24X Fiche: 50-000, 83/03/28, 8303300532.

--8303300561 Submits public version of request for return of listed controlled copies of emergency plan.
FLESSNER, R.A. Commonwealth Edison Co 83/03/15 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p 17763:179 24X Fiche: 50-000, 83/03/28, 8303300532.

8303300718 Releases public version of rev 10 emergency plan implementing procedure.
FELTON, J.M. Division of Rules and Records 83/03/28 Document Management Branch 1p 17763:358 24X Fiche: 50-295, 83/03/28, 8303300718.

--8303300722 Public version of Rev 2 to Emergency Plan Implementing Procedure EPIP 1801-1, "Rad/Chem Director EPIP." Revised index encl.
* Commonwealth Edison Co 83/02/23 5pp 17763:360 24X Fiche: 50-295, 83/03/28, 8303300718.

8303310004 Releases public version of rev to emergency plan implementing procedure.
FELTON, J.M. Division of Rules and Records 83/03/28 Document Management Branch 1p 17777:355 24X Fiche: 50-295, 83/03/28, 8303310004.

--8303310005 Public version of Rev 2 to Emergency Plan Implementing Procedure EPIP 360-1, "Site Evacuation of Nonessential Personnel."
* Commonwealth Edison Co 83/02/23 4pp 17777:356 24X Fiche: 50-295, 83/03/28, 8303310004.

## G. Adjudicatory correspondence

8303150143 Forwards Director's Decision DD-83-4, denying 821011 petition to deny Comm Ed permission to use high burnup nuclear fuel & provide evidence to public re continued operation despite reactor vessel embrittlement.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director 83/03/01 QUIGG, C. Pollution & Environmental Problems, Inc 2pp 17585:001 24X Fiche: 50-295, 83/03/01, 8303150143.

--8303150153 Director's Decision DD-83-4 denying Pollution & Environ Problems, Inc 821011 petition to deny util use of high burnup fuel & provide evidence for continued safe operation despite reactor vessel embrittlement.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director 83/03/01 8pp 17585:003 24X Fiche: 50-295, 83/03/01, 8303150143.

--8303150161 Notice of issuance of Director's Decision DD-83-4 under 10CFR2.206 denying Pollution & Environ Problems, Inc 821011 petition.
CASE, E.G. Office of Nuclear Reactor Regulation, Director 83/03/01 4pp 17585:011 24X Fiche: 50-295, 83/03/01, 8303150143.

--8211190015 Discusses ACRS 821014 comments re NRC 820913 draft evaluation of pressurized thermal shock.Addl comments by D Okrent will be considered in preparation of SECY paper.
DIRCKS, W.J. Office of the Executive Director for Operations 82/11/12 SHEWMON, P.S. ACRS - Advisory Committee on Reactor Safeguards 12pp 17585:055 24X Fiche: 50-295, 83/03/01, 8303150143.

--8303150203 "NRC Staff Evaluation of Pressurized Thermal Shock."
* NRC - No Detailed Affiliation Given 82/11/30 453pp 17585:067 24X Fiche: 50-295, 83/03/01, 8303150143.

--8303150223 Forwards Pollution & Environ Problems, Inc 821011 petition seeking denial of Comm Ed request to use high burnup nuclear fuel & requesting NRC provide evidence to public that reactors are able to withstand embrittlement.
LIEBERMAN, J. Regional Operations & Enforcement Division 82/11/05 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 5pp 17586:160 24X Fiche: 50-295, 83/03/01, 8303150143.

8303300362 Advises that time for Commission to review Director's Decision DD-83-4 expired.Commission declined review. Decision became final agency action on 830328.
CHILK, S.J. Office of the Secretary of the Commission 83/03/29 QUIGG, C. Pollution & Environmental Problems, Inc 1p 17734:194 24X Fiche: 50-295, 83/03/29, 8303300362.

## H. General correspondence

8303030528 Informs that DL Farrar has replaced LD DelGeorge as Director of Nuclear Licensing for util.Rev of current NRC distribution list requested.
FARRAR, D.L. Commonwealth Edison Co 83/02/02 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p 17409:048 24X Fiche: 50-000, 83/02/02, 8303030528.

## I. Financial information

8303070135 Forwards Annual Financial Rept 1982.
BRESEMANN, R.W. Commonwealth Edison Co 83/02/28 Division of Licensing 1p 17433:001 24X Fiche: 50-000, 83/02/28, 8303070135.

--8303070151 Annual Financial Rept 1982.
O'CONNOR, J.J. Commonwealth Edison Co 83/02/03 13pp 17433:002 24X Fiche: 50-000, 83/02/28, 8303070135.

## J. Insurance & indemnity information

8303160578 Forwards Endorsements 143, 75, 62 & 24 to NELIA Policies NF-43, NF-187, NF-201 & NF-253, respectively.
OSTER, J. Commonwealth Edison Co 83/03/09 SALTZMAN, J. Assistant Director for State & Licensee Relations 5pp 17507:017 24X Fiche: 50-000, 83/03/09, 8303160578.

## P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982.Section 302 requires owners & generators to contract w/DOE for waste disposal.Svc list encl.
EISENHUT, D.G. Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 19pp 17492:033 24X Fiche: 50-000, 83/02/16, 8302170082.

8303090285 Requests assessment of operability of large diameter Pratt purge & vent valves & intentions on maintaining purge & vent valves sealed closed per SRP Section 6.2.4 & II.6.f within 15 days Background info encl.
VARGA,S.A. Operating Reactors Branch 1 83/02/16 FARRAR,D.L.
Commonwealth Edison Co. 5pp. 17484:298 24X Fiche:50-295,83/02/16,8303090285

8303110002 Forwards Amends 81 & 71 to Licenses DPR-39 & DPR-48, respectively, safety evaluation & notice of issuance & availability. Amends change designation numbers for reactor coolant pump undervoltage devices.
NORRIS,J. Operating Reactors Branch 1 83/02/25 FARRAR,D.L.
Commonwealth Edison Co. 2pp. 17546:276 24X Fiche:50-295,83/02/25,8303110002

--8303110003 Amends 81 & 71 to Licenses DPR-39 & DPR-48, respectively, revising Tech Specs to change designation numbers for reactor coolant pump undervoltage devices & reduce frequency of channel functional testing.
VARGA,S.A. Operating Reactors Branch 1 83/02/25 11pp.
17546:278 24X Fiche:50-295,83/02/25,8303110002

--8303110012 Safety evaluation supporting Amends 81 & 71 to Licenses DPR-39 & DPR-48, respectively.
* Office of Nuclear Reactor Regulation, Director 83/02/25 2pp.
17546:289 24X Fiche:50-295,83/02/25,8303110002

--8303110019 Notice of issuance & availability of Amends 81 & 71 to Licenses DPR-39 & DPR-48, respectively.
VARGA,S.A. Operating Reactors Branch 1 83/02/25 2pp.
17546:291 24X Fiche:50-295,83/02/25,8303110002

8303020021 Generic Ltr 83-13 to all applicants for OLs & holders of OPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT,D.G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700:303 24X
Fiche:50-000,83/03/02,8303023021

8303080328 Submits addl info in response to NRC concerns re operability of large diameter Pratt butterfly valves. Util does not intend to maintain valves closed in modes other than cold shutdown & refueling.
LENTINE,F.G. Commonwealth Edison Co. 83/03/03 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 3pp. 17447:350 24X
Fiche:50-295,83/03/03,8303080328

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER,J.G. Region 3, Office of Director 83/03/03
Commonwealth Edison Co. 2pp. 17492:014 24X Fiche:50-000,83/03/03,8303100364

8303100348 Suppls 830114 ltr providing justification for continued operation per SER on environ qualification of electrical equipment. Discussion of addl post-accident monitoring requirements for transmitters encl.
LENTINE,F.G. Commonwealth Edison Co. 83/03/04 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 3pp. 17488:348 24X
Fiche:50-295,83/03/04,8303100348

8303100507 Requests remittance of fee for 801107 Tech Spec change request re DHR capability, per 10CFR170.22. Fee due within 15 days of ltr receipt.
MILLER,W.O. License Fee Management Branch 83/03/04
DELGEORGE,L.O. Commonwealth Edison Co. 1p. 17521:328 24X
Fiche:50-295,83/03/04,8303100507

8303110246 Forwards Rev 23 to CE-1-A, "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments.
SWARTZ,E.D. Commonwealth Edison Co. 83/03/04 HAASS,W.P. Quality Assurance Branch 1p. 17515:357 24X Fiche:50-000,83/03/04,8303110246

--8303110279 Rev 23 to "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments.
SHEWSKI,W.J. Commonwealth Edison Co. CE-1-A R23 83/03/07 5pp.
17515:358 24X Fiche:50-000,83/03/04,8303110246

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT,D.G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp. 17660:176 24X
Fiche:50-000,83/03/07,8303040005

8303170125 Summary of 830228 meeting w/licensee re PWR neutronic methodology program proposed for use in fuel reload reviews. Approval requested to perform neutronics calculations in-house & for Westinghouse to continue accident analyses.
WIGGINTON,D.L. Operating Reactors Branch 1 83/03/07 Operating Reactors Branch 1 42pp. 17615:290 24X Fiche:50-295,83/03/07,8303170125

8303220081 Forwards response to Generic Ltr 82-28, "Inadequate Core Cooling Instrumentation Sys," per 10CFR50.54(f).
LENTINE,F.G. Commonwealth Edison Co. 83/03/10 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 46pp. 17652:214 24X
Fiche:50-295,83/03/10,8303220081

8303290836 Advises that Tech Specs should be changed to reflect manual initiated operating bypass of protection sys channels. Tech Specs should explicity identify conditions where operating bypasses will block ESF channels.
VARGA,S.A. Operating Reactors Branch 1 83/03/11 FARRAR,D.L.
Commonwealth Edison Co. 4pp. 17748:045 24X Fiche:50-295,83/03/11,8303290836

8303210325 Responds to NRC 830204 request for addl info re control room review. Response specifically answers discrepancies re defeat of nuisance alarms; prioritization of multiple alarms & communications w/breathing apparatus.
STIEDE,W.L. Commonwealth Edison Co. 83/03/15 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 5pp. 17632:123 24X
Fiche:50-295,83/03/15,8303210325

8303220256 Advises that util will not provide 90-day response to NRC 821214 ltr Requirement to identify equipment already qualified & to submit plans & schedules for qualification or replacement of remaining equipment will be fulfilled 830520.
LENTINE,F.G. Commonwealth Edison Co. 83/03/17 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 1p. 17656:278 24X
Fiche:50-295,83/03/17,8303220256

8303300165 Forwards complete copy of encls to 830208 ltr requesting addl info on NUREG-0737, Items II.F.1.4, "Containment Pressure Monitor," II.F.1.5, "Containment Water Level Monitor" & II.F.1.6, "Containment Hydrogen Monitor."
VARGA,S.A. Operating Reactors Branch 1 83/03/17 FARRAR,D.L.
Commonwealth Edison Co. 10pp. 17763:105 24X Fiche:50-295,83/03/17,8303300165

8303240319 Responds to NRC 830311 ltr requesting rev to Tech Spec re blocking of safety injection signals during cooldown. Third page of Table 3.4.1 contains necessary provisions. Rev to Tech Specs not required.
LENTINE,F.G. Commonwealth Edison Co. 83/03/18 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 2pp. 17679:302 24X
Fiche:50-295,83/03/18,8303240319

8303260062 Requests itemized bill of actual fees paid for review of proposed Amends 65 & 62. Review of application should be administrative or pro forma in nature since model Tech Specs adopted. Addl fees unjustified.
LENTINE,F.G. Commonwealth Edison Co. 83/03/18 MILLER,W.O.
License Fee Management Branch 4pp. 17707:278 24X
Fiche:50-295,83/03/18,8303260062

8303290033 Requests util incorporate responses to NRC QA Questions 1 through 51 & staff positions in Topical Rept CE-1-A, "QA Program." Util alternate approach to Staff Position A acceptable.
VARGA,S.A. Operating Reactors Branch 1 83/03/21 FARRAR,D.L.
Commonwealth Edison Co. 3pp. 17729:294 24X Fiche:50-295,83/03/21,8303290033

8303280112 Forwards SER re NUREG-0737, Item II.B.2.2, "Design Review of Plant Shielding-Access to Vital Areas."
NORELIUS,C.E. Division of Project & Resident Programs 83/03/24
EISENHUT,D.G. Division of Licensing 3pp. 17709:340 24X
Fiche:50-295,83/03/24,8303280112

8303280270 Requests that petition for hearing on environ qualification of safety-related electrical equipment be withdrawn based on listed interpretations. Significant improvements in final rule 10CFR50.49 obviate hearings.
STEPTOE,P.P. Isham, Lincoln & Beale STEPTOE,P.P. Commonwealth Edison Co. 83/03/24 EISENHUT,D.G. Division of Licensing 2pp.
17706:289 24X Fiche:50-000,83/03/24,8303280270

8303290526 Provides schedule for resolution of TMI Action Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps," in response to Generic Ltrs 83-10c & 83-10d. Info will be provided by 830423 based on Westinghouse Owners Group input.
SWARTZ,E.D. Commonwealth Edison Co. 83/03/24 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 2pp. 17724:161 24X
Fiche:50-000,83/03/24,8303290526

Q Inspection reports, IE Bulletins & correspondence

8303170501 Forwards IE Insp Repts 50-295/82-28 & 50-304/82-25 on 821202-830117 No noncompliance noted
STREETER, J F Division of Project & Resident Programs 83/02/09
REED, C Commonwealth Edison Co 2pp 17610 219 24X
Fiche 50-295, 83/02/09, 8303170501

--8303170506 IE Insp Repts 50-295/82-28 & 50-304/82-25 on 821202-830117 No noncompliance noted Major areas inspected previous insp items, unit startup w/penetration pressurization air compressor out of svc & spent fuel shipment
WATERS, J R , DUNAWAY, F R , HARTMAN, P L Region 3, Office of Director 83/02/07 14pp 17610 221 24X Fiche 50-295, 83/02/09, 8303170501

8303140270 Forwards IE Insp Repts 50-295/83-01 & 50-304/83-01 on 830117-20 No noncompliance noted
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/11 REED, C Commonwealth Edison Co 3pp 17543 351 24X Fiche 50-295, 83/02/11, 8303140270

--8303140314 IE Insp Repts 50-295/83-01 & 50-304/83-01 on 830117-20 No noncompliance noted Major areas inspected emergency preparedness exercise involving observations of key functions & locations during exercise
PHILLIPS, M P , PLOSKI, T J , PATTERSON, J P Region 3, Office of Director 83/02/09 9pp 17543 354 24X Fiche 50-295, 83/02/11, 8303140270

8303040566 Forwards IE Insp Repts 50-295/82-24 & 50-304/82-21 on 820920-22 & 1214-16 No noncompliance noted
LITTLE, W S Division of Engineering 83/02/15 REED, C Commonwealth Edison Co 2pp 17374 168 24X Fiche 50-295, 83/02/15, 8303040566

--8303040574 IE Insp Repts 50-295/82-24 & 50-304/82-21 on 820920-22 & 1214-16 No noncompliance noted Major areas inspected allegations re improper stress relieving of steam generators & unnecessary personnel exposure to radiation
KEY, W J , MILLER, D P Region 3, Office of Director
DANIELSON, D H Division of Engineering 83/02/15 6pp 17374 170 24X Fiche 50-295, 83/02/15, 8303040566

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 111sp 17571 001 24X Fiche 50-000, 83/02/25, 8212060367

8302280356 Ack receipt of 830216 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/82-20 & 50-304/82-18
SPESSARD, R L Division of Engineering 83/02/25 REED, C Commonwealth Edison Co 1p 17311 080 24X Fiche 50-295, 83/02/25, 8302280356

--8302280361 Responds to NRC 830114 ltr re violations noted in IE Insp Repts 50-295/82-20 & 50-304/82-18 Failure to perform required surveillance isolated incident Existing procedural controls adequate
FARRAR, D L Commonwealth Edison Co 83/02/16 KEPPLER, J G Region 3, Office of Director 2pp 17311 083 24X
Fiche 50-295, 83/02/25, 8302280356

8303170532 Forwards IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al, on 830126 No noncompliance noted
DAVIS, A B Region 3, Office of Director 83/02/25 REED, C Commonwealth Edison Co 2pp 17610 143 24X Fiche 50-000, 83/02/25, 8303170532

--8303170557 IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al, on 830126 No noncompliance noted Major areas discussed proposed guidelines util personnel should use for providing info to Region III inspectors
GULDEMOND, W G Division of Project & Resident Programs 83/02/15 4pp 17610 145 24X Fiche 50-000, 83/02/25, 8303170532

8303030438 Clarifies NRC position re procedures for admitting NRC personnel to facilities Lists of NRC inspectors & personnel likely to visit facility two or more times per yr & at anytime encl Lists will be updated every 6 months
KEPPLER, J G Region 3, Office of Director 83/02/28 REED, C Commonwealth Edison Co 6pp 17410 101 24X Fiche 50-295, 83/02/28, 8303030438

8303080184 Forwards corrected second page to 830209 ltr transmitting IE Insp Repts 50-295/82-28 & 50-304/82-25 Rept numbers incorrectly stated Incorrect page should be removed
STREETER, J F Division of Project & Resident Programs 83/03/02
REED, C Commonwealth Edison Co 2pp 17457 341 24X
Fiche 50-295, 83/03/02, 8303080184

8303070036 Forwards responses to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Bunker-Ramo electrical penetrations installed in LaSalle Unit 2, Byron Unit 2 & Braidwood Unit 2
SWARTZ, E D Commonwealth Edison Co 83/03/03 KEPPLER, J G Region 3, Office of Director 13pp 17435 290 24X Fiche 50-000, 83/03/03, 8303070036

8303110284 Responds to IE Bulletin 83-01 re failure of reactor trip breakers Surveillance test of undervoltage trip performed on Unit 1 on 830225 All licensed operators being notified of Salem event during shift meeting
LENTINE, F G Commonwealth Edison Co 83/03/07 KEPPLER, J G Region 3, Office of Director 3pp 17517 347 24X
Fiche 50-295, 83/03/07, 8303110284

8303140296 Ack receipt of 830210 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-295/82-31 & 50-304/82-28
MILLER, J R Region 3, Office of Director 83/03/07 REED, C Commonwealth Edison Co 1p 17535 043 24X Fiche 50-295, 83/03/07, 8303140296

--8303140304 Responds to NRC 830111 ltr re violations noted in IE Safeguards Insp Repts 50-295/82-31 & 50-304/82-28 Corrective actions withheld (ref 10CFR73 21)
FARRAR, D L Commonwealth Edison Co 83/02/10 KEPPLER, J G Region 3, Office of Director 1p 17535 044 24X
Fiche 50-295, 83/03/07, 8303140296

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc 117pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 121pp 17774 352 24X Fiche 50-000, 83/03/21, 8212060387

8303310211 Forwards addl info in response to IE Bulletin 81-03 re methods to control Corbicula "Environ Studies of Braidwood Cooling Pond, 1982," encl
SWARTZ, E D Commonwealth Edison Co 83/03/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 17pp 17755 095 24X
Fiche 50-000, 83/03/28, 8303310211

R Periodic operating reports & related correspondence

8303280293 Forwards Part 1 of "Radioactive Effluent Monitoring Rept, Jan-June 1982."
GRAESSER, K L Commonwealth Edison Co 82/08/15 KEPPLER, J G Region 3, Office of Director 1p 17705 271 24X
Fiche 50-295, 82/08/15, 8303280293

--8303280299 Part 1 of "Radioactive Effluent Monitoring Rept Jan-June 1982."
Commonwealth Edison Co 82/08/15 49pp 17705 272 24X
Fiche 50-295, 82/08/15, 8303280293

8303150349 Forwards monthly operating repts for Feb 1983
GRAESSER, K L Commonwealth Edison Co 83/03/07 Director's Office, Office of Inspection and Enforcement 1p 17563 004 24X
Fiche 50-295, 83/03/07, 8303150349

--8303150354 Monthly operating repts for Feb 1983
AUSTIN, G Commonwealth Edison Co 83/03/07 11pp 17563 005
24X Fiche 50-295, 83/03/07, 8303150349

S Reportable occurrences, LERs & related correspondence

8303010662 Forwards LER 83-003/03L-0
GRAESSER, K L Commonwealth Edison Co 83/02/22 KEPPLER, J G Region 3, Office of Director 1p 17336 142 24X
Fiche 50-295, 83/02/22, 8303010662

--8303010671 LER 83-003/03L-0 on 830124, during normal operation, condenser air ejector gas monitor 1RE-0015 showed intermittent spiking to failed low position Caused by moisture in detector chamber Chamber cleaned Detector tube replaced
AKER, R E Commonwealth Edison Co 83/02/22 Region 3, Office of Director 1p 17336 143 24X Fiche 50-295, 83/02/22, 8303010662

8303140460 Forwards LER 83-006/03L-0.
GRAESSER, K. L. Commonwealth Edison Co. 83/03/04. KEPPLER, J. G.
Region 3, Office of Director. 1p. 17541:174. 24X
Fiche: 50-295, 83/03/04, 8303140460.

--8303140470 LER 83-006/03L-0: on 830202 & 22, at 80% power, steam generator 1A differential pressure bistable 1PC-516C tripped & reset. Caused by out-of-tolerance high condition in comparator 1PC-516 CD Comparator replaced.
CANTWELL, P. F. Commonwealth Edison Co. 83/03/04. Region 3, Office of Director. 1p. 17541:175. 24X Fiche: 50-295, 83/03/04, 8303140460.

8303140342 Forwards LER 83-007/03L-0.
GRAESSER, K. L. Commonwealth Edison Co. 83/03/08. KEPPLER, J. G.
Region 3, Office of Director. 1p. 17534:231. 24X
Fiche: 50-295, 83/03/06, 8303140342.

--8303140360 LER 83-007/03L-0: on 830211, steam generator 1A 100-1b steam line differential pressure bistable 1PC-515A found flashing intermittently. Caused by steam leak impingement on transmitter. Leak repaired.
CANTWELL, P. F. Commonwealth Edison Co. 83/03/08. Region 3, Office of Director. 1p. 17534:232. 24X Fiche: 50-295, 83/03/08, 8303140342.

8303140350 Forwards LER 83-008/03L-0.
GRAESSER, K. L. Commonwealth Edison Co. 83/03/08. KEPPLER, J. G.
Region 3, Office of Director. 1p. 17544:025. 24X
Fiche: 50-295, 83/03/08, 8303140350.

--8303140355 LER 83-008/03L-0: on 830208, during steady-state operation, steam generator 1C feedwater flow channel failed high. Caused by broken mounting for ferrite disk & coil transmitter 1FT-520. Transmitter replaced.
CANTWELL, P. F. Commonwealth Edison Co. 83/03/08. Region 3, Office of Director. 1p. 17544:026. 24X Fiche: 50-295, 83/03/08, 8303140350.

8303170497 Forwards updated LER 83-002/99X-1.
GRAESSER, K. L. Commonwealth Edison Co. 83/03/10. KEPPLER, J. G.
Region 3, Office of Director. 1p. 17610:321. 24X
Fiche: 50-295, 83/03/10, 8303170497.

--8303170502 Updated LER 83-002/99X-1 has been canceled.
SCHULTZ, C. Commonwealth Edison Co. 83/03/10. Region 3, Office of Director. 1p. 17610:322. 24X Fiche: 50-295, 83/03/10, 8303170497.

8303220235 ONO-III-83-018 on 830228, contractor employee gained unauthorized entry to protected & vital plant areas. Two contractor employees terminated for violating security requirements & security guard for failure to take action.
CREED, J., MILLER, J. Region 3, Office of Director. 83/03/16. 1p. 17656:260. 24X Fiche: 50-295, 83/03/16, 8303220235.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303040631 Forwards listing of projected operator licensing exam dates including type of exam & probable number of candidates, in response to 830111 Generic Ltr 83-01.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/01. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 17367:209. 24X
Fiche: 50-000, 83/03/01, 8303040631.

DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

8303010293 Responds to NRC 820727 ltr re violations noted in IE Insp Repts 50-259/82-20, 50-260/82-20 & 50-296/82-20. Corrective actions security program audit will be performed by 830130.
MILLS, L. M. Tennessee Valley Authority. 82/12/28. O'REILLY, J. P. Region 2, Office of Director. 1p. 17334:086. 24X
Fiche: 50-259, 82/12/28, 8301010293.

8303210756 Ack receipt of 830222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-46, 50-260/82-46 & 50-296/82-46.
LEWIS, R. C. Division of Project & Resident Programs. 83/03/02.
PARRIS, H. G. Tennessee Valley Authority. 1p. 17635:044. 24X
Fiche: 50-259, 83/03/02, 8303210756.

--8303210775 IE Insp Repts 50-259/82-46, 50-260/82-46 & 50-296/82-46 on 821129-1225. Noncompliance noted: failure to have control room emergency pressurization sys operable & to perform maint per plant instructions.
PAULK, G. L. Region 2, Office of Director. 83/01/18. 8pp. 17635:054. 24X Fiche: 50-259, 83/03/02, 8303210756.

8303250092 Confirms understanding of App R evaluation criteria re availability of offsite power, manual operator actions & unit trip, per NRC 830318 telcon.
MILLS, L. M. Tennessee Valley Authority. 83/03/22. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17693:073. 24X Fiche: 50-259, 83/03/22, 8303250092.

G. Adjudicatory correspondence

8303110228 Advises that time for Commission to review ALAB-711 expired. Commission declined review. Decision became final agency action on 830302.
CHILK, S. J. Office of the Secretary of the Commission. 83/03/10. Tennessee Valley Authority. 1p. 17518:357. 24X
Fiche: 50-259, 83/03/10, 8303110228.

J. Insurance & indemnity information

8303290341 Forwards Endorsement 64 to NELIA Policy NF-198.
DUCK, J. R. Marsh & McLennan, Inc. 83/03/15. SALTZMAN, J. Assistant Director for State & Licensee Relations. 2pp. 17716:255. 24X
Fiche: 50-259, 83/03/15, 8303290341.

P. Operating license stage documents & correspondence

8303030063 Forwards Amends 86, 83 & 57 to Licenses DPR-33, DPR-52 & DPR-68, respectively, safety evaluation & notice of issuance & availability. Amends change Tech Specs by reducing duration of leak rate tests.
VASSALLO, D. B. Operating Reactors Branch 2. 83/02/14. PARRIS, H. G. Tennessee Valley Authority. 2pp. 17365:305. 24X
Fiche: 50-259, 83/02/14, 8303030063.

--8303030068 Amends 86, 83 & 57 to Licenses DPR-33, DPR-52 & DPR-68, respectively, changing Tech Specs by reducing duration of leak rate tests.
VASSALLO, D. B. Operating Reactors Branch 2. 83/02/14. 38pp. 17365:307. 24X Fiche: 50-259, 83/02/14, 8303030063.

--8303030075 Safety evaluation supporting Amends 86, 83 & 57 to Licenses DPR-33, DPR-52 & DPR-68, respectively.
* Office of Nuclear Reactor Regulation, Director. 83/02/14. 3pp. 17365:345. 24X Fiche: 50-259, 83/02/14, 8303030063.

--8303030085 Notice of issuance & availability of Amends 86, 83 & 57 to Licenses DPR-33, DPR-52 & DPR-68, respectively.
VASSALLO, D. B. Operating Reactors Branch 2. 83/02/14. 2pp. 17365:348. 24X Fiche: 50-259, 83/02/14, 8303030063.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303040341 Responds to technical evaluation rept, "Safety Evaluation for Environ Qualification of Safety-Related Electrical Equipment." Ongoing investigations still in progress re Item 87.
MILLS, L. M. Tennessee Valley Authority. 83/02/28. VASSALLO, D. B. Operating Reactors Branch 2. 164pp. 17372:087. 24X
Fiche: 50-259, 83/02/28, 8303040341.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303100295 Requests refund re 800121 & 1124 application for amends to OLs. Amends authorizing onsite storage of radwaste applicable to 10CFR30 licenses. Amend fee not required.
MILLS, L. M. Tennessee Valley Authority. 83/03/03. MILLER, W. O. License Fee Management Branch. 1p. 17489:295. 24X
Fiche: 50-000, 83/03/03, 8303100295.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5pp 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303300094 Forwards Region II SER re util response to NUREG-0737, Item II.B.2.2, "Plant Shielding Mods for Vital Area Access." Requirements met.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/08 PARRIS, H. G. Tennessee Valley Authority 2pp 17749:173 24X
Fiche: 50-259, 83/03/08, 8303300094.

--8303300102 SER re util response to NUREG-0737, Item II.B.2.2, "Plant Shielding Mods for Vital Area Access." Shield design & emergency operating procedures acceptable.
* Region 2, Office of Director 83/03/08 2pp 17749:175 24X
Fiche: 50-259, 83/03/08, 8303300094.

8303300299 Forwards Amends 87, 84 & 53 to Licenses DPR-33, DPR-52 & DPR-68, respectively & notice of issuance & availability. Amends delete App B ETS re nonradiological water quality-related requirements.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/11 PARRIS, H. G. Tennessee Valley Authority 3pp 17749:129 24X
Fiche: 50-259, 83/03/11, 8303300299.

--8303300308 Amends 87, 84 & 53 to Licenses DPR-33, DPR-52 & DPR-68, respectively, deleting App B ETS pertaining to nonradiological water quality-related requirements required by Federal Water Pollution Control Act Amends of 1972.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/11 32pp 17749:132 24X Fiche: 50-259, 83/03/11, 8303300299.

--8303300325 Notice of issuance & availability of Amends 87, 84 & 53 to Licenses DPR-33, DPR-52 & DPR-68, respectively.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/11 2pp 17749:164 24X Fiche: 50-259, 83/03/11, 8303300299.

8303180454 Responds to NRC 830302 & 08 conference calls requesting addl info re RETRAN Methodology Repts TVA-TRB1-01 & TVA-MDS-553. Immediate approval of submittal requested.
MILLS, L. M. Tennessee Valley Authority 83/03/15 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 9pp 17621:259 24X Fiche: 50-259, 83/03/15, 8303180454.

8303240447 Confirms verbal requirement to submit NPDES permit changes or violations requiring notification per NRC 830311 request.
MILLS, L. M. Tennessee Valley Authority 83/03/22 VASSALLO, D. B. Operating Reactors Branch 2 1p 17678:343 24X
Fiche: 50-259, 83/03/22, 8303240447.

8303310420 Application to amend OLs, revising Tech Specs re drywell leakage, in response to IE Bulletin 82-03, "Stress Corrosion Cracking in Thick Wall Large Diameter Stainless Steel, Recirculation Sys Piping at BWR Plants."
MILLS, L. M. Tennessee Valley Authority 83/03/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp 17755:081 24X Fiche: 50-259, 83/03/25, 8303310420.

--8303310424 Proposed Tech Spec changes re drywell leakage.
* Tennessee Valley Authority 83/03/25 11pp 17755:084 24X
Fiche: 50-259, 83/03/25, 8303310420.

## G. Inspection reports, IE Bulletins & correspondence

8303010448 Responds to NRC 820517 ltr re violations noted in IE Insp Repts 50-259/82-13, 50-260/82-13 & 50-296/82-13. Corrective actions: complete rev of sys operating instructions will be delayed from 830101 to 830201.
MILLS, L. M. Tennessee Valley Authority 82/12/16 O'REILLY, J. P. Region 2, Office of Director 1p 17343:052 24X
Fiche: 50-259, 82/12/16, 8303010448.

8303010293 Responds to NRC 820727 ltr re violations noted in IE Insp Repts 50-259/82-20, 50-260/82-20 & 50-296/82-20. Corrective actions: security program audit will be performed by 830130.
MILLS, L. M. Tennessee Valley Authority 82/12/28 O'REILLY, J. P. Region 2, Office of Director 1p 17334:086 24X
Fiche: 50-259, 82/12/28, 8303010293.

8303010428 Forwards results of mechanical snubber insps required by IE Bulletin 81-01. All Intl Nuclear Safeguards Corp mechanical snubbers installed in Unit 2 replaced w/Pacific Scientific Corp snubbers.
MILLS, L. M. Tennessee Valley Authority 83/02/16 O'REILLY, J. P. Region 2, Office of Director 2pp 17343:269 24X
Fiche: 50-259, 83/02/16, 8303010428.

8303010541 Ack receipt of 830207 ltr & remittance wired on 830216 in payment of civil penalties proposed in 830103 ltr. Corrective actions described in ltr will be examined during future insps.
AXELRAD, J. A. Director's Office, Office of Inspection and Enforcement 83/02/24 PARRIS, H. G. Tennessee Valley Authority 2pp 17342:259 24X Fiche: 50-259, 83/02/24, 8303010541.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 111pp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210756 Ack receipt of 830222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-46, 50-260/82-46 & 50-296/82-46.
LEWIS, R. C. Division of Project & Resident Programs 83/03/02
PARRIS, H. G. Tennessee Valley Authority 1p 17635:044 24X
Fiche: 50-259, 83/03/02, 8303210756.

--8303210765 Responds to NRC 830119 ltr re violations noted in IE Insp Repts 50-259/82-46, 50-260/82-46 & 50-296/82-46. Corrective actions: charcoal trays in control room emergency ventilation sys replaced.
MILLS, L. M. Tennessee Valley Authority 83/02/22 O'REILLY, J. P. Region 2, Office of Director 5pp 17635:045 24X
Fiche: 50-259, 83/03/02, 8303210756.

--8303210771 Forwards IE Insp Repts 50-259/82-46, 50-260/82-46 & 50-296/82-46 on 821126-1225 & notice of violation.
LEWIS, R. C. Division of Project & Resident Programs 83/01/19
PARRIS, H. G. Tennessee Valley Authority 2pp 17635:050 24X
Fiche: 50-259, 83/03/02, 8303210756.

--8303210772 Notice of violation from insp on 821126-1225.
* Region 2, Office of Director 83/01/19 2pp 17635:052 24X
Fiche: 50-259, 83/03/02, 8303210756.

--8303210773 IE Insp Repts 50-259/82-46, 50-260/82-46 & 50-296/82-46 on 821126-1225 Noncompliance noted: failure to have control room emergency pressurization sys operable & to perform maint per plant instructions.
PAULK, G. L. Region 2, Office of Director CANTRELL, F. S. Division of Project & Resident Programs 83/01/18 8pp 17635:054 24X
Fiche: 50-259, 83/03/02, 8303210756.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

8303310420 Application to amend OLs, revising Tech Specs re drywell leakage, in response to IE Bulletin 82-03, "Stress Corrosion Cracking in Thick Wall Large Diameter Stainless Steel, Recirculation Sys Piping at BWR Plants."
MILLS, L. M. Tennessee Valley Authority 83/03/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp 17755:081 24X Fiche: 50-259, 83/03/25, 8303310420.

--8303310424 Proposed Tech Spec changes re drywell leakage.
* Tennessee Valley Authority 83/03/25 11pp 17755:084 24X
Fiche: 50-259, 83/03/25, 8303310420.

## R. Periodic operating reports & related correspondence

8303080016 Forwards monthly operating repts for Dec 1982.
JONES, O. T. Tennessee Valley Authority 83/01/11 Office of Resource Management, Director 1p 17458:072 24X
Fiche: 50-259, 83/01/11, 8303080016.

--8303080021 Monthly operating repts for Dec 1982.
THOM, T. Tennessee Valley Authority 83/01/01 40pp 17458:073 24X Fiche: 50-259, 83/01/11, 8303080016.

8303150490 Forwards monthly operating repts for Jan 1983.
JONES, O. T. Tennessee Valley Authority. 83/02/09. Office of Resource Management, Director. 1p. 17560:349. 24X
Fiche: 50-259, 83/02/09, 8303150490.

--8303150496 Monthly operating repts for Jan 1983.
SWINDELL, J. E., THOM, T. Tennessee Valley Authority. 83/02/01. 40pp. 17560:350. 24X Fiche: 50-259, 83/02/09, 8303150490.

8303160216 Central emergency control ctr meteorological data statistics for Oct-Dec 1982, reported per util commitment to NUREG-0737, Item III.A.2.1.
MILLS, L. M. Tennessee Valley Authority. 83/03/09. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17596:323. 24X Fiche: 50-000, 83/03/09, 8303160216.

8303170463 Forwards monthly operating repts for Feb 1983.
JONES, O. T. Tennessee Valley Authority. 83/03/10. Division of Data Automation & Management Information. 1p. 17609:213. 24X
Fiche: 50-259, 83/03/10, 8303170463.

--8303170467 Monthly operating repts for Feb 1983.
JONES, O. T., THOM, T. Tennessee Valley Authority. 83/03/01. 44pp. 17609:214. 24X Fiche: 50-259, 83/03/10, 8303170463.

S. Reportable occurrences, LERs & related correspondence

8303040374 Forwards LER 83-006/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/02/24. O'REILLY, J. P. Region 2, Office of Director. 1p. 17420:011. 24X
Fiche: 50-296, 83/02/24, 8303040374.

--8303040395 LER 83-006/03L-0 on 830128, during shutdown, while performing monthly vibration tests on 480-volt reactor motor operated valve motor generator sets, high vibration readings detected. Caused by leak in seal ring Coupling & rings replaced.
AARON, J. R. Tennessee Valley Authority. 83/02/24. Region 2, Office of Director. 1p. 17420:012. 24X Fiche: 50-296, 83/02/24, 8303040374.

8303040381 Forwards LER 83-007/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/02/24. O'REILLY, J. P. Region 2, Office of Director. 1p. 17420:004. 24X
Fiche: 50-296, 83/02/24, 8303040381.

--8303040389 LER 83-007/03L-0 on 830128, during monthly vibration checks, generator/Flywheel ball bearing developed high vibration levels. Cause suspected to be normal wear. Bearing replaced.
AARON, J. R. Tennessee Valley Authority. 83/02/24. Region 2, Office of Director. 2pp. 17420:005. 24X Fiche: 50-296, 83/02/24, 8303040381.

8303150297 Forwards LER 83-009/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/03/07. O'REILLY, J. P. Region 2, Office of Director. 1p. 17566:261. 24X
Fiche: 50-296, 83/03/07, 8303150297.

--8303150309 LER 83-009/03L-0 on 830209, sample pump found inoperative during reactor & turbine bldg vent monitor CAM 3-RM-90-250 daily source & background check. Caused by blown fuse. Faulty Allied RS5D relay caused control room alarm malfunction.
NORWOOD, D. W. Tennessee Valley Authority. 83/03/07. Region 2, Office of Director. 2pp. 17566:262. 24X Fiche: 50-296, 83/03/07, 8303150297.

8303150466 Forwards LER 83-010/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/03/07. O'REILLY, J. P. Region 2, Office of Director. 1p. 17561:133. 24X
Fiche: 50-296, 83/03/07, 8303150466.

--8303150467 LER 83-010/03L-0 on 830209, main steam line low pressure switch found w/low setpoint. Caused by instrument drift. Switch 3-PS-1-76 recalibr.
LITTLE, G. V. Tennessee Valley Authority. 83/03/07. Region 2, Office of Director. 3pp. 17561:134. 24X Fiche: 50-296, 83/03/07, 8303150466.

8303150248 Forwards LER 83-011/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/03/09. O'REILLY, J. P. Region 2, Office of Director. 1p. 17567:132. 24X
Fiche: 50-296, 83/03/09, 8303150248.

--8303150263 LER 83-011/03L-0 on 830211, during monthly lubrication insps, leak discovered on 480-volt reactor motor-operated valve board motor-generated set 3EN. Caused by damage during installation of seal rings. Seal rings replaced.
AARON, J. R. Tennessee Valley Authority. 83/03/09. Region 2, Office of Director. 2pp. 17567:133. 24X Fiche: 50-296, 83/03/09, 8303150248.

8303160432 Forwards LER 83-012/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/03/09. O'REILLY, J. P. Region 2, Office of Director. 1p. 17592:342. 24X
Fiche: 50-296, 83/03/09, 8303160432.

--8303160438 LER 83-012/03L-0 on 830217, drywell pressure switch 3-PS-64-58C operated above Tech Spec limit. Caused by calibr drift. Switch recalibr.
BASS, G. W. Tennessee Valley Authority. 83/03/09. Region 2, Office of Director. 3pp. 17592:343. 24X Fiche: 50-296, 83/03/09, 8303160432.

8303160531 Forwards revised LER 82-056/03X-1.
GREEN, H. J. Tennessee Valley Authority. 83/03/09. O'REILLY, J. P. Region 2, Office of Director. 1p. 17587:234. 24X
Fiche: 50-296, 83/03/09, 8303160531.

--8303160536 Revised LER 82-056/03X-1 on 821128, particulate channel on 3-RM-90-256 drywell CAM went downscale due to moisture in sample chamber. Caused by leakage past sealing O-rings. O-rings replaced.
THORPE, D. Tennessee Valley Authority. 83/03/09. Region 2, Office of Director. 2pp. 17587:235. 24X Fiche: 50-296, 83/03/09, 8303160531.

8303240606 Forwards LER 83-013/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/03/17. O'REILLY, J. P. Region 2, Office of Director. 1p. 17683:211. 24X
Fiche: 50-296, 83/03/17, 8303240606.

--8303240608 LER 83-013/03L-0 on 830217, while performing ST 4.2.F.7, suppression pool level instrument loop 64-66 found out of tolerance. Caused by setpoint drift of level transmitter & level indicator. Transmitter recalibr & tested.
GOODWIN, D. C. Tennessee Valley Authority. 83/03/17. Region 2, Office of Director. 2pp. 17683:212. 24X Fiche: 50-296, 83/03/17, 8303240606.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303080442 Submits schedule for NRC operator licensing exam site visits through 1985, in response to Generic Ltr 83-01. Exams on 830815-19 for Watts Bar requested to be postponed due to delay in final fuel loading date.
MILLS, L. M. Tennessee Valley Authority. 83/02/28. ADENSAM, T. Licensing Branch 4. 2pp. 17454:256. 24X Fiche: 50-000, 83/02/28, 8303080442.

X. Onsite Storage of Low Level Waste

8303100295 Requests refund re 800121 & 1124 application for amends to OLs. Amends authorizing onsite storage of radwaste applicable to 10CFR30 licenses. Amend fee not required.
MILLS, L. M. Tennessee Valley Authority. 83/03/03. MILLER, W. O. License Fee Management Branch. 1p. 17489:295. 24X
Fiche: 50-000, 83/03/03, 8303100295.

DOCKET 50-297 NORTH CAROLINA STATE UNIV. PULSTAR REACTOR

F. Security, medical, emergency & fire protection plans

8303180257 Forwards request for addl comments re security plan. Amended plan pages requested within 30 days. Request for addl info withheld (ref 10CFR2.790).
THOMAS, C. O. Standardization & Special Projects Branch. 83/03/15. THOMAS, J. L. North Carolina State Univ. 2pp. 17616:178. 24X
Fiche: 50-297, 83/03/15, 8303180257.

DOCKET 50-298 COOPER NUCLEAR STATION

F. Security, medical, emergency & fire protection plans

8302090056 Requests that encl proposed route for irradiated reactor fuel shipment be withheld from public disclosure per 10CFR2.790. Encl withheld (ref 10CFR2.790).
PILANT, J. M. Nebraska Public Power District. 82/11/30. SHERR, T. S. Material Transfer Safeguards Licensing Branch. 1p. 17119:182. 24X
Fiche: 50-298, 82/11/30, 8302090056.

8303010412 Requests assistance in determining optimal locations for emergency notification sys & health physics network (HPN) phones in emergency response facilities, supplementing NUREG-0696. Replacement of HPN lines w/FTS lines considered. COLLINS, J. T. Region 4, Office of Director 83/02/24 PILANT, J. M. Nebraska Public Power District 2pp 17346:234 24X Fiche: 50-298, 83/02/24, 8303010412.

8303010527 Advises that emergency notification sys & health physics network telephones in emergency operations ctr will be relocated by 830318, per 830203 ltr. MADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs 83/02/24 PILANT, J. M. Nebraska Public Power District 1p 17337:190 24X Fiche: 50-298, 83/02/24, 8303010527.

--8303010535 Requests relocation of emergency notification sys telephones fr security bldg PBX room & health physics network telephones in security bldg radiological assessment area to new emergency operations facility by 830401. PILANT, J. M. Nebraska Public Power District 83/02/03 MADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs 1p 17337:191 24X Fiche: 50-298, 83/02/24, 8303010527.

8303290120 Releases public version of revised emergency plan implementing procedures. FELTON, J. M. Division of Rules and Records 83/03/17 Document Management Branch 1p 17729:044 24X Fiche: 50-298, 83/03/17, 8303290120.

--8303290129 Forwards public version of revised emergency plan implementing procedures, including Procedures 5.7.2 re notification of unusual event, 5.7.3 re alert & 5.7.12 re emergency radiation exposure control. PILANT, J. M. Nebraska Public Power District 83/03/08 Document Management Branch 1p 17729:045 24X Fiche: 50-298, 83/03/17, 8303290120.

--8303290137 Public version of revised emergency plan implementing procedures, including Procedures 5.7.2 re notification of unusual event, 5.7.3 re alert & 5.7.12 reemergency radiation exposure control. LESSOR, L. C. ; WHITMAN, D. ; SAYER, J. Nebraska Public Power District 83/02/21 58pp 17729:046 24X Fiche: 50-298, 83/02/17, 8303290120.

8303250134 Forwards revised preliminary supplemental response to NRC 821214 SER of util 820628 request for exemption from 10CFR50, App R re fire protection. Encl info documents 830303 meeting presentation & should justify requested exemptions. PILANT, J. M. Nebraska Public Power District 83/03/18 VASSALLO, D. B. Operating Reactors Branch 2 21pp 17692:209 24X Fiche: 50-298, 83/03/18, 8303250134.

8303280038 Forwards rept of change to safeguards plan, Rev 2. Rept withheld (ref 10CFR2.790 & 10CFR73.21). PILANT, J. M. Nebraska Public Power District 83/03/23 Office of Nuclear Reactor Regulation, Director 1p 17707:314 24X Fiche: 50-298, 83/03/25, 8303280038.

J. Insurance & indemnity information

8303160426 Forwards Endorsements 58 & 46 to NELIA Policy NF-200 & MAELU Policy MF-70, respectively. PILANT, J. M. Nebraska Public Power District 83/03/09 Office of Nuclear Reactor Regulation, Director 3pp 17592:284 24X Fiche: 50-298, 83/03/09, 8303160426.

K. Utility Final Safety Analysis Report (FSAR) & amends

8302280075 Chapter 10 to Cooper updated FSAR, "Auxiliary Sys." * Nebraska Public Power District 83/01/19 181pp 17327:105 24X Fiche: 50-298, 83/01/19, 8302280075.

P. Operating license stage documents & correspondence

8303020463 Forwards request for addl info in order to complete review of NUREG-0737, Item II.B.3, "Post-Accident Sampling Sys." Response due within 60 days of ltr receipt. VASSALLO, D. B. Operating Reactors Branch 2 83/02/15 PILANT, J. M. Nebraska Public Power District 36pp 17357:113 24X Fiche: 50-298, 83/02/15, 8303020463.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl. EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X Fiche: 50-000, 83/02/16, 8302170082.

8303020066 Forwards payment of balance of fees, per NRC 830210 request. Assistance in resolving matter appreciated. PILANT, J. M. Nebraska Public Power District 83/02/24 DIGGS, R. M. License Fee Management Branch 1p 17357:128 24X Fiche: 50-298, 83/02/24, 8303020066.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl. EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X Fiche: 50-000, 83/03/02, 8303020321.

8303150313 Forwards documentation of qualification & training of MT Culjat, replacement for shift technical advisor, per NUREG-0737, Item I.A.1.1. PILANT, J. M. Nebraska Public Power District 83/03/04 VASSALLO, D. B. Operating Reactors Branch 2 4pp 17567:073 24X Fiche: 50-298, 83/03/04, 8303150313.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl. EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp 17660:176 24X Fiche: 50-000, 83/03/07, 8303040005.

8303150340 Advises of 830405 meeting w/licensees & major contractors at Dallas/Fort Worth, TX to provide info & guidance re 10CFR50 QA & Tech Spec deviations & discuss decentralization policy. Questions should be submitted in writing by 830321. COLLINS, J. T. Region 4, Office of Director 83/03/10 Public Service Co. of Colorado 12pp 17562:291 24X Fiche: 50-000, 83/03/10, 8303150340.

8303150352 Advises of 830405 meeting w/licensees & major contractors in Dallas/Fort Worth, TX to provide info & guidance re 10CFR50 QA & Tech Spec deviaitions & discuss decentralization policy. Questions should be submitted in writing by 830321. COLLINS, J. T. Region 4, Office of Director 83/03/11 PILANT, J. M. Nebraska Public Power District 3pp 17562:353 24X Fiche: 50-298, 83/03/11, 8303150352.

8303250114 Forwards Amend 81 to License DPR-46 & notice of issuance & availability. Amend deletes App B ETS pertaining to nonradiological water quality-related requirements. VASSALLO, D. B. Operating Reactors Branch 2 83/03/11 PILANT, J. M. Nebraska Public Power District 3pp 17700:341 24X Fiche: 50-298, 83/03/11, 8303250114.

--8303250116 Amend 81 to License DPR-46, deleting App B ETS pertaining to nonradiological water quality-related requirements. VASSALLO, D. B. Operating Reactors Branch 2 83/03/11 10pp 17700:344 24X Fiche: 50-298, 83/03/11, 8303250114.

--8303250119 Notice of issuance & availability of Amend 81 to License DPR-46. VASSALLO, D. B. Operating Reactors Branch 2 83/03/11 2pp 17700:354 24X Fiche: 50-298, 83/03/11, 8303250114.

8303280093 Forwards safety evaluation re design review of plant shielding. Mods to post-accident sampling sys & procedures for post-accident sampling per NUREG-0737, Item II.B.3 acceptable. VASSALLO, D. B. Operating Reactors Branch 2 83/03/11 PILANT, J. M. Nebraska Public Power District 2pp 17715:342 24X Fiche: 50-298, 83/03/11, 8303280093.

--8303280095 Safety evaluation supporting mods resulting from plant shielding design review for post-accident acccess to vital areas per NUREG-0737, Item II.B.2. * Office of Nuclear Reactor Regulation, Director 83/03/11 2pp 17715:344 24X Fiche: 50-298, 83/03/11, 8303280093.

8303300213 Forwards order confirming util commitment to implement post-TMI-related items set forth in NUREG-0737 & Generic Ltrs 82-05 & 82-10. VASSALLO, D. B. Operating Reactors Branch 2 83/03/14 PILANT, J. M. Nebraska Public Power District 3pp 17749:270 24X Fiche: 50-298, 83/03/14, 8303300213.

--8303300217 Order confirming util commitment to implement post-TMI-related items set forth in NUREG-0737 & Generic Ltrs 82-05 & 82-10. Hearing may be requested within 20 days of order publication. PURPLE, R. A. Division of Licensing 83/03/14 Nebraska Public Power District 9pp 17749:273 24X Fiche: 50-298, 83/03/14, 8303300213.

8303240473 Advises that NRC/MO environ monitoring program terminated 830301 since program duplicates NE Public Power District program conducted in site vicinity. Tabulation of NRC/MO environ monitoring program encl.
COLLINS, J. T. Region 4, Office of Director. 83/03/15. MILLER, K. Missouri, State of. 8pp. 17678:028. 24X Fiche: 50-298, 83/03/15, 8303240473.

Q. Inspection reports, IE Bulletins & correspondence

8303180228 Forwards IE Insp Rept 50-298/82-27 on 821004-08. No noncompliance noted.
MADSEN, G. L. Region 4, Office of Director. 82/12/30. PILANT, J. M. Nebraska Public Power District. 4pp. 17621:141. 24X Fiche: 50-298, 82/12/30, 8303180228.

--8303180230 IE Insp Rept 50-298/82-27 on 821004-08. No noncompliance noted. Major areas inspected: staffing, training program, sample collection, sample treatment & analysis, chemistry analytical procedures & lab instrument calibr & QC.
NICHOLAS, J. B., WISE, R., MURRAY, B. Region 4, Office of Director. 82/12/06. 18pp. 17621:145. 24X Fiche: 50-298, 82/12/30, 8303180228.

8303010405 Forwards IE Insp Rept 50-298/83-01 on 830101-31. No noncompliance noted.
MADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs. 83/02/16. PILANT, J. M. Nebraska Public Power District. 1p. 17346:214. 24X Fiche: 50-298, 83/02/16, 8303010405.

--8303010410 IE Insp Rept 50-298/83-01 on 830101-31. No noncompliance noted. Major areas inspected: operational safety verifications, monthly surveillance & maint observations, LERs & TMI action plan requirements.
DUBOIS, D. L. Region 4, Office of Director. WESTERMAN, T. F. Division of Resident, Reactor Project & Engineering Programs. 83/02/16. 9pp. 17346:215. 24X Fiche: 50-298, 83/02/16, 8303010405.

8303090143 Ack receipt of 821007, 1119 & 23 ltrs in response to 820809 notice of violation & proposed imposition of civil penalties re violations discovered during 820311-30 insp. Violations reconfirmed. Order encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/18. JONES, C. R. Nebraska Public Power District. 2pp. 17464:350. 24X Fiche: 50-298, 83/02/18, 8303090143.

--8303090146 Order imposing civil monetary penalty in amount of $112,000 for violations discovered during 820311-30 insp.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/18. Nebraska Public Power District. 9pp. 17464:352. 24X Fiche: 50-298, 83/02/18, 8303090143.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303150212 Responds to IE Info Notice 83-01, "Fraudulent Practices of Ray Miller, Inc." Ray Miller, Inc is not & never was on plant qualified vendor list. Some Ray Miller, Inc piping & fittings supplied to sys not classified as essential.
SCHAUFELBERGER. Nebraska Public Power District. 83/03/10.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 2pp. 17555:122. 24X Fiche: 50-298, 83/03/10, 8303150212.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303180222 Ack receipt of 830217 ltr informing NRC of steps taken to correct violation & deviation noted in IE Insp Rept 50-298/82-36.
MADSEN, G. L. Region 4, Office of Director. 83/03/15. PILANT, J. M. Nebraska Public Power District. 2pp. 17617:348. 24X Fiche: 50-298, 83/03/15, 8303180222.

--8303180226 Responds to NRC 830118 ltr re violations noted in IE Insp Rept 50-298/82-36. Corrective actions: individuals who did not attend required lectures have completed required annual requalification exam training.
PILANT, J. M. Nebraska Public Power District. 83/02/17.
MADSEN, G. L. Region 4, Office of Director. 5pp. 17617:350. 24X Fiche: 50-298, 83/03/15, 8303180222.

8303240007 Forwards payment in response to NRC 830218 ltr transmitting order imposing civil monetary penalty (EA-82-46).
JONES, C. R. Nebraska Public Power District. 83/03/16. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 4pp. 17681:097. 24X Fiche: 50-298, 83/03/16, 8303240007.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

R. Periodic operating reports & related correspondence

8303080185 Forwards monthly operating rept for Dec 1982.
LESSOR, L. C. Nebraska Public Power District. 83/01/05. Division of Data Automation & Management Information. 1p. 17457:345. 24X Fiche: 50-298, 83/01/05, 8303080185.

--8303080191 Monthly operating rept for Dec 1982.
BALLINGER, P. L. Nebraska Public Power District. 83/01/05. 4pp. 17457:346. 24X Fiche: 50-298, 83/01/05, 8303080185.

8303150550 Forwards monthly operating rept for Jan 1983.
LESSOR, L. C. Nebraska Public Power District. 83/02/04. Office of Resource Management, Director. 1p. 17568:059. 24X Fiche: 50-298, 83/02/04, 8303150550.

--8303150555 Monthly operating rept for Jan 1983.
BALLINGER, P. L. Nebraska Public Power District. 83/02/04. 4pp. 17568:060. 24X Fiche: 50-298, 83/02/04, 8303150550.

8303150256 Forwards "Annual Operating Rept, 1982."
PILANT, J. M. Nebraska Public Power District. 83/02/22. COLLINS, J. T. Region 4, Office of Director. 1p. 17567:276. 24X Fiche: 50-298, 83/02/22, 8303150256.

--8303150260 "Annual Operating Rept, 1982."
Nebraska Public Power District. 83/02/22. 16pp. 17567:277. 24X Fiche: 50-298, 83/02/22, 8303150256.

S. Reportable occurrences, LERs & related correspondence

8303250007 Forwards LER 83-002/03L-0. Detailed event analysis submitted.
LESSOR, L. C. Nebraska Public Power District. 83/03/17. COLLINS, J. T. Region 4, Office of Director. 4pp. 17692:111. 24X Fiche: 50-298, 83/03/17, 8303250007.

--8303250011 LER 83-002/03L-0 on 830218, source range monitor rod blocks not tested prior to hot startup. Caused by inadequate procedures. Procedure 2.1.2 revised.
WIRE, K. Nebraska Public Power District. 83/03/17. Region 4, Office of Director. 1p. 17692:115. 24X Fiche: 50-298, 83/03/17, 8303250007.

8303250025 Forwards LER 83-001/03L-0. Detailed event analysis submitted.
LESSOR, L. C. Nebraska Public Power District. 83/03/17. COLLINS, J. T. Region 4, Office of Director. 2pp. 17693:133. 24X Fiche: 50-298, 83/03/17, 8303250025.

--8303250028 LER 83-001/03L-0 on 830223, while performing Surveillance Procedure 6.2.2.2.4, safety relief valve 71-C failed to transfer alternate power source when fuse pulled. Caused by bad contact on relay. Relay control wire adjusted.
STUDEBAKER, S. T. Nebraska Public Power District. 83/03/17. Region 4, Office of Director. 1p. 17693:135. 24X Fiche: 50-298, 83/03/17, 8303250025.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8303140112 Requests that comments on 830114 draft SER re App R exemption requests be submitted as soon as possible to allow preparation for early meeting to review technical info.
CLARK, R. A. Operating Reactors Branch 3. 83/02/23. FAY, C. W. Wisconsin Electric Power Co. 2pp. 17548:303. 24X Fiche: 50-266, 83/02/23, 8303140112.

8303040622 Forwards technical evaluations of NRC 830114 draft safety evaluation & BNL evaluation re util requests for exemption from 10CFR50, App R, Section III.G requirements. All requested exemptions should be granted.
FAY, C. W. Wisconsin Electric Power Co. 83/02/25 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 144pp 17369:178
24X Fiche: 50-266, 83/02/25, 8303040622.

8303140402 Forwards IE Mgt Meeting Repts 50-266/83-02 & 50-301/83-02 on 830110. No noncompliance noted.
LITTLE, W. S. Region 3, Office of Director 83/02/28 BURSTEIN, S.
Wisconsin Electric Power Co. 2pp 17542:190 24X
Fiche: 50-266, 83/02/28, 8303140402.

--8303140406 IE Mgt Meeting Repts 50-266/83-02 & 50-301/83-02 on 830110. No noncompliance noted. Major areas discussed previously identified unresolved issues including fire protection.
RAMSEY, C. Region 3, Office of Director 83/02/12 3pp.
17542:192 24X Fiche: 50-266, 83/02/28, 8303140402.

8303240242 Forwards IE Insp Repts 50-266/83-01 & 50-301/83-01 on 830131-0225 & notice of violation.
PAPERIELLO, C. J. Region 3, Office of Director 83/03/08
BURSTEIN, S. Wisconsin Electric Power Co. 2pp 17682:139 24X
Fiche: 50-266, 83/03/08, 8303240242.

--8303240248 Notice of violation from insp on 830131-0225.
PAPERIELLO, C. J. Region 3, Office of Director 83/03/07 1p.
17682:141 24X Fiche: 50-266, 83/03/08, 8303240242.

--8303240259 IE Insp Repts 50-266/83-01 & 50-301/83-01 on 830131-0225. Noncompliance noted: inadequate emergency preparedness implementation procedures to assure notification of state & local govt agencies within 15 minutes.
PAGLIARO, J. A. Region 3, Office of Director 83/03/05 16pp.
17682:142 24X Fiche: 50-266, 83/03/08, 8303240242.

8303170445 Forwards IE Safeguards Insp Repts 50-266/83-05 & 50-301/83-05 on 830207-11 & notice of violation. Notice of violation & rept details withheld (ref 10CFR73.21).
HIND, J. A. Region 3, Office of Director 83/03/14 BURSTEIN, S.
Wisconsin Electric Power Co. 2pp 17609:204 24X
Fiche: 50-266, 83/03/14, 8303170445.

--8303170459 IE Safeguards Insp Repts 50-266/83-05 & 50-301/83-05 on 830207-11. Noncompliance noted: documentation not available for access control & test penetration not detected by intrusion alarm sys. Details withheld (ref 10CFR73.21).
PIRTLE, G. L. Region 3, Office of Director 83/03/10 2pp.
17609:206 24X Fiche: 50-266, 83/03/14, 8303170445.

8303240001 Notification of 830322 meeting w/util & BNL in Bethesda, MD to discuss technical info associated w/requested exemptions from 10CFR50, App R.
COLBURN, T. G. Operating Reactors Branch 3 83/03/14 CLARK, R. A.
Operating Reactors Branch 3 2pp 17694:356 24X
Fiche: 50-266, 83/03/14, 8303240001.

8303280006 Application for amends to Licenses DPR-24 & DPR-27 incorporating changes to Tech Specs which provide that independent audit of emergency preparedness program be carried out in accordance w/10CFR50.54(t).
FAY, C. W. Wisconsin Electric Power Co. 83/03/21 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 2pp 17707:155
24X Fiche: 50-266, 83/03/21, 8303280006.

--8303280007 Proposed Tech Specs incorporating changes re independent audit of emergency preparedness program.
* Wisconsin Electric Power Co. 83/03/21 2pp 17707:157 24X
Fiche: 50-266, 83/03/21, 8303280006.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director 83/03/22 Commonwealth Edison Co. 2pp 17690:316 24X Fiche: 50-000, 83/03/22, 8303240440.

## 9. Adjudicatory correspondence

8303230257 Brief supporting WI Environ Decade 830211 exceptions to ASLB initial decision. ASLB refused to make prerequisite findings on degree of assurance necessary to protect public safety. Affidavit of Mailing encl.
ANDERSON, P. Wisconsin's Environmental Decade 83/03/16
Commissioners 12pp. 17661:170 24X Fiche: 50-266, 83/03/16, 8303230257.

## J. Insurance & indemnity information

8303310035 Forwards Endorsement 70 to NELIA Policy NF-178.
DUNDAS, W. J. Wisconsin Electric Power Co. 83/03/28 NRC - No
Detailed Affiliation Given 2pp 17763:050 24X
Fiche: 50-266, 83/03/28, 8303310035.

## K. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated
Edison Co. of New York, Inc. 18pp 17492:033 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303090260 Ack misinterpretation of util requests for relief from requirements re inservice testing of safety class components. Relief extended to Unit 2. Requested relief from frequency of visual exams denied. Corrected Tech Specs encl.
CLARK, R. A. Operating Reactors Branch 3 83/02/17 FAY, C. W.
Wisconsin Electric Power Co. 3pp 17485:182 24X
Fiche: 50-266, 83/02/17, 8303090260.

--8303090268 Corrected Table 1 re Class 1 components, to Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively.
* Operating Reactors Branch 3 83/02/17 3pp 17485:185 24X
Fiche: 50-266, 83/02/17, 8303090260.

8303010697 Forwards info identifying proprietary portions of Franklin Research 821222 safety & technical evaluation repts on environ qualification of safety-related electrical equipment per request. Proprietary portions deleted.
FAY, C. W. Wisconsin Electric Power Co. 83/02/22 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director CLARK, R. A.
Operating Reactors Branch 3 47pp 17341:165 24X
Fiche: 50-266, 83/02/22, 8303010697.

8303160162 Forwards addl info re NUREG-0737, Item II.F.1.4, "Containment Pressure Monitor," Item II.F.1.5, "Containment Water Level Monitor" & Item II.F.1.6, "Containment Hydrogen Monitor," in response to NRC 830202 ltr.
FAY, C. W. Wisconsin Electric Power Co. 83/02/28 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director CLARK, R. A.
Operating Reactors Branch 3 19pp 17597:001 24X
Fiche: 50-266, 83/02/28, 8303160162.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated
Edison Co. of New York, Inc. 17pp 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303090130 Forwards NFS 770506 ltr confirming title to spent fuel assemblies stored at West Valley facility in response to 830302 request.
FAY, C. W. Wisconsin Electric Power Co. 83/03/03 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director CLARK, R. A.
Operating Reactors Branch 3 5pp 17470:301 24X
Fiche: 50-266, 83/03/03, 8303090130.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J. G. Region 3, Office of Director 83/03/03
Commonwealth Edison Co. 2pp 17492:014 24X Fiche: 50-000, 83/03/03, 8303100364.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated
Edison Co. of New York, Inc. 51pp 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303150333 Mod to application for amend to Licenses DPR-24 & DPR-27, changing Tech Spec Change Request 69 to revise Section 15.3.1.C & Table 15.4.1-2 re max coolant activity & min frequencies for equipment & sampling tests, respectively.
FAY, C. W. Wisconsin Electric Power Co. 83/03/09 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director CLARK, R. A.
Operating Reactors Branch 3 1p. 17563:026 24X
Fiche: 50-266, 83/03/09, 8303150333.

--8303150338 Proposed revised Tech Spec Section 15.3.1.C & Table 15.4.1-2 re max coolant activity & min frequencies for equipment & sampling tests, respectively.
* Wisconsin Electric Power Co. 83/03/09 7pp 17563:027 24X
Fiche: 50-266, 83/03/09, 8303150333.

8303240350 Forwards Amends 69 & 74 to Licenses DPR-24 & DPR-27, respectively, & notice of issuance & availability. Amends delete ETS nonradiological water quality-related requirements.
CLARK, R. A. Operating Reactors Branch 3. 83/03/11. FAY, C. W. Wisconsin Electric Power Co. 5pp. 17694:038. 24X
Fiche: 50-266, 83/03/11, 8303240350.

--8303240353 Amends 69 & 74 to Licenses DPR-24 & DPR-27, respectively, deleting ETS nonradiological water quality-related requirements.
CLARK, R. A. Operating Reactors Branch 3. 83/03/11. 9pp. 17694:043. 24X Fiche: 50-266, 83/03/11, 8303240350.

--8303240361 Notice of issuance & availability of Amends 69 & 74 to Licenses DPR-24 & DPR-27, respectively.
CLARK, R. A. Operating Reactors Branch 3. 83/03/11. 2pp. 17694:052. 24X Fiche: 50-266, 83/03/11, 8303240350.

8303210111 Application for amend to Licenses DPR-24 & DPR-27, revising limitations & bases re use of Westinghouse 14x14 optimized fuel assembly design.
FAY, C. W. Wisconsin Electric Power Co. 83/03/14. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 4pp. 17629:246. 24X
Fiche: 50-266, 83/03/14, 8303210111.

--8303210116 Proposed Tech Spec Change 87, revising Westinghouse 14x14 optimized fuel assembly design.
* Wisconsin Electric Power Co. 83/03/14. 38pp. 17629:250. 24X
Fiche: 50-266, 83/03/14, 8303210111.

8303220137 Supplis 791012 & 810601 responses to requests for addl info re offsite power distribution sys NRC safety analysis concluded that ac auxiliary power sys adequate & physical & electrical separation of power sys acceptable.
FAY, C. W. Wisconsin Electric Power Co. 83/03/14. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17657:245. 24X
Fiche: 50-266, 83/03/14, 8303220137.

8303230071 Forwards order confirming commitments to implement post-TMI items scheduled for completion on or after 820701, based on responses to Generic Ltrs 82-05 & 82-10.
CLARK, R. A. Operating Reactors Branch 3. 83/03/14. FAY, C. W. Wisconsin Electric Power Co. 3pp. 17688:062. 24X
Fiche: 50-266, 83/03/14, 8303230071.

--8303230079 Order confirming licensee commitments to implement & maintain post-TMI issues.
PURPLE, R. A. Division of Licensing. 83/03/14. Wisconsin Electric Power Co. 14pp. 17688:065. 24X Fiche: 50-266, 83/03/14, 8303230071.

8303230231 Agrees that present licenses need not be modified to authorize possession & storage of spent fuel assemblies in spent fuel storage pools. Disposal of spent fuel should be included in arrangements w/DOE.
CLARK, R. A. Operating Reactors Branch 3. 83/03/14. FAY, C. W. Wisconsin Electric Power Co. 3pp. 17686:065. 24X
Fiche: 50-266, 83/03/14, 8303230231.

8303280006 Application for amends to Licenses DPR-24 & DPR-27 incorporating changes to Tech Specs which provide that independent audit of emergency preparedness program be carried out in accordance w/10CFR50.54(t).
FAY, C. W. Wisconsin Electric Power Co. 83/03/21. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17707:155. 24X
Fiche: 50-266, 83/03/21, 8303280006.

--8303280007 Proposed Tech Specs incorporating changes re independent audit of emergency preparedness program.
* Wisconsin Electric Power Co. 83/03/21. 2pp. 17707:157. 24X
Fiche: 50-266, 83/03/21, 8303280006.

8303280037 Forwards response to Generic Ltr 82-28, "Inadequate Core Cooling Instrumentation Sys," including response to NUREG-0737, Item II.F.2.
FAY, C. W. Wisconsin Electric Power Co. 83/03/21. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 22pp. 17707:315. 24X
Fiche: 50-266, 83/03/21, 8303280037.

8303300127 Application for amend to Licenses DPR-24 & DPR-27, modifying 820427 Tech Spec Change Request 77 re loss of voltage protective relays.
FAY, C. W. Wisconsin Electric Power Co. 83/03/23. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17731:207. 24X
Fiche: 50-266, 83/03/23, 8303300127.

--8303300132 Proposed Tech Specs, modifying 820427 Tech Spec Change Request 77 re loss of voltage protective relays.
* Wisconsin Electric Power Co. 83/03/23. 1p. 17731:209. 24X
Fiche: 50-266, 83/03/23, 8303300127.

8303290258 Discusses differing concepts of operability re auxiliary feedwater sys. Procedural & hardware mods to sys presently being studied in order to resolve differences in interpretation. Tech Specs should be modified as stated.
FAY, C. W. Wisconsin Electric Power Co. 83/03/24. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 3pp. 17716:001. 24X
Fiche: 50-266, 83/03/24, 8303290258.

8303300293 Withdraws request for hearing on NRC 801024 order imposing requirements re environ qualification of safety-related electrical equipment, based on interpretation of qualification criteria & replacement equipment.
FAY, C. W. Wisconsin Electric Power Co. 83/03/24. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. EISENHUT, D. G. Division of Licensing. 2pp. 17734:284. 24X Fiche: 50-266, 83/03/24, 8303300293.

8303310013 Informs that Amends 69 & 74 to Licenses DPR-24 & DPR-27, respectively, deleting nonradiological water quality surveillance requirements from Tech Specs exempt from fees. NRC will refund previously submitted fees.
MILLER, W. O. License Fee Management Branch. 83/03/28. FAY, C. W. Wisconsin Electric Power Co. 1p. 17777:354. 24X
Fiche: 50-266, 83/03/28, 8303310013.

G. Inspection reports, IE Bulletins & correspondence

8303030591 Forwards IE Insp Repts 50-266/83-03 & 50-301/83-03 on 830125-27. No noncompliance noted.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 83/02/16. BURSTEIN, S. Wisconsin Electric Power Co. 2pp. 17410:001. 24X Fiche: 50-266, 83/02/16, 8303030591.

--8303030598 IE Insp Repts 50-266/83-03 & 50-301/83-03 on 830125-27. No noncompliance noted. Major areas inspected: effluent control instrumentation, testing of air cleaning sys, licensee audits, radiation protection procedures, posting & exposure control.
LOVENDALE, P. C., GREGER, L. R. Region 3, Office of Director. 83/02/16. 8pp. 17410:003. 24X Fiche: 50-266, 83/02/16, 8303030591.

8303090260 Ack misinterpretation of util requests for relief from requirements re inservice testing of safety class components. Relief extended to Unit 2. Requested relief from frequency of visual exams denied. Corrected Tech Specs encl.
CLARK, R. A. Operating Reactors Branch 3. 83/02/17. FAY, C. W. Wisconsin Electric Power Co. 3pp. 17485:182. 24X
Fiche: 50-266, 83/02/17, 8303090260.

--8303090268 Corrected Table 1 re Class 1 components, to Amends 63 & 68 to Licenses DPR-24 & DPR-27, respectively.
* Operating Reactors Branch 3. 83/02/17. 3pp. 17485:185. 24X
Fiche: 50-266, 83/02/17, 8303090260.

8212060367 IE Bulletin 80-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." S/c list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303030443 Clarifies NRC position re procedures for admitting NRC personnel to facilities. Lists of NRC inspectors & personnel likely to visit facility two or more times per qtr & at anytime encl. Lists will be updated every 6 months.
KEPPLER, J. G. Region 3, Office of Director. 83/02/28. BURSTEIN, S. Wisconsin Electric Power Co. 4pp. 17410:074. 24X
Fiche: 50-266, 83/02/28, 8303030443.

8303140402 Forwards IE Mgt Meeting Repts 50-266/83-02 & 50-301/83-02 on 830110. No noncompliance noted.
LITTLE, W. S. Region 3, Office of Director. 83/02/28. BURSTEIN, S. Wisconsin Electric Power Co. 2pp. 17542:190. 24X
Fiche: 50-266, 83/02/28, 8303140402.

--8303140406 IE Mgt Meeting Repts 50-266/83-02 & 50-301/83-02 on 830110. No noncompliance noted. Major areas discussed: previously identified unresolved issues including fire protection.
RAMSEY, C., ULIE, J., WILLIAMS, C. C. Region 3, Office of Director. 83/02/12. 3pp. 17542:192. 24X Fiche: 50-266, 83/02/28, 8303140402.

8303080271 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers to Open on Automatic Trip Signal." Plant Procedure ICP 2.3 changed to meet surveillance requirements & log entries verified.
FAY, C. W. Wisconsin Electric Power Co. 83/03/03. KEPPLER, J. G. Region 3, Office of Director. 2pp. 17449:352. 24X
Fiche: 50-266, 83/03/03, 8303080271.

# DOCKETED ITEMS

8303170369 Forwards IE Insp Repts 50-266/82-24 & 50-301/82-22 on 821201-830131 No noncompliance noted.
STREETER, J. F. Division of Project & Resident Programs. 83/03/03.
BURSTEIN, S. Wisconsin Electric Power Co. 2pp. 17609:319. 24X.
Fiche: 50-266, 83/03/03, 8303170369.

--8303170408 IE Insp Repts 50-266/82-24 & 50-301/82-22 on 821201-830131 No noncompliance noted. Major areas inspected: maint, surveillance, LERs, IE bulletins, NFBD relay failures, plant trips, previous insp findings & operational safety.
HAGUE, R. L., FITZPATRICK, B. Region 3, Office of Director.
JACKIW, I. N. Division of Project & Resident Programs. 83/03/03.
8pp. 17609:321. 24X. Fiche: 50-266, 83/03/03, 8303170369.

8303160221 Forwards Class III fee re 830119 request for relief from certain ASME Section XI inservice insp requirements.
FAY, C. W. Wisconsin Electric Power Co. 83/03/04. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. DIGGS, R. License Fee Management Branch. 2pp. 17596:325. 24X. Fiche: 50-301, 83/03/04, 8303160221.

8303240242 Forwards IE Insp Repts 50-266/83-01 & 50-301/83-01 on 830131-0225 & notice of violation.
PAPERIELLO, C. J. Region 3, Office of Director. 83/03/08.
BURSTEIN, S. Wisconsin Electric Power Co. 2pp. 17682:139. 24X.
Fiche: 50-266, 83/03/08, 8303240242.

--8303240248 Notice of violation from insp on 830131-0225.
PAPERIELLO, C. J. Region 3, Office of Director. 83/03/07. 1p.
17682:141. 24X. Fiche: 50-266, 83/03/08, 8303240242.

--8303240259 IE Insp Repts 50-266/83-01 & 50-301/83-01 on 830131-0225. Noncompliance noted: inadequate emergency preparedness implementation procedures to assure notification of state & local govt agencies within 15 minutes.
PAGLIARO, J. A., SNELL, W. G., AXELSON, W. L. Region 3, Office of Director. 83/03/05. 16pp. 17682:142. 24X. Fiche: 50-266, 83/03/08, 8303240242.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers," Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X. Fiche: 50-000, 83/03/11, 8212060380.

8303170445 Forwards IE Safeguards Insp Repts 50-266/83-05 & 50-301/83-05 on 830207-11 & notice of violation. Notice of violation & rept details withheld (ref 10CFR73.21).
HIND, J. A. Region 3, Office of Director. 83/03/14. BURSTEIN, S. Wisconsin Electric Power Co. 2pp. 17609:204. 24X.
Fiche: 50-266, 83/03/14, 8303170445.

--8303170459 IE Safeguards Insp Repts 50-266/83-05 & 50-301/83-05 on 830207-11. Noncompliance noted: documentation not available for access control & test penetration not detected by intrusion alarm sys. Details withheld (ref 10CFR73.21).
PIRTLE, G. L., CHRISTOFFER, G., CREED, J. R. Region 3, Office of Director. 83/03/10. 2pp. 17609:206. 24X. Fiche: 50-266, 83/03/14, 8303170445.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds," Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X. Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp," Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X. Fiche: 50-000, 83/03/21, 8212060387.

## R. Periodic operating reports & related correspondence

8303040530 Forwards "Semiannual Monitoring Rept, Jul-Dec 1982." Rept contains info re plant releases, new fuel receipts, environ radiological monitoring & leak testing of sources.
FAY, C. W. Wisconsin Electric Power Co. 83/02/25. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17366:139. 24X.
Fiche: 50-266, 83/02/25, 8303040530.

--8303040538 "Semiannual Monitoring Rept, Jul-Dec 1982."
* Wisconsin Electric Power Co. 83/02/25. 15pp. 17366:140. 24X.
Fiche: 50-266, 83/02/25, 8303040530.

8303160569 Forwards monthly operating repts for Feb 1983.
FAY, C. W. Wisconsin Electric Power Co. 83/03/10. NRC - No Detailed Affiliation Given. 1p. 17587:004. 24X.
Fiche: 50-266, 83/03/10, 8303160569.

--8303160577 Monthly operating repts for Feb 1983.
FAY, C. W. Wisconsin Electric Power Co. 83/03/07. 7pp. 17587:005. 24X. Fiche: 50-266, 83/03/10, 8303160569.

## S. Reportable occurrences, LERs & related correspondence

8303310152 Forwards licensee 830318 ltr to State of WI Dept of Natural Resources re 830207 violation of State of WI PDES Submittal confirms commitment to rept permit violations per Amends 69 & 74 to Licenses DPR-24 & DPR-27, respectively.
FAY, C. W. Wisconsin Electric Power Co. 83/03/25. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 17763:057. 24X. Fiche: 50-266, 83/03/25, 8303310152.

## V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X. Fiche: 50-000, 83/02/24, 8302250505.

8303080515 Submits schedule for requested NRC site visits to conduct operator licensing exams through Oct 1985 per Generic Ltr 83-01.
FAY, C. W. Wisconsin Electric Power Co. 83/03/02. EISENHUT, D. G. Division of Licensing. 1p. 17452:280. 24X. Fiche: 50-266, 83/03/02, 8303080515.

## DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

## F. Security, medical, emergency & fire protection plans

8303110163 Forwards 1983 radiological emergency exercise scenario. Exercise scheduled for 830222-24.
WESTAFER, G. R. Florida Power Corp. 83/01/07. O'REILLY, J. P. Region 2, Office of Director. 22pp. 17517:290. 24X. Fiche: 50-302, 83/01/07, 8303110163.

8303210599 Forwards IE Enforcement Meeting Rept 50-302/83-02 on 830124. No noncompliance noted.
O'REILLY, J. P. Region 2, Office of Director. 83/02/28. HANCOCK, J. A. Florida Power Corp. 2pp. 17636:322. 24X. Fiche: 50-302, 83/02/28, 8303210599.

--8303210612 IE Enforcement Meeting Rept 50-302/83-02 on 830124. No noncompliance noted. Major items discussed: 821020 operational mode change, 821105 nonfunctional fire barrier, 821111 maint procedure control & 821207 inadequate boron injection path.
DANCE, H. C. Division of Project & Resident Programs. 83/02/25. 4pp. 17636:324. 24X. Fiche: 50-302, 83/02/28, 8303210599.

8303170645 Forwards Amend 62 to License DPR-72 & notice of issuance & availability. Amend requires maint of guard training & qualification program.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/04. HANCOCK, J. A. Florida Power Corp. 3pp. 17615:152. 24X. Fiche: 50-302, 83/03/04, 8303170645.

--8303170648 Amend 62 to License DPR-72, requiring maint of guard training & qualification program.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/04. 2pp.
17615:155. 24X. Fiche: 50-302, 83/03/04, 8303170645.

--8303170650 Notice of issuance & availability of Amend 62 to License DPR-72.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/04. 2pp.
17615:157. 24X. Fiche: 50-302, 83/03/04, 8303170645.

8303110232 Forwards revised pages of physical security plan, Rev 4. Pages withheld (ref 10CFR2.790).
WESTAFER, G. R. Florida Power Corp. 83/03/07. Office of Nuclear Reactor Regulation, Director. 1p. 17518:358. 24X.
Fiche: 50-302, 83/03/07, 8303110232.

8303290831 Releases public version of revised radiological emergency response plan.
FELTON, J. M. Division of Rules and Records. 83/03/23. Document Management Branch. 1p. 17747:001. 24X. Fiche: 50-302, 83/03/23, 8303290831.

--8303290839 Forwards public version of Rev 2 to radiological emergency response plan.
WESTAFER, G. R. Florida Power Corp. 83/03/04. O'REILLY, J. P. Region 2, Office of Director. 1p. 17747:002. 24X.
Fiche: 50-302, 83/03/23, 8303290831.

--8303290845 Public version of Rev 2 to radiological emergency response plan.
* Florida Power Corp 83/02/03 389pp 17747.003 24X
Fiche: 50-302, 83/03/23, 8303290831

H. General correspondence

8303140074 Ack receipt of 830111 ltr requesting info on safe operation of facility, NRC 740705 SER best source for info on stds & safety goals, available in LPDR. Sufficient capacity in spent fuel pool to safely hold spent fuel through 1990.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 83/03/02 ORION, O. Affiliation Unknown 1p 17548.063 24X
Fiche: 50-302, 83/03/02, 8303140074

--8303140079 Requests addl info on stds & safety goals at facility.
ORION, O. Affiliation Unknown 83/01/11 GILINSKY, V. Commissioners 4pp 17548.064 24X Fiche: 50-302, 83/03/02, 8303140074

J. Insurance & indemnity information

8303290055 Forwards Endorsement 57 to NELIA Policy NF-195.
DUCK, J. R. Marsh & McLennan, Inc 83/03/15 SALTZMAN, J. Office of State Programs, Director 2pp 17722.312 24X
Fiche: 50-302, 83/03/15, 8303290055

P. Operating license stage documents & correspondence

8303240268 "Tech Specs for Redundant DHR Capability, Crystal River, Unit 3," informal rept.
FARMER, F. G. EG&G, Inc FIN A-6429 8303240268 82/07/31
DONOHEW, J. N. Division of Licensing 18pp 17696.329 24X
Fiche: 50-302, 82/07/31, 8303240268

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc 18pp 17492.033 24X
Fiche: 50-000, 83/02/16, 8302170082

8303010a98 Notification of 830118 meeting w/B&W Owners Group & B&W in Bethesda, MD to discuss plans in developing study re frequency & severity of potential pressurized thermal shock events applicable to all B&W plants.
VISSING, G. Operating Reactors Branch 4 83/02/18 STOLZ, J. Operating Reactors Branch 4 3pp 17348.334 24X
Fiche: 50-000, 83/02/18, 8303010a98

8303020213 Grants interim relief from implementation schedule for head vent installation. Final determination for granting full-term exemption depends upon successful demonstration of ability to safely vent noncondensable gas using hot leg vents.
EISENHUT, D. G. Division of Licensing 83/02/22 HANCOCK, J. A. Florida Power Corp 4pp 17358.001 24X Fiche: 50-302, 83/02/22, 8303020213

8303030703 Notification of 830307 meeting w/utils & NUS Corp in Bethesda, MD to discuss proposed rev to 10CFR40, Appendix A (Tech Specs).
BRINKMAN, D. S. Standardization & Special Projects Branch 83/02/22
THOMAS, C. O. Standardization & Special Projects Branch 2pp 17363.227 24X Fiche: 50-000, 83/02/22, 8303030703

8303040276 Requests submittal of applicable fee for 820827 request for relief from ASME Section XI requirements re reactor vessel insps within 15 days.
MILLER, W. O. License Fee Management Branch 83/03/01 HANCOCK, J. A. Florida Power Corp 1p 17426.354 24X Fiche: 50-302, 83/03/01, 8303040276

8303080077 Responds to 830216 ltr re assessment of operability of large diameter purge & vent valves mfg by Pratt. Purge & vent valves closed & will be verified every 31 days when in Modes 1, 2, 3, or 4.
WESTAFER, G. R. Florida Power Corp 83/03/01 STOLZ, J. F. Operating Reactors Branch 4 1p 17457.120 24X Fiche: 50-302, 83/03/01, 8303080077

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc 17pp 17700.303 24X
Fiche: 50-000, 83/03/02, 8303020321

8303100290 Informs that Tech Specs per Generic Ltr 82-16 re NUREG-0737, Items II.E.1.1, "Short-Term Auxiliary Feedwater Sys Evaluation," II.E.4.2.6, "Containment Purge Valve" & II.K.3.12, will be submitted by 830401.
WESTAFER, G. R. Florida Power Corp 83/03/04 EISENHUT, D. G. Division of Licensing 1p 17489.359 24X Fiche: 50-302, 83/03/04, 8303100290

8303170645 Forwards Amend 62 to License DPR-72 & notice of issuance & availability. Amend requires maint of guard training & qualification program.
STOLZ, J. F. Operating Reactors Branch 4 83/03/04 HANCOCK, J. A. Florida Power Corp 3pp 17615.152 24X Fiche: 50-302, 83/03/04, 8303170645

--8303170648 Amend 62 to License DPR-72, requiring maint of guard training & qualification program.
STOLZ, J. F. Operating Reactors Branch 4 83/03/04 2pp 17615.155 24X Fiche: 50-302, 83/03/04, 8303170645

--8303170650 Notice of issuance & availability of Amend 62 to License DPR-72.
STOLZ, J. F. Operating Reactors Branch 4 83/03/04 2pp 17615.157 24X Fiche: 50-302, 83/03/04, 8303170645

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc 51pp 17660.176 24X
Fiche: 50-000, 83/03/07, 8303040005

8303170136 Summary of 830223 meeting w/B&W Regulatory Response Group in Bethesda, MD re small break LOCA procedures & maintaining proper steam generator water level.
VAN VLIET, J. Operating Reactors Branch 4 83/03/08 Operating Reactors Branch 4 43pp 17615.224 24X Fiche: 50-000, 83/03/08, 8303170136

8303150407 Advises that info per 830222 ltr re exemption from 10CFR50.44(c)(3)(iii), "Installation of Reactor Vessel Head Vent," requirements will be submitted by 830513.
WESTAFER, G. R. Florida Power Corp 83/03/09 EISENHUT, D. G. Division of Licensing 1p 17561.265 24X Fiche: 50-302, 83/03/09, 8303150407

8303230405 Forwards Amend 63 to License DPR-72, safety evaluation & notice of issuance & availability. Amend exempts certain containment isolation valves from provisions of Tech Spec 3.0.4.
STOLZ, J. F. Operating Reactors Branch 4 83/03/10 HANCOCK, J. A. Florida Power Corp 3pp 17675.221 24X Fiche: 50-302, 83/03/10, 8303230405

--8303230409 Amend 63 to License DPR-72, exempting certain containment isolation valves, after valves placed in containment isolation position, from provisions of Tech Spec 3.0.4.
STOLZ, J. F. Operating Reactors Branch 4 83/03/10 11pp 17675.224 24X Fiche: 50-302, 83/03/10, 8303230405

--8303230416 Safety evaluation supporting Amend 63 to License DPR-72.
* Office of Nuclear Reactor Regulation, Director 83/03/10 2pp 17675.235 24X Fiche: 50-302, 83/03/10, 8303230405

--8303230420 Notice of issuance & availability of Amend 63 to License DPR-72.
STOLZ, J. F. Operating Reactors Branch 4 83/03/10 2pp 17675.237 24X Fiche: 50-302, 83/03/10, 8303230405

8303300733 Summary of 830303 meeting w/utils, B&W Owners Group & Natl Nuclear Corp in Bethesda, MD re plans concerning frequency & severity of pressurized thermal shock events for B&W plants. Viewgraphs encl.
VISSING, G. S. Operating Reactors Branch 4 83/03/15 Operating Reactors Branch 4 174pp 17765.013 24X Fiche: 50-000, 83/03/15, 8303300733

8303240101 Responds to 821229 ltr providing commitment to install control room indications of overrides consistent w/installation of emergency feedwater initiation & control sys, per TMI Action Item II.E.1.2. Sys acceptable.
STOLZ, J. F. Operating Reactors Branch 4 83/03/16 HANCOCK, J. A. Florida Power Corp 2pp 17700.301 24X Fiche: 50-302, 83/03/16, 8303240101

8303220158 Application for amend to License DPR-72, App A including Tech Spec Change Request 106 to allow use of roped & marked access barriers to high radiation areas at plant. Certificate of Svc encl.
WESTAFER, G. R. Florida Power Corp 83/03/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp 17659.017 24X
Fiche: 50-302, 83/03/18, 8303220158

# DOCKETED ITEMS

--8303220160 Tech Spec Change Request 106 allowing use of roped & marked access barriers to high radiation areas at plant when permanent locked encls cannot be readily constructed
* Florida Power Corp. 83/03/18 4pp. 17659.020 24X
Fiche 50-302.83/03/18.8303220158

8303250030 Discusses util actions re 821210 order for mod of license which requires installation of inadequate core cooling instrumentation sys. Util will provide preliminary conceptual design of reactor coolant tracking sys by 830415.
WESTAFER, G.R. Florida Power Corp. 83/03/22 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp. 17693.139 24X
Fiche 50-302.83/03/22.8303250030

8303290482 Responds to Generic Ltr 83-10 re submission of plans & schedule for NUREG-0737, Item II.K.3.5, "Automatic Trip of Reactor Pumps." Util will submit requested plans & schedule by 830701. Delay needed to formulate util position.
WESTAFER, G.R. Florida Power Corp. 83/03/25 EISENHUT, D.G. Division of Licensing 2pp. 17724.233 24X Fiche 50-302.83/03/25.
8303290482

8303310551 Notification of 830407 meeting w/B&W Owners Group in Bethesda, MD to review progress, schedules & typical event analyses re study of pressurized thermal shock.
VISSING, G.S. Operating Reactors Branch 4 83/03/25 STOLZ, J.F. Operating Reactors Branch 4 2pp. 17780.360 24X
Fiche 50-000.83/03/25.8303310551.

Q. Inspection reports, IE Bulletins & correspondence

8303210663 Responds to NRC 820820 ltr re violations noted in IE Insp Rept 50-302/82-15. Corrective actions: all quality-related records inspected for damage & returned to administrative bldg records vault.
BAYNARD, P.Y. Florida Power Corp. 82/09/24 O'REILLY, J.P. Region 2, Office of Director 2pp. 17635.229 24X Fiche 50-302.82/09/24.
8303210663

--8303210671 Forwards IE Insp Rept 50-302/82-15 on 820720-23 & notice of violation.
DANCE, H.C. Division of Project & Resident Programs 82/08/20
HANCOCK, J.A. Florida Power Corp. 2pp. 17635.231 24X
Fiche 50-302.82/09/24.8303210663

--8303210675 Notice of violation from Insp on 820720-23.
* Region 2, Office of Director 82/08/20 1p. 17635.233 24X
Fiche 50-302.82/09/24.8303210663

8303210682 IE Insp Rept 50-302/82-15 on 820720-23. Noncompliance noted: failure to establish measures for maint of quality records.
KLEINSORGE, W.P. Region 2, Office of Director ECONOMOS, N. Division of Engineering & Radiological Safety Programs 82/08/16 12pp.
17635.234 24X Fiche 50-302.82/09/24.8303240663

8303210731 Responds to NRC 821228 ltr re violations noted in IE Insp Rept 50-302/82-20. Corrective actions detailed review of all document control procedures initiated to ensure procedures meet intent of ANSI N45.2.9.
WESTAFER, G.R. Florida Power Corp. 83/01/20 O'REILLY, J.P. Region 2, Office of Director 2pp. 17635.294 24X Fiche 50-302.83/01/20.
8303210731

8303010245 Forwards IE Insp Rept 50-302/83-01 on 830110-14. No noncompliance noted.
DANCE, H.C. Division of Project & Resident Programs 83/02/10
HANCOCK, J.A. Florida Power Corp. 2pp. 17335.167 24X
Fiche 50-302.83/02/10.8303010245

--8303010251 IE Insp Rept 50-302/83-01 on 830110-14. No noncompliance noted. Major areas inspected: radiation protection, including ALARA program, training, reviews & audits, external exposure control, instrument calibr & followup on LERs.
KAHLE, J.B., BARR, K.P. Division of Project & Resident Programs 83/02/04 1pp. 17335.169 24X Fiche 50-302.83/02/10.8303010245

8303020214 Approves use of Section XI of Summer 1976 addenda of ASME Boiler & Pressure Vessel Code re requirements for visual & volumetric insp of reactor vessel & head cladding.
STOLZ, J.F. Operating Reactors Branch 4 83/02/22 HANCOCK, J.A. Florida Power Corp. 3pp. 17357.360 24X Fiche 50-302.83/02/22.
8303020214

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc.
11lpp. 17521.001 24X Fiche 50-000.83/02/25.8212060367.

8303040544 Forwards "B&W 177 Fuel Assembly Owners Group Safe End Task Force Rept on Generic Investigation of HPI/MU Nozzle Component Cracking," per util 830121 commitment. Thermal sleeves in HPI sys will be inspected during Refuel IV.
WESTAFER, G.R. Florida Power Corp. 83/02/28 STOLZ, J.F. Operating Reactors Branch 4 2pp. 17374.066 24X Fiche 50-302.83/02/28.
8303040544.

8303210599 Forwards IE Enforcement Meeting Rept 50-302/83-02 on 830124. No noncompliance noted.
O'REILLY, J.P. Region 2, Office of Director 83/02/28 HANCOCK, J.A. Florida Power Corp. 2pp. 17636.322 24X Fiche 50-302.83/02/28.
8303210599.

--8303210612 IE Enforcement Meeting Rept 50-302/83-02 on 830124. No noncompliance noted. Major items discussed: 821028 operational mode change, 821105 nonfunctional fire barrier, 821111 maint procedure control & 821207 inadequate boron injection path.
DANCE, H.C. Division of Project & Resident Programs 83/02/25
4pp. 17636.324 24X Fiche 50-302.83/02/28.8303210599.

8303040276 Requests submittal of applicable fee for 820827 request for relief from ASME Section XI requirements re reactor vessel insps within 15 days.
MILLER, W.D. License Fee Management Branch 83/03/01 HANCOCK, J.A. Florida Power Corp. 1p. 17426.354 24X Fiche 50-302.83/03/01.
8303040276.

8303210415 Ack receipt of 820924, 830130 & 0216 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-302/82-15 & 50-302/82-20.
DANCE, H.C. Division of Project & Resident Programs 83/03/03
HANCOCK, J.A. Florida Power Corp. 1p. 17634.335 24X
Fiche 50-302.83/03/03.8303210415

8303110234 Responds to IE Bulletin 83-01 re failure of reactor trip breakers (Westinghouse DB-50). Breakers w/undervoltage trip attachment not used in safety-related sys.
WESTAFER, G.R. Florida Power Corp. 83/03/04 O'REILLY, J.P. Region 2, Office of Director 2pp. 17520.115 24X Fiche 50-302.83/03/04.
8303110234

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc.
117pp. 17611.070 24X Fiche 50-000.83/03/11.8212060380

8303170319 Requests waiver from Subarticles IWA-4210 & IWA-4240, 1974 edition through Summer 1975 addenda of Section XI to ASME Code re inservice insp. Listed subarticles of 1977 edition through Summer 1978 addenda contain more accurate info.
WESTAFER, R. Florida Power Corp. 83/03/14 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp. 17605.160 24X
Fiche 50-302.83/03/14.8303170319.

8303170492 Requests relief from ASME Section XI requirement for volumetric exam of reactor vessel nozzle welds until end of 10-yr insp interval. Visual insp of interior vessel cladding will be performed during upcoming refueling outage.
WESTAFER, G.R. Florida Power Corp. 83/03/14 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 9pp. 17610.312 24X
Fiche 50-302.83/03/14.8303170492.

8303180328 Forwards fee in response to NRC 830301 ltr re 820827 application concerning relief from requirements of ASME Section XI for visual & volumetric insps of reactor vessel & head cladding.
WESTAFER, G.R. Florida Power Corp. 83/03/14 MILLER, W.D. License Fee Management Branch 1p. 17619.340 24X Fiche 50-302.83/03/14.
8303180328.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche 50-000.83/03/18.8212060383.

8303220095 Provides fee to cover 830314 request for relief from ASME Section XI, Article IWB-2000 re reactor vessel nozzle insps.
WESTAFER, G.R. Florida Power Corp. 83/03/18 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p. 17650.075 24X
Fiche 50-302.83/03/18.8303220095.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21 Consolidated Edison Co. of New York, Inc. 12lpp. 17774.352 24X Fiche 50-000.83/03/21.8212060387.

8303240098 Responds to IE Bulletin 83-04. "Failure of Undervoltage Trip Function of Reactor Trip Breakers (GE AK-2)." Surveillance tests of undervoltage trip function of reactor protection sys completed on 830303 & 04 w/no failures.
WESTAFER, G. R. Florida Power Corp. 83/03/21. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 5pp. 17681:035. 24X Fiche: 50-302, 83/03/21, 8303240098.

8303290477 Requests specific relief from ASME Boiler & Pressure Vessel Code Section XI re ultrasonic exam of reactor vessel. Proposed alternate exams & methods encl. Class III license amend fee encl.
WESTAFER, G. R. Florida Power Corp. 83/03/25. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 17724:327. 24X Fiche: 50-302, 83/03/25, 8303290477.

R. Periodic operating reports & related correspondence

8303080029 Forwards monthly operating rept for Jan 1983 & revised monthly operating rept for Dec 1982.
BAYNARD, P. Y. Florida Power Corp. 83/02/15. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 1p. 17457:001. 24X Fiche: 50-302, 83/02/15, 8303080029.

--8303080039 Monthly operating rept for Jan 1983.
BOGART, D. Florida Power Corp. 83/02/02. 4pp. 17457:002. 24X Fiche: 50-302, 83/02/15, 8303080029.

--8303080045 Revised monthly operating rept for Dec 1982.
BOGART, D. Florida Power Corp. 83/01/03. 4pp. 17457:006. 24X Fiche: 50-302, 83/02/15, 8303080029.

8303160318 Forwards monthly operating rept for Feb 1983.
WESTAFER, G. R. Florida Power Corp. 83/03/11. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 1p. 17596:044. 24X Fiche: 50-302, 83/03/11, 8303160318.

--8303160325 Monthly operating rept for Feb 1983.
BOGART, D. Florida Power Corp. 83/03/07. 4pp. 17596:045. 24X Fiche: 50-302, 83/03/11, 8303160318.

S. Reportable occurrences, LERs & related correspondence

8303010264 Forwards LER 83-004/03L-0.
HANCOCK, J. A. Florida Power Corp. 83/02/18. O'REILLY, J. P. Region 2, Office of Director. 1p. 17335:108. 24X Fiche: 50-302, 83/02/18, 8303010264.

--8303010269 LER 83-004/03L-0 on 830120, containment isolation valve CAV-6 determined inoperable. Containment penetration isolated & CAV-6 deactivated. Caused by weak valve operator spring. Spring will be replaced during next outage.
BUFE, J. Florida Power Corp. 83/02/18. Region 2, Office of Director. 2pp. 17335:109. 24X Fiche: 50-302, 83/02/18, 8303010264.

8303010272 Forwards LER 83-001/01T-1.
HANCOCK, J. A. Florida Power Corp. 83/02/18. O'REILLY, J. P. Region 2, Office of Director. 1p. 17335:093. 24X Fiche: 50-302, 83/02/18, 8303010272.

--8303010279 LER 83-001/01T-1 on 830106, determined that failure of radiation monitors A3, 4, 5, 7 & 8 to alarm in all failure modes constituted unreviewed safety question. Caused by design inadequacy. Engineering investigation performed.
HUGHES, P. G. Florida Power Corp. 83/02/18. Region 2, Office of Director. 2pp. 17335:094. 24X Fiche: 50-302, 83/02/18, 8303010272.

8303040430 Forwards LER 83-005/03L-0.
WESTAFER, G. R. Florida Power Corp. 83/02/24. O'REILLY, J. P. Region 2, Office of Director. 1p. 17370:295. 24X Fiche: 50-302, 83/02/24, 8303040430.

--8303040431 LER 83-005/03L-0 on 830125, 33-ft wind direction recorder declared inoperable. Wind speed & direction failures possibly caused by loose connector & wiring interference. Out of tolerance due to instrument drift.
PERRY, D. N. Florida Power Corp. 83/02/24. Region 2, Office of Director. 3pp. 17370:296. 24X Fiche: 50-302, 83/02/24, 8303040430.

8303100200 Forwards 830228 response to EPA show cause order re 830110 incident concerning discharge from outfall 007, regeneration waste neutralization tank, exceeding daily limit for oil & grease.
WESTAFER, G. R. Florida Power Corp. 83/03/03. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 11pp. 17492:016. 24X Fiche: 50-302, 83/03/03, 8303100200.

8303160471 Forwards LER 83-006/03L-0.
WESTAFER, G. R. Florida Power Corp. 83/03/04. O'REILLY, J. P. Region 2, Office of Director. 1p. 17592:350. 24X Fiche: 50-302, 83/03/04, 8303160471.

--8303160483 LER 83-006/03L-0 on 830203, during control rod exercise surveillance, absolute position indication for rod 6, group 2 failed to indicate +/-2% motion per Tech Spec requirements. Caused by failed reed switch. Tube replaced.
BUFE, J. Florida Power Corp. 83/03/04. Region 2, Office of Director. 2pp. 17592:351. 24X Fiche: 50-302, 83/03/04, 8303160471.

8303180185 Forwards LER 83-008/03L-0.
WESTAFER, G. R. Florida Power Corp. 83/03/11. O'REILLY, J. P. Region 2, Office of Director. 1p. 17617:260. 24X Fiche: 50-302, 83/03/11, 8303180185.

--8303180199 LER 83-008/03L-0 on 830211, absolute position indication for rod 1, group 1, failed to indicate +/- 2% motion. Caused by failed reed switch. Rod position verified via zone ref. Position indicator tube containing faulty switch replaced.
BUFE, J. Florida Power Corp. 83/03/11. Region 2, Office of Director. 2pp. 17617:261. 24X Fiche: 50-302, 83/03/11, 8303180185.

8303180253 Forwards LER 83-007/03L-0.
WESTAFER, G. R. Florida Power Corp. 83/03/11. O'REILLY, J. P. Region 2, Office of Director. 1p. 17621:088. 24X Fiche: 50-302, 83/03/11, 8303180253.

--8303180260 LER 83-007/03L-0 on 830209, reactor bldg pressure indicator discovered inoperable. Caused by instrument drift. Transmitter recalibr. Pressure transmitters will be replaced during next refueling outage.
BUFE, J. L. Florida Power Corp. 83/03/11. Region 2, Office of Director. 1p. 17621:089. 24X Fiche: 50-302, 83/03/11, 8303180253.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8303140270 Forwards IE Insp Repts 50-295/83-01 & 50-304/83-01 on 830117-20. No noncompliance noted.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 83/02/11. REED, C. Commonwealth Edison Co. 3pp. 17543:351. 24X Fiche: 50-295, 83/02/11, 8303140270.

--8303140314 IE Insp Repts 50-295/83-01 & 50-304/83-01 on 830117-20. No noncompliance noted. Major areas inspected: emergency preparedness exercise involving observations of key functions & locations during exercise.
PHILLIPS, M. P., SMITH, M. J., LICKUS, R. M. Region 3, Office of Director. 83/02/09. 9pp. 17543:354. 24X Fiche: 50-295, 83/02/11, 8303140270.

8303010595 Ack receipt of 830124 ltr identifying 1983 dates for emergency preparedness exercises within State of IL. Dates determined to be within required exercise frequency.
HIND, J. A. Region 3, Office of Director. 83/02/24. JONES, E. E. Illinois, State of. 2pp. 17336:208. 24X Fiche: 50-000, 83/02/24, 8303010595.

--8303010618 Submits 1983 dates scheduled for emergency preparedness exercises for facilities within State of IL.
JONES, E. E. Illinois, State of. 83/01/24. KEPPLER, J. Region 3, Office of Director. 2pp. 17336:210. 24X Fiche: 50-000, 83/02/24, 8303010595.

8303040489 Forwards info re proposed installation mod of instrumentation to monitor source range neutron flux & cold leg temp at remote shutdown panel to complete util compliance w/App R to 10CFR50 re fire protection.
LENTINE, F. G. Commonwealth Edison Co. 83/02/25. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 17373:354. 24X Fiche: 50-295, 83/02/25, 8303040489.

8303140296 Ack receipt of 830210 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-295/82-31 & 50-304/82-28.
MILLER, J. R. Region 3, Office of Director. 83/03/07. REED, C. Commonwealth Edison Co. 1p. 17535:043. 24X Fiche: 50-295, 83/03/07, 8303140296.

--8303140304 Responds to NRC 830111 ltr re violations noted in IE Safeguards Insp Repts 50-295/82-31 & 50-304/82-28. Corrective actions withheld (ref 10CFR73.21).
FARRAR, D. L. Commonwealth Edison Co. 83/02/10. KEPPLER, J. G. Region 3, Office of Director. 1p. 17535:044. 24X
Fiche: 50-295, 83/03/07, 8303140296.

8303230102 Forwards exemption from requirements of 10CFR50, App R, Item III. G. 2 re cable trains & equipment necessary to achieve & maintain safe shutdown.
VARGA, S. A. Operating Reactors Branch 1. 83/03/07. FARRAR, D. L. Commonwealth Edison Co. 2pp. 17687:129. 24X Fiche: 50-295, 83/03/07, 8303230102.

--8303230107 Exemption from requirements of 10CFR50, App R, Item III. G. 2 re equipment necessary to achieve & maintain safe shutdown.
EISENHUT, D. G. Division of Licensing. 83/03/07. Commonwealth Edison Co. 4pp. 17687:131. 24X Fiche: 50-295, 83/03/07, 8303230102.

--8303230111 Safety evaluation supporting exemption from requirements of 10CFR50, App R, Item III. G. 2 re equipment necessary to achieve & maintain safe shutdown.
* Office of Nuclear Reactor Regulation, Director. 83/03/07. 22pp. 17687:135. 24X Fiche: 50-295, 83/03/07, 8303230102.

8303300248 Summarizes review of licensee 820416, 0702 & 30 descriptions of safe shutdown in event of fire & proposed mods to meet App R to 10CFR50, Items III. G. 3 & III. L. Facility in compliance w/App R.
VARGA, S. A. Operating Reactors Branch 1. 83/03/17. FARRAR, D. L. Commonwealth Edison Co. 2pp. 17751:358. 24X Fiche: 50-295, 83/03/17, 8303300248.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director. 83/03/22. Commonwealth Edison Co. 2pp. 17690:316. 24X Fiche: 50-000, 83/03/22, 8303240440.

8303310124 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/25. Document Management Branch. 1p. 17775:184. 24X Fiche: 50-000, 83/03/25, 8303310124.

--8303310130 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure EG-1, "Coordination of Environs Group Activities by Environs Director."
* Commonwealth Edison Co. 83/03/17. Director's Office, Office of Inspection and Enforcement. 1p. 17775:185. 24X
Fiche: 50-000, 83/03/25, 8303310124.

--8303310146 Public version of Rev 3 to Emergency Plan Implementing Procedure EG-1, "Coordination of Environs Group Activities by Environs Director."
PAJOWSKI, J. E. Commonwealth Edison Co. 83/03/08. 87pp. 17775:186. 24X Fiche: 50-000, 83/03/25, 8303310124.

8303300532 Releases public version of request for return of listed controlled copies of emergency plan.
FELTON, J. M. Division of Rules and Records. 83/03/28. Document Management Branch. 1p. 17763:178. 24X Fiche: 50-000, 83/03/28, 8303300532.

--8303300561 Submits public version of request for return of listed controlled copies of emergency plan.
FLESSNER, R. A. Commonwealth Edison Co. 83/03/15. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17763:179. 24X Fiche: 50-000, 83/03/28, 8303300532.

8303300718 Releases public version of rev to emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/28. Document Management Branch. 1p. 17763:358. 24X Fiche: 50-295, 83/03/28, 8303300718.

--8303300722 Public version of Rev 2 to Emergency Plan Implementing Procedure EPIP 1801-1, "Rad/Chem Director EPIP." Revised index encl.
* Commonwealth Edison Co. 83/02/23. 5pp. 17763:360. 24X
Fiche: 50-295, 83/03/28, 8303300718.

8303310004 Releases public version of rev to emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/28. Document Management Branch. 1p. 17777:355. 24X Fiche: 50-295, 83/03/28, 8303310004.

--8303310005 Public version of Rev 2 to Emergency Plan Implementing Procedure EPIP 360-1, "Site Evacuation of Nonessential Personnel."
* Commonwealth Edison Co. 83/02/23. 4pp. 17777:356. 24X
Fiche: 50-295, 83/03/28, 8303310004.

## G. Adjudicatory correspondence

8303150143 Forwards Director's Decision DD-83-4, denying 821011 petition to deny Comm Ed permission to use high burnup nuclear fuel & provide evidence to public re continued operation despite reactor vessel embrittlement.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 83/03/01. GUIDO, C. Pollution & Environmental Problems, Inc. 2pp. 17585:001. 24X Fiche: 50-295, 83/03/01, 8303150143.

--8303150153 Director's Decision DD-83-4 denying Pollution & Environ Problems, Inc 821011 petition to deny util use of high burnup fuel & provide evidence for continued safe operation despite reactor vessel embrittlement.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 83/03/01. 8pp. 17585:003. 24X Fiche: 50-295, 83/03/01, 8303150143.

--8303150161 Notice of issuance of Director's Decision DD-83-4 under 10CFR2.206 denying Pollution & Environ Problems, Inc 821011 petition.
CASE, E. G. Office of Nuclear Reactor Regulation, Director. 83/03/01. 4pp. 17585:011. 24X Fiche: 50-295, 83/03/01, 8303150143.

--8303150223 Forwards Pollution & Environ Problems, Inc 821011 petition seeking denial of Comm Ed request to use high burnup nuclear fuel & requesting NRC provide evidence to public that reactors are able to withstand embrittlement.
LIEBERMAN, J. Regional Operations & Enforcement Division, 92/11/05. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 5pp. 17586:160. 24X Fiche: 50-295, 83/03/01, 8303150143.

8303300362 Advises that time for Commission to review Director's Decision DD-83-4 expired. Commission declined review. Decision became final agency action on 830328.
CHILK, S. J. Office of the Secretary of the Commission. 83/03/29. GUIDO, C. Pollution & Environmental Problems, Inc. 1p. 17734:194. 24X Fiche: 50-295, 83/03/29, 8303300362.

## H. General correspondence

8303030528 Informs that DL Farrar has replaced LD DelGeorge as Director of Nuclear Licensing for util. Rev of current NRC distribution list requested.
FARRAR, D. L. Commonwealth Edison Co. 83/02/02. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17409:048. 24X
Fiche: 50-000, 83/02/02, 8303030528.

## I. Financial information

8303070135 Forwards Annual Financial Rept 1982.
BRESEMANN, R. W. Commonwealth Edison Co. 83/02/28. Division of Licensing. 1p. 17433:001. 24X Fiche: 50-000, 83/02/28, 8303070135.

--8303070151 Annual Financial Rept 1982.
O'CONNOR, J. J. Commonwealth Edison Co. 83/02/03. 13pp. 17433:002. 24X Fiche: 50-000, 83/02/28, 8303070135.

## P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303090285 Requests assessment of operability of large diameter Pratt purge & vent valves & intentions on maintaining purge & vent valves sealed closed, per SRP Section 6.2.4 & II.6.f, within 15 days. Background info encl.
VARGA, S. A. Operating Reactors Branch 1. 83/02/16. FARRAR, D. L. Commonwealth Edison Co. 5pp. 17484:298. 24X Fiche: 50-295, 83/02/16, 8303090285.

8303080269 Advises that reload safety evaluation demonstrates that Tech Spec changes & OL amend not required for operation during Cycle 7. New dropped rod accident evaluation encl.
LENTINE, F. G. Commonwealth Edison Co. 83/02/25. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 17454:294. 24X
Fiche: 50-304, 83/02/25, 8303080269.

8303110002 Forwards Amends 81 & 71 to Licenses DPR-39 & DPR-48, respectively, safety evaluation & notice of issuance & availability. Amends change designation numbers for reactor coolant pump undervoltage devices.
NORRIS, J. Operating Reactors Branch 1. 83/02/25. FARRAR, D. L. Commonwealth Edison Co. 2pp. 17546:276. 24X Fiche: 50-295, 83/02/25, 8303110002.

--8303110003 Amends 81 & 71 to Licenses DPR-39 & DPR-48, respectively, revising Tech Specs to change designation numbers for reactor coolant pump undervoltage devices & reduce frequency of channel functional testing.
VARGA, S. A. Operating Reactors Branch 1. 83/02/25. 11pp. 17546:278. 24X Fiche: 50-295, 83/02/25, 8303110002.

--8303110012 Safety evaluation supporting Amends 81 & 71 to Licenses DPR-39 & DPR-48, respectively.
* Office of Nuclear Reactor Regulation, Director. 83/02/25. 2pp. 17546:289. 24X Fiche: 50-295, 83/02/25, 8303110002.

--8303110018 Notice of issuance & availability of Amends 81 & 71 to Licenses DPR-39 & DPR-48, respectively.
VARGA, S. A. Operating Reactors Branch 1. 83/02/25. 2pp. 17546:291. 24X Fiche: 50-295, 83/02/25, 8303110002.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303080328 Submits addl info in response to NRC concerns re operability of large diameter (>4") butterfly valves. Util does not intend to maintain valves closed in modes other than cold shutdown & refueling.
LENTINE, F. G. Commonwealth Edison Co. 83/03/03. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 17447:350. 24X Fiche: 50-295, 83/03/03, 8303080328.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J. G. Region 3, Office of Director. 83/03/03. Commonwealth Edison Co. 2pp. 17492:014. 24X Fiche: 50-000, 83/03/03, 8303100364.

8303100348 Supplis 830114 ltr providing justification for continued operation per SER on environ qualification of electrical equipment. Discussion of addl post-accident monitoring requirements for transmitters encl.
LENTINE, F. G. Commonwealth Edison Co. 83/03/04. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 17488:348. 24X Fiche: 50-295, 83/03/04, 8303100348.

8303100507 Requests remittance of fee for 801107 Tech Spec change request re DHR capability, per 10CFR170.22. Fee due within 15 days of ltr receipt.
MILLER, W. O. License Fee Management Branch. 83/03/04.
DELGEORGE, L. O. Commonwealth Edison Co. 1p. 17521:328. 24X Fiche: 50-295, 83/03/04, 8303100507.

8303110246 Forwards Rev 23 to CE-1-A, "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/04. HAASS, W. P. Quality Assurance Branch. 1p. 17515:357. 24X Fiche: 50-000, 83/03/04, 8303110246.

--8303110279 Rev 23 to "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments.
SHEWSKI, W. J. Commonwealth Edison Co. CE-1-A R23. 83/03/07. 5pp. 17515:358. 24X Fiche: 50-000, 83/03/04, 8303110246.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303170125 Summary of 830228 meeting w/licensee re PWR neutronic methodology program proposed for use in fuel reload reviews. Approval requested to perform neutronics calculations in-house & for Westinghouse to continue accident analyses.
WIGGINTON, D. L. Operating Reactors Branch 1. 83/03/07. Operating Reactors Branch 1. 42pp. 17615:290. 24X Fiche: 50-295, 83/03/07, 8303170125.

8303220081 Forwards response to Generic Ltr 82-28, "Inadequate Core Cooling Instrumentation Sys," per 10CFR50.54(f).
LENTINE, F. G. Commonwealth Edison Co. 83/03/10. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 46pp. 17652:214. 24X Fiche: 50-295, 83/03/10, 8303220081.

8303290836 Advises that Tech Specs should be changed to reflect manual initiated operating bypass of protection sys channels. Tech Specs should explicitly identify conditions where operating bypasses will block ESF channels.
VARGA, S. A. Operating Reactors Branch 1. 83/03/11. FARRAR, D. L. Commonwealth Edison Co. 4pp. 17748:045. 24X Fiche: 50-295, 83/03/11, 8303290836.

8303210325 Responds to NRC 830204 request for addl info re control room review. Response specifically answers discrepancies re defeat of nuisance alarms, prioritization of multiple alarms & communications w/breathing apparatus.
STIEDE, W. L. Commonwealth Edison Co. 83/03/15. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 5pp. 17632:123. 24X Fiche: 50-295, 83/03/15, 8303210325.

8303220256 Advises that util will not provide 90-day response to NRC 821214 ltr. Requirement to identify equipment already qualified & to submit plans & schedules for qualification or replacement of remaining equipment will be fulfilled 830520.
LENTINE, F. G. Commonwealth Edison Co. 83/03/17. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17656:278. 24X Fiche: 50-295, 83/03/17, 8303220256.

8303300165 Forwards complete copy of encls to 830208 ltr requesting addl info on NUREG-0737, Items II.F.1.4, "Containment Pressure Monitor," II.F.1.5, "Containment Water Level Monitor" & II.F.1.6, "Containment Hydrogen Monitor."
VARGA, S. A. Operating Reactors Branch 1. 83/03/17. FARRAR, D. L. Commonwealth Edison Co. 10pp. 17763:105. 24X Fiche: 50-295, 83/03/17, 8303300165.

8303240319 Responds to NRC 830311 ltr requesting rev to Tech Spec re blocking of safety injection signals during cooldown. Third page of Table 3.4.1 contains necessary provisions. Rev to Tech Specs not required.
LENTINE, F. G. Commonwealth Edison Co. 83/03/18. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17679:352. 24X Fiche: 50-295, 83/03/18, 8303240319.

8303280062 Requests itemized bill of actual fees paid for review of proposed Amends 65 & 62. Review of application should be administrative or pro forma in nature since model Tech Specs adopted. Addl fees unjustified.
LENTINE, F. G. Commonwealth Edison Co. 83/03/18. MILLER, W. O. License Fee Management Branch. 4pp. 17707:278. 24X Fiche: 50-295, 83/03/18, 8303280062.

8303290033 Requests util incorporate responses to NRC QA Questions 1 through 51 & staff positions in Topical Rept CE-1-A, "QA Program." Util alternate approach to Staff Position A acceptable.
VARGA, S. A. Operating Reactors Branch 1. 83/03/21. FARRAR, D. L. Commonwealth Edison Co. 3pp. 17729:294. 24X Fiche: 50-295, 83/03/21, 8303290033.

8303280112 Forwards SER re NUREG-0737, Item II.B.2.2, "Design Review of Plant Shielding-Access to Vital Areas."
NOREL(US), C. E. Division of Project & Resident Programs. 83/03/24.
EISENHUT, D. G. Division of Licensing. 3pp. 17709:340. 24X Fiche: 50-295, 83/03/24, 8303280112.

8303280270 Requests that petition for hearing on environ qualification of safety-related electrical equipment be withdrawn based on listed interpretations. Significant improvements in final rule 10CFR50.49 obviate hearings.
STEPTOE, P. P. Isham, Lincoln & Beale. 83/03/24. EISENHUT, D. G. Division of Licensing. 2pp. 17706:289. 24X Fiche: 50-000, 83/03/24, 8303280270.

8303290526 Provides schedule for resolution of TMI Action Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps," in response to Generic Ltrs 83-10c & 83-10d. Info will be provided by 830423 based on Westinghouse Owners Group input.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/24. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17724:161. 24X Fiche: 50-000, 83/03/24, 8303290526.

## Q. Inspection reports, IE Bulletins & correspondence

8303170501 Forwards IE Insp Repts 50-295/82-28 & 50-304/82-25 on 821202-830117. No noncompliance noted.
STREETER, J. F. Division of Project & Resident Programs. 83/02/09.
REED, C. Commonwealth Edison Co. 2pp. 17610:219. 24X Fiche: 50-295, 83/02/09, 8303170501.

8303170506 IE Insp Repts 50-295/82-28 & 50-304/82-25 on 821202-830117. No noncompliance noted. Major areas inspected: previous insp items, unit startup w/penetration pressurization air compressor out of svc & spent fuel shipment.
WATERS, J. R., DUNAWAY, F. R., HARTMAN, P. L. Region 3, Office of Director. 83/02/07. 14pp. 17610:221. 24X Fiche: 50-295, 83/02/09, 8303170501.

8303140270 Forwards IE Insp Repts 50-295/83-01 & 50-304/83-01 on 830117-20. No noncompliance noted.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 83/02/11. REED, C. Commonwealth Edison Co. 3pp. 17543:351. 24X Fiche: 50-295, 83/02/11, 8303140270.

--8303140314 IE Insp Repts 50-295/83-01 & 50-304/83-01 on 830117-20. No noncompliance noted. Major areas inspected: emergency preparedness exercise involving observations of key functions & locations during exercise.
PHILLIPS, M. P., PLOSKI, T. J., PATTERSON, J. P. Region 3, Office of Director. 83/02/09. 9pp. 17543:354. 24X Fiche: 50-295, 83/02/11, 8303140270.

8303040566 Forwards IE Insp Repts 50-295/82-24 & 50-304/82-21 on 820920-22 & 1214-16. No noncompliance noted.
LITTLE, W. S. Division of Engineering. 83/02/15. REED, C. Commonwealth Edison Co. 2pp. 17374:168. 24X Fiche: 50-295, 83/02/15, 8303040566.

--8303040574 IE Insp Repts 50-295/82-24 & 50-304/82-21 on 820920-22 & 1214-16. No noncompliance noted. Major areas inspected: allegations re improper stress relieving of steam generators & unnecessary personnel exposure to radiation.
KEY, W. J., MILLER, D. E. Region 3, Office of Director. DANIELSON, D. H. Division of Engineering. 83/02/15. 8pp. 17374:170. 24X Fiche: 50-295, 83/02/15, 8303040566.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8302280356 Ack receipt of 830216 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/82-20 & 50-304/82-18.
SPESSARD, R. L. Division of Engineering. 83/02/25. REED, C. Commonwealth Edison Co. 1p. 17311:082. 24X Fiche: 50-295, 83/02/25, 8302280356.

--8302280361 Responds to NRC 830114 ltr re violations noted in IE Insp Repts 50-295/82-20 & 50-304/82-18. Failure to perform required surveillance isolated incident. Existing procedural controls adequate.
FARRAR, D. L. Commonwealth Edison Co. 83/02/16. KEPPLER, J. G. Region 3, Office of Director. 2pp. 17311:083. 24X Fiche: 50-295, 83/02/25, 8302280356.

8303170532 Forwards IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al. on 830126. No noncompliance noted.
DAVIS, A. B. Region 3, Office of Director. 83/02/25. REED, C. Commonwealth Edison Co. 2pp. 17610:143. 24X Fiche: 50-000, 83/02/25, 8303170532.

--8303170557 IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al. on 830126. No noncompliance noted. Major areas discussed: proposed guidelines util personnel should use for providing info to Region III inspectors.
GOLDEMOND, W. G. Division of Project & Resident Programs. 83/02/15. 4pp. 17610:145. 24X Fiche: 50-000, 83/02/25, 8303170532.

8303030438 Clarifies NRC position re procedures for admitting NRC personnel to facilities. Lists of NRC inspectors & personnel likely to visit facility two or more times per yr & at anytime encl. Lists will be updated every 6 months.
KEPPLER, J. G. Region 3, Office of Director. 83/02/28. REED, C. Commonwealth Edison Co. 6pp. 17410:101. 24X Fiche: 50-295, 83/02/28, 8303030438.

8303080184 Forwards corrected second page to 830209 ltr transmitting IE Insp Repts 50-295/82-28 & 50-304/82-25. Rept numbers incorrectly stated. Incorrect page should be removed.
STREETER, J. F. Division of Project & Resident Programs. 83/03/02. REED, C. Commonwealth Edison Co. 2pp. 17457:341. 24X Fiche: 50-295, 83/03/02, 8303080184.

8303070036 Forwards responses to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Bunker-Ramo electrical penetrations installed in LaSalle Unit 2, Byron Unit 2 & Braidwood Unit 2.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/03. KEPPLER, J. G. Region 3, Office of Director. 13pp. 17435:290. 24X Fiche: 50-000, 83/03/03, 8303070036.

8303110284 Responds to IE Bulletin 83-01 re failure of reactor trip breakers. Surveillance test of undervoltage trip performed on Unit 1 on 830225. All licensed operators being notified of Salem event during shift meeting.
LENTINE, F. G. Commonwealth Edison Co. 83/03/07. KEPPLER, J. G. Region 3, Office of Director. 3pp. 17517:347. 24X Fiche: 50-295, 83/03/07, 8303110284.

8303140296 Ack receipt of 830210 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-295/82-31 & 50-304/82-28.
MILLER, J. R. Region 3, Office of Director. 83/03/07. REED, C. Commonwealth Edison Co. 1p. 17535:043. 24X Fiche: 50-295, 83/03/07, 8303140296.

--8303140304 Responds to NRC 830111 ltr re violations noted in IE Safeguards Insp Repts 50-295/82-31 & 50-304/82-28. Corrective actions withheld (ref 10CFR73.21).
FARRAR, D. L. Commonwealth Edison Co. 83/02/10. KEPPLER, J. G. Region 3, Office of Director. 1p. 17535:044. 24X Fiche: 50-295, 83/03/07, 8303140296.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17771:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303310211 Forwards addl info in response to IE Bulletin 81-03 re methods to control Corbicula. "Environ Studies of Braidwood Cooling Pond, 1982," encl.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/28. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 17pp. 17755:095. 24X Fiche: 50-000, 83/03/28, 8303310211.

R Periodic operating reports & related correspondence

8303280293 Forwards Part 1 of "Radioactive Effluent Monitoring Rept, Jan-June 1982."
GRAESSER, K. L. Commonwealth Edison Co. 82/08/15. KEPPLER, J. G. Region 3, Office of Director. 1p. 17705:271. 24X Fiche: 50-295, 82/08/15, 8303280293.

--8303280299 Part 1 of "Radioactive Effluent Monitoring Rept Jan-June 1982."
* Commonwealth Edison Co. 82/08/15. 49pp. 17705:272. 24X Fiche: 50-295, 82/08/15, 8303280293.

8303150349 Forwards monthly operating repts for Feb 1983.
GRAESSER, K. L. Commonwealth Edison Co. 83/03/07. Director's Office, Office of Inspection and Enforcement. 1p. 17563:004. 24X Fiche: 50-295, 83/03/07, 8303150349.

--8303150354 Monthly operating repts for Feb 1983.
AUSTIN, G. Commonwealth Edison Co. 83/03/07. 11pp. 17563:005. 24X Fiche: 50-295, 83/03/07, 8303150349.

S Reportable occurrences, LERs & related correspondence

8303140550 Forwards LER 83-004/03L-0.
GRAESSER, K. L. Commonwealth Edison Co. 83/03/04. KEPPLER, J. G. Region 3, Office of Director. 1p. 17541:043. 24X Fiche: 50-304, 83/03/04, 8303140550.

--8303140563 LER 83-004/03L-0 on 830210, electric penetration zone 1 line pressure dropped below 47 psig due to blown rupture disc. Caused by operator error. Rupture disc replaced.
SHIM, K. Commonwealth Edison Co. 83/03/04. Region 3, Office of Director. 1p. 17541:044. 24X Fiche: 50-304, 83/03/04, 8303140550.

8303140587 Forwards LER 83-005/03L-0.
GRAESSER, K. L. Commonwealth Edison Co. 83/03/04. KEPPLER, J. G. Region 3, Office of Director. 1p. 17534:019. 24X Fiche: 50-304, 83/03/04, 8303140587.

--8303140595 LER 83-005/03L-0 on 830212, electric penetration zone 1 line pressure dropped below 47 psig due to blown rupture disc. Caused by operator error. Rupture disc replaced.
SHIM, K. Commonwealth Edison Co. 83/03/04. Region 3, Office of Director. 1p. 17534:020. 24X Fiche: 50-304, 83/03/04, 8303140587.

8303140516 Forwards LER 83-006/03L-0.
QRAESSER, K. L. Commonwealth Edison Co. 83/03/08. KEPPLER, J. G. Region 3, Office of Director. 1p. 17540:343. 24X Fiche: 50-304, 83/03/08, 8303140516.

--8303140535 LER 83-006/03L-0 on 830207, heat trace failure alarm found on primary heat trace on line from boric acid filter to boric acid supply line. Caused by breaker to primary circuit inadvertently turned off. Trace re-energized.
KAPLAN, S. A. Commonwealth Edison Co. 83/03/08. Region 3, Office of Director. 1p. 17540:344. 24X Fiche: 50-304, 83/03/08, 8303140516.

8303170335 Forwards LER 83-007/01T-0.
QRAESSER, K. L. Commonwealth Edison Co. 83/03/09. KEPPLER, J. G. Region 3, Office of Director. 1p. 17605:172. 24X Fiche: 50-304, 83/03/09, 8303170335.

--8303170354 LER 83-007/01T-0 on 830131, diesel generator D failed to accept load greater than 50% during operability check. Caused by Cooper-Bessemer turbo charger MDL seizure. Turbo replaced & diesel generator tested satisfactorily.
FANNING, G. Commonwealth Edison Co. 83/03/09. Region 3, Office of Director. 1p. 17605:173. 24X Fiche: 50-304, 83/03/09, 8303170335.

8303220235 PNO-III-83-018 on 830228, contractor employee gained unauthorized entry to protected & vital plant areas. Two contractor employees terminated for violating security requirements & security guard for failure to take action.
CREED, J. ; MILLER, J. Region 3, Office of Director. 83/03/16. 1p. 17656:260. 24X Fiche: 50-295, 83/03/16, 8303220235.

8303240198 Forwards LER 83-006/03L-0.
QRAESSER, K. L. Commonwealth Edison Co. 83/03/17. KEPPLER, J. G. Region 3, Office of Director. 1p. 17682:181. 24X Fiche: 50-304, 83/03/17, 8303240198.

--8303240212 LER 83-008/03L-0 on 830215, steam generator 2C steam flow channel 2FT-522 drifted low w/respect to redundant indication. Caused by zero shift on transmitter 2FT-522. Transmitter recalibr.
CANTWELL, P. F. Commonwealth Edison Co. 83/03/17. Region 3, Office of Director. 1p. 17682:182. 24X Fiche: 50-304, 83/03/17, 8303240198.

## V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303040631 Forwards listing of projected operator licensing exam dates including type of exam & probable number of candidates, in response to 830111 Generic Ltr 83-01.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/01. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 17367:209. 24X Fiche: 50-000, 83/03/01, 8303040631.

## DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT

## F. Security, medical, emergency & fire protection plans

8303030535 Forwards IE Insp Rept 50-305/83-02 on 830207-11. No noncompliance noted.
MILLER, J. R. Region 3, Office of Director. 83/02/25. GIESLER, C. W. Wisconsin Public Service Corp. 2pp. 17409:043. 24X Fiche: 50-305, 83/02/25, 8303030535.

--8303030543 IE Insp Rept 50-305/83-02 on 830207-11. No noncompliance noted. Major areas inspected: security plan implementing procedures, physical barriers, assessment aids, access controls & detection aids. Details withheld (ref 10CFR73.21).
BELANGER, J. L. ; KNICELEY, J. R. ; CREED, J. R. Region 3, Office of Director. 83/02/25. 2pp. 17409:045. 24X Fiche: 50-305, 83/02/25, 8303030535.

8303090311 Responds to 820504 ltr re minor safeguards & administrative changes to industrial security manual, security contingency plan & security force training & qualification manual. Changes acceptable.
VARGA, S. A. Operating Reactors Branch 1. 83/02/25. GIESL, C. W. Wisconsin Public Service Corp. 2pp. 17484:240. 24X Fiche: 50-305, 83/02/25, 8303090311.

8303240092 Releases public version of revised radiological emergency response plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/21. Document Management Branch. 1p. 17694:065. 24X Fiche: 50-305, 83/03/21, 8303240092.

--8303240096 Forwards public version of revised radiological emergency response plan implementing procedures, including Procedure EP-SEC-2, "Security Force Response to Emergencies."
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/10.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17694:066. 24X Fiche: 50-305, 83/03/21, 8303240092.

--8303240102 Public version of revised radiological emergency response plan implementing procedures, including Procedure EP-SEC-2, "Security Force Response to Emergencies." Revised table of contents encl.
* Wisconsin Public Service Corp. 83/03/01. 35pp. 17694:068. 24X Fiche: 50-305, 83/03/21, 8303240092.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director. 83/03/22. Commonwealth Edison Co. 2pp. 17690:316. 24X Fiche: 50-000, 83/03/22, 8303240440.

## I. Financial information

8303220350 Forwards cash flow projection for 1983.
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/18. SALTZMAN, J. Assistant Director for State & Licensee Relations. 2pp. 17654:297. 24X Fiche: 50-305, 83/03/18, 8303220350.

## J. Insurance & indemnity information

8303220342 Forwards Endorsement 60 to NELIA Policy NF-204.
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/18. DINITZ, I. Antitrust & Economic Analysis Branch (Utility Finance). 2pp. 17648:029. 24X Fiche: 50-305, 83/03/18, 8303220342.

8303240247 Submits info re present levels of onsite property damage insurance per 10CFR50.54(W)(4). Total amount of insurance is $460 million plus addl amount up to $68 million for damage in excess of $500 million.
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/21. Office of Nuclear Reactor Regulation, Director. 1p. 17681:362. 24X Fiche: 50-305, 83/03/21, 8303240247.

## P. Operating license stage documents & correspondence

8303010117 Concurs partially w/801223 response to NRC 800410 request to include term "operable" in Tech Spec areas re single failure criterion of safety sys in power reactors. Reconsideration of encl model Tech Specs due in 90 days.
VARGA, S. A. Operating Reactors Branch 1. 83/02/14. GIESLER, C. W. Wisconsin Public Service Corp. 6pp. 17347:319. 24X Fiche: 50-305, 83/02/14, 8303010117.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303010277 Forwards reload safety evaluation for Cycle IX reload core. Core design more conservative than design utilized in accident analysis so no unreviewed safety question exists. Cycle IX startup testing scheduled for 830503.
GIESLER, C. W. Wisconsin Public Service Corp. 83/02/24. VARGA, S. A. Operating Reactors Branch 1. 1p. 17344:292. 24X Fiche: 50-305, 83/02/24, 8303010277.

--8303010292 "Reload Safety Evaluation, Kewaunee Cycle IX, Feb 1983."
HOLLY, J. T. ; ROPSON, D. J. ; SCHROCK, C. A. Wisconsin Public Service Corp. 83/02/28. 66pp. 17344:293. 24X Fiche: 50-305, 83/02/24, 8303010277.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp. 17760:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303080444 Advises that info on ability of auxiliary feedwater sys pumps to remain operable after extended operation at runout flow & on implementation of recommendations for sys will be provided by 830506.
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/02 VARGA, S. A. Operating Reactors Branch 1. 2pp. 17453:288. 24X
Fiche: 50-305, 83/03/02, 8303080444.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J. G. Region 3, Office of Director 83/03/03
Commonwealth Edison Co. 2pp. 17492:014. 24X Fiche: 50-000, 83/03/03, 8303100364.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5ipp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303100316 Forwards addl info requested in 830215 ltr re assessment of operability of 36-inch diameter vent & purge valves. Commitment to maintain valves sealed shut while above hot shutdown pending further investigation provided.
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/07 VARGA, S. A. Operating Reactors Branch 1. 4pp. 17486:262. 24X
Fiche: 50-305, 83/03/07, 8303100316.

8303210242 Forwards evaluation of deficiency found in containment cooling sys & proposed correction for guidance. Tech Specs should be reviewed & amend proposed within 60 days.
VARGA, S. A. Operating Reactors Branch 1. 83/03/07 GIESLER, C. W. Wisconsin Public Service Corp. 2pp. 17640:350. 24X
Fiche: 50-305, 83/03/07, 8303210242.

--8303210246 Evaluation of Tech Spec deficiencies re containment cooling sys operability. Tech Spec 3.3.3.2 should be modified to correct deficiencies.
* Containment Systems Branch 83/03/07 4pp. 1:640:352. 24X
Fiche: 50-305, 83/03/07, 8303210242.

8303140329 Application for amend to License DPR-43, requesting relief from performing exams of reactor coolant pump internal casing welds required by Section XI, Table IWB-2500 of ASME Code.
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/08
EISENHUT, D. G. Division of Licensing 3pp. 17534:199. 24X
Fiche: 50-305, 83/03/08, 8303140329.

8303140519 Confirms 830303 conversation re environ qualification of electrical equipment important to safety. Thirty-day response justifying continued operation, per 830202 request, will be superseded by revised transmittal ltr.
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/08 VARGA, S. A. Operating Reactors Branch 1. 1p. 17534:175. 24X
Fiche: 50-305, 83/03/09, 8303140519.

8303110373 Forwards "Nine-Month Response to Generic Ltr 81-07, NUREG-0612, Control of Heavy Loads."
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/09
EISENHUT, D. G. Division of Licensing 1p. 17506:307. 24X
Fiche: 50-305, 83/03/09, 8303110373.

--8303110377 "Nine-Month Response to Generic Ltr 81-07, NUREG-0612, Control of Heavy Loads."
* Wisconsin Public Service Corp. * Wisconsin Power & Light Co. * Madison Gas & Electric Co. 83/03/09 32pp. 17506:309. 24X
Fiche: 50-305, 83/03/09, 8303110373.

8303160315 Provides summary of three instruments which comprise inadequate core cooling sys to facilitate NRC review per Generic Ltr 82-28. Description of subcooling margin monitor encl.
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/09
EISENHUT, D. G. Division of Licensing 20pp. 17596:024. 24X
Fiche: 50-305, 83/03/09, 8303160315.

P303300180 Forwards order confirming util commitment to implement post-TMI-related items set forth in NUREG-0737 & Generic Ltrs 82-05 & 82-10.
VARGA, S. A. Operating Reactors Branch 1. 83/03/14 GIESLER, C. W. Wisconsin Public Service Corp. 2pp. 17754:346. 24X
Fiche: 50-305, 83/03/14, 8303300180.

--8303300191 Order confirming util commitment to implement post-TMI-related items set forth in NUREG-0737 & Generic Ltrs 82-05 & 82-10. Hearing may be requested within 20 days of order publication.
PURPLE, R. A. Division of Licensing 83/03/14 Wisconsin Public Service Corp. 8pp. 17754:348. 24X Fiche: 50-305, 83/03/14, 8303300180.

8303220335 Responds to 830203 Generic Ltr 83-10, Item D, requesting schedule for final resolution of NUREG-0737, Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps." Schedule for final resolution expected by 830615.
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/18
EISENHUT, D. G. Division of Licensing 1p. 17656:147. 24X
Fiche: 50-305, 83/03/18, 8303220335.

8303310016 Clarifies 830202 environ qualification SER based on Franklin Research Ctr technical evaluation rept (TER). App. D to TER not applicable to all deficiencies listed in TER. Response re equipment in Categories I.B, II.A & IV due in 30 days.
VARGA, S. A. Operating Reactors Branch 1. 83/03/25 GIESLER, C. W. Wisconsin Public Service Corp. 3pp. 17775:360. 24X
Fiche: 50-305, 83/03/25, 8303310016.

G. Inspection reports, IE Bulletins & correspondence

8303100509 Forwards request for addl info re response to IE Bulletin 80-11, "Masonry Wall Design." Info due within 60 days of ltr receipt.
VARGA, S. A. Operating Reactors Branch 1. 83/02/22 GIESLER, C. W. Washington Public Power Supply System 5pp. 17521:321. 24X
Fiche: 50-305, 83/02/22, 8303100509.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303030535 Forwards IE Insp Rept 50-305/83-02 on 830207-11. No noncompliance noted.
MILLER, J. R. Region 3, Office of Director 83/02/25 GIESLER, C. W. Wisconsin Public Service Corp. 2pp. 17409:043. 24X
Fiche: 50-305, 83/02/25, 8303030535.

--8303030543 IE Insp Rept 50-305/83-02 on 830207-11. No noncompliance noted. Major areas inspected: security plan implementing procedures, physical barriers, assessment aids, access controls & detection aids. Details withheld (ref 10CFR73.21). BELANGER, J. L., KNICELEY, J. R., CREED, J. R. Region 3, Office of Director 83/02/25 2pp. 17409:045. 24X Fiche: 50-305, 83/02/25, 8303030535.

8303030466 Clarifies NRC position re procedures for admitting NRC personnel to facility. Site orientation re issuance of badges, escort duties & emergency evacuation for personnel listed in Encls 1 & 2 requested.
KEPPLER, J. G. Region 3, Office of Director 83/02/28 GIESLER, C. W. Wisconsin Public Service Corp. 6pp. 17409:256. 24X
Fiche: 50-305, 83/02/28, 8303030466.

8303140396 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Bunker-Ramo electrical penetrations not utilized at plant.
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/03 KEPPLER, J. G. Region 3, Office of Director 1p. 17547:130. 24X
Fiche: 50-305, 83/03/03, 8303140396.

8303150287 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Surveillance testing of undervoltage trip function completed. No problems encountered.
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/04 KEPPLER, J. G. Region 3, Office of Director 3pp. 17567:038. 24X
Fiche: 50-305, 83/03/04, 8303150287.

8303140329 Application for amend to License DPR-43, requesting relief from performing exams of reactor coolant pump internal casing welds required by Section XI, Table IWB-2500 of ASME Code.
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/08
EISENHUT, D. G. Division of Licensing 3pp. 17534:199. 24X
Fiche: 50-305, 83/03/08, 8303140329.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303170414 Ack receipt of 830303 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-305/82-21.
STREETER, J. F. Division of Project & Resident Programs. 83/03/11.
GIESLER, C. W. Wisconsin Public Service Corp. 1p. 17610:091. 24X Fiche: 50-305. 83/03/11. 8303170414.

--8303170419 Responds to NRC 830201 ltr re violations noted in IE Insp Rept 50-305/82-21. Corrective actions tracking sheet used to maintain current status of drawing changes.
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/03.
STREETER, J. F. Division of Project & Resident Programs. 3pp. 17610:092. 24X Fiche: 50-305. 83/03/11. 8303170414.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering. Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000. 83/03/18. 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering. Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 12lpp. 17774:352. 24X Fiche: 50-000. 83/03/21. 8212060387.

R. Periodic operating reports & related correspondence

8303080163 Forwards monthly operating rept for Dec 1982.
GIESLER, C. W. Wisconsin Public Service Corp. 83/01/10. Division of Data Automation & Management Information. 1p. 17457:305. 24X Fiche: 50-305. 83/01/10. 8303080163.

--8303080166 Monthly operating rept for Dec 1982.
RUITER, G. H. Wisconsin Public Service Corp. 83/01/05. 4pp. 17457:306. 24X Fiche: 50-305. 83/01/10. 8303080163.

8303030083 Forwards "Annual Operating Rept, 1982."
GIESLER, C. W. Wisconsin Public Service Corp. 83/02/28. Office of Nuclear Reactor Regulation, Director. 1p. 17413:131. 24X Fiche: 50-305. 83/02/28. 8303030083.

--8303030088 "Annual Operating Rept, 1982."
* Wisconsin Public Service Corp. * Wisconsin Power & Light Co. * Madison Gas & Electric Co. 83/02/28. 97pp. 17413:132. 24X Fiche: 50-305. 83/02/28. 8303030083.

8303160352 Forwards monthly operating rept for Feb 1983.
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/10. Director's Office, Office of Inspection and Enforcement. 1p. 17595:318. 24X Fiche: 50-305. 83/03/10. 8303160352.

--8303160358 Monthly operating rept for Feb 1983.
RUITER, G. H. Wisconsin Public Service Corp. 83/03/01. 4pp. 17595:319. 24X Fiche: 50-305. 83/03/10. 8303160352.

S. Reportable occurrences, LERs & related correspondence

8303080122 Forwards LER 83-002/03L-0.
GIESLER, C. W. Wisconsin Public Service Corp. 83/02/25. KEPPLER, J. G. Region 3, Office of Director. 1p. 17458:269. 24X Fiche: 50-305. 83/02/25. 8303080122.

--8303080134 LER 83-002/03L-0 on 830126, during full power, diesel generator removed from svc to repair leaks in cooling sys HX. Caused by corrosion on svc water side of cooling water HX. Two tubes plugged & four tube sheet faces repaired.
BERNHOFT, S. L. Wisconsin Public Service Corp. 83/02/25. Region 3, Office of Director. 1p. 17458:270. 24X Fiche: 50-305. 83/02/25. 8303080122.

8303140400 Forwards LER 83-003/03L-0.
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/03. KEPPLER, J. G. Region 3, Office of Director. 1p. 17541:055. 24X Fiche: 50-305. 83/03/03. 8303140400.

--8303140414 LER 83-003/03L-0 on 830201, containment air sampling line feeding R11 & R12 manually isolated due to failure of sample isolation valves to cycle from cuntrol room. Caused by solenoid valve stuck in open position.
BERNHOFT, S. L. Wisconsin Public Service Corp. 83/03/03. Region 3, Office of Director. 1p. 17541:056. 24X Fiche: 50-305. 83/03/03. 8303140400.

8303140493 Forwards LER 83-004/03L-0.
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/04. KEPPLER, J. G. Region 3, Office of Director. 1p. 17533:354. 24X Fiche: 50-305. 83/03/04. 8303140493.

--8303140505 LER 83-004/03L-0 on 830204, water found dripping into controller for valve AFW-10 during investigation of battery ground fault condition on battery 1A. Caused by wet rags stuffed in newly drilled holes in concrete wall.
BERNHOFT, S. L. Wisconsin Public Service Corp. 83/03/04. Region 3, Office of Director. 2pp. 17533:355. 24X Fiche: 50-305. 83/03/04. 8303140493.

8303240225 Forwards updated LER 83-001/01X-1.
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/16. KEPPLER, J. G. Region 3, Office of Director. 1p. 17682:159. 24X Fiche: 50-305. 83/03/16. 8303240225.

--8303240238 Updated LER 83-001/01X-1 on 830105, electrician performing corrective maint pulled fuse to de-energize SV33379 leaving CV31394 caustic additive to containment spray sys isolation valve in open position. Design change initiated.
BERNHOFT, S. L. Wisconsin Public Service Corp. 83/03/16. Region 3, Office of Director. 2pp. 17682:160. 24X Fiche: 50-305. 83/03/16. 8303240225.

8303240565 Forwards LER 83-005/03L-0.
GIESLER, C. W. Wisconsin Public Service Corp. 83/03/18. KEPPLER, J. G. Region 3, Office of Director. 1p. 17683:182. 24X Fiche: 50-305. 83/03/18. 8303240565.

--8303240574 LER 83-005/03L-0 on 830216, during maint on svc water outlet control valve from diesel generator 1B oil cooler, SW-3018 failed to open fully when diesel started. Caused by bad ball valve. Valve replaced & generator returned to svc.
BERNHOFT, S. L. Wisconsin Public Service Corp. 83/03/18. Region 3, Office of Director. 1p. 17683:183. 24X Fiche: 50-305. 83/03/18. 8303240565.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000. 83/02/24. 8302250505.

8303010559 Requests senior reactor operator exam for 5 applicants during wk of 830523. Update of steps taken to comply w/NUREG-0737, Item I.A.1.3 re second senior reactor operator on-shift provided.
GIESLER, C. W. Washington Public Power Supply System. 83/02/25.
VARGA, S. A. Operating Reactors Branch 1. 2pp. 17343:038. 24X Fiche: 50-305. 83/02/25. 8303010559.

8303010690 Submits tentative schedule for operator license applications through 1985, per Generic Ltr 83-01.
GIESLER, C. W. Wisconsin Public Service Corp. 83/02/25.
EISENHUT, D. G. Division of Licensing. 2pp. 17341:163. 24X Fiche: 50-305. 83/02/25. 8303010690.

DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8303100180 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17495:148. 24X Fiche: 50-000. 83/03/02. 8303100180.

--8303100186 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1.10 re offsite surveys, EPIP 1.1.11 re accident assessment & EPIP 1.1.14 re vendor & consultant svcs.
WARD, E. C. Northern States Power Co. 83/02/17. Region 3, Office of Director. 1p. 17495:149. 24X Fiche: 50-000. 83/03/02. 8303100180.

--8303100193 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1.10 re offsite surveys, EPIP 1.1.11 re accident assessment & EPIP 1.1.14 re vendor & consultant svcs.
HUDSON, G., WARD, E. C. Northern States Power Co. 83/02/17. 62pp. 17495:150. 24X Fiche: 50-000. 83/03/02. 8303100180.

8303210090 Forwards IE Insp Repts 50-282/83-03 & 50-306/83-02 on 830131-0204. No noncompliance noted.
PAPERIELLO, C. J. Region 3, Office of Director. 83/03/02.
LARSON, C. E. Northern States Power Co. 2pp. 17630:174. 24X Fiche: 50-282. 83/03/02. 8303210090.

# DOCKETED ITEMS

--8303210097 IE Insp Repts 50-282/83-03 & 50-306/83-02 on 830131-0204 Noncompliance noted Major areas inspected action taken re NRC 811217 confirmation of action ltr & emergency preparedness appraisal improvement items.
PATTERSEN, J P. Region 3, Office of Director. 83/02/28. 12pp.
17630:176. 24X Fiche: 50-282, 83/03/02, 8303210090.

8303150703 Responds to 821230 request for changes submitted as Rev 8 to security plan. Changes consistent w/provisions of 10CFR50.54 & do not decrease effectiveness of plan except for change re rotation of locks.
CLARK, R A. Operating Reactors Branch 3. 83/03/10. MUSOLF, D M.
Northern States Power Co. 2pp. 17586:240. 24X
Fiche: 50-282, 83/03/10, 8303150703.

8303170215 Requests relief from fixed suppression sys installation requirement of 10CFR50.48, Paragraph b, for Fire Areas 58, 59, 73 & 74.
MUSOLF, D. Northern States Power Co. 83/03/11. Office of Nuclear Reactor Regulation, Director. 36pp. 17606:079. 24X
Fiche: 50-282, 83/03/11, 8303170215.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J A. Region 3, Office of Director. 83/03/22. Commonwealth Edison Co. 2pp. 17690:316. 24X Fiche: 50-000, 83/03/22, 8303240440.

## I. Financial information

8303280039 Forwards Annual Financial Rept 1982.
BRUSVEN, A D. Northern States Power Co. 83/03/23. Office of Nuclear Reactor Regulation, Director. 1p. 17707:107. 24X
Fiche: 50-000, 83/03/23, 8303280039.

--8303280044 Annual Financial Rept 1982.
* Northern States Power Co. 82/12/31. 43pp. 17707:108. 24X
Fiche: 50-000, 83/03/23, 8303280039.

8303300123 Forwards suppl to Annual Financial Rept 1982.
BRUSVEN, A D. Northern States Power Co. 83/03/25. Office of Nuclear Reactor Regulation, Director. 1p. 17734:330. 24X
Fiche: 50-000, 83/03/25, 8303300123.

--8303300133 Suppl to Annual Financial Rept 1982.
* Northern States Power Co. 83/03/31. 21pp. 17734:331. 24X
Fiche: 50-000, 83/03/25, 8303300123.

## P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303090265 Forwards safety evaluation re reactor physics & reload safety evaluation methods, based on review of 821213 submittal of Technical Repts NSPNAD-8101P, Rev 1 & NSPNAD-8102P, Rev 1. Methods acceptable.
CLARK, R A. Operating Reactors Branch 3. 83/02/17. MUSOLF, D M.
Northern States Power Co. 2pp. 17485:098. 24X
Fiche: 50-282, 83/02/17, 8303090265.

--8303090272 Safety evaluation supporting reactor physics & reload safety evaluation methods addressed in Technical Repts NSPNAD-8101P & 8102P. Methods acceptable.
* Office of Nuclear Reactor Regulation, Director. 83/02/17. 82pp. 17485:100. 24X Fiche: 50-282, 83/02/17, 8303090265.

8303140077 Forwards Amends 62 & 56 to Licenses DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & availability. Amends revise Tech Specs for compliance w/ testing requirements of 10CFR50, App J.
DIIANNI, D C. Operating Reactors Branch 3. 83/02/23. MUSOLF, D M.
Northern States Power Co. 2pp. 17548:002. 24X
Fiche: 50-282, 83/02/23, 8303140077.

--8303140082 Amends 62 & 56 to Licenses DPR-42 & DPR-60, respectively, revising Tech Specs for compliance w/testing requirements of 10CFR50, App J.
CLARK, R A. Operating Reactors Branch 3. 83/02/23. 17pp.
17548:004. 24X Fiche: 50-282, 83/02/23, 8303140077.

--8303140089 Safety evaluation supporting Amends 62 & 56 to Licenses DPR-42 & DPR-60, respectively. Technical evaluation rept encl.
* Office of Nuclear Reactor Regulation, Director. 83/02/23. 19pp. 17548:022. 24X Fiche: 50-282, 83/02/23, 8303140077.

--8205290497 "Containment Leakage Rate Testing."
DELGAIZO, T J. Franklin Institute/Franklin Research Center.
NRC-03-79-118. TER-C5257-43/44. 82/03/25. HUANG, Y S. NRC - No Detailed Affiliation Given. 21pp. 17548:041. 24X
Fiche: 50-282, 83/02/23, 8303140077.

--8303140115 Notice of issuance & availability of Amends 62 & 56 to Licenses DPR-42 & DPR-60, respectively.
CLARK, R A. Operating Reactors Branch 3. 83/02/23. 2pp.
17548:061. 24X Fiche: 50-282, 83/02/23, 8303140077.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J G. Region 3, Office of Director. 83/03/03. Commonwealth Edison Co. 2pp. 17492:014. 24X Fiche: 50-000, 83/03/03, 8303100364.

8303140250 Advises that TMI Action Item III.D.3.4, "Control Room Habitability Mod" will be completed on 830531. Delay due to design changes to test procedures.
MUSOLF, D. Northern States Power Co. 83/03/03. Office of Nuclear Reactor Regulation, Director. 1p. 17538:337. 24X
Fiche: 50-282, 83/03/03, 8303140250.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12) Svc list encl.
EISENHUT, D G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 31pp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303180131 Notification of 830318 meeting w/util & Franklin Research Ctr in Bethesda, MD to discuss resolution of open items in technical evaluation rept re control of heavy loads.
DIIANNI, D C. Operating Reactors Branch 3. 83/03/10. CLARK, R A. Operating Reactors Branch 3. 2pp. 17625:134. 24X
Fiche: 50-282, 83/03/10, 8303180131.

8303170381 Forwards response to Generic Ltr 82-28 requesting submittal of info re inadequate core cooling instrumentation per revised post-TMI requirements.
MUSOLF, D. Northern States Power Co. 83/03/14. Office of Nuclear Reactor Regulation, Director. 4pp. 17610:075. 24X
Fiche: 50-282, 83/03/14, 8303170381.

8303230153 Forwards order confirming commitments to implement post-TMI related items scheduled for completion on or after 820701, based on Generic Ltrs 82-05 & 82-10.
CLARK, R A. Operating Reactors Branch 3. 83/03/14. MUSOLF, D M.
Northern States Power Co. 3pp. 17686:190. 24X
Fiche: 50-282, 83/03/14, 8303230153.

--8303230159 Order confirming licensee commitments to implement & maintain post-TMI related issues.
PURPLE, R A. Division of Licensing. 83/03/14. Northern States Power Co. 10pp. 17686:193. 24X Fiche: 50-282, 83/03/14, 8303230153.

8303210058 Provides addl info re NUREG-0737, Item II.D.1.2, "Relief & Safety Valve Performance." Westinghouse & Crosby Valve working on scheme to optimize valve ring settings. Fluor Power investigating effects of increased support loadings.
MUSOLF, D. Northern States Power Co. 83/03/15. Office of Nuclear Reactor Regulation, Director. 2pp. 17630:254. 24X
Fiche: 50-282, 83/03/15, 8303210058.

8303310281 Forwards proprietary info presented at 830223 meeting w/NRC in Bethesda, MD re fuel assembly failure. Info withheld (ref 10CFR2.790).
MUSOLF, D. Northern States Power Co. 83/03/22. Office of Nuclear Reactor Regulation, Director. 1p. 17756:151. 24X
Fiche: 50-282, 83/03/22, 8303310281.

--8303310287 Authorizes utilization of encl Affidavit AW-77-47 in support of Northern States Power request to withhold proprietary info per 10CFR2.790.
WIESEMANN, R A. Westinghouse Electric Corp. 83/03/17. THOMAS, C O. Standardization & Special Projects Branch. 6pp. 17756:152. 24X
Fiche: 50-282, 83/03/22, 8303310281.

G. Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303030450 Clarifies NRC position re procedures for admitting NRC personnel to facilities. Lists of NRC inspectors & personnel likely to visit facility two or more times per yr & at anytime encl. Lists will be updated every 6 months.
KEPPLER, J. G. Region 3, Office of Director 83/02/28 LARSON, C. E. Northern States Power Co. 6pp. 17410:049. 24X Fiche: 50-282, 83/02/28, 8303030450.

8303210090 Forwards IE Insp Rpts 50-282/83-03 & 50-306/83-02 on 830131-0204. No noncompliance noted.
PAPERIELLO, C. J. Region 3, Office of Director 83/03/02 LARSON, C. E. Northern States Power Co. 2pp. 17630:174. 24X Fiche: 50-282, 83/03/02, 8303210090.

--8303210097 IE Insp Rpts 50-282/83-03 & 50-306/83-02 on 830131-0204. No noncompliance noted. Major areas inspected. action taken re NRC 811217 confirmation of action ltr & emergency preparedness appraisal improvement items.
PATTERSON, J. P., GLOERSEN, W. B., AXELSON, W. L. Region 3, Office of Director 83/02/28 12pp. 17630:176. 24X Fiche: 50-282, 83/03/02, 8303210090.

8303150269 Responds to IE Bulletin 83-01 Testing of reactor main trip breakers accomplished. Breaker maint program reviewed & found to conform to vendor recommendation. Operators advised of Salem event & appropriate actions.
LARSON, C. E. Northern States Power Co. 83/03/04 KEPPLER, J. G. Region 3, Office of Director 1p. 17567:229. 24X Fiche: 50-282, 83/03/04, 8303150269.

8303240538 Forwards IE Insp Rpts 50-282/83-01 & 50-306/83-01 on 830124-27 & notice of violation.
&TREETER, J. F. Region 3, Office of Director 83/03/09 LARSON, C. E. Northern States Power Co. 2pp. 17682:322. 24X Fiche: 50-282, 83/03/09, 8303240538.

--8303240546 Notice of violation from insp on 830124-27.
&TREETER, J. F. Region 3, Office of Director 83/03/09 2pp. 17682:324. 24X Fiche: 50-282, 83/03/09, 8303240538.

--8303240556 IE Insp Rpts 50-282/83-01 & 50-306/83-01 on 830124-27. Noncompliance noted: failure to establish required log & procedures implementing Sections 5.7.9 & 10 of ANSI N45.2.11-1974 & to implement 10CFR21.6(a) & 31.
BRICKLEY, P. H., JACKIW, I. N. Region 3, Office of Director 83/03/07 3pp. 17682:326. 24X Fiche: 50-282, 83/03/09, 8303240538.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12lpp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303290454 Responds to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Sys Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel)." No abnormal buildup of clams identified. Flow monitoring instrumentation installed.
LARSON, C. E. Northern States Power Co. 83/03/22 KEPPLER, J. G. Region 3, Office of Director 2pp. 17725:329. 24X Fiche: 50-282, 83/03/22, 8303290454.

R. Periodic operating reports & related correspondence

8303080049 Forwards monthly operating repts for Dec 1982.
MUSOLF, D. Northern States Power Co. 83/01/12 Director's Office, Office of Inspection and Enforcement 1p. 17454:354. 24X Fiche: 50-282, 83/01/12, 8303080049.

--8303080053 Monthly operating repts for Dec 1982.
DUGSTAD, D. Northern States Power Co. 83/01/05 8pp. 17454:355. 24X Fiche: 50-282, 83/01/12, 8303080049.

8303150460 Forwards monthly operating repts for Jan 1983.
MUSOLF, D. Northern States Power Co. 83/02/10 Office of Resource Management, Director 1p. 17561:044. 24X Fiche: 50-282, 83/02/10, 8303150460.

--8303150462 Monthly operating repts for Jan 1983.
DUGSTAD, D. Northern States Power Co. 83/02/04 8pp. 17561:045. 24X Fiche: 50-282, 83/02/10, 8303150460.

8303150277 Forwards "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1982."
MUSOLF, D. Northern States Power Co. 83/03/01 Region 3, Office of Director 1p. 17567:138. 24X Fiche: 50-282, 83/03/01, 8303150277.

--8303150280 "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1982."
* Northern States Power Co. 83/03/01 20pp. 17567:139. 24X Fiche: 50-282, 83/03/01, 8303150277.

S. Reportable occurrences, LERs & related correspondence

8303110513 Summary of 830223 meeting w/util & Westinghouse in Bethesda, MD re fuel assembly failure in spent fuel pool.
DIIANNI, D. C. Operating Reactors Branch 3 83/03/04 Operating Reactors Branch 3 6pp. 17522:348. 24X Fiche: 50-282, 83/03/04, 8303110513.

8303280142 Forwards LER 83-002/03L-0.
MUSOLF, D. Northern States Power Co. 83/03/18 Region 3, Office of Director 1p. 17709:308. 24X Fiche: 50-306, 83/03/18, 8303280142.

--8303280151 LER 83-002/03L-0 on 830216, control switches for heat trace circuits ET2R & ET47R found in off position. Caused by personnel error. Switches returned to automatic position.
HUNSTAD, A. A. Northern States Power Co. 83/03/18 Region 3, Office of Director 1p. 17709:309. 24X Fiche: 50-306, 83/03/18, 8303280142.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303040478 Submits schedule for operator licensing exams in response to Generic Ltr 83-01. Plans based on current rate of turnover & anticipated exam needs.
MUSOLF, D. M. Northern States Power Co. 83/02/28 Office of Nuclear Reactor Regulation, Director 2pp. 17373:361. 24X Fiche: 50-000, 83/02/28, 8303040478.

DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

F. Security, medical, emergency & fire protection plans

8303300196 Forwards Amend 69 to License DPR-36 & notice of issuance & availability. Amend changes Tech Specs to require audit of emergency & security plans at least once per yr.
HEITNER, K. L. Operating Reactors Branch 3 83/03/16 GARRITY, J. H. Maine Yankee Atomic Power Co. 4pp. 17754:322. 24X Fiche: 50-309, 83/03/16, 8303300196.

--8303300207 Amend 69 to License DPR-36, changing Tech Specs to require audit of emergency & security plans at least once per yr.
CLARK, R. A. Operating Reactors Branch 3 83/03/16 4pp. 17754:326. 24X Fiche: 50-309, 83/03/16, 8303300196.

--8303300209 Notice of issuance & availability of Amend 69 to License DPR-36.
CLARK, R. A. Operating Reactors Branch 3 83/03/16 2pp. 17754:330. 24X Fiche: 50-309, 83/03/16, 8303300196.

8303310478 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 83/03/29 Document Management Branch 1p. 17804:024. 24X Fiche: 50-309, 83/03/29, 8303310478.

--8303310483 Forwards public version of revised emergency plan implementing procedures, including Procedures 2.50.3 re site area emergency, 2.50.4 re general emergency & 2.50.12 re emergency offsite radiation monitoring.
* Maine Yankee Atomic Power Co. 83/02/18 NRC - No Detailed Affiliation Given 1p. 17804:025. 24X Fiche: 50-309, 83/03/29, 8303310478.

--8303310487 Public version of revised emergency plan implementing procedures, including Procedures 2.50.3 re site area emergency, 2.50.4 re general emergency & 2.50.12 re emergency offsite radiation monitoring. Revised index encl.
* Maine Yankee Atomic Power Co. 83/02/18 105pp 17804:026
24X Fiche: 50-309, 83/03/29, 8303310478.

Q. Adjudicatory correspondence

8303110046 Interrogatories & request for production of documents. Certificate of Svc encl.
GODDARD, R. J.; LESSY, R. P. Hearing Branch 3 83/03/09 Sensible Maine Power 19pp 17519:304 24X Fiche: 50-309, 83/03/09, 8303110046.

8303110205 Order extending time until 830411 for Commission to act to review Director's Decision DD-83-3.
CHILK, S. J. Office of the Secretary of the Commission 83/03/10 Commissioners ltr 17513:359 24X Fiche: 50-309, 83/03/10, 8303110205.

8303220214 Expresses disappointment re 2-wk delay of util response to interrogatories. Sensible ME Power will probably need enlargements of time for discovery. Related correspondence.
MILLER, D. S. Miller, D. S. MILLER, D. S. Sensible Maine Power 83/03/13 GAD, R. K. Ropes & Gray ltr 17657:288 24X
Fiche: 50-309, 83/03/13, 8303220214.

8303220218 Second set of interrogatories & requests for documents. Certificate of Svc encl.
MILLER, D. S. Sensible Maine Power. MILLER, D. S. Miller, D. S. 83/03/13 Maine Yankee Atomic Power Co. 8pp 17654:311 24X
Fiche: 50-309, 83/03/13, 8303220218.

8303290062 Memorializes 930316 telcon re timing of Sensible ME Power responses to NRC 830309 interrogatories. Responses to be filed by 830411.
GODDARD, R. J. Hearing Branch 3 83/03/17 MILLER, D. S. Sensible Maine Power. MILLER, D. S. Miller, D. S. ltr 17720:117 24X
Fiche: 50-309, 83/03/17, 8303290062.

8303300006 Memorializes 830324 telcon re timing of State of ME responses to NRC 830309 interrogatories. Responses due by 830411.
GODDARD, R. J. Hearing Branch 3 83/03/28 AHRENS, P. Maine, State of 2pp 17735:314 24X Fiche: 50-309, 83/03/28, 8303300006.

8303310145 Repts on successful resolution among parties of proposed schedule for proceeding. Schedule listed. Prehearing conference needed.
LESSY, R. P.; GODDARD, R. J. Hearing Branch 3 83/03/30 LAZO, R. M.; MORRIS, P. A.; HAND, C. H. Atomic Safety and Licensing Board Panel 2pp 17763:055 24X Fiche: 50-309, 83/03/30, 8303310145.

J. Insurance & indemnity information

8303140359 Submits info re nuclear property insurance in force on 830401, per 10CFR50.54(w).
CRABTREE, R. A. Maine Yankee Atomic Power Co. 83/03/08 SALTZMAN, J. Antitrust & Economic analysis Branch (Utility Finance) ltr 17543:307 24X Fiche: 50-309, 83/03/08, 8303140359.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303040159 Requests participation in research project, "Task Analysis of Nuclear Power Plant Control Room Crews."
CLARK, R. A. Licensing Branch 3 83/02/18 GARRITY, J. Maine Yankee Atomic Power Co. 3pp 17427:038 24X Fiche: 50-309, 83/02/18, 8303040159.

8303030670 Forwards "Thermal Shield Support Sys Dislodged Positioning Pin Evaluation for ME Yankee." Rept summarizes 821027 meeting info. Radiation measurements support theory that pins lost preload & became dislodged early in plant life.
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/02/28 CLARK, R. A. Operating Reactors Branch 3 2pp 17416:013 24X
Fiche: 50-309, 83/02/28, 8303030670.

--8303030675 "Thermal Shield Support Sys Dislodged Positioning Pin Evaluation for ME Yankee."
* Combustion Engineering, Inc. CEN-232(M) 82/12/31 3pp
17416:015 24X Fiche: 50-309, 83/02/28, 8303030670.

8303160620 EXAMINATION OF FAILED STUDS FROM NO. 2 STEAM GENERATOR AT THE MAINE YANKEE NUCLEAR POWER STATION.
CZAJKOWSKI, C. Brookhaven National Laboratory FIN A-3400
NUREG/CR-2993. 83/02/28. Division of Engineering. 32pp
Available at NRC $3.75 17602:251 24X Fiche: 50-309, 83/02/28, 8303160620.

8303150367 Advises that facility design meets criteria identified in NUREG-0737, Item III.D.3.4, "Control Room Habitability," per 810811 & 821208 submittals & is acceptable. SER encl.
CLARK, R. A. Operating Reactors Branch 3 83/03/01 GARRITY, J. H. Maine Yankee Atomic Power Co. 5pp 17597:171 24X
Fiche: 50-309, 83/03/01, 8303150367.

8303160645 Requests review of adequacy of pressurized heaters in preventing void formation in other parts of RCS during natural circulation cooldown. Written response requested within 120 days of ltr receipt.
CLARK, R. A. Operating Reactors Branch 3 83/03/01 GARRITY, J. H. Maine Yankee Atomic Power Co. 2pp 17604:351 24X
Fiche: 50-309, 83/03/01, 8303160645.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303080503 Discusses environ qualification of electrical equipment re high pressure safety injection pump ventilation sys, per 810902 proposal. Addition of new sys not warranted & design effort discontinued.
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/03/03 CLARK, R. A. Operating Reactors Branch 3 3pp 17451:360 24X
Fiche: 50-309, 83/03/03, 8303080503.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303300235 Forwards operational QA program, Rev. 2, for review. Rev updates organizational & responsibility changes & changes requirements for calibr of radiological contr ls instrument to be consistent w/current regulatory guidance.
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/03/10 TAYLOR, J. M. Director's Office, Office of Inspection and Enforcement 3pp
17733:026 24X Fiche: 50-309, 83/03/10, 8303300235.

--8303300243 Operational QA Program, Rev. 2.
LAWTON, R. R. Maine Yankee Atomic Power Co. 2164N-RRL R02
83/03/01 81pp 17733:029 24X Fiche: 50-309, 83/03/10, 8303300235.

8303170140 Responds to NRC 830302 request for addl info re environ qualification of safety-related electrical equipment. Info re Equipment Items 31.32 & 42 addresses concerns identified by Franklin Research Ctr.
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/03/11 CLARK, R. A. Operating Reactors Branch 3 4pp 17609:030 24X
Fiche: 50-309, 83/03/11, 8303170140.

8303220488 Forwards order confirming commitments to implement post-TMI items scheduled for completion on or after 820701, based on responses to Generic Ltrs 82-05 & 82-10.
CLARK, R. A. Operating Reactors Branch 3 83/03/14 GARRITY, J. H. Maine Yankee Atomic Power Co. 3pp 17670:326 24X
Fiche: 50-309, 83/03/14, 8303220488.

--8303220491 Order confirming licensee commitments to implement & maintain post-TMI-related issues.
PURPLE, R. A. Division of Licensing 83/03/14 Maine Yankee Atomic Power Co. 9pp 17670:329 24X Fiche: 50-309, 83/03/14, 8303220488.

8303220100 Advises that plant operating procedures design details for diesel generator load shedding & Tech Spec changes will be submitted 3 months prior to placing degraded grid voltage protection scheme in svc & no later than 831230.
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/03/16 CLARK, R. A. Operating Reactors Branch 3 ltr 17650:071 24X
Fiche: 50-309, 83/03/16, 8303220100.

8303220289 Requests that comprehensive submittal, in response to Generic Ltr 82-28, re inadequate core cooling instrumentation sys, be revised to 830429 due to refueling outage & outage for feedwater line repair.
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/03/16 CLARK, R. A. Operating Reactors Branch 3 ltr 17656:129 24X
Fiche: 50-309, 83/03/16, 8303220289.

8303300196 Forwards Amend 69 to License DPR-36 & notice of issuance & availability. Amend changes Tech Specs to require audit of emergency & security plans at least once per yr.
HEITNER, K. L. Operating Reactors Branch 3 83/03/16 GARRITY, J. H.
Maine Yankee Atomic Power Co. 4pp. 17754:322 24X
Fiche: 50-309, 83/03/16, 8303300196.

--8303300207 Amend 69 to License DPR-36, changing Tech Specs to require audit of emergency & security plans at least once per yr.
CLARK, R. A. Operating Reactors Branch 3 83/03/16 4pp.
17754:326 24X Fiche: 50-309, 83/03/16, 8303300196.

-8303300209 Notice of issuance & availability of Amend 69 to License DPR-36.
CLARK, R. A. Operating Reactors Branch 3 83/03/16 2pp.
17754:330 24X Fiche: 50-309, 83/03/16, 8303300196.

8303300037 Forwards safety evaluation supporting util 830209 meeting presentation on feedwater line break. No response required.
CLARK, R. A. Operating Reactors Branch 3 83/03/18 GARRITY, J. H.
Maine Yankee Atomic Power Co. 2pp. 17753:014 24X
Fiche: 50-309, 83/03/18, 8303300037.

--8303300043 Safety evaluation supporting programs for assessment of damage, repair & mod of facility.
* Office of Nuclear Reactor Regulation, Director 83/03/18 6pp.
17753:016 24X Fiche: 50-309, 83/03/18, 8303300037.

## 0. Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc.
11pp. 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303100169 Forwards IE Insp Rept 50-309/82-17 on 820908-10 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs 83/02/25
RANDAZZA, J. B. Maine Yankee Atomic Power Co. 2pp. 17485:207 24X
Fiche: 50-309, 83/02/25, 8303100169.

--8303100171 Notice of violation from insp on 820908-10.
* Division of Engineering & Technical Programs 83/02/25 2pp.
17485:209 24X Fiche: 50-309, 83/02/25, 8303100169.

--8303100177 IE Insp Rept 50-309/82-17 on 820908-10. Noncompliance noted: failure to maintain records & follow procedures for activities affecting quality of shipping packages.
CLEMONS, P., ROWE, C. Region 1, Office of Director SHANBAKY, M.
Division of Engineering & Technical Programs 83/02/24 4pp.
17485:211 24X Fiche: 50-309, 83/02/25, 8303100169.

8303170220 Responds to IE Bulletin 83-01 re failure of reactor trip breakers (Westinghouse DB-50) to open on automatic trip signal. Breakers not used in reactor protective sys.
RANDAZZA, J. B. Maine Yankee Atomic Power Co. 83/03/08 HAYNES, R. C.
Region 1, Office of Director 1p. 17606:059 24X
Fiche: 50-309, 83/03/08, 8303170220.

8303150540 Ack receipt of 830217 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/82-25.
MARTIN, T. T. Division of Engineering & Technical Programs 83/03/09
RANDAZZA, J. B. Maine Yankee Atomic Power Co. 1p. 17568:055 24X
Fiche: 50-309, 83/03/09, 8303150540.

--8303150557 Responds to NRC 830103 ltr re violations noted in IE Insp Rept 50-309/82-25. Corrective actions: exact work locations & detailed work location surveys will be determined prior to issuance of radiation work permit.
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/02/17 HAYNES, R. C.
Region 1, Office of Director 3pp. 17568:056 24X
Fiche: 50-309, 83/03/09, 8303150540.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc.
117pp. 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8303240328 Responds to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB." Action Item 4 re threaded fastener practices.
RANDAZZA, J. B. Maine Yankee Atomic Power Co. 83/03/16 HAYNES, R. C.
Region 1, Office of Director 4pp. 17679:338 24X
Fiche: 50-309, 83/03/16, 8303240328.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8303300493 Forwards IE Insp Rept 50-309/83-03 on 830128-31 & 0209-12 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs 83/03/18
RANDAZZA, J. B. Maine Yankee Atomic Power Co. 2pp. 17731:130 24X
Fiche: 50-309, 83/03/18, 8303300493.

--8303300498 Notice of violation from insp on 830128-31 & 0209-12.
* Region 1, Office of Director 83/03/18 1p. 17731:132 24X
Fiche: 50-309, 83/03/18, 8303300493.

--8303300504 IE Insp Rept 50-309/83-03 on 830128-31 & 0209-12. Noncompliance noted: use of welders prior to renewal of qualifications.
REYNOLDS, S. D., KERCH, H., GRAY, E. H. Region 1, Office of Director
83/03/16 5pp. 17731:133 24X Fiche: 50-309, 83/03/18, 8303300493.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12lpp. 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

8303290442 Ack receipt of 830303 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/82-26.
STAROSTECKI, R. Division of Project & Resident Programs 83/03/22
RANDAZZA, J. B. Maine Yankee Atomic Power Co. 1p. 17725:124 24X
Fiche: 50-309, 83/03/22, 8303290442.

--8303290461 Responds to NRC 830131 ltr re violations noted in IE Insp Rept 50-309/82-26. Corrective actions: disciplinary action enforced & memo issued stressing compliance w/radiation protective practices.
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/03/03 HAYNES, R. C.
Region 1, Office of Director 2pp. 17725:125 24X
Fiche: 50-309, 83/03/22, 8303290442.

## R. Periodic operating reports & related correspondence

8303080012 Forwards monthly operating rept for Dec 1982.
GRACE, R. H. Maine Yankee Atomic Power Co. 83/01/07 Division of Data Automation & Management Information 1p. 17436:353 24X
Fiche: 50-309, 83/01/07, 8303080012.

--8303080013 Monthly operating rept for Dec 1982.
BATTERSON, S. Maine Yankee Atomic Power Co. 83/01/03 4pp.
17436:354 24X Fiche: 50-309, 83/01/07, 8303080012.

8303150424 Forwards monthly operating rept for Jan 1983.
GROCE, R. H. Maine Yankee Atomic Power Co. 83/02/09 HARTFIELD, R. A.
Management Information Branch 1p. 17561:172 24X
Fiche: 50-309, 83/02/09, 8303150424.

--8303150425 Monthly operating rept for Jan 1983.
BATTERSON, S. Maine Yankee Atomic Power Co. 83/02/09 5pp.
17561:173 24X Fiche: 50-309, 83/02/09, 8303150424.

8303140239 Forwards "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1982."
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/03/02 HAYNES, R. C.
Region 1, Office of Director 1p. 17539:012 24X
Fiche: 50-309, 83/03/02, 8303140239.

--8303140247 "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1982."
* Maine Yankee Atomic Power Co. 83/03/02 8pp. 17539:013 24X
Fiche: 50-309, 83/03/02, 8303140239.

## S. Reportable occurrences, LERs & related correspondence

8303010492 Forwards LER 83-001/03L-0.
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/02/16 HAYNES, R. C.
Region 1, Office of Director 1p. 17343:321 24X
Fiche: 50-309, 83/02/16, 8303010492.

--8303010502 LER 83-001/03L-0 on 830103. 08 & 18, daily checks on auxiliary feedwater flow instrument channels revealed faulty light on Controlotron Flow transmitter 1201A. Cause not stated. Circuit board replaced.
MORRISON, G. M. Maine Yankee Atomic Power Co. 83/02/16 Region 1, Office of Director 2pp. 17343:322 24X Fiche: 50-309, 83/02/16, 8303010492.

8303010504 Forwards LER 83-003/03L-0.
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/02/17. HAYNES, R. C.
Region 1, Office of Director. 1p. 17341:058. 24X
Fiche: 50-309, 83/02/17, 8303010504.

--8303010515 LER 83-003/03L-0 on 830118, recirculation actuation sys channel A inadvertently actuated. Repositioned valves rendered ECCS train A inoperable. Caused by shorted power leads. Procedure for testing switches revised.
CROSBY, R. C. Maine Yankee Atomic Power Co. 83/02/17. Region 1, Office of Director. 2pp. 17341:059. 24X Fiche: 50-309, 83/02/17, 8303010504.

8303010555 LER 83-004/01T-0 when operated in conformance w/Tech Spec 3.4.D.1, low temp overpressure protection (LTOP) sys did not maintain same margin of safety for limiting LTOP events as determined in sys safety analysis.
WOOD, E. C. Maine Yankee Atomic Power Co. 83/02/17. Region 1, Office of Director. 1p. 17343:040. 24X Fiche: 50-309, 83/02/17, 8303010555.

8303010472 Forwards followup LER 83-002/01T-1.
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/02/18. HAYNES, R. C.
Region 1, Office of Director. 1p. 17343:306. 24X
Fiche: 50-309, 83/02/18, 8303010472.

--8303010404 Followup LER 83-002/01T-1 on 830125, plant tripped from full load while isolating electrical ground. Feed line found severely leaking in containment. Caused by crack in feed pipe due to water hammer event. J tubes installed on feed rings.
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/02/18. Region 1, Office of Director. 5pp. 17343:307. 24X Fiche: 50-309, 83/02/18, 8303010472.

8303080168 LER 83-006/01T-0 during hot shutdown, leak discovered in safety injection check valve of RCS loop one. Caused by pin hole in seal weld of shaft bearing cover. Plant cooled down to repair leak.
WOOD, E. C. Maine Yankee Atomic Power Co. 83/02/22. Region 1, Office of Director. 1p. 17457:351. 24X Fiche: 50-309, 83/02/22, 8303080168.

8303040115 Forwards info re improper shipment of radwaste matl from ME Yankee Atomic Power Co to Barnwell, SC in response to 830120 ltr.
DIRCAS, W. J. Office of the Executive Director for Operations. 83/02/24. MITCHELL, G. J. Senate. 2pp. 17424:272. 24X
Fiche: 50-309, 83/02/24, 8303040115.

--8303040120 Forwards State of SC 821220 investigation rept re improper shipment of radwaste matl from ME Yankee Atomic Power Co to Barnwell, SC.
GIBSON, A. F. Division of Engineering & Radiological Safety Programs. 83/01/04. JOYNER, J. H. Division of Engineering & Technical Programs. 7pp. 17424:275. 24X Fiche: 50-309, 83/02/24, 8303040115.

--8303040125 Requests all available info re improper shipment of radwaste matl from ME Yankee Atomic Power Co to Barnwell, SC.
MITCHELL, G. J. Senate. 83/01/20. KAMMERER, C. Office of Congressional Affairs. 1p. 17424:281. 24X Fiche: 50-309, 83/02/24, 8303040115.

8303160335 Forwards LER 83-005/01T-1.
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/03/01. HAYNES, R. C.
Region 1, Office of Director. 1p. 17595:223. 24X
Fiche: 50-309, 83/03/01, 8303160335.

--8303160354 LER 83-005/01T-1 on 830218, contractor discovered inaccuracy in version of PDQ computer code used to calculate coefficients for INCA incore analysis code. Caused by coding error on contractor code. Corrected version of code obtained.
LAFLAMME, S. J. Maine Yankee Atomic Power Co. 83/03/01. Region 1, Office of Director. 2pp. 17595:224. 24X Fiche: 50-309, 83/03/01, 8303160335.

8303140433 Forwards updated LER 83-035/03X-1.
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/03/03. HAYNES, R. C.
Region 1, Office of Director. 1p. 17543:018. 24X
Fiche: 50-309, 83/03/03, 8303140433.

--8303140466 Updated LER 82-035/03X-1 on 821003, recirculation actuation refueling water storage tank level switches found to be out of tolerance. Cause unknown. United Electric Model J-110A-5-144 level switches recalibr.
MCALLISTER, S. A. Maine Yankee Atomic Power Co. 83/03/03. Region 1, Office of Director. 2pp. 17543:019. 24X Fiche: 50-309, 83/03/03, 8303140433.

8303140495 Forwards LER 83-006/01T-1.
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/03/03. HAYNES, R. C.
Region 1, Office of Director. 1p. 17541:057. 24X
Fiche: 50-309, 83/03/03, 8303140495.

--8303140506 LER 83-006/01T-1 on 830218, while in hot shutdown, small leak discovered in seal weld on HSI-17 check valve shaft bearing cover. Caused by inadequate application of welding & grinding techniques.
NELSON, R. H. Maine Yankee Atomic Power Co. 83/03/03. Region 1, Office of Director. 2pp. 17541:058. 24X Fiche: 50-309, 83/03/03, 8303140495.

8303140522 Forwards LER 83-004/01T-0.
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/03/03. HAYNES, R. C.
Region 1, Office of Director. 1p. 17534:172. 24X
Fiche: 50-309, 83/03/03, 8303140522.

--8303140536 LER 83-004/01T-0 on 830217, re-evaluation of low temp overpressure protection (LTOP) sys design & bases indicated that sys does not maintain same margin of safety for limiting LTOP events. Administrative procedures instituted.
STEVENS, J. L. Maine Yankee Atomic Power Co. 83/03/03. Region 1, Office of Director. 2pp. 17534:173. 24X Fiche: 50-309, 83/03/03, 8303140522.

8303280239 Forwards responses to NRC 830124 questions re 821214 offsite power supply degraded voltage conditions & Rev 0 to Procedure 1-22-6, "Backfeeding Busses 3, 4, 5 & 6 from 345 kV Switchgear & De-energizing X-14."
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/03/24. CLARK, R. A. Operating Reactors Branch 3. 6pp. 17708:143. 24X
Fiche: 50-309, 83/03/24, 8303280239.

--8303280251 Rev 0 to Procedure 1-22-6, "Backfeeding Busses 3, 4, 5 & 6 from 345 kV Switchyard & De-energizing X-14."
e Maine Yankee Atomic Power Co. 82/01/27. 6pp. 17708:149. 24X
Fiche: 50-309, 83/03/24, 8303280239.

8303290237 RO on 830310, containment high-range radiation monitor, required per TMI Action Item II.F.1.3, failed daily radiation monitoring sys check. Parts on order. Need for onsite spare parts being evaluated.
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/03/24. CLARK, R. A. Operating Reactors Branch 3. 1p. 17716:095. 24X
Fiche: 50-309, 83/03/24, 8303290237.

U. Congressional/Executive Correspondence

8303090169 Responds to 830201 ltr re 830125 trip. Water hammer event occurred, overstressing & deforming feedwater sys pipe supports & seismic restraints & damaging internal feedwater piping of two steam generators.
KAMMERER, C. Office of Congressional Affairs. 83/02/24. MITCHELL, G. J. Senate. 15pp. 17465:232. 24X Fiche: 50-309, 83/02/24, 8303090169.

--8303090177 Requests info re plant 830125 trip, including safety significance of event, cause of failure in feedwater pipe, proper operator procedures & length of time plant will be out of svc.
MITCHELL, G. J. Senate. 83/02/01. PALLADINO, N. J. Commissioners. 2pp. 17465:246. 24X Fiche: 50-309, 83/02/24, 8303090169.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303040429 Forwards tentative schedule for operator licensing exams to be conducted from present to 851231 per Generic Ltr 83-01.
GARRITY, J. H. Maine Yankee Atomic Power Co. 83/02/28. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17371:178. 24X
Fiche: 50-309, 83/02/28, 8303040429.

DOCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8303140614 Ack receipt of 821122 ltr & payment of civil penalty proposed in NRC 821027 notice of violation. Proposed security program improvements will be examined during future NRC insp. NRC should be notified of future changes.
HAYNES, R. C. Region 1, Office of Director. 82/12/30. UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 2pp. 17569:304
24X Fiche: 50-272, 82/12/30, 8303140614.

--8303140621 Responds to NRC 821027 ltr, notice of violation & proposed imposition of civil penalty. Addl security mgt improvement programs initiated. Corrective actions withheld (ref 10CFR73.21).
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 82/11/22. DEYOUNG, R. C. Director's Office. Office of Inspection and Enforcement. 2pp. 17569:306. 24X Fiche: 50-272, 82/12/30, 8303140614.

8303100202 Forwards IE Mgt Meeting Repts 50-272/83-07 & 50-311/83-06 on 830208. Util agreement to conduct Security Measure 1 on second shift confirmed per 830210 telcon.
STAROSTECKI, R. Division of Project & Resident Programs. 83/02/23.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 2pp. 17492:027. 24X Fiche: 50-272, 83/02/23, 8303100202.

--8303100210 IE Mgt Meeting Repts 50-272/83-07 & 50-311/83-06 on 830208. Major areas discussed: security improvement program & addl measures per Confirmatory Action Ltr 82-22. Safeguards info deleted (ref 10CFR73.21).
NORRHOLM, L. J. Division of Project & Resident Programs. 83/02/15. 4pp. 17492:029. 24X Fiche: 50-272, 83/02/23, 8303100202.

8303240290 Ack receipt of 821101 transmittal of Rev 7 to security plan. Changes acceptable. Encls to ltr withheld (ref 10CFR73.21).
VARGA, S. A. Operating Reactors Branch 1. 83/03/18. UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 2pp. 17694:358. 24X Fiche: 50-272, 83/03/18, 8303240290.

I. Financial information

8303170159 Forwards Annual Financial Rests 1982 & 1983.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/14. SALTZMAN, J. Assistant Director for State & Licensee Relations. 7pp. 17605:183. 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170169 Annual Financial Rept 1982.
SMITH, R. I. Public Service Electric & Gas Co. of New Jersey. 83/03/14. 52pp. 17605:191. 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170182 Annual Financial Rept 1982.
EVERETT, J. L. Philadelphia Electric Co. 83/03/14. 41pp. 17603:243. 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170193 Annual Financial Rept 1982.
WEIMER, R. D. Delmarva Power & Light Co. 83/02/04. 44pp. 17609:287. 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170206 Annual Financial Rept 1982.
FEEHAN, J. D. Atlantic Electric of New Jersey. 83/03/14. 42pp. 17605:333. 24X Fiche: 50-000, 83/03/14, 8303170159.

P. Operating license stage documents & correspondence

8303280331 "Evaluation of Salem Generating Station."
* Institute of Nuclear Power Operations. 83/01/31. 33pp. 17713:123. 24X Fiche: 50-272, 83/01/31, 8303280331.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303040418 Responds to NRC 830119 & 21 ltrs requesting rationale & justification for protection of proprietary info concerning SER for safety-related equipment. Reasons for declaration are provided in affidavit attached to util 830203 ltr.
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey. 83/02/16. VARGA, S. A. Operating Reactors Branch 1. 2pp. 17374:299. 24X Fiche: 50-272, 83/02/16, 8303040418.

8303160539 Responds to Franklin Research Ctr request for addl info re NRC Categories 1B, 2A & 2B regarding justification for continued operation not previously submitted. Justification submitted.
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey. 83/02/25. VARGA, S. A. Operating Reactors Branch 1. 2pp. 17587:250. 24X Fiche: 50-272, 83/02/25, 8303160539.

8303020321 Generic Ltr 83-12 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303100308 Forwards fee requested in NRC 830120 ltr in payment of Tech Spec changes re operation w/one component cooling water loop inoperable & deferral of 18-month surveillance requirements.
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey. 83/03/03. MILLER, W. D. License Fee Management Branch. 2pp. 17490:244. 24X Fiche: 50-311, 83/03/03, 8303100308.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 31pp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303280322 Forwards Amends 51 & 18 to Licenses DPR-70 & DPR-75, respectively & notice of issuance & availability. Amends delete App B, ETS, re nonradiological water quality-related requirements.
VARGA, S. A. Operating Reactors Branch 1. 83/03/11. UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 4pp. 17713:202. 24X Fiche: 50-272, 83/03/11, 8303280322.

--8303280324 Amends 51 & 18 to Licenses DPR-70 & DPR-75, respectively, deleting App B, ETS, re nonradiological water quality-related requirements.
VARGA, S. A. Operating Reactors Branch 1. 83/03/11. 26pp. 17713:206. 24X Fiche: 50-272, 83/03/11, 8303280322.

--8303280327 Notice of issuance & availability of Amends 51 & 18 to Licenses DPR-70 & DPR-75, respectively.
VARGA, S. A. Operating Reactors Branch 1. 83/03/11. 2pp. 17713:232. 24X Fiche: 50-272, 83/03/11, 8303280322.

Q. Inspection reports, IE Bulletins & correspondence

8303140614 Ack receipt of 821122 ltr & payment of civil penalty proposed in NRC 821027 notice of violation. Proposed security program improvements will be examined during future NRC insp. NRC should be notified of future changes.
HAYNES, R. C. Region 1, Office of Director. 82/12/30. UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 2pp. 17569:304. 24X Fiche: 50-272, 82/12/30, 8303140614.

--8303140621 Responds to NRC 821027 ltr, notice of violation & proposed imposition of civil penalty. Addl security mgt improvement programs initiated. Corrective actions withheld (ref 10CFR73.21).
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 82/11/22. DEYOUNG, R. C. Director's Office. Office of Inspection and Enforcement. 2pp. 17569:306. 24X Fiche: 50-272, 82/12/30, 8303140614.

8303110006 Addl response to FOIA request for 22 categories of documents. Forwards documents listed in App A. Addl documents undergoing review for safeguards info.
FELTON, J. M. Division of Rules and Records. 83/01/31. SHOLLY, S. C. Union of Concerned Scientists. 4pp. 17547:028. 24X Fiche: 50-000, 83/01/31, 8303110006.

--8303110081 Investigation status sheets.
* Director's Office, Office of Inspection and Enforcement. 83/01/31. 22pp. 17547:218. 24X Fiche: 50-000, 83/01/31, 8303110006.

8303010646 Forwards IE Insp Repts 50-272/82-36 & 50-311/82-33 on 821222-830125 & notice of violation.
STAROSTECKI, R. Division of Project & Resident Programs. 83/02/15.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 2pp. 17341:081. 24X Fiche: 50-272, 83/02/15, 8303010646.

--8303010654 Notice of violation from insp on 821222-830125.
* Division of Project & Resident Programs. 83/02/15. 1p. 17341:083. 24X Fiche: 50-272, 83/02/15, 8303010646.

--8303010667 IE Insp Repts 50-272/82-36 & 50-311/82-33 on 821222-830125. Noncompliance noted: daily grab samples not taken & analyzed for gross radioactivity while vent gross radioactivity monitor inoperable.
NORRHOLM, L. J., SUMMERS, R. J., TRIPP, L. E. Division of Project & Resident Programs. 83/02/09. 15pp. 17341:084. 24X Fiche: 50-272, 83/02/15, 8303010646.

8303030644 Forwards IE Insp Repts 50-272/83-04 & 50-311/83-03 on 830124-28. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/02/16.
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey. 2pp. 17410:354. 24X Fiche: 50-272, 83/02/16, 8303030644.

--8303030662 IE Insp Repts 50-272/83-04 & 50-311/83-03 on 830124-28 No noncompliance noted Major areas inspected procedure review, test witnessing & results evaluation of local leak rate testing & review of preparation & schedule for next test. PULLANI, S V ; NORRHOLM, L J Division of Engineering & Technical Programs 83/02/15 6pp 17410 356 24X Fiche 50-272, 83/02/16, 8303030644

8303030156 Forwards IE Insp Repts 50-272/83-05 & 50-311/83-04 on 830124-28 No noncompliance noted. MARTIN, T T Division of Engineering & Technical Programs 83/02/18 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 17412 342 24X Fiche 50-272, 83/02/18, 8303030156

--8303030166 IE Insp Repts 50-272/83-05 & 50-311/83-04 on 830124-28 No noncompliance noted Major areas inspected in-plant radiation protection implementation, respiratory protection program, personnel selection & training & exposure control ROWE, C A ; SHANBAKY, M Region 1, Office of Director 83/02/18 5pp 17412 344 24X Fiche 50-272, 83/02/18, 8303030156

8303100202 Forwards IE Mgt Meeting Repts 50-272/83-07 & 50-311/83-06 on 830208 Util agreement to conduct Security Measure 1 on second shift confirmed per 830210 telcon STAROSTECKI, R Division of Project & Resident Programs 83/02/23 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 17492 027 24X Fiche 50-272, 83/02/23, 8303100202

--8303100210 IE Mgt Meeting Repts 50-272/83-07 & 50-311/83-06 on 830208 Major areas discussed security improvement program & addl measures per Confirmatory Action Ltr 82-22 Safeguards info deleted (ref 10CFR73 21) NORRHOLM, L J ; TRIPP, L E Division of Project & Resident Programs 83/02/15 4pp 17492 029 24X Fiche 50-272, 83/02/23, 8303100202

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 111pp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367

8303140438 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." No Bunker Ramo electrical penetration used or planned for use at facilities LIDEN, E A Public Service Electric & Gas Co of New Jersey 83/03/01 HAYNES, R C Region 1, Office of Director 2pp 17737 357 24X Fiche 50-272, 83/03/01, 8303140438

8303160429 Forwards IE Insp Repts 50-272/83-01 & 50-311/83-01 on 830103-07 & IE Mgt Meeting Repts 50-272/83-10 & 50-311/83-09 on 830215 No noncompliance noted. MARTIN, T T Division of Engineering & Technical Programs 83/03/04 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 3pp 17592 287 24X Fiche 50-272, 83/03/04, 8303160429

--8303160431 IE Insp Repts 50-272/83-01 & 50-311/83-01 on 830103-07 No noncompliance noted Major areas inspected licensee action on previous insp findings, QA organizations, audits & QC MEYER, G W ; BISSETT, P Region 1, Office of Director CAPHTON, D L Division of Engineering & Technical Programs 83/02/17 9pp 17592 290 24X Fiche 50-272, 83/03/04, 8303160429

--8303160433 IE Mgt Meeting Repts 50-272/83-10 & 50-311/83-09 on 830215 Major areas discussed questionable calibr of test meter, 821019 notice of violation item & apparent inaccurate util 821119 response MEYER, G W Region 1, Office of Director BETTENHAUSEN, L Division of Engineering & Technical Programs 83/02/16 4pp 17592 299 24X Fiche 50-272, 83/03/04, 8303160429

8303240521 Forwards IE Insp Repts 50-272/83-09 & 50-311/82-08 conducted by State of WA Dept of Social & Health Svcs on 830117 & notice of violation MARTIN, T T Division of Engineering & Technical Programs 83/03/10 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 17690 338 24X Fiche 50-272, 83/03/10, 8303240521

--8303240527 Notice of violation from insp on 830117 * Region 1, Office of Director 83/03/10 1p 17690 340 24X Fiche 50-272, 83/03/10, 8303240521

--8303240535 IE Insp Repts 50-272/83-09 & 50-311/83-08 conducted by State of WA Dept of Social & Health Svcs on 830117 Noncompliance noted bracing not provided to prevent shift of lading CLEMONS, P ; SHANBAKY, M Region 1, Office of Director 83/03/04 4pp 17690 341 24X Fiche 50-272, 83/03/10, 8303240521

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc 117pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380

8303280258 Forwards IE Insp Repts 50-272/82-33 & 50-311/82-31 on 821109-1221 STAROSTECKI, R Division of Project & Resident Programs 83/03/14 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 17706 211 2 fiche 50-272, 83/03/14, 8303280258

--8303280267 IE Insp Repts 50-272/82-33 & 50-311/82-31 on 821109-1221 Noncompliance noted limiting condition for operation for containment isolation instrumentation exceeded NORRHOLM, L J ; SUMMERS, R J ; WHITE, J R Region 1, Office of Director 83/02/23 17pp 17706 213 24X Fiche 50-272, 83/03/14, 8303280258

8303170250 Advises that IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal," addressed in 830301, 08, 14 & 15 submittals Affidavit encl UDERITZ, R A Public Service Electric & Gas Co of New Jersey 83/03/15 HAYNES, R C Region 1, Office of Director 4pp 17606 137 24X Fiche 50-272, 83/03/15, 8303170250

8303250082 Informs that util responded to 830222 & 25 reactor trip breaker failures & IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal," in 830301, 08, 14 & 15 ltrs Affidavit encl UDERITZ, R A Public Service Electric & Gas Co of New Jersey 83/03/15 HAYNES, R C Region 1, Office of Director 4pp 17693 274 24X Fiche 50-272, 83/03/15, 8303250082

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 121pp 17774 352 24X Fiche 50-000, 83/03/21, 8212060367

R Periodic operating reports & related correspondence

8303040390 Forwards NPDES discharge monitoring repts for Jan 1983 MILLER, L K Public Service Electric & Gas Co of New Jersey 83/02/10 BAKER, R A Environmental Protection Agency 2pp 17369 156 24X Fiche 50-272, 83, 02/10, 8303040390

--8303040634 NPDES discharge monitoring rept for Jan 1983 MILLER, L K Public Service Electric & Gas Co of New Jersey 83/02/10 19pp 17369 158 24X Fiche 50-272, 83/02/10, 8303040390

8303150284 Forwards tabulated rept of personnel exposure during 1982 according to work & job functions Rept labeled Unit 0 represents work common to both units ZUPKO, J M Public Service Electric & Gas Co of New Jersey 83/02/23 HAYNES, R C Region 1, Office of Director 1p 17567 047 24X Fiche 50-272, 83/02/23, 8303150284

--8303150290 Rept of personnel exposure during 1982 * Public Service Electric & Gas Co of New Jersey 83/02/23 6pp 17567 048 24X Fiche 50-272, 83/02/23, 8303150284

8303280279 Forwards "Semiannual Radioactive Effluent Release Rept, Jul-Dec 1982." LIDEN, E A Public Service Electric & Gas Co of New Jersey 83/03/03 HAYNES, R C Region 1, Office of Director 2pp 17706 111 24X Fiche 50-272, 83/03/03, 8303280279

--8303280286 "Semiannual Radioactive Effluent Release Rept, Jul-Dec 1982." * Public Service Electric & Gas Co of New Jersey RERR-131 83/03/31 46pp 17706 113 24X Fiche 50-272, 83/03/03, 8303280279

S Reportable occurrences, LERs & related correspondence

8303110006 Addl response to FOIA request for 22 categories of documents Forwards documents listed in App A Addl documents undergoing review for safeguards info FELTON, J M Division of Rules and Records 83/01/31 SHOLLY, S C Union of Concerned Scientists 4pp 17547 028 24X Fiche 50-000, 83/01/31, 8303110006

--8303110088 Discusses inquiry into 820816 incident involving closing of two emergency diesel generator valves. No further investigation planned. Related info encl.
MATAKAS, R. A. Region 1, Office of Director 82/10/11
SHEPHERD, R. E. Region 1, Office of Director 10pp. 17547:305
24X Fiche: 50-000, 83/01/31, 8303110006

8303080329 Forwards LER 83-003/03L-0. Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
83/02/09 HAYNES, R. C. Region 1, Office of Director 3pp.
17442:358 24X Fiche: 50-311, 83/02/09, 8303080329.

--8303080339 LER 83-003/03L-0 on 830111, rod position indicator channel 1SA2 indicated approx half scale, contrary to flux map indication that no change in rod position occurred. Caused by failed signal conditioner. Module replaced.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey
83/02/04 Region 1, Office of Director 1p. 17442:361 24X
Fiche: 50-311, 83/02/09, 8303080329.

8303030050 Telecopy message of LER 83-007/01P on 830218, two 1,000-klp steam generator snubbers failed to meet lockup & bleed rate velocity requirements. Cause not stated. Investigation continuing. Detailed rept to be submitted in 14 days.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
83/02/18 HAYNES, R. C. Region 1, Office of Director 1p.
17412:195 24X Fiche: 50-311, 83/02/18, 8303030050.

8303030009 Forwards LER 83-005/03L-0. Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
83/02/22 HAYNES, R. C. Region 1, Office of Director 4pp.
17412:334 24X Fiche: 50-311, 83/02/22, 8303030009.

--8303030014 LER 83-005/03L-0 on 830122, during routine cooldown, both channels of pressurizer overpressurization protection sys declared inoperable. Caused by leakage in pressurizer relief lines.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey
83/02/17 Region 1, Office of Director 1p. 17412:338 24X
Fiche: 50-311, 83/02/22, 8303030009.

8303090215 Forwards LER 83-008/99X-0. Detailed event anaysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
83/02/24 HAYNES, R. C. Region 1, Office of Director 3pp.
17472:351 24X Fiche: 50-311, 83/02/24, 8303090215.

--8303090225 LER 83-008/99X-0 on 830218, diesel generator area low pressure carbon monoxide sys automatic initiation feature disabled & tagged out for planned maint. Continuous fire watch established. On 830131, event became reportable.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey
83/02/23 Region 1, Office of Director 1p. 17472:354 24X
Fiche: 50-311, 83/02/24, 8303090215.

8303140238 Forwards LER 83-007/01T-0. Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
83/03/04 HAYNES, R. C. Region 1, Office of Director 3pp.
17539:021 24X Fiche: 50-311, 83/03/04, 8303140238.

--8303140243 LER 83-007/01T-0 on 830210 & 11, during routine surveillance testing, two steam generator snubbers failed to meet acceleration & bleed test requirements. Caused by aging of snubber piston seal rubber matl. Seals will be rebuilt.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey
83/03/03 Region 1, Office of Director 1p. 17539:024 24X
Fiche: 50-311, 83/03/04, 8303140238.

8303140242 Forwards LER 83-009/03L-0. Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
83/03/04 HAYNES, R. C. Region 1, Office of Director 3pp.
17539:003 24X Fiche: 50-311, 83/03/04, 8303140242.

--8303140245 LER 83-009/03L-0 on 830203, during shutdown operation, sample analysis of RCS boron concentration revealed concentration less than Tech Spec limit. Caused by hydrolazing steam generators. RCS boration performed to maintain concentration.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey
83/03/03 Region 1, Office of Director 1p. 17539:006 24X
Fiche: 50-311, 83/03/04, 8303140242.

8303140347 Forwards LER 83-010/03L-0. Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
83/03/04 HAYNES, R. C. Region 1, Office of Director 4pp.
17544:020 24X Fiche: 50-311, 83/03/04, 8303140347.

--8303140361 LER 83-010/03L-0 on 830126, during shutdown operations, control air header 21 isolated & tagged for leak rate testing. PORV 2PR1 closed resulting in loss of RCS vent path. Caused by surge in header 22 due to failed valve.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey
83/03/03 Region 1, Office of Director 1p. 17544:024 24X
Fiche: 50-311, 83/03/04, 8303140347.

8303160189 Confirms 830225 telcon agreement that Unit 1 will not be taken critical w/o prior NRC approval. Agreement will be superseded when issues associated w/830222-25 malfunction of automatic scram sys resolved.
STAROSTECKI, R. Division of Project & Resident Programs 83/03/07
UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey 2pp.
17596:281 24X Fiche: 50-272, 83/03/07, 8303160189.

8303230332 Provides rept on current status of NRC evaluation of 830222 & 25 automatic scram events & NRC action plan for authorizing restart. Show cause order should be issued.
DIRCKS, W. J. Office of the Executive Director for Operations
SECY-83-098A 83/03/14 37pp. 17675:020 24X
Fiche: 50-272, 83/03/14, 8303230332.

8303160730 Forwards TA Rehm memos listing & appending 100 info items re facility event provided to Congressman Udell. Requests placement in PDR.
SCOTT, R. S. Document Management Branch 83/03/16 Public Document Branch 1p. 17611:288 24X Fiche: 50-272, 83/03/16, 8303160730.

--8303160738 Forwards documents pursuant to Congressman Udell request re facility event. Listed draft documents & documents en route from Region 1 omitted.
REHM, T. A. Office of the Executive Director for Operations
83/03/14 KAMMERER, C. Office of Congressional Affairs 1p.
17611:289 24X Fiche: 50-272, 83/03/16, 8303160730.

--8303160745 Forwards addl documents re facility event pursuant to Congressman Udell 830309 request.
REHM, T. A. Office of the Executive Director for Operations
83/03/15 KAMMERER, C. Office of Congressional Affairs 1000pp.
17611:290 24X Fiche: 50-272, 83/03/16, 8303160730.

8303290802 Notification of 830401 meeting w/util group on ATWS to discuss implications of Salem incident on proposed rule PRM-50-29.
ERNST, M. L. Division of Risk Analysis 83/03/23 BAER, R. Office of Nuclear Regulatory Research, Director BARANOWSKY, P., BERNERD, R. Division of Risk Analysis 2pp. 17748:093 24X
Fiche: 50-272, 83/03/23, 8303290802.

T. Hearing transcripts on non-antitrust matters

8303160627 Transcript of 830302 public meeting in Washington, DC re failure of reactor to trip. Pp 1-124.
* Commissioners 83/03/02 169pp. 17603:290 24X
Fiche: 50-272, 83/03/02, 8303160627.

V. Operator Examinations

8303090178 Forwards projected schedule for operator licensing exam/ instructor certificate exam site visits, in response to Generic Ltr 83-01.
LIDEN, E. A. Public Service Electric & Gas Co. of New Jersey
83/02/23 VARGA, S. A. Operating Reactors Branch 1 2pp. 17469:361
24X Fiche: 50-272, 83/02/23, 8303090178.

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

F. Security, medical, emergency & fire protection plans

8303090430 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 83/03/02 Document Management Branch 1p. 17483:180 24X Fiche: 50-312, 83/03/02, 8303090430.

--8303090435 Forwards public version of revised emergency plan implementing procedures, including Procedures AP-580 re training, AP-581.01 re communications drills & AP-585 re emergency assignment verification. Revised index encl.
MATTIMOE, J. J. Sacramento Municipal Utility District 83/02/08
NRC - No Detailed Affiliation Given 4pp. 17483:181 24X
Fiche: 50-312, 83/03/02, 8303090430.

--8303090440 Public version of revised emergency plan implementing procedures, including Procedures AP-580 re training, AP-581.01 re communications drills & AP-585 re emergency assignment verification.
* Sacramento Municipal Utility District 83/02/08 240pp.
17483:185 24X Fiche: 50-312, 83/03/02, 8303090430.

8303110264 Requests exemption from full requirement of 10CFR50.47.b.14 & App E IV.F to conduct full-scale emergency exercise w/state & local govts in CY83. Full-schedule exercise expected early in 1984.
MATTIMOE, J. J. Sacramento Municipal Utility District 83/03/03
ENGELKEN, R. H. Region 5, Office of Director 1p 17520.059 24X
Fiche: 50-312, 83/03/03, 8303110264.

8303140488 Forwards IE Safeguards Insp Rept 50-312/83-03 on 830222-25 & notice of violation. Encls withheld (ref 10CFR2.790 & 73.21).
NORDERHAUG, L. R. Division of Radiological Safety & Safeguards Programs 83/03/08 MATTIMOE, J. J. Sacramento Municipal Utility District 2pp 17540.308 24X Fiche: 50-312, 83/03/08, 8303140488.

8303150238 Forwards one oversize drawing to support util request for exemption from App R requirements, in response to NRC 830110 ltr. Aperture card is available in PDR.
LATHAM, W. H. Sacramento Municipal Utility District 83/03/09
STOLZ, J. F. Operating Reactors Branch 4 1p 17562.256 24X
Fiche: 50-312, 83/03/09, 8303150238.

H. General correspondence

8303010382 Designates RJ Rodrigues as senior mgt contact for all nuclear activities. License amend reflecting organization change presently under preparation.
MATTIMOE, J. J. Sacramento Municipal Utility District 83/02/23
EISENHUT, D. G. Division of Licensing 1p 17345.103 24X
Fiche: 50-312, 83/02/23, 8303010382.

8303110277 Informs of designation of RJ Rodriguez as senior mgt contact for all nuclear activities. Amend reflecting change under preparation.
MATTIMOE, J. J. Sacramento Municipal Utility District 83/02/23
ENGELKEN, R. H. Region 5, Office of Director 1p 17517.352 24X
Fiche: 50-312, 83/02/23, 8303110277.

J. Insurance & indemnity information

8303290344 Forwards Endorsements 63 & 54 to NELIA & MAELU Policies NF-212 & MF-75, respectively.
RODRIGUEZ, R. J. Sacramento Municipal Utility District 83/03/07
SALTZMAN, J. D. Antitrust & Economic analysis Branch (Utility Finance) 3pp 17716.158 24X Fiche: 50-312, 83/03/07, 8303290344.

P. Operating license stage documents & correspondence

8303010004 Forwards Amend 44 to License DPR-54, safety evaluation & notice of issuance & availability. Amend adds surveillance calibr of subcooling meters & position indicators on pressurizer electromagnetic relief valve (PORV).
MINER, S. Operating Reactors Branch 4 83/02/11 MATTIMOE, J. J. Sacramento Municipal Utility District 3pp 17348.288 24X
Fiche: 50-312, 83/02/11, 8303010004.

--8303010007 Amend 44 to License DPR-54 adding surveillance calibr of subcooling meters & position indicators.
STOLZ, J. F. Operating Reactors Branch 4 83/02/11 4pp 17348.291 24X Fiche: 50-312, 83/02/11, 8303010004.

--8303010009 Safety evaluation supporting Amend 44 to License DPR-54.
* Office of Nuclear Reactor Regulation, Director 83/02/11 2pp 17348.295 24X Fiche: 50-312, 83/02/11, 8303010004.

--8303010011 Notice of issuance & availability of Amend 44 to License DPR-54.
STOLZ, J. F. Operating Reactors Branch 4 83/02/11 2pp 17348.297 24X Fiche: 50-312, 83/02/11, 8303010004.

8303040117 Forwards SER of util submittal on NUREG-0737, Item II.B.3, "Post-Accident Sampling Sys." All but four criteria met. Meeting should be held to resolve open items.
STOLZ, J. F. Operating Reactors Branch 4 83/02/15 MATTIMOE, J. J. Sacramento Municipal Utility District 40pp 17424.172 24X
Fiche: 50-312, 83/02/15, 8303040117.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492.033 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303010698 Notification of 830118 meeting w/B&W Owners Group & B&W in Bethesda, MD to discuss plans in developing study re frequency & severity of potential pressurized thermal shock events applicable to all B&W plants.
VISSING, G. Operating Reactors Branch 4 83/02/18 STOLZ, J. Operating Reactors Branch 4 3pp 17348.334 24X
Fiche: 50-000, 83/02/18, 8303010698.

8303020104 Grants interim relief from implementation schedule for head vent installation. Final determination for granting full-term exemption depends upon successful demonstration of ability to safely vent noncondensable gas using hot leg vents.
EISENHUT, D. G. Division of Licensing 83/02/22 MATTIMOE, J. J. Sacramento Municipal Utility District 4pp 17360.141 24X
Fiche: 50-312, 83/02/22, 8303020104.

8303010423 Maintains that NRC & Franklin Research Ctr should determine what portions of technical evaluation rept discussed in 830117 ltr are proprietary. Util unable to delineate proprietary info.
RODRIGUEZ, R. Sacramento Municipal Utility District 83/02/25
STOLZ, J. F. Operating Reactors Branch 4 2pp 17343.264 24X
Fiche: 50-312, 83/02/25, 8303010423.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700.303 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303110099 Forwards response to NRC 821215 request for addl info re inservice testing program relief request.
MATTIMOE, J. J. Sacramento Municipal Utility District 83/03/03
STOLZ, J. F. Operating Reactors Branch 4 7pp 17517.332 24X
Fiche: 50-312, 83/03/03, 8303110099.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp 17660.176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303140022 Responds to proposed Tech Spec Change 71 requesting that electric inverters out-of-svc times be limited to 48 h to control potential risk. Confirmation within 30 days of receipt of ltr requested.
STOLZ, J. F. Operating Reactors Branch 4 83/03/08 MATTIMOE, J. J. Sacramento Municipal Utility District 2pp 17548.066 24X
Fiche: 50-312, 83/03/08, 8303140022.

8303140056 Forwards addl info, per 830217 meeting, re design features of new storage racks, supplementing 820928 licensing rept & proposed license amend. Structural drawings for existing fuel storage pool encl.
LATHAM, W. H. Sacramento Municipal Utility District 83/03/08
STOLZ, J. F. Operating Reactors Branch 4 18pp 17540.173 24X
Fiche: 50-312, 83/03/08, 8303140056.

8303170136 Summary of 830223 meeting w/B&W Regulatory Response Group in Bethesda, MD re small break LOCA procedures & maintaining proper steam generator water level.
VAN VLIET, J. Operating Reactors Branch 4 83/03/08 Operating Reactors Branch 4 43pp 17615.224 24X Fiche: 50-000, 83/03/08, 8303170136.

8303160098 Summary of 830127 meeting w/utils, Bechtel, B&W & Shaw, Pittman, Potts & Trowbridge re extension requests concerning NRC 821210 order for mod of licenses for inadequate core cooling instrumentation. Viewgraphs encl.
MINER, S. Operating Reactors Branch 4 83/03/09 Operating Reactors Branch 4 9pp 17614.323 24X Fiche: 50-000, 83/03/09, 8303160098.

8303180116 Summary of 830209 meeting w/util re responses to NRC 821208 request for addl info concerning design of auxiliary feedwater sys.
MINER, S. Operating Reactors Branch 4 83/03/09 Operating Reactors Branch 4 6pp 17625.173 24X Fiche: 50-312, 83/03/09, 8303180116.

8303210127 Forwards request for addl info re radiation analysis needed to complete review of proposed spent fuel capacity expansion.
STOLZ, J. F. Operating Reactors Branch 4 83/03/09 MATTIMOE, J. J. Sacramento Municipal Utility District 4pp 17660.132 24X
Fiche: 50-312, 83/03/09, 8303210127.

8303210001 Forwards Amend 45 to License DPR-54 & notice of issuance & availability. Amend deletes ETS re nonradiological water quality-related requirements.
STOLZ, J. F. Operating Reactors Branch 4 83/03/11 MATTIMOE, J. J. Sacramento Municipal Utility District 4pp 17659.324 24X
Fiche: 50-312, 83/03/11, 8303210001.

--8303210002 Amend 45 to License DPR-54, deleting ETS re nonradiological water quality-related requirements.
STOLZ, J. F. Operating Reactors Branch 4 83/03/11 14pp 17659.328 24X Fiche: 50-312, 83/03/11, 8303210001.

--8303210003 Notice of issuance & availability of Amend 45 to License DPR-54.
STOLZ, J. F. Operating Reactors Branch 4 83/03/11 2pp.
17659:342 24X Fiche: 50-312, 83/03/11, 8303210001.

8303290418 Forwards order confirming util commitment to implement post-TMI items contained in NUREG-0737 & in responses to Generic Ltrs 82-05 & 82-10.
STOLZ, J. F. Operating Reactors Branch 4 83/03/14 MATTIMOE, J. J. Sacramento Municipal Utility District 3pp 17729:009 24X
Fiche: 50-312, 83/03/14, 8303290418.

--8303290429 Order confirming util commitment to implement post-TMI items contained in NUREG-0737 & in responses to Generic Ltrs 82-05 & 82-10.
PURPLE, R. A. Division of Licensing 83/03/14 Sacramento Municipal Utility District 11pp 17729:012 24X
Fiche: 50-312, 83/03/14, 8303290418.

8303290539 Approves request for extension to 830415 to respond to order re NUREG-0737, Item II.F.2, "Inadequate Core Cooling," subj to encl guidance.
EISENHUT, D. G. Division of Licensing 83/03/14 MATTIMOE, J. J. Sacramento Municipal Utility District 6pp 17742:212 24X
Fiche: 50-312, 83/03/14, 8303290539.

8303220171 Responds to 830222 request for addl info re util 820702 request for exemption from 10CFR50.44 requirements re installation of reactor vessel head vents. Util will participate in integral sys test.
RODRIGUEZ, R. J. Sacramento Municipal Utility District 83/03/15
EISENHUT, D. G. Division of Licensing 1p 17657:166 24X
Fiche: 50-312, 83/03/15, 8303220171.

8303300733 Summary of 830303 meeting w/utils, B&W Owners Group & Natl Nuclear Corp in Bethesda, MD re plans concerning frequency & severity of pressurized thermal shock events for B&W plants. Viewgraphs encl.
VISSING, G. S. Operating Reactors Branch 4 83/03/15 Operating Reactors Branch 4 174pp 17765:013 24X Fiche: 50-000, 83/03/15, 8303300733.

8303300711 Board Notification 83-218: forwards ltr transmitting B&W regulatory response rept re emergency feedwater spray effectiveness & small break LOCA operating procedure.
EISENHUT, D. G. Division of Licensing 83/03/16 PALLADINO, N. J., GILINSKY, V., AHEARNE, J. F. Commissioners. 2pp 17764:275 24X
Fiche: 50-000, 83/03/16, 8303300711.

8303300531 Forwards Amend 46 to License DPR-54, safety evaluation & notice of issuance & availability. Amend adds requirements for degraded voltage protection sys for Class IE equipment installed during refueling outage.
STOLZ, J. F. Operating Reactors Branch 4 83/03/21 MATTIMOE, J. J. Sacramento Municipal Utility District 2pp 17753:342 24X
Fiche: 50-312, 83/03/21, 8303300531.

--8303300536 Amend 46 to License DPR-54, adding requirements for degraded voltage protection sys for Class IE equipment installed during refueling outage.
STOLZ, J. F. Operating Reactors Branch 4 83/03/21 14pp
17753:345 24X Fiche: 50-312, 83/03/21, 8303300531.

--8303300543 Safety evaluation supporting Amend 46 to License DPR-54.
* Office of Nuclear Reactor Regulation, Director 83/03/21 2pp
17753:359 24X Fiche: 50-312, 83/03/21, 8303300531.

--8303300546 Notice of issuance & availability of Amend 46 to License DPR-54.
STOLZ, J. F. Operating Reactors Branch 4 83/03/21 2pp.
17753:361 24X Fiche: 50-312, 83/03/21, 8303300531.

8303290471 Informs that due to discrepancies in B&W rept & development of B&W Owners Group position, submittal of further info re NUREG-0630 implementation concerning clad swell & rupture models not practical until 830515.
RODRIGUEZ, R. J. Sacramento Municipal Utility District 83/03/22
STOLZ, J. F. Operating Reactors Branch 4 1p 17722:352 24X
Fiche: 50-312, 83/03/22, 8303290471.

8303310095 Requests Class III fee for proposed Amend 83 to License DPR-54, dtd 830217, requiring certain Tech Spec changes for compliance w/NUREG-0737.
MILLER, W. O. License Fee Management Branch 83/03/23 MATTIMOE, J. J. Sacramento Municipal Utility District 1p 17775:319 24X
Fiche: 50-312, 83/03/23, 8303310095.

8303290436 Responds to Generic Ltr 83-10f requesting plans & schedules to resolve TMI Action Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps." Plans & schedules to be submitted by 830815.
LATHAM, W. K. Sacramento Municipal Utility District 83/03/24
EISENHUT, D. G. Division of Licensing 1p 17725:323 24X
Fiche: 50-312, 83/03/24, 8303290436.

8303310551 Notification of 830407 meeting w/B&W Owners Group in Bethesda, MD to review progress, schedules & typical event analyses re study of pressurized thermal shock.
VISSING, G. S. Operating Reactors Branch 4 83/03/25 STOLZ, J. F. Operating Reactors Branch 4 2pp 17780:360 24X
Fiche: 50-000, 83/03/25, 8303310551.

## G. Inspection reports, IE Bulletins & correspondence

8303110634 Discusses util 821123 request for reconsideration of 821020 order imposing civil penalties. Careful reexamination of facts & site visit abrogates request. Util has 30 days from date of ltr to pay civil penalties or request hearing.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/01/27 MATTIMOE, J. J. Sacramento Municipal Utility District 2pp 17523:059 24X Fiche: 50-312, 83/01/27, 8303110634.

8303110367 Forwards corrected Pages 5, 6, 8 & 9 to IE Insp Rept 50-312/83-02 transmitted via 830210 ltr.
STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 83/02/22 MATTIMOE, J. J. Sacramento Municipal Utility District 1p 17506:339 24X Fiche: 50-312, 83/02/22, 8303110367.

--8303110368 Corrected Pages 5, 6, 8 & 9 to IE Insp Rept 50-312/83-02.
* Region 5, Office of Director 83/02/23 4pp 17506:340 24X
Fiche: 50-312, 83/02/22, 8303110367.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc 11lpp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303040096 Ack receipt of $120,000 in payment of civil penalties imposed by 821026 order.
AXELRAD, J. A. Director's Office (Pre 820201). 83/02/25.
MATTIMOE, J. J. Sacramento Municipal Utility District. 2pp.
17424:351. 24X Fiche: 50-312, 83/02/25, 8303040096.

8303180401 Forwards IE Insp Rept 50-312/83-01 on 830110-14 & 18-21 & notice of violation.
BOOK, H. E. Division of Radiological Safety & Safeguards Program 83/03/03 MATTIMOE, J. J. Sacramento Municipal Utility District 2pp 17622:183 24X Fiche: 50-312, 83/03/03, 8303180401.

--8303180403 Notice of violation from insp of 830110-14 & 18-21.
WENSLAWSKI, F. A. Region 5, Office of Director 83/03/03 2pp
17622:185 24X Fiche: 50-312, 83/03/03, 8303180401.

--8303180407 IE Insp Rept 50-312/83-01 on 830110-14 & 18-21. Noncompliance noted drum containing contaminated lead shot released from auxiliary bldg for use in uncontrolled area w/o survey of drum interior & contents including smear tests.
SHERMAN, C., NORTH, H. S., WENSLAWSKI, F. A. Region 5, Office of Director 83/03/03 35pp 17622:187 24X Fiche: 50-312, 83/03/03, 8303180401.

8303080479 Forwards IE Mgt Meeting Rept 50-312/83-06 on 830105 & SALP rept for Jul 1981 - Sept 1982. Performance acceptable.
ENGELKEN, R. H. Region 5, Office of Director 83/03/04
RODRIGUEZ, R. J. Sacramento Municipal Utility District 2pp
17452:226 24X Fiche: 50-312, 83/03/04, 8303080479.

--8303080489 IE Mgt Meeting Rept 50-312/83-06 on 830105. No new enforcement actions identified. Major areas discussed: results of SALP for Jul 1981 - Sept 1982.
CANTER, H. L., YOUNG, T. Division of Resident, Reactor Project & Engineering Programs 83/03/02 2pp 17452:250 24X
Fiche: 50-312, 83/03/04, 8303080479.

--8303080499 SALP rept for Jul 1981 - Sept 1982. Performance in area of plant mods w/contractors having limited experience in need of increased NRC & util attention.
* Region 5, Office of Director 82/11/23 38pp 17452:232 24X
Fiche: 50-312, 83/03/04, 8303080479.

--8303080509 Comments on SALP rept for Jul 1981 - Sept 1982. Performance assessment should not be Category 2. Maint activity & fire hazards analysis should be Category 1.
MATTIMOE, J. J. Sacramento Municipal Utility District. 83/02/11
ENGELKEN, R. H. Region 5, Office of Director. 4pp. 17452:270 24X
Fiche: 50-312, 83/03/04, 8303080479.

8303110237 Responds to IE Bulletin 83-01 re failure of Westinghouse DB-type circuit breakers to trip open on receipt of automatic trip signal. No subj breakers in use at facility.
RODRIGUEZ, R. J. Sacramento Municipal Utility District 83/03/07
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 1p 17517:357 24X Fiche 50-312, 83/03/07, 8303110237

8303140488 Forwards IE Safeguards Insp Rept 50-312/83-03 on 830222-25 & notice of violation. Encls withheld (ref 10CFR2.790 & 73.21).
NORDERHAUG, L. R. Division of Radiological Safety & Safeguards Programs 83/03/08 MATTIMOE, J. J. Sacramento Municipal Utility District 2pp 17540:308 24X Fiche 50-312, 83/03/08, 8303140488

8303290291 Forwards IE Insp Rept 50-312/83-04 on 830217-18 & 24-25. No noncompliance noted.
STERNBERG, D. M. Region 5, Office of Director 83/03/08
RODRIGUEZ, R. J. Sacramento Municipal Utility District 2pp
17716:123 24X Fiche 50-312, 83/03/08, 8303290291

--8303290295 IE Insp Rept 50-312/83-04 on 830217-18 & 24-25. No noncompliance noted. Major areas inspected: surveillance & calibr program & independent insp effort.
JOHNSON, P. ; YOUNG, T. Region 5, Office of Director 83/03/08
3pp 17716:125 24X Fiche 50-312, 83/03/08, 8303290291

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc.
117pp 17611:070 24X Fiche 50-000, 83/03/11, 8212060380

8303250018 Submits addl info requested re anticipated m/rem exposure levels for HP1/makeup nozzles C & D insps. Info based on actual manhours worked during 1982 insp.
RODRIGUEZ, R. J. Sacramento Municipal Utility District 83/03/11
MINER, S. NRC - No Detailed Affiliation Given 2pp 17693:255 24X
Fiche 50-312, 83/03/11, 8303250018

8303210080 Notifies of IAEA 830324-25 visit to perform insp of spent fuel. Individual identifications will be held.
STOLZ, J. F. Operating Reactors Branch 4 83/03/14 MATTIMOE, J. J.
Sacramento Municipal Utility District 3pp 17630:256 24X
Fiche 50-312, 83/03/14, 8303210080

8303240079 Advises that J. Skaiylo of BNL will assist w/decontamination of periscope on 830324-25 following IAEA insp of facility.
STOLZ, J. F. Operating Reactors Branch 4 83/03/16 RODRIGUEZ, R. J.
Sacramento Municipal Utility District 3pp 17694:125 24X
Fiche 50-312, 83/03/16, 8303240079

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 11?pp 24X Fiche 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12ipp 17774:352 24X Fiche 50-000, 83/03/21, 8212060387

R. Periodic operating reports & related correspondence

8303150342 Forwards monthly operating rept for Feb 1983.
RODRIGUEZ, R. J. Sacramento Municipal Utility District 83/03/07
Director's Office, Office of Inspection and Enforcement 1p
17566:255 24X Fiche 50-312, 83/03/07, 8303150342

--8303150346 Monthly operating rept for Feb 1983.
COLOMBO, R. Sacramento Municipal Utility District 83/02/28 5pp
17566:256 24X Fiche 50-312, 83/03/07, 8303150342

8303300225 Forwards Rev 1 to monthly operating rept for Feb 1983.
RODRIGUEZ, R. J. Sacramento Municipal Utility District 83/03/24
Director's Office, Office of Inspection and Enforcement 1p
17733:111 24X Fiche 50-312, 83/03/24, 8303300225

--8303300233 Rev 1 to monthly operating rept for Feb 1983.
COLOMBO, R. Sacramento Municipal Utility District 83/03/24 1p
17733:112 24X Fiche 50-312, 83/03/24, 8303300225

S. Reportable occurrences, LERs & related correspondence

8303110149 Forwards LER 83-005/03L-0. Detailed event analysis submitted.
MATTIMOE, J. J. Sacramento Municipal Utility District 83/02/18
ENGELKEN, R. H. Region 5, Office of Director 1p 23022:303 24X
Fiche 50-312, 83/02/18, 8303110149

--8303110160 LER 83-005/03L-0 on 830125, nuclear svc cooling water pump B failed to start after start button depressed. No cause stated. Pump started second time after delay. No problems found in breaker or control sys.
COLOMBO, R. W. Sacramento Municipal Utility District 83/02/17
Region 5, Office of Director 1p 17517:313 24X
Fiche 50-312, 83/02/18, 8303110149

8303110354 Forwards LER 83-006/03L-0. Detailed event analysis submitted.
MATTIMOE, J. J. Sacramento Municipal Utility District 83/02/18
ENGELKEN, R. H. Region 5, Office of Director 2pp 17506:350 24X
Fiche 50-312, 83/02/18, 8303110354

--8303110361 LER 83-006/03L-0 on 821213, control air to main feedwater valve not lined up & kept open. On 830124, condition indicating procedural error noted. Procedures did not ensure valve would stroke prior to startup.
COLOMBO, R. W. Sacramento Municipal Utility District 83/02/18
Region 5, Office of Director 1p 17506:352 24X
Fiche 50-312, 83/02/18, 8303110354

8303110311 Forwards followup LER 82-024/03L-1. Detailed event analysis submitted.
MATTIMOE, J. J. Sacramento Municipal Utility District 83/02/25
ENGELKEN, R. H. Region 5, Office of Director 2pp 17518:118 24X
Fiche 50-312, 83/02/25, 8303110311

--8303110318 Followup LER 82-024/03L-1 on 820818. Class I cable tray (carrying B safeguards channel) had two supports cut back & replaced w/temporary supports. Supports replaced & all electrical foremen reinstructed.
COLOMBO, R. W. Sacramento Municipal Utility District 82/09/16
Region 5, Office of Director 1p 17518:120 24X
Fiche 50-312, 83/02/25, 8303110311

8303110357 Forwards LER 83-007/03L-0. Detailed event analysis submitted.
RODRIGUEZ, R. J. Sacramento Municipal Utility District 83/03/02
ENGELKEN, R. H. Region 5, Office of Director 1p 17506:245 24X
Fiche 50-312, 83/03/02, 8303110357

--8303110364 LER 83-007/03L-0 on 830204, reactor coolant pump C manually tripped due to excessive vibration. Reactor protection sys D channel underpower relay did not sense trip resulting in improper lineup of auxiliary feedwater pump autostart logic.
COLOMBO, R. W. Sacramento Municipal Utility District 83/03/02
Region 5, Office of Director 1p 17506:246 24X
Fiche 50-312, 83/03/02, 8303110357

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp 24X Fiche 50-000, 83/02/24, 8302250505

DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1

F. Security, medical, emergency & fire protection plans

8303280252 Notifies that emergency notification sys telephone will be moved within technical support ctr per 821210 request. Health physics network telephone will not be moved due to changeover to FTS.
SEIDLE, W. C. Region 4, Office of Director 83/01/25 CAVANAUGH, W.
Arkansas Power & Light Co. 1p 17706:281 24X
Fiche 50-313, 83/01/25, 8303280252

--8303280266 Requests that emergency notification sys & health physics network telephones be moved to main floor of technical support ctr to be available for Mar 1983 emergency preparedness exercise.
MARSHALL, J. R. Arkansas Power & Light Co. 82/12/10 SEIDLE, W. C.
Region 4, Office of Director 2pp 17706:282 24X
Fiche 50-313, 83/01/25, 8303280252

8303010237 Forwards IE Insp Repts 50-313/82-24 & 50-368/82-21 on 820728-29. Violation re prompt public notification corrected. No further info required.
SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 83/02/11 CAVANAUGH, W. Arkansas Power & Light Co. 2pp
17335:179 24X Fiche 50-313, 83/02/11, 8303010237

--8303010247 IE Insp Repts 50-313/82-24 & 50-368/82-21 on 820728-29. Noncompliance noted: lack of capability for providing prompt public notification in portion of plume exposure pathway.
HACKNEY, C. A. ; MONTGOMERY, J. L. ; WASHINGTON, K. E. Division of Resident, Reactor Project & Engineering Programs 83/02/09 7pp
17335:181 24X Fiche 50-313, 83/02/11, 8303010237

8303010641 Requests assistance in determining optional locations for emergency notification sys & health physics network (HPN) phones in emergency response facilities, supplementing NUREG-0696. Replacement of HPN lines w/FTS lines considered. COLLINS, J. T. Region 4, Office of Director 83/02/24 CAVANAUGH, W. Arkansas Power & Light Co. 2pp. 17336:112 24X Fiche: 50-313, 83/02/24, 8303010641.

8303010682 Ack receipt of 830112 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/82-15 & 50-368/82-12. SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs. 83/02/25 CAVANAUGH, W. Arkansas Power & Light Co. 1p. 17341:160 24X Fiche: 50-313, 83/02/25, 8303010682.

--8303010685 Responds to NRC 821112 ltr re violations noted in IE Insp Repts 50-313/82-15 & 50-368/82-12. Closed end rigid metal conduit penetrating frame will not significantly affect fire resistant ability of door assemblies. MARSHALL, J. R. Arkansas Power & Light Co. 83/01/12 SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs. 2pp. 17341:161 24X Fiche: 50-313, 83/02/25, 8303010682.

8303090410 Releases public version of revised emergency plan implementing procedure instructions. FELTON, J. M. Division of Rules and Records 83/03/02 Document Management Branch 1p. 17484:092 24X Fiche: 50-313, 83/03/02, 8303090410.

--8303090414 Forwards public version of instructions to delete Rev 4 to Emergency Plan Implementing Procedure 1202.40 re refueling accident & Rev 5 to 1202.44 re natural emergencies. * Arkansas Power & Light Co. 83/02/01 NRC - No Detailed Affiliation Given. 5pp. 17484:093 24X Fiche: 50-313, 83/03/02, 8303090410.

8303090576 Releases public version of util 821210 ltr re distribution of emergency instructions to transient population. FELTON, J. M. Division of Rules and Records 83/03/02 Document Management Branch 1p. 17480:147 24X Fiche: 50-313, 83/03/02, 8303090576.

--8303090583 Forwards public version of util 821210 ltr re distribution of emergency instructions to transient population. SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs. 83/02/08 CAVANAUGH, W. Arkansas Power & Light Co. 2pp. 17480:148 24X Fiche: 50-313, 83/03/02, 8303090576.

--8303090594 Submits public version of info re distribution of emergency instructions to transient population. Program will be implemented within 90 days. MARSHALL, J. R. Arkansas Power & Light Co. 82/12/10 COLLINS, J. T. Region 4, Office of Director 2pp. 17480:150 24X Fiche: 50-313, 83/03/02, 8303090576.

8303210234 Application for amend to Licenses DPR-51 & NPF-6, changing Tech Specs to require annual audits of emergency plan & security plan. GRIFFIN, J. M. Arkansas Power & Light Co. 83/03/15 STOLZ, J. F. Operating Reactors Branch 4 CLARK, R. A. Operating Reactors Branch 3 2pp. 17632:170 24X Fiche: 50-313, 83/03/15, 8303210234.

--8303210244 Proposed Tech Specs re annual audits of emergency plan & security plan. * Arkansas Power & Light Co. 83/03/15 3pp. 17632:172 24X Fiche: 50-313, 83/03/15, 8303210234.

8303230160 Releases public version of revised emergency plan implementing procedure. FELTON, J. M. Division of Rules and Records 83/03/16 Document Management Branch 1p. 17687:108 24X Fiche: 50-313, 83/03/16, 8303230160.

--8303230164 Forwards public version of Rev 4 to Emergency Plan Implementing Procedure 1903.42, "Duties of Emergency Medical Team." Receipt form encl. * Arkansas Power & Light Co. 83/03/03 NRC - No Detailed Affiliation Given. 1p. 17687:109 24X Fiche: 50-313, 83/03/16, 8303230160.

--8303230170 Public version of Rev 4 to Emergency Plan Implementing Procedure 1903.42, "Duties of Emergency Medical Team." Revised index encl. LEVINE, J. M. Arkansas Power & Light Co. 83/03/03 4pp. 17687:110 24X Fiche: 50-313, 83/03/16, 8303230160.

8303240469 Ack receipt of 830217 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/82-33 & 50-368/82-33. SEIDLE, W. C. Region 4, Office of Director 83/03/18 GRIFFIN, J. M. Arkansas Power & Light Co. 1p. 17678:036 24X Fiche: 50-313, 83/03/18, 8303240469.

--8303240478 Responds to NRC 830118 ltr re violations noted in IE Insp Repts 50-313/82-33 & 50-368/82-33. Corrective actions: nonconformance rept procedure revised, fire watch established & independent walkdown of fire barriers conducted. MARSHALL, J. R. Arkansas Power & Light Co. 83/02/17 SEIDLE, W. C. Region 4, Office of Director 4pp. 17678:037 24X Fiche: 50-313, 83/03/18, 8303240469.

8303250001 Releases public version of revised emergency plan implementing procedures. FELTON, J. M. Division of Rules and Records 83/03/21 Document Management Branch 1p. 17710:139 24X Fiche: 50-313, 83/03/21, 8303250001.

--8303250004 Forwards public version of revised emergency plan implementing procedures, including Procedures 1903.30 re plant evacuation, 1903.50 re emergency response organization & 1904.07 re protective action recommendations. * Arkansas Power & Light Co. 83/03/10 NRC - No Detailed Affiliation Given. 3pp. 17710:140 24X Fiche: 50-313, 83/03/21, 8303250001.

--8303250005 Public version of revised emergency plan implementing procedures, including Procedures 1903.30 re plant evacuation, 1903.50 re emergency response organization & 1904.07 re protective action recommendations. * Arkansas Power & Light Co. 83/03/10 32pp. 17710:143 24X Fiche: 50-313, 83/03/21, 8303250001.

8303290634 Releases public version of distribution list of emergency instructions to transient population. FELTON, J. M. Division of Rules and Records 83/03/23 Document Management Branch 1p. 17745:153 24X Fiche: 50-313, 83/03/23, 8303290634.

--8303290641 Forwards public version of distribution list of emergency instructions to transient population. MARSHALL, J. R. Arkansas Power & Light Co. 83/02/25 COLLINS, J. T. Region 4, Office of Director 6pp. 17745:154 24X Fiche: 50-313, 83/03/23, 8303290634.

8303290669 Releases public version of revised emergency plan implementing procedure. FELTON, J. M. Division of Rules and Records 83/03/23 Document Management Branch 1p. 17742:320 24X Fiche: 50-313, 83/03/23, 8303290669.

--8303290685 Forwards public version of Rev 8 to Emergency Plan Implementing Procedure 1903.10, "Emergency Action Level Response." Receipt form encl. * Arkansas Power & Light Co. 83/03/04 NRC - No Detailed Affiliation Given. 2pp. 17742:321 24X Fiche: 50-313, 83/03/23, 8303290669.

--8303290699 Public version of Rev 8 to Emergency Plan Implementing Procedure 1903.10, "Emergency Action Level Response." LEVINE, J. M. Arkansas Power & Light Co. 83/03/04 13pp. 17742:323 24X Fiche: 50-313, 83/03/23, 8303290669.

8303290708 Releases public version of revised emergency plan implementing procedure. FELTON, J. M. Division of Rules and Records 83/03/23 Document Management Branch 1p. 17745:173 24X Fiche: 50-313, 83/03/23, 8303290708.

--8303290711 Forwards public version of Rev 6 to Emergency Plan Implementing Procedure 1903.30, "Plant Evacuation." * Arkansas Power & Light Co. 83/03/09 NRC - No Detailed Affiliation Given. 2pp. 17745:174 24X Fiche: 50-313, 83/03/23, 8303290708.

--8303290716 Public version of Rev 6 to Emergency Plan Implementing Procedure 1903.30, "Plant Evacuation." LEVINE, J. M. Arkansas Power & Light Co. 83/03/08 21pp. 17745:176 24X Fiche: 50-313, 83/03/23, 8303290708.

8303300044 Releases public version of rev to emergency plan procedure. FELTON, J. M. Division of Rules and Records 83/03/23 Document Management Branch 1p. 17751:126 24X Fiche: 50-313, 83/03/23, 8303300044.

--8303300049 Forwards public version of Rev 6 to Emergency Plan Procedure 1903.23, "Personnel Emergency." * Arkansas Power & Light Co. 83/03/08 NRC - No Detailed Affiliation Given. 2pp. 17751:127 24X Fiche: 50-313, 83/03/23, 8303300044.

--8303300054 Public version of Rev 6 to Emergency Plan Procedure 1903.23, "Personnel Emergency." LEVINE, J. M. Arkansas Power & Light Co. 83/03/07 8pp. 17751:129 24X Fiche: 50-313, 83/03/23, 8303300044.

8303290015 Notifies of repts received from several utils re telephone inquiries from unidentified persons re plant security sys. Investigation revealed that individual was personnel recruiter. Individual cautioned.
COLLINS, J. T. Region 4, Office of Director. 83/03/25. GRIFFIN, J. M. Arkansas Power & Light Co. 2pp. 17722:249. 24X Fiche: 50-313, 83/03/25, 8303290015.

8303300610 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/25. Document Management Branch. 1p. 17768:294. 24X Fiche: 50-313, 83/03/25, 8303300610.

--8303300619 Forwards public version of Rev 2 to Emergency Plan Implementing Procedure 1903.61, "Communications Equipment Tests."
* Arkansas Power & Light Co. 83/03/17. NRC - No Detailed Affiliation Given. 1p. 17768:295. 24X Fiche: 50-313, 83/03/25, 8303300610.

--8303300633 F[illegible]ersion of Rev 2 to Emergency Plan Implementing Procedure [illegible].1, "Communications Equipment Tests." Revised index encl.
LEVINE, J. M. Arkansas Power & Light Co. 83/03/16. 7pp. 17768:296. 24X Fiche: 50-313, 83/03/25, 8303300610.

H. General correspondence

8303110240 Designates J. Griffin as senior nuclear mgt representative for util.
CAVANAUGH, W. Arkansas Power & Light Co. 83/02/17. COLLINS, J. T. Region 4, Office of Director. 2pp. 17518:361. 24X Fiche: 50-313, 83/02/17, 8303110240.

8303040594 Forwards revised distribution list to reflect changes in State of AR Dept of Health & util organizations.
MARSHALL, J. R. Arkansas Power & Light Co. 83/03/01. STOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17373:316. 24X Fiche: 50-313, 83/03/01, 8303040594.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303010698 Notification of 830118 meeting w/B&W Owners Group & B&W in Bethesda, MD to discuss plans in developing study re frequency & severity of potential pressurized thermal shock events applicable to all B&W plants.
VISSING, G. Operating Reactors Branch 4. 83/02/18. STOLZ, J. Operating Reactors Branch 4. 3pp. 17348:334. 24X Fiche: 50-000, 83/02/18, 8303010698.

8303020442 Advises that only interim relief granted from implementation deadline for installation of reactor vessel head vent until demonstration of B&W Owners Group integral sys test program. Listed info required to consider deadline extension.
EISENHUT, D. G. Division of Licensing. 83/02/22. CAVANAUGH, W. Arkansas Power & Light Co. 4pp. 17357:236. 24X Fiche: 50-313, 83/02/22, 8303020442.

8303030703 Notification of 830307 meeting w/utils & NUS Corp in Bethesda, MD to discuss proposed rev to 10CFR40, Appendix A (Tech Specs).
BRINKMAN, D. S. Standardization & Special Projects Branch. 83/02/22. THOMAS, C. O. Standardization & Special Projects Branch. 2pp. 17363:227. 24X Fiche: 50-000, 83/02/22, 8303030703.

8303010415 Application for amend to Licenses DPR-51 & NPF-6, revising Tech Specs to change in-core detector surveillance requirements & to correct various typographical, title & ref errors.
GRIFFIN, J. M. Arkansas Power & Light Co. 83/02/23. CLARK, R. A. Operating Reactors Branch 3. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 17343:231. 24X Fiche: 50-313, 83/02/23, 8303010415.

--8303010417 Proposed Tech Specs re in-core detector surveillance requirements.
* Arkansas Power & Light Co. 83/02/23. 28pp. 17343:233. 24X Fiche: 50-313, 83/02/23, 8303010415.

8303010418 Discusses understanding re 821210 order for mod to OL concerning inadequate core cooling, per 830127 meeting w/NRC. Util 830117 request for extension of deadline for hearing requests will be withdrawn. NRC confirmation requested.
GRIFFIN, J. M. Arkansas Power & Light Co. 83/02/23. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17343:261. 24X Fiche: 50-313, 83/02/23, 8303010418.

8303040348 Application for amend to Licenses DPR-51 & NPF-6, changing Tech Specs Section 6 to require annual reporting of safety & relief valve challenges, in response to NRC 820920 Generic Ltr 82-16.
GRIFFIN, J. M. Arkansas Power & Light Co. 83/02/25. STOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17374:321. 24X Fiche: 50-313, 83/02/25, 8303040348.

--8303040353 Proposed changes to Tech Specs Section 6, requiring annual reporting of safety & relief valve challenges.
* Arkansas Power & Light Co. 83/02/25. 2pp. 17374:323. 24X Fiche: 50-313, 83/02/25, 8303040348.

8303040407 Advises that efforts underway & progress being made toward compliance w/820210 order for mod of license re detection of inadequate core cooling. Response expected by 830415.
MARSHALL, J. R. Arkansas Power & Light Co. 83/02/25. STOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17374:307. 24X Fiche: 50-313, 83/02/25, 8303040407.

8303040393 Provides status on station electrical distribution voltage verification test. Test scheduled for 830304.
MARSHALL, J. R. Arkansas Power & Light Co. 83/02/28. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 17426:244. 24X Fiche: 50-313, 83/02/28, 8303040393.

8303040593 Documents commitment to integral sys testing program described by B&W Owners Group 830113 ltr. Need for program linked w/several TMI-related issues.
MARSHALL, J. R. Arkansas Power & Light Co. 83/02/28. STOLZ, J. F. Operating Reactors Branch 4. 1p. 17373:318. 24X Fiche: 50-313, 83/02/28, 8303040593.

8303040597 Requests extension for submittal of response to App I Tech Specs. Revised response schedule will be submitted by 830311.
MARSHALL, J. R. Arkansas Power & Light Co. 83/02/28. STOLZ, J. F. Operating Reactors Branch 4. Operating Reactors Branch 3. 1p. 17374:283. 24X Fiche: 50-313, 83/02/28, 8303040597.

8303070128 Responds to NRC 830126 ltr re schedule for response concerning electrical equipment. Completed response will not be provided within 30 days. Justification for interim operation encl.
MARSHALL, J. R. Arkansas Power & Light Co. 83/02/28. STOLZ, J. F. Operating Reactors Branch 4. 4pp. 17433:071. 24X Fiche: 50-313, 83/02/28, 8303070128.

8303110398 Forwards Amend 70 to License DPR-51, safety evaluation & notice of issuance & availability. Amend implements secondary water chemistry monitoring program.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/01. CAVANAUGH, W. Arkansas Power & Light Co. 3pp. 17523:042. 24X Fiche: 50-313, 83/03/01, 8303110398.

--8303110401 Amend 70 to License DPR-51, implementing secondary water chemistry monitoring program.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/01. 2pp. 17523:043. 24X Fiche: 50-313, 83/03/01, 8303110398.

--8303110404 Safety evaluation supporting Amend 70 to License DPR-51.
* Office of Nuclear Reactor Regulation, Director. 83/03/01. 3pp. 17523:047. 24X Fiche: 50-313, 83/03/01, 8303110398.

--8303110408 Notice of issuance & availability of Amend 70 to License DPR-51.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/01. 2pp. 17523:050. 24X Fiche: 50-313, 83/03/01, 8303110398.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303080062 Forwards addl chemical engineering info re proposed spent fuel storage expansion, per NRC 830110 request. Demineralized resins more than adequate to maintain water quality for 1 yr under normal circumstances.
MARSHALL, J. R. Arkansas Power & Light Co. 83/03/03. STOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17457:227. 24X Fiche: 50-313, 83/03/03, 8303080062.

8303080299 Forwards addl info re proposed spent fuel storage expansion per 830124 request Proposed Tech Specs associated w/rack expansion address NUREG-0830 elements Administrative controls established to prevent loading errors.
MARSHALL, J. R. Arkansas Power & Light Co. 83/03/03. STOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 6pp. 17449:321. 24X Fiche: 50-313, 83/03/03, 8303080299.

8303160388 Forwards addl info re proposed spent fuel storage expansion, in response to NRC 830105 request. W/14 oversize drawings. Proprietary drawings withheld (ref 10CFR2.790). Proprietary aperture cards in Central Files, nonproprietary in PDR.
MARSHALL, J. R. Arkansas Power & Light Co. 83/03/03. STOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 81pp. 17591:140. 24X Fiche: 50-313, 83/03/03, 8303160388.

--8303160395 Application for withholding seven oversize proprietary drawings (ref 10CFR2.790). Affidavit encl.
WIESEMANN, R. A. Westinghouse Electric Corp. 83/02/21. STOLZ, J. F. Operating Reactors Branch 4. 6pp. 17591:221. 24X Fiche: 50-313, 83/03/03, 8303160388.

8303110328 Advises that written notification of determination to reaffirm or withdraw request for hearing re order imposing environ qualification requirements will be submitted by 830324.
MARSHALL, J. R. Arkansas Power & Light Co. 83/03/04. EISENHUT, D. G. Division of Licensing. 1p. 17512:354. 24X Fiche: 50-313, 83/03/04, 8303110328.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 5ipp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303090279 Releases util 821022 rept, "Response to NRC Questions on Pressurizer Relief & Safety Valves," for public disclosure.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/07. BAILEY, I. Records Services & Facilities Branch. 1p. 17473:101. 24X Fiche: 50-313, 83/03/07, 8303090279.

--8211020433 "Response to NRC Questions on Pressurizer Relief & Safety Valves."
* Babcock & Wilcox Co. 82/10/22. 42pp. 17473:106. 24X Fiche: 50-313, 83/03/07, 8303090279.

8303110352 Forwards addl info re spent fuel storage expansion per 830201 request Seismic analysis performed using combined weights of fuel assembly & control rod assembly in each cell location.
MARSHALL, J. R. Arkansas Power & Light Co. 83/03/07. STOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 29pp. 17506:247. 24X Fiche: 50-313, 83/03/07, 8303110352.

8303140059 Notifies that info re spent fuel storage expansion will be submitted by end of current wk in response to 830215 request.
MARSHALL, J. R. Arkansas Power & Light Co. 83/03/07. STOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 1p. 17540:172. 24X Fiche: 50-313, w3/03/07, 8303140059.

8303160051 Forwards request for addl info re expected dose to onsite personnel during spent fuel pool expansion.
CLARK, R. A. Operating Reactors Branch 4. 83/03/07. GRIFFIN, J. M. Arkansas Power & Light Co. 3pp. 17615:001. 24X Fiche: 50-313, 83/03/07, 8303160051.

8303150668 Authorizes refund of $4,000 for 820402 application for App H exemption re spent fuel pool.
MILLER, W. O. License Fee Management Branch. 83/03/08. CAVANAUGH, W. Arkansas Power & Light Co. 2pp. 17586:256. 24X Fiche: 50-313, 83/03/08, 8303150668.

8303170136 Summary of 830223 meeting w/B&W Regulatory Response Group in Bethesda, MD re small break LOCA procedures & maintaining proper steam generator water level.
VAN VLIET, J. Operating Reactors Branch 4. 83/03/08. Operating Reactors Branch 4. 43pp. 17615:224. 24X Fiche: 50-000, 83/03/08, 8303170136.

8303160098 Summary of 830127 meeting w/utils, Bechtel, B&W & Shaw, Pittman, Potts & Trowbridge re extension requests concerning NRC 821210 order for mod of licenses for inadequate core cooling instrumentation. Viewgraphs encl.
MINER, S. Operating Reactors Branch 4. 83/03/09. Operating Reactors Branch 4. 9pp. 17614:323. 24X Fiche: 50-000, 83/03/09, 8303160098.

8303140370 Forwards response to NRC 830215 request for addl info re proposed spent fuel storage expansion Poison surveillance program, which allows access to representative poison samples, will be utilized.
MARSHALL, J. R. Arkansas Power & Light Co. 83/03/10. STOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 4pp. 17543:320. 24X Fiche: 50-313, 83/03/10, 8303140370.

8303150340 Advises of 830405 meeting w/licensees & major contractors at Dallas/Fort Worth, TX to provide info & guidance re 10CFR50 QA & Tech Spec deviations & discuss decentralization policy. Questions should be submitted in writing by 830321.
COLLINS, J. T. Region 4, Office of Director. 83/03/10. Public Service Co. of Colorado. 12pp. 17562:291. 24X Fiche: 50-000, 83/03/10, 8303150340.

8303210007 Forwards Amend 71 to License DPR-51, safety evaluation & notice of issuance & availability. Amend revises Tech Specs to support operation at full rated power during Cycle 6.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/10. GRIFFIN, J. M. Arkansas Power & Light Co. 2pp. 17660:012. 24X Fiche: 50-313, 83/03/10, 8303210007.

--8303210008 Amend 71 to License DPR-51, revising Tech Specs to support operation at full rated power during Cycle 6.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/10. 29pp. 17660:014. 24X Fiche: 50-313, 83/03/10, 8303210007.

--8303210010 Safety evaluation supporting Amend 71 to License DPR-51.
* Office of Nuclear Reactor Regulation, Director. 83/03/10. 9pp. 17660:043. 24X Fiche: 50-313, 83/03/10, 8303210007.

--8303210011 Notice of issuance & availability of Amend 71 to License DPR-51.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/10. 2pp. 17660:052. 24X Fiche: 50-313, 83/03/10, 8303210007.

8303150257 Notifies of 830405 public meeting at Dallas/Fort Worth, TX Airport to discuss NRC decentralization policy & changes to 10CFR50 reporting requirements.
COLLINS, J. T. Region 4, Office of Director. 83/03/11. GRIFFIN, J. M. Arkansas Power & Light Co. 3pp. 17555:215. 24X Fiche: 50-313, 83/03/11, 8303150257.

8303150473 Application for amend to License DPR-51, revising reactor bldg tendon surveillance requirement to reduce number of tendons from 21 to 9 for tenth year & all subsequent tendon surveillances.
GRIFFIN, J. M. Arkansas Power & Light Co. 83/03/11. STOLZ, J. F. Operating Reactors Branch 4. 3pp. 17561:035. 24X Fiche: 50-313, 83/03/11, 8303150473.

--8303150474 Proposed Tech Specs re reactor bldg tendon surveillance requirement, reducing number of surveillance tendons from 21 to 9 for tenth year & all subsequent tendon surveillances.
* Arkansas Power & Light Co. 83/03/11. 6pp. 17561:038. 24X Fiche: 50-313, 83/03/11, 8303150473.

8303210399 Requests extension until 830930 for submittal of complete up-to-date App I Tech Specs. Review of App I hampered by manpower availability as result of back-to-back refueling outages.
MARSHALL, J. R. Arkansas Power & Light Co. 83/03/11. STOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17634:151. 24X Fiche: 50-313, 83/03/11, 8303210399.

8303240067 Forwards Amends 72 & 40 to Licenses DPR-51 & NPF-6, respectively & notice of issuance & availability. Amends revise App B ETS re nonradiological water quality-related requirements.
STOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 83/03/11. GRIFFIN, J. Arkansas Power & Light Co. 5pp. 17694:198. 24X Fiche: 50-313, 83/03/11, 8303240067.

--8303240073 Amends 72 & 40 to Licenses DPR-51 & NPF-6, respectively, revising App B ETS re nonradiological water quality-related requirements of Federal Water Pollution Control Act amends of 1972.
STOLZ, J. F. Operating Reactors Branch 4. CLARK, R. A. Operating Reactors Branch 3. 83/03/11. 34pp. 17694:203. 24X Fiche: 50-313, 83/03/11, 8303240067.

--8303240080 Notice of issuance & availability of Amends 72 & 40 to Licenses DPR-51 & NPF-6, respectively.
CLARK, R. A. Operating Reactors Branch 3. 83/03/11. 2pp. 17694:237. 24X Fiche: 50-313, 83/03/11, 8303240067.

8303290605 Forwards order confirming licensee commitments on post-TMI-related issues contained in NUREG-0737 Order based on commitments contained in util responses to Generic Ltrs 82-05 & 82-10.
STOLZ, J. F. Operating Reactors Branch 4 83/03/14 CAVANAUGH, W.
Arkansas Power & Light Co. 3pp. 17744:345 24X
Fiche: 50-313, 83/03/14, 8303290605.

--8303290622 Order confirming licensee commitments on post-TMI-related issues contained in NUREG-0737.
PURPLE, R. A. Assistant Director for Licensing 83/03/14
Arkansas Power & Light Co. 9pp. 17744:348 24X
Fiche: 50-313, 83/03/14, 8303290605.

8303210234 Application for amend to Licenses DPR-51 & NPF-6, changing Tech Specs to require annual audits of emergency plan & security plan.
GRIFFIN, J. M. Arkansas Power & Light Co. 83/03/15 STOLZ, J. F.
Operating Reactors Branch 4 CLARK, R. A. Operating Reactors Branch 3. 2pp. 17632:170 24X Fiche: 50-313, 83/03/15, 8303210234.

--8303210244 Proposed Tech Specs re annual audits of emergency plan & security plan.
* Arkansas Power & Light Co. 83/03/15 3pp. 17632:172 24X
Fiche: 50-313, 83/03/15, 8303210234.

8303220034 Forwards six oversize revised P&IDs. Aperture cards are available in PDR.
SHIVELY, C. Arkansas Power & Light Co. 83/03/15 NRC - No Detailed Affiliation Given. 2pp. 17649:266 24X
Fiche: 50-313, 83/03/15, 8303220034.

8303220044 Requests addl time to correct data inconsistencies of B&W supplemental ECCS calculations addressing impact of cladding models presented in NUREG-0630, "Results of Bounding Analysis." Corrected rept expected by 830515.
MARSHALL, J. R. Arkansas Power & Light Co. 83/03/15 STOLZ, J. F.
Operating Reactors Branch 4 1p. 17652:158 24X
Fiche: 50-313, 83/03/15, 8303220044.

8303300733 Summary of 830303 meeting w/utils, B&W Owners Group & Natl Nuclear Corp in Bethesda, MD re plans concerning frequency & severity of pressurized thermal shock events for B&W plants. Viewgraphs encl.
VISSING, G. S. Operating Reactors Branch 4 83/03/15 Operating Reactors Branch 4. 174pp. 17765:013 24X Fiche: 50-000, 83/03/15, 8303300733.

8303210277 Forwards cooldown & heatup dates for each unit since OL issuance & Tech Spec changes re reactor bldg purge valves. Action initiated to install key lock switches on containment purge valves by next refueling outage per 830127 request.
GRIFFIN, J. M. Arkansas Power & Light Co. 83/03/16 STOLZ, J. F.
Operating Reactors Branch 4 CLARK, R. A. Operating Reactors Branch 3. 6pp. 17632:036 24X Fiche: 50-313, 83/03/16, 8303210277.

--8303210283 Proposed Tech Spec changes re reactor bldg purge valves.
* Arkansas Power & Light Co. 83/03/16 2pp. 17632:042 24X
Fiche: 50-313, 83/03/16, 8303210277.

8303210329 Forwards outline of schedule for spent fuel storage expansion. Response by 830325 requested so util can adjust planning & work plans.
MARSHALL, J. R. Arkansas Power & Light Co. 83/03/16 STOLZ, J. F.
Operating Reactors Branch 4 CLARK, R. A. Operating Reactors Branch 3. 4pp. 17632:117 24X Fiche: 50-313, 83/03/16, 8303210329.

8303250133 Forwards supplemental response to 830309 request for addl info re spent fuel storage expansion.
MARSHALL, J. R. Arkansas Power & Light Co. 83/03/21 STOLZ, J. F.
Operating Reactors Branch 4 CLARK, R. A. Operating Reactors Branch 3. 3pp. 17693:012 24X Fiche: 50-313, 83/03/21, 8303250133.

8303300013 Forwards safety evaluation re Tech Spec requirements for steam generator tube insp & tube plugging. Insp & corrective actions acceptable.
STOLZ, J. F. Operating Reactors Branch 4 83/03/21 GRIFFIN, J. M.
Arkansas Power & Light Co. 5pp. 17751:239 24X
Fiche: 50-313, 83/03/21, 8303300013.

--8303300020 Safety evaluation re Tech Spec requirements for steam generator tube insp & tube plugging. Util insp & corrective actions acceptable.
* Office of Nuclear Reactor Regulation, Director 83/03/21 5pp. 17751:241 24X Fiche: 50-313, 83/03/21, 8303300013.

8303300776 Requests supplemental response to NRC 830126 environ qualification safety evaluation to justify continued operation of all safety-related electrical equipment. Response requested within 30 days. Guidelines encl.
STOLZ, J. F. Operating Reactors Branch 4 83/03/22 GRIFFIN, J. M.
Arkansas Power & Light Co. 5pp. 17765:254 24X
Fiche: 50-313, 83/03/22, 8303300776.

8303310687 Forwards request for addl info needed to complete review of open issues re emergency feedwater evaluation, NUREG-0737, Item II.E.1.1.
STOLZ, J. F. Operating Reactors Branch 4 83/03/22 GRIFFIN, J. M.
Arkansas Power & Light Co. 4pp. 17780:288 24X
Fiche: 50-313, 83/03/22, 8303310687.

8303290419 Forwards response to NRC 830318 request for addl info re util 821105 proposed expansion of spent fuel storage in fuel pool. No changes to NPDES will be submitted since no addl nonradiological wastes will be discharged from reracking.
MARSHALL, J. R. Arkansas Power & Light Co. 83/03/24 STOLZ, J. F.
Operating Reactors Branch 4 CLARK, R. A. Operating Reactors Branch 3. 2pp. 17726:282 24X Fiche: 50-313, 83/03/24, 8303290419.

8303310551 Notification of 830407 meeting w/B&W Owners Group in Bethesda, MD to review progress, schedules & typical event analyses re study of pressurized thermal shock.
VISSING, G. S. Operating Reactors Branch 4 83/03/25 STOLZ, J. F.
Operating Reactors Branch 4 2pp. 17780:360 24X
Fiche: 50-000, 83/03/25, 8303310551.

## G. Inspection reports, IE Bulletins & correspondence

8303180430 Forwards IE Insp Repts 50-313/82-38 & 50-368/82-28 on 821004-08. No noncompliance noted.
SEIDLE, W. C. Region 4, Office of Director 83/01/05 CAVANAUGH, W.
Arkansas Power & Light Co. 2pp. 17621:165 24X
Fiche: 50-313, 83/01/05, 8303180430.

--8303180433 IE Insp Repts 50-313/82-38 & 50-368/82-28 on 821004-08. No noncompliance noted. Major areas inspected: procedures, advanced planning & preparations, training, exposure control, posting & control & audits.
BAER, R., HOLLEY, W., MURRAY, B. Region 4, Office of Director 82/12/17 21pp. 17621:167 24X Fiche: 50-313, 83/01/05, 8303180430.

8303010237 Forwards IE Insp Rpts 50-313/82-24 & 50-368/82-21 on 820728-29. Violation re prompt public notification corrected. No further info required.
SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 83/02/11 CAVANAUGH, W. Arkansas Power & Light Co. 2pp. 17335:179 24X Fiche: 50-313, 83/02/11, 8303010237.

--8303010247 IE Insp Rpts 50-313/82-24 & 50-368/82-21 on 820728-29. Noncompliance noted: lack of capability for providing prompt public notification in portion of plume exposure pathway.
HACKNEY, C. A., MONTGOMERY, J. L., WASHINGTON, K. E. Division of Resident, Reactor Project & Engineering Programs 83/02/09 7pp. 17335:181 24X Fiche: 50-313, 83/02/11, 8303010237.

8303210547 Forwards IE Insp Rpts 50-313/83-01 & 50-368/83-01 on 830101-31 & notice of violation.
SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 83/02/17 CAVANAUGH, W. Arkansas Power & Light Co. 2pp. 17632:252 24X Fiche: 50-313, 83/02/17, 8303210547.

--8303210554 Notice of violation from insp on 830101-31.
* Region 4, Office of Director 83/02/17 1p. 17632:254 24X
Fiche: 50-313, 83/02/17, 8303210547.

--8303210562 IE Insp Rpts 50-313/83-01 & 50-368/83-01 on 830101-31. Noncompliance noted: specific gravity readings not taken in accordance w/procedures.
CALLAN, L. J., CUMMINS, J. E., JOHNSON, W. D. Region 4, Office of Director 83/02/16 10pp. 17632:255 24X Fiche: 50-313, 83/02/17, 8303210547.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 111pp. 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303010682 Ack receipt of 830112 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpts 50-313/82-15 & 50-368/82-12.
SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 83/02/25 CAVANAUGH, W. Arkansas Power & Light Co. 1p. 17341:160 24X Fiche: 50-313, 83/02/25, 8303010682.

--8303010685 Responds to NRC 821112 ltr re violations noted in IE Insp Rpts 50-313/82-15 & 50-368/82-12. Closed end rigid metal conduit penetrating frame will not significantly affect fire resistant ability of door assemblies.
MARSHALL, J. R. Arkansas Power & Light Co. 83/01/12 SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs. 2pp. 17341:161 24X Fiche: 50-313, 83/02/25, 8303010682.

8303040611 Submits resolution to snubber surveillance issue Program would test mechanical & hydraulic snubbers which are nuclear safety-related in accordance w/ANSI/ASME OM-4 1982 Past insp will be utilized as baseline for insp progrm.
MARSHALL, J R Arkansas Power & Light Co 83/02/28 STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 3pp 17768:022 24X Fiche 50-313, 83/02/28, 8303040611

8303040557 EN-83-012 on 830308, notice of violation & proposed imposition of civil penalty in amount of $20,000 to be issued. Action based on failure to restore reactor bldg pressure transmitter to svc prior to operation.
KLINGLER, G , JR,ELRAD, J Director's Office, Office of Inspection and Enforcement 83/03/03 1p 17373:347 24X Fiche 50-313, 83/03/03, 8303040557

8303080272 Responds to IE Bulletin 82-04 "Deficiencies in Primary Containment Electrical Penetration Assemblies." No Bunker Ramo assemblies installed at Unit 1. No defects or failures identified at Unit 2.
MARSHALL, J R. Arkansas Power & Light Co. 83/03/03. COLLINS, J. T. Region 4, Office of Director. 3pp. 17454:310. 24X
Fiche: 50-313, 83/03/03, 8303080272.

8303110332 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Westinghouse DB-50 breakers not used. Unit 1 uses GE AK-2A-25 breakers & Unit 2 uses GE AK-2-25 breakers.
REUTER, D A Arkansas Power & Light Co 83/03/04 COLLINS, J T Region 4, Office of Director 2pp 17512:333 24X
Fiche: 50-313, 83/03/04, 8303110332

8303140581 Discusses 821216 discovery of two inoperable reactor bldg pressure transmitters due to installation of plugs from input ports to transmitters & forwards notice of violation & proposed imposition of civil penalty.
COLLINS, J T Region 4, Office of Director 83/03/08 GRIFFIN, J M Arkansas Power & Light Co 2pp 17534:010 24X
Fiche: 50-313, 83/03/08, 8303140581

--8303140593 Notice of violation & proposed imposition of civil penalty in amount of $20,000. Noncompliance noted: failure to ensure temporary procedure change & test activities adequate to ensure compliance w/Tech Specs re plugs in input ports.
COLLINS, J T Region 4, Office of Director 83/03/08 4pp 17534:012 24X Fiche: 50-313, 83/03/08, 8303140581

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche 50-000, 83/03/11, 8212060380.

8303250036 Requests expeditious review of Tech Specs for corrective actions taken as result of inservice insp of once-through steam generator tubes. Unit scheduled to restart by 830322.
MARSHALL, J R Arkansas Power & Light Co 83/03/16 STOLZ, J F Operating Reactors Branch 4 2pp 17692:062 24X
Fiche: 50-313, 83/03/16, 8303250036.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc 117pp 24X Fiche 50-000, 83/03/18, 8212060383.

8303240469 Ack receipt of 830217 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/82-33 & 50-368/82-33.
SEIDLE, W C Region 4, Office of Director 83/03/18 GRIFFIN, J M Arkansas Power & Light Co 1p 17678:036 24X
Fiche: 50-313, 83/03/18, 8303240469.

--8303240478 Responds to NRC 830118 ltr re violations noted in IE Insp Repts 50-313/82-33 & 50-368/82-33. Corrective actions: nonconformance rept procedure revised, fire watch established & independent walkdown of fire barriers conducted.
MARSHALL, J R Arkansas Power & Light Co 83/02/17 SEIDLE, W C Region 4, Office of Director 4pp 17678:037 24X
Fiche: 50-313, 83/03/18, 8303240469.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc 121pp 17774:352 24X Fiche 50-000, 83/03/21, 8212060387.

8303280017 Responds to Item 4 of IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Surveillance tests of undervoltage trip function performed. Devices functioned properly.
REUTER, D A Arkansas Power & Light Co 83/03/21 COLLINS, J T Region 4, Office of Director 7pp 17707:291 24X
Fiche: 50-313, 83/03/21, 8303280017.

8303300013 Forwards safety evaluation re Tech Spec requirements for steam generator tube insp & tube plugging. Insp & corrective actions acceptable.
STOLZ, J F Operating Reactors Branch 4 83/03/21 GRIFFIN, J M Arkansas Power & Light Co 5pp 17751:239 24X
Fiche: 50-313, 83/03/21, 8303300013.

--8303300020 Safety evaluation re Tech Spec requirements for steam generator tube insp & tube plugging. Util insp & corrective actions acceptable.
* Office of Nuclear Reactor Regulation, Director 83/03/21 5pp 17751:241 24X Fiche: 50-313, 83/03/21, 8303300013.

R. Periodic operating reports & related correspondence

8303080055 Forwards monthly operating rept for Dec 1982.
MARSHALL, J R Arkansas Power & Light Co 83/01/14 HALLER, N H Office of Resource Management, Director 1p 17458:206 24X
Fiche: 50-313, 83/01/14, 8303080055.

--8303080059 Monthly operating rept for Dec 1982.
GERTSCH, A J Arkansas Power & Light Co 83/01/14 6pp 17458:207 24X Fiche: 50-313, 83/01/14, 8303080055.

8303290063 Submits first monthly progress rept on regulatory response & commitment control program. Interim guidelines implemented. Next status rept scheduled for 830314.
MARSHALL, J R Arkansas Power & Light Co 83/02/14 COLLINS, J T Region 4, Office of Director 3pp 17722:337 24X
Fiche: 50-313, 83/02/14, 8303290063.

8303150381 Forwards monthly operating rept for Jan 1983.
MARSHALL, J R Arkansas Power & Light Co 83/02/15 HALLER, N H Office of Resource Management, Director 1p 17562:020 24X
Fiche: 50-313, 83/02/15, 8303150381.

--8303150384 Monthly operating rept for Jan 1983.
GERTSCH, A J Arkansas Power & Light Co 83/02/15 7pp 17562:021 24X Fiche: 50-313, 83/02/15, 8303150381.

8303080346 Forwards "Screen Monitoring for Jan 1983."
MARSHALL, J R Arkansas Power & Light Co 83/02/28 STOLZ, J F Operating Reactors Branch 4 1p 17453:327 24X
Fiche: 50-313, 83/02/28, 8303080346.

--8303080351 "Screen Monitoring for Jan 1983."
* Arkansas Power & Light Co 83/02/11 7pp 17453:328 24X
Fiche: 50-313, 83/02/28, 8303080346.

S. Reportable occurrences, LERs & related correspondence

8303240374 Forwards LER 83-004/03L-0.
MARSHALL, J R Arkansas Power & Light Co 83/03/14 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 1p 17679:073 24X Fiche: 50-313, 83/03/14, 8303240374.

--8303240382 LER 83-004/03L-0 on 830214, RCS pressure transmitters PT-1040 & PT-1020 found out of tolerance. Caused by transmitter drift. Transmitter recalibr & left within allowable tolerance.
ROGERS, P Arkansas Power & Light Co 83/03/14 Region 4, Office of Director 1p 17679:074 24X Fiche: 50-313, 83/03/14, 8303240374.

8303280122 PNO-IV-83-012 on 830323, undervoltage trip mechanism of ac reactor trip breaker A failed. Vendor will assist in investigation. Unit in cold shutdown, preparing for heatup following refueling outage.
JOHNSON, W D , CALLAN, L J Region 4, Office of Director 83/03/24 1p 17706:321 24X Fiche: 50-313, 83/03/24, 8303280122.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp 24X Fiche: 50-000, 83/02/24, 8302250505.

8303070028 Forwards estimated schedule for operator licensing exams through 1985 in response to NRC 830111 Generic Ltr 83-01. No instructor certification exams planned during specified time frame.
MARSHALL, J R Arkansas Power & Light Co 83/02/28 EISENHUT, D G Division of Licensing 2pp 17434:337 24X Fiche: 50-313, 83/02/28, 8303070028.

DOCKET 50-315 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8303170108 Forwards updated info in tabular format on status of emergency operations facility (EOF), verbally transmitted on 821124 & 1203, per NRR project manager request. EOF located 11 miles northeast of plants.
HUNTER, R. S. Indiana & Michigan Electric Co. 82/12/06 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 17609:144. 24X Fiche: 50-315, 82/12/06, 8303170108.

8303020432 Forwards Amends 70 & 52 to Licenses DPR-58 & DPR-74, respectively & notice of issuance & availability. Amends modify licenses to include requirement to maintain guard training & qualification plan.
VARGA, S. A. Operating Reactors Branch 1. 83/02/22 DOLAN, J. Indiana & Michigan Electric Co. 3pp. 17357:241. 24X Fiche: 50-315, 83/02/22, 8303020432.

--8303020441 Amends 70 & 52 to Licenses DPR-58 & DPR-74, respectively, modifying licenses to include requirement to maintain guard training & qualification plan.
VARGA, S. A. Operating Reactors Branch 1. 83/02/22 4pp. 17357:244. 24X Fiche: 50-315, 83/02/22, 8303020432.

--8303020448 Notice of issuance & availability of Amends 70 & 52 to Licenses DPR-58 & DPR-74, respectively.
VARGA, S. A. Operating Reactors Branch 1. 83/02/22 2pp. 17357:248. 24X Fiche: 50-315, 83/02/22, 8303020432.

8303180024 Requests confirmation on info tabulated from response re emergency operating facilities.
VARGA, S. A. Operating Reactors Branch 1. 83/03/04 DOLAN, J. Indiana & Michigan Electric Co. 3pp. 17625:272. 24X Fiche: 50-315, 83/03/04, 8303180024.

8303290597 Confirms 830310 telcon re fire protection review. Lack of fire dampers betwen adjacent areas containing redundant trains of safe shutdown equipment requires evaluation.
VARGA, S. A. Operating Reactors Branch 1. 83/03/11 DOLAN, J. Indiana & Michigan Electric Co. 2p. 17743:359. 24X Fiche: 50-315, 83/03/11, 8303290597.

8303210215 Ack receipt of 830218 ltr informing of steps taken to correct problem re prompt public notification to transient population of Warren Dunes State Park.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 83/03/16 DOLAN, J. E. Indiana & Michigan Electric Co. 1p. 17632:001. 24X Fiche: 50-315, 83/03/16, 8303210215.

8303250051 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/21 Document Management Branch. 1p. 17710:102. 24X Fiche: 50-315, 83/03/21, 8303250051.

--8303250053 Forwards public version of Rev 0 to Emergency Plan Implementing Procedure PMP 2081 EPP 027, "Unit Vent Emergency Release Level Determination." Receipt form encl.
FRYER, J. Indiana & Michigan Electric Co. 83/03/09 NRC - No Detailed Affiliation Given. 1p. 17710:103. 24X Fiche: 50-315, 83/03/21, 8303250051.

--8303250056 Public version of Rev 0 to Emergency Plan Implementing Procedure PMP 2081 EPP 027, "Unit Vent Emergency Release Level Determination."
MURPHY, C. E. Indiana & Michigan Electric Co. 83/03/01 12pp. 17710:104. 24X Fiche: 50-315, 83/03/21, 8303250051.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director. 83/03/22 Commonwealth Edison Co. 2pp. 17690:316. 24X Fiche: 50-000, 83/03/22, 8303240440.

8303300788 Responds to 830214 ltr w/Rev 7 to modified amended security plan. Changes consistent w/10CFR50.54(p) provisions. Encl to ltr withheld (ref 10CFR73.21).
VARGA, S. A. Operating Reactors Branch 1. 83/03/24 DOLAN, J. Indiana & Michigan Electric Co. 1p. 17770:255. 24X Fiche: 50-313, 83/03/24, 8303300788.

J. Insurance & indemnity information

8303110226 Forwards Endorsement 56 to NELIA Policy NF-206.
NADEL, M. Marsh & McLennan, Inc. 83/03/07 SALTZMAN, J. Assistant Director for State & Licensee Relations. 2pp. 17518:355. 24X Fiche: 50-315, 83/03/07, 8303110226.

P. Operating license stage documents & correspondence

8303010128 Advises that requirements of TMI Action Items I.A.2.1.4 & II.B.4.1 re upgrading of reactor operator training & training for mitigating core damage, respectively, satisfied.
VARGA, S. A. Operating Reactors Branch 1. 83/02/11 DOLAN, J. Indiana & Michigan Electric Co. 5pp. 17354:346. 24X Fiche: 50-315, 83/02/11, 8303010128.

--8208260154 "Improvements in Training & Requalification Programs as Required by TMI Action Items I.A.2.1 & II.B.4," final technical evaluation rept.
* Science Applications, Inc. NRC-03-82-096. SAI-186-029-09. 82/08/17. NRC - No Detailed Affiliation Given. 15pp. 17355:001. 24X Fiche: 50-315, 83/02/11, 8303010128.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303020432 Forwards Amends 70 & 52 to Licenses DPR-58 & DPR-74, respectively & notice of issuance & availability. Amends modify licenses to include requirement to maintain guard training & qualification plan.
VARGA, S. A. Operating Reactors Branch 1. 83/02/22 DOLAN, J. Indiana & Michigan Electric Co. 3pp. 17357:241. 24X Fiche: 50-315, 83/02/22, 8303020432.

--8303020441 Amends 70 & 52 to Licenses DPR-58 & DPR-74, respectively, modifying licenses to include requirement to maintain guard training & qualification plan.
VARGA, S. A. Operating Reactors Branch 1. 83/02/22 4pp. 17357:244. 24X Fiche: 50-315, 83/02/22, 8303020432.

--8303020448 Notice of issuance & availability of Amends 70 & 52 to Licenses DPR-58 & DPR-74, respectively.
VARGA, S. A. Operating Reactors Branch 1. 83/02/22 2pp. 17357:248. 24X Fiche: 50-315, 83/02/22, 8303020432.

8303010265 Informs that Westinghouse analysis of lifting arrangement for reactor vessel head & upper internals will not be completed by 830315 due to backlog of load analyses at Westinghouse. Revised date for submittal is 830601.
ALEXICH, M. P. American Electric Power Service Corp. 83/02/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17335:106. 24X Fiche: 50-315, 83/02/25, 8303010265.

8303010315 Requests extension until 830701 for submittal of plant-specific evaluation rept on adequacy of safety & relief valve discharge piping & plant-specific qualification of safety & relief valves (NUREG-0737, Item II.D.1).
ALEXICH, M. P. American Electric Power Service Corp. 83/02/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17333:322. 24X Fiche: 50-315, 83/02/25, 8303010315.

8303010323 Requests that payment for NUREG-0737, Item II.F.1.6 Tech Spec be made part of single fee to be levied for issuance of Tech Spec changes required by NUREG-0737. Util should not be penalized for early implementation of safety equipment.
ALEXICH, M. P. American Electric Power Service Corp. 83/02/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17333:320. 24X Fiche: 50-315, 83/02/25, 8303010323.

8303020013 Application to amend Licenses DPR-58 & DPR-74 by revising App A to Tech Specs re surveillance interval for inoperable equipment.
HUNTER, R. S. Indiana & Michigan Electric Co. 83/02/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17354:267. 24X Fiche: 50-315, 83/02/25, 8303020013.

--8303020020 Proposed changes to App A Tech Specs re surveillance interval for inoperable equipment.
* Indiana & Michigan Electric Co. 83/02/25 3pp. 17354:270. 24X Fiche: 50-315, 83/02/25, 8303020013.

8303080141 Application for amend to Licenses DPR-58 & DPR-74, changing Tech Specs to permit storage of Westinghouse 15x15 optimized fuel assembly design fuel in new fuel storage area & spent fuel pool.
HUNTER, R. S. Indiana & Michigan Electric Co. 83/02/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17457:264. 24X Fiche: 50-315, 83/02/28, 8303080141.

--8303080145 "Summary of New & Spent Fuel Storage Array Criticality Safety Analyses."
* Indiana & Michigan Electric Co. 83/02/28 21pp. 17457:266. 24X Fiche: 50-315, 83/02/28, 8303080141.

--8303080150 Proposed Tech Specs permitting storage of Westinghouse 15x15 optimized fuel assembly design fuel in new fuel storage area & spent fuel pool.
* Indiana & Michigan Electric Co. 83/02/28. 4pp. 17457:287. 24X Fiche: 50-315, 83/02/28, 8303080141.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303100159 Notification of 830315 meeting w/util & Exxon in Bethesda, MD to discuss fuel reload methodology & info/schedule for submittals to satisfy Cycle 4 & 5 requirements.
WIGGINTON, D. Operating Reactors Branch 1. 83/03/03. VARGA, S. A. Operating Reactors Branch 1. 2pp. 17496:014. 24X Fiche: 50-315, 83/03/03, 8303100159.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J. G. Region 3, Office of Director. 83/03/03. Commonwealth Edison Co. 2pp. 17492:014. 24X Fiche: 50-000, 83/03/03, 8303100364.

8303080111 Forwards Rev 2 to Procedure 12 PMP 3150 PCP 001, "Radwaste Process Manual," per requirement of radiological effluent Tech Spec (RETS) Section 6.14. NRC approval requested prior to RETS implementation date of 830415.
HUNTER, R. S. Indiana & Michigan Electric Co. 83/03/04. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17458:276. 24X Fiche: 50-315, 83/03/04, 8303080111.

--8303080119 Rev 2 to Procedure 12 PMP 3150 PCP 001, "Radwaste Process Control Manual."
* Indiana & Michigan Electric Co. 83/02/15. 61pp. 17458:277. 24X Fiche: 50-315, 83/03/04, 8303080111.

8303080348 Provides justification for continued operation, in response to 821230 SER on environ qualification of safety-related electrical equipment.
HUNTER, R. S. Indiana & Michigan Electric Co. 83/03/04. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 17453:324. 24X Fiche: 50-315, 83/03/04, 8303080348.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303150673 Requests $4,400 fee still due for 820929 application for changes to Tech Specs re radiological water quality.
MILLER, W. O. License Fee Management Branch. 83/03/08. DOLAN, J. Indiana & Michigan Electric Co. 2pp. 17586:254. 24X Fiche: 50-315, 83/03/08, 8303150673.

8303280050 Requests extension to 830615 to provide addl info requested in Generic Ltr 82-28 re inadequate core cooling instrumentation sys. Summary of previously submitted info re Westinghouse differential pressure monitoring sys encl.
HERING, R. F. Indiana & Michigan Electric Co. 83/03/11. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 5pp. 17707:298. 24X Fiche: 50-315, 83/03/11, 8303280050.

8303290800 Forwards order confirming util commitment to implement post-TMI-related items set forth in NUREG-0737 & Generic Ltrs 82-05 & 82-10.
VARGA, S. A. Operating Reactors Branch 1. 83/03/14. DOLAN, J. Indiana & Michigan Electric Co. 2pp. 17748:098. 24X Fiche: 50-315, 83/03/14, 8303290800.

--8303290806 Order confirming util commitment to implement post-TMI-related items set forth in NUREG-0737 & Generic Ltrs 82-05 & 82-10. Hearing may be requested within 20 days of order publication.
PURPLE, R. A. Division of Licensing. 83/03/14. Indiana & Michigan Electric Co. 9pp. 17748:100. 24X Fiche: 50-315, 83/03/14, 8303290800.

8303250088 Requests remittance of Class I & III fees for application to change Tech Specs to permit storage of Westinghouse 15x15 optimized fuel in spent fuel pool.
DIGGS, R. M. License Fee Management Branch. 83/03/18. DOLAN, J. Indiana & Michigan Electric Co. 1p. 17700:356. 24X Fiche: 50-315, 83/03/18, 8303250088.

## G. Inspection reports, IE Bulletins & correspondence

8303030619 Forwards IE Mgt Meeting Repts 50-315/82-25 & 50-316/82-25 on 820804, 0907, 1102 & 1229. No noncompliance noted.
KEPPLER, J. G. Region 3, Office of Director. 83/02/14. DOLAN, J. E. Indiana & Michigan Power Co. DOLAN, J. E. American Electric Power Service Corp. 2pp. 17409:298. 24X Fiche: 50-315, 83/02/14, 8303030619.

--8303030634 IE Mgt Meeting Repts 50-315/82-25 & 50-316/82-25 on 820804, 0907, 1102 & 1229. No noncompliance noted. Major areas discussed: responses to insp repts, licensee mgt reviews & regulatory procedures.
STREETER, J. F. Division of Project & Resident Programs. 83/02/07. 5pp. 17409:300. 24X Fiche: 50-315, 83/02/14, 8303030619.

8303080248 Forwards IE Insp Repts 50-315/82-22 & 50-316/82-22 on 821101-1231 & notice of violation.
STREETER, J. F. Division of Project & Resident Programs. 83/02/18. DOLAN, J. F. American Electric Power Service Corp. DOLAN, J. F. Indiana & Michigan Electric Co. 2pp. 17454:275. 24X Fiche: 50-315, 83/02/18, 8303080248.

--8303080258 Notice of violation from insp on 821101-1231. STREETER, J. F. Division of Project & Resident Programs. 83/02/18. 2pp. 17454:277. 24X Fiche: 50-315, 83/02/18, 8303080248.

--8303080270 IE Insp Repts 50-315/82-22 & 50-316/82-22 on 821101-1231. Noncompliance noted: failure to submit personnel radiation exposure rept to NRC & individuals & failure to implement QC by neglecting testing.
BOYD, D. C., SWANSON, E. R., DUBRY, N. E. Division of Project & Resident Programs. 83/02/14. 14pp. 17454:279. 24X Fiche: 50-315, 83/02/18, 8303080248.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303030463 Clarifies NRC position re procedures for admitting NRC personnel to facilities. Site orientation re issuance of badges, escort duties & emergency evacuation for personnel listed in Encls 1 & 2 requested.
KEPPLER, J. G. Region 3, Office of Director. 83/02/28. DOLAN, J. E. American Electric Power Service Corp. DOLAN, J. E. Indiana & Michigan Electric Co. 6pp. 17409:067. 24X Fiche: 50-315, 83/02/28, 8303030463.

8303140452 Responds to IE Bulletin 82-04, "Deficiency in Primary Containment Electrical Penetration Assemblies." No Bunker-Ramo electrical penetrations installed at facilities.
HUNTER, R. S. Indiana & Michigan Electric Co. 83/03/03. KEPPLER, J. G. Region 3, Office of Director. 2pp. 17542:238. 24X Fiche: 50-315, 83/03/03, 8303140452.

8303210623 Forwards IE Insp Repts 50-315/83-03 & 50-316/83-03 on 830214-15 & notice of violation.
PAPERIELLO, C. J. Region 3, Office of Director. 83/03/03. DOLAN, J. E. American Electric Power Service Corp. DOLAN, J. E. Indiana & Michigan Electric Co. 2pp. 17636:224. 24X Fiche: 50-315, 83/03/03, 8303210623.

--8303210628 Notice of violation from insp on 830214-15. PAPERIELLO, C. J. Region 3, Office of Director. 83/03/03. 1p. 17636:226. 24X Fiche: 50-315, 83/03/03, 8303210623.

--8303210637 IE Insp Repts 50-315/83-03 & 50-316/83-03 on 830214-15. Noncompliance noted: failure to follow plant procedure during collection of vol control tank gaseous sample & to review & approve changes to plant procedure.
LOVENDALE, P. C., PECK, C. C., GREGER, L. R. Region 3, Office of Director. 83/03/02. 6pp. 17636:227. 24X Fiche: 50-315, 83/03/03, 8303210623.

8303150218 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Surveillance test results satisfactory. Notification to all licensed operators is in progress.
HUNTER, R. S. Indiana & Michigan Electric Co. 83/03/07. KEPPLER, J. G. Region 3, Office of Director. 4pp. 17556:084. 24X Fiche: 50-315, 83/03/07, 8303150218.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/18 Consolidated Edison Co. of New
York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8303220279 Forwards safety evaluation & referenced portion of IE Insp
Repts 50-315/82-24 & 50-316/82-24, documenting completed
review of NUREG-0737, Item II.B.2.2, "Plant Shielding
Access to Vital Areas."
NORELIUS, C. E. Division of Project & Resident Programs 83/03/18
EISENHUT, D. G. Division of Licensing 2pp 17656:141 24X
Fiche: 50-315, 83/03/18, 8303220279.

8303240178 Ack receipt of 830121 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-315/82-19 &
50-316/82-19. Shift briefings will be conducted when major
testing activities completed.
NORELIUS, C. E. Division of Project & Resident Programs 83/03/18
DOLAN, J. E. American Electric Power Service Corp DOLAN, J. E.
Indiana & Michigan Electric Co. 2pp 17681:001 24X
Fiche: 50-315, 83/03/18, 8303240178.

--8303240190 Responds to NRC 821215 ltr re violations noted in IE Insp
Repts 50-315/82-19 & 50-316/82-19. Corrective actions:
controlled document containing list of all bistables to be
tripped will be written.
HERING, R. F. Indiana & Michigan Electric Co. 83/01/21
KEPPLER, J. G. Region 3, Office of Director 6pp 17681:003 24X
Fiche: 50-315, 83/03/18, 8303240178.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-
Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/21 Consolidated Edison Co. of New
York, Inc. 121pp. 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

R. Periodic operating reports & related correspondence

8303080423 Forwards monthly operating rept for Dec 1982.
SMITH, W. G. Indiana & Michigan Electric Co. 83/01/13 Office of
Resource Management, Director 1p 17453:001 24X
Fiche: 50-315, 83/01/13, 8303080423.

--8303080429 Monthly operating rept for Dec 1982.
MIGHT, A., SVENSSON, B. A., MURPHY, C. E. Indiana & Michigan Electric
Co. 83/01/13 9pp 17453:002 24X Fiche: 50-315, 83/01/13,
8303080423.

8303150510 Forwards monthly operating rept for Jan 1983.
SMITH, W. G. Indiana & Michigan Electric Co. 83/02/14 Office of
Resource Management, Director 1p 17568:163 24X
Fiche: 50-315, 83/02/14, 8303150510.

--8303150531 Monthly operating rept for Jan 1983.
GILLETT, W. T. Indiana & Michigan Electric Co. 83/02/14 7pp
17568:164 24X Fiche: 50-315, 83/02/14, 8303150510.

8303140399 Forwards "Semiannual Radioactive Effluent Release Rept,
Jul-Dec 1982."
HUNTER, R. S. Indiana & Michigan Electric Co. 83/03/01 KEPPLER, J. G.
Region 3, Office of Director 1p 17541:238 24X
Fiche: 50-315, 83/03/01, 8303140399.

--8303140401 "Semiannual Radioactive Effluent Release Rept, Jul-Dec 1982."
Indiana & Michigan Electric Co. 83/03/01 177pp 17541:239
24X Fiche: 50-315, 83/03/01, 8303140399.

S. Reportable occurrences, LERs & related correspondence

8303080079 Forwards LER 83-011/03L-0.
SMITH, W. G. Indiana & Michigan Electric Co. 83/02/24 KEPPLER, J. G.
Region 3, Office of Director 1p 17457:354 24X
Fiche: 50-315, 83/02/24, 8303080079.

--8303080087 LER 83-011/03L-0 on 830125, while repairing transfer pump
2 BA pump 1 BA removed from svc. Caused by excessive seal
leakage due to bearing failure.
CARTEAUX, P. Indiana & Michigan Electric Co. 83/02/24 Region
3, Office of Director 1p 17457:355 24X Fiche: 50-315, 83/02/24,
8303080079.

8303080105 Forwards LER 83-002/03L-0.
SMITH, W. G. Indiana & Michigan Electric Co. 83/02/24 KEPPLER, J. G.
Region 3, Office of Director 1p 17458:172 24X
Fiche: 50-315, 83/02/24, 8303080105.

--8303080113 LER 83-002/03L-0 on 830125, ice condenser intermediate deck
door weighing procedure revealed 70 doors exceeded max
initial opening force specs. Caused by misalignment &/or
dented hinges. Hinges realigned & lubricated.
CARTEAUX, P. Indiana & Michigan Electric Co. 83/02/24 Region
3, Office of Director 2pp 17458:173 24X Fiche: 50-315,
83/02/24, 8303080105.

8303080375 Forwards LERs 83-012/03L-0, 83-013/03L-0 & 83-014/03L-0.
SMITH, W. G. Indiana & Michigan Electric Co. 83/02/25 KEPPLER, J. G.
Region 3, Office of Director 1p 17454:048 24X
Fiche: 50-315, 83/02/25, 8303080375.

--8303080384 LER 83-012/03L-0 on 830203, fire door 460 blocked open.
Caused by metal plate between door stop & door. Metal piece
removed.
CARTEAUX, P. Indiana & Michigan Electric Co. 83/02/25 Region
3, Office of Director 1p 17454:049 24X Fiche: 50-315, 83/02/25,
8303080375.

--8303080398 LER 83-013/03L-0 on 830201, when maint supervisor clearance
placed on MRV-212 steam generator 1 stop valve dump valve to
repair seat leakage, valve declared inoperable. Valve cage &
plug replaced.
ROBINSON, D. Indiana & Michigan Electric Co. 83/02/25 Region
3, Office of Director 1p 17454:050 24X Fiche: 50-315, 83/02/25,
8303080375.

--8303080410 LER 83-014/03L-0 on 830202 & 07, duplex strainer circuit
breaker on east emergency svc water 1 experienced problem.
Caused by change in pressure across strainer slide gates
when valves WRV-761 & 771 did not close fully.
ROBINSON, D. Indiana & Michigan Electric Co. 83/02/25 Region
3, Office of Director 1p 17454:051 24X Fiche: 50-315, 83/02/25,
8303080375.

8303080331 Forwards updated LER 82-077/01X-2.
SMITH, W. G. Indiana & Michigan Electric Co. 83/02/28 KEPPLER, J. G.
Region 3, Office of Director 1p 17453:320 24X
Fiche: 50-315, 83/02/28, 8303080331.

--8303080344 Updated LER 82-077/01X-2 on 820910, while in Mode 4,
discovered that required testing after design change on
control room ventilation sys not performed. Caused by
personnel error. Administrative controls strengthened.
BEILMAN, T. P. Indiana & Michigan Electric Co. 83/02/28 Region
3, Office of Director 3pp 17453:321 24X Fiche: 50-315,
83/02/28, 8303080331.

8303140373 Forwards LER 83-015/03L-0.
SMITH, W. G. Indiana & Michigan Electric Co. 83/03/02 KEPPLER, J. G.
Region 3, Office of Director 1p 17542:195 24X
Fiche: 50-315, 83/03/02, 8303140373.

--8303140377 LER 83-015/03L-0 on 830203, during normal operation, control
room access fire door 412 failed to operate properly. Cause
not stated. Door closer mechanism replaced.
CARTEAUX, P. Indiana & Michigan Electric Co. 83/03/02 Region
3, Office of Director 1p 17542:196 24X Fiche: 50-315, 83/03/02,
8303140373.

8303140603 Forwards LER 82-111/03L-0.
SMITH, W. G. Indiana & Michigan Electric Co. 83/03/02 KEPPLER, J. G.
Region 3, Office of Director 1p 17534:028 24X
Fiche: 50-315, 83/03/02, 8303140603.

--8303140610 LER 82-111/03L-0 on 821109, auxiliary cable vault experienced
inadvertent carbon dioxide discharge. Cause not stated.
Isolating valve closed & main isolation valve reopened.
Operating memo issued describing preferred methodology.
KRAUSE, D. F. Indiana & Michigan Electric Co. 83/03/02 Region
3, Office of Director 1p 17534:029 24X Fiche: 50-315, 83/03/02,
8303140603.

8303220102 RO on 830311, fire door in boron injection tank room found
not to have label to substantiate UL certification. Cause
not stated. Continuous fire watch posted.
SMITH, W. G. Indiana & Michigan Electric Co. 83/03/14 KEPPLER, J. G.
Region 3, Office of Director 1p 17650:067 24X
Fiche: 50-315, 83/03/14, 8303220102.

8303290386 RO on 830219, reservoir containing lubricating oil for
turbine 2 leaked into Lake MI. Caused by tube failure. Tube
plugged.
SMITH, W. G. Indiana & Michigan Electric Co. 83/03/17 KEPPLER, J. G.
Region 3, Office of Director 3pp 17716:268 24X
Fiche: 50-315, 83/03/17, 8303290386.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp 24X Fiche 50-000, 83/02/24, 8302250505.

8303040476 Requests util policy re facial hair & effect on access to plant facilities during operator licensing exams Recent denial of access to NRC examiners due to facial hair could potentially interfere w/insp program.
HIND, J. A. Division of Project & Resident Programs 83/02/28 DOLAN, J. E. American Electric Power Service Corp. DOLAN, J. E. Indiana & Michigan Electric Co. 1p. 17374:013 24X
Fiche: 50-315, 83/02/28, 8303040476.

DOCKET 50-316 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8303170108 Forwards updated info in tabular format on status of emergency operations facility (EOF), verbally transmitted on 821124 & 1203, per NRR project manager request EOF located 11 miles northeast of plants.
HUNTER, R. S. Indiana & Michigan Electric Co. 82/12/06 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp 17609:144 24X Fiche: 50-315, 82/12/06, 8303170108.

8303020432 Forwards Amends 70 & 52 to Licenses DPR-58 & DPR-74, respectively & notice of issuance & availability. Amends modify licenses to include requirement to maintain guard training & qualification plan.
VARGA, S. A. Operating Reactors Branch 1 83/02/22 DOLAN, J. Indiana & Michigan Electric Co. 3pp 17357:241 24X
Fiche: 50-315, 83/02/22, 8303020432.

--8303020441 Amends 70 & 52 to Licenses DPR-58 & DPR-74, respectively, modifying licenses to include requirement to maintain guard training & qualification plan.
VARGA, S. A. Operating Reactors Branch 1 83/02/22 4pp.
17357:244 24X Fiche: 50-315, 83/02/22, 8303020432.

--8303020448 Notice of issuance & availability of Amends 70 & 52 to Licenses DPR-58 & DPR-74, respectively.
VARGA, S. A. Operating Reactors Branch 1 83/02/22 2pp.
17357:248 24X Fiche: 50-315, 83/02/22, 8303020432.

8303180024 Requests confirmation on info tabulated from response re emergency operating facilities.
VARGA, S. A. Operating Reactors Branch 1 83/03/04 DOLAN, J. Indiana & Michigan Electric Co. 3pp 17625:272 24X
Fiche: 50-315, 83/03/04, 8303180024.

8303290597 Confirms 830310 telcon re fire protection review. Lack of fire dampers betwen adjacent areas containing redundant trains of safe shutdown equipment requires evaluation.
VARGA, S. A. Operating Reactors Branch 1 83/03/11 DOLAN, J. Indiana & Michigan Electric Co. 2pp 17747:359 24X
Fiche: 50-315, 83/03/11, 8303290597.

8303210215 Ack receipt of 830218 ltr informing of steps taken to correct problem re prompt public notification to transient population of Warren Dunes State Park.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 83/03/16 DOLAN, J. E. Indiana & Michigan Electric Co. 1p. 17632:001 24X Fiche: 50-315, 83/03/16, 8303210215.

8303250051 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records 83/03/21 Document Management Branch 1p. 17710:102 24X Fiche: 50-315, 83/03/21, 8303250051.

--8303250053 Forwards public version of Rev 0 to Emergency Plan Implementing Procedure PMP 2081 EPP 027, "Unit Vent Emergency Release Level Determination." Receipt form encl.
FRYER, J. Indiana & Michigan Electric Co. 83/03/09 NRC - No Detailed Affiliation Given 1p. 17710:103 24X
Fiche: 50-315, 83/03/21, 8303250051.

--8303250056 Public version of Rev 0 to Emergency Plan Implementing Procedure PMP 2081 EPP 027, "Unit Vent Emergency Release Level Determination."
MURPHY, C. E. Indiana & Michigan Electric Co. 83/03/01 12pp 17710:104 24X Fiche: 50-315, 83/03/21, 8303250051.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director 83/03/22 Commonwealth Edison Co. 2pp 17690:316 24X Fiche: 50-000, 83/03/22, 8303240440.

8303300788 Responds to 830214 ltr w/Rev 7 to modified amended security plan. Changes consistent w/10CFR50.54(p) provisions. Encl to ltr withheld (ref 10CFR73.21).
VARGA, S. A. Operating Reactors Branch 1 83/03/24 DOLAN, J. Indiana & Michigan Electric Co. 1p. 17770:255 24X
Fiche: 50-315, 83/03/24, 8303300788.

J. Insurance & indemnity information

8303110226 Forwards Endorsement 56 to NELIA Policy NF-206.
NADEL, M. Marsh & McLennan, Inc. 83/03/07 SALTZMAN, J. Assistant Director for State & Licensee Relations 2pp 17518:355 24X
Fiche: 50-315, 83/03/07, 8303110226.

P. Operating license stage documents & correspondence

8303010128 Advises that requirements of TMI Action Items I.A.2.1.4 & II.B.4.1 re upgrading of reactor operator training & training for mitigating core damage, respectively, satisfied.
VARGA, S. A. Operating Reactors Branch 1 83/02/11 DOLAN, J. Indiana & Michigan Electric Co. 5pp 17354:346 24X
Fiche: 50-315, 83/02/11, 8303010128.

--8208260154 "Improvements in Training & Requalification Programs as Required by TMI Action Items I.A.2.1 & II.B.4," final technical evaluation rept.
* Science Applications, Inc. NRC-03-82-096 SAI-186-029-09 82/08/17 NRC - No Detailed Affiliation Given 15pp. 17355:001 24X Fiche: 50-315, 83/02/11, 8303010128.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303020432 Forwards Amends 70 & 52 to Licenses DPR-58 & DPR-74, respectively & notice of issuance & availability. Amends modify licenses to include requirement to maintain guard training & qualification plan.
VARGA, S. A. Operating Reactors Branch 1 83/02/22 DOLAN, J. Indiana & Michigan Electric Co. 3pp 17357:241 24X
Fiche: 50-315, 83/02/22, 8303020432.

--8303020441 Amends 70 & 52 to Licenses DPR-58 & DPR-74, respectively, modifying licenses to include requirement to maintain guard training & qualification plan.
VARGA, S. A. Operating Reactors Branch 1 83/02/22 4pp.
17357:244 24X Fiche: 50-315, 83/02/22, 8303020432.

--8303020448 Notice of issuance & availability of Amends 70 & 52 to Licenses DPR-58 & DPR-74, respectively.
VARGA, S. A. Operating Reactors Branch 1 83/02/22 2pp.
17357:248 24X Fiche: 50-315, 83/02/22, 8303020432.

8303010265 Informs that Westinghouse analysis of lifting arrangement for reactor vessel head & upper internals will not be completed by 830315 due to backlog of load analyses at Westinghouse. Revised date for submittal is 830601.
ALEXICH, M. P. American Electric Power Service Corp. 83/02/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17335:106 24X Fiche: 50-315, 83/02/25, 8303010265.

8303010315 Requests extension until 830701 for submittal of plant-specific evaluation rept on adequacy of safety & relief valve discharge piping & plant-specific qualification of safety & relief valves (NUREG-0737, Item II.D.1).
ALEXICH, M. P. American Electric Power Service Corp. 83/02/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17333:322 24X Fiche: 50-315, 83/02/25, 8303010315.

8303010323 Requests that payment for NUREG-0737, Item II.F.1.6 Tech Spec be made part of single fee to be levied for issuance of Tech Spec changes required by NUREG-0737. Util should not be penalized for early implementation of safety equipment.
ALEXICH, M. P. American Electric Power Service Corp. 83/02/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17333:320 24X Fiche: 50-315, 83/02/25, 8303010323.

8303020013 Application to amend Licenses DPR-58 & DPR-74 by revising App A to Tech Specs re surveillance interval for inoperable equipment.
HUNTER, R. S. Indiana & Michigan Electric Co. 83/02/25. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17354:267.
24X Fiche: 50-315, 83/02/25, 8303020013.

--8303020020 Proposed changes to App A Tech Specs re surveillance interval for inoperable equipment.
* Indiana & Michigan Electric Co. 83/02/25. 3pp. 17354:270.
24X Fiche: 50-315, 83/02/25, 8303020013.

8303080141 Application for amend to Licenses DPR-58 & DPR-74, changing Tech Specs to permit storage of Westinghouse 15x15 optimized fuel assembly design fuel in new fuel storage area & spent fuel pool.
HUNTER, R. S. Indiana & Michigan Electric Co. 83/02/28. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17457:264.
24X Fiche: 50-315, 83/02/28, 8303080141.

--8303080145 "Summary of New & Spent Fuel Storage Array Criticality Safety Analyses."
* Indiana & Michigan Electric Co. 83/02/28. 21pp. 17457:266.
24X Fiche: 50-315, 83/02/28, 8303080141.

--8303080150 Proposed Tech Specs permiting storage of Westinghouse 15x15 optimized fuel assembly design fuel in new fuel storage area & spent fuel pool.
* Indiana & Michigan Electric Co. 83/02/28. 4pp. 17457:287.
24X Fiche: 50-315, 83/02/28, 8303080141.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303100159 Notification of 830315 meeting w/util & Exxon in Bethesda, MD to discuss fuel reload methodology & info/schedule for submittals to satisfy Cycle 4 & 5 requirements.
WIGGINTON, D. Operating Reactors Branch 1. 83/03/03. VARGA, S. A. Operating Reactors Branch 1. 2pp. 17496:014. 24X
Fiche: 50-315, 83/03/03, 8303100159.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J. G. Region 3, Office of Director. 83/03/03.
Commonwealth Edison Co. 2pp. 17492:014. 24X Fiche: 50-000, 83/03/03, 8303100364.

8303080111 Forwards Rev 2 to Procedure 12 PMP 3150 PCP 001, "Radwaste Process Manual," per requirement of radiological effluent Tech Spec (RETS) Section 6.14. NRC approval requested prior to RETS implementation date of 830415.
HUNTER, R. S. Indiana & Michigan Electric Co. 83/03/04. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17458:276. 24X
Fiche: 50-315, 83/03/04, 8303080111.

--8303080119 Rev 2 to Procedure 12 PMP 3150 PCP 001, "Radwaste Process Control Manual."
* Indiana & Michigan Electric Co. 83/02/15. 61pp. 17458:277.
24X Fiche: 50-315, 83/03/04, 8303080111.

8303080348 Provides justification for continued operation, in response to 821230 SER on environ qualification of safety-related electrical equipment.
HUNTER, R. S. Indiana & Michigan Electric Co. 83/03/04. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 17453:324.
24X Fiche: 50-315, 83/03/04, 8303080348.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303140344 Discusses License DPR-74 amend authorizing Cycle 4 which contains number of restrictions re reactor operations. Meeting requested for 830315 to present util program for obtaining info & justifying removal of licensing conditions.
HUNTER, R. S. Indiana & Michigan Electric Co. 83/03/07. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17534:243.
24X Fiche: 50-316, 83/03/07, 8303140344.

8303150673 Requests $4,400 fee still due for 820929 application for changes to Tech Specs re radiological water quality.
MILLER, W. O. License Fee Management Branch. 83/03/08. DOLAN, J. Indiana & Michigan Electric Co. 2pp. 17586:254. 24X
Fiche: 50-315, 83/03/08, 8303150673.

8303280050 Requests extension to 830615 to provide addl info requested in Generic Ltr 82-28 re inadequate core cooling instrumentation sys. Summary of previously submitted info re Westinghouse differential pressure monitoring sys encl.
HERING, R. F. Indiana & Michigan Electric Co. 83/03/11. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 5pp. 17707:298.
24X Fiche: 50-315, 83/03/11, 8303280050.

8303290800 Forwards order confirming util commitment to implement post-TMI-related items set forth in NUREG-0737 & Generic Ltrs 82-05 & 82-10.
VARGA, S. A. Operating Reactors Branch 1. 83/03/14. DOLAN, J. Indiana & Michigan Electric Co. 2pp. 17748:098. 24X
Fiche: 50-315, 83/03/14, 8303290800.

--8303290806 Order confirming util commitment to implement post-TMI-related items set forth in NUREG-0737 & Generic Ltrs 82-05 & 82-10. Hearing may be requested within 20 days of order publication.
PURPLE, R. A. Division of Licensing. 83/03/14. Indiana & Michigan Electric Co. 9pp. 17748:100. 24X Fiche: 50-315, 83/03/14, 8303290800.

8303250088 Requests remittance of Class I & III fees for application to change Tech Specs to permit storage of Westinghouse 15x15 optimized fuel in spent fuel pool.
DIGGS, R. H. License Fee Management Branch. 83/03/18. DOLAN, J. Indiana & Michigan Electric Co. 1p. 17700:356. 24X
Fiche: 50-315, 83/03/18, 8303250088.

Q. Inspection reports, IE Bulletins & correspondence

8303030619 Forwards IE Mgt Meeting Repts 50-315/82-25 & 50-316/82-25 on 820804, 0907, 1102 & 1229. No noncompliance noted.
KEPPLER, J. G. Region 3, Office of Director. 83/02/14. DOLAN, J. E. Indiana & Michigan Power Co. DOLAN, J. E. American Electric Power Service Corp. 2pp. 17409:298. 24X Fiche: 50-315, 83/02/14, 8303030619.

--8303030634 IE Mgt Meeting Repts 50-315/82-25 & 50-316/82-25 on 820804, 0907, 1102 & 1229. No noncompliance noted. Major areas discussed: responses to insp. repts, licensee mgt reviews & regulatory procedures.
STREETER, J. F. Division of Project & Resident Programs. 83/02/07. 5pp. 17409:300. 24X Fiche: 50-315, 83/02/14, 8303030619.

8303080248 Forwards IE Insp Repts 50-315/82-22 & 50-316/82-22 on 821101-1231 & notice of violation.
STREETER, J. F. Division of Project & Resident Programs. 83/02/18.
DOLAN, J. F. American Electric Power Service Corp. DOLAN, J. F. Indiana & Michigan Electric Co. 2pp. 17454:275. 24X
Fiche: 50-315, 83/02/15, 8303080248.

--8303080258 Notice of violation from insp on 821101-1231.
STREETER, J. F. Division of Project & Resident Programs. 83/02/18. 2pp. 17454:277. 24X Fiche: 50-315, 83/02/18, 8303080248.

--8303080270 IE Insp Repts 50-315/82-22 & 50-316/82-22 on 821101-1231. Noncompliance noted: failure to submit personnel radiation exposure rept to NRC & individuals & failure to implement QC by neglecting testing.
BOYD, D. C., SWANSON, E. R., DUBE[illegible], M. E. Division of Project & Resident Programs. 83/02/14. 14pp. [illegible]4:279. 24X Fiche: 50-315, 83/02/18, 8303080248.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521:001. 8X Fiche: 50-000, 83/02/25, 8212060367.

8303030463 Clarifies NRC position re procedures for admitting NRC personnel to facilities. Site orientation re issuance of badges, escort duties & emergency evacuation for personnel listed in Encls 1 & 2 requested.
KEPPLER, J. G. Region 3, Office of Director. 83/02/28. DOLAN, J. E. American Electric Power Service Corp. DOLAN, J. E. Indiana & Michigan Electric Co. 6pp. 17409:067. 24X Fiche: 50-315, 83/02/28, 8303030463.

8303140452 Responds to IE Bulletin 82-04, "Deficiency in Primary Containment Electrical Penetration Assemblies." No Bunker-Ramo electrical penetrations installed at facilities.
HUNTER, R. S. Indiana & Michigan Electric Co. 83/03/03. KEPPLER, J. G. Region 3, Office of Director. 2pp. 17542:238. 24X
Fiche: 50-315, 83/03/03, 8303140452.

8303210623 Forwards IE Insp Repts 50-315/83-03 & 50-316/83-03 on 830214-15 & notice of violation.
PAPERIELLO, C. J. Region 3, Office of Director 83/03/03 DOLAN, J. E. American Electric Power Service Corp. DOLAN, J. E. Indiana & Michigan Electric Co. 2pp. 17636:224 24X Fiche: 50-315, 83/03/03, 8303210623.

--8303210628 Notice of violation from insp on 830214-15.
PAPERIELLO, C. J. Region 3, Office of Director 83/03/03 1p. 17636:226 24X Fiche: 50-315, 83/03/03, 8303210623.

--8303210637 IE Insp Repts 50-315/83-03 & 50-316/83-03 on 830214-15. Noncompliance noted: failure to follow plant procedure during collection of vol control tank gaseous sample & to review & approve changes to plant procedure.
LOVENDALE, P. C. ; PECK, C. C. ; GREGER, L. R. Region 3, Office of Director 83/03/02 6pp. 17636:227 24X Fiche: 50-315, 83/03/03, 8303210623.

8303150218 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Surveillance test results satisfactory. Notification to all licensed operators is in progress.
HUNTER, R. S. Indiana & Michigan Electric Co. 83/03/07 KEPPLER, J. G. Region 3, Office of Director 4pp. 17556:084 24X Fiche: 50-315, 83/03/07, 8303150218.

8303140524 Confirms 830301 plans to conduct enforcement conference on 830316 in Glen Ellyn, IL. Region III ofc re circumstances surrounding inoperability of containment spray additive sys & degradation of safety injection flowpath.
NORELIUS, C. E. Division of Project & Resident Programs 83/03/09
DOLAN, J. American Electric Power Service Corp. DOLAN, J. Indiana & Michigan Electric Co. 1p. 17541:019 24X Fiche: 50-316, 83/03/09, 8303140524.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp. 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8303220279 Forwards safety evaluation & referenced portion of IE Insp Repts 50-315/82-24 & 50-316/82-24, documenting completed review of NUREG-0737, Item II.B.2.2, "Plant Shielding Access to Vital Areas."
NORELIUS, C. E. Division of Project & Resident Programs 83/03/18
EISENHUT, D. G. Division of Licensing 2pp. 17656:141 24X Fiche: 50-315, 83/03/18, 8303220279.

8303240178 Ack receipt of 830121 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/82-19 & 50-316/82-19. Shift briefings will be conducted when major testing activities completed.
NORELIUS, C. E. Division of Project & Resident Programs 83/03/18
DOLAN, J. E. American Electric Power Service Corp. DOLAN, J. E. Indiana & Michigan Electric Co. 2pp. 17681:001 24X Fiche: 50-315, 83/03/18, 8303240178.

--8303240190 Responds to NRC 821215 ltr re violations noted in IE Insp Repts 50-315/82-19 & 50-316/82-19. Corrective actions: controlled document containing list of all bistables to be tripped will be written.
HERING, R. F. Indiana & Michigan Electric Co. 83/01/21
KEPPLER, J. G. Region 3, Office of Director 6pp. 17681:003 24X Fiche: 50-315, 83/03/18, 8303240178.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12lpp. 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

## R. Periodic operating reports & related correspondence

8303080268 Forwards monthly operating rept for Dec 1982.
SMITH, W. G. Indiana & Michigan Electric Co. 83/01/13 Office of Resource Management, Director 1p. 17449:354 24X Fiche: 50-316, 83/01/13, 8303080268.

--8303080276 Monthly operating rept for Dec 1982.
MIGHT, A. ; SVENSSON, B. A. Indiana & Michigan Electric Co. 83/01/13 7pp. 17449:355 24X Fiche: 50-316, 83/01/13, 8303080268.

8303150537 Forwards monthly operating rept for Jan 1983.
SMITH, W. G. Indiana & Michigan Electric Co. 83/02/14 Office of Resource Management, Director 1p. 17568:185 24X Fiche: 50-316, 83/02/14, 8303150537.

--8303150544 Monthly operating rept for Jan 1983.
GILLETT, W. T. Indiana & Michigan Electric Co. 83/02/14 11pp. 17568:186 24X Fiche: 50-316, 83/02/14, 8303150537.

8303140399 Forwards "Semiannual Radioactive Effluent Release Rept, Jul-Dec 1982."
HUNTER, R. S. Indiana & Michigan Electric Co. 83/03/01 KEPPLER, J. G. Region 3, Office of Director 1p. 17541:238 24X Fiche: 50-315, 83/03/01, 8303140399.

--8303140401 "Semiannual Radioactive Effluent Release Rept, Jul-Dec 1982." * Indiana & Michigan Electric Co. 83/03/01 177pp. 17541:239 24X Fiche: 50-315, 83/03/01, 8303140399.

## S. Reportable occurrences, LERs & related correspondence

8303080436 RO on 830224, during review of computerized printout which delineates calibr surveillance test schedules, discovered that containment fire detector instrumentation surveillance test not performed.
SMITH, W. G. Indiana & Michigan Electric Co. 83/02/24 KEPPLER, J. G. Region 3, Office of Director 1p. 17454:165 24X Fiche: 50-316, 83/02/24, 8303080436.

8303080507 Forwards LERs 83-023/03L-0 & 83-024/03L-0.
SMITH, W. G. Indiana & Michigan Electric Co. 83/02/25 KEPPLER, J. G. Region 3, Office of Director 1p. 17450:312 24X Fiche: 50-316, 83/02/25, 8303080507.

--8303080514 LER 83-023/03L-0 on 830203, east containment spray tank discharge isolation valve CTS 128E could not reopen after surveillance test. Caused by galling between valve stem & yoke bushing. Valve stem & yoke bushing cleaned & lubricated.
CARTEAUX, P. Indiana & Michigan Electric Co. 83/02/25 Region 3, Office of Director 1p. 17450:313 24X Fiche: 50-316, 83/02/25, 8303080507.

--8303080519 LER 83-024/03L-0 on 830203, during normal operation, control air to containment isolation valve (XCR-100) closed & deactivated to permit troubleshooting on possible ground. Caused by faulty cable. New cable installed.
PALMER, R. A. Indiana & Michigan Electric Co. 83/02/25 Region 3, Office of Director 1p. 17450:314 24X Fiche: 50-316, 83/02/25, 8303080507.

8303140518 Forwards LER 83-025/03L-0.
SMITH, W. G. Indiana & Michigan Electric Co. 83/03/02 KEPPLER, J. G. Region 3, Office of Director 1p. 17534:176 24X Fiche: 50-316, 83/03/02, 8303140518.

--8303140525 LER 83-025/03L-0 on 830203 & 05, fire door 374 to startup blowdown flash tank area would not close against air flow through door opening. Door closer mechanism & closer arm & screws replaced. Door closer adjusted.
CARTEAUX, P. Indiana & Michigan Electric Co. 83/03/02 Region 3, Office of Director 1p. 17534:177 24X Fiche: 50-316, 83/03/02, 8303140518.

8303210416 Forwards LER 83-026/01T-0.
SMITH, W. G. Indiana & Michigan Electric Co. 83/03/10 KEPPLER, J. G. Region 3, Office of Director 1p. 17634:255 24X Fiche: 50-316, 83/03/10, 8303210416.

--8303210424 LER 83-026/01T-0 on 830224, containment fire detection sys surveillance had not been performed within required allowable time. Caused by personnel error. Computer scheduling updated to include all control & surveillance tests.
PALMER, R. A. Indiana & Michigan Electric Co. 83/03/10 Region 3, Office of Director 2pp. 17634:256 24X Fiche: 50-316, 83/03/10, 8303210416.

8303240401 Forwards LER 83-022/03L-0.
SMITH, W. G. Indiana & Michigan Electric Co. 83/03/17 KEPPLER, J. G. Region 3, Office of Director 1p. 17679:048 24X Fiche: 50-316, 83/03/17, 8303240401.

--8303240402 LER 83-022/03L-0 on 830218, carbon dioxide sys switch discovered in isolated position w/no established fire watch. Caused by personnel error. Key lock switches installed.
PALMER, R. A. Indiana & Michigan Electric Co. 83/03/17 Region 3, Office of Director 1p. 17679:049 24X Fiche: 50-316, 83/03/17, 8303240401.

8303290386 RO on 830219, reservoir containing lubricating oil for turbine 2 leaked into Lake MI. Caused by tube failure. Tube plugged.
BMI, A.W.G. Indiana & Michigan Electric Co. 83/03/17. KEPPLER, J.G. Region 3, Office of Director. 3pp. 17716:268. 24X
Fiche: 50-315, 83/03/17, 8303290386.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D.G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303040476 Requests util policy re facial hair & effect on access to plant facilities during operator licensing exams. Recent denial of access to NRC examiners due to facial hair could potentially interfere w/insp program.
HIND, J.A. Division of Project & Resident Programs. 83/02/28.
DOLAN, J.E. American Electric Power Service Corp. DOLAN, J.E. Indiana & Michigan Electric Co. 1p. 17374:013. 24X
Fiche: 50-315, 83/02/28, 8303040476.

DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8303030246 Forwards IE Safeguards Insp Repts 50-317/82-28 & 50-318/82-24 on 821101-05 & notice of violation.
MARTIN, T.T. Division of Engineering & Technical Programs. 82/02/16.
BOWMAKER, N.J. Baltimore Gas & Electric Co. 2pp. 17410:342. 24X
Fiche: 50-317, 83/02/16, 8303030246.

--8303030254 Notice of violation from insp on 821101-05. Safeguards info deleted (ref 10CFR73.21).
* Division of Engineering & Technical Programs. 83/02/16. 2pp. 17410:344. 24X Fiche: 50-317, 83/02/16, 8303030246.

--8303030268 IE Safeguards Insp Repts 50-317/82-28 & 50-318/82-24 on 821101-05. Noncompliance noted: failure to maintain isolation zone & apply compensatory measures per security plan requirements. Safeguards info deleted (ref 10CFR73.21).
MCKEOWN, L.M., DUNLAP, J.M., GODY, A.T. Division of Engineering & Technical Programs. 82/02/15. 6pp. 17410:346. 24X
Fiche: 50-317, 83/02/16, 8303030246.

8303020035 Application to amend Licenses DPR-53 & DPR-69, requesting schedular relief from emergency lighting requirements per App R, as described. Class I & III amend fees encl.
LUNDVALL, A.E. Baltimore Gas & Electric Co. 83/02/23. CLARK, R.A. Operating Reactors Branch 3. 4pp. 17352:189. 24X
Fiche: 50-317, 83/02/23, 8303020035.

8303020081 Forwards revs to training & qualification plan. Revs withheld (ref 10CFR73.21).
BOWMAKER, N.J. Baltimore Gas & Electric Co. 83/02/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 17352:164. 24X
Fiche: 50-317, 83/02/23, 8303020081.

8303090424 Forwards Amends 81 & 64 to Licenses DPR-53 & DPR-69, respectively, & notice of issuance & availability. Amends incorporate most recent revs to physical security plan.
CLARK, R.A. Operating Reactors Branch 3. 83/02/24. LUNDVALL, A.E. Baltimore Gas & Electric Co. 3pp. 17484:070. 24X
Fiche: 50-317, 83/02/24, 8303090424.

--8303090434 Amends 81 & 64 to Licenses DPR-53 & DPR-69, respectively, incorporating most recent revs to physical security plan.
CLARK, R.A. Operating Reactors Branch 3. 83/02/24. 4pp. 17484:074. 24X Fiche: 50-317, 83/02/24, 8303090424.

--8303090447 Notice of issuance & availability of Amends 81 & 64 to Licenses DPR-53 & DPR-69, respectively.
CLARK, R.A. Operating Reactors Branch 3. 83/02/24. 2pp. 17484:078. 24X Fiche: 50-317, 83/02/24, 8303090424.

8303100227 Forwards IE Insp Repts 50-317/83-02 & 50-318/83-02 on 830111-0215. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs. 83/02/25.
LUNDVALL, A.E. Baltimore Gas & Electric Co. 2pp. 17489:235. 24X
Fiche: 50-317, 83/02/25, 8303100227.

--8303100243 IE Insp Repts 50-317/83-02 & 50-318/83-02 on 830111-0215. No noncompliance noted. Major areas inspected: control room, accessible parts of plant structures, operations, radiation protection, physical security & radwaste releases.
ARCHITZEL, R.E., TRIMBLE, D.C. Region 1, Office of Director. MCCABE, E.C. Division of Project & Resident Programs. 83/02/23. 25pp. 17489:237. 24X Fiche: 50-317, 83/02/25, 8303100227.

8303110130 Requests exemption from certain 10CFR50, App R requirements to install automatic fire suppression sys in main control room & intake structure. Control room area continuously manned & has low fire load installation capability.
LUNDVALL, A.E. Baltimore Gas & Electric Co. 83/03/04. CLARK, R.A. Operating Reactors Branch 3. 5pp. 17517:314. 24X
Fiche: 50-317, 83/03/04, 8303110130.

8303300065 Responds to 821230 ltr transmitting security plan changes. Changes consistent w/provisions of 10CFR50.54(P) & do not decrease effectiveness of plan. Encl to ltrs withheld (ref 10CFR73.21).
CLARK, R.A. Operating Reactors Branch 3. 83/03/14. LUNDVALL, A.E. Baltimore Gas & Electric Co. 2pp. 17751:065. 24X
Fiche: 50-317, 83/03/14, 8303300065.

8303220446 Forwards exemption granting extension to deadline for implementation of emergency lighting sys per App R to 10CFR50.
EISENHUT, D.G. Division of Licensing. 83/03/15. LUNDVALL, A.E. Baltimore Gas & Electric Co. 3pp. 17670:059. 24X
Fiche: 50-317, 83/03/15, 8303220446.

--8303220450 Exemption from schedular requirements of 10CF50.48 re installation of emergency lighting sys. Deadline extended to 830901.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 83/03/15. Baltimore Gas & Electric Co. 4pp. 17670:061. 24X
Fiche: 50-317, 83/03/15, 8303220446.

8303220015 Forwards revs to security & safeguards contingency plans. Revs withheld (ref 10CFR73.21).
BOWMAKER, N.J. Baltimore Gas & Electric Co. 83/03/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 17652:109. 24X
Fiche: 50-317, 83/03/16, 8303220015.

8303240377 Provides addl info to clarify 830303 request for exemption from schedular requirements of 10CFR50, App R Mods, w/ exception of flux monitoring & emergency lighting, specifically discussed in interactive cable analyses.
LUNDVALL, A.E. Baltimore Gas & Electric Co. 83/03/17. CLARK, R.A. Operating Reactors Branch 3. 3pp. 17679:075. 24X
Fiche: 50-317, 83/03/17, 8303240377.

8303280357 Advises that Region I must be notified in 60 days if util plans to continue practice of designating company personnel holding high-level positions as regular site employees to fulfill physical search requirements.
CLARK, R.A. Operating Reactors Branch 3. 83/02/17. LUNDVALL, A.E. Baltimore Gas & Electric Co. 2pp. 17726:304. 24X
Fiche: 50-317, 83/03/17, 8303280357.

8303300770 Releases public version of revised emergency plan implementing procedures.
FELTON, J.M. Division of Rules and Records. 83/03/25. Document Management Branch. 1p. 17765:212. 24X Fiche: 50-317, 83/03/25, 8303300770.

--8303300774 Forwards public version of revised emergency plan implementing procedures, including Procedures ERPIP 4.1.25 re environ svcs, ERPIP 4.1.26 re environ monitoring team & ERPIP 4.5.6 re offsite protective actions.
* Baltimore Gas & Electric Co. 83/03/21. CLARK, R.A. Division of Licensing. 1p. 17765:213. 24X Fiche: 50-317, 83/03/25, 8303300770.

--8303300777 Public version of revised emergency plan implementing procedures, including Procedures ERPIP 4.1.25 re environ svcs, ERPIP 4.1.26 re environ monitoring team & ERPIP 4.5.6 re offsite protective actions.
* Baltimore Gas & Electric Co. 83/02/09. 29pp. 17765:215. 24X
Fiche: 50-317, 83/03/25, 8303300770.

J. Insurance & indemnity information

8303290370 Forwards Endorsements 52 & 21 to NELIA Policies NF-216 & NS-348, respectively.
YORK, W.G. Baltimore Gas & Electric Co. 83/03/23. DINITZ, I. Assistant Director for State & Licensee Relations. 3pp. 17716:198. 24X Fiche: 50-317, 83/03/23, 8303290370.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492.033 24X
Fiche: 50-000, 83/02/16, 8302170082

8303020035 Application to amend Licenses DPR-53 & DPR-69, requesting schedular relief from emergency lighting requirements per App R, as described. Class I & III amend fees encl.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/02/23 CLARK, R. A. Operating Reactors Branch 3 4pp 17352.189 24X
Fiche: 50-317, 83/02/23, 8303020035

8303040328 Responds to 830104 ltr re qualification of shift technical advisors. Shift technical advisor candidates, w/exception of four individuals listed in 830104 ltr, must have bachelor degree or equivalent in scientific/engineering discipline.
CLARK, R. A. Operating Reactors Branch 3 83/02/23 LUNDVALL, A. E. Baltimore Gas & Electric Co. 3pp 17426.285 24X
Fiche: 50-317, 83/02/23, 8303040328

8303010528 Application for amend to Licenses DPR-53 & DPR-69, changing Tech Specs re RCS containment sys, plant sys & electrical power sys.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/02/24 CLARK, R. A. Operating Reactors Branch 3 7pp 17342.261 24X
Fiche: 50-317, 83/02/24, 8303010528

--8303010536 Proposed Tech Specs re RCS, containment sys, plant sys & electrical power sys.
* Baltimore Gas & Electric Co. 83/02/24 101pp 17342.268 24X
Fiche: 50-317, 83/02/24, 8303010528

8303090424 Forwards Amends 81 & 64 to Licenses DPR-53 & DPR-69, respectively & notice of issuance & availability. Amends incorporate most recent revs to physical security plan.
CLARK, R. A. Operating Reactors Branch 3 83/02/24 LUNDVALL, A. E. Baltimore Gas & Electric Co. 3pp 17484.070 24X
Fiche: 50-317, 83/02/24, 8303090424

--8303090434 Amends 81 & 64 to Licenses DPR-53 & DPR-69, respectively, incorporating most recent revs to physical security plan.
CLARK, R. A. Operating Reactors Branch 3 83/02/24 4pp 17484.074 24X Fiche: 50-317, 83/02/24, 8303090424

--8303090447 Notice of issuance & availability of Amends 81 & 64 to Licenses DPR-53 & DPR-69, respectively.
CLARK, R. A. Operating Reactors Branch 3 83/02/24 2pp 17484.078 24X Fiche: 50-317, 83/02/24, 8303090424

8303090217 Assures that requirements of NUREG-0737, Item II.D.1, "PORV Block Valve Testing," satisfied. Valve functional adequacy demonstrated by tests of similar valves conducted by EPRI.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/01 CLARK, R. A. Operating Reactors Branch 3 2pp 17472.349 24X
Fiche: 50-317, 83/03/01, 8303090217

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700.303 24X
Fiche: 50-000, 83/03/02, 8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5pp 17660.176 24X
Fiche: 50-000, 83/03/07, 8303040005

8303100266 Clarifies various aspects of design & operation of RCS vents, in response to NUREG-0737, Item II.B.1.
OLSON, R. C. Baltimore Gas & Electric Co. 83/03/07 CLARK, R. A. Operating Reactors Branch 3 2pp 17489.179 24X
Fiche: 50-317, 83/03/07, 8303100266

8303210177 Application for amend to License DPR-53 revising limiting condition for operation for containment structural integrity, to allow time for engineering evaluation of potentially abnormal condition.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/07 CLARK, R. A. Operating Reactors Branch 3 2pp 17632.188 24X
Fiche: 50-317, 83/03/07, 8303210177

--8303210188 Proposed Tech Specs revising limiting condition for operation for containment structural integrity to allow specified time period for performance of engineering evaluation of potentially abnormal condition.
* Baltimore Gas & Electric Co. 83/03/07 7pp 17632.190 24X
Fiche: 50-317, 83/03/07, 8303210177

--8303210192 "Safety Evaluation for Proposed Tech Spec Rev to Containment Structure Post-Tensioning Sys Limiting Condition for Operation & Tendon Surveillance Requirements."
* Baltimore Gas & Electric Co. 83/02/01 18pp 17632.197 24X
Fiche: 50-317, 83/03/07, 8303210177

8303150387 Informs that info re NUREG-0737, Action Item II.D.1, "Performance Testing of Safety & Relief Valves," will be submitted no later than Sept 1983 for Unit 1 & Feb 1984 for Unit 2, per 821116 ltr.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/09 CLARK, R. A. Operating Reactors Branch 3 2pp 17592.018 24X
Fiche: 50-317, 83/03/09, 8303150387

8303170274 Describes current status of inadequate core cooling instrumentation sys & schedule for submittal of remaining info, per Generic Ltr 82-28 for NUREG-0737, Item II.F.2. Delay due to installation of reactor coolant tracking sys.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/10 CLARK, R. A. Operating Reactors Branch 3 3pp 17606.054 24X
Fiche: 50-317, 83/03/10, 8303170274

8303230068 Summary of 830224 meeting w/util re recent problems w/ESF actuation sys. Util contends that problem was properly diagnosed as inverter problem & that mods made. Agenda & viewgraphs encl.
JAFFE, D. H. Operating Reactors Branch 3 83/03/10 Operating Reactors Branch 3 25pp 17688.080 24X Fiche: 50-317, 83/03/10, 8303230068

8303170056 Forwards response to 830111 ltr requesting info re TMI Action Items II.F.1.4, 5 & 6 concerning post-implementation review of containment pressure, water level & hydrogen monitors.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/14 CLARK, R. A. Operating Reactors Branch 3 9pp 17608.315 24X
Fiche: 50-317, 83/03/14, 8303170056

8303290300 Application for amend to Licenses DPR-53 & DPR-69, replacing Tech Spec Pp 3/4 1-19, 3/4 1-22 & B 3/4 1-4 re reactivity control sys.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/15 CLARK, R. A. Operating Reactors Branch 3 5pp 17716.181 24X
Fiche: 50-317, 83/03/15, 8303290300

--8303290304 Proposed Tech Spec Pp 3/4 1-19, 3/4 1-22 & B 3/4 1-4 re reactivity control sys.
* Baltimore Gas & Electric Co. 83/03/15 6pp 17716.186 24X
Fiche: 50-317, 83/03/15, 8303290300

8303300110 Forwards order confirming util commitment to implement post-TMI items in NUREG-0737 & in responses to Generic Ltrs 82-05 & 82-10.
CLARK, R. A. Operating Reactors Branch 3 83/03/16 LUNDVALL, A. E. Baltimore Gas & Electric Co. 3pp 17749.256 24X
Fiche: 50-317, 83/03/16, 8303300110

--8303300118 Order confirming util commitment to implement post-TMI items in NUREG-0737 & in responses to Generic Ltrs 82-05 & 82-10.
PURPLE, R. A. Division of Licensing 83/03/16 Baltimore Gas & Electric Co. 9pp 17749.259 24X Fiche: 50-317, 83/03/16, 8303300110

8303310270 Informs of application of HERMITE methodology to steam line break analysis for Cycle 7 per recent design & analysis changes. Code does not constitute new methodology & can be folded into routine reload license application.
MIHALCIK, J. A. Baltimore Gas & Electric Co. 83/03/28 CLARK, R. A. Operating Reactors Branch 3 3pp 17756.034 24X
Fiche: 50-317, 83/03/28, 8303310270

Q. Inspection reports, IE Bulletins & correspondence

8303030246 Forwards IE Safeguards Insp Repts 50-317/82-28 & 50-318/82-24 on 821101-05 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs 82/02/16
BOWMAKER, N. J. Baltimore Gas & Electric Co. 2pp 17410.342 24X
Fiche: 50-317, 83/02/16, 8303030246

--8303030254 Notice of violation from insp on 821101-05 Safeguards info deleted (ref 10CFR73.21).
* Division of Engineering & Technical Programs 83/02/16 2pp 17410.344 24X Fiche: 50-317, 83/02/16, 8303030246

--8303030268 IE Safeguards Insp Repts 50-317/82-28 & 50-318/82-24 on 821101-05 Noncompliance noted: failure to maintain isolation zone & apply compensatory measures per security plan requirements. Safeguards info deleted (ref 10CFR73.21). MCKEOWN, L. M.; DUNLAP, J. M.; GODY, A. T. Division of Engineering & Technical Programs 82/02/15 6pp 17410:346 24X Fiche: 50-317, 83/02/16, 8303030246.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11pp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303100227 Forwards IE Insp Repts 50-317/83-02 & 50-318/83-02 on 830111-0215. No noncompliance noted. STAROSTECKI, R. Division of Project & Resident Programs 83/02/25. LUNDVALL, A. E. Baltimore Gas & Electric Co. 2pp 17489:235 24X Fiche: 50-317, 83/02/25, 8303100227.

--8303100243 IE Insp Repts 50-317/83-02 & 50-318/83-02 on 830111-0215. No noncompliance noted. Major areas inspected: control room, accessible parts of plant structures, operations, radiation protection, physical security & radwaste releases. ARCHITZEL, R. E.; TRIMBLE, D. C. Region 1, Office of Director. MCCABE, E. C. Division of Project & Resident Programs. 83/02/23. 25pp. 17489:237 24X Fiche: 50-317, 83/02/25, 8303100227.

8303110308 Forwards "Calvert Cliffs Unit 1 Eddy Current Insp of Steam Generators 11 & 12" & "Calvert Cliffs Units 2 Eddy Current Insp of Steam Generators 21 & 22," per Tech Spec 4.4.5.5. Insp results discussed. List of tubes examined encl. LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/02/25 HAYNES, R. C. Region 1, Office of Director. 6pp. 17518:121 24X Fiche: 50-317, 83/02/25, 8303110308.

--8303110312 "Calvert Cliffs Unit 1 Eddy Current Insp of Steam Generators 11 & 12," Final rept. BEIERS, T. S. Zetec, Inc. 82/05/31 82pp 17518:128 24X Fiche: 50-317, 83/02/25, 8303110308.

--8303110317 "Calvert Cliffs Unit 2 Eddy Current Insp of Steam Generators 21 & 22," Final rept. GRAY, W. A.; BEIERS, T. S. Zetec, Inc. 82/12/31 118pp 17518:223 24X Fiche: 50-317, 83/02/25, 8303110308.

8303090063 Responds to IE Bulletin 82-04 re Bunker Ramo Co electrical penetrations. All Bunker Ramo electrical penetrations utilizing header design replaced w/Conax Corp penetrations. LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/01 HAYNES, R. C. Region 1, Office of Director. 2pp. 17467:018 24X Fiche: 50-317, 83/03/01, 8303090063.

8303090277 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." No Westinghouse DB-50 breakers used at facilities. LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/03. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 2pp. 17473:335 24X Fiche: 50-317, 83/03/03, 8303090277.

8303110295 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." No Westinghouse DB type breakers employed at facilities. LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/03 HAYNES, R. C. Region 1, Office of Director. 2pp. 17520:076 24X Fiche: 50-317, 83/03/03, 8303110295.

8303160558 Forwards IE Insp Repts 50-317/83-01 & 50-318/83-01 on 830117-21 & notice of violation. MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/03. LUNDVALL, A. E. Baltimore Gas & Electric Co. 2pp. 17587:269 24X Fiche: 50-317, 83/03/03, 8303160558.

--8303160564 Notice of violation from insp on 830117-21. * Region 1, Office of Director. 83/03/03 1p. 17587:271 24X Fiche: 50-317, 83/03/03, 8303160558.

--8303160570 IE Insp Repts 50-317/83-01 & 50-318/83-01 on 830117-21. Noncompliance noted: failure to establish adequate procedures for respiratory protective equipment. MCBRIDE, M. H.; SHANBAKY, M. Region 1, Office of Director. 83/02/28. 7pp. 17587:272 24X Fiche: 50-317, 83/03/03, 8303160558.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering. Response (Post 830103). 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche: 50-000, 83/03/18, 8212060383.

8303220341 Forwards computer printouts supplementing 830210 response to NRC 821216 SER re environ qualification of safety-related equipment, per IE Bulletin 79-01B. LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/18 CLARK, R. A. Operating Reactors Branch 3. 286pp. 17648:056 24X Fiche: 50-317, 83/03/18, 8303220341.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering. Response (Post 830103). 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp. 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

R. Periodic operating reports & related correspondence

8303100363 Forwards "Number of Personnel & Man-Rem by Work & Lab Function for 1982." TIERMAN, J. A. Baltimore Gas & Electric Co. 83/03/01 HAYNES, R. C. Region 1, Office of Director. 1p. 17490:332 24X Fiche: 50-317, 83/03/01, 8303100363.

--8303100365 "Number of Personnel & Man-Rem by Work & Job Function, 1982." * Baltimore Gas & Electric Co. 83/03/01 2pp 17490:333 24X Fiche: 50-317, 83/03/01, 8303100363.

8303220022 Forwards monthly operating repts for Feb 1983. LOTITO, E. M. Baltimore Gas & Electric Co. 83/03/16 Director's Office, Office of Inspection and Enforcement. 1p. 17652:132 24X Fiche: 50-317, 83/03/16, 8303220022.

--8303220026 Monthly operating repts for Feb 1983. LOTITO, E. Baltimore Gas & Electric Co. 83/03/15 11pp 17652:133 24X Fiche: 50-317, 83/03/16, 8303220022.

8303220316 Forwards revised monthly operating repts for Oct 1982 - Feb 1983. LOTITO, E. M. Baltimore Gas & Electric Co. 83/03/17 Director's Office, Office of Inspection and Enforcement. 1p. 17656:102 24X Fiche: 50-317, 83/03/17, 8303220316.

--8303220322 Revised monthly operating rept for Oct 1982. LOTITO, E. Baltimore Gas & Electric Co. 83/03/17 1p. 17656:103 24X Fiche: 50-317, 83/03/17, 8303220316.

--8303220328 Revised monthly operating rept for Nov 1982. LOTITO, E. Baltimore Gas & Electric Co. 83/03/17 1p. 17656:104 24X Fiche: 50-317, 83/03/17, 8303220316.

--8303220334 Revised monthly operating rept for Dec 1982. LOTITO, E. Baltimore Gas & Electric Co. 83/03/17 1p. 17656:105 24X Fiche: 50-317, 83/03/17, 8303220316.

--8303220339 Revised monthly operating rept for Jan 1983. LOTITO, E. Baltimore Gas & Electric Co. 83/03/17 1p. 17656:106 24X Fiche: 50-317, 83/03/17, 8303220316.

--8303220346 Revised monthly operating rept for Feb 1983. LOTITO, E. Baltimore Gas & Electric Co. 83/03/17 1p. 17656:107 24X Fiche: 50-317, 83/03/17, 8303220316.

S. Reportable occurrences, LERs & related correspondence

8303010244 Forwards LER 83-008/01T-0. RUSSELL, L. B. Baltimore Gas & Electric Co. 83/02/18 HAYNES, R. C. Region 1, Office of Director. 1p. 17335:176 24X Fiche: 50-317, 83/02/18, 8303010244.

--8303010256 LER 83-008/01T-0 on 830205, control element assembly 26 reed switch position indication was erratic & declared inoperable. Caused by failure of reed stack position transmitter for assemblies 26 & 28 Transmitters replaced. JUNGE, M. A.; RAYNOR, J. W. Baltimore Gas & Electric Co. 83/02/18. Region 1, Office of Director. 2pp 17335:177 24X Fiche: 50-317, 83/02/18, 8303010244.

8303140194 Forwards LER 83-010/03L-0. RUSSELL, L. B. Baltimore Gas & Electric Co. 83/02/25 HAYNES, R. C. Region 1, Office of Director. 1p. 17528:129 24X Fiche: 50-317, 83/02/25, 8303140194.

--8303140199 LER 83-010/03L-0 on 830127, boric acid storage tank 11 rendered inoperable due to high boron concentration. Caused by inadequate procedures. Procedures modified & chemistry technicians informed.
JUNGE, M A. ; BROBST, G E. Baltimore Gas & Electric Co. 83/02/25
Region 1, Office of Director. 2pp. 17528:130. 24X
Fiche: 50-317, 83/02/25, 8303140194.

8303140375 Forwards LER 83-006/03L-0.
RUSSELL, L. B. Baltimore Gas & Electric Co. 83/02/25. HAYNES, R. C.
Region 1, Office of Director. 1p. 17542:197. 24X
Fiche: 50-317, 83/02/25, 8303140375.

--8303140378 LER 83-006/03L-0 on 830127, during normal operation, intake structure door 1B-1 found open. Door left open following painting. Caused by personnel error in not following posted instructions. Personnel counseled.
LAGIEWSKI, J. S. ; MAHON, C. R. Baltimore Gas & Electric Co. 83/02/25
Region 1, Office of Director. 1p. 17542:198. 24X
Fiche: 50-317, 83/02/25, 8303140375.

8303160268 Forwards updated LER 82-070/01X-1.
RUSSELL, L. B. Baltimore Gas & Electric Co. 83/03/03. HAYNES, R. C.
Region 1, Office of Director. 1p. 17596:335. 24X
Fiche: 50-317, 83/03/03, 8303160268.

--8303160274 Updated LER 82-070/01X-1 on 821118, mgt informed that generation of chemical vol & control isolation signal may be prohibited by single failure. Caused by two sensor channels in letdown HX room not seeing pressure increase.
WENGER, L. W. Baltimore Gas & Electric Co. 83/03/03. Region 1, Office of Director. 2pp. 17596:336. 24X Fiche: 50-317, 83/03/03, 8303160268.

8303210410 Forwards LER 83-009/03L-0.
RUSSELL, L. B. Baltimore Gas & Electric Co. 83/03/10. HAYNES, R. C.
Region 1, Office of Director. 1p. 17634:260. 24X
Fiche: 50-317, 83/03/10, 8303210410.

--8303210418 LER 83-009/03L-0 on 830210, while conducting review of snubber surveillance test procedures, snubber 2-15-10 not included in Tech Specs & snubber 1-15-8 missed surveillance. Snubber 2-15-10 incorrectly tagged 1-15-8.
FARRELL, E. V. Baltimore Gas & Electric Co. 83/03/10. Region 1, Office of Director. 2pp. 17634:261. 24X Fiche: 50-317, 83/03/10, 8303210410.

8303210613 Forwards LER 83-011/03L-0.
RUSSELL, L. B. Baltimore Gas & Electric Co. 83/03/10. HAYNES, R. C.
Region 1, Office of Director. 1p. 17636:237. 24X
Fiche: 50-317, 83/03/10, 8303210613.

--8303210621 LER 83-011/03L-0 on 830212, during Mode 1, refueling water tank level decreased below Tech Specs limit. Caused by failure of operating instruction to require shutting of spent fuel pool pump 11 suction. Instruction corrected.
WENDERLICH, R. L. Baltimore Gas & Electric Co. 83/03/10. Region 1, Office of Director. 1p. 17636:238. 24X Fiche: 50-317, 83/03/10, 8303210613.

8303290078 Forwards AEOD/E304, "Investigation of Backflow Protection in Common Equipment & Floor Drain Sys to Prevent Flooding of Vital Equipment in Safety-Related Compartments." AEOD engineering evaluation rept.
HELTEMES, C. J. Director's Office. 83/03/11. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17729:260. 24X
Fiche: 50-317, 83/03/11, 8303290078.

--8303290088 "Investigation of Backflow Protection in Common Equipment & Floor Drain Sys to Prevent Flooding of Vital Equipment in Safety-Related Compartments." AEOD engineering evaluation rept.
* Director's Office. 83/03/11. 6pp. 17729:261. 24X
Fiche: 50-317, 83/03/11, 8303290078.

8303290097 Forwards AEOD/E304, "Investigation of Backflow Protection in Common Equipment & Floor Drain Sys to Prevent Flooding of Vital Equipment in Safety-Related Compartments." AEOD engineering evaluation rept.
CINTULA, T. C. Reactor Operations Analysis Branch. 83/03/11.
SEYFRIT, K. V. Reactor Operations Analysis Branch. 1p. 17729:225. 24X Fiche: 50-317, 83/03/11, 8303290097.

8303290109 Forwards AEOD/E304, "Investigation of Backflow Protection in Common Equipment & Floor Drain Sys to Prevent Flooding of Vital Equipment in Safety-Related Compartments." AEOD engineering evaluation rept.
HELTEMES, C. J. Director's Office. 83/03/11. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 1p. 17729:181. 24X Fiche: 50-317, 83/03/11, 8303290109.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8303030246 Forwards IE Safeguards Insp Repts 50-317/82-28 & 50-318/82-24 on 821101-05 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs. 82/02/16.
BOWMAKER, N. J. Baltimore Gas & Electric Co. 2pp. 17410:342. 24X
Fiche: 50-317, 83/02/16, 8303030246.

--8303030254 Notice of violation from insp on 821101-05. Safeguards info deleted (ref 10CFR73.21).
* Division of Engineering & Technical Programs. 83/02/16. 2pp. 17410:344. 24X Fiche: 50-317, 83/02/16, 8303030246.

--8303030268 IE Safeguards Insp Repts 50-317/82-28 & 50-318/82-24 on 821101-05. Noncompliance noted: failure to maintain isolation zone & apply compensatory measures per security plan requirements. Safeguards info deleted (ref 10CFR73.21).
MCKEOWN, L. M. Division of Engineering & Technical Programs. 82/02/15. 6pp. 17410:346. 24X Fiche: 50-317, 83/02/16, 8303030246.

8303020035 Application to amend Licenses DPR-53 & DPR-69, requesting schedular relief from emergency lighting requirements per App R, as described. Class I & III amend fees encl.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/02/23. CLARK, R. A. Operating Reactors Branch 3. 4pp. 17352:189. 24X
Fiche: 50-317, 83/02/23, 8303020035.

8303020081 Forwards revs to training & qualification plan. Revs withheld (ref 10CFR73.21).
BOWMAKER, N. J. Baltimore Gas & Electric Co. 83/02/23. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17352:164. 24X
Fiche: 50-317, 83/02/23, 8303020081.

8303090424 Forwards Amends 81 & 64 to Licenses DPR-53 & DPR-69, respectively, & notice of issuance & availability. Amends incorporate most recent revs to physical security plan.
CLARK, R. A. Operating Reactors Branch 3. 83/02/24. LUNDVALL, A. E. Baltimore Gas & Electric Co. 3pp. 17484:070. 24X
Fiche: 50-317, 83/02/24, 8303090424.

--8303090434 Amends 81 & 64 to Licenses DPR-53 & DPR-69, respectively, incorporating most recent revs to physical security plan.
CLARK, R. A. Operating Reactors Branch 3. 83/02/24. 4pp. 17484:074. 24X Fiche: 50-317, 83/02/24, 8303090424.

--8303090447 Notice of issuance & availability of Amends 81 & 64 to Licenses DPR-53 & DPR-69, respectively.
CLARK, R. A. Operating Reactors Branch 3. 83/02/24. 2pp. 17484:078. 24X Fiche: 50-317, 83/02/24, 8303090424.

8303100227 Forwards IE Insp Repts 50-317/83-02 & 50-318/83-02 on 830111-0215. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs. 83/02/25.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 2pp. 17489:235. 24X
Fiche: 50-317, 83/02/25, 8303100227.

8303110130 Requests exemption from certain 10CFR50, App R requirements to install automatic fire suppression sys in main control room & intake structure. Control room area continuously manned & has low fire load installation capability.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/04. CLARK, R. A. Operating Reactors Branch 3. 5pp. 17517:314. 24X
Fiche: 50-317, 83/03/04, 8303110130.

8303300065 Responds to 821230 ltr transmitting security plan changes. Changes consistent w/provisions of 10CFR50.54(P) & do not decrease effectiveness of plan. Encl to ltrs withheld (ref 10CFR73.21).
CLARK, R. A. Operating Reactors Branch 3. 83/03/14. LUNDVALL, A. E. Baltimore Gas & Electric Co. 2pp. 17751:065. 24X
Fiche: 50-317, 83/03/14, 8303300065.

8303220446 Forwards exemption granting extension to deadline for implementation of emergency lighting sys per App R to 10CFR50.
EISENHUT, D. G. Division of Licensing. 83/03/15. LUNDVALL, A. E. Baltimore Gas & Electric Co. 3pp. 17670:059. 24X
Fiche: 50-317, 83/03/15, 8303220446.

--8303220450 Exemption from schedular requirements of 10CF50.48 re installation of emergency lighting sys. Deadline extended to 830901.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 83/03/15. Baltimore Gas & Electric Co. 4pp. 17670:061. 24X
Fiche: 50-317, 83/03/15, 8303220446.

8303220015 Forwards revs to security & safeguards contingency plans. Revs withheld (ref 10CFR73.21).
BOWMAKER, N. J. Baltimore Gas & Electric Co. 83/03/16. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17652:109. 24X
Fiche: 50-317, 83/03/16, 8303220015.

8303240377 Provides addl info to clarify 830303 request for exemption from schedular requirements of 10CFR50, App R. Mods w/ exception of flux monitoring & emergency lighting, specifically discussed in interactive cable analyses.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/17. CLARK, R. A. Operating Reactors Branch 3. 3pp. 17679:075. 24X
Fiche: 50-317, 83/03/17, 8303240377.

8303280357 Advises that Region I must be notified in 60 days if util plans to continue practice of designating company personnel holding high-level positions as regular site employees to fulfill physical search requirements.
CLARK, R. A. Operating Reactors Branch 3. 83/02/17. LUNDVALL, A. E. Baltimore Gas & Electric Co. 2pp. 17726:304. 24X
Fiche: 50-317, 83/03/17, 8303280357.

8303300770 Releases public version of rrvised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/25. Document Management Branch. 1p. 17765:212. 24X Fiche: 50-317, 83/03/25, 8303300770.

--8303300774 Forwards public version of revised emergency plan implementing procedures, including Procedures ERPIP 4.1.25 re environ svcs, ERPIP 4.1.26 re environ monitoring team & ERPIP 4.5.6 re offsite protective actions.
* Baltimore Gas & Electric Co. 83/03/21. CLARK, R. A. Division of Licensing. 1p. 17765:213. 24X Fiche: 50-317, 83/03/25, 8303300770.

--8303300777 Public version of revised emergency plan implementing procedures, including Procedures ERPIP 4.1.25 re environ svcs, ERPIP 4.1.26 re environ monitoring team & ERPIP 4.5.6 re offsite protective actions.
* Baltimore Gas & Electric Co. 83/02/09. 29pp. 17765:215. 24X
Fiche: 50-317, 83/03/25, 8303300770.

J. Insurance & indemnity information

8303290370 Forwards Endorsements 52 & 21 to NELIA Policies NF-216 & NS-348, respectively.
YORK, W. G. Baltimore Gas & Electric Co. 83/03/23. DINITZ, I. Assistant Director for State & Licensee Relations. 3pp. 17716:198. 24X Fiche: 50-317, 83/03/23, 8303290370.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303020035 Application to amend Licenses DPR-53 & DPR-69, requesting schedular relief from emergency lighting requirements per App R, as described. Class I & III amend fees encl.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/02/23. CLARK, R. A. Operating Reactors Branch 3. 4pp. 17352:189. 24X
Fiche: 50-317, 83/02/23, 8303020035.

8303040328 Responds to 830104 ltr re qualification of shift technical advisors. Shift technical advisor candidates, w/exception of four individuals listed in 830104 ltr, must have bachelor degree or equivalent in scientific/engineering discipline.
CLARK, R. A. Operating Reactors Branch 3. 83/02/23. LUNDVALL, A. E. Baltimore Gas & Electric Co. 3pp. 17426:285. 24X
Fiche: 50-317, 83/02/23, 8303040328.

8303010528 Application for amend to Licenses DPR-53 & DPR-69, changing Tech Specs re RCS, containment sys, plant sys & electrical power sys.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/02/24. CLARK, R. A. Operating Reactors Branch 3. 7pp. 17342:261. 24X
Fiche: 50-317, 83/02/24, 8303010528.

--8303010536 Proposed Tech Specs re RCS, containment sys, plant sys & electrical power sys.
* Baltimore Gas & Electric Co. 83/02/24. 101pp. 17342:268. 24X
Fiche: 50-317, 83/02/24, 8303010528.

8303090424 Forwards Amends 81 & 64 to Licenses DPR-53 & DPR-69, respectively & notice of issuance & availability. Amends incorporate most recent revs to physical security plan.
CLARK, R. A. Operating Reactors Branch 3. 83/02/24. LUNDVALL, A. E. Baltimore Gas & Electric Co. 3pp. 17484:070. 24X
Fiche: 50-317, 83/02/24, 8303090424.

--8303090434 Amends 81 & 64 to Licenses DPR-53 & DPR-69, respectively, incorporating most recent revs to physical security plan.
CLARK, R. A. Operating Reactors Branch 3. 83/02/24. 4pp. 17484:074. 24X Fiche: 50-317, 83/02/24, 8303090424.

--8303090447 Notice of issuance & availability of Amends 81 & 64 to Licenses DPR-53 & DPR-69, respectively.
CLARK, R. A. Operating Reactors Branch 3. 83/02/24. 2pp. 17484:078. 24X Fiche: 50-317, 83/02/24, 8303090424.

8303090217 Assures that requirements of NUREG-0737, Item II.D.1, "PORV Block Valve Testing," satisfied. Valve functional adequacy demonstrated by tests of similar valves conducted by EPRI.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/01. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17472:349. 24X
Fiche: 50-317, 83/03/01, 8303090217.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303100266 Clarifies various aspects of design & operation of RCS vents, in response to NUREG-0737, Item II.B.1.
OLSON, R. C. Baltimore Gas & Electric Co. 83/03/07. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17489:179. 24X
Fiche: 50-317, 83/03/07, 8303100266.

8303150387 Informs that info re NUREG-0737, Action Item II.D.1, "Performance Testing of Safety & Relief Valves," will be submitted no later than Sept 1983 for Unit 1 & Feb 1984 for Unit 2, per 821116 ltr.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/09. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17562:018. 24X
Fiche: 50-317, 83/03/09, 8303150387.

8303170274 Describes current status of inadequate core cooling instrumentation sys & schedule for submittal of remaining info, per Generic Ltr 82-28 for NUREG-0737, Item II.F.2. Delay due to installation of reactor coolant tracking sys.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/10. CLARK, R. A. Operating Reactors Branch 3. 3pp. 17606:054. 24X
Fiche: 50-317, 83/03/10, 8303170274.

8303230068 Summary of 830224 meeting w/util re recent problems w/ESF actuation sys. Util contends that problem was properly diagnosed as inverter problem & that mods made. Agenda & viewgraphs encl.
JAFFE, D. H. Operating Reactors Branch 3. 83/03/10. Operating Reactors Branch 3. 25pp. 17688:080. 24X Fiche: 50-317, 83/03/10, 8303230068.

8303170056 Forwards response to 830111 ltr requesting info re TMI Action Items II.F.1.4, 5 & 6 concerning post-implementation review of containment pressure, water level & hydrogen monitors.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/14. CLARK, R. A. Operating Reactors Branch 3. 9pp. 17608:315. 24X
Fiche: 50-317, 83/03/14, 8303170056.

8303290300 Application for amend to Licenses DPR-53 & DPR-69, replacing Tech Spec Pp 3/4 1-19, 3/4 1-22 & B 3/4 1-4 re reactivity control sys.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/15. CLARK, R. A. Operating Reactors Branch 3. 5pp. 17716:181. 24X
Fiche: 50-317, 83/03/15, 8303290300.

--8303290304 Proposed Tech Spec Pp 3/4 1-19,3/4 1-22 & B 3/4 1-4 re reactivity control sys.
* Baltimore Gas & Electric Co 83/03/15 6pp 17716:186 24X
Fiche: 50-317, 83/03/15, 8303290300

8303300110 Forwards order confirming util commitment to implement post-TMI items in NUREG-0737 & in responses to Generic Ltrs 82-05 & 82-10.
CLARK, R. A. Operating Reactors Branch 3 83/03/16 LUNDVALL, A. E.
Baltimore Gas & Electric Co 3pp 17749:256 24X
Fiche: 50-317, 83/03/16, 8303300110

--8303300118 Order confirming util commitment to implement post-TMI items in NUREG-0737 & in responses to Generic Ltrs 82-05 & 82-10.
PURPLE, R. A. Division of Licensing 83/03/16 Baltimore Gas & Electric Co. 9pp 17749:259 24X Fiche: 50-317, 83/03/16, 8303300110

Q. Inspection reports, IE Bulletins & correspondence

8303030246 Forwards IE Safeguards Insp Repts 50-317/82-28 & 50-318/82-24 on 821101-05 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs 82/02/16
BOWMAKER, N. J. Baltimore Gas & Electric Co. 2pp 17410:342 24X
Fiche: 50-317, 83/02/16, 8303030246

--8303030254 Notice of violation from insp on 821101-05 Safeguards info deleted (ref 10CFR73.21).
* Division of Engineering & Technical Programs 83/02/16 2pp
17410:344 24X Fiche: 50-317, 83/02/16, 8303030246

--8303030268 IE Safeguards Insp Repts 50-317/82-28 & 50-318/82-24 on 821101-05 Noncompliance noted: failure to maintain isolation zone & apply compensatory measures per security plan requirements Safeguards info deleted (ref 10CFR73.21).
MCKEOWN, L. M., DUNLAP, J. M., GODY, A. T. Division of Engineering & Technical Programs 82/02/15 6pp 17410:346 24X
Fiche: 50-317, 83/02/16, 8303030246

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc.
11lpp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367

8303100227 Forwards IE Insp Repts 50-317/83-02 & 50-318/83-02 on 830111-0215. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs 83/02/25
LUNDVALL, A. E. Baltimore Gas & Electric Co. 2pp 17489:235 24X
Fiche: 50-317, 83/02/25, 8303100227

--8303100243 IE Insp Repts 50-317/83-02 & 50-318/83-02 on 830111-0215. No noncompliance noted. Major areas inspected: control room, accessible parts of plant structures, operations, radiation protection, physical security & radwaste releases.
ARCHITZEL, R. E., TRIMBLE, D. C. Region 1, Office of Director
MCCABE, E. C. Division of Project & Resident Programs 83/02/23
29pp 17489:237 24X Fiche: 50-317, 83/02/25, 8303100227

8303110308 Forwards "Calvert Cliffs Unit 1 Eddy Current Insp of Steam Generators 11 & 12" & "Calvert Cliffs Units 2 Eddy Current Insp of Steam Generators 21 & 22," per Tech Spec 4.4.5.5. Insp results discussed. List of tubes examined encl.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/02/25 HAYNES, R. C.
Region 1, Office of Director 6pp 17518:121 24X
Fiche: 50-317, 83/02/25, 8303110308

--8303110317 "Calvert Cliffs Unit 2 Eddy Current Insp of Steam Generators 21 & 22," Final rept.
GRAY, W. A., BEIERS, T. S. Zetec, Inc. 82/12/31 118pp 17518:223
24X Fiche: 50-317, 83/02/25, 8303110308

8303090063 Responds to IE Bulletin 82-04 re Bunker Ramo Co electrical penetrations. All Bunker Ramo electrical penetrations utilizing header design replaced w/Conax Corp penetrations.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/01 HAYNES, R. C.
Region 1, Office of Director 2pp 17467:018 24X
Fiche: 50-317, 83/03/01, 8303090063

8303090277 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." No Westinghouse DB-50 breakers used at facilities.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/03 DEYOUNG, R. C.
Director's Office, Office of Inspection and Enforcement 2pp
17473:335 24X Fiche: 50-317, 83/03/03, 8303090277

8303110295 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." No Westinghouse DB type breakers employed at facilities.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/03 HAYNES, R. C.
Region 1, Office of Director 2pp 17520:076 24X
Fiche: 50-317, 83/03/03, 8303110295

8303160558 Forwards IE Insp Repts 50-317/83-01 & 50-318/83-01 on 830117-21 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs 83/03/03
LUNDVALL, A. E. Baltimore Gas & Electric Co. 2pp 17587:269 24X
Fiche: 50-317, 83/03/03, 8303160558

--8303160564 Notice of violation from insp on 830117-21.
* Region 1, Office of Director 83/03/03 1p 17587:271 24X
Fiche: 50-317, 83/03/03, 8303160558

--8303160570 IE Insp Repts 50-317/83-01 & 50-318/83-01 on 830117-21. Noncompliance noted: failure to establish adequate procedures for respiratory protective equipment.
MCBRIDE, M. H., SHANBAKY, M. Region 1, Office of Director 83/02/28
7pp 17587:272 24X Fiche: 50-317, 83/03/03, 8303160558

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc.
117pp 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche: 50-000, 83/03/18, 8212060383

8303220341 Forwards computer printouts supplementing 830210 response to NRC 821216 SER re environ qualification of safety-related equipment per IE Bulletin 79-01B.
LUNDVALL, A. E. Baltimore Gas & Electric Co. 83/03/18 CLARK, R. A.
Operating Reactors Branch 3 286pp 17648:036 24X
Fiche: 50-317, 83/03/18, 8303220341

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387

R. Periodic operating reports & related correspondence

8303100363 Forwards "Number of Personnel & Man-Rem by Work & Lab Function for 1982."
TIERMAN, J. A. Baltimore Gas & Electric Co. 83/03/01 HAYNES, R. C.
Region 1, Office of Director 1p 17490:332 24X
Fiche: 50-317, 83/03/01, 8303100363

--8303100365 "Number of Personnel & Man-Rem by Work & Job Function, 1982."
* Baltimore Gas & Electric Co. 83/03/01 2pp 17490:333 24X
Fiche: 50-317, 83/03/01, 8303100363

8303220022 Forwards monthly operating repts for Feb 1983.
LOTITO, E. M. Baltimore Gas & Electric Co. 83/03/16 Director's Office, Office of Inspection and Enforcement 1p 17652:132 24X
Fiche: 50-317, 83/03/16, 8303220022

--8303220026 Monthly operating repts for Feb 1983.
LOTITO, E. Baltimore Gas & Electric Co. 83/03/15 11pp
17652:133 24X Fiche: 50-317, 83/03/16, 8303220022

S. Reportable occurrences, LERs & related correspondence

8303030673 Forwards NPDES noncompliance notification.
RUSSELL, L. B. Baltimore Gas & Electric Co. 83/02/15 HAYNES, R. C.
Region 1, Office of Director 1p 17411:001 24X
Fiche: 50-318, 83/02/15, 8303030673

--8303030681 NPDES noncompliance notification on 830211, temp increased across condensers for outfall 001 Caused by restricted cooling water flow due to greases & other debris broken loose by severe weather. Debris removed.
RUSSELL, L. B. Baltimore Gas & Electric Co. 83/02/15 Maryland, State of 1p 17411:002 24X Fiche: 50-318, 83/02/15, 8303030673

8303010387 Forwards LER 83-006/03L-0.
RUSSELL, L. B. Baltimore Gas & Electric Co. 83/02/18 HAYNES, R. C.
Region 1, Office of Director 1p 17343:196 24X
Fiche: 50-318, 83/02/18, 8303010387

--8303010393 LER 83-006/03L-0 on 830123, auxiliary feedwater actuating sys channel ZD for steam generator 21 level indicated low. Caused by failure of level transmitter 2-LT-1114A due to defective zero adjustment potentiometer. Transmitter replaced. LAGIEWSKI, J. S. ; RAYNOR, J. W. Baltimore Gas & Electric Co. 83/02/18 Region 1, Office of Director 1p 17343:197 24X Fiche: 50-318, 83/02/18, 8303010387.

8303010521 Forwards followup LER 83-007/01T-0. RUSSELL, L. B. Baltimore Gas & Electric Co. 83/02/18. HAYNES, R. C. Region 1, Office of Director. 1p. 17337:268. 24X Fiche: 50-318, 83/02/18, 8303010521.

--8303010542 Followup LER 83-007/01T-0 on 830203, de-energization of reactor protection sys (RPS) channels caused PORV & pressurizer quench tank rupture disk to open. Caused by blown fuse in RPS channel A due to crossed leads in inverter 21. JUNGE, M. A. Baltimore Gas & Electric Co. 83/02/18. Region 1, Office of Director. 2pp. 17337:269. 24X Fiche: 50-318, 83/02/18, 8303010521.

8303160145 Forwards LER 83-008/03L-0. RUSSELL, L. B. Baltimore Gas & Electric Co. 83/03/02. HAYNES, R. C. Region 1, Office of Director. 1p. 17597:075. 24X Fiche: 50-318, 83/03/02, 8303160145.

--8303160153 LER 83-008/03L-0 on 830131, containment spray header 21 isolation valve CV-4150 found to stroke only partially, rendering containment spray header 21 inoperable. Caused by improper adjustment of spring adjuster. Adjustment corrected. LAGIEWSKI, J. S. ; CELLARS, K. B. Baltimore Gas & Electric Co. 83/03/02. Region 1, Office of Director. 2pp. 17597:076. 24X Fiche: 50-318, 83/03/02, 8303160145.

8303160312 Forwards LER 83-014/03L-0. RUSSELL, L. B. Baltimore Gas & Electric Co. 83/03/02. HAYNES, R. C. Region 1, Office of Director. 1p. 17596:021. 24X Fiche: 50-318, 83/03/02, 8303160312.

--8303160324 LER 83-014/03L-0 on 830131, pressurizer level decreased to 120 inches while loading main turbine & to 127 inches on 830204 due to excessive feeding of steam generators while shifting steam generator feed pump steam supply. JUNGE, M. A. Baltimore Gas & Electric Co. 83/03/02. Region 1, Office of Director. 2pp. 17596:022. 24X Fiche: 50-318, 83/03/02, 8303160312.

8303160255 Forwards LER 83-013/03L-0. RUSSELL, L. B. Baltimore Gas & Electric Co. 83/03/03. HAYNES, R. C. Region 1, Office of Director. 1p. 17596:331. 24X Fiche: 50-318, 83/03/03, 8303160255.

--8303160265 LER 83-013/03L-0 on 830203, during testing of inverter 22, emergency diesel generator 21 failed to start. Cause not determined. Diesel operation will be closely monitored during ESF actuation sys. Update expected if failure revealed. WENDERLICH, R. L. ; BASSO, L. F. Baltimore Gas & Electric Co. 83/03/03. Region 1, Office of Director. 1p. 17596:332. 24X Fiche: 50-318, 83/03/03, 8303160255.

8303160410 Forwards LER 83-011/03L-0. RUSSELL, L. B. Baltimore Gas & Electric Co. 83/03/03. HAYNES, R. C. Region 1, Office of Director. 1p. 17592:339. 24X Fiche: 50-318, 83/03/03, 8303160410.

--8303160411 LER 83-011/03L-0 on 830207, during surveillance testing, ESF actuation sys A logic sequencer failed, rendering diesel generator 12 out of svc. Cause undetermined. Sequential blocking module replaced. LAGIEWSKI, J. S. ; BASSO, L. F. Baltimore Gas & Electric Co. 83/03/03. Region 1, Office of Director. 1p. 17592:340. 24X Fiche: 50-318, 83/03/03, 8303160410.

8303160176 Forwards updated LER 83-004/03X-1. RUSSELL, L. B. Baltimore Gas & Electric Co. 83/03/07. HAYNES, R. C. Region 1, Office of Director. 1p. 17596:282. 24X Fiche: 50-318, 83/03/07, 8303160176.

--8303160184 Updated LER 83-004/03X-1: 830112, auxiliary feedwater pump could not deliver flow to steam generators. Caused by leaking seal oil ring replacement resulting in improperly adjusted turbine governor. PAVIS, G. S. ; FARRELL, E. V. Baltimore Gas & Electric Co. 83/03/07. Region 1, Office of Director. 2pp. 17596:283. 24X Fiche: 50-318, 83/03/07, 8303160176.

8303210702 Forwards LER 83-010/03L-0. RUSSELL, L. B. Baltimore Gas & Electric Co. 83/03/10. HAYNES, R. C. Region 1, Office of Director. 1p. 17635:086. 24X Fiche: 50-318, 83/03/10, 8303210702.

--8303210715 LER 83-010/03L-0 on 830208, during surveillance testing, auxiliary feedwater actuating sys channel ZF setpoint found out of spec. Investigation found converter 2-E/I-1023C out of calibr, zero & span. Cause unknown. Converter recalibr. LAGIEWSKI, J. S. ; BUSSO, L. F. Baltimore Gas & Electric Co. 83/03/10. Region 1, Office of Director. 1p. 17635:087. 24X Fiche: 50-318, 83/03/10, 8303210702.

8303210570 Forwards LER 83-012/03L-0. RUSSELL, L. B. Baltimore Gas & Electric Co. 83/03/11. HAYNES, R. C. Region 1, Office of Director. 1p. 17632:298. 24X Fiche: 50-318, 83/03/11, 8303210570.

--8303210577 LER 83-012/03L-0 on 830211 & 0306, dose equivalent I-131 exceeded 1.0 mCi/g. Caused by iodine spiking due to small number of leaking fuel pins & change in power level. Frequency of sampling increased until levels decreased. JUNGE, M. A. Baltimore Gas & Electric Co. 83/03/11. Region 1, Office of Director. 6pp. 17632:299. 24X Fiche: 50-318, 83/03/11, 8303210570.

8303290078 Forwards AEOD/E304, "Investigation of Backflow Protection in Common Equipment & Floor Drain Sys to Prevent Flooding of Vital Equipment in Safety-Related Compartments," AEOD engineering evaluation rept. HELTEMES, C. J. Director's Office. 83/03/11. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17729:260. 24X Fiche: 50-317, 83/03/11, 8303290078.

--8303290088 "Investigation of Backflow Protection in Common Equipment & Floor Drain Sys to Prevent Flooding of Vital Equipment in Safety-Related Compartments," AEOD engineering evaluation rept. * Director's Office. 83/03/11. 6pp. 17729:261. 24X Fiche: 50-317, 83/03/11, 8303290078.

8303290097 Forwards AEOD/E304, "Investigation of Backflow Protection in Common Equipment & Floor Drain Sys to Prevent Flooding of Vital Equipment in Safety-Related Compartments," AEOD engineering evaluation rept. CINTULA, T. C. Reactor Operations Analysis Branch. 83/03/11. SEYFRIT, K. V. Reactor Operations Analysis Branch. 1p. 17729:225. 24X Fiche: 50-317, 83/03/11, 8303290097.

8303290109 Forwards AEOD/E304, "Investigation of Backflow Protection in Common Equipment & Floor Drain Sys to Prevent Flooding of Vital Equipment in Safety-Related Compartments," AEOD engineering evaluation rept. HELTEMES, C. J. Director's Office. 83/03/11. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 1p. 17729:181 24X Fiche: 50-317, 83/03/11, 8303290109.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8303030198 Forwards IE Insp Rept 50-320/83-01 on 830110-14. No noncompliance noted. MARTIN, T. T. Division of Engineering & Technical Programs. 83/02/18. KANGA, B. K. General Public Utilities - GPU Service Corp. 2pp. 17414:021. 24X Fiche: 50-320, 83/02/18, 8303030198.

--8303030206 IE Insp Rept 50-320/83-01 on 830110-14. No noncompliance noted. Major areas inspected: site orientation, security plan & implementing procedures, security organization, records & repts, testing & maint, physical barriers & access control. SMITH, G. C. ; BAILEY, R. J. ; KUSHNER, W. L. Region 1, Office of Director. 83/02/17. 6pp. 17414:023. 24X Fiche: 50-320, 83/02/18, 8303030198.

8303090561 Releases public version of revised emergency plan implementing procedures. FELTON, J. M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17479:355. 24X Fiche: 50-320, 83/03/02, 8303090561.

--8303090566 Forwards public version of revised Emergency Plan Implementing Procedures 1054.33 re handling high activity reactor coolant samples & 1054.18 re search & rescue. Receipt form encl.
SHAVER, L. General Public Utilities - GPU Service Corp. 83/02/01.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p.
17479:356. 24X Fiche: 50-320, 83/03/02, 8303090561.

--8303090572 Public version of revised Emergency Plan Implementing Procedures 1054.33 re handling high activity reactor coolant samples & 1054.18 re search & rescue.
* General Public Utilities - GPU Service Corp. 83/01/28. 18pp.
17479:357. 24X Fiche: 50-320, 83/03/02, 8303090561.

8303290615 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/23. Document Management Branch. 1p. 17745:027. 24X Fiche: 50-320, 83/03/23, 8303290515.

--8303290624 Forwards public version of Rev 6 to Emergency Plan Implementing Procedure 1054.6, "Addl Assistance & Notification."
SHAVER, L. General Public Utilities - GPU Service Corp. 83/03/07.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p.
17745:028. 24X Fiche: 50-320, 83/03/23, 8303290615.

--8303290628 Public version of Rev 6 to Emergency Plan Implementing Procedure 1054.6, "Addl Assistance & Notification."
* General Public Utilities - GPU Service Corp. 83/03/03. 21pp.
17745:029. 24X Fiche: 50-320, 83/03/23, 8303290615.

## Q. Adjudicatory correspondence

8303020063 Response opposing util motion to strike C Kepford supplemental affidavit re qualifications as expert witness. Intervenors unable to respond in detail since motion never received. Certificate of Svc encl.
JOHNSRUD, J. H. Environmental Coalition on Nuclear Power. 83/02/24. Commissioners. 2pp. 17352:136. 24X Fiche: 50-000, 83/02/24, 8303020063.

8303170503 Order granting NRC, licensee & WA Lochstet joint motion, approving stipulation settling Lochstet contentions. Lochstet is dismissed from proceeding. Proposed Tech Spec 3.3.1.1 to be modified.
WOLF, J. F., PARIS, O. H., SHON, F. J. Atomic Safety and Licensing Board Panel. 83/03/14. 17pp. 17610:280. 24X Fiche: 50-320, 83/03/14, 8303170503.

8303290391 Forwards affidavit of RD Parks re safety-related mods to equipment components w/o full power engineering & approval, QA violations through issuance of test & administrative procedures & use of polar crane w/o safety tests.
DEVINE, T. Government Accountability Project. 83/03/23.
PALLADINO, N. J. Commissioners. 2pp. 17725:213. 24X Fiche: 50-320, 83/03/23, 8303290391.

--8303290396 Affidavit of RD Parks re alleged safety-related mods to equipment components & QA violations through issuance of test & administrative procedures w/o full power engineering & approval & use of polar crane w/o safety tests.
PARKS, R. D. Government Accountability Project. PARKS, R. D. Bechtel Corp. 83/03/21. 57pp. 17725:215. 24X Fiche: 50-320, 83/03/23, 8303290391.

8303300335 Forwards "Rept of Review of B&W - GPU Lawsuit Trial Court Record," in response to Commission 821229 request. Trial court record does not contain info affecting NRC understanding of accident or restart decision.
DIRCKS, W. J. Office of the Executive Director for Operations. 83/03/28. PALLADINO, N. J., GILINSKY, V., AHEARNE, J. Commissioners. 1p. 17734:301. 24X Fiche: 50-320, 83/03/28, 8303300335.

--8303300338 "Rept of Review of B&W - GPU Lawsuit Trial Court Record."
* NRC - No Detailed Affiliation Given. 83/03/28. 28pp.
17734:302. 24X Fiche: 50-320, 83/03/28, 8303300335.

## J. Insurance & indemnity information

8303150418 Forwards Endorsements 1 & 2 to NELIA Binders N-56 & N-65 & MAELU Binder M-56, respectively.
GERETY, H. F. General Public Utilities - GPU Service Corp. 83/03/07.
SALTZMAN, J. Antitrust & Economic analysis Branch (Utility Finance). 37pp. 17561:201. 24X Fiche: 50-289, 83/03/07, 8303150418.

8303180360 Forwards Endorsement 55 to MAELU Policy MF-73 & Endorsement 63 to NELIA Policy NF-220.
GERETY, H. F. General Public Utilities - GPU Service Corp. 83/03/07.
SALTZMAN, J. Assistant Director for State & Licensee Relations. 3pp.
17620:074. 24X Fiche: 50-289, 83/03/07, 8303180360.

8303220089 Forwards Endorsements 56 & 57 to MAELU Policy MF-73.
GERETY, H. F. General Public Utilities - GPU Service Corp. 83/03/16.
SALTZMAN, J. Antitrust & Economic analysis Branch (Utility Finance). 3pp. 17649:286. 24X Fiche: 50-289, 83/03/16, 8303220089.

## P. Operating license stage documents & correspondence

8303280341 Notification of contract execution, Mod 4 to "Reanalysis of Existing Data From Telephone Surveys Concerning TMI." Contractor: PA State Univ.
FIELDS, J. A. Technical Assistance Contracts Branch. NRC-03-82-123. 83/01/03. VOLLMER, R. H. Division of Engineering. REGAN, W. NRC - No Detailed Affiliation Given. 1p. 17713:103. 24X Fiche: 50-289, 83/01/03, 8303280341.

--8303280346 Mod 4, revising address for submitting invoices & incorporating revised Manual Chapter 3202, to "Reanalysis of Existing Data From Telephone Surveys Concerning TMI."
FULGINITI, S. A. Pennsylvania State Univ. HAGAN, T. F. Division of Contracts. 83/01/03. 1p. 17713:104. 24X Fiche: 50-289, 83/01/03, 8303280341.

8303010728 Notifies that 830214 proposed plan for draining RCS to 328-ft elevation & lowering ion chamber into reactor vessel acceptable since safety-related issues re venting combustible gases into reactor bldg already addressed.
BARRETT, L. H. TMI Program Office. 83/02/15. KANGA, B. K. General Public Utilities - GPU Service Corp. 1p. 17347:361. 24X Fiche: 50-320, 83/02/15, 8303010728.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303020028 Advises that makeup & purification demineralizer resin sampling scheduled to commence on 830228. Hydrogen generation rates insufficient to generate explosive hydrogen levels. Safety evaluation for resin sampling & inter-ofc memos encl.
KANGA, B. K. General Public Utilities - GPU Service Corp. 83/02/25.
BARRETT, L. H. TMI Program Office. 14pp. 17354:205. 24X Fiche: 50-320, 83/02/25, 8303020028.

8303030047 Notification of contract execution, Mod 1 to "Technical, Economic & Regulatory Evaluation of TMI-2 Processed Water Disposal Alternatives." Contractor: Waste Mgt Group, Inc.
SILVIS, R. M. Technical Assistance Contracts Branch. FIN B-8038. 83/02/25. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. SNYDER, B. NRC - No Detailed Affiliation Given. 1p. 17365:277. 24X Fiche: 50-320, 83/02/25, 8303030047.

--8303030223 Mod 1, deobligating funds, to "Technical, Economic & Regulatory Evaluation of TMI-2 Processed Water Disposal Alternatives."
TUITE, P. Waste Management Group, Inc. GUSTAVE, R. P. Division of Contracts. FIN B-8038. 83/02/25. 1p. 17365:278. 24X Fiche: 50-320, 83/02/25, 8303030047.

8303040402 Forwards application for amend to License DPR-73 consisting of Amend 1 to Tech Spec Change Request 40 resolving concerns re location of review & audit requirements & revising implementing procedure.
ARNOLD, R. C. General Public Utilities - GPU Service Corp. 83/02/25.
SNYDER, B. J. TMI Program Office. 1p. 17374:325. 24X Fiche: 50-320, 83/02/25, 8303040402.

--8303040410 Application for amend to License DPR-73 consisting of Amend 1 to Tech Spec Change Request 40 resolving concerns re location of review & audit requirements & revising implementing procedure.
ARNOLD, R. C. General Public Utilities - GPU Service Corp. 83/02/25. 8pp. 17374:326. 24X Fiche: 50-320, 83/02/25, 8303040402.

--8303040417 Proposed Amend 1 to Tech Spec Change Request 40 resolving concerns re location of review & audit requirements & revising implementing procedure.
* General Public Utilities - GPU Service Corp. 83/02/25. 19pp.
17374:334. 24X Fiche: 50-320, 83/02/25, 8303040402.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303160054 Approves proposed plan for collecting resin samples from both purification demineralizer vessels, per 830225 submittal.
BARRETT, L. H. TMI Program Office 83/03/02 KANGA, B. K. General Public Utilities - GPU Service Corp. 2pp. 17614:360 24X
Fiche: 50-320, 83/03/02, 8303160054

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005

8303110249 Forwards response to 830105 request for addl info re impact of Unit 2 water inleakage & water processing on Unit 1 storage capacity & justification that condensate storage tank not required for future water storage capacity.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 83/03/07
STOLZ, J. F. Operating Reactors Branch 4 2pp. 17520:063 24X
Fiche: 50-289, 83/03/07, 8303110249

8303160037 Concurs w/functional description of reactor bldg polar crane load test using main hoist sys.
SNYDER, B. J. TMI Program Office 83/03/07 KANGA, B. K. General Public Utilities - GPU Service Corp. 4pp. 17615:029 24X
Fiche: 50-320, 83/03/07, 8303160037

8303180302 Forwards "Head & Internals Handling Equipment, Design Loads & Stress Evaluation Summary" & addendum to "TMI-2 DHR Rept of Apr 1982."
KANGA, B. K. General Public Utilities - GPU Service Corp. 83/03/15
BARRETT, L. H. TMI Program Office 10pp. 17620:001 24X
Fiche: 50-320, 83/03/15, 8303180302

--8303180308 "TMI-2 Recovery Program Head & Internals Handling Equipment Design Loads & Stress Evaluation Summary."
SPARKS, J. G. Babcock & Wilcox Co. 83/02/28 7pp. 17620:011 24X
Fiche: 50-320, 83/03/15, 8303180302

--8303180313 Addendum to "TMI-2 DHR Rept of Apr 1982."
HIPP, G. A., LOSH, L. L., MILLER, E. R. Babcock & Wilcox Co. 83/03/15
34pp. 17620:018 24X Fiche: 50-320, 83/03/15, 8303180302

8303180392 Forwards "TMI-2 Core Accountability," technical plan. Plan provides basis to develop detailed procedures.
KANGA, B. K. General Public Utilities - GPU Service Corp. 83/03/15
SNYDER, B. J. TMI Program Office 2pp. 17622:288 24X
Fiche: 50-320, 83/03/15, 8303180392

--8303180397 "TMI-2 Core Accountability," technical plan.
* General Public Utilities - GPU Service Corp. 83/01/31 19pp. 17622:290 24X Fiche: 50-320, 83/03/15, 8303180392

## Q. Inspection reports, IE Bulletins & correspondence

8303030198 Forwards IE Insp Rept 50-320/83-01 on 830110-14. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs 83/02/18
KANGA, B. K. General Public Utilities - GPU Service Corp. 2pp. 17414:021 24X Fiche: 50-320, 83/02/18, 8303030198

--8303030206 IE Insp Rept 50-320/83-01 on 830110-14. No noncompliance noted. Major areas inspected: site orientation, security plan & implementing procedures, security organization, records & repts, testing & maint, physical barriers & access control.
SMITH, Q. C., BAILEY, R. J., KUSHNER, W. L. Region 1, Office of Director 83/02/17 6pp. 17414:023 24X Fiche: 50-320, 83/02/18, 8303030198

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367

8303140047 Responds to IE Bulletin 83-01 re use of Westinghouse Type DB-50 breakers w/undervoltage trip attachments in reactor protective sys. No subj breakers in use. No further action required.
KANGA, B. K. General Public Utilities - GPU Service Corp. 83/03/08
HAYNES, R. C. Region 1, Office of Director 1p. 17539:347 24X
Fiche: 50-320, 83/03/08, 8303140047

8303150270 Forwards SALP rept for Oct 1981 - Sept 1982.
HAYNES, R. C. Region 1, Office of Director 83/03/08 ARNOLD, R. C. General Public Utilities - GPU Service Corp. 4pp. 17567:166 24X
Fiche: 50-320, 83/03/08, 8303150270

--8303150279 SALP rept for Oct 1981 - Sept 1982.
* Region 1, Office of Director 82/11/15 48pp. 17567:170 24X
Fiche: 50-320, 83/03/08, 8303150270

--8303150293 Responds to NRC 821206 ltr re SALP rept. Licensee appointed contractor manager as director of facility. Entire Bechtel & util organizations integrated to provide uninterrupted communication paths.
BARTON, J. J. General Public Utilities - GPU Service Corp. 82/12/30 STAROSTECKI, R. Region 1, Office of Director 9pp. 17567:218 24X Fiche: 50-320, 83/03/08, 8303150270

--8303150301 Forwards SALP Board rept from Region I review of util activities on 821115 Meeting scheduled for 821210 to discuss assessment w/o encl.
STAROSTECKI, R. Division of Project & Resident Programs 82/12/06
KANGA, B. K. General Public Utilities - GPU Service Corp. 2pp. 17567:227 24X Fiche: 50-320, 83/03/08, 8303150270

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380

8303280169 Forwards IE Insp Rept 50-320/83-03 on 830130-0226. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs 83/03/14
KANGA, B. K. General Public Utilities - GPU Service Corp. 2pp. 17709:297 24X Fiche: 50-320, 83/03/14, 8303280169

--8303280173 IE Insp Rept 50-320/83-03 on 830130-0226. No noncompliance noted. Major areas inspected: periodic & special repts, routine plant operations, LERs, polar crane procedure & surveillance activities.
WIEBE, J., BARR, K., O'NEILL, B. Region 1, Office of Director 83/03/08 6pp. 17709:299 24X Fiche: 50-320, 83/03/14, 8303280169

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche: 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12lpp. 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387

## R. Periodic operating reports & related correspondence

8303010711 Forwards TMI Program ofc weekly status rept for wk of 830206-12.
BARRETT, L. H. TMI Program Office 83/02/14 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 10pp. 17348:308 24X
Fiche: 50-320, 83/02/14, 8303010711

8303100422 Forwards TMI Program Ofc weekly status rept for wk of 830213-18.
BARRETT, L. H. TMI Program Office 83/02/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director SNYDER, B. J. TMI Program Office 7pp. 17522:025 24X Fiche: 50-320, 83/02/18, 8303100422

8303100420 Forwards TMI Program Ofc weekly status rept for wk of 830219-26.
BARRETT, L. H. TMI Program Office 83/02/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director SNYDER, B. J. TMI Program Office 11pp. 17522:032 24X Fiche: 50-320, 83/02/28, 8303100420

8303110053 Forwards "Annual Exposure Rept, 1982."
KANGA, B. K. General Public Utilities - GPU Service Corp. 83/03/01
HAYNES, R. C. Region 1, Office of Director 1p. 17517:341 24X
Fiche: 50-320, 83/03/01, 8303110053

--8303110076 "Annual Exposure Rept, 1982." Aircraft movements at Harrisburg Intl Airport during 1982 encl.
* General Public Utilities - GPU Service Corp. 83/03/01 3pp. 17517:342 24X Fiche: 50-320, 83/03/01, 8303110053

8303170080 Forwards TMI Program Ofc weekly status rept for wk of 830228-0305.
BARRETT, L. H. TMI Program Office 83/03/07 DENTON, H. R. Office of Nuclear Reactor Regulation, Director SNYDER, B. J. TMI Program Office 7pp. 17625:113 24X Fiche: 50-320, 83/03/07, 8303170080

8303180424 Forwards "Quarterly Dose Assessment Rept - Second Quarter 1982 Semiannual Radioactive Effluent & Release Rept."
KANGA, B. K. General Public Utilities - GPU Service Corp. 83/03/07
HAYNES, R. C. Region 1, Office of Director 2pp. 17622:126 24X
Fiche: 50-320, 83/03/07, 8303180424

--8303180427 "Quarterly Dose Assessment Rept - Second Quarter 1982 Semiannual Radioactive Effluent Release Rept."
* General Public Utilities - GPU Service Corp. 83/03/07. 33pp. 17622:128. 24X Fiche:50-320,83/03/07,8303180424.

6. Reportable occurrences, LERs & related correspondence

8303250067 Forwards LER 83-003/01L-0.
KANGA,B.K. General Public Utilities - GPU Service Corp. 83/03/14.
HAYNES,R.C. Region 1, Office of Director. 1p. 17693:126. 24X Fiche:50-320,83/03/14,8303250067.

--8303250076 LER 83-003/01L-0 on 830211, while replacing selected fire barrier seals in river water pump house, firewatch tours were performed on less than hourly basis during backshifts. Caused by personnel error. Firewatch implemented on hourly basis.
CHAPLIN,S.D. General Public Utilities - GPU Service Corp. 83/03/14. Region 1, Office of Director. 2pp. 17693:127. 24X Fiche:50-320,83/03/14,8303250067.

T. Hearing transcripts on non-antitrust matters

8303290239 Transcript of 830317 affirmation/discussion & vote in Washington,DC re SECY-83-74, review of ALAB-698. Pp 1-5.
* Commissioners. 83/03/17. 7pp. 17727:207. 24X
Fiche:50-289,83/03/17,8303290239.

U. Congressional/Executive Correspondence

8303040160 Responds to 830125 ltr re NRC handling of 821223 ltr concerning news story about core damage at TMI-2 & concern over delegation of responsibility to answer Congressional ltrs. Senior NRC mgt responds to Congressional inquiries.
PALLADINO,N.J. Commissioners. 83/02/18. MARKEY,E.J. House of Rep., Interior & Insular Affairs. 1p. 17427:036. 24X
Fiche:50-320,83/02/18,8303040160.

--8303040172 Expresses concern & displeasure over handling of 821223 inquiry re news story about core damage at TMI-2 & delegation of responsibility to answer Congressional inquiries.
MARKEY,E.J. House of Rep., Interior & Insular Affairs. 83/01/25.
PALLADINO,N.J. Commissioners. 1p. 17427:037. 24X
Fiche:50-320,83/02/18,8303040160.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT,D.G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche:50-000,83/02/24,8302250505.

DOCKET 50-321 EDWIN I. HATCH NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8303020060 Forwards SER for Sections III.G.3 & III.L of App R to 10CFR50 re safe shutdown capability. Licensee conceptual design of alternative shutdown capability for control room & cable spreading room acceptable.
STOLZ,J.F. Operating Reactors Branch 4. 83/02/11. BECKHAM,J.T. Georgia Power Co. 2pp. 17359:321. 24X Fiche:50-321,83/02/11,8303020060.

--8303020062 SER accepting licensee proposed alternate safe shutdown sys for maintaining cold shutdown conditions free of fire damage.
SINGH,B.K. NRC - No Detailed Affiliation Given. 83/02/11. 10pp. 17359:323. 24X Fiche:50-321,83/02/11,8303020060.

8303090532 Releases public version of revised emergency plan implementing procedures.
FELTON,J.M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17483:123. 24X Fiche:50-321,83/03/02,8303090532.

--8303090537 Forwards public version of revised emergency plan implementing procedures, including Procedure HNP-8030 re health physics startup surveillance.
NIX,H.C. Georgia Power Co. 83/02/15. Office of Nuclear Reactor Regulation, Director. 1p. 17483:124. 24X Fiche:50-321,83/03/02,8303090532.

--8303090544 Public version of revised emergency plan implementing procedures, including Procedure HNP-8030 re health physics startup surveillance.
* Georgia Power Co. 83/01/11. 39pp. 17483:125. 24X
Fiche:50-321,83/03/02,8303090532.

8303100125 Releases public version of revised pages to emergency plan.
FELTON,J.M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17496:147. 24X Fiche:50-321,83/03/02,8303100125.

--8303100130 Forwards public version of revised pages to emergency plan. Receipt form encl.
OLLINGER,W.H. Georgia Power Co. 83/01/15. NRC - No Detailed Affiliation Given. 1p. 17496:148. 24X Fiche:50-321,83/03/02,8303100125.

--8303100132 Public version of revised pages to emergency plan.
* Georgia Power Co. 83/01/31. 16pp. 17496:149. 24X
Fiche:50-321,83/03/02,8303100125.

8303240111 Releases public version of revised emergency plan implementing procedures.
FELTON,J.M. Division of Rules and Records. 83/03/21. Document Management Branch. 1p. 17700:256. 24X Fiche:50-321,83/03/21,8303240111.

--8303240114 Forwards public version of Rev 11 to Emergency Plan Implementing Procedure HNP-8050, "Survey Frequency & Work Scheduling" & Rev 7 to HNP-8120, "Count Rate Meter PRM-4A Operation & Calibr." Receipt form encl.
NIX,H.C. Georgia Power Co. 83/03/14. Office of Nuclear Reactor Regulation, Director. 1p. 17700:257. 24X Fiche:50-321,83/03/21,8303240111.

--8303240119 Public version of Rev 11 to Emergency Plan Implementing Procedure HNP-8050, "Survey Frequency & Work Scheduling" & Rev 7 to HNP-8120, "Count Rate Meter PRM-4A Operation & Calibr."
ROGERS,W.H. Georgia Power Co. 83/03/07. 32pp. 17700:258. 24X
Fiche:50-321,83/03/21,8303240111.

8303250042 Releases public version of revised emergency plan implementing procedure.
FELTON,J.M. Division of Rules and Records. 83/03/21. Document Management Branch. 1p. 17710:116. 24X Fiche:50-321,83/03/21,8303250042.

--8303250043 Forwards public version of Rev 15 to Emergency Plan Implementing Procedure HNP-8008, "Radiation Work Permit."
NIX,H.C. Georgia Power Co. 83/03/08. Office of Nuclear Reactor Regulation, Director. 2pp. 17710:117. 24X Fiche:50-321,83/03/21,8303250042.

--8303250048 Public version of Rev 15 to Emergency Plan Implementing Procedure HNP-8008, "Radiation Work Permit."
NIX,H. Georgia Power Co. 83/02/28. 20pp. 17710:119. 24X
Fiche:50-321,83/03/21,8303250042.

8303280281 Forwards IE Safeguards Insp Repts 50-321/83-05 & 50-366/83-05 on 830222-25. No noncompliance noted.
DANCE,H.C. Division of Project & Resident Programs. 83/03/22.
KELLY,R.J. Georgia Power Co. 2pp. 17706:039. 24X
Fiche:50-321,83/03/22,8303280281.

--8303280291 IE Safeguards Insp Repts 50-321/83-05 & 50-366/83-05 on 830222-25. No noncompliance noted. Major areas inspected: site orientation & review of security plan & implementing procedures. Details withheld (ref 10CFR73.21).
HALL,B.L., MCGUIRE,D.R. Region 2, Office of Director. 83/03/17. 1p. 17706:041. 24X Fiche:50-321,83/03/22,8303280281.

8303310113 Releases public version of revised emergency plan implementing procedures.
FELTON,J.M. Division of Rules and Records. 83/03/25. Document Management Branch. 1p. 17775:273. 24X Fiche:50-321,83/03/25,8303310113.

--8303310118 Forwards public version of Rev 7 to Emergency Plan Implementing Procedure HNP-8022 re environ & personnel TLD cross-check program, Rev 1 to HNP-8143 re low vol air sampler & Rev 1 to HNP-8146 re calibr of rate meter.
NIX,H.C. Georgia Power Co. 83/02/08. Office of Nuclear Reactor Regulation, Director. 1p. 17775:274. 24X Fiche:50-321,83/03/25,8303310113.

--8303310121 Public version of Rev 7 to Emergency Plan Implementing Procedure HNP-8022 re environ & personnel TLD cross-check program, Rev 1 to HNP-8143 re low vol air sampler & Rev 1 to HNP-8146 re operation calibr of portable rate meter-scaler.
* Georgia Power Co. 83/02/09. 42pp. 17775:275. 24X
Fiche:50-321,83/03/25,8303310113.

8303310167 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 83/03/28 Document Management Branch 1p 17775:114 24X Fiche 50-321, 83/03/28, 8303310167.

--8303310174 Forwards public version of Rev 7 to Emergency Plan Implementing Procedure HNP-8020, "Plant Fume Velocity Measurement" & Rev 3 to HNP-4864, "Technical Support Ctr."
NIX, H. C. Georgia Power Co. 83/02/28 Office of Nuclear Reactor Regulation, Director 1p 17775:115 24X Fiche 50-321, 83/03/28, 8303310167.

--8303310180 Public version of Rev 7 to Emergency Plan Implementing Procedure HNP-8020, "Plant Fume Velocity Measurements" & Rev 3 to HNP-4864, "Technical Support Ctr."
ROGERS, W. H., NIX, H. Georgia Power Co. 83/02/23 33pp 17775:116 24X Fiche 50-321, 83/03/28, 8303310167.

J. Insurance & indemnity information

8303010250 Forwards Endorsements 75 & 76 & 61 & 62 to NELIA Policy NF-215 & MAELU Policy MF-78, respectively.
DUCK, J. R. Marsh & McLennan, Inc. 83/02/22 SALTZMAN, J. Assistant Director for State & Licensee Relations 5pp 17335:154 24X Fiche 50-321, 83/02/22, 8303010250.

8303290409 Forwards Endorsement 77 to NELIA Policy NF-215.
DUCK, J. R. Marsh & McLennan, Inc. 83/03/15 SALTZMAN, J. Office of State Programs, Director 2pp 17725:174 24X Fiche 50-321, 83/03/15, 8303290409.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X Fiche 50-000, 83/02/16, 8302170082.

8303040463 Documents 830124 telcon re replacement of selected portion of stainless steel 4-inch diameter reactor water cleanup return line piping.
GUCWA, L. T. Georgia Power Co. 83/02/18 STOLZ, J. F. Operating Reactors Branch 4 2pp 17373:335 24X Fiche 50-321, 83/02/18, 8303040463.

8303040237 Confirms authorization for one-time change in Tech Spec 3.7.A.5b, "Oxygen Concentration," to extend time interval from 24 h to 72 h before concentration in drywell shall be reduced to 4% after reactor placed in run mode.
LAINAS, G. C. Assistant Director for Operating Reactors 83/02/23
BECKHAM, J. T. Georgia Power Co. 4pp 17427:350 24X Fiche 50-321, 83/02/23, 8303040237.

--8303040241 Safety evaluation supporting one-time change to Tech Spec 3.7.A.5b, "Oxygen Concentration."
* Office of Nuclear Reactor Regulation, Director 83/02/22 2pp 17427:354 24X Fiche 50-321, 83/02/23, 8303040237.

8303070001 Application for amend to License NPF-5 Tech Specs, supporting installation of low-low set safety relief valve logic sys & GE analog transmitter trip sys Proprietary supporting info withheld (ref 10CFR2.790).
CAUSEY, J. C. Georgia Power Co. 83/02/23 STOLZ, J. F. Operating Reactors Branch 4 10pp 17459:112 24X Fiche 50-366, 83/02/23, 8303070001.

8303020010 Forwards, "Mark I Containment Long-Term Program Plant Unique Analysis Rept-Suppl." Rept addresses safety-relief valve discharge line drywell supports, torus attached piping & supports, valves, pumps & torus shell nozzles.
GUCWA, L. T. Georgia Power Co. 83/02/28 STOLZ, J. F. Operating Reactors Branch 4 1p 17353:181 24X Fiche 50-321, 83/02/28, 8303020010.

--8303020014 "Mark I Containment Long-Term Program Plant Unique Analysis Rept-Suppl."
* Bechtel Corp. 83/02/28 327pp 17353:182 24X Fiche 50-321, 83/02/28, 8303020010.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X Fiche 50-000, 83/02/02, 8303020321.

8303090290 Forwards Class III amend fee for immediate relief from Tech Specs re primary containment oxygen concentration requested in 830222 application for amend to License DPR-57.
GUCWA, L. T. Georgia Power Co. 83/03/02 STOLZ, J. F. Operating Reactors Branch 4 2pp 17492:152 24X Fiche 50-321, 83/03/02, 8303090290.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp 17660:176 24X Fiche 50-000, 83/03/07, 8303040005.

8303170300 Revises estimated completion date to 830701 for implementation of NUREG-0737, Item II.B.3, "Post-Accident Sampling." Grab sample analysis will be used in interim.
BECKHAM, J. T. Georgia Power Co. 83/03/11 STOLZ, J. F. Operating Reactors Branch 4 2pp 17605:129 24X Fiche 50-321, 83/03/11, 8303170300.

8303220458 Forwards Amends 94 & 31 to Licenses DPR-57 & NPF-5, respectively, & notice of issuance & availability. Amends revise ETS to delete nonradiological water quality-related requirements.
STOLZ, J. F. Operating Reactors Branch 4 83/03/11 BECKHAM, J. T. Georgia Power Co. 5pp 17670:128 24X Fiche 50-321, 83/03/11, 8303220458.

--8303220463 Amends 94 & 31 to Licenses DPR-57 & NPF-5, respectively, revising ETS to delete nonradiological water quality-related requirements.
STOLZ, J. F. Operating Reactors Branch 4 83/03/11 20pp 17670:133 24X Fiche 50-321, 83/03/11, 8303220458.

--8303220468 Notice of issuance & availability of Amends 94 & 31 to Licenses DPR-57 & NPF-5, respectively.
STOLZ, J. F. Operating Reactors Branch 4 83/03/11 2pp 17670:153 24X Fiche 50-321, 83/03/11, 8303220458.

8303210427 Forwards response to 830208 request for addl info re NUREG-0737, Items I.A.2.1, "Upgrading Reactor Operator & Senior Reactor Operator Training Qualifications" & II.B.4, "Training for Mitigating Core Damage."
BECKHAM, J. T. Georgia Power Co. 83/03/14 STOLZ, J. F. Operating Reactors Branch 4 7pp 17634:343 24X Fiche 50-321, 83/03/14, 8303210427.

8303290012 Forwards order confirming licensee commitments on post-TMI related issues, based on util responses to Generic Ltrs 82-05 & 82-10.
STOLZ, J. F. Operating Reactors Branch 4 83/03/14 BECKHAM, J. T. Georgia Power Co. 3pp 17730:030 24X Fiche 50-321, 83/03/14, 8303290012.

--8303290019 Order confirming licensee commitments to implement post-TMI related items contained in NUREG-0737.
PURPLE, R. A. Assistant Director for Licensing 83/03/14
Georgia Power Co. 10pp 17730:033 24X Fiche 50-321, 83/03/14, 8303290012.

8303310070 Forwards safety evaluations on BWR Owners Group 801001 & 1229 responses to NUREG-0737, Item II.K.3.13 re separation of HPCI & RCIC sys initiation levels & mod of RCIC sys automatic restart, respectively. Item complete.
STOLZ, J. Operating Reactors Branch 4 83/03/16 BACKHAM, J. T. Georgia Power Co. 3pp 17775:330 24X Fiche 50-321, 83/03/16, 8303310070.

8303230386 Notification of 830330 meeting w/util in Bethesda, MD to discuss appeal of denials listed in draft SER on facility exemption requests.
RIVENBARK, G. Operating Reactors Branch 4 83/03/18 STOLZ, J. F. Operating Reactors Branch 4 2pp 17675:255 24X Fiche 50-321, 83/03/18, 8303230386.

8303240124 Notification of 830331 meeting w/util in Bethesda, MD to discuss status of remaining issues re review of purging & venting during normal operations.
RIVENBARK, G. Operating Reactors Branch 4 83/03/18 STOLZ, J. F. Operating Reactors Branch 4 2pp 17698:344 24X Fiche 50-321, 83/03/18, 8303240124.

8303300507 Forwards Amend 95 to License DPR-57, safety evaluation & notice of issuance & availability. Amend permits extension of time interval from 24 h to 72 h before oxygen concentration in drywell must be reduced.
RIVENBARK, G. W. Operating Reactors Branch 4 83/03/22 BECKHAM, J. T. Georgia Power Co. 2pp 17748:271 24X Fiche 50-321, 83/03/22, 8303300507.

--8303300509 Amend 95 to License DPR-57, permitting extension of time interval from 24 h to 72 h before oxygen concentration in drywell must be reduced.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/22. 5pp.
17748:274. 24X Fiche: 50-321, 83/03/22, 8303300507.

--8303300516 Safety evaluation supporting Amend 95 to License DPR-57.
* Office of Nuclear Reactor Regulation, Director. 83/03/22. 3pp.
17748:279. 24X Fiche: 50-321, 83/03/22, 8303300507.

--8303300520 Notice of issuance & availability of Amend 95 to License DPR-57.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/22. 2pp.
17748:282. 24X Fiche: 50-321, 83/03/22, 8303300507.

9. Inspection reports, IE Bulletins & correspondence

8303100068 Responds to FOIA request for NUREG-0313, results of stress ratio index tests on welds & info re intergranular stress corrosion cracking & performance of weld overlay patches. Forwards App A documents, App B documents available in PDR.
FELTON, J. M. Division of Rules and Records. 83/02/15. VAN
ALLEN, S. E. Northern Sun Alliance. 4pp. 17494:148. 24X
Fiche: 50-000, 83/02/15, 8303100068.

--8303100102 Discusses degradation & cracking in thick-wall large diameter stainless steel piping at BWR plants per IE Bulletin 82-03 & NRR generic responsibilities. Guidelines for review of pipe crack problem listed.
DIRCKS, W. J. Office of the Executive Director for Operations. 82/12/08. Region 1, Office of Director. 4pp. 17494:326. 24X
Fiche: 50-000, 83/02/15, 8303100068.

8303010512 Ack receipt of 830202 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-321/82-41.
DANCE, H. C. Division of Project & Resident Programs. 83/02/17.
KELLY, R. J. Georgia Power Co. 1p. 17337:223. 24X
Fiche: 50-321, 83/02/17, 8303010512.

--8303010520 Responds to NRC ltr re violations noted in IE Insp Rept 50-321/82-41. Corrective actions: personnel involved in violation immediately counseled in correct method of procedure revs. Welders qualified in accordance w/procedures.
BECKHAM, J. T. Georgia Power Co. 83/02/02. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17337:224. 24X Fiche: 50-321, 83/02/17, 8303010512.

--8303010526 Forwards IE Insp Rept 50-321/82-41 on 821213-16 & notice of violation.
DANCE, H. C. Division of Project & Resident Programs. 83/01/03.
KELLY, R. J. Georgia Power Co. 2pp. 17337:226. 24X
Fiche: 50-321, 83/02/17, 8303010512.

--8303010530 Notice of violation from insp on 821213-16.
* Division of Project & Resident Programs. 83/01/03. 1p.
17337:228. 24X Fiche: 50-321, 83/02/17, 8303010512.

--8303010537 IE Insp Rept 50-321/82-41 on 821213-16. Noncompliance noted: unapproved, uncontrolled change to plant procedure HNP-6914 used for qualification of Class I pipe welders.
CROWLEY, B. R. Region 2, Office of Director. BLAKE, J. J. Division of Engineering & Radiological Safety Programs. 82/12/30. 10pp.
17337:229. 24X Fiche: 50-321, 83/02/17, 8303010512.

8303210655 Forwards IE Insp Repts 50-321/83-03 & 50-366/83-03 on 830129-0203. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/02/24.
KELLY, R. J. Georgia Power Co. 2pp. 17635:187. 24X
Fiche: 50-321, 83/02/24, 8303210655.

--8303210668 IE Insp Repts 50-321/83-03 & 50-366/83-03 on 830129-0203. No noncompliance noted. Major areas inspected: integrated leak rate test procedure review, test controls, ILRT witnessing & followup on outstanding insp items.
WHITENER, H. L., JAPE, F. Region 2, Office of Director. 83/02/23.
5pp. 17635:189. 24X Fiche: 50-321, 83/02/24, 8303210655.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc.
11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210632 Ack receipt of 830210 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/82-42 & 50-366/82-40.
LEWIS, R. C. Division of Project & Resident Programs. 83/03/02.
KELLY, R. J. Georgia Power Co. 1p. 17636:252. 24X
Fiche: 50-321, 83/03/02, 8303210632.

--8303210639 Responds to NRC 830111 ltr re violations noted in IE Insp Repts 50-321/82-42 & 50-366/82-40. Corrective actions: new QA position filled, overdue initial corrective action responses submitted & lead auditor qualification records reviewed.
GUCWA, L. T. Georgia Power Co. 83/02/10. O'REILLY, J. P. Region 2, Office of Director. 6pp. 17636:253. 24X Fiche: 50-321, 83/03/02, 8303210632.

--8303210648 Forwards IE Insp Repts 50-321/82-42 & 50-366/82-40 on 821213-15 & notice of violation.
LEWIS, R. C. Division of Project & Resident Programs. 83/01/11.
KELLY, R. J. Georgia Power Co. 2pp. 17636:259. 24X
Fiche: 50-321, 83/03/02, 8303210632.

--8303210654 Notice of violation from insp on 821213-15.
* Region 2, Office of Director. 83/01/11. 2pp. 17636:261. 24X
Fiche: 50-321, 83/03/02, 8303210632.

--8303210662 IE Insp Repts 50-321/82-42 & 50-366/82-40 on 821213-15. Noncompliance noted: failure to promptly correct items adverse to quality, to respond to audit findings within required timeframe & to update lead auditor qualifications.
BELISLE, G. A., JACKSON, L. H. Region 2, Office of Director. UPRIGHT, C. M. Division of Engineering & Radiological Safety Programs. 83/01/06. 7pp. 17636:263. 24X Fiche: 50-321, 83/03/02, 8303210632.

8303210387 Requests extension to 830310 to respond to IE Bulletin 82-04.
GUCWA, L. T. Georgia Power Co. 83/03/03. O'REILLY, J. P. Region 2, Office of Director. 1p. 17634:174. 24X Fiche: 50-321, 83/03/03, 8303210387.

8303210361 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Bunker-Ramo penetration assemblies not used at facilities.
BECKHAM, J. T. Georgia Power Co. 83/03/10. O'REILLY, J. P. Region 2, Office of Director. 1p. 17635:010. 24X Fiche: 50-321, 83/03/10, 8303210361.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc.
117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303210458 Ack receipt of 830126 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-321/82-38 & 50-366/82-36.
LEWIS, R. C. Division of Project & Resident Programs. 83/03/11.
KELLY, R. J. Georgia Power Co. 2pp. 17631:271. 24X
Fiche: 50-321, 83/03/11, 8303210458.

--8303210464 Responds to NRC 821221 ltr re violation noted in IE Insp Repts 50-321/82-38 & 50-366/82-36. Corrective actions: qualifications of personnel conducting Type C leak tests, per HNP-1-3952-E, reviewed & found acceptable.
GUCWA, L. T. Georgia Power Co. 83/01/26. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17631:273. 24X Fiche: 50-321, 83/03/11, 8303210458.

--8303210472 Forwards IE Insp Repts 50-321/82-38 & 50-366/82-36 on 821116-19 & notice of violation.
LEWIS, R. C. Division of Project & Resident Programs. 82/12/21.
KELLY, R. J. Georgia Power Co. 2pp. 17631:275. 24X
Fiche: 50-321, 83/03/11, 8303210458.

--8303210478 Notice of violation from insp on 821116-19.
* Region 2, Office of Director. 82/12/21. 1p. 17631:277. 24X
Fiche: 50-321, 83/03/11, 8303210458.

--8303210487 IE Insp Repts 50-321/82-38 & 50-366/82-36 on 821116-19. Noncompliance noted: HNP-1-3952-E, Rev 13, did not identify all valve positions associated w/Type C leak rate tests.
WHITENER, H. L., JAPE, F. Division of Engineering & Radiological Safety Programs. 82/12/17. 4pp.
17631:278. 24X Fiche: 50-321, 83/03/11, 8303210458.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 12lpp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303280281 Forwards IE Safeguards Insp Repts 50-321/83-05 & 50-366/83-05 on 830222-25 No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs 83/03/22
KELLY, R. J. Georgia Power Co. 2pp 17706:039 24X
Fiche: 50-321, 83/03/22, 8303280281.

--8303280291 IE Safeguards Insp Repts 50-321/83-05 & 50-366/83-05 on 830222-25 No noncompliance noted Major areas inspected: site orientation & review of security plan & implementing procedures. Details withheld (ref 10CFR73.21).
HALL, B. L. ; MCGUIRE, D. R. Region 2, Office of Director 83/03/17
1p 17706:041 24X Fiche: 50-321, 83/03/22, 8303280291.

R Periodic operating reports & related correspondence

8303090360 Forwards "Semiannual Rept for Plant Radioactive Effluent Releases, Jan-June 1981."
MANRY, M. Georgia Power Co. 81/08/25 O'REILLY, J. P. Region 2, Atlanta, Office of the Director (81/03/01) 1p 17470:153 24X
Fiche: 50-321, 81/08/25, 8303090360.

--8303090363 Forwards "Semiannual Rept for Plant Radioactive Effluent Releases, Jan-June 1981."
MANRY, M. Georgia Power Co. 81/08/25 Director's Office, Office of Inspection and Enforcement 1p 17470:154 24X
Fiche: 50-321, 81/08/25, 8303090360.

--8303090368 "Semiannual Rept for Plant Radioactive Effluent Releases, Jan-June 1981."
* Georgia Power Co. 81/08/25 43pp 17470:155 24X
Fiche: 50-321, 81/08/25, 8303090360.

8303090188 Forwards "Semiannual Rept: Plant Radioactive Effluent Releases, Jul-Dec 1981."
MANRY, M. Georgia Power Co. 82/02/25 O'REILLY, J. P. Region 2, Office of Director 1p 17472:302 24X Fiche: 50-321, 82/02/25, 8303090188.

8303030213 Forwards "Semiannual Rept Plant Radioactive Effluent Releases, Jul-Dec 1982."
NIX, H. C. Georgia Power Co. 83/02/23 Director's Office, Office of Inspection and Enforcement 1p 17411:283 24X
Fiche: 50-321, 83/02/23, 8303030213.

--8303030220 Forwards "Semiannual Rept: Plant Radioactive Effluent Releases, Jul-Dec 1982."
NIX, H. C. Georgia Power Co. 83/02/23 O'REILLY, J. P. Region 2, Office of Director 1p 17411:284 24X Fiche: 50-321, 83/02/23, 8303030213.

--8303030228 "Semiannual Rept: Plant Radioactive Effluent Releases, Jul-Dec 1982."
* Georgia Power Co. 83/02/23 51pp 17411:285 24X
Fiche: 50-321, 83/02/23, 8303030213.

8303150478 Forwards monthly operating repts for Feb 1983.
NIX, H. C. Georgia Power Co. 83/03/09 Director's Office, Office of Inspection and Enforcement 1p 17568:253 24X
Fiche: 50-321, 83/03/09, 8303150478.

--8303150480 Monthly operating repts for Feb 1983.
SEWELL, S. K. Georgia Power Co. 83/03/10 44pp 17568:254 24X
Fiche: 50-321, 83/03/09, 8303150478.

8303160583 Forwards monthly operating repts for Feb 1983.
NIX, H. C. Georgia Power Co. 83/03/09 NRC - No Detailed Affiliation Given 1p 17587:022 24X Fiche: 50-321, 83/03/09, 8303160583.

--8303160588 Monthly operating repts for Feb 1983.
SEWELL, S. K. Georgia Power Co. 83/03/10 44pp 17587:023 24X
Fiche: 50-321, 83/03/09, 8303160583.

S Reportable occurrences, LERs & related correspondence

8303140453 Discusses revised corrective actions as result of LER 50-321/78-30 re failure to control issuances of LERs adequately. Plant regulatory compliance group established to track LERs w/computer sys. GA dept tracking inefficient.
GUCWA, L. T. Georgia Power Co. 83/02/21 O'REILLY, J. P. Region 2, Office of Director 1p 17541:179 24X Fiche: 50-321, 83/02/21, 8303140453.

8303080043 Forwards updated LER 82-058/03X-1.
NIX, H. C. Georgia Power Co. 83/02/22 O'REILLY, J. P. Region 2, Office of Director 1p 17436:361 24X Fiche: 50-321, 83/02/22, 8303080043.

--8303080048 Updated LER 82-058/03X-1 on 820617, during startup surveillance, hydrogen & oxygen analyzer B found out of calibr. Caused by instrument drift. Analyzer recalibr. Design change request written.
TIPPS, S. B. Georgia Power Co. 83/02/22 Region 2, Office of Director 1p 17436:362 24X Fiche: 50-321, 83/02/22, 8303080043.

8303080206 Forwards updated LER 81-136/03X-1.
NIX, H. C. Georgia Power Co. 83/02/22 O'REILLY, J. P. Region 2, Office of Director 1p 17457:100 24X Fiche: 50-321, 83/02/22, 8303080206.

--8303080214 Updated LER 81-136/03X-1 on 811215, both off-gas hydrogen analyzers found inoperable. Caused by component failure. Analyzer A found out of calibr. Analyzer A recalibr & returned to svc. Pumps replaced on analyzer B.
TIPPS, S. B. Georgia Power Co. 83/02/22 Region 2, Office of Director 2pp 17457:101 24X Fiche: 50-321, 83/02/22, 8303080206.

8303150545 Forwards LER 83-009/03L-0.
NIX, H. C. Georgia Power Co. 83/02/22 O'REILLY, J. P. Region 2, Office of Director 1p 17568:315 24X Fiche: 50-321, 83/02/22, 8303150545.

--8303150563 LER 83-009/03L-0 on 830126, while performing reactor high pressure instrument FT&C procedure, reactor pressure instrument B actuated at 164 psig, above Tech Spec limit. Caused by setpoint drift. Instrument recalibr.
TIPPS, S. B. Georgia Power Co. 83/02/22 Region 2, Office of Director 1p 17568:316 24X Fiche: 50-321, 83/02/22, 8303150545.

8303080404 RO 50-321/1983-001 on 830213, during shutdown for refueling, apprx 3,000 gallons of 21% glycol spilled on floor of offgas bldg. Caused by oversight on clearance of offgas cooler condenser relief valve. Personnel instructed.
NIX, H. C. Georgia Power Co. 83/02/23 O'REILLY, J. P. Region 2, Office of Director 2pp 17454:032 24X Fiche: 50-321, 83/02/23, 8303080404.

8303140478 RO on 830114, employee gained access to plant w/o proper badge exchange. Initially reported per 830113 deviation rept. To prevent recurrence, security officer will escort vehicle drivers to vehicle & verify proper badges.
NIX, H. C. Georgia Power Co. 83/02/24 O'REILLY, J. P. Region 2, Office of Director 2pp 17540:340 24X Fiche: 50-321, 83/02/24, 8303140478.

8303140584 Forwards LER 83-014/01T-0.
NIX, H. C. Georgia Power Co. 83/02/24 O'REILLY, J. P. Region 2, Office of Director 1p 17534:016 24X Fiche: 50-321, 83/02/24, 8303140584.

--8303140588 LER 83-014/01T-0 on 830211, during cold shutdown for refueling, piping support hanger found installed on RBCCW sys rather than plant svc water (PSW) sys. Caused by const error. New hanger installed on PSW sys.
SUMNER, H. L. Georgia Power Co. 83/02/24 Region 2, Office of Director 2pp 17534:017 24X Fiche: 50-321, 83/02/24, 8303140584.

8303150204 Forwards LER 83-017/03L-0.
NIX, H. C. Georgia Power Co. 83/02/24 O'REILLY, J. P. Region 2, Office of Director 1p 17549:042 24X Fiche: 50-321, 83/02/24, 8303150204.

--8303150214 LER 83-017/03L-0 on 830128, insp of secondary containment walls revealed breached fire barrier in 164 ft elevation reactor bldg airlock. Caused by design change which did not provide for sealing of fire barrier penetrations.
SUMNER, H. L. Georgia Power Co. 83/02/24 Region 2, Office of Director 1p 17549:043 24X Fiche: 50-321, 83/02/24, 8303150204.

8303150452 Forwards LER 83-006/03L-0.
NIX, H. C. Georgia Power Co. 83/02/24 O'REILLY, J. P. Region 2, Office of Director 1p 17561:053 24X Fiche: 50-321, 83/02/24, 8303150452.

--8303150456 LER 83-006/03L-0 on 830126, during refueling outage, plant svc water turbine bldg isolation valves A & D failed to isolate & pump 1A failed to start. Caused by disconnected control wire lifted for unknown reasons.
SUMNER, H. L. Georgia Power Co. 83/02/24 Region 2, Office of Director 2pp 17561:054 24X Fiche: 50-321, 83/02/24, 8303150452.

8303210388 Forwards LER 83-011/03L-0.
NIX, H. C. Georgia Power Co. 83/02/24 O'REILLY, J. P. Region 2, Office of Director 1p 17634:171 24X Fiche: 50-321, 83/02/24, 8303210388.

--8303210393 LER 83-011/03L-0 on 830204, during performance of sys walkdown, circuit which supplies essential control power to trip circulating water pump feeder breakers found terminated. Caused by improper const installation. SUMNER, H. L. Georgia Power Co. 83/02/24. Region 2, Office of Director. 2pp. 17634:172. 24X Fiche: 50-321, 83/02/24, 8303210388.

8303140570 Forwards updated LER 81-094/03X-1. NIX, H. C. Georgia Power Co. 83/03/01. O'REILLY, J. P. Region 2, Office of Director. 1p. 17533:361. 24X Fiche: 50-321, 83/03/01, 8303140570.

--8303140580 Updated LER 81-094/03X-1 on 810904, while testing standby gas treatment filter train A, train would not remove greater than or equal to 99% of halogenated hydrocarbon gas, per Tech Specs. Caused by defective charcoal. SUMNER, H. L. Georgia Power Co. 83/03/01. Region 2, Office of Director. 1p. 17533:362. 24X Fiche: 50-321, 83/03/01, 8303140570.

8303160443 Forwards LER 83-015/03L-0. NIX, H. C. Georgia Power Co. 83/03/03. O'REILLY, J. P. Region 2, Office of Director. 1p. 17592:281. 24X Fiche: 50-321, 83/03/03, 8303160443.

--8303160445 LER 83-015/03L-0 on 830204, reactor water cleanup sys differential instrument FT&C procedure not performed in Sept 1982. Caused by personnel error during entry of listed surveillance. Mod instituted. TIPPS, S. B. Georgia Power Co. 83/03/03. Region 2, Office of Director. 2pp. 17592:282. 24X Fiche: 50-321, 83/03/03, 8303160443.

8303210350 Forwards updated LER 80-055/01X-2. NIX, H. C. Georgia Power Co. 83/03/10. O'REILLY, J. P. Region 2, Office of Director. 1p. 17631:355. 24X Fiche: 50-321, 83/03/10, 8303210350.

--8303210354 Updated LER 80-055/01X-2 on 800531, during cold shutdown, 45 out of 61 mechanical snubbers found to be locked up. Caused by corrosion of snubbers. All but three snubbers replaced w/Pacific Scientific snubbers. SUMNER, H. L. Georgia Power Co. 83/03/10. Region 2, Office of Director. 2pp. 17631:356. 24X Fiche: 50-321, 83/03/10, 8303210350.

8303210463 Forwards LER 83-007/03L-0. NIX, H. C. Georgia Power Co. 83/03/10. O'REILLY, J. P. Region 2, Office of Director. 1p. 17634:155. 24X Fiche: 50-321, 83/03/10, 8303210463.

--8303210467 LER 83-007/03L-0 on 830218, HPCI turbine would not trip at less than 5,000 rpm. Caused by chipped ball on ball-tappet assembly. Ball-tappet assembly replaced. TIPPS, S. B. Georgia Power Co. 83/03/10. Region 2, Office of Director. 2pp. 17634:156. 24X Fiche: 50-321, 83/03/10, 8303210463.

8303210476 Forwards LER 83-019/03L-0. NIX, H. C. Georgia Power Co. 83/03/10. O'REILLY, J. P. Region 2, Office of Director. 1p. 17631:292. 24X Fiche: 50-321, 83/03/10, 8303210476.

--8303210485 LER 83-019/03L-0 on 830217, following refueling outage, intermediate range monitors F & H failed to come on scale & B had unacceptable overlap. Caused by component failure & setpoint drift. Faulty connectors replaced. TIPPS, S. B. Georgia Power Co. 83/03/10. Region 2, Office of Director. 1p. 17631:293. 24X Fiche: 50-321, 83/03/10, 8303210476.

8303210558 Forwards updated LER 81-018/01X-1. NIX, H. C. Georgia Power Co. 83/03/10. O'REILLY, J. P. Region 2, Office of Director. 1p. 17632:308. 24X Fiche: 50-321, 83/03/10, 8303210558.

--8303210563 Updated LER 81-018/01X-1 on 810311, during refueling shutdown/mod outage, cracks discovered in concrete wall around base plate of beam B2 in northeast diagonal. Caused unknown. Beam B2 resupported. SUMNER, H. [illegible]. Georgia Power Co. 83/03/10. Region 2, Office of Director. 2pp. 17632:309. 24X Fiche: 50-321, 83/03/10, 8303210558.

8303220046 Forwards LER 83-025/03L-0. NIX, H. C. Georgia Power Co. 83/03/15. O'REILLY, J. P. Region 2, Office of Director. 1p. 17652:159. 24X Fiche: 50-321, 83/03/15, 8303220046.

--8303220054 LER 83-025/03L-0 on 830224, "recirculation pump trip sys A out of svc or loss of control power" alarm annunciated & would not reset. Caused by component failure. Undervoltage monitors replaced. TIPPS, S. B. Georgia Power Co. 83/03/15. Region 2, Office of Director. 2pp. 17652:160. 24X Fiche: 50-321, 83/03/15, 8303220046.

8303240448 Forwards LER 83-018/03L-0. NIX, H. C. Georgia Power Co. 83/03/15. O'REILLY, J. P. Region 2, Office of Director. 1p. 17678:008. 24X Fiche: 50-321, 83/03/15, 8303240448.

--8303240453 LER 83-018/03L-0 on 830216, reactor water conductivity monitor indicated higher than correct reading taken by lab personnel. Caused by component failure due to inadequate flow to instrument. Instrument sample line cleaned. TIPPS, S. B. General Public Utilities - GPU Service Corp. 83/03/15. Region 2, Office of Director. 1p. 17678:009. 24X Fiche: 50-321, 83/03/15, 8303240448.

V. Operator Examinations

8303010551 Submits schedule for site visits to conduct operator licensing/instructor exams through Feb 1986, in response to 830111 Generic Ltr 83-01. GUCWA, L. T. Georgia Power Co. 83/02/23. EISENHUT, D. G. Division of Licensing. 2pp. 17343:035. 24X Fiche: 50-321, 83/02/23, 8303010551.

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

A. Application/construction stage documents & correspondence

8302010100 Forwards "Control of Heavy Loads," second phase of study re compliance w/NUREG-0612. SMITH, J. L. Long Island Lighting Co. 83/01/06. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 16974:089. 24X Fiche: 50-322, 83/01/06, 8302010100.

--8302010106 "Control of Heavy Loads." Long Island Lighting Co. 83/01/31. 43pp. 16974:092. 24X Fiche: 50-322, 83/01/06, 8302010100.

8303140002 Forwards Teledyne Engineering Svcs 830131 proposed findings re independent design review. BORDENICK, B. M. Hearing Branch 3. 83/02/04. BRENNER, L., MORRIS, P. A., CARPENTER, J. L. Atomic Safety and Licensing Board Panel. 10pp. 17539:337. 24X Fiche: 50-322, 83/02/04, 8303140002.

8303040248 Notification of change of 830301 meeting to 830317 w/util & Teledyne in Bethesda, MD to discuss independent design verification program. CARUSO, R. Licensing Branch 2. 83/02/15. SCHWENCER, A. Licensing Branch 2. 3pp. 17427:346. 24X Fiche: 50-322, 83/02/15, 8303040248.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303030596 Forwards record of 830214 telcon between Teledyne Engineering Svcs, util & S&W re independent design review for facility. KING, J. P. Teledyne Engineering Services. 83/02/17. DENTON, H. Office of Nuclear Reactor Regulation, Director. 5pp. 17409:323. 24X Fiche: 50-322, 83/02/17, 8303030596.

8303020287 Outlines NRC position on FSAR commitment to include listed procedures in preventive & corrective maint programs for nonsafety-related items. Response requested within 10 days of ltr receipt. EISENHUT, D. G. Division of Licensing. 83/02/18. POLLOCK, M. S. Long Island Lighting Co. 3pp. 17355:313. 24X Fiche: 50-322, 83/02/18, 8303020287.

8303010458 Requests extension of const completion date from 830331 to 831231. Cause of delays include overall increase in manpower requirements & matl quantities, new regulatory requirements, delays in startup program & delays in matl deliveries. MUSELER, W. J. Long Island Lighting Co. 83/02/25. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 9pp. 17346:187. 24X Fiche: 50-322, 83/02/25, 8303010458.

8303030160 Forwards "List of Active Safety-Related Equipment at Qualification Level," per NRC 821110 request. SMITH, J. L. Long Island Lighting Co. 83/02/25. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 54pp. 17412:138. 24X Fiche: 50-322, 83/02/25, 8303030160.

8303090171 Forwards minutes of 830215 meeting w/util & S&W to clarify util response to independent design review.
KING, J. P. Teledyne Engineering Services 83/02/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 5pp 17471:320
24X Fiche: 50-322, 83/02/25, 8303090171.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303090221 Comments on consideration of safety significance accorded nonsafety-related structure, sys or components delineated in FSAR, Tech Specs & emergency operating procedures. Util will continue to meet requirements of GDC 1.
POLLOCK, M. S. Long Island Lighting Co. 83/03/02 EISENHUT, D. G. Division of Licensing 2pp 17472:347 24X Fiche: 50-322, 83/03/02, 8303090221.

8303110148 Summary of 830218 meeting w/util in Bethesda, MD re classification of sys, components & structures.
WEINKAM, E. J. Licensing Branch 2 83/03/03 Licensing Branch 2 9pp 17523:149 24X Fiche: 50-322, 83/03/03, 8303110148.

--8303110156 Transcript of 830218 meeting in Bethesda, MD to discuss clarification of sys, components & structures. Pp 1-150.
* NRC - No Detailed Affiliation Given 83/02/18 152pp 17523:158 24X Fiche: 50-322, 83/03/03, 8303110148.

8303080466 Forwards current classification of items from independent design review for facility. Results of review of util responses to items originally classified as reaffirmation of findings also encl.
LANDERS, D. F. Teledyne Engineering Services 83/03/04 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 15pp 17453:181
24X Fiche: 50-322, 83/03/04, 8303080466.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303140596 Requests FSAR amends to include commitment for nonsafety-related items to be submitted as soon as possible.
EISENHUT, D. G. Division of Licensing 83/03/07 POLLOCK, M. S. Long Island Lighting Co. 2pp 17548:332 24X Fiche: 50-322, 83/03/07, 8303140596.

8303210153 Forwards "Reactor Containment Bldg Integrated Leak Rate Test Type A, B & C Preoperational Test."
SMITH, J. L. Long Island Lighting Co. 83/03/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17630:188 24X
Fiche: 50-322, 83/03/10, 8303210153.

--8303210155 "Reactor Containment Bldg Integrated Leak Rate Test Type A, B & C Preoperational Test."
* Stone & Webster Engineering Corp. 82/12/31 60pp 17630:190
24X Fiche: 50-322, 83/03/10, 8303210153.

8303150210 Forwards latest classification of items from independent design review. Results of review of util responses to items originally classified as findings also encl.
LANDERS, D. F. Teledyne Engineering Services 83/03/11 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 33pp 17556:088
24X Fiche: 50-322, 83/03/11, 8303150210.

8303180409 Forwards latest classification of items from independent design review. Results of review of util response to findings encl.
LANDERS, D. F. Teledyne Engineering Services 83/03/15 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 16pp 17622:011
24X Fiche: 50-322, 83/03/15, 8303180409.

8303210173 Forwards info re feedwater pipe breaks outside containment in response to NRC 830106 ltr. Piping designed for all loading conditions, including pump trip transient, thus minimizing possibility of stress induced pipe break.
SMITH, J. L. Long Island Lighting Co. 83/03/15 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp 17632:185 24X
Fiche: 50-322, 83/03/15, 8303210173.

8303230201 Notification of 830330 meeting w/util & Teledyne Engineering Svcs in Bethesda, MD to discuss independent design verification program findings.
CARUSO, R. Licensing Branch 2 83/03/15 SCHWENCER, A. Licensing Branch 2 4pp 17687:090 24X Fiche: 50-322, 83/03/15, 8303230201.

8303230065 Forwards "Mark II Hydrodynamic Loads Confirmatory Program Addl Piping & Support Evaluations, Shoreham Nuclear Power Station-Unit 1, Long Island Lighting Co." containing results of analyses for addl 67 piping subsystems.
SMITH, J. L. Long Island Lighting Co. 83/03/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp 17665:047 24X
Fiche: 50-322, 83/03/17, 8303230065.

--8303230119 "Mark II Hydrodynamic Loads Confirmatory Program Addl Piping & Support Evaluations, Shoreham Nuclear Power Station-Unit 1, Long Island Lighting Co."
* Long Island Lighting Co 83/03/17 17pp 17665:050 24X
Fiche: 50-322, 83/03/17, 8303230065.

8303280297 Notification of 830323 meeting w/util in Bethesda, MD to discuss long-term scheduling of work at facility.
CARUSO, R. Licensing Branch 2 83/03/17 SCHWENCER, A. Licensing Branch 2 3pp 17713:308 24X Fiche: 50-322, 83/03/17, 8303280297.

8303300218 Forwards surveillance & maint program description & sample procedures, in response to NRC 830203 request. Description addresses qualified life for equipment in nonharsh environs & is consistent w/10CFR50.49.
SMITH, J. L. Long Island Lighting Co. 83/03/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 11pp 17733:125 24X
Fiche: 50-322, 83/03/17, 8303300218.

--8303300227 "Instruction Manual for 60 Cells NCX-2550 Battery Assembled on 2-507-074710-806, 125-Volt Control Storage Battery."
* Gould, Inc. 75/11/18 25pp 17733:137 24X
Fiche: 50-322, 83/03/17, 8303300218.

--8303300240 Rev 0 to "Station Battery Capacity Tests, 125-Volt DC."
* Gould, Inc. 76/09/02 17pp 17733:162 24X
Fiche: 50-322, 83/03/17, 8303300218.

--8303300246 Rev 4 to "125-Volt Battery - Weekly Check."
* Gould, Inc. 82/07/23 9pp 17733:179 24X
Fiche: 50-322, 83/03/17, 8303300218.

--8303300251 Rev 2 to "Quarterly Station Battery Check - Voltage & Density - 125-Volt DC."
* Gould, Inc. 81/11/23 13pp 17733:188 24X
Fiche: 50-322, 83/03/17, 8303300218.

--8303300255 Rev 1 to "Svc Water Pump Rotating Assembly Removal & Installation."
* Gould, Inc. 83/02/03 7pp 17733:201 24X
Fiche: 50-322, 83/03/17, 8303300218.

--8303300258 Rev 0 to "Lubrication Control."
* Gould, Inc. 82/05/01 31pp 17733:208 24X
Fiche: 50-322, 83/03/17, 8303300218.

--8303300260 Rev 0 to "Large Electric Motors - Disassembly & Assembly."
* Gould, Inc. 77/10/20 11pp 17733:239 24X
Fiche: 50-322, 83/03/17, 8303300218.

--8303300265 Rev 2 to "Insulation Resistance Test of Auxiliary Electrical Equipment." Portions of Westinghouse spec, draft Tech Specs & surveillance procedure excerpts encl.
* Gould, Inc. 83/02/01 66pp 17733:250 24X
Fiche: 50-322, 83/03/17, 8303300218.

8303300724 Board Notification 83-32: Forwards Region I 830228 memo re errors discovered in computer analyses used to support Mark II containment confirmatory program.
NOVAK, T. M. Assistant Director for Licensing 83/03/18 Atomic Safety and Licensing Board Panel 5pp 17765:003 24X
Fiche: 50-000, 83/03/18, 8303300724.

--8303300727 Discusses util 820927 & 830215 repts of errors discovered in computer analyses that support Mark II containment confirmatory program. Seismic response spectra unaffected. Matter should be considered for board notification.
STAROSTECKI, R. Division of Project & Resident Programs 83/02/28
EISENHUT, D. G. Division of Licensing 3pp 17765:008 24X
Fiche: 50-000, 83/03/18, 8303300724.

8303300238 Confirms statements re compliance w/Reg Guide 1.62 listed in encl to NRC 830106 ltr. No seal cooling required for LPCI pumps as long as sys is pumping from suppression pool & temp below 212 F. RHR valves normally aligned for LPCI operation.
SMITH, J. L. Long Island Lighting Co. 83/03/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 5pp 17733:315 24X
Fiche: 50-322, 83/03/22, 8303300238.

8303300423 Forwards counsel 830322 ltr to NRR re extension of CP & ltr to ASLB transmitting errata to util brief opposing Suffolk County motion to terminate proceeding & for certification.
REVELEY, W. T. Hunton & Williams. REVELEY, W. T. Long Island Lighting Co. 83/03/22. PALLADINO, N. J.; GILINSKY, V.; AHEARNE, J. F. Commissioners. 1p. 17734:353. 24X Fiche: 50-322, 83/03/22, 8303300423.

--8303240039 Responds to HH Brown theory that Suffolk County, NY can veto util application to extend CP by withdrawing assurance of offsite emergency preparedness. Theory incorrect & irrelevant. Decision to extend CP should be made by NRR.
REVELEY, W. T. Hunton & Williams. REVELEY, W. T. Long Island Lighting Co. 83/03/22. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 17734:354. 24X Fiche: 50-322, 83/03/22, 8303300423.

8303290687 Requests review of GE Model CR-2940 electrical switch use due to recent failure during environ qualification testing under design basis LOCA radiation levels. Plans or justification requested in 30 days.
SCHWENCER, A. Licensing Branch 2. 83/03/24. POLLOCK, M. S. Long Island Lighting Co. 3pp. 17743:026. 24X Fiche: 50-322, 83/03/24, 8303290687.

8303310224 Responds to util counsel 830322 ltr re CP extension. Util has no legal right to extension & cannot show good cause for extension. Fact that plant cannot be licensed makes continued const futile.
BROWN, H. H. Kirkpatrick, Lockhart, Hill, Christopher & Phillips. BROWN, H. H. Suffolk County, NY. 83/03/28. DENTON, H. R. NRC - No Detailed Affiliation Given. 3pp. 17763:035. 24X Fiche: 50-322, 83/03/28, 8303310224.

F. Security, medical, emergency & fire protection plans

8303100245 Confirms info discussed w/R Gilbert re permanent emergency operations facility. Facility located approx 19 miles west southwest from site. Structure consists of concrete block wall w/steel framing.
SMITH, J. L. Long Island Lighting Co. 83/03/07. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17485:355. 24X Fiche: 50-322, 83/03/07, 8303100245.

8303140216 Ack receipt of 830214 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-322/82-18.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/08. POLLOCK, M. S. Long Island Lighting Co. 1p. 17539:284. 24X Fiche: 50-322, 83/03/08, 8303140216.

--8303140218 Responds to NRC 820930 ltr re violations noted in IE Insp Rept 50-322/82-18. Corrective actions: corporate & onsite emergency preparedness coordinators assigned on permanent basis. Portable area radiation monitors ordered.
POLLOCK, M. S. Long Island Lighting Co. 82/10/29. SMITH, G. H. Division of Emergency Preparedness & Operational Support. 13pp. 17539:285. 24X Fiche: 50-322, 83/03/08, 8303140216.

--8303140219 Supplis 821029 response to NRC 820930 ltr re violations noted in IE Insp Rept 50-322/82-18. Revs to emergency plan implementing procedures completed. Fuel load scheduled for late in Second Quarter 1983.
POLLOCK, M. S. Long Island Lighting Co. 83/02/14. MARTIN, T. T. Division of Engineering & Technical Programs. 7pp. 17539:298. 24X Fiche: 50-322, 83/03/08, 8303140216.

8303280005 Requests review of listed documentation re implementation of final security settlement agreement to determine whether safeguards classification should be designated.
SMITH, J. L. Long Island Lighting Co. 83/03/24. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17707:348. 24X Fiche: 50-322, 83/03/24, 8303280005.

8303310681 Informs that safeguards info markings improperly applied to listed documents. Markings will be corrected & documents handled as nonsafeguards info.
NOVAK, T. M. Assistant Director for Licensing. 83/03/25. POLLOCK, M. S. Long Island Lighting Co. 3pp. 17780:292. 24X Fiche: 50-322, 83/03/25, 8303310681.

G. Adjudicatory correspondence

8303140002 Forwards Teledyne Engineering Svcs 830131 proposed findings re independent design review.
BORDENICK, B. M. Hearing Branch 3. 83/02/04. BRENNER, L.; MORRIS, P. A.; CARPENTER, J. L. Atomic Safety and Licensing Board Panel. 10pp. 17539:337. 24X Fiche: 50-322, 83/02/04, 8303140002.

8303140161 Informs that NRC 830204 ltr re Shoreham Opponents Coalition adoption of Suffolk County proposed findings should be modified to include ref to ASLAB 830104 decision (ALAB-709).
BORDENICK, B. M. Hearing Branch 3. 83/02/07. BRENNER, L.; MORRIS, P. A.; CARPENTER, J. L. Atomic Safety and Licensing Board Panel. 2pp. 17540:046. 24X Fiche: 50-322, 83/02/07, 8303140161.

8303140004 Informs that NRC concerns re cable separation in NSSS cabinets resolved. Issue was subj of NRC/util resolution of Suffolk County Contention 31/Shoreham Opponents Coalition Contention 19(g). Supplemehtal SER encl.
REPKA, D. A. Hearing Branch 3. 83/02/17. BRENNER, L.; MORRIS, P. A.; CARPENTER, J. L. Atomic Safety and Licensing Board Panel. 2pp. 17540:110. 24X Fiche: 50-322, 83/02/17, 8303140004.

8303010354 Views on JH Conran 830209 affidavit supporting reopening of record on Suffolk County/Shoreham Opponents Coalition Contention 7B re Unresolved Safety Issue A-17. Affidavit untimely & introduces no new facts. W/Certificate of Svc.
EARLEY, A. F. Long Island Lighting Co. EARLEY, A. F. Hunton & Williams. 83/02/22. Atomic Safety and Licensing Board Panel. 27pp. 17345:132. 24X Fiche: 50-322, 83/02/22, 8303010354.

8303040457 Reply to Suffolk County's NRC proposed opinions, findings of fact & conclusions of law. Certificate of Svc encl.
* Long Island Lighting Co. * Hunton & Williams. 83/02/22. 610pp. 17420:094. 24X Fiche: 50-322, 83/02/22, 8303040457.

8303010408 Notice of change of atty for intervenor. J Dougherty will substitute for firm of Twomey, Latham & Shea. Notice of appearance & Certificate of Svc encl.
DOUGHERTY, J.; BREDES, N. Shoreham Opponents Coalition. DOUGHERTY, J. Dougherty, J. B. 83/02/23. Atomic Safety and Licensing Board Panel. 5pp. 17343:356. 24X Fiche: 50-322, 83/02/23, 8303010408.

8303140504 Advises of resolution of Contention SC 22 on Item II.D.1 re safety relief valves. Confirmatory stress analysis evaluation submitted 830215.
REPKA, D. A. Hearing Branch 3. 83/02/23. BRENNER, L.; MORRIS, P. A.; CARPENTER, J. L. Atomic Safety and Licensing Board Panel. 2pp. 17540:211. 24X Fiche: 50-322, 83/02/23, 8303140504.

8303020032 Memorandum requesting submission of NY State views on Suffolk County, NY decision that no workable emergency evacuation plan can be developed. Response due by 830318.
BRENNER, L. Atomic Safety and Licensing Board Panel. 83/02/28. 4pp. 17352:260. 24X Fiche: 50-322, 83/02/28, 8303020032.

8303020084 Confirmatory memorandum & order directing submission of briefs on Suffolk County 830223 motion to terminate proceeding. County brief due by 830304; responsive briefs by 830318 & NRC brief by 830325.
BRENNER, L. Atomic Safety and Licensing Board Panel. 83/02/28. 5pp. 17352:159. 24X Fiche: 50-322, 83/02/28, 8303020084.

8303040522 Errata to util 830117 proposed opinion, findings of fact & conclusions of law in form of partial initial decision. Certificate of Svc encl.
MCCLESKEY, K. E. Long Island Lighting Co. MCCLESKEY, K. E. Hunton & Williams. 83/02/28. 8pp. 17373:280. 24X Fiche: 50-322, 83/02/28, 8303040522.

8303030455 Response to Town of Southampton 830223 notice of intent to participate as interested municipality. NRC does not object as long as Town takes proceeding as found. Certificate of Svc encl.
REPKA, D. A. Hearing Branch 3. 83/03/02. Atomic Safety and Licensing Board Panel. 5pp. 17410:044. 24X Fiche: 50-322, 83/03/02, 8303030455.

8303040315 Responds to 830223 ltr re Teledyne meeting scheduled for 830317. NRC does not arrange for transcription of review meetings. Mutually convenient meeting dates not always possible.
BORDENICK, B. M. Hearing Branch 3. 83/03/03. MILLER, M. S. Kirkpatrick, Lockhart, Hill, Christopher & Phillips. 2pp. 17421:348. 24X Fiche: 50-322, 83/03/03, 8303040315.

8303040327 Responds to ASLB 830223 questions re independent design verification program conducted by Teledyne. Program is voluntary & seeks to improve confidence in quality of design & const.
REPKA, D. A. Hearing Branch 3. 83/03/03. BRENNER, L.; MORRIS, P. A.; CARPENTER, J. L. Atomic Safety and Licensing Board Panel. 2pp. 17421:344. 24X Fiche: 50-322, 83/03/03, 8303040327.

8303080142 Response to Town of Southampton 830223 notice of intent to participate as interested municipality. Southampton should be required to delineate which offsite issues Town will participate in. Certificate of Svc encl.
MCCLESKEY, K. E. Long Island Lighting Co. MCCLESKEY, K. E. Hunton & Williams. 83/03/03. Atomic Safety and Licensing Board Panel. 8pp. 17457:256. 24X Fiche: 50-322, 83/03/03, 8303080142.

8303080054 Supplemental brief in support of motion to terminate OL proceeding. Issue of whether OL may be granted in absence of offsite emergency plan approved by local govt should be certified to Commission. Certificate of Svc encl.
BROWN, H. H. Suffolk County, NY BROWN, H. H. Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/03/04 Atomic Safety and Licensing Board Panel 55pp 17436:226 24X Fiche 50-322, 83/03/04, 8303080054.

8303080040 Advises that Teledyne Engineering Svcs independent design verification rept will not be submitted to NRC until mid-Apr 1983.
BORDENICK, B. M. Hearing Branch 3 83/03/07 BRENNER, L. ; MORRIS, P. A. ; CARPENTER, J. L. Atomic Safety and Licensing Board Panel 1p 17436:359 24X Fiche 50-322, 83/03/07, 8303080040.

8303080159 Notice of resumption of hearing on 830405 in Riverhead, NY which will continue until issues of sys interaction & safety classification raised by Conran affidavit resolved.
BRENNER, L. Atomic Safety and Licensing Board Panel 83/03/07 2pp 17457:352 24X Fiche 50-322, 83/03/07, 8303080159.

8303090132 Responds further to 830228 ltr re Teledyne documents. Encl 830211 ltr & Document RFI 5633-28 are final Teledyne documents re facility. Future Teledyne documents will be forwarded. W/o encl.
BORDENICK, B. M. Hearing Branch 4 83/03/07 MILLER, M. S. Kirkpatrick, Lockhart, Hill, Christopher & Phillips 2pp 17470:306 24X Fiche 50-322, 83/03/07, 8303090132.

8303100286 Motion to strike portions of NRC & util proposed opinion & findings of fact & util reply to NRC & Suffolk County proposed opinions & findings. Findings based on evidence not in record. Certificate of Svc encl.
LETSCHE, K. J. Suffolk County, NY LETSCHE, K. J. Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/03/08 Atomic Safety and Licensing Board Panel 10pp 17489:296 24X Fiche 50-322, 83/03/08, 8303100286.

8303140200 Forwards Teledyne 830217 ltr re independent design review, for info. Certificate of Svc encl.
BORDENICK, B. M. Hearing Branch 3 83/03/08 BRENNER, L. ; CARPENTER, J. L. ; MORRIS, P. A. Atomic Safety and Licensing Board Panel 4pp 17540:098 24X Fiche 50-322, 83/03/08, 8303140200.

8303140489 Forwards util request for CP extension until 831231.
BORDENICK, B. M. Hearing Branch 4 83/03/08 DOUGHERTY, J. B. Shoreham Opponents Coalition 1p 17540:324 24X Fiche 50-322, 83/03/08, 8303140489.

8303110194 Requests encl ltrs be served on parties.
LANE, V. M. Atomic Safety and Licensing Board Panel 83/03/09 STUCKY, S. Docketing & Services Branch 1p 17520:122 24X Fiche 50-322, 83/03/09, 8303110194.

--8303110196 Opposes plant licensing.
HUNT, T. ; HUNT, E. ; OPINANTE, A. Affiliation Unknown 83/03/03 BRENNER, L. ; MORRIS, P. ; CARPENTER, J. Atomic Safety and Licensing Board Panel 6pp 17520:123 24X Fiche 50-322, 83/03/09, 8303110196.

8303140073 Notifies that J Dougherty address corrected on PDR list, per 830302 instructions.
BORDENICK, B. M. Hearing Branch 3 83/03/09 LATHAM, S. B. Twomey, Latham & Shea 2pp 17540:070 24X Fiche 50-322, 83/03/09, 8303140073.

8303140254 Memorandum & order admitting Town of Southampton, NY as interested municipality. Since town must take proceeding as found, participation will be limited to offsite emergency planning matters.
BRENNER, L. Atomic Safety and Licensing Board Panel 83/03/10 Southampton, NY 5pp 17538:320 24X Fiche 50-322, 83/03/10, 8303140254.

8303140366 Responds to 830223 ltr re offsite emergency planning. Commission is studying filings of parties re development of offsite emergency plan.
PLAINE, H. H. Office of the General Counsel 83/03/10 COHALAN, P. F. Suffolk County, NY 1p 17543:317 24X Fiche 50-322, 83/03/10, 8303140366.

8303140170 Forwards Teledyne 830304 ltr re independent design review, for info. Certificate of Svc encl.
BORDENICK, B. M. Hearing Branch 3 83/03/11 BRENNER, L. ; CARPENTER, J. L. ; MORRIS, P. A. Atomic Safety and Licensing Board Panel 4pp 17540:027 24X Fiche 50-322, 83/03/11, 8303140170.

8303160035 Informs that document identified in footnote on P 1 of Attachment A to NRC 830228 ltr was discussed in Teledyne 830304 ltr to NRC. W/o encl.
BORDENICK, B. M. Hearing Branch 3 83/03/11 MILLER, M. S. Kirkpatrick, Lockhart, Hill, Christopher & Phillips 1p 17596:359 24X Fiche 50-322, 83/03/11, 8303160035.

8303170153 Forwards Teledyne Engineering Svcs 830225 ltr re facility independent design review. Certificate of Svc encl.
BORDENICK, B. M. Hearing Branch 3 83/03/15 BRENNER, L. ; CARPENTER, J. L. ; MORRIS, P. A. Atomic Safety and Licensing Board Panel 4pp 17608:347 24X Fiche 50-322, 83/03/15, 8303170153.

8303180037 Informs that encl NUREG/CR-2631, SAND 82-2726, "Logical Framework for Identifying Equipment Important to Safety in Nuclear Power Plants," is initial working draft which does not represent NRC final conclusions or positions. W/o encl.
BORDENICK, B. M. Hearing Branch 3 83/03/17 LETSCHE, K. J. Kirkpatrick, Lockhart, Hill, Christopher & Phillips 1p 17617:342 24X Fiche 50-322, 83/03/17, 8303180037.

8303220241 Memorandum supporting Suffolk County motion to terminate OL proceeding. ASLB has no legal authority under NRC authorization acts for FY80 & FY82-83 to issue OL. Certificate of Svc encl.
DOUGHERTY, J. B. Shoreham Opponents Coalition SHAPIRO, R. North Shore Committee Against Nuclear & Thermal Pollution DOUGHERTY, J. B. Dougherty, J. B. 83/03/17 Atomic Safety and Licensing Board Panel 20pp 17656:328 24X Fiche 50-322, 83/03/17, 8303220241.

8303230260 Brief supporting Suffolk County 830223 motion to terminate OL proceeding & motion for certification. Approved & implementable local emergency plan required for OL issuance. Certificate of Svc encl.
LATHAM, S. B. Southampton, NY LATHAM, S. B. Twomey, Latham & Shea 83/03/17 Atomic Safety and Licensing Board Panel 24pp 17661:182 24X Fiche 50-322, 83/03/17, 8303230260.

8303220185 Informs that NRC is closing out contract w/INEL re graded QA for important-to-safety structures, sys & components discussed during testimony by NRC witness WP Haass.
RAWSON, R. J. Hearing Branch 4 83/03/18 BRENNER, L. ; MORRIS, P. A. ; CARPENTER, J. L. Atomic Safety and Licensing Board Panel 2pp 17658:149 24X Fiche 50-322, 83/03/18, 8303220185.

8303220193 Forwards motion for leave to file amicus curiae brief & amicus curiae brief re Suffolk County motion to terminate OL proceeding.
ROBINSON, K. L. New York, State of 83/03/18 CHILK, S. Docketing & Services Branch 1p 17657:139 24X Fiche 50-322, 83/03/18, 8303220193.

--8303220197 Forwards motion for leave to file amicus curiae brief & amicus curiae brief re Suffolk County motion to terminate OL proceeding.
ROBINSON, K. L. New York, State of 83/03/18 BRENNER, L. ; CARPENTER, J. L. ; MORRIS, P. A. Atomic Safety and Licensing Board Panel 1p 17657:140 24X Fiche 50-322, 83/03/18, 8303220197.

--8303220200 Motion for leave to file amicus curiae brief responding to Suffolk County motion to terminate OL proceeding. Motion raises important legal issues re plant licensing. Decision may have significant impact on other plants.
LEIPZIG, S. D. ; ROBINSON, K. L. New York, State of 83/03/18 Atomic Safety and Licensing Board Panel 3pp 17657:141 24X Fiche 50-322, 83/03/18, 8303220193.

--8303220206 Amicus curiae brief in response to Suffolk County motion to terminate OL proceeding. NRC lacks authority to approve util application for OL when state & local offsite emergency preparedness plans do not exist. Certificate of Svc encl.
BIALIK, E. I. New York, State of 83/03/18 Atomic Safety and Licensing Board Panel 19pp 17657:144 24X Fiche 50-322, 83/03/18, 8303220193.

8303230209 Brief in opposition to Suffolk County 830223 motion to terminate proceeding & cease further consideration of OL application. County supported CP & collaborated in util emergency plan. Attachments & Certificate of Svc encl.
REVELEY, W. T. Long Island Lighting Co. REVELEY, W. T. Hunton & Williams 83/03/18 Atomic Safety and Licensing Board Panel 291pp 17662:233 24X Fiche 50-322, 83/03/18, 8303230209.

8303300470 Advises that request for State of NY submission sent to NY State Disaster Preparedness Commission Chairman, D Axelrod. Response will be sent 830318. Related correspondence.
KELLY, M. J. New York, State of 83/03/18 BRENNER, L. Atomic Safety and Licensing Board Panel 1p 17731:129 24X Fiche 50-322, 83/03/18, 8303300470.

8303230012 Response opposing Suffolk County 830308 motion to strike portions of NRC & util proposed opinion & findings of fact. Facts are offered as followup to info clearly on record. Certificate of Svc encl.
REPKA, D. A. Hearing Branch 3 83/03/21 Atomic Safety and Licensing Board Panel 8pp. 17665.026 24X Fiche 50-322, 83/03/21, 8303230012.

8303300423 Forwards counsel 830322 ltr to NRR re extension of CP & ltr to ASLB transmitting errata to util brief opposing Suffolk County motion to terminate proceeding & for certification.
REVELEY, W. T. Hunton & Williams REVELEY, W. T. Long Island Lighting Co. 83/03/22 PALLADINO, N. J.; GILINSKY, V.; AHEARNE, J. F. Commissioners 1p. 17734.353 24X Fiche 50-322, 83/03/22, 8303300423.

--8303240039 Responds to HH Brown theory that Suffolk County, NY can veto util application to extend CP by withdrawing assurance of offsite emergency preparedness. Theory incorrect & irrelevant. Decision to extend CP should be made by NRR.
REVELEY, W. T. Hunton & Williams REVELEY, W. T. Long Irland Lighting Co. 83/03/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 4pp. 17734.354 24X Fiche 50-322, 83/03/22, 8303300423.

--8303300551 Forwards errata to util 830318 brief opposing Suffolk County motion to terminate proceeding & for certification.
CHRISTMAN, J. N. Hunton & Williams CHRISTMAN, J. N. Long Island Lighting Co. 83/03/22 BRENNER, L.; MORRIS, P. A.; CARPENTER, J. H. Atomic Safety and Licensing Board Panel 2pp. 17734.358 24X Fiche 50-322, 83/03/22, 8303300423.

--8303300562 Errata to util 830318 brief opposing Suffolk County motion to terminate proceeding & for certification.
CHRISTMAN, J. N. Long Island Lighting Co. CHRISTMAN, J. N. Hunton & Williams 83/03/22 Atomic Safety and Licensing Board Panel 2pp. 17734.360 24X Fiche 50-322, 83/03/22, 8303300423.

8303240233 Calls ASLB attention to Commission 830308 "Policy Statement on Safety Goals for Operation of Nuclear Power Plants," per Contention 7B.
REIS, E. J. Hearings Division 83/03/23 BRENNER, L.; MORRIS, P. A.; CARPENTER, J. L. Atomic Safety and Licensing Board Panel 2pp. 17680.055 24X Fiche 50-322, 83/03/23, 8303240233.

8303300352 Response opposing Suffolk County 830308 motion to strike portions of NRC & util proposed opinion & findings of fact re Contentions SC-22 on safety relief valves & SC-21 on Mark II. Certificate of Svc encl.
IRWIN, D. P. Long Island Lighting Co. IRWIN, D. P. Hunton & Williams 83/03/23 Atomic Safety and Licensing Board Panel 67pp. 17735.001 24X Fiche 50-322, 83/03/23, 8303300352.

8303280298 Response opposing Suffolk County 830223 motions to terminate OL proceeding & for certification. County resolution not binding in proceeding. Certificate of Svc encl.
REPKA, D. A. Hearing Branch 3 83/03/25 Atomic Safety and Licensing Board Panel 26pp. 17706.045 24X Fiche 50-322, 83/03/25, 8303280298.

8303300466 Responds to ASLB 830228 memorandum requesting views on emergency planning. State may play role in achieving accommodation between Suffolk County & util.
AXELROD, D. New York, State of 83/03/25 BRENNER, L. Atomic Safety and Licensing Board Panel 2pp. 17731.104 24X Fiche 50-322, 83/03/25, 8303300466.

8303290190 Responds to WT Reveley 830322 ltr disputing need for immediate rule that CPPR-95 cannot lawfully be extended. Util fails to show good cause for extension & has no legal right to extension per 10CFR50.55(b).
BROWN, H. H. Kirkpatrick, Lockhart, Hill, Christopher & Phillips BROWN, H. H. Suffolk County, NY 83/03/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp. 17722.306 24X Fiche 50-322, 83/03/28, 8303290190.

8303300016 Forwards AR Dynner 830325 telecopy re current status of settlement discussions on QA manual & operations QA procedures. Dynner now unavailable. Ellis to provide schedular info re operations QA changes util agreed to make.
BORDENICK, B. M. Hearing Branch 3 83/03/28 BRENNER, L.; MORRIS, P. A.; CARPENTER, J. L. Atomic Safety and Licensing Board Panel 2pp. 17735.311 24X Fiche 50-322, 83/03/28, 8303300016.

--8303300023 Provides current status of settlement discussions on QA manual & operations QA procedures.
DYNNER, A. R. Kirkpatrick, Lockhart, Hill, Christopher & Phillips DYNNER, A. R. Long Island Lighting Co. 83/03/25 BORDENICK, B. M. Hearing Branch 3 ELLIS, T. S. Harmon & Weiss 1p. 17735.313 24X Fiche 50-322, 83/03/28, 8303300016.

8303310224 Responds to util counsel 830322 ltr re CP extension. Util has no legal right to extension & cannot show good cause for extension. Fact that plant cannot be licensed makes continued const futile.
BROWN, H. H. Kirkpatrick, Lockhart, Hill, Christopher & Phillips BROWN, H. H. Suffolk County, NY 83/03/28 DENTON, H. R. NRC - No Detailed Affiliation Given 3pp. 17763.035 24X Fiche 50-322, 83/03/28, 8303310224.

8303300346 Requests opportunity to present Suffolk County position on adequacy of NRC Unresolved Safety Issue A-17 program & on Conran concerns re sys interaction, if Commission 830331 briefing raises any Shoreham-related issues.
LETSCHE, K. J. Kirkpatrick, Lockhart, Hill, Christopher & Phillips LETSCHE, K. J. Suffolk County, NY 83/03/29 PALLADINO, N. J.; GILINSKY, V.; ASSELSTINE, J. K. Commissioners 3pp. 17734.195 24X Fiche 50-322, 83/03/29, 8303300346.

8303310269 Reply opposing util 830318 & NRC 830325 responses opposing Suffolk County motion to terminate OL proceeding & for certification. Util & NRC legal arguments irrelevant to issues presented or w/o merit.
MCMURRAY, C. M. Suffolk County, NY MCMURRAY, C. M. Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/03/29 Atomic Safety and Licensing Board Panel 23pp. 17756.043 24X Fiche 50-322, 83/03/29, 8303310269.

--8303310278 Petition for leave to file brief in reply to util 830318 & NRC 830325 briefs opposing Suffolk County motion to terminate OL proceeding. Util & NRC briefs mischaracterize County arguments & legal position. Certificate of Svc encl.
MCMURRAY, C. M. Suffolk County, NY MCMURRAY, C. M. Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/03/29 Atomic Safety and Licensing Board Panel 7pp. 17756.066 24X Fiche 50-322, 83/03/29, 8303310269.

8303310273 Motion to strike portions of Suffolk County supplemental testimony of MW Goldsmith, RB Hubbard & GC Minor on Contention 7B. Testimony beyond scope of reopened aspects of proceeding. Certificate of Svc encl.
RAWSON, R. J. Hearing Branch 4 83/03/30 Atomic Safety and Licensing Board Panel 15pp. 17755.327 24X Fiche 50-322, 83/03/30, 8303310273.

H. General correspondence

8303030378 Opposes plant. No evacuation possible.
METTA, L. L.; CARAVASSI, M. Affiliation Unknown 83/01/24 BRENNER, L. Atomic Safety and Licensing Board Panel 2pp. 17410.232 24X Fiche 50-322, 83/01/24, 8303030378.

8303180044 Discusses concerns re possible radiation leakage & capability of evacuation plans. Emergency procedures require onsite person to inform state, federal & local govts of abnormal conditions.
STAROSTECKI, R. Division of Project & Resident Programs 83/03/04 BELSON, B. Affiliation Unknown 3pp. 17625.263 24X Fiche 50-322, 83/03/04, 8303180044.

8303240066 Forwards response to 830214 ltr re JH Cochran allegations concerning facility safety. Complete history of resources assigned to Task A-17 will be provided.
DIRCKS, W. J. Office of the Executive Director for Operations 83/03/16 DOWNEY, T. J. House of Rep 12pp. 17694.239 24X Fiche 50-322, 83/03/16, 8303240066.

--8303240071 Task Action Plan A-17: "Sys Interactions in Nuclear Power Plants."
e. NRC - No Detailed Affiliation Given 83/03/31 31pp. 17694.251 24X Fiche 50-322, 83/03/16, 8303240066.

--8303240077 Requests info re J Cochran allegations concerning facility safety. Schedule for resolution of current unresolved safety issues encl.
DOWNEY, T. J. House of Rep 83/02/14 PALLADINO, N. J. Commissioners 7pp. 17694.282 24X Fiche 50-322, 83/03/16, 8303240066.

8303290143 Forwards FES (NUREG-0285), in response to 830217 ltr re homeowners insurance policies & possible radioactive contamination of drinking water supplies as result of nuclear accident. W/o encl.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 83/03/18 BELLEVILLE, A. Affiliation Unknown 6pp. 17730.270 24X Fiche 50-322, 83/03/18, 8303290143.

--8303290149 Opposes licensing of facility because of danger of contamination of water supplies & food crops & risk of invalidating homeowners insurance.
BELLEVILLE, A. Affiliation Unknown 83/02/17 PALLADINO, N. Commissioners 2pp. 17730.275 24X Fiche 50-322, 83/03/18, 8303290143.

# DOCKETED ITEMS

F. Operating license stage documents & correspondence

8303150340 Advises of 830405 meeting w/licensees & major contractors at Dallas/Fort Worth, TX to provide info & guidance re 10CFR50 QA & Tech Spec deviations & discuss decentralization policy. Questions should be submitted in writing by 830321. COLLINS, J. T. Region 4, Office of Director 83/03/10 Public Service Co. of Colorado. 12pp. 17562:291. 24X Fiche: 50-000, 83/03/10, 8303150340.

G. Inspection reports, IE Bulletins & correspondence

8303030360 Forwards IE Insp Rept 50-322/83-03 on 830117-21. No noncompliance noted. MARTIN, T. T. Division of Engineering & Technical Programs 83/02/15 POLLOCK, M. S. Long Island Lighting Co. 2pp. 17410:262. 24X Fiche: 50-322, 83/02/15, 8303030360.

--8303030364 IE Insp Rept 50-322/83-03 on 830117-21. No noncompliance noted. Major areas inspected: licensee action on previous insp findings, fuel receipt, handling & storage, preoperational test program & test procedure review. NICHOLAS, H. H., NORRHOLM, L. J. Region 1, Office of Director. 83/02/14. 11pp. 17410:264. 24X Fiche: 50-322, 83/02/15, 8303030360.

8303110355 Board Notification 83-14: forwards followup info on apparent deficiencies in Midland-Ross superstrut matl. EISENHUT, D. G. Division of Licensing 83/02/18 PALLADINO, N. Commissioners. 24pp. 17546:205. 24X Fiche: 50-000, 83/02/18, 8303110355.

8303080284 Forwards IE Insp Rept 50-322/82-35 on 821130-1231. STAROSTECKI, R. Division of Project & Resident Programs 83/02/24 POLLOCK, M. S. Long Island Lighting Co. 2pp. 17442:344. 24X Fiche: 50-322, 83/02/24, 8303080284.

--8303080292 IE Insp Rept 50-322/82-35 on 821130-1231. Noncompliance noted: failure of test program to assure that test requirements satisfied for emergency diesel generator 102. HIGGINS, J. C., HANNES, P. H., GALLO, R. M. Division of Project & Resident Programs. 83/02/01. 10pp. 17442:346. 24X Fiche: 50-322, 83/02/24, 8303080284.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303040459 Forwards IE Mgt Meeting Rept 50-322/83-04 on 830125. STAROSTECKI, R. Division of Project & Resident Programs 83/02/28 POLLOCK, M. S. Long Island Lighting Co. 2pp. 17373:337. 24X Fiche: 50-322, 83/02/28, 8303040459.

--8303040462 IE Mgt Meeting Rept 50-322/83-04 on 830125. Major areas discussed: findings of readiness assessment team insp referenced in IE Insp Rept 50-322/83-02. GALLO, R. M., GREENMAN, E. G. Division of Project & Resident Programs 83/02/28. 4pp. 17373:339. 24X Fiche: 50-322, 83/02/28, 8303040459.

8303100260 Ack receipt of 830121 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-322/82-30. STAROSTECKI, R. Division of Project & Resident Programs. 83/03/03 POLLOCK, M. S. Long Island Lighting Co. 2pp. 17490:001. 24X Fiche: 50-322, 83/03/03, 8303100260.

--8303100265 Responds to NRC 821223 ltr re violations noted in IE Insp Rept 50-322/83-30. Corrective actions: lug repaired, Deficiency Rept 954 issued & electricians & technicians reinstructed in proper techniques for installing & terminating cables. POLLOCK, M. S. Long Island Lighting Co. 83/01/21. STAROSTECKI, R. Division of Project & Resident Programs. 4pp. 17490:003. 24X Fiche: 50-322, 83/03/03, 8303100260.

8303180176 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." No Bunker-Ramo assemblies used at plant. POLLOCK, M. S. Long Island Lighting Co. 83/03/03 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 17617:256. 24X Fiche: 50-322, 83/03/03, 8303180176.

8303140216 Ack receipt of 830214 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-322/82-18. MARTIN, T. T. Division of Engineering & Technical Programs 83/03/08 POLLOCK, M. S. Long Island Lighting Co. 1p. 17539:284. 24X Fiche: 50-322, 83/03/08, 8303140216.

--8303140218 Responds to NRC 820930 ltr re violations noted in IE Insp Rept 50-322/82-18. Corrective actions: corporate & onsite emergency preparedness coordinators assigned on permanent basis. Portable area radiation monitors ordered. POLLOCK, M. S. Long Island Lighting Co. 82/10/29. SMITH, G. H. Division of Emergency Preparedness & Operational Support. 13pp. 17539:285. 24X Fiche: 50-322, 83/03/08, 8303140216.

--8303140219 Supplx 821029 response to NRC 820930 ltr re violations noted in IE Insp Rept 50-322/82-18. Revs to emergency plan implementing procedures completed. Fuel load scheduled for late in Second Quarter 1983. POLLOCK, M. S. Long Island Lighting Co. 83/03/14. MARTIN, T. T. Division of Engineering & Technical Programs. 7pp. 17539:298. 24X Fiche: 50-322, 83/03/08, 8303140216.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303240011 Ack receipt of 830225 ltr re actions taken concerning housekeeping conditions, in response to NRC 830119 ltr forwarding results of Region I special team insp. STAROSTECKI, R. Division of Project & Resident Programs. 83/03/14. POLLOCK, M. S. Long Island Lighting Co. 1p. 17694:350. 24X Fiche: 50-322, 83/03/14, 8303240011.

--8303240017 Responds to NRC 830119 ltr re IE Insp Rept 50-322/82-02 on 830110-15. Corrective actions: approx 55 addl craft personnel assigned to full-time housekeeping activities until housekeeping improved to satisfactory level. MUSELER, W. J. Long Island Lighting Co. 83/02/25. STAROSTECKI, R. Division of Project & Resident Programs. 5pp. 17694:351. 24X Fiche: 50-322, 83/03/14, 8303240011.

8303240462 Forwards IE Insp Rept 50-322/83-06 on 830214-18. No noncompliance noted. MARTIN, T. T. Division of Engineering & Technical Programs 83/03/15 POLLOCK, M. S. Long Island Lighting Co. 2pp. 17678:051. 24X Fiche: 50-322, 83/03/15, 8303240462.

--8303240467 IE Insp Rept 50-322/83-06 on 830214-18. No noncompliance noted. Major areas inspected: response to IE Circular 81-08, foundation matls & verification that foundation matls supporting & proximate to safety-related structures. VARELA, A. A., DURR, J. P. Region 1, Office of Director. 83/03/04. 5pp. 17678:053. 24X Fiche: 50-322, 83/03/15, 8303240462.

8303210161 Supplemental response to IE Bulletin 80-08 re containment liner penetrations. Primary containment penetrations not accessible for radiography. Major mods would be required to enable access for radiography of any welds. SMITH, J. L. Long Island Lighting Co. 83/03/16. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 17632:177. 24X Fiche: 50-322, 83/03/16, 8303210161.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 12ipp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

S. Reportable occurrences, LERs & related correspondence

8303080355 Final deficiency rept re potentially shorter-than-expected qualified life of Square D Co contactor coils installed in Category IE equipment. Initially reported on 830119. Coils will be replaced for equipment mfg before 1974 by 830531. MILLIGAN, M. H. Long Island Lighting Co. 83/02/22. HAYNES, R. C. Region 1, Office of Director. 3pp. 17453:246. 24X Fiche: 50-322, 83/02/22, 8303080355.

8303150620 Board Notification 83-26: forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys. Info may affect conclusions re probability of/corrective measures for ATWS. EISENHUT, D. G. Division of Licensing 83/03/03 PALLADINO, N. Commissioners. 24pp. 17584:097. 24X Fiche: 50-000, 83/03/03, 8303150620.

8303140255 Forwards proposed revs to FSAR requested during 830304 discussions w/NRC. Changes consistent w/previous util ltrs & guidance provided in NRC 830218 ltr. Proposed revs will be incorporated into future FSAR amend.
POLLOCK, M. S. Long Island Lighting Co. 83/03/08. EISENHUT, D. G. Division of Licensing. 8pp. 17538:312. 24X Fiche: 50-322, 83/03/08, 8303140255.

T. Hearing transcripts on non-antitrust matters

8303030588 Transcript of 830218 meeting w/util in Bethesda, MD. Pp 1-150.
* NRC - No Detailed Affiliation Given. 83/02/18. 153pp. 17409:092. 24X Fiche: 50-322, 83/02/18, 8303030588.

8303110148 Summary of 830218 meeting w/util in Bethesda, MD re classification of sys, components & structures.
WEINKAM, E. J. Licensing Branch 2. 83/03/03. Licensing Branch 2. 9pp. 17523:149. 24X Fiche: 50-322, 83/03/03, 8303110148.

--8303110156 Transcript of 830218 meeting in Bethesda, MD to discuss clarification of sys, components & structures. Pp 1-150.
* NRC - No Detailed Affiliation Given. 83/02/18. 152pp. 17523:158. 24X Fiche: 50-322, 83/03/03, 8303110148.

8303110227 Supplemental testimony of RJ Mattson, RH Vollmer, CE Rossi, AC Thadani & FD Coffman re Contention 7B, NRC program on Unresolved Safety Issue A-17, "Sys Interaction in Nuclear Power Plants" confirmatory. Certificate of Svc encl.
MATTSON, R. J. Division of Systems Integration (post 811005). VOLLMER, R. H. Division of Engineering. ROSSI, C. E. Instrumentation & Control Systems Branch. 83/03/10. 3pp. 17520:141. 24X Fiche: 50-322, 83/03/10, 8303110227.

8303250157 Supplemental testimony of MW Goldsmith, RB Hubbard & GC Minor on Unresolved Safety Issue A-47, "Sys Interaction" & on safety classification. NRC progress toward resolving A-47 inadequate. Certificate of Svc encl. Related correspondence.
GOLDSMITH, M. W., HUBBARD, R. B., MINOR, G. C. Suffolk County, NY. 83/03/23. 50pp. 17710:002. 24X Fiche: 50-322, 83/03/23, 8303250157.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303210167 Forwards tentative schedule of requests for NRC site visits to conduct operator licensing & instructor certification exams through 1985, in response to Generic Ltr 83-01.
SMITH, J. L. Long Island Lighting Co. 83/03/07. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 17632:181. 24X Fiche: 50-322, 83/03/07, 8303210167.

DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8303020147 Forwards voided cover sheet for TES EP-1-007. All copies of procedure previously transmitted should be destroyed or voided. Cover sheet w/attached procedure should be retained in files.
COOPER, W. E. Teledyne Engineering Services. 83/02/08. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17359:145. 24X Fiche: 50-275, 83/02/08, 8303020147.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303030747 Board Notification 83-13. Forwards EG&G draft rept, "Identification & Ranking of Nuclear Plant Structures, Sys & Components & Graded QA Guidelines."
EISENHUT, D. G. Division of Licensing. 83/02/17. PALLADINO, N. Commissioners. 24pp. 17364:037. 24X Fiche: 50-000, 83/02/17, 8303030747.

8303030710 Board Notification 83-17. Forwards JH Conran 830209 affidavit re changes to previous testimony on Unresolved Safety Issue A-17, "Sys Interaction in Nuclear Power Plants."
EISENHUT, D. G. Division of Licensing. 83/02/18. PALLADINO, N. J., GILINSKY, V., AHEARNE, J. Commissioners. 6pp. 17363:317. 24X Fiche: 50-000, 83/02/18, 8303030710.

8303030382 Forwards status summary of evaluation efforts in progress for independent design verification program. Critical element in completing activities is design verification of containment annulus steel structure & mods to structure.
DIRCKS, W. J. Office of the Executive Director for Operations. 83/02/23. PALLADINO, N. J., GILINSKY, V., AHEARNE, J. F. Commissioners. 8pp. 17365:009. 24X Fiche: 50-275, 83/02/23, 8303030382.

--8303030391 Responds to 830111 ltr re concerns of residents near plant on requirements to be satisfied prior to authorization to load fuel. High level of confidence required on const & design prior to decision to authorize operation.
PALLADINO, N. J. Commissioners. 83/02/17. UDALL, M. K. House of Rep., Interior & Insular Affairs. 7pp. 17365:016. 24X Fiche: 50-275, 83/02/23, 8303030382.

--8303030395 Expresses constituent concerns over possibility of allowing fuel load w/o adequate overall assessment of plant safety.
UDALL, M. K. House of Rep., Interior & Insular Affairs. 83/01/11. PALLADINO, N. J. Commissioners. 4pp. 17365:037. 24X Fiche: 50-275, 83/02/23, 8303030382.

--8303030400 Forwards board notification re adequacy of design of component cooling water sys. New review of sys should be undertaken. Determinations to be provided in SER listed w/o encl.
EISENHUT, D. G. Division of Licensing. 83/02/18. MATTSON, R. Division of Systems Integration (post 811005). 3pp. 17365:041. 24X Fiche: 50-275, 83/02/23, 8303030382.

--8207050037 Requests that Commission be briefed prior to NRR approval for Phase II reverification plan. Monthly status rept also requested.
CHILK, S. J. Office of the Secretary of the Commission. 82/07/27. DIRCKS, W. J. Office of the Executive Director for Operations. 2pp. 17365:044. 24X Fiche: 50-275, 83/02/23, 8303030382.

8303090389 Requests addl info to clarify technical questions & complete confirmatory evaluations for RHR loop 4 & Piping Problems B-11B, per 830223 telcon w/Westinghouse, PG&E & NRC.
REICH, M. Brookhaven National Laboratory. 83/02/24. HARTZMAN, M. NRC - No Detailed Affiliation Given. 1p. 17471:361. 24X Fiche: 50-275, 83/02/24, 8303090389.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303170348 Notifies that WCAP-9804, "Probabilistic Analysis & Operational Data in Response to Item II.K.3.2 for Westinghouse NSSS Plants," contains info & conclusions applicable to both units to satisfy Item II.K.3.2.
CRANE, P. A. Pacific Gas & Electric Co. 83/03/14. KNIGHTON, G. W. Licensing Branch 3. 2pp. 17605:179. 24X Fiche: 50-275, 83/03/14, 8303170348.

8303280137 Comments on Board Notification 83-38 re failure of GE AK-2 reactor trip breakers. Info may affect NRC conclusions re probability/corrective measures for transients w/o scram events (Unresolved Safety Issue A-9).
EISENHUT, D. G. Division of Licensing. 83/03/22. PALLADINO, N., AHEARNE, J. F., ASSELSTINE, T. Commissioners. 20pp. 17709:310. 24X Fiche: 50-000, 83/03/22, 8303280137.

8303290315 Confirms plans to submit schedule for resolution of TMI Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps," by end of May 1983 per Generic Ltr 83-10C.
SCHUYLER, J. O. Pacific Gas & Electric Co. 83/03/24. EISENHUT, D. G. Division of Licensing. 2pp. 17716:150. 24X Fiche: 50-275, 83/03/24, 8303290315.

8303300030 Provides plan for data collection re ECCS component outages, per B10213 commitment to satisfy NUREG-0737, Item II.K.3.17 requirements.
CRANE, P. A. Pacific Gas & Electric Co. 83/03/25. KNIGHTON, G. W. Licensing Branch 3. 2pp. 17731:189. 24X Fiche: 50-275, 83/03/25, 8303300030.

F. Security, medical, emergency & fire protection plans

8303040409 Forwards IE Insp Repts 50-275/83-03 & 50-323/83-02 on 830102-29. No noncompliance noted.
BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs. 83/02/11. CRANE, P. A. Pacific Gas & Electric Co. 2pp. 17374:301. 24X Fiche: 50-275, 83/02/11, 8303040409.

--8303040421 IE Insp Repts 50-275/83-03 & 50-323/83-02 on 830102-29. No noncompliance noted. Major areas inspected: plant operations, surveillance testing, physical security, maint, LER followup & TMI Action Plan Item II.E.4.2.
CARLSON, J. D. Division of Resident, Reactor Project & Engineering Programs. 83/02/10. 4pp. 17374:303. 24X Fiche: 50-275, 83/02/11, 8303040409.

8303210254 Declines NRC 821228 invitation to participate in pilot in-plant drill program. Participation not feasible w/scheduled workload & existing staffing levels.
SCHUYLER, J. O. Pacific Gas & Electric Co. 83/03/14. EISENHUT, D. G. Division of Licensing. 2pp. 17632:175. 24X Fiche: 50-275, 83/03/14, 8303210254.

8303300691 Releases public version of updates to detailed emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/28. Document Management Branch. 1p. 17764:207. 24X Fiche: 50-275, 83/03/28, 8303300691.

--8303300697 Forwards public version of updates to detailed emergency plan implementing procedures, including Procedures EP M-6 re nonradiological fire, EP OR-1 re offsite support & EP O-2 re onsite emergency organization.
CRANE, P. A. Pacific Gas & Electric Co. 83/02/10. ENGELKEN, R. H. Region 5, Office of Director. 2pp. 17764:208. 24X Fiche: 50-275, 83/03/28, 8303300691.

--8303300702 Public version of updates to detailed emergency plan implementing procedures, including Procedures EP M-6 re nonradiological fire, EP OR-1 re offsite support & EP O-2 re onsite emergency organization.
* Pacific Gas & Electric Co. 83/02/04. 60pp. 17764:210. 24X Fiche: 50-275, 83/03/28, 8303300691.

O. Adjudicatory correspondence

8303030462 Advises that LJ Chandler will represent NRC at 830316 oral argument, per ASLAB 830223 order.
CHANDLER, L. J. Hearing Branch 2. 83/03/02. SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 1p. 17409:263. 24X Fiche: 50-275, 83/03/02, 8303030462.

8303080061 Advises that J Reynolds will represent Joint Intervenors at 830316 oral argument.
REYNOLDS, J. R. Center for Law in the Public Interest. REYNOLDS, J. R. Joint Intervenors-Diablo Canyon. 83/03/04. MOORE, T., REED, W., BUCK, J. H. Atomic Safety and Licensing Appeal Panel. 1p. 17452:173. 24X Fiche: 50-275, 83/03/04, 8303080061.

8303080073 Advises that MJ Strumwasser will represent State of CA at 830316 oral argument.
STRUMWASSER, M. California, State of. 83/03/04. SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 1p. 17456:262. 24X Fiche: 50-275, 83/03/04, 8303080073.

8303080114 Advises that B Norton will present argument in response to ASLAB 830223 order.
CRANE, P. A. Pacific Gas & Electric Co. 83/03/04. MOORE, T. S. Atomic Safety and Licensing Appeal Panel. 1p. 17458:245. 24X Fiche: 50-275, 83/03/04, 8303080114.

8303110200 Order rescheduling 830316 oral arguments on appeals from ASLB 820831 initial decision & two motions to reopen record, for 830414, in Bethesda, MD.
TOMPKINS, B. A. Atomic Safety and Licensing Appeal Panel. 83/03/09. 2pp. 17517:353. 24X Fiche: 50-275, 83/03/09, 8303110200.

8303290296 Notice of change of address, effective 830321. Certificate of Svc encl.
NORTON, B. Pacific Gas & Electric Co. NORTON, B. Norton, Burke, Berry & French. 83/03/24. 3pp. 17716:178. 24X Fiche: 50-275, 83/03/24, 8303290296.

H. General correspondence

8303090258 Requests that MJ Strumwasser be placed on distribution list & HH Brown & BS Georgiou be deleted from list, per 830128 notice of substitution.
CRANE, P. A. Pacific Gas & Electric Co. 83/02/07. COOPER, W. E. Teledyne Engineering Services. 1p. 17473:345. 24X Fiche: 50-275, 83/02/07, 8303090258.

8303040137 Responds to concerns expressed in 821224 ltr re discharge of radiation into atmosphere & radioactive releases to Pacific Ocean.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 83/02/18. EVANS, M. California, State of. 17pp. 17425:057. 24X Fiche: 50-275, 83/02/18, 8303040137.

--8303040151 Requests further response to concerns re discharge of radiation into atmosphere & radioactive releases to Pacific Ocean.
EVANS, M. California, State of. 82/12/24. PALLADINO, N. J. Commissioners. 3pp. 17425:070. 24X Fiche: 50-275, 83/02/18, 8303040137.

8303300368 Forwards summary of allegations received from anonymous plant personnel, re containment structure tilting & classification of platform, on behalf of Joint Intervenors.
FLEISCHAKER, D. Affiliation Unknown. 83/03/28. EISENHUT, D. Division of Licensing. 3pp. 17731:028. 24X Fiche: 50-275, 83/03/28, 8303300368.

I. Financial information

8303290345 Forwards Annual Financial Rept 1982.
CRANE, P. A. Pacific Gas & Electric Co. 83/03/25. Office of Nuclear Reactor Regulation, Director. 1p. 17718:123. 24X Fiche: 50-000, 83/03/25, 8303290345.

--8303290349 Annual Financial Rept 1982.
* Pacific Gas & Electric Co. 83/02/16. 40pp. 17718:124. 24X Fiche: 50-000, 83/03/25, 8303290345.

Q. Inspection reports, IE Bulletins & correspondence

8303040409 Forwards IE Insp Repts 50-275/83-03 & 50-323/83-02 on 830102-29. No noncompliance noted.
BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs. 83/02/11. CRANE, P. A. Pacific Gas & Electric Co. 2pp. 17374:301. 24X Fiche: 50-275, 83/02/11, 8303040409.

--8303040421 IE Insp Repts 50-275/83-03 & 50-323/83-02 on 830102-29. No noncompliance noted. Major areas inspected: plant operations, surveillance testing, physical security, maint, LER followup & TMI Action Plan Item II.E.4.2.
CARLSON, J. D., MENDONCA, M. M., KIRSCH, D. F. Division of Resident, Reactor Project & Engineering Programs. 83/02/10. 4pp. 17374:303. 24X Fiche: 50-275, 83/02/11, 8303040409.

8303040447 Forwards IE Insp Repts 50-275/83-04 & 50-323/83-03 on 830125-27. No noncompliance noted.
BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs. 83/02/11. CRANE, P. A. Pacific Gas & Electric Co. 2pp. 17374:015. 24X Fiche: 50-275, 83/02/11, 8303040447.

--8303040454 IE Insp Repts 50-275/83-04 & 50-323/83-03 on 830125-27. No noncompliance noted. Major areas inspected: independent verification program, implementation of QA programs & project procedures.
MORRILL, P. J., ECKHARDT, J. H., KIRSCH, D. F. Division of Resident, Reactor Project & Engineering Programs. 83/02/11. 5pp. 17374:017. 24X Fiche: 50-275, 83/02/11, 8303040447.

8303040469 Forwards final response to IE Bulletin 79-02 re pipe support base plates design, per NRC 820205 request for addl info. Base plate flexibility incorporated in design criteria for pipe supports.
CRANE, P. A. Pacific Gas & Electric Co. 83/02/18. ENGELKEN, R. H. Region 5, Office of Director. 5pp. 17373:330. 24X Fiche: 50-323, 83/02/18, 8303040469.

8303110355 Board Notification 83-14: forwards followup info on apparent deficiencies in Midland-Ross superstrut matl.
EISENHUT, D. G. Division of Licensing. 83/02/18. PALLADINO, N., GILINSKY, V., AHEARNE, J. Commissioners. 24pp. 17546:205. 24X Fiche: 50-000, 83/02/18, 8303110355.

8212060367 IE Bulletin 83-01: "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303290262 Forwards IE Insp Repts 50-275/83-06 & 50-323/83-05 on 830215-18. No noncompliance noted.
BISHOP, T. W. Region 5, Office of Director. 83/03/07. CRANE, P. A. Pacific Gas & Electric Co. 2pp. 17716:082. 24X Fiche: 50-275, 83/03/07, 8303290262.

--8303290271 IE Insp Repts 50-275/83-06 & 50-323/83-05 on 830215-18. No noncompliance noted. Major areas inspected: licensee actions on previously identified items; mods to structural steel & electrical raceway & pipe supports.
BURDOIN, J. F. ; ZWETZIG, G. B. Region 5, Office of Director. 83/03/03. 5pp. 17716:084. 24X Fiche: 50-275, 83/03/07, 8303290262.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303290544 Notifies of 830407 mgt meeting in San Francisco, CA to discuss SALP for Jul 1981 - Dec 1982.
CREWS, J. L. Division of Resident, Reactor Project & Engineering Programs. 83/03/25. CRANE, P. A. Pacific Gas & Electric Co. 3pp. 17725:063. 24X Fiche: 50-275, 83/03/25, 8303290544.

--8303290546 SALP rept for Jul 1981 - Dec 1982.
* Region 5, Office of Director. 83/03/25. 35pp. 17725:066. 24X Fiche: 50-275, 83/03/25, 8303290544.

--8302250060 Forwards NRR input to Cycle 3 SALP evaluation for Jul 1981 - Dec 1982. Overall performance rating of Category 2 determined. Evaluation matrix encl.
BUCKLEY, B. Licensing Branch 3. 83/02/15. EISENHUT, D. G. Division of Licensing. 8pp. 17725:101. 24X Fiche: 50-275, 83/03/25, 8303290544.

R. Periodic operating reports & related correspondence

8303090259 Forwards program manager rept for Jan 1982. Individuals assigned to independent design verification program completed acceptable statement re potential or apparent conflicts of interest.
REEDY, R. F. Reedy, Herbert, Gibbons & Associates. 83/01/28.
COOPER, W. E. Teledyne Engineering Services. 6pp. 17473:339. 24X Fiche: 50-275, 83/01/28, 8303090259.

8303080031 Forwards revised tables consisting of NPDES data, including heavy metal analysis results, inadvertently omitted from annual rept.
THORNBERRY, R. C. Pacific Gas & Electric Co. 83/03/02. JONES, K. R. California, State of. 2pp. 17456:355. 24X Fiche: 50-275, 83/03/02, 8303080031.

--8303080036 Revised tables, consisting of NPDES data, including heavy metal analysis, inadvertently omitted from annual rept.
* Pacific Gas & Electric Co. 83/03/02. 4pp. 17456:357. 24X Fiche: 50-275, 83/03/02, 8303080031.

S. Reportable occurrences, LERs & related correspondence

8303150620 Board Notification 83-26: forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys. Info may affect conclusions re probability of/corrective measures for ATWS.
EISENHUT, D. G. Division of Licensing. 83/03/03. PALLADINO, N. Commissioners. 24pp. 17584:097. 24X Fiche: 50-000, 83/03/03, 8303150620.

T. Hearing transcripts on non-antitrust matters

8303080006 Forwards QA Maneatis testimony to be delivered before House of Representatives, Committee on Interior & Insular Affairs, Subcommittee on Energy & Environ, on 830308.
* Pacific Gas & Electric Co. 83/03/07. NRC - No Detailed Affiliation Given. 1p. 17455:298. 24X Fiche: 50-275, 83/03/07, 8303080006.

--8303080017 Testimony of QA Maneatis re NRC procedures for restoring authority to load fuel, before House of Representatives, Committee on Interior & Insular Affairs, Subcommittee on Energy & Environ. Related correspondence.
MANEATIS, Q. A. Pacific Gas & Electric Co. 83/03/08. 18pp. 17455:299. 24X Fiche: 50-275, 83/03/07, 8303080006.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303090330 Submits estimate of anticipated requests for site visits to conduct operator license exams through Jul 1985, per Generic Ltr 83-01.
CRANE, P. A. Pacific Gas & Electric Co. 83/02/28. EISENHUT, D. G. Division of Licensing. 1p. 17473:178. 24X Fiche: 50-275, 83/02/28, 8303090330.

DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8303090358 Requests appeal meeting re denials on App R fire protection exemption requests, per NRC 830131 ltr. Approval of schedule re installation of mods described in 820630 submittal also requested.
UTLEY, E. E. Carolina Power & Light Co. 83/02/28. EISENHUT, D. G. Division of Licensing. 2pp. 17472:132. 24X Fiche: 50-324, 83/02/28, 8303090358.

8303280011 Submits info re planned vent sys design for emergency operating facilities. Vent sys provides slight positive pressure to bldg, ensuring that any leakage would be from inside bldg to outside atmosphere.
ZIMMERMAN, S. R. Carolina Power & Light Co. 83/03/22. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17707:230. 24X Fiche: 50-000, 83/03/22, 8303280011.

J. Insurance & indemnity information

8303150170 Forwards Endorsement 41 to MAELU Policy MF-80.
BARHAM, C. D. Carolina Power & Light Co. 83/03/11. SALTZMAN, J. Assistant Director for State & Licensee Relations. 2pp. 17555:199. 24X Fiche: 50-324, 83/03/11, 8303150170.

8303150177 Forwards MAELU Certificates M-54 & M-55 & Endorsements 1, 2 & 3 to MAELU Master Policy 1.
BARHAM, C. D. Carolina Power & Light Co. 83/03/11. SALTZMAN, J. Assistant Director for State & Licensee Relations. 19pp. 17549:002. 24X Fiche: 50-324, 83/03/11, 8303150177.

8303150187 Forwards NELIA Certificates N-54 & N-55 & Endorsements 1, 2 & 3 to NELIA Master Policy 1.
BARHAM, C. D. Carolina Power & Light Co. 83/03/11. SALTZMAN, J. Assistant Director for State & Licensee Relations. 19pp. 17555:180. 24X Fiche: 50-324, 83/03/11, 8303150187.

8303150323 Forwards Endorsement 47 to NELIA Policy NF-218.
BARHAM, C. D. Carolina Power & Light Co. 83/03/11. SALTZMAN, J. Assistant Director for State & Licensee Relations. 2pp. 17562:314. 24X Fiche: 50-324, 83/03/11, 8303150323.

8303220344 Submits info re present level & source of onsite property damage insurance.
ZIMMERMAN, S. R. Carolina Power & Light Co. 83/03/18. EISENHUT, D. G. Division of Licensing. 2pp. 17648:357. 24X Fiche: 50-000, 83/03/18, 8303220344.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303010420 Informs that util is reviewing 830121 final rule on environ qualification. NRC will be notified in writing by 830324 whether util will reaffirm or withdraw request for hearing.
UTLEY, E. E. Carolina Power & Light Co. 83/02/21. EISENHUT, D. G. Division of Licensing. 1p. 17343:263. 24X Fiche: 50-324, 83/02/21, 8303010420.

8303030703 Notification of 830307 meeting w/utils & NUS Corp in Bethesda, MD to discuss proposed rev to 10CFR40, Appendix A (Tech Specs).
BRINKMAN, D. S. Standardization & Special Projects Branch. 83/02/22.
THOMAS, C. O. Standardization & Special Projects Branch. 2pp. 17363:227. 24X Fiche: 50-000, 83/02/22, 8303030703.

8303010580 Responds to Structural Engineering Branch 830117 questions re Tech Spec rev request for spent fuel pool expansion. Addl responses will be submitted by 830316. NRC approval of Tech Spec rev requested within 30 days of info submittal.
HURFORD, W. J. Carolina Power & Light Co. 83/02/23 VASSALLO, D. B.
Operating Reactors Branch 2. 3pp. 17336:017. 24X
Fiche: 50-324, 83/02/23, 8303010580.

8303040529 Forwards procedure, "Cable Qualification Test Program Outline, Secondary Containment for Brunswick Steam Electric Plant - Units 1 & 2."
HURFORD, W. J. Carolina Power & Light Co. 83/02/28 VASSALLO, D. B.
Operating Reactors Branch 2. 2pp. 17366:155. 24X
Fiche: 50-324, 83/02/28, 8303040529.

--8303040551 "Cable Qualification Test Program Outline, Secondary Containment for Brunswick Steam Electric Plant - Units 1 & 2."
RHYNE, D. D., WALDORF, J. M., ROTHMON, L. B. Carolina Power & Light Co.
83/02/17. 18pp. 17366:157. 24X Fiche: 50-324, 83/02/28, 8303040529.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303040585 Responds to 820827 ltr requesting addl info re NUREG-0737, Item III. D. 3. 4, "Control Room Habitability." Revised response encl.
HURFORD, W. J. Carolina Power & Light Co. 83/03/02 VASSALLO, D. B.
Operating Reactors Branch 2. 2pp. 17368:354. 24X
Fiche: 50-324, 83/03/02, 8303040585.

--8303040605 "Control Room Habitability Evaluation, Brunswick Steam Electric Plant (NRC TMI Action Item III. D. 3. 4)."
ECKERT, H. J., NATHAN, S. J., POWELL, D. NUS Corp. NUS-3697 R02
83/02/28. 153pp. 17369:003. 24X Fiche: 50-324, 83/03/02, 8303040585.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303160414 Forwards proprietary NF-1583.02 & NF-1583.03 & nonproprietary NF-1583-01, NF-1583.02 & NF-1583.03 re reload analysis methods. Repts will be referenced in licensing applications. Proprietary repts withheld (ref. 10CFR2.790).
ZIMMERMAN, S. R. Carolina Power & Light Co. 83/03/10 VASSALLO, D. B.
Operating Reactors Branch 2. 10pp. 17589:333. 24X
Fiche: 50-324, 83/03/10, 8303160414.

--8303160417 "Description & Validation of Steady-State Analysis Methods for BWRs."
KARCHER, K. E., CANTRELL, W. K., SCHROEDER, D. W. Carolina Power & Light Co. NF-1583.01. 83/02/28. 201pp. 17589:343. 24X
Fiche: 50-324, 83/03/10, 8303160414.

--8303160418 Nonproprietary "Methods of Record - LWR Fuel Assembly Burnup Code."
NAESS, H. K., SKARDHAMAR, T., WENNEMO, S. E. Carolina Power & Light Co.
NF-1583.02. 83/02/28. 169pp. 17590:184. 24X
Fiche: 50-324, 83/03/10, 8303160414.

--8303160421 Nonproprietary "Methods of PRESTO-B - Three-Dimensional LWR Core Simulation Code."
BORRENSEN, S., MOBERG, L., RASMUSSEN, J. Carolina Power & Light Co.
NF-1583.03. 83/02/28. 142pp. 17590:353. 24X
Fiche: 50-324, 83/03/10, 8303160414.

8303290553 Forwards Amends 54 & 79 to Licenses DPR-71 & DPR-62, respectively & notice of issuance & availability. Amends delete Tech Spec conditions re nonradiological water quality-related requirements.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/11 UTLEY, E. E.
Carolina Power & Light Co. 3pp. 17743:200. 24X
Fiche: 50-324, 83/03/11, 8303290553.

--8303290558 Amends 54 & 79 to Licenses DPR-71 & DPR-62, respectively, deleting Tech Spec conditions re nonradiological water quality-related requirements.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/11. 30pp.
17743:203. 24X Fiche: 50-324, 83/03/11, 8303290553.

--8303290562 Notice of issuance & availability of Amends 54 & 79 to Licenses DPR-71 & DPR-62, respectively.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/11. 2pp.
17743:233. 24X Fiche: 50-324, 83/03/11, 8303290553.

8303300047 Forwards orders confirming implementation of post-TMI-related items in NUREG-0737 based on commitments in response to Generic Ltrs 82-05 & 10.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/14. UTLEY, E. E.
Carolina Power & Light Co. 3pp. 17751:102. 24X
Fiche: 50-324, 83/03/14, 8303300047.

--8303300072 Order confirming licensee commitments on post-TMI-related issues in NUREG-0737.
PURPLE, R. A. Division of Licensing. 83/03/14. Carolina Power & Light Co. 21pp. 17751:105. 24X Fiche: 50-324, 83/03/14, 8303300047.

8303240533 Provides justification that present automatic depressurization sys (ADS) logic provides best response capabilities considering relative probability of need for blowdown in transient w/o LOCA.
HOWE, P. W. Carolina Power & Light Co. 83/03/17. VASSALLO, D. B.
Operating Reactors Branch 2. 3pp. 17682:308. 24X
Fiche: 50-324, 83/03/17, 8303240533.

8303300441 Summary of 830309 meeting w/util & Raychem Corp. in Bethesda, MD re environ qualification of Raychem cable.
MACKAY, S. D. Operating Reactors Branch 2. 83/03/21. Operating Reactors Branch 2. 4pp. 17753:304. 24X Fiche: 50-324, 83/03/21, 8303300441.

8303300625 Comments on proposed qualification tests of Raychem Flamtrol cable. Radiation & thermal aging must be conducted in air atmosphere.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/22. UTLEY, E. E.
Carolina Power & Light Co. 2pp. 17767:005. 24X
Fiche: 50-324, 83/03/22, 8303300625.

8303290491 Withdraws request for hearing re NRC order imposing environ qualification requirements for facilities. Withdrawal predicated on interpretation of final rule on environ qualification. Notification to contrary requested by 830524.
UTLEY, E. E. Carolina Power & Light Co. 83/03/24. EISENHUT, D. G.
Division of Licensing. 2pp. 17724:338. 24X Fiche: 50-000, 83/03/24, 8303290491.

8303310235 Advises that retyped Tech Specs distributed for use at facilities. Amended & retyped pages indicated at bottom of each page.
HOWE, P. W. Carolina Power & Light Co. 83/03/28. VASSALLO, D. B.
Operating Reactors Branch 2. 2pp. 17763:039. 24X
Fiche: 50-324, 83/03/28, 8303310235.

G. Inspection reports, IE Bulletins & correspondence

8303210615 Submits final response to violations noted in IE Insp Repts 50-324/82-23 & 50-325/82-23. Corrective actions: all boundaries currently under review to assure proper sys classification. Review will be completed by 830331.
DIETZ, C. R. Carolina Power & Light Co. 82/12/31. O'REILLY, J. P.
Region 2, Office of Director. 2pp. 17636:285. 24X
Fiche: 50-324, 82/12/31, 8303210615.

8303010159 Supplis 821216 response to IE Bulletin 82-03, Rev 1, "Stress Corrosion Cracking in Thick Wall, Large Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants." List of RHR sys welds being tested encl.
HOWE, P. W. Carolina Power & Light Co. 83/02/07. O'REILLY, J. P.
Region 2, Office of Director. 3pp. 17335:355. 24X
Fiche: 50-324, 83/02/07, 8303010159.

8303010314 Supplis response to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Sys Components by Corbicula Sp (Asiatic clam) & Mytilus Sp (mussel)." Insp & testing program established on safety sys w/shell problem.
HOWE, P. W. Carolina Power & Light Co. 83/02/10. O'REILLY, J. P.
Region 2, Office of Director. 2pp. 17333:324. 24X
Fiche: 50-324, 83/02/10, 8303010314.

8303210403 Forwards IE Insp Repts 50-324/83-06 & 50-325/83-06 on 820928-830117. No noncompliance noted.
VERRELLI, D. M. Division of Project & Resident Programs. 83/02/14.
UTLEY, E. E. Carolina Power & Light Co. 2pp. 17634:301. 24X
Fiche: 50-324, 83/02/14, 8303210403.

--8303210409 IE Insp Repts 50-324/83-06 & 50-325/83-06 on 820928-830117. No noncompliance noted. Major areas inspected: personnel exposure.
PEERY, W. W., BARR, K. P. Region 2, Office of Director. 83/02/03.
3pp. 17634:303. 24X Fiche: 50-324, 83/02/14, 8303210403.

8303210323 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Bunker-Ramo penetrations not used at plant.
HOWE, P.W. Carolina Power & Light Co. 83/02/16. O'REILLY, J.P. Region 2, Office of Director. 2pp. 17632:053. 24X
Fiche: 50-324, 83/02/16, 8303210323.

8303090166 Discusses IE insp on 820712-14 & 20-22 & forwards notice of violation & proposed imposition of civil penalty.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 83/02/18. UTLEY, E.E. Carolina Power & Light Co. 4pp. 17465:026. 24X Fiche: 50-324, 83/02/18, 8303090166.

--8303090176 Notice of violation & proposed imposition of civil penalty in amount of $600,000. Noncompliance noted: procedures for surveillance test, insp & calibr not established or maintained. Problems not corrected adequately.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 83/02/18. 6pp. 17465:030. 24X
Fiche: 50-324, 83/02/18, 8303090166.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

R Periodic operating reports & related correspondence

8303080151 Forwards monthly operating repts for Dec 1982.
DIETZ, C.R. Carolina Power & Light Co. 83/01/10. DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 1p. 17457:311. 24X Fiche: 50-324, 83/01/10, 8303080151.

--8303080158 Monthly operating repts for Dec 1982.
HARRISON, F. Carolina Power & Light Co. 83/01/31. 10pp. 17457:312. 24X Fiche: 50-324, 83/01/10, 8303080151.

8303150362 Forwards monthly operating repts for Feb 1983.
DIETZ, C.R. Carolina Power & Light Co. 83/03/07. DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 1p. 17562:304. 24X Fiche: 50-324, 83/03/07, 8303150362.

--8303150369 Monthly operating repts for Feb 1983.
HARRISON, F. Carolina Power & Light Co. 83/03/08. 9pp. 17562:305. 24X Fiche: 50-324, 83/03/07, 8303150362.

S Reportable occurrences, LERs & related correspondence

8303010188 Forwards LER 83-011/03L-0.
DIETZ, C.R. Carolina Power & Light Co. 83/02/18. O'REILLY, J.P. Region 2, Office of Director. 1p. 17332:356. 24X
Fiche: 50-324, 83/02/18, 8303010188.

--8303010197 LER 83-011/03L-0: on 830120, RHR reactor pressure low annunciation received. Caused by electrical resistor & relay failure in instrument N021C. Instrument replaced.
PASTVA, M.J. Carolina Power & Light Co. 83/02/18. Region 2, Office of Director. 1p. 17332:357. 24X Fiche: 50-324, 83/02/18, 8303010188.

8303010394 Forwards LER 83-010/03L-0.
DIETZ, C.R. Carolina Power & Light Co. 83/02/18. O'REILLY, J.P. Region 2, Office of Director. 1p. 17346:205. 24X
Fiche: 50-324, 83/02/18, 8303010394.

--8303010400 LER 83-010/03L-0: on 830119, during plant operation, both doors of reactor bldg 20-ft elevation personnel air lock opened simultaneously. Caused by misalignment of inner door due to normal wear preventing proper bolt engagement.
PASTVA, M.J. Carolina Power & Light Co. 83/02/18. Region 2, Office of Director. 1p. 17346:206. 24X Fiche: 50-324, 83/02/18, 8303010394.

8303010514 Forwards LER 83-012/03L-0.
DIETZ, C.R. Carolina Power & Light Co. 83/02/18. O'REILLY, J.P. Region 2, Office of Director. 1p. 17337:211. 24X
Fiche: 50-324, 83/02/18, 8303010514.

--8303010522 LER 83-012/03L-0: on 830121, surveillance revealed control air pressure of diesel generator 3 below Tech Spec limit. Caused by crud accumulation in diesel control air moisture drain trap filter. Filter replaced.
PASTVA, M.J. Carolina Power & Light Co. 83/02/18. Region 2, Office of Director. 2pp. 17337:212. 24X Fiche: 50-324, 83/02/18, 8303010514.

8303010278 Forwards LER 83-013/03L-0.
DIETZ, C.R. Carolina Power & Light Co. 83/02/21. O'REILLY, J.P. Region 2, Office of Director. 1p. 17335:190. 24X
Fiche: 50-324, 83/02/21, 8303010278.

--8303010282 LER 83-013/03L-0: on 830122, rod block monitor B inoperable annunciator received when control rod 30-35 selected. Caused by three defective dual operational amplifier IC chips on fifth first-level multiplexer card. Card replaced.
PASTVA, M.J. Carolina Power & Light Co. 83/02/21. Region 2, Office of Director. 1p. 17335:191. 24X Fiche: 50-324, 83/02/21, 8303010278.

8303040365 Forwards LER 83-015/03L-0.
DIETZ, C.R. Carolina Power & Light Co. 83/02/22. O'REILLY, J.P. Region 2, Office of Director. 1p. 17420:019. 24X
Fiche: 50-324, 83/02/22, 8303040365.

--8303040380 LER 83-015/03L-0: on 830123, reactor recirculation pump 2A tripped. Caused by ATWS reactor pressure instrument 2-B21-PS-N045C actuation below Tech Spec limit. Instrument replaced.
PASTVA, M.J. Carolina Power & Light Co. 83/02/22. Region 2, Office of Director. 1p. 17420:020. 24X Fiche: 50-324, 83/02/22, 8303040365.

8303140562 Forwards LER 83-018/03L-0.
DIETZ, C.R. Carolina Power & Light Co. 83/02/25. O'REILLY, J.P. Region 2, Office of Director. 1p. 17541:047. 24X
Fiche: 50-324, 83/02/25, 8303140562.

--8303140567 LER 83-018/03L-0: on 830126, RHR A HX svc water outlet flow control valve 2-E11-F068A could not be opened using RTGB controller. Caused by loose coupler in valve position modulator circuit feedback potentiometer. Coupler fastened.
PASTVA, M.J. Carolina Power & Light Co. 83/02/25. Region 2, Office of Director. 1p. 17541:048. 24X Fiche: 50-324, 83/02/25, 8303140562.

8303210368 Forwards LER 83-017/03L-0.
DIETZ, C.R. Carolina Power & Light Co. 83/02/25. O'REILLY, J.P. Region 2, Office of Director. 1p. 17634:361. 24X
Fiche: 50-324, 83/02/25, 8303210368.

--8303210374 LER 83-017/03L-0: on 830126, during standby gas treatment sys heater check, one heater element in treatment sys A found inoperable. Caused by damaged power supply cable terminal lug ring. Lugs checked for proper tightness.
PASTVA, M.J. Carolina Power & Light Co. 83/02/25. Region 2, Office of Director. 1p. 17634:362. 24X Fiche: 50-324, 83/02/25, 8303210368.

8303210700 RO: on 830210, alternate power supplies lost for both motor-driven & diesel-driven fire pumps. Subsequent review determined that original surveillance had incorrectly recorded battery voltage. Event considered nonreportable.
DIETZ, C.R. Carolina Power & Light Co. 83/02/25. O'REILLY, J.P. Region 2, Office of Director. 1p. 17635:292. 24X
Fiche: 50-324, 83/02/25, 8303210700.

8303210314 Forwards LER 83-019/01T-0.
DIETZ, C.R. Carolina Power & Light Co. 83/02/28. O'REILLY, J.P. Region 2, Office of Director. 1p. 17632:058. 24X
Fiche: 50-324, 83/02/28, 8303210314.

--8303210318 LER 83-019/01T-0: on 830210, while performing drywell insp, instrument air tubing to safety relief & ADS valve accumulators inadequately supported. Caused by inadequate controls to ensure support design compliance.
PASTVA, M.J. Carolina Power & Light Co. 83/02/28. Region 2, Office of Director. 2pp. 17632:059. 24X Fiche: 50-324, 83/02/28, 8303210314.

8303210315 Forwards LER 83-020/03L-0.
DIETZ, C. R. Carolina Power & Light Co. 83/03/01 O'REILLY, J. P.
Region 2, Office of Director. 1p. 17632:051. 24X
Fiche: 50-324, 83/03/01, 8303210315.

--8303210317 LER 83-020/03L-0 on 830129, primary containment atmosphere oxygen analyzer 2-CAC-AT-1263-2 indicated 0.5% step decrease in drywell oxygen concentration. Caused by zero shift in instrument magnetic analyzer 1263-2 Analyzer replaced.
PASTVA, M. J. Carolina Power & Light Co. 83/03/01 Region 2, Office of Director. 1p. 17632:052. 24X Fiche: 50-324, 83/03/01, 8303210315.

8303140302 Forwards LER 83-022/03L-0.
DIETZ, C. R. Carolina Power & Light Co. 83/03/03 O'REILLY, J. P.
Region 2, Office of Director. 1p. 17535:039. 24X
Fiche: 50-324, 83/03/03, 8303140302.

--8303140310 LER 83-022/03L-0 on 830201, primary containment atmosphere oxygen/hydrogen monitor 2-CAC-ATH-1259 showed erratic indications of drywell concentrations. Caused by water accumulation in sample lines. Water removed.
PASTVA, M. J. Carolina Power & Light Co. 83/03/03 Region 2, Office of Director. 1p. 17535:040. 24X Fiche: 50-324, 83/03/03, 8303140302.

8303160230 Forwards LER 83-023/03L-0.
DIETZ, C. R. Carolina Power & Light Co. 83/03/04 O'REILLY, J. P.
Region 2, Office of Director. 1p. 17596:348. 24X
Fiche: 50-324, 83/03/04, 8303160230.

--8303160242 LER 83-023/03L-0 on 830203, during reactor shutdown, intermediate range monitor (IRM) E did not give onscale indication until IRM range switch was on position 2. Caused by failed bearing & binding in detector drive mechanism.
PASTVA, M. J. Carolina Power & Light Co. 83/03/04 Region 2, Office of Director. 1p. 17596:349. 24X Fiche: 50-324, 83/03/04, 8303160230.

8303160278 Forwards LER 83-027/03L-0.
DIETZ, C. R. Carolina Power & Light Co. 83/03/04 O'REILLY, J. P.
Region 2, Office of Director. 1p. 17596:338. 24X
Fiche: 50-324, 83/03/04, 8303160278.

--8303160286 LER 83-027/03L-0 on 830216, primary containment atmosphere oxygen analyzer 2-CAC-AT-1263-2 indicated erroneous drywell oxygen concentration. Caused by instrument drift. Analyzer recalibr.
PASTVA, M. J. Carolina Power & Light Co. 83/03/04 Region 2, Office of Director. 1p. 17596:339. 24X Fiche: 50-324, 83/03/04, 8303160278.

8303160490 Forwards LER 83-025/03L-0.
DIETZ, C. R. Carolina Power & Light Co. 83/03/07 O'REILLY, J. P.
Region 2, Office of Director. 1p. 17592:325. 24X
Fiche: 50-324, 83/03/07, 8303160490.

--8303160497 LER 83-025/03L-0 on 830216, closed position indication for drywell to suppression pool vacuum breaker X18C could not be achieved. Caused by problem w/vacuum breaker closed position limit switch LS-240-794. Problem will be investigated.
PASTVA, M. J. Carolina Power & Light Co. 83/03/07 Region 2, Office of Director. 1p. 17592:326. 24X Fiche: 50-324, 83/03/07, 8303160490.

8303160576 Forwards LER 83-014/03L-0.
DIETZ, C. R. Carolina Power & Light Co. 83/03/07 O'REILLY, J. P.
Region 2, Office of Director. 1p. 17587:015. 24X
Fiche: 50-324, 83/03/07, 8303160576.

--8303160582 LER 83-014/03L-0 on 830216, primary containment atmosphere oxygen analyzer 2-CAC-AT-1259-2 showed drywell oxygen concentration 1% higher than indicated by redundant analyzer. Caused by instrument drift. Analyzer recalibr.
PASTVA, M. J. Carolina Power & Light Co. 83/03/07 Region 2, Office of Director. 1p. 17587:016. 24X Fiche: 50-324, 83/03/07, 8303160576.

8303180213 Forwards updated LER 81-022/03L-1.
DIETZ, C. R. Carolina Power & Light Co. 83/03/10 O'REILLY, J. P.
Region 2, Office of Director. 1p. 17617:345. 24X
Fiche: 50-324, 83/03/10, 8303180213.

--8303180218 Updated LER 81-022/03L-1 on 810607, primary containment atmospheric control suppression pool level indicator, 2-CAC-LI-2601-3, gave erratic indication level. Caused by blockage in water supply throttle valve.
PASTVA, M. J. Carolina Power & Light Co. 83/03/10 Region 2, Office of Director. 2pp. 17617:346. 24X Fiche: 50-324, 83/03/10, 8303180213.

8303180201 Forwards LER 83-021/03L-0.
DIETZ, C. R. Carolina Power & Light Co. 83/03/11 O'REILLY, J. P.
Region 2, Office of Director. 1p. 17616:001. 24X
Fiche: 50-324, 83/03/11, 8303180201.

--8303180232 LER 83-021/03L-0 on 830301, HPCI sys declared inoperable when instrument 2E41-dPIS-N005 showed negative indication while redundant instrument 2E41-dPIS-N004 indicated zero. Caused by instrument drift. N005 calibr & returned to svc.
PASTVA, M. J. Carolina Power & Light Co. 83/03/11 Region 2, Office of Director. 1p. 17616:002. 24X Fiche: 50-324, 83/03/11, 8303180201.

8303180274 RO limiting conditions for operation, issued on 830213, 19 & 20 to permit work in control & svc water bldgs required for plant mods, exceeded 7-day specified time frame.
DIETZ, C. R. Carolina Power & Light Co. 83/03/11 O'REILLY, J. P.
Region 2, Office of Director. 1p. 17621:091. 24X
Fiche: 50-324, 83/03/11, 8303180274.

8303180339 Forwards supplemental LER 82-131/03L-1.
DIETZ, C. R. Carolina Power & Light Co. 83/03/11 O'REILLY, J. P.
Region 2, Office of Director. 1p. 17619:329. 24X
Fiche: 50-324, 83/03/11, 8303180339.

--8303180367 Supplemental LER 82-131/03L-1 on 821206, one-half automatic reactor scram signal received due to instrument downscale signal from main steam line radiation monitor D, 2-D12-RM-K603D. Caused by disconnection of instrument cable.
PASTVA, M. J. Carolina Power & Light Co. 83/03/11 Region 2, Office of Director. 1p. 17619:330. 24X Fiche: 50-324, 83/03/11, 8303180339.

8303180402 Forwards LER 83-031/03L-0.
DIETZ, C. R. Carolina Power & Light Co. 83/03/11 O'REILLY, J. P.
Region 2, Office of Director. 1p. 17621:361. 24X
Fiche: 50-324, 83/03/11, 8303180402.

--8303180411 LER 83-031/03L-0 on 830223, performance of suppression pool level indicators operability test revealed indicator/recover level, redundant indicators & local level indicator levels incompatible. Caused by loss of trickle flow.
PASTVA, M. J. Carolina Power & Light Co. 83/03/11 Region 2, Office of Director. 1p. 17621:362. 24X Fiche: 50-324, 83/03/11, 8303180402.

8303240494 Forwards LER 83-029/03L-0.
DIETZ, C. R. Carolina Power & Light Co. 83/03/17 O'REILLY, J. P.
Region 2, Office of Director. 1p. 17678:094. 24X
Fiche: 50-324, 83/03/17, 8303240494.

--8303240505 LER 83-029/03L-0 on 830220, routine surveillance during plant operation revealed audible evidence of airflow through both doors of reactor bldg 50-ft elevation. Caused by 1 1/2 inch diameter hole in outer door. Hole in door sealed.
PASTVA, M. J. Carolina Power & Light Co. 83/03/17 Region 2, Office of Director. 1p. 17678:095. 24X Fiche: 50-324, 83/03/17, 8303240494.

V. Operator Examinations
---

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303090350 Submits projected requests for site visits to conduct operator license exams through Dec 1985, in response to Generic Ltr 83-01.
ZIMMERMAN, S. R. Carolina Power & Light Co. 83/03/02 EISENHUT, D. G. Division of Licensing 2pp. 17472:138. 24X Fiche: 50-000, 83/03/02, 8303090350.

DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1
---
F. Security, medical, emergency & fire protection plans
---

8303090358 Requests appeal meeting re denials on App R fire protection exemption requests, per NRC 830131 ltr. Approval of schedule re installation of mods described in 820630 submittal also requested.
UTLEY, E. E. Carolina Power & Light Co. 83/02/28 EISENHUT, D. G. Division of Licensing 2pp. 17472:132. 24X Fiche: 50-324, 83/02/28, 8303090358.

8303280011 Submits info re planned vent sys design for emergency operating facilities. Vent sys provides slight positive pressure to bldg, ensuring that any leakage would be from inside bldg to outside atmosphere.
ZIMMERMAN, S. R. Carolina Power & Light Co. 83/03/22. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17707:230.
24X Fiche: 50-000, 83/03/22, 8303280011.

J. Insurance & indemnity information

8303150170 Forwards Endorsement 41 to MAELU Policy MF-80.
BARHAM, C. D. Carolina Power & Light Co. 83/03/11. SALTZMAN, J. Assistant Director for State & Licensee Relations. 2pp. 17555:199.
24X Fiche: 50-324, 83/03/11, 8303150170.

8303150177 Forwards MAELU Certificates M-54 & M-55 & Endorsements 1, 2 & 3 to MAELU Master Policy 1.
BARHAM, C. D. Carolina Power & Light Co. 83/03/11. SALTZMAN, J. Assistant Director for State & Licensee Relations. 19pp. 17549:002.
24X Fiche: 50-324, 83/03/11, 8303150177.

8303150187 Forwards NELIA Certificates N-54 & N-55 & Endorsements 1, 2 & 3 to NELIA Master Policy 1.
BARHAM, C. D. Carolina Power & Light Co. 83/03/11. SALTZMAN, J. Assistant Director for State & Licensee Relations. 19pp. 17555:180.
24X Fiche: 50-324, 83/03/11, 8303150187.

8303150323 Forwards Endorsement 47 to NELIA Policy NF-218.
BARHAM, C. D. Carolina Power & Light Co. 83/03/11. SALTZMAN, J. Assistant Director for State & Licensee Relations. 2pp. 17562:314.
24X Fiche: 50-324, 83/03/11, 8303150323.

8303220344 Submits info re present level & source of onsite property damage insurance.
ZIMMERMAN, S. R. Carolina Power & Light Co. 83/03/18. EISENHUT, D. G. Division of Licensing. 2pp. 17648:357. 24X Fiche: 50-000, 83/03/18, 8303220344.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303010420 Informs that util is reviewing 830121 final rule on environ qualification. NRC will be notified in writing by 830324 whether util will reaffirm or withdraw request for hearing.
UTLEY, E. E. Carolina Power & Light Co. 83/02/21. EISENHUT, D. G. Division of Licensing. 1p. 17743:263. 24X Fiche: 50-324, 83/02/21, 8303010420.

8303030703 Notification of 830307 meeting w/utils & NUS Corp in Bethesda, MD to discuss proposed rev to 10CFR40, Ap (Tech Specs).
BRINKMAN, D. S. Standardization & Special Projects Branch. 83/02/22.
THOMAS, C. O. Standardization & Special Projects Branch. 2pp. 17363:227. 24X Fiche: 50-000, 83/02/22, 8303030703.

8303010580 Responds to Structural Engineering Branch 830117 questions re Tech Spec rev request for spent fuel pool expansion. Addl responses will be submitted by 830316. NRC approval of Tech Spec rev requested within 30 days of info submittal.
HURFORD, W. J. Carolina Power & Light Co. 83/02/23. VASSALLO, D. B. Operating Reactors Branch 2. 3pp. 17336:017. 24X
Fiche: 50-324, 83/02/23, 8303010580.

8303010452 Revises schedule for cutting & capping control rod drive return line to next refueling outage, scheduled for 1984.
UTLEY, E. E. Carolina Power & Light Co. 83/02/24. VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 17346:185. 24X
Fiche: 50-325, 83/02/24, 8303010452.

8303040529 Forwards procedure, "Cable Qualification Test Program Outline, Secondary Containment for Brunswick Steam Electric Plant - Units 1 & 2."
HURFORD, W. J. Carolina Power & Light Co. 83/02/28. VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 17366:155. 24X
Fiche: 50-324, 83/02/28, 8303040529.

--8303040551 "Cable Qualification Test Program Outline, Secondary Containment for Brunswick Steam Electric Plant - Units 1 & 2."
RHYNE, D. D., WALDORF, J. M., ROTHMON, L. B. Carolina Power & Light Co. 83/02/17. 18pp. 17366:157. 24X Fiche: 50-324, 83/02/28, 8303040529.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303040585 Responds to 820827 ltr requesting addl info re NUREG-0737, Item III.D.3.4, "Control Room Habitability." Revised response encl.
HURFORD, W. J. Carolina Power & Light Co. 83/03/02. VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 17368:354. 24X
Fiche: 50-324, 83/03/02, 8303040585.

--8303040605 "Control Room Habitability Evaluation, Brunswick Steam Electric Plant (NRC TMI Action Item III.D.3.4)."
ECKERT, H. J., NATHAN, S. J., POWELL, D. NUS Corp. NUS-3697, R02. 83/02/28. 153pp. 17369:003. 24X Fiche: 50-324, 83/03/02, 8303040585.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 5pp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303160414 Forwards proprietary NF-1583.02 & NF-1583.03 & nonproprietary NF-1583-01, NF-1583.02 & NF-1583.03 re reload analysis methods. Repts will be referenced in licensing applications. Proprietary repts withheld (ref 10CFR2.790).
ZIMMERMAN, S. R. Carolina Power & Light Co. 83/03/10. VASSALLO, D. B. Operating Reactors Branch 2. 10pp. 17589:333. 24X
Fiche: 50-324, 83/03/10, 8303160414.

--8303160417 "Description & Validation of Steady-State Analysis Methods for BWRs."
KARCHER, K. E., CANTRELL, W. K., SCHROEDER, D. W. Carolina Power & Light Co. NF-1583.01. 83/02/28. 201pp. 17589:343. 24X
Fiche: 50-324, 83/03/10, 8303160414.

--8303160418 Nonproprietary "Methods of Record - LWR Fuel Assembly Burnup Code."
NAESS, H. K., SKARDHAMAR, T., WENNEMO, S. E. Carolina Power & Light Co. NF-1583.02. 83/02/28. 169pp. 17590:184. 24X
Fiche: 50-324, 83/03/10, 8303160414.

--8303160421 Nonproprietary "Methods of PRESTO-B - Three-Dimensional LWR Core Simulation Code."
BORRENSEN, S., MOBERG, L., RASMUSSEN, J. Carolina Power & Light Co. NF-1583.03. 83/02/28. 142pp. 17590:353. 24X
Fiche: 50-324, 83/03/10, 8303160414.

8303290553 Forwards Amends 54 & 79 to Licenses DPR-71 & DPR-62, respectively, & notice of issuance & availability. Amends delete Tech Spec conditions re nonradiological water quality-related requirements.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/11. UTLEY, E. E. Carolina Power & Light Co. 3pp. 17743:200. 24X
Fiche: 50-324, 83/03/11, 8303290553.

--8303290558 Amends 54 & 79 to Licenses DPR-71 & DPR-62, respectively, deleting Tech Spec conditions re nonradiological water quality-related requirements.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/11. 30pp. 17743:203. 24X Fiche: 50-324, 83/03/11, 8303290553.

--8303290562 Notice of issuance & availability of Amends 54 & 79 to Licenses DPR-71 & DPR-62, respectively.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/11. 2pp. 17743:233. 24X Fiche: 50-324, 83/03/11, 8303290553.

8303300047 Forwards orders confirming implementation of post-TMI-related items in NUREG-0737 based on commitments in response to Generic Ltrs 82-05 & 10.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/14. UTLEY, E. E. Carolina Power & Light Co. 3pp. 17751:102. 24X
Fiche: 50-324, 83/03/14, 8303300047.

--8303300072 Order confirming licensee commitments on post-TMI-related issues in NUREG-0737.
PURPLE, R. A. Division of Licensing. 83/03/14. Carolina Power & Light Co. 21pp. 17751:105. 24X Fiche: 50-324, 83/03/14, 8303300047.

8303290534 Forwards Amend 55 to License DPR-71, safety evaluation & notice of issuance & availability. Amend permits postponement of flow test of core spray until 48 h after restoration of suppression chamber to operable status.
MACKAY, S. D. Operating Reactors Branch 2. 83/03/15. UTLEY, E. E. Carolina Power & Light Co. 2pp. 17742:201. 24X
Fiche: 50-325, 83/03/15, 8303290534.

--8303290538 Amend 55 to License DPR-71, permitting postponement of flow test for core spray sys until 48 h after restoration of suppression chamber to operable status.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/15. 4pp.
17742:203. 24X Fiche: 50-325, 83/03/15, 8303290534.

--8303290540 Safety evaluation supporting Amend 55 to License DPR-71.
* Office of Nuclear Reactor Regulation, Director. 83/03/15. 3pp.
17742:207. 24X Fiche: 50-325, 83/03/15, 8303290534.

--8303290543 Notice of issuance & availability of Amend 55 to License DPR-71.
ROONEY, V. L. Operating Reactors Branch 2. 83/03/15. 2pp.
17742:210. 24X Fiche: 50-325, 83/03/15, 8303290534.

8303240533 Provides justification that present automatic depressurization sys (ADS) logic provides best response capabilities considering relative probability of need for blowdown in transient w/o LOCA.
HOWE, P. W. Carolina Power & Light Co. 83/03/17. VASSALLO, D. B. Operating Reactors Branch 2. 3pp. 17682:308. 24X Fiche: 50-324, 83/03/17, 8303240533.

8303300625 Comments on proposed qualification tests of Raychem Flamtrol cable. Radiation & thermal aging must be conducted in air atmosphere.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/22. UTLEY, E. E. Carolina Power & Light Co. 2pp. 17767:005. 24X Fiche: 50-324, 83/03/22, 8303300625.

8303290491 Withdraws request for hearing re NRC order imposing environ qualification requirements for facilities. Withdrawal predicated on interpretation of final rule on environ qualification. Notification to contrary requested by 830524.
UTLEY, E. E. Carolina Power & Light Co. 83/03/24. EISENHUT, D. G. Division of Licensing. 2pp. 17724:338. 24X Fiche: 50-000, 83/03/24, 8303290491.

8303310235 Advises that retyped Tech Specs distributed for use at facilities. Amended & retyped pages indicated at bottom of each page.
HOWE, P. W. Carolina Power & Light Co. 83/03/28. VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 17763:039. 24X Fiche: 50-324, 83/03/28, 8303310235.

Q. Inspection reports, IE Bulletins & correspondence

8303210615 Submits final response to violations noted in IE Insp Repts 50-324/82-23 & 50-325/82-23. Corrective actions, all boundaries currently under review to assure proper sys classification. Review will be completed by 830331.
DIETZ, C. R. Carolina Power & Light Co. 82/12/31. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17636:285. 24X Fiche: 50-324, 82/12/31, 8303210615.

8303010159 Supplis 821216 response to IE Bulletin 82-03, Rev 1, "Stress Corrosion Cracking in Thick Wall, Large Diameter, Stainless Steel Recirculation Sys Piping at BWR Plants." List of RHR sys welds being tested encl.
HOWE, P. W. Carolina Power & Light Co. 83/02/07. O'REILLY, J. P. Region 2, Office of Director. 5pp. 17335:355. 24X Fiche: 50-324, 83/02/07, 8303010159.

8303010314 Supplis response to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safetu Sys Components by Corbicula Sp (Asiatic clam) & Mytilus Sp (mussel)." Insp & testing program established on safety sys w/shell problem.
HOWE, P. W. Carolina Power & Light Co. 83/02/10. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17333:324. 24X Fiche: 50-324, 83/02/10, 8303010314.

8303210403 Forwards IE Insp Repts 50-324/83-06 & 50-325/83-06 on 820928-830117. No noncompliance noted.
VERRELLI, D. M. Division of Project & Resident Programs. 83/02/14. UTLEY, E. E. Carolina Power & Light Co. 2pp. 17634:301. 24X Fiche: 50-324, 83/02/14, 8303210403.

--8303210409 IE Insp Repts 50-324/83-06 & 50-325/83-06 on 820928-830117. No noncompliance noted. Major areas inspected: personnel exposure.
PEERY, W. W., BARR, K. P. Region 2, Office of Director. 83/02/03. 3pp. 17634:303. 24X Fiche: 50-324, 83/02/14, 8303210403.

8303210323 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Bunker-Ramo penetrations not used at plant.
HOWE, P. W. Carolina Power & Light Co. 83/02/16. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17632:053. 24X Fiche: 50-324, 83/02/16, 8303210323.

8303090166 Discusses IE insp on 820712-14 & 20-22 & forwards notice of violation & proposed imposition of civil penalty.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/18. UTLEY, E. E. Carolina Power & Light Co. 4pp.
17465:026. 24X Fiche: 50-324, 83/02/18, 8303090166.

--8303090176 Notice of violation & proposed imposition of civil penalty in amount of $600,000. Noncompliance noted: procedures for surveillance test, insp & calibr not established or maintained. Problems not corrected adequately.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/18. 6pp. 17465:030. 24X Fiche: 50-324, 83/02/18, 8303090166.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 12lpp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

R. Periodic operating reports & related correspondence

8303080151 Forwards monthly operating repts for Dec 1982.
DIETZ, C. R. Carolina Power & Light Co. 83/01/10. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 1p.
17457:311. 24X Fiche: 50-324, 83/01/10, 8303080151.

--8303080158 Monthly operating repts for Dec 1982.
HARRISON, F. Carolina Power & Light Co. 83/01/31. 10pp.
17457:312. 24X Fiche: 50-324, 83/01/10, 8303080151.

8303150362 Forwards monthly operating repts for Feb 1983.
DIETZ, C. R. Carolina Power & Light Co. 83/03/07. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 1p.
17562:304. 24X Fiche: 50-324, 83/03/07, 8303150362.

--8303150369 Monthly operating repts for Feb 1983.
HARRISON, F. Carolina Power & Light Co. 83/03/08. 9pp.
17562:305. 24X Fiche: 50-324, 83/03/07, 8303150362.

S. Reportable occurrences, LERs & related correspondence

8302010586 Forwards updated LER 82-143/03L-1.
DIETZ, C. R. Carolina Power & Light Co. 83/01/26. O'REILLY, J. P. Region 2, Office of Director. 1p. 16978:170. 24X Fiche: 50-325, 83/01/26, 8302010586.

--8302010596 Updated LER 82-143/03L-1 on 821123, 50-ft elevation inner doors (fire doors) of personnel secondary containment airlocks would not self-close w/door closers. Caused by excessive leakage past seals. Doors sealed & adjusted.
PASTVA, M. J. Carolina Power & Light Co. 83/01/26. Region 2, Office of Director. 1p. 16978:171. 24X Fiche: 50-325, 83/01/26, 8302010586.

8303010373 Forwards LER 83-005/03L-0.
DIETZ, C. R. Carolina Power & Light Co. 83/02/18. O'REILLY, J. P. Region 2, Office of Director. 1p. 17345:124. 24X Fiche: 50-325, 83/02/18, 8303010373.

--8303010377 LER 83-005/03L-0 on 830119, during normal operation, measured specific gravity of pilot cell for Div I battery 1A-1 was 1.166 & 1.167 for Div II battery 1B-1. Caused by age of pilot cells. Cells replaced. Batteries returned to svc.
PASTVA, M. J. Carolina Power & Light Co. 83/02/18. Region 2, Office of Director. 1p. 17345:125. 24X Fiche: 50-325, 83/02/18, 8303010373.

8303010381 Forwards LER 83-010/03L-0.
DIETZ, C. R. Carolina Power & Light Co. 83/02/18. O'REILLY, J. P. Region 2, Office of Director. 1p. 17343:173. 24X Fiche: 50-325, 83/02/18, 8303010381.

--8303010384 LER 83-010/03L-0: on 830120, routine surveillance revealed water leaking into reactor bldg at 17-ft elevation via secondary containment penetration/fire barrier seal R1-1-049. Caused by degradation due to exposure to rainwater. PASTVA, M. J. Carolina Power & Light Co. 83/02/18. Region 2, Office of Director. 1p. 17343:174. 24X Fiche: 50-325, 83/02/18, 8303010381.

8303010477 Forwards LER 83-006/03L-0. DIETZ, C. R. Carolina Power & Light Co. 83/02/18. O'REILLY, J. P. Region 2, Office of Director. 1p. 17343:112. 24X Fiche: 50-325, 83/02/18, 8303010477.

--8303010486 LER 83-006/03L-0: on 830119, insert withdrawal position & drive power indication discovered inoperable. Caused by blown power supply fuse F13. Fuse MIN 10 replaced & work request & authorization written. PASTVA, M. J. Carolina Power & Light Co. 83/02/18. Region 2, Office of Director. 1p. 17343:113. 24X Fiche: 50-325, 83/02/18, 8303010477.

8303010271 Forwards LER 83-007/03L-0. DIETZ, C. R. Carolina Power & Light Co. 83/02/21. O'REILLY, J. P. Region 2, Office of Director. 1p. 17335:097. 24X Fiche: 50-325, 83/02/21, 8303010271.

--8303010275 LER 83-007/03L-0: on 830123, routine surveillance revealed one fuel bundle located around each of withdrawn control rods 22-15, 34-23, 34-27 & 26-43. Caused by procedural deficiency. Rods inserted & procedure revised. POULK, R. M. Carolina Power & Light Co. 83/02/21. Region 2, Office of Director. 4pp. 17335:098. 24X Fiche: 50-325, 83/02/21, 8303010271.

8303210477 Forwards LER 83-009/03L-0. DIETZ, C. R. Carolina Power & Light Co. 83/02/25. O'REILLY, J. P. Region 2, Office of Director. 1p. 17631:299. 24X Fiche: 50-325, 83/02/25, 8303210477.

--8303210490 LER 83-009/03L-0: on 830127, average power range monitors C & E determined inoperable due to too few operable LPRM inputs. Caused by control rod drive undervessel work during outage inadvertently damaging cables. PASTVA, M. J. Carolina Power & Light Co. 83/02/25. Region 2, Office of Director. 1p. 17631:300. 24X Fiche: 50-325, 83/02/25, 8303210477.

8303210324 Forwards updated LER 83-006/03L-1. DIETZ, C. R. Carolina Power & Light Co. 83/02/28. O'REILLY, J. P. Region 2, Office of Director. 1p. 17632:049. 24X Fiche: 50-325, 83/02/28, 8303210324.

--8303210326 Updated LER 83-006/03L-1: on 830119, insert/withdrawal position & drive power indication for source range & immediate range monitors discovered inoperable. Caused by blown control power supply fuse F13. Fuse replaced. PASTVA, M. J. Carolina Power & Light Co. 83/02/28. Region 2, Office of Director. 1p. 17632:050. 24X Fiche: 50-325, 83/02/28, 8303210324.

8303210428 Forwards updated LER 83-007/03L-1. DIETZ, C. R. Carolina Power & Light Co. 83/02/28. O'REILLY, J. P. Region 2, Office of Director. 1p. 17634:215. 24X Fiche: 50-325, 83/02/28, 8303210428.

--8303210445 Updated LER 83-007/03L-1: on 830123, during extended refueling outage, one fuel bundle located around control rods 22-15, 34-23, 34-27 & 26-43. Caused by procedual inadequacy. Rods inserted & procedure revised. POULK, R. M. Carolina Power & Light Co. 83/02/28. Region 2, Office of Director. 4pp. 17634:216. 24X Fiche: 50-325, 83/02/28, 8303210428.

8303160207 RO: on 830127, discovered water leak into southeast corner of diesel generator bldg 2-ft elevation via two fire barrier penetration seals. Caused by degradation due to exposure to rainwater originating from underground plant cable vault. DIETZ, C. R. Carolina Power & Light Co. 83/03/03. O'REILLY, J. P. Region 2, Office of Director. 1p. 17596:297. 24X Fiche: 50-325, 83/03/03, 8303160207.

8303160348 RO: on 830213, fire barrier penetration limiting conditions for operation generated on fire barrier penetration located in 20-ft elevation east wall of svc water bldg to permit installation of temporary power supply cables. DIETZ, C. R. Carolina Power & Light Co. 83/03/04. O'REILLY, J. P. Region 2, Office of Director. 1p. 17595:317. 24X Fiche: 50-325, 83/03/04, 8303160348.

8303180311 Forwards LER 83-008/03L-0. DIETZ, C. R. Carolina Power & Light Co. 83/03/11. O'REILLY, J. P. Region 2, Office of Director. 1p. 17621:061. 24X Fiche: 50-325, 83/03/11, 8303180311.

--8303180335 LER 83-008/03L-0: on 830212, exhaust inboard isolation damper 1C-BFIV-RB had dual open-close position indication when closed & exhaust dampers failed to close within required time. Caused by open limit switch sticking. PASTVA, M. J. Carolina Power & Light Co. 83/03/11. Region 2, Office of Director. 2pp. 17621:062. 24X Fiche: 50-325, 83/03/11, 8303180311.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303090350 Submits projected requests for site visits to conduct operator license exams through Dec 1985, in response to Generic Ltr 83-01. ZIMMERMAN, S. R. Carolina Power & Light Co. 83/03/02. EISENHUT, D. G. Division of Licensing. 2pp. 17472:138. 24X Fiche: 50-000, 83/03/02, 8303090350.

DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8303100035 Releases public version of Rev 4 to radiological emergency plan. FELTON, J. M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17522:059. 24X Fiche: 50-327, 83/03/02, 8303100035.

--8303100043 Forwards public version of Rev 4 to radiological emergency plan, including App F, "TN Multijurisdictional Radiological Emergency Response Plan." KAMMER, D. S. Tennessee Valley Authority. 83/01/25. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17522:061. 24X Fiche: 50-327, 83/03/02, 8303100035.

--8303100046 Public version of Rev 4 to radiological emergency plan, including App F, "TN Multijurisdictional Radiological Emergency Response Plan." * Tennessee Valley Authority. 82/11/05. 273pp. 17522:062. 24X Fiche: 50-327, 83/03/02, 8303100035.

8303100044 Releases public version of revised radiological emergency plan implementing procedures. FELTON, J. M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17493:110. 24X Fiche: 50-327, 83/03/02, 8303100044.

--8303100049 Forwards public version of revised radiological emergency plan implementing procedures, including Procedures IP-1 re emergency plan classification logic, IP-3 re alert & IP-4 re site area emergency. MILLS, L. M. Tennessee Valley Authority. 83/02/10. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17493:111. 24X Fiche: 50-327, 83/03/02, 8303100044.

--8303100053 Public version of revised radiological emergency plan implementing procedures, including Procedures IP-1 re emergency plan classification logic, IP-3 re alert & IP-4 re site area emergency. WALKER, J. R., HARDING, M. R., KITTS, R. J. Tennessee Valley Authority. 83/02/09. 73pp. 17493:112. 24X Fiche: 50-327, 83/03/02, 8303100044.

8303150388 Forwards IE Safeguards Insp Repts 50-327/83-02 & 50-328/83-02 on 830213-17. No noncompliance noted. VERRELLI, D. Division of Project & Resident Programs. 83/03/04. PARRIS, H. G. Tennessee Valley Authority. 2pp. 17562:015. 24X Fiche: 50-327, 83/03/04, 8303150388.

--8303150401 IE Safeguards Insp Repts 50-327/83-02 & 50-328/83-02 on 830213-17. No noncompliance noted. Major areas inspected: security plan & implementing procedures, organization & mgt & personnel. Details withheld (ref 10CFR73.21). MOORE, D. E. Region 2, Office of Director. MCGUIRE, D. R. Division of Emergency Preparedness & Materials Safety. 83/03/04. 1p. 17562:017. 24X Fiche: 50-327, 83/03/04, 8303150388.

8303180530 Application for amend to Licenses DPR-77 & DPR-79, changing Tech Specs re reassignment of responsibility for annual mgt directive issuance, physical security audit frequency & site radiological emergency plan rev frequency. MILLS, L. M. Tennessee Valley Authority. 83/03/15. ADENSAM, E. Licensing Branch 4. 2pp. 17621:268. 24X Fiche: 50-327, 83/03/15, 8303180530.

--8303180537 Proposed Tech Specs re reassignment of responsibility for annual mgt directive issuance, physical security audit frequency & site radiological plan rev frequency.
* Tennessee Valley Authority. 83/03/15. 13pp. 17621:270. 24X Fiche: 50-327, 83/03/15, 8303180530.

8303310024 Releases public version of revised emergency plan implementing procedures.
FELTON, J.M. Division of Rules and Records. 83/03/25. Document Management Branch. 1p. 17780:256. 24X Fiche: 50-327, 83/03/25, 8303310024.

--8303310028 Forwards public version of revised emergency plan implementing procedures, including Procedures IP-2 re notification of unusual event, IP-3 re alert & IP-4 re site area emergency.
MILLS, L.M. Tennessee Valley Authority. 83/03/17. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 17780:257. 24X Fiche: 50-327, 83/03/25, 8303310024.

--8303310036 Public version of revised emergency plan implementing procedures, including Procedures IP-2 re notification of unusual event, IP-3 re alert & IP-4 re site area emergency.
* Tennessee Valley Authority. 83/03/04. 30pp. 17780:258. 24X Fiche: 50-327, 83/03/25, 8303310024.

J. Insurance & indemnity information

8303290423 Forwards Endorsement 31 to NELIA Policy NF-247.
DUCK, J.R. Marsh & McLennan, Inc. 83/03/15. SALTZMAN, J. Assistant Director for State & Licensee Relations. 2pp. 17726:297. 24X Fiche: 50-327, 83/03/15, 8303290423.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8303100107 Forwards NRR response to ACRS recommendations following 271st & 272nd meetings, per 821208 & 830107 memos.
GOODWIN, E.F. Technical Support Branch. 83/02/15. FRALEY, R.F. ACRS - Advisory Committee on Reactor Safeguards. 5pp. 17504:036. 24X Fiche: 50-000, 83/02/15, 8303100107.

--8301180041 Forwards list of requests made at 272nd ACRS meeting on 821209-11 per agreement to provide summary of actions, agreements, assignments & requests made at each full ACRS meeting.
FRALEY, R.F. ACRS - Advisory Committee on Reactor Safeguards. 83/01/05. DIRCKS, W.J. Office of the Executive Director for Operations. 4pp. 17504:041. 24X Fiche: 50-000, 83/02/15, 8303100107.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D.G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D.G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303100295 Requests refund re 800121 & 1124 application for amends to OLs. Amends authorizing onsite storage of radwaste applicable to 10CFR30 licenses. Amend fee not required.
MILLS, L.M. Tennessee Valley Authority. 83/03/03. MILLER, W.O. License Fee Management Branch. 1p. 17489:295. 24X Fiche: 50-000, 83/03/03, 8303100295.

8303090343 Requests License Condition 2.C.(24) be revised w/respect to Rev 2 of Reg Guide 1.97, "Instrumentation for Light Water Cooled Nuclear Power Plants to Access Plant Conditions During & Following Accident."
MILLS, L.M. Tennessee Valley Authority. 83/03/04. ADENSAM, E. Licensing Branch 4. 3pp. 17472:140. 24X Fiche: 50-327, 83/03/04, 8303090343.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D.G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303140234 Forwards response to Generic Ltr 82-28 re inadequate core cooling instrumentation sys per NUREG-0737, Item II.F.2 requirements.
MILLS, L.M. Tennessee Valley Authority. 83/03/06. ADENSAM, E. Licensing Branch 4. 2pp. 17538:345. 24X Fiche: 50-327, 83/03/06, 8303140234.

8303230443 Forwards Amends 26 & 15 to Licenses DPR-77 & DPR-79, respectively, safety evaluation & notice of issuance & availability. Amends change Tech Specs re rod position indication sys, in response to NRC 820816 ltr.
ADENSAM, E.G. Licensing Branch 4. 83/03/14. PARRIS, H.G. Tennessee Valley Authority. 2pp. 17674:088. 24X Fiche: 50-327, 83/03/14, 8303230443.

--8303230446 Amends 26 & 15 to Licenses DPR-77 & DPR-79, respectively, changing Tech Specs re rod position indication sys.
ADENSAM, E.G. Licensing Branch 4. 83/03/14. 8pp. 17674:090. 24X Fiche: 50-327, 83/03/14, 8303230443.

--8303230449 Safety evaluation supporting Amends 26 & 15 to Licenses DPR-77 & DPR-79, respectively.
* Office of Nuclear Reactor Regulation, Director. 83/03/14. 3pp. 17674:098. 24X Fiche: 50-327, 83/03/14, 8303230443.

--8303230454 Notice of issuance & availability of Amends 26 & 15 to Licenses DPR-77 & DPR-79, respectively.
ADENSAM, E.G. Licensing Branch 4. 83/03/14. 3pp. 17674:101. 24X Fiche: 50-327, 83/03/14, 8303230443.

8303180530 Application for amend to Licenses DPR-77 & DPR-79, changing Tech Specs re reassignment of responsibility for annual mgt directive issuance, physical security audit frequency & site radiological emergency plan rev frequency.
MILLS, L.M. Tennessee Valley Authority. 83/03/15. ADENSAM, E. Licensing Branch 4. 2pp. 17621:268. 24X Fiche: 50-327, 83/03/15, 8303180530.

--8303180537 Proposed Tech Specs re reassignment of responsibility for annual mgt directive issuance, physical security audit frequency & site radiological plan rev frequency.
* Tennessee Valley Authority. 83/03/15. 13pp. 17621:270. 24X Fiche: 50-327, 83/03/15, 8303180530.

8303220296 Application for amend to Licenses DPR-77 & DPR-79, revising Tech Specs to change limiting condition for operation of carbon dioxide sys.
MILLS, L.M. Tennessee Valley Authority. 83/03/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 17656:123. 24X Fiche: 50-327, 83/03/16, 8303220296.

--8303220303 Proposed Tech Specs re carbon dioxide sys.
* Tennessee Valley Authority. 83/03/16. 4pp. 17656:125. 24X Fiche: 50-327, 83/03/16, 8303220296.

8303230425 Forwards Amends 27 & 16 to Licenses DPR-77 & DPR-79, respectively, safety evaluation & notice of issuance & availability. Amends extend time interval required to conduct analog channel operational tests of ESF actuation sys.
ADENSAM, E.G. Licensing Branch 4. 83/03/16. PARRIS, H.G. Tennessee Valley Authority. 2pp. 17674:143. 24X Fiche: 50-327, 83/03/16, 8303230425.

--8303230431 Amends 27 & 16 to Licenses DPR-77 & DPR-79, respectively, extending time interval required to conduct ESF actuation & reactor trip sys from 1 to 3 months.
ADENSAM, E.G. Licensing Branch 4. 83/03/16. 19pp. 17674:145. 24X Fiche: 50-327, 83/03/16, 8303230425.

--8303230433 Safety evaluation supporting Amends 27 & 16 to Licenses DPR-77 & DPR-79, respectively.
* Office of Nuclear Reactor Regulation, Director. 83/03/16. 3pp. 17674:164. 24X Fiche: 50-327, 83/03/16, 8303230425.

--8303230438 Notice of issuance & availability of Amends 27 & 16 to Licenses DPR-77 & DPR-79, respectively.
ADENSAM, E.G. Licensing Branch 4. 83/03/16. 3pp. 17674:167. 24X Fiche: 50-327, 83/03/16, 8303230425.

8303220156 Confirms 830307 telcon re acceptance criteria for surveillance requirement for emergency gas treatment sys charcoal filters.
MILLS, L.M. Tennessee Valley Authority. 83/03/18. ADENSAM, E. Licensing Branch 4. 1p. 17658:155. 24X Fiche: 50-327, 83/03/18, 8303220156.

8303220162 Forwards changes to NPDES Permit TN0026450 & State of TN Section 401 of Federal Water Pollution Control Act Certification per ETS Section 5.5.2.
MILLS, L.M. Tennessee Valley Authority. 83/03/18. ADENSAM, E. Licensing Branch 4. 63pp. 17658:309. 24X Fiche: 50-327, 83/03/18, 8303220162.

8303280045 Forwards equipment qualification sheets & supporting documentation on acoustic monitors for PORV & SV position indication, per TMI Action Plan Item II.D.3, in response to 820125 request.
MILLS, L. M. Tennessee Valley Authority 83/03/22 ADENSAM, E. Licensing Branch 4 9pp 17707:303 24X Fiche: 50-327, 83/03/22, 8303280045.

8303300125 Application for amend to Licenses DPR-77 & DPR-79, changing upper head injection accumulator water level setpoint & tolerances.
MILLS, L. M. Tennessee Valley Authority 83/03/28 ADENSAM, E. Licensing Branch 4 1p 17731:200 24X Fiche: 50-327, 83/03/28, 8303300125.

--8303300131 Proposed Tech Specs changing upper head injection accumulator water level setpoint & tolerances.
* Tennessee Valley Authority 83/03/28 4pp 17731:201 24X Fiche: 50-327, 83/03/28, 8303300125.

8303300666 Forwards addl guidance for use in preparing required reporting of offsite doses to public for 1982.
ADENSAM, E. G. Licensing Branch 4 83/03/28 PARRIS, H. G. Tennessee Valley Authority 4pp 17768:284 24X Fiche: 50-327, 83/03/28, 8303300666.

Q. Inspection reports, IE Bulletins & correspondence

8303010511 Forwards IE Insp Repts 50-327/82-36 & 50-328/82-35 on 821206-830105. No noncompliance noted.
VERRELLI, D. M. Division of Project & Resident Programs 83/02/02
PARRIS, H. G. Tennessee Valley Authority 2pp 17337:214 24X
Fiche: 50-327, 83/02/02, 8303010511.

--8303010523 IE Insp Repts 50-327/82-36 & 50-328/82-35 on 821206-830105. No noncompliance noted. Major areas inspected: operational safety verification, refueling outage, LER review, IE bulletin closeout & independent insp effort.
FORD, E. J. ; BUTLER, S. D. Region 2, Office of Director
FREDRICKSON, P. Division of Project & Resident Programs 83/02/01
7pp 17337:216 24X Fiche: 50-327, 83/02/02, 8303010511.

8303010429 Ack receipt of 830202 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-35 & 50-328/82-34.
VERRELLI, D. M. Division of Project & Resident Programs 83/02/10
PARRIS, H. G. Tennessee Valley Authority 1p 17343:138 24X
Fiche: 50-327, 83/02/10, 8303010429.

--8303010433 Responds to NRC 830106 ltr re violations noted in IE Insp Repts 50-327/82-35 & 50-328/82-34. Corrective actions: current rev to NRC Form-3, "Notice to Employees," posted on 821216.
KAMMER, D. S. Tennessee Valley Authority 83/02/02 O'REILLY, J. P.
Region 2, Office of Director 2pp 17343:139 24X
Fiche: 50-327, 83/02/10, 8303010429.

--8303010438 Forwards IE Insp Repts 50-327/82-35 & 50-328/82-34 on 821213-17 & notice of violation.
VERRELLI, D. M. Division of Project & Resident Programs 83/01/06
PARRIS, H. G. Tennessee Valley Authority 2pp 17343:141 24X
Fiche: 50-327, 83/02/10, 8303010429.

--8303010445 Notice of violation from insp on 821213-17.
* Division of Project & Resident Programs 83/01/06 1p
17343:143 24X Fiche: 50-327, 83/02/10, 8303010429.

--8303010453 IE Insp Repts 50-327/82-35 & 50-328/82-34 on 821213-17. Noncompliance noted: current copies of Form NRC-3, "Notice to Employees," not posted.
COLLINS, T. R. Region 2, Office of Director BARR, K. P. Division of Engineering & Radiological Safety Programs 83/01/05 6pp
17343:144 24X Fiche: 50-327, 83/02/10, 8303010429.

8303010399 Forwards final response to IE Bulletin 80-20, "Adequate Min Flow Through Centrifugal Charging Pumps." Actions ensure min flow requirements maintained at all times.
MILLS, L. M. Tennessee Valley Authority 83/02/14 O'REILLY, J. P.
Region 2, Office of Director 6pp 17346:207 24X
Fiche: 50-327, 83/02/14, 8303010399.

8303010284 Responds to NRC 820602 request for addl info re IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants." Action Item 2 requirements for Unit 2 will be performed during refueling outage scheduled for Fall 1983.
MILLS, L. M. Tennessee Valley Authority 83/02/18 O'REILLY, J. P.
Region 2, Office of Director 2pp 17335:196 24X
Fiche: 50-327, 83/02/18, 8303010284.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc.
11lpp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210414 Ack receipt of 830216 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-16 & 50-328/82-16.
LEWIS, R. C. Division of Project & Resident Programs 83/02/25
PARRIS, H. G. Tennessee Valley Authority 1p 17634:333 24X
Fiche: 50-327, 83/02/25, 8303210414.

--8303210422 Responds to NRC 820820 ltr re violations noted in IE Insp Repts 50-327/82-16 & 50-328/82-16. Util expects to be in full compliance on or before 830225. Issuance of procedure for escalated corrective program to be completed by 830218.
MILLS, L. M. Tennessee Valley Authority 83/02/16 O'REILLY, J. P.
Region 2, Office of Director 1p 17634:334 24X
Fiche: 50-327, 83/02/25, 8303210414.

8303150388 Forwards IE Safeguards Insp Repts 50-327/83-02 & 50-328/83-02 on 830213-17. No noncompliance noted.
VERRELLI, D. Division of Project & Resident Programs 83/03/04
PARRIS, H. G. Tennessee Valley Authority 2pp 17562:015 24X
Fiche: 50-327, 83/03/04, 8303150388.

--8303150401 IE Safeguards Insp Repts 50-327/83-02 & 50-328/83-02 on 830213-17. No noncompliance noted. Major areas inspected: security plan & implementing procedures, organization & mgt & personnel. Details withheld (ref 10CFR73.21).
MOORE, D. E. Region 2, Office of Director MCGUIRE, D. R. Division of Emergency Preparedness & Materials Safety 83/03/04 1p
17562:017 24X Fiche: 50-327, 83/03/04, 8303150388.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc.
117pp 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

R. Periodic operating reports & related correspondence

8303090216 Forwards "Effluent & Waste Disposal Semiannual Rept, Jan-June 1981."
BALLENTINE, J. M. Tennessee Valley Authority 81/08/31 Region 2, Atlanta, Office of the Director (81/03/01) 1p 17471:130 24X
Fiche: 50-327, 81/08/31, 8303090216.

--8303090220 "Effluent & Waste Disposal Semiannual Rept, Jan-June 1981."
* Tennessee Valley Authority 81/08/31 104pp 17471:131 24X
Fiche: 50-327, 81/08/31, 8303090216.

8303080368 Forwards monthly operating repts for Dec 1982.
MASON, C. C. Tennessee Valley Authority 83/01/14 Office of Resource Management, Director 1p 17492:054 24X
Fiche: 50-327, 83/01/14, 8303080368.

--8303080377 Monthly operating repts for Dec 1982.
EDDINGS, M. G. ; DUPREE, D. C. ; MASON, C. C. Tennessee Valley Authority
83/01/11 13pp 17492:055 24X Fiche: 50-327, 83/01/14, 8303080368.

8303150463 Forwards monthly operating repts for Jan 1983.
MASON, C. C. Tennessee Valley Authority 83/02/14 Office of Resource Management, Director 1p 17568:118 24X
Fiche: 50-327, 83/02/14, 8303150463.

--8303150464 Monthly operating repts for Jan 1983.
MASON, C. C. ; EDDINGS, M. Tennessee Valley Authority 83/02/08
39pp 17568:119 24X Fiche: 50-327, 83/02/14, 8303150463.

8303150440 Forwards revised monthly operating rept for Jan 1983.
MASON, C. C. Tennessee Valley Authority 83/02/16 Office of Resource Management, Director 1p 17562:258 24X
Fiche: 50-327, 83/02/16, 8303150440.

--8303150445 Revised monthly operating rept for Jan 1983
EDDINGS, M. Tennessee Valley Authority. 83/02/16. 2pp.
17562:259. 24X Fiche: 50-327, 83/02/16, 8303150440.

8303100326 Forwards "Effluent & Waste Disposal Semiannual Rept, Supplemental Info, Jul-Dec 1982."
MASON, C. C. Tennessee Valley Authority. 83/03/01. Director's Office, Office of Inspection and Enforcement. 1p. 17489:199. 24X
Fiche: 50-327, 83/03/01, 8303100326.

--8303100331 "Effluent & Waste Disposl Semiannual Rept, Supplemental Info, Jul-Dec 1982."
* Tennessee Valley Authority. 83/03/01. 23pp. 17489:200. 24X
Fiche: 50-327, 83/03/01, 8303100326.

8303160216 Central emergency control ctr meteorological data statistics for Oct-Dec 1982, reported per util commitment to NUREG-0737, Item III.A.2.1.
MILLS, L. M. Tennessee Valley Authority. 83/03/09. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17596:323.
24X Fiche: 50-000, 83/03/09, 8303160216.

S. Reportable occurrences, LERs & related correspondence

8303040579 Forwards NPDES noncompliance notification.
TRAINA, P. J. Environmental Protection Agency. 83/02/16. WENE, R. Tennessee-American Water Co. 3pp. 17374:063. 24X
Fiche: 50-327, 83/02/16, 8303040579.

--8303040586 NPDES noncompliance notification: determined that Natl Pollutant Discharge Elimination Sys permit should be issued w/no substantial changes from tentative determinations previously announced.
TRAINA, P. J. Environmental Protection Agency. 83/02/16. 2pp. 17374:064. 24X Fiche: 50-327, 83/02/16, 8303040579.

8303210299 Forwards LER 83-019/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/03/02. O'REILLY, J. P. Region 2, Office of Director. 1p. 17632:044. 24X
Fiche: 50-327, 83/03/02, 8303210299.

--8303210308 LER 83-019/03L-0 on 830202, RPI for rod D-14 of shutdown bank A declared inoperable due to bottom light going on & off. Caused by open primary cable circuit due to loose connector on reactor head. Connector tightened & RPI returned to svc.
KULISEK, D. A., HARDING, M. R. Tennessee Valley Authority. 83/03/02. Region 2, Office of Director. 1p. 17632:045. 24X
Fiche: 50-327, 83/03/02, 8303210299.

8303210462 Forwards LER 83-018/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/03/02. O'REILLY, J. P. Region 2, Office of Director. 1p. 17634:160. 24X
Fiche: 50-327, 83/03/02, 8303210462.

--8303210469 LER 83-018/03L-0 on 830201, containment internal differential pressure exceeded 0.3 psig relative to annulus pressure. Caused by failure of emergency gas treatment sys suction damper to open causing high vacuum in annulus.
ROGERS, H. R., HARDING, M. R. Tennessee Valley Authority. 83/03/02. Region 2, Office of Director. 1p. 17634:161. 24X
Fiche: 50-327, 83/03/02, 8303210462.

8303140492 Forwards LER 83-016/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/03/03. O'REILLY, J. P. Region 2, Office of Director. 1p. 17540:312. 24X
Fiche: 50-327, 83/03/03, 8303140492.

--8303140501 LER 83-016/03L-0 on 830205, ice condenser temp monitoring sys recorder in main control room declared inoperable. Print head assembly, Westronics Model M11-E, failed upscale. Cause unknown. New recorder installed.
KULISEK, D. A., HARDING, M. R. Tennessee Valley Authority. 83/03/03. Region 2, Office of Director. 1p. 17540:313. 24X
Fiche: 50-327, 83/03/03, 8303140492.

8303140526 Forwards LER 83-020/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/03/03. O'REILLY, J. P. Region 2, Office of Director. 1p. 17533:352. 24X
Fiche: 50-327, 83/03/03, 8303140526.

--8303140539 LER 83-020/03L-0 on 830203, leak rate testing not performed within 24 h of stroking containment purge isolation valves. Caused by personnal error. Unit operator signoff added to SI-166.1.
KULISEK, D. A., HARDING, M. R. Tennessee Valley Authority. 83/03/03. Region 2, Office of Director. 1p. 17533:353. 24X
Fiche: 50-327, 83/03/03, 8303140526.

8303140548 Forwards LER 83-021/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/03/03. O'REILLY, J. P. Region 2, Office of Director. 1p. 17534:050. 24X
Fiche: 50-327, 83/03/03, 8303140548.

--8303140554 LER 83-021/03L-0 on 830205, during performance of Surveillance Instruction 16, channel 1199 & 1115 of boron injection tank piping discovered inoperable. Caused by failed Thermon Mfg controller. Fuse & relay replaced.
LUDWIG, W. C., HARDING, M. R. Tennessee Valley Authority. 83/03/03. Region 2, Office of Director. 1p. 17534:051. 24X
Fiche: 50-327, 83/03/03, 8303140548.

8303110375 NPDES noncompliance notification on 830223, grab sample collected from concrete batch plant settling pond contained 53 mg/L total suspended solids. Caused by rainfall runoff vol exceeding treatment capacity of pool. No action taken.
EL-ASHRY, M. T. Tennessee Valley Authority. 83/03/08. MARLAR, J. Environmental Protection Agency. 2pp. 17506:243. 24X
Fiche: 50-327, 83/03/08, 8303110375.

8303150472 Forwards LER 83-022/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/03/09. O'REILLY, J. P. Region 2, Office of Director. 1p. 17568:249. 24X
Fiche: 50-327, 83/03/09, 8303150472.

--8303150475 LER 83-022/03L-0 on 830211, two of four level switches found out of tolerance. Caused by instrument drift & inadequate calibr & testing techniques. Switches recalibr.
LUDWIG, W. C., HARDING, M. R. Tennessee Valley Authority. 83/03/09. Region 2, Office of Director. 1p. 17568:250. 24X
Fiche: 50-327, 83/03/09, 8303150472.

8303240410 Forwards LER 83-029/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/03/18. O'REILLY, J. P. Region 2, Office of Director. 1p. 17679:063. 24X
Fiche: 50-327, 83/03/18, 8303240410.

--8303240412 LER 83-029/03L-0 on 830219, ice condenser lower inlet door zone D limit switches indicated open door. Caused by misadjustment of microswitch limit switch model LSH1A for ice condenser bays 9 & 11. Limit switches adjusted.
LUDWIG, W. C., HARDING, M. R. Tennessee Valley Authority. 83/03/18. Region 2, Office of Director. 1p. 17679:064. 24X
Fiche: 50-327, 83/03/18, 8303240410.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303080442 Submits schedule for NRC operator licensing exam site visits through 1985, in response to Generic Ltr 83-01. Exams on 830815-19 for Watts Bar requested to be postponed due to delay in final fuel loading date.
MILLS, L. M. Tennessee Valley Authority. 83/02/28. ADENSAM, E. Licensing Branch 4. 2pp. 17454:256. 24X Fiche: 50-000, 83/02/28, 8303080442.

X. Onsite Storage of Low Level Waste

8303100295 Requests refund re 800121 & 1124 application for amends to OLs. Amends authorizing onsite storage of radwaste applicable to 10CFR30 licenses. Amend fee not required.
MILLS, L. M. Tennessee Valley Authority. 83/03/03. MILLER, W. O. License Fee Management Branch. 1p. 17489:295. 24X
Fiche: 50-000, 83/03/03, 8303100295.

DOCKET 50-328 SEQUOYAH NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8303100035 Releases public version of Rev 4 to radiological emergency plan.
FELTON, J. M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17522:059. 24X Fiche: 50-327, 83/03/02, 8303100035.

--8303100043 Forwards public version of Rev 4 to radiological emergency plan, including App F, "TN Multijurisdictional Radiological Emergency Response Plan."
KAMMER, D. S. Tennessee Valley Authority. 83/01/25. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17522:061.
24X Fiche: 50-327, 83/03/02, 8303100035.

--8303100046 Public version of Rev 4 to radiological emergency plan, including App F, "TN Multijurisdictional Radiological Emergency Response Plan."
* Tennessee Valley Authority. 82/11/05. 273pp. 17522:062. 24X Fiche: 50-327, 83/03/02, 8303100035.

8303100044 Releases public version of revised radiological emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17493:110. 24X Fiche: 50-327, 83/03/02, 8303100044.

--8303100049 Forwards public version of revised radiological emergency plan implementing procedures, including Procedures IP-1 re emergency plan classification logic, IP-3 re alert & IP-4 re site area emergency.
MILLS, L. M. Tennessee Valley Authority. 83/02/10. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17493:111. 24X Fiche: 50-327, 83/03/02, 8303100044.

--8303100053 Public version of revised radiological emergency plan implementing procedures, including Procedures IP-1 re emergency plan classification logic, IP-3 re alert & IP-4 re site area emergency.
WALKER, J. R.; HARDING, M. R.; KITTS, R. J. Tennessee Valley Authority. 83/02/09. 73pp. 17493:112. 24X Fiche: 50-327, 83/03/02, 8303100044.

8303150388 Forwards IE Safeguards Insp Repts 50-327/83-02 & 50-328/83-02 on 830213-17. No noncompliance noted. Major areas inspected: security plan & implementing procedures, organization & mgt & personnel. Details withheld (ref 10CFR73.21).
VERRELLI, D. Division of Project & Resident Programs. 83/03/04. PARRIS, H. G. Tennessee Valley Authority. 2pp. 17562:015. 24X Fiche: 50-327, 83/03/04, 8303150388.

--8303150401 IE Safeguards Insp Repts 50-327/83-02 & 50-328/83-02 on 830213-17. No noncompliance noted. Major areas inspected: security plan & implementing procedures, organization & mgt & personnel. Details withheld (ref 10CFR73.21).
MOORE, D. E. Region 2, Office of Director. 83/03/04. 1p. 17562:017. 24X Fiche: 50-327, 83/03/04, 8303150388.

8303180530 Application for amend to Licenses DPR-77 & DPR-79, changing Tech Specs re reassignment of responsibility for annual mgt directive issuance, physical security audit frequency & site radiological emergency plan rev frequency.
MILLS, L. M. Tennessee Valley Authority. 83/03/15. ADENSAM, E. Licensing Branch 4. 2pp. 17621:268. 24X Fiche: 50-327, 83/03/15, 8303180530.

--8303180537 Proposed Tech Specs re reassignment of responsibility for annual mgt directive issuance, physical security audit frequency & site radiological plan rev frequency.
* Tennessee Valley Authority. 83/03/15. 13pp. 17621:270. 24X Fiche: 50-327, 83/03/15, 8303180530.

8303310024 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/25. Document Management Branch. 1p. 17780:256. 24X Fiche: 50-327, 83/03/25, 8303310024.

--8303310028 Forwards public version of revised emergency plan implementing procedures, including Procedures IP-2 re notification of unusual event, IP-3 re alert & IP-4 re site area emergency.
MILLS, L. M. Tennessee Valley Authority. 83/03/17. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17780:257. 24X Fiche: 50-327, 83/03/25, 8303310024.

--8303310036 Public version of revised emergency plan implementing procedures, including Procedures IP-2 re notification of unusual event, IP-3 re alert & IP-4 re site area emergency.
* Tennessee Valley Authority. 83/03/04. 30pp. 17780:258. 24X Fiche: 50-327, 83/03/25, 8303310024.

## J. Insurance & indemnity information

8303290423 Forwards Endorsement 31 to NELIA Policy NF-247.
DUCK, J. R. Marsh & McLennan, Inc. 83/03/15. SALTZMAN, J. Assistant Director for State & Licensee Relations. 2pp. 17726:297. 24X Fiche: 50-327, 83/03/15, 8303290423.

## O. Advisory Committee on Reactor Safeguards reports & correspondence

8303100107 Forwards NRR response to ACRS recommendations following 271st & 272nd meetings per 821208 & 830107 memos.
GOODWIN, E. F. Technical Support Branch. 83/02/15. FRALEY, R. F. ACRS - Advisory Committee on Reactor Safeguards. 5pp. 17504:036. 24X Fiche: 50-000, 83/02/15, 8303100107.

--8301180041 Forwards list of requests made at 272nd ACRS meeting on 821209-11 per agreement to provide summary of actions, agreements, assignments & requests made at each full ACRS meeting.
FRALEY, R. F. ACRS - Advisory Committee on Reactor Safeguards. 83/01/05. DIRCKS, W. J. Office of the Executive Director for Operations. 4pp. 17504:041. 24X Fiche: 50-000, 83/02/15, 8303100107.

## P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303040406 Submits official notification that Operating License Condition 2.C.(16), requiring one experienced operator trained on Unit 1 low power testing for natural circulation operations be assigned to each shift on Unit 2, acceptable.
NOVAK, T. M. Assistant Director for Licensing. 83/02/25. PARRIS, H. G. Tennessee Valley Authority. 2pp. 17426:249. 24X Fiche: 50-328, 83/02/25, 8303040406.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303090343 Requests License Condition 2.C.(24) be revised w/respect to Rev 2 of Reg Guide 1.97, "Instrumentation for Light Water Cooled Nuclear Power Plants to Access Plant Conditions During & Following Accident."
MILLS, L. M. Tennessee Valley Authority. 83/03/04. ADENSAM, E. Licensing Branch 4. 3pp. 17472:140. 24X Fiche: 50-327, 83/03/04, 8303090343.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303140234 Forwards response to Generic Ltr 82-28 re inadequate core cooling instrumentation sys per NUREG-0737, Item II.F.2 requirements.
MILLS, L. M. Tennessee Valley Authority. 83/03/09. ADENSAM, E. Licensing Branch 4. 2pp. 17538:345. 24X Fiche: 50-327, 83/03/08, 8303140234.

8303230443 Forwards Amends 26 & 15 to Licenses DPR-77 & DPR-79, respectively, safety evaluation & notice of issuance & availability. Amends change Tech Specs re rod position indication sys, in response to NRC 820816 ltr.
ADENSAM, E. G. Licensing Branch 4. 83/03/14. PARRIS, H. G. Tennessee Valley Authority. 2pp. 17674:088. 24X Fiche: 50-327, 83/03/14, 8303230443.

--8303230446 Amends 26 & 15 to Licenses DPR-77 & DPR-79, respectively, changing Tech Specs re rod position indication sys.
ADENSAM, E. G. Licensing Branch 4. 83/03/14. 8pp. 17674:090. 24X Fiche: 50-327, 83/03/14, 8303230443.

--8303230449 Safety evaluation supporting Amends 26 & 15 to Licenses DPR-77 & DPR-79, respectively.
* Office of Nuclear Reactor Regulation, Director. 83/03/14. 3pp. 17674:098. 24X Fiche: 50-327, 83/03/14, 8303230443.

--8303230454 Notice of issuance & availability of Amends 26 & 15 to Licenses DPR-77 & DPR-79, respectively.
ADENSAM, E. G. Licensing Branch 4. 83/03/14. 3pp. 17674:101. 24X Fiche: 50-327, 83/03/14, 8303230443.

8303180530 Application for amend to Licenses DPR-77 & DPR-79, changing Tech Specs re reassignment of responsibility for annual mgt directive issuance, physical security audit frequency & site radiological emergency plan rev frequency.
MILLS, L. M. Tennessee Valley Authority. 83/03/15. ADENSAM, E. Licensing Branch 4. 2pp. 17621:268. 24X Fiche: 50-327, 83/03/15, 8303180530.

--8303180537 Proposed Tech Specs re reassignment of responsibility for annual mgt directive issuance, physical security audit frequency & site radiological plan rev frequency.
* Tennessee Valley Authority. 83/03/15. 13pp. 17621:270. 24X Fiche: 50-327, 83/03/15, 8303180530.

8303220296 Application for amend to Licenses DPR-77 & DPR-79, revising Tech Specs to change limiting condition for operation of carbon dioxide sys.
MILLS, L. H. Tennessee Valley Authority. 83/03/16. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17656:123. 24X Fiche: 50-327, 83/03/16, 8303220296.

--8303220303 Proposed Tech Specs re carbon dioxide sys.
* Tennessee Valley Authority. 83/03/16. 4pp. 17656:125. 24X Fiche: 50-327, 83/03/16, 8303220296.

8303230425 Forwards Amends 27 & 16 to Licenses DPR-77 & DPR-79, respectively, safety evaluation & notice of issuance & availability. Amends extend time interval required to conduct analog channel operational tests of ESF actuation sys.
ADENSAM, E. G. Licensing Branch 4. 83/03/16. PARRIS, H. G. Tennessee Valley Authority. 2pp. 17674:143. 24X Fiche: 50-327, 83/03/16, 8303230425.

--8303230431 Amends 27 & 16 to Licenses DPR-77 & DPR-79, respectively, extending time interval required to conduct ESF actuation & reactor trip sys from 1 to 3 months.
ADENSAM, E. G. Licensing Branch 4. 83/03/16. 19pp. 17674:145. 24X Fiche: 50-327, 83/03/16, 8303230425.

--8303230433 Safety evaluation supporting Amends 27 & 16 to Licensvs DPR-77 & DPR-79, respectively.
* Office of Nuclear Reactor Regulation, Director. 83/03/16. 3pp. 17674:164. 24X Fiche: 50-327, 83/03/16, 8303230425.

--8303230438 Notice of issuance & availability of Amends 27 & 16 to Licenses DPR-77 & DPR-79, respectively.
ADENSAM, E. G. Licensing Branch 4. 83/03/16. 3pp. 17674:167. 24X Fiche: 50-327, 83/03/16, 8303230425.

8303220156 Confirms 830307 telcon re acceptance criteria for surveillance requirement for emergency gas treatment sys charcoal filters.
MILLS, L. M. Tennessee Valley Authority. 83/03/18. ADENSAM, E. Licensing Branch 4. 1p. 17658:155. 24X Fiche: 50-327, 83/03/18, 8303220156.

8303220162 Forwards changes to NPDES Permit TN0026450 & State of TN Section 401 of Federal Water Pollution Control Act Certification per ETS, Section 5.5.2.
MILLS, L. M. Tennessee Valley Authority. 83/03/18. ADENSAM, E. Licensing Branch 4. 63pp. 17658:309. 24X Fiche: 50-327, 83/03/18, 8303220162.

8303280023 Advises that Kaman Sciences Corp, util contractor, replaced by Pickard, Lowe & Garrick (PLG). PLG rept on full-scale nuiclear safety will be submitted by Jan 1984, per License Condition 2.F.
MILLS, L. M. Tennessee Valley Authority. 83/03/22. ADENSAM, E. Licensing Branch 4. 1p. 17707:152. 24X Fiche: 50-328, 83/03/22, 8303280023.

8303280045 Forwards equipment qualification sheets & supporting documentation on acoustic monitors for PORV & SV position indication, per TMI Action Plan Item II.D.3, in response to 820125 request.
MILLS, L. M. Tennessee Valley Authority. 83/03/22. ADENSAM, E. Licensing Branch 4. 9pp. 17707:303. 24X Fiche: 50-327, 83/03/22, 8303280045.

8303300125 Application for amend to Licenses DPR-77 & DPR-79, changing upper head injection accumulator water level setpoint & tolerances.
MILLS, L. M. Tennessee Valley Authority. 83/03/28. ADENSAM, E. Licensing Branch 4. 1p. 17731:200. 24X Fiche: 50-327, 83/03/28, 8303300125.

--8303300131 Proposed Tech Specs changing upper head injection accumulator water level setpoint & tolerances.
* Tennessee Valley Authority. 83/03/28. 4pp. 17731:201. 24X Fiche: 50-327, 83/03/28, 8303300125.

8303300666 Forwards addl guidance for use in preparing required reporting of offsite doses to public for 1982.
ADENSAM, E. G. Licensing Branch 4. 83/03/28. PARRIS, H. G. Tennessee Valley Authority. 4pp. 17768:284. 24X Fiche: 50-327, 83/03/28, 8303300666.

## Q. Inspection reports, IE Bulletins & correspondence

8303010511 Forwards IE Insp Repts 50-327/82-36 & 50-328/82-35 on 821206-830105. No noncompliance noted.
VERRELLI, D. M. Division of Project & Resident Programs. 83/02/02. PARRIS, H. G. Tennessee Valley Authority. 2pp. 17337:214. 24X Fiche: 50-327, 83/02/02, 8303010511.

--8303010523 IE Insp Repts 50-327/82-36 & 50-328/82-35 on 821206-830105. No noncompliance noted. Major areas inspected: operational safety verification, refueling outage, LER review, IE bulletin closeout & independent insp effort.
FORD, E. J.; BUTLER, S. D. Region 2, Office of Director. FREDRICKSON, P. Division of Project & Resident Programs. 83/02/01. 7pp. 17337:216. 24X Fiche: 50-327, 83/02/02, 8303010511.

8303010429 Ack receipt of 830202 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-35 & 50-328/82-34.
VERRELLI, D. M. Division of Project & Resident Programs. 83/02/10. PARRIS, H. G. Tennessee Valley Authority. 1p. 17343:138. 24X Fiche: 50-327, 83/02/10, 8303010429.

--8303010433 Responds to NRC 830106 ltr re violations noted in IE Insp Repts 50-327/82-35 & 50-328/82-34. Corrective actions: current rev to NRC Form-3, "Notice to Employees," posted on 821216.
KAMMER, D. S. Tennessee Valley Authority. 83/02/02. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17343:139. 24X Fiche: 50-327, 83/02/10, 8303010429.

--8303010438 Forwards IE Insp Repts 50-327/82-35 & 50-328/82-34 on 821213-17 & notice of violation.
VERRELLI, D. M. Division of Project & Resident Programs. 83/01/06. PARRIS, H. G. Tennessee Valley Authority. 2pp. 17343:141. 24X Fiche: 50-327, 83/02/10, 8303010429.

--8303010445 Notice of violation from insp on 821213-17.
* Division of Project & Resident Programs. 83/01/06. 1p. 17343:143. 24X Fiche: 50-327, 83/02/10, 8303010429.

--8303010453 IE Insp Repts 50-327/82-35 & 50-328/82-34 on 821213-17. Noncompliance noted: current copies of Form NRC-3, "Notice to Employees," not posted.
COLLINS, T. R. Region 2, Office of Director. BARR, K. P. Division of Engineering & Radiological Safety Programs. 83/01/05. 6pp. 17343:144. 24X Fiche: 50-327, 83/02/10, 8303010429.

8303010399 Forwards final response to IE Bulletin 80-20, "Adequate Min Flow Through Centrifugal Charging Pumps." Actions ensure min flow requirements maintained at all times.
MILLS, L. M. Tennessee Valley Authority. 83/02/14. O'REILLY, J. P. Region 2, Office of Director. 6pp. 17346:207. 24X Fiche: 50-327, 83/02/14, 8303010399.

8303010284 Responds to NRC 820602 request for addl info re IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants." Action Item 2 requirements for Unit 2 will be performed during refueling outage scheduled for Fall 1983.
MILLS, L. M. Tennessee Valley Authority. 83/02/18. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17335:196. 24X Fiche: 50-327, 83/02/18, 8303010284.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210414 Ack receipt of 830216 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/82-16 & 50-328/82-16.
LEWIS, R. C. Division of Project & Resident Programs. 83/02/25. PARRIS, H. G. Tennessee Valley Authority. 1p. 17634:333. 24X Fiche: 50-327, 83/02/25, 8303210414.

--8303210422 Responds to NRC 820820 ltr re violations noted in IE Insp Repts 50-327/82-16 & 50-328/82-16. Util expects to be in full compliance on or before 830225. Issuance of procedure for escalated corrective program to be completed by 830218.
MILLS, L. M. Tennessee Valley Authority. 83/02/16. O'REILLY, J. P. Region 2, Office of Director. 1p. 17634:334. 24X Fiche: 50-327, 83/02/25, 8303210414.

8303150388 Forwards IE Safeguards Insp Repts 50-327/83-02 & 50-328/83-02 on 830213-17. No noncompliance noted.
VERRELLI, D. Division of Project & Resident Programs. 83/03/04. PARRIS, H. G. Tennessee Valley Authority. 2pp. 17562:015. 24X Fiche: 50-327, 83/03/04, 8303150388.

--8303150401 IE Safeguards Insp Repts 50-327/83-02 & 50-328/83-02 on 830213-17. No noncompliance noted. Major areas inspected: security plan & implementing procedures, organization & mgt & personnel. Details withheld (ref 10CFR73.21).
MOORE, D. E. Region 2, Office of Director. MCGUIRE, D. R. Division of Emergency Preparedness & Materials Safety. 83/03/04. 1p. 17562:017. 24X Fiche: 50-327, 83/03/04, 8303150388.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

R Periodic operating reports & related correspondence

8303090216 Forwards "Effluent & Waste Disposal Semiannual Rept, Jan-June 1981."
BALLENTINE, J. M. Tennessee Valley Authority. 81/08/31. Region 2, Atlanta, Office of the Director (81/03/01). 1p. 17471:130. 24X Fiche: 50-327, 81/08/31, 8303090216.

--8303090220 "Effluent & Waste Disposal Semiannual Rept, Jan-June 1981."
* Tennessee Valley Authority. 81/08/31. 104pp. 17471:131. 24X Fiche: 50-327, 81/08/31, 8303090216.

8303080368 Forwards monthly operating repts for Dec 1982.
MASON, C. C. Tennessee Valley Authority. 83/01/14. Office of Resource Management, Director. 1p. 17492:054. 24X Fiche: 50-327, 83/01/14, 8303080368.

--8303080377 Monthly operating rep's for Dec 1982.
EDDINGS, M. G.; DUPREE, D. C.; MASON, C. C. Tennessee Valley Authority. 83/01/11. 13pp. 17492:055. 24X Fiche: 50-327, 83/01/14, 8303080368.

8303150463 Forwards monthly operating repts for Jan 1983.
MASON, C. C. Tennessee Valley Authority. 83/02/14. Office of Resource Management, Director. 1p. 17568:118. 24X Fiche: 50-327, 83/02/14, 8303150463.

--8303150464 Monthly operating repts for Jan 1983.
MASON, C. C.; EDDINGS, M. Tennessee Valley Authority. 83/02/08. 39pp. 17568:119. 24X Fiche: 50-327, 83/02/14, 8303150465.

8303100326 Forwards "Effluent & Waste Disposal Semiannual Rept, Supplemental Info, Jul-Dec 1982."
MASON, C. C. Tennessee Valley Authority. 83/03/01. Director's Office, Office of Inspection and Enforcement. 1p. 17489:199. 24X Fiche: 50-327, 83/03/01, 8303100326.

--8303100331 "Effluent & Waste Disposl Semiannual Rept, Supplemental Info, Jul-Dec 1982."
* Tennessee Valley Authority. 83/03/01. 23pp. 17489:200. 24X Fiche: 50-327, 83/03/01, 8303100326.

8303160216 Central emergency control ctr meteorological data statistics for Oct-Dec 1982, reported per util commitment to NUREG-0737, Item III.A.2.1.
MILLS, L. M. Tennessee Valley Authority. 83/03/09. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17596:323. 24X Fiche: 50-000, 83/03/09, 8303160216.

S Reportable occurrences: LERs & related correspondence

8303040579 Forwards NPDES noncompliance notification.
TRAINA, P. J. Environmental Protection Agency. 83/02/16. WENE, R. Tennessee-American Water Co. 3pp. 17374:063. 24X Fiche: 50-327, 83/02/16, 8303040579.

--8303040586 NPDES noncompliance notification determined that Natl Pollutant Discharge Elimination Sys permit should be issued w/no substantial changes from tentative determinations previously announced.
TRAINA, P. J. Environmental Protection Agency. 83/02/16. 2pp. 17374:064. 24X Fiche: 50-327, 83/02/16, 8303040579.

8303040434 Forwards updated LER 82-141/01X-1.
GREEN, H. J. Tennessee Valley Authority. 83/02/24. O'REILLY, J. P. Region 2, Office of Director. 1p. 17370:282. 24X Fiche: 50-328, 83/02/24, 8303040434.

--8303040438 Updated LER 82-141/01X-1 on 821214, both trains of engineered safeguard automatic actuation logic for containment ventilation isolation declared inoperable. Caused by failure of latching mechanism to hold relay in energized position.
ROGERS, H. R.; HARDING, M. R. Tennessee Valley Authority. 83/02/24. Region 2, Office of Director. 2pp. 17370:293. 24X Fiche: 50-328, 83/02/24, 8303040434.

8303040465 Forwards updated LER 82-137/03X-1.
GREEN, H. J. Tennessee Valley Authority. 83/02/24. O'REILLY, J. P. Region 2, Office of Director. 1p. 17424:110. 24X Fiche: 50-328, 83/02/24, 8303040465.

--8303040472 Updated LER 82-137/03X-1 on 821122, four upper head injection switches found out of tolerance & one failed to close. Caused by instrument drift & broken microswitch. Switch repaired & level switches adjusted. Pilot valve replaced.
LUDWIG, W. C.; HARDING, M. R. Tennessee Valley Authority. 83/02/24. Region 2, Office of Director. 2pp. 17424:111. 24X Fiche: 50-328, 83/02/24, 8303040465.

8303040575 Forwards LER 83-013/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/02/24. O'REILLY, J. P. Region 2, Office of Director. 1p. 17373:118. 24X Fiche: 50-328, 83/02/24, 8303040575.

--8303040588 LER 83-013/03L-0 on 830129, four RCS level switches found out of tolerance. Cause may be instrument drift or error in calibr & testing techniques. Switches recalibr.
LUDWIG, W. C.; HARDING, M. R. Tennessee Valley Authority. 83/02/24. Region 2, Office of Director. 1p. 17373:119. 24X Fiche: 50-328, 83/02/24, 8303040575.

8303210319 Forwards LER 83-015/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/03/02. O'REILLY, J. P. Region 2, Office of Director. 1p. 17632:157. 24X Fiche: 50-328, 83/03/02, 8303210319.

--8303210321 LER 83-015/03L-0 on 830202, one containment sump level channel 2-LT-63-176 declared inoperable due to failing high. Caused by air bubble in oil-filled ref sense line from bellows to transmitter. Channel recalibr & returned to svc.
ROGERS, H. R.; HARDING, M. R. Tennessee Valley Authority. 83/03/02. Region 2, Office of Director. 1p. 17632:158. 24X Fiche: 50-328, 83/03/02, 8303210319.

8303210322 Forwards LER 83-017/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/03/02. O'REILLY, J. P. Region 2, Office of Director. 1p. 17632:055. 24X Fiche: 50-328, 83/03/02, 8303210322.

--8303210327 LER 83-017/03L-0 on 830201, at 100% power, containment pressure for annulus discovered to be greater than +0.3 psi. Caused by normal air leakage into containment w/o venting. Personnel reminded to vent containment.
CARVER, A. M.; HARDING, M. R. Tennessee Valley Authority. 83/03/02. Region 2, Office of Director. 2pp. 17632:056. 24X Fiche: 50-328, 83/03/02, 8303210322.

8303240470 Forwards LER 83-024/03L-0.
GREEN, H. J. Tennessee Valley Authority. 83/03/18. O'REILLY, J. P. Region 2, Office of Director. 1p. 17678:096. 24X Fiche: 50-328, 83/03/18, 8303240470.

--8303240479 LER 83-024/03L-0 on 830220, w/unit in Mode 1, feedwater flow channel 2-FT-3-103B declared inoperable due to failing low. Caused by failed zener diode in Foxboro 66AC-OH-K flow modifier. Diode replaced.
ROGERS, H. R.; HARDING, M. R. Tennessee Valley Authority. 83/03/18. Region 2, Office of Director. 1p. 17678:097. 24X Fiche: 50-328, 83/03/18, 8303240470.

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303080442 Submits schedule for NRC operator licensing exam site visits through 1985, in response to Generic Ltr 83-01. Exams on 830815-19 for Watts Bar requested to be postponed due to delay in final fuel loading date.
MILLS, L. M. Tennessee Valley Authority 83/02/28 ADENSAM, E. Licensing Branch 4 2pp 17454:256 24X Fiche: 50-000, 83/02/28, 8303080442.

DOCKET 50-329 MIDLAND PLANT, UNIT 1

A Application/construction stage documents & correspondence

8303280075 Confirms 821222 discussion re purchase of plywood/fibreboard for bond breaker on Pier W11 non-Q. Bond breaker required to facilitate using Pier W11 as test load pier. Matl not previously identified as non-Q in util 820917 ltr.
MILLER, D. B. Consumers Power Co. 83/01/05 SHAFER, W. D. Region 3, Office of Director 1p 17707:282 24X Fiche: 50-329, 83/01/05, 8303280075.

8303280232 Advises of suspension of submittal of remedial soils work authorization monthly activities list due to NRC concerns w/info provided. Proposed suspension concurred w/on 830112.
MILLER, D. B. Consumers Power Co. 83/01/12 SHAFER, W. D. Region 3, Office of Director 1p 17706:195 24X Fiche: 50-329, 83/01/12, 8303280232.

8303280031 Requests formal authorization for Activities 312550027 & 322550027 re borated water storage tank foundation & tank repair program - shallow probing to locate electrical ductbank per 830121 discussions.
MILLER, D. B. Consumers Power Co. 83/01/25 SHAFER, W. D. Region 3, Office of Director 1p 17707:337 24X Fiche: 50-329, 83/01/25, 8303280031.

8303280108 Confirms 830125 telcon re installation of addl conduit support for auxiliary bldg underpinning instrumentation. Support will clamp to outside of conduit & cable will not be disturbed.
MILLER, D. B. Consumers Power Co. 83/01/25 SHAFER, W. D. Region 3, Office of Director 1p 17706:362 24X Fiche: 50-329, 83/01/25, 8303280108.

8303280071 Confirms 830125 discussions re loads to be applied during FIVP four point jacking. Util agrees to increase total jack load to value of 10% above estimated weight of structure. Structure will be jacked to max load of 1890K.
MILLER, D. B. Consumers Power Co. 83/01/27 SHAFER, W. D. Region 3, Office of Director 1p 17705:322 24X Fiche: 50-329, 83/01/27, 8303280071.

8303170508 Notifies of completion of review of documents for underpinning Pier 9 E&W. Authorization for listed activities requested.
MILLER, D. B. Consumers Power Co. 83/02/04 SHAFER, W. D. Region 3, Office of Director 1p 17610:208 24X Fiche: 50-329, 83/02/04, 8303170508.

8303140534 Summarizes 830202 discussion of svc water pump structure activity review. Shallow & deep probing & dewatering wells for svc water pump structure discussed. Shallow probing excavation extension drawing approved.
MILLER, D. B. Consumers Power Co. 83/02/09 SHAFER, W. Region 3, Office of Director 1p 17534:171 24X Fiche: 50-329, 83/02/09, 8303140534.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X Fiche: 50-000, 83/02/16, 8302170082.

8303040539 Requests authorization to begin work on svc water pump structure crack mapping.
MILLER, D. B. Consumers Power Co. 83/02/18 SHAFER, W. D. Region 3, Office of Director 1p 17366:004 24X Fiche: 50-329, 83/02/18, 8303040539.

8303040015 Forwards Tera Corp 830209 ltr transmitting QA plan, Rev 1 & engineering program plan, Rev 1, for independent design & const verification program.
HOOD, D. S. Licensing Branch 4 83/02/22 Licensing Branch 4 4pp 17425:139 24X Fiche: 50-329, 83/02/22, 8303040015.

--8303040024 Forwards QA plan, Rev 1 & engineering program plan, Rev 1, for independent design verification program.
LEVIN, H. A. TERA Corp. 83/02/09 KEPPLER, J. G. Region 3, Office of Director EISENHUT, D. G. Division of Licensing 1p 17425:143 24X Fiche: 50-329, 83/02/22, 8303040015.

--8303040032 "Engineering Program Plan, Project Instruction PI-3201-009, Midland Independent Design & Const Verification Program, Project 3201." Corrected pages encl.
* TERA Corp. 83/02/09 80pp 17425:144 24X Fiche: 50-329, 83/02/22, 8303040015.

--8303040041 QA program for Midland independent design & const verification program, Rev 1.
LEVIN, H. A., LEMON, C. E., BECK, J. W. TERA Corp. 83/01/17 184pp 17425:237 24X Fiche: 50-329, 83/02/22, 8303040015.

8303030780 Forwards TERA Corp 830217 ltr transmitting Rev 2 to project QA plan for independent design const & verification program.
HOOD, D. S. Operating Reactors Branch 4 83/02/23 Operating Reactors Branch 4 2pp 17364:300 24X Fiche: 50-329, 83/02/23, 8303030780.

--8303030789 Forwards Rev 2 to project QA plan for independent design const & verification program. Rev designates addl personnel who may potentially participate in project.
LEVIN, H. A. TERA Corp. 83/02/17 KEPPLER, J. G. Region 3, Office of Director EISENHUT, D. G. Division of Licensing 2pp 17364:302 24X Fiche: 50-329, 83/02/23, 8303030780.

--8303030792 Rev 2 to project QA plan for independent design const & verification program.
LEVIN, H. A., LEMON, C. E., BECK, J. W. TERA Corp. 83/02/15 38pp 17364:304 24X Fiche: 50-329, 83/02/23, 8303030780.

8303010545 Informs that S&W has been approved as third party for independent assessment of soils remedial work. Underpinning activities authorized to start under safety-related structures.
SHAFER, W. D. Region 3, Office of Director 83/02/24 MILLER, D. B. Consumers Power Co. 4pp 17337:258 24X Fiche: 50-329, 83/02/24, 8303010545.

8303010668 Responds to util proposal to have S&W perform third party independent assessment of soils remedial work activities. Proposal acceptable.
KEPPLER, J. G. Region 3, Office of Director 83/02/24 COOK, J. W. Consumers Power Co. 3pp 17336:183 24X Fiche: 50-329, 83/02/24, 8303010668.

8303030389 Summary of 830208 telcon w/applicant & Bechtel re underpinning const of turbine & auxiliary bldgs.
HOOD, D. S. Licensing Branch 4 83/02/24 Licensing Branch 4 7pp 17419:317 24X Fiche: 50-329, 83/02/24, 8303030389.

8303020302 Notification of 830307 meeting w/util in Bethesda, MD to discuss sys interaction program.
HERNAN, R. W. Licensing Branch 4 83/02/25 ADENSAM, E. G. Licensing Branch 4 2pp 66614:248 24X Fiche: 50-329, 83/02/25, 8303020302.

8303090140 Forwards "Process Control Program for Midland Nuclear Cogeneration Plant."
COOK, J. W. Consumers Power Co. 83/02/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17470:199 24X Fiche: 50-329, 83/02/25, 8303090140.

--8303090152 "Process Control Program for Midland Nuclear Cogeneration Plant."
* Consumers Power Co. 83/02/25 79pp 17470:201 24X Fiche: 50-329, 83/02/25, 8303090140.

8303140210 Forwards marked-up proposed Tech Specs for review & comment, per EG Adensam 830105 request. Comments requested by 830502.
COOK, J. W. Consumers Power Co. 83/02/25 DENTON, H. R. Division of Licensing 755pp 17529:264 24X Fiche: 50-329, 83/02/25, 8303140210.

8303170489 Requests remedial soils work authorization to perform release spring hanger activity on feedwater line.
MILLER, D. B. Consumers Power Co. 83/02/28 SHAFER, W. D. Region 3, Office of Director 1p 17610:279 24X Fiche: 50-329, 83/02/28, 8303170489.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X Fiche: 50-000, 83/03/02, 8303020321.

8303140083 Forwards two pages inadvertently omitted from QA documents forwarded on 830222 re independent design & const verification program.
HOOD, D. S. Licensing Branch 4 83/03/02 Licensing Branch 4 4pp 17548:309 24X Fiche: 50-329, 83/03/02, 8303140083.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/ electronic networking sys.
KEPPLER, J. G. Region 3, Office of Director. 83/03/03. Commonwealth Edison Co. 2pp. 17492:014. 24X Fiche: 50-000, 83/03/03, 8303100364.

8303170393 Documents 830302 discussions w/NRC re work activity list. Concurs w/deleting "Monitor & Adjust Pier Jacks After Load Transfer" from work activity list.
MILLER, D. B. Consumers Power Co. 83/03/03. SHAFER, W. D. Region 3, Office of Director. 1p. 17610:085. 24X Fiche: 50-329, 83/03/03, 8303170393.

8303220370 Forwards 821213 ltr to be inserted in front of Vol 1, Rev 1 to environ qualification rept.
BAUMAN, R. C. Consumers Power Co. 83/03/03. NRC - No Detailed Affiliation Given. 1p. 17656:017. 24X Fiche: 50-329, 83/03/03, 8303220370.

8303170385 Confirms 830303 telcon w/R Gardner to obtain concurrence on purchase of non-Q matls for underpinning instrumentation for svc water pump structure. QA program requirements will be invoked upon receipt & installation.
MILLER, D. B. Carolina Power & Light Co. 83/03/04. SHAFER, W. D. Region 3, Office of Director. 1p. 17610:084. 24X Fiche: 50-329, 83/03/04, 8303170385.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303170136 Summary of 830223 meeting w/B&W Regulatory Response Group in Bethesda, MD re small break LOCA procedures & maintaining proper steam generator water level.
VAN VLIET, J. Operating Reactors Branch 4. 83/03/08. Operating Reactors Branch 4. 43pp. 17615:224. 24X Fiche: 50-000, 83/03/08, 8303170136.

8303170388 Submits list of work activities discussed in 830308 telcon. Authorization to commence listed work requested.
MILLER, D. B. Consumers Power Co. 83/03/09. SHAFER, W. D. Region 3, Office of Director. 1p. 17609:281. 24X Fiche: 50-329, 83/03/09, 8303170388.

8303110362 Forwards Rev 1 to "Reactor Bldg Spray Sys Centrifugal Pump," "Reactor Bldg Spray Sys Hydrazine Addition Positive Displacement Pump" & "Hydraulic Snubbers," based on util response to NRC request re equipment qualification program.
HOOD, D. S. Licensing Branch 4. 83/03/10. Licensing Branch 4. 4pp. 17544:327. 24X Fiche: 50-329, 83/03/10, 8303110362.

--8303110365 Rev 1 to "Reactor Bldg Spray Sys Centrifugal Pump."
* NUTECH Engineers, Inc. 83/02/02. 133pp. 17544:331. 24X Fiche: 50-329, 83/03/10, 8303110362.

--8303110369 Rev 1 to "Reactor Bldg Spray Sys Hydrazine Addition Positive Displacement Pump."
* NUTECH Engineers, Inc. 83/02/02. 111pp. 17545:104. 24X Fiche: 50-329, 83/03/10, 8303110362.

--8303110374 Rev 1 to "Hydraulic Snubbers."
* NUTECH Engineers, Inc. 83/02/02. 350pp. 17545:215. 24X Fiche: 50-329, 83/03/10, 8303110362.

8303180153 Confirms 830223 discussions w/D Budrik & D Wuokko re submittals of draft Tech Specs for NRC review.
ADENSAM, E. G. Licensing Branch 4. 83/03/10. COOK, J. W. Consumers Power Co. 3pp. 17626:007. 24X Fiche: 50-329, 83/03/10, 8303180153.

8303210267 Forwards B Garde (Govt Accountability Project) 830307 ltr w/comments on licensee const completion plan.
HOOD, D. S. Licensing Branch 4. 83/03/14. Licensing Branch 4. 1p. 17659:035. 24X Fiche: 50-329, 83/03/14, 8303210267.

--8303210274 Addresses concerns re issues presented at 830208 public meeting. Issues for which addl info required listed. Process for choosing third-party auditor should be considered important & delicate matter by NRR.
GARDE, B. P. Government Accountability Project. 83/03/07. EISENHUT, D. G. Division of Licensing. 5pp. 17659:036. 24X Fiche: 50-329, 83/03/14, 8303210267.

--8303210282 Discusses periodic questionable QA re const activities. Util should develop design & const verification program by independent contractor & must be made aware of importance of focus on correcting identified problems in timely manner.
NORELIUS, C. E. Division of Engineering. SPESSARD, R. L. Division of Project & Resident Programs. 82/06/21. KEPPLER, J. G. Region 3, Office of Director. 5pp. 17659:047. 24X Fiche: 50-329, 83/03/14, 8303210267.

--8303210288 Provides list of items for consideration as indicative of questionable licensee performance. Items have become nuisance under reactive insp program.
COOK, R. J. Region 3, Office of Director. 82/06/23. WARNICK, R. F. Region 3, Office of Director. 8pp. 17659:052. 24X Fiche: 50-329, 83/03/14, 8303210267.

--8303210295 Summary of 820726 onsite meeting w/NRR re licensee performance & 820621 & 23 memos. Licensee should obtain independent design review & independent third-party to monitor implementation continuously.
WARNICK, R. F. Region 3, Office of Director. 82/08/18. Region 3, Office of Director. 1p. 17659:060. 24X Fiche: 50-329, 83/03/14, 8303210267.

--8303210301 Discusses actions taken re concerns surrounding facility performance. Augmented insp effort coupled w/other actions to strengthen QC/QA organization & mgt recommended. Actions should be discussed w/NRR & licensee.
WARNICK, R. F. Region 3, Office of Director. 82/08/18. KEPPLER, J. G. Region 3, Office of Director. 2pp. 17659:061. 24X Fiche: 50-329, 83/03/14, 8303210267.

--8303210307 Notifies that S&W acceptable as third party to perform independent assessment of soils remedial work activities. Scope of work should be broadened to include QA overview of design work packages.
KEPPLER, J. G. Region 3, Office of Director. 83/02/24. COOK, J. W. Consumers Power Co. 3pp. 17659:063. 24X Fiche: 50-329, 83/03/14, 8303210267.

--8303210312 Lists concerns corrected or in process of being corrected by licensee since work began on const of piers 12E & 12W. Only five insps performed to determine acceptability of work.
LANDSMAN, R. B. Region 3, Office of Director. 83/02/15. WARNICK, R. F. Region 3, Office of Director. 2pp. 17659:066. 24X Fiche: 50-329, 83/03/14, 8303210267.

8303220169 Forwards affidavits & resumes for addl team members assigned to independent assessment of underpinning work at facilities. Individuals meet "independence" requirements.
LUCKS, A. S. Stone & Webster, Inc. 83/03/15. KEPPLER, J. G. Region 3, Office of Director. 13pp. 17658:255. 24X Fiche: 50-329, 83/03/15, 8303220169.

8303240043 Requests authorization to proceed on listed resubmitted remedial soils work activities which were not started within 90 days of original approval.
MILLER, D. B. Consumers Power Co. 83/03/16. SHAFER, W. D. Region 3, Office of Director. 1p. 17681:025. 24X Fiche: 50-329, 83/03/16, 8303240043.

8303300711 Board Notification 83-21B: forwards ltr transmitting B&W regulatory response rept re emergency feedwater spray effectiveness & small break LOCA operating procedure.
EISENHUT, D. G. Division of Licensing. 83/03/16. PALLADINO, N. J., GILINSKY, V., AHEARNE, J. F. Commissioners. 2pp. 17764:275. 24X Fiche: 50-000, 83/03/16, 8303300711.

8303220076 Authorizes work on critical Work Activities 105050906, 312550018, 322550018, 207050385 & 207050386, per 830316 request.
SHAFER, W. D. Region 3, Office of Director. 83/03/17. MILLER, D. B. Consumers Power Co. 2pp. 17652:260. 24X Fiche: 50-329, 83/03/17, 8303220076.

--8303220082 Requests authorization to proceed on resubmitted Work Activities 105050806 re redress slope layback surfaces & 312550018, BWST 1 to reinstall piping, pipe hangers & electrical facilities.
MILLER, D. B. Consumers Power Co. 83/03/16. SHAFER, W. D. Region 3, Office of Director. 1p. 17652:262. 24X Fiche: 50-329, 83/03/17, 8303220076.

8303210448 Forwards affidavits attesting to corporate independence & prof qualifications of individuals who may participate in overview of const completion program.
LEVIN, H. A. TERA Corp. 83/03/18. KEPPLER, J. G. Region 3, Office of Director. EISENHUT, D. G. Division of Licensing. 80pp. 17634:054. 24X Fiche: 50-329, 83/03/18, 8303210448.

8303210685 Discusses independent design & const verification program. Corporate & individual independence, prof qualifications, scope of review, reporting & auditability & program status addressed. Affidavits encl.
LEVIN, H. A. TERA Corp. 83/03/18. KEPPLER, J. G. Region 3, Office of Director. EISENHUT, D. G. Division of Licensing. 79pp. 17635:296. 24X Fiche: 50-329, 83/03/18, 8303210685.

8303240266 Forwards converted figure for vertical axis of previously transmitted graph of Solid Waste Processing Sys II & discussion of relationship between estimated angle of internal friction & dynamic cone penetrometer resistance.
COOK, J. W. Consumers Power Co. 83/03/18. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 10pp. 17682:128. 24X Fiche: 50-329, 83/03/18, 8303240266.

8303240451 Requests delay until 830701 to submit plans & schedule, in response to Generic Ltr 83-10 re TMI Action Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps."
COOK, J. W. Consumers Power Co. 83/03/21. EISENHUT, D. G. Division of Licensing. 2pp. 17678:006. 24X Fiche: 50-329, 83/03/21, 8303240451.

8303280012 Forwards Tera Corp 830318 submittal re project QA & engineering program plans for independent design & const verification program. Early selection of second sys, direction re reporting & auditability & meeting requested.
HOOD, D. S. Licensing Branch 4. 83/03/21. Licensing Branch 4. 2pp. 17727:023. 24X Fiche: 50-329, 83/03/21, 8303280012.

8303290578 Selects electric power sys as second sys to form basis for independent design verification effort to be performed by TERA Corp. HVAC sys portion assuring control room habitability should be selected for independent review.
EISENHUT, D. G. Division of Licensing. 83/03/22. COOK, J. W. Consumers Power Co. 8pp. 17742:353. 24X Fiche: 50-329, 83/03/22, 8303290578.

8303300159 Summary of 830303 meeting w/util re performance sys interaction program. Viewgraphs encl.
HOOD, D. S. Licensing Branch 4. 83/03/22. Licensing Branch 4. 15pp. 17749:322. 24X Fiche: 50-329, 83/03/22, 8303300159.

8303300661 Board Notification 83-039: Forwards Mgt Analysis Co "Const Project Evaluation of Consumers Power Co Midland Energy Project Units 1 & 2," as info relevant to safety issues in OM/OL proceeding.
NOVAK, T. M. Assistant Director for Licensing. 83/03/24. Atomic Safety and Licensing Board Panel. 4pp. 17770:029. 24X Fiche: 50-329, 83/03/24, 8303300661.

--8303300665 Rev 1 to "Const Project Evaluation of Consumers Power Co Midland Energy Ctr Project Units 1 & 2."
* Management Analysis Co. 83/03/02. 201pp. 17770:033. 24X Fiche: 50-329, 83/03/24, 8303300661.

8303300785 Requests that copies of all correspondence re independent design & const verification program be forwarded to persons on encl svc list.
ADENSAM, E. G. Licensing Branch 4. 83/03/24. LEVIN, H. TERA Corp. 2pp. 17765:270. 24X Fiche: 50-329, 83/03/24, 8303300785.

## E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303110251 Forwards "Reactor Protection Sys Setpoint Methodology" & "Safety-Related Instrument Setpoint Methodology for Balance of Plant Equipment," per SER Confirmatory Item 15.
COOK, J. W. Consumers Power Co. 83/03/09. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17515:315. 24X Fiche: 50-329, 83/03/09, 8303110251.

--8303110253 "Reactor Protection Sys Setpoint Methodology."
* Consumers Power Co. 83/03/09. 22pp. 17515:317. 24X Fiche: 50-329, 83/03/09, 8303110251.

--8303110263 "Safety-Related Instrument Setpoint Methodology for Balance of Plant Equipment."
* Consumers Power Co. 83/03/09. 11pp. 17515:339. 24X Fiche: 50-329, 83/03/09, 8303110251.

8303240458 Provides justification for testing emergency core cooling actuation sys auxiliary relays & auxiliary feedwater pump suction transfer logic on 18-month interval basis. Info completes SER Confirmatory Issues 18 & 19.
COOK, J. W. Consumers Power Co. 83/03/17. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 17678:061. 24X Fiche: 50-329, 83/03/17, 8303240458.

8303280118 Ack receipt of util 830309 ltr commenting on SER, Suppl 2. Comments will be considered for inclusion in future SER suppl.
WARNICK, R. F. Region 3, Office of Director. 83/03/23. MOONEY, J. A. Consumers Power Co. 1p. 17709:346. 24X Fiche: 50-329, 83/03/23, 8303280118.

--8303280120 Forwards comments on Suppl 2 to SER, NUREG-0793.
MOONEY, J. D. Consumers Power Co. 83/03/09. SHAFER, W. D. Region 3, Office of Director. 4pp. 17709:347. 24X Fiche: 50-329, 83/03/23, 8303280118.

## F. Security, medical, emergency & fire protection plans

8303170280 Responds to 821028 ltr re security provisions for fission chamber assemblies. Points of clarification for procedures for control of locks & keys listed. Encls I & II to 821028 ltr withheld (ref 10CFR2.790).
EVANS, L. J. Fuel Facility Safeguards Licensing Branch. 82/11/24. COOK, J. W. Consumers Power Co. 2pp. 17623:073. 24X Fiche: 50-329, 82/11/24, 8303170280.

8303090008 Forwards comments on emergency action levels contained in Section 4 of Rev 1 to radiological emergency response plan. Several levels require mod or suppl. Response required within 30 days of ltr receipt.
ADENSAM, E. G. Licensing Branch 4. 83/02/28. COOK, J. W. Consumers Power Co. 17pp. 17466:194. 24X Fiche: 50-329, 83/02/28, 8303090008.

8303240027 Informs that response to NRC 821126 request for info re App R guidance concerning associated circuits related to fire protection safe shutdown will be forwarded in early Sept 1983.
COOK, J. W. Consumers Power Co. 83/03/16. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17681:095. 24X Fiche: 50-329, 83/03/16, 8303240027.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director. 83/03/22. Commonwealth Edison Co. 2pp. 17690:316. 24X Fiche: 50-000, 83/03/22, 8303240440.

## G. Adjudicatory correspondence

8303100204 Responds to appeal re denial of FOIA request for confidential proposed QA stipulation prepared for OL & CP proceedings. Document withheld (ref FOIA Exemptions 4 & 5).
CHILK, S. J. Office of the Secretary of the Commission. 83/02/04. STAMIRIS, B. Stamiris, B. 1p. 17504:085. 24X Fiche: 50-329, 83/02/04, 8303100204.

--8303100216 Denies request for extension for filing appeal re FOIA request for proposed QA stipulation in OL & CP proceedings. Request for reconsideration may be submitted when proceeding completed.
FELTON, J. M. Division of Rules and Records. 81/08/20. STAMIRIS, B. Stamiris, B. 1p. 17504:087. 24X Fiche: 50-329, 83/02/04, 8303100204.

--8303100225 Requests extension of 20 days beyond initial decision in OL/CP proceedings to file FOIA appeal for confidential proposed QA stipulation.
STAMIRIS, B. Stamiris, B. 81/08/12. FELTON, J. M. Division of Rules and Records. 1p. 17504:088. 24X Fiche: 50-329, 83/02/04, 8303100204.

8303140374 Forwards staff testimony on Sinclair Contention 3 & stipulation between NRC & applicant re alleged matl false statement in FSAR. ASLB 830214 order permits testimony to be filed on Sinclair Contention 3 by 830218.
WILCOVE, M. N. Hearing Branch 2. 83/02/07. BECHHOEFER, C., COWAN, F. P., HARBOUR, J. Atomic Safety and Licensing Board Panel. 2pp. 17533:295. 24X Fiche: 50-329, 83/02/07, 8303140374.

--8303140432 Stipulation agreeing not to contest that matl false statement made in FSAR re fill & backfill placement per Table 2.5-9 & that matl false statement was unintentional.
WILCOVE, M. N. Hearing Branch 2. STEPTOE, P. P. Consumers Power Co. 83/02/07. 1p. 17533:345. 24X Fiche: 50-329, 83/02/07, 8303140374.

8303010171 Notice of appearance in proceeding. Certificate of Svc encl.
GILOMEN, B. R. Consumers Power Co. GILOMEN, B. R. Isham, Lincoln & Beale. 83/02/22. 3pp. 17331:353. 24X Fiche: 50-329, 83/02/22, 8303010171.

8303010179 Forwards Figure 29, "Summary of Actual & Estimated Settlements (for Finite Element Analysis)," inadvertently omitted from applicant Exhibit 30 entered into evidence on 821210 Certificate of Svc encl.
STEPTOE, P. P. Isham, Lincoln & Beale. STEPTOE, P. P. Consumers Power Co. 83/02/23. BECHHOEFER, C., HARBOUR, J., COWAN, F. P. Atomic Safety and Licensing Board Panel. 4pp. 17332:359. 24X Fiche: 50-329, 83/02/23, 8303010179.

8303010077 Invites present or past site workers who have made allegations to visit site under terms described in JW Cook 821228 ltr. Related correspondence.
BRUNNER, J. E. Consumers Power Co. 83/02/24. GARDE, B. Government Accountability Project. 3pp. 17341:063. 24X Fiche: 50-329, 83/02/24, 8303010077.

8303070132 Informs that NUREG/CR-2300, "PRA Procedures Guide," sent to LPDR.
WILCOVE, M. N. Hearing Branch 2. 83/03/04. SINCLAIR, M. Sinclair, M. 1p. 17433:075. 24X Fiche: 50-329, 83/03/04, 8303070132.

8303080441 Notice rescheduling 830412-16 & 18-22 hearings on QA/QC issues for 830426-30 & 0502-06 in Midland, MI.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 83/03/04. 1p. 17454:240. 24X Fiche: 50-329, 83/03/04, 8303080441.

8303160775 Advises that only remaining issues to be litigated in hearing requested by applicant re 791206 order are QA & matters involving pending investigations. ASLB urged completion of investigation in time for 830426 hearing.
CUNNINGHAM, G. H. Office of the Executive Legal Director. 83/03/08. HAYES, B. B. Office of Investigation. 1p. 17600:182. 24X Fiche: 50-329, 83/03/08, 8303160775.

--8303160778 Requests investigation of two alleged violations of ASLB 820430 order re excavation below deep G duct & initiation of fireline relocation activities w/o NRC authorization.
KEPPLER, J. G. Region 3, Office of Director. 82/08/20. FITZGERALD, J. A. Office of Investigation. 2pp. 17600:183. 24X Fiche: 50-329, 83/03/08, 8303160775.

8303170006 Advises that allegations in five affidavits referred to Region III for investigation. CPC attys voluntarily refrained from engaging in discovery. QA hearing scheduled for 830426. Other issues arising from 791206 order submitted to ASLB.
CUNNINGHAM, G. H. Office of the Executive Legal Director. 83/03/08. KEPPLER, J. G. Region 3, Office of Director. 1p. 17624:341. 24X Fiche: 50-329, 83/03/[illegible], 8303170006.

8303100351 Notice of 830329-0401 hearings in Midland, MI on OL issues. Limited appearance statements will be heard on 830329.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 83/03/09. 2pp. 17490:354. 24X Fiche: 50-329, 83/03/09, 8303100351.

8303150417 Notice of 830328 addl evidentiary hearings on OL issues in Midland, MI.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 83/03/11. 1p. 17561:238. 24X Fiche: 50-329, 83/03/11, 8303150417.

8303180410 Requests info on dewatering sys & wells at plant. Related correspondence.
GADLER, S. J. Mapleton Intervenors. 83/03/11. NRC - No Detailed Affiliation Given. 2pp. 17622:027. 24X Fiche: 50-329, 83/03/11, 8303180410.

8303160113 Forwards rept summary for NUREG/CR-2497, "Precursors to Potential Severe Core Damage Accident: 1969-1979," w/o encl.
WRIGHT, N. Hearing Branch 2. 83/03/14. STAMIRIS, B. Stamiris, B. MARSHALL, W. H. Marshall, W. H. SINCLAIR, M. Sinclair, M. 1p. 17396:360. 24X Fiche: 50-329, 83/03/14, 8303160113.

8303180398 Forwards NRC Byron testimony re Class 9 accidents which applicant distributed to parties at 830308-11 hearings. Testimony will be useful background reading for NRC Midland testimony when filed.
KINNEAR, W. Isham, Lincoln & Beale. KINNEAR, W. Consumers Power Co. 83/03/15. COWAN, F. P. Atomic Safety and Licensing Board Panel. 2pp. 17622:222. 24X Fiche: 50-329, 83/03/15, 8303180398.

8303220172 Forwards transcript of util president, J Selby radio interview. Selby comment on plant completion referred to time needed to complete both units. Related correspondence.
STEPTOE, P. P. Isham, Lincoln & Beale. STEPTOE, P. P. Consumers Power Co. 83/03/15. BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 30pp. 17658:075. 24X Fiche: 50-329, 83/03/15, 8303220172.

8303220181 Praises JE Carlson & SY Tsai performances as witnesses & expresses regret over Carlson leaving ANL.
PATON, W. D. Hearing Branch 2. 83/03/17. HALLETT, W. J. Argonne National Laboratory. 1p. 17657:165. 24X Fiche: 50-329, 83/03/17, 8303220181.

8303310228 Forwards NUREG/CR-3069, "Interaction of Electromagnetic Pulse W/Commercial Nuclear Power Plant Sys" & executive summary, per 830312 request. W/o encl.
WRIGHT, N. A. Hearing Branch 2. 83/03/17. MARSHALL, W. A. Mapleton Intervenors. 1p. 17755:355. 24X Fiche: 50-329, 83/03/17, 8303310228.

8303240522 Memorializes 830309 meeting during hearing recess; subsequent telcons & ltrs re requests for informal discovery on matters to be covered in Apr hearings.
WILLIAMS, F. C. Isham, Lincoln & Beale. 83/03/22. STAMIRIS, B. Stamiris, B. SINCLAIR, M. Sinclair, M. 3pp. 17682:278. 24X Fiche: 50-329, 83/03/22, 8303240522.

8303250161 Requests to make limited appearance statement at 830329 hearings in Midland, MI.
BROWN, F. L. Affiliation Unknown. 83/03/22. Docketing & Services Branch. 1p. 17691:117. 24X Fiche: 50-329, 83/03/22, 8303250161.

8303290497 Requests to testify at 830329 hearings.
MACDONALD, S. W. Midland County, MI. 83/03/22. Docketing & Services Branch. 1p. 17725:049. 24X Fiche: 50-329, 83/03/22, 8303290497.

8303290455 Forwards proprietary documents requested by discovery in OL proceedings. Documents are provided per protective order adopted by ASLB on P 12,358 of transcript. W/o encl. Related correspondence.
BRUNNER, J. E. Consumers Power Co. 83/03/23. STAMIRIS, B. Affiliation Unknown. 2pp. 17725:327. 24X Fiche: 50-329, 83/03/23, 8303290455.

8303290511 Requests to testify at 830329 hearings.
ASIALA Affiliation Unknown. 83/03/23. Docketing & Services Branch. 1p. 17725:110. 24X Fiche: 50-329, 83/03/23, 8303290511.

8303290531 Requests to make limited appearance statement at 830329 hearings.
CHATTERTON, R. B. Affiliation Unknown. 83/03/23. NRC - No Detailed Affiliation Given. 1p. 17725:109. 24X Fiche: 50-329, 83/03/23, 8303290531.

8303290514 Requests to make limited appearance statement at OL hearings.
GORMAN, J. C. Affiliation Unknown. 83/03/24. Docketing & Services Branch. 1p. 17723:016. 24X Fiche: 50-329, 83/03/24, 8303290514.

8303310325 Requests to make limited appearance statement at 830329 hearings.
BREEN, J. Affiliation Unknown. 83/03/24. Docketing & Services Branch. 1p. 17755:044. 24X Fiche: 50-329, 83/03/24, 8303310325.

8303280302 Declines 830311 ltr requesting info re dewatering sys since discovery not open on issue.
PATON, W. D. Hearing Branch 2. 83/03/25. GADLER, S. Affiliation Unknown. 1p. 17706:291. 24X Fiche: 50-329, 83/03/25, 8303280302.

8303290509 Requests to testify at 830329 hearings.
THOMPSON, J. R. Affiliation Unknown. 83/03/25. Docketing & Services Branch. 1p. 17723:001. 24X Fiche: 50-329, 83/03/25, 8303290509.

H. General correspondence

8303090197 Comments on util mistakes, mismanagement & cost overruns for project. Plants not needed.
BAILEY, H. R. Affiliation Unknown. 83/02/27. DENTON, H. R. NRC - No Detailed Affiliation Given. 1p. 17472:291. 24X Fiche: 50-329, 83/02/27, 8303090197.

8303280282 Requests independent audit of plant.
ROMO, K. B. Affiliation Unknown. 83/03/24. EISENHUT, D. G. Division of Licensing. 1p. 17706:044. 24X Fiche: 50-329, 83/03/24, 8303280282.

I. Financial information

8303210279 Forwards Annual Financial Rept 1982.
PERRY, P. A. Consumers Power Co. 83/03/15. GIAMBUSSO, A. Division of Licensing. 1p. 17632:003. 24X Fiche: 50-000, 83/03/15, 8303210279.

--8303210286 Annual Financial Rept 1982.
SELBY, J. P., FALAHEE, J. B. Consumers Power Co. 83/02/04. 29pp. 17632:004. 24X Fiche: 50-000, 83/03/15, 8303210279.

Q Inspection reports, IE Bulletins & correspondence

8303140398 Grants access to job site to sources of allegations only in presence of NRC investigators.
COOK, J W Consumers Power Co 82/12/28 KEPPLER, J G Region 3, Office of Director 2pp 17542:131 24X Fiche 50-329, 82/12/28, 8303140398

8303110254 Discusses IE insp on 821012-1125 & 830119-21 & forwards notice of violation & proposed imposition of civil penalty.
KEPPLER, J G Region 3, Office of Director 83/02/08 SELBY, J D Consumers Power Co 3pp 17515:299 24X Fiche 50-329, 83/02/08, 8303110254

--8303110261 Notice of proposed violation & proposed imposition of civil penalty in amount of $120,000 Noncompliance noted: failure to assure that complete insp of drawings & specs performed after deficiencies corrected.
KEPPLER, J G Region 3, Office of Director 83/02/08 13pp 17515:302 24X Fiche 50-329, 83/02/08, 8303110254

8303110363 Forwards IE Insp Repts 50-329/82-22 & 50-330/82-22 on 821012-1125 & 830119-21 Separate ltr addressing noncompliance items transmitted.
KEPPLER, J G Region 3, Office of Director 83/02/08 SELBY, J D Consumers Power Co 2pp 17506:276 24X Fiche 50-329, 83/02/08, 8303110363

--8303110366 IE Insp Repts 50-329/82-22 & 50-330/82-22 on 821012-1125 & 830119-21 Noncompliance noted: failure to establish adequate design control measures & QA procedures & to conduct adequate component source & receipt insps.
BARRETT, P A , BURGESS, B L , COOK, R J Region 3, Office of Director 83/02/01 29pp 17506:278 24X Fiche 50-329, 83/02/08, 8303110363

8303090094 Responds to FOIA request for documents re NRC statement in 821113 Philadelphia Inquirer Statement made by Keppler based on impressions formed over period of yrs & not specific documents Forwards documents listed in app.
FELTON, J M Division of Rules and Records 83/02/14 ROMANO, F R Air and Water Pollution Patrol 2pp 17465:202 24X Fiche 50-329, 83/02/14, 8303090094

--8303090100 Forwards agenda of 821029 mgt meeting w/Bechtel Corp re means to improve Bechtel image & regulatory posture at plant site.
COOK, R J Region 3, Office of Director 82/12/16 Region 3, Office of Director 19pp 17465:205 24X Fiche 50-329, 83/02/14, 8303090094

--8303090108 Forwards list of items considered by various inspectors to be indicative of questionable licensee performance.
COOK, R J Region 3, Office of Director 82/07/23 WARNICK, R F Region 3, Office of Director 8pp 17465:224 24X Fiche 50-329, 83/02/14, 8303090094

8303110355 Board Notification 83-14: forwards followup info on apparent deficiencies in Midland-Ross superstrut matl.
EISENHUT, D G Division of Licensing 83/02/18 PALLADINO, N Commissioners 24pp 17546:205 24X Fiche 50-000, 83/02/18, 8303110355

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 11pp 17521:001 24X Fiche 50-000, 83/02/25, 8212060367

8303220215 Forwards IE Insp Repts 50-329/83-02 & 50-330/83-02 on 830216-18 No noncompliance noted.
PAPE'IELLO, C J Region 3, Office of Director 83/03/03 COOK, J W Consumers Power Co 2pp 17656:253 24X Fiche 50-329, 83/03/03, 8303220215

--8303220229 IE Insp Repts 50-329/83-02 & 50-330/83-02 on 830216-18 No noncompliance noted Major areas inspected preoperational & routine operational insp program in radiation protection & radwaste mgt areas.
GRANT, W B , GREGER, L R Region 3, Office of Director 83/03/03 5pp 17656:255 24X Fiche 50-329, 83/03/03, 8303220215

8303170428 Forwards IE Insp Repts 50-329/83-01 & 50-330/83-01 on 830111-14 & notice of violation.
WARNICK, R F Region 3, Office of Director 83/03/04 COOK, J W Consumers Power Co 2pp 17611:001 24X Fiche 50-329, 83/03/04, 8303170428

--8303170433 Notice of violation from insp on 830111-14.
WARNICK, R F Region 3, Office of Director 83/03/04 1p 17611:003 24X Fiche 50-329, 83/03/04, 8303170428

--8303170436 IE Insp Repts 50-329/83-01 & 50-330/83-01 on 830111-14 Noncompliance noted: failure to follow procedures re issuing untagged valve to welding fabrication area.
SIMON, J A , SATHER, A , SHAFER, W D Region 3, Office of Director 83/02/25 5pp 17611:004 24X Fiche 50-329, 83/03/04, 8303170428

8303180209 Responds to NRC 830208 notice of violation & proposed imposition of civil penalties Corrective actions Category I work halted, in-process insp notices to be reviewed & QC engineers instructed to complete insp activities.
COOK, J W Consumers Power Co 83/03/10 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 5lpp 17617:289 24X Fiche 50-329, 83/03/10, 8303180209

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc 117pp 17611:070 24X Fiche 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 121pp 17774:352 24X Fiche 50-000, 83/03/21, 8212060387

R Periodic operating reports & related correspondence

8303220016 "Nonconformance Repts for Dec 1982."
* Bechtel Corp * Consumers Power Co 82/12/31 693pp 17650:103 24X Fiche 50-329, 82/12/31, 8303220016

8303100208 Forwards, in accordance w/ALAB-106 dtd 730323 & Amend 1 to CP, Bechtel monthly nonconformance rep'ts & log sheets, Bechtel FSD nonconformance repts & log sheets & Bechtel QA findings.
COOK, J W Consumers Power Co 83/02/22 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 865pp 17486:001 24X Fiche 50-329, 83/02/22, 8303100208

S Reportable occurrences, LERs & related correspondence

8303100384 Interim deficiency rept re hardness values of anchor & connecting studs for reactor coolant pump snubbers Snubber stud tension checked, low alloy quenched & tempered bolting tested Next rept expected by 830319.
COOK, J W Consumers Power Co 83/02/22 KEPPLER, J G Region 3, Office of Director 8pp 17490:339 24X Fiche 50-329, 83/02/22, 8303100384

8303100188 Interim deficiency rept re delivered, safety-related electrical equipment not meeting project requirements Task force established by Bechtel to investigate & resolve problems Next rept will be submitted by 830513.
COOK, J W Consumers Power Co 83/02/25 KEPPLER, J G Region 3, Office of Director 7pp 17489:168 24X Fiche 50-329, 83/02/25, 8303100188

8303100263 Interim Deficiency Rept 1 to MCAR 22 re reactor bldg spray piping supports Deficiency reopened due to possible unconservative water hammer loads used in original design analysis Bechtel rept encl Next rept expected by 830711.
COOK, J W Consumers Power Co 83/02/25 KEPPLER, J G Region 3, Office of Director 6pp 17490:298 24X Fiche 50-329, 83/02/25, 8303100263

8303100310 Interim deficiency rept re B&W steam generator auxiliary feedwater header design change Initially reported on 820526 B&W supplied preliminary 10CFR21 rept on nonapproved vendor Flanges returned Matl recertified Next rept by 820531.
COOK, J W Consumers Power Co 83/02/28 KEPPLER, J G Region 3, Office of Director 2pp 17489:282 24X Fiche 50-329, 83/02/28, 8303100310

8303100219 Interim Deficiency Rept 2 to MCAR 63 re shear lug design embedments Approx 2,500 embedments identified to date No corrective action established Bechtel rept encl Next rept expected by 830520.
COOK, J W Consumers Power Co 83/03/01 KEPPLER, J G Region 3, Office of Director 5pp 17489:228 24X Fiche 50-329, 83/03/01, 8303100219

8303150620 Board Notification 83-26: forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys. Info may affect conclusions re probability of/corrective actions for ATWS. EISENHUT, D. G. Division of Licensing. 83/03/03. PALLADINO, N. Commissioners. 24pp. 17584:097. 24X Fiche: 50-000, 83/03/03, 8303150620.

8303140463 Interim Deficiency Rept MCAR 64 re possible frazil ice formation in svc water intake structure. Corrective action initiated to ensure ice does not block structure. Options to prevent ice formation discussed. COOK, J. W. Consumers Power Co. 83/03/04. KEPPLER, J. G. Region 3, Office of Director. 7pp. 17541:180. 24X Fiche: 50-329, 83/03/04, 8303140463.

8303140368 Interim deficiency rept re quality program & mfg deficiencies affecting radiation monitoring equipment supplied by Victoreen. Initially reported on 821015. Investigation continuing. Next rept by 830506. COOK, J. W. Consumers Power Co. 83/03/09. KEPPLER, J. G. Region 3, Office of Director. 8pp. 17543:309. 24X Fiche: 50-329, 83/03/09, 8303140368.

8303140371 Interim Deficiency Rept MCAR 65 re auxiliary feedwater suction piping. Pressure relief valve will be installed on auxiliary feedwater suction line between pump & check valve. Next rept will be submitted on 830520. COOK, J. W. Consumers Power Co. 83/03/10. KEPPLER, J. G. Region 3, Office of Director. 5pp. 17543:324. 24X Fiche: 50-329, 83/03/10, 8303140371.

8303240211 Interim deficiency rept re underrated terminal strips on Limitorque valve operators. All underrated terminal blocks replaced by vendor w/correctly rated Marathon 300 series terminal blocks. Next rept expected by 830607. COOK, J. W. Consumers Power Co. 83/03/16. KEPPLER, J. G. Region 3, Office of Director. 12pp. 17682:166. 24X Fiche: 50-329, 83/03/16, 8303240211.

8303280135 Interim deficiency rept re adequacy of shear reinforcements at major containment penetrations. Initially reported on 810515. As-designed & as-built containment adequate. Condition not reportable per 10CFR50.55(e). COOK, J. W. Consumers Power Co. 83/03/18. KEPPLER, J. G. Region 3, Office of Director. 5pp. 17706:345. 24X Fiche: 50-329, 83/03/18, 8303280135.

T. Hearing transcripts on non-antitrust matters

8303140374 Forwards staff testimony on Sinclair Contention 3 & stipulation between NRC & applicant re alleged matl false statement in FSAR. ASLB 830214 order permits testimony to be filed on Sinclair Contention 3 by 830218. WILCOVE, M. N. Hearing Branch 2. 83/02/07. BECHHOEFER, C., COWAN, F. P., HARBOUR, J. Atomic Safety and Licensing Board Panel. 2pp. 17533:295. 24X Fiche: 50-329, 83/02/07, 8303140374.

--8303140420 Testimony of JN Ridgely & AW Serkiz on Sinclair Contention 3 re water hammer problem. Prof qualifications encl. RIDGELY, J. N. Auxiliary Systems Branch. SERKIZ, A. W. Generic Issues Branch. 83/02/07. 12pp. 17533:297. 24X Fiche: 50-329, 83/02/07, 8303140374.

--8303140432 Stipulation agreeing not to contest that matl false statement made in FSAR re fill & backfill placement per Table 2.5-9 & that matl false statement was unintentional. WILCOVE, M. N. Hearing Branch 2. STEPTOE, P. P. Consumers Power Co. 83/02/07. 1p. 17533:345. 24X Fiche: 50-329, 83/02/07, 8303140374.

8302280189 Order making transcript page number corrections. BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 83/02/25. 1p. 17306:058. 24X Fiche: 50-329, 83/02/25, 8302280189.

8303020002 Forwards JE Carson & SY Tsai testimony re Sinclair Contention 14 on cooling pond thermal performance & ice & fog generation. WRIGHT, N. A. Hearing Branch 2. 83/02/28. BECHHOEFER, C., COWAN, F. P., HARBOUR, J. Atomic Safety and Licensing Board Panel. 2pp. 17354:248. 24X Fiche: 50-329, 83/02/28, 8303020002.

--8303020006 Testimony of JE Carson re Sinclair Contention 14 on cooling pond. Describes analyses of ice & fog generation. Prof qualifications encl. CARSON, J. E. NRC - No Detailed Affiliation Given. CARSON, J. E. Argonne National Laboratory. 83/02/28. 11pp. 17354:250. 24X Fiche: 50-329, 83/02/28, 8303020002.

--8303020011 Testimony of SY Tsai re Contention 14 on cooling pond & thermal analysis. Applicant appropriately conducted thermal performance studies for various combinations of plant operating conditions & meteorological conditions. TSAI, S. Y. NRC - No Detailed Affiliation Given. TSAI, S. Y. Argonne National Laboratory. 83/02/28. 6pp. 17354:261. 24X Fiche: 50-329, 83/02/28, 8303020002.

8303030403 Forwards P 4 of DH Evans & D Sommers 830214 testimony re Sinclair Contention 14 on cooling pond. STEPTOE, P. P. Isham, Lincoln & Beale. STEPTOE, P. P. Consumers Power Co. 83/02/28. BECHHOEFER, C., HARBOUR, J., COWAN, F. P. Atomic Safety and Licensing Board Panel. 1p. 17410:123. 24X Fiche: 50-329, 83/02/28, 8303030403.

--8303030413 P 4 of DH Evans & D Sommers 830214 testimony re Sinclair Contention 14 on cooling pond, inadvertently omitted. Certificate of Svc encl. EVANS, D. H., SOMMERS, D. Consumers Power Co. 83/02/28. 3pp. 17410:124. 24X Fiche: 50-329, 83/02/28, 8303030403.

8303140060 Transcript of 830308 evidentiary hearing in Midland, MI. Pp 12,355-12,541. Supporting documentation encl. * Atomic Safety and Licensing Board Panel. 83/03/08. 251pp. 17539:033. 24X Fiche: 50-329, 83/03/08, 8303140060.

8303150148 Transcript of 830309 evidentiary hearing in Midland, MI. Pp 12,542-12,763. Supporting documentation encl. * Atomic Safety and Licensing Board Panel. 83/03/09. 242pp. 17550:286. 24X Fiche: 50-329, 83/03/09, 8303150148.

8303150163 Transcript of 830310 evidentiary hearing in Midland, MI. Pp 12,764-12,964. Supporting documentation encl. * Atomic Safety and Licensing Board Panel. 83/03/10. 304pp. 17554:041. 24X Fiche: 50-329, 83/03/10, 8303150163.

8303150137 Transcript of 830311 evidentiary hearing in Midland, MI. Pp 12,965-13,100. * Atomic Safety and Licensing Board Panel. 83/03/11. 137pp. 17554:345. 24X Fiche: 50-329, 83/03/11, 8303150137.

8303230243 Forwards A Savage testimony on Contention 4 re steam tube degradation problem. Contention 13 testimony re precursors to Class 9 accidents will be heard prior to steam tube degradation issue. Related correspondence. SINCLAIR, M. Sinclair, M. 83/03/18. Atomic Safety and Licensing Board Panel. 1p. 17661:152. 24X Fiche: 50-329, 83/03/18, 8303230243.

--8303230248 Testimony of A Savage on Contention 4 re corrosion & sludging of condenser tubes by pond water. Prof qualifications encl. SAVAGE, A. Sinclair, M. 83/03/18. 8pp. 17661:153. 24X Fiche: 50-329, 83/03/18, 8303230243.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-330 MIDLAND PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8303280075 Confirms 821222 discussion re purchase of plywood/fibreboard for bond breaker on Pier W11 non-Q. Bond breaker required to facilitate using Pier W11 as test load pier. Matl not previously identified as non-Q in util 820917 ltr. MILLER, D. B. Consumers Power Co. 83/01/05. SHAFER, W. D. Region 3, Office of Director. 1p. 17707:282. 24X Fiche: 50-329, 83/01/05, 8303280075.

8303280232 Advises of suspension of submittal of remedial soils work authorization monthly activities list due to NRC concerns w/info provided. Proposed suspension concurred w/on 830112. MILLER, D. B. Consumers Power Co. 83/01/12. SHAFER, W. D. Region 3, Office of Director. 1p. 17706:195. 24X Fiche: 50-329, 83/01/12, 8303280232.

8303280031 Requests formal authorization for Activities 312550027 & 322550027 re borated water storage tank foundation & tank repair program - shallow probing to locate electrical ductbank per 830121 discussions. MILLER, D. B. Consumers Power Co. 83/01/21. SHAFER, W. D. Region 3, Office of Director. 1p. 17707:337. 24X Fiche: 50-329, 83/01/25, 8303280031.

8303280108 Confirms 830125 telcon re installation of addl conduit support for auxiliary bldg underpinning instrumentation. Support will clamp to outside of conduit & cable will not be disturbed.
MILLER, D. B. Consumers Power Co. 83/01/25 SHAFER, W. D. Region 3, Office of Director 1p. 17706:362 24X Fiche: 50-329, 83/01/25, 8303280108.

8303280071 Confirms 830125 discussions re loads to be applied during FIVP four point jacking. Util. agrees to increase total jack load to value of 10% above estimated weight of structure. Structure will be jacked to max load of 1890K.
MILLER, D. B. Consumers Power Co. 83/01/27 SHAFER, W. D. Region 3, Office of Director 1p. 17705:322 24X Fiche: 50-329, 83/01/27, 8303280071.

8303170508 Notifies of completion of review of documents for underpinning Pier 9 E&W. Authorization for listed activities requested.
MILLER, D. B. Consumers Power Co. 83/02/04 SHAFER, W. D. Region 3, Office of Director 1p. 17610:208 24X Fiche: 50-329, 83/02/04, 8303170508.

8303140534 Summarizes 830202 discussion of svc water pump structure activity review. Shallow & deep probing & dewatering wells for svc water pump structure discussed. Shallow probing excavation extension drawing approved.
MILLER, D. B. Consumers Power Co. 83/02/09 SHAFER, W. Region 3, Office of Director 1p. 17534:171 24X Fiche: 50-329, 83/02/09, 8303140534.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp. 17492:033 24X Fiche: 50-000, 83/02/16, 8302170082.

8303040539 Requests authorization to begin work on svc water pump structure crack mapping.
MILLER, D. B. Consumers Power Co. 83/02/18 SHAFER, W. D. Region 3, Office of Director 1p. 17366:004 24X Fiche: 50-329, 83/02/18, 8303040539.

8303040015 Forwards Tera Corp 830209 ltr transmitting QA plan, Rev 1 & engineering program plan, Rev 1, for independent design & const verification program.
HOOD, D. S. Licensing Branch 4 83/02/22 Licensing Branch 4 4pp. 17425:139 24X Fiche: 50-329, 83/02/22, 8303040015.

--8303040024 Forwards QA plan, Rev 1 & engineering program plan, Rev 1, for independent design verification program.
LEVIN, H. A. TERA Corp. 83/02/09 KEPPLER, J. G. Region 3, Office of Director EISENHUT, D. G. Division of Licensing 1p. 17425:143 24X Fiche: 50-329, 83/02/22, 8303040015.

--8303040032 "Engineering Program Plan, Project Instruction PI-3201-009, Midland Independent Design & Const Verification Program, Project 3201." Corrected pages encl.
* TERA Corp. 83/02/09 60pp. 17425:144 24X Fiche: 50-329, 83/02/22, 8303040015.

--8303040041 QA program for Midland independent design & const verification program, Rev 1.
LEVIN, H. A. ; LEMON, C. E. ; BECK, J. W. TERA Corp. 83/01/17 184pp. 17425:237 24X Fiche: 50-329, 83/02/22, 8303040015.

8303030780 Forwards TERA Corp 830217 ltr transmitting Rev 2 to project QA plan for independent design const & verification program.
HOOD, D. S. Operating Reactors Branch 4 83/02/23 Operating Reactors Branch 4 2pp. 17364:300 24X Fiche: 50-329, 83/02/23, 8303030780.

--8303030789 Forwards Rev 2 to project QA plan for independent design const & verfication program. Rev designates addl personnel who may potentially participate in project.
LEVIN, H. A. TERA Corp. 83/02/17 KEPPLER, J. G. Region 3, Office of Direct EISENHUT, D. G. Division of Licensing 2pp. 17364:302 24X Fiche: 50-329, 83/02/23, 8303030780.

--8303030792 Rev 2 to project QA plan for independent design const & verification program.
LEVIN, H. A. ; LEMON, C. E. ; BECK, J. W. TERA Corp. 83/02/15 38pp. 17364:304 24X Fiche: 50-329, 83/02/23, 8303030780.

8303010545 Informs that S&W has been approved as third party for independent assessment of soils remedial work. Underpinning activities authorized to start under safety-related structures.
SHAFER, W. D. Region 3, Office of Director 83/02/24 MILLER, D. B. Consumers Power Co. 4pp. 17337:258 24X Fiche: 50-329, 83/02/24, 8303010545.

8303010668 Responds to util proposal to have S&W perform third party independent assessment of soils remedial work activities. Proposal acceptable.
KEPPLER, J. G. Region 3, Office of Director 83/02/24 COOK, J. W. Consumers Power Co. 3pp. 17336:183 24X Fiche: 50-329, 83/02/24, 8303010668.

8303030389 Summary of 830208 telcon w/applicant & Bechtel re underpinning const of turbine & auxiliary bldgs.
HOOD, D. S. Licensing Branch 4 83/02/24 Licensing Branch 4 7pp. 17419:317 24X Fiche: 50-329, 83/02/24, 8303030389.

8303020296 Notification of 830311 meeting w/util in Bethesda, MD to discuss const completion date for facility.
HERNAN, R. W. Licensing Branch 4 83/02/25 ADENSAM, E. G. Licensing Branch 4 2pp. 17355:299 24X Fiche: 50-330, 83/02/25, 8303020296.

8303020302 Notification of 830307 meeting w/util in Bethesda, MD to discuss sys interaction program.
HERNAN, R. W. Licensing Branch 4 83/02/25 ADENSAM, E. G. Licensing Branch 4 2pp. 66614:248 24X Fiche: 50-329, 83/02/25, 8303020302.

8303090140 Forwards "Process Control Program for Midland Nuclear Cogeneration Plant."
COOK, J. W. Consumers Power Co. 83/02/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 17470:199 24X Fiche: 50-329, 83/02/25, 8303090140.

--8303090152 "Process Control Program for Midland Nuclear Cogeneration Plant."
* Consumers Power Co. 83/02/25 79pp. 17470:201 24X Fiche: 50-329, 83/02/25, 8303090140.

8303140210 Forwards marked-up proposed Tech Specs for review & comment, per EG Adensam 830105 request. Comments requested by 830502.
COOK, J. W. Consumers Power Co. 83/02/25 DENTON, H. R. Division of Licensing 755pp. 17529:264 24X Fiche: 50-329, 83/02/25, 8303140210.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700:303 24X Fiche: 50-000, 83/02/02, 8303020321.

8303140083 Forwards two pages inadvertently omitted from QA documents forwarded on 830222 re independent design & const verification program.
HOOD, D. S. Licensing Branch 4 83/03/02 Licensing Branch 4 4pp. 17548:309 24X Fiche: 50-329, 83/03/02, 8303140083.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J. G. Region 3, Office of Director 83/03/03 Commonwealth Edison Co. 2pp. 17492:014 24X Fiche: 50-000, 83/03/03, 8303100364.

8303170393 Documents 830302 discussions w/NRC re work activity list. Concurs w/deleting "Monitor & Adjust Pier Jacks After Load Transfer" from work activity list.
MILLER, D. B. Consumers Power Co. 83/03/03 SHAFER, W. D. Region 3, Office of Director 1p. 17610:085 24X Fiche: 50-329, 83/03/03, 8303170393.

8303220370 Forwards 821213 ltr to be inserted in front of Vol 1, Rev 1 to environ qualification rept.
BAUMAN, R. C. Consumers Power Co. 83/03/03 NRC - No Detailed Affiliation Given 1p. 17656:017 24X Fiche: 50-329, 83/03/03, 8303220370.

8303170385 Confirms 830303 telcon w/R Gardner to obtain concurrence on purchase of non-Q matls for underpinning instrumentation for svc water pump structure. QA program requirements will be invoked upon receipt & installation.
MILLER, D. B. Carolina Power & Light Co. 83/03/04 SHAFER, W. D. Region 3, Office of Director 1p. 17610:084 24X Fiche: 50-329, 83/03/04, 8303170385.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5ipp. 17660:176 24X Fiche: 50-000, 83/03/07, 8303040005.

8303170136 Summary of 830223 meeting w/B&W Regulatory Response Group in Bethesda,MD re small break LOCA procedures & maintaining proper steam generator water level.
VAN VLIET, J. Operating Reactors Branch 4 83/03/08 Operating Reactors Branch 4 43pp 17615:224 24X Fiche:50-000,83/03/08, 8303170136.

8303280275 Confirms 830304 telcon informing of final disposition of slope layback As-built condition acceptable.Remaining work involving placement of temporary cribbing on east side of layback adjacent to turbine bldg authorized.
MILLER,D.B. Consumers Power Co 83/03/08 SHAFER,W.D. Region 3, Office of Director 1p 17706:038 24X Fiche:50-330,83/03/08, 8303280275.

8303170388 Submits list of work activities discussed in 830308 telcon. Authorization to commence listed work requested.
MILLER,D.B. Consumers Power Co 83/03/09 SHAFER,W.D. Region 3, Office of Director 1p 17609:281 24X Fiche:50-329,83/03/09, 8303170388.

8303110362 Forwards Rev 1 to "Reactor Bldg Spray Sys Centrifugal Pump," "Reactor Bldg Spray Sys Hydrazine Addition Positive Displacement Pump" & "Hydraulic Snubbers," based on util response to NRC request re equipment qualification program.
HOOD,D.S. Licensing Branch 4 83/03/10 Licensing Branch 4 4pp 17544:327 24X Fiche:50-329,83/03/10,8303110362.

--8303110365 Rev 1 to "Reactor Bldg Spray Sys Centrifugal Pump."
* NUTECH Engineers, Inc. 83/02/02 133pp 17544:331 24X Fiche:50-329,83/03/10,8303110362.

--8303110369 Rev 1 to "Reactor Bldg Spray Sys Hydrazine Addition Positive Displacement Pump."
* NUTECH Engineers, Inc. 83/02/02 111pp 17545:104 24X Fiche:50-329,83/03/10,8303110362.

--8303110374 Rev 1 to "Hydraulic Snubbers."
* NUTECH Engineers, Inc. 83/02/02 350pp 17545:215 24X Fiche:50-329,83/03/10,8303110362.

8303180153 Confirms 830223 discussions w/D Budzik & D Wuokko re submittals of draft Tech Specs for NRC review.
ADENSAM,E.G. Licensing Branch 4 83/03/10 COOK,J.W. Consumers Power Co 3pp 17626:007 24X Fiche:50-329,83/03/10,8303180153.

8303210267 Forwards B Garde (Govt Accountability Project) 830307 ltr w/comments on licensee const completion plan.
HOOD,D.S. Licensing Branch 4 83/03/14 Licensing Branch 4 1p 17659:035 24X Fiche:50-329,83/03/14,8303210267.

--8303210274 Addresses concerns re issues presented at 830208 public meeting.Issues for which addl info required listed.Process for choosing third-party auditor should be considered important & delicate matter by NRR.
GARDE,B.P. Government Accountability Project 83/03/07
EISENHUT,D.G. Division of Licensing 5pp 17659:036 24X Fiche:50-329,83/03/14,8303210267.

--8303210282 Discusses periodic questionable QA re const activities.Util should develop design & const verification program by independent contractor & must be made aware of importance of focus on correcting identified problems in timely manner.
NORELIUS,C.E. Division of Engineering SPESSARD,R.L. Division of Project & Resident Programs 82/06/21 KEPPLER,J.G. Region 3, Office of Director 5pp 17659:047 24X Fiche:50-329,83/03/14, 8303210267.

--8303210298 Provides list of items for consideration as indicative of questionable licensee performance.Items have become nuisance under reactive insp progra..
COOK,R.J. Region 3, Office of Director 82/06/23 WARNICK,R.F. Region 3, Office of Director 8pp 17659:052 24X Fiche:50-329,83/03/14,8303210267.

--8303210295 Summary of 820726 onsite meeting w/NPR re licensee performance & 820621 & 23 memos.Licensee should obtain independent design review & independent third-party to monitor implementation continuously.
WARNICK,R.F. Region 3, Office of Director 82/08/18 Region 3, Office of Director 1p 17659:060 24X Fiche:50-329,83/03/14, 8303210267.

--8303210301 Discusses actions taken re concerns surrounding facility performance.Augmented insp effort coupled w/other actions to strengthen QC/QA organization & mgt recommended.Actions should be discussed w/NRR & licensee.
WARNICK,R.F. Region 3, Office of Director 82/08/18
KEPPLER,J.G. Region 3, Office of Director 2pp 17659:061 24X Fiche:50-329,83/03/14,8303210267.

--8303210307 Notifies that B&W acceptable as third party to perform independent assessment of soils remedial work activities. Scope of work should be broadened to include QA overview of design work packages.
KEPPLER,J.G. Region 3, Office of Director 83/02/24 COOK,J.W. Consumers Power Co 3pp 17659:063 24X Fiche:50-329,83/03/14, 8303210267.

--8303210312 Lists concerns corrected or in process of being corrected by licensee since work began on const of piers 17E & 12W.Only five insps performed to determine acceptability of work.
LANDSMAN,R.B. Region 3, Office of Director 83/02/15
WARNICK,R.F. Region 3, Office of Director 2pp 17659:066 24X Fiche:50-329,83/03/14,8303210267.

8303220169 Forwards affidavits & resumes for addl team members assigned to independent assessment of underpinning work at facilities.Individuals meet "independence" requirements.
LUCAS,A.S. Stone & Webster, Inc. 83/03/15 KEPPLER,J.G. Region 3, Office of Director 13pp 17659:255 24X Fiche:50-329,83/03/15, 8303220169.

8303240043 Requests authorization to proceed on listed resubmitted remedial soils work activities which were not started within 90 days of original approval.
MILLER,D.B. Consumers Power Co 83/03/16 SHAFER,W.D. Region 3, Office of Director 1p 17681:025 24X Fiche:50-329,83/03/16, 8303240043.

8303300711 Board Notification 83-218:forwards ltr transmitting B&W regulatory response rept re emergency feedwater spray effectiveness & small break LOCA operating procedure.
EISENHUT,D.G. Division of Licensing 83/03/16 PALLADINO,N.J., ROBERTS,T.M., ASSELSTINE,J.K. Commissioners 2pp 17764:275 24X Fiche:50-000,83/03/16,8303300711.

8303220076 Authorizes work on critical Work Activities 105050906, 312550018,322550018,207050385 & 207050386,per 830316 request.
SHAFER,W.D. Region 3, Office of Director 83/03/17 MILLER,D.B. Consumers Power Co 2pp 17652:260 24X Fiche:50-329,83/03/17, 8303220076.

--8303220082 Requests authorization to proceed on resubmitted Work Activities 105050806 re redress slope layback surfaces & 312550018,BWST 1 to reinstall piping,pipe hangers & electrical facilities.
MILLER,D.B. Consumers Power Co 83/03/16 SHAFER,W.D. Region 3, Office of Director 1p 17652:262 24X Fiche:50-329,83/03/17, 8303220076.

8303210448 Forwards affidavits attesting to corporate independence & prof qualifications of individuals who may participate in overview of const completion program.
LEVIN,H.A. TERA Corp 83/03/18 KEPPLER,J.G. Region 3, Office of Director EISENHUT,D.G. Division of Licensing 80pp 17634:054 24X Fiche:50-329,83/03/18,8303210448.

8303210685 Discusses independent design & const verification program. Corporate & individual independence,prof qualifications, scope of review,reporting & auditability & program status addressed.Affidavits encl.
LEVIN,H.A. TERA Corp 83/03/18 KEPPLER,J.G. Region 3, Office of Director EISENHUT,D.G. Division of Licensing 79pp 17635:296 24X Fiche:50-329,83/03/18,8303210685.

8303240266 Forwards converted figure for vertical axis of previously transmitted graph of Solid Waste Processing Sys II & discussion of relationship between estimated angle of internal friction & dynamic cone penetrometer resistance.
COOK,J.W. Consumers Power Co 83/03/18 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 10pp 17682:128 24X Fiche:50-329,83/03/18,8303240266.

8303240451 Requests delay until 830701 to submit plans & schedule,in response to Generic Ltr 83-10 re TMI Action Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps."
COOK,J.W. Consumers Power Co 83/03/21 EISENHUT,D.G. Division of Licensing 2pp 17678:006 24X Fiche:50-329,83/03/21,8303240451.

8303280012 Forwards Tera Corp 830318 submittal re project QA & engineering program plans for independent design & const verification program.Early selection of second sys,direction re reporting & auditability & meeting requested.
HOOD,D.S. Licensing Branch 4 83/03/21 Licensing Branch 4 2pp 17727:023 24X Fiche:50-329,83/03/21,8303280012.

8303290578 Selects electric power sys as second sys to form basis for independent design verification effort to be performed by TERA Corp.HVAC sys portion assuring control room habitability should be selected for independent review.
EISENHUT,D.G. Division of Licensing 83/03/22 COOK,J.W. Consumers Power Co 8pp 17742:353 24X Fiche:50-329,83/03/22, 8303290578.

8303300159 Summary of 830303 meeting w/util re performance sys interaction program.Viewgraphs encl.
HOOD, D. S. Licensing Branch 4 83/03/22 Licensing Branch 4
15pp. 17749:322 24X Fiche: 50-329, 83/03/22, 8303300159.

8303300661 Board Notification 83-039 Forwards Mgt Analysis Co "Const Project Evaluation of Consumers Power Co Midland Energy Project Units 1 & 2," as info relevant to safety issues in OM/OL proceeding.
NOVAK, T. M. Assistant Director for Licensing 83/03/24 Atomic Safety and Licensing Board Panel 4pp. 17770:029 24X
Fiche: 50-329, 83/03/24, 8303300661.

--8303300665 Rev 1 to "Const Project Evaluation of Consumers Power Co Midland Energy Ctr Project Units 1 & 2."
* Management Analysis Co. 83/03/00 201pp. 17770:033 24X
Fiche: 50-329, 83/03/24, 8303300661.

8303300785 Requests that copies of all correspondence re independent design & const verification program be forwarded to persons on encl svc list.
ADENSAM, E. G. Licensing Branch 4 83/03/24 LEVIN, H. TERA Corp
2pp. 17765:270 24X Fiche: 50-329, 83/03/24, 8303300785.

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303110251 Forwards "Reactor Protection Sys Setpoint Methodology" & "Safety-Related Instrument Setpoint Methodology for Balance of Plant Equipment," per SER Confirmatory Item 15.
COOK, J. W. Consumers Power Co 83/03/09 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 17515:315 24X
Fiche: 50-329, 83/03/09, 8303110251.

--8303110253 "Reactor Protection Sys Setpoint Methodology."
* Consumers Power Co. 83/03/09 22pp. 17515:317 24X
Fiche: 50-329, 83/03/09, 8303110251.

--8303110263 "Safety-Related Instrument Setpoint Methodology for Balance of Plant Equipment."
* Consumers Power Co. 83/03/09 11pp. 17515:329 24X
Fiche: 50-329, 83/03/09, 8303110251.

8303240458 Provides justification for testing emergency core cooling actuation sys auxiliary relays & auxiliary feedwater pump suction transfer logic on 18-month interval basis. Info completes SER Confirmatory Issues 18 & 19.
COOK, J. W. Consumers Power Co. 83/03/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 4pp. 17678:061 24X
Fiche: 50-329, 83/03/17, 8303240458.

8303280118 Ack receipt of util 830309 ltr commenting on SER, Suppl 2. Comments will be considered for inclusion in future SER suppl.
WARNICK, R. F. Region 3, Office of Director 83/03/23 MOONEY, J. A. Consumers Power Co. 1p. 17709:346 24X Fiche: 50-329, 83/03/23, 8303280118.

--8303280120 Forwards comments on Suppl 2 to SER, NUREG-0793.
MOONEY, J. D. Consumers Power Co. 83/03/09 SHAFER, W. D. Region 3, Office of Director 4pp. 17709:347 24X Fiche: 50-329, 83/03/23, 8303280118.

F. Security, medical, emergency & fire protection plans

8303170280 Responds to 821028 ltr re security provisions for fission chamber assemblies. Points of clarification for procedures for control of locks & keys listed Encls I & II to 821028 ltr withheld (ref 10CFR2.790).
EVANS, L. J. Fuel Facility Safeguards Licensing Branch 82/11/24
COOK, J. W. Consumers Power Co. 2pp. 17623:073 24X
Fiche: 50-329, 82/11/24, 8303170280.

8303090008 Forwards comments on emergency action levels contained in Section 4 of Rev 1 to radiological emergency response plan. Several levels require mod or suppl. Response required within 30 days of ltr receipt.
ADENSAM, E. G. Licensing Branch 4 83/02/28 COOK, J. W. Consumers Power Co. 17pp. 17466:194 24X Fiche: 50-329, 83/02/28, 8303090008.

8303240027 Informs that response to NRC 821126 request for info re App R guidance concerning associated circuits related to fire protection safe shutdown will be forwarded in early Sept 1983.
COOK, J. W. Consumers Power Co. 83/03/16 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p. 17681:095 24X
Fiche: 50-329, 83/03/16, 8303240027.

8303240640 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director 83/03/22 Commonwealth Edison Co. 2pp. 17690:316 24X Fiche: 50-000, 83/03/22, 8303240440.

G. Adjudicatory correspondence

8303100059 Appeals denial of FOIA request for confidential proposed QA stipulation prepared for OL & CP proceedings.
STAMIRIS, B. Stamiris, B. 82/10/13 Office of the Secretary of the Commission 1p. 17504:079 24X Fiche: 50-330, 82/10/13, 8303100059.

8303100204 Responds to appeal re denial of FOIA request for confidential proposed QA stipulation prepared for OL & CP proceedings. Document withheld (ref FOIA Exemptions 4 & 5).
CHILK, S. J. Office of the Secretary of the Commission 83/02/04
STAMIRIS, B. Stamiris, B. 1p. 17504:085 24X Fiche: 50-330, 83/02/04, 8303100204.

--8303100216 Denies request for extension for filing appeal re FOIA request for proposed QA stipulation in OL & CP proceedings. Request for reconsideration may be submitted when proceeding completed.
FELTON, J. M. Division of Rules and Records 81/08/20 STAMIRIS, B. Stamiris, B. 1p. 17504:087 24X Fiche: 50-330, 83/02/04, 8303100204.

--8303100225 Requests extension of 20 days beyond initial decision in OL/CP proceedings to file FOIA appeal for confidential proposed QA stipulation.
STAMIRIS, B. Stamiris, B. 81/08/12 FELTON, J. M. Division of Rules and Records 1p. 17504:088 24X Fiche: 50-330, 83/02/04, 8303100204.

8303140374 Forwards staff testimony on Sinclair Contention 3 & stipulation between NRC & applicant re alleged matl false statement in FSAR. ASLB 830214 order permits testimony to be filed on Sinclair Contention 3 by 830218.
WILCOVE, M. N. Hearing Branch 2 83/02/07 BECHHOEFER, C. Atomic Safety and Licensing Board Panel 2pp. 17533:295 24X
Fiche: 50-329, 83/02/07, 8303140374.

--8303140432 Stipulation agreeing not to contest that matl false statement made in FSAR re fill & backfill placement per Table 2.5-9 & that matl false statement was unintentional.
WILCOVE, M. N. Hearing Branch 2 STEPTOE, P. P. Consumers Power Co. 83/02/07 1p. 17533:345 24X Fiche: 50-329, 83/02/07, 8303140374.

8303010171 Notice of appearance in proceeding. Certificate of Svc encl.
GILOMEN, B. R. Consumers Power Co. GILOMEN, B. R. Isham, Lincoln & Beale 83/02/22 3pp. 17333:353 24X Fiche: 50-329, 83/02/22, 8303010171.

8303010179 Forwards Figure 29, "Summary of Actual & Estimated Settlements (For Finite Element Analysis)," inadvertently omitted from applicant Exhibit 30 entered into evidence on 821210. Certificate of Svc encl.
STEPTOE, P. P. Isham, Lincoln & Beale STEPTOE, P. P. Consumers Power Co. 83/02/23 BECHHOEFER, C., HARBOUR, J., COWAN, F. P. Atomic Safety and Licensing Board Panel 4pp. 17332:359 24X
Fiche: 50-329, 83/02/23, 8303010179.

8303010077 Invites present or past site workers who have made allegations to visit site under terms described in JW Cook 821228 ltr. Related correspondence.
BRUNNER, J. E. Consumers Power Co. 83/02/24 GARDE, B. Government Accountability Project 3pp. 17341:063 24X Fiche: 50-329, 83/02/24, 8303010077.

8303070132 Informs that NUREG/CR-2300, "PRA Procedures Guide," sent to LPDR.
WILCOVE, M. N. Hearing Branch 2 83/03/04 SINCLAIR, M. Sinclair, M. 1p. 17433:075 24X Fiche: 50-329, 83/03/04, 8303070132.

8303080441 Notice rescheduling 830412-16 & 18-22 hearings on QA/QC issues for 830426-30 & 0502-06 in Midland, MI.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel ES/03/04
1p. 17454:240 24X Fiche: 50-329, 83/03/04, 8303080441.

8303160775 Advises that only remaining issues to be litigated in hearing requested by applicant re 791206 order are QA & matters involving pending investigations. ASLB urged completion of investigation in time for 830426 hearing.
CUNNINGHAM, G. H. Office of the Executive Legal Director 83/03/08
HAYES, B. B. Office of Investigation 1p. 17600:182 24X
Fiche: 50-329, 83/03/08, 8303160775.

--8303160778 Requests investigation of two alleged violations of ASLB 820430 order re excavation below deep G duct & initiation of fireline relocation activities w/o NRC authorization.
KEPPLER, J. G. Region 3, Office of Director. 82/0[illegible]
FITZGERALD, J. A. Office of Investigation. 2pp. 1 [illegible]83. 24X Fiche: 50-329, 83/03/08, 8303160775.

8303170006 Advises that allegations in five affidavits referred to Region III for investigation. CPC attys voluntarily refrained from engaging in discovery. GA hearing scheduled for 830426. Other issues arising from 791206 order submitted to ASLB.
CUNNINGHAM, G. H. Office of the Executive Legal Director. 83/03/08.
KEPPLER, J. G. Region 3, Office of Director. 1p. 17624:341. 24X Fiche: 50-329, 83/03/08, 8303170006.

8303100351 Notice of 830329-0401 hearings in Midland [illegible]on OL issues. Limited appearance statements will be heard on 830329.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 83/03/09. 2pp. 17490:354. 24X Fiche: 50-329, 83/03/09, 8303100351.

8303150417 Notice of 830328 addl evidentiary hearings on OL issues in Midland, MI.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 83/03/11. 1p. 17561:238. 24X Fiche: 50-329, 83/03/11, 8303150417.

8303180410 Requests info on dewatering sys & wells at plant. Related correspondence.
GADLER, S. J. Mapleton Intervenors. 83/03/11. NRC - No Detailed Affiliation Given. 2pp. 17622:027. 24X Fiche: 50-329, 83/03/11, 8303180410.

8303160113 Forwards rept summary for NUREG/CR-2497, "Precursors to Potential Severe Core Damage Accident: 1969-1979." W/o encl.
WRIGHT, N. Hearing Branch 2. 83/03/14. STAMIRIS, B. Stamiris, B. MARSHALL, W. H. Marshall, W. H. SINCLAIR, M. Sinclair, M. 1p. 17596:360. 24X Fiche: 50-329, 83/03/14, 8303160113.

8303180398 Forwards NRC Byron testimony re Class 9 accidents which applicant distributed to parties at 830308-11 hearings. Testimony will be useful background reading for NRC Midland testimony when filed.
KINNEAR, W. Isham, Lincoln & Beale. KINNEAR, W. Consumers Power Co. 83/03/15. COWAN, F. P. Atomic Safety and Licensing Board Panel. 2pp. 17629:222. 24X Fiche: 50-329, 83/03/15, 8303180398.

8303220172 Forwards transcript of util president, J Selby radio interview. Selby comment on plant completion referred to time needed to complete both units. Related correspondence.
STEPTOE, P. P. Isham, Lincoln & Beale. STEPTOE, P. P. Consumers Power Co. 83/03/15. BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 30pp. 17658:075. 24X Fiche: 50-329, 83/03/15, 8303220172.

8303220181 Praises JE Carlson & SY Tsai performances as witnesses & expresses regret over Carlson leaving ANL.
PATON, W. D. Hearing Branch 2. 83/03/17. HALLETT, W. J. Argonne National Laboratory. 1p. 17657:165. 24X Fiche: 50-329, 83/03/17, 8303220181.

8303310228 Forwards NUREG/CR-3069, "Interaction of Electromagnetic Pulse W/Commercial Nuclear Power Plant Sys" & executive summary, per 830312 request. W/o encl.
WRIGHT, N. A. Hearing Branch 2. 83/03/17. MARSHALL, W. A. Mapleton Intervenors. 1p. 17755:355. 24X Fiche: 50-329, 83/03/17, 8303310228.

8303240522 Memorializes 830309 meeting during hearing recess, subsequent telcons & ltrs re requests for informal discovery on matters to be covered in Apr hearings.
WILLIAMS, F. C. Isham, Lincoln & Beale. 83/03/22. STAMIRIS, B. Stamiris, B. SINCLAIR, M. Sinclair, M. 3pp. 17682:278. 24X Fiche: 50-329, 83/03/22, 8303240522.

8303250161 Requests to make limited appearance statement at 830329 hearings in Midland, MI.
BROWN, F. L. Affiliation Unknown. 83/03/22. Docketing & Services Branch. 1p. 17691:117. 24X Fiche: 50-329, 83/03/22, 8303250161.

8303290497 Requests to testify at 830329 hearings.
MACDONALD, S. W. Midland County, MI. 83/03/22. Docketing & Services Branch. 1p. 17725:049. 24X Fiche: 50-329, 83/03/22, 8303290497.

8303290455 Forwards proprietary documents requested by discovery in OL proceedings. Documents are provided per protective order adopted by ASLB on P 12,358 of transcript. W/o encl. Related correspondence.
BRUNNER, J. E. Consumers Power Co. 83/03/23. STAMIRIS, B. Affiliation Unknown. 2pp. 17725:327. 24X Fiche: 50-329, 83/03/23, 8303290455.

8303290511 Requests to testify at 830329 hearings.
ASIALA Affiliation Unknown. 83/03/23. Docketing & Services Branch. 1p. 17725:110. 24X Fiche: 50-329, 83/03/23, 8303290511.

8303290531 Requests to make limited appearance statement at 830329 hearings.
CHATTERTON, R. B. Affiliation Unknown. 83/03/23. NRC - No Detailed Affiliation Given. 1p. 17725:109. 24X Fiche: 50-329, 83/03/23, 8303290531.

8303290514 Requests to make limited appearance statement at OL hearings.
GORMAN, J. [illegible] Affiliation Unknown. 83/03/24. Docketing & Services Branch. 1p. 17723:016. 24X Fiche: 50-329, 83/03/24, 8303290514.

8303310325 Requests to make limited appearance statement at 830329 hearings.
BREEN, J. Affiliation Unknown. 83/03/24. Docketing & Services Branch. 1p. 17755:044. 24X Fiche: 50-329, 83/03/24, 8303310325.

8303280302 Declines 830311 ltr requesting info re dewatering sys since discovery not open on issue.
PATON, W. D. Hearing Branch 2. 83/03/25. GADLER, S. Affiliation Unknown. 1p. 17706:291. 24X Fiche: 50-329, 83/03/25, 8303280302.

8303290509 Requests to testify at 830329 hearings.
THOMPSON, J. R. Affiliation Unknown. 83/03/25. Docketing & Services Branch. 1p. 17723:001. 24X Fiche: 50-329, 83/03/25, 8303290509.

H. General correspondence

8303090197 Comments on util mistakes, mismanagement & cost overruns for project. Plants not needed.
BAILEY, H. R. Affiliation Unknown. 83/02/27. DENTON, H. R. NRC - No Detailed Affiliation Given. 1p. 17472:291. 24X Fiche: 50-329, 83/02/27, 8303090197.

8303280282 Requests independent audit of plant.
ROMO, K. B. Affiliation Unknown. 83/03/24. EISENHUT, D. G. Division of Licensing. 1p. 17706:044. 24X Fiche: 50-329, 83/03/24, 8303280282.

I. Financial information

8303210279 Forwards Annual Financial Rept 1982.
PERRY, P. A. Consumers Power Co. 83/03/15. GIAMBUSSO, A. Division of Licensing. 1p. 17632:003. 24X Fiche: 50-000, 83/03/15, 8303210279.

--8303210286 Annual Financial Rept 1982.
SELBY, J. P. Consumers Power Co. 83/02/04. 29pp. 17632:004. 24X Fiche: 50-000, 83/03/15, 8303210279.

O. Inspection reports, IE Bulletins & correspondence

8303140398 Grants access to job site to sources of allegations only in presence of NRC investigators.
COOK, J. W. Consumers Power Co. 82/12/28. KEPPLER, J. G. Region 3, Office of Director. 2pp. 17542:131. 24X Fiche: 50-329, 82/12/28, 8303140398.

8303110254 Discusses IE insp on 821012-1125 & 830119-21 & forwards notice of violation & proposed imposition of civil penalty.
KEPPLER, J. G. Region 3, Office of Director. 83/02/08. SELBY, J. D. Consumers Power Co. 3pp. 17515:299. 24X Fiche: 50-329, 83/02/08, 8303110254.

--8303110261 Notice of proposed violation & proposed imposition of civil penalty in amount of $120,000. Noncompliance noted: failure to assure that complete insp of drawings & specs performed after deficiencies corrected.
KEPPLER, J. G. Region 3, Office of Director. 83/02/08. 13pp. 17515:302. 24X Fiche: 50-329, 83/02/08, 8303110254.

8303110363 Forwards IE Insp Rpts 50-329/82-22 & 50-330/82-22 on 821012-1125 & 830119-21. Separate ltr addressing noncompliance items transmitted.
KEPPLER, J. G. Region 3, Office of Director. 83/02/08. SELBY, J. D. Consumers Power Co. 2pp. 17506:276. 24X Fiche: 50-329, 83/02/08, 8303110363.

--8303110366 IE Insp Rpts 50-329/82-22 & 50-330/82-22 on 821012-1125 & 830119-21. Noncompliance noted: failure to establish adequate design control measures & QA procedures & to conduct adequate component source & receipt insps.
BARRETT, P. A., BURGESS, B. L., COOK, R. J. Region 3, Office of Director. 83/02/01. 29pp. 17506:278. 24X Fiche: 50-329, 83/02/08, 8303110363.

8303090094 Responds to FOIA request for documents re NRC statement in 821113 Philadelphia Inquirer Statement made by Keppler based on impressions formed over period of yrs & not specific documents Forwards documents listed in app
FELTON, J M. Division of Rules and Records. 83/02/14. ROMANO, F R. Air and Water Pollution Patrol. 2pp. 17465:202. 24X Fiche: 50-329, 83/02/14, 8303090094.

--8303090100 Forwards agenda of 821029 mgt meeting w/Bechtel Corp re means to improve Bechtel image & regulatory posture at plant site.
COOK, R J. Region 3, Office of Director. 82/12/16. Region 3, Office of Director. 19pp. 17465:205. 24X Fiche: 50-329, 83/02/14, 8303090094.

--8303090108 Forwards list of items considered by various inspectors to be indicative of questionable licensee performance
COOK, R J. Region 3, Office of Director. 82/07/23. WARNICK, R F. Region 3, Office of Director. 8pp. 17465:224. 24X Fiche: 50-329, 83/02/14, 8303090094.

8303110355 Board Notification 83-14: forwards followup info on apparent deficiencies in Midland-Ross superstrut matl.
EISENHUT, D G. Division of Licensing. 83/02/18. PALLADINO, N. Commissioners. 24pp. 17546:205. 24X Fiche: 50-000, 83/02/18, 8303110355.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303220215 Forwards IE Insp Repts 50-329/83-02 & 50-330/83-02 on 830216-18. No noncompliance noted.
PAPERIELLO, C J. Region 3, Office of Director. 83/03/03. COOK, J W. Consumers Power Co. 2pp. 17656:253. 24X Fiche: 50-329, 83/03/03, 8303220215.

--8303220229 IE Insp Repts 50-329/83-02 & 50-330/83-02 on 830216-18. No noncompliance noted. Major areas inspected preoperational & routine operational insp program in radiation protection & radwaste mgt areas.
GRANT, W B., GREGER, L R. Region 3, Office of Director. 83/03/03. 5pp. 17656:255. 24X Fiche: 50-329, 83/03/03, 8303220215.

8303170428 Forwards IE Insp Repts 50-329/83-01 & 50-330/83-01 on 830111-14 & notice of violation.
WARNICK, R F. Region 3, Office of Director. 83/03/04. COOK, J W. Consumers Power Co. 2pp. 17611:001. 24X Fiche: 50-329, 83/03/04, 8303170428.

--8303170433 Notice of violation from insp on 830111-14.
WARNICK, R F. Region 3, Office of Director. 83/03/04. 1p. 17611:003. 24X Fiche: 50-329, 83/03/04, 8303170428.

--8303170436 IE Insp Repts 50-329/83-01 & 50-330/83-01 on 830111-14. Noncompliance noted: failure to follow procedures re issuing untagged valve to welding fabrication area.
SIMON, J A., SATHER, A., SHAFER, W D. Region 3, Office of Director. 83/02/25. 5pp. 17611:004. 24X Fiche: 50-329, 83/03/04, 8303170428.

8303180209 Responds to NRC 830208 notice of violation & proposed imposition of civil penalties. Corrective actions: Category I work halted, in-process insp notices to be reviewed & QC engineers instructed to complete insp activities.
COOK, J W. Consumers Power Co. 83/03/10. DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. 51pp. 17617:289. 24X Fiche: 50-329, 83/03/10, 8303180209.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-12, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

R Periodic operating reports & related correspondence

8303220016 "Nonconformance Repts for Dec 1982."
* Bechtel Corp. * Consumers Power Co. 82/12/31. 693pp. 17650:103. 24X Fiche: 50-329, 82/12/31, 8303220016.

8303100208 Forwards, in accordance w/ALAB-106 dtd 730323 & Amend 1 to CP, Bechtel monthly nonconformance repts & log sheets, Bechtel FSO nonconformance repts & log sheets & Bechtel QA findings.
COOK, J W. Consumers Power Co. 83/02/22. DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. 865pp. 17486:001. 24X Fiche: 50-329, 83/02/22, 8303100208.

S Reportable occurrences, LERs & related correspondence

8303100384 Interim deficiency rept re hardness values of anchor & connecting studs for reactor coolant pump snubbers. Snubber stud tension checked, low alloy quenched & tempered bolting tested. Next rept expected by 830319.
COOK, J W. Consumers Power Co. 83/02/22. KEPPLER, J G. Region 3, Office of Director. 8pp. 17490:339. 24X Fiche: 50-329, 83/02/22, 8303100384.

8303100188 Interim deficiency rept re delivered, safety-related electrical equipment not meeting project requirements. Task force established by Bechtel to investigate & resolve problems. Next rept will be submitted by 830513.
COOK, J W. Consumers Power Co. 83/02/25. KEPPLER, J G. Region 3, Office of Director. 7pp. 17489:168. 24X Fiche: 50-329, 83/02/25, 8303100188.

8303100263 Interim Deficiency Rept 1 to MCAR 22 re reactor bldg spray piping supports. Deficiency reopened due to possible unconservative water hammer loads used in original design analysis. Bechtel rept encl. Next rept expected by 830711.
COOK, J W. Consumers Power Co. 83/02/25. KEPPLER, J G. Region 3, Office of Director. 6pp. 17490:298. 24X Fiche: 50-329, 83/02/25, 8303100263.

8303100310 Interim deficiency rept re B&W steam generator auxiliary feedwater header design change. Initially reported on 820526. B&W supplied preliminary 10CFR21 rept on nonapproved vendor flanges returned. Matl recertified. Next rept by 830531.
COOK, J W. Consumers Power Co. 83/02/28. KEPPLER, J G. Region 3, Office of Director. 2pp. 17489:282. 24X Fiche: 50-329, 83/02/28, 8303100310.

8303100219 Interim Deficiency Rept 2 to MCAR 63 re shear lug design embedments. Approx 2,500 embedments identified to date. No corrective action established. Bechtel rept encl. Next rept expected by 830520.
COOK, J W. Consumers Power Co. 83/03/01. KEPPLER, J G. Region 3, Office of Director. 5pp. 17489:228. 24X Fiche: 50-329, 83/03/01, 8303100219.

8303150620 Board Notification 83-26: forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys. Info may affect conclusions re probability of/corrective actions for ATWS.
EISENHUT, D G. Division of Licensing. 83/03/03. PALLADINO, N. Commissioners. 24pp. 17584:097. 24X Fiche: 50-000, 83/03/03, 8303150620.

8303140463 Interim Deficiency Rept MCAR 64 re possible frazil ice formation in svc water intake structure. Corrective action initiated to ensure ice does not block structure. Options to prevent ice formation discussed.
COOK, J W. Consumers Power Co. 83/03/04. KEPPLER, J G. Region 3, Office of Director. 7pp. 17541:188. 24X Fiche: 50-329, 83/03/04, 8303140463.

8303140368 Interim deficiency rept re quality program & mfg deficiencies affecting radiation monitoring equipment supplied by Victoreen. Initially reported on 821015. Investigation continuing. Next rept by 830506.
COOK, J W. Consumers Power Co. 83/03/09. KEPPLER, J G. Region 3, Office of Director. 8pp. 17543:309. 24X Fiche: 50-329, 83/03/09, 8303140368.

8303140371 Interim Deficiency Rept MCAR 65 re auxiliary feedwater suction piping. Pressure relief valve will be installed on auxiliary feedwater suction line between pump & check valve. Next rept will be submitted on 830520.
COOK, J W. Consumers Power Co. 83/03/10. KEPPLER, J G. Region 3, Office of Director. 5pp. 17543:324. 24X Fiche: 50-329, 83/03/10, 8303140371.

8303240211 Interim deficiency rept re underrated terminal strips on Limitorque valve operators.All underrated terminal blocks replaced by vendor w/correctly rated Marathon 300 series terminal blocks.Next rept expected by 830607.
COOK, J.W. Consumers Power Co. 83/03/16. KEPPLER, J.G. Region 3, Office of Director. 12pp. 17682:166. 24X Fiche:50-329,83/03/16, 8303240211.

8303280135 Interim deficiency rept re adequacy of shear reinforcements at major containment penetrations.Initially reported on 810515.As-designed & as-built containment adequate.Condition not reportable per 10CFR50.55(e).
COOK, J.W. Consumers Power Co. 83/03/18. KEPPLER, J.G. Region 3, Office of Director. 5pp. 17706:345. 24X Fiche:50-329,83/03/18, 8303280135.

T. Hearing transcripts on non-antitrust matters

8303140374 Forwards staff testimony on Sinclair Contention 3 & stipulation between NRC & applicant re alleged matl false statement in FSAR.ASLB 830214 order permits testimony to be filed on Sinclair Contention 3 by 830218.
WILCOVE, M.N. Hearing Branch 2. 83/02/07. BECHHOEFER, C., COWAN, F.P., HARBOUR, J. Atomic Safety and Licensing Board Panel. 2pp. 17533:295. 24X Fiche:50-329,83/02/07, 8303140374.

--8303140420 Testimony of JN Ridgely & Aw Serkiz on Sinclair Contention 3 re water hammer problem.Prof qualifications encl.
RIDGELY, J.N. Auxiliary Systems Branch. SERKIZ, A.W. Generic Issues Branch. 83/02/07. 12pp. 17533:297. 24X Fiche:50-329,83/02/07, 8303140374.

8302280189 Order making transcript page number corrections.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 83/02/25. 1p. 17306:058. 24X Fiche:50-329,83/02/25, 8302280189.

8303020002 Forwards JE Carson & SY Tsai testimony re Sinclair Contention 14 on cooling pond thermal performance & ice & fog generation.
WRIGHT, N.A. Hearing Branch 2. 83/02/28. BECHHOEFER, C., COWAN, F.P., HARBOUR, J. Atomic Safety and Licensing Board Panel. 2pp. 17354:248. 24X Fiche:50-329,83/02/28, 8303020002.

--8303020006 Testimony of JE Carson re Sinclair Contention 14 on cooling pond.Describes analyses of ice & fog generation.Prof qualifications encl.
CARSON, J.E. NRC - No Detailed Affiliation Given. CARSON, J.E. Argonne National Laboratory. 83/02/28. 11pp. 17354:250. 24X Fiche:50-329,83/02/28, 8303020002.

--8303020011 Testimony of SY Tsai re Contention 14 on cooling pond & thermal analysis.Applicant appropriately conducted thermal performance studies for various combinations of plant operating conditions & meteorological conditions.
TSAI, S.Y. NRC - No Detailed Affiliation Given. TSAI, S.Y. Argonne National Laboratory. 83/02/28. 6pp. 17354:261. 24X Fiche:50-329,83/02/28, 8303020002.

8303030403 Forwards P 4 of DH Evans & D Sommers 830214 testimony re Sinclair Contention 14 on cooling pond.
STEPTOE, P.P. Isham, Lincoln & Beale. STEPTOE, P.P. Consumers Power Co. 83/02/28. BECHHOEFER, C., HARBOUR, J., COWAN, F.P. Atomic Safety and Licensing Board Panel. 1p. 17410:123. 24X Fiche:50-329,83/02/28, 8303030403.

--8303030413 P 4 of DH Evans & D Sommers 830214 testimony re Sinclair Contention 14 on cooling pond; inadvertently omitted.Certificate of Svc encl.
EVANS, D.H., SOMMERS, D. Consumers Power Co. 83/02/28. 3pp. 17410:124. 24X Fiche:50-329,83/02/28, 8303030403.

8303140060 Transcript of 830308 evidentiary hearing in Midland, MI. Pp 12,355-12,541.Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 83/03/08. 251pp. 17539:033. 24X Fiche:50-329,83/03/08, 8303140060.

8303150148 Transcript of 830309 evidentiary hearing in Midland, MI. Pp 12,542-12,763.Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 83/03/09. 242pp. 17550:286. 24X Fiche:50-329,83/03/09, 8303150148.

8303150163 Transcript of 830310 evidentiary hearing in Midland, MI. Pp 12,764-12,964.Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 83/03/10. 304pp. 17554:041. 24X Fiche:50-329,83/03/10, 8303150163.

8303150137 Transcript of 830311 evidentiary hearing in Midland, MI. Pp 12,965-13,100.
* Atomic Safety and Licensing Board Panel. 83/03/11. 137pp. 17554:345. 24X Fiche:50-329,83/03/11, 8303150137.

8303230243 Forwards A Savage testimony on Contention 4 re steam tube degradation problem.Contention 13 testimony re precursors to Class 9 accidents will be heard prior to steam tube degradation issue.Related correspondence.
SINCLAIR, M. Sinclair, M. 83/03/18. Atomic Safety and Licensing Board Panel. 1p. 17661:152. 24X Fiche:50-329,83/03/18, 8303230243.

--8303230248 Testimony of A Savage on Contention 4 re corrosion & sludging of condenser tubes by pond water.Prof qualifications encl.
SAVAGE, A. Sinclair, M. 83/03/18. 8pp. 17661:153. 24X Fiche:50-329,83/03/18, 8303230243.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D.G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche:50-000,83/02/24, 8302250505.

DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

F. Security, medical, emergency & fire protection plans

8303180640 Responds to 821210 ltr re Rev 10-82 to modified amended security plan.Changes consistent w/provisions of 10CFR50.54(p) & do not decrease effectiveness of plan.
VASSALLO, D.B. Operating Reactors Branch 2. 83/03/14. ARNOLD, D. Iowa Electric Light & Power Co. 2pp. 17637:150. 24X Fiche:50-331,83/03/14, 8303180640.

8303240170 Provides revised public info brochure, currently being distributed to general public within 10-mile plume exposure emergency planning zone.
ROOT, L.D. Iowa Electric Light & Power Co. 83/03/14. KEPPLER, J.G. Region 3, Office of Director. 2pp. 17681:031. 24X Fiche:50-331,83/03/14, 8303240170.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition.Appropriate planning should take place to prevent possible transmission errors.
HIND, J.A. Region 3, Office of Director. 83/03/22. Commonwealth Edison Co. 2pp. 17690:316. 24X Fiche:50-000,83/03/22, 8303240440.

8303300024 Releases public version of revised emergency plan.
FELTON, J.M. Division of Rules and Records. 83/03/23. Document Management Branch. 1p. 17751:185. 24X Fiche:50-331,83/03/23, 8303300024.

--8303300029 Forwards public version of Rev 4 to emergency plan App 3 & P N-2.
PORTZ, R. Iowa Electric Light & Power Co. 83/03/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 17751:186. 24X Fiche:50-331,83/03/23, 8303300024.

--8303300033 Public version of Rev 4 to emergency plan App 3 & P N-2.
ROOT, L.D. Iowa Electric Light & Power Co. 83/03/08. 39pp. 17751:187. 24X Fiche:50-331,83/03/23, 8303300024.

J. Insurance & indemnity information

8303230031 Forwards Endorsement 57 to NELIA Policy NF-214.
SHEA, K.H. Lowenstein, Newman, Reis, Axelrad & Toll. 83/03/17. SALTZMAN, J. Assistant Director for State & Licensee Relations. 2pp. 17663:244. 24X Fiche:50-331,83/03/17, 8303230031.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982.Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal.Svc list encl.
EISENHUT, D.G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche:50-000,83/02/16, 8302170082.

8303010339 Notifies that control rod scram time testing performed near end of Cycle 6 on 830108.Test data compared to data obtained at beginning of Cycle 6 operation.No trend of degradation exists.
ROOT, L.D. Iowa Electric Light & Power Co. 83/02/21. DENTON, H. Office of Nuclear Reactor Regulation, Director. 1p. 17346:179. 24X Fiche:50-331,83/02/21, 8303010339.

8303030703 Notification of 830307 meeting w/utils & NUS Corp in Bethesda, MD to discuss proposed rev to 10CFR40 Ap A (Tech Specs).
BRINKMAN, D. S. Standardization & Special Projects Branch 83/02/22
THOMAS, C. O. Standardization & Special Projects Branch 2pp.
17363:227 24X Fiche: 50-000, 83/02/22, 8303030703.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303080332 Application for amend to License DPR-49, changing Tech Specs to allow addition of five snubbers prior to 830630.
ROOT, L. D. Iowa Electric Light & Power Co. 83/03/02 DENTON, H. R
Office of Nuclear Reactor Regulation, Director 4pp. 17449:303
24X Fiche: 50-331, 83/03/02, 8303080332.

--8303080338 Proposed Tech Spec changes allowing addition of five snubbers prior to 830630.
* Iowa Electric Light & Power Co. 83/03/02 6pp. 17449:307
24X Fiche: 50-331, 83/03/02, 8303080332.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J. G. Region 3, Office of Director 83/03/03
Commonwealth Edison Co. 2pp. 17492:014 24X Fiche: 50-000, 83/03/03, 8303100364.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303170453 Application for amend to License DPR-49, App A consisting of Tech Spec Change RTS-148, revising Group 1 containment isolation signal from reactor vessel low-low to low-low-low water level. Proprietary rept withheld (ref 10CFR2.790).
ROOT, L. D. Iowa Electric Light & Power Co. 83/03/10 DENTON, H.
Office of Nuclear Reactor Regulation, Director 2pp. 17610:251
24X Fiche: 50-331, 83/03/10, 8303170453.

--8303170460 Proposed Tech Spec Change RTS-148, revising Group 1 containment isolation signal from reactor vessel low-low to low-low-low water level.
* Iowa Electric Light & Power Co. 83/01/26 11pp. 17610:253
24X Fiche: 50-331, 83/03/10, 8303170453.

8303300663 Forwards Amend 83 to License DPR-49, safety evaluation & notice of issuance & availability. Amend allows performance of manual stroke test on mechanical snubbers in lieu of required test.
APICELLA, F. L. Operating Reactors Branch 2 83/03/10 ARNOLD, D.
Iowa Electric Light & Power Co. 2pp. 17770:256 24X
Fiche: 50-331, 83/03/10, 8303300663.

--8303300671 Amend 83 to License DPR-49, allowing performance of manual stroke test on mechanical snubbers in lieu of required test.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/10 5pp.
17770:258 24X Fiche: 50-331, 83/03/10, 8303300663.

--8303300700 Safety evaluation supporting Amend 83 to License DPR-49.
* Office of Nuclear Reactor Regulation, Director 83/03/10 2pp.
17770:263 24X Fiche: 50-331, 83/03/10, 8303300663.

--8303300705 Notice of issuance & availability of Amend 83 to License DPR-49.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/10 2pp.
17770:265 24X Fiche: 50-331, 83/03/10, 8303300663.

8303290171 Forwards Amend 84 to License DPR-49 & notice of issuance & availability. Amend deletes App B ETS re nonradiological water quality-related requirements.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/11 ARNOLD, D.
Iowa Electric Light & Power Co. 3pp. 17730:202 24X
Fiche: 50-331, 83/03/11, 8303290171.

--8303290177 Amend 84 to License DPR-49, deleting App B ETS re nonradiological water quality-related requirements.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/11 11pp.
17730:205 24X Fiche: 50-331, 83/03/11, 8303290171.

--8303290182 Notice of issuance & availability of Amend 84 to License DPR-49.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/11 2pp.
17730:216 24X Fiche: 50-331, 83/03/11, 8303290171.

8303300163 Forwards order confirming implementation of post-TMI-related items in NUREG-0737 based on commitments in response to Generic Ltrs 82-05 & 10.
VASSALLO, D. B. Operating Reactors Branch 2 83/03/14 ARNOLD, D.
Iowa Electric Light & Power Co. 3pp. 17749:340 24X
Fiche: 50-331, 83/03/14, 8303300163.

--8303300171 Order confirming licensee commitments on post-TMI-related issues in NUREG-0737.
PURPLE, R. A. Division of Licensing 83/03/14 Iowa Electric Light & Power Co. 11pp. 17749:343 24X Fiche: 50-331, 83/03/14, 8303300163.

8303210258 Application for amend to License DPR-49, changing Tech Specs to add note to Table 6.2-1 deleting requirement for shift technical advisor during refueling mode per NUREG-0737, Item I.A.1.1.
ROOT, L. D. Iowa Electric Light & Power Co. 83/03/15 DENTON, H. R
Office of Nuclear Reactor Regulation, Director 2pp. 17632:167
24X Fiche: 50-331, 83/03/15, 8303210258.

--8303210263 Proposed Tech Spec Table 6.2-1 re min shift crew personnel & license requirements.
* Iowa Electric Light & Power Co. 83/03/15 1p. 17632:169 24X
Fiche: 50-331, 83/03/15, 8303210258.

8303210432 Application for amend to License DPR-49, consisting of proposed Tech Spec Change RTS-140a revising RTS-140 by replacing P 3.6-46 re safety-related snubbers.
ROOT, L. D. Iowa Electric Light & Power Co. 83/03/15 DENTON, H.
Office of Nuclear Reactor Regulation, Director 1p. 17634:208 24X
Fiche: 50-331, 83/03/15, 8303210432.

--8303210438 Proposed Tech Spec Change RTS-140a, replacing P 3.6-46 re safety-related snubbers.
* Iowa Electric Light & Power Co. 83/03/15 3pp. 17634:209
24X Fiche: 50-331, 83/03/15, 8303210432.

8303220207 Forwards revised P 2 to Radiological Tech Specs 140 & 140a for Snubbers HBB-1-SS-9 & HBB-1-SS-10 in RHR sys & core spray sys. Rev corrects description of change to tables listing snubbers in 830302 & 15 submittals.
ROOT, L. D. Iowa Electric Light & Power Co. 83/03/17 DENTON, H. R
Office of Nuclear Reactor Regulation, Director 2pp. 17657:137
24X Fiche: 50-331, 83/03/17, 8303220207.

8303250015 Responds to NRC 830117 request for addl info re TMI Items II.F.1.4, II.F.1.5 & II.F.1.6. Descriptions of containment pressure, water level & hydrogen monitoring sys encl, documenting compliance w/requirements of NUREG-0737.
ROOT, L. D. Iowa Electric Light & Power Co. 83/03/21 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 41pp. 17692:230
24X Fiche: 50-331, 83/03/21, 8303250015.

8303300189 Updates util progress re containment vent & purge mods during Cycle 7 outage. Installation of debris screens in drywell purge exhaust connection & relocation of test line connection for periodic leak testing will be completed.
ROOT, L. D. Iowa Electric Light & Power Co. 83/03/24 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 1p. 17733:025 24X
Fiche: 50-331, 83/03/24, 8303300189.

Q. Inspection reports, IE Bulletins & correspondence

8303080396 Forwards IE Insp Rept 50-331/82-19 on 821201-30. No noncompliance noted.
STREETER, J. F. Division of Project & Resident Programs 83/02/18
ARNOLD, D. Iowa Electric Light & Power Co. 2pp. 17454:157 24X
Fiche: 50-331, 83/02/18, 8303080396.

--8303080411 IE Insp Rept 50-331/82-19 on 821201-30. No noncompliance noted. Major areas inspected: operational safety, surveillance maint, procurement, receipt of new fuel, TMI action items, housekeeping & insp of action on 10CFR21 rept.
CLARDY, L. S.; WALKER, R. D. Division of Project & Resident Programs
83/02/18 6pp. 17454:159 24X Fiche: 50-331, 83/02/18, 8303080396.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc.
11lpp. 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303040285 Ack receipt of $840,000 in payment of civil penalties imposed by B21227 order.
AXELRAD, J. A. Enforcement Staff. 83/02/25. ROOT, L. D. Iowa Electric Light & Power Co. 2pp. 17426:253. 24X Fiche: 50-331, 83/02/25. 8303040285.

8303030464 Clarifies NRC position re procedures for admitting NRC personnel to facility. Site orientation re issuance of badges; escort duties & emergency evacuation for personnel listed in Encls 1 & 2 requested.
KEPPLER, J. G. Region 3, Office of Director. 83/02/28. ARNOLD, D. Iowa Electric Light & Power Co. 6pp. 17409:073. 24X Fiche: 50-331, 83/02/28, 8303030464.

8303290488 Forwards update to regulatory performance improvement program, providing status of each category discussed on 830210. Actions designed to improve mgt effectiveness & efficiency of operation.
LIU, L. Iowa Electric Light & Power Co. 83/02/28. KEPPLER, J. G. Region 3, Office of Director. 8pp. 17724:356. 24X Fiche: 50-331, 83/02/28, 8303290488.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303150609 Ack receipt of 830228 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-331/82-18.
STREETER, J. F. Division of Project & Resident Programs. 83/03/11. ARNOLD, D. Iowa Electric Light & Power Co. 1p. 17569:020. 24X Fiche: 50-331, 83/03/11, 8303150609.

--8303150612 Responds to NRC 830126 ltr re violations noted in IE Insp Rept 50-331/82-18. Corrective actions: valve line-ups immediately verified; valves properly locked & personnel reinstructed.
ROOT, L. D. Iowa Electric Light & Power Co. 83/02/28. KEPPLER, J. G. Region 3, Office of Director. 2pp. 17569:021. 24X Fiche: 50-331, 83/03/11, 8303150609.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 12ipp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

R Periodic operating reports & related correspondence

8303010490 Forwards "Semiannual Effluent Release Rept, Jul - Dec 1982." MINECK, D. L. Iowa Electric Light & Power Co. 83/02/22. NRC - No Detailed Affiliation Given. 1p. 17343:081. 24X Fiche: 50-331, 83/02/22, 8303010490.

--8303010493 "Semiannual Effluent Release Rept, Jul - Dec 1982." * Iowa Electric Light & Power Co. 83/02/22. 10pp. 17343:082. 24X Fiche: 50-331, 83/02/22, 8303010490.

8303150215 Forwards "Semiannual Rept Radioactive Effluent Releases, Jul-Dec 1982." MINECK, D. L. Iowa Electric Light & Power Co. 83/02/22. KEPPLER, J. Region 3, Office of Director. 1p. 17554:030. 24X Fiche: 50-331, 83/02/22, 8303150215.

--8303150221 "Semiannual Rept Radioactive Effluent Releases, Jul-Dec 1982." * Iowa Electric Light & Power Co. 83/02/22. 10pp. 17554:031. 24X Fiche: 50-331, 83/02/22, 8303150215.

8303290327 Forwards personnel monitoring repts for 1982 per 10CFR20.407.
MINECK, D. L. Iowa Electric Light & Power Co. 83/03/11. KEPPLER, J. Region 3, Office of Director. 1p. 17716:237. 24X Fiche: 50-331, 83/03/11, 8303290327.

--8303290333 Personnel monitoring repts for 1982. * Iowa Electric Light & Power Co. 83/03/11. 2pp. 17716:238. 24X Fiche: 50-331, 83/03/11, 8303290327.

8303220061 Forwards monthly operating rept for Feb 1983.
MINECK, D. L. Iowa Electric Light & Power Co. 83/03/15. Director's Office, Office of Inspection and Enforcement. 1p. 17652:171. 24X Fiche: 50-331, 83/03/15, 8303220061.

--8303220062 Monthly operating rept for Feb 1983.
MILLER, W. Iowa Electric Light & Power Co. 83/03/15. 6pp. 17652:172. 24X Fiche: 50-331, 83/03/15, 8303220061.

S Reportable occurrences, LERs & related correspondence

8303030664 Forwards updated LER 82-080/03X-1.
MINECK, D. L. Iowa Electric Light & Power Co. 83/02/18. KEPPLER, J. G. Region 3, Office of Director. 1p. 17411:021. 24X Fiche: 50-331, 83/02/18, 8303030664.

--8303030665 Updated LER 82-080/03X-1 on 821122, river water supply sys traveling screen wash pump 1P-1128 found w/discharge head below Tech Spec requirement for traveling screen 1F-36P. Caused by unaligned pump & motor. Pump/motor realigned.
HILL, K. L., WATSON, M. E. Iowa Electric Light & Power Co. 83/02/18. Region 3, Office of Director. 1p. 17411:022. 24X Fiche: 50-331, 83/02/18, 8303030664.

8303030620 Forwards LER 83-002/03L-0.
MINECK, D. L. Iowa Electric Light & Power Co. 83/02/22. KEPPLER, J. G. Region 3, Office of Director. 1p. 17409:296. 24X Fiche: 50-331, 83/02/22, 8303030620.

--8303030627 LER 83-002/03L-0 on 830124, during normal operation, drywell to torus low differential pressure alarm received. Caused by valve CV-4316 not opening properly due to inadequate calibr. Design review initiated.
HILL, K. L., BENTLEY, W. M. Iowa Electric Light & Power Co. 83/02/22. Region 3, Office of Director. 1p. 17409:297. 24X Fiche: 50-331, 83/02/22, 8303030620.

8303030570 RO 83-01: on 830214, uncontrolled release of low level activity liquid occurred when 20 gallons of condensate svc water leaked from mobile hydrolazer pump trailer into nearby storm sewer. Caused by poor equipment design. Leakage stopped.
MINECK, D. L. Iowa Electric Light & Power Co. 83/02/24. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17409:029. 24X Fiche: 50-331, 83/02/24, 8303030570.

8303140407 Forwards LER 83-009/03L-0.
MINECK, D. L. Iowa Electric Light & Power Co. 83/03/03. KEPPLER, J. G. Region 3, Office of Director. 1p. 17542:188. 24X Fiche: 50-331, 83/03/03, 8303140407.

--8303140408 LER 83-009/03L-0 on 830221, during cold shutdown surveillance testing, PS-1917A & PS-1917B tripped out of spec low at 93 & 89 psig, respectively. Caused by instrument drift. PS-1917A & PS-1917B recalibr.
HILL, K. L. Iowa Electric Light & Power Co. 83/03/03. Region 3, Office of Director. 1p. 17542:189. 24X Fiche: 50-331, 83/03/03, 8303140407.

8303140413 Forwards LER 83-007/03L-0.
MINECK, D. L. Iowa Electric Light & Power Co. 83/03/03. KEPPLER, J. G. Region 3, Office of Director. 1p. 17542:056. 24X Fiche: 50-331, 83/03/03, 8303140413.

--8303140416 LER 83-007/03L-0 on 830212, during shutdown surveillance testing, w/reactor pressure at 400 psig, instrument line in excess flow check valve XFV-4643A would not check closed & XFV-4637 & XFV-4438B gave open & closed signals when tested.
WATSON, M. E. Iowa Electric Light & Power Co. 83/03/03. Region 3, Office of Director. 1p. 17542:057. 24X Fiche: 50-331, 83/03/03, 8303140413.

8303140421 Forwards LER 83-006/03L-0.
MINECK, D. L. Iowa Electric Light & Power Co. 83/03/03. KEPPLER, J. G. Region 3, Office of Director. 1p. 17542:065. 24X Fiche: 50-331, 83/03/03, 8303140421.

--8303140428 LER 83-006/03L-0 on 830211, during normal operation, power lost to MSIV D leakage control sys. Caused by blown fuse due to random failure of high alarm relay B21 K2D. Fuse replaced. Replacement of relay under consideration.
WATSON, M. E. Iowa Electric Light & Power Co. 83/03/03. Region 3, Office of Director. 1p. 17542:066. 24X Fiche: 50-331, 83/03/03, 8303140421.

8303140435 Forwards LER 83-004/03L-0.
MINECK, D. L. Iowa Electric Light & Power Co. 83/03/03. KEPPLER, J. G. Region 3, Office of Director. 1p. 17542:227. 24X Fiche: 50-331, 83/03/03, 8303140435.

--8303140449 LER 83-004/03L-0 on 830208, during surveillance testing, RCIC motor-operated full-flow test valve MOV-2515 would not properly control flow. Caused by loose valve stem anti-rotation collar due to worn, loose set screws.
WATSON, M. E. Iowa Electric Light & Power Co. 83/03/03. Region 3, Office of Director. 1p. 17542:228. 24X Fiche: 50-331, 83/03/03, 8303140435.

8303170361 Forwards LER 83-005/03L-0.
MINECK, D. L. Iowa Electric Light & Power Co. 83/03/11. KEPPLER, J. G.
Region 3, Office of Director. 1p. 17609:331. 24X
Fiche: 50-331, 83/03/11, 8303170361.

--8303170372 LER 83-005/03L-0 on 830211, river water supply sys pumps 1P-117B & 1P-117D declared inoperative when ASME allowables exceeded. Caused by instrument error. Instrumentation will be recalibr & tested before startup from refueling.
DONNELLY, P. M. Iowa Electric Light & Power Co. 83/03/11. Region 3, Office of Director. 1p. 17609:332. 24X Fiche: 50-331, 83/03/11, 8303170361.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303010260 Forwards schedule showing licensing exam dates planned through 851231, per Generic Ltr 83-01 Apr 1983 dates firm. All others approx & tentative.
ROOT, L. D. Iowa Electric Light & Power Co. 83/02/24. EISENHUT, D. G. Division of Licensing. 2pp. 17335:133. 24X Fiche: 50-331, 83/02/24, 8303010260.

DOCKET 50-332 BARNWELL REPROCESSING PLANT

A. Application/construction stage documents & correspondence

8303250122 Trip rept of 830228-0304 site visit re current status of facility, demonstration run witnessing & review of Ray Miller Co investigation.
COLTON, J. P. Advanced Fuel & Spent Fuel Licensing Branch. 83/03/14.
ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch. 5pp. 17700:333. 24X Fiche: 50-332, 83/03/14, 8303250122.

DOCKET 50-333 JAMES A. FITZPATRICK NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

8303020008 Forwards application for amend to License DPR-59, revising App A Tech Specs to renumber mechanical snubbers for clarity, add sixteenth snubber & change emergency preparedness audit frequencies.
BAYNE, J. P. Power Authority of the State of New York. 83/02/25.
VASSALLO, D. B. Operating Reactors Branch 2. 3pp. 17353:082. 24X
Fiche: 50-333, 83/02/25, 8303020008.

--8303020015 Application for amend to License DPR-59, revising App A Tech Specs to renumber mechanical snubbers for clarity, add sixteenth snubber, per IE Bulletin 81-01 & change emergency preparedness audit frequencies.
BAYNE, J. P. Power Authority of the State of New York. 83/02/25.
2pp. 17353:085. 24X Fiche: 50-333, 83/02/25, 8303020008.

--8303020021 Proposed Tech Spec rev renumbering mechanical snubbers on Table 3.6-1b for clarity, adding sixteenth snubber & changing emergency preparedness audit frequencies.
* Power Authority of the State of New York. 83/02/25. 9pp.
17353:087. 24X Fiche: 50-333, 83/02/25, 8303020008.

8303040349 Discusses encl exemption requests from App R to 10CFR50 requirements contained in 820713 draft SER. Util will amend exemption requests no later than 830405.
BAYNE, J. P. Power Authority of the State of New York. 83/03/01.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 7pp.
17374:038. 24X Fiche: 50-333, 83/03/01, 8303040349.

8303160501 Forwards IE Insp Rept 50-333/82-26 on 821213-17. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/03.
MCNEILL, C. A. Power Authority of the State of New York. 2pp.
17593:028. 24X Fiche: 50-333, 83/03/03, 8303160501.

--8303160508 IE Insp Rept 50-333/82-26 on 821213-17. No noncompliance noted. Major areas inspected: procedures, representative records, equipment & facilities, measurement & interviews w/personnel.
COLLINS, D. J. Region 1, Office of Director. SHANBAKY, M. M. Division of Engineering & Technical Programs. 83/03/01. 12pp.
17593:030. 24X Fiche: 50-333, 83/03/03, 8303160501.

8303240557 Forwards IE Safeguards Insp Rept 50-333/83-02 on 830124-27. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/09.
MCNEILL, C. A. Power Authority of the State of New York. 2pp.
17683:205. 24X Fiche: 50-333, 83/03/09, 8303240557.

--8303240568 IE Safeguards Insp Rept 50-333/83-02 on 830124-27. No noncompliance noted. Major areas inspected: physical barriers, security sys power supply, lighting, assessment aids, access control, detection aids & alarm stations.
MADDEN, W., SMITH, G., GODY, A. T. Region 1, Office of Director. 83/03/09. 4pp. 17683:207. 24X Fiche: 50-333, 83/03/09, 8303240557.

H. General correspondence

8303080443 Informs that portion of headquarters staff has relocated. New address listed.
BAYNE, J. P. Power Authority of the State of New York. 83/03/04.
VASSALLO, D. B. Operating Reactors Branch 2. VARGA, S. A. Operating Reactors Branch 1. 2pp. 17452:351. 24X Fiche: 50-000, 83/03/04, 8303080443.

J. Insurance & indemnity information

8303080297 Forwards Endorsements 62 & 63 to NELIA Policy NF-208 & Endorsements 53 & 54 to MAELU Policy MF-77.
GOLDEN, M. P. Marsh & McLennan, Inc. 83/03/02. SALTZMAN, J. Assistant Director for State & Licensee Relations. 5pp. 17447:345. 24X Fiche: 50-000, 83/03/02, 8303080297.

P. Operating license stage documents & correspondence

8302180153 Requests addl time to respond to NRC 820825 review of radiological ETS & offsite dose calculation manual. Response undergoing final rev subsequent to receipt of revised NUREG-0472. Revised schedule forthcoming.
BAYNE, J. P. Power Authority of the State of New York. 83/01/10.
VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 17216:222. 24X
Fiche: 50-333, 83/01/10, 8302180153.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 16pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303030703 Notification of 830307 meeting w/utils & NUS Corp in Bethesda, MD to discuss proposed rev to 10CFR40 Ap (Tech Specs).
BRINKMAN, D. S. Standardization & Special Projects Branch. 83/02/22.
THOMAS, C. O. Standardization & Special Projects Branch. 2pp.
17363:227. 24X Fiche: 50-000, 83/02/22, 8303030703.

8303020008 Forwards application for amend to License DPR-59, revising App A Tech Specs to renumber mechanical snubbers for clarity, add sixteenth snubber & change emergency preparedness audit frequencies.
BAYNE, J. P. Power Authority of the State of New York. 83/02/25.
VASSALLO, D. B. Operating Reactors Branch 2. 3pp. 17353:082. 24X
Fiche: 50-333, 83/02/25, 8303020008.

--8303020015 Application for amend to License DPR-59, revising App A Tech Specs to renumber mechanical snubbers for clarity, add sixteenth snubber, per IE Bulletin 81-01 & change emergency preparedness audit frequencies.
BAYNE, J. P. Power Authority of the State of New York. 83/02/25.
2pp. 17353:085. 24X Fiche: 50-333, 83/02/25, 8303020008.

--8303020021 Proposed Tech Spec rev renumbering mechanical snubbers on Table 3.6-1b for clarity, adding sixteenth snubber & changing emergency preparedness audit frequencies.
* Power Authority of the State of New York. 83/02/25. 9pp.
17353:087. 24X Fiche: 50-333, 83/02/25, 8303020008.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 5pp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303180362 Confirms that submittals of radiological effluent Tech Specs & offsite dose calculation manual scheduled for 830430 & 0530, respectively, per 830228 discussion.
BAYNE, J. P. Power Authority of the State of New York. 83/03/09.
VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 17621:073. 24X
Fiche: 50-333, 83/03/09, 8303180362.

8303180356 Requests exemption from implementation schedule of 10CFR50.49(g) re equipment qualification; extending response date to 830819. SER of util 810929 submittal not yet received. Refueling outage scheduled for 830520.
BAYNE, J. P. Power Authority of the State of New York. 83/03/11.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17620:095. 24X Fiche: 50-333, 83/03/11, 8303180356.

8303180365 Advises that addl info re NUREG-0737, Item II.F.1.4 concerning containment pressure water level & hydrogen monitors will be provided in near future, per NRC 830202 request.
BAYNE, J. P. Power Authority of the State of New York. 83/03/11.
VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 17621:066. 24X
Fiche: 50-333, 83/03/11, 8303180365.

8303290153 Forwards Amend 73 to License DPR-59 & notice of issuance & availability. Amend deletes App B ETS re nonradiological water quality-related requirements.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/11. SINCLAIR, L. W. Power Authority of the State of New York. 3pp. 17730:232. 24X
Fiche: 50-333, 83/03/11, 8303290153.

--8303290158 Amend 73 to License DPR-59, deleting App B ETS re nonradiological water quality-related requirements.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/11. 13pp.
17730:235. 24X Fiche: 50-333, 83/03/11, 8303290153.

--8303290164 Notice of issuance & availability of Amend 73 to License DPR-59.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/11. 2pp.
17730:248. 24X Fiche: 50-333, 83/03/11, 8303290153.

8303230523 Submits correction to 830106 safety evaluation supporting Amend 72 to License DPR-59. Word "lower" in seventh line of first paragraph of Section 3.1 should read "higher" to accurately reflect parameter evaluation.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/12. SINCLAIR, L. W. Power Authority of the State of New York. 2pp. 17677:240. 24X
Fiche: 50-333, 83/03/12, 8303230523.

8303180350 Confirms that proposed Tech Spec changes to incorporate NRC 820728 model Tech Spec on reactor protection sys electric power monitoring, including proposed under & overvoltage setpoints will be submitted by third wk of Apr 1983.
BAYNE, J. P. Power Authority of the State of New York. 83/03/14.
VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 17620:130. 24X
Fiche: 50-333, 83/03/14, 8303180350.

8303180375 Forwards revised encl to 830202 submittal re performance evaluations of reactor coolant & main steam line tunnel leakage detection sys (JPN-83-10). False statements corrected.
BAYNE, J. P. Power Authority of the State of New York. 83/03/14.
VASSALLO, D. B. Operating Reactors Branch 2. 5pp. 17621:076. 24X
Fiche: 50-333, 83/03/14, 8303180375.

8303280123 Forwards order confirming licensee commitment on post-TMI-related issues. Order based on util commitments in responses to Generic Ltrs 82-05 & 82-10.
VASSALLO, D. B. Operating Reactors Branch 2. 83/03/14. SINCLAIR, L. W. Power Authority of the State of New York. 3pp. 17713:323. 24X
Fiche: 50-333, 83/03/14, 8303280123.

--8303280129 Order confirming licensee commitments on post-TMI-related issues.
PURPLE, R. A. Division of Licensing. 83/03/14. Power Authority of the State of New York. 11pp. 17713:326. 24X
Fiche: 50-333, 83/03/14, 8303280123.

8303220153 Forwards Change 1 to Rev 3 of "Inservice Testing Program for Pumps & Valves."
BAYNE, J. P. Power Authority of the State of New York. 83/03/18.
VASSALLO, D. B. Operating Reactors Branch 2. 1p. 17657:170. 24X
Fiche: 50-333, 83/03/18, 8303220153.

--8303220154 Change 1 to Rev 3 of "Inservice Testing Program for Pumps & Valves."
* Power Authority of the State of New York. 83/03/18. 15pp.
17657:171. 24X Fiche: 50-333, 83/03/18, 8303220153.

## 9. Inspection Reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01: "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303160206 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Bunker-Ramo electrical penetration assemblies using hard epoxy module design, not installed in safety-related sys at facility.
BAYNE, J. P. Power Authority of the State of New York. 83/02/28.
HAYNES, R. C. Region 1, Office of Director. 2pp. 17596:295. 24X
Fiche: 50-333, 83/02/28, 8303160206.

8303160533 Forwards IE Insp Rept 50-333/83-01 during Jan 1983 & notice of violation.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/02.
MCNEILL, C. A. Power Authority of the State of New York. 2pp.
17587:237. 24X Fiche: 50-333, 83/03/02, 8303160533.

--8303160538 Notice of violation from insp during Jan 1983.
* Region 1, Office of Director. 83/03/02. 1p. 17587:239. 24X
Fiche: 50-333, 83/03/02, 8303160533.

--8303160546 IE Insp Rept 50-333/83-01 during Jan 1983. Noncompliance noted: failure to establish & implement drywell inerting procedures & overtime procedures.
LINVILLE, J. C., DOERFLEIN, L. T. Region 1, Office of Director. KISTER, H. B. Division of Project & Resident Programs. 83/02/15. 10pp. 17587:240. 24X Fiche: 50-333, 83/03/02, 8303160533.

8303100139 Ack receipt of 830217 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/82-28.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/03.
MCNEILL, C. A. Power Authority of the State of New York. 1p.
17485:258. 24X Fiche: 50-333, 83/03/03, 8303100139.

--8303100140 Responds to NRC 830119 ltr re violations noted in IE Insp Rept 50-333/82-28. Corrective actions: component disassembled, welding & QC insp performed & documented & work procedures revised.
MCNEILL, C. A. Power Authority of the State of New York. 83/02/17.
STAROSTECKI, R. Division of Project & Resident Programs. 3pp.
17485:259. 24X Fiche: 50-333, 83/03/03, 8303100139.

8303100240 Ack receipt of 830125 ltr re status of augmented offgas treatment sys repair, per util 821129 commitment in response to IE health physics appraisal rept.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/03.
MCNEILL, C. A. Power Authority of the State of New York. 1p.
17485:294. 24X Fiche: 50-333, 83/03/03, 8303100240.

--8303100246 Submits status of augmented offgas treatment sys testing & repair. Recombiner inservice continuously w/exception of plant shutdown. Engineering study of high outlet moisture from recombiner sys initiated. Next update by 830501.
MCNEILL, C. A. Power Authority of the State of New York. 83/01/25.
MARTIN, T. T. Division of Engineering & Technical Programs. 1p.
17485:295. 24X Fiche: 50-333, 83/03/03, 8303100240.

8303160501 Forwards IE Insp Rept 50-333/82-26 on 821213-17. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/03.
MCNEILL, C. A. Power Authority of the State of New York. 2pp.
17593:028. 24X Fiche: 50-333, 83/03/03, 8303160501.

--8303160508 IE Insp Rept 50-333/82-26 on 821213-17. No noncompliance noted. Major areas inspected: procedures, representative records, equipment & facilities, measurement & interviews w/personnel.
COLLINS, D. J. Region 1, Office of Director. SHANBAKY, M. M. Division of Engineering & Technical Programs. 83/03/01. 12pp.
17593:030. 24X Fiche: 50-333, 83/03/03, 8303160501.

8303240557 Forwards IE Safeguards Insp Rept 50-333/83-02 on 830124-27. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/09.
MCNEILL, C. A. Power Authority of the State of New York. 2pp.
17683:205. 24X Fiche: 50-333, 83/03/09, 8303240557.

--8303240568 IE Safeguards Insp Rept 50-333/83-02 on 830124-27. No noncompliance noted. Major areas inspected: physical barriers, security sys power supply, lighting, assessment aids, access control, detection aids & alarm stations.
MADDEN, W., SMITH, G., GODY, A. T. Region 1, Office of Director. 83/03/09. 4pp. 17683:207. 24X Fiche: 50-333, 83/03/09, 8303240557.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 12?pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303300305 Ack receipt of 830224 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/82-15.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/24
MCNEILL, C. A. Power Authority of the State of New York. 1p.
17734:286. 24X Fiche: 50-333, 83/03/24, 8303300305.

--8303300310 Responds to NRC 820917 ltr re violations noted in IE Insp Rept 50-333/82-15. Corrective actions all maint dept procedures now entered into computer program using TRS-80 computer.
MCNEILL, C. A. Power Authority of the State of New York. 83/02/24.
STAROSTECKI, R. Division of Project & Resident Programs. 1p.
17734:287. 24X Fiche: 50-333, 83/03/24, 8303300310.

R Periodic operating reports & related correspondence

8303040437 Forwards "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1982."
MCNEILL, C. A. Power Authority of the State of New York. 83/02/22.
HAYNES, R. C. Region 1, Office of Director. 1p. 17370:232. 24X
Fiche: 50-333, 83/02/22, 8303040437.

--8303040442 "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1982." * Power Authority of the State of New York. 83/02/22. 53pp.
17370:233. 24X Fiche: 50-333, 83/02/22, 8303040437.

8303140222 Forwards monthly operating rept for Feb 1983.
MCNEILL, C. A. Power Authority of the State of New York. 83/03/09.
Director's Office, Office of Inspection and Enforcement. 1p.
17534:260. 24X Fiche: 50-333, 83/03/09, 8303140222.

--8303140227 Monthly operating rept for Feb 1983.
COOK, J. Power Authority of the State of New York. 83/03/07. 6pp.
17534:261. 24X Fiche: 50-333, 83/03/09, 8303140222.

S Reportable occurrences, LERs & related correspondence

8303080472 Forwards LER 83-009/03L-0.
MCNEILL, C. A. Power Authority of the State of New York. 83/02/25.
HAYNES, R. C. Region 1, Office of Director. 1p. 17453:150. 24X
Fiche: 50-333, 83/02/25, 8303080472.

--8303080477 LER 83-009/03L-0 on 830202, during surveillance testing on emergency svc water pump B side, pump motor supply tripped open on high current flow. Caused by improper adjustments during maint. Trip devices adjusted properly.
PETERS, R. Power Authority of the State of New York. 83/02/25.
Region 1, Office of Director. 2pp. 17453:151. 24X
Fiche: 50-333, 83/02/25, 8303080477.

8303080501 Forwards LER 83-010/03L-0.
MCNEILL, C. A. Power Authority of the State of New York. 83/02/25.
HAYNES, R. C. Region 1, Office of Director. 1p. 17452:312. 24X
Fiche: 50-333, 83/02/25, 8303080501.

--8303080506 LER 83-010/03L-0 on 830214, during normal operation, RHR pump B removed from svc for 3 days to inspect & repair discharge check valve. Three missing hanger returning cap screws & one sheared cap screw identified. Mod initiated.
SCHLAU, P. Power Authority of the State of New York. 83/02/25.
Region 1, Office of Director. 2pp. 17452:313. 24X
Fiche: 50-333, 83/02/25, 8303080506.

8303090182 Forwards updated LER 82-024/03L-1.
MCNEILL, C. A. Power Authority of the State of New York. 83/02/25.
HAYNES, R. C. Region 1, Office of Director. 1p. 17471:235. 24X
Fiche: 50-333, 83/02/25, 8303090182.

--8303090195 Updated LER 82-024/03L-1 on 820520, during normal operation, RHR svc water pump A discharge check valve stuck open at completion of pump testing. Caused by missing cotter pin w/ disc nut backed off. Stainless steel cotter pin installed.
FERNANDEZ, W. Power Authority of the State of New York. 83/02/25.
Region 1, Office of Director. 2pp. 17471:236. 24X
Fiche: 50-333, 83/02/25, 8303090182.

8303140497 Forwards LER 82-024/03L-2.
MCNEILL, C. A. Power Authority of the State of New York. 83/03/03.
HAYNES, R. C. Region 1, Office of Director. 1p. 17540:319. 24X
Fiche: 50-333, 83/03/03, 8303140497.

--8303140507 LER 82-024/03L-2 on 820520, RHR svc water (RHRSW) pump A discharge check valve stuck open & declared inoperable. Cause not stated. List of insp results & corrective actions for RHRSW & emergency svc water pump discharge valves encl.
FERNANDEZ, W. Power Authority of the State of New York. 83/03/03.
Region 1, Office of Director. 2pp. 17540:320. 24X
Fiche: 50-333, 83/03/03, 8303140497.

8303250032 Forwards LER 83-011/01T-0.
MCNEILL, C. A. Power Authority of the State of New York. 83/03/15.
HAYNES, R. C. Region 1, Office of Director. 1p. 17693:269. 24X
Fiche: 50-333, 83/03/15, 8303250032.

--8303250035 LER 83-011/01T-0 on 830304, abnormally high tailpiece temp indicated in safety relief valves D & F in Target Rock mode/valves. Caused by valve leakage. Topworks will be replaced during 1983 refueling outage.
LISENO, R. Power Authority of the State of New York. 83/03/15.
Region 1, Office of Director. 1p. 17693:270. 24X
Fiche: 50-333, 83/03/15, 8303250032.

8303250059 Forwards LER 83-012/04T-0.
MCNEILL, C. A. Power Authority of the State of New York. 83/03/15.
HAYNES, R. C. Region 1, Office of Director. 1p. 17693:123. 24X
Fiche: 50-333, 83/03/15, 8303250059.

--8303250065 LER 83-012/04T-0 on 830302, tritium concentration in inlet sample found 39.2 times control sample results. Caused by downstream sampling points of waste discharge rather than normal upstream locations. Sample not representative.
GORMAN, B. Power Authority of the State of New York. 83/03/15.
Region 1, Office of Director. 2pp. 17693:124. 24X
Fiche: 50-333, 83/03/15, 8303250059.

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303080493 Forwards tentative schedule for operator licensing exam site visits through Dec 1985, in response to Generic Ltr 83-01.
BAYNE, J. P. Power Authority of the State of New York. 83/03/01.
EISENHUT, D. G. Division of Licensing. 2pp. 17452:307. 24X
Fiche: 50-333, 83/03/01, 8303080493.

DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8303110212 Forwards "Beaver Valley Power Station Annual Emergency Preparedness Exercise."
CAREY, J. J. Duquesne Light Co. 82/12/27. VARGA, S. A. Operating Reactors Branch 1. 2pp. 17513:001. 24X Fiche: 50-334, 82/12/27, 8303110212.

--8303110220 "Beaver Valley Power Station Annual Emergency Preparedness Exercise." * Duquesne Light Co. 82/12/27. 259pp. 17513:003. 24X
Fiche: 50-334, 82/12/27, 8303110212.

8303080523 Forwards revised pages to 830105 SER re fire protection. Rev corrects errors inadvertently introduced during transfer of technical info.
TAM, P. S. Operating Reactors Branch 1. 83/03/01. CAREY, J. J. Duquesne Light Co. 4pp. 17464:346. 24X Fiche: 50-334, 83/03/01, 8303080523.

8303110382 Forwards info re emergency operating facility (EOF), in response to 830304 telecopy request. Permanent primary EOF bldg complete.
CAREY, J. J. Duquesne Light Co. 83/03/04 VARGA, S. A. Operating Reactors Branch 1. 2pp. 17512:331. 24X Fiche: 50-334, 83/03/04, 8303110383.

8303180028 Requests confirmation on info tabulated from response re emergency operating facilities.
VARGA, S. A. Operating Reactors Branch 1. 83/03/04 CAREY, J. J. Duquesne Light Co. 3pp. 17625:269. 24X Fiche: 50-334, 83/03/04, 8303180028.

8303240438 Forwards IE Insp Rept 50-334/83-03 on 830215-18. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/08
CAREY, J. J. Duquesne Light Co. 2pp. 17678:347. 24X
Fiche: 50-334, 83/03/08, 8303240438.

--8303240442 IE Insp Rept 50-334/83-03 on 830215-18. No noncompliance noted. Major areas inspected: emergency preparedness insp & observation of licensee annual emergency exercise performed on 830216.
SMITH, R. H. Region 1, Office of Director. CROCKER, H. W. Division of Engineering & Technical Programs. 83/03/07. 6pp. 17678:349. 24X Fiche: 50-334, 83/03/08, 8303240438.

8303290256 Forwards exemption from requirements of App R to 10CFR50 re fire protection, per 820630, 1022, 28 & 1221 requests.
VARGA, S. A. Operating Reactors Branch 1. 83/03/14. CAREY, J. J. Duquesne Light Co. 4pp. 17728:343. 24X Fiche: 50-334, 83/03/14, 8303290256.

--8303290263 Exemption from requirements of App R to 10CFR50 re fire protection.
EISENHUT, D. G. Division of Licensing. 83/03/14 Duquesne Light Co. 16pp. 17728:347. 24X Fiche: 50-334, 83/03/14, 8303290256.

--8303290270 Notice of exemption from App R to 10CFR50 re fire protection requirements.
PURPLE, R. A. Division of Licensing. 83/03/14. 5pp. 17729:001. 24X Fiche: 50-334, 83/03/14, 8303290256.

8303310492 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/29 Document Management Branch. 1p. 17778:001. 24X Fiche: 50-334, 83/03/29, 8303310492.

--8303310497 Forwards public version of Rev 1 to Issue 7 of emergency plan implementing procedures, including Procedures EPP/I-1 re recognition & classification of emergencies & EPP/I-5 re general emergency.
SIEBER, J. D. Duquesne Light Co. 83/02/14. VARGA, S. A. Operating Reactors Branch 1. 1p. 17778:002. 24X Fiche: 50-334, 83/03/29, 8303310492.

--8303310502 Forwards public version of Rev 1 to Issue 7 of emergency plan implementing procedures, including Procedures EPP/I-1 re recognition & classification of emergencies & EPP/I-5 re general emergency.
WIRTH, W. F. Duquesne Light Co. 83/02/02 NRC - No Detailed Affiliation Given. 3pp. 17778:003. 24X Fiche: 50-334, 83/03/29, 8303310492.

--8303310515 Public version of Rev 1 to Issue 7 of emergency plan implementing procedures, including Procedures EPP/I-1 re recognition & classification of emergencies & EPP/I-5 re general emergency.
LACEY, W. S. Duquesne Light Co. 83/02/03. 954pp. 17778:006. 24X Fiche: 50-334, 83/03/29, 8303310492.

P. Operating license stage documents & correspondence

8303110006 Addl response to FOIA request for 22 categories of documents. Forwards documents listed in App A. Addl documents undergoing review for safeguards info.
FELTON, J. M. Division of Rules and Records. 83/01/31. SHOLLY, S. C. Union of Concerned Scientists. 4pp. 17547:028. 24X
Fiche: 50-000, 83/01/31, 8303110006.

--8303110048 Delegates authority to administer oaths or affirmations re statements concerning security access, maint & surveillance programs associated w/misposition of suction valve for high head safety injection pump.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 81/06/09. SHEPHERD, R. E. Region 1, Philadelphia, Office of the Director. 1p. 17547:177. 24X Fiche: 50-000, 83/01/31, 8303110006.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303040564 Forwards proprietary revised pages of Westinghouse supporting documentation for Tech Spec App B Change Request 75, initially submitted by 830104 repts. "Incore Detector Thimble Reduction Study." Pages withheld.
CAREY, J. J. Duquesne Light Co. 83/02/24. VARGA, S. A. Operating Reactors Branch 1. 2pp. 17367:207. 24X Fiche: 50-334, 83/02/24, 8303040564.

8303040313 Forwards info re blocking of steam line high differential pressure safety injection signal during cooldown in certain BWRs. Response requested within 30 days.
VARGA, S. A. Operating Reactors Branch 1. 83/02/28. CAREY, J. J. Duquesne Light Co. 4pp. 17426:272. 24X Fiche: 50-334, 83/02/28, 8303040313.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303080291 Forwards addl info on two-loop operation, in response to NRC 830107 ltr. Status update will be submitted in Jul 1983 in response to question on pressurized thermal shock. W/four oversize drawings. Aperture cards available in PDR.
CAREY, J. J. Duquesne Light Co. 83/03/04. VARGA, S. A. Operating Reactors Branch 1. 12pp. 17454:298. 24X Fiche: 50-334, 83/03/04, 8303080291.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303150099 Informs that eight of 11 criteria in NUREG-0737, TMI Item II.B.3 satisfied. Addl info re post-accident sampling sys requested within 30 days of receipt of ltr. SER encl.
VARGA, S. A. Operating Reactors Branch 1. 83/03/07. CAREY, J. J. Duquesne Light Co. 10pp. 17586:262. 24X Fiche: 50-334, 83/03/07, 8303150099.

8303300005 Forwards Amend 64 to License DPR-66 & notice of issuance & availability. Amend deletes App B, ETS re nonradiological water quality-related requirements.
VARGA, S. A. Operating Reactors Branch 1. 83/03/11. CAREY, J. J. Duquesne Light Co. 4pp. 17751:269. 24X Fiche: 50-334, 83/03/11, 8303300005.

--8303300012 Amend 64 to License DPR-66 deleting App B, ETS re nonradiological water quality-related requirements.
VARGA, S. A. Operating Reactors Branch 1. 83/03/11. 11pp. 17751:273. 24X Fiche: 50-334, 83/03/11, 8303300005.

--8303300019 Notice of issuance & availability of Amend 64 to License DPR-66.
VARGA, S. A. Operating Reactors Branch 1. 83/03/11. 2pp. 17751:284. 24X Fiche: 50-334, 83/03/11, 8303300005.

8303240094 Responds to 830228 ltr re blocking of steamline high differential pressure safety injection signal during cooldown. STS should be amended to reflect plant-specific operating bypasses detailed in encl FSAR logic diagrams.
CAREY, J. J. Duquesne Light Co. 83/03/16. VARGA, S. A. Operating Reactors Branch 1. 33pp. 17681:040. 24X Fiche: 50-334, 83/03/16, 8303240094.

8303290008 Responds to Generic Ltr 83-13 re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Specs requiring rev identified. Wording will be modified.
CAREY, J. J. Duquesne Light Co. 83/03/21. VARGA, S. A. Operating Reactors Branch 1. 1p. 17722:248. 24X Fiche: 50-334, 83/03/21, 8303290008.

8303290473 Forwards response to 821210 Generic Ltr 82-28, "Inadequate Core Cooling Instrumentation Sys," consisting of upgraded subcooling margin monitors, core-exit thermocouples & reactor coolant inventory tracking sys info.
CAREY, J. J. Duquesne Light Co. 83/03/25. EISENHUT, D. G. Division of Licensing. 9pp. 17722:340. 24X Fiche: 50-334, 83/03/25, 8303290473.

8303310246 Forwards "Environ Qualification Documentation Rept." 90-day response required by NRC SER for environ qualification of safety-related electrical equipment.
CAREY, J. J. Duquesne Light Co. 83/03/25 VARGA, S. A. Operating Reactors Branch 1. 2pp. 17755:141. 24X Fiche: 50-334, 83/03/25, 8303310246.

--8303310248 "Environ Qualification Documentation Rept." for NRC SER 90-day response 1983.
* Duquesne Light Co. 83/03/25 182pp. 17755:143. 24X Fiche: 50-334, 83/03/25, 8303310246.

G. Inspection reports, IE Bulletins & correspondence

8303030182 Forwards IE Insp Rept 50-334/83-02 on 821124 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/02/18.
CAREY, J. J. Duquesne Light Co. 2pp. 17410:189. 24X
Fiche: 50-334, 83/02/18, 8303030182.

--8303030188 Notice of violation from insp on 821124.
* Division of Engineering & Technical Programs. 83/02/18 1p. 17410:191. 24X Fiche: 50-334, 83/02/18, 8303030182.

--8303030202 IE Insp Rept 50-334/83-02 on 821124 Noncompliance noted: waste shipment of byproduct matl containing 1.414 Ci solidified resin & compacted trash transferred to Chem-Nuclear Sys, Inc w/detectable free standing liquid.
CLEMONS, P., SHANBAKY, M. Region 1, Office of Director. 83/02/16. 4pp. 17410:192. 24X Fiche: 50-334, 83/02/18, 8303030182.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303100196 Forwards responses to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Operation & maint of breakers satisfactory & no further action necessary.
CAREY, J. J. Duquesne Light Co. 83/03/03. HAYNES, R. C. Region 1, Office of Director. 4pp. 17489:175. 24X Fiche: 50-334, 83/03/03, 8303100196.

8303240438 Forwards IE Insp Rept 50-334/83-03 on 830215-18. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/08.
CAREY, J. J. Duquesne Light Co. 2pp. 17678:347. 24X
Fiche: 50-334, 83/03/08, 8303240438.

--8303240442 IE Insp Rept 50-334/83-03 on 830215-18. No noncompliance noted. Major areas inspected: emergency preparedness insp & observation of licensee annual emergency exercise performed on 830216.
SMITH, R. H. Region 1, Office of Director. CROCKER, H. W. Division of Engineering & Technical Programs. 83/03/07. 6pp. 17678:349. 24X Fiche: 50-334, 83/03/08, 8303240438.

8303240532 Forwards IE Insp Rept 50-334/83-04 on 830201-28. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/09.
CAREY, J. J. Duquesne Light Co. 2pp. 17682:291. 24X
Fiche: 50-334, 83/03/09, 8303240532.

--8303240542 IE Insp Rept 50-334/83-04 on 830201-28. No noncompliance noted. Major areas inspected: plant operations, fire protection, radiological controls, physical security, maint activities, IE bulletins & previous insp findings followup.
TROSKOSKI, W. M., TRIPP, L. E. Region 1, Office of Director. 83/03/09. 15pp. 17682:293. 24X Fiche: 50-334, 83/03/09, 8303240532.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303290314 Forwards IE Insp Rept 50-334/83-05 on 830221-24. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/15.
CAREY, J. J. Duquesne Light Co. 2pp. 17716:222. 24X
Fiche: 50-334, 83/03/15, 8303290314.

--8303290319 IE Insp Rept 50-334/83-05 on 830221-24. No noncompliance noted. Major areas inspected: in-plant radiological controls, high radiation area access controls, sealed source & leak testing, dosimetry records & radiological instrument calibr.
COLLINS, D. J., SHANBAKY, M. M. Region 1, Office of Director. 83/03/10. 6pp. 17716:224. 24X Fiche: 50-334, 83/03/15, 8303290314.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

R. Periodic operating reports & related correspondence

8303080246 Forwards monthly operating rept for Dec 1982.
CAREY, J. J. Duquesne Light Co. 83/01/11. Office of Resource Management, Director. 1p. 17450:296. 24X Fiche: 50-334, 83/01/11, 8303080246.

--8303080251 Monthly operating rept for Dec 1982.
HOLTZ, J. L. Duquesne Light Co. 83/01/11. 5pp. 17450:297. 24X
Fiche: 50-334, 83/01/11, 8303080246.

8303150572 Forwards monthly operating rept for Jan 1983.
CAREY, J. J. Duquesne Light Co. 83/02/09. Office of Resource Management, Director. 1p. 17568:019. 24X Fiche: 50-334, 83/02/09, 8303150572.

--8303150581 Monthly operating rept for Jan 1983.
HOLTZ, J. L. Duquesne Light Co. 83/02/04. 7pp. 17568:020. 24X
Fiche: 50-334, 83/02/09, 8303150572.

8303080381 Forwards Effluent & Waste Disposal Semiannual Rept for Second Half 1982." per Reg Guide 1.21, Rev 1.
CAREY, J. J. Duquesne Light Co. 83/02/23. Region 1, Office of Director. 1p. 1745* :0. 24X Fiche: 50-334, 83/02/23, 8303080381.

--8303080387 "Effluent & Waste Disposal Semiannual Rept for Second Half 1982."
* Duquesne Light Co. 83/02/23. 59pp. 17454:171. 24X
Fiche: 50-334, 83/02/23, 8303080381.

8303150335 Forwards monthly operating rept for Feb 1983.
CAREY, J. J. Duquesne Light Co. 83/03/03. Division of Data Automation & Management Information. 1p. 17563:017. 24X
Fiche: 50-334, 83/03/03, 8303150335.

--8303150337 Monthly operating rept for Feb 1983.
HOLTZ, J. L. Duquesne Light Co. 83/03/03. 8pp. 17563:018. 24X
Fiche: 50-334, 83/03/03, 8303150335.

S. Reportable occurrences, LERs & related correspondence

8303110006 Addl response to FOIA request for 22 categories of documents. Forwards documents listed in App A. Addl documents undergoing review for safeguards info.
FELTON, J. M. Division of Rules and Records. 83/01/31. SHOLLY, S. C. Union of Concerned Scientists. 4pp. 17547:028. 24X
Fiche: 50-000, 83/01/31, 8303110006.

--8303110061 Forwards B10602 rept re feedwater pump trip compiled by F Witkowsky & J Daugherty. Handwritten notes on various subjs encl.
LACEY, W. S. Duquesne Light Co. 81/06/09. WERLING, J. A. Duquesne Light Co. 31pp. 17547:178. 24X Fiche: 50-000, 83/01/31, 8303110006.

--8303110068 Recommends that investigative efforts be directed towards establishing that event was deliberate act. Special insp should address issues of efficacy of safeguards program &/or compliance w/NRC requirements. Related info encl.
WARD, W. J. Investigations Branch (Pre 820201). 81/06/15. SMITH, R. Region 1, Philadelphia, Office of the Director. 7pp. 17547:209. 24X Fiche: 50-000, 83/01/31, 8303110006.

8302250194 Forwards LER 83-004/03L-0.
LACEY, W. S. Duquesne Light Co. 83/02/10. HAYNES, R. C. Region 1, Office of Director. 2pp. 17293:001. 24X Fiche: 50-334, 83/02/10, 8302250194.

--8302250202 LER 83-004/03L-0 on 830114, circuit breaker OCB 83 tripped resulting in loss of standby sys station svc transformer 1B. Caused by over excitation relay due to setpoint drift & increase in transformer 1B secondary side voltage.
* Duquesne Light Co. 83/02/10 Region 1, Office of Director 2pp. 17293:003. 24X Fiche: 50-334, 83/02/10, 8302250194.

8303040375 Forwards LER 83-007/04T-0.
LACEY, W. S. Duquesne Light Co. 83/02/18. HAYNES, R. C. Region 1, Office of Director. 2pp. 17420:007. 24X Fiche: 50-334, 83/02/18, 8303040375.

--8303040382 LER 83-007/04T-0 on 830214, tritium activity in Fourth Quarter 1982 composite of weekly grab samples collected in OH River downstream of effluent found to be above ETS limits. Amend to ETS submitted to increase acceptable limit.
* Duquesne Light Co. 83/02/18 Region 1, Office of Director
2pp. 17420:009. 24X Fiche: 50-334, 83/02/18, 8303040375.

8303070041 Forwards LER 83-003/03L-0.
LACEY, W. S. Duquesne Light Co. 83/02/24. HAYNES, R. C. Region 1, Office of Director. 2pp. 17434:205. 24X Fiche: 50-334, 83/02/24, 8303070041.

--8303070046 LER 83-003/03L-0 on 830110, low voltage condition logged on battery bus 1 Caused by open circuit in charge collector resistor preventing charger control in voltage circuit from properly regulating charger output voltage.
DRUGA, R. J. Duquesne Light Co. 83/02/24 Region 1, Office of Director. 2pp. 17434:207. 24X Fiche: 50-334, 83/02/24, 8303070041.

8303070148 Forwards LER 83-002/03L-0.
LACEY, W. S. Duquesne Light Co. 83/02/24. HAYNES, R. C. Region 1, Office of Director. 2pp. 17430:349. 24X Fiche: 50-334, 83/02/24, 8303070148.

--8303070159 LER 83-002/03L-0 on 830107, w/reactor power at 99%, 138 kv bus 1 lost, violating Tech Spec 3.8.1.1, causing reactor to trip on 2/3 RCP bus 4 kV undervoltages. Caused by inadvertent operation of bus back-up timer relay 62-241.
* Duquesne Light Co. 83/02/24 Region 1, Office of Director.
2pp. 17430:351. 24X Fiche: 50-334, 83/02/24, 8303070148.

8303140502 Forwards LER 83-005/99X-0.
LACEY, W. S. Duquesne Light Co. 83/02/28. HAYNES, R. C. Region 1, Office of Director. 2pp. 17540:270. 24X Fiche: 50-334, 83/02/28, 8303140502.

--8303140512 LER 83-005/99X-0 on 830212, main steam trip valve TV-MS-101B shut on loss of air causing momentary drop in steam line pressure initiating safety injection/reactor trip. Caused by separated sweated fitting. Fitting repaired.
* Duquesne Light Co. 83/02/28 Region 1, Office of Director.
2pp. 17540:272. 24X Fiche: 50-334, 83/02/28, 8303140502.

8303240580 Forwards LER 83-006/03L-0.
LACEY, W. S. Duquesne Light Co. 83/03/07. HAYNES, R. C. Region 1, Office of Director. 2pp. 17683:158. 24X Fiche: 50-334, 83/03/07, 8303240580.

--8303240588 LER 83-006/03L-0 on 830212, trip valve (TV-MS-101B) failed to close during stroke test. Caused by combination of debris that caused slight cylinder scoring & loose pivot arm. Piston dressed up & cylinder wall honed.
* Duquesne Light Co. 83/03/07 Region 1, Office of Director.
2pp. 17683:160. 24X Fiche: 50-334, 83/03/07, 8303240580.

V. Operator Examinations

8303080447 Forwards info for projected schedule through 1985 for prospective operator licensing exams per Generic Ltr 83-01.
CAREY, J. J. Duquesne Light Co. 83/02/23. EISENHUT, D. G. Division of Licensing. 3pp. 17455:193. 24X Fiche: 50-334, 83/02/23, 8303080447.

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-335 ST. LUCIE PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8303010660 Forwards RC Lewis 821112 ltr transmitting SALP Repts 50-250/82-33, 50-251/82-33 & 50-335/82-37 for May 1980 - June 1982 & 50-389/82-56 for Sept 1980 - June 1982. Overall performance satisfactory.
O'REILLY, J. P. Region 2, Office of Director. 83/01/18 UHRIG, R. E. Florida Power & Light Co. 2pp. 17341:106. 24X
Fiche: 50-000, 83/01/18, 8303010660.

--8303010678 SALP Repts 50-250/82-33, 50-251/82-33 & 50-335/82-37 for May 1980 - June 1982 & 50-389/82-56 for Sept 1980 - June 1982 Overall performance satisfactory.
* Region 2, Office of Director. 82/11/12. 50pp. 17341:110. 24X
Fiche: 50-000, 83/01/18, 8303010660.

8303010640 Forwards IE Insp Rept 50-335/82-43 on 821122-24. No noncompliance noted. Continued mgt attention should be directed toward state of operational readiness of technical support ctr.
O'REILLY, J. P. Region 2, Office of Director. 83/02/07. UHRIG, R. E. Florida Power & Light Co. 2pp. 17336:114. 24X
Fiche: 50-335, 83/02/07, 8303010640.

--8303010648 IE Insp Rept 50-335/82-43 on 821122-24. No noncompliance noted. Major areas inspected: emergency preparedness. Deficiency noted in technical support ctr staff augmentation.
HUFFMAN, G. N. Region 2, Office of Director. JENKINS, G. R. Division of Emergency Preparedness & Materials Safety. 83/02/02. 4pp.
17336:116. 24X Fiche: 50-335, 83/02/07, 8303010640.

8303010570 Forwards IE Insp Repts 50-335/83-04 & 50-389/83-12 on 830119-20. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/02/10. UHRIG, R. E. Florida Power & Light Co. 2pp. 17336:233. 24X
Fiche: 50-335, 83/02/10, 8303010570.

--8303010585 IE Insp Repts 50-335/83-04 & 50-389/83-12 on 830119-20. No noncompliance noted. Major areas inspected: radiological emergency exercise.
HUFFMAN, G. N. Region 2, Office of Director. JENKINS, G. R. Division of Emergency Preparedness & Materials Safety. 83/02/07. 11pp.
17336:235. 24X Fiche: 50-335, 83/02/10, 8303010570.

8303030554 Responds to 830106, 14 & 0218 ltrs by confirming agreements of 830223 meeting that util will suppl fire protection proposals to reflect recent work showing addl compliance w/App R requirements. Suppls to be submitted by 830408.
UHRIG, R. E. Florida Power & Light Co. 83/03/01. EISENHUT, D. G. Division of Licensing. 1p. 17412:362. 24X Fiche: 50-000, 83/03/01, 8303030554.

8303210697 Ack receipt of 830217 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-389/82-75.
DANCE, H. C. Division of Project & Resident Programs. 83/03/01.
UHRIG, R. E. Florida Power & Light Co. 1p. 17635:072. 24X
Fiche: 50-389, 83/03/01, 8303210697.

--8303210721 IE Insp Repts 50-389/82-75 & 50-335/82-46 on 821213-17. Deviation noted: improper storage of safety-related HEPA filters.
WRAY, J. R. Region 2, Office of Director. 83/01/06. 8pp.
17635:078. 24X Fiche: 50-389, 83/03/01, 8303210697.

8303160513 Forwards status update of offsite plans & emergency preparedness in area of public educ & info.
KRIMM, R. W. Federal Emergency Management Agency. 83/03/04.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 4pp. 17592:327. 24X Fiche: 50-335, 83/03/04, 8303160513.

8303160257 Advises of withdrawal of request for exemption from certain requirements of 10CFR73.21, per 811222 ltr. Facilities in compliance w/applicable sections.
UHRIG, R. E. Florida Power & Light Co. 83/03/10. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17596:340. 24X
Fiche: 50-000, 83/03/10, 8303160257.

8303240126 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/21. Document Management Branch. 1p. 17699:213. 24X Fiche: 50-335, 83/03/21, 8303240126.

--8303240130 Forwards public version of revised emergency plan implementing procedures, including Procedures 2-0030141 re control room inaccessibility & 2-0120035 re pressurizer pressure level.
WETHY, C. M. Florida Power & Light Co. 83/03/10. Director's Office, Office of Inspection and Enforcement. 1p. 17699:214. 24X
Fiche: 50-335, 83/03/21, 8303240126.

--8303240133 Public version of revised emergency plan implementing procedures, including Procedures 2-0030141 re control room inaccessibility & 2-0120035 re pressurizer pressure level.
* Florida Power & Light Co. 83/03/03. 86pp. 17699:215. 24X
Fiche: 50-335, 83/03/21, 8303240126.

8303290349 Discusses request for exemptions from certain requirements of 10CFR73.21 Sections (d)(2) & (e) re marking & storage of safeguards matl. Request to withdraw exemption request acceptable, per util 830310 ltr.
VARGA, S. A. Operating Reactors Branch 1. 83/03/21. UHRIG, R. E. Florida Power & Light Co. 2pp. 17713:101. 24X
Fiche: 50-000, 83/03/21, 8303290349.

8303300143 Forwards marked-up Table 3-1 of radiological emergency plan. Changes respond to comments during 830322 telcon & will be incorporated into Rev 13 by 840101.
UHRIG, R. E. Florida Power & Light Co. 83/03/28 EISENHUT, D. G. Division of Licensing. 10pp. 17731:210. 24X Fiche: 50-335, 83/03/28, 8303300143.

8303310467 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/29. Document Management Branch. 1p. 17795:349. 24X Fiche: 50-335, 83/03/29, 8303310467.

--8303310471 Forwards public version of revised emergency plan implementing procedures, including Procedures 1-0210030 re charging & letdown, 2-0120036 re pressurizer relief/safety valve & 2-1300031 re airlocks.
WETHY, C. M. Florida Power & Light Co. 83/02/23. Director's Office, Office of Inspection and Enforcement. 1p. 17795:350. 24X Fiche: 50-335, 83/03/29, 8303310467.

--8303310474 Public version of revised emergency plan implementing procedures, including Procedures 1-0210030 re charging & letdown, 2-0120036 re pressurizer relief/safety valve & 2-1300031 re airlocks.
* Florida Power & Light Co. 83/02/18. 36pp. 17795:351. 24X Fiche: 50-335, 83/03/29, 8303310467.

H. General correspondence

8303040338 Advises of current mailing address, effective Jul 1982.
UHRIG, R. E. Florida Power & Light Co. 83/02/25. EISENHUT, D. G. Division of Licensing. 1p. 17420:072. 24X Fiche: 50-000, 83/02/25, 8303040338.

J. Insurance & indemnity information

8303290310 Forwards Endorsement 46 to NELIA Policy NF-227.
DUCK, J. R. Marsh & McLennan, Inc. 83/03/15. SALTZMAN, J. Office of State Programs, Director. 2pp. 17716:204. 24X
Fiche: 50-335, 83/03/15, 8303290310.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303020211 Requests, within 15 days, assessment of operability of Henry Pratt RIA butterfly valves used for purging & venting of containment & commitment that subj valves will be sealed closed per SRP Section 6.2.4, II.6.f.
CLARK, R. A. Operating Reactors Branch 3. 83/02/16. UHRIG, R. E. Florida Power & Light Co. 6pp. 17358:006. 24X
Fiche: 50-335, 83/02/16, 8303020211.

8303030703 Notification of 830307 meeting w/utils & NUS Corp in Bethesda, MD to discuss proposed rev to 10CFR40 36 (Tech Specs).
BRINKMAN, D. S. Standardization & Special Projects Branch. 83/02/22. THOMAS, C. O. Standardization & Special Projects Branch. 2pp. 17363:227. 24X Fiche: 50-000, 83/02/22, 8303030703.

8303140090 Forwards corrected Tech Spec Pp 3/4 4-1d & 3/4 4-1e contained in 821221 Amend 56 to License DPR-67, amending DHR capability.
SELLS, D. E. Operating Reactors Branch 3. 83/02/23. UHRIG, R. E. Florida Power & Light Co. 2pp. 17548:305. 24X
Fiche: 50-335, 83/02/23, 8303140090.

--8303140093 Corrected Tech Spec Pp 3/4 4-1d & 3/4 4-1e, amending DHR capability.
* Florida Power & Light Co. 83/02/23. 2pp. 17548:307. 24X
Fiche: 50-335, 83/02/23, 8303140090.

8303160011 Comments on analysis re capacity of special lifting rig for handling reactor & pressurizer missile shield, per util 830103 ltr re control of heavy loads. Sketch SK-128-9.3000 reflects poor rigging practice.
CLARK, R. A. Operating Reactors Branch 3. 83/02/25. UHRIG, R. E. Florida Power & Light Co. 5pp. 17615:071. 24X
Fiche: 50-335, 83/02/25, 8303160011.

8303150029 Notification of 830314-18 meetings w/util in Juno Beach & Miami, FL to discuss licensing actions w/util mgt & conduct site visit during Cycle 6 refueling outage.
SELLS, D. E. Operating Reactors Branch 3. 83/02/28. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17597:165. 24X
Fiche: 50-335, 83/02/28, 8303150029.

8303030499 Forwards info re natural circulation cooldown in response to 830103 ltr.
UHRIG, R. E. Florida Power & Light Co. 83/03/01. CLARK, R. A. Operating Reactors Branch 3. 5pp. 17409:335. 24X
Fiche: 50-335, 83/03/01, 8303030499.

8303140609 Forwards request for addl info re overpressure mitigation sys & Cycle 6 reload. Response requested within 30 days of receipt of ltr.
CLARK, R. A. Operating Reactors Branch 3. 83/03/01. UHRIG, R. E. Florida Power & Light Co. 4pp. 17548:343. 24X
Fiche: 50-335, 83/03/01, 8303140609.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 5ipp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303140057 Informs of intent to submit assessment of operability of large Pratt purge & vent valves by 830331, per NRC 830216 request.
UHRIG, R. E. Florida Power & Light Co. 83/03/07. CLARK, R. A. Operating Reactors Branch 3. 1p. 17540:131. 24X
Fiche: 50-335, 83/03/07, 8303140057.

8303160171 Application for amend to License DPR-67 changing Tech Specs to modify surveillance requirements & bases associated w/chlorine detection sys.
UHRIG, R. E. Florida Power & Light Co. 83/03/09. EISENHUT, D. G. Division of Licensing. 2pp. 17597:025. 24X Fiche: 50-335, 83/03/09, 8303160171.

--8303160177 Proposed Tech Specs modifying surveillance requirements & bases associated w/chlorine detection sys.
* Florida Power & Light Co. 83/03/09. 6pp. 17597:027. 24X
Fiche: 50-335, 83/03/09, 8303160171.

8303160360 Forwards responses to Generic Ltr 82-28 re inadequate core cooling sys for facility. W/five oversize drawings. Aperture cards are available in PDR.
UHRIG, R. E. Florida Power & Light Co. 83/03/10. EISENHUT, D. G. Division of Licensing. 17pp. 17592:040. 24X Fiche: 50-335, 83/03/10, 8303160360.

--8303160373 Rev 0 to "Functional Design Description for Qualified Safety Parameter Display Sys for St Lucie Unit 1."
STARKWEATHER, G., CASTAGNO, J. G., ROHDE, K. R. Combustion Engineering, Inc. 11181-ICE-3218 R00. 82/09/01. 9pp. 17592:086. 24X
Fiche: 50-335, 83/03/10, 8303160360.

--8303160379 Rev 0 to "Data Base Description for Qualified Safety Parameter Display Sys for St Lucie Unit 1."
STARKWEATHER, G., CASTAGNO, J. G., ROHDE, K. R. Combustion Engineering, Inc. 11181-ICE-3219 R00. 82/12/07. 2opp. 17592:095. 24X
Fiche: 50-335, 83/03/10, 8303160360.

--8303160386 Rev 0 to "Functional Design Spec for Qualified Safety Parameter Display Sys Displays for St Lucie Unit 1."
STARKWEATHER, G., HENRICH, G. E., ROHDE, K. R. Combustion Engineering, Inc. 11181-ICE-3220 R00. 83/01/07. 22pp. 17592:121. 24X
Fiche: 50-335, 83/03/10, 8303160360.

--8303160394 Rev 0 to "Interface Design Requirements for Qualified Safety Parameter Display/Safety Assessment Sys Data Communications for St Lucie Unit 1."
HOYT, H. F., HENRY, R. A., FOSTER, R. G. Combustion Engineering, Inc. 11181-ICE-3111 R00. 82/09/30. 32pp. 17592:143. 24X
Fiche: 50-335, 83/03/10, 8303160360.

8303150434 Forwards proprietary C-E 810821 responses to BNWL questions re statistical combination of uncertainties that form basis of methodology used in support of facility reloads. C-E responses withheld (ref 10CFR2.790). Affidavit encl.
UHRIG, R. E. Florida Power & Light Co. 83/03/11. CLARK, R. A. Operating Reactors Branch 3. 6pp. 17562:285. 24X
Fiche: 50-335, 83/03/11, 8303150434.

8303160200 Forwards addl info re 821210 degraded grid voltage protection submittals, per 820223 telcon. Voltage/time setpoints will be supported by two undervoltage devices.
UHRIG, R. E. Florida Power & Light Co. 83/03/11. CLARK, R. A. Operating Reactors Branch 3. 3pp. 17596:292. 24X
Fiche: 50-335, 83/03/11, 8303160200.

8303170304 Responds to 821210 request for info on use of Raychem flamtrol cables. Only cable affected is conductor 2AWG (1-3/C 2) 480-volt power cable, utilized in six safety-related applications. Cables to be replaced.
UHRIG, R. E. Florida Power & Light Co. 83/03/11. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 2pp. 17605:131. 24X Fiche: 50-335, 83/03/11, 8303170304.

8303230061 Forwards order confirming commitments to implement post-TMI items scheduled for completion on or after 820701 based on responses to Generic Ltrs 82-05 & 82-10.
CLARK, R. A. Operating Reactors Branch 3. 83/03/14. UHRIG, R. E. Florida Power & Light Co. 3pp. 17688:329. 24X
Fiche: 50-335, 83/03/14, 8303230061.

--8303230066 Order confirming licensee commitments to implement & maintain post-TMI related issues.
PURPLE, R. A. Division of Licensing. 83/03/14. Florida Power & Light Co. 6pp. 17688:332. 24X Fiche: 50-335, 83/03/14, 8303230061.

8303250020 Describes preliminary safety concern re unanalyzed reactor vessel thermal stress during cooldown. Investigation can be furthered by obtaining actual reactor vessel & head flange metal temps during natural circulation cooldown.
TAYLOR, J. H. Babcock & Wilcox Co. 83/03/18. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 3pp. 17693:265. 24X Fiche: 50-335, 83/03/18, 8303250020.

8303240501 Forwards proprietary Rev 0 to "Justification of XNB DNB Correlation for St Lucie Unit 1." Rept withheld (ref 10CFR2.790). Affidavit encl.
UHRIG, R. E. Florida Power & Light Co. 83/03/22. EISENHUT, D. G. Division of Licensing. 5pp. 17678:046. 24X Fiche: 50-335, 83/03/22, 8303240501.

8303280278 Forwards proprietary "Exxon Nuclear Analysis of Power Distribution Measurement Uncertainty for St Lucie Unit 1." Responses re overpressure mitigating sys & Cycle 6 reload encl. Proprietary rept withheld (ref 10CFR2.790).
UHRIG, R. E. Florida Power & Light Co. 83/03/23. CLARK, R. A. Operating Reactors Branch 3. 6pp. 17706:071. 24X
Fiche: 50-335, 83/03/23, 8303280278.

8303300249 Forwards Rev 2 to "Offsite Dose Calculation Manual."
UHRIG, R. E. Florida Power & Light Co. 83/03/28. EISENHUT, D. G. Division of Licensing. 1p. 17732:282. 24X Fiche: 50-335, 83/03/28, 8303300249.

--8303300254 Rev 2 to "Offsite Dose Calculation Manual."
* Florida Power & Light Co. 83/03/28. 100pp. 17732:283. 24X
Fiche: 50-335, 83/03/28, 8303300249.

8303310057 Forwards revised radiological effluent Tech Specs. Tech Spec change request dtd 771221 withdrawn.
UHRIG, R. E. Florida Power & Light Co. 83/03/29. EISENHUT, D. G. Division of Licensing. 3pp. 17758:048. 24X Fiche: 50-335, 83/03/29, 8303310057.

--8303310060 Revised radiological effluent Tech Specs.
* Florida Power & Light Co. 83/03/29. 77pp. 17758:051. 24X
Fiche: 50-335, 83/03/29, 8303310057.

Q. Inspection reports. IE Bulletins & correspondence

8303010660 Forwards RC Lewis 821112 ltr transmitting SALP Repts 50-250/82-33, 50-251/82-33 & 50-335/82-37 for May 1980 - June 1982 & 50-389/82-56 for Sept 1980 - June 1982. Overall performance satisfactory.
O'REILLY, J. P. Region 2, Office of Director. 83/01/18. UHRIG, R. E. Florida Power & Light Co. 2pp. 17341:106. 24X
Fiche: 50-000, 83/01/18, 8303010660.

--8303010672 Forwards SALP Repts 50-250/82-33, 50-251/82-33 & 50-335/82-37 for May 1980 - June 1982 & 50-389/82-56 for Sept 1980 - June 1982. Evaluation will be discussed at 821123 meeting in Miami, FL.
LEWIS, R. C. Division of Project & Resident Programs. 82/11/12
UHRIG, R. E. Florida Power & Light Co. 2pp. 17341:108. 24X
Fiche: 50-000, 83/01/18, 8303010660.

--8303010678 SALP Repts 50-250/82-33, 50-251/82-33 & 50-335/82-37 for May 1980 - June 1982 & 50-389/82-56 for Sept 1980 - June 1982. Overall performance satisfactory.
* Region 2, Office of Director. 82/11/12. 50pp. 17341:110. 24X
Fiche: 50-000, 83/01/18, 8303010660.

8303010640 Forwards IE Insp Rept 50-335/82-43 on 821122-24. No noncompliance noted. Continued mgt attention should be directed toward state of operational readiness of technical support ctr.
O'REILLY, J. P. Region 2, Office of Director. 83/02/07. UHRIG, R. E. Florida Power & Light Co. 2pp. 17336:114. 24X
Fiche: 50-335, 83/02/07, 8303010640.

--8303010648 IE I[illegible] Rept 50-335/82-43 on 821122-24. No noncompliance noted. Major area inspected: emergency preparedness. Deficiency noted in technical support ctr staff augmentation.
HUFFMAN, G. N. Region 2, Office of Director. JENKINS, G. R. Division of Emergency Preparedness & Materials Safety. 83/02/02. 4pp. 17336:116. 24X Fiche: 50-335, 83/02/07, 8303010640.

8303010570 Forwards IE Insp Repts 50-335/83-04 & 50-389/83-12 on 830119-20. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/02/10
UHRIG, R. E. Florida Power & Light Co. 2pp. 17336:233. 24X
Fiche: 50-335, 83/02/10, 8303010570.

--8303010585 IE Insp Repts 50-335/83-04 & 50-389/83-12 on 830119-20. No noncompliance noted. Major areas inspected: radiological emergency exercise.
HUFFMAN, G. N. Region 2, Office of Director. JENKINS, G. R. Division of Emergency Preparedness & Materials Safety. 83/02/07. 11pp. 17336:235. 24X Fiche: 50-335, 83/02/10, 8303010570.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210444 Forwards IE Insp Repts 50-335/82-45 & 50-389/82-74 on 821211-830110. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/02/25
UHRIG, R. E. Florida Power & Light Co. 2pp. 17634:180. 24X
Fiche: 50-335, 83/02/25, 8303210444.

--8303210453 IE Insp Repts 50-335/82-45 & 50-389/82-74 on 821211-830110. No noncompliance noted. Major areas inspected: maint observation, operational safety verification, new fuel handling & bulletins, circulars & info notices.
ELROD, S. A., BIBB, H. E. Region 2, Office of Director. JULIAN, C. A. Division of Project & Resident Programs. 82/02/24. 12pp. 17634:182. 24X Fiche: 50-335, 83/02/25, 8303210444.

8303040514 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." No Bunker-Ramo electrical penetrations installed at facility.
UHRIG, R. E. Florida Power & Light Co. 83/02/28. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 2pp. 17374:047. 24X Fiche: 50-335, 83/02/28, 8303040514.

8303210697 Ack receipt of 830217 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-389/82-75.
DANCE, H. C. Division of Project & Resident Programs. 83/03/01.
UHRIG, R. E. Florida Power & Light Co. 1p. 17635:072. 24X
Fiche: 50-389, 83/03/01, 8303210697.

--8303210712 Forwards IE Insp Repts 50-335/82-46 & 50-389/82-75 on 821213-17 & notice of deviation.
DANCE, H. C. Division of Project & Resident Programs. 83/01/11
UHRIG, R. E. Florida Power & Light Co. 2pp. 17635:075. 24X
Fiche: 50-389, 83/03/01, 8303210697.

--8303210721 IE Insp Repts 50-389/82-75 & 50-335/82-46 on 821213-17. Deviation noted: improper storage of safety-related HEPA filters.
WRAY, J. R., BARR, K. P. Region 2, Office of Director. 83/01/06. 8pp. 17635:078. 24X Fiche: 50-389, 83/03/01, 8303210697.

8303210352 Advises of review of IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Plant does not have subj breakers or employ subj trip design.
UHRIG, R. E. Florida Power & Light Co. 83/03/07. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17634:359. 24X
Fiche: 50-335, 83/03/07, 8303210352.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

R. Periodic operating reports & related correspondence

8303090158 Forwards "Semiannual Radioactive Effluent Release Rept for Jan-June 1981."
UHRIG, R. E. Florida Power & Light Co. 81/08/06. O'REILLY, J. P. Region 2, Atlanta, Office of the Director (81/03/01). 1p. 17471:329. 24X Fiche: 50-335, 81/08/06, 8303090158.

--8303090165 "Semiannual Radioactive Effluent Release Rept for Jan-June 1981."
* Florida Power & Light Co. 81/06/30. 30pp. 17471:330. 24X
Fiche: 50-335, 81/08/06, 8303090158.

8303080402 Forwards monthly operating repts for Dec 1982.
WILLIAMS, J. W. Florida Power & Light Co. 83/01/17. Office of Resource Management, Director. 1p. 17454:034. 24X
Fiche: 50-000, 83/01/17, 8303080402.

--8303080408 Monthly operating repts for Dec 1982.
PACE, P. Florida Power & Light Co. 83/01/17. 13pp. 17454:035. 24X Fiche: 50-000, 83/01/17, 8303080402.

8303150539 Forwa. monthly operating repts for Jan 1983 & corrected monthly operating repts for May-Dec 1982 for St Lucie Unit 1.
WILLIAMS, J. W. Florida Power & Light Co. 83/02/14. Office of Resource Management, Director. 1p. 17568:034. 24X
Fiche: 50-000, 83/02/14, 8303150539.

--8303150546 Monthly operating repts for Jan 1983.
PACE, P. Florida Power & Light Co. 83/02/14. 12pp. 17568:035. 24X Fiche: 50-000, 83/02/14, 8303150539.

--8303150558 Corrected monthly operating repts for May-Dec 1982.
PACE, P. Florida Power & Light Co. 83/02/14. 8pp. 17568:047. 24X Fiche: 50-000, 83/02/14, 8303150539.

S. Reportable occurrences, LERs & related correspondence

8303080422 Forwards LER 83-007/03L-0.
WILLIAMS, J. W. Florida Power & Light Co. 83/02/28. O'REILLY, J. P. Region 2, Office of Director. 1p. 17453:271. 24X
Fiche: 50-335, 83/02/28, 8303080422.

--8303080426 LER 83-007/03L-0 on 830203, control element assembly 66 dropped 56 inches to core. No cause found. Element returned to group position & normal operation resumed.
HAYES, R. L. Florida Power & Light Co. 83/02/28. Region 1, Office of Director. 1p. 17453:272. 24X Fiche: 50-335, 83/02/28, 8303080422.

8303210397 Forwards LER 83-006/03L-0.
WILLIAMS, J. W. Florida Power & Light Co. 83/02/28. O'REILLY, J. P. Region 2, Office of Director. 1p. 17635:011. 24X
Fiche: 50-335, 83/02/28, 8303210397.

--8303210402 LER 83-006/03L-0 on 830121, during periodic control element assembly (CEA) exercise, CEA 43 slipped. Cause not determined. CEA 45 has operated normally since event.
WEST, D. Florida Power & Light Co. 83/02/28. Region 2, Office of Director. 1p. 17635:012. 24X Fiche: 50-335, 83/02/28, 8303210397.

8303160575 Forwards LER 83-009/03L-0.
WILLIAMS, J. W. Florida Power & Light Co. 83/03/09. O'REILLY, J. P. Region 2, Office of Director. 1p. 17587:013. 24X
Fiche: 50-335, 83/03/09, 8303160575.

--8303160586 LER 83-009/03L-0 on 830207, train heaters for shield bldg ventilation sys tripped off due to high temp. Caused by defective Fenwal Model 543 temp controller. Controller replaced.
MCLAUGHLIN, L. Florida Power & Light Co. 83/03/09. Region 2, Office of Director. 1p. 17587:014. 24X Fiche: 50-335, 83/03/09, 8303160575.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8303030189 Forwards IE Insp Repts 50-245/83-02 & 50-336/83-02 on 830109-29. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs. 83/02/18. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 17410:298. 24X Fiche: 50-245, 83/02/18, 8303030189.

--8303030201 IE Insp Repts 50-245/83-02 & 50-336/83-02 on 830109-29. No noncompliance noted. Major areas inspected: evaluations of plant operations, startup testing, radiation protection, physical security, fire protection & plant operating records.
SHEDLOSKY, J. T. Division of Project & Resident Programs. 83/02/14. 14pp. 17410:300. 24X Fiche: 50-245, 83/02/18, 8303030189.

8303090317 Responds to 820817 ltr re changes submitted as Rev 10 to modified amended security plan. Changes acceptable.
CRUTCHFIELD, D. Operating Reactors Branch 5. 83/02/18. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 1p. 17484:239. 24X Fiche: 50-245, 83/02/18, 8303090317.

8303160258 Notification of 830318 meeting w/util in Bethesda, MD to discuss proposed fire protection exemption requests.
LEECH, P. H. Operating Reactors Branch 3. 83/03/09. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17604:353. 24X
Fiche: 50-245, 83/03/09, 8303160258.

8303300462 Forwards IE Insp Repts 50-245/83-05 & 50-336/83-06 on 830130-0226. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/16. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 17731:013. 24X Fiche: 50-245, 83/03/16, 8303300462.

--8303300475 IE Insp Repts 50-245/83-05 & 50-336/83-06 on 830130-0226. No noncompliance noted. Major areas inspected: startup testing, equipment alignments & readiness, radiation protection, physical security & surveillance testing & mod.
SHEDLOSKY, J. T. Region 1, Office of Director. ELSASSER, T. C. Division of Project & Resident Programs. 83/03/15. 13pp. 17731:015. 24X Fiche: 50-245, 83/03/16, 8303300462.

8303290058 Releases public version of rept of emergency plan media briefing session.
FELTON, J. M. Division of Rules and Records. 83/03/21. Document Management Branch. 1p. 17730:290. 24X Fiche: 50-000, 83/03/21, 8303290058.

--8303290064 Forwards public version of rept of 830113 emergency plan media briefing session.
COUNSIL, W. G. Connecticut Yankee Atomic Power Co. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities Service Co. 83/03/11. CLARK, R. A. Operating Reactors Branch 3. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 17730:291. 24X Fiche: 50-000, 83/03/21, 8303290058.

8303290235 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/21. Document Management Branch. 1p. 17727:214. 24X Fiche: 50-245, 83/03/21, 8303290235.

--8303290243 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 4201 re radiological dose assessment, EPIP 4207 re radiological sampling & EPIP 4220 re radiological communications.
COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/03/04. EISENHUT, D. G. Division of Licensing. 2pp. 17727:215. 24X Fiche: 50-245, 83/03/21, 8303290235.

--8303290251 Public version of revised emergency plan implementing procedures, including Procedures EPIP 4201 re radiological dose assessment, EPIP 4207 re radiological sampling & EPIP 4220 re radiological communications.
MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/02/28. 105pp. 17727:217. 24X
Fiche: 50-245, 83/03/21, 8303290235.

J. Insurance & indemnity information

8303080211 Endorsements 84 & 85 to NELIA Policy NF-173 & Endorsements 76 & 77 to MAELU Policy MF-52.
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/02/22. NRC - No Detailed Affiliation Given. 4pp. 17457:090. 24X Fiche: 50-245, 83/02/22, 8303080211.

8303140244 Forwards Endorsement 86 to NELIA Policy NF-173.
SINISI, J. M. Marsh & McLennan, Inc. 83/03/07. SALTZMAN, J. D. Assistant Director for State & Licensee Relations. 2pp. 17539:001. 24X Fiche: 50-245, 83/03/07, 8303140244.

8303140231 Forwards Endorsement 74 to NELIA Policy NF-151.
SINISI, J. M. Marsh & McLennan, Inc. 83/03/08. SALTZMAN, J. D. Assistant Director for State & Licensee Relations. 2pp. 17538:335. 24X Fiche: 50-245, 83/03/08, 8303140231.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303010386 Application to amend Licenses DPR-21 & DPR-65, deleting water quality limits & related monitoring programs from ETS.
COUNSIL, W. G., WERNER, R. P. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/02/16.
CRUTCHFIELD, D. Operating Reactors Branch 5. CLARK, R. A. Operating Reactors Branch 3. 3pp. 17343:175. 24X Fiche: 50-245, 83/02/16, 8303010386.

--8303010390 Proposed Tech Spec changes, deleting water quality limits & related monitoring programs.
* Northeast Nuclrar Energy Co. (subs. of Northeast Utilities). 83/02/28. 17pp. 17343:178. 24X Fiche: 50-245, 83/02/16, 8303010386.

8303040178 Responds to 830128 ltr re simulator program & commends util commitment to provide plant-specific simulators for use in training nuclear power plant operators.
THOMPSON, H. L. Division of Human Factors Safety. 83/02/25.
COUNSIL, W. G. Northeast Utilities. 4pp. 17427:018. 24X
Fiche: 50-000, 83/02/25, 8303040178.

--8303040187 Discusses use of plant simulators to train nuclear power plant operators. Util committed to procurement & use of plant-specific simulators.
COUNSIL, W. G. Connecticut Yankee Atomic Power Co. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/01/28. DIRCKS, W. J. Office of the Executive Director for Operations. 3pp. 17427:022. 24X
Fiche: 50-000, 83/02/25, 8303040178.

8303110313 Application for amend to License DPR-65, changing Tech Spec 3.4.6.2.b to extend time period which plant must be in cold shutdown following determination that unidentified RCS leakage exceeded 1.0 gpm limit.
COUNSIL, W. G., SEARS, C. F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/03/01.
CLARK, R. A. Operating Reactors Branch 3. 3pp. 17518:113. 24X
Fiche: 50-336, 83/03/01, 8303110313.

--8303110322 Proposed changes to Tech Spec 3.4.6.2.b, extending time period which plant must be in cold shutdown following determination that unidentified RCS leakage exceeded 1.0 gpm limit.
* Northeast Utilities. 83/03/01. 2pp. 17518:116. 24X
Fiche: 50-336, 83/03/01, 8303110313.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303160668 Confirms 830301 telcon authorizing Tech Spec change re RCS leakage, per 830301 telecopy request. Amend to License DPR-65, safety evaluation & FR notice forthcoming.
LAINAS, G. C. Assistant Director for Operating Reactors. 83/03/02.
COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 6pp. 17600:287. 24X Fiche: 50-336, 83/03/02, 8303160668.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303100258 Advises of minor oversight in documentation of containment water level monitoring sys in response to NUREG-0737, Item II.F.1.5. Design verification reveals wide-range containment water level monitor measures vol of 565,000 gallons.
COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/03/08.
CLARK, R. A. Operating Reactors Branch 3. 2pp. 17489:357. 24X
Fiche: 50-336, 83/03/08, 8303100258.

8303170156 Advises of minor discrepancy re containment water level monitoring sys. Sys capable of measuring in excess of max postulated containment water vol, therefore intent of NUREG-0737, Item II.F.1.5 fulfilled.
COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/03/08.
CLARK, R. A. Operating Reactors Branch 3. 2pp. 17609:079. 24X
Fiche: 50-336, 83/03/08, 8303170156.

8303160550 Responds to 830217 ltr requesting info on presence of federally listed & proposed endangered or threatened species in plant area. Except for occasional transient individuals, no species identified in project impact areas.
BECKETT, G. E. Interior, Dept. of, Fish & Wildlife Service. 83/03/10
YOUNGBLOOD, B. J. Licensing Branch 1. 2pp. 17587:260. 24X
Fiche: 50-245, 83/03/10, 8303160550.

8303230044 Forwards info re inadequate core cooling instrumentation sys in response to Generic Ltr 82-28 & TMI Action Item II.F.2. Core exit thermocouples & subcooled margin monitors installed or upgraded.
COUNSIL, W. G. Connecticut Yankee Atomic Power Co. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/03/11. EISENHUT, D. G. Division of Licensing. 18pp. 17663:294. 24X Fiche: 50-000, 83/03/11, 8303230044.

8303230421 Forwards Amends 89 & 81 to Licenses DPR-21 & DPR-65, respectively & notice of issuance & availability. Amends delete App B ETS re nonradiological water quality-related requirements.
CLARK, R. A. Operating Reactors Branch 3. 83/03/11. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 4pp. 17674:108. 24X Fiche: 50-245, 83/03/11, 8303230421.

--8303230429 Amends 89 & 81 to Licenses DPR-21 & DPR-65, respectively, deleting App B ETS re nonradiological water quality-related requirements.
CRUTCHFIELD, D. Operating Reactors Branch 5. CLARK, R. A. Operating Reactors Branch 3. 83/03/11. 26pp. 17674:112. 24X
Fiche: 50-245, 83/03/11, 8303230421.

--8303230435 Notice of issuance & availability of Amends 89 & 81 to Licenses DPR-21 & DPR-65, respectively.
CLARK, R. A. Operating Reactors Branch 3. 83/03/11. 2pp.
17674:138. 24X Fiche: 50-245, 83/03/11, 8303230421.

8303240015 Forwards Amend 82 to License DPR-65, safety evaluation & notice of issuance & availability. Amend adds footnote to Tech Spec 3.4.6.2.b action statement to allow addl 24 h before unit must be in cold shutdown.
CLARK, R. A. Operating Reactors Branch 3. 83/03/11. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp.
17694:338. 24X Fiche: 50-336, 83/03/11, 8303240015.

--8303240038 Amend 82 to License DPR-65, adding footnote to Tech Spec 3.4.6.2.b action statement to allow addl 24 h before unit must be in cold shutdown after 1 gpm RCS unidentified leakage limit exceeded.
CLARK, R. A. Operating Reactors Branch 3. 83/03/11. 5pp.
17694:341. 24X Fiche: 50-336, 83/03/11, 8303240015.

--8303240041 Safety evaluation supporting Amend 82 to License DPR-65.
* Office of Nuclear Reactor Regulation, Director. 83/03/11. 2pp.
17694:346. 24X Fiche:50-336,83/03/11,8303240015.

--8303240042 Notice of issuance & availability of Amend 82 to License DPR-65.
CLARK,R.A. Operating Reactors Branch 3. 83/03/11. 2pp.
17694:348. 24X Fiche:50-336,83/03/11,8303240015.

8303230098 Forwards order confirming commitments to implement post-TMI items scheduled for completion on or after 820701, based on responses to Generic Ltrs 82-05 & 82-10.
CLARK,R.A. Operating Reactors Branch 3. 83/03/14. COUNSIL,W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp.
17687:161. 24X Fiche:50-336,83/03/14,8303230098.

--8303230103 Order confirming licensee commitments to implement & maintain post-TMI related issues.
PURPLE,R.A. Division of Licensing. 83/03/14. Connecticut Light & Power Co. 10pp. 17687:164. 24X Fiche:50-336,83/03/14,8303230098.

8303290452 Application for amend to License DPR-65, revising Tech Specs re steam generator inservice insp.
COUNSIL,W.G. Northeast Utilities. 83/03/14. CLARK,R.A. Operating Reactors Branch 3. 5pp. 17725:331. 24X Fiche:50-336,83/03/14,8303290452.

--8303290459 Proposed Tech Spec revs re frequency of steam generator inservice insp.
* Northeast Utilities. 83/03/01. 4pp. 17725:336. 24X Fiche:50-336,83/03/14,8303290452.

8303300253 Forwards Amend 83 to License DPR-65, safety evaluation & notice of issuance & availability. Amend defers steam generator inservice insp requirements of Tech Spec to May 1983 refueling outage.
CLARK,R.A. Operating Reactors Branch 3. 83/03/16. COUNSIL,W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp.
17748:321. 24X Fiche:50-336,83/03/16,8303300253.

--8303300256 Amend 83 to License DPR-65, deferring steam generator inservice insp requirements of Tech Spec to May 1983 refueling outage.
CLARK,R.A. Operating Reactors Branch 3. 83/03/16. 7pp.
17748:324. 24X Fiche:50-336,83/03/16,8303300253.

--8303300261 Safety evaluation supporting Amend 83 to License DPR-65.
* Office of Nuclear Reactor Regulation, Director. 83/03/16. 7pp.
17748:331. 24X Fiche:50-336,83/03/16,8303300253.

--8303300266 Notice of issuance & availability of Amend 83 to License DPR-65.
CLARK,R.A. Operating Reactors Branch 3. 83/03/16. 2pp.
17748:338. 24X Fiche:50-336,83/03/16,8303300253.

8303290443 Informs that schedule for completion of qualification of electrical equipment will be submitted by 830520. Ninety-day responses requested in NRC 821213 ltr superseded by issuance of 10CFR50.49 final rule.
COUNSIL,W.G. Connecticut Yankee Atomic Power Co. COUNSIL,W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL,W.G. Northeast Utilities. 83/03/18. CLARK,R.A. Operating Reactors Branch 3. CRUTCHFIELD,D. Operating Reactors Branch 5.
2pp. 17725:350. 24X Fiche:50-000,83/03/18,8303290443.

8303290195 Forwards comments on 830128 draft generic ltr to PWR licensees addressing NUREG-0737 items scheduled for implementation after 811231. Basis for extension of response time to 120 or 150 days provided.
COUNSIL,W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL,W.G. Connecticut Yankee Atomic Power Co. COUNSIL,W.G. Northeast Utilities. 83/03/24. EISENHUT,D.G. Division of Licensing. 5pp. 17722:251. 24X Fiche:50-000,83/03/24,8303290195.

8303310311 Withdraws request for hearing re environ qualification of safety-related electrical equipment. Withdrawal based on interpretations of 10CFR50.49, final rule re qualification criteria & replacement equipment.
COUNSIL,W.G. Connecticut Yankee Atomic Power Co. COUNSIL,W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL,W.G. Northeast Utilities. 83/03/24. EISENHUT,D.G. Division of Licensing. 2pp. 17755:139. 24X Fiche:50-000,83/03/24,8303310311.

G. Inspection reports, IE Bulletins & correspondence

8303010347 Provides results of ongoing study of merits of not tripping diesel generators upon restoration of 125-volt dc electrical power, per agreement reached on IE Insp Rept 50-336/82-23. Listed mods to be incorporated by end of 1983.
COUNSIL,W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL,W.G. Northeast Utilities. 83/01/27.
MARTIN,T.T. Division of Engineering & Technical Programs. 2pp.
17346:171. 24X Fiche:50-336,83/01/27,8303010347.

8303030172 Forwards IE Insp Repts 50-245/82-23 & 50-336/82-25 on 821121-830108 & notice of violation.
STAROSTECKI,R. Division of Project & Resident Programs. 83/02/18.
COUNSIL,W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 17410:153. 24X Fiche:50-245,83/02/18,8303030172.

--8303030177 Notice of violation from insp on 821121-830108.
* Region 1, Office of Director. 83/02/18. 2pp. 17410:155. 24X Fiche:50-245,83/02/18,8303030172.

--8303030184 IE Insp Repts 50-245/82-23 & 50-336/82-25 on 821121-830108. Noncompliance noted: failure to implement test procedures & failure to follow procedures re quality & testing.
SHEDLOSKY,J.T., LIPINSKI,D.R., ELSASSER,T.C. Division of Project & Resident Programs. 83/01/25. 26pp. 17410:157. 24X Fiche:50-245,83/02/18,8303030172.

8303030189 Forwards IE Insp Repts 50-245/83-02 & 50-336/83-02 on 830109-29. No noncompliance noted.
STAROSTECKI,R. Division of Project & Resident Programs. 83/02/18.
COUNSIL,W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 17410:298. 24X Fiche:50-245,83/02/18,8303030189.

--8303030201 IE Insp Repts 50-245/83-02 & 50-336/83-02 on 830109-29. No noncompliance noted. Major areas inspected: evaluations of plant operations, startup testing, radiation protection, physical security, fire protection & plant operating records.
SHEDLOSKY,J.T., LIPINSKI,D.R., ELSASSER,T.C. Division of Project & Resident Programs. 83/02/14. 14pp. 17410:300. 24X Fiche:50-245,83/02/18,8303030189.

8303040368 Responds to request to review IE Bulletin 82-04 re applicability of deficiencies in primary containment electrical penetration assemblies. No assemblies mfg by Bunker-Ramo in svc or planned for use at plants.
COUNSIL,W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL,W.G. Northeast Utilities. COUNSIL,W.G. Connecticut Yankee Atomic Power Co. 83/02/22. HAYNES,R.C. Region 1, Office of Director. 2pp. 17420:014. 24X Fiche:50-000,83/02/22,8303040368.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc.
11pp. 17521:001. 24X Fiche:50-000,83/02/25,8212060367.

8303100146 Forwards IE Insp Rept 50-336/83-03 on 830202-04. No noncompliance noted.
MARTIN,T.T. Division of Engineering & Technical Programs. 83/02/25.
COUNSIL,W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 17485:243. 24X Fiche:50-336,83/02/25,8303100146.

--8303100150 IE Insp Rept 50-336/83-03 on 830202-04. No noncompliance noted. Major areas inspected: inservice testing surveillance program for pumps & valves & containment penetration leakage testing surveillance.
REKITO,W.A., NORRHOLM,L.J. Division of Engineering & Technical Programs. 83/02/25. 7pp. 17485:245. 24X Fiche:50-336,83/02/25,8303100146.

8303160612 Forwards IE Insp Repts 50-245/83-03 & 50-336/83-04 on 830208-11. No noncompliance noted.
MARTIN,T.T. Division of Engineering & Technical Programs. 83/03/04.
COUNSIL,W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 17587:213. 24X Fiche:50-245,83/03/04,8303160612.

--8303160616 IE Insp Repts 50-245/83-03 & 50-336/83-04 on 830208-11. No noncompliance noted. Major areas inspected: mgt controls, licensee program for QC & analytical measures & followup action on previous environ insp findings.
JANG,J.C., PASCIAK,W.J. Region 1, Office of Director. 83/02/28.
6pp. 17587:215. 24X Fiche:50-245,83/03/04,8303160612.

8303180297 Responds to IE Bulletin 83-01 re failures of Westinghouse DB-type circuit breakers. Millstone Unit 2 does not use sub; circuit breakers. Testing at Haddam Neck demonstrated no abnormal conditions present.
COUNSIL, W. G. Connecticut Yankee Atomic Power Co. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/03/04. HAYNES, R. C. Region 1, Office of Director. 2pp. 17616:007. 24X Fiche: 50-000, 83/03/04, 8303180297.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303280207 Forwards IE Insp Repts 50-245/83-04 & 50-336/83-05 on 830208-11. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/14. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 17706:293. 24X Fiche: 50-245, 83/03/14, 8303280207.

--8303280214 IE Insp Repts 50-245/83-04 & 50-336/83-05 on 830208-11. No noncompliance noted. Major areas inspected: previously identified items, exposure control, radiation protection program implementation & personnel qualification & training.
ROWE, C., MCBRIDE, M., SHANBAKY, M. Region 1, Office of Director. 83/03/10. 5pp. 17706:295. 24X Fiche: 50-245, 83/03/14, 8303280207.

8303290452 Application for amend to License DPR-65, revising Tech Specs re steam generator inservice insp.
COUNSIL, W. G. Northeast Utilities. 83/03/14. CLARK, R. A. Operating Reactors Branch 3. 5pp. 17725:331. 24X Fiche: 50-336, 83/03/14, 8303290452.

--8303290459 Proposed Tech Spec revs re frequency of steam generator inservice insp.
* Northeast Utilities. 83/03/01. 4pp. 17725:336. 24X Fiche: 50-336, 83/03/14, 8303290452.

8303300253 Forwards Amend 83 to License DPR-65, safety evaluation & notice of issuance & availability. Amend defers steam generator inservice insp requirements of Tech Spec to May 1983 refueling outage.
CLARK, R. A. Operating Reactors Branch 3. 83/03/16. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp. 17748:321. 24X Fiche: 50-336, 83/03/16, 8303300253.

--8303300256 Amend 83 to License DPR-65, deferring steam generator inservice insp requirements of Tech Spec to May 1983 refueling outage.
CLARK, R. A. Operating Reactors Branch 3. 83/03/16. 7pp. 17748:324. 24X Fiche: 50-336, 83/03/16, 8303300253.

--8303300261 Safety evaluation supporting Amend 83 to License DPR-65.
* Office of Nuclear Reactor Regulation, Director. 83/03/16. 7pp. 17748:331. 24X Fiche: 50-336, 83/03/16, 8303300253.

--8303300266 Notice of issuance & availability of Amend 83 to License DPR-65.
CLARK, R. A. Operating Reactors Branch 3. 83/03/16. 2pp. 17748:338. 24X Fiche: 50-336, 83/03/16, 8303300253.

8303300462 Forwards IE Insp Repts 50-245/83-05 & 50-336/83-06 on 830130-0226. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/16. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 17731:013. 24X Fiche: 50-245, 83/03/16, 8303300462.

--8303300475 IE Insp Repts 50-245/83-05 & 50-336/83-06 on 830130-0226. No noncompliance noted. Major areas inspected: startup testing, equipment alignments & readiness, radiation protection, physical security & surveillance testing & mod.
SHEDLOSKY, J. T., LIPINSKI, D. R., GRAY, E. H. Region 1, Office of Director. 83/03/15. 13pp. 17731:015. 24X Fiche: 50-245, 83/03/16, 8303300462.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303300359 Responds to IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Breakers." Undervoltage trip function of each breaker successfully tested independent of respective shunt trip function.
COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/03/21. HAYNES, R. C. Region 1, Office of Director. 2pp. 17734:192. 24X Fiche: 50-336, 83/03/21, 8303300359.

R. Periodic operating reports & related correspondence

8303080201 Forwards monthly operating rept for Dec 1982.
MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA, E. J. Northeast Utilities. 83/01/13. Division of Data Automation & Management Information. 1p. 17457:064. 24X Fiche: 50-336, 83/01/13, 8303080201.

--8303080207 Monthly operating rept for Dec 1982.
GIBSON, J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/01/13. 5pp. 17457:065. 24X Fiche: 50-336, 83/01/13, 8303080201.

8303150430 Forwards monthly operating rept for Jan 1983.
MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA, E. J. Northeast Utilities. 83/02/15. Division of Data Automation & Management Information. 1p. 17561:152. 24X Fiche: 50-336, 83/02/15, 8303150430.

--8303150433 Monthly operating rept for Jan 1983.
GIBSON, J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/02/11. 5pp. 17561:153. 24X Fiche: 50-336, 83/02/15, 8303150430.

8303080208 Forwards "Semiannual Radioactive Effluents Release Rept, Jul-Dec 1982."
COUNSIL, W. G., SEARS, C. F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/02/18. HAYNES, R. C. Region 1, Office of Director. 1p. 17439:166. 24X Fiche: 50-245, 83/02/18, 8303080208.

--8303080218 "Semiannual Radioactive Effluents Release Rept, Jul-Dec 1982."
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/02/18. 121pp. 17439:167. 24X Fiche: 50-245, 83/02/18, 8303080208.

8303240407 Forwards "Haddam Neck Plant & Millstone Station Units 1 & 2 Annual Rept, 1982," containing summary of challenges to relief valves, per util 800610 commitment.
COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Connecticut Yankee Atomic Power Co. COUNSIL, W. G. Northeast Utilities. 83/03/01. HAYNES, R. C. Region 1, Office of Director. 1p. 17679:130. 24X Fiche: 50-000, 83/03/01, 8303240407.

--8303240408 "Haddam Neck Plant & Millstone Station Units 1 & 2 Annual Rept, 1982."
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). * Connecticut Yankee Atomic Power Co. * Northeast Utilities. 83/03/01. 183pp. 17679:131. 24X Fiche: 50-000, 83/03/01, 8303240407.

S. Reportable occurrences, LERs & related correspondence

8303020185 Forwards safety evaluation of licensee investigation & actions in response to 810102 reactor trip following de-energization of 125-volt dc bus. Licensee responses & associated changes in emergency power sys acceptable.
CLARK, R. A. Operating Reactors Branch 3. 83/02/16. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 17358:285. 24X Fiche: 50-336, 83/02/16, 8303020185.

--8303020189 Safety evaluation supporting licensee changes to emergency power sys in response to 810102 reactor trip following de-energization of 125-volt dc bus.
EAPEN, P. K. Region 1, Office of Director. CONNER, E. L., LEECH, P. H. Office of Nuclear Reactor Regulation, Director. 83/02/16. 7pp. 17358:287. 24X Fiche: 50-336, 83/02/16, 8303020185.

8303080413 Forwards LER 83-002/03L-0.
MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA, F. J. Northeast Utilities. 83/02/24. HAYNES, R. C. Region 1, Office of Director. 1p. 17454:052. 24X Fiche: 50-336, 83/02/24, 8303080413.

--8303080419 LER 83-002/03L-0: on 830127, discovered surveillance for charging pump operability not performed within required period. Caused by personnel error. Dept instruction & operator reinstruction instituted, covering surveillance deadlines.
PARULIS, P. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/02/24. Region 1, Office of Director. 1p. 17454:053. 24X Fiche: 50-336, 83/02/24, 8303080413.

8303180330 Forwards LER 83-004/03L-0.
MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA, E. J. Northeast Utilities. 83/03/11.
HAYNES, R. C. Region 1, Office of Director. 1p. 17619:295. 24X Fiche: 50-336, 83/03/11, 8303180330.

--8302180336 LER 83-004/03L-0 on 830218, while in Mode 1, CEA 16 dropped 27 steps during surveillance testing per Tech Spec 4.1.3.1.2. Cause unknown. CEA withdrawn & coil power programmer power main & backup supplies tested.
KOMOSKY, G. E. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/03/11. Region 1, Office of Director. 1p. 17619:296. 24X Fiche: 50-336, 83/03/11, 8303180330.

8303180374 Forwards LER 83-003/03L-0. Detailed event analysis encl.
MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA, E. J. Northeast Utilities. 83/03/11.
HAYNES, R. C. Region 1, Office of Director. 2pp. 17621:339. 24X Fiche: 50-336, 83/03/11, 8303180374.

--8303180382 LER 83-003/03L-0 on 830219, following reactor trip from 98% power, activity of greater than 1.0 uCi/g dose equivalent I-131 found in primary coolant. Caused by small number of degraded fuel pins. No corrective actions stated.
BORCHERT, R. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/03/11. Region 1, Office of Director. 1p. 17621:341. 24X Fiche: 50-336, 83/03/11, 8303180374.

8303240457 Forwards LER 83-001/04T-0.
MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA, E. J. Northeast Utilities. 83/03/11.
HAYNES, R. C. Region 1, Office of Director. 1p. 17678:065. 24X Fiche: 50-336, 83/03/11, 8303240457.

--8303240463 LER 83-001/04T-0 on 830302, recorder associated w/liquid radwaste discharge path RJR 9129 failed while in Mode 3 at 532 F. Caused by stripped gear on drive motor. Defective gear & motor replaced.
DUFFY, B. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 83/03/11. Region 1, Office of Director. 1p. 17678:066. 24X Fiche: 50-336, 83/03/11, 8303240457.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8303210722 Forwards IE Insp Repts 50-338/83-02 & 50-339/83-02 on 830110-14. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/02/17.
STEWART, W. L. Virginia Electric & Power Co. 2pp. 17635:137. 24X Fiche: 50-338, 83/02/17, 8303210722.

--8303210730 IE Insp Repts 50-338/83-02 & 50-339/83-02 on 830110-14. No noncompliance noted. Major areas inspected: emergency preparedness.
MARSTON, R. R., JENKINS, G. R. Region 2, Office of Director. 83/02/14. 14pp. 17635:139. 24X Fiche: 50-338, 83/02/17, 8303210722.

8303240395 Ack receipt of 820811 & 1209 proposed Rev 8 to security plan. Identified changes unacceptable. Security effectiveness decreased & changes inconsistent w/10CFR50.54. Encls to ltrs withheld (ref 10CFR2.790).
CLARK, R. A. Operating Reactors Branch 3. 83/03/22. STEWART, W. L. Virginia Electric & Power Co. 2pp. 17679:050. 24X Fiche: 50-338, 83/03/22, 8303240395.

8303300419 Responds to 830202 ltr submitting Rev 9 to security program. Changes consistent w/provisions of 10CFR50.54(p). Encl to ltr withheld (ref 10CFR73.21).
CLARK, R. A. Operating Reactors Branch 3. 83/03/22. STEWART, W. L. Virginia Electric & Power Co. 1p. 17754:016. 24X Fiche: 50-338, 83/03/22, 8303300419.

8303290457 Forwards IE Safeguards Insp Repts 50-338/83-06 & 50-339/83-06 on 830307-11. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/03/23.
STEWART, W. L. Virginia Electric & Power Co. 2pp. 17725:121. 24X Fiche: 50-338, 83/03/23, 8303290457.

--8303290485 IE Safeguards Insp Repts 50-338/83-06 & 50-339/83-06 on 830307-11. No noncompliance noted. Major areas inspected: site orientation, physical barriers for protected & vital areas & detection aids. Details withheld (ref 10CFR73.21).
HALL, B. L. Region 2, Office of Director. MCGUIRE, D. R. Division of Emergency Preparedness & Materials Safety. 83/03/23. 1p. 17725:123. 24X Fiche: 50-338, 83/03/23, 8303290457.

8303290725 Releases public version of revised corporate emergency response plan & implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/23. Document Management Branch. 1p. 17746:219. 24X Fiche: 50-000, 83/03/23, 8303290725.

--8303290732 Forwards public version of Rev 2 to corporate emergency response plan & implementing procedures.
STEWART, W. L. Virginia Electric & Power Co. 83/03/15.
O'REILLY, J. P. Region 2, Office of Director. 1p. 17746:220. 24X Fiche: 50-000, 83/03/23, 8303290725.

--8303290739 Public version of Rev 2 to corporate emergency response plan.
MARTIN, J. W. Virginia Electric & Power Co. 83/03/11. 72pp. 17746:221. 24X Fiche: 50-000, 83/03/23, 8303290725.

--8303290743 Public version of Rev 2 to corporate plan implementing procedures, including Procedures CPIP-3.0 re administrative svc manager callout/activation, CPIP-3.2 re immediate action items & CPIP-3.3 re message handling. Revised index encl.
* Virginia Electric & Power Co. 83/02/15. 18pp. 17746:292. 24X Fiche: 50-000, 83/03/23, 8303290725.

G. Adjudicatory correspondence

8303040479 Forwards util 820713 ltr to NRC w/attachments constituting util application to transfer spent fuel from Surry. Attachment 4 requires special treatment & will be sent separately. W/o encl. Related correspondence.
MAUPIN, M. W. Hunton & Williams. MAUPIN, M. W. Virginia Electric & Power Co. 83/03/01. WOLFE, S. J., KLINE, J., FERGUSON, G. A. Atomic Safety and Licensing Board Panel. 2pp. 17373:359. 24X Fiche: 50-338, 83/03/01, 8303040479.

8303040483 Forwards util 820820 ltr w/attachments constituting util application to expand spent fuel pool. Util 821021 encl ltr corrects info in application. W/o encl. Related correspondence.
MAUPIN, M. W. Hunton & Williams. MAUPIN, M. W. Virginia Electric & Power Co. 83/03/01. WOLFE, S. J., KLINE, J., FERGUSON, G. A. Atomic Safety and Licensing Board Panel. 2pp. 17374:008. 24X Fiche: 50-338, 83/03/01, 8303040483.

8303040324 Forwards Catawba ASLB 830225 memorandum & order ruling on transshipment issue. W/o encl.
MCGURREN, H. J. Hearing Branch 1. 83/03/02. WOLFE, S. J., FERGUSON, G. A., KLINE, J. Atomic Safety and Licensing Board Panel. 1p. 17421:346. 24X Fiche: 50-338, 83/03/02, 8303040324.

8303100142 Forwards facility licensing info including OLs & amends re expansion of fuel pool capacity & transportation of spent fuel, per ASLB 830218 order memorializing 830216 special prehearing conference. W/o encl.
MCGURREN, H. J. Hearing Branch 1. 83/03/09. WOLFE, S. J., FERGUSON, G. A., KLINE, J. Atomic Safety and Licensing Board Panel. 2pp. 17485:252. 24X Fiche: 50-338, 83/03/09, 8303100142.

H. General correspondence

8303160160 Notifies that EW Harrell will replace WR Cartwright as station manager as of 830318.
STEWART, W. L. Virginia Electric & Power Co. 83/03/10. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 1p. 17596:362. 24X Fiche: 50-338, 83/03/10, 8303160160.

J. Insurance & indemnity information

8303110207 Forwards Endorsements 42 & 69 to NELIA Policies NF-240 & NF-186, respectively.
WILSON, J. M. Marsh & McLennan, Inc. 83/03/08. DINITZ, I. Antitrust & Economic analysis Branch (Utility Finance). 3pp. 17513:360. 24X Fiche: 50-000, 83/03/08, 8303110207.

M. Antitrust correspondence

8303140221 Application for amends to Licenses NPF-4 & NPF-7, incorporating Old Dominion Electric Cooperative as potential owner of facility. Indemnity agreements & antitrust info will be provided at later date.
STEWART, W. L. Virginia Electric & Power Co. 83/03/10. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 485pp. 17527:004. 24X
Fiche: 50-338, 83/03/10, 8303140221.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303080484 Submits response to draft technical evaluation rept, "Control of Heavy Loads," Item 2.1.8, "Crane Design." Util awaiting final documentation of evaluation due to decrease in staff. Final rept to be provided by 830401.
STEWART, W. L. Virginia Electric & Power Co. 83/03/01. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17452:276. 24X
Fiche: 50-338, 83/03/01, 8303080484.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303100189 Supplemental application for amend to Licenses NPF-4 & NPF-7, proposing Tech Spec changes to delete remaining portions of ETS from 821217 radiological effluent Tech Spec submittal. No addl amend fee required.
STEWART, W. L. Virginia Electric & Power Co. 83/03/03. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 1p. 17485:188. 24X
Fiche: 50-338, 83/03/03, 8303100189.

--8303100191 Proposed Tech Specs, deleting ETS from radiological effluent Tech Specs. Discussion of proposed change encl.
* Virginia Electric & Power Co. 83/03/03. 6pp. 17485:189. 24X
Fiche: 50-338, 83/03/03, 8303100189.

8303100372 Forwards justification of continued operation of equipment in Category II.B as defined in Franklin Research Ctr draft technical evaluation rept on environ qualification of safety-related electrical equipment, per 830224 request.
STEWART, W. L. Virginia Electric & Power Co. 83/03/03. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 6pp. 17490:326. 24X
Fiche: 50-338, 83/03/03, 8303100372.

8303110120 Informs that Victoreen does not have source available to perform final in situ calibr of containment high-range radiation monitors required by NUREG-0737, Item II.F.1.3. Source will be made available before 840930 deadline.
STEWART, W. L. Virginia Electric & Power Co. 83/03/03. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. EISENHUT, D. G. Division of Licensing. 1p. 17517:319. 24X Fiche: 50-338, 83/03/03, 8303110120.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 31pp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303140221 Application for amends to Licenses NPF-4 & NPF-7, incorporating Old Dominion Electric Cooperative as potential owner of facility. Indemnity agreements & antitrust info will be provided at later date.
STEWART, W. L. Virginia Electric & Power Co. 83/03/10. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 485pp. 17527:004. 24X
Fiche: 50-338, 83/03/10, 8303140221.

8303160198 Requests 60-day extension, until 830509, to respond to Generic Ltr 82-28 re inadequate core cooling instrumentation sys, in order to complete review.
STEWART, W. L. Virginia Electric & Power Co. 83/03/10. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. EISENHUT, D. G. Division of Licensing. 1p. 17596:291. 24X Fiche: 50-000, 83/03/10, 8303160198.

8303170525 Informs that final in situ calibr of containment high-range radiation monitors, per NUREG-0737, Item II.F.1.3, can be completed during maint outage scheduled for completion by 831031.
STEWART, W. L. Virginia Electric & Power Co. 83/03/11. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. EISENHUT, D. G. Division of Licensing. 1p. 17610:182. 24X Fiche: 50-338, 83/03/11, 8303170525.

8303180467 Suppls 830303 ltr re containment sump wide-range & narrow-range level transmitters. Wide-range level transmitters for containment sumps replaced on Unit 1. Narrow-range level transmitters will be replaced on Unit 2 during Apr outage.
STEWART, W. L. Virginia Electric & Power Co. 83/03/15. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17621:251. 24X Fiche: 50-338, 83/03/15, 8303180467.

8303290646 Forwards order confirming util commitments to implement post-TMI-related items set forth in NUREG-0737 & in Generic Ltrs 82-05 & 82-10.
CLARK, R. A. Operating Reactors Branch 3. 83/03/15. STEWART, W. L. Virginia Electric & Power Co. 3pp. 17745:160. 24X
Fiche: 50-338, 83/03/15, 8303290646.

--8303290653 Order conforming commitment to implement post-TMI-related items set forth in NUREG-0737 & Generic Ltrs 82-05 & 82-10.
PURPLE, R. A. Division of Licensing. 83/03/15. Virginia Electric & Power Co. 8pp. 17745:163. 24X Fiche: 50-338, 83/03/15, 8303290646.

8303310606 Summary of 830310 meeting w/LLL re evaluation of main transformer failures impact on plant. LLL plan on approach to be used in evaluation requested by 830321.
LEE, R. S. Operating Reactors Branch 3. 83/03/22. CLARK, R. A. Operating Reactors Branch 3. 4pp. 17780:326. 24X
Fiche: 50-338, 83/03/22, 8303310606.

8303280105 Forwards Bechtel Assoc revised "Comparison Between CMAA-70 & EOCI-61," final response to technical evaluation rept, Section 2.1.8 re crane design per NUREG-0612.
STEWART, W. L. Virginia Electric & Power Co. 83/03/23. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 1p. 17707:007. 24X
Fiche: 50-338, 83/03/23, 8303280105.

--8303280110 Revised "Comparison Between CMAA-70 & EOCI-61."
* Bechtel Corp. 83/03/01. 4pp. 17707:008. 24X
Fiche: 50-338, 83/03/23, 8303280105.

8303300138 Informs that util has decided not to request public hearing on orders for mod of license re qualification of safety-related electrical equipment.
CHRISTMAN, J. N. Hunton & Williams. 83/03/24. EISENHUT, D. G. Division of Licensing. 2pp. 17735:296. 24X Fiche: 50-000, 83/03/24, 8303300138.

8303300584 Forwards safety evaluations for environ qualification of safety-related electrical equipment. Justification for continued operation must be submitted by 830520. W/o technical evaluation rept.
CLARK, R. A. Operating Reactors Branch 3. 83/03/24. STEWART, W. L. Virginia Electric & Power Co. 3pp. 17766:317. 24X
Fiche: 50-338, 83/03/24, 8303300584.

--8303300591 Safety evaluation for environ qualification of safety-related electric equipment. Submission of info providing justification for continued operation required in 30 days.
SHEMANSKI, P. Operating Reactors Branch 3. 83/03/24. 12pp. 17766:320. 24X Fiche: 50-338, 83/03/24, 8303300584.

Q. Inspection reports, IE Bulletins & correspondence

8303010443 Forwards IE Insp Repts 50-338/82-40 & 50-339/82-40 on 821206-830105. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/02/07. STEWART, W. L. Virginia Electric & Power Co. 2pp. 17343:055. 24X
Fiche: 50-338, 83/02/07, 8303010443.

--8303010465 IE Insp Repts 50-338/82-40 & 50-339/82-40 on 821206-830105. No noncompliance noted. Major areas inspected: outage activities, surveillance program, plant winterization program, bulletin followup & plant operation.
SHYNLOCK, M. B., JULIAN, C. Division of Project & Resident Programs. 83/02/07. 5pp. 17343:057. 24X Fiche: 50-338, 83/02/07, 8303010443.

8303210722 Forwards IE Insp Repts 50-338/83-02 & 50-339/83-02 on 830110-14. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/02/17. STEWART, W. L. Virginia Electric & Power Co. 2pp. 17635:137. 24X
Fiche: 50-338, 83/02/17, 8303210722.

--8303210730 IE Insp Repts 50-338/83-02 & 50-339/83-02 on 830110-14 No noncompliance noted. Major areas inspected: emergency preparedness.
MARSTON, R. R., JENKINS, G. R. Region 2, Office of Director. 83/02/14. 14pp. 17635:139. 24X Fiche: 50-338, 83/02/17, 8303210722.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210523 Forwards response to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Operators reviewed Salem event. Operability tests performed.
STEWART, W. L. Virginia Electric & Power Co. 83/03/04. O'REILLY, J. P. Region 2, Office of Director. 4pp. 17632:219. 24X Fiche: 50-000, 83/03/04, 8303210523.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303280056 Forwards addl info re IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel)." No evidence of Corbicula infestation noted.
STEWART, W. L. Virginia Electric & Power Co. 83/03/22. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. JORDAN, E. L. Division of Safeguards & Inspection Programs (Post 830103). 3pp. 17707:288. 24X Fiche: 50-338, 83/03/22, 8303280056.

8303290457 Forwards IE Safeguards Insp Repts 50-338/83-06 & 50-339/83-06 on 830307-11. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/03/23. STEWART, W. L. Virginia Electric & Power Co. 2pp. 17725:121. 24X Fiche: 50-338, 83/03/23, 8303290457.

--8303290485 IE Safeguards Insp Repts 50-338/83-06 & 50-339/83-06 on 830307-11. No noncompliance noted. Major areas inspected: site orientation, physical barriers for protected & vital areas & detection aids. Details withheld (ref 10CFR73.21).
HALL, B. L. Region 2, Office of Director. MCGUIRE, D. R. Division of Emergency Preparedness & Materials Safety. 83/03/23. 1p. 17725:123. 24X Fiche: 50-338, 83/03/23, 8303290457.

R Periodic operating reports & related correspondence

8303080372 Forwards monthly operating repts for Dec 1982.
STEWART, W. L. Virginia Electric & Power Co. 83/01/14. HALLER, N. M. Office of Resource Management, Director. 1p. 17453:307. 24X Fiche: 50-338, 83/01/14, 8303080372.

--8303080379 Monthly operating repts for Dec 1982.
SCHMITENDORF, G. Virginia Electric & Power Co. 83/01/01. 10pp. 17453:308. 24X Fiche: 50-338, 83/01/14, 8303080372.

8303150438 Forwards monthly operating repts for Jan 1983 & corrected monthly operating rept for Nov 1982 for Unit 2.
STEWART, W. L. Virginia Electric & Power Co. 83/02/15. HALLER, N. M. Division of Data Automation & Management Information. 1p. 17562:267. 24X Fiche: 50-338, 83/02/15, 8303150438.

--8303150441 Monthly operating repts for Jan 1983.
SCHMITENDORF, G. Virginia Electric & Power Co. 83/02/01. 9pp. 17562:268. 24X Fiche: 50-338, 83/02/15, 8303150438.

--8303150447 Corrected monthly operating rept for Nov 1982.
SCHMITENDORF, G. Virginia Electric & Power Co. 82/12/01. 1p. 17562:277. 24X Fiche: 50-338, 83/02/15, 8303150438.

8303040475 Forwards "Monitoring of Settlement & Groundwater Level at Svc Water Reservoir, North Anna Power Station Units 1 & 2," 5-yr rept.
STEWART, W. L. Virginia Electric & Power Co. 83/02/24. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 1p. 17372:322. 24X Fiche: 50-338, 83/02/24, 8303040475.

--8303040480 "Monitoring of Settlement & Groundwater Level at Svc Water Reservoir, North Anna Power Station Units 1 & 2," 5-yr rept.
* Virginia Electric & Power Co. 83/02/28. 154pp. 17372:324. 24X Fiche: 50-338, 83/02/24, 8303040475.

S Reportable occurrences, LERs & related correspondence

8302230312 Forwards LER 83-006/03L-0.
CARTWRIGHT, W. R. Virginia Electric & Power Co. 83/02/15. O'REILLY, J. P. Region 2, Office of Director. 1p. 17247:358. 24X Fiche: 50-338, 83/02/15, 8302230312.

--8302230319 LER 83-006/03L-0 on 830125, triaxial peak accelegraphs on RHR HX & safety injection pipe found inoperable from corrosion damage on internal parts. Caused by moisture entering accelegraphs. Units replaced.
CARTWRIGHT, W. R. Virginia Electric & Power Co. 83/02/15. Region 2, Office of Director. 1p. 17247:359. 24X Fiche: 50-338, 83/02/15, 8302230312.

8303010435 Forwards LER 83-004/03L-0.
CARTWRIGHT, W. R. Virginia Electric & Power Co. 83/02/23. O'REILLY, J. P. Region 2, Office of Director. 1p. 17343:062. 24X Fiche: 50-338, 83/02/23, 8303010435.

--8303010444 LER 83-004/03L-0 on 830125, svc water supply valves MOV-SW-1038 & C & discharge valve MOV-SW-104C to recirculation spray HXs would not open. Caused by problems in valve operators. Valves removed & cleaned.
CARTWRIGHT, W. R. Virginia Electric & Power Co. 83/02/23. Region 2, Office of Director. 2pp. 17343:063. 24X Fiche: 50-338, 83/02/23, 8303010435.

8303150217 Forwards LER 83-007/03L-0.
CARTWRIGHT, W. R. Virginia Electric & Power Co. 83/03/04. O'REILLY, J. P. Region 2, Office of Director. 1p. 17568:340. 24X Fiche: 50-338, 83/03/04, 8303150217.

--8303150226 LER 83-007/03L-0 on 830202, during Mode 5, high head safety injection throttle valve found out of alignment by 7/8 of turn. Caused by miscount of valve handle turns during Type C 821109 test or 821108 valve verification procedure.
CARTWRIGHT, W. R. Virginia Electric & Power Co. 83/03/04. Region 2, Office of Director. 3pp. 17568:341. 24X Fiche: 50-338, 83/03/04, 8303150217.

8303180025 Forwards LER 83-009/03L-0.
CARTWRIGHT, W. R. Virginia Electric & Power Co. 83/03/10. O'REILLY, J. P. Region 2, Office of Director. 1p. 17617:355. 24X Fiche: 50-338, 83/03/10, 8303180025.

--8303180030 LER 83-009/03L-0 on 830218, control room operator observed indications of cavitation on RHR pumps A & B. Cause unknown. Pumps secured & vented. No air observed while venting pumps.
CARTWRIGHT, W. R. Virginia Electric & Power Co. 83/03/10. Region 2, Office of Director. 3pp. 17617:356. 24X Fiche: 50-338, 83/03/10, 8303180025.

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8303210722 Forwards IE Insp Repts 50-338/83-02 & 50-339/83-02 on 830110-14 No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/02/17. STEWART, W. L. Virginia Electric & Power Co. 2pp. 17635:137. 24X Fiche: 50-338, 83/02/17, 8303210722.

--8303210730 IE Insp Repts 50-338/83-02 & 50-339/83-02 on 830110-14. No noncompliance noted. Major areas inspected: emergency preparedness.
MARSTON, R. R. Region 2, Office of Director. 83/02/14. 14pp. 17635:139. 24X Fiche: 50-338, 83/02/17, 8303210722.

8303240395 Ack receipt of 820811 & 1209 proposed Rev 8 to security plan. Identified changes unacceptable. Security effectiveness decreased & changes inconsistent w/10CFR50.54. Encls to ltrs withheld (ref 10CFR2.790).
CLARK, R. A. Operating Reactors Branch 3. 83/03/22. STEWART, W. L. Virginia Electric & Power Co. 2pp. 17679:050. 24X
Fiche: 50-338, 83/03/22, 8303240395.

8303300419 Responds to 830202 ltr submitting Rev 9 to security program. Changes consistent w/provisions of 10CFR50.54(p). Encl to ltr withheld (ref 10CFR73.21).
CLARK, R. A. Operating Reactors Branch 3. 83/03/22. STEWART, W. L. Virginia Electric & Power Co. 1p. 17754:016. 24X
Fiche: 50-338, 83/03/22, 8303300419.

8303290457 Forwards IE Safeguards Insp Repts 50-338/83-06 & 50-339/83-06 on 830307-11. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/03/23.
STEWART, W. L. Virginia Electric & Power Co. 2pp. 17725:121. 24X
Fiche: 50-338, 83/03/23, 8303290457.

--8303290485 IE Safeguards Insp Repts 50-338/83-06 & 50-339/83-06 on 830307-11. No noncompliance noted. Major areas inspected: site orientation, physical barriers for protected & vital areas & detection aids. Details withheld (ref 10CFR73.21).
HALL, B. L. Region 2, Office of Director. 83/03/23. 1p. 17725:123. 24X Fiche: 50-338, 83/03/23, 8303290457.

8303290725 Releases public version of revised corporate emergency response plan & implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/23. Document Management Branch. 1p. 17746:219. 24X Fiche: 50-000, 83/03/23, 8303290725.

--8303290732 Forwards public version of Rev 2 to corporate emergency response plan & implementing procedures.
STEWART, W. L. Virginia Electric & Power Co. 83/03/15.
O'REILLY, J. P. Region 2, Office of Director. 1p. 17746:220. 24X
Fiche: 50-000, 83/03/23, 8303290725.

--8303290739 Public version of Rev 2 to corporate emergency response plan.
MARTIN, J. W. Virginia Electric & Power Co. 83/03/11. 72pp. 17746:221. 24X Fiche: 50-000, 83/03/23, 8303290725.

--8303290743 Public version of Rev 2 to corporate plan implementing procedures, including Procedures CPIP-3.0 re administrative svc manager callout/activation, CPIP-3.2 re immediate action items & CPIP-3.3 re message handling. Revised index encl.
* Virginia Electric & Power Co. 83/02/15. 18pp. 17746:292. 24X
Fiche: 50-000, 83/03/23, 8303290725.

G. Adjudicatory correspondence

8303040479 Forwards util 820713 ltr to NRC w/attachments constituting util application to transfer spent fuel from Surry. Attachment 4 requires special treatment & will be sent separately. W/o encl. Related correspondence.
MAUPIN, M. W. Hunton & Williams. MAUPIN, M. W. Virginia Electric & Power Co. 83/03/01. WOLFE, S. J., KLINE, J., FERGUSON, G. A. Atomic Safety and Licensing Board Panel. 2pp. 17373:359. 24X
Fiche: 50-338, 83/03/01, 8303040479.

8303040483 Forwards util 820820 ltr w/attachments constituting util application to expand spent fuel pool. Util 821021 encl ltr corrects info in application. W/o encl. Related correspondence.
MAUPIN, M. W. Hunton & Williams. MAUPIN, M. W. Virginia Electric & Power Co. 83/03/01. WOLFE, S. J., KLINE, J., FERGUSON, G. A. Atomic Safety and Licensing Board Panel. 2pp. 17374:008. 24X
Fiche: 50-338, 83/03/01, 8303040483.

8303040324 Forwards Catawba ASLB 830225 memorandum & order ruling on transshipment issue. W/o encl.
MCGURREN, H. J. Hearing Branch 1. 83/03/02. WOLFE, S. J., FERGUSON, G. A., KLINE, J. Atomic Safety and Licensing Board Panel. 1p. 17421:346. 24X Fiche: 50-338, 83/03/02, 8303040324.

8303100142 Forwards facility licensing info including OLs & amends re expansion of fuel pool capacity & transportation of spent fuel, per ASLB 830218 order memorializing 830216 special prehearing conference. W/o encl.
MCGURREN, H. J. Hearing Branch 1. 83/03/09. WOLFE, S. J., FERGUSON, G. A., KLINE, J. Atomic Safety and Licensing Board Panel. 2pp. 17485:272. 24X Fiche: 50-338, 83/03/09, 8303100142.

H. General correspondence

8303160160 Notifies that EW Harrell will replace WR Cartwright as station manager as of 830318.
STEWART, W. L. Virginia Electric & Power Co. 83/03/10. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 1p. 17596:362. 24X
Fiche: 50-338, 83/03/10, 8303160160.

J. Insurance & indemnity information

8303110207 Forwards Endorsements 42 & 69 to NELIA Policies NF-240 & NF-186, respectively.
WILSON, J. M. Marsh & McLennan, Inc. 83/03/08. DINITZ, I. Antitrust & Economic analysis Branch (Utility Finance). 3pp. 17513:360. 24X
Fiche: 50-000, 83/03/08, 8303110207.

M. Antitrust correspondence

8303140221 Application for amends to Licenses NPF-4 & NPF-7, incorporating Old Dominion Electric Cooperative as potential owner of facility. Indemnity agreements & antitrust info will be provided at later date.
STEWART, W. L. Virginia Electric & Power Co. 83/03/10. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 485pp. 17527:004. 24X Fiche: 50-338, 83/03/10, 8303140221.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303080484 Submits response to draft technical evaluation rept, "Control of Heavy Loads," Item 2.1.8, "Crane Design." Util awaiting final documentation of evaluation due to decrease in staff. Final rept to be provided by 830401.
STEWART, W. L. Virginia Electric & Power Co. 83/03/01. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17452:276. 24X
Fiche: 50-338, 83/03/01, 8303080484.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303100189 Supplemental application for amend to Licenses NPF-4 & NPF-7, proposing Tech Spec changes to delete remaining portions of ETS from 821217 radiological effluent Tech Spec submittal. No addl amend fee required.
STEWART, W. L. Virginia Electric & Power Co. 83/03/03. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 1p. 17485:138. 24X
Fiche: 50-338, 83/03/03, 8303100189.

--8303100191 Proposed Tech Specs, deleting ETS from radiological effluent Tech Specs. Discussion of proposed change encl.
* Virginia Electric & Power Co. 83/03/03. 6pp. 17485:189. 24X
Fiche: 50-338, 83/03/03, 8303100189.

8303100342 Advises of plans for Cycle 3 reload core & transmits core surveillance rept containing specific power distribution limits applicable for Cycle 3 operation.
STEWART, W. L. Virginia Electric & Power Co. 83/03/03. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 5pp. 17488:353. 24X
Fiche: 50-339, 83/03/03, 8303100342.

8303100372 Forwards justification of continued operation of equipment in Category II.B as defined in Franklin Research Ctr draft technical evaluation rept on environ qualification of safety-related electrical equipment, per 830224 request.
STEWART, W. L. Virginia Electric & Power Co. 83/03/03. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 6pp. 17490:326. 24X
Fiche: 50-338, 83/03/03, 8303100372.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303140221 Application for amends to Licenses NPF-4 & NPF-7, incorporating Old Dominion Electric Cooperative as potential owner of facility. Indemnity agreements & antitrust info will be provided at later date.
STEWART, W. L. Virginia Electric & Power Co. 83/03/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director CLARK, R. A. Operating Reactors Branch 3. 485pp. 17527:004 24X
Fiche: 50-338, 83/03/10, 8303140221

8303160198 Requests 60-day extension, until 830509, to respond to Generic Ltr 82-28 re inadequate core cooling instrumentation sys, in order to complete review.
STEWART, W. L. Virginia Electric & Power Co. 83/03/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p. 17596:291 24X
Fiche: 50-000, 83/03/10, 8303160198.

8303180467 Suppls 830303 ltr re containment sump wide-range & narrow-range level transmitters. Wide-range level transmitters for containment sumps replaced on Unit 1. Narrow-range level transmitters will be replaced on Unit 2 during Apr outage.
STEWART, W. L. Virginia Electric & Power Co. 83/03/15 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 17621:251 24X Fiche: 50-338, 83/03/15, 8303180467.

8303310606 Summary of 830310 meeting w/LLL re evaluation of main transformer failures impact on plant. LLL plan on approach to be used in evaluation requested by 830321.
LEE, R. S. Operating Reactors Branch 3 83/03/22 CLARK, R. A. Operating Reactors Branch 3. 4pp. 17780:326 24X
Fiche: 50-338, 83/03/22, 8303310606.

8303280105 Forwards Bechtel Assoc revised "Comparison Between CMAA-70 & EOCI-61," final response to technical evaluation rept, Section 2.1.8 re crane design per NUREG-0612.
STEWART, W. L. Virginia Electric & Power Co. 83/03/23 DENTON, H. R. Office of Nuclear Reactor Regulation, Director CLARK, R. A. Operating Reactors Branch 3. 1p. 17707:007 24X
Fiche: 50-338, 83/03/23, 8303280105.

--8303280110 Revised "Comparison Between CMAA-70 & EOCI-61."
* Bechtel Corp. 83/03/01 4pp. 17707:008 24X
Fiche: 50-338, 83/03/23, 8303280105.

8303280274 Forwards addl info supporting 821208 request to change Cycle 3 fractional power multiplier, per 830315 telcon.
STEWART, W. L. Virginia Electric & Power Co. 83/03/23 DENTON, H. R. Office of Nuclear Reactor Regulation, Director CLARK, R. A. Operating Reactors Branch 3. 2pp. 17706:160 24X
Fiche: 50-339, 83/03/23, 8303280274.

8303300138 Informs that util has decided not to request public hearing on orders for mod of license re qualification of safety-related electrical equipment.
CHRISTMAN, J. N. Hunton & Williams. 83/03/24 EISENHUT, D. G. Division of Licensing. 2pp. 17735:296 24X Fiche: 50-000, 83/03/24, 8303300138.

8303300584 Forwards safety evaluations for environ qualification of safety-related electrical equipment. Justification for continued operation must be submitted by 830520. W/o technical evaluation rept.
CLARK, R. A. Operating Reactors Branch 3 83/03/24 STEWART, W. L. Virginia Electric & Power Co. 3pp. 17766:317 24X
Fiche: 50-338, 83/03/24, 8303300584.

--8303300591 Safety evaluation for environ qualification of safety-related electric equipment. Submission of info providing justification for continued operation required in 30 days.
SHEMANSKI, P. Operating Reactors Branch 3 83/03/24 12pp. 17766:320 24X Fiche: 50-338, 83/03/24, 8303300584.

## O. Inspection reports, IE Bulletins & correspondence

8303010443 Forwards IE Insp Repts 50-338/82-40 & 50-339/82-40 on 821206-830105. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs 83/02/07 STEWART, W. L. Virginia Electric & Power Co. 2pp. 17343:055 24X
Fiche: 50-338, 83/02/07, 8303010443.

--8303010465 IE Insp Repts 50-338/82-40 & 50-339/82-40 on 821206-830105. No noncompliance noted. Major areas inspected: outage activities, surveillance program, plant winterization program, bulletin followup & plant operation.
SHYMLOCK, M. B., JULIAN, C. Division of Project & Resident Programs 83/02/07. 5pp. 17343:057 24X Fiche: 50-338, 83/02/07, 8303010443.

8303210722 Forwards IE Insp Repts 50-338/83-02 & 50-339/83-02 on 830110-14. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs 83/02/17 STEWART, W. L. Virginia Electric & Power Co. 2pp. 17635:137 24X
Fiche: 50-338, 83/02/17, 8303210722.

--8303210730 IE Insp Repts 50-338/83-02 & 50-339/83-02 on 830110-14. No noncompliance noted. Major areas inspected: emergency preparedness.
MARSTON, R. R., JENKINS, G. R. Region 2, Office of Director. 83/02/14 14pp. 17635:139 24X Fiche: 50-338, 83/02/17, 8303210722.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25 Consolidated Edison Co. of New York, Inc. 111pp. 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210523 Forwards response to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Operators reviewed Salem event. Operability tests performed.
STEWART, W. L. Virginia Electric & Power Co. 83/03/04 O'REILLY, J. P. Region 2, Office of Director. 4pp. 17632:219 24X
Fiche: 50-000, 83/03/04, 8303210523.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp. 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp. 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

8303280056 Forwards addl info re IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel)." No evidence of Corbicula infestation noted.
STEWART, W. L. Virginia Electric & Power Co. 83/03/22 DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. JORDAN, E. L. Division of Safeguards & Inspection Programs (Post 830103). 3pp. 17707:288 24X Fiche: 50-338, 83/03/22, 8303280056.

8303290457 Forwards IE Safeguards Insp Repts 50-338/83-06 & 50-339/83-06 on 830307-11. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/03/23.
STEWART, W. L. Virginia Electric & Power Co. 2pp. 17725:121 24X
Fiche: 50-338, 83/03/23, 8303290457.

--8303290485 IE Safeguards Insp Repts 50-338/83-06 & 50-339/83-06 on 830307-11. No noncompliance noted. Major areas inspected: site orientation, physical barriers for protected & vital areas & detection aids. Details withheld (ref 10CFR73.21).
HALL, B. L. Region 2, Office of Director. MCGUIRE, D. R. Division of Emergency Preparedness & Materials Safety. 83/03/23 1p. 17725:123 24X Fiche: 50-338, 83/03/23, 8303290457.

## R. Periodic operating reports & related correspondence

8303080372 Forwards monthly operating repts for Dec 1982.
STEWART, W. L. Virginia Electric & Power Co. 83/01/14 HALLER, N. M. Office of Resource Management, Director 1p. 17453:307 24X
Fiche: 50-338, 83/01/14, 8303080372.

--8303080379 Monthly operating repts for Dec 1982.
SCHMITENDORF, G. Virginia Electric & Power Co. 83/01/01 10pp. 17453:308 24X Fiche: 50-338, 83/01/14, 8303080372.

8303150438 Forwards monthly operating repts for Jan 1983 & corrected monthly operating rept for Nov 1982 for Unit 2.
STEWART, W. L. Virginia Electric & Power Co. 83/02/15 HALLER, N. M. Division of Data Automation & Management Information. 1p. 17562:267 24X Fiche: 50-338, 83/02/15, 8303150438.

--8303150441 Monthly operating repts for Jan 1983.
SCHMITENDORF, G. Virginia Electric & Power Co. 83/02/01 9pp. 17562:268 24X Fiche: 50-338, 83/02/15, 8303150438.

--8303150447 Corrected monthly operating rept for Nov 1982.
SCHMITENDORF, G. Virginia Electric & Power Co. 82/12/01 1p. 17562:277 24X Fiche: 50-338, 83/02/15, 8303150438.

8303040475 Forwards "Monitoring of Settlement & Groundwater Level at Svc Water Reservoir, North Anna Power Station Units 1 & 2." 5-yr rept
STEWART, W. L. Virginia Electric & Power Co. 83/02/24. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 1p. 17372:322. 24X
Fiche: 50-338, 83/02/24, 8303040475

--8303040480 "Monitoring of Settlement & Groundwater Level at Svc Water Reservoir, North Anna Power Station Units 1 & 2." 5-yr rept
* Virginia Electric & Power Co. 83/02/28. 154pp. 17372:324. 24X Fiche: 50-338, 83/02/24, 8303040475.

S. Reportable occurrences, LERs & related correspondence

8302150454 Forwards LER 83-006/03L-0.
CARTWRIGHT, W. Virginia Electric & Power Co. 83/02/02.
O'REILLY, J. P. Region 2, Office of Director. 1p. 17158:148. 24X
Fiche: 50-339, 83/02/02, 8302150454.

--8302150468 LER 83-006/03L-0 on 830106, MOV-RS-2558, recirculation spray pump 2B suction isolation valve failed to reopen after periodic test, rendering 2-RS-P-2B inoperable. Caused by motor operator torquing out from jammed seal cap. Cap reset.
CARTWRIGHT, W. R. Virginia Electric & Power Co. 83/02/02. Region 2, Office of Director. 2pp. 17158:149. 24X Fiche: 50-339, 83/02/02, 8302150454.

8303010594 Forwards LER 83-001/03L-0.
CARTWRIGHT, W. R. Virginia Electric & Power Co. 83/02/18.
O'REILLY, J. P. Region 2, Office of Director. 1p. 17336:088. 24X
Fiche: 50-339, 83/02/18, 8303010594.

--8303010602 LER 83-001/03L-0 on 830123, charging pump 2-CH-P-1C secured from operation during high lube oil temp evaluation on pump speed changer. Caused by faulty temp indicator. Excess oil drained & temp returned to normal. Temp indicator replaced.
CARTWRIGHT, W. R. Virginia Electric & Power Co. 83/02/18. Region 2, Office of Director. 2pp. 17336:089. 24X Fiche: 50-339, 83/02/18, 8303010594.

8303210456 Forwards LER 83-015/03L-0.
CARTWRIGHT, W. R. Virginia Electric & Power Co. 83/02/28.
O'REILLY, J. P. Region 2, Office of Director. 1p. 17634:237. 24X
Fiche: 50-339, 83/02/28, 8303210456.

--8303210465 LER 83-015/03L-0 on 830202, ESF P-12 interlock reset value found out of limit high on one of three channels. Caused by erratic & sensitive potentiometer on comparator card TC-432E. Card replaced.
CARTWRIGHT, W. R. Virginia Electric & Power Co. 83/02/28. Region 2, Office of Director. 2pp. 17634:238. 24X Fiche: 50-339, 83/02/28, 8303210456.

8303210489 Forwards LER 83-007/03L-0.
CARTWRIGHT, W. R. Virginia Electric & Power Co. 83/02/28.
O'REILLY, J. P. Region 2, Office of Director. 1p. 17631:251. 24X
Fiche: 50-339, 83/02/28, 8303210489.

--8303210498 LER 83-007/03L-0 on 830201, svc water supply header to charging pump lube oil coolers & air compressors isolated to repair pinhole leaks. Caused by aggressive water & bacterial reduction of mild steel piping. Piping replaced.
CARTWRIGHT, W. R. Virginia Electric & Power Co. 83/02/28. Region 2, Office of Director. 3pp. 17631:252. 24X Fiche: 50-339, 83/02/28, 8303210489.

8303180342 Forwards LER 83-017/03L-0.
CARTWRIGHT, W. R. Virginia Electric & Power Co. 83/03/10.
O'REILLY, J. P. Region 2, Office of Director. 1p. 17621:044. 24X
Fiche: 50-339, 83/03/10, 8303180342.

--8303180351 LER 83-017/03L-0 on 830215, w/unit at 100% power, one of two series accumulator fill line valves found locked in open position. Caused by personnel error. Responsible operators instructed to follow procedures carefully.
CARTWRIGHT, W. R. Virginia Electric & Power Co. 83/03/10. Region 2, Office of Director. 1p. 17621:045. 24X Fiche: 50-339, 83/03/10, 8303180342.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J. G. Region 3, Office of Director. 83/03/03.
Commonwealth Edison Co. 2pp. 17492:014. 24X Fiche: 50-000, 83/03/03, 8303100364.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 5ipp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303210336 Informs that plant-unique calculations per Generic Ltr 83-08, "Mod of Vacuum Breakers in Mark I Containments," provided in B21109 ltr.
TAUBER, H. Detroit Edison Co. 83/03/16. YOUNGBLOOD, B. J. Licensing Branch 1. 1p. 17634:162. 24X Fiche: 50-341, 83/03/16, 8303210336.

8303250099 Forwards two oversize drawings confirming applicability of GE B21119 ltr re low-low set logic/lowered MSIV for Mark I plants. FSAR change will be updated to include mods. Aperture cards are available in PDR.
TAUBER, H. Detroit Edison Co. 83/03/16. YOUNGBLOOD, B. J. Licensing Branch 1. 2pp. 17692:069. 24X Fiche: 50-341, 83/03/16, 8303250099.

8303290680 Forwards request for addl info re proposed inservice testing program for safety-related pumps & valves.
YOUNGBLOOD, B. J. Licensing Branch 1. 83/03/16. TAUBER, H. Detroit Edison Co. 12pp. 17745:122. 24X Fiche: 50-341, 83/03/16, 8303290680.

8303290714 Requests review of safety-related sys to determine whether GE switch, Type 2940 & Marathon 600 series terminal blocks installed or will be installed. Proposed approach for resolving matter required.
YOUNGBLOOD, B. J. Licensing Branch 1. 83/03/16. TAUBER, H. Detroit Edison Co. 2pp. 17746:316. 24X Fiche: 50-341, 83/03/16, 8303290714.

E. NRC Safety Evaluation Report (SER), suppls & correspondence

830308000! Forwards table comparing pertinent sections of SER to current fire protection design. Review of SER revealed inconsistencies between SER & actual design. Comments & justification for differences or changes indicated.
TAUBER, H. Detroit Edison Co. 83/03/01. YOUNGBLOOD, B. J. Licensing Branch 1. 30pp. 17454:313. 24X Fiche: 50-341, 83/03/01, 8303080001.

F. Security, medical, emergency & fire protection plans

8303080001 Forwards table comparing pertinent sections of SER to current fire protection design. Review of SER revealed inconsistencies between SER & actual design. Comments & justification for differences or changes indicated.
TAUBER, H. Detroit Edison Co. 83/03/01. YOUNGBLOOD, B. J. Licensing Branch 1. 30pp. 17454:313. 24X Fiche: 50-341, 83/03/01, 8303080001.

8303210608 Forwards IE Insp Rept 50-341/83-03 on 830201-04. No noncompliance noted.
PAPERIELLO, C. J. Region 3, Office of Director. 83/03/02. WELLS, D. A. Detroit Edison Co. 2pp. 17636:292. 24X Fiche: 50-341, 83/03/02, 8303210608.

--8303210614 IE Insp Rept 50-341/83-03 on 830201-04. No noncompliance noted. Major areas inspected: organization & staffing, training, radiation protection procedures, facilities, instruments, equipment, bulletins & circulars.
HUETER, L. J., GREGER, L. R. Region 3, Office of Director. 83/03/02. 6pp. 17636:294. 24X Fiche: 50-341, 83/03/02, 8303210608.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director. 83/03/22. Commonwealth Edison Co. 2pp. 17690:316. 24X Fiche: 50-000, 83/03/22, 8303240440.

G. Adjudicatory correspondence

8303010248 Order extending time until 830304 for Commission to act to review ALAB-709.
CHILK, S. J. Office of the Secretary of the Commission 83/02/14
Commissioners 1p 17335:352 24X Fiche 50-341, 83/02/14,
8303010248.

8303010259 Order extending time until 830304 for Commission to act to review ALAB-707.
CHILK, S. J. Office of the Secretary of the Commission 83/02/18
Commissioners 1p 17335:135 24X Fiche 50-341, 83/02/18,
8303010259.

8303110233 Advises that time for Commission to review ALAB-707 expired. Commission declined review. Decision became final agency action on 830304.
CHILK, S. J. Office of the Secretary of the Commission 83/03/10
Detroit Edison Co 1p 17520:117 24X Fiche 50-341, 83/03/10,
8303110233.

8303110235 Advises that time for Commission to review ALAB-709 expired. Commission declined review. Decision became final agency action on 830304.
CHILK, S. J. Office of the Secretary of the Commission 83/03/10
Detroit Edison Co 1p 17520:114 24X Fiche 50-341, 83/03/10,
8303110235.

8303150357 Forwards NRR Director ltr informing Monroe County, MI that County petition re offsite emergency plans will be treated as 10CFR2.206 request. W/o encl.
WOODHEAD, C. P. Hearing Branch 1 83/03/11 PERRY, S. Federal Emergency Management Agency 1p 17566:246 24X
Fiche 50-341, 83/03/11, 8303150357.

8303170382 Brief opposing Citizens for Employment & Energy 821108 exceptions & 830209 brief supporting exceptions to ASLB 821029 initial decision. Assertions re Monroe County emergency plans moot. Certificate of Svc encl.
VOIGT, H. H. Detroit Edison Co. VOIGT, H. H. Wolverine Electric Cooperative VOIGT, H. H. LeBoeuf, Lamb, Leiby & MacRae 83/03/16
Atomic Safety and Licensing Appeal Panel 21pp 17609:282 24X
Fiche 50-341, 83/03/16, 8303170382.

8303290016 Response opposing Citizens for Employment & Energy 821108 appeal of ASLB 821029 initial decision. Status of Monroe County, MI emergency plan irrelevant. Certificate of Svc encl.
WOODHEAD, C. P. Hearing Branch 1 83/03/28 Atomic Safety and Licensing Appeal Panel 23pp 17722:314 24X Fiche 50-341,
83/03/28, 8303290016.

8303310307 Order scheduling 830504 oral argument in Bethesda, MD to hear Citizens for Employment & Energy appeal from ASLB 821029 initial decision. ASLAB secretary should be notified by 830425 of person presenting oral argument.
SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 83/03/30
2pp 17755:049 24X Fiche 50-341, 83/03/30, 8303310307.

H. General correspondence

8303090295 Forwards 830301 statement presented to FEMA & State of MI on recovery & re-entry responsibilities. Items to be addressed include communication needs, financial concerns of Monroe County & evacuation routes for Stoney Point & Estral Beach.
WESTOVER, A. T. Monroe County, MI 83/03/02 DENTON, H. R. Office of Nuclear Reactor Regulation; Director 8pp 17473:158 24X
Fiche 50-341, 83/03/02, 8303090295.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X
Fiche 50-000, 83/02/16, 8302170082.

Q. Inspection reports, IE Bulletins & correspondence

8303030759 Board Notification 83-19 forwards IE Insp Rept 50-341/82-14 re deficiencies in electrical const area.
NOVAK, T. M. Division of Licensing 83/02/18 Atomic Safety and Licensing Appeal Panel 5pp 17363:234 24X Fiche 50-341, 83/02/18,
8303030759.

8303080072 Responds to IE Bulletin 82-04 re electrical penetration assemblies. No Bunker-Ramo electrical penetration assemblies in use at facility. Facility uses electrical containment penetrations mfg by Conax Corp.
WELLS, D. A. Detroit Edison Co 83/03/16 KEPPLER, J. G. Region 3, Office of Director 2pp 17457:121 24X Fiche 50-341, 83/02/18,
8303080072.

8303110355 Board Notification 83-14 forwards followup info on apparent deficiencies in Midland-Ross superstrut matl.
EISENHUT, D. G. Division of Licensing 83/02/18 PALLADINO, N.
Commissioners 24pp 17546:205 24X Fiche 50-000, 83/02/18,
8303110355.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc.
11lpp 17521:001 24X Fiche 50-000, 83/02/25, 8212060367.

8303030656 Clarifies NRC position re procedures for admitting NRC personnel to facilities. Lists of NRC inspectors & personnel likely to visit facility two or more times per yr & at anytime encl. Lists will be updated every 6 months.
KEPPLER, J. G. Region 3, Office of Director 83/02/28 WELLS, D. A.
Detroit Edison Co 6pp 17414:039 24X Fiche 50-341, 83/02/28,
8303030656.

8303210608 Forwards IE Insp Rept 50-341/83-03 on 830201-04. No noncompliance noted.
PAPERIELLO, C. J. Region 3, Office of Director 83/03/02 WELLS, D. A.
Detroit Edison Co 2pp 17636:292 24X Fiche 50-341, 83/03/02,
8303210608.

--8303210614 IE Insp Rept 50-341/83-03 on 830201-04. No noncompliance noted. Major areas inspected: organization & staffing, training, radiation protection procedures, facilities, instruments, equipment, bulletins & circulars.
HUETER, L. J.; GREGER, L. R. Region 3, Office of Director 83/03/02
6pp 17636:294 24X Fiche 50-341, 83/03/02, 8303210608.

8303240456 Forwards IE Insp Rept 50-341/83-01 on 830105-0201. No noncompliance noted.
LITTLE, W. S. Region 3, Office of Director 83/03/10 WELLS, D. A.
Detroit Edison Co. 2pp 17678:067 24X Fiche 50-341, 83/03/10,
8303240456.

--8303240460 IE Insp Rept 50-341/83-01 on 830105-0201. No noncompliance noted. Major areas inspected: preoperational test procedure review & implementation & control of configuration of equipment after turnover for testing.
REIMANN, F. W.; REYES, L. A. Region 3, Office of Director 83/03/07
8pp 17678:069 24X Fiche 50-341, 83/03/10, 8303240456.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc.
117pp 17611:070 24X Fiche 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche 50-000, 83/03/18, 8212060383.

8303220183 Ack receipt of 830222 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/82-21. Item 82-04-01 will remain open until NUS corrective action complete.
PAPERIELLO, C. J. Region 3, Office of Director 83/03/18 WELLS, D. A.
Detroit Edison Co. 1p 17656:359 24X Fiche 50-341, 83/03/18,
8303220183.

--8303220184 Responds to NRC 830121 ltr re violations noted in IE Insp Rept 50-341/82-21. Corrective actions: repts associated w/ terrestrial monitoring program will be made available in final form within 3 months of ltr date.
WELLS, D. A. Detroit Edison Co. 83/02/22 HIND, J. A. Region 3, Office of Director 3pp 17656:360 24X Fiche 50-341, 83/03/18,
8303220183.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp 17774:352 24X Fiche 50-000, 83/03/21, 8212060387.

S Reportable occurrences, LERs & related correspondence

8303010631 Amends 830114 Final Deficiency Rept 82 to interim deficiency rept re questionable QC acceptance of pipe hanger installations. Final rept will be issued when actions in 821210 ltr complete. Rept expected by 830630.
WELLS, D. A. Detroit Edison Co. 83/02/10. KEPPLER, J. G. Region 3, Office of Director. 1p. 17336:122. 24X Fiche: 50-341, 83/02/10, 8303010631.

8303150620 Board Notification 83-26: Forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys. Info may affect conclusions re probability of/corrective measures for ATWS.
EISENHUT, D. G. Division of Licensing. 83/03/03. PALLADINO, N. Commissioners. 24pp. 17584:097. 24X Fiche: 50-000, 83/03/03, 8303150620.

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303070094 Responds to Generic Ltr 83-01 re number of estimated candidates for operator licensing exams. Number of candidates for each exam through 1985 listed.
TAUBER, H. Detroit Edison Co. 83/02/28. YOUNGBLOOD, B. J. Licensing Branch 1. 1p. 17434:324. 24X Fiche: 50-341, 83/02/28, 8303070094.

DOCKET 50-344 TROJAN NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

8303040583 Forwards IE Insp Rept 50-344/83-04 on 830110-0204. No noncompliance noted.
STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 83/02/16. WITHERS, B. D. Portland General Electric Co. 2pp. 17374:273. 24X Fiche: 50-344, 83/02/16, 8303040583.

--8303040600 IE Insp Rept 50-344/83-04 on 830110-0204. No noncompliance noted. Major areas inspected: plant operations, surveillance testing, maint, security, new fuel receipt & followup on previous insp items.
MALMROS, M. H. Region 5, Office of Director. DODDS, R. T. Division of Resident, Reactor Project & Engineering Programs. 83/02/15. 6pp. 17374:275. 24X Fiche: 50-344, 83/02/16, 8303040583.

8303150230 Forwards revised findings & determination for facility. No significant deficiencies in emergency plan identified.
DONOVAN, R. W. Federal Emergency Management Agency. 83/03/07. TRAMMELL, C. NRC - No Detailed Affiliation Given. 20pp. 17551:168. 24X Fiche: 50-344, 83/03/07, 8303150230.

8303180051 Requests remittance of Class III fee for 810319 request for exemption from certain App R requirements. Exemption from fee requirements per 10CFR170.22 granted.
MILLER, W. O. License Fee Management Branch. 83/03/14. WITHERS, B. D. Portland General Electric Co. 1p. 17625:257. 24X Fiche: 50-344, 83/03/14, 8303180051.

8303300384 Forwards Amend 79 to License NPF-1 & notice of issuance & availability. Amend revises frequency for audits of emergency & security plans to at least once per 12 months.
TRAMMELL, C. M. Operating Reactors Branch 3. 83/03/15. WITHERS, B. D. Portland General Electric Co. 4pp. 17754:273. 24X Fiche: 50-344, 83/03/15, 8303300384.

--8303300388 Amend 79 to License NPF-1, revising frequency for audits of emergency & security plans to at least once per 12 months.
CLARK, R. A. Operating Reactors Branch 3. 83/03/15. 4pp. 17754:277. 24X Fiche: 50-344, 83/03/15, 8303300384.

--8303300393 Notice of issuance & availability of Amend 79 to License NPF-1.
CLARK, R. A. Operating Reactors Branch 3. 83/03/15. 2pp. 17754:281. 24X Fiche: 50-344, 83/03/15, 8303300384.

8303290215 Discusses US/IAEA Safeguards Agreement. Util will assist IAEA in making required measurements. Util also understands IAEA wishes addl exam to verify serial numbers of 30% of spent fuel assemblies.
WITHERS, B. D. Portland General Electric Co. 83/03/23. CLARK, R. A. Operating Reactors Branch 3. 2pp. 17722:240. 24X Fiche: 50-344, 83/03/23, 8303290215.

J Insurance & indemnity information

8303230034 Forwards Endorsement 59 to NELIA Policy NF-225.
JOHANSEN, E. Portland General Electric Co. 83/03/15. SALTZMAN, J. Assistant Director for State & Licensee Relations. 2pp. 17665:039. 24X Fiche: 50-344, 83/03/15, 8303230034.

P Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 10pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303090218 Supplis radiation shielding review per NUREG-0737, Item II.B.2, "Plant Shielding." Revised emergency instructions implemented. Functional Restoration Instruction C-1 will be revised. Restriction on access to auxiliary bldg unnecessary.
WITHERS, B. D. Portland General Electric Co. 83/03/04. EISENHUT, D. G. Division of Licensing. 2pp. 17492:132. 24X Fiche: 50-344, 83/03/04, 8303090218.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303[illegible]068 Forwards IAEA 830217 ltr containing procedures for measuring enrichment of fresh & irradiated fuel, per request. W/o ltr.
CLARK, R. A. Operating Reactors Branch 3. 83/03/08. WITHERS, B. D. Portland General Electric Co. 22pp. 17694:176. 24X Fiche: 50-344, 83/03/08, 8303240068.

8303240082 Forwards review of Westinghouse rept, "Dropped Rod Methodology for Negative Flux Rate Trip Plants." Analytical methods in Westinghouse rept acceptable substitute for operating restrictions.
CLARK, R. A. Operating Reactors Branch 3. 83/03/09. WITHERS, B. D. Portland General Electric Co. 12pp. 17694:113. 24X Fiche: 50-344, 83/03/09, 8303240082.

8303220456 Forwards order confirming commitments to implement NUREG-0737 post-TMI items scheduled for completion on or after 810701. Order based on commitments contained in ltrs responding to Generic Ltrs 82-05 & 82-10.
CLARK, R. A. Operating Reactors Branch 3. 83/03/14. WITHERS, B. D. Portland General Electric Co. 3pp. 17670:114. 24X Fiche: 50-344, 83/03/14, 8303220456.

--8303220462 Order confirming licensee commitments to implement & maintain post-TMI items per responses to Generic Ltrs 82-05 & 82-10.
PURPLE, R. A. Division of Licensing. 83/03/14. Portland General Electric Co. 11pp. 17670:117. 24X Fiche: 50-344, 83/03/14, 8303220456.

8303300384 Forwards Amend 79 to License NPF-1 & notice of issuance & availability. Amend revises frequency for audits of emergency & security plans to at least once per 12 months.
TRAMMELL, C. M. Operating Reactors Branch 3. 83/03/15. WITHERS, B. D. Portland General Electric Co. 4pp. 17754:273. 24X Fiche: 50-344, 83/03/15, 8303300384.

--8303300388 Amend 79 to License NPF-1, revising frequency for audits of emergency & security plans to at least once per 12 months.
CLARK, R. A. Operating Reactors Branch 3. 83/03/15. 4pp. 17754:277. 24X Fiche: 50-344, 83/03/15, 8303300384.

--8303300393 Notice of issuance & availability of Amend 79 to License NPF-1.
CLARK, R. A. Operating Reactors Branch 3. 83/03/15. 2pp. 17754:281. 24X Fiche: 50-344, 83/03/15, 8303300384.

8303240236 Responds to Generic Ltr 82-28 re design & schedular info for instrumentation to detect inadequate core cooling. Westinghouse reactor vessel level instrumentation sys installed & currently undergoing testing & data collection. WITHERS, B. D. Portland General Electric Co. 83/03/18. EISENHUT, D. G. Division of Licensing. 19pp. 17680:036. 24X Fiche: 50-344, 83/03/18, 8303240236.

8303280189 Comments on Generic Ltr 83-11 re licensee qualification for performing safety analyses in support of licensing actions. Proposed user qualification package will not serve intended goals for code proficiency. WITHERS, B. D. Portland General Electric Co. 83/03/21. EISENHUT, D. G. Division of Licensing. 2pp. 17706:314. 24X Fiche: 50-344, 83/03/21, 8303280189.

Q. Inspection reports, IE Bulletins & correspondence

8303040357 Forwards IE Insp Rept 50-344/83-02 on 830117-20. No noncompliance noted. BOOK, H. E. Division of Radiological Safety & Safeguards Program. 83/02/15. WITHERS, B. D. Portland General Electric Co. 2pp. 17420:046. 24X Fiche: 50-344, 83/02/15, 8303040357.

--8303040362 IE Insp Rept 50-344/83-02 on 830117-20. No noncompliance noted. Major areas inspected: lab QC program & independent confirmatory measurements involving Region V mobile lab. HAMADA, G., TEMPLE, G., WENSLAWSKI, F. A. Division of Radiological Safety & Safeguards Program. 83/02/14. 1p. 17420:048. 24X Fiche: 50-344, 83/02/15, 8303040357.

8303040436 Forwards IE Insp Rept 50-344/83-03 on 830131-0204. No noncompliance noted. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 83/02/16. WITHERS, B. D. Portland General Electric Co. 2pp. 17370:286. 24X Fiche: 50-344, 83/02/16, 8303040436.

--8303040446 IE Insp Rept 50-344/83-03 on 830131-0204. No noncompliance noted. Major areas inspected: surveillance & calibr programs, followup on previous insp findings & independent insp. WILLETT, D. J., DODDS, R. T. Division of Resident, Reactor Project & Engineering Programs. 83/02/15. 4pp. 17370:288. 24X Fiche: 50-344, 83/02/16, 8303040436.

8303040583 Forwards IE Insp Rept 50-344/83-04 on 830110-0204. No noncompliance noted. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 83/02/16. WITHERS, B. D. Portland General Electric Co. 2pp. 17374:273. 24X Fiche: 50-344, 83/02/16, 8303040583.

--8303040600 IE Insp Rept 50-344/83-04 on 830110-0204. No noncompliance noted. Major areas inspected: plant operations, surveillance testing, maint, security, new fuel receipt & followup on previous insp items. MALMROS, M. H. Region 5, Office of Director. DODDS, R. T. Division of Resident, Reactor Project & Engineering Programs. 83/02/15. 6pp. 17374:275. 24X Fiche: 50-344, 83/02/16, 8303040583.

8303010588 Advises that no Bunker-Ramo electrical penetrations using hard epoxy module design installed or planned to be installed in safety-related sys, in response to IE Bulletin 82-04. BROEHL, D. J. Portland General Electric Co. 83/02/18. ENGELKEN, R. H. Region 5, Office of Director. 2pp. 17336:139. 24X Fiche: 50-344, 83/02/18, 8303010588.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11ipp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303080437 Forwards requests for exemption from inservice insp requirements of Section XI of ASME Boiler & Pressure Vessel Code, per 10CFR50.55a(g). Encl requests constitute Class III exemption request. WITHERS, B. D. Portland General Electric Co. 83/03/03. CLARK, R. A. Operating Reactors Branch 3. 8pp. 17454:243. 24X Fiche: 50-344, 83/03/03, 8303080437.

8303290456 Forwards IE Insp Rept 50-344/83-05 on 830207-11 & notice of violation. BOOK, H. E. Region 5, Office of Director. 83/03/03. WITHERS, B. D. Portland General Electric Co. 2pp. 17726:001. 24X Fiche: 50-344, 83/03/03, 8303290456.

--8303290460 Notice of violation from insp on 830207-11. WENSLAWSKI, F. A. Region 5, Office of Director. 83/03/03. 1p. 17726:003. 24X Fiche: 50-344, 83/03/03, 8303290456.

--8303290463 IE Insp Rept 50-344/83-05 on 830207-11. Noncompliance noted: failure to verify performance & qualifications of facility staff. CILLIS, M., WENSLAWSKI, F. A., BOOK, H. E. Region 5, Office of Director. 83/03/03. 11pp. 17726:004. 24X Fiche: 50-344, 83/03/03, 8303290456.

8303150553 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Maint Procedure MP-1-9 in conformance w/bulletin for lubricant applied to trip mechanism. WITHERS, B. D. Portland General Electric Co. 83/03/08. ENGELKEN, R. H. Region 5, Office of Director. 2pp. 17568:116. 24X Fiche: 50-344, 83/03/08, 8303150553.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060382 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche: 50-000, 83/03/18, 8212060382.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 12ipp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

R. Periodic operating reports & related correspondence

8303080313 Forwards monthly operating rept for Dec 1982. YUNDT, C. P. Portland General Electric Co. 83/01/10. Office of Resource Management, Director. 1p. 17449:330. 24X Fiche: 50-344, 83/01/10, 8303080313.

--8303080321 Monthly operating rept for Dec 1982. KENT, G. J. Portland General Electric Co. 83/01/10. 4pp. 17449:331. 24X Fiche: 50-344, 83/01/10, 8303080313.

8303150489 Forwards monthly operating rept for Jan 1983. YUNDT, C. D. Portland General Electric Co. 83/02/16. Office of Resource Management, Director. 1p. 17560:329. 24X Fiche: 50-344, 83/02/16, 8303150489.

--8303150502 Monthly operating rept for Jan 1983. KAMMEYER, D. J. Portland General Electric Co. 83/02/08. 4pp. 17560:330. 24X Fiche: 50-344, 83/02/16, 8303150489.

8303110238 Forwards Annual Rept for 1982. WITHERS, B. D. Portland General Electric Co. 83/03/01. ENGELKEN, R. H. Region 5, Office of Director. 1p. 17519:001. 24X Fiche: 50-344, 83/03/01, 8303110238.

--8303110243 "Annual Rept for 1982." Portland General Electric Co. PGE-1015-82. 83/03/01. 190pp. 17519:002. 24X Fiche: 50-344, 83/03/01, 8303110238.

S. Reportable occurrences, LERs & related correspondence

8303110330 Forwards LER 83-002/03L-0. Detailed event analysis encl. YUNDT, C. P. Portland General Electric Co. 83/02/16. ENGELKEN, R. H. Region 5, Office of Director. 3pp. 17512:335. 24X Fiche: 50-344, 83/02/16, 8303110330.

--8303110335 LER 83-002/03L-0 on 830122, while in Mode 2, ESF auxiliary feedwater pumps secured following auto start from hi-hi steam generator level main feedwater trip. Caused by personnel misinterpretation of procedure. BAIR, G. G. Portland General Electric Co. 83/02/16. Region 5, Office of Director. 3pp. 17512:338. 24X Fiche: 50-344, 83/02/16, 8303110330.

8303110390 NPDES noncompliance notification on 830125, 262 to 900 lbs oil discharged to Columbia River from oil/water separator exceeding NPDES limit. Caused by high flow rate into turbine bldg sump due to pump drainage. Plant procedures revised. YUNDT, C. P. Portland General Electric Co. 83/02/23. ENGELKEN, R. H. Region 5, Office of Director. 1p. 17506:242. 24X Fiche: 50-344, 83/02/23, 8303110390.

8303110108 RO: on 830203, diesel fire pump removed from svc to perform functional testing of newly installed batteries. Testing verified that NFPA Section 8-2.2 met. Diesel fire pump returned to svc on 830215.
YUNDT, C. P. Portland General Electric Co. 83/03/01 ENGELKEN, R. H. Region 5, Office of Director. 1p. 17517:326. 24X Fiche: 50-344, 83/03/01, 8303110108.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303220087 Discusses util inservice testing program relief requests. Disagrees w/significant number of relief requests & some EG&G recommendations. Safety evaluation schedule extended to 830630.
NORELIUS, C. E. Division of Project & Resident Programs 83/03/18
EISENHUT, D. G. Division of Licensing 1p. 17649:272. 24X Fiche: 50-346, 83/03/18, 8303220087.

F. Security, medical, emergency & fire protection plans

8303040635 Advises of completion of review of Rev 6 to emergency plan. Plan meets 10CFR50.47(b) stds & App E to 10CFR50 requirements.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 83/02/28 CROUSE, R. P. Toledo Edison Co. 1p. 17368:347. 24X Fiche: 50-346, 83/02/28, 8303040635.

8303090374 Releases public version of revised emergency plan supporting procedure rev index.
FELTON, J. M. Division of Rules and Records 83/03/02 Document Management Branch. 1p. 17484:123. 24X Fiche: 50-346, 83/03/02, 8303090374.

--8303090401 Forwards public version of Rev 166 to emergency plan supporting procedure rev index.
* Toledo Edison Co. 83/02/03 Office of Nuclear Reactor Regulation, Director. 2pp. 17484:124. 24X Fiche: 50-346, 83/03/02, 8303090374.

--8303090405 Public version of Rev 166 to emergency plan supporting procedure rev index.
* Toledo Edison Co. 83/02/28 1p. 17484:126. 24X Fiche: 50-346, 83/03/02, 8303090374.

8303150072 Forwards NRC memos presenting positions re instrumentation required & allowable repairs for alternative shutdown per App R to 10CFR50. Memos should be used to assist in evaluating readiness for audit.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/02. CROUSE, R. P. Toledo Edison Co. 3pp. 17584:354. 24X Fiche: 50-346, 83/03/02, 8303150072.

--8208040524 Forwards position statement re allowable repairs for alternative shutdown & App R requirements for time required to achieve cold shutdown. Licensee should have capability of repairing equipment & achieving cold shutdown within 72-h.
MATTSON, R. J. Division of Systems Integration (post 811005) 82/07/02 VOLLMER, R. H. Division of Engineering. 3pp. 17584:357. 24X Fiche: 50-346, 83/03/02, 8303150072.

--8302010011 Forwards staff position that monitoring of source range flux, reactor coolant temps & steam generator pressure is necessary to comply w/Section III.L of 10CFR50, App R re alternative shutdown capability. Instrumentation list encl.
RUBENSTEIN, L. S. Assistant Director for Core & Plant Systems. 83/01/07. MATTSON, R. J. Division of Systems Integration (post 811005). 5pp. 17584:359. 24X Fiche: 50-346, 83/03/02, 8303150072.

8303220379 Releases public version of revised Administrative Memorandum 42-19.
FELTON, J. M. Division of Rules and Records 83/03/16 Document Management Branch. 1p. 17673:118. 24X Fiche: 50-346, 83/03/16, 8303220379.

--8303220381 Forwards public version of revised Administrative Memorandum 42-19 re radiation monitoring teams. Revised rev index encl.
* Toledo Edison Co. 83/03/08 NRC - No Detailed Affiliation Given. 2pp. 17673:119. 24X Fiche: 50-346, 83/03/16, 8303220379.

--8303220385 Public version of revised Administrative Memorandum 42-19 re radiation monitoring teams.
MURRAY, T. D. Toledo Edison Co. 83/02/28. 1p. 17673:121. 24X Fiche: 50-346, 83/03/16, 8303220379.

8303290031 Forwards Amend 56 to License NPF-3 & notice of issuance & availability. Amend includes requirement to maintain guard training & qualification plan.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/17. CROUSE, R. P. Toledo Edison Co. 4pp. 17729:297. 24X Fiche: 50-346, 83/03/17, 8303290031.

--8303290037 Amend 56 to License NPF-3, including requirement to maintain guard training & qualification plan.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/17. 2pp. 17729:301. 24X Fiche: 50-346, 83/03/17, 8303290031.

--8303290041 Notice of issuance & availability of Amend 56 to License NPF-3.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/17. 2pp. 17729:303. 24X Fiche: 50-346, 83/03/17, 8303290031.

8303250105 Releases public version of revised emergency plan administrative procedure.
FELTON, J. M. Division of Rules and Records 83/03/21 Document Management Branch. 1p. 17710:052. 24X Fiche: 50-346, 83/03/21, 8303250105.

--8303250109 Forwards public version of Rev 5 to Emergency Plan Administrative Procedure AD 1850.04, "Post-Accident Radiological Sampling & Counting." Receipt form encl.
* Toledo Edison Co. 83/03/04 NRC - No Detailed Affiliation Given. 1p. 17710:053. 24X Fiche: 50-346, 83/03/21, 8303250105.

--8303250124 Public version of Rev 5 to Emergency Plan Administrative Procedure AD 1850.04, "Post-Accident Radiological Sampling & Counting." Revised index encl.
BRIDEN, D. W. Toledo Edison Co. 83/02/28. 24pp. 17710:054. 24X Fiche: 50-346, 83/03/21, 8303250105.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director. 83/03/22. Commonwealth Edison Co. 2pp. 17690:316. 24X Fiche: 50-000, 83/03/22, 8303240440.

8303280192 Ack receipt of 830225 ltr providing objectives & guidelines for 1983 annual exercise. Site assembly info w/accountability & actual demonstration of collecting & analyzing post-accident sample recommended.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 83/03/22. CROUSE, R. P. Toledo Edison Co. 1p. 17709:187. 24X Fiche: 50-346, 83/03/22, 8303280192.

--8303280197 Forwards objectives & guidelines for 1983 annual exercise.
CROUSE, R. P. Toledo Edison Co. 83/02/25. KEPPLER, J. G. Region 3, Office of Director. 5pp. 17709:188. 24X Fiche: 50-346, 83/03/22, 8303280192.

8303300058 Releases public version of rev to emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 83/03/23 Document Management Branch. 1p. 17754:145. 24X Fiche: 50-346, 83/03/23, 8303300058.

8303310001 Releases public version of revised emergency plan supporting procedures rev index.
FELTON, J. M. Division of Rules and Records 83/03/25 Document Management Branch. 1p. 17777:360. 24X Fiche: 50-346, 83/03/25, 8303310001.

--8303310002 Forwards public version of Rev 171 to emergency plan supporting procedures rev index.
Toledo Edison Co. 83/03/11 Office of Nuclear Reactor Regulation, Director. 1p. 17777:361. 24X Fiche: 50-346, 83/03/25, 8303310001.

--8303310003 Public version of Rev 171 to emergency plan supporting procedures rev index.
* Toledo Edison Co. 83/03/31 1p. 17777:362. 24X Fiche: 50-346, 83/03/25, 8303310001.

8303300695 Releases public version of rev to emergency plan supporting procedures index.
FELTON, J. M. Division of Rules and Records 83/03/28 Document Management Branch. 1p. 17767:270. 24X Fiche: 50-346, 83/03/28, 8303300695.

--8303300701 Forwards public version of Rev 167 to emergency plan supporting procedures index Receipt form encl.
* Toledo Edison Co. 83/03/01 Office of Nuclear Reactor Regulation, Director 1p 17764:271 24X Fiche:50-346,83/03/28, 8303300695.

--8303300707 Public version of Rev 167 to emergency plan supporting procedures index.
* Toledo Edison Co. 83/03/31 1p 17764:272 24X Fiche:50-346,83/03/28,8303300695.

8303310006 Releases public version of revised emergency plan supporting procedures rev index.
FELTON,J.M. Division of Rules and Records 83/03/28 Document Management Branch 1p 17780:253 24X Fiche:50-346,83/03/28, 8303310006.

--8303310007 Forwards public version of Rev 170 to emergency plan supporting procedures rev index.
* Toledo Edison Co. 83/03/09 Office of Nuclear Reactor Regulation, Director 1p 17780:254 24X Fiche:50-346,83/03/28, 8303310006.

--8303310008 Public version of Rev 170 to emergency plan supporting procedures rev index.
* Toledo Edison Co. 83/03/31 1p 17780:255 24X Fiche:50-346,83/03/28,8303310006.

H. General correspondence

8303140008 Responds to 821124 ltr to Senator Glenn re plant safety. Funding for const & operation of plant is entirely through private sources.
DENTON,H.R. Office of Nuclear Reactor Regulation, Director 83/03/03 SPEHAR,S. Affiliation Unknown 4pp 17549:225 24X Fiche:50-346,83/03/03,8303140008.

--8303140011 Forwards constituent S Spehar 821124 ltr on plant safety, for response.
GLENN,J. Senate 83/02/04 KAMMERER,C. Office of Congressional Affairs 3pp 17548:228 24X Fiche:50-346,83/03/03,8303140008.

M. Antitrust correspondence

8303140007 Requests advice re DOJ position on need for imposition of civil penalty against util for alleged failure to comply w/antitrust license conditions.
RUTBERG,J. Hearing Branch 2 83/03/03 CUTLER,M. Justice, Dept of 2pp 17540:123 24X Fiche:50-000,83/03/03,8303140007.

P. Operating license stage documents & correspondence

8302170446 Forwards SER re environ qualification of safety-related electrical equipment. Justifications for continued operation for listed items requested within 30 days of ltr receipt.
STOLZ,J.F. Operating Reactors Branch 4 83/02/08 CROUSE,R.P. Toledo Edison Co. 3pp 17205:129 24X Fiche:50-346,83/02/08, 8302170446.

--8302170451 SER re environ qualification of safety-related electrical equipment.
* Equipment Qualification Branch 83/02/08 5pp 17205:132 24X Fiche:50-346,83/02/08,8302170446.

--8301170075 Vols 1 & 2 to nonproprietary "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60), Davis-Besse Nuclear Power Station Unit 1."
TOMAN,G.J.; PANDEY,Q.; CARFAGNO,S. Franklin Institute/Franklin Research Center NRC-03-79-118 TER-C5257-505 83/01/11
SHEMANSKI,P. NRC - No Detailed Affiliation Given 1,372pp 66557:263 24X Fiche:50-346,83/02/08,8302170446.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl.
EISENHUT,D.G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X Fiche:50-000,83/02/16,8302170082.

8303040101 Requests util assessment of operability of large-diameter Pratt purge & vent valves & intentions to maintain valves sealed closed per SRP & to verify valves closed every 31 days. Response requested within 15 days of receipt of ltr.
STOLZ,J.F. Operating Reactors Branch 4 83/02/16 CROUSE,R.P. Toledo Edison Co. 5pp 17424:345 24X Fiche:50-346,83/02/16, 8303040101.

8303020385 Forwards Amend 53 to License NPF-3, safety evaluation & notice of issuance & availability. Amend modifies Tech Specs to delete safety-related snubber 33A-GCB-4-HS.
DEAGAZIO,A.W. Operating Reactors Branch 4 83/02/17 CROUSE,R.P. Toledo Edison Co. 3pp 17357:331 24X Fiche:50-346,83/02/17, 8303020385.

--8303020392 Amend 53 to License NPF-3, modifying Tech Specs to delete safety-related snubber 33A-GCB-4-HS to be replaced w/sway strut.
STOLZ,J.F. Operating Reactors Branch 4 83/02/17 5pp 17357:334 24X Fiche:50-346,83/02/17,8303020385.

--8303020397 Safety evaluation supporting Amend 53 to License NPF-3.
* Office of Nuclear Reactor Regulation, Director 83/02/17 2pp 17357:338 24X Fiche:50-346,83/02/17,8303020385.

--8303020416 Notice of issuance & availability of Amend 53 to License NPF-3.
STOLZ,J.F. Operating Reactors Branch 4 83/02/17 2pp 17357:340 24X Fiche:50-346,83/02/17,8303020385.

8303020413 Forwards Amend 54 to License NPF-3, safety evaluation & notice of issuance & availability. Amend eliminates requirement for 30-day written repts under certain conditions & clarifies RCS surveillance requirements.
DEAGAZIO,A.W. Operating Reactors Branch 4 83/02/17 CROUSE,R.P. Toledo Edison Co. 3pp 17357:308 24X Fiche:50-346,83/02/17, 8303020413.

--8303020417 Amend 54 to License NPF-3, eliminating requirement for 30-day written repts under certain conditions & clarifying surveillance requirement re RCS pressure isolation valves.
STOLZ,J.F. Operating Reactors Branch 4 83/02/17 6pp 17357:311 24X Fiche:50-346,83/02/17,8303020413.

--8303020435 Safety evaluation supporting Amend 54 to License NPF-3.
* Office of Nuclear Reactor Regulation, Director 83/02/17 3pp 17357:317 24X Fiche:50-346,83/02/17,8303020413.

--8303020437 Notice of issuance & availability of Amend 54 to License NPF-3.
STOLZ,J.F. Operating Reactors Branch 4 83/02/17 2pp 17357:320 24X Fiche:50-346,83/02/17,8303020413.

8303030398 Forwards Amend 52 to License NPF-3, safety evaluation, technical evaluation & notice of issuance & availability. Amend permits defeat of essential bus feeder breaker undervoltage trip when starting certain pumps.
DEAGAZIO,A.W. Operating Reactors Branch 4 83/02/17 CROUSE,R.P. Toledo Edison Co. 4pp 17419:275 24X Fiche:50-346,83/02/17, 8303030398.

--8303030409 Amend 52 to License NPF-3, permitting defeat of essential bus feeder breaker undervoltage trips for up to 1 minute when starting reactor coolant or circulating water pump.
STOLZ,J.F. Operating Reactors Branch 4 83/02/17 11pp 17419:278 24X Fiche:50-346,83/02/17,8303030398.

--8303030522 Safety evaluation supporting Amend 52 to License NPF-3.
* Office of Nuclear Reactor Regulation, Director 83/02/17 6pp 17419:287 24X Fiche:50-346,83/02/17,8303030398.

--8211050147 Rev 1 to "Adequacy of Station Electric Distribution Sys Voltages for Davis Besse Nuclear Power Station," technical evaluation rept.
WHITE,R.L. Lawrence Livermore Laboratory FIN A-0250 UCID-19114 R01 82/09/27 NRC - No Detailed Affiliation Given 13pp 17419:293 24X Fiche:50-346,83/02/17,8303030398.

--8303030424 Notice of issuance & availability of Amend 52 to License NPF-3.
STOLZ,J.F. Operating Reactors Branch 4 83/02/17 2pp 17419:306 24X Fiche:50-346,83/02/17,8303030398.

8303010698 Notification of 830118 meeting w/B&W Owners Group & B&W in Bethesda,MD to discuss plans in developing study re frequency & severity of potential pressurized thermal shock events applicable to all B&W plants.
VISSING,G. Operating Reactors Branch 4 83/02/18 STOLZ,J. Operating Reactors Branch 4 3pp 17348:334 24X Fiche:50-000,83/02/18,8303010698.

8303030329 Lists info needed to consider granting exemption extending reactor vessel head vent requirement implementation deadline. Response schedule due in 15 days.
EISENHUT,D.G. Division of Licensing 83/02/22 CROUSE,R.P. Toledo Edison Co. 4pp 17365:125 24X Fiche:50-346,83/02/22,8303030329.

8303100128 Requests commitment by 830308 that all persons in operational chain at site will receive training per NUREG-0737, Item II.B.4, "Training for Mitigating Core Damage," or request meeting on why training unnecessary. STOLZ, J.F. Operating Reactors Branch 4. 83/02/25. CROUSE, R.P. Toledo Edison Co. 3pp. 17496:144. 24X Fiche: 50-346, 83/02/25, 8303100128.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl. EISENHUT, D.G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys. KEPPLER, J.G. Region 3, Office of Director. 83/03/03. Commonwealth Edison Co. 2pp. 17492:014. 24X Fiche: 50-000, 83/03/03, 8303100364.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl. EISENHUT, D.G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303170136 Summary of 830223 meeting w/B&W Regulatory Response Group in Bethesda, MD re small break LOCA procedures & maintaining proper steam generator water level. VAN VLIET, J. Operating Reactors Branch 4. 83/03/08. Operating Reactors Branch 4. 43pp. 17615:224. 24X Fiche: 50-000, 83/03/08, 8303170136.

8303150432 Provides addl info per NRC 830222 request re exemption request to extend implementation date of vessel head vent test. Integral sys test to demonstrate removal of noncondensable gases included in test matrix. CROUSE, R.P. Toledo Edison Co. 83/03/09. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 17561:150. 24X Fiche: 50-346, 83/03/09, 8303150432.

8303160098 Summary of 830127 meeting w/utils, Bechtel, B&W & Shaw, Pittman, Potts & Trowbridge re extension requests concerning NRC 821210 order for mod of licenses for inadequate core cooling instrumentation. Viewgraphs encl. MINER, S. Operating Reactors Branch 4. 83/03/09. Operating Reactors Branch 4. 9pp. 17614:323. 24X Fiche: 50-000, 83/03/09, 8303160098.

8303150252 Responds to NRC 830208 ltr re safety-related electrical equipment. Justification for continued operation encl. CROUSE, R.P. Toledo Edison Co. 83/03/10. STOLZ, J.F. Operating Reactors Branch 4. 164pp. 17555:218. 24X Fiche: 50-346, 83/03/10, 8303150252.

8303150427 Responds to NRC 830110 ltr re TMI Item II.E.1.2, "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication." Surveillance requirements will be revised by 830430 to allow functional test on output relay contacts. CROUSE, R.P. Toledo Edison Co. 83/03/11. STOLZ, J.F. Operating Reactors Branch 4. 3pp. 17561:169. 24X Fiche: 50-346, 83/03/11, 8303150427.

8303150499 Advises that due to administrative error, util unable to meet 830310 due date for responding to 821210 order to provide design info & schedules on inadequate core cooling instrumentation. Response will be provided by 830322. CROUSE, R.P. Toledo Edison Co. 83/03/11. EISENHUT, D.G. Division of Licensing. 1p. 17560:348. 24X Fiche: 50-346, 83/03/11, 8303150499.

8303210012 Forwards Amend 55 to License NPF-3 & notice of issuance & availability. Amend deletes ETS re nonradiological water quality-related requirements. STOLZ, J.F. Operating Reactors Branch 4. 83/03/11. CROUSE, R.P. Toledo Edison Co. 5pp. 17660:054. 24X Fiche: 50-346, 83/03/11, 8303210012.

--8303210050 Amend 55 to License NPF-3, deleting ETS re nonradiological water quality-related requirements. STOLZ, J.F. Operating Reactors Branch 4. 83/03/11. 10pp. 17660:059. 24X Fiche: 50-346, 83/03/11, 8303210012.

--8303210055 Notice of issuance & availability of Amend 55 to License NPF-3. STOLZ, J.F. Operating Reactors Branch 4. 83/03/11. 2pp. 17660:069. 24X Fiche: 50-346, 83/03/11, 8303210012.

8303220073 Forwards response to 830131 ltr re safety features actuation sys shared power supply returns. Permanent grounding of power supply commons to instrument ground will be provided to resolve channel independence issue. CROUSE, R.P. Toledo Edison Co. 83/03/11. STOLZ, J.F. Operating Reactors Branch 4. 4pp. 17652:198. 24X Fiche: 50-346, 83/03/11, 8303220073.

8303220150 Responds to NRC 830225 ltr re training for station superintendent. Station superintendent will receive training for mitigating core damage beginning 830314. CROUSE, R.P. Toledo Edison Co. 83/03/14. STOLZ, J.F. Operating Reactors Branch 4. 1p. 17658:249. 24X Fiche: 50-346, 83/03/14, 8303220150.

8303280336 Forwards order confirming licensee commitments to implement post-TMI-related actions contained in NUREG-0737, based on util responses to Generic Ltrs 82-05 & 82-10. STOLZ, J.F. Operating Reactors Branch 4. 83/03/14. CROUSE, R.P. Toledo Edison Co. 2pp. 17713:107. 24X Fiche: 50-346, 83/03/14, 8303280336.

--8303280343 Order confirming licensee commitments on post-TMI-related issues. PURPLE, R.A. Assistant Director for Licensing. 83/03/14. Toledo Edison Co. 10pp. 17713:110. 24X Fiche: 50-346, 83/03/14, 8303280336.

8303280350 Responds to 830117 ltr re NRC order on NUREG-0737, Item II.F.2, "Inadequate Core Cooling." Util request for extension until 830415 to evaluate alternative approach to reactor vessel head monitoring approved. EISENHUT, D.G. Division of Licensing. 83/03/14. CROUSE, R.P. Toledo Edison Co. 8pp. 17713:093. 24X Fiche: 50-346, 83/03/14, 8303280350.

8303180634 Advises that response to 830208 SER re environ qualification of safety-related electrical equipment not due until 830520. STOLZ, J.F. Operating Reactors Branch 4. 83/03/15. CROUSE, R.P. Toledo Edison Co. 2pp. 17626:306. 24X Fiche: 50-346, 83/03/15, 8303180634.

8303300733 Summary of 830303 meeting w/utils, B&W Owners Group & Natl Nuclear Corp in Bethesda, MD re plans concerning frequency & severity of pressurized thermal shock events for B&W plants. Viewgraphs encl. VISSING, G.S. Operating Reactors Branch 4. 83/03/15. Operating Reactors Branch 4. 174pp. 17765:013. 24X Fiche: 50-000, 83/03/15, 8303300733.

8303220155 Responds to NRC 830216 ltr requesting response to questions re Pratt butterfly valves used to purge or vent containment. Mechanical restrictions installed to limit valve opening to 55 degrees in one train & 65 degrees in second train. CROUSE, R.P. Toledo Edison Co. 83/03/16. STOLZ, J.F. Operating Reactors Branch 4. 3pp. 17639:024. 24X Fiche: 50-346, 83/03/16, 8303220155.

8303220058 Forwards explanation on how DHR redundancy assured in Mode 3 operation, in response to NRC 830201 ltr. Tech Specs will be revised to include applicable limits by 830513. CROUSE, R.P. Toledo Edison Co. 83/03/17. STOLZ, J.F. Operating Reactors Branch 4. 3pp. 17652:168. 24X Fiche: 50-346, 83/03/17, 8303220058.

8303290031 Forwards Amend 56 to License NPF-3 & notice of issuance & availability. Amend includes requirement to maintain guard training & qualification plan. STOLZ, J.F. Operating Reactors Branch 4. 83/03/17. CROUSE, R.P. Toledo Edison Co. 4pp. 17729:297. 24X Fiche: 50-346, 83/03/17, 8303290031.

--8303290037 Amend 56 to License NPF-3, including requirement to maintain guard training & qualification plan. STOLZ, J.F. Operating Reactors Branch 4. 83/03/17. 2pp. 17729:301. 24X Fiche: 50-346, 83/03/17, 8303290031.

--8303290041 Notice of issuance & availability of Amend 56 to License NPF-3. STOLZ, J.F. Operating Reactors Branch 4. 83/03/17. 2pp. 17729:303. 24X Fiche: 50-346, 83/03/17, 8303290031.

8303300004 Informs that review of addl info submitted 821222 re secondary water chemistry monitoring & control program acceptable. Safety evaluation encl. STOLZ, J.F. Operating Reactors Branch 4. 83/03/18. CROUSE, R.P. Toledo Edison Co. 2pp. 17751:286. 24X Fiche: 50-346, 83/03/18, 8303300004.

--8303300007 Safety evaluation supporting util secondary chemistry monitoring & control program. * Office of Nuclear Reactor Regulation, Director. 83/03/18. 4pp. 17751:288. 24X Fiche: 50-346, 83/03/18, 8303300004.

8303240496 Responds to Generic Ltr 83-10 re resolution of TMI Action Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps." Extension to 830701 requested for submittal of schedule for resolution of issue.
CROUSE,R.P. Toledo Edison Co. 83/03/21. EISENHUT,D.G. Division of Licensing. 1p. 17678:093. 24X Fiche:50-346,83/03/21,8303240496.

8303290393 Forwards response to NRC 830126 request for addl info re proposed change to Tech Spec 3.2.5 concerning flow/thermal power setpoint. Proposed Tech Spec is conservative in terms of min DNBR.
CROUSE,R.P. Toledo Edison Co. 83/03/21. STOLZ,J.F. Operating Reactors Branch 4. 17pp. 17726:234. 24X Fiche:50-346,83/03/21,8303290393.

8303280030 Forwards response to NRC 821210 order to install inadequate core cooling instrumentation sys per NUREG-0737, Item II.F.2.Hot leg level measurement sys will be installed during 1984 refueling outage.
CROUSE,R.P. Toledo Edison Co. 83/03/23. EISENHUT,D.G. Division of Licensing. 17pp. 17707:194. 24X Fiche:50-346,83/03/23,8303280030.

8303300394 Responds to 830217 ltr forwarding safety evaluation of Amend 52 to License NPF-3.Voltages will be recorded while starting largest non-Class IE 4.16-kV motor.Tests supersede previous commitment & complete requirements of 790808 & 830217 ltrs.
CROUSE,R.P. Toledo Edison Co. 83/03/23. DEAGAZIO,A.W. Operating Reactors Branch 4. 4pp. 17731:009. 24X Fiche:50-346,83/03/23,8303300394.

8303310551 Notification of 830407 meeting w/B&W Owners Group in Bethesda,MD to review progress,schedules & typical event analyses re study of pressurized thermal shock.
VISSING,G.S. Operating Reactors Branch 4. 83/03/25. STOLZ,J.F. Operating Reactors Branch 4. 2pp. 17780:360. 24X
Fiche:50-000,83/03/25,8303310551.

G. Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11pp. 17521:001. 24X Fiche:50-000,83/02/25,8212060367.

8303030461 Clarifies NRC position re procedures for admitting NRC personnel to facility.Site orientation re issuance of badges,escort duties & emergency evacuation for personnel listed in Encls 1 & 2 requested.
KEPPLER,J.G. Region 3, Office of Director. 83/02/28. CROUSE,R.P. Toledo Edison Co. 6pp. 17409:270. 24X Fiche:50-346,83/02/28,8303030461.

8303080047 Advises that no Bunker-Ramo electrical penetration assemblies utilizing hard epoxy module design installed or planned to be installed,per IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies."
CROUSE,R.P. Toledo Edison Co. 83/02/28. DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement. 1p. 17454:353. 24X
Fiche:50-346,83/02/28,8303080047.

8303080223 Confirms plans discussed at 830218 meeting to conduct 830309 enforcement conference in Oak Harbor,OH to discuss recent insp findings in areas of equipment maint & operability.
NORELIUS,C.E. Division of Project & Resident Programs. 83/02/28.
CROUSE,R.P. Toledo Edison Co. 1p. 17439:291. 24X
Fiche:50-346,83/02/28,8303080223.

8303150274 Responds to IE Bulletin 83-01, "Failure of Westinghouse DB-50 Reactor Trip Breakers to Open on Automatic Trip Signal." No Westinghouse DB-50 breakers used at facility.
CROUSE,R.P. Toledo Edison Co. 83/03/07. KEPPLER,J.G. Region 3, Office of Director. 2pp. 17567:164. 24X Fiche:50-346,83/03/07,8303150274.

8303240586 Forwards IE Insp Rept 50-346/83-01 during Jan 1983 & notice of violation.
NORELIUS,C.E. Division of Project & Resident Programs. 83/03/08.
CROUSE,R.P. Toledo Edison Co. 2pp. 17683:102. 24X
Fiche:50-346,83/03/08,8303240586.

--8303240589 Notice of violation from insp during Jan 1983.
* Region 3, Office of Director. 83/03/08. 3pp. 17683:104. 24X
Fiche:50-346,83/03/08,8303240586.

--8303240594 IE Insp Rept 50-346/83-01 during Jan 1983.Noncompliance noted:failure to identi[illegible]ocument & handle nonconformances, to adequately test & to follow procedures.
PEEBLES,T.A., ROGERS,W.G., JACKIW,I.N. Region 3, Office of Director. 83/03/07. 12pp. 17683:107. 24X Fiche:50-346,83/03/08,8303240586.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070. 24X Fiche:50-000,83/03/11,8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche:50-000,83/03/18,8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 12?pp. 17774:352. 24X Fiche:50-000,83/03/21,8212060387.

8303290380 Responds to IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers," dtd 830311.Channel functional test of reactor trip module logic & control rod trip breaker performed satisfactorily on 830314.
CROUSE,R.P. Toledo Edison Co. 83/03/24. DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement. 3pp. 17718:096. 24X
Fiche:50-346,83/03/24,8303290380.

R. Periodic operating reports & related correspondence

8303080165 Forwards monthly operating rept for Dec 1982.
MURRAY,T.D. Toledo Edison Co. 83/01/07. HALLER,N. Division of Data Automation & Management Information. 1p. 17457:250. 24X
Fiche:50-346,83/01/07,8303080165.

--8303080170 Monthly operating rept for Dec 1982.
SARSOUR,B. Toledo Edison Co. 83/01/07. 5pp. 17457:251. 24X
Fiche:50-346,83/01/07,8303080165.

8303150498 Forwards monthly operating rept for Jan 1983.
MURRAY,T.D. Toledo Edison Co. 83/02/08. HALLER,N. Office of Resource Management, Director. 1p. 17560:256. 24X
Fiche:50-346,83/02/08,8303150498.

--8303150504 Monthly operating rept for Jan 1983.
SARSOUR,B. Toledo Edison Co. 83/02/08. 6pp. 17560:257. 24X
Fiche:50-346,83/02/08,8303150498.

8303170362 Forwards "Semiannual Radioactive Liquid & Gaseous Release Rept,Davis-Besse Nuclear Power Station Unit 1,Jul-Dec 1982."
MURRAY,T.D. Toledo Edison Co. 83/02/14. KEPPLER,J.G. Region 3, Office of Director. 1p. 17609:333. 24X Fiche:50-346,83/02/14,8303170362.

--8303170366 "Semiannual Radioactive Liquid & Gaseous Release Rept, Davis-Besse Nuclear Power Station Unit 1,Jul-Dec 1982."
* Toledo Edison Co. 83/02/14. 85pp. 17609:334. 24X
Fiche:50-346,83/02/14,8303170362.

S. Reportable occurrences, LERs & related correspondence

8303020413 Forwards Amend 54 to License NPF-3,safety evaluation & notice of issuance & availability.Amend eliminates requirement for 30-day written repts under certain conditions & clarifies RCS surveillance requirements.
DEAGAZIO,A.W. Operating Reactors Branch 4. 83/02/17. CROUSE,R.P. Toledo Edison Co. 3pp. 17357:308. 24X Fiche:50-346,83/02/17,8303020413.

--8303020417 Amend 54 to License NPF-3,eliminating requirement for 30-day written repts under certain conditions & clarifying surveillance requirement re RCS pressure isolation valves.
STOLZ,J.F. Operating Reactors Branch 4. 83/02/17. 6pp. 17357:311. 24X Fiche:50-346,83/02/17,8303020413.

--8303020435 Safety evaluation supporting Amend 54 to License NPF-3.
* Office of Nuclear Reactor Regulation, Director. 83/02/17. 3pp. 17357:317. 24X Fiche:50-346,83/02/17,8303020413.

--8303020437 Notice of issuance & availability of Amend 54 to License NPF-3.
STOLZ,J.F. Operating Reactors Branch 4. 83/02/17. 2pp. 17357:320. 24X Fiche:50-346,83/02/17,8303020413.

8303080478 Forwards LER 83-006/03L-0.
MURRAY,T.D. Toledo Edison Co. 83/02/25. KEPPLER,J.G. Region 3, Office of Director. 1p. 17452:294. 24X Fiche:50-346,83/02/25,8303080478.

--8303080494 LER 83-006/03L-0 on 830126, door 311, auxiliary bldg southeast stairway at 585-ft level, found open Caused by failure of closure mechanism due to normal wear Closure mechanism replaced.
WOLFE, R. Toledo Edison Co. 83/02/25 Region 3, Office of Director. 2pp. 17452:295. 24X Fiche: 50-346, 83/02/25, 8303080478.

8303080518 Forwards LER 83-005/03L-0.
MURRAY, T. D. Toledo Edison Co. 83/02/25. KEPPLER, J. G. Region 3, Office of Director. 1p. 17450:305. 24X Fiche: 50-346, 83/02/25, 8303080518.

--8303080522 LER 83-005/03L-0 on 830127, acceptance criteria of containment airlock seal leakage surveillance test ST 5061.05 did not agree w/Tech Spec surveillance requirements Caused by procedure deficiency.
LANG, T. Toledo Edison Co. 83/02/25 Region 3, Office of Director. 3pp. 17450:306. 24X Fiche: 50-346, 83/02/25, 8303080518.

8303140528 Forwards LER 83-007/03L-0.
MURRAY, T. D. Toledo Edison Co. 83/03/01. KEPPLER, J. G. Region 3, Office of Director. 1p. 17534:178. 24X Fiche: 50-346, 83/03/01, 8303140528.

--8303140540 LER 83-007/03L-0 on 830131, loss of 120-volt ac essential bus Y1 experienced Pressurizer level indication from LT-RC-14-3 lost Loss of Y1 caused by failure of YV1 inverter input fuse Root cause unknown.
YARGER, K. Toledo Edison Co. 83/03/01 Region 3, Office of Director. 3pp. 17534:179. 24X Fiche: 50-346, 83/03/01, 8303140528.

8303140409 Forwards LER 83-008/03L-0.
MURRAY, T. D. Toledo Edison Co. 83/03/03. KEPPLER, J. G. Region 3, Office of Director. 1p. 17542:231. 24X Fiche: 50-346, 83/03/03, 8303140409.

--8303140429 LER 83-008/03L-0 on 830127, batteries 2P pilot cell 18 & 1P pilot cell 33 specific gravity & battery 1N pilot cell 18 voltage read low Caused by stringent Tech Specs Batteries recharged.
UEBBING, R. Toledo Edison Co. 83/03/03. Region 3, Office of Director. 3pp. 17542:232. 24X Fiche: 50-346, 83/03/03, 8303140409.

8303170442 Forwards LER 83-010/03L-0.
MURRAY, T. D. Toledo Edison Co. 83/03/08. KEPPLER, J. G. Region 3, Office of Director. 1p. 17610:335. 24X Fiche: 50-346, 83/03/08, 8303170442.

--8303170449 LER 83-010/03L-0 on 830207, during performance of auxiliary feedwater sys channel functional test, isolation valve MS106A failed to close electrically Caused by dirty & improperly lubricated valve stem Valve stem & drive nut cleaned.
LONG, J. Toledo Edison Co. 83/03/08 Region 3, Office of Director. 2pp. 17610:336. 24X Fiche: 50-346, 83/03/08, 8303170442.

8303170522 Forwards LER 83-009/03L-0.
MURRAY, T. D. Toledo Edison Co. 83/03/08. KEPPLER, J. G. Region 3, Office of Director. 1p. 17611:016. 24X Fiche: 50-346, 83/03/08, 8303170522.

--8303170526 LER 83-009/03L-0 on 830207, during performance of miscellaneous valves Quarterly Test ST 5099.08, containment isolation valve CV5010D Failed to close electrically Caused by failure of torque switch close contacts Switch replaced.
LONG, J. Toledo Edison Co. 83/03/08. Region 3, Office of Director. 2pp. 17611:017. 24X Fiche: 50-346, 83/03/08, 8303170522.

8303210358 Forwards LER 83-011/03L-0.
MURRAY, T. D. Toledo Edison Co. 83/03/11. KEPPLER, J. G. Region 3, Office of Director. 1p. 17636:023. 24X Fiche: 50-346, 83/03/11, 8303210358.

--8303210362 LER 83-011/03L-0 on 830211, auxiliary feedwater pump turbine 2 overspeed trip alarm sounded Caused by personnel error. Personnel bumped turbine overspeed trip linkage causing trip of trip throttle valve when removing case guards.
THOMPSON, T. Toledo Edison Co. 83/03/11 Region 3, Office of Director. 2pp. 17636:024. 24X Fiche: 50-346, 83/03/11, 8303210358.

8303240474 Forwards LER 83-012/01L-0.
MURRAY, T. D. Toledo Edison Co. 83/03/17. KEPPLER, J. G. Region 3, Office of Director. 1p. 17678:024. 24X Fiche: 50-346, 83/03/17, 8303240474.

--8303240493 LER 83-012/01L-0 on 830303, current practice of requiring one ECCS room cooler valved into svc in each room determined less conservative than SAR assumptions Caused by lack of procedural control for non-Tech Spec equipment.
RICHTER, L. Toledo Edison Co. 83/03/17. Region 3, Office of Director. 3pp. 17678:023. 24X Fiche: 50-346, 83/03/17, 8303240474.

V. Operator Examinations

8303010430 Requests exam for three senior reactor operators & three fuel handling senior reactor operators during wk of 830613, in response to Generic Ltr 83-01 Exams tentatively planned for First Quarter 1984.
CROUSE, R. P. Toledo Edison Co. 83/02/22. EISENHUT, D. G. Division of Licensing. 1p. 17343:271. 24X Fiche: 50-346, 83/02/22, 8303010430.

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-348 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8303110102 Forwards description of scope of annual emergency plan exercise schedule for 830209, in response to NRC 820129 request Detailed description of exercise scenario & anticipated licensee actions will be submitted by 821226.
CLAYTON, F. L. Alabama Power Co. 82/08/27. STOHR, J. P. Region 2, Office of Director. 5pp. 17517:327. 24X Fiche: 50-348, 82/08/27, 8303110102.

8302070360 Application for amend to Licenses NPF-2 & NPF-8, proposing changes to Tech Spec 3/4.3.3.4 to incorporate backup tower into Tables 3.3-8 & 4.3-5 re allowable meteorological monitoring instrumentation Safety evaluation encl.
CLAYTON, F. L. Alabama Power Co. 83/01/24. VARGA, S. A. Office of Nuclear Reactor Regulation, Director. 4pp. 17030:001. 24X Fiche: 50-348, 83/01/24, 8302070360.

--8302070362 Proposed Tech Spec Tables 3.3-8 & 4.3-5 re meteorological monitoring instrumentation.
* Alabama Power Co. 83/01/24. 5pp. 17030:005. 24X Fiche: 50-348, 83/01/24, 8302070360.

8303090191 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17484:127. 24X Fiche: 50-348, 83/03/02, 8303090191.

--8303090199 Forwards public version of Rev 10 to Emergency Plan Implementing Procedure FNP-0-EIP-4 re chemistry & health physics support to emergency plan & Rev 11 to FNP-0-EIP-9 re radiation exposure estimates & emergency classification.
HUDSPETH, J. B. Alabama Power Co. 83/02/09. Office of Nuclear Reactor Regulation, Director. 1p. 17484:128. 24X Fiche: 50-348, 83/03/02, 8303090191.

--8303090207 Public version of Rev 10 to Emergency Plan Implementing Procedure FNP-0-EIP-4 re chemistry & health physics support to emergency plan & Rev 11 to FNP-0-EIP-9 re radiation exposure estimates & emergency classification.
* Alabama Power Co. 83/02/08. 6pp. 17484:129. 24X Fiche: 50-348, 83/03/02, 8303090191.

8303090369 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17484:147. 24X Fiche: 50-348, 83/03/02, 8303090369.

--8303090375 Forwards public version of Rev 2 to Emergency Plan Implementing Procedure GO-EIP-111 re corporate activation & notification procedures & Rev 2 to GO-EIP-112 re emergency mobile communications.
CLAYTON, F. L. Alabama Power Co. 83/02/02. VARGA, S. A. Assistant Director for Operating Reactors. 1p. 17484:148. 24X Fiche: 50-348, 83/03/02, 8303090369.

--8303090377 Public version of Rev 2 to Emergency Plan Implementing Procedure GO-EIP-111 re corporate activation & notification procedures & Rev 2 to GO-EIP-112 re emergency mobile communications.
MCGOWAN, J. K. Alabama Power Co. 83/02/03. 47pp. 17484:149. 24X Fiche: 50-348, 83/03/02, 8303090369.

8303100402 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17502:210. 24X Fiche: 50-348, 83/03/02, 8303100402.

--8303100407 Forwards public version of revised emergency plan implementing procedures, including Procedures FNP-O-EIP-15 re emergency drills & FNP-O-EIP-4 re chemistry & health physics support to emergency plan.
HUDSPETH, J. B. Alabama Power Co. 83/02/02. Office of Nuclear Reactor Regulation, Director. 1p. 17502:211. 24X
Fiche: 50-348, 83/03/02, 8303100402.

--8303100410 Public version of revised emergency plan implementing procedures, including Procedures FNP-O-EIP-15 re emergency drills & FNP-O-EIP-4 re chemistry & health physics support to emergency plan.
* Alabama Power Co. 83/02/02. 148pp. 17502:212. 24X
Fiche: 50-348, 83/03/02, 8303100402.

8303210502 Forwards SALP rept for Jul 1981 - Jul 1982. Further NRC review necessary to address util comments re mischaracterization of fire protection issues.
O'REILLY, J. P. Region 2, Office of Director. 83/03/09.
MCDONALD, R. P. Alabama Power Co. 3pp. 17631:188. 24X
Fiche: 50-348, 83/03/09, 8303210502.

--8303210532 Forwards SALP board assessment for Jul 1981 - Jul 1982. Comments due in 20 days.
LEWIS, R. C. Division of Project & Resident Programs. 82/12/06.
MCDONALD, R. P. Alabama Power Co. 2pp. 17631:191. 24X
Fiche: 50-348, 83/03/09, 8303210502.

--8303210539 SALP Repts 50-348/82-28 & 50-364/82-28 for Jul 1981 - Jul 1982.
* Region 2, Office of Director. 83/03/09. 20pp. 17631:193. 24X
Fiche: 50-348, 83/03/09, 8303210502.

--8303210546 Requests closure & removal of issues re 10CFR50, App R, Sections H & K.3, from SALP Repts 50-348/82-28 & 50-364/82-28.
CLAYTON, F. L. Alabama Power Co. 82/12/21. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17631:219. 24X Fiche: 50-348, 83/03/09, 8303210502.

8303230415 Releases public version of rev to emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/16. Document Management Branch. 1p. 17674:172. 24X Fiche: 50-348, 83/03/16, 8303230415.

--8303230418 Forwards public version of Rev 11 to Emergency Plan Implementing Procedure FNP-O-EIP-10, "Evacuation & Personnel Accountability." Receipt form encl.
HUDSPETH, J. B. Alabama Power Co. 83/02/24. Office of Nuclear Reactor Regulation, Director. 2pp. 17674:173. 24X
Fiche: 50-348, 83/03/16, 8303230415.

--8303230423 Public version of Rev 11 to Emergency Plan Implementing Procedure FNP-O-EIP-10, "Evacuation & Personnel Accountability."
* Alabama Power Co. 83/02/22. 11pp. 17674:175. 24X
Fiche: 50-348, 83/03/16, 8303230415.

8303240107 Releases public version of memo & request form voiding emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/21. Document Management Branch. 1p. 17700:290. 24X Fiche: 50-348, 83/03/21, 8303240107.

--8303240112 Forwards public version of memo & procedure request form voiding FNP-O-EIP-20, "Recovery - Emergency Operations Facility," per Administrative Procedure FNP-O-AP-4, "Control of Plant Documents & Records."
HUDSPETH, J. B. Alabama Power Co. 83/03/07. Office of Nuclear Reactor Regulation, Director. 5pp. 17700:291. 24X
Fiche: 50-348, 83/03/21, 8303240107.

## J. Insurance & indemnity information

8303010299 Requests prorated refund for each unit from effective zero indemnification date of 821125 through end of term for each indemnity fee prepaid. Refund justification page encl.
MCDONALD, R. P. Alabama Power Co. 83/02/17. SALTZMAN, J. Assistant Director for State & Licensee Relations. 2pp. 17333:336. 24X
Fiche: 50-348, 83/02/17, 8303010299.

8303010232 Forwards Endorsements 49 & 50 & 41 & 42 to NELIA Policy NF-238 & MAELU Policy MF-93, respectively.
DUCK, J. R. Marsh & McLennan, Inc. 83/02/22. SALTZMAN, J. Assistant Director for State & Licensee Relations. 6pp. 17333:356. 24X
Fiche: 50-348, 83/02/22, 8303010232.

8303290431 Forwards Endorsement 51 to NELIA Policy NF-238.
DUCK, J. R. Marsh & McLennan, Inc. 83/03/15. SALTZMAN, J. Assistant Director for State & Licensee Relations. 2pp. 17725:325. 24X
Fiche: 50-348, 83/03/15, 8303290431.

## P. Operating license stage documents & correspondence

8302070360 Application for amend to Licenses NPF-2 & NPF-8, proposing changes to Tech Spec 3/4.3.3.4 to incorporate backup tower into Tables 3.3-8 & 4.3-5 re allowable meteorological monitoring instrumentation. Safety evaluation encl.
CLAYTON, F. L. Alabama Power Co. 83/01/24. VARGA, S. A. Office of Nuclear Reactor Regulation, Director. 4pp. 17030:001. 24X
Fiche: 50-348, 83/01/24, 8302070360.

--8302070362 Proposed Tech Spec Tables 3.3-8 & 4.3-5 re meteorological monitoring instrumentation.
* Alabama Power Co. 83/01/24. 5pp. 17030:005. 24X
Fiche: 50-348, 83/01/24, 8302070360.

8302170032 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303030195 Forwards Amend 29 to License NPF-2, safety evaluation & notice of issuance & availability. Amend modifies Tech Specs to extend fourth fuel outage cold shutdown to 96 h.
REEVES, E. A. Operating Reactors Branch 1. 83/02/17. CLAYTON, F. L. Alabama Power Co. 2pp. 17365:245. 24X Fiche: 50-348, 83/02/17, 8303030195.

--8303030199 Amend 29 to License NPF-2, modifying Tech Specs to extend fourth refueling outage cold shutdown from 30 h to 96 h, for one time only.
VARGA, S. A. Operating Reactors Branch 1. 83/02/17. 4pp. 17365:247. 24X Fiche: 50-348, 83/02/17, 8303030195.

--8303030205 Safety evaluation supporting Amend 29 to License NPF-2.
* Office of Nuclear Reactor Regulation, Director. 83/02/17. 3pp. 17365:251. 24X Fiche: 50-348, 83/02/17, 8303030195.

--8303030210 Notice of issuance & availability of Amend 29 to License NPF-2.
VARGA, S. A. Operating Reactors Branch 1. 83/02/17. 2pp. 17365:254. 24X Fiche: 50-348, 83/02/17, 8303030195.

8303080512 Responds to 830223 telcon request to provide justification for continued operation for level sensors in main steam valve room & containment per 830204 technical evaluation repts.
CLAYTON, F. L. Alabama Power Co. 83/02/25. VARGA, S. A. Office of Nuclear Reactor Regulation, Director. 3pp. 17450:309. 24X
Fiche: 50-348, 83/02/25, 8303080512.

8303080242 Discusses rod swap methodology presented in Westinghouse "Rod Bank Worth Measurements Utilizing Bank Exchange-" May 1982." Util intends to use methodology for Cycle 5.
CLAYTON, F. L. Alabama Power Co. 83/03/01. VARGA, S. A. Office of Nuclear Reactor Regulation, Director. 2pp. 17446:350. 24X
Fiche: 50-348, 83/03/01, 8303080242.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303080517 Responds to 830302 telcon request for addl justification for continued operation of level sensors in main steam valve room & containment, per 830204 technical evaluation repts. Supports position that De Laval instruments are qualified.
CLAYTON, F. L. Alabama Power Co. 83/03/02. VARGA, S. A. Office of Nuclear Reactor Regulation, Director. 3pp. 17452:309. 24X
Fiche: 50-348, 83/03/02, 8303080517.

8303080480 Requests info of proprietary nature identified in technical evaluation repts be withheld per 10CFR2.790. Vendors have not supplied requested applications & affidavits at present.
CLAYTON, F. L. Alabama Power Co. 83/03/03. VARGA, S. A. Office of Nuclear Reactor Regulation, Director. 2pp. 17452:278. 24X
Fiche: 50-348, 83/03/03, 8303080480.

8303140312 Application for amend to Licenses NPF-2 & NPF-8 clarifying & updating charcoal filter Tech Specs.
CLAYTON, F. L. Alabama Power Co. 83/03/04. VARGA, S. A. Office of Nuclear Reactor Regulation, Director. 7pp. 17543:329. 24X
Fiche: 50-348, 83/03/04, 8303140312.

--8303140318 Proposed Tech Specs clarifying & updating interpretation & testing stds for charcoal filters.
* Alabama Power Co. 83/03/04. 15pp. 17543:336. 24X
Fiche: 50-348, 83/03/04, 8303140312.

8303140376 Application for amend to Licenses NPF-2 & NPF-8, revising Tech Specs 3.1.3.1 re movable control assemblies.
CLAYTON, F.L. Alabama Power Co. 83/03/04. VARGA, S.A. Office of Nuclear Reactor Regulation, Director. 4pp. 17542:199. 24X
Fiche: 50-348, 83/03/04, 8303140376.

--8303140380 Proposed Tech Spec 3.1.3.1 re limiting condition for operation of movable control assemblies.
* Alabama Power Co. 83/03/04. 3pp. 17542:203. 24X
Fiche: 50-348, 83/03/04, 8303140376.

8303140491 Requests that NRC approve 821230 Tech Spec changes to reduce boron concentration in boron injection tanks by 830318 instead of 830331, to support Unit 1 Cycle 5 restart.
CLAYTON, F.L. Alabama Power Co. 83/03/04. VARGA, S.A. Office of Nuclear Reactor Regulation, Director. 1p. 17540:311. 24X
Fiche: 50-348, 83/03/04, 8303140491.

8303140558 Forwards status of licensing items requiring NRC approval in 1983, identified in util 830113 ltr & summary of proposed actions to be taken on listed items w/no submittal or requested approval dates. Status provided on monthly basis.
CLAYTON, F.L. Alabama Power Co. 83/03/04. VARGA, S.A. Office of Nuclear Reactor Regulation, Director. 7pp. 17534:042. 24X
Fiche: 50-348, 83/03/04, 8303140558.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D.G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303150486 Provides results of reactor vessel level sys review & addresses Generic Ltr 82-28. Applicable provisions of NUREG-0737 met except environ qualification criteria of App B. Summary of feasibility study encl.
CLAYTON, F.L. Alabama Power Co. 83/03/10. VARGA, S.A. Office of Nuclear Reactor Regulation, Director. 42pp. 17560:268. 24X
Fiche: 50-348, 83/03/10, 8303150486.

8303300198 Forwards order confirming util commitment to implement post-TMI-related items set forth in NUREG-0737 & Generic Ltrs 82-05 & 82-10.
VARGA, S.A. Operating Reactors Branch 1. 83/03/14. CLAYTON, F.L. Alabama Power Co. 2pp. 17754:312. 24X Fiche: 50-348, 83/03/14, 8303300198.

--8303300205 Order confirming util commitment to implement post-TMI-related items set forth in NUREG-0737 & Generic Ltrs 82-05 & 82-10. Hearing may be requested within 20 days of order publication.
PURPLE, R.A. Division of Licensing. 83/03/14. Alabama Power Co. 8pp. 17754:314. 24X Fiche: 50-348, 83/03/14, 8303300198.

8303230227 Discusses Cycle 5 core reload Tech Spec changes not required for operation during Cycle 5, per WCAP-9272. Verification of reload core design performed per std startup physics tests.
CLAYTON, F.L. Alabama Power Co. 83/03/17. VARGA, S.A. Office of Nuclear Reactor Regulation, Director. 2pp. 17661:042. 24X
Fiche: 50-348, 83/03/17, 8303230227.

## 9. Inspection reports, IE Bulletins & correspondence

8303010432 Forwards IE Insp Repts 50-348/82-30 & 50-364/82-31 on 821216-830115. No noncompliance noted.
VERRELLI, D.M. Division of Project & Resident Programs. 83/02/02.
MCDONALD, R.P. Alabama Power Co. 2pp. 17343:073. 24X
Fiche: 50-348, 83/02/02, 8303010432.

--8303010437 IE Insp Repts 50-348/82-30 & 50-364/82-31 on 821216-830115. No noncompliance noted. Major areas inspected: monthly surveillance & maint observation, operational safety verification & routine events review.
BRADFORD, W.H., CANTRELL, F.S. Division of Project & Resident Programs. 83/02/01. 6pp. 17343:075. 24X Fiche: 50-348, 83/02/02, 8303010432.

8303010289 Forwards IE Insp Repts 50-348/83-01 & 50-364/83-01 on 830111-14. No noncompliance noted.
VERRELLI, D.M. Division of Project & Resident Programs. 83/02/03.
MCDONALD, R.P. Alabama Power Co. 2pp. 17335:270. 24X
Fiche: 50-348, 83/02/03, 8303010289.

--8303010295 IE Insp Repts 50-348/83-01 & 50-364/83-01 on 830111-14. No noncompliance noted. Major areas inspected: radiological environ monitoring, including mgt & administrative controls & insp of selected monitoring & sampling stations.
CUNNINGHAM, A.L., MONTGOMERY, D.M. Division of Project & Resident Programs. 83/01/31. 5pp. 17335:272. 24X Fiche: 50-348, 83/02/03, 8303010289.

8303010186 Ack receipt of 830207 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/82-29 & 50-364/82-30.
LEWIS, R.C. Division of Project & Resident Programs. 83/02/16.
MCDONALD, R.P. Alabama Power Co. 1p. 17333:338. 24X
Fiche: 50-348, 83/02/16, 8303010186.

--8303010209 Responds to NRC 830111 ltr re violations noted in IE Insp Repts 50-348/82-29 & 50-364/82-30. Corrective actions cause for alarmed annunicators determined & condition corrected. Memo written to emphasize importance of prompt response.
CLAYTON, F.L. Alabama Power Co. 83/02/07. LEWIS, R.C. Region 2, Office of Director. 2pp. 17333:339. 24X Fiche: 50-348, 83/02/16, 8303010186.

--8303010213 Forwards IE Insp Repts 50-348/82-29 & 50-364/82-30 on 821127-1215 & notice of violation.
LEWIS, R.C. Division of Project & Resident Programs. 83/01/11.
MCDONALD, R.P. Alabama Power Co. 2pp. 17333:341. 24X
Fiche: 50-348, 83/02/16, 8303010186.

--8303010215 Notice of violation from insp on 821127-1215.
* Division of Project & Resident Programs. 83/01/11. 1p. 17333:343. 24X Fiche: 50-348, 83/02/16, 8303010186.

--8303010221 IE Insp Repts 50-348/82-29 & 50-364/82-30 on 821127-1215. Noncompliance noted: failure to follow established procedures for annunicator response.
BRADFORD, W.H., CANTRELL, F.S. Division of Project & Resident Programs. 83/01/10. 6pp. 17333:344. 24X Fiche: 50-348, 83/02/16, 8303010186.

8303210723 Forwards IE Insp Rept 50-348/83-05 on 830201-04. No noncompliance noted.
VERRELLI, D.M. Division of Project & Resident Programs. 83/02/22.
MCDONALD, R.P. Alabama Power Co. 2pp. 17635:089. 24X
Fiche: 50-348, 83/02/22, 8303210723.

--8303210727 IE Insp Rept 50-348/83-05 on 830201-04. No noncompliance noted. Major areas inspected: radiation protection during refueling outage.
PEERY, W.W., BARR, K.P. Region 2, Office of Director. 83/02/18. 4pp. 17635:091. 24X Fiche: 50-348, 83/02/22, 8303210723.

8303210584 Forwards IE Insp Rept 50-348/83-04 on 830207-09. No noncompliance noted.
VERRELLI, D.M. Division of Project & Resident Programs. 83/02/24.
MCDONALD, R.P. Alabama Power Co. 2pp. 17632:245. 24X
Fiche: 50-348, 83/02/24, 8303210584.

--83[illegible]0591 IE Insp Rept 50-348/83-04 on 830207-09. No noncompliance [illegible]. Major areas inspected: core barrel mods for alteration [illegible] core barrel cooling water flow & fuel damage & fuel [illegible] et & pellet matl transport.
KR[illegible], H.E. Region 2, Office of Director. JAPE, F. Division of Eng neering & Radiological Safety Programs. 83/02/18. 5pp. 176[illegible]2:247. 24X Fiche: 50-348, 83/02/24, 8303210584.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210426 Forwards IE Insp Repts 50-348/83-06 & 50-364/83-04 on 830116-0215. No noncompliance noted.
VERRELLI, D.M. Division of Project & Resident Programs. 83/03/01.
MCDONALD, R.P. Alabama Power Co. 2pp. 17634:220. 24X
Fiche: 50-348, 83/03/01, 8303210426.

--8303210436 IE Insp Repts 50-348/83-06 & 50-364/83-04 on 830116-0215. No noncompliance noted. Major areas inspected: monthly surveillance observation, operational safety evaluation, independent insp effort & review of routine events.
BRADFORD, W.H. Region 2, Office of Director. CANTRELL, F.S. Division of Project & Resident Programs. 83/03/01. 7pp. 17634:222. 24X Fiche: 50-348, 83/03/01, 8303210426.

8303090312 Responds to IE Bulletin 83-01 re failure of Westinghouse DB-type breakers. DB-type breakers tested at least once per 31 days & verified open when undervoltage coil receives simulated trip signal.
CLAYTON, F. L. Alabama Power Co. 83/03/04. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17473:217. 24X Fiche: 50-348, 83/03/04, 8303090312.

8303210502 Forwards SALP rept for Jul 1981 - Jul 1982. Further NRC review necessary to address util comments re mischaracterization of fire protection issues.
O'REILLY, J. P. Region 2, Office of Director. 83/03/09.
MCDONALD, R. P. Alabama Power Co. 3pp. 17631:188. 24X Fiche: 50-348, 83/03/09, 8303210502.

--8303210532 Forwards SALP board assessment for Jul 1981 - Jul 1982. Comments due in 20 days.
LEWIS, R. C. Division of Project & Resident Programs. 82/12/06.
MCDONALD, R. P. Alabama Power Co. 2pp. 17631:191. 24X Fiche: 50-348, 83/03/09, 8303210502.

--8303210539 SALP Repts 50-348/82-28 & 50-364/82-28 for Jul 1981 - Jul 1982.
* Region 2, Office of Director. 83/03/09. 20pp. 17631:193. 24X Fiche: 50-348, 83/03/09, 8303210502.

--8303210548 Requests closure & removal of issues re 10CFR50, App R, Sections H & K.5, from SALP Repts 50-348/82-28 & 50-364/82-28.
CLAYTON, F. L. Alabama Power Co. 82/12/21. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17631:219. 24X Fiche: 50-348, 83/03/09, 8303210502.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303170531 Forwards addl response to IE Bulletin 79-01 re environ qualification of Class IE electrical equipment. Only outstanding action item is installation of water tight fitting on Victoreen radiation detectors.
CLAYTON, F. L. Alabama Power Co. 83/03/14. VARGA, S. A. Office of Nuclear Reactor Regulation, Director. 78pp. 17608:216. 24X Fiche: 50-348, 83/03/14, 8303170531.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 12?pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303290354 Responds to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel)." No significant fouling or flow blockage by Corbicula shells discovered.
CLAYTON, F. L. Alabama Power Co. 83/03/22. JORDAN, E. L. Division of Engineering & Quality Assurance (Pre 830103). 2pp. 17716:168. 24X Fiche: 50-348, 83/03/22, 830329 : 4.

R. Periodic operating reports & related correspondence

8303090341 Forwards "Semiannual Radioactive Effluent Release Rept, Jul-Dec 1981."
CLAYTON, F. L. Alabama Power Co. 83/03/02. O'REILLY, J. P. Region 2, Office of Director. 1p. 17472:143. 24X Fiche: 50-348, 82/03/02, 8303090341.

--8303090348 "Semiannual Radioactive Effluent Release Rept, Jul-Dec 1981."
* Alabama Power Co. 82/03/02. 147pp. 17472:144. 24X Fiche: 50-348, 82/03/02, 8303090341.

S. Reportable occurrences, LERs & related correspondence

8303040318 Forwards LER 83-002/03L-0.
CLAYTON, F. L. Alabama Power Co. 83/02/25. Region 2, Office of Director. 1p. 17367:329. 24X Fiche: 50-348, 83/02/25, 8303040318.

--8303040323 LER 83-002/03L-0 on 830128, source range detector NI-31 declared inoperable due to low detector voltage. Caused by setpoint drift. High voltage power supply adjusted & detector returned to svc.
HAIRSTON, W. G. Alabama Power Co. 83/02/25. Region 2, Office of Director. 1p. 17367:330. 24X Fiche: 50-348, 83/02/25, 8303040318.

8303040329 Forwards LER 83-007/03L-0.
CLAYTON, F. L. Alabama Power Co. 83/02/25. Region 2, Office of Director. 1p. 17372:256. 24X Fiche: 50-348, 83/02/25, 8303040329.

--8303040334 LER 83-007/03L-0 on 830114, electrical penetration G1T52B038-B failed local leak rate test. Caused by O-ring damage at inner seal from repairs during previous refueling outage. O-rings replaced.
HAIRSTON, W. G. Alabama Power Co. 83/02/25. Region 2, Office of Director. 2pp. 17372:257. 24X Fiche: 50-348, 83/02/25, 8303040329.

8303210377 Forwards LER 83-006/01T-0.
CLAYTON, F. L. Alabama Power Co. 83/03/02. Region 2, Office of Director. 1p. 17634:298. 24X Fiche: 50-348, 83/03/02, 8303210377.

--8303210384 LER 83-006/01T-0 on 830215, both trains of common control room filtration unit penetration room filtration sys carbon filters train A failed to meet criteria for iodine removal efficiency. Caused by misinterpretation of Reg Guide 1.52.
HAIRSTON, W. G. Alabama Power Co. 83/03/02. Region 2, Office of Director. 2pp. 17634:299. 24X Fiche: 50-348, 83/03/02, 8303210377.

8303180378 Forwards LER 83-008/03L-0, 83-006/03L-0, 83-007/03L-0, 83-008/03L-0 & 83-011/03L-0 W/o LERs 83-006/03L-0, 83-007/03L-0, 83-008/03L-0 & 83-011/03L-0.
CLAYTON, F. L. Alabama Power Co. 83/03/08. Region 2, Office of Director. 1p. 17621:342. 24X Fiche: 50-348, 83/03/08, 8303180378.

--8303180384 LER 83-008/03L-0 on 830213, penetration room filtration sys declared inoperable when surveillance test not performed per Tech Specs. Caused by personnel error. Test performed & sys declared operable on 830214.
HAIRSTON, W. G. Alabama Power Co. 83/03/08. Region 2, Office of Director. 2pp. 17621:343. 24X Fiche: 50-348, 83/03/08, 8303180378.

8303240302 PNO-II-83-014 on 830320, unusual noise detected in steam generator 1C not leg while in hot standby following refueling outage. Sludge lancing performed on secondary side. Plant being cooled down.
BUTCHER, R. C. ; CANTRELL, F. S. Region 2, Office of Director. 83/03/21. 1p. 17678:005. 24X Fiche: 50-348, 83/03/21, 8303240502.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303010506 Forwards list of anticipated requests for site visits for operator licensing exams through 1985, in response to Generic Ltr 83-01.
CLAYTON, F. L. Alabama Power Co. 83/02/24. EISENHUT, D. G. Division of Licensing. 2pp. 17337:249. 24X Fiche: 50-348, 83/02/24, 8303010506.

DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1

A. Application/construction stage documents & correspondence

8208060366 Board Notification 82-70 notifies of differing prof opinion re sensitization of BWR stainless steel weldments.
EISENHUT, D. G. Division of Licensing. 82/07/20. PALLADINO, N. J. Commissioners. 4pp. 17043:001. 24X Fiche: 50-000, 82/07/20, 8208060366.

8301310260 Forwards Amend 45 to OL application, consisting of Rev 2 to fire protection evaluation rept (Filed in PDR Category F) & Rev 16 to FSAR (Filed in PDR Category K).
BRADLEY, E. J. Philadelphia Electric Co. 83/01/28. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 16967:246. 24X Fiche: 50-352, 83/01/28, 8301310260.

--8301310266 Amend 45 to OL application, consisting of Rev 2 to Fire Protection Evaluation Rept & Rev 16 to FSAR Certificate of Svc encl.
BOYER, V. S. Philadelphia Electric Co. 83/01/26. 6pp. 16967:248. 24X Fiche: 50-352, 83/01/28, 8301310260.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303030115 Notification of 830314-18 meetings w/util, Bechtel & GE in San Francisco, CA to discuss previously identified instrumentation & control sys open issues.
SCHWENCER, A. Licensing Branch 2. 83/02/24. MARTIN, R. Licensing Branch 2. 3pp. 17365:285. 24X Fiche: 50-352, 83/02/24, 8303030115.

8303010431 Forwards "Investigation of Previously Recorded Prehistoric Archeological Sites." & "Survey of Cultural Resources in Area of Proposed Point Pleasant . . ." in response to Question E310.10 in NRC 821108 ltr.
BAUER, E. G. Philadelphia Electric Co. 83/02/25. SCHWENCER, A. Division of Licensing. 2pp. 17344:001. 24X Fiche: 50-352, 83/02/25, 8303010431.

--8303010439 "Investigation of Previously Recorded Prehistoric Archeological Sites Associated W/Proposed Limerick Transmission Lines, Montgomery & Chester Counties, PA." W/four oversize maps. Aperture cards are available in PDR.
STRUTHERS, T. L., HOFFMAN, F. F. John Milner Associates. 82/12/31. 46pp. 17344:003. 24X Fiche: 50-352, 83/02/25, 8303010431.

--8303010447 "Survey of Cultural Resources in Area of Proposed Point Pleasant Pumping Facilities, Combined Transmission Main, Bradshaw Reservoir, North Branch Main & Perkiomen Main, Bucks County, PA."
SCHORTMAN, E. M., URBAN, P. A. E. H. Bourquard Associates, Inc. 78/09/12. 62pp. 17344:050. 24X Fiche: 50-352, 83/02/25, 8303010431.

8303030016 Forwards 12 oversize riser diagrams for radioactive & nonradioactive equipment & floor drainage piping sys in response to Question 410.75 in NRC 820809 ltr. Aperture cards are available in PDR.
BRADLEY, E. J. Philadelphia Electric Co. 83/02/25. SCHWENCER, A. Licensing Branch 2. 2pp. 17414:016. 24X Fiche: 50-352, 83/02/25, 8303030016.

8303030084 Notification of 830309 meeting w/util in Bethesda, MD to identify & resolve open issues within Power Sys Branch area of review.
MARTIN, R. Licensing Branch 2. 83/02/25. SCHWENCER, A. Licensing Branch 2. 3pp. 17365:301. 24X Fiche: 50-352, 83/02/25, 8303030084.

8303030107 Notification of 830304 meeting w/util in Bethesda, MD for util presentation of program for environ & seismic & dynamic qualification of equipment.
MARTIN, R. Licensing Branch 2. 83/02/25. SCHWENCER, A. Licensing Branch 2. 3pp. 17365:289. 24X Fiche: 50-352, 83/02/25, 8303030107.

8303020029 Forwards Amend 46 to OL application, consisting of Rev 10 to environ rept - OL stage (filed in PDR Category C) & Rev 17 to FSAR (filed in PDR Category K).
BRADLEY, E. J. Philadelphia Electric Co. 83/02/28. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17350:208. 24X Fiche: 50-352, 83/02/28, 8303020029.

--8303020039 Amend 46 to OL application. Certificate of Svc encl.
BOYER, V. S., BRADLEY, E. J. Philadelphia Electric Co. 83/02/28. 6pp. 17350:210. 24X Fiche: 50-352, 83/02/28, 8303020029.

8303140664 A REVIEW OF THE LIMERICK GENERATING STATION PROBABILISTIC RISK ASSESSMENT.
PAPAZOGLOU, I. A., KAROL, R., SHIU, K. Brookhaven National Laboratory. FIN A-3393. NUREG/CR-3028. 83/02/28. Division of Safety Technology. 410pp. Available at NRC. $9.50. 17575:030. 24X Fiche: 50-352, 83/02/28, 8303140664.

8303100013 Notification of 830222-25 mechanical engineering review meetings w/util, Bechtel & GE in San Jose, CA to discuss open issues identified in 830207 ltr.
MARTIN, R. Licensing Branch 2. 83/03/01. SCHWENCER, A. Licensing Branch 2. 4pp. 17493:187. 24X Fiche: 50-352, 83/03/01, 8303100013.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303100205 Forwards draft responses & FSAR page changes re Instrumentation & Control Sys Branch request for addl info per Virgilio request. Info will be incorporated into FSAR subsequent to 830314 meeting.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/04. SCHWENCER, A. Licensing Branch 2. 157pp. 17489:001. 24X Fiche: 50-352, 83/03/04, 8303100205.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303160072 Forwards request for addl info re fracture toughness of reactor vessel & RCPB matls. Completion date for response requested within 10 days.
SCHWENCER, A. Licensing Branch 2. 83/03/08. BAUER, E. G. Philadelphia Electric Co. 6pp. 17614:350. 24X Fiche: 50-352, 83/03/08, 8303160072.

8303140367 Advises that response to NRC request for addl info re fast scram hydrodynamic loads on control rod drive sys will be submitted by 830429.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/09. SCHWENCER, A. Licensing Branch 2. 2pp. 17543:318. 24X Fiche: 50-352, 83/03/09, 8303140367.

8303180349 Provides update of const completion date. Const completion date of Aug 1984 consistent w/previous rept.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/16. EISENHUT, D. G. Division of Licensing. 2pp. 17620:132. 24X Fiche: 50-352, 83/03/16, 8303180349.

8303290479 Forwards updated info re NRC seismic & dynamic qualification & pump & valve operability review team audits. Info contains listing of equipment, location, dates & brief description of dynamic qualification tests.
KEMPER, J. S. Philadelphia Electric Co. 83/03/21. SCHWENCER, A. Licensing Branch 2. 4pp. 17724:331. 24X Fiche: 50-352, 83/03/21, 8303290479.

8303290101 Notification of 830329 & 30 meetings w/util in Philadelphia, PA to discuss responses to requests for addl info submitted in FSAR Rev 17.
MARTIN, R. E. Licensing Branch 2. 83/03/22. SCHWENCER, A. Licensing Branch 2. 3pp. 17729:208. 24X Fiche: 50-352, 83/03/22, 8303290101.

8303300615 Notification of 830406 meeting w/util in Bethesda, MD to resolve open issues within Containment Sys Branch area of review.
MARTIN, R. E. Licensing Branch 2. 83/03/23. SCHWENCER, A. Licensing Branch 2. 4pp. 17767:001. 24X Fiche: 50-352, 83/03/23, 8303300615.

8303300622 Notification of 830330 meeting w/util in Bethesda, MD to resolve open issues within Auxiliary Sys Branch area of review responsibility.
MARTIN, R. E. Licensing Branch 2. 83/03/23. SCHWENCER, A. Licensing Branch 2. 4pp. 17765:329. 24X Fiche: 50-352, 83/03/23, 8303300622.

8303280035 Forwards changes to FSAR text & draft responses to questions resulting from 830309-10 meetings w/Power Sys Branch. Response to Question 430.75 will be provided by end of Apr 1983.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/24. SCHWENCER, A. Licensing Branch 2. 95pp. 17707:012. 24X Fiche: 50-352, 83/03/24, 8303280035.

C. Utility Environmental Report (ER), amends & correspondence

8303020029 Forwards Rev 10 to environ rept - OL stage.
BRADLEY, E. J. Philadelphia Electric Co. 83/02/28. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17350:208. 24X Fiche: 50-352, 83/02/28, 8303020029.

--8303020042 Rev 10 to environ rept - OL stage.
* Philadelphia Electric Co. 83/02/28. 66pp. 17350:216. 24X Fiche: 50-352, 83/02/28, 8303020029.

8303160494 Forwards Affidavit of Svc re distribution of Rev 17 to FSAR & Rev 10 to environ rept, per DG Eisenhut 810706 ltr.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/14. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 5pp. 17592:318. 24X Fiche: 50-352, 83/03/14, 8303160494.

E. NRC Safety Evaluation Report (SER), supplements & correspondence

8303160675 Board Notification 83-25: forwards info re NUREG/CR-3028, "Review of Limerick Generating Station PRA." NRC review will be included in SER scheduled for Aug 1983 publication. W/o stated rept.
NOVAK, T. M. Assistant Director for Licensing. 83/03/04. Atomic Safety and Licensing Board Panel. 3pp. 17600:266. 24X Fiche: 50-352, 83/03/04, 8303160675.

--8303160705 Comments on BNL evaluation & assessment of plant PRA submitted 830222 as NUREG/CR-3028. Attention focused on areas of disagreement between BNL & util.
SPEIS, T. P. Division of Safety Technology. 83/03/04. EISENHUT, D. Division of Licensing. 4pp. 17600:269. 24X Fiche: 50-352, 83/03/04, 8303160675.

8303230091 Forwards draft SER encls discussing unresolved areas of review. Util will be contacted re actions required to resolve issues.
SCHWENCER, A. Licensing Branch 2. 83/03/11. BAUER, E. G. Philadelphia Electric Co. 71pp. 17687:179. 24X Fiche: 50-352, 83/03/11, 8303230091.

8303170545 Forwards draft responses & related FSAR page changes to open items contained in Mechanical Engineering Branch draft SER. Changes will be incorporated into FSAR following 830321 meeting.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/14. SCHWENCER, A. Licensing Branch 2. 209pp. 17608:007. 24X Fiche: 50-352, 83/03/14, 8303170545.

8303280103 Informs that dedicated effort required from util & NRC to achieve timely resolution of large number of open SER items. NRC will request several meetings be held to reduce number of open items.
NOVAK, T. M. Assistant Director for Licensing. 83/03/18. BAUER, E. G. Philadelphia Electric Co. 2pp. 17713:357. 24X
Fiche: 50-352, 83/03/18, 8303280103.

F. Security, medical, emergency & fire protection plans

8301310260 Forwards Rev 2 to fire protection evaluation rept.
BRADLEY, E. J. Philadelphia Electric Co. 83/01/28. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 16967:246. 24X Fiche: 50-352, 83/01/28, 8301310260.

--8301310270 Rev 2 to Fire Protection Evaluation Rept.
* Philadelphia Electric Co. 83/01/31. 79pp. 16967:254. 24X
Fiche: 50-352, 83/01/28, 8301310260.

8303010290 Requests response to encl comments re 820913 & 1217 ltrs concerning physical security plan. Comments withheld (ref 10CFR73.21).
SCHWENCER, A. Licensing Branch 2. 83/02/25. BAUER, E. G. Philadelphia Electric Co. 1p. 17335:277. 24X Fiche: 50-352, 83/02/25, 8303010290.

8303300315 Notification of 830419 meeting w/util in Silver Spring, MD to discuss present plans for implementation of security plan during operation of Unit 1 w/Unit 2 under const.
MARTIN, R. E. Licensing Branch 2. 83/03/25. SCHWENCER, A. Licensing Branch 2. 4pp. 17749:166. 24X Fiche: 50-352, 83/03/25, 8303300315.

G. Adjudicatory correspondence

8302030438 Informs that DES & SER to be issued in May & Aug 1983, respectively, will respond to 820826 & 830117 requests for addl info re credibility of facility accidents for design basis acceptance & determination of site acceptability.
HODGDON, A. P. Hearing Branch 2. 83/01/20. DORSEY, J. A. Dorsey, J. A. 2pp. 17006:187. 24X Fiche: 50-352, 83/01/20, 8302030438.

--8302030448 Requests addl NRC documents re determination of credibility of facility accidents for purposes of acceptance of design basis & for determination of site acceptability under 10CFR100, per informal discovery order.
DORSEY, J. A. Dorsey, J. A. * Limerick Ecology Action. 82/08/26.
LEWIS, S. H. Hearing Branch 2. 1p. 17006:189. 24X
Fiche: 50-352, 83/01/20, 8302030438.

8303010302 Order extending time until 830225 for Commission to act to review Directors 821207 decision denying Del-Aware Unlimited 820706 petition.
CHILK, S. J. Office of the Secretary of the Commission. 83/02/11. Commissioners. 1p. 17333:334. 24X Fiche: 50-352, 83/02/11, 8303010302.

8303140166 Advises of 830224-25 visit to Philadelphia, PA to examine documents produced by util in response to Limerick Ecology Action informal discovery request.
HODGDON, A. P. Hearing Branch 2. 83/02/17. WETTERHAHN, M. Conner & Wetterhahn. 1p. 17540:158. 24X Fiche: 50-352, 83/02/17, 8303140166.

8303140001 Forwards IE Insp Rept 50-352/82-16 issued as result of const assessment team 821129-1210 visit.
HODGDON, A. P. Hearing Branch 2. 83/02/24. WHITE, J. H. White, J. LEWIS, M. I. Lewis, M. 1p. 17528:140. 24X Fiche: 50-352, 83/02/24, 8303140001.

8303010375 Response opposing Del-Aware Unlimited 830202 petition for reconsideration or certification for appeal of denial of proposed contentions . 30214 petition to file late-filed contentions. Certificate of Svc encl.
HODGDON, A. P. ; CHAN, E. I. Hearing Branch 2. 83/02/25. Atomic Safety and Licensing Board Panel. 19pp. 17345:105. 24X
Fiche: 50-352, 83/02/25, 8303010375.

8303010406 Petition to add contention to require successful completion of TMI test of capability before reactors are granted OL. Certificate of Svc encl.
ROMANO, F. R. Air and Water Pollution Patrol. 83/02/28. Atomic Safety and Licensing board Panel. 2pp. 17346:224. 24X
Fiche: 50-352, 83/02/28, 8303010406.

8303020070 Advises that time for Commission to review Director's Decision DD-82-13 expired. Commission declined review. Decision became final agency action on 830225.
CHILK, S. J. Office of the Secretary of the Commission. 83/03/01. SUGARMAN, R. J. Sugarman, R. J. SUGARMAN, R. J. Del-Aware Unlimited, Inc. 1p. 17352:188. 24X Fiche: 50-352, 83/03/01, 8303020070.

8303040439 Forwards response to ASLB 830210 memorandum & order requesting info on conditionally admitted contentions.
WETTERHAHN, M. J. Conner & Wetterhahn. WETTERHAHN, M. J. Philadelphia Electric Co. 83/03/01. BRENNER, L. ; COLE, R. F. ; MORRIS, P. A. Atomic Safety and Licensing Board Panel. 9pp. 17370:223. 24X
Fiche: 50-352, 83/03/01, 8303040439.

8303040317 Informs that visit to Philadephia, PA to examine PRA documents produced by util in response to Limerick Ecology Action 820826 request deferred until 830310-11.
HODGDON, A. P. Hearing Branch 2. 83/03/02. WETTERHAHN, M. Conner & Wetterhahn. 1p. 17421:347. 24X Fiche: 50-352, 83/03/02, 8303040317.

8303090309 Partial initial decision on supplementary cooling water sys contentions. No significant adverse impact expected on American shad & shortnose sturgeon populations in DE River due to Point Pleasant intake operation.
BRENNER, L. ; COLE, R. F. ; MORRIS, P. A. Atomic Safety and Licensing Board Panel. 83/03/08. 113pp. 17473:219. 24X Fiche: 50-352, 83/03/08, 8303090309.

8303100357 Memorandum & order denying Del-Aware petitions for reconsideration & to admit late contention. Affirms rationale in 830124 ruling that Contentions V-22, V-23 & V-24 not be admitted.
BRENNER, L. Atomic Safety and Licensing Board Panel. 83/03/08. Del-Aware Unlimited, Inc. 12pp. 17488:336. 24X
Fiche: 50-352, 83/03/08, 8303100357.

8303140352 Forwards petition to file late Contention V-26 re effect of revised mgt plan for DE River. Petition should also be considered application to reopen record.
SUGARMAN, R. J. Sugarman, R. J. SUGARMAN, R. J. Del-Aware Unlimited, Inc. 83/03/08. BRENNER, L. ; COLE, R. F. ; MORRIS, P. A. Atomic Safety and Licensing Board Panel. 2pp. 17544:027. 24X
Fiche: 50-352, 83/03/08, 8303140352.

--8303140356 Petition to file late Contention V-26 re new DE River mgt plan. Plan announced on 830223. Reduced flows drastically affect viability of river follower method & might adversely affect spawning of fish. Certificate of Svc encl.
SUGARMAN, R. J. Del-Aware Unlimited, Inc. SUGARMAN, R. J. Sugarman, R. J. 83/03/08. Commissioners. 6pp. 17544:029. 24X
Fiche: 50-352, 83/03/08, 8303140352.

8303140272 Notice of ASLAB constitution. CN Kohl, chairman & SF Eilperin & RL Gotchy, members.
SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 83/03/10. 1p. 17535:031. 24X Fiche: 50-352, 83/03/10, 8303140272.

8303140285 Order denying Friends of the Earth 821219 motion for reconsideration of ASLB 821122 order denying Contentions 1, 2, 6, 8 & 9. Motion untimely.
BRENNER, L. Atomic Safety and Licensing Board Panel. 83/03/10. Friends of the Earth. 4pp. 17535:060. 24X Fiche: 50-352, 83/03/10, 8303140285.

8303150391 Answer opposing Air & Water Pollution Patrol petition for addl intervention contention on TMI test of capability. Intervenor is seeking adoption of new std applicable to industry. Certificate of Svc encl.
CONNER, T. B. Philadelphia Electric Co. CONNER, T. B. Conner & Wetterhahn. 83/03/11. Atomic Safety and Licensing Board Panel. 8pp. 17562:003. 24X Fiche: 50-352, 83/03/11, 8303150391.

8303180252 Request for clarification of ASLB 830210 order & extension until 830515 to review & comment on BNL PRA document. Uncertainties exist re ASLB expectations on PRA contentions & NRC review of PRA. Certificate of Svc encl.
DORSEY, J. A. Limerick Ecology Action. DORSEY, J. A. Dorsey, J. A. 83/03/14. Atomic Safety and Licensing Board Panel. 5pp. 17621:081. 24X Fiche: 50-352, 83/03/14, 8303180252.

8303170020 Response opposing Air & Water Pollution Patrol petition for admission of addl contention. Contention lacks basis & specificity. No good cause shown for late filing. Certificate of Svc encl.
CHAN, E. I. Hearing Branch 3 83/03/15 Atomic Safety and Licensing Board Panel 8pp. 17610:327 24X Fiche: 50-352, 83/03/15, 8303170020.

8303220249 Memorandum & order directing parties to address question of jurisdiction to rule on Del-Aware 830308 request for late filed Contention V-26. ASLB 830308 order remains final decision excluding Contention V-25.
BRENNER, L. Atomic Safety and Licensing Board Panel 83/03/17 8pp. 17656:279 24X Fiche: 50-352, 83/03/17, 8303220249.

8303230198 Notice & order of prehearing conference set for 830509-11 in Philadelphia, PA. Matters to be discussed include admissibility of conditionally admitted contentions & PRA contentions & status of discovery & emergency plans.
BRENNER, L. Atomic Safety and Licensing Board Panel 83/03/21 5pp. 17665:098 24X Fiche: 50-352, 83/03/21, 8303230198.

8303250167 Exceptions to ASLB 830308 partial initial decision on supplementary cooling water sys contentions. ASLB acted contrary to law in failing to complete DES before issuing decision. Certificate of Svc encl.
SUGARMAN, R. J. Del-Aware Unlimited, Inc. SUGARMAN, R. J. Sugarman, R. J. 83/03/21 Atomic Safety and Licensing Appeal Panel 10pp. 17691:124 24X Fiche: 50-352, 83/03/21, 8303250167.

8303290438 Clarifies 830301 ltr re status of conditionally admitted Contentions I.33(G) & 33(L).
WETTERHAHN, M. J. Conner & Wetterhahn WETTERHAHN, M. J. Philadelphia Electric Co. 83/03/23 BRENNER, L. J., MORRIS, P. A., COLE, R. F. Atomic Safety and Licensing Board Panel 2pp. 17725:359 24X
Fiche: 50-352, 83/03/23, 8303290438.

8303290505 Order deferring Del-Aware Unlimited briefing of exceptions to ASLB 830308 partial initial decision until further order. Exceptions will not be briefed while Del-Aware 830308 motion for admission of late Contention V-26 is pending.
SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 83/03/25 Del-Aware Unlimited, Inc. 2pp. 17723:002 24X
Fiche: 50-352, 83/03/25, 8303290505.

K. Utility Final Safety Analysis Report (FSAR) & amends.

8301310260 Forwards Rev 16 to FSAR.
BRADLEY, E. J. Philadelphia Electric Co. 83/01/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 16967:246. 24X Fiche: 50-352, 83/01/28, 8301310260.

8303020029 Forwards Rev 17 to FSAR.
BRADLEY, E. J. Philadelphia Electric Co. 83/02/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 17350:208 24X Fiche: 50-352, 83/02/28, 8303020029.

--8303020047 Rev 17 to FSAR.
* Philadelphia Electric Co. 511pp. 17350:287 24X
Fiche: 50-352, 83/02/28, 8303020029.

8303160494 Forwards Affidavit of Svc re distribution of Rev 17 to FSAR & Rev 10 to environ rept, per DG Eisenhut 810706 ltr.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/14 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 5pp. 17592:318 24X Fiche: 50-352, 83/03/14, 8303160494.

M. Antitrust correspondence.

8303110552 Fowards notice of receipt of antitrust info.
SCHWENCER, A. Licensing Branch 2 83/03/02 BAUER, E. G. Philadelphia Electric Co. 4pp. 17523:065 24X
Fiche: 50-352, 83/03/02, 8303110552.

--8303110556 Notice of receipt of antitrust info.
SCHWENCER, A. Licensing Branch 2 83/03/02 2pp. 17523:068 24X
Fiche: 50-352, 83/03/02, 8303110552.

O. Inspection reports, IE Bulletins & correspondence.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303240376 Forwards IE Insp Rept 50-352/83-03 on 830101-0214. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs 83/03/08
KEMPER, J. S. Philadelphia Electric Co. 2pp. 17679:082 24X
Fiche: 50-352, 83/03/08, 8303240376.

--8303240380 IE Insp Rept 50-352/83-03 on 830101-0214. No noncompliance noted. Major areas inspected: design of snubber clamps, HVAV subcontractor audit by licensee, followup of QE Part 21 rept & document review of reactor vessel work.
CHAUDHARY, S. K., GRAY, E. H., KEIMIG, R. R. Region 1, Office of Director 83/03/03 4pp. 17679:084 24X Fiche: 50-352, 83/03/08, 8303240376.

8303240287 Forwards IE Insp Rept 50-352/83-02 on 830131-0204 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs 83/03/10
KEMPER, J. S. Philadelphia Electric Co. 2pp. 17682:197 24X
Fiche: 50-352, 83/03/10, 8303240287.

--8303240293 Notice of violation from insp on 830131-0204.
* Region 1, Office of Director 83/03/10 1p. 17682:199 24X
Fiche: 50-352, 83/03/10, 8303240287.

--8303240301 IE Insp Rept 50-352/83-02 on 830131-0204. Noncompliance noted: failure to review & redline change to isometric drawing prior to installation & failure to correctly translate instrument tubing spec into drawing.
PADLINO, R. J., EAPEN, P. K., PLISCO, L. R. Region 1, Office of Director 83/02/25 13pp. 17682:200 24X Fiche: 50-352, 83/03/10, 8303240287.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp. 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8303240471 Ack receipt of 821221 & 830225 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-352/82-13.
STAROSTECKI, R. Division of Project & Resident Programs 83/03/16
KEMPER, J. S. Philadelphia Electric Co. 1p. 17678:098 24X
Fiche: 50-352, 83/03/16, 8303240471.

--8303240475 Responds to NRC 821123 ltr re violations noted in IE Insp Rept 50-352/82-13. Corrective actions: computerized logs of drawing change notices being used as periodic reminders to incorporate changes into drawings.
KEMPER, J. S. Philadelphia Electric Co. 83/02/25 HAYNES, R. C. Region 1, Office of Director 3pp. 17678:099 24X
Fiche: 50-352, 83/03/16, 8303240471.

--8303240477 Responds to NRC 821123 ltr re violations noted in IE Insp Rept 50-352/82-13. Corrective actions: Field Change Requests M-11.559F & M-11.939F incorporated into Drawing GBB-102-H1.
KEMPER, J. S. Philadelphia Electric Co. 82/12/21 HAYNES, R. C. Region 1, Office of Director 3pp. 17678:102 24X
Fiche: 50-352, 83/03/16, 8303240471.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp. 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

S. Reportable occurrences, LERs & related correspondence.

8303030671 Significant Deficiency Rept 67 re Rockwell Intl hydrogen recombiner equipment failures. Initially reported on 821021. Failed components listed. Also reportable per 10CFR21. Repairs will be made per vendor instruction.
KEMPER, J. S. Philadelphia Electric Co. 83/02/15 HAYNES, R. C. Region 1, Office of Director 2pp. 17414:029 24X
Fiche: 50-352, 83/02/15, 8303030671.

8303040554 Significant Deficiency Rept 38 re defects in Limitorque motor operator. Terminal blocks will be eliminated & external cables wired directly to motor operator elements.
KEMPER, J. S. Philadelphia Electric Co. 83/02/24 HAYNES, R. C. Region 1, Office of Director 4pp. 17424:122 24X
Fiche: 50-352, 83/02/24, 8303040554.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303030079 Responds to Generic Ltr 83-01 re operator licensing exam site visits through 1985.
GALLAGHER, J. W. Philadelphia Electric Co. 83/02/24 EISENHUT, D. G. Division of Licensing 3pp. 17413:229. 24X Fiche: 50-000, 83/02/24, 8303030079.

DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

A. Application/construction stage documents & correspondence

8301310260 Forwards Amend 45 to OL application, consisting of Rev 2 to fire protection evaluation rept (Filed in PDR Category F) & Rev 16 to FSAR (Filed in PDR Category K).
BRADLEY, E. J. Philadelphia Electric Co. 83/01/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 16967:246. 24X Fiche: 50-352, 83/01/28, 8301310260.

--8301310266 Amend 45 to OL application, consisting of Rev 2 to Fire Protection Evaluation Rept & Rev 16 to FSAR Certificate of Svc encl.
BOYER, V. S. Philadelphia Electric Co. 83/01/26 6pp. 16967:248. 24X Fiche: 50-352, 83/01/28, 8301310260.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303010431 Forwards "Investigation of Previously Recorded Prehistoric Archeological Sites..." & "Survey of Cultural Resources in Area of Proposed Point Pleasant..." in response to Question E310.10 in NRC 821108 ltr.
BAUER, E. G. Philadelphia Electric Co. 83/02/25 SCHWENCER, A. Division of Licensing 2pp. 17344:001. 24X Fiche: 50-352, 83/02/25, 8303010431.

--8303010439 "Investigation of Previously Recorded Prehistoric Archeological Sites Associated W/Proposed Limerick Transmission Lines, Montgomery & Chester Counties, PA." W/four oversize maps. Aperture cards are available in PDR.
STRUTHERS, T. L.; HOFFMAN, R. F. John Milner Associates 82/12/31. 46pp. 17344:003. 24X Fiche: 50-352, 83/02/25, 8303010431.

--8303010447 "Survey of Cultural Resources in Area of Proposed Point Pleasant Pumping Facilities, Combined Transmission Main, Bradshaw Reservoir, North Branch Main & Perkiomen Main, Bucks County, PA."
SCHORTMAN, E. M.; URBAN, P. A. E. H. Bourquard Associates, Inc. 78/09/12. 62pp. 17344:050. 24X Fiche: 50-352, 83/02/25, 8303010431.

8303030016 Forwards 12 oversize riser diagrams for radioactive & nonradioactive equipment & floor drainage piping sys, in response to Question 410.75 in NRC 820809 ltr. Aperture cards are available in PDR.
BRADLEY, E. J. Philadelphia Electric Co. 83/02/25 SCHWENCER, A. Licensing Branch 2 2pp. 17414:016. 24X Fiche: 50-352, 83/02/25, 8303030016.

8303030084 Notification of 830309 meeting w/util in Bethesda, MD to identify & resolve open issues within Power Sys Branch area of review.
MARTIN, R. Licensing Branch 2 83/02/25 SCHWENCER, A. Licensing Branch 2 3pp. 17365:301. 24X Fiche: 50-352, 83/02/25, 8303030084.

8303030107 Notification of 830304 meeting w/util in Bethesda, MD for util presentation of program for environ & seismic & dynamic qualification of equipment.
MARTIN, R. Licensing Branch 2 83/02/25 SCHWENCER, A. Licensing Branch 2 3pp. 17365:28[illegible] 24X Fiche: 50-352, 83/02/25, 8303030107.

8303020029 Forwards Amend 46 to OL application, consisting of Rev 10 to environ rept - OL stage (Filed in PDR Category C) & Rev 17 to FSAR (Filed in PDR Cateyory K).
BRADLEY, E. J. Philadelphia Electric Co. 83/02/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 17350:208. 24X Fiche: 50-352, 83/02/28, 8303020029.

--8303020039 Amend 46 to OL application. Certificate of Svc encl.
BOYER, V. S.; BRADLEY, E. J. Philadelphia Electric Co. 83/02/28. 6pp. 17350:210. 24X Fiche: 50-352, 83/02/28, 8303020029.

8303100013 Notification of 830222-25 mechanical engineering review meetings w/util, Bechtel & GE in San Jose, CA to discuss open issues identified in 830207 ltr.
MARTIN, R. Licensing Branch 2 83/03/01 SCHWENCER, A. Licensing Branch 2 4pp. 17493:187. 24X Fiche: 50-352, 83/03/01, 8303100013.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303100205 Forwards draft responses & FSAR page changes re Instrumentation & Control Sys Branch request for addl info per Virgilio request. Info will be incorporated into FSAR subsequent to 830314 meeting.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/04 SCHWENCER, A. Licensing Branch 2 157pp. 17489:001. 24X Fiche: 50-352, 83/03/04, 8303100205.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303160072 Forwards request for addl info re fracture toughness of reactor vessel & RCPB matls. Completion date for response requested within 10 days.
SCHWENCER, A. Licensing Branch 2 83/03/08 BAUER, E. G. Philadelphia Electric Co. 6pp. 17614:350. 24X Fiche: 50-352, 83/03/08, 8303160072.

8303140367 Advises that response to NRC request for addl info re fast scram hydrodynamic loads on control rod drive sys will be submitted by 830429.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/09 SCHWENCER, A. Licensing Branch 2 2pp. 17543:318. 24X Fiche: 50-352, 83/03/09, 8303140367.

8303290479 Forwards updated info re NRC seismic & dynamic qualification & pump & valve operability review team audits. Info contains listing of equipment, location, dates & brief description of dynamic qualification tests.
KEMPER, J. S. Philadelphia Electric Co. 83/03/21 SCHWENCER, A. Licensing Branch 2 4pp. 17724:331. 24X Fiche: 50-352, 83/03/21, 8303290479.

8303290101 Notification of 830329 & 30 meetings w/util in Philadelphia, PA to discuss responses to requests for addl info submitted in FSAR Rev 17.
MARTIN, R. E. Licensing Branch 2 83/03/22 SCHWENCER, A. Licensing Branch 2 3pp. 17729:208. 24X Fiche: 50-352, 83/03/22, 8303290101.

8303300615 Notification of 830406 meeting w/util in Bethesda, MD to resolve open issues within Containment Sys Branch area of review.
MARTIN, R. E. Licensing Branch 2 83/03/23 SCHWENCER, A. Licensing Branch 2 4pp. 17767:001. 24X Fiche: 50-352, 83/03/23, 8303300615.

8303300622 Notification of 830330 meeting w/util in Bethesda, MD to resolve open issues within Auxiliary Sys Branch area of review responsibility.
MARTIN, R. E. Licensing Branch 2 83/03/23 SCHWENCER, A. Licensing Branch 2 4pp. 17765:329. 24X Fiche: 50-352, 83/03/23, 8303300622.

8303280035 Forwards changes to FSAR text & draft responses to questions resulting from 830309-10 meetings w/Power Sys Branch. Response to Question 430.75 will be provided by end of Apr 1983.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/24 SCHWENCER, A. Licensing Branch 2 95pp. 17707:012. 24X Fiche: 50-352, 83/03/24, 8303280035.

C. Utility Environmental Report (ER), amends & correspondence

8303020029 Forwards Rev 10 to environ rept - OL stage.
BRADLEY, E. J. Philadelphia Electric Co. 83/02/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 17350:208. 24X Fiche: 50-352, 83/02/28, 8303020029.

--8303020042 Rev 10 to environ rept - OL stage.
* Philadelphia Electric Co. 83/02/28 66pp. 17350:216. 24X Fiche: 50-352, 83/02/28, 8303020029.

8303160494 Forwards Affidavit of Svc re distribution of Rev 17 to FSAR & Rev 10 to environ rept per DG Eisenhut 810706 ltr.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/14. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 5pp. 17592:318. 24X Fiche: 50-352, 83/03/14, 8303160494.

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303160675 Board Notification 83-25 forwards info re NUREG/CR-3028, "Review of Limerick Generating Station PRA." NRC review will be included in SER scheduled for Aug 1983 publication. W/o stated rept.
NOVAK, T. M. Assistant Director for Licensing. 83/03/04. Atomic Safety and Licensing Board Panel. 3pp. 17600:266. 24X Fiche: 50-352, 83/03/04, 8303160675.

--8303160705 Comments on BNL evaluation & assessment of plant PRA submitted 830222 as NUREG/CR-3028. Attention focused on areas of disagreement between BNL & util.
SPEIS, T. P. Division of Safety Technology. 83/03/04. EISENHUT, D. Division of Licensing. 4pp. 17600:269. 24X Fiche: 50-352, 83/03/04, 8303160675.

8303230091 Forwards draft SER encls discussing unresolved areas of review. Util will be contacted re actions required to resolve issues.
SCHWENCER, A. Licensing Branch 2. 83/03/11. BAUER, E. G. Philadelphia Electric Co. 71pp. 17687:179. 24X Fiche: 50-352, 83/03/11, 8303230091.

8303170545 Forwards draft responses & related FSAR page changes to open items contained in Mechanical Engineering Branch draft SER. Changes will be incorporated into FSAR following 830321 meeting.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/14. SCHWENCER, A. Licensing Branch 2. 209pp. 17608:007. 24X Fiche: 50-352, 83/03/14, 8303170545.

8303280103 Informs that dedicated effort required from util & NRC to achieve timely resolution of large number of open SER items. NRC will request several meetings be held to reduce number of open items.
NOVAK, T. M. Assistant Director for Licensing. 83/03/18. BAUER, E. G. Philadelphia Electric Co. 2pp. 17713:357. 24X Fiche: 50-352, 83/03/18, 8303280103.

F. Security, medical, emergency & fire protection plans

8301310260 Forwards Rev 2 to fire protection evaluation rept.
BRADLEY, E. J. Philadelphia Electric Co. 83/01/28. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 16967:246. 24X Fiche: 50-352, 83/01/28, 8301310260.

--8301310270 Rev 2 to Fire Protection Evaluation Rept.
* Philadelphia Electric Co. 83/01/31. 79pp. 16967:254. 24X Fiche: 50-352, 83/01/28, 8301310260.

8303010290 Requests response to encl comments re 820913 & 1217 ltrs concerning physical security plan. Comments withheld (ref 10CFR73.21).
SCHWENCER, A. Licensing Branch 2. 83/02/25. BAUER, E. G. Philadelphia Electric Co. 1p. 17335:277. 24X Fiche: 50-352, 83/02/25, 8303010290.

8303300315 Notification of 830419 meeting w/util in Silver Spring, MD to discuss present plans for implementation of security plan during operation of Unit 1 w/Unit 2 under const.
MARTIN, R. E. Licensing Branch 2. 83/03/25. SCHWENCER, A. Licensing Branch 2. 4pp. 17749:166. 24X Fiche: 50-352, 83/03/25, 8303300315.

G. Adjudicatory correspondence

8302030438 Informs that DES & SER to be issued in May & Aug 1983, respectively, will respond to 820826 & 830117 requests for addl info re credibility of facility accidents for design basi, acceptance & determination of site acceptability.
HODGDON, A. P. Hearing Branch 2. 83/01/20. DORSEY, J. A. Dorsey, J. A. 2pp. 17006:187. 24X Fiche: 50-352, 83/01/20, 8302030438.

--8302030448 Requests addl NRC documents re determination of credibility of facility accidents for purposes of acceptance of design basis & for determination of site acceptability under 10CFR100, per informal discovery order.
DORSEY, J. A. Dorsey, J. A. * Limerick Ecology Action. 82/08/26. LEWIS, S. H. Hearing Branch 2. 1p. 17006:189. 24X Fiche: 50-352, 83/01/20, 8302030438.

8303010302 Order extending time until 830225 for Commission to act to review Directors 821207 decision denying Del-Aware Unlimited 820706 petition.
CHILK, S. J. Office of the Secretary of the Commission. 83/02/11. Commissioners. 1p. 17333:334. 24X Fiche: 50-352, 83/02/11, 8303010302.

8303140166 Advises of 830224-25 visit to Philadelphia, PA to examine documents produced by util in response to Limerick Ecology Action informal discovery request.
HODGDON, A. P. Hearing Branch 2. 83/02/17. WETTERHAHN, M. Conner & Wetterhahn. 1p. 17540:158. 24X Fiche: 50-352, 83/02/17, 8303140166.

8303140001 Forwards IE Insp Rept 50-352/82-16 issued as result of const assessment team 821129-1210 visit.
HODGDON, A. P. Hearing Branch 2. 83/02/24. WHITE, J. H. White, J. LEWIS, M. I. Lewis, M. 1p. 17528:140. 24X Fiche: 50-352, 83/02/24, 8303140001.

8303010375 Response opposing Del-Aware Unlimited 830202 petition for reconsideration or certification for appeal of denial of proposed contentions & 830214 petition to file late-filed contentions. Certificate of Svc encl.
HODGDON, A. P. ; CHAN, E. I. Hearing Branch 2. 83/02/25. Atomic Safety and Licensing Board Panel. 19pp. 17345:105. 24X Fiche: 50-352, 83/02/25, 8303010375.

8303010406 Petition to add contention to require successful completion of TMI test of capability before reactors are granted OL. Certificate of Svc encl.
ROMANO, F. R. Air and Water Pollution Patrol. 83/02/28. Atomic Safety and Licensing Board Panel. 2pp. 17346:224. 24X Fiche: 50-352, 83/02/28, 8303010406.

8303020070 Advises that time for Commission to review Director's Decision DD-82-13 expired. Commission declined review. Decision became final agency action on 830225.
CHILK, S. J. Office of the Secretary of the Commission. 83/03/01. SUGARMAN, R. J. Sugarman, R. J. SUGARMAN, R. J. Del-Aware Unlimited, Inc. 1p. 17352:188. 24X Fiche: 50-352, 83/03/01, 8303020070.

8303040439 Forwards response to ASLB 830210 memorandum & order requesting info on conditionally admitted contentions.
WETTERHAHN, M. J. Conner & Wetterhahn. WETTERHAHN, M. J. Philadelphia Electric Co. 83/03/01. BRENNER, L. ; COLE, R. F. ; MORRIS, P. A. Atomic Safety and Licensing Board Panel. 9pp. 17370:223. 24X Fiche: 50-352, 83/03/01, 8303040439.

8303040317 Informs that visit to Philadephia, PA to examine PRA documents produced by util in response to Limerick Ecology Action 820826 request deferred until 830310-11.
HODGDON, A. P. Hearing Branch 2. 83/03/02. WETTERHAHN, M. Conner & Wetterhahn. 1p. 17421:347. 24X Fiche: 50-352, 83/03/02, 8303040317.

8303090309 Partial initial decision on supplementary cooling water sys contentions. No significant adverse impact expected on American shad & shortnose sturgeon populations in DE River due to Point Pleasant intake operation.
BRENNER, L. ; COLE, R. F. ; MORRIS, P. A. Atomic Safety and Licensing Board Panel. 83/03/08. 113pp. 17473:219. 24X Fiche: 50-352, 83/03/08, 8303090309.

8303100357 Memorandum & order denying Del-Aware petitions for reconsideration & to admit late contention. Affirms rationale in 830124 ruling that Contentions V-22, V-23 & V-24 not be admitted.
BRENNER, L. Atomic Safety and Licensing Board Panel. 83/03/08. Del-Aware Unlimited, Inc. 12pp. 17488:336. 24X Fiche: 50-352, 83/03/08, 8303100357.

8303140352 Forwards petition to file late Contention V-26 re effect of revised mgt plan for DE River. Petition should also be considered application to reopen record.
SUGARMAN, R. J. Sugarman, R. J. SUGARMAN, R. J. Del-Aware Unlimited, Inc. 83/03/08. BRENNER, L. ; COLE, R. F. ; MORRIS, P. A. Atomic Safety and Licensing Board Panel. 2pp. 17544:027. 24X Fiche: 50-352, 83/03/08, 8303140352.

--8303140356 Petition to file late Contention V-26 re new DE River mgt plan. Plan announced on 830223. Reduced flows drastically affect viability of river follower method & might adversely effect spawning of fish. Certificate of Svc encl.
SUGARMAN, R. J. Del-Aware Unlimited, Inc. SUGARMAN, R. J. Sugarman, R. J. 83/03/08. Commissioners. 6pp. 17544:029. 24X Fiche: 50-352, 83/03/08, 8303140352.

8303140272 Notice of ASLAB constitution. CN Kohl, chairman & SF Eilperin & RL Gotchy, members.
SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 83/03/10. 1p. 17535:031. 24X Fiche: 50-352, 83/03/10, 8303140272.

8303140285 Order denying Friends of the Earth 821219 motion for reconsideration of ASLB 821122 order denying Contentions 1, 2, 6, 8 & 9. Motion untimely.
BRENNER, L. Atomic Safety and Licensing Board Panel. 83/03/10. Friends of the Earth. 4pp. 17535:060. 24X Fiche: 50-352, 83/03/10, 8303140285.

8303150391 Answer opposing Air & Water Pollution Patrol petition for addl intervention contention on TMI test of capability. Intervenor is seeking adoption of new std applicable to industry. Certificate of Svc encl.
CONNER, T. B. Philadelphia Electric Co. CONNER, T. B. Conner & Wetterhahn. 83/03/11. Atomic Safety and Licensing Board Panel. 8pp. 17562:003. 24X Fiche: 50-352, 83/03/11, 8303150391.

8303180252 Request for clarification of ASLB 830210 order & extension until 830515 to review & comment on BNL PRA document. Uncertainties exist re ASLB expectations on PRA contentions & NRC review of PRA. Certificate of Svc encl.
DORSEY, J. A. Limerick Ecology Action. DORSEY, J. A. Dorsey, J. A. 83/03/14. Atomic Safety and Licensing Board Panel. 5pp. 17621:081. 24X Fiche: 50-352, 83/03/14, 8303180252.

8303170020 Response opposing Air & Water Pollution Patrol petition for admission of addl contention. Contention lacks basis & specificity. No good cause shown for late filing. Certificate of Svc encl.
CHAN, E. I. Hearing Branch 3. 83/03/15. Atomic Safety and Licensing Board Panel. 8pp. 17610:327. 24X Fiche: 50-352, 83/03/15, 8303170020.

8303220249 Memorandum & order directing parties to address question of jurisdiction to rule on Del-Aware 830308 request for late filed Contention V-26. ASLB 830308 order remains final decision excluding Contention V-25.
BRENNER, L. Atomic Safety and Licensing Board Panel. 83/03/17. 8pp. 17656:279. 24X Fiche: 50-352, 83/03/17, 8303220249.

8303230198 Notice & order of prehearing conference set for 830509-11 in Philadelphia, PA. Matters to be discussed include admissibility of conditionally admitted contentions & PRA contentions & status of discovery & emergency plans.
BRENNER, L. Atomic Safety and Licensing Board Panel. 83/03/21. 5pp. 17665:098. 24X Fiche: 50-352, 83/03/21, 8303230198.

8303250167 Exceptions to ASLB 830308 partial initial decision on supplementary cooling water sys contentions. ASLB acted contrary to law in failing to complete DES before issuing decision. Certificate of Svc encl.
SUGARMAN, R. J. Del-Aware Unlimited, Inc. SUGARMAN, R. J. Sugarman, R. J. 83/03/21. Atomic Safety and Licensing Appeal Panel. 10pp. 17691:124. 24X Fiche: 50-352, 83/03/21, 8303250167.

8303290438 Clarifies 830301 ltr re status of conditionally admitted Contentions I.33(G) & 33(L).
WETTERHAHN, M. J. Conner & Wetterhahn. WETTERHAHN, M. J. Philadelphia Electric Co. 83/03/23. BRENNER, L. J., MORRIS, P. A., COLE, R. F. Atomic Safety and Licensing Board Panel. 2pp. 17725:359. 24X Fiche: 50-352, 83/03/23, 8303290438.

8303290505 Order deferring Del-Aware Unlimited briefing of exceptions to ASLB 830308 partial initial decision until further order. Exceptions will not be briefed while Del-Aware 830308 motion for admission of late Contention V-26 is pending.
SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 83/03/25. Del-Aware Unlimited, Inc. 2pp. 17723:002. 24X Fiche: 50-352, 83/03/25, 8303290505.

K. Utility Final Safety Analysis Report (FSAR) & amends.

8301310260 Forwards Rev 16 to FSAR.
BRADLEY, E. J. Philadelphia Electric Co. 83/01/28. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 16967:246. 24X Fiche: 50-352, 83/01/28, 8301310260.

8303020029 Forwards Rev 17 to FSAR.
BRADLEY, E. J. Philadelphia Electric Co. 83/02/28. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17350:208. 24X Fiche: 50-352, 83/02/28, 8303020029.

--8303020047 Rev 17 to FSAR.
* Philadelphia Electric Co. 83/02/28. 511pp. 17350:287. 24X Fiche: 50-352, 83/02/28, 8303020029.

8303160494 Forwards Affidavit of Svc re distribution of Rev 17 to FSAR & Rev 10 to environ rept, per DG Eisenhut 810706 ltr.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/14. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 5pp. 17592:318. 24X Fiche: 50-352, 83/03/14, 8303160494.

M. Antitrust correspondence.

8303110552 Fowards notice of receipt of antitrust info.
SCHWENCER, A. Licensing Branch 2. 83/03/02. BAUER, E. G. Philadelphia Electric Co. 4pp. 17523:065. 24X Fiche: 50-352, 83/03/02, 8303110552.

--8303110556 Notice of receipt of antitrust info.
SCHWENCER, A. Licensing Branch 2. 83/03/02. 2pp. 17523:068. 24X Fiche: 50-352, 83/03/02, 8303110552.

Q. Inspection reports, IE Bulletins & correspondence.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

S. Reportable occurrences, LERs & related correspondence.

8303030671 Significant Deficiency Rept 67 re Rockwell Intl hydrogen recombiner equipment failures. Initially reported on 821021. Failed components listed. Also reportable per 10CFR21. Repairs will be made per vendor instruction.
KEMPER, J. S. Philadelphia Electric Co. 83/02/15. HAYNES, R. C. Region 1, Office of Director. 2pp. 17414:029. 24X Fiche: 50-352, 83/02/15, 8303030671.

8303040554 Significant Deficiency Rept 38 re defects in Limitorque motor operator. Terminal blocks will be eliminated & external cables wired directly to motor operator elements.
KEMPER, J. S. Philadelphia Electric Co. 83/02/24. HAYNES, R. C. Region 1, Office of Director. 4pp. 17424:122. 24X Fiche: 50-352, 83/02/24, 8303040554.

V. Operator Examinations.

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303030079 Responds to Generic Ltr 83-01 re operator licensing exam site visits through 1985.
GALLAGHER, J. W. Philadelphia Electric Co. 83/02/24. EISENHUT, D. G. Division of Licensing. 3pp. 17413:229. 24X Fiche: 50-000, 83/02/24, 8303030079.

DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence.

8303030458 Forwards acceptance review copies of amended OL application, consisting of antitrust review (PDR Category M), FSAR (Category A), security plan (Category F), environ rept (Category C) & Central Files version of emergency plan.
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey. 83/03/01. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 24X Fiche: 50-354, 83/03/01, 8303030458.

--8303030470 Acceptance review copy of amended OL application, consisting of antitrust review info, FSAR, security plan, emergency plan & environ rept.
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey. 83/03/01. 19pp. 24X Fiche: 50-354, 83/03/01, 8303030458.

8303100167 Submits daily highlight for 830302 Application for OL tendered. Projected fuel load date is Jan 1986. Licensing review will be developed upon completion of caseload forecast panel site visit in Apr 1983.
WAGNER, D. Licensing Branch 2 83/03/02 DENTON, H. R., CASE, E. G., CARTER, J. Office of Nuclear Reactor Regulation, Director 1p. 17495:212 24X Fiche: 50-354, 83/03/02, 8303100167.

8303160487 Forwards GE proprietary info re nuclear design description. Info will be ref in first amend to FSAR, Section 4.3.2.1. Info withheld (ref 10CFR2.790).
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey 83/03/02 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p. 17592:358 24X Fiche: 50-354, 83/03/02, 8303160487.

8303140274 Forwards "Onsite & Regional Meteorological Analysis for Hope Creek Generating Station Environ Rept - OL Stage & FSAR Submittal (Data Period, 1977-81)." Vols I & II. Data referenced in Section 1.3 of FSAR & environ rept.
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey 83/03/09 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p. 17535:125 24X Fiche: 50-354, 83/03/09, 8303140274.

--8303140280 "Onsite & Regional Meteorological Analysis for Hope Creek Generating Station Environ Rept - OL Stage & FSAR Submittal (Data Period, 1977-81)." Vols I & II.
* Public Service Electric & Gas Co. of New Jersey 83/03/09 533pp. 17537:052 24X Fiche: 50-354, 83/03/09, 8303140274.

8303280094 Notification of NRC caseload forecast panel 830405-07 meetings w/util in Salem County, NJ to discuss status of const & completion schedules.
WAGNER, D. Licensing Branch 2 83/03/18 SCHWENCER, A. Licensing Branch 2 5pp. 17715:337 24X Fiche: 50-354, 83/03/18, 8303280094.

C. Utility Environmental Report (ER), amends & correspondence

8303030458 Forwards acceptance review copy of environ rept.
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey 83/03/01 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 24X Fiche: 50-354, 83/03/01, 8303030458.

--8303030532 Acceptance review copy of environ rept for Hope Creek Generating Station, Unit 1.
* Public Service Electric & Gas Co. of New Jersey 83/03/01 1,000pp. 24X Fiche: 50-354, 83/03/01, 8303030458.

8303140274 Forwards "Onsite & Regional Meteorological Analysis for Hope Creek Generating Station Environ Rept - OL Stage & FSAR Submittal (Data Period, 1977-81)." Vols I & II. Data referenced in Section 1.3 of FSAR & environ rept.
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey 83/03/09 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p. 17535:125 24X Fiche: 50-354, 83/03/09, 8303140274.

--8303140280 "Onsite & Regional Meteorological Analysis for Hope Creek Generating Station Environ Rept - OL Stage & FSAR Submittal (Data Period, 1977-81)." Vols I & II.
* Public Service Electric & Gas Co. of New Jersey 83/03/09 533pp. 17537:052 24X Fiche: 50-354, 83/03/09, 8303140274.

F. Security, medical, emergency & fire protection plans

8303030458 Forwards acceptance review copy of security plan for Hope Creek Generating Station, Unit 1. Plan withheld (ref 10CFR2.790).
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey 83/03/01 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 24X Fiche: 50-354, 83/03/01, 8303030458.

--8303030467 Forwards acceptance review copy of security plan for Hope Creek Nuclear Generating Station, Unit 1. Plan withheld (ref 10CFR2.790).
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey 83/03/01 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p. 24X Fiche: 50-354, 83/03/01, 8303030458.

8303140274 Forwards "Onsite & Regional Meteorological Analysis for Hope Creek Generating Station Environ Rept - OL Stage & FSAR Submittal (Data Period, 1977-81)." Vols I & II. Data referenced in Section 1.3 of FSAR & environ rept.
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey 83/03/09 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p. 17535:125 24X Fiche: 50-354, 83/03/09, 8303140274.

--8303140280 "Onsite & Regional Meteorological Analysis for Hope Creek Generating Station Environ Rept - OL Stage & FSAR Submittal (Data Period, 1977-81)." Vols I & II.
* Public Service Electric & Gas Co. of New Jersey 83/03/09 533pp. 17537:052 24X Fiche: 50-354, 83/03/09, 8303140274.

G. Adjudicatory correspondence

8303020063 Response opposing util motion to strike C Kepford supplemental affidavit re qualifications as expert witness. Intervenors unable to respond in detail since motion never received. Certificate of Svc encl.
JOHNSRUD, J. H. Environmental Coalition on Nuclear Power 83/02/24 Commissioners 2pp. 17352:136 24X Fiche: 50-000, 83/02/24, 8303020063.

H. General correspondence

8303230255 Forwards revised distribution sheet for all NRC correspondence from NRR.
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey 83/03/08 SCHWENCER, A. Licensing Branch 2 3pp. 17661:167 24X Fiche: 50-354, 83/03/08, 8303230255.

I. Financial information

8303170159 Forwards Annual Financial Repts 1982 & 1983.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/14 SALTZMAN, J. Assistant Director for State & Licensee Relations 7pp. 17605:183 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170169 Annual Financial Rept 1982.
SMITH, R. I. Public Service Electric & Gas Co. of New Jersey 83/02/14 52pp. 17605:191 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170182 Annual Financial Rept 1982.
EVERETT, J. L. Philadelphia Electric Co. 83/03/14 41pp. 17605:243 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170193 Annual Financial Rept 1982.
WEIMER, R. D. Delmarva Power & Light Co. 83/02/04 44pp. 17605:287 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170206 Annual Financial Rept 1982.
FEEHAN, J. D. Atlantic Electric of New Jersey 83/03/14 42pp. 17605:333 24X Fiche: 50-000, 83/03/14, 8303170159.

K. Utility Final Safety Analysis Report (FSAR) & amends

8303030458 Forwards acceptance review copy of FSAR for Hope Creek Generating Station, Unit 1.
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey 83/03/01 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 24X Fiche: 50-354, 83/03/01, 8303030458.

--8303030527 Acceptance review copy of FSAR for Hope Creek Nuclear Generating Station, Unit 1. W/2,067 oversize drawings. Aperture cards are available in PDR.
* Public Service Electric & Gas Co. of New Jersey 83/03/01 6,371pp. 24X Fiche: 50-354, 83/03/01, 8303030458.

8303030537 Acceptance review copy of Chapter 1 to Hope Creek Generating Station, Unit 1, FSAR, "Introduction & General Description of Plant."
* Public Service Electric & Gas Co. of New Jersey 83/03/01 550pp. 24X Fiche: 50-354, 83/03/01, 8303030537.

8303030541 Acceptance review copy of Chapter 2 to Hope Creek Generating Station, Unit 1, FSAR, "Site Characteristics."
* Public Service Electric & Gas Co. of New Jersey 83/03/01 900pp. 24X Fiche: 50-354, 83/03/01, 8303030541.

8303030545 Acceptance review copy of Chapter 3 to Hope Creek Generating Station, Unit 1, FSAR, "Design of Structures, Components, Equipment & Sys."
* Public Service Electric & Gas Co. of New Jersey 83/03/01 800pp. 24X Fiche: 50-354, 83/03/01, 8303030545.

8303030550 Acceptance review copy of App 3A to Hope Creek FSAR, "Computer Programs Used in Structural Analysis & Design."
* Public Service Electric & Gas Co. of New Jersey 83/03/01 17pp. 24X Fiche: 50-354, 83/03/01, 8303030550.

8303030553 Acceptance review copy of App 3B to Hope Creek FSAR, "Mark I Long-Term Program Plant-Unique Analysis FSAR Summary Rept."
* Public Service Electric & Gas Co. of New Jersey * NUTECH Engineers, Inc. 83/03/01 59pp. 24X Fiche: 50-354, 83/03/01, 8303030553.

8303030558 Acceptance review copy of App 3C to Hope Creek FSAR, "Reactor Asymmetric Loads Analysis."
* Public Service Electric & Gas Co. of New Jersey 83/03/01 4pp. 24X Fiche: 50-354, 83/03/01, 8303030558.

8303030561 Acceptance review copy of Chapter 4 to Hope Creek Generating Station, Unit 1, FSAR, "Reactor."
* Public Service Electric & Gas Co. of New Jersey. 83/03/01.
200pp. 24X Fiche: 50-354, 83/03/01, 8303030561.

8303030564 Acceptance review copy of Chapter 5 to Hope Creek Generating Station, Unit 1, FSAR, "RCS & Connected Sys."
* Public Service Electric & Gas Co. of New Jersey. 83/03/01.
250pp. 24X Fiche: 50-354, 83/03/01, 8303030564.

8303030569 Acceptance review copy of Chapter 6 to Hope Creek Generating Station, Unit 1, FSAR, "ESF."
* Public Service Electric & Gas Co. of New Jersey. 83/03/01.
600pp. 24X Fiche: 50-354, 83/03/01, 8303030569.

8303030573 Acceptance review copy of App 6A to Hope Creek FSAR, "Negative Pressure Design Evaluation."
* Public Service Electric & Gas Co. of New Jersey. 83/03/01. 23pp.
24X Fiche: 50-354, 83/03/01, 8303030573.

8303030577 Acceptance review copy of App 6B to Hope Creek FSAR, "Subcompartment Differential Pressure Considerations."
* Public Service Electric & Gas Co. of New Jersey. 83/03/01. 64pp.
24X Fiche: 50-354, 83/03/01, 8303030577.

8303030583 Acceptance review copy of Chapter 7 to Hope Creek Generating Station, Unit 1, FSAR, "Instrumentation & Controls."
* Public Service Electric & Gas Co. of New Jersey. 83/03/01.
500pp. 24X Fiche: 50-354, 83/03/01, 8303030583.

8303030586 Acceptance review copy of Chapter 8 to Hope Creek Generating Station, Unit 1, FSAR, "Electrical Power."
* Public Service Electric & Gas Co. of New Jersey. 83/03/01.
175pp. 24X Fiche: 50-354, 83/03/01, 8303030586.

8303030589 Acceptance review copy of Chapter 9 to Hope Creek Generating Station, Unit 1, FSAR, "Auxiliary Sys."
* Public Service Electric & Gas Co. of New Jersey. 83/03/01.
525pp. 24X Fiche: 50-354, 83/03/01, 8303030589.

8303030593 Acceptance review copy of App 9A to Hope Creek FSAR, "App R Comparison."
* Public Service Electric & Gas Co. of New Jersey. 83/03/01.
100pp. 24X Fiche: 50-354, 83/03/01, 8303030593.

8303030599 Acceptance review copy of Chapter 10 to Hope Creek Generating Station, Unit 1, FSAR, "Steam & Power Conversion Sys."
* Public Service Electric & Gas Co. of New Jersey. 83/03/01.
100pp. 24X Fiche: 50-354, 83/03/01, 8303030599.

8303030603 Acceptance review copy o. Chapter 11 to Hope Creek Generating Station, Unit 1, FSAR, "Radwaste Mgt."
* Public Service Electric & Gas Co. of New Jersey. 83/03/01.
225pp. 24X Fiche: 50-354, 83/03/01, 8303030603.

8303030607 Acceptance review copy of Chapter 12 to Hope Creek Generating Station, Unit 1, FSAR, "Radiation Protection."
* Public Service Electric & Gas Co. of New Jersey. 83/03/01.
450pp. 24X Fiche: 50-354, 83/03/01, 8303030607.

8303030610 Acceptance review copy of Chapter 13 to Hope Creek Generating Station, Unit 1, FSAR, "Conduct of Operations."
* Public Service Electric & Gas Co. of New Jersey. 83/03/01.
200pp. 24X Fiche: 50-354, 83/03/01, 8303030610.

8303030615 Acceptance review copy of Chapter 14 to Hope Creek Generating Station, Unit 1, FSAR, "Initial Test Program."
* Public Service Electric & Gas Co. of New Jersey. 83/03/01.
141pp. 24X Fiche: 50-354, 83/03/01, 8303030615.

8303030621 Acceptance review copy of Chapter 15 to Hope Creek Generating Station, Unit 1, FSAR, "Accident Analyses."
* Public Service Electric & Gas Co. of New Jersey. 83/03/01.
400pp. 24X Fiche: 50-354, 83/03/01, 8303030621.

8303030623 Acceptance review copy of App 15A to Hopr Creek FSAR.
* Public Service Electric & Gas Co. of New Jersey. 83/03/01. 22pp.
24X Fiche: 50-354, 83/03/01, 8303030623.

8303030630 Acceptance review copy of Chapter 16 to Hope Creek Generating Station, Unit 1, FSAR, "Tech Specs."
* Public Service Electric & Gas Co. of New Jersey. 83/03/01. 8pp.
24X Fiche: 50-354, 83/03/01, 8303030630.

8303030635 Acceptance review copy of Chapter 17 to Hope Creek Generating Station, Unit 1, FSAR, "QA."
* Public Service Electric & Gas Co. of New Jersey. 83/03/01. 52pp.
24X Fiche: 50-354, 83/03/01, 8303030635.

8303030639 Acceptance review copy of Chapter 18 to Hope Creek Generating Station, Unit 1, FSAR, "Human Factors Engineering."
* Public Service Electric & Gas Co. of New Jersey. 83/03/01. 6pp.
24X Fiche: 50-354, 83/03/01, 8303030639.

M. Antitrust correspondence
---

8303030458 Forwards acceptancc review copy of "Info for Antitrust Review of OL Application, Hope Creek Nuclear Generating Station, Unit 1."
MITTL, R. L. Public Service Electric & Gas Co. of New Jersey.
83/03/01. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 24X Fiche: 50-354, 83/03/01, 8303030458.

--8303030524 "Info for Antitrust Review of OL Application, Hope Creek Nuclear Generating Station, Unit 1."
* Public Service Electric & Gas Co. of New Jersey. 83/03/01.
21pp. 24X Fiche: 50-354, 83/03/01, 8303030458.

Q. Inspection reports, IE Bulletins & correspondence
---

8303140574 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." No Bunker-Ramo electrical connections used at facility.
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey.
83/03/03. HAYNES, R. C. Region 1, Office of Director. 1p.
17534:004. 24X Fiche: 50-354, 83/03/03, 8303140574.

8303240562 Forwards IE Insp Rept 50-354/83-02 on 830201-28 & notice of violation.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/11.
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey. 2pp.
17683:185. 24X Fiche: 50-354, 83/03/11, 8303240562.

--8303240567 Notice of violation from insp on 830201-28.
* Region 1, Office of Director. 83/03/11. 1p. 17683:187. 24X Fiche: 50-354, 83/03/11, 8303240562.

--8303240575 IE Insp Rept 50-354/83-02 on 830201-28. Noncompliance noted: failure to cure concrete per spec & ACI requirements.
BATEMAN, W. H., GRANT, J., TRIPP, L. E. Region 1, Office of Director.
83/03/10. 7pp. 17683:188. 24X Fiche: 50-354, 83/03/11, 8303240562.

8303280294 Forwards IE Insp Rept 50-354/83-03 on 830214-18. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/14.
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey. 2pp.
17706:185. 24X Fiche: 50-354, 83/03/14, 8303280294.

--8303280303 IE Insp Rept 50-354/83-03 on 830214-18. No noncompliance noted. Major areas inspected: design, procurement, receipt & installation of electrical components/sys.
PAOLINO, R. J., ANDERSON, C. J. Region 1, Office of Director.
83/03/11. 5pp. 17706:187. 24X Fiche: 50-354, 83/03/14, 8303280294.

S. Reportable occurrences, LERs & related correspondence
---

8303090061 Interim deficiency rept re const of scribed lines on small bore piping used in gauging socket weld locations. Initially reported on 830124. Investigation underway. Final rept to be submitted by 830430.
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey.
83/02/24. HAYNES, R. C. Region 1, Office of Director. 2pp.
17467:016. 24X Fiche: 50-354, 83/02/24, 8303090061.

8303140386 Interim deficiency rept re defective spot welds in four Class 1E termination cabinet assemblies. Initially reported on 830125. Defective cabinets reworked by Bailey Controls Co. Final rept will be submitted by 830430.
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey.
83/02/28. HAYNES, R. C. Region 1, Office of Director. 2pp.
17542:120. 24X Fiche: 50-354, 83/02/28, 8303140386.

DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2
---

Q. Adjudicatory correspondence
---

8303020063 Response opposing util motion to strike C Kepford supplemental affidavit re qualifications as expert witness. Intervenors unable to respond in detail since motion never received. Certificate of Svc encl.
JOHNSRUD, J. H. Environmental Coalition on Nuclear Power Commissioners. 83/02/24. 2pp. 17352:136. 24X Fiche: 50-000, 83/02/24, 8303020063.

I. Financial information

8303170159 Forwards Annual Financial Repts 1982 & 1983.
BRADLEY, E. J. Philadelphia Electric Co. 83/03/14. SALTZMAN, J.
Assistant Director for State & Licensee Relations. 7pp. 17605:183.
24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170169 Annual Financial Rept 1982.
SMITH, R. I. Public Service Electric & Gas Co. of New Jersey.
83/02/14. 52pp. 17605:191. 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170182 Annual Financial Rept 1982.
EVERETT, J. L. Philadelphia Electric Co. 83/03/14. 41pp.
17605:243. 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170193 Annual Financial Rept 1982.
WEIMER, R. D. Delmarva Power & Light Co. 83/02/04. 44pp.
17605:287. 24X Fiche: 50-000, 83/03/14, 8303170159.

--8303170206 Annual Financial Rept 1982.
FEEHAN, J. D. Atlantic Electric of New Jersey. 83/03/14. 42pp.
17605:333. 24X Fiche: 50-000, 83/03/14, 8303170159.

Q. Inspection reports, IE Bulletins & correspondence

8303140574 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." No Bunker-Ramo electrical connections used at facility.
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey.
83/03/03. HAYNES, R. C. Region 1, Office of Director. 1p.
17534:004. 24X Fiche: 50-354, 83/03/03, 8303140574.

S. Reportable occurrences, LERs & related correspondence

8303090061 Interim deficiency rept re const ... scribed lines on small bore piping used in gauging socket weld locations. Initially reported on 830124. Investigation underway. Final rept to be submitted by 830430.
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey.
83/02/24. HAYNES, R. C. Region 1, Office of Director. 2pp.
17467:016. 24X Fiche: 50-354, 83/02/24, 8303090061.

8303140386 Interim deficiency rept re defective spot welds in four Class 1E termination cabinet assemblies. Initially reported on 830125. Defective cabinets reworked by Bailey Controls Co. Final rept will be submitted by 830430.
MARTIN, T. J. Public Service Electric & Gas Co. of New Jersey.
83/02/28. HAYNES, R. C. Region 1, Office of Director. 2pp.
17542:120. 24X Fiche: 50-354, 83/02/28, 8303140386.

DOCKET: 50-358 WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

8303230092 Clarifies & supplis info from Palladino 821020 ltr to Congressman Udall & monthly status rept re welder qualification issue. NRC did not agree w/util conclusion that only 19 welders unqualified.
KEPPLER, J. G. Region 3, Office of Director. 83/02/07. DIRCKS, W. J.
Office of the Executive Director for Operations. 2pp. 17687:177.
24X Fiche: 50-358, 83/02/07, 8303230092.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303030747 Board Notification 83-13: forwards EG&G draft rept, "Identification & Ranking of Nuclear Plant Structures, Sys & Components & Graded QA Guidelines."
EISENHUT, D. G. Division of Licensing. 83/02/17. PALLADINO, N. ,
GILINSKY, V. , ASSELSTINE Commissioners. 24pp. 17364:037. 24X
Fiche: 50-000, 83/02/17, 8303030747.

8303030710 Board Notification 83-17: forwards JH Conran 830209 affidavit re changes to previous testimony on Unresolved Safety Issue A-17, "Sys Interaction in Nuclear Power Plants."
EISENHUT, D. G. Division of Licensing. 83/02/18. PALLADINO, N. J.
Commissioners. 6pp. 17363:317. 24X Fiche: 50-000, 83/02/18,
8303030710.

8303230085 Supplis 830207 memo re welder qualification issue. Pertinent info re status of ongoing investigation listed.
KEPPLER, J. G. Region 3, Office of Director. 83/02/18. DIRCKS, W. J.
Office of the Executive Director for Operations. 3pp. 17687:250.
24X Fiche: 50-358, 83/02/18, 8303230085.

8303020294 Lists addl info needed to complete review of environ qualification of safety-related equipment. Results should be concurrent w/site audit.
YOUNGBLOOD, B. J. Licensing Branch 1. 83/02/22. BORGMANN, E. A.
Cincinnati Gas & Electric Co. 4pp. 17355:308. 24X
Fiche: 50-358, 83/02/22, 8303020294.

8303020295 Forwards request for addl info re OL application. Info due by 830331.
YOUNGBLOOD, B. J. Licensing Branch 1. 83/02/22. BORGMANN, E. A.
Cincinnati Gas & Electric Co. 7pp. 17355:301. 24X
Fiche: 50-358, 83/02/22, 8303020295.

8303100491 Forwards 821206 & 830119 repts from Mechanical & Structural Engineering Branches, per 821012 request for NRR assistance re Sargent & Lundy design calculations of plant main steam sys. Addl info needed.
EISENHUT, D. G. Division of Licensing. 83/02/25. WARNICK, R. F.
Region 3, Office of Director. 1p. 17503:001. 24X
Fiche: 50-358, 83/02/25, 8303100491.

--8212150184 Trip rept of 821025-26 visit to Chicago to review plant QA program & determine acceptability of supporting seismic Category I main steam piping in nonseismic turbine bldg. Piping & supports adequate to withstand seismic event.
TERAO, D. Mechanical Engineering Branch. 82/12/06. BOSNAK, R. J.
Mechanical Engineering Branch. 4pp. 17503:002. 24X
Fiche: 50-358, 83/02/25, 8303100491.

--8301250065 Trip rept of 821025-26 meeting w/Sargent & Lundy & util in Chicago, IL to review QA Program. NRR requested to assist Region 4 in determination of acceptability of seismic analysis & design of turbine bldg.
LIPINSKI, R. E. Structural Engineering Branch. 83/01/19.
SCHAUER, F. P. Structural Engineering Branch. 6pp. 17503:006. 24X
Fiche: 50-358, 83/02/25, 8303100491.

8303220357 Advises that Bechtel will not perform independent mgt review but will be retained as consultant to assist w/listed activities permitted under 821112 order to show cause & 830218 memo.
DICKHONER, W. H. Cincinnati Gas & Electric Co. 83/02/28.
KEPPLER, J. G. Region 3, Office of Director. 2pp. 17656:002. 24X
Fiche: 50-358, 83/02/28, 8303220357.

8303110027 Board Notification 83-18 provides brief description of independent assessment by NRC evaluation team of installed safety-related equipment.
EISENHUT, D. G. Division of Licensing. 83/03/01. PALLADINO, N. ,
GILINSKY, V. , AHEARNE, J. Commissioners. 7pp. 17546:297. 24X
Fiche: 50-358, 83/03/01, 8303110027.

--8303110032 Confirms NRC intent to perform team evaluation & independent measurement verification of safety-related equipment between 830124-0304.
MARTIN, T. T. Division of Engineering & Technical Programs.
83/01/11. BORGMANN, E. A. Cincinnati Gas & Electric Co. 2pp.
17546:304. 24X Fiche: 50-358, 83/03/01, 8303110027.

--8301050367 Forwards plan of action to review util implementation of Commission 821112 show cause order & order immediately suspending const, CLI-82-33. Review of proposal for approval of Bechtel as mgt reviewer scheduled for Jan 1983.
DIRCKS, W. J. Office of the Executive Director for Operations.
82/12/17. PALLADINO, N. J. , GILINSKY, V. , AHEARNE, J. Commissioners.
7pp. 17546:306. 24X Fiche: 50-358, 83/03/01, 8303110027.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303090095 Responds to 830221 ltr re continuation of certain site activities. Movement of permanent plant matl from plant fabrication shops or warehouse areas not considered safety-related const suspended by show cause order.
WARNICK, R. F. Region 3, Office of Director. 83/03/03. BORGMANN, E. A.
Cincinnati Gas & Electric Co. 2pp. 17469:342. 24X
Fiche: 50-358, 83/03/03, 8303090095.

--8303090101 Clarifies Item 11 of NRC 821130 ltr. When permanent plant matl is in power plant, fab shops or warehouse matl can be moved to secure location or location for inventory purpose, as long as movement is not for permanent installation.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 83/02/21.
KEPPLER, J. G. Region 3, Office of Director. 1p. 17469:344. 24X
Fiche: 50-358, 83/03/03, 8303090095.

8303090208 Responds to util 830223 ltr requesting NRC review & concurrence w/performance of work on flanged joints & release of piping from warehouse for testing purposes. Items not considered to be suspended on show cause order.
WARNICK, R. F. Region 3, Office of Director 83/03/03 BORGMANN, E. A. Cincinnati Gas & Electric Co. 2pp. 17492.137 24X
Fiche: 50-358, 83/03/03, 8303090208.

--8303090212 Requests NRC review & concurrence w/work activities on flanged joints & release of piping from warehouse for testing purposes. Activities do not violate B21112 show cause order for immediate suspension of essential const.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 83/02/23
KEPPLER, J. G. Region 3, Office of Director 2pp. 17492.139 24X
Fiche: 50-358, 83/03/03, 8303090208.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J. G. Region 3, Office of Director 83/03/03
Commonwealth Edison Co. 2pp. 17492.014 24X Fiche: 50-000, 83/03/03, 8303100364.

8303080008 Amend 146 to OL application, consisting of Rev 92 to FSAR.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 83/03/04 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 17456.196 24X Fiche: 50-358, 83/03/04, 8303080008.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp. 17660.176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303170511 Forwards Certificate of Svc of Amend 146 to application for OL consisting of Rev 92 to FSAR.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 83/03/10 DENTON, H. Office of Nuclear Reactor Regulation, Director 2pp. 17607.131 24X Fiche: 50-358, 83/03/10, 8303170511.

8303230063 Advises that Torrey Pines Technology will perform independent mgt review of facility per B21112 order. Util 830307 ltr, providing info re contractor competence & independence, to be provided for public comment.
DIRCKS, W. J. Office of the Executive Director for Operations 83/03/11 PALLADINO, N. J.; GILINSKY, V.; AHEARNE, J. Commissioners 1p. 17688.340 24X Fiche: 50-358, 83/03/11, 8303230063.

--8303230072 Responds to B21112 order to show cause which suspended all safety-related activities. Interim measures assuring that const will proceed per NRC requirements listed. Bechtel will consult on activities not restricted by order.
DICKHONER, W. H. Cincinnati Gas & Electric Co. 83/02/28
KEPPLER, J. G. Region 3, Office of Director 2pp. 17688.341 24X
Fiche: 50-358, 83/03/11, 8303230063.

--8303230078 Responds to util 830228 response to B21112 show cause order. Commission does not object to util activities to determine facility status & prepare comprehensive plans for const quality verification & const continuation.
KEPPLER, J. G. Region 3, Office of Director 83/03/10
DICKHONER, W. H. Cincinnati Gas & Electric Co. 1p. 17688.343 24X
Fiche: 50-358, 83/03/11, 8303230063.

--8303230084 Requests approval to retain Torrey Pines Technology to perform independent mgt review of project mgt per B21112 show cause order. Contractor 830304 proposal not encl.
DICKHONER, W. H. Cincinnati Gas & Electric Co. 83/03/07
KEPPLER, J. G. Region 3, Office of Director 2pp. 17688.344 24X
Fiche: 50-358, 83/03/11, 8303230063.

8303220098 Forwards request for addl info re Torrey Pines Technology proposal to conduct independent mgt review. Responses should be provided prior to 830328 public meeting in Cincinnati, OH.
KEPPLER, J. G. Region 3, Office of Director 83/03/16
DICKHONER, W. H. Cincinnati Gas & Electric Co. 3pp. 17650.072 24X
Fiche: 50-358, 83/03/16, 8303220098.

8303300724 Board Notification 83-32 forwards Region I 830228 memo re errors discovered in computer analyses used to support Mark II containment confirmatory program.
NOVAK, T. M. Assistant Director for Licensing 83/03/18 Atomic Safety and Licensing Board Panel 5pp. 17765.003 24X
Fiche: 50-000, 83/03/18, 8303300724.

8303310393 Board Notification 83-37 provides info re facility const QA plan & review of main steam line design calculations. Addl analyses required to demonstrate design meets regulatory guidelines.
EISENHUT, D. G. Division of Licensing 83/03/18 PALLADINO, N.; GILINSKY, V.; AHEARNE, J. Commissioners 10pp. 17796.038 24X
Fiche: 50-358, 83/03/18, 8303310393.

8303290383 Forwards list of initial documents & info required in anticipation that Torrey Pines Technology will be confirmed as independent reviewer of project mgt. NRC advised of request via 830322 telcon.
NEYLAN, A. J. Torrey Pines Technology 83/03/22 DICKHONER, W. H. Cincinnati Gas & Electric Co. 6pp. 17716.261 24X
Fiche: 50-358, 83/03/22, 8303290383.

8303300212 Requests improved schedule for submission of Mark II containment analyses & dates for all info needed to close open items in OL apolication. Response requested by 830415.
YOUNGBLOOD, B. J. Licensing Branch 1 83/03/24 BORGMANN, E. A. Cincinnati Gas & Electric Co. 4pp. 17754.141 24X
Fiche: 50-358, 83/03/24, 8303300212.

8303300282 Requests description of use of Marathon 6000 series terminal block in harsh environ created by accident conditions & corrective actions planned & target dates for installation of qualified components. Response requested by 830415.
YOUNGBLOOD, B. J. Licensing Branch 1 83/03/24 BORGMANN, E. A. Cincinnati Gas & Electric Co. 3pp. 17749.118 24X
Fiche: 50-358, 83/03/24, 8303300282.

F. Security, medical, emergency & fire protection plans

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director 83/03/22 Commonwealth Edison Co. 2pp. 17690.316 24X Fiche: 50-000, 83/03/22, 8303240440.

G. Adjudicatory correspondence

8303070060 Forwards D Gillman document delineating five new contentions. NRC response will be filed w/ASLB.
BARTH, C. A. Hearing Branch 1 83/03/04 FRY, J. H.; LIVINGSTON, M. S.; HOOPER, F. F. Atomic Safety and Licensing Board Panel 7pp. 17434.289 24X Fiche: 50-358, 83/03/04, 8303070060.

8303100385 Order extending time until 830408 for Commission to act to review 830210 director's decision.
CHILK, S. J. Office of the Secretary of the Commission 83/03/07 Commissioners 1p. 17488.283 24X Fiche: 50-358, 83/03/07, 8303100385.

8303140305 Memorandum & order asserting jurisdiction over D Gillman five contentions. Responses should be submitted within time limit set for petitions to intervene. Time limits begin w/date of svc of memorandum & order.
FRYE, J. H. Atomic Safety and Licensing Board Panel 83/03/10 3pp. 17535.036 24X Fiche: 50-358, 83/03/10, 8303140305.

8303180034 Response opposing D Gillman five new contentions. Gillman lacks standing. No interest shown. No good cause shown for filing contentions over 7 yrs late. Certificate of Svc encl.
BARTH, C. A. Hearing Branch 1 83/03/16 Atomic Safety and Licensing Board Panel 8pp. 17617.248 24X Fiche: 50-358, 83/03/16, 8303180034.

8303290527 Answer opposing D Gillman late-filed petition to intervene. Proposed contentions lack discernable meaning. Coherent presentation not made re interest & late contentions or reopening record requirements. Certificate of Svc encl.
WETTERHAHN, M. J. Southern California Edison Co. WETTERHAHN, M. J. Conner & Wetterhahn 83/03/24 Atomic Safety and Licensing Board Panel 13pp. 17725.050 24X Fiche: 50-358, 83/03/24, 8303290527.

J. Insurance & indemnity information

8303110269 Forwards Endorsement 22 to NELIA Policy NF-249.
NADEL, M. Marsh & McLennan, Inc. 83/03/07 SALTZMAN, J. Assistant Director for State & Licensee Relations 2pp. 17517.345 24X
Fiche: 50-358, 83/03/07, 8303110269.

K. Utility Final Safety Analysis Report (FSAR) & amends

8303080008 Amend 146 to OL application, consisting of Rev 92 to FSAR.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 83/03/04 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 17456.196 24X Fiche: 50-358, 83/03/04, 8303080008.

--8303080010 Rev 92 to FSAR.
* Cincinnati Gas & Electric Co. 83/03/31 72pp. 17456.198 24X
Fiche: 50-358, 83/03/04, 8303080008.

8303170511 Forwards Certificate of Svc of Amend 146 to application for OL consisting of Rev 92 to FSAR.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 83/03/10 DENTON, H. Office of Nuclear Reactor Regulation, Director 2pp 17607:131 24X Fiche: 50-358, 83/03/10, 8303170511.

Q. Inspection reports, IE Bulletins & correspondence

8303110355 Board Notification 83-14 forwards followup info on apparent deficiencies in Midland-Ross superstrut matl.
EISENHUT, D. G. Division of Licensing 83/02/18 PALLADINO, N., GILINSKY, V., AHEARNE, J. Commissioners 24pp 17546:205 24X Fiche: 50-000, 83/02/18, 8303110355.

8303140468 Forwards IE Mgt Meeting Rept 50-358/82-15 on 821117.
KEPPLER, J. G. Region 3, Office of Director 83/02/24.
DICKHONER, W. H. Cincinnati Gas & Electric Co. 2pp 17541:049 24X Fiche: 50-358, 83/02/24, 8303140468.

--8303140475 IE Mgt Meeting Rept 50-358/82-15 on 821117. Items discussed: 821112 order to show cause & immediately suspend const & util plan for implementing order. No commitments made by licensee.
HUNTER, D. R., WARNICK, R. F. Region 3, Office of Director 83/02/17. 4pp 17541:051 24X Fiche: 50-358, 83/02/24, 8303140468.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11lpp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303030661 Clarifies NRC position re procedures for admitting NRC personnel to facilities. Lists of NRC inspectors & personnel likely to visit facility two or more times per yr & at anytime encl. Lists will be updated every 6 months.
KEPPLER, J. G. Region 3, Office of Director 83/02/28 BORGMANN, E. A. Cincinnati Gas & Electric Co. 6pp 17411:023 24X Fiche: 50-358, 83/02/28, 8303030661.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8303150535 Ack receipt of 830228 response to NRC 820924 demand for info to determine whether CPPR-88 should be modified, suspended or revoked. Response will be examined during subsequent insps.
KEPPLER, J. G. Region 3, Office of Director 83/03/11 BORGMANN, E. A. Cincinnati Gas & Electric Co. 2pp 17556:326 24X Fiche: 50-358, 83/03/11, 8303150535.

--8303150543 Forwards response to NRC 820924 demand for info to determine whether CPPR-88 should be modified, suspended or revoked. Affidavit encl.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 83/02/28 DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement KEPPLER, J. G. Region 3, Office of Director 343pp 17556:328 24X Fiche: 50-358, 83/03/11, 8303150535.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

R. Periodic operating reports & related correspondence

8211090617 Forwards "Zimmer Monthly Status Rept." Aug-Sept 1982.
DIRCKS, W. J. Office of the Executive Director for Operations 82/10/26 PALLADINO, N. J. Commissioners 1p 17483:001 24X Fiche: 50-358, 82/10/26, 8211090617.

--8211090619 "Zimmer Monthly Status Rept." Aug-Sept 1982.
* NRC - No Detailed Affiliation Given 82/09/30 82pp 17483:002 24X Fiche: 50-358, 82/10/26, 8211090617.

8303080496 Forwards "Quality Confirmation Program Status, Jan 1983."
BORGMANN, E. A. Cincinnati Gas & Electric Co. 83/02/24 KEPPLER, J. G. Region 3, Office of Director 1p 17450:336 24X Fiche: 50-358, 83/02/24, 8303080496.

--8303080504 "Quality Confirmation Program Status, Jan 1983."
SHAFFER, J. F. Cincinnati Gas & Electric Co. 83/02/24 25pp 17450:337 24X Fiche: 50-358, 83/02/24, 8303080496.

8303220134 Forwards "Quality Confirmation Program Status," monthly rept for Feb 1983, per NRC 821230 ltr.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 83/03/14 KEPPLER, J. G. Region 3, Office of Director 2pp 17649:199 24X Fiche: 50-358, 83/03/14, 8303220134.

--8303220136 "Quality Confirmation Program Status," monthly rept for Feb 1983.
* Cincinnati Gas & Electric Co. 83/03/14 23pp 17649:201 24X Fiche: 50-358, 83/03/14, 8303220134.

8303250136 Forwards monthly status rept for Jan & Feb 1983.
DIRCKS, W. J. Office of the Executive Director for Operations 83/03/18 PALLADINO, N. Commissioners 1p 17710:175 24X Fiche: 50-358, 83/03/18, 8303250136.

--8303250139 Monthly status rept for Jan & Feb 1983.
* Region 3, Office of Director 83/03/18 52pp 17710:176 24X Fiche: 50-358, 83/03/18, 8303250136.

S. Reportable occurrences, LERs & related correspondence

8303040486 Interim deficiency rept re valves not torquing out in closed position. Initially reported on 780822. Valves equipped w/Limitorque size SMB-000 operators. Caused by improper factory adjustment. Limitorque contacted for commitment.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 78/12/05
HIESHMAN, R. F. Region 3, Chicago, Office of the Director 2pp 17373:357 24X Fiche: 50-358, 78/12/05, 8303040486.

8303080178 Suppls 821230 interim deficiency rept re HFA relays mfg between 1974 & 1979 subj to cracking. Initially reported on 820302. Replaced relays also found cracked. Corrective action re-evaluated. Next rept expected by 830415.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 83/02/18 KEPPLER, J. G. Region 3, Office of Director 2pp 17457:339 24X Fiche: 50-358, 83/02/18, 8303080178.

8303080475 Interim deficiency rept re Item M-24, seismic qualification of 13 essential damper operator mounting brackets. American Warming & Ventilating Co seismic repts & design drawings will be approved by Sargent & Lundy by 830331.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 83/02/22 KEPPLER, J. G. Region 3, Office of Director 1p 17453:147 24X Fiche: 50-358, 83/02/22, 8303080475.

8303080239 Interim deficiency rept re unacceptable radiographic & weld for sacrificial shields, containment monorail & vent stack welds. Review of radiographs indicated all but seven welds acceptable. Monorail welds will be reradiographed.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 83/02/23 KEPPLER, J. G. Region 3, Office of Director 2pp 17446:352 24X Fiche: 50-358, 83/02/23, 8303080239.

8303080288 Interim deficiency rept re Item M-45, indeterminate welder qualifications. Review of welder performance documents & associated corrective actions will be completed by 830630.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 83/02/23 KEPPLER, J. G. Region 3, Office of Director 1p 17442:343 24X Fiche: 50-358, 83/02/23, 8303080288.

8303080431 Interim deficiency rept re Item M-67 on lack of procedural qualification for pipe bends. Initially reported on 821109. Appeal to Region III sought for permission to perform requalification of small bore pipe bending operations.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 83/02/23 KEPPLER, J. G. Region 3, Office of Director 2pp 17454:065 24X Fiche: 50-358, 83/02/23, 8303080431.

8303080485 Suppl to final deficiency rept re Item M-53, defective torque switches in Limitorque operators. Switch replacement will be completed 3 months after NRC lifts order immediately suspending const. Followup rept to be submitted by 830731.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 83/02/23 KEPPLER, J. G. Region 3, Office of Director 1p 17450:362 24X Fiche: 50-358, 83/02/23, 8303080485.

8303100221 Interim deficiency rept re Brown Boveri 125-volt dc control device failure on 6.9 kV & 4.16 kV switchgear. Initially reported on 830202. Caused by over travel of operating arm. Next rept expected on 830430.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 83/02/23 KEPPLER, J. G. Region 3, Office of Director 2pp 17489:233 24X Fiche: 50-358, 83/02/23, 8303100221.

8303080434 Interim deficiency rept re lack of insp records for Nelson studs Finalized verification program will be submitted by 830415 Delay due to large amount of site records to be reviewed.
BORGMANN,E A Cincinnati Gas & Electric Co 83/02/24 KEPPLER,J G Region 3, Office of Director 1p 17454 252 24X
Fiche 50-358,83/02/24,8303080434

8303150620 Board Notification 83-26 Forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys Info may affect conclusions re probability of/corrective measures for ATWS
EISENHUT,D G Division of Licensing 83/03/03 PALLADINO,N ,
GILINSKY,V ,AHEARNE,J Commissioners 24pp 17584 097 24X
Fiche 50-000,83/03/03,8303150620

8303220064 Interim deficiency rept re fire damper failure Initially reported on 821029 Hooks on all seismic fire dampers mfg by Air Balance,Inc will be reversed to point open end away from blade Final rept will be submitted by 830615
BORGMANN,E A Cincinnati Gas & Electric Co 83/03/07 KEPPLER,J G Region 3, Office of Director 2pp 17652 78 24X
Fiche 50-358,83/03/07,8303220064

8303220008 Interim deficiency rept re incomplete hydraulic analysis of control rod drive sys piping Initially reported on 821228 Field verification of installed hardware initiated Followup rept will be submitted by 830630
BORGMANN,E A Cincinnati Gas & Electric Co 83/03/08 KEPPLER,J G Region 3, Office of Director 2pp 17652 080 24X
Fiche 50-358,83/03/08,8303220008

8303220007 Interim deficiency rept re insp personnel w/qualifications & certifications inappropriately documented Initially reported on 821208 Followup rept will be issued by 830508
BORGMANN,E A Cincinnati Gas & Electric Co 83/03/10 KEPPLER,J G Region 3, Office of Director 2pp 17652 180 24X
Fiche 50-358,83/03/10,8303220007

8303220174 Final deficiency rept re improper heat number transfer of structural steel Initially reported on 821131 A-36 matl identified correctly Condition determined not reportable per 10CFR50 55(e)
BORGMANN,E A Cincinnati Gas & Electric Co 83/03/10 KEPPLER,J G Region 3, Office of Director 2pp 17658 153 24X
Fiche 50-358,83/03/10,8303220174

8303290499 Interim deficiency rept re GE HMA relays mfg in 1974 & 1976 - 1981 Initially reported on 830225 Const work authorization request prepared to perform corrective actions Next rept will be submitted by 830531
BORGMANN,E A Cincinnati Gas & Electric Co 83/03/21 KEPPLER,J G Region 3, Office of Director 3pp 17723 042 24X
Fiche 50-358,83/03/21,8303290499

8303300245 Supplemental interim deficiency rept re Brown Boveri electric control device for medium voltage circuit breakers Engineering analysis of broken limit switch carrier on device,instructions for insp & corrective action encl
DUVALL,D D Brown Boveri Corp (subs Brown Boveri & Co , Ltd ) 83/03/22 STELLO,V Director's Office, Office of Inspection and Enforcement 10pp 17733 113 24X Fiche 50-358,83/03/22,8303300245

U Congressional/Executive Correspondence

8303110136 Forwards addl info on plant requested in 821220 ltr
PALLADINO,N J Commissioners 83/02/25 UDALL,M K House of Rep , Interior & Insular Affairs 1p 17524 030 24X
Fiche 50-358,83/02/25,8303110136

--8303110143 Forwards info requested by Congressman Udall 821220 ltr Info includes tabulation of welders qualified under special program,welding procedure excerpt,QA procedure,IE Insp Rept 50-358/82-10 excerpt & 10CFR50 55(e) rept
GWYNN,T P Region 3, Office of Director 83/01/31 HUNTER,D R Region 3, Office of Director 147pp 17524 031 24X
Fiche 50-358,83/02/25,8303110136

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL,holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee," Svc list encl
EISENHUT,D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000,83/02/24,8302250505

DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8303030170 Forwards Amends 15 & 4 to Licenses NPF-10 & NPF-15, respectively & notice of issuance & availability Amend modifies emergency preparedness license conditions re medical svcs
KNIGHTON,G W Licensing Branch 3 83/02/17 DIETCH,R Southern California Edison Co COTTON,G D , BERNATH,L San Diego Gas & Electric Co 6pp 17365 265 24X Fiche 50-361,83/02/17,8303030170

--8303030179 Amends 15 & 4 to Licenses NPF-10 & NPF-15, respectively, modifying emergency preparedness license conditions to grant addl time to satisfy requirements of 10CFR50 47(b)(12) re medical svcs
EISENHUT,D G Division of Licensing 83/02/17 4pp 17365 270 24X Fiche 50-361,83/02/17,8303030170

--8303030186 Notice of issuance & availability of Amends 15 & 4 to Licenses NPF-10 & NPF-15, respertively
KNIGHTON,G W Licensing Branch 3 83/02/17 2pp 17365 274 24X Fiche 50-361,83/02/17,8303030170

8303030668 Responds to 821221 submittal re Rev 8 to physical security plan Changes acceptable
KNIGHTON,G W Licensing Branch 3 83/02/23 DIETCH,R Southern California Edison Co COTTON,G D San Diego Gas & Electric Co 4pp 17364 013 24X Fiche 50-206,83/02/23,8303030668

8303250012 Forwards Rev 9 to physical security plan Rev withheld (ref 10CFR73 21)
BASKIN,K P Southern California Edison Co 83/03/23 Division of Licensing 1p 17692 125 24X Fiche 50-206,83/03/23,8303250012

8303250029 Forwards Rev 2 to security force training & qualification plan Rev withheld (ref 10CFR73 21)
BASKIN,K P Southern California Edison Co 83/03/23 Office of Nuclear Reactor Regulation, Director 1p 17692 271 24X
Fiche 50-206,83/03/23,8303250029

8303290503 Forwards IE Enforcement Conference Rept 50-361/83-09 on 830307 No response required
ENGELKEN,R H Region 5, Office of Director 83/03/23 PAPAY,L T Southern California Edison Co 1p 17723 009 24X
Fiche 50-361,83/03/23,8303290503

--8303290508 IE Enforcement Conference Rept 50-361/83-09 on 830307 Major areas discussed noncompliances documented in IE Insp Repts 50-361/83-06 & 50-361/83-08 & concerns identified during ongoing safeguards insps
CREWS,J L , BISHOP,T W Division of Resident Reactor Project & Engineering Programs JOHNSON,A D Region 5, Office of Director 83/03/10 5pp 17723 010 24X Fiche 50-361,83/03/23,8303290503

8303300223 Releases public version of revised emergency plan implementing procedures
FELTON,J M Division of Rules and Records 83/03/25 Document Management Branch 1p 17750 001 24X Fiche 50-206,83/03/25,8303300223

--8303300232 Forwards public version of revised emergency plan implementing procedures,including Procedures EPIP SO1-VIII-1 re recognition & classification of emergencies & EPIP SO123-VIII-10 re emergency coordinator duties
BASKIN,K P Southern California Edison Co 83/03/17
EISENHUT,D G Office of Nuclear Reactor Regulation, Director 1p 17750 002 24X Fiche 50-206,83/03/25,8303300223

--8303300239 Public version of revised emergency plan implementing procedures,including Procedures EPIP SO1-VIII-1 re recognition & classification of emergencies & EPIP SO123-VIII-10 re emergency coordinator duties
MCCLOSKEY,D P Southern California Edison Co 83/03/01 316pp 17750 003 24X Fiche 50-206,83/03/25,8303300223

G Adjudicatory correspondence

8303080149 Decision ALAB-717,affirming ASLB 820111 & 0514 decisions re seismic issues & emergency planning which authorized issuance of full power OL
SHOEMAKER,C J Atomic Safety and Licensing Appeal Panel 83/03/04 71pp 17458 001 24X Fiche 50-361,83/03/04,8303080149

8303090300 Memorializes Commissioner Gilinsky 830214 plant tour,mgt meeting & emergency operations ctr tour
JOOSTEN,J K Commissioners 83/03/07 Commissioners 4pp 17473 151 24X Fiche 50-361,83/03/07,8303090300

8303230183 Petition for review of emergency planning issues re scope & nature of participation of FEMA in licensing process. Guidelines for communications between applicants & FEMA should be established. Certificate of Svc encl. MCCLUNG, C. E. GUARD. MCCLUNG, C. E. Carstens, A. S. MCCLUNG, C. E. Flemming, Anderson, McClung & Finch. 83/03/21. Commissioners. 13pp. 17665.067. 24X Fiche. 50-361, 83/03/21, 8303230183.

P. Operating license stage documents & correspondence

8303240214 Requests negotiations w/DOE to complete & execute contract for disposal of spent nuclear fuel & high level radwaste. BRIDENBECKER, R. Southern California Edison Co. 83/02/02. HODEL, D. F. Energy, Dept. of. 2pp. 17682.186. 24X Fiche. 50-206, 83/02/02, 8303240214.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492.033. 24X Fiche. 50-000, 83/02/16, 8302170082.

8303010002 Notification of contract execution, Mod. 3 to "Followon Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station." Contractor: MIT. LITTLE, M. Administrative Contracts Branch. FIN B-6898. 83/02/17. VOLLMER, R. Division of Engineering. JACKSON, R. NRC - No Detailed Affiliation Given. 1p. 17322.350. 24X Fiche. 50-206, 83/02/17, 8303010002.

--8303010003 Mod. 3, extending period of performance to 831230 & adding requirement of monthly business ltr, to "Followon Simulation of Earthquake Ground Motions For San Onofre Nuclear Generating Station." AKI, K. Massachusetts Institute of Technology. REBELLO, J. E. Division of Contracts. FIN B-6898. 83/02/17. 3pp. 17322.351. 24X Fiche. 50-206, 83/02/17, 8303010002.

8303030170 Forwards Amends 15 & 4 to Licenses NPF-10 & NPF-15, respectively & notice of issuance & availability. Amend modifies emergency preparedness license conditions re medical svcs. KNIGHTON, G. W. Licensing Branch 3. 83/02/17. DIETCH, R. Southern California Edison Co. COTTON, G. D., BERNATH, L. San Diego Gas & Electric Co. 6pp. 17365.265. 24X Fiche. 50-361, 83/02/17, 8303030170.

--8303030179 Amends 15 & 4 to Licenses NPF-10 & NPF-15, respectively, modifying emergency preparedness license conditions to grant addl time to satisfy requirements of 10CFR50.47(b)(12) re medical svcs. EISENHUT, D. G. Division of Licensing. 83/02/17. 4pp. 17365.270. 24X Fiche. 50-361, 83/02/17, 8303030170.

--8303030186 Notice of issuance & availability of Amends 15 & 4 to Licenses NPF-10 & NPF-15, respectively. KNIGHTON, G. W. Licensing Branch 3. 83/02/17. 2pp. 17365.274. 24X Fiche. 50-361, 83/02/17, 8303030170.

8303030710 Board Notification 83-17 forwards JH Conran 830209 affidavit re changes to previous testimony on Unresolved Safety Issue A-17, "Sys Interaction in Nuclear Power Plants." EISENHUT, D. G. Division of Licensing. 83/02/18. PALLADINO, N. J., ROBERTS, T. M., ASSELSTINE, J. A. Commissioners. 6pp. 17363.317. 24X Fiche. 50-000, 83/02/18, 8303030710.

8303100411 Forwards Amends 14 & 3 to Licenses NPF-10 & NPF-15, respectively, safety evaluation & notice of issuance & availability. Amends modify Tech Specs to change control room emergency air cleanup sys flow rate. KNIGHTON, G. W. Licensing Branch 3. 83/02/18. DIETCH, R. Southern California Edison Co. CATTON, G. D. San Diego Gas & Electric Co. 3pp. 17503.157. 24X Fiche. 50-361, 83/02/18, 8303100411.

--8303100475 Amends 14 & 3 to Licenses NPF-10 & NPF-15, respectively, modifying Tech Specs to change control room emergency air cleanup sys flow rate. KNIGHTON, G. W. Licensing Branch 3. 83/02/18. 12pp. 17503.160. 24X Fiche. 50-361, 83/02/18, 8303100411.

--8303100483 Safety evaluation supporting Amends 14 & 3 to Licenses NPF-10 & NPF-15, respectively. * Office of Nuclear Reactor Regulation. Director. 83/02/18. 3pp. 17503.172. 24X Fiche. 50-361, 83/02/18, 8303100411.

--8303100484 Notice of issuance & availability of Amends 14 & 3 to Licenses NPF-10 & NPF-15, respectively. KNIGHTON, G. W. Licensing Branch 3. 83/02/18. 3pp. 17503.175. 24X Fiche. 50-361, 83/02/18, 8303100411.

8303040224 Approves licensee request for 90-day exemption from 10CFR50, App. A, GDC 56 per issuance of Amend 12 to License NPF-10, based on util commitment to meet GDC 56 for noncritical component cooling water loop containment penetrations. EISENHUT, D. G. Division of Licensing. 83/02/22. DIETCH, R. Southern California Edison Co. COTTON, G. D., BERNATH, L. San Diego Gas & Electric Co. 7pp. 17428.001. 24X Fiche. 50-361, 83/02/22, 8303040224.

--8303040230 Exemption for 90 days from 10CFR50, App. A, GDC 56 re noncritical component cooling water loop containment penetrations. KNIGHTON, G. W. Licensing Branch 3. 83/02/22. Southern California Edison Co. 2pp. 17428.007. 24X Fiche. 50-361, 83/02/22, 8303040224.

8303230495 Responds to FOIA request for SECY-82-319. Forwards document. Document also available in PDR under FOIA Request 83-57. FELTON, J. M. Division of Rules and Records. 83/02/23. REAP, M. E. Debevoise & Liberman. 1p. 17673.126. 24X Fiche. 50-361, 83/02/23, 8303230495.

--8208270667 Forwards NRC opposition to motion by AS Carstens, Friends of Earth, et al for emergency stay of full power operation of San Onofre, Units 2 & 3. SLAGGIE, E. L. Office of the General Counsel. SECY-82-319. 82/07/28. 30pp. 17673.127. 24X Fiche. 50-361, 83/02/23, 8303230495.

8303020034 Forwards Affidavit of Svc re distribution of Amend Applications 18 & 4 to Licenses NPF-10 & NPF-15, respectively. MEDFORD, M. O. Southern California Edison Co. 83/02/28. KNIGHTON, G. W. Licensing Branch 3. 4pp. 17354.225. 24X Fiche. 50-361, 83/02/28, 8303020034.

8303040525 Responds to 820327 request for addl info re existing capability for rapid depressurization & DHR w/o PORVs C-E Owners Group scope of work outlined. Performance & probabilistic evaluations should be completed by Mar. 1983. BASKIN, K. P. Southern California Edison Co. 83/02/28. KNIGHTON, G. W. Licensing Branch 3. 2pp. 17366.187. 24X Fiche. 50-361, 83/02/28, 8303040525.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700.303. 24X Fiche. 50-000, 83/03/02, 8303020321.

8303080192 Clarifies & suppls 830224 request for amends to OLs providing addl time to make post-accident sampling sys operable & implement post-accident sampling program per NUREG-0737. BASKIN, K. P. Southern California Edison Co. 83/03/04. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 9pp. 17457.291. 24X Fiche. 50-361, 83/03/04, 8303080192.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl. EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660.176. 24X Fiche. 50-000, 83/03/07, 8303040005.

8303090151 Responds to 830214 request re auxiliary feedwater pump motor bearing qualification & correction of core protection computer software error. Hardware mod to meet SRP & Branch Technical Position 10-1 criteria described. BASKIN, K. P. Southern California Edison Co. 83/03/07. KNIGHTON, G. W. Licensing Branch 3. 4pp. 17469.354. 24X Fiche. 50-361, 83/03/07, 8303090151.

8303180040 Forwards Affidavit of Svc attesting that direct distribution of Amend Applications 19 & 5 to Licenses NPF-10 & NPF-15, respectively, completed per encl svc list. MEDFORD, M. O. Southern California Edison Co. 83/03/16. KNIGHTON, G. W. Licensing Branch 3. 4pp. 17617.244. 24X Fiche. 50-361, 83/03/16, 8303180040.

8303210642 Forwards info re GE Type AK-2-25 reactor trip breakers, in response to NRC request at 830312 & 13 meetings. W/24 oversize drawings, including one illegible drawing. Aperture cards are available in PDR. BASKIN, K. P. Southern California Edison Co. 83/03/17. KNIGHTON, G. W. Licensing Branch 3. 3pp. 17641.001. 24X Fiche. 50-361, 83/03/17, 8303210642.

--8303210652 Rev. 7 to "Emergency Plant Shutdown." CLEMENTS, R., MORGAN, H. E. Southern California Edison Co. 83/01/14. 37pp. 17641.004. 24X Fiche. 50-361, 83/03/17, 8303210642.

--8303210657 Rev 5 to "Control Element Drive Mechanism Motor Generator Set Operation."
MORGAN, H. E. Southern California Edison Co. 82/08/09 11pp
17641:043 24X Fiche: 50-361, 83/03/17, 8303210642

--8303210667 Rev 8 to "Surveillance Requirement Reactor Plant Protection Sys Channel Functional Test."
* Southern California Edison Co. 83/02/23 426pp 17641:056
24X Fiche: 50-361, 83/03/17, 8303210642

--8303210680 Rev 2 to "Surveillance Requirement Reactor Breakers Undervoltage & Shunt Trip Device Circuit Test."
CLIFT, R. L., KATZ, B. Southern California Edison Co. 83/02/02
11pp 17642:122 24X Fiche: 50-361, 83/03/17, 8303210642

--8303210688 Rev 1 to "Plant Protection Sys Response Time Test for Channel A."
KATZ, B. Southern California Edison Co. 83/02/01 382pp
17642:135 24X Fiche: 50-361, 83/03/17, 8303210642

--8303210696 Rev 1 to "Plant Protection Sys Response Time Test for Channel B."
KATZ, B. Southern California Edison Co. 83/02/01 346pp
17643:157 24X Fiche: 50-361, 83/03/17, 8303210642

--8303210704 Rev 1 to "Plant Protection Sys Response Time Test for Channel C."
KATZ, B. Southern California Edison Co. 83/02/01 379pp
17644:143 24X Fiche: 50-361, 83/03/17, 8303210642

--8303210720 Rev 1 to "Plant Protection Sys Response Time Testing for Channel D."
KATZ, B. Southern California Edison Co. 83/02/01 375pp
17645:162 24X Fiche: 50-361, 83/03/17, 8303210642

--8303210741 Rev 0 to "Under-Voltage Tripping Device of GE AK-2-25 Circuit Breakers in Reactor Trip Switchgear."
BIALECKI, L., BALDWIN, P. Southern California Edison Co. 83/03/09
11lpp 17646:177 24X Fiche: 50-361, 83/03/17, 8303210642

--8303210749 Rev 0 to "Insp & Adjustment of Under Voltage Tripping Device."
PORCH, D. R., GRIMES, J. C. Southern California Edison Co. 83/03/08
115pp 17646:288 24X Fiche: 50-361, 83/03/17, 8303210642

--8303210754 "Instruction Manual C-E Inc Reactor Trip Circuit Breaker Switchgear, San Onofre Unit 3."
* Combustion Engineering, Inc. 76/08/02 136pp 17647:043 24X
Fiche: 50-361, 83/03/17, 8303210642

--8303210758 "Instruction Manual C-E Inc Reactor Trip Circuit Breaker Switchgear, San Onofre Unit 2."
* Combustion Engineering, Inc. 76/07/15 144pp 17647:179 24X
Fiche: 50-361, 83/03/17, 8303210642

--8303210760 "Reactor Breakers Undervoltage & Shunt Trip Device Circuit Test."
* Southern California Edison Co. 82/02/26 10pp 17647:323
24X Fiche: 50-361, 83/03/17, 8303210642

--8303210762 Rev 1 to "Reactor Breakers Undervoltage & Shunt Trip Device Circuit Test."
* Southern California Edison Co. 82/06/04 14pp 17647:331
24X Fiche: 50-361, 83/03/17, 8303210642

--8303210767 Rev 2 to "Reactor Breakers Undervoltage & Shunt Trip Device Circuit Test."
* Southern California Edison Co. 83/03/01 7pp 17647:345 24X
Fiche: 50-361, 83/03/17, 8303210642

--8303210773 "Availability Data Program Rept to Nuclear Util Mgt Concerning Power Plants W/C-E NSSS." quarterly rept
* Combustion Engineering, Inc. 81/03/31 27pp 17647:353 24X
Fiche: 50-361, 83/03/17, 8303210642

8303240012 Forwards four documentation & info packages re 830301 & 03 surveillance testing of GE Type AK-2-25 reactor trip breakers. Any addl info on breakers will be transmitted as developed.
BUSHKIN, K. P. Southern California Edison Co. 83/03/21
KNIGHTON, G. W. Licensing Branch 3 146pp 17681:102 24X
Fiche: 50-361, 83/03/21, 8303240012

8303290667 Board Notification 83-31: forwards AZ Public Svc Co evaluation concluding that PORVs not warranted for Palo Verde. NRC review of util evaluation incomplete.
EISENHUT, D. G. Division of Licensing 83/03/21 PALLADINO, N. J., GILINSKY, V., AHEARNE, J. Commissioners 9pp 17745:135 24X
Fiche: 50-000, 83/03/21, 8303290667

--8303110307 Comments on util 821103 ltr re evaluation on safety effects & operational flexibility possibly resulting from installation of pressurizer PORV. Evaluation of info in ref ltr not yet complete.
MATTSON, R. J. Division of Systems Integration (post 811005)
83/02/25 EISENHUT, D. Division of Licensing 2pp 66680:030
24X Fiche: 50-000, 83/03/21, 8303290667

8303280137 Comments on Board Notification 83-38 re failure of GE AK-2 reactor trip breakers. Info may affect NRC conclusions re probability/corrective measures for transients w/o scram events (Unresolved Safety Issue A-9).
EISENHUT, D. G. Division of Licensing 83/03/22 PALLADINO, N., AHEARNE, J. F., ASSELSTINE, T. Commissioners 20pp 17709:310 24X
Fiche: 50-000, 83/03/22, 8303280137

8303310299 Forwards 10 oversize drawings to be used in evaluation of util 810707 & 820430 responses to NRC 811222 ltr re NUREG-0612, "Control of Heavy Loads." Aperture cards are available in PDR.
BASKIN, K. P. Southern California Edison Co. 83/03/29 KNIGHTON, G. W. Licensing Branch 3 2pp 17755:051 24X Fiche: 50-361, 83/03/29, 8303310299

G. Inspection reports, IE Bulletins & correspondence

---

8303040404 Forwards IE Insp Repts 50-206/83-01, 50-361/83-01 & 50-362/83-01 on 830103-21. No noncompliance noted.
BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs 83/02/15 PAPAY, L. T. Southern California Edison Co.
2pp 17374:309 24X Fiche: 50-206, 83/02/15, 8303040404

--8303040414 IE Insp Repts 50-206/83-01, 50-361/83-01 & 50-362/83-01 on 830103-21. No noncompliance noted. Major areas inspected: surveillance program review, design changes & mods, circulars & bulletins & power ascention test procedures.
STEWART, J. P., KIRSCH, D. F. Division of Resident, Reactor Project & Engineering Programs 83/02/15 10pp 17374:311 24X
Fiche: 50-206, 83/02/15, 8303040404

8303100028 Addl response to FOIA request for documents re 821130 special insp rept. App A documents available in PDR under FOIA-82-528. Forwards documents listed in Apps B & C. App C documents partially withheld (ref FOIA Exemption 6).
FELTON, J. H. Division of Rules and Records 83/02/15 GARDE, B. Government Accountability Project 5pp 17493:007 24X
Fiche: 50-206, 83/02/15, 8303100028

--8303100033 Structural details w/handwritten notes indicating violations at facilities.
* Affiliation Unknown 82/11/16 3pp 17493:016 24X
Fiche: 50-206, 83/02/15, 8303100028

--8303100037 Summarizes investigation re E Kent allegations concerning deficient equipment/piping at facilities. Three interviews conducted w/E Kent. No evidence of willful violation of NRC rules found. No further action warranted.
JOUKOFF, P. V. Region 5, Office of Director 82/10/29 Region 5, Office of Director 1p 17493:019 24X Fiche: 50-206, 83/02/15, 8303100028

--8303100041 Submits handwritten notes re E Kent allegations concerning welding at facilities.
SHACKLETON, O. C. NRC - No Detailed Affiliation Given 82/10/12
FOSTER, J. NRC - No Detailed Affiliation Given 2pp 17493:020
24X Fiche: 50-206, 83/02/15, 8303100028

--8303100045 Submits handwritten memo discussing directives from headquarters on action to be taken re E Kent allegations concerning facilities.
SHACKLETON, O. C. NRC - No Detailed Affiliation Given 82/10/14
NRC - No Detailed Affiliation Given 1p 17493:022 24X
Fiche: 50-206, 83/02/15, 8303100028

--8303100050 Forwards WV Johnston 821117 memo to TM Novak transmitting SER re E Kent allegations concerning adequacy of weldments at facilities, per 821029 request. Allegations unsubstantiated & no further action recommended.
EISENHUT, D. G. Division of Licensing 82/11/28 CREWS, J. L. Division of Resident, Reactor Project & Engineering Programs 1p
17493:023 24X Fiche: 50-206, 83/02/15, 8303100028

--8303100067 Forwards EE Kent statement obtained on 821016 & modified statement, per 821019 telcon. W/o encls.
SHACKLETON, O. C. NRC - No Detailed Affiliation Given 82/10/20
SMITH, D. Materials Engineering Branch 1p 17493:040 24X
Fiche: 50-206, 83/02/15, 8303100028

8303110355 Board Notification 83-14: forwards followup info on apparent deficiencies in Midland-Ross superstrut matl.
EISENHUT, D. G. Division of Licensing 83/02/18 PALLADINO, N. Commissioners 24pp 17546:205 24X Fiche: 50-000, 83/02/18, 8303110355

8303150296 Forwards IE Insp Repts 50-361/83-07 & 50-362/83-07 on 830207-11 No noncompliance noted.
BISHOP, T W. Division of Resident, Reactor Project & Engineering Programs. 83/02/24. PAPAY, L T. Southern California Edison Co.
2pp. 17567 061. 24X Fiche 50-361, 83/02/24, 8303150296.

--8303150305 IE Insp Repts 50-361/83-07 & 50-362/83-07 on 830207-11 No noncompliance noted. Major areas inspected evaluation of onsite review committee activities & exam of safety-related equipment procurement & storage problems.
ECKHARDT, J H ; KIRSCH, D F. Division of Resident, Reactor Project & Engineering Programs. 83/02/24. 4pp. 17567 063. 24X Fiche 50-361, 83/02/24, 8303150296.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc.
111pp. 17521 001. 24X Fiche 50-000, 83/02/25, 8212060367.

8303070055 Responds to Action Item 5 of IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." No Bunker-Ramo containment electrical penetration using hard epoxy module design installed.
HAYNES, J G. Southern California Edison Co. 83/03/03. ENGELKEN, R H, Region 5, Office of Director. 1p. 17435 007. 24X
Fiche 50-361, 83/03/03, 8303070055.

8303290453 Forwards IE Insp Repts 50-206/83-04, 50-361/83-06 & 50-362/83-06 on 830103-0212 & IE Insp Rept 50-361/83-08 on 830207-11.
CREWS, J L. Division of Resident, Reactor Project & Engineering Programs. 83/03/04. PAPAY, L T. Southern California Edison Co.
4pp. 17725 285. 24X Fiche 50-206, 83/03/04, 8303290453.

--8303290462 IE Insp Repts 50-206/83-04, 50-361/83-06 & 50-362/83-06 on 830103-0212 No noncompliance noted. Major areas inspected: monthly maint & surveillance activities, followup of LERs, unresolved item & notice of violation.
CHAFFEE, A E ; MILLER, L ; KIRSCH, D F. Region 5, Office of Director.
83/03/04. 17pp. 17725 289. 24X Fiche 50-206, 83/03/04, 8303290453.

--8303290468 IE Insp Rept 50-361/83-08 on 830207-11 No noncompliance noted. Failure to have operable post-accident sampling sys & fully implemented post-accident sampling program & failure to rept violation of License Condition 2.G.
YUHAS, G P ; SHERMAN, C I ; WENSLAWSKI, F. Region 5, Office of Director. 83/03/04. 12pp. 17725 306. 24X Fiche 50-206, 83/03/04, 8303290453.

8303100346 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Westinghouse Model DB-50 reactor trip circuit breakers not installed at facilities.
DIETCH, R. Southern California Edison Co. 83/03/08. ENGELKEN, R H, Region 5, Office of Director. 2pp. 17488 351. 24X
Fiche 50-361, 83/03/08, 8303100346.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc.
117pp. 17611 070. 24X Fiche 50-000, 83/03/11, 8212060380.

8303150311 Confirms understanding, per 830311 telcon, that util will take no action to close reactor trip breakers, except for breaker testing, w/rods de-energized (ref IE Bulletin 83-01).
ENGELKEN, R H. Region 5, Office of Director. 83/03/11. PAPAY, L T. Southern California Edison Co. 1p. 17566 264. 24X
Fiche 50-361, 83/03/11, 8303150311.

8303290247 Forwards IE Insp Repts 50-361/83-05 & 50-362/83-03 on 830124-0220. No noncompliance noted.
BISHOP, T W. Region 5, Office of Director. 83/03/14. PAPAY, L T. Southern California Edison Co. 2pp. 17716 089. 24X
Fiche 50-361, 83/03/14, 8303290247.

--8303290255 IE Insp Repts 50-361/83-05 & 50-362/83-03 on 830124-0220 No noncompliance noted. Major areas inspected: operational safety verification, monthly surveillance, LER review & independent insp effort.
PATE, R J ; STEWART, J P ; KIRSCH, D F. Region 5, Office of Director.
83/03/11. 4pp. 17716 091. 24X Fiche 50-361, 83/03/14, 8303290247.

8303290582 Forwards IE Insp Repts 50-361/83-03 & 50-362/83-04 on 830116-0301. No noncompliance noted.
BISHOP, T W. Region 5, Office of Director. 83/03/14. PAPAY, L T. Southern California Edison Co. 2pp. 17724 006. 24X
Fiche 50-361, 83/03/14, 8303290582.

--8303290590 IE Insp Repts 50-361/83-03 & 50-362/83-04 on 830116-0301 No noncompliance noted. Major areas inspected: followup on items of noncompliance, operational safety verification & design changes & mods.
CHAFFEE, A ; MENDONCA, M ; JOHNSTON, G. Region 5, Office of Director.
83/03/11. 9pp. 17724 008. 24X Fiche 50-361, 83/03/14, 8303290582.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774 352. 24X Fiche 50-000, 83/03/21, 8212060387.

8303230236 EN-83-017 on 830324, notice of violation & proposed imposition of civil penalties in amount of $120,000 to be issued based on three violations re limiting condition of operation exceeded & failure to make timely rept.
BARBER, G ; AXELRAD, J. Director's Office, Office of Inspection and Enforcement. 83/03/21. 1p. 17661 101. 24X Fiche 50-361, 83/03/21, 8303230236.

8303240016 Provides 10-day response to IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." On 830301, three breakers in Unit 2 failed to open. On 830308, one breaker in Unit 3 failed to open. Investigation continuing.
BASKIN, K P. Southern California Edison Co. 83/03/22. ENGELKEN, R H, Region 5, Office of Director. 2pp. 17681 249. 24X
Fiche 50-361, 83/03/22, 8303240016.

8303290503 Forwards IE Enforcement Conference Rept 50-361/83-09 on 830307. No response required.
ENGELKEN, R H. Region 5, Office of Director. 83/03/23. PAPAY, L T. Southern California Edison Co. 1p. 17723 009. 24X
Fiche 50-361, 83/03/23, 8303290503.

--8303290508 IE Enforcement Conference Rept 50-361/83-09 on 830307 Major areas discussed: noncompliances documented in IE Insp Repts 50-361/83-06 & 50-361/83-08 & concerns identified during ongoing safeguards insps.
CREWS, J L ; BISHOP, T W. Division of Resident, Reactor Project & Engineering Programs. JOHNSON, A D. Region 5, Office of Director.
83/03/10. 5pp. 17723 010. 24X Fiche 50-361, 83/03/23, 8303290503.

R Periodic operating reports & related correspondence

8303080095 Forwards monthly operating repts for Dec 1982.
RAY, H B. Southern California Edison Co. 83/01/14. Office of Resource Management, Director. 1p. 17457 216. 24X
Fiche 50-361, 83/01/14, 8303080095.

--8303080097 Monthly operating repts for Dec 1982.
MAYWEATHER, L. Southern California Edison Co. 83/01/14. 10pp.
17457 217. 24X Fiche 50-361, 83/01/14, 8303080095.

8303150566 Forwards monthly operating repts for Jan 1983 & revised pages to monthly operating repts for Sept-Dec 1982 for Unit 2.
RAY, H B. Southern California Edison Co. 83/02/15. Office of Resource Management, Director. 1p. 17567 333. 24X
Fiche 50-361, 83/02/15, 8303150566.

--8303150574 Monthly operating repts for Jan 1983.
MAYWEATHER, L. Southern California Edison Co. 83/02/15. 14pp.
17567 334. 24X Fiche 50-361, 83/02/15, 8303150566.

--8303150592 Revised pages to monthly operating repts for Sept-Dec 1982.
MAYWEATHER, L. Southern California Edison Co. 83/02/15. 9pp.
17567 348. 24X Fiche 50-361, 83/02/15, 8303150566.

S Reportable occurrences, LERs & related correspondence

8302150674 Forwards updated LER 82-159/03L-1. Detailed event analysis submitted.
RAY, H B. Southern California Edison Co. 83/01/31. ENGELKEN, R H, Region 5, Office of Director. 2pp. 17154 123. 24X
Fiche 50-361, 83/01/31, 8302150674.

--8302150685 Updated LER 82-139/03L-1 on 821128, pressure indicator 2PI-8300 for steam generator E-088 on essential plant parameter monitoring sys panel 2I-411 read greater than similar indicator on control room panel CR-52. Cause unknown.
RAY, H B. Southern California Edison Co. 83/01/31. Region 5, Office of Director. 1p. 17154 125. 24X Fiche 50-361, 83/01/31, 8302150674.

8303040502 RO 83-010 on 830208, control room emergency air sys train A declared inoperable for damper insp On 830211, train A remained inoperable due to inability to develop positive pressure of 1/8-inch water gauge in control room. RAY, H B Southern California Edison Co 83/02/14 ENGELKEN, R H Region 5, Office of Director 2pp 17368 011 24X Fiche 50-361, 83/02/14, 8303040502

8303040629 Forwards LER 83-009/03L-0. RAY, H B Southern California Edison Co 83/02/15 ENGELKEN, R H Region 5, Office of Director 1p 17368 345 24X Fiche 50-361, 83/02/15, 8303040629

--8303040636 LER 83-009/03L-0 on 830116, w/purification ion exchanger 2E-074 in svc, RCS chloride concentration determined greater than Tech Spec limits Caused by resin bed exhaustion displacing chloride from ion exchanger Spent bed replaced. RAY, H B Southern California Edison Co 83/02/15 Region 5, Office of Director 1p 17368 346 24X Fiche 50-361, 83/02/15, 8303040629.

8303040618 Forwards LER 83-013/03L-0. RAY, H B Southern California Edison Co 83/02/18 ENGELKEN, R H Region 5, Office of Director 1p 17374 236 24X Fiche 50-361, 83/02/18, 8303040618

--8303040624 LER 83-013/03L-0 on 830120, radiation monitor RI-7807 lost sample flow & declared inoperable Caused by burned out light diode unit in sample flow controller Diode replaced. RAY, H B Southern California Edison Co 83/02/18 Region 5, Office of Director 1p 17374 237 24X Fiche 50-361, 83/02/18, 8303040618.

8303110258 RO 83-018 on 830218, wide-range monitor 3RT-7865-1 found inoperable Followup rept will be submitted by 830304 RAY, H B Southern California Edison Co 83/02/22 ENGELKEN, R H Region 5, Office of Director 1p 17520 068 24X Fiche 50-361, 83/02/22, 8303110258

8303180265 Forwards LER 83-017/03L-0. RAY, H B Southern California Edison Co 83/02/23 ENGELKEN, R H Region 5, Office of Director 1p 17616 166 24X Fiche 50-361, 83/02/23, 8303180265

--8303180272 LER 83-017/03L-0 on 830124, exam confirmed continuing alarms on containment high range radiation monitor RI-7820 were defeating function Caused by 2 R/hr setpoint being too close to normal reading Tech Spec amend to be submitted. RAY, H B Southern California Edison Co 83/02/23 Region 5, Office of Director 1p 17616 170 24X Fiche 50-361, 83/02/23, 8303180265

8303110225 Forwards LER 83-011/03L-0. RAY, H B Southern California Edison Co 83/02/25 ENGELKEN, R H Region 5, Office of Director 1p 17518 353 24X Fiche 50-361, 83/02/25, 8303110225

--8303110230 LER 83-011/03L-0 on 830127, control element assembly calculator 1 revealed loss of position indication for control element assembly 28 Caused by faulty isolation amplifier card Card replaced. RAY, H B Southern California Edison Co 83/02/25 Region 5, Office of Director 1p 17518 354 24X Fiche 50-361, 83/02/25, 8303110225

8303110267 Forwards LER 83-010/01T-0. RAY, H B Southern California Edison Co 83/02/25 ENGELKEN, R H Region 5, Office of Director 2pp 17568 319 24X Fiche 50-361, 83/02/25, 8303110267.

--8303110273 LER 83-010/01T-0 on 830211, w/Unit 2 in Mode 3 & Unit 3 in Mode 5, CREACUS Train A failed to maintain 1/8-inch positive pressure in control room during testing Caused by air leakage from boundary Design changes made to fans. RAY, H B Southern California Edison Co 83/02/25 Region 5, Office of Director 2pp 17568 321 24X Fiche 50-361, 83/02/25, 8303110267

8303110115 Forwards LER 83-014/03L-0 Detailed event analysis encl. RAY, H B Southern California Edison Co 83/03/02 ENGELKEN, R H Region 5, Office of Director 2pp 17517 320 24X Fiche 50-361, 83/03/02, 8303110115

--8303110142 LER 83-014/03L-0 on 830130, during alignment of withdrawn control element assemblies (CEAs), CEAs 79 & 82 slipped into fully inserted position Caused by defective coil driver actuation card & sticking grippers Investigation continuing. RAY, H B Southern California Edison Co 83/03/02 Region 5, Office of Director 1p 17517 322 24X Fiche 50-361, 83/03/02, 8303110115

8303150620 Board Notification 83-26 forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys Info may affect conclusions re probability of/corrective measures for ATWS. EISENHUT, D G Division of Licensing 83/03/03 PALLADINO, N Commissioners 24pp 17584 097 24X Fiche 50-000, 83/03/03, 8303150620

8303180481 Forwards LER 83-018/01T-0. RAY, H B Southern California Edison Co 83/03/03 ENGELKEN, R H Region 5, Office of Director 1p 17622 181 24X Fiche 50-361, 83/03/03, 8303180481

--8303180487 LER 83-018/01T-0 on 830218, while in Mode 5, determined sample sys piping associated w/plant vent stack monitor incorrectly installed Cause not stated Proper piping configuration established & monitor declared operable on 830223. RAY, H B , MOODY, W Southern California Edison Co 83/03/03 Region 5, Office of Director 1p 17622 182 24X Fiche 50-361, 83/03/03, 8303180481

8303180520 Forwards LER 83-016/03L-0. RAY, H B Southern California Edison Co 83/03/07 ENGELKEN, R H Region 5, Office of Director 1p 17621 336 24X Fiche 50-361, 83/03/07, 8303180520

--8303180525 LER 83-016/03L-0 on 830205, during overboarding of hotwells to reduce chloride concentrations, condensate storage tank T121 drawn below Tech Spec limit Caused by lack of coordination of plant evolutions. RAY, H B Southern California Edison Co 83/03/07 Region 5, Office of Director 1p 17621 337 24X Fiche 50-361, 83/03/07, 8303180520.

8303210164 PNO-V-83-011 three GE reactor trip breakers on Unit 2 & one on Unit 3 failed to open during surveillance testing of undervoltage coils Both units will remain shut down until breaker concerns resolved News release not planned. KIRSCH, D F Region 5, Office of Director 83/03/11 1p 17632 184 24X Fiche 50-361, 83/03/11, 8303210164

8303290376 ROs 83-019 & 83-023 on 830303 & 08, during Surveillance Test Procedure SO23-II-11 161, reactor trip breakers failed to trip on undervoltage Cause unknown GE investigation continuing. RAY, H B Southern California Edison Co 83/03/11 ENGELKEN, R H Region 5, Office of Director 2pp 17716 271 24X Fiche 50-361, 83/03/11, 8303290376

8303290492 Forwards LER 83-015/03L-0. RAY, H B Southern California Edison Co 83/03/11 ENGELKEN, R H Region 5, Office of Director 1p 17724 163 24X Fiche 50-361, 83/03/11, 8303290492

--8303290494 LER 83-015/03L-0 on 830211, reactor coolant cold leg temp (Tc) exceeded limiting conditions of operation Associated action statement invoked Caused by failure of operations personnel to properly monitor & control Tc. RAY, H B Southern California Edison Co 83/03/11 Region 5, Office of Director 1p 17724 164 24X Fiche 50-361, 83/03/11, 8303290492.

8303180507 PNO-V-83-011A on 830313, improper operation of reactor trip breaker demonstrated Possibly caused by resistance in mechanical latching mechanism associated w/undervoltage trip device Similar failures in Mar & Jul 1982 not reported. KIRSCH, D F Region 5, Office of Director 83/03/14 1p 17621 331 24X Fiche 50-361, 83/03/14, 8303180507

8303290277 Forwards LER 83-021/03L-0. RAY, H B Southern California Edison Co 83/03/18 ENGELKEN, R H Region 5, Office of Director 2pp 17716 120 24X Fiche 50-361, 83/03/18, 8303290277.

--8303290286 LER 83-021/03L-0 on 830217, isolation damper FV-9761 associated w/emergency ventilation supply Unit A failed to cycle Caused by damper jammed closed Further investigation into cause under evaluation Damper & controller exercised. RAY, H B Southern California Edison Co 83/03/18 Region 5, Office of Director 1p 1771o 122 24X Fiche 50-361, 83/03/18, 8303290277.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT, D G Division o- Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000, 83/02/24, 8302250505

8303070039 Identifies all requests for site visits to conduct operator licensing exams or instructor certification exams, in response to Generic Ltr 83-01
BASKIN, K P Southern California Edison Co 83/03/03 EISENHUT, D G Division of Licensing 2pp 17435 288 24X Fiche 50-206, 83/03/03, 8303070039

DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

8303040516 Forwards executive summary of Plant Operations Personnel Review Committee rept, per 821115 commitment Plant operations personnel experienced & adequately trained to conduct power operations
DIETCH, R Southern California Edison Co 83/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 12pp 17374 049 24X Fiche 50-362, 83/03/02, 8303040516

F Security, medical, emergency & fire protection plans

8303030170 Forwards Amends 15 & 4 to Licenses NPF-10 & NPF-15, respectively & notice of issuance & availability Amend modifies emergency preparedness license conditions re medical svcs
KNIGHTON, G W Licensing Branch 3 83/02/17 DIETCH, R Southern California Edison Co 6pp 17365 265 24X Fiche 50-361, 83/02/17, 8303030170

--8303030179 Amends 15 & 4 to Licenses NPF-10 & NPF-15, respectively, modifying emergency preparedness license conditions to grant addl time to satisfy requirements of 10CFR50 47(b)(12) re medical svcs
EISENHUT, D G Division of Licensing 83/02/17 4pp 17365 270 24X Fiche 50-361, 83/02/17, 8303030170

--8303030186 Notice of issuance & availability of Amends 15 & 4 to Licenses NPF-10 & NPF-15, respectively
KNIGHTON, G W Licensing Branch 3 83/02/17 2pp 17365 274 24X Fiche 50-361, 83/02/17, 8303030170

8303030668 Responds to 821221 submittal re Rev 8 to physical security plan Changes acceptable
KNIGHTON, G W Licensing Branch 3 83/02/23 DIETCH, R Southern California Edison Co COTTON, G D San Diego Gas & Electric Co 4pp 17364 013 24X Fiche 50-206, 83/02/23, 8303030668

8303250012 Forwards Rev 9 to physical security plan Rev withheld (ref 10CFR73 21)
BASKIN, K P Southern California Edison Co 83/03/23 Division of Licensing 1p 17692 125 24X Fiche 50-206, 83/03/23, 8303250012

8303250029 Forwards Rev 2 to security force training & qualification plan Rev withheld (ref 10CFR73 21)
BASKIN, K P Southern California Edison Co 83/03/23 Office of Nuclear Reactor Regulation, Director 1p 17692 271 24X Fiche 50-206, 83/03/23, 8303250029

8303300223 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/03/25 Document Management Branch 1p 17750 001 24X Fiche 50-206, 83/03/25, 8303300223

--8303300232 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP SOI-VIII-1 re recognition & classification of emergencies & EPIP SO123-VIII-10 re emergency coordinator duties
BASKIN, K P Southern California Edison Co 83/03/17
EISENHUT, D G Office of Nuclear Reactor Regulation, Director 1p 17750 002 24X Fiche 50-206, 83/03/25, 8303300223

--8303300239 Public version of revised emergency plan implementing procedures, including Procedures EPIP SOI-VIII-1 re recognition & classification of emergencies & EPIP SO123-VIII-10 re emergency coordinator duties
MCCLOSKEY, D P Southern California Edison Co 83/03/01 316pp 17750 003 24X Fiche 50-206, 83/03/25, 8303300223

G Adjudicatory correspondence

8303080149 Decision ALAB-717, affirming ASLB 820111 & 0514 decisions re seismic issues & emergency planning which authorized issuance of full power OL
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/03/04 71pp 17450 001 24X Fiche 50-361, 83/03/04, 8303080149

8303090300 Memorializes Commissioner Gilinsky 830214 plant tour, mgt meeting & emergency operations ctr tour
JOOSTEN, J K Commissioners 83/03/07 Commissioners 4pp 17473 151 24X Fiche 50-361, 83/03/07, 8303090300

8303230183 Petition for review of emergency planning issues re scope & nature of participation of FEMA in licensing process Guidelines for communications between applicants & FEMA should be established Certificate of Svc encl
MCCLUNG, C E GUARD MCCLUNG, C E Carstens, A S MCCLUNG, C E Flemming, Anderson, McClung & Finch 83/03/21 Commissioners 13pp 17665 067 24X Fiche 50-361, 83/03/21, 8303230183

P Operating license stage documents & correspondence

8303240214 Requests negotiations w/DOE to complete & execute contract for disposal of spent nuclear fuel & high level radwaste
BRIDENBECKER, R Southern California Edison Co 83/02/02
HODEL, D P Energy, Dept of 2pp 17682 186 24X Fiche 50-206, 83/02/02, 8303240214

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24X Fiche 50-000, 83/02/16, 8302170082

8303010002 Notification of contract execution, Mod 3 to "Followon Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station " Contractor MIT
LITTLE, M Administrative Contracts Branch FIN B-6898 83/02/17
VOLLMER, R Division of Engineering 1p 17322 350 24X Fiche 50-362, 83/02/17, 8303010002

--8303010003 Mod 3, extending period of performance to 831230 & adding requirement of monthly business ltr, to "Followon Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station "
AKI, K Massachusetts Institute of Technology 83/02/17 3pp 17322 351 24X Fiche 50-362, 83/02/17, 8303010002

8303030170 Forwards Amends 15 & 4 to Licenses NPF-10 & NPF-15, respectively & notice of issuance & availability Amend modifies emergency preparedness license conditions re medical svcs
KNIGHTON, G W Licensing Branch 3 83/02/17 DIETCH, R Southern California Edison Co COTTON, G D , BERNATH, L San Diego Gas & Electric Co 6pp 17365 265 24X Fiche 50-361, 83/02/17, 8303030170

--8303030179 Amends 15 & 4 to Licenses NPF-10 & NPF-15, respectively, modifying emergency preparedness license conditions to grant addl time to satisfy requirements of 10CFR50 47(b)(12) re medical svcs
EISENHUT, D G Division of Licensing 83/02/17 4pp 17365 270 24X Fiche 50-361, 83/02/17, 8303030170

--8303030186 Notice of issuance & availability of Amends 15 & 4 to Licenses NPF-10 & NPF-15, respectively
KNIGHTON, G W Licensing Branch 3 83/02/17 2pp 17365 274 24X Fiche 50-361, 83/02/17, 8303030170

8303030710 Board Notification 83-17 Forwards JH Conran 830209 affidavit re changes to previous testimony on Unresolved Safety Issue A-17, "Sys Interaction in Nuclear Power Plants "
EISENHUT, D G Division of Licensing 83/02/18 PALLADINO, N J Commissioners 6pp 17363 317 24X Fiche 50-000, 83/02/18, 8303030710

8303100411 Forwards Amends 14 & 3 to Licenses NPF-10 & NPF-15, respectively, safety evaluation & notice of issuance & availability Amends modify Tech Specs to change control room emergency air cleanup sys flow rate
KNIGHTON, G W Licensing Branch 3 83/02/18 DIETCH, R Southern California Edison Co CATTON, G D San Diego Gas & Electric Co 3pp 17503 157 24X Fiche 50-361, 83/02/18, 8303100411

--8303100475 Amends 14 & 3 to Licenses NPF-10 & NPF-15, respectively, modifying Tech Specs to change control room emergency air cleanup sys flow rate
KNIGHTON, G W Licensing Branch 3 83/02/18 12pp 17503 160 24X Fiche 50-361, 83/02/18, 8303100411

--8303100483 Safety evaluation supporting Amends 14 & 3 to Licenses NPF-10 & NPF-15, respectively
* Office of Nuclear Reactor Regulation, Director 83/02/18 3pp 17503 172 24X Fiche 50-361, 83/02/18, 8303100411

# DOCKETED ITEMS

--8303100484 Notice of issuance & availability of Amends 14 & 3 to Licenses NPF-10 & NPF-15, respectively.
KNIGHTON, G. W. Licensing Branch 3 83/02/18 3pp 17503:175
24X Fiche 50-361, 83/02/18, 8303100411

8303230495 Responds to FOIA request for SECY-82-319. Forwards document. Document also available in PDR under FOIA Request 83-57.
FELTON, J. M. Division of Rules and Records 83/02/23 REAP, M. E. Debevoise & Liberman 1p 17673:126 24X Fiche 50-362, 83/02/23, 8303230495.

--8208270667 Forwards NRC opposition to motion by AS Carstens, Friends of Earth, et al for emergency stay of full power operation of San Onofre, Units 2 & 3.
SLAGGIE, E. L. Office of the General Counsel SECY-82-319
82/07/28 30pp 17673:127 24X Fiche 50-362, 83/02/23, 8303230495.

8303020034 Forwards Affidavit of Svc re distribution of Amend Applications 18 & 4 to Licenses NPF-10 & NPF-15, respectively.
MEDFORD, M. O. Southern California Edison Co. 83/02/28
KNIGHTON, G. W. Licensing Branch 3 4pp 17354:225 24X
Fiche 50-361, 83/02/28, 8303020034.

8303040525 Responds to 820327 request for addl info re existing capability for rapid depressurization & DHR w/o PORVs. C-E Owners Group scope of work outlined. Performance & probabilistic evaluations should be completed by Mar 1983.
BASKIN, K. P. Southern California Edison Co. 83/02/28. KNIGHTON, G. W. Licensing Branch 3 2pp 17366:187 24X Fiche 50-361, 83/02/28, 8303040525.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X
Fiche 50-000, 83/03/02, 8303020321.

8303080192 Clarifies & supplis 830224 request for amends to OLs providing addl time to make post-accident sampling sys operable & implement post-accident sampling program per NUREG-0737.
BASKIN, K. P. Southern California Edison Co. 83/03/04 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 9pp 17457:291
24X Fiche 50-361, 83/03/04, 8303080192.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp 17660:176 24X
Fiche 50-000, 83/03/07, 8303040005.

8303090151 Responds to 830214 request re auxiliary feedwater pump motor bearing qualification & correction of core protection computer software error. Hardware mod to meet SRP & Branch Technical Position 10-1 criteria described.
BASKIN, K. P. Southern California Edison Co. 83/03/07 KNIGHTON, G. W. Licensing Branch 3 4pp 17469:354 24X Fiche 50-361, 83/03/07, 8303090151.

8303180040 Forwards Affidavit of Svc attesting that direct distribution of Amend Applications 19 & 5 to Licenses NPF-10 & NPF-15, respectively, completed per encl svc list.
MEDFORD, M. O. Southern California Edison Co. 83/03/16
KNIGHTON, G. W. Licensing Branch 3 4pp 17617:244 24X
Fiche 50-361, 83/03/16, 8303180040.

8303210642 Forwards info re GE Type AK-2-25 reactor trip breakers, in response to NRC request at 830312 & 13 meetings. W/24 oversize drawings, including one illegible drawing. Aperture cards are available in PDR.
BASKIN, K. P. Southern California Edison Co. 83/03/17 KNIGHTON, G. W. Licensing Branch 3 3pp 17641:001 24X Fiche 50-361, 83/03/17, 8303210642.

--8303210652 Rev 7 to "Emergency Plant Shutdown."
CLEMENTS, R., MORGAN, H. E. Southern California Edison Co. 83/01/14
37pp 17641:004 24X Fiche 50-361, 83/03/17, 8303210642.

--8303210657 Rev 5 to "Control Element Drive Mechanism Motor Generator Set Operation."
MORGAN, H. E. Southern California Edison Co. 82/08/09 11pp
17641:043 24X Fiche 50-361, 83/03/17, 8303210642.

--8303210667 Rev 8 to "Surveillance Requirement Reactor Plant Protection Sys Channel Functional Test."
* Southern California Edison Co. 83/02/23 426pp 17641:056
24X Fiche 50-361, 83/03/17, 8303210642.

--8303210680 Rev 2 to "Surveillance Requirement Reactor Breakers Undervoltage & Shunt Trip Device Circuit Test."
CLIFT, R. L., KATZ, B. Southern California Edison Co. 83/02/02
11pp 17642:122 24X Fiche 50-361, 83/03/17, 8303210642.

--8303210688 Rev 1 to "Plant Protection Sys Response Time Test for Channel A."
KATZ, B. Southern California Edison Co. 83/02/01 382pp
17642:135 24X Fiche 50-361, 83/03/17, 8303210642.

--8303210696 Rev 1 to "Plant Protection Sys Response Time Test for Channel B."
KATZ, B. Southern California Edison Co. 83/02/01 346pp
17643:157 24X Fiche 50-361, 83/03/17, 8303210642.

--8303210704 Rev 1 to "Plant Protection Sys Response Time Test for Channel C."
KATZ, B. Southern California Edison Co. 83/02/01 379pp
17644:143 24X Fiche 50-361, 83/03/17, 8303210642.

--8303210720 Rev 1 to "Plant Protection Sys Response Time Testing for Channel D."
KATZ, B. Southern California Edison Co. 83/02/01 375pp
17645:162 24X Fiche 50-361, 83/03/17, 8303210642.

--8303210741 Rev 0 to "Under-Voltage Tripping Device of GE AK-2-25 Circuit Breakers in Reactor Trip Switchgear."
BIALECKI, L., BALDWIN, P. Southern California Edison Co. 83/03/09
11lpp 17646:177 24X Fiche 50-361, 83/03/17, 8303210642.

--8303210749 Rev 0 to "Insp & Adjustment of Under Voltage Tripping Device."
PORCH, D. R., GRIMES, J. C. Southern California Edison Co. 83/03/08
115pp 17646:288 24X Fiche 50-361, 83/03/17, 8303210642.

--8303210754 "Instruction Manual C-E, Inc Reactor Trip Circuit Breaker Switchgear, San Onofre Unit 3."
* Combustion Engineering, Inc. 76/08/02 136pp 17647:043 24X
Fiche 50-361, 83/03/17, 8303210642.

--8303210767 Rev 2 to "Reactor Breakers Undervoltage & Shunt Trip Device Circuit Test."
* Southern California Edison Co. 83/03/01 7pp 17647:345 24X
Fiche 50-361, 83/03/17, 8303210642.

--8303210773 "Availability Data Program Rept to Nuclear Util Mgt Concerning Power Plants W/C-E NSSS," quarterly rept.
* Combustion Engineering, Inc. 81/03/31 27pp 17647:353 24X
Fiche 50-361, 83/03/17, 8303210642.

8303240012 Forwards four documentation & info packages re 830301 & 03 surveillance testing of GE Type AK-2-25 reactor trip breakers. Any addl info on breakers will be transmitted as developed.
BUSHKIN, K. P. Southern California Edison Co. 83/03/21.
KNIGHTON, G. W. Licensing Branch 3 146pp 17681:102 24X
Fiche 50-361, 83/03/21, 8303240012.

8303290667 Board Notification 83-31 forwards AZ Public Svc Co evaluation concluding that PORVs not warranted for Palo Verde. NRC review of util evaluation incomplete.
EISENHUT, D. G. Division of Licensing 83/03/21 PALLADINO, N. J., GILINSKY, V., AHEARNE, J. Commissioners 9pp 17745:135 24X
Fiche 50-000, 83/03/21, 8303290667.

8303280137 Comments on Board Notification 83-38 re failure of GE AK-2 reactor trip breakers. Info may affect NRC conclusions re probability/corrective measures for transients w/o scram events (Unresolved Safety Issue A-9).
EISENHUT, D. G. Division of Licensing 83/03/22 PALLADINO, N., GILINSKY, V., ROBERTS, T. M. Commissioners 20pp 17709:310 24X
Fiche 50-000, 83/03/22, 8303280137.

8303310299 Forwards 10 oversize drawings to be used in evaluation of util 810707 & 820430 responses to NRC 811222 ltr re NUREG-0612, "Control of Heavy Loads." Aperture cards are available in PDR.
BASKIN, K. P. Southern California Edison Co. 83/03/29 KNIGHTON, G. W. Licensing Branch 3 2pp 17755:051 24X Fiche 50-361, 83/03/29, 8303310299.

## Q. Inspection reports, IE Bulletins & correspondence

8303040404 Forwards IE Insp Repts 50-206/83-01, 50-361/83-01 & 50-362/83-01 on 830103-21. No noncompliance noted.
BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs 83/02/15 PAPAY, L. T. Southern California Edison Co.
2pp 17374:309 24X Fiche 50-206, 83/02/15, 8303040404.

--8303040414 IE Insp Repts 50-206/83-01, 50-361/83-01 & 50-362/83-01 on 830103-21 No noncompliance noted Major areas inspected: surveillance program review, design changes & mods, circulars & bulletins & power ascention test procedures. STEWART, J. P., KIRSCH, D. F. Division of Resident, Reactor Project & Engineering Programs 83/02/15 10pp 17374 311 24X Fiche 50-206, 83/02/15, 8303040404

8303100028 Addl response to FOIA request for documents re 821130 special insp rept App A documents available in PDR under FOIA-82-528 Forwards documents listed in Apps B & C App C documents partially withheld (ref FOIA Exemption 6). FELTON, J. M. Division of Rules and Records 83/02/15 GARDE, B Government Accountability Project 5pp 17493 007 24X Fiche 50-362, 83/02/15, 8303100028

--8303100033 Structural details w/handwritten notes indicating violations at facilities. * Affiliation Unknown. 82/11/16 3pp 17493 016 24X Fiche 50-362, 83/02/15, 8303100028

--8303100037 Summarizes investigation re E Kent allegations concerning deficient equipment/piping at facilities. Three interviews conducted w/E Kent. No evidence of willful violation of NRC rules found. No further action warranted. JOUKOFF, P. V. Region 5, Office of Director 82/10/29 Region 5, Office of Director 1p 17493 019 24X Fiche 50-362, 83/02/15, 8303100028

--8303100041 Submits handwritten notes re E Kent allegations concerning welding at facilities. SHACKLETON, O. C. NRC - No Detailed Affiliation Given 82/10/12 FOSTER, J. NRC - No Detailed Affiliation Given 2pp 17493 020 24X Fiche 50-362, 83/02/15, 8303100028

--8303100045 Submits handwritten memo discussing directives from headquarters on action to be taken re E Kent allegations concerning facilities. SHACKLETON, O. C. NRC - No Detailed Affiliation Given 82/10/14 NRC - No Detailed Affiliation Given 1p 17493 022 24X Fiche 50-362, 83/02/15, 8303100028

--8303100050 Forwards WV Johnston 821117 memo to TM Novak transmitting SER re E Kent allegations concerning adequacy of weldments at facilities, per 821029 request. Allegations unsubstantiated & no further action recommended. EISENHUT, D. G. Division of Licensing 82/11/28 CREWS, J. L. Division of Resident, Reactor Project & Engineering Programs 1p 17493 023 24X Fiche 50-362, 83/02/15, 8303100028

--8303100067 Forwards EE Kent statement obtained on 821016 & modified statement, per 821019 telcon. W/o encls. SHACKLETON, O. C. NRC - No Detailed Affiliation Given 82/10/20 SMITH, D. Materials Engineering Branch 1p 17493 040 24X Fiche 50-362, 83/02/15, 8303100028

8303110355 Board Notification 83-14, forwards followup info on apparent deficiencies in Midland-Ross superstrut matl. EISENHUT, D. G. Division of Licensing 83/02/18 PALLADINO, N. Commissioners 24pp 17546 205 24X Fiche 50-000, 83/02/18, 8303110355

8303150296 Forwards IE Insp Repts 50-361/83-07 & 50-362/83-07 on 830207-11. No noncompliance noted. BISHOP, T. W. Division of Resident, Reactor Project & Engineering Programs 83/02/24 PAPAY, L. T. Southern California Edison Co. 2pp 17567 061 24X Fiche 50-361, 83/02/24, 8303150296

--8303150305 IE Insp Repts 50-361/83-07 & 50-362/83-07 on 830207-11. No noncompliance noted. Major areas inspected: evaluation of onsite review committee activities & exam of safety-related equipment procurement & storage problems. ECKHARDT, J. H., KIRSCH, D. F. Division of Resident, Reactor Project & Engineering Programs 83/02/24 4pp 17567 063 24X Fiche 50-361, 83/02/24, 8303150296

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 111pp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367

8303070055 Responds to Action Item 5 of IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." No Bunker-Ramo containment electrical penetration using hard epoxy module design installed. HAYNES, J. G. Southern California Edison Co. 83/03/03 ENGELKEN, R. H. Region 5, Office of Director 1p 17433 007 24X Fiche 50-361, 83/03/03, 8303070055

8303290453 Forwards IE Insp Repts 50-206/83-04, 50-361/83-06 & 50-362/83-06 on 830103-0212 & IE Insp Rept 50-361/83-08 on 830207-11. CREWS, J. L. Division of Resident, Reactor Project & Engineering Programs 83/03/04 PAPAY, L. T. Southern California Edison Co. 4pp 17725 285 24X Fiche 50-206, 83/03/04, 8303290453

--8303290462 IE Insp Repts 50-206/83-04, 50-361/83-06 & 50-362/83-06 on 830103-0212. No noncompliance noted. Major areas inspected: monthly maint & surveillance activities, followup of LERs, unresolved item & notice of violation. CHAFFEE, A. E., MILLER, L., KIRSCH, D. F. Region 5, Office of Director 83/03/04 17pp 17725 289 24X Fiche 50-206, 83/03/04, 8303290453

8303100346 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Westinghouse Model DB-50 reactor trip circuit breakers not installed at facilities. DIETCH, R. Southern California Edison Co. 83/03/08 ENGELKEN, R. H. Region 5, Office of Director 2pp 17488 351 24X Fiche 50-361, 83/03/08, 8303100346

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380

8303150311 Confirms understanding, per 830311 telcon, that util will take no action to close reactor trip breakers, except for breaker testing, w/rods de-energized (ref IE Bulletin 83-01). ENGELKEN, R. H. Region 5, Office of Director 83/03/11 PAPAY, L. T. Southern California Edison Co. 1p 17566 264 24X Fiche 50-361, 83/03/11, 8303150311

8303290247 Forwards IE Insp Repts 50-361/83-05 & 50-362/83-03 on 830124-0220. No noncompliance noted. BISHOP, T. W. Region 5, Office of Director 83/03/14 PAPAY, L. T. Southern California Edison Co. 2pp 17716 089 24X Fiche 50-361, 83/03/14, 8303290247

--8303290255 IE Insp Repts 50-361/83-05 & 50-362/83-03 on 830124-0220. No noncompliance noted. Major areas inspected: operational safety verification, monthly surveillance, LER review & independent insp effort. PATE, R. J., STEWART, J. P., KIRSCH, D. F. Region 5, Office of Director 83/03/11 4pp 17716 091 24X Fiche 50-361, 83/03/14, 8303290247

8303290582 Forwards IE Insp Repts 50-361/83-03 & 50-362/83-04 on 830116-0301. No noncompliance noted. BISHOP, T. W. Region 5, Office of Director 83/03/14 PAPAY, L. T. Southern California Edison Co. 2pp 17724 006 24X Fiche 50-361, 83/03/14, 8303290582

--8303290590 IE Insp Repts 50-361/83-03 & 50-362/83-04 on 830116-0301. No noncompliance noted. Major areas inspected: followup on items of noncompliance, operational safety verification & design changes & mods. CHAFFEE, A., MENDONCA, M., JOHNSTON, G. Region 3, Office of Director 83/03/11 9pp 17724 008 24X Fiche 50-361, 83/03/14, 8303290582

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp 17774 352 24X Fiche 50-000, 83/03/21, 8212060387

8303240016 Provides 10-day response to IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." On 830301, three breakers in Unit 2 failed to open. On 830308, one breaker in Unit 3 failed to open. Investigation continuing. BASKIN, R. P. Southern California Edison Co. 83/03/22 ENGELKEN, R. H. Region 5, Office of Director 2pp 17681 249 24X Fiche 50-361, 83/03/22, 8303240016

R Periodic operating reports & related correspondence

8303080095 Forwards monthly operating repts for Dec 1982. RAY, H. B. Southern California Edison Co. 83/01/14 Office of Resource Management, Director 1p 17457 216 24X Fiche 50-361, 83/01/14, 8303080095

--8303080097 Monthly operating repts for Dec 1982. MAYWEATHER, L. Southern California Edison Co. 83/01/14 10pp 17457 217 24X Fiche 50-361, 83/01/14, 8303080095

8303150566 Forwards monthly operating repts for Jan 1983 & revised pages to monthly operating repts for Sept-Dec 1982 for Unit 2.
RAY,H.B. Southern California Edison Co. 83/02/15 Office of Resource Management, Director 1p 17567 333 24X
Fiche 50-361,83/02/15,8303150566.

--8303150574 Monthly operating repts for Jan 1983.
MAYWEATHER,L. Southern California Edison Co. 83/02/15 14pp.
17567 334 24X Fiche 50-361,83/02/15,8303150566.

--8303150592 Revised pages to monthly operating repts for Sept-Dec 1982.
MAYWEATHER,L. Southern California Edison Co. 83/02/15 9pp.
17567 348 24X Fiche 50-361,83/02/15,8303150566.

S Reportable occurrences, LERs & related correspondence
---

8303040502 RO 83-010 on 830208,control room emergency air sys train A declared inoperable for damper insp.On 830211,train A remained inoperable due to inability to develop positive pressure of 1/8-inch water gauge in control room.
RAY,H.B. Southern California Edison Co. 83/02/14 ENGELKEN,R.H.
Region 5, Office of Director 2pp 17368 011 24X
Fiche 50-361,83/02/14,8303040502.

8303040520 Forwards LER 83-003/03L-0.
RAY,H.B. Southern California Edison Co. 83/02/17 ENGELKEN,R.H.
Region 5, Office of Director 1p 17374 195 24X
Fiche 50-362,83/02/17,8303040520.

--8303040526 LER 83-003/03L-0 on 830118,pressurizer safety valve position indicators declared inoperable.Caused by poorly attached position indication brackets.Brackets replaced & after functional test & calibr,indicators declared operable.
RAY,H.B. Southern California Edison Co. 83/02/17 Region 5,
Office of Director 1p 17374 196 24X Fiche 50-362,83/02/17,
8303040520.

8303040567 Forwards LER 83-002/03L-0.
RAY,H.B. Southern California Edison Co. 83/02/17 ENGELKEN,R.H.
Region 5, Office of Director 2pp 17373 292 24X
Fiche 50-362,83/02/17,8303040567.

--8303040573 LER 83-002/03L-0 on 830118,review of operational surveillance records revealed that RCS water inventory due on 830118 missed,per Tech Specs.Caused by nontransferance of surveillance to surveillance control sheet at shift change.
RAY,H.B. Southern California Edison Co. 83/02/17 Region 5,
Office of Director 1p 17373 294 24X Fiche 50-362,83/02/17,
8303040567.

8303040602 Forwards LER 83-019/03L-0.
RAY,H.B. Southern California Edison Co. 83/02/17 ENGELKEN,R.H.
Region 5, Office of Director 1p 17374 229 24X
Fiche 50-362,83/02/17,8303040602.

--8303040615 LER 83-019/03L-0 on 830118,Mode 3 entered w/eight fire detectors inoperable.Caused by spurious alarm not reset following const activity.Compensatory measures initiated.Personnel counseled.
RAY,H.B. Southern California Edison Co. 83/02/17 Region 5,
Office of Director 1p 17374 230 24X Fiche 50-362,83/02/17,
8303040602.

8303040608 Forwards LER 83-004/03L-0.
RAY,H.B. Southern California Edison Co. 83/02/17 ENGELKEN,R.H.
Region 5, Office of Director 1p 17368 025 24X
Fiche 50-362,83/02/17,8303040608.

--8303040616 LER 83-004/03L-0 on 830118,temp indicator TI-0111BX for loop 1 hot leg on panel 3L-411 declared inoperable.Caused by improper termination on cable 3ARL12449 which runs temp element TE-0111X1.Cable termination corrected.
RAY,H.B. Southern California Edison Co. 83/02/17 Region 5,
Office of Director 2pp 17368 026 24X Fiche 50-362,83/02/17,
8303040608.

8303040577 Forwards LER 83-007/03L-0.
RAY,H.B. Southern California Edison Co. 83/02/18 ENGELKEN,R.H.
Region 5, Office of Director 1p 17373 288 24X
Fiche 50-362,83/02/18,8303040577.

--8303040589 LER 83-007/03L-0 on 830119,while in Mode 3,high pressure safety injection hot leg flow indicator 3FI-0321-1 declared inoperable.Cause unknown.Occurrence under investigation.
RAY,H.B. Southern California Edison Co. 83/02/18 Region 5,
Office of Director 1p 17373 289 24X Fiche 50-362,83/02/18,
8303040577.

8303110080 Forwards LER 83-008/03L-0.
RAY,H.B. Southern California Edison Co. 83/02/22 ENGELKEN,R.H.
Region 5, Office of Director 1p 17517 339 24X
Fiche 50-362,83/02/22,8303110080.

--8303110092 LER 83-008/03L-0 on 830123,while in Mode 3,Channel A level indicator 3LI-1113-1 for steam generator E-089 declared inoperable when indicator failed Tech Spec surveillance.Caused by instrument drift.Indicator recalibr.
RAY,H.B. Southern California Edison Co. 83/02/22 Region 5,
Office of Director 1p 17517 340 24X Fiche 50-362,83/02/22,
8303110080.

8303110305 Forwards LER 83-012/03L-0.
RAY,H.B. Southern California Edison Co. 83/02/22 ENGELKEN,R.H.
Region 5, Office of Director 1p 17515 350 24X
Fiche 50-362,83/02/22,8303110305.

--8303110325 LER 83-012/03L-0 on 830123,while in Mode 3,hot leg temp indicator TI-0111BX failed Tech Spec surveillance & declared inoperable.Temp element tied down & could not be connected to complete surveillance.Tie down removed.Indicator tested.
RAY,H.B. Southern California Edison Co. 83/02/22 Region 5,
Office of Director 1p 17515 351 24X Fiche 50-362,83/02/22,
8303110305.

8303110333 Forwards LERs 83-010/03L-0 & 83-011/03L-0.
RAY,H.B. Southern California Edison Co. 83/02/22 ENGELKEN,R.H.
Region 5, Office of Director 1p 17506 344 24X
Fiche 50-362,83/02/22,8303110333.

--8303110337 LER 83-010/03L-0 on 830123,pressure indicator 3PI-8301 for steam generator E-089 declared inoperable.Caused by inadvertent isolation of 3PI-8301 from detector 3PT-8301.Valve lineup corrected.
RAY,H.B. Southern California Edison Co. 83/02/22 Region 5,
Office of Director 2pp 17506 345 24X Fiche 50-362,83/02/22,
8303110333.

--8303110342 LER 83-011/03L-0 on 830123,pressure indicator 3PI-8300 for steam generator E-088 declared inoperable.Caused by inadvertent isolation of 3PI-8300 from detector 3PT-8300.Valve lineup corrected.
RAY,H.B. Southern California Edison Co. 83/02/22 Region 5,
Office of Director 2pp 17506 347 24X Fiche 50-362,83/02/22,
8303110333.

8303110347 Forwards LER 83-018/03L-0.
RAY,H.B. Southern California Edison Co. 83/02/23 ENGELKEN,R.H.
Region 5, Office of Director 1p 17506 353 24X
Fiche 50-362,83/02/23,8303110347.

--8303110349 LER 83-018/03L-0 on 830124,steam driven auxiliary feedwater pump 3P-140 failed to run at rated speed during inservice insp testing & declared inoperable.Caused by damaged motor on Limitorque valve operator.Motor replaced.
RAY,H.B. Southern California Edison Co. 83/02/23 Region 5,
Office of Director 1p 17506 354 24X Fiche 50-362,83/02/23,
8303110347.

8303110113 Forwards LERs 83-014/03L-0 & 83-015/03L-0.
RAY,H.B. Southern California Edison Co. 83/02/24 ENGELKEN,R.H.
Region 5, Office of Director 1p 17517 285 24X
Fiche 50-362,83/02/24,8303110113.

--8303110125 LER 83-014/03L-0 on 830125,safety injection tank pressure dropped below allowable limits.Caused by failure of 3PSV-9346 to reseat following overpressurization.Valve being tested to determine if repair or replacement needed.
RAY,H.B. Southern California Edison Co. 83/02/24 Region 5,
Office of Director 2pp 17517 286 24X Fiche 50-362,83/02/24,
8303110113.

--8303110134 LER 83-015/03L-0 on 830128,safety injection tank pressure dropped below allowable limits.Caused by failure of 3PSV-9346 to reseat following overpressurization.Valve being tested to determine if repair or replacement needed.
RAY,H.B. Southern California Edison Co. 83/02/24 Region 5,
Office of Director 2pp 17517 288 24X Fiche 50-362,83/02/24,
8303110113.

8303110239 RO 83-005 on 830222,loose snubbers & hangers discovered in two sample lines of reactor coolant loops.Cause undetermined.LER will be submitted by 830311.
RAY,H.B. Southern California Edison Co. 83/02/28 ENGELKEN,R.H.
Region 5, Office of Director 2pp 17518 359 24X
Fiche 50-362,83/02/28,8303110239.

8303110188 Forwards LER 83-009/03L-0.
RAY,H.B. Southern California Edison Co. 83/03/01 ENGELKEN,R.H.
Region 5, Office of Director 1p 17520 139 24X
Fiche 50-362,83/03/01,8303110188.

--8303110191 LER 83-009/03L-0 on 830130, containment high-range radiation monitor channel RI-7820-2 failed during surveillance test. Cause not determined. Monitor channel electrical unit replaced & unit returned to manufacturer for analysis. RAY, H B Southern California Edison Co. 83/03/01 Region 5, Office of Director 1p 17520 140 24X Fiche 50-362, 83/03/01, 8303110188

8303110201 Forwards LER 83-021/03L-0. RAY, H B Southern California Edison Co. 83/03/02 ENGELKEN, R H Region 5, Office of Director 1p 17517 355 24X Fiche 50-362, 83/03/02, 8303110201

--8303110208 LER 83-021/03L-0 on 830131, tendon 9 required liftoff force in excess of Tech Spec. Caused by less than anticipated relaxation rate when liftoff values calculated. Tech Spec change will correct liftoff force criteria. RAY, H B Southern California Edison Co. 83/03/02 Region 5, Office of Director 1p 17517 356 24X Fiche 50-362, 83/03/02, 8303110201

8303110224 RO 83-006 on 830301, emergency chiller E-335 associated w/control room emergency air cleanup sys train B failed & declared inoperable. LER 83-006 documenting event investigation will be provided by 830315. RAY, H B Southern California Edison Co. 83/03/02 ENGELKEN, R H Region 5, Office of Director 1p 17518 352 24X Fiche 50-362, 83/03/02, 8303110224

8303150620 Board Notification 83-26 forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys. Info may affect conclusions re probability of/corrective measures for ATWS. EISENHUT, D G Division of Licensing 83/03/03 PALLADINO, N Commissioners 24pp 17584 097 24X Fiche 50-000, 83/03/03, 8303150620

8303180435 Forwards revised LER 83-001/03X-1. RAY, H B Southern California Edison Co. 83/03/03 ENGELKEN, R H Region 5, Office of Director 1p 17621 163 24X Fiche 50-362, 83/03/03, 8303180435

--8303180443 Revised LER 83-001/03X-1 on 830111, component cooling water sys noncritical loop return containment isolation valve 3HV-6216 rendered inoperable. Caused by power loss when valve actuator supply breaker opened for troubleshooting. RAY, H B Southern California Edison Co. 83/03/03 Region 5, Office of Director 1p 17621 164 24X Fiche 50-362, 83/03/03, 8303180435

8303180501 RO 83-020 on 830303, error discovered in hydrostatic testing of line leading from component cooling water sys train A to motor cooler of high pressure safety injection pump 3P-017. Cooldown toward Mode 5 initiated. RAY, H B Southern California Edison Co. 83/03/04 ENGELKEN, R H Region 5, Office of Director 2pp 17622 076 24X Fiche 50-362, 83/03/04, 8303180501

8303180428 RO 83-022 on 830304, attempt to open valve 3HV6369 in containment cooling sys chiller fan 3ME400 failed, rendering containment cooling sys train B inoperable. Inoperability of train B prohibited entry into Mode 4. MORGAN, H E Southern California Edison Co. 83/03/07 ENGELKEN, R H Region 5, Office of Director 2pp 17621 188 24X Fiche 50-362, 83/03/07, 8303180428

8303180486 Forwards LER 83-017/03L-0. RAY, H B Southern California Edison Co. 83/03/07 ENGELKEN, R H Region 5, Office of Director 1p 17622 122 24X Fiche 50-362, 83/03/07, 8303180486

--8303180495 LER 83-017/03L-0 on 830205, tank vol & pressure for safety injection tank 3T-008 found outside allowable limits. Caused by leakage past header isolation valve 3HV-9324 & backflow through outlet check valve MU040. RAY, H B Southern California Edison Co. 83/03/07 Region 5, Office of Director 2pp 17622 123 24X Fiche 50-362, 83/03/07, 8303180486

8303150521 PNO-V-83-010 on 830307, while in operational Mode 3, both emergency diesel generators placed in inoperable status. Level of insolubles in fuel oil storage tanks exceeded Tech Spec requirements. Level not critical in diesel design. KIRSCH, D F Region 5, Office of Director 83/03/08 1p 17568 197 24X Fiche 50-362, 83/03/08, 8303150521

8303290321 Forwards LER 83-016/03L-0. MORGAN, H E Southern California Edison Co. 83/03/09 ENGELKEN, R H Region 5, Office of Director 1p 17716 230 24X Fiche 50-362, 83/03/09, 8303290321

--8303290326 LER 83-016/03L-0 on 830207, plant tour revealed failed temporary instrument line on auxiliary feedwater pump turbine stop valve 3HV-4716. Cause not stated. Line replaced & pump declared operable. Investigation continuing. RAY, H B Southern California Edison Co. 83/03/09 Region 5, Office of Director 1p 17716 221 24X Fiche 50-362, 83/03/09, 8303290321

8303210164 PNO-V-83-011 three GE reactor trip breakers on Unit 2 & one on Unit 3 failed to open during surveillance testing of undervoltage coils. Both units will remain shut down until breaker concerns resolved. News release not planned. KIRSCH, D F Region 5, Office of Director 83/03/11 1p 17632 184 24X Fiche 50-361, 83/03/11, 8303210164

8303290329 Forwards LER 83-005/01T-0. RAY, H B Southern California Edison Co. 83/03/11 ENGELKEN, R H Region 5, Office of Director 1p 17716 240 24X Fiche 50-362, 83/03/11, 8303290329

--8303290335 LER 83-005/01T-0 on 830222, loose snubbers & hangers associated w/RCS sampling valves 3HV508 & 3HV517 observed. Caused by removal of associated components for maint. Snubbers connected & declared operable. RAY, H B Southern California Edison Co. 83/03/11 Region 5, Office of Director 1p 17716 241 24X Fiche 50-362, 83/03/11, 8303290329

8303290376 ROs 83-019 & 83-023 on 830303 & 08, during Surveillance Test Procedure S023-II-11 161, reactor trip breakers failed to trip on undervoltage. Cause unknown. GE investigation continuing. RAY, H B Southern California Edison Co. 83/03/11 ENGELKEN, R H Region 5, Office of Director 2pp 17716 271 24X Fiche 50-361, 83/03/11, 8303290376

8303180507 PNO-V-83-011A on 830313, improper operation of reactor trip breaker demonstrated. Possibly caused by resistance in mechanical latching mechanism associated w/undervoltage trip device. Similar failures in Mar & Jul 1982 not reported. KIRSCH, D F Region 5, Office of Director 83/03/14 1p 17621 331 24X Fiche 50-361, 83/03/14, 8303180507

8303290067 Forwards LER 83-006/01T-0. RAY, H B Southern California Edison Co. 83/03/15 ENGELKEN, R H Region 5, Office of Director 2pp 17722 309 24X Fiche 50-362, 83/03/15, 8303290067

--8303290072 LER 83-006/01T-0 on 830301, emergency chiller E-335 associated w/control room emergency air cleanup sys train B failed to start & declared inoperable. Caused by failed temp sensor. Temporary mod installed to jumper sensor. RAY, H B Southern California Edison Co. 83/03/15 Region 5, Office of Director 1p 17722 311 24X Fiche 50-362, 83/03/15, 8303290067

8303290216 Forwards updated LER 83-016/03L-1. RAY, H B Southern California Edison Co. 83/03/17 ENGELKEN, R H Region 5, Office of Director 1p 17722 244 24X Fiche 50-362, 83/03/17, 8303290216

--8303290221 Updated LER 83-016/03L-1 on 830207, failed instrument line on automatic feedwater pump turbine stop valve 3HV-4716 identified. Caused by fatigue. Copper line & fittings replaced w/stainless steel & pump returned to svc. RAY, H B Southern California Edison Co. 83/03/17 Region 5, Office of Director 2pp 17722 245 24X Fiche 50-362, 83/03/17, 8303290216

8303290225 Forwards LER 83-020/01T-0. RAY, H B Southern California Edison Co. 83/03/17 ENGELKEN, R H Region 5, Office of Director 1p 17722 233 24X Fiche 50-362, 83/03/17, 8303290225

--8303290233 LER 83-020/01T-0 on 830203, review of ASME test data revealed error in hydrotesting of line from component cooling water Train A to HPSI pump 3P-17. Cause due to misinterpretation of hydrostatic test pressure requirement. Line retested. RAY, H B Southern California Edison Co. 83/03/17 Region 5, Office of Director 2pp 17722 234 24X Fiche 50-362, 83/03/17, 8303290225

8303290202 Forwards LER 83-022/01T-0. MORGAN, H E Southern California Edison Co. 83/03/18 ENGELKEN, R H Region 5, Office of Director 2pp 17722 236 24X Fiche 50-362, 83/03/18, 8303290202

--8303290212 LER 83-022/01T-0 on 830304 during Mode 5 at 190 F preparing for Mode 4 entry open valve 3HV6369 in containment cooling sys chiller fan 3ME400 failed Caused by failure of operator to followup on temp response of RCS
RAY, H B Southern California Edison Co 83/03/18 Region 5, Office of Director 2pp 17722 238 24X Fiche 50-362, 83/03/18, 8303290202

8303290277 Forwards LER 83-021/03L-0
RAY, H B Southern California Edison Co 83/03/18 ENGELKEN, R H Region 5, Office of Director 2pp 17716 120 24X Fiche 50-361, 83/03/18, 8303290277

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee " Svc list encl
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000, 83/02/24, 8302250505

8303070039 Identifies all requests for site visits to conduct operator licensing exams or instructor certification exams in response to Generic Ltr 83-01
BASKIN, K P Southern California Edison Co 83/03/03 EISENHUT, D G Division of Licensing 2pp 17435 288 24X Fiche 50-206, 83/03/03, 8303070039

DOCKET 50-364 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8303110102 Forwards description of scope of annual emergency plan exercise schedule for 830209 in response to NRC 820129 request Detailed description of exercise scenario & anticipated licensee actions will be submitted by 821226
CLAYTON, F L Alabama Power Co 82/08/27 STOHR, J P Region 2, Office of Director 5pp 17517 327 24X Fiche 50-348, 82/08/27, 8303110102

8302070360 Application for amend to Licenses NPF-2 & NPF-8, proposing changes to Tech Spec 3/4 3 3 4 to incorporate backup tower into Tables 3 3-8 & 4 3-5 re allowable meteorological monitoring instrumentation Safety evaluation encl
CLAYTON, F L Alabama Power Co 83/01/24 VARGA, S A Office of Nuclear Reactor Regulation, Director 4pp 17030 001 24X Fiche 50-348, 83/01/24, 8302070360

--8302070362 Proposed Tech Spec Tables 3 3-8 & 4 3-5 re meteorological monitoring instrumentation
* Alabama Power Co 83/01/24 5pp 17030 005 24X Fiche 50-348, 83/01/24, 8302070360

8303090191 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/03/02 Document Management Branch 1p 17484 127 24X Fiche 50-348, 83/03/02, 8303090191

--8303090199 Forwards public version of Rev 10 to Emergency Plan Implementing Procedure FNP-O-EIP-4 re chemistry & health physics support to emergency plan & Rev 11 to FNP-O-EIP-9 re radiation exposure estimates & emergency classification
HUDSPETH, J B Alabama Power Co 83/02/09 Office of Nuclear Reactor Regulation, Director 1p 17484 128 24X Fiche 50-348, 83/03/02, 8303090191

--8303090207 Public version of Rev 10 to Emergency Plan Implementing Procedure FNP-O-EIP-4 re chemistry & health physics support to emergency plan & Rev 11 to FNP-O-EIP-9 re radiation exposure estimates & emergency classification
* Alabama Power Co 83/02/08 6pp 17484 129 24X Fiche 50-348, 83/03/02, 8303090191

8303090369 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/03/02 Document Management Branch 1p 17484 147 24X Fiche 50-348, 83/03/02, 8303090369

--8303090375 Forwards public version of Rev 2 to Emergency Plan Implementing Procedure GO-EIP-111 re corporate activation & notification procedures & Rev 2 to GO-EIP-112 re emergency mobile communications
CLAYTON, F L Alabama Power Co 83/02/02 VARGA, S A Assistant Director for Operating Reactors 1p 17484 148 24X Fiche 50-348, 83/03/02, 8303090369

--8303090377 Public version of Rev 2 to Emergency Plan Implementing Procedure GO-EIP-111 re corporate activation & notification procedures & Rev 2 to GO-EIP-112 re emergency mobile communications
MCGOWAN, J K Alabama Power Co 83/02/03 47pp 17484 149 24X Fiche 50-348, 83/03/02, 8303090369

8303100402 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/03/02 Document Management Branch 1p 17502 210 24X Fiche 50-348, 83/03/02, 8303100402

--8303100407 Forwards public version of revised emergency plan implementing procedures, including Procedures FNP-O-EIP-15 re emergency drills & FNP-O-EIP-4 re chemistry & health physics support to emergency plan
HUDSPETH, J B Alabama Power Co 83/02/02 Office of Nuclear Reactor Regulation, Director 1p 17502 211 24X Fiche 50-348, 83/03/02, 8303100402

--8303100410 Public version of revised emergency plan implementing procedures, including Procedures FNP-O-EIP-15 re emergency drills & FNP-O-EIP-4 re chemistry & health physics support to emergency plan
* Alabama Power Co 83/02/02 148pp 17502 212 24X Fiche 50-348, 83/03/02, 8303100402

8303210502 Forwards SALP rept for Jul 1981 - Jul 1982 Further NRC review necessary to address util comments re mischaracterization of fire protection issues
O'REILLY, J P Region 2, Office of Director 83/03/09
MCDONALD, R P Alabama Power Co 3pp 17631 188 24X Fiche 50-348, 83/03/09, 8303210502

--8303210532 Forwards SALP board assessment for Jul 1981 - Jul 1982 Comments due in 20 days
LEWIS, R C Division of Project & Resident Programs 82/12/06
MCDONALD, R P Alabama Power Co 2pp 17631 191 24X Fiche 50-348, 83/03/09, 8303210502

--8303210539 SALP Repts 50-348/82-28 & 50-364/82-28 for Jul 1981 - Jul 1982
* Region 2, Office of Director 83/03/09 20pp 17631 193 24X Fiche 50-348, 83/03/09, 8303210502

--8303210548 Requests closure & removal of issues re 10CFR50, App R, Sections H & K 5, from SALP Repts 50-348/82-28 & 50-364/82-28
CLAYTON, F L Alabama Power Co 82/12/21 O'REILLY, J P Region 2, Office of Director 2pp 17631 219 24X Fiche 50-348, 83/03/09, 8303210502

8303230415 Releases public version of rev to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/03/16 Document Management Branch 1p 17674 172 24X Fiche 50-348, 82/03/16, 8303230415

--8303230418 Forwards public version of Rev 11 to Emergency Plan Implementing Procedure FNP-O-EIP-10, "Evacuation & Personnel Accountability " Receipt form encl
HUDSPETH, J B Alabama Power Co 83/02/24 Office of Nuclear Reactor Regulation, Director 2pp 17674 173 24X Fiche 50-348, 83/03/16, 8303230415

--8303230423 Public version of Rev 11 to Emergency Plan Implementing Procedure FNP-O-EIP-10, "Evacuation & Personnel Accountability "
* Alabama Power Co 83/02/22 11pp 17674 175 24X Fiche 50-348, 83/03/16, 8303230415

8303240107 Releases public version of memo & request form voiding emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/03/21 Document Management Branch 1p 17700 290 24X Fiche 50-348, 83/03/21, 8303240107

--8303240112 Forwards public version of memo & procedure request form voiding FNP-O-EIP-20, "Recovery - Emergency Operations Facility," per Administrative Procedure FNP-O-AP-4, "Control of Plant Documents & Records "
HUDSPETH, J B Alabama Power Co 83/03/07 Office of Nuclear Reactor Regulation, Director 5pp 17700 291 24X Fiche 50-348, 83/03/21, 8303240107

J. Insurance & indemnity information

8303010299 Requests prorated refund for each unit from effective zero indemnification date of 821125 through end of term for each indemnity fee prepaid. Refund justification page encl.
MCDONALD, R. P. Alabama Power Co. 83/02/17 SALTZMAN, J. Assistant Director for State & Licensee Relations. 2pp. 17333:336. 24X
Fiche: 50-348, 83/02/17, 8303010299

8303010232 Forwards Endorsements 49 & 50 & 41 & 42 to NELIA Policy NF-238 & MAELU Policy MF-93, respectively.
DUCK, J. R. Marsh & McLennan, Inc. 83/02/22 SALTZMAN, J. Assistant Director for State & Licensee Relations. 6pp. 17333:356. 24X
Fiche: 50-348, 83/02/22, 8303010232

8303290431 Forwards Endorsement 51 to NELIA Policy NF-238.
DUCK, J. R. Marsh & McLennan, Inc. 83/03/15 SALTZMAN, J. Assistant Director for State & Licensee Relations. 2pp. 17725:325. 24X
Fiche: 50-348, 83/03/15, 8303290431

P. Operating license stage documents & correspondence

8302070360 Application for amend to Licenses NPF-2 & NPF-8, proposing changes to Tech Spec 3/4.3.3.4 to incorporate backup tower into Tables 3.3-8 & 4.3-5 re allowable meteorological monitoring instrumentation. Safety evaluation encl.
CLAYTON, F. L. Alabama Power Co. 83/01/24 VARGA, S. A. Office of Nuclear Reactor Regulation, Director. 4pp. 17030:001. 24X
Fiche: 50-348, 83/01/24, 8302070360

--8302070362 Proposed Tech Spec Tables 3.3-8 & 4.3-5 re meteorological monitoring instrumentation.
* Alabama Power Co. 83/01/24 5pp. 17030:005. 24X
Fiche: 50-348, 83/01/24, 8302070360

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082

8303080512 Responds to 830223 telcon request to provide justification for continued operation for level sensors in main steam valve room & containment per 830204 technical evaluation repts.
CLAYTON, F. L. Alabama Power Co. 83/02/25 VARGA, S. A. Office of Nuclear Reactor Regulation, Director. 3pp. 17450:309. 24X
Fiche: 50-348, 83/02/25, 8303080512

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/02/02, 8303020321

8303080517 Responds to 830302 telcon request for addl justification for continued operation of level sensors in main steam valve room & containment, per 830204 technical evaluation repts. Supports position that De Laval instruments are qualified.
CLAYTON, F. L. Alabama Power Co. 83/03/02 VARGA, S. A. Office of Nuclear Reactor Regulation, Director. 3pp. 17452:309. 24X
Fiche: 50-348, 83/03/02, 8303080517

8303080480 Requests info of proprietary nature identified in technical evaluation repts be withheld per 10CFR2.790. Vendors have not supplied requested applications & affidavits at present.
CLAYTON, F. L. Alabama Power Co. 83/03/03 VARGA, S. A. Office of Nuclear Reactor Regulation, Director. 2pp. 17452:278. 24X
Fiche: 50-348, 83/03/03, 8303080480

8303140312 Application for amend to Licenses NPF-2 & NPF-8 clarifying & updating charcoal filter Tech Specs.
CLAYTON, F. L. Alabama Power Co. 83/03/04 VARGA, S. A. Office of Nuclear Reactor Regulation, Director. 7pp. 17543:329. 24X
Fiche: 50-348, 83/03/04, 8303140312

--8303140318 Proposed Tech Specs clarifying & updating interpretation & testing stds for charcoal filters.
* Alabama Power Co. 83/03/04 15pp. 17543:336. 24X
Fiche: 50-348, 83/03/04, 8303140312

8303140376 Application for amend to Licenses NPF-2 & NPF-8, revising Tech Specs 3.1.3.1 re movable control assemblies.
CLAYTON, F. L. Alabama Power Co. 83/03/04 VARGA, S. A. Office of Nuclear Reactor Regulation, Director. 4pp. 17542:199. 24X
Fiche: 50-348, 83/03/04, 8303140376

--8303140380 Proposed Tech Spec 3.1.3.1 re limiting condition for operation of movable control assemblies.
* Alabama Power Co. 83/03/04 3pp. 17542:203. 24X
Fiche: 50-348, 83/03/04, 8303140376

8303140491 Requests that NRC approve 821230 Tech Spec changes to reduce boron concentration in boron injection tanks by 830318 instead of 830331, to support Unit 1 Cycle 5 restart.
CLAYTON, F. L. Alabama Power Co. 83/03/04 VARGA, S. A. Office of Nuclear Reactor Regulation, Director. 1p. 17540:311. 24X
Fiche: 50-348, 83/03/04, 8303140491

8303140558 Forwards status of licensing items requiring NRC approval in 1983, identified in util 830113 ltr & summary of proposed actions to be taken on listed items w/no submittal or requested approval dates. Status provided on monthly basis.
CLAYTON, F. L. Alabama Power Co. 83/03/04 VARGA, S. A. Office of Nuclear Reactor Regulation, Director. 7pp. 17534:042. 24X
Fiche: 50-348, 83/03/04, 8303140558

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005

8303150486 Provides results of reactor vessel level sys review & addresses Generic Ltr 82-28. Applicable provisions of NUREG-0737 met except environ qualification criteria of App B. Summary of feasibility study encl.
CLAYTON, F. L. Alabama Power Co. 83/03/10 VARGA, S. A. Office of Nuclear Reactor Regulation, Director. 42pp. 17560:268. 24X
Fiche: 50-348, 83/03/10, 8303150486

8303300306 Forwards rept on environ qualification of Class IE electrical equipment, per NRC 830204 SER of util response to NUREG-0588. Water-tight fitting on Victoreen radiation detectors will be installed, per NUREG-0737 requirements.
CLAYTON, F. L. Alabama Power Co. 83/03/14 VARGA, S. A. Office of Nuclear Reactor Regulation, Director. 73pp. 17734:061. 24X
Fiche: 50-364, 83/03/14, 8303300206

8303180681 Notification of 830323 meeting w/util & Westinghouse in Bethesda, MD to discuss util request to delete turbine valve testing from Tech Specs.
REEVES, F. Operating Reactors Branch 1 83/03/15 VARGA, S. Operating Reactors Branch 1 2pp. 17637:018. 24X
Fiche: 50-364, 83/03/15, 8303180681

8303230247 Forwards "JM Farley Nuclear Plant Unit 2 Cycle 2 Startup Test Rept." per commitment in util 820914 ltr.
CLAYTON, F. L. Alabama Power Co. 83/03/15 VARGA, S. Office of Nuclear Reactor Regulation, Director. 1p. 17662:006. 24X
Fiche: 50-364, 83/03/15, 8303230247

--8303230252 "JM Farley Nuclear Plant Unit 2 Cycle 2 Startup Test Rept."
* Alabama Power Co. 83/02/28 19pp. 17662:007. 24X
Fiche: 50-364, 83/03/15, 8303230247

Q. Inspection reports, IE Bulletins & correspondence

8303010432 Forwards IE Insp Repts 50-348/82-30 & 50-364/82-31 on 821216-830115. No noncompliance noted.
VERRELLI, D. M. Division of Project & Resident Programs. 83/02/02
MCDONALD, R. P. Alabama Power Co. 2pp. 17343:073. 24X
Fiche: 50-348, 83/02/02, 8303010432

--8303010437 IE Insp Repts 50-348/82-30 & 50-364/82-31 on 821216-830115. No noncompliance noted. Major areas inspected: monthly surveillance & maint observation; operational safety verification & routine events review.
BRADFORD, W. H., CANTRELL, F. S. Division of Project & Resident Programs. 83/02/01 6pp. 17343:075. 24X Fiche: 50-348, 83/02/02, 8303010432

8303040484 Discusses IE insp on 821028-1102 & forwards notice of violation & proposed imposition of civil penalty.
O'REILLY, J. P. Region 2, Office of Director. 83/02/02
MCDONALD, R. P. Alabama Power Co. 3pp. 17426:248. 24X
Fiche: 50-364, 83/02/02, 8303040484

--8303040488 Notice of violation & proposed imposition of civil penalty in amount of $40,000. Noncompliance noted: licensee operated reactor w/o having satisfied limiting condition for operation of two independent containment spray sys.
O'REILLY, J. P. Region 2, Office of Director. 83/02/02 2pp. 17426:251. 24X Fiche: 50-364, 83/02/02, 8303040484

# DOCKETED ITEMS

8303010289 Forwards IE Insp Repts 50-348/83-01 & 50-364/83-01 on 830111-14 No noncompliance noted.
VERRELLI, D M. Division of Project & Resident Programs 83/02/03
MCDONALD, R P. Alabama Power Co. 2pp. 17335:270. 24X
Fiche: 50-348, 83/02/03, 8303010289.

--8303010295 IE Insp Repts 50-348/83-01 & 50-364/83-01 on 830111-14 No noncompliance noted. Major areas inspected: radiological environ monitoring, including mgt & administrative controls & insp of selected monitoring & sampling stations.
CUNNINGHAM, A L ; MONTGOMERY, D M. Division of Project & Resident Programs. 83/01/31. 5pp. 17335:272. 24X Fiche: 50-348, 83/02/03, 8303010289.

8303010186 Ack receipt of 830207 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/82-29 & 50-364/82-30.
LEWIS, R C. Division of Project & Resident Programs. 83/02/16
MCDONALD, R P. Alabama Power Co. 1p. 17333:338. 24X
Fiche: 50-348, 83/02/16, 8303010186.

--8303010209 Responds to NRC 830111 ltr re violations noted in IE Insp Repts 50-348/82-29 & 50-364/82-30. Corrective actions: cause for alarmed annunicators determined & condition corrected. Memo written to emphasize importance of prompt response.
CLAYTON, F L. Alabama Power Co. 83/02/07. LEWIS, R C. Region 2, Office of Director. 2pp. 17333:339. 24X Fiche: 50-348, 83/02/16, 8303010186.

--8303010213 Forwards IE Insp Repts 50-348/82-29 & 50-364/82-30 on 821127-1215 & notice of violation.
LEWIS, R C. Division of Project & Resident Programs. 83/01/11.
MCDONALD, R P. Alabama Power Co. 2pp. 17333:341. 24X
Fiche: 50-348, 83/02/16, 8303010186.

--8303010215 Notice of violation from insp on 821127-1215.
* Division of Project & Resident Programs. 83/01/11. 1p.
17333:343. 24X Fiche: 50-348, 83/02/16, 8303010186.

--8303010221 IE Insp Repts 50-348/82-29 & 50-364/82-30 on 821127-1215. Noncompliance noted: failure to follow established procedures for annunicator response.
BRADFORD, W H ; CANTRELL, F S. Division of Project & Resident Programs. 83/01/10. 6pp. 17333:344. 24X Fiche: 50-348, 83/02/16, 8303010186.

8303020027 Responds to violations noted in IE Insp Rept 50-364/82-25. Corrective actions: locked valves verified by physical valve movement & valve verification instruction validated.
CLAYTON, F L. Alabama Power Co. 83/02/22. Region 2, Office of Director. 6pp. 17354:219. 24X Fiche: 50-364, 83/02/22, 8303020027.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303090289 Forwards technical evaluation rept re util responses to IE Bulletin 80-11, "Masonry Wall Design." Items 2 & 3 fully implemented; except for Wall 2 CBW-34 W/o encl.
VARGA, S A. Operating Reactors Branch 1. 83/03/01. CLAYTON, F L. Alabama Power Co. 2pp. 17484:296. 24X Fiche: 50-364, 83/03/01, 8303090289.

8303210426 Forwards IE Insp Repts 50-348/83-06 & 50-364/83-04 on 830116-0215. No noncompliance noted.
VERRELLI, D M. Division of Project & Resident Programs. 83/03/01
MCDONALD, R P. Alabama Power Co. 2pp. 17634:220. 24X
Fiche: 50-348, 83/03/01, 8303210426.

--8303210436 IE Insp Repts 50-348/83-06 & 50-364/83-04 on 830116-0215. No noncompliance noted. Major areas inspected: monthly surveillance observation; operational safety evaluation; independent insp effort & review of routine events.
BRADFORD, W H. Region 2, Office of Director. CANTRELL, F S. Division of Project & Resident Programs. 83/03/01. 7pp.
17634:222. 24X Fiche: 50-348, 83/03/01, 8303210426.

8303210401 Ack receipt of 830222 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-364/82-25.
O'REILLY, J P. Region 2, Office of Director. 83/03/03
MCDONALD, R P. Alabama Power Co. 1p. 17634:150. 24X
Fiche: 50-364, 83/03/03, 8303210401.

8303090312 Responds to IE Bulletin 83-01 re failure of Westinghouse DB-type breakers. DB-type breakers tested at least once per 31 days & verified open when undervoltage coil receives simulated trip signal.
CLAYTON, F L. Alabama Power Co. 83/03/04. O'REILLY, J P. Region 2, Office of Director. 2pp. 17473:217. 24X Fiche: 50-348, 83/03/04, 8303090312.

8303210502 Forwards SALP rept for Jul 1981 - Jul 1982. Further NRC review necessary to address util comments re mischaracterization of fire protection issues.
O'REILLY, J P. Region 2, Office of Director. 83/03/09.
MCDONALD, R P. Alabama Power Co. 3pp. 17631:188. 24X
Fiche: 50-348, 83/03/09, 8303210502.

--8303210532 Forwards SALP board assessment for Jul 1981 - Jul 1982. Comments due in 20 days.
LEWIS, R C. Division of Project & Resident Programs. 82/12/06.
MCDONALD, R P. Alabama Power Co. 2pp. 17631:191. 24X
Fiche: 50-348, 83/03/09, 8303210502.

--8303210539 SALP Repts 50-348/82-28 & 50-364/82-28 for Jul 1981 - Jul 1982.
* Region 2, Office of Director. 83/03/09. 20pp. 17631:193. 24X
Fiche: 50-348, 83/03/09, 8303210502.

--8303210548 Requests closure & removal of issues re 10CFR50, App R, Sections H & K.5 from SALP Repts 50-348/82-28 & 50-364/82-28.
CLAYTON, F L. Alabama Power Co. 82/12/21. O'REILLY, J P. Region 2, Office of Director. 2pp. 17631:219. 24X Fiche: 50-348, 83/03/09, 8303210502.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 12?pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303290354 Responds to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel)." No significant fouling or flow blockage by Corbicula shells discovered.
CLAYTON, F L. Alabama Power Co. 83/03/22. JORDAN, E L. Division of Engineering & Quality Assurance (Pre 830103). 2pp. 17716:168. 24X
Fiche: 50-348, 83/03/22, 8303290354.

R Periodic operating reports & related correspondence

8303090341 Forwards "Semiannual Radioactive Effluent Release Rept, Jul-Dec 1981."
CLAYTON, F L. Alabama Power Co. 83/03/02. O'REILLY, J P. Region 2, Office of Director. 1p. 17472:143. 24X Fiche: 50-348, 82/03/02, 8303090341.

--8303090348 "Semiannual Radioactive Effluent Release Rept, Jul-Dec 1981."
* Alabama Power Co. 82/03/02. 147pp. 17472:144. 24X
Fiche: 50-348, 82/03/02, 8303090341.

S Reportable occurrences, LERs & related correspondence

8303210460 Forwards LERs 83-009/03L-0, 83-010/03L-0 & 83-012/03L-0 W/o LERs 83-010/03L-0 & 83-012/03L-0.
CLAYTON, F L. Alabama Power Co. 83/03/11. Region 2, Office of Director. 1p. 17634:153. 24X Fiche: 50-364, 83/03/11, 8303210460.

--8303210468 LER 83-009/03L-0 on 830217, pressurizer PORV 444B declared inoperable when pressurizer pressure controller card 444A failed low. Caused by failure of driver card. PORV 444B declared operable following calibr & replacement of card.
HAIRSTON, W G. Alabama Power Co. 83/03/11. Region 2, Office of Director. 1p. 17634:154. 24X Fiche: 50-364, 83/03/11, 8303210460.

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303010506 Forwards list of anticipated requests for site visits for operator licensing exams through 1985, in response to Generic Ltr 83-01.
CLAYTON, F. L. Alabama Power Co. 83/02/24 EISENHUT, D. G. Division of Licensing 2pp 17337.249 24X Fiche 50-348,83/02/24, 8303010506.

DOCKET 50-366 EDWIN I. HATCH NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8303020060 Forwards SER for Sections III.G.3 & III.L of App R to 10CFR50 re safe shutdown capability. Licensee conceptual design of alternative shutdown capability for control room & cable spreading room acceptable.
STOLZ, J. F. Operating Reactors Branch 4 83/02/11 BECKHAM, J. T. Georgia Power Co. 2pp 17359.321 24X Fiche 50-321,83/02/11, 8303020060.

--8303020062 SER accepting licensee proposed alternate safe shutdown sys for maintaining cold shutdown conditions free of fire damage.
SINGH, B. K. NRC - No Detailed Affiliation Given. 83/02/11 10pp 17359.323 24X Fiche 50-321,83/02/11,8303020060.

8303090532 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/02 Document Management Branch. 1p 17483.123 24X Fiche 50-321,83/03/02, 8303090532.

--8303090537 Forwards public version of revised emergency plan implementing procedures, including Procedure HNP-8030 re health physics startup surveillance.
NIX, H. C. Georgia Power Co. 83/02/15 Office of Nuclear Reactor Regulation, Director. 1p 17483.124 24X Fiche 50-321,83/03/02, 8303090532.

--8303090544 Public version of revised emergency plan implementing procedures, including Procedure HNP-8030 re health physics startup surveillance.
* Georgia Power Co. 83/01/11 39pp 17483.125 24X Fiche 50-321,83/03/02,8303090532.

8303100125 Releases public version of revised pages to emergency plan.
FELTON, J. M. Division of Rules and Records. 83/03/02 Document Management Branch. 1p 17496.147 24X Fiche 50-321,83/03/02, 8303100125.

--8303100130 Forwards public version of revised pages to emergency plan. Receipt form encl.
OLLINGER, W. H. Georgia Power Co. 83/01/15 NRC - No Detailed Affiliation Given. 1p 17496.148 24X Fiche 50-321,83/03/02, 8303100125.

--8303100132 Public version of revised pages to emergency plan.
* Georgia Power Co. 83/01/31 16pp 17496.149 24X Fiche 50-321,83/03/02,8303100125.

8303240111 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/21 Document Management Branch. 1p 17700.256 24X Fiche 50-321,83/03/21, 8303240111.

--8303240114 Forwards public version of Rev 11 to Emergency Plan Implementing Procedure HNP-8050, "Survey Frequency & Work Scheduling" & Rev 7 to HNP-8120, "Count Rate Meter PRM-4A Operation & Calibr." Receipt form encl.
NIX, H. C. Georgia Power Co. 83/03/14 Office of Nuclear Reactor Regulation, Director. 1p 17700.257 24X Fiche 50-321,83/03/21, 8303240111.

--8303240119 Public version of Rev 11 to Emergency Plan Implementing Procedure HNP-8050, "Survey Frequency & Work Scheduling" & Rev 7 to HNP-8120, "Count Rate Meter PRM-4A Operation & Calibr."
ROGERS, W. H. Georgia Power Co. 83/03/07 32pp 17700.258 24X Fiche 50-321,83/03/21,8303240111.

8303250042 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/21 Document Management Branch. 1p 17710.116 24X Fiche 50-321,83/03/21, 8303250042.

--8303250043 Forwards public version of Rev 15 to Emergency Plan Implementing Procedure HNP-8008, "Radiation Work Permit."
NIX, H. C. Georgia Power Co. 83/03/08 Office of Nuclear Reactor Regulation, Director. 2pp 17710.117 24X Fiche 50-321,83/03/21, 8303250042.

--8303250048 Public version of Rev 15 to Emergency Plan Implementing Procedure HNP-8008, "Radiation Work Permit."
NIX, H. Georgia Power Co. 83/02/28 20pp 17710.119 24X Fiche 50-321,83/03/21,8303250042.

8303280281 Forwards IE Safeguards Insp Repts 50-321/83-05 & 50-366/83-05 on 830222-25. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/03/22 KELLY, R. J. Georgia Power Co. 2pp 17706.039 24X Fiche 50-321,83/03/22,8303280281.

--8303280291 IE Safeguards Insp Repts 50-321/83-05 & 50-366/83-05 on 830222-25. No noncompliance noted. Major areas inspected site orientation & review of security plan & implementing procedures. Details withheld (ref 10CFR73.21).
HALL, B. L. Region 2, Office of Director. 83/03/17 1p 17706.041 24X Fiche 50-321,83/03/22,8303280281.

8303310113 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/25 Document Management Branch. 1p 17775.273 24X Fiche 50-321,83/03/25, 8303310113.

--8303310118 Forwards public version of Rev 7 to Emergency Plan Implementing Procedure HNP-8022 re environ & personnel TLD cross-check program, Rev 1 to HNP-8143 re low vol air sampler & Rev 1 to HNP-8146 re calibr of rate meter.
NIX, H. C. Georgia Power Co. 83/02/08 Office of Nuclear Reactor Regulation, Director. 1p 17775.274 24X Fiche 50-321,83/03/25, 8303310113.

--8303310121 Public version of Rev 7 to Emergency Plan Implementing Procedure HNP-8022 re environ & personnel TLD cross-check program, Rev 1 to HNP-8143 re low vol air sampler & Rev 1 to HNP-8146 re operation calibr of portable rate meter-scaler.
* Georgia Power Co. 83/02/09 42pp 17775.275 24X Fiche 50-321,83/03/25,8303310113.

8303310167 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 83/03/28 Document Management Branch. 1p 17775.114 24X Fiche 50-321,83/03/28, 8303310167.

--8303310174 Forwards public version of Rev 7 to Emergency Plan Implementing Procedure HNP-8020, "Plant Fume Velocity Measurement" & Rev 3 to HNP-4864, "Technical Support Ctr."
NIX, H. C. Georgia Power Co. 83/02/28 Office of Nuclear Reactor Regulation, Director. 1p 17775.115 24X Fiche 50-321,83/03/28, 8303310167.

--8303310180 Public version of Rev 7 to Emergency Plan Implementing Procedure HNP-8020, "Plant Fume Velocity Measurements" & Rev 3 to HNP-4864, "Technical Support Ctr."
ROGERS, W. H., NIX, H. Georgia Power Co. 83/02/23 33pp 17775.116 24X Fiche 50-321,83/03/28,8303310167.

J. Insurance & indemnity information

8303010250 Forwards Endorsements 75 & 76 & 61 & 62 to NELIA Policy NF-215 & MAELU Policy MF-78 respectively.
DUCK, J. R. Marsh & McLennan, Inc. 83/02/22 SALTZMAN, J. Assistant Director for State & Licensee Relations 5pp 17335.154 24X Fiche 50-321,83/02/22,8303010250.

8303290409 Forwards Endorsement 77 to NELIA Policy NF-213.
DUCK, J. R. Marsh & McLennan, Inc. 83/03/15 SALTZMAN, J. Office of State Programs, Director. 2pp 17725.174 24X Fiche 50-321,83/03/15,8303290409.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants re OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492.033 24X Fiche 50-000,83/02/16,8302170082.

8303070001 Application for amend to License NPF-5 Tech Specs, supporting installation of low-low set safety relief valve logic sys & GE analog transmitter trip sys. Proprietary supporting info withheld (ref 10CFR2.790).
CAUSEY, J. C. Georgia Power Co. 83/02/23 STOLZ, J. F. Operating Reactors Branch 4 10pp 17459.112 24X Fiche 50-366,83/02/23, 8303070001.

# DOCKETED ITEMS

8303020010 Forwards, "Mark I Containment Long-Term Program Plant Unique Analysis Rept-Suppl." Rept addresses safety-relief valve discharge line drywell supports, torus attached piping & supports, valves, pumps & torus shell nozzles.
GUCWA, L. T. Georgia Power Co. 83/02/28. STOLZ, J. F. Operating Reactors Branch 4. 1p. 17353:181. 24X Fiche: 50-321, 83/02/28, 8303020010.

--8303020014 "Mark I Containment Long-Term Program Plant Unique Analysis Rept-Suppl."
* Bechtel Corp. 83/02/28. 327pp. 17353:182. 24X Fiche: 50-321, 83/02/28, 8303020010.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," clarification of Generic Ltr 82-12. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303170300 Revises estimated completion date to 830701 for implementation of NUREG-0737, Item II.B.3, "Post-Accident Sampling." Grab sample analysis will be used in interim.
BECKHAM, J. T. Georgia Power Co. 83/03/11. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 17605:129. 24X Fiche: 50-321, 83/03/11, 8303170300.

8303220458 Forwards Amends 94 & 31 to Licenses DPR-57 & NPF-5, respectively & notice of issuance & availability. Amends revise ETS to delete nonradiological water quality-related requirements.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/11. BECKHAM, J. T. Georgia Power Co. 5pp. 17670:128. 24X Fiche: 50-321, 83/03/11, 8303220458.

--8303220463 Amends 94 & 31 to Licenses DPR-57 & NPF-5, respectively, revising ETS to delete nonradiological water quality-related requirements.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/11. 20pp. 17670:133. 24X Fiche: 50-321, 83/03/11, 8303220458.

--8303220468 Notice of issuance & availability of Amends 94 & 31 to Licenses DPR-57 & NPF-5, respectively.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/11. 2pp. 17670:153. 24X Fiche: 50-321, 83/03/11, 8303220458.

8303210427 Forwards response to 830208 request for addl info re NUREG-0737, Items I.A.2.1, "Upgrading Reactor Operator & Senior Reactor Operator Training Qualifications" & II.B.4, "Training for Mitigating Core Damage."
BECKHAM, J. T. Georgia Power Co. 83/03/14. STOLZ, J. F. Operating Reactors Branch 4. 7pp. 17634:343. 24X Fiche: 50-321, 83/03/14, 8303210427.

8303290012 Forwards order confirming licensee commitments on post-TMI related issues based on util responses to Generic Ltrs 82-05 & 82-10.
STOLZ, J. F. Operating Reactors Branch 4. 83/03/14. BECKHAM, J. T. Georgia Power Co. 3pp. 17730:030. 24X Fiche: 50-321, 83/03/14, 8303290012.

--8303290019 Order confirming licensee commitments to implement post-TMI related items contained in NUREG-0737.
PURPLE, R. A. Assistant Director for Licensing. 83/03/14. Georgia Power Co. 10pp. 17730:033. 24X Fiche: 50-321, 83/03/14, 8303290012.

8303310070 Forwards safety evaluations on BWR Owners Group B01001 & 1229 responses to NUREG-0737, Item II.K.3.13 re separation of HPCI & RCIC sys initiation levels & mod of RCIC sys automatic restart, respectively. Item complete.
STOLZ, J. Operating Reactors Branch 4. 83/03/16. BACKHAM, J. T. Georgia Power Co. 3pp. 17775:330. 24X Fiche: 50-321, 83/03/16, 8303310070.

8303230386 Notification of 830330 meeting w/util in Bethesda, MD to discuss appeal of denials listed in draft SER on facility exemption requests.
RIVENBARK, G. Operating Reactors Branch 4. 83/03/18. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 17675:255. 24X Fiche: 50-321, 83/03/18, 8303230386.

8303240124 Notification of 830331 meeting w/util in Bethesda, MD to discuss status of remaining issues re review of purging & venting during normal operations.
RIVENBARK, G. Operating Reactors Branch 4. 83/03/18. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 17698:344. 24X Fiche: 50-321, 83/03/18, 8303240124.

8303290322 Application for amend to License NPF-5, changing Tech Specs for one-time extension of grace period for calibr of local power range monitors.
BECKHAM, J. T. Georgia Power Co. 83/03/24. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 17716:232. 24X Fiche: 50-366, 83/03/24, 8303290322.

--8303290330 Proposed Tech Specs providing for one-time extension of grace period for calibr of local power range monitors.
* Georgia Power Co. 83/03/24. 3pp. 17716:234. 24X Fiche: 50-366, 83/03/24, 8303290322.

G Inspection reports, IE Bulletins & correspondence

8303210655 Forwards IE Insp Repts 50-321/83-03 & 50-366/83-03 on 830129-0203. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/02/24. KELLY, R. J. Georgia Power Co. 2pp. 17635:187. 24X Fiche: 50-321, 83/02/24, 8303210655.

--8303210668 IE Insp Repts 50-321/83-03 & 50-366/83-03 on 830129-0203. No noncompliance noted. Major areas inspected integrated leak rate test procedure review, test controls, ILRT witnessing & followup on outstanding insp items.
WHITENER, H. L., JAPE, F. Region 2, Office of Director. 83/02/23. 5pp. 17635:189. 24X Fiche: 50-321, 83/02/24, 8303210655.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210632 Ack receipt of 830210 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/82-42 & 50-366/82-40.
LEWIS, R. C. Division of Project & Resident Programs. 83/03/02. KELLY, R. J. Georgia Power Co. 1p. 17636:252. 24X Fiche: 50-321, 83/03/02, 8303210632.

--8303210639 Responds to NRC 830111 ltr re violations noted in IE Insp Repts 50-321/82-42 & 50-366/82-40. Corrective actions new QA position filled, overdue initial corrective action responses submitted & lead auditor qualification records reviewed.
GUCWA, L. T. Georgia Power Co. 83/02/10. O'REILLY, J. P. Region 2, Office of Director. 6pp. 17636:253. 24X Fiche: 50-321, 83/03/02, 8303210632.

--8303210648 Forwards IE Insp Repts 50-321/82-42 & 50-366/82-40 on 821213-15 & notice of violation.
LEWIS, R. C. Division of Project & Resident Programs. 83/01/11. KELLY, R. J. Georgia Power Co. 2pp. 17636:259. 24X Fiche: 50-321, 83/03/02, 8303210632.

--8303210654 Notice of violation from insp on 821213-15.
* Region 2, Office of Director. 83/01/11. 2pp. 17636:261. 24X Fiche: 50-321, 83/03/02, 8303210632.

--8303210662 IE Insp Repts 50-321/82-42 & 50-366/82-40 on 821213-15. Noncompliance noted: failure to promptly correct items adverse to quality, to respond to audit findings within required timeframe & to update lead auditor qualifications.
BELISLE, G. A., JACKSON, L. H. Region 2, Office of Director. UPRIGHT, C. M. Division of Engineering & Radiological Safety Programs. 83/01/06. 7pp. 17636:263. 24X Fiche: 50-321, 83/03/02, 8303210632.

8303210387 Requests extension to 830310 to respond to IE Bulletin 82-04.
GUCWA, L. T. Georgia Power Co. 83/03/03. O'REILLY, J. P. Region 2, Office of Director. 1p. 17634:174. 24X Fiche: 50-321, 83/03/03, 8303210387.

8303210361 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Bunker-Ramo penetration assemblies not used at facilities.
BECKHAM, J. T. Georgia Power Co. 83/03/10. O'REILLY, J. P. Region 2, Office of Director. 1p. 17635:010. 24X Fiche: 50-321, 83/03/10, 8303210361.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611.070. 24X Fiche. 50-000, 83/03/11, 8212060380.

8303210458 Ack receipt of 830126 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-321/82-38 & 50-366/82-36.
LEWIS, R. C. Division of Project & Resident Programs. 83/03/11.
KELLY, R. J. Georgia Power Co. 2pp. 17631.271. 24X.
Fiche. 50-321, 83/03/11, 8303210458.

--8303210464 Responds to NRC 821221 ltr re violation noted in IE Insp Repts 50-321/82-38 & 50-366/82-36. Corrective actions: qualifications of personnel conducting Type C leak tests, per HNP-1-3952-E, reviewed & found acceptable.
GUCWA, L. T. Georgia Power Co. 83/01/26. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17631.273. 24X Fiche. 50-321, 83/03/11, 8303210458.

--8303210472 Forwards IE Insp Repts 50-321/82-38 & 50-366/82-36 on 821116-19 & notice of violation.
LEWIS, R. C. Division of Project & Resident Programs. 82/12/21.
KELLY, R. J. Georgia Power Co. 2pp. 17631.275. 24X.
Fiche. 50-321, 83/03/11, 8303210458.

--8303210487 IE Insp Repts 50-321/82-38 & 50-366/82-36 on 821116-19. Noncompliance noted: HNP-1-3952-E, Rev 13, did not identify all valve positions associated w/Type C leak rate tests.
WHITENER, H. L. Region 2, Office of Director. JAPE, F. Division of Engineering & Radiological Safety Programs. 82/12/17. 4pp. 17631.278. 24X Fiche. 50-321, 83/03/11, 8303210458.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche. 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774.352. 24X Fiche. 50-000, 83/03/21, 8212060387.

8303280281 Forwards IE Safeguards Insp Repts 50-321/83-05 & 50-366/83-05 on 830222-25. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/03/22.
KELLY, R. J. Georgia Power Co. 2pp. 17706.039. 24X.
Fiche. 50-321, 83/03/22, 8303280281.

--8303280291 IE Safeguards Insp Repts 50-321/83-05 & 50-366/83-05 on 830222-25. No noncompliance noted. Major areas inspected: site orientation & review of security plan & implementing procedures. Details withheld (ref 10CFR73.21).
HALL, B. L., MCGUIRE, D. R. Region 2, Office of Director. 83/03/17.
1p. 17706.041. 24X Fiche. 50-321, 83/03/22, 8303280281.

R Periodic operating reports & related correspondence

8303090360 Forwards "Semiannual Rept for Plant Radioactive Effluent Releases, Jan-June 1981."
MANRY, M. Georgia Power Co. 81/08/25. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. (81/03/01). 1p. 17470.153. 24X.
Fiche. 50-321, 81/08/25, 8303090360.

--8303090363 Forwards "Semiannual Rept for Plant Radioactive Effluent Releases, Jan-June 1981."
MANRY, M. Georgia Power Co. 81/08/25. Director's Office, Office of Inspection and Enforcement. 1p. 17470.154. 24X.
Fiche. 50-321, 81/08/25, 8303090360.

--8303090368 "Semiannual Rept for Plant Radioactive Effluent Releases, Jan-June 1981."
* Georgia Power Co. 81/08/25. 43pp. 17470.155. 24X.
Fiche. 50-321, 81/08/25, 8303090360.

8303090188 Forwards "Semiannual Rept Plant Radioactive Effluent Releases, Jul-Dec 1981."
MANRY, M. Georgia Power Co. 82/02/25. O'REILLY, J. P. Region 2, Office of Director. 1p. 17472.302. 24X Fiche. 50-321, 82/02/25, 8303090188.

8303030213 Forwards "Semiannual Rept Plant Radioactive Effluent Releases, Jul-Dec 1982."
NIX, H. C. Georgia Power Co. 83/02/23. Director's Office, Office of Inspection and Enforcement. 1p. 17411.283. 24X.
Fiche. 50-321, 83/02/23, 8303030213.

--8303030220 Forwards "Semiannual Rept Plant Radioactive Effluent Releases, Jul-Dec 1982."
NIX, H. C. Georgia Power Co. 83/02/23. O'REILLY, J. P. Region 2, Office of Director. 1p. 17411.284. 24X Fiche. 50-321, 83/02/23, 8303030213.

--8303030228 "Semiannual Rept Plant Radioactive Effluent Releases, Jul-Dec 1982."
* Georgia Power Co. 83/02/23. 51pp. 17411.285. 24X.
Fiche. 50-321, 83/02/23, 8303030213.

8303150478 Forwards monthly operating repts for Feb 1983.
NIX, H. C. Georgia Power Co. 83/03/09. Director's Office, Office of Inspection and Enforcement. 1p. 17568.253. 24X.
Fiche. 50-321, 83/03/09, 8303150478.

--8303150480 Monthly operating repts for Feb 1983.
SEWELL, S. K. Georgia Power Co. 83/03/10. 44pp. 17568.254. 24X.
Fiche. 50-321, 83/03/09, 8303150478.

8303160583 Forwards monthly operating repts for Feb 1983.
NIX, H. C. Georgia Power Co. 83/03/09. NRC - No Detailed Affiliation Given. 1p. 17587.022. 24X Fiche. 50-321, 83/03/09, 8303160583.

--8303160588 Monthly operating repts for Feb 1983.
SEWELL, S. K. Georgia Power Co. 83/03/10. 44pp. 17587.023. 24X.
Fiche. 50-321, 83/03/09, 8303160583.

S Reportable occurrences, LERs & related correspondence

8302150605 Forwards updated LER 82-023/03X-1.
NIX, H. C. Georgia Power Co. 83/02/03. O'REILLY, J. P. Region 2, Office of Director. 1p. 17154.111. 24X Fiche. 50-366, 83/02/03, 8302150605.

--8302150615 Updated LER 82-023/03X-1 on 820312. Wyle Labs personnel noted pilot sensing tube missing from safety relief valve B during bench testing of main steam safety relief valves. Caused by failure of welds holding sensing tube. Tube replaced.
SUMNER, H. L. Georgia Power Co. 83/02/03. Region 2, Office of Director. 1p. 17154.112. 24X Fiche. 50-366, 83/02/03, 8302150605.

8303210694 RO on 830208, 14-day limit for isolation of spray/sprinkler sys protecting east cableway expired. Sys isolated to perform necessary mods. Mod work continuing. Mod will be completed by mid-Mar 1983.
NIX, H. C. Georgia Power Co. 83/02/24. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17635.290. 24X Fiche. 50-366, 83/02/24, 8303210694.

8303150482 Forwards updated LER 79-048/03X-1.
NIX, H. C. Georgia Power Co. 83/03/01. Region 2, Office of Director. 1p. 17561.030. 24X Fiche. 50-366, 83/03/01, 8303150482.

--8303150495 Updated LER 79-048/03X-1 on 790603, at 86% power, average drywell temp discovered at 135.3 F. High temp caused by control rod drive access to underside of vessel through biological shield left off during drywell closeout.
SUMNER, H. L. Georgia Power Co. 83/03/01. Region 2, Office of Director. 1p. 17561.031. 24X Fiche. 50-366, 83/03/01, 8303150482.

8303180363 Forwards LER 83-008/03L-0.
NIX, H. C. Georgia Power Co. 83/03/03. O'REILLY, J. P. Region 2, Office of Director. 1p. 17621.071. 24X Fiche. 50-366, 83/03/03, 8303180363.

--8303180370 LER 83-008/03L-0 on 830207, reactor coolant recirculation pump 2A tripped. Cause attributed to spurious trip of 4160-volt bus. Volt bus re-energized & pump restarted.
TIPPS, S. B. Georgia Power Co. 83/03/03. Region 2, Office of Director. 1p. 17621.072. 24X Fiche. 50-366, 83/03/03, 8303180363.

8303210406 Forwards LER 83-009/03L-0.
NIX, H. C. Georgia Power Co. 83/03/08. O'REILLY, J. P. Region 2, Office of Director. 1p. 17634.266. 24X Fiche. 50-366, 83/03/08, 8303210406.

--8303210413 LER 83-009/03L-0 on 830212. RCIC trip & throttle valve failed to manually trip. Caused by failed torque switch in Limitorque valve operator. Torque switch replaced. RCIC trip & throttle valve reset.
TIPPS, S. B. Georgia Power Co. 83/03/08. Region 2, Office of Director. 1p. 17634.267. 24X Fiche. 50-366, 83/03/08, 8303210406.

8303210316 Forwards LER 83-003/03L-0.
NIX, H. C. Georgia Power Co. 83/03/10. O'REILLY, J. P. Region 2, Office of Director. 1p. 17632.061. 24X Fiche. 50-366, 83/03/10, 8303210316.

# DOCKETED ITEMS

--8303210320 LER 83-003/03L-0 on 830214, drywell 2(HO) B analyzer would not calibr Cause not stated Sample pump head assemblies & diaphragms replaced & bypass check valves cleaned A & B analyzers will be replaced w/improved model
TIPPS, S B Georgia Power Co 83/03/10 Region 2, Office of Director 1p 17632 062 24X Fiche 50-366, 83/03/10, 8303210316

8303210412 Forwards LER 83-011/03L-0
NIX, H C Georgia Power Co 83/03/10 O'REILLY, J P Region 2, Office of Director 1p 17634 256 24X Fiche 50-366, 83/03/10, 8303210412

--8303210419 LER 83-011/03L-0 on 830210, during shift surveillance check procedure, drywell torus temp recorder found inoperable Caused by failed internal parts Parts replaced
TIPPS, S B Georgia Power Co 83/03/10 Region 2, Office of Director 1p 17634 259 24X Fiche 50-366, 83/03/10, 8303210412

8303210517 Forwards updated LER 80-113/03X-1
NIX, H C Georgia Power Co 83/03/10 O'REILLY, J P Region 2, Office of Director 1p 17632 216 24X Fiche 50-366, 83/03/10, 8303210517

--8303210527 Updated LER 80-113/03X-1 on 800726, scram discharge vol hi level switches A & D found inoperable following scram per IE Bulletin 80-17 Caused by crushed floats on both switches New switches installed
SUMNER, H L Georgia Power Co 83/03/10 Region 2, Office of Director 2pp 17632 217 24X Fiche 50-366, 83/03/10, 8303210517

V Operator Examinations

8303010551 Submits schedule for site visits to conduct operator licensing/instructor exams through Feb 1986, in response to 830111 Generic Ltr 83-01
GUCWA, L T Georgia Power Co 83/02/23 EISENHUT, D G Division of Licensing 2pp 17343 035 24X Fiche 50-321, 83/02/23, 8303010551

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee " Svc list encl
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000, 83/02/24, 8302250505

DOCKET 50-367 BAILLY GENERATING STATION

A Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants For OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24X Fiche 50-000, 83/02/16, 8302170082

H General correspondence

8303300062 Responds to 830302 proposal re closing LPDRs for cancelled or deferred plants No objection to closing LPDRs for submitted plants Other LPDRs will remain open pending resolution of CP status
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/03/18 FELTON, J M Division of Rules and Records 3pp 17751 074 24X Fiche 50-000, 83/03/18, 8303300062

DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2

F Security, medical, emergency & fire protection plans

8303280252 Notifies that emergency notification sys telephone will be moved within technical support ctr per 821210 request Health physics network telephone will not be moved due to changeover to FTS
SEIDLE, W C Region 4, Office of Director 83/01/25 CAVANAUGH, W Arkansas Power & Light Co 1p 17706 281 24X Fiche 50-313, 83/01/25, 8303280252

--8303280266 Requests that emergency notification sys & health physics network telephones be moved to main floor of technical support ctr to be available for Mar 1983 emergency preparedness exercise
MARSHALL, J R Arkansas Power & Light Co 82/12/10 SEIDLE, W C Region 4, Office of Director 2pp 17706 282 24X Fiche 50-313, 83/01/25, 8303280252

8303010237 Forwards IE Insp Repts 50-313/82-24 & 50-368/82-21 on 820728-29 Violation re prompt public notification corrected No further info required
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/02/11 CAVANAUGH, W Arkansas Power & Light Co 2pp 17335 179 24X Fiche 50-313, 83/02/11, 8303010237

--8303010247 IE Insp Repts 50-313/82-24 & 50-368/82-21 on 820728-29 Noncompliance noted lack of capability for providing prompt public notification in portion of plume exposure pathway
HACKNEY, C A , WHITEACRE, M , JOHNSON, W D Division of Resident, Reactor Project & Engineering Programs 83/02/09 7pp 17335 181 24X Fiche 50-313, 83/02/11, 8303010237

8303010641 Requests assistance in determining optional locations for emergency notification sys & health physics network (HPN) phones in emergency response facilities, supplementing NUREG-0696 Replacement of HPN lines w/FTS lines considered
COLLINS, J T Region 4, Office of Director 83/02/24 CAVANAUGH, W Arkansas Power & Light Co 2pp 17336 112 24X Fiche 50-313, 83/02/24, 8303010641

8303010682 Ack receipt of 830112 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/82-15 & 50-368/82-12
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/02/25 CAVANAUGH, W Arkansas Power & Light Co 1p 17341 160 24X Fiche 50-313, 83/02/25, 8303010682

--8303010685 Responds to NRC 821112 ltr re violations noted in IE Insp Repts 50-313/82-15 & 50-368/82-12 Closed end rigid metal conduit penetrating frame will not significantly affect fire resistant ability of door assemblies
MARSHALL, J R Arkansas Power & Light Co 83/01/12 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 2pp 17341 161 24X Fiche 50-313, 83/02/25, 8303010682

8303090576 Releases public version of util 821210 ltr re distribution of emergency instructions to transient population
FELTON, J M Division of Rules and Records 83/03/02 Document Management Branch 1p 17480 147 24X Fiche 50-313, 83/03/02, 8303090576

--8303090583 Forwards public version of util 821210 ltr re distribution of emergency instructions to transient population
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/02/08 CAVANAUGH, W Arkansas Power & Light Co 2pp 17480 148 24X Fiche 50-313, 83/03/02, 8303090576

--8303090594 Submits public version of info re distribution of emergency instructions to transient population Program will be implemented within 90 days
MARSHALL, J R Arkansas Power & Light Co 82/12/10 COLLINS, J T Region 4, Office of Director 2pp 17480 150 24X Fiche 50-313, 83/03/02, 8303090576

8303210234 Application for amend to Licenses DPR-51 & NPF-6, changing Tech Specs to require annual audits of emergency plan & security plan
GRIFFIN, J M Arkansas Power & Light Co 83/03/15 STOLZ, J F Operating Reactors Branch 4 2pp 17632 170 24X Fiche 50-313, 83/03/15, 8303210234

--8303210244 Proposed Tech Specs re annual audits of emergency plan & security plan
* Arkansas Power & Light Co 83/03/15 3pp 17632 172 24X Fiche 50-313, 83/03/15, 8303210234

8303230160 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/03/16 Document Management Branch 1p 17687 108 24X Fiche 50-313, 83/03/16, 8303230160

--8303230164 Forwards public version of Rev 4 to Emergency Plan Implementing Procedure 1903.42, "Duties of Emergency Medical Team " Receipt form encl
* Arkansas Power & Light Co 83/03/03 NRC - No Detailed Affiliation Given 1p 17687 109 24X Fiche 50-313, 83/03/16, 8303230160

--8303230170 Public version of Rev 4 to Emergency Plan Implementing Procedure 1903.42, "Duties of Emergency Medical Team " Revised index encl
LEVINE, J M Arkansas Power & Light Co 83/03/03 4pp 17687 110 24X Fiche 50-313, 83/03/16, 8303230160

8303240469 Ack receipt of 830217 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/82-33 & 50-368/82-33
SEIDLE, W C Region 4, Office of Director 83/03/18 GRIFFIN, J M Arkansas Power & Light Co 1p 17678 036 24X Fiche 50-313, 83/03/18, 8303240469

--8303240478 Responds to NRC 830118 ltr re violations noted in IE Insp Repts 50-313/82-33 & 50-368/82-33. Corrective actions: nonconformance rept procedure revised; fire watch established & independent walkdown of fire barriers conducted.
MARSHALL, J. R. Arkansas Power & Light Co. 83/02/17 SEIDLE, W. C. Region 4, Office of Director 4pp 17678.037 24X
Fiche: 50-313, 83/03/18, 8303240469.

8303250001 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 83/03/21 Document Management Branch 1p 17710.139 24X Fiche: 50-313, 83/03/21, 8303250001.

--8303250004 Forwards public version of revised emergency plan implementing procedures, including Procedures 1903.30 re plant evacuation, 1903.50 re emergency response organization & 1904.07 re protective action recommendations.
* Arkansas Power & Light Co. 83/03/10 NRC - No Detailed Affiliation Given 3pp 17710.140 24X Fiche: 50-313, 83/03/21, 8303250001.

--8303250005 Public version of revised emergency plan implementing procedures, including Procedures 1903.30 re plant evacuation, 1903.50 re emergency response organization & 1904.07 re protective action recommendations.
* Arkansas Power & Light Co. 83/03/10 32pp 17710.143 24X Fiche: 50-313, 83/03/21, 8303250001.

8303290634 Releases public version of distribution list of emergency instructions to transient population.
FELTON, J. M. Division of Rules and Records 83/03/23 Document Management Branch 1p 17745.153 24X Fiche: 50-313, 83/03/23, 8303290634.

--8303290641 Forwards public version of distribution list of emergency instructions to transient population.
MARSHALL, J. R. Arkansas Power & Light Co. 83/02/25 COLLINS, J. T. Region 4, Office of Director 6pp 17745.154 24X
Fiche: 50-313, 83/03/23, 8303290634.

8303290669 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records 83/03/23 Document Management Branch 1p 17742.320 24X Fiche: 50-313, 83/03/23, 8303290669.

--8303290685 Forwards public version of Rev 8 to Emergency Plan Implementing Procedure 1903.10, "Emergency Action Level Response," Receipt form encl.
* Arkansas Power & Light Co. 83/03/04 NRC - No Detailed Affiliation Given 2pp 17742.321 24X Fiche: 50-313, 83/03/23, 8303290669.

--8303290699 Public version of Rev 8 to Emergency Plan Implementing Procedure 1903.10, "Emergency Action Level Response."
LEVINE, J. M. Arkansas Power & Light Co. 83/03/04 13pp 17742.323 24X Fiche: 50-313, 83/03/23, 8303290669.

8303290708 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records 83/03/23 Document Management Branch 1p 17745.173 24X Fiche: 50-313, 83/03/23, 8303290708.

--8303290711 Forwards public version of Rev 6 to Emergency Plan Implementing Procedure 1903.30, "Plant Evacuation."
* Arkansas Power & Light Co. 83/03/09 NRC - No Detailed Affiliation Given 2pp 17745.174 24X Fiche: 50-313, 83/03/23, 8303290708.

--8303290716 Public version of Rev 6 to Emergency Plan Implementing Procedure 1903.30, "Plant Evacuation."
LEVINE, J. M. Arkansas Power & Light Co. 83/03/08 21pp 17745.176 24X Fiche: 50-313, 83/03/23, 8303290708.

8303300044 Releases public version of rev to emergency plan procedure.
FELTON, J. M. Division of Rules and Records 83/03/23 Document Management Branch 1p 17751.126 24X Fiche: 50-313, 83/03/23, 8303300044.

--8303300049 Forwards public version of Rev 6 to Emergency Plan Procedure 1903.23, "Personnel Emergency."
* Arkansas Power & Light Co. 83/03/08 NRC - No Detailed Affiliation Given 2pp 17751.127 24X Fiche: 50-313, 83/03/23, 8303300044.

--8303300054 Public version of Rev 6 to Emergency Plan Procedure 1903.23, "Personnel Emergency."
LEVINE, J. M. Arkansas Power & Light Co. 83/03/07 8pp 17751.129 24X Fiche: 50-313, 83/03/23, 8303300044.

8303290015 Notifies of repts received from several utils re telephone inquiries from unidentified persons re plant security sys. Investigation revealed that individual was personnel recruiter. Individual cautioned.
COLLINS, J. T. Region 4, Office of Director 83/03/25 GRIFFIN, J. M. Arkansas Power & Light Co. 2pp 17722.249 24X
Fiche: 50-313, 83/03/25, 8303290015.

8303300610 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records 83/03/25 Document Management Branch 1p 17768.294 24X Fiche: 50-313, 83/03/25, 8303300610.

--8303300619 Forwards public version of Rev 2 to Emergency Plan Implementing Procedure 1903.61, "Communications Equipment Tests."
* Arkansas Power & Light Co. 83/03/17 NRC - No Detailed Affiliation Given 1p 17768.295 24X Fiche: 50-313, 83/03/25, 8303300610.

--8303300633 Public version of Rev 2 to Emergency Plan Implementing Procedure 1903.61, "Communications Equipment Tests." Revised index encl.
LEVINE, J. M. Arkansas Power & Light Co. 83/03/16 7pp 17768.296 24X Fiche: 50-313, 83/03/25, 8303300610.

H. General correspondence

8303110240 Designates J. Griffin as senior nuclear mgt representative for util.
CAVANAUGH, W. Arkansas Power & Light Co. 83/02/17 COLLINS, J. T. Region 4, Office of Director 2pp 17518.361 24X
Fiche: 50-313, 83/02/17, 8303110240.

8303040594 Forwards revised distribution list to reflect changes in State of AR Dept of Health & util organizations.
MARSHALL, J. R. Arkansas Power & Light Co. 83/03/01 STOLZ, J. F. Operating Reactors Branch 4 CLARK, R. A. Operating Reactors Branch 3 2pp 17373.316 24X Fiche: 50-313, 83/03/01, 8303040594.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492.033 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303030703 Notification of 830307 meeting w/utils & NUS Corp in Bethesda, MD to discuss proposed rev to 10CFR40 36 (Tech Specs).
BRINKMAN, D. S. Standardization & Special Projects Branch 83/02/22
THOMAS, C. O. Standardization & Special Projects Branch 2pp
17363.227 24X Fiche: 50-000, 83/02/22, 8303030703.

8303090239 Forwards seven oversize revised P&IDs. Aperture cards are available in PDR.
SHIVELY, C. Arkansas Power & Light Co. 83/02/22 NRC - No Detailed Affiliation Given 7pp 17473.149 24X
Fiche: 50-368, 83/02/22, 8303090239.

8302010415 Application for amend to Licenses DPR-51 & NPF-6, revising Tech Specs to change in-core detector surveillance requirements & to correct various typographical, title & ref errors.
GRIFFIN, J. M. Arkansas Power & Light Co. 83/02/23 CLARK, R. A. Operating Reactors Branch 3 STOLZ, J. F. Operating Reactors Branch 4 2pp 17343.231 24X Fiche: 50-313, 83/02/23, 8303010415.

--8303010417 Proposed Tech Specs re in-core detector surveillance requirements.
* Arkansas Power & Light Co. 83/02/23 28pp 17343.233 24X
Fiche: 50-313, 83/02/23, 8303010415.

8303040333 Responds to 830206 ltr re schedule for core protection computer mods to correct low power density penalty factor. Correction will be provided during next software update. Schedule should be available by 830530.
MARSHALL, J. R. Arkansas Power & Light Co. 83/02/25 CLARK, R. A. Operating Reactors Branch 3 1p 17422.004 24X
Fiche: 50-368, 83/02/25, 8303040333.

8303040348 Application for amend to Licenses DPR-51 & NPF-6, changing Tech Specs Section 6 to require annual reporting of safety & relief valve challenges, in response to NRC 820920 Generic Ltr 82-16.
GRIFFIN, J. M. Arkansas Power & Light Co. 83/02/25 STOLZ, J. F. Operating Reactors Branch 4 CLARK, R. A. Operating Reactors Branch 3 2pp 17374.321 24X Fiche: 50-313, 83/02/25, 8303040348.

--8303040353 Proposed changes to Tech Specs Section 6 requiring annual reporting of safety & relief valve challenges
* Arkansas Power & Light Co 83/02/25 2pp 17374 323 24X
Fiche 50-313, 83/02/25, 8303040348

8303040407 Advises that efforts underway & progress being made toward compliance w/B20210 order for mod of license re detection of inadequate core cooling Response expected by B30415
MARSHALL, J R Arkansas Power & Light Co 83/02/25 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 2pp 17374 307 24X Fiche 50-313, 83/02/25, 8303040407

8303290222 Forwards procedures re resins involved in high integrity container exothermic reaction, per B30204 telecopy request
MARSHALL, J R Arkansas Power & Light Co 83/02/25 SEIDLE, W C
Region 4, Office of Director 4pp 17722 178 24X
Fiche 50-368, 83/02/25, 8303290222

--8303290226 Rev 1 to Procedure 1409 26, "Resin Transfer From T-13 to Transport Cask."
* Arkansas Power & Light Co 82/05/24 13pp 17722 182 24X
Fiche 50-368, 83/02/25, 8303290222

--8303290230 Rev 1 to Procedure 1603 006, "Disposal of Spent Radioactive Resin."
* Arkansas Power & Light Co 82/11/18 7pp 17722 195 24X
Fiche 50-368, 83/02/25, 8303290222

--8303290236 Rev 1 to Procedure 2104 17, "Spent Fuel Resin Transfer."
* Arkansas Power & Light Co 82/07/08 14pp 17722 202 24X
Fiche 50-368, 83/02/25, 8303290222

--8303290244 Rev 2 to Procedure 2409 13, "Resin Transfer From 2T13."
* Arkansas Power & Light Co 82/08/23 15pp 17722 216 24X
Fiche 50-368, 83/02/25, 8303290222

8303040597 Requests extension for submittal of response to App I Tech Specs Revised response schedule will be submitted by B30311
MARSHALL, J R Arkansas Power & Light Co 83/02/28 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 1p 17374 283 24X Fiche 50-313, 83/02/28, 8303040597

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X
Fiche 50-000, 83/03/02, 8303020321

8303080062 Forwards addl chemical engineering info re proposed spent fuel storage expansion, per NRC B30110 request Demineralized resins more than adequate to maintain water quality for 1 yr under normal circumstances
MARSHALL, J R Arkansas Power & Light Co 83/03/03 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 2pp 17457 227 24X Fiche 50-313, 83/03/03, 8303080062

8303080299 Forwards addl info re proposed spent fuel storage expansion per B30124 request Proposed Tech Specs associated w/rack expansion address NUREG-0830 elements Administrative controls established to prevent loading errors
MARSHALL, J R Arkansas Power & Light Co 83/03/03 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 6pp 17449 321 24X Fiche 50-313, 83/03/03, 8303080299

8303160388 Forwards addl info re proposed spent fuel storage expansion, in response to NRC B30105 request W/14 oversize drawings Proprietary drawings withheld (ref 10CFR2 790) Proprietary aperture cards in Central Files, nonproprietary in PDR
MARSHALL, J R Arkansas Power & Light Co 83/03/03 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 81pp 17591 140 24X Fiche 50-313, 83/03/03, 8303160388

--8303160395 Application for withholding seven oversize proprietary drawings (ref 10CFR2 790) Affidavit encl
WIESEMANN, R A Westinghouse Electric Corp 83/02/21 STOLZ, J F
Operating Reactors Branch 4 6pp 17591 221 24X
Fiche 50-313, 83/03/03, 8303160388

8303110328 Advises that written notification of determination to reaffirm or withdraw request for hearing re order imposing environ qualification requirements will be submitted by B30324
MARSHALL, J R Arkansas Power & Light Co 83/03/04 EISENHUT, D G
Division of Licensing 1p 17512 354 24X Fiche 50-313, 83/03/04, 8303110328

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12) Svc list encl
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 51pp 17660 176 24X
Fiche 50-000, 83/03/07, 8303040005

8303110352 Forwards addl info re spent fuel storage expansion per B30201 request Seismic analysis performed using combined weights of fuel assembly & control rod assembly in each cell location
MARSHALL, J R Arkansas Power & Light Co 83/03/07 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 29pp 17506 247 24X Fiche 50-313, 83/03/07, 8303110352

8303140059 Notifies that info re spent fuel storage expansion will be submitted by end of current wk in response to B30215 request
MARSHALL, J R Arkansas Power & Light Co 83/03/07 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 1p 17540 172 24X Fiche 50-313, 83/03/07, 8303140059

8303160051 Forwards request for addl info re expected dose to onsite personnel during spent fuel pool expansion
CLARK, R A Operating Reactors Branch 4 83/03/07 GRIFFIN, J M
Arkansas Power & Light Co 3pp 17615 001 24X
Fiche 50-313, 83/03/07, 8303160051

8303140370 Forwards response to NRC B30215 request for addl info re proposed spent fuel storage expansion Poison surveillance program which allows access to representative poison samples will be utilized
MARSHALL, J R Arkansas Power & Light Co 83/03/10 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 4pp 17543 320 24X Fiche 50-313, 83/03/10, 8303140370

8303150340 Advises of B30405 meeting w/licensees & major contractors at Dallas/Fort Worth, TX to provide info & guidance re 10CFR50 QA & Tech Spec deviations & discuss decentralization policy Questions should be submitted in writing by B30321
COLLINS, J T Region 4, Office of Director 83/03/10 Public Service Co of Colorado 12pp 17562 291 24X
Fiche 50-000, 83/03/10, 8303150340

8303150257 Notifies of B30405 public meeting at Dallas/Fort Worth, TX Airport to discuss NRC decentralization policy & changes to 10CFR30 reporting requirements
COLLINS, J T Region 4, Office of Director 83/03/11 GRIFFIN, J M
Arkansas Power & Light Co 3pp 17555 215 24X
Fiche 50-313, 83/03/11, 8303150257

8303210399 Requests extension until B30930 for submittal of complete up-to-date App I Tech Specs Review of App I hampered by manpower availability as result of back-to-back refueling outages
MARSHALL, J R Arkansas Power & Light Co 83/03/11 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 2pp 17634 151 24X Fiche 50-313, 83/03/11, 8303210399

8303240067 Forwards Amends 72 & 40 to Licenses DPR-51 & NPF-6, respectively & notice of issuance & availability Amends revise App B ETS re nonradiological water quality-related requirements
STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 83/03/11 GRIFFIN, J Arkansas Power & Light Co 5pp 17694 198 24X Fiche 50-313, 83/03/11, 8303240067

--8303240073 Amends 72 & 40 to Licenses DPR-51 & NPF-6, respectively, revising App B ETS re nonradiological water quality-related requirements of Federal Water Pollution Control Act amends of 1972
STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 83/03/11 34pp 17694 203 24X
Fiche 50-313, 83/03/11, 8303240067

--8303240080 Notice of issuance & availability of Amends 72 & 40 to Licenses DPR-51 & NPF-6, respectively
CLARK, R A Operating Reactors Branch 3 83/03/11 2pp
17694 237 24X Fiche 50-313, 83/03/11, 8303240067

8303290049 Forwards order confirming licensee commitments on post-TMI-related issues Order based on commitments in Generic Ltrs 82-05 & 82-10
CLARK, R A Operating Reactors Branch 3 83/03/14 CAVANAUGH, W
Arkansas Power & Light Co 3pp 17729 278 24X
Fiche 50-368, 83/03/14, 8303290049

--8303290054 Order confirming licensee commitments on post-TMI-related issues
PURPLE, R A Division of Licensing 83/03/14 Arkansas Power & Light Co 8pp 17729 281 24X Fiche 50-368, 83/03/14, 8303290049

8303210234 Application for amend to Licenses DPR-51 & NPF-6, changing Tech Specs to require annual audits of emergency plan & security plan
GRIFFIN, J M Arkansas Power & Light Co 83/03/15 STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 2pp 17632 170 24X Fiche 50-313, 83/03/15, 8303210234

--8303210244 Proposed Tech Specs re annual audits of emergency plan & security plan
* Arkansas Power & Light Co 83/03/15 3pp 17632 172 24X Fiche 50-313, 83/03/15, 8303210234

8303210277 Forwards cooldown & heatup dates for each unit since OL issuance & Tech Spec changes re reactor bldg purge valves Action initiated to install key lock switches on containment purge valves by next refueling outage per 830127 request
GRIFFIN, J M Arkansas Power & Light Co 83/03/16 STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 6pp 17632 036 24X Fiche 50-313, 83/03/16, 8303210277

--8303210283 Proposed Tech Spec changes re reactor bldg purge valves
* Arkansas Power & Light Co 83/03/16 2pp 17632 042 24X Fiche 50-313, 83/03/16, 8303210277

8303210329 Forwards outline of schedule for spent fuel storage expansion Response by 830325 requested so util can adjust planning & work plans
MARSHALL, J R Arkansas Power & Light Co 83/03/16 STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 4pp 17632 117 24X Fiche 50-313, 83/03/16, 8303210329

8303250133 Forwards supplemental response to 830309 request for addl info re spent fuel storage expansion
MARSHALL, J R Arkansas Power & Light Co 83/03/21 STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 3pp 17693 012 24X Fiche 50-313, 83/03/21, 8303250133

8303290419 Forwards response to NRC 830318 request for addl info re util 821105 proposed expansion of spent fuel storage in fuel pool No changes to NPDES will be submitted since no addl nonradiological wastes will be discharged from reracking
MARSHALL, J R Arkansas Power & Light Co 83/03/24 STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 2pp 17726 282 24X Fiche 50-313, 83/03/24, 8303290419

Q Inspection reports, IE Bulletins & correspondence

8303180430 Forwards IE Insp Repts 50-313/82-38 & 50-368/82-28 on 821004-08 No noncompliance noted
SEIDLE, W C Region 4, Office of Director 83/01/05 CAVANAUGH, W Arkansas Power & Light Co 2pp 17621 165 24X Fiche 50-313, 83/01/05, 8303180430

--8303180433 IE Insp Repts 50-313/82-38 & 50-368/82-28 on 821004-08 No noncompliance noted Major areas inspected: procedures, advanced planning & preparations, training, exposure control, posting & control & audits
BAER, R , HOLLEY, W , MURRAY, B Region 4, Office of Director 82/12/17 21pp 17621 167 24X Fiche 50-313, 83/01/05, 8303180430

8303010513 Submits addl info re IE Bulletin 82-01, Rev 1, Supp 1, "Alterations of Radiographs of Welds in Piping Subassemblies," in response to NRC 830107 request W/two oversize drawings Aperture cards are available in PDR
MARSHALL, J R Arkansas Power & Light Co 83/02/03 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 4pp 17343 042 24X Fiche 50-368, 83/02/03, 8303010513

8303010237 Forwards IE Insp Repts 50-313/82-24 & 50-368/82-21 on 820728-29 Violation re prompt public notification corrected No further info required
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/02/11 CAVANAUGH, W Arkansas Power & Light Co 2pp 17335 179 24X Fiche 50-313, 83/02/11, 8303010237

--8303010247 IE Insp Repts 50-313/82-24 & 50-368/82-21 on 820728-29 Noncompliance noted: lack of capability for providing prompt public notification in portion of plume exposure pathway
HACKNEY, C A , MONTGOMERY, J L , WASHINGTON, K E Division of Resident, Reactor Project & Engineering Programs 83/02/09 7pp 17335 181 24X Fiche 50-313, 83/02/11, 8303010237

8303210547 Forwards IE Insp Repts 50-313/83-01 & 50-368/83-01 on 830101-31 & notice of violation
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/02/17 CAVANAUGH, W Arkansas Power & Light Co 2pp 17632 252 24X Fiche 50-313, 83/02/17, 8303210547

--8303210562 IE Insp Repts 50-313/83-01 & 50-368/83-01 on 830101-31 Noncompliance noted: specific gravity readings not taken in accordance w/procedures
CALLAN, L J , CUMMINS, J E , JOHNSON, W D Region 4, Office of Director 83/02/16 10pp 17632 255 24X Fiche 50-313, 83/02/17, 8303210547

8303010509 Ack receipt of 830203 ltr forwarding INPO rept dtd 830107, in response to requirements of 830118 confirmatory order modifying license Requests status of actions w/respect to recommendations in rept
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/02/23 CAVANAUGH, W Arkansas Power & Light Co 1p 17337 239 24X Fiche 50-368, 83/02/23, 8303010509

--8303010519 Forwards INPO assessment of regulatory response & commitment control program in response to 830118 ltr & order to satisfy requirement of Article IV of order
MARSHALL, J R Arkansas Power & Light Co 83/02/03 COLLINS, J T Region 4, Office of Director 9pp 17337 240 24X Fiche 50-368, 83/02/23, 8303010509

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 111pp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367

8303010682 Ack receipt of 830112 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/82-15 & 50-368/82-12
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 83/02/25 CAVANAUGH, W Arkansas Power & Light Co 1p 17341 160 24X Fiche 50-313, 83/02/25, 8303010682

--8303010685 Responds to NRC 821112 ltr re violations noted in IE Insp Repts 50-313/82-15 & 50-368/82-12 Closed end rigid metal conduit penetrating frame will not significantly affect fire resistant ability of door assemblies
MARSHALL, J R Arkansas Power & Light Co 83/01/12 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 2pp 17341 161 24X Fiche 50-313, 83/02/25, 8303010682

8303040611 Submits resolution to snubber surveillance issue Program would test mechanical & hydraulic snubbers which are nuclear safety-related in accordance w/ANSI/ASME OM-4 1982 Past insp will be utilized as baseline for insp program
MARSHALL, J R Arkansas Power & Light Co 83/02/28 STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 3pp 17368 022 24X Fiche 50-313, 83/02/28, 8303040611

8303080272 Responds to IE Bulletin 82-04 "Deficiencies in Primary Containment Electrical Penetration Assemblies." No Bunker Ramo assemblies installed at Unit 1 No defects or failures identified at Unit 2
MARSHALL, J R Arkansas Power & Light Co 83/03/03 COLLINS, J T Region 4, Office of Director 3pp 17454 310 24X Fiche 50-313, 83/03/03, 8303080272

8303110332 Responds to IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Westinghouse DB-50 breakers not used Unit 1 uses GE AK-2A-25 breakers & Unit 2 uses GE AK-2-25 breakers
REUTER, D A Arkansas Power & Light Co 83/03/04 COLLINS, J T Region 4, Office of Director 2pp 17512 333 24X Fiche 50-313, 83/03/04, 8303110332

8303290439 Advises that addl info in response to IE Bulletin 82-02 will be provided by 830324
MARSHALL, J R Arkansas Power & Light Co 83/03/10 SEIDLE, W C Region 4, Office of Director 1p 17725 358 24X Fiche 50-368, 83/03/10, 8303290439

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc 117pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8303240469 Ack receipt of 830217 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/82-33 & 50-368/82-33
SEIDLE, W C Region 4, Office of Director 83/03/18 GRIFFIN, J M Arkansas Power & Light Co 1p 17678 036 24X Fiche 50-313, 83/03/18, 8303240469

--8303240478 Responds to NRC 830118 ltr re violations noted in IE Insp Repts 50-313/82-33 & 50-368/82-33 Corrective actions nonconformance rept procedure revised, fire watch established & independent walkdown of fire barriers conducted
MARSHALL, J R Arkansas Power & Light Co 83/02/17 SEIDLE, W C
Region 4, Office of Director 4pp 17678 037 24X
Fiche 50-313, 83/03/18, 8303240469

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 12lpp 17774 352 24X Fiche 50-000, 83/03/21, 8212060387

8303280017 Responds to Item 4 of IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Surveillance tests of undervoltage trip function performed Devices functioned properly
REUTER, D A Arkansas Power & Light Co 83/03/21 COLLINS, J T
Region 4, Office of Director 7pp 17707 291 24X
Fiche 50-313, 83/03/21, 8303280017

R Periodic operating reports & related correspondence

8303080038 Forwards monthly operating rept for Dec 1982
MARSHALL, J R Arkansas Power & Light Co 83/01/14 HALLER, N M
Office of Resource Management, Director 1p 17458 200 24X
Fiche 50-368, 83/01/14, 8303080038

--8303080046 Monthly operating rept for Dec 1982
BRAMLETT, L S Arkansas Power & Light Co 83/01/14 6pp
17458 201 24X Fiche 50-368, 83/01/14, 8303080038

8303290063 Submits first monthly progress rept on regulatory response & commitment control program Interim guidelines implemented Next status rept scheduled for 830314
MARSHALL, J R Arkansas Power & Light Co 83/02/14 COLLINS, J T
Region 4, Office of Director 3pp 17722 337 24X
Fiche 50-313, 83/02/14, 8303290063

8303150517 Forwards monthly operating rept for Jan 1983
MARSHALL, J R Arkansas Power & Light Co 83/02/15 HALLER, N M
Office of Resource Management, Director 1p 17568 177 24X
Fiche 50-368, 83/02/15, 8303150517

--8303150527 Monthly operating rept for Jan 1983
BRAMLETT, L S Arkansas Power & Light Co 83/02/15 7pp
17568 178 24X Fiche 50-368, 83/02/15, 8303150517

S Reportable occurrences, LERs & related correspondence

8303030518 Forwards LER 83-006/03L-0
MARSHALL, J R Arkansas Power & Light Co 83/02/22 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 1p
17409 053 24X Fiche 50-368, 83/02/22, 8303030518

--8303030523 LER 83-006/03L-0 on 830202, while in Mode 1 at 33% power, control room A emergency chiller 2VE-1A tripped on high condenser pressure during preventive maint Caused by defective power supply Power supply replaced
ROGERS, P C Arkansas Power & Light Co 83/02/22 Region 4,
Office of Director 2pp 17409 054 24X Fiche 50-368, 83/02/22, 8303030518

8303030614 Forwards LER 83-005/03L-0
MARSHALL, J R Arkansas Power & Light Co 83/02/22 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 1p
17409 305 24X Fiche 50-368, 83/02/22, 8303030614

--8303030629 LER 83-005/03L-0 on 830201, emergency feedwater control valve 2CV-1025-1 failed to close while steam generator level adjustments being made Probably caused by low hydraulic fluid Hydraulic fluid added
ROGERS, P Arkansas Power & Light Co 83/02/22 Region 4,
Office of Director 2pp 17409 306 24X Fiche 50-368, 83/02/22, 8303030614

8303150481 Forwards LER 83-007/03L-0
MARSHALL, J R Arkansas Power & Light Co 83/02/28 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 1p
17568 243 24X Fiche 50-368, 83/02/28, 8303150481

--8303150484 LER 83-007/03L-0 on 830203, while in Mode 3 at 86% full power, hydraulic pump for operator for emergency feedwater control valve 2CV-1075-1 determined to need replacing On 830204 & 17, valve failed to close during reduction of flow
ROGERS, P C Arkansas Power & Light Co 83/02/28 Region 4,
Office of Director 2pp 17568 244 24X Fiche 50-368, 83/02/28, 8303150481

8303150454 LER 83-009/01T-0 on 830304, determined response time of four RCS resistance temp detectors increased New penalty factors calculated & entered into affected core protection calculator on 830304
LEVINE, J M Arkansas Power & Light Co 83/03/05 COLLINS, J T
Region 4, Office of Director 1p 17561 076 24X
Fiche 50-368, 83/03/05, 8303150454

8303150328 PNO-IV-83-009A on 830308, train A containment spray inadvertently actuated No significant damage or unusual conditions noted in containment during containment entry Water analysis indicated sodium concentration within range
JAUDON, J P ; CALLAN, L J Region 4, Office of Director 83/03/09
1p 17563 036 24X Fiche 50-368, 83/03/09, 8303150328

8303240354 Forwards LER 83-008/03L-0
MARSHALL, J R Arkansas Power & Light Co 83/03/09 SEIDLE, W C
Division of Resident, Reactor Project & Engineering Programs 1p
17681 356 24X Fiche 50-368, 83/03/09, 8303240354

--8303240358 LER 83-008/03L-0 on 830207, assessment of fire barrier discrepancies updated Generally caused by inadequate work controls & surveillance methods Specific design change controls installed & program reassessed
DUGGER, L Arkansas Power & Light Co 83/03/09 Region 4,
Office of Director 3pp 17681 357 24X Fiche 50-368, 83/03/09, 8303240354

8303250021 Forwards LER 83-010/03L-0
MARSHALL, J R Arkansas Power & Light Co 83/03/17 SEIDLE, W C
Region 4, Office of Director 1p 17693 130 24X
Fiche 50-368, 83/03/17, 8303250021

--8303250027 LER 83-010/03L-0 on 830216, fires discovered at auto transformer connection & at oil circuit breaker connection of 22-kV supply line to startup transformer 3 Caused by failure of supply line connection due to trapped air
WADE, P B Arkansas Power & Light Co 83/03/17 Region 4,
Office of Director 2pp 17693 131 24X Fiche 50-368, 83/03/17, 8303250021

8303280154 Forwards LER 83-011/03L-0
MARSHALL, J R Arkansas Power & Light Co 83/03/18 SEIDLE, W C
Region 4, Office of Director 1p 17708 221 24X
Fiche 50-368, 83/03/18, 8303280154

--8303280187 LER 83-011/03L-0 on 830218, during Mode 3 & feeding of steam generators w/emergency feedwater pump 2P-7B, control valve 2CV-1036 failed to close Caused by shorted relay coil ITE Imperial 220-EB220PA-5 Relay replaced w/Gould relay
WADE, P B Arkansas Power & Light Co 83/03/18 Region 4,
Office of Director 1p 17708 222 24X Fiche 50-368, 83/03/18, 8303280154

8303280208 Forwards LER 83-009/01T-0
MARSHALL, J R Arkansas Power & Light Co 83/03/18 SEIDLE, W C
Region 4, Office of Director 1p 17708 209 24X
Fiche 50-368, 83/03/18, 8303280208

--8303280217 LER 83-009/01T-0 on 830225, during Mode 1 surveillance test, five resistance temp detectors had response time greater than required & s Caused by degradation of couplant Addl penalty factors in two affected channels installed
WADE, P B Arkansas Power & Light Co 83/03/18 Region 4,
Office of Director 5pp 17708 210 24X Fiche 50-368, 83/03/18, 8303280208

V Operator Examinations

8302250505 Generic Ltr 82-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl
EISENHUT, D G Division of Licensing 83/02/24 Consolidated
Edison Co of New York, Inc 18pp 24X Fiche 50-000, 83/02/24, 8302250505

8303070028 Forwards estimated schedule for operator licensing exams through 1985, in response to NRC 830111 Generic Ltr 83-01 No instructor certification exams planned during specified time frame
MARSHALL, J R Arkansas Power & Light Co 83/02/28 EISENHUT, D G
Division of Licensing 2pp 17434 337 24X Fiche 50-313, 83/02/28, 8303070028

DOCKET 50-369 WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 1

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303230239 SAFETY EVALUATION REPORT RELATED TO OPERATION OF MCGUIRE NUCLEAR STATION, UNITS 1 AND 2 Docket Nos. 50-369 And 50-370. (Duke Power Company)
* Office of Nuclear Reactor Regulation, Director. NUREG-0422 S06 83/02/28. 58pp. Available at NRC $5.50. 17685.030. 24X Fiche 50-369,83/02/28,8303230239.

8303180574 Forwards Suppl 6 to SER re application for OLs W/o encl.
NOVAK, T.M. Assistant Director for Licensing. 83/03/14. TUCKER, H.B. Duke Power Co. 2pp. 17640.042. 24X Fiche 50-369,83/03/14, 8303180574.

F. Security, medical, emergency & fire protection plans

8303010596 Forwards IE Insp Repts 50-369/83-01 & 50-370/83-01 on 830103-07 No noncompliance noted.
DANCE, H.C. Division of Project & Resident Programs. 83/02/02. TUCKER, H.B. Duke Power Co. 2pp. 17336.004. 24X Fiche 50-369,83/02/02,8303010596.

--8303010608 IE Insp Repts 50-369/83-01 & 50-370/83-01 on 830103-07 No noncompliance noted. Major areas inspected radiation protection & preoperational testing for Unit 2.
ALBRIGHT, R.H.; BARR, K.P. Division of Engineering & Radiological Safety Programs. 83/02/01. 5pp. 17336.006. 24X Fiche 50-369,83/02/02,8303010596.

8303100148 Releases public version of revised emergency plan implementing procedures.
FELTON, J.M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17503.012. 24X Fiche 50-369,83/03/02, 8303100148.

8303290475 Requests exemption from 10CFR50 App E, Item IV.F.h & 10CFR50.47 b(14) re active participation of crisis mgt ctr personnel for each station during annual emergency preparedness exercise.
TUCKER, H.B. Duke Power Co. 83/03/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 17724.324. 24X Fiche 50-000,83/03/09,8303290475.

8303150694 Responds to 830114 ltr submitting Rev 2 to safeguards contingency plan. Changes consistent w/10CFR50.54(p) & do not decrease effectiveness of plan.
ADENSAM, E.G. Licensing Branch 4. 83/03/10. TUCKER, H.B. Duke Power Co. 2pp. 17586.245. 24X Fiche 50-369,83/03/10,8303150694.

8303230057 Advises that changes listed in 821110 & 830125 ltrs re safeguards contingency plan acceptable. Encls to ltrs withheld (ref 10CFR2.790).
ADENSAM, E.G. Licensing Branch 4. 83/03/10. TUCKER, H.B. Duke Power Co. 2pp. 17688.346. 24X Fiche 50-369,83/03/10,8303230057.

8303240113 Releases public version of revised crisis mgt plan implementing procedures.
FELTON, J.M. Division of Rules and Records. 83/03/21. Document Management Branch. 1p. 17700.029. 24X Fiche 50-000,83/03/21, 8303240113.

--8303240120 Forwards public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.1 re recovery manager & immediate staff group plan & 5.3.4 re scheduling/planning support group.
TUCKER, H.B. Duke Power Co. 83/03/08. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 17700.030. 24X Fiche 50-000,83/03/21,8303240113.

--8303240127 Public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.1 re recovery manager & immediate staff group plan & 5.3.4 re scheduling/planning support group.
* Duke Power Co. 83/02/28. 175pp. 24X Fiche 50-000,83/03/21, 8303240113.

8303250091 Releases public version of revised emergency plan.
FELTON, J.M. Division of Rules and Records. 83/03/21. Document Management Branch. 1p. 17710.078. 24X Fiche 50-369,83/03/21, 8303250091.

--8303250095 Forwards public version of Rev 10 to emergency plan.
TUCKER, H.B. Duke Power Co. 83/03/11. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 2pp. 17710.079. 24X Fiche 50-369,83/03/21,8303250091.

--8303250100 Public version of Rev 10 to emergency plan.
MCINTOSH, M.D. Duke Power Co. 83/02/28. 21pp. 17710.081. 24X Fiche 50-369,83/03/21,8303250091.

I. Financial information

8303080084 Forwards annual financial rept, 1981. Financial forecast for 1982-84 also encl.
TUCKER, H.B. Duke Power Co. 83/03/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 6pp. 17452.174. 24X Fiche 50-000,83/03/01,8303080084.

--8303080092 Annual financial rept, 1981.
HORN, C. Duke Power Co. 82/02/15. 44pp. 17452.180. 24X Fiche 50-000,83/03/01,8303080084.

J. Insurance & indemnity information

8303150107 Unexecuted Amend 7 to Indemnity Agreement B-83, replacing entire Item 3 of attachment by including License NPF-17.
SALTZMAN, J. Assistant Director for State & Licensee Relations. 83/03/03. 1p. 17597.145. 24X Fiche 50-369,83/03/03,8303150107.

8303080492 Forwards signed Amend 7 to Indemnity Agreement B-83, indicating acceptance effective 830303.
TUCKER, H.B. Duke Power Co. 83/03/04. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. SALTZMAN, J. Antitrust & Economic analysis Branch (Utility Finance). 2pp. 17452.321. 24X Fiche 50-369,83/03/04,8303080492.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D.G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492.033. 24X Fiche 50-000,83/02/16,8302170082.

8303020208 Forwards request for addl info re 830203 rept on D2/D3 steam generator design mod. Info must be received no later than 830225.
ADENSAM, E.G. Licensing Branch 4. 83/02/18. TUCKER, H.B. Duke Power Co. 4pp. 17358.012. 24X Fiche 50-369,83/02/18,8303020208.

8303240381 Forwards supplemental info to 830214 ltr re methodology for calculating 40-yr normal operation dose rates.
TUCKER, H.B. Duke Power Co. 83/03/21. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 2pp. 17679.088. 24X Fiche 50-369,83/02/21,8303240381.

8303010311 Forwards info re Items 27 & 39 in NRC/Franklin Research Inst technical evaluation rept on environ qualification of safety-related equipment. Category II.B Environ concerns do not represent safety concern.
TUCKER, H.B. Duke Power Co. 83/02/25. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 3pp. 17333.326. 24X Fiche 50-369,83/02/25,8303010311.

8303070141 Forwards "Procedures Generation Package," "Technical Verification of Nuclear Station Emergency Procedures & Guidelines," "Writers Guide for Emergency & Abnormal..." & "Control Room Review Plan," per NUREG-0737, Suppl 1.
TUCKER, H.B. Duke Power Co. 83/02/28. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 17432.011. 24X Fiche 50-000,83/02/28,8303070141.

--8303070169 "Control Room Review Plan for Oconee, McGuire & Catawba Nuclear Stations, Duke Power Co."
* Duke Power Co. C/1800023 R03. 83/02/15. 38pp. 17432.065. 24X Fiche 50-000,83/03/28,8303070141.

8303080294 Forwards revised "Offsite Dose Calculation Manual for Duke Power Nuclear Stations."
TUCKER, H.B. Duke Power Co. 83/02/28. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 1p. 17455.196. 24X Fiche 50-000,83/02/28,8303080294.

--8303080324 Revised "Offsite Dose Calculation Manual for Duke Power Nuclear Stations."
BIRCH, M.L.; MCINTOSH, M.D. Duke Power Co. 83/02/28. 96pp. 17455.198. 24X Fiche 50-000,83/02/28,8303080294.

8303090210 Discusses review of reactor trip sys per NRC request Testing of Westinghouse DS-416 switchgear breakers revealed no failures Future maint & lubrication will be performed per Westinghouse manual No Westinghouse DB-50 breakers used.
TUCKER, H B Duke Power Co 83/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 17472 355 24X Fiche 50-369, 83/02/28, 8303090210

8303040536 Forwards addl info re mod to main feedwater lines to steam generators D2/D3 to alleviate certain forward flushing transients per NRC 830218 request
TUCKER, H B Duke Power Co 83/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 23pp 17366 005 24X Fiche 50-369, 83/03/01, 8303040536

8303090148 Forwards addl info & clarifies several items in 830228 ltr re reactor trip circuit breakers DS-416 circuit breaker adequately qualified & will perform w/high degree of reliability
TUCKER, H B Duke Power Co 83/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 17470 352 24X Fiche 50-369, 83/03/01, 8303090148

8303150036 Forwards App A Tech Specs for use in issuing license for Unit 2 & amending license for Unit 1 Tech Specs combine requirements on Units 1 & 2 & upgrade Unit 1 requirements to current stds per NUREG-0452, Rev 4
MIRAGLIA, F J Assistant Director for Safety Assessment 83/03/01
NOVAK, T M Assistant Director for Licensing 1p 17586 319 24X
Fiche 50-369, 83/03/01, 8303150036

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X
Fiche 50-000, 83/03/02, 8303020321

8303090466 Forwards request for addl info re 821123 proposed amend to reduce measurement uncertainty for total RCS flow resulting in decrease in min RCS flow for acceptable operation
ADENSAM, E G Licensing Branch 4 83/03/02 TUCKER, H B Duke Power Co 4pp 17483 166 24X Fiche 50-369, 83/03/02, 8303090466

8303150020 Summary of 830225 meeting w/util in Charlotte, NC re NRC mgt review of applicant preparation for initial fuel loading & Unit 2 power operation
BIRKEL, R A Licensing Branch 4 83/03/03 Licensing Branch 4
5pp 17597 146 24X Fiche 50-369, 83/03/03, 8303150020

8303080190 Forwards proprietary & nonproprietary, "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60), McGuire Nuclear Station, Unit 1, Vols 1 & 2," technical evaluation rept
NOVAK, T M Assistant Director for Licensing 83/03/04 TUCKER, H B Duke Power Co 4pp 17443 001 24X Fiche 50-369, 83/03/04, 8303080190

--8303080196 SER re environ qualification of safety-related electric equipment Licensee must provide plans for qualification or replacement of unqualified equipment & schedule for accomplishing proposed action
* Equipment Qualification Branch 83/03/04 6pp 17443 005 24X Fiche 50-369, 83/03/04, 8303080190

--8302020153 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60), Vols 1 & 2," technical evaluation rept
TOMAN, G J Franklin Institute/Franklin Research Center
NRC-03-79-118 TER-C5257-521 83/01/25 SHEMANSKI, P NRC - No Detailed Affiliation Given 909pp 17443 011 24X
Fiche 50-369, 83/03/04, 8303080190

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12) Svc list encl
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 5lpp 17660 176 24X
Fiche 50-000, 83/03/07, 8303040005

8303160766 Summary of 830121 meeting w/Design Review Panel in Bethesda, MD re D2/D3 steam generator mod
HOPKINS, J B Licensing Branch 4 83/03/08 Licensing Branch 4
13pp 17600 202 24X Fiche 50-000, 83/03/08, 8303160766

8303150317 Forwards response to Generic Ltr 82-28 re inadequate core cooling instrumentation sys Subcooling monitor fully operational No mods planned Present & upgraded sys capabilities per NUREG-0737, Item II F 2, discussed
TUCKER, H B Duke Power Co 83/03/09 EISENHUT, D G Division of Licensing ADENSAM, E G Licensing Branch 4 14pp 17567 077 24X
Fiche 50-369, 83/03/09, 8303150317

8303150416 Forwards request for relief from ASME Code Section XI requirement for hydrostatic testing of feedwater sys to steam generators Immediate action requested
TUCKER, H B Duke Power Co 83/03/11 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 5pp 17561 239 24X Fiche 50-369, 83/03/11, 8303150416

8303180533 Forwards Rev 2 to process control program for CNSI mobile solidification units using DOW process & for dewatering resin
TUCKER, H B Duke Power Co 83/03/11 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 17621 283 24X Fiche 50-369, 83/03/11, 8303180533

--8303180536 Rev 2 to process control program for CNSI mobile solidification units using DOW process & for dewatering resin
* Duke Power Co 83/03/11 4pp 17621 285 24X
Fiche 50-369, 83/03/11, 8303180533

8303160270 Forwards proprietary info in response to NRC 830302 ltr Response supports NRC review of proposed Tech Specs change re feedwater flow Response withheld (ref 10CFR2 790)
TUCKER, H B Duke Power Co 83/03/14 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 1p 17596 171 24X Fiche 50-369, 83/03/14, 8303160270

8303180345 Clarifies 830301 response to 830218 request for addl info re mod to main feedwater lines to steam generator to alleviate flushing transients per 830308 telcon No addl safety-grade active valves added as result of mod
TUCKER, H B Duke Power Co 83/03/14 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 17621 042 24X Fiche 50-369, 83/03/14, 8303180345

8303180645 Informs of improvements identified during review of hydrogen control sys Min sys enhancements necessary to upgrade interim hydrogen mitigation sys listed
NOVAK, T M Assistant Director for Licensing 83/03/16 TUCKER, H B Duke Power Co 3pp 17637 139 24X Fiche 50-369, 83/03/16, 8303180645

8303230222 Forwards Rev 7 to "Analysis of Hydrogen Control Measures at McGuire Nuclear Station," Rev provides addl info re Question 8, per 830124 request
TUCKER, H B Duke Power Co 83/03/16 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 3pp 17665 125 24X Fiche 50-369, 83/03/16, 8303230222

8303230527 Forwards NUREG-0996 evaluating util design review panel rept on mod to Westinghouse D2/D3 steam generators W/o encl Generator mods acceptable
NOVAK, T M Assistant Director for Licensing 83/03/16 TUCKER, H B Duke Power Co PARRIS, H G Tennessee Valley Authority DIXON, D W South Carolina Electric & Gas Co 8pp 17677 232 24X
Fiche 50-000, 83/03/16, 8303230527

8303240075 Forwards request for addl info to complete review of 821123 proposed amend to Tech Spec re reducing measurement uncertainty for total RCS flow resulting in decrease in min RCS flow Info requested by 830401
ADENSAM, E G Licensing Branch 4 83/03/17 TUCKER, H B Duke Power Co 3pp 17694 173 24X Fiche 50-369, 83/03/17, 8303240075

8303280306 Notification of 830321 meeting w/Design Review Panel in Bethesda, MD to discuss info re forward flush transient on steam generators D2/D3 Meeting closed to public due to proprietary nature of info
HOPKINS, J B Licensing Branch 4 83/03/18 ADENSAM, E G Licensing Branch 4 6pp 17713 301 24X Fiche 50-000, 83/03/18, 8303280306

8303240378 Forwards evaluation of Section II B of technical rept re environ qualification of electrical equipment Subj transmitters qualified to perform safety function per NUREG-0588 response
TUCKER, H B Duke Power Co 83/03/21 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 4pp 17679 078 24X Fiche 50-369, 83/03/21, 8303240378

8303300366 Notification of 830330 meeting w/util in Bethesda, MD to discuss permanent hydrogen mitigation sys
BIRKEL, R A Licensing Branch 4 83/03/22 ADENSAM, E G Licensing Branch 4 3pp 17754 289 24X Fiche 50-369, 83/03/22, 8303300366

8303290092 Notification of 830324 meeting w/design review panel in Bethesda, MD to discuss info re forward flush transient on D2/D3 steam generator
HOPKINS, J B Licensing Branch 4 83/03/23 ADENSAM, E G Licensing Branch 4 6pp 17729 236 24X Fiche 50-000, 83/03/23, 8303290092

8303310050 Application for amend to Licenses NPF-9 & NPF-17, revising Tech Specs to increase max flow rate for centrifugal charging pumps.
TUCKER, H B. Duke Power Co. 83/03/24. DENTON, H R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E G. Licensing Branch 4. 3pp. 17763:060. 24X Fiche: 50-369, 83/03/24, 8303310050.

--8303310062 Proposed Tech Specs increasing max flow rate for centrifugal charging pumps.
* Duke Power Co. 83/03/24. 22pp. 17763:063. 24X Fiche: 50-369, 83/03/24, 8303310050.

8303300119 Forwards responses to questions in 830317 ltr re proposed Tech Spec change to reduce measurement uncertainty for RCS flow rate.
TUCKER, H B. Duke Power Co. 83/03/28. DENTON, H R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E G. Licensing Branch 4. 8pp. 17735:298. 24X Fiche: 50-369, 83/03/28, 8303300119.

8303300668 Forwards addl guidance for use in preparing required reporting of offsite doses to public for 1982.
ADENSAM, E G. Licensing Branch 4. 83/03/28. TUCKER, H B. Duke Power Co. 4pp. 17768:289. 24X Fiche: 50-369, 83/03/28, 8303300668.

8303220438 TECHNICAL SPECIFICATIONS FOR MCGUIRE NUCLEAR STATION, UNITS 1 AND 2. Docket Nos. 50-369 And 50-370. (Duke Power Company).
ANDERSON, F. Division of Licensing. NUREG-0964. 83/03/31. 592pp. Available at NRC $12.00. 17670:343. 24X Fiche: 50-369, 83/03/31, 8303220438.

## G. Inspection reports, IE Bulletins & correspondence.

8303010596 Forwards IE Insp Repts 50-369/83-01 & 50-370/83-01 on 830103-07. No noncompliance noted.
DANCE, H C. Division of Project & Resident Programs. 83/02/02.
TUCKER, H B. Duke Power Co. 2pp. 17336:004. 24X Fiche: 50-369, 83/02/02, 8303010596.

--8303010608 IE Insp Repts 50-369/83-01 & 50-370/83-01 on 830103-07. No noncompliance noted. Major areas inspected: radiation protection & preoperational testing for Unit 2.
ALBRIGHT, R H., BARR, K P. Division of Engineering & Radiological Safety Programs. 83/02/01. 5pp. 17336:006. 24X
Fiche: 50-369, 83/02/02, 8303010596.

8303010650 Forwards addl response to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp. (Asiatic clam) & Mytilus Sp. (mussel)." Two HX in nuclear svc water sys will be monitored quarterly.
TUCKER, H B. Duke Power Co. 83/02/11. O'REILLY, J P. Region 2, Office of Director. 3pp. 17341:077. 24X Fiche: 50-369, 83/02/11, 8303010650.

8303210638 Forwards IE Insp Repts 50-369/83-02 & 50-370/83-04 on 830119-21. No noncompliance noted.
DANCE, H C. Division of Project & Resident Programs. 83/02/16.
TUCKER, H B. Duke Power Co. 2pp. 17636:244. 24X
Fiche: 50-369, 83/02/16, 8303210638.

--8303210646 IE Insp Repts 50-369/83-02 & 50-370/83-04 on 830119-21. No noncompliance noted. Major areas inspected: test witnessing, test procedure review & review of outstanding items.
BURNETT, P T. Region 2, Office of Director. JAPE, F. Division of Project & Resident Programs. 83/02/10. 4pp. 17636:246. 24X
Fiche: 50-369, 83/02/16, 8303210638.

8303210370 Forwards IE Insp Repts 50-369/83-06 & 50-370/83-10 on 821220-830120. No noncompliance noted.
DANCE, H C. Division of Project & Resident Programs. 83/02/17.
TUCKER, H B. Duke Power Co. 2pp. 17635:001. 24X
Fiche: 50-369, 83/02/17, 8303210370.

--8303210373 IE Insp Repts 50-369/83-06 & 50-370/83-10 on 821220-830120. No noncompliance noted. Major areas inspected: operations, maint activities & surveillance.
ORDERS, W. Region 2, Office of Director. IGNATONIS, A J. Division of Project & Resident Programs. 83/02/16. 5pp. 17635:003. 24X
Fiche: 50-369, 83/02/17, 8303210370.

8303210540 Ack receipt of IE Insp Repts 50-369/82-47 & 50-370/82-40. No proprietary info.
TUCKER, H B. Duke Power Co. 83/02/24. O'REILLY, J P. Region 2, Office of Director. 1p. 17632:225. 24X Fiche: 50-369, 83/02/24, 8303210540.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210268 Responds to IE Bulletin 83-01 re failure of reactor trip breakers to open on automatic trip signal. Westinghouse type DB-50 breakers not used in any safety-related or nonsafety-related sys.
TUCKER, H B. Duke Power Co. 83/03/02. O'REILLY, J P. Region 2, Office of Director. 1p. 17632:002. 24X Fiche: 50-369, 83/03/02, 8303210268.

8303210542 Ack receipt of IE Insp Repts 50-369/83-01 & 50-370/83-01. No proprietary info.
TUCKER, H B. Duke Power Co. 83/03/04. O'REILLY, J P. Region 2, Office of Director. 1p. 17632:297. 24X Fiche: 50-369, 83/03/04, 8303210542.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

## R. Periodic operating reports & related correspondence.

8303180373 Forwards monthly operating rept for Feb 1983.
TUCKER, H B. Duke Power Co. 83/03/15. Director's Office, Office of Inspection and Enforcement. 1p. 17620:068. 24X
Fiche: 50-369, 83/03/15, 8303180373.

--8303180376 Monthly operating rept for Feb 1983.
REAVIS, J A. Duke Power Co. 83/03/15. 5pp. 17620:069. 24X
Fiche: 50-369, 83/03/15, 8303180373.

## S. Reportable occurrences, LERs & related correspondence.

8303010562 Forwards LER 83-004/03L-0.
TUCKER, H B. Duke Power Co. 83/02/18. O'REILLY, J P. Region 2, Office of Director. 1p. 17336:034. 24X Fiche: 50-369, 83/02/18, 8303010562.

--8303010571 LER 83-004/03L-0 on 830121, during monthly battery insp, cell 9 of battery EVCA had specific gravity below Tech Spec limit. Caused by normal degradation. Bus EVDA tied to operable battery bank. Cell 9 jumpered out & battery returned to svc.
NARDOCI, P B. Duke Power Co. 83/02/18. Region 2, Office of Director. 1p. 17336:035. 24X Fiche: 50-369, 83/02/18, 8303010562.

8303140379 Forwards LER 83-005/03L-0. Detailed event analysis encl.
TUCKER, H B. Duke Power Co. 83/02/25. O'REILLY, J P. Region 2, Office of Director. 3pp. 17542:074. 24X Fiche: 50-369, 83/02/25, 8303140379.

--8303140382 LER 83-005/03L-0 on 830127, while in Mode 5, evaluation of initial ice condenser basket weights found numerous accessible row 8 & 9 baskets had net ice weights below Tech Specs. Caused by heat loading & air current.
NARDOCI, P B. Duke Power Co. 83/02/25. Region 2, Office of Director. 1p. 17542:077. 24X Fiche: 50-369, 83/02/25, 8303140379.

8303140391 Forwards LER 83-007/03L-0.
TUCKER, H B. Duke Power Co. 83/03/02. O'REILLY, J P. Region 2, Office of Director. 1p. 17542:125. 24X Fiche: 50-369, 83/03/02, 8303140391.

--8303140392 LER 83-007/03L-0 on 830131, vent radiation monitors 1EMF-35, 36 & 37 declared inoperable following loss of sample flow alarm. Caused by clogged charcoal filter. Filter replaced.
NARDOCI, P B. Duke Power Co. 83/03/02. Region 2, Office of Director. 1p. 17542:126. 24X Fiche: 50-369, 83/03/02, 8303140391.

8303150451 Forwards LER 83-006/03L-0. Detailed event analysis encl.
TUCKER, H B. Duke Power Co. 83/03/02. O'REILLY, J P. Region 2, Office of Director. 4pp. 17561:071. 24X Fiche: 50-369, 83/03/02, 8303150451.

--8303150457 LER 83-006/03L-0 on 830131, unit changed from Mode 5 to 6 w/ control room area outside air pressure filter train 2 (VC-B) inoperable. Sub, train A VC train A inoperable on 830125:26 & 29. Caused by misinterpretation of Tech Specs.
NARDOCI, P B. Duke Power Co. 83/03/02. Region 2, Office of Director. 1p. 17561:075. 24X Fiche: 50-369, 83/03/02, 8303150451.

8303240599 Forwards LER 83-008/03L-0
TUCKER, H B Duke Power Co 83/03/16 O'REILLY, J P Region 2, Office of Director 1p 17683 064 24X Fiche 50-369, 83/03/16, 8303240599

--8303240604 LER 83-008/03L-0 on 830124, weekly composite sample analysis not performed for conventional waste water treatment sys continuous discharge Caused by personnel error & procedural deficiency Procedures will be changed by 830331
NARDOCI, P B Duke Power Co 83/03/16 Region 2, Office of Director 1p 17683 065 24X Fiche 50-369, 83/03/16, 8303240599

8303240397 PNO-II-83-015 on 830319, train A breakers failed to open on actuation of undervoltage trip coil On 830318, train B failed Investigation continuing
IGNATONIS, A , DANCE, H C Region 2, Office of Director 83/03/21 2pp 17678 361 24X Fiche 50-369, 83/03/21, 8303240397

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee " Svc list encl
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000, 83/02/24, 8302250505

DOCKET 50-370 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24X Fiche 50-000, 83/02/16, 8302170082

8303010311 Forwards info re Items 27 & 39 in NRC/Franklin Research Inst technical evaluation rept on environ qualification of safety-related equipment, Category II B Environ concerns do not represent safety concern
TUCKER, H B Duke Power Co 83/02/25 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 3pp 17333 326 24X Fiche 50-369, 83/02/25, 8303010311

8303070141 Forwards "Procedures Generation Package," "Technical Verification of Nuclear Station Emergency Procedures & Guidelines," "Writers Guide for Emergency & Abnormal " & "Control Room Review Plan," per NUREG-0737, Suppl 1
TUCKER, H B Duke Power Co 83/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17432 011 24X Fiche 50-000, 83/02/28, 8303070141

--8303070169 "Control Room Review Plan for Oconee, McGuire & Catawba Nuclear Stations, Duke Power Co "
* Duke Power Co C/1800023 R03 83/02/15 38pp 17432 065 24X Fiche 50-000, 83/02/28, 8303070141

8303080294 Forwards revised "Offsite Dose Calculation Manual for Duke Power Nuclear Stations "
TUCKER, H B Duke Power Co 83/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 1p 17455 196 24X Fiche 50-000, 83/02/28, 8303080294

--8303080324 Revised "Offsite Dose Calculation Manual for Duke Power Nuclear Stations "
BIRCH, M L , MCINTOSH, M D Duke Power Co 83/02/28 96pp 17455 198 24X Fiche 50-000, 83/02/28, 8303080294

8303090210 Discusses review of reactor trip sys per NRC request Testing of Westinghouse DS-416 switchgear breakers revealed no failures Future maint & lubrication will be performed per Westinghouse manual No Westinghouse DB-50 breakers used
TUCKER, H B Duke Power Co 83/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 17472 355 24X Fiche 50-369, 83/02/28, 8303090210

8303090214 Provides justification for safe operation up to 5% power anticipated on 830301, pending completion of equipment qualification required per 10CFR50 49(i)
TUCKER, H B Duke Power Co 83/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 3pp 17492 134 24X Fiche 50-370, 83/02/28, 8303090214

8303090148 Forwards addl info & clarifies several items in 830228 ltr re reactor trip circuit breakers DS-416 circuit breaker adequately qualified & will perform w/high degree of reliability
TUCKER, H B Duke Power Co 83/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 17470 352 24X Fiche 50-369, 83/03/01, 8303090148

8303150036 Forwards App A Tech Specs for use in issuing license for Unit 2 & amending license for Unit 1 Tech Specs combine requirements on Units 1 & 2 & upgrade Unit 1 requirements to current stds, per NUREG-0452, Rev 4
MIRAGLIA, F J Assistant Director for Safety Assessment 83/03/01 NOVAK, T M Assistant Director for Licensing 1p 17586 319 24X Fiche 50-369, 83/03/01, 8303150036

E NRC Safety Evaluation Report (SER), suppls & correspondence

8303230239 SAFETY EVALUATION REPORT RELATED TO OPERATION OF MCGUIRE NUCLEAR STATION, UNITS 1 AND 2 Docket Nos 50-369 And 50-370 (Duke Power Company)
* Office of Nuclear Reactor Regulation, Director NUREG-0422 S06 83/02/2H 58pp Available at NRC $5 50 17685 030 24X Fiche 50-369, 83/02/28, 8303230239

8303180574 Forwards Suppl 6 to SER re application for OLs W/o encl
NOVAK, T M Assistant Director for Licensing 83/03/14 TUCKER, H B Duke Power Co 2pp 17640 042 24X Fiche 50-369, 83/03/14, 8303180574

F Security, medical, emergency & fire protection plans

8303010596 Forwards IE Insp Repts 50-369/83-01 & 50-370/83-01 on 830103-07 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/02/02
TUCKER, H B Duke Power Co 2pp 17336 004 24X Fiche 50-369, 83/02/02, 8303010596

--8303010608 IE Insp Repts 50-369/83-01 & 50-370/83-01 on 830103-07 No noncompliance noted Major areas inspected radiation protection & preoperational testing for Unit 2
ALBRIGHT, R H Division of Engineering & Radiological Safety Programs 83/02/01 5pp 17336 006 24X Fiche 50-369, 83/02/02, 8303010596

8303100148 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/03/02 Document Management Branch 1p 17503 012 24X Fiche 50-369, 83/03/02, 8303100148

8303290475 Requests exemption from 10CFR50 App E, Item IV F h & 10CFR50 47 b(14) re active participation of crisis mgt ctr personnel for each station during annual emergency preparedness exercise
TUCKER, H B Duke Power Co 83/03/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17724 324 24X Fiche 50-000, 83/03/09, 8303290475

8303150476 Forwards IE Safeguards Insp Rept 50-370/83-17 on 830223-25 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/03/10
TUCKER, H B Duke Power Co 2pp 17568 246 24X Fiche 50-370, 83/03/10, 8303150476

--8303150505 IE Safeguards Insp Rept 50-370/83-17 on 830223-25 No noncompliance noted Major areas inspected review of testing & maint, locks, keys & combinations & physical barriers - vital areas Details withheld (ref 10CFR73 21)
TILLMAN, A , MCGUIRE, D R Region 2, Office of Director 83/03/09 1p 17568 248 24X Fiche 50-370, 83/03/10, 8303150476

8303150694 Responds to 830114 ltr submitting Rev 2 to safeguards contingency plan Changes consistent w/10CFR50 54(p) & do not decrease effectiveness of plan
ADENSAM, E G Licensing Branch 4 83/03/10 TUCKER, H B Duke Power Co 2pp 17586 245 24X Fiche 50-369, 83/03/10, 8303150694

8303220321 Advises that interest in & time available for drills pilot program nonexistent Limited drill pilot program could be conducted during simulator requalification training
BOSTIAN, R W Duke Power Co 83/03/10 EISENHUT, D G Division of Licensing 1p 17655 348 24X Fiche 50-000, 83/03/10, 8303220321

8303230057 Advises that changes listed in 821110 & 830125 ltrs re safeguards contingency plan acceptable Encls to ltrs withheld (ref 10CFR2 790)
ADENSAM, E G Licensing Branch 4 83/03/10 TUCKER, H B Duke Power Co 2pp 17688 346 24X Fiche 50-369, 83/03/10, 8303230057

8303240113 Releases public version of revised crisis mgt plan implementing procedures.
FELTON, J. M. Division of Rules and Records 83/03/21 Document Management Branch 1p 17700.029 24X Fiche 50-000,83/03/21, 8303240113.

--8303240120 Forwards public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.1 re recovery manager & immediate staff group plan & 5.3.4 re scheduling/planning support group.
TUCKER, H. B. Duke Power Co. 83/03/08 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17700.030 24X Fiche 50-000,83/03/21, 8303240113.

--8303240127 Public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.1 re recovery manager & immediate staff group plan & 5.3.4 re scheduling/planning support group.
* Duke Power Co. 83/02/28 175pp 24X Fiche 50-000,83/03/21, 8303240113.

8303250091 Releases public version of revised emergency plan.
FELTON, J. M. Division of Rules and Records 83/03/21 Document Management Branch 1p 17710.078 24X Fiche 50-369,83/03/21, 8303250091.

--8303250095 Forwards public version of Rev 10 to emergency plan.
TUCKER, H. B. Duke Power Co. 83/03/11 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENSAM, E. G. Licensing Branch 4 2pp 17710.079 24X Fiche 50-369,83/03/21, 8303250091.

--8303250100 Public version of Rev 10 to emergency plan.
MCINTOSH, M. D. Duke Power Co. 83/02/28 21pp 17710.081 24X Fiche 50-369,83/03/21, 8303250091.

J Insurance & indemnity information

8303150107 Unexecuted Amend 7 to Indemnity Agreement B-83, replacing entire Item 3 of attachment by including License NPF-17.
SALTZMAN, J. Assistant Director for State & Licensee Relations 83/03/03 1p 17597.145 24X Fiche 50-369,83/03/03, 8303150107.

8303230312 Forwards License NPF-17, FR notice & Amend 7 to Indemnity Agreement B-83 License authorizes low power testing & operation at up to but not to exceed 5% power.
EISENHUT, D. G. Division of Licensing 83/03/03 TUCKER, H. B. Duke Power Co. 2pp 17675.060 24X Fiche 50-370,83/03/03, 8303230312.

--8303230325 Notice of issuance of License NPF-17 Amend 7 to Indemnity Agreement B-83 encl.
ADENSAM, E. G. Licensing Branch 4 83/03/03 12pp 17675.072 24X Fiche 50-370,83/03/03, 8303230312.

8303080492 Forwards signed Amend 7 to Indemnity Agreement B-83, indicating acceptance effective 830303.
TUCKER, H. B. Duke Power Co. 83/03/04 DENTON, H. R. Office of Nuclear Reactor Regulation, Director SALTZMAN, J. Antitrust & Economic analysis Branch (Utility Finance) 2pp 17452.321 24X Fiche 50-369,83/03/04, 8303080492.

P Operating license stage documents & correspondence

8303240381 Forwards supplemental info to 830214 ltr re methodology for calculating 40-yr normal operation dose rates.
TUCKER, H. B. Duke Power Co. 83/03/21 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENSAM, E. G. Licensing Branch 4 2pp 17679.088 24X Fiche 50-369,83/02/21, 8303240381.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700.303 24X Fiche 50-000,83/03/02, 8303020321.

8303150020 Summary of 830225 meeting w/util in Charlotte, NC re NRC mgt review of applicant preparation for initial fuel loading & Unit 2 power operation.
BIRKEL, R. A. Licensing Branch 4 83/03/03 Licensing Branch 4 5pp 17597.146 24X Fiche 50-369,83/03/03, 8303150020.

8303230312 Forwards License NPF-17, FR notice & Amend 7 to Indemnity Agreement B-83 License authorizes low power testing & operation at up to but not to exceed 5% power.
EISENHUT, D. G. Division of Licensing 83/03/03 TUCKER, H. B. Duke Power Co. 2pp 17675.060 24X Fiche 50-370,83/03/03, 8303230312.

--8303230314 License NPF-17 for facility, authorizing low power testing & operation not to exceed 5% power.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 83/03/03 10pp 17675.062 24X Fiche 50-370,83/03/03, 8303230312.

--8303230325 Notice of issuance of License NPF-17 Amend 7 to Indemnity Agreement B-83 encl.
ADENSAM, E. G. Licensing Branch 4 83/03/03 12pp 17675.072 24X Fiche 50-370,83/03/03, 8303230312.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp 17660.176 24X Fiche 50-000,83/03/07, 8303040005.

8303160766 Summary of 830121 meeting w/Design Review Panel in Bethesda, MD re D2/D3 steam generator mod.
HOPKINS, J. B. Licensing Branch 4 83/03/08 Licensing Branch 4 15pp 17600.202 24X Fiche 50-000,83/03/08, 8303160766.

8303150317 Forwards response to Generic Ltr 82-28 re inadequate core cooling instrumentation sys. Subcooling monitor fully operational. No mods planned. Present & upgraded sys capabilities per NUREG-0737, Item II.F.2 discussed.
TUCKER, H. B. Duke Power Co. 83/03/09 EISENHUT, D. G. Division of Licensing ADENSAM, E. G. Licensing Branch 4 14pp 17567.077 24X Fiche 50-369,83/03/09, 8303150317.

8303150416 Forwards request for relief from ASME Code Section XI requirement for hydrostatic testing of feedwater sys to steam generators. Immediate action requested.
TUCKER, H. B. Duke Power Co. 83/03/11 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENSAM, E. G. Licensing Branch 4 5pp 17561.239 24X Fiche 50-369,83/03/11, 8303150416.

8303180533 Forwards Rev 2 to process control program for CNSI mobile solidification units using DOW process & for dewatering resin.
TUCKER, H. B. Duke Power Co. 83/03/11 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENSAM, E. G. Licensing Branch 4 2pp 17621.283 24X Fiche 50-369,83/03/11, 8303180533.

--8303180538 Rev 2 to process control program for CNSI mobile solidification units using DOW process & for dewatering resin.
* Duke Power Co. 83/03/11 4pp 17621.285 24X Fiche 50-369,83/03/11, 8303180533.

8303180347 Identifies startup testing schedule so that NRC licensing activities can be scheduled accordingly. Initial criticality scheduled for 830425 & testing at less than 5% power level to be completed by 830516.
TUCKER, H. B. Duke Power Co. 83/03/15 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENSAM, E. G. Licensing Branch 4 1p 17621.040 24X Fiche 50-370,83/03/15, 8303180347.

8303180645 Informs of improvements identified during review of hydrogen control sys. Min sys enhancements necessary to upgrade interim hydrogen mitigation sys listed.
NOVAK, T. M. Assistant Director for Licensing 83/03/16 TUCKER, H. B. Duke Power Co. 3pp 17637.139 24X Fiche 50-369,83/03/16, 8303180645.

8303230222 Forwards Rev 7 to "Analysis of Hydrogen Control Measures at McGuire Nuclear Station." Rev provides addl info re Question 8, per 830124 request.
TUCKER, H. B. Duke Power Co. 83/03/16 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENSAM, E. G. Licensing Branch 4 3pp 17665.125 24X Fiche 50-369,83/03/16, 8303230222.

8303230527 Forwards NUREG-0996 evaluating util design review panel rept on mod to Westinghouse D2/D3 steam generators. W/o encl. Generator mods acceptable.
NOVAK, T. M. Assistant Director for Licensing 83/03/16 TUCKER, H. B. Duke Power Co. PARRIS, H. G. Tennessee Valley Authority DIXON, O. W. South Carolina Electric & Gas Co. 8pp 17677.232 24X Fiche 50-000,83/03/16, 8303230527.

8303280306 Notification of 830321 meeting w/Design Review Panel in Bethesda, MD to discuss info re forward flush transient on steam generators D2/D3. Meeting closed to public due to proprietary nature of info.
HOPKINS, J. B. Licensing Branch 4 83/03/18 ADENSAM, E. G. Licensing Branch 4 6pp 17713.301 24X Fiche 50-000,83/03/18, 8303280306.

8303240378 Forwards evaluation of Section II B of technical rept re environ qualification of electrical equipment Subj transmitters qualified to perform safety function per NUREG-0588 response.
TUCKER,H B. Duke Power Co. 83/03/21. DENTON,H R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E G. Licensing Branch 4. 4pp. 17679 078. 24X Fiche 50-369,83/03/21,8303240378.

8303280137 Comments on Board Notification 83-38 re failure of GE AK-2 reactor trip breakers. Info may affect NRC conclusions re probability/corrective measures for transients w/o scram events (Unresolved Safety Issue A-9).
EISENHUT,D G. Division of Licensing. 83/03/22. PALLADINO,N. , GILINSKY,V. , ROBERTS,T M. Commissioners. 20pp. 17709 310. 24X Fiche 50-000,83/03/22,8303280137.

8303300366 Notification of 830330 meeting w/util in Bethesda,MD to discuss permanent hydrogen mitigation sys.
BIRKEL,R A. Licensing Branch 4. 83/03/22. ADENSAM,E G. Licensing Branch 4. 3pp. 17754 289. 24X Fiche 50-369,83/03/22,8303300366.

8303290092 Notification of 830324 meeting w/design review panel in Bethesda,MD to discuss info re forward flush transient on D2/D3 steam generator.
HOPKINS,J B. Licensing Branch 4. 83/03/23. ADENSAM,E G. Licensing Branch 4. 6pp. 17729 236. 24X Fiche 50-000,83/03/23,8303290092.

8303310050 Application for amend to Licenses NPF-9 & NPF-17, revising Tech Specs to increase max flow rate for centrifugal charging pumps.
TUCKER,H B. Duke Power Co. 83/03/24. DENTON,H R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E G. Licensing Branch 4. 3pp. 17763 060. 24X Fiche 50-369,83/03/24,8303310050.

--8303310062 Proposed Tech Specs increasing max flow rate for centrifugal charging pumps.
* Duke Power Co. 83/03/24. 22pp. 17763 063. 24X Fiche 50-369,83/03/24,8303310050.

8303300668 Forwards addl guidance for use in preparing required reporting of offsite doses to public for 1982.
ADENSAM,E G. Licensing Branch 4. 83/03/28. TUCKER,H B. Duke Power Co. 4pp. 17768 289. 24X Fiche 50-369,83/03/28,8303300668.

8303220438 TECHNICAL SPECIFICATIONS FOR MCGUIRE NUCLEAR STATION, UNITS 1 AND 2 Docket Nos. 50-369 And 50-370 (Duke Power Company)
ANDERSON,F. Division of Licensing. NUREG-0964. 83/03/31. 592pp. Available at NRC. $12.00. 17670 343. 24X Fiche 50-369,83/03/31,8303220438.

## 8 Inspection reports, IE Bulletins & correspondence

8303010155 Forwards IE Insp Rept 50-370/83-02 on 830104-07 & notice of violation.
DANCE,H C. Division of Project & Resident Programs. 83/01/31. TUCKER,H B. Duke Power Co. 2pp. 17335 358. 24X Fiche 50-370,83/01/31,8303010155.

--8303010160 Notice of violation from insp on 830104-07.
* Region 2, Office of Director. 83/01/31. 1p. 17335 360. 24X Fiche 50-370,83/01/31,8303010...

--8303010168 IE Insp Rept 50-370/83-02 on 830104-07 Noncompliance noted QC accepted 6-inch IPS RHR pipe measured too long between Column GG-60 & centerline of elbow.
ANG,W P , BLAKE,J J. Division of Engineering & Radiological Safety Programs. 83/01/26. 4pp. 17335 361. 24X Fiche 50-370,83/01/31,8303010155.

8303010596 Forwards IE Insp Repts 50-369/83-01 & 50-370/83-01 on 830103-07 No noncompliance noted.
DANCE,H C. Division of Project & Resident Programs. 83/02/02. TUCKER,H B. Duke Power Co. 2pp. 17336 004. 24X Fiche 50-369,83/02/02,8303010596.

--8303010608 IE Insp Repts 50-369/83-01 & 50-370/83-01 on 830103-07 No noncompliance noted Major areas inspected radiation protection & preoperational testing for Unit 2.
ALBRIGHT,R H , BARR,K P. Division of Engineering & Radiological Safety Programs. 83/02/01. 5pp. 17336 006. 24X Fiche 50-369,83/02/02,8303010596.

8303010650 Forwards addl response to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp (Asiatic clam) & Mytilus Sp (mussel)." Two HX in nuclear svc water sys will be monitored quarterly.
TUCKER,H B. Duke Power Co. 83/02/11. O'REILLY,J P. Region 2, Office of Director. 3pp. 17341 077. 24X Fiche 50-369,83/02/11,8303010650.

8303210496 Forwards IE Insp Rept 50-270/83-03 on 830112-20 No noncompliance noted.
DANCE,H C. Division of Project & Resident Programs. 83/02/11. TUCKER,H B. Duke Power Co. 2pp. 17631 225. 24X Fiche 50-370,83/02/11,8303210496.

--8303210503 IE Insp Rept 50-370/83-03 on 830112-20 No noncompliance noted Major areas inspected preoperational ESF test witnessing, plant procedures & followup on previous findings.
THOMAS,M , KRUG,H E , TAYLOR,P A. Region 2, Office of Director. 83/02/09. 5pp. 17631 227. 24X Fiche 50-370,83/02/11,8303210496.

8303210638 Forwards IE Insp Repts 50-369/83-02 & 50-370/83-04 on 830119-21 No noncompliance noted.
DANCE,H C. Division of Project & Resident Programs. 83/02/16. TUCKER,H B. Duke Power Co. 2pp. 17636 244. 24X Fiche 50-369,83/02/16,8303210638.

--8303210646 IE Insp Repts 50-369/83-02 & 50-370/83-04 on 830119-21 No noncompliance noted Major areas inspected test witnessing, test procedure review & review of outstanding items.
BURNETT,P T. Region 2, Office of Director. JAPE,F. Division of Project & Resident Programs. 83/02/10. 4pp. 17636 246. 24X Fiche 50-369,83/02/16,8303210638.

8303210370 Forwards IE Insp Repts 50-369/83-06 & 50-370/83-10 on 821220-830120 No noncompliance noted.
DANCE,H C. Division of Project & Resident Programs. 83/02/17. TUCKER,H B. Duke Power Co. 2pp. 17635 001. 24X Fiche 50-369,83/02/17,8303210370.

--8303210373 IE Insp Repts 50-369/83-06 & 50-370/83-10 on 821220-830120 No noncompliance noted Major areas inspected operations, maint activities & surveillance.
ORDERS,W. Region 2, Office of Director. IGNATONIS,A J. Division of Project & Resident Programs. 83/02/16. 5pp. 17635 003. 24X Fiche 50-369,83/02/17,8303210370.

8303210344 Forwards IE Insp Rept 50-370/83-09 on 830131-0204 No noncompliance noted.
DANCE,H C. Division of Project & Resident Programs. 83/02/23. TUCKER,H B. Duke Power Co. 2pp. 17634 137. 24X Fiche 50-370,83/02/23,8303210344.

--8303210347 IE Insp Rept 50-370/83-09 on 830131-0204 No noncompliance noted Major areas inspected preoperational test witnessing, preoperational test results review & plant procedures.
THOMAS,M , KRUG,H E , JAPE,F. Region 2, Office of Director. 83/02/22. 6pp. 17634 139. 24X Fiche 50-370,83/02/23,8303210344.

8303210540 Ack receipt of IE Insp Repts 50-369/82-47 & 50-370/82-40 No proprietary info.
TUCKER,H B. Duke Power Co. 83/02/24. O'REILLY,J P. Region 2, Office of Director. 1p. 17632 225. 24X Fiche 50-369,83/02/24,8303210540.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG,R C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521 001. 24X Fiche 50-000,83/02/25,8212060367.

8303010534 Advises of preservice insp results per 830216 telcon. Corrective action re reportable indications found on two reactor vessel closure nuts will be completed & nuts reinspected prior to use.
TUCKER,H B. Duke Power Co. 83/02/25. DENTON,H R. Office of Nuclear Reactor Regulation, Director. ADENSAM,E G. Licensing Branch 4. 2pp. 17343 024. 24X Fiche 50-370,83/02/25,8303010534.

8303210536 Ack receipt of IE Insp Rept 50-370/83-05 No proprietary info.
TUCKER,W T. Duke Power Co. 83/02/25. O'REILLY,J P. Region 2, Office of Director. 1p. 17632 281. 24X Fiche 50-370,83/02/25,8303210536.

8303210268 Responds to IE Bulletin 83-01 re failure of reactor trip breakers to open on automatic trip signal Westinghouse type DB-50 breakers not used in any safety-related or nonsafety-related sys.
TUCKER,H B. Duke Power Co. 83/03/02. O'REILLY,J P. Region 2, Office of Director. 1p. 17632 002. 24X Fiche 50-369,83/03/02,8303210268.

8303210430 Ack receipt of IE Insp Rept 50-370/83-02 No proprietary info. Response not required due to completion of corrective actions prior to conclusion of insp.
TUCKER,H B. Duke Power Co. 83/03/02. O'REILLY,J P. Region 2, Office of Director. 1p. 17634 352. 24X Fiche 50-370,83/03/02,8303210430.

8303210542 Ack receipt of IE Insp Repts 50-369/83-01 & 50-370/83-01 No proprietary info.
TUCKER, H B. Duke Power Co. 83/03/04 O'REILLY, J P. Region 2, Office of Director. 1p. 17632:297. 24X Fiche: 50-369, 83/03/04, 8303210542.

8303150476 Forwards IE Safeguards Insp Rept 50-370/83-17 on 830223-25 No noncompliance noted.
DANCE, H C. Division of Project & Resident Programs. 83/03/10
TUCKER, H B. Duke Power Co. 2pp. 17568:246. 24X
Fiche: 50-370, 83/03/10, 8303150476.

--8303150505 IE Safeguards Insp Rept 50-370/83-17 on 830223-25 No noncompliance noted. Major areas inspected: review of testing & maint; locks, keys & combinations & physical barriers - vital areas. Details withheld (ref 10CFR73.21).
TILLMAN, A ., MCGUIRE, D R. Region 2, Office of Director. 83/03/09
1p. 17568:248. 24X Fiche: 50-370, 83/03/10, 8303150476.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc.
117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303210447 Ack receipt of IE Insp Rept 50-370/83-03 No proprietary info.
TUCKER, H B. Duke Power Co. 83/03/11 O'REILLY, J P. Region 2, Office of Director. 1p. 17634:179. 24X Fiche: 50-370, 83/03/11, 8303210447.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

S. Reportable occurrences, LERs & related correspondence

8303150294 Interim deficiency rept re ITT Barton Class IE transmitters exhibiting thermal nonrepeatability. Initially reported on 821210. Sufficient margins exist in protection sys setpoints to accommodate changes in accuracies. Next rept by 830331.
TUCKER, H B. Duke Power Co. 83/02/28. O'REILLY, J P. Region 2, Office of Director. 1p. 17567:060. 24X Fiche: 50-370, 83/02/28, 8303150294.

8303240297 RNO-II-83-015 on 830317: train A breakers failed to open on actuation of undervoltage trip coil. On 830318, train B failed. Investigation continuing.
IGNATONIS, A ., DANCE, H C. Region 2, Office of Director. 83/03/21
2pp. 17678:361. 24X Fiche: 50-369, 83/03/21, 8303240297.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8303010595 Ack receipt of 830124 ltr identifying 1983 dates for emergency preparedness exercises within State of IL. Dates determined to be within required exercise frequency.
HIND, J A. Region 3, Office of Director. 83/02/24. JONES, E E. Illinois, State of. 2pp. 17336:208. 24X Fiche: 50-000, 83/02/24, 8303010595.

---8303010618 Submits 1983 dates scheduled for emergency preparedness exercises for facilities within State of IL.
JONES, E E. Illinois, State of. 83/01/24. KEPPLER, J. Region 3, Office of Director. 2pp. 17336:210. 24X Fiche: 50-000, 83/02/24, 8303010595.

8303030530 Forwards IE Safeguards Insp Rept 50-373/83-08 on 830203-04 No noncompliance noted.
MILLER, J R. Division of Engineering. 83/02/25. REED, C. Commonwealth Edison Co. 2pp. 17409:049. 24X Fiche: 50-373, 83/02/25, 8303030530.

--8303030540 IE Safeguards Insp Rept 50-373/83-08 on 830203-04 No noncompliance noted. Major areas inspected: actions pertaining to fire within turbine bldg. Details withheld (ref 10CFR73.21).
PIRTLE, G L ., CREED, J R. Region 3, Office of Director. 83/02/24
1p. 17409:051. 24X Fiche: 50-373, 83/02/25, 8303030530.

8303030020 Forwards corrected Page 5-7c of Rev 13 to modified security plan. Page withheld (ref 10CFR73.21).
FARRAR, D L. Commonwealth Edison Co. 83/02/28. Office of Nuclear Reactor Regulation, Director. 1p. 17412:132. 24X
Fiche: 50-373, 83/02/28, 8303030020.

8303090267 Releases public version of revised emergency plan implementing procedure.
FELTON, J M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17484:303. 24X Fiche: 50-373, 83/03/02, 8303090267.

--8303090274 Forwards public version of Rev 2 to Emergency Plan Implementing Procedure LZP 1550-5, "Technical Support Ctr Quarterly Surveillance."
* Commonwealth Edison Co. 83/03/09. Office of Nuclear Reactor Regulation, Director. 1p. 17484:304. 24X Fiche: 50-373, 83/03/02, 8303090267.

--8303090284 Public version of Rev 2 to Emergency Plan Implementing Procedure LZP 1550-5, "Technical Support Ctr Quarterly Surveillance." Revised index encl.
* Commonwealth Edison Co. 83/02/09. 12pp. 17484:305. 24X
Fiche: 50-373, 83/03/02, 8303090267.

8303170209 Advises that Rev 13 to modified amended security plan acceptable. Encl to 821129 ltr withheld (ref 10CFR73.21).
SCHWENCER, A. Licensing Branch 2. 83/03/10. FARRAR, D L. Commonwealth Edison Co. 2pp. 17623:352. 24X Fiche: 50-373, 83/03/10, 8303170209.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J A. Region 3, Office of Director. 83/03/22. Commonwealth Edison Co. 2pp. 17690:316. 24X Fiche: 50-000, 83/03/22, 8303240440.

8303310082 Releases public version of revised emergency plan implementing procedures.
FELTON, J M. Division of Rules and Records. 83/03/25. Document Management Branch. 1p. 17777:102. 24X Fiche: 50-373, 83/03/25, 8303310082.

--8303310087 Forwards public version of Rev 4 to Emergency Plan Implementing Procedure LZP-1110-1 re station director (acting station director) implementing procedure & Rev 3 to LZP-1310-1 re notifications.
* Commonwealth Edison Co. 83/03/07. Office of Nuclear Reactor Regulation, Director. 5pp. 17777:103. 24X Fiche: 50-373, 83/03/25, 8303310082.

--8303310092 Public version of Rev 4 to Emergency Plan Implementing Procedure LZP-1110-1 re station director (acting station director) implementing procedure & Rev 3 to LZP-1310-1 re notifications.
* Commonwealth Edison Co. 83/03/02. 52pp. 17777:108. 24X
Fiche: 50-373, 83/03/25, 8303310082.

8303310124 Releases public version of revised emergency plan implementing procedure.
FELTON, J M. Division of Rules and Records. 83/03/25. Document Management Branch. 1p. 17775:184. 24X Fiche: 50-000, 83/03/25, 8303310124.

--8303310130 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure EG-1, "Coordination of Environs Group Activities by Environs Director."
* Commonwealth Edison Co. 83/03/17. Director's Office, Office of Inspection and Enforcement. 1p. 17775:185. 24X
Fiche: 50-000, 83/03/25, 8303310124.

--8303310146 Public version of Rev 3 to Emergency Plan Implementing Procedure EG-1, "Coordination of Environs Group Activities by Environs Director."
PAJOWSKI, J E. Commonwealth Edison Co. 83/03/08. 87pp.
17775:186. 24X Fiche: 50-000, 83/03/25, 8303310124.

8303300532 Releases public version of request for return of listed controlled copies of emergency plan.
FELTON, J M. Division of Rules and Records. 83/03/28. Document Management Branch. 1p. 17763:178. 24X Fiche: 50-000, 83/03/28, 8303300532.

--8303300561 Submits public version of request for return of listed controlled copies of emergency plan.
FLESSNER, R A. Commonwealth Edison Co. 83/03/15. DENTON, H R. Office of Nuclear Reactor Regulation, Director. 1p. 17763:179. 24X Fiche: 50-000, 83/03/28, 8303300532.

G. Adjudicatory correspondence

8303100387 Order extending time until 830407 for Commission to act to review Director's Decision DD-83-01.
CHILK, S J. Office of the Secretary of the Commission. 83/03/07. Commissioners. 1p. 17488:335. 24X Fiche: 50-373, 83/03/07, 8303100387.

H. General correspondence

8303030528 Informs that DL Farrar has replaced LO DelGeorge as Director of Nuclear Licensing for util Rev of current NRC distribution list requested.
FARRAR, D L. Commonwealth Edison Co. 83/02/02. DENTON, H R. Office of Nuclear Reactor Regulation, Director. 1p. 17409:048. 24X Fiche: 50-000, 83/02/02, 8303030528.

I. Financial information

8303070135 Forwards Annual Financial Rept 1982.
BRESEMANN, R W. Commonwealth Edison Co. 83/02/28. Division of Licensing. 1p. 17433:001. 24X Fiche: 50-000, 83/02/28, 8303070135.

--8303070151 Annual Financial Rept 1982.
O'CONNOR, J J. Commonwealth Edison Co. 83/02/03. 13pp. 17433:002. 24X Fiche: 50-000, 83/02/28, 8303070135.

J. Insurance & indemnity information

8303160578 Forwards Endorsements 143, 75, 62 & 24 to NELIA Policies NF-43, NF-187, NF-201 & NF-253, respectively.
OSTER, J. Commonwealth Edison Co. 83/03/09. SALTZMAN, J. Assistant Director for State & Licensee Relations. 5pp. 17587:017. 24X Fiche: 50-000, 83/03/09, 8303160578.

P. Operating license stage documents & correspondence

8303090437 FOIA request for NRC records reviewing CF Braun audit of HVAC sys at facilities Waiver of fees requested.
GARDE, B. Government Accountability Project. 83/01/14. Office of Administration. 1p. 17481:174. 24X Fiche: 50-373, 83/01/14, 8303090437.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303090443 Responds to FOIA request for NRC records reviewing CF Braun audit of HVAC sys at facilities. Forwards App B documents. App A documents available in PDR.
FELTON, J M. Division of Rules and Records. 83/02/16. GARDE, B. Government Accountability Project. 4pp. 17481:175. 24X Fiche: 50-373, 83/02/16, 8303090443.

--8209210510 Comments on review of Revision 1 to technical proposal for independent review of HVAC sys, submitted on 820827. Addl reviews performed by other branches encl. Proposed program will accomplish verification of HVAC sys.
RUBENSTEIN, L S. Assistant Director for Core & Plant Systems. 82/09/01. NOVAK, T M. Assistant Director for Licensing. 3pp. 17481:223. 24X Fiche: 50-373, 83/02/16, 8303090443.

--8211090596 Advises that CF Brown interim rept on plant independent HVAC sys review acceptable & consistent w/820825 technical proposal. Objective of review is to verify Zack Co HVAC installation in accordance w/Sargent & Lundy design.
KNIGHT, J P. Assistant Director for Comp. & Structures Engineering (Pre 830201). 82/10/28. NOVAK, T M. Assistant Director for Licensing. 1p. 17481:232. 24X Fiche: 50-373, 83/02/16, 8303090443.

--8211110155 Forwards Mechanical Engineering Branch SER input re mechanical design, based on review of CF Braun 821027 "Independent HVAC Review Final Rept - LaSalle Station."
KNIGHT, J P. Assistant Director for Comp. & Structures Engineering (Pre 830201). 82/11/02. NOVAK, T M. Assistant Director for Licensing. 3pp. 17481:233. 24X Fiche: 50-373, 83/02/16, 8303090443.

--8211110643 Forwards QA Branch final SER input re independent HVAC review conducted by CF Brown & Co.
JOHNSTON, W V. Assistant Director for Matls & Qualif. Engineering (Pre 830201). 82/11/03. NOVAK, T M. Assistant Director for Licensing. 3pp. 17481:210. 24X Fiche: 50-373, 83/02/16, 8303090443.

--8211120231 Requests that independent review of rept on HVAC sys & written SER be provided on priority basis. Rept expected in Bethesda on 821028. Licensee indicated readiness to exceed 50% power upon receiving NRC release.
EISENHUT, D G. Division of Licensing. 82/10/29. VOLLMER, R H. Division of Engineering. 2pp. 17481:179. 24X Fiche: 50-373, 83/02/16, 8303090443.

--8211170104 Forwards SER input on independent design review of HVAC sys. Independent review of HVAC sys acceptably verified functional adequacy of HVAC sys.
RUBENSTEIN, L S. Assistant Director for Core & Plant Systems. 82/11/04. NOVAK, T M. Assistant Director for Licensing. 6pp. 17481:226. 24X Fiche: 50-373, 83/02/16, 8303090443.

--8212010304 Informs that Matls Engineering Branch review of 821027 "Independent HVAC Review Final Rept" complete. SER input addressing area of matl engineering encl.
JOHNSTON, W V. Assistant Director for Matls & Qualif. Engineering (Pre 830201). 82/11/18. NOVAK, T M. Assistant Director for Licensing. 5pp. 17481:218. 24X Fiche: 50-373, 83/02/16, 8303090443.

--8212020228 Forwards addl info to draft SER re CF Braun HVAC review describing NRC involvement & summary of overall results. Review & comments requested by 821122.
NOVAK, T M. Assistant Director for Licensing. 82/11/19. NORELIUS, C E. Division of Engineering. JOHNSTON, W V. Assistant Director for Matls & Qualif. Engineering (Pre 830201). RUBENSTEIN, L R. Assistant Director for Core & Plant Systems. 17pp. 17481:184. 24X Fiche: 50-373, 83/02/16, 8303090443.

--8212160101 Forwards revised Pages 10, 11, 12 & 13 of draft SER on HVAC independent review in response to 821119 memo.
JOHNSTON, W V. Assistant Director for Matls & Qualif. Engineering (Pre 830201). 82/12/02. NOVAK, T M. Assistant Director for Licensing. 5pp. 17481:213. 24X Fiche: 50-373, 83/02/16, 8303090443.

--8212210480 Forwards revised SER for QA of independent HVAC review providing addl detail of review per 821118 meeting commitment.
JOHNSTON, W V. Assistant Director for Matls & Qualif. Engineering (Pre 830201). 82/12/02. NOVAK, T M. Assistant Director for Licensing. 3pp. 17481:181. 24X Fiche: 50-373, 83/02/16, 8303090443.

--8303090499 Forwards final draft SER in response to CF Braun rept re HVAC sys. W/o encl Matls Engineering Branch requirements of SER encl.
EISENHUT, D G. Division of Licensing. 82/11/09. KEPPLER, J G. Region 3, Office of Director. 5pp. 17481:236. 24X Fiche: 50-373, 83/02/16, 8303090443.

--8303090517 Forwards draft SER app re matl sampling program of HVAC sys at facilities. Discussion of subj scheduled for 821123.
DENTON, H. Office of Nuclear Reactor Regulation, Director. 82/11/22. KEPPLER, J. Region 3, Office of Director. 4pp. 17481:241. 24X Fiche: 50-373, 83/02/16, 8303090443.

--8303090529 Discusses final draft SER in response to CF Braun independent HVAC review. Draft SER app describing differences between results of Region III matl sampling program & portion of results made available to CF Braun, revised.
LANKSBURY, R D. Region 3, Office of Director. 83/01/06. Region 3, Office of Director. 1p. 17481:245. 24X Fiche: 50-373, 83/02/16, 8303090443.

8303020004 Tech Spec Change Request NPF-11/83-02 to License NPF-11, changing Tech Specs to reduce level requirements for carbon dioxide storage tanks.
SCHROEDER, C W. Commonwealth Edison Co. 83/02/24. SCHWENCER, A. Licensing Branch 2. 1p. 17353:146. 24X Fiche: 50-373, 83/02/24, 8303020004.

--8303020007 Proposed Tech Specs reducing level requirements for carbon dioxide storage tanks.
* Commonwealth Edison Co. 83/02/24. 4pp. 17353:147. 24X Fiche: 50-373, 83/02/24, 8303020004.

8303020012 Change Request NPF-11/83-01 to License NPF-11, revising organizational chart to reflect project manager position.
SCHROEDER, C W. Commonwealth Edison Co. 83/02/24. SCHWENCER, A. Licensing Branch 2. 1p. 17354:282. 24X Fiche: 50-373, 83/02/24, 8303020012.

--8303020018 Proposed Tech Spec change to Figure 6.1-1 re project manager position.
* Commonwealth Edison Co. 83/02/24. 2pp. 17354:283. 24X Fiche: 50-373, 83/02/24, 8303020012.

8303040491 Forwards proprietary "Comm Ed Discussion of NRC Concerns re LaSalle Containment High Frequency Response." Encl withheld (ref 10CFR2.790). Affidavit encl.
SCHROEDER, C. W. Commonwealth Edison Co. 83/02/28. SCHWENCER, A. Licensing Branch 2. 4pp. 17367:203. 24X Fiche: 50-373, 83/02/28, 8303040491.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303080470 Discusses util position re fee imposed by NRC 830128 ltr. License NPF-11 amended by NRC w/Amend 12 to clarify NRC intent re exemptions from 10CFR50.44. Fee considered inappropriate.
SCHROEDER, C. W. Commonwealth Edison Co. 83/03/02. DIGGS, R. M. License Fee Management Branch. 2pp. 17453:121. 24X Fiche: 50-373, 83/03/02, 8303080470.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J. G. Region 3, Office of Director. 83/03/03. Commonwealth Edison Co. 2pp. 17492:014. 24X Fiche: 50-000, 83/03/03, 8303100364.

8303110246 Forwards Rev 23 to CE-1-A, "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/04. HAASS, W. P. Quality Assurance Branch. 1p. 17515:357. 24X Fiche: 50-000, 83/03/04, 8303110246.

--8303110279 Rev 23 to "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments.
SHEWSKI, W. J. Commonwealth Edison Co. CE-1-A R23. 83/03/07. 5pp. 17515:358. 24X Fiche: 50-000, 83/03/04, 8303110246.

8303110314 Forwards proprietary "In-Plant Safety Relief Valve Test," initial evaluation rept. Withheld (rev 10CFR2.790).
SCHROEDER, C. W. Commonwealth Edison Co. 83/03/04. SCHWENCER, A. Licensing Branch 2. 4pp. 17517:265. 24X Fiche: 50-373, 83/03/04, 8303110314.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303180354 Notification of 830321-23 caseload forecast meetings w/util at site to discuss update of NRC projected Unit 2 fuel load date. Agenda encl.
BOURNIA, A. Licensing Branch 2. 83/03/08. SCHWENCER, A. Licensing Branch 2. 6pp. 17640:269. 24X Fiche: 50-373, 83/03/08, 8303180354.

8303170307 Change Request NPF-11/83-03 to License NPF-11, to reflect qualification requirements for rad/chem technicians.
SCHROEDER, C. W. Commonwealth Edison Co. 83/03/11. SCHWENCER, A. Licensing Branch 2. 5pp. 17605:144. 24X Fiche: 50-373, 83/03/11, 8303170307.

--8303170310 Proposed Tech Specs re qualifications of nuclear plant personnel.
* Commonwealth Edison Co. 83/03/11. 9pp. 17605:149. 24X Fiche: 50-373, 83/03/11, 8303170307.

8303220165 Forwards results of startup tests. Startup test program still incomplete. Repts covering remainder of testing will be submitted in 3-month intervals until testing complete.
SCHROEDER, C. W. Commonwealth Edison Co. 83/03/11. KEPPLER, J. G. Region 3, Office of Director. 2pp. 17657:041. 24X Fiche: 50-373, 83/03/11, 8303220165.

--8303220166 Results of startup tests.
* Commonwealth Edison Co. 83/03/11. 74pp. 17657:043. 24X Fiche: 50-373, 83/03/11, 8303220165.

8303180489 Forwards scaled cross-sectional drawings of drywell-to-wetwell vacuum breaker disc & valve body assembly, justifying use of hydrodynamic torque measurements to make vacuum breaker valve simulations.
SCHROEDER, C. W. Commonwealth Edison Co. 83/03/15. SCHWENCER, A. Licensing Branch 2. 4pp. 17622:118. 24X Fiche: 50-373, 83/03/15, 8303180489.

8303180609 Informs that GE switch, Type CR 2940 failed radiation environ qualification test. Resolution & justification for interim operation requested.
SCHWENCER, A. Licensing Branch 2. 83/03/16. FARRAR, D. A. Commonwealth Edison Co. 2pp. 17640:170. 24X Fiche: 50-373, 83/03/16, 8303180609.

8303300090 Clarifies intent of Tech Spec 3.8.1.2, per 830128 request. Spec should be flexible enough to permit operability of alternate electrical power sources.
EISENHUT, D. G. Division of Licensing. 83/03/22. NORELIUS, C. E. Division of Project & Resident Programs. 2pp. 17754:150. 24X Fiche: 50-373, 83/03/22, 8303300090.

8303290748 Forwards addl guidance for use in reporting offsite doses to public for 1982, per Tech Spec requirements.
SCHWENCER, A. Licensing Branch 2. 83/03/24. FARRAR, D. A. Commonwealth Edison Co. 4pp. 17748:032. 24X Fiche: 50-373, 83/03/24, 8303290748.

## Q. Inspection reports, IE Bulletins & correspondence

8303020074 Forwards addenda to inservice insp program rept, formatted to fit into inservice insp program document.
SCHROEDER, C. W. Commonwealth Edison Co. 83/02/18. SCHWENCER, A. Licensing Branch 2. 2pp. 17352:301. 24X Fiche: 50-373, 83/02/18, 8303020074.

--8303020079 Addenda to inservice insp program rept & instructions for updating rept.
* General Electric Co. 83/01/31. 139pp. 17352:303. 24X Fiche: 50-373, 83/02/18, 8303020074.

8303170529 Forwards IE Insp Repts 50-373/82-55 & 50-374/82-23 on 821201-31 & notice of violation.
NORELIUS, C. E. Division of Project & Resident Programs. 83/02/23. REED, C. Commonwealth Edison Co. 3pp. 17610:162. 24X Fiche: 50-373, 83/02/23, 8303170529.

--8303170534 Notice of violation from insp on 821201-31.
NORELIUS, C. E. Division of Project & Resident Programs. 83/02/23. 1p. 17610:165. 24X Fiche: 50-373, 83/02/23, 8303170529.

--8303170540 IE Insp Repts 50-373/82-55 & 50-374/82-23 on 821201-31. Noncompliance noted: failure to follow procedures re high voltage power supply causing cable to be left disconnected.
GULDEMOND, W., MADISON, A. Region 3, Office of Director. WALKER, R. D. Division of Project & Resident Programs. 83/02/10. 16pp. 17610:166. 24X Fiche: 50-373, 83/02/23, 8303170529.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303030530 Forwards IE Safeguards Insp Rept 50-373/83-08 on 830203-04. No noncompliance noted.
MILLER, J. R. Division of Engineering. 83/02/25. REED, C. Commonwealth Edison Co. 2pp. 17409:049. 24X Fiche: 50-373, 83/02/25, 8303030530.

--8303030540 IE Safeguards Insp Rept 50-373/83-08 on 830203-04. No noncompliance noted. Major areas inspected: actions pertaining to fire within turbine bldg. Details withheld (ref 10CFR73.21).
PIRTLE, G. L., CREED, J. R. Region 3, Office of Director. 83/02/24. 1p. 17409:051. 24X Fiche: 50-373, 83/02/25, 8303030530.

8303170532 Forwards IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al, on 830126. No noncompliance noted.
DAVIS, A. B. Region 3, Office of Director. 83/02/25. REED, C. Commonwealth Edison Co. 2pp. 17610:143. 24X Fiche: 50-000, 83/02/25, 8303170532.

--8303170557 IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al, on 830126. No noncompliance noted. Major areas discussed: proposed guidelines util personnel should use for providing info to Region III inspectors.
GULDEMOND, W. G. Division of Project & Resident Programs. 83/02/15. 4pp. 17610:145. 24X Fiche: 50-000, 83/02/25, 8303170532.

8303030471 Clarifies NRC position re procedures for admitting NRC personnel to facilities. Site orientation re issuance of badges, escort duties & emergency evacuation for personnel listed in Encls 1 & 2 requested.
KEPPLER, J. G. Region 3, Office of Director. 83/02/28. REED, C. Commonwealth Edison Co. 6pp. 17409:002. 24X Fiche: 50-373, 83/02/28, 8303030471.

8303140381 Forwards IE Insp Repts 50-373/82-57 & 50-374/82-24 on 821129-830112 & notice of violation.
SPESSARD, R L. Division of Engineering 83/02/28 REED, C
Commonwealth Edison Co 2pp 17541 001 24X Fiche 50-373, 83/02/28, 8303140381

--8303140411 Notice of violation from insp on 821129-830112
SPESSARD, R L. Region 3, Office of Director 83/02/28 3pp
17541 003 24X Fiche 50-373, 83/02/28, 8303140381

--8303140423 IE Insp Repts 50-373/82-57 & 50-374/82-24 on 821129-830112
Noncompliance noted: failure to follow procedures for temporary removal of support restraints & failure to perform adequate gamma plug insps.
MAURA, F ; NAIDU, K ; RING, M. Region 3, Office of Director
83/02/25 13pp 17541 006 24X Fiche 50-373, 83/02/28, 8303140381

8303170510 Forwards IE Insp Repts 50-373/83-01 & 50-374/83-01 on 830103-31 & notice of violation.
STREETER, J F. Division of Project & Resident Programs 83/03/01
REED, C. Commonwealth Edison Co 2pp 17610 186 24X
Fiche 50-373, 83/03/01, 8303170510

--8303170515 Notice of violation from insp on 830103-31.
STREETER, J F. Division of Project & Resident Programs 83/03/01
1p 17610 188 24X Fiche 50-373, 83/03/01, 8303170510

--8303170519 IE Insp Repts 50-373/83-01 & 50-374/83-01 on 830103-31.
Noncompliance noted: valve 1C41-F014 found unlocked.
GULDEMOND, W G ; MADISON, A L ; WALKER, R D. Division of Project & Resident Programs 83/02/25 11pp 17610 189 24X
Fiche 50-373, 83/03/01, 8303170510

8303070036 Forwards responses to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies," Bunker-Ramo electrical penetrations installed in LaSalle Unit 2, Byron Unit 2 & Braidwood Unit 2.
SWARTZ, E D. Commonwealth Edison Co 83/03/03 KEPPLER, J G Region 3, Office of Director 13pp 17435 290 24X Fiche 50-000, 83/03/03, 8303070036

8303140473 Ack receipt of 830215 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-373/83-01.
STREETER, J F. Region 3, Office of Director 83/03/09 REED, C
Commonwealth Edison Co 1p 17541 062 24X Fiche 50-373, 83/03/09, 8303140473

--8303140482 Responds to NRC 830119 ltr re violations noted in IE Insp Rept 50-373/83-01 Corrective actions: visible reminder signs placed at 710-ft & 768-ft entrances prohibiting smoking, eating & drinking.
FARRAR, D L. Commonwealth Edison Co 83/02/15 KEPPLER, J G
Region 3, Office of Director 3pp 17541 063 24X
Fiche 50-373, 83/03/09, 8303140473

8303240484 Forwards IE Insp Rept 50-373/83-02 on 830117-21 & notice of violation.
LITTLE, W S. Region 3, Office of Director 83/03/10 REED, C
Commonwealth Edison Co 2pp 17690 327 24X Fiche 50-373, 83/03/10, 8303240484

--8303240489 Notice of violation from insp on 830117-21.
LITTLE, W S. Region 3, Office of Director 83/03/09 1p
17690 329 24X Fiche 50-373, 83/03/10, 8303240484

--8303240498 IE Insp Rept 50-373/83-02 on 830117-21 Noncompliance noted: failure to provide documentary evidence that ECCS surveillance test conducted.
FARRELL, R E ; KISH, J N ; SUTPHIN, R N. Region 3, Office of Director 83/03/09 8pp 17690 330 24X Fiche 50-373, 83/03/10, 8303240484

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc
117pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 12lpp 17774 352 24X Fiche 50-000, 83/03/21, 8212060387

8303310211 Forwards addl info in response to IE Bulletin 81-03 re methods to control Corbicula. "Environ Studies of Braidwood Cooling Pond, 1982," encl.
SWARTZ, E D. Commonwealth Edison Co 83/03/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 17pp 17755 095 24X
Fiche 50-000, 83/03/28, 8303310211

R Periodic operating reports & related correspondence

8303150422 Forwards monthly operating rept for Jan 1983.
DIEDERICH, G J. Commonwealth Edison Co 83/02/03 Division of Data Automation & Management Information 1p 17561 178 24X
Fiche 50-373, 83/02/03, 8303150422

--8303150426 Monthly operating rept for Jan 1983.
ULLRICH, J. Commonwealth Edison Co 83/02/02 14pp 17561 179
24X Fiche 50-373, 83/02/03, 8303150422

S Reportable occurrences, LERs & related correspondence

8303080066 Forwards NPDES noncompliance notification on 830126, total suspended solids greater than parameter & permit limit. Probably caused by addition of condensate polishing sys to tank const wastes.
DIEDERICH, G J. Commonwealth Edison Co 83/02/18 KEPPLER, J G
Region 3, Office of Director 3pp 17457 239 24X
Fiche 50-373, 83/02/18, 8303080066

8303080234 Forwards LER 83-006/03L-0.
DIEDERICH, G J. Commonwealth Edison Co 83/02/24 KEPPLER, J G
Region 3, Office of Director 1p 17439 288 24X
Fiche 50-373, 83/02/24, 8303080234

--8303080244 LER 83-006/03L-0 on 830202, steam observed leaking from MSIV, 1B21-F028A, due to two cracks 180 degrees apart in weld where 1MS20AA-2-inch drain line attached to valve body. Caused by improper weld application. Weld repaired.
SPENCER, D. Commonwealth Edison Co 83/02/24 Region 3, Office of Director 2pp 17439 289 24X Fiche 50-373, 83/02/24, 8303080234

8303080491 Forwards LER 83-001/01T-0.
DIEDERICH, G J. Commonwealth Edison Co 83/02/24 KEPPLER, J G
Region 3, Office of Director 1p 17452 323 24X
Fiche 50-373, 83/02/24, 8303080491

--8303080502 LER 83-001/01T-0 on 830211, pressure switch 1E12-N413A in reactor vessel pressure LPCS/LPCI valve permissive circuit, found to have leaked past actuator stem. Caused by failure of seal inside switches. Switches replaced.
HOUSTON, R W. Commonwealth Edison Co 83/02/24 Region 3, Office of Director 3pp 17452 324 24X Fiche 50-373, 83/02/24, 8303080491

8303080064 Forwards LER 83-008/03L-0.
DIEDERICH, G J. Commonwealth Edison Co 83/02/25 KEPPLER, J G
Region 3, Office of Director 1p 17458 353 24X
Fiche 50-373, 83/02/25, 8303080064

--8303080075 LER 83-008/03L-0 on 830203, while performing visual insp per Tech Specs, snubber LC01-1106S found inoperable. Caused by missing pin due to improper field practices. Pin replaced.
SPENCER, D. Commonwealth Edison Co 83/02/25 Region 3, Office of Director 2pp 17458 354 24X Fiche 50-373, 83/02/25, 8303080064

8303080358 Forwards NPDES noncompliance notification re excessive iron activity in Outfall 001c low vol waste wastewater treatment facility effluent on 830201. Caused by failure of alum pumps to inject alum. Transmittal ltr to EPA encl.
DIEDERICH, G J. Commonwealth Edison Co 83/02/25 KEPPLER, J G
Region 3, Office of Director 2pp 17453 243 24X
Fiche 50-373, 83/02/25, 8303080358

--8303080366 NPDES noncompliance notification on 830201, Outfall 001c low vol waste wastewater treatment facility effluent had measured activity of 1.6 mg per liter of total iron, exceeding 1 mg limit. Caused by alum pump malfunction.
* Commonwealth Edison Co 83/02/25 1p 17453 245 24X
Fiche 50-373, 83/02/25, 8303080358

8303140477 Forwards LER 83-007/01T-0.
DIEDERICH, G J. Commonwealth Edison Co 83/02/25 KEPPLER, J G
Region 3, Office of Director 1p 17540 305 24X
Fiche 50-373, 83/02/25, 8303140477

--8303140486 LER 83-007/01T-0 on 830205, observed steam leaking from MSIV 1B21-F022C due to crack in weld where 1MS14AC 2-inch drainline connects to valve body. Caused by improper weld application. Weld repaired & ground to eliminate notches. SPENCER, D Commonwealth Edison Co 83/02/25 Region 3, Office of Director 2pp 17540 306 24X Fiche 50-373, 83/02/25, 8303140477.

8303140424 Forwards LER 83-010/03L-0. DIEDERICH, G J Commonwealth Edison Co 83/03/03 KEPPLER, J G Region 3, Office of Director 1p 17542 060 24X Fiche 50-373, 83/03/03, 8303140424.

--8303140437 LER 83-010/03L-0 on 830209, during insp of main steam drain line piping, mechanical restraint MS20-1012X found installed on line 1MS20BA-1-1/2 inch in violation of plant design. Caused by personnel oversight. Restraint removed. SPENCER, D Commonwealth Edison Co 83/03/03 Region 3, Office of Director 2pp 17542 061 24X Fiche 50-373, 83/03/03, 8303140424.

8303170477 Forwards LER 83-009/03L-0. DIEDERICH, G J Commonwealth Edison Co 83/03/04 KEPPLER, J G Region 3, Office of Director 1p 17610 245 24X Fiche 50-373, 83/03/04, 8303170477.

--8303170481 LER 83-009/03L-0 on 830208, during insp of main steam drain line piping, mechanical snubber 1MS20CB-1 1/2 HOIS found excessively hard to stroke. Caused by bent ball screw shaft. Snubber & welds replaced. SPENCER, D Commonwealth Edison Co 83/03/03 Region 3, Office of Director 2pp 17610 246 24X Fiche 50-373, 83/03/04, 8303170477.

8303170478 Forwards LER 83-011/03L-0. DIEDERICH, G J Commonwealth Edison Co 83/03/07 KEPPLER, J G Region 3, Office of Director 1p 17610 248 24X Fiche 50-373, 83/03/07, 8303170478.

--8303170486 LER 83-011/03L-0 on 830208, during LIS-NB-01, LIS 1B21-N024B setpoint found out of tolerance in nonconservative direction. Cause undetermined. Switch recalibr. ITT Barton Model 288A trended to assist in determining further action. HOUSTON, R Commonwealth Edison Co 83/03/07 Region 3, Office of Director 2pp 17610 249 24X Fiche 50-373, 83/03/07, 8303170478.

8303210431 Forwards updated LER 83-006/01X-1. DIEDERICH, G J Commonwealth Edison Co 83/03/07 KEPPLER, J G Region 3, Office of Director 1p 17634 212 24X Fiche 50-373, 83/03/07, 8303210431.

--8303210441 Updated LER 83-006/01X-1 on 830208, cracks discovered in MSIV 1B21-F028A drain line weld. Caused by improper weld application. Weld repaired. New weld ground down to eliminate notches between passes & magnetic particle tested. SPENCER, D Commonwealth Edison Co 83/03/07 Region 3, Office of Director 2pp 17634 213 24X Fiche 50-373, 83/03/07, 8303210431.

8303210356 Forwards LER 83-012/03L-0. DIEDERICH, G J Commonwealth Edison Co 83/03/10 KEPPLER, J G Region 3, Office of Director 1p 17632 319 24X Fiche 50-373, 83/03/10, 8303210356.

--8303210359 LER 83-012/03L-0 on 830210, during LIS-R1-03, RCIC leak detection temp switch setpoints found out of calibr. Caused by defective calibr instrument. Temp switches recalibr. Calibr instrument replaced. WITTENBURG, K Commonwealth Edison Co 83/03/10 Region 3, Office of Director 2pp 17632 320 24X Fiche 50-373, 83/03/10, 8303210356.

8303220107 Forwards LER 83-014/03L-0. DIEDERICH, G J Commonwealth Edison Co 83/03/16 KEPPLER, J G Region 3, Office of Director 1p 17649 274 24X Fiche 50-373, 83/03/16, 8303220107.

--8303220109 LER 83-014/03L-0 on 830215, differential pressure indicating switch 1E31-N013A high differential pressure setpoint found out of tolerance in nonconservative direction. Cause undetermined. Switch recalibr. HOUSTON, R W Commonwealth Edison Co 83/03/16 Region 3, Office of Director 2pp 17649 275 24X Fiche 50-373, 83/03/16, 8303220107.

8303240387 Forwards updated LER 82-149/03X-1. DIEDERICH, G J Commonwealth Edison Co 83/03/16 KEPPLER, J G Region 2, Office of Director 1p 17679 127 24X Fiche 50-373, 83/03/16, 8303240387.

--8303240389 Updated LER 82-149/03X-1 on 821112, flow recorder gave incorrect readings. Caused by algae buildup on instrument probe. Sys modified & AIR 1-82-58035 generated to track mod. WATFORD, P S Commonwealth Edison Co 83/03/16 Region 2, Office of Director 2pp 17679 128 24X Fiche 50-373, 83/03/16, 8303240387.

8303240421 Forwards LER 83-015/03L-0. Detailed event analysis encl. DIEDERICH, G J Commonwealth Edison Co 83/03/17 KEPPLER, J G Region 3, Office of Director 2pp 17679 036 24X Fiche 50-373, 83/03/17, 8303240421.

--8303240424 LER 83-015/03L-0 on 830217, while testing diesel generator 1B per LOS-DG-M3, diesel tripped while being off loaded. Diesel restarted & speed varied between 400 & 900 rpm. Caused by bad connection at run solenoid. Connection reconnected. HIETALA, J J Commonwealth Edison Co 83/03/17 Region 3, Office of Director 1p 17679 038 24X Fiche 50-373, 83/03/17, 8303240421.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000, 83/02/24, 8302250505.

8303040631 Forwards listing of projected operator licensing exam dates including type of exam & probable number of candidates, in response to 830111 Generic Ltr 83-01. SWARTZ, E D Commonwealth Edison Co 83/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 17367 209 24X Fiche 50-000, 83/03/01, 8303040631.

DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2

A. Application/construction stage documents & correspondence

8303090437 FOIA request for NRC records reviewing CF Braun audit of HVAC sys at facilities. Waiver of fees requested. GARDE, B Government Accountability Project 83/01/14 Office of Administration 1p 17481 174 24X Fiche 50-373, 83/01/14, 8303090437.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl. EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24X Fiche 50-000, 83/02/16, 8302170082.

8303090443 Responds to FOIA request for NRC records reviewing CF Braun audit of HVAC sys at facilities. Forwards App B documents. App A documents available in PDR. FELTON, J M Division of Rules and Records 83/02/16 GARDE, B Government Accountability Project 4pp 17481 175 24X Fiche 50-373, 83/02/16, 8303090443.

--8209210510 Comments on review of Revision 1 to technical proposal for independent review of HVAC sys, submitted on 820827. Addl reviews performed by other branches encl. Proposed program will accomplish verification of HVAC sys. RUBENSTEIN, L S Assistant Director for Core & Plant Systems 82/09/01 NOVAK, T M Assistant Director for Licensing 3pp 17481 223 24X Fiche 50-373, 83/02/16, 8303090443.

--8211090596 Advises that CF Brown interim rept on plant independent HVAC sys review acceptable & consistent w/820825 technical proposal. Objective of review is to verify Zack Co HVAC installation in accordance w/Sargent & Lundy design. KNIGHT, J P Assistant Director for Comp & Structures Engineering (Pre 830201) 82/10/28 NOVAK, T M Assistant Director for Licensing 1p 17481 232 24X Fiche 50-373, 83/02/16, 8303090443.

--8211110155 Forwards Mechanical Engineering Branch SER input re mechanical design, based on review of CF Braun 821027 "Independent HVAC Review Final Rept - LaSalle Station." KNIGHT, J P Assistant Director for Comp & Structures Engineering (Pre 830201) 82/11/02 NOVAK, T M Assistant Director for Licensing 3pp 17481 233 24X Fiche 50-373, 83/02/16, 8303090443.

--8211110643 Forwards QA Branch final SER input re independent HVAC review conducted by CF Brown & Co. JOHNSTON, W V Assistant Director for Matls & Qualif Engineering (Pre 830201) 82/11/03 NOVAK, T M Assistant Director for Licensing 3pp 17481 210 24X Fiche 50-373, 83/02/16, 8303090443.

--8211170104 Forwards SER input on independent design review of HVAC sys Independent review of HVAC sys acceptably verified functional adequacy of HVAC sys
RUBENSTEIN, L S Assistant Director for Core & Plant Systems 82/11/04 NOVAK, T M Assistant Director for Licensing 6pp 17481 226 24X Fiche 50-373, 83/02/16, 8303090443

--8212010304 Informs that Matls Engineering Branch review of 821027 "Independent HVAC Review Final Rept" complete SER input addressing area of matl engineering encl
JOHNSTON, W V Assistant Director for Matls & Qualif Engineering (Pre 830201) 82/11/18 NOVAK, T M Assistant Director for Licensing 5pp 17481 218 24X Fiche 50-373, 83/02/16, 8303090443

--8212020228 Forwards addl info to draft SER re CF Braun HVAC review describing NRC involvement & summary of overall results Review & comments requested by 821122
NOVAK, T M Assistant Director for Licensing 82/11/19
NORELIUS, C E Division of Engineering JOHNSTON, W V Assistant Director for Matls & Qualif Engineering (Pre 830201)
RUBENSTEIN, L R Assistant Director for Core & Plant Systems
17pp 17481 184 24X Fiche 50-373, 83/02/16, 8303090443

--8212160101 Forwards revised Pages 10, 11, 12 & 13 of draft SER on HVAC independent review in response to 821119 memo
JOHNSTON, W V Assistant Director for Matls & Qualif Engineering (Pre 830201) 82/12/02 NOVAK, T M Assistant Director for Licensing 5pp 17481 213 24X Fiche 50-373, 83/02/16, 8303090443

--8212210480 Forwards revised SER for QA of independent HVAC review providing addl detail of review per 821118 meeting commitment
JOHNSTON, W V Assistant Director for Matls & Qualif Engineering (Pre 830201) 82/12/02 NOVAK, T M Assistant Director for Licensing 3pp 17481 181 24X Fiche 50-373, 83/02/16, 8303090443

--8303090499 Forwards final draft SER in response to CF Braun rept re HVAC sys W/o encl Matls Engineering Branch requirements of SER encl
EISENHUT, D G Division of Licensing 82/11/09 KEPPLER, J G Region 3, Office of Director 5pp 17481 236 24X
Fiche 50-373, 83/02/16, 8303090443

--8303090517 Forwards draft SER app re matl sampling program of HVAC sys at facilities Discussion of subj scheduled for 821123
DENTON, H Office of Nuclear Reactor Regulation, Director 82/11/22 KEPPLER, J Region 3, Office of Director 4pp 17481 241 24X Fiche 50-373, 83/02/16, 8303090443

--8303090529 Discusses final draft SER in response to CF Braun independent HVAC review Draft SER app describing differences between results of Region III matl sampling program & portion of results made available to CF Braun revised
LANKSBURY, R D Region 3, Office of Director 83/01/06 Region 3, Office of Director 1p 17481 245 24X Fiche 50-373, 83/02/16, 8303090443

8303040491 Forwards proprietary "Comm Ed Discussion of NRC Concerns re LaSalle Containment High Frequency Response " Encl withheld (ref 10CFR2 790) Affidavit encl
SCHROEDER, C W Commonwealth Edison Co 83/02/28 SCHWENCER, A Licensing Branch 2 4pp 17367 203 24X Fiche 50-373, 83/02/28, 8303040491

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification or surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X
Fiche 50-000, 83/03/02, 8303020321

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/ electronic networking sys
KEPPLER, J G Region 3, Office of Director 83/03/03
Commonwealth Edison Co 2pp 17492 014 24X Fiche 50-000, 83/03/03, 8303100364

8303110246 Forwards Rev 23 to CE-1-A, "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments
SWART2, E D Commonwealth Edison Co 83/03/04 HAASS, W P Quality Assurance Branch 1p 17515 357 24X Fiche 50-000, 83/03/04, 8303110246

--8303110279 Rev 23 to "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments
SHEWSKI, W J Commonwealth Edison Co CE-1-A R23 83/03/07 5pp 17515 358 24X Fiche 50-000, 83/03/04, 8303110246

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 5lpp 17660 176 24X
Fiche 50-000, 83/03/07, 8303040005

8303180354 Notification of 830321-23 caseload forecast meetings w/util at site to discuss update of NRC projected Unit 2 fuel load date Agenda encl
BOURNIA, A Licensing Branch 2 83/03/08 SCHWENCER, A Licensing Branch 2 6pp 17640 269 24X Fiche 50-373, 83/03/09, 8303180354

8303180489 Forwards scaled cross-sectional drawings of drywell-to-wetwell vacuum breaker disc & valve body assembly, justifying use of hydrodynamic torque measurments to make vacuum breaker valve simulations
SCHROEDER, C W Commonwealth Edison Co 83/03/15 SCHWENCER, A Licensing Branch 2 4pp 17622 118 24X Fiche 50-373, 83/03/15, 8303180489

8303180609 Informs that GE switch, Type CR 2940 failed radiation environ qualification test Resolution & justification for interim operation requested
SCHWENCER, A Licensing Branch 2 83/03/16 FARRAR, D A Commonwealth Edison Co 2pp 17640 170 24X Fiche 50-373, 83/03/16, 8303180609

8303290269 Forwards review of implementation status of Unit 1 license conditions as potentially applicable to Unit 2 Documentation, corrections of deficiencies & testing will be completed by Unit 2 OL issuance
SCHROEDER, C W Commonwealth Edison Co 83/03/18 SCHWENCER, A Licensing Branch 2 64pp 17716 017 24X Fiche 50-374, 83/03/18, 8303290269

F Security, medical, emergency & fire protection plans

8303010595 Ack receipt of 830124 ltr identifying 1983 dates for emergency preparedness exercises within State of IL Dates determined to be within required exercise frequency
HIND, J A Region 3, Office of Director 83/02/24 JONES, E E Illinois, State of 2pp 17336 208 24X Fiche 50-000, 83/02/24, 8303010595

--8303010618 Submits 1983 dates scheduled for emergency preparedness exercises for facilities within State of IL
JONES, E E Illinois, State of 83/01/24 KEPPLER, J Region 3, Office of Director 2pp 17336 210 24X Fiche 50-000, 83/02/24, 8303010595

8303030020 Forwards corrected Page 5-7c of Rev 13 to modified security plan Page withheld (ref 10CFR73 21)
FARRAR, D L Commonwealth Edison Co 83/02/28 Office of Nuclear Reactor Regulation, Director 1p 17412 132 24X
Fiche 50-373, 83/02/28, 8303030020

8303090267 Releases public version of revised emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/03/02 Document Management Branch 1p 17484 303 24X Fiche 50-373, 83/03/02, 8303090267

--8303090274 Forwards public version of Rev 2 to Emergency Plan Implementing Procedure LZP 1550-5, "Technical Support Ctr Quarterly Surveillance "
* Commonwealth Edison Co 83/03/09 Office of Nuclear Reactor Regulation, Director 1p 17484 304 24X Fiche 50-373, 83/03/02, 8303090267

--8303090284 Public version of Rev 2 to Emergency Plan Implementing Procedure LZP 1550-5, "Technical Support Ctr Quarterly Surveillance " Revised index encl
* Commonwealth Edison Co 83/02/09 12pp 17484 305 24X
Fiche 50-373, 83/03/02, 8303090267

8303170209 Advises that Rev 13 to modified amended security plan acceptable Encl to 821129 ltr withheld (ref 10CFR73 21)
SCHWENCER, A Licensing Branch 2 83/03/10 FARRAR, D L Commonwealth Edison Co 2pp 17623 352 24X Fiche 50-373, 83/03/10, 8303170209

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition Appropriate planning should take place to prevent possible transmission errors
HIND, J A Region 3, Office of Director 83/03/22 Commonwealth Edison Co 2pp 17690 316 24X Fiche 50-000, 83/03/22, 8303240440

8303310082 Releases public version of revised emergency plan implementing procedures.
FELTON, J M. Division of Rules and Records 83/03/25 Document Management Branch 1p 17777 102 24X Fiche 50-373, 83/03/25, 8303310082.

--8303310087 Forwards public version of Rev 4 to Emergency Plan Implementing Procedure LZP-1110-1 re station director (acting station director) implementing procedure & Rev 3 to LZP-1310-1 re notifications.
* Commonwealth Edison Co 83/03/07 Office of Nuclear Reactor Regulation, Director 5pp 17777 103 24X Fiche 50-373, 83/03/25, 8303310082.

--8303310092 Public version of Rev 4 to Emergency Plan Implementing Procedure LZP-1110-1 re station director (acting station director) implementing procedure & Rev 3 to LZP-1310-1 re notifications.
* Commonwealth Edison Co 83/03/02 52pp 17777 108 24X Fiche 50-373, 83/03/25, 8303310082.

8303310124 Releases public version of revised emergency plan implementing procedure.
FELTON, J M. Division of Rules and Records 83/03/25 Document Management Branch 1p 17775 184 24X Fiche 50-000, 83/03/25, 8303310124.

--8303310130 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure EG-1, "Coordination of Environs Group Activities by Environs Director."
* Commonwealth Edison Co 83/03/17 Director's Office, Office of Inspection and Enforcement 1p 17775 185 24X Fiche 50-000, 83/03/25, 8303310124.

--8303310146 Public version of Rev 3 to Emergency Plan Implementing Procedure EG-1, "Coordination of Environs Group Activities by Environs Director."
PAJOWSKI, J E. Commonwealth Edison Co 83/03/08 87pp 17775 186 24X Fiche 50-000, 83/03/25, 8303310124.

8303300532 Releases public version of request for return of listed controlled copies of emergency plan.
FELTON, J M. Division of Rules and Records 83/03/28 Document Management Branch 1p 17763 178 24X Fiche 50-000, 83/03/28, 8303300532.

--8303300561 Submits public version of request for return of listed controlled copies of emergency plan.
FLESSNER, R A. Commonwealth Edison Co 83/03/15 DENTON, H R. Office of Nuclear Reactor Regulation, Director 1p 17763 179 24X Fiche 50-000, 83/03/28, 8303300532.

## Q. Adjudicatory correspondence

8303100387 Order extending time until 830407 for Commission to act to review Director's Decision DD-83-01.
CHILK, S J. Office of the Secretary of the Commission 83/03/07 Commissioners 1p 17488 335 24X Fiche 50-373, 83/03/07, 8303100387.

## H. General correspondence

8303030528 Informs that DL Farrar has replaced LO DelGeorge as Director of Nuclear Licensing for util Rev of current NRC distribution list requested.
FARRAR, D L. Commonwealth Edison Co 83/02/02 DENTON, H R. Office of Nuclear Reactor Regulation, Director 1p 17409 048 24X Fiche 50-000, 83/02/02, 8303030528.

## I. Financial information

8303070135 Forwards Annual Financial Rept 1982.
BRESEMANN, R W. Commonwealth Edison Co 83/02/28 Division of Licensing 1p 17433 001 24X Fiche 50-000, 83/02/28, 8303070135.

--8303070151 Annual Financial Rept 1982.
O'CONNOR, J J. Commonwealth Edison Co 83/02/03 13pp 17433 002 24X Fiche 50-000, 83/02/28, 8303070135.

## Q. Inspection reports, IE Bulletins & correspondence

8303170529 Forwards IE Insp Repts 50-373/82-55 & 50-374/82-23 on 821201-31 & notice of violation.
NORELIUS, C E. Division of Project & Resident Programs 83/02/23 REED, C. Commonwealth Edison Co 3pp 17610 162 24X Fiche 50-373, 83/02/23, 8303170529.

--8303170534 Notice of violation from insp on 821201-31.
NORELIUS, C E. Division of Project & Resident Programs 83/02/23 1p 17610 165 24X Fiche 50-373, 83/02/23, 8303170529.

--8303170540 IE Insp Repts 50-373/82-55 & 50-374/82-23 on 821201-31. Noncompliance noted: failure to follow procedures re high voltage power supply causing cable to be left disconnected.
GULDEMOND, W., MADISON, A. Region 3, Office of Director WALKER, R D. Division of Project & Resident Programs 83/02/10 16pp 17610 166 24X Fiche 50-373, 83/02/23, 8303170529.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 111pp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367.

8303170532 Forwards IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al, on 830126. No noncompliance noted.
DAVIS, A B. Region 3, Office of Director 83/02/25 REED, C. Commonwealth Edison Co 2pp 17610 143 24X Fiche 50-000, 83/02/25, 8303170532.

--8303170557 IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al, on 830126. No noncompliance noted. Major areas discussed: proposed guidelines util personnel should use for providing info to Region III inspectors.
GULDEMOND, W G. Division of Project & Resident Programs 83/02/15 4pp 17610 145 24X Fiche 50-000, 83/02/25, 8303170532.

8303030471 Clarifies NRC position re procedures for admitting NRC personnel to facilities. Site orientation re issuance of badges, escort duties & emergency evacuation for personnel listed in Encls 1 & 2 requested.
KEPPLER, J G. Region 3, Office of Director 83/02/28 REED, C. Commonwealth Edison Co 6pp 17409 002 24X Fiche 50-373, 83/02/28, 8303030471.

8303140381 Forwards IE Insp Repts 50-373/82-57 & 50-374/82-24 on 821129-830112 & notice of violation.
SPESSARD, R L. Division of Engineering 83/02/28 REED, C. Commonwealth Edison Co 2pp 17541 001 24X Fiche 50-373, 83/02/28, 8303140381.

--8303140411 Notice of violation from insp on 821129-830112.
SPESSARD, R L. Region 3, Office of Director 83/02/28 3pp 17541 003 24X Fiche 50-373, 83/02/28, 8303140381.

--8303140423 IE Insp Repts 50-373/82-57 & 50-374/82-24 on 821129-830112. Noncompliance noted: failure to follow procedures for temporary removal of support restraints & failure to perform adequate gamma plug insps.
MAURA, F., NAIDU, K., RING, M. Region 3, Office of Director 83/02/25 13pp 17541 006 24X Fiche 50-373, 83/02/28, 8303140381.

8303170510 Forwards IE Insp Repts 50-373/83-01 & 50-374/83-01 on 830103-31 & notice of violation.
STREETER, J F. Division of Project & Resident Programs 83/03/01 REED, C. Commonwealth Edison Co 2pp 17610 186 24X Fiche 50-373, 83/03/01, 8303170510.

--8303170519 IE Insp Repts 50-373/83-01 & 50-374/83-01 on 830103-31. Noncompliance noted: valve 1C41-F014 found unlocked.
GULDEMOND, W G., MADISON, A L., WALKER, R D. Division of Project & Resident Programs 83/02/25 11pp 17610 189 24X Fiche 50-373, 83/03/01, 8303170510.

8303070036 Forwards responses to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies," Bunker-Ramo electrical penetrations installed in LaSalle Unit 2, Byron Unit 2 & Braidwood Unit 2.
SWARTZ, E D. Commonwealth Edison Co 83/03/03 KEPPLER, J G. Region 3, Office of Director 13pp 17435 290 24X Fiche 50-000, 83/03/03, 8303070036.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc 117pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 121pp 17774 352 24X Fiche 50-000, 83/03/21, 8212060387.

8303310211 Forwards addl info in response to IE Bulletin 81-03 re methods to control Corbicula. "Environ Studies of Braidwood Cooling Pond, 1982." encl
SWARTZ, E. D. Commonwealth Edison Co. 83/03/28. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 17pp. 17755:095. 24X Fiche: 50-000, 83/03/28, 8303310211.

S. Reportable occurrences, LERs & related correspondence

8303080003 PNO-III-83-016 on 830228, two contractor employees apprehended for smoking marijuana in heater drain tank room. Employees refused to release urinalysis results to licensee & were subsequently fired. No news release planned.
CREED, J. WALKER, R. Region 3, Office of Director. 83/03/01. 1p. 17454:346. 24X Fiche: 50-374, 83/03/01, 8303080003.

8303140365 Final Deficiency Rept 82-08 re electrical penetration assemblies. Initially reported on 820817. Replacement modules will be installed by 830501.
SCHROEDER, C. W. Commonwealth Edison Co. 83/03/01. KEPPLER, J. G. Region 3, Office of Director. 2pp. 17544:144. 24X Fiche: 50-374, 83/03/01, 8303140365.

8303220056 Final deficiency rept re significant deviation from performance specs for SOR, Inc pressure switches installed as part of ECCS interlock mod. Initially reported on 830216. All leaking O-rings replaced.
SCHROEDER, C. W. Commonwealth Edison Co. 83/03/16. KEPPLER, J. G. Region 3, Office of Director. 2pp. 17652:166. 24X Fiche: 50-374, 83/03/16, 8303220056.

8303220145 Interim Deficiency Rept 83-01 re significant deviation from performance specs for Riley temp switches in leak detection sys. Initially reported on 830215. Two units returned to GE for evaluation. Temp module resolution expected by Apr 1983.
SCHROEDER, C. W. Commonwealth Edison Co. 83/03/16. KEPPLER, J. G. Region 3, Office of Director. 2pp. 17658:250. 24X Fiche: 50-374, 83/03/16, 8303220145.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303040631 Forwards listing of projected operator licensing exam dates including type of exam & probable number of candidates, in response to 830111 Generic Ltr 83-01.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/01. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 17367:209. 24X Fiche: 50-000, 83/03/01, 8303040631.

DOCKET: 50-375 NUCLEAR EXAMINATION REACTOR

W. Decommissioning Stage Documents & Correspondence

8303020389 Forwards order authorizing dismantling of L-85 nuclear exam reactor, per 800310 application. Safety evaluation, EIA & negative declaration encl.
EISENHUT, D. G. Division of Licensing. 83/02/22. REMLEY, M. E. Rockwell International Corp. 2pp. 17357:322. 24X Fiche: 50-375, 83/02/22, 8303020389.

--8303020394 Order authorizing dismantling of facility & disposition of component parts.
EISENHUT, D. G. Division of Licensing. 83/02/22. Rockwell International Corp. 2pp. 17357:324. 24X Fiche: 50-375, 83/02/22, 8303020389.

--8303020400 Safety evaluation supporting order authorizing dismantling of facility & disposition of component parts.
* Office of Nuclear Reactor Regulation, Director. 83/02/22. 2pp. 17357:326. 24X Fiche: 50-375, 83/02/22, 8303020389.

--8303020403 EIA supporting order authorizing dismantling of facility & disposition of component parts.
* Office of Nuclear Reactor Regulation, Director. 83/02/22. 2pp. 17357:328. 24X Fiche: 50-375, 83/02/22, 8303020389.

--8303020407 Negative declaration supporting order authorizing dismantling of facility & disposition of component parts.
EISENHUT, D. G. Division of Licensing. 83/02/22. 1p. 17357:330. 24X Fiche: 50-375, 83/02/22, 8303020389.

DOCKET: 50-382 WATERFORD GENERATING STATION, UNIT 3

A. Application/construction stage documents & correspondence

8303010600 Forwards Rev 2 to response to NUREG-0588, "Environmental Qualification of Safety-Related Electrical Equipment Exposed to Harsh Environ."
MAURIN, L. V. Louisiana Power & Light Co. 82/11/17. NOVAK, T. M. Assistant Director for Licensing. 1p. 17337:272. 24X Fiche: 50-382, 82/11/17, 8303010600.

--8303010607 "Waterford SES Unit 3 Response to NUREG-0588," re environ qualification of safety-related equipment.
* Ebasco Services, Inc. (subs. of Enserch Corp.). 82/11/17. 1,221pp. 17337:273. 24X Fiche: 50-382, 82/11/17, 8303010600.

8303140612 Forwards request for addl info re core protection calculator/reactor power cutback sys. Response requested within 30 days.
KNIGHTON, G. W. Licensing Branch 3. 83/02/10. MAURIN, L. V. Louisiana Power & Light Co. 5pp. 17548:347. 24X Fiche: 50-382, 83/02/10, 8303140612.

8303010499 Responds to 830128 ltr re seismic qualification of equipment. No containment structure mounted equipment qualified by single frequency method.
MAURIN, L. V. Louisiana Power & Light Co. 83/02/11. KNIGHTON, G. Licensing Branch 3. 1p. 17343:347. 24X Fiche: 50-382, 83/02/11, 8303010499.

8303030678 Submits confirmatory info re util commitment to conduct UHS preoperational testing to verify performance ability. Results of series of full-capacity heat load tests, conducted May-Oct 1982, show that UHS sys meets thermal design basis.
MAURIN, L. V. Louisiana Power & Light Co. 83/02/11. NOVAK, T. M. Assistant Director for Licensing. 7pp. 17411:003. 24X Fiche: 50-382, 83/02/11, 8303030678.

8303010707 Responds to util 821220 ltr re inadequate licensing method for calculating C-E 16 x 16 fuel assembly shoulder gap spacing reduction. FSAR should be amended to reflect proposed fuel assembly mod & analytical basis.
NOVAK, T. M. Assistant Director for Licensing. 83/02/15. MAURIN, L. V. Louisiana Power & Light Co. 2pp. 17348:320. 24X Fiche: 50-382, 83/02/15, 8303010707.

8303030747 Board Notification 83-13 forwards EG&G draft rept, "Identification & Ranking of Nuclear Plant Structures, Sys & Components & Graded QA Guidelines."
EISENHUT, D. G. Division of Licensing. 83/02/17. PALLADINO, N. Commissioners. 24pp. 17364:037. 24X Fiche: 50-000, 83/02/17, 8303030747.

8303030710 Board Notification 83-17 forwards JH Conran 830209 affidavit re changes to previous testimony on Unresolved Safety Issue A-17, "Sys Interaction in Nuclear Power Plants."
EISENHUT, D. G. Division of Licensing. 83/02/18. PALLADINO, N. J. Commissioners. 6pp. 17363:317. 24X Fiche: 50-000, 83/02/18, 8303030710.

8303100274 Forwards addl info re equipment qualification (EQ) per request during EQ audit at facility. Info concerns use of O-rings on ITT Barton pressure switches.
MAURIN, L. V. Louisiana Power & Light Co. 83/02/24. KNIGHTON, G. Licensing Branch 3. 3pp. 17489:340. 24X Fiche: 50-382, 83/02/27, 8303100274.

8303100285 Advises that valve manufacturer contracted to provide info re containment purge valve operability per 820923 ltr. Response to Equipment Qualification Branch questions will be submitted by 830516.
MAURIN, L. V. Louisiana Power & Light Co. 83/02/28. KNIGHTON, G. Licensing Branch 3. 1p. 17489:306. 24X Fiche: 50-382, 83/02/28, 8303100285.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303080014 Forwards response to 830103 request for addl info re effects of harsh environ on nonmetallic matls of components in safety-related sys. Comprehensive evaluation of safety-related purchase orders conducted.
MAURIN, L. V. Louisiana Power & Light Co. 83/03/02. KNIGHTON, G. W. Licensing Branch 3. 7pp. 17455:317. 24X Fiche: 50-382, 83/03/02, 8303080014.

8303080083 Forwards equipment qualification data evaluation forms, per 830202 ltr, in response to H Garg request Package should close out audit followup. Comment 25.
MAURIN, L. V. Louisiana Power & Light Co. 83/03/02 KNIGHTON, G. W. Licensing Branch 3 885pp 17437.001 24X Fiche 50-382, 83/03/02, 8303080083.

8303080467 Forwards draft amend to FSAR, consisting of results of revised large break LOCA ECCS performance analysis. Amend also updates FSAR Sections 6.2.1.5.6.3.3.1 & 15.6.3.3.1. Info will be included in next FSAR amend.
MAURIN, L. V. Louisiana Power & Light Co. 83/03/03 KNIGHTON, G. W. Licensing Branch 3 47pp 17453.066 24X Fiche 50-382, 83/03/03, 8303080467.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp 17660.176 24X Fiche 50-000, 83/03/07, 8303040005.

8303180503 Notification of 830310 meeting w/util & P&L in Bethesda, MD to discuss operating procedures for facility.
WILSON, J. H. Licensing Branch 3 83/03/07 KNIGHTON, G. W. Licensing Branch 3 3pp 17640.207 24X Fiche 50-382, 83/03/07, 8303180503.

8303150340 Advises of 830405 meeting w/licensees & major contractors at Dallas/Fort Worth, TX to provide info & guidance re 10CFR50 QA & Tech Spec deviations & discuss decentralization policy. Questions should be submitted in writing by 830321.
COLLINS, J. T. Region 4, Office of Director 83/03/10 Public Service Co. of Colorado 12pp 17562.291 24X Fiche 50-000, 83/03/10, 8303150340.

8303160506 Forwards proposed rev to FSAR committing to set of low power natural circulation tests in satisfaction of operator training requirements of NUREG-0737, Item I.G.1.
MAURIN, L. V. Louisiana Power & Light Co. 83/03/10 KNIGHTON, G. Licensing Branch 3 4pp 17592.314 24X Fiche 50-382, 83/03/10, 8303160506.

8303150364 Advises of 830405 meeting w/licensees & major contractors at Dallas/Fort Worth, TX to provide info & guidance re 10CFR50 QA & Tech Spec deviations & discuss decentralization policy. Questions should be submitted in writing by 830321.
COLLINS, J. T. Region 4, Office of Director 83/03/11 MAURIN, L. V. Louisiana Power & Light Co. 3pp 17566.243 24X Fiche 50-382, 83/03/11, 8303150364.

8303170360 Responds to NRC 830209 ltr re Union Carbide plant chemical explosion & fire during Dec 1982. Incident did not jeopardize safety of plant. Evaluation suggests some improvements in onsite procedures should be made.
MAURIN, L. V. Louisiana Power & Light Co. 83/03/11 EISENHUT, D. G. Division of Licensing 11pp 17609.267 24X Fiche 50-382, 83/03/11, 8303170360.

8303240188 Forwards application for 40-yr OL from date of issuance of OL rather than from date of CP issuance.
MAURIN, L. V. Louisiana Power & Light Co. 83/03/18 KNIGHTON, G. W. Licensing Branch 3 3pp 17681.016 24X Fiche 50-382, 83/03/18, 8303240188.

--8303240196 Application for 40-yr OL.
MAURIN, L. V. Louisiana Power & Light Co. 83/03/15 3pp 17681.019 24X Fiche 50-382, 83/03/18, 8303240188.

8303290667 Board Notification 83-31 forwards AZ Public Svc Co evaluation concluding that PORVs not warranted for Palo Verde NRC review of util evaluation incomplete.
EISENHUT, D. G. Division of Licensing 83/03/21 PALLADINO, N. J., GILINSKY, V., AHEARNE, J. Commissioners 9pp 17745.135 24X Fiche 50-000, 83/03/21, 8303290667.

8303310039 Forwards util 830309 ltr transmitting Vols 1-3, "Independent Design Review of Waterford Steam Electric Station Unit 3 Emergency Feedwater Sys Sys design adequate.
CARPENTER, F. D. Torrey Pines Technology 83/03/29 KNIGHTON, G. W. Licensing Branch 3 2pp 17759.182 24X Fiche 50-382, 83/03/29, 8303310039.

--8303310045 Forwards Vols 1-3, "Independent Design Review of Waterford Steam Electric Station Unit 3 Emergency Feedwater Sys," per 820826 meeting. Potential finding repts will be evaluated & corrective action plans will be processed & dispositioned.
MAURIN, L. V. Louisiana Power & Light Co. 83/03/09 KNIGHTON, G. W. Licensing Branch 3 2pp 17759.184 24X Fiche 50-382, 83/03/29, 8303310039.

--8303310053 Vols 1-3, "Independent Design Review of Waterford Steam Electric Station Unit 3 Emergency Feedwater Sys," consisting of executive summary, program results, potential finding repts & corrective action plans.
* Torrey Pines Technology GA-C16900 83/03/31 1,288pp 17759.187 24X Fiche 50-382, 83/03/29, 8303310039.

E NRC Safety Evaluation Report (SER), suppls & correspondence

8303210351 Advises that Tech Specs 3/4.9.7 will prohibit travel of heavy loads over fuel assemblies in storage pool. NUREG-0612 interim requirements per SER satisfied.
MAURIN, L. V. Louisiana Power & Light Co. 83/03/15 KNIGHTON, G. Licensing Branch 3 1p 17632.317 24X Fiche 50-382, 83/03/15, 8303210351.

8303210407 Submits updated plans for meeting requirements of NUREG-0660 Item I.A.1.2, "Shift Supervisors Requirements," per 820707 ltr re SER open items on licensee qualifications. FSAR will be updated accordingly.
MAURIN, L. V. Louisiana Power & Light Co. 83/03/15 KNIGHTON, G. W. Licensing Branch 3 2pp 17634.264 24X Fiche 50-382, 83/03/15, 8303210407.

8303280086 Forwards addendum to Dec 1982 response to Human Factors Engineering control room design review audit to complete SER review. Meters for containment pressure mislabeled.
MAURIN, L. V. Louisiana Power & Light Co. 83/03/22 KNIGHTON, G. Licensing Branch 3 12pp 17707.232 24X Fiche 50-382, 83/03/22, 8303280086.

8303290407 Forwards description of inadequate core cooling instrumentation, including evaluation of compliance w/ specific requirements of NUREG-0737, Item II.F.2, per SER. Info will be incorporated in Amend 32 to FSAR.
MAURIN, L. V. Louisiana Power & Light Co. 83/03/25 KNIGHTON, G. Licensing Branch 3 35pp 17725.176 24X Fiche 50-382, 83/03/25, 8303290407.

F Security, medical, emergency & fire protection plans

8303140282 Ack receipt of 820628 ltr re rev to "Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." Rev acceptable. Provisions of plan should be in effect whenever fresh fuel stored on site.
EVANS, L. J. Fuel Facility Safeguards Licensing Branch 82/11/26 MAURIN, L. V. Louisiana Power & Light Co. 1p 17547.356 24X Fiche 50-382, 82/11/26, 8303140282.

8303090302 Forwards info re fire protection & detection equipment installed at facility, in response to NRC concerns due to temporary lack of factory mutual approvals.
MAURIN, L. V. Louisiana Power & Light Co. 83/02/14 NOVAK, T. Assistant Director for Operating Reactors 8pp 17470.001 24X Fiche 50-382, 83/02/14, 8303090302.

--8303090310 "A888-M77 Acceptance Test Procedure."
* Allison Control, Inc. 79/02/20 104pp 17470.009 24X Fiche 50-382, 83/02/14, 8303090302.

--8303090318 Rev B to "Std Test Procedure 150 for Control Units." W/five oversize proprietary drawings. Drawings withheld (may contain company sensitive info). Aperture cards are available in Central Files.
KOLLMAR, S. Allison Control, Inc. 83/01/20 40pp 17470.113 24X Fiche 50-382, 83/02/14, 8303090302.

8303010220 Forwards IE Insp Rept 50-382/82-30 on 821201-31. No noncompliance noted.
MADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs 83/02/16 MAURIN, L. V. Louisiana Power & Light Co. 2pp 17332.001 24X Fiche 50-382, 83/02/16, 8303010220.

--8303010227 IE Insp Rept 50-382/82-30 on 821201-31. No noncompliance noted. Major areas inspected: previous insp findings, site evaluation, preoperational test procedure review, mgt meeting & Tech Spec review.
CONSTABLE, G. L., FLIPPO, T. A., CROSSMAN, W. A. Region 4, Office of Director 83/02/15 8pp 17332.003 24X Fiche 50-382, 83/02/16, 8303010220.

8303140240 Requests cooperation w/NRC in determining optimal locations for emergency notification sys & health physics network, per NUREG-0696, "Functional Criteria for Emergency Response Facilities."
COLLINS, J. T. Region 4, Office of Director 83/02/24 MAURIN, L. V. Louisiana Power & Light Co. 2pp 17539.010 24X Fiche 50-382, 83/02/24, 8303140240.

8303140582 Requests current hazardous chemical listing in FSAR be updated to include all significant quantities of hazardous chemicals near site.
NOVAK, T M. Assistant Director for Licensing 83/02/24 MAURIN, L V Louisiana Power & Light Co 3pp 17548 327 24X
Fiche: 50-382, 83/02/24, 8303140582

8303150199 Forwards IE Safeguards Insp Rept 50-382/82-22 on 820831-830103. No noncompliance noted.
MADSEN, G L. Division of Resident, Reactor Project & Engineering Programs 83/02/25 MAURIN, L V. Louisiana Power & Light Co 2pp 17556 121 24X Fiche: 50-382, 83/02/25, 8303150199

--8303150219 IE Safeguards Insp Rept 50-382/82-22 on 820831-830103. No noncompliance noted. Major areas inspected: safeguards info control activities by licensee & Ebasco. Details withheld (ref 10CFR73.21).
KELLY, J A ; BROWN, G D. Region 4, Office of Director 83/02/16 Ip 17556 123 24X Fiche: 50-382, 83/02/25, 8303150199

8303160521 Requests retraction of request that util disconnect fire water sys as source of lubricating & cooling water to circulating water pumps, based on reasons listed.
MAURIN, L V. Louisiana Power & Light Co 83/03/03 KNIGHTON, G Licensing Branch 3 3pp 17592 331 24X Fiche: 50-382, 83/03/03, 8303160521

8303180247 Informs that Rev 7 of physical security plan transmitted in 830221 ltr w/revised Figure 3-1, "Perimeter Road, Fence Perimeter, Intrusion Detectors & Closed Circuit TV Cameras," should be marked proprietary.
MAURIN, L V. Louisiana Power & Light Co 83/03/10 Office of Nuclear Reactor Regulation, Director 1p 17617 089 24X
Fiche: 50-382, 83/03/10, 8303180247

8303240514 Forwards Rev 2 to safeguards contingency plan. Rev withheld.
MAURIN, L V. Louisiana Power & Light Co 83/03/14 Office of Nuclear Reactor Regulation, Director 1p 17682 252 24X
Fiche: 50-382, 83/03/14, 8303240514

8303220004 Responds to NRC concerns raised at 830217 meeting re installation of fire protection envelope for Class 1E electrical cables & use of Insulco/HEMYC sys. HEMYC sys will provide 1-h fire protection envelope.
MAURIN, L V. Louisiana Power & Light Co 83/03/15 NOVAK, T M Assistant Director for Licensing 6pp 17652 113 24X
Fiche: 50-382, 83/03/15, 8303220004

8303290318 Discusses unauthorized & unacceptable telephonic inquiries by personnel recruiter re security sys info. Recruiter brushed Section 147 of Atomic Energy Act. Practice will not be tolerated. Preventative measures requested.
COLLINS, J T. Region 4, Office of Director 83/03/25 MAURIN, L V Louisiana Power & Light Co 2pp 17716 148 24X
Fiche: 50-382, 83/03/25, 8303290318

## O Adjudicatory correspondence

8303100248 Requests ASLB be allowed to visit plant on 830418. Visit should include tour of plant, including control room, emergency operating facility & radiological monitoring equipment.
TOMPKINS, B A. Atomic Safety and Licensing Appeal Panel 83/03/08
CHURCHILL, B W. Shaw, Pittman, Potts & Trowbridge. CHURCHILL, B W Louisiana Power & Light Co. 2pp 17488 361 24X
Fiche: 50-382, 83/03/08, 8303100248

8303100377 Order scheduling oral argument on joint intervenors Save Our Wetlands, Inc & Oystershell Alliance appeal from ASLB 821103 partial initial decision for 830419 in New Orleans, LA.
TOMPKINS, B A. Atomic Safety and Licensing Appeal Panel 83/03/08 2pp 17490 324 24X Fiche: 50-382, 83/03/08, 8303100377

8303100381 Order informing that Commission completed review of ASLB 821103 decision authorizing OL issuance & determined that no contested issues constitute grounds for delaying decision effectiveness.
CHILK, S J. Office of the Secretary of the Commission 83/03/08 2pp 17488 284 24X Fiche: 50-382, 83/03/08, 8303100381

8303170483 Motion to file brief amicus curiae per 10CFR2.715, re feed & bleed capability. Issue must be presented to ASLAB. Certificate of Svc encl.
LINDSEY, I D. Louisiana, State of 83/03/11 Atomic Safety and Licensing Appeal Panel 7pp 17610 126 24X Fiche: 50-382, 83/03/11, 8303170483

8303170423 Forwards proposed findings of fact, conclusions of law & brief in form of proposed partial initial decision on Joint Intervenors Contention 17/26(1)(a).
CHURCHILL, B W. Shaw, Pittman, Potts & Trowbridge. CHURCHILL, B W Louisiana Power & Light Co. 83/03/14 WOLFE, S J ; JORDAN, W H ; FOREMAN, H Atomic Safety and Licensing Board Panel 2pp 17605 008 24X Fiche: 50-382, 83/03/14, 8303170423

--8303170427 Proposed findings of fact, conclusions of law & brief in form of proposed partial initial decision on Joint Intervenors Contention 17/26(1)(a). Certificate of Svc encl.
CHURCHILL, B W. Shaw, Pittman, Potts & Trowbridge. CHURCHILL, B W Louisiana Power & Light Co. 83/03/14 76pp 17605 010 24X
Fiche: 50-382, 83/03/14, 8303170423

8303220238 Request for enlargement of 70-page limit on brief opposing Joint Intervenors exceptions. Sixty-one exceptions cannot be addressed in 70 pages. Certificate of Svc encl.
CHURCHILL, B W. Louisiana Power & Light Co. CHURCHILL, B W. Shaw, Pittman, Potts & Trowbridge. 83/03/18 Atomic Safety and Licensing Appeal Panel 5pp 17657 283 24X Fiche: 50-382, 83/03/18, 8303220238

8303250141 Response opposing State of LA 830311 motion for leave to file amicus curiae brief on issue of DHR capability. Motion untimely & no good cause shown. Issue abandoned by parties cannot be briefed. Certificate of Svc encl.
HAMLIN, J B. Louisiana Power & Light Co. HAMLIN, J B. Shaw, Pittman, Potts & Trowbridge. 83/03/22 Atomic Safety and Licensing Appeal Panel 10pp 17691 149 24X Fiche: 50-382, 83/03/22, 8303250141

8303250144 Trip rept of V Gilinsky 830309 site visit. Tour conducted & mgt meeting held.
JOOSTEN, J K. Commissioners. 83/03/23 Commissioners 4pp 17691 001 24X Fiche: 50-382, 83/03/23, 8303250144

8303290069 Brief opposing Joint Intervenors 821227 exceptions to ASLB 821102 Partial Initial Decision LBP-82-100. ASLB correctly resolved all contested issues. Certificate of Svc encl.
TURK, S E. Hearing Branch 1 83/03/25 Atomic Safety and Licensing Appeal Panel 75pp 17723 045 24X Fiche: 50-382, 83/03/25, 8303290069

8303290464 Brief in opposition to Joint Intervenors 821227 exceptions to ASLB 821103 partial initial decision. Exceptions either waived for failure to brief or are w/o merit. Certificate of Svc encl.
CHURCHILL, B W. Louisiana Power & Light Co. CHURCHILL, B W. Shaw, Pittman, Potts & Trowbridge. 83/03/25 Atomic Safety and Licensing Appeal Panel 102pp 17723 243 24X
Fiche: 50-382, 83/03/25, 8303290464

8303290489 Brief opposing Joint Intervenors exceptions to ASLB 831103 partial initial decision. ASLB correctly decided all contested issues. Certificate of Svc encl.
TURK, S E. Hearing Branch 1 83/03/25 Atomic Safety and Licensing Appeal Panel 68pp 17724 165 24X Fiche: 50-382, 83/03/25, 8303290489

8303290301 Requests notification of change in fuel load & commercial operation dates.
WOLFE, S J. Atomic Safety and Licensing Board Panel 83/03/28
HAMLIN, J B. Shaw, Pittman, Potts & Trowbridge. 1p 17716 162 24X
Fiche: 50-382, 83/03/28, 8303290301

8303290500 Advises that SE Turk will represent NRC at 830419 oral argument.
TURK, S E. Hearing Branch 1 83/03/28 TOMPKINS, B A. Atomic Safety and Licensing Appeal Panel 1p 17723 015 24X
Fiche: 50-382, 83/03/28, 8303290500

## O Advisory Committee on Reactor Safeguards reports & correspondence

8303100107 Forwards NRR response to ACRS recommendations following 271st & 272nd meetings, per 821208 & 830107 memos.
GOODWIN, E F. Technical Support Branch 83/02/15 FRALEY, R F. ACRS - Advisory Committee on Reactor Safeguards 5pp 17504 036 24X
Fiche: 50-000, 83/02/15, 8303100107

--8301180041 Forwards list of requests made at 272nd ACRS meeting on 821209-11 per agreement to provide summary of actions, agreements, assignments & requests made at each full ACRS meeting.
FRALEY, R F. ACRS - Advisory Committee on Reactor Safeguards. 83/01/05 DIRCKS, W J. Office of the Executive Director for Operations. 4pp 17504 041 24X Fiche: 50-000, 83/02/15, 8303100107

F Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl. EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24X Fiche 50-000, 83/02/16, 8302170082

G Inspection reports, IE Bulletins & correspondence

8303180418 Forwards IE Insp Rept 50-382/82-26 on 821018-20 No noncompliance noted, however six open items identified MADSEN, G L Region 4, Office of Director 82/12/07 MAURIN, L V Louisiana Power & Light Co 2pp 17622 047 24X Fiche 50-382, 82/12/07, 8303180418

--8303180421 IE Insp Rept 50-382/82-26 on 821018-20 No noncompliance noted Major areas inspected organization & administration, training & qualification, audits & radiological environ monitoring WILBORN, L , MURRAY, B Region 4, Office of Director 82/12/11 15pp 17622 049 24X Fiche 50-382, 82/12/07, 8303180418

8303010424 Forwards IE Insp Rept 50-382/83-06 on 830117-21 No noncompliance noted MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/10 MAURIN, L V Louisiana Power & Light Co 2pp 17343 150 24X Fiche 50-382, 83/02/10, 8303010424

--8303010427 IE Insp Rept 50-382/83-06 on 830117-21 No noncompliance noted Major areas inspected licensee action on previous insp findings, records for post-weld heat treatment of safety-related piping & QA/QC electrical procedures GILBERT, L D , MULLIKIN, R F , HUNNICUTT, D M Division of Resident, Reactor Project & Engineering Programs 83/02/04 7pp 17343 152 24X Fiche 50-382, 83/02/10, 8303010424

8303010220 Forwards IE Insp Rept 50-382/82-30 on 821201-31 No noncompliance noted MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/16 MAURIN, L V Louisiana Power & Light Co 2pp 17332 001 24X Fiche 50-382, 83/02/16, 8303010220

--8303010227 IE Insp Rept 50-382/82-30 on 821201-31 No noncompliance noted Major areas inspected previous insp findings, site evaluation, preoperational test procedure review, mgt meeting & Tech Spec review CONSTABLE, G L , FLIPPO, T A , CROSSMAN, W A Region 4, Office of Director 83/02/15 8pp 17332 003 24X Fiche 50-382, 83/02/16, 8303010220

8303110355 Board Notification 83-14 Forwards followup info on apparent deficiencies in Midland-Ross superstrut matl EISENHUT, D G Division of Licensing 83/02/18 PALLADINO, N Commissioners 24pp 17546 205 24X Fiche 50-000, 83/02/18, 8303110355

8212060367 IE Bulletin 83-01 "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 11lpp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367

8303150199 Forwards IE Safeguards Insp Rept 50-382/82-22 on 820831-830103 No noncompliance noted MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/25 MAURIN, L V Louisiana Power & Light Co 2pp 17556 121 24X Fiche 50-382, 83/02/25, 8303150199

--8303150219 IE Safeguards Insp Rept 50-382/82-22 on 820831-830103 No noncompliance noted Major areas inspected safeguards info control activities by licensee & Ebasco Details withheld (ref 10CFR73 21) KELLY, J A , BROWN, G D Region 4, Office of Director 83/02/16 1p 17556 123 24X Fiche 50-382, 83/02/25, 8303150199

8303080486 Responds to IE Info Notice 82-34, Rev 1 & NRC request for submittal addressing reliability of welds in main control panels Detailed weld insp & mapping conducted on hydrogen analyzer panel Structural evaluation underway MAURIN, L V Louisiana Power & Light Co 83/03/02 KNIGHTON, G W Licensing Branch 3 1p 17452 336 24X Fiche 50-382, 83/03/02, 8303080486

8303210624 Forwards IE Insp Rept 50-382/83-01 on 830101-31 No noncompliance noted MADSEN, G L Region 4, Office of Director 83/03/02 MAURIN, L V Louisiana Power & Light Co 2pp 17636 207 24X Fiche 50-382, 83/03/02, 8303210624

--8303210631 IE Insp Rept 50-382/83-01 on 830101-31 No noncompliance noted Major areas inspected preoperational test procedure review & witnessing, fuel receipt preparations, site tour & human factors walkdown CONSTABLE, G L , FLIPPO, T A , CROSSMAN, W A Region 4, Office of Director 83/02/28 5pp 17636 209 24X Fiche 50-382, 83/03/02, 8303210624

8303210650 Forwards IE Insp Rept 50-382/83-05 on 830103-28 No noncompliance noted MADSEN, G L Region 4, Office of Director 83/03/04 MAURIN, L V Louisiana Power & Light Co 2pp 17636 050 24X Fiche 50-382, 83/03/04, 8303210650

--8303210661 IE Insp Rept 50-382/83-05 on 830103-28 No noncompliance noted Major areas inspected welding QC & NDE programs KERCH, H W , HARRIS, R H , NARROW, L Region 4, Office of Director 83/02/14 11pp 17636 052 24X Fiche 50-382, 83/03/04, 8303210650

8303280247 Forwards IE Insp Rept 50-382/83-03 on 830110-14 & 24-28 No noncompliance noted MADSEN, G L Region 4, Office of Director 83/03/10 MAURIN, L V Louisiana Power & Light Co 2pp 17706 264 24X Fiche 50-382, 83/03/10, 8303280247

--8303280262 IE Insp Rept 50-382/83-03 on 830110-14 & 24-28 No noncompliance noted Major areas inspected followup on licensee identified items, site tour & installation of safety-related equipment MARTIN, L E , CROSSMAN, W A Region 4, Office of Director 83/03/09 12pp 17706 266 24X Fiche 50-382, 83/03/10, 8303280247

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc 117pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380

8303180298 EN-82-037A on 830316, order imposing civil penalty in amount of $20,000 issued Penalty based on violation of QA requirements illustrated by numerous deficiencies & discrepancies in as-built condition of sys KLINGLER, G , AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/03/16 1p 17616 180 24X Fiche 50-382, 83/03/16, 8303180298

8303210604 Ack receipt of 830223 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-382/82-27 MADSEN, G L Region 4, Office of Director 83/03/16 MAURIN, L V Louisiana Power & Light Co 1p 17636 317 24X Fiche 50-382, 83/03/16, 8303210604

--8303210610 Responds to NRC 830118 ltr re violations noted in IE Insp Rept 50-382/82-27 Corrective actions Procedure SIT-TP-125 successfully completed for steam generators 1 & 2 Procedures carefully reviewed prior to performance MAURIN, L V Louisiana Power & Light Co 83/02/23 MADSEN, G L Region 4, Office of Director 4pp 17636 318 24X Fiche 50-382, 83/03/16, 8303210604

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 121pp 17774 352 24X Fiche 50-000, 83/03/21, 8212060387

R Periodic operating reports & related correspondence

8303160285 Forwards monthly rept for Feb 1983 re recruiting & upgrading of total corporate capability Encls provide staffing status of nuclear organization as of 830215 & status of commitments made in 810420 ltr MAURIN, L V Louisiana Power & Light Co 83/03/03 WILSON, J NRC - No Detailed Affiliation Given 3pp 17596 258 24X Fiche 50-382, 83/03/03, 8303160285

S Reportable occurrences, LERs & related correspondence

8303080298 Final Potentially Reportable Deficiency Rept 99 re Magnetrol Model LDN level switch design Level switches not Class IE devices & not required for safe shutdown Condition not reportable per 10CFR50 55e MAURIN, L V Louisiana Power & Light Co 83/02/28 COLLINS, J T Region 4, Office of Director 1p 17449 320 24X Fiche 50-382, 83/02/28, 8303080293

8303080455 Final Significant Const Deficiency Rept 48,R-1 re design application of break flanges at elevated temps Forty-five flanges w/Type 316 SS matl replaced & installed bolts replaced w/high strength bolts for addl 21 flanges MAURIN,L V Louisiana Power & Light Co 83/02/28 COLLINS,J T Region 4, Office of Director 3pp 17453:298 24X Fiche 50-382,83/02/28,8303080455

8303080195 First interim Significant Const Deficiency Rept 69 re Crosby Valve & Gage Co stellite alloy 6B discs Discs will be replaced w/certified matl Next rept will be submitted by 830510 MAURIN,L V Louisiana Power & Light Co 83/03/01 COLLINS,J T Region 4, Office of Director 2pp 17457:322 24X Fiche 50-382,83/03/01,8303080195

8303080461 Final Significant Const Deficiency Rept 61 re linear crack in SA213 stainless steel tubing Initially reported on 820831 Defects result of processing rather than metallurgical composition Vendor QA program improved MAURIN,L V Louisiana Power & Light Co 83/03/01 COLLINS,J T Region 4, Office of Director 8pp 17453:113 24X Fiche 50-382,83/03/01,8303080461

8303150620 Board Notification 83-26 forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys Info may affect conclusions re probability of/corrective measures for ATWS EISENHUT,D G Division of Licensing 83/03/03 PALLADINO,N Commissioners 24pp 17584:097 24X Fiche 50-000,83/03/03, 8303150620

8303210556 Interim deficiency rept re chilled water piping supports Two hangers remain to be reworked in chilled water sys but cannot be reworked at present time due to preoperational testing Final rept due on 830510 MAURIN,L V Louisiana Power & Light Co 83/03/07 COLLINS,J T Region 4, Office of Director 1p 17632:311 24X Fiche 50-382,83/03/07,8303210556

8303210569 Interim deficiency rept re inadequate review of condition identification & work authorization forms for reportability QA group screening forms for reportability Possibly 10,000 forms may require screening Next rept by 830510 MAURIN,L V Louisiana Power & Light Co 83/03/15 COLLINS,J T Region 4, Office of Director 3pp 17632:269 24X Fiche 50-382,83/03/15,8303210569

8303280121 Fifth interim Significant Const Deficiency Rept 54 re tube steel (HT 16600) laminations Initially reported on 830217 Corrective action mods & review expected to be completed by 830506 Final rept expected by 830516 MAURIN,L V Louisiana Power & Light Co 83/03/21 COLLINS,J T Region 4, Office of Director 1p 17709:362 24X Fiche 50-382,83/03/21,8303280121

8303280124 First interim Significant Const Deficiency Rept 70 re GE 480-volt SG trip coils not dropping out after tripping Initially reported on 830218 Nonconformance Rept W3-5737 intitiated to implement corrective action Next rept 830510 MAURIN,L V Louisiana Power & Light Co 83/03/21 COLLINS,J T Region 4, Office of Director 2pp 17706:350 24X Fiche 50-382,83/03/21,8303280124

8303280179 Final Significant Deficiency Rept 62 re undersize welds on 1/2-inch Schedule 160 pipe Welds reworked & reinspected by Mercury Co Welding insp program upgraded to preclude recurrence MAURIN,L V Louisiana Power & Light Co 83/03/21 COLLINS,J T Region 4, Office of Director 2pp 17706:316 24X Fiche 50-382,83/03/21,8303280179

8303280186 Interim Significant Const Deficiency Rept 72 re radiation monitoring sys RM-23 control modules Initially reported on 830302 GA Technologies modifying RM-23s Also reportable per Part 21 Next rept by 830510 MAURIN,L V Louisiana Power & Light Co 83/03/21 COLLINS,J T Region 4, Office of Director 2pp 17709:185 24X Fiche 50-382,83/03/21,8303280186

f. Hearing transcripts on non-antitrust matters

8303220280 Proposed corrections to 830208-11 evidentiary hearing transcript Certificate of Svc encl CHURCHILL,B W Louisiana Power & Light Co CHURCHILL,B W Shaw, Pittman, Potts & Trowbridge 83/03/18 7pp 17656:191 24X Fiche 50-382,83/03/18,8303220280

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl EISENHUT,D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000,83/02/24, 8302250505

DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

A. Application/construction stage documents & correspondence

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl EISENHUT,D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700:303 24X Fiche 50-000,83/03/02,8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl EISENHUT,D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 5lpp 17660:176 24X Fiche 50-000,83/03/07,8303040005

F. Security, medical, emergency & fire protection plans

8303070065 Responds to emergency preparedness Licensing Conditions 2.C.(20)(a),(b) & (c) Potassium iodide supplies adequate. CDV-742 (0-200R) self-reading dosimeters will be supplied to emergency workers & emergency response plans revised CURTIS,N W Pennsylvania Power & Light Co 83/02/28 SCHWENCER,A Licensing Branch 2 1p 17435:249 24X Fiche 50-387,83/02/28, 8303070065

--8303070072 "Transfer of CD V-730 Dosimeters From TMI Risk Counties to Susquehanna Steam Electric Station Risk Counties," interim procedure BELSER,A L Pennsylvania, Commonwealth of, 83/02/24 3pp 17435:250 24X Fiche 50-387,83/02/28,8303070065

8303280063 Forwards response to 830106 request for addl info re low level radwaste holding facility CURTIS,N W Pennsylvania Power & Light Co 83/03/01 ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 9pp 17726:322 24X Fiche 50-387,83/03/01,8303280063

8303110270 Responds to NRC request for info on emergency operations facility (EOF). No interim primary or backup EOFs implemented. Response to Generic Ltr 81-10 transmitted on 810402. CURTIS,N W Pennsylvania Power & Light Co 83/03/07 SCHWENCER,A Licensing Branch 2 1p 17517:351 24X Fiche 50-387,83/03/07, 8303110270

8303290542 Releases public version of revised emergency plan implementing procedure. FELTON,J M Division of Rules and Records 83/03/21 Document Management Branch 1p 17742:218 24X Fiche 50-387,83/03/21, 8303290542

--8303290547 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-041, "Fire Emergencies." * Pennsylvania Power & Light Co 83/03/02 NRC - No Detailed Affiliation Given 1p 17742:219 24X Fiche 50-387,83/03/21, 8303290542

--8303290548 Public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-041, "Fire Emergencies." Revised index encl * Pennsylvania Power & Light Co 83/02/28 13pp 17742:220 24X Fiche 50-387,83/03/21,8303290542

8303280020 Informs that Change N to physical security plan, originally scheduled for Feb 1983 submittal, will be provided by Apr 1983. CURTIS,N W Pennsylvania Power & Light Co 83/03/23 SCHWENCER,A Licensing Branch 2 1p 17707:312 24X Fiche 50-387,83/03/23, 8303280020

8303310009 Releases public version of rev to emergency plan implementing procedure. FELTON,J M Division of Rules and Records 83/03/28 Document Management Branch 1p 17780:240 24X Fiche 50-387,83/03/28, 8303310009

--8303310010 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-014, "Personnel & Vehicle Contamination Surveys." Receipt form encl.
* Pennsylvania Power & Light Co. 83/02/24 SCHWENCER, A. NRC - No Detailed Affiliation Given 1p 17780:241 24X Fiche 50-387, 83/03/28, 8303310009.

--8303310011 Public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-014, "Personnel & Vehicle Contamination Surveys."
* Pennsylvania Power & Light Co. 83/02/24 11pp 17780:242 24X Fiche 50-387, 83/03/28, 8303310009.

H General correspondence

8303030176 Responds to B30120 ltr commenting on inadequacy of radiological emergency response planning for communities surrounding facility. Ltr forwarded to FEMA & PA Emergency Mgt Agency for further response.
HAYNES, R. C. Region 1, Office of Director 83/02/09 NEMETHY, E. Affiliation Unknown 5pp 17365:256 24X Fiche 50-387, 83/02/09, 8303030176.

--8303030191 Comments on inadequacy of radiological emergency response planning for areas surrounding facility.
NEMETHY, E. Affiliation Unknown 83/01/20 ASSELSTINE, J. Commissioners 5pp 17365:260 24X Fiche 50-387, 83/02/09, 8303030176.

8303180543 Comments on Resolution 36159 re leakage of radioactive water at facility. NRC regulations for design & operation of nuclear power plants adequate to protect public health & safety.
HAYNES, R. C. Region 1, Office of Director 83/03/11 BRACE, W. G. Wilkes-Barre, PA 2pp 17754:015 24X Fiche 50-387, 83/03/11, 8303180543.

8303180543 Comments on Resolution 36159 re leakage of radioactive water at facility. NRC regulations for design & operation of nuclear power plants adequate to protect public health & safety.
HAYNES, R. C. Region 1, Office of Director 83/03/11 BRACE, W. G. Wilkes-Barre, PA 2pp 17754:015 24X Fiche 50-387, 83/03/11, 8303180543.

--8303300129 Forwards City of Wilkes-Barre, PA resolution re recent radioactive water leakage for reply.
HAYNES, R. C. Region 1, Office of Director 83/02/11 REHM, T. A. Office of the Executive Director for Operations 2pp 17754:011 24X Fiche 50-387, 83/03/11, 8303180543.

I Financial information

8303210332 Forwards Annual Financial Rept 1982.
CURTIS, N. W. Pennsylvania Power & Light Co. 83/03/16 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 17632:063 24X Fiche 50-387, 83/03/16, 8303210332.

--8303210333 Annual Financial Rept 1982.
CAMPBELL, R. K. Pennsylvania Power & Light Co. 83/03/01 51pp 17632:064 24X Fiche 50-387, 83/03/16, 8303210332.

P Operating license stage documents & correspondence

8208060366 Board Notification 82-70 notifies of differing prof opinion re sensitization of BWR stainless steel weldments.
EISENHUT, D. G. Division of Licensing 82/07/20 PALLADINO, N. J. Commissioners 4pp 17043:001 24X Fiche 50-000, 82/07/20, 8208060366.

--8104230100 Presents differing professional opinion re Reg Guide 1.44, "Control of Use of Sensitized Stainless Steels." Issue recommended to be identified in BWR SER inputs as open item subj to development of more definitive guidance.
HALAPATZ, J. Materials Engineering Branch 81/04/07 PAULICKI, S. S. Materials Engineering Branch 2pp 17043:004 24X Fiche 50-387, 82/07/20, 8208060366.

--8104230095 Discusses differing professional opinion re Reg Guide 1.44, "Control of Use of Sensitized Stainless Stains," presented in encl 8104090 memo. Revision of subj guide to reflect NUREG-0313 recommendations suggested.
PAULICKI, S. S. Office of Management and Program Analysis 81/04/14 VOLLMER, R. H. Division of Engineering 1p 17043:006 24X Fiche 50-387, 82/07/20, 8208060366.

--8103310185 Discusses compliance w/NUREG-0313, Revision 1, for BWR OL & CP reviews. Input to SER re issue encl.
NOONAN, V. S. Assistant Director for Matls & Qualif Engineering (Pre 830201) 81/02/18 TEDESCO, R. L. Assistant Director for Licensing 2pp 17043:014 24X Fiche 50-387, 82/07/20, 8208060366.

--8108050060 Responds to B10414 & 07 memos re stress corrosion cracking of stainless steel weldments in BWR environs. J. Halapatz assigned responsibility for reviewing aspects of GE welding procedures.
VOLLMER, R. H. Division of Engineering 83/06/26 HALAPATZ, J. Materials Engineering Branch 1p 17043:016 24X Fiche 50-387, 82/07/20, 8208060366.

--8302040541 Outlines plans to develop definitive info to characterize metallurgically, propensity for intergranular stress corrosion cracking of BWR austenitic stainless steel weldments.
HALAPATZ, J. Materials Engineering Branch 81/07/06 VOLLMER, R. H. Division of Engineering 2pp 17043:017 24X Fiche 50-387, 82/07/20, 8208060366.

--8108240174 Comments on differing prof opinion re sensitization of BWR stainless steel weldments. Insp programs on BWR internals includes spray lines, feedwater spargers & jet pump components.
HAZELTON, W. S. Materials Engineering Branch 81/07/31 VOLLMER, R. H. Division of Engineering 2pp 17043:019 24X Fiche 50-387, 82/07/20, 8208060366.

--8302040546 Provides statement of record, per NRC App 4125 re differing prof opinion on generic sensitization of BWR stainless steel weldments.
HALAPATZ, J. Materials Engineering Branch 81/08/05 VOLLMER, R. H. Division of Engineering 56pp 17043:021 24X Fiche 50-387, 82/07/20, 8208060366.

--8302040548 Requests author be informed when dates of visit to GE established re differing prof opinion on sensitization of BWR stainless steel weldments.
VOLLMER, R. H. Division of Engineering 82/03/08 HALAPATZ, J. NRC - No Detailed Affiliation Given 1p 17043:081 24X Fiche 50-387, 82/07/20, 8208060366.

--8302040551 Provides update of current status of differing prof opinion re sensitization of BWR stainless steel weldments.
HALAPATZ, J. Division of Engineering 82/03/16 VOLLMER, R. H. Division of Engineering 2pp 17043:082 24X Fiche 50-387, 82/07/20, 8208060366.

--8302040555 Accepts alternative proposal of requesting fabrication procedure for two BWR OLs to resolve differing prof opinion re sensitization of BWR stainless steel weldments.
VOLLMER, R. H. Division of Engineering 82/04/30 HALAPATZ, J. Materials Engineering Branch 1p 17043:084 24X Fiche 50-387, 82/07/20, 8208060366.

--8302040557 Forwards planned implementation of alternative plan to resolve differing prof opinion re sensitization of BWR stainless steel weldments W/o encl.
HALAPATZ, J. Materials Engineering Branch 82/05/14 VOLLMER, R. H. Division of Engineering 4pp 17043:085 24X Fiche 50-387, 82/07/20, 8208060366.

8302280091 Forwards 171 oversize revised drawings per Reg Guide 1.70 Marked-up FSAR Table 1.7-1 encl. Aperture cards are available in PDR.
CODDINGTON, C. T. Pennsylvania Power & Light Co. 83/02/11 Commissioners 12pp 17306:090 24X Fiche 50-387, 83/02/11, 8302280091.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X Fiche 50-000, 83/02/16, 8302170082.

8303030599 Notifies that review of design & analysis of Category III anchors completed. Commitments of FSAR complied w/ based on results of independent design review & anchor reconciliation program.
LANDERS, D. F. Teledyne Engineering Services 83/02/16 SCHWENCER, A. Licensing Branch 2 3pp 17409:039 24X Fiche 50-387, 83/02/16, 8303030599.

8303010332 Informs that contingent upon NRC approval of BWR Owners Group Rev 3 to emergency procedure guidelines, util will incorporate portions dealing w/secondary containment control into facility emergency operating procedures.
CURTIS, N. W. Pennsylvania Power & Light Co. 83/02/18 SCHWENCER, A. Licensing Branch 2 1p 17345:129 24X Fiche 50-387, 83/02/18, 8303010332.

8303020460 Approves util 821217 position re seismic & dynamic qualification review & audit; pending review of listed items. Addl info re differences between Unit 1 & 2 equipment required.
SCHWENCER, A Licensing Branch 2 83/02/23 CURTIS, N W
Pennsylvania Power & Light Co 3pp 17357 210 24x
Fiche 50-387, 83/02/23, 8303020460

8303020454 Forwards Amend 11 to License NPF-14, safety evaluation & notice of issuance & availability. Amend revises Tech Specs in response to Generic Ltrs 82-17 & 82-23.
SCHWENCER, A Licensing Branch 2 83/02/24 CURTIS, N W
Pennsylvania Power & Light Co 2pp 17357 215 24x
Fiche 50-387, 83/02/24, 8303020454

--8303020461 Amend 11 to License NPF-14, revising Tech Specs in response to Generic Ltrs 82-17 & 82-23.
SCHWENCER, A Licensing Branch 2 83/02/24 9pp 17357 217 24x
Fiche 50-387, 83/02/24, 8303020454

--8303020466 Safety evaluation supporting Amend 11 to License NPF-14.
* Office of Nuclear Reactor Regulation, Director 83/02/24 2pp
17357 226 24x Fiche 50-387, 83/02/24, 8303020454

--8303020469 Notice of issuance & availability of Amend 11 to License NPF-14.
SCHWENCER, A Licensing Branch 2 83/02/24 4pp 17357 228 24x
Fiche 50-387, 83/02/24, 8303020454

8303040405 Submits response to License Condition 2.C.(13), describing permanent mods which limit flow in 12-inch gas pipeline near facility, w/three oversize drawings. Aperture cards are available in PDR.
CURTIS, N W Pennsylvania Power & Light Co 83/02/25 SCHWENCER, A
Licensing Branch 2 2pp 17420 069 24X Fiche 50-387, 83/02/25,
8303040405

8303090700 Advises that Amend 7 to License NPF-14 includes requirement re Nuclear Waste Policy Act of 1982 (PL97-425). Agreement re high level radwaste & spent nuclear fuel must be reached w/DOE by 830501.
SCHWENCER, A Licensing Branch 2 83/02/25 CURTIS, N W
Pennsylvania Power & Light Co 2pp 17480 218 24X
Fiche 50-387, 83/02/25, 8303090700

8303070080 Forwards Rev 2 to "Susquehanna Steam Electric Station, Units 1 & 2, Dynamic Qualification," for recirculation discharge gate valve assemblies HV-1F031 A & B, including Limitorque actuator installation.
CURTIS, N W Pennsylvania Power & Light Co 83/02/28 SCHWENCER, A
Licensing Branch 2 1p 17435 149 24X Fiche 50-387, 83/02/28,
8303070080

--8303070089 Rev 2 to "Susquehanna Steam Electric Station, Units 1 & 2, Dynamic Qualification."
LE, H General Electric Co NR1-831-F031 R02 83/01/24 24pp
17435 150 24X Fiche 50-387, 83/02/28, 8303070080

8303070097 Advises that final response to Humphrey Issue 3 will be submitted by 830601.
CURTIS, N W Pennsylvania Power & Light Co 83/02/28 SCHWENCER, A
Licensing Branch 2 1p 17435 276 24X Fiche 50-387, 83/02/28,
8303070097

8303090234 Forwards 223 oversize drawings, per Reg Guide 1.70. Drawing list encl. Aperture cards are available in PDR.
MOLCHANY, W J Pennsylvania Power & Light Co 83/03/01
SCHWENCER, A Licensing Branch 2 11pp 17471 107 24X
Fiche 50-387, 83/03/01, 8303090234

8303140458 Forwards Rev 8 to nonproprietary "Design Assessment Rept."
CURTIS, N W Pennsylvania Power & Light Co 83/03/07 SCHWENCER, A
Licensing Branch 2 2pp 17543 021 24X Fiche 50-387, 83/03/07,
8303140458

--8303140464 Rev 8 to nonproprietary "Design Assessment Rept."
* Pennsylvania Power & Light Co 83/02/28 274pp 17543 023
24X Fiche 50-387, 83/03/07, 8303140458

8303140237 Informs of change to startup test program described in Section 14.2 of FSAR. Venting & purging portion of ST 37 will be performed during Test Condition 6 in order to facilitate testing schedule.
CURTIS, N W Pennsylvania Power & Light Co 83/03/09 SCHWENCER, A
Licensing Branch 2 1p 17539 025 24X Fiche 50-387, 83/03/09,
8303140237

8303180164 Forwards Amend 12 to License NPF-14, safety evaluation & notice of issuance & availability. Amend modifies license condition re qualification & operation of containment vent & purge valves.
EISENHUT, D G Division of Licensing 83/03/09 CURTIS, N W
Pennsylvania Power & Light Co 2pp 17625 351 24z
Fiche 50-387, 83/03/09, 8303180164

--8303180190 Amend 12 to License NPF-14, modifying license condition re qualification & operation of containment vent & purge valves.
EISENHUT, D G Division of Licensing 83/03/09 2pp 17625 353
24x Fiche 50-387, 83/03/09, 8303180164

--8303180195 Safety evaluation supporting Amend 12 to License NPF-14.
* Office of Nuclear Reactor Regulation, Director 83/03/09 3pp
17625 355 24x Fiche 50-387, 83/03/09, 8303180164

--8303180198 Notice of issuance & availability of Amend 12 to License NPF-14.
SCHWENCER, A Licensing Branch 2 83/03/09 3pp 17625 358 24x
Fiche 50-387, 83/03/09, 8303180164

8303230339 Responds to 821210 request for exemption from 10CFR50.44 requirements. Based on installation of operable inerting sys, which conforms w/10CFR50.44(c)(3)(ii), requested exemption not necessary.
EISENHUT, D G Division of Licensing 83/03/10 CURTIS, N W
Pennsylvania Power & Light Co 3pp 17675 017 24X
Fiche 50-387, 83/03/10, 8303230339

8303160281 Forwards application for Amend 21 to License NPF-14 proposing changes to App A Tech Specs re typographical & administrative errors in radiological release specs Class III license fee encl.
CURTIS, N W Pennsylvania Power & Light Co 83/03/11 SCHWENCER, A
Licensing Branch 2 2pp 17596 261 24X Fiche 50-387, 83/03/11,
8303160281

--8303160289 Application for Amend 21 to License NPF-14, proposing changes to App A Tech Specs re typographical & administrative errors in radiological release specs.
CURTIS, N W Pennsylvania Power & Light Co 83/03/11 1p
17596 263 24X Fiche 50-387, 83/03/11, 8303160281

--8303160297 Proposed App A Tech Specs re typographical & administrative errors in radiological release specs.
* Pennsylvania Power & Light Co 83/03/11 13pp 17596 264
24X Fiche 50-387, 83/03/11, 8303160281

8303170524 Requests one-time exemption from performing integrated leak rate test on containment penetrations X246A & X246B after LLRT on RHR relief valves. Exemption requested by 830321 to support next outage schedule.
CURTIS, N W Pennsylvania Power & Light Co 83/03/14 SCHWENCER, A
Licensing Branch 2 7pp 17611 009 24X Fiche 50-387, 83/03/14,
8303170524

8303230097 Requests info re determination of effect operation & maint may have on Archaeological Sites SES-3, SES-6, SES-8 & SES-11, per 830303 telcon. Info should be developed following steps presented in 36CFR800.3 & 800.4.
SCHWENCER, A Licensing Branch 2 83/03/15 CURTIS, N W
Pennsylvania Power & Light Co 2pp 17687 174 24X
Fiche 50-387, 83/03/15, 8303230097

8303220177 Discusses final results of addl test of adequacy of design process Audit to verify test results confirms design adequacy.
CURTIS, N W Pennsylvania Power & Light Co 83/03/16 NOVAK, T
Assistant Director for Licensing 2pp 17657 120 24X
Fiche 50-387, 83/03/16, 8303220177

8303220329 Discusses results of analysis of proposed Transcontinental Gas Pipe Line Corp natural gas pipeline installation. Resulting plumes would be above highest air intakes, therefore pose no impact to facility operation.
CURTIS, N W Pennsylvania Power & Light Co 83/03/17 SCHWENCER, A
Licensing Branch 2 5pp 17656 148 24X Fiche 50-387, 83/03/17,
8303220329

8303220276 Forwards "Susquehanna Post-Accident Airborne & Plateout Dose Calculation For Equipment Qualification per NUREG-0588," supporting Rev 31 to FSAR.
CURTIS, N W Pennsylvania Power & Light Co 83/03/18 SCHWENCER, A
Licensing Branch 2 1p 17656 198 24X Fiche 50-387, 83/03/18,
8303220276

--8303220283 "Susquehanna Post-Accident Airborne & Plateout Dose Calculation for Equipment Qualification per NUREG-0588."
* Pennsylvania Power & Light Co 82/07/28 12pp 17656 199
24X Fiche 50-387, 83/03/18, 8303220276

8303280162 Forwards rev to NPDES Permit PA-0027448 re sewage treatment
CURTIS,N.W. Pennsylvania Power & Light Co. 83/03/22 SCHWENCER,A.
Licensing Branch 2 20pp. 17708.001 24X Fiche 50-387,83/03/22,
8303280162.

G. Inspection reports, IE Bulletins & correspondence

8303100297 Forwards IE Insp Rept 50-387/83-02 on 830117-21 & notice
of violation.
MARTIN,T.T. Division of Engineering & Technical Programs 83/02/24
KENYON,B.D. Pennsylvania Power & Light Co. 2pp. 17489.286 24X
Fiche 50-387,83/02/24,8303100297.

--8303100300 Notice of violation from insp on 830117-21.
Region 1, Office of Director 83/02/24 2pp. 17489.288 24X
Fiche 50-387,83/02/24,8303100297.

--8303100307 IE Insp Rept 50-387/83-02 on 830117-21 Noncompliance noted:
failure to determine low level dose for 24-h iodine &
particulate samples,to keep log for gamma spectrometry sys &
to approve contractor procedures prior to implementation.
JANG,J.C.; PASCIAK,W.J. Region 1, Office of Director 83/02/22
5pp. 17489.290 24X Fiche 50-387,83/02/24,8303100297.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers
(Westinghouse DB-50) to Open on Automatic Trip Signal." Svc
list encl.
DEYOUNG,R.C. Director's Office, Office of Inspection and
Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc.
111pp. 17521.001 24X Fiche 50-000,83/02/25,8212060367.

8303040359 Summary of 830125-27 meetings w/util & General Physics Corp
re pump & valve inservice test program (inservice insp
program).
PERCH,R.L. Licensing Branch 2 83/02/25 Licensing Branch 2
15pp. 17426.304 24X Fiche 50-387,83/02/25,8303040359.

8303080474 Supplis relief requests from preservice insp requirements.
Request for review determined Class III.
CURTIS,N.W. Pennsylvania Power & Light Co. 83/03/03 SCHWENCER,A.
Licensing Branch 2 28pp. 17453.153 24X Fiche 50-387,83/03/03,
8303080474.

8303240360 Forwards IE Insp Rept 50-387/82-44 on 821223-830121 No
noncompliance noted.
MARTIN,T.T. Division of Engineering & Technical Programs 83/03/09
KENYON,B.D. Pennsylvania Power & Light Co. 2pp. 17682.031 24X
Fiche 50-387,83/03/09,8303240360.

--8303240363 IE Insp Rept 50-387/82-44 on 821223-830121 No noncompliance
noted.Major areas inspected:actions on previous insp
findings;administrative controls of startup testing;
resolution of test exception repts & plant tour.
PLISCO,L.; PULLANI,S.; CHUNG,J.W. Region 1, Office of Director
83/03/04 16pp. 17682.033 24X Fiche 50-387,83/03/09,8303240360.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of
Reactor Trip Breakers." Svc list encl.
DEYOUNG,R.C. Director's Office, Office of Inspection and
Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc.
117pp. 17611.070 24X Fiche 50-000,83/03/11,8212060380.

8303280219 Forwards IE Insp Repts 50-387/83-03 & 50-388/83-01 on
830112-0308 Violations will be addressed in separate
enforcement action.
STAROSTECKI,R. Division of Project & Resident Programs 83/03/14
KENYON,B.D. Pennsylvania Power & Light Co. 2pp. 17708.025 24X
Fiche 50-387,83/03/14,8303280219.

--8303280231 IE Insp Repts 50-387/83-03 & 50-388/83-01 on 830112-0308.
Noncompliance noted:standby gas treatment sys improperly
tagged out,leading to inoperability.
RHOADS,G.; MCCANN,J. Region 1, Office of Director MCCABE,E.C.
Division of Project & Resident Programs 83/03/14 20pp.
17708.027 24X Fiche 50-387,83/03/14,8303280219.

8303180461 Confirms 830315 arrangements re 830317 enforcement
conference concerning recent operation of facility in excess
of Tech Spec limiting condition for operation for standby
gas treament sys,per IE Insp Rept 50-387/83-03.
STAROSTECKI,R. Division of Project & Resident Programs 83/03/15
KENYON,B.D. Pennsylvania Power & Light Co. 2pp. 17621.255 24X
Fiche 50-387,83/03/15,8303180461.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/18 Consolidated Edison Co. of New
York, Inc. 117pp. 24X Fiche 50-000,83/03/18,8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-
Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/21 Consolidated Edison Co. of New
York, Inc. 121pp. 17774.352 24X Fiche 50-000,83/03/21,8212060387.

R. Periodic operating reports & related correspondence

8303080400 Forwards monthly operating rept for Dec 1982.
KENYON,B.D. Pennsylvania Power & Light Co. 83/01/14 BEEBE,M.R.
Management Information Branch 1p. 17454.026 24X
Fiche 50-387,83/01/14,8303080400.

--8303080403 Monthly operating rept for Dec 1982.
KUCZYNSKI,L.A. Pennsylvania Power & Light Co. 83/01/10 4pp.
17454.027 24X Fiche 50-387,83/01/14,8303080400.

8303150485 Forwards monthly operating rept for Jan 1983.
KENYON,B.D. Pennsylvania Power & Light Co. 83/02/14 BEEBE,M.R.
Management Information Branch 1p. 17560.263 24X
Fiche 50-387,83/02/14,8303150485.

--8303150487 Monthly operating rept for Jan 1983.
KUCZYNSKI,L.A. Pennsylvaria Power & Light Co. 83/02/04 4pp.
17560.264 24X Fiche 50-387,83/02/14,8303150485.

8303140474 Forwards "Susquehanna Steam Electric Station Semiannual
Effluent & Waste Disposal Rept,Sept-Dec 1982."
KENYON,B.D. Pennsylvania Power & Light Co. 83/03/01 HAYNES,R.C.
Region 1, Office of Director 1p. 17541.066 24X
Fiche 50-387,83/03/01,8303140474.

--8303140485 "Susquehanna Steam Electric Station Semiannual Effluent &
Waste Disposal Rept,Sept-Dec 1982."
WIDNER,T.E.; SHANK,R.E.; MILLER,D.W. Pennsylvania Power & Light
Co. 83/02/28 107pp. 17541.067 24X Fiche 50-387,83/03/01,
8303140474.

S. Reportable occurrences, LERs & related correspondence

8303010561 Forwards LER 83-014/03L-0.
KEISER,H.W. Pennsylvania Power & Light Co. 83/02/18 HAYNES,R.C.
Region 1, Office of Director 1p. 17337.182 24X
Fiche 50-387,83/02/18,8303010561.

--8303010567 LER 83-014/03L-0 on 830119,during startup test program,
recirculation pump A motor generator set tripped.Caused by
overload in dc relay heater in exciter field circuit.
Investigation will be performed after data collected.
KUCZYNSKI,L.A. Pennsylvania Power & Light Co. 83/02/18 Region
1, Office of Director 2pp. 17337.183 24X Fiche 50-387,
83/02/18,8303010561.

8303010651 Forwards LER 83-015/03L-0.
KEISER,H.W. Pennsylvania Power & Light Co. 83/02/18 HAYNES,R.C.
Region 1, Office of Director 1p. 17336.231 24X
Fiche 50-387,83/02/18,8303010651.

--8303010659 LER 83-015/03L-0 on 830121,control rod 34-51 could not be
withdrawn during normal startup.Cause not stated.Control
rod freed using higher drive water pressures.
THOMPSON,D.J. Pennsylvania Power & Light Co. 83/02/18 Region
1, Office of Director 1p. 17336.232 24X Fiche 50-387,83/02/18,
8303010651.

8303010611 Forwards LER 83-010/01T-0.
KEISER,H.W. Pennsylvania Power & Light Co. 83/02/22 HAYNES,R.C.
Region 1, Office of Director 1p. 17336.011 24X
Fiche 50-387,83/02/22,8303010611.

--8303010620 LER 83-010/01T-0 on 830208,during startup test,total runout
flow on feedwater pumps in excess of assumed value in FSAR.
Caused by changes in plant parameters.Stop settings reset.
KUCZYNSKI,L.A. Pennsylvania Power & Light Co. 83/02/22 Region
1, Office of Director 2pp. 17336.012 24X Fiche 50-387,
83/02/22,8303010611.

8303010637 Correction to interim deficiency rept re potentially
defective GE HMA relays.Recorded date for Ltr PLA-1528 is
830218.
CURTIS,N.W. Pennsylvania Power & Light Co. 83/02/23 HAYNES,R.C.
Region 1, Office of Director 2pp. 17336.134 24X
Fiche 50-387,83/02/23,8303010637.

8303080002 Forwards LER 83-016/03L-0.Detailed event analysis encl.
KEISER,H.W. Pennsylvania Power & Light Co. 83/02/24 HAYNES,R.C.
Region 1, Office of Director 2pp. 17454.343 24X
Fiche 50-387,83/02/24,8303080002.

--8303080007 LER 83-016/03L-0 on 830125 during startup test two instances of excessive feedwater & reactor water conductivity & pH experienced Caused by water containing organic substance entering chamber Procedures being developed
KUCZYNSKI,L A Pennsylvania Power & Light Co 83/02/24 Region 1 Office of Director 1p 17454 345 24x Fiche 50-387 83/02/24 8303080002

8303080300 Forwards LER 83-017/03L-0
KEISER,H W Pennsylvania Power & Light Co 83/02/24 HAYNES,R C
Region 1 Office of Director 1p 17449 262 24x
Fiche 50-387 83/02/24 8303080300

--8303080311 LER 83-017/03L-0 on 830126 rod worth minimizer generated spurious blocks indicating out-of-sequence control rod 46-23 Caused by intermittent fault in rod position probe sent to rod scan by rod position indication sys
BUTT,R J Pennsylvania Power & Light Co 83/02/24 Region 1 Office of Director 1p 17449 263 24x Fiche 50-387 83/02/24 8303080300

8303090098 Forwards LER 83-018/03L-0
KEISER,H W Pennsylvania Power & Light Co 83/02/25 HAYNES,R C
Region 1 Office of Director 1p 17470 360 24x
Fiche 50-387 83/02/25 8303090098

--8303090116 LER 83-018/03L-0 on 830126 during startup test program found inaccurate value for 100% rated recirculation flow utilized to establish average power range monitor flow-biased rod block & scram setpoints Points reset
KUCZYNSKI,L A Pennsylvania Power & Light Co 83/02/25 Region 1 Office of Director 2pp 17470 361 24x Fiche 50-387 83/02/25 8303090098

8303140205 LER 83-021/01P-0 on 830225 nonqualified containment vent & purge valves not maintained in lock-closed position during primary containment integrity test Measures to restore electrical isolation instituted
KEISER,H W Pennsylvania Power & Light Co 83/02/28 HAYNES,R C
Region 1 Office of Director 1p 17540 073 24x
Fiche 50-387 83/02/28 8303140205

8303140405 Forwards LER 83-020/03L-0
KEISER,H W Pennsylvania Power & Light Co 83/02/28 HAYNES,R C
Region 1 Office of Director 1p 17542 175 24x
Fiche 50-387 83/02/28 8303140405

--8303140412 LER 83-020/03L-0 on 830129 & 0203 during startup testing control structure chlorine detector A constant drip feature failed Caused by clogging of orifice due to crystallization on detector wick & orifice Wick & orifice cleaned
KUCZYNSKI,L A Pennsylvania Power & Light Co 83/02/28 Region 1 Office of Director 1p 17542 176 24x Fiche 50-387 83/02/28 8303140405

8303160227 Updated Final deficiency rept re defects in Agastat GP series relays All safety-related relays except relays in diesel generator panels replaced w/new qualified relays
CURTIS,N W Pennsylvania Power & Light Co 83/03/02 HAYNES,R C
Region 1 Office of Director 2pp 17596 346 24x
Fiche 50-387 83/03/02 8303160227

8303160261 LER 83-026/01T-0 on 830302 both standby gas treatment sys trains found inoperable Caused by inappropriate application of protective permit for personnel safety Upon removal of permit sys restored to operable status
KEISER,H W Pennsylvania Power & Light Co 83/03/02 HAYNES,R C
Region 1 Office of Director 1p 17596 333 24x
Fiche 50-387 83/03/02 8303160261

8303160174 Forwards LER 83-022/03L-0
KEISER,H W Pennsylvania Power & Light Co 83/03/04 HAYNES,R C
Region 1 Office of Director 1p 17596 288 24x
Fiche 50-387 83/03/04 8303160174

--8303160180 LER 83-022/03L-0 on 830203 reagent gas bottle (oxygen) for hydrogen analyzer found exhausted during startup test program Caused by periodic gas bottle pressure check omission & inadequate storeroom min inventory
TODD,J T Pennsylvania Power & Light Co 83/03/04 Region 1 Office of Director 2pp 17596 289 24x Fiche 50-387 83/03/04 8303160174

8303160186 Forwards LER 83-025/03L-0
KEISER,H W Pennsylvania Power & Light Co 83/03/04 HAYNES,R C
Region 1 Office of Director 1p 17596 285 24x
Fiche 50-387 83/03/04 8303160186

--8303160191 LER 83-025/03L-0 on 830204 reactor recirculation pump A tripped off-line during startup test program Caused by deficiency in silicon controlled rectifier resulting in high field circuit current Voltage regulator board replaced
TODD,J T Pennsylvania Power & Light Co 83/03/04 Region 1 Office of Director 2pp 17596 286 24x Fiche 50-387 83/03/04 8303160186

8303160241 Forwards LER 83-023/03L-0
KEISER,H W Pennsylvania Power & Light Co 83/03/04 HAYNES,R C
Region 1 Office of Director 1p 17596 355 24x
Fiche 50-387 83/03/04 8303160241

--8303160250 LER 83-023/03L-0 on 830202 ventilation to reactor bldg zones I & III lost once & zone III second time High wind conditions caused pressure fluctuations of exterior delta pressure sensor Sensor rerouted
KUCZYNSKI,L A Pennsylvania Power & Light Co 83/03/04 Region 1 Office of Director 1p 17596 356 24x Fiche 50-387 83/03/04 8303160241

8303160369 Forwards LER 83-024/03L-0
KEISER,H W Pennsylvania Power & Light Co 83/03/04 HAYNES,R C
Region 1 Office of Director 1p 17595 330 24x
Fiche 50-387 83/03/04 8303160369

--8303160375 LER 83-024/03L-0 on 830205 during startup testing at 93% power contacts in reactor vessel level switch LIS-B21-1N042A would not close at setpoint Caused by mechanical failure inside mechanism Switch replaced
TODD,J T Pennsylvania Power & Light Co 83/03/04 Region 1 Office of Director 2pp 17595 331 24x Fiche 50-387 83/03/04 8303160369

8303240503 Forwards LER 83-027/03L-0
KEISER,H W Pennsylvania Power & Light Co 83/03/10 HAYNES,R C
Region 1 Office of Director 1p 17682 231 24x
Fiche 50-387 83/03/10 8303240503

--8303240520 LER 83-027/03L-0 on 830219 technician discovered that PSH-B21-N056 B & C (low condenser vacuum pressure switches-channel B & C) did not meet Tech Spec Caused by setpoint drift Switches recalibr
TODD,J T Pennsylvania Power & Light Co 83/03/10 Region 1 Office of Director 1p 17682 232 24x Fiche 50-387 83/03/10 8303240503

8303210533 LER 83-033/01P-0 while in operating condition breach of secondary containment discovered Breach restored & unit started up Investigation revealed that discovery date may not be occurrence date
KEISER,H W Pennsylvania Power & Light Co 83/03/11 HAYNES,R C
Region 1 Office of Director 1p 17632 284 24x
Fiche 50-387 83/03/11 8303210533

8303210746 Forwards LER 83-028/03L-0
KEISER,H W Pennsylvania Power & Light Co 83/03/11 HAYNES,R C
Region 1 Office of Director 1p 17635 123 24x
Fiche 50-387 83/03/11 8303210746

--8303210751 LER 83-028/03L-0 on 830213 one of two offsite power feeds to onsite Class 1E distribution sys de-energized Caused by transformer differential relay scheme opening lower supply breakers due to failure of A phase winding to ground
TODD,J T Pennsylvania Power & Light Co 83/03/11 Region 1 Office of Director 2pp 17635 124 24x Fiche 50-387 83/03/11 8303210746

8303210380 PNO-1-83-017 on 830311 airborne radioactivity identified in turbine & radwaste bldgs following local air monitor alarm Release terminated within 1 h by shifting back to recombiner Open drain valve on common recombiner identified
ARCHITZEL,REIMIG Region 1 Office of Director 83/03/14 1p 17634 177 24x Fiche 50-387 83/03/14 8303210380

8303210692 Forwards LER 83-029/03L-0
KEISER,H W Pennsylvania Power & Light Co 83/03/14 HAYNES,R C
Region 1 Office of Director 1p 17635 288 24x
Fiche 50-387 83/03/14 8303210692

--8303210701 LER 83-029/03L-0 on 830215 quarterly calibr Surveillance SI-83-321 on high drywell pressure channel D PSH-E11-N010D failed at meet Tech Spec value Caused by setpoint drift Instrument will be checked during next quarterly calibr
TODD,J T Pennsylvania Power & Light Co 83/03/14 Region 1 Office of Director 1p 17635 289 24x Fiche 50-387 83/03/14 8303210692

8303210709 Forwards LER 83-032/03L-0
KEISER,H W Pennsylvania Power & Light Co 83/03/14 HAYNES,R C
Region 1 Office of Director 1p 17635 120 24x
Fiche 50-387 83/03/14 8303210709

--8303210713 LER 83-032/03L-0 on 830213, drywell average air temps exceeded Tech Spec during startup test following 100% load reject test. Caused by loss of svc water due to failure to achieve auxiliary electrical bus fast transfer.
TODD, J. T. Pennsylvania Power & Light Co. 83/03/14. Region 1, Office of Director. 2pp. 17635:121. 24X Fiche: 50-387, 83/03/14, 8303210709.

8303240128 Notification of 830317 significant licensee meeting w/util in King of Prussia, PA to discuss recent inoperability of both standby gas treatment subsystems.
* Region 1, Office of Director. 83/03/15. Region 1, Office of Director. 1p. 17698:343. 24X Fiche: 50-387, 83/03/15, 8303240128.

8303250117 Forwards LER 83-026/01T-0.
KEISER, H. W. Pennsylvania Power & Light Co. 83/03/15. HAYNES, R. C. Region 1, Office of Director. 1p. 17693:076. 24X Fiche: 50-387, 83/03/15, 8303250117.

--8303250123 LER 83-026/01T-0 on 830301, while operating at 100% power, operator tagged out standby gas treatment sys A, causing both trains to be inoperable. Caused by personnel error. Reinstruction & training being formulated.
TODD, J. T. Pennsylvania Power & Light Co. 83/03/15. Region 1, Office of Director. 3pp. 17693:077. 24X Fiche: 50-387, 83/03/15, 8303250117.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303090229 Responds to Generic Ltr 83-01 re site visits to conduct operator licensing exams & instructor certification exams. Category S exams tentatively scheduled for Dec & June of each yr beginning in Dec 1983.
KENYON, B. D. Pennsylvania Power & Light Co. 83/02/28. EISENHUT, D. G. Division of Licensing. 1p. 17472:362. 24X Fiche: 50-387, 83/02/28, 8303090229.

X. Onsite Storage of Low Level Waste

8303280063 Forwards response to 830106 request for addl info re low level radwaste holding facility.
CURTIS, N. W. Pennsylvania Power & Light Co. 83/03/01. ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch. 9pp. 17726:322. 24X Fiche: 50-387, 83/03/01, 8303280063.

DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

A. Application/construction stage documents & correspondence

8208060366 Board Notification 82-70 notifies of differing prof opinion re sensitization of BWR stainless steel weldments.
EISENHUT, D. G. Division of Licensing. 82/07/20. PALLADINO, N. J. Commissioners. 4pp. 17043:001. 24X Fiche: 50-000, 82/07/20, 8208060366.

8302280091 Forwards 171 oversize revised drawings per Reg Guide 1.70. Marked-up FSAR Table 1.7-1 encl. Aperture cards are available in PDR.
CODDINGTON, C. T. Pennsylvania Power & Light Co. 83/02/11. Commissioners. 12pp. 17306:090. 24X Fiche: 50-387, 83/02/11, 8302280091.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303020460 Approves util 821217 position re seismic & dynamic qualification review & audit, pending review of listed items. Addl info re differences between Unit 1 & 2 equipment required.
SCHWENCER, A. Licensing Branch 2. 83/02/23. CURTIS, N. W. Pennsylvania Power & Light Co. 3pp. 17357:210. 24X Fiche: 50-387, 83/02/23, 8303020460.

8303040405 Submits response to License Condition 2.C.(13), describing permanent mods which limit flow in 12-inch gas pipeline near facility w/three oversize drawings. Aperture cards are available in PDR.
CURTIS, N. W. Pennsylvania Power & Light Co. 83/02/25. SCHWENCER, A. Licensing Branch 2. 2pp. 17420:069. 24X Fiche: 50-387, 83/02/25, 8303040405.

8303070080 Forwards Rev 2 to "Susquehanna Steam Electric Station, Units 1 & 2, Dynamic Qualification," for recirculation discharge gate valve assemblies HV-1F031 A & B, including Limitorque actuator installation.
CURTIS, N. W. Pennsylvania Power & Light Co. 83/02/28. SCHWENCER, A. Licensing Branch 2. 1p. 17435:149. 24X Fiche: 50-387, 83/02/28, 8303070080.

--8303070089 Rev 2 to "Susquehanna Steam Electric Station, Units 1 & 2, Dynamic Qualification."
LE, H. General Electric Co. KR1-831-F031 R02. 83/01/24. 24pp. 17435:150. 24X Fiche: 50-387, 83/02/28, 8303070080.

8303070097 Advises that final response to Humphrey Issue 3 will be submitted by 830601.
CURTIS, N. W. Pennsylvania Power & Light Co. 83/02/28. SCHWENCER, A. Licensing Branch 2. 1p. 17435:276. 24X Fiche: 50-387, 83/02/28, 8303070097.

8303090234 Forwards 223 oversize drawings, per Reg Guide 1.70. Drawing list encl. Aperture cards are available in PDR.
MOLCHANY, W. J. Pennsylvania Power & Light Co. 83/03/01. SCHWENCER, A. Licensing Branch 2. 11pp. 17471:107. 24X Fiche: 50-387, 83/03/01, 8303090234.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303140458 Forwards Rev 8 to nonproprietary "Design Assessment Rept." CURTIS, N. W. Pennsylvania Power & Light Co. 83/03/07. SCHWENCER, A. Licensing Branch 2. 2pp. 17543:021. 24X Fiche: 50-387, 83/03/07, 8303140458.

--8303140464 Rev 8 to nonproprietary "Design Assessment Rept."
* Pennsylvania Power & Light Co. 83/02/28. 274pp. 17543:023. 24X Fiche: 50-387, 83/03/07, 8303140458.

8303230339 Responds to 821210 request for exemption from 10CFR50.44 requirements. Based on installation of operable inerting sys, which conforms w/10CFR50.44(c)(3)(i), requested exemption not necessary.
EISENHUT, D. G. Division of Licensing. 83/03/10. CURTIS, N. W. Pennsylvania Power & Light Co. 3pp. 17675:017. 24X Fiche: 50-387, 83/03/10, 8303230339.

8303230097 Requests info re determination of effect operation & maint may have on Archaeological Sites SES-3, SES-6, SES-8 & SES-11, per 830303 telcon. Info should be developed following steps presented in 36CFR800.3 & 800.4.
SCHWENCER, A. Licensing Branch 2. 83/03/15. CURTIS, N. W. Pennsylvania Power & Light Co. 2pp. 17687:174. 24X Fiche: 50-387, 83/03/15, 8303230097.

8303220177 Discusses final results of addl test of adequacy of design process. Audit to verify test results confirms design adequacy.
CURTIS, N. W. Pennsylvania Power & Light Co. 83/03/16. NOVAK, T. Assistant Director for Licensing. 2pp. 17657:120. 24X Fiche: 50-387, 83/03/16, 8303220177.

8303220276 Forwards "Susquehanna Post-Accident Airborne & Plateout Dose Calculation for Equipment Qualification per NUREG-0588," supporting Rev 31 to FSAR.
CURTIS, N. W. Pennsylvania Power & Light Co. 83/03/18. SCHWENCER, A. Licensing Branch 2. 1p. 17656:198. 24X Fiche: 50-387, 83/03/18, 8303220276.

--8303220283 "Susquehanna Post-Accident Airborne & Plateout Dose Calculation for Equipment Qualification per NUREG-0588."
* Pennsylvania Power & Light Co. 82/07/28. 12pp. 17656:199. 24X Fiche: 50-387, 83/03/18, 8303220276.

8303280162 Forwards rev to NPDES Permit PA-0027448 re sewage treatment.
CURTIS, N. W. Pennsylvania Power & Light Co. 83/03/22. SCHWENCER, A.
Licensing Branch 2. 20pp. 17708:001. 24X Fiche: 50-387, 83/03/22,
8303280162.

F. Security, medical, emergency & fire protection plans

8303280063 Forwards response to 830106 request for addl info re low level radwaste holding facility.
CURTIS, N. W. Pennsylvania Power & Light Co. 83/03/01. ROUSE, L. C.
Advanced Fuel & Spent Fuel Licensing Branch. 9pp. 17726:322. 24X
Fiche: 50-387, 83/03/01, 8303280063.

8303110270 Responds to NRC request for info on emergency operations facility (EOF). No interim primary or backup EOFs implemented. Response to Generic Ltr 81-10 transmitted on 810402.
CURTIS, N. W. Pennsylvania Power & Light Co. 83/03/07. SCHWENCER, A.
Licensing Branch 2. 1p. 17517:351. 24X Fiche: 50-387, 83/03/07,
8303110270.

8303290542 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/21. Document
Management Branch. 1p. 17742:218. 24X Fiche: 50-387, 83/03/21,
8303290542.

--8303290547 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-041, "Fire Emergencies."
* Pennsylvania Power & Light Co. 83/03/02. NRC - No Detailed Affiliation Given. 1p. 17742:219. 24X Fiche: 50-387, 83/03/[illegible],
8303290542.

--8303290548 Public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-041, "Fire Emergencies." Revised index encl.
* Pennsylvania Power & Light Co. 83/02/28. 13pp. 17742:220.
24X Fiche: 50-387, 83/03/21, 8303290542.

8303280020 Informs that Change N to physical security plan, originally scheduled for Feb 1983 submittal, will be provided by Apr 1983.
CURTIS, N. W. Pennsylvania Power & Light Co. 83/03/23. SCHWENCER, A.
Licensing Branch 2. 1p. 17707:312. 24X Fiche: 50-387, 83/03/23,
8303280020.

8303310009 Releases public version of rev to emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 83/03/28. Document
Management Branch. 1p. 17780:240. 24X Fiche: 50-387, 83/03/28,
8303310009.

--8303310010 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-014, "Personnel & Vehicle Contamination Surveys." Receipt form encl.
* Pennsylvania Power & Light Co. 83/02/24. SCHWENCER, A. NRC - No Detailed Affiliation Given. 1p. 17780:241. 24X
Fiche: 50-387, 83/03/28, 8303310009.

--8303310011 Public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-014, "Personnel & Vehicle Contamination Surveys."
* Pennsylvania Power & Light Co. 83/02/24. 11pp. 17780:242.
24X Fiche: 50-387, 83/03/28, 8303310009.

H. General correspondence

8303030176 Responds to 830120 ltr commenting on inadequacy of radiological emergency response planning for communities surrounding facility. Ltr forwarded to FEMA & PA Emergency Mgt Agency for further response.
HAYNES, R. C. Region 1, Office of Director. 83/02/09. NEMETHY, E.
Affiliation Unknown. 5pp. 17365:256. 24X Fiche: 50-387, 83/02/09,
8303030176.

--8303030191 Comments on inadequacy of radiological emergency response planning for areas surrounding facility.
NEMETHY, E. Affiliation Unknown. 83/01/20. ASSELSTINE, J.
Commissioners. 5pp. 17365:260. 24X Fiche: 50-387, 83/02/09,
8303030176.

8303180543 Comments on Resolution 36159 re leakage of radioactive water at facility. NRC regulations for design & operation of nuclear power plants adequate to protect public health & safety.
HAYNES, R. C. Region 1, Office of Director. 83/03/11. BRACE, W. G.
Wilkes-Barre, PA. 2pp. 17754:015. 24X Fiche: 50-387, 83/03/11,
8303180543.

--8303300129 Forwards City of Wilkes-Barre, PA resolution re recent radioactive water leakage for reply.
HAYNES, R. C. Region 1, Office of Director. 83/02/11. REHM, T. A.
Office of the Executive Director for Operations. 2pp. 17754:011.
24X Fiche: 50-387, 83/03/11, 8303180543.

I. Financial information

8303210332 Forwards Annual Financial Rept 1982.
CURTIS, N. W. Pennsylvania Power & Light Co. 83/03/16. DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. 1p. 17632:063. 24X
Fiche: 50-387, 83/03/16, 8303210332.

--8303210333 Annual Financial Rept 1982.
CAMPBELL, R. K. Pennsylvania Power & Light Co. 83/03/01. 51pp.
17632:064. 24X Fiche: 50-387, 83/03/16, 8303210332.

P. Operating license stage documents & correspondence

8303030559 Notifies that review of design & analysis of Category III anchors completed. Commitments of FSAR complied w/ based on results of independent design review & anchor reconciliation program.
LANDERS, D. F. Teledyne Engineering Services. 83/02/16. SCHWENCER, A.
Licensing Branch 2. 3pp. 17409:039. 24X Fiche: 50-387, 83/02/16,
8303030559.

Q. Inspection reports, IE Bulletins & correspondence

8303100314 Forwards IE Insp Rept 50-388/83-02 on 830125-28. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/02/23.
KENYON, B. D. Pennsylvania Power & Light Co. 2pp. 17490:238. 24X
Fiche: 50-388, 83/02/23, 8303100314.

--8303100317 IE Insp Rept 50-388/83-02 on 830125-28. No noncompliance noted. Major areas inspected: documents for installation of mechanical pumps in RCIC sys & HPCI sys.
VARELA, A. A., DURR, J. P. Region 1, Office of Director. 83/02/18.
4pp. 17490:240. 24X Fiche: 50-388, 83/02/23, 8303100314.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc.
11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303040359 Summary of 830125-27 meetings w/util & General Physics Corp re pump & valve inservice test program (inservice insp program).
PERCH, R. L. Licensing Branch 2. 83/02/25. Licensing Branch 2.
15pp. 17426:304. 24X Fiche: 50-387, 83/02/25, 8303040359.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc.
117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303280219 Forwards IE Insp Repts 50-387/83-03 & 50-388/83-01 on 830112-0308. Violations will be addressed in separate enforcement action.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/14.
KENYON, B. D. Pennsylvania Power & Light Co. 2pp. 17708:025. 24X
Fiche: 50-387, 83/03/14, 8303280219.

--8303280231 IE Insp Repts 50-387/83-03 & 50-388/83-01 on 830112-0308. Noncompliance noted: standby gas treatment sys improperly tagged out, leading to inoperability.
RHOADS, G., MCCANN, J. Region 1, Office of Director. MCCABE, E. C.
Division of Project & Resident Programs. 83/03/14. 20pp.
17708:027. 24X Fiche: 50-387, 83/03/14, 8303280219.

8303210480 Informs that NDE van insp rescheduled for 830705-15. Documents relevant to review should be made available by 830610. Insp will include independent verification of const. const activities, matls & svcs.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/16.
CURTIS, N. W. Pennsylvania Power & Light Co. 2pp. 17631:297. 24X
Fiche: 50-388, 83/03/16, 8303210480.

8212060383 IE Info Notice 83-12: "Incorrect Boron Stds." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche. 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13: "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12lpp. 17774:352 24X Fiche. 50-000, 83/03/21, 8212060387.

S. Reportable occurrences, LERs & related correspondence

8303010267 Interim deficiency rept re defective GE HMA auxiliary relays resulting in insufficient clearances between armature tail piece & molded posts. Initially reported on 830119. Final rept by 830601. Also reported per Part 21.
CURTIS, N.W. Pennsylvania Power & Light Co. 83/02/18 HAYNES, R.C.
Region 1, Office of Director 3pp. 17335:103 24X
Fiche. 50-388, 83/02/18, 8303010267.

8303010637 Correction to interim deficiency rept re potentially defective GE HMA relays. Recorded date for Ltr PLA-1528 is 830218.
CURTIS, N.W. Pennsylvania Power & Light Co. 83/02/23 HAYNES, R.C.
Region 1, Office of Director 2pp. 17336:134 24X
Fiche. 50-387, 83/02/23, 8303010637.

8303160227 Updated Final deficiency rept re defects in Agastat GP series relays. All safety-related relays, except relays in diesel generator panels, replaced w/new qualified relays.
CURTIS, N.W. Pennsylvania Power & Light Co. 83/03/02 HAYNES, R.C.
Region 1, Office of Director 2pp. 17596:346 24X
Fiche. 50-387, 83/03/02, 8303160227.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D.G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche. 50-000, 83/02/24, 8302250505.

8303090229 Responds to Generic Ltr 83-01 re site visits to conduct operator licensing exams & instructor certification exams. Category B exams tentatively scheduled for Dec & June of each yr beginning in Dec 1983.
KENYON, B.D. Pennsylvania Power & Light Co. 83/02/28 EISENHUT, D.G.
Division of Licensing 1p. 17472:362 24X Fiche. 50-387, 83/02/28, 8303090229.

X. Onsite Storage of Low Level Waste

8303280063 Forwards response to 830106 request for addl info re low level radwaste holding facility.
CURTIS, N.W. Pennsylvania Power & Light Co. 83/03/01 ROUSE, L.C.
Advanced Fuel & Spent Fuel Licensing Branch 9pp. 17726:322 24X
Fiche. 50-387, 83/03/01, 8303280063.

DOCKET 50-389 ST. LUCIE PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D.G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp. 17492:033 24X
Fiche. 50-000, 83/02/16, 8302170082.

8303030703 Notification of 830307 meeting w/utils & NUS Corp. in Bethesda, MD to discuss proposed rev to 10CFR40, Appendix A (Tech Specs).
BRINKMAN, D.S. Standardization & Special Projects Branch 83/02/22
THOMAS, C.O. Standardization & Special Projects Branch 2pp.
17363:227 24X Fiche. 50-000, 83/02/22, 8303030703.

8303100343 Notification of 830303 meeting w/util in Bethesda, MD to discuss actions taken to complete items re axial growth & high burnup fission gas release prior to issuance of license.
NERSES, V. Licensing Branch 3 83/02/24 KNIGHTON, G.W. Licensing Branch 3 3pp. 17504:069 24X Fiche. 50-389, 83/02/24, 8303100343.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D.G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700:303 24X
Fiche. 50-000, 83/03/02, 8303020321.

8303080126 Forwards "Reactor Containment Bldg Integrated Leakage Rate Test," final rept, per App J requirements.
UHRIG, R.E. Florida Power & Light Co. 83/03/02 EISENHUT, D.G.
Division of Licensing 1p. 17447:162 24X Fiche. 50-389, 83/03/02, 8303080126.

--8303080131 "Reactor Containment Bldg Integrated Leakage Rate Test," final rept.
GRAASS, J.J. Ebasco Services, Inc. (subs. of Enserch Corp.).
82/12/02 123pp. 17447:163 24X Fiche. 50-389, 83/03/02, 8303080126.

8303100164 Advises that existing pipe configuration for vol control tank overpressure protection consistent w/appropriate ASME Code. Minor mod to V-2526 being processed, to satisfy NRC 830215 concern. Completion expected prior to core load.
UHRIG, R.E. Florida Power & Light Co. 83/03/03 EISENHUT, D.G.
Division of Licensing 4pp. 17485:220 24X Fiche. 50-389, 83/03/03, 8303100164.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D.G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176 24X
Fiche. 50-000, 83/03/07, 8303040005.

8303110257 Forwards Seismic Qualification Test Repts N-46474P038368 Rev 1, "Core Protection Calculators 1 & 2," STR6764 Rev A, "Ex-Core Safety Channel Neutron Flux Signal Processing Electronics," & TS6575.2 Rev A, "Bistable/Auxiliary Trip ..."
UHRIG, R.E. Florida Power & Light Co. 83/03/09 EISENHUT, D.G.
Division of Licensing 1p. 17516:001 24X Fiche. 50-389, 83/03/09, 8303110257.

--8303110260 "Seismic Qualification Test Rept for Core Protection Calculators 1 & 2."
DREHER, J., GEANURACOS, L., GURA, A. Combustion Engineering, Inc.
N-46474P038368 R01 80/08/13 12pp. 17516:002 24X
Fiche. 50-389, 83/03/09, 8303110257.

--8303110262 "Seismic Test Program Performed on One CPC 1 & One CPC 2."
ZIMOULIS, T., ROTHAUG, R. Dayton T. Brown, Inc. DTB04RB0-0479 RA.
80/08/05 80pp. 17516:014 24X Fiche. 50-389, 83/03/09, 8303110257.

--8303110266 "EMI, Seismic & Environ Qualification Test Procedure for Core Protection Calculators 1 & 2."
GEANURACOS, L., GURA, L., UPTON, E. Combustion Engineering, Inc.
80/03/10 16pp. 17516:094 24X Fiche. 50-389, 83/03/09, 8303110257.

--8303110268 "Seismic Qualification Test Rept Ex-Core Safety Channel Neutron Flux Signal Processing Electronics."
* Electro-Mechanics, Inc. STR6764 82/06/09 186pp. 17516:110
24X Fiche. 50-389, 83/03/09, 8303110257.

--8303110271 "Seismic Qualification Test Rept Bistable/Auxiliary Trip Units."
* Electro-Mechanics, Inc. TS 6575-2 RA 82/08/05 181pp.
17516:296 24X Fiche. 50-389, 83/03/09, 8303110257.

8303150312 Discusses commitment re fragmentation of cladding embrittlement, per 830303 meeting. Results of ECCS analysis encl. Info previously discussed in Section 4.2.3(a) of SER (NUREG-0843).
UHRIG, R.E. Florida Power & Light Co. 83/03/10 EISENHUT, D.G.
Division of Licensing 2pp. 17567:013 24X Fiche. 50-389, 83/03/10, 8303150312.

8303160228 Submits addl info re human factors issues under appeal, per NRC mgt 830224-25 site visit. Current configuration of control board 206 will not pose increased risk to health & safety nor involve unreviewed safety question.
UHRIG, R.E. Florida Power & Light Co. 83/03/11 EISENHUT, D.G.
Division of Licensing 8pp. 17596:172 24X Fiche. 50-389, 83/03/11, 8303160228.

8303240276 Forwards DOE 830211 ltr stating that util is negotiating w/DOE for contract for disposal svcs.
KNIGHTON, G.W. Licensing Branch 3 83/03/15 UHRIG, R.E. Florida Power & Light Co. 2pp. 17695:320 24X Fiche. 50-389, 83/03/15, 8303240276.

8303310107 Forwards proprietary emergency operating pro_edures re natural circulation/cooldown & blackout operation & offnormal operating procedure re control element assembly offnormal operation & realignment Procedures withheld
WETHY,C M Florida Power & Light Co 83/03/16 Director's Office, Office of Inspection and Enforcement 1p 17755.001 24X Fiche 50-389,83/03/16,8303310107

8303250040 Forwards one oversize map in response to NRC request Aperture card is available in PDR
DANIEL,J K Florida Power & Light Co 83/03/17 LEE,J NRC - No Detailed Affiliation Given 1p 17692.083 24X Fiche 50-389,83/03/17,8303250040

8303240208 Discusses concerns raised by Equipment Qualification Branch re testing of pre-aged batteries to demonstrate seismic qualification Batteries will be replaced after 10 yrs from purchase date or addl test data will be provided
UHRIG,R E Florida Power & Light Co 83/03/18 EISENHUT,D G Division of Licensing 1p 17682.183 24X Fiche 50-389,83/03/18, 8303240208

8303240284 Requests confirmation of NRC understanding re testing of ESF actuation sys at power If sys does not comply w/Reg Guide 1 22 & Std IEEE-338, justification must be provided Response schedule due in 7 days
KNIGHTON,G W Licensing Branch 3 83/03/18 UHRIG,R E Florida Power & Light Co 2pp 17694.360 24X Fiche 50-389,83/03/18, 8303240284

8303240437 Forwards addl info requested at 830315 meeting re compliance of surveillance requirements for ac sources w/plant-specific design Tech Specs 3/4 8 1 1 changed as noted
UHRIG,R E Florida Power & Light Co 83/03/18 EISENHUT,D G Division of Licensing 2pp 17678.355 24X Fiche 50-389,83/03/18, 8303240437

8303240446 Advises that remaining active safety-related valves, including safety-related check valves,will be stroked after valve safety sys tested during hot functional testing after core load but prior to initial criticality
UHRIG,R E Florida Power & Light Co 83/03/18 EISENHUT,D G Division of Licensing 1p 17678.344 24X Fiche 50-389,83/03/18, 8303240446

8303240459 Responds to 10CFR50.49, "Environ Qualification of Electric Equipment Important to Safety for Nuclear Power Plants " Facility environ qualification program meets NUREG-0588 requirements & complies w/10CFR50.49
UHRIG,R E Florida Power & Light Co 83/03/18 EISENHUT,D G Division of Licensing 3pp 17678.058 24X Fiche 50-389,83/03/18, 8303240459

8303250085 Informs that Amend 14 to FSAR will be issued approx 4 months following issuance of OL
UHRIG,R E Florida Power & Light Co 83/03/21 EISENHUT,D G Division of Licensing 1p 17692.335 24X Fiche 50-389,83/03/21, 8303250085

8303250096 Forwards Suppl 1 to "Analytical Justification of Seismic Test Adequacy of St Lucie Unit 2 CPC & NI Modules in Reactor Protection Sys Cabinet," operability rept
UHRIG,R E Florida Power & Light Co 83/03/21 EISENHUT,D G Division of Licensing 1p 17693.100 24X Fiche 50-389,83/03/21, 8303250096

--8303250103 Suppl 1 to "Analytical Justification of E_smic Test Adequacy of St Lucie Unit 2 CPC & NI Modules in Reactor Protection Sys Cabinet," operability rept
* Florida Power & Light Co 83/03/21 21pp 17693.101 24X Fiche 50-389,83/03/21,8303250096

8303280087 Forwards Suppl A to "Independent Verification of Design & Const for St Lucie Unit 2 Nuclear Generating Station, Resolution of Discrepancies & Corrective Action Plans "
UHRIG,R E Florida Power & Light Co 83/03/21 EISENHUT,D G Division of Licensing 2pp 17707.250 24X Fiche 50-389,83/03/21, 8303280087

--8303280090 Suppl A to "Independent Verification of Design & Const for St Lucie Unit 2 Nuclear Generating Station,Resolution of Discrepancies & Corrective Action Plans "
* Florida Power & Light Co 83/03/31 26pp 17707.252 24X Fiche 50-389,83/03/21,8303280087

8303250017 Forwards final response to TMI Item II D 1, "Performance Testing of BWR & PWR Relief & Safety Valves " Conclusions reached in encl evaluation on operability of pressurizer safety valves & PORVs satisfy commitment
UHRIG,R E Florida Power & Light Co 83/03/22 EISENHUT,D G Assistant Director for Licensing 8pp 17692.085 24X Fiche 50-389,83/03/22,8303250017

8303280137 Comments on Board Notification 83-38 re failure of GE AK-2 reactor trip breakers Info may affect NRC conclusions re probability/corrective measures for transients w/o scram events (Unresolved Safety Issue A-9)
EISENHUT,D G Division of Licensing 83/03/22 PALLADINO,N Commissioners 20pp 17709.310 24X Fiche 50-000,83/03/22, 8303280137

8303310115 Forwards proprietary version of Emergency & Offnormal Operating Procedures 2-0030131, 2-0030141, 2-0120037, 2-0120040 & 2-0950030 Procedures withheld
WETHY,C M Florida Power & Light Co 83/03/22 Director's Office, Office of Inspection and Enforcement 1p 17763.049 24X Fiche 50-389,83/03/22,8303310115

8303280206 Advises that essential apparatus will be installed by end of first refueling to test 8-inch minipurge valves in containment ventilation sys every 92 days,per Tech Spec 4.6.1.7.4
UHRIG,R E Florida Power & Light Co 83/03/24 EISENHUT,D G Division of Licensing 1p 17708.208 24X Fiche 50-389,83/03/24, 8303280206

8303290472 Discusses mods to Batch C & 16 selected Batch B fuel assemblies similar to mods at AR Power & Light Unit 2 Shims installed on guide tubes to increase shoulder gap & holddown & flow plates machined in thickness to maintain length
UHRIG,R E Florida Power & Light Co 83/03/24 EISENHUT,D G Division of Licensing 3pp 17722.349 24X Fiche 50-389,83/03/24, 8303290472

8303300284 Summary of 830223 & 24 meetings w/util at site re NRC mgt review in preparation for license issuance Design, procurement & const in accord w/good engineering practices
NERSES,V Licensing Branch 3 83/03/24 Licensing Branch 3 6pp 17749.121 24X Fiche 50-389,83/03/24,8303300284

8303310403 Requests OL be granted based on facility readiness for fuel load by 830331 Plant completion status will not have adverse impact on plant safety Facility designed,constructed & tested per FSAR & licensing commitments
UHRIG,R E Florida Power & Light Co 83/03/24 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 17755.053 24X Fiche 50-389,83/03/24,8303310403

8303300224 Forwards P 25,corrective action plans,to Suppl A to "Engineering Verification Program," inadvertently omitted from util 830321 ltr
UHRIG,R E Florida Power & Light Co 83/03/25 EISENHUT,D G Division of Licensing 1p 17733.320 24X Fiche 50-389,83/03/25, 8303300224

--8303300230 P 25,corrective action plans,to Suppl A to "Engineering Verification Program "
* Florida Power & Light Co 83/03/25 100pp 17733.321 24X Fiche 50-389,83/03/25,8303300224

8303300273 Forwards schedule outlining portions of initial test program that may be incomplete by core load
UHRIG,R E Florida Power & Light Co 83/03/25 EISENHUT,D G Division of Licensing 15pp 17735.146 24X Fiche 50-389,83/03/25, 8303300273

8303300249 Forwards Rev 2 to "Offsite Dose Calculation Manual "
UHRIG,R E Florida Power & Light Co 83/03/28 EISENHUT,D G Division of Licensing 1p 17732.282 24X Fiche 50-335,83/03/28, 8303300249

--8303300254 Rev 2 to "Offsite Dose Calculation Manual "
* Florida Power & Light Co 83/03/28 100pp 17732.283 24X Fiche 50-335,83/03/28,8303300249

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303210442 Forwards IE Insp Rept 50-389/83-08 on 830124-27 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/02/16 UHRIG,R E Florida Power & Light Co 2pp 17634.242 24X Fiche 50-389,83/02/16,8303210442

--8303210459 IE Insp Rept 50-389/83-08 on 830124-27 No noncompliance noted Major areas inspected plant tour,review of SER (NUREG-0843) confirmatory items,insp followup items & testing of pipe supports & restraint sys
TAYLOR,P A ; BROOKS,E ; LANDIS,K Region 2, Office of Director 83/02/14 6pp 17634.244 24X Fiche 50-389,83/02/16,8303210442

8303100254 Forwards results of light surveys of remote shutdown panel room Surveys conducted to close out SER Item A.1.7
UHRIG,R E Florida Power & Light Co 83/03/03 EISENHUT,D G Division of Licensing 3pp 17489.353 24X Fiche 50-389,83/03/03, 8303100254

8303090340 Forwards info demonstrating capability of post-accident sampling sys closing out SER open items. "Interim Procedure Guideline for Core Damage Assessment" also encl.
UHRIG, R E Florida Power & Light Co. 83/03/04 EISENHUT, D G
Division of Licensing 23pp. 17472.001 24X Fiche 50-389, 83/03/04, 8303090340.

--8303090347 "Interim Procedure Guidelines for Core Damage Assessment."
* Combustion Engineering, Inc. 83/03/04 102pp. 17472.029 24X Fiche 50-389, 83/03/04, 8303090340.

8303150312 Discusses commitment re fragmentation of cladding embrittlement, per 830303 meeting. Results of ECCS analysis encl. Info previously discussed in Section 4.2.3(a) of SER (NUREG-0843).
UHRIG, R E Florida Power & Light Co. 83/03/10 EISENHUT, D G
Division of Licensing 2pp. 17567.013 24X Fiche 50-389, 83/03/10, 8303150312.

8303150528 Forwards "Comprehensive Vibration Assessment Program Final Summary Rept." completing action indicated in SER, NUREG-0843, Section 3.9.2.3. Rept favorably correlates reactor vibrational characteristics w/prototype reactor.
UHRIG, R E Florida Power & Light Co. 83/03/10 EISENHUT, D G
Division of Licensing 1p. 17568.205 24X Fiche 50-389, 83/03/10, 8303150528.

--8303150538 "Comprehensive Vibration Assessment Program Final Summary Rept."
UHRIG, R E Florida Power & Light Co. 83/02/28 9pp. 17568.206 24X Fiche 50-389, 83/03/10, 8303150528.

8303240210 Forwards addl info to clarify aspects of auxiliary feedwater pump endurance test rept per commitment in SER.
UHRIG, R E Florida Power & Light Co. 83/03/18 EISENHUT, D G
Division of Licensing 8pp. 17679.356 24X Fiche 50-389, 83/03/18, 8303240210.

F. Security, medical, emergency & fire protection plans

8303010660 Forwards RC Lewis 821112 ltr transmitting SALP Repts 50-250/82-33, 50-251/82-33 & 50-335/82-37 for May 1980 - June 1982 & 50-389/82-56 for Sept 1980 - June 1982. Overall performance satisfactory.
O'REILLY, J P. Region 2, Office of Director 83/01/18 UHRIG, R E
Florida Power & Light Co. 2pp. 17341.106 24X
Fiche 50-000, 83/01/18, 8303010660.

--8303010678 SALP Repts 50-250/82-33, 50-251/82-33 & 50-335/82-37 for May 1980 - June 1982 & 50-389/82-56 for Sept 1980 - June 1982. Overall performance satisfactory.
* Region 2, Office of Director 82/11/12 50pp. 17341.110 24X
Fiche 50-000, 83/01/18, 8303010660.

8303010570 Forwards IE Insp Repts 50-335/83-04 & 50-389/83-12 on 830119-20. No noncompliance noted.
DANCE, H C Division of Project & Resident Programs 83/02/10
UHRIG, R E Florida Power & Light Co. 2pp. 17336.233 24X
Fiche 50-335, 83/02/10, 8303010570.

--8303010585 IE Insp Repts 50-335/83-04 & 50-389/83-12 on 830119-20. No noncompliance noted. Major areas inspected: radiological emergency exercise.
HUFFMAN, G N. Region 2, Office of Director 83/02/07 11pp. 17336.235 24X Fiche 50-335, 83/02/10, 8303010570.

8303040346 Forwards Rev 1 to 820714 deviation requests for exemption from Section III.G of 10CFR50 App R & three new deviation requests, per results of completed detailed engineering design evaluation.
UHRIG, R E Florida Power & Light Co. 83/02/25 EISENHUT, D G
Division of Licensing 14pp. 17422.022 24X Fiche 50-389, 83/02/25, 8303040346.

8303040458 Forwards justification for not installing source range nuclear instrumentation isolation device & containment flame impingement shields in fire protection sys prior to core load.
UHRIG, R E Florida Power & Light Co. 83/02/25 EISENHUT, D G
Division of Licensing 4pp. 17373.343 24X Fiche 50-389, 83/02/25, 8303040458.

8303210697 Ack receipt of 830217 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-389/82-75.
DANCE, H C Division of Project & Resident Programs 83/03/01
UHRIG, R E Florida Power & Light Co. 1p. 17635.072 24X
Fiche 50-389, 83/03/01, 8303210697.

--8303210721 IE Insp Repts 50-389/82-75 & 50-335/82-46 on 821213-17. Deviation noted: improper storage of safety-related HEPA filters.
WRAY, J R., BARR, K P. Region 2, Office of Director 83/01/06
8pp. 17635.078 24X Fiche 50-389, 83/03/01, 8303210697.

8303160513 Forwards status update of offsite plans & emergency preparedness in area of public educ & info.
KRIMM, R W. Federal Emergency Management Agency 83/03/04
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 4pp. 17592.327 24X Fiche 50-335, 83/03/04, 8303160513.

8303160257 Advises of withdrawal of request for exemption from certain requirements of 10CFR73.21, per 811222 ltr. Facilities in compliance w/applicable sections.
UHRIG, R E Florida Power & Light Co. 83/03/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p. 17596.340 24X
Fiche 50-000, 83/03/10, 8303160257.

8303240126 Releases public version of revised emergency plan implementing procedures.
FELTON, J M. Division of Rules and Records 83/03/21 Document Management Branch 1p. 17699.213 24X Fiche 50-335, 83/03/21, 8303240126.

--8303240130 Forwards public version of revised emergency plan implementing procedures, including Procedures 2-0030141 re control room inaccessibility & 2-0120035 re pressurizer pressure level.
WETHY, C M. Florida Power & Light Co. 83/03/10 Director's Office, Office of Inspection and Enforcement 1p. 17699.214 24X
Fiche 50-335, 83/03/21, 8303240126.

--8303240133 Public version of revised emergency plan implementing procedures, including Procedures 2-0030141 re control room inaccessibility & 2-0120035 re pressurizer pressure level.
* Florida Power & Light Co. 83/03/03 86pp. 17699.215 24X
Fiche 50-335, 83/03/21, 8303240126.

8303250128 Forwards revised justification for interim operation prior to installation of containment flame impingement shields, highlighting measures taken to provide fire protection in affected areas above & beyond present NRC requirements.
UHRIG, R E Florida Power & Light Co. 83/03/21 EISENHUT, D G
Division of Licensing 4pp. 17692.203 24X Fiche 50-389, 83/03/21, 8303250128.

8303280349 Discusses request for exemptions from certain requirements of 10CFR73.21 Sections (d)(2) & (e) re marking & storage of safeguards matl. Request to withdraw exemption request acceptable, per util 830310 ltr.
VARGA, S A Operating Reactors Branch 1 83/03/21 UHRIG, R E
Florida Power & Light Co. 2pp. 17713.101 24X
Fiche 50-000, 83/03/21, 8303280349.

8303250010 Forwards present schedule to install TSI matl flame impingement shields on lower most cable trays in containment cable tray racks.
UHRIG, R E Florida Power & Light Co. 83/03/22 EISENHUT, D G
Division of Licensing 3pp. 17692.108 24X Fiche 50-389, 83/03/22, 8303250010.

8303300143 Forwards marked-up Table 3-1 of radiological emergency plan. Changes respond to comments during 830322 telcon & will be incorporated into Rev 13 by 840101.
UHRIG, R E Florida Power & Light Co. 83/03/28 EISENHUT, D G
Division of Licensing 10pp. 17731.210 24X Fiche 50-335, 83/03/28, 8303300143.

8303310467 Releases public version of revised emergency plan implementing procedures.
FELTON, J M. Division of Rules and Records 83/03/29 Document Management Branch 1p. 17795.349 24X Fiche 50-335, 83/03/29, 8303310467.

--8303310471 Forwards public version of revised emergency plan implementing procedures, including Procedures 1-0210030 re charging & letdown, 2-0120036 re pressurizer relief/safety valve & 2-1300031 re airlocks.
WETHY, C M. Florida Power & Light Co. 83/02/23 Director's Office, Office of Inspection and Enforcement 1p. 17795.350 24X
Fiche 50-335, 83/03/29, 8303310467.

--8303310474 Public version of revised emergency plan implementing procedures, including Procedures 1-0210030 re charging & letdown, 2-0120036 re pressurizer relief/safety valve & 2-1300031 re airlocks.
* Florida Power & Light Co. 83/02/18 36pp. 17795.351 24X
Fiche 50-335, 83/03/29, 8303310467.

# DOCKETED ITEMS

H. General correspondence

8303040338 Advises of current mailing address, effective Jul 1982.
UHRIG, R E. Florida Power & Light Co. 83/02/25. EISENHUT, D G.
Division of Licensing. 1p. 17375 072. 24X Fiche 50-000, 83/02/25,
8303040338.

J. Insurance & indemnity information

8303290310 Forwards Endorsement 46 to NELIA Policy NF-227.
DUCK, J R. Marsh & McLennan, Inc. 83/03/15. SALTZMAN, J. Office of
State Programs, Director. 2pp. 17716 204. 24X
Fiche 50-335, 83/03/15, 8303290310.

K. Utility Final Safety Analysis Report (FSAR) & amends

8303020086 Forwards Amend 13 to FSAR.
UHRIG, R E. Florida Power & Light Co. 83/02/28. EISENHUT, D G.
Division of Licensing. 4pp. 17349 144. 24X Fiche 50-389, 83/02/28,
8303020086.

--8303020091 Amend 13 to FSAR.
* Florida Power & Light Co. 83/02/28. 416pp. 17349 152. 24X
Fiche 50-389, 83/02/28, 8303020088.

Q. Inspection reports, IE Bulletins & correspondence

8303210506 Ack receipt of 820813 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-389/82-20.
Supplemental response re inadequate storage of electrical
penetrations should be provided by 830907.
DANCE, H C. Division of Project & Resident Programs. 82/09/02.
UHRIG, R E. Florida Power & Light Co. 1p. 17631 177. 24X
Fiche 50-389, 82/09/02, 8303210506.

--8303210512 Responds to NRC 820716 ltr re violations noted in IE Insp
Rept 50-389/82-29. Corrective actions: all supervisors, general
foreman, foremen & craftsmen instructed to cover penetrations
as soon as tasx completed.
UHRIG, R E. Florida Power & Light Co. 82/08/13. O'REILLY, J P.
Region 2, Office of Director. 3pp. 17631 178. 24X
Fiche 50-389, 82/09/02, 8303210506.

--8303210519 Forwards IE Insp Rept 50-389/82-29 on 820621-25. W/o notice
of violation.
DANCE, H C. Division of Project & Resident Programs. 82/07/16.
UHRIG, R E. Florida Power & Light Co. 2pp. 17631 181. 24X
Fiche 50-389, 82/09/02, 8303210506.

--8303210528 IE Insp Rept 50-389/82-29 on 820621-25. Noncompliance noted:
inadequate inplace storage of electrical penetrations.
HUNT, M D. Region 2, Office of Director. CONLON, T E. Division of
Engineering & Radiological Safety Programs. 82/07/15. 5pp.
17631 183. 24X Fiche 50-389, 82/09/02, 8303210506.

8303010660 Forwards RC Lewis 821112 ltr transmitting SALP Repts
50-250/82-33, 50-251/82-33 & 50-335/82-37 for May 1980 - June
1982 & 50-389/82-56 for Sept 1980 - June 1982. Overall
performance satisfactory.
O'REILLY, J P. Region 2, Office of Director. 83/01/18. UHRIG, R E.
Florida Power & Light Co. 2pp. 17341 106. 24X
Fiche 50-000, 83/01/18, 8303010660.

--8303010672 Forwards SALP Repts 50-250/82-33, 50-251/82-33 & 50-335/82-37
for May 1980 - June 1982 & 50-389/82-56 for Sept 1980 - June
1982. Evaluation will be discussed at 821123 meeting in
Miami, FL.
LEWIS, R C. Division of Project & Resident Programs. 82/11/12.
UHRIG, R E. Florida Power & Light Co. 2pp. 17341 108. 24X
Fiche 50-000, 83/01/18, 8303010660.

--8303010678 SALP Repts 50-250/82-33, 50-251/82-33 & 50-335/82-37 for
May 1980 - June 1982 & 50-389/82-56 for Sept 1980 - June
1982. Overall performance satisfactory.
* Region 2, Office of Director. 82/11/12. 50pp. 17341 110. 24X
Fiche 50-000, 83/01/18, 8303010660.

8303010329 Forwards IE Insp Rept 50-389/83-02 on 830104-07. No
noncompliance noted.
DANCE, H C. Division of Project & Resident Programs. 83/02/02.
UHRIG, R E. Florida Power & Light Co. 2pp. 17345 208. 24X
Fiche 50-389, 83/02/02, 8303010329.

--8303010334 IE Insp Rept 50-389/83-02 on 830104-07. No noncompliance
noted. Major areas inspected: 10CFR50.55(e) items, IE bulletins
& equipment storage.
HUNT, M D.; CONLON, T E. Division of Engineering & Radiological
Safety Programs. 83/01/27. 4pp. 17345 210. 24X
Fiche 50-389, 83/02/02, 8303010329.

8303010368 Forwards IE Insp Rept 50-389/83-01 on 830103-07. No
noncompliance noted.
DANCE, H C. Division of Project & Resident Programs. 83/02/04.
UHRIG, R E. Florida Power & Light Co. 2pp. 17345 162. 24X
Fiche 50-389, 83/02/04, 8303010368.

--8303010378 IE Insp Rept 50-389/83-01 on 830103-07. No noncompliance
noted. Major areas inspected: previous enforcement matters;
independent insp efforts; safety-related structures (welding)
& licensee action on previously identified insp items.
YORK, J W.; BLAKE, J J. Division of Engineering & Radiological
Safety Programs. 83/02/02. 5pp. 17345 164. 24X
Fiche 50-389, 83/02/04, 8303010368.

8303010280 Forwards addl info re IE Bulletin 81-03, "Flow Blockage of
Cooling Water to Safety Components by Corbicula Sp (Asiatic
clam) & Mytilus Sp (mussel)," per NRC 821210 request. Monthly
intake water pump tests performed.
UHRIG, R E. Florida Power & Light Co. 83/02/08. O'REILLY, J P.
Region 2, Office of Director. 2pp. 17345 130. 24X
Fiche 50-389, 83/02/08, 8303010280.

8303010210 Forwards IE Insp Rept 50-389/83-07 on 830117-21. No
noncompliance noted.
DANCE, H C. Division of Project & Resident Programs. 83/02/10.
UHRIG, R E. Florida Power & Light Co. 2pp. 17332 013. 24X
Fiche 50-389, 83/02/10, 8303010210.

--8303010216 IE Insp Rept 50-389/83-07 on 830117-21. No noncompliance
noted. Major areas inspected: preoperational test program for
radwaste sys, licensee action on bulletins, circulars, notices
& inspector followup items & receipt of startup sources.
HOSEY, C M.; BARR, K P. Division of Project & Resident Programs.
83/02/08. 7pp. 17332 015. 24X Fiche 50-389, 83/02/10, 8303010210.

8303010570 Forwards IE Insp Repts 50-335/83-04 & 50-389/83-12 on
830119-20. No noncompliance noted.
DANCE, H C. Division of Project & Resident Programs. 83/02/10.
UHRIG, R E. Florida Power & Light Co. 2pp. 17336 233. 24X
Fiche 50-335, 83/02/10, 8303010570.

--8303010585 IE Insp Repts 50-335/83-04 & 50-389/83-12 on 830119-20. No
noncompliance noted. Major areas inspected: radiological
emergency exercise.
HUFFMAN, G N. Region 2, Office of Director. JENKINS, G R. Division
of Emergency Preparedness & Materials Safety. 83/02/07. 11pp.
17336 235. 24X Fiche 50-335, 83/02/10, 8303010570.

8303210442 Forwards IE Insp Rept 50-389/83-08 on 830124-27. No
noncompliance noted.
DANCE, H C. Division of Project & Resident Programs. 83/02/16.
UHRIG, R E. Florida Power & Light Co. 2pp. 17634 242. 24X
Fiche 50-389, 83/02/16, 8303210442.

--8303210459 IE Insp Rept 50-389/83-08 on 830124-27. No noncompliance
noted. Major areas inspected: plant tour; review of SER (NUREG-
0843) confirmatory items; insp followup items & testing of
pipe supports & restraint sys.
TAYLOR, P A.; BROOKS, E.; LANDIS, K. Region 2, Office of Director.
83/02/14. 6pp. 17634 244. 24X Fiche 50-389, 83/02/16, 8303210442.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers
(Westinghouse DB-50) to Open on Automatic Trip Signal." Svc
list encl.
DEYOUNG, R C. Director's Office, Office of Inspection and
Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc.
11lpp. 17521 001. 24X Fiche 50-000, 83/02/25, 8212060367.

8303210444 Forwards IE Insp Repts 50-335/82-45 & 50-389/82-74 on
821211-830110. No noncompliance noted.
DANCE, H C. Division of Project & Resident Programs. 83/02/25.
UHRIG, R E. Florida Power & Light Co. 2pp. 17634 180. 24X
Fiche 50-335, 83/02/25, 8303210444.

--8303210453 IE Insp Rept: 50-335/82-45 & 50-389/82-74 on 821211-830110.
No noncompliance noted. Major areas inspected: maint
observation, operational safety verification, new fuel
handling & bulletins, circulars & info notices.
ELROD, S A.; BIBB, H E. Region 2, Office of Director. JULIAN, C A.
Division of Project & Resident Programs. 82/02/24. 12pp.
17634 182. 24X Fiche 50-335, 83/02/25, 8303210444.

8303040638 Responds to IE Bulletin 82-04, "Deficiencies in Primary
Containment Electrical Penetration Assemblies." Primary
containment electrical penetration assemblies mfg by Conax.
Bulletin not applicable.
UHRIG, R E. Florida Power & Light Co. 83/02/28. DEYOUNG, R C.
Director's Office, Office of Inspection and Enforcement. 2pp.
17368 350. 24X Fiche 50-389, 83/02/28, 8303040638.

8303210697 Ack receipt of 830217 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-389/82-75.
DANCE,H.C. Division of Project & Resident Programs 83/03/01
UHRIG,R.E. Florida Power & Light Co. 1p 17635.072 24X
Fiche: 50-389, 83/03/01, 8303210697

--8303210706 Responds to NRC 820111 ltr re violations noted in IE Insp Rept 50-389/82-75. Corrective actions HEPA filters restacked three cartons high & undamaged; stored in accordance w/ANSI N509-1980 & marked correctly.
UHRIG,R.E. Florida Power & Light Co. 83/02/17 O'REILLY,J.P.
Region 2, Office of Director 2pp 17635.073 24X
Fiche: 50-389, 83/03/01, 8303210697

--8303210712 Forwards IE Insp Repts 50-335/82-46 & 50-389/82-75 on 821213-17 & notice of deviation.
DANCE,H.C. Division of Project & Resident Programs 83/01/11
UHRIG,R.E. Florida Power & Light Co. 2pp 17635.075 24X
Fiche: 50-389, 83/03/01, 8303210697

--8303210714 Notice of deviation from insp on 821213-17.
* Region 2, Office of Director 83/01/11 1p 17635.077 24X
Fiche: 50-389, 83/03/01, 8303210697

--8303210721 IE Insp Repts 50-389/82-75 & 50-335/82-46 on 821213-17. Deviation noted: improper storage of safety-related HEPA filters.
WRAY,J.R. ; BARR,K.P. Region 2, Office of Director 83/01/06
8pp 17635.078 24X Fiche: 50-389, 83/03/01, 8303210697

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc.
117pp 17611.070 24X Fiche: 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc.
117pp 24X Fiche: 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc.
12Ipp 17774.352 24X Fiche: 50-000, 83/03/21, 8212060387

R Periodic operating reports & related correspondence

8303280028 Forwards const/startup monthly status rept for Feb 1983. Current target fuel load date is 830323.
UHRIG,R.E. Florida Power & Light Co. 83/03/21 EISENHUT,D.G. Division of Licensing 2pp 17707.338 24X Fiche: 50-389, 83/03/21, 8303280028

S Reportable occurrences, LERs & related correspondence

8303010261 Interim deficiency rept re lack of insp of small bore piping bends. Initially reported on 821013. Results of insp undergoing engineering evaluation. Final rept will be submitted 830318.
UHRIG,R.E. Florida Power & Light Co. 83/02/22 O'REILLY,J.P.
Region 2, Office of Director 1p 17335.111 24X
Fiche: 50-389, 83/02/22, 8303010261

8303040460 Final deficiency rept re fan belt problems during initial startup of diesel generator. Initially reported on 830210. Belt & bearings strengthened & structural support members relocated.
UHRIG,R.E. Florida Power & Light Co. 83/02/25 O'REILLY,J.P.
Region 2, Office of Director 3pp 17373.327 24X
Fiche: 50-389, 83/02/25, 8303040460

8303040464 Final deficiency rept re failure of reactor shutdown cooling bypass valves to respond to command signals. Initially reported on 820630. Model 108 controllers will be replaced. Not reportable per 10CFR50.55(e).
UHRIG,R.E. Florida Power & Light Co. 83/02/25 O'REILLY,J.P.
Region 2, Office of Director 9pp 17424.113 24X
Fiche: 50-389, 83/02/25, 8303040464

8303150165 Final deficiency rept re signal drift uncertainties larger than design specs in ITT Barton pressure transmitters. Initially reported on 821221. Four transmitters replaced w/ Rosemount transmitters.
UHRIG,R.E. Florida Power & Light Co. 83/02/25 O'REILLY,J.P.
Region 2, Office of Director 3pp 17555.201 24X
Fiche: 50-389, 83/02/25, 8303150165

8303240569 Interim deficiency rept re radiation monitoring sys display panel lockup. Initially reported on 830210. Final rept will be submitted on 830325. Evaluation in progress.
UHRIG,R.E. Florida Power & Light Co. 83/03/11 O'REILLY,J.P.
Region 2, Office of Director 1p 17683.169 24X
Fiche: 50-389, 83/03/11, 8303240569

8303240579 Final Deficiency Rept 83-001 re potential long-term galling between internal components of Garrett PORV solenoids. Initially reported on 820210. PORV solenoids & parts for safety injection tank solenoid vent valves will be replaced.
UHRIG,R.E. Florida Power & Light Co. 83/03/11 O'REILLY,J.P.
Region 2, Office of Director 2pp 17683.163 24X
Fiche: 50-389, 83/03/11, 8303240579

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees; applicants for OL; holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT,D.G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc.
18pp 24X Fiche: 50-000, 83/02/24, 8302250505

DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees; applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT,D.G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc.
18pp 17492.033 24X
Fiche: 50-000, 83/02/16, 8302170082

8302280512 Forwards Hittman Nuclear & Development Corp proprietary process control program for ensuring solidification & dewatering at facilities. Affidavit in support of proprietary determination encl. Program withheld (ref 10CFR2.790).
MILLS,L.M. Tennessee Valley Authority 83/02/22 ADENSAM,E.
Licensing Branch 4 3pp 17309.148 24X Fiche: 50-390, 83/02/22, 8302280512

8303030277 Informs of NRC denial of Westinghouse appeal of NRC position on reactor trip breaker testing.
ADENSAM,E.G. Licensing Branch 4 83/02/22 PARRIS,H.G. Tennessee Valley Authority 2pp 17365.236 24X Fiche: 50-390, 83/02/22, 8303030277

8303040609 Submits revised dates for new fuel load. Revised dates reflect current sys completion schedules & assessment of remaining schedule uncertainties. Fuel load scheduled for Unit 1 in Jan 1984 & for Unit 2 in Jan 1985.
MILLS,L.M. Tennessee Valley Authority 83/02/25 ADENSAM,E.
Licensing Branch 4 1p 17374.224 24X Fiche: 50-390, 83/02/25, 8303040609

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT,D.G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc.
17pp 17700.303 24X
Fiche: 50-000, 83/03/02, 8303020321

8303110348 Notification of 830311 meeting w/util in Bethesda, MD to discuss evaluation of liquefaction potential beneath ERCW pipeline at facility.
KENYON,T.J. Licensing Branch 4 83/03/04 ADENSAM,E.G. Licensing Branch 4
2pp 17523.056 24X Fiche: 50-390, 83/03/04, 8303110348

8303040005 Generic Ltr 83-14 to all licensees of operating reactors; applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT,D.G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc.
5Ipp 17660.176 24X
Fiche: 50-000, 83/03/07, 8303040005

8303160766 Summary of 830121 meeting w/Design Review Panel in Bethesda, MD re D2/D3 steam generator mod.
HOPKINS,J.B. Licensing Branch 4 83/03/08 Licensing Branch 4
15pp 17600.202 24X Fiche: 50-000, 83/03/08, 8303160766

8303230527 Forwards NUREG-0996 evaluating util design review panel rept on mod to Westinghouse D2/D3 steam generators w/o encl. Generator mods acceptable.
NOVAK,T.M. Assistant Director for Licensing 83/03/16 TUCKER,H.B.
Duke Power Co. 8pp 17677.232 24X Fiche: 50-000, 83/03/16, 8303230527

# DOCKETED ITEMS

8303280306 Notification of 830321 meeting w/Design Review Panel in Bethesda, MD to discuss info re forward flush transient on steam generators D2/D3 Meeting closed to public due to proprietary nature of info
HOPKINS, J. B. Licensing Branch 4 83/03/18 ADENSAM, E. G. Licensing Branch 4 6pp 17713.301 24X Fiche 50-000, 83/03/18, 8303280306

8303310161 Forwards draft STS for Westinghouse PWRs to ensure info properly docketed
MILLS, L. M. Tennessee Valley Authority 83/03/22 ADENSAM, E. Licensing Branch 4 1p 17756.249 24X Fiche 50-390, 83/03/22, 8303310161

--8303310165 Draft STS for Westinghouse PWRs
* Tennessee Valley Authority 83/03/22 518pp 17756.250 24X Fiche 50-390, 83/03/22, 8303310161

8303290092 Notification of 830324 meeting w/design review panel in Bethesda, MD to discuss info re forward flush transient on D2/D3 steam generator
HOPKINS, J. B. Licensing Branch 4 83/03/23 ADENSAM, E. G. Licensing Branch 4 6pp 17729.236 24X Fiche 50-000, 83/03/23, 8303290092

8303300137 Denies 830222 request for withholding from public disclosure per 10CFR2.790, Hittman Nuclear & Development Corp process control program & plan for solidification & dewatering. Documents to be placed in PDR within 30 days of ltr date
ADENSAM, E. G. Licensing Branch 4 83/03/23 PARRIS, H. G. Tennessee Valley Authority 3pp 17750.328 24X Fiche 50-390, 83/03/23, 8303300137

8303290306 Forwards addl info re util analysis of axial stresses on buried pipe, including revised Criteria WB-DC-40-31.5 "Seismically Qualified Buried Piping Sys."
MILLS, L. M. Tennessee Valley Authority 83/03/25 ADENSAM, E. Licensing Branch 4 3pp 17716.129 24X Fiche 50-390, 83/03/25, 8303290306

--8303290317 Rev 1 to "Seismically Qualified Buried Piping Sys." design criteria
MYSINGER, E. D. ; KEY, J. C. ; GIVENS, J. I. Tennessee Valley Authority 83/01/13 16pp 17716.132 24X Fiche 50-390, 83/03/25, 8303290306

8303310581 Summary of Caseload Forecast Panel 830302-04 site visits re updating projected fuel load date Earliest fuel load date for Unit 1 estimated to be June 1984
KENYON, T. J. Licensing Branch 4 83/03/25 Licensing Branch 4 7pp 17780.338 24X Fiche 50-390, 83/03/25, 8303310581

## E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303030669 Responds to 820921 analysis on boron dilution event illustrating how SER single-failure criterion met Submittal does not resolve issue Util requested to show how alarm that initiates mitigating action meets single-failure criterion
NOVAK, T. M. Assistant Director for Licensing 83/02/24 PARRIS, H. G. Tennessee Valley Authority 3pp 17364.010 24X Fiche 50-390, 83/02/24, 8303030669

## F. Security, medical, emergency & fire protection plans

8303010479 Forwards IE Safeguards Insp Repts 50-390/83-03 & 50-391/83-03 on 830207-08 No noncompliance noted
VERRELLI, D. Division of Project & Resident Programs 83/02/25 PARRIS, H. G. Tennessee Valley Authority 2pp 17341.054 24X Fiche 50-390, 83/02/25, 8303010479

--8303010489 IE Safeguards Insp Repts 50-390/83-03 & 50-391/83-03 on 830207-08 No noncompliance noted Major areas inspected: circumstances of incident involving telephonic bomb threat & discovery of hoax device Details withheld (ref 10CFR73.21).
TILLMAN, A. ; MCGUIRE, D. R. Division of Project & Resident Programs 83/02/24 1p 17341.056 24X Fiche 50-390, 83/02/25, 8303010479

## J. Insurance & indemnity information

8303010243 Forwards Endorsements 19 & 20 to NELIA Policy NF-256
DUCK, J. R. Marsh & McLennan, Inc. 83/02/22 SALTZMAN, J. Assistant Director for State & Licensee Relations 3pp 17335.069 24X Fiche 50-390, 83/02/22, 8303010243

8303290415 Forwards Endorsement 21 to NELIA Policy NF-256
DUCK, J. R. Marsh & McLennan, Inc. 83/03/15 SALTZMAN, J. Assistant Director for State & Licensee Relations 2pp 17726.280 24X Fiche 50-390, 83/03/15, 8303290415

## Q. Inspection reports, IE Bulletins & correspondence

8303010330 Forwards IE Insp Repts 50-390/82-27 & 50-391/82-24 on 820727-0806 & notice of deviation
VERRELLI, D. M. Division of Project & Resident Programs 82/09/10 PARRIS, H. G. Tennessee Valley Authority 2pp 17345.182 24X Fiche 50-390, 82/09/10, 8303010330

--8303010335 Notice of deviation from insp on 820727-0806
* Division of Project & Resident Programs 82/09/10 1p 17345.184 24X Fiche 50-390, 82/09/10, 8303010330

--8303010341 IE Insp Repts 50-390/82-27 & 50-391/82-24 on 820727-0806 Deviation noted: general rev to procedures excluded requirement for application of tamperproof paint to junction boxes, conduits & other equipment access covers.
MCFARLAND, C. R. ; ANG, W. P. ; LENAHAN, J. J. Division of Project & Resident Programs 82/09/10 21pp 17345.185 24X Fiche 50-390, 82/09/10, 8303010330

8303010342 Forwards corrected P 20 of IE Insp Repts 50-390/82-27 & 50-391/82-24, inadvertently omitted from original rept W/o encl
VERRELLI, D. M. Division of Project & Resident Programs 82/09/28 PARRIS, H. G. Tennessee Valley Authority 2pp 17346.177 24X Fiche 50-390, 82/09/28, 8303010342

8303010346 Forwards corrected P 21 to IE Insp Repts 50-390/82-27 & 50-391/82-24, inadvertently omitted from original rept
VERRELLI, D. M. Division of Project & Resident Programs 82/10/07 PARRIS, H. G. Tennessee Valley Authority 1p 17346.173 24X Fiche 50-390, 82/10/07, 8303010346

--8303010350 Corrected P 21 to IE Insp Repts 50-390/82-27 & 50-391/82-24, inadvertently omitted from original rept
* Division of Project & Resident Programs 82/10/07 1p 17346.174 24X Fiche 50-390, 82/10/07, 8303010346

8303010262 Responds to NRC 820530 ltr re deviations noted in IE Insp Repts 50-390/82-27 & 50-391/82-24 Corrective actions: visual verification of cable routing will be employed & use of tamperproof paint on electrical junction box covers started
MILLS, L. M. Tennessee Valley Authority 82/10/14 O'REILLY, J. P. Region 2, Office of Director 3pp 17335.130 24X Fiche 50-390, 82/10/14, 8303010262

8303010255 Forwards final response to NRC ltr re violations noted in IE Insp Repts 50-390/82-27 & 50-391/82-24 Corrective actions: WBNP-QCP-3.05 revised to require signal trace verification of 100% of safety-related cables
MILLS, L. M. Tennessee Valley Authority 82/12/01 O'REILLY, J. P. Region 2, Office of Director 6pp 17335.137 24X Fiche 50-390, 82/12/01, 8303010255

8303010252 Revises response to NRC ltr re violations noted in IE Insp Repts 50-390/82-27 & 50-391/82-24 Corrective actions future coordination combined w/procedure review will constitute mgt control sys to avoid future problems
MILLS, L. M. Tennessee Valley Authority 83/01/19 O'REILLY, J. P. Region 2, Office of Director 7pp 17335.147 24X Fiche 50-390, 83/01/19, 8303010252

8303210551 Responds to NRC 820604 ltr re violations noted in IE Insp Rept 50-390/82-17 Due to underestimation of time required to complete reinsp, corrective actions will be completed 830331 instead of 830110
MILLS, L. M. Tennessee Valley Authority 83/01/19 O'REILLY, J. P. Region 2, Office of Director 1p 17632.312 24X Fiche 50-390, 83/01/19, 8303210551

8303010258 Suppl revised response to NRC ltr re deviations noted in IE Insp Repts 50-390/82-27 & 50-391/82-24 Corrective actions WBNCP-QCI-3.05 & WBNP-QCP-3.05 revised to require signal trace verification of 10% Completion by 830228
MILLS, L. M. Tennessee Valley Authority 83/02/07 O'REILLY, J. P. Region 2, Office of Director 1p 17335.136 24X Fiche 50-390, 83/02/07, 8303010258

8303210392 Forwards IE Insp Repts 50-390/83-01 & 50-391/83-01 on 830118-21 No noncompliance noted
VERRELLI, D. M. Division of Project & Resident Programs 83/02/11 PARRIS, H. G. Tennessee Valley Authority 2pp 17635.020 24X Fiche 50-390, 83/02/11, 8303210392

--8303210398 IE Insp Repts 50-390/83-01 & 50-391/83-01 on 830118-21 No noncompliance noted Major areas inspected: seismic analysis for as-built safety-related pipe sys (IE Bulletin 79-14) & action on previously identified items
YORK, J. W. ; LIU, W. ; BLAKE, J. J. Region 2, Office of Director 83/02/10 7pp 17635.022 24X Fiche 50-390, 83/02/11, 8303210392

8303210572 Forwards IE Insp Repts 50-390/83-02 & 50-391/83-02 on 821221-830121 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/02/14
PARRIS, H G Tennessee Valley Authority 2pp 17632 273 24X
Fiche 50-390, 83/02/14, 8303210572

--8303210585 IE Insp Repts 50-390/83-02 & 50-391/83-02 on 821221-830121 No noncompliance noted Major areas inspected: licensee identified items, licensee action on previous enforcement matters & independent insp effort
HEATHERLY, T L , SWAN, W Region 2, Office of Director
FREDRICKSON, P Division of Project & Resident Programs 83/02/14
6pp 17632 275 24X Fiche 50-390, 83/02/14, 8303210572

8303010241 Ack receipt of 821201, 830119 & 0207 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-27 & 50-391/82-24
VERRELLI, D M Division of Project & Resident Programs 83/02/23
PARRIS, H G Tennessee Valley Authority 1p 17335 072 24X
Fiche 50-390, 83/02/23, 8303010241

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc
111pp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367

8303010479 Forwards IE Safeguards Insp Repts 50-390/83-03 & 50-391/83-03 on 830207-08 No noncompliance noted
VERRELLI, D Division of Project & Resident Programs 83/02/25
PARRIS, H G Tennessee Valley Authority 2pp 17341 054 24X
Fiche 50-390, 83/02/25, 8303010479

--8303010489 IE Safeguards Insp Repts 50-390/83-03 & 50-391/83-03 on 830207-08 No noncompliance noted Major areas inspected: circumstances of incident involving telephonic bomb threat & discovery of hoax device Details withheld (ref 10CFR73 21)
TILLMAN, A , MCGUIRE, D R Division of Project & Resident Programs
83/02/24 1p 17341 056 24X Fiche 50-390, 83/02/25, 8303010479

8303210349 Ack receipt of supplemental 830228 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-35 & 50-391/82-32
VERRELLI, D M Division of Project & Resident Programs 83/03/07
PARRIS, H G Tennessee Valley Authority 1p 17634 147 24X
Fiche 50-390, 83/03/07, 8303210349

--8303210353 Responds to NRC 821102 ltr re violations noted in IE Insp Repts 50-390/82-35 & 50-391/82-32 Based on 830216-17 discussions w/NRC, criteria in final review process & completion date extended to 830301
MILLS, L M Tennessee Valley Authority 83/02/28 O'REILLY, J P
Region 2, Office of Director 1p 17634 148 24X
Fiche 50-390, 83/03/07, 8303210349

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc
117pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 12ipp 17774 352 24X Fiche 50-000, 83/03/21, 8212060387

5 Reportable occurrences, LERs & related correspondence

8303010198 Third interim deficiency rept re inadequate design of attachments of conduit & piping supports to cable tray supports Initially reported on 820607 Sampled attachments found to be within allowable values Next rept due by 830401
MILLS, L M Tennessee Valley Authority 83/02/23 O'REILLY, J P
Region 2, Office of Director 2pp 17332 352 24X
Fiche 50-390, 83/02/23, 8303010198

8303010207 Seventh interim deficiency rept re diesel generator room exhaust fan mod Initially reported on 810831 Design mods in progress Next rept will be submitted by 830628 Also reported per Part 21
MILLS, L M Tennessee Valley Authority 83/02/23 O'REILLY, J P
Region 2, Office of Director 1p 17332 022 24X
Fiche 50-390, 83/02/23, 8303010207

8303010586 Suppl 2 to final deficiency rept re improper weld attachment of shear lugs Initially reported on 801030 Six hangers require addl rework Corrective actions will be completed by 830315
MILLS, L M Tennessee Valley Authority 83/02/23 O'REILLY, J P
Region 2, Office of Director 1p 17336 141 24X
Fiche 50-390, 83/02/23, 8303010586

8303040545 Second interim deficiency rept re venting of high points in ERCW sys Initially reported on 820930 Manual vents unsuitable for ERCW sys due to restricted access under accident conditions Next rept will be submitted on 830429
MILLS, L M Tennessee Valley Authority 83/02/25 O'REILLY, J P
Region 2, Office of Director 2pp 17422 240 24X
Fiche 50-390, 83/02/25, 8303040545

8303040559 Final deficiency rept re absence of test procedure for HVAC refrigerant equipment Initially reported on 821012 Const specs revised to address const, cleaning, flushing, balancing & operational integrity of safety-related refrigerant sys
MILLS, L M Tennessee Valley Authority 83/02/25 O'REILLY, J P
Region 2, Office of Director 2pp 17374 189 24X
Fiche 50-390, 83/02/25, 8303040559

8303040603 Fifth interim deficiency rept re failure to provide cable separation in ERCW intake pumping station Initially reported on 811204 Drawings revised per Engineering Change Notice 3321 to add fire barrier protection Next rept due by 830616
MILLS, L M Tennessee Valley Authority 83/02/25 O'REILLY, J P
Region 2, Office of Director 2pp 17374 220 24X
Fiche 50-390, 83/02/25, 8303040603

8303040617 Final deficiency rept re undocumented minor mods to structural & miscellaneous steel Initially reported on 820510 Civil Quality Control inspectors & craft personnel instructed to inspect items per approved specs
MILLS, L M Tennessee Valley Authority 83/02/25 O'REILLY, J P
Region 2, Office of Director 2pp 17367 361 24X
Fiche 50-390, 83/02/25, 8303040617

8303040630 Fifth interim deficiency rept re containment spray miniflow valve design error Initially reported on 820305 Implementation of Engineering Change Notice 3420 continuing Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/02/25 O'REILLY, J P
Region 2, Office of Director 2pp 17367 213 24X
Fiche 50-390, 83/02/25, 8303040630

8303040613 Revised final deficiency rept re failure to inspect stud welds on flush-mounted embedded plates Initially reported on 820812 Due to oversight, intended completion date for corrective actions is 830513 & not 830313 as specified
MILLS, L M Tennessee Valley Authority 83/02/28 O'REILLY, J P
Region 2, Office of Director 1p 17368 021 24X
Fiche 50-390, 83/02/28, 8303040613

8303210679 First interim deficiency rept re transfer switches to auxiliary feedwater w/nondivisional power Initially reported on 830202 Control power to pressure switches may be provided from standby diesel generators Next rept expected by 830627
MILLS, L M Tennessee Valley Authority 83/03/02 O'REILLY, J P
Region 2, Office of Director 3pp 17635 062 24X
Fiche 50-000, 83/03/02, 8303210679

8303140418 First interim deficiency rept re valve position indication problem for EMD gate valves Initially reported on 830203 Westinghouse preparing field change notices to correct valve closure problems Next rept to be submitted 830622
MILLS, L M Tennessee Valley Authority 83/03/04 O'REILLY, J P
Region 2, Office of Director 2pp 17533 293 24X
Fiche 50-390, 83/03/04, 8303140418

8303140422 Second interim deficiency rept re use of incorrect DBA allowable loads for anchors Initially reported on 820924 Next rept expected by 830627
MILLS, L M Tennessee Valley Authority 83/03/04 O'REILLY, J P
Region 2, Office of Director 2pp 17542 063 24X
Fiche 50-390, 83/03/04, 8303140422

8303180050 Fourth interim deficiency rept re ambiguous outputs from Barton pressure transmitters in RCS Initially reported on 820409 Westinghouse defined corrective actions Also reported per Part 21 Next rept by 830630
MILLS, L M Tennessee Valley Authority 83/03/07 O'REILLY, J P
Region 2, Office of Director 2pp 17617 343 24X
Fiche 50-390, 83/03/07, 8303180050

8303150200 Fifth interim deficiency rept re loading criteria for structural steel & supports Initially reported on 811117 Caused by inadequate review of design notes General notes revised for clarity Next rept due by 830607
MILLS, L M Tennessee Valley Authority 83/03/08 O'REILLY, J P
Region 2, Office of Director 2pp 17555 168 24X
Fiche 50-390, 83/03/08, 8303150200

8303180300 Fifth interim deficiency rept re insufficient documentation for electrical equipment Initially reported on 810729 Summary of corrective actions for electrical components encl Next rept to be submitted by 831130
MILLS,L M Tennessee Valley Authority 83/03/08 O'REILLY,J P
Region 2 Office of Director 36pp 17617 092 24X
Fiche 50-390,83/03/08,8303180300

8303180022 Final deficiency rept re qualification of RHR/DHR sump valve rooms Initially reported on 820422 Caused by failure to establish & implement design criteria in accordance w/FSAR Mod underway
MILLS,L M Tennessee Valley Authority 83/03/09 O'REILLY,J P
Region 2 Office of Director 2pp 17618 102 24X
Fiche 50-000,83/03/09,8303180022

8303160450 Final deficiency rept re addition of locking devices to handwheel-operated valves Initially reported on 820916 No locking devices exceeding 10% valve weight criteria found Item not reportable per 10CFR50 55(e)
MILLS,L M Tennessee Valley Authority 83/03/10 O'REILLY,J P
Region 2 Office of Director 2pp 17592 272 24X
Fiche 50-000,83/03/10,8303160450

8303210396 Final deficiency rept re improperly installed support anchors Initially reported on 810608 All insps & load tests completed Seismic support insps now conducted using drawings to eliminate ambiguity
MILLS,L M Tennessee Valley Authority 83/03/14 O'REILLY,J P
Region 2 Office of Director 7pp 17634 314 24X
Fiche 50-390,83/03/14,8303210396

8303210596 Final deficiency rept re use of unqualified fillet welds on piping lugs Initially reported on 820819 Design procedures included in design input memo WB-DC-31 9-5 to control future design of fillet-welded lugs
MILLS,L M Tennessee Valley Authority 83/03/14 O'REILLY,J P
Region 2 Office of Director 2pp 17636 330 24X
Fiche 50-390,83/03/14,8303210596

8303220047 Supplemental info to final deficiency rept re Class 1E electrical components for ERCW traveling screens Initially reported on 810518 Corrective actions indicated in 820409 rept will be completed by 830502
MILLS,L M Tennessee Valley Authority 83/03/16 O'REILLY,J P
Region 2 Office of Director 1p 17652 272 24X
Fiche 50-390,83/03/16,8303220047

8303220336 Eleventh interim deficiency rept re steel containment penetration assembly Initially reported on 801219 Supports redesigned to account for new loads generated by piping reanalysis Next rept expected by 830627
MILLS,L M Tennessee Valley Authority 83/03/16 O'REILLY,J P
Region 2 Office of Director 1p 17656 001 24X
Fiche 50-390,83/03/16,8303220336

8303240429 Final deficiency rept re selection of undersized sway struts Initially reported on 820901 Condition no longer adverse to safety or plant operations Deficiency description modified to envelope linear type supports design
MILLS,L M Tennessee Valley Authority 83/03/17 O'REILLY,J P
Region 2 Office of Director 6pp 17679 067 24X
Fiche 50-390,83/03/17,8303240429

8303240525 Final deficiency rept re quality engineering branch unauthorized review of purchase requisitions Initially reported on 820120 Procedure EN DES-EP 5 01 revised to incorporate procurement specs requiring correct insp
MILLS,L M Tennessee Valley Authority 83/03/17 O'REILLY,J P
Region 2 Office of Director 3pp 17684 289 24X
Fiche 50-000,83/03/17,8303240525

8303240551 Final deficiency rept re incorrect pipe support design by EDS Initially reported on 811119 Incorrectly designed supports redesigned Field mods for Unit 1 completed Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 83/03/17 O'REILLY,J P
Region 2 Office of Director 2pp 17682 216 24X
Fiche 50-390,83/03/17,8303240551

8303240365 Second interim deficiency rept re valve verification program not performed & included in preoperation test instructions Initially reported on 821019 Westinghouse will provide addl testing info Next rept expected by 830808
MILLS,L M Tennessee Valley Authority 83/03/18 O'REILLY,J P
Region 2 Office of Director 2pp 17681 360 24X
Fiche 50-390,83/03/18,8303240365

8303240406 Final deficiency rept re regional quality engineering branch insp ofc manpower Initially reported on 820120 QA training completed 830318 Technical training will continue
MILLS,L M Tennessee Valley Authority 83/03/18 O'REILLY,J P
Region 2 Office of Director 3pp 17679 012 24X
Fiche 50-000,83/03/18,8303240406

8303240603 Fourth interim deficiency rept re use of incorrect seismic displacements & response spectra Initially reported on 820430 Hardware changes will be required Reanalysis not completed Next rept due by 830902
MILLS,L M Tennessee Valley Authority 83/03/18 O'REILLY,J P
Region 2 Office of Director 1p 17683 051 24X
Fiche 50-390,83/03/18,8303240603

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl
EISENHUT,D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000,83/02/24,8302250505

8303080442 Submits schedule for NRC operator licensing exam site visits through 1985 in response to Generic Ltr 83-01 Exams on 830815-19 for Watts Bar requested to be postponed due to delay in final fuel loading date
MILLS,L M Tennessee Valley Authority 83/02/28 ADENSAM,E Licensing Branch 4 2pp 17454 256 24X Fiche 50-000,83/02/28,8303080442

DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT,D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24X
Fiche 50-000,83/02/16,8302170082

8302280512 Forwards Hittman Nuclear & Development Corp proprietary process control program for ensuring solidification & dewatering at facilities Affidavit in support of proprietary determination encl Program withheld (ref 10CFR2 790)
MILLS,L M Tennessee Valley Authority 83/02/22 ADENSAM,E Licensing Branch 4 3pp 17309 148 24X Fiche 50-390,83/02/22,8302280512

8303030277 Informs of NRC denial of Westinghouse appeal of NRC position on reactor trip breaker testing
ADENSAM,E G Licensing Branch 4 83/02/22 PARRIS,H G Tennessee Valley Authority 2pp 17365 236 24X Fiche 50-390,83/02/22,8303030277

8303040609 Submits revised dates for new fuel load Revised dates reflect current sys completion schedules & assessment of remaining schedule uncertainties Fuel load scheduled for Unit 1 in Jan 1984 & for Unit 2 in Jan 1985
MILLS,L M Tennessee Valley Authority 83/02/25 ADENSAM,E Licensing Branch 4 1p 17374 224 24X Fiche 50-390,83/02/25,8303040609

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT,D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X
Fiche 50-000,83/03/02,8303020321

8303110348 Notification of 830311 meeting w/util in Bethesda,MD to discuss evaluation of liquefaction potential beneath ERCW pipeline at Facility
KENYON,T J Licensing Branch 4 83/03/04 ADENSAM,E G Licensing Branch 4 2pp 17523 056 24X Fiche 50-390,83/03/04,8303110348

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl
EISENHUT,D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 5lpp 17660 176 24X
Fiche 50-000,83/03/07,8303040005

8303160766 Summary of 830121 meeting w/Design Review Panel in Bethesda,MD re D2/D3 steam generator mod
HOPKINS,J B Licensing Branch 4 83/03/08 Licensing Branch 4 15pp 17600 202 24X Fiche 50-000,83/03/08,8303160766

8303230527 Forwards NUREG-0996 evaluating util design review panel rept on mod to Westinghouse D2/D3 steam generators W/o encl Generator mods acceptable
NOVAK, T M Assistant Director for Licensing 83/03/16 TUCKER, H B Duke Power Co 8pp 17677 232 24X Fiche 50-000, 83/03/16, 8303230527

8303280306 Notification of 830321 meeting w/Design Review Panel in Bethesda, MD to discuss info re forward flush transient on steam generators D2/D3 Meeting closed to public due to proprietary nature of info
HOPKINS, J B Licensing Branch 4 83/03/18 ADENSAM, E G Licensing Branch 4 6pp 17713 301 24X Fiche 50-000, 83/03/18, 8303280306

8303310161 Forwards draft STS for Westinghouse PWRs to ensure info properly docketed
MILLS, L M Tennessee Valley Authority 83/03/22 ADENSAM, E Licensing Branch 4 1p 17756 249 24X Fiche 50-390, 83/03/22, 8303310161

--8303310165 Draft STS for Westinghouse PWRs
* Tennessee Valley Authority 83/03/22 518pp 17756 250 24X Fiche 50-390, 83/03/22, 8303310161

8303290092 Notification of 830324 meeting w/design review panel in Bethesda, MD to discuss info re forward flush transient on D2/D3 steam generator
HOPKINS, J B Licensing Branch 4 83/03/23 ADENSAM, E G Licensing Branch 4 6pp 17729 236 24X Fiche 50-000, 83/03/23, 8303290092

8303300137 Denies 830222 request for withholding from public disclosure per 10CFR2 790, Hittman Nuclear & Development Corp process control program & plan for solidification & dewatering Documents to be placed in PDR within 30 days of ltr date
ADENSAM, E G Licensing Branch 4 83/03/23 PARRIS, H G Tennessee Valley Authority 3pp 17750 328 24X Fiche 50-390, 83/03/23, 8303300137

8303290306 Forwards addl info re util analysis of axial stresses on buried pipe, including revised Criteria WB-DC-40-31 5 "Seismically Qualified Buried Piping Sys "
MILLS, L M Tennessee Valley Authority 83/03/25 ADENSAM, E Licensing Branch 4 3pp 17716 129 24X Fiche 50-390, 83/03/25, 8303290306

--8303290317 Rev 1 to "Seismically Qualified Buried Piping Sys," design criteria
MYSINGER, E D , KEY, J C , GIVENS, J I Tennessee Valley Authority 83/01/13 16pp 17716 132 24X Fiche 50-390, 83/03/25, 8303290306

8303310581 Summary of Caseload Forecast Panel 830302-04 site visits re updating projected fuel load date Earliest fuel load date for Unit 1 estimated to be June 1984
KENYON, T J Licensing Branch 4 83/03/25 Licensing Branch 4 7pp 17780 338 24X Fiche 50-390, 83/03/25, 8303310581

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303030669 Responds to 820921 analysis on boron dilution event illustrating how SER single-failure criterion met Submittal does not resolve issue Util requested to show how alarm that initiates mitigating action meets single-failure criterion
NOVAK, T M Assistant Director for Licensing 83/02/24 PARRIS, H G Tennessee Valley Authority 3pp 17364 010 24X Fiche 50-390, 83/02/24, 8303030669

F. Security, medical, emergency & fire protection plans

8303010479 Forwards IE Safeguards Insp Repts 50-390/83-03 & 50-391/83-03 on 830207-08 No noncompliance noted
VERRELLI, D Division of Project & Resident Programs 83/02/25 PARRIS, H G Tennessee Valley Authority 2pp 17341 054 24X Fiche 50-390, 83/02/25, 8303010479

--8303010489 IE Safeguards Insp Repts 50-390/83-03 & 50-391/83-03 on 830207-08 No noncompliance noted Major areas inspected circumstances of incident involving telephonic bomb threat & discovery of hoax device Details withheld (ref 10CFR73 21)
TILLMAN, A Division of Project & Resident Programs 83/02/24 1p 17341 056 24X Fiche 50-390, 83/02/25, 8303010479

J. Insurance & indemnity information

8303010243 Forwards Endorsements 19 & 20 to NELIA Policy NF-256
DUCK, J R Marsh & McLennan, Inc 83/02/22 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 17335 069 24X Fiche 50-390, 83/02/22, 8303010243

8303290415 Forwards Endorsement 21 to NELIA Policy NF-256
DUCK, J R Marsh & McLennan, Inc 83/03/15 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 17726 280 24X Fiche 50-390, 83/03/15, 8303290415

Q. Inspection reports, IE Bulletins & correspondence

8303010330 Forwards IE Insp Repts 50-390/82-27 & 50-391/82-24 on 820727-0806 & notice of deviation
VERRELLI, D M Division of Project & Resident Programs 82/09/10 PARRIS, H G Tennessee Valley Authority 2pp 17345 182 24X Fiche 50-390, 82/09/10, 8303010330

--8303010335 Notice of deviation from insp on 820727-0806
* Division of Project & Resident Programs 82/09/10 1p 17345 184 24X Fiche 50-390, 82/09/10, 8303010330

--8303010341 IE Insp Repts 50-390/82-27 & 50-391/82-24 on 820727-0806 Deviation noted general rev to procedures excluded requirement for application of tamperproof paint to junction boxes, conduits & other equipment access covers
MCFARLAND, C R , ANG, W P , LENAHAN, J J Division of Project & Resident Programs 82/09/10 21pp 17345 185 24X Fiche 50-390, 82/09/10, 8303010330

8303010342 Forwards corrected P 20 of IE Insp Repts 50-390/82-27 & 50-391/82-24, inadvertently omitted from original rept W/o encl
VERRELLI, D M Division of Project & Resident Programs 82/09/28 PARRIS, H G Tennessee Valley Authority 2pp 17346 177 24X Fiche 50-390, 82/09/28, 8303010342

8303010346 Forwards corrected P 21 to IE Insp Repts 50-390/82-27 & 50-391/82-24, inadvertently omitted from original rept
VERRELLI, D M Division of Project & Resident Programs 82/10/07 PARRIS, H G Tennessee Valley Authority 1p 17346 173 24X Fiche 50-390, 82/10/07, 8303010346

--8303010350 Corrected P 21 to IE Insp Repts 50-390/82-27 & 50-391/82-24, inadvertently omitted from original rept
* Division of Project & Resident Programs 82/10/07 1p 17346 174 24X Fiche 50-390, 82/10/07, 8303010346

8303010262 Responds to NRC 820530 ltr re deviations noted in IE Insp Repts 50-390/82-27 & 50-391/82-24 Corrective actions visual verification of cable routing will be employed & use of tamperproof paint on electrical junction box covers started
MILLS, L M Tennessee Valley Authority 82/10/14 O'REILLY, J P Region 2, Office of Director 3pp 17335 130 24X Fiche 50-390, 82/10/14, 8303010262

8303010255 Forwards final response to NRC ltr re violations noted in IE Insp Repts 50-390/82-27 & 50-391/82-24 Corrective actions WBNP-QCP-3 05 revised to require signal trace verification of 100% of safety-related cables
MILLS, L M Tennessee Valley Authority 82/12/01 O'REILLY, J P Region 2, Office of Director 6pp 17335 137 24X Fiche 50-390, 82/12/01, 8303010255

8303010252 Revises response to NRC ltr re violations noted in IE Insp Repts 50-390/82-27 & 50-391/82-24 Corrective actions future coordination, combined w/procedure review, will constitute mgt control sys to avoid future problems
MILLS, L M Tennessee Valley Authority 83/01/19 O'REILLY, J P Region 2, Office of Director 7pp 17335 147 24X Fiche 50-390, 83/01/19, 8303010252

8303010258 Suppl revised response to NRC ltr re deviations noted in IE Insp Repts 50-390/82-27 & 50-391/82-24 Corrective actions WBNCP-QCI-3 05 & WBNP-QCP-3 05 revised to require signal trace verification of 10% Completion by 830228
MILLS, L M Tennessee Valley Authority 83/02/07 O'REILLY, J P Region 2, Office of Director 1p 17335 136 24X Fiche 50-390, 83/02/07, 8303010258

8303210392 Forwards IE Insp Repts 50-390/83-01 & 50-391/83-01 on 830118-21 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/02/11 PARRIS, H G Tennessee Valley Authority 2pp 17635 020 24X Fiche 50-390, 83/02/11, 8303210392

--8303210398 IE Insp Repts 50-390/83-01 & 50-391/83-01 on 830118-21 No noncompliance noted Major areas inspected seismic analysis for as-built safety-related pipe sys (IE Bulletin 79-14) & action on previously identified items
YORK, J W , LIU, W , BLAKE, J J Region 2, Office of Director 83/02/10 7pp 17635 022 24X Fiche 50-390, 83/02/11, 8303210392

8303210572 Forwards IE Insp Repts 50-390/83-02 & 50-391/83-02 on 821221-830121 No noncompliance noted.
VERRELLI, D M Division of Project & Resident Programs 83/02/14
PARRIS, H G Tennessee Valley Authority 2pp 17632:273 24X
Fiche: 50-390, 83/02/14, 8303210572

--8303210585 IE Insp Repts 50-390/83-02 & 50-391/83-02 on 821221-830121. No noncompliance noted. Major areas inspected: licensee identified items, licensee action on previous enforcement matters & independent insp effort.
HEATHERLY, T L ; SWAN, W Region 2, Office of Director
FREDRICKSON, P Division of Project & Resident Programs 83/02/14
6pp 17632:275 24X Fiche: 50-390, 83/02/14, 8303210572

8303010241 Ack receipt of 821201, 830119 & 0207 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-27 & 50-391/82-24.
VERRELLI, D M Division of Project & Resident Programs 83/02/23
PARRIS, H G Tennessee Valley Authority 1p 17335:072 24X
Fiche: 50-390, 83/02/23, 8303010241

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc.
11lpp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367

8303010479 Forwards IE Safeguards Insp Repts 50-390/83-03 & 50-391/83-03 on 830207-08. No noncompliance noted.
VERRELLI, D Division of Project & Resident Programs 83/02/25
PARRIS, H G Tennessee Valley Authority 2pp 17341:054 24X
Fiche: 50-390, 83/02/25, 8303010479

--8303010489 IE Safeguards Insp Repts 50-390/83-03 & 50-391/83-03 on 830207-08. No noncompliance noted. Major areas inspected: circumstances of incident involving telephonic bomb threat & discovery of hoax device. Details withheld (ref 10CFR73.21).
TILLMAN, A ; MCGUIRE, D R Division of Project & Resident Programs
83/02/24 1p 17341:055 24X Fiche: 50-390, 83/02/25, 8303010479

8303210349 Ack receipt of supplemental 830228 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-35 & 50-391/82-32.
VERRELLI, D M Division of Project & Resident Programs 83/03/07
PARRIS, H G Tennessee Valley Authority 1p 17634:147 24X
Fiche: 50-390, 83/03/07, 8303210349

--8303210353 Responds to NRC 821102 ltr re violations noted in IE Insp Repts 50-390/82-35 & 50-391/82-32. Based on 830216-17 discussions w/NRC, criteria in final review process & completion date extended to 830301.
MILLS, L M Tennessee Valley Authority 83/02/28 O'REILLY, J P
Region 2, Office of Director 1p 17634:148 24X
Fiche: 50-390, 83/03/07, 8303210349

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc.
117pp 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche: 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387

E. Reportable occurrences, LERs & related correspondence

8303010198 Third interim deficiency rept re inadequate design of attachments of conduit & piping supports to cable tray supports. Initially reported on 820607. Sampled attachments found to be within allowable values. Next rept due by 830401.
MILLS, L M Tennessee Valley Authority 83/02/23 O'REILLY, J P
Region 2, Office of Director 2pp 17332:352 24X
Fiche: 50-390, 83/02/23, 8303010198

8303010207 Seventh interim deficiency rept re diesel generator room exhaust fan mod. Initially reported on 810831. Design mods in progress. Next rept will be submitted by 830628. Also reported per Part 21.
MILLS, L M Tennessee Valley Authority 83/02/23 O'REILLY, J P
Region 2, Office of Director 1p 17332:022 24X
Fiche: 50-390, 83/02/23, 8303010207

8303010586 Suppl 2 to final deficiency rept re improper weld attachment of shear lugs. Initially reported on 801030. Six hangers require addl rework. Corrective actions will be completed by 830315.
MILLS, L M Tennessee Valley Authority 83/02/23 O'REILLY, J P
Region 2, Office of Director 1p 17336:141 24X
Fiche: 50-390, 83/02/23, 8303010586

8303040545 Second interim deficiency rept re venting of high points in ERCW sys. Initially reported on 820930. Manual vents unsuitable for ERCW sys due to restricted access under accident conditions. Next rept will be submitted on 830429.
MILLS, L M Tennessee Valley Authority 83/02/25 O'REILLY, J P
Region 2, Office of Director 2pp 17422:240 24X
Fiche: 50-390, 83/02/25, 8303040545

8303040559 Final deficiency rept re absence of test procedure for HVAC refrigerant equipment. Initially reported on 821012. Const specs revised to address const, cleaning, flushing, balancing & operational integrity of safety-related refrigerant sys.
MILLS, L M Tennessee Valley Authority 83/02/25 O'REILLY, J P
Region 2, Office of Director 2pp 17374:189 24X
Fiche: 50-390, 83/02/25, 8303040559

8303040603 Fifth interim deficiency rept re failure to provide cable separation in ERCW intake pumping station. Initially reported on 811204. Drawings revised per Engineering Change Notice 3321 to add fire barrier protection. Next rept due by 830616.
MILLS, L M Tennessee Valley Authority 83/02/25 O'REILLY, J P
Region 2, Office of Director 2pp 17374:220 24X
Fiche: 50-390, 83/02/25, 8303040603

8303040617 Final deficiency rept re undocumented minor mods to structural & miscellaneous steel. Initially reported on 820510. Civil Quality Control inspectors & craft personnel instructed to inspect items per approved specs.
MILLS, L M Tennessee Valley Authority 83/02/25 O'REILLY, J P
Region 2, Office of Director 2pp 17367:361 24X
Fiche: 50-390, 83/02/25, 8303040617

8303040630 Fifth interim deficiency rept re containment spray miniflow valve design error. Initially reported on 820305. Implementation of Engineering Change Notice 3420 continuing. Also reportable per Part 21.
MILLS, L M Tennessee Valley Authority 83/02/25 O'REILLY, J P
Region 2, Office of Director 2pp 17367:213 24X
Fiche: 50-390, 83/02/25, 8303040630

8303040613 Revised final deficiency rept re failure to inspect stud welds on flush-mounted embedded plates. Initially reported on 820812. Due to oversight, intended completion date for corrective actions is 830513 & not 830313 as specified.
MILLS, L M Tennessee Valley Authority 83/02/28 O'REILLY, J P
Region 2, Office of Director 1p 17368:021 24X
Fiche: 50-390, 83/02/28, 8303040613

8303210679 First interim deficiency rept re transfer switches to auxiliary feedwater w/nondivisional power. Initially reported on 830202. Control power to pressure switches may be provided from standby diesel generators. Next rept expected by 830627.
MILLS, L M Tennessee Valley Authority 83/03/02 O'REILLY, J P
Region 2, Office of Director 3pp 17635:062 24X
Fiche: 50-000, 83/03/02, 8303210679

8303140418 First interim deficiency rept re valve position indication problem for EMD gate valves. Initially reported on 830203. Westinghouse preparing field change notices to correct valve closure problems. Next rept to be submitted 830622.
MILLS, L M Tennessee Valley Authority 83/03/04 O'REILLY, J P
Region 2, Office of Director 2pp 17533:293 24X
Fiche: 50-390, 83/03/04, 8303140418

8303180050 Fourth interim deficiency rept re ambiguous outputs from Barton pressure transmitters in RCS. Initially reported on 820409. Westinghouse defined corrective actions. Also reported per Part 21. Next rept by 830630.
MILLS, L M Tennessee Valley Authority 83/03/07 O'REILLY, J P
Region 2, Office of Director 2pp 17617:343 24X
Fiche: 50-390, 83/03/07, 8303180050

8303150200 Fifth interim deficiency rept re loading criteria for structural steel & supports. Initially reported on 811117. Caused by inadequate review of design notes. General notes revised for clarity. Next rept due by 830607.
MILLS, L M Tennessee Valley Authority 83/03/08 O'REILLY, J P
Region 2, Office of Director 2pp 17555:168 24X
Fiche: 50-390, 83/03/08, 8303150200

8303180300 Fifth interim deficiency rept re insufficient documentation for electrical equipment. Initially reported on 810729. Summary of corrective actions for electrical components encl. Next rept to be submitted by 831130.
MILLS, L M Tennessee Valley Authority 83/03/08 O'REILLY, J P
Region 2, Office of Director 36pp 17617:092 24X
Fiche: 50-390, 83/03/08, 8303180300

8303180022 Final deficiency rept re qualification of RHR/DHR sump valve rooms. Initially reported on 820422. Caused by failure to establish & implement design criteria in accordance w/FSAR. Mod underway.
MILLS,L M. Tennessee Valley Authority. 83/03/09. O'REILLY,J P. Region 2, Office of Director. 2pp. 17618:102. 24X
Fiche: 50-000, 83/03/09, 8303180022.

8303160450 Final deficiency rept re addition of locking devices to handwheel-operated valves. Initially reported on 820916. No locking devices exceeding 10% valve weight criteria found. Item not reportable per 10CFR50.55(e).
MILLS,L M. Tennessee Valley Authority. 83/03/10. O'REILLY,J P. Region 2, Office of Director. 2pp. 17592:272. 24X
Fiche: 50-000, 83/03/10, 8303160450.

8303210396 Final deficiency rept re improperly installed support anchors. Initially reported on 810608. All insps & load tests completed. Seismic support insps now conducted using drawings to eliminate ambiguity.
MILLS,L M. Tennessee Valley Authority. 83/03/14. O'REILLY,J P. Region 2, Office of Director. 7pp. 17634:314. 24X
Fiche: 50-390, 83/03/14, 8303210396.

8303210596 Final deficiency rept re use of unqualified fillet welds on piping lugs. Initially reported on 820819. Design procedures included in design input memo WB-DC-31-9-5 to control future design of fillet-welded lugs.
MILLS,L M. Tennessee Valley Authority. 83/03/14. O'REILLY,J P. Region 2, Office of Director. 2pp. 17636:330. 24X
Fiche: 50-390, 83/03/14, 8303210596.

8303220047 Supplemental info to final deficiency rept re Class 1E electrical components for ERCW traveling screens. Initially reported on 810518. Corrective actions indicated in 820409 rept will be completed by 830502.
MILLS,L M. Tennessee Valley Authority. 83/03/16. O'REILLY,J P. Region 2, Office of Director. 1p. 17652:272. 24X
Fiche: 50-390, 83/03/16, 8303220047.

8303220336 Eleventh interim deficiency rept re steel containment penetration assembly. Initially reported on 801219. Supports redesigned to account for new loads generated by piping reanalysis. Next rept expected by 830627.
MILLS,L M. Tennessee Valley Authority. 83/03/16. O'REILLY,J P. Region 2, Office of Director. 1p. 17656:001. 24X
Fiche: 50-390, 83/03/16, 8303220336.

8303240359 Supplis 820329 final deficiency rept re defective 6.9 GE circuit breaker. Initially reported on 811218. Commitments to inspect primary gap on all AM13.8 & AM17.2 type breakers delayed. Completion expected by 830401.
MILLS,L M. Tennessee Valley Authority. 83/03/17. O'REILLY,J P. Region 2, Office of Director. 2pp. 17682:003. 24X
Fiche: 50-391, 83/03/17, 8303240359.

8303240429 Final deficiency rept re selection of undersized sway struts. Initially reported on 820901. Condition no longer adverse to safety or plant operations. Deficiency description modified to envelope linear type supports design.
MILLS,L M. Tennessee Valley Authority. 83/03/17. O'REILLY,J P. Region 2, Office of Director. 6pp. 17679:067. 24X
Fiche: 50-390, 83/03/17, 8303240429.

8303240525 Final deficiency rept re quality engineering branch unauthorized review of purchase requisitions. Initially reported on 820120. Procedure EN DES-EP 5.01 revised to incorporate procurement specs requiring correct insp.
MILLS,L M. Tennessee Valley Authority. 83/03/17. O'REILLY,J P. Region 2, Office of Director. 3pp. 17684:289. 24X
Fiche: 50-000, 83/03/17, 8303240525.

8303240551 Final deficiency rept re incorrect pipe support design by EDS. Initially reported on 811119. Incorrectly designed supports redesigned. Field mods for Unit 1 completed. Also reportable per Part 21.
MILLS,L M. Tennessee Valley Authority. 83/03/17. O'REILLY,J P. Region 2, Office of Director. 2pp. 17682:216. 24X
Fiche: 50-390, 83/03/17, 8303240551.

8303240365 Second interim deficiency rept re valve verification program not performed & included in preoperation test instructions. Initially reported on 821019. Westinghouse will provide addl testing info. Next rept expected by 830808.
MILLS,L M. Tennessee Valley Authority. 83/03/18. O'REILLY,J P. Region 2, Office of Director. 2pp. 17681:360. 24X
Fiche: 50-390, 83/03/18, 8303240365.

8303240406 Final deficiency rept re regional quality engineering branch insp ofc manpower. Initially reported on 820120. QA training completed 830318. Technical training will continue.
MILLS,L M. Tennessee Valley Authority. 83/03/18. O'REILLY,J P. Region 2, Office of Director. 3pp. 17679:012. 24X
Fiche: 50-000, 83/03/18, 8303240406.

8303240603 Fourth interim deficiency rept re use of incorrect seismic displacements & response spectra. Initially reported on 820430. Hardware changes will be required. Reanalysis not completed. Next rept due by 830902.
MILLS,L M. Tennessee Valley Authority. 83/03/18. O'REILLY,J P. Region 2, Office of Director. 1p. 17683:051. 24X
Fiche: 50-390, 83/03/18, 8303240603.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT,D G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303080442 Submits schedule for NRC operator licensing exam site visits through 1985, in response to Generic Ltr 83-01. Exams on 830815-19 for Watts Bar requested to be postponed due to delay in final fuel loading date.
MILLS,L M. Tennessee Valley Authority. 83/02/28. ADENSAM,E. Licensing Branch 4. 2pp. 17454:256. 24X Fiche: 50-000, 83/02/28, 8303080442.

DOCKET: 50-395 VIRGIL C. SUMMER NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8302280081 Forwards Rev 9 to "Fire Protection Evaluation-Fire Hazards Analysis Rept," per 821118 commitment.
DIXON,O W. South Carolina Electric & Gas Co. 83/02/25. DENTON,H R. Office of Nuclear Reactor Regulation, Director. 1p. 17304:006. 24X Fiche: 50-395, 83/02/25, 8302280081.

--8302280085 Rev 9 to "Fire Protection Evaluation-Fire Hazards Analysis Rept."
* South Carolina Electric & Gas Co. 83/02/04. 252pp. 17304:007. 24X Fiche: 50-395, 83/02/25, 8302280081.

8303210717 Ack receipt of 830225 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-395/82-55.
LEWIS,R C. Division of Project & Resident Programs. 83/03/01.
DIXON,O W. South Carolina Electric & Gas Co. 1p. 17635:095. 24X
Fiche: 50-395, 83/03/01, 8303210717.

--8303210745 IE Insp Rept 50-395/82-55 on 821101-1203. Noncompliance noted: failure to adequately establish & implement surveillance test procedures & to meet action statement.
SKOLDS,J L., BROWNLEE,V L. Region 2, Office of Director. 83/01/25. 12pp. 17635:108. 24X Fiche: 50-395, 83/03/01, 8303210717.

8303100088 Releases public version of revised emergency plan implementing procedure.
FELTON,J M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17493:059. 24X Fiche: 50-395, 83/03/02, 8303100088.

--8303100091 Forwards public version of Rev 4 to Emergency Plan Procedure EPP-002, "Communication & Notification."
DIXON,O W. South Carolina Electric & Gas Co. 83/03/02.
DENTON,H R. Office of Nuclear Reactor Regulation, Director. 1p. 17493:060. 24X Fiche: 50-395, 83/03/02, 8303100088.

--8303100094 Public version Rev 4 to Emergency Plan Procedure EPP-002, "Communication & Notification."
* South Carolina Electric & Gas Co. 83/01/31. 37pp. 17493:061. 24X Fiche: 50-395, 83/03/02, 8303100088.

8303210511 Ack receipt of 830223 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-395/82-57.
LEWIS,R C. Division of Project & Resident Programs. 83/03/03.
DIXON,O W. South Carolina Electric & Gas Co. 1p. 17636:034. 24X
Fiche: 50-395, 83/03/03, 8303210511.

--8303210521 Responds to NRC 830128 ltr re violations noted in IE Insp Rept 50-395/82-57. Corrective actions: fire suppression water sys test apparatus mfg on site & full flow test satisfactorily performed.
DIXON,O W. South Carolina Electric & Gas Co. 83/02/23.
O'REILLY,J P. Region 2, Office of Director. 2pp. 17636:035. 24X
Fiche: 50-395, 83/03/03, 8303210511.

--8303210535 Notice of violation from insp on 821117-19.
* Region 2, Office of Director. 83/01/28. 1p. 17636:039. 24X
Fiche: 50-395, 83/03/03, 8303210511.

--8303210541 IE Insp Rept 50-395/82-57 on 821117-19 Noncompliance noted: failure to conduct flow test of fire protection water distribution sys
MILLER, W. H. Region 2, Office of Director CONLON, T. E. Division of Engineering & Radiological Safety Programs 82/12/28 9pp 17636.040 24X Fiche 50-395, 83/03/03, 8303210511

8303180117 Responds to 821129 submittal of Amend 8 to physical security plan. Amend acceptable
ADENSAM, E. G. Licensing Branch 4 83/03/09 DIXON, O. W. South Carolina Electric & Gas Co. 2pp 17625.171 24X
Fiche 50-395, 83/03/09, 8303180117

G Adjudicatory correspondence

8303010236 Order extending time until 830225 for Commission to act to review ALAB-710
CHILK, S. J. Office of the Secretary of the Commission 83/02/22 Commissioners 1p 17333.362 24X Fiche 50-395, 83/02/22, 8303010236

8303030361 Advises that time for Commission to review ALAB-710 expired. Commission declined review. Decision became final agency action on 830225
CHILK, S. J. Office of the Secretary of the Commission 83/03/02 South Carolina Electric & Gas Co. 1p 17410.261 24X
Fiche 50-395, 83/03/02, 8303030361

J Insurance & indemnity information

8303280117 Forwards Statement of Insurance Certificate per nuclear property insurance requirements
DIXON, O. W. South Carolina Electric & Gas Co. 83/03/23 WOOD, R. Assistant Director for State & Licensee Relations 3pp 17709.343 24X Fiche 50-395, 83/03/23, 8303280117

P Operating license stage documents & correspondence

8303080463 Forwards "Seismic Confirmatory Program" per License Condition 2.C.25
DIXON, O. W. South Carolina Electric & Gas Co. 83/02/01 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 17450.001 24X Fiche 50-395, 83/02/01, 8303080463

--8303080468 "Seismic Confirmatory Program."
* South Carolina Electric & Gas Co. 83/02/28 286pp 17450.002 24X Fiche 50-395, 83/02/01, 8303080463

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492.033 24X
Fiche 50-000, 83/02/16, 8302170082

8303030747 Board Notification 83-13: Forwards EG&G draft rept, "Identification & Ranking of Nuclear Plant Structures, Sys & Components & Graded QA Guidelines."
EISENHUT, D. G. Division of Licensing 83/02/17 PALLADINO, N. Commissioners 24pp 17364.037 24X Fiche 50-000, 83/02/17, 8303030747

8303030710 Board Notification 83-17: Forwards JH Conran 830209 affidavit re changes to previous testimony on Unresolved Safety Issue A-17, "Sys Interaction in Nuclear Power Plants."
EISENHUT, D. G. Division of Licensing 83/02/18 PALLADINO, N. J., ROBERTS, T. M., ASSELSTINE, J. A. Commissioners 6pp 17363.317 24X
Fiche 50-000, 83/02/18, 8303030710

8303010131 Forwards Amend 11 to License NPF-12, safety evaluation & notice of issuance & availability. Amend provides extended operation of plant in excess of 2,000 hrs within specified power levels
ADENSAM, E. G. Licensing Branch 4 83/02/22 DIXON, O. W. South Carolina Electric & Gas Co. 2pp 17355.062 24X
Fiche 50-395, 83/02/22, 8303010131

--8303010144 Amend 11 to License NPF-12, providing extended plant operation in excess of 2,000 hrs within specified power levels
EISENHUT, D. G. Division of Licensing 83/02/22 2pp 17355.067 24X Fiche 50-395, 83/02/22, 8303010131

--8303010157 Safety evaluation supporting Amend 11 to License NPF-12
* Office of Nuclear Reactor Regulation, Director 83/02/22 4pp 17355.068 24X Fiche 50-395, 83/02/22, 8303010131

--8303010169 Notice of issuance & availability of Amend 11 to License NPF-12
ADENSAM, E. G. Licensing Branch 4 83/02/22 2pp 17355.072 24X
Fiche 50-395, 83/02/22, 8303010131

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700.303 24X
Fiche 50-000, 83/03/02, 8303020321

8303080005 Requests meeting on 830310 w/NRC to discuss results of experimental phase of seismic confirmatory program per License Condition 2.C(25). Addendum to program rept being developed by contractor
DIXON, O. W. South Carolina Electric & Gas Co. 83/03/02 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17454.349 24X Fiche 50-395, 83/03/02, 8303080005

8303170606 Forwards Amend 12 to License NPF-12, safety evaluation & notice of issuance & availability. Amend changes Tech Specs by adding containment penetration overcurrent protective device for steam cleaning machine permanent power source
ADENSAM, E. G. Licensing Branch 4 83/03/04 DIXON, O. W. South Carolina Electric & Gas Co. 3pp 17615.191 24X
Fiche 50-395, 83/03/04, 8303170606

--8303170611 Amend 12 to License NPF-12, changing Tech Specs by adding containment penetration conductor overcurrent protective device for steam cleaning machine permanent power source
ADENSAM, E. G. Licensing Branch 4 83/03/04 5pp 17615.193 24X
Fiche 50-395, 83/03/04, 8303170606

--8303170618 Safety evaluation supporting Amend 12 to License NPF-12
* Office of Nuclear Reactor Regulation, Director 83/03/04 2pp 17615.197 24X Fiche 50-395, 83/03/04, 8303170606

--8303170623 Notice of issuance & availability of Amend 12 to License NPF-12
ADENSAM, E. G. Licensing Branch 4 83/03/04 2pp 17615.199 24X
Fiche 50-395, 83/03/04, 8303170606

--8303170629 Advises of no known public correspondence or irreversible impact associated w/issuance of Amend 12 to License NPF-12
HOPKINS, J. Licensing Branch 4 83/01/17 NOVAK, T. M. Assistant Director for Licensing 1p 17615.201 24X Fiche 50-395, 83/03/04, 8303170606

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp 17660.176 24X
Fiche 50-000, 83/03/07, 8303040005

8303170007 Notification of 830310 meeting w/util in Bethesda, MD to discuss 830201 submittal re seismic confirmatory program
HOPKINS, J. B. Licensing Branch 4 83/03/07 ADENSAM, E. G. Licensing Branch 4 2pp 17615.222 24X Fiche 50-395, 83/03/07, 8303170007

8303160237 Forwards addl info re NUREG-0737, Item II.F.2, "Inadequate Core Cooling Instrumentation Sys," per Generic Ltr 82-28. Because of procurement difficulties, util may utilize different hardware & instrumentation
DIXON, O. W. South Carolina Electric & Gas Co. 83/03/08 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 9pp 17597.034 24X Fiche 50-395, 83/03/08, 8303160237

8303160766 Summary of 830121 meeting w/Design Review Panel in Bethesda, MD re D2/D3 steam generator mod
HOPKINS, J. B. Licensing Branch 4 83/03/08 Licensing Branch 4 15pp 17600.202 24X Fiche 50-000, 83/03/08, 8303160766

8303110035 Forwards addendum to "Experimental Investigation of Relative Response of Accelerograph Pad, Free Field & Structural Foundations at Virgil C Summer Nuclear Station" & errata page to be inserted in original rept
DIXON, O. W. South Carolina Electric & Gas Co. 83/03/09 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17519.323 24X Fiche 50-395, 83/03/09, 8303110035

--8303110040 Addendum to "Experimental Investigation of Relative Response of Accelerograph Pad, Free Field & Structural Foundations at Virgil C Summer Nuclear Station"
* URS Corp. 83/03/31 33pp 17519.326 24X
Fiche 50-395, 83/03/09, 8303110035

8303150154 Advises that typographical error made in 830308 response to Generic Ltr 82-28 re inadequate core cooling (TMI Item II.F.2). App 1, Explanation C, under I*.., 1-a schedule, should read 850331.
DIXON, O.W. South Carolina Electric & Gas Co. 83/03/10 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p 17549.001
24X Fiche 50-395.83/03/10.8303150154

8303230527 Forwards NUREG-0996 evaluating util design review panel rept on mod to Westinghouse D2/D3 steam generators W/o encl. Generator mods acceptable.
NOVAK, T.M. Assistant Director for Licensing 83/03/16 TUCKER, H.B. Duke Power Co. 8pp 17677.232 24X Fiche 50-000.83/03/16.
8303230527

8303220135 Informs NRC that Steam Generator D3 mod program will be performed in accordance w/provisions of util QA program.
DIXON, O.W. South Carolina Electric & Gas Co. 83/03/17 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p 17649.198
24X Fiche 50-395.83/03/17.8303220135

8303280306 Notification of 830321 meeting w/Design Review Panel in Bethesda, MD to discuss info re forward flush transient on steam generators D2/D3. Meeting closed to public due to proprietary nature of info.
HOPKINS, J.B. Licensing Branch 4 83/03/18 ADENSAM, E.G. Licensing Branch 4 6pp 17713.301 24X Fiche 50-000.83/03/18.8303280306

8303280137 Comments on Board Notification 83-38 re failure of GE AK-2 reactor trip breakers. Info may affect NRC conclusions re probability/corrective measures for transients w/o scram events (Unresolved Safety Issue A-9).
EISENHUT, D.G. Division of Licensing 83/03/22 PALLADINO, N. Commissioners 20pp 17709.310 24X Fiche 50-000.83/03/22.
8303280137

8303290092 Notification of 830324 meeting w/design review panel in Bethesda, MD to discuss info re forward flush transient on D2/D3 steam generator.
HOPKINS, J.B. Licensing Branch 4 83/03/23 ADENSAM, E.G. Licensing Branch 4 6pp 17729.236 24X Fiche 50-000.83/03/23.8303290092

8303300348 Forwards Amend 13 to License NPF-12, safety evaluation & notice of issuance & availability. Amend changes Tech Specs to permit one-time extension for performance of response time tests of reactor trip sys & ESF.
ADENSAM, E.G. Licensing Branch 4 83/03/23 DIXON, O.W. South Carolina Electric & Gas Co. 3pp 17754.295 24X
Fiche 50-395.83/03/23.8303300348

--8303300354 Amend 13 to License NPF-12, changing Tech Specs to permit one-time extension for performance of response time tests of reactor trip sys & ESF.
ADENSAM, E.G. Licensing Branch 4 83/03/23 5pp 17754.297 24X
Fiche 50-395.83/03/23.8303300348

--8303300357 Safety evaluation supporting Amend 13 to License NPF-12.
* Office of Nuclear Reactor Regulation, Director 83/03/23 2pp
17754.302 24X Fiche 50-395.83/03/23.8303300348

--8303300363 Notice of issuance & availability of Amend 13 to License NPF-12.
ADENSAM, E.G. Licensing Branch 4 83/03/23 2pp 17754.304 24X
Fiche 50-395.83/03/23.8303300348

8303300664 Forwards addl guidance for use in preparing required reporting of offsite doses to public for 1982.
ADENSAM, E.G. Licensing Branch 4 83/03/28 DIXON, D.W. South Carolina Electric & Gas Co. 4pp 17768.280 24X
Fiche 50-395.83/03/28.8303300664

G Inspection reports, IE Bulletins & correspondence

8302010466 Requests exception to requirements of IWA-1400, Paragraph (f) of ASME Section XI re contract w/authorized insp agency. Changes re authorized insp agency witness will be included in Rev 2 of First Interval Inservice Insp Program by 830501.
DIXON, O.W. South Carolina Electric & Gas Co. 83/01/27 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 16981.011
24X Fiche 50-395.83/01/27.8302010466

8303010175 Responds to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp (Asiatic clam) & Mytilus Sp (mussel)." Any flow restrictions will be physically cleaned of fouling agents.
DIXON, O.W. South Carolina Electric & Gas Co. 83/02/07
O'REILLY, J.P. Region 2, Office of Director 2pp 17335.353 24X
Fiche 50-395.83/02/07.8303010175

8303210483 Forwards IE Insp Rept 50-395/83-02 on 830111-14. No noncompliance noted.
DANCE, H.C. Division of Project & Resident Programs 83/02/11
DIXON, O.W. South Carolina Electric & Gas Co. 2pp 17631.308 24X
Fiche 50-395.83/02/11.8303210483

--8303210491 IE Insp Rept 50-395/83-02 on 830111-14. No noncompliance noted. Major areas inspected: completed power operation tests & surveillance test procedures.
BURNETT, P.T., JAPE, F. Region 2, Office of Director 83/02/10
6pp 17631.310 24X Fiche 50-395.83/02/11.8303210483

8303210425 Forwards IE Insp Rept 50-395/83-03 on 830125-28. No noncompliance noted.
DANCE, H.C. Division of Project & Resident Programs 83/02/16
DIXON, O.W. South Carolina Electric & Gas Co. 2pp 17634.229 24X
Fiche 50-395.83/02/16.8303210425

--8303210429 IE Insp Rept 50-395/83-03 on 830125-28. No noncompliance noted. Major areas inspected: radiological environ monitoring & review of environ sample intercomparison program.
CUNNINGHAM, A.L. Region 2, Office of Director MONTGOMERY, D.M. Division of Engineering & Radiological Safety Programs 83/02/15.
5pp 17634.231 24X Fiche 50-395.83/02/16.8303210425

8303110355 Board Notification 83-14 forwards followup info on apparent deficiencies in Midland-Ross superstrut matl.
EISENHUT, D.G. Division of Licensing 83/02/18 PALLADINO, N. Commissioners 24pp 17546.205 24X Fiche 50-000.83/02/18.
8303110355

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc.
111pp 17521.001 24X Fiche 50-000.83/02/25.8212060367

8303210717 Ack receipt of 830225 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-395/82-55.
LEWIS, R.C. Division of Project & Resident Programs 83/03/01
DIXON, O.W. South Carolina Electric & Gas Co. 1p 17635.095 24X
Fiche 50-395.83/03/01.8303210717

--8303210726 Responds to NRC 830127 ltr re violations noted in IE Insp Rept 50-395/82-55. Corrective actions: both RHR pumps retested on 831203 & found acceptable; appropriate surveillance test procedures revised & interim training program prepared.
DIXON, O.W. South Carolina Electric & Gas Co. 83/02/25
O'REILLY, J.P. Region 2, Office of Director 7pp 17635.096 24X
Fiche 50-395.83/03/01.8303210717

--8303210733 Forwards IE Insp Rept 50-395/82-55 on 821101-1203 & notice of violation.
LEWIS, R.C. Division of Project & Resident Programs 83/01/27
DIXON, O.W. South Carolina Electric & Gas Co. 2pp 17635.103
24X Fiche 50-395.83/03/01.8303210717

--8303210738 Notice of violation from insp on 821101-1203.
* Region 2, Office of Director 83/01/27 3pp 17635.105 24X
Fiche 50-395.83/03/01.8303210717

--8303210745 IE Insp Rept 50-395/82-55 on 821101-1203. Noncompliance noted: failure to adequately establish & implement surveillance test procedures & to meet action statement.
SKOLDS, J.L., BROWNLEE, V.L. Region 2, Office of Director
83/01/25 12pp 17635.108 24X Fiche 50-395.83/03/01.8303210717

8303210345 Responds to IE Bulletin 83-01. Plant does not use Westinghouse DB-type reactor trip breakers.
DIXON, O.W. South Carolina Electric & Gas Co. 83/03/03
O'REILLY, J.P. Region 2, Office of Director 1p 17634.290 24X
Fiche 50-395.83/03/03.8303210345

8303210400 Discusses 821104 commitment to perform study of overlap techniques for pipe analyses in response to IE Bulletin 79-14, "Analyses for As-Built Safety-Related Piping Sys." Study complete. Final rept will be submitted by 830316.
DIXON, O.W. South Carolina Electric & Gas Co. 83/03/03
O'REILLY, J.P. Region 2, Office of Director 2pp 17634.322 24X
Fiche 50-395.83/03/03.8303210400

8303210511 Ack receipt of 830223 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-395/82-57.
LEWIS, R.C. Division of Project & Resident Programs 83/03/03
DIXON, O.W. South Carolina Electric & Gas Co. 1p 17636.034 24X
Fiche 50-395.83/03/03.8303210511

--8303210521 Responds to NRC 830128 ltr re violations noted in IE Insp Rept 50-395/82-57 Corrective actions fire suppression water sys test apparatus mfg on site & full flow test satisfactorily performed.
DIXON, O W South Carolina Electric & Gas Co 83/02/23
O'REILLY, J P Region 2, Office of Director 2pp 17636 035 24X
Fiche 50-395, 83/03/03, 8303210511

--8303210531 Forwards IE Insp Rept 50-395/82-57 on 821117-19 & notice of violation.
LEWIS, R C Division of Project & Resident Programs 83/01/28
DIXON, O W South Carolina Electric & Gas Co 2pp 17636 037
24X Fiche 50-395, 83/03/03, 8303210511

--8303210535 Notice of violation from insp on 821117-19.
* Region 2, Office of Director 83/01/28 1p 17636 039 24X
Fiche 50-395, 83/03/03, 8303210511

--8303210541 IE Insp Rept 50-395/82-57 on 821117-19 Noncompliance noted failure to conduct flow test of fire protection water distribution sys.
MILLER, W H Region 2, Office of Director CONLON, T E Division of Engineering & Radiological Safety Programs 82/12/28 9pp
17636 040 24X Fiche 50-395, 83/03/03, 8303210511

8303210394 Supplx 820622 ltr re IE Bulletin 81-01 concerning insp results for safety-related snubbers All but one inoperable snubber evaluated for mode of failure Final rept expected after evaluation complete
DIXON, O W South Carolina Electric & Gas Co 83/03/04
O'REILLY, J P Region 2, Office of Director 2pp 17635 018 24X
Fiche 50-395, 83/03/04, 8303210394

8303210659 Provides affirmation or oath under provisions of Section 182a of Atomic Energy Act that 830105 & 0303 responses to IE Bulletins 82-04 & 83-01, respectively, are true & correct Oath inadvertently omitted.
DIXON, O W South Carolina Electric & Gas Co 83/03/10
O'REILLY, J P Region 2, Office of Director 1p 17636 202 24X
Fiche 50-395, 83/03/10, 8303210659

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc
117pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 121pp 17774 352 24X Fiche 50-000, 83/03/21, 8212060387

8303280100 Responds to IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Maint program conforms to all manufacturer recommendations w/exception of frequency Frequency changed to annual basis.
DIXON, O W South Carolina Electric & Gas Co 83/03/23
O'REILLY, J P Region 2, Office of Director 2pp 17706 359 24X
Fiche 50-395, 83/03/23, 8303280100

8303290585 Discusses status of crack monitoring insp requirements for svc water intake structure review Change to existing license condition proposed to eliminate periodic underwater insp unless differential settlement occurs.
DIRCKS, W J Office of the Executive Director for Operations
83/03/23 PALLADINO, N , GILINSKY, V , AHEARNE, J F Commissioners
2pp 17743 287 24X Fiche 50-395, 83/03/23, 8303290585

8303290745 Requests results of Jan 1983 insp of svc water intake structure to complete evaluation of 821124 proposed amend to OL Reply requested within 10 days of ltr receipt.
NOVAK, T M Assistant Director for Licensing 83/03/24 DIXON, O W South Carolina Electric & Gas Co 2pp 17748 036 24X
Fiche 50-395, 83/03/24, 8303290745

R Periodic operating reports & related correspondence

8303110341 Forwards Technical Rept 82-3, "Seismic Activity Near VC Summer Nuclear Station, Jul-Sept 1982."
DIXON, O W South Carolina Electric & Gas Co 83/03/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17512 307
24X Fiche 50-395, 83/03/07, 8303110341

--8303110343 "Seismic Activity Near VC Summer Nuclear Station, Jul-Sept 1982."
TALWANI, P South Carolina, Univ of 82-3 82/09/30 20pp
17512 308 24X Fiche 50-395, 83/03/07, 8303110341

S Reportable occurrences, LERs & related correspondence

8303010449 Forwards LER 83-008/03L-0 Detailed event analysis encl
DIXON, O W South Carolina Electric & Gas Co 83/02/21
O'REILLY, J P Region 2, Office of Director 2pp 17343 049 24X
Fiche 50-395, 83/02/21, 8303010449

--8303010457 LER 83-008/03L-0 on 830127, main control board indication (PI-486) for steam generator B steam pressure decreased approx 100 psig Caused by plugged transmitter sensing line Line back flushed.
MCKINNEY, C J South Carolina Electric & Gas Co 83/02/21
Region 2, Office of Director 1p 17343 051 24X
Fiche 50-395, 83/02/21, 8303010449

8303010204 Forwards updated LER 83-006/03L-1 Detailed event analysis encl
DIXON, O W South Carolina Electric & Gas Co 83/02/22
O'REILLY, J P Region 2, Office of Director 3pp 17332 347 24X
Fiche 50-395, 83/02/22, 8303010204

--8303010222 Updated LER 83-006/03L-1 on 830113, while in Mode 1, post-accident hydrogen analyzer A declared inoperable due to possible heater failure in sample compartment Caused by inadequately insulated cover Detector cell/wiring replaced.
MCKINNEY, C J South Carolina Electric & Gas Co 83/02/22
Region 2, Office of Director 1p 17332 350 24X
Fiche 50-395, 83/02/22, 8303010204

8303010283 Forwards updated LER 83-002/03L-1 Detailed event analysis encl
DIXON, O W South Carolina Electric & Gas Co 83/02/22
O'REILLY, J P Region 2, Office of Director 2pp 17335 193 24X
Fiche 50-395, 83/02/22, 8303010283

--8303010291 Updated LER 83-002/03L-1 on 830109, main vent exhaust sys flow rate indication failed low Caused by corrosion on fuse block or card edge connector of mixing amplifier circuit board Circuit board components cleaned.
MCKINNEY, C J South Carolina Electric & Gas Co 83/02/22
Region 2, Office of Director 1p 17335 195 24X
Fiche 50-395, 83/02/22, 8303010283

8303010461 Forwards updated LER 83-005/03L-1 Detailed event analysis encl
DIXON, O W South Carolina Electric & Gas Co 83/02/22
O'REILLY, J P Region 2, Office of Director 2pp 17343 276 24X
Fiche 50-395, 83/02/22, 8303010461

--8303010474 Updated LER 83-005/03L-1 on 830112, during performance of operational test, fire detector zone DDD in svc water pumphouse failed to reset Caused by grounded smoke detector Ground head properly reinstalled.
MCKINNEY, C J South Carolina Electric & Gas Co 83/02/22
Region 2, Office of Director 1p 17343 278 24X
Fiche 50-395, 83/02/22, 8303010461

8303010495 Forwards updated LER 83-007/03L-1 Detailed event analysis encl
DIXON, O W South Carolina Electric & Gas Co 83/02/22
O'REILLY, J P Region 2, Office of Director 3pp 17343 335 24X
Fiche 50-395, 83/02/22, 8303010495

--8303010507 Updated LER 83-007/03L-1 on 830124, inspector identified discrepancy of 9% between main control board & control room evacuation panel indication for pressurizer relief tank level Caused by instrument drift Transmitter calibr.
MCKINNEY, C J South Carolina Electric & Gas Co 83/02/21
Region 2, Office of Director 1p 17343 338 24X
Fiche 50-395, 83/02/22, 8303010495

8303010556 Forwards updated LER 83-001/01T-1 Detailed event analysis encl
DIXON, O W South Carolina Electric & Gas Co 83/02/22
O'REILLY, J P Region 2, Office of Director 4pp 17337 185 24X
Fiche 50-395, 83/02/22, 8303010556

--8303010566 Updated LER 83-001/01T-1 on 830119, three refueling water storage tank level transmitters failed high Caused by transmitter base freezing Transmitters thawed Insulated encls & addl permanent heat trace will be installed.
MCKINNEY, C J South Carolina Electric & Gas Co 83/02/22
Region 2, Office of Director 1p 17337 189 24X
Fiche 50-395, 83/02/22, 8303010556

8303040367 Forwards LER 83-004/03L-0. Detailed event analysis encl.
DIXON, O.W. South Carolina Electric & Gas Co. 83/02/23.
O'REILLY, J.P. Region 2, Office of Director. 2pp. 17420:016. 24X
Fiche: 50-395, 83/02/23, 8303040367.

--8303040376 LER 83-004/03L-0 on 830109, during Mode 1 operation, spurious inadequate core cooling alarms received on Channel B of RCS subcooling margin monitor. Cause unknown. Channel de-energized then re-energized normally.
MCKINNEY, C.J. South Carolina Electric & Gas Co. 83/02/23.
Region 2, Office of Director. 1p. 17420:018. 24X
Fiche: 50-395, 83/02/23, 8303040367.

8303040553 Forwards LER 83-009/03L-0. Detailed event analysis encl.
DIXON, O.W. South Carolina Electric & Gas Co. 83/02/23.
O'REILLY, J.P. Region 2, Office of Director. 2pp. 17367:331. 24X
Fiche: 50-395, 83/02/23, 8303040553.

--8303040565 LER 83-009/03L-0 on 830203, main control board indicator (PI-950) for reactor bldg pressure failed low. Caused by intermittent pressure transmitter failure. Transmitter output returned to normal.
MCKINNEY, C.J. South Carolina Electric & Gas Co. 83/02/23.
Region 2, Office of Director. 1p. 17367:333. 24X
Fiche: 50-395, 83/02/23, 8303040553.

8303150341 Forwards LER 83-010/03L-0. Detailed event analysis encl.
DIXON, O.W. South Carolina Electric & Gas Co. 83/03/04.
O'REILLY, J.P. Region 2, Office of Director. 2pp. 17563:108. 24X
Fiche: 50-395, 83/03/04, 8303150341.

--8303150347 LER 83-010/03L-0 on 830206, only one isotopic Iodine analysis performed during power reduction from 50% to 5% Caused by personnel misinterpreting power changes Chemistry lab policy issued re need for analysis.
FIELDS, H.C. South Carolina Electric & Gas Co. 83/03/04. Region 2, Office of Director. 1p. 17563:110. 24X Fiche: 50-395, 83/03/04, 8303150341.

8303180258 Forwards LER 83-011/03L-0. Detailed event analysis encl.
DIXON, O.W. South Carolina Electric & Gas Co. 83/03/09.
O'REILLY, J.P. Region 2, Office of Director. 3pp. 17616:174. 24X
Fiche: 50-395, 83/03/09, 8303180258.

--8303180268 LER 83-011/03L-0 on 830208 & 17, during Mode 1 operation, nuclear sampling sys valves 9398 A, B & C failed to close. Caused by limit switch failure on one valve & crud buildup on other valve seats. Crud dislodged. Limit switches repaired.
MCKINNEY, C.J. South Carolina Electric & Gas Co. 83/03/09.
Region 2, Office of Director. 1p. 17616:177. 24X
Fiche: 50-395, 83/03/09, 8303180258.

8303180238 Forwards LER 83-012/03L-0. Detailed event analysis encl.
DIXON, O.W. South Carolina Electric & Gas Co. 83/03/10.
O'REILLY, J.P. Region 2, Office of Director. 2pp. 17621:118. 24X
Fiche: 50-395, 83/03/10, 8303180238.

--8303180241 LER 83-012/03L-0 on 830210, flow indicator for steam generator A feedwater flow FI-477 failed low. Caused by failure of power supply FQY-477. Circuit board replaced.
MCKINLEY, C.J. South Carolina Electric & Gas Co. 83/03/10.
Region 2, Office of Director. 1p. 17621:120. 24X
Fiche: 50-395, 83/03/10, 8303180238.

8303180229 Forwards LER 83-013/03L-0. Detailed event analysis encl.
DIXON, O.W. South Carolina Electric & Gas Co. 83/03/11.
O'REILLY, J.P. Region 2, Office of Director. 3pp. 17621:137. 24X
Fiche: 50-395, 83/03/11, 8303180229.

--8303180234 LER 83-013/03L-0 on 830113 & 19, condensate storage tank level transmitters LT-3631 & LT-3631A failed due to frozen instrument lines. Caused by temp sensing element not being located per design specs. Element relocated.
MCKINNEY, C.J. South Carolina Electric & Gas Co. 83/03/11.
Region 2, Office of Director. 1p. 17621:140. 24X
Fiche: 50-395, 83/03/11, 8303180229.

8303220063 PNO-II-83-012 on 830311, malfunction of undetermined cause activated four emergency warning sys sirens for 3 minutes. No emergency at plant evident. Cause under investigation. Local media interest occurred.
ROGGE, J.F., BROWNLEE, V.L. Region 2, Office of Director. 83/03/14. 1p. 17652:265. 24X Fiche: 50-395, 83/03/14, 8303220063.

8303240530 Forwards LER 83-015/03L-0. Detailed event analysis encl.
DIXON, O.W. South Carolina Electric & Gas Co. 83/03/17.
O'REILLY, J.P. Region 2, Office of Director. 2pp. 17682:286. 24X
Fiche: 50-395, 83/03/17, 8303240530.

--8303240539 LER 83-015/03L-0 on 830219, while in Mode 1, 5% discrepancy observed between main control board & control room evacuation panel indication for pressurizer relief tank level. Caused by design error. New transmitter installed.
MCKINNEY, C.J. South Carolina Electric & Gas Co. 83/03/17.
Region 2, Office of Director. 1p. 17682:288. 24X
Fiche: 50-395, 83/03/17, 8303240530.

8303240583 Forwards LER 83-016/03L-0. Detailed event analysis encl.
DIXON, O.W. South Carolina Electric & Gas Co. 83/03/17.
O'REILLY, J.P. Region 2, Office of Director. 2pp. 17683:135. 24X
Fiche: 50-395, 83/03/17, 8303240583.

--8303240592 LER 83-016/03L-0 on 830216, w/plant in Mode 1, discrepancy of 6% observed between main control board indicators for sodium hydroxide storage tank level. Caused by loose fitting on high side sensing line of level transmitter.
MCKINNEY, C.J. South Carolina Electric & Gas Co. 83/03/17.
Region 2, Office of Director. 1p. 17683:137. 24X
Fiche: 50-395, 83/03/17, 8303240583.

8303240585 Forwards LER 83-014/03L-0. Detailed event analysis encl.
DIXON, O.W. South Carolina Electric & Gas Co. 83/03/17.
O'REILLY, J.P. Region 2, Office of Director. 2pp. 17683:119. 24X
Fiche: 50-395, 83/03/17, 8303240585.

--8303240595 LER 83-014/03L-0 on 830217 & 0303, pressurizer PORV PCV-4458 found leaking. Events discovered by high temp indication in PORV discharge piping. Cause unknown. Valve will remain closed & be disassembled during 830317 outage.
FIELDS, H.C. South Carolina Electric & Gas Co. 83/03/17. Region 2, Office of Director. 1p. 17683:121. 24X Fiche: 50-395, 83/03/17, 8303240585.

8303240596 Forwards updated LER 83-008/03L-1. Detailed event analysis encl.
DIXON, O.W. South Carolina Electric & Gas Co. 83/03/17.
O'REILLY, J.P. Region 2, Office of Director. 2pp. 17683:069. 24X
Fiche: 50-395, 83/03/17, 8303240596.

--8303240600 Updated LER 83-008/03L-1 on 830127, w/plant in Mode 1, main control board indication for steam generator B steam pressure decreased approx 100 psig. Caused by plugged transmitter sensing line. Sensing line back flushed.
MCKINNEY, C.J. South Carolina Electric & Gas Co. 83/03/17.
Region 2, Office of Director. 1p. 17683:071. 24X
Fiche: 50-395, 83/03/17, 8303240596.

8303240561 PNO-II-83-013: reactor shut down for scheduled outage in order to modify steam generators. Mods involve installation of flow diffuser on cold leg side within preheater section to reduce excitation of generator tubes from high velocity.
BUTCHER, R.C., CANTRELL, F.S. Region 2, Office of Director. 83/03/21. 2pp. 17683:195. 24X Fiche: 50-395, 83/03/21, 8303240561.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D.G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2

A. Application/construction stage documents & correspondence

8303010649 Confirms 830113 telcon re NUREG-0803, Question 010.066 concerning capability of curbed area around control rod drive (CRD) line piping to contain water from CRD line break. Vol within curbed area can retain vol of 160 ft cubed.
BOUCHEY, G.D. Washington Public Power Supply System. 83/02/03.
SCHWENCER, A. Licensing Branch 2. 1p. 17336:246. 24X
Fiche: 50-397, 83/02/03, 8303010649.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D.G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303040482 Submits changes to 821004 submittal of Rev 1 to "Control of Heavy Loads." Safe load path for cattle chute will be shown in Plant Procedure 10.3.5.
BOUCHEY, G.D. Washington Public Power Supply System. 83/02/23.
SCHWENCER, A. Licensing Branch 2. 3pp. 17374:010. 24X
Fiche: 50-397, 83/02/23, 8303040482.

8303040607 Responds to NRC Question 010.068 re secondary missile generation resulting from spalling & scabbing of concrete walls & barriers upon impact by credible plant missiles. Survey indicates no secondary missiles can be generated.
BOUCHEY, G. D. Washington Public Power Supply System 83/02/23
SCHWENCER, A. Licensing Branch 2 2pp 17374 222 24X
Fiche: 50-397, 83/02/23, 8303040607

8303070138 Advises that rev to FSAR Chapter 11, Section 11.4, "Utilization of Interim Portable Solid Radwaste Solidification Sys," will be submitted after fuel load.
BOUCHEY, G. D. Washington Public Power Supply System 83/02/25
SCHWENCER, A. Licensing Branch 2 1p 17432 346 24X
Fiche: 50-397, 83/02/25, 8303070138

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700 303 24X
Fiche: 50-000, 83/03/02, 8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp 17660 176 24X
Fiche: 50-000, 83/03/07, 8303040005

8303140009 Notification of 830310 meeting w/util in Bethesda, MD to discuss applicant estimated plant completion date.
AULUCK, R. Licensing Branch 2 83/03/08 SCHWENCER, A. Licensing Branch 2 4pp 17548 221 24X Fiche: 50-397, 83/03/08, 8303140009

8303240220 Forwards rewrite of FSAR Section 3.9, "New Loads," which will be incorporated into FSAR Amend 29.
BOUCHEY, G. D. Washington Public Power Supply System 83/03/08
SCHWENCER, A. Licensing Branch 2 201pp 17680 121 24X
Fiche: 50-397, 83/03/08, 8303240220

P8303160290 Forwards "Rept of Audit of WPPSS Plant Verification Program for WA Nuclear Plant Unit 2."
BOUCHEY, G. D. Washington Public Power Supply System 83/03/10
SCHWENCER, A. Licensing Branch 2 1p 17596 187 24X
Fiche: 50-397, 83/03/10, 8303160290

8303230434 Notification of 830329 meeting w/util in Bethesda, MD to discuss justification for interim operation re environ equipment qualification.
AULUCK, R. Licensing Branch 2 83/03/14 SCHWENCER, A. Licensing Branch 4 3pp 17674 140 24X Fiche: 50-397, 83/03/14, 8303230434

8303220057 Confirms discussions w/Mechanical Engineering Branch re installation sequence for pipe whip restraint.
BOUCHEY, G. D. Washington Public Power Supply System 83/03/15
SCHWENCER, A. Licensing Branch 2 2pp 17652 270 24X
Fiche: 50-397, 83/03/15, 8303220057

8303210017 Advises that probability of unacceptable damage to safety-related sys & components due to turbine missiles acceptably low provided turbine missile generation probability maintained for life of plant by acceptable maint program.
SCHWENCER, A. Licensing Branch 2 83/03/16 FERGUSON, R. L. Washington Public Power Supply System 2pp 17660 071 24X
Fiche: 50-397, 83/03/16, 8303210017

8303290105 Notification of 830405-06 meetings w/util in Richland, WA to discuss electrical cable separation issue & conduct site audit.
AULUCK, R. Licensing Branch 2 83/03/17 SCHWENCER, A. Licensing Branch 2 3pp 17729 203 24X Fiche: 50-397, 83/03/17, 8303290105

8303290401 Forwards draft ETS re instrumentation & radioactive effluents.
BOUCHEY, G. D. Washington Public Power Supply System 83/03/18
SCHWENCER, A. Licensing Branch 2 64pp 17726 015 24X
Fiche: 50-397, 83/03/18, 8303290401

E. NRC Safety Evaluation Report (SER), supplS & correspondence

8303010357 Forwards "Applicability of Use of Square-Root-of-Sum-of-Square (SRSS) Method for Combining Peak Dynamic Responses for WA Nuclear Plant 2," per 821103 ltr. Rept satisfies NUREG-0892 SER Confirmatory Item 6.
BOUCHEY, G. D. Washington Public Power Supply System 83/02/03
SCHWENCER, A. Licensing Branch 2 1p 17346 037 24X
Fiche: 50-397, 83/02/03, 8303010357

--8303010362 "Applicability of Use of Square-Root-of-Sum-of-Squares (SRSS) Method for Combining Peak Dynamic Responses for WA Nuclear Plant 2."
DEFELICE, N., NG, L., BEDROSIAN, B. Burns & Roe Co. 83/01/26
130pp. 17346 038 24X Fiche: 50-397, 83/02/03, 8303010357.

8303040397 Commits to modifying design such that motor operated valves at standby svc water pumphouse are directly connected to motor control ctr in radwaste bldg per NUREG-0892, SER Outstanding Issue 10.
BOUCHEY, G. D. Washington Public Power Supply System 83/02/23
SCHWENCER, A. Licensing Branch 2 4pp 17426 241 24X
Fiche: 50-397, 83/02/23, 8303040397

8303010234 Forwards supporting documentation & response to NRC 820916 request for addl info & NUREG-0892 SER Outstanding Issue 26, "Operability of Purge Valves." Submittal also confirms discussions w/R. Auluck during PVORT audit in Nov 1982.
BOUCHEY, G. D. Washington Public Power Supply System 83/02/24
SCHWENCER, A. Licensing Branch 2 80pp 17334 087 24X
Fiche: 50-397, 83/02/24, 8303010234

8303300262 Forwards request for addl info needed to close out SER confirmatory item re component support design. Response requested by 830415 to maintain licensing schedule.
SCHWENCER, A. Licensing Branch 2 83/03/23 FERGUSON, R. L. Washington Public Power Supply System 3pp 17748 344 24X
Fiche: 50-397, 83/03/23, 8303300262

F. Security, medical, emergency & fire protection plans

8303110089 Ack receipt of 821022 ltr re amend of Condition 3 of 820817 supplemental physical security conditions for 820716 fuel storage physical security plan. Revised commitment acceptable. Encl withheld (ref 10CFR2.790(d)).
EVANS, L. J. Fuel Facility Safeguards Licensing Branch 82/11/10
BOUCHEY, G. D. Washington Public Power Supply System 1p 17526 280 24X Fiche: 50-397, 82/11/10, 8303110089

8303070154 Discusses fire hose & standpipe mods. Meeting scheduled for 830304 will present position that current sys provides fully satisfactory implementation of App. R requirements.
BOUCHEY, G. D. Washington Public Power Supply System 83/02/24
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp
17430 343 24X Fiche: 50-397, 83/02/24, 8303070154

8303030094 Notification of 830304 meeting w/util in Bethesda, MD to discuss fire hose standpipe mods.
AULUCK, R. Licensing Branch 2 83/02/25 SCHWENCER, A. Licensing Branch 2 3pp 17365 293 24X Fiche: 50-397, 83/02/25, 8303030094

8303170278 Forwards emergency plan implementing procedures EPIP 13.1.1, "Classification of Emergency," will be submitted by 830315. W/o stated encl.
BOUCHEY, G. D. Washington Public Power Supply System 83/03/01
SCHWENCER, A. Licensing Branch 2 1p 17606 052 24X
Fiche: 50-397, 83/03/01, 8303170278

8303090015 Notification of 830314 meeting w/util in Richland, WA to conduct physical security program confirmatory site visit. Meeting closed (ref 10CFR73.55).
AULUCK, R. Licensing Branch 2 83/03/02 SCHWENCER, A. Licensing Branch 2 3pp 17466 178 24X Fiche: 50-397, 83/03/02, 8303090015

8303140602 Advises that mod to restricted area boundary acceptable, in response to util 830127 ltr.
NOVAK, T. M. Assistant Director for Licensing 83/03/04
FERGUSON, R. L. Washington Public Power Supply System 2pp
17548 341 24X Fiche: 50-397, 83/03/04, 8303140602

8303160427 Forwards info presented at 830304 meeting in Bethesda, MD re fire hose/standpipe mod. Encl info provides technical basis for acceptance of current manual fire suppression sys design.
BOUCHEY, G. D. Washington Public Power Supply System 83/03/04
SCHWENCER, A. Licensing Branch 2 20pp 17592 233 24X
Fiche: 50-397, 83/03/04, 8303160427

8303160033 Advises that fire hose/standpipe mods unnecessary. Present sys adequate to implement 10CFR50, App. R.
SCHWENCER, A. Licensing Branch 2 83/03/09 FERGUSON, R. L. Washington Public Power Supply System 2pp 17615 040 24X
Fiche: 50-397, 83/03/09, 8303160033

9. Adjudicatory correspondence

8303030692 Informs that on 830222 ASLB denied Coalition for Safe Power request for hearing.Petition to intervene denied on grounds that petitioner failed to set forth contention within scope of proceeding.
AULUCK, R. Licensing Branch 2. 83/02/28. DENTON, H. R.; CASE, E. G.; CARTER, J. Office of Nuclear Reactor Regulation, Director. 1p. 17364:019. 24X Fiche: 50-397, 83/02/28, 8303030692.

8303180331 Notice of appeal of ASLB 830222 memorandum & order on issue of util delay.
BELL, N. Coalition for Safe Power. 83/03/10. 1p. 17619:334. 24X Fiche: 50-397, 83/03/10, 8303180331.

--8303180344 Brief supporting appeal from ASLB 830222 memorandum & order. ASLB erred in concluding petitioner failed to show dilatory conduct by util & was not entitled to hearing on CP extension.Certificate of Svc encl.
BELL, N. Coalition for Safe Power. 83/03/10. Atomic Safety and Licensing Appeal Panel. 5pp. 17619:335. 24X Fiche: 50-397, 83/03/10, 8303180331.

8303170435 Notice of ASLAB constitution: SF Eilperin, chairman & CN Kohl & RL Gotchy, members.
SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 83/03/15. 1p. 17610:360. 24X Fiche: 50-397, 83/03/15, 8303170435.

8303280119 Brief in opposition to Coalition for Safe Power 830310 appeal from ASLB 830222 memorandum & order denying petition to intervene.Request for hearing correctly denied for failure to particularize contention.Certificate of Svc encl.
PATON, W. D. Hearing Branch 2. 83/03/25. Atomic Safety and Licensing Appeal Panel. 11pp. 17709:351. 24X Fiche: 50-397, 83/03/25, 8303280119.

K. Utility Final Safety Analysis Report (FSAR) & amends

8303010684 Forwards Amend 28 to FSAR.
BOUCHEY, G. D. Washington Public Power Supply System. 83/02/15.
SCHWENCER, A. Licensing Branch 2. 2pp. 17341:213. 24X
Fiche: 50-397, 83/02/15, 8303010684.

--8303010688 Amend 28 to FSAR.
* Washington Public Power Supply System. 83/01/31. 402pp.
17341:215. 24X Fiche: 50-397, 83/02/15, 8303010684.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8303170277 Proposed summary of ACRS WPPSS-2 Subcommittee 820902-03 meetings in Richland, WA re OL application.
* ACRS - Advisory Committee on Reactor Safeguards. 82/09/29.
ACRS - Advisory Committee on Reactor Safeguards. 14pp. 17623:320.
24X Fiche: 50-397, 82/09/29, 8303170277.

Q. Inspection reports, IE Bulletins & correspondence

8303010129 Transmits preservice insp drawings for scram discharge piping per NRC request.Boundary diagram & supply sys exam requirements for piping forwarded by 820922 ltr.
BOUCHEY, G. D. Washington Public Power Supply System. 83/02/03.
SCHWENCER, A. Licensing Branch 2. 7pp. 17345:027. 24X
Fiche: 50-397, 83/02/03, 8303010129.

8303040451 Forwards IE Insp Rept 50-397/83-04 on 830101-31. No noncompliance noted.
STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 83/02/15. MATLOCK, R. G. Washington Public Power Supply System. 2pp. 17366:191. 24X Fiche: 50-397, 83/02/15, 8303040451.

--8303040461 IE Insp Rept 50-397/83-04 on 830101-31. No noncompliance noted. Major areas inspected: preoperational test witnessing & independent insp effort.
FEIL, R. A.; DODDS, R. T. Division of Resident, Reactor Project & Engineering Programs. 83/02/14. 4pp. 17366:193. 24X
Fiche: 50-397, 83/02/15, 8303040451.

8303040366 Forwards IE Insp Rept 50-397/83-03 on 830101-31 & notice of deviation.
STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 83/02/18. MATLOCK, R. G. Washington Public Power Supply System. 2pp. 17420:023. 24X Fiche: 50-397, 83/02/18, 8303040366.

--8303040371 Notice of deviation from insp on 830101-31.
DODDS, R. T. Division of Resident, Reactor Project & Engineering Programs. 83/02/18. 1p. 17420:025. 24X Fiche: 50-397, 83/02/18, 8303040366.

--8303040377 IE Insp Rept 50-397/83-03 on 830101-31. Noncompliance noted: task force failed to resolve issues re record discrepancy for welding on valve SW-V-718 body.
TOTH, A. D.; DODDS, R. T. Division of Resident, Reactor Project & Engineering Programs. 83/02/17. 20pp. 17420:026. 24X
Fiche: 50-397, 83/02/18, 8303040366.

8303150492 Forwards IE Insp Rept 50-397/83-01 on 830103-07. No noncompliance noted.
STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 83/02/24. MATLOCK, R. G. Washington Public Power Supply System. 2pp. 17560:334. 24X Fiche: 50-397, 83/02/24, 8303150492.

--8303150501 IE Insp Rept 50-397/83-01 on 830103-07. No noncompliance noted. Major areas inspected: preoperational test records, operating staff training, safety committee activities & followups of open items & IE bulletin/circular.
WILLETT, D. J.; DODDS, R. T. Division of Resident, Reactor Project & Engineering Programs. 83/02/24. 5pp. 17560:336. 24X
Fiche: 50-397, 83/02/24, 8303150492.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303080203 Forwards IE Mgt Meeting Rept 50-397/83-06 on 830208. No noncompliance noted.
STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 83/03/02. MAZUR, D. W. Washington Public Power Supply System. 2pp. 17457:070. 24X Fiche: 50-397, 83/03/02, 8303080203.

--8303080210 IE Mgt Meeting Rept 50-397/83-06 on 830208. No noncompliance noted. Major areas discussed: status of startup program, operational program, quality & safety assurance programs & engineering transition phase.
WILLETT, D. J.; DODDS, R. T.; FEIL, R. A. Division of Resident, Reactor Project & Engineering Programs. 83/03/01. 3pp. 17457:072. 24X
Fiche: 50-397, 83/03/02, 8303080203.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

S. Reportable occurrences, LERs & related correspondence

8303280156 Part 21 rept re section modules error in ALDPIPE. Initially reported on 830128. Error exists in ALDPIPE pipe stress analysis program where section modules used for stresses in reduced branch outlets. Study underway.
LAGERAAEN, A. J. Burns & Roe Co. 83/01/28. COLLINS, J. P. Region 4, Office of Director. 2pp. 17708:022. 24X Fiche: 50-397, 83/01/28, 8303280156.

8303280225 Part 21 Rept 82-12 re ALDPIPE Deficiency subsequently finalized & determined not reportable.Final engineering rept, "Evaluation of ALDPIPE Deficiency on Completed Stress Analysis," encl.
LAGERAAEN, A. Burns & Roe Co. 83/02/01. COLLINS, J. P. Region 4, Office of Director. 1p. 17708:223. 24X Fiche: 50-397, 83/02/01, 8303280225.

--8303280233 Rev 1 to "Evaluation of ALDPIPE Deficiency on Completed Stress Analysis."
CHU, A.; STUDNICKA, Z.; MICHEJDA, O. Burns & Roe Co. 82/12/31. 71pp. 17708:224. 24X Fiche: 50-397, 83/02/01, 8303280225.

8303010569 Forwards final deficiency repts re skewed T joints & interim deficiency repts re RHR relief valve vents & LPCS & RHR support pin receptacles.
MATLOCK, R. G. Washington Public Power Supply System. 83/02/18.
ENGELKEN, R. H. Region 5, Office of Director. 1p. 17341:099. 24X
Fiche: 50-397, 83/02/18, 8303010569.

--8303010577 Final deficiency rept re skewed T joint welds. Insp sampling plan established to randomly select & verify weld size of skewed angle welds performed by Bechtel. Condition determined nonreportable based on results of program.
* Washington Public Power Supply System 83/02/18 1p
17341:100 24X Fiche: 50-397, 83/02/18, 8303010569.

--8303010582 Interim deficiency rept re RHR relief valve vents. Crosby Valve & Gauge Co indicated that valve can be converted. Supply Sys & Burns & Roe Engineering implementing mods. Next rept will be submitted by 830517.
* Washington Public Power Supply System 83/02/18 3pp
17341:101 24X Fiche: 50-397, 83/02/18, 8303010569.

--8303010589 Interim deficiency rept re LPCS & RHR support pin receptacles AE & QE reviewing alternatives other than complete pump removal to effect pin receptacle installation. Next rept will be submitted by 830517.
* Washington Public Power Supply System 83/02/18 1p
17341:104 24X Fiche: 50-397, 83/02/18, 8303010569.

8303040253 Final Deficiency Rept 190 re excessive cable length causing voltage drop. Initially reported on 820511. Control power transformer increased from 300 VA to 500 VA to preclude voltage drop.
MATLOCK, R. G. Washington Public Power Supply System 83/02/22
ENGELKEN, R. H. Region 5, Office of Director 3pp 17421:350 24X
Fiche: 50-397, 83/02/22, 8303040253.

8303080011 Final deficiency rept on Conditions 208, 209, 223 & 229 re remote shutdown panel, RHR & LPCS pump discharge pressure switches, standby liquid control sys & missing hangers in turned over HPCS Sys 7.1, respectively. Next rept due 830523.
MATLOCK, R. G. Washington Public Power Supply System 83/02/25
ENGELKEN, R. H. Region 5, Office of Director 9pp 17436:344 24X
Fiche: 50-397, 83/02/25, 8303080011.

8303140633 Final deficiency rept re damage to electrical cable 2SMB-0080 during installation of Thermo Lag fire resistant matl (Condition 235). Initially reported on 830204. Damaged cable repaired. Condition not reportable per 10CFR50.55(e).
MATLOCK, R. G. Washington Public Power Supply System 83/03/03
ENGELKEN, R. H. Region 5, Office of Director 3pp 17533:286 24X
Fiche: 50-397, 83/03/03, 8303140633.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated
Edison Co. of New York, Inc. 18pp 24X Fiche: 50-000, 83/02/24, 8302250505.

8303090172 Provides formal notification re schedule for operator licensing exams, per 830111 Generic Ltr 83-01.
BOUCHEY, G. D. Washington Public Power Supply System 83/03/04
EISENHUT, D. G. Division of Licensing 2pp 17471:325 24X
Fiche: 50-397, 83/03/04, 8303090172.

DOCKET 50-400 (SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1)

A. Application/construction stage documents & correspondence

8303010723 Forwards revised table clarifying licensing schedule. Fuel load dates for Units 1 & 2 scheduled for June 1985 & June 1989, respectively. Other licensing milestones applicable to both units.
NOVAK, T. M. Assistant Director for Licensing 83/02/09 UTLEY, E. E.
Carolina Power & Light Co. 3pp 17348:299 24X
Fiche: 50-400, 83/02/09, 8303010723.

8303030274 Notification of 830228 meeting w/applicant in Bethesda, MD to discuss postulated Neuse fault, rev of USGS position & seismic monitoring instrumentation.
KADAMBI, N. P. Licensing Branch 3 83/02/10 KNIGHTON, G. W.
Licensing Branch 3 3pp 17365:240 24X Fiche: 50-400, 83/02/10, 8303030274.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated
Edison Co. of New York, Inc. 18pp 17492:033 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303030283 Notification of 830307-11 meetings w/applicant & Ebasco in New York, NY to discuss structural design for seismic Category I structures & implementation of FSAR design criteria.
KADAMBI, N. P. Licensing Branch 3 83/02/22 KNIGHTON, G. W.
Licensing Branch 3 3pp 17365:233 24X Fiche: 50-400, 83/02/22, 8303030283.

8303030703 Notification of 830307 meeting w/utils & NUS Corp in Bethesda, MD to discuss proposed rev to 10CFR40, Appendix A (Tech Specs).
BRINKMAN, D. S. Standardization & Special Projects Branch 83/02/22
THOMAS, C. O. Standardization & Special Projects Branch 2pp
17363:227 24X Fiche: 50-000, 83/02/22, 8303030703.

8303070166 Forwards source term evaluation for vol reduction sys.
ZIMMERMAN, S. R. Carolina Power & Light Co. 83/02/24 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 11pp 17433:112
24X Fiche: 50-400, 83/02/24, 8303070166.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated
Edison Co. of New York, Inc. 17pp 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated
Edison Co. of New York, Inc. 5pp 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303230101 Notification of 830325 meeting w/util in Bethesda, MD to discuss info re current control room design & documentation status.
KADAMBI, N. P. Licensing Branch 3 83/03/08 KNIGHTON, G. W.
Licensing Branch 3 3pp 17687:157 24X Fiche: 50-400, 83/03/08, 8303230101.

8303230346 Summary of 830228 meeting w/util in Bethesda, MD re seismic monitoring instrumentation & postulated Neuse fault & to exchange info on USGS re-evaluation of implications of Charleston earthquake.
KADAMBI, N. P. Licensing Branch 3 83/03/09 Licensing Branch 3
6pp 17675:275 24X Fiche: 50-400, 83/03/09, 8303230346.

8303160556 Requests to be included in 1984 schedule for aerial gamma spectral mapping to determine radiological anomalies of environ prior to operation.
HURFORD, W. J. Carolina Power & Light Co. 83/03/14 DEYOUNG, R. C.
Director's Office, Office of Inspection and Enforcement 1p
17587:268 24X Fiche: 50-400, 83/03/14, 8303160556.

8303220164 Forwards minutes of 830201-03 meetings w/Mechanical Engineering Branch to respond to questions transmitted in 821222 ltr. Responses committing to FSAR change will be incorporated into future amend.
MCDUFFIE, M. A. Carolina Power & Light Co. 83/03/16 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 74pp 17658:167
24X Fiche: 50-400, 83/03/16, 8303220164.

8303310654 Requests arrangements be made for Geotechnical Engineering Section 830415-17 site visit & audit.
KNIGHTON, G. W. Licensing Branch 3 83/03/16 UTLEY, E. E. Carolina
Power & Light Co. 9pp 17780:308 24X Fiche: 50-400, 83/03/16, 8303310654.

8303310666 Advises of discrepancy between FSAR Sections 4.3 & 15.6 re LOCA peaking factor. Peaking factor control, analysis & surveillance or power reduction remain open FSAR items.
KNIGHTON, G. W. Licensing Branch 3 83/03/24 UTLEY, E. E. Carolina
Power & Light Co. 3pp 17780:301 24X Fiche: 50-400, 83/03/24, 8303310666.

C. Utility Environmental Report (ER), amends & correspondence

8303280040 Forwards revised environ rept Tables 3.3-1 & 3.6.2-2, P 3.6-2, table of waste discharge rates to cooling tower blowdown, in response to NRC request.
ZIMMERMAN, S. R. Carolina Power & Light Co. 83/03/21 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 11pp 17707:218
24X Fiche: 50-400, 83/03/21, 8303280040.

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303010727 Forwards draft SER identifying incomplete info & disagreement of approach. Timely submittals required to resolve all items by SER Nov 1983 issue date. W/o encl.
KNIGHTON, G. W. Licensing Branch 3 83/02/01 UTLEY, E. E. Carolina Power & Light Co. 2pp. 17347.359 24X Fiche: 50-400, 83/02/01, 8303010727.

Q. Adjudicatory correspondence

8303030469 Memorandum amending svc list.
MILLER, R. G. Atomic Safety and Licensing Board Panel 83/03/01 1p. 17409.334 24X Fiche: 50-400, 83/03/01, 8303030469.

8303070116 Forwards NRC & applicant briefs in Catawba proceeding re contentions based on new info disclosed in documents generated after time to file contentions, in response to ASLB 830224 request. W/o encl.
BARTH, C. A. Hearing Branch 1 83/03/03 PAYNE, T. Affiliation Unknown NEWMAN, P. T. Citizens Against Nuclear Power RUNKLE, J. Conservation Council of North Carolina 2pp. 17433.069 24X Fiche: 50-400, 83/03/03, 8303070116.

8303140269 Response to interrogatories & request for production of documents. Certificate of Svc encl. Related correspondence.
WILSON, R. Wilson, R. 83/03/03 Carolina Power & Light Co. 6pp. 17535.117 24X Fiche: 50-400, 83/03/03, 8303140269.

8303110193 Revised proposed schedule for adjudication of issues for remainder of proceeding. Rev reflects areas of agreement & compromise reached during 830224 prehearing conference. Certificate of Svc encl.
O'NEILL, J. H. Carolina Power & Light Co. O'NEILL, J. H. North Carolina Municipal Power Agencies 83/03/08 9pp. 17520.129 24X Fiche: 50-400, 83/03/08, 8303110193.

8303110209 Notice of appearance in proceeding.
ANDERSON, P. H. Carolina Power & Light Co. ANDERSON, P. H. Shaw, Pittman, Potts & Trowbridge 83/03/08 1p. 17515.097 24X Fiche: 50-400, 83/03/08, 8303110209.

8303110211 Notice of appearance in proceeding.
BAUSER, D. B. Carolina Power & Light Co. BAUSER, D. B. Shaw, Pittman, Potts & Trowbridge 83/03/08 1p. 17519.293 24X Fiche: 50-400, 83/03/08, 8303110211.

8303110213 Notice of appearance in proceeding.
CARROW, B. B. Carolina Power & Light Co. 83/03/08 1p. 17519.294 24X Fiche: 50-400, 83/03/08, 8303110213.

8303140252 First set of interrogatories & request for production of documents.
BAUSER, D. B. Carolina Power & Light Co. BAUSER, D. B. Shaw, Pittman, Potts & Trowbridge 83/03/09 Citizens Against Nuclear Power 21pp. 17544.060 24X Fiche: 50-400, 83/03/09, 8303140252.

--8303140258 Second set of interrogatories & request for production of documents.
BAUSER, D. B. Carolina Power & Light Co. BAUSER, D. B. Shaw, Pittman, Potts & Trowbridge 83/03/09 Eddleman, W. 11pp. 17544.081 24X Fiche: 50-400, 83/03/09, 8303140252.

--8303140262 Second set of interrogatories & request for production of documents to Joint Intervenors.
BAUSER, D. B. Carolina Power & Light Co. BAUSER, D. B. Shaw, Pittman, Potts & Trowbridge 83/03/09 Chapel Hill Anti-Nuclear Group Effort 13pp. 17544.092 24X Fiche: 50-400, 83/03/09, 8303140252.

--8303140266 Second set of interrogatories & request for production of documents. Certificate of Svc encl.
BAUSER, D. B. Carolina Power & Light Co. BAUSER, D. B. Shaw, Pittman, Potts & Trowbridge 83/03/09 Wilson, R. 10pp. 17544.105 24X Fiche: 50-400, 83/03/09, 8303140252.

8303140214 Forwards NRC papers re $600,000 civil penalty imposed upon applicant for violations at Brunswick facilities. Info relevant to mgt capability & QA/QC issues.
BARTH, C. A. Hearing Branch 1 83/03/10 KELLEY, J. L. ; BRIGHT, G. O. ; CARPENTER, J. H. Atomic Safety and Licensing Board Panel 31pp. 17539.306 24X Fiche: 50-400, 83/03/10, 8303140214.

8303140279 Memorandum & order reflecting decisions made following 830224 second prehearing conference in Raleigh, NC. Decisions concern scheduling, discovery guidelines & rulings on related matters.
KELLEY, J. L. ; CARPENTER, J. H. ; BRIGHT, G. O. Atomic Safety and Licensing Board Panel 83/03/10 41pp. 17535.064 24X Fiche: 50-400, 83/03/10, 8303140279.

8303150397 Response to first set of interrogatories. Related correspondence.
RUNKLE, J. D. Conservation Council of North Carolina 83/03/10 Carolina Power & Light Co. 16pp. 17561.312 24X Fiche: 50-400, 83/03/10, 8303150397.

--8303150400 Response to 830204 interrogatories. Related correspondence.
RUNKLE, J. D. Conservation Council of North Carolina 83/03/10 Office of the Executive Legal Director 15pp. 17561.328 24X Fiche: 50-400, 83/03/10, 8303150397.

--8303150405 Response to 830204 request for admission re potential for bringing plants to cold shutdown mode if heat removal capability of main condenser unavailable. Intervenor cannot admit or deny statement. Related correspondence.
RUNKLE, J. D. Conservation Council of North Carolina 83/03/10 Office of the Executive Legal Director 1p. 17561.343 24X Fiche: 50-400, 83/03/10, 8303150397.

--8303150411 Motion for protective order re responses to util interrogatories on Contentions 12 & 14, NRC interrogatories on Contentions 4, 12 & 14 & NRC 830204 request for admission. W/Certificate of Svc. Related correspondence.
RUNKLE, J. D. Conservation Council of North Carolina 83/03/10 Atomic Safety and Licensing Board Panel 2pp. 17561.344 24X Fiche: 50-400, 83/03/10, 8303150397.

8303150413 Response to first set of interrogatories. Certificate of Svc encl. Related correspondence.
READ, D. F. Chapel Hill Anti-Nuclear Group Effort 83/03/10 Carolina Power & Light Co. 7pp. 17561.248 24X Fiche: 50-400, 83/03/10, 8303150413.

8303150603 Notes on applicant revised proposed schedule. Response time should be tolled until hearings completed. Certificate of Svc encl.
EDDLEMAN, W. Eddleman, W. 83/03/10 2pp. 17568.018 24X Fiche: 50-400, 83/03/10, 8303150603.

8303240426 Forwards resumes of managing consultants & project engineers to be employed in analyzing & assessing plant physical security plan.
HENKE, D. A. Safeguards International, Inc. 83/03/10 GREENBLATT, D. Affiliation Unknown 10pp. 17678.272 24X Fiche: 50-400, 83/03/10, 8303240426.

8303150320 Response in opposition to W Eddleman 830211 revised, amended & addl contentions based on Contention 15. No new info served by applicant as basis for revised or addl contentions on issue of capacity factor. Certificate of Svc encl.
BARTH, C. A. Hearing Branch 1 83/03/11 Atomic Safety and Licensing Board Panel 9pp. 17567.123 24X Fiche: 50-400, 83/03/11, 8303150320.

8303150593 Response to applicant revised proposed schedule. Schedule acceptable as long as latter dates are flexible. Section on tolling of discovery during hearings should be clarified. Certificate of Svc encl.
RUNKLE, J. Conservation Council of North Carolina 83/03/11 2pp. 17567.323 24X Fiche: 50-400, 83/03/11, 8303150593.

8303150597 Reply to W Eddleman 830211 revised, amended & addl contentions. Opposes proposed Contentions 15X, 15Y & 15A - 15S. Original Contention 15 should be dismissed as moot. Certificate of Svc encl.
O'NEILL, J. H. Carolina Power & Light Co. O'NEILL, J. H. Shaw, Pittman, Potts & Trowbridge 83/03/11 Atomic Safety and Licensing Board Panel 28pp. 17568.347 24X Fiche: 50-400, 83/03/11, 8303150597.

8303220320 Answer to NRC & applicant response re revised, amended & addl contentions based on Eddleman Contention 15 & Amend 5 to environ rept.
EDDLEMAN, W. Eddleman, W. 83/03/14 Atomic Safety and Licensing Board Panel 10pp. 17655.349 24X Fiche: 50-400, 83/03/14, 8303220320.

8303240563 Requests KE Long, as representative of NC Util Commission, be added to svc list.
LONG, K. E. North Carolina, State of 83/03/17 KELLEY, J. L. Atomic Safety and Licensing Board Panel 1p. 17683.184 24X Fiche: 50-400, 83/03/17, 8303240563.

8303220224 Interrogatories to RD Wilson. Certificate of Svc encl.
BARTH, C. A. Hearing Branch 1 83/03/18 Wilson, R. 7pp. 17657.293 24X Fiche: 50-400, 83/03/18, 8303220224.

8303220228 Interrogatories to W Eddleman.
BARTH, C. A. Hearing Branch 1 83/03/18 EDDLEMAN, W. Eddleman, W. 8pp. 17657.270 24X Fiche: 50-400, 83/03/18, 8303220228.

8303220236 Request for admission that Units 1 & 2 can be brought to cold shutdown mode even if heat removal capability of main condenser unavailable.
BARTH,C A Hearing Branch 1 83/03/18 Eddleman, W 1p
17657 308 24X Fiche 50-400,83/03/18,8303220236

8303220242 Interrogatories to Joint Intervenor.
BARTH,C A Hearing Branch 1 83/03/18 Chapel Hill Anti-Nuclear Group Effort 6pp 17656 261 24X Fiche 50-400,83/03/18,8303220242

8303220258 Objections & request for clarification of hearing schedule. Certificate of Svc encl.
EDDLEMAN,W Eddleman, W 83/03/18 Atomic Safety and Licensing Board Panel 2pp 17656 246 24X Fiche 50-400,83/03/18,8303220258

8303230186 Interrogatories & request for production of documents. Certificate of Svc encl Related correspondence.
ANDERSON,P H Carolina Power & Light Co ANDERSON,P H Shaw, Pittman, Potts & Trowbridge 83/03/21 Wilson, R 18pp
17665 080 24X Fiche 50-400,83/03/21,8303230186

8303300334 First set of interrogatories & interrogatories on Contentions 22A,22B,41,45,65,75,80,83 & 84. Certificate of Svc encl Related correspondence.
EDDLEMAN,W Eddleman, W 83/03/21 Carolina Power & Light Co
33pp 17735 068 24X Fiche 50-400,83/03/21,8303300334

--8303300339 First request for admission re Contention 22-B on operating payroll. Related correspondence.
EDDLEMAN,W Eddleman, W 83/03/21 Carolina Power & Light Co
1p 17735 101 24X Fiche 50-400,83/03/21,8303300334

8303300347 Response to first set of interrogatories & request for production of documents, per ASLB 830224 oral order. Certificate of Svc encl Related correspondence.
EDDLEMAN,W Eddleman, W 83/03/21 Carolina Power & Light Co
57pp 17734 130 24X Fiche 50-400,83/03/21,8303300347

--8303300353 Certification of negotiations re efforts to resolve objections to applicant 830131 interrogatories.
EDDLEMAN,W Eddleman, W 83/03/21 2pp 17734 187 24X
Fiche 50-400,83/03/21,8303300347

8303240281 Confirms 830322 telcon. Response to NRC interrogatories unsatisfactory. If no expert relied upon in contention formulation, basis for contention must be stated.
BARTH,C A Hearing Branch 1 83/03/23 RUNKLE,J Conservation Council of North Carolina 3pp 17682 194 24X
Fiche 50-400,83/03/23,8303240281

8303240516 Memorandum adding KE Long to svc list as representing NC Util Commission.
MILLER,R G Atomic Safety and Licensing Board Panel 83/03/23 1p
17682 254 24X Fiche 50-400,83/03/23,8303240516

8303250160 Discusses deadlines for discovery. Mutual understandings must be attempted on discovery disputes. Svc list encl. Related correspondence.
BAXTER,T A Shaw, Pittman, Potts & Trowbridge BAXTER,T A Carolina Power & Light Co 83/03/23 PAYNE,M T Edelstein & Payne
4pp 17691 113 24X Fiche 50-400,83/03/23,8303250160

8303290506 Response to ASLB 830310 memorandum & order reflecting decisions made after 830224 prehearing conference. Applicant revised proposed schedule intended to memorialize changes reached at conference. Certificate of Svc encl.
BAXTER,T A Carolina Power & Light Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/03/25 7pp 17724 080 24X
Fiche 50-400,83/03/25,8303290506

8303290507 Memorandum & order memorializing 830323 telcon & propounding questions to be briefed re comparative cost analysis savings, alternative energy sources & need for power.
KELLEY,J L Atomic Safety and Licensing Board Panel 83/03/25
3pp 17725 112 24X Fiche 50-400,83/03/25,8303290507

## Q Inspection reports, IE Bulletins & correspondence

8303010134 Forwards IE Insp Repts 50-400/83-04 & 50-401/83-04 on 821220-830120. No noncompliance noted.
VERRELLI,D M Division of Project & Resident Programs 83/02/07
UTLEY,E E Carolina Power & Light Co 2pp 17345 013 24X
Fiche 50-400,83/02/07,8303010134

--8303010137 IE Insp Repts 50-400/83-04 & 50-401/83-04 on 821220-830120. No noncompliance noted. Major areas inspected: licensee action on previous insp findings, concrete & cadwelding, storage, welding, electrical raceway supports & piping sys.
MAXWELL,G F ; BEMIS,P Division of Project & Resident Programs
83/02/07 7pp 17345 015 24X Fiche 50-400,83/02/07,8303010134

8303010257 Advises that addl info re IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp (Asiatic clam) & Mytilus Sp (mussel)," will be submitted by 830321. Delay due to extensive interfacing necessary.
HURFORD,W J Carolina Power & Light Co 83/02/08 O'REILLY,J P
Region 2, Office of Director 1p 17345 181 24X
Fiche 50-400,83/02/08,8303010257

8303210446 Forwards IE Insp Repts 50-400/83-02 & 50-401/83-02 on 830125-28. No noncompliance noted.
VERRELLI,D M Division of Project & Resident Programs 83/02/11
UTLEY,E E Carolina Power & Light Co 2pp 17634 306 24X
Fiche 50-400,83/02/11,8303210446

--8303210454 IE Insp Repts 50-400/83-02 & 50-401/83-02 on 830125-28. No noncompliance noted. Major areas inspected: licensee action on previous matters, calibr & control of crimping tools & review of implementing QA procedures for electrical cables.
RUFF,A B ; CONLON,T E Region 2, Office of Director 83/02/09
5pp 17634 308 24X Fiche 50-400,83/02/11,8303210446

8303210729 Forwards IE Insp Repts 50-400/83-01 & 50-401/83-01 on 830110-14. No noncompliance noted.
VERRELLI,D M Division of Project & Resident Programs 83/02/11
UTLEY,E E Carolina Power & Light Co 2pp 17635 126 24X
Fiche 50-400,83/02/11,8303210729

--8303210739 IE Insp Repts 50-400/83-01 & 50-401/83-01 on 830110-14. No noncompliance noted. Major areas inspected: onsite design activities, implementation of 10CFR21 requirements & 10CFR50.55(e) item.
WRIGHT,R W ; MCFARLAND,C R ; UPRIGHT,C M Region 2, Office of Director 83/02/09 9pp 17635 128 24X Fiche 50-400,83/02/11,8303210729

8303010532 Ack receipt of 830204 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/82-39 & 50-401/82-39.
LEWIS,R C Division of Project & Resident Programs 83/02/16
UTLEY,E E Carolina Power & Light Co 1p 17343 010 24X
Fiche 50-400,83/02/16,8303010532

--8303010538 Responds to NRC 830107 ltr re violations noted in IE Insp Rept 50-400/82-39. Corrective actions: incomplete welds repaired, bolts replaced, seismic Category I pumps inspected & documents revised to reflect installed bolting matl.
PARSONS,R M Carolina Power & Light Co 83/02/04 O'REILLY,J P
Region 2, Office of Director 3pp 17343 011 24X
Fiche 50-400,83/02/16,8303010532

--8303010543 Forwards IE Insp Repts 50-400/82-39 & 50-401/82-39 on 821120-1220 & notice of violation.
LEWIS,R C Division of Project & Resident Programs 83/01/07
UTLEY,E E Carolina Power & Light Co 2pp 17343 014 24X
Fiche 50-400,83/02/16,8303010532

--8303010549 Notice of violation from insp on 821120-1220.
* Division of Project & Resident Programs 82/12/30 1p
17343 016 24X Fiche 50-400,83/02/16,8303010532

--8303010553 IE Insp Repts 50-400/82-39 & 50-401/82-39 on 821120-1220. Noncompliance noted: resistant spot welds on foundation cradle did not conform to procurement documents.
MAXWELL,G F Region 2, Office of Director BEMIS,P Division of Project & Resident Programs 82/12/30 7pp 17343 017 24X
Fiche 50-400,83/02/16,8303010532

8303210331 Forwards IE Insp Repts 50-400/83-05 & 50-401/83-05 on 830201-04. No noncompliance noted.
VERRELLI,D M Division of Project & Resident Programs 83/02/23
UTLEY,E E Carolina Power & Light Co 2pp 17632 159 24X
Fiche 50-400,83/02/23,8303210331

--8303210335 IE Insp Repts 50-400/83-05 & 50-401/83-05 on 830201-04. No noncompliance noted. Major areas inspected: independent insp effort, safety-related pipe support & restraint sys & other safety-related piping sys.
YORK,J W ; LIU,W C ; BLAKE,J J Region 2, Office of Director
83/02/22 6pp 17632 161 24X Fiche 50-400,83/02/23,8303210331

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc
111pp 17521 001 24X Fiche 50-000,83/02/25,8212060367

8303210689 Ack receipt of 830208 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-400/82-38.
VERRELLI,D M Division of Project & Resident Programs 83/03/03
UTLEY,E E Carolina Power & Light Co 1p 17636 013 24X
Fiche 50-400,83/03/03,8303210689

--8303210698 Responds to NRC 830110 ltr re violation noted in IE Insp Rept 50-400/82-38. Corrective actions Field Change Request FCR-AS-2378 issued & sampling-type insp for cable tray bolting changed to 100% insp program.
PARSONS, R. M. Carolina Power & Light Co. 83/02/08. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17636:014. 24X
Fiche: 50-400, 83/03/03, 8303210689

--8303210705 Forwards IE Insp Repts 50-400/82-38 & 50-401/82-38 on 821214-17 & notice of violation.
VERRELLI, D. M. Division of Project & Resident Programs. 83/01/10.
UTLEY, E. E. Carolina Power & Light Co. 2pp. 17636:016. 24X
Fiche: 50-400, 83/03/03, 8303210689

--8303210711 Notice of violation from insp on 821214-17.
* Region 2, Office of Director. 83/01/10. 1p. 17636:018. 24X
Fiche: 50-400, 83/03/03, 8303210689

--8303210719 IE Insp Repts 50-400/82-38 & 50-401/82-38 on 821214-17. Noncompliance noted: 12 cable tray splice bolts & one hold down bolt did not have specified torque.
MERRIWEATHER, N. Region 2, Office of Director. CONLON, T. E. Division of Engineering & Radiological Safety Programs. 83/01/06. 4pp. 17636:019. 24X Fiche: 50-400, 83/03/03, 8303210689

8303150403 Responds to IE Bulletin 82-04. No Bunker-Ramo electrical penetration assemblies used at facility.
EURY, L. W. Carolina Power & Light Co. 83/03/09. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 1p. 17561:268. 24X Fiche: 50-400, 83/03/09, 8303150403.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303180293 Forwards Rev 2 to, "Reactor Vessel Preservice Insp Program." Position statement for Reg Guide 1.150 will be revised to reflect rev in future amend. Exam of reactor vessel welds commenced on 830115.
HURFORD, W. J. Carolina Power & Light Co. 83/03/14. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17617:154. 24X Fiche: 50-400, 83/03/14, 8303180293.

--8303180295 Rev 2 to "Reactor Pressure Vessel Preservice Insp Program Plan."
AHMED, A. Nuclear Energy Service, Inc. 83/01/31. 80pp. 17617:155. 24X Fiche: 50-400, 83/03/14, 8303180293.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

S. Reportable occurrences: LERs & related correspondence
---

8303040474 Firth interim deficiency rept re threaded studs o/insufficient threaded engagement into embedded strip plates. Evaluation of eight plates & rework on seven plates complete. Extension until 830401 requested for final rept.
PARSONS, R. M. Carolina Power & Light Co. 83/02/24. O'REILLY, J. P. Region 2, Office of Director. 4pp. 17373:323. 24X
Fiche: 50-400, 83/02/24, 8303040474.

8303140479 Deficiency rept re welding deficiencies on Class 1E battery racks supplied by C&D Batteries. Weld rework completed. Extension until 830515 for submitting evaluation rept requested. Also reportable per Part 21.
PARSONS, R. M. Carolina Power & Light Co. 83/03/02. O'REILLY, J. P. Region 2, Office of Director. 1p. 17540:310. 24X
Fiche: 50-400, 83/03/02, 8303140479.

8303140330 Interim deficiency & Part 21 repts re design defect in solid state protection sys procured under westinghouse Purchase Order NY-435002. Initially reported on 821012. Final rept expected by 840112.
PARSONS, R. M. Carolina Power & Light Co. 83/03/03. O'REILLY, J. P. Region 2, Office of Director. 4pp. 17534:203. 24X
Fiche: 50-400, 83/03/03, 8303140330.

8303160522 Final rept re Westinghouse reactor coolant pump motor frame weld deficiencies. Initially reported on 830304. Welding deficiencies determined not reportable per provisions of 10CFR50.55(e) & 10CFR21.
CHIANGI, N. J. Carolina Power & Light Co. 83/03/04. O'REILLY, J. P. Region 2, Office of Director. 1p. 17592:334. 24X
Fiche: 50-400, 83/03/04, 8303160522.

8303240526 Deficiency rept re welding on traveling water screens received from Reynord, Inc. Initially reported on 830311. Deficiency not reportable per 10CFR50.55(e).
CHIANGI, N. J. Carolina Power & Light Co. 83/03/14. O'REILLY, J. P. Region 2, Office of Director. 1p. 17682:282. 24X
Fiche: 50-400, 83/03/14, 8303240526.

8303240431 Interim deficiency rept re base defect in spool piece supplied by Southwest Fabricating & Welding Co. Initially reported on 830215. Spool piece will be replaced. Final rept will be submitted by 830429. Also reported per Part 21.
PARSONS, R. M. Carolina Power & Light Co. 83/03/16. O'REILLY, J. P. Region 2, Office of Director. 4pp. 17678:001. 24X
Fiche: 50-400, 83/03/16, 8303240431.

T. Hearing transcripts on non-antitrust matters
---

8303010225 Transcript of 830224 prehearing conference in Raleigh, NC. Pp. 457-619.
* Atomic Safety and Licensing Board Panel. 83/02/24. 163pp. 17353:145. 24X Fiche: 50-400, 83/02/24, 8303010225.

V. Operator Examinations
---

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303090350 Submits projected requests for site visits to conduct operator license exams through Dec. 1985 in response to Generic Ltr 83-01.
ZIMMERMAN, S. R. Carolina Power & Light Co. 83/03/02. EISENHUT, D. G. Division of Licensing. 2pp. 17472:138. 24X Fiche: 50-000, 83/03/02, 8303090350.

DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2
---

A. Application/construction stage documents & correspondence
---

8303010723 Forwards revised table clarifying licensing schedule. Fuel load dates for Units 1 & 2 scheduled for June 1985 & June 1989, respectively. Other licensing milestones applicable to both units.
NOVAK, T. M. Assistant Director for Licensing. 83/02/09. UTLEY, E. E. Carolina Power & Light Co. 3pp. 17348:299. 24X
Fiche: 50-400, 83/02/09, 8303010723.

8303030274 Notification of 830228 meeting w/applicant in Bethesda, MD to discuss postulated Neuse fault; rev of USGS position & seismic monitoring instrumentation.
KADAMBI, N. P. Licensing Branch 3. 83/02/10. KNIGHTON, G. W. Licensing Branch 3. 3pp. 17365:240. 24X Fiche: 50-400, 83/02/10, 8303030274.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303030283 Notification of 830307-11 meetings w/applicant & Ebasco in New York, NY to discuss structural design for seismic Category I structures & implementation of FSAR design criteria.
KADAMBI, N. P. Licensing Branch 3. 83/02/22. KNIGHTON, G. W. Licensing Branch 3. 3pp. 17365:233. 24X Fiche: 50-400, 83/02/22, 8303030283.

8303030703 Notification of 830307 meeting w/utils & NUS Corp in Bethesda, MD to discuss proposed rev to 10CFR40.36 (Tech Specs).
BRINKMAN, D. S. Standardization & Special Projects Branch. 83/02/22.
THOMAS, C. O. Standardization & Special Projects Branch. 2pp. 17363:227. 24X Fiche: 50-000, 83/02/22, 8303030703.

8303070166 Forwards source term evaluation for vol reduction sys.
ZIMMERMAN, S R Carolina Power & Light Co 83/02/24 DENTON, H R
Office of Nuclear Reactor Regulation, Director 11pp 17433 112
24X Fiche 50-400, 83/02/24, 8303070166

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl.
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X
Fiche 50-000, 83/03/02, 8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 5lpp 17660 176 24X
Fiche 50-000, 83/03/07, 8303040005

8303230101 Notification of 830325 meeting w/util in Bethesda, MD to discuss info re current control room design & documentation status.
KADAMBI, N P Licensing Branch 3 83/03/08 KNIGHTON, G W
Licensing Branch 3 3pp 17687 157 24X Fiche 50-400, 83/03/08, 8303230101

8303230346 Summary of 830228 meeting w/util in Bethesda, MD re seismic monitoring instrumentation & postulated Neuse fault & to exchange info on USGS re-evaluation of implications of Charleston earthquake.
KADAMBI, N P Licensing Branch 3 83/03/09 Licensing Branch 3
6pp 17675 275 24X Fiche 50-400, 83/03/09, 8303230346

8303160556 Requests to be included in 1984 schedule for aerial gamma spectral mapping to determine radiological anomalies of environ prior to operation.
HURFORD, W J Carolina Power & Light Co 83/03/14 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 1p
17587 268 24X Fiche 50-400, 83/03/14, 8303160556

8303220164 Forwards minutes of 830201-02 meetings w/Mechanical Engineering Branch to respond to questions transmitted in 821222 ltr Responses committing to FSAR change will be incorporated into future amend.
MCDUFFIE, M A Carolina Power & Light Co 83/03/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director 74pp 17658 167
24X Fiche 50-400, 83/03/16, 8303220164

8303310654 Requests arrangements be made for Geotechnical Engineering Section 830415-17 site visit & audit.
KNIGHTON, G W Licensing Branch 3 83/03/16 UTLEY, E E Carolina
Power & Light Co 9pp 17780 308 24X Fiche 50-400, 83/03/16,
8303310654

8303310666 Advises of discrepancy between FSAR Sections 4.3 & 15.6 re LOCA peaking factor. Peaking factor control, analysis & surveillance or power reduction remain open FSAR items.
KNIGHTON, G W Licensing Branch 3 83/03/24 UTLEY, E E Carolina
Power & Light Co 3pp 17780 301 24X Fiche 50-400, 83/03/24,
8303310666

C. Utility Environmental Report (ER), amends & correspondence

8303280040 Forwards revised environ rept Tables 3.3-1 & 3.6.2-2, P 3.6-2 table of waste discharge rates to cooling tower blowdown, in response to NRC request.
ZIMMERMAN, S R Carolina Power & Light Co 83/03/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director 11pp 17707 218
24X Fiche 50-400, 83/03/21, 8303280040

E. NRC Safety Evaluation Report (SER), supplS & correspondence

8303010727 Forwards draft SER, identifying incomplete info & disagreement of approach. Timely submittals required to resolve all items by SER Nov 1983 issue date. W/o encl.
KNIGHTON, G W Licensing Branch 3 83/02/01 UTLEY, E E Carolina
Power & Light Co 2pp 17347 359 24X Fiche 50-400, 83/02/01,
8303010727

O. Adjudicatory correspondence

8303030469 Memorandum amending svc list.
MILLER, R G Atomic Safety and Licensing Board Panel 83/03/01 1p
17409 334 24X Fiche 50-400, 83/03/01, 8303030469

8303070116 Forwards NRC & applicant briefs in Catawba proceeding re contentions based on new info disclosed in documents generated after time to file contentions, in response to ASLB 830224 request W/o encl.
BARTH, C A Hearing Branch 1 83/03/03 PAYNE, T Affiliation
Unknown NEWMAN, P T Citizens Against Nuclear Power RUNKLE, J
Conservation Council of North Carolina 2pp 17433 069 24X
Fiche 50-400, 83/03/03, 8303070116

8303140269 Response to interrogatories & request for production of documents Certificate of Svc encl Related correspondence.
WILSON, R Wilson, R 83/03/03 Carolina Power & Light Co 6pp
17535 117 24X Fiche 50-400, 83/03/03, 8303140267

8303110193 Revised proposed schedule for adjudication of issues for remainder of proceeding Rev reflects areas of agreement & compromise reached during 830224 prehearing conference. Certificate of Svc encl.
O'NEILL, J H Carolina Power & Light Co O'NEILL, J H North
Carolina Municipal Power Agencies 83/03/08 9pp 17520 129 24X
Fiche 50-400, 83/03/08, 8303110193

8303110209 Notice of appearance in proceeding.
ANDERSON, P H Carolina Power & Light Co ANDERSON, P H Shaw,
Pittman, Potts & Trowbridge 83/03/08 1p 17515 097 24X
Fiche 50-400, 83/03/08, 8303110209

8303110211 Notice of appearance in proceeding.
BAUSER, D B Carolina Power & Light Co BAUSER, D B Shaw, Pittman,
Potts & Trowbridge 83/03/08 1p 17519 293 24X
Fiche 50-400, 83/03/08, 8303110211

8303110213 Notice of appearance in proceeding.
CARROW, B B Carolina Power & Light Co 83/03/08 1p 17519 294
24X Fiche 50-400, 83/03/08, 8303110213

8303140252 First set of interrogatories & request for production of documents.
BAUSER, D B Carolina Power & Light Co BAUSER, D B Shaw, Pittman,
Potts & Trowbridge 83/03/09 Citizens Against Nuclear Power
21pp 17544 060 24X Fiche 50-400, 83/03/09, 8303140252

--8303140258 Second set of interrogatories & request for production of documents.
BAUSER, D B Carolina Power & Light Co BAUSER, D B Shaw,
Pittman, Potts & Trowbridge 83/03/09 Eddleman, W 11pp
17544 081 24X Fiche 50-400, 83/03/09, 8303140252

--8303140262 Second set of interrogatories & request for production of documents to Joint Intervenors.
BAUSER, D B Carolina Power & Light Co BAUSER, D B Shaw,
Pittman, Potts & Trowbridge 83/03/09 Chapel Hill Anti-Nuclear
Group Effort 13pp 17544 092 24X Fiche 50-400, 83/03/09,
8303140252

--8303140266 Second set of interrogatories & request for production of documents Certificate of Svc encl.
BAUSER, D B Carolina Power & Light Co BAUSER, D B Shaw,
Pittman, Potts & Trowbridge 83/03/09 Wilson, R 10pp
17544 105 24X Fiche 50-400, 83/03/09, 8303140252

8303140214 Forwards NRC papers re $600,000 civil penalty imposed upon applicant for violations at Brunswick facilities. Info relevant to mgt capability & QA/QC issues.
BARTH, C A Hearing Branch 1 83/03/10 KELLEY, J L , BRIGHT, G O ,
CARPENTER, J H Atomic Safety and Licensing Board Panel 31pp
17539 306 24X Fiche 50-400, 83/03/10, 8303140[illegible]

8303140279 Memorandum & order reflecting decisions [illegible] owing 830224 second prehearing conference in Raleigh, NC [illegible] ons concern scheduling, discovery guidelines & rulings on related matters.
KELLEY, J L , CARPENTER, J H , BRIGHT, G O Atomic Safety and Licensing
Board Panel 83/03/10 41pp 17535 064 24X Fiche 50-400,
83/03/10, 8303140279

8303150397 Response to first set of interrogatories Related correspondence.
RUNKLE, J D Conservation Council of North Carolina 83/03/10
Carolina Power & Light Co 16pp 17561 312 24X
Fiche 50-400, 83/03/10, 8303150397

--8303150400 Response to 830204 interrogatories Related correspondence.
RUNKLE, J D Conservation Council of North Carolina 83/03/10
Office of the Executive Legal Director [illegible]pp 17561 328 24X
Fiche 50-400, 83/03/10, 8303150397

--8303150405 Response to 830204 request for admission re potential for bringing plants to cold shutdown mode if heat removal capability of main condenser unavailable. Intervenor cannot admit or deny statement. Related correspondence.
RUNKLE, J. D. Conservation Council of North Carolina 83/03/10
Office of the Executive Legal Director 1p 17561 343 24X
Fiche: 50-400, 83/03/10, 8303150397

--8303150411 Motion for protective order re responses to util interrogatories on Contentions 12 & 14, NRC interrogatories on Contentions 4, 12 & 14 & NRC 830204 request for admission. W/Certificate of Svc. Related correspondence.
RUNKLE, J. D. Conservation Council of North Carolina 83/03/10
Atomic Safety and Licensing Board Panel 2pp 17561 344 24X
Fiche: 50-400, 83/03/10, 8303150397

8303150413 Response to first set of interrogatories. Certificate of Svc encl. Related correspondence.
READ, D. F. Chapel Hill Anti-Nuclear Group Effort 83/03/10
Carolina Power & Light Co. 7pp 17561 248 24X
Fiche: 50-400, 83/03/10, 8303150413

8303150603 Notes on applicant revised proposed schedule. Response time should be tolled until hearings completed. Certificate of Svc encl.
EDDLEMAN, W. Eddleman, W. 83/03/10 2pp 17568 019 24X
Fiche: 50-400, 83/03/10, 8303150603

8303240426 Forwards resumes of managing consultants & project engineers to be employed in analyzing & assessing plant physical security plan.
HENKE, D. A. Safeguards International, Inc. 83/03/10 GREENBLATT, D.
Affiliation Unknown 10pp 17678 272 24X Fiche: 50-400, 83/03/10, 8303240426

8303150320 Response in opposition to W Eddleman 830211 revised, amended & addl contentions based on Contention 15. No new info served by applicant as basis for revised or addl contentions on issue of capacity factor. Certificate of Svc encl.
BARTH, C. A. Hearing Branch 1 83/03/11 Atomic Safety and Licensing Board Panel 9pp 17567 123 24X Fiche: 50-400, 83/03/11, 8303150320

8303150593 Response to applicant revised proposed schedule. Schedule acceptable as long as latter dates are flexible. Section on tolling of discovery during hearings should be clarified. Certificate of Svc encl.
RUNKLE, J. Conservation Council of North Carolina 83/03/11 2pp 17567 323 24X Fiche: 50-400, 83/03/11, 8303150593

8303150597 Reply to W Eddleman 830211 revised, amended & addl contentions. Opposes proposed Contentions 15X, 15Y & 15A - 15S. Original Contention 15 should be dismissed as moot. Certificate of Svc encl.
O'NEILL, J. H. Carolina Power & Light Co. O'NEILL, J. H. Shaw, Pittman, Potts & Trowbridge 83/03/11 ..tomic Safety and Licensing Board Panel 28pp 17568 347 24X Fiche: 50-400, 83/03/11, 8303150597

8303220320 Answer to NRC & applicant response re revised, amended & addl contentions based on Eddleman Contention 15 & Amend 5 to environ rept.
EDDLEMAN, W. Eddleman, W. 83/03/14 Atomic Safety and Licensing Board Panel 10pp 17655 349 24X Fiche: 50-400, 83/03/14, 8303220320

8303240563 Requests KE Long, as representative of NC Util Commission, be added to svc list.
LONG, K. E. North Carolina, State of 83/03/17 KELLEY, J. L. Atomic Safety and Licensing Board Panel 1p 17683 184 24X
Fiche: 50-400, 83/03/17, 8303240563

W303220224 Interrogatories to RD Wilson. Certificate of Svc encl.
BARTH, C. A. Hearing Branch 1 83/03/18 Wilson, R. 7pp
17657 293 24X Fiche: 50-400, 83/03/18, 8303220224

8303220228 Interrogatories to W Eddleman.
BARTH, C. A. Hearing Branch 1 83/03/18 EDDLEMAN, W. Eddleman, W.
8pp 17657 270 24X Fiche: 50-400, 83/03/18, 8303220228

8303220236 Request for admission that Units 1 & 2 can be brought to cold shutdown mode even if heat removal capability of main condenser unavailable.
BARTH, C. A. Hearing Branch 1 83/03/18 Eddleman, W. 1p
17657 308 24X Fiche: 50-400, 83/03/18, 8303220236

8303220242 Interrogatories to Joint Intervenor.
BARTH, C. A. Hearing Branch 1 83/03/18 Chapel Hill Anti-Nuclear Group Effort 6pp 17656 261 24X Fiche: 50-400, 83/03/18, 8303220242

8303220258 Objections & request for clarification of hearing schedule. Certificate of Svc encl.
EDDLEMAN, W. Eddleman, W. 83/03/18 Atomic Safety and Licensing Board Panel 2pp 17656 246 24X Fiche: 50-400, 83/03/18, 8303220258

8303230186 Interrogatories & request for production of documents. Certificate of Svc encl. Related correspondence.
ANDERSON, P. H. Carolina Power & Light Co. ANDERSON, P. H. Shaw, Pittman, Potts & Trowbridge 83/03/21 Wilson, R. 18pp.
17665 080 24X Fiche: 50-400, 83/03/21, 8303230186.

8303300334 First set of interrogatories & interrogatories on Contentions 22A, 22B, 41, 45, 65, 75, 80, 83 & 84. Certificate of Svc encl. Related correspondence.
EDDLEMAN, W. Eddleman, W. 83/03/21 Carolina Power & Light Co.
33pp 17735 068 24X Fiche: 50-400, 83/03/21, 8303300334.

--8303300339 First request for admission re Contention 22-B on operating payroll. Related correspondence.
EDDLEMAN, W. Eddleman, W. 83/03/21 Carolina Power & Light Co.
1p 17735 101 24X Fiche: 50-400, 83/03/21, 8303300334.

8303300347 Response to first set of interrogatories & request for production of documents, per ASLB 830224 oral order. Certificate of Svc encl. Related correspondence.
EDDLEMAN, W. Eddleman, W. 83/03/21 Carolina Power & Light Co.
57pp 17734 130 24X Fiche: 50-400, 83/03/21, 8303300347.

--8303300353 Certification of negotiations re efforts to resolve objections to applicant 830131 interrogatories.
EDDLEMAN, W. Eddleman, W. 83/03/21 2pp 17734 187 24X
Fiche: 50-400, 83/03/21, 8303300347.

8303240281 Confirms 830322 telcon. Response to NRC interrogatories unsatisfactory. If no expert relied upon in contention formulation, basis for contention must be stated.
BARTH, C. A. Hearing Branch 1 83/03/23 RUNKLE, J. Conservation Council of North Carolina 3pp 17682 194 24X
Fiche: 50-400, 83/03/23, 8303240281.

8303240516 Memorandum adding KE Long to svc list as representing NC Util Commission.
MILLER, R. G. Atomic Safety and Licensing Board Panel 83/03/23 1p.
17682 254 24X Fiche: 50-400, 83/03/23, 8303240516.

8303250160 Discusses deadlines for discovery. Mutual understandings must be attempted on discovery disputes. Svc list encl. Related correspondence.
BAXTER, T. A. Shaw, Pittman, Potts & Trowbridge BAXTER, T. A.
Carolina Power & Light Co. 83/03/23 PAYNE, M. T. Edelstein & Payne.
4pp 17691 113 24X Fiche: 50-400, 83/03/23, 8303250160.

8303290506 Response to ASLB 830310 memorandum & order reflecting decisions made after 830224 prehearing conference. Applicant revised proposed schedule intended to memorialize changes reached at conference. Certificate of Svc encl.
BAXTER, T. A. Carolina Power & Light Co. BAXTER, T. A. Shaw, Pittman, Potts & Trowbridge 83/03/25 7pp 17724 080 24X
Fiche: 50-400, 83/03/25, 8303290506.

8303290507 Memorandum & order memorializing 830323 telcon & propounding questions to be briefed re comparative cost analysis, savings, alternative energy sources & need for power.
KELLEY, J. L. Atomic Safety and Licensing Board Panel 83/03/25.
3pp 17725 112 24X Fiche: 50-400, 83/03/25, 8303290507.

G. Inspection reports, IE Bulletins & correspondence

8303010134 Forwards IE Insp Repts 50-400/83-04 & 50-401/83-04 on 821220-830120. No noncompliance noted.
VERRELLI, D. M. Division of Project & Resident Programs 83/02/07.
UTLEY, E. E. Carolina Power & Light Co. 2pp 17345 013 24X
Fiche: 50-400, 83/02/07, 8303010134.

--8303010137 IE Insp Repts 50-400/83-04 & 50-401/83-04 on 821220-830120. No noncompliance noted. Major areas inspected: licensee action on previous insp findings, concrete & cadwelding, storage, welding, electrical raceway supports & piping sys.
MAXWELL, G. F.; BEMIS, P. Division of Project & Resident Programs.
83/02/07. 7pp 17345 015 24X Fiche: 50-400, 83/02/07, 8303010134.

8303010257 Advises that addl info re IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp. (Asiatic clam) & Mytilus Sp. (mussel)," will be submitted by 830321. Delay due to extensive interfacing necessary.
HURFORD, W. J. Carolina Power & Light Co. 83/02/08. O'REILLY, J. P.
Region 2, Office of Director 1p 17345 181 24X
Fiche: 50-400, 83/02/08, 8303010257.

# DOCKETED ITEMS

8303210446 Forwards IE Insp Repts 50-400/83-02 & 50-401/83-02 on d30125-28. No noncompliance noted.
VERRELLI, D. M. Division of Project & Resident Programs 83/02/11
UTLEY, E. E. Carolina Power & Light Co. 2pp 17634:306 24X
Fiche: 50-400, 83/02/11, 8303210446.

--8303210454 IE Insp Repts 50-400/83-02 & 50-401/83-02 on 830125-28. No noncompliance noted. Major areas inspected: licensee action on previous matters, calibr & control of criti ing tools & review of implementing QA procedures for electr / cables.
RUFF, A. S. ; CONLON, T. E. Region 2, Offic Director 83/02/09
5pp. 17634:308 24X Fiche: 50-400, 83/0 /11, 8303210446.

8303210729 Forwards IE Insp Repts 50-400/83-01 & 50-401/83-01 on 830110-14. No noncompliance noted.
VERRELLI, D. M. Division of Project & Resident Programs 83/02/11
UTLEY, E. E. Carolina Power & Light Co. 2pp 17635:126 24X
Fiche: 50-400, 83/02/11, 8303210729.

--8303210739 IE Insp Repts 50-400/83-01 & 50-401/83-01 on 830110-14. No noncompliance noted. Major areas inspected: onsite design activities; implementation of 10CFR21 requirements & 10CFR50.55(e) item.
WRIGHT, R. W. ; MCFARLAND, C. R. ; UPRIGHT, C. M. Region 2, Office of Director 83/02/09 9pp 17635:128 24X Fiche: 50-400, 83/02/11, 8303210729.

8303010532 Ack receipt of 830204 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/82-39 & 50-401/82-39.
LEWIS, R. C. Division of Project & Resident Programs 83/02/16
UTLEY, E. E. Carolina Power & Light Co. 1p 17343:010 24X
Fiche: 50-400, 83/02/16, 8303010532.

--8303010538 Responds to NRC 830107 ltr re violations noted in IE Insp Rept 50-400/82-39. Corrective actions: incomplete welds repaired, bolts replaced; seismic Category I pumps inspected & documents revised to reflect installed bolting matl.
PARSONS, R. M. Carolina Power & Light Co. 83/02/04 O'REILLY, J. P.
Region 2, Office of Director 3pp 17343:011 24X
Fiche: 50-400, 83/02/16, 8303010532.

--8303010543 Forwards IE Insp Repts 50-400/82-39 & 50-401/82-39 on 821120-1220 & notice of violation.
LEWIS, R. C. Division of Project & Resident Programs 83/01/07
UTLEY, E. E. Carolina Power & Light Co. 2pp 17343:014 24X
Fiche: 50-400, 83/02/16, 8303010532.

--8303010553 IE Insp Repts 50-400/82-39 & 50-401/82-39 on 821120-1220. Noncompliance noted: resistant spot welds on foundation cradle did not conform to procurement documents.
MAXWELL, G. F. Region 2, Office of Director BEMIS, P. Division of Project & Resident Programs 82/12/30 7pp 17343:017 24X
Fiche: 50-400, 83/02/16, 8303010532.

8303210331 Forwards IE Insp Repts 50-400/83-05 & 50-401/83-05 on 830201-04. No noncompliance noted.
VERRELLI, D. M. Division of Project & Resident Programs 83/02/23
UTLEY, E. E. Carolina Power & Light Co. 2pp 17632:159 24X
Fiche: 50-400, 83/02/23, 8303210331.

--8303210335 IE Insp Repts 50-400/83-05 & 50-401/83-05 on 830201-04. No noncompliance noted. Major areas inspected: independent insp effort, safety-related pipe support & restraint sys & other safety-related piping sys.
YORK, J. W. ; LIU, W. C. ; BLAKE, J. J. Region 2, Office of Director
83/02/22 6pp 17632:161 24X Fiche: 50-400, 83/02/23, 8303210331.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc.
111pp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210689 Ack receipt of 830208 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-400/82-38.
VERRELLI, D. M. Division of Project & Resident Programs 83/03/03
UTLEY, E. E. Carolina Power & Light Co. 1p 17636:013 24X
Fiche: 50-400, 83/03/03, 8303210689.

--8303210705 Forwards IE Insp Repts 50-400/82-38 & 50-40[illegible]82-38 on 821214-17 & notice of violation.
VERRELLI, D. M. Division of Project & Resident Programs 83/01/10
UTLEY, E. E. Carolina Power & Light Co. 2pp 17636:016 24X
Fiche: 50-400, 83/03/03, 8303210689.

--8303210719 IE Insp Repts 50-400/82-38 & 50-401/82-38 on 821214-17. Noncompliance noted: 12 cable tray splice bolts & one hold down bolt did not have specified torque.
MERRIWEATHER, N. Region 2, Office of Director CONLON, T. E. Division of Engineering & Radiological Safety Programs 83/01/06
4pp 17636:019 24X Fiche: 50-400, 83/03/03, 8303210689.

8303150403 Responds to IE Bulletin 82-04. No Bunker-Ramo electrical penetration assemblies used at facility.
EURY, L. W. Carolina Power & Light Co. 83/03/09 DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 1p
17561:268 24X Fiche: 50-400, 83/03/09, 8303150403.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc.
117pp 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

## S. Reportable occurrences, LERs & related correspondence

8303040474 Fifth interim deficiency rept re threaded studs w/insufficient threaded engagement into embedded strip plates. Evaluation of eight plates & rework on seven plates complete. Extension until 830401 requested for final rept.
PARSONS, R. M. Carolina Power & Light Co. 83/02/24 O'REILLY, J. P.
Region 2, Office of Director 4pp 17373:323 24X
Fiche: 50-400, 83/02/24, 8303040474.

8303140479 Deficiency rept re welding deficiencies on Class 1E battery racks supplied by C&D Batteries. Weld rework completed. Extension until 830515 for submitting evaluation rept requested. Also reportable per Part 21.
PARSONS, R. M. Carolina Power & Light Co. 83/03/02 O'REILLY, J. P.
Region 2, Office of Director 1p 17540:310 24X
Fiche: 50-400, 83/03/02, 8303140479.

8303140330 Interim deficiency & Part 21 repts re design defect in solid state protection sys procured under Westinghouse Purchase Order NY-435002. Initially reported on 821012. Final rept expected by 840112.
PARSONS, R. M. Carolina Power & Light Co. 83/03/03 O'REILLY, J. P.
Region 2, Office of Director 4pp 17534:203 24X
Fiche: 50-400, 83/03/03, 8303140330.

8303160522 Final rept re Westinghouse reactor coolant pump motor frame weld deficiencies. Initially reported on 830304. Welding deficiencies determined not reportable per provisions of 10CFR50.55(e) & 10CFR21.
CHIANGI, N. J. Carolina Power & Light Co. 83/03/04 O'REILLY, J. P.
Region 2, Office of Director 1p 17592:334 24X
Fiche: 50-400, 83/03/04, 8303160522.

8303240526 Deficiency rept re welding on traveling water screens received from Rexnord, Inc. Initially reported on 830311. Deficiency not reportable per 10CFR50.55(e).
CHIANGI, N. J. Carolina Power & Light Co. 83/03/14 O'REILLY, J. P.
Region 2, Office of Director 1p 17682:282 24X
Fiche: 50-400, 83/03/14, 8303240526.

8303240431 Interim deficiency rept re base defect in spool piece supplied by Southwest Fabricating & Welding Co. Initially reported on 830215. Spool piece will be replaced. Final rept will be submitted by 830429. Also reported per Part 21.
PARSONS, R. M. Carolina Power & Light Co. 83/03/16 O'REILLY, J. P.
Region 2, Office of Director 4pp 17678:001 24X
Fiche: 50-400, 83/03/16, 8303240431.

## T. Hearing transcripts on non-antitrust matters

8303010225 Transcript of 830224 prehearing conference in Raleigh, NC. Pp 457-619.
* Atomic Safety and Licensing Board Panel 83/02/24 164pp
17333:145 24X Fiche: 50-400, 83/02/24, 8303010225.

## V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp 24X Fiche: 50-000, 83/02/24, 8302250505.

8303090350 Submits projected requests for site visits to conduct operator license exams through Dec 1985 in response to Generic Ltr 83-01.
ZIMMERMAN, S R Carolina Power & Light Co 83/03/02 EISENHUT, D G Division of Licensing 2pp 17472 138 24X Fiche 50-000, 83/03/02, 8303090350

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

F Security, medical, emergency & fire protection plans

8303030270 Advises that 821214 & 830105 revs to security force training & qualification & physical security plans acceptable. Encls to util ltrs withheld (ref 10CFR73.21).
CRUTCHFIELD, D Operating Reactors Branch 5 83/02/23 LINDER, F Dairyland Power Cooperative 2pp 17365 243 24X Fiche 50-409, 83/02/23, 8303030270

8303170179 Forwards Amend 32 to License DPR-45 & notice of issuance & availability. Amend requires audit of emergency preparedness programs & safeguards contingency plan (security plan) at frequency of at least once per yr.
CRUTCHFIELD, D Operating Reactors Branch 5 83/03/14 LINDER, F Dairyland Power Cooperative 3pp 17609 014 24X Fiche 50-409, 83/03/14, 8303170179

--8303170188 Amend 32 to License DPR-45, requiring audit of emergency preparedness programs & safeguards contingency plan (security plan) at frequency of at least once per yr.
CRUTCHFIELD, D Operating Reactors Branch 5 83/03/14 6pp 17609 017 24X Fiche 50-409, 83/03/14, 8303170179

--8303170197 Notice of issuance & availability of Amend 32 to License DPR-45.
CRUTCHFIELD, D Operating Reactors Branch 5 83/03/14 2pp 17609 023 24X Fiche 50-409, 83/03/14, 8303170179

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J A Region 3, Office of Director 83/03/22 Commonwealth Edison Co 2pp 17690 316 24X Fiche 50-000, 83/03/22, 8303240440

P Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24X Fiche 50-000, 83/02/16, 8302170082

8303020030 Forwards fee in payment of 830203 proposed Tech Spec revs.
LINDER, F Dairyland Power Cooperative 83/02/18 DIGGS, R M License Fee Management Branch 1p 17352 187 24X Fiche 50-409, 83/02/18, 8303020030

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X Fiche 50-000, 83/03/02, 8303020321

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J G Region 3, Office of Director 83/03/03 Commonwealth Edison Co 2pp 17492 014 24X Fiche 50-000, 83/03/03, 8303100364

8303090205 Submits status of TMI Action Plan Items II E 4-2 & "Operable Valves or if Closed Must be Sealed Closed." & II E 4 2 7 "Primary Containment High Radiation to Close Vent & Purge Valves" Requirements for II E 4 2 7 met.
CRUTCHFIELD, D Operating Reactors Branch 5 83/03/04 LINDER, F Dairyland Power Cooperative 3pp 17472 357 24X Fiche 50-409, 83/03/04, 8303090205

8303100510 Requests remittance of fee for 821029 application within 15 days of ltr receipt.
MILLER, W O License Fee Management Branch 83/03/04 LINDER, F Dairyland Power Cooperative 1p 17521 320 24X Fiche 50-409, 83/03/04, 8303100510

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 51pp 17660 176 24X Fiche 50-000, 83/03/07, 8303040005

8303210437 Requests extension until third refueling outage (Fall 1984) for completion of environ qualification of electrical equipment.
LINDER, F Dairyland Power Cooperative 83/03/11 CRUTCHFIELD, D Operating Reactors Branch 5 7pp 17634 201 24X Fiche 50-409, 83/03/11, 8303210437

8303170179 Forwards Amend 32 to License DPR-45 & notice of issuance & availability. Amend requires audit of emergency preparedness programs & safeguards contingency plan (security plan) at frequency of at least once per yr.
CRUTCHFIELD, D Operating Reactors Branch 5 83/03/14 LINDER, F Dairyland Power Cooperative 3pp 17609 014 24X Fiche 50-409, 83/03/14, 8303170179

--8303170188 Amend 32 to License DPR-45, requiring audit of emergency preparedness programs & safeguards contingency plan (security plan) at frequency of at least once per yr.
CRUTCHFIELD, D Operating Reactors Branch 5 83/03/14 6pp 17609 017 24X Fiche 50-409, 83/03/14, 8303170179

--8303170197 Notice of issuance & availability of Amend 32 to License DPR-45.
CRUTCHFIELD, D Operating Reactors Branch 5 83/03/14 2pp 17609 023 24X Fiche 50-409, 83/03/14, 8303170179

8303170249 Forwards order confirming commitments to implement post-TMI related items contained in NUREG-0737. Order based on 820517 & 0505 ltrs responding to Generic Ltrs 82-05 & 82-10, respectively.
CRUTCHFIELD, D Operating Reactors Branch 5 83/03/14 LINDER, F Dairyland Power Cooperative 3pp 17606 125 24X Fiche 50-409, 83/03/14, 8303170249

--8303170256 Order confirming licensee commitments on post-TMI related items contained in NUREG-0737.
EISENHUT, D G Division of Licensing 83/03/14 Dairyland Power Cooperative 9pp 17606 128 24X Fiche 50-409, 83/03/14, 8303170249

8303180054 Requests remittance of fee for 820609 application within 15 days.
MILLER, W O License Fee Management Branch 83/03/14 LINDER, F Dairyland Power Cooperative 1p 17625 254 24X Fiche 50-409, 83/03/14, 8303180054

8303220358 Forwards fee for Class II OL amend. per NRC 830106 & 0304 ltr requests.
LINDER, F Dairyland Power Cooperative 83/03/14 MILLER, W O License Fee Management Branch 1p 17648 360 24X Fiche 50-409, 83/03/14, 8303220358

8303220268 Disputes NRC Class II fee for util 820609 application for amend to License DPR-45. Util did not wish to request Tech Spec change; change has only minor safety significance & change was requested for convenience of NRC.
LINDER, F Dairyland Power Cooperative 83/03/15 MILLER, W O License Fee Management Branch 1p 17656 222 24X Fiche 50-409, 83/03/15, 8303220268

8303290402 Ack receipt of 830304 ltr re QA program description (QAPD) status. No further submittals required unless changes made to QAPD previously approved by NRC. Future QAPD changes should be submitted per 10CFR50.54.
SPESSARD, R L Region 3, Office of Director 83/03/24 LINDER, F W Dairyland Power Cooperative 1p 17725 321 24X Fiche 50-409, 83/03/24, 8303290402

--8303290408 Advises that QA program submitted w/util 800228 ltr subsequently accepted by NRC 830202 ltr. No addl submittals necessary to satisfy 10CFR50.42(a)(2) requirements.
LINDER, F Dairyland Power Cooperative 83/03/04 KEPPLER, J G Region 3, Office of Director 1p 17725 322 24X Fiche 50-409, 83/03/24, 8303290402

Q Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 11lpp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367

8303080081 Concurs w/821021 contention that shipment did not violate 10CFR30.41(b)(5), as stated in 820924 notice of violation Item 2 in notice of violation rescinded.
KEPPLER, J. G. Region 3, Office of Director. 83/02/25. LINDER, F. W. Dairyland Power Cooperative. 1p. 17457:165. 24X
Fiche: 50-409, 83/02/25, 8303080081.

8303030468 Clarifies NRC position re procedures for admitting NRC personnel to Facility Site orientation re issuance of badges, escort duties & emergency evacuation for personnel listed in Encls 1 & 2 requested.
KEPPLER, J. G. Region 3, Office of Director. 83/02/28. LINDER, F. W. Dairyland Power Cooperative. 6pp. 17409:328. 24X
Fiche: 50-409, 83/02/28, 8303030468.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303150227 Ack receipt of 830209 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409/82-20.
NORELIUS, C. E. Division of Project & Resident Programs. 83/03/11. LINDER, F. W. Dairyland Power Cooperative. 1p. 17556:080. 24X
Fiche: 50-409, 83/03/11, 8303150227.

--8303150234 Responds to NRC 830120 ltr re violations noted in IE Insp Rept 50-409/82-20. Corrective actions memo circulated re turnover checklist & correct completion of maint request forms stressed.
LINDER, F. Dairyland Power Cooperative. 83/02/09. STREETER, J. F. Division of Project & Resident Programs. 3pp. 17556:081. 24X
Fiche: 50-409, 83/03/11, 8303150227.

8303170520 Advises that Radiological Environ Svc Lab results of Spring 4 particulate analysis for Co-60 & Cs-137 comparable to Region III mobile lab results per IE Insp Rept 50-409/82-17. New calibr data forwarded to L Nelson for analysis.
PAPERIELLO, C. J. Region 3, Office of Director. 83/03/14. ZIBUNG, B. Dairyland Power Cooperative. 1p. 17610:149. 24X
Fiche: 50-409, 83/03/14, 8303170520.

8303220140 Responds to NRC request for addl info re IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Sys Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel)."
LINDER, F. Dairyland Power Cooperative. 83/03/15. JORDAN, E. L. Division of Engineering & Quality Assurance (Pre 830103). 3pp. 17658:252. 24X Fiche: 50-409, 83/03/15, 8303220140.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

R Periodic operating reports & related correspondence

8303080221 Forwards monthly operating rept for Dec 1982.
LINDER, F. Dairyland Power Cooperative. 83/01/05. Division of Data Automation & Management Information. 1p. 17450:288. 24X
Fiche: 50-409, 83/01/05, 8303080221.

--8303080227 Monthly operating rept for Dec 1982.
QADOW, G. R. Dairyland Power Cooperative. 83/01/05. 7pp.
17450:289. 24X Fiche: 50-409, 83/01/05, 8303080221.

8303150410 Forwards monthly operating rept for Jan 1983.
LINDER, F. Dairyland Power Cooperative. 83/02/09. Division of Data Automation & Management Information. 1p. 17561:255. 24X
Fiche: 50-409, 83/02/09, 8303150410.

--8303150412 Monthly operating rept for Jan 1983.
QADOW, G. R. Dairyland Power Cooperative. 83/02/09. 7pp.
17561:256. 24X Fiche: 50-409, 83/02/09, 8303150410.

8303170095 Forwards "LACBWR Annual Rept 1982."
LINDER, F. Dairyland Power Cooperative. 83/02/17. KEPPLER, J. G. Region 3, Office of Director. 1p. 17608:304. 24X
Fiche: 50-409, 83/02/17, 8303170095.

--8303170101 "LACBWR Annual Rept 1982."
* Dairyland Power Cooperative. 83/02/17. 10pp. 17608:305. 24X
Fiche: 50-409, 83/02/17, 8303170095.

8303080275 Forwards "Radioactive Effluent Rept & Environ Monitoring Rept of LACBWR, 1982."
LINDER, F. Dairyland Power Cooperative. 83/02/28. CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 17447:301. 24X
Fiche: 50-409, 83/02/28, 8303080275.

--8303080279 "Radioactive Effluent Rept & Environ Monitoring Rept of LACBWR, 1982."
* Dairyland Power Cooperative. 83/02/28. 43pp. 17447:302. 24X
Fiche: 50-409, 83/02/28, 8303080275.

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303160015 Forwards order granting extension of const completion date to 871231 for CPPR-112.
EISENHUT, D. G. Division of Licensing. 83/02/28. RHODE, G. K. Niagara Mohawk Power Corp. 4pp. 17615:059. 24X Fiche: 50-410, 83/02/28, 8303160015.

--8303160016 Safety evaluation supporting issuance of order extending latest const completion date for CPPR-112 to 871231.
* NRC - No Detailed Affiliation Given. 83/02/28. 4pp.
17615:063. 24X Fiche: 50-410, 83/02/28, 8303160015.

--8303160018 Order extending const completion date to 871231 for CPPR-112.
PURPLE, R. A. Division of Licensing. 83/02/28. Niagara Mohawk Power Corp. 3pp. 17615:067. 24X Fiche: 50-410, 83/02/28, 8303160015.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303180446 Advises that use of Paragraph NF-2130 of Summer 1982 Addenda to ASME Boiler & Pressure Vessel Code acceptable, provided use limited to certificates of compliance.
SCHWENCER, A. Licensing Branch 2. 83/03/11. RHODE, G. K. Niagara Mohawk Power Corp. 2pp. 17640:266. 24X Fiche: 50-410, 83/03/11, 8303180446.

F Security, medical, emergency & fire protection plans

8303100253 Forwards magnetic tape w/validated onsite meteorological data for Jan 1974 - Dec 1976 & Jan 1978 - Oct 1980. Data for NRC review of FSAR & environ rept. Format & content complies w/NUREG-0900 requirements. W/o tape.
MANGAN, C. V. Niagara Mohawk Power Corp. 83/03/04. SCHWENCER, A. Licensing Branch 2. 4pp. 17485:358. 24X Fiche: 50-410, 83/03/04, 8303100253.

8303170474 Forwards commitment & response to NRC telcon request re security plan. Commitment & response withheld (ref 10CFR73.21).
SUNSER, T. T. Niagara Mohawk Power Corp. 83/03/11. SCHWENCER, A. Licensing Branch 2. 1p. 17610:242. 24X Fiche: 50-410, 83/03/11, 8303170474.

8303180104 Informs that physical security & safeguards contingency plans reviewed & are acceptable for docketing. Physical security plan needs to include description of measures to be taken to insure granting unescorted access.
THOMAS, C. O. Standardization & Special Projects Branch 83/03/14
SCHWENCER, A. Licensing Branch 2 1p 17625:189 24X
Fiche: 50-410, 83/03/14, 8303180104

M. Antitrust correspondence

8303300128 Ack receipt of 830214 responses to Reg Guide 9.3. Addl info requested re electric svc or cooperative venture or study.
REGAN, W. H. Site Analysis Branch 83/03/21 MANGAN, C. V. Niagara Mohawk Power Corp 3pp 17749:357 24X Fiche: 50-410, 83/03/21, 8303300128

Q. Inspection reports, IE Bulletins & correspondence

8303030353 Forwards IE Investigation Rept 50-410/82-78 on 821101-04. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs 83/02/17
RHODE, G. K. Niagara Mohawk Power Corp 2pp 17410:203 24X
Fiche: 50-410, 83/02/17, 8303030353.

--8303030359 IE Investigation Rept 50-410/82-78 on 821101-04. No noncompliance noted. Major areas investigated: circumstances surrounding alleged improper use of S&W QC inspector trainees.
MATAKAS, R. A. , CHRISTOPHER, R. , FITZGERALD, J. A. Region 1, Office of Director 82/12/21 27pp 17410:205 24X Fiche: 50-410, 83/02/17, 8303030353.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 111pp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367

8303150595 Forwards IE Insp Rept 50-410/83-01 on 830103-0204 & notice of violation.
STAROSTECKI, R. Region 4, Office of Director 83/02/28 RHODE, G. K. Niagara Mohawk Power Corp 2pp 17567:298 24X
Fiche: 50-410, 83/02/28, 8303150595.

--8303150598 Notice of violation from insp on 830103-0204.
* Region 1, Office of Director 83/02/28 1p 17567:300 24X
Fiche: 50-410, 83/02/28, 8303150595.

--8303150600 IE Insp Rept 50-410/83-01 on 830103-0204. Noncompliance noted: failure to follow procedures for production welding due to inadequate training of craft supervisory personnel.
SCHULZ, R. D. , GRANT, J. Region 1, Office of Director KISTER, H. B. Division of Project & Resident Programs 83/02/24 16pp
17567:301 24X Fiche: 50-410, 83/02/28, 8303150595.

8303140439 Forwards SALP rept for Oct 1981 - Sept 1982, RW Starostecki 821210 transmittal ltr & util 830125 ltr proposing actions to improve performance. Performance acceptable, but mgt attention re QA needed. W/list of 821220 meeting attendees.
HAYNES, R. C. Region 1, Office of Director 83/03/07 RHODE, G. K. Niagara Mohawk Power Corp 5pp 17542:135 24X
Fiche: 50-410, 83/03/07, 8303140439

--8303140445 SALP rept for Oct 1981 - Sept 1982. Overall performance acceptable. Weaknesses identified in area of QA.
* Region 1, Office of Director 82/11/24 29pp 17542:140 24X
Fiche: 50-410, 83/03/07, 8303140439

--8303140451 Forwards SALP rept for Oct 1981 - Sept 1982. Meeting scheduled for 821220 to discuss assessment. Util should be prepared to address status & progress of efforts re QA.
STAROSTECKI, R. Division of Project & Resident Programs 82/12/10
RHODE, G. K. Niagara Mohawk Power Corp 3pp 17542:169 24X
Fiche: 50-410, 83/03/07, 8303140439

--8303140457 Comments on 821124 SALP rept for Oct 1981 - Sept 1982. Surveillance of Reactor Controls, Inc QA activities increased, preventive maint procedures strengthened & QA organization reorganized.
RHODE, G. K. Niagara Mohawk Power Corp 83/01/25 STAROSTECKI, R. Division of Project & Resident Programs 3pp 17542:172 24X
Fiche: 50-410, 83/03/07, 8303140439

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 11?pp 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12ipp 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

S. Reportable occurrences, LERs & related correspondence

8303010628 Interim deficiency rept re attempt to artificially enhance radiograph for weld F of T-quencher. Initially reported on 830119. Investigation continuing. Final rept will be submitted by 830615.
MANGAN, C. V. Niagara Mohawk Power Corp 83/02/17 STAROSTECKI, R. Division of Project & Resident Programs 2pp 17336:267 24X
Fiche: 50-410, 83/02/17, 8303010628.

8303080057 Interim deficiency rept re separation criteria for power generation control complex equipment supplied by GE. Initially reported on 830120. GE notified of deficiency through Nonconformance Rept 53. Final rept due by 830401.
MANNO, S. F. Niagara Mohawk Power Corp 83/02/23 STAROSTECKI, R. Division of Project & Resident Programs 2pp 17436:283 24X
Fiche: 50-410, 83/02/23, 8303080057.

8303140613 Final deficiency rept re problem concerning ITT Grinnell Category II planners for Category I work. Initially reported on 821026. Field Planner SB-400 canceled. General Engineering Procedure 40 modified ensuring correct category designation.
MANNO, S. F. Niagara Mohawk Power Corp 83/03/01 STAROSTECKI, R. Division of Project & Resident Programs 2pp 17534:033 24X
Fiche: 50-410, 83/03/01, 8303140613.

8303210578 Interim deficiency rept re Power Generation control complex floor module welds supplied by GE. Initially reported on 830207. Matter under investigation. Final rept to be submitted by 830515.
MANNO, S. F. Niagara Mohawk Power Corp 83/03/07 STAROSTECKI, R. Region 1, Office of Director 2pp 17632:238 24X
Fiche: 50-410, 83/03/07, 8303210578.

8303290427 Final deficiency rept re problem concerning ITT Grinnell T-quencher diffusion holes. Initially reported on 820729. Vendor performed 100% dimensional check on T-quenchers. T-quenchers w/10% increased loads within ASME Code limits.
MANNO, S. F. Niagara Mohawk Power Corp 83/03/16 STAROSTECKI, R. Division of Project & Resident Programs 2pp 17726:226 24X
Fiche: 50-410, 83/03/16, 8303290427.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303020307 Notification of 830223 meeting w/util to discuss emergency preparedness plan & control room review plan.
LAZO, L. Licensing Branch 3 83/02/22 KNIGHTON, G. W. Licensing Branch 3 3pp 17355:285 24X Fiche: 50-412, 83/02/22, 8303020307.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321.

# DOCKETED ITEMS

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12) Svc list encl.
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 5lpp 17660 176 24X
Fiche 50-000, 83/03/07, 8303040005

8303180638 Summary of 830209 meeting w/util in Bethesda, MD re util schedule for detailed control room design review Both unit control rooms will be housed in same room.
LAZO, L Licensing Branch 3 83/03/09 Licensing Branch 3 4pp 17626 302 24X Fiche 50-412, 83/03/09, 8303180638

8303230211 Trip rept of caseload forecast panel 830126-28 site visit to collect loading data for use in development of schedule for reviewing OL application.
LAZO, L Licensing Branch 3 83/03/09 Licensing Branch 3 88pp 17686 219 24X Fiche 50-412, 83/03/09, 8303230211

F. Security, medical, emergency & fire protection plans

8303020307 Notification of 830223 meeting w/util to discuss emergency preparedness plan & control room review plan.
LAZO, L Licensing Branch 3 83/02/22 KNIGHTON, G W Licensing Branch 3 3pp 17355 285 24X Fiche 50-412, 83/02/22, 8303020307

8303160750 Notification of 830317 meeting w/util in Bethesda, MD to discuss security plan.
LAZO, L Licensing Branch 3 83/02/24 KNIGHTON, G Licensing Branch 3 3pp 17600 227 24X Fiche 50-412, 83/02/24, 8303160750

G. Inspection reports, IE Bulletins & correspondence

8303100380 Forwards IE Insp Rept 50-412/83-03 on 830124-27 No noncompliance noted.
MARTIN, T T Division of Engineering & Technical Programs 83/02/23
WOOLEVER, E J Duquesne Light Co 2pp 17488 286 24X
Fiche 50-412, 83/02/23, 8303100380

--8303100382 IE Insp Rept 50-412/83-03 on 830124-27 No noncompliance noted Major areas inspected installation of safety-related cables, cable trays/conduits & equipment.
FINKEL, A E ; ANDERSON, A E Region 1, Office of Director
83/02/15 5pp 17488 288 24X Fiche 50-412, 83/02/23, 8303100380

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 11lpp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc 117pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380

8303160215 Ack receipt of 830131 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-412/82-11.
STAROSTECKI, R Division of Project & Resident Programs 83/03/11
WOOLEVER, E J Duquesne Light Co 1p 17596 311 24X
Fiche 50-412, 83/03/11, 8303160215

--8303160224 Responds to NRC 831101 ltr re violations noted in IE Insp Rept 50-412/82-11 Corrective actions QA program inspected & found adequate Duct support connections evaluated.
WOOLEVER, E J Duquesne Light Co 83/01/31 STAROSTECKI, R Division of Project & Resident Programs 11pp 17596 312 24X
Fiche 50-412, 83/03/11, 8303160215

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 12lpp 17774 352 24X Fiche 50-000, 83/03/21, 8212060387

S. Reportable occurrences, LERs & related correspondence

8303030286 Final Significant Deficiency Rept 82-02 re RCS wide-range pressure transmitters Two transmitters located outside containment will be connected by sealed sys to satisfy post-accident accuracy requirements.
WOOLEVER, E J Duquesne Light Co 83/02/24 HAYNES, R C Region 1, Office of Director 4pp 17410 294 24X Fiche 50-412, 83/02/24, 8303030286

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000, 83/02/24, 8302250505

8303090283 Forwards projections for licensing exams requiring NRC site visits, in response to 830101 Generic Ltr 83-01.
WOOLEVER, E J Duquesne Light Co 83/02/28 KNIGHTON, G Licensing Branch 3 3pp 17473 332 24X Fiche 50-412, 83/02/28, 8303090283

DOCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl.
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24X
Fiche 50-000, 83/02/16, 8302170082

8302240208 Amend 29 to OL applications, consisting of Rev 7 to FSAR.
TUCKER, H B Duke Power Co 83/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 17269 001 24X Fiche 50-413, 83/02/22, 8302240208

8303010496 Forwards summary of 821213 & 14 meetings w/Westinghouse & NRC Reactor Sys Branch in Bethesda, MD re open items from previous meeting List of attendees encl.
TUCKER, H B Duke Power Co 83/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 8pp 17343 339 24X Fiche 50-413, 83/02/22, 8303010496

8303040004 Notifies that NRC position re reactor trip breaker remains unchanged following 830126 repeal meeting w/Westinghouse.
ADENSAM, E G Licensing Branch 4 83/02/23 TUCKER, H B Duke Power Co 2pp 17426 063 24X Fiche 50-413, 83/02/23, 8303040004

--8302100191 Denies Westinghouse 830126 appeal re NRC position on testing of reactor trip breakers Proposal to resolve issue for all licensed Westinghouse plants will be initiated.
HOUSTON, R W Assistant Director for Reactor Safety 83/02/02
RAHE, E P Westinghouse Electric Corp 2pp 17426 065 24X
Fiche 50-413, 83/02/23, 8303040004

8303070141 Forwards "Procedures Generation Package," "Technical Verification of Nuclear Station Emergency Procedures & Guidelines," "Writers Guide for Emergency & Abnormal . . ." & "Control Room Review Plan," per NUREG-0737, Suppl 1.
TUCKER, H B Duke Power Co 83/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 17432 011 24X Fiche 50-000, 83/02/28, 8303070141

--8303070152 "Procedures Generation Package, Catawba Nuclear Station."
* Duke Power Co 83/02/28 9pp 17432 013 24X
Fiche 50-000, 83/02/28, 8303070141

--8303070158 "Verification Process for Emergency Procedures, Catawba Nuclear Station."
* Duke Power Co 83/02/28 8pp 17432 022 24X
Fiche 50-000, 83/02/28, 8303070141

--8303070164 "Technical Verification of Nuclear Station Emergency Procedures & Guidelines," reactor safety procedures.
SWINDLEHURST, G ; ABRAHAM, P M Duke Power Co RS-003 83/02/21
23pp 17432 030 24X Fiche 50-000, 83/02/28, 8303070141

--8303070167 "Validation of Emergency Procedures, Catawba Nuclear Station."
* Duke Power Co 83/02/28 12pp 17432 053 24X
Fiche 50-000, 83/02/28, 8303070141

--8303070169 "Control Room Review Plan for Oconee, McGuire & Catawba Nuclear Stations, Duke Power Co."
* Duke Power Co C/1800023 R03 83/02/15 38pp 17432.065
24X Fiche 50-000, 83/02/28, 8303070141.

--8303070173 "Writers Guide for Emergency & Abnormal Procedures, Catawba Nuclear Station."
* Duke Power Co 83/02/28 84pp 17432.103 24X
Fiche 50-000, 83/02/28, 8303070141.

8303080294 Forwards revised "Offsite Dose Calculation Manual for Duke Power Nuclear Stations."
TUCKER, H B Duke Power Co 83/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17455.196 24X
Fiche 50-000, 83/02/28, 8303080294.

--8303080324 Revised "Offsite Dose Calculation Manual for Duke Power Nuclear Stations."
BIRCH, M L Duke Power Co 83/02/28 96pp 17455.198 24X
Fiche 50-000, 83/02/28, 8303080294.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in BTS on ESF cleanup sys. Svc list encl.
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700.303 24X
Fiche 50-000, 83/03/02, 8303020321.

8303160002 Approves 821208 application for withholding, per 10CFR2.790, info re improved thermal design procedures, submitted in response to NRC Question 492.2.
ADENSAM, E G Licensing Branch 4 83/03/03 TUCKER, H B Duke Power Co 2pp 17615.112 24X Fiche 50-413, 83/03/03, 8303160002.

8303160003 Forwards request for addl info re environ equipment qualification program. Justification for interim operation should be provided prior to exceeding 5% power for equipment utilizing nonmetallics not environmentally qualified.
ADENSAM, E G Licensing Branch 4 83/03/03 TUCKER, H B Duke Power Co 5pp 17615.107 24X Fiche 50-413, 83/03/03, 8303160003.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp 17660.176 24X
Fiche 50-000, 83/03/07, 8303040005.

8303160766 Summary of 830121 meeting w/Design Review Panel in Bethesda, MD re D2/D3 steam generator mod.
HOPKINS, J B Licensing Branch 4 83/03/08 Licensing Branch 4 15pp 17600.202 24X Fiche 50-000, 83/03/08, 8303160766.

8303140395 Forwards "Pump & Valve Inservice Testing Program, Unit 1."
TUCKER, H B Duke Power Co 83/03/09 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 3pp 17542.244 24X Fiche 50-413, 83/03/09, 8303140395.

--8303140397 "Pump & Valve Inservice Testing Program, Unit 1." W/62 oversize drawings. Aperture cards are available in PDR.
* Duke Power Co 83/03/09 126pp 17542.247 24X
Fiche 50-413, 83/03/09, 8303140395.

8303160025 Approves 830119 request for withholding, per 10CFR2.790 response to NRC Question 492.2 re improved thermal design procedures.
ADENSAM, E G Licensing Branch 4 83/03/10 TUCKER, H B Duke Power Co 3pp 17615.054 24X Fiche 50-413, 83/03/10, 8303160025.

8303230527 Forwards NUREG-0996 evaluating util design review panel rept on mod to Westinghouse D2/D3 steam generators. W/o encl. Generator mods acceptable.
NOVAK, T M Assistant Director for Licensing 83/03/16 TUCKER, H B Duke Power Co PARRIS, H G Tennessee Valley Authority DIXON, D W South Carolina Electric & Gas Co. 8pp 17677.232 24X
Fiche 50-000, 83/03/16, 8303230527.

8303280306 Notification of 830321 meeting w/Design Review Panel in Bethesda, MD to discuss info re forward flush transient on steam generators D2/D3. Meeting closed to public due to proprietary nature of info.
HOPKINS, J B Licensing Branch 4 83/03/18 ADENSAM, E G Licensing Branch 4 6pp 17713.301 24X Fiche 50-000, 83/03/18, 8303280306.

8303280193 Forwards response to NRC 830110 Question 210.122 re design documentation for Class 2 & 3 piping sys. Table re guidelines for design & application of branch outlets - shop & field fabrication encl.
TUCKER, H B Duke Power Co 83/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 9pp 17708.297 24X Fiche 50-413, 83/03/23, 8303280195.

--8303280204 Rev 5 to "Allowable Design Pressures for Various Branch Connection Configurations To Be Used in ASME Section III Class 1 Piping of Catawba Nuclear Power Station."
* EDS Nuclear, Inc 82/02/24 19pp 17708.306 24X
Fiche 50-413, 83/03/23, 8303280193.

--8303280212 Rev 1 to "Catawba 1 & 2, Procedure for Selection of Type of Piping Branch Connection, Duke Classes B, C, E, F, G."
* Duke Power Co 81/08/19 16pp 17708.325 24X
Fiche 50-413, 83/03/23, 8303280193.

--8303280223 Rev 2 to "CLIBIC Computer Program for ASME Section III Class 1 Area Reinforcement Analysis for Certain Branch Connection Types of Catawba Nuclear Power Station." Certifications of engineering calculations encl.
YEE, V, ROSSELLE, C J EDS Nuclear, Inc 78/03/22 203pp 17708.341 24X Fiche 50-413, 83/03/23, 8303280193.

8303290092 Notification of 830324 meeting w/design review panel in Bethesda, MD to discuss info re forward flush transient on D2/D3 steam generator.
HOPKINS, J B Licensing Branch 4 83/03/23 ADENSAM, E G Licensing Branch 4 6pp 17729.236 24X Fiche 50-000, 83/03/23, 8303290092.

8303290843 Forwards Chairman Palladino 830315 ltr re ACRS review of OL application. W/o encl.
ADENSAM, E G Licensing Branch 4 83/03/23 TUCKER, H B Duke Power Co 2pp 17746.075 24X Fiche 50-413, 83/03/23, 8303290843.

8303290850 Forwards request for addl info re seismic & dynamic qualification of equipment & pump & valve operability. Info needed by 830506.
ADENSAM, E G Licensing Branch 4 83/03/23 TUCKER, H B Duke Power Co 30pp 17746.044 24X Fiche 50-413, 83/03/23, 8303290850.

D. NRC Draft/Final Environmental Statements, suppls & correspondence

8303140425 Comments on FES submitted on 830110. Potential impacts of proposed thermal discharge on water quality stds & aquatic life as well as aquatic organism mortality resulting from impingement & entrainment not adequately described.
BLANCHARD, B Interior, Dept of 83/03/09 ADENSAM, E G Licensing Branch 4 2pp 17542.206 24X Fiche 50-413, 83/03/09, 8303140425.

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303010724 Forwards SER. Eighteen issues remain outstanding. All issues must be resolved prior to decision on issuance of OL. W/o encl.
NOVAK, T M Assistant Director for Licensing 83/02/10 RAY, J ACRS - Advisory Committee on Reactor Safeguards 1p 17347.362
24X Fiche 50-413, 83/02/10, 8303010724.

8303020149 Forwards SER re operation of facility (NUREG-0954) & notice of issuance & availability. W/o SER.
NOVAK, T M Assistant Director for Licensing 83/02/22 TUCKER, H B Duke Power Co 2pp 17359.141 24X Fiche 50-413, 83/02/22, 8303020149.

--8303020152 Notice of issuance & availability of SER (NUREG-0954).
ADENSAM, E G Licensing Branch 4 83/02/22 2pp 17359.143 24X
Fiche 50-413, 83/02/22, 8303020149.

8303230269 Forwards response to 830222 request for addl info on SER confirmatory issues re SSI for bldgs not founded on rock & vertical seismic response spectra.
TUCKER, H B Duke Power Co 83/03/15 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 199pp 17662.034 24X Fiche 50-413, 83/03/15, 8303230269.

F. Security, medical, emergency & fire protection plans

8303090162 Forwards Rev 3 to security plan. Rev withheld (ref 10CFR73.21).
TUCKER, H B Duke Power Co 83/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 17469.358 24X Fiche 50-413, 83/02/24, 8303090162.

8303100162 Releases public version of revised emergency plan.
FELTON, J M Division of Rules and Records 83/03/02 Document Management Branch 1p 17495.213 24X Fiche 50-413, 83/03/02, 8303100162.

# DOCKETED ITEMS

--8303100168 Forwards public version of Rev 2 to emergency plan.
TUCKER, H B Duke Power Co 83/02/16 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 17495 214 24X Fiche 50-413, 83/03/02, 8303100162

--8303100174 Public version of Rev 2 to emergency plan.
HAMPTON, J W Duke Power Co 83/01/31 158pp 17495 216 24X Fiche 50-413, 83/03/02, 8303100162

8303290475 Requests exemption from 10CFR50 App E, Item IV.F.h & 10CFR50 47 b(14) re active participation of crisis mgt ctr personnel for each station during annual emergency preparedness exercise.
TUCKER, H B Duke Power Co 83/03/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17724 324 24X Fiche 50-000, 83/03/09, 8303290475

8303220321 Advises that interest in & time available for drills pilot program nonexistent Limited drill pilot program could be conducted during simulator requalification training.
BOSTIAN, R W Duke Power Co 83/03/10 EISENHUT, D G Division of Licensing 1p 17655 348 24X Fiche 50-000, 83/03/10, 8303220321

8303210249 Requests technical assistance in reviewing addl info on planned relocation of central alarm switch License condition re physical security plan, safeguards contingency plan & training & qualification plan submitted W/o encl.
THOMAS, C O Standardization & Special Projects Branch 83/03/15 MCCORKLE, G W Power Reactor Safeguards Licensing Branch 1p 17659 071 24X Fiche 50-413, 83/03/15, 8303210249

8303240113 Releases public version of revised crisis mgt plan implementing procedures.
FELTON, J M Division of Rules and Records 83/03/21 Document Management Branch 1p 17700 029 24X Fiche 50-000, 83/03/21, 8303240113

--8303240120 Forwards public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.1 re recovery manager & immediate staff group plan & 5.3.4 re scheduling/pl nning support group.
TUCKER, H B ke Power Co 83/03/08 DENTON, H R Office of Nuclear React Regulation, Director 2pp 17700 030 24X Fiche 50-000, L /03/21, 8303240113

--8303240127 Public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.1 re recovery manager & immediate staff group plan & 5.3.4 re scheduling/planning support group.
* Duke Power Co 83/02/28 175pp 24X Fiche 50-000, 83/03/21, 8303240113

Q Adjudicatory correspondence

8303010396 Memorandum & order ruling on spent fuel Contentions 10 & 19. Contention 10 & transshipment part of Contention 19 rejected as impermissible attacks on Commission rule.
KELLEY, J L Atomic Safety and Licensing Board Panel 83/02/25 Palmetto Alliance 9pp 17346 196 24X Fiche 50-413, 83/02/25, 8303010396

8303040534 Supplemental response to interrogatories & requests to produce re Palmetto Alliance Contentions 6, 7, 8, 27 & 44, in response to ASLB 830209 memorandum & order Certificate of Svc encl Related correspondence.
CARR, A V Duke Power Co CARR, A V Debevoise & Liberman 83/02/28 Palmetto Alliance 80pp 17366 052 24X Fiche 50-413, 83/02/28, 8303040534

8303080117 Memorandum & order memorializing 830302 conference call re DES Contentions 11 & 22, SER & emergency planning contentions, proposed protective order & Palmetto Alliance followup interrogatories &/or answers.
KELLEY, J L Atomic Safety and Licensing Board Panel 83/03/04 5pp 17458 271 24X Fiche 50-413, 83/03/04, 8303080117

8303110214 Forwards affidavit of nondisclosure to be signed in order to receive B&W proprietary document in response to Palmetto Alliance Interrogatory 2 on Contention 44 Related correspondence W/o encl.
CARR, A V Duke Power Co 83/03/07 GUILD, R Guild, R 2pp 17519 295 24X Fiche 50-413, 83/03/07, 8303110214

8303100161 First set of interrogatories & document production requests on Contention DES-17 Certificate of Svc encl.
JOHNSON, G E Hearing Branch 4 83/03/08 Palmetto Alliance 6pp 17485 224 24X Fiche 50-413, 83/03/08, 8303100161

8303140291 Memorandum & order commenting on discovery matters ASLB tentative position is to uphold applicant work product privilege Telephone conference call scheduled for 830317.
KELLEY, J L Atomic Safety and Licensing Board Panel 83/03/10 4pp 17535 052 24X Fiche 50-413, 83/03/10, 8303140291

8303150374 Response to interrogatories & requests to produce Certificate of Svc encl.
JOHNSON, G E Hearing Branch 4 83/03/14 Palmetto Alliance 83pp 17562 035 24X Fiche 50-413, 83/03/14, 8303150374

8303230192 Followup interrogatories & requests to produce re Palmetto Contentions 6, 7, 8, 16, 27 & 44 Certificate of Svc encl Related correspondence.
GUILD, R Palmetto Alliance GUILD, R Guild, R 83/03/16 Duke Power Co 18pp 17665 222 24X Fiche 50-413, 83/03/16, 8303230192

8303240584 Response to 821215 second set of interrogatories & document production requests Affidavit of Svc encl Related correspondence.
RILEY, J L Carolina Environmental Study Group 83/03/17 Office of the Executive Legal Director 13pp 17683 122 24X Fiche 50-413, 83/03/17, 8303240584

8303230242 Forwards DJ Abernethy, CW Graves & JC Wolfmeyer interrogatory affidavits JL Elliott job title should be changed to principal engineer, mechanical-nuclear div Related correspondence.
CARR, A V Duke Power Co 83/03/18 GUILD, R Guild, R 4pp 17661 147 24X Fiche 50-413, 83/03/18, 8303230242

8303250146 Provides rept on contacts made w/affected employees re discovery on Palmetto Alliance QA Contention 6 Ltrs sent to terminated, active & former plant QA employees & employees identified in intervenor documents Related correspondence.
CARR, A V Duke Power Co 83/03/22 KELLEY, J L , CALLIHAN, A D , FOSTER, R F Atomic Safety and Licensing Board Panel 6pp 17691 005 24X Fiche 50-413, 83/03/22, 8303250146

8303290513 Memorandum & order making further rulings on environ contentions Admits first sentences of Contention DES-11. Smoothing aspect of Contention DES-22 rejected upon reconsideration Contention DES-17 unchanged.
KELLEY, J L Atomic Safety and Licensing Board Panel 83/03/24 5pp 17724 094 24X Fiche 50-413, 83/03/24, 8303290513

8303310345 Response to 830308 first set of interrogatories & document requests on Contention DES-17 Affirmation of Svc encl Related correspondence.
GUILD, R Palmetto Alliance RILEY, J L Carolina Environmental Study Group GUILD, R Guild, R 83/03/28 Office of the Executive Legal Director 6pp 17755 023 24X Fiche 50-413, 83/03/28, 8303310345

8303310353 Response in opposition to applicant request to limit contacts by Palmetto Alliance w/applicant employees. Protection sought not supported by good cause Applicant may later seek discovery limitation Certificate of Svc encl.
JOHNSON, G E Hearing Branch 4 83/03/30 Atomic Safety and Licensing Board Panel 7pp 17755 029 24X Fiche 50-413, 83/03/30, 8303310353

K Utility Final Safety Analysis Report (FSAR) & amends

8302240208 Amend 29 to OL applications, consisting of Rev 7 to FSAR.
TUCKER, H B Duke Power Co 83/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 17269 001 24X Fiche 50-413, 83/02/22, 8302240208

--8302240210 Rev 7 to FSAR W/134 oversize P&IDs Aperture cards are available in PDR.
* Duke Power Co 83/02/22 866pp 17269 003 24X Fiche 50-413, 83/02/22, 8302240208

Q Inspection reports, IE Bulletins & correspondence

8303010301 Responds to NRC ltr re violations noted in IE Insp Rents 50-413/82-03 & 50-414/82-03 Addl insps & cleaning unnecessary.
TUCKER, H B Duke Power Co 82/12/01 O'REILLY, J F Region 2, Office of Director 1p 17333 335 24X Fiche 50-413, 82/12/01, 8303010301

8303210479 Responds to NRC ltr re violations noted in IE Insp Repts 50-413/82-21 & 50-414/82-19 Corrective actions nonconforming item evaluation team formed to review repts & identify areas of concern Compliance achieved as of 830114.
TUCKER, H B Duke Power Co 83/01/14 O'REILLY, J P Region 2, Office of Director 3pp 17631 294 24X Fiche 50-413, 83/01/14, 8303210479

8303010200 Advises that addl info re IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp (Asiatic clam) & Mytilus (mussel)," will be available by 830318.
TUCKER, H.B. Duke Power Co. 83/02/07 O'REILLY, J.P. Region 2, Office of Director 1p 17332.351 24X Fiche 50-413, 83/02/07, 8303010200.

8303010231 Forwards IE Insp Repts 50-413/83-01 & 50-414/83-01 on 830111-14. No noncompliance noted.
DANCE, H.C. Division of Project & Resident Programs 83/02/10.
TUCKER, H.B. Duke Power Co. 2pp 17335.056 24X
Fiche 50-413, 83/02/10, 8303010231.

--8303010235 IE Insp Repts 50-413/83-01 & 50-414/83-01 on 830111-14. No noncompliance noted. Major areas inspected: electrical cable termination, observation of work & review of QC records & licensee identified items.
RUFF, A.B., CONLON, T.E. Division of Engineering & Radiological Safety Programs 83/02/07 4pp 17335.058 24X
Fiche 50-413, 83/02/10, 8303010231.

8303210708 Forwards IE Insp Repts 50-413/82-33 & 50-414/82-31 on 821226-830125. No noncompliance noted.
DANCE, H.C. Division of Project & Resident Programs 83/02/14
TUCKER, H.B. Duke Power Co. 2pp 17635.065 24X
Fiche 50-413, 83/02/14, 8303210708.

--8303210716 IE Insp Repts 50-413/82-33 & 50-414/82-31 on 821226-830125. No noncompliance noted. Major areas inspected: followup on licensee actions re QC welding insp concerns, QA surveillance repts & safety-related piping (welding).
VAN DOORN, P.K. Region 2, Office of Director IGNATONIS, A.J. Division of Project & Resident Programs 83/02/11 5pp 17635.067 24X Fiche 50-413, 83/02/14, 8303210708.

8303210471 Ack receipt of IE Insp Repts 50-413/82-31 & 50-414/82-29. No proprietary info.
TUCKER, H.B. Duke Power Co. 83/02/22 O'REILLY, J.P. Region 2, Office of Director 1p 17634.158 24X Fiche 50-413, 83/02/22, 8303210471.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11lpp 17521.001 24X Fiche 50-000, 83/02/25, 8212060367.

8303210334 Ack receipt of 830114 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/82-21 & 50-414/82-19.
LEWIS, R.C. Division of Project & Residents Programs 83/03/10.
TUCKER, H.B. Duke Power Co. 1p 17634.236 24X
Fiche 50-413, 83/03/10, 8303210334.

8303210337 Ack receipt of 821201 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/82-03 & 50-414/82-03.
DANCE, H.C. Division of Project & Resident Programs 83/03/10.
TUCKER, H.B. Duke Power Co. 1p 17634.163 24X
Fiche 50-413, 83/03/10, 8303210337.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp 17611.070 24X Fiche 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp 17774.352 24X Fiche 50-000, 83/03/21, 8212060387.

S. Reportable occurrences: LERs & related correspondence

8303210640 Supplemental Interim Significant Deficiency Rept SD 413/82-17 re evaluation of base metal indications. Initially reported on 820903. No significant defects exist in erected plant. Review of previous radiographs not necessary.
TUCKER, H.B. Duke Power Co. 83/02/28 O'REILLY, J.P. Region 2, Office of Director 2pp 17636.242 24X Fiche 50-413, 83/02/28, 8303210440.

8303140515 Significant deficiency rept re inappropriate governor drive matl coupling on diesel generator. Corrective action scheduled for completion 830301 will be delayed until 831001, due to delay in mfg of replacement couplings.
TUCKER, H.B. Duke Power Co. 83/03/01 O'REILLY, J.P. Region 2, Office of Director 1p 17540.345 24X Fiche 50-413, 83/03/01, 8303140515.

T. Hearing transcripts on non-antitrust matters

8303090078 Transcript of ACRS Subcommittee on Catawba Nuclear Power Station Units 1 & 2 830304 meeting in Charlotte, NC. Pp 1-245. Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards 83/03/04
431pp 17467.065 24X Fiche 50-413, 83/03/04, 8303090078.

8303090084 Transcript of ACRS Subcommittee on Catawba Nuclear Power Station Units 1 & 2 830305 meeting in Charlotte, NC. Pp 246-459. Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards 83/03/05
297pp 17468.136 24X Fiche 50-413, 83/03/05, 8303090084.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D.G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp 24X Fiche 50-000, 83/02/24, 8302250505.

DOCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D.G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492.033 24X
Fiche 50-000, 83/02/16, 8302170082.

8302240208 Amend 29 to OL applications, consisting of Rev 7 to FSAR.
TUCKER, H.B. Duke Power Co. 83/02/22 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 17269.001 24X
Fiche 50-413, 83/02/22, 8302240208.

8303010496 Forwards summary of 821213 & 14 meetings w/Westinghouse & NRC Reactor Sys Branch in Bethesda, MD re open items from previous meeting. List of attendees encl.
TUCKER, H.B. Duke Power Co. 83/02/22 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ADENSAM, E.G. Licensing Branch 4 8pp 17343.339 24X Fiche 50-413, 83/02/22, 8303010496.

8303040004 Notifies that NRC position re reactor trip breaker remains unchanged following 830126 repeal meeting w/Westinghouse.
ADENSAM, E.G. Licensing Branch 4 83/02/23 TUCKER, H.B. Duke Power Co. 2pp 17426.063 24X Fiche 50-413, 83/02/23, 8303040004.

--8302100191 Denies Westinghouse 830126 appeal re NRC position on testing of reactor trip breakers. Proposal to resolve issue for all licensed Westinghouse plants will be initiated.
HOUSTON, R.W. Assistant Director for Reactor Safety 83/02/02
RAHE, E.P. Westinghouse Electric Corp. 2pp 17426.065 24X
Fiche 50-413, 83/02/23, 8303040004.

8303070141 Forwards "Procedures Generation Package," "Technical Verification of Nuclear Station Emergency Procedures & Guidelines," "Writers Guide for Emergency & Abnormal..." & "Control Room Review Plan," per NUREG-0737, Suppl 1.
TUCKER, H.B. Duke Power Co. 83/02/28 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ADENSAM, E.G. Licensing Branch 4 2pp 17432.011 24X Fiche 50-000, 83/02/28, 8303070141.

--8303070152 "Procedures Generation Package, Catawba Nuclear Station."
* Duke Power Co. 83/02/28 9pp 17432.013 24X
Fiche 50-000, 83/02/28, 8303070141.

--8303070156 "Verification Process for Emergency Procedures, Catawba Nuclear Station."
* Duke Power Co. 83/02/28 8pp 17432.022 24X
Fiche 50-000, 83/02/28, 8303070141.

--8303070164 "Technical Verification of Nuclear Station Emergency Procedures & Guidelines," reactor safety procedures.
SWINDLEHURST, G., ABRAHAM, P.M. Duke Power Co. RS-003 83/02/21
23pp 17432.030 24X Fiche 50-000, 83/02/28, 8303070141.

--8303070167 "Validation of Emergency Procedures, Catawba Nuclear Station."
* Duke Power Co. 83/02/28. 12pp. 17432:053. 24X
Fiche: 50-000, 83/02/28, 8303070141.

--8303070169 "Control Room Review Plan for Oconee, McGuire & Catawba Nuclear Stations, Duke Power Co."
* Duke Power Co. C/1800023 R03. 83/02/15. 38pp. 17432:065. 24X Fiche: 50-000, 83/02/28, 8303070141.

--8303070173 "Writers Guide for Emergency & Abnormal Procedures, Catawba Nuclear Station."
* Duke Power Co. 83/02/28. 84pp. 17432:103. 24X
Fiche: 50-000, 83/02/28, 8303070141.

8303080294 Forwards revised "Offsite Dose Calculation Manual for Duke Power Nuclear Stations."
TUCKER, H.B. Duke Power Co. 83/02/28. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 17455:196. 24X
Fiche: 50-000, 83/02/28, 8303080294.

--8303080324 Revised "Offsite Dose Calculation Manual for Duke Power Nuclear Stations."
BIRCH, M.L. Duke Power Co. 83/02/28. 96pp. 17455:198. 24X
Fiche: 50-000, 83/02/28, 8303080294.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D.G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303160002 Approves 821208 application for withholding, per 10CFR2.790, info re improved thermal design procedures, submitted in response to NRC Question 492.2.
ADENSAM, E.G. Licensing Branch 4. 83/03/03. TUCKER, H.B. Duke Power Co. 2pp. 17615:112. 24X Fiche: 50-413, 83/03/03, 8303160002.

8303160003 Forwards request for addl info re environ equipment qualification program. Justification for interim operation should be provided prior to exceeding 5% power for equipment utilizing nonmetallics not environmentally qualified.
ADENSAM, E.G. Licensing Branch 4. 83/03/03. TUCKER, H.B. Duke Power Co. 3pp. 17615:107. 24X Fiche: 50-413, 83/03/03, 8303160003.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D.G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303160025 Approves 830119 request for withholding, per 10CFR2.790 response to NRC Question 492.2 re improved thermal design procedures.
ADENSAM, E.G. Licensing Branch 4. 83/03/10. TUCKER, H.B. Duke Power Co. 3pp. 17615:054. 24X Fiche: 50-413, 83/03/10, 8303160025.

8303280193 Forwards response to NRC 830110 Question 210.122 re design documentation for Class 2 & 3 piping sys. Table re guidelines for design & application of branch outlets - shop & field fabrication encl.
TUCKER, H.B. Duke Power Co. 83/03/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 9pp. 17708:297. 24X Fiche: 50-413, 83/03/23, 8303280193.

--8303280204 Rev 5 to "Allowable Design Pressures for Various Branch Connection Configurations To Be Used in ASME Section III Class 1 Piping of Catawba Nuclear Power Station."
* EDS Nuclear, Inc. 82/02/24. 19pp. 17708:306. 24X
Fiche: 50-413, 83/03/23, 8303280193.

--8303280212 Rev 1 to "Catawba 1 & 2 Procedure for Selection of Type of Piping Branch Connection, Duke Classes B,C,E,F,G."
* Duke Power Co. 81/08/19. 16pp. 17708:325. 24X
Fiche: 50-413, 83/03/23, 8303280193.

--8303280223 Rev 2 to "CL1BIC Computer Program for ASME Section III Class 1 Area Reinforcement Analysis for Certain Branch Connection Types of Catawba Nuclear Power Station." Certifications of engineering calculations encl.
YEE, V., ROSSELLE, C.J. EDS Nuclear, Inc. 78/03/22. 203pp. 17708:341. 24X Fiche: 50-413, 83/03/23, 8303280193.

8303290843 Forwards Chairman Palladino 830315 ltr re ACRS review of OL application W/o encl.
ADENSAM, E.G. Licensing Branch 4. 83/03/23. TUCKER, H.B. Duke Power Co. 2pp. 17746:075. 24X Fiche: 50-413, 83/03/23, 8303290943.

8303290850 Forwards request for addl info re seismic & dynamic qualification of equipment & pump & valve operability. Info needed by 830506.
ADENSAM, E.G. Licensing Branch 4. 83/03/23. TUCKER, H.B. Duke Power Co. 30pp. 17746:044. 24X Fiche: 50-413, 83/03/23, 8303290850.

D. NRC Draft/Final Environmental Statement & suppls & correspondence

8303140425 Comments on FES submitted on 830110 Potential impacts of proposed thermal discharge on water quality stds & aquatic life as well as aquatic organism mortality resulting from impingement & entrainment not adequately described.
BLANCHARD, B. Interior, Dept. of. 83/03/09. ADENSAM, E.G. Licensing Branch 4. 2pp. 17542:206. 24X Fiche: 50-413, 83/03/09, 8303140425.

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303010724 Forwards SER. Eighteen issues remain outstanding. All issues must be resolved prior to decision on issuance of OL. W/o encl.
NOVAK, T.M. Assistant Director for Licensing. 83/02/10. RAY, J. ACRS - Advisory Committee on Reactor Safeguards. 1p. 17347:362. 24X Fiche: 50-413, 83/02/10, 8303010724.

8303020149 Forwards SER re operation of facility (NUREG-0954) & notice of issuance & availability. W/o SER.
NOVAK, T.M. Assistant Director for Licensing. 83/02/22. TUCKER, H.B. Duke Power Co. 2pp. 17359:141. 24X Fiche: 50-413, 83/02/22, 8303020149.

--8303020152 Notice of issuance & availability of SER (NUREG-0954).
ADENSAM, E.G. Licensing Branch 4. 83/02/22. 2pp. 17359:143. 24X
Fiche: 50-413, 83/02/22, 8303020149.

8303230269 Forwards response to 830222 request for addl info on SER confirmatory issues re SSI for bldgs not founded on rock & vertical seismic response spectra.
TUCKER, H.B. Duke Power Co. 83/03/15. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 199pp. 17662:034. 24X Fiche: 50-413, 83/03/15, 8303230269.

F. Security, medical, emergency & fire protection plans

8303090162 Forwards Rev 3 to security plan. Rev withheld (ref 10CFR73.21).
TUCKER, H.B. Duke Power Co. 83/02/24. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 2pp. 17469:358. 24X Fiche: 50-413, 83/02/24, 8303090162.

8303100162 Releases public version of revised emergency plan.
FELTON, J.M. Division of Rules and Records. 83/03/02. Document Management Branch. 1p. 17495:213. 24X Fiche: 50-413, 83/03/02, 8303100162.

--8303100168 Forwards public version of Rev 2 to emergency plan.
TUCKER, H.B. Duke Power Co. 83/02/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 2pp. 17495:214. 24X Fiche: 50-413, 83/03/02, 8303100162.

--8303100174 Public version of Rev 2 to emergency plan.
HAMPTON, J.W. Duke Power Co. 83/01/31. 158pp. 17495:216. 24X
Fiche: 50-413, 83/03/02, 8303100162.

8303290475 Requests exemption from 10CFR50 App E, Item IV.F.h & 10CFR50.47.b(14) re active participation of crisis mgt ctr personnel for each station during annual emergency preparedness exercise.
TUCKER, H.B. Duke Power Co. 83/03/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 17724:324. 24X
Fiche: 50-000, 83/03/09, 8303290475.

8303220321 Advises that interest in & time available for drills pilot program nonexistent. Limited drill pilot program could be conducted during simulator requalification training.
BOSTIAN, R.W. Duke Power Co. 83/03/10. EISENHUT, D.G. Division of Licensing. 1p. 17655:348. 24X Fiche: 50-000, 83/03/10, 8303220321.

8303210249 Requests technical assistance in reviewing addl info on planned relocation of central alarm switch. License condition re physical security plan, safeguards contingency plan & training & qualification plan submitted. W/o encl.
THOMAS, C.O. Standardization & Special Projects Branch. 83/03/15. MCCORKLE, G.W. Power Reactor Safeguards Licensing Branch. 1p. 17659:071. 24X Fiche: 50-413, 83/03/15, 8303210249.

8303240113 Releases public version of revised crisis mgt plan implementing procedures.
FELTON, J.M. Division of Rules and Records. 83/03/21. Document Management Branch. 1p. 17700:029. 24X Fiche: 50-000, 83/03/21, 8303240113.

--8303240120 Forwards public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.1 re recovery manager & immediate staff group plan & 5.3.4 re scheduling/planning support group.
TUCKER, H.B. Duke Power Co. 83/03/08 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp 17700:030 24X Fiche: 50-000, 83/03/21, 8303240113.

--8303240127 Public version of revised crisis mgt plan implementing procedures, including Procedures 5.3.1 re recovery manager & immediate staff group plan & 5.3.4 re scheduling/planning support group.
* Duke Power Co. 83/02/28 175pp. 24X Fiche: 50-000, 83/03/21, 8303240113.

Q. Adjudicatory correspondence.

8303010396 Memorandum & order ruling on spent fuel Contentions 10 & 19. Contention 10 & transshipment part of Contention 19 rejected as impermissible attacks on Commission rule.
KELLEY, J.L. Atomic Safety and Licensing Board Panel 83/02/25. Palmetto Alliance 9pp 17346:196 24X Fiche: 50-413, 83/02/25, 8303010396.

8303040534 Supplemental response to interrogatories & requests to produce re Palmetto Alliance Contentions 6, 7, 8, 27 & 44, in response to ASLB 830209 memorandum & order. Certificate of Svc encl. Related correspondence.
CARR, A.V. Duke Power Co. CARR, A.V. Debevoise & Liberman. 83/02/28 Palmetto Alliance 80pp 17366:052 24X Fiche: 50-413, 83/02/28, 8303040534.

8303080117 Memorandum & order memorializing 830302 conference call re DES Contentions 11 & 22, SER & emergency planning contentions; proposed protective order & Palmetto Alliance followup interrogatories &/or answers.
KELLEY, J.L. Atomic Safety and Licensing Board Panel 83/03/04 5pp 17458:271 24X Fiche: 50-413, 83/03/04, 8303080117.

8303110214 Forwards affidavit of nondisclosure to be signed in order to receive B&W proprietary document in response to Palmetto Alliance Interrogatory 2 on Contention 44. Related correspondence W/o encl.
CARR, A.V. Duke Power Co. 83/03/07 GUILD, R. Guild, R. 2pp 17519:295 24X Fiche: 50-413, 83/03/07, 8303110214.

8303100161 First set of interrogatories & document production requests on Contention DES-17. Certificate of Svc encl.
JOHNSON, G.E. Hearing Branch 4 83/03/08 Palmetto Alliance. 6pp 17485:224 24X Fiche: 50-413, 83/03/08, 8303100161.

8303140291 Memorandum & order commenting on discovery matters. ASLB tentative position is to uphold applicant work product privilege. Telephone conference call scheduled for 830317.
KELLEY, J.L. Atomic Safety and Licensing Board Panel 83/03/10 4pp 17535:052 24X Fiche: 50-413, 83/03/10, 8303140291.

8303150374 Response to interrogatories & requests to produce. Certificate of Svc encl.
JOHNSON, G.E. Hearing Branch 4 83/03/14 Palmetto Alliance. 83pp 17562:035 24X Fiche: 50-413, 83/03/14, 8303150374.

8303230192 Followup interrogatories & requests to produce re Palmetto Contentions 6, 7, 8, 16, 27 & 44. Certificate of Svc encl. Related correspondence.
GUILD, R. Palmetto Alliance GUILD, R. Guild, R. 83/03/16 Duke Power Co. 18pp 17665:222 24X Fiche: 50-413, 83/03/16, 8303230192.

8303240584 Response to 821215 second set of interrogatories & document production requests. Affidavit of Svc encl. Related correspondence.
RILEY, J.L. Carolina Environmental Study Group 83/03/17 Office of the Executive Legal Director 13pp 17683:122 24X Fiche: 50-413, 83/03/17, 8303240584.

8303230242 Forwards DJ Abernethy, CW Graves & JC Wolfmeyer interrogatory affidavits. JL Elliott job title should be changed to principal engineer, mechanical-nuclear div. Related correspondence.
CARR, A.V. Duke Power Co. 83/03/18 GUILD, R. Guild, R. 4pp 17661:147 24X Fiche: 50-413, 83/03/18, 8303230242.

8303250146 Provides rept on contacts made w/affected employees re discovery on Palmetto Alliance QA Contention 6. Ltrs sent to terminated, active & former plant QA employees & employees identified in intervenor documents. Related correspondence.
CARR, A.V. Duke Power Co. 83/03/22 KELLEY, J.L., CALLIHAN, A.D., FOSTER, R.F. Atomic Safety and Licensing Board Panel. 6pp 17691:005 24X Fiche: 50-413, 83/03/22, 8303250146.

8303290513 Memorandum & order making further rulings on environ contentions. Admits first sentences of Contention DES-11. Smoothing aspect of Contention DES-22 rejected upon reconsideration. Contention DES-17 unchanged.
KELLEY, J.L. Atomic Safety and Licensing Board Panel 83/03/24 5pp 17724:094 24X Fiche: 50-413, 83/03/24, 8303290513.

8303310345 Response to 830308 first set of interrogatories & document requests on Contention DES-17. Affirmation of Svc encl. Related correspondence.
GUILD, R. Palmetto Alliance. RILEY, J.L. Carolina Environmental Study Group. GUILD, R. Guild, R. 83/03/28 Office of the Executive Legal Director 6pp 17755:023 24X Fiche: 50-413, 83/03/28, 8303310345.

8303310353 Response in opposition to applicant request to limit contacts by Palmetto Alliance w/applicant employees. Protection sought not supported by good cause. Applicant may later seek discovery limitation. Certificate of Svc encl.
JOHNSON, G.E. Hearing Branch 4 83/03/30 Atomic Safety and Licensing Board Panel. 7pp 17755:029 24X Fiche: 50-413, 83/03/30, 8303310353.

K. Utility Final Safety Analysis Report (FSAR) & amends

8302240208 Amend 29 to OL applications, consisting of Rev 7 to FSAR.
TUCKER, H.B. Duke Power Co. 83/02/22 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E.G. Licensing Branch 4. 2pp 17269:001 24X Fiche: 50-413, 83/02/22, 8302240208.

--8302240210 Rev 7 to FSAR W/134 oversize P&IDs. Aperture cards are avail'able in PDR.
* Duke Power Co. 83/02/22 866pp. 17269:003 24X Fiche: 50-413, 83/02/22, 8302240208.

Q. Inspection reports, IE Bulletins & correspondence.

8303010301 Responds to NRC ltr re violations noted in IE Insp Repts 50-413/82-03 & 50-414/82-03. Addl insps & cleaning unnecessary.
TUCKER, H.B. Duke Power Co. 82/12/01 O'REILLY, J.P. Region 2, Office of Director. 1p 17333:335 24X Fiche: 50-413, 82/12/01, 8303010301.

8303210479 Responds to NRC ltr re violations noted in IE Insp Repts 50-413/82-21 & 50-414/82-19. Corrective actions: nonconforming item evaluation team formed to review repts & identify areas of concern. Compliance achieved $\checkmark$ of 830114.
TUCKER, H.B. Duke Power Co. 83/01/14 O'REILLY, J.P. Region 2, Office of Director. 3pp 17631:294 24X Fiche: 50-413, 83/01/14, 8303210479.

8303010200 Advises that addl info re IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp (Asiatic clam) & Mytilus (mussel)," will be available by 830318.
TUCKER, H.B. Duke Power Co. 83/02/07 O'REILLY, J.P. Region 2, Office of Director. 1p 17332:351 24X Fiche: 50-413, 83/02/07, 8303010200.

8303010231 Forwards IE Insp Repts 50-413/83-01 & 50-414/83-01 on 830111-14. No noncompliance noted.
DANCE, H.C. Division of Project & Resident Programs. 83/02/10. TUCKER, H.B. Duke Power Co. 2pp 17335:056 24X Fiche: 50-413, 83/02/10, 8303010231.

--8303010235 IE Insp Repts 50-413/83-01 & 50-414/83-01 on 830111-14. No noncompliance noted. Major areas inspected: electrical cable termination, observation of work & review of QC records & licensee identified items.
RUFF, A.B., CONLON, T.E. Division of Engineering & Radiological Safety Programs. 83/02/07 4pp 17335:058 24X Fiche: 50-413, 83/02/10, 8303010231.

8303210708 Forwards IE Insp Repts 50-413/82-33 & 50-414/82-31 on 821226-830125. No noncompliance noted.
DANCE, H.C. Division of Project & Resident Programs. 83/02/14. TUCKER, H.B. Duke Power Co. 2pp 17635:065 24X Fiche: 50-413, 83/02/14, 8303210708.

--8303210716 IE Insp Repts 50-413/82-33 & 50-414/82-31 on 821226-830125. No noncompliance noted. Major areas inspected: followup on licensee actions re QC welding insp concerns, QA surveillance repts & safety-related piping (welding).
VAN DOORN, P.K. Region 2, Office of Director. IGNATONIS, A.J. Division of Project & Resident Programs. 83/02/11 5pp 17635:067 24X Fiche: 50-413, 83/02/14, 8303210708.

8303210471 Ack receipt of IE Insp Repts 50-413/82-31 & 50-414/82-29. No proprietary info.
TUCKER, H. B. Duke Power Co. 83/02/22. O'REILLY, J. P. Region 2, Office of Director. 1p. 17634:158. 24X Fiche: 50-413, 83/02/22, 8303210471.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210334 Ack receipt of 830114 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/82-21 & 50-414/82-19.
LEWIS, R. C. Division of Project & Resident Programs. 83/03/10.
TUCKER, H. B. Duke Power Co. 1p. 17634:236. 24X
Fiche: 50-413, 83/03/10, 8303210334.

8303210337 Ack receipt of 821201 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/82-03 & 50-414/82-03.
DANCE, H. C. Division of Project & Resident Programs. 83/03/10.
TUCKER, H. B. Duke Power Co. 1p. 17634:163. 24X
Fiche: 50-413, 83/03/10, 8303210337.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

S. Reportable occurrences, LERs & related correspondence

8303010531 Followup to Significant Deficiency Rept SD 414/83-02 re linear indications in base metal of welds mfg by Custom Alloy, Inc. Results of full investigation will be provided by 830311.
TUCKER, H. B. Duke Power Co. 83/02/17. O'REILLY, J. B. Region 2, Office of Director. 1p. 17343:037. 24X Fiche: 50-414, 83/02/17, 8303010531.

8303140515 Significant deficiency rept re inappropriate governor drive matl coupling on diesel generator. Corrective action scheduled for completion 830301 will be delayed until 831001, due to delay in mfg of replacement couplings.
TUCKER, H. B. Duke Power Co. 83/03/01. O'REILLY, J. P. Region 2, Office of Director. 1p. 17540:345. 24X Fiche: 50-413, 83/03/01, 8303140515.

8303220103 Significant Deficiency Rept SD 414/83-02 re unacceptable base metal indications in two fittings. Initially reported on 830118. Detected indications removed. Condition discussed w/manufacturer.
TUCKER, H. B. Duke Power Co. 83/03/11. O'REILLY, J. P. Region 2, Office of Director. 3pp. 17650:064. 24X Fiche: 50-414, 83/03/11, 8303220103.

T. Hearing transcripts on non-antitrust matters

8303090078 Transcript of ACRS Subcommittee on Catawba Nuclear Power Station Units 1 & 2 830304 meeting in Charlotte, NC. Pp. 1-245. Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards. 83/03/04.
431pp. 17467:065. 24X Fiche: 50-413, 83/03/04, 8303090078.

8303090084 Transcript of ACRS Subcommittee on Catawba Nuclear Power Station Units 1 & 2 830305 meeting in Charlotte, NC. Pp. 246-459. Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards. 83/03/05.
297pp. 17468:136. 24X Fiche: 50-413, 83/03/05, 8303090084.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303080508 Submits info re deep draft pumps trending analysis, Humphrey containment concerns & masonry wall design & const per supplemental SER in response to NRC 830112 request.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/02/25. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 17452:281. 24X Fiche: 50-416, 83/02/25, 8303080508.

F. Security, medical, emergency & fire protection plans

8303010307 Advises that response to NRC comments on Rev 5 to physical security plan will be delayed until 830318.
DALE, L. F. Mississippi Power & Light Co. 83/02/25. SCHWENCER, A. Licensing Branch 2. 2pp. 17333:329. 24X Fiche: 50-416, 83/02/25, 8303010307.

8303210686 Forwards IE Insp Rept 50-416/83-03 on 830124-27. No noncompliance noted.
VERRELLI, D. M. Division of Project & Resident Programs. 83/02/28.
STAMPLEY, N. L. Mississippi Power & Light Co. 2pp. 17635:201. 24X
Fiche: 50-416, 83/02/28, 8303210686.

--8303210695 IE Insp Rept 50-416/83-03 on 830124-27. No noncompliance noted. Major areas inspected: emergency preparedness exercise.
CLINE, W. E. Region 2, Office of Director. JENKINS, G. [illegible]. Division of Emergency Preparedness & Materials Safety. 83/02/25. 9pp.
17635:203. 24X Fiche: 50-416, 83/02/28, 8303210686.

P. Operating license stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303030150 Forwards fee for review of applications for OL amends.
DALE, L. F. Mississippi Power & Light Co. 83/02/23. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17412:340.
24X Fiche: 50-416, 83/02/23, 8303030150.

8303030215 Requests that agreement be made w/DOE for disposal of high level radwaste & spent nuclear fuel. DOE 830211 ltr to Chairman Palladino encl for guidance.
SCHWENCER, A. Licensing Branch 2. 83/02/23. MCGAUGHY, J. P. Mississippi Power & Light Co. 2pp. 17364:352. 24X
Fiche: 50-416, 83/02/23, 8303030215.

--8303030218 Certifies negotiations w/listed utils for nuclear waste disposal contract. Utils requiring NRC actions on issuance or renewal of license not able to enter into negotiations.
HODEL, D. P. Energy, Dept. of. 83/02/11. PALLADINO, N. J. Commissioners. 2pp. 17364:354. 24X Fiche: 50-416, 83/02/[illegible], 8303030215.

8303030384 Advises that 830128 request for mod to FSAR Subsection 18.1.4 to reduce senior operator on shift training requirement from 3 to 6 months acceptable & within requirements of NUREG-0737.
SCHWENCER, A. Licensing Branch 2. 83/02/24. MCGAUGHY, J. P. Mississippi Power & Light Co. 2pp. 17419:324. 24X
Fiche: 50-416, 83/02/24, 8303030384.

8303310453 Partial response to FOIA request for six categories of documents. Forwards App A documents identified as Items 1, 3, 4, 5 & 6 of request. Search for documents re Item 2 of request continuing.
FELTON, J. M. Division of Rules and Records. 83/02/24. HIATT, S. L. Ohio Citizens for Responsible Energy. 2pp. 17804:132. 24X
Fiche: 50-000, 83/02/24, 8303310453.

--8303310465 "Assessment of Postulated Degraded Core Accidents in Grand Gulf Reactor Plant," draft informal rept
GASSER, R. D. Brookhaven National Laboratory 82/06/30 NRC - No Detailed Affiliation Given 247pp 17804:135 24X
Fiche: 50-000, 83/02/24, 8303310453

--8303310470 Forwards "Analysis of Full Core Meltdown Accidents in Grand Gulf Reactor Plant," draft informal rept Rept satisfies preliminary rept milestone for Task I defined in "Safety Evaluation of Core Melt Accidents CP, ML & OL Applicants."
PRATT, W. T. Brookhaven National Laboratory FIN A-3399 82/09/21
MEYER, J. F. Reactor Systems Branch 1p 17805:022 24X
Fiche: 50-000, 83/02/24, 8303310453

--8303310476 "Analysis of Full Core Meltdown Accidents in Grand Gulf Reactor Plant," draft informal rept
GASSER, R. D. Brookhaven National Laboratory FIN A-3399
82/08/31 NRC - No Detailed Affiliation Given 467pp
17805:023 24X Fiche: 50-000, 83/02/24, 8303310453

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12) Svc list encl
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005

8303290369 Forwards proprietary & nonproprietary versions of "CLASIX-3 Computer Program for Analysis of Reactor Plant Containment Response to Hydrogen Release & Deflagration." Proprietary version withheld (ref 10CFR2.790)
RICHARDSON, J. D. Hydrogen Control Owners Group, BWR-6 Mark III
RICHARDSON, J. D. Mississippi Power & Light Co. 83/03/18
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp
17726:079 24X Fiche: 50-000, 83/03/18, 8303290369

--8303290378 Requests that "CLASIX-3 Computer Program for Analysis of Reactor Plant Containment Response to Hydrogen Release & Deflagration" be withheld from public disclosure Affidavit encl
WIESEMANN, R. A. Westinghouse Electric Corp. 83/01/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 6pp 17726:081 24X Fiche: 50-000, 83/03/18, 8303290369

--8303290385 Nonproprietary "CLASIX-3 Computer Program for Analysis of Reactor Plant Containment Response to Hydrogen Release & Deflagration"
FULS, Q. M. Westinghouse Electric Corp. WCAP-10260 83/03/31
139pp 17726:087 24X Fiche: 50-416, 83/03/18, 8303290369

8303280025 Forwards response to five of six items contained in 821203 ltr re util work addressing containment issues Evaluation of condensation oscillation loads produced by discharges from RHR HX relief valve will be completed by late Apr
DALE, L. F. Mississippi Power & Light Co. 83/03/23 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 31pp 17707:159 24X Fiche: 50-416, 83/03/23, 8303280025

8303280310 Proposed Amend PCOL-83/03 to License NPF-13, consisting of changes to surveillance procedure review - Package 1, Items 1-32 & miscellaneous Tech Spec changes
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/03/24 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp 17705:323 24X Fiche: 50-416, 83/03/24, 8303280310

--8303280316 Proposed Tech Specs including changes to surveillance procedure review - Package 1, Items 1-32
* Mississippi Power & Light Co. 83/03/24 74pp 17705:326 24X
Fiche: 50-416, 83/03/24, 8303280310

Q. Inspection reports, IE Bulletins & correspondence

8303010547 Advises that rev to Plant Administrative Procedure 01-S-06-1 will be issued by 830310 Submittal responds to violation noted in IE Insp Rept 50-416/82-76
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/02/08
O'REILLY, J. P. Region 2, Office of Director 1p 17337:271 24X
Fiche: 50-416, 83/02/08, 8303010547

8303010494 Forwards IE Insp Rept 50-416/83-02 on 830103-07 No noncompliance noted
VERRELLI, D. M. Division of Project & Resident Programs 83/02/10
STAMPLEY, N. L. Mississippi Power & Light Co. 2pp 17343:324 24X
Fiche: 50-416, 83/02/10, 8303010494

--8303010501 IE Insp Rept 50-416/83-02 on 830103-07 No noncompliance noted Major areas inspected: solid & gaseous preoperational test program, radiation protection program, LERs, IE bulletins, info notice & previous insp items
COLLINS, T. R. Region 2, Office of Director BARR, K. P. Division of Project & Resident Programs 83/02/10 9pp 17343:326 24X
Fiche: 50-416, 83/02/10, 8303010494

8303010485 Ack receipt of 830121 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-416/82-67 Violation re valve position still applicable
O'REILLY, J. P. Region 2, Office of Director 83/02/16
STAMPLEY, N. L. Mississippi Power & Light Co. 1p 17336:036 24X
Fiche: 50-416, 83/02/16, 8303010485

--8303010524 Responds to NRC 821220 ltr re violations noted in IE Insp Rept 50-416/82-67 Corrective actions: procedures & FSAR re verification of trip setpoints revised & surveillance review program established
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/01/21
O'REILLY, J. P. Region 2, Office of Director 3pp 17336:037 24X
Fiche: 50-416, 83/02/16, 8303010485

--8303010548 Responds to NRC 821220 ltr re violations noted in IE Insp Rept 50-416/82-67 Rept does not indicate which date inspector observed valve in disassembled condition Violation disputed
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/01/21
O'REILLY, J. P. Region 2, Office of Director 2pp 17336:040 24X
Fiche: 50-416, 83/02/16, 8303010485

--8303010558 Forwards IE Insp Rept 50-416/82-67 & notice of violation
O'REILLY, J. P. Region 2, Office of Director 82/12/20
STAMPLEY, N. L. Mississippi Power & Light Co. 2pp 17336:042 24X
Fiche: 50-416, 83/02/16, 8303010485

--8303010574 Notice of violation from insp on 820927-1008
* Region 2, Office of Director 82/12/20 3pp 17336:044 24X
Fiche: 50-416, 83/02/16, 8303010485

--8303010590 IE Insp Rept 50-416/82-67 on 820927-1008 Noncompliance noted activities affecting quality not documented by appropriate acceptance criteria & channel checks not required in Mode 3
HUNT, M., WAGNER, A. G., BUTCHER, R. C. Region 2, Office of Director
82/11/22 17pp 17336:047 24X Fiche: 50-416, 83/02/16, 8303010485

8303010463 Ack receipt of 821119, 830112 & 0201 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-416/82-53 Noncompliance withdrawn
LEWIS, R. C. Division of Project & Resident Programs 83/02/17
STAMPLEY, N. L. Mississippi Power & Light Co. 1p 17343:281 24X
Fiche: 50-416, 83/02/17, 8303010463

--8303010473 Informs that discharge basin automated sample gathering sys failed to operate properly when energized Failed sys under investigation Operability expected prior to next reactor criticality
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/02/01
O'REILLY, J. P. Region 2, Office of Director 1p 17343:282 24X
Fiche: 50-416, 83/02/17, 8303010463

--8303010481 Submits corrected copy of response to NRC ltr re violations noted in IE Insp Rept 50-416/82-53 Corrective actions: automated sample gathering sys installed & expected to be tested & operational by 830201
MCGAUGHY, J. Mississippi Power & Light Co. 83/01/12
O'REILLY, J. P. Region 2, Office of Director 2pp 17343:283 24X
Fiche: 50-416, 83/02/17, 8303010463

--8303010491 Responds to NRC 821020 ltr re violations noted in IE Insp Rept 50-416/82-53 Corrective actions: util believes no violation existed & 8 h sample collection frequency justified & conservative
MCGAUGHY, J. P. Mississippi Power & Light Co. 82/11/19
O'REILLY, J. P. Region 2, Office of Director 2pp 17343:287 24X
Fiche: 50-416, 83/02/17, 8303010463

--8303010497 Forwards IE Insp Repts 50-416/82-53 on 820921-24 & notice of violation
VERRELLI, D. M. Division of Project & Resident Programs 82/10/20
STAMPLEY, N. L. Mississippi Power & Light Co. 2pp 17343:289 24X
Fiche: 50-416, 83/02/17, 8303010463

--8303010500 Notice of violation from insp on 820921-24
* Division of Project & Resident Programs 82/10/20 1p
17343:291 24X Fiche: 50-416, 83/02/17, 8303010463

# DOCKETED ITEMS

--8303010508 IE Insp Repts 50-416/82-53 on 820921-24 Noncompliance noted hourly samples not taken to meet requirements of monthly average composite sample of discharge basin
COLLINS, T R Region 2, Office of Director BARR, K P Division of Engineering & Radiological Safety Programs 82/10/13 5pp
17343 292 24X Fiche 50-416, 83/02/17, 8303010463

8303210389 Forwards IE Insp Rept 50-416/83-05 on 830131-0204 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/02/17
STAMPLEY, N L Mississippi Power & Light Co 2pp 17634 165 24X
Fiche 50-416, 83/02/17, 8303210389

--8303210391 IE Insp Rept 50-416/83-05 on 830131-0204 No noncompliance noted Major areas inspected startup test procedures
BURNETT, P T Region 2, Office of Director JAPE, F Division of Engineering & Radiological Safety Programs 83/02/16 4pp
17634 167 24X Fiche 50-416, 83/02/17, 8303210389

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc
111pp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367

8303210686 Forwards IE Insp Rept 50-416/83-03 on 830124-27 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/02/28
STAMPLEY, N L Mississippi Power & Light Co 2pp 17635 201 24X
Fiche 50-416, 83/02/28, 8303210686

--8303210695 IE Insp Rept 50-416/83-03 on 830124-27 No noncompliance noted Major areas inspected emergency preparedness exercise
CLINE, W E Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/02/25 9pp
17635 203 24X Fiche 50-416, 83/02/28, 8303210686

8303210328 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetrations " Bunker-Ramo electrical penetrations not used at facility Three manhours expended in bulletin response
DALE, L F Mississippi Power & Light Co 83/03/03 O'REILLY, J P
Region 2, Office of Director 2pp 17632 121 24X
Fiche 50-416, 83/03/03, 8303210328

8303210564 Ack receipt of 830218 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-416/83-03 & 50-417/83-01
VERRELLI, D M Division of Project & Resident Programs 83/03/03
STAMPLEY, N L Mississippi Power & Light Co 1p 17636 343 24X
Fiche 50-416, 83/03/03, 8303210564

--8303210579 Responds to NRC 830119 ltr re violations noted in IE Insp Rept 50-417/83-01 Corrective actions concrete wall pour 02T22-W-2218JWIA completed on 830104 QC verified that curing process initiated at proper time
MCGAUGHY, J P Mississippi Power & Light Co 83/02/18
O'REILLY, J P Region 2, Office of Director 3pp 17636 344 24X
Fiche 50-416, 83/03/03, 8303210564

--8303210587 Forwards IE Insp Repts 50-416/83-03 & 50-417/83-01 on 830104-07 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/01/19
STAMPLEY, N L Mississippi Power & Light Co 2pp 17636 347 24X
Fiche 50-416, 83/03/03, 8303210564

--8303210592 Notice of violation from insp on 830104-07
* Region 2, Office of Director 83/01/19 1p 17637 349 24X
Fiche 50-416, 83/03/03, 8303210564

--8303210597 IE Insp Repts 50-416/83-03 & 50-417/83-01 on 830104-07 Noncompliance noted failure to properly cure concrete in auxiliary bldg const
HARRIS, J R Region 2, Office of Director CONLON, T E Division of Engineering & Radiological Safety Programs 83/01/17 4pp
17636 350 24X Fiche 50-416, 83/03/03, 8303210564

8303210620 Ack receipt of 830121 & 0224 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-416/82-67
O'REILLY, J P Region 2, Office of Director 83/03/09 RICHARD, J B
Mississippi Power & Light Co 1p 17636 279 24X
Fiche 50-416, 83/03/09, 8303210620

--8303210649 Suppls response to NRC 821220 ltr re violations noted in IE Insp Rept 50-416/82-67 Corrective actions all possible avenues of investigation re unlocked valve P42-F200B pursued No further action planned
MCGAUGHY, J P Mississippi Power & Light Co 83/02/24
O'REILLY, J P Region 2, Office of Director 3pp 17636 280 24X
Fiche 50-416, 83/03/09, 8303210620

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers " Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc
117pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380

8303210691 Ack receipt of 821029 & 830304 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-416/82-65
LEWIS, R C Division of Project & Resident Programs 83/03/11
RICHARD, J B Mississippi Power & Light Co 1p 17635 154 24X
Fiche 50-416, 83/03/11, 8303210691

--8303210703 Suppls 821029 response to violations noted in IE Insp Rept 50-416/82-65 Corrective actions Administrative Procedure 01-S-07-1, "Control of Work on Plant Equipment & Facilities" implemented
MCGAUGHY, J P Mississippi Power & Light Co 83/03/04
O'REILLY, J P Region 2, Office of Director 2pp 17635 155 24X
Fiche 50-416, 83/03/11, 8303210691

--8303210718 Responds to NRC 820929 ltr re violations noted in IE Insp Rept 50-416/82-65 Corrective actions permanent plant equipment recalibr
MCGAUGHY, J P Mississippi Power & Light Co 82/10/29
O'REILLY, J P Region 2, Office of Director 2pp 17635 157 24X
Fiche 50-416, 83/03/11, 8303210691

--8303210725 Responds to NRC 820929 ltr re violations noted in IE Insp Rept 50-416/82-65 Corrective actions all support-type maint work orders on sys turned over to plant staff for operation closed
MCGAUGHY, J P Mississippi Power & Light Co 82/10/29
O'REILLY, J P Region 2, Office of Director 2pp 17635 159 24X
Fiche 50-416, 83/03/11, 8303210691

--8303210736 Responds to NRC 820929 ltr re violations noted in IE Insp Rept 50-416/82-65 Corrective actions procedures on reactor water cleanup & fuel pool cooling & cleanup sys placed at selected locations for easy access
MCGAUGHY, J P Mississippi Power & Light Co 82/10/29
O'REILLY, J P Region 2, Office of Director 2pp 17635 161 24X
Fiche 50-416, 83/03/11, 8303210691

--8303210742 Forwards IE Insp Rept 50-416/82-65 on 820816-0917 & notice of violation
LEWIS, R C Division of Project & Resident Programs 82/09/29
STAMPLEY, N L Mississippi Power & Light Co 2pp 17635 163 24X
Fiche 50-416, 83/03/11, 8303210691

--8303210747 Notice of violation from insp on 820816-0917
* Region 2, Office of Director 82/09/29 2pp 17635 165 24X
Fiche 50-416, 83/03/11, 8303210691

--8303210752 IE Insp Rept 50-416/82-65 on 820816-0917 Noncompliance noted failure to follow equipment qualification procedures & sys operating instructions
WAGNER, A G , SCOTT, D E Region 2, Office of Director
CANTRELL, F S Division of Project & Resident Programs 82/09/29
8pp 17635 167 24X Fiche 50-416, 83/03/11, 8303210691

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 121pp 17774 352 24X Fiche 50-000, 83/03/21, 8212060387

R Periodic operating reports & related correspondence

8303230020 Forwards monthly operating rept for Feb 1983
MCGAUGHY, J P Mississippi Power & Light Co 83/03/15 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 1p
17663 248 24X Fiche 50-416, 83/03/15, 8303230020

--8303230022 Monthly operating rept for Feb 1983
RICHARDSON, J D Mississippi Power & Light Co 83/03/14 4pp
17663 249 24X Fiche 50-416, 83/03/15, 8303230020

8303290753 Forwards addl guidance for use in reporting offsite doses to public for 1982
SCHWENCER, A Licensing Branch 2 83/03/24 MCGAUGHY, J P
Mississippi Power & Light Co 4pp 17746 357 24X
Fiche 50-416, 83/03/24, 8303290753

6. Reportable occurrences, LERs & related correspondence

8303010193 Forwards LER 83-033/99X-0.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/02/23.
O'REILLY, J P. Region 2, Office of Director. 1p. 17332 354. 24X
Fiche 50-416, 83/02/23, 8303010193.

--8303010201 LER 83-033/99X-0 on 830118, supervision sys for fire rated doors in auxiliary bldg & control bldg alarmed w/doors closed. Caused by misadjustment of limit & magnetic switches. Switches adjusted.
BYRD, R., SHINGLETON, B. Mississippi Power & Light Co. 83/02/23.
Region 2, Office of Director. 1p. 17332 355. 24X
Fiche 50-416, 83/02/23, 8303010193.

8303010178 Forwards LER 83-038/03L-0.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/02/24.
O'REILLY, J P. Region 2, Office of Director. 1p. 17333 351. 24X
Fiche 50-416, 83/02/24, 8303010178.

--8303010185 LER 83-038/03L-0 on 830125, tachometer went downscale while speed increased. Caused by failure of solid state chip in tachometer relay due to short produced by voltage surge from hookup of maint & test equipment. Tachometer replaced.
ROHRER, M V., SHINGLETON, B. Mississippi Power & Light Co.
83/02/24. Region 2, Office of Director. 1p. 17333 352. 24X
Fiche 50-416, 83/02/24, 8303010178.

8303010212 Forwards LER 83-026/03L-0.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/02/24.
O'REILLY, J P. Region 2, Office of Director. 1p. 17332 011. 24X
Fiche 50-416, 83/02/24, 8303010212.

--8303010218 LER 83-026/03L-0 on 830128, fire doors 0C220 & 1A211 alarmed on supervision sys & would not reset. Cause not determined. Fire detectors verified operable & hourly fire watch established.
ROHRER, M V., SHINGLETON, B. Mississippi Power & Light Co.
83/02/24. Region 2, Office of Director. 1p. 17332 012. 24X
Fiche 50-416, 83/02/24, 8303010212.

8303010226 Forwards LER 83-029/03L-0.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/02/24.
O'REILLY, J P. Region 2, Office of Director. 1p. 17335 067. 24X
Fiche 50-416, 83/02/24, 8303010226.

--8303010233 LER 83-029/03L-0 on 830128, fire doors 1A401, 1A202 & 1A108 in auxiliary bldg blocked open to allow routing of electrical cords & air hoses. Caused by need to perform planned maint. Hourly fire watch established.
ROHRER, M V., SHINGLETON, B. Mississippi Power & Light Co.
83/02/24. Region 2, Office of Director. 1p. 17335 068. 24X
Fiche 50-416, 83/02/24, 8303010226.

8303010343 Forwards LER 83-027/99X-0.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/02/24.
O'REILLY, J P. Region 2, Office of Director. 1p. 17346 175. 24X
Fiche 50-416, 83/02/24, 8303010343.

--8303010349 LER 83-027/99X-0 on 830128, fire door 1A215 alarmed on supervision sys & would not reset, yet verified closed. Caused by door position switch out of adjustment. Fire watch established. Switch adjusted. Door returned to svc on 830201.
ROHRER, M V., SHINGLETON, B. Mississippi Power & Light Co.
83/02/24. Region 2, Office of Director. 1p. 17346 176. 24X
Fiche 50-416, 83/02/24, 8303010343.

8303140498 Interim deficiency rept re incorrect wipe setting of normally closed contacts converted from open contacts on some HFA relays. Initially reported on 820802. Also reportable per Part 21 for Unit 1.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/02/24.
O'REILLY, J P. Region 2, Office of Director. 5pp. 17540 314. 24X
Fiche 50-416, 83/02/24, 8303140498.

8303040319 Forwards LER 83-039/99X-0.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/02/25.
O'REILLY, J P. Region 2, Office of Director. 1p. 17422 002. 24X
Fiche 50-416, 83/02/25, 8303040319.

--8303040325 LER 83-039/99X-0 on 830112, during cold shutdown, halon panel 1H13P911 detector A alarmed & would not reset. Hourly fire watch established. Corrective maint underway.
FLOYD, J M., SHINGLETON, E B. Mississippi Power & Light Co.
83/02/25. Region 2, Office of Director. 1p. 17422 003. 24X
Fiche 50-416, 83/02/25, 8303040319.

8303040358 Forwards LER 83-040/03L-0.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/02/25.
O'REILLY, J P. Region 2, Office of Director. 1p. 17420 044. 24X
Fiche 50-416, 83/02/25, 8303040358.

--8303040363 LER 83-040/03L-0 on 830127, smoke detector in zone covering elevation 139 ft in auxiliary bldg covered to perform welding in area & prevent actuation of alarm. Caused by planned maint activities. Smoke detector uncovered.
ROHRER, M V. Mississippi Power & Light Co. 83/02/25. Region 2, Office of Director. 1p. 17420 045. 24X Fiche 50-416, 83/02/25, 8303040358.

8303040420 Forwards LER 83-034/03L-0.
MCGAUGHY, J. Mississippi Power & Light Co. 83/02/25. O'REILLY, J P. Region 2, Office of Director. 1p. 17374 297. 24X
Fiche 50-416, 83/02/25, 8303040420.

--8303040425 LER 83-034/03L-0 on 830129, fire door 1A106 alarmed on supervision sys & would not reset. Caused by failure of lock/latch mechanisms. Lock/latch mechanisms replaced & doors returned to svc.
ROHRER, M V., SHINGLETON, B. Mississippi Power & Light Co.
83/02/25. Region 2, Office of Director. 1p. 17374 298. 24X
Fiche 50-416, 83/02/25, 8303040420.

8303040498 Forwards LER 83-032/03L-0.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/02/28.
O'REILLY, J P. Region 2, Office of Director. 1p. 17373 307. 24X
Fiche 50-416, 83/02/28, 8303040498.

--8303040504 LER 83-032/03L-0 on 830208, several smoke detectors in Zones 1-6, 1-18, 2-6 & 2-18 covered to prevent actuation while approved welding was being conducted. All detectors restored within 14 day limit of action statement.
FLOYD, J M., SHINGLETON, B. Arkansas Power & Light Co. 83/02/28.
Region 2, Office of Director. 2pp. 17373 308. 24X
Fiche 50-416, 83/02/28, 8303040498.

8303040506 Forwards LER 83-044/99X-0.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/01.
O'REILLY, J P. Region 2, Office of Director. 1p. 17368 013. 24X
Fiche 50-416, 83/03/01, 8303040506.

--8303040508 LER 83-044/99X-0 on 830124, equipment hatch on auxiliary bldg 139 ft elevation west corridor removed. Caused by need to transport matls to 119 ft elevation for installation of drywell chiller sys.
BYRD, R., SHINGLETON, B. Mississippi Power & Light Co. 83/03/01.
Region 2, Office of Director. 1p. 17368 014. 24X
Fiche 50-416, 83/03/01, 8303040506.

8303040541 Forwards LER 83-041/03L-0.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/01.
O'REILLY, J P. Region 2, Office of Director. 1p. 17366 002. 24X
Fiche 50-416, 83/03/01, 8303040541.

--8303040549 LER 83-041/03L-0 on 830131, maint personnel began opening eight penetrations in control bldg to allow conduit routing. Caused by planned maint. Hourly fire watch conducted on each penetration. Updated rept will be submitted on 830501.
ROHRER, M., SHINGLETON, B. Mississippi Power & Light Co. 83/03/01.
Region 2, Office of Director. 1p. 17366 003. 24X
Fiche 50-416, 83/03/01, 8303040541.

8303040620 Forwards LER 83-042/99X-0.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/01.
O'REILLY, J P. Region 2, Office of Director. 1p. 17374 267. 24X
Fiche 50-416, 83/03/01, 8303040620.

--8303040626 LER 83-042/99X-0 on 830124, fire door 1A104 blocked open for passage of welding leads. Caused by planned maint activities. Hourly fire watch established per Tech Spec. Door operability restored within 11 days.
BYRD, R., SHINGLETON, B. Mississippi Power & Light Co. 83/03/01.
Region 2, Office of Director. 1p. 17374 268. 24X
Fiche 50-416, 83/03/01, 8303040620.

8303150242 Forwards updated LER 82-141/99X-1.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/01.
O'REILLY, J P. Region 2, Office of Director. 1p. 17556 028. 24X
Fiche 50-416, 83/03/01, 8303150242.

--8303150254 Updated LER 82-141/99X-1 on 821112, limiting condition for operation entered to perform planned maint activity. Fire doors 1A308 & 1A316 opened to route hoses in support of sandblasting operations in suppression pool.
FREEMAN, M S., SHINGLETON, B. Mississippi Power & Light Co.
83/03/01. Region 2, Office of Director. 1p. 17556 029. 24X
Fiche 50-416, 83/03/01, 8303150242.

8303150443 Forwards updated LER 82-095/99X-1.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/01.
O'REILLY, J P. Region 2, Office of Director. 1p. 17561 059. 24X
Fiche 50-416, 83/03/01, 8303150443.

# DOCKETED ITEMS

--8303150448 Updated LER 82-095/99X-1 on 821106 during painting in suppression pool, three fire rated doors in auxiliary bldg blocked open. Caused by routing of sand blasting hoses from auxiliary bldg to pool. Doors closed on 830110.
FREEMAN, M. S. ; SHINGLETON, B. Mississippi Power & Light Co. 83/03/01 Region 2, Office of Director Ltr 17561 060 24X
Fiche: 50-416, 83/03/01, 8303150443.

8303210537 Forwards LER 83-043/03L-0.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/03/01
O'REILLY, J. P. Region 2, Office of Director Ltr 17632 223 24X
Fiche: 50-416, 83/03/01, 8303210537.

--8303210545 LER 83-043/03L-0 on 830131 smoke detectors for upper cable spreading room in control bldg (Zone 1-23) alarmed & would not reset. Possibly caused by dust in detector. Detector cleaned & return to svc.
ROHRER, M. V. ; SHINGLETON, B. Mississippi Power & Light Co. 83/03/01 Region 2, Office of Director Ltr 17632 224 24X
Fiche: 50-416, 83/03/01, 8303210537.

8303140388 Forwards updated LER 82-032/99X-1.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/03/02
O'REILLY, J. P. Region 2, Office of Director Ltr 17542 058 24X
Fiche: 50-416, 83/03/02, 8303140388.

--8303140389 Updated LER 82-032/99X-1 on 820723, no seal found on electrical penetration between hot machine shop & div 2 ESF switchgear room. Caused by penetration not sealed during const. Penetration sealed.
FREEMAN, M. S. ; SHINGLETON, B. Mississippi Power & Light Co. 83/03/03 Region 2, Office of Director Ltr 17542 059 24X
Fiche: 50-416, 83/03/02, 8303140388.

8303140403 Forwards updated LER 82-120/99X-1.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/03/02
O'REILLY, J. P. Region 2, Office of Director Ltr 17542 133 24X
Fiche: 50-416, 83/03/02, 8303140403.

--8303140404 Updated LER 82-120/99X-1 on 821105 during shutdown, fire door 1A106 in auxiliary bldg north stairwell, elevation 93 ft, opened for passage of hose to drain station svc water loop B. Fire guard posted. Door secured on 821229.
BYRD, R. W. ; SHINGLETON, E. B. Mississippi Power & Light Co. 83/03/02 Region 2, Office of Director Ltr 17542 134 24X
Fiche: 50-416, 83/03/02, 8303140403.

8303150146 Forwards updated LER 82-150/99X-1.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/03/02
O'REILLY, J. P. Region 2, Office of Director 2pp 17555 205 24X
Fiche: 50-416, 83/03/02, 8303150146.

--8303150183 Updated LER 82-150/99X-1 on 821122, limiting condition of operation entered when five fire-rated floor penetrations in auxiliary bldg opened to complete heat tracing portion of drywell monitoring sys.
BYRD, R. ; SHINGLETON, B. Mississippi Power & Light Co. 83/03/02 Region 2, Office of Director Ltr 17555 207 24X
Fiche: 50-416, 83/03/02, 8303150146.

8303150576 Forwards updated LER 82-166/99X-1.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/03/02
O'REILLY, J. P. Region 2, Office of Director Ltr 17568 345 24X
Fiche: 50-416, 83/03/02, 8303150576.

--8303150586 Updated LER 82-166/99X-1 on 821202, fire barriers broken in control bldg computer room & upper cable spreading room to route cables under maint work authorization. Caused by planned maint activity. Penetration closed & sealed.
ROHRER, M. V. ; SHINGLETON, B. Mississippi Power & Light Co. 83/03/02 Region 2, Office of Director Ltr 17568 346 24X
Fiche: 50-416, 83/03/02, 8303150576.

8303140557 Forwards LER 83-045/99X-0.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/03/03
O'REILLY, J. P. Region 2, Office of Director Ltr 17541 045 24X
Fiche: 50-416, 83/03/03, 8303140557.

--8303140565 LER 83-045/99X-0 on 830201, fire door 1A307 to RHR HX room B blocked open to allow routing of hose for planned maint activity. Fire door returned to normally closed position & alarm circuits activated on 830223.
ROHRER, M. V. ; SHINGLETON, B. Mississippi Power & Light Co. 83/03/03 Region 2, Office of Director Ltr 17541 046 24X
Fiche: 50-416, 83/03/03, 8303140557.

8303160397 Forwards LER 83-050/03L-0.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/03/04
O'REILLY, J. P. Region 2, Office of Director Ltr 17592 359 24X
Fiche: 50-416, 83/03/04, 8303160397.

--8303160403 LER 83-050/03L-0 on 830204, fire rated doors 1A401 & 1A302 alarmed & would not reset. Caused by loose supervision switches. Switches adjusted & tightened. Doors returned to svc on 830209.
BYRD, R. Mississippi Power & Light Co. 83/03/04 Region 2, Office of Director Ltr 17592 360 24X Fiche: 50-416, 83/03/04, 8303160397.

0303160300 Forwards LER 83-054/03L-0.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/03/07
O'REILLY, J. P. Region 2, Office of Director Ltr 17594 360 24X
Fiche: 50-416, 83/03/07, 8303160300.

--8303160310 LER 83-054/03L-0 on 830203, failure to perform weekly prelube of HPCS diesel determined reportable. Caused by lack of established procedure. Procedure 04-S-03-PB1-1, HPCS diesel generator prelube, issued 821129.
BYRD, R. Mississippi Power & Light Co. 83/03/07 Region 2, Office of Director Ltr 17594 361 24X Fiche: 50-416, 83/03/07, 8303160300.

8303160452 Forwards updated LER 82-126/99X-1.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/03/07
O'REILLY, J. P. Region 2, Office of Director Ltr 17592 306 24X
Fiche: 50-416, 83/03/07, 8303160452.

--8303160455 Updated LER 82-126/99X-1 on 821026, while repairing cables in control room, several fire dams broken. Caused by removal of barriers to replace damaged cable. Hourly fire watch established. Cables replaced & fire dams restored.
ROHRER, M. V. ; SHINGLETON, B. Mississippi Power & Light Co. 83/03/07 Region 2, Office of Director Ltr 17592 307 24X
Fiche: 50-416, 83/03/07, 8303160452.

8303160457 Forwards updated LER 82-020/03X-1.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/03/07
O'REILLY, J. P. Region 2, Office of Director Ltr 17592 274 24X
Fiche: 50-416, 83/03/07, 8303160457.

--8303160460 Updated LER 82-020/03X-1 on 820718, HPCS diesel generator 13 shut down prior to completion of functional test due to receipt of generator RTD high temp alarm. Caused by spurious signals while generator was parallel to bus.
FREEMAN, S. ; SHINGLETON, B. Mississippi Power & Light Co. 83/03/07 Region 2, Office of Director 3pp 17592 275 24X
Fiche: 50-416, 83/03/07, 8303160457.

8303160540 Forwards updated LER 82-122/99X-1.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/03/07
O'REILLY, J. P. Region 2, Office of Director Ltr 17587 252 24X
Fiche: 50-416, 83/03/07, 8303160540.

--8303160549 Updated LER 82-122/99X-1 on 821104, control room bldg lower cable spreading room HVAC chase cover found removed. Caused by need for maint work. Control room notification assured prior to fire barrier opening.
FREEMAN, M. S. ; SHINGLETON, B. Mississippi Power & Light Co. 83/03/07 Region 2, Office of Director Ltr 17587 253 24X
Fiche: 50-416, 83/03/07, 8303160540.

8303180248 Forwards updated LER 82-043/03X-1.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/03/07
O'REILLY, J. P. Region 2, Office of Director 2pp 17621 094 24X
Fiche: 50-416, 83/03/07, 8303180248.

--8303180254 Updated LER 82-043/03X-1 on 820722, monthly composite sample for discharge basin composited from samples taken at 8 h intervals rather than 1 h. Caused by unavailable equipment for collecting aliquots at short time intervals.
BYRD, R. ; SHINGLETON, B. Mississippi Power & Light Co. 83/03/04 Region 2, Office of Director 2pp 17621 096 24X
Fiche: 50-416, 83/03/07, 8303180248.

8303180359 Forwards updated LER 82-080/01X-1.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/03/07
O'REILLY, J. P. Region 2, Office of Director 2pp 17620 081 24X
Fiche: 50-416, 83/03/07, 8303180359.

--8303180369 Updated LER 82-080/01X-1 on 821004, during special insp on Div 2 standby diesel generator, one capscrew which secures rear crankcase cover to engine block discovered defective. Caused by fatigue. Capscrew replaced.
FREEMAN, S. ; SHINGLETON, B. Mississippi Power & Light Co. 83/03/07 Region 2, Office of Director 2pp 17620 082 24X
Fiche: 50-416, 83/03/07, 8303180359.

8303160551 Forwards updated LER 82-178/99X-1.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/03/08
O'REILLY, J. P. Region 2, Office of Director Ltr 17587 262 24X
Fiche: 50-416, 83/03/08, 8303160551.

--8303160574 Updated LER 82-178/99X-1 on 821218, several fire barriers in control room floor opened to reroute cable through floor. Limiting conditions for operation initiated & hourly fire watch established. Barriers resealed 830121.
FREEMAN, M S. Mississippi Power & Light Co. 83/03/08. Region 2, Office of Director. 1p. 17587:263. 24X Fiche: 50-416, 83/03/08, 8303160551.

8303160436 Forwards LER 83-053/99X-0.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/10.
O'REILLY, J P. Region 2, Office of Director. 1p. 17592:335. 24X
Fiche: 50-416, 83/03/10, 8303160436.

--8303160440 LER 83-053/99X-0 on 830201, electrical penetrations AE138C & CE-7E opened to perform planned maint activity. Caused by need to route conduit through penetrations as part of planned maint. Work in progress. Next rept by 830525.
ROHRER, M V; SHINGLETON, B. Mississippi Power & Light Co. 83/03/10. Region 2, Office of Director. 1p. 17592:336. 24X
Fiche: 50-416, 83/03/10, 8303160436.

8303180027 Forwards LER 83-047/03L-0.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/11.
O'REILLY, J P. Region 2, Office of Director. 1p. 17617:359. 24X
Fiche: 50-416, 83/03/11, 8303180027.

--8303180033 LER 83-047/03L-0 on 830210, control room air conditioning sys B train declared inoperable due to freon leak. Caused by blown gasket between valve bonnet & body flange. Gasket replaced.
ROHRER, M V; SHINGLETON, B. Mississippi Power & Light Co. 83/03/11. Region 2, Office of Director. 1p. 17617:360. 24X
Fiche: 50-416, 83/03/11, 8303180027.

8303180281 Forwards LER 83-055/03L-0.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/11.
O'REILLY, J P. Region 2, Office of Director. 1p. 17621:092. 24X
Fiche: 50-416, 83/03/11, 8303180281.

--8303180292 LER 83-055/03L-0 on 830209, auxiliary bldg isolation valve G1P45-F159 in floor & equipment drain sys indicated both open & closed. Caused by loose collar set screw on valve stem allowing collar to turn & miss arm switches.
FLOYD, J M. Mississippi Power & Light Co. 83/03/11. Region 2, Office of Director. 1p. 17621:093. 24X Fiche: 50-416, 83/03/11, 8303180281.

8303220266 Forwards LER 83-057/03L-0.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/14.
O'REILLY, J P. Region 2, Office of Director. 1p. 17656:223. 24X
Fiche: 50-416, 83/03/14, 8303220266.

--8303220275 LER 83-057/03L-0 on 830211, Div 1 battery 1A3 failed to satisfactorily pass all cell check surveillance procedure. Caused by low battery temp due to room heater control circuit being in off position. Pilot switches placed on.
ROHRER, M V; SHINGLETON, E B. Mississippi Power & Light Co. 83/03/14. Region 2, Office of Director. 2pp. 17656:225. 24X
Fiche: 50-416, 83/03/14, 8303220266.

8303220348 Forwards updated LER 82-176/99X-1.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/14.
O'REILLY, J P. Region 2, Office of Director. 1p. 17656:024. 24X
Fiche: 50-416, 83/03/14, 8303220348.

--8303220352 Updated LER 82-176/99X-1 on 821215 & 17, fire barriers broken to route cables for mods to transient test sys. Barriers left open to allow passage of cables. Fire watch posted during event. Work completed on 830124.
ROHRER, M V. Mississippi Power & Light Co. 83/03/14. Region 2, Office of Director. 1p. 17656:025. 24X Fiche: 50-416, 83/03/14, 8303220348.

8303240420 Forwards updated LER 82-018/01X-1.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/14.
O'REILLY, J P. Region 2, Office of Director. 2pp. 17678:284. 24X
Fiche: 50-416, 83/03/14, 8303240420.

--8303240423 Updated LER 82-018/01X-1 on 820728, during special insp, discrepancy between Vol 15, App 9 of FSAR & field conditions identified. Evaluation determined that fire detection not needed in turbine bldg.
FREEMAN, M S. Mississippi Power & Light Co. 83/03/14. Region 2, Office of Director. 2pp. 17678:286. 24X Fiche: 50-416, 83/03/14, 8303240420.

8303240432 Forwards updated LER 82-172/99X-1. Work order initiated to reseal penetration assembly.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/15.
O'REILLY, J P. Region 2, Office of Director. 1p. 17679:034. 24X
Fiche: 50-416, 83/03/15, 8303240432.

--8303240434 Updated LER 82-172/99X-1 on 821210, penetration AE154C in auxiliary bldg opened to perform planned maint. Penetration opened to pull cable through. Limiting condition for operation initiated & hourly fire watch established.
ROHRER, M V; SHINGLETON, B. Mississippi Power & Light Co. 83/03/15. Region 2, Office of Director. 1p. 17679:035. 24X
Fiche: 50-416, 83/03/15, 8303240432.

8303240560 Interim Deficiency Rept 2 re Nelson stud failures on embed plates. Initially reported on 821221. Failed plate sent to TRW to determine cause. New plates installed. Final rept by 830607. Also reported per Part 21.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/15.
O'REILLY, J P. Region 2, Office of Director. 5pp. 17683:197. 24X
Fiche: 50-416, 83/03/15, 8303240560.

8303240590 Interim deficiency rept re installation of noncorrosion resistant matl for instrument air pipe penetrations. Initially reported on 830315. Design change will be implemented. Also reported per Part 21.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/15.
O'REILLY, J P. Region 2, Office of Director. 5pp. 17683:085. 24X
Fiche: 50-416, 83/03/15, 8303240590.

8303240393 RO 83-002/0 on 830201, smoke detectors on Elevation 119 ft of auxiliary bldg covered to perform planned maint. Hourly fire watch established. Updated rept will be submitted by 830515.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/16.
O'REILLY, J P. Region 2, Office of Director. 2pp. 17678:359. 24X
Fiche: 50-416, 83/03/16, 8303240393.

8303240507 RO 83-001/0 on 830202, smoke detectors on LPCS pump room covered to perform planned maint activity. Hourly fire watch established. Work continuing. Updated rept will be submitted by 830515.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/16.
O'REILLY, J P. Region 2, Office of Director. 1p. 17678:108. 24X
Fiche: 50-416, 83/03/16, 8303240507.

8303240488 RO 83-003/01 on 830208, during cold shutdown, fire door DC414 alarmed & would not reset after door closed. Hourly fire watch established. Caused by latch bolt malfunction. Latch mechanism reworked.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/17.
O'REILLY, J P. Region 2, Office of Director. 2pp. 17678:016. 24X
Fiche: 50-416, 83/03/17, 8303240488.

8303240520 RO 83-006/0 on 830210, fire penetrations AE-382C & AE-384C opened. Caused by planned maint work order. Hourly fire watch established. Work not completed. Updated rept will be submitted by 830514.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/18.
O'REILLY, J P. Region 2, Office of Director. 1p. 17682:270. 24X
Fiche: 50-416, 83/03/18, 8303240520.

8303240531 RO 83-005/0 on 830209, w/reactor mode switch in refuel position, fire doors blocked open during welding activities. Caused by planned maint work order. Fire doors returned to normal operation upon work completion.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/18.
O'REILLY, J P. Region 2, Office of Director. 2pp. 17682:289. 24X
Fiche: 50-416, 83/03/18, 8303240531.

8303240552 RO 83-004/0 on 830209, w/reactor mode switch in refuel position, LPCS room fire door blocked open to allow for planned welding. Fire watch established. Door closed upon completion of work.
MCGAUGHY, J P. Mississippi Power & Light Co. 83/03/18.
O'REILLY, J P. Region 2, Office of Director. 2pp. 17682:224. 24X
Fiche: 50-416, 83/03/18, 8303240552.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082.

# DOCKETED ITEMS

8303030384 Advises that 830128 request for mod to FSAR Subsection 18.I.4 to reduce senior operator on shift training requirement from 3 to 6 months acceptable & within requirements of NUREG-0737.
SCHWENCER, A. Licensing Branch 2 83/02/24 MCGAUGHY, J. P. Mississippi Power & Light Co. 2pp. 17419:324 24X
Fiche: 50-416, 83/02/24, 8303030384

8303310453 Partial response to FOIA request for six categories of documents. Forwards App A documents identified as Items 1, 3, 4, 5 & 6 of request. Search for documents re Item 2 of request continuing.
FELTON, J. M. Division of Rules and Records 83/02/24 HIATT, S. L. Ohio Citizens for Responsible Energy 2pp. 17804:132 24X
Fiche: 50-000, 83/02/24, 8303310453

--8303310465 "Assessment of Postulated Degraded Core Accidents in Grand Gulf Reactor Plant," draft informal rept.
GASSER, R. D. Brookhaven National Laboratory 82/06/30 NRC - No Detailed Affiliation Given 247pp. 17804:135 24X
Fiche: 50-000, 83/02/24, 8303310453.

--8303310470 Forwards "Analysis of Full Core Meltdown Accidents in Grand Gulf Reactor Plant," draft informal rept. Rept satisfies preliminary rept milestone for Task I defined in "Safety Evaluation of Core Melt Accidents CP, ML & OL Applicants."
PRATT, W. T. Brookhaven National Laboratory FIN A-3399 82/09/21.
MEYER, J. E. Reactor Systems Branch 1p. 17805:022 24X
Fiche: 50-000, 83/02/24, 8303310453

--8303310476 "Analysis of Full Core Meltdown Accidents in Grand Gulf Reactor Plant," draft informal rept.
GASSER, R. D. Brookhaven National Laboratory FIN A-3399 82/08/31 NRC - No Detailed Affiliation Given 467pp. 17805:023 24X Fiche: 50-000, 83/02/24, 8303310453.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STB on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005

8303290369 Forwards proprietary & nonproprietary versions of "CLASIX-3 Computer Program for Analysis of Reactor Plant Containment Response to Hydrogen Release & Deflagration." Proprietary version withheld (ref 10CFR2.790).
RICHARDSON, J. D. Hydrogen Control Owners Group, BWR-6 Mark III.
RICHARDSON, J. D. Mississippi Power & Light Co. 83/03/18.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 17726:079 24X Fiche: 50-000, 83/03/18, 8303290369

--8303290378 Requests that "CLASIX-3 Computer Program for Analysis of Reactor Plant Containment Response to Hydrogen Release & Deflagration" be withheld from public disclosure. Affidavit encl.
WIESEMANN, R. A. Westinghouse Electric Corp. 83/01/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 6pp. 17726:081 24X Fiche: 50-000, 83/03/18, 8303290369

8303280025 Forwards response to five of six items contained in 821203 ltr re util work addressing containment issues. Evaluation of condensation oscillation loads produced by discharges from RHR HX relief valve will be completed by late Apr.
DALE, L. F. Mississippi Power & Light Co. 83/03/23. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 31pp. 17707:159 24X Fiche: 50-416, 83/03/23, 8303280025

## E. NRC Safety Evaluation Report (SER), supplS & correspondence

8303080508 Submits info re deep draft pumps trending analysis, Humphrey containment concerns & masonry wall design & const, per supplemental SER, in response to NRC 830112 request.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/02/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp. 17452:281 24X Fiche: 50-416, 83/02/25, 8303080508

## F. Security, medical, emergency & fire protection plans

8303010307 Advises that response to NRC comments on Rev 5 to physical security plan will be delayed until 830318.
DALE, L. F. Mississippi Power & Light Co. 83/02/25 SCHWENCER, A. Licensing Branch 2 2pp. 17333:329 24X Fiche: 50-416, 83/02/25, 8303010307

## G. Inspection reports, IE Bulletins & correspondence

8303210338 Forwards IE Insp Rept 50-417/83-02 on 830207-10. No noncompliance noted.
VERRELLI, D. M. Division of Project & Resident Programs 83/02/24.
STAMPLEY, N. L. Mississippi Power & Light Co. 2pp. 17634:038 24X
Fiche: 50-417, 83/02/24, 8303210338

--8303210341 IE Insp Rept 50-417/83-02 on 820207-10. No noncompliance noted. Major areas inspected: RCPB piping; safety-related piping, containment steel structures & supports; safety-related steel structures & supports.
CROWLEY, B. R., BLAKE, J. J. Region 2, Office of Director 83/02/24 14pp. 17634:040 24X Fiche: 50-417, 83/02/24, 8303210338

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210328 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetrations." Bunker-Ramo electrical penetrations not used at facility. Three manhours expended in bulletin response.
DALE, L. F. Mississippi Power & Light Co. 83/03/03. O'REILLY, J. P. Region 2, Office of Director 2pp. 17632:121 24X
Fiche: 50-416, 83/03/03, 8303210328.

8303210564 Ack receipt of 830218 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-416/83-03 & 50-417/83-01.
VERRELLI, D. M. Division of Project & Resident Programs 83/03/03.
STAMPLEY, N. L. Mississippi Power & Light Co. 1p. 17636:343 24X
Fiche: 50-416, 83/03/03, 8303210564

--8303210579 Responds to NRC 830119 ltr re violations noted in IE Insp Rept 50-417/83-01. Corrective actions: concrete wall pour 92T22-W-22183WIA completed on 830104. QC verified that curing process initiated at proper time.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/02/18.
O'REILLY, J. P. Region 2, Office of Director 3pp. 17636:344 24X
Fiche: 50-416, 83/03/03, 8303210564

--8303210587 Forwards IE Insp Repts 50-416/83-03 & 50-417/83-01 on 830104-07 & notice of violation.
VERRELLI, D. M. Division of Project & Resident Programs 83/01/19.
STAMPLEY, N. L. Mississippi Power & Light Co. 2pp. 17636:347 24X
Fiche: 50-416, 83/03/03, 8303210564

--8303210592 Notice of violation from insp on 830104-07.
* Region 2, Office of Director 83/01/19 1p. 17636:349 24X
Fiche: 50-416, 83/03/03, 8303210564

--8303210597 IE Insp Repts 50-416/83-03 & 50-417/83-01 on 830104-07. Noncompliance noted: failure to properly cure concrete in auxiliary bldg const.
HARRIS, J. R. Region 2, Office of Director. CONLON, T. E. Division of Engineering & Radiological Safety Programs. 83/01/17 4pp.
17636:350 24X Fiche: 50-416, 83/03/03, 8303210564

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21 Consolidated Edisrn Co. of New York, Inc. 121pp. 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

## S. Reportable occurrences, LERs & related correspondence

8303140498 Interim deficiency rept re incorrect wipe setting of normally closed contacts converted from open contacts on some HFA relays. Initially reported on 820802. Also reportable per Part 21 for Unit 1.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/02/24.
O'REILLY, J. P. Region 2, Office of Director 5pp. 17540:314 24X
Fiche: 50-416, 83/02/24, 8303140498.

8303240560 Interim Deficiency Rept 2 re Nelson stud failures on embed plates. Initially reported on 821221. Failed plate sent to TRW to determine cause. New plates installed. Final rept by 830607. Also reported per Part 21.
MCGAUGHY, J. P. Mississippi Power & Light Co. 83/03/15
O'REILLY, J. P. Region 2, Office of Director. 5pp. 17683:197. 24X
Fiche: 50-416. 83/03/15. 8303240560.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000. 83/02/24. 8302250505.

DOCKET: 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000. 83/02/16. 8302170082.

8303040178 Responds to 830128 ltr re simulator program & commends util commitment to provide plant-specific simulators for use in training nuclear power plant operators.
THOMPSON, H. L. Division of Human Factors Safety. 83/02/25.
COUNSIL, W. G. Northeast Utilities. 4pp. 17427:018. 24X
Fiche: 50-000. 83/02/25. 8303040178.

--8303040187 Discusses use of plant simulators to train nuclear power plant operators. Util committed to procurement & use of plant-specific simulators.
COUNSIL, W. G. Connecticut Yankee Atomic Power Co. 83/01/28.
DIRCKS, W. J. Office of the Executive Director for Operations. 3pp. 17427:022. 24X Fiche: 50-000. 83/02/25. 8303040178.

8303110047 Advises of safety & environ review schedules for OL. Safety review questions should be submitted by 830415. Environ review questions resulting from site visit should be submitted within 1 wk following Apr site visit.
EISENHUT, D. G. Division of Licensing. 83/03/01. VOLLMER, R. H. Division of Engineering. MATTSON, R. J. Division of Systems Integration (post 811005). THOMPSON, H. L. Division of Human Factors Safety. 3pp. 17546:264. 24X Fiche: 50-423. 83/03/01. 8303110047.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000. 83/03/02. 8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12) Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176. 24X
Fiche: 50-000. 83/03/07. 8303040005.

8303160550 Responds to 830217 ltr requesting info on presence of federally listed & proposed endangered or threatened species in plant area. Except for occasional transient individuals, no species identified in project impact areas.
BECKETT, G. E. Interior, Dept. of, Fish & Wildlife Service. 83/03/10.
YOUNGBLOOD, B. J. Licensing Branch 1. 2pp. 17587:260. 24X
Fiche: 50-245. 83/03/10. 8303160550.

8303220431 Notification of 830412 meeting w/util to provide opportunity to air views on specific issues of particular concern during OL application review.
EISENHUT, D. G. Division of Licensing. 83/03/18. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. MATTSON, R. J. Division of Systems Integration (post 811005). VOLLMER, R. H. Division of Engineering. 1p. 17672:240. 24X Fiche: 50-423. 83/03/18. 8303220431.

8303300289 Requests approval of change in schedule for environ review of OL application. Change involves approx 3 month postponement.
YOUNGBLOOD, B. J. Licensing Branch 1. 83/03/21. EISENHUT, D. G. Division of Licensing. 2pp. 17749:127. 24X Fiche: 50-423. 83/03/21. 8303300289.

8303300278 Notification of 830412 meeting w/util in Bethesda, MD to discuss review of docketed OL application.
DOOLITTLE, E. W. Licensing Branch 1. 83/03/23. YOUNGBLOOD, B. J. Licensing Branch 1. 3pp. 17749:102. 24X Fiche: 50-423. 83/03/23. 8303300278.

8303300739 Requests 830412 mgt meeting in order to discuss plans for licensing review of OL application & to provide mgt w/opportunity to air views on specific issues of particular concern. Brief presentation on plant status requested.
YOUNGBLOOD, B. J. Licensing Branch 1. 83/03/23. COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp. 17765:197. 24X Fiche: 50-423. 83/03/23. 8303300739.

C. Utility Environmental Report (ER), amends & correspondence

8303040487 Forwards Amend 1 to environ rept - OL stage & Amend 1 to FSAR (filed in PDR Category K).
COUNSIL, W. G. ; SEARS, C. F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/02/28.
YOUNGBLOOD, B. J. Licensing Branch 1. 3pp. 17422:242. 24X
Fiche: 50-423. 83/02/28. 8303040487.

--8303040493 Amend 1 to environ rept - OL stage, covering transportation, major industries, educ facilities & other major institutions.
* Northeast Utilities. 83/02/28. 93pp. 17422:245. 24X
Fiche: 50-423. 83/02/28. 8303040487.

K. Utility Final Safety Analysis Report (FSAR) & amends

8303040487 Forwards Amend 1 to FSAR.
COUNSIL, W. G. ; SEARS, C. F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/02/28.
YOUNGBLOOD, B. J. Licensing Branch 1. 3pp. 17422:242. 24X
Fiche: 50-423. 83/02/28. 8303040487.

--8303040496 Amend 1 to FSAR, covering comparison of containment concepts & atmosphere pressure sensor parameters.
* Northeast Utilities. 83/02/28. 490pp. 17422:340. 24X
Fiche: 50-423. 83/02/28. 8303040487.

Q. Inspection reports, IE Bulletins & correspondence

8303030144 Forwards IE Insp Rept 50-423/83-01 on 830124-28 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/02/16.
COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 17410:332. 24X Fiche: 50-423. 83/02/16. 8303030144.

--8303030175 Notice of violation from insp on 830124-28.
* Division of Engineering & Technical Programs. 83/02/16. 1p. 17410:334. 24X Fiche: 50-423. 83/02/16. 8303030144.

--8303030183 IE Insp Rept 50-423/83-01 on 830124-28. Noncompliance noted: use of stainless steel weld procedure for welding on Inconel.
GRAY, E. H. ; NARROW, L. Region 1, Office of Director. 83/02/15.
6pp. 17410:335. 24X Fiche: 50-423. 83/02/16. 8303030144.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche: 50-000. 83/02/25. 8212060367.

8303240499 Forwards IE Insp Rept 50-423/83-03 on 830210. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/01.
COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 17682:226. 24X Fiche: 50-423. 83/03/01. 8303240499.

--8303240512 IE Insp Rept 50-423/83-03 on 830210. No noncompliance noted. Major areas inspected: environ protection program for const phase & verification of implementation status of CP requirements.
JANG, J. C. ; PASCIAK, W. J. Region 1, Office of Director. 83/02/25.
3pp. 17682:228. 24X Fiche: 50-423. 83/03/01. 8303240499.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070. 24X Fiche: 50-000. 83/03/11. 8212060380.

8303280178 Forwards IE Insp Rept 50-423/83-02 on 830110-0214. No noncompliance noted.
STAROSTECKI, R. Division of Project & Resident Programs. 83/03/14.
COUNSIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 17708:172. 24X Fiche: 50-423. 83/03/14. 8303280178.

--8303280188 IE Insp Rept 50-423/83-02 on 830110-0214 No noncompliance noted. Major areas inspected: followup of previous insp findings; review of licensee action for NRC issued bulletins, circulars & info notices & 10CFR50.55(e) items.
MATTIA, J. C. Region 1, Office of Director. ELSASSER, T. Division of Project & Resident Programs. 83/03/09. 10pp. 17708:174. 24X Fiche: 50-423, 83/03/14, 8303280178.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering. Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering. Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-424 ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche: 50-000, 83/02/16, 8302170082.

8303140544 Informs that due to evaluation problems, submittal of final rept re unverified computer code for main feedwater pipe supports will be delayed from 830228 to 830422.
FOSTER, D. O. Georgia Power Co. 83/02/28. O'REILLY, J. P. Region 2, Office of Director. 1p. 17534:049. 24X Fiche: 50-424, 83/02/28, 8303140544.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche: 50-000, 83/03/02, 8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 5pp. 17660:176. 24X Fiche: 50-000, 83/03/07, 8303040005.

8303160075 Notification of 830317 meeting w/util & Southern Co Svcs, Inc in Atlanta, GA to discuss FSAR preparation.
MILLER, M. A. Licensing Branch 4. 83/03/11. ADENSAM, E. G. Licensing Branch 4. 2pp. 17604:361. 24X Fiche: 50-424, 83/03/11, 8303160075.

8303230518 Forwards review of util rept "Studies of Postulated Millet Fault." Fault investigation prompted by USGS Open-File Rept 82-156. No evidence of capable fault at locations inferred in open-file rept.
NOVAK, T. M. Assistant Director for Licensing. 83/03/16. DUTTON, D. Georgia Power Co. 7pp. 17677:243. 24X Fiche: 50-424, 83/03/16, 8303230518.

F. Security, medical, emergency & fire protection plans

8303210443 Forwards IE Insp Repts 50-424/83-03 & 50-425/83-03 on 830118-21. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/03/01.
KELLY, R. J. Georgia Power Co. 2pp. 17634:194. 24X
Fiche: 50-424, 83/03/01, 8303210443.

--8303210451 IE Insp Repts 50-424/83-03 & 50-425/83-03 on 830118-21. No noncompliance noted. Major areas inspected: electrical components & sys; work activities & fire protection.
GIBBONS, T. D. Region 2, Office of Director. CONLON, T. E. Division of Engineering & Radiological Safety Programs. 83/02/28. 3pp. 17634:196. 24X Fiche: 50-424, 83/03/01, 8303210443.

G. Inspection reports, IE Bulletins & correspondence

8303210481 Forwards IE Insp Repts 50-424/83-02 & 50-425/83-02 on 830117-21. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/02/14.
KELLY, R. J. Georgia Power Co. 2pp. 17631:301. 24X
Fiche: 50-424, 83/02/14, 8303210481.

--8303210497 IE Insp Repts 50-424/83-02 & 50-425/83-02 on 830117-21. No noncompliance noted. Major areas inspected: licensee action on previous enforcement matters; licensee identified matters & IE bulletins.
GIRARD, E. H., BLAKE, J. J. Region 2, Office of Director. 83/02/10. 5pp. 17631:303. 24X Fiche: 50-424, 83/02/14, 8303210481.

8303210573 Forwards IE Insp Repts 50-424/83-01 & 50-425/83-01 on 821214-830114. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/02/16.
KELLY, R. J. Georgia Power Co. 2pp. 17632:226. 24X
Fiche: 50-424, 83/02/16, 8303210573.

--8303210589 IE Insp Repts 50-424/83-01 & 50-425/83-01 on 821214-830114. No noncompliance noted. Major areas inspected: primary containment structures; steam generator placements; containment liner penetrations & electrical matl storage.
SANDERS, W. F. Region 2, Office of Director. BROWNLEE, V. L. Division of Project & Resident Programs. 83/02/15. 4pp. 17632:228. 24X Fiche: 50-424, 83/02/16, 8303210573.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303210348 Responds to IE Bulletin re deficiencies in hard epoxy electrical penetration assemblies mfg by Bunker-Ramo. Facility uses Conax penetration assemblies.
FOSTER, D. O. Georgia Power Co. FOSTER, D. O. Southern Co. Services, Inc. 83/02/25. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17634:145. 24X Fiche: 50-424, 83/02/25, 8303210348.

8303210443 Forwards IE Insp Repts 50-424/83-03 & 50-425/83-03 on 830118-21. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/03/01.
KELLY, R. J. Georgia Power Co. 2pp. 17634:194. 24X
Fiche: 50-424, 83/03/01, 8303210443.

--8303210451 IE Insp Repts 50-424/83-03 & 50-425/83-03 on 830118-21. No noncompliance noted. Major areas inspected: electrical components & sys; work activities & fire protection.
GIBBONS, T. D. Region 2, Office of Director. CONLON, T. E. Division of Engineering & Radiological Safety Programs. 83/02/28. 3pp. 17634:196. 24X Fiche: 50-424, 83/03/01, 8303210443.

8303210653 Ack receipt of 830211 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-424/82-29 & 50-425/82-29.
LEWIS, R. C. Division of Project & Resident Programs. 83/03/01.
KELLY, R. J. Georgia Power Co. 1p. 17635:175. 24X
Fiche: 50-424, 83/03/01, 8303210653.

--8303210660 Responds to NRC 830111 ltr re violation noted in IE Insp Repts 50-424/82-29 & 50-425/82-29. Corrective actions: equipment program re-evaluated, Procedure GD-T-09 & desk instructions revised & torn/loose coverings replaced.
FOSTER, D. O. Georgia Power Co. 83/02/11. LEWIS, R. C. Region 2, Office of Director. 2pp. 17635:176. 24X Fiche: 50-424, 83/03/01, 8303210653.

--8303210670 Forwards IE Insp Repts 50-424/82-29 & 50-425/82-29 on 821115-1213 & notice of violation.
LEWIS, R. C. Division of Project & Resident Programs. 83/01/11.
KELLY, R. J. Georgia Power Co. 2pp. 17635:178. 24X
Fiche: 50-424, 83/03/01, 8303210653.

--8303210674 Notice of violation from insp on 821115-1213.
* Region 2, Office of Director. 83/01/11. 1p. 17635:180. 24X
Fiche: 50-424, 83/03/01, 8303210653.

--8303210684 IE Insp Repts 50-424/82-29 & 50-425/82-29 on 821115-1213. Noncompliance noted: 27 electrical equipment cabinets stored in Level B of control bldg w/o required protection for damage from dust, dirt, moisture, vandalism & rodents.
SANDERS, W. F. Region 2, Office of Director. BROWNLEE, V. L. Division of Project & Resident Programs. 83/01/11. 6pp. 17635:181. 24X Fiche: 50-424, 83/03/01, 8303210653.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070. 24X Fiche. 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering. Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche. 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering. Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 12ipp. 17774:352. 24X Fiche. 50-000, 83/03/21, 8212060387.

S. Reportable occurrences, LERs & related correspondence

8303210408 Interim deficiency rept re HVAC duct supports-design inconsistencies. Initially reported on 820930. All duct support std design drawings reviewed & revised as necessary. Final rept expected by 830805.
FOSTER, D. O. Georgia Power Co. 83/02/25. O'REILLY, J. P. Region 2, Office of Director. 4pp. 17634:329. 24X Fiche. 50-424, 83/02/25, 8303210408.

8303210647 Interim deficiency rept re quality of Pullman Power Products welds & radiographs. Initially reported on 830125. Investigation in progress. Next interim rept will be submitted by 830527.
FOSTER, E. J. Georgia Power Co. 83/02/28. O'REILLY, J. P. Region 2, Office of Director. 1p. 17636:251. 24X Fiche. 50-424, 83/02/28, 8303210647.

8303210499 Significant deficiency rept re Transamerica Delaval diesel generator piston skirt cracking. Initially reported on 821223. Defective piston skirts will be replaced by vendor. Also reported per Part 21.
FOSTER, D. O. Georgia Power Co. 83/03/01. O'REILLY, J. P. Region 2, Office of Director. 4pp. 17631:221. 24X Fiche. 50-424, 83/03/01, 8303210499.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche. 50-000, 83/02/24, 8302250505.

DOCKET 50-425 ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche. 50-000, 83/02/16, 8302170082.

8303140544 Informs that due to evaluation problems, submittal of final rept re unverified computer code for main feedwater pipe supports will be delayed from 830228 to 830422.
FOSTER, D. O. Georgia Power Co. 83/02/28. O'REILLY, J. P. Region 2, Office of Director. 1p. 17534:049. 24X Fiche. 50-424, 83/02/28, 8303140544.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X Fiche. 50-000, 83/02/02, 8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel" (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 5ipp. 17660:176. 24X Fiche. 50-000, 83/03/07, 8303040005.

8303160075 Notification of 830317 meeting w/util & Southern Co Svcs, Inc in Atlanta, GA to discuss FSAR preparation.
MILLER, M. A. Licensing Branch 4. 83/03/11. ADENSAM, E. G. Licensing Branch 4. 2pp. 17604:361. 24X Fiche. 50-424, 83/03/11, 8303160075.

8303230518 Forwards review of util rept "Studies of Postulated Millet Fault." Fault investigation prompted by USGS Open-File Rept 82-156. No evidence of capable fault at locations inferred in open-file rept.
NOVAK, T. M. Assistant Director for Licensing. 83/03/16. DUTTON, D. Georgia Power Co. 7pp. 17677:243. 24X Fiche. 50-424, 83/03/16, 8303230518.

F. Security, medical, emergency & fire protection plans

8303210443 Forwards IE Insp Repts 50-424/83-03 & 50-425/83-03 on 830118-21. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/03/01. KELLY, R. J. Georgia Power Co. 2pp. 17634:194. 24X Fiche. 50-424, 83/03/01, 8303210443.

--8303210451 IE Insp Repts 50-424/83-03 & 50-425/83-03 on 830118-21. No noncompliance noted. Major areas inspected: electrical components & sys, work activities & fire protection.
GIBBONS, T. D. Region 2, Office of Director. 83/02/28. 3pp. 17634:196. 24X Fiche. 50-424, 83/03/01, 8303210443.

G. Inspection reports, IE Bulletins & correspondence

8303210481 Forwards IE Insp Repts 50-424/83-02 & 50-425/83-02 on 830117-21. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/02/14. KELLY, R. J. Georgia Power Co. 2pp. 17631:301. 24X Fiche. 50-424, 83/02/14, 8303210481.

--8303210497 IE Insp Repts 50-424/83-02 & 50-425/83-02 on 830117-21. No noncompliance noted. Major areas inspected: licensee action on previous enforcement matters, licensee identified matters & IE bulletins.
GIRARD, E. H., BLAKE, J. J. Region 2, Office of Director. 83/02/10. 5pp. 17631:303. 24X Fiche. 50-424, 83/02/14, 8303210481.

8303210573 Forwards IE Insp Repts 50-424/83-01 & 50-425/83-01 on 821214-830114. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/02/16. KELLY, R. J. Georgia Power Co. 2pp. 17632:226. 24X Fiche. 50-424, 83/02/16, 8303210573.

--8303210589 IE Insp Repts 50-424/83-01 & 50-425/83-01 on 821214-830114. No noncompliance noted. Major areas inspected: primary containment structures, steam generator placements, containment liner penetrations & electrical matl storage.
SANDERS, W. F. Region 2, Office of Director. BROWNLEE, V. L. Division of Project & Resident Programs. 83/02/15. 4pp. 17632:228. 24X Fiche. 50-424, 83/02/16, 8303210573.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11ipp. 17521:001. 24X Fiche. 50-000, 83/02/25, 8212060367.

8303210348 Responds to IE Bulletin re deficiencies in hard epoxy electrical penetration assemblies mfg by Bunker-Ramo. Facility uses Conax penetration assemblies.
FOSTER, D. O. Georgia Power Co. FOSTER, D. O. Southern Co. Services, Inc. 83/02/25. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17634:145. 24X Fiche. 50-424, 83/02/25, 8303210348.

8303210443 Forwards IE Insp Repts 50-424/83-03 & 50-425/83-03 on 830118-21. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 83/03/01. KELLY, R. J. Georgia Power Co. 2pp. 17634:194. 24X Fiche. 50-424, 83/03/01, 8303210443.

--8303210451 IE Insp Repts 50-424/83-03 & 50-425/83-03 on 830118-21. No noncompliance noted. Major areas inspected: electrical components & sys, work activities & fire protection.
GIBBONS, T. D. Region 2, Office of Director. CONLON, T. E. Division of Engineering & Radiological Safety Programs. 83/02/28. 3pp. 17634:196. 24X Fiche. 50-424, 83/03/01, 8303210443.

8303210653 Ack receipt of 830211 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-424/82-29 & 50-425/82-29.
LEWIS, R. C. Division of Project & Resident Programs. 83/03/01. KELLY, R. J. Georgia Power Co. 1p. 17635:175. 24X Fiche. 50-424, 83/03/01, 8303210653.

--8303210660 Responds to NRC 830111 ltr re violation noted in IE Insp Repts 50-424/82-29 & 50-425/82-29 Corrective actions equipment program re-evaluated. Procedure GD-T-09 & desk instructions revised & torn/loose coverings replaced
FOSTER, D O Georgia Power Co 83/02/11 LEWIS, R C Region 2, Office of Director 2pp 17635 176 24X Fiche 50-424, 83/03/01, 8303210653

--8303210670 Forwards IE Insp Repts 50-424/82-29 & 50-425/82-29 on 821115-1213 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/01/11
KELLY, R J Georgia Power Co 2pp 17635 178 24X Fiche 50-424, 83/03/01, 8303210653

--8303210674 Notice of violation from insp on 821115-1213
* Region 2, Office of Director 83/01/11 1p 17635 180 24X Fiche 50-424, 83/03/01, 8303210653

--8303210684 IE Insp Repts 50-424/82-29 & 50-425/82-29 on 821115-1213 Noncompliance noted: 27 electrical equipment cabinets stored in Level B of control bldg w/o required protection for damage from dust, dirt, moisture, vandalism & rodents
SANDERS, W F Region 2, Office of Director BROWNLEE, V L Division of Project & Resident Programs 83/01/11 6pp 17635 181 24X Fiche 50-424, 83/03/01, 8303210653

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc 117pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 121pp 17774 352 24X Fiche 50-000, 83/03/21, 8212060387

S Reportable occurrences, LERs & related correspondence

8303210408 Interim deficiency rept re HVAC duct supports-design inconsistencies Initially reported on 820930 All duct support std design drawings reviewed & revised as necessary Final rept expected by 830805
FOSTER, D O Georgia Power Co 83/02/25 O'REILLY, J P Region 2, Office of Director 4pp 17634 329 24X Fiche 50-424, 83/02/25, 8303210408

8303210647 Interim deficiency rept re quality of Pullman Power Products welds & radiographs Initially reported on 830125 Investigation in progress Next interim rept will be submitted by 830527
FOSTER, E J Georgia Power Co 83/02/28 O'REILLY, J P Region 2, Office of Director 1p 17636 251 24X Fiche 50-424, 83/02/28, 8303210647

8303210499 Significant deficiency rept re Transamerica Delaval diesel generator piston skirt cracking Initially reported on 821223 Defective piston skirts will be replaced by vendor Also reported per Part 21
FOSTER, D O Georgia Power Co 83/03/01 O'REILLY, J P Region 2, Office of Director 4pp 17631 221 24X Fiche 50-424, 83/03/01, 8303210499

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000, 83/02/24, 8302250505

DOCKET 50-426 ALVIN W VOGTLE NUCLEAR PLANT, UNIT 3

H General correspondence

8303300062 Responds to 830302 proposal re closing LPDRs for cancelled or deferred plants No objection to closing LPDRs for submitted plants Other LPDRs will remain open pending resolution of CP status
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/03/18 FELTON, J M Division of Rules and Records 3pp 17751 074 24X Fiche 50-000, 83/03/18, 8303300062

DOCKET 50-427 ALVIN W VOGTLE NUCLEAR PLANT, UNIT 4

H General correspondence

8303300062 Responds to 830302 proposal re closing LPDRs for cancelled or deferred plants No objection to closing LPDRs for submitted plants Other LPDRs will remain open pending resolution of CP status
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/03/18 FELTON, J M Division of Rules and Records 3pp 17751 074 24X Fiche 50-000, 83/03/18, 8303300062

DOCKET STN-50-437 FLOATING NUCLEAR PLANT

A Application/construction stage documents & correspondence

8303100400 Ack receipt of Generic Ltr 83-07 re requirements of Nuclear Waste Policy Act of 1982 Lists reasons for not entering into waste disposal contract w/DOE
THOMAS, R A Offshore Power Systems (subs of Westinghouse Electric Corp.) 83/03/01 EISENHUT, D G Division of Licensing 2pp 17490 335 24X Fiche 50-437, 83/03/01, 8303100400

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X Fiche 50-000, 83/03/02, 8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12) Svc list encl
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 5lpp 17660 176 24X Fiche 50-000, 83/03/07, 8303040005

8303280137 Comments on Board Notification 83-38 re failure of GE AK-2 reactor trip breakers Info may affect NRC conclusions re probability/corrective measures for transients w/o scram events (Unresolved Safety Issue A-9)
EISENHUT, D G Division of Licensing 83/03/22 PALLADINO, N Commissioners 20pp 17709 310 24X Fiche 50-000, 83/03/22, 8303280137

Q Adjudicatory correspondence

8303140277 Decision ALAB-718, affirming LBP-82-49 authorizing NRR Director to issue license to mfg standardized nuclear power plants Consideration of site-specific concerns properly deferred not wrongly ignored
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/03/10 5pp 17535 105 24X Fiche 50-437, 83/03/10, 8303140277

Q Inspection reports, IE Bulletins & correspondence

8303110355 Board Notification 83-14 forwards followup info on apparent deficiencies in Midland-Ross superstrut matl
EISENHUT, D G Division of Licensing 83/02/18 PALLADINO, N Commissioners 24pp 17546 205 24X Fiche 50-000, 83/02/18, 8303110355

S Reportable occurrences, LERs & related correspondence

8303150620 Board Notification 83-26 forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys Info may affect conclusions re probability of/corrective measures for ATWS
EISENHUT, D G Division of Licensing 83/03/03 PALLADINO, N Commissioners 24pp 17584 097 24X Fiche 50-000, 83/03/03, 8303150620

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000, 83/02/24, 8302250505

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 7 pp 17492 033 24X
Fiche 50-000, 83/02/16, 8302170082

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X
Fiche 50-000, 83/03/02, 8303020321

8303090403 Requests remittance of Class I & II fees for 830126 application requesting extension of const completion dates
DIGGS, R M License Fee Management Branch 83/03/03 PARRIS, H G Tennessee Valley Authority Ip 17484 098 24X
Fiche 50-438, 83/03/03, 8303090403

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel" (clarification of Generic Ltr 82-12) Svc list encl
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 5 pp 17660 176 24X
Fiche 50-000, 83/03/07, 8303040005

8303170136 Summary of 830223 meeting w/B&W Regulatory Response Group in Bethesda, MD re small break LOCA procedures & maintaining proper steam generator water level
VAN VLIET, J Operating Reactors Branch 4 83/03/08 Operating Reactors Branch 4 43pp 17615 224 24X Fiche 50-000, 83/03/08, 8303170136

8303160293 Responds to NRC 830303 ltr re determination of fees for facilities Fee acceptable & will be forwarded by wire transfer
MILLS, L M Tennessee Valley Authority 83/03/09 MILLER, W O License Fee Management Branch Ip 17596 257 24X
Fiche 50-438, 83/03/09, 8303160293

8303290343 Notifies that detailed plans & schedules for resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps," will be provided by 830815 Continued const justified & CPs should not be modified, suspended or revoked
KAMMER, D S Tennessee Valley Authority 83/03/24 EISENHUT, D G Division of Licensing 2pp 17718 099 24X Fiche 50-438, 83/03/24, 8303290343

F Security, medical, emergency & fire protection plans

8303010383 Forwards IE Insp Repts 50-438/83-01 & 50-439/83-01 on 830111-14 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/02/02
PARRIS, H G Tennessee Valley Authority 2pp 17343 348 24X
Fiche 50-438, 83/02/02, 8303010383

--8303010398 IE Insp Repts 50-438/83-01 & 50-439/83-01 on 830111-14 No noncompliance noted Major areas inspected receiving & storage installation of fire stops & instrumentation components & sys work & work activities
MERRIWEATHER, N , CONLON, T E Division of Engineering & Radiological Safety Programs 83/01/31 4pp 17343 350 24X
Fiche 50-438, 83/02/02, 8303010398

J Insurance & indemnity information

8303010239 Forwards Endorsements 17 & 18 to NELIA Policy NF-258
DUCK, J R Marsh & McLennan, Inc 83/02/22 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 17335 073 24X
Fiche 50-438, 83/02/22, 8303010239

8303290086 Forwards Endorsement 19 to NELIA Policy NF-258
DUCK, J R Marsh & McLennan, Inc 83/03/15 SALTZMAN, J Office of State Programs, Director 2pp 17723 113 24X
Fiche 50-438, 83/03/15, 8303290086

G Inspection reports, IE Bulletins & correspondence

8303010553 Responds to NRC 820812 ltr re violations noted in IE Insp Repts 50-438/82-22 & 50-439/82-22 Corrective actions delayed by extensive vendor evaluation but will be completed by 830701
MILLS, L M Tennessee Valley Authority 82/12/16 O'REILLY, J P Region 2, Office of Director Ip 17341 080 24X
Fiche 50-438, 82/12/16, 8303010563

8303010467 Supplis response to NRC 820826 ltr re violations noted in IE Insp Repts 50-438/82-23 & 50-439/82-23 Delay anticipated in receipt of info to identify cause of deficiencies Corrective actions to be completed by 830622
MILLS, L M Tennessee Valley Authority 82/12/17 O'REILLY, J P Region 3, Office of Director Ip 17343 305 24X
Fiche 50-438, 82/12/17, 8303010467

8303250016 Forwards IE Const Appraisal Repts 50-438/82-32 & 50-439/82-32 on 820920-1001 & 1012-22 No noncompliance noted
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/01/13 PARRIS, H G Tennessee Valley Authority 12pp 17693 141 24X Fiche 50-438, 83/01/13, 8303250016

--8303250034 IE Const Appraisal Repts 50-438/82-32 & 50-439/82-32 on 820920-1001 & 1012-22 No noncompliance noted Major areas inspected QA project mgt, design control changes & corrective action sys, electrical const & welding
KESHISHIAN, P , ROHRBACHER, R , GOWER, G Director's Office, Office of Inspection and Enforcement 83/01/05 102pp 17693 153 24X
Fiche 50-438, 83/01/13, 8303250016

8303010383 Forwards IE Insp Repts 50-438/83-01 & 50-439/83-01 on 830111-14 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/02/02
PARRIS, H G Tennessee Valley Authority 2pp 17343 348 24X
Fiche 50-438, 83/02/02, 8303010383

--8303010398 IE Insp Repts 50-438/83-01 & 50-439/83-01 on 830111-14 No noncompliance noted Major areas inspected receiving & storage installation of fire stops & instrumentation components & sys work & work activities
MERRIWEATHER, N , CONLON, T E Division of Engineering & Radiological Safety Programs 83/01/31 4pp 17343 350 24X
Fiche 50-438, 83/02/02, 8303010398

8303010303 Responds to addl questions re IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Components by Corbicula sp (Asiatic clam) & Mytilus sp (mussel)." Insps of ERCW sys produced no evidence of Asiatic clam infestation
MILLS, L M Tennessee Valley Authority 83/02/17 O'REILLY, S P Region 2, Office of Director 3pp 17341 072 24X
Fiche 50-438, 83/02/17, 8303010303

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 11pp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc 117pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 12ipp 17774 352 24X Fiche 50-000, 83/03/21, 8212060387

R Periodic operating reports & related correspondence

8303210340 Forwards interim environ radiological monitoring program, replacing preoperational monitoring program until 1 yr before Unit 1 fuel load Proposed changes necessary due to fuel load schedule slippages
MILLS, L M Tennessee Valley Authority 83/03/16 ADENSAM, E Licensing Branch 4 14pp 17634 268 24X Fiche 50-438, 83/03/16, 8303210340

S. Reportable occurrences, LERs & related correspondence

8303040352 First interim deficiency rept re snubber interference from rear brackets. Initially reported on 830126. Review of welded rear brackets planned. Corrective action will be determined. Next rept expected by 830722. Also reported per Part 21.
MILLS,L M. Tennessee Valley Authority. 83/02/24. O'REILLY, J P.
Region 2, Office of Director. 2pp. 17374:045. 24X
Fiche: 50-438, 83/02/24, 8303040352.

8303040384 Final deficiency rept re incorrect insp code on hanger drawings by ITT Grinnell. Initially reported on 820301. No deficiency in ITT Grinnell method of determining NDA designations identified.
MILLS,L M. Tennessee Valley Authority. 83/02/24. O'REILLY, J P.
Region 2, Office of Director. 2pp. 17420:001. 24X
Fiche: 50-438, 83/02/24, 8303040384.

8303040561 First interim deficiency rept re unidentifiable grade of nuts on approx 50% of all high strength bolted connections due to orientation. Initially reported on 830126. Sampling program will be conducted. Next rept expected by 830614.
MILLS,L M. Tennessee Valley Authority. 83/02/24. O'REILLY, J P.
Region 2, Office of Director. 2pp. 17374:138. 24X
Fiche: 50-438, 83/02/24, 8303040561.

8303040542 Supplemental final deficiency rept re potential deterioration of isoprene gaskets on standby diesel generators. Initially reported on 821217. Corrective action completed by 831228. Also reported per Part 21.
MILLS,L M. Tennessee Valley Authority. 83/02/28. O'REILLY, J P.
Region 2, Office of Director. 1p. 17366:001. 24X
Fiche: 50-438, 83/02/28, 8303040542.

8303040632 First interim deficiency rept re incorrect performance of seismic pipe support insp. Initially reported on 830131. Insp records for analyzed supports reviewed to determine location recorded within specs. Next rept by 830620.
MILLS,L M. Tennessee Valley Authority. 83/02/28. O'REILLY, J P.
Region 2, Office of Director. 2pp. 17368:348. 24X
Fiche: 50-438, 83/02/28, 8303040632.

8303210630 Third interim deficiency rept re operational defects in HPI nozzles & thermal sleeves. Initially reported on 820429. Next rept expected by 830418. Also reportable under Part 21.
MILLS,L M. Tennessee Valley Authority. 83/03/01. O'REILLY, J P.
Region 2, Office of Director. 2pp. 17636:214. 24X
Fiche: 50-438, 83/03/01, 8303210630.

8303140430 First interim deficiency rept re pressure drop across Velan 2 1/2-inch stop/check valve. Initially reported on 830202. Valves disassembled, but no blockage or defect found. Next rept expected by 830923. Also reportable under Part 21.
MILLS,L M. Tennessee Valley Authority. 83/03/03. O'REILLY, J P.
Region 2, Office of Director. 2pp. 17542:225. 24X
Fiche: 50-438, 83/03/03, 8303140430.

8303180022 Final deficiency rept re qualification of RHR/DHR sump valve rooms. Initially reported on 820422. Caused by failure to establish & implement design criteria in accordance w/FSAR. Mod underway.
MILLS,L M. Tennessee Valley Authority. 83/03/09. O'REILLY, J P.
Region 2, Office of Director. 2pp. 17618:102. 24X
Fiche: 50-000, 83/03/09, 8303180022.

8303180383 First interim deficiency rept re Johnson Machine Works welds on auxiliary feedwater pump doors. Initially reported on 830210. Util analyzing welds to determine performance during secondary safety function. Also reportable per Part 21.
MILLS,L M. Tennessee Valley Authority. 83/03/09. O'REILLY, J P.
Region 2, Office of Director. 2pp. 17621:346. 24X
Fiche: 50-438, 83/03/09, 8303180383.

8303160450 Final deficiency rept re addition of locking devices to handwheel-operated valves. Initially reported on 820916. No locking devices exceeding 10% valve weight criteria found. Item not reportable per 10CFR50.55(e).
MILLS,L M. Tennessee Valley Authority. 83/03/10. O'REILLY, J P.
Region 2, Office of Director. 2pp. 17592:272. 24X
Fiche: 50-000, 83/03/10, 8303160450.

8303180023 Eighth interim deficiency rept re ITT Grinnel welded supports w/discrepancies in weld designation. Initially reported on 800905. Util & manufacturer revising all hanger detail sheets. Also reported per Part 21. Next rept by 831208.
MILLS,L M. Tennessee Valley Authority. 83/03/11. O'REILLY, J P.
Region 2, Office of Director. 2pp. 17618:105. 24X
Fiche: 50-438, 83/03/11, 8303180023.

8303180348 Final deficiency rept re rebar missing from control bldg wall. Initially reported on 830210. Field change request to omit rebar initiated prior to pour. Condition not reportable per 10CFR50.55(e).
MILLS,L M. Tennessee Valley Authority. 83/03/11. O'REILLY, J P.
Region 2, Office of Director. 2pp. 17621:037. 24X
Fiche: 50-438, 83/03/11, 8303180348.

8303180472 Second interim deficiency rept re valves not installed to design criteria. Initially reported on 820804. Engineering change notice initiated to classify valves IE & provide isolation signal to automatically close isolation valves.
MILLS,L M. Tennessee Valley Authority. 83/03/11. O'REILLY, J P.
Region 2, Office of Director. 2pp. 17621:249. 24X
Fiche: 50-438, 83/03/11, 8303180472.

8303210605 Final deficiency rept re erroneous tolerance for tubular steel cable tray hangers. Initially reported on 810716. No condition adverse to safety of operations of plant exists. Condition not reportable per 10CFR50.55e.
MILLS,L M. Tennessee Valley Authority. 83/03/15. O'REILLY, J P.
Region 2, Office of Director. 3pp. 17636:314. 24X
Fiche: 50-438, 83/03/15, 8303210605.

8303210626 Third interim deficiency rept re use of fillet welds on piping lugs. Initially reported on 820819. Documentation efforts on qualification of lugs & calculation package currently in progress. Next rept expected by 830518.
MILLS,L M. Tennessee Valley Authority. 83/03/15. O'REILLY, J P.
Region 2, Office of Director. 2pp. 17636:277. 24X
Fiche: 50-438, 83/03/15, 8303210626.

8303210634 Suppl to final deficiency rept re reactor bldg hatch cover. Initially reported on 810820. Completion of corrective action not met by 830301 due to nonavailability of matls. Action should be complete by 830801.
MILLS,L M. Tennessee Valley Authority. 83/03/15. O'REILLY, J P.
Region 2, Office of Director. 1p. 17636:250. 24X
Fiche: 50-438, 83/03/15, 8303210634.

8303220119 Final deficiency rept re unacceptable pipe break interactions. Initially reported on 810127. Util issued several engineering change notices to add spray shields & drain pans.
MILLS,L M. Tennessee Valley Authority. 83/03/16. O'REILLY, J P.
Region 2, Office of Director. 2pp. 17649:269. 24X
Fiche: 50-438, 83/03/16, 8303220119.

8303220354 First interim deficiency rept re incorrect thermal data in Problem N4-1RK-A from Program EZ. Initially reported on 830216. Data hypothesized as being thermal condition that can occur, but not documented. Next rept expected by 840419.
MILLS,L M. Tennessee Valley Authority. 83/03/16. O'REILLY, J P.
Region 2, Office of Director. 2pp. 17648:361. 24X
Fiche: 50-438, 83/03/16, 8303220354.

8303240525 Final deficiency rept re quality engineering branch unauthorized review of purchase requisitions. Initially reported on 820120. Procedure EN DES-EP 5.01 revised to incorporate procurement specs requiring correct insp.
MILLS,L M. Tennessee Valley Authority. 83/03/17. O'REILLY, J P.
Region 2, Office of Director. 3pp. 17684:289. 24X
Fiche: 50-000, 83/03/17, 8303240525.

8303240406 Final deficiency rept re regional quality engineering branch insp ofc manpower. Initially reported on 820120. QA training completed 830318. Technical training will continue.
MILLS,L M. Tennessee Valley Authority. 83/03/18. O'REILLY, J P.
Region 2, Office of Director. 3pp. 17679:012. 24X
Fiche: 50-000, 83/03/18, 8303240406.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505.

8303080442 Submits schedule for NRC operator licensing exam site visits through 1985, in response to Generic Ltr 83-01. Exams on 830815-19 for Watts Bar requested to be postponed due to delay in final fuel loading date.
MILLS,L M. Tennessee Valley Authority. 83/02/28. ADENSAM, E. Licensing Branch 4. 2pp. 17454:256. 24X Fiche: 50-000, 83/02/28, 8303080442.

DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24X
Fiche 50-000, 83/02/16, 8302170082

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X
Fiche 50-000, 83/03/02, 8303020321

8303090403 Requests remittance of Class I & II fees for 830126 application requesting extension of const completion dates
DIGGS, R M License Fee Management Branch 83/03/03 PARRIS, H G Tennessee Valley Authority 1p 17484 098 24X
Fiche 50-438, 83/03/03, 8303090403

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12) Svc list encl
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 51pp 17660 176 24X
Fiche 50-000, 83/03/07, 8303040005

8303170136 Summary of 830223 meeting w/B&W Regulatory Response Group in Bethesda, MD re small break LOCA procedures & maintaining proper steam generator water level
VAN VLIET, J Operating Reactors Branch 4 83/03/08 Operating Reactors Branch 4 43pp 17615 224 24X Fiche 50-000, 83/03/08, 8303170136

8303160293 Responds to NRC 830303 ltr re determination of fees for facilities Fee acceptable & will be forwarded by wire transfer
MILLS, L M Tennessee Valley Authority 83/03/09 MILLER, W O License Fee Management Branch 1p 17596 257 24X
Fiche 50-438, 83/03/09, 8303160293

8303290343 Notifies that detailed plans & schedules for resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps," will be provided by 830815 Continued const justified & CPs should not be modified, suspended or revoked
KAMMER, D S Tennessee Valley Authority 83/03/24 EISENHUT, D G Division of Licensing 2pp 17718 099 24X Fiche 50-438, 83/03/24, 8303290343

F. Security, medical, emergency & fire protection plans

8303010383 Forwards IE Insp Repts 50-438/83-01 & 50-439/83-01 on 830111-14 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/02/02
PARRIS, H G Tennessee Valley Authority 2pp 17343 348 24X
Fiche 50-438, 83/02/02, 8303010383

--8303010398 IE Insp Repts 50-438/83-01 & 50-439/83-01 on 830111-14 No noncompliance noted Major areas inspected receiving & storage installation of fire stops & instrumentation components & sys work & work activities
MERRIWEATHER, N Division of Engineering & Radiological Safety Programs 83/01/31 4pp 17343 350 24X Fiche 50-438, 83/02/02, 8303010383

J. Insurance & indemnity information

8303010239 Forwards Endorsements 17 & 18 to NELIA Policy NF-258
DUCK, J R Marsh & McLennan, Inc 83/02/22 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 17335 073 24X
Fiche 50-438, 83/02/22, 8303010239

8303290086 Forwards Endorsement 19 to NELIA Policy NF-258
DUCK, J R Marsh & McLennan, Inc 83/03/15 SALTZMAN, J Office of State Programs, Director 2pp 17723 113 24X
Fiche 50-438, 83/03/15, 8303290086

Q. Inspection reports, IE Bulletins & correspondence

8303010563 Responds to NRC 820812 ltr re violations noted in IE Insp Repts 50-438/82-22 & 50-439/82-22 Corrective actions delayed by extensive vendor evaluation but will be completed by 830701
MILLS, L M Tennessee Valley Authority 82/12/16 O'REILLY, J P Region 2, Office of Director 1p 17341 080 24X
Fiche 50-438, 82/12/16, 8303010563

8303010467 Supplis response to NRC 820826 ltr re violations noted in IE Insp Repts 50-438/82-23 & 50-439/82-23 Delay anticipated in receipt of info to identify cause of deficiencies Corrective actions to be completed by 830622
MILLS, L M Tennessee Valley Authority 82/12/17 O'REILLY, J P Region 3, Office of Director 1p 17343 305 24X
Fiche 50-438, 82/12/17, 8303010467

8303250016 Forwards IE Const Appraisal Repts 50-438/82-32 & 50-439/82-32 on 820920-1001 & 1012-22 No noncompliance noted
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/01/13 PARRIS, H G Tennessee Valley Authority 12pp 17693 141 24X Fiche 50-438, 83/01/13, 8303250016

--8303250034 IE Const Appraisal Repts 50-438/82-32 & 50-439/82-32 on 820920-1001 & 1012-22 No noncompliance noted Major areas inspected QA, project mgt, design control changes & corrective action sys, electrical const & welding
KESHISHIAN, P , ROHRBACHER, R , GOWER, G Director's Office, Office of Inspection and Enforcement 83/01/05 102pp 17693 153 24X
Fiche 50-438, 83/01/13, 8303250016

8303010383 Forwards IE Insp Repts 50-438/83-01 & 50-439/83-01 on 830111-14 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/02/02
PARRIS, H G Tennessee Valley Authority 2pp 17343 348 24X
Fiche 50-438, 83/02/02, 8303010383

--8303010398 IE Insp Repts 50-438/83-01 & 50-439/83-01 on 830111-14 No noncompliance noted Major areas inspected receiving & storage installation of fire stops & instrumentation components & sys work & work activities
MERRIWEATHER, N , CONLON, T E Division of Engineering & Radiological Safety Programs 83/01/31 4pp 17343 350 24X
Fiche 50-438, 83/02/02, 8303010383

)10303 Responds to addl questions re IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Components by Corbicula sp (Asiatic clam) & Mytilus sp (mussel)," Insps of ERCW sys produced no evidence of Asiatic clam infestation
MILLS, L M Tennessee Valley Authority 83/02/17 O'REILLY, S P Region 2, Office of Director 3pp 17341 072 24X
Fiche 50-438, 83/02/17, 8303010303

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal," Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 111pp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers," Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc 117pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 121pp 17774 352 24X Fiche 50-000, 83/03/21, 8212060387

R. Periodic operating reports & related correspondence

8303210340 Forwards interim environ radiological monitoring program, replacing preoperational monitoring program until 1 yr before Unit 1 fuel load Proposed changes necessary due to fuel load schedule slippages
MILLS, L M Tennessee Valley Authority 83/03/16 ADENSAM, E Licensing Branch 4 14pp 17634 268 24X Fiche 50-438, 83/03/16, 8303210340

B. Reportable occurrences: LERs & related correspondence

8303040352 First interim deficiency rept re snubber interference from rear brackets. Initially reported on 830126. Review of welded rear brackets planned. Corrective action will be determined. Next rept expected by 830722. Also reported per Part 21.
MILLS,L.M. Tennessee Valley Authority. 83/02/24. O'REILLY,J.P.
Region 2, Office of Director. 2pp. 17374:045. 24X
Fiche: 50-438,83/02/24,8303040352.

8303040384 Final deficiency rept re incorrect insp code on hanger drawings by ITT Grinnell. Initially reported on 820301. No deficiency in ITT Grinnell method of determining NDA designations identified.
MILLS,L.M. Tennessee Valley Authority. 83/02/24. O'REILLY,J.P.
Region 2, Office of Director. 2pp. 17420:001. 24X
Fiche: 50-438,83/02/24,8303040384.

8303040561 First interim deficiency rept re unidentifiable grade of nuts on approx 50% of all high strength bolted connections due to orientation. Initially reported on 830126. Sampling program will be conducted. Next rept expected by 830614.
MILLS,L.M. Tennessee Valley Authority. 83/02/24. O'REILLY,J.P.
Region 2, Office of Director. 2pp. 17374:138. 24X
Fiche: 50-438,83/02/24,8303040561.

8303040542 Supplemental final deficiency rept re potential deterioration of isoprene gaskets on standby diesel generators. Initially reported on 821217. Corrective action completed by 831228. Also reported per Part 21.
MILLS,L.M. Tennessee Valley Authority. 83/02/28. O'REILLY,J.P.
Region 2, Office of Director. 1p. 17366:001. 24X
Fiche: 50-438,83/02/28,8303040542.

8303040632 First interim deficiency rept re incorrect performance of seismic pipe support insp. Initially reported on 830131. Insp records for analyzed supports reviewed to determine location recorded within specs. Next rept by 830620.
MILLS,L.M. Tennessee Valley Authority. 83/02/28. O'REILLY,J.P.
Region 2, Office of Director. 2pp. 17368:348. 24X
Fiche: 50-438,83/02/28,8303040632.

8303210630 Third interim deficiency rept re operational defects in HPI nozzles & thermal sleeves. Initially reported on 820429. Next rept expected by 830418. Also reportable under Part 21.
MILLS,L.M. Tennessee Valley Authority. 83/03/01. O'REILLY,J.P.
Region 2, Office of Director. 2pp. 17636:214. 24X
Fiche: 50-438,83/03/01,8303210630.

8303140430 First interim deficiency rept re pressure drop across Velan 2 1/2-inch stop/check valve. Initially reported on 830202. Valves disassembled, but no blockage or defect found. Next rept expected by 830923. Also reportable under Part 21.
MILLS,L.M. Tennessee Valley Authority. 83/03/03. O'REILLY,J.P.
Region 2, Office of Director. 2pp. 17542:225. 24X
Fiche: 50-438,83/03/03,8303140430.

8303180022 Final deficiency rept re qualification of RHR/DHR sump valve rooms. Initially reported on 820422. Caused by failure to establish & implement design criteria in accordance w/FSAR. Mod underway.
MILLS,L.M. Tennessee Valley Authority. 83/03/09. O'REILLY,J.P.
Region 2, Office of Director. 2pp. 17618:102. 24X
Fiche: 50-000,83/03/09,8303180022.

8303180383 First interim deficiency rept re Johnson Machine Works welds on auxiliary feedwater pump doors. Initially reported on 830210. Util analyzing welds to determine performance during secondary safety function. Also reportable per Part 21.
MILLS,L.M. Tennessee Valley Authority. 83/03/09. O'REILLY,J.P.
Region 2, Office of Director. 2pp. 17621:346. 24X
Fiche: 50-438,83/03/09,8303180383.

8303160450 Final deficiency rept re addition of locking devices to handwheel-operated valves. Initially reported on 820916. No locking devices exceeding 10% valve weight criteria found. Item not reportable per 10CFR50.55(e).
MILLS,L.M. Tennessee Valley Authority. 83/03/10. O'REILLY,J.P.
Region 2, Office of Director. 2pp. 17592:272. 24X
Fiche: 50-000,83/03/10,8303160450.

8303180023 Eighth interim deficiency rept re ITT Grinnel welded supports w/discrepancies in weld designation. Initially reported on 800905. Util & manufacturer revising all hanger detail sheets. Also reported per Part 21. Next rept by 831208.
MILLS,L.M. Tennessee Valley Authority. 83/03/11. O'REILLY,J.P.
Region 2, Office of Director. 2pp. 17618:105. 24X
Fiche: 50-438,83/03/11,8303180023.

8303180348 Final deficiency rept re rebar missing from control bldg wall. Initially reported on 830210. Field change request to omit rebar initiated prior to pour. Condition not reportable per 10CFR50.55(e).
MILLS,L.M. Tennessee Valley Authority. 83/03/11. O'REILLY,J.P.
Region 2, Office of Director. 2pp. 17621:037. 24X
Fiche: 50-438,83/03/11,8303180348.

8303180472 Second interim deficiency rept re valves not installed to design criteria. Initially reported on 820804. Engineering change notice initiated to classify valves IE & provide isolation signal to automatically close isolation valves.
MILLS,L.M. Tennessee Valley Authority. 83/03/11. O'REILLY,J.P.
Region 2, Office of Director. 2pp. 17621:249. 24X
Fiche: 50-438,83/03/11,8303180472.

8303210605 Final deficiency rept re erroneous tolerance for tubular steel cable tray hangers. Initially reported on 810716. No condition adverse to safety of operations of plant exists. Condition not reportable per 10CFR50.55e.
MILLS,L.M. Tennessee Valley Authority. 83/03/15. O'REILLY,J.P.
Region 2, Office of Director. 3pp. 17636:314. 24X
Fiche: 50-438,83/03/15,8303210605.

8303210626 Third interim deficiency rept re use of fillet welds on piping lugs. Initially reported on 820819. Documentation efforts on qualification of lugs & calculation package currently in progress. Next rept expected by 830518.
MILLS,L.M. Tennessee Valley Authority. 83/03/15. O'REILLY,J.P.
Region 2, Office of Director. 2pp. 17636:277. 24X
Fiche: 50-438,83/03/15,8303210626.

8303210634 Suppl to final deficiency rept re reactor bldg hatch cover. Initially reported on 810820. Completion of corrective action not met by 830301, due to nonavailability of extls. Action should be complete by 830801.
MILLS,L.M. Tennessee Valley Authority. 83/03/15. O'REILLY,J.P.
Region 2, Office of Director. 1p. 17636:250. 24X
Fiche: 50-438,83/03/15,8303210634.

8303220119 Final deficiency rept re unacceptable pipe break interactions. Initially reported on 810127. Util issued several engineering change notices to add spray shields & drain pans.
MILLS,L.M. Tennessee Valley Authority. 83/03/16. O'REILLY,J.P.
Region 2, Office of Director. 2pp. 17649:269. 24X
Fiche: 50-438,83/03/16,8303220119.

8303240525 Final deficiency rept re quality engineering branch unauthorized review of purchase requisitions. Initially reported on 820120. Procedure EN-DES-EP-5.01 revised to incorporate procurement specs requiring correct insp.
MILLS,L.M. Tennessee Valley Authority. 83/03/17. O'REILLY,J.P.
Region 2, Office of Director. 3pp. 17684:289. 24X
Fiche: 50-000,83/03/17,8303240525.

8303240406 Final deficiency rept re regional quality engineering branch insp ofc manpower. Initially reported on 820120. QA training completed 830318. Technical training will continue.
MILLS,L.M. Tennessee Valley Authority. 83/03/18. O'REILLY,J.P.
Region 2, Office of Director. 3pp. 17679:012. 24X
Fiche: 50-000,83/03/18,8303240406.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT,D.G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000,83/02/24,8302250505.

8303080442 Submits schedule for NRC operator licensing exam site visits through 1985, in response to Generic Ltr 83-01. Exams on 830815-19 for Watts Bar requested to be postponed due to delay in final fuel loading date.
MILLS,L.M. Tennessee Valley Authority. 83/02/28. ADENSAM,E. Licensing Branch 4. 2pp. 17454:256. 24X Fiche: 50-000,83/02/28,8303080442.

DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

A. Application/construction stage documents & correspondence

8303100076 FOIA request for four categories of documents re risks from low trajectory turbine missiles.
HIATT,S.L. Ohio Citizens for Responsible Energy. 82/12/28.
FELTON,J.M. Division of Rules and Records. 1p. 17492:254. 24X
Fiche: 50-440,82/12/28,8303100076.

8303020163 Addl response to FOIA request for four categories of documents re FOIA Request 82-397 & 82-305 facility design differences & meeting re HHS liaison during emergency & potassium iodide use Forwards App A documents W/o encls
FELTON, J M Division of Rules and Records 83/01/25 HIATT, S L
Ohio Citizens for Responsible Energy 2pp 17356:225 24X
Fiche 50-440, 83/01/25, 8303020163

8303100080 Responds to FOIA request for four categories of documents re risks from low trajectory turbine missiles Forwards App A documents Documents partially & completely withheld (ref FOIA Exemptions 4 & 5)
FELTON, J M Division of Rules and Records 83/02/10 HIATT, S L
Ohio Citizens for Responsible Energy 3pp 17492:255 24X
Fiche 50-440, 83/02/10, 8303100080

--8205100335 Informs of unacceptability of SER input re unfavorably oriented turbine in station rescher bldg Simplified turbine generator sys requirements prepared to replace Reg Guide 1 115 & SRP 3 5 1 3, 10 2, 10 2 3
JOHNSTON, W V Assistant Director for Matls & Qualif Engineering (Pre 830201) 82/04/27 TEDESCO, R L Assistant Director for Licensing 4pp 17492:339 24X Fiche 50-440, 83/02/10, 8303100080

--8208050017 Forwards Matls Engineering Branch revised SER input re turbine missiles
JOHNSTON, W V Assistant Director for Matls & Qualif Engineering (Pre 830201) 82/07/26 TEDESCO, R L Assistant Director for Licensing 2pp 17492:345 24X Fiche 50-440, 83/02/10, 8303100080

--8303100092 "Analysis of Low Trajectory Turbine Missile Hazard "
WEISE, K E , WEBB, S W , TATE, J Gilbert/Commonwealth Cos 184P 76/10/08 81pp 17492:258 24X Fiche 50-440, 83/02/10, 8303100080

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492:033 24X
Fiche 50-000, 83/02/16, 8302170082

8303030703 Notification of 830307 meeting w/utils & NUS Corp in Bethesda, MD to discuss proposed rev to 10CFR40 36 (Tech Specs)
BRINKMAN, D S Standardization & Special Projects Branch 83/02/22
THOMAS, C O Standardization & Special Projects Branch 2pp 17363:227 24X Fiche 50-000, 83/02/22, 8303030703

8303230132 Addl response to FOIA request for five categories of documents Forwards SECY-82-87, SECY-82-396 & SECY-82-396A, identified as Item 1 of request
FELTON, J M Division of Rules and Records 83/02/23 HIATT, S L
Ohio Citizens for Responsible Energy 1p 17684:292 24X
Fiche 50-000, 83/02/23, 8303230132

8303100334 Notification of 830310 meeting w/util in Bethesda, MD to discuss plant containment purge design criteria
STEFANO, J J Licensing Branch 1 83/02/24 YOUNGBLOOD, B J
Licensing Branch 1 3pp 17504:072 24X Fiche 50-440, 83/02/24, 8303100334

8303310453 Partial response to FOIA request for six categories of documents Forwards App A documents identified as Items 1, 3, 4, 5 & 6 of request Search for documents re Item 2 of request continuing
FELTON, J M Division of Rules and Records 83/02/24 HIATT, S L
Ohio Citizens for Responsible Energy 2pp 17804:132 24X
Fiche 50-000, 83/02/24, 8303310453

--8303310489 Forwards BNL 821213 memo re degraded core accidents at facilities, per Task III 3 defined in "Design Basis for Hydrogen Control Sys in CP & OL Applications " No-cost extension to contract requested
PRATT, W T Brookhaven National Laboratory FIN A-3389 82/12/20
LONG, J Reactor Systems Branch 19pp 17806:160 24X
Fiche 50-000, 83/02/24, 8303310453

8303110050 Accepts results of Kuosheng nuclear plant safety relief valve discharge tests & sys designs in place of NUREG-0763 requirements for in-plant test Waiver of requirements will be noted in future SER suppl
YOUNGBLOOD, B J Licensing Branch 1 83/03/01 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 17546:247 24X
Fiche 50-440, 83/03/01, 8303110050

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700:303 24X
Fiche 50-000, 83/03/02, 8303020321

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys
KEPPLER, J G Region 3, Office of Director 83/03/03
Commonwealth Edison Co 2pp 17492:014 24X Fiche 50-000, 83/03/03, 8303100364

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12) Svc list encl
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 5lpp 17660:176 24X
Fiche 50-000, 83/03/07, 8303040005

8303240193 Notification of canceled 830321 meeting w/util in Bethesda, MD to discuss estimated const completion dates for facilities
STEFANO, J J Licensing Branch 1 83/03/07 YOUNGBLOOD, B J
Licensing Branch 1 3pp 17696:349 24X Fiche 50-440, 83/03/07, 8303240193

8303250111 Notification of 830321 mgt meeting w/util in Bethesda, MD to discuss estimated const completion dates
STEFANO, J J Licensing Branch 1 83/03/07 YOUNGBLOOD, B J
Licensing Branch 1 3pp 17700:338 24X Fiche 50-440, 83/03/07, 8303250111

8303290789 Forwards response to util 821019 ltr providing clarification & addl info re QA list documented in Amends 8 & 9 of FSAR
YOUNGBLOOD, B J Licensing Branch 1 83/03/07 EDELMAN, M R
Cleveland Electric Illuminating Co 6pp 17748:180 24X
Fiche 50-440, 83/03/07, 8303290789

8303110204 Forwards util press release announcing delay of up to 12 months in projected fuel load date New date might be as late as Dec 1984 Svc list encl
SILBERG, J E Shaw, Pittman, Potts & Trowbridge SILBERG, J E
Cleveland Electric Illuminating Co 83/03/08 BLOCH, P B ,
KLINE, J R , BRIGHT, G O Atomic Safety and Licensing Board Panel
4pp 17513:355 24X Fiche 50-440, 83/03/08, 8303110204

8303290557 Summary of Caseload Forecast Panel 830111-13 meetings w/util at site re projected fuel loading date Latest target date is 831130 Viewgraphs & handouts encl
STEFANO, J Licensing Branch 1 83/03/17 Licensing Branch 1
44pp 17743:240 24X Fiche 50-440, 83/03/17, 8303290557

8303290369 Forwards proprietary & nonproprietary versions of "CLASIX-3 Computer Program for Analysis of Reactor Plant Containment Response to Hydrogen Release & Deflagration " Proprietary version withheld (ref 10CFR2 790)
RICHARDSON, J D Hydrogen Control Owners Group, BWR-6 Mark III
RICHARDSON, J D Mississippi Power & Light Co 83/03/18
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
17726:079 24X Fiche 50-000, 83/03/18, 8303290369

--8303290378 Requests that "CLASIX-3 Computer Program for Analysis of Reactor Plant Containment Response to Hydrogen Release & Deflagration" be withheld from public disclosure Affidavit encl
WIESEMANN, R A Westinghouse Electric Corp 83/01/28 DENTON, H R
Office of Nuclear Reactor Regulation, Director 6pp 17726:081
24X Fiche 50-000, 83/03/18, 8303290369

8303300768 Forwards request for addl info re environ equipment qualification program preparatory to NRC environ site audit Response schedule due in 5 days
YOUNGBLOOD, B J Licensing Branch 1 83/03/23 EDELMAN, M R
Cleveland Electric Illuminating Co 7pp 17765:205 24X
Fiche 50-440, 83/03/23, 8303300768

8303300009 Advises that fuel load date for Unit 1 revised to Dec 1984 Fuel load date for Unit 2 remains May 1987
EDELMAN, M R Cleveland Electric Illuminating Co 83/03/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p
17731:229 24X Fiche 50-440, 83/03/24, 8303300009

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303100080 Responds to FOIA request for four categories of documents re risks from low trajectory turbine missiles Forwards App A documents Documents partially & completely withheld (ref FOIA Exemptions 4 & 5)
FELTON, J M Division of Rules and Records 83/02/10 HIATT, S L
Ohio Citizens for Responsible Energy 3pp 17492:255 24X
Fiche 50-440, 83/02/10, 8303100080

--8303100105 Recommends that evaluation input contained in final draft of SER Suppl 2 be retained.Rept to ACRS should be delayed until Div of Licensing advised of CRGR approval by Div of Engineering.
STEFANO, J. J. Licensing Branch 1 82/12/23 NOVAK, T. M. Assistant Director for Licensing 2pp 17492.343 24X
Fiche: 50-440, 83/02/10, 8303100080

8303170158 Responds to Equipment Qualification Branch 830204 request for addl info re SER Confirmatory Issue 7, "Generic BWR Safety/Relief Valve Operability Test Results" & TMI Action Item II.D.1, "Reliability Engineering."
EDELEMAN, M.R. Cleveland Electric Illuminating Co. 83/03/11
YOUNGBLOOD, B.J. Licensing Branch 1 20pp 17609.059 24X
Fiche: 50-440, 83/03/11, 8303170158

8303170254 Forwards responses to NRC Questions 420.03, 420.05 & 420.06. Questions also identified as SER Open Item 13, "Loss of Non-Class 1E Instrumentation & Control Power Sys Bus During Operation" & 14, "Control Sys Failure."
EDELMAN, M.R. Cleveland Electric Illuminating Co. 83/03/14
YOUNGBLOOD, B.J. Licensing Branch 1 19pp 17606.141 24X
Fiche: 50-440, 83/03/14, 8303170254

8303290801 Requests formal agreement to submit turbine generator sys maint program within 3 yrs of issuance of OL or inspect all low pressure turbine rotors at alternating refueling outages until maint program approved per SER.
YOUNGBLOOD, B.J. Licensing Branch 1 83/03/14 EDELMAN, M.R. Cleveland Electric Illuminating Co 3pp 17748.095 24X
Fiche: 50-440, 83/03/14, 8303290801

8303170087 Requests that intermittent containment purge be permitted up to limit of 4,750 h per yr. Results of re-evaluation of requirements for intermittent containment purge supporting resolution of SER Outstanding Issue 10 encl.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 83/03/15
YOUNGBLOOD, B.J. Licensing Branch 1 3pp 17609.102 24X
Fiche: 50-440, 83/03/15, 8303170087

8303170267 Addresses SER Confirmatory Issue 36 re 3-h fire rating for gypsum walls. Research Five Technology Group of Gold Bond Bldg Products ltr supplying verification of 3-h fire rating encl.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 83/03/15
YOUNGBLOOD, B.J. Licensing Branch 1 5pp 17606.174 24X
Fiche: 50-440, 83/03/15, 8303170267

8303300018 Responds to SER Confirmatory Issue 15 re preservice insp (PSI) program. Previously submitted PSI program plans listed. Rev 1 to "Preservice Insp Program Plan Standby Liquid Control Sys" forwarded.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 83/03/21
YOUNGBLOOD, B.J. Licensing Branch 1 1p 17731.169 24X
Fiche: 50-440, 83/03/21, 8303300018

--8303300025 Rev 1 to "Preservice Insp Program Plan Standby Liquid Control Sys."
AHMED, A. Nuclear Energy Service, Inc. 82/10/0- 19pp
17731.170 24X Fiche: 50-440, 83/03/21, 8303300018

8303310023 Releases public version of rev to emergency plan.
FELTON, J.M. Division of Rules and Records 83/03/28 Document Management Branch 1p 17776.001 24X Fiche: 50-440, 83/03/28, 8303310023

--8303310027 Forwards public version of Rev 1 to Emergency Plan OM-15A, incorporating encl responses to questions in NRC 811221 & 820830 ltrs & addressing SER Outstanding Issue 19.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 83/03/04
YOUNGBLOOD, B. Licensing Branch 1 41pp 17776.002 24X
Fiche: 50-440, 83/03/28, 8303310023

F. Security, medical, emergency & fire protection plans

8303170267 Addresses SER Confirmatory Issue 36 re 3-h fire rating for gypsum walls. Research Five Technology Group of Gold Bond Bldg Products ltr supplying verification of 3-h fire rating encl.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 83/03/15
YOUNGBLOOD, B.J. Licensing Branch 1 5pp 17606.174 24X
Fiche: 50-440, 83/03/15, 8303170267

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J.A. Region 3, Office of Director 83/03/22 Commonwealth Edison Co. 2pp 17690.316 24X Fiche: 50-000, 83/03/22, 8303240440

8303300199 Addresses commitment in util 820506 ltr re automatic fire detection sys recommended by 10CFR50, App R, Item III.F. Justification for not providing automatic detection in areas based on low potential for uncontrolled fire.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 83/03/24
YOUNGBLOOD, B.J. Licensing Branch 1 10pp 17732.270 24X
Fiche: 50-440, 83/03/24, 8303300199

8303310023 Releases public version of rev to emergency plan.
FELTON, J.M. Division of Rules and Records 83/03/28 Document Management Branch 1p 17776.001 24X Fiche: 50-440, 83/03/28, 8303310023

--8303310027 Forwards public version of Rev 1 to Emergency Plan OM-15A, incorporating encl responses to questions in NRC 811221 & 820830 ltrs & addressing SER Outstanding Issue 19.
EDELMAN, M.R. Cleveland Electric Illuminating Co. 83/03/04
YOUNGBLOOD, B. Licensing Branch 1 41pp 17776.002 24X
Fiche: 50-440, 83/03/28, 8303310023

--8303310037 Public version of Rev 1 to Emergency Plan OM-15A.
*. Cleveland Electric Illuminating Co. 83/03/01 406pp
17776.043 24X Fiche: 50-440, 83/03/28, 8303310023

Q. Adjudicatory correspondence

8303100080 Responds to FOIA request for four categories of documents re risks from low trajectory turbine missiles. Forwards App A documents. Documents partially & completely withheld (ref FOIA Exemptions 4 & 5).
FELTON, J.M. Division of Rules and Records 83/02/10 HIATT, S.L. Ohio Citizens for Responsible Energy 3pp 17492.255 24X
Fiche: 50-440, 83/02/10, 8303100080

--8303100113 Forwards response to request from Div of Licensing, Matls Engineering Branch & Div of Engineering, to OH Citizens for Responsible Energy Contention 21 W/o encl.
JOHNSTON, W.V. Assistant Director for Matls & Qualif. Engineering (Pre 830201) 82/12/23 NOVAK, T.M. Assistant Director for Licensing 2pp 17492.347 24X Fiche: 50-440, 83/02/10, 8303100080

8303010076 Requests to make limited appearance statement at OL hearings.
ACTON, R.W. International Brotherhood of Electrical Workers 83/02/18 Docketing & Services Branch 1p 17335.076 24X
Fiche: 50-440, 83/02/18, 8303010076

8303010104 Requests to make limited appearance statement at OL hearings.
SCHOSSLER, M. Affiliation Unknown 83/02/21 Atomic Safety and Licensing Board Panel 1p 17345.034 24X Fiche: 50-440, 83/02/21, 8303010104

8303010100 Requests to make limited appearance statement at OL hearings.
BARNES, W.R. United Assoc. of Journeyman & Apprentices of Plumbing & Pipe Fitters Industry... 83/02/22 Docketing & Services Branch 1p 17335.328 24X Fiche: 50-440, 83/02/22, 8303010100

8303010087 Ninth discovery progress rept, filed per ASLB 810909 memorandum & order. Certificate of Svc encl. Related correspondence.
HIATT, S.L. Ohio Citizens for Responsible Energy 83/02/23 2pp 17335.345 24X Fiche: 50-440, 83/02/23, 8303010087

8303010090 Reply in opposition to applicant 830208 response in support of NRC 830114 motion for summary disposition of Issue 9 re radiation-induced polymer degradation. Certificate of Svc encl. Related correspondence.
HIATT, S.L. Ohio Citizens for Responsible Energy 83/02/23
Atomic Safety and Licensing Board Panel 6pp 17335.339 24X
Fiche: 50-440, 83/02/23, 8303010090

8303010098 Reply in opposition to NRC 830208 motion for 830310 deadline for spec of scenario for Issue 8. Issue should be reworded & action deferred on scenario spec until final rule on Mark III hydrogen control published. Certificate of Svc encl.
HIATT, S.L. Ohio Citizens for Responsible Energy 83/02/23
Atomic Safety and Licensing Board Panel 7pp 17335.330 24X
Fiche: 50-440, 83/02/23, 8303010098

8303010263 Answer to 830131 Interrogatories 9-26 through 9-37 re Issue 14 on in-core thermocouples. Certificate of Svc encl. Related correspondence.
GLASSPIEGEL, H. Cleveland Electric Illuminating Co. GLASSPIEGEL, H. Shaw, Pittman, Potts & Trowbridge 83/02/25 Ohio Citizens for Responsible Energy 18pp 17335.112 24X Fiche: 50-440, 83/02/25, 8303010263

8303010516 Answers to Interrogatories 9-26 through 9-37 re in-core thermocouples (Issue 14). Interrogatory portions re core-exit thermocouples irrelevant & will not be answered. Certificate of Svc encl.
GLASSPIEGEL, H. Commonwealth Edison Co. GLASSPIEGEL, H. Shaw, Pittman, Potts & Trowbridge. 83/02/25. Ohio Citizens for Responsible Energy. 18pp. 17337.193. 24X Fiche. 50-440, 83/02/25, 8303010516.

8303030373 Request to make limited appearance statement at OL hearings.
WALSH, J. F. United Assoc. of Journeyman & Apprentices of Plumbing & Pipe Fitters Industry. 83/02/28. Docketing & Services Branch. 1p. 17410.260. 24X Fiche. 50-440, 83/02/28, 8303030373.

8303020076 Answers to 830131 ninth set of interrogatories. Prof qualifications & Certificate of Svc encl.
CUTCHIN, J. M. Hearing Branch 4. 83/03/01. Ohio Citizens for Responsible Energy. 43pp. 17352.085. 24X Fiche. 50-440, 83/03/01, 8303020076.

8303070068 Response to relevant portion of General Interrogatory 9-52. Svc list encl.
GLASSPIEGEL, H. Cleveland Electric Illuminating Co. GLASSPIEGEL, H. Shaw, Pittman, Potts & Trowbridge. 83/03/03. HIATT, S. Ohio Citizens for Responsible Energy. 4pp. 17435.174. 24X Fiche. 50-440, 83/03/03, 8303070068.

8303070076 Forwards RV Tanney original affidavit to applicant 830225 answer to OH Citizens for Responsible Energy interrogatories. Svc list encl. Related correspondence.
GLASSPIEGEL, H. Shaw, Pittman, Potts & Trowbridge. GLASSPIEGEL, H. Cleveland Electric Illuminating Co. 83/03/03. Docketing & Services Branch. 3pp. 17435.346. 24X Fiche. 50-440, 83/03/03, 8303070076.

8303070091 Memorializes 830302 telcon w/PB Bloch re current status of hydrogen control proposed rule. Issuance of final rule in May 1983 unlikely. Schedule for implementation of rule revised.
CUTCHIN, J. M. Hearing Branch 4. 83/03/03. BLOCH, P. B., BRIGHT, G. O., KLINE, J. P. Atomic Safety and Licensing Board Panel. 2pp. 17435.272. 24X Fiche. 50-440, 83/03/03, 8303070091.

8303070111 Memorandum & order denying NRC 830208 motion to establish deadline by which OH Citizens for Responsible Energy would be required to specify hydrogen generating scenario. Spec unnecessary to assure orderly progress of proceeding.
BLOCH, P. B., KLINE, J. R., BRIGHT, G. O. Atomic Safety and Licensing Board Panel. 83/03/03. Office of the Executive Legal Director. 3pp. 17430.359. 24X Fiche. 50-440, 83/03/03, 8303070111.

8303100392 Requests to make limited appearance statement at OL hearings.
DAVIES, O. Affiliation Unknown. 83/03/03. NRC - No Detailed Affiliation Given. 1p. 17490.337. 24X Fiche. 50-440, 83/03/03, 8303100392.

8303100397 Requests to make limited appearance statement at OL hearings.
SEIDMAN, H. S. Affiliation Unknown. 83/03/05. NRC - No Detailed Affiliation Given. 1p. 17490.338. 24X Fiche. 50-440, 83/03/05, 8303100397.

8303100408 Answers to Interrogatories 9-1 through 9-25 & 9-38 through 9-52 re Issues 13 & 15, from 830131 ninth set of interrogatories. Prof qualifications & Certificate of Svc encl.
SWIGER, M. A. Cleveland Electric Illuminating Co. SWIGER, M. A. Shaw, Pittman, Potts & Trowbridge. 83/03/08. Ohio Citizens for Responsible Energy. 40pp. 17491.294. 24X Fiche. 50-440, 83/03/08, 8303100408.

8303110204 Forwards util press release announcing delay of up to 12 months in projected fuel load date. New date might be as late as Dec 1984. Svc list encl.
SILBERG, J. E. Shaw, Pittman, Potts & Trowbridge. SILBERG, J. E. Cleveland Electric Illuminating Co. 83/03/08. BLOCH, P. B., KLINE, J. R., BRIGHT, G. O. Atomic Safety and Licensing Board Panel. 4pp. 17513.355. 24X Fiche. 50-440, 83/03/08, 8303110204.

8303100138 Response in support of applicant 830218 motion to strike ref to "synergistic effects on polysers" in OH Citizens for Responsible Energy 830207 response to NRC motion for summary disposition of Issue 9. Certificate of Svc encl.
JOHNSON, G. E. Hearing Branch 4. 83/03/09. Atomic Safety and Licensing Board Panel. 8pp. 17485.262. 24X Fiche. 50-440, 83/03/09, 8303100138.

8303170452 Forwards RA Pender & EJ Turk original affidavits to replace copies in util 830308 answers to OH Citizens for Responsible Energy Interrogatories 9-1 through 9-25 & 9-38 through 9-52 re Issues 13 & 15. Svc list encl.
SWIGER, M. A. Shaw, Pittman, Potts & Trowbridge. SWIGER, M. A. Cleveland Electric Illuminating Co. 83/03/11. Docketing & Services Branch. 4pp. 17610.349. 24X Fiche. 50-440, 83/03/11, 8303170452.

8303170275 Requests to make limited appearance statement at OL hearings.
GITLIN, D. Affiliation Unknown. 83/03/14. Docketing & Services Branch. 1p. 17606.053. 24X Fiche. 50-440, 83/03/14, 8303170275.

8303170438 Updated response to applicant 830308 response to Interrogatory 9-1 in 830131 ninth set. Svc list encl.
SWIGER, M. A. Cleveland Electric Illuminating Co. SWIGER, M. A. Shaw, Pittman, Potts & Trowbridge. 83/03/14. HIATT, S. L. Ohio Citizens for Responsible Energy. 3pp. 17610.338. 24X Fiche. 50-440, 83/03/14, 8303170438.

8303170505 Answer opposing OH Citizens for Responsible Energy 830223 motion for rewording of Issue 8 & spec of guidelines for litigation. Motion seeks to frustrate & further delay Issue 8 litigation. Certificate of Svc encl.
SILBERG, J. E. Cleveland Electric Illuminating Co. SILBERG, J. E. Shaw, Pittman, Potts & Trowbridge. 83/03/14. Ohio Citizens for Responsible Energy. 10pp. 17610.209. 24X Fiche. 50-440, 83/03/14, 8303170505.

8303160590 Response opposing OH Citizens for Responsible Energy 830223 motion to reword Issue 8, to defer action on specifying accident scenario until final rule published & to request answers on accident scenario. Certificate of Svc encl.
JOHNSON, G. E. Hearing Branch 4. 83/03/15. Atomic Safety and Licensing Board Panel. 12pp. 17587.067. 24X Fiche. 50-440, 83/03/15, 8303160590.

8303220170 Requests to make limited appearance statement at OL hearings.
PARKER, R. D. Affiliation Unknown. 83/03/16. Docketing & Services Branch. 1p. 17658.156. 24X Fiche. 50-440, 83/03/16, 8303220170.

8303300330 Response to third set of interrogatories & request for production of documents. Certificate of Svc encl. Related correspondence.
HIATT, S. L. Ohio Citizens for Responsible Energy. 83/03/18. Cleveland Electric Illuminating Co. 26pp. 17735.102. 24X Fiche. 50-440, 83/03/18, 8303300330.

8303310286 Memorandum & order granting NRC 830114 motion for summary disposition of portion of polymer degradation question re polymers used for electric insulation. Issue of util insp & maint program of polymers admitted as genuine issue.
BLOCH, P. B., KLINE, J. R., BRIGHT, G. O. Atomic Safety and Licensing Board Panel. 83/03/30. Office of the Executive Legal Director. 19pp. 17756.010. 24X Fiche. 50-440, 83/03/30, 8303310286.

M. Antitrust correspondence

8303140007 Requests advice re DOJ position on need for imposition of civil penalty against util for alleged failure to comply w/antitrust license conditions.
RUTBERG, J. Hearing Branch 2. 83/03/03. CUTLER, M. Justice, Dept. of. 2pp. 17540.123. 24X Fiche. 50-000, 83/03/03, 8303140007.

O. Inspection reports; IE Bulletins & correspondence

8303010028 Final response to FOIA request for documents re labor unions, strikes & const defects, design errors & QA problems involving LK Comstock Co. Forwards G Pirtle 810925 memo. Document partially withheld (ref FOIA Exemption 5).
FELTON, J. M. Division of Rules and Records. 83/01/21. SAWICKI, S. G. News-Herald Willoughby, OH. 1p. 17347.305. 24X Fiche. 50-440, 83/01/21, 8303010028.

--8303010072 Forwards Div of Engineering & Technical Insp inputs for SALP rept except for Matls & Processes Section. Info constituting staff advice, opinions & recommendations deleted.
PIRTLE, G. Division of Engineering & Technical Inspection. 81/09/25. WARNICK, R. Region 3, Chicago. Office of the Director (81/03/01). 12pp. 17347.306. 24X Fiche. 50-440, 83/01/21, 8303010028.

8303080449 Forwards IE Insp Repts 50-440/83-03 & 50-441/83-03 on 830125-28. No noncompliance noted.
KNOP, R. C. Division of Project & Resident Programs. 83/02/18. EDELMAN, M. R. Cleveland Electric Illuminating Co. 2pp. 17453.292. 24X Fiche. 50-440, 83/02/18, 8303080449.

--8303080457 IE Insp Repts 50-440/83-03 & 50-441/83-03 on 830125-28 No noncompliance noted. Major areas inspected: licensee actions on previous insp findings.
PELKE, P. R.; KONKLIN, J. E. Division of Project & Resident Programs 83/02/17 4pp. 17453:294. 24X Fiche. 50-440, 83/02/18, 8303080449

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11pp. 17521:001 24X Fiche. 50-000, 83/02/25, 8212060367.

8303220240 Forwards IE Insp Repts 50-440/83-05 & 50-441/83-05 on 830201-03. No noncompliance noted.
LITTLE, W. S. Region 3, Office of Director 83/03/08 EDELMAN, M. R. Cleveland Electric Illuminating Co. 2pp. 17656:267. 24X Fiche. 50-440, 83/03/08, 8303220240.

--8303220253 IE Insp Repts 50-440/83-05 & 50-441/83-05 on 830201-03. No noncompliance noted. Major areas inspected: action taken on IE bulletins & circulars & actions taken re noncompliances noted in IE Insp Repts 50-440/81-19 & 50-441/81-19.
NAIDU, K. R.; WILLIAMS, C. C. Region 3, Office of Director 83/02/24 9pp. 17656:269. 24X Fiche. 50-440, 83/03/08, 8303220240.

8303240508 Forwards IE Insp Repts 50-440/83-02 & 50-441/83-02 on 830104-07 & 18-21. No noncompliance noted.
LITTLE, W. S. Region 3, Office of Director 83/03/09 EDELMAN, M. R. Cleveland Electric Illuminating Co. 2pp. 17682:233. 24X Fiche. 50-440, 83/03/09, 8303240508.

--8303240517 IE Insp Repts 50-440/83-02 & 50-441/83-02 on 830104-07 & 18-21. No noncompliance noted. Major areas inspected: preservice insp procedure, NDE of personnel certifications & data, previous insp findings & IE bulletins.
WARD, K. D.; GILIMBERG, R. L.; DANIELSON, D. H. Region 3, Office of Director 83/03/07 12pp. 17682:235. 24X Fiche. 50-440, 83/03/09, 8303240508.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070. 24X Fiche. 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche. 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12?pp. 17774:352. 24X Fiche. 50-000, 83/03/21, 8212060387.

8303300018 Responds to SER Confirmatory Issue 15 re preservice insp (PSI) program. Previously submitted PSI program plans listed. Rev 1 to "Preservice Insp Program Plan Standby Liquid Control Sys." forwarded.
EDELMAN, M. R. Cleveland Electric Illuminating Co. 83/03/21
YOUNGBLOOD, B. J. Licensing Branch 1 1p. 17731:169. 24X Fiche. 50-440, 83/03/21, 8303300018.

--8303300025 Rev 1 to "Preservice Insp Program Plan Standby Liquid Control Sys."
AHMED, A. Nuclear Energy Services, Inc. 82/10/06 19pp. 17731:170. 24X Fiche. 50-440, 83/03/21, 8303300018.

5. Reportable occurrences, LERs & related correspondence

8303150620 Board Notification 83-26: forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys. Info may affect conclusions re probability of/corrective measures for ATWS.
EISENHUT, D. G. Division of Licensing 83/03/03 PALLADINO, N. Commissioners 24pp. 17584:097. 24X Fiche. 50-000, 83/03/03, 8303150620.

8303170440 Interim deficiency rept re installation spacing requirements of Hilti Kwik bolts. Initially reported on 830207. Onsite load tests will be conducted in attempt to re-evaluate existing spacing criteria. Next rept expected by 830701.
EDELMAN, M. R. Cleveland Electric Illuminating Co. 83/03/09
KEPPLER, J. G. Region 3, Office of Director 2pp. 17610:358. 24X Fiche. 50-440, 83/03/09, 8303170440.

8303170462 Interim deficiency rept re potential breach of seal integrity associated w/hydrogen igniters supplied by Power Sys. Initially reported on 830207. Igniters returned for rework. Final rept by 830429. Also reported per Part 21.
EDELMAN, M. R. Cleveland Electric Illuminating Co. 83/03/09
KEPPLER, J. G. Region 3, Office of Director 2pp. 17609:211. 24X Fiche. 50-440, 83/03/09, 8303170462.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche. 50-000, 83/02/24, 8302250505.

DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8303100076 FOIA request for four categories of documents re risks from low trajectory turbine missiles.
HIATT, S. L. Ohio Citizens for Responsible Energy 82/12/28
FELTON, J. M. Division of Rules and Records 1p. 17492:254. 24X Fiche. 50-440, 82/12/28, 8303100076.

8303020163 Addl response to FOIA request for four categories of documents re FOIA Request 82-397 & 82-305, facility design differences & meeting re HHS liaison during emergency & potassium iodide use. Forwards App A documents. W/o encls.
FELTON, J. M. Division of Rules and Records 83/01/25 HIATT, S. Ohio Citizens for Responsible Energy 2pp. 17356:225. 24X Fiche. 50-440, 83/01/25, 8303020163.

8303100080 Responds to FOIA request for four categories of documents re risks from low trajectory turbine missiles. Forwards App A documents. Documents partially & completely withheld (ref FOIA Exemptions 4 & 5).
FELTON, J. M. Division of Rules and Records 83/02/10 HIATT, S. L. Ohio Citizens for Responsible Energy 3pp. 17492:255. 24X Fiche. 50-440, 83/02/10, 8303100080.

--8205100335 Informs of unacceptability of SER input re unfavorably oriented turbine in station reacher bldg. Simplified turbine generator sys requirements prepared to replace Reg Guide 1.115 & SRP 3.5.1.3, 10.2, 10.2.3.
JOHNSTON, W. V. Assistant Director for Matls & Qualif Engineering (Pre 830201) 82/04/27 TEDESCO, R. L. Assistant Director for Licensing 4pp. 17492:339. 24X Fiche. 50-440, 83/02/10, 8303100080.

--8208050017 Forwards Matls Engineering Branch revised SER input re turbine missiles.
JOHNSTON, W. V. Assistant Director for Matls & Qualif Engineering (Pre 830201) 82/07/26 TEDESCO, R. L. Assistant Director for Licensing 2pp. 17492:345. 24X Fiche. 50-440, 83/02/10, 8303100080.

--8303100092 "Analysis of Low Trajectory Turbine Missile Hazard." WEISE, K. E.; WEBB, S. W.; TATE, J. Gilbert/Commonwealth Cos. 1848. 76/10/00 81pp. 17492:258. 24X Fiche. 50-440, 83/02/10, 8303100080.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche. 50-000, 83/02/16, 8302170082.

8303030703 Notification of 830307 meeting w/utils & NUS Corp in Bethesda, MD to discuss proposed rev to 10CFR40, Ap. (Tech Specs).
BRINKMAN, D. S. Standardization & Special Projects Branch 83/02/22
THOMAS, C. O. Standardization & Special Projects Branch 2pp. 17363:227. 24X Fiche. 50-000, 83/02/22, 8303030703.

8303230132 Addl response to FOIA request for five categories of documents. Forwards SECY-82-87, SECY-82-396 & SECY-82-396A, identified as Item 1 of request.
FELTON, J. M. Division of Rules and Records 83/02/23 HIATT, S. L. Ohio Citizens for Responsible Energy 1p. 17684:292. 24X Fiche. 50-000, 83/02/23, 8303230132.

8303100334 Notification of 830310 meeting w/util in Bethesda, MD to discuss plant containment purge design criteria.
STEFANO, J. J. Licensing Branch 1 83/02/24 YOUNGBLOOD, B. J. Licensing Branch 1 3pp. 17504:072. 24X Fiche. 50-440, 83/02/24, 8303100334.

8303310453 Partial response to FOIA request for six categories of documents Forwards App A documents identified as Items 1, 3, 4, 5 & 6 of request Search for document, re Item 2 of request continuing.
FELTON, J M Division of Rules and Records 83/02/24 HIATT, S L Ohio Citizens for Responsible Energy 2pp 17804 132 24X
Fiche 50-000, 83/02/24, 8303310453

--8303310489 Forwards BNL 821213 memeo re degraded core accidents at facilities, per Task III 3 defined in "Design Basis for Hydrogen Control Sys in CP & OL Applications." No-cost extension to contract requested.
PRATT, W T Brookhaven National Laboratory FIN A-3389 82/12/20
LONG, J Reactor Systems Branch 19pp 17806 160 24X
Fiche 50-000, 83/02/24, 8303310453

8303110050 Accepts results of Kuosheng nuclear plant safety relief valve discharge tests & sys designs in place of NUREG-0763 requirements for in-plant test Waiver of requirements will be noted in future SER suppl.
YOUNGBLOOD, B J Licensing Branch 1 83/03/01 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 17546 247 24X
Fiche 50-440, 83/03/01, 8303110050

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl.
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X
Fiche 50-000, 83/03/02, 8303020321

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J G Region 3, Office of Director 83/03/03
Commonwealth Edison Co 2pp 17492 014 24X Fiche 50-000, 83/03/03, 8303100364

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 51pp 17660 176 24X
Fiche 50-000, 83/03/07, 8303040005

8303240193 Notification of canceled 830321 meeting w/util in Bethesda, MD to discuss estimated const completion dates for facilities.
STEFANO, J J Licensing Branch 1 83/03/07 YOUNGBLOOD, B J Licensing Branch 1 3pp 17696 349 24X Fiche 50-440, 83/03/07, 8303240193

8303250111 Notification of 830321 mgt meeting w/util in Bethesda, MD to discuss estimated const completion dates.
STEFANO, J J Licensing Branch 1 83/03/07 YOUNGBLOOD, B J Licensing Branch 1 3pp 17700 338 24X Fiche 50-440, 83/03/07, 8303250111

8303290789 Forwards response to util 821019 ltr providing clarification & addl info re SA list documented in Amends 8 & 9 of FSAR.
YOUNGBLOOD, B J Licensing Branch 1 83/03/07 EDELMAN, M R Cleveland Electric Illuminating Co 6pp 17748 180 24X
Fiche 50-440, 83/03/07, 8303290789

8303110204 Forwards util press release announcing delay of up to 12 months in projected fuel load date New date might be as late as Dec 1984 Svc list encl.
SILBERG, J E Shaw, Pittman, Potts & Trowbridge 83/03/08
BLOCH, P B Atomic Safety and Licensing Board Panel 4pp 17513 355 24X Fiche 50-440, 83/03/08, 8303110204

8303290557 Summary of Caseload Forecast Panel 830111-13 meetings w/util at site re projected fuel loading date Latest target date is 831130. Viewgraphs & handouts encl.
STEFANO, J Licensing Branch 1 83/03/17 Licensing Branch 1 44pp 17743 240 24X Fiche 50-440, 83/03/17, 8303290557

8303290369 Forwards proprietary & nonproprietary versions of "CLASIX-3 Computer Program for Analysis of Reactor Plant Containment Response to Hydrogen Release & Deflagration." Proprietary version withheld (ref 10CFR2.790).
RICHARDSON, J D Hydrogen Control Owners Group, BWR-6 Mark III 83/03/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17726 079 24X Fiche 50-000, 83/03/18, 8303290369

--8303290378 Requests that "CLASIX-3 Computer Program for Analysis of Reactor Plant Containment Response to Hydrogen Release & Deflagration" be withheld from public disclosure Affidavit encl.
WIESEMANN, R A Westinghouse Electric Corp 83/01/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 17726 081 24X Fiche 50-000, 83/03/18, 8303290369

8303300768 Forwards request for addl info re environ equipment qualification program preparatory to NRC environ site audit. Response schedule due in 5 days.
YOUNGBLOOD, B J Licensing Branch 1 83/03/23 EDELMAN, M R Cleveland Electric Illuminating Co 7pp 17765 205 24X
Fiche 50-440, 83/03/23, 8303300768

8303300009 Advises that fuel load date for Unit 1 revised to Dec 1984. Fuel load date for Unit 2 remains May 1987.
EDELMAN, M R Cleveland Electric Illuminating Co 83/03/24
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17731 229 24X Fiche 50-440, 83/03/24, 8303300009

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303100080 Responds to FOIA request for four categories of documents re risks from low trajectory turbine missiles Forwards App A documents Documents partially & completely withheld (ref FOIA Exemptions 4 & 5).
FELTON, J M Division of Rules and Records 83/02/10 HIATT, S L Ohio Citizens for Responsible Energy 3pp 17492 255 24X
Fiche 50-440, 83/02/10, 8303100080

--8303100105 Recommends that evaluation input contained in final draft of SER Suppl 2 be retained Rept to ACRS should be delayed until Div of Licensing advised of CRGR approval by Div of Engineering.
STEFANO, J J Licensing Branch 1 82/12/23 NOVAK, T M Assistant Director for Licensing 2pp 17492 343 24X
Fiche 50-440, 83/02/10, 8303100080

8303170158 Responds to Equipment Qualification Branch 830204 request for addl info re SER Confirmatory Issue 7, "Generic BWR Safety/Relief Valve Operability Test Results" & TMI Action Item II D 1, "Reliability Engineering."
EDELEMAN, M R Cleveland Electric Illuminating Co 83/03/11
YOUNGBLOOD, B J Licensing Branch 1 20pp 17609 059 24X
Fiche 50-440, 83/03/11, 8303170158

8303170254 Forwards responses to NRC Questions 420.03, 420.05 & 420.06 Questions also identified as SER Open Item 13, "Loss of Non-Class 1E Instrumentation & Control Power Sys Bus During Operation" & 14, "Control Sys Failure."
EDELMAN, M R Cleveland Electric Illuminating Co 83/03/14
YOUNGBLOOD, B J Licensing Branch 1 19pp 17606 141 24X
Fiche 50-440, 83/03/14, 8303170254

8303290801 Requests formal agreement to submit turbine generator sys maint program within 3 yrs of issuance of OL or inspect all low pressure turbine rotors at alternating refueling outages until maint program approved, per SER.
YOUNGBLOOD, B J Licensing Branch 1 83/03/14 EDELMAN, M R Cleveland Electric Illuminating Co 3pp 17748 095 24X
Fiche 50-440, 83/03/14, 8303290801

8303170087 Requests that intermittent containment purge be permitted up to limit of 4,750 h per yr Results of re-evaluation of requirements for intermittent containment purge supporting resolution of SER Outstanding Issue 10 encl.
EDELMAN, M R Cleveland Electric Illuminating Co 83/03/15
YOUNGBLOOD, B J Licensing Branch 1 3pp 17609 102 24X
Fiche 50-440, 83/03/15, 8303170087

8303170267 Addresses SER Confirmatory Issue 36 re 3-h fire rating for gypsum walls Research Five Technology Group of Gold Bond Bldg Products ltr supplying verification of 3-h fire rating encl.
EDELMAN, M R Cleveland Electric Illuminating Co 83/03/15
YOUNGBLOOD, B J Licensing Branch 1 3pp 17606 174 24X
Fiche 50-440, 83/03/15, 8303170267

8303300018 Responds to SER Confirmatory Issue 15 re preservice insp (PSI) program Previously submitted PSI program plans listed. Rev 1 to "Preservice Insp Program Plan Standby Liquid Control Sys" forwarded.
EDELMAN, M R Cleveland Electric Illuminating Co 83/03/21
YOUNGBLOOD, B J Licensing Branch 1 1p 17731 169 24X
Fiche 50-440, 83/03/21, 8303300018

8303310023 Releases public version of rev to emergency plan.
FELTON, J M Division of Rules and Records 83/03/28 Document Management Branch 1p 17776 001 24X Fiche 50-440, 83/03/28, 8303310023

--8303310027 Forwards public version of Rev 1 to Emergency Plan OM-15A, incorporating encl responses to questions in NRC 811221 & 820830 ltrs & addressing SER Outstanding Issue 19.
EDELMAN, M R Cleveland Electric Illuminating Co 83/03/04
YOUNGBLOOD, B Licensing Branch 1 41pp 17776 002 24X
Fiche 50-440, 83/03/28, 8303310023

F. Security, medical, emergency & fire protection plans

8303170267 Addresses SER Confirmatory Issue 36 re 3-h fire rating for gypsum walls Research Five Technology Group of Gold Bond Bldg Products ltr supplying verification of 3-h fire rating encl
EDELMAN, M R Cleveland Electric Illuminating Co 83/03/15
YOUNGBLOOD, B J Licensing Branch 1 5pp 17606:174 24X
Fiche 50-440, 83/03/15, 8303170267

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition Appropriate planning should take place to prevent possible transmission errors
HINO, J A Region 3, Office of Director 83/03/22 Commonwealth Edison Co 2pp 17690:316 24X Fiche 50-000, 83/03/22, 8303240440

8303300199 Addresses commitment in util 820906 ltr re automatic fire detection sys recommended by 10CFR50, App R, Item III F Justification for not providing automatic detection in areas based on low potential for uncontrolled fire
EDELMAN, M R Cleveland Electric Illuminating Co 83/03/24
YOUNGBLOOD, B J Licensing Branch 1 10pp 17732:270 24X
Fiche 50-440, 83/03/24, 8303300199

8303310023 Releases public version of rev to emergency plan
FELTON, J M Division of Rules and Records 83/03/28 Document Management Branch 1p 17776:001 24X Fiche 50-440, 83/03/28, 8303310023

--8303310027 Forwards public version of Rev 1 to Emergency Plan OM-15A, incorporating encl responses to questions in NRC 811221 & 820830 ltrs & addressing SER Outstanding Issue 19
EDELMAN, M R Cleveland Electric Illuminating Co 83/03/04
YOUNGBLOOD, B Licensing Branch 1 41pp 17776:002 24X
Fiche 50-440, 83/03/28, 8303310023

--8303310037 Public version of Rev 1 to Emergency Plan OM-15A
* Cleveland Electric Illuminating Co 83/03/01 40app
17776:043 24X Fiche 50-440, 83/03/28, 8303310023

Q. Adjudicatory correspondence

8303100080 Responds to FOIA request for four categories of documents re risks from low trajectory turbine missiles Forwards App A documents Documents partially & completely withheld (ref FOIA Exemptions 4 & 5)
FELTON, J M Division of Rules and Records 83/02/10 HIATT, S L Ohio Citizens for Responsible Energy 3pp 17492:255 24X
Fiche 50-440, 83/02/10, 8303100080

--8303100113 Forwards response to request from Div of Licensing, Matls Engineering Branch & Div of Engineering, to OH Citizens for Responsible Energy Contention 21 W/o encl
JOHNSTON, W V Assistant Director for Matls & Qualif Engineering (Pre 830201) 82/12/23 NOVAK, T M Assistant Director for Licensing 2pp 17492:347 24X Fiche 50-440, 83/02/10, 8303100080

8303010076 Requests to make limited appearance statement at OL hearings
ACTON, R W International Brotherhood of Electrical Workers 83/02/18 Docketing & Services Branch 1p 17335:076 24X
Fiche 50-440, 83/02/18, 8303010076

8303010104 Requests to make limited appearance statement at OL hearings
SCHOSSLER, M Affiliation Unknown 83/02/21 Atomic Safety and Licensing Board Panel 1p 17345:034 24X Fiche 50-440, 83/02/21, 8303010104

8303010100 Requests to make limited appearance statement at OL hearings
BARNES, W R United Assoc of Journeyman & Apprentices of Plumbing & Pipe Fitters Industry 83/02/22 Docketing & Services Branch 1p 17335:328 24X Fiche 50-440, 83/02/22, 8303010100

8303010087 Ninth discovery progress rept, filed per ASLB 810909 memorandum & order Certificate of Svc encl Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 83/02/23 2pp 17335:343 24X Fiche 50-440, 83/02/23, 8303010087

8303010090 Reply in opposition to applicant 830208 response in support of NRC 830114 motion for summary disposition of Issue 9 re radiation-induced polymer degradation Certificate of Svc encl Related correspondence
HIATT, S L Ohio Citizens for Responsible Energy 83/02/23
Atomic Safety and Licensing Board Panel 6pp 17335:339 24X
Fiche 50-440, 83/02/23, 8303010090

8303010098 Reply in opposition to NRC 830208 motion for 830310 deadline for spec of scenario for Issue 8 Issue should be reworded & action deferred on scenario spec until final rule on Mark III hydrogen control published Certificate of Svc encl
HIATT, S L Ohio Citizens for Responsible Energy 83/02/23
Atomic Safety and Licensing Board Panel 7pp 17335:330 24X
Fiche 50-440, 83/02/23, 8303010098

8303010263 Answer to 830131 interrogatories 9-26 through 9-37 re Issue 14 on in-core thermocouples Certificate of Svc encl Related correspondence
GLASSPIEGEL, H Cleveland Electric Illuminating Co GLASSPIEGEL, H Shaw, Pittman, Potts & Trowbridge 83/02/25 Ohio Citizens for Responsible Energy 18pp 17335:112 24X Fiche 50-440, 83/02/25, 8303010263

8303010516 Answers to Interrogatories 9-26 through 9-37 re in-core thermocouples (Issue 14) Interrogatory portions re core-exit thermocouples irrelevant & will not be answered Certificate of Svc encl
GLASSPIEGEL, H Commonwealth Edison Co GLASSPIEGEL, H Shaw, Pittman, Potts & Trowbridge 83/02/25 Ohio Citizens for Responsible Energy 18pp 17337:193 24X Fiche 50-440, 83/02/25, 8303010516

8303030373 Request to make limited appearance statement at OL hearings
WALSH, J F United Assoc of Journeyman & Apprentices of Plumbing & Pipe Fitters Industry 83/02/28 Docketing & Services Branch 1p 17410:260 24X Fiche 50-440, 83/02/28, 8303030373

8303020076 Answers to 830131 ninth set of interrogatories Prof qualifications & Certificate of Svc encl
CUTCHIN, J M Hearing Branch 4 83/03/01 Ohio Citizens for Responsible Energy 43pp 17352:085 24X Fiche 50-440, 83/03/01, 8303020076

8303070068 Response to relevant portion of General Interrogatory 9-52 Svc list encl
GLASSPIEGEL, H Cleveland Electric Illuminating Co GLASSPIEGEL, H Shaw, Pittman, Potts & Trowbridge 83/03/03 HIATT, S Ohio Citizens for Responsible Energy 4pp 17435:174 24X
Fiche 50-440, 83/03/03, 8303070068

8303070076 Forwards RV Tanney original affidavit to applicant 830225 answer to OH Citizens for Responsible Energy interrogatories Svc list encl Related correspondence
GLASSPIEGEL, H Shaw, Pittman, Potts & Trowbridge GLASSPIEGEL, H Cleveland Electric Illuminating Co 83/03/03 Docketing & Services Branch 3pp 17435:346 24X Fiche 50-440, 83/03/03, 8303070076

8303070091 Memorializes 830302 telcon w/PB Bloch re current status of hydrogen control proposed rule Issuance of final rule in May 1983 unlikely Schedule for implementation of rule revised
CUTCHIN, J M Hearing Branch 4 83/03/03 BLOCH, P B , BRIGHT, G O , KLINE, J P Atomic Safety and Licensing Board Panel 2pp
17435:272 24X Fiche 50-440, 83/03/03, 8303070091

8303070111 Memorandum & order denying NRC 830208 motion to establish deadline by which OH Citizens for Responsible Energy would be required to specify hydrogen generating scenario Spec unnecessary to assure orderly progress of proceeding
BLOCH, P B , KLINE, J R , BRIGHT, G O Atomic Safety and Licensing Board Panel 83/03/03 Office of the Executive Legal Director 3pp 17430:359 24X Fiche 50-440, 83/03/03, 8303070111

8303100392 Requests to make limited appearance statement at OL hearings
DAVIES, D Affiliation Unknown 83/03/03 NRC - No Detailed Affiliation Given 1p 17490:337 24X Fiche 50-440, 83/03/03, 8303100392

8303100397 Requests to make limited appearance statement at OL hearings
SEIDMAN, H S Affiliation Unknown 83/03/05 NRC - No Detailed Affiliation Given 1p 17490:338 24X Fiche 50-440, 83/03/05, 8303100397

8303100408 Answers to Interrogatories 9-1 through 9-25 & 9-38 through 9-52 re Issues 13 & 15, from 830131 ninth set of interrogatories Prof qualifications & Certificate of Svc encl
SWIGER, M A Cleveland Electric Illuminating Co SWIGER, M A Shaw, Pittman, Potts & Trowbridge 83/03/08 Ohio Citizens for Responsible Energy 40pp 17491:294 24X Fiche 50-440, 83/03/08, 8303100408

8303110204 Forwards util press release announcing delay of up to 12 months in projected fuel load date. New date might be as late as Dec 1984. Svc list encl.
SILBERG, J. E. Shaw, Pittman, Potts & Trowbridge. SILBERG, J. E.
Cleveland Electric Illuminating Co. 83/03/08. BLOCH, P. B. ,
KLINE, J. R. , BRIGHT, G. O. Atomic Safety and Licensing Board Panel.
4pp. 17513:355. 24X Fiche. 50-440, 83/03/08, 8303110204.

8303100138 Response in support of applicant 830218 motion to strike ref to "synergistic effects on polymers" in OH Citizens for Responsible Energy 830207 response to NRC motion for summary disposition of Issue 9. Certificate of Svc encl.
JOHNSON, G. E. Hearing Branch 4. 83/03/09. Atomic Safety and Licensing Board Panel. 8pp. 17485:262. 24X Fiche. 50-440, 83/03/09, 8303100138.

8303170452 Forwards RA Pender & EJ Turk original affidavits to replace copies in util 830308 answers to OH Citizens for Responsible Energy Interrogatories 9-1 through 9-25 & 9-38 through 9-52 re Issues 13 & 15. Svc list encl.
SWIGER, M. A. Shaw, Pittman, Potts & Trowbridge. SWIGER, M. A.
Cleveland Electric Illuminating Co. 83/03/11. Docketing & Services Branch. 4pp. 17610:349. 24X Fiche. 50-440, 83/03/11, 8303170452.

8303170275 Requests to make limited appearance statement at OL hearings.
GITLIN, D. Affiliation Unknown. 83/03/14. Docketing & Services Branch. 1p. 17606:053. 24X Fiche. 50-440, 83/03/14, 8303170275.

8303170438 Updated response to applicant 830308 response to Interrogatory 9-1 in 830131 ninth set. Svc list encl.
SWIGER, M. A. Cleveland Electric Illuminating Co. SWIGER, M. A. Shaw, Pittman, Potts & Trowbridge. 83/03/14. HIATT, S. L. Ohio Citizens for Responsible Energy. 3pp. 17610:336. 24X Fiche. 50-440, 83/03/14, 8303170438.

8303170505 Answer opposing OH Citizens for Responsible Energy 830223 motion for rewording of Issue 8 & spec of guidelines for litigation. Motion seeks to frustrate & further delay Issue 8 litigation. Certificate of Svc encl.
SILBERG, J. E. Cleveland Electric Illuminating Co. SILBERG, J. E.
Shaw, Pittman, Potts & Trowbridge. 83/03/14. Ohio Citizens for Responsible Energy. 10pp. 17610:209. 24X Fiche. 50-440, 83/03/14, 8303170505.

8303160590 Response opposing OH Citizens for Responsible Energy 830223 motion to reword Issue 8, to defer action on specifying accident scenario until final rule published & to request answers on accident scenario. Certificate of Svc encl.
JOHNSON, G. E. Hearing Branch 4. 83/03/15. Atomic Safety and Licensing Board Panel. 12pp. 17587:067. 24X Fiche. 50-440, 83/03/15, 8303160590.

8303220170 Requests to make limited appearance statement at OL hearings.
PARKER, R. D. Affiliation Unknown. 83/03/16. Docketing & Services Branch. 1p. 17658:156. 24X Fiche. 50-440, 83/03/16, 8303220170.

8303300330 Response to third set of interrogatories & request for production of documents. Certificate of Svc encl. Related correspondence.
HIATT, S. L. Ohio Citizens for Responsible Energy. 83/03/18.
Cleveland Electric Illuminating Co. 26pp. 17735:102. 24X
Fiche. 50-440, 83/03/18, 8303300330.

8303310286 Memorandum & order granting NRC 830114 motion for summary disposition of portion of polymer degradation question re polymers used for electric insulation. Issue of util insp & maint program of polymers admitted as genuine issue.
BLOCH, P. B. , KLINE, J. R. , BRIGHT, G. O. Atomic Safety and Licensing Board Panel. 83/03/30. Office of the Executive Legal Director. 19pp. 17756:010. 24X Fiche. 50-440, 83/03/30, 8303310286.

## M. Antitrust correspondence

8303140007 Requests advice re DOJ position on need for imposition of civil penalty against util for alleged failure to comply w/antitrust license conditions.
RUTBERG, J. Hearing Branch 2. 83/03/03. CUTLER, M. Justice, Dept of. 2pp. 17540:123. 24X Fiche. 50-000, 83/03/03, 8303140007.

## Q. Inspection reports, IE Bulletins & correspondence

8303010028 Final response to FOIA request for documents re labor unions, strikes & const defects, design errors & QA problems involving LR Comstock Co. Forwards G Pirtle 810925 memo. Document partially withheld (ref FOIA Exemption 5).
FELTON, J. M. Division of Rules and Records. 83/01/21. SAWICKI, S. G.
News-Herald Willoughby, OH. 1p. 17347:305. 24X
Fiche. 50-440, 83/01/21, 8303010028.

--8303010072 Forwards Div of Engineering & Technical Insp inputs for SALP rept except for Matls & Processes Section. Info constituting staff advice, opinions & recommendations deleted.
PIRTLE, G. Division of Engineering & Technical Inspection.
81/09/25. WARNICK, R. Region 3, Chicago, Office of the Director (81/03/01). 12pp. 17347:306. 24X Fiche. 50-440, 83/01/21, 8303010028.

8303080449 Forwards IE Insp Repts 50-440/83-03 & 50-441/83-03 on 830125-28. No noncompliance noted.
KNOP, R. C. Division of Project & Resident Programs. 83/02/18.
EDELMAN, M. R. Cleveland Electric Illuminating Co. 2pp. 17453:292.
24X Fiche. 50-440, 83/02/18, 8303080449.

--8303080457 IE Insp Repts 50-440/83-03 & 50-441/83-03 on 830125-28. No noncompliance noted. Major areas inspected: licensee actions on previous insp findings.
PELKE, P. R. , KONKLIN, J. E. Division of Project & Resident Programs.
83/02/17. 4pp. 17453:294. 24X Fiche. 50-440, 83/02/18, 8303080449.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc.
111pp. 17521:001. 24X Fiche. 50-000, 83/02/25, 8212060367.

8303220240 Forwards IE Insp Repts 50-440/83-05 & 50-441/83-05 on 830201-03. No noncompliance noted.
LITTLE, W. S. Region 3, Office of Director. 83/03/08. EDELMAN, M. R.
Cleveland Electric Illuminating Co. 2pp. 17656:267. 24X
Fiche. 50-440, 83/03/08, 8303220240.

--8303220253 IE Insp Repts 50-440/83-05 & 50-441/83-05 on 830201-03. No noncompliance noted. Major areas inspected: action taken on IE bulletins & circulars & actions taken re noncompliances noted in IE Insp Repts 50-440/81-19 & 50-441/81-19.
NAIDU, K. R. , WILLIAMS, C. C. Region 3, Office of Director. 83/02/24.
9pp. 17656:269. 24X Fiche. 50-440, 83/03/08, 8303220240.

8303240508 Forwards IE Insp Repts 50-440/83-02 & 50-441/83-02 on 830104-07 & 18-21. No noncompliance noted.
LITTLE, W. S. Region 3, Office of Director. 83/03/09. EDELMAN, M. R.
Cleveland Electric Illuminating Co. 2pp. 17682:233. 24X
Fiche. 50-440, 83/03/09, 8303240508.

--8303240517 IE Insp Repts 50-440/83-02 & 50-441/83-02 on 830104-07 & 18-21. No noncompliance noted. Major areas inspected: preservice insp procedure, NDE of personnel certifications & data, previous insp findings & IE bulletins.
WARD, K. D. , CILIMBERG, R. L. , DANIELSON, D. H. Region 3, Office of
Director. 83/03/07. 12pp. 17682:235. 24X Fiche. 50-440, 83/03/09,
8303240508.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and
Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc.
117pp. 17611:070. 24X Fiche. 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/03/18. Consolidated Edison Co. of New
York, Inc. 117pp. 24X Fiche. 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/03/21. Consolidated Edison Co. of New
York, Inc. 121pp. 17774:352. 24X Fiche. 50-000, 83/03/21, 8212060387.

8303300018 Responds to SER Confirmatory Issue 15 re preservice insp (PSI) program. Previously submitted PSI program plans listed. Rev 1 to "Preservice Insp Program Plan: Standby Liquid Control Sys" forwarded.
EDELMAN, M. R. Cleveland Electric Illuminating Co. 83/03/21.
YOUNGBLOOD, B. J. Licensing Branch 1. 1p. 17731:169. 24X
Fiche. 50-440, 83/03/21, 8303300018.

--8303300025 Rev 1 to "Preservice Insp Program Plan: Standby Liquid Control Sys."
AHMED, A. Nuclear Energy Service, Inc. 82/10/06. 19pp.
17731:170. 24X Fiche. 50-440, 83/03/21, 8303300018.

S. Reportable occurrences, LERs & related correspondence

8303150620 Board Notification 83-26 forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys Info may affect conclusions re probability of/corrective measures for ATWS.
EISENHUT, D G Division of Licensing 83/03/03 PALLADINO, N Commissioners 24pp 17584 097 24X Fiche 50-000, 83/03/03, 8303150620

83031/0440 Interim deficiency rept re installation spacing requirements of Hilti Kwik bolts Initially reported on 830207 Onsite load tests will be conducted in attempt to re-evaluate existing spacing criteria Next rept expected by 830701
EDELMAN, M R Cleveland Electric Illuminating Co 83/03/09
KEPPLER, J G Region 3, Office of Director 2pp 17610 358 24X
Fiche 50-440, 83/03/09, 8303170440

8303170462 Interim deficiency rept re potential breach of seal integrity associated w/hydrogen igniters supplied by Power Sys Initially reported on 830207 Igniters returned for rework Final rept by 830429 Also reported per Part 21
EDELMAN, M R Cleveland Electric Illuminating Co 83/03/09
KEPPLER, J G Region 3, Office of Director 2pp 17609 211 24X
Fiche 50-440, 83/03/09, 8303170462

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000, 83/02/24, 8302250505

DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24X
Fiche 50-000, 83/02/16, 8302170082

8303010409 Forwards technical justification for not installing gross radioactivity monitor in svc water sys in response to Effluent Treatment Sys Branch open item Encl revised FSAR Page 9.2-4 will be incorporated in OL application Amend 49
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/02/24 KNIGHTON, G W Licensing Branch 3 4pp 17346 228 24X Fiche 50-443, 83/02/24, 8303010409

8303010533 Forwards response to open item re single failure assumptions for Condition II events Info will be incorporated in OL Application Amend 49
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/02/24 KNIGHTON, G W Licensing Branch 3 9pp 17343 026 24X Fiche 50-443, 83/02/24, 8303010533

8303020083 Forwards revised response to NRC Request for Addl Info 440.27 re hydrogen control in radioactive gaseous waste sys cubicles Revised response will be incorporated in OL application Amend 49
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/02/25 KNIGHTON, G W Licensing Branch 3 3pp 17352 131 24X Fiche 50-443, 83/02/25, 8303020083

8303020085 Clarifies util position on Request for Addl Info 440.133 re compliance w/Branch Technical Position RSB 5-1, "Design Requirements of RHR Sys." Pressurizer heaters not required to bring reactor to cold shutdown condition
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/02/25 KNIGHTON, G W Licensing Branch 3 2pp 17352 134 24X Fiche 50-443, 83/02/25, 8303020085

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X
Fiche 50-000, 83/03/02, 8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12) Svc list encl
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 5pp 17660 176 24X
Fiche 50-000, 83/03/07, 8303040005

8303150207 Summarizes 830224 meeting w/Region 1 re verification programs which assure FSAR program & engineering criteria are translated into const & insp documents & are implemented
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/03/07 KNIGHTON, G W Licensing Branch 3 5pp 17555 163 24X Fiche 50-443, 83/03/07, 8303150207

8303230308 Discusses fuel load date Data provided to NRC Caseload Forecast Panel (CFP) under re-evaluation Util representatives invited to meet w/NRC on 830408 to discuss possible revs due to re-evaluation
KNIGHTON, G W Licensing Branch 3 83/03/09 HARRISON, R J Public Service Co of New Hampshire 2pp 17686 177 24X
Fiche 50-443, 83/03/09, 8303230308

8303150195 Forwards "Pressure Boundary Calculations of Horizontal Pumps," in response to request for addl info re containment spray pumps OL application Amend 49 will ref encl rept Svc list encl
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/03/10 KNIGHTON, G W Licensing Branch 3 2pp 17549 021 24X Fiche 50-443, 83/03/10, 8303150195

--8303150202 "Pressure Boundary Calculations of Horizontal Pumps."
MCDONALD, C K McDonald Engineering Analysis Co., Inc 83/02/09
19pp 17549 023 24X Fiche 50-443, 83/03/10, 8303150195

8303150436 Forwards response to request for addl info re postulated failure of nonseismic portion of svc water sys Response revises previously submitted meeting notes & will be incorporated in Amend 49 to OL application
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/03/10 KNIGHTON, G W Licensing Branch 3 5pp 17562 279 24X Fiche 50-443, 83/03/10, 8303150436

8303170441 Responds to Meteorological & Effluent Treatment Sys Branch Request for Addl Info 460.35 re turbine gland steam condenser exhaust Radiation monitor need not be installed in turbine steam gland condenser vent
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/03/10 KNIGHTON, G W Licensing Branch 3 3pp 17609 264 24X Fiche 50-443, 83/03/10, 8303170441

8303170358 Confirms 830311 telcon re pressure transmitter location/qualification Transmitters RC PT 403 & 405 located outside containment & will be fully qualified for specific environ per NUREG-0588
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/03/15 KNIGHTON, G W Licensing Branch 3 2pp 17605 181 24X Fiche 50-443, 83/03/15, 8303170358

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303090631 Advises that mgt review of SER Section 13.6, physical security plan & Section 16, Tech Specs, has been completed & found acceptable
MIRAGLIA, F J Assistant Director for Safety Assessment 83/03/02
NOVAK, T M Assistant Director for Licensing 1p 17480 285 24X
Fiche 50-443, 83/03/02, 8303090631

8303150331 Informs of commitment to qualify Class IE electronic valve operators installed inside containment Issue expected to be open item in SER
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/03/09 KNIGHTON, G W Licensing Branch 3 2pp 17563 034 24X Fiche 50-443, 83/03/09, 8303150331

8303180122 Forwards SER (NUREG-0896) & FR notice of availability W/o SER
KNIGHTON, G W Licensing Branch 3 83/03/10 TALLMAN, W C Public Service Co of New Hampshire 3pp 17625 164 24X
Fiche 50-443, 83/03/10, 8303180122

--8303180124 Notice of availability of SER (NUREG-0896)
KNIGHTON, G W Licensing Branch 3 83/03/10 2pp 17625 167
24X Fiche 50-443, 83/03/10, 8303180122

8303290721 Forwards SER re application for OLs Resolution of all open items required prior to decision on issuance of OLs W/o SER
NOVAK, T M Assistant Director for Licensing 83/03/10 EBERSOLE, J ACRS - Advisory Committee on Reactor Safeguards 2pp 17746 313
24X Fiche 50-443, 83/03/10, 8303290721

8303290254 Responds to 830310 ltr re SER open item, reiterating util position on NUREG-0737 requirement for shift technical advisor on shift. Shift technical advisor position need not be staffed to meet NUREG-0737 & Generic Ltr 82-33.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire. 83/03/24. KNIGHTON, G. W. Licensing Branch 3. 3pp. 17716.004. 24X Fiche 50-443, 83/03/24, 8303290254.

8303220444 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SEABROOK STATION, UNITS 1 AND 2 Docket Nos. 50-443 And 50-444 (Public Service Company Of New Hampshire, et al.)
* Division of Licensing. NUREG-0896. 83/03/31. 668pp. Available at NRC. $14.00. 17668.111. 24X Fiche 50-443, 83/03/31, 8303220444.

F. Security, medical, emergency & fire protection plans

8303140085 Forwards FEMA 830215 ltr notifying NRC of inability to meet 830505 testimony filing date. Prehearing conference or telcon w/parties suggested. No direct impact expected on schedule for litigation of nonemergency contentions.
LESSY, R. P. Hearings Division. 83/02/16. HOYT, H. ; LUEBKE, E. A. ; HARBOUR, J. Atomic Safety and Licensing Board Panel. 6pp. 17540.134. 24X Fiche 50-443, 83/02/16, 8303140085.

8303010578 Responds to Power Sys Branch Open Item SRP 9.5.4 re protection of fuel oil transfer pump from damage due to inadvertent actuation of fire protection sys. Commitment to replace open heads of deluge sys encl.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire. 83/02/24. KNIGHTON, G. W. Licensing Branch 3. 3pp. 17336.064. 24X Fiche 50-443, 83/02/24, 8303010578.

8303140010 Forwards Newburyport, MA draft radiological emergency response plan. Plan received by FEMA on 830223 from State of MA.
LESSY, R. P. Hearing Branch 3. 83/02/28. HOYT, H. ; LUEBKE, E. A. ; HARBOUR, J. Atomic Safety and Licensing Board Panel. 179pp. 17544.148. 24X Fiche 50-443, 83/02/28, 8303140010.

G. Adjudicatory correspondence

8303140553 Ack receipt of ltrs re interest of municipalities in proceedings. Ltrs forwarded to ASLB Certificate of Svc encl.
LESSY, R. P. Hearings Division. 83/02/07. MCKEON, P. J. Rye, NH. PEVEAR, R. C. Hampton Falls, NH. GAVUTIS, S. East Kingston, NH. 4pp. 17539.026. 24X Fiche 50-443, 83/02/07, 8303140553.

--8303140559 Informs of interest & concern w/emergency planning, warning of residents, monitoring of radiation & insurance coverage for evacuation. Permission to address other subjs in proceeding requested.
GAVUTIS, S. East Kingston, NH. 83/01/27. LESSY, R. P. Hearings Division. 1p. 17539.030. 24X Fiche 50-443, 83/02/07, 8303140553.

--8303140566 Informs of interest & concern w/emergency planning, warning of residents, monitoring of radiation & insurance coverage for evacuation. Permission to address other subjs in proceeding requested.
PEVEAR, R. C. Hampton Falls, NH. 83/01/17. LESSY, R. P. Hearings Division. 1p. 17539.031. 24X Fiche 50-443, 83/02/07, 8303140553.

--8303140575 Informs of interest in emergency planning, warning of public, monitoring of radiation & insurance coverage for evacuation. Permission to address other subjs in proceeding requested.
MCKEON, P. J. Rye, NH. 83/01/20. LESSY, R. P. Hearings Division. 1p. 17539.032. 24X Fiche 50-443, 83/02/07, 8303140553.

8302180118 Fifteenth motion for summary disposition of Contention NECNP I.G re wide-range pressure transmitters. No genuine issue of matl fact exists. Related correspondence.
DIGNAN, T. G. ; GAD, R. K. Public Service Co. of New Hampshire. DIGNAN, T. G. Ropes & Gray. 83/02/11. Atomic Safety and Licensing Board Panel. 3pp. 17216.184. 24X Fiche 50-443, 83/02/11, 8302180118.

--8302180128 Affidavit of WN Fadden supporting fifteenth motion for summary disposition of Contention NECNP I.G. Certificate of Svc encl.
FADDEN, W. N. Yankee Atomic Electric Co. 83/02/11. 3pp. 17216.187. 24X Fiche 50-443, 83/02/11, 8302180118.

8303140085 Forwards FEMA 830215 ltr notifying NRC of inability to meet 830505 testimony filing date. Prehearing conference or telcon w/parties suggested. No direct impact expected on schedule for litigation of nonemergency contentions.
LESSY, R. P. Hearings Division. 83/02/16. HOYT, H. ; LUEBKE, E. A. ; HARBOUR, J. Atomic Safety and Licensing Board Panel. 6pp. 17540.134. 24X Fiche 50-443, 83/02/16, 8303140085.

8303010078 Forwards applicant answers to New England Coalition on Nuclear Pollution 820204 first set of interrogatories & requests for documents on Contentions III.1, III.2, III.12 & III.13.
GAD, R. K. Ropes & Gray. GAD, R. K. Public Service Co. of New Hampshire. 83/02/25. Office of the Secretary of the Commission. 1p. 17335.278. 24X Fiche 50-443, 83/02/25, 8303010078.

--8303010082 Answers to 820204 first set of interrogatories & requests for documents on Contentions III.1, III.2, III.3, III.12 & III.13. Certificate of Svc encl.
GAD, R. K. Public Service Co. of New Hampshire. GAD, R. K. Ropes & Gray. 83/02/25. New England Coalition on Nuclear Pollution. 49pp. 17335.279. 24X Fiche 50-443, 83/02/25, 8303010078.

8303010407 Answer opposing NRC 830204 motion to dismiss chamber from hearings because of failure to respond to interrogatories. Chamber has no expert witness, but wishes to present case through cross examination.
HOLLINGWORTH, B. Chamber of Commerce, Hampton Beach Area, NH. 83/02/25. Atomic Safety and Licensing Board Panel. 2pp. 17346.226. 24X Fiche 50-443, 83/02/25, 8303010407.

8303080082 Forwards applicant answers to New England Coalition on Nuclear Pollution motions to compel answers to second & third set of interrogatories.
GAD, R. K. Ropes & Gray. GAD, R. K. Public Service Co. of New Hampshire. 83/02/28. Office of the Secretary of the Commission. 1p. 17457.166. 24X Fiche 50-443, 83/02/28, 8303080082.

--8303080089 Answers to New England Coalition on Nuclear Pollution 830216 motion to compel applicant answers to Coalition third set of interrogatories on Contentions I.A.2, I.B.1, I.B.2 & I.C. Certificate of Svc encl.
GAD, R. K. Public Service Co. of New Hampshire. GAD, R. K. Ropes & Gray. 83/02/28. Atomic Safety and Licensing Board Panel. 7pp. 17457.167. 24X Fiche 50-443, 83/02/28, 8303080082.

--8303080106 Answers to New England Coalition on Nuclear Pollution 830216 motion to compel applicant answers to Coalition second set of interrogatories on Contentions I.D.1, I.D.4, I.F.1, I.I, I.L & II.R. Certificate of Svc encl.
GAD, R. K. Public Service Co. of New Hampshire. GAD, R. K. Ropes & Gray. 83/02/28. Atomic Safety and Licensing Board Panel. 5pp. 17457.174. 24X Fiche 50-443, 83/02/28, 8303080082.

8303140010 Forwards Newburyport, MA draft radiological emergency response plan. Plan received by FEMA on 830223 from State of MA.
LESSY, R. P. Hearing Branch 3. 83/02/28. HOYT, H. ; LUEBKE, E. A. ; HARBOUR, J. Atomic Safety and Licensing Board Panel. 179pp. 17544.148. 24X Fiche 50-443, 83/02/28, 8303140010.

8303140078 Motion for summary disposition of New England Coalition on Nuclear Pollution Contentions II.B.1, II.B.3, II.B.4 & II.B.5 re QA organization & program. Statement of matl facts as to which there is no genuine issue to be heard encl.
PATTERSON, W. F. Hearing Branch 3. 83/02/28. Atomic Safety and Licensing Board Panel. 10pp. 17544.035. 24X Fiche 50-443, 83/02/28, 8303140078.

--8303140086 Affidavit of JW Gilray re assertions contained in New England Coalition on Nuclear Pollution Contentions II.B.1, II.B.3, II.B.4 & II.B.5 on QA program. Certificate of Svc encl.
GILRAY, J. W. QA Branch. 83/02/28. 9pp. 17544.051. 24X Fiche 50-443, 83/02/28, 8303140078.

8303140148 Motion for summary disposition of New England Coalition on Nuclear Pollution Contention I.B.1 re RHR environ qualification. RHR sys are safety-related. Matl facts as to which there is no genuine issue to be heard encl.
PERLIS, R. G. Hearing Branch 3. LESSY, R. P. Hearings Division. 83/02/28. Atomic Safety and Licensing Board Panel. 10pp. 17540.140. 24X Fiche 50-443, 83/02/28, 8303140148.

--8303140154 Affidavit of CY Liang re New England Coalition on Nuclear Pollution Contention I.B.1 re environ qualification of sys required for RHR. Certificate of Svc encl.
LIANG, C. Y. Reactor Systems Branch. 83/02/28. 8pp. 17540.150. 24X Fiche 50-443, 83/02/28, 8303140148.

8303030344 Memorandum & order ruling on applicant 830125 motions to compel Seacoast Anti-Pollution League & State of NH answers to listed interrogatories.
HOYT, H. F. Atomic Safety and Licensing Board Panel. 83/03/01. New Hampshire, State of. 9pp. 17410.035. 24X Fiche 50-443, 83/03/01, 8303030344.

8303030352 Order admitting Town of Portsmouth, NH as interested municipality. Admitted contentions encl.
HOYT, H. F. Atomic Safety and Licensing Board Panel. 83/03/01. Portsmouth, NH. 10pp. 17410.018. 24X Fiche 50-443, 83/03/01, 8303030352.

8303040337 Response opposing Seacoast Anti-Pollution League 830211 motion to suppl motion for summary disposition of Contention SAPL Suppl III Rules of practice prohibit supplemental pleading Certificate of Svc encl
LESSY, R P Hearing Branch 3 83/03/03 Atomic Safety and Licensing Board Panel 5pp 17372:251 24X Fiche 50-443, 83/03/03, 8303040337

8303070095 Advises that RG Miller & CA Cannery should be added to svc list
COPELAND, J Atomic Safety and Licensing Board Panel 83/03/03 Public Service Co of New Hampshire 1p 17434:323 24X Fiche 50-443, 83/03/03, 8303070095

8303080454 Motion for immediate stay of obligation to answer motions for summary judgment until ASLB rules on encl motion for deferral, in order to prevent needless filings
JORDAN, W S , CURRAN, D New England Coalition on Nuclear Pollution 83/03/03 Atomic Safety and Licensing Appeal Panel 3pp 17453:304 24X Fiche 50-443, 83/03/03, 8303080454

8303080490 Motion for deferral of consideration of motions for summary disposition until issuance of SER Prehearing conference should be rescheduled Certificate of Svc encl
JORDAN, W S , CURRAN, D New England Coalition on Nuclear Pollution 83/03/03 Atomic Safety and Licensing Appeal Panel 9pp 17451:351 24X Fiche 50-443, 83/03/03, 8303080490

8303080026 Confirms NRC understanding of contentions New England Coalition on Nuclear Pollution agreed to withdraw NRC will file responses to util first, second, third, eleventh, sixteenth & seventeenth motions for summary disposition
LESSY, R P Hearings Division PERLIS, R G Hearing Branch 3 83/03/04 JORDAN, W S , CURRAN, D Harmon & Weiss 2pp 17455:357 24X Fiche 50-443, 83/03/04, 8303080026

8303080050 Informs of 830302 meeting w/NH Governor Sununu re special emergency planning problems caused by crowds at beaches close to site Memo distributed to satisfy ex parte regulations
GILINSKY, V Commissioners 83/03/04 Commissioners 1p 17455:294 24X Fiche 50-443, 83/03/04, 8303080050

8303100157 Requests opportunity to file response to New England Coalition on Nuclear Pollution 830304 motion for deferral of consideration of motions for summary disposition or for dismissal SER (NUREG-0896) issued on 830304 W/o encl
LESSY, R P Hearings Division 83/03/07 HOYT, H , LUEBKE, E A , HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 17485:230 24X Fiche 50-443, 83/03/07, 8303100157

8303100378 Order vacating ASLB 830224 order scheduling 830317 prehearing conference Confirms 830304 oral order granting deferral until date named for filing answers to motions for summary disposition
HOYT, H F Atomic Safety and Licensing Board Panel 83/03/07 1p 17488:282 24X Fiche 50-443, 83/03/07, 8303100378

8303140322 Forwards answer supporting New England Coalition on Nuclear Pollution 830303 motion for deferral of consideration of motions for summary disposition or for dismissal Related correspondence
BRISBEE, G D New Hampshire, State of 83/03/08 Docketing & Services Branch 1p 17544:001 24X Fiche 50-443, 83/03/08, 8303140322

--8303140027 Answer supporting New England Coalition on Nuclear Pollution 830303 motion for deferral of consideration of motions for summary disposition or for dismissal SER must be issued before ruling W/Certificate of Svc Related correspondence
BRISBEE, G D New Hampshire, State of 83/03/08 Atomic Safety and Licensing Board Panel 8pp ,7544:002 24X Fiche 50-443, 83/03/08, 8303140322

8303170422 Forwards applicant answer to New England Coalition on Nuclear Power 830303 motion for deferral of consideration of motions for summary disposition or for dismissal
GAD, R K Ropes & Gray GAD, R K Public Service Co of New Hampshire 83/03/08 Office of the Secretary of the Commission 1p 17610:107 24X Fiche 50-443, 83/03/08, 8303170422

--8303170426 Answer in opposition to New England Coalition on Nuclear Power 830303 motion for deferral of consideration of motions for summary disposition or for dismissal Such motions may be entertained prior to SER issuance Certificate of Svc encl
DIGNAN, T G , GAD, R K Public Service Co of New Hampshire DIGNAN, T G Ropes & Gray 83/03/08 Atomic Safety and Licensing Board Panel 11pp 17610:108 24X Fiche 50-443, 83/03/08, 8303170422

--8303170430 Forwards applicant answer to New England Coalition on Nuclear Pollution 830303 motion for deferral of consideration of motions for summary disposition or for dismissal W/o encl
GAD, R K Ropes & Gray GAD, R K Public Service Co of New Hampshire 83/03/07 HOYT, H F Atomic Safety and Licensing Board Panel 1p 17610:119 24X Fiche 50-443, 83/03/08, 8303170422

8303170437 Response opposing Seacoast Antipollution League motion for summary disposition of Contention Suppl 3 Certificate of Svc encl Related correspondence
DIGNAN, T G Public Service Co of New Hampshire DIGNAN, T G Ropes & Gray 83/03/09 Atomic Safety and Licensing Board Panel 5pp 17609:198 24X Fiche 50-443, 83/03/09, 8303170437

8303140206 Response opposing New England Coalition on Nuclear Pollution 830303 motion for deferral of consideration of pending motions for summary disposition Deadlines should be established & SER discovery denied Certificate of Svc encl
LESSY, R P Hearings Division PERLIS, R G Hearing Branch 3 83/03/10 Atomic Safety and Licensing Board Panel 14pp 17540:084 24X Fiche 50-443, 83/03/10, 8303140206

8303180323 Forwards supplemental answers to util interrogatories & request for production of documents Related correspondence
BACKUS, R A Backus, Shea & Meyer BACKUS, R A Seacoast Anti-Pollution League 83/03/10 Office of the Secretary of the Commission 1p 17619:303 24X Fiche 50-443, 83/03/10, 8303180323

--8303180329 Supplemental answers to interrogatories & request for production of documents Svc list encl Related correspondence
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/03/10 Public Service Co of New Hampshire 24pp 17619:304 24X Fiche 50-443, 83/03/10, 8303180323

8303230261 Forwards request to participate as interested municipality in proceedings
MACHIROS, A Newbury, MA 83/03/10 HOYT, H F Atomic Safety and Licensing Board Panel 1p 17662:026 24X Fiche 50-443, 83/03/10, 8303230261

--8303230263 Request to participate as interested municipality in proceedings Certificate of Svc encl
MACHIROS, A Newbury, MA 83/03/10 Atomic Safety and Licensing Board Panel 2pp 17662:027 24X Fiche 50-443, 83/03/10, 8303230261

8303180151 Motion for dismissal of Hampton Beach Area Chamber of Commerce (CCCNH) 820913 contentions 5 of CCCNH as party to proceedings, due to CCCNH failure to participate in discovery Certificate of Svc encl
DIGNAN, T G , GAD, R K Public Service Co of New Hampshire DIGNAN, T G Ropes & Gray 83/03/11 Atomic Safety and Licensing Board Panel 8pp 17617:281 24X Fiche 50-443, 83/03/11, 8303180151

8303170025 Renewed motion to dismiss Hampton Beach Chamber of Commerce (HBCC) Contention 7 & to compel HBCC answers to interrogatories on HBCC Contentions 4 & 5 HBCC failed to answer interrogatories as ordered by ASLB
LESSY, R P Hearings Division PERLIS, R G , PATTERSON, W F Hearing Branch 3 83/03/15 Atomic Safety and Licensing Board Panel 8pp 17608:324 24X Fiche 50-443, 83/03/15, 8303170025

--8303170030 Response to interrogatories & request for production of documents Certificate of Svc encl
HOLLINGSWORTH Hampton Beach Area Chamber of Commerce, Hampton, NH 83/02/26 Office of the Executive Legal Director 5pp 17608:332 24X Fiche 50-443, 83/03/15, 8303170025

8303230212 Objection to applicant 830214 21st motion for summary disposition of New England Coalition on Nuclear Pollution Contentions III 12 & III 13 Related correspondence
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/03/15 Atomic Safety and Licensing Board Panel 5pp 17665:103 24X Fiche 50-443, 83/03/15, 8303230212

--8303230216 Motion for change of prehearing conference location Conference should be held within plume emergency planning zone for convenience of petitioners & board members Svc list encl
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/03/18 Atomic Safety and Licensing Board Panel 3pp 17665:108 24X Fiche 50-443, 83/03/15, 8303230212

8303180143 Telecopy order rescheduling prehearing conference for 830407 & ruling on New England Coalition on Nuclear Pollution 830303 motion for deferral of consideration of motions for summary disposition or for dismissal
HOYT, H F Atomic Safety and Licensing Board Panel 83/03/16 Public Service Co of New Hampshire 6pp 17617:238 24X Fiche 50-443, 83/03/16, 8303180143

8303180148 Order scheduling 830407-08 prehearing conference. Parties directed to be prepared to discuss pending motions for summary disposition & adjustments to 820910 schedule.
HOYT, H. F. Atomic Safety and Licensing Board Panel. 83/03/16. 2pp. 17617:279. 24X Fiche. 50-443, 83/03/16, 8303180148.

8303230251 Forwards State of NH supplemental response to 821208 interrogatories & requests for production of documents. Related correspondence.
BISBEE, G. D. New Hampshire, State of. 83/03/16. Docketing & Services Branch. 1p. 17661:161. 24X Fiche. 50-443, 83/03/16, 8303230251.

--8303230256 Supplemental response to 821208 interrogatories & requests for production of documents. Certificate of Svc encl. Related correspondence.
BISBEE, G. D. New Hampshire, State of. FAN, S. S. New Hampshire, Univ. of. 83/03/16. Public Service Co. of New Hampshire. 5pp. 17661:162. 24X Fiche. 50-443, 83/03/16, 8303230251.

8303220254 Order directing util either to provide New England Coalition on Nuclear Pollution draft reactor vessel exam plan or provide date when plan will be submitted. Grants motion to compel more accurate & specific answer to Interrogatory 7.
HOYT, H. F. Atomic Safety and Licensing Board Panel. 83/03/17. Public Service Co. of New Hampshire. 2pp. 17656:248. 24X Fiche. 50-443, 83/03/17, 8303220254.

8303220273 Order ruling on New England Coalition on Nuclear Pollution 830216 motion to compel answers to interrogatories. Motion re Interrogatory 7 denied. Ruling re Interrogatory 17 deferred. Interrogatory 21 moot.
HOYT, H. F. Atomic Safety and Licensing Board Panel. 83/03/17. New England Coalition on Nuclear Pollution. 3pp. 17656:211. 24X Fiche. 50-443, 83/03/17, 8303220273.

8303220168 Order admitting Town of Newbury, MA as interested municipality. Town must observe procedural requirements & take proceeding as found.
HOYT, H. F. Atomic Safety and Licensing Board Panel. 83/03/18. Newbury, MA. 10pp. 17658:157. 24X Fiche. 50-443, 83/03/18, 8303220168.

8303220234 Motion to relocate 830407-08 prehearing conference set in Boston, MA to site within 10 miles of plant. Holding conference 50 miles from affected area unfair & inconsistent w/Commission practices. Certificate of Svc encl.
CURRAN, D. , JORDAN, W. S. New England Coalition on Nuclear Pollution.
CURRAN, D. Harmon & Weiss. 83/03/18. Atomic Safety and Licensing Board Panel. 5pp. 17657:278. 24X Fiche. 50-443, 83/03/18, 8303220234.

8303220245 Motion to extend deadline until 830517 for final discovery requests re emergency planning contentions admitted by ASLB on 821117. Related correspondence.
JORDAN, W. S. , CURRAN, D. New England Coalition on Nuclear Pollution.
JORDAN, W. S. Harmon & Weiss. 83/03/18. Atomic Safety and Licensing Board Panel. 2pp. 17657:309. 24X Fiche. 50-443, 83/03/18, 8303220245.

8303230219 Notice of withdrawal of EJ McDermott & AC Thompson appearances in proceeding.
THOMPSON, A. C. South Hampton, NH. THOMPSON, A. C. Sanders & McDermott. 83/03/18. 1p. 17665:193. 24X Fiche. 50-443, 83/03/18, 8303230219.

8303230221 Notice of withdrawal of LM Edelman & WL Sanders appearances in proceeding.
EDELMAN, L. M. Sanders & McDermott. 83/03/18. 1p. 17665:188. 24X Fiche. 50-443, 83/03/18, 8303230221.

8303240430 Motion for clarification of ASLB 830117 order. Thirty-day period for filing contentions on emergency planning should not be triggered by receipt of City of Newburyport, MA draft emergency plan. Moves for stay of contention filing deadline.
SHOTWELL, J. A. Massachusetts, Commonwealth of. 83/03/18. Atomic Safety and Licensing Board Panel. 6pp. 17679:001. 24X Fiche. 50-443, 83/03/18, 8303240430.

--8303240435 Advises that City of Newburyport, MA has not reviewed or approved draft emergency plan for City. Plan should not be treated as City emergency plan.
SULLIVAN, R. E. Newburyport, MA. 83/03/14. HOYT, H. , LUEBKE, E. A. , HARBOUR, J. Atomic Safety and Licensing Board Panel. 2pp. 17679:307. 24X Fiche. 50-443, 83/03/18, 8303240430.

--8303240445 Informs that emergency plan submitted to FEMA was not meant to be submitted to NRC or to initiate formal litigation. Plan submitted to obtain initial reactions of federal radiological assistance committee. W/Certificate of Svc.
DOLAN, J. C. Massachusetts, Commonwealth of. 83/03/17. HOYT, H. , LUEBKE, E. , HARBOUR, J. Atomic Safety and Licensing Board Panel. 3pp. 17679:009. 24X Fiche. 50-443, 83/03/18, 8303240430.

8303230019 Response to Town of Newbury, MA 830310 request to participate as interested municipality. NRC does not oppose admission if subj to conditions of observing procedural requirements & taking hearing as found. W/Certificate of Svc.
PATTERSON, W. F. Hearing Branch 3. 83/03/21. Atomic Safety and Licensing Board Panel. 4pp. 17665:034. 24X Fiche. 50-443, 83/03/21, 8303230019.

8303230039 Resprnse to applicant 830211 fifth motion for summary disposition or State of NH Contention 9. Supports disposition of portions of contentions re NUREG-0737, Items II. B. 2. II. F. 1, III. D. 1. 1, III. D. 3. 3 & III. D. 3. 4. W/Certificate of Svc.
PERLIS, R. G. Hearing Branch 3. LESSY, R. P. Hearings Division. 83/03/21. Atomic Safety and Licensing Board Panel. 8pp. 17663:236. 24X Fiche. 50-443, 83/03/21, 8303230039.

8303250164 Answer opposing applicant nineteenth motion for summary disposition of Contention SAPL Suppl III. Applicant statement of matl fact fails to address compliance & adequacy w/policy statement. W/svc list. Related correspondence.
BACKUS, R. A. Seacoast Anti-Pollution League. BACKUS, R. A. Backus, Shea & Meyer. 83/03/21. Atomic Safety and Licensing Board Panel. 8pp. 17691:140. 24X Fiche. 50-443, 83/03/21, 8303250164.

8303230191 Forwards response to MA Atty General Bellotti motion for clarification of ASLB 830117 order & for immediate stay of filing deadline for contentions on emergency planning for City of Newburyport.
GAD, R. K. Ropes & Gray. GAD, R. K. Public Service Co. of New Hampshire. 83/03/22. Office of the Secretary of the Commission. 1p. 17665:212. 24X Fiche. 50-443, 83/03/22, 8303230191.

--8303230199 Response in opposition to MA Atty General Bellotti motion for clarification of ASLB 830117 order & for immediate stay of filing deadline for contentions on emergency planning for City of Newburyport. Certificate of Svc encl.
DIGNAN, T. G. , GAD, R. K. Public Service Co. of New Hampshire.
DIGNAN, T. G. Ropes & Gray. 83/03/22. Atomic Safety and Licensing Board Panel. 9pp. 17665:213. 24X Fiche. 50-443, 83/03/22, 8303230191.

8303240411 Order delineating agenda for 830407-08 prehearing conference. Agenda will include pending motions for summary disposition; adjustments to schedule & matters pertaining to admitted contentions. FEMA to participate on 830408.
HOYT, H. F. Atomic Safety and Licensing Board Panel. 83/03/22. 2pp. 17679:065. 24X Fiche. 50-443, 83/03/22, 8303240411.

8303250163 Corrects address for Sun Valley Assoc as noted in 830318 notice of withdrawal of appearance.
EDELMAN, L. M. Sanders & McDermott. 83/03/22. Docketing & Services Branch. 1p. 17691:148. 24X Fiche. 50-443, 83/03/22, 8303250163.

8303290432 Requests that public hearing on evacuation plans be scheduled for seacoast area.
CANNEY, C. A. Portsmouth, NH. 83/03/22. HOYT, H. , LUEBKE, E. A. , HARBOUR, J. Atomic Safety and Licensin Board Panel. 1p. 17725:324. 24X Fiche. 50-443, 83/03/22, 8303290 '

8303240022 Response opposing Seacoast Anti-Pollution League 830211 motion for summary disposition of Contention SAPL Suppl 3. League has not shown that FES does not comply w/Commission interim policy statement on serious accidents.
LESSY, R. P. Hearings Division. PERLIS, R. G. Hearing Branch 3. 83/03/23. Atomic Safety and Licensing Board Panel. 10pp. 17681:075. 24X Fiche. 50-443, 83/03/23, 8303240022.

--8303240024 Affidavit of JA Mitchell re Seacoast Anti-Pollution League 830211 motion for summary disposition. Evacuation study calculations provide perspective of risks at site as stated in FES. Certificate of Svc encl.
MITCHELL, J. A. Accident Evaluation Branch. 83/03/22. 8pp. 17681:085. 24X Fiche. 50-443, 83/03/23, 8303240022.

8303240318 Response to Commonwealth of MA 830318 motion for clarification of ASLB 830117 order & for stay of filing deadline for contentions on City of Newbury, MA emergency plan. Opposes stay. Certificate of Svc encl.
PERLIS, P. G. Hearing Branch 2. 83/03/23. Atomic Safety and Licensing Board Panel. 8pp. 17679:344. 24X Fiche. 50-443, 83/03/23, 8303240318.

8303250153 Forwards answers to util & NRC motions for summary disposition. Related correspondence.
BISBEE, G. D. New Hampshire, State of. 83/03/23. Docketing & Services Branch. 1p. 17691:084. 24X Fiche. 50-443, 83/03/23, 8303250153.

--8303250154 Answer opposing util & NRC motions for summary disposition of Contention NECNP-I.B.1 re RHR sys. Factual dispute exists over adequacy of steam generators to provide RHR capability. Related correspondence.
BISBEE, G.D. New Hampshire, State of 83/03/23 Atomic Safety and Licensing Board Panel 3pp. 17691:085 24X Fiche: 50-443, 83/03/23, 8303250153.

--8303250158 Affidavit of SS Fan re steam generator tube integrity. RHR sys design should be studied to assess design limitations & effectiveness of sys & to determine if addl means of RHR needed to ensure sys adequacy.
FAN, S.S. New Hampshire, State of 83/03/23 2pp. 17691:088 24X Fiche: 50-443, 83/03/23, 8303250153.

--8303250162 Answer to util motion for full summary disposition & NRC motion for partial summary disposition of Contention NH-13. Opposes disposition of NUREG-0737, Items I.C.1 & I.A.1.1 but not II.B.4. Related correspondence.
BISBEE, G.D. New Hampshire, State of 83/03/23 Atomic Safety and Licensing Board Panel 4pp. 17691:090 24X Fiche: 50-443, 83/03/23, 8303250153.

--8303250166 Answer opposing applicant nineteenth motion for summary disposition of Contention SAPL Suppl III Genuine issues of fact remain re NRC 800613 policy statement. Related correspondence.
BISBEE, G.D. New Hampshire, State of 83/03/23 Atomic Safety and Licensing Board Panel 4pp. 17691:094 24X Fiche: 50-443, 83/03/23, 8303250153.

--8303250168 Affidavit of SS Fan. Until NRC properly considers Class 9 accidents & identifies addl features or other actions which would prevent or mitigate consequences of serious accidents, NRC will not comply w/NRC 800613 policy statement.
FAN, S.S. New Hampshire, State of 83/03/23 2pp. 17691:098 24X Fiche: 50-443, 83/03/23, 8303250153.

--8303250170 Answer opposing applicant seventh motion for summary disposition of Contentions NH-21 & CCCNH-5. Motion premature & should be held in abeyance. Discovery not completed. Issues of fact still in dispute. Related correspondence.
BISBEE, G.D. New Hampshire, State of 83/03/23 Atomic Safety and Licensing Board Panel 6pp. 17691:100 24X Fiche: 50-443, 83/03/23, 8303250153.

--P303250171 Answer to applicant fifth motion for summary disposition of Contention NH-9. Motion should be held in abeyance since discovery not complete or should be denied as to NUREG-0737, Item II.B.3 W/Certificate of Svc. Related correspondence.
BISBEE, G.D. New Hampshire, State of 83/03/23 Atomic Safety and Licensing Board Panel 5pp. 17691:106 24X Fiche: 50-443, 83/03/23, 8303250153.

8303250147 Order denying State of MA 830318 motion for clarification of ASLB 830117 order. Plain language of order identified triggering event for filing emergency planning contentions. Extension to file contentions until 830328 granted.
HOYT, H.F. Atomic Safety and Licensing Board Panel 83/03/24 2pp. 17691:012 24X Fiche: 50-443, 83/03/24, 8303250147.

8303290445 Forwards applicant response to New England Coalition on Nuclear Pollution motion to extend emergency planning discovery deadline.
GAD, R.K. Ropes & Gray GAD, R.K. Public Service Co. of New Hampshire 83/03/24 Office of the Secretary of the Commission. 1p. 17725:341 24X Fiche: 50-443, 83/03/24, 8303290445.

--8303290449 Response to New England Coalition on Nuclear Pollution motion to extend emergency planning discovery deadline. Insufficient basis shown for relief requested, but no objection posed. Certificate of Svc encl.
DIGNAN, T.G., GAD, R.K. Public Service Co. of New Hampshire. DIGNAN, T.G. Ropes & Gray 83/03/24 Atomic Safety and Licensing Board Panel 7pp. 17725:342 24X Fiche: 50-443, 83/03/24, 8303290445.

8303290516 Order denying New England Coalition on Nuclear Pollution & Seacoast Anti-Pollution League 830318 motions to relocate prehearing conference.
HOYT, H.F. Atomic Safety and Licensing Board Panel 83/03/24 New England Coalition on Nuclear Pollution. 1p. 17725:111 24X Fiche: 50-443, 83/03/24, 8303290516.

8303290525 Memorandum & order granting portion of applicant 830128 motion to compel answers to interrogatories & denying portion of New England Coalition on Nuclear Pollution 830216 request for protective order.
HOYT, H.F. Atomic Safety and Licensing Board Panel 83/03/24 Public Service Co. of New Hampshire 15pp. 17724:099 24X Fiche: 50-443, 83/03/24, 8303290525.

8303290536 Response opposing util & NRC motions for summary disposition of Contentions I.A.2, I.B.1, I.D.2, I.G, II.B.3 & II.B.4. Some contentions withdrawn since discovery satisfied concerns. W/Certificate of Svc. Related correspondence.
CURRAN, D. New England Coalition on Nuclear Pollution. CURRAN, D. Harmon & Weiss 83/03/24 Atomic Safety and Licensing Board Panel 45pp. 17724:114 24X Fiche: 50-443, 83/03/24, 8303290536.

8303310313 Order denying New England Coalition on Nuclear Pollution 830318 motion to extend emergency planning deadline until 830517. No good cause shown for request.
HOYT, H.F. Atomic Safety and Licensing Board Panel 83/03/30 New England Coalition on Nuclear Pollution. 2pp. 17755:047 24X Fiche: 50-443, 83/03/30, 8303310313.

H. General correspondence

8303070156 Requests all future NRC correspondence be directed to RJ Harrison & document svc to WC Tallman be discontinued.
DEVINCENTIS, J. Yankee Atomic Electric Co. 83/03/01 KNIGHTON, G.W. Licensing Branch 3 2pp. 17433:354 24X Fiche: 50-443, 83/03/01, 8303070156.

Q. Inspection reports, IE Bulletins & correspondence

8302180214 Forwards IE Insp Repts 50-443/82-16 & 50-444/82-14 on 821221-830117 & notice of violation.
STAROSTECKI, R. Division of Project & Resident Programs 83/02/03. TALLMAN, W.C. Public Service Co. of New Hampshire 2pp. .7215:314 24X Fiche: 50-443, 83/02/03, 8302180214.

--8302180219 Notice of violation from insp on 821221-830117.
* Division of Project & Resident Programs 82/02/03 1p. 17215:316 24X Fiche: 50-443, 83/02/03, 8302180214.

--8302180224 IE Insp Repts 50-443/82-16 & 50-444/82-14 on 821221-830117. Noncompliance noted: failure to assure installation of Class IE cable in seismically qualified raceway sys.
CERNE, A.C., GRAMM, R.A., GALLO, R.M. Division of Project & Resident Programs 83/01/30 1p. 17215:317 24X Fiche: 50-443, 83/02/03, 8302180214.

8303100275 Forwards IE Insp Repts 50-443/83-01 & 50-444/83-01 on 830117-21. No noncompliance noted.
MARTIN, T.T. Division of Engineering & Technical Programs 83/02/23. TALLMAN, W.C. Public Service Co. of New Hampshire 2pp. 17489:307 24X Fiche: 50-443, 83/02/23, 8303100275.

--8303100281 IE Insp Repts 50-443/83-01 & 50-444/83-01 on 830117-21. No noncompliance noted. Major areas inspected: work activities, procedures & records re pipe support installation & return end (boxing) welding concerning hanger fabrication.
REYNOLDS, S.D., DURR, J. Region 1, Office of Director 83/02/17. 6pp. 17489:309 24X Fiche: 50-443, 83/02/23, 8303100275.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11pp. 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8303220139 Ack receipt of 830303 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/82-16 & 50-444/82-14. Future corrective actions will include development of computer program re cable crossings.
STAROSTECKI, R. Division of Project & Resident Programs 83/03/17. HARRISON, R.J. Public Service Co. of New Hampshire 2pp. 17657:247 24X Fiche: 50-443, 83/03/17, 8303220139.

--8303220148 Responds to NRC 830203 ltr re violations noted in IE Insp Repts 50-443/82-16 & 50-444/82-14. Corrective actions: cable installer issued interim procedure change requiring cable pull slips w/mixed raceway be returned for evaluation.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/03/03. STAROSTECKI, R. Division of Project & Resident Programs. 3pp. 17657:249 24X Fiche: 50-443, 83/03/17, 8303220139.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12lpp. 17774:352 24X Fiche 50-000, 83/03/21, 8212060387

S. Reportable occurrences, LERs & related correspondence

8303140607 Part 21 rept re defect in UHS svc water cooling tower structure. Structure will be modified to accommodate transverse shear forces. Design of mods will be completed by 830331.
SARSTEN, G. E. United Engineers & Constructors, Inc. (subs. of Raytheon Co.) 83/03/07 Director's Office, Office of Inspection and Enforcement 3pp. 17534:030 24X Fiche 50-443, 83/03/07, 8303140607

8303240366 Final deficiency rept re intermittent lock-up of GA Co radiation monitoring display RM-23. Initially reported on 830215. GA Co reviewing RM-23 design & conducting addl tests. Also reportable per Part 21.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/03/16 STAROSTECKI, R. Division of Project & Resident Programs 2pp. 17682:005 24X Fiche 50-443, 83/03/16, 8303240366

8303240441 Interim deficiency rept re power transistor heat sink separation from transistors in Westinghouse 7300 series process I&C sys cabinets. Initially reported on 830216. Evaluation results expected by 830515.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/03/18 STAROSTECKI, R. Division of Project & Resident Programs 2pp. 17678:345 24X Fiche 50-443, 83/03/18, 8303240441

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche 50-000, 83/02/24, 8302250505

DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp. 17492:033 24X Fiche 50-000, 83/02/16, 8302170082

8303010409 Forwards technical justification for not installing gross radioactivity monitor in svc water sys, in response to Effluent Treatment Sys Branch open item. Encl revised FSAR Page 9.2-4 will be incorporated in OL application Amend 49.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/02/24 KNIGHTON, G. W. Licensing Branch 3 4pp. 17346:228 24X Fiche 50-443, 83/02/24, 8303010409

8303010533 Forwards response to open item re single failure assumptions for Condition II events. Info will be incorporated in OL Application Amend 49.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/02/24 KNIGHTON, G. W. Licensing Branch 3 9pp. 17343:026 24X Fiche 50-443, 83/02/24, 8303010533

8303020083 Forwards revised response to NRC Request for Addl Info 460.27 re hydrogen control in radioactive gaseous waste sys cubicles. Revised response will be incorporated in OL application, Amend 49.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/02/25 KNIGHTON, G. W. Licensing Branch 3 3pp. 17352:131 24X Fiche 50-443, 83/02/25, 8303020083

8303020085 Clarifies util position on Request for Addl Info 440.133 re compliance w/Branch Technical Position RSB 5-1, "Design Requirements of RHR Sys." Pressurizer heaters not required to bring reactor to cold shutdown condition.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/02/25 KNIGHTON, G. W. Licensing Branch 3 2pp. 17352:134 24X Fiche 50-443, 83/02/25, 8303020085

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700:303 24X Fiche 50-000, 83/03/02, 8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176 24X Fiche 50-000, 83/03/07, 8303040005

8303150207 Summarizes 830224 meeting w/Region I re verification programs which assure FSAR, program & engineering criteria are translated into const & insp documents & are implemented.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/03/07 KNIGHTON, G. W. Licensing Branch 3 5pp. 17555:163 24X Fiche 50-443, 83/03/07, 8303150207

8303150195 Forwards "Pressure Boundary Calculations of Horizontal Pumps," in response to request for addl info re containment spray pumps OL application, Amend 49 will ref encl rept. Svc list encl.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/03/10 KNIGHTON, G. W. Licensing Branch 3 2pp. 17549:021 24X Fiche 50-443, 83/03/10, 8303150195

--8303150202 "Pressure Boundary Calculations of Horizontal Pumps."
MCDONALD, C. K. McDonald Engineering Analysis Co., Inc. 83/02/09
19pp. 17549:023 24X Fiche 50-443, 83/03/10, 8303150195

8303150436 Forwards response to request for addl info re postulated failure of nonseismic portion of svc water sys. Response revises previously submitted meeting notes & will be incorporated in Amend 49 to OL application.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/03/10 KNIGHTON, G. W. Licensing Branch 3 5pp. 17562:279 24X Fiche 50-443, 83/03/10, 8303150436

8303170441 Responds to Meteorological & Effluent Treatment Sys Branch Request for Addl Info 460.35 re turbine gland steam condenser exhaust. Radiation monitor need not be installed in turbine steam gland condenser vent.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/03/10 KNIGHTON, G. W. Licensing Branch 3 3pp. 17609:264 24X Fiche 50-443, 83/03/10, 8303170441

8303170358 Confirms 830311 telcon re pressure transmitter location/qualification. Transmitters RC PT 403 & 405 located outside containment & will be fully qualified for specific environ per NUREG-0588.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/03/15 KNIGHTON, G. W. Licensing Branch 3 2pp. 17605:181 24X Fiche 50-443, 83/03/15, 8303170358

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303090631 Advises that mgt review of SER Section 13.6, physical security plan & Section 16, Tech Specs, has been completed & found acceptable.
MIRAGLIA, F. J. Assistant Director for Safety Assessment 83/03/02
NOVAK, T. M. Assistant Director for Licensing 1p. 17480:285 24X Fiche 50-443, 83/03/02, 8303090631

8303150331 Informs of commitment to qualify Class IE electronic valve operators installed inside containment. Issue expected to be open item in SER.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/03/09 KNIGHTON, G. W. Licensing Branch 3 2pp. 17563:034 24X Fiche 50-443, 83/03/09, 8303150331

8303180122 Forwards SER (NUREG-0896) & FR notice of availability. W/o SER.
KNIGHTON, G. W. Licensing Branch 3 83/03/10 TALLMAN, W. C. Public Service Co. of New Hampshire 3pp. 17625:164 24X Fiche 50-443, 83/03/10, 8303180122

--8303180124 Notice of availability of SER (NUREG-0896).
KNIGHTON, G. W. Licensing Branch 3 83/03/10 2pp. 17625:167
24X Fiche 50-443, 83/03/10, 8303180122.

8303290721 Forwards SER re application for OLs. Resolution of all open items required prior to decision on issuance of OLs. W/o SER.
NOVAK, T. M. Assistant Director for Licensing 83/03/10 EBERSOLE, J. ACRS - Advisory Committee on Reactor Safeguards 2pp. 17746:313
24X Fiche 50-443, 83/03/10, 8303290721.

8303290254 Responds to 830310 ltr re SER open item, reiterating util position on NUREG-0737 requirement for shift technical advisor on shift. Shift technical advisor position need not be staffed to meet NUREG-0737 & Generic Ltr 82-33.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire. 83/03/24. KNIGHTON, G. W. Licensing Branch 3. 3pp. 17716:004. 24X Fiche 50-443, 83/03/24, 8303290254.

8303220444 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SEABROOK STATION, UNITS 1 AND 2 Docket Nos. 50-443 And 50-444. (Public Service Company Of New Hampshire, et al.)
+ Division of Licensing. NUREG-0896. 83/03/31. 668pp. Available at NRC. $14.00. 17668:111. 24X Fiche 50-443, 83/03/31, 8303220444.

F. Security, medical, emergency & fire protection plans

8303140085 Forwards FEMA 830215 ltr notifying NRC of inability to meet 830505 testimony filing date. Prehearing conference or telcon w/parties suggested. No direct impact expected on schedule for litigation of nonemergency contentions.
LESSY, R. P. Hearings Division. 83/02/16. HOYT, H. Atomic Safety and Licensing Board Panel. 6pp. 17540:134. 24X Fiche 50-443, 83/02/16, 8303140085.

8303010578 Responds to Power Sys Branch Open Item SRP 9.5.4 re protection of fuel oil transfer pump from damage due to inadvertent actuation of fire protection sys. Commitment to replace open heads of deluge sys encl.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire. 83/02/24. KNIGHTON, G. W. Licensing Branch 3. 3pp. 17336:064. 24X Fiche 50-443, 83/02/24, 8303010578.

8303140010 Forwards Newburyport, MA draft radiological emergency response plan. Plan received by FEMA on 830223 from State of MA.
LESSY, R. P. Hearing Branch 3. 83/02/28. HOYT, H. Atomic Safety and Licensing Board Panel. 179pp. 17544:148. 24X Fiche 50-443, 83/02/28, 8303140010.

G. Adjudicatory correspondence

8303140553 Ack receipt of ltrs re interest of municipalities in proceedings. Ltrs forwarded to ASLB. Certificate of Svc encl.
LESSY, R. P. Hearings Division. 83/02/07. MCKEON, P. J. Rye, NH.
PEVEAR, R. C. Hampton Falls, NH. GAVUTIS, S. East Kingston, NH. 4pp. 17539:026. 24X Fiche 50-443, 83/02/07, 8303140553.

--8303140559 Informs of interest & concern w/emergency planning, warning of residents, monitoring of radiation & insurance coverage for evacuation. Permission to address other subjs in proceeding requested.
GAVUTIS, S. East Kingston, NH. 83/01/27. LESSY, R. P. Hearings Division. 1p. 17539:030. 24X Fiche 50-443, 83/02/07, 8303140553.

--8303140566 Informs of interest & concern w/emergency planning, warning of residents, monitoring of radiation & insurance coverage for evacuation. Permission to address other subjs in proceeding requested.
PEVEAR, R. C. Hampton Falls, NH. 83/01/17. LESSY, R. P. Hearings Division. 1p. 17539:031. 24X Fiche 50-443, 83/02/07, 8303140553.

--8303140575 Informs of interest in emergency planning, warning of public, monitoring of radiation & insurance coverage for evacuation. Permission to address other subjs in proceeding requested.
MCKEON, P. J. Rye, NH. 83/01/20. LESSY, R. P. Hearings Division. 1p. 17539:032. 24X Fiche 50-443, 83/02/07, 8303140553.

8302180118 Fifteenth motion for summary disposition of Contention NECNP I.G re wide-range pressure transmitters. No genuine issue of matl fact exists. Related correspondence.
DIGNAN, T. G., GAD, R. K. Public Service Co. of New Hampshire.
DIGNAN, T. G. Ropes & Gray. 83/02/11. Atomic Safety and Licensing Board Panel. 3pp. 17216:184. 24X Fiche 50-443, 83/02/11, 8302180118.

--8302180120 Affidavit of WN Fadden supporting fifteenth motion for summary disposition of Contention NECNP I.G. Certificate of Svc encl.
FADDEN, W. N. Yankee Atomic Electric Co. 83/02/11. 3pp. 17216:187. 24X Fiche 50-443, 83/02/11, 8302180118.

8303140085 Forwards FEMA 830215 ltr notifying NRC of inability to meet 830505 testimony filing date. Prehearing conference or telcon w/parties suggested. No direct impact expected on schedule for litigation of nonemergency contentions.
LESSY, R. P. Hearings Division. 83/02/16. HOYT, H., LUEBKE, E. A., HARBOUR, J. Atomic Safety and Licensing Board Panel. 6pp. 17540:134. 24X Fiche 50-443, 83/02/16, 8303140085.

8303010078 Forwards applicant answers to New England Coalition on Nuclear Pollution 820204 first set of interrogatories & requests for documents on Contentions III.1, III.2, III.12 & III.13.
GAD, R. K. Ropes & Gray. GAD, R. K. Public Service Co. of New Hampshire. 83/02/25. Office of the Secretary of the Commission. 1p. 17335:278. 24X Fiche 50-443, 83/02/25, 8303010078.

--8303010082 Answers to 820204 first set of interrogatories & requests for documents on Contentions III.1, III.2, III.3, III.12 & III.13. Certificate of Svc encl.
GAD, R. K. Public Service Co. of New Hampshire. GAD, R. K. Ropes & Gray. 83/02/25. New England Coalition on Nuclear Pollution. 49pp. 17335:279. 24X Fiche 50-443, 83/02/25, 8303010078.

8303010407 Answer opposing NRC 830204 motion to dismiss chamber from hearings because of failure to respond to interrogatories. Chamber has no expert witness, but wishes to present case through cross examination.
HOLLINGWORTH, B. Chamber of Commerce, Hampton Beach Area, NH. 83/02/25. Atomic Safety and Licensing Board Panel. 2pp. 17346:226. 24X Fiche 50-443, 83/02/25, 8303010407.

8303080082 Forwards applicant answers to New England Coalition on Nuclear Pollution motions to compel answers to second & third set of interrogatories.
GAD, R. K. Ropes & Gray. GAD, R. K. Public Service Co. of New Hampshire. 83/02/28. Office of the Secretary of the Commission. 1p. 17457:166. 24X Fiche 50-443, 83/02/28, 8303080082.

--8303080089 Answers to New England Coalition on Nuclear Pollution 830216 motion to compel applicant answers to Coalition third set of interrogatories on Contentions I.A.2, I.B.1, I.B.2 & I.C. Certificate of Svc encl.
GAD, R. K. Public Service Co. of New Hampshire. GAD, R. K. Ropes & Gray. 83/02/28. Atomic Safety and Licensing Board Panel. 7pp. 17457:167. 24X Fiche 50-443, 83/02/28, 8303080082.

--8303080106 Answers to New England Coalition on Nuclear Pollution 830216 motion to compel applicant answers to Coalition second set of interrogatories on Contentions I.D.1, I.D.4, I.F, I.I, I.L & II.B. Certificate of Svc encl.
GAD, R. K. Public Service Co. of New Hampshire. GAD, R. K. Ropes & Gray. 83/02/28. Atomic Safety and Licensing Board Panel. 5pp. 17457:174. 24X Fiche 50-443, 83/02/28, 8303080082.

8303140010 Forwards Newburyport, MA draft radiological emergency response plan. Plan received by FEMA on 830223 from State of MA.
LESSY, R. P. Hearing Branch 3. 83/02/28. HOYT, H., LUEBKE, E. A., HARBOUR, J. Atomic Safety and Licensing Board Panel. 179pp. 17544:148. 24X Fiche 50-443, 83/02/28, 8303140010.

8303140078 Motion for summary disposition of New England Coalition on Nuclear Pollution Contentions II.B.1, II.B.3, II.B.4 & II.B.5 re QA organization & program. Statement of matl facts as to which there is no genuine issue to be heard encl.
PATTERSON, W. F. Hearing Branch 3. 83/02/28. Atomic Safety and Licensing Board Panel. 16pp. 17544:035. 24X Fiche 50-443, 83/02/28, 8303140078.

--8303140086 Affidavit of JW Gilray re assertions contained in New England Coalition on Nuclear Pollution Contentions II.B.1, II.B.3, II.B.4 & II.B.5 on QA program. Certificate of Svc encl.
GILRAY, J. W. QA Branch. 83/02/28. 9pp. 17544:051. 24X Fiche 50-443, 83/02/28, 8303140078.

8303140148 Motion for summary disposition of New England Coalition on Nuclear Pollution Contention I.B.1 re RHR environ qualification. FHR sys are safety-related. Matl facts as to which there is no genuine issue to be heard encl.
PERLIS, R. G. Hearing Branch 3. LESSY, R. P. Hearings Division. 83/02/28. Atomic Safety and Licensing Board Panel. 10pp. 17540:140. 24X Fiche 50-443, 83/02/28, 8303140148.

--8303140154 Affidavit of CY Liang re New England Coalition on Nuclear Pollution Contention I.B.1 re environ qualification of sys required for RHR. Certificate of Svc encl.
LIANG, C. Y. Reactor Systems Branch. 83/02/28. 8pp. 17540:150. 24X Fiche 50-443, 83/02/28, 8303140148.

8303030344 Memorandum & order ruling on applicant 830125 motions to compel Seacoast Anti-Pollution League & State of NH answers to listed interrogatories.
HOYT, H. F. Atomic Safety and Licensing Board Panel. 83/03/01. New Hampshire, State of. 9pp. 17410:035. 24X Fiche 50-443, 83/03/01, 8303030344.

8303030352 Order admitting Town of Portsmouth, NH as interested municipality. Admitted contentions encl.
HOYT, H. F. Atomic Safety and Licensing Board Panel. 83/03/01. Portsmouth, NH. 10pp. 17410:018. 24X Fiche 50-443, 83/03/01, 8303030352.

8303040337 Response opposing Seacoast Anti-Pollution League 830211 motion to suppl motion for summary disposition of Contention SAPL Suppl III Rules of practice prohibit supplemental pleading Certificate of Svc encl.
LESSY, R P. Hearing Branch 3. 83/03/03. Atomic Safety and Licensing Board Panel. 5pp. 17372:251. 24X Fiche: 50-443, 83/03/03, 8303040337.

8303070095 Advises that RG Miller & CA Cannery should be added to svc list.
COPELAND, J. Atomic Safety and Licensing Board Panel. 83/03/03. Public Service Co. of New Hampshire. 1p. 17434:323. 24X Fiche: 50-443, 83/03/03, 8303070095.

8303080454 Motion for immediate stay of obligation to answer motions for summary judgment until ASLB rules on encl motion for deferral, in order to prevent needless filings.
JORDAN, W S. ; CURRAN, D. New England Coalition on Nuclear Pollution. 83/03/03. Atomic Safety and Licensing Appeal Panel. 3pp. 17453:304. 24X Fiche: 50-443, 83/03/03, 8303080454.

8303080490 Motion for deferral of consideration of motions for summary disposition until issuance of SER Prehearing conference should be rescheduled Certificate of Svc encl.
JORDAN, W S. ; CURRAN, D. New England Coalition on Nuclear Pollution. 83/03/03. Atomic Safety and Licensing Appeal Panel. 9pp. 17451:351. 24X Fiche: 50-443, 83/03/03, 8303080490.

8303080026 Confirms NRC understanding of contentions New England Coalition on Nuclear Pollution agreed to withdraw NRC will file responses to util first, second, third, eleventh, sixteenth & seventeenth motions for summary disposition.
LESSY, R P. Hearings Division. PERLIS, R G. Hearing Branch 3. 83/03/04. JORDAN, W S. ; CURRAN, D. Harmon & Weiss. 2pp. 17455:357. 24X Fiche: 50-443, 83/03/04, 8303080026.

8303080050 Informs of 830302 meeting w/NH Governor Sununu re special emergency planning problems caused by crowds at beaches close to site. Memo distributed to satisfy ex parte regulations.
GILINSKY, V. Commissioners. 83/03/04. Commissioners. 1p. 17455:294. 24X Fiche: 50-443, 83/03/04, 8303080050.

8303100157 Requests opportunity to file response to New England Coalition on Nuclear Pollution 830304 motion for deferral of consideration of motions for summary disposition or for dismissal SER (NUREG-0896) issued on 830304 W/o encl.
LESSY, R P. Hearings Division. 83/03/07. HOYT, H. ; LUEBKE, E A. ; HARBOUR, J. Atomic Safety and Licensing Board Panel. 2pp. 17485:230. 24X Fiche: 50-443, 83/03/07, 8303100157.

8303100378 Order vacating ASLB 830224 order scheduling 830317 prehearing conference. Confirms 830304 oral order granting deferral until date named for filing answers to motions for summary disposition.
HOYT, H F. Atomic Safety and Licensing Board Panel. 83/03/07. 1p. 17488:282. 24X Fiche: 50-443, 83/03/07, 8303100378.

8303140322 Forwards answer supporting New England Coalition on Nuclear Pollution 830303 motion for deferral of consideration of motions for summary disposition or for dismissal Related correspondence.
BRISBEE, G D. New Hampshire, State of. 83/03/08. Docketing & Services Branch. 1p. 17544:001. 24X Fiche: 50-443, 83/03/08, 8303140322.

--8303140327 Answer supporting New England Coalition on Nuclear Pollution 830303 motion for deferral of consideration of motions for summary disposition or for dismissal SER must be issued before ruling W/Certificate of Svc Related correspondence.
BRISBEE, G D. New Hampshire, State of. 83/03/08. Atomic Safety and Licensing Board Panel. 8pp. 17544:002. 24X Fiche: 50-443, 83/03/08, 8303140327.

8303170422 Forwards applicant answer to New England Coalition on Nuclear Power 830303 motion for deferral of consideration of motions for summary disposition or for dismissal.
GAD, R K. Ropes & Gray. GAD, R K. Public Service Co. of New Hampshire. 83/03/08. Office of the Secretary of the Commission. 1p. 17610:107. 24X Fiche: 50-443, 83/03/08, 8303170422.

--8303170426 Answer in opposition to New England Coalition on Nuclear Power 830303 motion for deferral of consideration of motions for summary disposition or for dismissal Such motions may be entertained prior to SER issuance Certificate of Svc encl.
DIGNAN, T G. ; GAD, R K. Public Service Co. of New Hampshire. DIGNAN, T G. Ropes & Gray. 83/03/08. Atomic Safety and Licensing Board Panel. 11pp. 17610:108. 24X Fiche: 50-443, 83/03/08, 8303170422.

--8303170430 Forwards applicant answer to New England Coalition on Nuclear Pollution 830303 motion for deferral of consideration of motions for summary disposition or for dismissal W/o encl.
GAD, R K. Ropes & Gray. GAD, R K. Public Service Co. of New Hampshire. 83/03/07. HOYT, H F. Atomic Safety and Licensing Board Panel. 1p. 17610:119. 24X Fiche: 50-443, 83/03/08, 8303170422.

8303170437 Response opposing Seacoast Antipollution League motion for summary disposition of Contention Suppl 3 Certificate of Svc encl Related correspondence.
DIGNAN, T G. Public Service Co. of New Hampshire. DIGNAN, T G. Ropes & Gray. 83/03/09. Atomic Safety and Licensing Board Panel. 5pp. 17609:198. 24X Fiche: 50-443, 83/03/09, 8303170437.

8303140206 Response opposing New England Coalition on Nuclear Pollution 830303 motion for deferral of consideration of pending motions for summary disposition Deadlines should be established & SER discovery denied Certificate of Svc encl.
LESSY, R P. Hearings Division. PERLIS, R G. Hearing Branch 3. 83/03/10. Atomic Safety and Licensing Board Panel. 14pp. 17540:084. 24X Fiche: 50-443, 83/03/10, 8303140206.

8303180323 Forwards supplemental answers to util interrogatories & request for production of documents Related correspondence.
BACKUS, R A. Backus, Shea & Meyer. BACKUS, R A. Seacoast Anti-Pollution League. 83/03/10. Office of the Secretary of the Commission. 1p. 17619:303. 24X Fiche: 50-443, 83/03/10, 8303180323.

--8303180329 Supplemental answers to interrogatories & request for production of documents Svc list encl Related correspondence.
BACKUS, R A. Seacoast Anti-Pollution League. BACKUS, R A. Backus, Shea & Meyer. 83/03/10. Public Service Co. of New Hampshire. 24pp. 17619:304. 24X Fiche: 50-443, 83/03/10, 8303180323.

8303230261 Forwards request to participate as interested municipality in proceedings.
MACHIROS, A. Newbury, MA. 83/03/10. HOYT, H F. Atomic Safety and Licensing Board Panel. 1p. 17662:026. 24X Fiche: 50-443, 83/03/10, 8303230261.

--8303230263 Request to participate as interested municipality in proceedings Certificate of Svc encl.
MACHIROS, A. Newbury, MA. 83/03/10. Atomic Safety and Licensing Board Panel. 2pp. 17662:027. 24X Fiche: 50-443, 83/03/10, 8303230261.

8303180151 Motion for dismissal of Hampton Beach Area Chamber of Commerce (CCCNH) 820913 contentions 5 of CCCNH as party to proceedings, due to CCCNH failure to participate in discovery Certificate of Svc encl.
DIGNAN, T G. ; GAD, R K. Public Service Co. of New Hampshire. DIGNAN, T G. Ropes & Gray. 83/03/11. Atomic Safety and Licensing Board Panel. 8pp. 17617:281. 24X Fiche: 50-443, 83/03/11, 8303180151.

8303170025 Renewed motion to dismiss Hampton Beach Chamber of Commerce (HBCC) Contention 7 & to compel HBCC answers to interrogatories on HBCC Contentions 4 & 5 HBCC failed to answer interrogatories as ordered by ASLB.
LESSY, R P. Hearings Division. PERLIS, R G. ; PATTERSON, W F. Hearing Branch 3. 83/03/15. Atomic Safety and Licensing Board Panel. 8pp. 17608:324. 24X Fiche: 50-443, 83/03/15, 8303170025.

--8303170030 Response to interrogatories & request for production of documents Certificate of Svc encl.
HOLLINGSWORTH Hampton Beach Area Chamber of Commerce, Hampton, NH. 83/02/26. Office of the Executive Legal Director. 5pp. 17608:332. 24X Fiche: 50-443, 83/03/15, 8303170025.

8303230212 Objection to applicant 830214 21st motion for summary disposition of New England Coalition on Nuclear Pollution Contentions III.12 & III.13 Related correspondence.
BACKUS, R A. Seacoast Anti-Pollution League. BACKUS, R A. Backus, Shea & Meyer. 83/03/15. Atomic Safety and Licensing Board Panel. 5pp. 17665:103. 24X Fiche: 50-443, 83/03/15, 8303230212.

--8303230216 Motion for change of prehearing conference location. Conference should be held within plume emergency planning zone for convenience of petitioners & board members Svc list encl.
BACKUS, R A. Seacoast Anti-Pollution League. BACKUS, R A. Backus, Shea & Meyer. 83/03/18. Atomic Safety and Licensing Board Panel. 3pp. 17665:108. 24X Fiche: 50-443, 83/03/15, 8303230212.

8303180143 Telecopy order rescheduling prehearing conference for 830407 & ruling on New England Coalition on Nuclear Pollution 830303 motion for deferral of consideration of motions for summary disposition or for dismissal.
HOYT, H F. Atomic Safety and Licensing Board Panel. 83/03/16. Public Service Co. of New Hampshire. 6pp. 17617:238. 24X Fiche: 50-443, 83/03/16, 8303180143.

8303180148 Order scheduling 830407-08 prehearing conference. Parties directed to be prepared to discuss pending motions for summary disposition & adjustments to 820910 schedule.
HOYT, H. F. Atomic Safety and Licensing Board Panel. 83/03/16. 2pp. 17617:279. 2[illegible] Fiche: 50-443, 83/03/16, 8303180148.

8303230251 Forwards State of NH supplemental response to 821208 interrogatories & requests for production of documents. Related correspondence.
BISBEE, G. D. New Hampshire, State of. 83/03/16. Docketing & Services Branch. 1p. 17661:161. 24X Fiche: 50-443, 83/03/16, 8303230251.

--8303230256 Supplemental response to 821208 interrogatories & requests for production of documents. Certificate of Svc encl. Related correspondence.
BISBEE, G. D. New Hampshire, State of. FAN, S. S. New Hampshire, Univ. of. 83/03/16. Public Service Co. of New Hampshire. 5pp. 17661:162. 24X Fiche: 50-443, 83/03/16, 8303230251.

8303220254 Order directing util either to provide New England Coalition on Nuclear Pollution draft reactor vessel exam plan or provide date when plan will be submitted. Grants motion to compel more accurate & specific answer to Interrogatory 7.
HOYT, H. F. Atomic Safety and Licensing Board Panel. 83/03/17. Public Service Co. of New Hampshire. 2pp. 17656:248. 24X Fiche: 50-443, 83/03/17, 8303220254.

8303220273 Order ruling on New England Coalition on Nuclear Pollution 830216 motion to compel answers to interrogatories. Motion re Interrogatory 7 denied. Ruling re Interrogatory 17 deferred. Interrogatory 21 moot.
HOYT, H. F. Atomic Safety and Licensing Board Panel. 83/03/17. New England Coalition on Nuclear Pollution. 3pp. 17656:211. 24X Fiche: 50-443, 83/03/17, 8303220273.

8303220168 Order admitting Town of Newbury, MA as interested municipality. Town must observe procedural requirements & take proceeding as found.
HOYT, H. F. Atomic Safety and Licensing Board Panel. 83/03/18. Newbury, MA. 10pp. 17658:157. 24X Fiche: 50-443, 83/03/18, 8303220168.

8303220234 Motion to relocate 830407-08 prehearing conference set in Boston, MA to site within 10 miles of plant. Holding conference 50 miles from affected area unfair & inconsistent w/Commission practices. Certificate of Svc encl.
CURRAN, D., JORDAN, W. S. New England Coalition on Nuclear Pollution.
CURRAN, D. Harmon & Weiss. 83/03/18. Atomic Safety and Licensing Board Panel. 5pp. 17657:278. 24X Fiche: 50-443, 83/03/18, 8303220234.

8303220245 Motion to extend deadline until 830517 for final discovery requests re emergency planning contentions admitted by ASLB on 821117. Related correspondence.
JORDAN, W. S., CURRAN, D. New England Coalition on Nuclear Pollution.
JORDAN, W. S. Harmon & Weiss. 83/03/18. Atomic Safety and Licensing Board Panel. 2pp. 17657:309. 24X Fiche: 50-443, 83/03/18, 8303220245.

8303230219 Notice of withdrawal of EJ McDermott & AC Thompson appearances in proceeding.
THOMPSON, A. C. South Hampton, NH. THOMPSON, A. C. Sanders & McDermott. 83/03/18. 1p. 17665:193. 24X Fiche: 50-443, 83/03/18, 8303230219.

8303230221 Notice of withdrawal of LM Edelman & WL Sanders appearances in proceeding.
EDELMAN, L. M. Sanders & McDermott. 83/03/18. 1p. 17665:188. 24X Fiche: 50-443, 83/03/18, 8303230221.

8303240430 Motion for clarification of ASLB 830117 order. Thirty-day period for filing contentions on emergency planning should not be triggered by receipt of City of Newburyport, MA draft emergency plan. Moves for stay of contention filing deadline.
SHOTWELL, J. A. Massachusetts, Commonwealth of. 83/03/18. Atomic Safety and Licensing Board Panel. 6pp. 17679:001. 24X Fiche: 50-443, 83/03/18, 8303240430.

--8303240435 Advises that City of Newburyport, MA has not reviewed or approved draft emergency plan for City. Plan should not be treated as City emergency plan.
SULLIVAN, R. E. Newburyport, MA. 83/03/14. HOYT, H., LUEBKE, E. A., HARBOUR, J. Atomic Safety and Licensing Board Panel. 2pp. 17679:007. 24X Fiche: 50-443, 83/03/18, 8303240430.

--8303240445 Informs that emergency plan submitted to FEMA was not meant to be submitted to NRC or to initiate formal litigation. Plan submitted to obtain initial reactions of federal radiological assistance committee. W/Certificate of Svc.
DOLAN, J. C. Massachusetts, Commonwealth of. 83/03/17. HOYT, H., LUEBKE, E., HARBOUR, J. Atomic Safety and Licensing Board Panel. 3pp. 17679:009. 24X Fiche: 50-443, 83/03/18, 8303240430.

8303230019 Response to Town of Newbury, MA 830310 request to participate as interested municipality. NRC does not oppose admission if subj to conditions of observing procedural requirements & taking hearing as found. W/Certificate of Svc.
PATTERSON, W. F. Hearing Branch 3. 83/03/21. Atomic Safety and Licensing Board Panel. 4pp. 17665:034. 24X Fiche: 50-443, 83/03/21, 8303230019.

8303230039 Response to applicant 830211 fifth motion for summary disposition of State of NH Contention 9. Supports disposition of portions of contentions re NUREG-0737, Items II.B.2, II.F.1, III.D.1.1, III.D.3.3 & III.D.3.4. W/Certificate of Svc.
PERLIS, R. G. Hearing Branch 3. LESSY, R. P. Hearings Division. 83/03/21. Atomic Safety and Licensing Board Panel. 8pp. 17663:236. 24X Fiche: 50-443, 83/03/21, 8303230039.

8303250164 Answer opposing applicant nineteenth motion for summary disposition of Contention SAPL Suppl III. Applicant statement of matl fact fails to address compliance & adequacy w/policy statement. W/svc list. Related correspondence.
BACKUS, R. A. Seacoast Anti-Pollution League. BACKUS, R. A. Backus, Shea & Meyer. 83/03/21. Atomic Safety and Licensing Board Panel. 8pp. 17691:140. 24X Fiche: 50-443, 83/03/21, 8303250164.

8303230191 Forwards response to MA Atty General Bellutti motion for clarification of ASLB 830117 order & for immediate stay of filing deadline for contentions on emergency planning for City of Newburyport.
GAD, R. K. Ropes & Gray. GAD, R. K. Public Service Co. of New Hampshire. 83/03/22. Office of the Secretary of the Commission. 1p. 17665:212. 24X Fiche: 50-443, 83/03/22, 8303230191.

--8303230199 Response in opposition to MA Atty General Bellotti motion for clarification of ASLB 830117 order & for immediate stay of filing deadline for contentions on emergency planning for City of Newburyport. Certificate of Svc encl.
DIGNAN, T. G., GAD, R. K. Public Service Co. of New Hampshire.
DIGNAN, T. G. Ropes & Gray. 83/03/22. Atomic Safety and Licensing Board Panel. 9pp. 17665:213. 24X Fiche: 50-443, 83/03/22, 8303230191.

8303240411 Order delineating agenda for 830407-08 prehearing conference. Agenda will include pending motions for summary disposition, adjustments to schedule & matters pertaining to admitted contentions. FEMA to participate on 830408.
HOYT, H. F. Atomic Safety and Licensing Board Panel. 83/03/22. 2pp. 17679:065. 24X Fiche: 50-443, 83/03/22, 8303240411.

8303250163 Corrects address for Sun Valley Assoc as noted in 830318 notice of withdrawal of appearance.
EDELMAN, L. M. Sanders & McDermott. 83/03/22. Docketing & Services Branch. 1p. 17691:148. 24X Fiche: 50-443, 83/03/22, 8303250163.

8303290432 Requests that public hearing on evacuation plans be scheduled for seacoast area.
CANNEY, C. A. Portsmouth, NH. 83/03/22. HOYT, H., LUEBKE, E. A., HARBOUR, J. Atomic Safety and Licensing Board Panel. 1p. 17725:324. 24X Fiche: 50-443, 83/03/22, 8303290432.

8303240022 Response opposing Seacoast Anti-Pollution League 830211 motion for summary disposition of Contention SAPL Suppl 3. League has not shown that FES does not comply w/Commission interim policy statement on serious accidents.
LESSY, R. P. Hearings Division. PERLIS, R. G. Hearing Branch 3. 83/03/23. Atomic Safety and Licensing Board Panel. 10pp. 17681:075. 24X Fiche: 50-443, 83/03/23, 8303240022.

--8303240024 Affidavit of JA Mitchell re Seacoast Anti-Pollution League 830211 motion for summary disposition. Evacuation study calculations provide perspective of risks at site as stated in FES. Certificate of Svc encl.
MITCHELL, J. A. Accident Evaluation Branch. 83/03/22. 8pp. 17681:085. 24X Fiche: 50-443, 83/03/23, 8303240022.

8303240318 Response to Commonwealth of MA 830318 motion for clarification of ASLB 830117 order & for stay of filing deadline for contentions on City of Newbury, MA emergency plan. Opposes stay. Certificate of Svc encl.
PERLIS, R. G. Hearing Branch 2. 83/03/23. Atomic Safety and Licensing Board Panel. 8pp. 17679:344. 24X Fiche: 50-443, 83/03/23, 8303240318.

8303250153 Forwards answers to util & NRC motions for summary disposition. Related correspondence.
BISBEE, G. D. New Hampshire, State of. 83/03/23. Docketing & Service Branch. 1p. 17691:084. 24X Fiche: 50-443, 83/03/23, 8303250153.

--8303250154 Answer opposing util & NRC motions for summary disposition of Contention NECNP-I.B.1 re RHR sys. Factual dispute exists over adequacy of steam generators to provide RHR capability. Related correspondence.
BISBEE, G.D. New Hampshire, State of 83/03/23 Atomic Safety and Licensing Board Panel 3pp 17691:085 24X Fiche: 50-443, 83/03/23, 8303250153.

--8303250158 Affidavit of SS Fan re steam generator tube integrity. RHR sys design should be studied to assess design limitations & effectiveness of sys & to determine if addl means of RHR needed to ensure sys adequacy.
FAN, S.S. New Hampshire, State of 83/03/23 2pp 17691:088 24X Fiche: 50-443, 83/03/23, 8303250153.

--8303250162 Answer to util motion for full summary disposition & NRC motion for partial summary disposition of Contention NH-13. Opposes disposition of NUREG-0737, Items I.C.1 & I.A.I.1 but not II.B.4. Related correspondence.
BISBEE, G.D. New Hampshire, State of 83/03/23 Atomic Safety and Licensing Board Panel 4pp 17691:090 24X Fiche: 50-443, 83/03/23, 8303250153.

--8303250166 Answer opposing applicant nineteenth motion for summary disposition of Contention SAPL Suppl III Genuine issues of fact remain re NRC 800613 policy statement. Related correspondence.
BISBEE, G.D. New Hampshire, State of 83/03/23 Atomic Safety and Licensing Board Panel 4pp 17691:094 24X Fiche: 50-443, 83/03/23, 8303250153.

--8303250168 Affidavit of SS Fan. Until NRC properly considers Class 9 accidents & identifies addl features or other actions which would prevent or mitigate consequences of serious accidents, NRC will not comply w/NRC 800613 policy statement.
FAN, S.S. New Hampshire, State of 83/03/23 2pp 17691:098 24X Fiche: 50-443, 83/03/23, 8303250153.

--8303250170 Answer opposing applicant seventh motion for summary disposition of Contentions NH-21 & CCCNP-5. Motion premature & should be held in abeyance. Discovery not completed. Issues of fact still in dispute. Related correspondence.
BISBEE, G.D. New Hampshire, State of 83/03/23 Atomic Safety and Licensing Board Panel 6pp 17691:100 24X Fiche: 50-443, 83/03/23, 8303250153.

--8303250171 Answer to applicant fifth motion for summary disposition of Contention NH-9. Motion should be held in abeyance since discovery not complete or should be denied as to NUREG-0737, Item II.B.3 W/Certificate of Svc. Related correspondence.
BISBEE, G.D. New Hampshire, State of 83/03/23 Atomic Safety and Licensing Board Panel 5pp 17691:106 24X Fiche: 50-443, 83/03/23, 8303250153.

8303250147 Order denying State of MA 830318 motion for clarification of ASLB 830117 order. Plain language of order identified triggering event for filing emergency planning contentions. Extension to file contentions until 830328 granted.
HOYT, H.F. Atomic Safety and Licensing Board Panel 83/03/24 2pp 17691:012 24X Fiche: 50-443, 83/03/24, 8303250147.

8303290445 Forwards applicant response to New England Coalition on Nuclear Pollution motion to extend emergency planning discovery deadline.
GAD, R.K. Ropes & Gray GAD, R.K. Public Service Co. of New Hampshire 83/03/24 Office of the Secretary of the Commission 1p 17725:341 24X Fiche: 50-443, 83/03/24, 8303290445.

--8303290449 Response to New England Coalition on Nuclear Pollution motion to extend emergency planning discovery deadline. Insufficient basis shown for relief requested, but no objection posed. Certificate of Svc encl.
DIGNAN, T.G., GAD, R.K. Public Service Co. of New Hampshire
DIGNAN, T.G. Ropes & Gray 83/03/24 Atomic Safety and Licensing Board Panel 7pp 17725:342 24X Fiche: 50-443, 83/03/24, 8303290445.

8303290516 Order denying New England Coalition on Nuclear Pollution & Seacoast Anti-Pollution League 830318 motions to relocate prehearing conference.
HOYT, H.F. Atomic Safety and Licensing Board Panel 83/03/24 New England Coalition on Nuclear Pollution 1p 17725:111 24X Fiche: 50-443, 83/03/24, 8303290516.

8303290525 Memorandum & order granting portion of applicant 830128 motion to compel answers to interrogatories & denying portion of New England Coalition on Nuclear Pollution 830216 request for protective order.
HOYT, H.F. Atomic Safety and Licensing Board Panel 83/03/24
Public Service Co. of New Hampshire 15pp 17724:099 24X Fiche: 50-443, 83/03/24, 8303290525.

8303290536 Response opposing util & NRC motions for summary disposition of Contentions I.A.2.1.B.1, I.D.2.1.G, II.B.3 & II.B.4. Some contentions withdrawn since discovery satisfied concerns. W/Certificate of Svc. Related correspondence.
CURRAN, D. New England Coalition on Nuclear Pollution CURRAN, D.
Harmon & Weiss 83/03/24 Atomic Safety and Licensing Board Panel 45pp 17724:114 24X Fiche: 50-443, 83/03/24, 8303290536.

8303310313 Order denying New England Coalition on Nuclear Pollution 830318 motion to extend emergency planning deadline until 830517. No good cause shown for request.
HOYT, H.F. Atomic Safety and Licensing Board Panel 83/03/30 New England Coalition on Nuclear Pollution 2pp 17755:047 24X Fiche: 50-443, 83/03/30, 8303310313.

H. General correspondence

8303070156 Requests all future NRC correspondence be directed to RJ Harrison & document svc to WC Tallman be discontinued.
DEVINCENTIS, J. Yankee Atomic Electric Co. 83/03/01 KNIGHTON, G.W. Licensing Branch 3 2pp 17433:354 24X Fiche: 50-443, 83/03/01, 8303070156.

Q. Inspection reports, IE Bulletins & correspondence

8302180214 Forwards IE Insp Repts 50-443/82-16 & 50-444/82-14 on 821221-830117 & notice of violation.
STAROSTECKI, R. Division of Project & Resident Programs 83/02/03
TALLMAN, W.C. Public Service Co. of New Hampshire 2pp 17215:314 24X Fiche: 50-443, 83/02/03, 8302180214.

--8302180224 IE Insp Repts 50-443/82-16 & 50-444/82-14 on 821221-830117. Noncompliance noted: failure to assure installation of Class IE cable in seismically qualified raceway sys.
CERNE, A.C., GRAMM, R.A., GALLO, R.M. Division of Project & Resident Programs 83/01/30 1p 17215:317 24X Fiche: 50-443, 83/02/03, 8302180214.

8303100275 Forwards IE Insp Repts 50-443/83-01 & 50-444/83-01 on 830117-21. No noncompliance noted.
MARTIN, T.T. Division of Engineering & Technical Programs 83/02/23
TALLMAN, W.C. Public Service Co. of New Hampshire 2pp 17489:307 24X Fiche: 50-443, 83/02/23, 8303100275.

--8303100281 IE Insp Repts 50-443/83-01 & 50-444/83-01 on 830117-21. No noncompliance noted. Major areas inspected: work activities, procedures & records re pipe support installation & return end (boxing) welding concerning hanger fabrication.
REYNOLDS, S.D., DURR, J. Region 1, Office of Director 83/02/17
6pp 17489:309 24X Fiche: 50-443, 83/02/23, 8303100275.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc.
111pp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc.
117pp 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8303220139 Ack receipt of 830303 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/82-16 & 50-444/82-14. Future corrective actions will include development of computer program re cable crossings.
STAROSTECKI, R. Division of Project & Resident Programs 83/03/17
HARRISON, R.J. Public Service Co. of New Hampshire 2pp 17657:247 24X Fiche: 50-443, 83/03/17, 8303220139.

--8303220148 Responds to NRC 830203 ltr re violations noted in IE Insp Repts 50-443/82-16 & 50-444/82-14. Corrective actions: cable installer issued interim procedure change requiring cable pull slips w/mixed raceway be returned for evaluation.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/03/03 STAROSTECKI, R. Division of Project & Resident Programs 3pp 17657:249 24X Fiche: 50-443, 83/03/17, 8303220139.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

B. Reportable occurrences, LERs & related correspondence

8303140607 Part 21 rept re defect in UHS svc water cooling tower structure. Structure will be modified to accommodate transverse shear forces. Design of mods will be completed by 830331.
SARSTEN, G. E. United Engineers & Constructors, Inc. (subs. of Raytheon Co.) 83/03/07 Director's Office, Office of Inspection and Enforcement 3pp 17534:030 24X Fiche: 50-443, 83/03/07, 8303140607.

8303240366 Final deficiency rept re intermittent lock-up of GA Co radiation monitoring display RM-23. Initially reported on 830215. GA Co reviewing RM-23 design & conducting addl tests. Also reportable per Part 21.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/03/16 STAROSTECKI, R. Division of Project & Resident Programs 2pp 17682:005 24X
Fiche: 50-443, 83/03/16, 8303240366.

8303240441 Interim deficiency rept re power transistor heat sink separation from transistors in Westinghouse 7300 series process I&C sys cabinets. Initially reported on 830216. Evaluation results expected by 830515.
DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/03/18 STAROSTECKI, R. Division of Project & Resident Programs 2pp 17678:345 24X
Fiche: 50-443, 83/03/18, 8303240441.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA., UNIT 1

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303010642 Reviews environ qualification audit, accounting for post-accident operability. Qualification documentation for large pump motors revised to reflect new calculations accounting for 5-yr qualified life.
SCHMIDT, H. C. Texas Utilities Services, Inc. 83/02/23
YOUNGBLOOD, B. J. Licensing Branch 1 2pp 17336:120 24X
Fiche: 50-445, 83/02/23, 8303010642.

8303030018 Forwards list of safety-related electrical equipment to be included in environ qualification files.
SCHMIDT, H. C. Texas Utilities Services, Inc. 83/02/24
YOUNGBLOOD, B. J. Licensing Branch 1 119pp 17413:001 24X
Fiche: 50-445, 83/02/24, 8303030018.

8303250023 Forwards Rev 0 to nonproprietary WCAP-8587, Suppl 1, "Equipment Qualification Data Packages" & proprietary WCAP-8687, Suppl 2 "Equipment Qualification Test Repts." Proprietary repts withheld (ref 10CFR2.790).
RAHE, E. P. Westinghouse Electric Corp. 83/02/28 THOMAS, C. O. Standardization & Special Projects Branch 7pp 17691:320 24X
Fiche: 50-445, 83/02/28, 8303250023.

8303110215 Describes how station has satisfied human factors guidance re sys function task analysis. Plant-specific emergency response guidelines procedure prepared per NUREG-0899 to determine discrepancies w/control board.
SCHMIDT, H. C. Texas Utilities Generating Co. 83/03/01
YOUNGBLOOD, B. J. Licensing Branch 1 7pp 17519:297 24X
Fiche: 50-445, 83/03/01, 8303110215.

8303240121 Summary of 830228 meeting w/util in Bethesda, MD re status of const & preoperational testing program & projection for fuel load date. Fuel load expected by mid-Sept 1983.
BURWELL, S. B. Licensing Branch 1 83/03/03 Licensing Branch 1
8pp 17698:347 24X Fiche: 50-445, 83/03/03, 8303240121.

8303140615 Requests telephone notification with 10 days & written application within 30 days to withhold proprietary info contained in rept, "Comanche Peak Steam Electric Station, Design & Const Self-Initiated Evaluation, Oct 1982."
NOVAK, T. M. Assistant Director for Licensing 83/03/04 GARY, R. J. Texas Utilities Generating Co. 3pp 17548:352 24X
Fiche: 50-445, 83/03/04, 8303140615.

8303100141 Forwards 830304 ltr to util re proprietary nature of "Comanche Peak Steam Electric Station, Design & Const Self-Initiated Evaluation, Oct 1982."
ROTHSCHILD, M. U. Hearing Branch 1 83/03/08 MILLER, M. E., JORDAN, W. H., MCCOLLOM, K. A. Atomic Safety and Licensing Board Panel.
4pp 17485:254 24X Fiche: 50-445, 83/03/08, 8303100141.

8303140340 Discusses position indication for steam generator safety valves. Commits to installation of accident monitoring indicators during first refueling outage.
SCHMIDT, H. C. Texas Utilities Services, Inc. 83/03/08
YOUNGBLOOD, B. J. Licensing Branch 1 2pp 17534:229 24X
Fiche: 50-445, 83/03/08, 8303140340.

8303230381 Notification of 830310 meeting w/util in Bethesda, MD to discuss plan for independent design verification program.
BURWELL, S. B. Licensing Branch 1 83/03/08 YOUNGBLOOD, B. J. Licensing Branch 1 3pp 17675:262 24X Fiche: 50-445, 83/03/08, 8303230381.

8303240116 Summary of 821118 meeting w/util in Bethesda, MD re clarification of NRC requirements concerning independent design verification program.
BURWELL, S. B. Licensing Branch 1 83/03/08 Licensing Branch 1
4pp 17698:355 24X Fiche: 50-445, 83/03/08, 8303240116.

8303150340 Advises of 830405 meeting w/licensees & major contractors at Dallas/Fort Worth, TX to provide info & guidance re 10CFR50 QA & Tech Spec deviations & discuss decentralization policy. Questions should be submitted in writing by 830321.
COLLINS, J. T. Region 4, Office of Director 83/03/10 Public Service Co. of Colorado 12pp 17562:291 24X
Fiche: 50-000, 83/03/10, 8303150340.

8303150283 Notifies of 830405 public meeting at Dallas/Ft Worth, TX Airport re decentralization policy & 10CFR50 reporting requirements.
COLLINS, J. T. Region 4, Office of Director 83/03/11 GARY, R. J. Texas Utilities Generating Co. 3pp 17567:044 24X
Fiche: 50-445, 83/03/11, 8303150283.

8303240163 Notification of 830324-25 meetings w/util in Rockford, IL to discuss status of const & completion schedules for facilities.
OLSHAM, L. N. Licensing Branch 1 83/03/11 YOUNGBLOOD, B. J. Licensing Branch 1 6pp 17696:353 24X Fiche: 50-445, 83/03/11, 8303240163.

8303290730 Requests determination of eligibility of May House for inclusion in Natl Register of Historic Places. Detailed info encl. W/o encls.
YOUNGBLOOD, B. J. Licensing Branch 1 83/03/14 ROGERS, J. Interior, Dept. of, National Park Service 1p 17748:044 24X
Fiche: 50-445, 83/03/14, 8303290730.

8303290661 Notification of 830331 meeting w/util in Bethesda, MD to discuss plans for independent design verification program.
BURWELL, S. B. Licensing Branch 1 83/03/21 YOUNGBLOOD, B. J. Licensing Branch 1 3pp 17742:350 24X Fiche: 50-445, 83/03/21, 8303290661.

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303290691 Forwards Suppl 3 to SER re operation of facilities. W/o encl.
YOUNGBLOOD, B. J. Licensing Branch 1 83/03/11 GARY, R. J. Texas Utilities Generating Co. 2pp 17745:120 24X Fiche: 50-445, 83/03/11, 8303290691.

8303220010 Forwards Rev 3 to Procedure ODA-302, "Relief of Personnel." Procedure includes auxiliary operator relief checklists & completes response to SER, NUREG-0797, Item I.C.2.
MARSHALL, J. S. Texas Utilities Generating Co. 83/03/16
CROCKER, L. P. Division of Human Factors Safety 1p 17652:082 24X
Fiche: 50-445, 83/03/16, 8303220010.

--8303220014 Rev 3 to Procedure ODA-302, "Relief of Personnel."
* Texas Utilities Generating Co 83/01/26 26pp 17652:083
24X Fiche: 50-445, 83/03/16, 8303220010.

8303300176 Forwards Suppl 3 to SER (NUREG-0797) W/o encl.
YOUNGBLOOD, B. J. Licensing Branch 1 83/03/22 GARY, R. J. Texas Utilities Generating Co. 2pp 17763:086 24X Fiche: 50-445, 83/03/22, 8303300176.

F. Security, medical, emergency & fire protection plans

8303140324 Submits guidance on location of emergency notification sys & health physics network in emergency response facilities, per NUREG-0696.
COLLINS, J T. Region 4, Office of Director. 83/02/24. GARY, R J. Texas Utilities Generating Co. 2pp. 17544:011. 24X Fiche: 50-145, 83/02/24, 8303140324.

8303220105 Forwards Amend 39 to FSAR, consisting of Rev 6 to emergency plan. Affidavit encl.
GARY, R J. Texas Utilities Generating Co. 83/03/08. DENTON, H R. Office of Nuclear Reactor Regulation, Director. 2pp. 17649:001. 24X Fiche: 50-445, 83/03/08, 8303220105.

--8303220128 Amend 39 to FSAR, consisting of Rev 6 to emergency plan.
JONES, R A. Texas Utilities Generating Co. 83/03/08. 195pp. 17649:003. 24X Fiche: 50-445, 83/03/08, 8303220105.

8303220188 Describes alternate shutdown design for associatwd circuits during fire in cuntrol room or cable spreading room. Alternate shutdown circuits independent of cables, sys & components in cable spreading room & control room.
SCHMIDT, H C. Texas Utilities Services, Inc. 83/03/18.
YOUNGBLOOD, B J. Licensing Branch 1. 2pp. 17658:147. 24X Fiche: 50-445, 83/03/18, 8303220188.

8303220387 Describes alternate reactor shutdown for fire in control room or cable spreading room. Design & procedures adequately assure reactor shutdown throughout duration of cable spreading room or control room fire scenario.
SCHMIDT, H C. Texas Utilities Services, Inc. 83/03/18.
YOUNGBLOOD, B J. Licensing Branch 1. 2pp. 17648:355. 24X Fiche: 50-445, 83/03/18, 8303220387.

8303290231 Discusses repts from utils re telephonic inquiries from unidentified persons about security sys. Calls made by personnel recruiter attempting to locate personnel familiar w/particular computer. Recruiter admonished.
COLLINS, J T. Region 4, Office of Director. 83/03/25. GARY, R J. Texas Utilities Generating Co. 2pp. 17722:231. 24X Fiche: 50-445, 83/03/25, 8303290231.

8303310100 Releases public version of revised emergency plan.
FELTON, J M. Division of Rules and Records. 83/03/28. Document Management Branch. 1p. 17777:162. 24X Fiche: 50-445, 83/03/28, 8303310100.

--8303310105 Forwards public version of Rev 6 to emergency plan, consisting of Amend 39 to FSAR. Return receipt requested.
SMART, T L. Texas Utilities Services, Inc. 83/03/08. DENTON, H R. Office of Nuclear Reactor Regulation, Director. 2pp. 17777:163. 24X Fiche: 50-445, 83/03/28, 8303310100.

Q. Adjudicatory correspondence

8303100256 Suggests that performance of siren early warning sys totally unacceptable. Sirens cannot be heard by many citizens.
CRUMP, G R. Somervell County, TX. 83/02/21. MILLER, M E. Atomic Safety and Licensing Board Panel. 1p. 17489:356. 24X Fiche: 50-445, 83/02/21, 8303100256.

8303010084 Informs of applicant release of IE rept to press before receipt by intervenors. Applicant timing is prejudicing case.
ELLIS, J. Citizens Association for Sound Energy. 83/02/24.
MILLER, M E., COLE, R F., MCCOLLOM, K A. Atomic Safety and Licensing Board Panel. 2pp. 17335:348. 24X Fiche: 50-445, 83/02/24, 8303010084.

8303010105 Provisional proposed findings of fact. Certificate of Svc encl.
ELLIS, J. Citizens Association for Sound Energy. 83/02/24. 65pp. 17369:038. 24X Fiche: 50-445, 83/02/24, 8303010105.

8303010276 Motion for 21-day extension to file addl provisional proposed findings of fact & to suspend discovery on issues until 830329. Delay due to unreasonable work load & complexity of issues. Certificate of Svc encl.
ELLIS, J. Citizens Association for Sound Energy. 83/02/24. Atomic Safety and Licensing Board Panel. 8pp. 17335:085. 24X Fiche: 50-445, 83/02/24, 8303010276.

8303010401 Notice of ASLB reconstitution: ME Miller, Chairman; RA McCollom & WH Jordan, members.
COTTER, B P. Atomic Safety and Licensing Board Panel. 83/02/24. 2pp. 17346:213. 24X Fiche: 50-445, 83/02/24, 8303010401.

8303010315 Motion for admission of JT Merritt affidavit re structural integrity tests. Results confirm structural integrity of containment, including repaired portion of Unit 1 dome.
REYNOLDS, N S., HORIN, W A. Texas Utilities Generating Co.
REYNOLDS, N S. Debevoise & Liberman. 83/02/25. Atomic Safety and Licensing Board Panel. 2pp. 17345:218. 24X Fiche: 50-445, 83/02/25, 8303010316.

--8303010328 Affidavit of JT Merritt re structural integrity test. Results confirm structural integrity of containment dome, including repaired portion of Unit 1 dome. Certificate of Svc encl.
MERRITT, J T. Texas Utilities Generating Co. 83/02/23. 4pp. 17345:220. 24X Fiche: 50-445, 83/02/25, 8303010316.

8303010333 Proposed findings of fact in form of partial initial decision. Certificate of Svc encl.
REYNOLDS, N S., HORIN, W A. Texas Utilities Generating Co.
REYNOLDS, N S. Debevoise & Liberman. 83/02/25. 182pp. 17346:236. 24X Fiche: 50-445, 83/02/25, 8303010333.

8303020067 Memorandum & order denying & striking from record Citizens Assoc for Sound Energy, util & NRC motions, responses to motions & filings. Prolix motions irrelevant to issues & beyond scope of ASLB function or jurisdiction.
MILLER, M E. Atomic Safety and Licensing Board Panel. 83/03/01.
Citizens Association for Sound Energy. 6pp. 17352:078. 24X Fiche: 50-445, 83/03/01, 8303020067.

8303020071 Application for stay of effectiveness of ALAB-714. Disclosure of informants could harm Commission investigative ability & would be contrary to Commission policy favoring informant confidentiality. Certificate of Svc encl.
CUNNINGHAM, G H. Office of the Executive Legal Director. TURK, S E. Hearing Branch 1. 83/03/01. Commissioners. 14pp. 17352:171. 24X Fiche: 50-445, 83/03/01, 8303020071.

8303030447 Memorandum & Order ALAB-716 denying NRC 830225 motion for stay of effectiveness of ALAB-714, requiring disclosure of informants. NRC would not be irreparably injured. Argument is frivolous.
SHOEMAKER, C J. Atomic Safety and Licensing Appeal Panel. 83/03/01.
Office of the Executive Legal Director. 7pp. 17410:061. 24X Fiche: 50-445, 83/03/01, 8303030447.

8303040330 Forwards NRC 830224 provisional proposed findings of fact. W/o encl.
ROTHSCHILD, M U. Hearing Branch 1. 83/03/02. JORDAN, W H. Atomic Safety and Licensing Board Panel. 1p. 17420:071. 24X Fiche: 50-445, 83/03/02, 8303040330.

6303040625 Response to ASLB 830217 order requesting info re const completion date for Unit 1. Fuel load scheduled for Dec 1983.
ROTHSCHILD, M U. Hearing Branch 1. 83/03/03. 2pp. 17374:240. 24X Fiche: 50-445, 83/03/03, 8303040625.

--8303040633 Affidavit of SB Burwell re const completion date for Unit 1. Fuel load scheduled for Dec 1983. Prof qualifications & Certificate of Svc encl.
BURWELL, S B. Licensing Branch 1. 83/03/03. 25pp. 17374:242. 24X Fiche: 50-445, 83/03/03, 8303040625.

8303070122 Response to AELB order requesting repts on current best projections of plant completion date. Risk of not completing licensing process prior to plant completion not eliminated. Certificate of Svc encl.
REYNOLDS, N S., HORIN, W A. Texas Utilities Generating Co.
REYNOLDS, N S. Debevoise & Liberman. 83/03/03. 8pp. 17433:080. 24X Fiche: 50-445, 83/03/03, 8303070122.

8303080024 Requests amend to svc list to include RJ Gray.
REYNOLDS, N S. Debevoise & Liberman. REYNOLDS, N S. Texas Utilities Generating Co. 83/03/03. MILLER, M E., JORDAN, W H., MCCOLLOM, K A. Atomic Safety and Licensing Board Panel. 1p. 17455:351. 24X Fiche: 50-445, 83/03/03, 8303080024.

8303080172 Notice of resumption of hearing on 830404 in Fort Worth, TX covering all matters in controversy not completed. NRC should prepare & ser. subpoenas for appearance of listed persons as ASLB witnesses.
MILLER, M E. Atomic Safety and Licensing Board Panel. 83/03/04. 15pp. 17457:105. 24X Fiche: 50-445, 83/03/04, 8303080172.

8303080462 Order CLI-83-6, granting NRC 830301 application for stay of effectiveness of ALAB-714 pending filing & resolution of appeal. Disclosure of informants will irreparably alter status quo.
CHILK, S J. Office of the Secretary of the Commission. 83/03/04.
Office of the Executive Legal Director. 3pp. 17451:348. 24X Fiche: 50-445, 83/03/04, 8303080462.

# DOCKETED ITEMS

8303100141 Forwards 830304 ltr to util re proprietary nature of "Comanche Peak Steam Electric Station, Design & Const Self-Initiated Evaluation, Oct 1982." ROTHSCHILD, M. U. Hearing Branch 1 83/03/08 MILLER, M. E. JORDAN, W. H., MCCOLLOM, K. A. Atomic Safety and Licensing Board Panel 4pp 17485.254 24X Fiche. 50-445, 83/03/08, 8303100141.

8303110195 Memorandum & order memorializing 830308 conference call re matters to be covered during scheduled wk of resumed hearing beginning on 830404. MILLER, M. E. Atomic Safety and Licensing Board Panel 83/03/09 4pp 17520.118 24X Fiche. 50-445, 83/03/09, 8303110195.

8303150127 Petition for review of ALAB-714 re disclosure of informants. Decision contains significant errors & establishes unacceptable policy & procedural precedent. Identities are not known for certain. Certificate of Svc encl. CUNNINGHAM, G. H. Office of the Executive Legal Director TURK, S. E. Hearing Branch 1 83/03/11 Commissioners 12pp 17549.044 24X Fiche. 50-445, 83/03/11, 8303150127.

8303160534 Confirms 830404-08 hearing in Forth Worth, TX. ASLB requested FEMA interim findings be entered into record. ASLB wants to inquire into new info in findings re availability of & alternatives to EBS sys & County judges advisory info. MIZUNO, G. S. Hearing Branch 1 83/03/11 LOOKABAUGH, A., BENTON, J., PERRY, S. Federal Emergency Management Agency 1p 17592.337 24X Fiche. 50-445, 83/03/11, 8303160534.

8303180380 Provides list of documents requested under ASLB informal discovery. Related correspondence. ELLIS, J. Citizens Association for Sound Energy 83/03/11 REYNOLDS, N. S. Debevoise & Liberman 17pp 17622.249 24X Fiche. 50-445, 83/03/11, 8303180380.

8303180385 Requests svc list be amended to include LA Sinkin. ELLIS, J. Citizens Association for Sound Energy 83/03/11 Atomic Safety and Licensing Board Panel 1p 17621.345 24X Fiche. 50-445, 83/03/11, 8303180385.

8303180400 Forwards IE 830308 response to Citizens Assoc for Sound Energy 10CFR2.206 petition for show cause order based on util failure to have documents in possession on component design. ELLIS, J. Citizens Association for Sound Energy 83/03/11 MILLER, M. E., MCCOLLOM, K. A., JORDAN, W. H. Atomic Safety and Licensing Board Panel 4pp 17621.357 24X Fiche. 50-445, 83/03/11, 8303180400.

8303160528 Forwards photocopies of SER Suppl 3 (NUREG-0797). Bound copies will be sent when available. W/o encl. ROTHSCHILD, M. U. Hearing Branch 1 83/03/14 MILLER, M. E., JORDAN, W. H., MCCOLLOM, K. A. Atomic Safety and Licensing Board Panel 3pp 17592.278 24X Fiche. 50-445, 83/03/14, 8303160528.

8303170048 Clarifies statements made in 830311 ltr. Discovery requests may be sent in lieu of engaging in informal discovery. List of documents discussed in IE Insp Repts 50-445/82-26 & 50-446/82-26 promised in 830311 ltr not received. ROTHSCHILD, M. U. Hearing Branch 1 83/03/15 ELLIS, J. Citizens Association for Sound Energy 1p 17609.097 24X Fiche. 50-445, 83/03/15, 8303170048.

8303180406 Confirms 830315 telcon re intervenor 830311 request for documents on NRC insp of Walsh & Doyle allegations. Intervenor request for 200 categories of documents does not conform to ASLB discovery limits. Related correspondence. HORIN, W. A. Debevoise & Liberman HORIN, W. A. Texas Utilities Generating Co 83/03/15 ELLIS, J. Citizens Association for Sound Energy 1p 17622.010 24X Fiche. 50-445, 83/03/15, 8303180406.

8303220226 Motion for reconsideration re hearings on Walsh/Doyle allegations. Hearings scheduled for 830404-08 should not include allegations. Ninety days should be allotted to analyze documents. Certificate of Svc encl. ELLIS, J. Citizens Association for Sound Energy 83/03/15 Atomic Safety and Licensing Board Panel 17pp 17657.252 24X Fiche. 50-445, 83/03/15, 8303220226.

--8303220233 Advises of receipt of SER Suppl 3 after 830315 motion for reconsideration printed. Time needed to review suppl & rev to FSAR on emergency planning. ELLIS, J. Citizens Association for Sound Energy 83/03/15 MILLER, M. E., JORDAN, W. H., MCCOLLOM, K. A. Atomic Safety and Licensing Board Panel 1p 17657.269 24X Fiche. 50-445, 83/03/15, 8303220226.

8303230245 Confirms 830316 telcon listing priority of items on 830311 list re documents relied upon by NRC special insp team in IE Insp Repts 50-445/82-26 & 50-446/82-14. Related correspondence. ELLIS, J. Citizens Association for Sound Energy 83/03/16 HORIN, W. A. Debevoise & Liberman HORIN, W. A. Texas Utilities Generating Co 1p 17661.151 24X Fiche. 50-445, 83/03/16, 8303230245.

8303180358 Forwards IE Insp Repts 50-445/82-25 & 50-446/82-13 & notice of violation. Repts are followups of previous insps on source surveillance activities. ROTHSCHILD, M. U. Hearing Branch 1 83/03/17 MILLER, M. E., JORDAN, W. H., MCCOLLOM, K. A. Atomic Safety and Licensing Board Panel 10pp 17620.085 24X Fiche. 50-445, 83/03/17, 8303180358.

8303180364 Answer to applicant 830225 motion for admission of affidavit re structual integrity test. NRC does not object to admission. Certificate of Svc encl. ROTHSCHILD, M. U. Hearing Branch 1 83/03/17 Atomic Safety and Licensing Board Panel 3pp 17621.068 24X Fiche. 50-445, 83/03/17, 8303180364.

8303180371 Informs that ASLB witnesses will appear voluntarily at 830403 hearings. Subpoenas unnecessary. REYNOLDS, N. S. Debevoise & Liberman TREBY, S. A. Hearing Branch 1 REYNOLDS, N. S. Texas Utilities Generating Co 83/03/17 MILLER, M. E., JORDAN, W. H., MCCOLLOM, K. A. Atomic Safety and Licensing Board Panel 2pp 17621.064 24X Fiche. 50-445, 83/03/17, 8303180371.

8303220264 Order denying Citizens Assoc for Sound Energy 830315 motion for reconsideration of ASLB 830304 & 09 orders re hearings on Walsh-Doyle allegations. Resumed hearing set for 830404-08 will proceed as scheduled. MILLER, M. E. Atomic Safety and Licensing Board Panel 83/03/17 Citizens Association for Sound Energy 1p 17656.227 24X Fiche. 50-445, 83/03/17, 8303220264.

8303230213 Provides assessment of relevance & significance of board notification & other repts to hearings, as allowed by ASLB 830309 memorandum & order. Problems w/Hayward Tyler Pump Co relevant. Related correspondence. ELLIS, J. Citizens Association for Sound Energy 83/03/17 MILLER, M. E., JORDAN, W. H., MCCOLLOM, K. A. Atomic Safety and Licensing Board Panel 3pp 17665.111 24X Fiche. 50-445, 83/03/17, 8303230213.

8303220190 Advises of NRC conclusion that only Board Notification 83-29 re const appraisal team insp is relevant & significant to issues in controversy. NRC still assessing relevance of Board Notification 82-105 re alleged design deficiency. W/o encl. ROTHSCHILD, M. U. Hearing Branch 1 83/03/18 MILLER, M. E., JORDAN, W. H., MCCOLLOM, K. A. Atomic Safety and Licensing Board Panel 2pp 17657.122 24X Fiche. 50-445, 83/03/18, 8303220190.

8303230043 Motion for order in limine to exclude questioning of prospective ASLB witnesses to decide if witnesses are witnesses whose identity NRC is protecting or to exclude production of unexpurgated statements. W/Certificate of Svc. TREBY, S. A., ROTHSCHILD, M. U. Hearing Branch 1 83/03/18 Atomic Safety and Licensing Board Panel 14pp 17663.222 24X Fiche. 50-445, 83/03/18, 8303230043.

8303230228 Assessment of relevance & significance of board notifications, as allowed by ASLB 830309 memorandum & order. Matters raised by board notifications should not be dealt w/by ASLB. Related correspondence. REYNOLDS, N. S., HORIN, W. A. Texas Utilities Generating Co. REYNOLDS, N. S. Debevoise & Liberman 83/03/18 20pp 17661.209 24X Fiche. 50-445, 83/03/18, 8303230228.

--8303230234 Affidavit of DH Wade re Midland-Ross superstrut matl. Board Notifications 83-02 & 83-14 welds in main control panels & Board Notifications 82-90, 82-90A & 82-116 Util committed to perform confirmatory sampling. Certificate of Svc encl. WADE, D. H. Texas Utilities Generating Co 83/03/16 8pp 17661.230 24X Fiche. 50-445, 83/03/18, 8303230228.

8303240519 Provides matl core exhibits admitted into evidence in Dept of Labor evidentiary hearing, Case 82-ERA-9, per 830304 request. W/o encl. HORIN, W. A. Debevoise & Liberman HORIN, W. A. Texas Utilities Generating Co 83/03/21 MILLER, M. E., JORDAN, W. H., MCCOLLOM, K. A. Atomic Safety and Licensing Board Panel 2pp 17682.268 24X Fiche. 50-445, 83/03/21, 8303240519.

8303300371 Motion to compel applicants to provide design criteria & related info on pipe supports. Info relevant to Walsh/Doyle allegations. Applicants have not made required showing that info sought is proprietary. Certificate of Svc encl. ELLIS, J. Citizens Association for Sound Energy 83/03/23 Atomic Safety and Licensing Board Panel 7pp 17731.050 24X Fiche. 50-445, 83/03/23, 8303300371.

8303250125 Forwards Suppl 3 to SER (NUREG-0797). W/o encl. ROTHSCHILD, M. Hearing Branch 1 83/03/24 MILLER, M. E., JORDAN, W. H., MCCOLLOM, K. A. Atomic Safety and Licensing Board Panel 1p 17693.011 24X Fiche. 50-445, 83/03/24, 8303250125.

8303250148 Expresses displeasure w/not being informed of second person being on telephone line during recent telcon, in response to 830321 ltr re request for admissions.
ROTHSCHILD, M. Hearing Branch 1 83/03/24 ELLIS, J. Citizens Association for Sound Energy 1p 17691 011 24X
Fiche: 50-445, 83/03/24, 8303250148

8303300356 Notice of appearance in proceeding. Certificate of Svc encl.
MATTOX, J. Texas, State of 83/03/25 3pp 17734 189 24X
Fiche: 50-445, 83/03/25, 8303300356

8303300411 Motion for stay of evidentiary hearing scheduled to begin on 830404. Time needed for discovery on allegations & to prepare for hearing. Certificate of Svc encl.
MATTOX, J. Texas, State of 83/03/25 Atomic Safety and Licensing Board Panel 6pp 17731 072 24X Fiche: 50-445, 83/03/25, 8303300411

8303300288 Order denying State of TX 830325 motion for stay of hearings scheduled to commence on 830404. Motion unreasonable. State had ample opportunity to follow evidence & participate in proceeding in appropriate manner.
MILLER, M E Atomic Safety and Licensing Board Panel 83/03/28
Texas, State of 2pp 17734 281 24X Fiche: 50-445, 83/03/28, 8303300288

8303300436 Confirms telcon re requested documents concerning IE Insp Rept 82-26/82-14. Some documents available in Region IV ofc. NRC does not have documents for Items 31, 39, 40, 60, 66, 70, 107, 166, 171 or 197.
ROTHSCHILD, M U Hearing Branch 1 83/03/29 ELLIS, J. Citizens Association for Sound Energy 2pp 17731 081 24X
Fiche: 50-445, 83/03/29, 8303300436

8303310263 Identifies proposed witnesses, per ASLB request in 830309 memorandum & order. All 11 ASLB witnesses will appear & testify on 830404 w/o subpoenas.
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Texas Utilities Generating Co 83/03/29 MILLER, M E , JORDAN, W H , MCCOLLOM, K A Atomic Safety and Licensing Board Panel 2pp 17755 325 24X
Fiche: 50-445, 83/03/29, 8303310263

8303310272 Response to ASLB questions re emergency planning. Record should not be kept open for introduction of FEMA final findings re offsite emergency preparedness. Findings not issued until after Oct 1983 exercise. W/Certificate of Svc.
REYNOLDS, N S Texas Utilities Generating Co REYNOLDS, N S Debevoise & Liberman 83/03/29 6pp 17756 037 24X
Fiche: 50-445, 83/03/29, 8303310272

8303310293 Order directing NRC to produce RG Taylor, DD Driskill & RK Herr on 830404 for in camera exam by ASLB.
MILLER, M E Atomic Safety and Licensing Board Panel 83/03/29 1p 17756 033 24X Fiche: 50-445, 83/03/29, 8303310293

8303310250 Provides further response to request for info re documents referenced in IE Insp Rept 82-26/82-14. Certain special insp team documents unavailable w/o encl.
ROTHSCHILD, M U Hearing Branch 1 83/03/30 ELLIS, J. Citizens Association for Sound Energy 3pp 17755 342 24X
Fiche: 50-445, 83/03/30, 8303310250

8303310290 Responds to 830323 ltr protesting closed door meetings re independent design verification program. Advanced notice of proposed meetings will be given by project manager. W/o encl.
ROTHSCHILD, M U Hearing Branch 1 83/03/30 ELLIS, J. Citizens Association for Sound Energy 2pp 17756 029 24X
Fiche: 50-445, 83/03/30, 8303310290

## K. Utility Final Safety Analysis Report (FSAR) & amends

8303220105 Forwards Amend 39 to FSAR, consisting of Rev 6 to emergency plan. Affidavit encl.
GARY, R. J. Texas Utilities Generating Co 83/03/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17649 001 24X Fiche: 50-445, 83/03/08, 8303220105

--8303220128 Amend 39 to FSAR, consisting of Rev 6 to emergency plan.
JONES, R A Texas Utilities Generating Co 83/03/08 195pp 17649 003 24X Fiche: 50-445, 83/03/08, 8303220105

## O. Inspection reports, IE Bulletins & correspondence

8303010442 Forwards IE Insp Repts 50-445/83-02 & 50-446/83-02 on 820112-13. No noncompliance noted.
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/11 GARY, R J Texas Utilities Generating Co 2pp 17346 180 24X Fiche: 50-445, 83/02/11, 8303010442

--8303010451 IE Insp Repts 50-445/83-02 & 50-446/83-02 on 830112-13. No noncompliance noted. Major areas inspected: one control panel for verification of defect magnitude.
TOMLINSON, D P , WESTERMAN, T F , HUNNICUTT, D M Division of Resident, Reactor Project & Engineering Programs 83/01/27 3pp 17346 182 24X Fiche: 50-445, 83/02/11, 8303010442

8303110355 Board Notification 83-14 forwards followup info on apparent deficiencies in Midland-Ross superstrut matl.
EISENHUT, D G Division of Licensing 83/02/18 PALLADINO, N Commissioners 24pp 17546 205 24X Fiche: 50-000, 83/02/18, 8303110355

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11pp 17521 001 24X Fiche: 50-000, 83/02/25, 8212060367

8303150515 Forwards IE Insp Repts 50-445/82-25 & 50-446/82-13 on 821122-24 & notice of violation.
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/28 GARY, R J Texas Utilities Generating Co 3pp 17568 225 24X Fiche: 50-445, 83/02/28, 8303150515

--8303150520 Notice of violation from insp on 821122-24.
* Division of Resident, Reactor Project & Engineering Programs 83/02/28 2pp 17568 228 24X Fiche: 50-445, 83/02/28, 8303150515

--8303150530 IE Insp Repts 50-445/82-25 & 50-446/82-13 on 821122-24. Noncompliance noted: Level III inspector not recertified until 820713, certification expiration date missing from inspector records & audit plans missing.
CONWAY, J T , ROBERDS, H W Division of Vendor & Technical Programs STEWART, R C Division of Resident, Reactor Project & Engineering Programs 82/02/24 4pp 17568 230 24X Fiche: 50-445, 83/02/28, 8303150515

8303090167 Advises of reactor vessel preservice insp in early Apr 1983. Insp will consist of std ASME Code Section XI insp & addl insp of beltline region welds utilizing Westinghouse shallow angle near-surface technique.
SCHMIDT, H C Texas Utilities Services, Inc. 83/03/01
YOUNGBLOOD, B J Licensing Branch 1 1p 17469 360 24X
Fiche: 50-445, 83/03/01, 8303090167

8303110522 Board Notification 83-29: forwards insp results from IE const appraisal team.
NOVAK, T M Assistant Director for Licensing 83/03/02 Atomic Safety and Licensing Board Panel 1p 17523 070 24X
Fiche: 50-445, 83/03/02, 8303110522

--8303110533 Advises that IE Const Appraisal Team completed majority of onsite work. Insp rept will be issued early Apr 1983. Breakdown on work & QC in safety-related portions of HVAC sys indicated.
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/02 EISENHUT, D G Division of Licensing 3pp 17523 071 24X Fiche: 50-445, 83/03/02, 8303110522

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 11?pp 17611 070 24X Fiche: 50-000, 83/03/11, 8212060380.

8303180358 Forwards IE Insp Repts 50-445/82-25 & 50-446/82-13 & notice of violation. Repts are followups of previous insps on source surveillance activities.
ROTHSCHILD, M U Hearing Branch 1 83/03/17 MILLER, M E , JORDAN, W H , MCCOLLOM, K A Atomic Safety and Licensing Board Panel 10pp 17620 085 24X Fiche: 50-445, 83/03/17, 8303180358

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 11?pp 24X Fiche: 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12?pp 17774 352 24X Fiche: 50-000, 83/03/21, 8212060387

# DOCKETED ITEMS

S Reportable occurrences, LERs & related correspondence

8303080063 Interim deficiency rept re position indication of EMD gate valves supplied by Westinghouse Initially reported on 830125 Affected valves modified per manufacturer recommendations Corrective actions to be complete by 830408 GARY, R J Texas Utilities Generating Co 83/02/25 MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 2pp 17457 229 24X Fiche 50-445, 83/02/25, 8303080063

8303080188 Final deficiency rept re procurement & installation of nonmetallic insulation Initially reported on 830126 Matter not reportable per 10CFR50 55(e) GARY, R J Texas Utilities Generating Co 83/02/25 MADSEN, G L Region 4, Office of Director 1p 17457 359 24X Fiche 50-445, 83/02/25, 8303080188

8303080334 Final deficiency rept re radiation monitoring sys Initially reported on 830201 Investigation complete Matter not reportable per 10CFR50 55(e) GARY, R J Texas Utilities Generating Co 83/02/28 MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 1p 17442 342 24X Fiche 50-445, 83/02/28, 8303080334

8303080378 Interim deficiency rept re cracked Pacific Pump multi-vane diffuser producing linear indications Initially reported on 820414 Deficiency not reportable per 10CFR50 55(e) GARY, R J Texas Utilities Generating Co 83/02/28 MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 1p 17453 267 24X Fiche 50-445, 83/02/28, 8303080378

8303150620 Board Notification 83-26 forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys Info may affect conclusions re probability of/corrective measures for ATWS EISENHUT, D G Division of Licensing 83/03/03 PALLADINO, N Commissioners 24pp 17584 097 24X Fiche 50-000, 83/03/03, 8303150620

T Hearing transcripts on non-antitrust matters

8303310251 Identifies proposed witnesses to participate in ASLB 830404 in camera hearing re Walsh/Doyle concerns & emergency preparedness Witness testimony encl TREBY, S A , MIZUNO, G S Hearing Branch 1 83/03/30 MILLER, M E , JORDAN, W H , MCCOLLOM, K A Atomic Safety and Licensing Board Panel 2pp 17756 073 24X Fiche 50-445, 83/03/30, 8303310251

--8303310256 Testimony of S Burwell, WP Chen, JI Tapia, JR Rajan & RG Taylor re MA Walsh & J Doyle concerns BURWELL, S Division of Licensing CHEN, W P Energy, Dept. of TAPIA, J I Division of Resident, Reactor Project & Engineering Programs 83/03/30 12pp 17756 075 24X Fiche 50-445, 83/03/30, 8303310251

--8303310262 Supplementary testimony of DK Rohrer re emergency preparedness ROHRER, D M Emergency Preparedness Branch 83/03/30 4pp 17756 087 24X Fiche 50-445, 83/03/30, 8303310251

--8303310266 Supplementary testimony of A Lookabaugh & J Benton re emergency preparedness LOOKABAUGH, A , BENTON, J Federal Emergency Management Agency 83/03/30 5pp 17756 091 24X Fiche 50-445, 83/03/30, 8303310251

DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA , UNIT 2

A Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24X Fiche 50-000, 83/02/16, 8302170082

8303010642 Reviews environ qualification audit, accounting for post-accident operability Qualification documentation for large pump motors revised to reflect new calculations accounting for 5-yr qualified life SCHMIDT, H C Texas Utilities Services, Inc 83/02/23 YOUNGBLOOD, B J Licensing Branch 1 2pp 17336 120 24X Fiche 50-445, 83/02/23, 8303010642

8303030018 Forwards list of safety-related electrical equipment to be included in environ qualification files SCHMIDT, H C Texas Utilities Services, Inc 83/02/24 YOUNGBLOOD, B J Licensing Branch 1 119pp 17413 001 24X Fiche 50-445, 83/02/24, 8303030018

8303250023 Forwards Rev 0 to nonproprietary WCAP-8587, Suppl 1, "Equipment Qualification Data Packages" & proprietary WCAP-8687, Suppl 2 "Equipment Qualification Test Repts " Proprietary repts withheld (ref 10CFR2 790) RAHE, E P Westinghouse Electric Corp 83/02/28 THOMAS, C O Standardization & Special Projects Branch 7pp 17691 320 24X Fiche 50-445, 83/02/28, 8303250023

8303110215 Describes how station has satisfied human factors guidance re sys function task analysis Plant-specific emergency response guidelines procedure prepared per NUREG-0899 to determine discrepancies w/control board SCHMIDT, H C Texas Utilities Generating Co 83/03/01 YOUNGBLOOD, B J Licensing Branch 1 7pp 17519 297 24X Fiche 50-445, 83/03/01, 8303110215

8303140615 Requests telephone notification with 10 days & written application within 30 days to withhold proprietary info contained in rept, "Comanche Peak Steam Electric Station, Design & Const Self-Initiated Evaluation, Oct 1982 " NOVAK, T M Assistant Director for Licensing 83/03/04 GARY, R J Texas Utilities Generating Co 3pp 17548 352 24X Fiche 50-445, 83/03/04, 8303140615

8303100141 Forwards 830304 ltr to util re proprietary nature of "Comanche Peak Steam Electric Station, Design & Const Self-Initiated Evaluation, Oct 1982 " ROTHSCHILD, M U Hearing Branch 1 83/03/08 MILLER, M E Atomic Safety and Licensing Board Panel 4pp 17485 254 24X Fiche 50-445, 83/03/08, 8303100141

8303140340 Discusses position indication for steam generator safety valves Commits to installation of accident monitoring indicators during first refueling outage SCHMIDT, H C Texas Utilities Services, Inc 83/03/08 YOUNGBLOOD, B J Licensing Branch 1 2pp 17534 229 24X Fiche 50-445, 83/03/08, 8303140340

8303230381 Notification of 830310 meeting w/util in Bethesda, MD to discuss plan for independent design verification program BURWELL, S B Licensing Branch 1 83/03/08 YOUNGBLOOD, B J Licensing Branch 1 3pp 17675 262 24X Fiche 50-445, 83/03/08, 8303230381

8303240116 Summary of 821118 meeting w/util in Bethesda, MD re clarification of NRC requirements concerning independent design verification program BURWELL, S B Licensing Branch 1 83/03/08 Licensing Branch 1 4pp 17698 355 24X Fiche 50-445, 83/03/08, 8303240116

8303150340 Advises of 830405 meeting w/licensees & major contractors at Dallas/Fort Worth, TX to provide info & guidance re 10CFR50 QA & Tech Spec deviations & discuss decentralization policy Questions should be submitted in writing by 830321 COLLINS, J T Region 4, Office of Director 83/03/10 Public Service Co of Colorado 12pp 17562 291 24X Fiche 50-000, 83/03/10, 8303150340

8303150283 Notifies of 830405 public meeting at Dallas/Ft Worth, TX Airport re decentralization policy & 10CFR50 reporting requirements COLLINS, J T Region 4, Office of Director 83/03/11 GARY, R J Texas Utilities Generating Co 3pp 17567 044 24X Fiche 50-445, 83/03/11, 8303150283

8303240163 Notification of 830324-25 meetings w/util in Rockford, IL to discuss status of const & completion schedules for facilities OLSHAN, L N Licensing Branch 1 83/03/11 YOUNGBLOOD, B J Licensing Branch 1 6pp 17696 353 24X Fiche 50-445, 83/03/11, 8303240163

8303290730 Requests determination of eligibility of May House for inclusion in Natl Register of Historic Places Detailed info encl W/o encls YOUNGBLOOD, B J Licensing Branch 1 83/03/14 ROGERS, J Interior, Dept. of, National Park Service 1p 17748 044 24X Fiche 50-445, 83/03/14, 8303290730

8303290661 Notification of 830331 meeting w/util in Bethesda, MD to discuss plans for independent design verification program BURWELL, S B Licensing Branch 1 83/03/21 YOUNGBLOOD, B J Licensing Branch 1 3pp 17742 350 24X Fiche 50-445, 83/03/21, 8303290661

E NRC Safety Evaluation Report (SER), suppls & correspondence

8303290691 Forwards Suppl 3 to SER re operation of facilities W/o encl YOUNGBLOOD, B J Licensing Branch 1 83/03/11 GARY, R J Texas Utilities Generating Co 2pp 17745 120 24X Fiche 50-445, 83/03/11, 8303290691

8303220010 Forwards Rev 3 to Procedure ODA-302, "Relief of Personnel." Procedure includes auxiliary operator relief checklists & completes response to SER, NUREG-0797, Item I.C.2.
MARSHALL, J.S. Texas Utilities Generating Co. 83/03/16.
CROCKER, L.P. Division of Human Factors Safety. 1p. 17652:082. 24X Fiche: 50-445, 83/03/16, 8303220010.

--8303220014 Rev 3 to Procedure ODA-302, "Relief of Personnel."
* Texas Utilities Generating Co. 83/01/26. 26pp. 17652:083. 24X Fiche: 50-445, 83/03/16, 8303220010.

8303300176 Forwards Suppl 3 to SER (NUREG-0797). W/o encl.
YOUNGBLOOD, B.J. Licensing Branch 1. 83/03/22. GARY, R.J. Texas Utilities Generating Co. 2pp. 17763:086. 24X Fiche: 50-445, 83/03/22, 8303300176.

F. Security, medical, emergency & fire protection plans

8303140324 Submits guidance on location of emergency notification sys & health physics network in emergency response facilities, per NUREG-0696.
COLLINS, J.T. Region 4, Office of Director. 83/02/24. GARY, R.J. Texas Utilities Generating Co. 2pp. 17544:011. 24X Fiche: 50-445, 83/02/24, 8303140324.

8303220105 Forwards Amend 39 to FSAR, consisting of Rev 6 to emergency plan. Affidavit encl.
GARY, R.J. Texas Utilities Generating Co. 83/03/08. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 17649:001. 24X Fiche: 50-445, 83/03/08, 8303220105.

--8303220128 Amend 39 to FSAR, consisting of Rev 6 to emergency plan.
JONES, R.A. Texas Utilities Generating Co. 83/03/08. 195pp. 17649:003. 24X Fiche: 50-445, 83/03/08, 8303220105.

8303220188 Describes alternate shutdown design for associated circuits during fire in control room or cable spreading room. Alternate shutdown circuits independent of cables, sys & components in cable spreading room & control room.
SCHMIDT, H.C. Texas Utilities Services, Inc. 83/03/18.
YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 17658:147. 24X Fiche: 50-445, 83/03/18, 8303220188.

8303220387 Describes alternate reactor shutdown for fire in control room or cable spreading room. Design & procedures adequately assure reactor shutdown throughout duration of cable spreading room or control room fire scenario.
SCHMIDT, H.C. Texas Utilities Services, Inc. 83/03/18.
YOUNGBLOOD, B.J. Licensing Branch 1. 2pp. 17648:355. 24X Fiche: 50-445, 83/03/18, 8303220387.

8303290231 Discusses repts from utils re telephonic inquiries from unidentified persons about security sys. Calls made by personnel recruiter attempting to locate personnel familiar w/particular computer. Recruiter admonished.
COLLINS, J.T. Region 4, Office of Director. 83/03/25. GARY, R.J. Texas Utilities Generating Co. 2pp. 17722:231. 24X Fiche: 50-445, 83/03/25, 8303290231.

8303310100 Releases public version of revised emergency plan.
FELTON, J.M. Division of Rules and Records. 83/03/28. Document Management Branch. 1p. 17777:162. 24X Fiche: 50-445, 83/03/28, 8303310100.

--8303310105 Forwards public version of Rev 6 to emergency plan, consisting of Amend 39 to FSAR. Return receipt requested.
SMART, T.L. Texas Utilities Services, Inc. 83/03/08. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 17777:163. 24X Fiche: 50-445, 83/03/28, 8303310100.

Q. Adjudicatory correspondence

8303100256 Suggests that performance of siren early warning sys totally unacceptable. Sirens cannot be heard by many citizens.
CRUMP, Q.R. Somervell County, TX. 83/02/21. MILLER, M.E. Atomic Safety and Licensing Board Panel. 1p. 17489:356. 24X Fiche: 50-445, 83/02/21, 8303100256.

8303010084 Informs of applicant release of IE rept to press before receipt by intervenors. Applicant timing is prejudicing case.
ELLIS, J. Citizens Association for Sound Energy. 83/02/24.
MILLER, M.E., COLE, R.F., MCCOLLOM, K.A. Atomic Safety and Licensing Board Panel. 2pp. 17335:348. 24X Fiche: 50-445, 83/02/24, 8303010084.

8303010105 Provisional proposed findings of fact. Certificate of Svc encl.
ELLIS, J. Citizens Association for Sound Energy. 83/02/24. 65pp. 17345:038. 24X Fiche: 50-445, 83/02/24, 8303010105.

8303010276 Motion for 21-day extension to file addl provisional proposed findings of fact & to suspend discovery on issues until 830329. Delay due to unreasonable work load & complexity of issues. Certificate of Svc encl.
ELLIS, J. Citizens Association for Sound Energy. 83/02/24. Atomic Safety and Licensing Board Panel. 8pp. 17335:085. 24X Fiche: 50-445, 83/02/24, 8303010276.

8303010401 Notice of ASLB reconstitution: RE Miller, Chairman; KA McCollom & WH Jordan, members.
COTTER, B.P. Atomic Safety and Licensing Board Panel. 83/02/24. 2pp. 17346:213. 24X Fiche: 50-445, 83/02/24, 8303010401.

8303010316 Motion for admission of JT Merritt affidavit re structural integrity tests. Results confirm structural integrity of containment, including repaired portion of Unit 1 dome.
REYNOLDS, N.S., HORIN, W.A. Texas Utilities Generating Co.
REYNOLDS, N.S. Debevoise & Liberman. 83/02/25. Atomic Safety and Licensing Board Panel. 2pp. 17345:218. 24X Fiche: 50-445, 83/02/25, 8303010316.

--8303010328 Affidavit of JT Merritt re structural integrity test. Results confirm structural integrity of containment dome, including repaired portion of Unit 1 dome. Certificate of Svc encl.
MERRITT, J.T. Texas Utilities Generating Co. 83/02/23. 4pp. 17345:220. 24X Fiche: 50-445, 83/02/25, 8303010316.

8303010333 Proposed findings of fact in form of partial initial decision. Certificate of Svc encl.
REYNOLDS, N.S., HORIN, W.A. Texas Utilities Generating Co.
REYNOLDS, N.S. Debevoise & Liberman. 83/02/25. 182pp. 17346:236. 24X Fiche: 50-445, 83/02/25, 8303010333.

8303020067 Memorandum & order denying & striking from record Citizens Assoc for Sound Energy, util & NRC motions, responses to motions & filings. Prolix motions irrelevant to issues & beyond scope of ASLB function or jurisdiction.
MILLER, M.E. Atomic Safety and Licensing Board Panel. 83/03/01. Citizens Association for Sound Energy. 6pp. 17352:078. 24X Fiche: 50-445, 83/03/01, 8303020067.

8303020071 Application for stay of effectiveness of ALAB-714. Disclosure of informants could harm Commission investigative ability & would be contrary to Commission policy favoring informant confidentiality. Certificate of Svc encl.
CUNNINGHAM, G.H. Office of the Executive Legal Director. TURK, S.E. Hearing Branch 1. 83/03/01. Commissioners. 14pp. 17352:171. 24X Fiche: 50-445, 83/03/01, 8303020071.

8303030447 Memorandum & Order ALAB-716 denying NRC 830225 motion for stay of effectiveness of ALAB-714, requiring disclosure of informants. NRC would not be irreparably injured. Argument is frivolous.
SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. 83/03/01. Office of the Executive Legal Director. 7pp. 17410:061. 24X Fiche: 50-445, 83/03/01, 8303030447.

8303040330 Forwards NRC 830224 provisional proposed findings of fact. W/o encl.
ROTHSCHILD, M.U. Hearing Branch 1. 83/03/02. JORDAN, W.H. Atomic Safety and Licensing Board Panel. 1p. 17420:071. 24X Fiche: 50-445, 83/03/02, 8303040330.

8303040625 Response to ASLB 830217 order requesting info re const completion date for Unit 1. Fuel load scheduled for Dec 1983.
ROTHSCHILD, M.U. Hearing Branch 1. 83/03/03. 2pp. 17374:240. 24X Fiche: 50-445, 83/03/03, 8303040625.

--8303040633 Affidavit of SB Burwell re const completion date for Unit 1. Fuel load scheduled for Dec 1983. Prof qualifications & Certificate of Svc encl.
BURWELL, S.B. Licensing Branch 1. 83/03/03. 25pp. 17374:242. 24X Fiche: 50-445, 83/03/03, 8303040625.

8303070122 Response to ASLB order requesting repts on current best projections of plant completion date. Risk of not completing licensing process prior to plant completion not eliminated. Certificate of Svc encl.
REYNOLDS, N.S., HORIN, W.A. Texas Utilities Generating Co.
REYNOLDS, N.S. Debevoise & Liberman. 83/03/03. 8pp. 17433:080. 24X Fiche: 50-445, 83/03/03, 8303070122.

8303080024 Requests amend to svc list to include RJ Gray.
REYNOLDS, N.S. Debevoise & Liberman. REYNOLDS, N.S. Texas Utilities Generating Co. 83/03/03. MILLER, M.E., JORDAN, W.H., MCCOLLOM, K.A. Atomic Safety and Licensing Board Panel. 1p. 17455:351. 24X Fiche: 50-445, 83/03/03, 8303080024.

# DOCKETED ITEMS

8303080172 Notice of resumption of hearing on 830404 in Fort Worth, TX covering all matters in controversy not completed. NRC should prepare & serve subpoenas for appearance of listed persons as ASLB witnesses.
MILLER, M E. Atomic Safety and Licensing Board Panel. 83/03/04.
15pp. 17457:105. 24X Fiche: 50-445, 83/03/04, 8303080172.

8303080462 Order CLI-83-6, granting NRC 830301 application for stay of effectiveness of ALAB-714 pending filing & resolution of appeal. Disclosure of informants will irreparably alter status quo.
CHILK, S J. Office of the Secretary of the Commission. 83/03/04.
Office of the Executive Legal Director. 3pp. 17451:348. 24X Fiche: 50-445, 83/03/04, 8303080462.

8303100141 Forwards 830304 ltr to util re proprietary nature of "Comanche Peak Steam Electric Station, Design & Const Self-Initiated Evaluation, Oct 1982."
ROTHSCHILD, M U. Hearing Branch 1. 83/03/08. MILLER, M E., JORDAN, W H., MCCOLLOM, K A. Atomic Safety and Licensing Board Panel.
4pp. 17485:254. 24X Fiche: 50-445, 83/03/08, 8303100141.

8303110195 Memorandum & order memorializing 830308 conference call re matters to be covered during scheduled wk of resumed hearing beginning on 830404.
MILLER, M E. Atomic Safety and Licensing Board Panel. 83/03/09.
4pp. 17520:118. 24X Fiche: 50-445, 83/03/09, 8303110195.

8303150127 Petition for review of ALAB-714 re disclosure of informants. Decision contains significant errors & establishes unacceptable policy & procedural precedent. Identities are not known for certain. Certificate of Svc encl.
CUNNINGHAM, G H. Office of the Executive Legal Director. TURK, S E. Hearing Branch 1. 83/03/11. Commissioners. 12pp. 17549:044.
24X Fiche: 50-445, 83/03/11, 8303150127.

8303160534 Confirms 830404-08 hearing in Forth Worth, TX. ASLB requested FEMA interim findings be entered into record. ASLB wants to inquire into new info in findings re availability of & alternatives to EBS sys & County judges advisory info.
MIZUNO, G S. Hearing Branch 1. 83/03/11. LOOKABAUGH, A., BENTON, J., PERRY, S. Federal Emergency Management Agency. 1p. 17592:337. 24X
Fiche: 50-445, 83/03/11, 8303160534.

8303180380 Provides list of documents requested under ASLB informal discovery. Related correspondence.
ELLIS, J. Citizens Association for Sound Energy. 83/03/11.
REYNOLDS, N S. Debevoise & Liberman. 17pp. 17622:249. 24X
Fiche: 50-445, 83/03/11, 8303180380.

8303180385 Requests svc list be amended to include LA Sinkin.
ELLIS, J. Citizens Association for Sound Energy. 83/03/11. Atomic Safety and Licensing Board Panel. 1p. 17621:345. 24X
Fiche: 50-445, 83/03/11, 8303180385.

8303180400 Forwards IE 830308 response to Citizens Assoc for Sound Energy 10CFR2.206 petition for show cause order based on util failure to have documents in possession on component design.
ELLIS, J. Citizens Association for Sound Energy. 83/03/11.
MILLER, M E., MCCOLLOM, K A., JORDAN, W H. Atomic Safety and Licensing Board Panel. 4pp. 17621:357. 24X Fiche: 50-445, 83/03/11, 8303180400.

8303160528 Forwards photocopies of SER Suppl 3 (NUREG-0797). Bound copies will be sent when available. W/o encl.
ROTHSCHILD, M U. Hearing Branch 1. 83/03/14. MILLER, M E., JORDAN, W H., MCCOLLOM, K A. Atomic Safety and Licensing Board Panel.
3pp. 17592:278. 24X Fiche: 50-445, 83/03/14, 8303160528.

8303170048 Clarifies statements made in 830311 ltr. Discovery requests may be sent in lieu of engaging in informal discovery. List of documents discussed in IE Insp Repts 50-445/82-26 & 50-446/82-26 promised in 830311 ltr not received.
ROTHSCHILD, M U. Hearing Branch 1. 83/03/15. ELLIS, J. Citizens Association for Sound Energy. 1p. 17609:097. 24X
Fiche: 50-445, 83/03/15, 8303170048.

8303180406 Confirms 830315 telcon re intervenor 830311 request for documents on NRC insp of Walsh & Doyle allegations. Intervenor request for 200 categories of documents does not conform to ASLB discovery limits. Related correspondence.
HORIN, W A. Debevoise & Liberman. HORIN, W A. Texas Utilities Generating Co. 83/03/15. ELLIS, J. Citizens Association for Sound Energy. 1p. 17622:010. 24X Fiche: 50-445, 83/03/15, 8303180406.

8303220226 Motion for reconsideration re hearings on Walsh/Doyle allegations. Hearings scheduled for 830404-08 should not include allegations. Ninety days should be allotted to analyze documents. Certificate of Svc encl.
ELLIS, J. Citizens Association for Sound Energy. 83/03/15. Atomic Safety and Licensing Board Panel. 17pp. 17657:252. 24X
Fiche: 50-445, 83/03/15, 8303220226.

--8303220233 Advises of receipt of SER Suppl 3 after 830315 motion for reconsideration printed. Time needed to review suppl & rev to FSAR on emergency planning.
ELLIS, J. Citizens Association for Sound Energy. 83/03/15.
MILLER, M E., JORDAN, W H., MCCOLLOM, K A. Atomic Safety and Licensing Board Panel. 1p. 17657:269. 24X Fiche: 50-445, 83/03/15, 8303220226.

8303230245 Confirms 830316 telcon listing priority of items on 830311 list re documents relied upon by NRC special insp team in IE Insp Repts 50-445/82-26 & 50-446/82-14. Related correspondence.
ELLIS, J. Citizens Association for Sound Energy. 83/03/16.
HORIN, W A. Debevoise & Liberman. HORIN, W A. Texas Utilities Generating Co. 1p. 17661:151. 24X Fiche: 50-445, 83/03/16, 8303230245.

8303180358 Forwards IE Insp Repts 50-445/82-25 & 50-446/82-13 & notice of violation. Repts are followups of previous insps on source surveillance activities.
ROTHSCHILD, M U. Hearing Branch 1. 83/03/17. MILLER, M E., JORDAN, W H., MCCOLLOM, K A. Atomic Safety and Licensing Board Panel.
10pp. 17620:085. 24X Fiche: 50-445, 83/03/17, 8303180358.

8303180364 Answer to applicant 830225 motion for admission of affidavit re structual integrity test. NRC does not object to admission. Certificate of Svc encl.
ROTHSCHILD, M U. Hearing Branch 1. 83/03/17. Atomic Safety and Licensing Board Panel. 3pp. 17621:068. 24X Fiche: 50-445, 83/03/17, 8303180364.

8303180371 Informs that ASLB witnesses will appear voluntarily at 830403 hearings. Subpoenas unnecessary.
REYNOLDS, N S. Debevoise & Liberman. TREBY, S A. Hearing Branch 1.
REYNOLDS, N S. Texas Utilities Generating Co. 83/03/17.
MILLER, M E., JORDAN, W H., MCCOLLOM, K A. Atomic Safety and Licensing Board Panel. 2pp. 17621:064. 24X Fiche: 50-445, 83/03/17, 8303180371.

8303220264 Order denying Citizens Assoc for Sound Energy 830315 motion for reconsideration of ASLB 830304 & 09 orders re hearings on Walsh-Doyle allegations. Resumed hearing set for 830404-08 will proceed as scheduled.
MILLER, M E. Atomic Safety and Licensing Board Panel. 83/03/17.
Citizens Association for Sound Energy. 1p. 17656:227. 24X
Fiche: 50-445, 83/03/17, 8303220264.

8303230213 Provides assessment of relevance & significance of board notification & other repts to hearings, as allowed by ASLB 830309 memorandum & order. Problems w/Hayward Tyler Pump Co relevant. Related correspondence.
ELLIS, J. Citizens Association for Sound Energy. 83/03/17.
MILLER, M E., JORDAN, W H., MCCOLLOM, K A. Atomic Safety and Licensing Board Panel. 3pp. 17665:111. 24X Fiche: 50-445, 83/03/17, 8303230213.

8303220190 Advises of NRC conclusion that only Board Notification 83-29 re const appraisal team insp is relevant & significant to issues in controversy. NRC still assessing relevance of Board Notification 82-105 re alleged design deficiency. W/o encl.
ROTHSCHILD, M U. Hearing Branch 1. 83/03/18. MILLER, M E., JORDAN, W H., MCCOLLOM, K A. Atomic Safety and Licensing Board Panel.
2pp. 17657:122. 24X Fiche: 50-445, 83/03/18, 8303220190.

8303230043 Motion for order in limine to exclude questioning of prospective ASLB witnesses to decide if witnesses are witnesses whose identity NRC is protecting or to exclude production of unexpurgated statements. W/Certificate of Svc.
TREBY, S A., ROTHSCHILD, M U. Hearing Branch 1. 83/03/18. Atomic Safety and Licensing Board Panel. 14pp. 17663:222. 24X
Fiche: 50-445, 83/03/18, 8303230043.

8303230228 Assessment of relevance & significance of board notifications, as allowed by ASLB 830309 memorandum & order. Matters raised by board notifications should not be dealt w/by ASLB. Related correspondence.
REYNOLDS, N S., HORIN, W A. Texas Utilities Generating Co.
REYNOLDS, N S. Debevoise & Liberman. 83/03/18. 20pp. 17661:209.
24X Fiche: 50-445, 83/03/18, 8303230228.

--8303230234 Affidavit of DH Wade re Midland-Ross superstrut matl. Board Notifications 83-02 & 83-14 welds in main control panels & Board Notifications 82-90, 82-90A & 82-116. Util committed to perform confirmatory sampling. Certificate of Svc encl.
WADE, D H. Texas Utilities Generating Co. 83/03/16. 8pp.
17661:230. 24X Fiche: 50-445, 83/03/18, 8303230228.

8303240519 Provides matl core exhibits admitted into evidence in Dept of Labor evidentiary hearing, Case 82-ERA-9, per 830304 request. W/o encl.
HORIN, W A. Debevoise & Liberman. HORIN, W A. Texas Utilities Generating Co. 83/03/21. MILLER, M E., JORDAN, W H., MCCOLLOM, K A. Atomic Safety and Licensing Board Panel. 2pp. 17682:268. 24X
Fiche: 50-445, 83/03/21, 8303240519.

8303300371 Motion to compel applicants to provide design criteria & related info on pipe supports. Info relevant to Walsh/Doyle allegations. Applicants have not made required showing that info sought is proprietary. Certificate of Svc encl.
ELLIS, J. Citizens Association for Sound Energy. 83/03/23. Atomic Safety and Licensing Board Panel. 7pp. 17731:050. 24X.
Fiche: 50-445, 83/03/23, 8303300371.

8303250125 Forwards Suppl 3 to SER (NUREG-0797). W/o encl.
ROTHSCHILD, M. ; JORDAN, W.H. ; MCCOLLOM, K.A. Atomic Safety and Licensing Board Panel. 1p. 17693:011. 24X. Fiche: 50-445, 83/03/24, 8303250125.

8303250148 Expresses displeasure w/not being informed of second person being on telephone line during recent telcon; in response to 830321 ltr re request for admissions.
ROTHSCHILD, M. Hearing Branch 1. 83/03/24. ELLIS, J. Citizens Association for Sound Energy. 1p. 17691:011. 24X.
Fiche: 50-445, 83/03/24, 8303250148.

8303300356 Notice of appearance in proceeding. Certificate of Svc encl.
MATTOX, J. Texas, State of. 83/03/25. 3pp. 17734:189. 24X.
Fiche: 50-445, 83/03/25, 8303300356.

8303300411 Motion for stay of evidentiary hearing scheduled to begin on 830404. Time needed for discovery on allegations & to prepare for hearing. Certificate of Svc encl.
MATTOX, J. Texas, State of. 83/03/25. Atomic Safety and Licensing Board Panel. 6pp. 17731:072. 24X. Fiche: 50-445, 83/03/25, 8303300411.

8303300288 Order denying State of TX 830325 motion for stay of hearings scheduled to commence on 830404. Motion unreasonable. State had ample opportunity to follow evidence & participate in proceeding in appropriate manner.
MILLER, M.E. Atomic Safety and Licensing Board Panel. 83/03/28.
Texas, State of. 2pp. 17734:281. 24X. Fiche: 50-445, 83/03/28, 8303300288.

8303300436 Confirms telcon re requested documents concerning IE Insp Rept 82-26/82-14. Some documents available in Region IV ofc. NRC does not have documents for Items 31, 39, 40, 60, 66, 70, 107, 166, 171 or 197.
ROTHSCHILD, M.U. Hearing Branch 1. 83/03/29. ELLIS, J. Citizens Association for Sound Energy. 2pp. 17731:081. 24X.
Fiche: 50-445, 83/03/29, 8303300436.

8303310263 Identifies proposed witnesses, per ASLB request in 830309 memorandum & order. All 11 ASLB witnesses will appear & testify on 830404 w/o subpoenas.
REYNOLDS, N.S. Debevoise & Liberman. REYNOLDS, N.S. Texas Utilities Generating Co. 83/03/29. MILLER, M.E. ; JORDAN, W.H. ; MCCOLLOM, K.A. Atomic Safety and Licensing Board Panel. 2pp. 17755:325. 24X.
Fiche: 50-445, 83/03/29, 8303310263.

8303310272 Response to ASLB questions re emergency planning. Record should not be kept open for introduction of FEMA final findings re offsite emergency preparedness. Findings not issued until after Oct 1983 exercise. W/Certificate of Svc.
REYNOLDS, N.S. Texas Utilities Generating Co. REYNOLDS, N.S. Debevoise & Liberman. 83/03/29. 6pp. 17756:037. 24X.
Fiche: 50-445, 83/03/29, 8303310272.

8303310293 Order directing NRC to produce RG Taylor, DD Driskill & RK Herr on 830404 for in camera exam by ASLB.
MILLER, M.E. Atomic Safety and Licensing Board Panel. 83/03/29. 1p. 17756:033. 24X. Fiche: 50-445, 83/03/29, 8303310293.

8303310250 Provides further response to request for info re documents referenced in IE Insp Rept 82-26/82-14. Certain special insp team documents unavailable. W/o encl.
ROTHSCHILD, M.U. Hearing Branch 1. 83/03/30. ELLIS, J. Citizens Association for Sound Energy. 3pp. 17755:342. 24X.
Fiche: 50-445, 83/03/30, 8303310250.

8303310290 Responds to 830323 ltr protesting closed door meetings re independent design verification program. Advanced notice of proposed meetings will be given by project manager. W/o encl.
ROTHSCHILD, M.U. Hearing Branch 1. 83/03/30. ELLIS, J. Citizens Association for Sound Energy. 2pp. 17756:029. 24X.
Fiche: 50-445, 83/03/30, 8303310290.

## K. Utility Final Safety Analysis Report (FSAR) & amends

8303220105 Forwards Amend 39 to FSAR, consisting of Rev 6 to emergency plan. Affidavit encl.
GARY, R.J. Texas Utilities Generating Co. 83/03/08. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 17649:001. 24X. Fiche: 50-445, 83/03/08, 8303220105.

--8303220128 Amend 39 to FSAR, consisting of Rev 6 to emergency plan.
JONES, R.A. Texas Utilities Generating Co. 83/03/08. 195pp. 17649:003. 24X. Fiche: 50-445, 83/03/08, 8303220105.

## Q. Inspection reports, IE Bulletins & correspondence

8303010442 Forwards IE Insp Repts 50-445/83-02 & 50-446/83-02 on 820112-13. No noncompliance noted.
MADSEN, G.L. Division of Resident, Reactor Project & Engineering Programs. 83/02/11. GARY, R.J. Texas Utilities Generating Co. 2pp. 17346:180. 24X. Fiche: 50-445, 83/02/11, 8303010442.

--8303010451 IE Insp Repts 50-445/83-02 & 50-446/83-02 on 830112-13. No noncompliance noted. Major areas inspected: one control panel for verification of defect magnitude.
TOMLINSON, D.P. ; WESTERMAN, T.F. ; HUNNICUTT, D.M. Division of Resident, Reactor Project & Engineering Programs. 83/01/27. 3pp. 17346:182. 24X. Fiche: 50-445, 83/02/11, 8303010442.

8303110355 Board Notification 83-14: Forwards followup info on apparent deficiencies in Midland-Ross superstrut matl.
EISENHUT, D.G. Division of Licensing. 83/02/18. PALLADINO, N. Commissioners. 24pp. 17546:205. 24X. Fiche: 50-000, 83/02/18, 8303110355.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521:001. 24X. Fiche: 50-000, 83/02/25, 8212060367.

8303150515 Forwards IE Insp Repts 50-445/82-25 & 50-446/82-13 on 821122-24 & notice of violation.
MADSEN, G.L. Division of Resident, Reactor Project & Engineering Programs. 83/02/28. GARY, R.J. Texas Utilities Generating Co. 3pp. 17568:225. 24X. Fiche: 50-445, 83/02/28, 8303150515.

--8303150520 Notice of violation from insp on 821122-24.
* Division of Resident, Reactor Project & Engineering Programs. 83/02/28. 2pp. 17568:228. 24X. Fiche: 50-445, 83/02/28, 8303150515.

--8303150530 IE Insp Repts 50-445/82-25 & 50-446/82-13 on 821122-24. Noncompliance noted: Level III inspector not recertified until 820713; certification expiration date missing from inspector records & audit plans missing.
CONWAY, J.T. ; ROBERDS, H.W. Division of Vendor & Technical Programs. STEWART, R.C. Division of Resident, Reactor Project & Engineering Programs. 82/02/24. 4pp. 17568:230. 24X. Fiche: 50-445, 83/02/28, 8303150515.

8303090167 Advises of reactor vessel preservice insp in early Apr 1983. Insp will consist of std ASME Code Section XI insp & addl insp of beltline region welds utilizing Westinghouse shallow angle near-surface technique.
SCHMIDT, H.C. Texas Utilities Services, Inc. 83/03/01.
YOUNGBLOOD, B.J. Licensing Branch 1. 1p. 17469:360. 24X.
Fiche: 50-445, 83/03/01, 8303090167.

8303110522 Board Notification 83-29: forwards insp results from IE const appraisal team.
NOVAK, T.M. Assistant Director for Licensing. 83/03/02. Atomic Safety and Licensing Board Panel. 1p. 17523:070. 24X.
Fiche: 50-445, 83/03/02, 8303110522.

--8303110533 Advises that IE Const Appraisal Team completed majority of onsite work. Insp rept will be issued early Apr 1983. Breakdown on work & QC in safety-related portions of HVAC sys indicated.
TAYLOR, J.M. Division of Safeguards & Inspection Programs (Post 830103). 83/03/02. EISENHUT, D.G. Division of Licensing. 3pp. 17523:071. 24X. Fiche: 50-445, 83/03/02, 8303110522.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X. Fiche: 50-000, 83/03/11, 8212060380.

8303180358 Forwards IE Insp Repts 50-445/82-25 & 50-446/82-13 & notice of violation. Repts are followups of previous insps on source surveillance activities.
ROTHSCHILD, M.U. Hearing Branch 1. 83/03/17. MILLER, M.E. Atomic Safety and Licensing Board Panel. 10pp. 17620:085. 24X.
Fiche: 50-445, 83/03/17, 8303180358.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X. Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X. Fiche: 50-000, 83/03/21, 8212060387.

S Reportable occurrences, LERs & related correspondence

8303080063 Interim deficiency rept re position indication of EMD gate valves supplied by Westinghouse Initially reported on 830125 Affected valves modified per manufacturer recommendations Corrective actions to be complete by 830408
GARY, R J Texas Utilities Generating Co 83/02/25 MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 2pp 17457 229 24X Fiche 50-445, 83/02/25, 8303080063

8303080188 Final deficiency rept re procurement & installation of nonmetallic insulation Initially reported on 830126 Matter not reportable per 10CFR50 55(e)
GARY, R J Texas Utilities Generating Co 83/02/25 MADSEN, G L Region 4, Office of Director 1p 17457 359 24X Fiche 50-445, 83/02/25, 8303080188

8303080334 Final deficiency rept re radiation monitoring sys Initially reported on 830201 Investigation complete Matter not reportable per 10CFR50 55(e)
GARY, R J Texas Utilities Generating Co 83/02/28 MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 1p 17442 342 24X Fiche 50-445, 83/02/28, 8303080334

8303080378 Interim deficiency rept re cracked Pacific Pump multi-vane diffuser producing linear indications Initially reported on 820414 Defiriency not reportable per 10CFR50 55(e)
GARY, R J Texas Utilities Generating Co 83/02/28 MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 1p 17453 267 24X Fiche 50-445, 83/02/28, 8303080378

8303150620 Board Notification 83-26 forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys Info may affect conclusions re probability of/corrective measures for ATWS
EISENHUT, D G Division of Licensing 83/03/03 PALLADINO, N Commissioners 24pp 17584 097 24X Fiche 50-000, 83/03/03, 8303150620

T Hearing transcripts on non-antitrust matters

8303310251 Identifies proposed witnesses to participate in ASLB 830404 in camera hearing re Walsh/Doyle concerns & emergency preparedness Witness testimony encl
TREBY, S A , MIZUNO, G S Hearing Branch 1 83/03/30 MILLER, M E , JORDAN, W H , MCCOLLOM, K A Atomic Safety and Licensing Board Panel 2pp 17756 073 24X Fiche 50-445, 83/03/30, 8303310251

--8303310256 Testimony of S Burwell, WP Chen, JI Tapia, JR Rajan & RG Taylor re MA Walsh & J Doyle concerns
BURWELL, S Division of Licensing CHEN, W P Energy, Dept of TAPIA, J I Division of Resident, Reactor Project & Engineering Programs 83/03/30 12pp 17756 075 24X Fiche 50-445, 83/03/30, 8303310251

--8303310262 Supplementary testimony of DM Rohrer re emergency preparedness
ROHRER, D M Emergency Preparedness Branch 83/03/30 4pp 17756 087 24X Fiche 50-445, 83/03/30, 8303310251

--8303310266 Supplementary testimony of A Lookabaugh & J Benton re emergency preparedness
LOOKABAUGH, A , BENTON, J Federal Emergency Management Agency 83/03/30 5pp 17756 091 24X Fiche 50-445, 83/03/30, 8303310251

DOCKET STN-50-447 GESSAR-238

A Application/construction stage documents & correspondence

8303030767 Notification of 830303 meeting w/GE in Bethesda, MD to discuss proposed BWR/6 Mark III GESSAR-II seismic event analysis
SCALETTI, D C Standardization & Special Projects Branch 83/02/24
THOMAS, C O Standardization & Special Projects Branch 4pp 17363 221 24X Fiche 50-447, 83/02/24, 8303030767

8303070062 Forwards listing of major NSSS & balance of plant documents supporting GESSAR II design including equipment vendor independent documents reviewed by Mechanical & Structural Engineering Branches during audits
SHERWOOD, G G General Electric Co 83/03/03 EISENHUT, D G Division of Licensing 20pp 17435 014 24X Fiche 50-447, 83/03/03, 8303070062

8303070127 Requests review of GESSAR II, Section 3 11 in parallel w/ current review of NEDE-24326-1-P, "GE Environ Qualification Program " Marked-up proposed plan encl
SHERWOOD, G G General Electric Co 83/03/03 EISENHUT, D G Division of Licensing 73pp 17433 274 24X Fiche 50-447, 83/03/03, 8303070127

8303160028 Requests computer input tape re severe accident portion of GE application for final approval of GESSAR II design identified in PRA be sent to BNL
THOMAS, C O Standardization & Special Projects Branch 83/03/07
SHERWOOD, G G General Electric Co 2pp 17604 359 24X Fiche 50-447, 83/03/07, 8303160028

8303140179 Documents agreements on credit for suppression pool scrubbing in GESSAR-II, Chapter 15 re radiological dose calculations Potential decontamination capability provided by scrubbing will be recognized
SHERWOOD, G G General Electric Co 83/03/09 EISENHUT, D G Division of Licensing 2pp 17539 349 24X Fiche 50-447, 83/03/09, 8303140179

8303150541 Reaffirms request re issuance of final design approval for GESSAR-II Resolution of technical requirements currently imposed by NRC proposed in submittal docketed 820222
SHERWOOD, G G General Electric Co 83/03/09 EISENHUT, D G Division of Licensing 2pp 17568 161 24X Fiche 50-447, 83/03/09, 8303150541

8303170291 Forwards revised final draft responses to Power Sys & Reactor Sys Branch questions per 820825 & 1115 requests Only mods (new or revised) to responses of referenced ltrs provided
SHERWOOD, G G General Electric Co 83/03/15 EISENHUT, D G Division of Licensing 29pp 17605 098 24X Fiche 50-447, 83/03/15, 8303170291

8303180017 Forwards final draft responses to Auxiliary Sys Branch questions & Equipment Qualification Branch discussion items, in response to NRC 820825 request for info
SHERWOOD, G G General Electric Co 83/03/16 EISENHUT, D G Division of Licensing 20pp 17618 107 24X Fiche 50-447, 83/03/16, 8303180017

8303210290 Forwards revised draft responses to 821005 info request re GESSAR-II
SHERWOOD, G G General Electric Co 83/03/17 EISENHUT, D G Division of Licensing 58pp 17632 322 24X Fiche 50-447, 83/03/17, 8303210290

8303220138 Forwards revised final draft responses to selected Commission 820825 & 1005 questions re fire protection, leak rate testing & ESF sys Proposed resolution discussion items encl
SHERWOOD, G G General Electric Co 83/03/18 EISENHUT, D G Division of Licensing 58pp 17657 186 24X Fiche 50-447, 83/03/18, 8303220138

8303290360 Forwards GESSAR-II SRP assessments, describing compliance w/NUREG-0800 Section-by-section comparison of GESSAR-II design to SRP, NUREG-0800, will be provided by 830915
SHERWOOD, G G General Electric Co 83/03/25 EISENHUT, D G Division of Licensing 841pp 17718 163 24X Fiche 50-447, 83/03/25, 8303290360

8303310277 Forwards supplemental response to Instrumentation & Control Sys Branch question on manual initiation of safety sys & proposed resolution of Meteorology & Effluent Treatment Branch discussion items
SHERWOOD, G G General Electric Co 83/03/29 EISENHUT, D G Division of Licensing 5pp 17755 356 24X Fiche 50-447, 83/03/29, 8303310277

B Utility Preliminary Safety Analysis Report, amends

8302040379 Forwards Amend 13 to 238 GE SSAR, amending GESSAR-II by correcting rev designation of proprietary pages provided under Amend 1 Nonproprietary version not included
SHERWOOD, G G General Electric Co 83/01/19 EISENHUT, D G Division of Licensing 1p 17019 101 24X Fiche 50-447, 83/01/19, 8302040379

--8302040383 Forwards proprietary portion of Amend 13, replacing proprietary pages of Amend 1 to SSAR Encl withheld (ref 10CFR2 790)
SHERWOOD, G G General Electric Co 83/01/19 EISENHUT, D G Division of Licensing 6pp 17019 103 24X Fiche 50-447, 83/01/19, 8302040379

E NRC Safety Evaluation Report (SER), suppls & correspondence

8303110294 Forwards revised final draft responses to NRC 820825 & 1115 requests & Mechanical Engineering Branch SER meetings Draft revs to Reg Guides 1 31 & 1 44 encl
SHERWOOD, G G General Electric Co 83/03/09 EISENHUT, D G Division of Licensing 93pp 17513 262 24X Fiche 50-447, 83/03/09, 8303110294

F. Security, medical, emergency & fire protection plans

8303220138 Forwards revised final draft responses to selected Commission 820825 & 1005 questions re fire protection, leak rate testing & ESF sys Proposed resolution discussion items encl
SHERWOOD, G. G. General Electric Co. 83/03/18. EISENHUT, D. G. Division of Licensing. 58pp. 17657:186. 24X Fiche: 50-447, 83/03/18, 8303220138

DOCKET STN-50-454 BYRON STATION, UNIT 1

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X
Fiche: 50-000, 83/02/16, 8302170082

8303080154 Forwards Rev 5 to "Offsite Dose Calculation Manual."
PAJOWSKI, J. Commonwealth Edison Co. 83/02/28. CASE, E. G. NRC - No Detailed Affiliation Given. 1p. 17445:191. 24X
Fiche: 50-454, 83/02/28, 8303080154

--8303080157 Rev 5 to "Offsite Dose Calculation Manual."
* Commonwealth Edison Co. 83/02/28. 204pp. 17445:192. 24X
Fiche: 50-454, 83/02/28, 8303080154

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X
Fiche: 50-000, 83/03/02, 8303020321

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys
KEPPLER, J. G. Region 3, Office of Director. 83/03/03. Commonwealth Edison Co. 2pp. 17492:014. 24X Fiche: 50-000, 83/03/03, 8303100364

8303110246 Forwards Rev 23 to CE-1-A, "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments
SHARTZ, E. D. Commonwealth Edison Co. 83/03/04. HAASS, W. P. Quality Assurance Branch. 1p. 17515:357. 24X Fiche: 50-000, 83/03/04, 8303110246

--8303110279 Rev 23 to "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments
SHEWSKI, W. J. Commonwealth Edison Co. CE-1-A R23. 83/03/07. 5pp. 17515:358. 24X Fiche: 50-000, 83/03/04, 8303110246

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl
EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 51pp. 17660:176. 24X
Fiche: 50-000, 83/03/07, 8303040005

8303150275 Advises of apparent error in FSAR analysis of accidental releases of radioactive liquids to groundwater Re-evaluation of two pump tests for Galena Platteville aquifer, ungrouted rock transmissivity values should be magnitude higher
TRAMM, T. R. Commonwealth Edison Co. 83/03/11. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17567:162. 24X
Fiche: 50-454, 83/03/11, 8303150275

8303290703 Requests addl info needed to complete evaluation of environ qualification program Questions & comments encl Info required by 830415 FSAR should be amended to reflect response
YOUNGBLOOD, B. J. Licensing Branch 1. 83/03/15. FARRAR, D. L. Commonwealth Edison Co. 4pp. 17730:356. 24X Fiche: 50-000, 83/03/15, 8303290703

8303280159 Forwards revised pages to FSAR Revs correct values of transmissivity of ungrouted rock used in analysis of accidental releases of radioactive liquids to groundwater
TRAMM, T. R. Commonwealth Edison Co. 83/03/21. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 8pp. 17707:355. 24X
Fiche: 50-454, 83/03/21, 8303280159

8303290526 Provides schedule for resolution of TMI Action Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps," in response to Generic Ltrs 83-10c & 83-10d Info will be provided by 830423 based on Westinghouse Owners Group input
SHARTZ, E. D. Commonwealth Edison Co. 83/03/24. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 17724:161. 24X
Fiche: 50-000, 83/03/24, 8303290526

F. Security, medical, emergency & fire protection plans

8303010595 Ack receipt of 830124 ltr identifying 1983 dates for emergency preparedness exercises within State of IL Dates determined to be within required exercise frequency
HIND, J. A. Region 3, Office of Director. 83/02/24. JONES, E. E. Illinois, State of. 2pp. 17336:208. 24X Fiche: 50-000, 83/02/24, 8303010595

--8303010618 Submits 1983 dates scheduled for emergency preparedness exercises for facilities within State of IL
JONES, E. E. Illinois, State of. 83/01/24. KEPPLER, J. Region 3, Office of Director. 2pp. 17336:210. 24X Fiche: 50-000, 83/02/24, 8303010595

8303100313 Forwards Amend 1 to 820816 fire protection rept Amend contains voluntary changes & items revised per NRC questions
SCHROEDER, C. W. Commonwealth Edison Co. 83/03/04. Division of Licensing. 2pp. 17491:214. 24X Fiche: 50-000, 83/03/04, 8303100313

--8303100318 Amend 1 to fire protection rept.
* Commonwealth Edison Co. 83/03/31. 28pp. 17491:216. 24X
Fiche: 50-454, 83/03/04, 8303100313

8303150326 Informs that prefire plans have been developed for areas necessary for receipt of new fuel, per Branch Technical Positions CMEB 9.5-1 & C.1.E & 10CFR50, App R, Section 3.K.12. Prefire plans available onsite for NRC review
SCHROEDER, C. W. Commonwealth Edison Co. 83/03/08. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17563:037. 24X
Fiche: 50-454, 83/03/08, 8303150326

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition Appropriate planning should take place to prevent possible transmission errors
HIND, J. A. Region 3, Office of Director. 83/03/22. Commonwealth Edison Co. 2pp. 17690:316. 24X Fiche: 50-000, 83/03/22, 8303240440

8303310124 Releases public version of revised emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records. 83/03/25. Document Management Branch. 1p. 17775:184. 24X Fiche: 50-000, 83/03/25, 8303310124

--8303310130 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure EG-1, "Coordination of Environs Group Activities by Environ Director."
* Commonwealth Edison Co. 83/03/17. Director's Office, Office of Inspection and Enforcement. 1p. 17775:185. 24X
Fiche: 50-000, 83/03/25, 8303310124

--8303310146 Public version of Rev 3 to Emergency Plan Implementing Procedure EG-1, "Coordination of Environs Group Activities by Environs Director."
PAJOWSKI, J. E. Commonwealth Edison Co. 83/03/08. 87pp. 17775:186. 24X Fiche: 50-000, 83/03/25, 8303310124

8303300532 Releases public version of request for return of listed controlled copies of emergency plan
FELTON, J. M. Division of Rules and Records. 83/03/28. Document Management Branch. 1p. 17763:178. 24X Fiche: 50-000, 83/03/28, 8303300532

--8303300561 Submits public version of request for return of listed controlled copies of emergency plan
FLESSNER, R. A. Commonwealth Edison Co. 83/03/15. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17763:179. 24X Fiche: 50-000, 83/03/28, 8303300532

G. Adjudicatory correspondence

8303010091 Requests to make limited appearance statement at OL hearings
GALBREATH, B. L. Affiliation Unknown. 83/02/21. Docketing & Services Branch. 1p. 17341:071. 24X Fiche: 50-454, 83/02/21, 8303010091

8303010094 Requests to make limited appearance statement at OL hearings
MEYER, A. Affiliation Unknown. 83/02/22. Docketing & Services Branch. 1p. 17335:329. 24X Fiche: 50-454, 83/02/22, 8303010094

8303010068 Puts recipient on notice that copies of IL plan for radiological accidents must not be disseminated in any form, but must be returned to State of IL at completion of proceedings Vols subj to ongoing rev.
BIELAWSKI, A P. Isham, Lincoln & Beale BIELAWSKI, A P. Commonwealth Edison Co 83/02/25 CHAVEZ, D Safe Energy for New Haven lp 17335 084 24X Fiche 50-454, 83/02/25, 8303010068

8303030381 Forwards util 830209 ltr committing to limit power operation to 70% or lower if steam generators are not modified to minimize effect of flow-induced vibration prior to startup.
GALLO, J Isham, Lincoln & Beale GALLO, J Commonwealth Edison Co 83/02/28 SMITH, I W , COLE, R F , CALLIHAN, A D Atomic Safety and Licensing Board Panel 25pr 17410 234 24X Fiche 50-454, 83/02/28, 8303030381

8303070155 Forwards J Greenberg notice of appearance re QA/QC issues Notice of A Haswell appearance withdrawn Certificate of Svc encl
WHICHER, J M Businessmen for the Public Interest WHICHER, J M DeKalb Area Alliance for Responsible Energy WHICHER, J M Sinnissippi Alliance for the Environment (SAFE) 83/03/01
SMITH, I W , COLE, R F , CALLAHAN, A D Atomic Safety and Licensing Board Panel 4pp 17433 108 24X Fiche 50-454, 83/03/01, 8303070155

8303140275 Forwards list of witnesses presently scheduled to testify in proceeding Svc list encl Related correspondence
BIELAWSKI, A Isham, Lincoln & Beale BIELAWSKI, A Commonwealth Edison Co 83/03/07 SMITH, I W , COLE, R F , CALLIHAN, A D Atomic Safety and Licensing Board Panel 5pp 17535 110 24X Fiche 50-454, 83/03/07, 8303140275

8303240550 Identifies witnesses util expects to call to litigate issues in Paragraph 3(a) of agreement
COPELAND, V G Isham, Lincoln & Beale COPELAND, V G Commonwealth Edison Co 83/03/18 SAVAGE, B Affiliation Unknown lp 17682 215 24X Fiche 50-454, 03/03/18, 8303240550

8303230264 Memorandum & order directing that info be presented on operational QC implications of Salem 830222 & 25 failures of automatic reactor scram Presentation should include proposed maint procedures at Byron
SMITH, I W Atomic Safety and Licensing Board Panel 83/03/21 1p 17661 196 24X Fiche 50-454, 83/03/21, 8303230264

8303240386 Motion for leave to respond to intervenor 830317 reply to licensee response to ASLB #20914 order by 830405 Licensee entitled to respond to specific issues raised by intervenors Certificate of Svc encl
COPELAND, V G Consumers Power Co COPELAND, V G Isham, Lincoln & Beale 83/03/21 Atomic Safety and Licensing Board Panel 5pp 17679 112 24X Fiche 50-454, 83/03/21, 8303240386

8303250137 Confirms 830324 telcon re motion to have ASLB receive transcribed copy of diagram placed on blackboard at 830310 hearing as evidence Motion opposed Unconditional receipt inappropriate due to abbreviated nature of explanation
RAWSON, R J Hearing Branch 4 83/03/24 THOMAS, D C Affiliation Unknown 2pp 17692 207 24X Fiche 50-454, 83/03/24, 8303250137

## H General correspondence

8303030528 Informs that DL Farrar has replaced LD DeHGeorge as Director of Nuclear Licensing for util Rev of current NRC distribution list requested
FARRAR, D L Commonwealth Edison Co 83/02/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17409 048 24X Fiche 50-000, 83/02/02, 8303030528

## I Financial information

8303070135 Forwards Annual Financial Rept 1982
BRESEMANN, R W Commonwealth Edison Co 83/02/28 Division of Licensing 1p 17433 001 24X Fiche 50-000, 83/02/28, 8303070135

--8303070151 Annual Financial Rept 1982
O'CONNOR, J J Commonwealth Edison Co 83/02/03 13pp 17433 002 24X Fiche 50-000, 83/02/28, 8303070135

## J Insurance & indemnity information

8303080135 Forwards Endorsements 1-6 to NELIA Policy NF-237
OSTER, J Commonwealth Edison Co 83/02/01 SALTZMAN, J Assistant Director for State & Licensee Relations 17pp 17458 228 24X Fiche 50-454, 83/03/01, 8303080135

## K Utility Final Safety Analysis Report (FSAR) & amends

8303220317 Forwards affidavit affirming that Amend 41 to FSAR distributed per Encl 1 of NRC 781020 ltr
LENTINE, F G Commonwealth Edison Co 83/03/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17656 026 24X Fiche 50-000, 83/03/18, 8303220317

## O Inspection reports, IE Bulletins & correspondence

8303110355 Board Notification 83-14 forwards followup info on apparent deficiencies in Midland-Ross superstrut matl
EISENHUT, D G Division of Licensing 83/02/18 PALLADINO, N Commissioners 24pp 17546 205 24X Fiche 50-000, 83/02/18, 8303110355

8303040591 Forwards IE Insp Rept 50-454/83-03 on 830118-0204 No noncompliance noted
LITTLE, W S Division of Engineering 83/02/22 REED, C Commonwealth Edison Co 2pp 17368 356 24X Fiche 50-454, 83/02/22, 8303040591

--8303040596 IE Insp Rept 50-454/83-03 on 830118-0204 No noncompliance noted Major areas inspected preoperational test procedures, performance & result evaluations & licensee action on previous open items
RING, M A , FEYES, L Region 3, Office of Director 83/02/16 5pp 17368 360 24X Fiche 50-454, 83/02/22, 8303040591

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 11lpp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367

8303170532 Forwards IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al, on 830126 No noncompliance noted
DAVIS, A B Region 3, Office of Director 83/02/25 REED, C Commonwealth Edison Co 2pp 17610 143 24X Fiche 50-000, 83/02/25, 8303170532

--8303170557 IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al, on 830126 No noncompliance noted Major areas discussed proposed guidelines util personnel should use for providing info to Region III inspectors
GULDEMOND, W G Division of Project & Resident Programs 83/02/15 4pp 17610 145 24X Fiche 50-000, 83/02/25, 8303170532

8303040500 Forwards Rev 2 to "Preservice Insp Program Plan Tables" & plan Apps A & B
TRAMM, T R Commonwealth Edison Co 83/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17373 120 24X Fiche 50-454, 83/03/01, 8303040500

--8303040501 Rev 2 to "Preservice Insp Program Plan Tables." Apps A & B to plan encl
* Commonwealth Edison Co 83/03/01 153pp 17373 122 24X Fiche 50-454, 83/03/01, 8303040500

8303080425 Requests relief from certain inservice insp requirements for snubbers Justification for relief requests encl
TRAMM, T R Commonwealth Edison Co 83/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 17454 055 24X Fiche 50-000, 83/03/01, 8303080425

8303080305 Notifies of util intent to utilize ASME Code Case N-340 providing for alternate rules for exam of weld edge preparation by ultrasonic exam of completed weld NRC acceptability requested ASME Code Case N-340 encl
TRAMM, T R Commonwealth Edison Co 83/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17449 260 24X Fiche 50-000, 83/03/02, 8303080305

8303070036 Forwards responses to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Bunker-Ramo electrical penetrations installed in LaSalle Unit 2, Byron Unit 2 & Braidwood Unit 2
SWARTZ, E D Commonwealth Edison Co 83/03/03 KEPPLER, J G Region 3, Office of Director 13pp 17435 290 24X Fiche 50-000, 83/03/03, 8303070036

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc 11?pp 17411 070 24X Fiche 50-000, 83/03/11, 8212060380

8303210293 Ack receipt of 830224 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04
SPESSARD,R L. Region 3, Office of Director. 83/03/16. REED,C. Commonwealth Edison Co. 1p. 17632.046. 24X Fiche 50-454,83/03/16. 8303210293

8303220277 Forwards applicant 830224 ltr inadvertently omitted from NRC 830316 ltr to applicant
MAXSON,J R. Region 3, Office of Director. 83/03/16. Document Management Branch. 1p. 17656.189. 24X Fiche 50-454,83/03/16. 8303220277

--8303220293 Submits revised schedule for completion of review of cable pulling tension per IE Insp Repts 50-454/82-05 & 50-455/82-06 Addl analysis to assure that recorded tensions acceptable should be completed by 830701.
STIEDE,W L. Commonwealth Edison Co. 83/02/24. KEPPLER,J G. Region 3, Office of Director. 1p. 17654.190. 24X Fiche 50-454,83/03/16. 8303220277

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche 50-000,83/03/18. 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 12?pp. 17774.352. 24X Fiche 50-000,83/03/21. 8212060387

8303280289 Ack receipt of 830223 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04. Visual weld exam classification used only for surface conditions not affecting integrity of weld.
SPESSARD,R L. Region 3, Office of Director. 83/03/22. REED,C. Commonwealth Edison Co. 1p. 17706.077. 24X Fiche 50-454,83/03/22. 8303280289

--8303280301 Responds to NRC 820624 ltr re violations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04 Corrective actions program assuring verification updated requirements for inspector contractor procedures established.
STIEDE,W L. Commonwealth Edison Co. 83/02/23. KEPPLER,J G. Region 3, Office of Director. 33pp. 17706.078. 24X Fiche 50-454,83/03/22. 8303280289

8303300459 Responds to IE Insp Rept 50-454/83-03 open items re RCS leak detection sys capability, combination of vol control tank level,charging & letdown flow provide real-time indication of onset of RCS leakage FSAR Section 5.2.5 to be revised.
SWARTZ,E D. Commonwealth Edison Co. 83/03/23. DENTON,H R. Office of Nuclear Reactor Regulation, Director. 4pp. 17731.150. 24X Fiche 50-000,83/03/23. 8303300459

8303310211 Forwards addl info in response to IE Bulletin 81-03 re methods to control Corbicula. "Environ Studies of Braidwood Cooling Pond, 1982," encl.
SWARTZ,E D. Commonwealth Edison Co. 83/03/28. DENTON,H R. Office of Nuclear Reactor Regulation, Director. 17pp. 17755.095. 24X Fiche 50-000,83/03/28. 8303310211

## 6. Reportable occurrences: LERs & related correspondence

8303150620 Board Notification 83-26 Forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protection sys. Info may affect conclusions re probability of corrective measures for ATWS.
EISENHUT,D G. Division of Licensing. 83/03/03. PALLADINO,N. GILINSKY,V. AHEARNE,J. Commissioners. 24pp. 17584.097. 24X Fiche 50-000,83/03/03. 8303150620

## 7. Hearing transcripts on non-antitrust matters

8303010297 Forwards GL Wegner,G Staley & R Codell testimony on listed contentions.
GOLDBERG,S C. Hearing Branch 2. 83/02/25. PLEASANT,E. Docketing & Services Branch. 1p. 17344.112. 24X Fiche 50-454,83/02/25. 8303010297

--8303010403 Testimony of GL Wenger on Rockford League of Women Voters Contentions 19 & 109 & DeKalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 2 re offsite emergency planning.
WENGER,G L. Federal Emergency Management Agency. 83/02/25. 16pp. 17344.113. 24X Fiche 50-454,83/02/25. 8303010297

--8303010309 Testimony of R Codell & G Staley on Rockford League of Women Voters Contentions 39 & 109 re liquid pathways.
CODELL,R. STALEY,G. Environmental & Hydrologic Engineering Branch. 83/02/25. 1p. 17344.129. 24X Fiche 50-454,83/02/25. 8303010297

8303010306 Forwards testimony of WD Fletcher,MR Patel,DD Malinowski, MJ Wootten,L Conway,TF Timmons,JC Blomgren & N Paul.
GALLO,J. Isham, Lincoln & Beale. GALLO,J. Commonwealth Edison Co. 83/02/25. SMITH,I W., COLE,R F., CALLIHAN,A D. Atomic Safety and Licensing Board Panel. 1p. 17345.224. 24X Fiche 50-454,83/02/25. 8303010306

--8303010312 Testimony of WD Fletcher re steam generator tube integrity.
FLETCHER,W D. Commonwealth Edison Co. FLETCHER,W D. Westinghouse Electric Corp. 83/02/25. 21pp. 17345.225. 24X Fiche 50-454,83/02/25. 8303010306

--8303010317 Testimony of MR Patel re steam generator tube integrity (tube plugging criteria).
PATEL,M R. Commonwealth Edison Co. PATEL,M R. Westinghouse Electric Corp. 83/02/25. 17pp. 17345.246. 24X Fiche 50-454,83/02/25. 8303010306

--8303010320 Testimony of DD Malinowski re steam generator tube integrity (insp & eddy current testing).
MALINOWSKI,D D. Commonwealth Edison Co. MALINOWSKI,D D. Westinghouse Electric Corp. 83/02/25. 24pp. 17345.263. 24X Fiche 50-454,83/02/25. 8303010306

--8303010324 Testimony of MJ Wootten re steam generator tube integrity (water chemistry).
WOOTTEN,M J. Commonwealth Edison Co. WOOTTEN,M J. Westinghouse Electric Corp. 83/02/25. 20pp. 17345.287. 24X Fiche 50-454,83/02/25. 8303010306

--8303010331 Testimony of L Conway re steam generator tube integrity (steam generator design).
CONWAY,L. Commonwealth Edison Co. CONWAY,L. Westinghouse Electric Corp. 83/02/25. 23pp. 17345.307. 24X Fiche 50-454,83/02/25. 8303010306

--8303010337 Testimony of TF Timmons re steam generator tube integrity (flow-induced vibration phenomenon).
TIMMONS,T F. Commonwealth Edison Co. TIMMONS,T F. Westinghouse Electric Corp. 83/02/25. 31pp. 17345.330. 24X Fiche 50-454,83/02/25. 8303010306

--8303010340 Testimony of JC Blomgren re steam generator tube integrity (water chemistry, eddy current testing, loose parts control program & Comm Ed commitment re flow-induced vibration phenomenon & tube plugging criterion).
BLOMGREN,J C. Commonwealth Edison Co. 83/02/25. 26pp. 17345.361. 24X Fiche 50-454,83/02/25. 8303010306

--8303010345 Testimony of N Paul re steam generator tube integrity (preservice insp).
PAUL,N. Commonwealth Edison Co. PAUL,N. Ebasco Services, Inc (subs. of Enserch Corp.). 83/02/25. 12pp. 17346.026. 24X Fiche 50-454,83/02/25. 8303010306

8303030357 Forwards MJ Hitchler testimony re quantitative assessment of steam generator tube integrity,per Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance Contention 9c & Rockford League of Women Voters Contention 22.
GALLO,J. Isham, Lincoln & Beale. GALLO,J. Commonwealth Edison Co. 83/02/28. SMITH,I W., COLE,R F., CALLIHAN,A D. Atomic Safety and Licensing Board Panel. 1p. 17410.275. 24X Fiche 50-454,83/02/28. 8303030357

--8303030368 Testimony of MJ Hitchler re quantitative assessment of steam generator tube integrity. Steam generator tube degradation under normal operating & accident conditions is not safety concern.
HITCHLER,M J. Commonwealth Edison Co. 83/02/28. 18pp. 17410.276. 24X Fiche 50-454,83/02/28. 8303030357

8303070034 Forwards testimony of MA Smith,DW Gallagher & P Stomfay-Stitz re QA/QC Contention 1A w/o Smith testimony. Certificate of Svc encl.
WHICHER,J M. Businessmen for the Public Interest. WHICHER,J M. DeKalb Area Alliance for Responsible Energy. WHICHER,J M. Sinnissippi Alliance for the Environment (SAFE). 83/03/01.
SMITH,I W., COLE,R F., CALLAHAN,A D. Atomic Safety and Licensing Board Panel. 4pp. 17434.001. 24X Fiche 50-454,83/03/01. 8303070034

--8303070049 Testimony of DW Gallagher re use of concrete in plant Concrete batch plant sys incapable of mixing competent concrete Supervision & insp of placement of concrete inadequate
GALLAGHER,D W Sinnissippi Alliance for the Environment (SAFE)
GALLAGHER,D W DeKalb Area Alliance for Responsible Energy
GALLAGHER,D W League of Women Voters of Rockford, IL 82/09/06
39pp 17434.005 24X Fiche 50-454,83/03/01,8303070034

--8303070054 Testimony of P Stomfay-Stitz re work while in Blount Brothers Corp employ QA/QC matls controller training & supervision inadequate Special insp of tendons inadequately performed &/or documented
STOMFAY-STITZ Sinnissippi Alliance for the Environment (SAFE)
STOMFAY-STITZ DeKalb Area Alliance for Responsible Energy
STOMFAY-STITZ League of Women Voters of Rockford, IL 82/09/30
160pp 17434.045 24X Fiche 50-454,83/03/01,8303070034

8303070170 Transcript of 830301 hearing in Rockford, IL Pp 337-417
* Atomic Safety and Licensing Board Panel 83/03/01 81pp
17430.117 24X Fiche 50-454,83/03/01,8303070170

8303080058 Testimony of D Pope in response to D Gallagher allegations challenging QA program adequacy Related correspondence
POPE,D Commonwealth Edison Co 83/03/01 58pp 17436.285 24X Fiche 50-454,83/03/01,8303080058

8303080065 Testimony of R Barnhart in response to P Stomfay-Stitz allegations in support of Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 1A re QA adequacy Related correspondence
BARNHART,R Commonwealth Edisnn Co 83/03/01 8pp 17457.231 24X Fiche 50-454,83/03/01,8303080065

8303080069 Testimony of ML Somsag re M Smith allegations on Contention 1A concerning QA program Related correspondence
SOMSAG,M L Commonwealth Edison Co 83/03/01 16lpp 17447.001 24X Fiche 50-454,83/03/01,8303080069

8303080074 Testimony of MA Stanish re Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 1 on ability & willingness of util to assure safe operation of facility Related correspondence
STANISH,M A Commonwealth Edison Co 83/03/01 77pp 17456.278 24X Fiche 50-454,83/03/01,8303080074

8303080080 Testimony of LO Del George re Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 1 on ability & willingness of util to assure safe operation of facility Related correspondence
DELGEORGE,L O Commonwealth Edison Co 83/03/01 39pp 17457.126 24X Fiche 50-454,83/03/01,8303080080

8303080094 Testimony of RE Guerio re Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 1 on ability & willingness of util to assure safe operation of facility Related correspondence
GUERIO,R E Commonwealth Edison Co 83/03/01 21pp 17457.195 24X Fiche 50-454,83/03/01,8303080094

8303080098 Testimony of L Holish re consolidated Contentions 39 & 109 on assumptions used in determining time radioactive contaminants released to groundwater would take to travel to nearest well Related correspondence
HOLISH,L Commonwealth Edison Co HOLISH,L Sargent & Lundy, Inc
83/03/01 15pp 17456.263 24X Fiche 50-454,83/03/01,8303080098

8303080104 Testimony of GC Klopp re consolidated Contentions 39 & 109 on likelihood of core melt leading to significant releases of radioactive contaminants to groundwater Related correspondence
KLOPP,G C Commonwealth Edison Co 83/03/01 13pp 17458.175 24X Fiche 50-454,83/03/01,8303080104

8303080139 Transcript of 830301 limited appearance session in Rockford, IL Pp 417 1-417 125
* Atomic Safety and Licensing Board Panel 83/03/01 127pp
17436.099 24X Fiche 50-454,83/03/01,8303080139

8303080186 Testimony of EE Jones re Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 3 & Rockford League of Women Voters Contentions 19 & 108 Related correspondence
JONES,E E Commonwealth Edison Co JONES,E E Illinois, State of
83/03/01 424pp 17440.001 24X Fiche 50-454,83/03/01,8303080186

8303080200 Testimony of JC Golden re Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 3 & Rockford League of Women Voters Contentions 19 & 103 Related correspondence
GOLDEN,J C Commonwealth Edison Co 83/03/01 303pp 17446.036 24X Fiche 50-454,83/03/01,8303080200

8303080204 Testimony of DD Ed re role of IL Dept of Nuclear Safety in site emergency planning Related correspondence
ED,D D Commonwealth Edison Co ED,D D Illinois, State of
83/03/01 4lpp 17457.023 24X Fiche 50-454,83/03/01,8303080204

8303080216 Testimony of GP Lahti re radiological impacts associated w/assumed releases to groundwater of radioactive contaminants Related correspondence
LAHTI,G P Commonwealth Edison Co LAHTI,G P Sargent & Lundy, Inc 83/03/01 8pp 17457.082 24X Fiche 50-454,83/03/01, 8303080216

8303080262 Testimony of J Mihovilovich re Stomfay-Stitz allegations concerning adequacy of site QA Related correspondence
MIHOVILOVICH,J Commonwealth Edison Co 83/03/01 289pp
17441.065 24X Fiche 50-454,83/03/01,8303080262

8303080481 Testimony of WJ Shewski re Contention 1 on QA program Related correspondence encl
SHEWSKI,W J Commonwealth Edison Co 83/03/01 44pp 17453.023 24X Fiche 50-454,83/03/01,8303080481

8303080482 Testimony of C Reed on Contention 1 re util inability or unwillingness to operate facility within NRC regulations Related correspondence
REED,C Commonwealth Edison Co 83/03/01 11pp 17452.337 24X Fiche 50-454,83/03/01,8303080482

8303090273 Public appearance statements received by ASLB on 830301 in Rockford, IL
QUIGG,C Pollution & Environmental Problems, Inc SKALA,J J ,
SKALA,S Y Affiliation Unknown 83/03/01 37pp 17442.158 24X Fiche 50-454,83/03/01,8303090273

8303080397 Transcript of 830302 hearing in Rockford, IL Pp 418-696
Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/03/02 317pp
17451.001 24X Fiche 50-454,83/03/02,8303080397

8303080277 Transcript of 830303 hearing in Rockford, IL Pp 697-934
Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/03/03 341pp
17442.001 24X Fiche 50-454,83/03/03,8303080277

8303080143 Transcript of 830304 hearing in Rockford, IL Pp 935-1,041
Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/03/04 116pp
17458.356 24X Fiche 50-454,83/03/04,8303080143

8303080250 Testimony of DL Smith re site emergency planning State of IL plan for radiological accidents encl Related correspondence
SMITH,D L Commonwealth Edison Co SMITH,D L Illinois, State of
83/03/07 619pp 17448.001 24X Fiche 50-454,83/03/07,8303080250

8303090142 Testimony of DW Gallaghor re incompetent mixing of concrete at concrete batch plant
GALLAGHER,D W DeKalb Area Alliance for Responsible Energy
GALLAGHER,D W Sinnissippi Alliance for the Environment (SAFE)
GALLAGHER,D W League of Women Voters of Rockford, IL 83/03/07
4lpp 17470.311 24X Fiche 50-454,83/03/07,8303090142

8303090294 Memorandum forwarding written public appearance statements received by ASLB on 830301 in Rockford, IL W/o encl
MORAN,D M Atomic Safety and Licensing Board Panel 83/03/07 1p
17473.362 24X Fiche 50-454,83/03/07,8303090294

8303110216 Transcript of 830307 hearing in Rockford, IL Pp 1,042-1,140
* Atomic Safety and Licensing Board Panel 83/03/07 101pp
17519.192 24X Fiche 50-454,83/03/07,8303110216

8303140037 Transcript of 830308 hearing in Rockford, IL Pp 1,141-1,371
Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/03/08 289pp
17528.335 24X Fiche 50-454,83/03/08,8303140037

8303150173 Transcript of 830309 hearing in Rockford, IL Pp 1,372-1,569
Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/03/09 401pp
17549.056 24X Fiche 50-454,83/03/09,8303150173

8303150201 Transcript of 830310 hearing in Rockford, IL Pp 1,570-1,825
Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/03/10 316pp
17553.074 24X Fiche 50-454,83/03/10,8303150201

8303150156 Transcript of 830311 hearing in Rockford, IL Pp 1,826-1,923
Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/03/11 202pp
17556.124 24X Fiche 50-454,83/03/11,8303150156

8303230041 Transcript of 830315 hearing in Rockford, IL Pp 1, 924-2, 140 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/03/15 296pp
17664 090 24X Fiche 50-454, 83/03/15, 8303230041

8303220195 Forwards Pp 12-17, missing from P Stomfay-Stitz prefiled testimony
WHICHER, J M Businessmen for the Public Interest 83/03/16
SMITH, I W , CALLIHAN, A D , COLE, R F Atomic Safety and Licensing Board Panel 2pp 17657 124 24X Fiche 50-454, 83/03/16, 8303220195

--8303220198 Missing Pp 12-17 from P Stomfay-Stitz prefiled testimony
STOMFAY-STITZ League of Women Voters of Rockford, IL
STOMFAY-STITZ DeKalb Area Alliance for Responsible Energy
STOMFAY-STITZ Sinnissippi Alliance for the Environment (SAFE)
83/03/16 6pp 17657 126 24X Fiche 50-454, 83/03/16, 8303220195

8303230037 Transcript of 830316 hearing in Rockford, IL Pp 2, 141-2, 336
* Atomic Safety and Licensing Board Panel 83/03/16 96pp
17663 354 24X Fiche 50-454, 83/03/16, 8303230037

8303300453 Forwards P 22 of Shewski testimony, inadvertently omitted from prefiled testimony Related correspondence
HERRIN, M G Isham, Lincoln & Beale 83/03/22 SMITH, I W , COLE, R F , CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 17731 101 24X Fiche 50-454, 83/03/22, 8303300453

--8303300457 P 22 of Shewski testimony, inadvertently omitted from prefiled testimony
SHEWSKI Affiliation Unknown 83/03/22 2pp 17731 102 24X Fiche 50-454, 83/03/22, 8303300453

8303300409 Forwards Pp 31 & 37 of M Smith prefiled testimony
GREENBERG, J Businessmen for the Public Interest GREENBERG, J League of Women Voters of Rockford, IL GREENBERG, J Sinnissippi Alliance for the Environment (SAFE) 83/03/23 SMITH, I W , COLE, R F , CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 17731 093 24X Fiche 50-454, 83/03/23, 8303300409

--8303300431 Pp 31 & 37 to M Smith prefiled testimony
SMITH, M Sinnissippi Alliance for the Environment (SAFE)
SMITH, M DeKalb Area Alliance for Responsible Energy SMITH, M League of Women Voters of Rockford, IL 83/03/23 2pp
17731 095 24X Fiche 50-454, 83/03/23, 8303300409

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee " Svc list encl
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000, 83/02/24, 8302250505

8303040631 Forwards listing of projected operator licensing exam dates including type of exam & probable number of candidates, in response to 830111 Generic Ltr 83-01
SWARTZ, E D Commonwealth Edison Co 83/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 17367 209 24X Fiche 50-000, 83/03/01, 8303040631

DOCKET STN-50-455 BYRON STATION, UNIT 2

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24X Fiche 50-000, 83/02/16, 8302170082

8303080154 Forwards Rev 5 to "Offsite Dose Calculation Manual "
PAJOWSKI, J Commonwealth Edison Co 83/02/28 CASE, E G NRC - No Detailed Affiliation Given 1p 17445 191 24X Fiche 50-454, 83/02/28, 8303080154

--8303080157 Rev 5 to "Offsite Dose Calculation Manual "
* Commonwealth Edison Co 83/02/28 204pp 17445 192 24X Fiche 50-454, 83/02/28, 8303080154

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X Fiche 50-000, 83/03/02, 8303020321

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys
KEPPLER, J G Region 3, Office of Director 83/03/03
Commonwealth Edison Co 2pp 17492 014 24X Fiche 50-000, 83/03/03, 8303100364

8303110246 Forwards Rev 23 to CE-1-A, "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments
SWARTZ, E D Commonwealth Edison Co 83/03/04 HAASS, W P Quality Assurance Branch 1p 17515 357 24X Fiche 50-000, 83/03/04, 8303110246

--8303110279 Rev 23 to "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments
SHEWSKI, W J Commonwealth Edison Co CE-1-A R23 83/03/07 5pp 17515 358 24X Fiche 50-000, 83/03/04, 8303110246

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12) Svc list encl
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 5lpp 17600 176 24X Fiche 50-000, 83/03/07, 8303040005

8303150275 Advises of apparent error in FSAR analysis of accidental releases of radioactive liquids to groundwater Re-evaluation of two pump tests for Galena Platteville acquifer, ungrouted rock transmissivity values should be magnitude higher
TRAMM, T R Commonwealth Edison Co 83/03/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17567 162 24X Fiche 50-454, 83/03/11, 8303150275

8303290703 Requests addl info needed to complete evaluation of environ qualification program Questions & comments encl Info required by 830415 FSAR should be amended to reflect response
YOUNGBLOOD, B J Licensing Branch 1 83/03/15 FARRAR, D L
Commonwealth Edison Co 6pp 17730 356 24X Fiche 50-000, 83/03/15, 8303290703

8303280159 Forwards revised pages to FSAR Revs correct values of transmissivity of ungrouted rock used in analysis of accidental releases of radioactive liquids to groundwater
TRAMM, T R Commonwealth Edison Co 83/03/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 17707 355 24X Fiche 50-454, 83/03/21, 8303280159

8303290526 Provides schedule for resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps," in response to Generic Ltrs 83-10c & 83-10d Info will be provided by 830423 based on Westinghouse Owners Group input
SWARTZ, E D Commonwealth Edison Co 83/03/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17724 161 24X Fiche 50-000, 83/03/24, 8303290526

F. Security, medical, emergency & fire protection plans

8303010595 Ack receipt of 830124 ltr identifying 1983 dates for emergency preparedness exercises within State of IL Dates determined to be within required exercise frequency
HIND, J A Region 3, Office of Director 83/02/24 JONES, E E Illinois, State of 2pp 17336 208 24X Fiche 50-000, 83/02/24, 8303010595

--8303010618 Submits 1983 dates scheduled for emergency preparedness exercises for facilities within State of IL
JONES, E E Illinois, State of 83/01/24 KEPPLER, J Region 3, Office of Director 2pp 17336 210 24X Fiche 50-000, 83/02/24, 8303010595

8303100313 Forwards Amend 1 to 820816 fire protection rept Amend contains voluntary changes & items revised per NRC questions
SCHROEDER, C W Commonwealth Edison Co 83/03/04 Division of Licensing 2pp 17491 214 24X Fiche 50-000, 83/03/04, 8303100313

--8303100318 Amend 1 to fire protection rept
* Commonwealth Edison Co 83/03/31 28pp 17491 216 24X Fiche 50-454, 83/03/04, 8303100313

8303150326 Informs that prefire plans have been developed for areas necessary for receipt of new fuel, per Branch Technical Positions CMEB 9 5-1 & C 1 E & 10CFR50, App R, Section 3 K 12 Prefire plans available onsite for NRC review
SCHROEDER, C W Commonwealth Edison Co 83/03/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17563 037 24X Fiche 50-454, 83/03/08, 8303150326

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition Appropriate planning should take place to prevent possible transmission errors.
HIND, J A. Region 3, Office of Director 83/03/22 Commonwealth Edison Co 2pp 24X Fiche 50-000, 83/03/22, 8303240440.

8303310124 Releases public version of revised emergency plan implementing procedure.
FELTON, J M. Division of Rules and Records 83/03/25 Document Management Branch 1p 17775 184 24X Fiche 50-000, 83/03/25, 8303310124.

--8303310130 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure EG-1, "Coordination of Environs Group Activities by Environ Director."
* Commonwealth Edison Co 83/03/17 Director's Office, Office of Inspection and Enforcement 1p 17775 185 24X Fiche 50-000, 83/03/25, 8303310124.

--8303310146 Public version of Rev 3 to Emergency Plan Implementing Procedure EG-1, "Coordination of Environs Group Activities by Environs Director."
PAJOWSKI, J E. Commonwealth Edison Co 83/03/08 87pp 17775 186 24X Fiche 50-000, 83/03/25, 8303310124.

8303300532 Releases public version of request for return of listed controlled copies of emergency plan.
FELTON, J M. Division of Rules and Records 83/03/28 Document Management Branch 1p 17763 178 24X Fiche 50-000, 83/03/28, 8303300532.

--8303300561 Submits public version of request for return of listed controlled copies of emergency plan.
FLESSNER, R A. Commonwealth Edison Co 83/03/15 DENTON, H R. Office of Nuclear Reactor Regulation, Director 1p 17763 179 24X Fiche 50-000, 83/03/28, 8303300532.

## Q. Adjudicatory correspondence

8303010091 Requests to make limited appearance statement at OL hearings.
GALBREATH, B L. Affiliation Unknown 83/02/21 Docketing & Services Branch 1p 17341 071 24X Fiche 50-454, 83/02/21, 8303010091.

8303010094 Requests to make limited appearance statement at OL hearings.
MEYER, A. Affiliation Unknown 83/02/22 Docketing & Services Branch 1p 17335 329 24X Fiche 50-454, 83/02/22, 8303010094.

8303010068 Puts recipient on notice that copies of IL plan for radiological accidents must not be disseminated in any form, but must be returned to State of IL at completion of proceedings Vols subj to ongoing rev.
BIELAWSKI, A P. Isham, Lincoln & Beale BIELAWSKI, A P. Commonwealth Edison Co 83/02/25 CHAVEZ, D Safe Energy for New Haven 1p 17335 084 24X Fiche 50-454, 83/02/25, 8303010068.

8303030381 Forwards util 830209 ltr committing to limit power operation to 70% or lower if steam generators are not modified to minimize effect of flow-induced vibration prior to startup.
GALLO, J Isham, Lincoln & Beale GALLO, J Commonwealth Edison Co 83/02/28 SMITH, I W ; COLE, R F ; CALLIHAN, A D Atomic Safety and Licensing Board Panel 25pp 17410 234 24X Fiche 50-454, 83/02/28, 8303030381.

8303070155 Forwards J Greenberg notice of appearance re QA/QC issues. Notice of A Heswell appearance withdrawn Certificate of Svc encl.
WHICHER, J M. Businessmen for the Public Interest WHICHER, J M. DeKalb Area Alliance for Responsible Energy WHICHER, J M. Sinnissippi Alliance for the Environment (SAFE) 83/03/01 SMITH, I W ; COLE, R F ; CALLAHAN, A D Atomic Safety and Licensing Board Panel 4pp 17433 108 24X Fiche 50-454, 83/03/01, 8303070155.

8303140275 Forwards list of witnesses presently scheduled to testify in proceeding Svc list encl Related correspondence.
BIELAWSKI, A Isham, Lincoln & Beale BIELAWSKI, A Commonwealth Edison Co 83/03/07 SMITH, I W ; COLE, R F ; CALLIHAN, A D Atomic Safety and Licensing Board Panel 5pp 17535 110 24X Fiche 50-454, 83/03/07, 8303140275.

8303240550 Identifies witnesses util expects to call to litigate issues in Paragraph 3(a) of agreement.
COPELAND, V G. Isham, Lincoln & Beale COPELAND, V G. Commonwealth Edison Co 83/03/18 SAVAGE, B Affiliation Unknown 1p 17682 215 24X Fiche 50-454, 83/03/18, 8303240550.

8303230264 Memorandum & order directing that info be presented on operational QC implications of Salem 830222 & 25 failures of automatic reactor scram Presentation should include proposed maint procedures at Byron.
SMITH, I W Atomic Safety and Licensing Board Panel 83/03/21 1p 17661 196 24X Fiche 50-454, 83/03/21, 8303230264.

8303240386 Motion for leave to respond to intervenor 830317 reply to licensee response to ASLB 820914 order, by 830405 Licensee entitled to respond to specific issues raised by intervenors Certificate of Svc encl.
COPELAND, V G. Consumers Power Co COPELAND, V G. Isham, Lincoln & Beale 83/03/21 Atomic Safety and Licensing Board Panel 5pp 17679 112 24X Fiche 50-454, 83/03/21, 8303240386.

8303250137 Confirms 830324 telcon re motion to have ASLB receive transcribed copy of diagram placed on blackboard at 830310 hearing as evidence Motion opposed Unconditional receipt inappropriate due to abbreviated nature of explanation.
RAWSON, R J. Hearing Branch 4 83/03/24 THOMAS, D C. Affiliation Unknown 2pp 17692 207 24X Fiche 50-454, 83/03/24, 8303250137.

## H. General correspondence

8303030528 Informs that DL Farrar has replaced LD DelGeorge as Director of Nuclear Licensing for util Rev of current NRC distribution list requested.
FARRAR, D L. Commonwealth Edison Co 83/02/02 DENTON, H R. Office of Nuclear Reactor Regulation, Director 1p 17409 048 24X Fiche 50-000, 83/02/02, 8303030528.

## I. Financial information

8303070135 Forwards Annual Financial Rept 1982.
BRESEMANN, R W Commonwealth Edison Co 83/02/28 Division of Licensing 1p 17433 001 24X Fiche 50-000, 83/02/28, 8303070135.

--8303070151 Annual Financial Rept 1982.
O'CONNOR, J J. Commonwealth Edison Co 83/02/03 13pp 17433 002 24X Fiche 50-000, 83/02/28, 8303070135.

## K. Utility Final Safety Analysis Report (FSAR) & amends

8303220317 Forwards affidavit affirming that Amend 41 to FSAR distributed per Encl 1 of NRC 781020 ltr.
LENTINE, F G. Commonwealth Edison Co 83/03/18 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 17656 026 24X Fiche 50-000, 83/03/18, 8303220317.

## O. Inspection reports, IE Bulletins & correspondence

8303110355 Board Notification 83-14 forwards followup info on apparent deficiencies in Midland-Ross superstrut matl.
EISENHUT, D G. Division of Licensing 83/02/18 PALLADINO, N. Commissioners 24pp 17546 205 24X Fiche 50-000, 83/02/18, 8303110355.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 111pp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367.

8303170532 Forwards IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al, on 830126 No noncompliance noted.
DAVIS, A B. Region 3, Office of Director 83/02/25 REED, C. Commonwealth Edison Co 2pp 17610 143 24X Fiche 50-000, 83/02/25, 8303170532.

--8303170557 IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al, on 830126 No noncompliance noted Major areas discussed proposed guidelines util personnel should use for providing info to Region III inspectors.
GULDEMOND, W G. Division of Project & Resident Programs 83/02/15 4pp 17610 145 24X Fiche 50-000, 83/02/25, 8303170532.

8303080425 Requests relief from certain inservice insp requirements for snubbers Justification for relief requests encl.
TRAMM, T R. Commonwealth Edison Co 83/03/01 DENTON, H R. Office of Nuclear Reactor Regulation, Director 10pp 17454 055 24X Fiche 50-000, 83/03/01, 8303080425.

8303080305 Notifies of util intent to utilize ASME Code Case N-340 providing for alternate rules for exam of weld edge preparation by ultrasonic exam of completed weld NRC acceptability requested ASME Code Case N-340 encl.
TRAMM, T R. Commonwealth Edison Co 83/03/02 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 17449 260 24X Fiche 50-000, 83/03/02, 8303080305.

8303070036 Forwards responses to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies," Bunker-Ramo electrical penetrations installed in LaSalle Unit 2, Byron Unit 2 & Braidwood Unit 2.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/03. KEPPLER, J. G. Region 3, Office of Director. 13pp. 17435:290. 24X Fiche: 50-000, 83/03/03, 8303070036.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17411:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303210293 Ack receipt of 830224 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04.
SPESSARD, R. L. Region 3, Office of Director. 83/03/16. REED, C. Commonwealth Edison Co. 1p. 17632:046. 24X Fiche: 50-454, 83/03/16, 8303210293.

8303220277 Forwards applicant 830224 ltr inadvertently omitted from NRC 830316 ltr to applicant.
MAXSON, J. K. Region 3, Office of Director. 83/03/16. Document Management Branch. 1p. 17656:189. 24X Fiche: 50-454, 83/03/16, 8303220277.

--8303220293 Submits revised schedule for completion of review of cable pulling tension per IE Insp Repts 50-454/82-05 & 50-455/82-06. Addl analysis to assure that recorded tensions acceptable should be completed by 830701.
STIEDE, W. L. Commonwealth Edison Co. 83/02/24. KEPPLER, J. G. Region 3, Office of Director. 1p. 17656:190. 24X Fiche: 50-454, 83/03/16, 8303220277.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

8303280289 Ack receipt of 830223 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04. Visual weld exam classification used only for surface conditions not affecting integrity of weld.
SPESSARD, R. L. Region 3, Office of Director. 83/03/22. REED, C. Commonwealth Edison Co. 1p. 17706:077. 24X Fiche: 50-454, 83/03/22, 8303280289.

--8303280301 Responds to NRC 820624 ltr re violations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04. Corrective actions: program assuring certification updated requirements for inspector contractor procedures established.
STIEDE, W. L. Commonwealth Edison Co. 83/02/23. KEPPLER, J. G. Region 3, Office of Director. 33pp. 17706:078. 24X Fiche: 50-454, 83/03/22, 8303280289.

8303300459 Responds to IE Insp Rept 50-454/83-03 open items re RCS leak detection sys capability. Combination of vol control tank level, charging & letdown flow provide real-time indication of onset of RCS leakage. FSAR Section 5.2.5 to be revised.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/23. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 17731:150. 24X Fiche: 50-000, 83/03/23, 8303300459.

8303310211 Forwards addl info in response to IE Bulletin 81-03 re methods to control Corbicula. "Environ Studies of Braidwood Cooling Pond, 1982," encl.
SWARTZ, E. D. Commonwealth Edison Co. 83/03/28. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 17pp. 17755:095. 24X Fiche: 50-000, 83/03/28, 8303310211.

## S. Reportable occurrences, LERs & related correspondence

8303150620 Board Notification 82-26 forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys. Info may affect conclusions re probability of/corrective measures for ATWS.
EISENHUT, D. G. Division of Licensing. 83/03/03. PALLADINO, N., ROBERTS, T. M., ASSELSTEIN, J. K. Commissioners. 24pp. 17594:097. 24X Fiche: 50-000, 83/03/03, 8303150620.

## T. Hearing transcripts on non-antitrust matters

8303010297 Forwards GL Wegner, G Staley & R Codell testimony on listed contentions.
GOLDBERG, S. C. Hearing Branch 2. 83/02/25. PLEASANT, E. Docketing & Services Branch. 1p. 17344:112. 24X Fiche: 50-454, 83/02/25, 8303010297.

--8303010403 Testimony of GL Wenger on Rockford League of Women Voters Contentions 29 & 108 & Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 3 re offsite emergency planning.
WENGER, G. L. Federal Emergency Management Agency. 83/02/25. 16pp. 17344:113. 24X Fiche: 50-454, 83/02/25, 8303010297.

--8303010309 Testimony of R Codell & G Staley on Rockford League of Women Voters Contentions 39 & 109 re liquid pathways.
CODELL, R., STALEY, G. Environmental & Hydrologic Engineering Branch. 83/02/25. 1p. 17344:129. 24X Fiche: 50-454, 83/02/25, 8303010297.

8303010306 Forwards testimony of WD Fletcher, MR Patel, DD Malinowski, MJ Wootten, L Conway, TF Timmons, JC Blomgren & N Paul.
GALLO, J. Isham, Lincoln & Beale. GALLO, J. Commonwealth Edison Co. 83/02/25. SMITH, I. W., COLE, R. F., CALLIHAN, A. D. Atomic Safety and Licensing Board Panel. 1p. 17345:224. 24X Fiche: 50-454, 83/02/25, 8303010306.

--8303010312 Testimony of WD Fletcher re steam generator tube integrity.
FLETCHER, W. D. Commonwealth Edison Co. FLETCHER, W. D. Westinghouse Electric Corp. 83/02/25. 21pp. 17345:225. 24X Fiche: 50-454, 83/02/25, 8303010306.

--8303010317 Testimony of MR Patel re steam generator tube integrity (tube plugging criteria).
PATEL, M. R. Commonwealth Edison Co. PATEL, M. R. Westinghouse Electric Corp. 83/02/25. 17pp. 17345:246. 24X Fiche: 50-454, 83/02/25, 8303010306.

--8303010320 Testimony of DD Malinowski re steam generator tube integrity (insp & eddy current testing).
MALINOWSKI, D. D. Commonwealth Edison Co. MALINOWSKI, D. D. Westinghouse Electric Corp. 83/02/25. 24pp. 17345:263. 24X Fiche: 50-454, 83/02/25, 8303010306.

--8303010324 Testimony of MJ Wootten re steam generator tube integrity (water chemistry).
WOOTTEN, M. J. Commonwealth Edison Co. WOOTTEN, M. J. Westinghouse Electric Corp. 83/02/25. 20pp. 17345:287. 24X Fiche: 50-454, 83/02/25, 8303010306.

--8303010331 Testimony of L Conway re steam generator tube integrity (steam generator design).
CONWAY, L. Commonwealth Edison Co. CONWAY, L. Westinghouse Electric Corp. 83/02/25. 23pp. 17345:307. 24X Fiche: 50-454, 83/02/25, 8303010306.

--8303010337 Testimony of TF Timmons re steam generator tube integrity (flow-induced vibration phenomenon).
TIMMONS, T. F. Commonwealth Edison Co. TIMMONS, T. F. Westinghouse Electric Corp. 83/02/25. 31pp. 17345:330. 24X Fiche: 50-454, 83/02/25, 8303010306.

--8303010340 Testimony of JC Blomgren re steam generator tube integrity (water chemistry, eddy current testing, loose parts control program & Comm Ed comitment re flow-induced vibration phenomenon & tube plugging criterion).
BLOMGREN, J. C. Commonwealth Edison Co. 83/02/25. 26pp. 17345:361. 24X Fiche: 50-454, 83/02/25, 8303010306.

--8303010345 Testimony of N Paul re steam generator tube integrity (preservice insp).
PAUL, N. Commonwealth Edison Co. PAUL, N. Ebasco Services, Inc. (subs. of Enserch Corp.). 83/02/25. 12pp. 17346:026. 24X Fiche: 50-454, 83/02/25, 8303010306.

8303030357 Forwards MJ Hitchler testimony re quantitative assessment of steam generator tube integrity, per Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance Contention 9c & Rockford League of Women Voters Contention 22.
GALLO, J. Isham, Lincoln & Beale. GALLO, J. Commonwealth Edison Co. 83/02/28. SMITH, I. W., COLE, R. F., CALLIHAN, A. D. Atomic Safety and Licensing Board Panel. 1p. 17410:275. 24X Fiche: 50-454, 83/02/28, 8303030357.

--8303030368 Testimony of MJ Hitchler re quantitative assessment of steam generator tube integrity. Steam generator tube degradation under normal operating & accident conditions is not safety concern.
HITCHLER, M. J. Commonwealth Edison Co. 83/02/28. 18pp. 17410:276. 24X Fiche: 50-454, 83/02/28, 8303030357.

8303070034 Forwards testimony of MA Smith, DW Gallagher & P Stomfay-Stitz re QA/QC Contention 1A. W/o Smith testimony. Certificate of Svc encl.
WHICHER, J. M. Businessmen for the Public Interest. WHICHER, J. M. DeKalb Area Alliance for Responsible Energy. WHICHER, J. M. Sinnissippi Alliance for the Environment (SAFE). 83/03/01.
SMITH, I. W.; COLE, R. F.; CALLAHAN, A. D. Atomic Safety and Licensing Board Panel. 4pp. 17434.001. 24X Fiche. 50-454, 83/03/01, 8303070034.

--8303070049 Testimony of DW Gallagher re use of concrete in plant. Concrete batch plant sys incapable of mixing competent concrete. Supervision & insp of placement of concrete inadequate.
GALLAGHER, D. W. Sinnissippi Alliance for the Environment (SAFE).
GALLAGHER, D. W. DeKalb Area Alliance for Responsible Energy.
GALLAGHER, D. W. League of Women Voters of Rockford, IL. 82/09/06. 39pp. 17434.005. 24X Fiche. 50-454, 83/03/01, 8303070034.

--8303070054 Testimony of P Stomfay-Stitz re work while in Blount Brothers Corp employ. QA/QC matls controller training & supervision inadequate. Special insp of tendons inadequately performed &/or documented.
STOMFAY-STITZ. Sinnissippi Alliance for the Environment (SAFE).
STOMFAY-STITZ. DeKalb Area Alliance for Responsible Energy.
STOMFAY-STITZ. League of Women Voters of Rockford, IL. 82/09/30. 160pp. 17434.045. 24X Fiche. 50-454, 83/03/01, 8303070034.

8303070170 Transcript of 830301 hearing in Rockford, IL. Pp. 337-417.
* Atomic Safety and Licensing Board Panel. 83/03/01. 81pp. 17430.147. 24X Fiche. 50-454, 83/03/01, 8303070170.

8303080058 Testimony of D Pope in response to D Gallagher allegations challenging QA program adequacy. Related correspondence.
POPE, D. Commonwealth Edison Co. 83/03/01. 58pp. 17436.285. 24X Fiche. 50-454, 83/03/01, 8303080058.

8303080065 Testimony of R Barnhart in response to P Stomfay-Stitz allegations in support of DeKalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 1A re QA adequacy. Related correspondence.
BARNHART, R. Commonwealth Edison Co. 83/03/01. 8pp. 17457.231. 24X Fiche. 50-454, 83/03/01, 8303080065.

8303080069 Testimony of ML Somsag re M Smith allegations on Contention 1A concerning QA program. Related correspondence.
SOMSAG, M. L. Commonwealth Edison Co. 83/03/01. 16lpp. 17447.001. 24X Fiche. 50-454, 83/03/01, 8303080069.

8303080074 Testimony of MA Stanish re DeKalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 1 on ability & willingness of util to assure safe operation of facility. Related correspondence.
STANISH, M. A. Commonwealth Edison Co. 83/03/01. 77pp. 17456.278. 24X Fiche. 50-454, 83/03/01, 8303080074.

8303080080 Testimony of LD Del George re DeKalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 1 on ability & willingness of util to assure safe operation of facility. Related correspondence.
DELGEORGE, L. D. Commonwealth Edison Co. 83/03/01. 39pp. 17457.126. 24X Fiche. 50-454, 83/03/01, 8303080080.

8303080094 Testimony of RE Guerio re DeKalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 1 on ability & willingness of util to assure safe operation of facility. Related correspondence.
GUERIO, R. E. Commonwealth Edison Co. 83/03/01. 2lpp. 17457.195. 24X Fiche. 50-454, 83/03/01, 8303080094.

8303080098 Testimony of L Holish re consolidated Contentions 39 & 109 on assumptions used in determining time radioactive contaminants released to groundwater would take to travel to nearest well. Related correspondence.
HOLISH, L. Commonwealth Edison Co. HOLISH, L. Sargent & Lundy, Inc. 83/03/01. 15pp. 17456.263. 24X Fiche. 50-454, 83/03/01, 8303080098.

8303080104 Testimony of GC Klopp re consolidated Contentions 39 & 109 on likelihood of core melt leading to significant releases of radioactive contaminants to groundwater. Related correspondence.
KLOPP, G. C. Commonwealth Edison Co. 83/03/01. 13pp. 17458.175. 24X Fiche. 50-454, 83/03/01, 8303080104.

8303080139 Transcript of 830301 limited appearance session in Rockford, IL. Pp. 417.1-417.125.
* Atomic Safety and Licensing Board Panel. 83/03/01. 127pp. 17436.099. 24X Fiche. 50-454, 83/03/01, 8303080139.

8303080186 Testimony of EE Jones re DeKalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 3 & Rockford League of Women Voters Contentions 19 & 108. Related correspondence.
JONES, E. E. Commonwealth Edison Co. JONES, E. E. Illinois, State of. 83/03/01. 424pp. 17440.001. 24X Fiche. 50-454, 83/03/01, 8303080186.

8303080200 Testimony of JC Golden re DeKalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 3 & Rockford League of Women Voters Contentions 19 & 103. Related correspondence.
GOLDEN, J. C. Commonwealth Edison Co. 83/03/01. 303pp. 17446.036. 24X Fiche. 50-454, 83/03/01, 8303080200.

8303080204 Testimony of DD Ed re role of IL Dept of Nuclear Safety in site emergency planning. Related correspondence.
ED, D. D. Commonwealth Edison Co. ED, D. D. Illinois, State of. 83/03/01. 41pp. 17457.023. 24X Fiche. 50-454, 83/03/01, 8303080204.

8303080216 Testimony of GP Lahti re radiological impacts associated w/assumed releases to groundwater of radioactive contaminants. Related correspondence.
LAHTI, G. P. Commonwealth Edison Co. LAHTI, G. P. Sargent & Lundy, Inc. 83/03/01. 8pp. 17457.082. 24X Fiche. 50-454, 83/03/01, 8303080216.

8303080262 Testimony of J Mihovilovich re Stomfay-Stitz allegations concerning adequacy of site QA. Related correspondence.
MIHOVILOVICH, J. Commonwealth Edison Co. 83/03/01. 289pp. 17441.065. 24X Fiche. 50-454, 83/03/01, 8303080262.

8303080481 Testimony of WJ Shewski re Contention 1 on QA program. Related correspondence encl.
SHEWSKI, W. J. Commonwealth Edison Co. 83/03/01. 44pp. 17453.023. 24X Fiche. 50-454, 83/03/01, 8303080481.

8303080482 Testimony of C Reed on Contention 1 re util inability or unwillingness to operate facility within NRC regulations. Related correspondence.
REED, C. Commonwealth Edison Co. 83/03/01. 11pp. 17452.337. 24X Fiche. 50-454, 83/03/01, 8303080482.

8303090273 Public appearance statements received by ASLB on 830301 in Rockford, IL.
QUIGG, C. Pollution & Environmental Problems, Inc. SKALA, J. J. SKALA, S. Y. Affiliation Unknown. 83/03/01. 37pp. 17492.158. 24X Fiche. 50-454, 83/03/01, 8303090273.

8303080397 Transcript of 830302 hearing in Rockford, IL. Pp. 418-696. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 83/03/02. 317pp. 17451.001. 24X Fiche. 50-454, 83/03/02, 8303080397.

8303080277 Transcript of 830303 hearing in Rockford, IL. Pp. 697-934. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 83/03/03. 341pp. 17442.001. 24X Fiche. 50-454, 83/03/03, 8303080277.

8303080143 Transcript of 830304 hearing in Rockford, IL. Pp. 935-1,041. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 83/03/04. 116pp. 17458.356. 24X Fiche. 50-454, 83/03/04, 8303080143.

8303080250 Testimony of DL Smith re site emergency planning. State of IL plan for radiological accidents encl. Related correspondence.
SMITH, D. L. Commonwealth Edison Co. SMITH, D. L. Illinois, State of. 83/03/07. 619pp. 17448.001. 24X Fiche. 50-454, 83/03/07, 8303080250.

830.090142 Testimony of DW Gallagher re incompetent mixing of concrete at concrete batch plant.
GALLAGHER, D. W. DeKalb Area Alliance for Responsible Energy.
GALLAGHER, D. W. Sinnissippi Alliance for the Environment (SAFE).
GALLAGHER, D. W. League of Women Voters of Rockford, IL. 83/03/07. 41pp. 17470.311. 24X Fiche. 50-454, 83/03/07, 8303090142.

8303090294 Memorandum forwarding written public appearance statements received by ASLB on 830301 in Rockford, IL. W/o encl.
MORAN, D. M. Atomic Safety and Licensing Board Panel. 83/03/07. 1p. 17473.362. 24X Fiche. 50-454, 83/03/07, 8303090294.

8303110216 Transcript of 830307 hearing in Rockford, IL. Pp. 1,042-1,140.
* Atomic Safety and Licensing Board Panel. 83/03/07. 101pp. 17519.192. 24X Fiche. 50-454, 83/03/07, 8303110216.

8303140037 Transcript of 830308 hearing in Rockford, IL. Pp. 1,141-1,371. Supporting documentation encl.
* Atomic Safety and Licensing Board Panel. 83/03/08. 289pp. 17528.335. 24X Fiche. 50-454, 83/03/08, 8303140037.

8303150173 Transcript of 830309 hearing in Rockford, IL Pp 1,372-1,569
Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/03/09 401pp
17549:056 24x Fiche 50-454,83/03/09,8303150173

8303150201 Transcript of 830310 hearing in Rockford, IL Pp 1,570-1,825
Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/03/10 316pp
17553:074 24x Fiche 50-454,83/03/10,8303150201

8303150156 Transcript of 830311 hearing in Rockford, IL Pp 1,826-1,923
Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/03/11 202pp
17556:124 24x Fiche 50-454,83/03/11,8303150156

8303230041 Transcript of 830315 hearing in Rockford, IL Pp 1,924-2,140
Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/03/15 296pp
17664:090 24x Fiche 50-454,83/03/15,8303230041

8303220195 Forwards Pp 12-17, missing from P Stomfay-Stitz prefiled testimony
WHICHER,J M Businessmen for the Public Interest 83/03/16
SMITH,I W, CALLIHAN,A D, COLE,R F Atomic Safety and Licensing Board Panel 2pp 17657:124 24X Fiche 50-454,83/03/16,8303220195

--8303220198 Missing Pp 12-17 from P Stomfay-Stitz prefiled testimony
STOMFAY-STITZ League of Women Voters of Rockford, IL
STOMFAY-STITZ DeKalb Area Alliance for Responsible Energy
STOMFAY-STITZ Sinnissippi Alliance for the Environment (SAFE)
83/03/16 6pp 17657:126 24X Fiche 50-454,83/03/16,8303220195

8303230037 Transcript of 830316 hearing in Rockford, IL Pp 2,141-2,336
* Atomic Safety and Licensing Board Panel 83/03/16 96pp
17663:354 24X Fiche 50-454,83/03/16,8303230037

8303300453 Forwards P 22 of Shewski testimony, inadvertently omitted from prefiled testimony Related correspondence
HERRIN,M G Isham, Lincoln & Beale 83/03/22 SMITH,I W,
COLE,R F, CALLIHAN,A D Atomic Safety and Licensing Board Panel
1p 17731:101 24X Fiche 50-454,83/03/22,8303300453

--8303300457 P 22 of Shewski testimony, inadvertently omitted from prefiled testimony
SHEWSKI Affiliation Unknown 83/03/22 2pp 17731:102 24X
Fiche 50-454,83/03/22,8303300453

8303300409 Forwards Pp 31 & 37 of M Smith prefiled testimony
GREENBERG,J Businessmen for the Public Interest GREENBERG,J
League of Women Voters of Rockford, IL GREENBERG,J Sinnissippi
Alliance for the Environment (SAFE) 83/03/23 SMITH,I W,
COLE,R F, CALLIHAN,A D Atomic Safety and Licensing Board Panel
2pp 17731:093 24X Fiche 50-454,83/03/23,8303300409

--8303300431 Pp 31 & 37 to M Smith prefiled testimony
SMITH,M Sinnissippi Alliance for the Environment (SAFE)
SMITH,M DeKalb Area Alliance for Responsible Energy SMITH,M
League of Women Voters of Rockford, IL 83/03/23 2pp
17731:095 24X Fiche 50-454,83/03/23,8303300409

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl
EISENHUT,D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000,83/02/24,8302250505

8303040631 Forwards listing of projected operator licensing exam dates including type of exam & probable number of candidates, in response to 830111 Generic Ltr 83-01
SHARTZ,E D Commonwealth Edison Co 83/03/01 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 17367:209 24X
Fiche 50-000,83/03/01,8303040631

DOCKET STN-50-456 BRAIDWOOD STATION, UNIT 1

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT,D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 10pp 17492:033 24X
Fiche 50-000,83/02/16,8302170082

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT,D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700:303 24X
Fiche 50-000,83/03/02,8303020321

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys
KEPPLER,J G Region 3, Office of Director 83/03/03
Commonwealth Edison Co 2pp 17492:014 24X Fiche 50-000,83/03/03,8303100364

8303110246 Forwards Rev 23 to CE-1-A, "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments
SHARTZ,E D Commonwealth Edison Co 83/03/04 HAASS,W P Quality Assurance Branch 1p 17515:357 24X Fiche 50-000,83/03/04,8303110246

--8303110279 Rev 23 to "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments
SHEWSKI,W J Commonwealth Edison Co CE-1-A R23 83/03/07 5pp
17515:358 24X Fiche 50-000,83/03/04,8303110246

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12) Svc list encl
EISENHUT,D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 51pp 17660:176 24X
Fiche 50-000,83/03/07,8303040005

8303150336 Forwards responses to Questions 10.60,10.62,361.1-361.5, 362.1,362.10,371.10,371.19 & 372.23 re circulating water sys & excavation mapping, per 830114 & 0201 requests for addl info concerning FSAR
SHARTZ,E D Commonwealth Edison Co 83/03/08 DENTON,H R Office of Nuclear Reactor Regulation, Director 64pp 17563:044 24X
Fiche 50-456,83/03/08,8303150336

8303290703 Requests addl info needed to complete evaluation of environ qualification program Questions & comments encl Info required by 830415 FSAR should be amended to reflect response
YOUNGBLOOD,B J Licensing Branch 1 83/03/15 FARRAR,D L
Commonwealth Edison Co 6pp 17730:356 24X Fiche 50-000,83/03/15,8303290703

8303220311 Responds to NRC 830114 request for addl info re FSAR Encl response on population distribution will be included in amend Schedule for submittal of remaining open items currently being discussed w/JA Stevens
SHARTZ,E D Commonwealth Edison Co 83/03/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 66pp 17656:036 24X
Fiche 50-456,83/03/16,8303220311

8303290266 Forwards response to 830114 request for addl FSAR info. Questions 430.56,362.11 & 317.17 FSAR will be amended to include encl info
SHARTZ,E D Commonwealth Edison Co 83/03/23 DENTON,H R Office of Nuclear Reactor Regulation, Director 7pp 17715:106 24X
Fiche 50-456,83/03/23,8303290266

8303290526 Provides schedule for resolution of TMI Action Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps," in response to Generic Ltrs 83-10c & 83-10d Info will be provided by 830423 based on Westinghouse Owners Group input
SHARTZ,E D Commonwealth Edison Co 83/03/24 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 17724:161 24X
Fiche 50-000,83/03/24,8303290526

C. Utility Environmental Report (ER), amends & correspondence

8303100323 Forwards Amend 1 to environ rept - OL stage
SHARTZ,E D Commonwealth Edison Co 83/03/03 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 17490:007 24X
Fiche 50-456,83/03/03,8303100323

--8303100328 Amend 1 to environ rept - OL stage.
* Commonwealth Edison Co 83/02/28 227pp 17490:011 24X
Fiche 50-456,83/03/03,8303100323

F. Security, medical, emergency & fire protection plans

8303170434 Forwards IE Insp Repts 50-456/82-05 & 50-457/82-05 on 830419-0720 & 0908-10 W/o encl separate ltr addressing noncompliance items.
KEPPLER, J G Region 3, Office of Director 83/02/02 O'CONNOR, J J Commonwealth Edison Co 2pp 17609 158 24X Fiche 50-456, 83/02/02, 8303170434

--8303170444 IE Insp Repts 50-456/82-05 & 50-457/82-05 on 820419-0720 & 0908-10 Noncompliance noted failure to implement QA program for erection of mechanical safety-related equipment, to issue const deficiency rept & to ensure matl/equipment protection.
MCGREGOR, L G , KEY, W J Region 3, Office of Director HAYES, D W Division of Project & Resident Programs 83/02/01 38pp 17609 160 24X Fiche 50-456, 83/02/02, 8303170434

8303110242 Submits data tape attributes containing 1974-76 meterological data for facility. Description of tape format encl.
WHITE, J K Commonwealth Edison Co 83/03/03 HAWKHURST, J Effluent Treatment Systems Branch 2pp 17520 069 24X Fiche 50-456, 83/03/03, 8303110242

8303100313 Forwards Amend 1 to 820816 fire protection rept Amend contains voluntary changes & items revised per NRC questions.
SCHROEDER, C W Commonwealth Edison Co 83/03/04 Division of Licensing 2pp 17491 214 24X Fiche 50-000, 83/03/04, 8303100313

--8303100318 Amend 1 to fire protection rept.
* Commonwealth Edison Co 83/03/31 28pp 17491 216 24X Fiche 50-454, 83/03/04, 8303100313

8303150583 Forwards resumes for radiation/chemistry supervisor & station health physicist per JA Stevens 830216 request. Qualifications for radiation protection manager per Reg Guide 1.8-1977 will be fulfilled FSAR will be amended.
SWARTZ, E D Commonwealth Edison Co 83/03/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17567 325 24X Fiche 50-456, 83/03/08, 8303150583

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J A Region 3, Office of Director 83/03/22 Commonwealth Edison Co 2pp 17690 316 24X Fiche 50-000, 83/03/22, 8303240440

8303300532 Releases public version of request for return of listed controlled copies of emergency plan.
FELTON, J M Division of Rules and Records 83/03/28 Document Management Branch 1p 17763 178 24X Fiche 50-000, 83/03/28, 8303300532

--8303300561 Submits public version of request for return of listed controlled copies of emergency plan.
FLESSNER, R A Commonwealth Edison Co 83/03/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17763 179 24X Fiche 50-000, 83/03/28, 8303300532

H. General correspondence

8303030528 Informs that DL Farrar has replaced LO DelGeorge as Director of Nuclear Licensing for util Rev of current NRC distribution list requested.
FARRAR, D L Commonwealth Edison Co 83/02/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17409 048 24X Fiche 50-000, 83/02/02, 8303030528

I. Financial information

8303070135 Forwards Annual Financial Rept 1982.
BRESEMANN, R W Commonwealth Edison Co 83/02/28 Division of Licensing 1p 17433 001 24X Fiche 50-000, 83/02/28, 8303070135

--8303070151 Annual Financial Rept 1982.
O'CONNOR, J J Commonwealth Edison Co 83/02/03 13pp 17433 002 24X Fiche 50-000, 83/02/28, 8303070135

K. Utility Final Safety Analysis Report (FSAR) & amends

8303220317 Forwards affidavit affirming that Amend 41 to FSAR distributed per Encl 1 of NRC 781020 ltr.
LENTINE, F G Commonwealth Edison Co 83/03/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17656 026 24X Fiche 50-000, 83/03/18, 8303220317

Q. Inspection reports, IE Bulletins & correspondence

8303170434 Forwards IE Insp Repts 50-456/82-05 & 50-457/82-05 on 830419-0720 & 0908-10 W/o encl separate ltr addressing noncompliance items.
KEPPLER, J G Region 3, Office of Director 83/02/02 O'CONNOR, J J Commonwealth Edison Co 2pp 17609 158 24X Fiche 50-456, 83/02/02, 8303170434

--8303170444 IE Insp Repts 50-456/82-05 & 50-457/82-05 on 820419-0720 & 0908-10 Noncompliance noted failure to implement QA program for erection of mechanical safety-related equipment, to issue const deficiency rept & to ensure matl/equipment protection.
MCGREGOR, L G , KEY, W J Region 3, Office of Director HAYES, D W Division of Project & Resident Programs 83/02/01 38pp 17609 160 24X Fiche 50-456, 83/02/02, 8303170434

8303030626 Forwards IE Insp Repts 50-456/82-08 & 50-457/82-08 on 820910-1231 & notice of violation.
NORELIUS, C E Division of Project & Resident Programs 83/02/10
REED, C Commonwealth Edison Co 2pp 17409 276 24X Fiche 50-456, 83/02/10, 8303030626

--8303030632 Notice of violation from insp on 820910-1231.
NORELIUS, C E Division of Project & Resident Programs 83/02/10 4pp 17409 278 24X Fiche 50-456, 83/02/10, 8303030626

--8303030641 IE Insp Repts 50-456/82-08 & 50-457/82-08 on 820910-1231 Noncompliance noted failure to protect safety-related equipment, properly implement engineering change notice & provide proper changes to sys drawings.
MCGREGOR, L G Region 3, Office of Director HAYES, D W Division of Project & Resident Programs 83/02/07 10pp 17409 282 24X Fiche 50-456, 83/02/10, 8303030626

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 111pp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367

8303030685 Ack receipt of 830218 ltr requesting 30-day extension to reply to notice of violation & proposed civil penalties. Request granted.
NORELIUS, C E Division of Project & Resident Programs 83/02/25
REED, C Commonwealth Edison Co 1p 17411 019 24X Fiche 50-456, 83/02/25, 8303030685

--8303030691 Requests 30-day extension until 830404 to respond to notice of violation contained in IE Insp Repts 50-456/82-05 & 50-457/82-05.
REED, C Commonwealth Edison Co 83/02/18 KEPPLER, J G Region 3, Office of Director 1p 17411 020 24X Fiche 50-456, 83/02/25, 8303030685

8303170532 Forwards IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al, on 830126 No noncompliance noted.
DAVIS, A B Region 3, Office of Director 83/02/25 REED, C Commonwealth Edison Co 2pp 17610 143 24X Fiche 50-000, 83/02/25, 8303170532

--8303170557 IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al, on 830126 No noncompliance noted. Major areas discussed: proposed guidelines util personnel should use for providing info to Region III inspectors.
GULDEMOND, W G Division of Project & Resident Programs 83/02/15 4pp 17610 145 24X Fiche 50-000, 83/02/25, 8303170532

8303080425 Requests relief from certain inservice insp requirements for snubbers. Justification for relief requests encl.
TRAMM, T R Commonwealth Edison Co 83/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 17454 055 24X Fiche 50-000, 83/03/01, 8303080425

8303080305 Notifies of util intent to utilize ASME Code Case N-340 providing for alternate rules for exam of weld edge preparation by ultrasonic exam of completed weld. NRC acceptability requested. ASME Code Case N-340 encl.
TRAMM, T R Commonwealth Edison Co 83/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17449 260 24X Fiche 50-000, 83/03/02, 8303080305

8303070036 Forwards responses to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Bunker-Ramo electrical penetrations installed in LaSalle Unit 2, Byron Unit 2 & Braidwood Unit 2.
SWARTZ, E D Commonwealth Edison Co 83/03/03 KEPPLER, J G Region 3, Office of Director 13pp 17435 290 24X Fiche 50-000, 83/03/03, 8303070036

8303140249 Ack receipt of 830114 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-456/82-06. Supplemental response re Items 1.a 3.3.3 a.3.d & 4.a on cable tray locations requested within 20 days.
BPESSARD,R.L. Division of Engineering 03/03/08 REED,C. Commonwealth Edison Co. 3pp. 17538:348 24X Fiche 50-456,83/03/08, 8303140249

--8303140261 Responds to NRC 821210 ltr re violations noted in IE Insp Rept 50-456/82-06 Corrective actions tray Section 11335B C1E or 11335F P1B to be relocated to maintain required 1-inch separation Damaged cable reel removed & rereeled.
DELGEORGE,L.O. Commonwealth Edison Co. 83/01/14 KEPPLER,J.G. Region 3, Office of Director 10pp. 17538:351 24X
Fiche 50-456,83/03/08,8303140249

8303140456 Ack receipt of 830222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/82-07 & 50-457/82-07.
NORELIUS,C.E. Division of Project & Resident Programs 83/03/09 REED,C. Commonwealth Edison Co. 1p. 17541:180 24X
Fiche 50-456,83/03/09,8303140456

--8303140467 Responds to NRC 830119 ltr re violations noted in IE Insp Repts 50-456/82-07 & 50-457/82-07 Corrective actions warehouseman instructed to read thermometers on periodic basis & record temp.
FARRAR,D.L. Commonwealth Edison Co. 83/02/22 KEPPLER,J.G. Region 3, Office of Director 7pp. 17541:181 24X
Fiche 50-456,83/03/09,8303140456

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp. 17611:070 24X Fiche 50-000,83/03/11,8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche 50-000,83/03/18,8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp. 17774:352 24X Fiche 50-000,83/03/21,8212060387

8303300459 Responds to IE Insp Rept 50-454/83-03 open items re RCS leak detection sys capability. Combination of vol control tank level, charging & letdown flow provide real-time indication of onset of RCS leakage FSAR Section 5.2.5 to be revised.
SWARTZ,E.D. Commonwealth Edison Co. 83/03/23 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 4pp. 17731:150 24X
Fiche 50-000,83/03/23,8303300459

8303310211 Forwards addl info in response to IE Bulletin 81-03 re methods to control Corbicula. "Environ Studies of Braidwood Cooling Pond, 1982," encl.
SWARTZ,E.D. Commonwealth Edison Co. 83/03/28 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 17pp. 17755:095 24X
Fiche 50-000,83/03/28,8303310211

8303310230 Draft Vol 1 to "Environ Studies of Braidwood Cooling Pond, 1982."
LARIMORE,R.W.; SKELLY,T.M. Illinois, State of 82/12/31 27pp.
17755:112 24X Fiche 50-000,83/03/28,8303310211

5 Reportable occurrences, LERs & related correspondence

8303140594 Interim Deficiency Rept 83-01 re Pullman Sheet Metal installation of HVAC sys components. Initially reported on 830126. Present design tolerances clarified & addl tolerances provided in order to achieve proper installation & insp.
SWARTZ,E.D. Commonwealth Edison Co. 83/03/01 KEPPLER,J.G. Region 3, Office of Director 2pp. 17534:023 24X Fiche 50-456,83/03/01,8303140594

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT,D.G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 10pp. 24X Fiche 50-000,83/02/24,8302250505

8303040631 Forwards listing of projected operator licensing exam dates including type of exam & probable number of candidates in response to 830111 Generic Ltr 83-01.
SWARTZ,E.D. Commonwealth Edison Co. 83/03/01 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 4pp. 17367:209 24X
Fiche 50-000,83/03/01,8303040631

DOCKET STN-50-457 BRAIDWOOD STATION, UNIT 2

A Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT,D.G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp. 17492:033 24X
Fiche 50-000,83/02/16,8302170082

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT,D.G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700:303 24X
Fiche 50-000,83/03/02,8303020321

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER,J.G. Region 3, Office of Director 83/03/03 Commonwealth Edison Co. 2pp. 17492:014 24X Fiche 50-000,83/03/03,8303100364

8303110246 Forwards Rev 23 to CE-1-A, "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments.
SWARTZ,E.D. Commonwealth Edison Co. 83/03/04 HAASS,W.P. Quality Assurance Branch 1p. 17515:357 24X Fiche 50-000,83/03/04,8303110246

--8303110279 Rev 23 to "QA Program," consisting of revised Pages 1-13, 1-14, 1-15 & 1-36 re responsibility assignments.
SHEWSKI,W.J. Commonwealth Edison Co. CE-1-A R23 83/03/07 5pp.
17515:358 24X Fiche 50-000,83/03/04,8303110246

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT,D.G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp. 17660:176 24X
Fiche 50-000,83/03/07,8303040005

8303150336 Forwards responses to Questions 10.60, 10.62, 361.1-361.5, 362.1, 362.10, 371.10, 371.19 & 372.23 re circulating water sys & excavation mapping, per 830114 & 0201 requests for addl info concerning FSAR.
SWARTZ,E.D. Commonwealth Edison Co. 83/03/08 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 64pp. 17563:044 24X
Fiche 50-456,83/03/08,8303150336

8303290703 Requests addl info needed to complete evaluation of environ qualification program. Questions & comments encl. Info required by 830415 FSAR should be amended to reflect response.
YOUNGBLOOD,B.J. Licensing Branch 1 83/03/15 FARRAR,D.L. Commonwealth Edison Co. 6pp. 17730:356 24X Fiche 50-000,83/03/15,8303290703

8303220311 Responds to NRC 830114 request for addl info re FSAR. Encl response on population distribution will be included in amend. Schedule for submittal of remaining open items currently being discussed w/JG Stevens.
SWARTZ,E.D. Commonwealth Edison Co. 83/03/16 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 66pp. 17656:036 24X
Fiche 50-456,83/03/16,8303220311

8303290266 Forwards response to 830114 request for addl FSAR info. Questions 130.56, 362.11 & 317.17 FSAR will be amended to include encl info.
SWARTZ,E.D. Commonwealth Edison Co. 83/03/23 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 7pp. 17716:106 24X
Fiche 50-456,83/03/23,8303290266

8303290526 Provides schedule for resolution of TMI Action Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps," in response to Generic Ltrs 83-10c & 83-10d. Info will be provided by 830423 based on Westinghouse Owners Group input.
SWARTZ,E.D. Commonwealth Edison Co. 83/03/24 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 2pp. 17724:161 24X
Fiche 50-000,83/03/24,8303290526

C Utility Environmental Report (ER), amends & correspondence

8303100323 Forwards Amend 1 to environ rept - OL stage.
SWARTZ, E D Commonwealth Edison Co 83/03/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17490 007 24X Fiche 50-456, 83/03/03, 8303100323

--8303100328 Amend 1 to environ rept - OL stage.
* Commonwealth Edison Co 83/02/28 227pp 17490 011 24X Fiche 50-456, 83/03/03, 8303100323

F Security, medical, emergency & fire protection plans

8303170434 Forwards IE Insp Repts 50-456/82-05 & 50-457/82-05 on 820419-0720 & 0908-10 W/o encl separate ltr addressing noncompliance items.
KEPPLER, J G Region 3, Office of Director 83/02/02 O'CONNOR, J J Commonwealth Edison Co 2pp 17609 158 24X Fiche 50-456, 83/02/02, 8303170434

--8303170444 IE Insp Repts 50-456/82-05 & 50-457/82-05 on 820419-0720 & 0908-10 Noncompliance noted: failure to implement QA program for erection of mechanical safety-related equipment, to issue const deficiency rept & to ensure matl/equipment protection.
MCGREGOR, L G , DANIELSON, D H Region 3, Office of Director 83/02/01 38pp 17609 160 24X Fiche 50-456, 83/02/02, 8303170434

8303110242 Submits data tape attributes containing 1974-76 meterological data for Facility Description of tape format encl.
WHITE, J K Commonwealth Edison Co 83/03/03 HAWXHURST, J Effluent Treatment Systems Branch 2pp 17520 069 24X Fiche 50-456, 83/03/03, 8303110242

8303100313 Forwards Amend 1 to 820816 fire protection rept. Amend contains voluntary changes & items revised per NRC questions.
SCHROEDER, C W Commonwealth Edison Co 83/03/04 Division of Licensing 2pp 17491 214 24X Fiche 50-000, 83/03/04, 8303100313

--8303100318 Amend 1 to fire protection rept.
* Commonwealth Edison Co 83/03/31 28pp 17491 216 24X Fiche 50-454, 83/03/04, 8303100313

8303150583 Forwards resumes for radiation/chemistry supervisor & station health physicist per JA Stevens 830216 reques. Qualifications for radiation protection manager per Reg Guide 1.8-1977 will be fulfilled FSAR will be amended.
SWARTZ, E D Commonwealth Edison Co 83/03/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17567 325 24X Fiche 50-456, 83/03/08, 8303150583

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J A Region 3, Office of Director 83/03/22 Commonwealth Edison Co 2pp 17690 316 24X Fiche 50-000, 83/03/22, 8303240440

8303300532 Releases public version of request for return of listed controlled copies of emergency plan.
FELTON, J M Division of Rules and Records 83/03/28 Document Management Branch 1p 17763 178 24X Fiche 50-000, 83/03/28, 8303300532

--8303300561 Submits public version of request for return of listed controlled copies of emergency plan.
FLEISSNER, R A Commonwealth Edison Co 83/03/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17763 179 24X Fiche 50-000, 83/03/28, 8303300532

H General correspondence

8303030528 Informs that DL Farrar has replaced LD DelGeorge as Director of Nuclear Licensing for util Rev of current NRC distribution list requested.
FARRAR, D L Commonwealth Edison Co 83/02/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17409 048 24X Fiche 50-000, 83/02/02, 8303030528

I Financial information

8303070135 Forwards Annual Financial Rept 1982.
BRESEMANN, R W Commonwealth Edison Co 83/02/28 Division of Licensing 1p 17433 001 24X Fiche 50-000, 83/02/28, 8303070135

--8303070151 Annual Financial Rept 1982.
O'CONNOR, J J Commonwealth Edison Co 83/02/03 13pp 17433 002 24X Fiche 50-000, 83/02/28, 8303070135

K Utility Final Safety Analysis Report (FSAR) & amends

8303220317 Forwards affidavit affirming that Amend 41 to FSAR distributed per Encl 1 of NRC 781000 ltr.
LENTINE, F G Commonwealth Edison Co 83/03/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17656 026 24X Fiche 50-000, 83/03/18, 8303220317

Q Inspection reports, IE Bulletins & correspondence

8303170434 Forwards IE Insp Repts 50-456/82-05 & 50-457/82-05 on 820419-0720 & 0908-10. W/o encl separate ltr addressing noncompliance items.
KEPPLER, J G Region 3, Office of Director 83/02/02 O'CONNOR, J J Commonwealth Edison Co 2pp 17609 158 24X Fiche 50-456, 83/02/02, 8303170434

--8303170444 IE Insp Repts 50-456/82-05 & 50-457/82-05 on 820419-0720 & 0908-10 Noncompliance noted: failure to implement QA program for erection of mechanical safety-related equipment, to issue const deficiency rept & to ensure matl/equipment protection.
MCGREGOR, L G , KEY, W J Region 3, Office of Director HAYES, D W Division of Project & Resident Programs 83/02/01 38pp 17609 160 24X Fiche 50-456, 83/02/02, 8303170434

8303030626 Forwards IE Insp Repts 50-456/82-08 & 50-457/82-08 on 820910-1231 & notice of violation.
NORELIUS, C E Division of Project & Resident Programs 83/02/10
REED, C Commonwealth Edison Co 2pp 17409 276 24X Fiche 50-456, 83/02/10, 8303030626

--8303030632 Notice of violation from insp on 820910-1231.
NORELIUS, C E Division of Project & Resident Programs 83/02/10 4pp 17409 278 24X Fiche 50-456, 83/02/10, 8303030626

--8303030641 IE Insp Repts 50-456/82-08 & 50-457/82-08 on 820910-1231 Noncompliance noted: failure to protect safety-related equipment, properly implement engineering change notice & provide proper changes to sys drawings.
MCGREGOR, L G Region 3, Office of Director HAYES, D W Division of Project & Resident Programs 83/02/07 10pp 17409 282 24X Fiche 50-456, 83/02/10, 8303030626

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 111pp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367

8303030685 Ack receipt of 830218 ltr requesting 30-day extension to reply to notice of violation & proposed civil penalties. Request granted.
NORELIUS, C E Division of Project & Resident Programs 83/02/25
REED, C Commonwealth Edison Co 1p 17411 019 24X Fiche 50-456, 83/02/25, 8303030685

--8303030691 Reques.. 30-day extension until 830404 to respond to notice of violation contained in IE Insp Repts 50-456/82-05 & 50-457/82-05.
REED, C Commonwealth Edison Co 83/02/18 KEPPLER, J G Region 3, Office of Director 1p 17411 020 24X Fiche 50-456, 83/02/25, 8303030685

8303170532 Forwards IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al, on 830126. No noncompliance noted.
DAVIS, A B Region 3, Office of Director 83/02/25 REED, C Commonwealth Edison Co 2pp 17610 143 24X Fiche 50-000, 83/02/25, 8303170532

--8303170557 IE Mgt Meeting Repts 50-010/83-03, 50-237/83-04, 50-249/83-03, et al, on 830126. No noncompliance noted. Major areas discussed proposed guidelines util personnel should use for providing info to Region III inspectors.
GULDEMOND, W G Division of Project & Resident Programs 83/02/15 4pp 17610 145 24X Fiche 50-000, 83/02/25, 8303170532

8303080425 Requests relief from certain inservice insp requirements for snubbers. Justification for relief requests encl.
TRAMM, T R Commonwealth Edison Co 83/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 17454 055 24X Fiche 50-000, 83/03/01, 8303080425

8303080305 Notifies of util intent to utilize ASME Code Case N-340 providing for alternate rules for exam of weld edge preparation by ultrasonic exam of completed weld. NRC acceptability requested. ASME Code Case N-340 encl.
TRAMM, T R Commonwealth Edison Co 83/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17449 260 24X Fiche 50-000, 83/03/02, 8303080305

8303070036 Forwards responses to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." Bunker-Ramo electrical penetrations installed in LaSalle Unit 2, Byron Unit 2 & Braidwood Unit 2.
SWARTZ, E D Commonwealth Edison Co 83/03/03 KEPPLER, J G Region 3, Office of Director 13pp 17435:290 24X Fiche 50-000, 83/03/03, 8303070036

8303140456 Ack receipt of 830222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/82-07 & 50-457/82-07.
NORELIUS, C E Division of Project & Resident Programs 83/03/09
REED, C Commonwealth Edison Co 1p 17541:180 24X
Fiche 50-456, 83/03/09, 8303140456

--8303140467 Responds to NRC 830119 ltr re violations noted in IE Insp Repts 50-456/82-07 & 50-457/82-07. Corrective actions: warehouseman instructed to read thermometers on periodic basis & record temp.
FARRAR, D L Commonwealth Edison Co 83/02/22 KEPPLER, J G Region 3, Office of Director 7pp 17541:181 24X
Fiche 50-456, 83/03/09, 8303140456

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc 117pp 17611:070 24X Fiche 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/16 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000, 83/03/16, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 121pp 17774:352 24X Fiche 50-000, 83/03/21, 8212060387

8303300459 Responds to IE Insp Rept 50-454/83-03 open items re RCS leak detection sys capability. Combination of vol control tank level, charging & letdown flow provide real-time indication of onset of RCS leakage. FSAR Section 5.2.5 to be revised.
SWARTZ, E D Commonwealth Edison Co 83/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 17731:150 24X
Fiche 50-000, 83/03/23, 8303300459

8303310211 Forwards addl info in response to IE Bulletin 81-03 re methods to control Corbicula. "Environ Studies of Braidwood Cooling Pond, 1982," encl.
SWARTZ, E D Commonwealth Edison Co 83/03/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 17pp 17755:095 24X
Fiche 50-000, 83/03/28, 8303310211

--8303310230 Draft Vol 1 to "Environ Studies of Braidwood Cooling Pond, 1982,"
LARIMORE, R W ; SKELLY, T M Illinois, State of 82/12/31 27pp
17755:112 24X Fiche 50-000, 83/03/28, 8303310211

S. Reportable occurrences, LERs & related correspondence

8303140594 Interim Deficiency Rept 83-01 re Pullman Sheet Metal installation of HVAC sys components. Initially reported on 830126. Present design tolerances clarified & addl tolerances provided in order to achieve proper installation & insp.
SWARTZ, E D Commonwealth Edison Co 83/03/01 KEPPLER, J G Region 3, Office of Director 2pp 17534:023 24X Fiche 50-456, 83/03/01, 8303140594

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000, 83/02/24, 8302250505

8303040631 Forwards listing of projected operator licensing exam dates including type of exam & probable number of candidates, in response to 830111 Generic Ltr 83-01.
SWARTZ, E D Commonwealth Edison Co 83/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 17367:209 24X
Fiche 50-000, 83/03/01, 8303040631

DOCKET 50-458 RIVER BEND STATION, UNIT 1

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492:033 24X
Fiche 50-000, 83/02/16, 8302170082

8303090451 Notification of 830330-0401 meetings w/applicant in West Feliciana Parish, LA to discuss status & schedule for completion of const activities. Agenda encl.
WEINKAM, E J Licensing Branch 2 83/02/22 SCHWENCER, A Licensing Branch 2 6pp 17483:173 24X Fiche 50-458, 83/02/22, 8303090451

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700:303 24X
Fiche 50-000, 83/03/02, 8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 51pp 17660:176 24X
Fiche 50-000, 83/03/07, 8303040005

8303150340 Advises of 830405 meeting w/licensees & major contractors at Dallas/Fort Worth, TX to provide info & guidance re 10CFR50 QA & Tech Spec deviations & discuss decentralization policy. Questions should be submitted in writing by 830321.
COLLINS, J T Region 4, Office of Director 83/03/10 Public Service Co of Colorado 12pp 17562:291 24X
Fiche 50-000, 83/03/10, 8303150340

8303150398 Notifies of 830405 public meeting at Dallas/Forth Worth, TX Airport to discuss policy of decentralization, recent changes to 10CFR50 & changes to allow licensee to depart from license conditions in emergency.
COLLINS, J T Region 4, Office of Director 83/03/11 CAHILL, W J Gulf States Utilities Co 3pp 17561:285 24X
Fiche 50-458, 83/03/11, 8303150398

8303290369 Forwards proprietary & nonproprietary versions of "CLASIX-3 Computer Program for Analysis of Reactor Plant Containment Response to Hydrogen Release & Deflagration." Proprietary version withheld (ref 10CFR2.790).
RICHARDSON, J D Hydrogen Control Owners Group, BWR-6 Mark III 83/03/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17726:079 24X Fiche 50-000, 83/03/18, 8303290369.

--8303290378 Requests that "CLASIX-3 Computer Program for Analysis of Reactor Plant Containment Response to Hydrogen Release & Deflagration" be withheld from public disclosure. Affidavit encl.
WIESEMANN, R A Westinghouse Electric Corp 83/01/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 17726:081 24X Fiche 50-000, 83/03/18, 8303290369.

8303310679 Forwards comments on util seismic reflection profile data to assess if any structures or faults exist within region. Response requested.
SCHWENCER, A Licensing Branch 2 83/03/25 CAHILL, W J Gulf States Utilities Co 3pp 17780:296 24X Fiche 50-458, 83/03/25, 8303310679

C. Utility Environmental Report (ER), amends & correspondence

8303030411 Forwards Suppl 4 to environ rept - OL stage & Amend 7 to FSAR (filed in PDR Category K) Affidavit of Svc encl.
CAHILL, W J Gulf States Utilities Co 83/02/28 EISENHUT, D G Division of Licensing 8pp 17416:048 24X Fiche 50-458, 83/02/28, 8303030411

--8303030430 Suppl 4 to environ rept - OL stage
* Gulf States Utilities Co 83/02/28 190pp 17416:056 24X
Fiche 50-458, 83/02/28, 8303030411

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303180539 Forwards geology & seismology sections for draft SER. No known capable faults at site or region around site identified.
SCHWENCER, A. Licensing Branch 2. 83/03/10. CAHILL, W. J. Gulf States Utilities Co. 21pp. 17679 259. 24X Fiche. 50-458. 83/03/10. 8303180539

8303180630 Forwards draft SER radiation protection program sections. Site visit planned to resolve eight open items.
SCHWENCER, A. Licensing Branch 2. 83/03/11. CAHILL, W. J. Gulf States Utilities Co. 17pp. 17626 315. 24X Fiche. 50-458. 83/03/11. 8303180630

F. Security, medical, emergency & fire protection plans

8303140317 Submits guidance re location of emergency notification sys & health physics network in emergency response plan per NUREG-0696.
COLLINS, J. T. Region 4, Office of Director. 83/02/24. CAHILL, W. J. Gulf States Utilities Co. 2pp. 17543 300. 24X Fiche. 50-458. 83/02/24. 8303140317

8303100155 Forwards Rev 3 to training & qualification plan. Rev withheld (ref 10CFR2.790). Affidavit encl.
CAHILL, W. J. Gulf States Utilities Co. 83/03/07. SCHWENCER, A. Licensing Branch 2. 3pp. 17485 239. 24X Fiche. 50-458. 83/03/07. 8303100155

8303140066 Provides info in response to project manager request re emergency operations facility structure completed & located 1.1 miles from Unit 1. Info will be included in future FSAR amend.
BOOKER, J. E. Gulf States Utilities Co. 83/03/07. SCHWENCER, A. Licensing Branch 2. 1p. 17540 072. 24X Fiche. 50-458. 83/03/07. 8303140066

8303290467 Advises of recently developed practice of personnel recruiter attempting to locate personnel familiar w/certain computer. Caution should be taken when answering questions which might pertain to security matters.
COLLINS, J. T. Region 4, Office of Director. 83/03/25. CAHILL, W. J. Gulf States Utilities Co. 2pp. 17722 359. 24X Fiche. 50-458. 83/03/25. 8303290467

G. Adjudicatory correspondence

8303040312 Proposed contentions re financial & technical qualifications, environ qualification, induced seismic activity, prematurity of application, liquid pathway study & generic safety issues. Svc list encl.
FALKENHEINER, D. Louisiana Consumer's League, Inc. WATKINS, L. B. Rothschild, G. E. 82/12/15. Atomic Safety and Licensing Board Panel. 10pp. 17421 355. 24X Fiche. 50-458. 82/12/15. 8303040312

8303220301 Suppl to petition to intervene, listing contentions. Certificate of Svc encl.
LINDSEY, I. D. Louisiana, State of. 83/03/15. Atomic Safety and Licensing Board Panel. 11pp. 17656 110. 24X Fiche. 50-458. 83/03/15. 8303220301

8303300329 Notice of change of address of counsel. Certificate of Svc encl.
FALKENHEINER, D. Falkenheiner, D. IRVING, S. M. Irving, S. M. WATKINS, L. B. Watkins, L. B. 83/03/21. 3pp. 17734 298. 24X Fiche. 50-458. 83/03/21. 8303300329

K. Utility Final Safety Analysis Report (FSAR) & amends

8303030411 Forwards Amend 7 to FSAR.
CAHILL, W. J. Gulf States Utilities Co. 83/02/28. EISENHUT, D. G. Division of Licensing. 8pp. 17416 048. 24X Fiche. 50-458. 83/02/28. 8303030411

--8303030434 Amend 7 to FSAR.
* Gulf States Utilities Co. 83/02/28. 987pp. 17416 246. 24X Fiche. 50-458. 83/02/28. 8303030411

O. Inspection reports, IE Bulletins & correspondence

8303080367 Forwards IE Insp Rept 50-458/81-04 on 810301-0331. No noncompliance noted.
MADSEN, G. L. Reactor Projects Branch. 81/04/13. DRAPER, E. L. Gulf States Utilities Co. 2pp. 17453 340. 24X Fiche. 50-458. 81/04/13. 8303080367.

--8303080374 IE Insp Rept 50-458/81-04 on 810301-0331. No noncompliance noted. Major areas inspected welding & structural steel erection & concrete placement activities.
BEACH, A. B., CROSSMAN, W. A. Project Section 3. 81/04/09. 5pp. 17453 342. 24X Fiche. 50-458. 81/04/13. 8303080367.

8303080085 Forwards IE Investigation Rept 50-458/81-03 on 810218-20 re alleged incorrect addition of water to truckload of concrete & falsification of respective records. No noncompliance noted.
COLLINS, J. T. Region 4, Dallas, Office of the Director (81/03/01). 81/04/30. DRAPER, E. L. Gulf States Utilities Co. 2pp. 17457 179. 24X Fiche. 50-458. 81/04/30. 8303080085

--8303080091 IE Investigation Rept 50-458/81-03 on 810218-20. No noncompliance noted. Major areas investigated allegations re incorrect addition of water to truckload of concrete & falsification of respective records.
DRISKILL, D. D., GAGLIARDO, J. E., CROSSMAN, W. A. Region 4, Dallas, Office of the Director (81/03/01). 81/04/29. 11pp. 17457 181. 24X Fiche. 50-458. 81/04/30. 8303080085

8303010579 Forwards IE Insp Rept 50-458/83-02 on 830110-14. No noncompliance noted.
MADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs. 83/02/11. CAHILL, W. J. Gulf States Utilities Co. 2pp. 17336 019. 24X Fiche. 50-458. 83/02/11. 8303010579.

--8303010587 IE Insp Rept 50-458/83-02 on 830110-14. No noncompliance noted. Major areas inspected review of QA program for safety-related structural concrete & steel supports receipt, storage, installation & identification.
JOHNSON, C. E., BESS, J., CROSSMAN, W. A. Division of Resident, Reactor Project & Engineering Programs. 83/02/09. 10pp. 17336 021. 24X Fiche. 50-458. 83/02/11. 8303010579.

8303010246 Forwards IE Insp Repts 50-458/83-01 & 50-459/83-01 on 821216-830131. No noncompliance noted.
MADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs. 83/02/14. CAHILL, W. J. Gulf States Utilities Co. 2pp. 17335 159. 24X Fiche. 50-458. 83/02/14. 8303010246.

--8303010249 IE Insp Repts 50-458/83-01 & 50-459/83-01 on 821216-830131. No noncompliance noted. Major areas inspected: followup of previous insp findings, licensee identified const deficiency & electrical components & sys installation.
BROWN, R. L., CROSSMAN, W. A. Division of Resident, Reactor Project & Engineering Programs. 83/02/10. 6pp. 17335 161. 24X Fiche. 50-458. 83/02/14. 8303010246.

8303030613 Advises that environ protection/preoperational insp will be performed on 830228-0304.
BAER, R. E. Region 4, Office of Director. 83/02/22. MURRAY, B. Region 4, Office of Director. 1p. 17409 245. 24X Fiche. 50-458. 83/02/22. 8303030613.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521 001. 24X Fiche. 50-000. 83/02/25. 8212060367.

8303280230 Suppls 811002 response to IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes." Final rept to be submitted 830503, subj to GE evaluation completion.
BOOKER, J. E. Gulf States Utilities Co. 83/03/01. COLLINS, J. T. Region 4, Office of Director. 1p. 17708 136. 24X Fiche. 50-458. 83/03/01. 8303280230.

8303280264 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." No Bunker-Ramo electrical penetrations purchased. Affidavit encl.
BOOKER, J. E. Gulf States Utilities Co. 83/03/03. COLLINS, J. T. Region 4, Office of Director. 2pp. 17706 262. 24X Fiche. 50-458. 83/03/03. 8303280264.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611 070. 24X Fiche. 50-000. 83/03/11. 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche. 50-000. 83/03/18. 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 12lpp 17774 352 24X Fiche 50-000, 83/03/21, 8212060387

S Reportable occurrences, LERs & related correspondence

8303080405 Interim deficiency rept re damage to primary shield wall. Initially reported on 810224. Investigation of incident anticipated to be complete by 810615 at which time final rept will be submitted.
DRAPER, E L Gulf States Utilities Co 81/04/24 SEYFRIT, K V
Region 4, Dallas, Office of the Director (81/03/01) 1p 17454 031 24X Fiche 50-458, 81/04/24, 8303080405

8303080420 Final deficiency rept re Manitowac 4600 W crane tipping forward & causing extended boom to strike portion of standby cooling tower basin I under const. Initially reported on 810421. Condition not reportable per 10CFR50.55(e).
DRAPER, E L Gulf States Utilities Co 81/05/26 SEYFRIT, K V
Region 4, Office of Director 1p 17454 054 24X
Fiche 50-458, 81/05/26, 8303080420

8303080362 Final Deficiency Rept DR-53 re BF Shaw rolled plate pipe rejected for incomplete documentation & radiographs. Initially reported on 820524. Deficiency determined not reportaule per 10CFR50.55(e).
BOOKER, J E Gulf States Utilities Co 82/06/18 COLLINS, J T
Region 4, Office of Director 1p 17453 347 24X
Fiche 50-458, 82/06/18, 8303080362

8303080009 Interim Deficiency Rept DR-82 re installation Spec 248.000 which did not include mfg limits on cable sidewall pressure. Initially reported on 821203. Evaluation continuing. Next rept will be submitted by 830421.
BOOKER, J E Gulf States Utilities Co 83/02/23 COLLINS, J T
Region 4, Office of Director 1p 17436 343 24X
Fiche 50-458, 83/02/23, 8303080009

8303110219 Interim Deficiency Rept DR-72 re improper installation, testing & insp of concrete drilled in expansion-type anchors. Initially reported on 820830. Addl info from S&W expected. Final rept will be provided by 830425.
BOOKER, J E Gulf States Utilities Co 83/02/28 COLLINS, J T
Region 4, Office of Director 1p 17518 347 24X
Fiche 50-458, 83/02/28, 8303110219

8303110387 Final Deficiency Rept DR-81 re improper O-ring matl used in control bldg chiller pumps & normal svc water pumps supplied by Gould. Initially reported on 821228. O-ring matl determined functional. Condition not reportable under 10CFR50.55(e).
BOOKER, J E Gulf States Utilities Co 83/03/01 COLLINS, J T
Region 4, Office of Director 1p 17506 241 24X
Fiche 50-458, 83/03/01, 8303110387

8303150264 Final Deficiency Rept DR-79 re failure to follow weld procedures on field weld. Initially reported on 821123. Condition determined not reportable per 10CFR50.55(e).
BOOKER, J E Gulf States Utilities Co 83/03/02 COLLINS, J T
Region 4, Office of Director 1p 17567 260 24X
Fiche 50-458, 83/03/02, 8303150264

8303110255 Interim Deficiency Rept DR-85 re incorrect taper at welds between outside diameter of heavy wall pipe fittings & outside diameter of std wall pipe on svc water piping sys. Initially reported on 821208. Next rept expected by 830516.
BOOKER, J E Gulf States Utilities Co 83/03/03 COLLINS, J T
Region 4, Office of Director 1p 17520 001 24X
Fiche 50-458, 83/03/03, 8303110255

8303150282 Interim Deficiency Rept DR-94 re welded 90 degree elbow furnished by Gulfalloy. Initially reported on 830201. Investigation not completed. Next rept expected by 830408.
BOOKER, J E Gulf States Utilities Co 83/03/03 COLLINS, J T
Region 4, Office of Director 1p 17567 041 24X
Fiche 50-458, 83/03/03, 8303150282

8303150605 Interim Deficiency Rept DR-95 re possible defect in plate & face plate gaskets for hydrogen ignitor Model 6043 assemblies. Initially reported on 830204. Investigation continuing. Next rept will be submitted by 830606.
BOOKER, J E Gulf States Utilities Co 83/03/04 COLLINS, J T
Region 4, Office of Director 1p 17569 028 24X
Fiche 50-458, 83/03/04, 8303150605

8303210466 Interim Deficiency Rept 86 re possible misinterpretation of electrical equipment hold-down weld detail. Initially reported on 821213. Investigation incomplete. Next rept due by 830520.
BOOKER, J E Gulf States Utilities Co 83/03/08 COLLINS, J T
Region 4, Office of Director 1p 17634 159 24X
Fiche 50-458, 83/03/08, 8303210466

8303180018 Interim Deficiency Rept 87 re nonconforming installation of connection between electrical cable tray & support sys. Initially reported on 821217. Some connection bolt holes found enlarged. Next rept expected by 830408.
BOOKER, J E Gulf States Utilities Co 83/03/09 COLLINS, J T
Region 4, Office of Director 1p 17618 099 24X
Fiche 50-458, 83/03/09, 8303180018

8303240468 Interim Deficiency Rept DR-75 re error in Ghosh-Wilson computer program used in reactor bldg hydrodynamic analysis. Corrected analyses resulted in changes in "g" values that do not require hardware mods. Next rept expected by 830930.
BOOKER, J E Gulf States Utilities Co 83/03/15 COLLINS, J T
Region 4, Office of Director 1p 17678 041 24X
Fiche 50-458, 83/03/15, 8303240468

8303240476 Final Deficiency Rept DR-83 re potentially undersized fillet welds attaching support lugs to safety relief valve quenchers. Welds in compliance w/ASME requirements. Design adequate. Condition not reportable per 10CFR50.55(e).
BOOKER, J E Gulf States Utilities Co 83/03/15 COLLINS, J T
Region 4, Office of Director 1p 17678 105 24X
Fiche 50-458, 83/03/15, 8303240476

8303250110 Interim Deficiency Rept DR-89 re potential malfunction of primary knife-type disconnect mfg by RTE Delta Corp. Initially reported on 821222. Transamerica Delaval will provide info. Interim or final rept expected by 830527.
BOOKER, J E Gulf States Utilities Co 83/03/17 COLLINS, J T
Region 4, Office of Director 1p 17693 075 24X
Fiche 50-458, 83/03/17, 8303250110

8303250050 Interim Deficiency Rept DR-96 re linear indications in section of tube steel supplied by Bergen-Paterson. Initially reported on 830217. Investigation incomplete. Interim or final status rept will be submitted by 830520.
BOOKER, J E Gulf States Utilities Co 83/03/18 COLLINS, J T
Region 4, Office of Director 1p 17693 122 24X
Fiche 50-458, 83/03/18, 8303250050

8303280141 Interim Deficiency Rept DR-97 re clearance between armature tail piece & molded posts of HMA auxiliary relays mfg by GE in 1974. Initially reported on 830217. Investigation continuing. Interim or final rept due by 830624.
BOOKER, J E Gulf States Utilities Co 83/03/18 COLLINS, J T
Region 4, Office of Director 1p 17705 321 24X
Fiche 50-458, 83/03/18, 8303280141

8303280256 Interim Deficiency Rept DR 98 re potential failure of SBM control switches mfg by GE. Initially reported on 830217. Investigation incomplete. Interim or final rept will be submitted by 830624.
BOOKER, J E Gulf States Utilities Co 83/03/18 COLLINS, J T
Region 4, Office of Director 1p 17706 278 24X
Fiche 50-458, 83/03/18, 8303280256

8303280229 Interim Deficiency Rept DR-73 re improperly installed spring nuts in GE supplied Power Generation Control Complex termination cabinets. Initially reported on 820902. Vendor rept pending. Next rept will be provided by 830524.
BOOKER, J E Gulf States Utilities Co 83/03/21 COLLINS, J T
Region 4, Office of Director 1p 17708 170 24X
Fiche 50-458, 83/03/21, 8303280229

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 10pp 24X Fiche 50-000, 83/02/24, 8302250505

8303090342 Submits projected requests for site visits to conduct operator licensing or instructor certification exams through Dec 1985, in response to 830111 Generic Ltr 83-01.
BOOKER, J E Gulf States Utilities Co 83/03/02 EISENHUT, D G
Division of Licensing 1p 17471 129 24X Fiche 50-458, 83/03/02, 8303090342

DOCKET 50-459 RIVER BEND STATION, UNIT 2

A Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24X
Fiche 50-000, 83/02/16, 8302170082

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X
Fiche 50-000, 83/03/02, 8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 5lpp 17660 176 24X
Fiche 50-000, 83/03/07, 8303040005

8303150340 Advises of 830405 meeting w/licensees & major contractors at Dallas/Fort Worth, TX to provide info & guidance re 10CFR50 QA & Tech Spec deviations & discuss decentralization policy. Questions should be submitted in writing by 830321
COLLINS, J T Region 4, Office of Director 83/03/10 Public Service Co of Colorado 12pp 17562 291 24X
Fiche 50-000, 83/03/10, 8303150340

8303150398 Notifies of 830405 public meeting at Dallas/Forth Worth, TX Airport to discuss policy of decentralization, recent changes to 10CFR50 & changes to allow licensee to depart from license conditions in emergency
COLLINS, J T Region 4, Office of Director 83/03/11 CAHILL, W J Gulf States Utilities Co 3pp 17561 285 24X
Fiche 50-458, 83/03/11, 8303150398

8303310679 Forwards comments on util seismic reflection profile data to assess if any structures or faults exist within region Response requested
SCHWENCER, A Licensing Branch 2 83/03/25 CAHILL, W J Gulf States Utilities Co 3pp 17780 296 24X Fiche 50-458, 83/03/25, 8303310679

C. Utility Environmental Report (ER), amends & correspondence

8303030411 Forwards Suppl 4 to environ rept - OL stage & Amend 7 to FSAR (Filed in PDR Category K) Affidavit of Svc encl
CAHILL, W J Gulf States Utilities Co 83/02/28 EISENHUT, D G Division of Licensing 8pp 17416 048 24X Fiche 50-458, 83/02/28, 8303030411

--8303030430 Suppl 4 to environ rept - OL stage
* Gulf States Utilities Co 83/02/28 190pp 17416 056 24X
Fiche 50-458, 83/02/28, 8303030411

E. NRC Safety Evaluation Report (SER), supplS & correspondence

8303180539 Forwards geology & seismology sections for draft SER No known capable faults at site or region around site identified
SCHWENCER, A Licensing Branch 2 83/03/10 CAHILL, W J Gulf States Utilities Co 21pp 17639 259 24X Fiche 50-458, 83/03/10, 8303180539

F. Security, medical, emergency & fire protection plans

8303140317 Submits guidance re location of emergency notification sys & health physics network in emergency response plan per NUREG-0696
COLLINS, J T Region 4, Office of Director 83/02/24 CAHILL, W J Gulf States Utilities Co 2pp 17543 300 24X
Fiche 50-458, 83/02/24, 8303140317

8303100155 Forwards Rev 3 to training & qualification plan Rev withheld (ref 10CFR2 790) Affidavit encl
CAHILL, W J Gulf States Utilities Co 83/03/07 SCHWENCER, A Licensing Branch 2 3pp 17485 239 24X Fiche 50-458, 83/03/07, 8303100155

8303140066 Provides info in response to project manager request re emergency operations facility Structure completed & located 1.1 miles from Unit 1 Info will be included in future FSAR amend
BOOKER, J E Gulf States Utilities Co 83/03/07 SCHWENCER, A Licensing Branch 2 1p 17540 072 24X Fiche 50-458, 83/03/07, 8303140066

8303290467 Advises of recently developed practice of personnel recruiter attempting to locate personnel familiar w/certain computer Caution should be taken when answering questions which might pertain to security matters
COLLINS, J T Region 4, Office of Director 83/03/25 CAHILL, W J Gulf States Utilities Co 2pp 17722 359 24X
Fiche 50-458, 83/03/25, 8303290467

G. Adjudicatory correspondence

8303040312 Proposed contentions re financial & technical qualifications, environ qualification, induced seismic activity, prematurity of application, liquid pathway study & generic safety issues Svc list encl
FALKENHEINER, D Louisiana Consumer's League, Inc WATKINS, L B Rothschild, G E 82/12/15 Atomic Safety and Licensing Board Panel 10pp 17421 355 24X Fiche 50-458, 82/12/15, 8303040312

8303220301 Suppl to petition to intervene, listing contentions Certificate of Svc encl
LINDSEY, I D Louisiana, State of 83/03/15 Atomic Safety and Licensing Board Panel 11pp 17656 110 24X Fiche 50-458, 83/03/15, 8303220301

8303300329 Notice of change of address of counsel Certificate of Svc encl
FALKENHEINER, D Falkenheiner, D IRVING, S M Irving, S M
WATKINS, L B Watkins, L B 83/03/21 3pp 17734 298 24X
Fiche 50-458, 83/03/21, 8303300329

K. Utility Final Safety Analysis Report (FSAR) & amends

8303030411 Forwards Amend 7 to FSAR
CAHILL, W J Gulf States Utilities Co 83/02/28 EISENHUT, D G Division of Licensing 8pp 17416 048 24X Fiche 50-458, 83/02/28, 8303030411

--8303030434 Amend 7 to FSAR
* Gulf States Utilities Co 83/02/28 987pp 17416 246 24X
Fiche 50-458, 83/02/28, 8303030411

Q. Inspection reports, IE Bulletins & correspondence

8303010246 Forwards IE Insp Repts 50-458/83-01 & 50-459/83-01 on 821216-830131 No noncompliance noted
MADSEN, G L Division of Resident, Reactor Project & Engineering Programs 83/02/14 CAHILL, W J Gulf States Utilities Co 2pp 17335 159 24X Fiche 50-458, 83/02/14, 8303010246

--8303010249 IE Insp Repts 50-458/83-01 & 50-459/83-01 on 821216-830131 No noncompliance noted Major areas inspected followup of previous insp findings, licensee identified const deficiency & electrical components & sys installation
BROWN, R L ; CROSSMAN, W A Division of Resident, Reactor Project & Engineering Programs 83/02/10 6pp 17335 161 24X
Fiche 50-458, 83/02/14, 8303010246

8303030613 Advises that environ protection/preoperational insp will be performed on 830228-0304
BAER, R E Region 4, Office of Director 83/02/22 MURRAY, B Region 4, Office of Director 1p 17409 245 24X
Fiche 50-458, 83/02/22, 8303030613

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 11lpp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367

8303280230 Suppls 811002 response to IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes." Final rept to be submitted 830503, subj to GE evaluation completion
BOOKER, J E Gulf States Utilities Co 83/03/01 COLLINS, J T Region 4, Office of Director 1p 17708 136 24X
Fiche 50-458, 83/03/01, 8303280230

8303280264 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies." No Bunker-Ramo electrical penetrations purchased Affidavit encl
BOOKER, J E Gulf States Utilities Co 83/03/03 COLLINS, J T Region 4, Office of Director 2pp 17706 262 24X
Fiche 50-458, 83/03/03, 8303280264

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl
DEYOUNG R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc 117pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8212060307 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 12lpp 17774.352 24X Fiche 50-000.83/03/21.8212060307.

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000.83/02/24.8302250505.

DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

A Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492.033 24X Fiche 50-000.83/02/16.8302170082.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700.303 24X Fiche 50-000.83/03/02.8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12) Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 5lpp 17660.176 24X Fiche 50-000.83/03/07.8303040005.

8303140268 Forwards newspaper article re cutback in work force at plant which will extend const completion date.
BELL, N. Coalition for Safe Power 83/03/07 GROSSMAN, H., HARBOUR, J., BRIGHT, G. O. Atomic Safety and Licensing Board Panel 2pp 17535.123 24X Fiche 50-460.83/03/07.8303140268.

8303170136 Summary of 830223 meeting w/BSW Regulatory Response Group in Bethesda, MD re small break LOCA procedures & maintaining proper steam generator water level.
VAN VLIET, J. Operating Reactors Branch 4 83/03/08 Operating Reactors Branch 4 43pp 17615.224 24X Fiche 50-000.83/03/08.8303170136.

8303150406 Submits info re amount of time listed factors delayed const which necessitated 810721 & 830111 requests for extension of const completion dates, in response to M Thadani request.
BOUCHEY, G. D. Washington Public Power Supply System 83/03/09 ADENSAM, E. G. Licensing Branch 4 2pp 17561.266 24X Fiche 50-460.83/03/09.8303150406.

8303290003 Advises that plan & schedule info for resolution of TMI Action Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps," will be submitted by 830701, in response to 820208 Generic Ltr 83-10e.
BOUCHEY, G. D. Washington Public Power Supply System 83/03/24 ADENSAM, E. G. Licensing Branch 4 1p 17723.129 24X Fiche 50-460.83/03/24.8303290003.

C Utility Environmental Report (ER), amends & correspondence

8303040449 Forwards Amend 1 to environ rept - OL stage, correcting typographical & organizational errors & incorporating responses to NRC acceptance review questions.
BOUCHEY, G. D. Washington Public Power Supply System 83/02/11 ADENSAM, E. G. Licensing Branch 4 2pp 17366.197 24X Fiche 50-460.83/02/11.8303040449.

--8303040453 Amend 1 to environ rept - OL stage, covering site & environ interfaces, environ effects of const & plant operation & effluent & environ measurement programs.
* Washington Public Power Supply System 83/02/28 362pp 17366.199 24X Fiche 50-460.83/02/11.8303040449.

G Adjudicatory correspondence

8303010086 Clarifies circumstances behind applicant 830217 motion for leave to suppl memorandum. Chairman Wolf believed Dana was potential witness, not member of Coalition for Safe Power.
BELL, N. Coalition for Safe Power 83/02/22 GROSSMAN, H., HARBOUR, J., BRIGHT, G. O. Atomic Safety and Licensing Board Panel 1p 17335.347 24X Fiche 50-460.83/02/22.8303010086.

8303020057 Response opposing proposed amended Contention 2. Petitioner fails to set forth adequate basis & specificity. No basis given to support allegation that util was dilatory or failed to show good cause for CP extension. W/Certificate of Svc.
REYNOLDS, N. S. Washington Public Power Supply System. REYNOLDS, N. S. Debevoise & Liberman 83/02/23 Atomic Safety and Licensing Board Panel 15pp 17352.163 24X Fiche 50-460.83/02/23.8303020057.

8303020023 Position on timetable for conduct of proceeding, in response to ASLB request at 830127 special prehearing conference. Discusses scheduling & ruling on admissibility of contentions. Certificate of Svc encl.
WAGNER, M. E., YOUNG, M. A. Hearing Branch 4 83/02/28 13pp 17352.288 24X Fiche 50-460.83/02/28.8303020023.

8303020036 Memorandum re scheduling & renoticing of future proceedings. Proceeding should not be deferred. Certificate of Svc encl.
REYNOLDS, N. S. Washington Public Power Supply System. REYNOLDS, N. S. Debevoise & Liberman 83/02/28 19pp 17354.229 24X Fiche 50-460.83/02/28.8303020036.

8303080034 Informs of util const committee request of util staff to develop program reducing staff size to number sufficient to continue only essential work & postpone plant completion until 1991.
REYNOLDS, N. S. Debevoise & Liberman. REYNOLDS, N. S. Washington Public Power Supply System 83/03/07 GROSSMAN, H., BRIGHT, G. O., HARBOUR, J. Atomic Safety and Licensing Board Panel 2pp 17455.359 24X Fiche 50-460.83/03/07.8303080034.

8303140268 Forwards newspaper article re cutback in work force at plant which will extend const completion date.
BELL, N. Coalition for Safe Power 83/03/07 GROSSMAN, H., HARBOUR, J., BRIGHT, G. O. Atomic Safety and Licensing Board Panel 2pp 17535.123 24X Fiche 50-460.83/03/07.8303140268.

8303100166 Response to util 830217 motion to suppl 830207 memorandum opposing issuance of protective order. NRC does not oppose motion. Basis for motion not unreasonable & justifies protective order. Certificate of Svc encl.
YOUNG, M. A., WAGNER, M. E. Hearing Branch 4 83/03/08 Atomic Safety and Licensing Board Panel 5pp 17485.215 24X Fiche 50-460.83/03/08.8303100166.

8303170498 Memorandum & order reciting actions taken at 830126-27 special prehearing conference & issuing order protecting Coalition for Safe Power membership info. Rights of association of member of Coalition threatened.
HARBOUR, J., BRIGHT, G. O., GROSSMAN, H. Atomic Safety and Licensing Board Panel 83/03/15 19pp 17611.051 24X Fiche 50-460.83/03/15.8303170498.

8303220250 Responds to petitioner 830307 ltr transmitting Oregonian article. Article appeared in 830303 & 04 editions, not 830226 edition as petitioner implied.
REYNOLDS, N. S. Debevoise & Liberman. REYNOLDS, N. S. Washington Public Power Supply System 83/03/18 Atomic Safety and Licensing Board Panel 6pp 17657.021 24X Fiche 50-460.83/03/18.8303220250.

8303290501 Memorandum & order admitting Coalition for Safe Power (CSP) as intervenor & CSP Contention 2. CSP Contention 1 denied. Discovery to commence immediately. Discovery status rept due on 830601.
HARBOUR, J., BRIGHT, G. O., GROSSMAN, H. Atomic Safety and Licensing Board Panel 83/03/25 Coalition for Safe Power 7pp 17724.087 24X Fiche 50-460.83/03/25.8303290501.

Q Inspection reports, IE Bulletins & correspondence

8303110058 Responds to FOIA request for rept by Ofc of Inspector & Auditor & associated records. Forwards documents listed in app. Documents partially withheld (ref FOIA Exemptions 6 & 7). Denial may be appealed within 30 days from ltr receipt.
FELTON, J. M. Division of Rules and Records 83/02/03 EMSHWILLER, J. R. Wall Street Journal 3pp 17520.189 24X Fiche 50-206.83/02/03.8303110058.

--8303110066 "Paul P. Narbut - Release of Draft Rept to Licensee," rept of investigation. Personally identifiable info deleted.
GAMBLE, D. H., RESNER, M. E. Office of Inspector & Auditor 82/06/15 57pp 17520.192 24X Fiche 50-000.83/02/03.8303110058.

--8303110086 Discusses actions re release of draft IE Insp Rept 50-460/82-04 on 820222-0312 by Univ Nuclear Sys, Inc. Personally identifiable info deleted.
NARBUT, P. Region 5, Office of Director 82/04/15 BISHOP, T. Division of Resident, Reactor Project & Engineering Programs 2pp 17520:248 24X Fiche 50-000, 83/02/03, 8303110058.

--8303110095 Prohibits use or release of all draft repts, insp repts & enforcement documents outside NRC unless prior approval obtained from regional administrator or authorized by established procedures. Related info encl.
ENGELKEN, R. H. Region 5, Office of Director 82/04/09 CREWS, J. L. Division of Resident, Reactor Project & Engineering Programs
SPENCER, G. S. Division of Radiological Safety & Safeguards Program 3pp 17520:250 24X Fiche 50-000, 83/02/03, 8303110058.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11lpp 17521:001 24X Fiche 50-000, 83/02/25, 8212060367.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp 17611:070 24X Fiche 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12lpp 17774:352 24X Fiche 50-000, 83/03/21, 8212060387.

S. Reportable occurrences, LERs & related correspondence

8303010617 Interim deficiency rept re generic problems w/ASCO NP-1 valves in nuclear applications including fire protection sys. Initially reported on 830120. Process for establishing position for recommended fix continuing.
ROOT, R. W. Washington Public Power Supply System 83/02/15
STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 4pp 17336:107 24X Fiche 50-460, 83/02/15, 8303010617.

8303040571 Interim deficiency rept re installation of improper auxiliary fuel oil motor on emergency diesel generator. Initially reported on 830120. Rework will be completed after const restart. Final rept will be provided following rework.
ROOT, R. W. Washington Public Power Supply System 83/02/18
STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 2pp 17374:061 24X Fiche 50-460, 83/02/18, 8303040571.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp 24X Fiche 50-000, 83/02/24, 8302250505.

DOCKET 50-461 CLINTON POWER STATION, UNIT 1

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 930630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X Fiche 50-000, 83/02/16, 8302170082.

8303010653 Confirms plans for 830317 meeting in Glen Ellyn, IL to discuss improvement program.
NORELIUS, C. E. Division of Project & Resident Programs 83/02/24
GERSTNER, W. C. Illinois Power Co. 1p 24X Fiche 50-461, 83/02/24, 8303010653.

8303310453 Partial response to FOIA request for six categories of documents. Forwards App A documents identified as Items 1, 3, 4, 5 & 6 of request. Search for documents re Item 2 of request continuing.
FELTON, J. M. Division of Rules and Records 83/02/24 HIATT, S. L. Ohio Citizens for Responsible Energy 2pp 17804:132 24X Fiche 50-000, 83/02/24, 8303310453.

--8303310481 Discusses MARCH analysis of hydrogen burn during degraded core accidents for facilities. Detailed comparisons of facility design parameters w/GESSAR & Grand Gulf encl.
YANG, J. W. Brookhaven National Laboratory 82/09/27 PRATT, W. T. Brookhaven National Laboratory 30pp 17806:130 24X Fiche 50-000, 83/02/24, 8303310453.

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J. G. Region 3, Office of Director 83/03/03 Commonwealth Edison Co. 2pp 17492:014 24X Fiche 50-000, 83/03/03, 8303100364.

8303160055 Summary of 830111 & 12 meetings w/util & GE in Bethesda, MD re design details of automatic testing sys used to test protection sys circuitry.
ABELSON, H. Licensing Branch 2 KENDALL, R. Instrumentation & Control Systems Branch 83/03/09 Licensing Branch 2 80pp 17604:233 24X Fiche 50-461, 83/03/09, 8303160055.

8303170548 Forwards "Nuclear Power Program Mgt Manual," update to 821115 submittal.
HALL, D. P. Illinois Power Co. 83/03/09 KEPPLER, J. G. Region 3, Office of Director 2pp 17607:334 24X Fiche 50-461, 83/03/09, 8303170548.

--8303170550 Updated "Nuclear Power Mgt Manual."
* Illinois Power Co. 83/03/09 33pp 17607:336 24X Fiche 50-461, 83/03/09, 8303170548.

8303210048 Confirms 830309 telcon re proposed FSAR figure deletions. Figures being deleted since drawings not controlled & maintained by GE.
WULLER, G. E. Illinois Power Co. 83/03/11 SCHWENCER, A. Licensing Branch 2 3pp 17631:358 24X Fiche 50-461, 83/03/11, 8303210048.

8303240215 Requests authorization to conduct cable pulling operation.
HALL, D. P. Illinois Power Co. 83/03/16 KEPPLER, J. G. Region 3, Office of Director 2pp 17682:164 24X Fiche 50-461, 83/03/16, 8303240215.

8303290369 Forwards proprietary & nonproprietary versions of "CLASIX-3 Computer Program for Analysis of Reactor Plant Containment Response to Hydrogen Release & De/lagration." Proprietary version withheld (ref 10CFR2.790).
RICHARDSON, J. D. Hydrogen Control Owners Group, BWR-6 Mark III 83/03/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17726:079 24X Fiche 50-000, 83/03/18, 8303290369.

--8303290378 Requests that "CLASIX-3 Computer Program for Analysis of Reactor Plant Containment Response to Hydrogen Release & Deflagration" be withheld from public disclosure. Affidavit encl.
WIESEMANN, R. A. Westinghouse Electric Corp. 83/01/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 6pp 17726:081 24X Fiche 50-000, 83/03/18, 8303290369.

8303290504 Forwards responses to NRC 820513 ltr & 820928 telcon, resolving Section 2.1 of Encl 3 to NRC 801222 ltr re control of heavy loads (NUREG-0612). Remaining info discussed in 820928 telcon will be provided by mid-June 1983.
WULLER, G. E. Illinois Power Co. 83/03/18 SCHWENCER, A. Licensing Branch 2 5pp 17723:004 24X Fiche 50-461, 83/03/18, 8303290504.

8303290371 Forwards responses to NRC questions re util 811016 preliminary rept on hydrogen ignition sys & 821229 submittal concerning degraded core hydrogen control, per 830303 telcon.
WULLER, G. E. Illinois Power Co. 83/03/21 SCHWENCER, A. Licensing Branch 2 3pp 17716:201 24X Fiche 50-461, 83/03/21, 8303290371.

8303280099 Responds to 830314 ltr proposing deletion of 20 outdated instrumentation engineering diagrams & functional control diagrams contained in Chapters 7 & 8 of FSAR. Proposal acceptable.
SCHWENCER, A. Licensing Branch 2 83/03/23 WULLER, G. Illinois Power Co. 2pp 17715:335 24X Fiche 50-461, 83/03/23, 8303280099.

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303090077 Clarifies commitment to perform leakage tests of valves on vent & drain lines located between containment isolation valves to resolve SER Outstanding Issue 10C.
WULLER,G.E. Illinois Power Co. 83/03/01 SCHWENCER,A. Licensing Branch 2. 3pp. 17467:062. 24X Fiche:50-461:83/03/01:8303090077.

8303090206 Forwards response to IE Bulletin 80-06 & SER Outstanding Issue 12 re ESF reset controls.List of equipment which returns to pre-LOCA state after reset encl.
WULLER,G.E. Illinois Power Co. 83/03/01 SCHWENCER,A. Licensing Branch 2. 7pp. 17471:118. 24X Fiche:50-461:83/03/01:8303090206.

8303090301 Forwards "Hazard Analysis of Flammable Compressed Gas Shipments on IL Central Gulf Railroad Near Clinton Power Station" & "Evaluation of Control Room Habitability During Postulated Release of ," per SER Outstanding Issue 1.
WULLER,G.E. Illinois Power Co. 83/03/04 SCHWENCER,A. Licensing Branch 2. 2pp. 17471:245. 24X Fiche:50-461:83/03/04:8303090301.

--8303090308 "Hazard Analysis of Flammable Compressed Gas Shipments on IL Central Gulf Railroad Near Clinton Power Station." (SER Outstanding Issue 1).
* Illinois Power Co. 83/03/04 34pp. 17471:247. 24X Fiche:50-461:83/03/04:8303090301.

--8303090315 "Evaluation of Control Room Habitability During Postulated Release of Toxic Matls Shipped by Rail." (SER Outstanding Issue 1).
* Illinois Power Co. 83/03/04 36pp. 17471:281. 24X Fiche:50-461:83/02/04:8303090301.

8303140600 Advises that resolution of portion of SER Outstanding Issue 20 re operational QA program will require additions & revs to FSAR,including commitment made in Mar 1982 conference call.
SCHWENCER,A. Licensing Branch 2. 83/03/07 WULLER,G. Illinois Power Co. 4pp. 17548:335. 24X Fiche:50-461:83/03/07:8303140600.

8303170162 Forwards "Response to NRC Request for Further Clarification on Soil Amplification Issue," per NRC 830112 ltr.Info adequate to close SER Outstanding Issue 3 in next SER suppl.
WULLER,G.E. Illinois Power Co. 83/03/10 SCHWENCER,A. Licensing Branch 2. 17pp. 17608:356. 24X Fiche:50-461:83/03/10:8303170162.

8303220088 Submits info on SER Confirmatory Issue 53 re containment penetration debris screen design.Debris screens to be installed on piping will be designed to listed criteria. Info will be incorporated in future FSAR amend.
WULLER,G.E. Illinois Power Co. 83/03/11 SCHWENCER,A. Licensing Branch 2. 2pp. 17650:055. 24X Fiche:50-461:83/03/11:8303220088.

8303220031 Responds to NRC review of ultimate containment pressure retaining capability,per Section 3.8.1 of SER (NUREG-0853). Use of 1.2 safety factor,reducing retaining capability to 63 psig agreeable.Confirmatory Issue 6 should be closed.
WULLER,G.E. Illinois Power Co. 83/03/15 SCHWENCER,A. Licensing Branch 2. 3pp. 17652:155. 24X Fiche:50-461:83/03/15:8303220031.

8303240327 Provides addl clarification of util commitment to perform periodic leakage testing of containment vent/purge isolation valves,per SER Outstanding Issue 10c.Tests of 36-inch vent/purge valves shall be conducted every 3 months.
WULLER,G.E. Illinois Power Co. 83/03/18 SCHWENCER,A. Licensing Branch 2. 2pp. 17679:342. 24X Fiche:50-461:83/03/18:8303240327.

8303280092 Provides addl info on qualification & design of optical isolators,per SER Confirmatory Issue 26.Qualification program included review of aging,seismic,environ & electromagnetic interference effects.
WULLER,G.E. Illinois Power Co. 83/03/23 SCHWENCER,A. Licensing Branch 2. 1p. 17707:248. 24X Fiche:50-461:83/03/23:8303280092.

8303280139 Submits info to close out SER Outstanding Issue 14 re safe shutdown capability following loss of bus supplying power to instruments & controls per IE Bulletins 79-22 & 79-27.
WULLER,G.E. Illinois Power Co. 83/03/23 SCHWENCER,A. Licensing Branch 2. 1p. 17706:342. 24X Fiche:50-461:83/03/23:8303280139.

8303290006 Advises that fire tests for penetration seals performed by Portland Cement Assoc.in response to Chemical Engineering Branch request at 830216-17 meeting.Info closes out SER Confirmatory Issue 59.
WULLER,G.E. Illinois Power Co. 83/03/25 SCHWENCER,A. Licensing Branch 2. 1p. 17722:247. 24X Fiche:50-461:83/03/25:8303290006.

F. Security, medical, emergency & fire protection plans

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition.Appropriate planning should take place to prevent possible transmission errors.
HIND,J.A. Region 3, Office of Director 83/03/22 Commonwealth Edison Co. 2pp. 17690:316. 24X Fiche:50-000:83/03/22:8303240440.

8303290006 Advises that fire tests for penetration seals performed by Portland Cement Assoc.in response to Chemical Engineering Branch request at 830216-17 meeting.Info closes out SER Confirmatory Issue 59.
WULLER,G.E. Illinois Power Co. 83/03/25 SCHWENCER,A. Licensing Branch 2. 1p. 17722:247. 24X Fiche:50-461:83/03/25:8303290006.

G. Adjudicatory correspondence

8303110222 Affidavit of J.Foy opposing applicant motion for summary disposition or for continuance pending discovery.No documents produced re Prairie Alliance 830128 request. Certificate of Svc encl.Related correspondence.
FOY,J.M. Prairie Alliance 83/03/03 2pp. 17518:348. 24X Fiche:50-461:83/03/03:8303110222.

8303150402 Response opposing Prairie Alliance 830305 affidavit opposing applicant 830117 motion for summary disposition or for continuance pending discovery.Rules prohibit ASLB consideration of late filed affidavit.W/Certificate of Svc.
FOX,C.D. Illinois Power Co. FOX,C.D. Schiff, Hardin & Waite. 83/03/11 Commissioners 7pp. 17561:269. 24X Fiche:50-461:83/03/11:8303150402.

I. Financial information

8303230268 Forwards Annual Financial Rept 1982 for applicant & Western IL Power Cooperative,Inc & Annual Financial Rept 1981 for Soyland Power Cooperative,Inc.W/o Western IL Power Cooperative Annual Rept.
WULLER,G.E. Illinois Power Co. 83/03/18 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 1p. 17661:044. 24X Fiche:50-461:83/03/18:8303230268.

--8303230271 Annual Financial Rept 1981.
SMITH,W. Soyland Power Cooperative, Inc. 83/03/18 19pp. 17661:045. 24X Fiche:50-461:83/03/18:8303230268.

--8303230280 Annual Financial Rept 1982.
KELLEY,W.J. Illinois Power Co. 83/02/23 35pp. 17661:065. 24X Fiche:50-461:83/03/18:8303230268.

J. Insurance & indemnity information

8303170270 Forwards Endorsement 17 to NELIA Policy NF-261.
TURNER,C.L. Illinois Power Co. 83/03/10 SALTZMAN,J. Antitrust & Economic Analysis Branch (Utility Finance) 2pp. 17606:057. 24X Fiche:50-461:83/03/10:8303170270.

K. Utility Final Safety Analysis Report (FSAR) & amends

8303040347 Forwards Amend 23 to FSAR.
HALL,D.P. Illinois Power Co. 83/02/25 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 1p. 17371:182. 24X Fiche:50-461:83/02/25:8303040347.

--8303040351 Amend 23 to FSAR,updating QA program Chapter 17 to reflect current organization structure,evaluating plant-specific ECCS performance (TMI Item II.K.3.31) & changing SER issues.
* Illinois Power Co. 83/02/28 263pp. 17371:184. 24X Fiche:50-461:83/02/25:8303040347.

Q. Inspection reports, IE Bulletins & correspondence

8303090125 Responds to IE Bulletin 82-04 re deficiencies in primary containment electrical penetration assemblies.No Bunker-Ramo electrical penetrations using hard epoxy module design installed or planned to be installed in safety-related sys.
WULLER,G.E. Illinois Power Co. 83/02/15 KEPPLER,J.G. Region 3, Office of Director 1p. 17470:300. 24X Fiche:50-461:83/02/15:8303090125.

8303140295 Forwards IE Insp Rept 50-461/83-03 on 830207-10.No noncompliance noted.
PAPERIELLO,C.J. Division of Emergency Preparedness & Operational Support 83/02/24 GERSTNER,W.C. Illinois Power Co. 2pp. 17535:045. 24X Fiche:50-461:83/02/24:8303140295.

--8303140300 IE Insp Rept 50-461/83-03 on 830207-10 No noncompliance noted Major areas inspected preoperational insp of radwaste & radiation protection programs including staffing, procedures & respiratory protection
PAUL, R A ; GREGER, L R Region 3, Office of Director 83/02/24
5pp 17535:047 24X Fiche 50-461, 83/02/24, 8303140295

8303080256 Ack receipt of 830218 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-461/82-20
KNOP, R C Division of Project & Resident Programs 83/03/01
GERSTNER, W C Illinois Power Co 1p 17446:341 24X
Fiche 50-461, 83/03/01, 8303080256

--8303080263 Responds to NRC 830118 ltr re violations noted in IE Insp Rept 50-461/82-20 Corrective actions overall sys stability verified through review of existing calculations of total sys Lateral stability of support arrangement confirmed
HALL, D P Illinois Power Co 83/01/18 KNOP, R C Division of Project & Resident Programs 4pp 17446:342 24X
Fiche 50-461, 83/03/01, 8303080256

8303090206 Forwards response to IE Bulletin 80-06 & SER Outstanding Issue 12 re ESF reset controls List of equipment which returns to pre-LOCA state after reset encl
WULLER, G E Illinois Power Co 83/03/01 SCHWENCER, A Licensing Branch 2 7pp 17471:118 24X Fiche 50-461, 83/03/01, 8303090206

8303140182 Ack receipt of 820604 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-461/81-15
NORELIUS, C E Division of Project & Resident Programs 83/03/08
GERSTNER, W C Illinois Power Co 1p 17528:132 24X
Fiche 50-461, 83/03/08, 8303140182

--8303140186 Responds to NRC 820517 ltr re violations noted in IE Insp Rept 50-461/81-15 Corrective actions QA manual rewritten, test data bank of questions for QC inspectors developed & bldg arrangement & grading exam process changed
GERSTNER, W C Illinois Power Co 82/06/04 KEPPLER, J G Region 3, Office of Director 7pp 17528:133 24X Fiche 50-461, 83/03/08, 8303140182

8303170398 Advises that all procedures, instructions & checklists re overinsp & record verification program were submitted to NRC on 830309
HALL, D P Illinois Power Co 83/03/09 KEPPLER, J G Region 3, Office of Director 1p 17609:280 24X Fiche 50-461, 83/03/09, 8303170398

8303170329 Reconfirms 830317 meeting w/util in Glen Ellyn, IL to discuss SALP rept
NORELIUS, C E Division of Project & Resident Programs 83/03/11
GERSTNER, W C Illinois Power Co 1p 17605:169 24X
Fiche 50-461, 83/03/11, 8303170329

8303240222 Responds to NRC 820127, 0901, 1006 & 1220 ltrs re util improvement program Status update comprehensive corrective action program in place, effective QA audit & surveillance program established & staffing of QA adequate
HALL, D P Illinois Power Co 83/03/16 KEPPLER, J G Region 3, Office of Director 2pp 17682:162 24X Fiche 50-461, 83/03/16, 8303240222

8303280139 Submits info to close out SER Outstanding Issue 14 re safe shutdown capability following loss of bus supplying power to instruments & controls per IE Bulletins 79-22 & 79-27
WULLER, G E Illinois Power Co 83/03/23 SCHWENCER, A Licensing Branch 2 1p 17706:342 24X Fiche 50-461, 83/03/23, 8303280139

8303280196 Ack receipt of 830209 ltr re recovery plan for procurement of spare & replacement parts NRC concurs w/plan Activities will be examined during future insp
KEPPLER, J G Region 3, Office of Director 83/03/23 GERSTNER, W C Illinois Power Co 1p 17706:300 24X Fiche 50-461, 83/03/23, 8303280196

## S Reportable occurrences, LERs & related correspondence

8302080314 Interim Deficiency Rept 82-07 re breakdown in QA program for implementation of Criteria X & XVI of 10CFR50, App B Initially reported on 820708 Addl 90 days required to complete evaluation & submit corrective actions
HALL, D P Illinois Power Co 83/01/31 KEPPLER, J G Region 3, Office of Director 8pp 17056:282 24X Fiche 50-461, 83/01/31, 8302080314

## DOCKET 50-462 CLINTON POWER STATION, UNIT 2

### A Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492:033 24X
Fiche 50-000, 83/02/16, 8302170082

8303310453 Partial response to FOIA request for six categories of documents Forwards App A documents identified as Items 1, 3, 4, 5 & 6 of request Search for documents re Item 2 of request continuing
FELTON, J M Division of Rules and Records 83/02/24 HIATT, S L Ohio Citizens for Responsible Energy 2pp 17804:132 24X
Fiche 50-000, 83/02/24, 8303310453

--8303310481 Discusses MARCH analysis of hydrogen burn during degraded core accidents for facilities Detailed comparisons of facility design parameters w/GESSAR & Grand Gulf encl
YANG, J W Brookhaven National Laboratory 82/09/27 PRATT, W T Brookhaven National Laboratory 30pp 17806:130 24X
Fiche 50-000, 83/02/24, 8303310453

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys
KEPFLER, J G Region 3, Office of Director 83/03/03
Commonwealth Edison Co 2pp 17492:014 24X Fiche 50-000, 83/03/03, 8303100364

### F Security, medical, emergency & fire protection plans

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition Appropriate planning should take place to prevent possible transmission errors
HIND, J A Region 3, Office of Director 83/03/22 Commonwealth Edison Co 2pp 17690:316 24X Fiche 50-000, 83/03/22, 8303240440

### I Financial information

8303230268 Forwards Annual Financial Rept 1982 for applicant & Western IL Power Cooperative, Inc & Annual Financial Rept 1981 for Soyland Power Cooperative, Inc W/o Western IL Power Cooperative Annual Rept
WULLER, G E Illinois Power Co 83/03/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17661:044 24X
Fiche 50-461, 83/03/18, 8303230268

--8303230271 Annual Financial Rept 1981
SMITH, W Soyland Power Cooperative, Inc 83/03/18 19pp
17661:045 24X Fiche 50-461, 83/03/18, 8303230268

--8303230280 Annual Financial Rept 1982
KELLEY, W J Illinois Power Co 83/02/23 35pp 17661:065 24X
Fiche 50-461, 83/03/18, 8303230268

### J Insurance & indemnity information

8303170270 Forwards Endorsement 17 to NELIA Policy NF-261
TURNER, C L Illinois Power Co 83/03/10 SALTZMAN, J Antitrust & Economic Analysis Branch (Utility Finance) 2pp 17606:057 24X
Fiche 50-461, 83/03/10, 8303170270

### O Inspection reports, IE Bulletins & correspondence

8303170329 Reconfirms 830317 meeting w/util in Glen Ellyn, IL to discuss SALP rept
NORELIUS, C E Division of Project & Resident Programs 83/03/11
GERSTNER, W C Illinois Power Co 1p 17605:169 24X
Fiche 50-461, 83/03/11, 8303170329

## DOCKET STN-50-470 CESSAR SYSTEM 80

### A Application/construction stage documents & correspondence

8303030423 Advises that response to NRC 830131 ltr re util 820330 submittal on core protection calculators will be submitted by 830331
SCHERER, A E Combustion Engineering, Inc 83/02/25 EISENHUT, D G Division of Licensing 2pp 17410:113 24X Fiche 50-470, 83/02/25, 8303030423

8303030419 Advises that results of CESSAR-F load limiter tests in reactor vessel lower key horizontal supports will be provided to AZ Public Svc during Second Quarter 1983 for inclusion in dockets for Palo Verde Plants
SCHERER, A E Combustion Engineering, Inc 83/02/28 EISENHUT, D G Division of Licensing 2pp 17410 121 24X Fiche 50-470, 83/02/28, 8303030419

8303040467 Forwards draft mods to Sys 80 fuel design for CESSAR-F Mods include completion of seismic & LOCA loading analyses Changes will be formally incorporated into CESSAR-F in next amend
SCHERER, A E Combustion Engineering, Inc 83/02/28 EISENHUT, D G Division of Licensing 6pp 17373 310 24X Fiche 50-470, 83/02/28, 8303040467

8303080226 Forwards proprietary & nonproprietary versions of "Sys 80 CESSAR FSAR Responses to Questions on CESEC " Affidavit encl Proprietary version withheld (ref 10CFR2 790)
SCHERER, A E Combustion Engineering, Inc 83/02/28 THOMAS, C O Standardization & Special Projects Branch 5pp 17455 008 24X Fiche 50-470, 83/02/28, 8303080226

--8303080236 Nonproprietary "Sys 80 CESSAR FSAR Responses to Questions on CESEC "
* Combustion Engineering, Inc 83/02/28 180pp 17455 013 24X Fiche 50-470, 83/02/28, 8303080226

8303090351 Responds to NRC 820326 request re info concerning rapid depressurization & DHR capability Some responses will rely on plant-specific info from balance of plant C-E Owners Group rept will be submitted by 830630
SCHERER, A E Combustion Engineering, Inc 83/02/28 EISENHUT, D G Division of Licensing 2pp 17472 136 24X Fiche 50-470, 83/02/28, 8303090351

8303160031 Forwards request for addl info re Parts II & III of "Statistical Combination of Uncertainties for C-E Sys 80 Plants," transmitted by 821008 ltr Schedule of responses requested within 7 days of ltr receipt
THOMAS, C O Standardization & Special Projects Branch 83/03/07
SCHERER, A E Combustion Engineering, Inc 5pp 17615 042 24X Fiche 50-470, 83/03/07, 8303160031

8303150057 Notification of 830323 meeting w/C-E in Bethesda, MD to discuss NRC position re use of iodine removal sys
MEYER, G C Standardization & Special Projects Branch 83/03/08
THOMAS, C O Standardization & Special Projects Branch 3pp 17586 303 24X Fiche 50-470, 83/03/08, 8303150057

8303160024 Responds to 830127 ltr re CESSAR FDA schedule Conclusions re adequacy & completeness of interface requirements could be verified by direct feedback from Palo Verde review
EISENHUT, D G Division of Licensing 83/03/10 SCHERER, A E Combustion Engineering, Inc 4pp 17615 057 24X Fiche 50-470, 83/03/10, 8303160024

8303240261 Provides ref info in order to close out NUREG-0737, Items II K 2 13, "Thermal-Mechanical Rept," II K 2 17, "Potential Voiding in RCS" & II K 3 30, "10CFR50 App K Small Break LOCA Methods "
SCHERER, A E Combustion Engineering, Inc 83/03/22 EISENHUT, D G Division of Licensing 2pp 17682 213 24X Fiche 50-470, 83/03/22, 8303240261

E. NRC Safety Evaluation Report (SER), supplS & correspondence

8303030284 Forwards list of status of all open & confirmatory items listed in SER, NUREG-0852 Many items resolved
MIRAGLIA, F J Assistant Director for Safety Assessment 83/02/22
HOUSTON, R W Assistant Director for Reactor Safety RUBENSTEIN, L S Assistant Director for Core & Plant Systems KNIGHT, J P Assistant Director for Comp & Structures Engineering (Post 830201) 9pp 17365 224 24X Fiche 50-470, 83/02/22, 8303030284

8303030647 Forwards proprietary & nonproprietary "Statistical Combination of Uncertainties Part II, Uncertainty Analysis of Limiting Conditions for Operation, C-E Sys 80 NSSS, Part III " Proprietary versions withheld (10CFR2 790)
SCHERER, A E Combustion Engineering, Inc 83/02/28 EISENHUT, D G Division of Licensing 6pp 17414 045 24X Fiche 50-470, 83/02/28, 8303030647

--8303030651 Nonproprietary "Statistical Combination of Uncertainties Part II, Uncertainty Analysis of Limiting Safety Sys Settings C-E Sys 80 NSSS, Part II "
* Combustion Engineering, Inc 83/01/31 53pp 17414 051 24X Fiche 50-470, 83/02/28, 8303030647

--8303030655 Nonproprietary "Statistical Combination of Uncertainties Part III, Uncertainty Analysis of Limiting Conditions for Operation C-E Sys 80 NSSS, Part III "
* Combustion Engineering, Inc 83/01/31 53pp 17414 103 24X Fiche 50-470, 83/02/28, 8303030647

8303080406 Forwards nonproprietary & proprietary "Response to NRC Questions for CESSAR-F Statistical Combination of Uncertainty in Thermal Margin Analysis for Sys 80," per SER Confirmatory Item 7 Affidavit per 10CFR2 790 encl
SCHERER, A E Combustion Engineering, Inc 83/03/04 EISENHUT, D G Division of Licensing 5pp 17451 318 24X Fiche 50-470, 83/03/04, 8303080406

--8303080412 Nonproprietary "Response to NRC Questions for CESSAR-F Statistical Combination of Uncertainty in Thermal Margin Analysis for Sys 80 "
* Combustion Engineering, Inc LD-83-020 1-NP 83/03/31 25pp 17451 323 24X Fiche 50-470, 83/03/04, 8303080406

8303150209 Forwards amended CESSAR-F Section 15 3 3, "Single Reactor Coolant Pump Rotor Seizure W/Loss of Offsite Power," in response to NRC 820115 request & SER Confirmatory Item 16
SCHERER, A E Combustion Engineering, Inc 83/03/10 EISENHUT, D G Division of Licensing 29pp 17555 124 24X Fiche 50-470, 83/03/10, 8303150209

8303230483 Forwards status rept of open & confirmatory items listed in 830307 SER Suppl 1 to SER will be issued on 830331 Comments & concurrence on draft requested by 830316
MIRAGLIA, F J Assistant Director for Safety Assessment 83/03/11
HOUSTON, R W Assistant Director for Reactor Safety RUBENSTEIN, L S Assistant Director for Core & Plant Systems KNIGHT, J P Assistant Director for Comp & Structures Engineering (Post 830201) 8pp 17677 252 24X Fiche 50-470, 83/03/11, 8303230483

DOCKET 50-471 PILGRIM NUCLEAR POWER STATION, UNIT 2

H. General correspondence

8303300062 Responds to 830302 proposal re closing LPDRs for cancelled or deferred plants No objection to closing LPDRs for submitted plants Other LPDRs will remain open pending resolution of CP status
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/03/18 FELTON, J M Division of Rules and Records 3pp 17751 074 24X Fiche 50-000, 83/03/18, 8303300062

DOCKET STN-50-482 WOLF CREEK GENERATING STATION

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24X Fiche 50-000, 83/02/16, 8302170082

8303100370 Summary of 830223 meeting w/utils, SNUPPS, Bechtel & Westinghouse in Bethesda, MD re equipment qualification Effort will be made to complete audits of both units during same wk in mid-May if practical
EDISON, G E , HOLONICH, J J Licensing Branch 1 83/02/24
Licensing Branch 1 5pp 17522 011 24X Fiche 50-000, 83/02/24, 8303100370

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillanre requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X Fiche 50-000, 83/03/02, 8303020321

8303040524 Requests that simultaneous review of both Facility Tech Specs be performed in interest of standardization & review efficiency
PETRICK, N Standardized Nuclear Unit Power Plant System 83/03/02
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17366 189 24X Fiche 50-000, 83/03/02, 8303040524

8303100369 Summary of 821129 meeting w/utils & SNUPPS in Bethesda, MD re relaxation of proposed pipe snubber Tech Spec
HOPKINS, J B Licensing Branch 4 83/03/02 Licensing Branch 4 6pp 17522 016 24X Fiche 50-000, 83/03/02, 8303100369

8303150469 Submits objectives of sys turnover quality action plan & actions & criteria to be used to determine when to lift self-imposed stop work order
KOESTER, G. L. Kansas Gas & Electric Co. 83/03/02 COLLINS, J. T. Region 4, Office of Director 2pp 17561:142 24X
Fiche: 50-482, 83/03/02, 8303150469

8303080257 Forwards revised Figure 3.4-2 containing heatup limitations for RCS, replacing 830216 figure in draft Tech Specs Info incorporated into OL application
KOESTER, G. L. Kansas Gas & Electric Co. 83/03/04 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp 17452:300 24X Fiche: 50-482, 83/03/04, 8303080257

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005

8303150340 Advises of 830405 meeting w/licensees & major contractors at Dallas/Fort Worth, TX to provide info & guidance re 10CFR50 QA & Tech Spec deviations & discuss decentralization policy. Questions should be submitted in writing by 830321
COLLINS, J. T. Region 4, Office of Director 83/03/10 Public Service Co. of Colorado 12pp 17562:291 24X
Fiche: 50-000, 83/03/10, 8303150340

8303150471 Ack receipt of 830302 ltr outlining action plan to correct deficiencies in QA programs re turnover of safety-related sys. Objectives & identified corrective actions appropriate. Notification prior to removing stop work order requested
COLLINS, J. T. Region 4, Office of Director 83/03/10 KOESTER, G. L. Kansas Gas & Electric Co. 1p 17561:061 24X Fiche: 50-482, 83/03/10, 8303150471

8303150453 Notifies of 830405 public meeting at Dallas/Ft Worth, TX Airport to discuss NRC policy of decentralization, change to 10CFR50, "Reporting of Change to QA Program" & proposal to allow licensee to depart from Tech Specs in emergency
COLLINS, J. T. Region 4, Office of Director 83/03/11 KOESTER, G. L. Kansas Gas & Electric Co. 2pp 17561:068 24X
Fiche: 50-482, 83/03/11, 8303150453

8303280022 Forwards Rev 6 to QA program for design & const W/o encl
SEIKEN, S. J. Standardized Nuclear Unit Power Plant System 83/03/23
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 17707:347 24X Fiche: 50-000, 83/03/23, 8303280022

## E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303110001 Notifies that unresolved item in NRC 820825 ltr re safety classification of accumulator level measurement resolved, based on 830223 supplemental SER input
EDISON, G. E. Licensing Branch 1 83/02/24 NEISLER, J. Licensing Branch 1 1p 17546:293 24X Fiche: 50-000, 83/02/24, 8303110001

8303140287 Forwards "Rept of Independent Review of Environ Qualification Programs to NUREG-0588," submitted per SER Confirmatory Issue 7. Rept documents status of safety-related electrical equipment. Site audit due in 4-6 wks
PETRICK, N. A. Standardized Nuclear Unit Power Plant System 83/03/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 17531:299 24X Fiche: 50-000, 83/03/10, 8303140287

--8303140294 "Rept of Independent Review of Environ Qualification Programs to NUREG-0588."
* Standardized Nuclear Unit Power Plant System 83/03/10 696pp 17531:301 24X Fiche: 50-000, 83/03/10, 8303140287

8303240143 Notification of 830412 meeting w/utils in Bethesda, MD to discuss schedule & status of SER issues & emergency response facilities
EDISON, G. E. HOLONICH, J. J. Licensing Branch 1 83/03/11
YOUNGBLOOD, B. J. Licensing Branch 1 4pp 17696:359 24X
Fiche: 50-000, 83/03/11, 8303240143

## F. Security, medical, emergency & fire protection plans

8303110098 Requests addl info re interim security plan within 30 days. Electrical breaker lock referred to in Section 1.2.8 should be described along w/procedures controlling lock
EVANS, L. J. Fuel Facility Safeguards Licensing Branch 82/11/24
KOESTER, G. L. Kansas Gas & Electric Co. 2pp 17526:215 24X
Fiche: 50-482, 82/11/24, 8303110098

8303140306 Requests close cooperation in determining optimal locations for emergency notification sys & health physics network phones, per NUREG-0696
COLLINS, J. T. Region 4, Office of Director 83/02/24 KOESTER, G. C. Kansas Gas & Electric Co. 2pp 17535:032 24X
Fiche: 50-482, 83/02/24, 8303140306

8303230378 Notification of 830323 meeting w/util in Bethesda, MD to discuss status of IE review of emergency preparedness plan
HOLONICH, J. J. Licensing Branch 1 83/03/07 YOUNGBLOOD, B. J. Licensing Branch 1 4pp 17675:265 24X Fiche: 50-482, 83/03/07, 8303230378

8303240143 Notification of 830412 meeting w/utils in Bethesda, MD to discuss schedule & status of SER issues & emergency response facilities
EDISON, G. E. HOLONICH, J. J. Licensing Branch 1 83/03/11
YOUNGBLOOD, B. J. Licensing Branch 1 4pp 17696:359 24X
Fiche: 50-000, 83/03/11, 8303240143

8303290259 Advises of unacceptable personnel recruiting practices which inadvertently may release safeguards info
COLLINS, J. T. Region 4, Office of Director 83/03/25 KOESTER, G. L. Kansas Gas & Electric Co. 2pp 17716:194 24X
Fiche: 50-482, 83/03/25, 8303290259

## G. Adjudicatory correspondence

8303220330 Order memorializing 830310 prehearing conference in Burlington, KS. ME Salava & W Christy directed to file updated answers to interrogatories & specific objections to emergency plan, in proposed stipulation form, by 830407
LAURENSON, J. A. Atomic Safety and Licensing Board Panel 83/03/18
Salava, M. E. Intervenor 5pp 17655:343 24X
Fiche: 50-482, 83/03/18, 8303220330

## K. Utility Final Safety Analysis Report (FSAR) & amends

8303150503 Forwards Rev 11 to SNUPPS FSAR
PETRICK, N. A. Standardized Nuclear Unit Power Plant System 83/03/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17559:249 24X Fiche: 50-000, 83/03/10, 8303150503

--8303150513 Rev 11 to SNUPPS FSAR.
* Standardized Nuclear Unit Power Plant System 83/03/31 221pp 17559:251 24X Fiche: 50-000, 83/03/10, 8303150503

## Q. Inspection reports, IE Bulletins & correspondence

8303210565 Discusses IE Insp Rept 50-482/82-22 on 821208 & forwards notice of violation
SEIDLE, W. C. Region 4, Office of Director 82/12/20 KOESTER, G. L. Kansas Gas & Electric Co. 1p 17632:305 24X Fiche: 50-482, 82/12/20, 8303210565

--8303210571 Notice of violation from insp on 821208. Noncompliance noted: failure to follow instructions, procedures & drawings per Administrative Procedure ADM 02-100, clearance order procedure
* Region 4, Office of Director 82/12/20 2pp 17632:306 24X
Fiche: 50-482, 82/12/20, 8303210565

8303180353 Forwards IE Insp Rept 50-482/82-18 on 821108-10. No noncompliance noted
SEIDLE, W. C. Region 4, Office of Director 83/01/11 KOESTER, G. L. Kansas Gas & Electric Co. 2pp 17620:097 24X
Fiche: 50-482, 83/01/11, 8303180353

--8303180357 IE Insp Rept 50-482/82-18 on 821108-10. No noncompliance noted. Major areas inspected: preoperational environ protection programs, including organization & administration, audits, training & procedures
CHANEY, H. D.; MURRAY, B. Region 4, Office of Director 83/01/05
24pp 17620:099 24X Fiche: 50-482, 83/01/11, 8303180353

8303210513 Forwards IE Insp Rept 50-482/82-22 on 821201-31 & notice of violation
SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 83/02/23 KOESTER, G. L. Kansas Gas & Electric Co. 3pp 17631:255 24X Fiche: 50-482, 83/02/23, 8303210513

--8303210520 Notice of violation from insp on 821201-31
* Region 4, Office of Director 83/02/23 2pp 17631:258 24X
Fiche: 50-482, 83/02/23, 8303210513

--8303210529 IE Insp Rept 50-482/82-22 on 821201-31. Noncompliance noted: failure to follow Administrative Procedure ADM 02-100, "Clearance Order Procedure."
SCHUM, W. S.; JOHNSON, W. D. Region 4, Office of Director 83/02/10
11pp 17631:260 24X Fiche: 50-482, 83/02/23, 8303210513

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11lpp. 17521.001 24X Fiche 50-000, 83/02/25, 8212060367.

8303210669 Forwards IE Insp Rept 50-482/83-01 on 821216-830115. No noncompliance noted.
SEIDLE, W. C. Region 4, Office of Director 83/02/28 KOESTER, G. L. Kansas Gas & Electric Co. 2pp. 17635.194 24X
Fiche 50-482, 83/02/28, 8303210669.

--8303210676 IE Insp Rept 50-482/83-01 on 821216-830115. No noncompliance noted. Major areas inspected: general plant tours, followup on previous insp findings & IE bulletins & safety-related component installation.
VANDEL, T. E., JOHNSON, W. D. Region 4, Office of Director 83/02/24 5pp. 17635.196 24X Fiche 50-482, 83/02/28, 8303210669.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 11lpp. 17611.070 24X Fiche 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 11lpp. 24X Fiche 50-000, 83/03/18, 8212060383.

8303230026 EN-83-015 on 830323, notice of violation & proposed imposition of civil penalty in amount of $40,000 will be issued re failure to ensure that sys turned over from const contractor to licensee startup organization complete.
KLINGLER, G., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/03/18 1p. 17663.247 24X Fiche 50-482, 83/03/18, 8303230026.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12lpp. 17774.352 24X Fiche 50-000, 83/03/21, 8212060387.

G. Reportable occurrences, LERs & related correspondence

8303030338 Submits daily highlight for 830218 Region IV enforcement meeting held w/util & Daniel Intl Corp re 10CFR50.55(e) concerns. Util issued self-imposed stop work order on turnover of sys to preoperational testing personnel.
HOLONICH, J. J. Licensing Branch 1 83/02/23 DENTON, H. R., CASE, E., CARTER, J. Office of Nuclear Reactor Regulation, Director 2pp. 17365.097 24X Fiche 50-482, 83/02/23, 8303030338.

8303080498 Interim deficiency rept re potential post-accident errors in RCS wide-range pressure instruments. Potential inaccuracies do not constitute significant deficiency for facility. Summary of evaluation encl.
KOESTER, G. L. Kansas Gas & Electric Co. 83/03/01 SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 6pp. 17452.315 24X Fiche 50-482, 83/03/01, 8303080498.

8303150334 Interim deficiency rept re matl traceability of bulk bolting matls. Initially reported on 830204. Corrective action rept issued to track evaluation & resolve U-bolt installed w/color indicating type matl. Status rept expected by 830523.
KOESTER, G. L. Kansas Gas & Electric Co. 83/03/03 SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 2pp. 17563.042 24X Fiche 50-482, 83/03/03, 8303150334.

8303150344 Interim deficiency rept re insufficient torque on structural steel bolted connections. Initially reported on 830204. Some connections in reactor & diesel generator bldg found insufficiently tightened. Status rept expected by 830620.
KOESTER, G. L. Kansas Gas & Electric Co. 83/03/03 SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 1p. 17562.352 24X Fiche 50-482, 83/03/03, 8303150344.

8303150390 Interim Significant Deficiency Rept 82-01 re sheared pinion keys on Limitorque SB-0-25 motor operators. Failures limited to motor operators used in conjunction w/Westinghouse valves subj to stall tests greater than max operating loads.
SEIKEN, S. J. Standardized Nuclear Unit Power Plant System 83/03/03 KEPPLER, J. G. Region 3, Office of Director 2pp. 17562.011 24X Fiche 50-000, 83/03/03, 8303150390.

8303150442 Interim deficiency rept re undetectable failure in Westinghouse solid state protection sys. No change in status since 820903 rept. No design changes expected within next 6 months. Followup rept will be submitted by 830902.
PETRICK, N. A. Standardized Nuclear Unit Power Plant System 83/03/03 KEPPLER, J. G. Region 3, Office of Director COLLINS, J. T. Region 4, Office of Director 1p. 17562.257 24X
Fiche 50-000, 83/03/03, 8303150442.

8303180249 Final deficiency rept re main steam isolation bypass control valves mfg by Masoneilan. Initially reported on 830211. Valves will be reworked & corrected prior to fuel load.
KOESTER, G. L. Kansas Gas & Electric Co. 83/03/11 SEIDLE, W. C. Region 4, Office of Director 1p. 17621.098 24X
Fiche 50-482, 83/03/11, 8303180249.

8303180306 Final deficiency rept re reliability of nuclear solenoid valves mfg by Garrett Corp. Initially reported on 830211. Garrett Corp changed matls & tolerances of detail components. Valves will be retrofitted prior to fuel load.
KOESTER, G. L. Kansas Gas & Electric Co. 83/03/11 SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 2pp. 17617.090 24X Fiche 50-482, 83/03/11, 8303180306.

8303250024 Interim deficiency rept re workmanship on Swagelok fittings. Initially reported on 830215. Corrective actions taken to ensure craft personnel deburr & properly install fittings. Next rept expected by 830603.
KOESTER, G. L. Kansas Gas & Electric Co. 83/03/17 SEIDLE, W. C. Division of Resident, Reactor Project & Engineering Programs 1p. 17693.129 24X Fiche 50-482, 83/03/17, 8303250024.

8303280201 Final deficiency rept re Foxboro modules. Initially reported on 830218. Certain model code devices subj to mfg damage. Nine modules returned to Foxboro Co for replacement.
KOESTER, G. L. Kansas Gas & Electric Co. 83/03/18 SEIDLE, W. C. Region 4, Office of Director 4pp. 17708.187 24X
Fiche 50-482, 83/03/18, 8303280201.

8303280226 Interim deficiency rept re matls supplied by Ray Miller Corp. Initially reported on 830218. Suspect matl used in safety-related applications being evaluated. Three of five identified flanges placed on hold. Next rept by 830715.
KOESTER, G. L. Kansas Gas & Electric Co. 83/03/18 SEIDLE, W. C. Region 4, Office of Director 1p. 17708.171 24X
Fiche 50-482, 83/03/18, 8303280226.

8303280164 Final deficiency rept re diesel pump for fire protection. Initially reported on 830221. Governor tubing will be replaced w/new tubing w/double flare ends. Corrective action will be completed prior to fuel load.
KOESTER, G. L. Kansas Gas & Electric Co. 83/03/21 SEIDLE, W. C. Region 4, Office of Director 4pp. 17709.233 24X
Fiche 50-482, 83/03/21, 8303280164.

8303280175 Interim deficiency rept re hanger notes & symbols. Initially reported on 830221. Designer & constructor will identify installed items needing rework. Review of spec changes continuing. Next rept will be submitted by 830919.
KOESTER, G. L. Kansas Gas & Electric Co. 83/03/21 SEIDLE, W. C. Region 4, Office of Director 2pp. 17709.286 24X
Fiche 50-482, 83/03/21, 8303280175.

8303280269 Interim deficiency rept re bolt torque on instrument mounts. Initially reported on 830222. Evaluation & revised torque specs for instrument mounting bolts requested from manufacturer. Status of evaluation expected by 830624.
KOESTER, G. L. Kansas Gas & Electric Co. 83/03/21 SEIDLE, W. C. Region 4, Office of Director 1p. 17706.255 24X
Fiche 50-482, 83/03/21, 8303280269.

8303290394 Interim Part 21 rept re lock-up of RM-23 display in radiation monitoring sys giving erroneous indication of channel activity. Initially reported on 830223. Problem software related. Final rept will be submitted by 830531.
SEIKEN, S. J. Standardized Nuclear Unit Power Plant System 83/03/22 KEPPLER, J. G. Region 3, Office of Director COLLINS, J. T. Region 4, Office of Director 2pp. 17725.211 24X Fiche 50-000, 83/03/22, 8303290394.

T. Hearing transcripts on non-antitrust matters

8303150181 Transcript of 830310 prehearing conference in Burlington, KS. Pp. 82-144.
* Atomic Safety and Licensing Board Panel 83/03/10 65pp. 17550.097 24X Fiche 50-482, 83/03/10, 8303150181.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche 50-000, 83/02/24, 8302250505

DOCKET STN-50-483 CALLAWAY PLANT, UNIT 1

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp. 17492 033. 24X
Fiche 50-000, 83/02/16, 8302170082

8303030747 Board Notification 83-13. Forwards EG&G draft rept, "Identification & Ranking of Nuclear Plant Structures, Sys & Components & Graded QA Guidelines."
EISENHUT, D. G. Division of Licensing 83/02/17 PALLADINO, N. Commissioners. 24pp. 17364 037. 24X Fiche 50-000, 83/02/17, 8303030747

8303030710 Board Notification 83-17. Forwards JH Conran 830209 affidavit re changes to previous testimony on Unresolved Safety Issue A-17, "Sys Interaction in Nuclear Power Plants."
EISENHUT, D. G. Division of Licensing 83/02/18 PALLADINO, N. J. Commissioners. 6pp. 17363 317. 24X Fiche 50-000, 83/02/18, 8303030710

8303100370 Summary of 830223 meeting w/utils, SNUPPS, Bechtel & Westinghouse in Bethesda, MD re equipment qualification. Effort will be made to complete audits of both units during same wk in mid-May if practical.
EDISON, G. E. ; HOLONICH, J. J. Licensing Branch 1 83/02/24 Licensing Branch 1 5pp. 17522 011. 24X Fiche 50-000, 83/02/24, 8303100370

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700 303. 24X
Fiche 50-000, 83/03/02, 8303020321

8303040524 Requests that simultaneous review of both facility Tech Specs be performed in interest of standardization & review efficiency.
PETRICK, N. Standardized Nuclear Unit Power Plant System 83/03/02
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp. 17366 189. 24X Fiche 50-000, 83/03/02, 8303040524

8303100369 Summary of 821129 meeting w/utils & SNUPPS in Bethesda, MD re relaxation of proposed pipe snubber Tech Spec.
HOPKINS, J. C. Licensing Branch 4 83/03/02 Licensing Branch 4 6pp. 17522 016. 24X Fiche 50-000, 83/03/02, 8303100369

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys.
KEPPLER, J. G. Region 3, Office of Director 83/03/03
Commonwealth Edison Co. 2pp. 17492 014. 24X Fiche 50-000, 83/03/03, 8303100364

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp. 17660 176. 24X
Fiche 50-000, 83/03/07, 8303040005

8303280137 Comments on Board Notification 83-38 re failure of GE AK-2 reactor trip breakers. Info may affect NRC conclusions re probability/corrective measures for transients w/o scram events (Unresolved Safety Issue A-9).
EISENHUT, D. G. Division of Licensing 83/03/22 PALLADINO, N. Commissioners. 20pp. 17709 310. 24X Fiche 50-000, 83/03/22, 8303280137

8303280022 Forwards Rev 6 to QA program for design & const W/o encl.
SEIKEN, S. J. Standardized Nuclear Unit Power Plant System 83/03/23
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p. 17707 347. 24X Fiche 50-000, 83/03/23, 8303280022

8303290351 Forwards revised Tech Spec Section 6.0 & justification for deviations from STS (NUREG-0452) for review.
SCHNELL, D. F. Union Electric Co. 83/03/23 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp. 17725 127. 24X
Fiche 50-483, 83/03/23, 8303290351

--8303290356 Revised Tech Spec Section 6.0 re administrative controls.
* Union Electric Co. 83/03/23 40pp. 17725 130. 24X
Fiche 50-483, 83/03/23, 8303290351

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303110001 Notifies that unresolved item in NRC 820825 ltr re safety classification of accumulator level measurement resolved, based on P30223 supplemental SER input.
EDISON, G. E. Licensing Branch 1 83/02/24 NEISLER, J. Licensing Branch 1 1p. 17546 293. 24X Fiche 50-000, 83/02/24, 8303110001

8303140287 Forwards "Rept of Independent Review of Environ Qualification Programs to NUREG-0588," submitted per SER Confirmatory Issue 7. Rept documents status of safety-related electrical equipment. Site audit due in 4-6 wks.
PETRICK, N. A. Standardized Nuclear Unit Power Plant System 83/03/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p. 17531 299. 24X Fiche 50-000, 83/03/10, 8303140287.

--8303140294 "Rept of Independent Review of Environ Qualification Programs to NUREG-0588."
* Standardized Nuclear Unit Power Plant System 83/03/10 696pp. 17531 301. 24X Fiche 50-000, 83/03/10, 8303140287.

8303240143 Notification of 830412 meeting w/utils in Bethesda, MD to discuss schedule & status of SER issues & emergency response facilities.
EDISON, G. E. ; HOLONICH, J. J. Licensing Branch 1 83/03/11
YOUNGBLOOD, B. J. Licensing Branch 1 4pp. 17696 359. 24X
Fiche 50-000, 83/03/11, 8303240143

F. Security, medical, emergency & fire protection plans

8303150299 Forwards Rev 5 to FSAR & revised radiological emergency response plan.
SCHNELL, D. F. Union Electric Co. 83/02/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp. 17563 171. 24X
Fiche 50-483, 83/02/28, 8303150299

--8303150304 Revised radiological emergency response plan.
* Union Electric Co. 83/02/28 426pp. 17565 176. 24X
Fiche 50-483, 83/02/28, 8303150299

8303210102 Discusses 830224 telcon re incorrect location of plant on 10 & 50 mile emergency planning zone maps. Error probably due to incorrect longitude given in plant FSAR site addendum.
WHITE, A. Union Electric Co. 83/02/28 AXELSON, W. L. Region 3, Office of Director 1p. 17630 265. 24X Fiche 50-483, 83/02/28, 8303210102

8303240143 Notification of 830412 meeting w/utils in Bethesda, MD to discuss schedule & status of SER issues & emergency response facilities.
EDISON, G. E. Licensing Branch 1 83/03/11 YOUNGBLOOD, B. J. Licensing Branch 1 4pp. 17696 359. 24X Fiche 50-000, 83/03/11, 8303240143.

8303240045 Responds to 830224 ltr re proposed use of control room simulator during initial emergency preparedness exercise. Proposal acceptable.
PAPERIELLO, C. J. Region 3, Office of Director 83/03/22
SCHNELL, D. F. Union Electric Co. 2pp. 17681 026. 24X
Fiche 50-483, 83/03/22, 8303240045

--8303240048 Requests assurance of understanding of acceptability of using simulator for forthcoming emergency drill-for-score at facility.
STILLER, M. A. Union Electric Co. 83/02/24 AXELSON, W. L. Region 3, Office of Director 1p. 17681 028. 24X Fiche 50-483, 83/03/22, 8303240045.

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition. Appropriate planning should take place to prevent possible transmission errors.
HIND, J. A. Region 3, Office of Director 83/03/22 Commonwealth Edison Co. 2pp. 17690 316. 24X Fiche 50-000, 83/03/22, 8303240440

Q. Adjudicatory correspondence

8303010101 Memorandum & order specifying & accepting JG Reed Contention II re offsite emergency plans.
BRIGHT, G O ; KLINE, J R ; GLEASON, J P Atomic Safety and Licensing Board Panel 83/02/25 REED, J G Reed, J G 3pp 17345:035 24X Fiche: 50-483, 83/02/25, 8303010101

8303070118 Brief supporting exceptions to ASLB 821203 partial initial decision on Contention 1. Decision granting OL should be denied, or alternatively, remanded to await independent analysis of plant safety. Certificate of Svc encl.
CHACKES, K M Joint Intervenors-Callaway CHACKES, K M Chackes & Hoare 83/03/02 Atomic Safety and Licensing Appeal Panel 28pp 17432:309 24X Fiche: 50-483, 83/03/02, 8303070118

J. Insurance & indemnity information

8303140308 Forwards Endorsement 13 to NELIA Policy NF-164.
NADEL, M Marsh & McLennan, Inc 83/03/07 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 17535:034 24X Fiche: 50-483, 83/03/07, 8303140308

K. Utility Final Safety Analysis Report (FSAR) & amends

8303150299 Forwards Rev 5 to FSAR & revised radiological emergency response plan.
SCHNELL, D F Union Electric Co 83/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17563:171 24X Fiche: 50-483, 83/02/28, 8303150299

--8303150303 Rev 5 to FSAR.
* Union Electric Co 83/02/28 720pp 17563:176 24X Fiche: 50-483, 83/02/28, 8303150299.

--8303150304 Revised radiological emergency response plan.
* Union Electric Co 83/02/28 426pp 17565:176 24X Fiche: 50-483, 83/02/28, 8303150299.

8303150503 Forwards Rev 11 to SNUPPS FSAR.
PETRICK, N A Standardized Nuclear Unit Power Plant System 83/03/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 17559:249 24X Fiche: 50-000, 83/03/10, 8303150503

--8303150513 Rev 11 to SNUPPS FSAR.
* Standardized Nuclear Unit Power Plant System 83/03/31 221pp 17559:251 24X Fiche: 50-000, 83/03/10, 8303150503.

Q. Inspection reports, IE Bulletins & correspondence

8303110355 Board Notification 83-14: forwards followup info on apparent deficiencies in Midland-Ross superstrut matl.
EISENHUT, D G Division of Licensing 83/02/18 PALLADINO, N Commissioners 24pp 17546:205 24X Fiche: 50-000, 83/02/18, 8303110355

8303040532 Forwards IE Insp Rept 50-483/82-17 on 821102-05. No noncompliance noted.
LITTLE, W S Division of Engineering 83/02/22 SCHNELL, D F Union Electric Co 2pp 17366:131 24X Fiche: 50-483, 83/02/22, 8303040532

--8303040540 IE Insp Rept 50-483/82-17 on 821102-05. No noncompliance noted. Major areas inspected: preoperational test program in areas of test result packages, maint, housekeeping & training.
WOHLD, P R ; REYES, L A Region 3, Office of Director 83/02/17 3pp 17366:133 24X Fiche: 50-483, 83/02/22, 8303040532.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11lpp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8303030452 Ack receipt of 830218 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-19.
KNOP, R C Division of Project & Resident Programs 83/02/25
SCHNELL, D F Union Electric Co 1p 17410:011 24X
Fiche: 50-483, 83/02/25, 8303030452

--8303030453 Responds to NRC 830120 ltr re violations noted in IE Insp Rept 50-483/82-19. Corrective actions: training sessions held by civil engineering for craft workers re installation of plates & quality work.
SCHNELL, D F Union Electric Co 83/02/18 KNOP, R C Division of Project & Resident Programs 3pp 17410:012 24X
Fiche: 50-483, 83/02/25, 8303030452

8303140328 Forwards IE Insp Rept 50-483/83-01 on 830124-28. No noncompliance noted.
LITTLE, W S Region 3, Office of Director 83/02/28 SCHNELL, D F Union Electric Co 2pp 17544:013 24X Fiche: 50-483, 83/02/28, 8303140328.

--8303140334 IE Insp Rept 50-483/83-01 on 830124-28. No noncompliance noted. Major areas inspected: preoperational test program procedures, motor operated valve setup & testing, sys release package control & followup on previous open items.
WOHLD, P R ; REYES, L Region 3, Office of Director 83/02/22. 5pp 17544:015 24X Fiche: 50-483, 83/02/28, 8303140328.

8303220035 Forwards IE Insp Rept 50-483/82-21 on 821129-30 & 1201-03 & notice of violation.
LITTLE, W S Region 3, Office of Director 83/03/08 SCHNELL, D F Union Electric Co 2pp 17652:273 24X Fiche: 50-483, 83/03/08, 8303220035.

--8303220045 Notice of violation from insp on 821129-30 & 1201-03.
LITTLE, W S Region 3, Office of Director 83/03/07 2pp. 17652:275 24X Fiche: 50-483, 83/03/08, 8303220035.

--8303220050 IE Insp Rept 50-483/82-21 on 821129-30 & 1201-03. Noncompliance noted: failure to follow procedures re max allowable sidewall pressure & failure to protect Class IE equipment properly.
MENDEZ, R ; WILLIAMS, C C Region 3, Office of Director 83/03/07. 8pp 17652:277 24X Fiche: 50-483, 83/03/08, 8303220035.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

82,2060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche: 50-000, 83/03/18, 8212060383.

8303240209 Ack receipt of 830224 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-10.
NORELIUS, C E Division of Project & Resident Programs 83/03/18
SCHNELL, D F Union Electric Co 1p 17682:178 24X
Fiche: 50-483, 83/03/18, 8303240209

--8303240213 Responds to NRC 821103 ltr re violations noted in IE Insp Rept 50-483/82-10. Corrective actions: no testing, other than X-ray analysis & helium leak rate, performed. Surface imperfections will not affect electrical performance.
SCHNELL, D F Union Electric Co 83/02/24 SPESSARD, R L Division of Project & Resident Programs 2pp 17682:179 24X Fiche: 50-483, 83/03/18, 8303240209.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

S. Reportable occurrences, LERs & related correspondence

8303150390 Interim Significant Deficiency Rept 82-01 re sheared pinion keys on Limitorque SB-0-25 motor operators. Failures limited to motor operators used in conjunction w/Westinghouse valves subj to stall tests greater than max operating loads.
SEIKEN, S J Standardized Nuclear Unit Power Plant System 83/03/03
KEPPLER, J G Region 3, Office of Director 2pp 17562:011 24X
Fiche: 50-000, 83/03/03, 8303150390.

8303150442 Interim deficiency rept re undetectable failure in Westinghouse solid state protection sys. No change in status since 820903 rept. No design changes expected within next 6 months. Followup rept will be submitted by 830902.
PETRICK, N A Standardized Nuclear Unit Power Plant System 83/03/03 KEPPLER, J G Region 3, Office of Director COLLINS, J T Region 4, Office of Director 1p 17562:257 24X
Fiche: 50-000, 83/03/03, 8303150442.

8303150620 Board Notification 83-26: forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys. Info may affect conclusions re probability of/corrective measures for ATWS.
EISENHUT, D G Division of Licensing 83/03/03 PALLADINO, N ; ROBERTS, T M ; ASSELSTEIN, J K Commissioners 24pp 17584:097 24X
Fiche: 50-000, 83/03/03, 8303150620.

8303220309 Interim deficiency rept re effect of potential post-accident errors in wide-range RCS pressure instruments on SNUPPS plants Potential inaccuracies do not constitute significant deficiency Next rept by 830701
SCHNELL, D F Union Electric Co 83/03/07 SPESSARD, R L Division of Project & Resident Programs 8pp 17656 028 24x
Fiche 50-483, 83/03/07, 8303220309

8303290394 Interim Part 21 rept re lock-up of RM-23 display in radiation monitoring sys giving erroneous indication of channel activity Initially reported on 830223 Problem software related Final rept will be submitted by 830531
SEIKEN, S J Standardized Nuclear Unit Power Plant System 83/03/22
KEPPLER, J G Region 3, Office of Director COLLINS, J T Region 4, Office of Director 2pp 17725 211 24x Fiche 50-000, 83/03/22, 8303290394

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24x Fiche 50-000, 83/02/24, 8302250505

8303150276 Submits info in response to Generic Ltr 83-01 re operator licensing exam site visits through 850910
CAPONE, D W Union Electric Co 83/03/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 17567 135 24x
Fiche 50-483, 83/03/08, 8303150276

DOCKET STN-50-486 CALLAWAY PLANT, UNIT 2

A Application/construction stage documents & correspondence

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys
KEPPLER, J G Region 3, Office of Director 83/03/03
Commonwealth Edison Co 2pp 17492 014 24x Fiche 50-000, 83/03/03, 8303100364

8303300158 Forwards order revoking CPPR-140, per 820423 request
EISENHUT, D G Division of Licensing 83/03/16 SCHNELL, D F Union Electric Co 3pp 17749 313 24x Fiche 50-486, 83/03/16, 8303300158

--8303300168 Order revoking CPPR-140
EISENHUT, D G Division of Licensing 83/03/16 Union Electric Co 6pp 17749 316 24x Fiche 50-486, 83/03/16, 8303300158

F Security, medical, emergency & fire protection plans

8303210102 Discusses 830224 telcon re incorrect location of plant on 10 & 50 mile emergency planning zone maps Error probably due to incorrect longitude given in plant FSAR site addendum
WHITE, A Union Electric Co 83/02/28 AXELSON, W L Region 3, Office of Director 1p 17630 265 24x Fiche 50-483, 83/02/28, 8303210102

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition Appropriate planning should take place to prevent possible transmission errors
HIND, J A Region 3, Office of Director 83/03/22 Commonwealth Edison Co 2pp 17690 316 24x Fiche 50-000, 83/03/22, 8303240440

J Insurance & indemnity information

8303140308 Forwards Endorsement 13 to NELIA Policy NF-164
NADEL, M Marsh & McLennan, Inc 83/03/07 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 17535 034 24x
Fiche 50-483, 83/03/07, 8303140308

DOCKET STN-50-488 PERKINS NUCLEAR STATION, UNIT 1

H General correspondence

8303300062 Responds to 830302 proposal re closing LPDRs for cancelled or deferred plants No objection to closing LPDRs for submitted plants Other LPDRs will remain open pending resolution of CP status
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/03/18 FELTON, J M Division of Rules and Records 3pp 17751 074 24x Fiche 50-000, 83/03/18, 8303300062

DOCKET STN-50-489 PERKINS NUCLEAR STATION, UNIT 2

H General correspondence

8303300062 Responds to 830302 proposal re closing LPDRs for cancelled or deferred plants No objection to closing LPDRs for submitted plants Other LPDRs will remain open pending resolution of CP status
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/03/18 FELTON, J M Division of Rules and Records 3pp 17751 074 24x Fiche 50-000, 83/03/18, 8303300062

DOCKET STN-50-490 PERKINS NUCLEAR STATION, UNIT 3

H General correspondence

8303300062 Responds to 830302 proposal re closing LPDRs for cancelled or deferred plants No objection to closing LPDRs for submitted plants Other LPDRs will remain open pending resolution of CP status
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/03/18 FELTON, J M Division of Rules and Records 3pp 17751 074 24x Fiche 50-000, 83/03/18, 8303300062

DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24x
Fiche 50-000, 83/02/16, 8302170082

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24x
Fiche 50-000, 83/03/02, 8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12) Svc list encl
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 5lpp 17660 176 24x
Fiche 50-000, 83/03/07, 8303040005

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24x Fiche 50-000, 83/02/24, 8302250505

DOCKET 50-496 MONTAGUE NUCLEAR POWER STATION, UNIT 1

A Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24x
Fiche 50-000, 83/02/16, 8302170082

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24x
Fiche 50-000, 83/03/02, 8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12) Svc list encl
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 5lpp 17660 176 24x
Fiche 50-000, 83/03/07, 8303040005

G Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc
11lpp 17521 001 24X Fiche 50-000,83/02/25,8212060367

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc
117pp 17611 070 24X Fiche 50-000,83/03/11,8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000,83/03/18,8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 121pp 17774 352 24X Fiche 50-000,83/03/21,8212060387

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000,83/02/24,8302250505

DOCKET 50-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24X
Fiche 50-000,83/02/16,8302170082

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X
Fiche 50-000,83/03/02,8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12) Svc list encl
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 51pp 17660 176 24X
Fiche 50-000,83/03/07,8303040005

G Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc
11lpp 17521 001 24X Fiche 50-000,83/02/25,8212060367

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc
117pp 17611 070 24X Fiche 50-000,83/03/11,8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000,83/03/18,8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 121pp 17774 352 24X Fiche 50-000,83/03/21,8212060387

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000,83/02/24,8302250505

DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1

A Application/construction stage documents & correspondence

8303250089 Discusses plans to address potential for flow induced vibration of tubes in Westinghouse Model E preheater type steam generators per NRC 821028 request No addl testing, special startup procedures/instrumentation needed.
GOLDBERG, J H Houston Lighting & Power Co 82/12/21 NOVAK, T M
Assistant Director for Licensing 3pp 17691 137 24X
Fiche 50-498,82/12/21,8303250089

8303250084 Forwards responses to NRC 820204 review Questions 220.06, 220.08, 220.09, 230.01, 230.04, 231.02 & 231.03 re structural engineering & geosciences. Responses will be incorporated into future FSAR amend.
GOLDBERG, J H Houston Lighting & Power Co 82/12/31 NOVAK, T M
Assistant Director for Licensing 50pp 17693 018 24X
Fiche 50-498,82/12/31,8303250084

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24X
Fiche 50-000,83/02/16,8302170082

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X
Fiche 50-000,83/03/02,8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12) Svc list encl
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 51pp 17660 176 24X
Fiche 50-000,83/03/07,8303040005

8303150340 Advises of 830405 meeting w/licensees & major contractors at Dallas/Fort Worth, TX to provide info & guidance re 10CFR50 QA & Tech Spec deviations & discuss decentralization policy. Questions should be submitted in writing by 830321.
COLLINS, J T Region 4, Office of Director 83/03/10 Public Service Co of Colorado 12pp 17562 291 24X
Fiche 50-000,83/03/10,8303150340

8303150358 Advises of 830405 meeting w/licensees & major contractors at Dallas/Fort Worth, TX to provide info & guidance re 10CFR50 QA & Tech Spec deviations & discuss decentralization policy. Questions should be submitted in writing by 830321.
COLLINS, J T Region 4, Office of Director 83/03/11 OPREA, G W
Houston Lighting & Power Co 3pp 17566 247 24X
Fiche 50-498,83/03/11,8303150358

8303310662 Advises that Director of Licensing approval not needed to perform const activities re high voltage direct current terminal facility & connection to plant switchyard, in response to Amend 6 to environ rept & Amend 28 to FSAR.
NOVAK, T M Assistant Director for Licensing 83/03/21 OPREA, G W
Houston Lighting & Power Co 2pp 17780 304 24X
Fiche 50-498,83/03/21,8303310662

F Security, medical, emergency & fire protection plans

8303140251 Advises of required location of emergency operations facility & technical support ctr voice communications equipment per NUREG-0696.
COLLINS, J T Region 4, Office of Director 83/02/24 OPREA, G W
Houston Lighting & Power Co 2pp 17538 333 24X
Fiche 50-498,83/02/24,8303140251

8303290554 Informs that personnel recruiter for private corporation attempted telephone inquiries re security matters. Corporate representative said recruiter unaware that questions being asked involved security matters.
COLLINS, J. T. Region 4, Office of Director 83/03/25 OPREA, G. W. Houston Lighting & Power Co. 2pp. 17724:159 24X
Fiche: 50-498, 83/03/25, 8303290554

G. Adjudicatory correspondence

8303110070 Forwards Director's Decision DD-83-5, denying Citizens Concerned About Nuclear Power, Inc 820804 10CFR2.206 petition to suspend const.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 83/03/03 SINKIN, L. Citizens Concerned About Nuclear Power, Inc. 3pp. 17526:317 24X Fiche: 50-498, 83/03/03, 8303110070

--8303110075 Decision DD-83-5, denying Citizens Concerned About Nuclear Power, Inc 820804 10CFR2.206 petition to suspend const because ov certain alleged design deficiencies described in Quadrex Corp rept.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 83/03/03 7pp. 17526:319 24X Fiche: 50-498, 83/03/03, 8303110070

--8303110079 Notice of issuance of Director's Decision DD-83-5, denying Citizens Concerned About Nuclear Power, Inc 820804 10CFR2.206 petition to suspend const.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 83/03/03 2pp. 17526:326 24X Fiche: 50-498, 83/03/03, 8303110070

8303150394 Sixth set of interrogatories & requests for production of documents Certificate of Svc encl Related correspondence.
GUTTERMAN, A. H. Joint Applicants-South Texas Project GUTTERMAN, A. H. Lowenstein, Newman, Reis, Axelrad & Toll 83/03/10 Citizens Concerned About Nuclear Power, Inc. 9pp. 17561:346 24X
Fiche: 50-498, 83/03/10, 8303150394

8303170283 Motion to conduct prehearing conference in view of info made available to parties in Bechtel Rept EN-619 & IE Repts 82-02 & 82-12, in order to clarify issues, discuss stipulations & set schedule for filing motions Certificate of Svc encl.
NEWMAN, J. R. Houston Lighting & Power Co. NEWMAN, J. R. Lowenstein, Newman, Reis, Axelrad & Toll 83/03/14 Atomic Safety and Licensing Board Panel 4pp. 17606:015 24X Fiche: 50-498, 83/03/14, 8303170283

8303230224 Motion for new contention re util lack of financial qualifications to complete & operate plant safely. PUC of TX denied util rate increase request & City of Austin, TX sued util for refund of investment Certificate of Svc encl.
SINKIN, L. Citizens Concerned About Nuclear Power, Inc. 83/03/18 Commissioners. 59pp. 17665:128 24X Fiche: 50-498, 83/03/18, 8303230224

8303300275 Order extending time until 830509 for Commission to act to review Director's decision.
CHILK, S. J. Office of the Secretary of the Commission 83/03/28 Commissioners. 1p. 17734:362 24X Fiche: 50-498, 83/03/28, 8303300275

8303310335 Seventh set of interrogatories & requests for production of documents Certificate of Svc encl Related correspondence.
GUTTERMAN, A. H. Joint Applicants-South Texas Project GUTTERMAN, A. H. Lowenstein, Newman, Reis, Axelrad & Toll 83/03/28 Citizens Concerned About Nuclear Power, Inc. 8pp. 17755:036 24X
Fiche: 50-498, 83/03/28, 8303310335

K. Utility Final Safety Analysis Report (FSAR) & amends

8303160382 Forwards Amend 30 to FSAR.
GOLDBERG, J. H. Houston Lighting & Power Co. 83/03/11 DENTON, H. Office of Nuclear Reactor Regulation, Director 4pp. 17593:043 24X Fiche: 50-498, 83/03/11, 8303160382

--8303160385 Amend 30 to FSAR.
* Houston Lighting & Power Co. 83/03/11 673pp. 17593:047 24X Fiche: 50-498, 83/03/11, 8303160382

Q. Inspection reports, IE Bulletins & correspondence

8303110355 Board Notification 83-14 forwards followup info on apparent deficiencies in Midland-Ross superstrut matl.
EISENHUT, D. G. Division of Licensing 83/02/18 PALLADINO, N. Commissioners. 24pp. 17546:205 24X Fiche: 50-000, 83/02/18, 8303110355

8303150488 Forwards IE Insp Repts 50-498/83-01 & 50-499/83-01 during Jan 1983. No noncompliance noted.
MADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs 83/02/24 OPREA, G. W. Houston Lighting & Power Co. 2pp. 17560:310 24X Fiche: 50-498, 83/02/24, 8303150488

--8303150491 IE Insp Repts 50-498/83-01 & 50-499/83-01 during Jan 1983. No noncompliance noted. Major areas inspected: RCS welding activities, storage & maint, site tours, structural concrete, transition activities & safety-related fasteners.
HILL, W. M., HUBACEK, W. G. Region 4, Office of Director. BOARDMAN, J. R. Division of Resident, Reactor Project & Engineering Programs 83/02/22 17pp. 17560:312 24X Fiche: 50-498, 83/02/24, 8303150488

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 111pp. 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp. 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp. 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387

S. Reportable occurrences, LERs & related correspondence

8303150560 Revised final deficiency rept re HILTI Kwik-Bolt expansion anchors. Schedule for remaining actions changed due to change in responsibilities of AE from Brown & Root to Bechtel & revised project schedule. Corrective actions listed.
OPREA, G. W. Houston Lighting & Power Co. 83/02/22 COLLINS, J. T. Region 4, Office of Director. 2pp. 17568:012 24X
Fiche: 50-498, 83/02/22, 8303150560

8303180242 First interim deficiency rept re pumps mfg by Hayward-Tyler Pump Co. Initially reported on 830216. Corrective action has not been determined due to preliminary nature of info. Next rept will by submitted 60 days following NRC final rept.
OPREA, G. W. Houston Lighting & Power Co. 83/03/09 COLLINS, J. T. Region 4, Office of Director. 3pp. 17616:171 24X
Fiche: 50-498, 83/03/09, 8303180242

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche: 50-000, 83/02/24, 8302250505

8303040614 Responds to Generic Ltr 83-01 re site visits to conduct operator licensing exams or instructor certification exams. Exams tentatively scheduled for Second Quarter 1984.
GOLDBERG, J. H. Houston Lighting & Power Co. 83/02/28 EISENHUT, D. G. Division of Licensing 2pp. 17426:246 24X Fiche: 50-498, 83/02/28, 8303040614

DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2

A. Application/construction stage documents & correspondence

8303250089 Discusses plans to address potential for flow induced vibration of tubes in Westinghouse Model E preheater type steam generators, per NRC 821028 request. No addl testing, special startup procedures/instrumentation needed.
GOLDBERG, J. H. Houston Lighting & Power Co. 82/12/21 NOVAK, T. M. Assistant Director for Licensing 3pp. 17691:137 24X
Fiche: 50-498, 82/12/21, 8303250089

8303250084 Forwards responses to NRC 820204 review Questions 220.06, 220.08, 220.09, 230.01, 230.04, 231.02 & 231.03 re structural engineering & geosciences. Responses will be incorporated into future FSAR amend.
GOLDBERG, J. H. Houston Lighting & Power Co. 82/12/31 NOVAK, T. M. Assistant Director for Licensing 50pp. 17693:018 24X
Fiche: 50-498, 82/12/31, 8303250084

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X
Fiche: 50-000, 83/02/16, 8302170082

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in BTS on ESF cleanup sys Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X
Fiche: 50-000, 83/02/02, 8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/07 Consolidated Edison Co. of New York, Inc. 51pp 17660:176 24X
Fiche: 50-000, 83/02/07, 8303040005

8303150340 Advises of 830405 meeting w/licensees & major contractors at Dallas/Fort Worth, TX to provide info & guidance re 10CFR50 QA & Tech Spec deviations & discuss decentralization policy. Questions should be submitted in writing by 830321.
COLLINS, J. T. Region 4, Office of Director 83/03/10 Public Service Co. of Colorado 12pp 17562:291 24X
Fiche: 50-000, 83/03/10, 8303150340

8303150358 Advises of 830405 meeting w/licensees & major contractors at Dallas/Fort Worth, TX to provide info & guidance re 10CFR50 QA & Tech Spec deviations & discuss decentralization policy. Questions should be submitted in writing by 830321.
COLLINS, J. T. Region 4, Office of Director 83/03/11 OPREA, G. W. Houston Lighting & Power Co. 3pp 17566:247 24X
Fiche: 50-498, 83/03/11, 8303150358

8303310662 Advises that Director of Licensing approval not needed to perform const activities re high voltage direct current terminal facility & connection to plant switchyard, in response to Amend 6 to environ rept & Amend 28 to FSAR.
NOVAK, T. M. Assistant Director for Licensing 83/03/21 OPREA, G. W. Houston Lighting & Power Co. 2pp 17780:304 24X
Fiche: 50-498, 83/03/21, 8303310662

## F. Security, medical, emergency & fire protection plans

8303140251 Advises of required location of emergency operations facility & technical support ctr voice communications equipment per NUREG-0696.
COLLINS, J. T. Region 4, Office of Director 83/02/24 OPREA, G. W. Houston Lighting & Power Co. 2pp 17538:333 24X
Fiche: 50-498, 83/02/24, 8303140251

8303290554 InForms that personnel recruiter for private corporation attempted telephone inquiries re security matters. Corporate representative said recruiter unaware that questions being asked involved security matters.
COLLINS, J. T. Region 4, Office of Director 83/03/25 OPREA, G. W. Houston Lighting & Power Co. 2pp 17724:159 24X
Fiche: 50-498, 83/03/25, 8303290554

## G. Adjudicatory correspondence

8303110070 Forwards Director's Decision DD-83-5, denying Citizens Concerned About Nuclear Power, Inc 820804 10CFR2.206 petition to suspend const.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 83/03/03 SINKIN, L. Citizens Concerned About Nuclear Power, Inc 3pp 17526:317 24X Fiche: 50-498, 83/03/03, 8303110070

--8303110075 Decision DD-83-5, denying Citizens Concerned About Nuclear Power, Inc 820804 10CFR2.206 petition to suspend const because of certain alleged design deficiencies described in Quadrex Corp rept.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 83/03/03 7pp 17526:319 24X Fiche: 50-498, 83/03/03, 8303110070

--8303110079 Notice of issuance of Director's Decision DD-83-5, denying Citizens Concerned About Nuclear Power, Inc 820804 10CFR2.206 petition to suspend const.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 83/03/03 2pp 17526:326 24X Fiche: 50-498, 83/03/03, 8303110070

8303150394 Sixth set of interrogatories & requests for production of documents. Certificate of Svc encl. Related correspondence.
GUTTERMAN, A. H. Joint Applicants-South Texas Project GUTTERMAN, A. H. Lowenstein, Newman, Reis, Axelrad & Toll 83/03/10 Citizens Concerned About Nuclear Power, Inc 9pp 17561:346 24X
Fiche: 50-498, 83/03/10, 8303150394

8303170283 Motion to conduct prehearing conference in view of info made available to parties in Bechtel Rept EN-619 & IE Repts 82-02 & 82-12, in order to clarify issues, discuss stipulations & set schedule for filing motions. Certificate of Svc encl.
NEWMAN, J. R. Houston Lighting & Power Co. NEWMAN, J. R. Lowenstein, Newman, Reis, Axelrad & Toll 83/03/14 Atomic Safety and Licensing Board Panel 4pp 17606:015 24X Fiche: 50-498, 83/03/14, 8303170283

8303230224 Motion for new contention re util lack of financial qualifications to complete & operate plant safely. PUC of TX denied util rate increase request & City of Austin, TX sued util for refund of investment. Certificate of Svc encl.
SINKIN, L. Citizens Concerned About Nuclear Power, Inc 83/03/18 Commissioners 59pp 17665:128 24X Fiche: 50-498, 83/03/18, 8303230224

8303300275 Order extending time until 830509 for Commission to act to review Director's decision.
CHILK, S. J. Office of the Secretary of the Commission 83/03/28 Commissioners 1p 17734:362 24X Fiche: 50-498, 83/03/28, 8303300275

8303310335 Seventh set of interrogatories & requests for production of documents. Certificate of Svc encl. Related correspondence.
GUTTERMAN, A. H. Joint Applicants-South Texas Project GUTTERMAN, A. H. Lowenstein, Newman, Reis, Axelrad & Toll 83/03/28 Citizens Concerned About Nuclear Power, Inc 8pp 17755:036 24X
Fiche: 50-498, 83/03/28, 8303310335

## H. Utility Final Safety Analysis Report (FSAR) & amends

8303160382 Forwards Amend 30 to FSAR.
GOLDBERG, J. H. Houston Lighting & Power Co. 83/03/11 DENTON, H. Office of Nuclear Reactor Regulation, Director 4pp 17593:043 24X Fiche: 50-498, 83/03/11, 8303160382.

--8303160385 Amend 30 to FSAR.
* Houston Lighting & Power Co. 83/03/11 673pp 17593:047 24X
Fiche: 50-498, 83/03/11, 8303160382.

## Q. Inspection reports, IE Bulletins & correspondence

8303110355 Board Notification 83-14. Forwards followup info on apparent deficiencies in Midland-Ross superstrut matl.
EISENHUT, D. G. Division of Licensing 83/02/18 PALLADINO, N. Commissioners 24pp 17546:205 24X Fiche: 50-000, 83/02/18, 8303110355

8303150488 Forwards IE Insp Repts 50-498/83-01 & 50-499/83-01 during Jan 1983. No noncompliance noted.
MADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs 83/02/24 OPREA, G. W. Houston Lighting & Power Co. 2pp 17560:310 24X Fiche: 50-498, 83/02/24, 8303150488

--8303150491 IE Insp Repts 50-498/83-01 & 50-499/83-01 during Jan 1983. No noncompliance noted. Major areas inspected: RCS welding activities, storage & maint, site tours, structural concrete, transition activities & safety-related fasteners.
HILL, W. M., HUBACEK, W. G. Region 4, Office of Director. BOARDMAN, J. R. Division of Resident, Reactor Project & Engineering Programs 83/02/22 17pp 17560:312 24X Fiche: 50-498, 83/02/24, 8303150488

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11pp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 11pp 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 11pp 24X Fiche: 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12pp 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387

S Reportable Occurrences, LERs & related correspondence

8309130560 Revised Final deficiency rept re HILTI Kwik-Bolt expansion anchors Schedule for remaining actions changed due to change in responsibilities of AE from Brown & Root to Bechtel & revised project schedule Corrective actions listed
OPREA, G W Houston Lighting & Power Co 83/02/22 COLLINS, J T
Region 4, Office of Director 2pp 17568 012 24X
Fiche 50-498, 83/02/22, 8309130560

8303180242 First interim deficiency rept re pumps mfg by Hayward-Tyler Pump Co Initially reported on 830216 Corrective action has not been determined due to preliminary nature of info Next rept will by submitted 60 days following NRC final rept
OPREA, G W Houston Lighting & Power Co 83/03/09 COLLINS, J T
Region 4, Office of Director 3pp 17676 171 24X
Fiche 50-498, 83/03/09, 8303180242

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee," Svc list encl
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000, 83/02/24, 8302250505

8303040614 Responds to Generic Ltr 83-01 re site visits to conduct operator licencing exams or instructor certification exams Exams tentatively scheduled for Second Quarter 1984
GOLDBERG, J H Houston Lighting & Power Co 83/02/28 EISENHUT, D G Division of Licensing 2pp 17426 246 24X Fiche 50-498, 83/02/28, 8303040614

DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2

H General correspondence

8303300062 Responds to 830302 proposal re closing LPDRs for cancelled or deferred plants No objection to closing LPDRs for submitted plants Other LPDRs will remain open pending resolution of CP status
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/03/18 FELTON, J M Division of Rules and Records 3pp 17751 074 24X Fiche 50-000, 83/03/18, 8303300062

DOCKET 50-501 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 3

H General correspondence

8303300064 Responds to 830302 proposal re closing LPDRs for cancelled or deferred plants No objection to closing LPDRs for submitted plants Other LPDRs will remain open pending resolution of CP status
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/03/18 FELTON, J M Division of Rules and Records 3pp 17751 074 24X Fiche 50-000, 83/03/18, 8303300064

DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

8303010109 Notifies of 830315-16 site visit to discuss info needed for environ statement associated w/OL application
KNIGHTON, G Operating Reactors Branch 3 83/02/15 FERGUSON, R L Washington Public Power Supply System 2pp 17347 320 24X
Fiche 50-508, 83/02/15, 8303010109

--8303010115 Notification of 830315-16 site meetings w/applicant to discuss info necessary for environ review Agenda encl
VIETTI, A Licensing Branch 3 83/02/10 KNIGHTON, G W Licensing Branch 3 3pp 17347 327 24X Fiche 50-508, 83/02/15, 8303010115

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 10pp 17492 033 24X
Fiche 50-000, 83/02/16, 8302170082

8303030192 Discusses responses to NRC 820625 questions re use of pipe clamps Results of test program inconclusive Results of effort using stressconn will be available by June 1983
BOUCHEY, G D Washington Public Power Supply System 83/02/25
KNIGHTON, G W Licensing Branch 3 2pp 17410 325 24X
Fiche 50-508, 83/02/25, 8303030192

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X
Fiche 50-000, 83/03/02, 8303020321

8303170009 Notification of 830315 meetings w/util onsite to discuss geology & seismology
VIETTI, A Licensing Branch 3 83/03/04 KNIGHTON, G W Licensing Branch 3 4pp 17624 337 24X Fiche 50-508, 83/03/04, 8303170009

8303230276 Notification of time & location changes for 830315-16 meetings w/util in Hanford, WA to discuss geology & seismology info & observe geology & seismology at selected locations
VIETTI, A Licensing Branch 3 83/03/04 KNIGHTON, G W Licensing Branch 3 4pp 17677 356 24X Fiche 50-508, 83/03/04, 8303230276

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12) Svc list encl
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 5lpp 17660 176 24X
Fiche 50-000, 83/03/07, 8303040005

8303180183 Extends invitation to make opening remarks at 830316 public meeting in Elma, WA to discuss environ areas of concern
KNIGHTON, G W Licensing Branch 3 83/03/08 FREDERICK, R Elma, WA 2pp 17625 344 24X Fiche 50-508, 83/03/08, 8303180183

8303290465 Forwards schedule for Feb 1983 commitments re design criteria in SRP No further change necessary w/exception of FSAR Conformance Review Table 1 8-3
BOUCHEY, G D Washington Public Power Supply System 83/03/23
KNIGHTON, G W Licensing Branch 3 3pp 17722 361 24X
Fiche 50-508, 83/03/23, 8303290465

8303290240 Forwards response to NRC acceptance review questions, per NRS 820820 request Responses will be incorporated in next FSAR amend
BOUCHEY, G D Washington Public Power Supply System 83/03/24
KNIGHTON, G W Licensing Branch 3 10pp 17716 007 24X
Fiche 50-508, 83/03/24, 8303290240

D NRC Draft/Final Environmental Statements, suppls & correspondence

8303010718 Discusses plans for NRC 830315-16 site visit w/federal & state agencies & 830316 public meeting re EIS Meeting agenda encl
KNIGHTON, G W Licensing Branch 3 83/02/16 LEWIS, N D Washington, State of 4pp 17348 304 24X Fiche 50-508, 83/02/16, 8303010718

8303180686 Informs of 830315 site tour & NRC 830316 meeting w/interested public officials in Elma, WA to discuss review process for preparing EIS Project manager should receive notice of plans to attend site tour by 830309
KNIGHTON, G W Licensing Branch 3 83/02/25 ROTTLE, J S Montesano, WA 2pp 17637 014 24X Fiche 50-508, 83/02/25, 8303180686

8303180689 Informs of 830315 site tour & NRC 830316 meeting w/interested public officials in Elma, WA to discuss review process for preparing EIS Project manager should receive notice of plans to attend site tour by 830309
KNIGHTON, G W Licensing Branch 3 83/02/25 FREDERICK, R Elma, WA 2pp 17637 012 24X Fiche 50-508, 83/02/25, 8303180689

8303180692 Informs of 830315 site tour & NRC 830316 meeting w/interested public officials in Elma, WA to discuss review process for preparing EIS Project manager should receive notice of plans to attend site tour by 830309
KNIGHTON, G W Licensing Branch 3 83/02/25 YOUMANS, D Montesano, WA 2pp 17637 010 24X Fiche 50-508, 83/02/25, 8303180692

8303180693 Informs of 830315 site tour & NRC 830316 meeting w/interested public officials in Elma, WA to discuss review process for preparing EIS Project manager should receive notice of plans to attend site tour by 830309
KNIGHTON, G W Licensing Branch 3 83/02/25 RAKOSKI, T McCleary, WA 2pp 17637 266 24X Fiche 50-508, 83/02/25, 8303180693

8303180695 Informs of 830315 site tour & NRC 830316 meeting w/interested public officials in Elma, WA to discuss review process for preparing EIS Project manager should receive notice of plans to attend site tour by 830309
KNIGHTON, G W Licensing Branch 3 83/02/25 JOHNSTON, E Shelton, WA 2pp 17637 264 24X Fiche 50-508, 83/02/25, 8303180695

8303180697 Informs of 830315 site tour & NRC 830316 meeting w/ interested public officials in Elma,WA to discuss review process for preparing EIS.Project manager should receive notice of plans to attend site tour by 830309. KNIGHTON,G W. Licensing Branch 3. 83/02/25. DURNEY,J. Aberdeen, WA. 2pp. 17637:262. 24X Fiche:50-508,83/02/25,8303180697.

8303180698 Informs of 830315 site tour & NRC 830316 meeting w/ interested public officials in Elma,WA to discuss review process for preparing EIS.Project manager should receive notice of plans to attend site tour by 830309. KNIGHTON,G W. Licensing Branch 3. 83/02/25. SKRAMSTAD,E A. Olympia, WA. 2pp. 17637:260. 24X Fiche:50-508,83/02/25,8303180698.

8303210098 Informs of 830315 site tour & NRC 830316 meeting w/ interested public officials in Elma,WA to discuss review process for preparing EIS.Project manager should receive notice of plans to attend site tour by 830309. KNIGHTON,G W. Licensing Branch 3. 83/02/25. BARNER,G. Olympia, WA. 2pp. 17660:126. 24X Fiche:50-508,83/02/25,8303210098.

8303160039 Notifies of 830315-16 site visit to review EIS preparation process associated w/OL application. KNIGHTON,G W. Licensing Branch 3. 83/03/04. LEWIS,N D. Washington, State of. 2pp. 17615:024. 24X Fiche:50-508,83/03/04, 8303160039.

8303160040 Notifies of 830315-16 site visit to review EIS preparation process associated w/OL application. KNIGHTON,G W. Operating Reactors Branch 3. 83/03/04. EVANS,D. Commerce, Dept. of, National Marine Fisheries Service. 3pp. 17613:018. 24X Fiche:50-508,83/03/04,8303160040.

8303160044 Notifies of 830315-16 site visit to review EIS preparation process associated w/OL application. KNIGHTON,G W. Licensing Branch 3. 83/03/04. BENDER,J. Agriculture,Dept of, Research Center. 3pp. 17615:012. 24X Fiche:50-508,83/03/04,8303160044.

8303160047 Notifies of 830315-16 site visit to review EIS preparation process associated w/OL application. KNIGHTON,G W. Licensing Branch 3. 83/03/04. MYSHOC,R J. Interior, Dept. of, Fish & Wildlife Service. 3pp. 17615:004. 24X Fiche:50-508,83/03/04,8303160047.

## Q. Adjudicatory correspondence

8303070119 Petition of Coalition for Safe Power for leave to intervene & request for hearing re OL application.Certificate of Svc encl. ROSOLIE,E. Coalition for Safe Power. 83/02/18. Atomic Safety and Licensing Board Panel. 11pp. 17433:089. 24X Fiche:50-508,83/02/18, 8303070119.

8303070117 Notice of ASLB constitution.MB Margulies,chairman & GO Bright & JH Carpenter,members. COTTER,B F. Atomic Safety and Licensing Board Panel. 83/03/03. 2pp. 17430:353. 24X Fiche:50-508,83/03/03,8303070117.

8303110218 Notice of appearance in proceeding.Certificate of Svc encl. REYNOLDS,W S. ; HARTMAN,S L. Washington Public Power Supply System. REYNOLDS,W S. Debevoise & Liberman. 83/03/09. 4pp. 17518:343. 24X Fiche:50-508,83/03/09,8303110218.

8303110236 Answer opposing Coalition for Safe Power 830222 request for hearing & petition to intervene re OL application.Clear legal interest not established.Good cause not shown for late intervention.Certificate of Svc encl. HARTMAN,S L. Washington Public Power Supply System. HARTMAN,S L. Debevoise & Liberman. 83/03/09. Atomic Safety and Licensing Board Panel. 34pp. 17520:080. 24X Fiche:50-508,83/03/09,8303110236.

8303160597 Response opposing Coalition for Safe Power 830222 request for hearing & petition for lwave to intervene.Coalition failed to prove representation of member w/requisite standing.Certificate of Svc encl. TREBY,B A. Hearing Branch 1. 83/03/14. Atomic Safety and Licensing Board Panel. 16pp. 17587:197. 24X Fiche:50-508,83/03/14, 8303160597.

## K. Utility Final Safety Analysis Report (FSAR) & amends

8301110169 Forwards 1,471 oversize electrical,instrumentation & control drawings & flow diagrams,in accordance w/Reg Guide 1.70, Rev 3 & commitments per FSAR Section 1.8.Amend 2 to FSAR reflects updated rev of Section 1.7.Aperture cards in PDR. BOUCHEY,G D. Washington Public Power Supply System. 83/01/03. KNIGHTON,G W. Licensing Branch 3. 1p. 17023:154. 24X Fiche:50-508,83/01/03,8301110169.

## Q. Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl. DEYOUNG,R C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521:001. 24X Fiche:50-000,83/02/25,8212060367.

8303140248 Responds to NRC 821202 ltr re violations noted in IE Insp Rept 50-508/83-02.Addl info required to assure satisfactory corrective action re hold point procedures.Rept expected by 830404. LEDDICK,R S. Washington Public Power Supply System. 83/03/02. STERNBERG,D M. Division of Resident,Reactor Project & Engineering Programs. 1p. 17538:361. 24X Fiche:50-508,83/03/02,8303140248.

8303110310 Ack receipt of 830211 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-508/82-16. STERNBERG,D M. Division of Resident,Reactor Project & Engineering Programs. 83/03/07. LEDDICK,R S. Washington Public Power Supply System. 1p. 17512:355. 24X Fiche:50-508,83/03/07,8303110310.

--8303110327 Responds to NRC ltr re violations noted in IE Insp Rept 50-508/82-16.Response to violation re electrical penetration design will be submitted by 830401.Reasons why Ebasco has sole responsibility for design changes discussed. LEDDICK,R S. Washington Public Power Supply System. 83/02/11. STERNBERG,D M. Division of Resident,Reactor Project & Engineering Programs. 7pp. 17512:356. 24X Fiche:50-508,83/03/07,8303110310.

8303110376 Ack receipt of 830211 ltr informing NRC of steps taken to correct violations noted in IE insp rept. STERNBERG,D M. Division of Resident,Reactor Project & Engineering Programs. 83/03/07. LEDDICK,R S. Washington Public Power Supply System. 1p. 17512:328. 24X Fiche:50-508,83/03/07,8303110376.

--8303110379 Responds to NRC 830117 ltr re violations noted in IE insp rept.Corrective actions:repair plan identifying grinding & welding,documentation of repair work & supply sys verification of work will be provided by Jul 1983. LEDDICK,R S. Washington Public Power Supply System. 83/02/11. STERNBERG,D M. Division of Resident,Reactor Project & Engineering Programs. 2pp. 17512:329. 24X Fiche:50-508,83/03/07,8303110376.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl. DEYOUNG,R C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche:50-000,83/03/11,8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche:50-000,83/03/18,8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche:50-000,83/03/21,8212060387.

## S. Reportable occurrences, LERs & related correspondence

8303140483 Final deficiency rept re safety injection tank safe-end indications (D/N 23).All linear indications found in safe-end-to-nozzle welds of safety injection tanks 3 & 4 removed & rewelded per ASME Section XI plan. LEDDICK,R S. Washington Public Power Supply System. 83/03/02. STERNBERG,D M. Division of Resident,Reactor Project & Engineering Programs. 3pp. 17541:235. 24X Fiche:50-508,83/03/02,8303140483.

8303110298 Forwards final deficiency rept re safety injection tanks - safe-end indications. LEDDICK,R S. Washington Public Power Supply System. 83/03/07. NRC - No Detailed Affiliation Given. 1p. 17519:359. 24X Fiche:50-508,83/03/07,8303110298.

--8303110306 Final deficiency rept re safety injection tanks - safe-end indications.All linear indications in safe-end-to-nozzle-welds in safety injection tanks 3 & 4 removed & rewelded per ASME Section XI plan.Final radiographs verified repairs. LEDDICK,R S. Washington Public Power Supply System. 83/03/02. Region 5, Office of Director. 1p. 17519:360. 24X Fiche:50-508,83/03/07,8303110298.

8303220157 Final deficiency rept re failure of structural welds to meet AWS min weld size requirements. Initially reported on 821124. Condition not reportable per 10CFR50.55(e) based on satisfactory completion of qualification testing. LEDDICK, R. S. Washington Public Power Supply System. 83/03/14. STERNBERG, D. M. Region 5, Office of Director. 3pp. 17657:167. 24X. Fiche: 50-508. 83/03/14. 8303220157.

8303280001 Forwards 830314 final deficiency rept re failure to meet min weld size requirements. LEDDICK, R. S. Washington Public Power Supply System. 83/03/17. NRC - No Detailed Affiliation Given. 1p. 17707:351. 24X. Fiche: 50-508. 83/03/17. 8303280001.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X. Fiche: 50-000. 83/02/24. 8302250505.

8303090172 Provides formal notification re schedule for operator licensing exams, per 830111 Generic Ltr 83-01. BOUCHEY, G. D. Washington Public Power Supply System. 83/03/04. EISENHUT, D. G. Division of Licensing. 2pp. 17471:325. 24X. Fiche: 50-397. 83/03/04. 8303090172.

DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5

K. Utility Final Safety Analysis Report (FSAR) & amends

8301110169 Forwards 1:471 oversize e.ectrical, instrumentation & control drawings & flow diagrams, in accordance w/Reg Guide 1.70, Rev 3 & commitments per FSAR Section 1.8. Amend 2 to FSAR reflects updated rev of Section 1.7. Aperture cards in PDR. BOUCHEY, G. D. Washington Public Power Supply System. 83/01/03. KNIGHTON, G. W. Licensing Branch 3. 1p. 17023:154. 24X. Fiche: 50-508. 83/01/03. 8301110169.

DOCKET 50-510 BLUE HILLS STATION, UNIT 1

H. General correspondence

8303300062 Responds to 830302 proposal re closing LPDRs for cancelled or deferred plants. No objection to closing LPDRs for submitted plants. Other LPDRs will remain open pending resolution of CP status. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 83/03/18. FELTON, J. M. Division of Rules and Records. 3pp. 17751:074. 24X. Fiche: 50-000. 83/03/18. 8303300062.

DOCKET 50-511 BLUE HILLS STATION, UNIT 2

H. General correspondence

8303300062 Responds to 830302 proposal re closing LPDRs for cancelled or deferred plants. No objection to closing LPDRs for submitted plants. Other LPDRs will remain open pending resolution of CP status. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 83/03/18. FELTON, J. M. Division of Rules and Records. 3pp. 17751:074. 24X. Fiche: 50-000. 83/03/18. 8303300062.

DOCKET 50-513 WPPSS NUCLEAR PROJECT, UNIT 4

S. Reportable occurrences, LERs & related correspondence

8303010617 Interim deficiency rept re generic problems w/ASCO NP-1 valves in nuclear applications including fire protection sys. Initially reported on 830120. Process for establishing position for recommended fix continuing. RODT, R. W. Washington Public Power Supply System. 83/02/15. STERNBERG, D. M. Division of Resident Reactor Project & Engineering Programs. 4pp. 17336:107. 24X. Fiche: 50-460. 83/02/15. 8303010617.

DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X. Fiche: 50-000. 83/02/16. 8302170082.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X. Fiche: 50-000. 83/03/02. 8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl. EISENHUT, D. G. Division of Licensing. 83/03/07. Consolidated Edison Co. of New York, Inc. 5lpp. 17e60.176. 24X. Fiche: 50-000. 83/03/07. 8303040005.

Q. Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 111pp. 17521:001. 24X. Fiche: 50-000. 83/02/25. 8212060367.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X. Fiche: 50-000. 83/03/11. 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X. Fiche: 50-000. 83/03/18. 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X. Fiche: 50-000. 83/03/21. 8212060387.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X. Fiche: 50-000. 83/02/24. 8302250505.

DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X. Fiche: 50-000. 83/02/16. 8302170082.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/03/02. Consolidated Edison Co. of New York, Inc. 17pp. 17700:303. 24X. Fiche: 50-000. 83/03/02. 8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 5lpp 17660 176 24X
Fiche 50-000, 83/03/07, 8303040005

G. Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 11lpp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc 117pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 121pp 17774 352 24X Fiche 50-000, 83/03/21, 8212060387

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000, 83/02/24, 8302250505

DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

8303010369 Reiterates 830121 request for CP extension until 870901 to permit final decision re future of nuclear units based on load growth/demand. Deferral plan details to be submitted by 830506.
MILLS, L. M. Tennessee Valley Authority 83/02/24 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17345 126 24X Fiche 50-000, 83/02/24, 8303010369

8303210525 Advises that AITS F02700201 re incorrect spec of RHR discharge line orifice diameter is closed based on discontinued work at facilities. All CF Braun records in GE storage.
POTAPOVS, U. Division of Vendor & Technical Programs 83/03/17
LEWIS, R. C. Division of Project & Resident Programs 1p 17632 285 24X Fiche 50-518, 83/03/17, 8303210525

S. Reportable occurrences, LERs & related correspondence

8303210679 First interim deficiency rept re transfer switches to auxiliary feedwater w/nondivisional power. Initially reported on 830202. Control power to pressure switches may be provided from standby diesel generators. Next rept expected by 830627.
MILLS, L. M. Tennessee Valley Authority 83/03/02 O'REILLY, J. P. Region 2, Office of Director 3pp 17635 062 24X
Fiche 50-000, 83/03/02, 8303210679

8303240525 Final deficiency rept re quality engineering branch unauthorized review of purchase requisitions. Initially reported on 820120. Procedure EN DES-EP 5.01 revised to incorporate procurement specs requiring correct insp.
MILLS, L. M. Tennessee Valley Authority 83/03/17 O'REILLY, J. P. Region 2, Office of Director 3pp 17684 289 24X
Fiche 50-000, 83/03/17, 8303240525

8303240406 Final deficiency rept re regional quality engineering branch insp ofc manpower. Initially reported on 820120. QA training completed 830318. Technical training will continue.
MILLS, L. M. Tennessee Valley Authority 83/03/18 O'REILLY, J. P. Region 2, Office of Director 3pp 17679 012 24X
Fiche 50-000, 83/03/18, 8303240406

DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8303250038 Forwards proposed cancellation plans for facilities. Requests withdrawal of CPPR-151 & CPPR-153. W/one oversize drawing. Aperture card is available in PDR.
MILLS, L. M. Tennessee Valley Authority 83/03/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 12pp 17692 071 24X Fiche 50-519, 83/03/22, 8303250038

DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3

A. Application/construction stage documents & correspondence

8303010369 Reiterates 830121 request for CP extension until 870901 to permit final decision re future of nuclear units based on load growth/demand. Deferral plan details to be submitted by 830506.
MILLS, L. M. Tennessee Valley Authority 83/02/24 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17345 126 24X Fiche 50-000, 83/02/24, 8303010369

S. Reportable occurrences, LERs & related correspondence

8303210679 First interim deficiency rept re transfer switches to auxiliary feedwater w/nondivisional power. Initially reported on 830202. Control power to pressure switches may be provided from standby diesel generators. Next rept expected by 830627.
MILLS, L. M. Tennessee Valley Authority 83/03/02 O'REILLY, J. P. Region 2, Office of Director 3pp 17635 062 24X
Fiche 50-000, 83/03/02, 8303210679

8303240525 Final deficiency rept re quality engineering branch unauthorized review of purchase requisitions. Initially reported on 820120. Procedure EN DES-EP 5.01 revised to incorporate procurement specs requiring correct insp.
MILLS, L. M. Tennessee Valley Authority 83/03/17 O'REILLY, J. P. Region 2, Office of Director 3pp 17684 289 24X
Fiche 50-000, 83/03/17, 8303240525

8303240406 Final deficiency rept re regional quality engineering branch insp ofc manpower. Initially reported on 820120. QA training completed 830318. Technical training will continue.
MILLS, L. M. Tennessee Valley Authority 83/03/18 O'REILLY, J. P. Region 2, Office of Director 3pp 17679 012 24X
Fiche 50-000, 83/03/18, 8303240406

DOCKET STN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4

A. Application/construction stage documents & correspondence

8303250038 Forwards proposed cancellation plans for facilities. Requests withdrawal of CPPR-151 & CPPR-153. W/one oversize drawing. Aperture card is available in PDR.
MILLS, L. M. Tennessee Valley Authority 83/03/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 12pp 17692 071 24X Fiche 50-519, 83/03/22, 8303250038

DOCKET 50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24X
Fiche 50-000, 83/02/16, 8302170082

8303010308 Commits to conduct proposed geol investigations of May Junction monocline similar to investigations identified as Phases III & IV in util 820804 ltr.
MYERS, R. V. Puget Sound Power & Light Co 83/02/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17345 169 24X Fiche 50-522, 83/02/18, 8303010308

8303310453 Partial response to FOIA request for six categories of documents. Forwards App A documents identified as Items 1, 3, 4, 5 & 6 of request. Search for documents re Item 2 of request continuing.
FELTON, J. M. Division of Rules and Records 83/02/24 HIATT, S. L. Ohio Citizens for Responsible Energy 2pp 17804 132 24X
Fiche 50-000, 83/02/24, 8303310453

--8303310481 Discusses MARCH analysis of hydrogen burn during degraded core accidents for facilities. Detailed comparisons of facility design parameters w/GESSAR & Grand Gulf encl.
YANG, J. W. Brookhaven National Laboratory 82/09/27 PRATT, W. T. Brookhaven National Laboratory 30pp 17806:130 24X
Fiche: 50-000, 83/02/24, 8303310453.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303290135 Responds to ACRS 830216 rept re applications for CP. Review of recommendation will be submitted in SER suppl scheduled to be issued in Apr 1983.
GOODWIN, E. F. Technical Support Branch 83/03/17 FRALEY, R. ACRS - Advisory Committee on Reactor Safeguards. 1p 17727:347 24X
Fiche: 50-522, 83/03/17, 8303290135.

--8302250124 Summarizes 274th ACRS meeting on 830210-12 re CP application. If due consideration given to matters noted, project can be constructed w/reasonable assurance that operation would not present risk to public health & safety.
RAY, J. J. ACRS - Advisory Committee on Reactor Safeguards. 83/02/16 PALLADINO, N. J. Commissioners 5pp 66643:358 24X
Fiche: 50-522, 83/03/17, 8303290135.

D. NRC Draft/Final Environmental Statements: suppls & correspondence

8303180146 Grants 830204 request for delay in issuance of FES until after Northwest Power Planning Council issues final regional conservation & electric power plan.
EISENHUT, D. G. Division of Licensing 83/03/11 MYERS, R. V. Puget Sound Power & Light Co. 3pp 17626:014 24X Fiche: 50-522, 83/03/11, 8303180146.

G. Adjudicatory correspondence

8303170443 Advises that time for Commission to review ALAB-712 expired. Commission declined review. Decision became final agency action on 830314.
CHILK, S. J. Office of the Secretary of the Commission 83/03/14 Atomic Safety and Licensing Board Panel 1p 17609:203 24X
Fiche: 50-522, 83/03/14, 8303170443.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8303180663 Comments on questions re site geology & seismology raised at ACRS 830124-25 subcommittee meeting. Addl drilling proposed by NRC should be designed to confirm present interpretations of May Junction monocline.
THOMPSON, G. A. Affiliation Unknown THOMPSON, G. A. ACRS - Advisory Committee on Reactor Safeguards 83/01/25 MARK, C. ACRS - Advisory Committee on Reactor Safeguards 1p 17637:124 24X
Fiche: 50-522, 83/01/25, 8303180663.

8303210149 Comments on applicant QA policy presented at recent meeting. Applicants, w/assistance of contractors, appear well prepared for const.
ZUDANS, Z. Franklin Institute/Franklin Research Center ZUDANS, Z. ACRS - Advisory Committee on Reactor Safeguards 83/01/31.
CAPPUCCI, A. J. ACRS - Advisory Committee on Reactor Safeguards 2pp 17660:174 24X Fiche: 50-522, 83/01/31, 8303210149.

8303030768 Forwards ACRS 830216 ltr re review of application for CP.
ADENSAM, E. G. Licensing Branch 4 83/02/23 MYERS, R. V. Puget Sound Power & Light Co. 2pp 17364:001 24X Fiche: 50-522, 83/02/23, 8303030768.

Q. Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11lpp 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp 17774:352 24X Fiche: 50-000, 83/03/21, 8212060387.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp 24X Fiche: 50-000, 83/02/24, 8302250505.

DOCKET 50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. J. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:073 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303010308 Commits to conduct proposed addl investigations of May Junction monocline similar to investigations identified as Phases III & IV in util 820804 ltr.
MYERS, R. V. Puget Sound Power & Light Co. 83/02/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17345:169 24X Fiche: 50-522, 83/02/18, 8303010308.

8303310453 Partial response to FOIA request for six categories of documents. Forwards App A documents identified as Items 1, 3, 4, 5 & 6 of request. Search for documents re Item 2 of request continuing.
FELTON, J. M. Division of Rules and Records 83/02/24 HIATT, S. L. Ohio Citizens for Responsible Energy 2pp 17804:132 24X
Fiche: 50-000, 83/02/24, 8303310453.

--8303310481 Discusses MARCH analysis of hydrogen burn during degraded core accidents for facilities. Detailed comparisons of facility design parameters w/GESSAR & Grand Gulf encl.
YANG, J. W. Brookhaven National Laboratory 82/09/27 PRATT, W. T. Brookhaven National Laboratory 30pp 17806:130 24X
Fiche: 50-000, 83/02/24, 8303310453.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5lpp 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303290135 Responds to ACRS 830216 rept re applications for CP. Review of recommendation will be submitted in SER suppl scheduled to be issued in Apr 1983.
GOODWIN, E. F. Technical Support Branch 83/03/17 FRALEY, R. ACRS - Advisory Committee on Reactor Safeguards. 1p 17727:347 24X
Fiche: 50-522, 83/03/17, 8303290135.

--8302250124 Summarizes 274th ACRS meeting on 830210-12 re CP application. If due consideration given to matters noted, project can be constructed w/reasonable assurance that operation would not present risk to public health & safety.
RAY, J. J. ACRS - Advisory Committee on Reactor Safeguards. 83/02/16 PALLADINO, N. J. Commissioners 5pp 66643:358 24X
Fiche: 50-522, 83/03/17, 8303290135.

D. NRC Draft/Final Environmental Statements: suppls & correspondence

8303180146 Grants 830204 request for delay in issuance of FES until after Northwest Power Planning Council issues final regional conservation & electric power plan.
EISENHUT, D G Division of Licensing 83/03/11 MYERS, R V Puget Sound Power & Light Co 3pp 17626 014 24X Fiche 50-522, 83/03/11, 8303180146

G. Adjudicatory correspondence

8303170443 Advises that time for Commission to review ALAB-712 expired Commission declined review Decision became final agency action on 830314.
CHILK, S J Office of the Secretary of the Commission 83/03/14
Atomic Safety and Licensing Board Panel 1p 17609 203 24X
Fiche 50-522, 83/03/14, 8303170443

O. Advisory Committee on Reactor Safeguards reports & correspondence

8303180663 Comments on questions re site geology & seismology raised at ACRS 830124-25 subcommittee meeting Addl drilling proposed by NRC should be designed to confirm present interpretations of May Junction monocline.
THOMPSON, G A Affiliation Unknown THOMPSON, G A ACRS - Advisory Committee on Reactor Safeguards 83/01/25 MARK, C ACRS - Advisory Committee on Reactor Safeguards 1p 17637 124 24X
Fiche 50-522, 83/01/25, 8303180663

8303210149 Comments on applicant QA policy presented at recent meeting Applicants, w/assistance of contractors, appear well prepared for const.
ZUDANS, Z Franklin Institute/Franklin Research Center ZUDANS, Z
ACRS - Advisory Committee on Reactor Safeguards 83/01/31
CAPPUCCI, A J ACRS - Advisory Committee on Reactor Safeguards 2pp 17660 174 24X Fiche 50-522, 83/01/31, 8303210149

8303030768 Forwards ACRS 830216 ltr re review of application for CP.
ADENSAM, E G Licensing Branch 4 83/02/23 MYERS, R V Puget Sound Power & Light Co 2pp 17364 001 24X Fiche 50-522, 83/02/23, 8303030768

Q. Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 111pp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 117pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp 17774 352 24X Fiche 50-000, 83/03/21, 8212060387

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualification Statement - Licensee." Svc list encl.
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp 24X Fiche 50-000, 83/02/24, 8302250505

DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

8303070040 Forwards responses to request for addl info re PRA for UHS, per 821122 request.
VAN BRUNT, E E Arizona Public Service Co. 83/01/31 KNIGHTON, G
Licensing Branch 3 43pp 17434 209 24X Fiche 50-528, 83/01/31, 8303070040

8303070058 Forwards "Pressurizer Safety Valve Discharge Piping Evaluation Rept," as final response to NUREG-0737, Item II.2.1. Rept presents plant-specific application of C-E generic program.
VAN BRUNT, E E Arizona Public Service Co. 83/01/31 KNIGHTON, G
Licensing Branch 3 3pp 17435 349 24X Fiche 50-528, 83/01/31, 8303070058

--8303070070 "Pressurizer Safety Valve Discharge Piping Evaluation Rept."
* Combustion Engineering, Inc. 83/01/31 107pp 17435 352 24X
Fiche 50-528, 83/01/31, 8303070058

8303010706 Requests info for evaluation of potential missile hazards resulting from fan blade assembly failure. Response requested by 830225.
KNIGHTON, G W Licensing Branch 3 83/02/04 VAN BRUNT, E E
Arizona Public Service Co. 2pp 17348 322 24X
Fiche 50-528, 83/02/04, 8303010706

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492 033 24X
Fiche 50-000, 83/02/16, 8302170082

8303030747 Board Notification 83-13 forwards EG&G draft rept, "Identification & Ranking of Nuclear Plant Structures, Sys & Components & Graded QA Guidelines."
EISENHUT, D G Division of Licensing 83/02/17 PALLADINO, N
Commissioners 24pp 17364 037 24X Fiche 50-000, 83/02/17, 8303030747

8303030710 Board Notification 83-17 forwards JH Conran 830209 affidavit re changes to previous testimony on Unresolved Safety Issue A-17, "Sys Interaction in Nuclear Power Plants."
EISENHUT, D G Division of Licensing 83/02/18 PALLADINO, N J
Commissioners 6pp 17363 317 24X Fiche 50-000, 83/02/18, 8303030710

8303090194 Forwards point-by-point comparison of special lifting devices against ANSI 14.6 & NUREG-0612 requirements, per 821118 commitment.
VAN BRUNT, E E Arizona Public Service Co. 83/02/23 KNIGHTON, G
Licensing Branch 3 8pp 17472 292 24X Fiche 50-528, 83/02/23, 8303090194

8303140589 Requests certification by util chief executive officer or designee that plant designed, constructed & tested per FSAR & other licensing commitments. Certification should be provided under oath or affirmation.
EISENHUT, D G Division of Licensing 83/02/24 VAN BRUNT, E E
Arizona Public Service Co. 2pp 17548 330 24X
Fiche 50-528, 83/02/24, 8303140589

8303040452 Summarizes 821020 meeting w/NRC in Bethesda, MD re removal of pipe whip restraints. Listed info will be provided to NRC by 830331.
VAN BRUNT, E E Arizona Public Service Co. 83/02/25 KNIGHTON, G
Licensing Branch 3 2pp 17368 008 24X Fiche 50-528, 83/02/25, 8303040452

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700 303 24X
Fiche 50-000, 83/03/02, 8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp 17660 176 24X
Fiche 50-000, 83/03/07, 8303040005

8303180442 Notification of 830309 meeting w/util, Bechtel & C-E in Bethesda, MD to discuss NRC comments on environ qualification rept.
LICITRA, E A Licensing Branch 3 83/03/08 KNIGHTON, G W
Licensing Branch 3 3pp 17640 263 24X Fiche 50-528, 83/03/08, 8303180442

8303230330 Submits addl guidance re submittal of info to complete review of environ qualification of safety-related mechanical equipment located in harsh environ.
KNIGHTON, G W Licensing Branch 3 83/03/08 VAN BRUNT, E E
Arizona Public Service Co. 3pp 17675 057 24X
Fiche 50-528, 83/03/08, 8303230330

8303230383 Summary of 830309 meeting w/applicant in Bethesda, MD re NRC comments on environ qualification rept. Add'l info required to perform site audit.
LICITRA, E. A. Licensing Branch 3 83/03/14 Licensing Branch 3
4pp. 17675:258 24X Fiche: 50-528, 83/03/14, 8303230383.

8303290737 Forwards request for addl info needed to complete review of environ qualification rept. Info requested prior to Apr 1983 site audit.
KNIGHTON, G. W. Licensing Branch 3 83/03/14 VAN BRUNT, E. E. Arizona Public Service Co. 5pp. 17748:039 24X
Fiche: 50-528, 83/03/14, 8303290737.

8303290667 Board Notification 83-31 forwards AZ Public Svc Co evaluation concluding that PORVs not warranted for Palo Verde NRC review of util evaluation incomplete.
EISENHUT, D. G. Division of Licensing 83/03/21 PALLADINO, N. J., ROBERTS, T. M., ASSELSTINE, J. K. Commissioners 9pp. 17745:135 24X
Fiche: 50-000, 83/03/21, 8303290667.

--8303110307 Comments on util 821103 ltr re evaluation on safety effects & operational flexibility possibly resulting from installation of pressurizer PORV. Evaluation of info in ref ltr not yet complete.
MATTSON, R. J. Division of Systems Integration (post 811005) 83/02/25 EISENHUT, D. Division of Licensing 2pp. 66680:030 24X Fiche: 50-000, 83/03/21, 8303290667.

8303280137 Comments on Board Notification 83-38 re failure of GE AK-2 reactor trip breakers. Info may affect NRC conclusions re probability/corrective measures for transients w/o scram events (Unresolved Safety Issue A-9).
EISENHUT, D. G. Division of Licensing 83/03/22 PALLADINO, N. Commissioners 20pp. 17709:310 24X Fiche: 50-000, 83/03/22, 8303280137.

8303280168 Forwards revs to Table 3.2-1 of FSAR re applicability of 10CFR50 App. B to GA class column. Revs replace footnote (e).
VAN BRUNT, E. E. Arizona Public Service Co. 83/03/22 KNIGHTON, G. Licensing Branch 3 17pp. 17709:237 24X Fiche: 50-528, 83/03/22, 8303280168.

8303300510 Notification of 830406-08 meetings w/util & Bechtel in Phoenix, AZ to conduct site audit of power sys. Agenda encl.
LICITRA, E. A. Licensing Branch 3 83/03/22 KNIGHTON, G. W. Licensing Branch 3 5pp. 17748:266 24X Fiche: 50-528, 83/03/22, 8303300510.

8303290490 Confirms that M-S-R Public Power Agency (M-S-R) should not be considered as applicant for OL per Amend 5 to CPPR-141, 142 & 143. Proposed transfer of ownership interest from El Paso Electric Co to M-S-R will not be consummated.
VAN BRUNT, E. E. Arizona Public Service Co. 83/03/24 KNIGHTON, G. Licensing Branch 3 1p. 17725:031 24X Fiche: 50-528, 83/03/24, 8303290490.

8303300187 Summary of 830215-17 seismic qualification audit meeting re equipment including both NSSS & balance of plant scope.
LICITRA, E. A. Licensing Branch 3 83/03/24 Licensing Branch 3
7pp. 17754:336 24X Fiche: 50-528, 83/03/24, 8303300187.

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303100345 Forwards proprietary & nonproprietary repts on core protection calculations & control element assembly calculators per SER, NUREG-0857. Affidavit for withholding per 10CFR2.790 encl. Proprietary repts withheld (ref 10CFR2.790).
VAN BRUNT, E. E. Arizona Public Service Co. 83/03/03 KNIGHTON, G. Licensing Branch 3 7pp. 17488:146 24X Fiche: 50-528, 83/03/03, 8303100345.

--8303100349 "Core Protection Calculation & Control Element Assembly Calculator Sys Phase I Software Verification Test Rept." Proprietary info deleted.
* Combustion Engineering, Inc. CEN-217(V)-NP R00. 83/01/31
21pp. 17488:153 24X Fiche: 50-528, 83/03/03, 8303100345.

--8303100353 "Core Protection Calculation & Control Element Assembly Calculator Sys Phase II Software Verification Test Rept." Proprietary info deleted.
* Combustion Engineering, Inc. CEN-219(V)-NP R00. 83/01/31
20pp. 17488:173 24X Fiche: 50-528, 83/03/03, 8303100345.

--8303100356 "Core Protection Calculation & Control Element Assembly Calculator Data Base Document." Proprietary info deleted.
* Combustion Engineering, Inc. CEN-226(V)-NP R00. 83/01/31
71pp. 17488:200 24X Fiche: 50-528, 83/03/03, 8303100345.

8303170114 Forwards discussion of TMI & IE equipment qualification items requiring relief from schedular requirements, per 821217 meeting. NUREG-0737, Items II.D.3, I.D.1, II.F.1.3, II.B.3 & II.F.2 discussed per SER (NUREG-0857).
VAN BRUNT, E. E. Arizona Public Service Co. 83/03/14 KNIGHTON, G. Licensing Branch 3 11pp. 17609:147 24X Fiche: 50-528, 83/03/14, 8303170114.

8303310657 Forwards SER Suppl 4 W/o encl.
KNIGHTON, G. W. Licensing Branch 3 83/03/21 VAN BRUNT, E. E. Arizona Public Service Co. 2pp. 17780:306 24X
Fiche: 50-528, 83/03/21, 8303310657.

8303300463 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF PALO VERDE NUCLEAR GENERATING STATION, UNITS 1, 2 AND 3. Docket Nos. STN 50-528, STN 50-529 And STN 50-530 (Arizona Public Service Company, et al.)
* Office of Nuclear Reactor Regulation, Director NUREG-0857 S04 83/03/31 45pp. 17763:304 24X Fiche: 50-528, 83/03/31, 8303300463.

F. Security, medical, emergency & fire protection plans

8303180355 Notification of 830308 meeting w/util at site to perform confirmatory evaluation of security program.
LICITRA, E. A. Licensing Branch 3 83/03/01 KNIGHTON, G. W. Licensing Branch 3 2pp. 17640:275 24X Fiche: 50-528, 83/03/01, 8303180355.

8303140546 Forwards SALP data package for Jul 1981 - Feb 1983. Draft performance analysis for each functional area requested by 830318. Responsible individuals for performance analyses listed. SALP Board will convene on 830413.
STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs 83/03/08 YOUNG, T. Region 5, Office of Director 2pp.
17541:020 24X Fiche: 50-528, 83/03/08, 8303140546.

--8303140555 SALP data package for Jul 1981 - Feb 1983, including excerpts of NRC Manual Chapter 0516, summaries of licensee activities & insps, enforcement actions, 10CFR50.55(e) repts & other pertinent data. Results to be provided after 830413 meeting.
* Region 5, Office of Director 83/04/30 21pp. 17541:022 24X
Fiche: 50-528, 83/03/08, 8303140546.

8303300674 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 83/03/28 Document Management Branch 1p. 17770:267 24X Fiche: 50-528, 83/03/28, 8303300674.

--8303300678 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EPIP-14B re dose assessment & Rev 0 to Procedures EPIP-01 through EPIP-14A & EPIP-15 through EPIP-55.
VAN BRUNT, E. E. Arizona Public Service Co. 83/02/23 Licensing Branch 3 2pp. 17770:268 24X Fiche: 50-528, 83/03/28, 8303300674.

--8303300684 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP-14B, "Dose Assessment" & Rev 0 to Procedures EPIP-01 through EPIP-14A & EPIP-15 through EPIP-55. Revised index encl.
LUCIA, B. Arizona Public Service Co. 83/01/26 584pp. 17770:270 24X Fiche: 50-528, 83/03/28, 8303300674.

G. Adjudicatory correspondence

8303100268 Response in opposition to PL Hourihan 830323 motion for leave to file response to West Valley Agricultural Protection Council 830202 motion for ruling on contentions. No good cause shown for late filing. Certificate of Svc encl.
CRAWFORD, V. A. Joint Applicants-Palo Verde. CRAWFORD, V. A. Snell & Wilmer 83/03/07 Atomic Safety and Licensing Board Panel 25pp.
17489:315 24X Fiche: 50-528, 83/03/07, 8303100268.

8303140462 Forwards stipulation & proposed order re discovery. Certificate of Svc encl.
PLATT, W. E. Snell & Wilmer 83/03/09 LAZO, R. M. Atomic Safety and Licensing Board Panel 4pp. 17540:347 24X Fiche: 50-528, 83/03/09, 8303140462.

--8303140472 Stipulation agreeing to encl proposed order re discovery, subj to acceptability by ASLB & to right to seek mods of proposed order.
DEWEY, L. S. Hearing Branch 3. BERLIN, K. West Valley Agricultural Protection Council, Inc. PLATT, W. E. Joint Applicants-Palo Verde.
83/03/09 7pp. 17540:351 24X Fiche: 50-528, 83/03/09, 8303140462.

8303220257 First set of nonuniform interrogatories. Certificate of Svc encl.
CRAWFORD, V. A. Joint Applicants-Palo Verde. CRAWFORD, V. A. Snell & Wilmer 83/03/15 West Valley Agricultural Protection Council, Inc. 124pp. 17657:311 24X Fiche: 50-528, 83/03/15, 8303220257.

8303240398 Response opposing NRC & Joint Applicants motions to strike PL Hourihan motion for leave to file response to West Valley Agricultural Protection Council, Inc motion for ruling on contentions Certificate of Svc encl.
BERNABEI, L. Hourihan, P. BERNABEI, L. Government Acc ntability Project 83/03/20 tomic Safety and Licensing Boa Panel 9pp
17679:015 24X Fiche 50-528,83/03/20,8303240398

8303300283 Order extending time until 830404 for Commission to act to review ALAB-713.
CHILK, S J. Office of the Secretary of the Commission 83/03/28
Commissioners 1p 17734:283 24X Fiche 50-528,83/03/28,
8303300283

Q. Inspection reports, IE Bulletins & correspondence

8303110244 Forwards signature & summary pages for IE Investigation Rept 5-82-006, conducted on 820716-0907, re allegations of faulty post-weld heat treatment on piping.
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 83/02/18 VAN BRUNT, E E Arizona Public Service Co 1p
17520:065 24X Fiche 50-528,83/02/18,8303110244

--8303110250 IE Investigation Rept 5-82-006 on 820616-0907 Major areas investigated allegations re faulty post-weld heat treatment on piping.
SHACKLETON, D C Region 5, Office of Director FITZGERALD, J A
Office of Investigation 83/01/31 2pp 17520:066 24X
Fiche 50-528,83/02/18,8303110244

8303110355 Board Notification 83-14 forwards followup info on apparent deficiencies in Midland-Ross superstrut matl.
EISENHUT, D G Division of Licensing 83/02/18 PALLADINO, N
Commissioners 24pp 17546:205 24X Fiche 50-000,83/02/18,
8303110355

8303150497 Forwards IE Insp Repts 50-528/83-04 & 50-529/83-02 on 830124-0218 No noncompliance noted.
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 83/02/23 ANDOGNINI, G C Arizona Public Service Co
2pp 17560:341 24X Fiche 50-528,83/02/23,8303150497

--8303150506 IE Insp Repts 50-528/83-04 & 50-529/83-02 on 830124-0218 No noncompliance noted Major areas inspected startup testing, maint, fuel receipt preparations & sys releases.
FIORELLI, G , JOHNSTON, G Region 5, Office of Director YOUNG, T
Division of Resident, Reactor Project & Engineering Programs
83/02/23 5pp 17560:343 24X Fiche 50-528,83/02/23,8303150497

8303040335 Forwards IE Insp Repts 50-528/82-37, 50-529/82-15 & 50-530/82-16 on 821122-830107 No noncompliance noted.
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 83/02/24 VAN BRUNT, E E Arizona Public Service Co
2pp 17420:056 24X Fiche 50-528,83/02/24,8303040355

--8303040361 IE Insp Repts 50-528/82-37, 50-529/82-15 & 50-530/82-16 on 821122-830107 No noncompliance noted Major areas inspected Unit 1 structural integrity test, Unit 2 steam generator dryer region & Unit 3 electrical penetrations.
VORDERBRUEGGEN, YOUNG, T Division of Resident, Reactor Project & Engineering Programs 83/02/22 11pp 17420:058 24X
Fiche 50-528,83/02/24,8303040355

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc
11lpp 17521:001 24X Fiche 50-000,83/02/25,8212060367

8303140541 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetrations & Assemblies." No Bunker-Ramo electrical penetrations in use or planned for use at facilities.
ANDOGNINI, G C Arizona Public Service Co 83/03/02 ENGELKEN, R H
Region 5, Office of Director 2pp 17534:182 24X
Fiche 50-528,83/03/02,8303140541

8303180513 Forwards IE Insp Rept 50-528/83-02 on 830104-07 & 17-21 & notice of violation.
STERNBERG, D M Region 5, Office of Director 83/03/02 VAN
BRUNT, E E Arizona Public Service Co 2pp 17622:161 24X
Fiche 50-528,83/03/02,8303180513

--8303180517 Notice of violation from insp on 830104-07 & 17-21.
YOUNG, T Region 5, Office of Director 83/03/02 2pp
17622:163 24X Fiche 50-528,83/03/02,8303180513

--8303180522 IE Insp Rept 50-528/83-02 on 830104-07 & 17-21 Noncompliance noted undocumented weld made in safety-related floor drain & failure to provide hangers.
NARBUT, P P , YOUNG, T Region 5, Office of Director 83/02/25
16pp 17622:165 24X Fiche 50-528,83/03/02,8303180513

8303140546 Forwards SALP data package for Jul 1981 - Feb 1983 Draft performance analysis for each functional area requested by 830318 Responsible individuals for performance analyses listed SALP Board will convene on 830413.
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 83/03/08 YOUNG, T , NARBUT, P , ECKHARDT, J Region 5, Office of Director 2pp 17541:020 24X Fiche 50-528,83/03/08,
8303140546

--8303140555 SALP data package for Jul 1981 - Feb 1983, including excerpts of NRC Manual Chapter 0516, summaries of licensee activities & insps, enforcement actions, 10CFR50.55(e) repts & other pertinent data Results to be provided after 830413 meeting.
* Region 5, Office of Director 83/04/30 21pp 17541:022 24X
Fiche 50-528,83/03/08,8303140546

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc.
117pp 17611:070 24X Fiche 50-000,83/03/11,8212060380.

8303290250 Forwards IE Insp Repts 50-528/83-03, 50-529/83-01 & 50-530/83-01 on 830214-18 No noncompliance noted.
BOOK, H E Region 5, Office of Director 83/03/11 ANDOGNINI, G C
Arizona Public Service Co 2pp 17716:096 24X
Fiche 50-528,83/03/11,8303290250

--8303290257 IE Insp Repts 50-528/83-03, 50-529/83-01 & 50-530/83-01 on 830214-18 No noncompliance noted Major areas inspected organization & staffing, environ protection, ESF HVAC sys testing, gaseous effluent monitoring sys & facility tour.
NORTH, H S , WENSLAWSKI, F A , BOOK, H E Region 5, Office of
Director 83/03/10 8pp 17716:098 24X Fiche 50-528,83/03/11,
8303290250

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 117pp 24X Fiche 50-000,83/03/18,8212060383.

8303220017 Responds to 821210 ltr requesting addl info re IE Bulletin 81-03 "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel)." Infestation of storage reservoir precluded by plant design.
VAN BRUNT, E E Arizona Public Service Co 83/03/18 JORDAN, E L
Division of Emergency Preparedness & Engineering Response (Post 830103) 4pp 17652:124 24X Fiche 50-528,83/03/18,8303220017.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 121pp 17774:352 24X Fiche 50-000,83/03/21,8212060387.

S. Reportable occurrences, LERs & related correspondence

8303040268 Deficiency Rept DER 82-68 re underground cables to startup transformers which may not carry full-load current at max site soil temp Info will be furnished by 830324.
VAN BRUNT, E E Arizona Public Service Co 83/02/16 STERNBERG, D M
Division of Resident, Reactor Project & Engineering Programs 2pp
17421:353 24X Fiche 50-528,83/02/16,8303040268

8303040441 Rev 1 to Final Deficiency Rept DER 80-23 re loose bushings on Corner & Lada sway struts Shop procedure requiring staking of all Size 1-3 rigid sway strut rod paddle ends instituted on 791119 Bechtel will repair subj struts.
VAN BRUNT, E E Arizona Public Service Co 83/02/16 STERNBERG, D M
Division of Resident, Reactor Project & Engineering Programs 8pp
17367:334 24X Fiche 50-528,83/02/16,8303040441

8303040444 Final Deficiency Rept DER 83-1 re diesel generator voltage regulating sys transformers not performing as specified at high ambient temps Initially reported on 830118 Design change packages issued Also reported per Part 21.
VAN BRUNT, E E Arizona Public Service Co 83/02/16 STERNBERG, D M
Division of Resident, Reactor Project & Engineering Programs 4pp
17370:213 24X Fiche 50-528,83/02/16,8303040444

8303040563 Final Deficiency Rept DER 81-15 re Terry Steam Turbine Corp turbine driven pump not providing auxiliary feedwater flow within 10 s in case of motor pump failure Initially reported on 820605 Deficiency not reportable per 10CFR50.55e.
VAN BRUNT, E E Arizona Public Service Co 83/02/16 STERNBERG, D M
Division of Resident, Reactor Project & Engineering Programs 14pp
17374:140 24X Fiche 50-528,83/02/16,8303040563

8303040578 Interim Deficiency Rept DER 82-61 re reactor coolant pump diffusor-ring cap screws & pump damage. Initially reported on 821021. Due to extensive evaluation, info will be finalized by 830329.
VAN BRUNT, E. E. Arizona Public Service Co. 83/02/16. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 1p. 17373:290. 24X Fiche. 50-528, 83/02/16, 8303040578.

8303080146 Final Deficiency Rept DER 82-55 re failure of dc motor feeder cable sizing to provide sufficient operating voltage at full load. Initially reported on 820930. All dc power & control feeder cables reviewed for correct sizing.
VAN BRUNT, E. E. Arizona Public Service Co. 83/02/23. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 3pp. 17458:212. 24X Fiche. 50-528, 83/02/23, 8303080146.

8303080235 Revised Interim Deficiency Rept DER 82-53 re 2-inch penetration of containment liner plate due to Joy fan blade failure. Initially reported on 820924. Final rept will be submitted by 830331.
VAN BRUNT, E. E. Arizona Public Service Co. 83/02/23. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 3pp. 17446:354. 24X Fiche. 50-528, 83/02/23, 8303080235.

8303080414 Interim Deficiency Rept DER 83-2 re accidentially interchanged valve operators by Posi-Seal on inside & outside valves. Initially reported on 830125. Evaluation in progress. Final rept expected by 830420.
VAN BRUNT, E. E. Arizona Public Service Co. 83/02/23. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 3pp. 17452:357. 24X Fiche. 50-528, 83/02/23, 8303080414.

8303080439 Interim Deficiency Rept DER 83-4 re failure of Waldinger Corp Procedure FWP 10.2-2.4 for air handling units to comply w/ANSI N510 requirements. Initially reported on 830128. Testing performed per procedure Rev. 1. Final rept due 830414.
VAN BRUNT, E. E. Arizona Public Service Co. 83/02/23. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 3pp. 17452:348. 24X Fiche. 50-528, 83/02/23, 8303080439.

8303140191 Final Deficiency Rept DER 81-39 re undocumented section of pipe & welds on C-E gas stripper used in Unit 1. Initially reported on 811121. Pipe to be replaced. Instruction manuals must be submitted to Bechtel Engineering.
VAN BRUNT, E. E. Arizona Public Service Co. 83/02/28. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 4pp. 17540:106. 24X Fiche. 50-528, 83/02/28, 8303140191.

8303140316 Final Deficiency Rept DER 83-6 re undersize shock suppressor installed & accepted by QC in containment. Initially reported on 830203. Formal training session held for all QC pipe support engineers.
VAN BRUNT, E. E. Arizona Public Service Co. 83/02/28. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 3pp. 17543:297. 24X Fiche. 50-528, 83/02/28, 8303140316.

8303140332 Final Deficiency Rept 83-8 re Rockwell hydrogen recombiner qualification test failure due to oxide on relay contacts. Existing timers will be replaced w/sealed timers qualified to IEEE 323. Also reported by Rockwell per Part 21.
VAN BRUNT, E. E. Arizona Public Service Co. 83/02/28. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 3pp. 17534:193. 24X Fiche. 50-528, 83/02/28, 8303140332.

8303140372 Deficiency Rept 83-3 re foreign matl in bearing house of high pressure safety injection pump. Initially reported on 830128. Deficiency subsequently determined not reportable per 10CFR50.55(e).
VAN BRUNT, E. E. Arizona Public Service Co. 83/02/28. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 2pp. 17544:138. 24X Fiche. 50-528, 83/02/28, 8303140372.

8303140480 Interim Deficiency Rept DER 82-42 re Unit 1 reactor coolant pump pressure tap nozzle weld leak due to overheating stainless alloy. Initially reported on 820709. Final rept will not be finalized until 830330 due to extensive evaluation.
VAN BRUNT, E. E. Arizona Public Service Co. 83/02/28. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 2pp. 17540:338. 24X Fiche. 50-528, 83/02/28, 8303140480.

8303150620 Board Notification 83-26 forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys. Info may affect conclusions re probability of/corrective measures for ATWS.
EISENHUT, D. G. Division of Licensing. 83/03/03. PALLADINO, N. Commissioners. 24pp. 17584:097. 24X Fiche. 50-000, 83/03/03, 8303150620.

8303220186 Deficiency Rept DER 83-7 re Drillco maxibolt anchors for safety-related equipment improperly installed due to use of defective torque/pressure gauge. Initially reported on 830204. Condition not reportable per 10CFR50.55(e).
VAN BRUNT, E. E. Arizona Public Service Co. 83/03/04. STERNBERG, D. M. Region 5, Office of Director. 2pp. 17657:163. 24X Fiche. 50-528, 83/03/04, 8303220186.

8303220204 Final Deficiency Rept DER 82-85 re failure of Harlo relay panels in tests due to supplier error using dc coils in ac circuits. Initially reported on 830107. Relays will be replaced prior to fuel load.
VAN BRUNT, E. E. Arizona Public Service Co. 83/03/07. STERNBERG, D. M. Region 5, Office of Director. 3pp. 17657:132. 24X Fiche. 50-528, 83/03/07, 8303220204.

8303140546 Forwards SALP data package for Jul 1981 - Feb 1983. Draft performance analysis for each functional area requested by 830318. Responsible individuals for performance analyses listed. SALP Board will convene on 830413.
STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 83/03/08. YOUNG, T. Region 5, Office of Director. 2pp. 17541:020. 24X Fiche. 50-528, 83/03/08, 8303140546.

--8303140555 SALP data package for Jul 1981 - Feb 1983, including excerpts of NRC Manual Chapter 0516, summaries of licensee activities & insps, enforcement actions, 10CFR50.55(e) repts & other pertinent data. Results to be provided after 830413 meeting.
* Region 5, Office of Director. 83/04/30. 21pp. 17541:022. 24X Fiche. 50-528, 83/03/08, 8303140546.

8303220161 Final Deficiency Rept DR 82-69 re incorrectly marked fuses in control element drive mechanism control sys. Initially reported on 821124. Existing 7 amp fuses replaced w/1 amp fuses. Item not reportable per 10CFR50.55(e).
VAN BRUNT, E. E. Arizona Public Service Co. 83/03/08. STERNBERG, D. M. Region 5, Office of Director. 7pp. 17659:010. 24X Fiche. 50-528, 83/03/08, 8303220161.

8303150585 Part 21 rept re two conditions concerning control wire terminations within 4.16 kV switchgear equipment. Two loose terminals isolated incident. Based on field insp, terminals meet requirements. No hazard exists.
DWYER, P. W. General Electric Co. 83/03/09. DEYOUNG, R. Director's Office, Office of Inspection and Enforcement. 5pp. 17567:328. 24X Fiche. 50-528, 83/03/09, 8303150585.

8303220180 Interim Deficiency Rept DER 82-76 re failure of Target Rock valves to meet specs/test requirements. Initially reported on 821124. Time extension requested to 830503 due to extensive evaluation required.
VAN BRUNT, E. E. Arizona Public Service Co. 83/03/10. STERNBERG, D. M. Region 5, Office of Director. 2pp. 17658:151. 24X Fiche. 50-528, 83/03/10, 8303220180.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche. 50-000, 83/02/24, 8302250505.

DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

8303070040 Forwards responses to request for addl info re PRA for UHS, per 821122 request.
VAN BRUNT, E. E. Arizona Public Service Co. 83/01/31. KNIGHTON, G. Licensing Branch 3. 43pp. 17434:209. 24X Fiche. 50-528, 83/01/31, 8303070040.

8303070058 Forwards "Pressurizer Safety Valve Discharge Piping Evaluation Rept," as final response to NUREG-0737, Item II.2.1. Rept presents plant-specific application of C-E generic program.
VAN BRUNT, E. E. Arizona Public Service Co. 83/01/31. KNIGHTON, G. Licensing Branch 3. 3pp. 17435:349. 24X Fiche. 50-528, 83/01/31, 8303070058.

--8303070070 "Pressurizer Safety Valve Discharge Piping Evaluation Rept."
* Combustion Engineering, Inc. 83/01/31. 107pp. 17435:352. 24X Fiche. 50-528, 83/01/31, 8303070058.

8303010706 Requests info for evaluation of potential missile hazards resulting from fan blade assembly failure. Response requested by 830225.
KNIGHTON, G. W. Licensing Branch 3. 83/02/04. VAN BRUNT, E. E. Arizona Public Service Co. 2pp. 17348:322. 24X Fiche. 50-528, 83/02/04, 8303010706.

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492.033 24X
Fiche: 50-000, 83/02/16, 8302170082.

8303030747 Board Notification 83-13 forwards EG&G draft rept, "Identification & Ranking of Nuclear Plant Structures, Sys & Components & Graded QA Guidelines."
EISENHUT, D. G. Division of Licensing 83/02/17 PALLADINO, N. Commissioners 24pp 17364.037 24X Fiche: 50-000, 83/02/17, 8303030747.

8303030710 Board Notification 83-17 forwards JH Conran 830209 affidavit re changes to previous testimony on Unresolved Safety Issue A-17, "Sys Interaction in Nuclear Power Plants."
EISENHUT, D. G. Division of Licensing 83/02/18 PALLADINO, N. J. Commissioners 6pp 17363.317 24X Fiche: 50-000, 83/02/18, 8303030710.

8303090194 Forwards point-by-point comparison of special lifting devices against ANSI 14.6 & NUREG-0612 requirements, per 821118 commitment.
VAN BRUNT, E. E. Arizona Public Service Co. 83/02/23 KNIGHTON, G. Licensing Branch 3 8pp 17472.292 24X Fiche: 50-528, 83/02/23, 8303090194.

8303140589 Requests certification by util chief executive officer or designee that plant designed, constructed & tested per FSAR & other licensing commitments. Certification should be provided under oath or affirmation.
EISENHUT, D. G. Division of Licensing 83/02/24 VAN BRUNT, E. E. Arizona Public Service Co. 2pp 17548.330 24X
Fiche: 50-528, 83/02/24, 8303140589.

8303040452 Summarizes 821020 meeting w/NRC in Bethesda, MD re removal of pipe whip restraints. Listed info will be provided to NRC by 830331.
VAN BRUNT, E. E. Arizona Public Service Co. 83/02/25 KNIGHTON, G. Licensing Branch 3 2pp 17368.008 24X Fiche: 50-528, 83/02/25, 8303040452.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700.303 24X
Fiche: 50-000, 83/03/02, 8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 51pp 17660.176 24X
Fiche: 50-000, 83/03/07, 8303040005.

8303180442 Notification of 830309 meeting w/util, Bechtel & C-E in Bethesda, MD to discuss NRC comments on environ qualification rept.
LICITRA, E. A. Licensing Branch 3 83/03/08 KNIGHTON, G. W. Licensing Branch 3 3pp 17640.263 24X Fiche: 50-528, 83/03/08, 8303180442.

8303230330 Submits addl guidance re submittal of info to complete review of environ qualification of safety-related mechanical equipment located in harsh environ.
KNIGHTON, G. W. Licensing Branch 3 83/03/08 VAN BRUNT, E. E. Arizona Public Service Co. 3pp 17675.057 24X
Fiche: 50-528, 83/03/08, 8303230330.

8303230383 Summary of 830309 meeting w/applicant in Bethesda, MD re NRC comments on environ qualification rept. Addl info required to perform site audit.
LICITRA, E. A. Licensing Branch 3 83/03/14 Licensing Branch 3 4pp 17675.258 24X Fiche: 50-528, 83/03/14, 8303230383.

8303290737 Forwards request for addl info needed to complete review of environ qualification rept. Info requested prior to Apr 1983 site audit.
KNIGHTON, G. W. Licensing Branch 3 83/03/14 VAN BRUNT, E. E. Arizona Public Service Co. 5pp 17748.039 24X
Fiche: 50-528, 83/03/14, 8303290737.

8303290667 Board Notification 83-31 forwards AZ Public Svc Co evaluation concluding that PORVs not warranted for Palo Verde. NRC review of util evaluation incomplete.
EISENHUT, D. G. Division of Licensing 83/03/21 PALLADINO, N. J., ROBERTS, T. M., ASSELSTINE, J. K. Commissioners 9pp 17745.135 24X
Fiche: 50-000, 83/03/21, 8303290667.

--8303110307 Comments on util 821103 ltr re evaluation on safety effects & operational flexibility possibly resulting from installation of pressurizer PORV. Evaluation of info in ref ltr not yet complete.
MATTSON, R. J. Division of Systems Integration (post 811005). 83/02/25 EISENHUT, D. Division of Licensing 2pp 6661D.030. 24X Fiche: 50-000, 83/03/21, 8303110307.

8303280137 Comments on Board Notification 83-38 re failure of GE AK-2 reactor trip breakers. Info may affect NRC conclusions re probability/corrective measures for transients w/o scram events (Unresolved Safety Issue A-9).
EISENHUT, D. G. Division of Licensing 83/03/22 PALLADINO, N. Commissioners 20pp 17709.310 24X Fiche: 50-000, 83/03/22, 8303280137.

8303280168 Forwards revs to Table 3.2-1 of FSAR re applicability of 10CFR50 App B to QA class column. Revs replace footnote (e).
VAN BRUNT, E. E. Arizona Public Service Co. 83/03/22 KNIGHTON, G. Licensing Branch 3 17pp 17709.237 24X Fiche: 50-528, 83/03/22, 8303280168.

8303300510 Notification of 830406-08 meetings w/util & Bechtel in Phoenix, AZ to conduct site audit of power sys. Agenda encl.
LICITRA, E. A. Licensing Branch 3 83/03/22 KNIGHTON, G. W. Licensing Branch 3 5pp 17748.266 24X Fiche: 50-528, 83/03/22, 8303300510.

8303290490 Confirms that M-S-R Public Power Agency (M-S-R) should not be considered as applicant for OL, per Amend 5 to CPPR-141, 142 & 143. Proposed transfer of ownership interest from EI Paso Electric Co to M-S-R will not be consummated.
VAN BRUNT, E. E. Arizona Public Service Co. 83/03/24 KNIGHTON, G. Licensing Branch 3 1p 17725.031 24X Fiche: 50-528, 83/03/24, 8303290490.

8303300187 Summary of 830215-17 seismic qualification audit meeting re equipment including both NSSS & balance of plant scope.
LICITRA, E. A. Licensing Branch 3 83/03/24 Licensing Branch 3 7pp 17754.336 24X Fiche: 50-528, 83/03/24, 8303300187.

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303170114 Forwards discussion of TMI & IE equipment qualification items requiring relief from schedular requirements, per 821217 meeting. NUREG-0737, Items II.D.3.1.D.1, II.F.1.3, II.B.3 & II.F.2 discussed per SER (NUREG-0857).
VAN BRUNT, E. E. Arizona Public Service Co. 83/03/14 KNIGHTON, G. Licensing Branch 3 11pp 17609.147 24X Fiche: 50-528, 83/03/14, 8303170114.

8303310657 Forwards SER Suppl 4 W/o encl.
KNIGHTON, G. W. Licensing Branch 3 83/03/21 VAN BRUNT, E. E. Arizona Public Service Co. 2pp 17780.306 24X
Fiche: 50-528, 83/03/21, 8303310657.

8303300463 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF PALO VERDE NUCLEAR GENERATING STATION, UNITS 1, 2 AND 3. Docket Nos. STN 50-528, STN 50-529 And STN 50-530. (Arizona Public Service Company, et al.)
* Office of Nuclear Reactor Regulation, Director NUREG-0857 S04. 83/03/31 45pp 17763.304 24X Fiche: 50-528, 83/03/31, 8303300463.

F. Security, medical, emergency & fire protection plans

8303180355 Notification of 830308 meeting w/util at site to perform confirmatory evaluation of security program.
LICITRA, E. A. Licensing Branch 3 83/03/01 KNIGHTON, G. W. Licensing Branch 3 2pp 17640.275 24X Fiche: 50-528, 83/03/01, 8303180355.

8303140546 Forwards SALP data package for Jul 1981 - Feb 1983. Draft performance analysis for each functional area requested by 830318. Responsible individuals for performance analyses listed. SALP Board will convene on 830413.
STERNBERG, D. M. Division of Resident/Reactor Project & Engineering Programs 83/03/08 YOUNG, T. Region 5, Office of Director 2pp 17541.020 24X Fiche: 50-528, 83/03/08, 8303140546.

--8303140555 SALP data package for Jul 1981 - Feb 1983, including excerpts of NRC Manual Chapter 0516, summaries of licensee activities & insps, enforcement actions, 10CFR50.55(e) repts & other pertinent data. Results to be provided after 830413 meeting.
* Region 5, Office of Director 83/04/30 21pp 17541.022 24X
Fiche: 50-528, 83/03/08, 8303140546.

8303300674 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 83/03/28 Document Management Branch 1p 17770.267 24X Fiche: 50-528, 83/03/28, 8303300674.

--8303300678 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EPIP-14B re dose assessment & Rev 0 to Procedures EPIP-01 through EPIP-14A & EPIP-15 through EPIP-55.
VAN BRUNT, E. E. Arizona Public Service Co. 83/02/23. Licensing Branch 3. 2pp. 17770:268. 24X Fiche: 50-528, 83/03/28, 8303300674.

--8303300684 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP-14B, "Dose Assessment" & Rev 0 to Procedures EPIP-01 through EPIP-14A & EPIP-15 through EPIP-55. Revised index encl.
LUCIA, S. Arizona Public Service Co. 83/01/26. 584pp. 17770:270. 24X Fiche: 50-528, 83/03/28, 8303300674.

G. Adjudicatory correspondence

8303100268 Response in opposition to PL Hourihan 830323 motion for leave to file response to West Valley Agricultural Protection Council 830202 motion for ruling on contentions. No good cause shown for late filing. Certificate of Svc encl.
CRAWFORD, V. A. Joint Applicants-Palo Verde. CRAWFORD, V. A. Snell & Wilmer. 83/03/07. Atomic Safety and Licensing Board Panel. 25pp. 17489:315. 24X Fiche: 50-528, 83/03/07, 8303100268.

8303140462 Forwards stipulation & proposed order re discovery. Certificate of Svc encl.
PLATT, W. E. Snell & Wilmer. 83/03/09. LAZO, R. M. Atomic Safety and Licensing Board Panel. 4pp. 17540:347. 24X Fiche: 50-528, 83/03/09, 8303140462.

--8303140472 Stipulation agreeing to encl proposed order re discovery, subj to acceptability by ASLB & to right to seek mods of proposed order.
DEWEY, L. S. Hearing Branch 3. BERLIN, K. West Valley Agricultural Protection Council, Inc. PLATT, W. E. Joint Applicants-Palo Verde. 83/03/09. 7pp. 17540:351. 24X Fiche: 50-528, 83/03/09, 8303140462.

8303140099 Response in opposition to PL Hourihan 830223 motion for leave to file late response to West Valley Agricultural Protection Council 830302 motion for ruling on contentions. Motion inexcusably tardy. Certificate of Svc encl.
DEWEY, L. S. Hearing Branch 3. 83/03/10. Atomic Safety and Licensing Board Panel. 10pp. 17540:060. 24X Fiche: 50-529, 83/03/10, 8303140099.

8303170035 First set of interrogatories. Certificate of Svc encl.
DEWEY, L. S. Hearing Branch 3. 83/03/15. West Valley Agricultural Protection Council, Inc. 11pp. 17609:086. 24X Fiche: 50-529, 83/03/15, 8303170035.

8303180289 First set of interrogatories. Certificate of Svc encl. Related correspondence.
BERLIN, K. West Valley Agricultural Protection Council, Inc. 83/03/15. Joint Applicants-Palo Verde. 22pp. 17617:128. 24X Fiche: 50-529, 83/03/15, 8303180289.

8303220257 First set of nonuniform interrogatories. Certificate of Svc encl.
CRAWFORD, V. A. Joint Applicants-Palo Verde. CRAWFORD, V. A. Snell & Wilmer. 83/03/15. West Valley Agricultural Protection Council, Inc. 124pp. 17657:311. 24X Fiche: 50-528, 83/03/15, 8303220257.

8303240398 Response opposing NRC & Joint Applicants motions to strike PL Hourihan motion for leave to file response to West Valley Agricultural Protection Council, Inc motion for ruling on contentions. Certificate of Svc encl.
BERNABEI, L. Hourihan, P. BERNABEI, L. Government Accountability Project. 83/03/20. Atomic Safety and Licensing Board Panel. 9pp. 17679:015. 24X Fiche: 50-528, 83/03/20, 8303240398.

8303240414 Memorandum & order memorializing 830224 prehearing conference in Phoenix, AZ. Discovery schedule & procedures listed.
LAZO, R. M. Atomic Safety and Licensing Board Panel. 83/03/23. 7pp. 17679:039. 24X Fiche: 50-529, 83/03/23, 8303240414.

8303280145 Forwards Suppl 4 to SER re operation of plants. W/o encl.
DEWEY, L. S. Hearing Branch 3. 83/03/25. LAZO, R. M.; COLE, R. F.; CALLIHAN, D. Atomic Safety and Licensing Board Panel. 1p. 17706:341. 24X Fiche: 50-529, 83/03/25, 8303280145.

8303300283 Order extending time until 830404 for Commission to act to review ALAB-713.
CHILK, S. J. Office of the Secretary of the Commission. 83/03/28. Commissioners. 1p. 17734:283. 24X Fiche: 50-528, 83/03/28, 8303300283.

8303300375 Advises that identity of former util employee who alleged faulty const practices remains confidential. Individual provided w/Govt Accountability Project phone number should individual desire conference w/intervenors.
DEWEY, L. S. Hearing Branch 3. 83/03/29. BERNABEI, L. Government Accountability Project. 1p. 17731:008. 24X Fiche: 50-529, 83/03/29, 8303300375.

8303300445 Contends that PL Hourihan 830320 response to joint applicant & NRC answers to 830223 pleading should be disregarded. Response mischaracterizes answers by referring to "motions to strike." Intervenor is not legally allowed to respond.
DEWEY, L. S. Hearing Branch 3. 83/03/29. LAZO, R. M.; CALLIHAN, D.; COLE, R. F. Atomic Safety and Licensing Board Panel. 2pp. 17731:083. 24X Fiche: 50-529, 83/03/29, 8303300445.

G. Inspection reports, IE Bulletins & correspondence

8303110355 Board Notification 83-14: Forwards followup info on apparent deficiencies in Midland-Ross superstrut matl.
EISENHUT, D. G. Division of Licensing. 83/02/18. PALLADINO, N. Commissioners. 24pp. 17546:205. 24X Fiche: 50-000, 83/02/18, 8303110355.

8303150497 Forwards IE Insp Repts 50-528/83-04 & 50-529/83-02 on 830124-0218. No noncompliance noted.
STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 83/02/23. ANDOGNINI, G. C. Arizona Public Service Co. 2pp. 17560:341. 24X Fiche: 50-528, 83/02/23, 8303150497.

--8303150306 IE Insp Repts 50-528/83-04 & 50-529/83-02 on 830124-0218. No noncompliance noted. Major areas inspected: startup testing, maint, fuel receipt preparations & sys releases.
FIORELLI, G.; JOHNSTON, G. Region 5, Office of Director. YOUNG, T. Division of Resident, Reactor Project & Engineering Programs. 83/02/23. 5pp. 17560:343. 24X Fiche: 50-528, 83/02/23, 8303150497.

8303040355 Forwards IE Insp Repts 50-528/82-37, 50-529/82-15 & 50-530/82-16 on 821122-830107. No noncompliance noted.
STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 83/02/24. VAN BRUNT, E. E. Arizona Public Service Co. 2pp. 17420:056. 24X Fiche: 50-528, 83/02/24, 8303040355.

--8303040361 IE Insp Repts 50-528/82-37, 50-529/82-15 & 50-530/82-16 on 821122-830107. No noncompliance noted. Major areas inspected: Unit 1 structural integrity test, Unit 2 steam generator dryer region & Unit 3 electrical penetrations.
VORDERBRUEGGER, YOUNG, T. Division of Resident, Reactor Project & Engineering Programs. 83/02/22. 11pp. 17420:058. 24X Fiche: 50-528, 83/02/24, 8303040355.

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11pp. 17521:001. 24X Fiche: 50-000, 83/02/25, 8212060367.

8303140541 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetrations & Assemblies." No Bunker-Ramo electrical penetrations in use or planned for use at facilities.
ANDOGNINI, G. C. Arizona Public Service Co. 83/03/02. ENGELKEN, R. H. Region 5, Office of Director. 2pp. 17534:182. 24X Fiche: 50-528, 83/03/02, 8303140541.

8303140546 Forwards SALP data package for Jul 1981 - Feb 1983. Draft performance analysis for each functional area requested by 830318. Responsible individuals for performance analyses listed. SALP Board will convene on 830413.
STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 83/03/08. YOUNG, T.; NARBUT, P.; ECKHARDT, J. Region 5, Office of Director. 2pp. 17541:020. 24X Fiche: 50-528, 83/03/08, 8303140546.

--8303140555 SALP data package for Jul 1981 - Feb 1983, including excerpts of NRC Manual Chapter 0516, summaries of licensee activities & insps, enforcement actions, 10CFR50.55(e) repts & other pertinent data. Results to be provided after 830413 meeting.
* Region 5, Office of Director. 83/04/30. 21pp. 17541:022. 24X Fiche: 50-528, 83/03/08, 8303140546.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070. 24X Fiche: 50-000, 83/03/11, 8212060380.

8303290250 Forwards IE Insp Repts 50-528/83-03, 50-529/83-01 & 50-530/83-01 on 830214-18. No noncompliance noted.
BOOK, H. E. Region 5, Office of Director. 83/03/11. ANDOGNINI, G. C. Arizona Public Service Co. 2pp. 17716:096. 24X Fiche: 50-528, 83/03/11, 8303290250.

--8303290257 IE Insp Repts 50-528/83-03, 50-529/83-01 & 50-530/83-01 on 830214-18 No noncompliance noted. Major areas inspected: organization & staffing, environ protection, ESF HVAC sys testing, gaseous effluent monitoring sys & facility tour. NORTH, H. S., WENSLAWSKI, F. A., BOOK, H. E. Region 5, Office of Director. 83/03/10. 8pp. 17716:098. 24X Fiche: 50-528, 83/03/11, 8303290250.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8303220017 Responds to 821210 ltr requesting addl info re IE Bulletin 81-03 "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel)." Infestation of storage reservoir precluded by plant design. VAN BRUNT, E. E. Arizona Public Service Co. 83/03/18. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 4pp. 17652:124. 24X Fiche: 50-528, 83/03/18, 8303220017.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 12lpp. 17774:352. 24X Fiche: 50-000, 83/03/21, 8212060387.

5, Reportable occurrences, LERs & related correspondence

8303040268 Deficiency Rept DER 82-68 re underground cables to startup transformers which may not carry full-load current at max site soil temp. Info will be furnished by 830324. VAN BRUNT, E. E. Arizona Public Service Co. 83/02/16. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 2pp. 17421:353. 24X Fiche: 50-528, 83/02/16, 8303040268.

8303040441 Rev 1 to Final Deficiency Rept DER 80-23 re loose bushings on Corner & Lada sway struts. Shop procedure requiring staking of all Size 1-3 rigid sway strut rod paddle ends instituted on 791119. Bechtel will repair subj struts. VAN BRUNT, E. E. Arizona Public Service Co. 83/02/16. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 6pp. 17367:334. 24X Fiche: 50-528, 83/02/16, 8303040441.

8303040444 Final Deficiency Rept DER 83-1 re diesel generator voltage regulating sys transformers not performing as specified at high ambient temps. Initially reported on 830118. Design change packages issued. Also reported per Part 21. VAN BRUNT, E. E. Arizona Public Service Co. 83/02/16. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 2pp. 17370:213. 24X Fiche: 50-528, 83/02/16, 8303040444.

8303040563 Final Deficiency Rept DER 81-15 re Terry Steam Turbine Corp turbine driven pump not providing auxiliary feedwater flow within 10 s in case of motor pump failure. Initially reported on 820605. Deficiency not reportable per 10CFR50.55e. VAN BRUNT, E. E. Arizona Public Service Co. 83/02/16. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 14pp. 17374:140. 24X Fiche: 50-528, 83/02/16, 8303040563.

8303040578 Interim Deficiency Rept DER 82-61 re reactor coolant pump diffusor-ring cap screws & pump damage. Initially reported on 821021. Due to extensive evaluation, info will be finalized by 830329. VAN BRUNT, E. E. Arizona Public Service Co. 83/02/16. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 1p. 17373:290. 24X Fiche: 50-528, 83/02/16, 8303040578.

8303080146 Final Deficiency Rept DER 82-55 re failure of dc motor feeder cable sizing to provide sufficient operating voltage at full load. Initially reported on 820930. All dc power & control feeder cables reviewed for correct sizing. VAN BRUNT, E. E. Arizona Public Service Co. 83/02/23. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 3pp. 17458:212. 24X Fiche: 50-528, 83/02/23, 8303080146.

8303080414 Interim Deficiency Rept DER 83-2 re accidentially interchanged valve operators by Posi-Seal on inside & outside valves. Initially reported on 830125. Evaluation in progress. Final rept expected by 830420. VAN BRUNT, E. E. Arizona Public Service Co. 83/02/23. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 3pp. 17452:357. 24X Fiche: 50-528, 83/02/23, 8303080414.

8303080439 Interim Deficiency Rept DER 83-4 re failure of Waldinger Corp Procedure FWP 10.2-2.4 for air handling units to comply w/ANSI N510 requirements. Initially reported on 830128. Testing performed per procedure Rev 1. Final rept due 830414. VAN BRUNT, E. E. Arizona Public Service Co. 83/02/23. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 3pp. 17452:348. 24X Fiche: 50-528, 83/02/23, 8303080439.

8303140191 Final Deficiency Rept DER 81-39 re undocumented section of pipe & welds on C-E gas stripper used in Unit 1. Initially reported on 811121. Pipe to be replaced. Instruction manuals must be submitted to Bechtel Engineering. VAN BRUNT, E. E. Arizona Public Service Co. 83/02/28. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 4pp. 17540:106. 24X Fiche: 50-528, 83/02/28, 8303140191.

8303140332 Final Deficiency Rept 83-8 re Rockwell hydrogen recombiner qualification test failure due to oxide on relay contacts. Existing timers will be replaced w/sealed timers qualified to IEEE 323. Also reported by Rockwell per Part 21. VAN BRUNT, E. E. Arizona Public Service Co. 83/02/28. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 3pp. 17534:193. 24X Fiche: 50-528, 83/02/28, 8303140332.

8303140455 Deficiency Evaluation Rept 83-5 re rework revealing weld undercut on pipe in safety injection sys. Initially reported on 830128. Deficiency determined not reportable per 10CFR50.55(e). No written rept required. VAN BRUNT, E. E. Arizona Public Service Co. 83/02/28. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 2pp. 17543:013. 24X Fiche: 50-529, 83/02/28, 8303140455.

8303140480 Interim Deficiency Rept DER 82-42 re Unit 1 reactor coolant pump pressure tap nozzle weld leak due to overheating stainless alloy. Initially reported on 820709. Final rept will not be finalized until 830330 due to extensive evaluation. VAN BRUNT, E. E. Arizona Public Service Co. 83/02/28. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 2pp. 17540:338. 24X Fiche: 50-528, 83/02/28, 8303140480.

8303220186 Deficiency Rept DER 83-7 re Drillco maxibolt anchors for safety-related equipment improperly installed due to use of defective torque/pressure gauge. Initially reported on 830204. Condition not reportable per 10CFR50.55(e). VAN BRUNT, E. E. Arizona Public Service Co. 83/03/04. STERNBERG, D. M. Region 5, Office of Director. 2pp. 17657:163. 24X Fiche: 50-528, 83/03/04, 8303220186.

8303220204 Final Deficiency Rept DER 82-85 re failure of Harlo relay panels in tests due to supplier error using dc coils in ac circuits. Initially reported on 830107. Relays will be replaced prior to fuel load. VAN BRUNT, E. E. Arizona Public Service Co. 83/03/07. STERNBERG, D. M. Region 5, Office of Director. 2pp. 17657:132. 24X Fiche: 50-528, 83/03/07, 8303220204.

8303140546 Forwards SALP data package for Jul 1981 - Feb 1983. Draft performance analysis for each functional area requested by 830318. Responsible individuals for performance analyses listed. SALP Board will convene on 830413. STERNBERG, D. M. Division of Resident, Reactor Project & Engineering Programs. 83/03/08. YOUNG, T. Region 5, Office of Director. 2pp. 17541:020. 24X Fiche: 50-528, 83/03/08, 8303140546.

--8303140555 SALP data package for Jul 1981 - Feb 1983, including excerpts of NRC Manual Chapter 0516, summaries of licensee activities & insps, enforcement actions, 10CFR50.55(e) repts & other pertinent data. Results to be provided after 830413 meeting. * Region 5, Office of Director. 83/04/30. 21pp. 17541:022. 24X Fiche: 50-528, 83/03/08, 8303140546.

8303220161 Final Deficiency Rept DR 82-69 re incorrectly marked fuses in control element drive mechanism control sys. Initially reported on 821124. Existing 7 amp fuses replaced w/1 amp fuses. Item not reportable per 10CFR50.55(e). VAN BRUNT, E. E. Arizona Public Service Co. 83/03/08. STERNBERG, D. M. Region 5, Office of Director. 7pp. 17659:010. 24X Fiche: 50-528, 83/03/08, 8303220161.

8303150585 Part 21 rept re two conditions concerning control wire terminations within 4.16 kV switchgear equipment. Two loose terminals isolated incident. Based on field insp, terminals meet requirements. No hazard exists. DWYER, P. W. General Electric Co. 83/03/09. DEYOUNG, R. Director's Office, Office of Inspection and Enforcement. 5pp. 17567:328. 24X Fiche: 50-528, 83/03/09, 8303150585.

8303220180 Interim Deficiency Rept DER 82-76 re failure of Target Rock valves to meet specs/test requirements. Initially reported on 821124. Time extension requested to 830503 due to extensive evaluation required. VAN BRUNT, E. E. Arizona Public Service Co. 83/03/10. STERNBERG, D. M. Region 5, Office of Director. 2pp. 17658:151. 24X Fiche: 50-528, 83/03/10, 8303220180.

8303220191 Interim Deficiency Rept DER 82-73 re ITT Grinnell pipe support clamps in main steam supply sys w/excess gap & improperly secured pipe. Initially reported on 821124. Complete rept will be submitted by 830421. VAN BRUNT, E. E. Arizona Public Service Co. 83/03/10. STERNBERG, D. M. Region 5, Office of Director. 2pp. 17658:145. 24X Fiche: 50-529, 83/03/10, 8303220191.

T. Hearing transcripts on non-antitrust matters

8303010206 Transcript of 830224 hearing in Phoenix, AZ. Pp. 2,711-2,893.
* Atomic Safety and Licensing Board Panel 83/02/24 182pp
17332:023 24X Fiche: 50-529, 83/02/24, 8303010206

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp 24X Fiche: 50-000, 83/02/24, 8302250505

DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

A. Application/construction stage documents & correspondence

8303070040 Forwards responses to request for addl info re PRA for UHS, per 821122 request.
VAN BRUNT, E. E. Arizona Public Service Co. 83/01/31 KNIGHTON, G. Licensing Branch 3 43pp 17434:209 24X Fiche: 50-528, 83/01/31, 8303070040

8303070058 Forwards "Pressurizer Safety Valve Discharge Piping Evaluation Rept," as final response to NUREG-0737, Item II.2.1. Rept presents plant-specific application of C-E generic program.
VAN BRUNT, E. E. Arizona Public Service Co. 83/01/31 KNIGHTON, G. Licensing Branch 3 3pp 17435:349 24X Fiche: 50-528, 83/01/31, 8303070058

--8303070070 "Pressurizer Safety Valve Discharge Piping Evaluation Rept."
* Combustion Engineering, Inc. 83/01/31 107pp 17435:352 24X Fiche: 50-528, 83/01/31, 8303070058

8303010706 Requests info for evaluation of potential missile hazards resulting from fan blade assembly failure. Response requested by 830225.
KNIGHTON, G. W. Licensing Branch 3 83/02/04 VAN BRUNT, E. E. Arizona Public Service Co. 2pp 17348:322 24X Fiche: 50-528, 83/02/04, 8303010706

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982. Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp 17492:033 24X Fiche: 50-000, 83/02/16, 8302170082

8303030747 Board Notification 83-13 forwards EG&G draft rept, "Identification & Ranking of Nuclear Plant Structures, Sys & Components & Graded QA Guidelines."
EISENHUT, D. G. Division of Licensing 83/02/[illegible] PALLADINO, N. Commissioners 24pp 17364:037 24X Fiche: 50-000, 83/02/[illegible], 8303030747

8303030710 Board Notification 83-17 forwards JH Conran 830209 affidavit re changes to previous testimony on Unresolved Safety Issue A-17, "Sys Interaction in Nuclear Power Plants."
EISENHUT, D. G. Division of Licensing 83/02/18 PALLADINO, N. J. Commissioners 6pp 17363:317 24X Fiche: 50-000, 83/02/18, 8303030710

8303090194 Forwards point-by-point comparison of special lifting devices against ANSI 14.6 & NUREG-0612 requirements, per 821118 commitment.
VAN BRUNT, E. E. Arizona Public Service Co. 83/02/23 KNIGHTON, G. Licensing Branch 3 8pp 17472:292 24X Fiche: 50-528, 83/02/23, 8303090194

8303140589 Requests certification by util chief executive officer or designee that plant designed, constructed & tested per FSAR & other licensing commitments. Certification should be provided under oath or affirmation.
EISENHUT, D. G. Division of Licensing 83/02/24 VAN BRUNT, E. E. Arizona Public Service Co. 2pp 17548:330 24X Fiche: 50-528, 83/02/24, 8303140589

8303040452 Summarizes 821020 meeting w/NRC in Bethesda, MD re removal of pipe whip restraints. Listed info will be provided to NRC by 830331.
VAN BRUNT, E. E. Arizona Public Service Co. 83/02/25 KNIGHTON, G. Licensing Branch 3 2pp 17368:008 24X Fiche: 50-528, 83/02/25, 8303040452

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp 17700:303 24X Fiche: 50-000, 83/03/02, 8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5pp 17660:176 24X Fiche: 50-000, 83/03/07, 8303040005

8303180442 Notification of 830309 meeting w/util, Bechtel & C-E in Bethesda, MD to discuss NRC comments on environ qualification rept.
LICITRA, E. A. Licensing Branch 3 83/03/08 KNIGHTON, G. W. Licensing Branch 3 3pp 17640:263 24X Fiche: 50-528, 83/03/08, 8303180442

8303230330 Submits addl guidance re submittal of info to complete review of environ qualification of safety-related mechanical equipment located in harsh environ.
KNIGHTON, G. W. Licensing Branch 3 83/03/08 VAN BRUNT, E. E. Arizona Public Service Co. 3pp 17675:057 24X Fiche: 50-528, 83/03/08, 8303230330

8303230383 Summary of 830309 meeting w/applicant in Bethesda, MD re NRC comments on environ qualification rept. Addl info required to perform site audit.
LICITRA, E. A. Licensing Branch 3 83/03/14 Licensing Branch 3 4pp 17675:258 24X Fiche: 50-528, 83/03/14, 8303230383

8303290737 Forwards request for addl info needed to complete review of environ qualification rept. Info requested prior to Apr 1983 site audit.
KNIGHTON, G. W. Licensing Branch 3 83/03/14 VAN BRUNT, E. E. Arizona Public Service Co. 5pp 17748:039 24X Fiche: 50-528, 83/03/14, 8303290737

8303290667 Board Notification 83-31 forwards AZ Public Svc Co evaluation concluding that PORVs not warranted for Palo Verde. NRC review of util evaluation incomplete.
EISENHUT, D. G. Division of Licensing 83/03/21 PALLADINO, N. J. Commissioners 9pp 17745:135 24X Fiche: 50-000, 83/03/21, 8303290667

8303110307 Comments on util 821103 ltr re evaluation on safety effects & operational flexibility possibly resulting from installation of pressurizer PORV. Evaluation of info in ref ltr not yet complete.
MATTSON, R. J. Division of Systems Integration (post 811005). 83/03/25 EISENHUT, D. Division of Licensing 2pp 17745:143 24X Fiche: 50-000, 83/03/21, 8303290667

830328013 Comments on Board Notification 83-38 re failure of GE AK-2 reactor trip breakers. Info may affect NRC conclusions re probability/corrective measures for transients w/o scram. Issue (Unresolved Safety Issue A-9).
EISENHUT, D. G. Division of Licensing 83/03/22 PALLADINO, N. Commissioners 20pp 17709:310 24X Fiche: 50-000, 83/03/22, 8303280137

8303280168 Forwards revs to Table 3.2-1 of FSAR re applicability of 10CFR50 App B to QA class column. Revs replace footnote (e).
VAN BRUNT, E. E. Arizona Public Service Co. 83/03/22 KNIGHTON, G. Licensing Branch 3 17pp 17709:237 24X Fiche: 50-528, 83/03/22, 8303280168

8303300510 Notification of 830406-08 meetings w/util & Bechtel in Phoenix, AZ to conduct site audit of power sys. Agenda encl.
LICITRA, E. A. Licensing Branch 3 83/03/22 KNIGHTON, G. W. Licensing Branch 3 5pp 17748:266 24X Fiche: 50-528, 83/03/22, 8303300510

8303290490 Confirms that M-S-R Public Power Agency (M-S-R) should not be considered as applicant for OL, per Amend 5 to CPPR-141, 142 & 143. Proposed transfer of ownership interest from El Paso Electric Co to M-S-R will not be consummated.
VAN BRUNT, E. E. Arizona Public Service Co. 83/03/24 KNIGHTON, G. Licensing Branch 3 1p. 17725:031 24X Fiche: 50-528, 83/03/24, 8303290490

8303300187 Summary of 830215-17 seismic qualification audit meeting re equipment including both NSSS & balance of plant scope.
LICITRA, E. A. Licensing Branch 3 83/03/24 Licensing Branch 3 7pp 17754:336 24X Fiche: 50-528, 83/03/24, 8303300187

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8303170114 Forwards discussion of TMI & IE equipment qualification items requiring relief from schedular requirements, per 821217 meeting NUREG-0737, Items II.D.3, I.D.1, II.F.1.3, II.B.3 & II.F.2 discussed per SER (NUREG-0857).
VAN BRUNT, E.E. Arizona Public Service Co. 83/03/14 KNIGHTON, G. Licensing Branch 3 11pp 17609.147 24X Fiche 50-528, 83/03/14, 8303170114

8303310657 Forwards SER Suppl 4 W/o encl.
KNIGHTON, G.W. Licensing Branch 3 83/03/21 VAN BRUNT, E.E. Arizona Public Service Co. 2pp 17780.306 24X Fiche 50-528, 83/03/21, 8303310657

8303300463 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF PALO VERDE NUCLEAR GENERATING STATION, UNITS 1, 2 AND 3 Docket Nos. STN 50-528, STN 50-529 And STN 50-530. (Arizona Public Service Company, et al.)
* Office of Nuclear Reactor Regulation, Director NUREG-0857 S04 83/03/31 45pp 17763.304 24X Fiche 50-528, 83/03/31, 8303300463

F. Security, medical, emergency & fire protection plans

8303180355 Notification of 830308 meeting w/util at site to perform confirmatory evaluation of security program.
LICITRA, E.A. Licensing Branch 3 83/03/01 KNIGHTON, G.W. Licensing Branch 3 2pp 17640.275 24X Fiche 50-528, 83/03/01, 8303180355

8303140546 Forwards SALP data package for Jul 1981 - Feb 1983. Draft performance analysis for each functional area requested by 830318. Responsible individuals for performance analyses listed. SALP Board will convene on 830413.
STERNBERG, D.M. Division of Resident, Reactor Project & Engineering Programs 83/03/08 YOUNG, T. Region 5, Office of Director 2pp 17541.020 24X Fiche 50-528, 83/03/08, 8303140546

--8303140555 SALP data package for Jul 1981 - Feb 1983, including excerpts of NRC Manual Chapter 0516, summaries of licensee activities & insps, enforcement actions, 10CFR50.55(e) repts & other pertinent data. Results to be provided after 830413 meeting.
* Region 5, Office of Director 83/04/30 21pp 17541.022 24X Fiche 50-528, 83/03/08, 8303140546

8303300674 Releases public version of revised emergency plan implementing procedures.
FELTON, J.M. Division of Rules and Records 83/03/28 Document Management Branch 1p 17770.267 24X Fiche 50-528, 83/03/28, 8303300674

--8303300678 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EPIP-14B re dose assessment & Rev 0 to Procedures EPIP-01 through EPIP-14A & EPIP-15 through EPIP-55.
VAN BRUNT, E.E. Arizona Public Service Co. 83/02/23 Licensing Branch 3 2pp 17770.268 24X Fiche 50-528, 83/03/28, 8303300674

--8303300684 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP-14B, "Dose Assessment" & Rev 0 to Procedures EPIP-01 through EPIP-14A & EPIP-15 through EPIP-55. Revised index encl.
LUCIA, S. Arizona Public Service Co. 83/01/26 584pp 17770.270 24X Fiche 50-528, 83/03/28, 8303300674

O. Adjudicatory correspondence

8303100268 Response in opposition to PL Hourihan 830323 motion for leave to file response to West Valley Agricultural Protection Council 830202 motion for ruling on contentions. No good cause shown for late filing. Certificate of Svc encl.
CRAWFORD, V.A. Joint Applicants-Palo Verde CRAWFORD, V.A. Snell & Wilmer 83/03/07 Atomic Safety and Licensing Board Panel 25pp 17489.315 24X Fiche 50-528, 83/03/07, 8303100268

8303140462 Forwards stipulation & proposed order re discovery. Certificate of Svc encl.
PLATT, W.E. Snell & Wilmer 83/03/09 LAZO, R.M. Atomic Safety and Licensing Board Panel 4pp 17540.347 24X Fiche 50-528, 83/03/09, 8303140462

--8303140472 Stipulation agreeing to encl proposed order re discovery, subj to acceptability by ASLB & to right to seek mods of proposed order.
DEWEY, L.S. Hearing Branch 3 BERLIN, K. West Valley Agricultural Protection Council, Inc PLATT, W.E. Joint Applicants-Palo Verde 83/03/09 7pp 17540.351 24X Fiche 50-528, 83/03/09, 8303140462

8303140099 Response in opposition to PL Hourihan 830223 motion for leave to file late response to West Valley Agricultural Protection Council 830302 motion for ruling on contentions. Motion inexcusably tardy. Certificate of Svc encl.
DEWEY, L.S. Hearing Branch 3 83/03/10 Atomic Safety and Licensing Board Panel 10pp 17540.060 24X Fiche 50-529, 83/03/10, 8303140099

8303170035 First set of interrogatories. Certificate of Svc encl.
DEWEY, L.S. Hearing Branch 3 83/03/15 West Valley Agricultural Protection Council, Inc. 11pp 17609.086 24X Fiche 50-529, 83/03/15, 8303170035

8303180289 First set of interrogatories. Certificate of Svc encl. Related correspondence.
BERLIN, K. West Valley Agricultural Protection Council, Inc. 83/03/15 Joint Applicants-Palo Verde 22pp 17617.128 24X Fiche 50-529, 83/03/15, 8303180289

8303220257 First set of nonuniform interrogatories. Certificate of Svc encl.
CRAWFORD, V.A. Joint Applicants-Palo Verde CRAWFORD, V.A. Snell & Wilmer 83/03/15 West Valley Agricultural Protection Council, Inc. 124pp 17657.311 24X Fiche 50-528, 83/03/15, 8303220257

8303240398 Response opposing NRC & Joint Applicants motions to strike PL Hourihan motion for leave to file response to West Valley Agricultural Protection Council, Inc motion for ruling on contentions. Certificate of Svc encl.
BERNABEI, L. Hourihan, P. BERNABEI, L. Government Accountability Project 83/03/20 Atomic Safety and Licensing Board Panel 9pp 17679.015 24X Fiche 50-528, 83/03/20, 8303240398

8303240414 Memorandum & order memorializing 830224 prehearing conference in Phoenix, AZ. Discovery schedule & procedures listed.
LAZO, R.M. Atomic Safety and Licensing Board Panel 83/03/23 7pp 17679.039 24X Fiche 50-529, 83/03/23, 8303240414

8303280145 Forwards Suppl 4 to SER re operation of plants. W/o encl.
DEWEY, L.S. Hearing Branch 3 83/03/25 LAZO, R.M., COLE, R.F. CALLIHAN, D. Atomic Safety and Licensing Board Panel 1p 17706.341 24X Fiche 50-529, 83/03/25, 8303280145

8303300283 Order extending time until 830404 for Commission to act to review ALAB-713.
CHILK, S.J. Office of the Secretary of the Commission 83/03/28 Commissioners 1p 17734.283 24X Fiche 50-528, 83/03/28, 8303300283

8303300375 Advises that identity of former util employee who alleged faulty const practices remains confidential. Individual provided w/Govt Accountability Project phone number should individual desire conference w/intervenors.
DEWEY, L.S. Hearing Branch 3 83/03/29 BERNABEI, L. Government Accountability Project 1p 17731.008 24X Fiche 50-529, 83/03/29, 8303300375

8303300445 Contends that PL Hourihan 830320 response to joint applicant & NRC answers to 830223 pleading should be disregarded. Response mischaracterizes answers by referring to "motions to strike." Intervenor is not legally allowed to respond.
DEWEY, L.S. Hearing Branch 3 83/03/29 LAZO, R.M., CALLIHAN, D., COLE, R.F. Atomic Safety and Licensing Board Panel 2pp 17731.083 24X Fiche 50-529, 83/03/29, 8303300445

H. General correspondence

8302700062 Responds to 830302 proposal re closing LPDRs for cancelled or deferred plants. No objection to closing LPDRs for submitted plants. Other LPDRs will remain open pending resolution of CP status.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director 83/03/18 FELTON, J.M. Division of Rules and Records 3pp 17751.074 24X Fiche 50-000, 83/03/18, 8303300062

Q. Inspection reports, IE Bulletins & correspondence

8303110355 Board Notification 83-14 forwards followup info on apparent deficiencies in Midland-Ross superstrut matl.
EISENHUT, D.G. Division of Licensing 83/02/18 PALLADINO, N. Commissioners 24pp 17546.205 24X Fiche 50-000, 83/02/18, 8303110355

8303040355 Forwards IE Insp Repts 50-528/82-37, 50-529/82-15 & 50-530/82-16 on 821122-830107. No noncompliance noted.
STERNBERG, D.M. Division of Resident, Reactor Project & Engineering Programs 83/02/24 VAN BRUNT, E.E. Arizona Public Service Co. 2pp 17420.056 24X Fiche 50-528, 83/02/24, 8303040355

--8303040361 IE Insp Repts 50-528/82-37, 50-529/82-15 & 50-530/82-16 on 821122-830107 No noncompliance noted Major areas inspected Unit 1 structural integrity test, Unit 2 steam generator dryer region & Unit 3 electrical penetrations VORDERBRUEGGER, T YOUNG, T Division of Resident, Reactor Project & Engineering Programs 83/02/22 11pp 17420 058 24X Fiche 50-528, 83/02/24, 8303040355

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 11lpp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367

8303140541 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetrations & Assemblies." No Bunker-Ramo electrical penetrations in use or planned for use at facilities ANDOGNINI, G C Arizona Public Service Co 83/03/02 ENGELKEN, R H Region 5, Office of Director 2pp 17534 182 24X Fiche 50-528, 83/03/02, 8303140541

8303140546 Forwards SALP data package for Jul 1981 - Feb 1983 Draft performance analysis for each functional area requested by 830318 Responsible individuals for performance analyses listed SALP Board will convene on 830413 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 83/03/08 YOUNG, T NARBUT, P ECKHARDT, J Region 5, Office of Director 2pp 17541 020 24X Fiche 50-528, 83/03/08, 8303140546

--8303140555 SALP data package for Jul 1981 - Feb 1983, including excerpts of NRC Manual Chapter 0516, summaries of licensee activities & insps, enforcement actions, 10CFR50 55(e) repts & other pertinent data Results to be provided after 830413 meeting. * Region 5, Office of Director 83/04/30 21pp 17541 022 24X Fiche 50-528, 83/03/08, 8303140546

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc 117pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380

8303290250 Forwards IE Insp Repts 50-528/83-03, 50-529/83-01 & 50-530/83-01 on 830214-18 No noncompliance noted BOOK, H E Region 5, Office of Director 83/03/11 ANDOGNINI, G C Arizona Public Service Co 2pp 17716 096 24X Fiche 50-528, 83/03/11, 8303290250

--8303290257 IE Insp Repts 50-528/83-03, 50-529/83-01 & 50-530/83-01 on 830214-18 No noncompliance noted Major areas inspected, organization & staffing, environ protection, ESF HVAC sys testing, gaseous effluent monitoring sys & facility tour NORTH, H S, WENSLAWSKI, F A, BOOK, H E Region 5, Office of Director 83/03/10 8pp 17716 098 24X Fiche 50-528, 83/03/11, 8303290250

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000, 83/03/18, 8212060383

8303220017 Responds to 821210 ltr requesting addl info re IE Bulletin 81-03 "Flow Blockage of Cooling Water to Safety Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel)." Infestation of storage reservoir precluded by plant design VAN BRUNT, E E Arizona Public Service Co 83/03/18 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 4pp 17652 124 24X Fiche 50-528, 83/03/18, 8303220017

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 121pp 17774 352 24X Fiche 50-000, 83/03/21, 8212060387

## E Reportable occurrences, LERs & related correspondence

8303040268 Deficiency Rept DER 82-68 re underground cables to startup transformers which may not carry full-load current at max site soil temp Info will be furnished by 830324 VAN BRUNT, E E Arizona Public Service Co 83/02/16 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 17421 353 24X Fiche 50-528, 83/02/16, 8303040268

8303040441 Rev 1 to Final Deficiency Rept DER 80-23 re loose bushings on Corner & Lada sway struts Shop procedure requiring staking of all Size 1-3 rigid sway strut rod paddle ends instituted on 791119 Bechtel will repair subj struts VAN BRUNT, E E Arizona Public Service Co 83/02/16 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 8pp 17367 334 24X Fiche 50-528, 83/02/16, 8303040441

8303040563 Final Deficiency Rept DER 81-15 re Terry Steam Turbine Corp turbine driven pump not providing auxiliary feedwater flow within 10 s in case of motor pump failure Initially reported on 820605 Deficiency not reportable per 10CFR50 55e VAN BRUNT, E E Arizona Public Service Co 83/02/16 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 14pp 17374 140 24X Fiche 50-528, 83/02/16, 8303040563

8303040578 Interim Deficiency Rept DER 82-61 re reactor coolant pump diffusor-ring cap screws & pump damage Initially reported on 821021 Due to extensive evaluation, info will be finalized by 830329 VAN BRUNT, E E Arizona Public Service Co 83/02/16 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 1p 17373 290 24X Fiche 50-528, 83/02/16, 8303040578

8303080146 Final Deficiency Rept DER 82-55 re failure of [illegible] motor feeder cable sizing to provide sufficient operating voltage at full load Initially reported on 820930 All dc power & control feeder cables reviewed for correct sizing VAN BRUNT, E E Arizona Public Service Co 83/02/23 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 17458 212 24X Fiche 50-528, 83/02/23, 8303080146

8303080414 Interim Deficiency Rept DER 83-2 re accidentially interchanged valve operators by Posi-Seal on inside & outside valves Initially reported on 830125 Evaluation in progress Final rept expected by 830420 VAN BRUNT, E E Arizona Public Service Co 83/02/23 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 17452 357 24X Fiche 50-528, 83/02/23, 8303080414

8303080439 Interim Deficiency Rept DER 83-4 re failure of Waldinger Corp Procedure FWP 10 2-2 4 for air handling units to comply w/ANSI N510 requirements Initially reported on 830128 Testing performed per procedure Rev 1 Final rept due 830414 VAN BRUNT, E E Arizona Public Service Co 83/02/23 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 17452 348 24X Fiche 50-528, 83/02/23, 8303080439

8303140191 Final Deficiency Rept DER 81-39 re undocumented section of pipe & welds on C-E gas stripper used in Unit 1 Initially reported on 811121 Pipe to be replaced Instruction manuals must be submitted to Bechtel Engineering VAN BRUNT, E E Arizona Public Service Co 83/02/28 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 4pp 17540 106 24X Fiche 50-528, 83/02/28, 8303140191

8303140332 Final Deficiency Rept 83-8 re Rockwell hydrogen recombiner qualification test failure due to oxide on relay contacts Existing timers will be replaced w/sealed timers qualified to IEEE 323 Also reported by Rockwell per Part 21 VAN BRUNT, E E Arizona Public Service Co 83/02/28 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 3pp 17534 193 24X Fiche 50-528, 83/02/28, 8303140332

8303140480 Interim Deficiency Rept DER 82-42 re Unit 1 reactor coolant pump pressure tap nozzle weld leak due to overheating stainless alloy Initially reported on 820709 Final rept will not be finalized until 830330 due to extensive evaluation VAN BRUNT, E E Arizona Public Service Co 83/02/28 STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 2pp 17540 338 24X Fiche 50-528, 83/02/28, 8303140480

8303150620 Board Notification 83-26 forwards info describing Salem Unit 1 830225 failure of reactor trip breakers to open on automatic signal from protective sys Info may affect conclusions re probability of/corrective measures for ATWS EISENHUT, D G Division of Licensing 83/03/03 PALLADINO, N Commissioners 24pp 17584 097 24X Fiche 50-000, 83/03/03, 8303150620

8303220186 Deficiency Rept DER 83-7 re Drillco maxibolt anchors for safety-related equipment improperly installed due to use of defective torque/pressure gauge Initially reported on 830204 Condition not reportable per 10CFR50 55(e) VAN BRUNT, E E Arizona Public Service Co 83/03/04 STERNBERG, D M Region 5, Office of Director 2pp 17657 163 24X Fiche 50-528, 83/03/04, 8303220186

8303220204 Final Deficiency Rept DER 82-85 re failure of Harlo relay panels in tests due to supplier error using dc coils in ac circuits Initially reported on 830107 Relays will be replaced prior to fuel load VAN BRUNT, E E Arizona Public Service Co 83/03/07 STERNBERG, D M Region 5, Office of Director 3pp 17657 132 24X Fiche 50-528, 83/03/07, 8303220204

8303140546 Forwards SALP data package for Jul 1981 - Feb 1983 Draft performance analysis for each functional area requested by 830318 Responsible individuals for performance analyses listed SALP Board will convene on 830412
STERNBERG, D. M. Division of Resident Reactor Project & Engineering Programs 83/03/08 YOUNG, T. Region 5, Office of Director 2pp 17541:020 24X Fiche: 50-528, 83/03/08, 8303140546

--8303140555 SALP data package for Jul 1981 - Feb 1983, including excerpts of NRC Manual Chapter 0516, summaries of licensee activities & insps, enforcement actions, 10CFR50.55(e) repts & other pertinent data Results to be provided after 830413 meeting.
* Region 5, Office of Director 83/04/30 21pp 17541:022 24X Fiche: 50-528, 83/03/08, 8303140546

8303220161 Final Deficiency Rept DR 82-69 re incorrectly marked fuses in control element drive mechanism control sys Initially reported on 821124 Existing 7 amp fuses replaced w/1 amp fuses Item not reportable per 10CFR50.55(e).
VAN BRUNT, E. E. Arizona Public Service Co. 83/03/08 STERNBERG, D. M. Region 5, Office of Director 7pp 17659:010 24X
Fiche: 50-528, 83/03/08, 8303220161

8303150385 Part 21 rept re two conditions concerning control wire terminations within 4.16 kV switchgear equipment Two loose terminals isolated incident Based on field insp, terminals meet requirements No hazard exists.
DWYER, P. W. General Electric Co. 83/03/09 DEYOUNG, R. Director's Office, Office of Inspection an. Enforcement 5pp 17567:328 24X
Fiche: 50-528, 83/03/09, 8303150585

8303220180 Interim Deficiency Rept DER 82-76 re failure of Target Rock valves to meet specs/test requirements Initially reported on 821124 Time extension requested to 830503 due to extensive evaluation required.
VAN BRUNT, E. E. Arizona Public Service Co. 83/03/10 STERNBERG, D. M. Region 5, Office of Director 2pp 17658:151 24X
Fiche: 50-528, 83/03/10, 8303220180

T. Hearing transcripts on non-antitrust matters

8303010206 Transcript of 830224 hearing in Phoenix, AZ Pp 2,711-2,893.
* Atomic Safety and Licensing Board Panel 83/02/24 182pp
17332:023 24X Fiche: 50-529, 83/02/24, 8303010206

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl
EISENHUT, D. G. Division of Licensing 83/02/24 Consolidated
Edison Co. of New York, Inc. 18pp 24X Fiche: 50-000, 83/02/24, 8302250505

DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

A. Application/construction stage documents & correspondence

8303040155 "SSC Development, Validation & Application" & "CRBR Balance of Plant Modeling," monthly highlights for Jan 1983.
QUPPY, J. G. Brookhaven National Laboratory FIN A-3015 8303040155
83/01/11 CURTIS, R. T. Severe Accident Assessment Branch 8pp
17425:031 24X Fiche: 50-537, 83/01/11, 8303040155

8303220106 "Estimate of Release Frequencies for CRBR Program Potential Core Disruptive Accidents."
NAJAFI, B. Science Applications, Inc. SAI-348-83-PA 83/01/31
Office of Nuclear Reactor Regulation, Director 107pp 17649:305
24X Fiche: 50-537, 83/01/31, 8303220106

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D. G. Division of Licensing 83/02/16 Consolidated
Edison Co. of New York, Inc. 18pp 17492:033 24X
Fiche: 50-000, 83/02/16, 8302170082

8303090275 Forwards criteria addressing essential elements of comprehensive reliability assurance program for review & compliance
GRACE, J. N. Clinch River Breeder Reactor Program Office 83/02/25
LONGENECKER, J. Energy, Dept. of, Clinch River Breeder Reactor Plant
24pp 17466:338 24X Fiche: 50-537, 83/02/25, 8303090275

8303010505 Forwards updated page to PSAR Chapter 4.4, design bases section Info concerns primary sodium gas entrainment & assembly flow blockage criteria Page will be submitted w/ next PSAR amend.
LONGENECKER, J. Energy, Dept. of, Clinch River Breeder Reactor Plant
83/02/28 GRACE, J. N. Clinch River Breeder Reactor Program Office
2pp 17337:251 24X Fiche: 50-537, 83/02/28, 8303010505

8303010573 Forwards revised PSAR pages re inservice insp & addl info re NDE procedure, per 830214 discussions Pages clarify design & provide info relative to piping insulation & NDE requirements for cell liners & fire suppression decks.
LONGENECKER, J. Energy, Dept. of, Clinch River Breeder Reactor Plant
83/02/28 GRACE, J. N. Clinch River Breeder Reactor Program Office
7pp 17336:081 24X Fiche: 50-537, 83/02/28, 8303010573

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl.
EISENHUT, D. G. Division of Licensing 83/03/02 Consolidated
Edison Co. of New York, Inc. 17pp 17700:303 24X
Fiche: 50-000, 83/03/02, 8303020321

8303030652 Amend to application for CP, consisting of Amend 76 to PSAR.
LONGENECKER, J. Energy, Dept. of, Clinch River Breeder Reactor Plant
83/03/02 GRACE, J. N. Clinch River Breeder Reactor Program Office
8pp 17414:142 24X Fiche: 50-537, 83/03/02, 8303030652

8303070005 Advises that reliability assurance program will be modified to comply w/criteria presented in NRC 830225 submittal. Project will provide reliability assurance program plan & schedule approx 6 months after issuance of CP.
LONGENECKER, J. Energy, Dept. of, Clinch River Breeder Reactor Plant
83/03/02 GRACE, J. N. Clinch River Breeder Reactor Program Office
2pp 17434:329 24X Fiche: 50-537, 83/03/02, 8303070005

8303150479 Forwards replacement PSAR P 9.4-1 for recently issued Amend 76.
RANDO, J. G. Burns & Roe Co. 83/03/02 NRC - No Detailed
Affiliation Given 2pp 17561:032 24X Fiche: 50-537, 83/03/02, 8303150479

8303070003 Forwards description of cell liner design validation program & fallback plan if base criteria not validated, per NRC request
LONGENECKER, J. Energy, Dept. of, Clinch River Breeder Reactor Plant
83/03/04 GRACE, J. N. Clinch River Breeder Reactor Program Office
4pp 17435:212 24X Fiche: 50-537, 83/03/04, 8303070003

8303070061 Forwards response to questions re thermal margin beyond design base, design & analysis Overly conservative assumptions made by NRC consultants re treatment of sodium aerosols inappropriate
LONGENECKER, J. Energy, Dept. of, Clinch River Breeder Reactor Plant
83/03/04 GRACE, J. N. Clinch River Breeder Reactor Program Office
14pp 17435:216 24X Fiche: 50-537, 83/03/04, 8303070061

8303070100 Addresses ACRS questions re capability of facility to continue shutdown heat removal on natural circulation w/loss of bulk ac power for greater than 2 h Info previously presented to NRC & documented in PSAR Section 5.7.5.
LONGENECKER, J. Energy, Dept. of, Clinch River Breeder Reactor Plant
83/03/04 GRACE, J. N. Clinch River Breeder Reactor Program Office
2pp 17435:274 24X Fiche: 50-537, 83/03/04, 8303070100

8303070112 Forwards "CRBR Program Heat Transport Sys Incontainment Piping Reserve Seismic Margins." Rept addresses questions raised during ACRS 830211 committee meeting.
LONGENECKER, J. Energy, Dept. of, Clinch River Breeder Reactor Plant
83/03/04 GRACE, J. N. Clinch River Breeder Reactor Program Office
1p 17433:030 24X Fiche: 50-537, 83/03/04, 8303070112

--8303070120 "CRBR Program Heat Transport Sys Incontainment Piping Reserve Seismic Margins."
MELLO, R. M.; CHANDRA, U.; MALLETT, R. H. Energy, Dept. of, Clinc River Breeder Reactor Plant ES-LPD-83-001 83/03/04 38pp
17433:031 24X Fiche: 50-537, 83/03/04, 8303070112

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel." (clarification of Generic Ltr 82-12). Svc list encl
EISENHUT, D. G. Division of Licensing 83/03/07 Consolidated
Edison Co. of New York, Inc. 51pp 17660:176 24X
Fiche: 50-000, 83/03/07, 8303040005

8303090298 Forwards corrected PSAR Table 5.6-12 covering DHR operating cases & sensitivity evaluations to be included in future PSAR amend
LONGENECKER, J. Energy, Dept. of, Clinch River Breeder Reactor Plant
83/03/07 GRACE, J. N. Clinch River Breeder Reactor Program Office
2pp 17473:156 24X Fiche: 50-537, 83/03/07, 8303090298

8303310063 Notification of contract execution, Mod 3 to "Casework - CRBR." Contractor: SBA Subcontractor: Engineering & Economics Research, Inc.
FLEENOR, C. Technical Assistance Contracts Branch FIN B-8601
83/03/07 CHECK, P. S. Clinch River Breeder Reactor Program Office
MORRIS, B. NRC - No Detailed Affiliation Given 1p 17775:343 24x Fiche 50-537, 83/03/07, 8303310063

--8303310067 Mod 3, providing incremental funds & incorporating project officer substitution, to "Casework - CRBR."
* Small Business Administration * Engineering & Economics Research, Inc. GUSTAVE, R. P. Division of Contracts FIN B-8601
83/03/07 2pp 17775:344 24X Fiche 50-537, 83/03/07, 8303310063

8303090306 Comments on design change to fission-driven compaction. Compaction of core could lead to energetics during hypothetical core disruptive accident. Design change feasible.
LONGENECKER, J. Energy, Dept. of, Clinch River Breeder Reactor Plant
83/03/08 GRACE, J. N. Clinch River Breeder Reactor Program Office
2pp 17471:240 24X Fiche 50-537, 83/03/08, 8303090306

8303110378 Notification of 830321 meeting w/util, Project Mgt Corp & DOE in Bethesda, MD to review open items.
STARK, R. W. Clinch River Breeder Reactor Program Office. 83/03/08.
GRACE, J. N. Clinch River Breeder Reactor Program Office. 3pp
17523:052 24X Fiche 50-537, 83/03/08, 8303110378

8303310068 "SSC Development, Validation & Application," & "CRBR Balance-of-Plant Modeling," monthly highlights for Feb 1983.
QUPPY, J. G. Brookhaven National Laboratory FIN A-3015 8303310068
83/03/09 CURTIS, R. T. Severe Accident Assessment Branch 8pp
17775:320 24X Fiche 50-537, 83/03/09, 8303310068

8303210063 "CRBR CDA Energetics Independent Assessment NUREG/CR-3224."
* NRC - No Detailed Affiliation Given 83/03/11 723pp
17627:001 24X Fiche 50-537, 83/03/11, 8303210063

8303180008 Notification of 830323 CRBR working meeting w/Mechanical Engineering Branch & DOE in Bethesda, MD to review open items.
STARK, R. M. Clinch River Breeder Reactor Program Office. 83/03/14.
GRACE, J. N. Clinch River Breeder Reactor Program Office. 3pp.
17625:338 24X Fiche 50-537, 83/03/14, 8303180008

8303290076 Notification of 830331 working meeting w/util, DOE & Project Mgt Corp in Bethesda, MD to discuss CRBR review open items. Meeting rescheduled from 830323.
STARK, R. M. Clinch River Breeder Reactor Program Office. 83/03/14.
GRACE, J. N. Clinch River Breeder Reactor Program Office. 3pp
17729:267 24X Fiche 50-537, 83/03/14, 8303290076

8303300088 Notification of contract execution: "CRBR Subcommittee & Associated Working Group," awarded to SI Abdel-Khalik.
MURPHY, L. G. Administrative Contracts Branch FIN B-1557 83/03/15
FRALEY, R. F. ACRS - Advisory Committee on Reactor Safeguards
BOEHNERT, P. NRC - No Detailed Affiliation Given 1p 17754:152
24X Fiche 50-537, 83/03/15, 8303300088

--8303300100 Contract: "CRBR Subcommittee & Associated Working Group," awarded to SI Abdel-Khalik.
ABDEL-KHALIK, S. Abdel-Khalick, S. I. REBELLO, J. E. Division of Contracts FIN B-1557 83/03/15 4pp 17754:153 24X
Fiche 50-537, 83/03/15, 8303300088

8303250013 Forwards new info re cell liner design validation program. Analysis of wall liner at circular penetrations encl.
LONGENECKER, J. Energy, Dept. of, Clinch River Breeder Reactor Plant
83/03/23 GRACE, J. N. Clinch River Breeder Reactor Program Office
13pp 17692:095 24X Fiche 50-537, 83/03/23, 8303250013

B. Utility Preliminary Safety Analysis Report: amends

8303030652 Amend to application for CP, consisting of Amend 76 to PSAR.
LONGENECKER, J. Energy, Dept. of, Clinch River Breeder Reactor Plant
83/03/02 GRACE, J. N. Clinch River Breeder Reactor Program Office
8pp 17414:142 24X Fiche 50-537, 83/03/02, 8303030652

--8303030654 Amend 76 to PSAR.
* Energy, Dept. of 83/03/02 583pp 17414:150 24X
Fiche 50-537, 83/03/02, 8303030652

E. NRC Safety Evaluation Report (SER): supplS & correspondence

8303180119 Forwards SER (NUREG-0968). W/o encl.
GRACE, J. N. Clinch River Breeder Reactor Program Office 83/03/11
LONGENECKER, J. Energy, Dept. of, Clinch River Breeder Reactor Plant
2pp 17624:361 24X Fiche 50-537, 83/03/11, 8303180119

8303210113 Forwards SER (NUREG-0968). W/o encl.
GRACE, J. N. Clinch River Breeder Reactor Program Office 83/03/11.
RAY, J. ACRS - Advisory Committee on Reactor Safeguards 1p.
17660:128 24X Fiche 50-537, 83/03/11, 8303210113

8303280078 Forwards notice of availability of SER (NUREG-0968).
GRACE, J. N. Clinch River Breeder Reactor Program Office. 83/03/23.
LONGENECKER, Energy, Dept. of, Clinch River Breeder Reactor Plant
1p 17715:354 24X Fiche 50-537, 83/03/23, 8303280078

--8303280080 Notice of availability of SER (NUREG-0968).
GRACE, J. N. Clinch River Breeder Reactor Program Office. 83/03/22
3pp 17715:355 24X Fiche 50-537, 83/03/23, 8303280078

8303300092 SAFETY EVALUATION REPORT RELATED TO THE CONSTRUCTION OF THE CLINCH RIVER BREEDER REACTOR PLANT Appendices A-H Docket No. 50-537. (U.S. Department of Energy, Tennessee Valley Authority And Project Management Corporation)
* Clinch River Breeder Reactor Program Office NUREG-0968 V02
83/03/31 373pp 17752:001 24X Fiche 50-537, 83/03/31, 8303300092

8303300448 SAFETY EVALUATION REPORT RELATED TO THE CONSTRUCTION OF THE CLINCH RIVER BREEDER REACTOR PLANT Main Report Docket No. 50-537. (U.S. Department of Energy, Tennessee Valley Authority And Project Management Corporation)
* Clinch River Breeder Reactor Program Office NUREG-0968 V0.1
83/03/31 93dpp 17772:134 24X Fiche 50-537, 83/03/31, 8303300448

F. Security, medical, emergency & fire protection plans

8303010510 Forwards addl info on PSAR, Section 13.3 re coordination w/State of NC & local officials for emergency planning. Info will be incorporated in next PSAR amend.
LONGENECKER, J. Energy, Dept. of, Clinch River Breeder Reactor Plant
83/02/25 GRACE, J. N. Clinch River Breeder Reactor Program Office
3pp 17337:253 24X Fiche 50-537, 83/02/25, 8303010510

G. Adjudicatory correspondence

8303020019 Addresses sequence of events which may follow issuance of partial initial decision.
TURK, S. E. Hearing Branch 1 83/02/28 GRACE, J. N. Clinch River Breeder Reactor Program Office 2pp 17353:163 24X
Fiche 50-537, 83/02/28, 8303020019

8303040435 Partial initial decision authorizing NRR director to issue LWA to conduct site preparation activities, per 10CFR50.10(e)(1).
HAND, C. H., LINENBERGER, G., MILLER, M. E. Atomic Safety and Licensing Board Panel 83/02/28 Office of Nuclear Reactor Regulation, Director 234pp 17370:302 24X Fiche 50-537, 83/02/28, 8303040435

8303030465 Advises that NRC intends to issue SER on 830311.
TURK, S. E. Hearing Branch 1 83/03/02 MILLER, M., HAND, C. H., LINENBERGER, G. Atomic Safety and Licensing Board Panel 1p.
17412:361 24X Fiche 50-537, 83/03/02, 8303030465

8303080497 Motion requesting ASLB to adopt encl CP hearings schedule. NRC concurs w/schedule. Certificate of Svc encl.
EDGAR, G. L. Project Management Corp. LUCK, W. D. Energy, Dept. of
83/03/07 Atomic Safety and Licensing Board Panel 17pp
17450:319 24X Fiche 50-537, 83/03/07, 8303080497

8303090299 Notice of ASLAB reconstitution: DJ Edles, chairman & WR Johnson & HA Wilber, members.
TOMPKINS, B. A. Atomic Safety and Licensing Appeal Panel 83/03/07
1p 17473:155 24X Fiche 50-537, 83/03/07, 8303090299

8303140298 Order opening discovery on all CP issues established by Contentions 1.2(f), 2(g), 2(h), 3, 9, 10 & 11(a).
MILLER, M. E. Atomic Safety and Licensing Board Panel 83/03/10
2pp 17535:041 24X Fiche 50-537, 83/03/10, 8303140298

8303220212 Application for stay of effectiveness of ASLB 830228 partial initial decision authorizing LWA. Intervenors will be irreparably injured due to LWA effect on environ & violation of NEPA rights.
FINAMORE, B. A. Natural Resources Defense Council. FINAMORE, B. A. Sierra Club 83/03/18 Atomic Safety and Licensing Appeal Panel
10pp 17658:105 24X Fiche 50-537, 83/03/18, 8303220212

--8303220221 Exceptions to ASLB 830228 partial initial decision authorizing LWA. Certificate of Svc encl.
FINAMORE, B., WEISS, E. R. Natural Resources Defense Council. WEISS, E. R. Sierra Club 83/03/18 Atomic Safety and Licensing Appeal Panel 23pp 17658:115 24X Fiche 50-537, 83/03/18, 8303220212

8303240006 Ack receipt of applicant 830307 motion re schedule for CP hearings. Mod of early stages of proposed schedule may be necessary to allow ASLB adequate time to rule on motion. TURK, S. E. Hearing Branch 1. 83/03/22. MILLER, M., HAND, C. H., LINENBERGER, G. Atomic Safety and Licensing Board Panel. 1p. 17681:096. 24X Fiche. 50-537. 83/03/22. 8303240006.

8303250165 Response opposing applicant 830323 suppl to 830307 schedule motion. Applicant reliance on intervenor proposed schedule misplaced. Proposed schedule for CP hearings unworkable & unnecessarily foreshortened. Certificate of Svc encl. FINAMORE, B. A., WEISS, E. R. Natural Resources Defense Council. WEISS, E. R. Sierra Club. 83/03/24. Atomic Safety and Licensing Board Panel. 6pp. 17691:118. 24X Fiche. 50-537. 83/03/24. 8303250165.

8303290411 Motion to extend time until 830518 for intervenors to file brief on appeal in support of exceptions. Intervenors engaged in several other proceedings requiring substantial attention. Certificate of Svc encl. FINAMORE, B. A. Natural Resources Defense Council. FINAMORE, B. A. Sierra Club. 83/03/25. Atomic Safety and Licensing Appeal Panel. 5pp. 17726:229. 24X Fiche. 50-537. 83/03/25. 8303290411.

8303290487 Corrections to ASLB 830228 partial initial decision. MILLER, M. E. Atomic Safety and Licensing Board Panel. 83/03/25. 3pp. 17724:335. 24X Fiche. 50-537. 83/03/25. 8303290487.

8303290422 Response in opposition to intervenor application for stay of effectiveness of ASLB partial initial decision. Intervenors failed to sustain burden of demonstrating that extraordinary relief of stay is warranted. Certificate of Svc encl. EDGAR, G. L. Project Management Corp. EDGAR, G. L. Edgar, G. L. LUCK, W. D. Energy, Dept. of, Clinch River Breeder Reactor Plant. 83/03/28. Atomic Safety and Licensing Appeal Panel. 13pp. 17726:284. 24X Fiche. 50-537. 83/03/28. 8303290422.

8303290496 Answer opposing NRDC & Sierra Club 830318 application for stay of effectiveness of ASLB 830228 partial initial decision authorizing limited work. Likelihood of success on merits is minimal. Certificate of Svc encl. TREBY, S. A. Hearing Branch 1. 83/03/28. Atomic Safety and Licensing Appeal Panel. 14pp. 17724:340. 24X Fiche. 50-537. 83/03/28. 8303290496.

8303290502 Order taking jurisdiction over effectiveness review of ASLB 830228 partial initial decision, w/o ASLAB involvement. Action taken due to Commission previous involvement & fundamental policy issues raised by proceeding. CHILK, S. J. Office of the Secretary of the Commission. 83/03/28. 6pp. 17725:115. 24X Fiche. 50-537. 83/03/28. 8303290502.

8303310279 Order establishing schedule for events leading to CP hearing phase. CP hearing to begin on 830718. MILLER, M. E. Atomic Safety and Licensing Board Panel. 83/03/29. 2pp. 17755:361. 24X Fiche. 50-537. 83/03/29. 8303310279.

H. General correspondence

8303230203 FOIA request for transcript of Commission 830105 meeting to consider exemption request per 10CFR50.12 for CRBR. GREENBERG, E. V. Galloway & Greenberg. GREENBERG, E. V. Natural Resources Defense Council. GREENBERG, E. V. Sierra Club. 83/01/25. NORRY, P. G. Office of Administration. 2pp. 17686:187. 24X Fiche. 50-537. 83/01/25. 8303230203.

8303230206 Responds to FOIA request for transcript of Commission 830105 meeting to consider exemption request per 10CFR50.12 for CRBR. Document withheld (ref FOIA Exemption 5). FELTON, J. M. Division of Rules and Records. 83/02/22. GREENBERG, E. V. Galloway & Greenberg. 1p. 17686:189. 24X Fiche. 50-537. 83/02/22. 8303230206.

G. Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/02/25. Consolidated Edison Co. of New York, Inc. 11lpp. 17521:001. 24X Fiche. 50-000. 83/02/25. 8212060367.

8303010573 Forwards revised PSAR pages re inservice insp & addl info re NDE procedure, per 830214 discussions. Pages clarify design & provide info relative to piping insulation & NDE requirements for cell liners & fire suppression decks. LONGENECKER, J. Energy, Dept. of, Clinch River Breeder Reactor Plant. 83/02/28. GRACE, J. N. Clinch River Breeder Reactor Program Office. 7pp. 17336:081. 24X Fiche. 50-537. 83/02/28. 8303010573.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 83/03/11. Consolidated Edison Co. of New York, Inc. 117pp. 17611:070. 24X Fiche. 50-000. 83/03/11. 8212060380.

8303150458 Forwards "Adequacy of CRBR Program Reactor Vessel NDE Insps." Rept supports conclusion that exam performed on reactor vessel adequate. Rept also applicable to ex-vessel storage tank & heat transport sys vessels. LONGENECKER, J. Energy, Dept. of, Clinch River Breeder Reactor Plant. 83/03/14. GRACE, J. N. Clinch River Breeder Reactor Program Office. 1p. 17561:077. 24X Fiche. 50-537. 83/03/14. 8303150458.

--8303150459 "Adequacy of CRBR Program Reactor Vessel NDE Insps." BALOH, J. Westinghouse Electric Corp. ES-LRD-83-3030 R01. 83/03/10. 55pp. 17561:078. 24X Fiche. 50-537. 83/03/14. 8303150458.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18. Consolidated Edison Co. of New York, Inc. 117pp. 24X Fiche. 50-000. 83/03/18. 8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc. 121pp. 17774:352. 24X Fiche. 50-000. 83/03/21. 8212060387.

T. Hearing transcripts on non-antitrust matters

8303180320 Transcript of ACRS CRBR Subcommittee & Structures & Matls Working Group 830316 combined meeting in Washington, DC. Pp 1-264. * ACRS - Advisory Committee on Reactor Safeguards. 83/03/16. 262pp. 17620:134. 24X Fiche. 50-537. 83/03/16. 8303180320.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl. EISENHUT, D. G. Division of Licensing. 83/02/24. Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche. 50-000. 83/02/24. 8302250505.

DOCKET 50-538 MEMPHIS STATE UNIV. RESEARCH REACTOR

R. Periodic operating reports & related correspondence

8303160439 Forwards "Nuclear Reactor Operations Annual Rept for 1982." JONES, D. W. Memphis State Univ. 83/03/09. Office of Nuclear Reactor Regulation, Director. 1p. 17592:175. 24X Fiche. 50-538. 83/03/09. 8303160439.

--8303160441 "Nuclear Reactor Operations Annual Rept for 1982." DIETZ, R. L., JONES, D. W. Memphis State Univ. 83/02/25. 57pp. 17592:176. 24X Fiche. 50-538. 83/03/09. 8303160439.

DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 require) owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl. EISENHUT, D. G. Division of Licensing. 83/02/16. Consolidated Edison Co. of New York, Inc. 18pp. 17492:033. 24X Fiche. 50-000. 83/02/16. 8302170082.

8303030420 Advises that application for OL sufficiently complete for docketing & initiation of safety & environ reviews. Request for addl info, clarification of GDC 51 & detailed guidance encl. EISENHUT, D. G. Division of Licensing. 83/02/23. SHIELDS, S. W. Public Service Co. of Indiana, Inc. 63pp. 17419:209. 24X Fiche. 50-546. 83/02/23. 8303030420.

8302280121 Forwards Amend 22 to OL application, consisting of responses to NRC questions, FSAR (filed in PDR Category K), security plan & fire protection rept (Category F), environ rept (Category C) & Central Files version of emergency plan. SHIELDS, S. W. Public Service Co. of Indiana, Inc. SHIELDS, S. W. Wabash Valley Power Association, Inc. 83/02/24. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 5pp. 17375:001. 24X Fiche. 50-546. 83/02/24. 8302280121.

# DOCKETED ITEMS

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal assorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X
Fiche 50-000, 83/03/02, 8303020321

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/ electronic networking sys
KEPPLER, J G Region 3, Office of Director 83/03/03 Commonwealth Edison Co 2pp 17492 014 24X Fiche 50-000, 83/03/03, 8303100364

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12) Svc list encl
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 51pp 17660 176 24X
Fiche 50-000, 83/03/07, 8303040005

8303220259 Forwards summary of Feb 1983 organizational changes, per commitment to notify of changes altering organizations described in consolidated description of QA program
SHIELDS, S W Public Service Co of Indiana, Inc 83/03/15
DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 17656 228 24X Fiche 50-546, 83/03/15, 8303220259

8303290810 Forwards notice of receipt of application for OLs, of availability of environ rept, of consideration of issuance of OLs & of opportunity for hearing
YOUNGBLOOD, B J Licensing Branch 1 83/03/15 SHIELDS, S W Public Service Co of Indiana, Inc 4pp 17748 075 24X
Fiche 50-546, 83/03/15, 8303290810

--8303290825 Notice of receipt of application for OLs, of availability of environ rept, of consideration of issuance of OLs & of opportunity for hearing
YOUNGBLOOD, B J Licensing Branch 1 83/03/15 10pp 17748 078 24X Fiche 50-546, 83/03/15, 8303290810

8303240134 Requests copy of response to J Gorn request to provide chronology of events re 830128 electrical stop work order & detailed discussion of current status of issue for Senate Subcommittee on Nuclear Regulation
O'CONNOR, P W Licensing Branch 1 83/03/16 HARRISON, J Region 3, Office of Director 1p 17698 342 24X Fiche 50-546, 83/03/16, 8303240134

8303220436 Advises of safety & environ OL review schedules for facilities Const approx 43% & 25% complete for Units 1 & 2, respectively & fuel load scheduled for June 1986
EISENHUT, D G Division of Licensing 83/03/18 VOLLMER, R H Division of Engineering MATTSON, R J Division of Systems Integration (post 811005) THOMPSON, H L Division of Human Factors Safety 3pp 17672 235 24X Fiche 50-546, 83/03/18, 8303220436

8303280096 Advises that response to Generic Ltr 83-10c re resolution of TMI Action Item II K 3 5 will be provided within specified 60-day timeframe Responses to Items I 1a, I 3a & I 3c will be submitted in amend to App E Section E 52 of FSAR by 840331
SHIELDS, S W Public Service Co of Indiana, Inc 83/03/23
EISENHUT, D G Division of Licensing 1p 17707 249 24X
Fiche 50-546, 83/03/23, 8303280096

C Utility Environmental Report (ER), amends & correspondence

8303290810 Forwards notice of receipt of application for OLs, of availability of environ rept, of consideration of issuance of OLs & of opportunity for hearing
YOUNGBLOOD, B J Licensing Branch 1 83/03/15 SHIELDS, S W Public Service Co of Indiana, Inc 4pp 17748 075 24X
Fiche 50-546, 83/03/15, 8303290810

--8303290825 Notice of receipt of application for OLs, of availability of environ rept, of consideration of issuance of OLs & of opportunity for hearing
YOUNGBLOOD, B J Licensing Branch 1 83/03/15 10pp 17748 078 24X Fiche 50-546, 83/03/15, 8303290810

F Security, medical, emergency & fire protection plans

8303100551 Releases public version of revised emergency plan
FELTON, J M Division of Rules and Records 83/03/04 Document Management Branch 1p 17504 145 24X Fiche 50-546, 83/03/04, 8303100551

--8303100555 Public version of Rev 0 to emergency plan
Public Service Co of Indiana, Inc 82/10/31 210pp 17504 151 24X Fiche 50-546, 83/03/04, 8303100551

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition Appropriate planning should take place to prevent possible t ansmission errors
HIND, J A Region 3, Office of Director 83/03/22 Commonwealth Edison Co 2pp 17690 316 24X Fiche 50-000, 83/03/22, 8303240440

O Adjudicatory correspondence

8303030459 Advises that responsibility for case will be transferred from Hearing Section III & E Reis to Hearing Section II & J Rutberg
CHRISTENBURY, E Hearings Division 83/03/02 REIS, E J Hearing Branch 3 RUTBERG, J Hearing Branch 2 1p 17409 262 24X
Fiche 50-546, 83/03/02, 8303030459

K Utility Final Safety Analysis Report (FSAR) & amends

8302280121 Forwards FSAR for Marble Hill Nuclear Generating Station, Units 1 & 2
SHIELDS, S W Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 17375 001 24X
Fiche 50-546, 83/02/24, 8302280121

--8302280137 FSAR for Marble Hill Nuclear Generating Station, Units 1 & 2 W/133 oversize drawings Aperture cards are available in PDR
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 1p 17375 027 24X
Fiche 50-546, 83/02/24, 8302280121

O Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal," Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 11pp 17521 001 24X Fiche 50-000, 83/02/25, 8212060367

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers," Svc list encl
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc 11?pp 17611 070 24X Fiche 50-000, 83/03/11, 8212060380

8303280235 Forwards IE Insp Repts 50-546/82-21 & 50-547/82-21 on 821011-830131 No noncompliance noted
KNOP, R C Region 3, Office of Director 83/03/14 SHIELDS, S W Public Service Co of Indiana, Inc 2pp 17706 196 24X
Fiche 50-546, 83/03/14, 8303280235

--8303280244 IE Insp Repts 50-546/82-21 & 50-547/82-21 on 821011-830131 No noncompliance noted Major areas inspected previous insp findings, erection, nondestructive testing & welding of Unit 1 containment structural steel
HARRISON, J J ; KONKLIN, J E Region 3, Office of Director 83/03/08 8pp 17706 198 24X Fiche 50-546, 83/03/14, 8303280235

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co of New York, Inc 11?pp 24X Fiche 50-000, 83/03/18, 8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 12?pp 17774 352 24X Fiche 50-000, 83/03/21, 8212060387

R Periodic operating reports & related correspondence

8303100325 Submits daily highlights for facility OL acceptance review completed Fuel load date of June 1986 projected by applicant
O'CONNER, P W Licensing Branch 1 83/02/25 DENTON, H R , CASE, E , CARTER, J Office of Nuclear Reactor Regulation, Director 1p 17504 075 24X Fiche 50-546, 83/02/25, 8303100325

S Reportable occurrences, LERs & related correspondence

8303150123 Interim deficiency rept re deformed wire anchors separated from embedded plates Initially reported on 821020 Cause under investigation Next rept due by 830610
SHIELDS, S W Public Service Co of Indiana, Inc 83/03/08
KEPPLER, J G Region 3, Office of Director 2pp 17550 280 24X
Fiche 50-546, 83/03/08, 8303150123

8303150286 Interim deficiency rept re inadequate implementation of QA program Initially reported on 830211 Commonwealth-Lord Joint Venture addressing util audit Required corrective actions will be taken Next rept due by 830520
SHIELDS, S W Public Service Co of Indiana, Inc 83/03/08
KEPPLER, J G Region 3, Office of Director 2pp 17567.054 24X
Fiche 50-546, 83/03/08, 8303150286

8303220020 Interim deficiency rept re welding techniques not covered by Brown-Boveri Electric QA program used in fabrication of safety-related switchgear Initially reported on 820525 Next rept will be submitted by 830715
SHIELDS, S W Public Service Co of Indiana, Inc 83/03/14
KEPPLER, J G Region 3, Office of Director 2pp 17652.130 24X
Fiche 50-546, 83/03/14, 8303220020

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee," Svc list encl
EISENHUT, D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000, 83/02/24, 8302250505

8303170409 Forwards schedule for site visits to conduct operator licensing exams in response to Generic Ltr 83-01 Exams tentatively scheduled for Mar-May 1986 for Unit 1 Exams for Unit 2 will be requested in early 1987
SHIELDS, S W Public Service Co of Indiana, Inc 83/02/28
KEPPLER, J G Region 3, Office of Director 2pp 17609.278 24X
Fiche 50-546, 83/02/28, 8303170409

DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal Svc list encl
EISENHUT, D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492.033 24X
Fiche 50-000, 83/02/16, 8302170082

8303030420 Advises that application for OL sufficiently complete for docketing & initiation of safety & environ reviews Request for addl info, clarification of GDC 51 & detailed guidance encl
EISENHUT, D G Division of Licensing 83/02/23 SHIELDS, S W Public Service Co of Indiana, Inc 63pp 17419.209 24X
Fiche 50-546, 83/02/23, 8303030420

8302280121 Forwards Amend 22 to OL application, consisting of responses to NRC questions, FSAR (filed in PDR Category A), security plan & fire protection rept (Category F), environ rept (Category C) & Central Files version of emergency plan
SHIELDS, S W Public Service Co of Indiana, Inc SHIELDS, S W Wabash Valley Power Association, Inc 83/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 17375.001 24X
Fiche 50-546, 83/02/24, 8302280121

8303020321 Generic Ltr 83-12 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys Svc list encl
EISENHUT, D G Division of Licensing 83/02/02 Consolidated Edison Co of New York, Inc 17pp 17700.303 24X
Fiche 50-000, 83/02/02, 8303020321

8303100364 Requests list of electronic communicating hardware installed at various ofcs if util interested in implementing computer/electronic networking sys
KEPPLER, J G Region 3, Office of Director 83/03/03
Commonwealth Edison Co 2pp 17492.014 24X Fiche 50-000, 83/03/03, 8303100364

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12) Svc list encl
EISENHUT, D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 51pp 17660.176 24X
Fiche 50-000, 83/03/07, 8303040005

8303220259 Forwards summary of Feb 1983 organizational changes, per commitment to notify of changes altering organizations described in consolidated description of QA program
SHIELDS, S W Public Service Co of Indiana, Inc 83/03/15
DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 17656.226 24X Fiche 50-546, 83/03/15, 8303220259

8303290810 Forwards notice of receipt of application for OLs, of availability of environ rept, of consideration of issuance of OLs & of opportunity for hearing
YOUNGBLOOD, B J Licensing Branch 1 83/03/15 SHIELDS, S W Public Service Co of Indiana, Inc 4pp 17748.075 24X
Fiche 50-546, 83/03/15, 8303290810

--8303290825 Notice of receipt of application for OLs, of availability of environ rept, of consideration of issuance of OLs & of opportunity for hearing
YOUNGBLOOD, B J Licensing Branch 1 83/03/15 10pp 17748.078 24X Fiche 50-546, 83/03/15, 8303290810

8303240134 Requests copy of response to J Gorn request to provide chronology of events re 830128 electrical stop work order & detailed discussion of current status of issue for Senate Subcommittee on Nuclear Regulation
O'CONNOR, P W Licensing Branch 1 83/03/16 HARRISON, J Region 3, Office of Director 1p 17698.342 24X Fiche 50-546, 83/03/16, 8303240134

8303220436 Advises of safety & environ OL review schedules for facilities Const approx 45% & 25% complete for Units 1 & 2, respectively & fuel load scheduled for June 1986
EISENHUT, D G Division of Licensing 83/03/18 VOLLMER, R H Division of Engineering MATTSON, R J Division of Systems Integration (post 811005) THOMPSON, H L Division of Human Factors Safety 3pp 17672.235 24X Fiche 50-546, 83/03/18, 8303220436

8303280096 Advises that response to Generic Ltr 83-10c re resolution of TMI Action Item II K 3.5 will be provided within specified 60-day timeframe Responses to Items I 1e, I 3a & I 3c will be submitted in amend to App E, Section E 52 of FSAR by 840331
SHIELDS, S W Public Service Co of Indiana, Inc 83/03/23
EISENHUT, D G Division of Licensing 1p 17707.249 24X
Fiche 50-546, 83/03/23, 8303280096

C Utility Environmental Report (ER), amends & correspondence

8303290810 Forwards notice of receipt of application for OLs, of availability of environ rept, of consideration of issuance of OLs & of opportunity for hearing
YOUNGBLOOD, B J Licensing Branch 1 83/03/15 SHIELDS, S W Public Service Co of Indiana, Inc 4pp 17748.075 24X
Fiche 50-546, 83/03/15, 8303290810

-8303290825 Notice of receipt of application for OLs, of availability of environ rept, of consideration of issuance of OLs & of opportunity for hearing
YOUNGBLOOD, B J Licensing Branch 1 83/03/15 10pp 17748.078 24X Fiche 50-546, 83/03/15, 8303290810

F Security, medical, emergency & fire protection plans

8303100551 Releases public version of revised emergency plan
FELTON, J M Division of Rules and Records 83/03/04 Document Management Branch 1p 17504.145 24X Fiche 50-546, 83/03/04, 8303100551

--8303100555 Public version of Rev 0 to emergency plan
* Public Service Co of Indiana, Inc 82/10/31 210pp 17504.151 24X Fiche 50-546, 83/03/04, 8303100551

8303240440 Notifies that FTS svc will be replacing current health physics network for transmitting NRC radiological info during incident or accident condition Appropriate planning should take place to prevent possible transmission errors
HIND, J A Region 3, Office of Director 83/03/22 Commonwealth Edison Co 2pp 17690.316 24X Fiche 50-000, 83/03/22, 8303240440

Q Adjudicatory correspondence

8303030459 Advises that responsibility for case will be transferred from Hearing Section III & E Reis to Hearing Section II & J Rutberg
CHRISTENBURY, E Hearings Division 83/03/07 REIS, E J Hearing Branch 3 RUTBERG, J Hearing Branch 2 1p 17409.262 24X
Fiche 50-546, 83/03/02, 8303030459

K Utility Final Safety Analysis Report (FSAR) & amends

8302280121 Forwards FSAR for Marble Hill Nuclear Generating Station, Units 1 & 2
SHIELDS, S W Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 17375.001 24X
Fiche 50-546, 83/02/24, 8302280121

--8302280137 FSAR for Marble Hill Nuclear Generating Station,Units 1 & 2 W/133 oversize drawings Aperture cards are available in PDR * Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc 83/02/24 Ip 17375 027 24X Fiche 50-546,83/02/24,8302280121

Q Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 11lpp 17521 001 24X Fiche 50-000,83/02/25,8212060367

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co of New York, Inc 11/pp 17611 070 24X Fiche 50-000,83/03/11,8212060380

8303280235 Forwards IE Insp Repts 50-546/82-21 & 50-547/82-21 on 821011-830131 No noncompliance noted KNOP,R C Region 3, Office of Director 83/03/14 SHIELDS,S W Public Service Co of Indiana, Inc 2pp 17706 196 24X Fiche 50-546,83/03/14,8303280235

--8303280244 IE Insp Repts 50-546/82-21 & 50-547/82-21 on 821011-830131 No noncompliance noted Major areas inspected previous insp findings,erection,nondestructive testing & welding of Unit 1 containment structural steel HARRISON,J J , KONKLIN,J E Region 3, Office of Director 83/03/08 8pp 17706 198 24X Fiche 50-546,83/03/14,8303280235

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 82/03/18 Consolidated Edison Co of New York, Inc 117pp 24X Fiche 50-000,83/03/18,8212060383

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 121pp 17774 352 24X Fiche 50-000,83/03/21,8212060387

R Periodic operating reports & related correspondence

8303100325 Submits daily highlights for facility OL acceptance review completed.Fuel load date of June 1986 projected by applicant O'CONNER,P W Licensing Branch 1 83/02/25 DENTON,H R , CASE,E , CARTER,J Office of Nuclear Reactor Regulation, Director Ip 17504 075 24X Fiche 50-546,83/02/25,8303100325

S Reportable occurrences, LERs & related correspondence

8303150123 Interim deficiency rept re deformed wire anchors separated from embedded plates.Initially reported on 821020.Cause under investigation.Next rept d/e by 830610 SHIELDS,S W Public Service Co of Indiana, Inc 83/03/08 KEPPLER,J G Region 3, Office of Director 2pp 17550 280 24X Fiche 50-546,83/03/08,8303150123

8303150286 Interim deficiency rept re inadequate implementation of QA program.Initially reported on 830211.Commonwealth-Lord Joint Venture addressing util audit.Required corrective actions will be taken.Next rept due by 830520 SHIELDS,S W Public Service Co of Indiana, Inc 83/03/08 KEPPLER,J G Region 3, Office of Director 2pp 17567 054 24X Fiche 50-546,83/03/08,8303150286

8303220020 Interim deficiency rept re welding techniques not covered by Brown-Boveri Electric QA program used in fabrication of safety-related switchgear.Initially reported on 820525.Next rept will be submitted by 830715 SHIELDS,S W Public Service Co of Indiana, Inc 83/03/14 KEPPLER,J G Region 3, Office of Director 2pp 17652 130 24X Fiche 50-546,83/03/14,8303220020

V Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL,holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl EISENHUT,D G Division of Licensing 83/02/24 Consolidated Edison Co of New York, Inc 18pp 24X Fiche 50-000,83/02/24, 8302250505

8303170409 Forwards schedule for site visits to conduct operator licensing exams in response to Generic Ltr 83-01.Exams tentatively scheduled for Mar-May 1986 for Unit 1.Exams for Unit 2 will be requested in early 1987. SHIELDS,S W Public Service Co of Indiana, Inc 83/02/28 KEPPLER,J G Region 3, Office of Director 2pp 17609 278 24X Fiche 50-546,83/02/28,8303170409

DOCKET STN-50-556 BLACK FOX STATION, UNIT 1

A Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982.Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal.Svc list encl. EISENHUT,D G Division of Licensing 83/02/16 Consolidated Edison Co of New York, Inc 18pp 17492 033 24X Fiche 50-000,83/02/16,8302170082

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys.Svc list encl. EISENHUT,D G Division of Licensing 83/03/02 Consolidated Edison Co of New York, Inc 17pp 17700 303 24X Fiche 50-000,83/03/02,8303020321

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel."(clarification of Generic Ltr 82-12). Svc list encl EISENHUT,D G Division of Licensing 83/03/07 Consolidated Edison Co of New York, Inc 51pp 17660 176 24X Fiche 50-000,83/03/07,8303040005

Q Adjudicatory correspondence

8303140071 Response in support of applicant 830123 motion for termination of proceeding & withdrawal of CP application. Soil stabilization & erosion control plan should be implemented.Certificate of Svc encl CHAN,E I Hearing Branch 2 83/02/07 Atomic Safety and Licensing Board Panel 7pp 17540 164 24X Fiche 50-556,83/02/07, 8303140071

8303140045 Response to State of OK 830207 motion for extension to respond to applicant 830123 motion for termination of proceeding & withdrawal of application.NRC does not object. Certificate of Svc encl CHAN,E I Hearing Branch 2 83/02/17 Atomic Safety and Licensing Board Panel 3pp 17540 126 24X Fiche 50-556,83/02/17, 8303140045

8303010177 Response to applicant motion for termination of proceeding & withdrawal of application.State of OK does not intend to file objections to motion.Certificate of Svc encl SINGER,R K , DRAKE,S J Oklahoma, State of 83/02/25 Atomic Safety and Licensing Board Panel 4pp 17341 066 24X Fiche 50-556,83/02/25,8303010177

8303080453 Order granting,w/o prejudice but subj to listed conditions, util 830123 motion to terminate proceeding & withdraw CP application WOLFE,S J Atomic Safety and Licensing Board Panel 83/03/07 Public Service Co of Oklahoma 3pp 17453 301 24X Fiche 50-556,83/03/07,8303080453

H General correspondence

8303300062 Responds to 830302 proposal re closing LPDRs for cancelled or deferred plants.No objection to closing LPDRs for submitted plants.Other LPDRs will remain open pending resolution of CP status. DENTON,H R Office of Nuclear Reactor Regulation, Director 83/03/18 FELTON,J M Division of Rules and Records 3pp 17751 074 24X Fiche 50-000,83/03/18,8303300062

Q Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co of New York, Inc 11lpp 17521 001 24X Fiche 50-000,83/02/25,8212060367

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070 24X Fiche:50-000,83/03/11,8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche:50-000,83/03/18,8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12?pp. 17774:352 24X Fiche:50-000,83/03/21,8212060387.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT,D.G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche:50-000,83/02/24,8302250505.

DOCKET STN-50-557 BLACK FOX STATION, UNIT 2

A. Application/construction stage documents & correspondence

8302170082 Generic Ltr 83-07 to all power & nonpower reactor licensees, applicants for OL & holders of CPs re Nuclear Waste Policy Act of 1982 Section 302 requires owners & generators to contract w/DOE by 830630 for waste disposal. Svc list encl.
EISENHUT,D.G. Division of Licensing 83/02/16 Consolidated Edison Co. of New York, Inc. 18pp. 17492:033 24X Fiche:50-000,83/02/16,8302170082.

8303020321 Generic Ltr 83-13 to all applicants for OLs & holders of CPs for power reactors re clarification of surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys. Svc list encl.
EISENHUT,D.G. Division of Licensing 83/03/02 Consolidated Edison Co. of New York, Inc. 17pp. 17700:303 24X Fiche:50-000,83/03/02,8303020321.

8303040005 Generic Ltr 83-14 to all licensees of operating reactors, applicants for OLs & holders of CPs re definition of "Key Maint Personnel," (clarification of Generic Ltr 82-12). Svc list encl.
EISENHUT,D.G. Division of Licensing 83/03/07 Consolidated Edison Co. of New York, Inc. 5?pp. 17660:176 24X Fiche:50-000,83/03/07,8303040005.

Q. Adjudicatory correspondence

8303140071 Response in support of applicant 830123 motion for termination of proceeding & withdrawal of CP application. Soil stabilization & erosion control plan should be implemented. Certificate of Svc encl.
CHAN,E.I. Hearing Branch 2 83/02/07 Atomic Safety and Licensing Board Panel 7pp. 17540:164 24X Fiche:50-556,83/02/07,8303140071.

8303140045 Response to State of OK 830207 motion for extension to respond to applicant 830123 motion for termination of proceeding & withdrawal of application. NRC does not object. Certificate of Svc encl.
CHAN,E.I. Hearing Branch 2 83/02/17 Atomic Safety and Licensing Board Panel 3pp. 17540:126 24X Fiche:50-556,83/02/17,8303140045.

8303010177 Response to applicant motion for termination of proceeding & withdrawal of application. State of OK does not intend to file objections to motion. Certificate of Svc encl.
BINGER,R.K., DRAKE,S.J. Oklahoma, State of 83/02/25 Atomic Safety and Licensing Board Panel 4pp. 17341:066 24X Fiche:50-556,83/02/25,8303010177.

8303080453 Order grant,ng w/o prejudice but subj to listed conditions, until 830123 motion to terminate proceeding & withdraw CP application.
WOLFE,S.J. Atomic Safety and Licensing Board Panel 83/03/07, Public Service Co. of Oklahoma 3pp. 17453:301 24X Fiche:50-556,83/03/07,8303080453.

H. General correspondence

8303300062 Responds to 830302 proposal re closing LPDRs for cancelled or deferred plants. No objection to closing LPDRs for submitted plants. Other LPDRs will remain open pending resolution of CP status.
DENTON,H.R. Office of Nuclear Reactor Regulation, Director 83/03/18 FELTON,J.M. Division of Rules and Records 3pp. 17751:074 24X Fiche:50-000,83/03/18,8303300062.

Q. Inspection reports, IE Bulletins & correspondence

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11?pp. 17521:001 24X Fiche:50-000,83/02/25,8212060367.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 11?pp. 17611:070 24X Fiche:50-000,83/03/11,8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/18 Consolidated Edison Co. of New York, Inc. 11?pp. 24X Fiche:50-000,83/03/18,8212060383.

8212060387 IE Info Notice 83-13, "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc. 12?pp. 17774:352 24X Fiche:50-000,83/03/21,8212060387.

V. Operator Examinations

8302250505 Generic Ltr 83-12 to all power & nonpower reactor licensees, applicants for OL, holders of CPs & NSSS vendors re issuance of NRC Form 398, "Personal Qualifications Statement - Licensee." Svc list encl.
EISENHUT,D.G. Division of Licensing 83/02/24 Consolidated Edison Co. of New York, Inc. 18pp. 24X Fiche:50-000,83/02/24,8302250505.

DOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

8303010369 Reiterates 830121 request for CP extension until 870901 to permit final decision re future of nuclear units based on load growth/demand. Deferral plan details to be submitted by 830506.
MILLS,L.M. Tennessee Valley Authority 83/02/24 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 2pp. 17345:126 24X Fiche:50-000,83/02/24,8303010369.

S. Reportable occurrences, LERs & related correspondence

8303210679 First interim deficiency rept re transfer switches to auxiliary feedwater w/nondivisional power. Initially reported on 830202. Control power to pressure switches may be provided from standby diesel generators. Next rept expected by 830627.
MILLS,L.M. Tennessee Valley Authority 83/03/02 O'REILLY,J.P. Region 2, Office of Director 3pp. 17635:062 24X Fiche:50-000,83/03/02,8303210679.

8303240525 Final deficiency rept re quality engineering branch unauthorized review of purchase requisitions. Initially reported on 820120. Procedure EN DES-EP 5.01 revised to incorporate procurement specs requiring correct insp.
MILLS,L.M. Tennessee Valley Authority 83/03/17 O'REILLY,J.P. Region 2, Office of Director 3pp. 17684:289 24X Fiche:50-000,83/03/17,8303240525.

8303240406 Final deficiency rept re regional quality engineering branch insp ofc manpower. Initially reported on 820120. QA training completed 830318. Technical training will continue.
MILLS,L.M. Tennessee Valley Authority 83/03/18 O'REILLY,J.P. Region 2, Office of Director 3pp. 17679:012 24X Fiche:50-000,83/03/18,8303240406.

# DOCKETED ITEMS

DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

8303010369 Reiterates 830121 request for CP extension until 870901 to permit final decision re future of nuclear units based on load growth/demand. Deferral plan details to be submitted by 830506.
MILLS, L. M. Tennessee Valley Authority 83/02/24 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17345:126
24X Fiche 50-000, 83/02/24, 8303010369

S. Reportable occurrences, LERs & related correspondence

8303210679 First interim deficiency rept re transfer switches to auxiliary feedwater w/nondivisional power. Initially reported on 830202. Control power to pressure switches may be provided from standby diesel generators. Next rept expected by 830627.
MILLS, L. M. Tennessee Valley Authority 83/03/02 O'REILLY, J. P. Region 2, Office of Director 3pp 17635:062 24X
Fiche 50-000, 83/03/02, 8303210679

8303240525 Final deficiency rept re quality engineering branch unauthorized review of purchase requisitions. Initially reported on 820120. Procedure EN DES-EP 5.01 revised to incorporate procurement specs requiring correct insp.
MILLS, L. M. Tennessee Valley Authority 83/03/17 O'REILLY, J. P. Region 2, Office of Director 3pp 17684:289 24X
Fiche 50-000, 83/03/17, 8303240525

8303240406 Final deficiency rept re regional quality engineering branch insp of manpower. Initially reported on 820120. QA training completed 830318. Technical training will continue.
MILLS, L. M. Tennessee Valley Authority 83/03/18 O'REILLY, J. P. Region 2, Office of Director 3pp 17679:012 24X
Fiche 50-000, 83/03/18, 8303240406

DOCKET STN-50-592 PALO VERDE NUCLEAR STATION, UNIT 4

H. General correspondence

8303300062 Responds to 830302 proposal re closing LPDRs for cancelled or deferred plants. No objection to closing LPDRs for submitted plants. Other LPDRs will remain open pending resolution of CP status.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 83/03/18 FELTON, J. M. Division of Rules and Records 3pp
17751:074 24X Fiche 50-000, 83/03/18, 8303300062

DOCKET STN-50-599 CARROLL FACILITY I

H. General correspondence

8303030528 Informs that DL Farrar has replaced LD DelGeorge as Director of Nuclear Licensing for util. Rev of current NRC distribution list requested.
FARRAR, D. L. Commonwealth Edison Co. 83/02/02 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 17409:048 24X
Fiche 50-000, 83/02/02, 8303030528

DOCKET STN-50-600 CARROLL FACILITY II

H. General correspondence

8303030528 Informs that DL Farrar has replaced LD DelGeorge as Director of Nuclear Licensing for util. Rev of current NRC distribution list requested.
FARRAR, D. L. Commonwealth Edison Co. 83/02/02 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 17409:048 24X
Fiche 50-000, 83/02/02, 8303030528

## DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP., CANOGA PARK, CA

8303140127 Responds to 821013 ltr re revised pages to "SNM Control Program for SEFOR Fuel Decladding." Revs acceptable & effective immediately.
EVANS, L. J. Fuel Facility Safeguards Licensing Branch 82/11/17
REMLEY, M. E. Rockwell International Corp. 2pp 17548:301

8303180049 Responds to query re physical protection requirements. If possession of SNM less than 5 kg per month, matl may be protected by continuing measures of current plan per 10CFR73.67(d). Submission of revised plan not required.
RENTSCHLER, R. R. Fuel Facility Safeguards Licensing Branch
82/11/30 REMLEY, M. E. Rockwell International Corp. 1p 17625:258

8303150060 Issues condition to Amend MPP-1 of License SNM-21, granting limited exemption from requirement to conduct review & audit of contractor measurements performed in Oct 1982, in response to 821104 request.
BURNETT, R. F. Division of Safeguards 82/12/03 REMLEY, M. E. Rockwell International Corp. 1p 17586:302

8303240566 Forwards IE Insp Rept 70-0025/83-01 on 830207-11. No noncompliance noted.
BOOK, H. E. Region 5, Office of Director 83/03/10 REMLEY, M. E. Rockwell International Corp. 4pp 17683:170

--8303240577 IE Insp Rept 70-0025/83-01 on 830207-11. No noncompliance noted. Major areas inspected: organization, facility mods, internal review & audit, safety committee activities, criticality safety & emergency planning.
BROCK, B. L., ZURAKOWSKI, P. R., THOMAS, R. D. Region 5, Office of Director 83/03/09 8pp 17683:174

DOCKET 70-0027 BABCOCK & WILCOX CO., LYNCHBURG, VA

8303170011 Submits discussion of improved proposed methods of reporting matl control & accountability requirements.
KELLY, J. W. Babcock & Wilcox Co. 82/09/20 EVANS, L. J. Fuel Facility Safeguards Licensing Branch 4pp 17624:333

8303150087 Issues condition to Safeguards Amend MPP-1 to License SNM-42, granting 14-day extension to complete Transfer CZA-PCR-3. Measured value rept for matl should be submitted by 821105.
BURNETT, R. F. Division of Safeguards 82/11/15 KELLY, J. W. Babcock & Wilcox Co. 1p 17586:277

8303170318 Approves 821022 request to receive finished fuel plates & elements from DOE facilities based on positive identification & verification of component cladding & measurement overcheck integrity. License SNM-42 amended.
RENTSCHLER, R. R. Fuel Facility Safeguards Licensing Branch
82/11/30 KELLY, J. W. Babcock & Wilcox Co. 3pp 17615:356

8303170357 Grants 821116 request for 7-day delay in starting physical inventory for Nov-Dec 1982 matl balance period. Safeguards Amend MPP-1 to License SNM-42 revised.
RENTSCHLER, R. R. Fuel Facility Safeguards Licensing Branch
82/12/09 KELLY, J. W. Babcock & Wilcox Co. 1p 17615:210

8303160608 Forwards comments on two incomplete items remaining on mods & installation schedule for physical security upgrade const. Mods listed in 820323 & 0720 ltrs acceptable. Ltrs & encls thereto withheld W/o encl.
DUBE, R. J. Fuel Facility Safeguards Licensing Branch 82/12/17
CORDANI, R. A. Babcock & Wilcox Co. 2pp 17603:193

8303160621 Forwards draft Rev 2 to Sections 1.0 - 8.0 of matls & plant protection Amend MPP-1 to License SNM-42 Review requested.
SMITH, C. N. Fuel Facility Safeguards Licensing Branch 82/12/20
CORDANI, R. A. Babcock & Wilcox Co. 5pp 17611:283

8303150090 Advises that compensatory measures to be instituted until completion of defense position relocation acceptable.
DUBE, R. J. Fuel Facility Safeguards Licensing Branch 82/12/30
ECKERT, J. P. Babcock & Wilcox Co. 1p 17586:276

8303010695 Forwards changes to physical security plan agreed upon during 820730 site visit & 820928 & 1021 ltrs. Changes withheld (ref 10CFR2.790).
REGAN, N. A. Babcock & Wilcox Co. 83/01/19 EVANS, L. J. Fuel Facility Safeguards Licensing Branch 1p 17348:339

8303010689 Advises that NA Regan replaces JW Kelly as nuclear safety & licensing officer for naval nuclear fuel div & will be focal contact for NRC correspondence in all areas of licensing.
CORDANI, R. A. Babcock & Wilcox Co. 83/02/03 SMITH, C. N. Fuel Facility Safeguards Licensing Branch 2pp 17348:342

8303020212 Advises that NA Regan is new nuclear safety & licensing officer. All future correspondence should be directed to Regan.
CORDANI, R. A. Babcock & Wilcox Co. 83/02/03 SMITH, C. N. Fuel Facility Safeguards Licensing Branch 1p 17358:005

8303010622 Forwards IE Safeguards Insp Rept 70-0027/83-03 on 830131-0204. No noncompliance noted.
STOHR, J. P. Division of Emergency Preparedness & Materials Safety 83/02/16 ECKERT, J. P. Babcock & Wilcox Co. 2pp 17336:271

--8303010626 IE Safeguards Insp Rept 70-0027/83-03 on 830131-0204 No noncompliance noted Major areas inspected records & repts Details withheld (ref 10CFR2 790)
LANKFORD, J B ; MCALFINE, E J Division of Emergency Preparedness & Materials Safety 83/02/16 1p 17336 273

8303210534 Forwards IE Safeguards Insp Rept 70-0027/83-02 on 830207-10 No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Materials Safety 83/02/28 ECKERT, J P Babcock & Wilcox Co 2pp 17636 357

--8303210544 IE Safeguards Insp Rept 70-0027/83-02 on 830207-10 No noncompliance noted Major areas inspected statistical controls associated w/SNM control & accountability measurements Details withheld (ref 10CFR2 790)
JONES, D W ; RICHARDS, B L Region 2, Office of Director 83/02/28 1p 17636 359

DOCKET 70-0033 TEXAS INSTRUMENTS, INC , ATTLEBORO, MA

8303010026 Forwards "Radiological Survey & Review of TX Instruments Complex, Attleboro, MA " Termination of License SNM-23 requested
VEALE, F J Texas Instruments, Inc 83/01/27 PAGE, R G Uranium Fuel Licensing Branch 1p 17348 204

--8303010036 "Radiological Survey & Review of TX Instruments Complex, Attleboro, MA "
VEALE, F J Texas Instruments, Inc 83/01/17 65pp 17348 205

8303240537 Forwards IE Insp Rept 70-0033/83-01 on 830131-0202 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/03/08 GOETZ, W K Texas Instruments, Inc 2pp 17682 313

--8303240544 IE Insp Rept 70-0033/83-01 on 830131-0202 No noncompliance noted Major areas inspected licensee survey rept & independent measurements in Bldgs 3,4 & 10
ROTH, J ; SMITH, G C Region 1, Office of Director GODY, A T Division of Engineering & Technical Programs 83/03/02 7pp 17682 315

DOCKET 70-0036 COMBUSTION ENGINEERING, INC , WINDSOR, CT

8303150041 Issues condition to Safeguards Amend MPP-3 to License SNM-33, extending reconciliation period for 821201 physical inventory, until 830114, in response to 821214 request
BURNETT, R F Division of Safeguards 82/12/29 ESKRIDGE, H E Combustion Engineering, Inc 1p 17586 316

8303110111 Forwards Rev 1 to application for renewal of License SNM-33, in response to 821229 ltr Requests License 24-16206-01 be canceled & authorization for possession & use of calibr sources be included in License SNM-33
ESKRIDGE, H E Combustion Engineering, Inc 83/02/21 CROW, W T Uranium Fuel Licensing Branch 1p 17526 148

--8303110121 Rev 1 to application to renew License SNM-33
* Combustion Engineering, Inc 83/01/24 48pp 17526 149

8303030697 Recommends issuance of amend to License SNM-33 based on review of 820903 submittal Amend replaces Conditions 12 & 24 re response measures in radiological contingency plan
FISHER, P D Uranium Fuel Licensing Branch 83/02/24 CROW, W T Uranium Fuel Licensing Branch 1p 17364 018

8303100523 Advises of issuance of Amend 9 to License SNM-33 re radiological contingency plan
PAGE, R G Uranium Fuel Licensing Branch 83/03/04 LICHTENBERGER Combustion Engineering, Inc 2pp 17521 284

DOCKET 70-0053 YALE UNIV , NEW HAVEN, CT

8303150547 Forwards IE Safeguards Insp Rept 70-0053/83-01 on 830302-03 & notice of violation Encls withheld (ref 10CFR2 790)
NORDERHAUG, L R Division of Radiological Safety & Safeguards Program 83/03/10 MILLER, J Army, Dept of 2pp 17568 336

DOCKET 70-0113 PENNSYLVANIA STATE UNIV , UNIVERSITY PARK, PA

8303210066 Advises of changes to univ isotopes committee membership & rules & procedures for use of radioactive matl
CUNNINGHAM, R G Pennsylvania State Univ 83/02/15 Office of Nuclear Material Safety & Safeguards, Director 7pp 17660 106

DOCKET 70-0124 TELEDYNE ISOTOPES, INC , WESTWOOD, NJ

8303140440 Ack receipt of 830215 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-0124/83-01
MARTIN, T T Division of Engineering & Technical Programs 83/03/03 SCHUTZ, D F Teledyne Isotopes 1p 17542 236

--8303140450 Responds to NRC 830204 ltr re violation noted in IE Insp Rept 70-0124/83-01 Corrective actions monthly health physics checklist updated to ensure all air flow characteristics performed on timely basis
BLACK, S A Teledyne Isotopes 83/02/15 Region 1, Office of Director 1p 17542 237

DOCKET 70-0135 BABCOCK & WILCOX CO , APOLLO, PA

8303160628 Revises Safeguard Amend MPP-1 to License SNM-145 to allow delay of mgt review of matl control & accounting program from Nov 1982 to Aug 1983, in response to 820618 submittal Licensee 820618 ltr withheld (ref 10CFR2 790)
BURNETT, R F Division of Safeguards 82/10/25 AUSTIN, M A Babcock & Wilcox Co 2pp 17603 288

8303170276 Responds to 821012 telecopy request for limited exemptions from 10CFR70 58(e) & (g)(1) to determine gross weights & evaluate shipper-receiver differences for U hexafluoride cylinders Amend MPP-1 to License SNM-145 issued accordingly
BURNETT, R F Fuel Facility Safeguards Licensing Branch 82/10/26 AUSTIN, M A Babcock & Wilcox Co 2pp 17623 334

8303150066 Issues condition to Amend MPP-1 to License SNM-145, granting extension for reconciling & filing low enriched U physical inventory started on 821123, until 830121, in response to 821029 request
BURNETT, R F Division of Safeguards 82/11/29 AUSTIN, M A Babcock & Wilcox Co 1p 17586 299

8303040528 Forwards IE Safeguards Insp Rept 70-0135/83-01 on 830117-21 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/02/17 COLEMAN, W L Babcock & Wilcox Co 2pp 17366 175

--8303040537 IE Safeguards Insp Rept 70-0135/83-01 on 830117-21 No noncompliance noted Major areas inspected 10CFR21, organization, facility changes & mods, procedure control, internal review & audit, safety committees, training & maint
ROTH, J Region 1, Office of Director GODY, A T Division of Engineering & Technical Programs 83/02/16 10pp 17366 177

8303100329 Forwards IE Safeguards Insp Rept 70-0135/83-02 on 830124-26 No noncompliance noted
MARTIN, T T Division of Emergency Preparedness & Operational Support 83/02/25 COLEMAN, W L Babcock & Wilcox Co 2pp 17489 360

--8303100332 IE Safeguards Insp Rept 70-0135/83-02 on 830124-26 No noncompliance noted Major areas inspected core drilling for depth profile study
ZILBULSKY, N ; GODY, A T Region 1, Office of Director 83/02/22 2pp 17489 362

8303100415 Forwards Amend 19 to Matls License SNM-414, incorporating revised organization & description of organizational responsibilities
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/03/03 AUSTIN, M A Babcock & Wilcox Co 1p 17522 044

--8303100418 SER supporting licensee amend request for revs to Matls Licenses SNM-414 & SNM-415, concerning rev of organizational structure to better reflect current activities Revs provide adequate coverage
BURKHARDT, W ; ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch NIXON, W A Uranium Fuel Licensing Branch 83/03/03 2pp 17522 057

8303310380 Forwards Amend 13 to License SNM-145, incorporating revised organization & description of organizational responsibilities
PAGE, R G Uranium Fuel Licensing Branch 83/03/22 AUSTIN, M A Babcock & Wilcox Co 1p 17796 025

--8303310381 Amend 13 to B&W License SNM-145, incorporating revised organization & description of organizational responsibilities
* Office of Nuclear Material Safety & Safeguards, Director 83/03/22 10pp 17796 026

DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC., ERWIN, TN

8303140303 Ack receipt of 820322 ltr re proposed amend to upgrade physical protection plan. Proposed amend acceptable, however, approval cannot be granted at present time due to certain limitations. Further notification forthcoming.
EVANS, L. J. Fuel Facility Safeguards Licensing Branch 82/10/07.
MICHEL, C. J. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
1p. 17547:359.

8303170272 Approves 820730 rev to Chapter 7.0 of fundamental nuclear matl control plan. Condition 2.1 to License SNM-124 revised to incorporate rev.
EVANS, L. J. Fuel Facility Safeguards Licensing Branch 82/10/14.
HENSLEY, K. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
2pp. 17623:336.

8303110083 Ack receipt of 820601 ltr re rev to current SNM detection searches for personnel exiting matl access areas. Proposed changes acceptable.
EVANS, L. J. Fuel Facility Safeguards Licensing Branch 82/10/20.
MICHEL, C. J. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
1p. 17526:202.

8303140297 Ack receipt of 820830 & 0920 ltrs re revs to Chapters 2 & 8 of fundamental nuclear matl control plan. Proposed revs acceptable. License Condition 2.1 of Amend MPP-1 to License SNM-124 revised.
EVANS, L. J. Fuel Facility Safeguards Licensing Branch 82/10/25.
HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
2pp. 17570:017.

8303110085 Ack receipt of 820922 ltr confirming delay in completing const of & manning new SAS. Compensatory measures acceptable.
EVANS, L. J. Fuel Facility Safeguards Licensing Branch 82/11/12.
MICHEL, C. J. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
1p. 17526:201.

8303150094 Issues new license condition to Amend MPP-1 to License SNM-124, granting 12-day extension for completion of 821013 high enriched U physical inventory, in response to 821109 request. Inventory should be completed by 821124.
BURNETT, R. F. Division of Safeguards 82/11/12. HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 1p.
17586:275.

8303140144 Responds to 821013 ltr re revs to Chapter 1.D of fundamental nuclear matl control plan. Proposed revs acceptable, however, commitment to have SNM shift supervisor present during handling of highly enriched U required.
EVANS, L. J. Fuel Facility Safeguards Licensing Branch 82/11/24.
HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
3pp. 17548:297.

8303170326 Responds to 820830 ltr forwarding Rev 39 to Chapter 4.0 of fundamental nurlear matl control plan. Rev unacceptable since previously approved commitments deleted w/o adequate justification. New rev must be submitted by 830107.
RENTSCHLER, R. R. Fuel Facility Safeguards Licensing Branch 82/11/30. HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 3pp. 17615:351.

8303010702 Forwards Rev 4 to interim security measures implemented 821231 w/revised schedule of implementation for const items. Schedule changes due to problems w/development of software for new sys.
MANSER, W. C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
83/01/13. BURNETT, R. F. Division of Safeguards. 1p. 17348:329.

8303140636 Forwards Rev 49 to Section 7.0 of fundamental nuclear matl control plan. No fees required. Encl withheld (ref 10CFR2.790).
HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
83/01/16. SMITH, C. N. Fuel Facility Safeguards Licensing Branch.
1p. 17569:168.

8303010047 Application for amend of License SNM-124. Details withheld (ref 10CFR2.790 & 10CFR9.5(a)(4)).
HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
83/01/25. RENTSCHLER, R. R. Assistant Director for Licensing. 1p.
17347:358.

8303010699 Application for amend of License SNM-124. Details withheld (ref 10CFR2.790 & 10CFR9.5(a)(4)).
HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
83/01/25. RENTSCHLER, R. R. Assistant Director for Licensing. 1p.
17348:333.

8303010065 Application for amend of License SNM-124. Details withheld (ref 10CFR2.790 & 10CFR9.5(a)(4)).
HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
83/01/28. RENTSCHLER, R. R. Assistant Director for Licensing. 1p.
17322:361.

8303010693 Forwards Jan 1983 Rev 47 to Oct 1982 Rev 43 to fundamental nuclear matl control plan. Changes describe temporary plant organization as result of recent manager death. Rev withheld (ref 10CFR2.790).
HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
83/02/01. SMITH, C. N. Fuel Facility Safeguards Licensing Branch.
1p. 17348:340.

8303010456 Forwards IE Insp Rept 70-0143/82-49 on 821214-17. No noncompliance noted.
STOHR, J. P. Division of Emergency Preparedness & Materials Safety.
83/02/02. MANSER, W. C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 2pp. 17343:114.

--8303010459 IE Insp Rept 70-0143/82-49 on 821214-17. No noncompliance noted. Major areas inspected: emergency preparedness.
CLINE, W. E., JENKINS, G. R. Division of Emergency Preparedness & Materials Safety. 83/01/12. 6pp. 17343:116.

8303010054 Application for amend of License SNM-124. Details withheld (ref 10CFR2.790 & 10CFR9.5(a)(4)).
HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
83/02/07. RENTSCHLER, R. Assistant Director for Licensing. 1p.
17322:362.

8303010089 Application for amend of License SNM-124. Details withheld (ref 10CFR2.790 & 10CFR9.5(9)(4)).
HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
83/02/07. RENTSCHLER, R. R. Assistant Director for Licensing. 1p.
17347:354.

8303110399 Forwards application to amend License SNM-124, consisting of Rev 50 to Section 8.0 of fundamental nuclear matl control plan. Administrative amend fee encl. Attachment withheld (ref 10CFR2.790(d)).
HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
83/02/09. RENTSCHLER, R. R. Fuel Facility Safeguards Licensing Branch. 1p. 17523:058.

8303010464 Forwards IE Safeguards Insp Rept 70-0143/83-04 on 830126-28. No noncompliance noted.
STOHR, J. P. Division of Emergency Preparedness & Materials Safety.
83/02/15. MANSER, W. C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 2pp. 17343:046.

--8303010480 IE Safeguards Insp Rept 70-0143/83-04 on 830126-28. No noncompliance noted. Major areas inspected: MC 85206B measurement control & statistics & followup on previous insp findings. Details withheld (ref 10CFR2.790).
SABADOS, J. W., MCALPINE, E. J. Division of Emergency Preparedness & Materials Safety. 83/02/15. 1p. 17343:048.

8303010584 Forwards IE Safeguards Insp Rept 70-0143/83-03 on 830110-14. No noncompliance noted.
STOHR, J. P. Division of Emergency Preparedness & Materials Safety.
83/02/15. MANSER, W. C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 2pp. 17336:274.

--8303010593 IE Safeguards Insp Rept 70-0143/83-03 on 830110-14. No noncompliance noted. Major areas inspected: statistical controls associated w/nuclear matl control & accountability measurements. Details withheld (ref 10CFR2.790).
JONES, D. W. Region 2, Office of Director. MCALPINE, E. J. Division of Emergency Preparedness & Materials Safety. 83/02/15. 1p.
17336:276.

8303110073 Forwards application for amend to License SNM-124 re safeguards & security measures. Encl withheld (ref 10CFR2.790(d)).
HENSLEY, K. D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.).
83/02/17. RENTSCHLER, R. R. Fuel Facility Safeguards Licensing Branch. 1p. 17526:313.

8303210575 Forwards IE Safeguards Insp Rept 70-0143/83-06 during Jan 1983. No noncompliance noted.
STOHR, J. P. Division of Emergency Preparedness & Materials Safety.
83/02/23. MANSER, W. C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 2pp. 17632:232.

--8303210583 IE Safeguards Insp Rept 70-0143/83-06 during Jan 1983. No noncompliance noted. Major areas inspected: facility operation, changes & mods, criticality safety, radiation, environ & physical protection & SNM control & accounting.
LEE, T. D. Region 2, Office of Director. MCALPINE, E. J. Division of Engineering & Radiological Safety Programs. 83/02/23. 4pp.
17632:234.

8303010296 Answers by TB Cochran to NRC & DOE questions Certificate of Svc encl
COCHRAN, T. B. Affiliation Unknown 83/02/25 Commissioners
21pp 17335:035

8303210606 Ack receipt of 830110 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 70-0143/82-48
STOHR, J. P. Division of Emergency Preparedness & Materials Safety 83/02/25 MANSER, W. C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 1p 17636:302

--8303210619 Forwards IE Safeguards Insp Rept 70-0143/82-48 on 821101-1203 & notice of deviation
GIBSON, A. F. Division of Engineering & Radiological Safety Programs 82/12/15 MANSER, W. C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 2pp 17636:305

--8303210625 Notice of deviation from insp on 821101-1203
* Division of Engineering & Radiological Safety Programs 82/12/15 1p 17636:307

--8303210643 IE Safeguards Insp Rept 70-0143/82-48 on 821101-1203 Noncompliance noted: failure to maintain fire doors on hexanol process control rooms in operable condition at all times
LEE, T. D., MCALPINE, E. J. Region 2, Office of Director 82/12/10 6pp 17636:308

8303020016 Responses to selected NRDC & DOE questions per Commission 830210 order Certificate of Svc encl
FONNER, R. L. Regulations Division 83/03/01 16pp 17353:165

8303020022 Response to NRDC proposed questions, per Commission 830210 order Certificate of Svc encl
BERGHOLZ, W. E. Energy, Dept. of 83/03/01 51pp 17354:149

8303030422 Forwards TB Cochran resume as attachment to Cochran 830225 answers to NRC & DOE questions.
PRATT, B., COCHRAN, T. B. Affiliation Unknown 83/03/01 6pp 17410:115

8303210076 Ack receipt of IE Insp Rept 70-0143/82-49 No proprietary info.
MANSER, W. C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 83/03/01 GIBSON, A. F. Region 2, Office of Director 1p 17636:026

8303070160 Response opposing NRDC objection to ex parte communication & request for remedial action Meeting on 830107 was not improper contact NRDC was not harmed by meeting Certificate of Svc encl
BERGHOLZ, W. E. Energy, Dept. of BERGHOLZ, W. E. Navy, Dept. of 83/03/04 Commissioners 6pp 17432:356

8303100251 Forwards NUSAC Jul 1982 classified rept, "Matl Balance Capability of Process Similar to That at NFS, Inc, Erwin, TN." W/o encl
MALSCH, M. G. Office of the General Counsel 83/03/08 DIRCKS, W. J. Office of the Executive Director for Operations 1p 17485:357

8303210576 Forwards IE Safeguards Insp Rept 70-0143/83-09 on 830222-25 No noncompliance noted.
STOHR, J. P. Division of Emergency Preparedness & Materials Safety 83/03/09 MANSER, W. C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 2pp 17636:360

--8303210580 IE Safeguards Insp Rept 70-0143/83-09 on 830222-25 No noncompliance noted. Major areas inspected: statistical controls associated w/nuclear matl control & accountability measurements Details withheld (ref 10CFR2.790).
RICHARDS, B. L. Region 2, Office of Director MCALPINE, E. J. Division of Emergency Preparedness & Materials Safety 83/03/09 1p 17636:362

8303150360 Responds to 830215 ltr requesting DOE & Dept of Navy allow NRDC access to three classified documents One document declassified & classified info deleted in other documents.
HODEL, D. P. Energy, Dept. of 83/03/10 PALLADINO, N. J. Commissioners 2pp 17562:175

--8303150375 Sanitized "Matl Balance Capability of Process Similar to That at NFS, Erwin, TN."
LUMB, R. F. NUSAC, Inc NRC-19-82-491 745 82/07/31 NRC - No Detailed Affiliation Given 24pp 17562:177

--8303150382 Forwards "Rept on Matl Control & Accountability for Mfg of Naval Fuel," in response to Feb 1980 request No one significant principal cause identified to explain fuel inventory difference performance at NFS.
BATEMAN, W. Energy, Dept. of 81/01/08 AHEARNE, J. F. Commissioners 3pp 17562:201

--8303150386 Unclassified "Rept on Matl Control Accountability for Mfg of Naval Fuel." Certificate of Svc encl
* Energy, Dept. of 81/01/07 27pp 17562:204

8303280236 Ack receipt of 830224 ltr informing NRC of steps taken to correct violation noted in IE Safeguards Insp Rept 70-0143/83-01
STOHR, J. P. Division of Emergency Preparedness & Materials Safety 83/03/14 MANSER, W. C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 1p 17708:139

--8303280241 Responds to NRC 830210 ltr re violation noted in IE Safeguards Insp Rept 70-0143/83-01 Corrective actions withheld
MANSER, W. C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 83/02/24 STOHR, J. P. Division of Emergency Preparedness & Materials Safety 1p 17708:140

--8303280246 Forwards IE Safeguards Insp Rept 70-0143/83-01 on 830117-20 & notice of violation Rept & notice of violation withheld
STOHR, P. Division of Emergency Preparedness & Materials Safety 83/02/10 MANSER, W. C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 2pp 17708:141

8303280276 Forwards IE Safeguards Insp Rept 70-0143/83-07 on 830106-0211 No noncompliance noted.
STOHR, J. P. Region 2, Office of Director 83/03/14 MANSER, W. C. Nuclear Fuel Services, Inc (subs. of Getty Oil Co.). 2pp 17706:234

--8303280284 IE Safeguards Insp Rept 70-0143/83-07 on 830106-0211 No noncompliance noted Major areas inspected: inventory difference performance since Jan 1980 Details withheld (ref 10CFR95).
LEE, T. D., MCALPINE, E. J. Region 2, Office of Director 83/03/10 1p 17706:236

8303170421 Motion to reschedule 830325 oral session to time at least 3 wks later due to unreviewed documents recently released & schedule conflict
WEISS, E. R. Natural Resources Defense Council WEISS, E. R. Harmon & Weiss 83/03/15 Commissioners 12pp 17610:095

8303180203 Response opposing NRDC motion to reschedule oral session. FOIA requests are not substitute for discovery. Inconvenience to counsel does not warrant extension. Certificate of Svc encl
BERGHOLZ, W. E. Energy, Dept. of 83/03/17 Commissioners 12pp 17617:263

8303220365 Order postponing 830325 oral hearing session until 830407.
CHILK, S. J. Office of the Secretary of the Commission 83/03/18 3pp 17942:206

8303240515 PNO-II-83-016 on 830318, Nuclear Fuel Svcs reported inventory difference resulting from 830216 inventory. Caused by loss of matl. Loss within regulatory requirements & calculated limit of error.
MCALPINE, E. J. Region 2, Office of Director 83/03/21 1p 17682:253

DOCKET 70-0146 SPENCER CHEMICAL CO., KANSAS CITY, MO

8303230510 FOIA request for compliance insp rept on 610502-05.
BARNES, C. Affiliation Unknown 83/01/24 FELTON, J. M. Division of Rules and Records 1p 17677:228

8303230503 Responds to FOIA requests for addl documents re Spencer Chemical Co Requested records not located. All documents re Spencer Chemical Co provided per previous FOIA requests.
FELTON, J. M. Division of Rules and Records 83/02/24 BARNES, C. Affiliation Unknown 1p 17677:226

DOCKET 70-0359 PITTSBURGH, UNIV. OF, PITTSBURGH, PA

8303030165 Discusses IE Insp Rpts 30-02945/83-01, 30-14639/83-01, 30-00451/83-01, 30-19122/83-01, 30-07057/83-01, 30-11114/83-01, 30-07060/83-01 & 70-0359/83-01 on 830110-13 & 17 & forwards notice of violation
MARTIN, T. T. Division of Engineering & Technical Programs 83/02/17. WALD, N. Pittsburgh, Univ. of 3pp 17410:327.

--8303030180 Notice of violation from insp on 830110-13 Noncompliance noted failure to perform surveys of corridors & patient rooms implanted w/Cs-137 or Ir-192 brachytherapy sources. * Division of Engineering & Technical Programs 83/02/17 2pp 17410 330

DOCKET 70-0364 BABCOCK & WILCOX CO., APOLLO, PA

8303170363 Approves 821027 request to delete Conditions 9.3.1 & 9.3.2 re decontamination of Pu bldg. from License SNM-414. Area below amounts set forth by conditions requiring protective measures License Section 9.0 amended. RENTSCHLER, R.R. Fuel Facility Safeguards Licensing Branch 82/12/07 AUSTIN, M.A. Babcock & Wilcox Co. 2pp 17615 208

8303150025 Forwards "Radiological Assessment of Parks Township Burial State (B&W), Leechburg, PA." Final rept. ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch FIN A-9093 83/01/05 AUSTIN, M.A. Babcock & Wilcox Co. 1p 17584 247

8303020217 Forwards page revs to Section II of License SNM-414, license drawings & listed manuals. Revs have been made since Jan 1982 submittals. AUSTIN, M.A. Babcock & Wilcox Co. 83/01/21 ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch 64pp 17355 352

--8303020222 "Health & Safety Evaluations Manual." CASSIDONI, R.D., BAUMAN, T.A., SKLINSKI, H. Babcock & Wilcox Co. 82/06/01 80pp 17356 052

--8303020227 "QA Policy & Procedures Manual, Rev 10." JARBADER, R. Babcock & Wilcox Co. 82/11/10 78pp 17356 131

8303100063 Forwards revised pages to Amend 18 to License SNM-414, adding inadvertently deleted authorization to possess U natural or depleted in Pu plant. ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch 83/02/25 AUSTIN, M.A. Babcock & Wilcox Co. 1p 17493 105

--8303100064 Errata to Amend 18 to License SNM-414, adding authorization to possess natural or depleted U in Pu plant. ROUSE, L.C. Office of Nuclear Material Safety & Safeguards, Director 83/02/25 4pp 17493 106

8303100415 Forwards Amend 19 to Matls License SNM-414, incorporating revised organization & description of organizational responsibilities. ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch 83/03/03 AUSTIN, M.A. Babcock & Wilcox Co. 1p 17522 044

--8303100417 Amend 19 to Matls License SNM-414, authorizing incorporation of revised organization & description of organizational responsibilities. LAPUR, P. Division of Fuel Cycle & Material Safety 83/03/03 12pp 17522 045

--8303100418 SER supporting licensee amend request for revs to Matls Licenses SNM-414 & SNM-415, concerning rev of organizational structure to better reflect current activities. Revs provide adequate coverage. BURKHARDT, W., ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch NIXON, W.A. Uranium Fuel Licensing Branch 83/03/03 2pp 17522 057

DOCKET 70-0371 UNC NAVAL PRODUCTS, INC., UNCASVILLE, CT

8303110079 Ack receipt of 820115 ltr re proposed amend to upgrade physical protection plan. Proposed amend acceptable, however, approval cannot be granted presently due to current limitation by Congress. Further notification forthcoming. EVANS, L.J. Fuel Facility Safeguards Licensing Branch 82/10/07 KIRK, W.F. United Nuclear Corp. 1p 17526 290

8303110103 Ack receipt of 820728 ltr re multi-man rule for B-South area. Proposed manning of zones within area acceptable. EVANS, L.J. Fuel Facility Safeguards Licensing Branch 82/10/21 KIRK, W.F. United Nuclear Corp. 1p 17526 201

8303110094 Ack receipt of 820928 ltr re rev to const schedule associated w/security upgrade plan. Request for 60-day extension acceptable. EVANS, L.J. Fuel Facility Safeguards Licensing Branch 82/11/24 KIRK, W.F. United Nuclear Corp. 1p 17546 263

8303150095 Reaffirms licensee obligation to assure adequate safety reviews for storage, clarifying 10CFR73.46 & 73.60. DUBE, R.J. Fuel Facility Safeguards Licensing Branch 82/12/30 KIRK, W.F. United Nuclear Corp. 1p 17586 274

8303020117 Forwards list of approved pages of Annex D to application for renewal of License SNM-368. ALARA info & updated environ info, in response to NRC 821119 request. Security classification of each page in Annex D included. KIRK, W.F. United Nuclear Corp. 83/01/26 CROW, W.T. Uranium Fuel Licensing Branch 310pp 17360 198

8303010696 Advises that physical protection plan for SNM Ref 29 emergency generator sys, P 36 revised to change weekly automatic test of Generator 2 from clock timer to weekly manual tests. Rev withheld (ref 10CFR70.32). GUSTAFSON, H.B. United Nuclear Corp. 83/01/31 RENTSCHLER, R.R. Fuel Facility Safeguards Licensing Branch 1p 17348 338

8303020282 Requests extension of 30-day reconciliation period from 830213 to 830304. Addl time needed due to delay in receipt of lab data pertinent to 830114 inventory. COLLOPY, T.J. United Nuclear Corp. 83/02/10 BROWN, W. Fuel Facility Safeguards Licensing Branch 3pp 17355 316

8303290134 Withdraws 821014 ltr re License SNM-368, in response to NRC requests. Revised partial resubmission on selected priority items shall be made by 830316. Remaining items expected to be submitted within 3 months. KIRK, W.F. United Nuclear Corp. 83/03/02 PAGE, R.G. Division of Fuel Cycle & Material Safety 1p 17730 283

8303160466 Forwards IE Safeguards Insp Rept 70-0371/83-01 on 830131-0204. No noncompliance noted. MARTIN, T.T. Division of Engineering & Technical Programs 83/03/03 AMY, G.D. United Nuclear Corp. 2pp 17592 346

--8303160472 IE Safeguards Insp Rept 70-0371/83-01 on 830131-0204. No noncompliance noted. Major areas inspected: inventory & shipper-receiver verification. ZIBULSKY, H., WOLTNER, E., DELLA RATTA, A. Region 1, Office of Director 83/02/25 2pp 17592 348

8303180321 Forwards "Effluent Monitoring Rept, Jul-Dec 1982." KIRK, W.F. United Nuclear Corp. 83/03/04 HAYNES, R.C. Region 1, Office of Director 1p 17619 341

--8303180326 "Effluent Monitoring Rept, Jul-Dec 1982." * United Nuclear Corp. 83/03/04 1p 17619 342

8303250132 Discusses items of interest for listed facilities. Meeting notices for 830316 & 22 meetings encl. PAGE, R.G. Uranium Fuel Licensing Branch 83/03/17 DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director 3pp 17700 325

8303310034 Proposes meeting to discuss problems associated w/license applications dtd 780322, 810430 & 820224. PAGE, R.G. Uranium Fuel Licensing Branch 83/03/22 AMY, G.D. United Nuclear Corp. 1p 17775 359

DOCKET 70-0553 ARMY, DEPT. OF, SACRAMENTO, CA

8303290384 Notifies that 830309 notice of violation re failure to file matl balance rept withdrawn. Matl balance rept not required for small possession limit authorized by license. NORDERHAUG, L.R. Region 5, Office of Director 83/03/23 MILLER, J. Agriculture, Dept. of 1p 17716 267

DOCKET 70-0734 GA TECHNOLOGIES, INC., SAN DIEGO, CA

8303140278 Notifies of acceptability of Rev B to Category I fixed site facility physical protection plan re protection of formula quantities of SSNM. EVANS, L.J. Fuel Facility Safeguards Licensing Branch 82/11/19 MOWRY, W.R. GA Technologies, Inc./General Atomic Co. 2pp 17547 357

8303150084 Advises that revised fundamental nuclear matls control plan incorporated into License SNM-696, Amend MPP-1, Condition 2.1. Rev withheld (ref 10CFR2.790). DUBE, R.J. Fuel Facility Safeguards Licensing Branch 82/12/15 MOWRY, W.R. GA Technologies, Inc./General Atomic Co. 1p 17586 278

8303010066 Forwards errata to Rev 1 of application to renew License SNM-696, consisting of editorial changes to text. MOWRY, W.R. GA Technologies, Inc./General Atomic Co. 83/02/04 CROW, W.T. Office of Nuclear Material Safety & Safeguards, Director 1p 17355 008

--8303010067 Errata to Rev 1 of application to renew License SNM-696, consisting of editorial changes to text.
* GA Technologies, Inc./General Atomic Co. 83/02/04 32pp. 17355:009.

8303010612 Forwards IE Safeguards Insp Rept 70-0734/83-01 on 830117-21. No noncompliance noted.
NORDERHAUG, L. R. Division of Radiological Safety & Safeguards Program. 83/02/23. PARKER, J. W. GA Technologies, Inc./General Atomic Co. 2pp. 17336:259.

--8303010632 IE Safeguards Insp Rept 70-0734/83-01 on 830117-21. No noncompliance noted. Major areas inspected: nuclear matl control & accounting program. Details withheld (ref 10CFR2.790).
NELSON, G. B., WIEDER, A. V., NORDERHAUG, L. Division of Radiological Safety & Safeguards Program. 83/02/22. 1p. 17336:261.

8303040411 Forwards draft EIA re renewal of License SNM-696 prepared by NRC w/technical assistance of ORNL. W/o encl.
CROW, W. T. Uranium Fuel Licensing Branch. 83/02/28. WARD, J. California, State of. 1p. 17426:351.

8303280248 Forwards IE Safeguards Insp Rept 70-0734/83-05 on 830307-10. No noncompliance noted.
NORDERHAUG, L. R. Region 5, Office of Director. 83/03/22.
PARKER, J. W. GA Technologies, Inc./General Atomic Co. 2pp.
17708:167.

--8303280255 IE Safeguards Insp Rept 70-0734/83-05 on 830307-10. No noncompliance noted. Major areas inspected: independent safeguards insp & measurement control program. Proprietary details withheld (ref 10CFR2.790).
NELSON, G. B., NORDERHAUG, L. R. Region 5, Office of Director. 83/03/21. 1p. 17708:169.

DOCKET 70-0754 GENERAL ELECTRIC CO., PLEASANTON, CA

8303170027 Submits shioping schedule of 28 irradiated fuel rod segments from Millstone Nuclear Station to Pleasanton, CA. Encl withheld (ref 10CFR73.21).
KIRKLAND, M. W. General Electric Co. 83/01/07. JOYNER, J. H. Region 1, Office of Director. 3pp. 17624:315.

8303020151 "Effluent Monitoring & Environ Surveillance Programs, Annual Summary - 1982, Vallecitos Nuclear Ctr."
GEST, R. E., KING, W. H. General Electric Co. 83/01/31. 60pp. 17355:086.

8303010700 Submits details for shipment of 16 irradiated fuel rod segments from Monticello, MN to Pleasanton, CA. GE Model 1600 Cask, Serial 1604 will be transported by Home Transportation Co, Inc. Details withheld (ref 10CFR73.21).
KIRKLAND, M. W. General Electric Co. 83/02/07. Region 3, Office of Director. 3pp. 17348:330.

8303140585 Forwards IE Insp Repts 70-0754/82-03 & 70-0754/82-04 & addl info re decontamination & termination of Pu activities in former advanced fuels lab.
KRATZKE, R. T., ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch. 83/02/28. Advanced Fuel & Spent Fuel Licensing Branch. 2pp. 17569:215.

--8208230089 Requests confirmatory survey re Pu decontamination prior to renovation for U fuels R&D. "Guidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use or Termination. . ." encl.
ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch. 82/08/11.
BOOK, H. E. Division of Radiological Safety & Safeguards Program. 2pp. 17569:251.

8303100419 Forwards evaluation of decontamination & termination of Pu activities in former Advanced Fuels Lab. Commitment by GE that NRC to be notified if Pu introduced into former Advanced Fuels Lab required. W/o encl.
ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch. 83/03/04.
CUNNINGHAM, G. E. General Electric Co. 1p. 17522:043.

DOCKET 70-0820 UNITED NUCLEAR CORP., WOOD RIVER JCT., RI

8303010126 Application for amend of License SNM-777 re frequency of monitoring programs due to decommissioning efforts.
HELGESON, K. A. United Nuclear Corp. 83/01/05. CROW, W. T. NRC - No Detailed Affiliation Given. 3pp. 17322:355.

8303020138 Forwards analysis sheets for test wells for 820101 to present.
HELGESON, K. A. United Nuclear Corp. 83/01/28. CROW, W. T. Office of Nuclear Material Safety & Safeguards, Director. 167pp. 17359:148.

8303180594 Forwards addenda sheets to final survey rept, "Description of Decontamination Methods."
HELGESON, K. A. United Nuclear Corp. 83/01/31. CROW, W. T. Office of Nuclear Material Safety & Safeguards, Director. 17pp. 17640:147.

8303210073 Forwards addenda sheets to final survey rept for Wood River Junction facility.
HELGESON, K. A. United Nuclear Corp. 83/02/14. CROW, W. T. Office of Nuclear Material Safety & Safeguards, Director. 1p. 17660:118.

--8303210078 Addenda sheets to "Final Survey Rept."
* United Nuclear Corp. 83/02/14. 7pp. 17660:119.

8303090104 Comments on 830105 proposal to eliminate or reduce frequency of monitoring requirements, including actions re stack sampling, fixed internal air sampling, air flow monitoring & internal liquid effluent monitoring.
PAGE, R. G. Uranium Fuel Licensing Branch. 83/02/17. HELGESON, K. United Nuclear Corp. 2pp. 17465:020.

8303160635 Submits info re issuance of License SNM-1913 on 830210, 830209 meeting w/WR Grace in Pompton Plains, NJ re site contamination & 830210 meeting w/United Nuclear Corp in Wood River Junction, RI re site decontamination.
PAGE, R. G. Uranium Fuel Licensing Branch. 83/02/17. DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director. 2pp. 17603:191.

8303090222 Advises of issuance of Amend 22 to License SNM-777, revising Section 200 re organization, personnel & administration & Section 400 re health physics stds.
PAGE, R. G. Uranium Fuel Licensing Branch. 83/02/24. GREGG, R. J. United Nuclear Corp. 2pp. 17485:008.

--8303090230 Safety evaluation supporting issuance of Amend 22 to License SNM-777, in response to 820924 proposed mod re organizational & health physics program.
BIDINGER, G. H., CROW, W. T. Uranium Fuel Licensing Branch. 83/02/24. 3pp. 17485:010.

8303160491 Forwards IE Safeguards Insp Rept 70-0820/83-01 on 830202-04 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/04.
AMY, G. D. United Nuclear Corp. 2pp. 17587:285.

--8303160496 Notice of violation from insp on 830202-04.
* Region 1, Office of Director. 83/03/04. 1p. 17587:287.

--8303160503 IE Safeguards Insp Rept 70-0820/83-01 on 830202-04. Noncompliance noted: failure to provide alpha survey meters or hand monitors for use by personnel exiting contamination control zones & failure to issue safety work permit.
ROTH, J. Region 1, Office of Director. GODY, A. T. Division of Engineering & Technical Programs. 83/03/04. 5pp. 17587:288.

8303300397 Forwards IE Safeguards Insp Rept 70-0820/83-02 on 830215-18. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 83/03/17.
AMY, G. D. United Nuclear Corp. 2pp. 17731:066.

--8303300403 IE Safeguards Insp Rept 70-0820/83-02 on 830215-18. No noncompliance noted. Major areas inspected: holdup measurements during decommissioning.
WOLTNER, E., DELLA RATTA, A., ZILBULSKY, H. Region 1, Office of Director. 83/03/16. 2pp. 17731:068.

DOCKET 70-0824 BABCOCK & WILCOX CO., LYNCHBURG, VA

8303150104 Grants extension until 830119 for calculation of unaccounted matl & associated limit of error, per 10CFR70.51. Extension constitutes rev to Amend MPP-1 to License SNM-778.
RENTSCHLER, R. R. Fuel Facility Safeguards Licensing Branch. 82/12/10. OLSEN, A. F. Babcock & Wilcox Co. 2pp. 17600:172.

8303150144 Issues revised condition to License SNM-778, requiring completion of physical inventory difference computation within 5 working days after receipt of data from lab. Limit of error to be calculated by 830119.
SMITH, C. N. Division of Safeguards. 82/12/22. OLSEN, A. F. Babcock & Wilcox Co. 1p. 17597:170.

8303110037 Requests SRP for termination of SNM licenses. Plan submitted during 830131 meeting in Silver Spring, MD will be useful in developing plans for decontamination of Bldg C.
OLSEN, A. F. Babcock & Wilcox Co. 83/02/08. CROW, W. J. Uranium Fuel Licensing Branch. 1p. 17546:267.

8303210225 Forwards "SRP for Termination of SNM Licenses," for guidance in developing & implementing plans to decontaminate Bldg C.
CROW,W.T. Uranium Fuel Licensing Branch 83/03/15 OLSEN,A.P.
Babcock & Wilcox Co. 14pp. 17640:336.

DOCKET 70-1062 TODD SHIPYARDS CORP., GALVESTON, TX

8303140031 Terminates License SNM-1015.
PAGE,R.G. Uranium Fuel Licensing Branch 83/03/04 HATHAWAY,C.W.
Todd Shipyards. 1p. 17548:231.

--8303140039 Safety evaluation supporting termination of License SNM-1015.
BIDINGER,G.H., CROW,W.T. Uranium Fuel Licensing Branch 83/03/04
3pp. 17548:232.

--8303140043 Forwards procedure, "Radiological Survey of Facility Bldg Sumps & Associated Piping," inadvertently omitted from request for unconditional release of piping sys & sumps & for termination of License SNM-1015.
WINTER,C.E. Todd Shipyards 82/09/15 PAGE,R.G. Uranium Fuel Licensing Branch 1p. 17548:235.

--8303140046 Research & technical div procedure, "Radiological Survey of Facility Bldg Sumps & Associated Piping," Rev 0.
* Todd Shipyards 82/05/16 4pp. 17548:236.

DOCKET 70-1100 COMBUSTION ENGINEERING, INC., WINDSOR, CT

8303150022 Issues condition to Amend MPP-4 to License SNM-1067, granting extension for completion of Sept 1982 matl balance rept, in response to 821026 request. Rept should be submitted by 821115.
BURNETT,R.F. Division of Safeguards 82/11/15 LICHENBERGER,H.
Combustion Engineering, Inc. 1p. 17586:324.

8303290766 Forwards renewed License SNM-1067, w/addl conditions per telcon w/RE Sheeran, N Ketilach & Al Soong. Matls & plant protection amend per 10CFR70 & Certificate of Compliance 1100 remain in effect.
PAGE,R.G. Uranium Fuel Licensing Branch 83/03/14 LICHTENBERGER
Combustion Engineering, Inc. 1p. 17746:150.

--8303290774 License SNM-1067 for C-E authorizing use of U in any form; Pu-238 as encapsulated neutron sources & U enriched to U-235 as oxide powder, pellets, rods & finished fuel assemblies per terms of 830514 application.
PAGE,R. Division of Fuel Cycle & Material Safety 83/03/17 6pp.
17746:151.

--8303290777 SER supporting issuance of renewed License SNM-1067.
SOONG,A.L., KETILACH,N., CROW,W.T. Division of Fuel Cycle & Material Safety 83/01/31 56pp. 17746:161.

8303250132 Discusses items of interest for listed facilities. Meeting notices for 830316 & 22 meetings encl.
PAGE,R.G. Uranium Fuel Licensing Branch 83/03/17 DAVIS,J.G.
Office of Nuclear Material Safety & Safeguards, Director
CUNNINGHAM,R.F. Division of Fuel Cycle & Material Safety 3pp.
17700:325.

DOCKET 70-1113 GENERAL ELECTRIC CO., WILMINGTON, NC

8303170268 Responds to 820318 ltr requesting deletion of Condition 2.2 of Amend MPP-3 to License SNM-1097 & changes to App C of fundamental nuclear matl control plan. Deletion of License Condition 2.2 approved. Revised page to App C requested.
EVANS,L.J. Fuel Facility Safeguards Licensing Branch 82/10/21
VAUGHAN,C.M. General Electric Co. 2pp. 17623:338.

8303150076 Issues condition to Amend MPP-3 to License SNM-1097, granting extension for submittal of safeguards audit, in response to 820907 request. Audit, initially scheduled to be completed in Sept 1982 should be completed by 821231.
BURNETT,R.F. Division of Safeguards 82/10/28 VAUGHN,C.M.
General Electric Co. 1p. 17586:279.

8303140135 Ack receipt of 821117 ltr transmitting revised P C-1 to fundamental nuclear matl control plan. Prior NRC approval of change expressed in NRC 821021 ltr.
EVANS,L.J. Fuel Facility Safeguards Licensing Branch 82/11/26
VAUGHN,C.M. General Electric Co. 1p. 17548:300.

8303010304 Responds to NRC 820615 ltr re violations noted in IE Insp Rept 70-1113/82-10. Corrective actions: special audit personnel retrained & discussions re proper survey techniques conducted.
VAUGHAN,C.M. General Electric Co. 82/12/15 GIBSON,A.F. Division of Engineering & Radiological Safety Programs 2pp. 17333:332.

8303170370 Responds to 820406 & 1118 ltrs w/revised pages to fundamental nuclear matl control plan. Proposed revs to Condition 2.1 to License SNM-1097 acceptable. Encls to ltrs withheld (ref 10CFR2.790).
DUBE,R.J. Fuel Facility Safeguards Licensing Branch 82/12/15
VAUGHAN,C.M. General Electric Co. 2pp. 17615:206.

8303010614 Forwards IE Safeguards Insp Rept 70-1113/83-02 on 830111-14. No noncompliance noted.
STOHR,J.P. Division of Emergency Preparedness & Materials Safety
83/02/15 LONG,J.A. General Electric Co. 2pp. 17336:262.

--8303010621 IE Safeguards Insp Rept 70-1113/83-02 on 830111-14. No noncompliance noted. Major areas inspected: measurements & statistical controls, independent insp effort & followup on previous insp findings. Details withheld (ref 10CFR2.790).
BATES,J.W., MCALPINE,E.J. Division of Emergency Preparedness & Materials Safety 83/02/15 1p. 17336:264.

8303210360 Forwards IE Insp Rept 70-1113/83-04 on 830207-11. No noncompliance noted.
STOHR,J.P. Division of Emergency Preparedness & Materials Safety
83/02/25 LONG,J.A. General Electric Co. 2pp. 17634:291.

--8303210363 IE Insp Rept 70-1113/83-04 on 830207-11. No noncompliance noted. Major areas inspected: operations, facility changes & mods, training, maint & safety committees.
CORYELL,G.P. Region 2, Office of Director MCALPINE,E.J.
Division of Emergency Preparedness & Materials Safety 83/02/24
5pp. 17634:293.

8303210452 Ack receipt of IE Insp Rept 70-1113/83-04 on 830207-11. No proprietary info.
VAUGHAN,C.M. General Electric Co. 83/03/09 STOHR,J.P. Region 2, Office of Director 1p. 17634:251.

8303210594 Forwards IE Safeguards Insp Rept 70-1113/83-07 on 830222-25. No noncompliance noted.
STOHR,J.P. Division of Emergency Preparedness & Materials Safety
83/03/14 LONG,J.A. General Electric Co. 2pp. 17636:354.

--8303210600 IE Safeguards Insp Rept 70-1113/83-07 on 830222-25. No noncompliance noted. Major areas inspected: measurement control program & verification of SNM export shipments. Details withheld (ref 10CFR2.790).
BATES,J.W., MCALPINE,E.J. Region 2, Office of Director 83/03/11
1p. 17636:356.

DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP., PITTSBURGH, PA

8303210330 PNO-I-83-019 on 830315, health physics technician injured when hoist lifting cut section of glovebox malfunctioned & dropped piece, causing 7-8 inch slash to left thigh above knee. Individual hospitalized.
ROTH,J., GODY,A.T. Region 1, Office of Director 83/03/16 1p.
17632:116.

DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP., PITTSBURGH, PA

8303170338 Approves 821025 request for partial exemption from 10CFR70.51(e)(1)(iv), Condition 7.3 to Amend MPP-1 to License SNM-1107 issued. Ltr of 821025 withheld (ref 10CFR2.790).
RENTSCHLER,R.R. Fuel Facility Safeguards Licensing Branch
82/12/01 NARDI,A.J. Westinghouse Electric Corp. 1p. 17615:213.

8303210364 Forwards IE Safeguards Insp Rept 70-1151/83-04 on 830131-0204. No noncompliance noted.
STOHR,J.P. Division of Emergency Preparedness & Materials Safety
83/02/23 D'AMORE,M. Westinghouse Electric Corp. 2pp. 17635:029.

--8303210369 IE Safeguards Insp Rept 70-1151/83-04 on 830131-0204. No noncompliance noted. Major areas inspected: MC 85206 measurements & statistical controls (new waste assay meter). Details withheld (ref 10CFR2.790).
CLAY,E.L., MCALPINE,E.J. Division of Emergency Preparedness & Materials Safety 83/02/23 1p. 17635:031.

DOCKET 70-1193 KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK

8303240037 FOIA request for NRC insp repts & safety violations noted at Kerr-McGee Pu plant from Aug 1972 to Nov 1974
WIDMER, R R Affiliation Unknown 82/12/27 HENDRIE, J M Commissioners 1p 17694:301

8303240040 Partial response to FOIA request for NRC insp repts & safety violations noted at Kerr-McGee Pu plant from Aug 1972 to Nov 1974 Documents listed in App A available in PDR
FELTON, J M Division of Rules and Records 83/02/17 WIDMER, R R Affiliation Unknown 3pp 17695:302

--8303240046 Ack receipt of 731120 ltr re Kerr-McGee Cimarron Pu plant Environ review site analysis addresses probabilities of floods & tornadoes Allegations of malfeasance investigated by Directorate of Regulatory Operations
CHITWOOD, R B Atomic Energy Commission, Directorate of Licensing 73/12/19 YOUNGHEIN, J Affiliation Unknown 2pp 17695:305

--8303240050 Discusses concerns re radwaste leak at facility Risks involving operation of facility should be discussed w/public
YOUNGHEIN, I H., YOUNGHEIN, G A Affiliation Unknown 73/10/01
BRUNER, E J Atomic Energy Commission 3pp 17695:307

--8303240055 Comments on AEC insp repts & related AEC correspondence w/Kerr-McGee Corp Concerns re design & operation of facility expressed Public right-to-know abridged
YOUNGHEIN, I., YOUNGHEIN, G Affiliation Unknown 73/10/09
Atomic Energy Commission 7pp 17695:310

--8303240060 Discusses 731203 & 05 telcons w/T Cochran & Tamplin re Youngheims concerns on 730818 waste drum leak at facility
FIORELLI, G Region 3, Chicago, Office of the Director 74/01/10
Region 3, Chicago, Office of the Director 3pp 17695:317

8303160702 Forwards renewed License SNM-1174
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/03/03
SHELLEY, W J Kerr-McGee Nuclear Corp 2pp 17600:233

--8303160704 SNM License SNM-1174, renewed for 5-yr term expiring 880331, authorizing receipt, possession, use, storage & transfer of Pu, U & Cs-137 for purposes of decontamination & decommissioning activities
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/03/03
3pp 17600:235

--8303160707 Safety evaluation supporting renewal of License SNM-1174
BURKHARDT, H., ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/03/03 7pp 17600:244

DOCKET 70-1201 BABCOCK & WILCOX CO., LYNCHBURG, VA

8303170342 Approves 820421 & 0802 revised pages to phyrical protection plan Attachments to ltrs withheld (ref 10CFR2.790)
RENTSCHLER, R R Fuel Facility Safeguards Licensing Branch 82/12/03 FORD, J T Babcock & Wilcox Co 1p 17615:212

8303150050 Issues revised Safeguards Amend MPP-2 to License SNM-1168, deleting & changing license conditions re fundamental nuclear matl shipper-receiver differences
BURNETT, R F Division of Safeguards 82/12/21 FORD, J T Babcock & Wilcox Co 2pp 17586:307

8303150054 Issues condition to Safeguards Amend MPP-2 to License SNM-1168, granting 14-day delay in starting next physical inventory, in response to 821213 request Licensee may start next physical inventory by 830207
BURNETT, R F Division of Safeguards 82/12/21 FORD, J T Babcock & Wilcox Co 1p 17586:306

8303020123 "Gaseous & Liquid Effluent Monitoring Rept for Jul-Dec 1982 "
SPEIGHT, C W Babcock & Wilcox Co 83/01/24 KETZLACH, N Uranium Fuel Licensing Branch 2pp 17359:317

8303010692 Requests exemption from listed sections of fundamental nuclear matl control plan for shutdown period Encl withheld (ref 10CFR2.790)
* Babcock & Wilcox Co 83/01/28 SMITH, C N Fuel Facility Safeguards Licensing Branch 1p 17348:341

8303090656 Application for amend to License SNM-1168, requesting approval of exemptions during shutdown period of 830618-1016
FORD, J T Babcock & Wilcox Co 83/01/28 PAGE, R G Uranium Fuel Licensing Branch 5pp 17480:275

8303100514 Confirms approach to license exemptions & mods for fuel certification gap during Summer 1983 developed at 830215 meeting Vendor to notify U Fuel Licensing Branch & Region II within 1 working day of renewed licensed activity
FORD, J T Babcock & Wilcox Co 83/02/22 PAGE, R G Uranium Fuel Licensing Branch 1p 17521:312

8303110126 Forwards revised pages to application to renew License SNM-1168 & certification of ANI Policy NF-111 & MAELU Policy MF-85
FORD, J T Babcock & Wilcox Co 83/02/24 PAGE, R G Uranium Fuel Licensing Branch 1p 17526:082

--8303110133 Revised pages to application to renew License SNM-1168 Certification of ANI Policy NF-111 & MAELU Policy MF-85 encl
* Babcock & Wilcox Co 83/02/24 4pp 17526:083

8303150007 Forwards Rev 1 to "Effluent Monitoring Rept, Jul-Dec 1982 " Rev 1 supersedes rept sent 830124
SPEIGHT, C W Babcock & Wilcox Co 83/02/28 Region 2, Office of Director 1p 17597:151

--8303150014 Rev 1 to "Effluent Monitoring Rept, Jul-Dec 1982 "
SPEIGHT, C W Babcock & Wilcox Co 83/02/22 1p 17597:152

DOCKET 70-1216 NAVY, DEPT. OF, SAN DIEGO, CA

8303150231 Forwards IE Safeguards Insp Rept 70-1216/83-01 on 830302 & 03 Rept withheld (ref 10CFR2.790)
NORDERHAUG, L R Region 5, Office of Director 83/03/10
LUNDBERG, R E San Diego State College 2pp 17568:317

DOCKET 70-1257 EXXON NUCLEAR CO., INC., RICHLAND, WA

8303140299 Determines that approval of proposed changes to "Nuclear Matls Safeguards Procedures Description for Fuel Fabrication Plants," does not affect common defense or security Amend MPP-2 to License SNM-1227 modified to reflect changes
EVANS, L J Fuel Facility Safeguards Licensing Branch 82/10/14
SCHNEIDER, R A Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 2pp 17547:360

8303170351 Approves 821118 revs to fundamental nuclear matl control plan License Condition 2.1 to Amend MPP-2 to License SNM-1227 revised Attachments to ltrs withheld (ref 10CFR2.790)
RENTSCHLER, R R Fuel Facility Safeguards Licensing Branch 82/12/07 SCHNEIDER, R A Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 1p 17615:211

8303210781 Application for amend of License SNM-1227, to allow flexibility in managing Pu-contaminated gloveboxes in source factor bldg & to update license conditions consistent w/current Pu inventories
MALODY, C W Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 83/02/08 CROW, W T Division of Fuel Cycle & Material Safety 5pp 17640:277

8303240555 Forwards IE Safeguards Insp Rept 70-1257/83-01 on 830207-11 No noncompliance noted
NORDERHAUG, L R Region 5, Office of Director 83/03/21 NILSON, R Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 2pp 17682:221

--8303240564 IE Safeguards Insp Rept 70-1257/83-01 on 830207-11 No noncompliance noted Major areas inspected: organization & operations, measurement control program & shipper-receiver verification Details withheld (ref 10CFR2.790)
NELSON, G B., WIEDER, A V., NORDERHAUG, L Region 5, Office of Director 83/03/21 1p 17682:223

DOCKET 70-1308 GENERAL ELECTRIC CO., SAN JOSE, CA

8303030567 Forwards IE Insp Rept 72-0001/83-01 on 830111-13 & 24 No noncompliance noted
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support 83/02/15 VAN HOOMISSEN General Electric Co. 2pp 17409:031

--8303030584 IE Insp Rept 72-0001/83-01 on 830111-13 & 24 No noncompliance noted Major areas inspected: fuel receipt & storage, radiation protection, surveillance tests, safety committees, emergency planning & environ monitoring
PECK, C C., JANUSKA, A G., GREGER, L R Region 3, Office of Director 83/02/14 6pp 17409:033

8303100568 "Airborne Effluents Released to Environ During CY82."
EGER, K. J. General Electric Co. 83/02/17 Region 3, Office of Director 2pp 17521:348

DOCKET 70-1507 HENRY FORD HOSP., DETROIT, MI

8303010319 Discusses IE insp of Licenses 21-04109-16, 21-04109-08 & SNM-1456 on 830208-10 & forwards notice of violation.
SRENIAWSKI, D. J. Region 3, Office of Director 83/02/24
CENTURIONE, D. J. Henry Ford Hos p, Detroit, MI 2pp 17345:214

--8303010325 Notice of violation from insp on 830208-10 Noncompliance noted: failure to calibr survey meters annually & monitor Xe-133 traps monthly.
SRENIAWSKI, D. J. Region 3, Office of Director 83/02/24 2pp 17345:216

DOCKET 70-1621 DUQUESNE LIGHT CO., PITTSBURGH, PA

8303110275 Forwards Endorsement 62 to NELIA Policy NF-226.
BARNETT, J. E. Conover & Associates, Inc Insurance 83/03/08
DINITZ, I. Antitrust & Economic analysis Branch (Utility Finance) 2pp 17515:353

DOCKET 70-2322 EDLOW INTERNATIONAL CO., WASHINGTON, DC

8303110072 Requests extension of route approval for transport of spent reactor fuel per NRC 820618 ltr.
SHAW, A. Edlow International Co. 83/02/15 HILLMAN, C. NRC - No Detailed Affiliation Given. 3pp 17526:314

DOCKET 70-2684 BAYSTATE MEDICAL CENTER, SPRINGFIELD, MA

8303140129 Responds to FOIA request for most recent onsite insps for Matl/Byproduct Licenses 20-01412-03, 20-01412-05 & 20-01412-06. Forwards documents listed in App A.
FELTON, J. M. Division of Rules and Records 83/02/18
ROSENBAUM, P. J. Affiliation Unknown 2pp 17572:213

--8303140145 Discusses insp of Licenses SNM-1766, 20-01412-05, 20-01412-06 & 20-01495-03 on 780615 & 16 & forwards notice of violation. License SNM-1766 inactive.
MCCLINTOCK, R. O. Region 1, Philadelphia, Office of the Director 78/07/11 GIFFORD, H. C. Baystate Medical Center Springfield, MA 2pp 17572:227

--8303140165 Ack receipt of 780720 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-2684/78-01, 30-09946/78-01, 30-12395/78-01 & 30-00231/78-01.
MCCLINTOCK, R. O. Region 1, Philadelphia, Office of the Director 78/08/01 GIFFORD, H. C. Baystate Medical Center Springfield, MA 1p 17572:249

--8303140173 Responds to NRC 780711 ltr re violations noted in IE Insp Repts 70-2684/78-01, 30-12395/78-01 & 30-00231/78-01. Corrective actions complete: insp of isotope program at Wesson Memorial Hosp performed monthly.
KERRIGAN, G. A. Baystate Medical Center Springfield, MA 78/07/20
MCCLINTOCK, R. O. Region 1, Philadelphia, Office of the Director 1p 17572:250

--8303140184 IE Insp Rept 70-2684/79-01 on 790306 Noncompliance noted: failure to survey for contamination in shipping containers & on swabs prior to disposal; secure licensed matl & post radiation area.
MCCLINTOCK, R. O. Region 1, Philadelphia, Office of the Director 79/03/15 10pp 17572:267

DOCKET 70-2786 GENERAL ELECTRIC CO., SAN JOSE, CA

8303030349 Forwards info requesting route approval, per 10CFR73, for shipment of irradiated reactor fuel in Aug 1983 from Richmond to Pleasanton, CA.
KIRKLAND, M. W. General Electric Co. 83/01/26 HILLMAN, C. R. Office of Nuclear Material Safety & Safeguards, Director 8pp 17364:356

DOCKET 70-2837 MORNINGSIDE COLLEGE, SIOUX CITY, IA

8302010356 Discusses IE insp of License SNM-1825 on 830114 & forwards notice of violation.
WIEDEMAN, D. G. Region 3, Office of Director 83/01/26
TOMMERAASEN, M. Morningside College 1p 16973:331

--8302010358 Notice of violation from insp on 830114 Noncompliance noted: sealed source containing Pu-239 not tested regularly for contamination or leakage.
WIEDEMAN, D. G. Region 3, Office of Director 83/01/26 1p 16973:332

8303170448 Ack receipt of 830221 ltr informing NRC of steps taken to correct violations noted in IE insp of activities conducted under License SNM-1825.
WIEDEMAN, D. G. Region 3, Office of Director 83/03/10 GREEN, R. W. Morningside College 1p 17609:208

--8303170455 Responds to NRC 830126 ltr re violations noted in IE insp of activities conducted under License SNM-1825. Corrective actions: paper smear tests on source will be conducted every 6 months.
GREEN, R. W. Morningside College 83/02/21 WIEDEMAN, D. G. Region 3, Office of Director 2pp 17609:209

DOCKET 70-2910 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN

8303020376 Application for amend of Licenses SNM-1861 & SNM-1873, deleting ref to two fire truck pumpers as part of plant fire protection sys.
MILLS, L. M. Tennessee Valley Authority 83/01/27 CROW, W. T. Division of Fuel Cycle & Material Safety 1p 17357:345

8303180523 Advises of issuance of Amend 4 to License SNM-1861, revising requirements for fire protection sys.
PAGE, R. G. Uranium Fuel Licensing Branch 83/03/11 MILLS, L. M. Tennessee Valley Authority 1p 17640:223

--8303180526 Safety evaluation supporting Amend 4 to License SNM-1861.
BIDINGER, G. H. , CROW, W. T. Uranium Fuel Licensing Branch 83/03/11 1p 17640:224

DOCKET 70-2917 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN

8303020340 Application for amend of License SNM-1865, extending expiration date to 860531.
MILLS, L. M. Tennessee Valley Authority 83/01/26 CROW, W. T. Division of Fuel Cycle & Material Safety 1p 17357:348

8303110067 Issues Amend 2 to License SNM-1865, extending license expiration date from 830331 to 860531 or upon issuance of OL to Bellefonte Unit 1.
PAGE, R. G. Uranium Fuel Licensing Branch 83/03/02 MILLS, L. M. Tennessee Valley Authority 1p 17526:329

--8303110069 Safety evaluation supporting Amend 2 to License SNM-1865, extending license expiration date from 830331 to 860531 or upon issuance of OL to Bellefonte Unit 1.
BIDINGER, G. H. Uranium Fuel Licensing Branch 83/03/02 1p 17526:330

DOCKET 70-2920 ALABAMA POWER CO., BIRMINGHAM, AL

8303110370 Advises that all nuclear matl covered by License SNM-1868 now covered by License NPF-8 issued 810331. Requests termination of License SNM-1868.
CLAYTON, F. L. Alabama Power Co. 83/02/07 CUNNINGHAM, R. E. Licensing Management Branch 1p 17523:055

DOCKET 70-2926 DETROIT EDISON CO., DETROIT, MI

8303290001 Rev 4 to "Licensing Input in High Density Spent Fuel Racks for Fermi II Project."
SINGH, K. P. Joseph Oat Corp. TURNER, S. Southern Science Applications, Inc. TM-586 R.4 82/01/22 105pp 17730:067

8303220484 Forwards Rev 2 to application for license to receive, possess, repackage for shipment, transfer & store SNM.
TAUBER, H. Detroit Edison Co. 83/02/28 SERINI, B. L. Uranium Fuel Licensing Branch 8pp 17670:286

--8303220485 Rev 2 to application for license to receive, possess, repackage for shipment, transfer & store SNM.
* Detroit Edison Co. 83/02/28 32pp 17670:294

DOCKET 70-2928 TENNESSEE VALLEY AUTHORITY

8303020376 Application for amend of Licenses SNM-1861 & SNM-1873, deleting ref to two fire truck pumpers as part of plant fire protection sys.
MILLS, L. M. Tennessee Valley Authority 83/01/27 CROW, W. T. Division of Fuel Cycle & Material Safety 1p 17357:345

8303110162 Approves 830127 request for amend to License SNM-1873, authorizing rev of requirements for fire protection sys. SER encl.
PAGE, R. G. Uranium Fuel Licensing Branch 83/03/04 MILLS, L. M. Tennessee Valley Authority 1p 17520:357

--8303110165 SER supporting 830127 application for amend to License SNM-1873, revising fire protection sys.
BIDINGER, G. H. ; CROW, W. T. Uranium Fuel Licensing Branch 83/03/04 1p 17520:358

DOCKET 70-2932 TEXAS UTILITIES GENERATING CO., DALLAS, TX

8303040321 Forwards License SNM-1912 for TX Utils Generating Co, authorizing receipt, possession, insp & storage of U-235 contained in fuel assemblies.
PAGE, R. G. Uranium Fuel Licensing Branch 83/02/14 GARY, R. J. Texas Utilities Generating Co 2pp 17426:288

--8303040326 License SNM-1912 for TX Utils Generating Co, authorizing receipt, possession, insp & storage of U-235 contained in fuel assemblies.
CROW, W. T. Office of Nuclear Material Safety & Safeguards, Director 83/02/14 2pp 17426:290

--8303040331 Safety evaluation supporting issuance of License SNM-1912.
METZLACH, N. Uranium Fuel Licensing Branch CROW, W. T. Office of Nuclear Material Safety & Safeguards, Director 83/02/14 9pp 17426:292

8303100527 Advises of issuance on 830214 of License SNM-1912, authorizing receipt, possession, insp & storage of U-enriched in U-235 isotope. Westinghouse 830216 meeting re radioactive groundwater contamination & NRC talking paper discussed.
PAGE, R. G. Uranium Fuel Licensing Branch 83/02/23 DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director 2pp 17521:280

DOCKET 70-2941 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN

8303170332 Approves 821020 rev to fuel storage physical security plan for protection of low strategic SNM.
RENTSCHLER, R. R. Fuel Facility Safeguards Licensing Branch 82/11/29 MILLS, L. M. Tennessee Valley Authority 1p 17615:220

DOCKET 70-2945 UNION ELECTRIC CO., ST. LOUIS, MO

8303030508 Ack receipt of 830201 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 70-2945/82-01.
MILLER, J. R. Division of Engineering 83/02/24 SCHNELL, D. F. Union Electric Co. 1p 17409:059

--8303030521 Responds to NRC 830111 ltr re violations noted in IE Safeguards Insp Rept 70-2945/82-01 on 821216-17. Details withheld (ref 10CFR73.21).
SCHNELL, D. F. Union Electric Co. 83/02/01 MILLER, J. R. Division of Engineering 2pp 17409:060

DOCKET 70-2946 LOUISIANA POWER & LIGHT CO., NEW ORLEANS, LA

8303140282 Ack receipt of 820628 ltr re rev to "Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance." Rev acceptable. Provisions of plan should be in effect whenever fresh fuel stored on site.
EVANS, L. J. Fuel Facility Safeguards Licensing Branch 82/11/26
MAURIN, L. V. Louisiana Power & Light Co. 1p 17547:356 24X Fiche. 50-382. 82/11/26. 8303140282

8303030013 Forwards util course of action re 100% neutron attenuation testing of spent fuel storage racks or alternative method of assuring that fuel will not achieve critical configuration should poison be missing.
MAURIN, L. V. Louisiana Power & Light Co. 83/01/20 Office of Nuclear Material Safety & Safeguards, Director 4pp 17426:159

8303010669 Forwards addl info re administrative controls for storage of fuel in spent fuel pool, in response to NRC 830124 request. Controls will be in effect until 100% neutron attenuation testing completed.
MAURIN, L. V. Louisiana Power & Light Co. 83/01/24 Office of Nuclear Material Safety & Safeguards, Director 4pp 17348:348

8303020122 Forwards Endorsement 9 to NELIA Policy NF-263.
MAURIN, L. V. Louisiana Power & Light Co. 83/01/26 Office of Nuclear Material Safety & Safeguards, Director 9pp 17359:319

8303180127 Unexecuted Indemnity Agreement B-92.
SALTZMAN, J. Assistant Director for State & Licensee Relations 83/02/09 13pp 17625:149

8303010703 Forwards revised pages of application to amend License SNM-1913. Submittal clarifies operational status of fire protection program.
MAURIN, L. V. Louisiana Power & Light Co. 83/02/14 Office of Nuclear Material Safety & Safeguards, Director 4pp 17348:324

8303160635 Submits info re issuance of License SNM-1913 on 830210, 830209 meeting w/WR Grace in Pompton Plains, NJ re site contamination & 830210 meeting w/United Nuclear Corp in Wood River Junction, RI re site decontamination.
PAGE, R. G. Uranium Fuel Licensing Branch 83/02/17 DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director 2pp 17603:191

8303220459 Forwards revised page to application for amend of License SNM-1913, correcting logistical problem re verification of storage locations in spent fuel pool.
MAURIN, L. V. Louisiana Power & Light Co. 83/02/21 Office of Nuclear Material Safety & Safeguards, Director 1p 17670:155

--8303220470 Revised page to application for amend of License SNM-1913, correcting logistical problem re verification of storage locations in spent fuel pool.
* Louisiana Power & Light Co. 83/02/21 1p 17670:156

8303180133 Advises of issuance of Amend 1 to License SNM-1913. Conditions 9 & 18 re fuel handling operations.
PAGE, R. G. Uranium Fuel Licensing Branch 83/03/09 MAURIN, L. V. Louisiana Power & Light Co. 2pp 17625:126

--8303180136 Safety evaluation supporting Amend 1 to License SNM-1913.
SERINI, B. L. ; CROW, W. T. Uranium Fuel Licensing Branch 83/03/09 3pp 17625:128

DOCKET 70-2949 ARIZONA PUBLIC SERVICE CO., PHOENIX, AZ

8303010720 Unexecuted Indemnity Agreement B-95 between NRC & AZ Public Svc Co, Southern CA Edison Co, Public Svc Co of NM, El Paso Electric Co, Southern CA Public Power Authority & Salt River Project Agricultural Improvement & Power District.
SALTZMAN, J. Assistant Director for State & Licensee Relations 83/01/26 13pp 17354:291

8303290249 Forwards executed Indemnity Agreement B-95.
ANDOGNINI, G. C. Arizona Public Service Co. 83/03/02 Office of Nuclear Material Safety & Safeguards, Director 14pp 17729:149

DOCKET 70-2950 WASHINGTON PUBLIC POWER SUPPLY SYSTEM, RICHLAND, WA

8303110089 Ack receipt of 821022 ltr re amend of Condition 3 of 820817 supplemental physical security conditions for 820716 fuel storage physical security plan. Revised commitment acceptable. Encl withheld (ref 10CFR2.790(d)).
EVANS, L. J. Fuel Facility Safeguards Licensing Branch 82/11/10
BOUCHEY, G. D. Washington Public Power Supply System 1p 17526:280 24X Fiche. 50-397. 82/11/10. 8303110089.

8303210069 Confirms 830202 telcon understanding of Condition 18 of License SNM-1890 requirement re leak testing of sealed byproduct matl sources. Certificate of testing will be received from source vendor.
BOUCHEY, G. D. Washington Public Power Supply System 83/02/23
Office of Nuclear Material Safety & Safeguards, Director 1p 17660:113

DOCKET 70-2957 FLORIDA POWER & LIGHT CO., MIAMI, FL

8303210779 Application for amend of License SNM-1902, to include fire protection program & fuel handling bldg fire protection sys.
UHRIG, R. E. Florida Power & Light Co. 83/02/25 PAGE, R. G. Uranium Fuel Licensing Branch 7pp 17640:282

DOCKET 70-2960 KANSAS GAS & ELECTRIC CO., WICHITA, KS

8303110098 Requests addl info re interim security plan within 30 days. Electrical breaker lock referred to in Section 1.2.8 should be described along w/procedures controlling lock.
EVANS, L. J. Fuel Facility Safeguards Licensing Branch 82/11/24
KOESTER, G. L. Kansas Gas & Electric Co. 2pp. 17526:215. 24X Fiche 50-482. 82/11/24. 8303110098

DOCKET 70-2964 CONSUMERS POWER CO., JACKSON, MI

8303150100 Approves plant security plan for protection of SNM of low strategic significance, per 10CFR73.27(f)(g).
DUBE, R. J. Fuel Facility Safeguards Licensing Branch 82/12/30
COOK, J. W. Consumers Power Co. 1p. 17600:181

8303210060 Forwards response to NRC 821126 request for addl info re application for SNM license.
COOK, J. W. Consumers Power Co. 83/02/25. DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director. 11pp. 17660:095

8303210060 Forwards response to NRC 821126 request for addl info re application for SNM license. W/14 oversize drawings. Aperture cards are available in PDR.
COOK, J. W. Consumers Power Co. 83/02/25. DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director. 11pp. 17660:095

DOCKET 70-2965 CONSUMERS POWER CO., JACKSON, MI

8303150100 Approves plant security plan for protection of SNM of low strategic significance, per 10CFR73.27(f)(g).
DUBE, R. J. Fuel Facility Safeguards Licensing Branch 82/12/30
COOK, J. W. Consumers Power Co. 1p. 17600:181

8303210060 Forwards response to NRC 821126 request for addl info re application for SNM license. W/14 oversize drawings. Aperture cards are available in PDR.
COOK, J. W. Consumers Power Co. 83/02/25. DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director. 11pp. 17660:095

DOCKET 70-2968 CLEVELAND ELECTRIC ILLUMINATING CO., CLEVELAND, OH

8303310364 Forwards request for addl info re 820830 license application for storage of unirradiated reactor fuel & associated radioactive matl at Perry 1.
KILLINGER, M. H. Uranium Fuel Licensing Branch 83/03/25
DAVIDSON, D. R. Cleveland Electric Illuminating Co. 3pp. 17780:354

## PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0004 GENERAL ELECTRIC CO.

8303010071 Forwards Rev 7 to "Spent Fuel Svcs Operation & GE U Mgt Corp QA Plan."
DAWSON, D. M. General Electric Co. 83/02/10. MACDONALD, C. E. Division of Fuel Cycle & Material Safety. 1p. 17348:130.

--8303010075 Rev 7 to "Spent Fuel Svcs Operation & GE U Mgt Corp QA Plan."
* General Electric Co. NEDO-20776 R07. 82/09/30. 100pp. 17348:131.

DOCKET 71-0086 ALPHA-OMEGA SERVICES, INC.

8303110116 Requests rev to QA program for Certificate of Compliance 0086, Rev 0 for design, fabrication, assembly, testing & mod of radioactive matl shipping packages.
COLLINS, F. R. Alpha-Omega Services, Inc. 83/02/18. MACDONALD, C. E. Transportation Branch. 1p. 17526:107.

--8303110119 QA plan for shipping packages, Rev 0.
* Alpha-Omega Services, Inc. AOS/QAP-001 R00. 83/02/25. 30pp. 17526:108.

DOCKET 71-0423 H & H X-RAY SERVICES, INC.

8303230484 Forwards drawing showing physical address of location used to store sources temporarily in approved DOT shipping cans. Sources logged in & out according to approved guidelines.
HEAD, K. Y. H&H X-Ray Services, Inc. 83/03/02. MCDONALD, C. E. Transportation Branch. 2pp. 17677:250.

DOCKET 71-0492, CALIFORNIA POLYTECHNIC STATE UNIV.

8303020225 Forwards outline of QA program for return of U-235 enriched U from univ to DOE. QA program addresses design, fabrication, assembly, testing, maint, repair, mod & use of proposed packaging.
HALL, J. L. California Polytechnic State Univ. 83/02/04.
MACDONALD, C. E. Transportation Branch. 9pp. 17355:343.

8303040113 Forwards QA program approval for Radioactive Matl Package 0492, Rev. 0.
MACDONALD, C. E. Transportation Branch. 83/02/24. HALL, J. L. California Polytechnic State Univ. 1p. 17424:335.

--8303040116 QA program approval for Radioactive Matl Package 0492, Rev 0.
MACDONALD, C. E. Transportation Branch. 83/02/24. 1p. 17424:336.

DOCKET 71-4909 MODEL: GE 21PF-1, GENERAL ELECTRIC CO.

8303020246 Application for amend to Certificate of Compliance 4909 to accommodate minor changes to DOT Package 21PF-1 W/two oversize drawings, including one proprietary. Nonproprietary aperture card in PDR. Proprietary card in Central Files.
NARDI, A. J. Westinghouse Electric Corp. 83/01/19. MACDONALD, C. E. Transportation Branch. 5pp. 17355:279.

8303030208 Forwards 821229 request for addl fee for Rev 1 to Certificate of Compliance 4909. Addl fee must be submitted within 15 days of ltr date.
JACKSON, G. License Fee Management Branch. 83/01/25. VAUGHAN, C. M. General Electric Co. 1p. 17365:279.

--8303030237 Ack receipt of 821119 request for amend to Certificate of Compliance 4909. Request classified as minor amend. Addl fee required within 20 days of ltr date.
JACKSON, G. License Fee Management Branch. 82/12/29. VAUGHAN, C. M. General Electric Co. 1p. 17365:280.

--8303030271 Application for amend to Certificate of Compliance 4909 to include mod to DOT Spec Package 21PF-1. Fee encl. W/two oversize drawings. Aperture cards are available in PDR.
VAUGHAN, C. M. General Electric Co. 82/11/19. MACDONALD, C. E. Transportation Branch. 4pp. 17365:281.

8303030251 Forwards request for addl info before approving proposed Model W-21PF-1 packaging. Response in form of revised pages requested within 30 days.
MACDONALD, C. E. Transportation Branch. 83/02/24. NARDI, A. J. Westinghouse Electric Corp. 2pp. 17419:354.

8303280055 Requests registration of listed contractors as users of Certificate of Compliance 4909.
PRICHARD, R. P. Energy, Dept. of. 83/03/10. MACDONALD, C. E. Transportation Branch. 1p. 17726:333.

DOCKET 71-4986 MODEL: RA-2, RA-3, RA-J, GENERAL ELECTRIC CO.

8303030297 Application for amend to Certificate of Compliance 4986 to permit use of RA series container to ship zirconium clad fuel.
NARDI, A. J. Westinghouse Electric Corp. 83/02/04. MACDONALD, C. E. Transportation Branch. 12pp. 17365:211.

8303110107 Requests registration as user of Models RA-2 & RA-3.
COUNSIL, W. G., SEARS, C. F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. G. Northeast Utilities. 83/02/17
MACDONALD, C. E. Transportation Branch. 1p. 17526:198.

DOCKET 71-5026 MODEL: CNS 14-190, CHEM-NUCLEAR SYSTEMS, INC.

8303010069 Requests registration as user of Models HN-100s, HN-100 Series I, HN-200, CNS 8-120, CNS 21-300, CNS 14-195-H, CNS 4-45, CNS 14-190, AL-33-90 & RAD-WASTE CR 1.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/01/20
MACDONALD, C. E. Transportation Branch. 3pp. 17347:355.

8302090609 Informs that 9151 Rumsey Road, Columbia, MD 21045 is new address for company as result of acquisition by Westinghouse.
* Hittman Nuclear & Development Corp. (subs. Hittman Corp.)
83/01/22. MACDONALD, C. Transportation Branch. 1p. 17013:086.

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C. A. Chem-Nuclear Systems, Inc. 83/03/02 ODEGAARDEN, R. H. Transportation Branch. 1p. 17623:305.

DOCKET 71-5088 MODEL: D34710-1, D34710-2, ROCKWELL INTERNATIONAL

8303010001 Requests registration as user of Models D34710-1 & D34710-2.
REGAN, N. A. Babcock & Wilcox Co. 83/02/08 MACDONALD, C. E. Transportation Branch. 1p. 17322:354.

8303180547 Notification of registration as user of Models D34710-1 & D34710-2 in response to 830208 request.
MACDONALD, C. E. Transportation Branch. 83/03/14 REGAN, N. A. Babcock & Wilcox Co. 1p. 17639:286.

DOCKET 71-5364 MODEL: NPI-67-0442, NEUTRON PRODUCTS, INC.

8303100347 Requests registration as user of Model NPI-67-0442.
PRICHARD, R. P. Energy, Dept. of. 83/02/18 MACDONALD, C. E. Transportation Branch. 1p. 17504:068.

DOCKET 71-5450 MODEL: RCC, -1, -2, -3, -4, WESTINGHOUSE ELECTRIC CORP.

8303180550 Notification of registration as user of Models RCC, RCC-1, RCC-2, RCC-3 & RCC-4 in response to 830131 request.
MACDONALD, C. E. Transportation Branch. 83/03/14 BROWN, C. D. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 1p. 17639:326.

DOCKET 71-5580 MODEL: S5W POWER UNIT, ENERGY, DEPT. OF

8303300084 Forwards Rev 1 to Certificate of Compliance 5580 for Model S5W.
MACDONALD, C. E. Transportation Branch. 83/03/18 ENGEL, W. P. Energy, Dept. of. 1p. 17754:159.

--8303300087 Certificate of Compliance 5580, Rev 1, for Model S5W Approval record encl.
MACDONALD, C. E. Transportation Branch. 83/03/18 3pp. 17754:160.

DOCKET 71-5757 MODEL: S5W, REFUEL SRCE, ENERGY, DEPT. OF

8303300106 Forwards Rev 2 to Certificate of Compliance 5757 for Model S5W refueling source.
MACDONALD, C. E. Transportation Branch. 83/03/22 ENGEL, W. P. Energy, Dept. of. 1p. 17749:205.

--8303300109 Certificate of Compliance 5757, Rev 2, for Model S5W refueling source.
MACDONALD, C. E. Transportation Branch. 83/03/22 4pp. 17749:206.

DOCKET 71-5758 MODEL: S5W, ENERGY, DEPT. OF

8303290757 Forwards Rev 1 to Certificate of Compliance 5758 for Model S5W core barrel disposal cask.
MACDONALD, C. E. Transportation Branch. 83/03/22 ENGEL, W. P. Energy, Dept. of. 1p. 17746:337.

--8303290761 Certificate of Compliance 5758, Rev 1, for Model S5W core barrel disposal cask.
MACDONALD, C. E. Transportation Branch. 83/03/22 3pp. 17746:338.

DOCKET 71-5796 MODEL: 181375, 181361, ADVANCED MEDICAL SYSTEMS, INC.

8303100512 Responds to NRC 821229 ltr re vendor 821101 submittal. Packaging drop tested did not include internal support strap, but prototype source exchange container bolted directly to pallet base. Addl info expected by 830404.
IRWIN, H. R. Advanced Medical Systems, Inc. 83/02/03 MACDONALD, C. E. Transportation Branch. 1p. 17521:314.

8303030706 Responds to 830203 ltr re Model 181375 packaging. Test results of interval support assembly of tested prototype acceptable.
MACDONALD, C. E. Transportation Branch. 83/02/25 IRWIN, H. R. Advanced Medical Systems, Inc. 1p. 17364:299.

DOCKET 71-5805 MODEL: CNS-3-55, CHEM-NUCLEAR SYSTEMS, INC.

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C. A. Chem-Nuclear Systems, Inc. 83/03/02 ODEGAARDEN, R. H. Transportation Branch. 1p. 17623:305.

8303210137 Advises that NRC 830222 ltr re application for renewal of Certificate of Compliance 5805 for Model CNS 3-55 should have referenced Rev 10, not Rev 9.
MACDONALD, C. E. Transportation Branch. 83/03/10 DEAL, R. Chem-Nuclear Systems, Inc. 2pp. 17660:166.

DOCKET 71-5874 MODEL: WAPD-40, ENERGY, DEPT. OF

8303180462 Forwards Rev 2 to "SAR for Packaging for Shipment of WAPD-40 Cask."
ENGEL, W. P. Energy, Dept. of. 83/03/01 MACDONALD, C. E. Transportation Branch. 3pp. 17638:215.

--8303180469 Rev 2 to "SAR for Packaging for Shipment of WAPD-40 Cask."
* Energy, Dept. of. WAPD-RED(C)-270 R02. 83/02/28. 55pp. 17638:218.

DOCKET 71-5939 MODEL: GE-1500, GENERAL ELECTRIC CO.

8303010016 Requests registration as user of Model GE 1500.
DALE, L. F. Mississippi Power & Light Co. 83/02/03. MACDONALD, C. E. Transportation Branch. 1p. 17322:349.

DOCKET 71-5942 MODEL: GE-700, GENERAL ELECTRIC CO.

8302030609 InForms that 9151 Rumsey Road, Columbia, MD 21045 is new address for company as result of acquisition by Westinghouse.
* Hittman Nuclear & Development Corp. (subs. Hittman Corp.). 83/01/22. MACDONALD, C. Transportation Branch. 1p. 17013:086.

DOCKET 71-6002 MODEL: S3W/S4W NEW SUB, ENERGY, DEPT. OF

8303300142 Forwards Rev 0 to Certificate of Compliance 6002 for Model S3W/S4W.
MACDONALD, C. E. Transportation Branch. 83/03/18. ENGEL, W. P. Energy, Dept. of. 1p. 17750:342.

--8303300148 Certificate of Compliance 6002, Rev 0, for Model S3W/S4W Approval record encl.
MACDONALD, C. E. Transportation Branch. 83/03/18. 3pp. 17750:343.

DOCKET 71-6058 MODEL: B-3, U.S. ECOLOGY

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C. A. Chem-Nuclear Systems, Inc. 83/03/02. ODEGAARDEN, R. H. Transportation Branch. 1p. 17623:305.

DOCKET 71-6144 MODEL: B-2, U.S. ECOLOGY

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C. A. Chem-Nuclear Systems, Inc. 83/03/02. ODEGAARDEN, R. H. Transportation Branch. 1p. 17623:305.

DOCKET 71-6244 MODEL: 6244, CHEM-NUCLEAR SYSTEMS, INC.

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C. A. Chem-Nuclear Systems, Inc. 83/03/02. ODEGAARDEN, R. H. Transportation Branch. 1p. 17623:305.

# DOCKETED ITEMS

DOCKET 71-6272 MODEL: 6272, U.S. ECOLOGY

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C. A. Chem-Nuclear Systems, Inc. 83/03/02 ODEGAARDEN, R. H.
Transportation Branch Ltr 1p 17623:305

DOCKET 71-6294 MODEL: UNC-2901, COMBUSTION ENGINEERING CO., INC.

8303030712 Forwards request for info re 821217 request for amend to Model UNC-2901 packaging. Submittal date requested within 30 days.
MACDONALD, C. E. Transportation Branch 83/02/25 FORD, J. T. Babcock & Wilcox Co. 3pp 17364:296

DOCKET 71-6346 MODEL: FSV-1, GENERAL ATOMIC CO.

8303100571 Requests withdrawal of 801009 amend request due to postponement of West Valley high level waste sample shipping effort.
MOWRY, W. R. GA Technologies, Inc./General Atomic Co. 83/02/15
MACDONALD, C. E. Transportation Branch 1p 17521:346

8303180515 Informs that 801009 application request withdrawn per 830215 ltr.
MACDONALD, C. E. Transportation Branch 83/03/14 MOWRY, W. R. GA Technologies, Inc./General Atomic Co. 1p 17626:361

DOCKET 71-6375 MODEL: CNS 4-45, CHEM-NUCLEAR SYSTEMS, INC.

8303010069 Requests registration as user of Models HN-100s, HN-100, Series I, HN-200, CNS 8-120, CNS 21-300, CNS 14-195-H, CNS 4-45, CNS 14-190, AL-33-90 & RAD-WASTE CR-1.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/01/20
MACDONALD, C. E. Transportation Branch 3pp 17347:355

DOCKET 71-6387 MODEL: 60, BATTELLE MEM. INST., PACIFIC NORTHWEST LAB

8303110014 Forwards Rev 5 to Certificate of Compliance 6387 for Model 60 Expiration date extension to 850202 only change.
PRICHARD, R. P. Energy, Dept. of 83/02/18 MACDONALD, C. E.
Transportation Branch Ltr 1p 17546:268

--8303110028 Certificate of Compliance 6387, Rev 5, for Model 60. Expiration date changed to 850202.
GERTON, R. E. Energy, Dept. of 83/02/02 6pp 17546:269

DOCKET 71-6568 MODEL: LL-60-150, TENNESSEE VALLEY AUTHORITY

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C. A. Chem-Nuclear Systems, Inc. 83/03/02 ODEGAARDEN, R. H.
Transportation Branch Ltr 1p 17623:305

DOCKET 71-6574 MODEL: HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP.

8303010069 Requests registration as user of Models HN-100s, HN-100, Series I, HN-200, CNS 8-120, CNS 21-300, CNS 14-195-H, CNS 4-45, CNS 14-190, AL-33-90 & RAD-WASTE CR-1.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/01/20
MACDONALD, C. E. Transportation Branch 3pp 17347:355

8302030609 Informs that 9151 Rumsey Road, Columbia, MD 21045 is new address for company as result of acquisition by Westinghouse.
* Hittman Nuclear & Development Corp. (subs. Hittman Corp.)
83/01/22 MACDONALD, C. Transportation Branch Ltr 1p 17013:086

8303160692 Forwards Rev 8 to Certificate of Compliance 6574 for Model HN-200.
MACDONALD, C. E. Transportation Branch 83/03/02 ROWE, B. S. Hittman Nuclear & Development Corp. (subs. Hittman Corp.) 3pp 17600:252

--8303160696 Certificate of Compliance 6574, Rev 8, for Model HN-200. Approval record encl.
MACDONALD, C. E. Transportation Branch 83/03/02 4pp 17600:255

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C. A. Chem-Nuclear Systems, Inc. 83/03/02 ODEGAARDEN, R. H.
Transportation Branch Ltr 1p 17623:305

8303180160 Notification of registration as user of Models HN-200, HN-100 Series 2A & HN-100 Series 3 in response to 830210 request.
MACDONALD, C. E. Transportation Branch 83/03/14 MIS, F. J.
Rochester Gas & Electric Corp. Ltr 1p 17626:001

DOCKET 71-6601 MODEL: CNS 8-120, CHEM-NUCLEAR SYSTEMS, INC.

8303010069 Requests registration as user of Models HN-100s, HN-100, Series I, HN-200, CNS 8-120, CNS 21-300, CNS 14-195-H, CNS 4-45, CNS 14-190, AL-33-90 & RAD-WASTE CR-1.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 83/01/20
MACDONALD, C. E. Transportation Branch 3pp 17347:355

8303110112 Application for amend to Certificate of Compliance 6601.
SVINIS, B. Chem Systems, Inc. 83/02/08 MACDONALD, C. E.
Transportation Branch 7pp 17526:139

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C. A. Chem-Nuclear Systems, Inc. 83/03/02 ODEGAARDEN, R. H.
Transportation Branch Ltr 1p 17623:305

8303180090 Requests registration as user of Model CNS 8-120.
FLEISCHMANN, R. Philadelphia Electric Co. 83/03/04 MACDONALD, C. E.
Transportation Branch Ltr 1p 17625:207

DOCKET 71-6639 MODEL: MH-1A, ARMY, DEPT. OF

8303030317 Forwards request for addl info to complete review of Model MH-1A packaging. Response requested in form of revised pages.
MACDONALD, C. E. Transportation Branch 83/02/24 PRICHARD, R. P.
Energy, Dept. of 6pp 17365:167

DOCKET 71-6642 MODEL: 4.5 TON CF, ENERGY, DEPT. OF

8303030310 Application for amend to Certificate of Compliance 6642 stating certificate meets IAEA 1973 stds.
SHAW, A. Edlow International Co. 83/01/31 RAWL, R. R.
Transportation, Dept. of Ltr 1p 17365:176

DOCKET 71-6679 MODEL: 6679, U.S. ECOLOGY

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C. A. Chem-Nuclear Systems, Inc. 83/03/02 ODEGAARDEN, R. H.
Transportation Branch Ltr 1p 17623:305

DOCKET 71-6698 MODEL: NFS-4, NUCLEAR FUEL SERVICES, INC.

8303020144 Requests that NFS-4/NAC-1, NLI-1/2 & IF-300 shipping casks be withdrawn from svc pending performance of calculations to verify safety.
RESNIKOFF, M. Council on Economic Priorities 83/01/28
ODEGAARDEN, R. Office of Nuclear Material Safety & Safeguards, Director Ltr 1p 17359:147

8303010121 Ack receipt of ltr re further NRC analysis of "dry" shipments & removal of IF-300, NLI-1/2 & NAC-1 casks from svc. Van der Waal equation cannot be used due to steam compressibility.
RESNIKOFF, M. Council on Economic Priorities 83/02/08
ODEGAARDEN, R. Office of Nuclear Material Safety & Safeguards, Director 3pp 17322:358

8303010081 Responds to 830208 ltr expressing concerns re dry shipment of spent fuel. Possible failure of relief valve & loss of coolant considered in calculations & assumptions.
ODEGAARDEN, R. H. Transportation Branch 83/02/17 RESNIKOFF, M.
Council on Economic Priorities 2pp 17354:344

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C. A. Chem-Nuclear Systems, Inc. 83/03/02 ODEGAARDEN, R. H.
Transportation Branch Ltr 1p 17623:305

DOCKET 71-6717 MODEL: 6717-B, GAMMA INDUSTRIES

8303040227 Requests registration as user of Model 6717-B.
KERR, D. Kerr Inspection & Testing Service, Inc. 83/01/07.
MACDONALD, C. E. Transportation Branch. 1p. 17427:356.

8303020366 Requests registratic.. as user of Model 6717-B.
SHARP, J. Basin Industrial X-Ray, Inc. 83/02/04. MACDONALD, C. E.
Transportation Branch. 1p. 17337:346.

8303020355 Notification of registration as user of Model 6717-B in response to 830103 request.
MACDONALD, C. E. Transportation Branch. 83/02/22. ROLLINS, M. V.
Southwestern Laboratories. 1p. 17357:347.

DOCKET 71-6722 MODEL: BS-33-180, TENNESSEE VALLEY AUTHORITY

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C. A. Chem-Nuclear Systems, Inc. 83/03/02. ODEGAARDEN, R. H.
Transportation Branch. 1p. 17623:305.

DOCKET 71-6744 MODEL: 6744, U.S. ECOLOGY

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C. A. Chem-Nuclear Systems, Inc. 83/03/02. ODEGAARDEN, R. H.
Transportation Branch. 1p. 17623:305.

DOCKET 71-9001 MODEL: IF-300, GENERAL ELECTRIC CO.

8302040471 Forwards response to 821029 request for addl info re GE request for reinstatement of Model IF-300 for shipment of BWR fuel.
DAWSON, D. M. General Electric Uranium Management Corp. 83/01/21.
MACDONALD, C. E. Transportation Branch. 29pp. 17030:126.

--8302040475 Draft "IF-300 BWR Fuel Basket Horizontal Drop Analysis" App V-3.
OBERMILLER, K. E., MOK, G. C., RANGANATH, S. General Electric Co.
NEDO-10084-2G DRFT. 81/01/31. 33pp. 17050:155.

8303020144 Requests that NFS-4/NAC-1, NLI-1/2 & IF-300 shipping casks be withdrawn from svc pending performance of calculations to verify safety.
RESNIKOFF, M. Council on Economic Priorities. 83/01/28.
ODEGAARDEN, R. Office of Nuclear Material Safety &
Safeguards, Director. 1p. 17359:147.

8303010121 Ack receipt of ltr re further NRC analysis of "dry" shipments & removal of IF-300, NLI-1/2 & NAC-1 casks from svc. Van der Waal equation cannot be used due to steam compressibility.
RESNIKOFF, M. Council on Economic Priorities. 83/02/08.
ODEGAARDEN, R. Office of Nuclear Material Safety &
Safeguards, Director. 3pp. 17322:358.

8303010081 Responds to 830208 ltr expressing concerns re dry shipment of spent fuel. Possible failure of relief valve & loss of coolant considered in calculations & assumptions.
ODEGAARDEN, R. H. Transportation Branch. 83/02/17. RESNIKOFF, M.
Council on Economic Priorities. 2pp. 17354:344.

8303110147 Forwards response to 830222 request for addl info re tie rod buckling & spacer disk horizontal drop analyses per Rev 14 to Certificate of Compliance 9001.
DAWSON, D. M. General Electric Uranium Management Corp. 83/02/28.
MACDONALD, C. E. Transportation Branch. 12pp. 17523:136.

8303180508 Forwards addl info re 830228 response to Question e of NRC 830222 request for addl info concerning Rev 14 to Certificate of Compliance 9001 to reinstate use of GE IF-300 shipping cask for BWR shipment.
DAWSON, D. M. General Electric Uranium Management Corp. 83/03/04.
MACDONALD, C. E. Transportation Branch. 13pp. 17640:210.

8303210133 Forwards request for info needed to review 821021 application for amend to Model IF-300 packaging for shipment of BWR fuel assemblies.
MACDONALD, C. E. Transportation Branch. 83/03/09. DAWSON, D. M.
General Electric Co. 2pp. 17660:164.

8303300081 Forwards Rev 15 to Certificate of Compliance 9001 for Model IF-300.
MACDONALD, C. E. Transportation Branch. 83/03/22. DAWSON, D. M.
General Electric Co. 2pp. 17754:163.

--8303300096 Certificate of Compliance 9001, Rev 15, for Model IF-300.
MACDONALD, C. E. Transportation Branch. 83/03/22. 9pp. 17754:165.

DOCKET 71-9006 MODEL: 500-SU, AUTOMATION INDUSTRIES, INC.

8303140649 Forwards Rev 2 to "Test Results for Type B Packaging," in response to NRC 820924 ltr. Rev incorporates Engineering Drawing D-500SU-DP & includes evaluation & results of mechanical testing. W/o encl.
SANTORO, M. P. Automation Industries, Inc. 83/01/27. MACDONALD, C. E.
Transportation Branch. 4pp. 17572:358.

8303290022 Forwards P 13 to "Test Results for Type B Packaging Iridium Source Changer - Spent U Type & Model 520 Iriditron Exposure Device," inadvertently omitted from 830127 transmittal.
SANTORO, M. P. Automation Industries, Inc. 83/03/02. MACDONALD, C. E.
Transportation Branch. 1p. 17730:286.

--8303290026 Corrected pages to "Test Results for Type B Packaging Iridium Source Changer - Spent U Type & Model 520 Iriditron Exposure Device."
SANTORO, M. P. Automation Industries, Inc. 83/01/27. 2pp.
17730:288.

DOCKET 71-9010 MODEL: NLI-1/2, NL INDUSTRIES, INC.

8302030609 Informs that 9151 Rumsey Road, Columbia, MD 21045 is new address for company as result of acquisition by Westinghouse.
* Hittman Nuclear & Development Corp. (subs. Hittman Corp.).
83/01/22. MACDONALD, C. Transportation Branch. 1p. 17013:086.

8303020144 Requests that NFS-4/NAC-1, NLI-1/2 & IF-300 shipping casks be withdrawn from svc pending performance of calculations to verify safety.
RESNIKOFF, M. Council on Economic Priorities. 83/01/28.
ODEGAARDEN, R. Office of Nuclear Material Safety &
Safeguards, Director. 1p. 17359:147.

8303010121 Ack receipt of ltr re further NRC analysis of "dry" shipments & removal of IF-300, NLI-1/2 & NAC-1 casks from svc. Van der Waal equation cannot be used due to steam compressibility.
RESNIKOFF, M. Council on Economic Priorities. 83/02/08.
ODEGAARDEN, R. Office of Nuclear Material Safety &
Safeguards, Director. 3pp. 17322:358.

8303010081 Responds to 830208 ltr expressing concerns re dry shipment of spent fuel. Possible failure of relief valve & loss of coolant considered in calculations & assumptions.
ODEGAARDEN, R. H. Transportation Branch. 83/02/17. RESNIKOFF, M.
Council on Economic Priorities. 2pp. 17354:344.

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C. A. Chem-Nuclear Systems, Inc. 83/03/02. ODEGAARDEN, R. H.
Transportation Branch. 1p. 17623:305.

DOCKET 71-9015 MODEL: TN-8, -8L, NO USERS

8303030262 Forwards request for addl info to complete review of amend to Models TN-8 & TN-8L packagings. Response in form of revised pages to SAR requested within 30 days.
MACDONALD, C. E. Transportation Branch. 83/02/24. GOLDMAN, K.
Transnuclear, Inc. 2pp. 17419:352.

8303300077 Summary of 830315 meeting w/applicant in Silver Spring, MD re addl info requested by NRC 830224 ltr on 821203 application to increase allowable initial pressures within fuel rods.
ODEGAARDEN, R. H. Transportation Branch. 83/03/18. Transportation
Branch. 2pp. 17751:055.

DOCKET 71-9033 MODEL: 660 & 660E, TECHNICAL OPERATIONS, INC.

8303090675 Requests registration as user of Model 660.
SMITH, R. Kokomo Tube Co. 83/02/18. MACDONALD, C. E. Transportation
Branch. 1p. 17480:222.

8303160700 Notification of registration as user of Models 660 & 660E in response to 830126 request.
MACDONALD, C E Transportation Branch 83/03/02 DOHRMAN, K F
Panhandle Eastern Pipeline Co 1p 17600 251

DOCKET 71-9044 MODEL GE-1600, GENERAL ELECTRIC CO

8303030035 Application for rev of Certificate of Compliance 9044, revising certification drawings for GE Model 1600 shipping container.
CUNNINGHAM, G E General Electric Co 83/01/17 MACDONALD, C E
Transportation Branch 9pp 17365 352

8302030609 Informs that 9151 Rumsey Road, Columbia, MD 21045 is new address for company as result of acquisition by Westinghouse.
* Hittman Nuclear & Development Corp (subs Hittman Corp.)
83/01/22 MACDONALD, C Transportation Branch 1p 17013 086

8303030216 Submits changes to Drawings 129D4735, 129D4736 & 129D4737 in response to 830126 request that Model 1600 certification drawings be reviewed for discrepancies between drawings & fabrication details. Drawings encl.
CUNNINGHAM, G E General Electric Co 83/02/04 MACDONALD, C E
Transportation Branch 5pp 17426 192

8303170679 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN, R H
Transportation Branch 1p 17623 305

DOCKET 71-9070 MODEL N-55, ENERGY, DEPT OF

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN, R H
Transportation Branch 1p 17623 305

DOCKET 71-9071 MODEL AP-101, ANEFCO, INC

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN, R H
Transportation Branch 1p 17623 305

DOCKET 71-9073 MODEL OH-142, NUCLEAR PACKAGING, INC

8303020153 Forwards 830216 revised SAR pages for Model OH-142. Revs respond to NRC comments based on 821020 consolidated application for renewal of Certificate of Compliance 9073. Responses to NRC comments encl.
STREUTKER, S R Nuclear Packaging, Inc 83/02/16 MACDONALD, C A
Transportation Branch 20pp 17359 341

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN, R H
Transportation Branch 1p 17623 305

DOCKET 71-9074 MODEL AP-100, ANEFCO, INC

8303040051 Forwards Rev 8 to application for renewal of Certificate of Compliance 9074 to permit shipment of low specific activity radioactive matls.
MURPHY, J D Anefco, Inc 83/01/31 Division of Fuel Cycle & Material Safety 1p 17424 298

--8303040066 Rev 8 to application for renewal of Certificate of Compliance 9074 to permit shipment of low specific activity radioactive matls.
* Anefco, Inc 83/01/31 32pp 17424 299

8303100547 Forwards Rev 1 to Certificate of Compliance 9074 for Model AP-100.
MACDONALD, C E Transportation Branch 83/03/02 MURPHY, J D
Anefco, Inc 2pp 17521 262

--8303100549 Certificate of Compliance 9074, Rev 1, for Model AP-100. Approval record encl.
MACDONALD, C E Transportation Branch 83/03/02 4pp 17521 264

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN, R H
Transportation Branch 1p 17623 305

DOCKET 71-9079 MODEL HN-100, SERIES 2 & 2A, HITTMAN NUCLEAR

8302030609 Informs that 9151 Rumsey Road, Columbia, MD 21045 is new address for company as result of acquisition by Westinghouse.
* Hittman Nuclear & Development Corp (subs Hittman Corp.)
83/01/22 MACDONALD, C Transportation Branch 1p 17013 086

8303170679 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN, R H
Transportation Branch 1p 17623 305

8303180527 Forwards rev to "NuPac 14D-2 0 Package SAR."
STREUTKER, S R Nuclear Packaging, Inc 83/03/03 MACDONALD, C E
Transportation Branch 2pp 17640 225

--8303180534 Rev to "NuPac 14D-2 0 Package SAR."
* Nuclear Packaging, Inc 83/03/01 31pp 17640 228

8303180160 Notification of registration as user of Models HN-200, HN-100 Series 2A & HN-100 Series 3 in response to 830210 request.
MACDONALD, C E Transportation Branch 83/03/14 MIS, F J
Rochester Gas & Electric Corp 1p 17626 001

DOCKET 71-9080 MODEL 9080, HITTMAN NUCLEAR & DEVELOPMENT CORP

8302030609 Informs that 9151 Rumsey Road, Columbia, MD 21045 is new address for company as result of acquisition by Westinghouse.
* Hittman Nuclear & Development Corp (subs Hittman Corp.)
83/01/22 MACDONALD, C Transportation Branch 1p 17013 086

8303030316 Application for amend to Certificate of Compliance 9080 re shoring between small secondary containers & seals on main cover & shield plug cover.
MALLORY, C W Hittman Nuclear & Development Corp (subs Hittman Corp.) 83/01/31 MACDONALD, C Transportation Branch 2pp 17365 173

8303110106 Requests registration as user of Model 9080.
FAY, C W Wisconsin Electric Power Co 83/02/18 MACDONALD, C E
Transportation Branch 1p 17526 199

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN, R H
Transportation Branch 1p 17623 305

DOCKET 71-9091 MODEL CNSI 1-13C, CHEM-NUCLEAR SYSTEMS, INC

8302030609 Informs that 9151 Rumsey Road, Columbia, MD 21045 is new address for company as result of acquisition by Westinghouse.
* Hittman Nuclear & Development Corp (subs Hittman Corp.)
83/01/22 MACDONALD, C Transportation Branch 1p 17013 086

8303180099 Requests registration as user of Model CNSI-1-13C.
BORST, F J Public Service Co of Colorado 83/02/28
MACDONALD, C E Transportation Branch 2pp 17625 191

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC. Author name should be deleted from all correspondence lists.
MARSH, C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN, R H
Transportation Branch 1p 17623 305

DOCKET 71-9086 MODEL HN-100, SERIES 1, HITTMAN NUCLEAR & DEV CORP

8303010069 Requests registration as user of Models HN-100s, HN-100, Series 1, HN-200, CNS 8-120, CNS 21-300, CNS 14-195-H, CNS 4-45, CNS 14-190, AL-33-90 & RAD-WASTE CR-1.
FIEDLER, P B General Public Utilities - GPU Service Corp 83/01/20
MACDONALD, C E Transportation Branch 3pp 17347 355

8302030609 Informs that 9151 Rumsey Road,Columbia,MD 21045 is new address for company as result of acquisition by Westinghouse. * Hittman Nuclear & Development Corp (subs Hittman Corp.) 83/01/22 MACDONALD,C Transportation Branch 1p 17013:086

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia,SC Author name should be deleted from all correspondence lists. MARSH,C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN,R H Transportation Branch 1p 17623:305

8302300104 Forwards Rev 8 to Certificate of Compliance 9086 for Model HN-100 Series 1. MACDONALD,C E Transportation Branch 83/03/22 ROWE,B S Hittman Corp 3pp 17749:001

--8302300337 Certificate of Compliance 9086,Rev 8,for Model HN-100 Series 1 MACDONALD,C E Transportation Branch 83/03/22 5pp 17749:004

DOCKET 71-9089 MODEL HN-100S, HITTMAN NUCLEAR & DEVELOP CORP

8303010069 Requests registration as user of Models HN-100s,HN-100, Series I,HN-200,CNS 8-120,CNS 21-300,CNS 14-195-H,CNS 4-45, CNS 14-190,AL-33-90 & RAD-WASTE CR 1. FIEDLER,P B General Public Utilities - GPU Service Corp 83/01/20 MACDONALD,C E Transportation Branch 3pp 17347:355

8302030609 Informs that 9151 Rumsey Road,Columbia,MD 21045 is new address for company as result of acquisition by Westinghouse. * Hittman Nuclear & Development Corp (subs Hittman Corp.) 83/01/22 MACDONALD,C Transportation Branch 1p 17013:086

8303030326 Application for mod to Certificate of Compliance 9089 re shoring between small secondary containers & insp of seals on main cover & shield plug cover. MALLORY,C W Hittman Nuclear & Development Corp (subs Hittman Corp.) 83/01/31 MACDONALD,C Transportation Branch 2pp 17365:129

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia,SC Author name should be deleted from all correspondence lists. MARSH,C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN,R H Transportation Branch 1p 17623:305

DOCKET 71-9092 MODEL HN-300, HITTMAN NUCLEAR & DEVELOPMENT CORP

8302030609 Informs that 9151 Rumsey Road,Columbia,MD 21045 is new address for company as result of acquisition by Westinghouse. * Hittman Nuclear & Development Corp (subs Hittman Corp.) 83/01/22 MACDONALD,C Transportation Branch 1p 17013:086

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia,SC Author name should be deleted from all correspondence lists. MARSH,C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN,R H Transportation Branch 1p 17623:305

DOCKET 71-9093 MODEL HN-400, HITTMAN NUCLEAR & DEVELOPMENT CORP

8302030609 Informs that 9151 Rumsey Road,Columbia,MD 21045 is new address for company as result of acquisition by Westinghouse. * Hittman Nuclear & Development Corp (subs Hittman Corp.) 83/01/22 MACDONALD,C Transportation Branch 1p 17013:086

DOCKET 71-9094 MODEL CNS 14-195-H, CHEM-NUCLEAR SYSTEMS, INC.

8303010069 Requests registration as user of Models HN-100s,HN-100, Series I,HN-200,CNS 8-120,CNS 21-300,CNS 14-195-H,CNS 4-45, CNS 14-190,AL-33-90 & RAD-WASTE CR 1. FIEDLER,P B General Public Utilities - GPU Service Corp 83/01/20 MACDONALD,C E Transportation Branch 3pp 17347:355

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia,SC Author name should be deleted from all correspondence lists. MARSH,C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN,R H Transportation Branch 1p 17623:305

DOCKET 71-9096 MODEL CNS 21-300, CHEM-NUCLEAR SYSTEMS, INC.

8303010069 Requests registration as user of Models HN-100s,HN-100, Series I,HN-200,CNS 8-120,CNS 21-300,CNS 14-195-H,CNS 4-45, CNS 14-190,AL-33-90 & RAD-WASTE CR 1. FIEDLER,P B General Public Utilities - GPU Service Corp 83/01/20 MACDONALD,C E Transportation Branch 3pp 17347:355

8303180483 Forwards Rev 1 to "CNSI 21-300 Type A Radwaste Shipping Cask SAR," App 1. SVINIS,B Chem-Nuclear Systems, Inc 83/02/28 MACDONALD,C E Transportation Branch 2pp 17640:176

--8303180488 Rev 1 to "CNSI 21-300 Type A Radwaste Shipping Cask SAR," App 1. * Chem-Nuclear Systems, Inc 83/02/28 29pp 17640:178

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia,SC Author name should be deleted from all correspondence lists. MARSH,C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN,R H Transportation Branch 1p 17623:305

DOCKET 71-9101 MODEL CNSI-1-184-409, CHEM-NUCLEAR SYSTEMS, INC

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia,SC Author name should be deleted from all correspondence lists. MARSH,C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN,R H Transportation Branch 1p 17623:305

8303240105 Application for renewal of Certificate of Compliance 9101. Submittal includes reorganization & re-evaluation of previously approved SAR into format consistent w/Reg Guide 7.9. SVINIS,B Chem-Nuclear Systems, Inc 83/03/11 MACDONALD,C E Transportation Branch 1p 17699:341

--8303240110 "Procedures,License & SAR for Chem-Nuclear Sys,Inc 1-184-109 Radwaste Shipping Containers." * Chem-Nuclear Systems, Inc 83/03/11 47pp 17699:342

DOCKET 71-9105 MODEL RAD-WASTE CR 1, CHEM-NUCLEAR SYSTEMS, INC

8303010069 Requests registration as user of Models HN-100s,HN-100, Series I,HN-200,CNS 8-120,CNS 21-300,CNS 14-195-H,CNS 4-45, CNS 14-190,AL-33-90 & RAD-WASTE CR 1. FIEDLER,P B General Public Utilities - GPU Service Corp 83/01/20 MACDONALD,C E Transportation Branch 3pp 17347:355

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia,SC Author name should be deleted from all correspondence lists. MARSH,C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN,R H Transportation Branch 1p 17623:305

8303240093 Application for renewal of Certificate of Compliance 9105. No changes or additions to SAR & detailed calculations of prior submittals except for format changes per Reg Guide 7.9 Fee encl. SVINIS,B Chem-Nuclear Systems, Inc 83/03/04 MACDONALD,C E Transportation Branch 1p 17699:301

--8303240100 "Procedures,License & SAR for Chem-Nuclear Sys,Inc,CNS 6-101 Type A Radwaste Shipping Casks." * Chem-Nuclear Systems, Inc 83/03/01 32pp 17699:302

DOCKET 71-9108 MODEL AL-33-90, CHEM-NUCLEAR SYSTEMS, INC.

8303010069 Requests registration as user of Models HN-100s,HN-100, Series I,HN-200,CNS 8-120,CNS 21-300,CNS 14-195-H,CNS 4-45, CNS 14-190,AL-33-90 & RAD-WASTE CR 1. FIEDLER,P B General Public Utilities - GPU Service Corp 83/01/20 MACDONALD,C E Transportation Branch 3pp 17347:355

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia,SC Author name should be deleted from all correspondence lists. MARSH,C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN,R H Transportation Branch 1p 17623:305

DOCKET 71-9111 MODEL: CNS 6-80-2, CHEM-NUCLEAR SYSTEMS, INC

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC Author name should be deleted from all correspondence lists.
MARSH, C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN, R H Transportation Branch 1p 17623:305

8303280352 Application for administrative amend to Certificate of Compliance 9111, approving use of optional lid seal for casks.
SVINIS, B Chem-Nuclear Systems, Inc 83/03/03 MACDONALD, C E Transportation Branch 4pp 17713:247

DOCKET 71-9119 MODEL: BAPL 5910 BRDCG, ENERGY, DEPT OF

8303180134 Forwards Rev 3 to Certificate of Compliance 9119 for Model BAPL 5910 Birdcage packaging.
MACDONALD, C E Transportation Branch 83/03/14 ENGEL, W P Navy, Dept of 2pp 17625:120

--8303180139 Certificate of Compliance 9119, Rev 3, for Model BAPL 5910 Birdcage packaging.
MACDONALD, C E Transportation Branch 83/03/14 4pp 17625:122

DOCKET 71-9122 MODEL: 18-450, CHEM-NUCLEAR SYSTEMS, INC

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC Author name should be deleted from all correspondence lists.
MARSH, C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN, R H Transportation Branch 1p 17623:305

DOCKET 71-9133 MODEL: C-10, GAMMA INDUSTRIES

8303040316 Forwards Rev 0 to Certificate of Compliance 9133 for Model C-10.
MACDONALD, C E Transportation Branch 82/05/24 RICHARDSON, H Nuclear System 1p 17426:276

--8303040322 Certificate of Compliance 9133, Rev 0, for Model C-10.
MACDONALD, C E Transportation Branch 82/05/24 8pp 17426:277

8303290267 Informs of error on P 5 of safety evaluation accompanying Certificate of Compliance 9133 for Model C-10 Correction requested.
RIDDLE, D H Nuclear System 83/03/07 MACDONALD, C E Transportation Branch 1p 17729:036

DOCKET 71-9138 MODEL: 78-D-1458, NAVY, DEPT OF

8303010022 Responds to NRC 830127 ltr re container approval Approval no longer required for shipping container for Cs-137, 30 Ci gamma source.
MCKNIGHT, T R Navy, Dept of 83/02/10 MACDONALD, C E Transportation Branch 1p 17322:348

DOCKET 71-9139 MODEL: 589, GENERAL ELECTRIC CO

8303020197 Requests registration as user of Model 589.
EBENHACK, D O Chem-Nuclear Systems, Inc 83/01/24 MACDONALD, C E Transportation Branch 1p 17358:283

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC Author name should be deleted from all correspondence lists.
MARSH, C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN, R H Transportation Branch 1p 17623:305

DOCKET 71-9144 MODEL: SGC-1, CHEM-NUCLEAR SYSTEMS, INC

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC Author name should be deleted from all correspondence lists.
MARSH, C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN, R H Transportation Branch 1p 17623:305

DOCKET 71-9151 MODEL: HN-100, SERIES 3, HITTMAN NUCLEAR & DEV CORP

8302030609 Informs that 9151 Rumsey Road, Columbia, MD 21045 is new address for company as result of acquisition by Westinghouse.
* Hittman Nuclear & Development Corp (subs Hittman Corp ) 83/01/22 MACDONALD, C Transportation Branch 1p 17013:086

8303020187 Requests registration as user of Model HN-100, Series 3.
STEWART, W L Virginia Electric & Power Co 83/01/25
MACDONALD, C E Transportation Branch 1p 17358:284

8303100508 Forwards addl info re 830203 ltr requesting rev to Certificate of Compliance 9151 Address in Paragraph 3(a) should be changed to 9151 Rumsey Rd, Columbia, MD 21045
MALLORY, C W Hittman Nuclear & Development Corp (subs Hittman Corp ) 83/02/08 MACDONALD, C E Transportation Branch 2pp 17521:326

8303100368 Requests registration as user of Model HN-100 Series 3.
O'CONNOR, J M Public Service Electric & Gas Co of New Jersey 83/02/24 MACDONALD, C E Transportation Branch 1p 17522:022

8303180116 Requests registration as user of Model HN-100, Series 3.
MUSOLF, D Northern States Power Co 83/02/28 Transportation Branch 1p 17625:180

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC Author name should be deleted from all correspondence lists.
MARSH, C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN, R H Transportation Branch 1p 17623:305

(?)3180160 Notification of registration as user of Models HN-200, HN-100 Series 2A & HN-100 Series 3 in response to 830210 request.
MACDONALD, C E Transportation Branch 83/03/14 MIS, F J Rochester Gas & Electric Corp 1p 17626:001

DOCKET 71-9150 MODEL: CNS 1-13CII, CHEM-NUCLEAR SYSTEMS, INC

8303170678 Requests future certificate of compliance revs be sent to R Deal in Columbia, SC Author name should be deleted from all correspondence lists.
MARSH, C A Chem-Nuclear Systems, Inc 83/03/02 ODEGAARDEN, R H Transportation Branch 1p 17623:305

8303280060 Requests registration as user of Model CNS 1-13C II.
BRACKEN, R W Energy, Dept of 83/03/09 MACDONALD, C E Transportation Branch 1p 17726:332

DOCKET 71-9159 MODEL: NUPAC SERIES A, NUCLEAR PACKING, INC

8303100315 Forwards corrected copy of instructions for incorporation of Rev 2 of Series A SAR Also forwards Microfiche from Pp 2-84 of SAA Rev 2, "Type A Lug Analysis." Microfiche withheld.
STREUTKER, S R Nuclear Packaging, Inc 83/02/23 MACDONALD, C E Transportation Branch 3pp 17504:076

DOCKET 71-9180 MODEL: 20-VS & 40-VS, GULF NUCLEAR, INC

8303040074 Forwards package evaluations of Models 20-VS, 40-VS, R, GNM-20 & GNG-20.
HOPCRAFT, C P Gulf Nuclear, Inc 83/01/28 MACDONALD, C E Transportation Branch 1p 17426:068

--8303040080 "Package Evaluation, Model 20-VS & Model 40-VS, Type B Quantities."
HOPCRAFT, C P , ACREE, E H Gulf Nuclear, Inc 83/01/28 10pp 17426:069

--8303040083 "Package Evaluation, Model R, Type B Quantities."
HOPCRAFT, C P , ACREE, E H Gulf Nuclear, Inc 83/01/28 16pp 17426:087

--8303040099 "Package Evaluation, Model GNM-20, Type B Quantities."
HOPCRAFT, C P , ACREE, E H Gulf Nuclear, Inc 83/01/28 27pp 17426:103

--8303040106 "Package Evaluation, Model GNG-20, Type B Quantities."
HOPCRAFT, C P , ACREE, E H Gulf Nuclear, Inc 83/01/28 28pp 17426:131

8303290537 Summary of 830317 meeting w/vendor in Silver Spring, MD re review of util 830128 suppls concerning listed models. Closure mechanism on Model GNM-20 package should be redesigned to provide positive closure for transport. ODEGAARDEN, R H. Transportation Branch. 83/03/22. Transportation Branch. 2pp. 17740:356.

8303300285 Requests addl info in form of revised pages to 820302 application for approval of Models 20-VS & 40-VS packagings. Schedule for submittal of info requested within 30 days. MACDONALD, C E. Transportation Branch. 83/03/22. PAYNE, A E. Gulf Nuclear, Inc. 1p. 17748:362.

DOCKET 71-9161 MODEL: R. GULF NUCLEAR, INC.

8303040074 Forwards package evaluations of Models 20-VS, 40-VS, R, GNM-20 & GNG-20. HOPCRAFT, C P. Gulf Nuclear, Inc. 83/01/28. MACDONALD, C E. Transportation Branch. 1p. 17426:068.

--8303040088 "Package Evaluation, Model R, Type B Quantities." HOPCRAFT, C P.; ACREE, E H. Gulf Nuclear, Inc. 83/01/28. 18pp. 17426:087.

8303290537 Summary of 830317 meeting w/vendor in Silver Spring, MD re review of util 830128 suppls concerning listed models. Closure mechanism on Model GNM-20 package should be redesigned to provide positive closure for transport. ODEGAARDEN, R H. Transportation Branch. 83/03/22. Transportation Branch. 2pp. 17740:356.

8303300136 Advises that 830128 supplemental application for approval of Certificate of Compliance 9161 for Model R not responsive to NRC 820527 request for addl info. QA program should be expanded to include design & testing info. MACDONALD, C E. Transportation Branch. 83/03/22. PAYNE, A E. Gulf Nuclear, Inc. 1p. 17749:360.

DOCKET 71-9162 MODEL: GNM-20. GULF NUCLEAR, INC.

8303040074 Forwards package evaluations of Models 20-VS, 40-VS, R, GNM-20 & GNG-20. HOPCRAFT, C P. Gulf Nuclear, Inc. 83/01/28. MACDONALD, C E. Transportation Branch. 1p. 17426:068.

--8303040099 "Package Evaluation, Model GNM-20, Type B Quantities." HOPCRAFT, C P.; ACREE, E H. Gulf Nuclear, Inc. 83/01/28. 27pp. 17426:103.

8303170641 Advises that 830128 supplemental application for approval of Model GNM-20 packaging not responsive to NRC 820520 request for addl info. QA program needs to be expanded to include design, fabrication, assembly & testing. MACDONALD, C E. Transportation Branch. 83/03/14. PAYNE, A E. Gulf Nuclear, Inc. 1p. 17615:159.

8303290537 Summary of 830317 meeting w/vendor in Silver Spring, MD re review of util 830128 suppls concerning listed models. Closure mechanism on Model GNM-20 package should be redesigned to provide positive closure for transport. ODEGAARDEN, R H. Transportation Branch. 83/03/22. Transportation Branch. 2pp. 17740:356.

DOCKET 71-9163 MODEL: GNG-20. GULF NUCLEAR, INC.

8303040074 Forwards package evaluations of Models 20-VS, 40-VS, R, GNM-20 & GNG-20. HOPCRAFT, C P. Gulf Nuclear, Inc. 83/01/28. MACDONALD, C E. Transportation Branch. 1p. 17426:068.

--8303040106 "Package Evaluation, Model GNG-20, Type B Quantities." HOPCRAFT, C P.; ACREE, E H. Gulf Nuclear, Inc. 83/01/28. 28pp. 17426:131.

8303290537 Summary of 830317 meeting w/vendor in Silver Spring, MD re review of util 830128 suppls concerning listed models. Closure mechanism on Model GNM-20 package should be redesigned to provide positive closure for transport. ODEGAARDEN, R H. Transportation Branch. 83/03/22. Transportation Branch. 2pp. 17740:356.

8303290682 Advises that 830128 supplemental application requesting approval of Certificate of Compliance 9163 for Model GNG-20 not responsive to NRC 820514 request. QA program should be expanded to include design, fabrication & testing. MACDONALD, C E. Transportation Branch. 83/03/22. PAYNE, A E. Gulf Nuclear, Inc. 1p. 17745:134.

DOCKET 71-9166 MODEL: 864 TYPE B. TECHNICAL OPERATIONS, INC.

8303230448 Forwards Rev 0 to Certificate of Compliance 9166 for Model 864. MACDONALD, C E. Transportation Branch. 83/02/10. MUNRO, J J. Technical Operations, Inc. 1p. 17677:261.

--8303230452 Certificate of Compliance 9166, Rev 0, for Model 864. MACDONALD, C E. Transportation Branch. 83/02/10. 2pp. 17677:262.

--8303230457 SER supporting application for Rev 0 to Certificate of Compliance 9166 for Model 864. MACDONALD, C E. Transportation Branch. 83/02/10. 6pp. 17677:264.

8303240191 Advises that Tech Ops 820715 application requesting NRC certificate of compliance for Model 864 package acceptable. MACDONALD, C E. Transportation Branch. 83/02/10. RAWL, R R. Transportation, Dept of. 1p. 17696:352.

DOCKET 71-9167 MODEL: 3206B, 3227B & 3218. AMERSHAM CORP.

8303280356 Requests IAEA certificate of competent authority for Models 3206B, 3227B & 3218 approved under Certificate of Compliance 9167. BAGBY, L A. Amersham Corp. 83/03/04. RAWL, R. Transportation, Dept of. 1p. 17713:088.

8303290713 Advises that packages authorized by Certificate of Compliance 9167 meet requirements for Type B(4) packages. Approval conditioned to require serially numbered leadwire seal in combination w/closure mechanism. MACDONALD, C E. Transportation Branch. 83/03/11. RAWL, R R. Transportation, Dept of. 1p. 17745:172.

8303300112 Forwards Rev 0 to Certificate of Compliance 9167 for Models 3206B, 3227B & 3218. MACDONALD, C E. Transportation Branch. 83/03/11. BAGBY, L A. Amersham Corp. 1p. 17750:331.

--8303300117 Certificate of Compliance 9167, Rev 0 for Models 3206B, 3227B & 3218. MACDONALD, C E. Transportation Branch. 83/03/11. 9pp. 17750:332.

DOCKET 71-9783 MODEL: S5W ITR. ENERGY, DEPT OF.

8303030233 Forwards Rev 1 to Certificate of Compliance 9783 for Model S5W ITR. MACDONALD, C E. Transportation Branch. 83/02/23. ENGEL, W P. Energy, Dept. of. 1p. 17364:342.

--8303030243 Certificate of Compliance 9783, Rev 1, for Model S5W ITR. MACDONALD, C E. Transportation Branch. 83/02/23. 4pp. 17364:343.

DOCKET 71-9855 MODEL: ORNL DOT SPEC 6M SPECIAL FORM PACKAGE. ENERGY.

8303030311 Informs that 830105 request for review of Model DOT-6M for Certificate of Compliance 9855 not required. MACDONALD, C E. Transportation Branch. 83/02/23. PRICHARD, R P. Energy, Dept. of. 1p. 17365:175.

## LICENSING OF INDEPENDENT SPENT FUEL STORAGE

DOCKET 72-0001 MORRIS OPERATIONS, GENERAL ELECTRIC CO.

8303030567 Forwards IE Insp Rept 72-0001/83-01 on 830111-13 & 24. No noncompliance noted. PAPERIELLO, C J. Division of Emergency Preparedness & Operational Support. 83/02/15. VAN HOOMISSEN. General Electric Co. 2pp. 17409:031.

--8303030584 IE Insp Rept 72-0001/83-01 on 830111-13 & 24. No noncompliance noted. Major areas inspected: fuel receipt & storage; radiation protection; surveillance tests; safety committees; emergency planning & environ monitoring. PECK, C C.; JANUSKA, A G.; GREGER, L R. Region 3, Office of Director. 83/02/14. 6pp. 17409:033.

8303100568 "Airborne Effluents Released to Environ During CY82." EGER, K J. General Electric Co. 83/02/17. Region 3, Office of Director. 2pp. 17521:348.

DOCKET 72-0002 VIRGINIA ELECTRIC & POWER CO

8303020215 Forwards suppl to ISFSI SAR which reflects actual submittal of C-E Topical Rept CENPD-270 describing design for dry storage casks appropriate for use in storage
STEWART, W L Virginia Electric & Power Co 83/01/25
CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards Director 3pp 17357 357 24X Fiche 50-280, 83/01/25, 8303020215

DOCKET 72-0002 VIRGINIA ELECTRIC & POWER CO

8303280315 Comments on util application for ISFSI Topical rept review comments to C-E encl to keep util appraised of progress of review of C-E rept, "Dry Storage Cask for ISFSI," dtd Oct 1982
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 83/03/16
STEWART, W L Virginia Electric & Power Co 37pp 17713 251 24X Fiche 50-280, 83/03/16, 8303280315

# NONDOCKETED ITEMS

10CFR COMMISSION MEETING RECORDS

8303010716 Transcript of 830217 affirmation/discussion & vote in Washington, DC. Pp 1-4.
* Commissioners. 83/02/17. 8pp. 17354:304.

8303040204 Transcript of 830222 public meeting in Washington, DC re discussion of SECY-83-16A on regulations to implement Public Law 97-415. Pp 1-60.
* Commissioners. 83/02/22. 62pp. 17427:081.

--8303040214 Comments on SECY-83-16 re whether OL amends involve no significant hazards consideration. Urges NRC to delete from rule ref to reracking as example of OL amend that involves significant hazards consideration.
COUNSIL, W. G. Northeast Utilities Service Co. B10682. 83/02/09.
PALLADINO, N. J. Commissioners. 3pp. 17427:144.

--8303040223 Comments on draft proposal re license amends involving no significant hazards considerations, specifically reracking of spent fuel storage pool. Including reracking as example of amend inconsistent w/prior legislation.
MCGARRY, J. M. Debevoise & Liberman. 83/02/14. PALLADINO, N. J. Commissioners. 12pp. 17427:147.

--8303040233 Comments on SECY-83-16 re proposed amend which would establish criteria for determining whether license amend constitutes significant hazards consideration. Including spent fuel pool reracking not warranted.
THIES, A. C. Duke Power Co. 83/02/08. PALLADINO, N. J. Commissioners. 9pp. 17427:159.

8303040345 Staff requirements memo re 830222 discussion of SECY-83-16A, "Regulations to Implement Public Law 97-415."
CHILK, S. J. Office of the Secretary of the Commission. M830222.
83/02/28. DIRCKS, W. J. Office of the Executive Director for Operations. 1p. 17426:303.

8303100023 Staff requirements memo re 830217 briefing in Washington, DC on shift manning requirements.
CHILK, S. J. Office of the Secretary of the Commission. M830217A.
83/02/28. DIRCKS, W. J. Office of the Executive Director for Operations. 1p. 17494:144.

8303100144 Transcript of 830301 meeting in Washington, DC re regulatory reform task force administrative proposals concerning backfit rule. Pp 1-87. Proposed rule & draft policy statement encl.
* Commissioners. 83/03/01. 112pp. 17496:029.

8303110128 Staff requirements memo re 830302 briefing in Washington, DC on reactor trip breaker failure & corrective actions.
CHILK, S. J. Office of the Secretary of the Commission. M830302A.
83/03/07. DIRCKS, W. J. Office of the Executive Director for Operations. 2pp. 17526:080.

8303110135 Staff requirements memo re 830301 discussion in Washington, DC on regulatory reform task force administrative proposals.
CHILK, S. J. Office of the Secretary of the Commission. M830301.
83/03/07. TOURTELLOTTE, J. Regulatory Reform Task Force. 1p. 17523:117.

8303110140 Transcript of 830303 briefing on nuclear data link in Washington, DC. Pp 1-69. Supporting documentation & viewgraphs encl.
* Commissioners. 83/03/03. 76pp. 17523:314.

8303140697 Staff requirements memo re 830302 briefing in Washington, DC on NRC action on location of emergency operations facilities.
CHILK, S. J. Office of the Secretary of the Commission. M830302B.
83/03/03. DIRCKS, W. J. Office of the Executive Director for Operations. 1p. 17569:178.

8303140702 Staff requirements memo re 830304 briefing in Washington, DC on CRGR activities.
CHILK, S. J. Office of the Secretary of the Commission. M830304A.
83/03/04. DIRCKS, W. J. Office of the Executive Director for Operations. 1p. 17569:172.

8303150150 Transcript of 830304 briefing in Washington, DC re CRGR activities. Pp 1-85. Computer printout encl.
* Commissioners. 83/03/04. 118pp. 17599:345.

8303160633 Transcript of 830302 public meeting in Washington, DC re staff actions on location of emergency operations facilities. Pp 1-62.
* Commissioners. 83/03/02. 76pp. 17603:193.

8303180399 Staff requirements memo re 830303 briefing in Washington, DC on nuclear data link prototype sys.
CHILK, S. J. Office of the Secretary of the Commission. M830303A.
83/03/15. DIRCKS, W. J. Office of the Executive Director for Operations. 1p. 17640:167.

8303230138 Transcript of 830315 briefing in Washington, DC re reactor trip breaker failures at facility. Pp 1-116. V Gilinsky 830315 memo to Commission & viewgraphs encl.
* Commissioners. 83/03/15. 165pp. 17689:262.

8303230316 Transcript of 830311 briefing in Washington, DC re INPO evaluation program. Pp 1-66. Outline of industry comments encl.
* Commissioners. 83/03/11. 109pp. 17686:068.

8303230340 Transcript of 830314 briefing in Washington, DC re interim independent design verification program. Pp 1-82.
* Commissioners. 83/03/14. 98pp. 17674:279.

8303280345 Transcript of 830318 briefing on Nuclear Waste Mgt Act in Washington, DC. Pp 1-83.
* Commissioners. 83/03/18. 85pp. 17712:240.

--8303280348 SECY-83-107
Advises of principal provisions of Public Law 97-425, Nuclear Waste Policy Act of 1982, affecting NRC.
DIRCKS, W. J. Office of the Executive Director for Operations. 83/03/16. 123pp. 17712:325.

8303290399 Transcript of 830324 meeting in Washington, DC re briefing on plant post-trip rept. Pp 1-89. Twelve viewgraphs encl.
* Commissioners. 83/03/24. 104pp. 17727:103.

8303300150 Unofficial transcript of 830324 affirmation/discussion & vote in Washington, DC re SECY-83-168, regulation to implement Public Law 97-415. Pp 1-5.
* Commissioners. 83/03/24. 6pp. 17751:038.

8303300386 Transcript of 830324 public briefing by ad hoc Committee on Regulatory Reform-Administrative Proposals in Washington, DC. Pp 1-72.
* Commissioners. 83/03/24. 99pp. 17754:174.

8303300659 Final response to FOIA request for documents re NRC 820521 closed briefing on design basis threat. Forwards Documents 1-3 listed in app. Releasable portions of meeting transcript available in PDR. Document 4 released via FOIA-77-14 & 106.
FELTON, J. M. Division of Rules and Records. 83/03/04. COCHRAN, T. B. Natural Resources Defense Council. 2pp. 17765:187.

--8205240601 Staff requirements memo requesting current views on appropriate kind & degree of threat & vulnerabilities to such threat. Response to be submitted by 820513.
CHILK, S. J. Office of the Secretary of the Commission. 82/04/22.
DIRCKS, W. J. Office of the Executive Director for Operations. 1p. 17765:194.

--8303300688 Staff requirements memo re 820521 closed briefing on design basis threat Commission agreed that changes to current statements of design basis threat contained in 10CFR73.1(a) not warranted at this time.
CHILK, S. J. Office of the Secretary of the Commission. MB20521. 82/05/27. DIRCKS, W. J. Office of the Executive Director for Operations. 1p. 17765:195.

--8303300693 Staff requirements memo requesting clarification of meaning of "several" used in safeguards design basis threat of 10CFR73.1(a)(1). Response requested by 830115.
CHILK, S. J. Office of the Secretary of the Commission. 82/12/23. DIRCKS, W. J. Office of the Executive Director for Operations. 1p. 17765:196.

ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

8302080455 Trip rept of attendance at EPRI pressurized thermal shock program & thermal mixing technology 821007-08 workshop at CREARE in Hanover, NH.
CATTON, I. ACRS - Advisory Committee on Reactor Safeguards. 82/10/25. IGNE, I. ACRS - Advisory Committee on Reactor Safeguards. 3pp. 17107:342.

8303100107 Forwards NRR response to ACRS recommendations following 271st & 272nd meetings, per 821208 & 830107 memos.
GOODWIN, E. F. Technical Support Branch. 83/02/15. FRALEY, R. F. ACRS - Advisory Committee on Reactor Safeguards. 5pp. 17504:036. 24X Fiche 50-000, 83/02/15, 8303100107.

--8212290471 Comments on rulemaking re staffing at plants & draft policy statement on shift crew qualifications. Agrees w/proposal to amend 10CFR50.54(m) to require sufficient number of senior reactor operators on each shift.
SHEWMON, P. ACRS - Advisory Committee on Reactor Safeguards. 82/12/14. PALLADINO, N. J. Commissioners. 3pp. 17504:052.

--8212290054 Summarizes 272nd ACRS meeting on 821209-11 re proposed changes to 10CFR20, 50.54 & 140. Recommendations endorsed.
SHEWMON, P. ACRS - Advisory Committee on Reactor Safeguards. 82/12/14. DIRCKS, W. J. Office of the Executive Director for Operations. 4pp. 17504:056.

--8212290059 Submits ACRS recommendation on Reg Guide 1.150, "Ultrasonic Testing of Reactor Vessel Welds During Preservice & Inservice Exam," per 810205-07 meeting. Urges implementation of Reg Guide 1.150 & acceptance of industry alternative.
SHEWMON, P. ACRS - Advisory Committee on Reactor Safeguards. 82/12/14. DIRCKS, W. J. Office of the Executive Director for Operations. 1p. 17504:058.

--8212130273 Comments on NRC integrated human factors program plan. Program would benefit from initial appraisal of current status of matters covered in plan. Proposal to form review group to oversee program applauded.
SHEWMON, P. ACRS - Advisory Committee on Reactor Safeguards. 82/11/09. DIRCKS, W. J. Office of the Executive Director for Operations. 2pp. 17504:066.

8303110210 Transcript of ACRS Subcommittee on Reliability & PRA 830309 meeting in Washington, DC. Pp. 1-351. Viewgraphs encl.
* ACRS - Advisory Committee on Reactor Safeguards. 83/03/09. 456pp. 17514:001.

8303150190 Transcript of ACRS 275th general meeting on 830310 in Washington, DC. Pp. 1-414. Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards. 83/03/10. 604pp. 17551:190.

8303150493 Transcript of ACRS 275th general meeting on 830311 in Washington, DC. Pp. 1-367. Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards. 83/03/11. 550pp. 17558:059.

8303150718 Summary of ACRS Subcommittees on Reactor Radiological Effects & Site Evaluation 821112-13 meetings in Washington, DC re proposed revs, review of draft statement on potassium iodide & position on seismic events in emergency planning.
* ACRS - Advisory Committee on Reactor Safeguards. 83/01/10. ACRS - Advisory Committee on Reactor Safeguards. 24pp. 17583:336.

8303160648 Forwards EA Warman presentation before ACRS combined Subcommittee on Class 9 Accidents & Reactor Radiological Effects 830222 meeting re source term program.
BUCCI, D. ACRS - Advisory Committee on Reactor Safeguards. 83/02/25. DIRCKS, W. Office of the Executive Director for Operations. DENTON, H. Office of Nuclear Reactor Regulation, Director. MATTSON, R. Division of Systems Integration (post 811005). 1p. 17600:311.

--8303160650 Presentation before ACRS combined Subcommittee on Class 9 Accidents & Reactor Radiological Effects 830222 meeting re source term program.
WARMAN, E. A. Stone & Webster Engineering Corp. 83/02/22. 16pp. 17600:312.

8303170273 Summary of ACRS Subcommittee on Generic Items 821208 meeting in Washington, DC re methodology used in prioritization of generic safety issues.
* ACRS - Advisory Committee on Reactor Safeguards. 82/12/10. ACRS - Advisory Committee on Reactor Safeguards. 19pp. 17615:332.

8303170669 Summary of ACRS Subcommittee on Human Factors 821028 meeting in Washington, DC re proposed rule on licensed operating staffing at nuclear power units & other related staffing issues.
* ACRS - Advisory Committee on Reactor Safeguards. 83/01/07. ACRS - Advisory Committee on Reactor Safeguards. 27pp. 66687:248.

8303180175 Summarizes 821130-1201 meetings w/USGS & NRC re Charleston earthquake. Earthquake problem is generic to eastern US seismicity.
POMEROY, P. W. Rondout Associates. POMEROY, P. W. ACRS - Advisory Committee on Reactor Safeguards. 82/12/03. OKRENT, D. ACRS - Advisory Committee on Reactor Safeguards. 3pp. 17625:348.

8303180285 Transcript of ACRS Subcommittee on Regulatory Policy & Procedures 830316 meeting in Washington, DC. Pp. 1-116.
* ACRS - Advisory Committee on Reactor Safeguards. 83/03/16. 116pp. 17616:009.

8303180683 Comments on risk assessment portion of draft Science Applications, Inc 820923 study, "Value-Impact Analysis of Recommendations re Steam Generator Tube Degradations & Rupture Events."
DAVIS, P. R. Affiliation Unknown. DAVIS, P. R. ACRS - Advisory Committee on Reactor Safeguards. 83/02/01. MAJOR, R. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 17637:020.

8303210104 Comments on issues raised at ACRS Subcommittee on Class 9 Accidents 830121 meeting. Melt progression sensitivity & uncertainty analysis program should be directly used in planning future in-pile experiments.
CORRADINI, M. Wisconsin, Univ. of, Madison. 83/01/25. BUCCI, D. ACRS - Advisory Committee on Reactor Safeguards. 4pp. 17640:358.

--8303210108 Submits info re time spent preparing for ACRS Subcommittee on Class 9 Accidents 830121 meeting.
CORRADINI, M. Wisconsin, Univ. of, Madison. 83/01/25. BUCCI, D. ACRS - Advisory Committee on Reactor Safeguards. 1p. 17640:362.

8303210142 Concurs w/recommendation that proposal re training of human factors engineers for operation be included in next agenda.
PEARSON, R. G. ACRS - Advisory Committee on Reactor Safeguards. PEARSON, R. G. North Carolina State Univ. 83/02/09. FISCHER, D. WARD, D. ACRS - Advisory Committee on Reactor Safeguards. 1p. 17660:168.

8303210144 Comments on issues raised at ACRS Subcommittee on Class 9 Accidents 830121 meeting, including severe fuel damage research program & integral in-pile tests at power burst facility.
LEE, J. C. Michigan, Univ. of. LEE, J. C. ACRS - Advisory Committee on Reactor Safeguards. 83/01/28. BUCCI, D. R. ACRS - Advisory Committee on Reactor Safeguards. 3pp. 17660:169.

8303210147 Comments on progress of severe fuel damage program. Shift of funds from in-pile to out-of-pile experiments recommended.
SOLOMON, A. A. Affiliation Unknown. 83/02/01. KERR, W. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 17660:172.

8303220012 Transcript of ACRS Subcommittee on Program for Qualification of Safety-Related Equipment 830315 meeting in Washington, DC. Pp. 1-295. Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards. 83/03/15. 383pp. 17653:274.

8303220021 Transcript of ACRS Subcommittee on Waste Mgt 830318 meeting in Washington, DC. Pp. 1-267. Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards. 83/03/18. 336pp. 17652:298.

8303310086 Transcript of ACRS Subcommittees on Metal Components & Combination of Dynamic Loads 830329 meeting in Washington, DC. Pp. 1-260.
* ACRS - Advisory Committee on Reactor Safeguards. 83/03/29. 414pp. 17759:128.

COMMISSION NRC COMMISSIONERS

8303020299 Forwards status rept of recommendations made by Reactor Safety Research Review Group. Majority of recommendations under implementation.
PALLADINO, N. J. Commissioners 83/02/10 BABBITT, B. Arizona, State of. 7pp 17355:291

--8303020304 Requests update on implementation of recommendations made by Nuclear Safety Research Review Group.
BABBITT, B. ; DEUTCH, J. ; LEWIS, H. Affiliation Unknown 82/12/15
PALLADINO, N. J. Commissioners 1p 17355:298

8303030122 Forwards revs to monthly status rept on emergency preparedness.
DIRCKS, W. J. Office of the Executive Director for Operations 83/02/16 PALLADINO, N. J. Commissioners 3pp 17365:350

8303030176 Responds to 830120 ltr commenting on inadequacy of radiological emergency response planning for communities surrounding facility. Ltr forwarded to FEMA & PA Emergency Mgt Agency for further response.
HAYNES, R. C. Region 1, Office of Director 83/02/09 NEMETHY, E. Affiliation Unknown 5pp 17365:256

--8303030191 Comments on inadequacy of radiological emergency response planning for areas surrounding facility.
NEMETHY, E. Affiliation Unknown 83/01/20 ASSELSTINE, J. Commissioners 5pp 17365:260

8303040112 Weekly info rept for wk ending 830218.
REHM, T. A. Office of the Executive Director for Operations 83/02/24 38pp 17425:096

8303040180 Ack receipt of 830201 ltr on behalf of IDCOR Program supporting Commission adoption of SECY-82-01B, "Proposed Commission Policy Statement on Severe Accidents & Related Views on Nuclear Reactor Regulation."
DIRCKS, W. J. Office of the Executive Director for Operations 83/02/18 REED, C. Commonwealth Edison Co 1p 17427:300

--8301200157 Summary of 273rd ACRS meeting on 830106-08 re SECY-82-01B on proposed Commission policy statement on severe accidents & related views on nuclear reactor regulation.
RAY, J. J. ACRS - Advisory Committee on Reactor Safeguards 83/01/10 PALLADINO, N. J. Commissioners 8pp 17427:337

--8303040244 Expresses strong support for Commission adoption of SECY-82-01B proposing severe accident policy statement on behalf of IDCOR Program.
REED, C. Commonwealth Edison Co 83/02/01 PALLADINO, N. J. Commissioners 2pp 17427:344

8303040181 Responds to 830125 request for attendance at Committee on Away-From-Reactor Storage 830217 meeting. LC Rouse designated NRC representative to outline NRC responsibilities re spent fuel storage specified by Nuclear Waste Policy Act of 1982.
AHEARNE, J. F. Commissioners 83/02/15 RILEY, R. W. South Carolina, State of 1p 17427:016

--8303040185 Notifies of Committee on Away-From-Reactor Storage 830217 meeting in Columbia, SC to review Nuclear Waste Policy Act of 1982 & implications for mgt & storage of spent nuclear fuel. NRC representative invited.
RILEY, R. W. South Carolina, State of 83/01/25 PALLADINO, N. J. Commissioners 1p 17427:017

8303040191 Forwards comments on GAO recommendations in 821215 rept, "Problems & Delays Overshadow NRC Initial Success in Improving Reactor Operator Capabilities." Development activities being reviewed to ensure improvement.
PALLADINO, N. J. Commissioners 83/02/10 ROTH, W. V. Senate, Governmental Affairs 6pp 17427:010

8303040194 Accepts 830125 invitation for H Denton to appear as panelist at Session 4, "Social Environ for Nuclear Power Development," on 830325 in Tokyo, Japan.
PALLADINO, N. J. Commissioners 83/02/10 ARISAWA, H. Japan, Govt of, 1p 17427:001

--8303040198 Invites H Denton to Japan Industrial Forum, Inc 830323-25 annual conference in Tokyo to discuss NRC safety goals.
ARISAWA, H. Japan, Govt of, 83/01/25 PALLADINO, N. J. Commissioners 8pp 17427:002

8303040299 Responds to 830128 request for info re credentials of members of Commission & procedures in cases of repeated accidents. Commission members appointed by President. Biographies of members encl.
DIRCKS, W. J. Office of the Executive Director for Operations 83/02/18 YATRON, G. House of Rep 11pp 17426:258

--8303040310 Requests response to constituent C Walker 830115 ltr re credentials of members of Commission & procedures to be employed in cases of repeated accidents at nuclear stations.
YATRON, G. House of Rep 83/01/28 KAMMERER, C. Office of Congressional Affairs 4pp 17426:268

8303090200 Weekly info rept for wk ending 830225.
REHM, T. A. Office of the Executive Director for Operations 83/03/03 40pp 17485:017

8303100516 Forwards proposed bill authorizing appropriations for FY84 & 85 & analysis of bill.
PALLADINO, N. J. Commissioners 83/03/01 O'NEILL, T. P. House of Rep., Speaker of the House BUSH, G. H. Senate, President of the Senate SIMPSON, A. Senate, Environment & Public Works 13pp 17521:297

8303100520 Forwards CY82 FOIA administration rept per 741121 Public Law 93-502.
PALLADINO, N. J. Commissioners 83/02/24 O'NEILL, T. P. House of Rep., Speaker of the House 7pp 17521:288

8303100552 Responds to 830121 ltr re potentially faulty steel products which may have been supplied to NRC licensees by Ray Miller, Inc. Specific corrective actions in answer to eight questions encl.
PALLADINO, N. J. Commissioners 83/03/02 OTTINGER, R. L. House of Rep., Energy & Commerce 14pp 17504:089

--8303100556 PNO-IE-83-002A IE Notice 83-01 re fraudulent practices of Ray Miller, Inc distributed to regional ofcs on 830124. Two former employees will be interviewed 830125-26 to determine scope of fraudulent practices.
BAER, R. L. ; CUNNINGHAM, L. J. Director's Office, Office of Inspection and Enforcement 83/01/24 1p 17504:118

--8303100559 Forwards basic ltr addressing recent QA concerns sent to each nuclear util chief executive officer.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/01/26 DIRCKS, D. J. Office of the Executive Director for Operations 1p 17504:119

--8303100561 Forwards info on recent deficiencies in quality due to fraudulent activities by equipment suppliers.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/01/26 LEE, W. S. Duke Power Co 2pp 17504:120

--8303100563 Advises that some NRC licensees & DOE nuclear facilities may have installed or retained in inventory, faulty steel products supplied by Ray Miller Inc. R Miller found guilty of fraudulent activities.
OTTINGER, R. L. House of Rep., Energy & Commerce 83/01/21
PALLADINO, N. J. Commissioners 4pp 17504:142

8303110024 Agrees w/American College of Cardiology position to sponsor task force w/NRC participation to study issues of training requirements for physicians conducting cardiovascular diagnostic studies.
PALLADINO, N. J. Commissioners 83/03/02 KNOEBEL, S. B. American College of Cardiology 1p 17546:249

8303140629 Responds to 830128 ltr re fraudulent practices of Ray Miller, Inc. NRC actions taken & to be taken outlined. Action plans to deal w/potential safety concerns to be developed.
PALLADINO, N. J. Commissioners 83/03/01 MARKEY, E. J. House of Rep., Interior & Insular Affairs 6pp 17583:001

--8303140632 Forwards ltrs sent to utils on QA concerns.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/01/26 DIRCKS, W. J. Office of the Executive Director for Operations 1p 17583:007

--8303140637 Forwards info on recent deficiencies in quality arising from fraudulent activities of equipment suppliers. Info provided so util can assess need to act to ensure highest stds of quality.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/01/26 LEE, W. S. Duke Power Co 2pp 17583:008

--8303140644 Expresses concern re NRC handling of Ray Miller, Inc fraudulent practices investigation. NRC discussion of ongoing criminal investigation w/AIF before public notice on problem published questioned.
MARKEY, E. J. House of Rep., Interior & Insular Affairs 83/01/28
PALLADINO, N. J. Commissioners 1p 17583:061

# NONDOCKETED ITEMS

8303150005 Forwards responses to remaining questions in 830114 ltr re temporary authority to issue OLs contained in Public Law 97-415.
PALLADINO,N. Commissioners 83/03/02 OTTINGER,R.L. House of Rep 9pp 17597 154

8303160089 Weekly info rept for wk ending 830304.
REHM,T.A. Office of the Executive Director for Operations 83/03/11 7lpp 17604 133

8303160617 Ack receipt of util 830209 comments on NRC legislation & backfitting program.Open Commission meeting scheduled for 830301 to discuss backfitting process.Policy statement & proposed rule will be formulated.W/o encl.
PALLADINO,N.J. Commissioners 83/02/25 TRIBBLE,J.E. Yankee Atomic Electric Co 2pp 17603 185

--8303160622 Comments on generic & plant-specific backfitting.Codified backfitting controls would restore confidence in responsible NRC regulation.
TRIBBLE,J.E. Yankee Atomic Electric Co. 83/02/09 PALLADINO,N.J. Commissioners 4pp 17603 187

8303160717 Ack receipt of 830210 ltr.Proposed licensing reform legislation forwarded to Congress.
PALLADINO,N.J. Commissioners 83/02/25 MOORHEAD,C. House of Rep.; Energy & Commerce 1p 17600 230

--8303160721 Advises that nuclear licensing reform proposals should address short-term problems such as backfitting & public hearings & long-term obstacles such as two-stage licensing & duplicative environ reviews.
SIMPSON,A.K. Senate; Environment & Public Works MOORHEAD,C.J. House of Rep.; Energy & Commerce 83/02/10 PALLADINO,N.J. Commissioners 2pp 17600 231

8303180606 Forwards status rept on NRC requirements which exceed scope of current regulations.Rept includes review of NUREG-0737 Items I.A.1.3,I.A.2.1,I.A.2.3,I.C.1.2,I.C.5,II.B.1, II.K.2.11,II.K.3.44 & I.G.1.
DIRCKS,W.J. Office of the Executive Director for Operations 83/03/10 AHEARNE,J. Commissioners 8pp 17626 350

--8303180622 Requests Executive Director of Operations rept describing areas requiring regulation not covered by current regulation.
AHEARNE,J. Commissioners 83/01/21 CHILK,S.J. Office of the Secretary of the Commission 1p 17626 358

--8303180627 Advises of Commission approval of recommendations not to issue final rule imposing NUREG-0737 provisions on OL applicants.
CHILK,S.J. Office of the Secretary of the Commission 83/02/01
DIRCKS,W.J. Office of the Executive Director for Operations 2pp 17626 359

8303240062 Weekly info rept for wk ending 830311.
REHM,T.A. Office of the Executive Director for Operations 83/03/18 46pp 17694 285

8303290224 Requests info re FAA licensing practices in design,const & operation of aircraft & safety allocations among designer, manufacturer & operator as part of ongoing reform of nuclear reactor licensing.Briefing scheduled for 830404.
PALLADINO,N.J. Commissioners 83/03/03 HELMS,J.L. Federal Aviation Administration 1p 17727 328

8303290617 Weekly info rept for wk ending 830318.
REHM,T.A. Office of the Executive Director for Operations 83/03/24 48pp 17745 053

8303300071 Responds to 830124 ltr transmitting ANS statement of position on draft final high level waste technical criteria & supporting rationale document.Discussions on development of addl industry stds for satisfying 10CFR60 welcome.
DIRCKS,W.J. Office of the Executive Director for Operations 83/03/02 MUNTZING,L.M. American Nuclear Society 2pp 17751 061

8303310089 Expresses concern re proposed regionalization of operating reactor project mgt function.Regionalization would reduce NRC effectiveness in performing regulatory function & could reduce plant safety.Access to headquarters expertise needed.
FAIRTILE,M.D.; BEVAN,R.B.; DIIANNI,D.C. Assistant Director for Operating Reactors 83/03/14 PALLADINO,N.J.; GILINSKY,V.; AHEARNE,J. Commissioners 3pp 17763 052

CONTRACT NRC CONTRACTS AND MODIFICATIONS

8303010014 Notification of contract execution: "Electrostatic Copying & Related Svcs." awarded to Literature Research Co.
Solicitation,offer & award encl.
HAGEY,H. Administrative Contracts Branch NRC-10-83-318 83/02/10
BESAW,W.J.; BAGGETT,M. Division of Technical Information & Document Control 1p 17322 236

--8303010018 Solicitation,offer & award,to "Electrostatic Copying & Related Svcs." awarded to Literature Research Co.
BULLINGTON,R.L. Literature Research Corp MATTIA,M.J. Division of Contracts NRC-10-83-318 83/02/10 80pp 17322 237

8303010712 Notification of contract execution: "Computer Output Microfilm Production," awarded to Anacomp,Inc.
JACOBS,A. Administrative Contracts Branch NRC-10-83-297 83/02/15
BESAW,W.J. Division of Technical Information & Document Control SKOCZLAS,J. NRC - No Detailed Affiliation Given 1p 17354 312

--8303010714 Contract: "Computer Output Microfilm Production," awarded to Anacomp,Inc.
* Anacomp, Inc MATTIA,M.J. Division of Contracts
NRC-10-83-297 83/02/15 32pp 17354 313

8303010721 Notification of contract execution,Mod 1 to "Cobalt Teletherapy Calibr Course," Contractor MD Anderson Hosp.
HOYLE,A. Administrative Contracts Branch FIN B-5090
NRC-06-83-267 83/02/18 KERR,G.W. Office of State Programs, Director BOLLING,L.A. NRC - No Detailed Affiliation Given 1p 17348 302

--8303010730 Mod 1,exercising govt option to prepare & conduct second course under Article III,to "Cobalt Teletherapy Calibr Course."
* M.D. Anderson Hosp.; Houston, TX REBELLO,J.E. Division of Contracts FIN B-5090 NRC-06-83-267 83/02/18 1p 17348 303

8303\20068 Notification of contract execution,Mod 5 to "Investigation Program at Maxey Flats Radwaste Burial Facility," Contractor Commonwealth of KY.
WOLLETT,S. Technical Assistance Contracts Branch FIN B-6192
NRC-04-78-259 83/01/07 BATSON,W. Office of Nuclear Regulatory Research, Director O'DONNELL,E. NRC - No Detailed Affiliation Given 1p 17359 333

--8303020072 Mod 5,changing principal investigator,to "Investigation Program at Maxey Flats Radwaste Burial Facility."
SWEIGART,J. Kentucky, Commonwealth of; GUSTAVE,R.P. Division of Contracts FIN B-6192 NRC-04-78-259 83/01/07 1p 17359 334

8303020077 Notification of contract execution,Mod 8 to "Applications of Two-Phase Flow Quantitative Characterization to BWR Void Distribution Measurements," Contractor Univ of WA.
JACOBS,A.; WOLLETT,S. Technical Assistance Contracts Branch FIN B-6324 NRC-04-78-245 83/02/10 BATSON,W. Office of Nuclear Regulatory Research, Director ZUBER,N. NRC - No Detailed Affiliation Given 1p 17359 335

--8303020082 Mod 8,extending period of performance to 831231 & increasing funds,to "Applications of Two-Phase Flow Quantitative Characterization to BWR Void Distribution Measurements."
ZIMMERMAN,B.J. Washington, Univ. of GUSTAVE,R.P. Technical Assistance Contracts Branch FIN B-6324 NRC-04-78-245 83/02/10 5pp 17359 336

8303020176 Notification of contract execution: "Purchase & Installation of Low Background Alpha/Beta Counting Sys." awarded to Tennelec,Inc.
JACOBS,A. Administrative Contracts Branch FIN B-6558
NRC-32-83-689 83/02/22 ALEXANDER,I. Office of Resource Management, Director HAMADA,G. NRC - No Detailed Affiliation Given 1p 17355 242

--8303020177 Contract: "Purchase & Installation of Low Background Alpha/Beta Counting Sys." awarded to Tennelec,Inc.
* Tennelec, Inc. MATTIA,M.J. Division of Contracts FIN B-6558
NRC-32-83-689 83/02/22 36pp 17355 243

8303020480 Notification of contract execution,Mod 5 to "Engineering Characterizations of Seismic Motion for Nuclear Power Plant Design," Contractor Woodward-Clyde Consultants.
WOLLETT,S. Technical Assistance Contracts Branch FIN B-6680
NRC-04-82-192 83/02/25 FOREHAND,W. Office of Nuclear Regulatory Research, Director COSTELLO,J. NRC - No Detailed Affiliation Given 1p 17357 089

--8303020481 Mod 5, adding funds & work scope & extending period of performance to 840228, to "Engineering Characterizations of Seismic Motion for Nuclear Power Plant Design."
* Woodward-Clyde Consultants, Inc GUSTAVE, R P Division of Contracts FIN B-6680 NRC-04-82-192 83/02/25 16pp 17357 090

8303030062 Notification of contract execution "Multiple Award Task Order Contract For ADP Development," awarded to Advanced Technology, Inc
MILES, E B Administrative Contracts Branch NRC-33-83-452-02 83/02/25 BASSETT, H Office of Resource Management, Director HARVES, J NRC - No Detailed Affiliation Given 1p 17426 200

--8303030071 Contract "Multiple Award Task Order Contract For ADP Development," awarded to Advanced Technology, Inc
LOTITO, M A Advanced Technology, Inc MATTIA, M J Division of Contracts NRC-33-83-452-02 83/02/25 40pp 17426 201

8303030222 Notification of contract execution, Mod 9 to "Development of Nuclear Reactor Plant Data Bank." Contractor SBA, Subcontractor Technology Development c* CA
FLYNN, M Technical Assistance Contracts Branch FIN B-7077 NRC-04-80-215 83/02/23 BATSON, W Office of Nuclear Regulatory Research, Director LEE, T NRC - No Detailed Affiliation Given 1p 17364 347

--8303030231 Mod 9, funding addl task, to "Development of Nuclear Reactor Plant Data Bank."
GUENERO, L Small Business Administration HALE, R Technology Development of California, Inc GUSTAVE, R P Division of Contracts FIN B-7077 NRC-04-80-215 83/02/23 4pp 17364 348

8303030238 Notification of contract execution, Mod 17 to "FLECHT-SEASET." Contractor Westinghouse & EPRI
WOLLETT, S Technical Assistance Contracts Branch FIN B-6204 NRC-04-77-127 83/01/05 BATSON, W Office of Nuclear Regulatory Research, Director LEE, R NRC - No Detailed Affiliation Given 1p 17419 358

--8303030244 Ltr contract NRC-04-77-127, Mod 17, increasing funding, to "FLECHT-SEASET." Accepted by HB Rosenblatt on 830105
GUSTAVE, R P Technical Assistance Contracts Branch FIN B-6204 NRC-04-77-127 82/12/30 ROSENBLATT, H Westinghouse Electric Corp 1p 17419 359

8303030252 Notification of contract execution, Mod 18 to "FLECHT-SEASET." Contractor Westinghouse & EPRI
WOLLETT, S Technical Assistance Contracts Branch FIN B-6204 NRC-04-77-127 83/01/17 BATSON, W Office of Nuclear Regulatory Research, Director LEE, R NRC - No Detailed Affiliation Given 1p 17419 354

--8303030256 Ltr Contract NRC-04-77-127, Mod 18, increasing funds, to "FLECHT-SEASET." Accepted by HB Rosenblatt on 830117
GUSTAVE, R P Technical Assistance Contracts Branch FIN B-6204 NRC-04-77-127 83/01/17 ROSENBLATT, H Westinghouse Electric Corp 1p 17419 355

8303030263 Notification of contract execution, Mod 16 to "FLECHT-SEASET." Contractor Westinghouse & EPRI
WOLLETT, S Research Contracts Branch FIN B-6204 NRC-04-77-127 83/02/24 BATSON, W Office of Nuclear Regulatory Research, Director LEE, R NRC - No Detailed Affiliation Given 1p 17419 332

--8303030267 Mod 16, changing workscope, estimate of cost, period of performance & billing address, to "FLECHT-SEASET."
STERN, T Westinghouse Electric Corp RYTKONEN, B B Electric Power Research Institute GUSTAVE, R P Division of Contracts FIN B-6204 NRC-04-77-127 83/02/24 19pp 17419 333

8303030335 Notification of grant execution, Mod 2 to "Study of Effects of Grid Spacers & Blockage on Mist Cooling During LOCA Reflood of PWR." Grantee Research Foundation of State Univ of NY
MCDERMOTT, D Technical Assistance Contracts Branch FIN G-1001 NRC-G-04-81-014 83/02/22 BATSON, W Office of Nuclear Regulatory Research, Director YOUNG, M NRC - No Detailed Affiliation Given 1p 17365 123

--8303030342 Mod 2, providing addl funding & extending period of performance to 840831, to "Study of Effects of Grid Spacers & Blockage on Mist Cooling During LOCA Reflood of PWR."
SAWOSKA, H J New York, State Univ. of, Stony Brook MORTON, K V Division of Contracts FIN G-1001 NRC-G-04-81-014 83/02/22 1p 17365 124

8303030348 Notification of grant execution, Mod 3 to "Aerospace-Electric Power Workshop Conference on Commercial Nuclear Power." Grantee American Inst of Aeronautics & Astronautics
MCDERMOTT, D Technical Assistance Contracts Branch FIN G-1005 NRC-G-04-81-002 83/02/22 BATSON, W Office of Nuclear Regulatory Research, Director EISS, A NRC - No Detailed Affiliation Given 1p 17419 360

--8303030370 Mod 3, extending period of performance to 830630, to "Aerospace-Electric Power Workshop Conference on Commercial Nuclear Power."
BROWN, W R American Institute of Aeronautics & Astronautics
MORTON, K V Division of Contracts FIN G-1005 NRC-G-04-81-002 83/02/22 1p 17419 361

8303030377 Notification of contract execution, Mod 5 to "Application of Internal Friction Nondestructive Evaluation Technique for Detecting Incipient Cracking of Bypass Lines & Pipes in BWR Piping Sys." Contractor Daedalean Assoc, Inc
BROMBERG, B Technical Assistance Contracts Branch FIN B-6212 NRC-04-78-242 83/02/22 FOREHAND, B Office of Nuclear Regulatory Research, Director MUSCARA, J NRC - No Detailed Affiliation Given 1p 17419 326

--8303030383 Mod 5, elaborating basic settlement terms, to "Application of Internal Friction Nondestructive Evaluation Technique for Detecting Incipient Cracking of Bypass Lines & Pipes in BWR Piping Sys."
HOCHREIN, A A Daedalean Associates, Inc MORTON, K V Division of Contracts FIN B-6212 NRC-04-78-242 83/02/22 2pp 17419 327

8303030511 Notification of contract execution, Mod 2 to "Subscriptions to Nucleonics Wk." Contractor McGraw-Hill, Inc
SMITH, P A Division of Contracts NRC-10-80-665 83/02/24 SPRINGER, M Office of Administration CONYNGHAM, M NRC - No Detailed Affiliation Given 1p 17419 199

--8303030513 Mod 2, deobligating funds, to "Subscriptions to Nucleonics Wk."
COLLINS, P McGraw-Hill Publications Co SMITH, P A Division of Contracts NRC-10-80-665 83/02/24 1p 17419 200

8303030672 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to OR State Health Div
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8554 NRC-32-83-685 83/02/25 ALEXANDER, T Office of Resource Management, Director HAMADA, G NRC - No Detailed Affiliation Given 1p 17363 012

--8303030680 Contract "Radiation Monitoring Program Requirements," awarded to OR State Health Div
GEBBIE, K M Oregon, State of MORTON, K V Division of Contracts FIN B-8554 NRC-32-83-685 83/02/25 15pp 17363 013

8303030714 Notification of contract execution, Mod 7 to "Operation & Maint of NRC Document Control Sys (DCS)." Contractor Planning Research Corp
BROMBERG, B Administrative Contracts Branch NRC-10-82-356 83/02/15 NORRY, P G Office of Administration LUNDY, J NRC - No Detailed Affiliation Given 1p 17363 358

--8303030718 Mod 7, increasing funding, to "Operation & Maint of NRC Document Control Sys (DCS)."
* Planning Research Corp SMITH, P A Division of Contracts NRC-10-82-356 83/02/15 3pp 17363 359

8303030763 Notification to contract execution, Mod 4 to "Develop Info for & Assist NRC in Drafting Guide to Preparation of Environ Repts for Fuel Fabrication Plants." Contractor SBA
SILVIS, R M Technical Assistance Contracts Branch FIN B-5081 NRC-02-73-027 83/02/23 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director AIKENS, A E NRC - No Detailed Affiliation Given 1p 17363 232

--8303030766 Mod 4, deobligating funds, to "Develop Info for & Assist NRC in Drafting Guide to Preparation of Environ Repts for Fuel Fabrication Plants."
ROGERS, A A Small Business Administration GUSTAVE, R P Division of Contracts FIN B-5081 NRC-02-73-027 83/02/23 1p 17363 233

8303030769 Notification of contract execution, Mod 2 to "Reviewing Hydrogeologic Investigations of NV Test Site - Project D." Contractor Geotrans, Inc
FLEENOR, C Technical Assistance Contracts Branch NRC-02-82-047 83/01/27 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director POHLE, J NRC - No Detailed Affiliation Given 1p 17363 356

# NONDOCKETED ITEMS

--8303030775 Mod 2, revising indirect rates & substituting project officer, to "Reviewing Hydrogeologic Investigations of NV Test Site - Project D."
* Geotrans, Inc GUSTAVE, R P Division of Contracts
NRC-02-82-047 83/01/27 1p 17363 357

8303030774 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to State of ME
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8357
NRC-28-83-603 83/02/25 MCOSCAR, J Office of Resource Management, Director COSTELLO, F NRC - No Detailed Affiliation Given 1p
17364 021

--8303030782 Contract "Radiation Monitoring Program Requirements," awarded to State of ME
WAKEFIELD, J Maine, State of MORTON, K V Division of Contracts
FIN B-8357 NRC-28-83-603 83/02/25 15pp 17364 022

8303040281 Notification of contract execution, Mod 2 to "Transient Prototypical Steam Generator (MB-2) Research Testing Program." Contractor: Westinghouse & EPRI
BAISDEN, L Technical Assistance Contracts Branch FIN B-8252
NRC-04-82-020 83/02/25 BATSON, W Office of Nuclear Regulatory Research, Director HOPENFELD, J NRC - No Detailed Affiliation Given 1p 17426 255

--8303040292 Ltr Contract NRC-04-82-020, Mod 2, extending period of performance to 830228, to "Transient Prototypical Steam Generator (MB-2) Research Testing Program."
MORTON, K V Division of Contracts FIN B-8252 NRC-04-82-020
83/02/25 FERGUSON, K L Westinghouse Electric Corp
RYTKONEN, B B Electric Power Research Institute 2pp 17426 256

8303090416 Notification of contract execution, Mod 7 to "Analysis & Improvement of NRC Staff Papers & Related Staff Papers."
Contractor: Arthur Young & Co
MCLEAREN, T Administrative Contracts Branch NRC-17-76-279
83/02/28 MCGREGOR, E Office of the Secretary of the Commission
1p 17484 089

--8303090422 Mod 7, incorporating final indirect rates, to "Analysis & Improvement of NRC Staff Papers & Related Staff Papers."
MADDEN, J S Arthur Young & Co HAGAN, T F Division of Contracts
NRC-17-76-279 83/02/28 1p 17484 090

8303090428 Notification of contract execution, Mod 2 to "Maint of Licensing & Insp Planning Profile Sys (LIPP) Software."
Contractor: SBA Subcontractor: Sys Architects, Inc
PAGE, M Administrative Contracts Branch NRC-10-81-395 83/02/18
SPRINGER, M Office of Administration BURTON, J E NRC - No
Detailed Affiliation Given 1p 17484 065

--8303090433 Mod 2, deobligating funds, to "Maint of Licensing & Insp Planning Profile Sys (LIPP) Software."
MCLAURIN, J W Small Business Administration * System
Architects, Inc SMITH, P A Division of Contracts NRC-10-81-395
83/02/18 2pp 17484 066

8303090592 Notification of contract execution "Multiple Award Task Order Contract for ADP Development," awarded to Automation Industries, Inc
MILES, E B Administrative Contracts Branch NRC-33-83-452-01
83/02/03 BASSETT, H , HARVES, J Office of Resource Management, Director 1p 17485 057

--8303090599 Contract "Multiple Award Task Order Contract for ADP Development," awarded to Automation Industries, Inc
GORMLEY, R C Automation Industries, Inc MATTIA, M J
Administrative Contracts Branch NRC-33-83-452-01 83/02/03
40pp 17485 058

8303090662 Notification of contract execution, Mod 4 to "Source Term Characterization Resulting from Explosively-Caused Secondary Violations of Spent Fuel Shipping Casks." Contractor: BMCL
WOLLETT, S Research Contracts Branch FIN B-6710 NRC-04-80-180
83/02/28 FOREHAND, W Office of Nuclear Regulatory Research, Director LAHS, B NRC - No Detailed Affiliation Given 1p
17480 240

--8303090668 Mod 4, extending period of performance to 820820, to "Source Term Characterization Resulting from Explosively-Caused Secondary Violations of Spent Fuel Shipping Casks."
LUKZ, F J Battelle Memorial Institute, Columbus Laboratories
GUSTAVE, R P Research Contracts Branch FIN B-6710
NRC-04-80-180 83/02/28 1p 17480 241

8303100001 Notification of contract execution, Mod 2 to "Publication, Distribution & Inventory Svcs." Contractor: Computer Data Sys, Inc
GILDENHORN, A J Administrative Contracts Branch NRC-10-83-332
83/03/01 SPRINGER, M Office of Administration SCOTT, S NRC - No
Detailed Affiliation Given 1p 17493 193

--8303100005 Mod 2, extending effective date to 841207 & funding basic contract period, to "Publication, Distribution & Inventory Svcs."
JOHNSON, H J Computer Data Systems, Inc HAGAN, T F Division of Contracts NRC-10-83-332 83/03/01 4pp 17493 194

8303100007 Addl response to FOIA request for documents re extensions issued in Nov & Dec 1981 & proposed extensions to "Stenographic Reporting Svc," awarded to Alderson Reporting Co, Inc Documents partially withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/02/03 GALLO, J
Isham, Lincoln & Beale 3pp 17492 349

--8303100051 Mod 12, extending period of performance to 821215, to "Stenographic Reporting Svcs."
SHARP, R A Alderson Reporting SMITH, P A Division of Contracts
FIN B-1311 NRC-17-80-448-0 82/12/03 2pp 17493 002

8303100117 Corrected copy of notification of contract execution, Mod 3 to "Mobility of Radwaste Matls in Subsurface Migration by Particulate Transport." Contractor: GA Inst of Technology
SILVIS, R M Technical Assistance Contracts Branch FIN B-6338
NRC-04-78-253 83/02/25 BATSON, W Office of Nuclear Regulatory Research, Director JUPITER, C NRC - No Detailed Affiliation Given
1p 17496 174

8303100412 Corrected notification of grant execution, Mod 2 to "Process of Droplet Disposition in Two Phase Gas-Liquid Flow Analysis of Mechanism & Modeling." Grantee: Univ of Houston
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-1026
NRC-G-04-81-027 83/03/04 BATSON, W Office of Nuclear Regulatory Research, Director ZUBER, N NRC - No Detailed Affiliation Given
1p 17504 361

8303150151 Notification of contract execution, Mod 2 to "Security Survey Guides & Appraisal Guide." Contractor: D Wright
HOYLE, A Administrative Contracts Branch NRC-10-82-385 83/03/07
BRADY, R J Division of Security KIDD, D NRC - No Detailed
Affiliation Given 1p 17586 361

--8303150158 Mod 2, changing Article VI to reflect new delivery dates, to "Security Survey Guides & Appraisal Guides."
WRIGHT, D Wright, D REBELLO, J Division of Contracts
NRC-10-82-385 83/03/07 1p 17586 362

8303150167 Notification of contract execution, Mod 2 to "Keypunch & Verification Svcs." Contractor: SBA, Subcontractor: Info Sys & Networks Corp
PERLMAN, J Administrative Contracts Branch FIN B-8158
NRC-25-82-318 83/03/03 BASSETT, H Division of Data Automation & Management Information OLIVER, D NRC - No Detailed Affiliation
Given 1p 17597 168

--8303150171 Mod 2, increasing funding, to "Keypunch & Verification Svcs."
* Small Business Administration * Information Systems & Networks Corp SMITH, P A Division of Contracts FIN B-8158
NRC-25-82-318 83/03/03 1p 17597 169

8303150355 Notification of contract execution, Mod 3 to "Microfiche Verification & Retrofit." Contractor: SBA/Labat-Anderson, Inc
PAGE, M Administrative Contracts Branch NRC-10-82-425 83/03/07
BESAW, W J Division of Technical Information & Document Control
SKOCZLAS, J , SCOTT, S Document Management Branch 1p 17597 178

--8303150360 Mod 3, providing incremental funding to "Microfiche Verification & Retrofit."
* Small Business Administration * Labat-Anderson, Inc
SMITH, P A Division of Contracts NRC-10-82-425 83/03/07 3pp
17597 179

8303150617 Notification of contract execution, Mod 1 to "Fire Protection Review & Evaluation." Contractor: Gage-Babcock & Assoc
FIELDS, J A Technical Assistance Contracts Branch
NRC-03-82-093-04 83/02/10 VOLLMER, R H Division of Engineering
FERGUSON, B NRC - No Detailed Affiliation Given 1p 17586 236

--8303150618 Mod 1, revising address for submission of invoices, to "Fire Protection Review & Evaluation."
* Gage-Babcock Associates, Inc GUSTAVE, R P Technical
Assistance Contracts Branch NRC-03-82-093-04 83/02/10 1p
17586 237

8303150656 Notification of contract execution, Mod 2 to "Fire Protection Review & Evaluation." Contractor: Gage-Babcock & Assoc
FIELDS, J A Technical Assistance Contracts Branch
NRC-03-82-093-04 83/03/07 VOLLMER, R H Division of Engineering
FERGUSON, B NRC - No Detailed Affiliation Given 1p 17583 360

--8303150663 Mod 2, extending period of performance to 840331, to "Fire Protection Review & Evaluation."
COHN, B. M. Gage-Babcock Associates, Inc. GUSTAVE, R. P. Technical Assistance Contracts Branch. NRC-03-82-093-04. 83/03/07. 1p. 17583: 361.

8303150708 Notification of grant execution, Mod 2 to "Degraded Core Heat Transfer." Grantee: UCLA.
MCDERMOTT, D. Technical Assistance Contracts Branch. FIN G-1011. NRC-G-04-81-025. 83/03/07. BATSON, W. Office of Nuclear Regulatory Research, Director. YOUNG, N. NRC - No Detailed Affiliation Given. 1p. 17586: 238.

--8303150712 Mod 2, providing addl funds & extending period of performance to 840930, to "Degraded Core Heat Transfer."
DHILLON, H. California, Univ. of, Los Angeles. MORTON, K. V. Technical Assistance Contracts Branch. FIN G-1011. NRC-G-04-81-025. 83/03/07. 1p. 17586: 239.

8303160056 Notification of contract execution, Mod 3 to "Earthquake Recurrence Intervals at Nuclear Power Plant Sites." Contractor: Ertec Western, Inc.
GUSTAVE, R. P. Technical Assistance Contracts Branch. FIN B-7226. NRC-04-81-167. 83/02/25. BATSON, W. Office of Nuclear Regulatory Research, Director. MURPHY, A. NRC - No Detailed Affiliation Given. 1p. 17604: 230.

--8303160060 Mod 3, providing incremental funding & adjusting overhead rate, to "Earthquake Recurrence Intervals at Nuclear Power Plant Sites."
* Ertec, Inc. MORTON, K. V. Division of Contracts. FIN B-7226. NRC-04-81-167. 83/02/25. 2pp. 17604: 231.

8303160064 Notification of contract execution: "Specialized File Folders." awarded to Ames Safety Envelope Co.
BAZIN, J. P. Administrative Contracts Branch. NRC-10-83-328. 83/03/04. HOYLE, J. C. Office of the Secretary of the Commission. STUCKY, S. NRC - No Detailed Affiliation Given. 1p. 17604: 204.

--8303160069 Contract: "Specialized File Folders," awarded to Ames Safety Envelope Co.
* Ames Safety Envelope Co. MATTIA, M. J. Administrative Contracts Branch. NRC-10-83-328. 83/03/04. 25pp. 17604: 205.

8303160066 Notification of contract execution, Mod 5 to "Career Counseling." Contractor: Binder, Elster, Mendelson & Wheeler.
PAGE, M. Administrative Contracts Branch. NRC-10-82-358. 83/03/01. DORIE, W. Office of Administration. VAN SANTEN, L. W. NRC - No Detailed Affiliation Given. 1p. 17614: 357.

--8303160071 Mod 5, extending period of performance to 840131, to "Career Counseling."
MENDELSON, I. N. Binder, Elster, Mendelson & Wheeler, Inc. SMITH, P. A. Division of Contracts. NRC-10-82-358. 83/03/01. 2pp. 17614: 358.

8303160079 Notification of contract execution, Mod 9 to "Career Counseling." Contractor: Binder, Elster, Mendelson & Wheeler.
MCLEAREN, T. Administrative Contracts Branch. NRC-10-79-387. 83/03/04. SHRINGER, M. Office of Administration. 1p. 17614: 346.

--8303160085 Mod 9, deobligating funds, to "Career Counseling."
* Binder, Elster, Mendelson & Wheeler, Inc. HAGAN, T. F. Division of Contracts. NRC-10-79-387. 83/03/04. 1p. 17614: 347.

8303160091 Notification of contract execution, Mod 12 to "Analytical Studies of Aerosol Behavior of Fast Reactors." Contractor: BMI.
WOLLETT, S. Technical Assistance Contracts Branch. FIN A-4063. NRC-04-76-293. 83/02/15. BATSON, W. Office of Nuclear Regulatory Research, Director. LARKINS, S. NRC - No Detailed Affiliation Given. 1p. 17614: 340.

--8303160097 Mod 12, modifying scope to include continuation of work & extending period of contract to 830930, to "Analytical Studies of Aerosol Behavior of Fast Reactors."
LUKZ, F. J. Battelle Memorial Institute, Columbus Laboratories. GUSTAVE, R. P. Division of Contracts. FIN A-4063. NRC-04-76-293. 83/02/15. 1p. 17614: 341.

8303160660 Notification of contract execution: "Licensing Assistance/Geotechnical & Hydrological Evaluations," awarded to Ebasco Svcs, Inc.
FIELDS, J. A. Technical Assistance Contracts Branch. NRC-02-80-033-08. 83/03/09. DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director. GARCIA, P. NRC - No Detailed Affiliation Given. 1p. 17600: 295.

--8303160667 Contract: "Licensing Assistance/Geotechnical & Hydrological Evaluations," awarded to Ebasco Svcs, Inc.
RASILE, J. A. Ebasco Services, Inc. (subs. of Enserch Corp.). MORTON, K. V. Division of Contracts. NRC-02-80-033-08. 83/03/09. 11pp. 17600: 296.

8303170013 Notification of contract execution, Mod 1 to "Ecological Studies of Endemic & Introduced Shipworms in Vicinity of Nuclear Generating Station." Contractor: Academy of Natural Sciences.
WOLLETT, S. Technical Assistance Contracts Branch. FIN B-8138. NRC-04-82-009. 83/02/22. BATSON, W. Office of Nuclear Regulatory Research, Director. HAYES, P. NRC - No Detailed Affiliation Given. 1p. 17624: 331.

--8303170019 Mod 1, extending completion date at no addl cost from 830219 to 830701, to "Ecological Studies of Endemic & Introduced Shipworms in Vicinity of Nuclear Generating Station."
PALANTINO, S. A. Academy of Natural Sciences. GUSTAVE, R. P. Division of Contracts. FIN B-8138. NRC-04-82-009. 83/02/22. 1p. 17624: 332.

8303170653 Notification of contract execution: "Test Item Writing Workshops for NRC Examiners," awarded to Prof Examining Svc.
HOYLE, A. Purchasing Section. FIN B-8638. NRC-03-83-101. 83/03/08. THOMPSON, H. L. Division of Human Factors Safety. SHANKMAN, S. NRC - No Detailed Affiliation Given. 1p. 17615: 146.

--8303170656 Contract: "Test Item Writing Workshops for NRC Examiners," awarded to Prof Examining Svc.
KALEY, M. Professional Examining Service. REBELLO, J. E. Division of Contracts. FIN B-8638. NRC-03-83-101. 83/03/08. 5pp. 17615: 147.

8303180057 Notification of contract execution, Mod 1 to "Word Processing Svcs." Contractor: Keyboard Communications, Inc.
PAGE, M. Administrative Contracts Branch. NRC-10-83-296. 82/12/24. STEELE, M. Division of Technical Information & Document Control. JOHANSEN, J. NRC - No Detailed Affiliation Given. 2pp. 17625: 248.

--8303180062 Mod 1, reflecting funds currently obligated for performance period, to "Word Processing Svcs."
BRIGGS, H. J. Keyboard Communications, Inc. SMITH, P. A. Division of Contracts. NRC-10-83-296. 82/12/24. 2pp. 17625: 249.

8303180063 Notification of contract execution, Mod 3 to "Development of Matl Accounting Data Storage Analysis Sys." Contractor: NUSAC, Inc.
FIELDS, J. A. Technical Assistance Contracts Branch. NRC-02-82-033. 83/02/17. DENTON, J. Office of Nuclear Material Safety & Safeguards, Director. MILLER, M. NRC - No Detailed Affiliation Given. 1p. 17625: 238.

--8303180067 Mod 3, substituting project officer, to "Development of Matl Accounting Data Storage Analysis Sys."
* NUSAC, Inc. GUSTAVE, R. P. Technical Assistance Contracts Branch. NRC-02-82-033. 83/02/17. 1p. 17625: 239.

8303180072 Notification of contract execution, Mod 3, to "Demographic Projection & Regional Economic Impacts of Accidents." Contractor: Bureau of Economic Analysis.
FIELDS, J. A. Technical Assistance Contracts Branch. FIN B-8044. NRC-03-82-112. 83/02/17. VOLLMER, R. H. Division of Engineering. 1p. 17625: 216.

--8303180075 Mod 3, increasing dollar amount of agreement & incrementing addl funds, to "Demographic Projections & Regional Economic Impacts of Accidents."
KNOX, H. W. Commerce, Dept. of. GUSTAVE, R. P. Technical Assistance Contracts Branch. FIN B-8044. NRC-03-82-112. 83/02/17. 2pp. 17625: 217.

8303180080 Notification of contract execution, Mod 5 to "Licensing Review of OL Applications." Contractor: Naval Surface Weapons Ctr.
FIELDS, J. A. Technical Assistance Contracts Branch. NRC-03-80-109. 83/01/27. VOLLMER, R. Division of Engineering. RINALDI, F. NRC - No Detailed Affiliation Given. 1p. 17625: 210.

--8303180086 Mod 5, revising address for invoice submittal & incorporating revised Manual Chapter 3202, to "Licensing Review of OL Applications."
ROBERTS, E. S. Navy, Dept. of. GUSTAVE, R. P. Technical Assistance Contracts Branch. NRC-03-80-109. 83/01/27. 1p. 17625: 211.

8303180092 Notification of contract execution, Mod 6 to "Licensing Review of OL Applications." Contractor: Naval Surface Weapons Ctr.
FIELDS, J. A. Technical Assistance Contracts Branch. NRC-03-80-109. 83/02/17. VOLLMER, R. Division of Engineering. RINALDI, F. NRC - No Detailed Affiliation Given. 1p. 17625: 205.

--8303180096 Mod 6, extending period of performance to 836030, to "Licensing Review of OL Applications."
ROBERTS, E S Navy, Dept. of GUSTAVE, R P Technical Assistance Contracts Branch NRC-03-80-109 83/02/17 1p 17625 206

8303180528 Notification of contract execution, Mod 2 to "Development of Matl Accounting Data Storage Analysis Sys."
FIELDS, J A Technical Assistance Contracts Branch NRC-02-82-033 83/01/03 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director MILLER, M NRC - No Detailed Affiliation Given 1p 17640 259

--8303180536 Mod 2, modifying statement of work, key personnel & Article V, to "Development of Matl Accounting Data Storage Analysis Sys."
* NUSAC, Inc GUSTAVE, R P Technical Assistance Contracts Branch NRC-02-82-033 83/01/03 3pp 17640 260

8303180684 Notification of contract execution, Mod 2 to "Fire Protection Program Review & Evaluation." Contractor FPE Group
FIELDS, J A Technical Assistance Contracts Branch NRC-03-82-093-03 83/03/07 VOLLMER, R H Division of Engineering FERGUSON, R NRC - No Detailed Affiliation Given 1p 17637 016

--8303180680 Mod 2, extending period of performance to 840331, to "Fire Protection Program Review & Evaluation."
BERG, K FPE Group, The GUSTAVE, R P Technical Assistance Contracts Branch NRC-03-82-093-03 83/03/07 1p 17637 017

8303230129 Notification of contract execution, Mod 10 to "Publication Distribution Svcs." Contractor Computer Data Sys, Inc
PAGE, M Administrative Contracts Branch NRC-10-80-362 83/03/17
SPINGER, M L Office of Administration SCOTT, S Document Management Branch 1p 17690 068

--8303230135 Mod 10, extending period of performance to 830307, to "Publication Distribution Svcs."
JOHNSON, H J Computer Data Systems, Inc SMITH, P A Division of Contracts NRC-10-80-362 83/03/17 2pp 17690 069

8303230154 Notification of contract execution, Mod 1 to "Review of PRA of Tornado Missile Damage." Contractor NBS
FLEENOR, C Technical Assistance Contracts Branch FIN B-8624 NRC-03-82-133 83/03/07 MATTSON, R J Division of Systems Integration (post 811005) WERMIEL, J NRC - No Detailed Affiliation Given 1p 17687 114

--8303230158 Mod 1, extending period of performance to 830810 & providing final allotment of incremental funds, to "Review of PRA of Tornado Missile Damage."
SIMIU, E Commerce, Dept. of, National Bureau of Standards GUSTAVE, R P Division of Contracts FIN B-8624 NRC-03-82-133 83/03/07 2pp 17687 115

8303230162 Notification of contract execution, Mod 4 to "Fire Protection Program Review & Evaluation V." Contractor Gage-Babcock & Assoc
FIELDS, J A Technical Assistance Contracts Branch NRC-03-81-139 83/02/10 VOLLMER, R Division of Engineering FERGUSON, R NRC - No Detailed Affiliation Given 1p 17687 103

--8303230167 Mod 4, modifying list of facilities to be reviewed, to "Fire Protection Program Review & Evaluation V."
COHN, B M Gage-Babcock Associates, Inc GUSTAVE, R P Division of Contracts NRC-03-81-139 83/02/10 4pp 17687 104

8303230172 Notification of contract execution, Mod 3 to "Fire Protection Program Review & Evaluation V." Contractor Gage-Babcock & Assoc
FIELDS, J A Technical Assistance Contracts Branch NRC-03-81-139 83/01/03 VOLLMER, R Division of Engineering FERGUSON, R NRC - No Detailed Affiliation Given 1p 17687 101

--8303230175 Mod 3, changing refs from Ofc of Controller to Ofc of Resource Mgt, to "Fire Protection Program Review & Evaluation V."
COHN, B M Gage-Babcock Associates, Inc HAGAN, T F Division of Contracts NRC-03-81-139 83/01/03 1p 17687 102

8303230180 Notification of contract execution, Mod 2 to "Fire Protection Program Review Case Work Plant 2." Contractor Gage-Babcock & Assoc
FIELDS, J Technical Assistance Contracts Branch NRC-03-82-121 83/01/03 VOLLMER, R Division of Engineering NOLAN, F NRC - No Detailed Affiliation Given 1p 17687 099

--8303230182 Mod 2, changing refs from Ofc of Controller to Ofc of Resource Mgt, to "Fire Protection Program Review Case Work Plant 2."
COHN, B M Gage-Babcock Associates, Inc HAGAN, T F Division of Contracts NRC-03-82-121 83/01/03 1p 17687 100

8303230185 Notification of contract execution "Panel Member & Documentation Review of NUREG Prior to & During Selected Meetings of Peer Review Group for Review of Draft Rept Entitled . ." awarded to Harvard School of Public Health
TOWNSEND, B L Administrative Contracts Branch FIN B-8986 NRC-04-83-011 83/03/15 BASSETT, D E Division of Accident Evaluation JANKOWSKI, M W NRC - No Detailed Affiliation Given 1p 17687 094

--8303230195 Contract "Panel Member & Documentation Review of NUREG Prior to & During Selected Meetings of Peer Review Group for Review of Draft Rept Entitled 'Radionclide Release Under LWR Specific . .'" awarded to Harvard School of Public Health
COOPER, D Harvard Medical School REBELLO, J E Division of Contracts FIN B-8986 NRC-04-83-011 83/03/15 4pp 17687 095

8303230376 Notification of contract execution, Mod 3 to "NRC Procurement Training for Project Officers." Contractor USDA Graduate School
PERLMAN, J Administrative Contracts Branch NRC-10-81-402 83/03/16 DORIE, W Office of Administration BASSIN, C Management Development & Training Staff 1p 17675 269

--8303230380 Mod 3, adding regions to training areas, to "NRC Procurement Training for Project Officers."
VARNER, L S Agriculture, Dept. of, Graduate School SMITH, P A Division of Contracts NRC-10-81-402 83/03/16 1p 17675 270

8303280008 Notification of contract execution, Mod 3 to "Purchase of Secure Voice Terminals W/Desk Sets." Contractor Natl Security Agency
PERLMAN, J Administrative Contracts Branch NRC-10-80-718 83/03/18 DORIE, W Program Support Branch KERR, V NRC - No Detailed Affiliation Given 2pp 17726 335

--8303280013 Mod 3, increasing funding, to "Purchase of Secure Voice Terminals W/Desk Sets."
* National Security Agency SMITH, P A Division of Contracts NRC-10-80-718 83/03/18 1p 17726 336

8303280098 Notification of contract execution, Mod 1 to "Data Equipment Test & Evaluation Plan." Contractor Boeing Computer Svcs Co
MCLEAREN, T Administrative Contracts Branch FIN B-1292 NRC-05-82-243 83/03/18 BLAHA, J L Program Support Branch HIMES, J NRC - No Detailed Affiliation Given 1p 17713 359

--8303280102 Mod 1, deobligating unliquidated balance, to "Data Equipment Test & Evaluation Plan."
KIEL, R L Boeing Computer Services, Inc (subs of Boeing Co.)
HAGAN, T F Division of Contracts FIN B-1292 NRC-05-82-243 83/03/18 1p 17713 360

8303280332 Notification of contract execution, Mod 5 to "Analysis of Safeguards Needs for Transport of High Level Waste."
Contractor Battelle Columbus Labs
FIELDS, J A Division of Contracts NRC-02-81-030 83/01/11
DAVIS, J Office of Nuclear Material Safety & Safeguards, Director SAWYER, C NRC - No Detailed Affiliation Given 1p 17713 121

--8303280333 Mod 5, correcting expiration date to 840426, to "Analysis of Safeguards Needs for Transport of High Level Waste."
* Battelle Memorial Institute, Columbus Laboratories
GUSTAVE, R P Division of Contracts NRC-02-81-030 83/01/11 1p 17713 122

8303280337 Notification of contract execution, Mod 1 to "Fire Protection Program Review Case Work Plants 1."
Contractor Gage-Babcock & Assoc, Inc
FIELDS, J A Technical Assistance Contracts Branch NRC-03-82-118 83/01/03 VOLLMER, R H Division of Engineering NOLAN, F NRC - No Detailed Affiliation Given 1p 17713 105

--8303280339 Mod 1, revising address for submitting invoices & incorporating revised Manual Chapter 3202, to "Fire Protection Program Review Case Work Plants 1."
COHN, B M Gage-Babcock Associates, Inc HAGAN, T F Division of Contracts NRC-03-82-118 83/01/03 1p 17713 106

8303280351 Notification of contract execution, Mod 3 to "Licensing Assistance/Geotechnical & Hydrological Evaluations."
Contractor Geotechnical Engineers, Inc
FIELDS, J A Technical Assistance Contracts Branch NRC-02-80-033-01 83/01/03 DAVOS, J Office of Nuclear Material Safety & Safeguards, Director GARCIA, P NRC - No Detailed Affiliation Given 1p 17713 091

--8303280354 Mod 3, revising address for submitting invoices & incorporating revised Manual Chapter 3202, to "Licensing Assistance/Geotechnical & Hydrological Evaluations."
CASTRO, G Geotechnical Engineers, Inc HAGAN, T F Division of Contracts NRC-02-80-033-01 83/01/03 1p 17713 092

8303290013 Notification of contract execution. "Radiation Monitoring Program Requirements." awarded to Dept of Health & Human Svcs, State of WA.
MCDERMOTT, D. Technical Assistance Contracts Branch. FIN B-8551. NRC-32-83-682. 83/03/16. ALEXANDER, I. Office of Resource Management, Director. HAMADA, G. NRC - No Detailed Affiliation Given. 1p. 17727:331.

--8303290028 Contract: "Radiation Monitoring Program Requirements." awarded to Dept of Health & Human Svcs, State of WA.
BORTZ, D. G. Washington, State of. MORTON, K. V. Technical Assistance Contracts Branch. FIN B-8551. NRC-32-83-682. 83/03/16. 1p. 17727:332.

--8303290298 RQ5-83-682.
"Environ Measurement Verification of Radioactivity & Radiation Levels in Environ of Commission Licensed Activities Located Within State of WA & Selected by Commission."
*. Washington, State of. *. Technical Assistance Contracts Branch. FIN B-8551. NRC-32-83-682. 83/03/16. 13pp. 17727:333.

8303290018 Notification of contract execution. "Radiation Monitoring Program Requirements." awarded to NY State Dept of Health.
MCDERMOTT, D. Technical Assistance Contracts Branch. FIN B-8355. NRC-28-83-610. 83/03/16. MCOSCAR, J. Office of Resource Management, Director. COSTELLO, F. NRC - No Detailed Affiliation Given. 1p. 17730:010.

--8303290039 Contract: "Radiation Monitoring Program Requirements." awarded to NY State Dept of Health.
RIMAWI, K. New York, State of. MORTON, K. V. Division of Contracts. FIN B-8355. NRC-28-83-610. 83/03/16. 1p. 17730:011.

--8303290045 RQI-83-610.
"Environ Monitoring Program for State of NY."
*. New York, State of. FIN B-8355. NRC-28-83-610. 83/03/16. 16pp. 17730:012.

8303290084 Notification of contract execution, Mod 2 to "Demographic Projections & Regional Economic Impacts of Accidents."
Contractor: Dept of Commerce.
FIELDS, J. A. Technical Assistance Contracts Branch. NRC-03-82-112. 83/01/03. VOLLMER, R. H. Division of Engineering. SINISGALLI, A. NRC - No Detailed Affiliation Given. 1p. 17729:243.

--8303290091 Mod 2, revising address for submitting invoices & Manual Chapter 3202, to "Demographic Projections & Regional Economic Impacts of Accidents."
KNOX, H. W. Commerce, Dept. of. HAGAN, T. F. Division of Contracts. NRC-03-82-112. 83/01/03. 1p. 17729:244.

8303290096 Notification of contract execution, Mod 3 to "Review & Evaluation of US Geologic & Seismic Features of Nuclear Power Sites." Contractor: USGS.
FIELDS, J. A. Technical Assistance Contracts Branch. FIN B-6839. NRC-03-80-113. 83/01/03. VOLLMER, R. H., JACKSON, R. NRC - No Detailed Affiliation Given. 1p. 17729:232.

--8303290103 Mod 3, revising address for submitting invoices & Manual Chapter 3202, to "Review & Evaluation of Geologic & Seismic Features of Nuclear Power Sites."
FILSON, J. R. Interior, Dept. of, Geological Survey. HAGAN, T. F. Division of Contracts. FIN B-6839. NRC-03-80-113. 83/01/03. 1p. 17729:233.

8303290120 Notification of contract execution, Mod 6 to "Computer Time-Sharing & Related Svcs." Contractor: NIH.
PERLMAN, J. Administrative Contracts Branch. FIN B-1666. NRC-25-82-312. 83/03/17. BASSETT, H. S., KIRK, I., BADINI, B. Office of Resource Management, Director. 1p. 17727:353.

--8303290138 Mod 6, increasing funding, to "Computer Time-Sharing & Related Svcs."
*. HHS, Dept. of, US Public Health Service. SMITH, P. A. Division of Contracts. FIN B-1666. NRC-25-82-312. 83/03/17. 1p. 17727:354.

8303290175 Notification of contract execution, Mod 8 to "Memphis Area Regional Seismic Network." Contractor: Memphis State Univ.
FIELDS, J. A. Technical Assistance Contracts Branch. FIN B-6276. NRC-04-78-200. 83/02/16. BATSON, W. Office or Nuclear Regulatory Research, Director. MURPHY, A. NRC - No Detailed Affiliation Given. 1p. 17730:197.

--8303290185 Mod 8, extending period of performance to 831130 w/increased funding, to "Memphis Area Regional Seismic Network."
CARPENTER, T. G. Memphis State Univ. GUSTAVE, R. P. Technical Assistance Contracts Branch. FIN B-6276. NRC-04-78-200. 83/02/16. 4pp. 17730:198.

8303290187 Notification of contract execution, Mod 8 to "Technical Assistance for EIS on 10CFR61." Contractor: Dames & Moore.
FIELDS, J. A. Technical Assistance Contracts Branch. NRC-02-81-049. 83/01/03. DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director. ROLES, G. NRC - No Detailed Affiliation Given. 1p. 17730:193.

--8303290192 Mod 8, revising address for submitting invoices & Manual Chapter 3202, to "Technical Assistance for EIS on 10CFR61."
OZTUNALI, O. Dames & Moore. HAGAN, T. F. Division of Contracts. NRC-02-81-049. 83/01/03. 1p. 17730:194.

8303290191 Notification of contract execution, Mod 1 to "Low Level Nuclear Waste Processing & Shallow Land Burial Trench Isolation." Contractor: Univ of AZ.
WOLLETT, S. Technical Assistance Contracts Branch. FIN B-7072. NRC-04-81-220. 83/03/10. BATSON, W. Office of Nuclear Regulatory Research, Director. WASTLER, S. NRC - No Detailed Affiliation Given. 1p. 17730:174.

--8303290196 Mod 1, extending period of performance to 830930, to "Low Level Nuclear Waste Processing & Shallow Land Burial Trench Isolation."
CARR, S. E. Arizona, Univ. of. GUSTAVE, R. P. Division of Contracts. FIN B-7072. NRC-04-81-220. 83/03/10. 8pp. 17730:175.

8303290194 Notification of contract execution, Mod 6 to "Geotechnical Engineering Review of SEP Plants." Contractor: US Army Corps of Engineers.
FIELDS, J. A. Division of Contracts. NRC-03-81-122. 83/02/23. VOLLMER, R. H. Division of Engineering. HELLER, L. NRC - No Detailed Affiliation Given. 1p. 17730:172.

--8303290197 Mod 6, revising address for submitting invoices, to "Geotechnical Engineering Review of SEP Plants."
KAVANAUGH, P. F. Army, Dept. of, Corps of Engineers. HAGAN, T. F. Division of Contracts. NRC-03-81-122. 83/02/23. 1p. 17730:173.

8303290204 Notification of contract execution, Mod 4 to "Const of Nuclear & Fossil Fueled Power Plants." Contractor: Dept of Labor.
SILVIS, R. M. Technical Assistance Contracts Branch. FIN B-7640. NRC-03-79-125. 83/03/21. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. SINISGALLI, A. NRC - No Detailed Affiliation Given. 1p. 17727:329.

--8303290228 Mod 4, deobligating unliquidated balance, to "Const of Nuclear & Fossil Fueled Power Plants."
NORDLUND, W. J. Labor, Dept. of. GUSTAVE, R. P. Division of Contracts. FIN B-6540. NRC-03-79-125. 83/03/21. 1p. 17727:330.

8303290253 Notification of contract execution. "Multiple Award Task Order Contract for ADP Development." awarded to Boeing Computer Svcs Co.
MILES, E. B. Administrative Contracts Branch. FIN B-8166. NRC-33-83-452. 83/03/08. BASSETT, H. S., HARVES, J. Office of Resource Management, Director. 1p. 17729:104.

--8303290264 Contract: "Multiple Award Task Order Contract for ADP Development," awarded to Boeing Computer Svcs Co.
HOPKINS, H. R. Boeing Computer Services, Inc. (subs. of Boeing Co.). MATTIA, M. J. Division of Contracts. FIN B-8166. NRC-33-83-452. 83/03/08. 44pp. 17729:105.

8303290281 Notification of contract execution, Mod 2 to "Fire Protection Review & Evaluation." Contractor: Rolf-Jensen & Associates.
FIELDS, J. A. Technical Assistance Contracts Branch. NRC-03-82-093-01. 83/03/07. VOLLMER, R. H. Division of Engineering. FERGUSON, R. NRC - No Detailed Affiliation Given. 1p. 17727:361.

--8303290292 Mod 2, extending period of performance to 840331, to "Fire Protection Review & Evaluation."
WEBB, W. A. Rolf Jensen & Associates, Inc. GUSTAVE, R. P. Division of Contracts. NRC-03-82-093-01. 83/03/07. 1p. 17727:362.

8303290324 Notification of contract execution, Mod 7 to "In-Process Control of SNM." Contractor: Science Applications, Inc.
FIELDS, J. A. Technical Assistance Contracts Branch. NRC-02-81-040. 83/01/03. DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director. MENDELSOHN, B. NRC - No Detailed Affiliation Given. 1p. 17729:034.

--8303290336 Mod 7, revising address for submitting invoices & Manual Chapter 3202, to "In-Process Control of SNM."
MCDONALD, R. J. Science Applications, Inc. HAGAN, T. F. Division of Contracts. NRC-02-81-040. 83/01/03. 1p. 17729:035.

8303290406 Notification of contract execution,Mod 1 to "Radiation Monitoring Program Requirements." Contractor:OH Dept of Health.
MCDERMOTT,D. Technical Assistance Contracts Branch FIN B-8450 NRC-30-83-646 83/03/16 PAPPAS,H. Office of Resource Management, Director OESTMANN,M.J. NRC - No Detailed Affiliation Given 1p 17727.359.

--8303290413 Mod 1,correcting B&R number,to "Radiation Monitoring Program Requirements."
WILMOTH,B Ohio, State of MORTON,K.V. Division of Contracts FIN B-8450 NRC-30-83-646 83/03/16 1p 17727.360.

8303290417 Notification of contract execution,Mod 7 to "Regional Interstate Nuclear Facility Siting Procedures Demonstration Project." Contractor:Southern Interstate Nuclear Board
WOLLETT,S. Technical Assistance Contracts Branch FIN B-5020 NRC-01-76-324 83/03/18 FOREHAND,W. Office of Nuclear Regulatory Research, Director NICHOLS,C. NRC - No Detailed Affiliation Given 1p 17727.357.

--8303290425 Mod 7,extending period of performance to 830630 at no addl cost,to "Regional Interstate Nuclear Facility Siting Procedures Demonstration Project."
FELLOWS,W.S. Southern Interstate Nuclear Board GUSTAVE,R.P. Division of Contracts FIN B-5020 NRC-01-76-324 83/03/18 1p 17727.358.

8303290528 Notification of contract execution: "Radiation Monitoring Program Requirements," awarded to Dept of Health Svcs,State of CA.
MCDERMOTT,D. Technical Assistance Contracts Branch FIN B-8553 NRC-32-83-684 83/03/16 ALEXANDER,I. Office of Resource Management, Director HAMADA,G. NRC - No Detailed Affiliation Given 1p 17742.185.

--8303290532 Contract: "Radiation Monitoring Program Requirements," awarded to Dept of Health Svcs,State of CA.
ROHLFES,G.B. California, State of MORTON,K.V. Technical Assistance Contracts Branch FIN B-8553 NRC-32-83-684 83/03/16 1p 17742.186.

--8303290535 RGV-83-684
"Environ Measurement Verification of Radioactivity & Radiation & Radiation Levels in Environ of Commission Licensed Activities Located Within State of CA & Selected by Commission."
* California, State of * Technical Assistance Contracts Branch FIN B-8553 NRC-32-83-684 83/03/16 13pp 17742.187.

8303290568 Notification of contract execution,Mod 7 to "Technical Assistance in Repository Design." Contractor:Golder Assoc
FIELDS,J.A. Technical Assistance Contracts Branch NRC-02-81-037 83/01/03 DAVIS,J. Office of Nuclear Material Safety & Safeguards,Director HARTUNG,L. NRC - No Detailed Affiliation Given 1p 17741.361.

--8303290574 Mod 7,revising address for submission of invoices & incorporating revised Manual Chapter 3202,to "Technical Assistance in Repository Design."
WEST,S. Golder Associates HAGAN,T.F. Division of Contracts NRC-02-81-037 83/01/03 1p 17741.362.

8303290579 Notification of contract execution,Mod 8 to "Technical Assistance in Repository Design." Contractor:Golder Assoc
FIELDS,J.A. Technical Assistance Contracts Branch FIN B-6983-3 NRC-02-81-037 83/03/18 DAVIS,J. Office of Nuclear Material Safety & Safeguards,Director HARTUNG,L. NRC - No Detailed Affiliation Given 1p 17743.284.

--8303290584 Mod 8,establishing overhead rate for direct labor cost & obligating funds,to "Technical Assistance in Repository Design."
PENTZ,D.L. Golder Associates GUSTAVE,R.P. Division of Contracts FIN B-6983-3 NRC-02-81-037 83/03/18 2pp 17743.285.

8303290589 Notification of contract execution: "Multiple Award Task Order Contract for ADP Development," awarded to Booz-Allen & Hamilton,Inc.
DORSEY,M. Administrative Contracts Branch MILES,E.B. Technical Assistance Contracts Branch FIN B-8166 NRC-33-83-452 83/03/01 BASSETT,H.S., HARVES,J. Office of Resource Management, Director 1p 17743.308.

--8303290596 Contract: "Multiple Award Task Order Contract for ADP Development," awarded to Booz-Allen & Hamilton,Inc.
GOTTLIEB,S.E. Booz Allen & Hamilton, Inc MATTIA,M.J. Division of Contracts FIN B-8166 NRC-33-83-452 83/03/01 30pp 17743.309.

8303290599 Notification of contract execution,Mod 4 to "Unsaturated Flow & Transport Through Fractured Rock re High Level Waste Repositories.Contractor:Univ of AZ
JACOBS,A. Research Contracts Branch FIN B-7291 NRC-04-81-224 83/03/15 BATSON,W. Office of Nuclear Regulatory Research, Director NICHOLSON,T. NRC - No Detailed Affiliation Given 1p 17744.250.

--8303290608 Mod 4,extending period of performance to 851130 & adding addl funds,to "Unsaturated Flow & Transport Through Fractured Rock re High Level Waste Repositories."
CARR,S.E. Arizona, Univ. of GUSTAVE,R.P. Technical Assistance Contracts Branch FIN B-7291 NRC-04-81-224 83/03/15 16pp 17744.251.

8303290749 Notification of contract execution,Mod 19 to "FLECHT-SEASET." Contractor:Westinghouse/EPRI
WOLLETT,S. Technical Assistance Contracts Branch FIN B-6204 NRC-04-77-127 83/03/14 BATSON,W. Office of Nuclear Regulatory Research, Director LEE,R. NRC - No Detailed Affiliation Given 1p 17746.361.

--8303290752 Ltr contract,Mod 19,increasing funds,to "FLECHT-SEASET."
GUSTAVE,R.P. Technical Assistance Contracts Branch FIN B-6204 NRC-04-77-127 83/03/07 SPENCE,L.W. Westinghouse Electric Corp 1p 17746.362.

8303290755 Notification of contract execution: "Radiation Monitoring Program Requirements," awarded to State of VA.
MCDERMOTT,D. Technical Assistance Contracts Branch FIN B-8402 NRC-29-83-623 83/03/09 LOY,T.N. Division of Res. Nce Management & Administration MONTGOMERY,D.M. NRC - No Detailed Affiliation Given 1p 17746.341.

--8303290758 Contract: "Radiation Monitoring Program Requirements," awarded to State of VA.
KENLEY,J.B. Virginia, Commonwealth of, MORTON,K.V. Division of Contracts FIN B-8402 NRC-29-83-623 83/03/09 15pp 17746.342.

8303290759 Notification of contract execution,Mod 1 to "Fire Protection Program Review:Case Work Plant 2." Contractor:Gage-Babcock & Assoc
FIELDS,J.A. Technical Assistance Contracts Branch FIN B-8028 NRC-03-82-121 83/02/17 VOLLMER,R. Division of Engineering NOLAN,F. NRC - No Detailed Affiliation Given 1p 17746.334.

--8303290765 Mod 1,extending period of performance to 830925,increasing allotted amount to $44,000 & changing assigned project officer,to "Fire Protection Review:Case Work Plant 2."
COHN,B.M. Gage-Babcock Associates, Inc GUSTAVE,R.P. Division of Contracts FIN B-8028 NRC-03-82-121 83/02/17 2pp 17746.335.

8303290763 Notification of contract execution: "Radiation Monitoring Program Requirements," awarded to State of CT.
MCDERMOTT,D. Technical Assistance Contracts Branch FIN B-8358 NRC-28-83-604 83/03/07 MCOSCAR,J., COSTELLO,F. NRC - No Detailed Affiliation Given 1p 17746.318.

--8303290769 Contract: "Radiation Monitoring Program Requirements," awarded to State of CT.
HEUBNER,A.T. Connecticut, State of MORTON,K.V. Division of Contracts FIN B-8358 NRC-28-83-604 83/03/07 15pp 17746.319.

8303290770 Notification of contract execution,Mod 9 to "Evaluation of Matl Accounting Performance at Nuclear Fuel Cycle Facilities." Contractor:NUSAC, Inc.
FIELDS,J.A. Technical Assistance Contracts Branch NRC-02-81-028 83/02/22 DAVIS,J. Office of Nuclear Material Safety & Safeguards,Director MILLER,M. NRC - No Detailed Affiliation Given 1p 17746.148.

--8303290779 Mod 9,changing NRC project officer from M Messinger to ML Miller,to "Evaluation of Matl Accounting Performances at Nuclear Fuel Cycle Facilities."
PEVENSTEIN,J. NUSAC, Inc GUSTAVE,R.P. Division of Contracts NRC-02-81-028 83/02/22 1p 17746.149.

8303290783 Notification of contract execution: "Radiation Monitoring Program Requirements," awarded to State of TX Dept of Health.
MCDERMOTT,D. Technical Assistance Contracts Branch FIN B-8504 NRC-31-83-671 83/03/07 MEYERS,D.M. Region 4, Office of Director NICHOLAS,J.B. NRC - No Detailed Affiliation Given 1p 17748.194.

--8303290788 Contract: "Radiation Monitoring Program Requirements," awarded to State of TX Dept of Health.Statement of work encl
THIEL,J. Texas, State of MORTON,K.V. Division of Contracts FIN B-5804 NRC-31-83-671 83/03/07 18pp 17748.195.

8303290785 Notification of contract execution:Mod 5 to "MCLAMS Mod." Contractor:NUSAC, Inc. FIELDS, J A Technical Assistance Contracts Branch NRC-02-82-034 83/02/23 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director MILLER, M NRC - No Detailed Affiliation Given 1p 17748:192

--8303290790 Mod 5, changing NRC project manager from M Messinger to ML Miller, to "MCLAMS Mod." PEVENSTEIN, J NUSAC, Inc GUSTAVE, R P Division of Contracts NRC-02-82-034 83/02/23 1p 17748:193

8303290793 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to State of CO Dept of Health Statement of work MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8501 NRC-31-83-668 83/03/07 MEYERS, D M Region 4, Office of Director NICHOLAS, J B NRC - No Detailed Affiliation Given 1p 17748:157

--8303290798 Contract: "Radiation Monitoring Program Requirements," awarded to State of CO Dept of Health Statement of work encl TAYLOR, F Colorado, State of MORTON, K V Division of Contracts FIN B-8501 NRC-31-83-668 83/03/07 18pp 17748:158

8303290794 Notification of contract execution:Mod 8 to "Operation & Maint of NRC Document Control Sys." Contractor:Planning Research Corp BROMBERG, B Administrative Contracts Branch NRC-10-82-356 83/03/18 NORRY, P G Office of Administration LUNDY, J NRC - No Detailed Affiliation Given 1p 17748:151

--8303290818 Mod 8, providing personnel, matls & facilities necessary to reconfigure multiplexors, enabling regional ofc low speed terminal operators to dial off net from Bethesda, MD, to "Operation & Maint of NRC Document Control Sys." FURST, T J Planning Research Corp SMITH, P A Division of Contracts NRC-10-82-356 83/03/18 5pp 17748:152

8303290840 Notification of contract execution:Mod 3 to "Electrical & Instrumentation Technology & Codes Course." Contractor:GE WOLLETT, S Technical Assistance Contracts Branch FIN B-1258 NRC-05-81-261 83/03/18 BLAHA, J L Director's Office, Office of Inspection and Enforcement THAYER, C W NRC - No Detailed Affiliation Given 1p 17746:079

--8303290853 Mod 3, exercising options for 1983 courses & providing funding, to "Electrical & Instrumentation Technology & Codes Course." * General Electric Co GUSTAVE, R P Division of Contracts FIN B-1258 NRC-05-81-261 83/03/18 1p 17746:080

8303300061 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to State of VT MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8351 NRC-28-83-605 83/03/09 MCOSCAR, J Division of Resource Management & Administration COSTELLO, F NRC - No Detailed Affiliation Given 1p 17751:078

--8303300067 Contract: "Radiation Monitoring Program Requirements," awarded to State of VT ROSENSTREICH, B Vermont, State of MORTON, K V Division of Contracts FIN B-8351 NRC-28-83-605 83/03/09 10pp 17751:079

8303300073 Notification of contract execution:Mod 1 to "Radiation Monitoring Program Requirements." Contractor:State of MD MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8454 NRC-30-83-643 83/03/09 PAPPAS, H Division of Resource Management & Administration OESTMANN, M J NRC - No Detailed Affiliation Given 1p 17751:059

--8303300079 Mod 1, correcting B&R number, to "Radiation Monitoring Program Requirements." * Missouri, State of MORTON, K V Division of Contracts FIN B-8454 NRC-30-83-643 83/03/09 1p 17751:060

8303300297 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to State of MI MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8451 NRC-30-83-644 83/03/09 PAPPAS, H Office of Resource Management, Director OESTMANN, M J NRC - No Detailed Affiliation Given 1p 17754:001

--8303300585 Contract "Radiation Monitoring Program Requirements," awarded to State of MI WALKER, B Michigan, State of, Dept of Public Health MORTON, K V Division of Contracts FIN B-8451 NRC-30-83-644 83/03/09 9pp 17754:002

8303300439 Notification of contract execution:Mod 4 to "Training Consolidation Study." Contractor:BDM Corp SMITH, P A Division of Contracts NRC-10-78-414 83/03/25 SPRINGER, M Office of Administration COMELLA, P A NRC - No Detailed Affiliation Given 1p 17753:309

--8303300449 Mod 4, deobligating funds remaining under contract for closeout, to "Training Consolidation Study." YOUNG, R BDM Corp SMITH, P A Division of Contracts NRC-10-78-414 83/03/25 2pp 17753:310

8303300454 Notification of contract execution:Mod 4 to "Micrographic Svcs." Contractor:Microtech Industries, Inc SMITH, P A Division of Contracts NRC-10-80-708 83/03/25 SPRINGER, M Office of Administration JONES, P NRC - No Detailed Affiliation Given 1p 17753:322

--8303300458 Mod 4, deobligating funds remaining under contract for closeout, to "Micrographic Svcs." RUOCCHIO, J Microtech Industries, Inc SMITH, P A Division of Contracts NRC-10-80-708 83/03/25 1p 17753:323

8303300481 Notification of contract execution:Mod 2 to "Expert Opinion on Use of PRA & Safety Goals." Contractor:NUS Corp MURPHY, L Administrative Contracts Branch FIN B-8178 NRC-19-82-493 83/03/22 REMICK, F J Office of Policy Evaluations MONTGOMERY, J NRC - No Detailed Affiliation Given 1p 17748:284

--8303300485 Mod 2, extending period of performance to 830630 at no addl govt cost, to "Expert Opinion on Use of PRA & Safety Goals." * NUS Corp REBELLO, J E Division of Contracts FIN B-8178 NRC-19-82-493 83/03/22 1p 17748:285

8303300555 Notification of contract execution "Info Mgt Sys for NRC Operation Ctr." awarded to Phoenix Assoc, Inc HAGEY, H Administrative Contracts Branch FIN B-8709 NRC-05-83-218 83/03/18 MUIR, H Program Support Branch HIMES, J NRC - No Detailed Affiliation Given 1p 17763:115

--8303300574 Contract "Info Mgt Sys for NRC Operation Ctr." awarded to Phoenix Assoc, Inc FERSTERSTON, K J Phoenix Associates, Inc MATTIA, M J Administrative Contracts Branch FIN B-8709 NRC-05-83-218 83/03/18 62pp 17763:116

8303300568 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to State of OH MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8450 NRC-30-83-646 83/03/16 PAPPAS, H Region 3, Office of Director OESTMANN, M J NRC - No Detailed Affiliation Given 1p 17748:311

--8303300576 Contract "Radiation Monitoring Program Requirements," awarded to State of OH GARDNER, T A Ohio, State of MORTON, K V Division of Contracts FIN B-8450 NRC-30-83-646 83/03/16 9pp 17748:312

8303300598 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to State of TN MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8401 NRC-29-83-622 83/03/16 LOY, T N Office of Resource Management, Director MONTGOMERY, D M NRC - No Detailed Affiliation Given 1p 17766:304

--8303300604 Contract: "Radiation Monitoring Program Requirements," awarded to State of TN WORD, J E Tennessee, State of MORTON, K V Division of Contracts FIN B-8401 NRC-29-83-622 83/03/16 15pp 17766:335

8303300676 Notification of contract execution:Mod 1 to "Sys Analysis & Program Support Svcs." Contractor:SBA/Logical Technical Svc Corp GILDENHORN, A J Administrative Contracts Branch FIN B-8803 NRC-33-83-453 83/03/16 BARRY, L Office of Resource Management, Director PANZARELLA, J NRC - No Detailed Affiliation Given 1p 17768:303

--8303300677 Mod 1, clarifying work statement scope, adding provision for pilot study, increasing contract ceiling, adjusting fee withholding procedures & making minor corrections to: "Sys Analysis & Program Support Svcs." ROGERS, A A Small Business Administration BLOOMBERG, J R Logical Technical Service Corp HAGAN, T F Division of Contracts FIN B-8803 NRC-33-83-453 83/03/16 4pp 17768:304

8303300680 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to State of MS MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8400 NRC-29-83-621 83/03/16 LOY, T N Region 2, Office of Director MONTGOMERY, D M NRC - No Detailed Affiliation Given 1p 17763:343

--8303300683 Contract: "Radiation Monitoring Program Requirements," awarded to State of MS.
COMB, A B Mississippi, State of MORTON, K V Division of Contracts FIN B-8400 NRC-29-83-621 83/03/16 14pp 17763 344

8303300687 Notification of contract execution: "Radiation Monitoring Program Requirements," awarded to State of MN.
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8452 NRC-30-83-645 83/03/09 PAPPAS, H Region 3, Office of Director OESTMANN, M J NRC - No Detailed Affiliation Given 1p 17764 003

--8303300698 Contract: "Radiation Monitoring Program Requirements," awarded to State of MN.
ASHTON, M M Minnesota, State of MORTON, K V Division of Contracts FIN B-8452 NRC-30-83-645 83/03/09 9pp 17764 004

8303310052 Notification of contract execution, Mod 6 to "MCLAMS Mod." Contractor: NUSAC.
FIELDS, J A Technical Assistance Contracts Branch FIN B-7348-3 NRC-02-82-034 83/03/22 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director MILLER, M NRC - No Detailed Affiliation Given 1p 17775 346

--8303310056 Mod 6, extending period of performance to 840116, increasing contract funds & increasing essential personnel by two, to "MCLAMS Mod." Statement of work encl.
PEVENSTEIN, J NUSAC, Inc GUSTAVE, R P Division of Contracts FIN B-7348-3 NRC-02-82-034 83/03/22 12pp 17775 347

8303310072 Notification of grant execution, Mod 2 to "Study of Steam Water Flows." Grantee: Northwestern Univ.
MCDERMOTT, D Technical Assistance Contracts Branch FIN G-1000 NRC-G-04-81-020 83/03/21 BATSON, W Office of Nuclear Regulatory Research, Director REYES, J NRC - No Detailed Affiliation Given 1p 17775 328

--8303310103 Mod 2, extending grant period by 60 days & providing addl funds, to "Study of Steam Water Flows."
GEAR, Y W J Northwestern Univ. MORTON, K V Technical Assistance Contracts Branch FIN G-1000 NRC-G-04-81-020 83/03/21 1p 17775 329

8303310108 Notification of grant execution, Mod 3 to "Study of Faulting in & Near Surface & Underground Mines of Southwestern, IN." Grantee: IN Univ.
MCDERMOTT, D Technical Assistance Contracts Branch FIN G-1019 NRC-G-04-81-017 83/03/21 BATSON, W Office of Nuclear Regulatory Research, Director WASTLER, S NRC - No Detailed Affiliation Given 1p 17775 317

--8303310112 Mod 3, extending grant period by 1 yr & increasing funding, to "Study of Faulting in & Near Surface & Underground Mines of Southwestern IN."
MULHOLLAND, J D Indiana Univ. MORTON, K V Technical Assistance Contracts Branch FIN G-1019 NRC-G-04-81-017 83/03/21 1p 17775 318

8303310132 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements." Contractor: State of MI.
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8451 NRC-30-83-644 83/03/09 PAPPAS, H Region 3, Office of Director OESTMANN, M J NRC - No Detailed Affiliation Given 1p 17775 182

--8303310136 Mod 1, correcting B&R number, to "Radiation Monitoring Program Requirements."
HENNIGAN, J Michigan, State of MORTON, K V Division of Contracts FIN B-8451 NRC-30-83-644 83/03/09 1p 17775 183

8303310139 Notification of contract execution, Mod 5 to "Eastern TN/Western NC Regional Seismic Network." Contractor: Memphis State Univ.
FIELDS, J A Technical Assistance Contracts Branch FIN B-6675 NRC-04-79-214 83/03/02 BATSON, W Office of Nuclear Regulatory Research, Director MURPHY, A NRC - No Detailed Affiliation Given 1p 17775 174

--8303310143 Mod 5, extending period of performance to 831130 & increasing funds, to "Eastern TN/Western NC Regional Seismic Network."
CARPENTER, T G Memphis State Univ. GUSTAVE, R P Technical Assistance Contracts Branch FIN B-6675 NRC-04-79-214 83/03/02 5pp 17775 175

8303310151 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements." Contractor: State of WI.
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8453 NRC-30-83-647 83/03/16 PAPPAS, H Region 3, Office of Director OESTMANN, M J NRC - No Detailed Affiliation Given 1p 17775 180

--8303310155 Mod 1, correcting B&R number, to "Radiation Monitoring Program Requirements."
* Wisconsin, State of MORTON, K V Division of Contracts FIN B-8453 NRC-30-83-647 83/03/16 1p 17775 181

8303310186 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements." Contractor: State of MN.
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8452 NRC-30-83-645 83/03/09 PAPPAS, H Region 3, Office of Director OESTMANN, M J NRC - No Detailed Affiliation Given 1p 17775 112

--8303310200 Mod 1, correcting B&R number, to "Radiation Monitoring Program Requirements."
DOLEZAL, A Minnesota, State of MORTON, K V Division of Contracts FIN B-8452 NRC-30-83-645 83/03/09 1p 17775 113

8303310330 Notification of contract execution, Mod 2 to "Estimation of Atmospheric Dispersion at Nuclear Reactor Plants Utilizing Real Time Anemometer Statistics." Contractor: CO State Univ.
WOLLETT, S Technical Assistance Contracts Branch FIN B-7585 NRC-04-81-202 83/03/10 FOREHAND, W Office of Nuclear Regulatory Research, Director ABBEY, R NRC - No Detailed Affiliation Given 1p 17780 351

--8303310336 Ltr Contract NRC-04-81-202, Mod 2, unilaterally increasing funds to "Estimation of Atmospheric Dispersion at Nuclear Reactor Plants Utilizing Real Time Anemometer Statistics."
GUSTAVE, R P Technical Assistance Contracts Branch FIN B-7585 NRC-04-81-202 83/03/10 RUSSELL, D J Colorado State Univ. 1p 17780 352

8303310343 Notification of contract execution, Mod 2 to "Task Analysis of Nuclear Power Plant Control Room Crews." Contractor: General Physics Corp.
FLYNN, M Technical Assistance Contracts Branch FIN B-7491 NRC-04-82-005 83/03/11 FOREHAND, W Office of Nuclear Regulatory Research, Director JENKINS, J NRC - No Detailed Affiliation Given 1p 17780 348

--8303310348 Mod 2, adding incremental funding, to "Task Analysis of Nuclear Power Plant Control Room Crews."
* General Physics Corp GUSTAVE, R P Division of Contracts FIN B-7491 NRC-04-82-005 83/03/11 1p 17780 349

8303310349 Notification of contract execution: "Multiple Award Task Order Contract for ADP Development," awarded to Control Data Corp.
DORSEY, M, MILES, E B Administrative Contracts Branch FIN B-8166 NRC-33-83-452 83/02/25 BASSETT, H S, HARVES, J Office of Resource Management, Director 1p 17795 289

--8303310352 Contract: "Multiple Award Task Order Contract for ADP Development," awarded to Control Data Corp.
KINNEY, W H Control Data Corp. MATTIA, M J Administrative Contracts Branch FIN B-8166 NRC-33-83-452 83/02/25 42pp 17795 290

8303310363 Notification of contract execution: "Radiation Monitoring Program Requirements," awarded to State of WI.
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8453 NRC-30-83-647 83/03/16 PAPPAS, H Region 3, Office of Director OESTMANN, M J N.C - No Detailed Affiliation Given 1p 17795 332

--8303310367 Contract: "Radiation Monitoring Program Requirements," awarded to State of WI.
REIVITZ, L Wisconsin, State of MORTON, K V Division of Contracts FIN B-8453 NRC-30-83-647 83/03/16 16pp 17795 333

8303310370 Notification of contract execution: "Radiation Monitoring Program Requirements," awarded to State of AL.
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8405 NRC-29-83-626 83/03/16 LOY, T N Region 2, Office of Director MONTGOMERY, D M NRC - No Detailed Affiliation Given 1p 17796 058

--8303310374 Contract: "Radiation Monitoring Program Requirements," awarded to State of AL.
MYERS, I L Alabama, State of MORTON, K V Division of Contracts FIN B-8405 NRC-29-83-626 83/03/16 14pp 17796 059

8303310572 Notification of contract execution, Mod 2 to "LA Offshore Radiological Licensee Survey." Contractor: State of LA.
HOPPER, A M Administrative Contracts Branch FIN B-8703 NRC-05-82-252 82/09/23 BLAHA, J L Program Support Branch YACZKO, C NRC - No Detailed Affiliation Given 1p 17780 346

--8303310576 Mod 2, extending period of performance to 830731, to "LA Offshore Radiological Licensee Survey."
PORTER, J B Louisiana, State of REBELLO, J E Division of Contracts FIN B-8703 NRC-05-82-252 82/09/23 1p 17780 347

8303310584 Notification of contract execution:Mod 3 to "Transient Prototypical Steam Generator (MB-2) Research Testing Program." Contractor:Westinghouse/EPRI. BAISDEN,L. Technical Assistance Contracts Branch FIN B-8252 NRC-04-82-020 83/03/21 BATSON,W. Office of Nuclear Regulatory Research, Director HOPENFELD,J. NRC - No Detailed Affiliation Given 1p 17780:335.

--8303310594 Ltr Contract NRC-04-82-020,Mod 3,extending period of performance until 830331, to "Transient Prototypical Steam Generator (MB-2) Research Testing Program." MORTON,K.V. Division of Contracts FIN B-8252 NRC-04-82-020 83/03/21 SPENCE,L.W. Westinghouse Electric Corp. RYTKONEN,B.B. Electric Power Research Institute 2pp 17780:336.

8303310598 Notification of contract execution:Mod 2 to "Review Group on Man-Machine Considerations." Contractor:Aerospace Corp. SMITH,P.A. Division of Contracts NRC-10-79-667 83/03/24 DEYOUNG,R.C. BUDNITZ,R. NRC - No Detailed Affiliation Given 1p 17780:330.

--8303310602 Mod 2,deobligating balance of funds, to "Review Group on Man-Machine Considerations." CULVER,C.M. Aerospace Corp. SMITH,P.A. Division of Contracts NRC-10-79-667 83/03/24 1p 17780:331.

8303310621 Notification of grant execution:Mod 3 to "Process of Droplet Disposition on Two Phase Gas-Liquid Flow Analysis of Mechanism & Modeling." Grantee:Univ of Houston. MCDERMOTT,D. Technical Assistance Contracts Branch FIN G-1026 NRC-G-04-81-027 83/03/21 BATSON,W. Office of Nuclear Regulatory Research, Director ZUBER,N. NRC - No Detailed Affiliation Given 1p 17780:321.

--8303310628 Mod 3,extending grant period through 840930, to "Process of Droplet Disposition in Two Phase Gas-Liquid Flow Analysis of Mechanism & Modeling." NORRIS,J.T. Houston, Univ. of MORTON,K.V. Technical Assistance Contracts Branch FIN G-1026 NRC-G-04-81-027 83/03/21 1p 17780:322.

8303310642 Notification of grant execution "Intl Topical Meeting on LWR Severe Accident Evaluation," awarded to ANS. MCDERMOTT,D. Technical Assistance Contracts Branch FIN G-1046 NRC-G-04-83-002 83/03/23 BATSON,W. Office of Nuclear Regulatory Research, Director SULLIVAN,L. NRC - No Detailed Affiliation Given 1p 17780:318.

--8303310646 Grant: "Intl Topical Meeting on LWR Severe Accident Evaluation:" awarded to ANS. SHAFFER,H.C. American Nuclear Society MORTON,K.V. Technical Assistance Contracts Branch FIN G-1046 NRC-G-04-83-002 83/03/23 2pp 17780:319.

## FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES

8303010029 Final response to FOIA request for documents re labor unions, strikes & const defects, design errors & QA problems involving LK Comstock Co Forwards G Pirtle 810925 memo Document partially withheld (ref FOIA Exemption 5). FELTON,J.M. Division of Rules and Records 83/01/21 SAWICKI,S.G. News-Herald Willoughby, OH 1p 17347:305.

8303020017 "Structural Engineering Branch Criteria for Safety-Related Masonry Wall Evaluation." * Structural Engineering Branch 81/07/31 7pp 17360:029.

--8303020088 "Preliminary Title List Rept." * NRC - No Detailed Affiliation Given NRC-10-82-356 82/12/30 26pp 17360:107.

--8303020157 Informs that categorization of turbine bldgs as nonseismic Category I structures philosophically sound, in response to JF Ahearne 820924 memo. Provisions covering safety consideration & turbine bldg design adequate. SCHAUER,F.P. Structural Engineering Branch 82/10/20 CRUTCHFIELD,D. Operating Reactors Branch 5 4pp 17360:103.

8303020164 FOIA request for seven categories of records re Brown & Root, Inc & South TX Project. LINDEMAN,H.N. Lowenstein, Newman, Reis, Axelrad & Toll 82/12/13 Office of Administration 3pp 17356:215.

8303020166 Partial response to FOIA request for seven categories of records re Brown & Root, Inc & South TX Project. Region IV has no records on subj. Category I Addl 10 records re App A Category 4 available in PDR. FELTON,J.M. Division of Rules and Records 83/01/27 LINDEMAN,H.N. Lowenstein, Newman, Reis, Axelrad & Toll 3pp 17356:218.

8303020186 Appeals denial of FOIA request for SECY-82-111B. GRABER,L.D. Affiliation Unknown 82/12/08 HOYLE,J.C. Office of the Secretary of the Commission 1p 17356:210.

8303020192 Responds to appeal re denial of FOIA request for SECY-82-111B. Commission granted appeal. SECY-82-111B available in PDR. CHILK,S.J. Office of the Secretary of the Commission 83/01/25 GRABER,L. Affiliation Unknown 1p 17356:211.

8303020196 FOIA request for three categories of documents re spent fuel casks. AUDIN,L. Affiliation Unknown 82/12/19 Division of Rules and Records 1p 17356:228.

8303020199 Responds to FOIA request for three categories of documents re spent fuel casks. Forwards Documents 1, 2 & 12 listed in app. Remaining documents available in PDR. FELTON,J.M. Division of Rules and Records 83/01/24 AUDIN,L. Affiliation Unknown 2pp 17356:229.

--8303020202 Draft rev to "Topical SAR for Castor Cask Type ISFSI (Dry Storage)." * Gesellschaft fur Nukleur-Service mbH 82/11/30 210pp 17356:239.

8303030200 Addl response to FOIA request for documents re packaging & transporting spent nuclear fuel away from reactor sites by Southern CA Edison Co. Forwards documents W/o encls. FELTON,J.M. Division of Rules and Records 83/01/31 RAPKIN,A. Illinois, State of 1p 17365:191.

8303030204 FOIA request for printouts of all NRC licensed industrial radiographers & users of industrial gauges in Regions I & III. HUBER,S.A. Stan A. Huber Consultants, Inc 83/01/17 STRASMA,J. Office of Public Affairs 1p 17365:200.

8303030209 Responds to FOIA request for printout of all NRC licensed industrial radiographers & users of industrial gauges in Regions I & III. Forwards computer printouts W/o encl. FELTON,J.M. Division of Rules and Records 83/02/01 HUBER,S.A. Stan A. Huber Consultants, Inc 1p 17365:201.

8303030217 Final response to FOIA request for seven categories of info. Documents listed on app available in PDR. FELTON,J.M. Division of Rules and Records 83/01/26 SCHLISSEL,D.A. New York, State of 2pp 17365:202.

8303030221 FOIA request for IE Bulletin 82-02 distribution list. CROWLEY,E.D. Flexitallic Gasket Co., Inc. IEB-82-02 83/02/03 Division of Rules and Records 1p 17365:208.

8303030226 Responds to FOIA request for IE Bulletin 82-02 distribution list. Forwards requested list W/o encl. FELTON,J.M. Division of Rules and Records IEB-82-02 83/02/23 CROWLEY,E.D. Flexitallic Gasket Co., Inc. 1p 17365:209.

8303030230 Requests IE Bulletin 82-02 distribution list. CROWLEY,E.D. Flexitallic Gasket Co., Inc. 83/01/05 DISILVESTRE,S. Document Management Branch 1p 17365:210.

8303090001 FOIA request for documents re exploration, mining or milling of U in specific areas of State of NE. REID,A.B. Broken Plow Law Office 82/12/30 Division of Rules and Records 2pp 17466:303.

8303090002 Responds to FOIA request for documents re exploration, mining or milling of U in specific areas in State of NE. Forwards documents listed in app. Review of remaining documents in progress. FELTON,J.M. Division of Rules and Records 83/01/28 REID,A.B. Broken Plow Law Office 2pp 17466:305.

--8204070025 Requests NRC reassert regulatory authority to regulate source matls re U mining & milling. THONE,C. Nebraska, State of 82/02/19 KERR,G.W. Office of State Programs, Director 4pp 17466:307.

--8209280360 Comments on draft memorandum of understanding transmitted by 820727 memo. Memorandum should clearly state scope covers only U solution in situ mining projects. MURRAY,J.P. Deputy Executive Legal Director 82/08/18 COLLINS,J.T. Region 4, Office of Director 2pp 17466:323.

--8303090004 Recommends meeting w/State of NE officials to develop staff level agreement on coordination of license reviews. DAVIS,J.G. Office of Nuclear Material Safety & Safeguards, Director 82/05/18 COLLINS,J.T. Region 4, Office of Director 1p 17466:309.

--8303090005 Summary of 820608 meeting w/state of NE Dept of Environ Control to develop mechanism for coordinating reviews of U solution mining by NRC & state.
LINEHAN, J. J. Uranium Recovery Licensing Branch 82/06/16
SCARANO, R. A. Uranium Recovery Licensing Branch 3pp 17466:310.

--8303090006 Forwards MOU for in situ U mining in State of NE for signature & date W/o encl.
COLLINS, J. T. Region 4, Office of Director 82/11/08 DRAIN, D. T. Nebraska, State of 1p 17466:313.

--8303090007 Grants request for NRC to reassert authority regulating source matl re in situ or solution U milling & mining. Reassertion effective 820504 Proposal may be submitted later for amend agreement.
DIRCKS, W. J. Office of the Executive Director for Operations 82/05/10 THONE, C. Nebraska, State of 2pp 17466:317.

--8303090009 Requests signature on State of NE MOU. MOU pertains only to activities transferred to Region IV.
DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director 82/09/17 COLLINS, J. T. Region 4, Office of Director 2pp 17466:321.

--8303090013 Discusses state action to regulate U milling per 1978 U Mill Tailings Radiation Control Act Agreement States authorized to license & regulate U mills & mill tailings must enter into amended agreements w/NRC by 811108.
NUSSBAUMER, D. A. Assistant Director for State Agreements Programs 83/01/28 SMITH, H. D. Nebraska, State of 2pp 17466:325.

--8303090014 Forwards "Rules & Regulations for Underground Injection Control" & "NE Environ Protection Act." State has 30 days to issue or deny application after submitted & determined complete. W/o encl.
DRAIN, D. T. Nebraska, State of 82/03/24 MONTGOMERY, J. L. Region 4, Office of Director 1p 17466:327.

--8303090016 Concurs w/State of NE MOU for in situ U mining. Editorial change recommended FR notice & DT Drain 830311 ltr encl.
DAVIS, J. G. Division of Safeguards 82/10/18 COLLINS, J. T. Region 4, Office of Director 5pp 17466:328.

8303090020 FOIA request for documents re turbine failures & Ofc for Analysis & Evaluation of Operational Data case study on BWR vessel level instrumentation.
HIATT, S. L. Ohio Citizens for Responsible Energy 83/01/03
FELTON, J. M. Division of Rules and Records 1p 17466:235.

8303090022 Responds to FOIA request for documents re turbine failures & Ofc for Analysis & Evaluation of Operational Data case study on BWR vessel level instrumentation. Forwards App A documents.
FELTON, J. M. Division of Rules and Records 83/01/28 HIATT, S. Ohio Citizens for Responsible Energy 2pp 17466:236.

--8303090026 "Probability of Damage to Nuclear Components Due to Turbine Failure."
BUSH, S. H. Battelle Memorial Institute, Pacific Northwest Laboratory 73/06/30 15pp 17466:238.

--8303090029 Discusses 740619 incident at Gallatin Unit 2 re turbine failure in intermediate stage rotor during startup. Insp prior to incident revealed crack in rotor. Replacement ordered. Restricted operation continued.
TEDESCO, R. L. Atomic Energy Commission, Directorate of Licensing 74/06/20 Atomic Energy Commission, Directorate of Licensing 1p 17466:253.

--8303090032 Trip rept of 740214 visit to Shippingport facility to inspect turbine-generator unit which failed on 740204.
CAMPE, K. M. Atomic Energy Commission, Directorate of Licensing 74/08/07 DENTON, H. R. Atomic Energy Commission, Directorate of Licensing 3pp 17466:254.

--8303090035 Comments on Shippingport 1974 first quarter operating rept re 740204 failure of rotating blading. Station shutdown due to severe turbine generator vibration. Rept contrasts observations made during 740214 site visit. Photograph encl.
GRIMES, B. K. Atomic Energy Commission, Directorate of Licensing 74/08/12 TEDESCO, R. Atomic Energy Commission, Directorate of Licensing 2pp 17466:257.

8303090039 Addl response to FOIA request for six categories of records re proposed rev to license fee schedules. Documents listed in app available in PDR. Addl documents under review.
FELTON, J. M. Division of Rules and Records 83/01/24 KNOWLES, N. J. Shaw, Pittman, Potts & Trowbridge 2pp 17465:253.

--8303090043 Advises that SECY-81-615 re proposed schedule of license fees approved if modified by attached comments. Rule should be modified to allow automatic annual update of fees based on prevailing salary schedules.
AHEARNE, J. F. Commissioners 81/12/16 CHILK, S. J. Office of the Secretary of the Commission 19pp 17465:261.

8303090082 Appeals partial denial of FOIA request for documents re environ qualification rulemaking.
CURRAN, D. BISHOP, L. L. Harmon & Weiss 82/12/14 CHILK, S. J. Office of the Secretary of the Commission 3pp 17466:221.

8303090088 Responds to appeal re partial denial of FOIA request for documents concerning environ qualification rulemaking. Document 3 available in PDR. Forwards Document 5. Remaining documents withheld (ref FOIA Exemption 5).
CHILK, S. J. Office of the Secretary of the Commission 83/02/01
CURRAN, D. Harmon & Weiss 3pp 17466:231.

--8303090093 Advises that UCS filed suit to have Commission suspension of 820630 deadline for environ qualification declared illegal.
MANNING, W. Commissioners 82/09/03 GILINSKY, V. Commissioners 1p 17466:234.

8303090121 Responds to FOIA request for SECY-82-388, "Withdrawal of Medical Misadministration Reporting Requirements." Document withheld (ref FOIA Exemption 5).
FELTON, J. M. Division of Rules and Records 83/02/09
ERNSTTHAL, H. L. Society of Nuclear Medicine 1p 17465:193.

8303090124 FOIA request for SECY-82-388, "Withdrawal of Medical Misadministration Reporting Requirements."
ERNSTTHAL, H. L. Society of Nuclear Medicine 83/01/18 CARR, J. C. Division of Rules and Records 1p 17465:194.

8303090129 FOIA request for study showing medical misadministrations over 18-month period.
HOWELL, K. CBS News, CBS, Inc. 83/01/18 FELTON, J. M. Division of Rules and Records 1p 17465:195.

8303090135 Responds to FOIA request for study showing medical misadministrations over 18-month period. Forwards "Rept on Medical Misadministrations for Jan 1981 - June 1982" & computer printout listing State of MO hosps. W/o rept.
FELTON, J. M. Division of Rules and Records 83/02/08 HOWELL, K. CBS News, CBS, Inc. 1p 17465:196.

--8303090144 "Misadministrations From Jan 1982 to Present," computer printout.
* NRC - No Detailed Affiliation Given 83/01/31 3pp 17465:197.

8303090149 Responds to FOIA request for SECY-82-388, "Withdrawal of Medical Misadministration Reporting Requirements." Document withheld (ref FOIA Exemption 5).
FELTON, J. M. Division of Rules and Records 83/02/09 LINTON, O. W. American College of Radiology 1p 17465:200.

8303090153 FOIA request for SECY-82-388, "Withdrawal of Medical Misadminstration Reporting Requirements."
LINTON, O. W. American College of Radiology 83/01/19 CHILK, S. J. Office of the Secretary of the Commission 1p 17465:201.

8303090160 FOIA request that 398 specified SECY papers be made available in PDR.
PEDRO, J. NUS Corp CD-LIS-8825 82/12/30 Division of Rules and Records 9pp 17465:176.

8303090164 Responds to FOIA request that 398 specified SECY papers be made available in PDR. Forwards listing of publicly available 1982 SECY papers.
FELTON, J. M. Division of Rules and Records 83/02/10 PEDRO, J. NUS Corp 1p 17465:185.

--8303090170 "Publicly Available 1982 SECY Staff Papers."
* NRC - No Detailed Affiliation Given 83/02/10 7pp 17465:186.

8303090174 FOIA request for documents re death of K Silkwood & MUF at Cimarron facility.
WHITED, P. J. Affiliation Unknown 83/01/17 Office of Administration 1p 17465:168.

8303090180 Responds to FOIA request for documents re death of K Silkwood & MUF at Cimarron facility. Documents listed in app, rept entitled "Problems in Accounting For Safeguarding of SNM," NUREG-0430 & NUREG-0350 available in PDR.
FELTON, J. M. Division of Rules and Records 83/02/08 WHITED, P. J. Affiliation Unknown 7pp 17465:169.

8303090183 FOIA request for recently issued risk policy
LEE, D E Affiliation Unknown 83/01/14 FELTON, J M Division of Rules and Records 1p 17465:066

8303090187 Responds to FOIA request for recently issued risk policy. Forwards NUREG-0880, "Safety Goals for Nuclear Power Plants Discussion Paper," & JE Zerbe 830111 memo re safety goal policy statement.
FELTON, J M Division of Rules and Records 83/02/04 LEE, D E Affiliation Unknown 1p 17465:067

--8303090193 Forwards policy statement on safety goals for operation of nuclear power plants revised at Commission 830110 meeting. Final revs indicated on 830107 marked-up draft.
ZERBE, J E Office of Policy Evaluations 83/01/11
PALLADINO, N J ; GILINSKY, V ; AHEARNE, J F Commissioners 28pp 17465:140

8303090219 Appeals partial denial of FOIA request for documents re environ qualification of electrical equipment.
CURRAN, D ; BISHOP, L L Harmon & Weiss 82/11/15 DIRCKS, W J Office of the Executive Director for Operations CHILK, S J Office of the Secretary of the Commission 3pp 17484:242

8303090228 Responds to appeal re partial denial of FOIA request for documents concerning environ qualification of electrical equipment. Forwards Documents 29, 34, 68 & Encl 1 to Document 12. Remaining documents withheld (ref FOIA Exemption 5).
CHILK, S J Office of the Secretary of the Commission 83/02/01
CURRAN, D Harmon & Weiss 7pp 17484:254

--8303090235 Marked-up draft Commission paper re proposed rulemaking concerning environ & seismic qualification of electric equipment for nuclear power plants.
DIRCKS, W J Office of the Executive Director for Operations 81/08/11 27pp 17484:261

--8303090243 Requests addl info re 811202 responses to Commissioner JF Ahearne 811117 questions concerning seismic qualification of electric equipment (SECY 81-504 & SECY-81-603).
AHEARNE, J Commissioners 81/12/14 Office of the Executive Director for Operations 1p 17484:294

--8303090250 Approves extension of 820630 deadline for environ qualification of safety-related electric equipment (SECY-82-207B). Final rule should be completed no later than end of Jul.
ASSELSTINE, J K Commissioners 82/06/21 CHILK, S J Office of the Secretary of the Commission 1p 17484:295

--8201120008 Responds to 811117 memo re questions concerning seismic qualification of electric equipment. Evolution of seismic & dynamic qualification of electric equipment detailed.
DIRCKS, W J Office of the Executive Director for Operations 81/12/02 AHEARNE, J F Commissioners 6pp 17484:288

--8303090235 Marked-up draft Commission paper re proposed rulemaking concerning environ & seismic qualification of electric equipment for nuclear power plants.
DIRCKS, W J Office of the Executive Director for Operations 81/08/11 27pp 17484:261

--8303090243 Requests addl info re 811202 responses to Commissioner JF Ahearne 811117 questions concerning seismic qualification of electric equipment (SECY 81-504 & SECY-81-603).
AHEARNE, J Commissioners 81/12/14 Office of the Executive Director for Operations 1p 17484:294

--8303090250 Approves extension of 820630 deadline for environ qualification of safety-related electric equipment (SECY-82-207B). Final rule should be completed no later than end of Jul.
ASSELSTINE, J K Commissioners 82/06/21 CHILK, S J Office of the Secretary of the Commission 1p 17484:295

8303090334 FOIA request for Topical Rept CENPD-270, "Dry Storage Cask for ISFSI."
CELENTANO, C Chem-Nuclear Systems, Inc 83/01/17 FELTON, J M Division of Rules and Records 1p 17484:141

8303090345 Responds to FOIA request for Topical Rept CENPD-270, "Dry Storage Cask for ISFSI." Forwards document responsive to request. Document also available in PDR. W/o encl.
FELTON, J M Division of Rules and Records 83/02/02 CELENTANO, C Chem-Nuclear Systems, Inc 1p 17484:142

8303090353 FOIA request for four categories of records re NRC grants.
SINNREICH, J Stuart, Zavin & Sinnreich 83/01/11 Division of Rules and Records 5pp 17484:135

8303090361 Responds to FOIA request for four categories of records re NRC grants. No issues per request have arisen to date. Forwards portion of NRC manual, Bulletin 5106-2, "Financial Assistance Programs Policy & Procedure," 1980. W/o encl.
FELTON, J M Division of Rules and Records 83/02/02 SINNREICH, J Stuart, Zavin & Sinnreich 1p 17484:140

8303090364 FOIA request for all records re specified investigation by Ofc of Inspector & Auditor.
GARDE, B Government Accountability Project 82/12/14 Office of Administration 2pp 17484:143

8303090373 Responds to FOIA request for all records re specified investigation by Ofc of Inspector & Auditor. Related records listed on app available in PDR under FOIA request 82-527.
FELTON, J M Division of Rules and Records 83/02/03 GARDE, B Government Accountability Project 2pp 17484:145

8303090398 Final response to FOIA request for SECY-82-39A, 82-197, 82-197A & 82-197B. Forwards SECY-82-39A & SJ Chilk 820616 memo. SECY-82-39A placed in PDR.
FELTON, J M Division of Rules and Records 83/02/23 GRABER, L Affiliation Unknown 1p 17477:112

--8205270445 SECY-82-039A
Forwards revised charter of CRGR for approval. CRGR will be directed to address nuclear plant equipment qualification, QA in nuclear plants, NRC policy on severe accidents, NRC safety goal implementation & TMI action plan requirements.
DIRCKS, W J Office of the Executive Director for Operations 82/04/29 25pp 17477:115

--8303090400 Advises that Commissioners Palladino, Ahearne, Roberts & Asselstine approved Charter of CRGR on Reactor Licensees per SECY-82-39A. Commissioner Gilinsky disapproved. Charter should be sent to all reactor licensees.
CHILK, S J Office of the Secretary of the Commission 82/06/16
DIRCKS, W J Office of the Executive Director for Operations 1p 17477:140

8303090404 FOIA request for matl re IE 821208 meeting w/GE discussing GE recommended actions concerning resolutions of BWR generic issues.
HAFNER, B Affiliation Unknown 83/01/24 Office of Administration 1p 17482:305

8303090408 Responds to FOIA request for matl re IE 821208 meeting w/GE discussing GE recommended actions concerning resolutions of BWR generic issues. Forwards requested meeting summary.
FELTON, J M Division of Rules and Records 83/02/18 HAFNER, B Affiliation Unknown 1p 17482:306

--8303090411 Summary of 821208 meeting w/GE re IE interfaces w/GE Nuclear Energy Business Operation. Issues affecting BWRs discussed. List of attendees encl.
BAER, R L Engineering & Generic Communications Branch 83/02/07
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 3pp 17482:307

8303090413 FOIA request for D Eisenhut 820219 memo re OL rule for NUREG-0737 requirements.
GRABER, L Affiliation Unknown 83/01/28 Division of Rules and Records 1p 17477:070

8303090415 Responds to FOIA request for D Eisenhut 820219 memo re OL rule for NUREG-0737 requirements. Forwards requested memo. Document available in PDR.
FELTON, J M Division of Rules and Records 83/02/17 GRABER, L Affiliation Unknown 1p 17477:071

--8203150315 Forwards final rule for OL applicants re NUREG-0737 Comments required by 820225.
EISENHUT, D G Division of Licensing 82/02/19 MATTSON, R J Division of Systems Integration (post 811005) HANAUER, S H Division of Safety Technology VOLLMER, R H Division of Engineering 40pp 17477:072

8303090425 FOIA request for documents re legal reviews of recently adopted interim OL provision & effect of provision on technical assistance support programs.
HAFNER, B Affiliation Unknown 83/01/03 KARAS, F Office of Administration 1p 17477:141

8303090429 Responds to FOIA request for documents re legal reviews of interim OL provision & effect of provision on technical assistance support programs. Forwards SECY-83-16 & erratum. General Counsel 810923 memo withheld (ref FOIA Exemption 5).
FELTON, J M Division of Rules and Records 83/02/17 HAFNER, B Affiliation Unknown 2pp 17477:142

--8301270005 SECY-83-016 ERR
Corrected Page 27 to SECY-83-16.
CHILK, S. J. Office of the Secretary of the Commission 83/01/18.
2pp. 17477:144.

8303100003 FOIA request for documents re Dec 1980 insp/investigation of Sys Control Corp & Magnetics, Inc & correspondence between IE & Div of Licensing concerning IE Info Notice 82-34.
GARDE, B. Government Accountability Project 82/12/14 Office of Administration. 2pp. 17493:050.

8303100006 Responds to FOIA request for documents re Dec 1980 insp/investigation of Sys Control Corp & Magnetics, Inc & IE Info Notice 82-34. Forwards Document 2 listed in app. Document 1 in PDR. Documents 3-7 withheld (ref FOIA Exemptions 5 & 7A).
FELTON, J. M. Division of Rules and Records 83/02/14 GARDE, B. Government Accountability Project. 3pp. 17493:052.

--8211060703 Modifies recommendations re Board Notification 82-90, "Welds in Main Control Panels." Marble Hill 1 & 2 & Clinton deleted from revised Info Notice 82-34.
JORDAN, E. L. Division of Engineering & Quality Assurance (Pre 830103) 82/10/01 EISENHUT, D. G. Division of Licensing. 1p. 17493:055.

8303100007 Addl response to FOIA request for documents re extensions issued in Nov & Dec 1981 & proposed extensions to "Stenographic Reporting Svc." awarded to Alderson Reporting Co, Inc. Documents partially withheld (ref FOIA Exemption 5).
FELTON, J. M. Division of Rules and Records 83/02/03 GALLO, J. Isham, Lincoln & Beale. 3pp. 17492:349.

--8303100010 Discusses addl funding needed for Mod 9 to contract "Stenographic Reporting Svcs." awarded to Alderson Reporting Co.
* NRC - No Detailed Affiliation Given. 82/03/02 NRC - No Detailed Affiliation Given. 1p. 17492:352.

--8303100021 Informs that Alderson Reporting contract, "Stenographic Reporting Svcs," will be extended. Provision stating that cases started prior to & continuing after contract terminates responsibility of contractor will be added.
FITTI, C. J. NRC - No Detailed Affiliation Given. 82/10/29.
MCNAMARA, A. NRC - No Detailed Affiliation Given. 1p. 17492:355.

--8303100031 Request for procurement SEC-80-448, Mod 13, executing "Stenographic Reporting Svcs." Period of performance extended to 821215.
CHILK, S. J. Office of the Secretary of the Commission.
NRC-17-80-448-02 82/11/04. 2pp. 17492:358.

--8303100042 Forwards Mod 12 to contract "Stenographic Reporting Svcs." for review & execution. Contract will be executed upon receipt.
SMITH, P. A. Division of Contracts. NRC-17-80-448-02 82/11/30.
SHARP, R. A. Alderson Reporting. 1p. 17493:001.

--8303100051 Mod 12, extending period of performance to 821215, to "Stenographic Reporting Svcs."
SHARP, R. A. Alderson Reporting. SMITH, P. A. Division of Contracts. FIN B-1311. NRC-17-80-448-0 82/12/03. 2pp. 17493:002.

--8303100055 Advises that Mod 12 to contract, "Stenographic Reporting Svcs" has been fully executed. W/o stated encl.
SMITH, P. A. Division of Contracts. NRC-17-80-448-02 82/12/09.
Alderson Reporting. 1p. 17493:004.

8303100011 Responds to FOIA request for transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY. Forty-six transcripts available in PDR for viewing only.
FELTON, J. M. Division of Rules and Records 83/02/15 REDANO, R. T. Affiliation Unknown. 1p. 17493:048.

8303100015 FOIA request for transcript of lawsuit between General Public Utils & B&W in Federal District Court, Southern District of NY.
REDANO, R. T. Affiliation Unknown. 83/02/02 Office of Administration. 1p. 17493:049.

8303100018 Responds to FOIA request for document re NRC investigation concerning mobile nuclear medicine testing svc operated by LCM, Sioux Falls, SD. Investigation not yet completed. Request withdrawn.
FELTON, J. M. Division of Rules and Records 83/02/16 COLLISON, K. Omaha World-Herald Omaha, NE. 1p. 17493:046.

8303100022 FOIA request for document re NRC investigation concerning mobile nuclear medicine testing svc operated by LCM, Sioux Falls, SD.
COLLISON, K. Omaha World-Herald Omaha, NE 83/02/01 EVERETT, J. NRC - No Detailed Affiliation Given. 1p. 17493:047.

8303100080 Responds to FOIA request for four categories of documents re risks from low trajectory turbine missiles. Forwards App A documents. Documents partially & completely withheld (ref FOIA Exemptions 4 & 5).
FELTON, J. M. Division of Rules and Records 83/02/10 HIATT, S. L. Ohio Citizens for Responsible Energy. 3pp. 17492:255.

8303100204 Responds to appeal re denial of FOIA request for confidential proposed QA stipulation prepared for OL & CP proceedings. Document withheld (ref FOIA Exemptions 4 & 5).
CHILK, S. J. Office of the Secretary of the Commission. 83/02/04.
STAMIRIS, B. Stamiris, B. 1p. 17504:085.

8303100391 FOIA request for six categories of records re proposed rev to license fee schedules.
KNOWLES, N. J. Shaw, Pittman, Potts & Trowbridge 82/12/15 Office of Administration. 2pp. 17521:125.

8303100395 Addl response to FOIA request for six categories of records re proposed rev to license fee schedules. Forwards documents listed in app. Documents also available in PDR. Addl documents under review.
FELTON, J. M. Division of Rules and Records 83/01/20 KNOWLES, N. J. Shaw, Pittman, Potts & Trowbridge. 3pp. 17521:127.

--8303100399 Concurs in FR notice attached to P. Norry 821018 ltr. NMSS fee vs nonfee work chart encl.
MCCORKLE, G. W. Power Reactor Safeguards Licensing Branch 82/10/22. BEVERIDGE, G. Program Support Branch. 2pp. 17521:130.

--8303100403 Forwards Div of Fuel Cycle & Matl Safety, Div of Safeguards & Div of Waste Mgt fee vs nonfee work tables based on FY81 operating plan & fee recoverable percentages provided in Dec 1981.
BROWN, R. S. Program Support Branch. 82/03/24 BURNETT, R. F. Division of Safeguards. CUNNINGHAM, R. E. Division of Fuel Cycle & Material Safety. MARTIN, J. B. Division of Waste Management. 5pp. 17521:132.

--8303100406 Forwards fee vs nonfee work tables for Div of Fuel Cycle & Matl Safety, Div of Waste Mgt & Div of Safeguards.
EVANS, J. Program Support Branch 82/03/08 WEISS, D. License Fee Management Branch. 11pp. 17521:137.

--8303100431 Requests that encl memo re proposed license fee schedule rev be rewritten for Cunningham signature & date to be included in memo for submitting info to Ofc of Administration.
BROWN, R. S. Program Support Branch 82/03/05 CARTER, T. Division of Fuel Cycle & Material Safety. 4pp. 17521:148.

--8303100434 Discusses proposed license fee rev casework review effort. Hours required from pooled data for FY80 & FY81 recalculated. Info for license fee prof processing time encl.
WILDE, R. M. Division of Fuel Cycle & Material Safety. 82/02/17.
EVANS, J. D. Program Support Branch. 22pp. 17521:152.

--8303100438 Requests addl info re results of review on suitability of 5-yr expiration limit for matls licenses & designated contact familiar w/matls licensing expenditures.
BROWN, R. S. Program Support Branch. 82/01/21 CUNNINGHAM, R. E. Division of Fuel Cycle & Material Safety. 1p. 17521:174.

--8303100442 Discusses 820112 meeting re background of license fee vs nonfee sys. Attendees listed.
SEELIG, C. A. NRC - No Detailed Affiliation Given. 82/01/20 NRC - No Detailed Affiliation Given. 1p. 17521:175.

--8303100448 Notification of 820112 meeting to discuss practices in assessing license fees established by NMSS.
BROWN, R. S. Program Support Branch. 82/01/06 BURNETT, R. F. Division of Safeguards. CUNNINGHAM, R. E. Division of Fuel Cycle & Material Safety. MARTIN, J. B. Division of Waste Management. 2pp. 17521:176.

--8303100452 Requests discussion w/B. Miller re fee sys Bases employed for position in assessing fees should be explained.
DAVIS, J. G. NRC - No Detailed Affiliation Given. 81/12/29.
BROWN, R. S. NRC - No Detailed Affiliation Given. 1p. 17521:178.

--8303100456 Forwards info developed by program support staff per License Fee Mgt Branch request. Info will be used to answer Commission questions pending revs to license fee schedule.
BROWN, R. S. NRC - No Detailed Affiliation Given. 81/12/16.
DAVIS, J. G. NRC - No Detailed Affiliation Given. 6pp. 17521:179.

--8303100458 Requests estimate of license fee vs nonfee work. Resource charts for Div of Fuel Cycle, Div of Safeguards & Div of Waste Mgt encl.
BROWN, R. S. Program Support Branch. 81/12/08 BURNETT, R. F. Division of Safeguards. CUNNINGHAM, R. E. Division of Fuel Cycle & Material Safety. MARTIN, J. B. Division of Waste Management. 5pp.

--8303100462 Requests review of encl draft Commission paper re license fee schedule.
REHM, T. A. Office of the Executive Director for Operations. 81/10/20. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. DAVIS, J. , DEYOUNG, R. NRC - No Detailed Affiliation Given. 51pp. 17521:193.

--8303100464 Discusses info inadvertently omitted from 810922 draft notice of proposed rulemaking amending Commission license fee schedule. New procedure for fee collection not appropriate for certain matls licenses.
BROWN, R. S. Program Support Branch. 81/09/28. DONOGHUE, D. J. Office of Administration. 6pp. 17521:243.

--8303100466 Disagrees w/two proposed changes re notice of proposed rulemaking amending NRC license fee schedule.
MCCORKLE, G. W. Physical Security Development Branch. 81/09/25. CHAPELL, D. R. Division of Safeguards. 2pp. 17521:249.

--8303100469 Forwards safeguards manhour estimates for fee categories of 10CFR170.31 per 810717 request. Figures for fee Category 1.H reflecting rev proposed by Rouse 810717 memo also provided. W/o encl.
BURNETT, R. F. Division of Safeguards. 81/07/22. BROWN, R. S. Program Support Branch. 1p. 17521:251.

--8303100473 Forwards U Recovery Licensing Branch fee info per 810717 memo re proposed license fee schedule rev.
SCARANO, R. A. Uranium Recovery Licensing Branch. 81/07/22. BROWN, R. S. Program Support Branch. 3pp. 17521:252.

--8303100477 Forwards NMSS license fee info for proposed license fee schedule rev.
NEUMANN, E. NRC - No Detailed Affiliation Given. 81/07/22. SEELIG, C. NRC - No Detailed Affiliation Given. 3pp. 17521:257.

--8303100480 Forwards response re license fees for low level waste per 810717 memo. U Recovery Licensing Branch info sent separately. No similar info needed for fee purposes.
MARTIN, J. B. Division of Waste Management. 81/07/21. BROWN, R. S. Program Support Branch. 4pp. 17521:258.

8303110042 Various handwritten notes, tables & photographs.
DEVLIN, J. W. NRC - No Detailed Affiliation Given. 81/06/09. 75pp. 17547:102.

8303110049 FOIA request for rept by Ofc of Inspector & Auditor re allegations concerning Region V inspectors & associated documents.
EMSHWILLER, J. R. Wall Street Journal. 82/10/26. NRC - No Detailed Affiliation Given. 1p. 17520:188.

8303110058 Responds to FOIA request for rept by Ofc of Inspector & Auditor & associated records. Forwards documents listed in app. Documents partially withheld (ref FOIA Exemptions 6 & 7). Denial may be appealed within 30 days from ltr receipt.
FELTON, J. M. Division of Rules and Records. 83/02/03. EMSHWILLER, J. R. Wall Street Journal. 3pp. 17520:189.

--8303110100 Advises that draft investigation repts will not be given to or reviewed w/licensees or agents w/o permission.
DIRCKS, W. J. Office of the Executive Director for Operations. 82/03/24. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. HAYNES, R. C. Region 1, Office of Director. O'REILLY, J. P. Region 2, Office of Director. 2pp. 17520:327.

--8303110124 Advises that info concerning investigation must be given to authorized recipients only. Branch chief should be informed of violation re confidential info immediately. Related info encl.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 78/08/22. Region 5, San Francisco, Office of the Director. 4pp. 17520:333.

--8303110127 Concurs that potentially criminal matters should be reported to respective investigative staffs. General reporting criteria per 800903 memo adequate.
THOMPSON, D. Executive Officer for Operations Support. 80/09/26. SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 2pp. 17520:337.

--8303110132 Discusses requirement for prompt notification of potentially criminal matters to investigative staff.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 80/09/03. THOMPSON, D. Executive Officer for Operations Support. 1p. 17520:339.

--8303110139 Expresses concern re statement made in Paragraph 2 of J Lieberman 820317 memo. Statement gives impression that draft rept given to licensee & would be discussed at 820310 enforcement conference before becoming finalized.
ENGELKEN, R. H. Region 5, Office of Director. 82/03/25. SPENCER, G. S. Division of Radiological Safety & Safeguards Program. 1p. 17520:340.

--8303110153 Forwards info clarifying 820310 enforcement conference w/ Southern CA Edison per 820329 memo.
SPENCER, G. S. Division of Radiological Safety & Safeguards Program. 82/04/08. ENGELKEN, R. H. Region 5, Office of Director. 1p. 17520:341.

--8303110172 Forwards rept of investigation re Region V release of draft insp rept & notice of violation to licensee on 820407 or 08. Administrative sanctions unwarranted. Clear & unambiguous policy must be developed re release of info to licensees.
CUMMINGS, J. J. Office of Inspector & Auditor. 82/06/17. PALLADINO, N. , GILINSKY, V. , AHEARNE, J. Commissioners. 2pp. 17520:351.

--8303110182 Requests memo be filed to reflect nonconcurrence re passage omitted from Narbut rept of investigation transmitted to Commission by 820617 memo.
GAMBLE, D. H. Office of Inspector & Auditor. 82/06/22. CUMMINGS, J. J. Office of Inspector & Auditor. 2pp. 17520:353.

8303140119 FOIA request for three most recent onsite insps for Matl/Byproduct Licenses 20-01412-03, 20-01412-05 & 20-01412-06.
ROSENBAUM, P. J. Affiliation Unknown. 83/01/17. FELTON, J. M. Division of Rules and Records. 1p. 17572:212.

8303140129 Responds to FOIA request for most recent onsite insps for Matl/Byproduct Licenses 20-01412-03, 20-01412-05 & 20-01412-06. Forwards documents listed in App A.
FELTON, J. M. Division of Rules and Records. 83/02/18. ROSENBAUM, P. J. Affiliation Unknown. 2pp. 17572:213.

--8303140138 Submits annual summary rept for 1977 re output measurements, radiation surveys, wipe tests & QC per license condition requirements & radiation therapy program.
BRAHMAVAR, S. M. Baystate Medical Center Springfield, MA. 78/01/17. GRUGAN, R. Baystate Medical Center Springfield, MA. 12pp. 17572:215.

--8303140145 Discusses insp of Licenses SNM-1766, 20-01412-05, 20-01412-06 & 20-01495-03 on 780615 & 16 & forwards notice of violation. License SNM-1766 inactive.
MCCLINTOCK, R. O. Region 1, Philadelphia, Office of the Director. 78/07/11. GIFFORD, H. C. Baystate Medical Center Springfield, MA. 2pp. 17572:227.

--8303140152 Notice of violation from insp on 780615 & 16. Noncompliance noted: routine insp programs not conducted by radiation protection officer at Wesson Memorial Hosp. Handwritten IE Insp Rept 30-09946/78-01 encl.
* Region 1, Philadelphia, Office of the Director. 78/07/11. 20pp. 17572:229.

--8303140159 Discusses insp of Licenses 20-01412-03 & 20-01412-06 on 780705. No noncompliance noted. Major areas inspected: measurements of radiation output of teletherapy units. Draft IE Insp Repts 30-00231/78-02 & 30-12375/78-02 encl.
MCCLINTOCK, R. O. Region 1, Philadelphia, Office of the Director. 78/07/18. GIFFORD, H. C. Baystate Medical Center Springfield, MA. 10pp. 17572:251.

--8303140165 Ack receipt of 780720 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-2684/78-01, 30-09946/78-01, 30-12395/78-01 & 30-00231/78-01.
MCCLINTOCK, R. O. Region 1, Philadelphia, Office of the Director. 78/08/01. GIFFORD, H. C. Baystate Medical Center Springfield, MA. 1p. 17572:249.

--8303140173 Responds to NRC 780711 ltr re violations noted in Insp Repts 70-2684/78-01, 30-00946/78-01, 30-12395/78-01 & 30-00231/78-01. Corrective actions: completions of isotope program at Wesson Memorial performed monthly.
KERRIGAN, G. A. Baystate Medical Center Springfield, MA. 78/07/20. MCCLINTOCK, R. O. Region 1, Philadelphia, Office of the Director. 1p. 17572:250.

--8303140177 Submits Condition 19.11 to license re posting of notice of violation in response to 780823 ltr.
MCCLINTOCK, R. O. Region 1, Philadelphia, Office of the Director. 78/09/14. SYED, I. B. Baystate Medical Center Springfield, MA. 1p. 17572:261.

--8303140181 Requests addl info re posting of notice of violation from insp on 780613 & 16.
SYFD: I B. Baystate Medical Center Springfield, MA 78/09/23
MCCLINTOCK, R O Region 1, Philadelphia, Office of the Director
1p 17572 262.

--8303140190 IE Insp Repts 30-00230/79-01 & 30-12375/79-01 on 790306 No noncompliance noted. Major areas inspected: mgt meeting, program requirements, independent insp effort, organization, matls, facilities & instruments & personnel protection.
MCCLINTOCK, R O. Region 1, Philadelphia, Office of the Director.
30-12375/79-01 79/03/15 5pp 17572 290.

--8303140192 Confirms 790605 meeting to review IE insp rept & insp program per 790517 telcon.
WHITTEMORE, M C. Baystate Medical Center Springfield, MA 79/05/18
MCCLINTOCK, R O. Region 1, Philadelphia, Office of the Director.
1p 17572 307.

--8303140196 Summarizes 790605 meeting at Baystate Medical Ctr in Springfield, MA re insp requirements. Related IE insp repts encl.
MCCLINTOCK, R O. Region 1, Philadelphia, Office of the Director
79/07/11 GIFFORD, H C. Baystate Medical Center Springfield, MA
22pp 17572 308.

--8303140201 IE Insp Rept 30-09946/79-02 on 790605. Items of concern: radiation therapy dept at Wesson Memorial Hosp & accuracy of complaints registered on 790411 re deliveries at Springfield Hosp.
O'NEILL, B., MCCLINTOCK, R O. Region 1, Philadelphia, Office of the Director 79/06/08 3pp 17572 333.

8303230104 Responds to FOIA request for RFP RS-OIE-83-216. Document will be sent by NRC Div of Contracts.
FELTON, J M. Division of Rules and Records RS-OIE-83-216
83/02/23 OGHOJAFOV, W Affiliation Unknown 1p 17687 127.

8303230108 FOIA request for RFP RS-OIE-83-216.
OGHOJAFOV, W Affiliation Unknown RS-OIE-83-216 83/02/14
Division of Contracts 1p 17687 128.

8303230112 Responds to FOIA request for NUREG/CR-2239, "Technical Guidance for Siting Criteria Development." Document may be purchased from NRC.
FELTON, J M. Division of Rules and Records 83/02/22 LEWONTIN, Y
Affiliation Unknown 1p 17677 360.

8303230115 FOIA request for NUREG/CR-2239, "Technical Guidance for Siting Criteria Development."
LEWONTIN, Y. Affiliation Unknown 83/02/10 NRC - No Detailed
Affiliation Given 1p 17677 361.

8303230132 Addl response to FOIA request for five categories of documents. Forwards SECY-82-87, SECY-82-396 & SECY-82-396A, identified as Item 1 of request.
FELTON, J M. Division of Rules and Records 83/02/23 HIATT, S L
Ohio Citizens for Responsible Energy 1p 17684 292 24X
Fiche 50-000, 83/02/23, 8303230132.

--8211020694 SECY-82-396
Requests Commission comments & views re draft federal policy statement on distribution of potassium iodide in vicinity of nuclear power plants for purpose of thyroidal blocking in event of large scale accidental release of radioiodine.
DIRCKS, W J. Office of the Executive Director for Operations
82/09/27 17pp 17684 310.

--8211040047 SECY-82-396A
Withdraws SECY-82-396 proposal to draft federal policy statement on distribution of potassium iodine in plant vicinity.
DIRCKS, W J. Office of the Executive Director for Operations
82/10/15 2pp 17684 327.

8303230174 FOIA request for six specified records.
GRABER, L. Affiliation Unknown 82/12/03 Division of Rules and Records 1p 17684 329.

8303230177 Responds to FOIA request for six specified records. Forwards Documents 1-6 listed in app. Documents 7 & 8 available in PDR. SECY-82-389 withheld (ref FOIA Exemption 5).
FELTON, J M. Division of Rules and Records 83/02/25 GRABER, L.
Affiliation Unknown 3pp 17684 330.

--8208260515 SECY-82-335
Recommends approval of proposed amend for publication in FR. Amend would clarify Commission authority to copy & take away copies of certain licensee records & require tests on safeguards-related equipment & procedures. FR notice encl.
DIRCKS, W J. Office of the Executive Director for Operations
82/08/11 30pp 17684 346.

--8211300421 SECY-82-380
Requests Commission approval to publish proposed amend to 10CFR2.201, authorizing issuances of notices of violations to nonlicensees; clarifying authority of regional administrator to issue notices of violations.
DIRCKS, W J. Office of the Executive Director for Operations
82/09/15 14pp 17685 014.

--8303230178 Requests briefing on sys interaction & NRC PRA activities.
PALLADINO, N J. Commissioners 82/05/11 DIRCKS, W J. Office of the Executive Director for Operations 1p 17684 333.

--8303230181 Forwards briefing outline & specific responses to questions re sys interaction program, per 820511 request. Briefing scheduled for 820625.
DIRCKS, W J. Office of the Executive Director for Operations
82/06/17 PALLADINO, N J. Commissioners 12pp 17684 334.

--8303230187 Advises that Commission has partially approved proposed rulemaking to provide specific authority re testing of safeguards sys; copying of records & specifying retention period for physical security records (SECY-82-335).
CHILK, S J. Office of the Secretary of the Commission 82/10/19
DIRCKS, W J. Office of the Executive Director for Operations. 1p
17685 028.

--8303230190 Advises that Commission has approved proposed rulemaking to amend 10CFR2.200 & 2.201 (SECY-82-380). Final draft of proposed rule should be submitted for publication in FR.
CHILK, S J. Office of the Secretary of the Commission 82/10/20
DIRCKS, W J. Office of the Executive Director for Operations. 1p
17685 029.

8303230194 Responds to FOIA request for NUREG-2239 re possible consequences of nuclear reactor accidents. Document may be purchased from NRC.
FELTON, J M. Division of Rules and Records 83/02/23 CAMPBELL, B
End Nuclear Dumping in the Pacific 1p 17686 185.

8303230197 FOIA request for NUREG-2239 re possible consequences of nuclear reactor accidents.
CAMPBELL, B. End Nuclear Dumping in the Pacific 83/02/15
FELTON, J. Division of Rules and Records 1p 17686 186.

8303230293 Responds to FOIA request for NUREG/CR-2239, "Technical Guidance for Siting Criteria Development." Document may be purchased from NRC.
FELTON, J M. Division of Rules and Records 83/02/22 BOYLE, S
Affiliation Unknown 1p 17686 063.

8303230295 FOIA request for NUREG/CR-2239, "Technical Guidance for Siting Criteria Development."
BOYLE, S. Affiliation Unknown 83/02/09 NRC - No Detailed
Affiliation Given 1p 17686 064.

8303230472 Responds to FOIA request for final rept, "Radiological Assessment of Parks Township Burial Site (B&W) Leechburg, PA." Rept available in PDR.
FELTON, J M. Division of Rules and Records FIN A-9093-0 83/02/25
ZEYHER, S H. Atlantic Richfield Co (ARCO) 1p 17677 229.

8303230474 FOIA request for final rept, "Radiological Assessment of Parks Township Burial Site (B&W) Leechburg, PA."
ZEYHER, S H. Atlantic Richfield Co (ARCO). FIN A-9093-0 83/02/07
Office of Administration 1p 17677 230.

8303230487 Responds to FOIA request for documents re exploration, mining or milling of U in specific areas of State of NE. Forwards documents listed in App A. Review of remaining documents in progress.
FELTON, J H. Division of Rules and Records 83/02/24 REID, A B
Broken Plow Law Office 2pp 17673 157.

--8211180558 Forwards revised draft memorandum of understanding between State of NE Dept of Environ Control & NRC re in situ U mining. Ofc of Executive Legal Director has no legal objection to memorandum provided noted changes incorporated.
CUNNINGHAM, G H. Office of the Executive Legal Director 82/10/15
COLLINS, J T. Region 4, Office of Director 3pp 17673 163.

8303230490 FOIA request for SECY-82-319.
REAP, M E. Debevoise & Liberman 83/01/27 FELTON, J M. Division of Rules and Records 1p 17673 125.

8303240117 FOIA request for medical misadministration rpts from hosps licensed in WI per NRC "Rept on Medical Misadministrations for Jan 1981 - June 1982." WI State Journal article encl.
STOEFFLER, D. Wisconsin, State of 83/01/31 Division of Rules and Records 2pp 17693 282.

8303240122 Responds to FOIA request for medical misadministration repts from hosps in WI per NRC "Rept on Medical Misadministrations for Jan 1981 - June 1982." Forwards documents listed in app. Portions of documents withheld (ref FOIA Exemption 6). FELTON, J.M. Division of Rules and Records. 83/02/18. STOEFFLER, D. Wisconsin, State of. 4pp. 17693:284.

--8104070367 Advises that on 810204 patient arrived for thyroid scan as confirmed by referring doctors ofc. After injection of 5 mCi technectium, discovered doctor had ordered thyroid ultrasound. Physician name deleted.
* Sheboygan Memorial Hosp. Sheboygan, WI. 81/02/04. Region 3, Chicago, Office of the Director. 1p. 17693:288.

--8108210338 Informs of 810623 misadministration of radiopharm. Patient received incorrect technectium dose. Imaging of pyrophosphate scan delayed. Patient has been rescheduled for 810624. Physician name deleted.
* St. Lukes Hosp. Milwaukee, WI. 81/06/23. Region 3, Chicago, Office of the Director (81/03/01). 1p. 17693:300.

--8108210447 Informs of 810630 misadministration of radiopharm. Patient injected w/3 mCi Tc-99MAA. Physician name deleted.
PRICE, D. St. Michael Hosp. Milwaukee, WI. 81/07/01. Region 3, Chicago, Office of the Director (81/03/01). 1p. 17693:303.

--8108210490 Informs of 810622 misadministration of radiopharm. Patient was injected w/technectium-DTPA to perform brain scan instead of liver scan. Nuclear medicine technologists are double checking all scan orders.
RUTZ, L.J. St. Joseph's Hosp., Marshfield, WI. 81/07/09. Region 3, Chicago, Office of the Director (81/03/01). 2pp. 17693:304.

--8110150329 Informs of 810924 misadministration of radiopharm. Patient received 0.392 mCi I-131 instead of 5.4 mCi I-131 Capsule being stored for decay prior to disposal. Physician name deleted.
* Waukesha Memorial Hosp. Waukesha, WI. 81/09/25. Region 3, Chicago, Office of the Director (81/03/01). 2pp. 17693:308.

--8110150356 Informs of 810831 misadministration of radiopharm. Patient injected w/16.1 mCi Tc-99m MDP instead of Tc-99m sulfur colloid. Physician name deleted.
LINDGREN, R.D. St. Mary's Hosp. Madison, WI. 81/10/05. Region 3, Chicago, Office of the Director (81/03/01). 1p. 17693:310.

--8111170263 Informs of 810504 misadministration of radiopharm. Patient scheduled for bone scan inadvertently received 500 uCi Yb-169. Cause not stated. Incident discussed at bimonthly inservice meeting. Physician name deleted.
LLAURADO, J.G. Veterans Admin. Center, Wood, WI. 695/115. 81/11/09. Region 3, Chicago, Office of the Director (81/03/01). 1p. 17693:311.

--8112010615 Informs of 811005 misadministration of radiopharm. Nuclear medicine bone scan request was improperly filled out & bone scan was administered to incorrect patient. No adverse effect observed. Physician info deleted.
* St. Anthony Hosp. Milwaukee, WI. 81/11/10. Director's Office, Office of Inspection and Enforcement. 2pp. 17693:312.

--8201040114 Informs of 810824 misadministration of radiopharm. Vial of DTPA mislabeled as MDP resulting in injection of three patients w/DTPA instead of bone scans. No ill effects on patients. All vials to be rechecked prior to injection.
GRUNWALD, T.J. Mercy Medical Center of Oshkosh, Inc. Oshkosh, WI. 81/12/23. Region 3, Chicago, Office of the Director (81/03/01). 1p. 17693:315.

--8201060494 Informs of 811219 misadministration of radiopharm. Patient was given 4.8 mCi Tc-99m for lung scan instead of sulfur colloid for liver/spleen scan. No adverse effect detected. Physician name deleted.
REED, S.A. St. Elizabeth Hosp., Appleton, WI. 81/12/22. Region 3, Chicago, Office of the Director (81/03/01). 1p. 17693:314.

--8201200407 Informs of 811106 misadministration of radiopharm. Patient scheduled for MDP bone scan administered 17 mCi 99 mTc pertechnetate. Measures proposed to avoid repetition. Physician name deleted.
LLAURADO, J.G. Veterans Admin. Center, Wood, WI. 695/115. 82/01/05. Region 3, Chicago, Office of the Director (81/03/01). 1p. 17693:316.

--8201200536 Forwards rept of 811207 misadministration of radiopharm. Patient referred for I-131 whole body scan received bone scan. No adverse effects observed. Scan rescheduled. Physician info deleted.
SIMPKIN, D.J. St. Lukes Hosp. Milwaukee, WI. 82/01/07. Region 3, Chicago, Office of the Director (81/03/01). 4pp. 17693:317.

--8201270341 Informs of misadministration of radiopharm for period of Oct-Dec 1981. Patient injected w/65 mCi unlabeled technetium instead of 20 mCi technetium glucoheptonate for brain scan. Physician name deleted.
COLLINGS, M.D. St. Vincent Hosp. Green Bay, WI. 82/01/18. Region 3, Chicago, Office of the Director (81/03/01). 1p. 17693:321.

--8204220451 Informs of 810803 & 811112 misadministrations of radiopharm. Wrong patient injected w/5 mCi Tc99m for thyroid scan in first incident. In latter incident, wrong patient injected w/15.5 mCi Tc99m DTPA for brain scan. Physician info deleted.
KRAUSE, L. Luther Hosp. Eau Claire, WI. 82/04/13. ADAM, W.J. Region 3, Office of Director. 5pp. 17693:322.

--8303240129 Informs of 810312 misadministration of radiopharm. Patient injected w/3 mCi Tc-99m sulfur colloid instead of 15 mCi Tc-99m MDP. Effect on patient insignificant. Nuclear medicine requisition will be redesigned. Physician name deleted.
MATSIS, J.P. St. Joseph's Hosp. Milwaukee, WI. 81/03/18. Region 3, Chicago, Office of the Director (81/03/01). 1p. 17693:289.

--8303240136 Informs of misadministration of radiopharm for Jan-Mar 1981. Patient injected w/20.4 mCi Tc-99m bone scanning agent for lung scan. All syringes will be labeled prior to drawing isotope. Physician name deleted.
ORLEANS, D.E. Holy Family Hosp. Manitowoc, WI. 81/03/31. Region 3, Chicago, Office of the Director (81/03/01). 1p. 17693:290.

--8303240139 Informs of 810217 misadministration of radiopharm. Patient injected w/5 mCi Tc-99m sulfur colloid instead of Tc-99m methylene diphosphonate for bone scan. Technicians instructed to double check identity of matl. Physician name deleted.
NIMMO, E. Wisconsin, Univ. of, Madison. 81/04/06. ADAM, W. Region 3, Chicago, Office of the Director (81/03/01). 2pp. 17693:291.

--8303240148 Informs of misadministration of radiopharm for Jan-Mar 1981. Patient injected w/technetium glucoheptonate instead of technetium MDP for bone scan. No ill effects on patient observed. Physician name deleted.
COLLINGS, M.P. St. Vincent Hosp. Green Bay, WI. 81/04/08. Region 3, Chicago, Office of the Director (81/03/01). 1p. 17693:293.

--8303240155 Informs of 810330 misadministration of radiopharm. Patient received 750 uCi Tc-99m sulfur colloid unnecessarily for bone scan. No adverse effects detected. Technologist consulted on proper procedure. Physician name deleted.
FLAHERTY, T.T. Theda Clark Medical Center Neenah, WI. 81/04/09. Region 3, Chicago, Office of the Director (81/03/01). 2pp. 17693:294.

--8303240166 Informs of 810309 misadministration of radiopharm. Patient injected intravenously w/5 mCi 99mTc MAA for lung fluoroscopy instead of lung scan. Technologists instructed to check exam orders prior to testing. Physician name deleted.
LINDGREN, R.D. St. Mary's Hosp. Madison, WI. 81/04/10. Region 3, Chicago, Office of the Director (81/03/01). 1p. 17693:296.

--8303240172 Informs of 810413 misadministration of radiopharm. Patient injected w/15 mCi Tc-99m MDP instead of 6 mCi Ga-67 citrate. Technician instructed to identify patient by armband & radiopharm by label on syringe. Physician name deleted.
MATSIS, J.P. St. Joseph's Hosp. Milwaukee, WI. 81/04/13. Region 3, Chicago, Office of the Director (81/03/01). 1p. 17693:297.

--8303240176 Informs of 810507 misadministration of radiopharm. Two doses of approx 20 mCi Tc-99m MAA dispensed instead of ordered Tc-99m MDP. Doses delivered to St Mary Medical Ctr in Racine, WI. Caused by pharmacist error.
REAVIS, J.M. Nuclear Pharmacy, Inc. 81/05/08. DAVIS, A.B. Region 3, Chicago, Office of the Director (81/03/01). 1p. 17693:298.

--8303240181 Informs of 810409 misadministration of radiopharm. Wrong patient injected w/15 mCi Tc-99m MDP. No adverse effects on patient noted. Technician verbally reprimanded & patient identification procedure written. Physician names deleted.
RAE, R.M. Laboratory of Clinical Medicine Sioux Falls, SD. 81/06/03. Region 3, Chicago, Office of the Director (81/03/01). 1p. 17693:299.

--8303240207 Informs of 810821 misadministration of radiopharm. Patient injected w/5 mCi 99mTc sulfur colloid instead of 20 mCi 99mTc pyrophosphate for gated blood pool study. Caused by inadequate patient identification. Physician name deleted.
SULLIVAN, J.L. Vet. Admin. Medical Center Madison, WI. 81/09/18. Region 3, Chicago, Office of the Director (81/03/01). 2pp. 17693:307.

--8303240253 "Misadministrations for WI From 820101 to Present," computer printout.
* NRC - No Detailed Affiliation Given. 83/02/04. 1p. 17693:327.

8303300617 Final response to FOIA request for records re proposed rev of license fee schedules Forwards documents listed in App A Documents also available in PDR App B documents withheld (ref FOIA Exemption 5).
FELTON, J M Division of Rules and Records 83/02/28 KNOWLES, N J Shaw, Pittman, Potts & Trowbridge 4pp 17768 336

--8303300621 Submits revised vote on SECY-81-615 re proposed license fee schedule Dissenting views discussed
AHEARNE, J Commissioners 82/07/23 CHILK, S J Office of the Secretary of the Commission 2pp 17768 342

--8303300624 Requests that listed Commissioner Ahearne dissenting views be added to staff requirements memo for SECY-81-615 re license fees.
* Commissioners 82/09/24 NRC - No Detailed Affiliation Given 2pp 17768 344

--8303300629 Disapproves SECY-81-615 re proposed license fee schedule Appropriate motivation/incentives to staff should be established to perform expeditious & efficient reviews consistent w/NRC statutory responsibilities.
ROBERTS, T M Commissioners 82/09/09 CHILK, S J Office of the Secretary of the Commission 1p 17768 346

--8303300636 Approves SECY-81-615 re proposed license fee schedule as modified per Commissioner 820726 mods & Item A in Commissioner Ahearne 820723 memo
ASSELSTINE, J K Commissioners 82/08/20 CHILK, S J Office of the Secretary of the Commission 1p 17768 347

--8303300641 Submits info on allocated time expended by Ofc of Secretary in FY81 for review of license fees, in response to 811105 memo Summary of functional activities included.
CHILK, S J Office of the Secretary of the Commission 81/11/09
DONOGHUE, D J Office of Administration 2pp 17768 349

8303300645 FOIA request for SECY-83-004
MONAHAN, J Francis & McGinnis Associates 83/01/19 FELTON, J Division of Rules and Records 1p 17768 308

8303300647 Responds to FOIA request for SECY-83-004 Forwards document
FELTON, J M Division of Rules and Records 83/02/23 MONAHAN, J Francis & McGinnis Associates 1p 17768 309

--8303300652 SECY-83-004
Provides info paper on current status of NPRDS INPO new strategy of improving current failure reporting endorsed. Accurate assessment of effectiveness of INPO mgt of NPRDS not possible before end of 1983.
DIRCKS, W J Office of the Executive Director for Operations 83/01/04 26pp 17768 310

8303300659 Final response to FOIA request for documents re NRC 820521 closed briefing on design basis threat Forwards Documents 1-3 listed in app Releasable portions of meeting transcript available in PDR Document 4 released via FOIA-77-14 & 106.
FELTON, J M Division of Rules and Records 83/03/04 COCHRAN, T B Natural Resources Defense Council 2pp 17765 187

--8205240600 SECY-82-198
Informs Commission of NRC views concerning current design basis threats contained in 10CFR73 1(a), per 820422 request
DIRCKS, W J Office of the Executive Director for Operations 82/05/18 4pp 17765 190

--8205240601 Staff requirements memo requesting current views on appropriate kind & degree of threat & vulnerabilities to such threat Response to be submitted by 820513
CHILK, S J Office of the Secretary of the Commission 82/04/22
DIRCKS, W J Office of the Executive Director for Operations 1p 17765 194

--8303300688 Staff requirements memo re 820521 closed briefing on design basis threat Commission agreed that changes to current statements of design basis threat contained in 10CFR73 1(a) not warranted at this time.
CHILK, S J Office of the Secretary of the Commission M820521
82/05/27 DIRCKS, W J Office of the Executive Director for Operations 1p 17765 195

--8303300693 Staff requirements memo requesting clarification of meaning of "several" used in safeguards design basis threat of 10CFR73 1(a)(1) Response requested by 830115
CHILK, S J Office of the Secretary of the Commission 82/12/23
DIRCKS, W J Office of the Executive Director for Operations 1p 17765 196

8303300709 Responds to FOIA request for six listed comments of Chem-Nuclear Sys, Inc re proposed rules on low level waste disposal regulation & licensing requirements for land disposal of radwaste Documents available in PDR.
FELTON, J M Division of Rules and Records 83/03/03 PAY, D Affiliation Unknown 1p 17764 072

8303300715 FOIA request for six listed comments of Chem-Nuclear Sys, Inc re proposed rules on low level waste disposal regulation & licensing requirements for land disposal of radwaste
PAY, D Affiliation Unknown 83/02/14 Office of Administration 1p 17764 073

8303310066 FOIA request for license permit & file matls issued to Neutron Products, Inc to operate polymer processing plant in Dickerson, MD.
EASTER, L Calgon Corp 82/12/13 FELTON, J M Division of Rules and Records 1p 17796 073

8303310074 Partial response to FOIA request for license permit & file matls issued to Neutron Products, Inc to operate polymer processing plant in Dickerson, MD Forwards documents listed in App A Search for addl documents in progress.
FELTON, J M Division of Rules and Records 83/01/13 EASTER, L Calgon Corp 4pp 17796 074

--8303310078 Application for matl/byproduct license authorizing possession & use of 2,000,000 Ci Co-60 activation products formed in zirconium & stainless steel capsules during irradiation of cobalt.
RANSOHOFF, J A Neutron Products, Inc 99262 67/12/31 2pp 17796 078

--8303310081 Forwards "Byproduct Matl Safety Evaluation for Neutron Products, Inc Co-60 Storage Facility" & application for byproduct matl license Application not encl
RANSOHOFF, J A Neutron Products, Inc 67/12/19 Atomic Energy Commission 1p 17796 080

--8303310083 "Byproduct Matl Safety Evaluation for Neutron Products, Inc Co-60 Storage Facility."
* Neutron Products, Inc 67/12/31 69pp 17796 081

--8303310085 Forwards Suppl 1 to 671219 application for matl/byproduct license Suppl responds to AEC questions raised at 680202 meeting re application.
RANSOHOFF, J A Neutron Products, Inc 68/02/06 DAVIS, F Atomic Energy Commission 11pp 17796 150

--8303310088 Submits analysis of Neutron Products, Inc 2,000,000 Ci Co-60 storage, processing & irradiation facility Processing & storage pool, pilot plant process irradiation facility & irregular south cell described
DAVIS, F C Atomic Energy Commission 68/02/13 Atomic Energy Commission 6pp 17796 161

--8303310091 Trip rept of 680214 site visit re application for license for possession & storage of 2,000,000 Ci Co-60 Facility constructed according to application Discrepancies noted listed.
DAVIS, F C Atomic Energy Commission 68/02/14 Atomic Energy Commission 2pp 17796 167

--8303310094 Forwards Suppl 2 to 671219 application for matl/byproduct license Suppl responds to NRC questions raised at 680214 [illegible] insp
RANSOHOFF, J A Neutron Products, Inc 68/02/14 Atomic Energy Commission 6pp 17796 169

--8303310097 Matl/Byproduct License 19-12667-01 for Neutron Products, Inc, authorizing use of 2,000,000 Ci Co-60 in singly encapsulated sealed sources.
* Atomic Energy Commission 68/02/15 3pp 17796 175

--8303310099 Forwards radiation survey rept of pilot plant irradiator, per Item 15 of license.
HAIRSTON, J J Neutron Products, Inc 01424 68/03/11 Atomic Energy Commission 3pp 17796 178

--8303310102 Ack receipt of 680311 ltr & forwards Amend 1 to License 19-12667-01, deleting Condition 15 re radiation survey repts.
BUCHANAN, C R Atomic Energy Commission 68/04/19 HAIRSTON, J J Neutron Products, Inc 1p 17796 181

--8303310104 Amend 1 to Matl/Byproduct License 19-12667-01, deleting Condition 15.
BUCHANAN, C R Atomic Energy Commission 68/04/19 1p 17796 182

--9303310111 Amend 2 to Matl/Byproduct License 19-12667-01, authorizing use of ten sources Co-60, not to exceed 15 mCi in form of Mallinckrodt custom sources.
BUCHANAN, C. R. Atomic Energy Commission. 68/06/28. 1p.
17796:183.

--8303310116 Amend 3 to Matl/Byproduct License 19-12667-01, authorizing use of 10,000 Ci Co-60, not to exceed 5 Ci per source in sealed sources.
BUCHANAN, C. R. Atomic Energy Commission. 68/07/18. 1p.
17796:184.

--8303310119 Amend 4 to Matl/Byproduct License 19-12667-01, amending Subitem 9.A & Condition 14.
BUCHANAN, C. R. Atomic Energy Commission. 68/12/18. 1p.
17796:185.

--8303310128 Amend 5 to Matl/Byproduct License 19-12667-01, amending Condition 11 re supervision of licensed matl.
BUCHANAN, C. R. Atomic Energy Commission. 69/06/06. 1p.
17796:186.

--8303310131 Amend 6 to Matl/Byproduct License 19-12667-01, revising Subitem 9.A, defining use of matl & Condition 14.
BUCHANAN, C. R. Atomic Energy Commission. 69/08/13. 1p.
17796:187.

--8303310137 Amend 7 to Matl/Byproduct Licnese 19-12667-01, authorizing use of 50,000 Ci Co-60 in sealed sources.
BUCHANAN, C. R. Atomic Energy Commission. 69/12/15. 1p.
17796:188.

--8303310141 Amend 8 to Matl/Byproduct License 19-12667-01, revising Subitem 7A to allow possession & use of singly encapsulated sealed sources or other manufacturer doubly encapsulated sources.
BUCHANAN, C. R. Atomic Energy Commission. 70/01/19. 1p.
17796:189.

--8303310144 Amend 9 to Matl/Byproduct License 19-12667-01, revising Subitem 9.A re use of matl & Conditions 11 & 14.
BUCHANAN, C. R. Atomic Energy Commission. 70/02/05. 1p.
17796:190.

--8303310150 Amend 10 to Matl/Byproduct License 19-12667-01, revising amount of matl authorized to 3,000,000 Ci & specifying conditions re supervision of matl.
BUCHANAN, C. R. Atomic Energy Commission. 70/03/27. 1p.
17796:191.

--8303310154 Amend 11 to Matl/Byproduct License 19-12667-01, revising use & supervision of matl.
MALARO, J. C. Atomic Energy Commission. 70/10/16. 1p. 17796:192.

--8303310157 Amend 12 to Matl/Byproduct License 19-12667-01, revising Condition 14 re possession & use of licensed matl, per listed ltrs & applications.
MALARO, J. C. Atomic Energy Commission. 70/11/19. 1p. 17796:193.

--8303310175 Application for Amend 2 to Matl/Byproduct License 19-12667-01, authorizing use of 150 mCi Co-60 in form of needles contained in Mallinckrodt lead.
MORELAND, R. E. Neutron Products, Inc. 03188. 68/06/05. Atomic Energy Commission. 2pp. 17796:194.

--8303310204 Forwards description of single encapsulated source & 680625 procedure for second encapsulation, per telcon. Second encapsulation not provided due to varying needs of customers.
TURKANIS, M. M. Neutron Products, Inc. 1847. 68/07/15. DAVIS, F. Atomic Energy Commission. 7pp. 17796:196.

--8303310208 Application for Amend 3 to Matl/Byproduct License 19-12667-01, authorizing use of 5 Ci Co-60 in licensed calibr sources & 10,000 Ci in licensed sealed sources.
MORELAND, R. E. Neutron Products, Inc. 04060. 68/07/16. Atomic Energy Commission. 1p. 17796:203.

--8303310214 Advises of leak & contamination test procedures to verify integrity of double encapsulated Co-60 sources, per telcon & supplement to M Turkanis 680715 ltr. Procedures will be followed w/all customers possessing encapsulated sources.
RANSOHOFF, J. A. Neutron Products, Inc. 2019. 68/08/07. DAVIS, F. Atomic Energy Commission. 2pp. 17796:204.

--8303310220 Revises 680807 leak & contamination procedures for double encapsulations, per 680815 telcon. Water bath leak test described.
MORELAND, R. E. Neutron Products, Inc. 68/08/16. DAVIS, F. Atomic Energy Commission. 1p. 17796:206.

--8303310223 Ack receipt of 680715, 0807 & 0816 ltrs, clarifying Tech Specs for single encapsulated sources & testing procedures for proposed double encapsulations.
DAVIS, F. Atomic Energy Commission. 68/08/21. RANSOHOFF, J. A. Neutron Products, Inc. 1p. 17796:207.

--8303310227 Application to amend License 08-12332-01, increasing max limit Co-60 shipped in Mode IV Cask to 120,000 Ci.
TURKANIS, M. M. Neutron Products, Inc. 05171. 68/08/20.
LINDBERG, B. D. Atomic Energy Commission. 2pp. 17796:208.

--8303310232 Reviews 680830 application to amend License 19-12667-02. Increase in max limit of Co-60 to 120,000 Ci recommended.
ODEGAARDEN, R. H. Atomic Energy Commission. 68/09/09. Atomic Energy Commission. 1p. 17796:210.

--8303310236 Forwards Byproduct/Matl License 19-12667-02, amending License 08-12323-01, per 680830 request. License 08-12332-01 terminated due to change of address.
CHITWOOD, R. B. Atomic Energy Commission. 68/09/10. TURKANIS, M. M. Neutron Products, Inc. 1p. 17796:211.

--8303310240 Matl/Byproduct License for Neutron Products, Inc, authorizing possession & transfer of 600,000 Ci Co-60.
CHITWOOD, R. B. Atomic Energy Commission. 68/09/10. 2pp.
17796:212.

--8303310249 Requests special authorization for shipment of Univ of MD gamma irradiator w/Co-60. Dose rate less than 200 manrem/hour at surface of cage. License 19-12667-01 authorizes possession of Co-60.
MORELAND, R. E. Neutron Products, Inc. 06792. 68/11/21.
LINDBERG, B. Atomic Energy Commission. 1p. 17796:214.

--8303310253 Application to amend Matl/Byproduct License 19-12667-01 to fuel & operate prototype packaged goods irradiator.
RANSOHOFF, J. A. Neutron Products, Inc. 06797. 68/11/26. 8pp.
17796:215.

--8303310257 Notifies that no action will be taken re 681121 request for authorization of shipment of Univ of MD gamma irradiator. Shipment under DOT regulations.
CHITWOOD, R. B. Atomic Energy Commission. 69/02/13. TURKANIS, M. Neutron Products, Inc. 1p. 17796:223.

--8303310260 Application to amend Matl/Byproduct License 19-12667-01, revising supervision of matl use.
MORELAND, R. E. Neutron Products, Inc. 18185. 69/05/14. Atomic Energy Commission. 3pp. 17796:224.

--8303310265 Forwards Drawing A-200006 "Clad Wire Source (Co-60)" & Drawing A-200007 "Double Encapsulated Source," per telcon request.
TURKANIS, M. M. Neutron Products, Inc. 69/05/23. DAVIS, F. Atomic Energy Commission. 5pp. 17796:227.

--8303310268 Revises 690523 ltr re drawing of double encapsulated sources. Referenced ltr should be dtd 680716, not 0715.
TURKANIS, M. M. Neutron Products, Inc. 69/07/03. DAVIS, F. Atomic Energy Commission. 1p. 17796:232.

--8303310275 Withdraws 690523 request that double encapsulated source be approved for sale. Cladding thickness re clad wire source discussed.
TURKANIS, M. M. Neutron Products, Inc. 69/07/02. DAVIS, F. Atomic Energy Commission. 2pp. 17796:233.

--8303310280 Application for Amend 6 to Matl/Byproduct License 19-12667-01, authorizing operation of hot cell for processing once encapsulated Co-60 sources. Design description encl.
RANSOHOFF, J. A. Neutron Products, Inc. 11295. 69/07/15. Atomic Energy Commission. 8pp. 17796:235.

--8303310285 Ack receipt of 690523 & 0603 ltrs describing Tech Specs & testing procedures for singly encapsulated, clad-wire coil source. Source acceptable for licensing.
DAVIS, F. C. Atomic Energy Commission. 69/08/25. TURKANIS, M. M. Neutron Products, Inc. 1p. 17796:243.

--8303310291 Application for Amend 7 to Matl/Byproduct License 19-12667-01, authorizing receipt, possession, storage & use of 50,000 Ci Co-60 in doubly encapsulated slugs.
ARROWSMITH, P. D. Neutron Products, Inc. 13429. 69/11/14.
Atomic Energy Commission. 4pp. 17796:244.

--8303310298 Application for Amend 8 to Matl/Byproduct License 19-12667-01, revising Item 7A re sealed sources & deleting Items D & E.
ARROWSMITH, P. D. Neutron Products, Inc. 14125. 70/01/06.
Atomic Energy Commission. 2pp. 17796:248.

--8303310304 Application for Amend 9 to Matl/Byproduct License 19-12667-01, authorizing use of hot cell for irradiating packaged matls.
RANSOHOFF, J. A. Neutron Products, Inc. 70/01/22 Atomic Energy Commission 3pp. 17796:250.

--8303310309 Application for Amend 10 to Matl/Byproduct License 19-12667-01, revising supervision & authorized users of licensed matl.
RANSOHOFF, J. A. Neutron Products, Inc. 14430 70/01/22 Atomic Energy Commission 6pp. 17796:253.

--8303310314 Application for Amend 11 to Matl/Byproduct License 19-12667-01, authorizing use of 3,000,000 Ci Co-60.
RANSOHOFF, J. A. Neutron Products, Inc. 15061 70/03/06 Atomic Energy Commission 1p. 17796:259.

--8303310319 Application for Amend 12 to Matl/Byproduct License 19-12667-01, revising supervision requirements & authorized users of licensed matl.
RANSOHOFF, J. A. Neutron Products, Inc. 15179 70/03/11 Atomic Energy Commission 3pp. 17796:260.

--8303310324 Application for Amend 13 to Matl/Byproduct License 19-12667-01, authorizing opening, reforming & re-encapsulation of singly encapsulated Co-60 sources in hot cell.
ZIEBOLD, T. O. Neutron Products, Inc. 17193 70/08/05 Atomic Energy Commission 2pp. 17796:263.

--8303310328 Requests addl info to support application to amend License 19-12667-01. Procedures for dumping liquid radwaste into canal, placement of emergency exhaust fan & replacing air filters required.
HENDRIX, G. W. Atomic Energy Commission 17193 70/09/01
ZIEBOLD, T. O. Neutron Products, Inc. 2pp. 17796:265.

--8303310331 Responds to NRC 700901 request for addl info re 700605 application to amend License 19-12667-01. Procedure for hot cell entry after operations involving exposed cobalt & DG Woodward & TO Ziebold resumes encl.
ZIEBOLD, T. O. Neutron Products, Inc. 2062 70/09/15
HENDRIX, G. W. Atomic Energy Commission 14pp. 17796:267.

--8303310338 Responds to GW Hendrix questions during 700929 visit to facilities re 700805 application to amend License 19-12667-01. Authorization to reprocess cobalt sources requested.
ZIEBOLD, T. O. Neutron Products, Inc. 2221 70/10/01
HENDRIX, G. W. Atomic Energy Commission 5pp. 17796:281.

--8303310342 Application to amend Matl/Byproduct License 19-12667-01, designating TO Ziebold as radiation protection officer.
RANSOHOFF, J. A. Neutron Products, Inc. 18665 70/11/13
HENDRIX, G. W. Atomic Energy Commission 3pp. 17796:286.

--8303310347 Application to amend Matl/Byproduct License 19-12667-02 to permit shipment of Cs-137 sources. Six drawings of 670725 mod to existing facility encl.
ZIEBOLD, T. O. Neutron Products, Inc. 18223 70/12/17
STEVENSON, R. Atomic Energy Commission 8pp. 17796:289.

8303310450 FOIA request for six categories of documents. Waiver of 75% of fees requested.
HIATT, S. L. Ohio Citizens for Responsible Energy 83/02/14
FELTON, J. M. Division of Rules and Records 1p. 17804:131.

8303310453 Partial response to FOIA request for six categories of documents. Forwards App A documents identified as Items 1, 3, 4, 5 & 6 of request. Search for documents re Item 2 of request continuing.
FELTON, J. M. Division of Rules and Records 83/02/24 HIATT, S. L. Ohio Citizens for Responsible Energy 2pp. 17804:132 24X Fiche: 50-000, 83/02/24, 8303310453.

--8303310463 Advises that Commission has approved SECY-82-407, recommending implementation of TMI Action Plan Item II.F.2 (NUREG-0737) re addl instrumentation for detection of inadequate core cooling.
CHILK, S. J. Office of the Secretary of the Commission 82/11/04
DIRCKS, W. J. Office of the Executive Director for Operations 1p. 17804:134.

## GEN TEC IS GENERIC TECHNICAL ISSUES

8212290096 Submits summary of significant points discussed re pressurized thermal shock. SECY-82-465 Recommends Commission follow interim screening criteria for both longitudinal & circumferential welds.
BASDEKAS, D. L. Instrumentation & Control Branch 82/12/03
GILINSKY, V. Commissioners 5pp. 17677:103.

--8212290099 Forwards comments on draft rept on pressurized thermal shock dtd 820913.
BASDEKAS, D. L. Instrumentation & Control Branch 82/10/06
SHEWMON, P. S. ACRS - Advisory Committee on Reactor Safeguards 1p. 17677:113.

--8211010425 Comments on NRC 820913 draft rept on pressurized thermal shock, per 820915 request. Suggests content expansion, integrity (citing specific refs) & semantic changes.
BASDEKAS, D. L. Instrumentation & Control Branch 82/09/24
JOHNSON, C. E. Division of Risk Analysis 5pp. 17677:114.

8301060379 Provides comments on Generic Technical Issues 49 re pressurized thermal shock & 47 re safety implications of control sys per 821209 request. Plant design info at least for Oconee 1 required to resolve Issue A-49.
BASDEKAS, D. L. NRC - No Detailed Affiliation Given 82/12/14
GILINSKY, V. Commissioners 1p. 17677:101.

8302080455 Trip rept of attendance at EPRI pressurized thermal shock program & thermal mixing technology 821007-08 workshop at CREARE in Hanover, NH.
CATTON, I. ACRS - Advisory Committee on Reactor Safeguards 82/10/25 IGNE, I. ACRS - Advisory Committee on Reactor Safeguards 3pp. 17107:342.

8303020178 Notification of CRGR 830309 Meeting 33 in Bethesda, MD to discuss proposed rule 10CFR53 & findings re resolution of Unresolved Safety Issue A-1, "Water Hammer."
STELLO, V. Committee to Review Generic Requirements 83/02/25
EISENHUT, D. G. Office of Nuclear Reactor Regulation, Director
JORDAN, E. L. Director's Office, Office of Inspection and Enforcement
CUNNINGHAM, R. E. Office of Nuclear Material Safety & Safeguards, Director 201pp. 17358:294.

8303240109 Advises that CRGR concurs w/planned actions described in encl 830228 memo re Unresolved Issue A-43, "Containment Emergency Sump Performance." Package issued for public comment should include listed items.
STELLO, V. Regional Operations & Generic Requirements 83/03/16
DENTON, H. Office of Nuclear Reactor Regulation, Director 1p. 17693:334.

8303300221 Forwards high & low pressure basic versions of FR-P.1, "Response to Imminent Pressurized Thermal Shock Condition" & FR-P.2, "Response to Anticipated Pressurized Thermal Shock Condition."
SHEPPARD, J. J. Westinghouse Operating Plants Owners Group
SHEPPARD, J. J. Carolina Power & Light Co. OG-91 83/03/14
EISENHUT, D. G. Division of Licensing 2pp. 17735:162.

--8303300229 "Response to Imminent Pressurized Thermal Shock Condition," w/background info.
* Westinghouse Electric Corp. 82/12/01 52pp. 17735:164.

--8303300237 "Response to Anticipated Pressurized Thermal Shock Condition," w/background info.
* Westinghouse Electric Corp. 82/12/01 14pp. 17735:216.

--8303300244 "Response to Imminent Pressurized Thermal Shock Condition," w/background info.
* Westinghouse Electric Corp. 82/12/01 52pp. 17735:230.

--8303300252 "Response to Anticipated Pressurized Thermal Shock Condition," w/background info.
* Westinghouse Electric Corp. 82/12/02 14pp. 17735:282.

## I&E INSPECTION AND ENFORCEMENT

8212060367 IE Bulletin 83-01, "Failure of Reactor Trip Breakers (Westinghouse DB-50) to Open on Automatic Trip Signal." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/02/25 Consolidated Edison Co. of New York, Inc. 11pp. 17521:001 24X Fiche: 50-000, 83/02/25, 8212060367.

8212060380 IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers." Svc list encl.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 83/03/11 Consolidated Edison Co. of New York, Inc. 11pp. 17611:070 24X Fiche: 50-000, 83/03/11, 8212060380.

8212060383 IE Info Notice 83-12, "Incorrect Boron Stds." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/03/18 Consolidated Edison Co. of New York, Inc. 11pp. 24X Fiche: 50-000, 83/03/18, 8212060383.

8212060387 IE Info Notice 83-13: "Design Misapplication of Bergen-Paterson Std Strut Restraint Clamp." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/21
Consolidated Edison Co. of New York, Inc. 12lpp. 17774:352 24X Fiche 50-000, 83/03/21, 8212060387

8303030601 PNO-IV-83-005: on 830124, 10 mCi Cs-137 sealed source in shielded shipping container en route to Scotland via Dallas, TX not yet received. Efforts continuing to locate package.
EVERETT, R. J. Region 4, Office of Director 83/02/17 1p
17409:308

8303040455 PNO-I-83-013: on 830223, facility damaged by fire, resulting from dust explosion in potato fiber handling area. Two Kay Ray, Inc Model 7062 density/level gauges containing 50 mCi Ce-137 damaged. Kay Ray, Inc notified.
GLENN, J. Region 1, Office of Director 83/02/28 1p 17368:010

8303080390 PNO-I-83-014: on 830302, two 1.5 Ci Mo-99/Tc-99m generators found behind Philadelphia residence. Indicated surface readings less than 50 mR/hr. Generators stored in Misericordia Hosp for exam.
KINNEMAN, J. Region 1, Office of Director 83/03/02 1p
17494:274

8303080487 PNO-III-83-015: on 830210, Kay-Ray Model 7052 level indicator source holder containing 10 mCi CS-137 sealed source discovered missing. Notification made on 830228 that source & holder determined stolen. News release will be issued.
OBERG, C. T., WIEDEMAN, D. G. Region 3, Office of Director 83/03/01 1p 17452:327

8303100552 Responds to 830121 ltr re potentially faulty steel products which may have been suppl.ed to NRC licensees by Ray Miller, Inc. Specific corrective actions in answer to eight questions encl.
PALLADINO, N. J. Commissioners 83/03/02 OTTINGER, R. L. House of Rep., Energy & Commerce 14pp 17504:089

--8303100556 PNO-1E-83-002A: IE Notice 83-01 re fraudulent practices of Ray Miller, Inc distributed to regional ofcs on 830124. Two former employees will be interviewed 830125-26 to determine scope of fraudulent practices.
BAER, R. L., CUNNINGHAM, L. J. Director's Office, Office of Inspection and Enforcement 83/01/24 1p 17504:118

8303140629 Responds to 830128 ltr re fraudulent practices of Ray Miller, Inc. NRC actions taken & to be taken outlined. Action plans to deal w/potential safety concerns to be developed.
PALLADINO, N. J. Commissioners 83/03/01 MARKEY, E. J. House of Rep., Interior & Insular Affairs 6pp 17583:001

8303180507 PNO-V-83-011A: on 830313, improper operation of reactor trip breaker demonstrated. Possibly caused by resistance in mechanical latching mechanism associated w/undervoltage trip device. Similar failures in Mar & Jul 1982 not reported.
KIRSCH, D. F. Region 5, Office of Director 83/03/14 1p
17621:331

8303210378 PNO-III-83-017: on 830314, air terminal personnel at O'Hare Field found 100 mCi shipment of Xe-133 vials crushed. Since Xe-133 is noble gas & diffused into air, event not considered health hazard.
OBERG, C. T., WIEDEMAN, D. G. Region 3, Office of Director 83/03/14 1p 17634:178

8303210611 PNO-I-83-016: on 830314, transportation accident resulting in release of small amount of licensed radioactive matl (Tc 99m) occurred near Gettysburg, PA. Driver injured & taken to hosp. Vial placed in plastic bag & drum.
KINNEMAN, J. Region 1, Office of Director 83/03/14 1p
17636:287

8303210687 PNO-I-83-016A re 830314 transportation accident resulting in minor radioactive contamination. PA Bureau of Radiation Protection accounted for all packages containing radioactive matl. One package of Mo-99/Tc-99 damaged.
FRIEDMAN, L. F., GLENN, J. Region 1, Office of Director 83/03/15 1p 17635:212

8303220029 PNO-III-83-020: on 830317, radiation therapist received skin exposure of 400 rads in thigh area from Cs-137 sealed implant sources carried in labcoat for about 1 h. Film badges sent to supplier for processing. Evaluation in progress.
OBERG, C. T., LASUK, B. R., CREED, J. R. Region 3, Office of Director 83/03/18 2pp 17652:111

8303220235 PNO-III-83-018: on 830228, contractor employee gained unauthorized entry to protected & vital plant areas. Two contractor employees terminated for violating security requirements & security guard for failure to take action.
CREED, J. Region 3, Office of Director 83/03/16 1p 17656:260

8303230028 EN-83-013: on 830323, notice of violation & proposed imposition of civil penalty in amount of $2,000 to be issued. Action based on violation re unauthorized persons performing maint on teletherapy unit.
FLACK, E., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/03/18 1p 17645:039

8303230030 EN-83-014: on 830323, notice of violation & proposed imposition of civil penalties in amount of $4,000 will be issued based on licensee failure to adhere to full license conditions causing unmonitored inhalation exposure.
FLACK, E., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/03/18 1p 17663:246

8303240036 PNO-HQ-83-001: potential re-entry of Soviet nuclear-powered satellite (COSMOS 1402) monitored. Large satellite fragments which might threaten any licensed nuclear facility not expected during re-entry.
WEISS, B., PERKINS, K. Director's Office, Office of Inspection and Enforcement 83/01/07 1p 17681:024

8303240153 PNO-HQ-83-005: summarizes licensee repts of recent failures of GE AK-2 breakers submitted in response to IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers."
VILLAVALVA, LANIK Director's Office, Office of Inspection and Enforcement IEB-83-04 83/03/18 2pp 17681:033

8303240397 PNO-II-83-015: on 830319, train A breakers failed to open on actuation of undervoltage trip coil. On 830318, train B failed. Investigation continuing.
IGNATONIS, A. Region 2, Office of Director IEB-83-04 83/03/21 2pp 17678:361

8303240524 PNO-IV-83-010: on 830317, State of TX Bureau of Radiation Control notified that ORNL reported 8 to 20 max permissible lung burdens of Am-241 for two employees of Gulf Nuclear, Inc arising from 830208 incident. Investigation continuing.
DODA, R. J. Region 4, Office of Director 83/03/18 1p 17682:281

8303280043 EN-83-019: on 830329, notice of violation & proposed imposition of civil penalty in amount of $140,000 to be issued. Action based on failure to maintain mgt attention at level necessary to assure adherence to plant procedures.
FLACK, E. Director's Office, Office of Inspection and Enforcement 83/03/24 1p 17707:313

8303280125 PNA 83-005B: on 830310, Auburn Steel Co informed EPA of Co-60 contamination of metals production facility. Caused by receipt of scrap metal from sources in US & Canada. NY State Police investigation of scrap shipment records continuing.
CAMPBELL, M. Region 1, Office of Director LUBENAU, J. O. Office of State Programs, Director 83/03/10 3pp 17713:319

8303280313 Forwards four notices of nonroutine events involving Agreement State or agreement matls issued in 1983.
NUSSBAUMER, D. A. Office of State Programs, Director 83/03/15
SALTZMAN, J. Office of State Programs, Director 2pp 17713:288

--8303280318 PNA 83-006: on 830228, Suffolk County Dept of Health informed Region I of indications of buried radioactive matls at formerly licensed site in Bellport, NY. Measurements continuing.
CAMPBELL, M. Region 1, Office of Director 83/03/15 1p
17713:290

--8303280326 PNA 83-005A: on 830222, Auburn Steel Co informed Region I of discovery that steel reinforcement rods mfg on 830221 were contaminated w/radioactive matl. Investigation continuing.
CAMPBELL, M. Region 1, Office of Director 83/03/03 1p
17713:293

--8303280330 PNA 83-005: on 830221, during preparation of steel scrap for reinforcement rod mfg by Auburn Steel Co, level gauge indicated high radiation coming from rods. Facility shut down. Investigation continuing.
CAMPBELL, M. Region 1, Office of Director 83/02/23 1p
17713:294

--8303280335 PNA 83-004: on 830126, package received at temporary job site containing 200 Ci Ir-192 in radiography device surface radiation measured in excess of DOT limits. Investigation of shipment continuing.
CAMPBELL, M. A. Region 1, Office of Director 83/01/27 1p
17713:295

--8303280340 PNA 83-002: on 830107, Region III issued press release re company identified by NY Dept of Health which imported cloisonne jewelry containing U glaze. Release urges that unnecessary exposure to jewelry be minimized.
CAMPBELL, M. Region 1, Office of Director 83/03/15 1p
17713:296

8303300268 PNO-V-83-015: during period 830215-0315, radiographer received radiation dose of approx 7 rem. Exposure measured by film badge & processed at Naval Hosp, Bethesda, MD. Licensee investigating incident.
THOMAS, R. D. ; ZURAKOWSKI Region 5, Office of Director 83/03/24
1p 17733.024

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

8212220501 Forwards "Rept on Medical Misadministrations for Jan 1981 - June 1982."
MICHELSON, C. A. Director's Office AEOD/N2048 82/12/09
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 1p 17425.006

--8212220495 "Rept on Medical Misadministrations for Jan 1981 - June 1982."
PETTIJOHN, S. L. Director's Office AEOD/N2048 82/11/30 20pp
17425.007

8303010287 Procedure 81-JPGC-PWR-31, "Procedures for Estimating Probability of Steam Turbine Disc Rupture From Stress Corrosion Cracking."
CLARK, W. G. ; SETH, B. B. ; SHAFFER, D. H. American Society of Mechanical Engineers 83/03/01 29pp 17335.200

--8303010294 Speech entitled "Turbine Missile Risk Methodology & Computer Code," presented at EPRI 821025-26 seminar in Palo Alto, CA. Viewgraphs encl.
TWISDALE, L. A. ; DUNN, W. L. ; FRANK, R. A. Research Triangle Institute 82/10/25 16pp 17335.229

--8303010300 Speech entitled, "Concrete Impact Prediction Techniques," presented at EPRI 821025-26 seminar in Palo Alto, CA. Viewgraphs encl.
TWISDALE, L. A. ; FRANK, R. A. Research Triangle Institute 82/10/25 24pp 17335.245

8303030520 Confirms telcon during wk of 830110 re guidance on electronic component traceability. NRC concurrence that implementation of subj guidance satisfies traceability requirements of IEEE-323-1974 requested.
SANDERS, M. K. Rockwell International Corp 83ESG-1277 83/02/24
NOONAN, V. Equipment Qualification Branch 3pp 17409.056

8303100008 Notification of 830301 meeting w/Nuclear Util Fire Group in Bethesda, MD to discuss differences between NRC & licensee interpretations of App R to 10CFR50.
WAMBACH, T. V. Operating Reactors Branch 5 83/02/22 CRUTCHFIELD, D. Operating Reactors Branch 5 2pp 17493.191

8303100137 Speech entitled, "NRC Program for Insp & Enforcement of Nuclear Transportation," to be presented at ANS 830612-16 meeting on radiation protection & shielding.
GRELLA, A. W. Director's Office, Office of Inspection and Enforcement 83/03/02 3pp 17496.141

8303100152 Speech entitled "Effect of Tornado on Nuclear Power Plant Structures," to be presented at 830822-26 ASME Conference on Structural Mechanics in Reactor Technology in Chicago, IL.
PERSINKO, D. Office of Nuclear Reactor Regulation, Director 83/03/02 11pp 17496.018

8303100413 Comments on proposed policy re license QA program certification. Functions generated from study will help eradicate misconception that CP & OL QA plans be considered separately.
STEFANO, J. J. Licensing Branch 1 83/02/18 YOUNGBLOOD, B. J. Licensing Branch 1 NOVAK, T. M. Assistant Director for Licensing
WILLIAMS, M. A. Division of Licensing 3pp 17502.360

8303140590 Forwards translations of German papers, "Secondary Emissions of Light Water Pressure Reactors During Normal Operation & Selected Accidents" & "Secondary Loop Emissions of Light Water Pressure..." for placement in PDR.
HULMAN, L. G. Accident Evaluation Branch 83/03/01 SCATTOLINI, L. Public Document Branch 1p 17572.008

--8303140599 "Secondary Loop Emissions of Light Water Pressure Reactors During Normal Operation & Selected Accidents."
* Reactor Safety Co. (Germany GRS) 82/04/23 7pp 17572.009

--8303140606 "Secondary Emissions of Light Water Pressure Reactors During Normal Operation & Selected Accidents."
* Heidelberg Institute for Energy & Environmental Research 83/03/01 196pp 17572.016

8303210014 Requests that all FY82 contracts be modified to include requirement to provide microfiche of repts directly to NMSS. Listed contracts should be amended to include HJ Miller on rept distribution. Microform specs encl.
MARTIN, J. B. Division of Waste Management FIN B-3109 82/02/16
BROWN, R. S. Program Support Branch 3pp 17659.148

8303220482 Summarizes status of Multi-Plant Issue B-24 for selected PWRs & BWRs.
HULMAN, L. G. Accident Evaluation Branch 83/03/10 VARGA, S. A. Operating Reactors Branch 1 2pp 17670.284

8303230385 "Review of Draft Rept ONWI-36, Summary Characterization & Recommendation of Study Areas for Paradox Basin Study Region." Microfiche encl.
* Zytron 83/03/22 6pp 17683.220

8303240201 Forwards Endorsement 101 to NELIA Policy NF-14.
ASHBURN, D. J. Marsh & McLennan, Inc 83/03/18 SALTZMAN, J. Assistant Director for State & Licensee Relations 2pp 17681.022

8303240558 Forwards title page, preface, abstract & table of contents to "Correlation of Methodologies for Seismic Qualification Tests of Nuclear Plant Equipment" submitted as draft Task 2 summary rept for Quarterly Rept 7 for 821201-830228.
KANA, D. D. Southwest Research Institute NRC-04-81-185 83/03/14
CAMBELL, W. E. Office of Nuclear Regulatory Research, Director 6pp
17683.214

8303250046 Advises that Action Item Tracking Sys F02700196, "Maint & Test Equipment for Safety-Related Applications," closed w/o action. Vendor deficiency not indicated.
POTAPOVS, U. Division of Vendor & Technical Programs 83/03/17
LEWIS, R. C. Division of Project & Resident Programs 1p 17710.001

8303310519 Forwards notice of proposed rulemaking (Task TM 123-1) to require reporting of all licensed matl lost, stolen or missing for more than 30 days. W/o encl.
MINOGUE, R. B. Office of Nuclear Regulatory Research, Director 83/03/24 SIMPSON, A. Senate, Environment & Public Works 2pp
17801.110

NUREG NUREG REPORTS AND RELATED CORRESPONDENCE

8303010254 Forwards BWR Owners Group technical advisory committee recommendations re updating NUREG-0313, Rev 1, per NRC 821227 ltr. Application of hydrogen water chemistry should be accepted as alternative to inservice insp.
HOFFMAN, J. R. ; DEBARBA, E. Electric Power Research Institute
HOFFMAN, J. R. Yankee Atomic Electric Co. 83/02/16 HAZELTON, W. S. NRC - No Detailed Affiliation Given 3pp 17335.143

8303020095 Comments on draft NUREG-0933, "Prioritization of Generic Safety Issues." Combination of accident frequency estimates & accident consequence estimates used by NRC may be several orders of magnitude too high.
BRADBURY, R. B. Stone & Webster Engineering Corp 47FR57595 002
83/02/17 Docketing & Services Branch 3pp 17349.006

8303020204 Transcript of 830125 peer review meeting on draft NUREG-0956 re PWR analysis in Washington, DC. Pp 1-226.
* Commissioners 83/01/25 226pp 17358.016

8303020266 NUREG/CR-2703
INVESTIGATION OF SPECIAL PURPOSE PROCESSORS FOR REAL-TIME SYNTHETIC APERTURE FOCUSING TECHNIQUES FOR NONDESTRUCTIVE EVALUATION OF NUCLEAR REACTOR VESSELS AND PIPING COMPONENTS.
GANAPATHY, S. ; SCHMULT, B. ; WU, W. S. Michigan, Univ. of FIN A-4047
83/01/31 Materials Engineering Branch 87pp 17355.150

8303030784 Transcript of 830126 peer review meeting in Washington, DC re draft NUREG-0956, Vol 1 PWR analysis. Pp 227-416.
* Commissioners 83/01/26 192pp 17363.028

8303040191 Forwards comments on GAO recommendations in 821215 rept, "Problems & Delays Overshadow NRC Initial Success in Improving Reactor Operator Capabilities." Development activities being reviewed to ensure improvement.
PALLADINO, N. J. Commissioners 83/02/10 ROTH, W. V. Senate, Governmental Affairs 6pp 17427.010

8303040354 Discusses development of Westinghouse Owners Group response guidelines addressing NUREG-0737, Item II.K.2.17, "Potential Voiding in RCS." Natural circulation cooldown guidance will be utilized in plant emergency operating procedures.
MUENCH, R. A. Westinghouse Electric Corp. NSID/WOG-63 83/02/16
EISENHUT, D. G. Division of Licensing 2pp 17420.021

8303090163 FOIA request for recently issued risk policy
LEE,D.E. Affiliation Unknown 83/01/14 FELTON,J.M. Division of Rules and Records 1p 17465:066

8303090187 Responds to FOIA request for recently issued risk policy. Forwards NUREG-0880, "Safety Goals for Nuclear Power Plants Discussion Paper," & JE Zerbe 830111 memo re safety goal policy statement.
FELTON,J.M. Division of Rules and Records 83/02/04 LEE,D.E. Affiliation Unknown 1p 17465:067

--8303090193 Forwards policy statement on safety goals for operation of nuclear power plants, revised at Commission 830110 meeting. Final revs indicated on 830107 marked-up draft.
ZERBE,J.E. Office of Policy Evaluations 83/01/11
PALLADINO,N.J.; GILINSKY,V.; AHEARNE,J.F. Commissioners 28pp 17465:140

8303090213 Forwards safety evaluation supporting NEDE-22178-(P), "Mark II Containment Drywell-to Wetwell Vacuum Breaker Models," Rept acceptable for referencing in licensing applications.
THOMAS,C.O. Standardization & Special Projects Branch 83/02/24
SHERWOOD,G.G. General Electric Co 2pp 17484:196

8303090413 FOIA request for D Eisenhut 820219 memo re OL rule for NUREG-0737 requirements.
GRABER,L. Affiliation Unknown 83/01/28 Division of Rules and Records 1p 17477:070

8303090415 Responds to FOIA request for D Eisenhut 820219 memo re OL rule for NUREG-0737 requirements. Forwards requested memo. Document available in PDR.
FELTON,J.M. Division of Rules and Records 83/02/17 GRABER,L. Affiliation Unknown 1p 17477:071

--8203150315 Forwards final rule for OL applicants re NUREG-0737 Comments required by 820225.
EISENHUT,D.G. Division of Licensing 82/02/19 MATTSON,R.J. Division of Systems Integration (post 811005) HANAUER,S.H. Division of Safety Technology VOLLMER,R.H. Division of Engineering 40pp 17477:072

8303090505 NUREG-0845
AGENCY PROCEDURES FOR THE NRC INCIDENT RESPONSE PLAN
WEINSTEIN,E. Incident Response & Development Branch 83/02/28
296pp Available at NRC $8.50 17475:189

8303090510 NUREG/CR-2952
ENGINEERING EXPERTISE ON SHIFT IN NUCLEAR POWER PLANTS THE FOREIGN EXPERIENCE.
MELBER,B.D.; SCHREIBER,R.E. Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2360 83/02/28 Division of Human Factors Safety 21pp Available at NRC $4.50 17476:125

8303090520 NUREG/CR-2443
A MANUAL FOR USING ENERGY ANALYSIS FOR PLANT SITING.
ODUM,H.T.; LAVINE,M.J.; WANG,R.C. Florida, Univ. of, Gainesville FIN B-6155 83/02/28 Division of Health, Siting & Waste Management 242pp Available at NRC $7.50 17476:161

8303090659 NUREG/CR-2401
PWR FLECHT SEASET SYSTEMS EFFECTS NATURAL CIRCULATION AND REFLUX CONDENSATION Task Plan Report NRC/EPRI/Westinghouse Report No. 12
ROSAL,E.R.; HOCHREITER,L.E.; ANDREYCHEK,T.S. Westinghouse Electric Corp FIN B-6204 WCAP-9973 83/02/28 Division of Accident Evaluation 413pp 17481:252

8303090715 NUREG-0963
REVIEW AND EVALUATION OF THE NUCLEAR REGULATORY COMMISSION SAFETY RESEARCH PROGRAM FOR FISCAL YEARS 1984 AND 1985
* ACRS - Advisory Committee on Reactor Safeguards 83/02/28 86PP 17477:282

8303100416 NUREG/CR-2935
EXAMPLES OF MC&A SYSTEMS TO MEET PROMPT ACCOUNTABILITY SPECIFICATIONS.
EGGERS,R.F.; BROUNS,R.J.; BRYANT,J.L. Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2134 PNL-4336 83/01/31 Division of Facility Operations 294pp Available at NRC $8.50 17498:094

8303100421 NUREG/CR-2929
FEASIBILITY OF MONITORING THE STRENGTH OF HTGR CORE SUPPORT GRAPHITE--PART III.
MORGAN,W.C.; DAVIS,T.J.; THOMAS,M.T. Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2101-2 PNL-4449 83/02/28 Division of Accident Evaluation 49pp Available at NRC $4.75 17503:347

8303100424 NUREG/CR-3120
QUALITY ASSURANCE FOR MEASUREMENTS OF IONIZING RADIATION. Annual Report For FY 1982.
EISENHOWER,E.H.; EHRLICH,M.; SOARES,C. Commerce, Dept. of, National Bureau of Standards FIN B-7259 83/02/28 Division of Health, Siting & Waste Management 73pp Available at NRC $5.00 17503:178

8303100427 NUREG-0430 V03 N01
LICENSED FUEL FACILITY STATUS REPORT Inventory Difference Data January 1982 - June 1982.
* Director's Office, Office of Inspection and Enforcement 83/02/28 14pp 17503:332

8303100429 NUREG-0907
ACCEPTANCE CRITERIA FOR DETERMINING ARMED RESPONSE FORCE SIZE AT NUCLEAR POWER PLANTS
* Power Reactor Safeguards Licensing Branch 83/02/28 14pp Available at NRC $3.25 17503:317

8303100432 NUREG-0485 V05 N01
SYSTEMATIC EVALUATION PROGRAM STATUS SUMMARY REPORT Data As Of January 31, 1983. (Buff Book)
* Office of Resource Management, Director 83/02/28 64PP 17503:252

8303100433 NUREG/CR-2000 V02 N1
LICENSEE EVENT REPORT (LER) COMPILATION For Month Of January 1983.
* Oak Ridge National Laboratory FIN B-1583 ORNL/NSIC-200 83/02/28 Director's Office 118pp 17496:305

8303100443 NUREG/CR-2891
PERFORMANCE TESTING OF PERSONNEL DOSIMETRY SERVICES Final Report Of Test 3
PLATO,P.; MIKLOS,J. Michigan, Univ. of FIN B-1049 83/02/28 Division of Facility Operations 175pp Available at NRC $6.50 17497:063

8303100446 NUREG-0540 V04 N11
TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE November 1-30, 1982
* Division of Technical Information & Document Control 83/02/28 671pp 17499:028

8303100453 NUREG/CR-2892
PERFORMANCE TESTING OF PERSONNEL DOSIMETRY SERVICES A Revised Procedures Manual.
MIKLOS,J.; PLATO,P. Michigan, Univ. of, Medical School FIN B-1049 83/02/28 Division of Facility Operations 216pp Available at NRC $7.50 17497:238

8303100460 NUREG/CR-3069 V02
INTERACTION OF ELECTROMAGNETIC PULSE WITH COMMERCIAL NUCLEAR POWER PLANT SYSTEMS Main Report.
ERICSON,D.M. Sandia Laboratories STRAWE,D.F.; SANDBERG,S.J. Boeing Co. FIN A-1118 SAND82-2738/2 83/02/28 Division of Systems Integration (post 811005) 421pp Available at NRC $11.00 17501:149

8303100558 NUREG/CR-3069 V01
INTERACTION OF ELECTROMAGNETIC PULSE WITH COMMERCIAL NUCLEAR POWER PLANT SYSTEMS Executive Summary.
ERICSON,D.M. Sandia Laboratories STRAWE,D.F.; SANDBERG,S.J. Boeing Co. FIN A-1118 SAND82-2738/1 83/02/28 Division of Systems Integration (post 811005) 26pp Available at NRC $4.75 17500:339

8303100564 NUREG/CR-3109
SEISMICITY AND TECTONIC RELATIONSHIPS OF THE NEMAHA UPLIFT IN OKLAHOMA-Final Report.
LUZA,K.V.; LAWSON,J.E. Oklahoma, Univ. of FIN B-5967 83/02/28 Division of Health, Siting & Waste Management 67pp Available at NRC $5.50 17501:021

8303110129 NUREG-0800 ERR
STANDARD REVIEW PLAN Revision 5 To Section 6.2.1.1.C & Revision 2 To Appendix A To 6.2.1.1.C.
* Office of Nuclear Reactor Regulation, Director 83/01/31 24pp 17526:056

8303110137 NUREG-0566 V02 N04
STANDARDS DEVELOPMENT STATUS SUMMARY REPORT Data As Of December 31, 1982. (Green Book)
* Management Information Branch 83/02/28 188pp 17524:178

8303110145 NUREG-0020 V06 N10
LICENSED OPERATING REACTORS STATUS SUMMARY REPORT Data As Of September 30, 1982. (Grey Book)
* Management Information Branch 83/02/28 410pp 17525:006

8303140020 Forwards draft "Listing of All New Generic Issues, Task Action Plan Items & TMI Action Plan Items" & draft, "Prioritization of Non-NRR TMI Action Plan Items " ACRS can comment.
DENTON, H R. Office of Nuclear Reactor Regulation, Director 83/03/07. FRALEY, R F. ACRS - Advisory Committee on Reactor Safeguards 152pp. 17548:069

8303140617 NUREG/CR-2821
EBR-II IN-VESSEL NATURAL-CIRCULATION ANALYSIS.
BAUMANN, W L ., DOMANUS, H M ., MOHR, D. Argonne National Laboratory FIN A-2045. ANL-82-66. 83/01/31. Division of Accident Evaluation. 87pp. 17382:257.

8303140622 NUREG/CR-2824 V02
EDDY-CURRENT INSPECTION FOR STEAM GENERATOR TUBING PROGRAM. Quarterly Progress Report For Period Ending June 30, 1982.
DODD, C V ., DEEDS, W E ., MCCLUNG, R W. Oak Ridge National Laboratory FIN B-0417. ORNL/TM-8418/V2. 83/02/28. NRC - No Detailed Affiliation Given. 10pp. 17548:313.

8303140628 NUREG/CR-3103
PREDICTOR DISPLAY CONCEPTS FOR USE IN NUCLEAR PLANT CONTROL.
VENHUIZEN, J R ., GRIFFITH, J M. EG&G, Inc. FIN A-6308. EGG-2235. 83/02/28. Division of Facility Operations. 19pp. 17576:080.

8303140630 NUREG/CR-2998
A COMPARISON OF BWR STABILITY MEASUREMENTS WITH CALCULATIONS USING THE CODE LAPUR-IV.
MARCH-LEUBA, J ., OTADUY, P J. Oak Ridge National Laboratory. FIN B-0759. ORNL/TM-8546. 83/02/28. Division of Systems Integration (post 811005). 42pp. 17569:308.

8303140681 NUREG/BR-0051 V04 N5
POWER REACTOR EVENTS, July-August 1982.
MASSARO, S A. Director's Office. 83/02/28. 23pp. 17582:150.

8303140686 NUREG-0748 V03 N01
OPERATING REACTORS LICENSING ACTIONS SUMMARY Data As Of January 31, 1983 (Orange Book)
* Management Information Branch. 83/02/28. 293pp. 17581:217.

8303140690 NUREG-0383 V03 R02
DIRECTORY OF CERTIFICATES OF COMPLIANCE FOR RADIOACTIVE MATERIALS PACKAGES Summary Report Of NRC Approved Quality Assurance Programs For Radioactive Material Packages.
* Division of Fuel Cycle & Material Safety. 83/01/31. 74pp. Available at NRC. $6.00. 17581:075.

8303140696 NUREG/CR-2659
IODINE TRANSPORT PREDICTED FOR A POSTULATED STEAM LINE BREAK WITH CONCURRENT RUPTURES OF STEAM GENERATOR TUBES.
POSTMA, A K ., HESSON, G M ., FALETTI, D W. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2314. PNL-3794. 83/02/28. Division of Systems Integration (post 811005). 36pp. Available at NRC. $5.00. 17582:197.

8303140698 NUREG-0606 V05 N01
UNRESOLVED SAFETY ISSUES SUMMARY Data As Of February 18, 1983 (Aqua Book)
* Management Information Branch. 83/02/28. 49pp. 17569:257.

8303140701 NUREG-0383 V02 R05
DIRECTORY OF CERTIFICATES OF COMPLIANCE FOR RADIOACTIVE MATERIALS PACKAGES Certificates of Compliance.
* Division of Fuel Cycle & Material Safety. 83/01/31. 611pp. Available at NRC. $12.00. 17579:184.

8303140704 NUREG-0383 V01 R05
DIRECTORY OF CERTIFICATES OF COMPLIANCE FOR RADIOACTIVE MATERIALS PACKAGES Summary Report Of NRC Approved Packages.
* Division of Fuel Cycle & Material Safety. 83/01/31. 404pp. Available at NRC. $9.50. 17578:140.

8303140707 NUREG/CP-0027 V01
PROCEEDINGS OF THE INTERNATIONAL MEETING ON THERMAL NUCLEAR REACTOR SAFETY Held At Chicago, Illinois, August 29 - September 2, 1982.
* American Nuclear Society. 83/02/28. NRC - No Detailed Affiliation Given. 749pp. Available at NRC. $13.00. 17573:001.

8303140709 NUREG/CP-0027 V02
PROCEEDINGS OF THE INTERNATIONAL MEETING ON THERMAL NUCLEAR REACTOR SAFETY Held At Chicago, Illinois, August 29 - September 2, 1982.
* American Nuclear Society. 83/02/28. NRC - No Detailed Affiliation Given. 750pp. Available at NRC. $13.00. 17576:110.

8303140710 NUREG/CP-0027 V03
PROCEEDINGS OF THE INTERNATIONAL MEETING ON THERMAL NUCLEAR REACTOR SAFETY Held At Chicago, Illinois, August 29 - September 2, 1982.
* American Nuclear Society. 83/02/28. NRC - No Detailed Affiliation Given. 709pp. Available at NRC. $13.00. 17570:019.

8303150016 NUREG-0580 V12 N02
REGULATORY LICENSING STATUS SUMMARY REPORT Data As Of February 28, 1983 (Blue Book)
* Management Information Branch. 83/03/31. 40pp. 17586:172.

8303150031 NUREG/CR-3130
INFLUENCE OF LEACH RATE AND OTHER PARAMETERS ON GROUNDWATER MIGRATION.
OZTUNALI, O I ., PITT, C J ., FURFARO, J P. Dames & Moore. FIN B-7318. 83/02/28. Division of Waste Management. 308pp. Available at NRC. $8.50. 17597:181.

8303150044 Designates W Minners as NRR representative to safety goal evaluation plan steering group.
DENTON, H R. Office of Nuclear Reactor Regulation, Director. 83/03/07. DIRCKS, W J. Office of the Executive Director for Operations. 1p. 17611:197.

--8303150052 Requests name of representative to safety goal evaluation plan steering group by 830304.
DIRCKS, W J. Office of the Executive Director for Operations. 83/03/01. DENTON, H R. Office of Nuclear Reactor Regulation, Director. DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement. DAVIS, J G. Office of Nuclear Material Safety & Safeguards, Director. 1p. 17611:198.

8303150130 NUREG/CR-2904
SIMULATION OF GROUNDWATER FLOW AND CONTAINMENT TRANSPORT USING THE DETERMINISTIC-PROBABILISTIC CONTAMINANT TRANSPORT (DPCT) MODEL.
MCKAY, E D ., JOHNSON, T M ., READE, R T. CGS, Inc. FIN A-1267. SAND82-7077. 83/01/31. Division of Risk Analysis. 32pp. 17600:103.

8303150614 NUREG/CR-3126
SEMISCALE MOD-2A INTERMEDIATE BREAK TEST SERIES-TEST RESULTS COMPARISON.
BOUCHER, T J ., DIMENNA, R A. EG&G, Inc. FIN A-6038. EGG-2238. 83/02/28. Division of Accident Evaluation. 53pp. 17584:176.

8303150680 NUREG/CR-2800
GUIDELINES FOR NUCLEAR POWER PLANT SAFETY ISSUE PRIORITIZATION INFORMATION DEVELOPMENT.
ANDREWS, W B ., GALLUCCI, R H V ., HEABER, IN S W. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2507. PNL-429. 83/02/28. Division of Safety Technology. 274pp. Available at NRC. $8.00. 17583:062.

8303160009 NUREG/CR-2874 V02
HIGH-TEMPERATURE GAS-COOLED REACTOR SAFETY STUDIES FOR THE DIVISION OF ACCIDENT EVALUATION Quarterly Progress Report, April 1 - June 30, 1982.
BALL, S J ., CLAPP, N E ., CLEVELAND, J C. Oak Ridge National Laboratory. FIN B-0122. ORNL/TM-8443/V2. 83/02/28. Division of Accident Evaluation. 30pp. 17615:076.

8303160252 Notification of 830310 meeting w/Westinghouse Owners Group & WI Electric Power Co in Bethesda, MD to discuss generic proposal for core damage estimation procedure (NUREG-0737, Item II B.3, "Post-Accident Sampling").
COLBURN, T G. Operating Reactors Branch 3. 83/03/02. CLARK, R A. Operating Reactors Branch 3. 2pp. 17604:356.

8303160606 NUREG-0304 V07 N04
REGULATORY AND TECHNICAL REPORTS Compilation For 1982.
* Division of Technical Information & Document Control. 83/02/28. 630pp. 17600:341.

8303160611 NUREG/CR-3030
EVALUATION OF SELECTED NEUTRALIZING AGENTS FOR THE TREATMENT OF URANIUM TAILINGS LEACHATES Laboratory Progress Report.
SHERWOOD, D R ., SERNE, R J. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2370. PNL-4524. 83/02/28. Division of Health, Siting & Waste Management. 33pp. Available at NRC. $4.50. 17602:283.

8303160614 NUREG/CR-3009
FRACTURE TOUGHNESS OF PWR COMPONENT SUPPORTS.
KNORDVSKY, G A ., KRIEG, R D ., ALLEN, G C. Sandia Laboratories. FIN A-1106. SAND78-2347. 83/02/28. Division of Engineering. 225pp. Available at NRC. $7.50. 17602:318.

8303160626 NUREG-0525 R06
SAFEGUARDS SUMMARY EVENT LIST (SSEL).
* Office of Nuclear Material Safety & Safeguards, Director.
83/02/28. 42pp. 17611:233.

8303170281 NUREG/BR-0025 V09 N2
INFORMATION REPORT ON STATE LEGISLATION.
* Assistant Director for State & Licensee Relations. 83/03/01.
8pp. 17623:307.

8303170616 NUREG/CR-2968
EXPERIMENT DATA REPORT FOR MULTIROD BURST TEST (MRBT) BUNDLE B-4.
LONGEST, A. W., CHAPMAN, R. H., CROWLEY, J. L. Oak Ridge National Laboratory. FIN B-0120. ORNL/TM-8509. 83/01/31. Division of Accident Evaluation. 66pp. 17622:309.

8303170624 NUREG/CR-2863
VALENCE EFFECTS ON ADSORPTION A PRELIMINARY ASSESSMENT OF THE EFFECTS OF VALENCE STATE CONTROL ON SORPTION MEASUREMENTS.
MEYER, R. E., ARNOLD, W. D., CASE, F. Oak Ridge National Laboratory. FIN B-0642. ORNL-5965. 83/02/28. Division of Health, Siting & Waste Management. 31pp. 17615:160.

8303180606 Forwards status rept on NRC requirements which exceed scope of current regulations. Rept includes review of NUREG-0737, Items I.A.1.3, I.A.2.1, I.A.2.3, I.C.1.2, I.C.5, II.B.1, II.K.2.11, II.K.3.44 & I.G.1.
DIRCKS, W. J. Office of the Executive Director for Operations. 83/03/10. AHEARNE, J. Commissioners. 8pp. 17626:350.

--8303180622 Requests Executive Director of Operations rept describing areas requiring regulation not covered by current regulation.
AHEARNE, J. Commissioners. 83/01/21. CHILK, S. J. Office of the Secretary of the Commission. 1p. 17626:358.

--8303180627 Advises of Commission approval of recommendations not to issue final rule imposing NUREG-0737 provisions on OL applicants.
CHILK, S. J. Office of the Secretary of the Commission. 83/02/01. DIRCKS, W. J. Office of the Executive Director for Operations. 2pp. 17626:359.

8303220394 NUREG/CR-2098
COMMON CAUSE FAULT RATES FOR PUMPS Estimates Based On Licensee Event Reports At U.S. Commercial Nuclear Power Plants, January 1, 1972 Through September 30, 1980.
ATWOOD, C. L. EG&G, Inc. FIN A-6283. EGG-EA-5289. 83/02/28. Division of Risk Analysis. 206pp. Available at NRC. $7.00. 17666:085.

8303220400 NUREG/CR-2770
COMMON CAUSE FAULT RATES FOR VALVES. Estimates Based On Licensee Event Reports At U.S. Commercial Nuclear Power Plants, 1976-1980.
ATWOOD, C. L., STEVERSON, J. A. EG&G, Inc. FIN A-6283. EGG-EA-5485. 83/02/28. Division of Risk Analysis. 163pp. Available at NRC. $6.50. 17665:282.

8303220407 NUREG/CR-3145 V01
GEOPHYSICAL INVESTIGATIONS OF THE WESTERN OHIO-INDIANA REGION Annual Report, October 1981-September 1982.
CHRISTENSEN, D., WIEDENBECK, M. G., JACKSON, P. L. Michigan, Univ. of. FIN B-8080. 83/02/28. Division of Health, Siting & Waste Management. 64pp. Available at NRC. $5.50. 17666:291.

8303220409 NUREG/CR-2771
COMMON CAUSE FAULT RATES FOR INSTRUMENTATION AND CONTROL ASSEMBLIES Estimates Based On Licensee Event Reports At U.S. Commercial Nuclear Power Plants, 1976-1978.
ATWOOD, C. L. EG&G, Inc. FIN A-6283. EGG-EA-5623. 83/02/28. Division of Risk Analysis. 107pp. Available at NRC. $7.00. 17660:225.

8303220414 Forwards draft NUREG/CR-3122 "Potentially Damaging Failure Modes of High & Medium-Voltage Electrical Equipment," for review & comment re accuracy & completeness of technical details.
HELTEMES, C. J. Director's Office. 83/03/11. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. MINOGUE, R. B. Office of Nuclear Regulatory Research, Director. 2pp. 17673:009.

--8303220420 Forwards draft NUREG/CR-3122 "Potentially Damaging Failure Modes of High & Medium-Voltage Electrical Equipment," for review & comment re accuracy & completeness.
HELTEMES, C. J. Director's Office. 83/03/11. WILKINSON, E. P. Institute of Nuclear Power Operations. 2pp. 17673:011.

--8303220425 Forwards draft NUREG/CR-3122 "Potentially Damaging Failure Modes of High- & Medium-Voltage Electrical Equipment," for review & comment re accuracy & completeness.
HELTEMES, C. J. Director's Office. 83/03/11. ROSSIN, A. D. Nuclear Safety Analysis Center. 96pp. 17673:013.

8303220417 NUREG-0584 R03 DRFT
ASSURING THE AVAILABILITY OF FUNDS FOR DECOMMISSIONING NUCLEAR FACILITIES.
WOOD, R. S. Office of State Programs, Director. 83/03/31. 38pp. 17667:183.

8303220422 NUREG/CR-2878
DETECTION OF SMALL-SIZED NEAR-SURFACE UNDER-CLAD CRACKS FOR REACTOR PRESSURE VESSELS.
CRAWFORD, S. L., DOCTOR, S. R., TAYLOR, T. T. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2289. PNL-4373. 83/02/28. Division of Engineering Technology. 25pp. Available at NRC. $4.50. 17667:110.

8303220429 NUREG/CR-2901
CRAC CALCULATIONS FOR ACCIDENT SECTIONS OF ENVIRONMENTAL STATEMENTS.
JOHNSON, J. D., RITCHIE, L. T. Sandia Laboratories. FIN A-1307. SAND82-1693. 83/03/31. Division of Systems Integration (post 811005). 35pp. Available at NRC. $5.00. 17667:046.

8303220432 NUREG/CR-3144
TRENCH DESIGN AND CONSTRUCTION TECHNIQUES FOR LOW-LEVEL RADIOACTIVE WASTE DISPOSAL.
TUCKER, P. G. Army, Dept. of, Army Engineer Waterways Experiment Station. FIN B-6981. 83/02/28. Division of Waste Management. 221pp. Available at NRC. $8.00. 17667:250.

8303220453 NUREG/CR-3113
A TORSIONAL ULTRASONIC TECHNIQUE FOR LWR LIQUID LEVEL MEASUREMENT.
DRESS, W. B. Oak Ridge National Laboratory. FIN B-0401. ORNL/TM-8585. 83/02/28. Division of Facility Operations. 13pp. 17670:096.

8303230056 Transcript of 830301 regional workshop in San Francisco, CA re Suppl 1 to NUREG-0737. Pp 1-160.
* Region 5, Office of Director. 83/03/01. 160pp. 17688:348.

8303230074 Transcript of 830224 emergency response capability regional meeting in College Park, GA re Suppl 1 to NUREG-0737. Pp 1-160.
* NRC - No Detailed Affiliation Given. 83/02/24. 159pp. 17687:261.

8303230086 Transcript of 830222 regional workshop in Arlington, VA re Suppl 1 to NUREG-0737. Pp 1-161. Viewgraphs encl.
* NRC - No Detailed Affiliation Given. 83/02/22. 223pp. 17688:106.

8303230112 Responds to FOIA request for NUREG/CR-2239, "Technical Guidance for Siting Criteria Development." Document may be purchased from NRC.
FELTON, J. M. Division of Rules and Records. 83/02/22. LEWONTIN, Y. Affiliation Unknown. 1p. 17677:360.

8303230115 FOIA request for NUREG/CR-2239, "Technical Guidance for Siting Criteria Development."
LEWONTIN, Y. Affiliation Unknown. 83/02/10. NRC - No Detailed Affiliation Given. 1p. 17677:361.

8303230142 NUREG/CR-3092
CRITERIA FOR SAFETY-RELATED NUCLEAR POWER PLANT OPERATOR ACTIONS. INITIAL SIMULATOR TO FIELD DATA CALIBRATION.
BEARE, A. N., DORRIS, R. E., KOZINSKY, E. J. General Physics Corp. FIN B-0421-8. ORNL/TM-8599. 83/02/28. Division of Facility Operations. 61pp. 17689:154.

8303230194 Responds to FOIA request for NUREG-2239 re possible consequences of nuclear reactor accidents. Document may be purchased from NRC.
FELTON, J. M. Division of Rules and Records. 83/02/23. CAMPBELL, B. End Nuclear Dumping in the Pacific. 1p. 17686:185.

8303230197 FOIA request for NUREG-2239 re possible consequences of nuclear reactor accidents.
CAMPBELL, B. End Nuclear Dumping in the Pacific. 83/02/15. FELTON, J. Division of Rules and Records. 1p. 17686:186.

8303230205 Transcript of 830304 regional workshop in Arlington Heights, IL re Suppl 1 to NUREG-0737. Pp 1-148.
* Assistant Director for Safety Assessment. 83/03/04. 147pp. 17686:303.

8303230281 NUREG/CR-2729
USER'S GUIDE TO BFR A Computer Code Based On The Binomial Failure Rate Common Cause Model.
ATWOOD, C. L. ; SUITT, W. J. EG&G, Inc. FIN A-6283 EGG-EA-5502
83/02/28 Division of Risk Analysis 30pp. Available at NRC $4.75. 17686:015

8303230282 NUREG/CR-3082
PROBABILISTIC APPROACHES TO LCO'S AND SURVEILLANCE REQUIREMENTS FOR STANDBY SAFETY SYSTEMS.
LOFGREN, E. V. ; VARCOLIK, F. Science Applications, Inc. * Brookhaven National Laboratory FIN A-3231 BNL-NUREG-51628 83/02/28 Division of Risk Analysis 195pp. 17685:180.

8303230293 Responds to FOIA request for NUREG/CR-2239, "Technical Guidance for Siting Criteria Development." Document may be purchased from NRC.
FELTON, J. M. Division of Rules and Records 83/02/22 BOYLE, S. Affiliation Unknown. 1p. 17686:063.

8303230295 FOIA request for NUREG/CR-2239, "Technical Guidance for Siting Criteria Development."
BOYLE, S. Affiliation Unknown. 83/02/09 NRC - No Detailed Affiliation Given. 1p. 17686:064.

8303230338 "TMI Action Plan Tracking Sys." Jan 1983.
* Division of Data Automation & Management Information 83/01/30 164pp. 17673:166.

8303230362 NUREG/CR-2902
FLOW REGIME MODELING STUDY FOR THE SIMMER-II LMFBR SAFETY CODE CLAD RELOCATION.
GANAPOL, B. D. Los Alamos Scientific Laboratory FIN A-9707.
LA-9499-MS 83/02/28 Division of Accident Evaluation 38pp. 17673:330.

8303230408 NUREG/CR-2000 V02 N2
LICENSEE EVENT REPORT (LER) COMPILATION For Month Of February 1983.
* Oak Ridge National Laboratory FIN A-9135 ORNL/NSIC-200
83/03/31 Director's Office 70pp. 17675:084.

8303230413 NUREG/CR-3105
SECURORS APPLICATION TO A GENERIC NUCLEAR POWER PLANT.
ROUNDTREE, S. L. Sandia Laboratories FIN A-1060 SAND82-2821.
83/02/28 Division of Facility Operations 52pp. 17674:180.

8303230467 NUREG/CR-3114
PROCEEDINGS OF WORKSHOP ON COGNITIVE MODELING OF NUCLEAR PLANT CONTROL ROOM OPERATORS, August 15-18, 1982, DEDHAM, MASSACHUSETTS.
ABBOTT, L. S. Oak Ridge National Laboratory FIN B-0428
ORNL/TM-8614 83/02/28 Office of Nuclear Regulatory Research, Director 213pp. 17683:225.

8303230512 NUREG/CR-2939
EXPERIMENTAL AND ANALYTICAL STUDY OF NATURAL CONVECTION HEAT TRANSFER OF INTERNALLY HEATED LIQUIDS.
GREENE, G. A. Brookhaven National Laboratory FIN A-3024
BNL-NUREG-51585 83/02/28 Division of Accident Evaluation 56pp. 17677:119.

8303230517 NUREG/CR-3031
AN EVALUATION OF THE CALCULATED RESULTS OF AN UNPROTECTED TRANSIENT UNDERCOOLING ACCIDENT IN A LARGE, HETEROGENEOUS-CORE, LIQUID-METAL-COOLED FAST BREEDER REACTOR.
LUCK, L. B. ; DEVAULT, G. P. ; ASPREY, M. W. Los Alamos Scientific Laboratory. FIN A-7015 LA-9553-MS 83/02/28 Division of Accident Evaluation 211pp. 17684:078.

8303240109 Advises that CRGR concurs w/planned actions described in encl 830228 memo re Unresolved Issue A-43, "Containment Emergency Sump Performance." Package issued for public comment should include listed items.
STELLO, V. Regional Operations & Generic Requirements 83/03/16
DENTON, H. Office of Nuclear Reactor Regulation, Director 1p. 17693:334.

8303250113 NUREG/CR-2854
EVALUATION OF ALTERNATIVE SHAFT SINKING TECHNIQUES FOR HIGH LEVEL NUCLEAR WASTE (HLW) DEEP GEOLOGIC REPOSITORIES.
GONANO, L. ; FINDLEY, D. ; WILDANGER, W. Golder Associates FIN B-6983
813-1164D 83/03/31 Division of Waste Management 185pp. 17710:239.

8303250127 Summary of CRGR Meeting 33 on 830309 in Bethesda, MD re proposed rule 10CFR53, "Criteria & Procedures for Determining Adequacy of Spent Nuclear Fuel Storage Capacity" & Unresolved Safety Issue A-1. Recommends mods.
STELLO, V. Regional Operations & Generic Requirements 83/03/14
DIRCKS, W. J. Office of the Executive Director for Operations 5pp. 17700:328.

8303280061 NUREG/CR-3212
SELECTED REVIEW AND EVALUATION OF U.S. SAFETY RESEARCH VIS-A-VIS FOREIGN SAFETY RESEARCH FOR NUCLEAR POWER PLANTS.
STEVENSON, J. D. ; THOMAS, F. A. Stevenson & Associates FIN B-6769
83/03/31 Division of Engineering Technology 150pp. 17711:064.

8303280066 NUREG/CR-2974
USER'S MANUAL FOR LPGS: A Computer Program For Calculating Radiation Exposure Resulting From Accidental Radioactive Releases To The Hydrosphere.
WHITE, J. E. ; ECKERMAN, K. F. Oak Ridge National Laboratory FIN A-9100 ORNL/TDMC-2 83/03/31 Division of Technical Information & Document Control 167pp. 17711:214.

8303280097 NUREG/CR-3065 V02
IN SITU TEST PROGRAMS RELATED TO DESIGN AND CONSTRUCTION OF HIGH LEVEL NUCLEAR WASTE (HLW) DEEP GEOLOGIC REPOSITORIES Appendices.
ROBERDS, W. ; BAUHOF, F. ; GONANO, L. Golder Associates FIN B-6983
813-1163 83/03/31 Division of Waste Management 694pp. 17714:001.

8303280114 NUREG/CR-3065 V01
IN SITU TEST PROGRAMS RELATED TO DESIGN AND CONSTRUCTION OF HIGH LEVEL NUCLEAR WASTE (HLW) DEEP GEOLOGIC REPOSITORIES Main Report.
ROBERDS, W. ; BAUHOF, F. ; GONANO, L. Golder Associates FIN B-6983
813-1163 83/03/31 Division of Waste Management 219pp. 17712:021.

8303290355 Comments on proposed generic ltr to PWRs re NUREG-0737 Tech Specs Delay in inclusion of identified items in Tech Specs to be consistent w/issuance of new rule recommended.
SHEPPARD, J. J. Westinghouse Operating Plants Owners Group.
SHEPPARD, J. J. Carolina Power & Light Co. OG-93 83/03/21.
EISENHUT, D. G. Division of Licensing 3pp. 17716:256.

8303290673 NUREG/CR-2751 V03
HEAVY-SECTION STEEL TECHNOLOGY PROGRAM QUARTERLY PROGRESS REPORT FOR JULY-SEPTEMBER 1982.
WHITMAN, G. D. ; BRYAN, R. H. Oak Ridge National Laboratory FIN B-0119
ORNL/TM-8369/V3 83/02/28 Office of Nuclear Regulatory Research, Director 119pp. 17738:246.

8303290677 NUREG/CR-2887
RELAP5 ASSESSMENT: FLECHT SEASET STEAM GENERATOR TEST 23402.
KMETYK, L. N. Sandia Laboratories FIN A-1205 SAND82-2894
83/03/31 Division of Accident Evaluation 63pp. 17738:032.

8303290683 NUREG/CR-3115
EXPERT OPINION AND RANKING METHODS.
UPPULURI, V. R. R. Oak Ridge National Laboratory FIN B-0444
ORNL/CSD/TM-201 83/03/31 Office of Nuclear Regulatory Research, Director 23pp. 17742:244.

8303290689 NUREG/CR-2925
IN-PLANT CONSIDERATIONS FOR OPTIMAL OFFSITE RESPONSE TO REACTOR ACCIDENTS.
BURKE, R. P. ; HEISING, C. D. Massachusetts Institute of Technology
ALDRICH, D. C. Sandia Laboratories FIN A-1269 SAND82-2004
83/03/31 Division of Risk Analysis 150pp. 17738:096.

8303290694 NUREG-0837 V02 N03
TLD DIRECT RADIATION MONITORING NETWORK Progress Report July-September 1982.
COSTELLO, F. ; THOMPSON, T. ; COHEN, L. Region 1, Office of Director
83/03/31 198pp. Available at NRC $7.50. 17737:059.

8303290698 NUREG/CR-2928
DATA SUMMARY REPORT FOR FISSION PRODUCT RELEASE TEST HI-1.
OSBORNE, M. F. ; LORENZ, R. A. ; TRAVIS, J. R. Oak Ridge National Laboratory FIN B-0127 ORNL/TM-8500 83/02/28 Office of Nuclear Regulatory Research, Director 50pp. 17742:270.

8303290704 NUREG/CR-2945
CHARACTERIZATION OF EARTHQUAKE FORCES FOR PROBABILITY-BASED DESIGN OF NUCLEAR STRUCTURES.
ELLINGWOOD, B. ; BATTS, M. Commerce, Dept. of, National Bureau of Standards * Brookhaven National Laboratory FIN A-3226.
BNL/NUREG-51587 83/02/28 Division of Engineering Technology 70pp. 17737:257.

8303290707 NUREG/CR-2944
TORNADO DAMAGE RISK ASSESSMENT.
REINHOLD, T. A. ; ELLINGWOOD, B. Commerce, Dept. of, National Bureau of Standards FIN A-3226 BNL-NUREG-51586 83/02/28 Division of Engineering Technology 62pp. 17737:329.

8303290710 NUREG/CR-2824 V03
EDDY-CURRENT INSPECTION FOR STEAM GENERATOR TUBING PROGRAM Quarterly Progress Report For Period Ending September 30, 1982
DODD,C.V.; DEEDS,W.E.; MCCLUNG,R.W. Oak Ridge National Laboratory FIN B-0417 ORNL/TM-8418/V3 83/02/28 Division of Engineering 9pp 17742:234

8303290717 NUREG/CR-2886
THE IN-PLANT RELIABILITY DATA BASE FOR NUCLEAR PLANT COMPONENTS: INTERIM DATA REPORT-THE PUMP COMPONENT
DRAGO,J.P.; BORKOWSKI,R.J.; FRAGOLA,J.R. Oak Ridge National Laboratory FIN B-0445 ORNL/TM-8465 83/01/31 Division of Risk Analysis 158pp 17745:206

8303300221 Forwards high & low pressure basic versions of FR-P 1, "Response to Imminent Pressurized Thermal Shock Condition" & FR-P 2, "Response to Anticipated Pressurized Thermal Shock Condition."
SHEPPARD,J.J. Westinghouse Operating Plants Owners Group
SHEPPARD,J.J. Carolina Power & Light Co. 00-91 83/03/14
EISENHUT,D.G. Division of Licensing 2pp 17735:162

--8303300229 "Response to Imminent Pressurized Thermal Shock Condition," w/background info.
* Westinghouse Electric Corp 82/12/01 52pp 17735:164

--8303300237 "Response to Anticipated Pressurized Thermal Shock Condition," w/background info.
* Westinghouse Electric Corp 82/12/01 14pp 17735:216

--8303300244 "Response to Imminent Pressurized Thermal Shock Condition," w/background info.
* Westinghouse Electric Corp 82/12/01 52pp 17735:230

--8303300252 "Response to Anticipated Pressurized Thermal Shock Condition," w/background info.
* Westinghouse Electric Corp 82/12/02 14pp 17735:282

8303300426 NUREG-0020 V06 N11
LICENSED OPERATING REACTORS STATUS SUMMARY REPORT Data As Of October 31, 1982 (Grey Book)
* Management Information Branch 83/03/31 393pp 17768:356

8303300435 NUREG-0967
SEISMIC HAZARD REVIEW FOR THE SYSTEMATIC EVALUATION PROGRAM - A USE OF PROBABILITY IN DECISION MAKING
REITER,L.; JACKSON,R.E. Division of Engineering 83/03/31 65pp 17763:181

8303300446 NUREG/CR-2959
RELATIONSHIP OF AN IN SITU TEST FACILITY TO A DEEP GEOLOGIC REPOSITORY FOR HIGH LEVEL NUCLEAR WASTE
GATES,R.; BAUHOF,F.; GONANO,L. Golder Associates FIN B-6983 813-1165 83/03/31 Division of Waste Management 52pp 17763:245

8303300472 NUREG/CP-0028 V03
PROCEEDINGS OF THE SYMPOSIUM ON LOW-LEVEL WASTE DISPOSAL: Facility Design,Construction,And Operating Practices
YALCINTAS,M.G. Oak Ridge National Laboratory CONF-820911 83/03/31 Low Level Waste Licensing Branch 47pp 17767:011

8303300511 NUREG/CR-2997 V02
APPLICATIONS OF ENERGY RELEASE RATE TECHNIQUES TO PART-THROUGH CRACKS IN PLATES AND CYLINDERS: Volume 2: ORVIRT, A Finite Element Program For Energy Release Rate Calculations For 2-Dimensional And 3-Dimensional Crack Models
BASS,B.R.; BRYSON,J.W. Oak Ridge National Laboratory FIN B-0119 ORNL/TM-8527/V2 83/02/28 Division of Engineering Technology 52pp 17748:213

8303300514 NUREG/CR-2843 V01
THERMAL/HYDRAULIC ANALYSIS RESEARCH PROGRAM Quarterly Report, January - March 1982
THOMPSON,S.L. Sandia Laboratories FIN A-1205 SAND82-1788 83/03/31 Analytical Models Branch 63pp 17749:037

8303300518 NUREG/CR-3033
MODELING AOKI ET AL. EXPERIMENTS ON CONDENSATION OF FLOWING STEAM ONTO INJECTED WATER VIA K-FIX
MILOISNESS,R.C.; DALY,B.J. Los Alamos Scientific Laboratory FIN A-7027 LA-9574-MS 83/02/28 Division of Accident Evaluation 12pp 17748:286

8303300527 NUREG/CR-1391
MAEROS USER MANUAL
GELBARD,F. Sandia Laboratories FIN A-1196 SAND80-0822 83/02/28 Division of Accident Evaluation 56pp 17764:013

8303300597 NUREG/CR-3040 ERR
SELECTED REVIEW OF FOREIGN SAFETY RESEARCH FOR NUCLEAR POWER PLANTS
* Stevenson & Associates 83/03/15 Office of Nuclear Regulatory Research: Director 1p 17766:332

8303300628 NUREG/CR-3045 V01
LOSS OF BENEFITS RESULTING FROM NUCLEAR POWER PLANT OUTAGES Vol. 1: Approach And Analysis
BUEHRING,W.A.; PEERENBOOM,J.P. Argonne National Laboratory FIN A-2223 ANL/AA-28 83/02/28 Office of Nuclear Regulatory Research: Director 161pp 17766:006

8303300638 NUREG/CR-2751 V02
HEAVY SECTION STEEL TECHNOLOGY PROGRAM QUARTERLY PROGRESS REPORT FOR APRIL-JUNE 1982
WHITMAN,G.D.; BRYAN,R.H. Oak Ridge National Laboratory FIN B-0119 ORNL/TM-8369/V2 83/01/31 Division of Engineering Technology 150pp 17766:167

8303300651 NUREG/CR-2668
JOB ANALYSIS OF THE MAINTENANCE SUPERVISOR AND INSTRUMENT AND CONTROL SUPERVISOR POSITIONS FOR THE NUCLEAR POWER PLANT MAINTENANCE PERSONNEL RELIABILITY MODEL
BARTTER,W.D.; SIEGEL,A.I.; FEDERMAN,P.J. Oak Ridge National Laboratory FIN B-0461 ORNL/TM-8299 83/02/28 Division of Human Factors Safety 127pp 17768:153

8303310361 NUREG-0966
SAFETY EVALUATION REPORT RELATED TO THE D2/D3 STEAM GENERATOR DESIGN MODIFICATION
* Division of Licensing 83/03/31 147pp Available at NRC 6.50 17798:312

8303310366 NUREG/CR-3209
A SUMMARY OF COMPUTER CODES FOR RADIOLOGICAL ASSESSMENT
MILLS,M.; VOGT,D. Teknekron Research, Inc. FIN B-6985 83/03/31 Division of Waste Management 198pp Available at NRC $7.00 17796:297

8303310369 NUREG-0540 V04 N12
TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE December 1-31, 1982
* Division of Technical Information & Document Control 83/03/31 537pp 17797:135

8303310453 Partial response to FOIA request for six categories of documents. Forwards App A documents identified as Items 1, 3, 4, 5 & 6 of request. Search for documents re Item 2 of request continuing.
FELTON,J.M. Division of Rules and Records 83/02/24 HIATT,S.L. Ohio Citizens for Responsible Energy 2pp 17804:132 24x Fiche 50-000 83/02/24,8303310453.

--8303310463 Advises that Commission has approved SECY-82-407, recommending implementation of TMI Action Plan Item II.F.2 (NUREG-0737) re addl instrumentation for detection of inadequate core cooling.
CHILK,S.J. Office of the Secretary of the Commission 82/11/04
DIRCKS,W.J. Office of the Executive Director for Operations 1p 17804:134

ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS

8303020106 Forwards request for OMB review & supporting statement for clearance of info collection requirements in 10CFR32, "Transfers of Radioactive Consumer Products."
NORRY,P.G. Office of Administration 83/02/24 SCURRY,N. Office of Management & Budget 1p 17360:134

8303020125 Responds to approval request for info collection re 10CFR11 concerning criteria & procedures for determining eligibility for access to control over SNM. Request approved through 851231 under OMB Number 3150-0062.
SCURRY,N. Office of Management & Budget OMB 3150-0062 83/02/22
SCOTT,S. Document Management Branch 2pp 17359:137

8303020131 Responds to approval request for info collection re IE Bulletin 83-10, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation Sys Piping at BWR Plants." Request approved through 841231.
SCURRY,N. Office of Management & Budget OMB 3150-0096 83/02/22
SCOTT,S. Document Management Branch 2pp 17359:135

8303020137 Responds to approval request for info collection re 10CFR95 concerning security facility approval & safeguarding of matl security info & restricted data. Request approved through 860229 under OMB Number 3150-0047.
SCURRY,N. Office of Management & Budget OMB 3150-0047 83/02/22
SCOTT,S. Document Management Branch 2pp 17359:139

8303090394 Forwards request for OMB review & supporting statement covering info collection requirement re licensee analyses of significant hazards in license amend requests per SECY-83-16 & 16A.
NORRY, P G. Office of Administration. 83/03/04. SCURRY, N. Office of Management & Budget. 1p. 17480:214

8303090607 Informs that 830114 comments on ANSI/ANS 56.8-1981, "Containment Sys Leakage Testing Requirements" are being considered during development of reg guide.
ARNDT, E G. Mechanical/Structural Engineering Branch. 83/02/23.
REYTBLATT, Z V. Extran, Inc. 1p. 17480:163

--8303090614 Comments on ANSI/ANS-56.8-1981, "Containment Sys Leakage Testing Requirements." Std contains wrong equations which may result in underestimating leak rates by one or two orders of magnitude.
REYTBLATT, Z V. Extran, Inc. 83/01/14. ARNDT, E G. Mechanical/Structural Engineering Branch. 4pp. 17480:164

--8303090623 Informs that ANS N274 published as ANSI/ANS 56.8-1981, "Containment Sys Leakage Testing Requirements."
ARNDT, E G. Mechanical/Structural Engineering Branch. 82/11/01.
REYTBLATT, Z V. Extran, Inc. 1p. 17480:168

--8303090630 Ack receipt of 820921 ltr. ORNL will be contracted to work on containment leak testing. Most recent version of ANS N274 requested.
REYTBLATT, Z V. Extran, Inc. 82/10/05. GILLESPIE, F P. Administration & Resources Control Staff. 1p. 17480:169

--8303090634 Informs that no addl contract or consulting assistance in study of ANS N274 re containment leak testing required, in response to 820817 & 25 ltrs. Company placed on NRC bidder mailing list.
GILLESPIE, F P. Administration & Resources Control Staff. 82/09/21. REYTBLATT, Z V. Extran, Inc. 1p. 17480:170

--8303090639 Offers to participate in study of ANS N274 re containment leak testing. Unauthorized use of research re leak rate calculation objectionable.
REYTBLATT, Z V. Extran, Inc. 82/08/25. GILLESPIE, F P. Administration & Resources Control Staff. 1p. 17480:171

--8303090647 Informs that 820817 ltr re improvements to integral leak rate methodology & associated comments on gas mass calculations will be considered in review of ANSI/ANS 56.8-1981 (ANS N274).
GILLESPIE, F P. Administration & Resources Control Staff. 82/08/19. REYTBLATT, Z V. Extran, Inc. 1p. 17480:172

--8303090653 Urges prompt NRC formulation of position on company proposal re improvements to integral leak rate methodology.
REYTBLATT, Z V. Extran, Inc. 82/08/17. GILLESPIE, F P. Administration & Resources Control Staff. 1p. 17480:173

--8303090661 Informs that proposals submitted in 820426 ltr do not support research currently of interest to NRC. Company will be placed on NRC bidder mailing list.
GILLESPIE, F P. Administration & Resources Control Staff. 82/05/20. REYTBLATT, Z V. Extran, Inc. 1p. 17480:174

8303110087 Responds to 821209 ltr re nonpower reactor licensing function regionalization. Transfer delayed pending input from public meetings w/licensees & research, test & reactor community.
DIRCKS, W J. Office of the Executive Director for Operations. 83/03/02. RICHARDS, W. American Nuclear Society. 4pp. 17526:283

--8303110093 Submits Research Reactor Stds Committee (ANS-15) concerns re nonpower reactor function regionalization. Regionalization & decentralization will cause deterioration of uniformity & consistency of stds guidance.
RICHARDS, W J. American Nuclear Society. 82/12/09. PALLADINO, N J. Commissioners. 2pp. 17526:287

8303150046 Forwards radiological protection activities coordination plan for signature. Requirements for proposed rule requiring ALARA-integrated radiation protection plans will be considered w/major rev to 10CFR20.
DIRCKS, W J. Office of the Executive Director for Operations. 83/03/03. WILKINSON, E P. Institute of Nuclear Power Operations. 1p. 17586:309

--8303150051 Discusses recommendation to proceed w/coordination plan for radiological protection activities w/INPO. Unexecuted plan encl.
DENTON, H R. Office of Nuclear Reactor Regulation, Director. 83/02/25. DIRCKS, W J. Office of the Executive Director for Operations. 4pp. 17586:310

8303160022 Responds to approval request for info collection re 10CFR32 amend concerning reduction in requirement for reporting transfers of radioactive consumer products. Request approved through 831130 under OMB Number 3150-0001.
SCURRY, N. Office of Management & Budget. OMB 3150-0001. 83/03/02.
SCOTT, S. Document Management Branch. 2pp. 17615:115

8303170205 Responds to 830127 request for resource info re South Atlantic outer continental shelf Lease Sale 90. Brunswick & St Lucie plants are within planning area. NRC should be notified if toxic or flammable matls used nearby.
DENTON, H R. Office of Nuclear Reactor Regulation, Director. 83/03/08. GRESHAM, J B. Interior, Dept. of. 5pp. 17623:354

--8303170208 Requests resource info re South Atlantic outer continental shelf Lease Sale 90 by 830315.
GRESHAM, J B. Interior, Dept. of. 83/01/27. Commissioners. 3pp. 17623:358

8303230284 Forwards "Addendum to EIS Operation of PUREX & U Oxide Plant Facilities, Hanford Site, Richland, WA." DES w/addendum constitutes FES.
HEUSSER, R K. Energy, Dept. of. 83/02/28. NRC - No Detailed Affiliation Given. 1p. 17685:123

--8303230287 DOE/EIS-0089
"Addendum to EIS Operation of PUREX & U Oxide Plant Facilities, Hanford Site, Richland, WA."
* Energy, Dept. of. 83/02/28. 60pp. 17685:124

8303230316 Transcript of 830311 briefing in Washington, DC re INPO evaluation program. Pp 1-66. Outline of industry comments encl.
* Commissioners. 83/03/11. 109pp. 17686:068

8303300039 Releases public version of ANS comments on draft SRP for review & evaluation of emergency plans for research & test reactors.
FELTON, J M. Division of Rules and Records. 83/03/23. Document Management Branch. 1p. 17751:137

--8303300042 Forwards public version of ANS comments on draft SRP for review & evaluation of emergency plans for research & test reactors. Upon incorporation of encl comments, draft acceptable.
RICHARDS, W J. American Nuclear Society. 83/03/01. PAGANO, F G. EP Licensing Branch. 4pp. 17751:138

8303300071 Responds to 830124 ltr transmitting ANS statement of position on draft final high level waste technical criteria & supporting rationale document. Discussions on development of addl industry stds for satisfying 10CFR60 welcome.
DIRCKS, W J. Office of the Executive Director for Operations. 83/03/02. MUNTZING, L M. American Nuclear Society. 2pp. 17751:061

PR PROPOSED RULE

8302100331 Responds to 830107 inquiry re JM Paul 821220 comments on proposed rule 10CFR170 concerning schedule of revised fees for facilities & matls applications, renewals, amends & licenses. Fees intended to recover license costs.
KAMMERER, C. Office of Congressional Affairs. 47FR52454 021. 83/01/17. DIXON, A J. Senate. 2pp. 17116:356

--8302100333 Requests response to encl JM Paul 821220 ltr re proposed rule 10CFR170 on rev of license fees.
DIXON, A J. Senate. 47FR52454. 83/01/07. NRC - No Detailed Affiliation Given. 1p. 17116:358

--8302100335 Comments on proposed rule 10CFR170 re license fees for users of byproduct matls. Oppposes rule. NRC should scale down paper work for sake of economy.
PAUL, J M. Northwest Community Hosp. Arlington Heights, IL. 47FR52454. 82/12/20. Docketing & Services Branch. 1p. 17116:359

8302150708 Advises that presentation of Ofc of Executive Legal Director seminar series on nuclear waste disposal scheduled for 830215 in Bethesda, MD.
CUNNINGHAM, G H. Office of the Executive Legal Director. 83/02/09.
HARVEY, D M. Senate, Energy & Natural Resources. 1p. 17153:029

8302250325 Comments on proposed rule 10CFR170 re rev of licensee fee schedules. Supports rule.
LINTON, O W. American College of Radiology. 47FR52454:0133. 83/02/08. Docketing & Services Branch. 1p. 17291:052

8303020037 Ack receipt of 830128 ltr forwarding constituent J Parkyn comments on proposed rule 10CFR170 re NRC proposed revised fee schedule Proposed fees based on FY81 cost data & intended to recover costs of processing licenses.
KAMMERER,C. Office of Congressional Affairs 47FR52454 83/02/14
GUNDERSON,S. House of Rep 2pp 17353:156

8303020079 Responds to NRC 830125 ltr re schedule for current Natl Council on Radiation Protection & Measurements work on basic condition criteria in support of proposed rule 10CFR20 Final rept should be publicly available between 840101-0501
SINCLAIR,W.K. National Council on Radiation Protection & Measurements 45FR18023 077 83/02/11 MILLS,W.A. Health Effects Branch 2pp 17352:165

8303020090 Responds to 830208 inquiry re constituent RW Hahn comments on proposed rule 10CFR170 on schedule of revised fees for facilities & matl applications, renewals, amends & licenses Fees intended to recover costs of processing licenses.
KAMMERER,C. Office of Congressional Affairs 47FR52454 83/02/14
QUAYLE,D. Senate 2pp 17349:001

8303040415 Comments on Aug 1982 draft rev of 10CFR20, "Stds for Protection Against Radiation," in response to Council 821123 comments Estimate of target dates for development of Council recommendations requested.
MILLS,W.A. Health Effects Branch 83/01/25 SINCLAIR,W.K. National Council on Radiation Protection & Measurements 2pp 17426:352

8303160093 Summary of 830307 meeting w/vendors & NUS Corp re proposed criteria for determining content of Tech Specs & supplemental specs concerning proposed rulemaking on 10CFR50.36.
BRINKMAN,D.S. Standardization & Special Projects Branch 83/03/11
THOMAS,C.O. Standardization & Special Projects Branch 7pp 17614:333

8303170016 Forwards FR notice of final rule 10CFR35 re teletherapy room radiation monitors, for info.
BURNS,S.G. Regional Operations & Enforcement Division 83/03/08
LEMBARES,N. American Association of Physicists in Medicine 4pp 17609:082

8303280350 Responds to 830112 ltr expressing concern re NRC license fee program Processing of Ogle Petroleum case was inefficient Fee would probably not be reduced even if inefficiencies reduce cost.
DIRCKS,W.J. Office of the Executive Director for Operations 47FR52454 83/03/16 CHENEY,D. House of Rep 1p 17713:090

8303300580 Forwards FR notice amending 10CFR32 to modify reporting & recordkeeping requirements for consumer products Ltrs notifying congressional committees & Congressman Coelho also encl.
MINOGUE,R.B. Office of Nuclear Regulatory Research, Director 83/02/24 DIRCKS,W.J. Office of the Executive Director for Operations 3pp 17765:272

--8303300589 Forwards marked-up final rule package amending 10CFR32 Ofc of Administration cannot concur on final rule until amended reporting & recordkeeping requirements approved by OMB.
FELTON,J.M. Division of Rules and Records 83/02/14
MINOGUE,R.B. Office of Nuclear Regulatory Research, Director 1p 17765:281

--8303300595 Notice of final rule on 10CFR32 re consumer products containing small quantities of radioactive matl; modified reporting & recordkeeping requirements.
DIRCKS,W.J. Office of the Executive Director for Operations 83/03/04 12pp 17765:292

--8303300611 Forwards notice of final rulemaking amending 10CFR32 to modify requirement for distributors of consumer products containing byproduct matl to rept annually number of products distributed.
MINOGUE,R.B. Office of Nuclear Regulatory Research, Director 83/03/15 SIMPSON,A. Senate, Environment & Public Works 2pp 17765:304

--8303300616 Forwards notice of final rulemaking amending 10CFR32 to modify requirement re annual repts of distribution of consumer products containing byproduct matl.
PALLADINO,N.J. Commissioners 83/02/18 COELHO,T. Senate 2pp 17765:306

PRM PETITION FOR RULEMAKING

8302100345 Package of ten comments opposing UCS petition for rulemaking PRM-50-35 re emergency planning & preparedness proceedings.
CHRISTMAN,J.N. Hunton & Williams + LeBoeuf, Lamb, Leiby & MacRae
ZAHLER,R.E. Shaw, Pittman, Potts & Trowbridge 47FR51889
83/01/17 Docketing & Services Branch 50pp 17116:263

8303020048 Confirms 830128 telcon requesting addl 45 days to comment on petition for rulemaking PRM-40-24 Comments will be considered if received by 830317.
PHILIPS,J.D. Division of Rules and Records 47FR53889 83/01/28
HARTKE,J.A. New Mexico, State of 1p 17352:167

--8303020051 Requests addl 45 days to comment on Union Carbide Corp petition for rulemaking PRM-40-24 re U mill tailings license regulations.
HARTKE,J.A. New Mexico, State of 47FR53889 83/01/27
PHILIPS,J.D. Division of Rules and Records 1p 17352:168

8303020054 Comments on Union Carbide Corp petition for rulemaking PRM-40-24 re selection of sites to isolate tailings & associated contaminants Design objective of 1,000 yrs reasonable.
FREUDENTHAL,N. Wyoming, State of 47FR53889 007 83/02/16
CHILK,S.J. Office of the Secretary of the Commission 3pp 17353:151

--8303020058 Requests extension of comment period for Union Carbide Corp petition for rulemaking PRM-40-24.
PERRY,W. Wyoming, State of 47FR53889 007 83/02/16 CHILK,S.J. Office of the Secretary of the Commission 2pp 17353:154

8303020075 Comments on petition for rulemaking PRM-50-32A on hardening of safety-related equipment Hardening could be accomplished easily & inexpensively.
LEWIS,M.C. Lewis, M. 47FR53030 007 83/02/11 FELTON,J.M. Division of Rules and Records 2pp 17352:169

8303020098 Comments on petition for rulemaking PRM-34-3 re radiation surveys of radiographic exposure devices Supports petition.
DIXON,D.W. Southern California Edison Co. 47FR52722 005 83/02/15
CHILK,S.J. Office of the Secretary of the Commission 2pp 17349:112

8303290447 Requests status of petition for rulemaking re revision of NRC regulations to include consideration of electromagnetic pulse in design of nuclear plants.
MARSHALL,W.H. Marshall,W.H. MARSHALL,W.H. Mapleton Intervenors
83/03/18 FELTON,J.M. Division of Rules and Records 1p 17725:340

PROJ PROJECTS - PREDOCKET LICENSING

8303010080 Directs ASLB attention to 28USC1746 re intervenor question on ASLB 830119 memorandum & order discussing form of declaration of JH Malinowski.
MEISS,R.L. Pacific Gas & Electric Co. ISSUANCES A. 83/02/23
MARGULIES,M.B. Atomic Safety and Licensing Board Panel 2pp 17335:350

8303030340 Responds to 830223 ltr re JH Malinowski declaration discussed in Pp 11 & 12 of 830119 memorandum & order. Exceptions to decision filed on 830131 Any action taken would be inappropriate at present time.
MARGULIES,M.B. Atomic Safety and Licensing Board Panel ISSUANCES A 83/03/01 MEISS,R.L. Pacific Gas & Electric Co. 1p 17410:202

8303030367 Notifies of ASLAB reconstitution AS Rosenthal, chairman & SF Eilperin & GJ Edles, members.
ROSENTHAL,A.S. Atomic Safety and Licensing Appeal Panel. ISSUANCES A. 83/03/01 Atomic Safety and Licensing Appeal Panel. 1p. 17410:201

8303070109 Brief on exceptions to decision granting util motion to withdraw license application Util motion should be denied. If decision affirmed, util withdrawal should be conditioned as stated Certificate of Svc encl.
MCDIARMID,R.C., ADRAGNA,J.M. Northern California Power Agency, California, State of, MCDIARMID,R.C. Spiegel & McDiarmid ISSUANCES A 83/03/02 Atomic Safety and Licensing Appeal Panel 81pp 17430:230

8303080129 Forwards viewgraphs used at 830201 meeting on advanced control room design for advanced PWR & preliminary schedule for Phase I & II of design review Meetings scheduled May/June 1983 in Pittsburgh, PA to review task analysis tools.
RAHE,E.P. Westinghouse Electric Corp NS-EPR-2724 83/02/25
EISENHUT,D.G. Division of Licensing 21pp 17458:248

8303110064 Approves revs to QA plan for design & fabrication of dry storage cask for spent fuel.
HARPSTER, T. L. Division of Engineering & Quality Assurance (Pre 830103) 22003 83/02/17 ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch 1p 17526 333

8303150113 Forwards topical rept evaluation of CENPD-270, "Dry Storage Cask for ISFSI." Rept not acceptable. Revs suggested.
ROBERTS, J. P. Advanced Fuel & Spent Fuel Licensing Branch 83/02/25
SCHERER, A. E. Combustion Engineering, Inc. 2pp 17586 325

--8303150116 Topical rept evaluation of CENPD-270, "Dry Storage Cask for ISFSI." Rept not acceptable based on reasons listed.
* Advanced Fuel & Spent Fuel Licensing Branch 83/02/25 34pp 17586 327

8303180555 "Post-Test Analysis of LOFT Anticipated Transient Experiments L6-1, L6-2, L6-3 & L6-5," interim rept.
OLLIKKALA, H. , BEHLING, S. R. EG&G, Inc. FIN A-6048 EGG-LOFT-6159 83/01/31 MCPHERSON, G. D. NRC - No Detailed Affiliation Given 49pp 17639 331

8303290750 Forwards Rev 1 to "Topical Safety Analysis Rept for Castor IC Cask ISFSI (Dry Storage)," Nov 1982 & proprietary appx.
ROLLINS, J. D. Germany, Federal Republic of 83/02/21 Division of Fuel Cycle & Material Safety 2pp 17744 001

--8303290751 Rev 1 to "Topical Safety Analysis Rept for Castor IC Cask ISFSI (Dry Storage)."
* Germany, Federal Republic of 21957 82/11/30 212pp 17744 003

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

8303030572 Part 21 rept re possible defect on Rockbestos Triaxial Cable Type RSS-6-108. Initially reported on 830121. No effect on electrical or mechanical performance during temp excursion. Cable will meet LOCA requirements of IEEE 323-1974.
UNDERWOOD, R. H. , MASSEY, W. F. Westinghouse Electric Corp PT21 83-773-000 83/01/28 Region 4, Office of Director 11pp 17409 352

8303040511 Part 21 rept re possible misapplication of std Bergen-Paterson EA-3 strut restraint clamp. United Engineers & Constructors, Inc misinterpreted info in Catalog 66 re angle or position of installation. Applicable plants listed.
STEPHENS, R. H. Bergen-Paterson Pipe Support Corp. PT21 83-774-000 83/02/24 GRIER, B. H. Region 1, Office of Director 11pp 17373 295

8303090201 Part 21 rept re defective SBM control switches. Switches contained at least one contact which failed to close or remain closed. Contact infidelity covers Jan 1982 through end of Jan 1983. Sample warning ltr to customers encl.
MANKOFF, L. L. General Electric Co. PT21 83-761-000 83/03/01
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 2pp 17492 146

8303240349 Part 21 rept re PVD21B, D & HGA11 & 111 relays. Encl ltrs sent to customers applying for devices in nuclear installations. Response fulfills obligation.
MANKOFF, L. L. General Electric Co. PT21 83-758-000 83/02/24
DEYOUNG, R. Director's Office, Office of Inspection and Enforcement 3pp 17680 005

QA999 QUALITY ASSURANCE INSPECTIONS

8303010348 Discusses QA Program Insp Repts 99900033/82-01 & 99900033/82-02 on 820607-11 & 1213-16. Item F02700115 re potential failures of Westinghouse supplied valves to close under sys differential pressures completed.
POTAPOVS, U. Division of Vendor & Technical Programs 83/02/25
LEWIS, R. C. Division of Project & Resident Programs 1p 17346 170

8303010363 Discusses QA Program Insp Repts 99900033/82-01 & 99900033/82-02 on 820607-11 & 1213-16. Area of concern involves reactor coolant pump bolting failures due to stress corrosion. Source of halides unknown.
POTAPOVS, U. Division of Vendor & Technical Programs 83/02/25
BAER, R. L. Engineering & Technical Support Branch 1p 17345 128

8303010366 Confirms QA program insp on 830314-18 per 830222 telcon.
POTAPOVS, U. Division of Vendor & Technical Programs 83/02/25
TENZER, B. E. Ebasco Services, Inc. (subs. of Enserch Corp.) 1p 17344 359

8303010450 Forwards QA Program Insp Rept 99900033/82-02 on 821213-16 & notice of nonconformance.
POTAPOVS, U. Division of Vendor & Technical Programs 83/02/03
RUPPEL, H. D. Westinghouse Electric Corp 2pp 17343 122

--8303010454 Notice of nonconformance from insp on 821213-16.
* Division of Vendor & Technical Programs 83/02/03 2pp 17343 124

--8303010468 QA Program Insp Rept 99900033/82-02 on 821213-16. Noncompliance noted: insufficiently detailed formal analytic rept of valve mod program & failure to perform matl reidentification in timely manner.
MCNEILL, W. M. , BARNES, I. Division of Vendor & Technical Programs 83/02/03 9pp 17343 126

8303010475 Forwards QA Program Insp Rept 99900278/83-01 on 830110-11. No noncompliance noted.
POTAPOVS, U. Division of Vendor & Technical Programs 83/02/04
PRINCE, L. T. Conam Inspection 2pp 17343 312

--8303010483 QA Program Insp Rept 99900278/83-01 on 830110-11. No noncompliance noted. Major areas inspected: allegations that written exam question number & difficulty do not meet ASME code requirements.
ROBERDS, H. W. , BARNES, I. Division of Vendor & Technical Programs 83/02/03 5pp 17343 314

8303010476 Forwards QA Program Insp Rept 99900909/82-04 on 821129-1203, notice of violation & notice of nonconformance.
POTAPOVS, U. Division of Vendor & Technical Programs 83/01/31
MABRITO, B. Southwest Research Institute 3pp 17343 092

--8303010482 Notice of violation from insp on 821129-1203.
* Division of Vendor & Technical Programs 83/01/31 1p 17343 095

--8303010486 Notice of nonconformance from insp on 821129-1203.
* Division of Vendor & Technical Programs 83/01/31 1p 17343 096

--8303010498 QA Program Insp Rept 99900909/82-04 on 821129-1203. Noncompliance noted: failure to post required documents in radiation aging facility & to specify in purchase order to Conax Corp that 10CFR21 applied.
SMITH, A. L. , PHILLIPS, H. S. Division of Vendor & Technical Programs 83/01/28 15pp 17343 097

8303010657 Discusses QA Program Insp Rept 99900278/83-01 on 830110-11. No basis for allegation that Automation Industries Certification School for NDE personnel giving Level III exams of insufficient depth. Item 82-181 closed.
POTAPOVS, U. Division of Vendor & Technical Programs 83/02/25
JOHNSON, E. H. Region 4, Office of Director 1p 17341 075

8303030529 Ack receipt of 830106 & 0204 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900276/82-01.
POTAPOVS, U. Division of Vendor & Technical Programs 83/02/28
CASSIDY, R. F. Solidstate Controls, Inc. 1p 17409 009

--8303030538 Responds to NRC 821208 ltr re nonconformance noted in QA Program Insp Rept 99900276/82-01. Corrective actions: procedures initiated to assure proper documentation of investigation of possible reportable failures.
MCCLUNG, R. J. Solidstate Controls, Inc. 83/02/04 POTAPOVS, U. Division of Resident, Reactor Project & Engineering Programs 18pp 17409 010

--8303030547 Confirms 830106 telcon granting extension of time for answering 821208 ltr re nonconformance noted in QA Program Insp Rept 99900276/82-01.
MCCLUNG, R. J. Solidstate Controls, Inc. 83/01/06 POTAPOVS, U. Division of Vendor & Technical Programs 1p 17409 028

8303030637 Ack receipt of 830131 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900505/82-04. Each 10CFR50.55(e) rept must be evaluated for info required by Part 21.
POTAPOVS, U. Division of Vendor & Technical Programs 83/02/28
TENZER, B. E. Ebasco Services, Inc. (subs. of Enserch Corp.) 1p 17409 292

--8303030642 Responds to NRC 830106 ltr re nonconformance noted in QA Program Insp Rept 99900505/82-04. Corrective actions: Form 1352 utilized & memos will be sent to QA supervisor within 2 wks documenting verbal safety evaluations.
TENZER, B. E. Ebasco Services, Inc. (subs. of Enserch Corp.) 83/01/31 POTAPOVS, U. Division of Vendor & Technical Programs 3pp 17409 293

8303040535 Ack receipt of 821123 & 830202 ltrs informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 99900787/82-01.
POTAPOVS,U. Division of Vendor & Technical Programs. 83/02/28.
SANFORD,R.S. ALFAB, Inc. 1p. 17366:028.

--8303040550 Responds to NRC 821223 ltr re nonconformances noted in QA Program Insp Rept 99900787/82-01. Corrective actions: welding procedures submitted for approval; welding machines calibr & training session on stud testing conducted w/QC inspectors.
GRANTHAM,B. ALFAB, Inc. 83/02/02. BARNES,I. Region 4, Office of Director. 18pp. 17366:029.

--8303040560 Ack receipt of 821123 ltr informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 99900787/82-01. Addl info requested.
POTAPOVS,U. Division of Vendor & Technical Programs. 82/12/23.
SANFORD,R.S. ALFAB, Inc. 2pp. 17366:046.

--8303040582 Responds to NRC 821022 ltr re nonconformance noted in QA Program Insp Rept 99900787/82-01. Corrective actions: welders qualified per AWS D1.3; welding machines calibr; studs tested & tack welds removed & retacked by qualified tacker.
GRANTHAM,B. ALFAB, Inc. 82/12/23. BARNES,I. Region 4, Office of Director. 4pp. 17366:048.

8303040556 Forwards QA Program Insp Rept 99900903/82-02 on 821213-16 & notice of nonconformance.
POTAPOVS,U. Division of Vendor & Technical Programs. 83/02/03.
RUSSELL,J. Georgia Institute of Technology. 2pp. 17374:156.

--8303040562 Notice of nonconformance from insp on 821213-16.
* Division of Vendor & Technical Programs. 83/02/03. 1p. 17374:158.

--8303040572 QA Program Insp Rept 99900903/82-02 on 821213-16. Noncompliance noted: review of QA manual; implementation of QA requirements & witnessing of radiation testing of ITT Barton differential pressure indicating switches not conducted.
HUBBARD,G.T., PHILLIPS,H.S. Region 4, Office of Director.
BENSON,J.J. Sandia Laboratories. 83/02/03. 9pp. 17374:159.

8303040598 Ack receipt of 830131 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900532/82-01.
POTAPOVS,U. Division of Vendor & Technical Programs. 83/02/28.
SMITH,R.B. Control Data Corp. 1p. 17374:269.

--8303040606 Responds to NRC 820902 ltr re nonconformance noted in QA Program Insp Rept 99900532/82-01. Corrective actions: automated hotline logging sys established to alleviate indexing & completeness problems.
SMITH,R.B. Control Data Corp. 83/01/31. POTAPOVS,U. Division of Vendor & Technical Programs. 3pp. 17374:270.

8303070006 Forwards B&W final evaluation of potential safety concern noted in QA Program Insp Rept 99900400/82-04. Disagrees w/B&W conclusion of no substantial safety hazard had original design defect gone undetected. W/o encl.
POTAPOVS,U. Division of Vendor & Technical Programs. 83/03/03.
BAER,R.L. Engineering & Generic Communications Branch. 1p. 17433:273.

8303070016 Informs of use of steam generator drain line for blowdown as reported in QA Program Insp Rept 99900400/82-04. Util used drain line for high energy pipe applications. Possible enforcement action suggested. Matter closed at B&W.
POTAPOVS,U. Division of Vendor & Technical Programs. VITS 82-262.
83/03/03. LEWIS,R.C. Division of Project & Resident Programs. 1p. 17434:331.

8303070023 Forwards QA Program Insp Rept 99900394/83-01 on 830110-13. No noncompliance noted.
POTAPOVS,U. Division of Vendor & Technical Programs. 83/02/09.
SHAFER,J.C. Metal Bellows Corp. 2pp. 17435:303.

--8303070027 QA Program Insp Rept 99900394/83-01 on 830110-13. No noncompliance noted. Major areas inspected: mfg process control; internal audits; welding control & qualification of NDE personnel & procedures.
OLLER,R.E., BARNES,I. Region 4, Office of Director. 83/02/07. 12pp. 17435:305.

8303070029 Discusses 821115-19 insp of collapsing auxiliary feedwater headers. Cause identified as collapsing steam voids which generate negative pressure transients w/orders of magnitude larger than design calculations. No noncompliance noted.
POTAPOVS,U. Division of Vendor & Technical Programs. VITS 82-267.
83/03/03. LEWIS,R.C. Division of Project & Resident Programs. 1p. 17435:001.

8303070032 Forwards QA Program Insp Rept 99900913/82-02 on 821116-19 & notice of nonconformance.
POTAPOVS,U. Division of Vendor & Technical Programs. 83/02/07.
DIETZ,G.R. Isomedix, Inc. (Subs of Masefield Enterprises, Inc.). 2pp. 17434:340.

--8303070037 Notice of nonconformance from insp on 821116-19.
* Division of Vendor & Technical Programs. 83/02/07. 2pp. 17434:342.

--8303070044 QA Program Insp Rept 99900913/82-02 on 821116-19. Noncompliance noted: calculation of radiation time & total integrated dose for customer cable not performed & irradiation parameters changed w/o proper documentation.
JOHNSON,A.R., PHILLIPS,H.S. Region 4, Office of Director. 83/02/04. 13pp. 17434:344.

8303070033 Discusses QA Program Insp Rept 99900400/82-04 on 821115-19. Areas inspected: lock pins in stainless steel valves exhibiting high degree of magnetism & RCS support & restraint anchor bolt stress corrosion cracking.
POTAPOVS,U. Division of Vendor & Technical Programs. VITS 81-181.
83/03/03. LEWIS,R.C. Division of Project & Resident Programs. 1p. 17434:339.

8303070063 Confirms QA program insp at San Francisco Power Div on 830314-18 per 830225 telcon.
POTAPOVS,U. Division of Vendor & Technical Programs. 83/03/03.
STATTON,C.D. Bechtel Corp. 1p. 17435:013.

8303070069 Forwards QA Program Insp Rept 99900400/82-04 on 821115-19 & notice of nonconformance.
POTAPOVS,U. Division of Vendor & Technical Programs. 83/02/07.
QUILBERT,D.E. Babcock & Wilcox Co. 2pp. 17435:317.

--8303070078 Notice of nonconformance from insp on 821115-19.
* Division of Vendor & Technical Programs. 83/02/07. 1p. 17435:319.

--8303070085 QA Program Insp Rept 99900400/82-04 on 821115-19. Noncompliance noted: Operating Instruction IO-1262 re acceptance criteria for drawings issued & implemented w/o required approval of div QA.
BRICKLEY,R.H., BREAUX,D.G., SAKOWSKI,P. Division of Vendor & Technical Programs. 83/02/03. 26pp. 17435:320.

8303070074 Forwards QA Program Insp Rept 99900113/82-04 re ambiguous outputs from Barton pressure transmitters & post-accident readings from containment sump level transmitters. W/o rept.
POTAPOVS,U. Division of Vendor & Technical Programs. VITS 82-238.
83/03/03. LEWIS,R.C. Division of Project & Resident Programs. 1p. 17434:301.

8303070090 Confirms QA program insp to be conducted on 830328-0401 per 830225 telcon.
POTAPOVS,U. Division of Vendor & Technical Programs. 83/03/03.
PATTERSON,R.W. Sargent & Lundy, Inc. 1p. 17435:178.

8303070098 Ack receipt of 821222 & 830210 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900525/82-02.
POTAPOVS,U. Division of Vendor & Technical Programs. 83/03/03.
LORENZ,H. Gilbert/Commonwealth Cos. 1p. 17433:347.

--8303070140 Responds to NRC 821126 & 830115 ltrs re nonconformance noted in QA Program Insp Rept 99900525/82-02. Corrective actions: listed review activity evaluation & bulletin will be completed by 830228.
BARKER,N.R. Gilbert/Commonwealth Cos. 83/02/10. POTAPOVS,U. Division of Vendor & Technical Programs. 2pp. 17433:348.

--8303070143 Ack receipt of 821222 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900525/82-02. Addl corrective actions requested.
POTAPOVS,U. Division of Vendor & Technical Programs. 83/01/18.
LORENZ,H. Gilbert/Commonwealth Cos. 2pp. 17433:350.

--8303070147 Responds to NRC 821126 ltr re nonconformance noted in QA Program Insp Rept 99900525/82-02. Corrective actions: review of ASCO solenoid valves w/other than Viton seals will be completed by 830114.
BARKER,N.R. Gilbert/Commonwealth Cos. 82/12/22. POTAPOVS,U. Division of Vendor & Technical Programs. 2pp. 17433:352.

8303070101 Ack receipt of 830214 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900794/82-01.
POTAPOVS,U. Division of Vendor & Technical Programs. 83/03/03.
EGGERS,P. Ridihalgh, Eggers & Associates. 1p. 17433:099.

--8303070171 Confirms 821220 telcon re nonconformance noted in QA Program Insp Rept 99900794/82-01. Corrective actions internal memo written to confirm QA personnel instructed to file design control checklists & QAP Qa 02 submitted for approval.
ADAMS, J. E. Ridihalgh, Eggers & Associates 83/02/14 POTAPOVS, U. Division of Vendor & Technical Programs. 2pp. 17433:100.

--8303070172 Confirms agreement to extend deadline for submitting addl info re QA Program Insp Rept 99900794/82-01 to 830214.
ADAMS, J. E. Ridihalgh, Eggers & Associates. 83/02/03. POTAPOVS, U. Division of Vendor & Technical Programs. 2pp. 17433:102.

--8303070168 Ack receipt of 821215 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900794/82-01. Addl info needed re documentation of personnel instructions & revs to topical rept.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/01/13.
EGGERS, P. Ridihalgh, Eggers & Associates. 1p. 17433:103.

--8303070165 Responds to NRC 821116 ltr re nonconformance noted in QA Program Insp Rept 99900794/82-01. Corrective actions: internal audit on 821215 confirmed recent structural & thermal calculations entered in log of design calculations.
ADAMS, J. E. Ridihalgh, Eggers & Associates. 82/12/15. POTAPOVS, U. Division of Vendor & Technical Programs. 4pp. 17433:104.

8303070107 Forwards QA Program Insp Rept 99900113/82-04 on 821115-18 & notice of nonconformance.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/02/07.
WELT, G. R. International Telephone & Telegraph Corp. 2pp. 17434:264.

--8303070114 Notice of nonconformance from insp on 821115-18.
* Division of Vendor & Technical Programs. 83/02/07. 3pp. 17434:266.

--8303070126 QA Program Insp Rept 99900113/82-04 on 821115-18. Noncompliance noted: noise level of transmitter output & zero output had not been logged on initial calibr sheet.
OLLER, R. E. ; BARNES, I. ; FOSTER, W. E. Division of Vendor & Technical Programs. 83/02/04. 20pp. 17434:269.

8303070124 Forwards QA Program Insp Rept 99900764/83-01 on 830125-27 & notice of nonconformance.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/02/16.
LINDBERG, J. A. Sandvik Special Metals Corp. 2pp. 17434:252.

--8303070129 Notice of nonconformance from insp on 830125-27.
* Division of Vendor & Technical Programs. 83/02/16. 2pp. 17434:254.

--8303070136 QA Program Insp Rept 99900764/83-01 on 830125-27. Noncompliance noted: job training progress records not forwarded to documentation coordinator & indexes not maintained for process spec changes.
MCNEILL, W. M. Region 4, Office of Director. BARNES, I. Division of Vendor & Technical Programs. 83/02/15. 8pp. 17434:256.

8303070144 Ack receipt of 830218 ltr informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 99900736/82-01.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/03/03.
ROSENTRETER, R. NPS Industries, Inc. 1p. 17433:076.

--8303070153 Responds to NRC 830118 ltr re nonconformances noted in QA Program Insp Rept 99900736/82-01. Corrective actions: missing QA release form forwarded to NRC & welder qualification records corrected by entry of F number.
ROSENTRETER, R. NPS Industries, Inc. RCR-217. 83/02/18.
POTAPOVS, U. Division of Vendor & Technical Programs. 3pp. 17433:077.

8303080371 Forwards QA Program Insp Rept 99900521/82-05 on 821213-16. No noncompliance noted.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/02/11.
HINKELMAN, L. G. Bechtel Corp. 2pp. 17453:255.

--8303080376 QA Program Insp Rept 99900521/82-05 on 821213-16. No noncompliance noted. Major areas inspected: followup on previous insp concerns & two potential 10CFR50.55(e) repts from AZ Public Svc Co re design of condensate storage tank.
COSTELLO, J. R. ; HALE, C. J. Division of Vendor & Technical Programs. 83/02/12. 10pp. 17453:257.

8303080383 Confirms 830308 mgt meeting in Malvern, PA re implementation of equipment qualification QA program for Class 1E equipment per 830220 telcon.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/03/03.
CARDELLO, P. Anaconda Co. (subs. of Atlantic-Richfield Co.). 1p. 17454:169.

8303150159 Forwards QA Program Insp Rept 99900377/82-01 on 821101-05. QA program deficiencies identified by Bechtel & CPC valid. Concerns raised re adequacy of previous Bechtel audit & surveillance activities W/o encl.
POTAPOVS, U. Division of Vendor & Technical Programs. VITS 82-255. 83/03/11. HARNICK, R. F. Region 3, Office of Director. 1p. 17555:204.

8303150164 Forwards QA Program Insp Rept 99900097/82-02 on 821004-07 & notice of nonconformance.
POTAPOVS, U. Division of Vendor & Technical Programs. 82/11/12.
TUCKER, J. G. Chicago Bridge & Iron Co. 2pp. 17550:162.

--8303150169 Notice of nonconformance from insp on 821004-07.
* Division of Vendor & Technical Programs. 82/11/12. 1p. 17550:164.

--8303150172 QA Program Insp Rept 99900097/82-02 on 821004-07. Noncompliance noted: repetitive conditions of bent hinge pins, damaged hinges & door rebound in personnel locks not reported via corrective action request for mgt attention.
KELLEY, W. D. ; BARNES, I. Region 4, Office of Director. 82/11/03. 7pp. 17550:165.

--8303150179 Ack receipt of 821207, 830110 & 0203 ltrs in response to NRC 821112 & 830113 ltrs re QA Program Insp Rept 99900097/82-02. Corrective actions will be reviewed.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/02/18.
TUCKER, J. G. Chicago Bridge & Iron Co. 1p. 17550:172.

8303150236 Confirms QA program insp at Medford, NY plant on 830314-18 per 830303 telcon. Insp relates to implementation of QA program for safety-related equipment qualification testing.
POTAPOVS, U. Division of Vendor & Technical Programs. IEB-79-01B. 83/03/09. MULNAR, K. American Environments Co. 1p. 17556:070.

8303150245 Confirms QA program insp at San Jose & Vallecitos, CA plants on 830328-0401 per 830302 telcon. NRC insp team will consist of JR Agee & representative from Sandia Natl Labs.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/03/09.
SHIRLEY, N. G. General Electric Co. 1p. 17568:344.

8303150259 Forwards QA Program Insp Rept 99900377/82-01 on 821101-05 & notices of nonconformance & violation.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/01/19.
ASHE, J. Victoreen, Inc. (subs. of Sheller-Globe Corp.). 2pp. 17567:261.

--8303150266 Notice of violation from insp on 821101-05.
* Division of Vendor & Technical Programs. 83/01/19. 1p. 17567:263.

--8303150271 Notice of nonconformance from insp on 821101-05.
* Division of Vendor & Technical Programs. 83/01/19. 2pp. 17567:264.

--8303150278 QA Program Insp Rept 99900377/82-01 on 821101-05. Noncompliance noted: failure to assure procurement document specified that 10CFR21 applied & to prepare records on evaluation of known workmanship defects.
PARKER, L. B. ; BARNES, I. Region 4, Office of Director. 83/01/06. 10pp. 17567:266.

8303150302 Confirms 830215 telcon re 830228-0304 insp of QA program implementation.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/02/18.
LORENZ, H. Gilbert/Commonwealth Cos. 1p. 17567:070.

8303150314 Confirms QA program insp at Boston, MA plant on 830228-0304 per 830214 telcon. Equipment qualification testing of Class 1E equipment will be inspected.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/02/18.
SUTKUS, A. SIW Cable Systems, Inc. 1p. 17567:012.

8303150351 Ack receipt of 830220 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900903/82-02.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/03/09.
RUSSELL, J. L. Georgia Institute of Technology. 1p. 17562:356.

--8303150356 Responds to NRC 830203 ltr re nonconformance noted in QA Program Insp Rept 99900903/82-02. Corrective actions: hot cell operations personnel directed, since 830101, to initial data pages. Requirement will be formally implemented by 830401.
RUSSELL, J. L. Georgia Institute of Technology. 83/02/23.
POTAPOVS, U. Division of Vendor & Technical Programs. 1p. 17562:357.

8303150361 Forwards QA Program Insp Rept 99900296/82-01 on 821213-16 & notice of nonconformance.
POTAPOVS,U Division of Vendor & Technical Programs 83/02/22
NEWMAN,B Amerace Corp 3pp 17562:232

--8303150366 Notice of nonconformance from insp on 821213-16.
* Division of Vendor & Technical Programs 83/02/22 3pp 17562:235

--8303150373 QA Program Insp Rept 99900296/82-01 on 821213-16. Noncompliance noted internal QA audit checklist not modified per 811104 corrective action response & documentation not available re final QA insp or audits of returned units.
FOSTER,W E , BARNES,I Region 4, Office of Director 83/02/16 18pp 17562:238

8303150468 Ack receipt of 830114 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900507/82-02.
POTAPOVS,U Division of Vendor & Technical Programs 83/02/18
PATTERSON,R W Sargent & Lundy, Inc 1p 17561:137

--8303150470 Responds to NRC 821217 ltr re nonconformance noted in QA Program Insp Rept 99900507/82-02. Corrective actions design document changes status rept under review & will be completed by 830331.
TAYLOR,H S Sargent & Lundy, Inc 83/01/14 POTAPOVS,U Division of Vendor & Technical Programs 4pp 17561:138

8303150559 Ack receipt of 821207, 830110 & 0203 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900097/82-02.
POTAPOVS,U Division of Vendor & Technical Programs 83/02/18
TUCKER,J G Chicago Bridge & Iron Co 1p 17567:357

--8303150567 Responds to NRC 830113 ltr re nonconformance noted in QA Program Insp Rept 99900097/82-02. Owners of locks purchased before 700101 will be issued operating & maint manual addendum. Notification ltrs encl.
KELLEY,R E Chicago Bridge & Iron Co 83/02/03 POTAPOVS,U Division of Vendor & Technical Programs 7pp 17567:358

--8303150579 Ack receipt of 821207 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900097/82-02. Addl info needed within 25 days demonstrating that revised operating instructions provided to customers.
POTAPOVS,U Division of Vendor & Technical Programs 83/01/13
KELLEY,R E Chicago Bridge & Iron Co 7pp 17568:003

--8303150587 Responds to NRC 821215 telcon requesting addl info re nonconformance noted in QA Program Insp Rept 99900097/82-02. Ltr from NRC specifying addl info needed not yet received.
KELLEY,R E Chicago Bridge & Iron Co 83/01/10 POTAPOVS,U Division of Vendor & Technical Programs 1p 17568:004

--8303150594 Responds to nonconformance noted in QA Program Insp Rept 99900097/82-02. Adverse condition re ASME Boiler & Pressure Code properly processed utilizing appropriate internal mechanism. Supporting ltr encl.
KELLEY,R E Chicago Bridge & Iron Co 82/12/07 POTAPOVS,U Division of Vendor & Technical Programs 7pp 17568:005

8303180192 Forwards QA Program Insp Rept 99900806/83-01 on 830124-28 & notices of nonconformance & violation.
POTAPOVS,U Division of Vendor & Technical Programs 83/02/25
JACOBY,D J Alloy Crafts Co 2pp 17618:156

--8303180200 Notice of violation from insp on 830124-28.
* Region 4, Office of Director 83/02/25 1p 17618:158

--8303180204 Notice of nonconformance from insp on 830124-28.
* Region 4, Office of Director 83/02/25 2pp 17618:159

--8303180212 QA Program Insp Rept 99900806/83-01 on 830124-28. Noncompliances noted lack of documentation on exams for two technicians, no evidence of training sessions on code revs & revised page not signed off by QA manager.
CONWAY,J T , BARNES,I Region 4, Office of Director 83/02/17 8pp 17618:161

8303180366 Forwards QA Program Insp Rept 99900761/83-01 on 830124-28 & notice of nonconformance.
POTAPOVS,U Division of Vendor & Technical Programs 83/02/25
MORROW,R Reliance Electric Co 3pp 17620:052

--8303180372 Notice of nonconformance from insp on 830124-28.
* Region 4, Office of Director 83/02/25 1p 17620:055

--8303180381 QA Program Insp Rept 99900761/83-01 on 830124-28. Noncompliance noted failure to perform welder training until 821130 & failure to evaluate two calibr svcs suppliers.
OLLER,R E , BARNES,I Region 4, Office of Director 83/02/17 12pp 17620:056

8303180388 Forwards QA Program Insp Rept 99900904/82-02 on 831130-1203 & notices of nonconformance & violation. Insp dates vary throughout package.
POTAPOVS,U Division of Vendor & Technical Programs 83/02/25
MIGNOGNA,T Limitorque Corp 2pp 17622:224

--8303180390 Notice of violation from insp on 821130-1203.
* Region 4, Office of Director 83/02/25 1p 17622:226

--8303180394 Notice of nonconformance from insp on 821130-1203.
* Region 4, Office of Director 83/02/25 3pp 17622:227

--8303180399 QA Program Insp Rept 99900904/82-02 on 821130-1208. Noncompliance noted purchase orders issued to Isomedix & Action Environ Testing did not specify applicable provisions of 10CFR21 & QA program did not comply w/10CFR50, App B.
JOHNSON,A R , PHILLIPS,H S Region 4, Office of Director 83/02/18 19pp 17622:230

8303210366 Discusses QA Program Insp Repts 99900740/82-01 & 99900743/82-01 at Brown Boveri Electric, Inc. Corrective actions & preventive measures adequate. Capability & site calibr of devices questionable.
POTAPOVS,U Division of Vendor & Technical Programs VITS 81-019, 83/03/17 LEWIS,R C Division of Project & Resident Programs 2pp 17635:008

8303210395 Ack receipt of 830225 ltr informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 99900524/82-03.
POTAPOVS,U Division of Vendor & Technical Programs 83/03/14
DIRIENZO,P P Gibbs & Hill, Inc (subs of Dravo Corp.) 1p 17635:013

--8303210405 Responds to NRC 830128 ltr re nonconformances noted in QA Program Insp Rept 99900524/82-03. Corrective actions: stick files updated & drawing distribution list procedure revised.
DERIENZO,P P Gibbs & Hill, Inc (subs of Dravo Corp.) 83/02/25 POTAPOVS,U Division of Vendor & Technical Programs 4pp 17635:014

8303210404 Ack receipt of 830126 ltr informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 99900104/82-03.
POTAPOVS,U Division of Vendor & Technical Programs 83/03/14
MILLER,T D Westinghouse Electric Corp 1p 17634:324

--8303210411 Responds to NRC 830106 ltr re nonconformances noted in QA Program Insp Rept 99900104/82-03. Corrective actions: weld wire attendants reinstructed on oven use, steam generator CMTR reviewed & welding route sheet procedure reinforced.
MILLER,T D Westinghouse Electric Corp PA-83-013 83/01/28
POTAPOVS,U Division of Vendor & Technical Programs 4pp 17634:325

8303210420 Confirms QA program insp on 830425-29 at Oak Brook, IL re implementation of QA program per 830311 telcon.
POTAPOVS,U Division of Vendor & Technical Programs 83/03/17
BONIFACIO,A B W J Woolley Co 1p 17634:263

8303210457 Confirms QA program insp at Dickerson, MD plant on 830404-07, per 830311 telcon. Insp will relate to implementation of QA program.
POTAPOVS,U Division of Vendor & Technical Programs 83/03/17
RANSOHOFF,J Neutron Products, Inc 1p 17634:250

8303210482 Ack receipt of 830225 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900525/82-01.
POTAPOVS,U Division of Vendor & Technical Programs 83/03/14
MOERKE,N H Southwest Fabricating & Welding Co (subs of IU International Corp.) 1p 17631:317

--8303210492 Responds to NRC 830120 ltr re nonconformance noted in QA Program Insp Rept 99900025/82-01. Corrective actions: notice posted describing regulations & name of contact person.
MOERKE,N H Southwest Fabricating & Welding Co (subs of IU International Corp.) 83/02/25 POTAPOVS,U Division of Vendor & Technical Programs 12pp 17631:318

8303210514 Ack receipt of 830224 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900522/82-03.
POTAPOVS,U Division of Vendor & Technical Programs 83/03/17
STATTON,C D Bechtel Corp 1p 17632:291

--8303210524 Responds to NRC 830128 ltr re nonconformance noted in QA Program Insp Rept 99900522/82-03. Corrective actions: Spec 8856-M-213(Q) revised to include upgrade requirements for insp of prefabricated components.
STATTON, C. D. Bechtel Corp. 83/02/24. POTAPOVS, U. Division of Vendor & Technical Programs. 5pp. 17632:292.

8303210561 Confirms QA program insp at Los Angeles Power Div facility on 830328-0401 per 830308 telcon.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/03/17.
HINKELMAN, L. G. Bechtel Corp. 1p. 17632:272.

8303210601 Ack receipt of 830218 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900798/82-01.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/03/17.
HERD, R. Eberline Instrument Corp. 1p. 17636:288.

--8303210609 Responds to NRC 830120 ltr re nonconformance noted in QA Program Insp Rept 99900798/82-01. Corrective actions: QC dept will verify that both 10CFR21 & Section 206 of 1974 Energy Reorganization Act are posted.
HERD, R. Eberline Instrument Corp. EI-1198. 83/02/18.
POTAPOVS, U. Division of Vendor & Technical Programs. 3pp. 17636:289.

8303210618 Confirms 830311 telcon rescheduling insp of QA program implementation from 830328-31 to 830418-22.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/03/17.
SHIRLEY, N. G. General Electric Co. 1p. 17636:284.

8303210656 Ack receipt of 821206 & 830222 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900317/82-01.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/03/17.
STOLBA, F. B. Cooper Industries, Inc. 1p. 17635:213.

--8303210666 Responds to NRC 830131 ltr re nonconformance noted in QA Program Insp Rept 99900317/82-01. Corrective actions: all certificates of conformance will be signed by manager of QC, established by 821202 policy memo.
PATTERSON, C. H. Cooper Industries, Inc. QCQ-171. 83/02/22.
POTAPOVS, U. Division of Vendor & Technical Programs. 2pp. 17635:214.

--8303210672 Ack receipt of 821206 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900317/82-01. Addl info re nuclear policy for spare parts requested.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/01/31.
STOLBA, F. B. Cooper Industries, Inc. 8pp. 17635:216.

--8303210677 Responds to NRC 821112 ltr re nonconformance noted in QA Program Insp Rept 99900317/82-01. Corrective actions: proper documentation & 10CFR21 posted on all bulletin boards in Mt Vernon & Grove City facilities.
PATTERSON, C. H. Cooper Industries, Inc. 82/12/06. POTAPOVS, U. Division of Vendor & Technical Programs. 5pp. 17635:224.

8303210681 Ack receipt of 830113 ltr informing NRC of steps taken to correct violation & nonconformances noted in QA Program Insp Rept 99900323/82-01.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/03/14.
ADAMS, J. Conax Corp. 1p. 17635:277.

--8303210690 Responds to NRC 821217 ltr re violation & nonconformances noted in QA Program Insp Rept 99900323/82-01. Corrective actions: personnel reinstructed on importance of using CONAX MDR in accordance w/established procedures.
DUROURE, R. L. Conax Corp. 83/01/13. POTAPOVS, U. Division of Vendor & Technical Programs. 2pp. 17635:278.

8303280160 Closes out AITS F02700199 re 821115-18 insp of NDE codes on hanger drawings supplied to TVA. Insp results contained in attached QA Program Insp Rept 99900285/82-02. W/o encl.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/03/24.
LEWIS, R. C. Division of Project & Resident Programs. 1p. 17709:265.

8303280163 Forwards QA Program Insp Rept 99900285/82-02 on 821115-18 & notice of violation. Statement addressing circumstances & reasons for not performing formal evaluation of dimensional condition per 10CFR21 requested.
COLLINS, J. T. Region 4, Office of Director. 83/03/08. SEWELL, D. M. ITT Grinnell (subs. of ITT). 3pp. 17709:220.

--8303280167 Notice of violation from insp on 821115-18.
* Region 4, Office of Director. 83/03/08. 1p. 17709:223.

--8303280171 QA Program Insp Rept 99900285/82-02 on 821115-18. Noncompliance noted: dimensional conditions not formally evaluated. Other purchasers of similarly affected units not notified.
ELLERSHAW, L. E., BARNES, I. Region 4, Office of Director. 83/01/20. 9pp. 17709:224.

8303280165 Forwards QA Program Insp Rept 99900285/82-02 for possible issuance of bulletin or circular for violation re failure of ITT Grinnell to evaluate nonconforming dimensional condition. W/o encl.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/01/26.
BAER, R. L. Division of Engineering & Quality Assurance (Pre 830103). 2pp. 17706:319.

8303280198 Notifies that AIS F01700075 re 830110-14 insp of mixed diameter electrodes at Unibraze Corp closed. Insp results contained in attached QA Program Insp Rept 99900793/83-01. W/o encl.
POTAPOVS, U. Division of Vendor & Technical Programs. VTIS 81-122. 83/03/24. LEWIS, R. C. Division of Project & Resident Programs. 1p. 17709:219.

8303280205 Forwards QA Program Insp Rept 99900793/83-01 on 830110-14 & notices of nonconformance & violation.
POTAPOVS, U. Region 4, Office of Director. 83/02/28. MACBRYDE, M. B. Unibraze Corp. 2pp. 17708:196.

--8303280209 Notice of violation from insp on 830110-14.
* Region 4, Office of Director. 83/02/28. 1p. 17708:198.

--8303280213 Notice of nonconformance from insp on 830110-14.
* Region 4, Office of Director. 83/02/28. 2pp. 17708:199.

--8303280222 QA Program Insp Rept 99900793/83-01 on 830110-14. Noncompliance noted: two vendors performing testing svcs neither surveyed nor audited by licensee & reels of wire not identified w/tag containing required info.
CONWAY, J. T., BARNES, I. Region 4, Office of Director. 83/02/17. 7pp. 17708:201.

8303280305 Forwards QA Program Insp Rept 99900907/83-01 on 830110-14 & notices of nonconformance & violation.
POTAPOVS, U. Region 4, Office of Director. 83/03/09. TRAW, W. L. National Technical Systems. 2pp. 17706:165.

--8303280308 Notice of violation from insp on 830110-14.
* Region 4, Office of Director. 83/03/09. 1p. 17706:167.

--8303280314 Notice of nonconformance from insp on 830110-14.
* Region 4, Office of Director. 83/03/09. 3pp. 17706:168.

--8303280320 QA Program Insp Rept 99900907/83-01 on 830110-14. Noncompliance noted: current version of 10CFR21 not posted, data sheets on Master Job Order 548-9247 not signed by test technician & std operating procedures not reviewed.
HUBBARD, G. T., PHILLIPS, H. S. Region 4, Office of Director. 83/03/04. 14pp. 17706:171.

8303290205 Confirms WM McNeil 830214 telcon re 830418-22 insp at Wilmington, NC. Inspectors will be WM McNeil & insp will relate to implementation of QA program.
POTAPOVS, U. Region 4, Office of Director. 83/03/25. LONG, J. A. General Electric Co. 1p. 17724:020.

8303290288 Confirms 830304 telcon re insp at Seabrook, NH plant on 830404-08. Insp team members listed. Insp will relate to implementation of QA program for equipment qualification testing of safety-related equipment.
POTAPOVS, U. Region 4, Office of Director. 83/03/25. HILBERG, H. P. D. G. O'Brien, Inc. 1p. 17716:128.

8303290294 Confirms QA insp on 830328-31 at Cambridge, MA plant per 830321 telcon. Insp will relate to errors reported in ADLPIPE Computer Code.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/03/25.
DINGWELL, I. W. DIS/ADLPIPE, Inc. 1p. 17716:177.

8303290352 Confirms QA program insp at Huntsville, AL plant on 830329-0401 per 830309 telcon. Insp will examine equipment qualification testing of safety-related equipment.
POTAPOVS, U. Division of Vendor & Technical Programs. 83/03/25.
SMITH, E. W. Wyle Laboratories. 1p. 17716:167.

8303290372 Confirms QA program insp on 830404-08 at Lynchburg, VA plant per 830224 telcon.
POTAPOVS, U. Region 4, Office of Director. 83/03/25. PRYOR, C. W. Babcock & Wilcox Co. 1p. 17716:196.

REGGD REGULATORY GUIDES

8303020087 Comments on draft reg guide,Task MS 146-4, "Design, Installation & Insp of Seepage Control Liners at U Recovery Facilities."
SHELLEY,W J Kerr-McGee Corp 83/02/14 Docketing & Services Branch 1p 17352:158

8303020092 Comments on proposed Rev 1 to Reg Guide 5.59 (Task SG 229-4) Public disclosure,Page XV should be revised to cite 10CFR73.
BRADBURY,R B Stone & Webster Engineering Corp 83/02/18 Docketing & Services Branch 1p 17349:005

8303180006 Reg Guide 5.59,Rev 1 Task SG 229-4, "Std Format & Content for Licensee Physical Security Plan for Protection of SNM of Moderate or Low Strategic Significance."
* Office of Nuclear Regulatory Research, Director 83/02/28 37pp 17624:245

8303240156 Forwards draft proposed reg guide,Task RS 801-4, "Periodic Testing of Torque Protected Motor Operated Valves Important to Safety," Draft rept does not necessarily represent NRC position
WENZINGER,E C Instrumentation & Control Branch 83/03/11
FOUREST,B France 1p 17698:202

RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

8303010687 "Definition of Scenarios & Evaluation of Methods for Analyzing Source Terms of Major Accidents Involving U Hexafluoride at NRC-Licensed Fuel Cycle Facilities," monthly progress rept for Jan 1983
SIMAN-TOV,M Union Carbide Corp FIN B-0495 83/02/23
BERNSTEIN,S Transportation & Materials Risk Branch 3pp 17348:345

8303030318 "Program for Standardized Analysis of Fuel Shipping Containers," quarterly summary for Jan-Mar 1978
WHITESIDES,G E Oak Ridge National Laboratory ORNL/CSD/INF-78-78/04/11 NRC - No Detailed Affiliation Given 9pp 17365:158

8303030720 "ORNL Projects for NRC Ofc of Nuclear Regulatory Research," monthly highlights rept
LOTTS,A L Oak Ridge National Laboratory 83/01/31 Office of Nuclear Regulatory Research, Director 11pp 17364:189

8303040104 "Thermal-Hydraulic Reactor Safety Experiments," monthly highlight ltr for Jan 1983
GINSBERG,T , GREENE,G A Brookhaven National Laboratory FIN A-3024 83/01/31 CURTIS,R T Division of Accident Evaluation 4pp 17425:027

8303040122 "LWR Plant Analyzer Development," monthly highlight ltr for Jan 1983
WULFF,W Brookhaven National Laboratory FIN A-3227 83/01/31
SULLIVAN,L H Division of Accident Evaluation 4pp 17425:075

8303040138 "Stress Corrosion Cracking of PWR Steam Generator Tubing," monthly highlights for Jan 1983
VAN ROOYEN,D Brookhaven National Laboratory 83/02/16 TABOADA,A Office of Nuclear Regulatory Research, Director 5pp 17425:052

8303040155 "SSC Development,Validation & Application" & "CRBR Balance of Plant Modeling," monthly highlights for Jan 1983
GUPPY,J G Brookhaven National Laboratory FIN A-3041 83/01/11
CURTIS,R T Severe Accident Assessment Branch 8pp 17425:031

8303040170 "HTGR Safety Program," monthly highlights ltr for Jan 1983
BASTRE,C Brookhaven National Laboratory FIN A-3016 83/02/17
FOULDS,R Office of Nuclear Regulatory Research, Director 4pp 17426:355

8303040186 "LWR Code Assessment & Application," monthly highlight ltr
SAHA,P Brookhaven National Laboratory FIN A-3215 83/01/31
ODAR,F Analytical Models Branch 5pp 17427:024

8303090531 "Properties of Radwaste & Waste Containers," quarterly progress rept,Oct-Dec 1982
ARORA,H , DAYAL,R Brookhaven National Laboratory FIN A-3027 83/02/28 KIM,K Office of Nuclear Regulatory Research, Director 18pp 17482:343

8303090555 "Physical Adsorption of Gases on HTGR Graphites," informal rept
GROWCOCK,F B , RIVERA,E Brookhaven National Laboratory FIN A-3016 82/12/31 FOULDS,R NRC - No Detailed Affiliation Given 120pp 17479:233

8303090564 "Container Assessment-Corrosion Study of HLW Container Matls," quarterly progress rept,Oct-Dec 1982
AHN,T K , JAIN,H , SOO,P Brookhaven National Laboratory FIN A-3237 83/01/31 MCNEIL,M Waste Management Branch 27pp 17480:013

8303090569 "Source Term Studies at Shallow Land Burial Sites," quarterly progress rept,Oct-Dec 1982
DAYAL,R , ARORA,H Brookhaven National Laboratory FIN A-3042 83/02/28 BIRCHARD,G Division of Health, Siting & Waste Management 15pp 17480:045

8303090577 "Properties of Solidified Decontamination Wastes," quarterly progress rept,Oct-Dec 1982
DAVIS,M S , DAYAL,R Brookhaven National Laboratory FIN A-3253 83/01/31 MCNEIL,M Waste Management Branch 1p 17480:131

8303090608 "Characterization of TMI Type Wastes & Solid Products," quarterly progress rept,Oct-Dec 1982
SWYLER,K J , DAYAL,R Brookhaven National Laboratory FIN A-3236 83/01/31 KIM,K Office of Nuclear Regulatory Research, Director 27pp 17477:043

8303090616 "Decontamination Impacts on Solidification & Waste Disposal," quarterly progress rept,Oct-Dec 1982
DAVIS,M G , BOWERMAN,B S Brookhaven National Laboratory FIN A-3246 BNL-NUREG-32548 83/01/31 CARDILE,F P Chemical Engineering Branch 20pp 17481:152

8303090627 Speech entitled, "Shape Reactivity in Rod Ejection Accident," presented at 1983 Annual ANS 830612-17 meeting in Detroit,MI
NEDDY,P , CAREW,J F Brookhaven National Laboratory BNL-NUREG-32506 83/03/04 9pp 17480:286

8303100121 "Environ Assessment of Fuel Cycle Facilities," monthly progress rept for Dec 1982
KELLY,M J Oak Ridge National Laboratory FIN B-0279 ORNL/ED/EIS-181 82/12/31 GNUGNOLI,G N Uranium Recovery Licensing Branch 9pp 17496:165

8303100136 "Environ Survey of Nuclear Metals,Inc,Concord,MA," final rept
ROCCO,B P Oak Ridge National Laboratory FIN A-9090 83/02/28 Uranium Fuel Licensing Branch 80pp 17496:233

8303110118 "Experimental Evaluation of Ventilation Sys Components During Large-Pressure Pulses," monthly status rept for Jan 1983
GREGORY,W S Los Alamos Scientific Laboratory FIN A-7028 G-6-771 (R295) 83/01/31 SOLBERG,D E Transportation & Materials Risk Branch 6pp 17526:101

8303110597 "PWR Steady-State Capability of Wrap-A Water Reactor Analysis Package."
SHARP,D A Savannah River Laboratory DPST-NUREG-77-3 77/06/30 NRC - No Detailed Affiliation Given 20pp 17523:075

8303150615 "Environmentally Assisted Cracking in LWR Sys," monthly progress rept for Jan 1983
SHACK,W J , KASSNER,T F , KUPPERMAN,D Argonne National Laboratory FIN A-2212 83/03/07 MUSCARA,J Materials Engineering Branch 18pp 17584:229

8303160155 "Addition of ANS 1979 Std Decay Heat to RELAP5," internal technical rept
WAGNER,R J , HOWE,T M EG&G, Inc WR-NSMD-83-003 83/01/31 NRC - No Detailed Affiliation Given 18pp 17614:283

8303160164 "Addition of Components to RELAP5 Control Sys," internal technical rept
WAGNER,R J , HOWE,T M EG&G, Inc WR-NSMD-83-001 83/01/04 NRC - No Detailed Affiliation Given 21pp 17614:261

8303160175 "Investigation of Accident-Induced Flow & Matl Transport in Nuclear Facilities," informal monthly progress rept for Jan 1983
MARTIN,R A , GREGORY,W S Los Alamos Scientific Laboratory FIN A-7029 83/02/28 BERSTEIN,S Transportation & Materials Risk Branch 7pp 17614:254

8303160183 "BWR Thermohydraulics Simulation on AD-10 Peripheral Processor."
WULFF,W , CHENG,H S , LEKACH,S V Brookhaven National Laboratory BNL-NUREG-32501 83/03/10 NRC - No Detailed Affiliation Given 6pp 17614:248

8303160687 "Measurements & Analysis of Steam Generation Rate From Quenching of Superheated Debris Beds."
GINSBERG, T., KLEIN, T., KLAGES, J. Brookhaven National Laboratory
BNL-NUREG-32496 83/03/10 NRC - No Detailed Affiliation Given
7pp 17600:259

8303160758 Speech entitled "Guidance for Air Sampling at LWRs," to be presented at tenth water reactor safety research info meeting on 821012-15
JOHNSON, L. J., RICH, B. L., RITTER, P. D. EG&G, Inc EGG-M-21582
82/10/12 10pp 17600:217

8303180549 "Proof-of-Principle Tests for Concreting Incinerated Simulated TRU Waste."
GIBSON, G. W., BEAN, C. H. EG&G, Inc EGG-WM-5987 82/09/30 NRC - No Detailed Affiliation Given 37pp 17639:287

8303180555 "Post-Test Analysis of LOFT Anticipated Transient Experiments L6-1, L6-2, L6-3 & L6-5," interim rept
OLLIKKALA, H., BEHLING, S. R. EG&G, Inc FIN A-6048 EGG-LOFT-6159
83/01/31 MCPHERSON, G. D. NRC - No Detailed Affiliation Given
49pp 17639:331

8303180556 "ORNL Projects for NRC RES," monthly highlights rept for Feb 1983
LOTTS, A. L. Oak Ridge National Laboratory 83/02/28 Office of Nuclear Regulatory Research, Director 76pp 17638:109

8303180568 "ENDRAFL: ENDF/B Multigroup Cross Section Libraries for Raffle Monte Carlo Code."
GRIMESEY, R. A., MILLSAP, D. A., JOHNSON, J. R. EG&G, Inc EGG-PHYS-6149
82/12/31 NRC - No Detailed Affiliation Given 85pp 17637:323

8303180579 "Evaluation Procedures for Testing Class IE Analog Isolation Amplifiers," informal rept
NIELSON, J. R. EG&G, Inc FIN A-6370 EGG-EE-6136 82/12/17
BOEM, D. W. Office of Nuclear Regulatory Research, Director 71pp 17640:047

8303180613 "TRAC-BD1 Loss Coefficient & Two-Phase Friction Model," internal technical rept
GILES, M. M., WEAVER, W. L. EG&G, Inc WR-NSMD-82-082 82/12/31
NRC - No Detailed Affiliation Given 26pp 17637:152

8303180672 "TRAC-BWR Completion Rept Feedwater Heater," internal technical rept
MOHR, C. M., WEAVER, W. L. EG&G, Inc WR-CD-82-074 82/09/30 NRC - No Detailed Affiliation Given 31pp 17637:090

8303180674 "Evaluation Procedures for Testing Class IE Digital Isolators," informal rept
NIELSON, J. R. EG&G, Inc FIN A-6370 EGG-EE-6137 83/01/31
BOEHM, D. W. Office of Nuclear Regulatory Research, Director 68pp 17637:022

8303180694 "RELAP5 Ref Calculation for LOFT Experiment L6-7/L9-2," interim rept
CONDIE, K. G. EG&G, Inc FIN A-6048 EGG-LOFT-6014 83/01/31
MCPHERSON, G. D. Experimental Programs Branch 54pp 17637:268

8303180696 "Monthly Rept Representing Research Portion of Water Reactor Research Dept & Thermal Fuels Behavior Program."
DEARIEN, J. A. EG&G, Inc EGG-WRR-6157 82/12/31 NRC - No Detailed Affiliation Given 250pp 17626:052

8303180699 "Dynamic Dimensioning & Storage Improvements for TRAC-BD1," internal technical rept
SINGER, G. L., WEAVER, W. L., PETERSON, A. C. EG&G, Inc WR-NSMD-83-002
83/01/31 NRC - No Detailed Affiliation Given 82pp 17637:178

8303210186 Revised "TRAC-BWR Completion Rept, Noncondensible Gas Model," internal technical rept
WEAVER, W. L. EG&G, Inc WR-CD-82-062 83/01/31 NRC - No Detailed Affiliation Given 40pp 17659:072

8303210776 "Effect of Prior Circulation Coolings on Thermohydraulics of HTGR Primary Loop During Core Heat-up Accidents," informal rept
HSU, C. J., KROEGER, P. G., COLMAN, J. Brookhaven National Laboratory
FIN A-3016 BNL-NUREG-32520 82/11/30 FOULDS, R. NRC - No Detailed Affiliation Given 47pp 17640:292

8303240137 "Pulsed Eddy Current Testing of Zircaloy Tube Samples From OECD Halden Reactor Project," test results rept
COOK, B. A., YANCEY, M. E. EG&G, Inc FIN A-6041 EGG-TFBP-6179
83/02/28 VANLTOUTEN, R. NRC - No Detailed Affiliation Given 24pp 17698:316

8303240140 "Stress Analysis for FIST Piping Sys," technical rept
FORS, R. M. EG&G, Inc FIN A-6039 EGG-EA-5863 82/09/31
BECKNER, W. D. NRC - No Detailed Affiliation Given 78pp 17699:135

8303240144 "RELAP5/MOD1 Code Manual Vol 3: Checkout Problems Summary," informal technical rept
RIEMKE, R. A., CHOW, H., RANSOM, V. H. EG&G, Inc FIN A-6330
EGG-NSMD-6182 83/02/28 NRC - No Detailed Affiliation Given 134pp 17699:001

8303240146 "Monthly Rept Representing Research Portion of Water Reactor Research Dept & Thermal Fuels Behavior Program."
DEARIEN, J. A., WILLIAMS, B. E. EG&G, Inc EGG-WRR-6166 83/01/31
NRC - No Detailed Affiliation Given 149pp 17696:008

8303240167 "Preliminary Assessment of Backfitting Criteria for Digital Control & Protection Sys (Task 6)," technical rept
WILDE, N. EG&G, Inc FIN A-6370 EGG-EE-6060 82/09/30 NRC - No Detailed Affiliation Given 19pp 17698:182

8303240275 "Preliminary Experiment Operating Spec for Semiscale MOD-2B Steam Generator Tube Rupture Experiment Series."
MARTINEZ, L. J. EG&G, Inc FIN A-6C30 EGG-SEMI-6176 83/02/28
LANDRY, R. R. NRC - No Detailed Affiliation Given 46pp 17695:324

8303280329 "FRAP-T6 Analysis of Pellet Cladding Mechanical Interaction," informal technical rept
SHAH, V. N. EG&G, Inc FIN A-6050 EGG-NSMD-6155 83/02/28 NRC - No Detailed Affiliation Given 43pp 17713:159

8303290786 "Assessment of TRAC Codes w/Dartmouth College Counter-Current Flow Tests."
ROHATGI, U. S. Brookhaven National Laboratory BNL-NUREG-32585
83/01/31 NRC - No Detailed Affiliation Given 6pp 17748:186

8303290792 "Stress Corrosion Cracking of PWR Steam Generator Tubing," monthly highlights for Feb 1983
VAN ROOYEN, D. Brookhaven National Laboratory 83/02/28 NRC - No Detailed Affiliation Given 4pp 17748:176

8303290804 "HTGR Safety Program," monthly highlights ltr for Feb 1983
SASTRE, C. Brookhaven National Laboratory FIN A-3016 83/03/17
NRC - No Detailed Affiliation Given 4pp 17748:089

8303290824 "LWR Core Assessment & Application," monthly highlight ltr for Feb 1983
SAHA, P. Brookhaven National Laboratory FIN A-3215 83/02/28
ODAR, F. Analytical Models Branch 3pp 17748:064

8303290862 "LWR Plant Analyzer Development," monthly highlight ltr for Feb 1983
WULFF, W. Brookhaven National Laboratory FIN A-3227 83/02/28
SULLIVAN, L. H. Division of Accident Evaluation 5pp 17745:201

8303300103 "Summary Rept Temp Condensate Pressure Transducer for LOFT Sys 87."
BILLETER, T. R. EG&G, Inc FIN A-6107 EGG-LOFT-6186 83/03/01
NRC - No Detailed Affiliation Given 54pp 17753:157

8303300154 "Evaluation of SRV Pipe Failure Rates via Probabilistic Mechanical Design."
LEHNER, J. R., ECONOMOS, C. Brookhaven National Laboratory
BNL-NUREG-32558 83/03/29 NRC - No Detailed Affiliation Given 12pp 17749:300

8303300178 "Accident Aerosol Characterization," monthly progress rept for Jan 1983
OWCZARSKI, P. C. Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2287 83/03/18 Regulatory Analysis Branch 6pp 17754:356

8303300421 "Determining Lateral Load Spec for Downcomers During Chugging in Mark II Containment."
LEHNER, J. R. Brookhaven National Laboratory SONIN, A. A. Massachusetts Institute of Technology BNL-NUREG-32586 83/03/29
NRC - No Detailed Affiliation Given 10pp 17753:328

8303300427 "Chemical Changes in Radiation Damaged Natural Rock Salt: Preliminary Results," interim repts
PANNO, S. V. Brookhaven National Laboratory FIN A-3167
BNL-NUREG-32523 82/12/31 WIEK, E. A. High Level Waste Licensing Management Branch 18pp 17754:017

8303300571 "Analysis of FLECHT-SEASET Steam Generator Tests w/ RAC-PF1 & RELAP5/MOD1."
SLOVIK, G., SAHA, P. Brookhaven National Laboratory BNL-NUREG-32574
83/01/31 NRC - No Detailed Affiliation Given 6pp 17748:305

8303300578 "Thermal-Hydraulic Reactor Safety Experiments," monthly highlights ltr for Feb 1983.
QINSBERG, T., GREENE, G.A. Brookhaven National Laboratory FIN A-3024. 83/02/28. CURTIS, R.T. Division of Accident Evaluation. 4pp. 17748:301.

8303300606 "Environ Assessments of Fuel Cycle Facilities," monthly progress rept for Jan 1983.
KELLY, M.J. Oak Ridge National Laboratory FIN B-0279. ORNL/ED/EIS-182. 83/01/31. ONUGNOLI, G.N. Uranium Recovery Licensing Branch. 5pp. 17766:350.

8303300623 "Task 7 in Support of NRC on ASME Boiler & Pressure Vessel Code Section XI Activities-Exam & Testing of Supports," informal technical rept.
BLANDFORD, R.K. EG&G, Inc. FIN A-6367. EGG-EA-5908. 83/03/31. BAKER, E.T. Office of Nuclear Regulatory Research, Director. 48pp. 17768:099.

8303300632 "Definition of Scenarios & Evaluation of Methods for Analyzing Source Terms of Major Accidents Involving U Hexafluoride at NRC-Licensed Fuel Cycle Facilities," monthly progress rept for Feb 1983.
SIMAN-TOV, M. Union Carbide Corp. FIN B-0495. 83/03/11. BERNSTEIN, S. Transportation & Materials Risk Branch. 4pp. 17767:007.

8303300642 "BWR/4 Loss of Feedwater Transient Analysis."
LU, M.S., LEVINE, M.M., SHIER, W.G. Brookhaven National Laboratory. FIN A-3350. BNL-NUREG-32576. 83/01/31. NRC - No Detailed Affiliation Given. 7pp. 17770:234.

8303300667 "Accident Aerosol Characterization," monthly progress rept for Feb 1983.
OWCZARSKI, P.C. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2287. 83/03/22. BERNSTEIN, S. Division of Risk Analysis. 5pp. 17768:148.

8303310068 "SSC Development, Validation & Application," & "CRBR Balance-of-Plant Modeling," monthly highlights for Feb 1983.
QUPPY, J.G. Brookhaven National Laboratory. FIN A-3041. 83/03/09. CURTIS, R.T. Severe Accident Assessment Branch. 8pp. 17775:320.

REVIEW GRP NRC RESEARCH REVIEW GROUPS

8303020178 Notification of CRGR 830309 Meeting 33 in Bethesda, MD to discuss proposed rule 10CFR53 & findings re resolution of Unresolved Safety Issue A-1, "Water Hammer."
STELLO, V. Committee to Review Generic Requirements. 83/02/25. EISENHUT, D.G. Office of Nuclear Reactor Regulation, Director. JORDAN, E.L. Director's Office, Office of Inspection and Enforcement. CUNNINGHAM, R.E. Office of Nuclear Material Safety & Safeguards, Director. 201pp. 17358:294.

8303090183 FOIA request for recently issued risk policy.
LEE, D.E. Affiliation Unknown. 83/01/14. FELTON, J.M. Division of Rules and Records. 1p. 17465:066.

8303090187 Responds to FOIA request for recently issued risk policy. Forwards NUREG-0880, "Safety Goals for Nuclear Power Plants: Discussion Paper," & JE Zerbe 830111 memo re safety goal policy statement.
FELTON, J.M. Division of Rules and Records. 83/02/04. LEE, D.E. Affiliation Unknown. 1p. 17465:067.

--8303090193 Forwards policy statement on safety goals for operation of nuclear power plants, revised at Commission 830110 meeting. Final revs indicated on 830107 marked-up draft.
ZERBE, J.E. Office of Policy Evaluations. 83/01/11. PALLADINO, N.J., GILINSKY, V., AHEARNE, J.F. Commissioners. 28pp. 17465:140.

8303090621 Transcript of 830225 meeting in Washington, DC re administrative package. Pp 1-187.
* Commissioners. * Ad Hoc Committee for Review of Nuclear Reactor Reform Proposals. 83/02/25. 205pp. 17480:306.

8303110004 Forwards "Summary of CRGR Activities from Nov 1981 - Feb 1983."
SCHWINK, W. Committee to Review Generic Requirements. 83/03/03. Committee to Review Generic Requirements. 1p. 17569:034.

--8303110008 "Summary of CRGR Activities from Nov 1981 - Feb 1983."
* Committee to Review Generic Requirements. 83/02/28. 25pp. 17569:035.

8303110054 Advises that encl IE Bulletin 83-01 re failure of reactor trip breakers to open on automatic trip signal issued as emergency action w/o CRGR review. Comments will be addressed following CRGR 830309 Meeting 33.
STELLO, V. Committee to Review Generic Requirements. IEB-83-01. 83/03/03. EISENHUT, D.G. Office of Nuclear Reactor Regulation, Director. JORDAN, E. Director's Office, Office of Inspection and Enforcement. CUNNINGHAM, R. Office of Nuclear Material Safety & Safeguards, Director. 1p. 17526:354.

8303140236 Forwards Pp ii & 3.1-1 to revised nonproprietary version of "Util Design Review Panel Evaluation Rept, D2/D3 Steam Generator Design Mod," inadvertently omitted from 830302 transmittal.
BLACKLEY, S.K. Design Review Panel. 83/03/10. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. EISENHUT, D.G. Division of Licensing. 2pp. 17539:007.

--8303140241 Pp ii & 3.1-1 to revised nonproprietary version of "Util Design Review Panel Evaluation Rept, D2/D3 Steam Generator Design Mod."
* Design Review Panel. 83/01/31. 2pp. 17539:008.

8303140257 Forwards revised nonproprietary version of "Util Design Review Panel Evaluation Rept, D2/D3 Steam Generator Design Mod." Rept originally submitted on 830119.
BLACKLEY, S.K. Design Review Panel. 83/03/02. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 17534:269.

--8303140264 Revised nonproprietary version of "Util Design Review Panel Evaluation Rept, D2/D3 Steam Generator Design Mod."
* Design Review Panel. 83/01/31. 120pp. 17534:270.

8303140702 Staff requirements memo re 830304 briefing in Washington, DC on CRGR activities.
CHILK, S.J. Office of the Secretary of the Commission. M830304A. 83/03/04. DIRCKS, W.J. Office of the Executive Director for Operations. 1p. 17569:172.

8303150044 Designates W Minners as NRR representative to safety goal evaluation plan steering group.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 83/03/07. DIRCKS, W.J. Office of the Executive Director for Operations. 1p. 17611:197.

--8303150052 Requests name of representative to safety goal evaluation plan steering group by 830304.
DIRCKS, W.J. Office of the Executive Director for Operations. 83/03/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. DAVIS, J.G. Office of Nuclear Material Safety & Safeguards, Director. 1p. 17611:198.

8303150150 Transcript of 830304 briefing in Washington, DC re CRGR activities. Pp 1-85. Computer printout encl.
* Commissioners. 83/03/04. 118pp. 17599:345.

8303160595 Provides summary & assessment of CRGR activities to date. Printout summarizing CRGR activities Nov 1981 - Feb 1983 encl.
MURLEY, T.E. Regional Operations & Generic Requirements. 83/02/28. STELLO, V. Regional Operations & Generic Requirements. 28pp. 17587:169.

8303220025 Summary of CRGR 830309 Meeting 31 re proposed IE Bulletin 83-01. Bulletin provides summary of history of pipe cracks in BWR recirculation sys found as result of insp performed since issuance of IE Bulletin 82-03. Issuance recommended.
STELLO, V. Regional Operations & Generic Requirements. IEB-83-01. 83/02/25. DIRCKS, W.J. Office of the Executive Director for Operations. 5pp. 17652:144.

8303220078 Summary of CRGR 830217 Meeting 32 re proposed revs to 10CFR50.72 (immediate notification requirements) & 10CFR50.73 (LER rule).
STELLO, V. Regional Operations & Generic Requirements. 83/03/14. DIRCKS, W.J. Office of the Executive Director for Operations. 6pp. 17652:204.

8303220443 Informs that IE Bulletin 83-04 "Failure of Undervoltage Trip Function of Reactor Trip Breakers," was issued without CRGR review.
STELLO, V. Regional Operations & Generic Requirements. IEB-83-04. 83/03/16. EISENHUT, D.G. Division of Licensing. JORDAN, E.L. Director's Office, Office of Inspection and Enforcement. CUNNINGHAM, R.E. Office of Nuclear Material Safety & Safeguards, Director. 1p. 17670:339.

8303240054 Responds to 830117 memo re backfitting impact costs & procedures Quad Cities Units 1 & 2 chosen as typical two-unit station to represent NRC methods per request.
DIRCKS, W. J. Office of the Executive Director for Operations
83/03/15 TOURTELLOTTE, J. Regulatory Reform Task Force 7pp
17693:347

--8303180156 Forwards Antitrust & Economic Analysis Section comments in response to Question 7 of JR Tourtellotte 830117 memo re backfitting impact costs.
JOHNSTON, W. V. Assistant Director for Matls, Chem & Environ Technology (Post 830201) 83/03/01 PURPLE, R. A. Division of Licensing 2pp 17693:354

--8303240063 Forwards Cost Analysis Group, "Review of Nuclear Power Plant Backfitting & Regulatory Impact Costs," per 830216 request for response to Question 7 of J Tourtellotte 830117 memo.
TRINER, E. G. Division of Budget & Analysis 83/03/01 PURPLE, R. A. Assistant Director for Licensing 1p 17693:356

--8303240069 "Review of Nuclear Power Plant Backfitting & Regulatory Impact Costs."
* Division of Budget & Analysis 83/02/28 6pp 17693:357

--8303240076 Submits seven questions re encl analysis outlining actual costs of backfitting at nuclear power plants Response requested by 830201. W/o stated encl.
TOURTELLOTTE, J. Regulatory Reform Task Force 83/01/17
DIRCKS, W. J. Office of the Executive Director for Operations 2pp
17694:001

--8303240081 Requests independent evaluation of encl analysis outlining costs of backfitting plants Response requested by 830201. W/o stated encl.
TOURTELLOTTE, J. Regulatory Reform Task Force 83/01/17
ZERBE, J. E. Office of Policy Evaluations 1p 17694:003

--8303240087 Forwards cost figures & analyses re backfitting in response to several requests made in course of meeting w/industry representatives Financial impacts substantial. Backfitting pervasive regulatory problem.
TOURTELLOTTE, J. Regulatory Reform Task Force 83/01/17
PALLADINO, N., GILINSKY, V., AHEARNE, J. Commissioners 33pp
17694:004

--8302170236 Responds to 830117 memo re backfitting impact costs Deadline extended until 830304.
EISENHUT, D. G. Division of Licensing 83/02/01 TOURTELOTTE, J. Regulatory Reform Task Force 1p 17694:037

8303240109 Advises that CRGR concurs w/planned actions described in encl 830228 memo re Unresolved Issue A-43, "Containment Emergency Sump Performance." Package issued for public comment should include listed items.
STELLO, V. Regional Operations & Generic Requirements 83/03/16
DENTON, H. Office of Nuclear Reactor Regulation, Director 1p
17693:334

--8303020161 Responds to CRGR comments on proposed resolution of Unresolved Safety Issue A-43, "Containment Energy Sump Performance." NRR will perform addl analyses re need for backfit actions to assess fibrous insulation usage.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director
83/02/28 STELLO, V. Regional Operations & Generic Requirements
6pp 17693:335

8303250127 Summary of CRGR Meeting 33 on 830309 in Bethesda, MD re proposed rule 10CFR50, "Criteria & Procedures for Determining Adequacy of Spent Nuclear Fuel Storage Capacity" & Unresolved Safety Issue A-1. Recommends mods.
STELLO, V. Regional Operations & Generic Requirements 83/03/14
DIRCKS, W. J. Office of the Executive Director for Operations 5pp
17700:328

8303290602 Forwards transcript of Ad Hoc Committee for Review of Nuclear Reactor Licensing Proposals 830317 fourth meeting on administrative proposals in Washington, DC.
* Office of the Secretary of the Commission 83/03/21
PALLADINO, N. J., GILINSKY, V., AHEARNE, J. Commissioners 1p
17740:059

--8303290609 Transcript of Ad Hoc Committee for Review of Nuclear Reactor Licensing Proposals 830317 fourth meeting on administrative proposals in Washington, DC. Pp. 1-207.
* Ad Hoc Committee for Review of Nuclear Reactor Reform Proposals
83/03/17 226pp 17740:060

SECY POSITION PAPERS BEFORE THE COMMISSION

8302160113 SECY-83-016A
Revises regulations to obtain Commission approval re proposed & interim final regulations implementing legislation authorizing issuance of temporary OLs & requested OL amends involving no significant hazards.
DIRCKS, W. J. Office of the Executive Director for Operations
83/02/01 128pp 17427:168

8303090398 Final response to FOIA request for SECY-82-39A, 82-197, 82-197A & 82-197B. Forwards SECY-82-39A & SJ Chilk 820616 memo. SECY-82-39A placed in PDR.
FELTON, J. M. Division of Rules and Records 83/02/23 GRABER, L. Affiliation Unknown 1p 17477:112

--8205270445 SECY-82-039A
Forwards revised charter of CRGR for approval. CRGR will be directed to address nuclear plant equipment qualification, QA in nuclear plants, NRC policy on severe accidents, NRC safety goal implementation & TMI action plan requirements.
DIRCKS, W. J. Office of the Executive Director for Operations
82/04/29 25pp 17477:115

8303090429 Responds to FOIA request for documents re legal reviews of interim OL provision & effect of provision on technical assistance support programs. Forwards SECY-83-16 & erratum.
General Counsel 810923 memo withheld (ref FOIA Exemption 5).
FELTON, J. M. Division of Rules and Records 83/02/17 HAFNER, B. Affiliation Unknown 2pp 17477:142

--8301270005 SECY-83-016 ERR
Corrected Page 27 to SECY-83-16.
CHILK, S. J. Office of the Secretary of the Commission 83/01/18
2pp 17477:144

8303230132 Addl response to FOIA request for five categories of documents. Forwards SECY-82-87, SECY-82-396 & SECY-82-396A, identified as Item 1 of request.
FELTON, J. M. Division of Rules and Records 83/02/23 HIATT, S. L. Ohio Citizens for Responsible Energy 1p 17684:292 24X
Fiche 50-000, 83/02/23, 8303230132.

--8211020694 SECY-82-396
Requests Commission comments & views re draft federal policy statement on distribution of potassium iodide in vicinity of nuclear power plants for purpose of thyroidal blocking in event of large scale accidental release of radioiodine.
DIRCKS, W. J. Office of the Executive Director for Operations
82/09/27 17pp 17684:310

--8211040047 SECY-82-396A
Withdraws SECY-82-396 proposal to draft federal policy statement on distribution of potassium iodine in plant vicinity.
DIRCKS, W. J. Office of the Executive Director for Operations
82/10/15 2pp 17684:327

8303230177 Responds to FOIA request for six specified records. Forwards Documents 1-6 listed in app. Documents 7 & 8 available in PDR. SECY-82-389 withheld (ref FOIA Exemption 5).
FELTON, J. M. Division of Rules and Records 83/02/25 GRAGER, L. Affiliation Unknown 3pp 17684:330

--8208260515 SECY-82-335
Recommends approval of proposed amend for publication in FR. Amend would clarify Commission authority to copy & take away copies of certain licensee records & require tests on safeguards-related equipment & procedures. FR notice encl.
DIRCKS, W. J. Office of the Executive Director for Operations
82/08/11 30pp 17684:346

--8211300421 SECY-82-380
Requests Commission approval to publish proposed amend to 10CFR2.291, authorizing issuances of notices of violations to nonlicensees, clarifying authority of regional administrator to issue notices of violations.
DIRCKS, W. J. Office of the Executive Director for Operations
82/09/15 14pp 17685:014

8303230320 SECY-83-098
Provides interim draft rept on current status of evaluation of failure to scram automatically events. NRC to meet w/util on 830310 to discuss draft NRC status rept.
DIRCKS, W. J. Office of the Executive Director for Operations
83/03/10 25pp 17677:331

8303230332 SECY-83-098A
Provides rept on current status of NRC evaluation of 130222 & 25 automatic scram events & NRC action plan for authorizing restart Show caused order should be issued.
DIRCKS, W. J. Office of the Executive Director for Operations. 83/03/14. 37pp. 17675:020

8303280345 Transcript of 830318 briefing on Nuclear Waste Mgt Act in Washington, DC. Pp 1-83.
* Commissioners. 83/03/18. 85pp. 17712:240

--8303280348 SECY-83-107
Advises of principal provisions of Public Law 97-425, Nuclear Waste Policy Act of 1982, affecting NRC.
DIRCKS, W. J. Office of the Executive Director for Operations. 83/03/16. 123pp. 17712:325

8303300645 FOIA request for SECY-83-004.
MONAHAN, J. Francis & McGinnis Associates. 83/01/19. FELTON, J. Division of Rules and Records. 1p. 17768:308

8303300647 Responds to FOIA request for SECY-83-004. Forwards document.
FELTON, J. M. Division of Rules and Records. 83/02/23. MONAHAN, J. Francis & McGinnis Associates. 1p. 17768:309

--8303300652 SECY-83-004
Provides info paper on current status of NPRDS. INPO new strategy of improving current failure reporting endorsed. Accurate assessment of effectiveness of INPO mgt of NPRDS not possible before end of 1983.
DIRCKS, W. J. Office of the Executive Director for Operations. 83/01/04. 26pp. 17768:310

8303300659 Final response to FOIA request for documents re NRC 820521 closed briefing on design basis threat. Forwards Documents 1-3 listed in app. Releasable portions of meeting transcript available in PDR. Document 4 released via FOIA-77-14 & 106.
FELTON, J. M. Division of Rules and Records. 83/03/04. COCHRAN, T. B. Natural Resources Defense Council. 2pp. 17765:187.

--8205240600 SECY-82-198
Informs Commission of NRC views concerning current design basis threats contained in 10CFR73.1(a), per 820422 request.
DIRCKS, W. J. Office of the Executive Director for Operations. 82/05/18. 4pp. 17765:190

STATE PROG STATE PROGRAMS

8303020068 Notification of contract execution, Mod 5 to "Investigation Program at Maxey Flats Radwaste Burial Facility."
Contractor: Commonwealth of KY.
WOLLETT, S. Technical Assistance Contracts Branch. FIN B-6192. NRC-04-78-259. 83/01/07. BATSON, W. Office of Nuclear Regulatory Research, Director. O'DONNELL, E. NRC - No Detailed Affiliation Given. 1p. 17359:333.

--8303020072 Mod 5, changing principal investigator to "Investigation Program at Maxey Flats Radwaste Burial Facility."
SWEIGART, J. Kentucky, Commonwealth of. GUSTAVE, R. P. Division of Contracts. FIN B-6192. NRC-04-78-259. 83/01/07. 1p. 17359:334.

8303030672 Notification of contract execution: "Radiation Monitoring Program Requirements," awarded to OR State Health Div.
MCDERMOTT, D. Technical Assistance Contracts Branch. FIN B-8554. NRC-32-83-685. 83/02/25. ALEXANDER, I. Office of Resource Management, Director. HAMADA, G. NRC - No Detailed Affiliation Given. 1p. 17363:012.

--8303030680 Contract: "Radiation Monitoring Program Requirements," awarded to OR State Health Div.
GEBBIE, K. M. Oregon, State of. MORTON, K. V. Division of Contracts. FIN B-8554. NRC-32-83-685. 83/02/25. 15pp. 17363:013.

8303030774 Notification of contract execution: "Radiation Monitoring Program Requirements," awarded to State of ME.
MCDERMOTT, D. Technical Assistance Contracts Branch. FIN B-8357. NRC-28-83-603. 83/02/25. MCOSCAR, J. Office of Resource Management, Director. COSTELLO, E. NRC - No Detailed Affiliation Given. 1p. 17364:021.

--8303030782 Contract: "Radiation Monitoring Program Requirements," awarded to State of ME.
WAKEFIELD, J. Maine, State of. MORTON, K. V. Division of Contracts. FIN B-8357. NRC-28-83-603. 83/02/25. 15pp. 17364:022.

8303040181 Responds to 830125 request for attendance at Committee on Away-From-Reactor Storage 830217 meeting. LC Rouse designated NRC representative to outline NRC responsibilities re spent fuel storage specified by Nuclear Waste Policy Act of 1982.
AHEARNE, J. F. Commissioners. 83/02/15. RILEY, R. W. South Carolina, State of. 1p. 17427:016.

--8303040185 Notifies of Committee on Away-From-Reactor Storage 830217 meeting in Columbia, SC to review Nuclear Waste Policy Act of 1982 & implications for mgt & storage of spent nuclear fuel. NRC representative invited.
RILEY, R. W. South Carolina, State of. 83/01/25. PALLADINO, N. J. Commissioners. 1p. 17427:017.

8303040211 Ack receipt of 830119 ltr w/draft proposed amends to northwest compact on low level radwaste mgt. Comments & suggestions provided.
KERR, G. W. Office of State Programs, Director. 83/02/15. PRICE, E. G. Washington, State of. 5pp. 17428:010.

--8303040217 Forwards, for comment & suggestion, proposed amendatory compact on low level radwaste mgt.
PRICE, E. B. Washington, State of. 83/01/19. KERR, W. Office of State Programs, Director. 12pp. 17428:015.

8303040440 Discusses encl review & evaluation of radiation control program. Review covered principal administrative & technical aspects as well as legislation & regulations, organization, mgt & personnel. Program adequate.
HAYNES, R. C. Region 1, Office of Director. 83/02/25. SENCER, D. J. New York, NY. 6pp. 17370:217.

8303040518 Ack receipt of 830111 & 13 responses to NRC comments & recommendations following 1982 review of NY State Dept of Health radiation control program. Ltrs should be placed in state PDR or made available for public review.
HAYNES, R. C. Region 1, Office of Director. 83/02/25. AXELROD, D. New York, State of. 1p. 17373:276.

--8303040533 Informs that NRC 821210 ltr summarizing NRC review of NY Dept of Health radiation control program forwarded to Director of Bureau of Environ Radiation Protection for appropriate action.
AXELROD, D. New York, State of. 83/01/13. HAYNES, R. C. Region 1, Office of Director. 1p. 17373:277.

--8303040543 Submits plans for addressing NRC 821210 recommendations for correcting deficiencies in NY State Dept of Health radiation control program. Licensing guides used for license review revised to include NRC suggestions.
RIMAWI, K. New York, State of. 83/01/13. HAYNES, R. Region 1, Office of Director. 2pp. 17373:278.

8303080078 Comments on NRC 830210 ltr re recommendations for updating State of NV regulations for radiation control. Insp repts will be restructured so first matter considered will be status of previous noncompliance items.
JACKA, B. Nevada, State of. 83/02/18. ENGELKEN, R. H. Region 5, Office of Director. 3pp. 17457:123.

8303080306 Forwards Endorsement 7 to NELIA Master Policy 1 for subscribing companies for CY83.
LEVINE, J. M. American Nuclear Insurers. 83/03/01. DINITZ, I. P. Assistant Director for State & Licensee Relations. 2pp. 17441:354.

8303090002 Responds to FOIA request for documents re exploration, mining or milling of U in specific areas in State of NE. Forwards documents listed in app. Review of remaining documents in progress.
FELTON, J. M. Division of Rules and Records. 83/01/28. REID, A. B. Broken Plow Law Office. 2pp. 17466:305.

--8204070025 Requests NRC reassert regulatory authority to regulate source matls re U mining & milling.
THONE, C. Nebraska, State of. 82/02/18. KERR, G. W. Office of State Programs, Director. 4pp. 17466:307.

--8209280360 Comments on draft memorandum of understanding transmitted by 820727 memo. Memorandum should clearly state scope covers only U solution in situ mining projects.
MURRAY, J. P. Deputy Executive Legal Director. 82/08/18. COLLINS, J. T. Region 4, Office of Director. 2pp. 17466:323.

--8303090006 Forwards MOU for in situ U mining in State of NE for signature & date. W/o encl.
COLLINS, J. T. Region 4, Office of Director. 82/11/09. DRAIN, D. T. Nebraska, State of. 1p. 17466:313.

--8303090007 Grants request for NRC to reassert authority regulating source matl re in situ or solution U milling & mining. Reassertion effective 820504 Proposal may be submitted later for amend agreement.
DIRCKS, W. J. Office of the Executive Director for Operations. 82/05/10. THONE, C. Nebraska, State of. 2pp. 17466:317.

--8303090009 Requests signature on State of NE MOU. MOU pertains only to activities transferred to Region IV.
DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director. 82/09/17. COLLINS, J. T. Region 4, Office of Director. 2pp. 17466:321.

--8303090013 Discusses state action to regulate U milling per 1978 U Mill Tailings Radiation Control Act. Agreement States authorized to license & regulate U mills & mill tailings must enter into amended agreements w/NRC by 811108.
NUSSBAUMER, D. A. Assistant Director for State Agreements Programs. 83/01/28. SMITH, H. D. Nebraska, State of. 2pp. 17466:325.

8303090331 Forwards TX Dept of Health 830204 ltr requesting NRC comments on proposed license amend for Anaconda Minerals Rhode Ranch. Comments requested by 830228.
NUSSBAUMER, D. A. Assistant Director for State Agreements Programs. 00085. 83/02/10. SMITH, R. D. Uranium Recovery Field Office. FOWNER, R. Office of the Executive Legal Director. 1p. 17484:222.

--8303090337 Forwards draft Amend 1 to Anaconda Minerals Co Rhode Ranch License 8-3304. Encl draft response to NRC 821213 ltr adequately addresses NRC comments on license. Comments requested by 830228.
BAILEY, E. D. Texas, State of. 00085. 83/02/04. NUSSBAUMER, D. A. Assistant Director for State Agreements Programs. 16pp. 17484:223.

8303090574 Comments on 830103 discussion draft, "Northeast Interstate Low Level Radwaste Mgt Compact." Analysis based on NRC interpretation of consistency w/Low Level Waste Policy Act of 1980.
KERR, G. W. Office of State Programs, Director. 83/02/09.
STUBBS, A. D. Coalition of Northeastern Governors. 7pp. 17480:064.

--8303090579 Comments on 820707 discussion draft, "Northeast Interstate Low Level Radwaste Mgt Compact."
KERR, G. W. Office of State Programs, Director. 82/08/17.
ARNOLD, D. D. Coalition of Northeastern Governors. 7pp. 17480:071.

--8303090587 Requests comments on encl 830103 discussion draft, "Northeast Low Level Radwaste Mgt Compact."
STUBBS, A. D. Coalition of Northeastern Governors. 83/01/19.
KERR, W. Office of State Programs, Director. 53pp. 17480:078.

8303100515 Requests designation of state liaison officer.
PALLADINO, N. J. Commissioners. 83/02/28. HARRIS, F. J. Georgia, State of. 2pp. 17521:310.

8303100518 Requests designation of state liaison officer.
PALLADINO, N. J. Commissioners. 83/02/28. CLINTON, B. Arkansas, State of. 2pp. 17521:295.

8303100522 Requests designation of state liaison officer.
PALLADINO, N. J. Commissioners. 83/02/28. WALLACE, G. Alabama, State of. 2pp. 17521:286.

8303100525 Requests designation of state liaison officer.
PALLADINO, N. J. Commissioners. 83/02/28. DEUKMEJIAN, G. California, State of. 2pp. 17521:282.

8303110051 Recommends appointment of state liaison officer to improve federal/state cooperation.
PALLADINO, N. J. Commissioners. 83/02/28. KERREY, J. R. Nebraska, State of. 2pp. 17546:245.

8303110052 Recommends appointment of state liaison officer to improve federal/state cooperation.
PALLADINO, N. J. Commissioners. 83/02/28. ANAYA, T. New Mexico, State of. 2pp. 17526:361.

8303110056 Recommends appointment of state liaison officer to improve federal/state cooperation.
PALLADINO, N. J. Commissioners. 83/02/28. CUOMO, M. M. New York, State of. 2pp. 17526:341.

8303110057 Recommends appointment of state liaison officer to improve federal/state cooperation.
PALLADINO, N. J. Commissioners. 83/02/28. CELESTE, R. F. Ohio, State of. 2pp. 17526:339.

8303110059 Recommends appointment of state liaison officer to improve federal/state cooperation.
PALLADINO, N. J. Commissioners. 83/02/28. WHITE, M. W. Texas, State of. 2pp. 17526:337.

8303110062 Recommends appointment of state liaison officer to improve federal/state cooperation.
PALLADINO, N. J. Commissioners. 83/02/28. EARL, A. S. Wisconsin, State of. 2pp. 17526:335.

8303110141 Requests designation of state liaison officer.
PALLADINO, N. J. Commissioners. 83/02/28. BRANSTAD, T. Iowa, State of. 2pp. 17520:359.

8303110144 Requests designation of state liaison officer.
PALLADINO, N. J. Commissioners. 83/02/28. BLANCHARD, J. J. Michigan, State of. 2pp. 17520:361.

8303110146 Urges designation of state liaison officer per NRC recommendations for streamlining siting & environ review process for nuclear facilities.
PALLADINO, N. J. Commissioners. 83/02/28. PERRICH, R. G. Minnesota, State of. 2pp. 17523:310.

8303110150 Requests designation of state liaison officer.
PALLADINO, N. J. Commissioners. 83/02/28. SHEFFIELD, W. Alaska, State of. 2pp. 17520:355.

8303110152 Requests designation of state liaison officer.
PALLADINO, N. J. Commissioners. 83/02/28. DUKAKIS, M. S. Massachusetts, Commonwealth of. 2pp. 17523:312.

8303110619 Recommends appointment of state liaison officer to improve federal/state cooperation.
PALLADINO, N. J. Commissioners. 83/02/28. SUNUNU, H. J. New Hampshire, State of. 2pp. 17523:063.

8303110622 Recommends appointment of state liaison officer to improve federal/state cooperation.
PALLADINO, N. J. Commissioners. 83/02/28. BRYAN, R. Nevada, State of. 2pp. 17523:061.

8303140517 Forwards technical comments & recommendations for State of CO radiation control program & confirms 830128 discussions among RS Heyer, A Hazle & W Jacobi. Program adequate to protect public health & safety.
COLLINS, J. T. Region 4, Office of Director. 83/03/07. TRAYLOR, F. Colorado, State of. 4pp. 17540:358.

8303170281 NUREG/BR-0025 V09 N2.
INFORMATION REPORT ON STATE LEGISLATION.
* Assistant Director for State & Licensee Relations. 83/03/01.
8pp. 17623:307.

8303180011 Submits response to two Category I indications & technical comments & recommendation on State of NE radiation control program in response to NRC 830118 ltr.
SMITH, H. D. Nebraska, State of. 83/03/01. COLLINS, J. T. Region 4, Office of Director. 4pp. 17618:129.

8303180147 Informs that TX Dept of Health matl on NRC comments reviewed. Dept has not incorporated significant license conditions recommended by NRC re cover dewatering of tailings & borings program.
SMITH, R. D. Uranium Recovery Field Office. 00085. 83/03/03.
NUSSBAUMER, D. A. Office of State Programs, Director. 2pp. 17626:012.

8303180581 Forwards State of SC 830209 comments on Vikem Industries topical rept re solidification of contaminated waste lubricator oils.
SCHNEIDER, K. N. Assistant Director for State Agreements Programs. 83/02/22. JOHNSON, T. Division of Waste Management. 1p. 17640:119.

--8303180584 Responds to 830203 request for review of Vikem Industries, Inc topical rept re solidification of contaminated waste lubricator oils. Review of no interest to state since type of waste prohibited at Chem-Nuclear facility.
SHEALY, H. G. South Carolina, State of. 83/02/09. NUSSBAUMER, D. Assistant Director for State Agreements Programs. 1p. 17640:121.

8303180635 Responds to inquiry re state statutory authority to impose restrictions on low level radwaste shipment & disposal. Memos presenting NRC legal opinions & 10CFR61 forwarded w/o encl.
BROWNING, R. E. Division of Waste Management. 83/02/10.
HOLLINGSWORTH. New Hampshire, State of. 1p. 17626:309.

8303180641 Forwards discussion of waste mgt alternatives for wastes containing chelating agents, describing processes to degrade complexants solidification, use of high integrity containers & disposal options.
HAWKINS, E. Low Level Waste Licensing Branch 83/02/01 SHEALY, H South Carolina, State of 6pp 17637 144

8303220417 NUREG-0584 R03 DRFT
ASSURING THE AVAILABILITY OF FUNDS FOR DECOMMISSIONING NUCLEAR FACILITIES
WOOD, R S. Office of State Programs, Director 83/03/31 38pp 17667 183

8303240454 Responds to NRC 830201 ltr providing comments & recommendations re annual review of ND State Dept of Health radiation control program.
MOUNT, D K. North Dakota, State of 83/02/17 COLLINS, J T. Region 4, Office of Director 3pp 17678 090

8303240524 PNO-IV-83-010 on 830317, State of TX Bureau of Radiation Control notified that ORNL reported 8 to 20 max permissible lung burdens of Am-241 for two employees of Gulf Nuclear, Inc arising from 830208 incident. Investigation continuing.
DODA, R J. Region 4, Office of Director 83/03/18 1p 17682 281

w303280125 PNA 83-005B on 830310, Auburn Steel Co informed EPA of Co-60 contamination of metals production facility. Caused by receipt of scrap metal from sources in US & Canada. NY State Police investigation of scrap shipment records continuing.
CAMPBELL, M. Region 1, Office of Director LUBENAU, J O. Office of State Programs, Director 83/03/10 3pp 17713 319

8303280313 Forwards four notices of nonroutine events involving Agreement State or agreement matls issued in 1983.
NUSSBAUMER, D A. Office of State Programs, Director 83/03/15
SALTZMAN, J. Office of State Programs, Director 2pp 17713 288

--8303280318 PNA 83-006 on 830228, Suffolk County Dept of Health informed Region 1 of indications of buried radioactive matls at formerly licensed site in Bellport, NY. Measurements continuing.
CAMPBELL, M. Region 1, Office of Director 83/03/15 1p 17713 290

--8303280326 PNA 83-005A on 830222, Auburn Steel Co informed Region 1 of discovery that steel reinforcement rods mfg on 810221 were contaminated w/radioactive matl. Investigation continuing.
CAMPBELL, M. Region 1, Office of Director 83/03/03 1p 17713 293

--8303280330 PNA 83-005 on 830221, during preparation of steel scrap for reinforcement rod mfg by Auburn Steel Co, level gauge indicated high radiation coming from rods. Facility shut down. Investigation continuing.
CAMPBELL, M. Region 1, Office of Director 83/02/23 1p 17713 294

--8303280335 PNA 83-004 on 830126, package received at temporary job site containing 200 Ci Ir-192 in radiography device surface radiation measured in excess of DOT limits. Investigation of shipment continuing.
CAMPBELL, M A. Region 1, Office of Director 83/01/27 1p 17713 295

--8303280340 PNA 83-002 on 830107, Region III issued press release re company identified by NY Dept of Health which imported cloisonne jewelry containing U glaze. Release urges that unnecessary exposure to jewelry be minimized.
CAMPBELL, M. Region 1, Office of Director 83/03/15 1p 17713 296

8303290013 Notification of contract execution: "Radiation Monitoring Program Requirements," awarded to Dept of Health & Human Svcs, State of WA.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8551 NRC-32-83-682 83/03/16 ALEXANDER, I. Office of Resource Management, Director HAMADA, G. NRC - No Detailed Affiliation Given 1p 17727 331

--8303290028 Contract: "Radiation Monitoring Program Requirements," awarded to Dept of Health & Human Svcs, State of WA.
BORTI, D G. Washington, State of MORTON, K V. Technical Assistance Contracts Branch FIN B-8551 NRC-32-83-682 83/03/16 1p 17727 332

--8303290298 RQS-83-682
"Environ Measurement Verification of Radioactivity & Radiation Levels in Environ of Commission Licensed Activities Located Within State of WA & Selected by Commission."
* Washington, State of * Technical Assistance Contracts Branch FIN B-8551 NRC-32-83-682 83/03/16 13pp 17727 333

8303290014 Forwards State of NV comments on Viken Industries topical rept for solidification of contaminated waste lubricator oils.
SCHNEIDER, K N. Assistant Director for State Agreements Programs SA/KNS 83/03/18 JOHNSON, T. Division of Waste Management 1p 17730 028

--8303290017 Comments on rept, "Results of Test Program for Solidification of Contaminated Waste Lubrication Oils." All shipping containers must pass insp for free liquid (0.05 ml) prior to approval of any solidification procedure.
VADEN, J. Nevada, State of 83/02/24 NUSSBAUMER, D Assistant Director for State Agreements Programs 1p 17730 029

8303290018 Notification of contract execution: "Radiation Monitoring Program Requirements," awarded to NY State Dept of Health.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8355 NRC-28-83-610 83/03/16 MCOSCAR, J. Office of Resource Management, Director COSTELLO, F. NRC - No Detailed Affiliation Given 1p 17730 010

--8303290039 Contract: "Radiation Monitoring Program Requirements," awarded to NY State Dept of Health.
RIMAWI, K. New York, State of MORTON, K V. Division of Contracts FIN B-8355 NRC-28-83-610 83/03/16 1p 17730 011

--8303290045 RGI-83-610
"Environ Monitoring Program for State of NY."
* New York, State of FIN B-8355 NRC-28-83-610 83/03/16 16pp 17730 012

8303290406 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements." Contractor: OH Dept of Health.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8450 NRC-30-83-646 83/03/16 PAPPAS, P. Office of Resource Management, Director OESTMANN, M J. NRC - No Detailed Affiliation Given 1p 17727 359

--8303290413 Mod 1, correcting B&R number, to "Radiation Monitoring Program Requirements."
WILMOTH, B Ohio, State of MORTON, K V. Division of Contracts FIN B-8450 NRC-30-83-646 83/03/16 1p 17727 360

8303290528 Notification of contract execution: "Radiation Monitoring Program Requirements," awarded to Dept of Health Svcs, State of CA.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8553 NRC-32-83-684 83/03/16 ALEXANDER, I. Office of Resource Management, Director HAMADA, G. NRC - No Detailed Affiliation Given 1p 17740 185

--8303290532 Contract: "Radiation Monitoring Program Requirements," awarded to Dept of Health Svcs, State of CA.
ROHLFES, G B California, State of MORTON, K V. Technical Assistance Contracts Branch FIN B-8553 NRC-32-83-684 83/03/16 1p 17742 186

--8303290535 RGV-83-684
"Environ Measurement Verification of Radioactivity & Radiation & Radiation Levels in Environ of Commission Licensed Activities Located Within State of CA & Selected by Commission."
* California, State of * Technical Assistance Contracts Branch FIN B-8553 NRC-32-83-684 83/03/16 13pp 17742 187

8303290755 Notification of contract execution: "Radiation Monitoring Program Requirements," awarded to State of VA.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8402 NRC-29-83-623 83/03/09 LOY, T N. Division of Resource Management & Administration MONTGOMERY, D M. NRC - No Detailed Affiliation Given 1p 17746 341

--8303290758 Contract: "Radiation Monitoring Program Requirements," awarded to State of Vm.
KENLEY, J B Virginia, Commonwealth of, MORTON, K V. Division of Contracts FIN B-8402 NRC-29-83-623 83/03/09 15pp 17746 342

8303290763 Notification of contract execution: "Radiation Monitoring Program Requirements," awarded to State of CT.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8358 NRC-28-83-604 83/03/07 MCOSCAR, J., COSTELLO, F. NRC - No Detailed Affiliation Given 1p 17746 318

--8303290769 Contract: "Radiation Monitoring Program Requirements," awarded to State of CT.
HEUBNER, A T. Connecticut, State of MORTON, K V. Division of Contracts FIN B-8358 NRC-28-83-604 83/03/07 15pp 17746 319

8303290783 Notification of contract execution. "Radiation Monitoring Program Requirements," awarded to State of TX Dept of Health.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8504 NRC-31-83-671 83/03/07 MEYERS, D.M. Region 4, Office of Director NICHOLAS, J. B. NRC - No Detailed Affiliation Given 1p 17748:194

--8303290788 Contract. "Radiation Monitoring Program Requirements," awarded to State of TX Dept of Health Statement of work encl.
THIEL, J. Texas, State of MORTON, K. V. Division of Contracts FIN B-5804 NRC-31-83-671 83/03/07 18pp 17748:195

8303290793 Notification of contract execution. "Radiation Monitoring Program Requirements," awarded to State of CO Dept of Health.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8501 NRC-31-83-668 83/03/07 MEYERS, D.M. Region 4, Office of Director NICHOLAS, J. B. NRC - No Detailed Affiliation Given 1p 17748:157

--8303290798 Contract. "Radiation Monitoring Program Requirements," awarded to State of CO Dept of Health Statement of work encl.
TAYLOR, F. Colorado, State of MORTON, K. V. Division of Contracts FIN B-8501 NRC-31-83-668 83/03/07 18pp 17748:158

8303300061 Notification of contract execution. "Radiation Monitoring Program Requirements," awarded to State of VT.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8351 NRC-28-83-605 83/03/09 MCOSCAR, J. Division of Resource Management & Administration COSTELLO, F. NRC - No Detailed Affiliation Given 1p 17751:078

--8303300067 Contract. "Radiation Monitoring Program Requirements," awarded to State of VT.
ROSENSTREICH, B. Vermont, State of MORTON, K. V. Division of Contracts FIN B-8351 NRC-28-83-605 83/03/09 10pp 17751:079

8303300073 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements," Contractor State of MD.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8454 NRC-30-83-643 83/03/09 PAPPAS, H. Division of Resource Management & Administration OESTMANN, M. J. NRC - No Detailed Affiliation Given 1p 17751:059

--8303300079 Mod 1, correcting B&R number, to "Radiation Monitoring Program Requirements."
* Missouri, State of MORTON, K. V. Division of Contracts FIN B-6454 NRC-30-83-643 83/03/09 1p 17751:060

8303300270 Forwards WA Governor Spellman 820816 Executive Order 82-17, establishing state high level nuclear waste mgt task force.
KERR, G. W. Office of State Programs, Director 00271 82/09/02
DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director
ENGELKEN, R. Region 5, Office of Director 5pp 17749:009

8303300297 Notification of contract execution. "Radiation Monitoring Program Requirements," awarded to State of MI.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8451 NRC-30-83-644 83/03/09 PAPPAS, H. Office of Resource Management, Director OESTMANN, M. J. NRC - No Detailed Affiliation Given 1p 17754:001

--8303300585 Contract. "Radiation Monitoring Program Requirements," awarded to State of MI.
WALKER, B. Michigan, State of, Dept. of Public Health MORTON, K. V. Division of Contracts FIN B-8451 NRC-30-83-644 83/03/09 9pp 17754:002

8303300568 Notification of contract execution. "Radiation Monitoring Program Requirements," awarded to State of OH.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8450 NRC-30-83-646 83/03/16 PAPPAS, H. Region 3, Office of Director OESTMANN, M. J. NRC - No Detailed Affiliation Given 1p 17748:311

--8303300576 Contract. "Radiation Monitoring Program Requirements," awarded to State of OH.
GARDNER, T. A. Ohio, State of MORTON, K. V. Division of Contracts FIN B-8450 NRC-30-83-646 83/03/16 9pp 17748:312

8303300598 Notification of contract execution. "Radiation Monitoring Program Requirements," awarded to State of TN.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8401 NRC-29-83-622 83/03/16 LOY, T. N. Office of Resource Management, Director MONTGOMERY, D. M. NRC - No Detailed Affiliation Given 1p 17766:334

--8303300604 Contract. "Radiation Monitoring Program Requirements," awarded to State of TN.
WORD, J. E. Tennessee, State of MORTON, K. V. Division of Contracts FIN B-8401 NRC-29-83-622 83/03/16 15pp 17766:335

8303300680 Notification of contract execution. "Radiation Monitoring Program Requirements," awarded to State of MS.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8400 NRC-29-83-621 83/03/16 LOY, T. N. Region 2, Office of Director MONTGOMERY, D. M. NRC - No Detailed Affiliation Given 1p 17763:343

--8303300683 Contract. "Radiation Monitoring Program Requirements," awarded to State of MS.
COBB, A. B. Mississippi, State of MORTON, K. V. Division of Contracts FIN B-8400 NRC-29-83-621 83/03/16 14pp 17763:344

8303300687 Notification of contract execution. "Radiation Monitoring Program Requirements," awarded to State of MN.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8452 NRC-30-83-645 83/03/09 PAPPAS, H. Region 3, Office of Director OESTMANN, M. J. NRC - No Detailed Affiliation Given 1p 17764:003

--8303300698 Contract. "Radiation Monitoring Program Requirements," awarded to State of MN.
ASHTON, M. M. Minnesota, State of MORTON, K. V. Division of Contracts FIN B-8452 NRC-30-83-645 83/03/09 9pp 17764:004

8303310132 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements," Contractor State of MI.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8451 NRC-30-83-644 83/03/09 PAPPAS, H. Region 3, Office of Director OESTMANN, M. J. NRC - No Detailed Affiliation Given 1p 17775:182

--8303310136 Mod 1, correcting B&R number, to "Radiation Monitoring Program Requirements."
HENNIGAN, J. Michigan, State of MORTON, K. V. Division of Contracts FIN B-8451 NRC-30-83-644 83/03/09 1p 17775:183

8303310151 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements," Contractor State of WI.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8453 NRC-30-83-647 83/03/16 PAPPAS, H. Region 3, Office of Director OESTMANN, M. J. NRC - No Detailed Affiliation Given 1p 17775:190

--8303310155 Mod 1, correcting B&R number, to "Radiation Monitoring Program Requirements."
* Wisconsin, State of MORTON, K. V. Division of Contracts FIN B-8453 NRC-30-83-647 83/03/16 1p 17775:181

8303310186 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements," Contractor State of MN.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8452 NRC-30-83-645 83/03/09 PAPPAS, H. Region 3, Office of Director OESTMANN, M. J. NRC - No Detailed Affiliation Given 1p 17775:112

--8303310200 Mod 1, correcting B&R number, to "Radiation Monitoring Program Requirements."
DOLEZAL, A. Minnesota, State of MORTON, K. V. Division of Contracts FIN B-8452 NRC-30-83-645 83/03/09 1p 17775:113

8303310363 Notification of contract execution. "Radiation Monitoring Program Requirements," awarded to State of WI.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8453 NRC-30-83-647 83/03/16 PAPPAS, H. Region 3, Office of Director OESTMANN, M. J. NRC - No Detailed Affiliation Given 1p 17795:332

--8303310367 Contract. "Radiation Monitoring Program Requirements," awarded to State of WI.
REIVITZ, L. Wisconsin, State of MORTON, K. V. Division of Contracts FIN B-8453 NRC-30-83-647 83/03/16 1app. 17795:333

8303310370 Notification of contract execution. "Radiation Monitoring Program Requirements," awarded to State of AL.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8405 NRC-29-83-626 83/03/16 LOY, T. N. Region 2, Office of Director MONTGOMERY, D. M. NRC - No Detailed Affiliation Given 1p 17796:058

--8303310374 Contract. "Radiation Monitoring Program Requirements," awarded to State of AL.
MYERS, I. L. Alabama, State of MORTON, K. V. Division of Contracts FIN B-8405 NRC-29-83-626 83/03/16 14pp 17796:059

8303310572 Notification of contract execution: Mod 2 to "LA Offshore Radiological Licensee Survey." Contractor: State of LA.
HOPPER, A. M. Administrative Contracts Branch. FIN B-8703.
NRC-05-82-252. 82/09/23. BLAHA, J. L. Program Support Branch.
YACZKO, C. NRC - No Detailed Affiliation Given. 1p. 17780:346.

--8303310576 Mod 2, extending period of performance to 830731, to "LA Offshore Radiological Licensee Survey."
PORTER, J. B. Louisiana, State of. REBELLO, J. E. Division of Contracts. FIN B-8703. NRC-05-82-252. 82/09/23. 1p. 17780:347.

TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

8302160328 Forwards proprietary draft responses to NRC 821203 questions on proprietary repts WCAP-10079 & WCAP-10054 re NOTRUMP Code for small break ECCS evaluation model & general network code. Responses withheld (ref 10CFR2.790).
RAHE, E. P. Westinghouse Electric Corp. NS-EPR-2721. 83/02/14.
THOMAS, C. O. Standardization & Special Projects Branch. 1p. 17166:184.

--8302160332 Requests that draft responses to NRC questions on draft proprietary repts WCAP-10079 & WCAP-10054 re NOTRUMP Code be withheld (ref 10CFR2.790).
WIESEMANN, R. A. Westinghouse Electric Corp. AW-83-12. 83/02/10.
THOMAS, C. O. Standardization & Special Projects Branch. 1p. 17166:185.

8303010298 Forwards draft proposed Rev 6 to Topical Rept SL-TR-1A, "QA Program." Detailed summary of proposed changes also encl.
TAYLOR, H. S. Sargent & Lundy, Inc. 83/02/25. NRC - No Detailed Affiliation Given. 85pp. 17334:001.

8303010426 Forwards list of projects covered by Rev 4 to NEDO-11209-04A, "Nuclear Energy Business Operations BWR QA Program Description." QA activities conducted after 821230 will follow program described in rept.
CASE, J. M. General Electric Co. 83/02/22. HAASS, W. P. Quality Assurance Branch. 3pp. 17343:266.

8303010518 Questions ability of potential steam generator-related generic requirements to ensure public health & safety. Development of value impact assessments into regulatory requirements discouraged.
SCHERER, A. E. Combustion Engineering, Inc. LD-83-012. 83/02/24.
EISENHUT, D. G. Division of Licensing. 1p. 17337:192.

8303010572 Comments on draft EGG-EA-5109, "Identification & Ranking of Nuclear Plant Structures, Sys & Components & Graded QA Guidelines." Proposed guidelines would be burden to nuclear industry w/no measurable safety benefits.
DAIL, L. C. Duke Power Co. 83/02/23. HAASS, W. P. Quality Assurance Branch. 3pp. 17941:251.

8303010581 Discusses 830223 meeting re emergency feedwater spray effectiveness & steam generator level requirements & operating guidance during small break LOCA. No significant open items remain.
CROUSE, R. P. Babcock & Wilcox Regulatory Response Group. CROUSE, R. P. Toledo Edison Co. 83/02/25. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17336:016.

8303010591 Discusses meeting w/R Mattson & D Eisenhut re B&W Owners Group. Responsiveness for regulatory requirements will be demonstrated in technical & competent manner.
TUCKER, H. B. Duke Power Co. 83/02/23. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 17336:138.

8303010606 Forwards proprietary "Demonstration That Changes to LYNX2 Computer Code Did Not Significantly Affect Comparison Between BWC Correlation & Data Base." Encl withheld.
TAYLOR, J. H. Babcock & Wilcox Co. 83/02/16. THOMAS, C. O. Standardization & Special Projects Branch. 1p. 17336:258.

8303010636 Notifies that next regular amend to GA-A13010A, "GA Co QA Program," will reflect name change to GA Technologies, Inc. Corporate realignment will have no substantive effect on QA program.
FISHER, C. R. GA Technologies, Inc./General Atomic Co. LRS 13 CRF 83. 83/02/24. HAASS, W. P. Quality Assurance Branch. 1p. 17336:111.

8303020003 Advises of change of address for CB Brinkman.
MUELLER, E. Combustion Engineering, Inc. 83/02/24. CLARK, R. A. Operating Reactors Branch 3. 1p. 17353:096.

8303020009 Forwards proposed rev to proprietary version of "GE Std Application for Reactor Fuel," licensing topical rept. Affidavit for withholding per 10CFR2.790 encl. Rept withheld (ref 10CFR2.790).
CHARNLEY, J. S. General Electric Co. MFN-043-83. 83/02/25.
MIRAGLIA, F. J. Assistant Director for Safety Assessment. 6pp. 17354:285.

8303020053 Forwards Rev 4 to "Nuclear Energy Business Operations BWR QA Program Description." Ack of receipt requested.
* General Electric Co. 82/12/31. HAASS, W. P. NRC - No Detailed Affiliation Given. 2pp. 17353:097.

--8303020059 NEDO-11209-04AR4 ERR
Errata to Rev 4 to "Nuclear Energy Business Operations BWR QA Program Description."
* General Electric Co. 78NED116R. 82/12/31. 2pp. 17353:098.

--8303020065 NEDO-11209-04A R04
Rev 4 to "Nuclear Energy Business Operations BWR QA Program Description."
CASE, J. M. General Electric Co. 78NED116R. 82/12/31. 40pp. 17353:100.

--8212220088 Forwards topical rept evaluation of NEDO-11209-04A, "Nuclear Energy Business Group BWR QA Program Description." Rept acceptable.
HAASS, W. P. Quality Assurance Branch. 82/12/06. CASE, J. M. General Electric Co. 2pp. 17353:107.

--8212220095 Topical rept evaluation of NEDO-11209-04A, "Nuclear Energy Business Group BWR QA Program Description." Rept acceptable.
* Quality Assurance Branch. 82/12/06. 2pp. 17353:109.

8303030173 Requests names & addresses of current chairmen of owners groups & regulatory response groups for Westinghouse, GE & C-E design reactors.
CROUSE, R. P. Babcock & Wilcox Operating Plants Owners Group.
CROUSE, R. P. Toledo Edison Co. 83/02/25. EISENHUT, D. G. Division of Licensing. 1p. 17410:341.

8303030322 Forwards "Technical Evaluation of B&W Fuel Rod Bowing Evaluation Topical Rept BAW-10147P." Rept, as augmented by responses to requests for addl info, acceptable.
THOMAS, C. O. Standardization & Special Projects Branch. 83/02/15.
TAYLOR, J. H. Babcock & Wilcox Co. 2pp. 17365:134.

--8303030330 "Technical Evaluation of B&W Fuel Rod Bowing Evaluation Topical Rept BAW-10147P." Rept acceptable.
CAREW, J. F. Brookhaven National Laboratory. 82/08/31. NRC - No Detailed Affiliation Given. 22pp. 17365:136.

8303030336 Forwards "Technical Evaluation of C-E Fuel & Poison Rod Bowing Topical Rept CENPD-225-P & Suppls 1, 2-P & 3-P." Rept, as supplemented by responses to requests for addl info, acceptable.
THOMAS, C. O. Standardization & Special Projects Branch. 83/02/15.
SCHERER, A. E. Combustion Engineering, Inc. 2pp. 17365:099.

--8303030341 "Technical Evaluation of C-E Fuel & Poison Rod Bowing Topical Rept CENPD-225-P & Suppls 1, 2-P & 3-P." Rept acceptable.
CAREW, J. F. Brookhaven National Laboratory. 82/08/31. NRC - No Detailed Affiliation Given. 22pp. 17365:101.

8303030764 Forwards request for addl info needed to review Westinghouse Topical Rept WCAP-8264(P), "Mass & Energy Release Model for Containment Design - Mar 1979."
THOMAS, C. O. Standardization & Special Projects Branch. 83/02/22.
RAHE, E. P. Westinghouse Electric Corp. 4pp. 17364:006.

8303040192 Requests addl info re Amend 3 to NEDE-21175-3(P), "BWR Fuel Assembly Evaluation of Combined SSE & LOCA Loadings."
THOMAS, C. O. Standardization & Special Projects Branch. 83/02/15.
SHERWOOD, G. G. General Electric Co. 4pp. 17426:359.

8303040354 Discusses development of Westinghouse Owners Group response guidelines addressing NUREG-0737, Item II.K.2.17, "Potential Voiding in RCS." Natural circulation cooldown guidance will be utilized in plant emergency operating procedures.
MUENCH, R. A. Westinghouse Electric Corp. NSID/WOG-63. 83/02/16.
EISENHUT, D. G. Division of Licensing. 2pp. 17420:021.

8303040509 Informs that submittal of addl info requested in NRC 820830 ltr re BAW-10025(P), Rev 1, "Reactor Vessel Model Flow Tests for 205 Fuel Assembly Core," will be delayed from 830228 to 830430.
TAYLOR, J. H. Babcock & Wilcox Co. 83/02/23. THOMAS, C. O. Standardization & Special Projects Branch. 1p. 17373:306.

8303040509 Forwards review of 821213 Science Application, Inc value impact analysis rept re proposed steam generator requirements. Review considered multiple tube rupture in addition to detailed rept review.
RAHE, E. P. Westinghouse Electric Corp. NS-EPR-2706 83/02/15
EISENHUT, D. G. Division of Licensing 6pp 17368:015

8303040640 Forwards Amen. 6 to DUKE-1-A, "QA Program."
HENRY, W. O. Duke Power Co. 83/03/02 HARPSTER, T. L. QA Branch 1p 17367:215

--8303040643 DUKE-1-A A06
Amend 6 to "QA Program."
* Duke Power Co. 83/03/02 109pp 17367:216

--8303040644 Advises that DUKE-1-A, "QA Program," has been reviewed & found acceptable. Rept may be implemented upon issuance of amend.
HARPSTER, T. L. QA Branch 83/02/03 GRIER, G. W. Duke Power Co. 4pp 17367:325

8303070087 Forwards Rev 1 to nonproprietary Vol 1 & proprietary Vol 2 of "United Nuclear Corp Portland Cement/Sodium Silicate Radwaste Solidification Sys," for referencing in licensing actions. Proprietary Vol 2 withheld.
MASON, J. B. United Nuclear Corp. 83/02/18 THOMAS, C. O. Standardization & Special Projects Branch 1p 17432:187

--8303070096 UNC-S-8000-NP V01R01
Rev 1 to nonproprietary "United Nuclear Corp Portland Cement/Sodium Silicate Radwaste Solidification Sys, Vol 1, Sys Equipment & Process Description."
* United Nuclear Corp. 83/01/31 121pp 17432:188

8303070146 Forwards proprietary & nonproprietary "Supplemental Info for NRC Approved Version of WCAP-9401/9402 & WCAP-9500," per SER open issues re mixed core compatibility of optimized fuel assemblies. Proprietary rept withheld (ref 10CFR2.790).
RAHE, E. P. Westinghouse Electric Corp. NS-EPR-2723 83/02/21
THOMAS, C. O. Standardization & Special Projects Branch 3pp 17433:203

--8303070150 Requests withholding proprietary "Supplemental Info for NRC Approved Version of WCAP-9401/9402 & WCAP-9500" per 10CFR2.790 Affidavit AW-78-23 encl.
WIESEMANN, R. A. Westinghouse Electric Corp. AW-83-15 83/02/21
THOMAS, C. O. Standardization & Special Projects Branch 7pp 17433:206

--8303070157 "Supplemental Info for NRC Approved Version of WCAP-9401/9402 & WCAP-9500," Proprietary info deleted.
DAVIDSON, S. L., IORII, J. A. Westinghouse Electric Corp. 83/02/28 56pp 17433:213

8303080129 Forwards viewgraphs used at 830201 meeting on advanced control room design for advanced PWR & preliminary schedule for Phase I & II of design review. Meetings scheduled May/June 1983 in Pittsburgh, PA to review task analysis tools.
RAHE, E. P. Westinghouse Electric Corp. NS-EPR-2724 83/02/25
EISENHUT, D. G. Division of Licensing 21pp 17458:248

8303080220 Forwards revised pages to Rev 7, WPPSS-QA-004, "Operational QA Program Description."
BOUCHEY, G. D. Washington Public Power Supply System. GO2-83-187 83/03/03 HARPSTER, T. Director's Office, Office of Inspection and Enforcement 2pp 17439:292

--8303080225 WPPSS-QA-004 R07
Revised pages to Rev 7, "Operational QA Program Description." Revs reflect organizational changes since issuance of Rev 6 & consolidate position statements for all units.
* Washington Public Power Supply System 83/02/14 68pp 17439:294

8303090113 Notifies of 830204 organizational restructuring within water reactor div QA plan, NCAP-8370, Rev 9A, Amend 1. Change does not reduce any previously accepted commitments on program description. Organizational chart encl.
RAHE, E. P. Westinghouse Electric Corp. PI&DA-83-434 83/03/04
HAASS, W. P. Quality Assurance Branch 3pp 17470:281

8303090137 Comments on Nov 1982 draft EGG-EA-6109, "Identification & Ranking of Nuclear Plant Structures, Sys & Components & Graded QA Guidelines - Draft." Concept of separating components will not result in implementable QA sys.
BROWN, G. R. Edison Electric Institute 83/03/02 HAASS, W. P. QA Branch 2pp 17470:309

8303090192 Advises that interdivisional task force has been formed to address review of current methods for distribution of technical info within Westinghouse & dissemination of info to utils. Action in response to events at Salem.
RAHE, E. P. Westinghouse Electric Corp. NS-EPR-2726 83/03/01
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17472:300

8303090213 Forwards safety evaluation supporting NEDE-22178-(P), "Mark II Containment Drywell-to Wetwell Vacuum Breaker Models." Rept acceptable for referencing in licensing applications.
THOMAS, C. O. Standardization & Special Projects Branch 83/02/24
SHERWOOD, G. G. General Electric Co. 2pp 17484:196

--8303090231 Safety evaluation of NEDE-22178-(P), "Mark II Containment Drywell-to-Wetwell Vacuum Breaker Models." Rept acceptable for referencing in licensing applications.
* Standardization & Special Projects Branch 83/02/28 7pp 17484:198

8303090378 Forwards for review, "Natural Circulation Cooldown W/No Accident in Progress," "Natural Circulation W/Potential for Steam Void in Vessel Upper Head (W/RVLIS) & No Accident in Progress" & "Natural Circulation Cooldown W/Potential ".
SHEPPARD, J. J. Westinghouse Operating Plants Owners Group
SHEPPARD, J. J. Carolina Power & Light Co. OG-88 83/02/17
EISENHUT, D. G. Division of Licensing 3pp 17492:068

--8303090380 Rev HP - Basic to "Natural Circulation Cooldown W/No Accident in Progress."
* Westinghouse Electric Corp. 82/12/25 11pp 17492:072

--8303090383 Rev HP - Basic to "Natural Circulation Cooldown W/Potential for Steam Void in Vessel Upper Head (W/RVLIS) & No Accident in Progress."
* Westinghouse Electric Corp. 82/12/25 8pp 17492:082

--8303090386 Rev HP - Basic to "Natural Circulation Cooldown W/Potential for Steam Void in Vessel Upper Head (W/O RVLIS) & No Accident in Progress."
* Westinghouse Electric Corp. 82/12/25 13pp 17492:090

8303090393 Summary of 830214 meeting w/EPRI in Bethesda, MD re current status & progress-to-date in LWR standardization program.
MORAN, D. H. Standardization & Special Projects Branch 83/02/28
Standardization & Special Projects Branch 4pp 17484:118

8303090474 Forwards technical evaluation finding Topical Rept XN-NF-75-32(P) acceptable for ref in license applications. Requests publication of accepted version within 3 months of receipt of ltr. Rev limited to matl in Suppl 1-3.
THOMAS, C. O. Standardization & Special Projects Branch 83/02/25
STOUT, R. D. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 2pp 17482:310

--8303090481 "Technical Evaluation of Exxon Fuel Rod Bowing Topical Rept XN-NF-75-32 Suppls 1-3," Rept acceptable for ref in license applications.
CAREW, J. F. Brookhaven National Laboratory 82/08/31 20pp 17482:312

8303100070 Notification of 830302-03 meetings w/Westinghouse Owners Group & Westinghouse in Monroeville, PA to discuss emergency response guidelines.
JENSEN, W. Reactor Systems Branch 83/02/18 SHERON, B. W. Reactor Systems Branch 2pp 17493:103

8303100354 Notification of 830309-10 meetings w/BWR Owners Group, ORNL, IPI & EG&G in Bethesda, MD to review SLI 8212, "Inadequate Core Cooling Detection in BWRs," per TMI Action Item II.F.2.
SHEA, J. J. Operating Reactors Branch 5 83/03/01 CRUTCHFIELD, D. Operating Reactors Branch 5 2pp 17522:023

8303140236 Forwards Pp ii & 3.1-1 to revised nonproprietary version of "Util Design Review Panel Evaluation Rept, D2/D3 Steam Generator Design Mod," inadvertently omitted from 830302 transmittal.
BLACKLEY, S. K. Design Review Panel 83/03/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director EISENHUT, D. G. Division of Licensing 2pp 17539:007

--8303140241 Pp ii & 3.1-1 to revised nonproprietary version of "Util Design Review Panel Evaluation Rept, D2/D3 Steam Generator Design Mod."
* Design Review Panel 83/01/31 2pp 17539:008

8303140257 Forwards revised nonproprietary version of "Util Design Review Panel Evaluation Rept, D2/D3 Steam Generator Design Mod." Rept originally submitted on 830119.
BLACKLEY, S. K. Design Review Panel 83/03/02 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17534:269

--8303140264 Revised nonproprietary version of "Util Design Review Panel Evaluation Rept, D2/D3 Steam Generator Design Mod."
* Design Review Panel 83/01/31 120pp 17534 270

8303150028 DOE/EIS-0085-FS
"LMFBR Program." FES
* Energy, Dept. of 82/05/31 576pp 17598 129

8303150040 Comments on HPCS generator acceptance testing in response to 820727 ltr. Vendor should provide comparison of diesel generator units based on IEEE 387 criteria rather than on design bases or specs.
THOMAS, C. O. Standardization & Special Projects Branch 83/03/04
SHERWOOD, G. G. General Electric Co. 2pp 17586 317

8303150113 Forwards topical rept evaluation of CENPD-270, "Dry Storage Cask for ISFSI." Rept not acceptable. Revs suggested.
ROBERTS, J. P. Advanced Fuel & Spent Fuel Licensing Branch 83/02/25
SCHERER, A. E. Combustion Engineering, Inc. 2pp 17586 325

--8303150116 Topical rept evaluation of CENPD-270, "Dry Storage Cask for ISFSI." Rept not acceptable based on reasons listed.
* Advanced Fuel & Spent Fuel Licensing Branch 83/02/25 34pp 17586 327

8303160229 Forwards "GE Analytical Model for Loss-of-Coolant Analysis in Accordance W/10CFR50, App K, Amend 1 - Calculation of Low Flow Film Boiling Heat Transfer for BWR LOCA Analysis."
PFEFFERLEN, H. C. General Electric Co. MFN-040-83 83/02/24
TEDESCO, R. L. Assistant Director for Licensing 2pp 17596 059

--8303160236 NEDO-20566-1-A
"GE Analytical Model for Loss-of-Coolant Analysis in Accordance W/10CFR50, App K, Amend 1 - Calculation of Low Flow Film Boiling Heat Transfer for BWR LOCA Analysis."
KLEPFER, H. H., LEGNARD, J. E., SUN, K. H. General Electric Co.
7/NED304 82/10/31 105pp 17596 061

8303160252 Notification of 830310 meeting w/Westinghouse Owners Group & WI Electric Power Co in Bethesda, MD to discuss generic proposal for core damage estimation procedure (NUREG-0737, Item II.B.3, "Post-Accident Sampling").
COLBURN, T. G. Operating Reactors Branch 3 83/03/02 CLARK, R. A. Operating Reactors Branch 3 2pp 17604 356

8303160580 Forwards proprietary App C to "Thermal-Mechanical Bases for 8 x 8 & 8 x 8R Fuel Bundles." App withheld (ref 10CFR2.790).
CHARNLEY, J. S. General Electric Co. JSC-025-83 83/03/10
MIRAGLIA, F. J. Assistant Director for Safety Assessment 2pp 17589 326

8303160674 Forwards topical rept evaluation of Parts A & B of WCAP-10216(P). Parts A & B acceptable.
THOMAS, C. O. Standardization & Special Projects Branch 83/02/28
RAHE, E. P. Westinghouse Electric Corp. 2pp 17600 273

--8303160678 Topical rept evaluation of WCAP-10216(P), Part B, "FQ Surveillance Tech Spec" & Part A, "Relaxation of Constant Axial Offset Control." Rept parts acceptable.
* NRC - No Detailed Affiliation Given TAC 48818 83/02/28
8pp 17600 275

8303210355 Forwards evaluation re addl multiplier on quoted bare rod friction factors for use in stability audit calculations. No addl multiplier required for analysis of core stability for reactors which experienced no crud buildup.
KRYSINSKI, T. L. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 83/03/01 SCHWENK, G. A. Core Performance Branch 5pp 17634 354

8303210382 Grants exemption from 10CFR0.735-21(a) provisions. Integrity of svcs not affected by Westinghouse pension plan & no conflict of interest evident.
HAYNES, R. C. Region 1, Office of Director 83/03/17 REYNOLDS, S. D. Division of Engineering 1p 17634 176

8303220114 Forwards proprietary Suppl 1, Rev 2, to "Fuel Rod Thermal-Mechanical Response Evaluation Model. Response to NRC Request for Addl Info." Rept withheld (ref 10CFR2.790).
CHANDLER, J. C. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) JCC:040:83 83/03/18 THOMAS, C. O. Standardization & Special Projects Branch 1p 17649 268

8303220159 Forwards outline of C-E concept for scheduled 5-yr backfitting plan for reactor licensing. Adoption of plan will improve safety, reliability & availability of operating plants.
SCHERER, A. E. Combustion Engineering, Inc. LD-83-023 83/03/17
EISENHUT, D. G. Division of Licensing 4pp 17658 245

8303220205 Forwards listing of committee chairmen & sponsors for B&W Owners Group, per 830214 meeting.
CROUSE, R. P. Babcock & Wilcox Operating Plants Owners Group
CROUSE, R. P. Toledo Edison Co. 83/03/15 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 17658 138

8303220353 Forwards Endorsements 94 & 37 to NELIA Policies NF-146 & NS-282, respectively.
ROCCO, J. Southern California Edison Co. 83/03/18 DINITZ, I. Antitrust & Economic analysis Branch (Utility Finance) 3pp 17656 021

8303240019 Forwards Endorsement 7 to NELIA Policy NF-270.
ASHBURN, D. J. Marsh & McLennan, Inc. 83/03/18 SALTZMAN, J. Assistant Director for State & Licensee Relations 2pp 17681 073

8303240023 Forwards Endorsement 123 to NELIA Policy NF-34.
ASHBURN, D. J. Marsh & McLennan, Inc. 83/03/18 SALTZMAN, J. Assistant Director for State & Licensee Relations 2pp 17681 093

8303240206 Forwards Endorsement 57 to NELIA Policy NF-193.
ASHBURN, D. J. Marsh & McLennan, Inc. 83/03/18 SALTZMAN, J. Assistant Director for State & Licensee Relations 2pp 17682 184

8303240256 Advises that responses to NRC 830115 request for addl info re NEDE-21175-3(P) will be submitted by 830401.
QUIRK, J. F. General Electric Co. MFN-057-83 83/03/18 THOMAS, C. O. Standardization & Special Projects Branch 1p 17682 138

8303250023 Forwards Rev 0 to nonproprietary WCAP-8587, Suppl 1, "Equipment Qualification Data Packages" & proprietary WCAP-8687, Suppl 2, "Equipment Qualification Test Repts." Proprietary repts withheld (ref 10CFR2.790).
RAHE, E. P. Westinghouse Electric Corp. 9872A:1 83/02/28
THOMAS, C. O. Standardization & Special Projects Branch 7pp 17691 320

--8303250039 Submits application for withholding Rev 0 to proprietary WCAP-8687, Suppl 2, "Equipment Qualification Test Repts." per 10CFR2.790 Affidavit encl.
WIESEMANN, R. A. Westinghouse Electric Corp. AW-83-18 83/03/07
THOMAS, C. O. Standardization & Special Projects Branch 9pp 17691 325

--8303250044 WCAP-8587S1R0 ESE-49
Nonproprietary "Equipment Qualification Data Package," Rev 0 to Suppl 1, EQDP-ESE-49, "Differential Pressure Indicating Switch Qualifaction Group A."
RAHE, E. P. Westinghouse Electric Corp. EQDP-ESE-49 83/01/31
18pp 17691 336

--8303250045 WCAP-8587S1R0 ESE-42
Nonproprietary "Equipment Qualification Data Package," Rev 0 to Suppl 1, EQDP-ESE-42, "Resistance Temp Detectors Surface Mounted."
RAHE, E. P. Westinghouse Electric Corp. EQDP-ESE-42 83/01/31
23pp 17692 015

--8303250047 WCAP-8587S1R0 ESE-27
Nonproprietary "Equipment Qualification Data Package," Rev 0 to Suppl 1, EQDP-ESE-27, "N-16 Gamma Detection & High Voltage Distribution Box."
RAHE, E. P. Westinghouse Electric Corp. EQDP-ESE-27 83/01/31
24pp 17692 039

--8303250049 WCAP-8587S1R0 ESE-48
Nonproprietary "Equipment Qualification Data Package," Rev 0 to Suppl 1, EQDP-ESE-48, "High Vol Sensor Qualification Group A."
RAHE, E. P. Westinghouse Electric Corp. EQDP-ESE-48 83/01/31
18pp 17691 355

8303280312 Forwards SWRI Quarterly Progress Rept 7, "Seismic Qualification of Nuclear Plant Mechanical & Electrical Equipment." W/o encl.
CAMPBELL, W. E. Mechanical/Structural Engineering Branch
NRC-04-81-185 83/03/23 MORRIS, W. Electrical Engineering Branch
NOONAN, V. Equipment Qualification Branch BOSNAK, R. J. Mechanical Engineering Branch 1p 17713 297

8303290355 Comments on proposed generic ltr to PWRs re NUREG-0737 Tech Specs. Delay in inclusion of identified items in Tech Specs to be consistent w/issuance of new rule recommended.
SHEPPARD, J. J. Westinghouse Operating Plants Owners Group
SHEPPARD, J. J. Carolina Power & Light Co. OG-93 83/03/21
EISENHUT, D. G. Division of Licensing 3pp 17716 258

8303290358 Advises of recent reorganization of vendor power sys group. Updated organization charts will be formally submitted during Second Quarter 1983.
SCHERER, A. E. Combustion Engineering, Inc. LD-83-011 83/03/24
HAASS, W. P. Quality Assurance Branch 1p 17716 257

8303290594 Forwards Task 1 Summary Repts Parts I & II, "Seismic Qualification of Nuclear Plant Mechanical & Electrical Equipment." Comments on encl draft Task 2 summary rept requested by 830401.
CAMPBELL, W E Mechanical/Structural Engineering Branch
NRC-04-81-185 83/03/17 MORRIS, W Electrical Engineering Branch
NOONAN, V Equipment Qualification Branch BOSNAK, R J Mechanical Engineering Branch 1p 17739 005

--8303290606 SWRI-6582-002 DRFT
"Correlation of Methodologies For Seismic Qualification Tests of Nuclear Plant Equipment," Task 2 summary rept
KANA, D D , POMERENING, D J Southwest Research Institute
NRC-04-81-185 83/03/11 Office of Nuclear Regulatory Research, Director 91pp 17739 006

--8303290613 SWRI 6582-001 R01
"Survey of Methods For Seismic Qualification of Nuclear Plant Equipment & Components," Task 1 Summary Rept Part I
KANA, D D , SIMONIS, J C , POMERENING, D J Southwest Research Institute NRC-04-81-185 82/10/15 Office of Nuclear Regulatory Research, Director 185pp 17739 097

--8303290631 SWRI 6582-001 R02
"Evaluation of Methodology For Seismic Qualification of Nuclear Plant Electrical & Mechanical Equipment," Task 1 Summary Rept Part II
KANA, D D , POMERENING, D J , UNRUH, J F Southwest Research Institute NRC-04-81-185 83/02/01 Office of Nuclear Regulatory Research, Director 137pp 17739 282

8303300221 Forwards high & low pressure basic versions of FR-P 1, "Response to Imminent Pressurized Thermal Shock Condition" & FR-P 2, "Response to Anticipated Pressurized Thermal Shock Condition."
SHEPPARD, J J Westinghouse Operating Plants Owners Group
SHEPPARD, J J Carolina Power & Light Co OG-91 83/03/14
EISENHUT, D G Division of Licensing 2pp 17735 162

--8303300229 "Response to Imminent Pressurized Thermal Shock Condition," w/background info.
* Westinghouse Electric Corp 82/12/01 52pp 17735 164

--8303300237 "Response to Anticipated Pressurized Thermal Shock Condition," w/background info.
* Westinghouse Electric Corp 82/12/01 14pp 17735 216

--8303300244 "Response to Imminent Pressurized Thermal Shock Condition," w/background info.
* Westinghouse Electric Corp 82/12/01 52pp 17735 230

--8303300252 "Response to Anticipated Pressurized Thermal Shock Condition," w/background info.
* Westinghouse Electric Corp 82/12/02 14pp 17735 282

8303300376 Forwards proprietary "Measured Power Distribution Uncertainty Using Symmetry Option." Withheld (ref 10CFR2 790).
CHANDLER, J C Exxon Nuclear Co , Inc (subs of Exxon Corp ) JCC 046 83 83/03/21 THOMAS, C O Standardization & Special Projects Branch 1p 17731 166

8303300406 Reiterates position that plant design for combination of seismic & pipe break loads for piping, components & supporting structures is unnecessary. Tasks in Helba analysis, scope & cost & associated tables encl.
EDELMAN, M Atomic Industrial Forum 83/03/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp 17731 057

8303300542 Forwards proprietary response to 830201 request for addl info on Rev 1 of proprietary WCAP-10021, "Westinghouse Wet Annular Burnable Absorber Evaluation Rept." Response withheld (ref 10CFR2 790).
RAHE, E P Westinghouse Electric Corp NS-EPR-2729 83/03/11
THOMAS, C O Standardization & Special Projects Branch 2pp 17731 157

--8303300547 Requests that 830311 response to request for addl info re Rev 1 to proprietary WCAP-10021 be withheld from public disclosure per 10CFR2 790.
WIESEMANN, R A Westinghouse Electric Corp AW-83-17 83/03/11
THOMAS, C O Standardization & Special Projects Branch 7pp 17731 159

## WASTE MGT NUCLEAR WASTE MANAGEMENT

8303010023 Forwards Mod A002 to Cooperative Agreement DE-FC04-81AL16257 between DOE & State of CO. Mod complies w/provisions of U Mill Tailings Radiation Control Act of 1978.
HAWKINS, E F Low Level Waste Licensing Branch 83/02/16 HILL, T V Energy, Dept of 4pp 17322 344

8303010029 Accepts invitation for TC Johnson to participate in Advisory Group on Low Level Waste Mgt.
HAWKINS, E F Low Level Waste Licensing Branch 83/02/09
CLEMENTE, F Pennsylvania State Univ 1p 17322 343

8303010035 Advises that proposed 830131 meeting w/L Boggs of American Mining Congress to discuss 40CFR190 agreeable to all appropriate staff. Recipient attendance not required. Attendance list provided. Briefing paper will be submitted.
BROWNING, R E Division of Waste Management 83/01/26 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 1p 17322 342

8303010083 Advises that environ assessment for proposed remedial action program at Monument Valley will be forwarded by Ford, Bacon & Davis. Duplicate sets of comments should be sent to listed individuals.
MORLEY, J A Energy, Dept of 83/02/08 HAWKINS, E Low Level Waste Licensing Branch 1p 17322 337

8303010088 Forwards "Edgemont Remedial Action Program," monthly rept for Jan 1983.
JACKSON, P O , PERKINS, R W , WOGMAN, N A Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 83/02/11 FLORY, C A Low Level Waste Licensing Branch 1p 17322 325

--8303010093 "Edgemont Remedial Action Program," monthly rept for Jan 1983.
WOGMAN, N A , JACKSON, P O Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 83/02/11 NRC - No Detailed Affiliation Given 11pp 17322 326

8303010092 Forwards public hearing info on draft DOE/EIS-0099-D, "Remedial Actions at Former Vitro Chemical Co Site, South Salt Lake, Salt Lake County, UT," (Feb 1983).
MARLEY, J A Energy, Dept of 83/02/09 SCARANO, R A Division of Waste Management 5pp 17322 320

8303010095 "Edgemont Remedial Action Program," monthly rept for Dec 1982.
WOGMAN, N A , JACKSON, P O Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 83/01/24 FLORY, C A Uranium Recovery Licensing Branch 12pp 17347 342

8303010097 Forwards "Edgemont Remedial Action Program," monthly rept for Sept 1982.
JACKSON, P O , PERKINS, R W , WOGMAN, N A Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 82/11/10 FLORY, C A Uranium Recovery Licensing Branch 1p 17347 330

--8303010107 "Edgemont Remedial Action Program," monthly rept for Sept 1982.
WOGMAN, N A , JACKSON, P O Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 82/11/10 NRC - No Detailed Affiliation Given 11pp 17347 331

8303010139 Forwards "Edgemont Remedial Action Program," monthly ltr rept for Nov 1982.
PERKINS, R W , WOGMAN, N A Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 82/12/22 FLORY, C A Uranium Recovery Licensing Branch 1p 17355 076

--8303010147 "Edgemont Remedial Action Program," monthly ltr rept for Nov 1982.
WOGMAN, N A , JACKSON, P O Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 82/12/22 NRC - No Detailed Affiliation Given 9pp 17355 077

8303010313 Forwards "Edgemont Remedial Action Program," monthly ltr rept for Oct 1982.
PERKINS, R W Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 82/11/17 FLORY, C A Uranium Recovery Licensing Branch 1p 17348 352

--8303010321 "Edgemont Remedial Action Program," monthly ltr rept for Oct 1982.
WOGMAN, N A , JACKSON, P O Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2217 82/11/17 NRC - No Detailed Affiliation Given 9pp 17348 353

8303090036 Forwards "Rn-222 Rept for Dec 1982."
CAIN, J Cotter Corp 00091 83/02/10 HAZLE, A J Colorado, State of 2pp 17466 079

--8303090037 "Rn-222 Rept for Dec 1982."
* Cotter Corp 00091 83/02/10 1p 17466 081

8303090147 Forwards "General Air Summaries, Fourth Quarter 1982." Cumulative summaries for 1982 included.
CAIN, J Cotter Corp 00090 83/02/10 HAZLE, A J Colorado, State of 2pp 17465 248

--8303090157 "General Air Summaries,Fourth Quarter 1982." Cumulative summaries for 1982 encl.
* Cotter Corp. 00090 83/02/08 3pp 17465:250.

8303090331 Forwards TX Dept of Health 830204 ltr requesting NRC comments on proposed license amend for Anaconda Minerals Rhode Ranch.Comments requested by 830228.
NUSSBAUMER,D.A. Assistant Director for State Agreements Programs. 00085 83/02/10. SMITH,R.D. Uranium Recovery Field Office.
FONNER,R. Office of the Executive Legal Director. 1p. 17484:222.

--8303090337 Forwards draft Amend 1 to Anaconda Minerals Co Rhode Ranch License 8-3304.Encl draft response to NRC 821213 ltr adequately addresses NRC comments on license.Comments requested by 830228.
BAILEY,E.D. Texas, State of. 00085. 83/02/04. NUSSBAUMER,D.A. Assistant Director for State Agreements Programs. 16pp. 17484:223.

8303170242 Advises that proposed language re NRC reporting requirements & reporting identification symbols will be included in all future ltrs granting licenses.
BROWNING,R.E. Division of Waste Management. 83/02/25. BURNETT,R.F. Division of Safeguards. 1p. 17623:340.

8303170287 Comments on DOE "Waste Classification;Proposed Methodology for Classifying Low Level Radwaste." Rept classifies waste by total hazard.Rept has little practical use for low level waste classification.
JACKSON,K. Low Level Waste Licensing Branch. 83/02/24. Low Level Waste Licensing Branch. 2pp. 17623:071.

8303180056 Forwards info on 14 properties contaminated w/residual radioactive matl derived from Grand Junction,CO inactiv U mill tailings site.W/o encl.
BAUBLITZ,J.E. Energy, Dept of. 83/02/22. HAWKINS,E.F. Low Level Waste Licensing Branch. 1p. 17625:251.

8303180061 Advises that Ford,Bacon & Davis will forward draft environ assessment for DOE proposed remedial action at Tuba City inactive U mill tailings site.Comments requested by 830324.
MORLEY,J.A. Energy, Dept of. 83/02/22. HAWKINS,E. Low Level Waste Licensing Branch. 1p. 17625:240.

8303180071 Forwards trip rept of DF Ross 830108-22 visit to Japan, Taiwan & Korea to discuss plans for cooperative agreement w/JAERI re research in high level waste mgt.
BROWNING,R. Division of Waste Management. WM-83-121. 83/03/02. BENNETT,J.W. Energy, Dept of. 1p. 17624:008.

--8303180081 Responds to 830208 ltr re potential for cooperative agreement w/JAERI on research in high level waste mgt.NMSS should be kept informed of all developments.
BROWNING,R.E. Division of Waste Management. WM-83-121. 83/03/02. COMELLA,P.A. Division of Health, Siting & Waste Management. 1p. 17624:009.

--8303180091 Requests to be kept informed of efforts made in reaching cooperative agreement w/JAERI on waste mgt research.Efforts will be of interest to DOE.
COMELLA,P.A. Division of Health, Siting & Waste Management. 83/02/08. BROWNING,R. Division of Waste Management. 1p. 17624:010.

--8303180100 Discusses DF Ross trip to Japan to hold exploratory discussions re possible cooperative research agreement in waste mgt.Encl repts should be reviewed as potential research models.Comments requested by 830214.
COMELLA,P.A. Division of Health, Siting & Waste Management. 83/02/08. ERNST,M. Division of Risk Analysis. 2pp. 17624:011.

--8303180107 Trip rept of 830108-22 visit to Japan,Taiwan & Korea to discuss research agreements,to tour Kuosheng BWR-6 reactor & to discuss possible participation in severe fuel damage program.
ROSS,D.F. Office of Nuclear Regulatory Research, Director. 83/01/26. MINOGUE,R.B. Office of Nuclear Regulatory Research, Director. 25pp. 17624:013.

--8303180111 "Nuclear Safety Research Reactors Severe Fuel Damage Experiments Plan," draft rept.
* Japan, Govt of. 83/01/31. 17pp. 17624:039.

--8303180115 57-238
"Tentative Program of Nuclear Safety Research Reactors Experiment for FY82."
* Japan, Govt of. 82/09/30. 46pp. 17624:057.

--8303180120 "Safety Study on Ground Disposal of Low Level Wastes."
* Japan, Govt of. 83/03/02. 17pp. 17624:103.

--8303180123 "Rept on Safety Research of High Level Waste Mgt," draft rept.
* Japan, Govt of. 83/03/02. 49pp. 17624:120.

--8303180126 82-145
"Progress Rept on Safety Research of High Level Waste Mgt for Period Apr 1981 - May 1982."
TASHIRO,S. Japan, Govt of. 82/10/31. 75pp. 17624:169.

8303180074 Nominates DE Martin to replace K Hamill as Waste Mgt Div representative on 10CFR40 App A task force;effective immediately.
BROWNING,R.E. Division of Waste Management. 414.8.2/EFH/83/. 83/03/04. CUNNINGHAM,R.E. Division of Fuel Cycle & Material Safety. 1p. 17625:215.

8303180079 Forwards documents re free standing liquids in radwaste per telephone request.Waste generators should have option whether to solidify ion exchange resin & sludge wastes or dispose in dewatered condition in high integrity container.
HAWKINS,E. Low Level Waste Licensing Branch. 204.1.5/TJ/83/0. 83/03/03. GORN,J. Office of Congressional Affairs. 3pp. 17625:212.

8303180098 Reviews plan for final closure of Maxey Flats site. Long-term decommissioning plans may be more cost effective than short-term plans.Specific comments encl.
HAWKINS,E.F. Low Level Waste Licensing Branch. 201.6/RAP/83/2/. 83/02/23. NUSSBAUMER,D.A. Assistant Director for State Agreements Programs. 4pp. 17625:193.

8303180135 Forwards "Breathing Zone Summary for 1983" & "Breathing Zone for Airborne Particulates,Cotter Employees,for Feb 1983."
LANDAU,S. Cotter Corp. 1011K8610-43-4. 83/03/02. HAZLE,A.J. Colorado, State of. 2pp. 17624:357.

--8303180142 "Breathing Zone Summary for 1983" & "Breathing Zone for Airborne Particulates,Cotter Employees,Feb 1983."
* Cotter Corp. 00146. 83/03/01. 2pp. 17624:359.

8303180147 Informs that TX Dept of Health matl on NRC comments reviewed.Dept has not incorporated significant license conditions recommended by NRC re cover,dewatering of tailings & borings program.
SMITH,R.D. Uranium Recovery Field Office. 00085. 83/03/03. NUSSBAUMER,D.A. Office of State Programs, Director. 2pp. 17626:012.

8303180152 Submits compilation of FY82 products listed in Low Level Waste & U Recovery Licensing Branches completed through 830124.
HAWKINS,E. Low Level Waste Licensing Branch. 424.1/PHL/83/01. 83/02/16. BROWNING,R.E. Division of Waste Management. 2pp. 17626:010.

8303180202 Forwards,for concurrence,Mod A001,supplementing Cooperative Agreement DE-FC04-81AL16309 between DOE & State of UT in support of UMTRA project in UT.Document number & std terms established.W/o encl.
HILL,T.V. Energy, Dept of. 83/03/04. HAWKINS,E.F. Low Level Waste Licensing Branch. 1p. 17625:341.

8303180558 Forwards scope of work for collection of addl geohydrological data at Salt Lake City Vitro site.
KRISHNAN,R. Jacobs Engineering Group, Inc. 83/02/24. MARTIN,D. Low Level Waste Licensing Branch. 15pp. 17640:017.

8303180562 Forwards staff review notes in response to request for review of Nutek oil solidification procedure.Before state could approve agent,listed concerns must be addressed.
KIRNER,N.P. Washington, State of. 83/03/01. JOHNSON,T. Division of Waste Management. 2pp. 17640:037.

8303180572 Summary of 830110 meeting w/CSU in Denver,CO re review of comments on second draft long-term stability of U mill tailings topical rept.W/o encl.
FLEMING,T.E. Uranium Recovery Field Office. 83/02/25. SCARANO,R.A. Low Level Waste Licensing Branch. 2pp. 17640:040.

8303180577 Lists branch significant actions taken to execute NRC responsibilities to participate,review & concur in DOE conduct of UMTRAP.
SCARANO,R.A. Uranium Recovery Licensing Branch. 82/01/28. MARTIN,J.B. Division of Waste Management. 3pp. 17640:044.

8303180581 Forwards State of SC 830209 comments on Vikem Industries topical rept re solidification of contaminated waste lubricator oils.
SCHNEIDER,K.N. Assistant Director for State Agreements Programs. 83/02/22. JOHNSON,T. Division of Waste Management. 1p. 17640:119.

--8303180584 Responds to 830203 request for review of Vikem Industries, Inc topical rept re solidification of contaminated waste lubricator oils. Review of no interest to state since type of waste prohibited at Chem-Nuclear facility.
SHEALY, H. G. South Carolina, State of. 83/02/09. NUSSBAUMER, D. Assistant Director for State Agreements Programs. 1p. 17640:121.

8303180610 Responds to 830202 ltr requesting info on nuclear waste disposal. NRC responsible for regulating disposal of radwaste from licensed activities & high level radwastes generated by DOE. Rept excerpts forwarded W/o encl.
STILL, N. L. Division of Waste Management. WM-83145. 83/03/09. GREER, E. Affiliation Unknown. 1p. 17640:172.

8303180615 Responds to ltr requesting info on nuclear waste disposal. NRC responsible for regulating disposal of radwaste from licensed activities & high level radwastes generated by DOE. Rept excerpts forwarded W/o encl.
STILL, N. L. Division of Waste Management. WM-83108. 83/02/17. SINGLETON, A. Affiliation Unknown. 2pp. 17626:346.

8303180617 Responds to ltr requesting info on nuclear waste. No high level waste disposal sites licensed to date. W/o encl.
STILL, N. L. Division of Waste Management. WM-83109. 83/02/17. ST ROMAIN, G. Affiliation Unknown. 2pp. 17626:348.

8303180621 Responds to ltr requesting info on nuclear waste sites & transportation of nuclear waste matl in State of VA. No federal or state disposal sites exist in VA.
STILL, N. L. Division of Waste Management. WM-83084. 83/02/18. JOHNSON, D. Affiliation Unknown. 1p. 17626:332.

8303180626 Responds to ltr requesting info on nuclear waste. Excerpts from BMNL rept, "Understanding Radwaste," forwarded W/o encl.
STILL, N. L. Division of Waste Management. NMSS-83102. 83/02/17. GASKILL, C. Affiliation Unknown. 2pp. 17626:333.

8303180631 Comments on Edgemont cleanup action program rept for Dec 1982 Engineering assessment repts on verified residual radioactive matl sites should be given priority.
FLORY, C. A. Low Level Waste Licensing Branch. FIN B-2217. 83082. 83/02/25. WOGMAN, N. A. Battelle Memorial Institute, Pacific Northwest Laboratory. 5pp. 17626:310.

8303180635 Responds to inquiry re state statutory authority to impose restrictions on low level radwaste shipment & disposal. Memos presenting NRC legal opinions & 10CFR61 forwarded W/o encl.
BROWNING, R. E. Division of Waste Management. 83/02/10. HOLLINGSWORTH. New Hampshire, State of. 1p. 17626:309.

8303180641 Forwards discussion of waste mgt alternatives for wastes containing chelating agents, describing processes to degrade complexants solidification, use of high integrity containers & disposal options.
HAWKINS, E. Low Level Waste Licensing Branch. 83/02/01. SHEALY, H. South Carolina, State of. 6pp. 17637:144.

8303180646 Comments on Edgemont cleanup action program rept for Nov 1982 Progress of survey & engineering assessment programs satisfactory.
FLORY, C. A. Low Level Waste Licensing Branch. FIN B-2217. WM-83090. 83/02/14. WOGMAN, N. A. Battelle Memorial Institute, Pacific Northwest Laboratory. 1p. 17637:142.

8303180651 Responds to 830208 ltr re nuclear waste storage concept. DOE responsible for R&D of different disposal methods for high level & low level wastes.
STILL, N. L. Division of Waste Management. WM-83136. 83/02/18. RINGER, R. R. Affiliation Unknown. 1p. 17637:143.

8303180653 Forwards comments on draft reg guide re methods for erosion protection of stabilized U tailings site. Discussion of erosion by gullying & evaluation techniques lacking.
PENNIFILL, R. A. Low Level Waste Licensing Branch. 83/02/16. HARMON, D. Waste Management Branch. 5pp. 17637:134.

8303180657 Forwards citizen ltr requesting info on State of MI House Bill 5600 for response. W/o encl.
SURMEIER, J. J. Licensing Process & Integration Branch. 83/03/03. STRASMA, J. R. Region 3, Office of Director. 1p. 17637:125.

8303180659 Advises that NMSS will take lead to incorporate relevant portions of draft "Approaches to Assuring Availability of Funds to Clean Up Contamination Following Release at Nonreactor Nuclear Facility" into Commission paper.
DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director. 83/02/11. KERR, G. W. Office of State Programs, Director. MINOGUE, R. B. Office of Nuclear Regulatory Research, Director. 1p. 17637:123.

8303210016 "Tests for Evaluating Sites for Disposal of Low Level Radwaste," Final rept.
LUTTON, R. J., BUTLER, D. K., MEADE, R. B. Army, Dept. of, Army Engineer Waterways Experiment Station. FIN B-7324-1. NRC-02-81-056. 82/10/31. Low Level Waste Licensing Branch. 173pp. 17659:151.

8303220412 Forwards "Certificate of Water Analysis, Nov 1982." Corrections to Sept 1982 water quality rept listed.
CAIN, J. Cotter Corp. 00061. 83/01/25. HAZLE, A. J. Colorado, State of. 2pp. 17673:109.

--8303220419 "Certificate of Water Analysis, Nov 1982."
MCDOWELL, T., CURREY, M., HERRERA, D. Cotter Corp. 00061. 83/01/21. 4pp. 17673:111.

8303240103 Forwards corrected general air summary for Third Quarter 1982 & corrected cumulative general air summary. Location 0800 changed slightly due to calculational error.
CAIN, J. Cotter Corp. 20872. 82/11/16. HAZLE, A. J. Colorado, State of. 2pp. 17700:296.

--8303240108 Corrected general air summary for Third Quarter 1982 & corrected cumulative general air summary.
* Cotter Corp. 20872. 82/11/16. 3pp. 17700:298.

8303280068 Trip rept of 830207-09 UMTRAP EIS scoping meetings w/DOE in Rifle & Grand Junction, CO.
PANGBURN, G. C. Low Level Waste Licensing Branch. 83/03/08. HAWKINS, E. F. Low Level Waste Licensing Branch. 9pp. 17726:313.

8303280069 Requests assistance in making arrangements for discussion on Basalt Waste Isolation Project groundwater modeling.
MILLER, H. J. High Level Waste Technical Development Branch. 00193. 81/07/16. HEATH, C. Energy, Dept. of. 1p. 17715:362.

8303280070 Lists changes to distribution list for Basalt Waste Isolation Project repts sent to NRC.
MILLER, H. J. High Level Waste Technical Development Branch. 00194. 81/07/21. DEJU, R. A. Energy, Dept. of. 2pp. 17726:306.

8303280072 Provides list of topics for hydrogeology discussion during 810922 visit to Basalt Waste Isolation Project.
WRIGHT, R. J. High Level Waste Technical Development Branch. 00195. 81/08/06. GORANSON, R. Energy, Dept. of. 2pp. 17715:360.

8303280073 Forwards agenda for NRC 810922-24 visit to Basalt Waste Isolation Project.
HEATH, C. A. Energy, Dept. of. 00197. 81/08/19. MARTIN, J. B. Division of Waste Management. 5pp. 17726:308.

8303280076 Requests addl funding for FY83 in order to accomplish accelerated reassessment of radiological measurements based on final EPA stds & to complete addl work re Edgemont cleanup action program.
ROBERTSON, D. E. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN B-2217. 83/03/16. FLORY, C. A. Low Level Waste Licensing Branch. 2pp. 17715:358.

8303280077 Forwards comments by NRC contractors on Rev 3 to "Nuclear Repository in Basalt, Functional Design Criteria," RHO-BWI-CD-38 & "Nuclear Waste Repository in Basalt, Preconceptual Design Rept," RHO-BWI-CD-35.
MILLER, H. J. High Level Waste Technical Development Branch. 00198. 81/09/14. HEATH, C. Energy, Dept. of. 35pp. 17726:350.

8303280082 Provides priority list of performance assessment tasks at Basalt Waste Isolation Project based on review of activities described in 820302 memo.
WRIGHT, R. J. High Level Waste Technical Development Branch. 00054. 82/04/15. BELL, M. J. High Level Waste Licensing Management Branch. 2pp. 17715:352.

8303280083 Comments on rept, "Comparison of Model Studies -- Hanford Site." Rept presents excellent detailed discussion between Richland Headquarters Ofc & PNL re model studies of basin hydraulics.
BROWN, A. Golder Associates. 813-1167. 82/05/03. WRIGHT, R. Division of Waste Management. 4pp. 17715:348.

8303280091 Requests certain info & documentation for development of cooperative agreement w/State of SD re cleanup action program at Edgemont site.
MARQUEZ, R. A. Energy, Dept. of. 83/03/07. MARTIN, D. Low Level Waste Licensing Branch. 2pp. 17715:346.

8303280140 Responds to 830208 request for nuclear waste disposal info. NRC only regulates radwaste disposal. DOE responsible for R&D of different disposal methods. BNWL Doc 1981 rept excerpt not encl.
HALL, J. Licensing Process & Integration Branch. 411 1/JPH/83/03. 83/03/17. JONES, M. L. Affiliation Unknown. 1p. 17713:322.

8303280146 Forwards comments on remedial action concept papers for Grand Junction & Rifle sites, as discussed in 830223 telcon.
HAWKINS, E. F. Low Level Waste Licensing Branch. 83/03/03.
MORLEY, J. A. Energy, Dept. of. 4pp. 17713:314.

8303280292 Reviews monthly rept for Jan 1983 for Edgemont cleanup action program. Response requested if comments could result in changes to costs or final delivery of contract products.
FLORY, C. A. Low Level Waste Licensing Branch. FIN B-2217. 83/03/08.
WOGMAN, N. A. Battelle Memorial Institute, Pacific Northwest Laboratory. 2pp. 17713:312.

8303280300 Accepts invitation to present paper, "NRC Approach to Dealing W/Hazardous Substances in Low Level Radwaste," at ANS June annual meeting in Detroit, MI. W/o encl.
LOHAUS, P. H. Low Level Waste Licensing Branch. 83/03/08.
O'BRIEN, D. E. American Nuclear Society. 1p. 17713:307.

8303280344 Forwards summary chart of commercial low level radwaste disposal facilities.
HAWKINS, E. F. Low Level Waste Licensing Branch. 201. 83/03/08.
BROWNING, R. E. Division of Waste Management. 3pp. 17713:298.

8303290010 Forwards seventh (first FY83) status rept for Edgemont cleanup action program.
FLORY, C. Low Level Waste Licensing Branch. FIN B-2217. 426.2/CF/83/02/. 83/03/04. BAUBLITZ, J. Energy, Dept. of. 1p. 17730:003.

8303290014 Forwards State of NV comments on Viken Industries topical rept for solidification of contaminated waste lubricator oils.
SCHNEIDER, K. N. Assistant Director for State Agreements Programs. SA/KNS. 83/03/18. JOHNSON, T. Division of Waste Management. 1p. 17730:028.

--8303290017 Comments on rept, "Results of Test Program for Solidification of Contaminated Waste Lubrication Oils." All shipping containers must pass insp for free liquid (0.05 ml) prior to approval of any solidification procedure.
VADEN, J. Nevada, State of. 83/02/24. NUSSBAUMER, D. Assistant Director for State Agreements Programs. 1p. 17730:029.

8303290050 Forwards draft FR notice of availability of site characterization rept for Basalt Waste Isolation Project.
SAVOLAINEN, A. W. Policy & Publications Management Branch. 00078. 82/11/03. BUNTING, J. O. Licensing Process & Integration Branch. 3pp. 17729:275.

8303290060 Notification of 820618 meeting in Richland, WA to discuss underground testing at Basalt Waste Isolation Project.
PRESTHOLT, P. T. High Level Waste Technical Development Branch. 00056. J2/06/17. High Level Waste Technical Development Branch. 1p. 17729:273.

8303290068 Forwards final rept of Sept 1980 visit to Basalt Waste Isolation Project, in response to H Miller request. W/o encl.
WRIGHT, R. J. High Level Waste Technical Development Branch. 00267. 81/12/24. PARKER, F. L. Tennessee, State of. 1p. 17729:272.

8303290131 Trip rept of 820809-12 geochemistry workshop in Richland, WA. Rept is compilation of written record of matters re geochemistry-oriented portions of joint workshop, including contractor repts.
JUSTUS, P. S. High Level Waste Technical Development Branch. 82/09/13. MILLER, H. J. High Level Waste Technical Development Branch. 2pp. 17728:001.

8303290545 Forwards guidelines for preparation of site issue analyses.
WRIGHT, R. J. High Level Waste Technical Development Branch. 00104. 82/10/04. BOYLE, R., COOK, R., GREEVES, J. NRC - No Detailed Affiliation Given. 2pp. 17740:361.

8303290550 Forwards matl presented during 821022 meeting w/State of WA high level nuclear waste mgt task force in Richland, WA.
OLSON, O. L. Energy, Dept. of. 00210. 82/11/03. MILLER, H. J. High Level Waste Technical Development Branch. 92pp. 17742:093.

8303290551 Forwards Basalt Waste Isolation Project trip rept. W/o encl.
MILLER, H. J. High Level Waste Technical Development Branch. 00200. 81/12/17. COOLEY, C. Energy, Dept. of. 1p. 17743:199.

8303290559 Requests suggestions on how to obtain info requested in encl Sandia Labs 810406 ltr re Hanford project.
WRIGHT, R. J. High Level Waste Technical Development Branch. 00191. 81/04/21. NEWTON, C. Energy, Dept. of. 1p. 17745:197.

--8303290742 Requests listed documents referenced in Basalt Waste Isolation Project data package to develop realistic ref repository definition.
FINLEY, N. C. Sandia Laboratories. 81/04/06. ROSSBACH, L. W. High Level Waste Licensing Management Branch. 3pp. 17745:198.

8303290563 Proposes Basalt Waste Isolation Project visit to update NRC info on developments in site selection. Subjs of particular interest listed.
MILLER, H. J. High Level Waste Technical Development Branch. 00192. 81/05/26. HEATH, C. Energy, Dept. of. 1p. 17742:361.

8303290564 Trip rept of visit to Basalt Waste Isolation Project, BNL & QA, Co re waste package issues. Importance of multiple barrier concepts emphasized.
COOK, F. R. High Level Waste Technical Development Branch. 00068. 82/09/21. BELL, M. J. High Level Waste Technical Development Branch. 2pp. 17742:040.

--8303290566 Provides impressions of Basalt Waste Isolation Project technical program. Technical staff has clear comprehension of problems. DOE commitment of resources questioned.
MCNEIL, M. B. Waste Management Branch. 82/08/20. COOK, R. F. High Level Waste Licensing Management Branch. 8pp. 17742:042.

--8303290570 "Trip Rept: Pre-SCR (Site Characterization Rept) Review Workshop on Waste Package Design & Geochemistry Research for Waste Repository in Basalt," internal rept.
SIEGEL, M. Sandia Laboratories. 82/08/31. 31pp. 17742:050.

--8303290575 Forwards summary of 820809-12 Basalt Waste Isolation Project waste package workshop at Rockwell Hanford Operations. Plans for future tests & analyses required to resolve key issues discussed.
TALBOT, R. Golder Associates. NRC-02-81-027. 0/82/300. 82/09/10. COOK, F. R. High Level Waste Technical Development Branch. 12pp. 17742:081.

8303290565 Expresses appreciation for Rockwell documents forwarded on 821029. Date of receipt of RHO-BWI-CR-128P & RSD-BWI-CR-004 requested.
WRIGHT, R. J. High Level Waste Technical Development Branch. 00211. 82/11/04. OLSON, O. L. Energy, Dept. of. 1p. 17742:[illegible]2.

8303290569 Forwards RHO-BW-CR-128P & RHO-BW-EV-1P re geothermal resource potential assessment & NWTS-33(2) re criteria & screening consideration comparison, respectively, per 811104 request. W/o encl.
OLSON, O. L. Energy, Dept. of. 00212. 82/11/12. WRIGHT, R. J. High Level Waste Technical Development Branch. 1p. 17742:001.

8303290581 Forwards updated "Comparison of Model Studies: Hanford Reservation." Document rewritten to reflect concerns of technical reviewers.
QUINN, E. J. High Level Waste Technical Development Branch. 00063. 82/08/26. KNAPP, M. R. High Level Waste Technical Development Branch. 1p. 17740:286.

--8303290588 Updated "Comparison of Model Studies: Hanford Reservation."
LEHMAN, L. L., QUINN, E. J. High Level Waste Technical Development Branch. 00063. 82/08/26. 69pp. 17740:287.

8303290587 Comments on Basalt Waste Isolation Project Mgt reply to geochemistry paper. Future data analysis recommendations listed.
LEHMAN, L. Affiliation Unknown. 00058. 82/07/22. WRIGHT, R. NRC - No Detailed Affiliation Given. 12pp. 17743:296.

8303290593 Forwards geochemical data received during visit to Basalt Waste Isolation Project for 820721-27 hydrology workshop. Info preliminary so inconsistencies may exist. Clarifications noted.
QUINN, E. J. High Level Waste Licensing Management Branch. 00060. 82/08/16. WILLIAMS, R. E. Williams-Robinette & Associates, Inc. 20pp. 17743:339.

8303290595 Forwards "Mock Site Characterization Review of Basalt, Hanford Site," fulfilling operating plan Commitment 311253.
KNAPP, M. R. High Level Waste Licensing Management Branch. 00045. 81/10/01. MARTIN, J. B. Division of Waste Management. 1p. 17744:215.

--8303290601 "Mock Site Characterization Review of Basalt, Hanford Site."
LEHMAN, L., QUINN, E. NRC - No Detailed Affiliation Given. 00045. 81/10/01. 34pp. 17744:216.

8303290598 Forwards tabulation of research activities for transmittal to E Moore, as followup to waste form/waste package workshop.
WRIGHT, R. J. High Level Waste Technical Development Branch. 82/10/19. OLSON, L. Energy, Dept. of. 18pp. 17743:029.

8303290604 Forwards "Analysis of Boundary Conditions & Conductivity Ratios Used in Pasco Basin Modeling," documenting sensitivity studies conducted on NRC far-field model at Hanford site.
QUINN, E. J. High Level Waste Licensing Management Branch. 00064. 82/08/27. KNAPP, M. R. High Level Waste Licensing Management Branch. 1p. 17744:281.

--8303290610 "Analysis of Boundary Conditions & Conductivity Ratios Used in Pasco Basin Modeling."
QUINN, E. J. NRC - No Detailed Affiliation Given. 00064. 82/08/27. 63pp. 17744:282.

8303290612 Trip rept of visit to Hanford, WA re Rockwell Hanford Operations Hydrologic modeling efforts to integrate & explain behavior of flow sys underlying Hanford Reservation.
LEHMAN, L. L. High Level Waste Licensing Management Branch. 00046. 81/11/23. BELL, M. J. High Level Waste Licensing Management Branch. 26pp. 17745:001.

8303290616 Forwards agenda for presite characterization rept hydrology 821101-03 meetings w/contractors in Silver Spring, MD to discuss preparation of draft apps, site issue analyses & mockup groundwater chapter.
VERMA, T. R. High Level Waste Technical Development Branch. NRC-02-82-044. 00314. 82/10/28. WILLIAMS, R. E. Williams & Associates, Inc. 3pp. 17745:050.

8303290623 Forwards agenda for presite characterization rept hydrology 821101-03 meetings w/contractors in Silver Spring, MD to discuss preparation of draft apps, site issue analyses & mockup groundwater chapter.
VERMA, T. R. High Level Waste Technical Development Branch. NRC-02-82-045. 00110. 82/10/28. ROWE, J. Golder Associates. 3pp. 17745:116.

8303290626 Provides questions NRC should consider in reviewing upcoming DOE site characterization rept for Hanford basalt site. Questions are direct result of evaluating high resolution geophysical techniques.
ARMANTROUT, G. A., RAMIREZ, A. L., ROGUE, F. Lawrence Livermore Laboratory. LR 82-11-03. 82/11/10. BERATAN, L. NRC - No Detailed Affiliation Given. 6pp. 17744:357.

8303290630 Forwards draft mockup chapter for site characterization assessment & seven new Basalt Waste Isolation Project documents. Preparation of groundwater chapter for presentation at 821101 meeting requested. W/o encls.
VERMA, T. R. High Level Waste Technical Development Branch. NRC-02-82-044. 00106. 82/10/21. WILLIAMS, R. E. Williams & Associates, Inc. 1p. 17745:119.

8303290632 Requests rept on all Indian tribal rights which could affect Hanford site characterization process & analysis of extent of Indian rights. Relationship between Indian rights, laws & NRC statutory goals must be defined.
DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director. 00299. 82/10/12. CUNNINGHAM, G. H. Office of the Executive Legal Director. 2pp. 17743:361.

8303290650 Forwards draft summary of Basalt Waste Isolation Project 791205-06 annual technical info meeting in Richland, WA. Comments requested by 800123. W/o encl.
BOYLE, R. R. High Level Waste Licensing Management Branch. 00005. 80/01/17. BERATAN, L., COMELLA, P., HARTUNG, L. Office of Standards Development, Director. 1p. 17745:171.

8303290655 Trip rept of Basalt Waste Isolation Project 801205-06 annual technical info meeting in Richland, WA.
BOYLE, R. R. High Level Waste Licensing Management Branch. 00316. 80/02/05. MALARO, J. C. High Level Waste Licensing Management Branch. 12pp. 17742:336.

8303290658 Forwards draft mockup chapter for site characterization assessment & seven new Basalt Waste Isolation Project documents. Preparation of groundwater chapter for presentation at 821101 meeting requested. W/o encls.
VERMA, T. R. High Level Waste Technical Development Branch. NRC-02-82-045. 00107. 82/10/21. ROWE, J. Golder Associates. 1p. 17742:348.

8303290659 Notifies of 810921 meeting w/NRC participants in Richland, WA to discuss div of responsibility for Basalt Waste Isolation Project.
WRIGHT, R. J. High Level Waste Technical Development Branch. 00042. 81/08/26. WILLIAMS, R. E. R. E. Williams & Associates, Inc. 1p. 17742:349.

8303290664 Forwards Basalt Waste Isolation Project site review plan. Review will replace review of site screening rept, canceled by DOE. Partial list of geotechnical & design issues in Pasco Basin encl.
PRESTHOLT, P. T. High Level Waste Technical Development Branch. 00041. 81/07/23. MILLER, H. J. High Level Waste Technical Development Branch. 13pp. 17743:001.

8303290705 Summary of 810616 meeting in Silver Spring, MD re site suitability issues concerning Pasco Basin geochemistry to be discussed in LBL Task I basalt rept.
COPLAN, S. M. High Level Waste Technical Development Branch. 81/06/26. MILLER, H. J. High Level Waste Technical Development Branch. 2pp. 17730:350.

8303290709 Notification of 810611 meeting in Silver Spring, MD to discuss setup of SWIFT code & conceptual model of hydrology at Hanford site.
LEHMAN, L. L. High Level Waste Licensing Management Branch. 00039. 81/06/08. MILLER, H. J., ALEXANDER, D. H., COPLAN, S. M. High Level Waste Technical Development Branch. 2pp. 17730:348.

8303290724 Notification of 820915 meeting in Silver Spring, MD to prepare for Basalt Waste Isolation Project 821004 design workshop.
GREEVES, J. T. High Level Waste Technical Development Branch. 00067. 82/09/14. MILLER, H. J. High Level Waste Technical Development Branch. 3pp. 17746:310.

8303290780 Forwards draft tables of Kd values & solubility data for various isotopes for Basalt Waste Isolation Project sensitivity analyses. Lowest values should be used to achieve conservative results.
BROOKS, D. J. High Level Waste Technical Development Branch. 00065. 82/09/07. WISE, M. J., KNAPP, M. R. High Level Waste Licensing Management Branch. 6pp. 17746:142.

8303290782 Forwards marked-up "Review of Geological & Hydrologic Issues re Waste Isolation in Columbia River Basalts," & "Rept on Hydrologic Studies Within Columbia Plateau: Basalt Waste Isolation Project."
MILLER, H. J. Division of Waste Management. 00049. 82/02/04. WRIGHT, GREEVES, JUSTUS. NRC - No Detailed Affiliation Given. 60pp. 17746:081.

8303290817 Forwards geochemical data received during visit to Basalt Waste Isolation Project for 820721-27 hydrology workshop. Info preliminary so inconsistencies may exist.
QUINN, E. J. High Level Waste Licensing Management Branch. 00061. 82/08/16. ROWE, J. Golder Associates. 2pp. 17748:071.

8303290820 Discusses progress made since Jul 1980 site visit re regulations for high level radwaste repository.
WRIGHT, R. J. High Level Waste Technical Development Branch. 00265. 81/10/07. HULL, D. A. Washington, State of. 2pp. 17748:069.

8303290826 Summary of 820729 meeting w/BNL, Sandia & Golder Assoc in Bethesda, MD re preparation for Basalt Waste Isolation Project 820809-13 waste package workshop.
WICK, F. A. High Level Waste Licensing Management Branch. 00059. 82/08/03. High Level Waste Licensing Management Branch. 6pp. 17748:058.

8303290830 Forwards Confederated Tribes & Bands, Yakima Indian Nation, 811112 ltr to DOE re recognition of Indian rights by environ studies.
MENINICK, J. Confederated Tribes & Bands Yakima Indian Nation. 00298. 81/12/10. OSTROWSKI, C. NRC - No Detailed Affiliation Given. 4pp. 17748:049.

--8303290834 Requests Yakima Indian Nation be consulted prior to approval of EIS in order to protect Indian civil & human rights.
MENINICK, J., TOMASKIN, L. Confederated Tribes & Bands Yakima Indian Nation. 00298. 81/09/22. AULUCK, R. Division of Licensing. 5pp. 17748:053.

8303290849 Notifies of 821206 meeting w/DOE in Olympia, WA to brief high level nuclear waste mgt task force on site characterization rept.
LEWIS, N. D. Washington, State of. 00273. 82/11/05. BOYLE, B. J., STEVENS, D., GIBBS, A. J. Washington, State of. 1p. 17746:074.

8303290856 "Evaluation of Rept 'Geochemical Interpretations of Groundwater Flow Sys in Central Columbia Plateau' by Lehman & Quinn."
* Basalt Waste Isolation Project. 00057. 82/07/01. 40pp. 17746:004.

8303300050 Forwards "Water Quality Rept, Jan 1983." Th-230 & Pb-210 levels for Location 519 are being reanalyzed by outside lab for verification. Correction to Dec 1982 water quality rept requested.
CAIN, J. Cotter Corp 00171 83/03/08 HAZLE, A. J. Colorado State of 2pp 17751:095

--8303300056 "Water Quality Rept, Jan 1983."
KRAUTH, M. ; GOFF, M. ; HULSEY, D. Cotter Corp 01-83 83/03/08
6pp 17751:097

8303300053 Forwards response to request from 820721-23&26-27 Geohydrology Workshop for list of WA State contractors who are & have been performing work on Basalt Waste Isolation Project.
STEIN, R. Energy, Dept of 00205 82/09/21 MILLER, H. J. High Level Waste Technical Development Branch 4pp 17751:090

8303300060 Informs of assignment of Waste Mgt Project Number WM-10 to Basalt Waste Isolation Project upon receipt of site characterization rept. Project number provides mechanism for grouping all subsequent matl in PDR.
STILL, N. Division of Waste Management 00082 82/11/12 High Level Waste Licensing Management Branch 1p 17751:089

8303300064 Confirms 821013 discussion w/B Bennett re submission of site characterization rept to NRC & public. Sizable demand for rept possible. Draft FR notice encl.
MILLER, H. J. High Level Waste Technical Development Branch 00208
82/10/19 BALLARD, W. W. Energy, Dept of 7pp 17751:067

8303300074 Informs that listed individuals will probably participate in visit to Basalt Waste Isolation Project beginning 810922.
WRIGHT, R. J. High Level Waste Technical Development Branch 00199
81/09/14 GORANSON, R. Energy, Dept of 2pp 17751:057

8303300082 Comments on four matters re Basalt Waste Isolation Project draft list of repository siting & design issues to be forwarded for comment.
WRIGHT, R. J. High Level Waste Technical Development Branch 00201
82/05/05 GORANSON, R. Energy, Dept of 3pp 17751:052

8303300083 Forwards marked-up comments on draft NRC document on farfield groundwater modeling. Aspects of modeling apparently misunderstood.
BALLARD, W. W. Energy, Dept of 00202 82/07/15 MARTIN, J. Division of Waste Management 9pp 17750:319

8303300086 Advises that all refs to 10CFR60 made during review of site characterization rupt for Basalt Waste Isolation Project must relate to same draft.
WRIGHT, R. J. High Level Waste Technical Development Branch 00109
82/10/27 High Level Waste Technical Development Branch 2pp
17754:157

8303300091 Forwards refs listed in Basalt Waste Isolation Project site characterization rept. Some refs deleted from rept or unavailable until 821115.
OLSON, O. L. Energy, Dept of 00209 82/10/29 WRIGHT, R. J. High Level Waste Technical Development Branch 2pp 17751:361

8303300095 Summary of waste package team 820913-14 meeting w/BNL, GAI & SLA re preparation of waste package portion of site characterization analysis & apps.
CHANG, K. C. High Level Waste Technical Development Branch 00105
82/10/06 BELL, M. J. High Level Waste Technical Development Branch
27pp 17749:177

8303300098 Notifies of 821012 briefing on results of outside site characterization rept review plans, products & schedules.
MILLER, H. J. ; BELL, M. J. High Level Waste Technical Development Branch 82/10/06 High Level Waste Licensing Management Branch
1p 17749:204

8303300107 Forwards briefing package describing specific products, schedules & overall program approach for completion of site characterization rept review. Revised "Review Plan for Site Characterization Repts." also encl.
MILLER, H. J. High Level Waste Technical Development Branch 00069
82/09/30 MARTIN, H. J. Division of Waste Management 1p
17749:210

--8303300120 "NRC High Level Waste Licensing Site Characterization Review Process."
* NRC - No Detailed Affiliation Given 00069 82/09/30 20pp
17749:211

--8303300122 Rev 1 to, "Review Plan for Site Characterization Repts."
* Division of Waste Management 00069 82/05/31 25pp
17749:231

8303300124 Forwards minutes of DOE/NRC Repository 821005 & 06 workshops in Richland, WA. "Info Requests by NRC" items listed along w/commitment date when Basalt Waste Isolation Project mgt can submit items to NRC.
OLSON, O. L. Energy, Dept of 00206 82/10/15 MILLER, H. J. High Level Waste Technical Development Branch 6pp 17748:356

8303300126 Lists Sandia staff that will participate in Basalt Waste Isolation Project Sept 1981 visit.
ROSSBACH, L. W. High Level Waste Licensing Management Branch 00043
81/09/08 PRESTHOLT, P. T. High Level Waste Technical Development Branch 1p 17749:356

8303300139 Reviews draft "Repository Site Definition in Basalt Pasco Basin, WA," per 810817 memo. Rept presents excellent overview of available literature.
PRESTHOLT, P. T. High Level Waste Technical Development Branch
00044 81/09/15 BELL, M. J. High Level Waste Licensing Management Branch 2pp 17749:361

8303300152 Discusses Performance Assessment Section analytical capabilities & proposed plan for assessment prior to receipt of site characterization rept.
BELL, M. J. High Level Waste Licensing Management Branch 00051
82/03/02 MILLER, H. J. High Level Waste Technical Development Branch 6pp 17751:045

8303300153 Ack receipt of DOE site characterization rept for Basalt Waste Isolation Project. State, tribal & local officials notified.
SURMEIER, J. NRC - No Detailed Affiliation Given 00077 82/11/12
REHM, T. NRC - No Detailed Affiliation Given 1p 17751:051

8303300162 Requests Hanford site characterization rept be forwarded to individuals listed in encl. P Prestholt will collect & distribute copies of rept during author absence on 821115.
WRIGHT, R. J. High Level Waste Technical Development Branch 00080
82/11/10 STILL, N. ; HALL, J. Division of Waste Management 3pp
17749:337

8303300170 Forwards comments on Basalt Waste Isolation Project 821005-06 design workshop in Richland, WA. Load cells on expansion-anchored bolts do not provide reliable results because of creep.
CORF, E. L. Interior, Dept of, Bureau of Mines 00079 82/11/09
CHASE, L. Division of Waste Management 3pp 17763:102

8303300201 Trip rept of 801029-31 visit to Richland, WA re annual review of conceptual design for high level waste repository as part of Basalt Waste Isolation Project Agenda encl.
HARTUNG, L. F. High Level Waste Technical Development Branch 00038
80/11/07 BELL, M. J. High Level Waste Technical Development Branch
5pp 17754:307

8303300210 Documents 821013 discussion. High level prelicensing site characterization repts will be available for public purchase within 6 w[illegible] of publication date.
SAVOLAINEN, A. W. [illegible]cy & Publications Management Branch 00073
82/10/14 BUNTING, J. D. Licensing Process & Integration Branch
2pp 17749:268

8303300250 Forwards slide presentation entitled "NRC High Level Waste Licensing Site Characterization Review Process," delivered at 821012 briefing.
MILLER, H. J. High Level Waste Technical Development Branch
82/10/13 YOUNG, F. Office of State Programs, Director BERSON, B. Office of the Executive Legal Director DAVIS, J. Office of Nuclear Regulatory Research, Director 3pp 17754:103

8303300257 Summarizes 821022 meeting w/WA Govenor's task force in Richland, WA re DOE high level waste mgt proposal & task force work plan.
LEWIS, N. D. Washington, State of 00275 82/11/08 BOYLE, B. J. ,
STEVENS, D. ; GIBBS, A. J. Washington, State of 4pp 17748:340

8303300264 Trip rept of hydrologic modeling task force 820927-28 meetings w/USGS, PNL, Richland Headquarters Ofc & LBL in Richland, WA re modeling issues for Pasco Basin.
KNAPP, M. R. High Level Waste Licensing Management Branch VERMA, T. R. High Level Waste Technical Development Branch 00071 82/10/08
BELL, M. J. High Level Waste Licensing Management Branch MILLER, H. J. High Level Waste Technical Development Branch 8pp 17748:347

8303300267 Notifies of 821115 meeting w/NRC to discuss high level nuclear waste mgt task force work plan.
LEWIS, N. D. Washington, State of 00274 82/11/08 BOYLE, B. J. ,
STEVENS, D. ; GIBBS, A. J. Washington, State of 1p 17748:355

8303300270 Forwards WA Governor Spellman 820816 Executive Order 82-17, establishing state high level nuclear waste mgt task force.
KERR, G. W. Office of State Programs, Director 00271 82/09/02
DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director
ENGELKEN, R. Region 5, Office of Director 5pp 17749:009

8303300271 Forwards site issue analyses (SIAs) for Basalt Waste Isolation Project. Draft SIAs requested for 821101 meeting in order to aid NRC in preparing site characterization analysis chapter on groundwater & organizing content of app.
VERMA, T. R. High Level Waste Technical Development Branch.
NRC-02-82-045. 00108. 82/10/25. ROWE, J. Golder Associates. 15pp.
17749:022.

8303300274 Submits info re organization & makeup of NRC staff responsible for review of DOE high level site characterization activities at Hanford site per 820724 telcon.
MILLER, H. NRC - No Detailed Affiliation Given. 00269. 82/08/10.
LEWIS, N. NRC - No Detailed Affiliation Given. 6pp. 17749:014.

8303300277 Trip rept of 820519-22 visit to States of NV & WA re state participation in high level waste licensing & site characterization rept reviews.
ULECK, R. B. High Level Waste Technical Development Branch. 00270.
82/08/13. MILLER, H. J. High Level Waste Technical Development Branch. 2pp. 17749:020.

8303300281 Trip rept of 820331 & 0401 meetings w/state officials in Region V & LBL in Walnut Creek, CA re high level radwaste.
MILLER, H. J. High Level Waste Technical Development Branch. 00268.
82/04/15. MARTIN, J. B. Division of Waste Management. 13pp.
17749:105.

8303300345 Forwards agenda for 821101-03 pre-SCR (site characterization rept) hydrogeology meetings w/contractors.
LOGSDON, M. J. High Level Waste Technical Development Branch. 00075.
82/10/26. MILLER, H. J. High Level Waste Technical Development Branch. 3pp. 17749:170.

8303300350 Forwards meeting notes for Basalt Waste Isolation Project 821005-07 workshop on facility design.
WRIGHT, R. J. High Level Waste Technical Development Branch. 00076.
82/10/28. MILLER, H. J. High Level Waste Technical Development Branch. 3pp. 17754:292.

8303300424 Forwards suggested assignments for Basalt Waste Isolation Project team.
WRIGHT, R. J. High Level Waste Technical Development Branch. 00047.
81/12/17. MILLER, H. J. High Level Waste Technical Development Branch. 2pp. 17753:326.

8303300429 Trip rept of 820928 & 29 meetings to review document release sys at Basalt Waste Isolation Project & to review borehole & shaft sealing technical position w/Golder Assoc.
RHODERICK, J. E. High Level Waste Technical Development Branch. 00074. 82/10/19. GREEVES, J. T. High Level Waste Technical Development Branch. 4pp. 17753:338.

8303300437 Forwards schedule of activities for review & analysis of Basalt Waste Isolation Project site characterization rept Constraints listed.
WRIGHT, R. J. High Level Waste Technical Development Branch. 00062.
82/08/19. BELL, M. J.; MILLER, H. J. High Level Waste Technical Development Branch. 10pp. 17753:312.

8303310038 Forwards advance FR notice re receipt of Basalt Waste Isolation Project site characterization rept for signature.
BUNTING, J. O. Licensing Process & Integration Branch. 00081.
82/11/12. MARTIN, J. B. Division of Waste Management. 1p.
17777:096.

--8303310043 Notice of receipt of site characterization rept from DOE re proposed high level waste repository at Hanford Reservation.
MARTIN, J. B. Division of Waste Management. 00081. 82/11/12. 5pp.
17777:097.

XPORTLIC EXPORT AND IMPORT LICENSES

8303020108 Amends 820210 ltr of assurance re export of low enriched U to West Germany, increasing quantity to 1,505,760 kg U-235, contained in 55,542.0 kg U.
MARCHAL, J. European Communities, Commission of. 83/02/16.
GRIFFIN, J. A. Energy, Dept. of. 1p. 17360:140.

8303020112 Amends 820218 ltr of assurance re export of low enriched U to France, increasing quantity to 1,543,325 kg U-235, contained in 46,961 kg U.
MARCHAL, J. European Communities, Commission of. 83/02/16.
GRIFFIN, J. A. Energy, Dept. of. 1p. 17360:133.

8303020238 License for Teledyne Wah Chang Albany to export 97,050 lb Zircaloy trex to West Germany.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 2625 (JFM). 83/02/17. 1p. 17355:333.

8303020248 License for Nissha Iwai American Corp to export 1.1 Ci Cf-252, contained in sealed neutron radiation source, to Japan.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. GBM-1466. 83/02/22. 2pp. 17355:331.

8303020290 Forwards Transnuclear, Inc application for amend to export license for minor nuclear export. Ltr of assurance required. W/o encl.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/02/18. GRIFFIN, J. A. Energy, Dept. of. 1p. 17355:312.

8303020300 Supports Transnuclear, Inc request for license for export of U to be made into fuel elements be transferred to Pechiney Ugine Kuhlmann Development, Inc.
COURCIER, P. Pechiney Ugine Kuhlmann Development, Inc. 83/02/10.
WRIGHT, B. Assistant Director for Export/Import & International Safeguards. 1p. 17355:290.

8303020312 Ltr of assurance re export of 732 kg U-235, contained in 21,199 kg of U, to Japan.
SHIRAKAWA, T. Japan, Govt of. 83/02/08. GRIFFIN, J. A. Energy, Dept. of. 1p. 17355:284.

8303020318 Forwards application for license to export zirconium Grade III seamless tubing to Canada.
BAUMGARD, R. W. Cabot Corp. 83/02/10. HENBY, E. Assistant Director for Export/Import & International Safeguards. 1p. 17357:355.

--8303020324 Application for license to export zirconium Grade II seamless tubing to Canada.
BAUMGARD, R. W. Cabot Corp. 82441-00. 83/02/10. 1p. 17357:356.

8303020332 Forwards application for license to export 32,737 kg U-235, contained in 35,088 kg U, to West Germany. Quantities correctly noted in encl NUKEM, GmbH 830209 ltr.
HANNETT, B. A. Transnuclear, Inc. NUK-431. 83/02/22. MOORE, N. Office of International Programs, Director. 5pp. 17357:349.

--8303020337 Application for license to export 32,737 kg U-235, contained in 35,488 kg U, to West Germany.
HANNETT, B. A. Transnuclear, Inc. NUR-431. 83/02/22. 1p. 17357:354.

8303020368 Amend 1 to export license, changing licensee name to Pechiney Ugine Kuhlmann Development, Inc & authorizing export of 4,582 kg U-235, contained in 4,971 kg U, to Canada.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/02/23. 2pp. 17419:153.

--8303020178 Confirms request by Transnuclear, Inc to have license transferred to Pechiney Ugine Kuhlmann Development, Inc for export of U to France.
COURCIER, P. Pechiney Ugine Kuhlmann Development, Inc. 83/02/10.
WRIGHT, B. Assistant Director for Export/Import & International Safeguards. 1p. 17419:155.

--8303030194 Application for amend to export license, changing licensee from Transnuclear, Inc to Pechiney Ugine Kuhlmann Development, Inc. P Ernst telex request from McMaster Univ encl.
HANNETT, B. A. Transnuclear, Inc. 83/02/17. MOORE, N. Office of International Programs, Director. 2pp. 17419:156.

8303020414 Requests Executive Branch position re GE application for license to export fuel pellet gamma densitometer to Spain.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/02/22. STOIBER, C. R. State, Dept. of, Bureau of Oceans & Intl Environ & Scient Affairs. 1p. 17357:307.

8303020440 Informs that Transnuclear, Inc requested withdrawal of export license application on 830216.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/02/18. STOIBER, C. R. State, Dept. of, Bureau of Oceans & Intl Environ & Scient Affairs. 1p. 17357:240.

8303020449 Informs that addl quantities requested for export licenses not of Australian origin.
HANNETT, B. A. Transnuclear, Inc. RBU-394. 83/02/17. MOORE, N. Office of International Programs, Director. 1p. 17357:232.

8303020457 Submits application to amend export license, increasing quantity to 870,145 kg U-235, contained in 26,368 kg U.
HANNETT, B. A. Transnuclear, Inc. TNP-398. 83/02/10. MOORE, N. Office of International Programs, Director. 2pp. 17357:213.

8303020467 Submits application to amend export license increasing quantity of U-235 to 1,543,325 kg, contained in 46,961 kg U.
HANNETT, B. A. Transnuclear, Inc. TNP-396. 83/02/10. MOORE, N. Office of International Programs, Director. 2pp. 17357:111.

8303020472 Submits application to amend export license, increasing quantities to 1,545 kg U-235 contained in 55,542 kg U & 0.324 kg U-235 contained in 10 kg U.
HANNETT, B.A. Transnuclear, Inc. RBU-395. 83/02/14. MOORE, N.
Office of International Programs, Director. 2pp. 17357:109.

8303020476 Submits application to amend export license, changing name of licensee to Pehiney Ugine Kuhlmann Development, Inc.
HANNETT, B.A. Transnuclear, Inc. 83/02/17. MOORE, N. Office of International Programs, Director. 2pp. 17357:107.

8303020479 Submits application to amend export license, adding intermediate consignee & other party to export.
HERSCH, M.M. Westinghouse Electric Corp. MMH-335. 83/02/14.
ZIMMERMAN, J.V. Assistant Director for Export/Import & International Safeguards. 1p. 17357:106.

8303030356 Forwards info requesting route approval, per 10CFR73, for shipment of irradiated reactor fuel in Apr 1983 from Pleasanton to Richmond, CA.
KIRKLAND, M.W. General Electric Co. 21942. 83/01/26. HILLMAN, C.R.
Office of Nuclear Material Safety & Safeguards, Director. 8pp. 17365:001.

8303030489 Application for license to export 5 kg deuterium oxide liquid over 2-yr period to Spain.
* Sigma Chemical Co. D-105. 83/02/21. 1p. 17419:202.

8303030495 Application for license to export 2 ug Pu-239 alpha calibr source Model DNS-16S, electroplated on metal disc, to Canada.
ESPINOSA, G.J. Eberline Instrument Corp. SO NO 890390. 83/02/17.
1p. 17419:201.

8303030659 Application for license to export two WL-23157 neutron detector assemblies to Spain.
POCHAL, W.F. Westinghouse Electric Corp. ZE 20604. 83/02/08. 1p.
17364:017.

8303030770 Application for license to export 20,000 lb nickel base alloy, containing 400 lb thorium oxide by weight, in form of mill products, to Canada.
* AMAX Specialty Metals Corp. (subs. of AMAX, Inc.). 83/02/04. 1p.
17363:231.

8303030772 License for Sandvik Special Metals Corp to export 1,120 pieces of Zircaloy-4 guide thimble tubes to Japan.
ZIMMERMAN, J.V. Assistant Director for Export/Import & International Safeguards. XSI-30982/30983. 83/03/01. 1p. 17363:229.

8303030773 Application for license to export two compensated ionization & chambers Model WL-23944 to France.
POCHAL, W.F. Westinghouse Electric Corp. ZE 40116. 83/02/07. 1p.
17363:220.

8303030787 License for Westinghouse to export two compensated ionization chambers Model WL-8074 to Japan.
ZIMMERMAN, J.V. Assistant Director for Export/Import & International Safeguards. 83/02/22. 1p. 17363:230.

8303030793 License for GE to export 1,000 kg thorium, as natural & oxide, both in slurry mix & fire-coated on electrodes, to Canada.
ZIMMERMAN, J.V. Assistant Director for Export/Import & International Safeguards. SMB-191. 83/02/22. 1p. 17364:020.

8303040001 Amends 820211 ltr of assurance re export of low enriched U to France, changing quantity to 870,145 kg U-235 contained in 26,368 kg U.
MARCHAL, J. European Communities, Commission of. 83/02/16.
GRIFFIN, J.A. Energy, Dept. of. 1p. 17426:067.

8303040014 License for CERAC, Inc to export 7.54 kg thorium, contained in 10 kg thorium fluoride in granular form, to Switzerland.
ZIMMERMAN, J.V. Assistant Director for Export/Import & International Safeguards. TLX 269452. 83/02/18. 2pp. 17426:061.

8303040017 Advises of withdrawal of application for export license.
HANNETT, B.A. Transnuclear, Inc. NUK-379. 83/02/16. MOORE, N.
Assistant Director for Export/Import & International Safeguards. 1p.
17425:138.

8303040022 Executive Branch position re Edlow Intl application to export one 2 mg Cf-252 source. License amend should be granted.
DEVINE, J.B. State, Dept. of, Bureau of Oceans & Intl Environ & Scient. Affairs. 83/02/10. SHEA, J.R. Office of International Programs, Director. 1p. 17425:137.

8303040029 Submits application for license to import 30 mg Pu-238 from France. Waiver of 15-day waiting period requested.
NISSON, R.S. National Aeronautics & Space Admin. 83/02/16.
MOORE, R.N. Office of International Programs, Director. 1p.
17425:136.

8303040039 Submits Ofc of Intl Programs findings re NASA 830216 application to import 30 mg Pu-238 from France. Import acceptable. License issued w/o 15-day waiting period.
MOORE, R.N. Office of International Programs, Director. 83/02/18.
Office of International Programs, Director. 1p. 17425:135.

8303040049 Application for license to export 10 kg deuterium oxide over 2-yr period to Spain.
* Sigma Chemical Co. D-101. 83/02/07. 1p. 17425:134.

8303040053 Forwards Transnuclear, Inc application for amend to export license for minor nuclear export. Ltr of assurance required. W/o encl.
ZIMMERMAN, J.V. Assistant Director for Export/Import & International Safeguards. 83/02/18. GRIFFIN, J.A. Energy, Dept. of. 1p.
17424:361.

8303040055 Forwards applications for license to export automatic pellet insp equipment to Belgium & West Germany. W/o XCOM-0723 application.
WILSON, B.D. General Electric Co. BDW-013-83. 83/02/07.
ZIMMERMAN, J.V. Assistant Director for Export/Import & International Safeguards. 1p. 17425:093.

--8303040060 Corrects fourth paragraph of 830207 ltr providing info supplementing export license applications re multiple patents. Statement should read: "multiple patent applications have been filed."
WILSON, B.D. General Electric Co. 83/02/14. ZIMMERMAN, J.V.
Assistant Director for Export/Import & International Safeguards. 1p. 17425:094.

--8303040068 Application for license to export automatic pellet insp equipment to Belgium.
WILSON, B.D. General Electric Co. BDW-83-007. 83/02/07. 1p.
17425:095.

8303040061 Forwards Transnuclear, Inc application for export license for minor nuclear export. Ltr of assurance required. W/o encl.
ZIMMERMAN, J.V. Assistant Director for Export/Import & International Safeguards. 83/02/18. GRIFFIN, J.A. Energy, Dept. of. 1p.
17424:360.

8303040064 Application for license to export 5 kg deuterium oxide over 2-yr period to China.
* Sigma Chemical Co. D-104. 83/02/15. 1p. 17424:359.

8303040070 Forwards GA Technologies 830207 ltr clarifying info re amend to export license submitted in 821110 ltr. W/o encl.
ZIMMERMAN, J.V. Assistant Director for Export/Import & International Safeguards. 83/02/16. STOIBER, C.R. State, Dept. of, Bureau of Oceans & Intl Environ & Scient. Affairs. 1p. 17424:358.

8303040075 Application for license to export 450 pieces of zirconium tubing to West Germany.
WILSON, B. General Electric Co. BDW-017-83. 83/02/15. 1p.
17424:357.

8303040081 Application for license to export 0.1007 mg Np-237, electrudeposited onto nickel disc, to Yugoslavia.
HEIMAN, D. Reactor Experiments, Inc. AMEX 7114. 83/02/14. 1p.
17424:356.

8303040085 Requests Executive Branch position re GE 830207 application for licenses to export two automatic pellet insp sys to Belgium & West Germany.
ZIMMERMAN, J.V. Assistant Director for Export/Import & International Safeguards. 83/02/17. STOIBER, C.R. State, Dept. of, Bureau of Oceans & Intl Environ & Scient. Affairs. 1p. 17424:355.

8303040091 Application for license to export fuel assembly component parts to Sweden.
HERSCH, M.M. Westinghouse Electric Corp. MMH-334. 83/02/09. 1p.
17424:354.

8303040093 License for NASA to import 30 mg Pu-238 mixed w/C-13 from France.
ZIMMERMAN, J.V. Assistant Director for Export/Import & International Safeguards. 83/02/18. 1p. 17424:353.

8303040098 Application for license to export fuel tube for nuclear power reactor to Japan.
* C. Itoh & Co. (America), Inc. ME-15(04-3). 83/02/15. 1p.
17424:350.

8303040108 Application for license to export Zircaloy 2 & 4 tube shells to Japan.
*BUONOCORE, J. A. Mitsui & Co. (U.S.A.), Inc. (Subs. of Mitsui & Co., Ltd.). 136284. 83/02/04. 2pp. 17424:343.

8303040121 Submits application for license to import 500,000 kg U, enriched to 5% U-235. Country & facility of origin cannot be given.
HANNETT, B. A. Transnuclear, Inc. MIS-432. 83/02/22. MOORE, N. Office of International Programs, Director. 1p. 17425:080.

8303040127 Application for license to export four compensated ionization chambers, Model WL-23196, to France.
POCHAL, W. F. Westinghouse Electric Corp. ZE 40162. 83/02/07. 1p. 17425:079.

8303040129 Application for license to export 10 kg thorium fluoride granules to Switzerland.
COLTON, E. Cerac, Inc. 83/02/16. 1p. 17425:074.

8303040133 Application for license to export fuel pellet gamma densitometer, including Cs-137 source, to Spain.
WILSON, B. General Electric Co. BDW-83-114. 83/02/10. 1p. 17425:073.

8303040140 Application for license to export 5 kg deuterium liquid, over 2-yr period, to Spain.
* Sigma Chemical Co. D-102. 83/02/10. 7pp. 17425:045.

8303040168 Application for license to export 5 kg deuterium oxide, in liquid form, over 2-yr period to India.
* Sigma Chemical Co. D-103. 83/02/10. 7pp. 17427:029.

8303100529 License for GE to export 450 pieces zirconium tubing to Switzerland.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. BDW-017-83. 83/03/03. 1p. 17521:279.

8303100531 License for Brunswick Corp to export eight each P/N N240-180 & nine each P/N N239-180 check valves, 52 each P/N N243-521-1 valves & 40 each P/N N243-526-2 excess flow valves to Canada.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. S.O. N86996. 83/03/03. 1p. 17521:278.

8303100533 License for NBS to export 916.5 mCi Np-237, as oxide or fluoride, bonded to metal backings, to Belgium.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/03/02. 1p. 17521:277.

8303100535 License for AMAX Specialty Metals Corp to export 400 lb thorium oxide, contained in 20,000 lb nickel alloy in form of mill products, to Canada.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/03/03. 1p. 17521:276.

8303100537 License for Sigma Chemical Co to export 5 kg deuterium oxide to Spain.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. D-102. 83/03/03. 1p. 17521:275.

8303100540 License for Westinghouse to export four WL-23196 compensated ionization chambers to France.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. ZE-40162. 83/03/03. 1p. 17521:274.

8303100543 License for Sigma Chemical Co to export 10 kg deuterium oxide to Spain.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. D-101. 83/03/03. 1p. 17521:269.

8303100544 Informs that NRC issued license to Cabot Corp to export zirconium tubing to Canada for R&D purposes, in response to 830210 application. License issued w/o normal 15-day waiting period.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/02/28. Assistant Director for Export/Import & International Safeguards. 1p. 17521:268.

8303140547 Advises that export license issued w/o normal 15-day waiting period since matl ready for immediate shipment.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/03/03. Assistant Director for Export/Import & International Safeguards. 1p. 17547:362.

8303140549 Advises that export license issued w/o normal 15-day waiting period since matl urgently needed to meet scheduled fuel load.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/03/03. Assistant Director for Export/Import & International Safeguards. 1p. 17548:326.

8303140552 Forwards application for license to export nuclear reactor parts to Indonesia.
MOWRY, W. R. GA Technologies, Inc./General Atomic Co. IEL-4050. 83/02/25. ZIMMERMAN, J. Assistant Director for Export/Import & International Safeguards. 1p. 17548:339.

--8303140556 Application for license to export nuclear reactor parts to Indonesia.
MOWRY, W. R. GA Technologies, Inc./General Atomic Co. IEL-4050. 83/02/25. 1p. 17548:340.

8303140561 Informs that export license issued w/o normal 15-day waiting period because of urgency to meet test schedule.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/03/02. Assistant Director for Export/Import & International Safeguards. 1p. 17546:357.

8303140660 Application for license to export 8,601 kg U hexafluoride, enriched to 3.45%, to Japan.
FOSTER, C. M. Edlow International Co. HSA-JA-13(KLK-1. 83/02/23. 2pp. 17569:170.

8303140662 Application for license to export one moderator kit for Detector Assembly WL-23776 to Belgium.
POCHAL, W. F. Westinghouse Electric Corp. ZE 20602A. 83/02/21. 1p. 17569:169.

8303140665 License for Westinghouse to export two neutron detector assemblies, Model WL-23157 to Spain.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. ZE-20604. 83/03/02. 1p. 17548:001.

8303140666 License for Cabot Corp to export 500 ft zirconium Grade II seamless tubing to Canada.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 82441-CO. 83/02/28. 1p. 17572:357.

8303140667 License for Westinghouse to export two compensated ionization chambers, Model WL-23944, to France.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. ZE-40116. 83/03/02. 1p. 17582:256.

8303140668 Amend 2 to Westinghouse export license, adding CERCA, France as intermediate consignee & Nuclear Components Co as other party to export to Italy.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/03/04. 1p. 17548:362.

8303140670 Amend 5 to Hoke, Inc export license, increasing value of equipment exported to Canada.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/03/03. 1p. 17548:361.

8303140672 Amend 4 to Hoke, Inc export license, extending expiration date from 831231 to 851231.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/03/03. 1p. 17548:360.

8303140674 Amend 1 to Sandvik Special Metals Corp export license, increasing quantity of Zircaloy-4 part pilgerad cladding to 150,130 lb & extending expiration date from 830901 to 840228.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/03/03. 1p. 17548:359.

8303140699 Requests Executive Branch position re GE 830117,0210 & 22 & Westinghouse 830106 applications for licenses to export nuclear matl to Spain.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/03/02. STOIBER, C. R. State, Dept. of, Bureau of Oceans & Intl Environ & Scient. Affairs. 2pp. 17569:174.

8303150676 Submits application for license to export deposits of Th-232, U-238, U-235 & Np-237 to Belgium.
PEVEY, L. E. Commerce, Dept. of, National Bureau of Standards. 83/02/25. Assistant Director for Export/Import & International Safeguards. 1p. 17586:253.

8303150681 Submits application to amend license, increasing number of fuel elements to 90, containing addl 2,850 kg U, enriched to 35%, for export to Sweden.
KIEL, G. R. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 83/02/23. ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 1p. 17586:249.

8303150685 Requests withdrawal of 830106 application to amend export license.
WILSON, B. D. General Electric Co. BDW-83-020 83/03/03.
WRIGHT, B. L. Assistant Director for Export/Import & International Safeguards. 1p. 17586:248.

8303150689 Submits application to amend export licenses, increasing value of License XCOM-0219 to $150,000 & extending expiration date of License XCOM-0222 to 841231.
BRUSH, P. N. Hoke, Inc. 83/02/25. HEMBY, E. NRC - No Detailed Affiliation Given. 1p. 17586:247.

8303150695 Submits application to amend export license, increasing quantity to 150,130 lb exported matl & changing expiration date to 840228.
MENTER, L. Sandvik Special Metals Corp. 83/02/23. HEMBY, E. NRC - No Detailed Affiliation Given. 1p. 17611:232.

8303150698 Submits application to amend export license, extending expiration date to 900501.
HARMON, D. W. Edlow International Co. 83/03/02. HEMBY, E. Assistant Director for Export/Import & International Safeguards. 1p. 17586:242.

8303150701 Submits application to amend export license, changing ultimate consignee & ultimate end use.
WILSON, B. D. General Electric Co. BDW-018-83. 83/03/02. HEMBY, E. O. NRC - No Detailed Affiliation Given. 1p. 17583:362.

8303160029 Submits application for license to export 112 valves & 100 manuals to Canada.
TRAFFORD, S. Brunswick Co. 83/03/01. HEMBY, E. NRC - No Detailed Affiliation Given. 3pp. 17615:047.

8303160045 Submits application to amend export license, approving re-export of 0.5 microgram Cf-252, to Iraq from United Kingdom.
HARMON, D. W. Edlow International Co. 83/03/02. HEMBY, E. Assistant Director for Export/Import & International Safeguards. 1p. 17615:010.

--8303160050 Telecopy request to amend license to include 0.5 microgram Cf-252, for re-export to Iraq from United Kingdom.
JANICKI, M. Edlow International Co. 83/03/02. SHAW, A. NRC - No Detailed Affiliation Given. 1p. 1.615:011.

8303160640 Executive Branch position re Transnuclear, Inc application to export 1,200,000 kg natural U to EURATOM countries. Issuance of license recommended. End use statement encl.
DEVINE, J. B. State, Dept. of, Bureau of Oceans & Intl Environ & Scient. Affairs. 83/02/25. SHEA, J. R. Office of International Programs, Director. 3pp. 17600:328.

8303170022 Ltr of assurance re export of 1,135 kg U-235 contained in 33,750 kg U, to Sweden.
MARCHAL, J. European Communities, Commission of. 83/03/02.
GRIFFIN, J. A. Energy, Dept. of. 1p. 17624:319.

8303170028 Ltr of assurance re export of licensed nuclear matl to Norway.
AASHEIM, H. Norway. 83/03/02. GRIFFIN, J. A. Energy, Dept. of. 1p. 17615:362.

8303170154 Forwards application for license to export 100 kg 64% pure heavy water to Canada.
LUCENA, S. P. Interactive Radiation, Inc. 83/03/02. Assistant Director for Export/Import & International Safeguards. 1p. 17637:001.

--8303170157 Application for license to export 100 kg 64% pure heavy water to Canada.
LUCENA, S. P. Interactive Radiation, Inc. SL-4-81. 83/03/01. 1p. 17637:002.

8303170337 Forwards applications for export licenses for minor nuclear export. Ltrs of assurance required. W/o encls.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/03/08. GRIFFIN, J. A. Energy, Dept. of. 1p. 17615:214.

8303170667 Forwards application for export license for minor nuclear export. Ltr of assurance required. W/o encl.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/03/07. GRIFFIN, J. A. Energy, Dept. of. 1p. 17615:145.

8303170672 Forwards application for export license for minor nuclear export. Ltr of assurance required. W/o encl.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/03/07. GRIFFIN, J. A. Energy, Dept. of. 1p. 17615:117.

8303170675 Ltr of assurance re export of 16.2 kg U, in TRIGA fuel elements, to Indonesia.
SETYOKO, R. Indonesia. 83/02/17. GRIFFIN, J. A. Energy, Dept. of. 1p. 17623:306.

8303180016 Requests rev to application for license to export U-233 to Canada.
CEJA, S. Energy, Dept. of. 83/02/16. MOORE, N. Office of International Programs, Director. 1p. 17625:276.

8303180020 Requests Executive Branch position re DOE application for amend to license to decrease quantity of U-233 to be exported.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/03/08. STOIBER, C. R. State, Dept. of, Bureau of Oceans & Intl Environ & Scient. Affairs. 1p. 17625:275.

8303180045 Forwards application for export license for minor nuclear export. Ltr of assurance required. W/o encl.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/03/08. GRIFFIN, J. A. Energy, Dept. of. 1p. 17625:262.

8303180047 Forwards application for export license for minor nuclear export. Ltr of assurance required. W/o encl.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/03/08. GRIFFIN, J. A. Energy, Dept. of. 1p. 17625:259.

8303180082 Forwards application for license to export 150 kg U, containing 5 kg U-235, to Sweden.
HERSCH, M. M. Westinghouse Electric Corp. MMH-341. 83/03/02.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 1p. 17625:208.

--8303180087 Application for license to export 150 kg U, containing 5 kg U-235, to Sweden.
HERSCH, M. M. Westinghouse Electric Corp. MMH-341. 83/02/20. 1p. 17625:209.

8303180094 License for Reactor Experiments, Inc to export 0.1014 mg Np-237, electrodeposited onto nickel disc, to Yugoslavia.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. AMEX 7114. 83/03/10. 1p. 17625:204.

8303180105 Application for license to export 0.41 g U-238, enriched to 1.5% U-235, to Japan.
HELMAN, D. Reactor Experiments, Inc. 829-2. 83/02/28. 2pp. 17625:187.

8303180109 Requests Executive Branch position re GE application for license to export 1,000 kg natural U to Spain.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/03/09. STOIBER, C. R. State, Dept. of, Bureau of Oceans & Intl Environ & Scient. Affairs. 2pp. 17625:185.

8303180113 License for Sigma Chemical Co to export 5 kg deuterium oxide to China.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. D-104. 83/03/10. 1p. 17625:179.

8303180118 License for C Itoh & Co (America), Inc to export 33 pieces Zircaloy tubing to Japan.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. WE-159(04-3). 83/03/07. 1p. 17625:170.

8303180121 License for Sigma Chemical Co to export 5 kg deuterium oxide to Spain.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. D-105. 83/03/10. 1p. 17625:169.

8303180155 Forwards application for license to export 23,714 kg U dioxide powder to Japan.
NAKAI, T. Marubeni America Corp. (subs. of Marubeni Corp.).
MAS-7987. 83/03/01. WRIGHT, B. L. Assistant Director for Export/Import & International Safeguards. 1p. 17626:002.

--8303180161 Application for license to export 23,714 kg U dioxide powder, enriched to 3.95% U, to Japan.
NAKAI, T. Marubeni America Corp. (subs. of Marubeni Corp.).
ZH0225-1W. 83/02/28. 1p. 17626:003.

8303180178 License for Westinghouse to export nuclear fuel assembly component parts to Sweden.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. MMH-334. 83/03/10. 1p. 17625:347.

8303180181 License for Mitsui & Co (USA), Inc to export 167,200 lb Zircaloy-2 & Zircaloy-4 tube shells to Japan.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 136284. 83/03/10. 1p. 17625:346.

8303180189 Application for license to export 14,410 kg U as U hexafluoride, enriched 2.65% to Japan.
FOSTER, C. M. Edlow International Co. HSA-JA-2(XLK-16. 83/02/28. 1p. 17625:343.

8303180193 Application for license to export 5 kg liquid compounds containing deuterium to South Korea.
* Sigma Chemical Co. D-106. 83/03/01. 1p. 17625:342.

8303180567 Requests Executive Branch position re Amersham Intl Limited application for amend to license to export 0.05 microgram Cf-252 to Iraq.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. 83/03/09. STOIBER, C. R. State, Dept. of, Bureau of Oceans & Intl Environ & Scient Affairs. 1p. 17640:039.

8303180591 Application for license to export 403 kg U-235, as enriched U hexafluoride, to Japan.
OKADA, S. Mitsui & Co. (U.S.A.), Inc. (Subs. of Mitsui & Co., Ltd.). MBK-F5-R6 (A). 83/02/28. 1p. 17640:125.

8303180598 Forwards application for license to export 593.2 kg U-235, contained in 19,753 kg U & 0.243 kg U-235, contained in 6 kg U, to Sweden.
HANNETT, B. A. Transnuclear, Inc. RBU-433. 83/03/07. MOORE, R. N. Assistant Director for Export/Import & International Safeguards. 1p. 17640:164.

--8303180603 Application for license to export 593.2 kg U-235, contained in 19,753 kg U & 0.243 kg U-235, contained in 6 kg U, to Sweden. End use statement encl.
HANNETT, B. Transnuclear, Inc. RBU-433. 83/03/07. 2pp. 17640:160.

8303180607 Application for license to export 19.6 g U-238, enriched to 93% U-235 as metal disc, to Japan.
HEIMAN, D. Reactor Experiments, Inc. 839-1. 83/02/28. 2pp. 17640:168.

8303230002 Application for license to export 15 fuel tubes to Japan.
* C. Itoh & Co (America), Inc. WE-15(03,6,7,8). 83/02/11. 1p. 17689:153.

8303230003 Application for license to export 0.125 kg U oxide pellets to Belgium.
WILSON, B. D. General Electric Co. BDW-83-24. 83/03/11. 1p. 17689:152.

8303230004 Application for license to export two Reuter-Stokes Model RS-C1-1210-135 ionization chamber units to France.
SKARUPA, J. D. Reuter-Stokes, Inc. A-9623. 83/03/04. 1p. 17689:151.

8303230006 Application for license to export miscellaneous specially designed parts & components to Switzerland.
PEARSON, A. Borg-Warner Corp. 793-W-5823. 83/03/07. 1p. 17689:150.

8303230010 Forwards application for license to export 341 kg U-235, contained in 11,439 kg U hexafluoride, to Japan.
HATTORI, H. Mitsui & Co. (U.S.A.), Inc. (Subs. of Mitsui & Co., Ltd.). 83/03/09. Assistant Director for Export/Import & International Safeguards. 1p. 17689:148.

--8303230014 Application for license to export 341 kg U-235, contained in 11,439 kg U hexafluoride, to Japan.
OKADA, S. Mitsui & Co. (U.S.A.), Inc. (Subs. of Mitsui & Co., Ltd.). MBK-F5-R6 (B). 83/03/09. 1p. 17689:149.

8303230069 Revises 830228 export license application to change Item 22, country of origin, from Canada to South Africa & Australia.
UHOV, P. Marubeni America Corp. (subs. of Marubeni Corp.). MAS-7999. 83/03/10. WRIGHT, B. L. Assistant Director for Export/Import & International Safeguards. 1p. 17688:079.

8303230073 License for Eberline Instrument Corp to export 2 microgram Pu-239, contained in alpha calibr source Model DNS-165, to Canada.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. SO NO 890390. 83/03/11. 2pp. 17688:060.

8303230076 License for Westinghouse to export moderator kit, Model WL-23776, to Belgium.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards. ZE 20602A. 83/03/15. 1p. 17687:260.

8303230077 Forwards application for license to export slightly enriched U hexafluoride for fuel assembly fabrication to Japan.
SHIMA, S. Mitsubishi International Corp. (subs. of Mitsubishi Corp.). HSA-5482-09. 83/03/04. Assistant Director for Export/Import & International Safeguards. 3pp. 17687:255.

--8303230082 Application for license to export 365 kg U-235, contained in 10,554 kg U hexafluoride, to Japan. End use statement encl.
SHIMA, S. Mitsubishi International Corp. (subs. of Mitsubishi Corp.). HSA-5482-09. 83/03/04. 2pp. 17687:258.

8303230081 License for Mitsubishi Intl Corp to export 732 kg U-235, contained in 21,199 kg U, to Japan.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. HSA-5482-07. 83/03/16. 2pp. 17687:253.

8303230088 Amend 4 to GA Technologies, Inc license, increasing U to 36,745 kg, enriched to 19.9% w/o U-235, as TRIGA fuel elements, for export to Indonesia.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. IEL-4022. 83/03/11. 1p. 17688:105.

8303230093 Amend 2 to license for Westinghouse, increasing amount of import to 25,225 kg U, containing 980 kg U-235, from South Korea & extending license until 901231.
PETERSON, M. R. Office of International Programs, Director. 83/03/10. 1p. 17687:176.

8303230100 License for GE to import 0.250 kg U-235, contained in 17 kg U & 110 g Pu as metal clad fuel segments, from Norway.
PETERSON, M. R. Office of International Programs, Director. 83/03/10. 1p. 17687:160.

8303230141 Application for license to export spare parts for AV1681959 fuel shutoff valve to Canada.
* ITT General Controls (subs. of ITT). FB-83-135. 83/02/24. 1p. 17689:261.

8303230145 Application for license to export reactor fuel handling equipment, reactor control rods & reactor control rod drive mechanisms to China.
MOWRY, W. R. GA Technologies, Inc./General Atomic Co. IEL-4056. 83/03/11. 1p. 17687:119.

8303230151 Forwards application for license to export 6,560 kg U-235, contained in 160,000 kg enriched U, to South Korea.
SCHERER, A. E. Combustion Engineering, Inc. LD-83-021. 83/03/08. Assistant Director for Export/Import & International Safeguards. 1p. 17687:117.

--8303230157 Application for license to export 6,560 kg U-235, contained in 160,000 kg enriched U, to South Korea.
* Combustion Engineering, Inc. LD-83-021. 83/03/08. 1p. 17687:118.

8303230214 Submits application to amend export license, to re-export 200-mCi Cf-252 source to Israel.
FOSTER, C. M. Edlow International Co. 83/03/10. HEMBY, E. Assistant Director for Export/Import & International Safeguards. 1p. 17686:218.

8303230347 Application for license to export one Reuter-Stokes Model RS-C6-0201-276 & one Reuter Stokes Model RS-C4-0201-201 in-core probes, to Italy.
SKARUPA, J. D. Reuter-Stokes, Inc. A-9737. 83/03/08. 1p. 17675:274.

8303230351 Submits Ofc of Intl Programs findings re GE application to import 17 kg U, containing 250 g U-235 & 110 g Pu in 22 irradiated fuel segments, from Norway.
MOORE, R. N. Office of International Programs, Director. 83/03/10. Office of International Programs, Director. 1p. 17675:273.

8303230355 Submits Ofc of Intl Programs findings re Westinghouse application to increase import amount to 25,225 kg U & extend license until 901231.
MOORE, R. N. Office of International Programs, Director. 83/03/10. Office of International Programs, Director. 1p. 17675:272.

8303230359 Informs that License XSNM-1999 may be issued. No matl changed circumstances since issuance of License XSNM-1996.
MOORE, R. N. Assistant Director for Export/Import & International Safeguards. 83/03/16. Assistant Director for Export/Import & International Safeguards. 1p. 17675:271.

8303230363 Responds to 830218 ltr re possible violation in Shipment AM-36 to Amersham Intl, Inc. No NRC action will be taken. Licensee should consider amending license to increase limit on individual shipments.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/03/11 SHAW, A. Edlow International Co 1p 17674:042

--8303230366 Informs of possible violation in Shipment AM-36. Two packages, each containing 20,000 Ci, shipped on one air waybill, exceeding 30,000 Ci per shipment limit.
SHAW, A. Edlow International Co. 83/02/18 HEMBY, E. Assistant Director for Export/Import & International Safeguards 1p 17674:043

8303230427 Forwards application for export license for minor nuclear export. Ltr of assurance required. W/o encl.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/03/11 GRIFFEN, J. A. Energy, Dept. of 1p 17674:044

8303230442 Application for license to export 1 Model WL-23773 proportional counter to Belgium.
POCHAL, W. F. Westinghouse Electric Corp. ZE-20603A 83/03/04 1p 17674:104

8303230462 Application for license to export 55 fuel tubes to Japan.
* C. Itoh & Co. (America), Inc. WE-15(04-4.5) 83/03/08 1p 17677:260

8303230516 Forwards application for export license for minor nuclear export. Ltr of assurance required. W/o encl.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/03/11 GRIFFEN, J. A. Energy, Dept. of 1p 17677:231

8303240322 Application for license to export 2 g U-238, enriched to 93.12% U-235, to Japan.
HEIMAN, D. Reactor Experiments, Inc. JAPAN-1041 83/03/14 1p 17690:354

8303240335 Application for license to export three repaired ion chambers to Canada.
POCHAL, W. F. Westinghouse Electric Corp. V2A00065 83/03/17 1p 17690:355

8303240331 Executive Branch position re GA Co application to export 1,000 g U-235 in 5,030 g U, to Yugoslavia. License should be granted.
DEVINE, J. B. State, Dept. of, Bureau of Oceans & Intl Environ & Scient Affairs 83/03/15 SHEA, J. R. Office of International Programs, Director 11pp 17694:054

8303240337 License for GA Co to export miscellaneous specially designed or prepared parts & components for use in nuclear reactor, to Indonesia.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards IEL-4050 83/03/10 1p 17690:356

8303240344 License for Marubeni America Corp to export 249 kg U-235, contained in 9,002 kg U, to Japan.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards ZH0290-2W 83/03/18 2pp 17690:357

8303240348 License for Marubeni America Corp to export 1,542 kg U-235, contained in 51,160 kg U, to Japan.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards ZH0290-1W 83/03/18 2pp 17690:360

8303240352 Amend 6 to Edlow Intl Co export license, authorizing retransfer of 2-mg source of Cf-252 from United Kingdom to South Africa & changing ultimate consignee to Amersham Intl Ltd.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards TRC-4 83/03/18 1p 17690:359

8303280002 Amend 7 to Saunders-Roe Developments, Inc export license, revising condition re number of monthly shipments.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards 83/03/18 1p 17713:361

8303280104 Ltr of assurance re Transnuclear, Inc application to export 593,442 kg U-235, contained in 19,759 kg U, to Sweden.
MARCHAL, J. European Communities, Commission of RBU-433 83/03/16 GRIFFIN, J. A. Energy, Dept. of 1p 17713:356

8303280106 Ltr of assurance re export of 1,542 kg U-235, contained in 51,160 kg U, to Japan.
SHIRAKAWA, T. Japan, Govt of, 83/03/09 GRIFFIN, J. A. Energy, Dept. of 1p 17713:355

8303280109 Ltr of assurance re export of 249 kg U-235, contained in 9,000 kg U, to Japan.
SHIRAKAWA, T. Japan, Govt of, 83/03/09 GRIFFIN, J. A. Energy, Dept. of 1p 17713:354

8303280113 Application for license to export 70 kg U, enriched to 7% U-235, to Taiwan.
GARRETT, J. A. Separative Work Unit Corp. 83/03/17 3pp 17713:338

8303280116 Advises of issuance of license to export three ion chambers to Canada w/o normal 15-day waiting period.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/03/18 Assistant Director for Export/Import & International Safeguards 1p 17713:337

8303280334 Application for license to export 11.5 mg Pu-239 enriched to 98.8% to Japan.
HEIMAN, D. Reactor Experiments, Inc. JAPAN-1046 83/03/14 1p 17713:120

8303290044 Amend 4 to GA Co export license changing name of licensee to GA Technologies, Inc & increasing quantity of matl for export to 449 g U-235.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards IEL-4041 83/03/23 1p 17729:291

8303290048 Application for license to export Reuter-Stokes Model RS-C[illegible]-0201-231 in-core detectors to Spain.
SKARUPA, J. D. Reuter-Stokes, Inc. A-9792 83/03/16 2pp 17729:289

8303290051 Forwards GA application to amend export license increasing quantity of matl & adding another ultimate consignee. Ltr of assurance required. W/o encl.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/03/22 GRIFFIN, J. A. Energy, Dept. of, Clinch River Breeder Reactor Plant 1p 17729:214

8303290071 Application for license to export 5 kg deuterium oxide over 2-yr period to Argentina.
* Sigma Chemical Co. D-107 83/03/16 1pp 17729:271

8303290074 License for Sigma Chemical Co to export 5 kg deuterium oxide to South Korea.
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards D-106 83/03/11 1p 17729:270

8303290079 Advises of cancellation of 830318 Westinghouse application to export ion chambers to Argentina.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/03/23 STOIBER, C. R. State, Dept. of, Bureau of Oceans & Intl Environ & Scient Affairs 1p 17729:258

--8303290085 Requests cancellation of export license application. Matl no longer required. Argentine company purchased matls from English Corp. License application for export of one ion chamber should remain active.
TERWILLIGER, L. Westinghouse Electric Corp. 83/03/18 HEMBY, E. NRC - No Detailed Affiliation Given 1p 17729:259

8303290090 Requests Executive Branch position re Edlow Intl Co application for amend to export license increasing quantity of tritium gas from 30,000 to 40,000 Ci.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/03/23 STOIBER, C. R. State, Dept. of, Bureau of Oceans & Intl Environ & Scient Affairs 1p 17729:242

8303290094 Application for amend to license increasing quantity of sample matl for export to Spain.
WILSON, B. D. General Electric Co. BDW-026-83 83/03/15 WRIGHT, B. L. NRC - No Detailed Affiliation Given 2pp 17729:234

8303290099 Application for license to export depleted U hexafluoride to Korea.
FOSTER, C. M. Edlow International Co. KAERI-05 83/03/16 1p 17729:224

8303290104 License for GA Technologies to export 1 kg U-235, contained in 5,030 kg U, to Yugoslavia.
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards IEL-3094 83/03/21 2pp 17729:206

8303290110 Submits application for Amend 3 to export license, adding Italy as second ultimate consignee & increasing amount of authorized SNM.
MOWRY, W. R. GA Technologies, Inc./General Atomic Co. 83/03/16 ZIMMERMAN, J. Assistant Director for Export/Import & International Safeguards 2pp 17729:179

8303290113 Forwards application for license to export depleted U hexafluoride to South Korea. Ltr of assurance required W/o encl
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/03/22 GRIFFIN, J. A. Energy, Dept. of 1p 17729.008

8303290118 Submits application for Amend 3 to export license, increasing quantity from 30,000 to 40,000 Ci
FOSTER, C. M. Edlow International Co. 83/03/18 HEMBY, E. Assistant Director for Export/Import & International Safeguards 1p 17729.007

8303290119 Requests Executive Branch position re GE application for rev to export license increasing total amount of matl proposed from 333 g to 85 kg U
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/03/22 STOIBER, C. R. State, Dept. of, Bureau of Oceans & Intl Environ & Scient. Affairs 1p 17729.006

8303290123 License for Interactive Radiation, Inc to export 100 kg deuterium oxide to Canada
PETERSON, M. R. Assistant Director for Export/Import & International Safeguards SL-4-81. 83/03/11 1p 17727.356

8303290125 Requests Executive Branch position re Separative Work Units Corp, Inc application for license to export SNM to Taiwan
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/03/18 STOIBER, C. R. State, Dept. of 1p 17727.355

8303290133 Informs that License XSNM-2004 may be issued No matl changed circumstances since issuance of License XSNM-1996
MOORE, R. N. Assistant Director for Export/Import & International Safeguards 83/03/17 Assistant Director for Export/Import & International Safeguards 1p 17730.285

8303290140 Executive Branch position re GA Technologies application to export 1,000 g total U to West Germany License should be granted Ltr of assurance encl
DEVINE, J. B. State, Dept. of 83/03/18 SHEA, J. R. Office of International Programs, Director 4pp 17730.276

8303290145 Informs that License XSNM-2005 may be issued No matl changed circumstances since issuance of License XSNM-1996
MOORE, R. N. Assistant Director for Export/Import & International Safeguards 83/03/17 Assistant Director for Export/Import & International Safeguards 1p 17730.251

8303290148 License for Westinghouse to export three ion chambers to Canada
PETERSON, M. F. Assistant Director for Export/Import & International Safeguards V2A00085. 83/03/18 1p 17730.250

8303290150 Ltr of assurance re export of 207 kg U-235 contained in 6,834 kg U, to Japan
SHIRAKAWA, T. Japan, Govt of. 83/03/18 GRIFFIN, J. A. Energy, Dept. of 1p 17730.192

8303290168 Ltr of assurance re export of 611 kg U-235 contained in 21,294 kg U, to Japan
SHIRAKAWA, T. Japan, Govt of. 83/03/18 GRIFFIN, J. A. Energy, Dept. of 1p 17730.220

8303290169 Forwards correction to application for export license for minor nuclear export
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/03/18 GRIFFIN, J. A. Energy, Dept. of 1p 17730.218

--8303290173 Corrected application for export license for minor nuclear export, changing recipient address
SHAW, A. Edlow International Co. 83/03/09 WRIGHT, B. NRC - No Detailed Affiliation Given 1p 17730.219

8303290179 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/03/18 GRIFFIN, J. A. Energy, Dept. of 1p 17730.196

8303290183 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/03/18 GRIFFIN, J. A. Energy, Dept. of 1p 17730.195

8303290189 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/03/18 GRIFFIN, J. A. Energy, Dept. of 1p 17730.183

8303290207 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/03/18 GRIFFIN, J. A. Energy, Dept. of 1p 17729.176

8303290213 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/03/18 GRIFFIN, J. A. Energy, Dept. of 1p 17729.177

8303290220 Requests Executive Branch position re Edlow Intl Co application for export license amend to re-export 200-uCi source of Cf-252 to Israel
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/03/18 STOIBER, C. R. State, Dept. of, Bureau of Oceans & Intl Environ & Scient. Affairs 1p 17728.324

8303290227 Executive Branch position re Saunders-Roe Development, Inc application to amend export license authorizing increase in max monthly shipments to five Amend to export license should be granted
DEVINE, J. B. State, Dept. of, Bureau of Oceans & Intl Environ & Scient. Affairs 83/03/15 SHEA, J. R. Office of International Programs, Director 1p 17727.327

8303300051 Application for license to export 7 microgram curium dioxide electro deposited on platinum, to China
* Isotope Products Laboratories 83/03/17 1p 17751.094

8303300714 Application for license to export six Model RS-P6-1608-110 fission counters to India
SKARUPA, J. D. Reuter-Stokes, Inc GE-8594 83/03/17 1p 17764.273

8303300726 Application for license to export four Model RS-C2-0608-129 ionization chambers to India
SKARUPA, J. D. Reuter-Stokes, Inc GE-8593 83/03/17 1p 17764.274

8303310327 Application for license to export one Model N121-180-1 check valve & one lot QA documentation to Canada
* Circle Seal Controls N20157 83/03/14 1p 17760.353

8303310332 Application for license to export eight Model NV02*2 check valves, one lot engineering documentation & one lot quality documentation to Canada
* Circle Seal Controls N19950 83/03/14 1pp 17760.350

8303310544 License for ITT, General Controls Div to export specially designed spare parts for fuel shutoff valve to Canada
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards FB-83-125 83/03/28 1p 17780.363

8303310556 Returns applications for licenses to export detectors to India Requests for export licenses denied W/o encl
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/03/28 SKARUPA, J. D. Reuter-Stokes, Inc 1p 17780.359

8303310560 License for Byron Jackson Pump Div - Borg Warner to export miscellaneous specially designed parts & components for nuclear reactor coolant pumps to Switzerland
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 793-W-5823 83/03/25 1p 17780.357

8303310565 License for Reuter-Stokes, Inc to export two Model RS-C1-1210-135 ionization chambers to France
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards A-9623 83/03/25 1p 17780.358

8303310575 Submits application to amend export license, adding intermediate consignee shipping address
HERSCH, M. M. Westinghouse Electric Corp. MMH-354 83/03/24
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 1p 17780.345

8303310588 Forwards application to export depleted U greensalt to Israel
SMYTH, D. V. Milco International, Inc 83/03/25 HEMBY, E. Assistant Director for Export/Import & International Safeguards 2pp 17780.332

--8303310592 Application for license to export depleted U greensalt to Israel
SMYTH, D. V. Milco International, Inc 83/03/25 1p 17780.334

8303310607 License for Westinghouse to export one Model WL-23773 proportional counter to Belgium
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards ZE 20603A 83/03/25 1p 17780 325

8303310614 Application for license to export three Model RS-P7-0812-117 proportional counters to India
SKARUPA, J. D. Reuter-Stokes, Inc GF-8288 83/03/17 1p 17780 323

8303310650 License for Reuter-Stokes, Inc to export two incore probes, Models RS-C6-0201-278 & RS-C4-0201-201, to Italy
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards A-9737 83/03/23 1p 17780 317

# PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."


| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| AARON, J. R. | 8303040389* | 50-296 S |
| AARON, J. R. | 8303040395* | 50-296 S |
| AARON, J. R. | 8303150263* | 50-296 S |
| AARHEIM, H. | 8303170028 | XPORTLIC |
| ABBOTT, L. S. | 8303230467 | NUREG |
| ABDEL-KHALIK, S. | 8303300100* | 50-537 A |
| ABELSON, H. | 8303160055 | 50-461 A |
| ABRAHAM, F. M. | 8303070164* | 50-413 A |
| ACCORNERO, K. F. | 8303110324* | 50-244 P |
| ACKERMAN, W. C. | 8303090646 | 40-8502 |
| ACKERMAN, W. C. | 8303090652 | 40-8502 |
| ACKERMAN, W. C. | 8303090832 | 40-8594 |
| ACREE, E. H. | 8303040080* | 71-9160 |
| ACREE, E. H. | 8303040088* | 71-9160 |
| ACREE, E. H. | 8303040099* | 71-9160 |
| ACREE, E. H. | 8303040106* | 71-9160 |
| ACTON, R. W. | 8303010076 | 50-440 Q |
| ADAMKUS, V. V. | 8303020129 | 40-2061 |
| ADAMS, J. E. | 8303070165* | GA999 |
| ADAMS, J. E. | 8303070171* | GA999 |
| ADAMS, J. E. | 8303070172* | GA999 |
| ADCOCK, B. R. | 8303250129 | 50-170 P |
| ADENSAM, E. G. | 8303010131 | 50-395 P |
| ADENSAM, E. G. | 8303010169* | 50-395 P |
| ADENSAM, E. G. | 8303020152* | 50-413 E |
| ADENSAM, E. G. | 8303020208 | 50-369 P |
| ADENSAM, E. G. | 8303030277 | 50-390 A |
| ADENSAM, E. G. | 8303030768 | 50-522 O |
| ADENSAM, E. G. | 8303040004 | 50-413 A |
| ADENSAM, E. G. | 8303090008 | 50-329 F |
| ADENSAM, E. G. | 8303090466 | 50-369 P |
| ADENSAM, E. G. | 8303150694 | 50-369 F |
| ADENSAM, E. G. | 8303160002 | 50-413 A |
| ADENSAM, E. G. | 8303160003 | 50-413 A |
| ADENSAM, E. G. | 8303160025 | 50-413 A |
| ADENSAM, E. G. | 8303170606 | 50-395 P |
| ADENSAM, E. G. | 8303170611* | 50-395 P |
| ADENSAM, E. G. | 8303170623* | 50-395 P |
| ADENSAM, E. G. | 8303180117 | 50-395 F |
| ADENSAM, E. G. | 8303180153 | 50-329 A |
| ADENSAM, E. G. | 8303230057 | 50-369 F |
| ADENSAM, E. G. | 8303230325* | 50-370 P |
| ADENSAM, E. G. | 8303230425 | 50-327 P |
| ADENSAM, E. G. | 8303230431* | 50-327 P |
| ADENSAM, E. G. | 8303230438* | 50-327 P |
| ADENSAM, E. G. | 8303230443 | 50-327 P |
| ADENSAM, E. G. | 8303230446* | 50-327 P |
| ADENSAM, E. G. | 8303230454* | 50-327 P |
| ADENSAM, E. G. | 8303240075 | 50-369 P |
| ADENSAM, E. G. | 8303290843 | 50-413 A |
| ADENSAM, E. G. | 8303290850 | 50-413 A |
| ADENSAM, E. G. | 8303300137 | 50-390 A |
| ADENSAM, E. G. | 8303300348 | 50-395 P |
| ADENSAM, E. G. | 8303300354* | 50-395 P |
| ADENSAM, E. G. | 8303300363* | 50-395 P |
| ADENSAM, E. G. | 8303300664 | 50-395 P |
| ADENSAM, E. G. | 8303300666 | 50-327 P |
| ADENSAM, E. G. | 8303300668 | 50-369 P |
| ADENSAM, E. G. | 8303300785 | 50-329 A |
| ADLER, R. W. | 8303080068 | 50-289 G |
| ADRAGNA, J. M. | 8303070109 | PROJ |
| ADRAGNA, J. M. | 8303070109 | PROJ |
| AHEARNE, J. | 8303090243* | FOIA |
| AHEARNE, J. | 8303180622* | COMMISSION |
| AHEARNE, J. | 8303300621* | FOIA |
| AHEARNE, J. F. | 8303040181 | COMMISSION |
| AHEARNE, J. F. | 8303090043* | FOIA |
| AHMED, A. | 8303180415* | 50-400 Q |
| AHMED, A. | 8303300454* | 50-440 E |
| AHN, T. M. | 8303090564 | RES |
| AKER, R. E. | 8303010671* | 50-295 S |
| AKI, K. | 8303010003* | 50-206 P |
| ALBRIGHT, R. H. | 8303010471* | 50-261 O |
| ALBRIGHT, R. H. | 8303010608* | 50-369 Q |
| ALDEN, W. M. | 8303080458* | 50-277 R |
| ALDEN, W. M. | 8303090118 | 50-277 R |
| ALDEN, W. M. | 8303150571 | 50-277 P |
| ALDEN, W. M. | 8303160338* | 50-277 R |
| ALDEN, W. M. | 8303160559 | 50-277 R |
| ALDRICH, D. C. | 8303290688* | NUREG |
| ALEXANDER, J. F. | 8303090520 | NUREG |
| ALEXICH, M. P. | 8303010265 | 50-315 P |
| ALEXICH, M. P. | 8303010315 | 50-315 P |
| ALEXICH, M. P. | 8303010323 | 50-315 P |
| ALGER, D. M. | 8303090324* | 50-186 Q |
| ALGER, D. M. | 8303090407* | 50-186 Q |
| ALLAN, J. M. | 8303110031* | 50-272 Q |
| ALLEN, Q. C. | 8303160614 | NUREG |
| AMICO, P. J. | 8303110192 | 50-247 Q |
| AMSTUTZ, S. | 8303080033* | 50-155 R |
| AMSTUTZ, S. | 8303150529* | 50-155 R |
| ANAGLIA, R. | 8303090659 | NUREG |
| ANANDAPPA, A. | 8303080326* | 50-237 S |
| ANANDAPPA, A. N. | 8303080147* | 50-249 S |
| ANDERSON, A. E. | 8303100382* | 50-412 Q |
| ANDERSON, C. J. | 8301310290* | 50-277 Q |
| ANDERSON, C. J. | 8303240301* | 50-352 Q |
| ANDERSON, C. J. | 8303280303* | 50-354 Q |
| ANDERSON, F. | 8303220438 | 50-369 P |
| ANDERSON, H. T. | 8303110301* | 50-282 Q |
| ANDERSON, P. | 8303230257 | 50-266 Q |
| ANDERSON, P. H. | 8303110209 | 50-400 Q |
| ANDERSON, P. H. | 8303110209 | 50-400 Q |
| ANDERSON, P. H. | 8303230186 | 50-400 Q |
| ANDERSON, P. H. | 8303230186 | 50-400 Q |
| ANDOGNINI, G. C. | 8303140541 | 50-528 Q |
| ANDOGNINI, G. C. | 8303290249 | 70-2949 |
| ANDREWS, W. B. | 8303150680 | NUREG |
| ANDREYCHEK, T. S. | 8303090659 | NUREG |
| ANDRUS, N. J. | 8303090390 | 40-4492 |
| ANDRUS, N. J. | 8303140687 | 40-4492 |
| ANDRUS, N. J. | 8303180173 | 40-4492 |
| ANG, W. P. | 8303010168* | 50-370 Q |
| ANG, W. P. | 8303010341* | 50-390 Q |
| ANGERT, E. | 8303150519* | 50-244 R |
| APICELLA, F. G. | 8303300663 | 50-331 P |
| ARCHITZEL | 8303210380 | 50-387 S |
| ARCHITZEL, R. | 8303100327 | 50-278 S |
| ARCHITZEL, R. E. | 8303100243* | 50-317 Q |
| ARIAS, J. | 8303410557* | 50-250 S |
| ARISAKA, H. | 8303040193* | COMMISSION |
| ARMANTROUT, G. A. | 8303290626 | WASTE MGT |
| ARNDT, E. G. | 8303090602 | ORG |
| ARNDT, E. G. | 8303090623* | ORG |
| ARNOLD, N. C. | 8303040402 | 50-320 P |
| ARNOLD, N. C. | 8303040410* | 50-320 P |
| ARNOLD, R. C. | 8303100737 | 50-289 P |
| ARNOLD, W. D. | 8303170624 | NUREG |
| ARORA, H. | 8303090531 | RES |
| ARORA, H. | 8303090569 | RES |
| ARROWSMITH, P. D. | 8303310291* | FOIA |
| ARROWSMITH, P. D. | 8303310098* | FOIA |
| ASHBURN, D. J. | 8303240019 | TOPREP |
| ASHBURN, D. J. | 8303240093 | TOPREP |
| ASHBURN, D. J. | 8303240201 | MISC |
| ASHBURN, D. J. | 8303240206 | TOPREP |
| ASHTON, M. H. | 8303300698* | CONTRACT |
| ASIALA | 8303290511 | 50-329 Q |
| ASPREY, M. W. | 8303230517 | NUREG |
| ASSELSTINE, J. K. | 8303090250* | FOIA |
| ASSELSTINE, J. K. | 8303300636* | FOIA |
| ATWOOD, C. L. | 8303220394 | NUREG |
| ATWOOD, C. L. | 8303220400 | NUREG |
| ATWOOD, C. L. | 8303220409 | NUREG |
| ATWOOD, C. L. | 8303230281 | NUREG |
| AUDIN, L. | 8303020196 | FOIA |
| AULUCK, R. | 8303030094 | 50-397 F |
| AULUCK, R. | 8303030692 | 50-397 Q |
| AULUCK, R. | 8303090015 | 50-397 F |
| AULUCK, R. | 8303140009 | 50-397 A |
| AULUCK, R. | 8303230434 | 50-397 A |
| AULUCK, R. | 8303290105 | 50-397 A |
| AUSTIN, Q. | 8303150354* | 50-295 R |
| AUSTIN, J. H. | 8303170182* | 50-171 I |
| AUSTIN, M. A. | 8303020217 | 70-364 |
| AUTIO, H. A. | 8303010402 | 50-29 S |
| AUTIO, H. A. | 8303010629 | 50-29 S |
| AUTIO, H. A. | 8303010674 | 50-29 S |
| AUTIO, H. A. | 8303040450 | 50-29 S |
| AUTIO, H. A. | 8303090139 | 50-29 S |
| AUTIO, H. A. | 8303140529 | 50-29 S |
| AVANT, D. | 8303220090* | 50-187 R |
| AVANT, D. W. | 8303220083 | 50-187 R |
| AXELRAD, J. | 8303040557 | 50-313 Q |
| AXELRAD, J. | 8303180298 | 50-382 Q |

# PERSONAL AUTHOR INDEX


| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| AXELRAD, J. | 8303230026 | 50-482 G |
| AXELRAD, J. | 8303230028 | I&E |
| AXELRAD, J. | 8503230030 | I&E |
| AXELRAD, J. | 8703230225 | 50-280 G |
| AXELRAD, J. | 8303230229 | 50-272 G |
| AXELRAD, J. | 8303230236 | 50-361 G |
| AXELRAD, J. | 8703280043 | 50-277 G |
| AXELRAD, J. A. | 8303010541 | 50-259 G |
| AXELRAD, J. A. | 8303040096 | 50-312 G |
| AXELRAD, J. A. | 8303040285 | 50-331 G |
| AXELROD, D. | 8303040533* | State Prog |
| AXELROD, D. | 8303300466 | 50-322 G |
| AXELSON, W. L. | 8303140314* | 50-295 G |
| AXELSON, W. L. | 8303150604* | 50-254 G |
| AXELSON, W. L. | 8303210097* | 50-287 G |
| AXELSON, W. L. | 8303240259* | 50-266 G |
| AXELSON, W. L. | 8303240597* | 50-10 G |
| BABBITT, B. | 8303020304* | COMMISSION |
| BACHMANN, R. G. | 8303140444 | 50-155 G |
| BACHMANN, R. G. | 8303140514 | 50-155 G |
| BACKUS, R. A. | 8303180323 | 50-443 G |
| BACKUS, R. A. | 8303180323 | 50-443 G |
| BACKUS, R. A. | 8303180329* | 50-443 G |
| BACKUS, R. A. | 8303180329* | 50-443 G |
| BACKUS, R. A. | 8303230212 | 50-443 G |
| BACKUS, R. A. | 8303230212 | 50-443 G |
| BACKUS, R. A. | 8303230216* | 50-443 G |
| BACKUS, R. A. | 8303230216* | 50-443 G |
| BACKUS, R. A. | 8303250164 | 50-443 G |
| BACKUS, R. A. | 8303250164 | 50-443 G |
| BAER, R. | 8303180244* | 50-285 G |
| BAER, R. | 8303180433* | 50-313 G |
| BAER, R. E. | 8303090613 | 50-498 G |
| BAER, R. E. | 8303190223* | 50-247 G |
| BAER, R. L. | 8303090411* | FOIA |
| BAER, R. L. | 8303100356* | COMMISSION |
| BAGBY, L. A. | 8303280356 | 71-9157 |
| BAILEY, E. D. | 8303090337* | WASTE MGT |
| BAILEY, H. R. | 8303090197 | 50-329 H |
| BAILEY, R. | 8303160482* | 50-289 G |
| BAILEY, R. J. | 8303030206* | 50-320 G |
| BAIR, G. G. | 8303110335* | 50-344 S |
| BAISDEN, L. | 8303040281 | CONTRACT |
| BAISDEN, L. | 8303310584 | CONTRACT |
| BALDWIN, P. | 8303210741* | 50-361 P |
| BALL, S. J. | 8303160009 | NUREG |
| BALLARD, W. W. | 8303300083 | WASTE MGT |
| BALLENTINE, J. M. | 8303090216 | 50-327 R |
| BALLINGER, P. L. | 8303090191* | 50-298 R |
| BALLINGER, P. L. | 8303150555* | 50-298 R |
| BALOG, J. | 8303150459* | 50-537 G |
| BANGART, R. L. | 8303010247* | 50-313 G |
| BARAN, R. | 8303080347* | 50-219 R |
| BARAN, R. | 8303150431* | 50-219 R |
| BARBER, G. | 8303230225 | 50-280 G |
| BARBER, G. | 8303230229 | 50-272 G |
| BARBER, G. | 8303230236 | 50-361 G |
| BARHAM, C. D. | 8303150170 | 50-324 J |
| BARHAM, C. D. | 8303150177 | 50-324 J |
| BARHAM, C. D. | 8303150187 | 50-324 J |
| BARHAM, C. D. | 8303150192 | 50-261 J |
| BARHAM, C. D. | 8303150197 | 50-261 J |
| BARHAM, C. D. | 8303150308 | 50-261 J |
| BARHAM, C. D. | 8303150315 | 50-261 J |
| BARHAM, C. D. | 8303150323 | 50-324 J |
| BARI, R. A. | 8303140664 | 50-352 A |
| BARKER, N. R. | 8303070140* | QA999 |
| BARKER, N. R. | 8303070147* | QA999 |
| BARNES, C. | 8303230507 | 40-1478 |
| BARNES, C. | 8303230510 | 70-146 |
| BARNES, I. | 8303010468* | QA999 |
| BARNES, I. | 8303010483* | QA999 |
| BARNES, I. | 8303070027* | QA999 |
| BARNES, I. | 8303070126* | QA999 |
| BARNES, I. | 8303070136* | QA999 |
| BARNES, I. | 8303150172* | QA999 |
| BARNES, I. | 8303150278* | QA999 |
| BARNES, I. | 8303150373* | QA999 |
| BARNES, I. | 8303150530* | 50-445 G |
| BARNES, I. | 8303180212* | QA999 |
| BARNES, I. | 8303180381* | QA999 |
| BARNES, I. | 8303280171* | QA999 |
| BARNES, I. | 8303280222* | QA999 |
| BARNES, W. R. | 8303010100 | 50-440 G |
| BARNETT, J. E. | 8303110275 | 70-1621 |
| BARNHART, R. | 8303080065 | 50-454 T |
| BARR, K. | 8303280173* | 50-320 G |
| BARR, K. P. | 8303010216* | 50-389 G |
| BARR, K. P. | 8303010251* | 50-302 G |
| BARR, K. P. | 8303010353* | 50-327 G |
| BARR, K. P. | 8303010471* | 50-261 G |
| BARR, K. P. | 8303010501* | 50-416 G |
| BARR, K. P. | 8303010508* | 50-416 G |
| BARR, K. P. | 8303010608* | 50-369 G |
| BARR, K. P. | 8303210409* | 50-324 G |
| BARR, K. P. | 8303210588* | 50-250 G |
| BARR, K. P. | 8303210721* | 50-389 G |
| BARR, K. P. | 8303210727* | 50-348 G |
| BARRETT, L. H. | 8303010711 | 50-320 R |
| BARRETT, L. H. | 8303010728 | 50-320 P |
| BARRETT, L. H. | 8303100420 | 50-320 R |
| BARRETT, L. H. | 8303100422 | 50-320 R |
| BARRETT, L. H. | 8303160054 | 50-320 P |
| BARRETT, L. H. | 8303170080 | 50-320 R |
| BARRETT, P. A. | 8303110366* | 50-329 G |
| BARTH, C. A. | 8303070060 | 50-358 G |
| BARTH, C. A. | 8303070116 | 50-400 G |
| BARTH, C. A. | 8303140214 | 50-400 G |
| BARTH, C. A. | 8303150320 | 50-400 G |
| BARTH, C. A. | 8303180034 | 50-358 G |
| BARTH, C. A. | 8303220224 | 50-400 G |
| BARTH, C. A. | 8303220228 | 50-400 G |
| BARTH, C. A. | 8303220236 | 50-400 G |
| BARTH, C. A. | 8303220242 | 50-400 G |
| BARTH, C. A. | 8303240281 | 50-400 G |
| BARTON, J. J. | 8303150293* | 50-320 G |
| BARTTER, W. D. | 8303303651 | NUREG |
| BASDEKAS, D. L. | 8211210425* | GEN TEC IS |
| BASDEKAS, D. L. | 8212290096 | GEN TEC IS |
| BASDEKAS, D. L. | 8212290099* | GEN TEC IS |
| BASDEKAS, D. L. | 8301060379 | GEN TEC IS |
| BASKIN, K. P. | 8303040525 | 50-361 P |
| BASKIN, K. P. | 8303070018 | 50-206 P |
| BASKIN, K. P. | 8303070020 | 50-206 P |
| BASKIN, K. P. | 8303070039 | 50-206 V |
| BASKIN, K. P. | 8303070073 | 50-206 P |
| BASKIN, K. P. | 8303070079 | 50-206 P |
| BASKIN, K. P. | 8303080192 | 50-361 P |
| BASKIN, K. P. | 8703090151 | 50-361 P |
| BASKIN, K. P. | 9001150477 | 50-206 P |
| BASKIN, K. P. | 8302210643 | 50-361 P |
| BASKIN, K. P. | 8303240016 | 50-361 Q |
| BASKIN, K. P. | 8303250012 | 50-206 F |
| BASKIN, K. P. | 8303250029 | 50-206 F |
| BASKIN, K. P. | 8303300232* | 50-206 F |
| BASKIN, K. P. | 8303310299 | 50-361 P |
| BASS, B. R. | 8303300511 | NUREG |
| BASS, G. | 8303140520* | 50-260 S |
| BASS, G. W. | 8303160438* | 50-296 S |
| BASS, G. W. | 8303240605* | 50-259 S |
| BASSO, L. F. | 8303160265* | 50-318 S |
| BASSO, L. F. | 8303160411* | 50-318 S |
| BATEMAN, W. | 8303150382* | 70-143 |
| BATEMAN, W. H. | 8303240575* | 50-354 Q |
| BATES, J. W. | 8303010621* | 70-1113 |
| BATES, J. W. | 8303210600* | 70-1113 |
| BATTERSON, S. | 8303080013* | 50-309 R |
| BATTERSON, S. | 8303080369* | 50-29 R |
| BATTERSON, S. | 8303150425* | 50-309 R |
| BATTERSON, S. | 8303150556* | 50-29 R |
| BATTS, M. | 8303290704 | NUREG |
| BAUBLITZ, J. E. | 8303180056 | WASTE MGT |
| BAUER, E. G. | 8303010431 | 50-352 A |
| BAUER, E. G. | 8303150379* | 50-277 P |
| BAUER, T. L. | 8303160266 | 50-192 E |
| BAUGHMAN, J. D. | 8303020073 | 50-146 H |
| BAUHOF, F. | 8303280097 | NUREG |
| BAUHOF, F. | 8303280114 | NUREG |
| BAUHOF, F. | 8303300446 | NUREG |
| BAUMAN, R. C. | 8303220370 | 50-329 A |
| BAUMAN, T. A. | 8303020222* | 70-364 |
| BAUMANN, W. L. | 8303140617 | NUREG |
| BAUMGARD, R. W. | 8303020318 | XPORTLIC |
| BAUMGARD, R. W. | 8303020324* | XPORTLIC |
| BAUNACK, W. H. | 8303080428* | 50-244 Q |
| BAUSER, D. B. | 8303110211 | 50-400 Q |
| BAUSER, D. B. | 8303110211 | 50-400 Q |
| BAUSER, D. B. | 8303140252 | 50-400 Q |
| BAUSER, D. B. | 8303140252 | 50-400 Q |
| BAUSER, D. B. | 8303140258* | 50-400 Q |
| BAUSER, D. B. | 8303140258* | 50-400 Q |
| BAUSER, D. B. | 8303140262* | 50-400 Q |
| BAUSER, D. B. | 8303140262* | 50-400 Q |
| BAUSER, D. B. | 8303140266* | 50-400 Q |
| BAUSER, D. B. | 8303140266* | 50-400 Q |
| BAXTER, T. A. | 8303070083 | 50-289 Q |
| BAXTER, T. A. | 8303070083 | 50-289 Q |
| BAXTER, T. A. | 8303070093 | 50-289 Q |
| BAXTER, T. A. | 8303070093 | 50-289 Q |
| BAXTER, T. A. | 8303170431 | 50-289 Q |
| BAXTER, T. A. | 8303170431 | 50-289 Q |
| BAXTER, T. A. | 8303250160 | 50-400 Q |
| BAXTER, T. A. | 8303250160 | 50-400 Q |
| BAXTER, T. A. | 8303290506 | 50-400 Q |
| BAXTER, T. A. | 8303290506 | 50-400 Q |
| BAY, J. H. | 8303140267 | 50-142 Q |
| BAY, J. H. | 8303140267 | 50-142 Q |
| BAYNARD, P. Y. | 8303080029 | 50-302 R |
| BAYNARD, P. Y. | 8303210663 | 50-302 Q |
| BAYNE, J. P. | 8302180153 | 50-333 P |
| BAYNE, J. P. | 8303020008 | 50-333 P |
| BAYNE, J. P. | 8303020015* | 50-333 P |
| BAYNE, J. P. | 8303040349 | 50-333 F |
| BAYNE, J. P. | 8303080322 | 50-286 V |
| BAYNE, J. P. | 8303080443 | 50-286 H |
| BAYNE, J. P. | 8303080493 | 50-333 V |
| BAYNE, J. P. | 8303110245 | 50-286 P |
| BAYNE, J. P. | 8303150437 | 50-286 R |
| BAYNE, J. P. | 8303160266 | 50-333 Q |
| BAYNE, J. P. | 8303170207 | 50-286 P |
| BAYNE, J. P. | 8303180350 | 50-333 P |
| BAYNE, J. P. | 8303180356 | 50-333 P |
| BAYNE, J. P. | 8303180362 | 50-333 P |
| BAYNE, J. P. | 8303180365 | 50-333 P |
| BAYNE, J. P. | 8303180375 | 50-333 P |
| BAYNE, J. P. | 8303180479 | 50-286 P |
| BAYNE, J. P. | 8303220153 | 50-333 P |
| BAZIN, J. P. | 8303160064 | CONTRACT |
| BEACH, A. B. | 8303090374* | 50-458 Q |
| BEACH, W. | 8303250034* | 50-458 Q |
| BEAN, C. H. | 8303180549 | RES |
| BEARE, A. N. | 8303270142 | NUREG |
| BECHHOEFER, C. | 8302280189 | 50-329 T |
| BECHHOEFER, C. | 8303080441 | 50-329 Q |
| BECHHOEFER, C. | 8303100351 | 50-329 Q |
| BECHHOEFER, C. | 8303150417 | 50-329 Q |
| BECK, G. P. | 8303030212 | 50-151 R |
| BECK, J. W. | 8303030792* | 50-329 A |
| BECK, J. W. | 8303040041* | 50-329 A |
| BECKETT, G. E. | 8303160550 | 50-245 P |
| BECKHAM, J. T. | 8303010520* | 50-321 Q |
| BECKHAM, J. T. | 8303170300 | 50-321 P |
| BECKHAM, J. T. | 8303210361 | 50-321 Q |
| BECKHAM, J. T. | 8303210427 | 50-321 P |
| BECKHAM, J. T. | 8303290322 | 50-366 P |
| BEDROSIAN, B. | 8303010362* | 50-397 E |
| BEHLING, S. R. | 8303180555 | RES |
| BEIERS, T. S. | 8303110312* | 50-317 Q |
| BEIERS, T. S. | 8303110317* | 50-317 Q |
| BEILMAN, T. P. | 8303080344* | 50-315 S |
| BELANGER, J. L. | 8303030473* | 50-255 Q |
| BELANGER, J. L. | 8303030543* | 50-305 Q |
| BELANGER, J. L. | 8303280321* | 50-254 Q |
| BELISLE, G. A. | 8303210662* | 50-321 Q |
| BELL, C. R. | 8303230517 | NUREG |
| BELL, M. J. | 8303300098 | WASTE MGT |
| BELL, M. J. | 8303300152 | WASTE MGT |
| BELL, N. | 8303010086 | 50-460 Q |
| BELL, N. | 8303140268 | 50-460 Q |
| BELL, N. | 8303180331 | 50-397 Q |
| BELL, N. | 8303180344* | 50-397 Q |
| BELLEVILLE, A. | 8303290149* | 50-322 H |
| BELMORE, C. I. | 8303240405* | 50-219 R |
| BELSER, A. L. | 8303070072* | 50-387 F |
| BEMIS, P. | 8303010137* | 50-400 Q |
| BEMIS, P. | 8303010553* | 50-400 Q |
| BEMIS, P. | 8303210386* | 50-261 Q |
| BEMIS, P. R. | 8303210501* | 50-83 Q |
| BENSON, J. J. | 8303040572* | QA999 |
| BENTLEY, W. H. | 8303030627* | 50-331 S |
| BENTON, J. | 8303310266* | 50-445 T |
| BERG, K. | 8303180688* | CONTRACT |
| BERG, R. E. | 8303300215 | 40-8585 |
| BERGHOLZ, W. E. | 8303020022 | 70-143 |
| BERGHOLZ, W. E. | 8303070160 | 70-143 |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | |
|---|---|---|---|
| BERGHOLZ, W. E. | 8303070160 | 70-143 | |
| BERGHOLZ, W. E. | 8303180203 | 70-143 | |
| BERLIN, K. | 8303140472* | 50-528 | Q |
| BERLIN, K. | 8303140472* | 50-528 | Q |
| BERLIN, K. | 8303180289 | 50-529 | Q |
| BERNABEI, L. | 8303240398 | 50-528 | Q |
| BERNABEI, L. | 8303240398 | 50-528 | Q |
| BERNERO, R. M. | 8303230237* | 50-247 | T |
| BERNHOFT, S. L. | 8303080134* | 50-305 | S |
| BERNHOFT, S. L. | 8303140414* | 50-305 | S |
| BERNHOFT, S. L. | 8303140505* | 50-305 | S |
| BERNHOFT, S. L. | 8303240238* | 50-305 | S |
| BERNHOFT, S. L. | 8303240574* | 50-305 | S |
| BERRETH, A. J. | 8303090601 | 40-8584 | |
| BESS, J. | 8303010587* | 50-458 | Q |
| BETTENHAUSEN, L. | 8303160433* | 50-272 | Q |
| BEVAN, R. | 8202100501* | 50-265 | S |
| BEVAN, R. B. | 8303180069 | 50-265 | P |
| BEVAN, R. B. | 8303300648 | 50-265 | P |
| BEVAN, R. B. | 8303310089 | COMMISSION | |
| BEVERLY, R. G. | 8303140684 | 40-299 | |
| BEVERLY, R. G. | 8303180125 | 40-299 | |
| BIALECKI, L. | 8303210741* | 50-361 | P |
| BIALIK, E. I. | 8303220206* | 50-322 | Q |
| BIBB, H. E. | 8303210453* | 50-335 | Q |
| BICKFORD, W. E. | 8303150680 | NUREG | |
| BIDINGER, G. H. | 8303090230* | 70-820 | |
| BIDINGER, G. H. | 8303110069* | 70-2917 | |
| BIDINGER, G. H. | 8303110165* | 70-2928 | |
| BIDINGER, G. H. | 8303140039* | 70-1062 | |
| BIDINGER, G. H. | 8303180526* | 70-2810 | |
| BIELAWSKI, A. | 8303140275 | 50-434 | Q |
| BIELAWSKI, A. | 8303140275 | 50-434 | Q |
| BIELAWSKI, A. P. | 8303010068 | 50-434 | Q |
| BIELAWSKI, A. P. | 8303010068 | 50-458 | Q |
| BILLITER, T. R. | 8303030103 | RES | |
| BIRCH, M. L. | 8303080324* | 50-369 | P |
| BIRKEL, R. A. | 8303150020 | 50-369 | P |
| BIRKEL, R. A. | 8303330366 | 50-369 | P |
| BISBEE, G. D. | 8303230251 | 50-443 | Q |
| BISBEE, G. D. | 8303230256* | 50-443 | Q |
| BISBEE, G. D. | 8303250153 | 50-443 | Q |
| BISBEE, G. D. | 8303250154* | 50-443 | Q |
| BISBEE, G. D. | 8303290162* | 50-443 | Q |
| BISBEE, G. D. | 8303290166* | 50-443 | Q |
| BISBEE, G. D. | 8303290170* | 50-443 | Q |
| BISBEE, G. D. | 8303290171* | 50-443 | Q |
| BISHOP, L. L. | 8303090082 | FOIA | |
| BISHOP, L. L. | 8303090219 | FOIA | |
| BISHOP, T. W. | 8303010419 | 50-275 | D |
| BISHOP, T. W. | 8303040404 | 50-206 | Q |
| BISHOP, T. W. | 8303040409 | 50-275 | Q |
| BISHOP, T. W. | 8303040447 | 50-275 | Q |
| BISHOP, T. W. | 8303150296 | 50-361 | Q |
| BISHOP, T. W. | 8303150511 | 50-70 | Q |
| BISHOP, T. W. | 8303290247 | 50-361 | Q |
| BISHOP, T. W. | 8303290262 | 50-275 | Q |
| BISHOP, T. W. | 8303290273 | 50-206 | Q |
| BISHOP, T. W. | 8303290508* | 50-361 | Q |
| BISHOP, T. W. | 8303290582 | 50-361 | Q |
| BISSETT, P. | 8303160431* | 50-272 | Q |
| BISSETT, P. H. | 8303240373* | 50-213 | Q |
| BLACK, S. A. | 8303140450* | 70-124 | |
| BLACKLEY, S. K. | 8303140236 | REVIEW GRP | |
| BLACKLEY, S. K. | 8303140257 | REVIEW GRP | |
| BLAKE, J. J. | 8303010168* | 50-370 | Q |
| BLAKE, J. J. | 8303010195* | 50-250 | Q |
| BLAKE, J. J. | 8303010378* | 50-389 | Q |
| BLAKE, J. J. | 8303010537* | 50-321 | Q |
| BLAKE, J. J. | 8303210335* | 50-400 | Q |
| BLAKE, J. J. | 8303210341* | 50-417 | Q |
| BLAKE, J. J. | 8303210398* | 50-390 | Q |
| BLAKE, J. J. | 8303210497* | 50-424 | Q |
| BLANCHARD, B. | 8303140425 | 50-413 | D |
| BLANDFORD, R. K. | 8303300423 | RES | |
| BLEY, D. C. | 8303250149* | 50-247 | T |
| BLEY, D. C. | 8303250149* | 50-247 | T |
| BLOCH, P. B. | 8303070111 | 50-440 | Q |
| BLOCH, P. B. | 8303310286 | 50-440 | Q |
| BLOMGREN, J. C. | 8303010340* | 50-454 | T |
| BLOND, R. | 8303230233* | 50-247 | T |
| BLOOMBERG, J. R. | 8303300677* | CONTRACT | |
| BLOSSOM, J. N. | 8303220460 | 40-8452 | |
| BLOUGH, A. R. | 8303250070* | 50-277 | Q |
| BLUBAUGH, R. E. | 8303090071 | 40-3453 | |
| BLUBAUGH, R. E. | 8303170682 | 40-3453 | |
| BLUMBERG, N. J. | 8303290346* | 50-247 | Q |
| BOARDMAN, J. R. | 8303150491* | 50-498 | Q |
| BODINE, J. C. | 8303010372* | 50-244 | S |
| BODINE, J. C. | 8303010470* | 50-244 | S |
| BODINE, J. C. | 8303010487* | 50-244 | S |
| BOGART, D. | 8303080039* | 50-302 | R |
| BOGART, D. | 8303080045* | 50-302 | R |
| BOGART, D. | 8303160325* | 50-302 | R |
| BOGDEN, G. | 8303090024 | 40-1162 | |
| BOGDEN, G. | 8303090049 | 40-1162 | |
| BOGDEN, G. | 8303180129 | 40-1162 | |
| BOGDEN, G. | 8303180145 | 40-1162 | |
| BOGDEN, G. | 8303180511 | 40-1162 | |
| BOGDEN, G. | 8303300145 | 40-1162 | |
| BOGDEN, G. | 8303300236 | 40-1162 | |
| BOITEL, E. C. | 8303160213 | 50-30 | R |
| BOLANDER, M. A. | 8303300108 | 50-269 | P |
| BOMBERGER, C. | L302090302* | 50-271 | P |
| BOMBERGER, C. | 8302090307* | 50-250 | P |
| BOOK, H. E. | 8303040357 | 50-344 | Q |
| BOOK, H. E. | 8303040362* | 50-344 | Q |
| BOOK, H. E. | 8303080343 | 27-48 | |
| BOOK, H. E. | 8303080350* | 27-48 | |
| BOOK, H. E. | 8303140499 | 40-8713 | |
| BOOK, H. E. | 8303180401 | 50-312 | Q |
| BOOK, H. E. | 8303180407* | 50-312 | Q |
| BOOK, H. E. | 8303240566 | 70-25 | |
| BOOK, H. E. | 8303240577* | 70-25 | |
| BOOK, H. E. | 8303290250 | 50-528 | Q |
| BOOK, H. E. | 8303290257* | 50-528 | Q |
| BOOK, H. E. | 8303290456 | 50-344 | Q |
| BOOK, H. E. | 8303290463* | 50-344 | Q |
| BOOK, H. E. | 8303290468 | 50-206 | Q |
| BOOK, H. E. | 8303290474 | 50-141 | Q |
| BOOK, H. E. | 8303290480* | 50-141 | Q |
| BOOK, H. E. | 8303290592 | 40-8713 | |
| BOOKER, J. E. | 8303080009 | 50-458 | S |
| BOOKER, J. E. | 8303080362 | 50-458 | S |
| BOOKER, J. E. | 8303090342 | 50-458 | V |
| BOOKER, J. E. | 8303110219 | 50-458 | S |
| BOOKER, J. E. | 8303110255 | 50-458 | S |
| BOOKER, J. E. | 8303110387 | 50-458 | S |
| BOOKER, J. E. | 8303140066 | 50-458 | F |
| BOOKER, J. E. | 8303150264 | 50-458 | S |
| BOOKER, J. E. | 8303150282 | 50-458 | S |
| BOOKER, J. E. | 8303150605 | 50-458 | S |
| BOOKER, J. E. | 8303180018 | 50-458 | S |
| BOOKER, J. E. | 8303210466 | 50-458 | S |
| BOOKER, J. E. | 8303240468 | 50-458 | S |
| BOOKER, J. E. | 8303240476 | 50-458 | S |
| BOOKER, J. E. | 8303250050 | 50-458 | S |
| BOOKER, J. E. | 8303250110 | 50-458 | S |
| BOOKER, J. E. | 8303280141 | 50-458 | S |
| BOOKER, J. E. | 8303280229 | 50-458 | S |
| BOOKER, J. E. | 8303280230 | 50-458 | Q |
| BOOKER, J. E. | 8303280256 | 50-458 | S |
| BOOKER, J. E. | 8303280264 | 50-458 | Q |
| BORCHERT, R. | 8303180382* | 50-336 | S |
| BORDENICK, B. M. | 8303040315 | 50-322 | Q |
| BORDENICK, B. M. | 8303080040 | 50-322 | Q |
| BORDENICK, B. M. | 8303090132 | 50-322 | Q |
| BORDENICK, B. M. | 8303140002 | 50-322 | Q |
| BORDENICK, B. M. | 8303140073 | 50-322 | Q |
| BORDENICK, B. M. | 8303140161 | 50-322 | Q |
| BORDENICK, B. M. | 8303140170 | 50-322 | Q |
| BORDENICK, B. M. | 8303140200 | 50-322 | Q |
| BORDENICK, B. M. | 8303140489 | 50-322 | Q |
| BORDENICK, B. M. | 8303160035 | 50-322 | Q |
| BORDENICK, B. M. | 8303170153 | 50-322 | Q |
| BORDENICK, B. M. | 8303180037 | 50-322 | Q |
| BORDENICK, B. M. | 8303300016 | 50-322 | Q |
| BORDINE, T. C. | 8303170098 | 50-155 | P |
| BORDINE, T. C. | 8303280161 | 50-155 | R |
| BORGMANN, E. A. | 8303040486 | 50-358 | S |
| BORGMANN, E. A. | 8303080008 | 50-358 | K |
| BORGMANN, E. A. | 8303080178 | 50-358 | S |
| BORGMANN, E. A. | 8303080239 | 50-358 | S |
| BORGMANN, E. A. | 8303080288 | 50-358 | S |
| BORGMANN, E. A. | 8303080431 | 50-358 | S |
| BORGMANN, E. A. | 8303080434 | 50-358 | S |
| BORGMANN, E. A. | 8303080475 | 50-358 | S |
| BORGMANN, E. A. | 8303080485 | 50-358 | S |
| BORGMANN, E. A. | 8303080496 | 50-358 | R |
| BORGMANN, E. A. | 8303090101* | 50-358 | A |
| BORGMANN, E. A. | 8303090212* | 50-358 | A |
| BORGMANN, E. A. | 8303100221 | 50-358 | S |
| BORGMANN, E. A. | 8303150543* | 50-358 | Q |
| BORGMANN, E. A. | 8303170511 | 50-358 | K |
| BORGMANN, E. A. | 8303220007 | 50-358 | S |
| BORGMANN, E. A. | 8303220008 | 50-358 | S |
| BORGMANN, E. A. | 8303220064 | 50-358 | S |
| BORGMANN, E. A. | 8303220134 | 50-358 | R |
| BORGMANN, E. A. | 8303220174 | 50-358 | S |
| BORGMANN, E. A. | 8303290499 | 50-358 | S |
| BORKOWSKI, R. J. | 8303290717 | NUREG | |
| BORRENSEN, S. | 8303160421* | 50-324 | P |
| BORST, F. J. | 8303180099 | 71-9081 | |
| BORST, F. J. | 8303210651* | 50-267 | R |
| BORTZ, D. G. | 8303290028* | CONTRACT | |
| BOSTIAN, R. W. | 8303220321 | 50-370 | F |
| BOUCHER, T. J. | 8303150614 | NUREG | |
| BOUCHEY, G. D. | 8301110169 | 50-508 | K |
| BOUCHEY, G. D. | 8303010129 | 50-397 | Q |
| BOUCHEY, G. D. | 8303010234 | 50-397 | E |
| BOUCHEY, G. D. | 8303010357 | 50-397 | E |
| BOUCHEY, G. D. | 8303010649 | 50-397 | A |
| BOUCHEY, G. D. | 8303010684 | 50-397 | K |
| BOUCHEY, G. D. | 8303030192 | 50-508 | A |
| BOUCHEY, G. D. | 8303040397 | 50-397 | E |
| BOUCHEY, G. D. | 8303040449 | 50-460 | C |
| BOUCHEY, G. D. | 8303040482 | 50-397 | A |
| BOUCHEY, G. D. | 8303060607 | 50-397 | A |
| BOUCHEY, G. D. | 8303073138 | 50-397 | A |
| BOUCHEY, G. D. | 8303076134 | 50-397 | F |
| BOUCHEY, G. D. | 8303080220 | TUPREP | |
| BOUCHEY, G. D. | 8303090172 | 50-397 | V |
| BOUCHEY, G. D. | 8303150406 | 50-460 | A |
| BOUCHEY, G. D. | 8303160293 | 50-397 | A |
| BOUCHEY, G. D. | 8303160427 | 50-397 | F |
| BOUCHEY, G. D. | 8303170278 | 50-397 | F |
| BOUCHEY, G. D. | 8303210069 | 70-2950 | |
| BOUCHEY, G. D. | 8303220057 | 50-397 | A |
| BOUCHEY, G. D. | 8303240220 | 50-397 | A |
| BOUCHEY, G. D. | 8303290003 | 50-460 | A |
| BOUCHEY, G. D. | 8303290240 | 50-508 | A |
| BOUCHEY, G. D. | 8303290401 | 50-397 | A |
| BOUCHEY, G. D. | 8303290465 | 50-508 | A |
| BOURNIA, A. | 8303180354 | 50-373 | P |
| BOWERMAN, B. S. | 8303090616 | RES | |
| BOWMAKER, N. J. | 8303020061 | 50-317 | F |
| BOWMAKER, N. J. | 8303220015 | 50-317 | F |
| BOWMAN, C. E. | 8303290478* | 50-293 | R |
| BOYD, D. C. | 8303030650* | 50-255 | Q |
| BOYD, D. C. | 8303080270* | 50-315 | Q |
| BOYD, D. C. | 8303170506* | 50-295 | Q |
| BOYD, D. C. | 8303240597* | 50-10 | Q |
| BOYER, V. S. | 8301310266* | 50-352 | A |
| BOYER, V. S. | 8303020039* | 50-352 | A |
| BOYLE, R. R. | 8303290650 | WASTE MGT | |
| BOYLE, R. R. | 8303290655 | WASTE MGT | |
| BOYLE, S. | 8303230295 | FOIA | |
| BRAATZ, R. L. | 8303030350* | 50-247 | H |
| BRACKEN, K. W. | 8303280060 | 71-9152 | |
| BRADBURY, R. B. | 8302100345 | PRM | |
| BRADBURY, R. B. | 8303020092 | REGGD | |
| BRADBURY, R. B. | 8303020095 | NUREG | |
| BRADFORD, W. H. | 8303010221* | 50-348 | Q |
| BRADFORD, W. H. | 8303010437* | 50-348 | Q |
| BRADFORD, W. H. | 8303210436* | 50-348 | Q |
| BRADLEY, E. J. | 8301310260 | 50-352 | A |
| BRADLEY, E. J. | 8303020029 | 50-352 | A |
| BRADLEY, E. J. | 8303020039* | 50-352 | A |
| BRADLEY, E. J. | 8303030016 | 50-352 | A |
| BRADLEY, E. J. | 8303080205 | 50-277 | J |
| BRADLEY, E. J. | 8303100205 | 50-352 | A |
| BRADLEY, E. J. | 8303100358 | 50-277 | J |
| BRADLEY, E. J. | 8303140367 | 50-352 | A |
| BRADLEY, E. J. | 8303150371 | 50-277 | P |
| BRADLEY, E. J. | 8303150379* | 50-277 | P |
| BRADLEY, E. J. | 8303160494 | 50-352 | K |
| BRADLEY, E. J. | 8303170159 | 50-171 | I |
| BRADLEY, E. J. | 8303170545 | 50-352 | E |
| BRADLEY, E. J. | 8303180349 | 50-352 | A |
| BRADLEY, E. J. | 8303280035 | 50-352 | A |
| BRADLEY, E. J. | 8303290350 | 50-277 | J |
| BRAHMAVAR, S. M. | 8303140138* | FOIA | |
| BRAMLETT, L. S. | 8303080046* | 50-368 | R |
| BRAMLETT, L. S. | 8303150927* | 50-368 | R |
| BRAND, D. A. | 8303090226 | 50-133 | Q |

# PERSONAL AUTHOR INDEX


| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | |
|---|---|---|---|
| BRANDENBURG, B | 8303020046 | 50-247 | Q |
| BRANDENBURG, B | 8303020052* | 50-247 | Q |
| BRANDENBURG, B | 8303070110 | 50-247 | Q |
| BRANDENBURG, B | 8303070125 | 50-247 | Q |
| BRANDENBURG, B | 8303070134 | 50-247 | Q |
| BRANDENBURG, B | 8303080109 | 50-247 | Q |
| BRANDENBURG, B | 8303100271 | 50-247 | Q |
| BRANDENBURG, B | 8303100277 | 50-247 | Q |
| BRANDENBURG, B | 8303150393 | 50-247 | Q |
| BRANDENBURG, B | 8303170279 | 50-247 | Q |
| BRANDENBURG, B | 8303180277 | 50-247 | Q |
| BRANDENBURG, B | 8303220231 | 50-247 | Q |
| BRANDENBURG, B | 8303220261 | 50-247 | Q |
| BRANDENBURG, B | 8303230176 | 50-247 | Q |
| BRANDENBURG, B | 8303310303 | 50-247 | Q |
| BRANSCOME, J. M | 8303170050 | 40-8584 | |
| BREAUX, D. G | 8303070085* | GA999 | |
| BREDES, N | 8303010408 | 50-322 | Q |
| BREEN, J | 8303310325 | 50-329 | Q |
| BRENNER, L | 8303020032 | 50-322 | Q |
| BRENNER, L | 8303020084 | 50-322 | Q |
| BRENNER, L | 8303080159 | 50-322 | Q |
| BRENNER, L | 8303090309 | 50-352 | Q |
| BRENNER, L | 8303100357 | 50-352 | Q |
| BRENNER, L | 8303140254 | 50-322 | Q |
| BRENNER, L | 8303140265 | 50-352 | Q |
| BRENNER, L | 8303170485 | 50-201 | Q |
| BRENNER, L | 8303220249 | 50-352 | Q |
| BRENNER, L | 8303230198 | 50-352 | Q |
| BRESEMANN, R. W | 8303070135 | 50-10 | I |
| BREY, H. L | 8303210641 | 50-267 | R |
| BREY, H. L | 8303210664 | 50-267 | P |
| BRICKLEY, R. H | 8303070005* | GA999 | |
| BRICKLEY, R. H | 8303240556* | 50-282 | Q |
| BRIDEN, D. W | 8303250124* | 50-346 | F |
| BRIDENBECKER, R | 8303240214 | 50-206 | F |
| BRIGGS, H. J | 8303180062* | CONTRACT | |
| BRIGGS, L | 8303240461* | 50-213 | Q |
| BRIGGS, L | 8303300203* | 50-275 | Q |
| BRIGHT, G. O | 8303010131 | 50-483 | Q |
| BRIGHT, G. O | 8303070211 | 50-440 | Q |
| BRIGHT, G. O | 8303140279 | 50-400 | Q |
| BRIGHT, G. O | 8303170498 | 50-460 | Q |
| BRIGHT, G. O | 8303290501 | 50-400 | Q |
| BRIGHT, G. O | 8303310286 | 50-440 | Q |
| BRINKMAN, D. S | 8303030703 | 50-250 | F |
| BRINKMAN, D. S | 8303160093 | PP | |
| BRISBEE, G. D | 8303140322 | 50-443 | Q |
| BRISBEE, G. D | 8303140327* | 50-443 | Q |
| BRISTOR, P | 8303020266 | NUREG | |
| BRITE, D. W | 8303100416 | NUREG | |
| BROBST, G. E | 8303140199* | 50-317 | S |
| BROCK, B. L | 8303240577* | 70-25 | |
| BROEHL, D. J | 8303010588 | 50-344 | Q |
| BROMBERG, B | 8303030377 | CONTRACT | |
| BROMBERG, B | 8303030714 | CONTRACT | |
| BROMBERG, B | 8303290794 | CONTRACT | |
| BRONS, J. C | 8303150532 | 50-286 | R |
| BRONS, J. C | 8303160247 | 50-286 | Q |
| BRONS, J. C | 8303160374 | 50-286 | R |
| BRONS, J. C | 8303250055 | 50-286 | R |
| BROOKS, D. J | 8303290780 | WASTE MGT | |
| BROOKS, E | 8303210459* | 50-389 | Q |
| BROUNS, R. J | 8303100416 | NUREG | |
| BROWN, A | 8303280083 | WASTE MGT | |
| BROWN, C. H | 8303080042* | 50-263 | Q |
| BROWN, C. H | 8303170495* | 50-263 | Q |
| BROWN, F. L | 8303250161 | 50-329 | Q |
| BROWN, G. D | 8303150219* | 50-382 | Q |
| BROWN, G. D | 8303180233 | 40-8752 | |
| BROWN, G. D | 8303180239 | 40-6659 | |
| BROWN, G. D | 8303210435 | 40-299 | |
| BROWN, G. R | 8303090137 | TOPREP | |
| BROWN, H. H | 8303080054 | 50-322 | Q |
| BROWN, H. H | 8303080054 | 50-322 | Q |
| BROWN, H. H | 8303290190 | 50-322 | Q |
| BROWN, H. H | 8303290190 | 50-322 | Q |
| BROWN, H. H | 8303310224 | 50-322 | Q |
| BROWN, H. H | 8303310224 | 50-322 | Q |
| BROWN, K. J | 8303090017 | 40-8745 | |
| BROWN, R. C | 8303180243* | 40-6659 | |
| BROWN, R. L | 8303010249* | 50-458 | Q |
| BROWN, R. S | 8303100403* | FOIA | |
| BROWN, R. S | 8303100431* | FOIA | |
| BROWN, R. S | 8303100438* | FOIA | |
| BROWN, R. S | 8303100448* | FOIA | |
| BROWN, R. S | 8303100456* | FOIA | |
| BROWN, R. S | 8303100458* | FOIA | |
| BROWN, R. S | 8303100464* | FOIA | |
| BROWN, S | 8303150023 | 50-213 | P |
| BROWN, W. R | 8303030370* | CONTRACT | |
| BROWNING, R | 8303180071 | WASTE MGT | |
| BROWNING, R. E | 8303010035 | WASTE MGT | |
| BROWNING, R. E | 8303170242 | WASTE MGT | |
| BROWNING, R. E | 8303180074 | WASTE MGT | |
| BROWNING, R. E | 8303180081* | WASTE MGT | |
| BROWNING, R. E | 8303180635 | WASTE MGT | |
| BROWNLEE, V. L | 8303210589* | 50-424 | Q |
| BROWNLEE, V. L | 8303210684* | 50-424 | Q |
| BROWNLEE, V. L | 8303210745* | 50-395 | Q |
| BROWNLEE, V. L | 8303220063 | 50-395 | S |
| BRUNNER, E. J | 8303020103 | 50-293 | R |
| BRUNNER, J. E | 8303010077 | 50-329 | Q |
| BRUNNER, J. E | 8303290455 | 50-329 | Q |
| BRUSH, P. N | 8303150689 | XPORTLIC | |
| BRUSVEN, A. D | 8303280039 | 50-263 | I |
| BRUSVEN, A. D | 8303300123 | 50-263 | I |
| BRYAN, R. H | 8303290673 | NUREG | |
| BRYAN, R. H | 8303300638 | NUREG | |
| BRYANT, J. L | 8303100416 | NUREG | |
| BRYSON, J. W | 8303300511 | NUREG | |
| BUCCI, D | 8303160648 | ACRS | |
| BUCHANAN, C. R | 8303310102* | FOIA | |
| BUCHANAN, C. R | 8303310104* | FOIA | |
| BUCHANAN, C. R | 8303310111* | FOIA | |
| BUCHANAN, C. R | 8303310116* | FOIA | |
| BUCHANAN, C. R | 8303310119* | FOIA | |
| BUCHANAN, C. R | 8303310128* | FOIA | |
| BUCHANAN, C. R | 8303310131* | FOIA | |
| BUCHANAN, C. R | 8303310137* | FOIA | |
| BUCHANAN, C. R | 8303310141* | FOIA | |
| BUCHANAN, C. R | 8303310144* | FOIA | |
| BUCHANAN, C. R | 8303310150* | FOIA | |
| BUCKLEY, P | 8302250060* | 50-275 | Q |
| BUEHRING, W. A | 8303300628 | NUREG | |
| BUFE, J | 8303010269* | 50-302 | S |
| BUFE, J | 8303160383* | 50-302 | S |
| BUFE, J | 8303180199* | 50-302 | S |
| BUFE, J. L | 8303180260* | 50-302 | S |
| BULLINGTON, P. L | 8303010018* | CONTRACT | |
| BUNTING, J. O | 8303310038 | WASTE MGT | |
| BUONOCORE, J. A | 8303040106 | XPORTLIC | |
| BURDOIN, J. F | 8302290271* | 50-275 | Q |
| BURGER, F. J | 8303160367* | 50-271 | R |
| BURGESS, B. L | 8303110366* | 50-329 | Q |
| BURGMEIER, M. J | 8303010676* | 50-220 | S |
| BURGMEIER, M. J | 8303180416* | 50-220 | S |
| BURKE, D. J | 8303010645* | 50-280 | Q |
| BURKE, D. J | 8303010673* | 50-280 | Q |
| BURKE, D. J | 8303210346* | 50-280 | Q |
| BURKE, R. P | 8303290689 | NUREG | |
| BURKHARDT, W | 8303100418* | 70-364 | |
| BURKHARDT, W | 8303160707* | 70-1193 | |
| BURNETT, P. T | 8303210391* | 50-416 | Q |
| BURNETT, P. T | 8303210491* | 50-395 | Q |
| BURNETT, P. T | 8303210646* | 50-369 | Q |
| BURNETT, R. F | 8303100469* | FOIA | |
| BURNETT, R. F | 8303150022 | 70-1100 | |
| BURNETT, R. F | 8303150041 | 70-36 | |
| BURNETT, R. F | 8303150050 | 70-1201 | |
| BURNETT, R. F | 8303150054 | 70-1201 | |
| BURNETT, R. F | 8303150060 | 70-25 | |
| BURNETT, R. F | 8303150066 | 70-135 | |
| BURNETT, R. F | 8303150076 | 70-1113 | |
| BURNETT, R. F | 8303150087 | 70-27 | |
| BURNETT, R. F | 8303150094 | 70-143 | |
| BURNETT, R. F | 8303160628 | 70-135 | |
| BURNETT, R. F | 8303170276 | 70-135 | |
| BURNS, S. G | 8303170016 | PR | |
| BURWELL, S | 8303310256* | 50-445 | T |
| BURWELL, S. B | 8303040633* | 50-445 | Q |
| BURWELL, S. B | 8303230381 | 50-445 | A |
| BURWELL, S. B | 8303240116 | 50-445 | A |
| BURWELL, S. B | 8303240121 | 50-445 | A |
| BURWELL, S. B | 8303270661 | 50-445 | A |
| BUSH, S. H | 8303090026* | FOIA | |
| BUSHKIN, K. P | 8303240012 | 50-361 | P |
| BUSS, R. D | 83031 0391* | 50-254 | R |
| BUSSO, L. F | 8303210715* | 50-318 | S |
| BUTCHER, R. C | 8303010590* | 50-416 | Q |
| BUTCHER, R. C | 8303240502 | 50-348 | S |
| BUTCHER, R. C | 8303240561 | 50-395 | S |
| BUTLER, D. K | 8303210016 | WASTE MGT | |
| BUTLER, S. D | 8303010523* | 50-327 | Q |
| BUTLER, T | 8303090520 | NUREG | |
| BYRD, R | 8303010201* | 50-416 | S |
| BYRD, R | 8303040508* | 50-416 | S |
| BYRD, R | 8303040626* | 50-416 | S |
| BYRD, R | 8303150183* | 50-416 | S |
| BYRD, R | 8303160310* | 50-416 | S |
| BYRD, R | 8303160403* | 50-416 | S |
| BYRD, R | 8303160254* | 50-416 | S |
| BYRD, R. W | 8303140404* | 50-416 | S |
| BYRNE, J | 8303280097 | NUREG | |
| BYRNE, J | 8303280114 | NUREG | |
| CAHILL, W. J | 8303030411 | 50-458 | C |
| CAHILL, W. J | 8303100155 | 50-458 | F |
| CAIN, J | 8303090036 | WASTE MGT | |
| CAIN, J | 8303090147 | WASTE MGT | |
| CAIN, J | 8303220412 | WASTE MGT | |
| CAIN, J | 8303240103 | WASTE MGT | |
| CAIN, J | 8303300050 | WASTE MGT | |
| CALDWELL, R. A | 8303150455* | 50-267 | Q |
| CALLAN, L. J | 8303150328 | 50-368 | S |
| CALLAN, L. J | 8303210562* | 50-313 | Q |
| CALLAN, L. J | 8303280122 | 50-313 | S |
| CAMPBELL, B | 8303230197 | FOIA | |
| CAMPBELL, M | 8303280125 | I&E | |
| CAMPBELL, M | 8303280318* | I&E | |
| CAMPBELL, M | 8303280326* | I&E | |
| CAMPBELL, M | 8303280330* | I&E | |
| CAMPBELL, M | 8303280340* | I&E | |
| CAMPBELL, M. A | 8303230035* | I&E | |
| CAMPBELL, R. K | 8303210333* | 50-387 | I |
| CAMPBELL, W. C | 8303280314 | TOPREF | |
| CAMPBELL, W. E | 8303090594 | TOPREP | |
| CAMPE, K. M | 8303090036* | FOIA | |
| CANNEY, C. A | 8303290432 | 50-443 | Q |
| CANTER, H. L | 8303080489* | 50-313 | Q |
| CANTRELL, F. S | 8303010221* | 50-348 | Q |
| CANTRELL, F. S | 8303010437* | 50-348 | Q |
| CANTRELL, F. S | 8303010590* | 50-416 | Q |
| CANTRELL, F. S | 8303210436* | 50-348 | Q |
| CANTRELL, F. S | 8303210752* | 50-416 | Q |
| CANTRELL, F. S | 8303210775* | 50-259 | Q |
| CANTRELL, F. S | 8303240502 | 50-348 | S |
| CANTRELL, F. S | 8303240561 | 50-395 | S |
| CANTRELL, W. A | 8303160417* | 50-324 | P |
| CANTWELL, P. F | 8303150355* | 50-295 | S |
| CANTWELL, P. F | 8303140360* | 50-295 | S |
| CANTWELL, P. F | 8303140470* | 50-295 | S |
| CANTWELL, P. F | 8303240212* | 50-304 | S |
| CAPHTON, D. L | 8303090444 | 50-220 | Q |
| CAPHTON, D. L | 8303160431* | 50-272 | Q |
| CAPHTON, D. L | 8303240373* | 50-213 | Q |
| CAPHTON, D. L | 8303290346* | 50-247 | Q |
| CAPONE, D. W | 8303150276 | 50-483 | V |
| CARAVASSI, M | 8303030378 | 50-322 | H |
| CAREW, J. F | 8303030330* | TOPREP | |
| CAREW, J. F | 8303030341* | TOPREP | |
| CAREW, J. F | 8303090481* | TOPREP | |
| CAREW, J. F | 8303090627 | RES | |
| CAREY, J. J | 8303040564 | 50-334 | P |
| CAREY, J. J | 8303080246 | 50-334 | R |
| CAREY, J. J | 8303080291 | 50-334 | P |
| CAREY, J. J | 8303080381 | 50-334 | R |
| CAREY, J. J | 8303080447 | 50-334 | V |
| CAREY, J. J | 8303100196 | 50-334 | Q |
| CAREY, J. J | 8303110212 | 50-334 | F |
| CAREY, J. J | 8303110383 | 50-334 | F |
| CAREY, J. J | 8303150335 | 50-334 | R |
| CAREY, J. J | 8303150572 | 50-334 | R |
| CAREY, J. J | 8303240094 | 50-334 | P |
| CAREY, J. J | 8303290008 | 50-334 | P |
| CAREY, J. J | 8303290473 | 50-334 | P |
| CAREY, J. J | 8303310246 | 50-334 | P |
| CARFAGNO, S | 8301170075* | 50-346 | P |
| CARLEY, C. T | 8303170258 | 50-241 | J |
| CARLSON, J | 8303290590* | 50-361 | Q |
| CARLSON, J. D | 8303040421* | 50-275 | Q |
| CARNEY, G | 8303140447* | 50-254 | S |
| CARPENTER, F. D | 8303310039 | 50-382 | A |
| CARPENTER, J. H | 8303140279 | 50-400 | Q |
| CARPENTER, T. G | 8303290185* | CONTRACT | |
| CARPENTER, T. G | 8303310143* | CONTRACT | |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| CARR, A. V. | 8303040534 | 50-413 Q |
| CARR, A. V. | 8303040534 | 50-413 Q |
| CARR, A. V. | 8303110214 | 50-413 Q |
| CARR, A. V. | 8303230242 | 50-413 Q |
| CARR, A. V. | 8303250146 | 50-413 Q |
| CARR, A. V. | 8303290217 | 50-269 P |
| CARR, S. E. | 8303290196* | CONTRACT |
| CARR, S. E. | 8303290608* | CONTRACT |
| CARROW, B. B. | 8303110213 | 50-400 Q |
| CARSON, J. E. | 8303020006* | 50-329 T |
| CARSON, J. E. | 8303020006* | 50-329 T |
| CARTEAUX, P. | 8303080087* | 50-315 S |
| CARTEAUX, P. | 8303080113* | 50-315 S |
| CARTEAUX, P. | 8303080384* | 50-315 S |
| CARTEAUX, P. | 8303080314* | 50-316 S |
| CARTEAUX, P. | 8303140377* | 50-315 S |
| CARTEAUX, P. | 8303140525* | 50-316 S |
| CARTER, R. E. | 8303160012 | 50-146 H |
| CARTER, R. E. | 8303240200 | 50-131 P |
| CARTER, R. E. | 8303310089 | COMMISSION |
| CARTER, R. S. | 8303310243 | 50-184 R |
| CARTER, R. S. | 8303310245* | 50-184 R |
| CARTER, S. | 8303210434* | 50-259 S |
| CARTER, S. D. | 8303150306* | 50-259 S |
| CARTER, S. D. | 8303220179* | 50-259 S |
| CARTER, S. D. | 8303220324* | 50-260 S |
| CARTWRIGHT, W. | 8302150454 | 50-339 S |
| CARTWRIGHT, W. R. | 8302150458* | 50-339 S |
| CARTWRIGHT, W. R. | 8302230312 | 50-338 S |
| CARTWRIGHT, W. R. | 8303230319* | 50-338 S |
| CARTWRIGHT, W. R. | 8303010335 | 50-339 S |
| CARTWRIGHT, W. R. | 8303210446* | 50-339 S |
| CARTWRIGHT, W. R. | 8303210594 | 50-339 S |
| CARTWRIGHT, W. R. | 8303010602* | 50-339 S |
| CARTWRIGHT, W. R. | 8303150217 | 50-338 S |
| CARTWRIGHT, W. R. | 8303150226* | 50-338 S |
| CARTWRIGHT, W. R. | 8303180963 | 50-338 S |
| CARTWRIGHT, W. R. | 8303180630* | 50-338 S |
| CARTWRIGHT, W. R. | 8303180242 | 50-339 S |
| CARTWRIGHT, W. R. | 8303180351* | 50-339 S |
| CARTWRIGHT, W. R. | 8303210456 | 50-339 S |
| CARTWRIGHT, W. R. | 8303210465* | 50-339 S |
| CARTWRIGHT, W. R. | 8303210489 | 50-339 S |
| CARTWRIGHT, W. R. | 8303210493* | 50-339 S |
| CARUSO, R. | 8303040248 | 50-322 A |
| CARUSO, R. | 8303090667* | 50-29 P |
| CARUSO, R. | 8303090697* | 50-29 P |
| CARUSO, R. | 8303230401 | 50-322 A |
| CARUSO, R. | 8303280297 | 50-322 A |
| CARVER, A. M. | 8303210307* | 50-328 S |
| CASE, E. G. | 8303150161* | 50-293 Q |
| CASE, F. | 8303170624 | NUREG |
| CASE, J. M. | 8303010426 | TOPREP |
| CASE, J. M. | 8303020065* | TOPREP |
| CASSIDONI, R. D. | 8303020222* | 70-364 |
| CASTAGNO, J. G. | 8303160276* | 50-250 P |
| CASTAGNO, J. G. | 8303160282* | 50-250 P |
| CASTAGNO, J. G. | 8303160373* | 50-335 P |
| CASTAGNO, J. G. | 8303160379* | 50-335 P |
| CASTRO, G. | 8303280354* | CONTRACT |
| CATCHPOLE, G. J. | 8303090589 | 40-8745 |
| CATCHPOLE, G. J. | 8303290555 | 40-8745 |
| CATTON, I. | 8302080455 | ACRS |
| CAUSEY, J. C. | 8303070001 | 50-366 P |
| CAVANAUGH, W. | 8303110240 | 50-313 H |
| CEJA, S. | 8303180016 | XPORTLIC |
| CELENTANO, C. | 8303090334 | FOIA |
| CELLARS, K. B. | 8303160153* | 50-318 S |
| CERNE, A. C. | 8302180224* | 50-443 Q |
| CHACKES, K. M. | 8303070118 | 50-483 Q |
| CHACKES, K. M. | 8303070118 | 50-483 Q |
| CHAFFEE, A. | 8303290590* | 50-361 Q |
| CHAFFEE, A. E. | 8303290462* | 50-206 Q |
| CHAN, E. I. | 8303010375 | 50-352 Q |
| CHAN, E. I. | 8303140045 | 50-556 Q |
| CHAN, E. I. | 8303140071 | 50-556 Q |
| CHAN, E. I. | 8303170020 | 50-352 Q |
| CHANDLER, J. C. | 8303220114 | TOPREP |
| CHANDLER, J. C. | 8303300376 | TOPREP |
| CHANDLER, L. J. | 8303030462 | 50-275 Q |
| CHANDRA, U. | 8303070120* | 50-537 A |
| CHANEY, H. | 8303180244* | 50-285 Q |
| CHANEY, H. D. | 8303180357* | 50-482 Q |
| CHANG, K. C. | 8303110324* | 50-244 P |
| CHANG, K. C. | 8303300095 | WASTE MGT |
| CHAPLIN, S. D. | 8303250076* | 50-320 S |
| CHAPMAN, R. H. | 8303170616 | NUREG |
| CHARNLEY, J. S. | 8303020009 | TOPREP |
| CHARNLEY, J. S. | 8303160580 | TOPREP |
| CHARNOFF, G. | 8303010070* | 40-2061 |
| CHATTERTON, R. B. | 8303290531 | 50-327 Q |
| CHAUDHARY, S. K. | 8303240380* | 50-352 Q |
| CHEN, S. Y. | 8212020263* | 50-29 P |
| CHEN, W. P. | 8303310256* | 50-445 T |
| CHENG, H. S. | 8303160183 | RES |
| CHIANGI, N. J. | 8303160522 | 50-400 S |
| CHIANGI, N. J. | 8303240526 | 50-400 S |
| CHILK, S. J. | 8205240601* | FOIA |
| CHILK, S. J. | 8207050037* | 50-275 P |
| CHILK, S. J. | 8301270005* | FOIA |
| CHILK, S. J. | 8303010151 | 50-247 Q |
| CHILK, S. J. | 8303010236 | 50-395 Q |
| CHILK, S. J. | 8303010248 | 50-341 Q |
| CHILK, S. J. | 8303010259 | 50-341 Q |
| CHILK, S. J. | 8303010302 | 50-352 Q |
| CHILK, S. J. | 8303010305 | 50-289 Q |
| CHILK, S. J. | 8303010709 | 50-275 T |
| CHILK, S. J. | 8303020070 | 50-352 Q |
| CHILK, S. J. | 8303020192 | FOIA |
| CHILK, S. J. | 8303030361 | 50-395 Q |
| CHILK, S. J. | 8303040345 | 10CFR |
| CHILK, S. J. | 8303080214 | 50-289 Q |
| CHILK, S. J. | 8303080462 | 50-445 Q |
| CHILK, S. J. | 8303080471 | 50-289 Q |
| CHILK, S. J. | 8303090698 | FOIA |
| CHILK, S. J. | 8303090228 | FOIA |
| CHILK, S. J. | 8303090400* | FOIA |
| CHILK, S. J. | 8303100025 | 10CFR |
| CHILK, S. J. | 8303100031* | FOIA |
| CHILK, S. J. | 8303100204 | 50-329 Q |
| CHILK, S. J. | 8303100381 | 50-382 Q |
| CHILK, S. J. | 8303100385 | 50-358 Q |
| CHILK, S. J. | 8303100387 | 50-373 Q |
| CHILK, S. J. | 8303110128 | 50-272 S |
| CHILK, S. J. | 8303110135 | 10CFR |
| CHILK, S. J. | 8303110205 | 50-309 Q |
| CHILK, S. J. | 8303110228 | 50-259 Q |
| CHILK, S. J. | 8303110233 | 50-341 Q |
| CHILK, S. J. | 8303110235 | 50-341 Q |
| CHILK, S. J. | 8303140260 | 50-289 Q |
| CHILK, S. J. | 8303140697 | 10CFR |
| CHILK, S. J. | 8303140700 | 50-289 Q |
| CHILK, S. J. | 8303140702 | 10CFR |
| CHILK, S. J. | 8303170443 | 50-522 Q |
| CHILK, S. J. | 8303180599 | 10CFR |
| CHILK, S. J. | 8303180627* | COMMISSION |
| CHILK, S. J. | 8303220365 | 70-143 |
| CHILK, S. J. | 8303230187* | FOIA |
| CHILK, S. J. | 8303230190* | FOIA |
| CHILK, S. J. | 8303230204 | 50-289 Q |
| CHILK, S. J. | 8303290502 | 50-537 Q |
| CHILK, S. J. | 8303300275 | 50-498 Q |
| CHILK, S. J. | 8303300279 | 40-2061 |
| CHILK, S. J. | 8303300283 | 50-528 Q |
| CHILK, S. J. | 8303300362 | 50-295 Q |
| CHILK, S. J. | 8303300641* | FOIA |
| CHILK, S. J. | 8303300688* | FOIA |
| CHILK, S. J. | 8303300693* | FOIA |
| CHILK, S. J. | 8303310463* | FOIA |
| CHITWOOD, R. B. | 8303240046* | 70-1193 |
| CHITWOOD, R. B. | 8303310236* | FOIA |
| CHITWOOD, R. B. | 8303310240* | FOIA |
| CHITWOOD, R. B. | 8303310257* | FOIA |
| CHOKSHI, N. | 8303020040* | 50-206 P |
| CHOW, H. | 8303240144 | RES |
| CHRISSOTIMOS, N. | 8303170551* | 50-254 Q |
| CHRISSOTIMOS, N. | 8303240372* | 50-237 Q |
| CHRISSOTIMOS, N. | 8303240597* | 50-10 Q |
| CHRISTENBURY, E. | 8303030459 | 50-546 Q |
| CHRISTENSEN, D. | 8303220407 | NUREG |
| CHRISTMAN, J. N. | 8302100345 | PRM |
| CHRISTMAN, J. N. | 8303300138 | 50-280 P |
| CHRISTMAN, J. N. | 8303300551* | 50-322 Q |
| CHRISTMAN, J. N. | 8303300551* | 50-322 Q |
| CHRISTMAN, J. N. | 8303300562* | 50-322 Q |
| CHRISTMAN, J. N. | 8303300562* | 50-322 Q |
| CHRISTOFFER, G. | 8303170459* | 50-266 Q |
| CHRISTOPHER, R. | 8303030359* | 50-410 Q |
| CHRISTOPHER, R. | 8303040473* | 50-245 Q |
| CHRISTOPHER, R. | 8303110096* | 50-272 S |
| CHRISTOPHER, W. | 8303040569* | 50-259 S |
| CHU, A. | 8303280233* | 50-397 S |
| CHUNG, J. W. | 8303240363* | 50-387 Q |
| CHURCHILL, B. W. | 8303170423 | 50-382 Q |
| CHURCHILL, B. W. | 8303170423 | 50-382 Q |
| CHURCHILL, B. W. | 8303170427* | 50-382 Q |
| CHURCHILL, B. W. | 8303170427* | 50-382 Q |
| CHURCHILL, B. W. | 8303220238 | 50-382 Q |
| CHURCHILL, B. W. | 8303220238 | 50-382 Q |
| CHURCHILL, B. W. | 8303220280 | 50-382 T |
| CHURCHILL, B. W. | 8303220280 | 50-382 T |
| CHURCHILL, B. W. | 8303290464 | 50-382 Q |
| CHURCHILL, B. W. | 8303290464 | 50-382 Q |
| CILIMBERG, R. L. | 8303240517* | 50-440 Q |
| CILLIS, M. | 8303290463* | 50-344 Q |
| CINTULA, T. C. | 8303290097 | 50-317 S |
| CLAPP, N. E. | 8303160009 | NUREG |
| CLARDY, L. S. | 8303080411* | 50-331 Q |
| CLARK, A. T. | 8303180342 | 50-201 P |
| CLARK, D. | 8303240547* | 50-254 S |
| CLARK, D. | 8303310089 | COMMISSION |
| CLARK, D. E. | 8303180169 | 40-8102 |
| CLARK, J. R. | 8303160423* | 50-260 S |
| CLARK, L. | 8303100490* | 50-20 P |
| CLARK, L. | 8303280003 | 50-20 P |
| CLARK, R. A. | 8303090185 | 50-336 S |
| CLARK, R. A. | 8303090221 | 50-335 P |
| CLARK, R. A. | 8303090359 | 50-389 P |
| CLARK, R. A. | 8303090328 | 50-317 P |
| CLARK, R. A. | 8303090260 | 50-266 P |
| CLARK, R. A. | 8303090265 | 50-282 P |
| CLARK, R. A. | 8303090402* | 50-265 P |
| CLARK, R. A. | 8303090409* | 50-389 P |
| CLARK, R. A. | 8303090424 | 50-317 P |
| CLARK, R. A. | 8303090434* | 50-317 P |
| CLARK, R. A. | 8303090447* | 50-317 P |
| CLARK, R. A. | 8303110454* | 50-289 P |
| CLARK, R. A. | 8303110540* | 50-289 P |
| CLARK, R. A. | 8303140082* | 50-282 P |
| CLARK, R. A. | 8303140112 | 50-266 P |
| CLARK, R. A. | 8303140115* | 50-282 P |
| CLARK, R. A. | 8303140609 | 50-335 P |
| CLARK, R. A. | 8303150367 | 50-389 P |
| CLARK, R. A. | 8303150665 | 50-295 P |
| CLARK, R. A. | 8303150703 | 50-282 P |
| CLARK, R. A. | 8303160011 | 50-335 P |
| CLARK, R. A. | 8303160026 | 50-285 P |
| CLARK, R. A. | 8303160051 | 50-313 P |
| CLARK, R. A. | 8303160643 | 50-309 P |
| CLARK, R. A. | 8303220436 | 50-344 P |
| CLARK, R. A. | 8303220467 | 50-285 P |
| CLARK, R. A. | 8303220488 | 50-309 P |
| CLARK, R. A. | 8303230061 | 50-335 P |
| CLARK, R. A. | 8303230071 | 50-266 P |
| CLARK, R. A. | 8303230098 | 50-336 P |
| CLARK, R. A. | 8303230150 | 50-282 P |
| CLARK, R. A. | 8303230231 | 50-266 P |
| CLARK, R. A. | 8303230421 | 50-245 P |
| CLARK, R. A. | 8303230429* | 50-245 P |
| CLARK, R. A. | 8303230435* | 50-245 P |
| CLARK, R. A. | 8303240015 | 50-336 P |
| CLARK, R. A. | 8303240020 | 50-285 P |
| CLARK, R. A. | 8303240038* | 50-336 P |
| CLARK, R. A. | 8303240042* | 50-336 P |
| CLARK, R. A. | 8303240067 | 50-313 P |
| CLARK, R. A. | 8303240068 | 50-344 P |
| CLARK, R. A. | 8303240073* | 50-313 P |
| CLARK, R. A. | 8303240080* | 50-313 P |
| CLARK, R. A. | 8303240082 | 50-344 P |
| CLARK, R. A. | 8303240086 | 50-266 S |
| CLARK, R. A. | 8303240315 | 50-285 P |
| CLARK, R. A. | 8303240323* | 50-285 P |
| CLARK, R. A. | 8303240333* | 50-285 P |
| CLARK, R. A. | 8303240350 | 50-266 P |
| CLARK, R. A. | 8303240353* | 50-266 P |
| CLARK, R. A. | 8303240361* | 50-266 P |
| CLARK, R. A. | 8303240395 | 50-338 F |
| CLARK, R. A. | 8303280357 | 50-317 F |
| CLARK, R. A. | 8303290049 | 50-368 P |
| CLARK, R. A. | 8303290646 | 50-338 P |
| CLARK, R. A. | 8303300037 | 50-309 P |
| CLARK, R. A. | 8303300065 | 50-317 F |
| CLARK, R. A. | 8303300110 | 50-317 P |
| CLARK, R. A. | 8303300151* | 50-285 P |
| CLARK, R. A. | 8303300166* | 50-285 P |

# PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| CLARK, R. A. | 8303300207* | 50-309 P |
| CLARK, R. A. | 8303300209* | 50-309 P |
| CLARK, R. A. | 8303300253 | 50-336 P |
| CLARK, R. A. | 8303300256* | 50-336 P |
| CLARK, R. A. | 8303300266* | 50-336 P |
| CLARK, R. A. | 8303300388* | 50-344 P |
| CLARK, R. A. | 8303300393* | 50-344 P |
| CLARK, R. A. | 8303300419 | 50-338 P |
| CLARK, R. A. | 8303300584 | 50-338 P |
| CLARK, R. A. | 8303310673 | 50-285 P |
| CLARK, R. J. | 8303300219 | 50-259 P |
| CLARK, W. G. | 8303010287 | MISC |
| CLAY, E. L. | 8303210369* | 70-1151 |
| CLAYTON, F. L. | 8302070360 | 50-348 P |
| CLAYTON, F. L. | 8303010209* | 50-348 G |
| CLAYTON, F. L. | 8303010506 | 50-348 V |
| CLAYTON, F. L. | 8303020027 | 50-364 G |
| CLAYTON, F. L. | 8303040318 | 50-348 S |
| CLAYTON, F. L. | 8303040329 | 50-348 S |
| CLAYTON, F. L. | 8303080242 | 50-348 P |
| CLAYTON, F. L. | 8303080480 | 50-348 P |
| CLAYTON, F. L. | 8303080512 | 50-348 P |
| CLAYTON, F. L. | 8303080517 | 50-348 P |
| CLAYTON, F. L. | 8303090312 | 50-348 G |
| CLAYTON, F. L. | 8303090341 | 50-348 R |
| CLAYTON, F. L. | 8303090375* | 50-348 F |
| CLAYTON, F. L. | 8303110102 | 50-348 F |
| CLAYTON, F. L. | 8303110370 | 70-2920 |
| CLAYTON, F. L. | 8303140312 | 50-348 P |
| CLAYTON, F. L. | 8303140376 | 50-348 P |
| CLAYTON, F. L. | 8303140491 | 50-348 F |
| CLAYTON, F. L. | 8303140559 | 50-348 F |
| CLAYTON, F. L. | 8303150436 | 50-348 F |
| CLAYTON, F. L. | 8303170531 | 50-348 G |
| CLAYTON, F. L. | 8303180378 | 50-348 S |
| CLAYTON, F. L. | 8303210377 | 50-348 S |
| CLAYTON, F. L. | 8303210460 | 50-364 S |
| CLAYTON, F. L. | 8303210548* | 50-348 G |
| CLAYTON, F. L. | 8303230227 | 50-348 P |
| CLAYTON, F. L. | 8303230247 | 50-364 P |
| CLAYTON, F. L. | 8303290354 | 50-348 G |
| CLAYTON, F. L. | 8303300206 | 50-364 P |
| CLAYTON, O. J. | 8303210346 | 50-267 S |
| CLAYTON, O. J. | 8303210629 | 50-267 S |
| CLEMENTS, R. | 8303210652* | 50-361 P |
| CLEMONS, P. | 8303030202* | 50-334 G |
| CLEMONS, P. | 8303030312* | 50-256 G |
| CLEMONS, P. | 8303100177* | 50-309 G |
| CLEMONS, P. | 8303140229* | 50-213 G |
| CLEMONS, P. | 8303240449* | 50-213 G |
| CLEMONS, P. | 8303240535* | 50-272 G |
| CLEMONS, P. | 8303300455* | 50-247 G |
| CLEVELAND, J. C. | 8303160009 | NUREG |
| CLIFT, R. L. | 8303210680* | 50-361 P |
| CLINE, W. E. | 8303010459* | 70-143 |
| CLINE, W. E. | 8303210695* | 50-416 G |
| COBB, A. B. | 8303300683* | CONTRACT |
| COCHRAN, T. B. | 8303010296 | 70-143 |
| COCHRAN, T. B. | 8303030422 | 70-143 |
| COCKRELL, R. G. | 8303310396 | 50-111 W |
| CODDINGTON, C. T. | 8302280091 | 50-387 P |
| CODELL, R. | 8303010309* | 50-454 T |
| COFFMAN, F. D. | 8303110227 | 50-322 T |
| COHEN, I. | 8303280283* | 50-277 G |
| COHEN, L. | 8303290694 | NUREG |
| COHN, B. M. | 8303150663* | CONTRACT |
| COHN, B. M. | 8303230167* | CONTRACT |
| COHN, B. M. | 8303230175* | CONTRACT |
| COHN, B. M. | 8303230182* | CONTRACT |
| COHN, B. M. | 8303280339* | CONTRACT |
| COHN, B. M. | 8303290765* | CONTRACT |
| COLARULLI, P. F. | 8303070125 | 50-247 G |
| COLARULLI, P. F. | 8303070125 | 50-247 G |
| COLARULLI, P. F. | 8303070134 | 50-247 G |
| COLARULLI, P. F. | 8303070134 | 50-247 G |
| COLARULLI, P. F. | 8303100277 | 50-247 G |
| COLARULLI, P. F. | 8303100277 | 50-247 G |
| COLARULLI, P. F. | 8303220261 | 50-247 G |
| COLARULLI, P. F. | 8303220261 | 50-247 G |
| COLBURN, T. G. | 8303160252 | TOPREP |
| COLBURN, T. G. | 8303240001 | 50-266 F |
| COLE, R. F. | 8303090309 | 50-352 G |
| COLEMAN, R. J. | 8303110301* | 50-282 G |
| COLLINGS, M. D. | 8201270341* | FOIA |
| COLLINGS, M. P. | 8303240148* | FOIA |
| COLLINS, D. J. | 8303010440* | 50-219 G |
| COLLINS, D. J. | 8303160508* | 50-333 G |
| COLLINS, D. J. | 8303290319* | 50-334 G |
| COLLINS, F. R. | 8303110116 | 71-86 |
| COLLINS, J. T. | 8303010411 | 50-267 F |
| COLLINS, J. T. | 8303010412 | 50-298 F |
| COLLINS, J. T. | 8303010413 | 50-285 F |
| COLLINS, J. T. | 8303010641 | 50-313 F |
| COLLINS, J. T. | 8303030679 | 40-8698 |
| COLLINS, J. T. | 8303030687* | 40-8698 |
| COLLINS, J. T. | 8303080015 | 40-8681 |
| COLLINS, J. T. | 8303080020* | 40-8681 |
| COLLINS, J. T. | 8303080085 | 50-458 G |
| COLLINS, J. T. | 8303080320 | 50-267 P |
| COLLINS, J. T. | 8303090006* | FOIA |
| COLLINS, J. T. | 8303140240 | 50-382 F |
| COLLINS, J. T. | 8303140251 | 50-498 F |
| COLLINS, J. T. | 8303140306 | 50-482 F |
| COLLINS, J. T. | 8303140317 | 50-458 F |
| COLLINS, J. T. | 8303140324 | 50-445 F |
| COLLINS, J. T. | 8303140517 | State Prog |
| COLLINS, J. T. | 8303140581 | 50-313 G |
| COLLINS, J. T. | 8303140593* | 50-313 G |
| COLLINS, J. T. | 8303150257 | 50-313 P |
| COLLINS, J. T. | 8303150281 | 50-285 P |
| COLLINS, J. T. | 8303150283 | 50-445 A |
| COLLINS, J. T. | 8303150330 | 50-267 P |
| COLLINS, J. T. | 8303150340 | 50-267 P |
| COLLINS, J. T. | 8303150352 | 50-298 F |
| COLLINS, J. T. | 8303150358 | 50-498 A |
| COLLINS, J. T. | 8303150364 | 50-382 F |
| COLLINS, J. T. | 8303150498 | 50-498 A |
| COLLINS, J. T. | 8303150652 | 50-482 A |
| COLLINS, J. T. | 8303150473 | 50-482 A |
| COLLINS, J. T. | 8303240422 | 50-267 G |
| COLLINS, J. T. | 8303240427* | 50-267 G |
| COLLINS, J. T. | 8303240473 | 50-298 F |
| COLLINS, J. T. | 8303280163 | GA999 |
| COLLINS, J. T. | 8303290015 | 50-313 F |
| COLLINS, J. T. | 8303290038 | 50-267 F |
| COLLINS, J. T. | 8303290231 | 50-440 |
| COLLINS, J. T. | 8303290299 | 50-482 F |
| COLLINS, J. T. | 8303290318 | 50-382 F |
| COLLINS, J. T. | 8303290467 | 50-458 F |
| COLLINS, J. T. | 8303290493 | 50-285 F |
| COLLINS, J. T. | 8303290554 | 50-498 F |
| COLLINS, P. | 8303030513* | CONTRACT |
| COLLINS, S. J. | 8303160326* | 50-29 G |
| COLLINS, T. R. | 8303010453* | 50-327 G |
| COLLINS, T. R. | 8303010501* | 50-416 G |
| COLLINS, T. R. | 8303010508* | 50-416 G |
| COLLISON, K. | 8303100022 | FOIA |
| COLLOPY, T. J. | 8303020282 | 70-371 |
| COLMAN, J. | 8303210776 | RES |
| COLOMBO, R. | 8303150346* | 50-312 R |
| COLOMBO, R. | 8303300233* | 50-312 R |
| COLOMBO, R. W. | 8303110160* | 50-312 S |
| COLOMBO, R. W. | 8303110318* | 50-312 S |
| COLOMBO, R. W. | 8303110361* | 50-312 S |
| COLOMBO, R. W. | 8303110364* | 50-312 S |
| COLTON, E. | 8303040129 | XPORTLIC |
| COLTON, J. P. | 8303250122 | 50-332 A |
| COMELLA, P. A. | 8303180091* | WASTE MGT |
| COMELLA, P. A. | 8303180100* | WASTE MGT |
| CONDIE, K. G. | 8303180694 | RES |
| CONKLIN, J. C. | 8303160009 | NUREG |
| CONLON, T. E. | 8303010235* | 50-413 G |
| CONLON, T. E. | 8303010334* | 50-389 G |
| CONLON, T. E. | 8303010398* | 50-438 G |
| CONLON, T. E. | 8303210451* | 50-424 G |
| CONLON, T. E. | 8303210454* | 50-400 G |
| CONLON, T. E. | 8303210528* | 50-389 G |
| CONLON, T. E. | 8303210541* | 50-395 G |
| CONLON, T. E. | 8303210597* | 50-416 G |
| CONLON, T. E. | 8303210719* | 50-400 G |
| CONNER, E. L. | 8303020189* | 50-336 S |
| CONNER, E. L. | 8303210006 | 50-269 P |
| CONNER, T. B. | 8303150391 | 50-352 G |
| CONNER, T. B. | 8303150391 | 50-352 G |
| CONSTABLE, G. L. | 8303010227* | 50-382 G |
| CONSTABLE, G. L. | 8303210631* | 50-382 G |
| CONTE, R. | 8303280191* | 50-289 G |
| CONWAY, J. T. | 8303150530* | 50-445 G |
| CONWAY, J. T. | 8303180212* | GA999 |
| CONWAY, J. T. | 8303280222* | GA999 |
| CONWAY, L. | 8303010331* | 50-454 T |
| CONWAY, L. | 8303010331* | 50-454 T |
| COOK, B. A. | 8303240137 | RES |
| COOK, F. R. | 8303290564 | WASTE MGT |
| COOK, J. | 8303140227* | 50-333 R |
| COOK, J. W. | 8303090140 | 50-329 A |
| COOK, J. W. | 8303100188 | 50-329 S |
| COOK, J. W. | 8303100208 | 50-329 R |
| COOK, J. W. | 8303100219 | 50-329 S |
| COOK, J. W. | 8303100263 | 50-329 S |
| COOK, J. W. | 8303100310 | 50-329 S |
| COOK, J. W. | 8303100384 | 50-329 S |
| COOK, J. W. | 8303110251 | 50-329 E |
| COOK, J. W. | 8303140210 | 50-329 A |
| COOK, J. W. | 8303140368 | 50-329 S |
| COOK, J. W. | 8303140371 | 50-329 S |
| COOK, J. W. | 8303140398 | 50-329 G |
| COOK, J. W. | 8303140463 | 50-329 S |
| COOK, J. W. | 8303180209 | 50-329 G |
| COOK, J. W. | 8303210060 | 70-2964 |
| COOK, J. W. | 8303240027 | 50-329 F |
| COOK, J. W. | 8303240211 | 50-329 S |
| COOK, J. W. | 8303240266 | 50-329 A |
| COOK, J. W. | 8303240451 | 50-329 A |
| COOK, J. W. | 8303240458 | 50-329 E |
| COOK, J. W. | 8303280135 | 50-329 S |
| COOK, R. J. | 8303090100* | 50-329 G |
| COOK, R. J. | 8303090108* | 50-329 G |
| COOK, R. J. | 8303110366* | 50-329 G |
| COOK, R. J. | 8303210286* | 50-329 A |
| COONEY, R. J. | 8303080381 | 50-277 G |
| COONEY, R. J. | 8303080395* | 50-277 S |
| COONEY, R. J. | 8303080452 | 50-277 P |
| COONEY, R. J. | 8303140500 | 50-278 S |
| COONEY, R. J. | 8303140537* | 50-278 S |
| COONEY, R. J. | 8303160190 | 50-277 S |
| COONEY, R. J. | 8303160332 | 50-277 R |
| COONEY, R. J. | 8303290388 | 50-278 S |
| COOPER, D. | 8303230195* | CONTRACT |
| COOPER, W. E. | 8303020147 | 50-275 P |
| COOPER, W. E. | 8303090335 | 50-275 R |
| COOPER, W. E. | 8303090372 | 50-275 P |
| COOPER, W. E. | 8303090384 | 50-275 R |
| COOPER, W. E. | 8303240419 | 50-275 P |
| COOPER, W. E. | 8303290002 | 50-275 R |
| COPELAND, J. | 8303070095 | 50-440 G |
| COPELAND, V. G. | 8303240386 | 50-454 G |
| COPELAND, V. G. | 8303240386 | 50-454 G |
| COPELAND, V. G. | 8303240550 | 50-454 G |
| COPELAND, V. G. | 8303240550 | 50-454 G |
| COPELAND, V. G. | 8303290530 | 50-155 G |
| COPELAND, V. G. | 8303290530 | 50-155 G |
| COPLAN, S. M. | 8303290705 | WASTE MGT |
| CORDANI, R. A. | 8303010689 | 70-27 |
| CORDANI, R. A. | 8303020212 | 70-27 |
| CORMIER, W. H. | 8303220220 | 50-142 G |
| CORP, E. L. | 8303300170 | WASTE MGT |
| CORRADINI, M. | 8303210104 | ACRS |
| CORRADINI, M. | 8303210108* | ACRS |
| CORREN, D. R. | 8303180227* | 50-247 G |
| CORYELL, G. P. | 8303210363* | 70-1113 |
| COSTELLO, F. | 8303290694 | NUREG |
| COSTELLO, J. R. | 8303080376* | GA999 |
| COSTELLO, O. J. | 8303080037* | 50-280 R |
| COTTER, B. P. | 8303010401 | 50-445 G |
| COTTER, B. P. | 8303070117 | 50-508 G |
| COTTON, G. D. | 8303090288* | 50-206 P |
| COUNSIL, W. G. | 8303010347 | 50-336 G |
| COUNSIL, W. G. | 8303010347 | 50-336 G |
| COUNSIL, W. G. | 8303010386 | 50-245 P |
| COUNSIL, W. G. | 8303010386 | 50-245 P |
| COUNSIL, W. G. | 8303030077 | 50-213 P |
| COUNSIL, W. G. | 8303040187* | 50-213 P |
| COUNSIL, W. G. | 8303040187* | 50-213 P |
| COUNSIL, W. G. | 8303040187* | 50-213 P |
| COUNSIL, W. G. | 8303040214* | 10CFR |
| COUNSIL, W. G. | 8303040368 | 50-213 G |
| COUNSIL, W. G. | 8303040368 | 50-213 G |
| COUNSIL, W. G. | 8303040368 | 50-213 G |
| COUNSIL, W. G. | 8303040487 | 50-423 C |
| COUNSIL, W. G. | 8303040487 | 50-423 C |
| COUNSIL, W. G. | 8303040546 | 50-245 P |
| COUNSIL, W. G. | 8303040546 | 50-245 P |
| COUNSIL, W. G. | 8303080102 | 50-245 P |
| COUNSIL, W. G. | 8303080102 | 50-245 P |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| COUNSIL, W. G. | 8303080176 | 50-245 P |
| COUNSIL, W. G. | 8303080176 | 50-245 P |
| COUNSIL, W. G. | 8303080208 | 50-245 R |
| COUNSIL, W. G. | 8303080208 | 50-245 R |
| COUNSIL, W. G. | 8303080317 | 50-213 P |
| COUNSIL, W. G. | 8303080317 | 50-213 P |
| COUNSIL, W. G. | 8303080317 | 50-213 P |
| COUNSIL, W. G. | 8303080335 | 50-213 P |
| COUNSIL, W. G. | 8303080335 | 50-213 P |
| COUNSIL, W. G. | 8303080465 | 50-245 P |
| COUNSIL, W. G. | 8303080465 | 50-245 P |
| COUNSIL, W. G. | 8303090240* | 50-213 F |
| COUNSIL, W. G. | 8303100258 | 50-336 P |
| COUNSIL, W. G. | 8303100258 | 50-336 P |
| COUNSIL, W. G. | 8303110107 | 71-4986 |
| COUNSIL, W. G. | 8303110107 | 71-4986 |
| COUNSIL, W. G. | 8303110313 | 50-336 P |
| COUNSIL, W. G. | 8303110313 | 50-336 P |
| COUNSIL, W. G. | 8303150345 | 50-245 P |
| COUNSIL, W. G. | 8303150345 | 50-245 P |
| COUNSIL, W. G. | 8303160264 | 50-245 P |
| COUNSIL, W. G. | 8303160264 | 50-245 P |
| COUNSIL, W. G. | 8303170156 | 50-336 P |
| COUNSIL, W. G. | 8303170156 | 50-336 P |
| COUNSIL, W. G. | 8303180297 | 50-213 G |
| COUNSIL, W. G. | 8303180297 | 50-213 G |
| COUNSIL, W. G. | 8303180405 | 50-213 P |
| COUNSIL, W. G. | 8303210307 | 50-213 P |
| COUNSIL, W. G. | 8303220096 | 50-213 F |
| COUNSIL, W. G. | 8303270133 | 50-213 P |
| COUNSIL, W. G. | 8303290044 | 50-213 P |
| COUNSIL, W. G. | 8303290044 | 50-213 P |
| COUNSIL, W. G. | 8303290049 | 50-213 P |
| COUNSIL, W. G. | 8303240407 | 50-213 R |
| COUNSIL, W. G. | 8303240407 | 50-213 R |
| COUNSIL, W. G. | 8303240407 | 50-213 R |
| COUNSIL, W. G. | 8303290044* | 50-213 F |
| COUNSIL, W. G. | 8303290064* | 50-213 F |
| COUNSIL, W. G. | 8303290064* | 50-213 F |
| COUNSIL, W. G. | 8303290064* | 50-213 F |
| COUNSIL, W. G. | 8303290195 | 50-213 P |
| COUNSIL, W. G. | 8303290195 | 50-213 P |
| COUNSIL, W. G. | 8303290195 | 50-213 P |
| COUNSIL, W. G. | 8303290198 | 50-213 P |
| COUNSIL, W. G. | 8303290198 | 50-213 P |
| COUNSIL, W. G. | 8303290243* | 50-245 F |
| COUNSIL, W. G. | 8303290411 | 50-245 P |
| COUNSIL, W. G. | 8303290313 | 50-245 P |
| COUNSIL, W. G. | 8303290443 | 50-213 P |
| COUNSIL, W. G. | 8303290443 | 50-213 P |
| COUNSIL, W. G. | 8303290443 | 50-213 P |
| COUNSIL, W. G. | 8303290452 | 50-336 P |
| COUNSIL, W. G. | 8303290495 | 50-245 P |
| COUNSIL, W. G. | 8303290495 | 50-245 P |
| COUNSIL, W. G. | 8303290560 | 50-245 P |
| COUNSIL, W. G. | 8303290560 | 50-245 P |
| COUNSIL, W. G. | 8303300359 | 50-336 G |
| COUNSIL, W. G. | 8303300359 | 50-336 G |
| COUNSIL, W. G. | 8303310311 | 50-213 P |
| COUNSIL, W. G. | 8303310311 | 50-213 P |
| COUNSIL, W. G. | 8303310311 | 50-213 P |
| COUNSIL, W. G. | 8303310321 | 50-213 P |
| COURCIER, P. | 8303020300 | XPORTLIC |
| COURCIER, P. | 8303030178* | XPORTLIC |
| COX, E. J. | 8303090513 | 40-4492 |
| COX, H. T. | 8303240391* | 50-261 S |
| COYLE, L. | 8303080099* | 50-237 S |
| COYLE, L. | 8303080100* | 50-249 S |
| COYLE, L. | 8303150395* | 50-249 S |
| COYLE, L. | 8303220093 | 50-249 S |
| COZEN, G. | 8303220090* | 50-187 R |
| CRABTREE, R. A. | 8303140359 | 50-309 J |
| CRAGIN, J. G. | 8303090372 | 50-275 P |
| CRAGIN, J. G. | 8303240419 | 50-275 P |
| CRAGIN, J. G. | 8303290469 | 50-275 R |
| CRANE, P. A. | 8303010285 | 50-275 P |
| CRANE, P. A. | 8303010421* | 50-275 G |
| CRANE, P. A. | 8303040469 | 50-323 G |
| CRANE, P. A. | 8303040531 | 50-275 P |
| CRANE, P. A. | 8303080114 | 50-275 G |
| CRANE, P. A. | 8303080212 | 50-275 P |
| CRANE, P. A. | 8303080307 | 50-275 P |
| CRANE, P. A. | 8303080388 | 50-275 P |
| CRANE, P. A. | 8303080440 | 50-133 V |
| CRANE, P. A. | 8303080448 | 50-275 P |
| CRANE, P. A. | 8303080521 | 50-275 F |
| CRANE, P. A. | 8303090226 | 50-133 G |
| CRANE, P. A. | 8303090258 | 50-275 H |
| CRANE, P. A. | 8303090330 | 50-275 V |
| CRANE, P. A. | 8303100241 | 50-275 R |
| CRANE, P. A. | 8303110506* | 50-275 P |
| CRANE, P. A. | 8303170348 | 50-275 P |
| CRANE, P. A. | 8303220304 | 50-275 P |
| CRANE, P. A. | 8303240513 | 50-275 P |
| CRANE, P. A. | 8303250061 | 50-275 R |
| CRANE, P. A. | 8303250079 | 50-275 R |
| CRANE, P. A. | 8303280027 | 50-133 P |
| CRANE, P. A. | 8303280042 | 50-275 P |
| CRANE, P. A. | 8303280132 | 50-133 J |
| CRANE, P. A. | 8303290345 | 50-133 I |
| CRANE, P. A. | 8303290365 | 50-275 R |
| CRANE, P. A. | 8303300030 | 50-275 P |
| CRANE, P. A. | 8303300035 | 50-275 P |
| CRANE, P. A. | 8303300115 | 50-275 P |
| CRANE, P. A. | 8303300121 | 50-133 P |
| CRANE, P. A. | 8303300697* | 50-275 F |
| CRAWFORD, S. L. | 8303220422 | NUREG |
| CRAWFORD, V. A. | 8303100268 | 50-528 G |
| CRAWFORD, V. A. | 8303100268 | 50-528 G |
| CRAWFORD, V. A. | 8303220257 | 50-528 G |
| CRAWFORD, V. A. | 8303220257 | 50-528 G |
| CREED, J. | 8303080003 | 50-374 S |
| CREED, J. | 8303220233 | 50-295 S |
| CREED, J. R. | 8303030473* | 50-255 G |
| CREED, J. R. | 8303030540* | 50-213 G |
| CREED, J. R. | 8303030543* | 50-305 G |
| CREED, J. R. | 8303030690* | 99-186 G |
| CREED, J. R. | 8307150283* | 50-67 G |
| CREED, J. R. | 8303140357* | 50-2 G |
| CREED, J. R. | 8303170459* | 50-266 G |
| CREED, J. R. | 8303220029 | I&E |
| CREED, J. R. | 8303280321* | 50-254 G |
| CREWS, J. L. | 8303080210* | 50-397 G |
| CREWS, J. L. | 8303290453 | 50-206 G |
| CREWS, J. L. | 8303290508* | 50-361 G |
| CREWS, J. L. | 8303290544 | 50-275 G |
| CROCKER, H. W. | 8303240010 | 50-3 S |
| CROCKER, H. W. | 8303240442* | 50-334 G |
| CROCKER, H. W. | 8303280628* | 50-277 G |
| CROSBY, R. C. | 8303010315* | 50-309 S |
| CROSS, R. D. | 8303210400* | 50-111 W |
| CROSSMAN, W. A. | 8303013227* | 50-382 G |
| CROSSMAN, W. A. | 8303010249* | 50-459 G |
| CROSSMAN, W. A. | 8303010587* | 50-458 G |
| CROSSMAN, W. A. | 8303080091* | 50-458 G |
| CROSSMAN, W. A. | 8303080374* | 50-458 G |
| CROSSMAN, W. A. | 8303150491* | 50-498 G |
| CROSSMAN, W. A. | 8303210631* | 50-382 G |
| CROSSMAN, W. A. | 8303280262* | 50-382 G |
| CROUSE, R. P. | 8303010430 | 50-346 V |
| CROUSE, R. P. | 8303010581 | TOPREP |
| CROUSE, R. P. | 8303010581 | TOPREP |
| CROUSE, R. P. | 8303030173 | TOPREP |
| CROUSE, R. P. | 8303030173 | TOPREP |
| CROUSE, R. P. | 8303080047 | 50-346 G |
| CROUSE, R. P. | 8303150252 | 50-346 P |
| CROUSE, R. P. | 8303150274 | 50-346 G |
| CROUSE, R. P. | 8303150427 | 50-346 P |
| CROUSE, R. P. | 8303150432 | 50-346 P |
| CROUSE, R. P. | 8303150499 | 50-346 P |
| CROUSE, R. P. | 8303220058 | 50-346 P |
| CROUSE, R. P. | 8303220073 | 50-346 P |
| CROUSE, R. P. | 8303220150 | 50-346 P |
| CROUSE, R. P. | 8303220155 | 50-346 P |
| CROUSE, R. P. | 8303220205 | TOPREP |
| CROUSE, R. P. | 8303220205 | TOPREP |
| CROUSE, R. P. | 8303240496 | 50-346 P |
| CROUSE, R. P. | 8303280030 | 50-346 P |
| CROUSE, R. P. | 8303280197* | 50-346 F |
| CROUSE, R. P. | 8303290380 | 50-346 G |
| CROUSE, R. P. | 8303290393 | 50-346 P |
| CROUSE, R. P. | 8303300394 | 50-346 P |
| CROUSE, R. P. | 8303300717* | 50-289 P |
| CROUSE, R. P. | 8303300717* | 50-289 P |
| CROW, W. T. | 8303040326* | 70-2932 |
| CROW, W. T. | 8303040331* | 70-2932 |
| CROW, W. T. | 8303040411 | 70-734 |
| CROW, W. T. | 8303090230* | 70-820 |
| CROW, W. T. | 8303110165* | 70-2928 |
| CROW, W. T. | 8303140139* | 70-1062 |
| CROW, W. T. | 8303180136* | 70-2946 |
| CROW, W. T. | 8303180526* | 70-2910 |
| CROW, W. T. | 8303180667 | 40-8027 |
| CROW, W. T. | 8303210225 | 70-824 |
| CROW, W. T. | 8303290777* | 70-1100 |
| CROW, W. T. | 8303310379* | 40-2061 |
| CROWLEY, B. R. | 8303010537* | 50-321 G |
| CROWLEY, B. R. | 8303210341* | 50-417 G |
| CROWLEY, E. D. | 8303030221 | FOIA |
| CROWLEY, E. D. | 8303030230 | FOIA |
| CROWLEY, J. L. | 8303170616 | NUREG |
| CRUMP, G. R. | 8303100256 | 50-445 G |
| CRUTCHFIELD, D. | 8302220002 | 50-29 P |
| CRUTCHFIELD, D. | 8303010575 | 50-155 P |
| CRUTCHFIELD, D. | 8303010598 | 50-213 P |
| CRUTCHFIELD, D. | 8303010603* | 50-155 P |
| CRUTCHFIELD, D. | 8303010615* | 50-155 P |
| CRUTCHFIELD, D. | 8303030134 | 50-29 P |
| CRUTCHFIELD, D. | 8303030141* | 50-29 P |
| CRUTCHFIELD, D. | 8303030153* | 50-29 P |
| CRUTCHFIELD, D. | 8303030190 | 50-155 P |
| CRUTCHFIELD, D. | 8303030197* | 50-155 P |
| CRUTCHFIELD, D. | 8303030270 | 50-409 F |
| CRUTCHFIELD, D. | 8303040205 | 50-213 F |
| CRUTCHFIELD, D. | 8303040423 | 50-155 P |
| CRUTCHFIELD, D. | 8303040604 | 50-213 P |
| CRUTCHFIELD, D. | 8303080110 | 50-213 P |
| CRUTCHFIELD, D. | 8303080118* | 50-213 P |
| CRUTCHFIELD, D. | 8303090123 | 50-155 P |
| CRUTCHFIELD, D. | 8303090205 | 50-409 P |
| CRUTCHFIELD, D. | 8303090256 | 50-213 P |
| CRUTCHFIELD, D. | 8303090262* | 50-213 P |
| CRUTCHFIELD, D. | 8303090317 | 50-245 F |
| CRUTCHFIELD, D. | 8303100301 | 50-254 P |
| CRUTCHFIELD, D. | 8303110139 | 50-29 P |
| CRUTCHFIELD, D. | 8303140471 | 50-155 P |
| CRUTCHFIELD, D. | 8303170064 | 50-237 P |
| CRUTCHFIELD, D. | 8303170145 | 50-219 P |
| CRUTCHFIELD, D. | 8303170170 | 50-206 P |
| CRUTCHFIELD, D. | 8303170179 | 50-409 P |
| CRUTCHFIELD, D. | 8303170188* | 50-409 P |
| CRUTCHFIELD, D. | 8303170197* | 50-409 P |
| CRUTCHFIELD, D. | 8303170203* | 50-206 P |
| CRUTCHFIELD, D. | 8303170211* | 50-206 P |
| CRUTCHFIELD, D. | 8303170240 | 50-409 P |
| CRUTCHFIELD, D. | 8303170261 | 50-29 P |
| CRUTCHFIELD, D. | 8303170282 | 50-255 P |
| CRUTCHFIELD, D. | 8303170305 | 50-206 P |
| CRUTCHFIELD, D. | 8303180475 | 50-213 P |
| CRUTCHFIELD, D. | 8303180485* | 50-213 P |
| CRUTCHFIELD, D. | 8303180493* | 50-213 P |
| CRUTCHFIELD, D. | 8303220092 | 50-244 P |
| CRUTCHFIELD, D. | 8303220201 | 50-213 P |
| CRUTCHFIELD, D. | 8303220362 | 50-237 P |
| CRUTCHFIELD, D. | 8303220363 | 50-155 P |
| CRUTCHFIELD, D. | 8303230429* | 50-245 P |
| CRUTCHFIELD, D. | 8303280065 | 50-244 P |
| CRUTCHFIELD, D. | 8303280268 | 50-237 P |
| CULVER, C. M. | 8303310602* | CONTRACT |
| CUMMINGS, J. J. | 8303110172* | FOIA |
| CUMMINS, J. E. | 8303210562* | 50-313 G |
| CUNNINGHAM, A. L. | 8303010295* | 50-348 G |
| CUNNINGHAM, A. L. | 8303210429* | 50-395 G |
| CUNNINGHAM, G. E. | 8303030035 | 71-9044 |
| CUNNINGHAM, G. E. | 8303030216 | 71-9044 |
| CUNNINGHAM, G. E. | 8303170374 | 50-18 R |
| CUNNINGHAM, G. E. | 8303170399 | 50-183 R |
| CUNNINGHAM, G. E. | 8303170457 | 50-70 R |
| CUNNINGHAM, G. H. | 8211180558* | FOIA |
| CUNNINGHAM, G. H. | 8302150708 | PR |
| CUNNINGHAM, G. H. | 8303020071 | 50-445 G |
| CUNNINGHAM, G. H. | 8303150127 | 50-445 G |
| CUNNINGHAM, G. H. | 8303160775 | 50-329 G |
| CUNNINGHAM, G. H. | 8303170006 | 50-329 G |
| CUNNINGHAM, L. J. | 8303100556* | COMMISSION |
| CUNNINGHAM, L. J. | 8303240010 | 50-3 S |
| CUNNINGHAM, R. E. | 8303180452 | 50-201 P |
| CUNNINGHAM, R. G. | 8303210066 | 70-113 |
| CURRAN, D. | 8303080454 | 50-443 G |
| CURRAN, D. | 8303080490 | 50-443 G |
| CURRAN, D. | 8303090082 | FOIA |
| CURRAN, D. | 8303090219 | FOIA |
| CURRAN, D. | 8303220234 | 50-443 G |
| CURRAN, D. | 8303220234 | 50-443 G |

# PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| CURRAN, D. | 8303220245 | 50-443 G |
| CURRAN, D. | 8303220245 | 50-443 G |
| CURRAN, D. | 8303290536 | 50-443 G |
| CURRAN, D. | 8303290536 | 50-443 G |
| CURREY, M. | 8303220419* | WASTE MGT |
| CURTIS, N. M. | 8303170193* | 50-171 I |
| CURTIS, N. W | 8303010267 | 50-388 S |
| CURTIS, N. W. | 8303010332 | 50-387 P |
| CURTIS, N. W. | 8303010637 | 50-387 S |
| CURTIS, N. W. | 8303040405 | 50-387 P |
| CURTIS, N. W. | 8303070065 | 50-387 F |
| CURTIS, N. W. | 8303070080 | 50-387 P |
| CURTIS, N. W. | 8303070097 | 50-387 P |
| CURTIS, N. W. | 8303080474 | 50-387 Q |
| CURTIS, N. W. | 8303110270 | 50-387 F |
| CURTIS, N. W. | 8303140237 | 50-387 P |
| CURTIS, N. W. | 8303140458 | 50-387 P |
| CURTIS, N. W. | 8303160227 | 50-387 S |
| CURTIS, N. W. | 8303160281 | 50-387 P |
| CURTIS, N. W. | 8303160289* | 50-387 P |
| CURTIS, N. W. | 8303170524 | 50-387 P |
| CURTIS, N. W. | 8303210332 | 50-387 I |
| CURTIS, N. W. | 8303220177 | 50-387 P |
| CURTIS, N. W. | 8303220276 | 50-387 P |
| CURTIS, N. W. | 8303220329 | 50-387 P |
| CURTIS, N. W. | 8303280020 | 50-387 F |
| CURTIS, N. W. | 8303280063 | 50-387 X |
| CURTIS, N. W. | 8303280162 | 50-387 P |
| CUTCHIN, J. M. | 8303010075 | 50-440 Q |
| CUTCHIN, J. M. | 8303070091 | 50-440 Q |
| CUTCHIN, J. M. | 8303140317 | 50-289 G |
| CUTCHIN, J. M. | 8303150310 | 50-289 G |
| CZAJKOWSKI, C. | 8303160620 | 50-369 P |
| DAHLMAN, L. C. | 8303010211* | 50-263 G |
| DAIL, L. G. | 8303010572 | TOPREP |
| DALE, L. F. | 8303010016 | 71-5939 |
| DALE, L. F. | 8303010307 | 50-416 F |
| DALE, L. F. | 8303030150 | 50-416 P |
| DALE, L. F. | 8303210328 | 50-416 Q |
| DALE, L. F. | 8303280025 | 50-416 P |
| DALTROFF, S. L. | 8303070071 | 50-277 F |
| DALTROFF, S. L. | 8303080373* | 50-277 Q |
| DALTROFF, S. L. | 8303110329 | 50-277 P |
| DALTROFF, S. L. | 8303150379* | 50-277 P |
| DALTROFF, S. L. | 8303170339 | 50-277 P |
| DALTROFF, S. L. | 8303180327 | 50-277 P |
| DALTROFF, S. L. | 8303220211 | 50-277 Q |
| DALTROFF, S. L. | 8303280238 | 50-277 S |
| DALTROFF, S. L. | 8303290277 | 50-277 F |
| DALTROFF, S. L. | 8303300588* | 50-277 F |
| DALY, B. J. | 8303300518 | NUREG |
| DANCE, H. C. | 8303010145 | 50-250 Q |
| DANCE, H. C. | 8303010155 | 50-370 Q |
| DANCE, H. C. | 8303010166* | 50-250 Q |
| DANCE, H. C. | 8303010210 | 50-389 Q |
| DANCE, H. C. | 8303010231 | 50-413 Q |
| DANCE, H. C. | 8303010245 | 50-302 Q |
| DANCE, H. C. | 8303010329 | 50-389 Q |
| DANCE, H. C. | 8303010368 | 50-389 Q |
| DANCE, H. C. | 8303010443 | 50-338 Q |
| DANCE, H. C. | 8303010512 | 50-321 Q |
| DANCE, H. C. | 8303010526* | 50-321 Q |
| DANCE, H. C. | 8303010570 | 50-335 Q |
| DANCE, H. C. | 8303010596 | 50-369 Q |
| DANCE, H. C. | 8303010634 | 50-280 Q |
| DANCE, H. C. | 8303010677 | 50-250 Q |
| DANCE, H. C. | 8303150476 | 50-370 Q |
| DANCE, H. C. | 8303210337 | 50-413 Q |
| DANCE, H. C. | 8303210342 | 50-280 Q |
| DANCE, H. C. | 8303210344 | 50-370 Q |
| DANCE, H. C. | 8303210370 | 50-369 Q |
| DANCE, H. C. | 8303210415 | 50-302 Q |
| DANCE, H. C. | 8303210425 | 50-395 Q |
| DANCE, H. C. | 8303210442 | 50-389 Q |
| DANCE, H. C. | 8303210443 | 50-424 Q |
| DANCE, H. C. | 8303210444 | 50-335 Q |
| DANCE, H. C. | 8303210481 | 50-424 Q |
| DANCE, H. C. | 8303210483 | 50-395 Q |
| DANCE, H. C. | 8303210496 | 50-370 Q |
| DANCE, H. C. | 8303210506 | 50-389 Q |
| DANCE, H. C. | 8303210519* | 50-389 Q |
| DANCE, H. C. | 8303210573 | 50-424 Q |
| DANCE, H. C. | 8303210582 | 50-250 Q |
| DANCE, H. C. | 8303210612* | 50-302 Q |
| DANCE, H. C. | 8303210738 | 50-369 Q |
| DANCE, H. C. | 8303210635 | 50-321 Q |
| DANCE, H. C. | 8303210671* | 50-302 Q |
| DANCE, H. C. | 8303210678 | 50-280 Q |
| DANCE, H. C. | 8303210697 | 50-389 Q |
| DANCE, H. C. | 8303210708 | 50-413 Q |
| DANCE, H. C. | 8303210712* | 50-389 Q |
| DANCE, H. C. | 8303210722 | 50-338 Q |
| DANCE, H. C. | 8303210735 | 50-250 Q |
| DANCE, H. C. | 8303240397 | 50-369 S |
| DANCE, H. C. | 8303280131 | 50-269 Q |
| DANCE, H. C. | 8303280144* | 50-269 Q |
| DANCE, H. C. | 8303280281 | 50-321 Q |
| DANCE, H. C. | 8303290389 | 50-280 Q |
| DANCE, H. C. | 8303290424 | 50-250 Q |
| DANCE, H. C. | 8303290440* | 50-250 Q |
| DANCE, H. C. | 8303290457 | 50-338 Q |
| DANIEL, J. K. | 8303250040 | 50-389 A |
| DANIELSON, D. H. | 8303040574* | 50-295 Q |
| DANIELSON, D. H. | 8303170444* | 50-456 Q |
| DANIELSON, D. H. | 8303240517* | 50-440 Q |
| DAVENPORT, L. C. | 8303100416 | NUREG |
| DAVIDSON, S. L. | 8303070157* | TOPREP |
| DAVIES, O. | 8303100392 | 50-440 Q |
| DAVIS, A. B. | 8303170532 | 50-10 Q |
| DAVIS, F. | 8303310223* | FOIA |
| DAVIS, F. C. | 8303310088* | FOIA |
| DAVIS, F. C. | 8303310091* | FOIA |
| DAVIS, F. C. | 8303310285* | FOIA |
| DAVIS, J. G. | 8303090004* | FOIA |
| DAVIS, J. G. | 8303090009* | FOIA |
| DAVIS, J. G. | 8303090016* | FOIA |
| DAVIS, J. G. | 8303.00452* | FOIA |
| DAVIS, J. G. | 8303170259 | 40-8145 |
| DAVIS, J. G. | 8303180639 | WASTE MGT |
| DAVIS, J. G. | 8303290632 | WASTE MGT |
| DAVIS, M. G. | 8303090616 | RES |
| DAVIS, M. J. | 8303010645* | 50-280 Q |
| DAVIS, M. J. | 8303010673* | 50-200 Q |
| DAVIS, M. J. | 8303210346* | 50-280 Q |
| DAVIS, M. E. | 8303090577 | RES |
| DAVIS, P. R. | 8303180683 | ACRS |
| DAVIS, P. R. | 8303180683 | ACRS |
| DAVIS, T. J. | 8303100421 | NUREG |
| DAWSON, D. M. | 8302040471 | 71-9001 |
| DAWSON, D. M. | 8303010171 | 71-4 |
| DAWSON, D. M. | 8303110147 | 71-9001 |
| DAWSON, D. M. | 8303180508 | 71-9001 |
| DAYAL, R. | 8303090533 | RES |
| DAYAL, R. | 8303095e9 | RES |
| DAYAL, R. | 8303090577 | RES |
| DAYAL, R. | 8303090608 | RES |
| DEAGAZIO, A. W. | 8303020385 | 50-346 P |
| DEAGAZIO, A. W. | 8303020413 | 50-346 P |
| DEAGAZIO, A. W. | 8303030398 | 50-346 P |
| DEAGAZIO, A. W. | 8303310089 | COMMISSION |
| DEARIEN, J. A. | 8303180696 | RES |
| DEARIEN, J. A. | 8303240146 | RES |
| DEBARBA, E. | 8303010254 | NUREG |
| DEBARBA, E. | 8303010254 | NUREG |
| DEBARBA, E. A. | 8303040610* | 50-213 P |
| DEBS, B. T. | 8303210588* | 50-250 Q |
| DEEDS, W. E. | 8303140622 | NUREG |
| DEEDS, W. E. | 8303290710 | NUREG |
| DEFELICE, N. | 8303010362* | 50-397 E |
| DELAURENTIS, L. | 8303040555* | 50-293 P |
| DELGAIZO, T. J. | 8203290497* | 50-282 P |
| DELGEORGE, L. O. | 8303080080 | 50-454 T |
| DELGEORGE, L. O. | 8303140261* | 50-456 Q |
| DELLA RATTA, A. | 8303160472* | 70-371 |
| DELLA RATTA, A. | 8303300403* | 70-820 |
| DENISON, E. | 8303020102 | 50-275 P |
| DENISON, E. | 8303020109* | 50-275 P |
| DENISON, E. | 8303100229 | 50-275 P |
| DENISON, E. | 8303100235* | 50-275 P |
| DENISON, E. | 8303160337 | 50-275 R |
| DENISON, E. | 8303160342* | 50-275 R |
| DENISON, E. | 8303170118 | 50-275 R |
| DENTON, H. | 8303090517* | 50-373 P |
| DENTON, H. R. | 8205200343* | 50-206 P |
| DENTON, H. R. | 8303020161* | REVIEW GRP |
| DENTON, H. R. | 8303040137 | 50-275 H |
| DENTON, H. R. | 8303040142 | 50-170 U |
| DENTON, H. R. | 8303110070 | 50-498 Q |
| DENTON, H. R. | 8303110075* | 50-498 Q |
| DENTON, H. R. | 8303110079* | 50-498 Q |
| DENTON, H. R. | 8303140008 | 50-346 H |
| DENTON, H. R. | 8303140020 | NUREG |
| DENTON, H. R. | 8303140074 | 50-302 H |
| DENTON, H. R. | 8303150044 | REVIEW GRP |
| DENTON, H. R. | 8303150051* | ORG |
| DENTON, H. R. | 8303150143 | 50-295 Q |
| DENTON, H. R. | 8303150153* | 50-295 Q |
| DENTON, H. R. | 8303170205 | ORG |
| DENTON, H. R. | 8303220450* | 50-317 F |
| DENTON, H. R. | 8303230314* | 50-370 P |
| DENTON, H. R. | 8303290143 | 50-322 H |
| DENTON, H. R. | 8303300062 | 50-367 H |
| DERIENZO, P. P. | 8303210405* | GA999 |
| DERKS, P. S. | 8303080181* | 50-133 R |
| DERKS, P. S. | 8303150561* | 50-133 R |
| DERSHOWITZ, W. | 8303280097 | NUREG |
| DERSHOWITZ, W. | 8303280114 | NUREG |
| DEUTCH, J. | 8303020304* | COMMISSION |
| DEVAULT, G. P. | 8303230517 | NUREG |
| DEVINCENTIS, J. | 8303010409 | 50-443 A |
| DEVINCENTIS, J. | 8303010409 | 50-443 A |
| DEVINCENTIS, J. | 8303010533 | 50-443 A |
| DEVINCENTIS, J. | 8303010533 | 50-443 A |
| DEVINCENTIS, J. | 8303010578 | 50-443 F |
| DEVINCENTIS, J. | 8303010578 | 50-443 F |
| DEVINCENTIS, J. | 8303020083 | 50-443 A |
| DEVINCENTIS, J. | 8303020083 | 50-443 A |
| DEVINCENTIS, J. | 8303020085 | 50-443 A |
| DEVINCENTIS, J. | 8303020085 | 50-443 A |
| DEVINCENTIS, J. | 8303070156 | 50-443 H |
| DEVINCENTIS, J. | 8303150195 | 50-443 A |
| DEVINCENTIS, J. | 8303150295 | 50-443 A |
| DEVINCENTIS, J. | 8303.50207 | 50-443 A |
| DEVINCENTIS, J. | 8303150207 | 50-443 A |
| DEVINCENTIS, J. | 8303150331 | 50-443 E |
| DEVINCENTIS, J. | 8303150331 | 50-443 E |
| DEVINCENTIS, J. | 8303150436 | 50-443 A |
| DEVINCENTIS, J. | 8303150436 | 50-443 A |
| DEVINCENTIS, J. | 8303170358 | 50-443 A |
| DEVINCENTIS, J. | 8303170358 | 50-443 A |
| DEVINCENTIS, J. | 8303170441 | 50-443 A |
| DEVINCENTIS, J. | 8303170441 | 50-443 [illegible] |
| DEVINCENTIS, J. | 8303[illegible] | 50-443 Q |
| DEVINCENTIS, J. | 8303[illegible] | 50-443 Q |
| DEVINCENTIS, J. | 8303[illegible] | 50-443 R |
| DEVINCENTIS, J. | 8303240366 | 50-443 S |
| DEVINCENTIS, J. | 8303240441 | 50-443 C |
| DEVINCENTIS, J. | 8303240441 | 50-443 E |
| DEVINCENTIS, J. | 8303290254 | 50-443 E |
| DEVINCENTIS, J. | 8303290254 | 50-443 E |
| DEVINE, J. B. | 8303040022 | XPORTLIC |
| DEVINE, J. B. | 8303160640 | XPORTLIC |
| DEVINE, J. B. | 8303240331 | XPORTLIC |
| DEVINE, J. B. | 8303290140 | XPORTLIC |
| DEVINE, J. B. | 8303290227 | XPORTLIC |
| DEVINE, T. | 8303290391 | 50-320 Q |
| DEVLIN, J. W. | 8303110013* | 50-272 S |
| DEVLIN, J. W. | 8303110042* | FOIA |
| DEWEY, L. S. | 8303140099 | 50-529 Q |
| DEWEY, L. S. | 8303140472* | 50-528 Q |
| DEWEY, L. S. | 8303170035 | 50-529 Q |
| DEWEY, L. S. | 8303280145 | 50-529 Q |
| DEWEY, L. S. | 8303300375 | 50-529 Q |
| DEWEY, L. S. | 8303300445 | 50-529 Q |
| DEWITT, R. B. | 8303220151 | 50-255 P |
| DEYOUNG, R. C. | 8212060367 | 50-3 Q |
| DEYOUNG, R. C. | 8212060380 | 50-3 Q |
| DEYOUNG, R. C. | 8303090143 | 50-298 Q |
| DEYOUNG, R. C. | 8303090146* | 50-298 Q |
| DEYOUNG, R. C. | 8303090166 | 50-324 Q |
| DEYOUNG, R. C. | 8303090176* | 50-324 Q |
| DEYOUNG, R. C. | 8303100559* | COMMISSION |
| DEYOUNG, R. C. | 8303100561* | COMMISSION |
| DEYOUNG, R. C. | 8303110634 | 50-312 Q |
| DEYOUNG, R. C. | 8303140632* | COMMISSION |
| DEYOUNG, R. C. | 8303140637* | COMMISSION |
| DEYOUNG, R. C. | 8303250016 | 50-438 Q |
| DHILLON, H. | 8303150712* | CONTRACT |
| DICKENSON, A. C. | 8303160222* | 50-219 S |
| DICKERSON, M. W. | 8303070088* | 50-267 Q |
| DICKHONER, W. H. | 8303220357 | 50-358 A |
| DICKHONER, W. H. | 8303230072* | 50-358 A |
| DICKHONER, W. H. | 8303230084* | 50-358 A |
| DIEDERICH, G. J. | 8303080064 | 50-373 S |
| DIEDERICH, G. J. | 8303080066 | 50-373 S |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | |
|---|---|---|---|
| DIEDERICH, G. J. | 8303080234 | 50-373 | S |
| DIEDERICH, G. J. | 8303080358 | 50-373 | S |
| DIEDERICH, G. J. | 8303080491 | 50-373 | S |
| DIEDERICH, G. J. | 8303140424 | 50-373 | S |
| DIEDERICH, G. J. | 8303140477 | 50-373 | S |
| DIEDERICH, G. J. | 8303150422 | 50-373 | R |
| DIEDERICH, G. J. | 8303170477 | 50-373 | S |
| DIEDERICH, G. J. | 8303170478 | 50-373 | S |
| DIEDERICH, G. J. | 8303210356 | 50-373 | S |
| DIEDERICH, G. J. | 8303210431 | 50-373 | S |
| DIEDERICH, G. J. | 8303220107 | 50-373 | S |
| DIEDERICH, G. J. | 8303240387 | 50-373 | S |
| DIEDERICH, G. J. | 8303240421 | 50-373 | S |
| DIETCH, R. | 8303040516 | 50-362 | A |
| DIETCH, R. | 8303090282 | 50-206 | P |
| DIETCH, R. | 8303090288* | 50-206 | P |
| DIETCH, R. | 8303100272 | 50-206 | G |
| DIETCH, R. | 8303100346 | 50-361 | G |
| DIETZ, C. R. | 8302010586 | 50-325 | S |
| DIETZ, C. R. | 8303010188 | 50-324 | S |
| DIETZ, C. R. | 8303010271 | 50-325 | S |
| DIETZ, C. R. | 8303010278 | 50-324 | S |
| DIETZ, C. R. | 8303010373 | 50-325 | S |
| DIETZ, C. R. | 8303010381 | 50-325 | S |
| DIETZ, C. R. | 8303010394 | 50-324 | S |
| DIETZ, C. R. | 8303010477 | 50-325 | S |
| DIETZ, C. R. | 8303010514 | 50-324 | S |
| DIETZ, C. R. | 8303040365 | 50-324 | S |
| DIETZ, C. R. | 8303080151 | 50-324 | R |
| DIETZ, C. R. | 8303140302 | 50-324 | S |
| DIETZ, C. R. | 8303140582 | 50-324 | S |
| DIETZ, C. R. | 8303150366 | 50-324 | R |
| DIETZ, C. R. | 8303160217 | 50-325 | S |
| DIETZ, C. R. | 8303160250 | 50-324 | S |
| DIETZ, C. R. | 8303160278 | 50-324 | S |
| DIETZ, C. R. | 8303160348 | 50-325 | S |
| DIETZ, C. R. | 8303160490 | 50-324 | S |
| DIETZ, C. R. | 8303160576 | 50-324 | S |
| DIETZ, C. R. | 8303160901 | 50-324 | S |
| DIETZ, C. R. | 8303180213 | 50-324 | S |
| DIETZ, C. R. | 8303180274 | 50-324 | S |
| DIETZ, C. R. | 8303180311 | 50-325 | S |
| DIETZ, C. R. | 8303180339 | 50-324 | S |
| DIETZ, C. R. | 8303180402 | 50-324 | S |
| DIETZ, C. R. | 8303210314 | 50-324 | S |
| DIETZ, C. R. | 8303210315 | 50-324 | S |
| DIETZ, C. R. | 8303210324 | 50-325 | S |
| DIETZ, C. R. | 8303210366 | 50-324 | S |
| DIETZ, C. R. | 8303210428 | 50-325 | S |
| DIETZ, C. R. | 8303210477 | 50-325 | S |
| DIETZ, C. R. | 8303210615 | 50-324 | G |
| DIETZ, C. R. | 8303210700 | 50-324 | S |
| DIETZ, C. R. | 8303240494 | 50-324 | S |
| DIETZ, R. L. | 8303160441* | 50-538 | R |
| DIGGS, R. M. | 8303090403 | 50-438 | A |
| DIGGS, R. M. | 8303090412 | 50-293 | P |
| DIGGS, R. M. | 8303250088 | 50-315 | P |
| DIGNAN, T. G. | 8302180118 | 50-443 | G |
| DIGNAN, T. G. | 8302180119 | 50-443 | G |
| DIGNAN, T. G. | 8303170426* | 50-443 | G |
| DIGNAN, T. G. | 8303170426* | 50-443 | G |
| DIGNAN, T. G. | 8303170437 | 50-443 | G |
| DIGNAN, T. G. | 8303170437 | 50-443 | G |
| DIGNAN, T. G. | 8303180151 | 50-443 | G |
| DIGNAN, T. G. | 8303180151 | 50-443 | G |
| DIGNAN, T. G. | 8303230199* | 50-443 | G |
| DIGNAN, T. G. | 8303230199* | 50-443 | G |
| DIGNAN, T. G. | 8303290449* | 50-443 | G |
| DIGNAN, T. G. | 8303290449* | 50-443 | G |
| DIIANNI, D. C. | 8303110513 | 50-282 | S |
| DIIANNI, D. C. | 8303140077 | 50-282 | P |
| DIIANNI, D. C. | 8303180131 | 50-282 | P |
| DIIANNI, D. C. | 8303310089 | COMMISSION | |
| DIMEGLIO, A. F. | 8303290481 | 50-193 | R |
| DIMENNA, R. A. | 8303150614 | NUREG | |
| DIMMOCK, L. J. | 8303240597* | 50-10 | G |
| DIRCKS, W. J. | 8201120008* | FOIA | |
| DIRCKS, W. J. | 9205240600* | FOIA | |
| DIRCKS, W. J. | 9205270445* | FOIA | |
| DIRCKS, W. J. | 9208260515* | FOIA | |
| DIRCKS, W. J. | 8211020694* | FOIA | |
| DIRCKS, W. J. | 8411090617 | 50-358 | R |
| DIRCKS, W. J. | 8211190015* | 50-295 | G |
| DIRCKS, W. J. | 8211300421* | FOIA | |
| DIRCKS, W. J. | 8301050367* | 50-358 | A |
| DIRCKS, W. J. | 8302160113 | SECY | |
| DIRCKS, W. J. | 8303030122 | COMMISSION | |
| DIRCKS, W. J. | 8303030362 | 50-275 | P |
| DIRCKS, W. J. | 8303030741* | 50-289 | P |
| DIRCKS, W. J. | 8303040115 | 50-309 | S |
| DIRCKS, W. J. | 8303040180 | COMMISSION | |
| DIRCKS, W. J. | 8303040299 | COMMISSION | |
| DIRCKS, W. J. | 8303090007* | FOIA | |
| DIRCKS, W. J. | 8303090235* | FOIA | |
| DIRCKS, W. J. | 8303100102* | 50-220 | G |
| DIRCKS, W. J. | 8303100487 | 50-20 | P |
| DIRCKS, W. J. | 8303110087 | ORG | |
| DIRCKS, W. J. | 8303110100* | FOIA | |
| DIRCKS, W. J. | 8303150046 | ORG | |
| DIRCKS, W. J. | 8303150052* | REVIEW GRP | |
| DIRCKS, W. J. | 8303180606 | COMMISSION | |
| DIRCKS, W. J. | 8303230063 | 50-358 | A |
| DIRCKS, W. J. | 8303230181* | FOIA | |
| DIRCKS, W. J. | 8303230320 | 50-272 | S |
| DIRCKS, W. J. | 8303230332 | 50-272 | S |
| DIRCKS, W. J. | 8303240054 | REVIEW GRP | |
| DIRCKS, W. J. | 8303240066 | 50-322 | H |
| DIRCKS, W. J. | 8303250136 | 50-358 | R |
| DIRCKS, W. J. | 8303280348* | 10CFR | |
| DIRCKS, W. J. | 8303280353 | PR | |
| DIRCKS, W. J. | 8303290585 | 50-395 | G |
| DIRCKS, W. J. | 8303300027 | 50-213 | P |
| DIRCKS, W. J. | 8303300032* | 50-213 | P |
| DIRCKS, W. J. | 8303300071 | COMMISSION | |
| DIRCKS, W. J. | 8303300305 | 50-370 | G |
| DIRCKS, W. J. | 8303300505* | PR | |
| DIRCKS, W. J. | 8303300652* | FOIA | |
| DIRCKS, W. J. | 8311040047* | FOIA | |
| DIXON, A. J. | 8302100033* | PR | |
| DIXON, O. W. | 8302070066 | 50-395 | G |
| DIXON, O. W. | 8302280681 | 50-395 | P |
| DIXON, O. W. | 8303010175 | 50-395 | G |
| DIXON, O. W. | 8303030204 | 50-395 | S |
| DIXON, O. W. | 8303010283 | 50-395 | S |
| DIXON, O. W. | 8303010449 | 50-395 | S |
| DIXON, O. W. | 8303010461 | 50-395 | S |
| DIXON, O. W. | 8303010495 | 50-395 | S |
| DIXON, O. W. | 8303010556 | 50-395 | S |
| DIXON, O. W. | 8303020690 | PRM | |
| DIXON, O. W. | 8303040367 | 50-395 | S |
| DIXON, O. W. | 8303040553 | 50-395 | S |
| DIXON, O. W. | 8303060005 | 50-395 | P |
| DIXON, O. W. | 8303080463 | 50-395 | P |
| DIXON, O. W. | 8303100091* | 50-395 | P |
| DIXON, O. W. | 8303110035 | 50-395 | P |
| DIXON, O. W. | 8303110341 | 50-395 | R |
| DIXON, O. W. | 8303150154 | 50-395 | P |
| DIXON, O. W. | 8303150341 | 50-395 | S |
| DIXON, O. W. | 8303160237 | 50-395 | P |
| DIXON, O. W. | 8303180229 | 50-395 | S |
| DIXON, O. W. | 8303180238 | 50-395 | S |
| DIXON, O. W. | 8303180258 | 50-395 | S |
| DIXON, O. W. | 8303210345 | 50-395 | G |
| DIXON, O. W. | 8303210394 | 50-395 | G |
| DIXON, O. W. | 8303210400 | 50-395 | G |
| DIXON, O. W. | 8303210521* | 50-395 | G |
| DIXON, O. W. | 8303210659 | 50-395 | G |
| DIXON, O. W. | 8303210726* | 50-395 | G |
| DIXON, O. W. | 8303220135 | 50-395 | P |
| DIXON, O. W. | 8303240530 | 50-395 | S |
| DIXON, O. W. | 8303240583 | 50-395 | S |
| DIXON, O. W. | 8303240585 | 50-395 | S |
| DIXON, O. W. | 8303240596 | 50-395 | S |
| DIXON, O. W. | 8303280100 | 50-395 | G |
| DIXON, O. W. | 8303280117 | 50-395 | J |
| DOCTOR, S. R. | 8303220422 | NUREG | |
| DODA, R. J. | 8303240524 | I&E | |
| DODD, C. V. | 8303140622 | NUREG | |
| DODD, C. V. | 8303290710 | NUREG | |
| DODDS, R. T. | 8303040371* | 50-397 | G |
| DODDS, R. T. | 8303040377* | 50-397 | G |
| DODDS, R. T. | 8303040446* | 50-344 | G |
| DODDS, R. T. | 8303040461* | 50-397 | G |
| DODDS, R. T. | 8303040600* | 50-344 | G |
| DODDS, R. T. | 8303080210* | 50-397 | G |
| DODDS, R. T. | 8303150501* | 50-397 | G |
| DODDS, R. T. | 8303290446* | 50-288 | G |
| DOERFLEIN, L. T. | 8303160546* | 50-333 | G |
| DOLAN, J. C. | 8303240445* | 50-443 | G |
| DOLEZAL, A. | 8303310200* | CONTRACT | |
| DOMANUS, H. M. | 8303140617 | NUREG | |
| DONNELLY, P. M. | 8303170372* | 50-331 | S |
| DONOVAN, R. W. | 8303150230 | 50-344 | F |
| DOOLITTLE, E. W. | 8303300278 | 50-423 | A |
| DORRIS, R. E. | 8303230142 | NUREG | |
| DORSEY, J. A. | 8302030448* | 50-352 | G |
| DORSEY, J. A. | 8303180252 | 50-352 | G |
| DORSEY, J. A. | 8303180252 | 50-352 | G |
| DORSEY, M. | 8303290589 | CONTRACT | |
| DORSEY, M. | 8303310349 | CONTRACT | |
| DOUGHERTY, J. | 9303010408 | 50-322 | G |
| DOUGHERTY, J. | 8303010408 | 50-322 | G |
| DOUGHERTY, J. B. | 8303220241 | 50-322 | G |
| DOUGHERTY, J. B. | 8303220241 | 50-322 | G |
| DOWNEY, T. J. | 8303240077* | 50-322 | H |
| DRAGO, J. P. | 8303290717 | NUREG | |
| DRAIN, D. T. | 8303090014* | FOIA | |
| DRAKE, S. J. | 8303010177 | 50-556 | G |
| DRAPER, E. L. | 8303080405 | 50-458 | S |
| DRAPER, E. L. | 8303080420 | 50-458 | S |
| DREHER, J. | 8303110260* | 50-389 | A |
| DRESS, W. B. | 8303220453 | NUREG | |
| DRISKILL, D. D. | 8303080091* | 50-458 | G |
| DRUGA, R. J. | 8303070046* | 50-334 | S |
| DUBE, R. J. | 8303150084 | 70-734 | |
| DUBE, R. J. | 8303150090 | 70-27 | |
| DUBE, R. J. | 8303150095 | 70-371 | |
| DUBE, R. J. | 8303150100 | 70-2964 | |
| DUBE, R. J. | 8303160608 | 70-27 | |
| DUBE, R. J. | 8303170370 | 70-1113 | |
| DUBOIS, D. L. | 8303010410* | 50-298 | G |
| DUBRY, N. E. | 8303080270* | 50-315 | G |
| DUCK, J. R. | 8303010232 | 50-348 | J |
| DUCK, J. R. | 8303010239 | 50-438 | J |
| DUCK, J. R. | 8303010243 | 50-390 | J |
| DUCK, J. R. | 8303010250 | 50-321 | J |
| DUCK, J. R. | 8303290055 | 50-302 | J |
| DUCK, J. R. | 8303290086 | 50-438 | J |
| DUCK, J. R. | 8303290310 | 50-335 | J |
| DUCK, J. R. | 8303290339 | 50-250 | J |
| DUCK, J. R. | 8303290341 | 50-259 | J |
| DUCK, J. R. | 8303290409 | 50-327 | J |
| DUCK, J. R. | 8303290419 | 50-390 | J |
| DUCK, J. R. | 8303290429 | 50-327 | J |
| DUCK, J. R. | 8303290431 | 50-346 | J |
| DUDLEY, R. F. | 8303310089 | COMMISSION | |
| DUFFY, B. J. | 8303240463* | 50-336 | S |
| DUGGER, L. | 8303140058* | 50-368 | S |
| DUGUAY, D. | 8303080093* | 50-282 | R |
| DUGUAY, D. | 8303150462* | 50-282 | R |
| DUNAWAY, F. R. | 8303170506* | 50-295 | G |
| DUNDAS, W. J. | 8303310035 | 50-266 | J |
| DUNLAP, J. | 8303030185* | 50-293 | G |
| DUNLAP, J. M. | 8303030136* | 50-244 | G |
| DUNLAP, J. M. | 8303030268* | 50-317 | G |
| DUNLAP, J. M. | 8303160544* | 50-29 | G |
| DUNLOP, J. M. | 8303160467* | 50-213 | G |
| DUNN, S. D. | 8303080037* | 50-280 | R |
| DUNN, W. L. | 8303010294* | MISC | |
| DUPONT, S. G. | 8303240372* | 50-237 | G |
| DUPREE, D. C. | 8303080377* | 50-327 | R |
| DUROURE, R. L. | 8303210690* | GA999 | |
| DURR, J. | 8303100281* | 50-443 | G |
| DURR, J. | 8303100322* | 50-272 | G |
| DURR, J. | 8303300340* | 50-286 | G |
| DURR, J. | 8303300504* | 50-309 | G |
| DURR, J. P. | 8303100317* | 50-388 | G |
| DURR, J. P. | 8303240467* | 50-322 | G |
| DUVALL, D. D. | 8303300245 | 50-358 | S |
| DWYER, P. W. | 8303150585 | 50-528 | S |
| DYNNER, A. R. | 8303300023* | 50-322 | G |
| DYNNER, A. R. | 8303300023* | 50-322 | G |
| EAPEN, P. | 8303300323* | 50-293 | G |
| EAPEN, P. K. | 8303020189* | 50-336 | S |
| EAPEN, P. K. | 8303240301* | 50-352 | G |
| EARLES, J. W. | 8303160313* | 50-250 | P |
| EARLEY, A. F. | 8303010354 | 50-322 | G |
| EARLEY, A. F. | 8303010354 | 50-322 | G |
| EASTER, L. | 8303310066 | FOIA | |
| EBENHACK, D. G. | 8303020197 | 71-9139 | |
| ECCLESTON, K. T. | 8303310089 | COMMISSION | |
| ECKERMAN, K. F. | 8303280066 | NUREG | |
| ECKERT, H. J. | 8303040605* | 50-324 | P |
| ECKHARDT, J. H. | 8303040454* | 50-275 | G |
| ECKHARDT, J. H. | 8303150305* | 50-361 | G |

# PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| ECONOMOS, C | 8303300154 | RES |
| ECONOMOS, N | 8303010195* | 50-250 G |
| ECONOMOS, N | 8303210682* | 50-302 G |
| ED, D D | 8303080204 | 50-454 T |
| ED, D D | 8303080204 | 50-454 T |
| EDDINGS, M | 8303150445* | 50-327 R |
| EDDINGS, M | 8303150464* | 50-327 R |
| EDDINGS, M G | 8303080377* | 50-327 R |
| EDDLEMAN, W | 8303150603 | 50-400 G |
| EDDLEMAN, W | 8303220258 | 50-400 G |
| EDDLEMAN, W | 8303220320 | 50-400 G |
| EDDLEMAN, W | 8303300334 | 50-400 G |
| EDDLEMAN, W | 8303300339* | 50-400 G |
| EDDLEMAN, W | 8303300347 | 50-400 G |
| EDDLEMAN, W | 8303300353* | 50-400 G |
| EDELEMAN, M R | 8303170158 | 50-440 E |
| EDELMAN, L M | 8303230221 | 50-443 G |
| EDELMAN, L M | 8303250163 | 50-443 G |
| EDELMAN, M | 8303300406 | TOPREP |
| EDELMAN, M R | 8303170087 | 50-440 E |
| EDELMAN, M R | 8303170254 | 50-440 E |
| EDELMAN, M R | 8303170267 | 50-440 E |
| EDELMAN, M R | 8303170440 | 50-440 S |
| EDELMAN, M R | 8303170462 | 50-440 S |
| EDELMAN, M R | 8303300009 | 50-440 A |
| EDELMAN, M R | 8303300018 | 50-440 E |
| EDELMAN, M R | 8303300199 | 50-440 F |
| EDELMAN, M R | 8303310027* | 50-440 F |
| EDGAR, G L | 8303080497 | 50-537 G |
| EDGAR, G L | 8303290422 | 50-537 G |
| EDGAR, G L | 8303290422 | 50-537 G |
| EDISON, G E | 8303100370 | 50-482 A |
| EDISON, G E | 8303110001 | 50-482 E |
| EDISON, G E | 8303240143 | 50-482 E |
| EDWARDS, C | 8303090273 | 50-454 T |
| EDWARDS, D L | 8303090030 | 40-3453 |
| EDWARDS, D L | 8303090038 | 40-3453 |
| EDWARDS, D W | 8303280021 | 50-29 P |
| EDWARDS, G R | 8303100087* | 50-265 P |
| EGER, K J | 8303100568 | 70-1308 |
| EGGERS, R F | 8303100416 | NUREG |
| EGLE, D M | 8303010560* | 50-112 G |
| EHRLICH, M | 8303100424 | NUREG |
| EICH, E F | 8303220297* | 50-247 R |
| EISENHOWER, E H | 8303100424 | NUREG |
| EISENHUT, D G | 8203150315* | FOIA |
| EISENHUT, D G | 8208060366 | 50-387 P |
| EISENHUT, D G | 8211120231* | 50-373 P |
| EISENHUT, D G | 8302170082 | 50-3 P |
| EISENHUT, D G | 8302170236* | REVIEW GRP |
| EISENHUT, D G | 8302250505 | 50-3 V |
| EISENHUT, D G | 8303010164* | 50-395 P |
| EISENHUT, D G | 8303020104 | 50-312 P |
| EISENHUT, D G | 8303020194 | 50-269 P |
| EISENHUT, D G | 8303020213 | 50-302 P |
| EISENHUT, D G | 8303020287 | 50-322 A |
| EISENHUT, D G | 8303020321 | 50-3 P |
| EISENHUT, D G | 8303020389 | 50-375 W |
| EISENHUT, D G | 8303020394* | 50-375 W |
| EISENHUT, D G | 8303020407* | 50-375 W |
| EISENHUT, D G | 8303020442 | 50-313 P |
| EISENHUT, D G | 8303030179* | 50-361 P |
| EISENHUT, D G | 8303030329 | 50-346 P |
| EISENHUT, D G | 8303030400* | 50-275 P |
| EISENHUT, D G | 8303030420 | 50-346 A |
| EISENHUT, D G | 8303030710 | 50-275 P |
| EISENHUT, D G | 8303030731 | 50-289 P |
| EISENHUT, D G | 8303030747 | 50-275 P |
| EISENHUT, D G | 8303040005 | 50-3 P |
| EISENHUT, D G | 8303040110 | 50-112 P |
| EISENHUT, D G | 8303040224 | 50-361 P |
| EISENHUT, D G | 8303040645 | 50-275 P |
| EISENHUT, D G | 8303040653 | 50-70 P |
| EISENHUT, D G | 8303040654* | 50-70 P |
| EISENHUT, D G | 8303040656* | 50-70 P |
| EISENHUT, D G | 8303090105 | 50-289 G |
| EISENHUT, D G | 8303090110 | 50-289 P |
| EISENHUT, D G | 8303090499* | 50-373 P |
| EISENHUT, D G | 8303100050* | 50-206 G |
| EISENHUT, D G | 8303100491 | 50-358 A |
| EISENHUT, D G | 8303100494 | 50-289 P |
| EISENHUT, D G | 8303110027 | 50-358 A |
| EISENHUT, D G | 8303110047 | 50-423 A |
| EISENHUT, D G | 8303110355 | 50-275 G |
| EISENHUT, D G | 8303110466 | 50-275 P |
| EISENHUT, D G | 8303140195 | 50-289 G |
| EISENHUT, D G | 8303140481* | 50-155 F |
| EISENHUT, D G | 8303140589 | 50-528 A |
| EISENHUT, D G | 8303140596 | 50-322 A |
| EISENHUT, D G | 8303150128 | 50-142 P |
| EISENHUT, D G | 8303150135* | 50-142 P |
| EISENHUT, D G | 8303150324* | 50-267 F |
| EISENHUT, D G | 8303150620 | 50-272 S |
| EISENHUT, D G | 8303160015 | 50-410 A |
| EISENHUT, D G | 8303160024 | 50-470 A |
| EISENHUT, D G | 8303170151* | 50-219 P |
| EISENHUT, D G | 8303170256* | 50-409 P |
| EISENHUT, D G | 8303170271* | 50-29 P |
| EISENHUT, D G | 8303170289* | 50-255 P |
| EISENHUT, D G | 8303170308* | 50-206 P |
| EISENHUT, D G | 8303180128 | 50-289 F |
| EISENHUT, D G | 8303180146 | 50-522 D |
| EISENHUT, D G | 8303180164 | 50-387 P |
| EISENHUT, D G | 8303180190* | 50-387 P |
| EISENHUT, D G | 8303180592 | 50-289 P |
| EISENHUT, D G | 8303180618 | 50-275 P |
| EISENHUT, D G | 8303180623* | 50-275 P |
| EISENHUT, D G | 8303180629* | 50-275 P |
| EISENHUT, D G | 8303180656 | 50-289 V |
| EISENHUT, D G | 8303210018 | 50-289 P |
| EISENHUT, D G | 8303210120 | 50-269 P |
| EISENHUT, D G | 8303220113* | 50-244 P |
| EISENHUT, D G | 8303220209* | 50-213 P |
| EISENHUT, D G | 8303220255* | 50-213 P |
| EISENHUT, D G | 8303220367* | 50-237 P |
| EISENHUT, D G | 8303220376* | 50-155 P |
| EISENHUT, D G | 8303220431 | 50-423 A |
| EISENHUT, D G | 8303220436 | 50-546 A |
| EISENHUT, D G | 8303220446 | 50-317 F |
| EISENHUT, D G | 8303230107* | 50-295 F |
| EISENHUT, D G | 8303230312 | 50-370 P |
| EISENHUT, D G | 8303230339 | 50-387 P |
| EISENHUT, D G | 8303280137 | 50-275 P |
| EISENHUT, D G | 8303280350 | 50-346 P |
| EISENHUT, D G | 8303290263* | 50-334 F |
| EISENHUT, D G | 8303290539 | 50-312 P |
| EISENHUT, D G | 8303290578 | 50-329 A |
| EISENHUT, D G | 8303290667 | 50-361 P |
| EISENHUT, D G | 8303290692 | 50-275 P |
| EISENHUT, D G | 8303290701 | 50-289 V |
| EISENHUT, D G | 8303300090 | 50-373 P |
| EISENHUT, D G | 8303300158 | 50-486 A |
| EISENHUT, D G | 8303300168* | 50-486 A |
| EISENHUT, D G | 8303300711 | 50-289 P |
| EISENHUT, D G | 8303300773 | 50-289 P |
| EISENHUT, D G | 8303310393 | 50-358 A |
| EL-ASHRY, M T | 8303110375 | 50-327 S |
| ELIN, J O | 8303150533* | 50-70 G |
| ELLERSHAW, L E | 8303280171* | GA999 |
| ELLINGWOOD, B | 8303290704 | NUREG |
| ELLINGWOOD, B | 8303290707 | NUREG |
| ELLIS, J | 8303010084 | 50-445 G |
| ELLIS, J | 8303010105 | 50-445 G |
| ELLIS, J | 8303010276 | 50-445 G |
| ELLIS, J | 8303180380 | 50-445 G |
| ELLIS, J | 8303180385 | 50-445 G |
| ELLIS, J | 8303180400 | 50-445 G |
| ELLIS, J | 8303220226 | 50-445 G |
| ELLIS, J | 8303220233* | 50-445 G |
| ELLIS, J | 8303230213 | 50-445 G |
| ELLIS, J | 8303230245 | 50-445 G |
| ELLIS, J | 8303300371 | 50-445 G |
| ELMS, A | 8303080022* | 50-213 R |
| ELMS, A | 8303150525* | 50-213 R |
| ELROD, S A | 8303210453* | 50-335 G |
| ELSASSER | 8303210658 | 50-213 S |
| ELSASSER, T | 8303020314 | 50-293 G |
| ELSASSER, T | 8303280188* | 50-423 G |
| ELSASSER, T | 8303300323* | 50-293 G |
| ELSASSER, T C | 8303030184* | 50-245 G |
| ELSASSER, T C | 8303030201* | 50-245 G |
| ELSASSER, T C | 8303240461* | 50-213 G |
| ELSASSER, T C | 8303300475* | 50-245 G |
| ELSEN, M J | 8303080350* | 27-48 |
| ELY, J D | 8303150193* | 50-259 S |
| EMCH, R | 8303180514 | 50-155 P |
| EMCH, R L | 8303310089 | COMMISSION |
| EMSHWILLER, J R | 8303110049 | FOIA |
| ENGEL, W P | 8303180462 | 71-5874 |
| ENGELKEN, R H | 8303080479 | 50-312 G |
| ENGELKEN, R H | 8303110095* | 50-460 G |
| ENGELKEN, R H | 8303110124* | FOIA |
| ENGELKEN, R H | 8303110139* | FOIA |
| ENGELKEN, R H | 8303150311 | 50-361 G |
| ENGELKEN, R H | 8303290503 | 50-361 G |
| ENGLE, L B | 8303310089 | COMMISSION |
| ERDMAN, C A | 8303140212 | 50-59 H |
| ERICKSON, P B | 8303310089 | COMMISSION |
| ERICSON, D M | 8303100460 | NUREG |
| ERICSON, D M | 8303100558 | NUREG |
| ERNST, M L | 8303290802 | 50-272 S |
| ERNSTTHAL, H L | 8303090124 | FOIA |
| ESKRIDGE, H E | 8303110111 | 70-36 |
| ESPINOSA, G J | 8303030495 | XPORTLIC |
| EURY, L W | 8303150403 | 50-400 G |
| EURY, L W | 8303250142 | 50-261 P |
| EVANS, C A | 8303250008* | 50-285 G |
| EVANS, C D | 8303010416* | 50-261 G |
| EVANS, C D | 8303210693* | 50-280 G |
| EVANS, D H | 8303030413* | 50-329 T |
| EVANS, J | 8303100406* | FOIA |
| EVANS, L J | 8303110078 | 70-371 |
| EVANS, L J | 8303110083 | 70-143 |
| EVANS, L J | 8303110085 | 70-143 |
| EVANS, L J | 8303110089 | 50-397 F |
| EVANS, L J | 8303110094 | 70-371 |
| EVANS, L J | 8303110098 | 50-482 F |
| EVANS, L J | 8303110103 | 70-371 |
| EVANS, L J | 8303140127 | 70-25 |
| EVANS, L J | 8303140135 | 70-1113 |
| EVANS, L J | 8303140144 | 70-143 |
| EVANS, L J | 8303140278 | 70-734 |
| EVANS, L J | 8303140282 | 50-382 F |
| EVANS, L J | 8303140297 | 70-143 |
| EVANS, L J | 8303140299 | 70-1257 |
| EVANS, L J | 8303140303 | 70-143 |
| EVANS, L J | 8303170268 | 70-1113 |
| EVANS, L J | 8303170272 | 70-143 |
| EVANS, L J | 8303170280 | 50-329 F |
| EVANS, M | 8303040151* | 50-275 H |
| EVERETT, J L | 8303170182* | 50-171 I |
| EVERETT, R J | 8303030601 | I&E |
| EVERETT, R J | 8303180237* | 40-8752 |
| EVERETT, R J | 8303180243* | 40-6659 |
| FADDEN, W N | 8302180128* | 50-443 G |
| FAGER, J E | 8303100416 | NUREG |
| FAIRTILE, M B | 8303310089 | COMMISSION |
| FALAHEE, J B | 8303210286* | 50-155 I |
| FALETTI, D W | 8303140696 | NUREG |
| FALKENHEINER, D | 8303040312 | 50-458 G |
| FALKENHEINER, D | 8303300329 | 50-458 G |
| FAN, S S | 8303230256* | 50-443 G |
| FAN, S S | 8303250158* | 50-443 G |
| FAN, S S | 8303250168* | 50-443 G |
| FANNING, G | 8303170354* | 50-304 S |
| FARMER, F G | 8303240268 | 50-302 P |
| FARRAR, D L | 8302280361* | 50-295 G |
| FARRAR, D L | 8303030020 | 50-373 F |
| FARRAR, D L | 8303030528 | 50-10 H |
| FARRAR, D L | 8303140304* | 50-295 G |
| FARRAR, D L | 8303140467* | 50-456 G |
| FARRAR, D L | 8303140482* | 50-373 G |
| FARRELL, E V | 8303160184* | 50-318 S |
| FARRELL, E V | 8303210418* | 50-317 S |
| FARRELL, R E | 8303180396* | 50-10 G |
| FARRELL, R E | 8303240498* | 50-373 G |
| FASANO, A | 8303280173* | 50-320 G |
| FAY, C W | 8303010652 | 50-266 P |
| FAY, C W | 8303010697 | 50-266 P |
| FAY, C W | 8303040530 | 50-266 R |
| FAY, C W | 8303040622 | 50-266 F |
| FAY, C W | 8303080271 | 50-266 G |
| FAY, C W | 8303080430 | 50-266 P |
| FAY, C W | 8303080515 | 50-266 V |
| FAY, C W | 8303090130 | 50-266 P |
| FAY, C W | 8303110106 | 71-9080 |
| FAY, C W | 8303150333 | 50-266 P |
| FAY, C W | 8303160162 | 50-266 P |
| FAY, C W | 8303160221 | 50-301 G |
| FAY, C W | 8303160569 | 50-266 R |
| FAY, C W | 8303160577* | 50-266 R |
| FAY, C W | 8303210111 | 50-266 P |
| FAY, C W | 8303220137 | 50-266 P |
| FAY, C W | 8303280006 | 50-266 P |
| FAY, C W | 8303280037 | 50-266 P |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| FAY, C. W. | 8303290258 | 50-266 P |
| FAY, C. W. | 8303300127 | 50-266 P |
| FAY, C. W. | 8303300293 | 50-266 P |
| FAY, C. W. | 8303310152 | 50-266 S |
| FEDERMAN, P. J. | 8303300651 | NUREG |
| FEEHAN, J. D. | 8303170206* | 50-171 I |
| FEENEY, M. W. | 8303160313* | 50-250 P |
| FEIL, R. A. | 8303040461* | 50-397 G |
| FEIL, R. A. | 8303080210* | 50-397 G |
| FEINBERG, J. D. | 8303040470 | 50-247 G |
| FEINBERG, J. D. | 8303090319 | 50-247 G |
| FEINBERG, J. D. | 8303050329 | 50-247 G |
| FEINBERG, J. D. | 8303300494 | 50-247 G |
| FELLOWS, W. S. | 8303290425* | CONTRACT |
| FELTON, J. M. | 8303010028 | 50-440 G |
| FELTON, J. M. | 8303020005 | 50-206 P |
| FELTON, J. M. | 8303020163 | 50-440 A |
| FELTON, J. M. | 8303020166 | FOIA |
| FELTON, J. M. | 8303020199 | FOIA |
| FELTON, J. M. | 8303030200 | FOIA |
| FELTON, J. M. | 8303030209 | FOIA |
| FELTON, J. M. | 8303030217 | FOIA |
| FELTON, J. M. | 8303030226 | FOIA |
| FELTON, J. M. | 8303090002 | FOIA |
| FELTON, J. M. | 8303090022 | FOIA |
| FELTON, J. M. | 8303090039 | FOIA |
| FELTON, J. M. | 8303090094 | 50-329 G |
| FELTON, J. M. | 8303090121 | FOIA |
| FELTON, J. M. | 8303090135 | FOIA |
| FELTON, J. M. | 8303090149 | FOIA |
| FELTON, J. M. | 8303090164 | FOIA |
| FELTON, J. M. | 8303090180 | FOIA |
| FELTON, J. M. | 8303090187 | FOIA |
| FELTON, J. M. | 8303090191 | 50-348 F |
| FELTON, J. M. | 8303090233 | 50-213 F |
| FELTON, J. M. | 8303090267 | 50-373 F |
| FELTON, J. M. | 8303090345 | FOIA |
| FELTON, J. M. | 8303090361 | FOIA |
| FELTON, J. M. | 8303090369 | 50-348 F |
| FELTON, J. M. | 8303090373 | FOIA |
| FELTON, J. M. | 8303090374 | 50-346 F |
| FELTON, J. M. | 8303090398 | FOIA |
| FELTON, J. M. | 8303090408 | FOIA |
| FELTON, J. M. | 8303090410 | 50-313 F |
| FELTON, J. M. | 8303090415 | FOIA |
| FELTON, J. M. | 8303090429 | FOIA |
| FELTON, J. M. | 8303090430 | 50-312 F |
| FELTON, J. M. | 8303090443 | 50-373 P |
| FELTON, J. M. | 8303090552 | 50-321 F |
| FELTON, J. M. | 8303090561 | 50-320 F |
| FELTON, J. M. | 8303090576 | 50-313 F |
| FELTON, J. M. | 8303090637 | 50-29 F |
| FELTON, J. M. | 8303090671 | 50-29 F |
| FELTON, J. M. | 8303090685 | 50-263 F |
| FELTON, J. M. | 8303100006 | FOIA |
| FELTON, J. M. | 8303100007 | FOIA |
| FELTON, J. M. | 8303100011 | FOIA |
| FELTON, J. M. | 8303100018 | FOIA |
| FELTON, J. M. | 8303100020 | 50-267 F |
| FELTON, J. M. | 8303100028 | 50-206 G |
| FELTON, J. M. | 8303100035 | 50-327 F |
| FELTON, J. M. | 8303100044 | 50-327 F |
| FELTON, J. M. | 8303100068 | 50-265 S |
| FELTON, J. M. | 8303100075 | 50-254 F |
| FELTON, J. M. | 8303100080 | 50-440 A |
| FELTON, J. M. | 8303100088 | 50-395 F |
| FELTON, J. M. | 8303100097 | 50-285 F |
| FELTON, J. M. | 8303100125 | 50-321 F |
| FELTON, J. M. | 8303100148 | 50-369 F |
| FELTON, J. M. | 8303100162 | 50-413 F |
| FELTON, J. M. | 8303100180 | 50-263 F |
| FELTON, J. M. | 8303100216* | 50-329 G |
| FELTON, J. M. | 8303100395 | FOIA |
| FELTON, J. M. | 8303100402 | 50-348 F |
| FELTON, J. M. | 8303100541 | 50-29 F |
| FELTON, J. M. | 8303100551 | 50-346 F |
| FELTON, J. M. | 8303100553 | 50-289 F |
| FELTON, J. M. | 8303100562 | 50-285 F |
| FELTON, J. M. | 8303100566 | 50-285 F |
| FELTON, J. M. | 8303110006 | 50-272 P |
| FELTON, J. M. | 8303110058 | 50-206 G |
| FELTON, J. M. | 8303140129 | 70-2684 |
| FELTON, J. M. | 8303220379 | 50-346 F |
| FELTON, J. M. | 8303230104 | FOIA |
| FELTON, J. M. | 8303230112 | FOIA |
| FELTON, J. M. | 8303230132 | 50-440 A |
| FELTON, J. M. | 8303230143 | 50-10 F |
| FELTON, J. M. | 8303230160 | 50-313 F |
| FELTON, J. M. | 8303230177 | FOIA |
| FELTON, J. M. | 8303230194 | FOIA |
| FELTON, J. M. | 8303230206 | 50-537 H |
| FELTON, J. M. | 8303230293 | FOIA |
| FELTON, J. M. | 8303230302 | 50-263 P |
| FELTON, J. M. | 8303230415 | 50-348 F |
| FELTON, J. M. | 8303230472 | FOIA |
| FELTON, J. M. | 8303230487 | FOIA |
| FELTON, J. M. | 8303230495 | 50-361 P |
| FELTON, J. M. | 8303230503 | 40-1478 |
| FELTON, J. M. | 8303240040 | 70-1193 |
| FELTON, J. M. | 8303240074 | 50-254 F |
| FELTON, J. M. | 8303240092 | 50-305 F |
| FELTON, J. M. | 8303240107 | 50-348 F |
| FELTON, J. M. | 8303240111 | 50-321 F |
| FELTON, J. M. | 8303240113 | 50-269 F |
| FELTON, J. M. | 8303240115 | 50-29 F |
| FELTON, J. M. | 8303240122 | FOIA |
| FELTON, J. M. | 8303240125 | 50-335 F |
| FELTON, J. M. | 8303240379 | 50-155 F |
| FELTON, J. M. | 8303250001 | 50-313 F |
| FELTON, J. M. | 8303250042 | 50-321 F |
| FELTON, J. M. | 8303250051 | 50-315 F |
| FELTON, J. M. | 8303250091 | 50-369 F |
| FELTON, J. M. | 8303250105 | 50-346 F |
| FELTON, J. M. | 8303290058 | 50-213 F |
| FELTON, J. M. | 8303290120 | 50-298 F |
| FELTON, J. M. | 8303290235 | 50-245 F |
| FELTON, J. M. | 8303290542 | 50-387 F |
| FELTON, J. M. | 8303290615 | 50-320 F |
| FELTON, J. M. | 8303290634 | 50-313 F |
| FELTON, J. M. | 8303290669 | 50-313 F |
| FELTON, J. M. | 8303290708 | 50-313 F |
| FELTON, J. M. | 8303290725 | 50-280 F |
| FELTON, J. M. | 8303290831 | 50-302 F |
| FELTON, J. M. | 8303300008 | 50-254 F |
| FELTON, J. M. | 8303300024 | 50-331 F |
| FELTON, J. M. | 8303300039 | ORG |
| FELTON, J. M. | 8303300044 | 50-313 F |
| FELTON, J. M. | 8303300058 | 50-346 F |
| FELTON, J. M. | 8303300223 | 50-206 F |
| FELTON, J. M. | 8303300442 | 50-289 F |
| FELTON, J. M. | 8303300532 | 50-10 F |
| FELTON, J. M. | 8303300581 | 50-277 F |
| FELTON, J. M. | 8303300589* | PR |
| FELTON, J. M. | 8303300610 | 50-313 F |
| FELTON, J. M. | 8303300617 | FOIA |
| FELTON, J. M. | 8303300647 | FOIA |
| FELTON, J. M. | 8303300659 | FOIA |
| FELTON, J. M. | 8303300674 | 50-528 F |
| FELTON, J. M. | 8303300679 | 50-263 F |
| FELTON, J. M. | 8303300691 | 50-275 F |
| FELTON, J. M. | 8303300695 | 50-346 F |
| FELTON, J. M. | 8303300709 | FOIA |
| FELTON, J. M. | 8303300718 | 50-295 F |
| FELTON, J. M. | 8303300738 | 50-254 F |
| FELTON, J. M. | 8303300770 | 50-317 F |
| FELTON, J. M. | 8303300781 | 50-289 F |
| FELTON, J. M. | 8303310001 | 50-346 F |
| FELTON, J. M. | 8303310004 | 50-295 F |
| FELTON, J. M. | 8303310006 | 50-346 F |
| FELTON, J. M. | 8303310009 | 50-387 F |
| FELTON, J. M. | 8303310023 | 50-440 F |
| FELTON, J. M. | 8303310024 | 50-327 F |
| FELTON, J. M. | 8303310044 | 50-244 F |
| FELTON, J. M. | 8303310074 | FOIA |
| FELTON, J. M. | 8303310082 | 50-373 F |
| FELTON, J. M. | 8303310100 | 50-445 F |
| FELTON, J. M. | 8303310113 | 50-321 F |
| FELTON, J. M. | 8303310124 | 50-10 F |
| FELTON, J. M. | 8303310160 | 50-289 F |
| FELTON, J. M. | 8303310167 | 50-321 F |
| FELTON, J. M. | 8303310453 | 50-416 P |
| FELTON, J. M. | 8303310467 | 50-335 F |
| FELTON, J. M. | 8303310478 | 50-309 F |
| FELTON, J. M. | 8303310492 | 50-334 F |
| FERNANDEZ, W. | 8303090195* | 50-333 S |
| FERNANDEZ, W. | 8303140507* | 50-333 S |
| FERSTERSTOCK, J. | 8303300574* | CONTRACT |
| FEY, F. L. | 8303090698* | 50-263 F |
| FIARMAN, S. | 8303140664 | 50-352 A |
| FIEDLER, P. B. | 8302250327 | 50-219 S |
| FIEDLER, P. B. | 8303010069 | 71-5026 |
| FIEDLER, P. B. | 8303040517 | 50-219 G |
| FIEDLER, P. B. | 8303040581 | 50-219 R |
| FIEDLER, P. B. | 8303080341 | 50-219 R |
| FIEDLER, P. B. | 8303110101 | 50-219 P |
| FIEDLER, P. B. | 8303140383 | 50-219 S |
| FIEDLER, P. B. | 8303150380* | 50-219 G |
| FIEDLER, P. B. | 8303150428 | 50-219 R |
| FIEDLER, P. B. | 8303160197 | 50-219 S |
| FIEDLER, P. B. | 8303160214 | 50-219 S |
| FIEDLER, P. B. | 8303160225 | 50-219 S |
| FIEDLER, P. B. | 8303160303 | 50-219 R |
| FIEDLER, P. B. | 8303170285 | 50-219 P |
| FIEDLER, P. B. | 8303170294 | 50-219 P |
| FIEDLER, P. B. | 8303220313 | 50-219 P |
| FIEDLER, P. B. | 8303240403 | 50-219 R |
| FIEDLER, P. B. | 8303250090 | 50-219 S |
| FIEDLER, P. B. | 8303250098 | 50-219 P |
| FIEDLER, P. B. | 8303250104* | 50-219 P |
| FIEDLER, P. B. | 8303280133 | 50-219 D |
| FIEDLER, P. B. | 8303290363 | 50-219 P |
| FIELDS, H. C. | 8303150347* | 50-395 S |
| FIELDS, H. C. | 8303240595* | 50-395 S |
| FIELDS, J. | 8303230180 | CONTRACT |
| FIELDS, J. A. | 8303150617 | CONTRACT |
| FIELDS, J. A. | 8303150658 | CONTRACT |
| FIELDS, J. A. | 8303160660 | CONTRACT |
| FIELDS, J. A. | 8303180063 | CONTRACT |
| FIELDS, J. A. | 8303180072 | CONTRACT |
| FIELDS, J. A. | 8303180080 | CONTRACT |
| FIELDS, J. A. | 8303180092 | CONTRACT |
| FIELDS, J. A. | 8303180528 | CONTRACT |
| FIELDS, J. A. | 8303180684 | CONTRACT |
| FIELDS, J. A. | 8303230162 | CONTRACT |
| FIELDS, J. A. | 8303230172 | CONTRACT |
| FIELDS, J. A. | 8303280332 | CONTRACT |
| FIELDS, J. A. | 8303280337 | CONTRACT |
| FIELDS, J. A. | 8303280341 | 50-289 P |
| FIELDS, J. A. | 8303280351 | CONTRACT |
| FIELDS, J. A. | 8303290084 | CONTRACT |
| FIELDS, J. A. | 8303290096 | CONTRACT |
| FIELDS, J. A. | 8303290175 | CONTRACT |
| FIELDS, J. A. | 8303290187 | CONTRACT |
| FIELDS, J. A. | 8303290194 | CONTRACT |
| FIELDS, J. A. | 8303290281 | CONTRACT |
| FIELDS, J. A. | 8303290324 | CONTRACT |
| FIELDS, J. A. | 8303290568 | CONTRACT |
| FIELDS, J. A. | 8303290579 | CONTRACT |
| FIELDS, J. A. | 8303290759 | CONTRACT |
| FIELDS, J. A. | 8303290770 | CONTRACT |
| FIELDS, J. A. | 8303290785 | CONTRACT |
| FIELDS, J. A. | 8303310052 | CONTRACT |
| FIELDS, J. A. | 8303310139 | CONTRACT |
| FIELDS, W. W. | 8303250143* | 50-261 P |
| FILSON, J. R. | 8303290103* | CONTRACT |
| FINAMORE, B. | 8303220221* | 50-537 G |
| FINAMORE, B. A. | 8303220212 | 50-537 G |
| FINAMORE, B. A. | 8303220212 | 50-537 G |
| FINAMORE, B. A. | 8303250165 | 50-537 G |
| FINAMORE, B. A. | 8303290411 | 50-537 G |
| FINAMORE, B. A. | 8303290411 | 50-537 G |
| FINDLEY, D. | 8303250113 | NUREG |
| FINKEL, A. E. | 8303100382* | 50-412 G |
| FINLEY, N. C. | 8303290742* | WASTE MGT |
| FIORELLI, G. | 8303150506* | 50-528 G |
| FIORELLI, G. | 8303240060* | 70-1193 |
| FISCHER, D. | 8303210160 | 50-272 S |
| FISCHER, D. C. | 8303160065 | 50-272 P |
| FISCHER, D. C. | 8303310089 | COMMISSION |
| FISHER, B. O. | 8303310283 | 40-8698 |
| FISHER, C. R. | 8303010636 | TOPREP |
| FISHER, F. D. | 8303030697 | 70-36 |
| FITTI, C. J. | 8303100021* | FOIA |
| FITZGERALD, J. A. | 8203120424* | 50-250 G |
| FITZGERALD, J. A. | 8303030359* | 50-410 G |
| FITZGERALD, J. A. | 8303040473* | 50-245 G |
| FITZGERALD, J. A. | 8303110250* | 50-528 G |
| FITZPATRICK, S. | 8303170408* | 50-266 G |
| FLACK, E. | 8303230028 | I&E |
| FLACK, E. | 8303230030 | I&E |
| FLACK, E. | 8303280043 | 50-277 G |
| FLAHERTY, T. T. | 8303240155* | FOIA |
| FLEENOR, C. | 8303030769 | CONTRACT |
| FLEENOR, C. | 8303230154 | CONTRACT |
| FLEENOR, C. | 8303230422 | 50-247 F |

# PERSONAL AUTHOR INDEX


| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| FLEENOR, C | 8303310063 | 50-537 A |
| FLEISCHAKER, D | 8303300368 | 50-275 H |
| FLEISCHMANN, R | 8303160567* | 50-277 R |
| FLEISCHMANN, R | 8303180090 | 71-6601 |
| FLEMING, T E | 8303180572 | WASTE MGT |
| FLESSNER, R A | 8303305611* | 50-10 F |
| FLETCHER, C D | 8303300108 | 50-269 P |
| FLETCHER, W D | 8303010312* | 50-454 T |
| FLETCHER, W D | 8303010312* | 50-454 T |
| FLICKER, B | 8303020133* | 50-247 T |
| FLIPPO, T A | 8303010227* | 50-382 G |
| FLIPPO, T A | 8303210631* | 50-382 G |
| FLORY, C | 8303290010 | WASTE MGT |
| FLORY, C A | 8303090349 | 40-1341 |
| FLORY, C A | 8303180631 | WASTE MGT |
| FLORY, C A | 8303180646 | WASTE MGT |
| FLORY, C A | 8303280292 | WASTE MGT |
| FLOYD, J M | 8303040325* | 50-416 S |
| FLOYD, J M | 8303040504* | 50-416 S |
| FLOYD, J M | 8303180292* | 50-416 S |
| FLYNN, M | 8303030222 | CONTRACT |
| FLYNN, M | 8303310343 | CONTRACT |
| FOLEY, T | 8303300321* | 50-247 Q |
| FONNER, R L | 8303020016 | 70-143 |
| FORD, E J | 8303010523* | 50-327 G |
| FORD, J T | 8303090656 | 70-1201 |
| FORD, J T | 8303100514 | 70-1201 |
| FORD, J T | 8303110126 | 70-1201 |
| FORS, R M | 8303240140 | RES |
| FOSTER, C M | 8303140660 | XPORTLIC |
| FOSTER, C M | 8303180189 | XPORTLIC |
| FOSTER, C M | 8303230214 | XPORTLIC |
| FOSTER, C M | 8303290099 | XPORTLIC |
| FOSTER, C M | 8303290118 | XPORTLIC |
| FOSTER, D O | 8303140544 | 50-424 A |
| FOSTER, D O | 8303210348 | 50-424 Q |
| FOSTER, D O | 8303210348 | 50-424 Q |
| FOSTER, D O | 8303210408 | 50-424 S |
| FOSTER, D O | 8303210499 | 50-424 S |
| FOSTER, D O | 8303210660* | 50-424 Q |
| FOSTER, E J | 8303210647 | 50-424 S |
| FOSTER, R G | 8303160276* | 50-250 P |
| FOSTER, R G | 8303160313* | 50-250 P |
| FOSTER, R G | 8303160394* | 50-335 P |
| FOSTER, W E | 8303070126* | QA999 |
| FOSTER, W E | 8303150373* | QA999 |
| FOX, C D | 8303150402 | 50-461 Q |
| FOX, C D | 8303150402 | 50-461 Q |
| FOY, J M | 8303110222 | 50-461 Q |
| FRAGOLA, J R | 8303290717 | NUREG |
| FRAHM, R | 8303030014* | 50-311 S |
| FRAHM, R | 8303030126* | 50-272 S |
| FRAHM, R | 8303030272* | 50-272 S |
| FRAHM, R | 8303030308* | 50-272 S |
| FRAHM, R | 8303080339* | 50-311 S |
| FRAHM, R | 8303090185* | 50-272 S |
| FRAHM, R | 8303090225* | 50-311 S |
| FRAHM, R | 8303090247* | 50-272 S |
| FRAHM, R | 8303140243* | 50-211 S |
| FRAHM, R | 8303140245* | 50-311 S |
| FRAHM, R | 8303140361* | 50-311 S |
| FRAHM, R | 8303140568* | 50-272 S |
| FRAHM, R | 8303140583* | 50-272 S |
| FRAHM, R | 8303180314* | 50-272 S |
| FRAHM, R | 8303180324* | 50-272 S |
| FRAHM, R | 8303180368* | 50-272 S |
| FRAHM, R | 8303180420* | 50-272 S |
| FRAHM, R | 8303180425* | 50-272 S |
| FRAHM, R | 8303210530* | 50-272 S |
| FRAHM, R | 8303210633* | 50-272 S |
| FRALEY, R F | 8212290442* | 50-219 O |
| FRALEY, R F | 8301180041* | 50-237 O |
| FRANCIS, E | 8303090127 | 40-8745 |
| FRANCIS, E | 8303220428 | 40-4492 |
| FRANCIS, J | 8303080161* | 50-206 R |
| FRANK, R A | 8303010294* | MISC |
| FRANK, R A | 8303010300* | MISC |
| FREDRICKSON, P | 8303010523* | 50-327 G |
| FREDRICKSON, P | 8303210585* | 50-390 G |
| FREEMAN, M S | 8303140389* | 50-416 S |
| FREEMAN, M S | 8303150254* | 50-416 S |
| FREEMAN, M S | 8303150448* | 50-416 S |
| FREEMAN, M S | 8303160549* | 50-416 S |
| FREEMAN, M S | 8303160574* | 50-416 S |
| FREEMAN, M S | 8303240423* | 50-416 S |
| FREEMAN, S | 8303160460* | 50-416 S |
| FREEMAN, S | 8303180369* | 50-416 S |
| FRENCH, L D | 8303010638* | 50-29 S |
| FREUDENTHAL, N | 8303020054 | PRM |
| FREUDENTHAL, N | 8303220428 | 40-4492 |
| FRIEDMAN, L F | 8303210687 | I&E |
| FROUNFELKER, R | 8303220306 | 50-155 J |
| FROUNFELKER, R | 8303220310 | 50-255 J |
| FRYE, J H | 8303070106 | 50-142 Q |
| FRYE, J H | 8303140305 | 50-358 Q |
| FRYE, J H | 8303290510 | 50-142 Q |
| FRYER, J | 8303250053* | 50-315 F |
| FULGINITI, S A | 8303280346* | 50-289 P |
| FULLER, C | 8303150253* | 50-267 S |
| FULLER, C | 8303210559* | 50-267 S |
| FULLER, C | 8303210629 | 50-267 S |
| FULLER, C | 8303210635* | 50-267 S |
| FULLER, C | 8303280249* | 50-267 S |
| FULLER, C | 8303280257* | 50-267 S |
| FULLER, C | 8303280265* | 50-267 S |
| FULLER, C F | 8303210546 | 50-267 S |
| FULS, Q M | 8303290385* | 50-416 P |
| FURFARO, J P | 8303150031 | NUREG |
| FURR, B J | 8303280359 | 50-261 F |
| FURR, B J | 8303210371 | 50-261 Q |
| FURST, T J | 8303290818* | CONTRACT |
| GAD, R K | 8302180118 | 50-443 Q |
| GAD, R K | 8302180118 | 50-443 Q |
| GAD, R K | 8303010078 | 50-443 Q |
| GAD, R K | 8303010078 | 50-443 Q |
| GAD, R K | 8303010082* | 50-443 Q |
| GAD, R K | 8303010082* | 50-443 Q |
| GAD, R K | 8303080082 | 50-443 Q |
| GAD, R K | 8303080082 | 50-443 Q |
| GAD, R K | 8303080089* | 50-443 Q |
| GAD, R K | 8303080089* | 50-443 Q |
| GAD, R K | 8303080106* | 50-443 Q |
| GAD, R K | 8303080106* | 50-443 Q |
| GAD, R K | 8303170422 | 50-443 Q |
| GAD, R K | 8303170422 | 50-443 Q |
| GAD, R K | 8303170426* | 50-443 Q |
| GAD, R K | 8303170426* | 50-443 Q |
| GAD, R K | 8303170430* | 50-443 Q |
| GAD, R K | 8303170430* | 50-443 Q |
| GAD, R K | 8303180151 | 50-443 Q |
| GAD, R K | 8303180151 | 50-443 Q |
| GAD, R K | 8303230191 | 50-443 Q |
| GAD, R K | 8303230191 | 50-443 Q |
| GAD, R K | 8303230199* | 50-443 Q |
| GAD, R K | 8303230199* | 50-443 Q |
| GAD, R K | 8303280242 | 50-293 P |
| GAD, R K | 8303290445 | 50-443 Q |
| GAD, R K | 8303290445 | 50-443 Q |
| GAD, R K | 8303290449* | 50-443 Q |
| GAD, R K | 8303290449* | 50-443 Q |
| GADLER, S J | 8303180410 | 50-329 Q |
| GADON, G R | 8303150412* | 50-409 R |
| GADOW, G R | 8303080227* | 50-409 R |
| GAGLIARDO, J E | 8303080091* | 50-458 Q |
| GAGLIARDO, J E | 8303150319 | 50-267 F |
| GAGLIARDO, J E | 8303150392 | 50-267 P |
| GALBREATH, B L | 8303010091 | 50-454 Q |
| GALBREATH, B L | 8303090273 | 50-454 T |
| GALLAGHER, D W | 8303070049* | 50-454 T |
| GALLAGHER, D W | 8303070049* | 50-454 T |
| GALLAGHER, D W | 8303070049* | 50-454 T |
| GALLAGHER, D W | 8303090142 | 50-454 T |
| GALLAGHER, D W | 8303090142 | 50-454 T |
| GALLAGHER, D W | 8303090142 | 50-454 T |
| GALLAGHER, J W | 8303030079 | 50-277 V |
| GALLAGHER, J W | 8303040523 | 50-277 F |
| GALLAGHER, J W | 8303240450* | 50-277 Q |
| GALLIGAN, T J | 8303100214 | 50-293 I |
| GALLO | 8303210710 | 50-220 S |
| GALLO, J | 8303010306 | 50-454 T |
| GALLO, J | 8303010306 | 50-454 T |
| GALLO, J | 8303020041 | 50-155 Q |
| GALLO, J | 8303020041 | 50-155 Q |
| GALLO, J | 8303030357 | 50-454 T |
| GALLO, J | 8303030357 | 50-454 T |
| GALLO, J | 8303030381 | 50-454 Q |
| GALLO, J | 8303030381 | 50-454 Q |
| GALLO, J | 8303040445 | 50-155 Q |
| GALLO, J | 8303040445 | 50-155 Q |
| GALLO, J | 8303170509 | 50-155 Q |
| GALLO, J | 8303170509 | 50-155 Q |
| GALLO, R | 8303030080 | 50-271 S |
| GALLO, R | 8303240511 | 50-271 S |
| GALLO, R | 8303290367 | 50-271 S |
| GALLO, R M | 8302180224* | 50-443 Q |
| GALLO, R M | 8303040462* | 50-322 Q |
| GALLO, R M | 8303080292* | 50-322 Q |
| GALLO, R M | 8303160526* | 50-29 Q |
| GALLUCCI, R H V | 8303150680 | NUREG |
| GAMBLE, D H | 8303110066* | 50-206 Q |
| GAMBLE, D H | 8302110182* | FOIA |
| GANAPATHY, S | 8303020266 | NUREG |
| GANAPOL, B D | 8303230362 | NUREG |
| GARCIA, E | 8303180482 | 50-275 S |
| GARCIA, E M | 8303290480* | 50-141 Q |
| GARCIA, P J | 8303090426 | 40-1162 |
| GARCIA, P J | 8303170172 | 40-6622 |
| GARCIA, P J | 8303170303 | 40-6622 |
| GARCIA, P J | 8303170579 | 40-1162 |
| GARCIA, P J | 8303180102* | 40-3453 |
| GARCIA, P J | 8303180162 | 40-3453 |
| GARDE, B | 8303090364 | FOIA |
| GARDE, B | 8303090437 | 50-373 P |
| GARDE, B | 8303100003 | FOIA |
| GARDE, B P | 8303210274* | 50-329 A |
| GARDNER, R N | 8303110366* | 50-329 Q |
| GARDNER, T A | 8303300576* | CONTRACT |
| GARNER, L | 8303010590* | 50-416 Q |
| GARRETT, J A | 8303280113 | XPORTLIC |
| GARRITY, J H | 8303010472 | 50-309 S |
| GARRITY, J H | 8303010484* | 50-309 S |
| GARRITY, J H | 8303010492 | 50-309 S |
| GARRITY, J H | 8303010504 | 50-309 S |
| GARRITY, J H | 8303030670 | 50-309 P |
| GARRITY, J H | 8303040429 | 50-309 V |
| GARRITY, J H | 8303080503 | 50-309 P |
| GARRITY, J H | 8303140239 | 50-309 R |
| GARRITY, J H | 8303140433 | 50-309 S |
| GARRITY, J H | 8303140495 | 50-309 S |
| GARRITY, J H | 8303140522 | 50-309 S |
| GARRITY, J H | 8303150557* | 50-309 Q |
| GARRITY, J H | 8303160335 | 50-309 S |
| GARRITY, J H | 8303170140 | 50-309 P |
| GARRITY, J H | 8303220100 | 50-309 P |
| GARRITY, J H | 8303220289 | 50-309 P |
| GARRITY, J H | 8303280239 | 50-309 S |
| GARRITY, J H | 8303290237 | 50-309 S |
| GARRITY, J H | 8303290461* | 50-309 Q |
| GARRITY, J H | 8303300235 | 50-309 P |
| GARY, R J | 8303080063 | 50-445 S |
| GARY, R J | 8303080188 | 50-445 S |
| GARY, R J | 8303080334 | 50-445 S |
| GARY, R J | 8303080378 | 50-445 S |
| GARY, R J | 8303220105 | 50-445 K |
| GASSER, R D | 8303310465* | 50-416 P |
| GASSER, R D | 8303310476* | 50-416 P |
| GATES, R | 8303250113 | NUREG |
| GATES, R | 8303280097 | NUREG |
| GATES, R | 8303290114 | NUREG |
| GATES, R | 8303300446 | NUREG |
| GATES, W G | 8303040471* | 50-285 R |
| GAVULA, J J | 8303290567* | 50-237 P |
| GAVUTIS, S | 8303140559* | 50-443 Q |
| GDANSKI, S Z | 8303020105* | 50-247 T |
| GEALY, W J | 8303310103* | CONTRACT |
| GEANURACOS, L | 8303110260* | 50-389 A |
| GEANURACOS, L | 8303110266* | 50-389 A |
| GEARS, G | 8303030761 | 50-277 S |
| GEARS, G | 8303090418 | 50-277 P |
| GEARS, G | 8303090454 | 50-277 F |
| GEARS, G | 8303150683 | 50-277 P |
| GEARS, G | 8303180130 | 50-277 P |
| GEARS, G | 8303290541 | 50-277 F |
| GEARS, G E | 8303020420 | 50-277 P |
| GEARS, G E | 8303110151 | 50-277 P |
| GEARS, G E | 8303110509 | 50-277 P |
| GEBBIE, K M | 8303030680* | CONTRACT |
| GELBARD, F | 8303300527 | NUREG |
| GERDEMAN, F | 8303090115 | 40-7869 |
| GERDEMAN, F W | 8303090021 | 40-7869 |
| GERDEMAN, F W | 8303090064 | 40-8698 |
| GERDEMAN, F W | 8303090134 | 40-8698 |
| GERDEMAN, F W | 8303090617 | 40-8674 |
| GERDEMAN, F W | 8303160655 | 40-8698 |
| GERDEMAN, F W | 8303170320 | 40-7869 |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | |
|---|---|---|---|
| GERDEMAN, F. W. | 8303170324 | 40-8674 | |
| GERDEMAN, F. W. | 8303170331 | 40-8698 | |
| GERDEMAN, F. W. | 8303220435 | 40-8698 | |
| GERDEMAN, F. W. | 8303300189 | 40-8698 | |
| GERETY, H. F. | 8303150418 | 50-289 | J |
| GERETY, H. F. | 8303180360 | 50-289 | J |
| GERETY, H. F. | 8303220089 | 50-289 | J |
| GERNER, L. | 8303300744* | 50-254 | F |
| GERSTNER, W. C. | 8303140186* | 50-461 | G |
| GERTON, R. E. | 8303110028* | 71-6387 | |
| GERTSCH, A. J. | 8303080059* | 50-313 | R |
| GERTSCH, A. J. | 8303150384* | 50-313 | R |
| GEST, R. E. | 8303021151 | 70-754 | |
| GIBBONS, T. D. | 8303010341* | 50-390 | G |
| GIBBONS, T. D. | 8303210451* | 50-424 | G |
| GIBSON, A. F. | 8303040120* | 50-309 | S |
| GIBSON, A. F. | 8303210619* | 70-143 | |
| GIBSON, G. W. | 8303180549 | RES | |
| GIBSON, J. | 8303080207* | 50-336 | R |
| GIBSON, J. | 8303150433* | 50-336 | R |
| GIESLER, C. W. | 8303010277 | 50-305 | P |
| GIESLER, C. W. | 8303010559 | 50-305 | V |
| GIESLER, C. W. | 8303010690 | 50-305 | V |
| GIESLER, C. W. | 8303030083 | 50-305 | R |
| GIESLER, C. W. | 8303080122 | 50-305 | S |
| GIESLER, C. W. | 8303080163 | 50-305 | R |
| GIESLER, C. W. | 8303080444 | 50-305 | P |
| GIESLER, C. W. | 8303100316 | 50-305 | P |
| GIESLER, C. W. | 8303110373 | 50-305 | P |
| GIESLER, C. W. | 8303140329 | 50-305 | P |
| GIESLER, C. W. | 8303140396 | 50-305 | G |
| GIESLER, C. W. | 8303140400 | 50-305 | S |
| GIESLER, C. W. | 8303140493 | 50-305 | S |
| GIESLER, C. W. | 8303140511 | 50-305 | P |
| GIESLER, C. W. | 8303150287 | 50-305 | G |
| GIESLER, C. W. | 8303160315 | 50-305 | P |
| GIESLER, C. W. | 8303160352 | 50-305 | R |
| GIESLER, C. W. | 8303170419* | 50-305 | G |
| GIESLER, C. W. | 8303220335 | 50-305 | P |
| GIESLER, C. W. | 8303220342 | 50-305 | J |
| GIESLER, C. W. | 8303220350 | 50-305 | I |
| GIESLER, C. W. | 8303240096* | 50-305 | F |
| GIESLER, C. W. | 8303240225 | 50-305 | S |
| GIESLER, C. W. | 8303240247 | 50-305 | J |
| GIESLER, C. W. | 8303240565 | 50-305 | S |
| GILBERT, L. D. | 8303010427* | 50-382 | G |
| GILBERT, R. A. | 8302040188 | 50-237 | P |
| GILBERT, R. A. | 8303070149 | 50-237 | P |
| GILBERT, R. A. | 8303140385 | 50-237 | G |
| GILBERT, R. A. | 8303310089 | COMMISSION | |
| GILDENHORN, A. J. | 8303100001 | CONTRACT | |
| GILDENHORN, A. J. | 8303300676 | CONTRACT | |
| GILES, M. M. | 8303180613 | RES | |
| GILINSKY, V. | 8303080050 | 50-443 | G |
| GILLEN, D. M. | 8303180154 | 40-8681 | |
| GILLESPIE, F. P. | 8303090634* | ORG | |
| GILLESPIE, F. P. | 8303090647* | ORG | |
| GILLESPIE, F. P. | 8303090661* | ORG | |
| GILLETT, W. T. | 8303150531* | 50-315 | R |
| GILLETT, W. T. | 8303150544* | 50-316 | R |
| GILMAN, T. | 8303150611 | 50-237 | S |
| GILOMEN, B. R. | 8303010171 | 50-329 | G |
| GILOMEN, B. R. | 8303010171 | 50-329 | G |
| GILRAY, J. W. | 8303140086* | 50-443 | G |
| GINSBERG, T. | 8303040104 | RES | |
| GINSBERG, T. | 8303160687 | RES | |
| GINSBERG, T. | 8303300378 | RES | |
| GIRARD, E. H. | 8303210497* | 50-424 | G |
| GITLIN, D. | 8303170275 | 50-440 | G |
| GIVENS, J. I. | 8303290317* | 50-390 | G |
| GLASSPIEGEL, H. | 8303010263 | 50-440 | G |
| GLASSPIEGEL, H. | 8303010263 | 50-440 | G |
| GLASSPIEGEL, H. | 8303010516 | 50-440 | G |
| GLASSPIEGEL, H. | 8303010516 | 50-440 | G |
| GLASSPIEGEL, H. | 8303070068 | 50-440 | G |
| GLASSPIEGEL, H. | 8303070068 | 50-440 | G |
| GLASSPIEGEL, H. | 8303070076 | 50-440 | G |
| GLASSPIEGEL, H. | 8303070076 | 50-440 | G |
| GLEASON, J. P. | 8303010101 | 50-483 | G |
| GLEASON, J. P. | 8303010141 | 50-247 | G |
| GLEASON, J. P. | 8303020061 | 50-247 | G |
| GLEASON, J. P. | 8303090307 | 50-247 | G |
| GLEASON, J. P. | 8303090376 | 50-247 | G |
| GLEASON, J. P. | 8303100232 | 50-247 | G |
| GLEASON, J. P. | 8303110198 | 50-247 | G |
| GLEASON, J. P. | 8303240399 | 50-247 | G |
| GLEASON, J. P. | 8303310300 | 50-247 | G |
| GLENN, J. | 8303040455 | I&E | |
| GLENN, J. | 8303140011* | 50-346 | H |
| GLENN, J. | 8303210687 | I&E | |
| GLOERSEN, W. B. | 8303150606* | 50-254 | G |
| GLOERSEN, W. B. | 8303210097* | 50-282 | G |
| GODDARD, P. J. | 8303110046 | 50-309 | G |
| GODDARD, R. J. | 8303230215 | 50-155 | G |
| GODDARD, R. J. | 8303290062 | 50-309 | G |
| GODDARD, R. J. | 8303300006 | 50-309 | G |
| GODDARD, R. J. | 8303310145 | 50-309 | G |
| GODY, A. T. | 8303030136* | 50-244 | G |
| GODY, A. T. | 8303030185* | 50-293 | G |
| GODY, A. T. | 8303030206* | 50-320 | G |
| GODY, A. T. | 8303030268* | 50-317 | G |
| GODY, A. T. | 8303040537* | 70-135 | |
| GODY, A. T. | 8303100332* | 70-135 | |
| GODY, A. T. | 8303160467* | 50-213 | G |
| GODY, A. T. | 8303160472* | 70-371 | |
| GODY, A. T. | 8303160492* | 50-289 | G |
| GODY, A. T. | 8303160563* | 70-820 | |
| GODY, A. T. | 8303160544* | 50-29 | G |
| GODY, A. T. | 8303210330 | 70-1143 | |
| GODY, A. T. | 8303240544* | 70-33 | |
| GODY, A. T. | 8303240568* | 50-333 | G |
| GODY, A. T. | 8303290331* | 50-184 | G |
| GODY, A. T. | 8303290381* | 50-77 | G |
| GODY, A. T. | 8303300392* | 50-170 | G |
| GODY, A. T. | 8303300403* | 70-820 | |
| GOFF, M. | 8303300056* | WASTE MGT | |
| GOLDBERG, J. H. | 8303040614 | 50-498 | V |
| GOLDBERG, J. H. | 8303160382 | 50-498 | K |
| GOLDBERG, J. H. | 8303250084 | 50-498 | A |
| GOLDBERG, J. H. | 8303250089 | 50-498 | A |
| GOLDBERG, S. C. | 8303010297 | 50-454 | T |
| GOLDEN, J. C. | 8303080200 | 50-454 | T |
| GOLDEN, M. P. | 8303080297 | 50-286 | J |
| GOLDSMITH, M. W. | 8303250157 | 50-322 | T |
| GOLLER, K. R. | 8205280028* | 50-206 | P |
| GONANO, L. | 8303250113 | NUREG | |
| GONANO, L. | 8303280097 | NUREG | |
| GONANO, L. | 8303280114 | NUREG | |
| GONANO, L. | 8303300446 | NUREG | |
| GOODWIN, D. C. | 8303240608* | 50-296 | S |
| GOODWIN, E. F. | 8303100107 | 50-219 | O |
| GOODWIN, E. F. | 8303290135 | 50-522 | A |
| GORMAN, B. | 8303250065* | 50-333 | S |
| GORMAN, J. C. | 8303290514 | 50-329 | G |
| GORMLEY, P. C. | 8303090599* | CONTRACT | |
| GOTTLIEB, S. E. | 8303290596* | CONTRACT | |
| GOWER, G. | 8303250034* | 50-438 | G |
| GRAASS, J. J. | 8303080131* | 50-389 | A |
| GRABER, L. | 8303090413 | FOIA | |
| GRABER, L. | 8303230174 | FOIA | |
| GRABER, L. D. | 8303020186 | FOIA | |
| GRACE, J. N. | 8303090275 | 50-537 | A |
| GRACE, J. N. | 8303180119 | 50-537 | E |
| GRACE, J. N. | 8303210113 | 50-537 | E |
| GRACE, J. N. | 8303280078 | 50-537 | E |
| GRACE, J. N. | 8303280080* | 50-537 | E |
| GRACE, R. H. | 8303080012 | 50-309 | R |
| GRAESSER, K. L. | 8303010662 | 50-295 | S |
| GRAESSER, K. L. | 8303140342 | 50-295 | S |
| GRAESSER, K. L. | 8303140350 | 50-295 | S |
| GRAESSER, K. L. | 8303140460 | 50-295 | S |
| GRAESSER, K. L. | 8303140516 | 50-304 | S |
| GRAESSER, K. L. | 8303140550 | 50-304 | S |
| GRAESSER, K. L. | 8303140587 | 50-304 | S |
| GRAESSER, K. L. | 8303150349 | 50-295 | R |
| GRAESSER, K. L. | 8303170335 | 50-304 | S |
| GRAESSER, K. L. | 8303170497 | 50-295 | S |
| GRAESSER, K. L. | 8303240198 | 50-304 | S |
| GRAESSER, K. L. | 8303280293 | 50-295 | R |
| GRAHAM, M. J. | 8303150272* | 50-289 | P |
| GRAMM, R. A. | 8302180224* | 50-443 | G |
| GRANGE, G. | 8303300451* | 50-289 | F |
| GRANGE, G. J. | 8303100560* | 50-289 | F |
| GRANT, J. | 8303150600* | 50-410 | G |
| GRANT, J. | 8303240575* | 50-354 | G |
| GRANT, W. B. | 8303030457* | 50-263 | G |
| GRANT, W. B. | 8303220229* | 50-329 | G |
| GRANTHAM, B. | 8303040550* | GA999 | |
| GRANTHAM, B. | 8303040582* | GA999 | |
| GRAVES, R. H. | 8303030135 | 50-213 | S |
| GRAVES, R. H. | 8303080018 | 50-213 | R |
| GRAVES, R. H. | 8303150524 | 50-213 | R |
| GRAY, E. | 8303240591* | 50-289 | G |
| GRAY, E. H. | 8303030183* | 50-423 | G |
| GRAY, E. H. | 8303240380* | 50-352 | G |
| GRAY, E. H. | 8303300475* | 50-245 | G |
| GRAY, E. H. | 8303300504* | 50-309 | G |
| GRAY, W. A. | 8303110317* | 50-317 | G |
| GREEN, H. J. | 8303040374 | 50-296 | S |
| GREEN, H. J. | 8303040381 | 50-296 | S |
| GREEN, H. J. | 8303040426 | 50-260 | S |
| GREEN, H. J. | 8303040434 | 50-328 | S |
| GREEN, H. J. | 8303040465 | 50-328 | S |
| GREEN, H. J. | 8303040492 | 50-259 | S |
| GREEN, H. J. | 8303040558 | 50-259 | S |
| GREEN, H. J. | 8303040575 | 50-328 | S |
| GREEN, H. J. | 8303140492 | 50-327 | S |
| GREEN, H. J. | 8303140509 | 50-260 | S |
| GREEN, H. J. | 8303140526 | 50-327 | S |
| GREEN, H. J. | 8303140548 | 50-327 | S |
| GREEN, H. J. | 8303140601 | 50-259 | S |
| GREEN, H. J. | 8303150185 | 50-259 | S |
| GREEN, H. J. | 8303150248 | 50-296 | S |
| GREEN, H. J. | 8303150297 | 50-296 | S |
| GREEN, H. J. | 8303150300 | 50-259 | S |
| GREEN, H. J. | 8303150466 | 50-296 | S |
| GREEN, H. J. | 8303150472 | 50-327 | S |
| GREEN, H. J. | 8303160419 | 50-260 | S |
| GREEN, H. J. | 8303160432 | 50-296 | S |
| GREEN, H. J. | 8303160531 | 50-296 | S |
| GREEN, H. J. | 8303210299 | 50-327 | S |
| GREEN, H. J. | 8303210319 | 50-328 | S |
| GREEN, H. J. | 8303210322 | 50-328 | S |
| GREEN, H. J. | 8303210423 | 50-259 | S |
| GREEN, H. J. | 8303210462 | 50-327 | S |
| GREEN, H. J. | 8303220086 | 50-260 | S |
| GREEN, H. J. | 8303220176 | 50-259 | S |
| GREEN, H. J. | 8303220318 | 50-260 | S |
| GREEN, H. J. | 8303240410 | 50-327 | S |
| GREEN, H. J. | 8303240470 | 50-328 | S |
| GREEN, H. J. | 8303240598 | 50-259 | S |
| GREEN, H. J. | 8303240606 | 50-296 | S |
| GREEN, R. W. | 8303170455* | 70-2837 | |
| GREENAWAY, W. | 8303150272* | 50-289 | P |
| GREENBERG, E. V. | 8303230203 | 50-537 | H |
| GREENBERG, E. V. | 8303230203 | 50-537 | H |
| GREENBERG, E. V. | 8303230203 | 50-537 | H |
| GREENBERG, J. | 8303300409 | 50-454 | T |
| GREENBERG, J. | 8303300409 | 50-454 | T |
| GREENBERG, J. | 8303300409 | 50-454 | T |
| GREENBERG, J. | 8303300409 | 50-454 | T |
| GREENE, G. A. | 8303040104 | RES | |
| GREENE, G. A. | 8303230512 | NUREG | |
| GREENE, G. A. | 8303300578 | RES | |
| GREENMAN, E. G. | 8303040462* | 50-322 | G |
| GREEVES, J. T. | 8303290724 | WASTE MGT | |
| GREGER, L. R. | 8303030457* | 50-263 | G |
| GREGER, L. R. | 8303030584* | 70-1308 | |
| GREGER, L. R. | 8303030598* | 50-266 | G |
| GREGER, L. R. | 8303040574* | 50-295 | G |
| GREGER, L. R. | 8303140265* | 50-254 | G |
| GREGER, L. R. | 8303140300* | 50-461 | G |
| GREGER, L. R. | 8303210614* | 50-341 | G |
| GREGER, L. R. | 8303210637* | 50-315 | G |
| GREGER, L. R. | 8303220229* | 50-329 | G |
| GREGORY, W. S. | 8303110118 | RES | |
| GREGORY, W. S. | 8303160175 | RES | |
| GRELLA, A. W. | 8303100137 | MISC | |
| GRESHAM, J. B. | 8303170208* | ORG | |
| GRIER, B. H. | 8303110023* | 50-272 | G |
| GRIER, B. H. | 8303110048* | 50-334 | P |
| GRIFFIN, J. M. | 8303010415 | 50-313 | P |
| GRIFFIN, J. M. | 8303010418 | 50-313 | P |
| GRIFFIN, J. M. | 8303040348 | 50-313 | P |
| GRIFFIN, J. M. | 8303150473 | 50-313 | P |
| GRIFFIN, J. M. | 8303210234 | 50-313 | P |
| GRIFFIN, J. M. | 8303210277 | 50-313 | P |
| GRIFFITH, J. M. | 8303140628 | NUREG | |
| GRIMES, B. K. | 8303090035* | FOIA | |
| GRIMES, J. C. | 8303210749* | 50-361 | P |
| GRIMESEY, R. A. | 8303180568 | RES | |
| GROCE, R. H. | 8303150424 | 50-309 | R |
| GROSSMAN, H. | 8303170498 | 50-460 | G |
| GROSSMAN, H. | 8303290501 | 50-460 | G |
| GROWCOCK, F. B. | 8303090555 | RES | |

# PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| GRUNWALD, T. J. | 8201040114* | FOIA |
| GUCWA, L. T. | 8303010551 | 50-321 V |
| GUCWA, L. T. | 8303020010 | 50-321 P |
| GUCWA, L. T. | 8303040463 | 50-321 P |
| GUCWA, L. T. | 8303090290 | 50-321 P |
| GUCWA, L. T. | 8303140453 | 50-321 S |
| GUCWA, L. T. | 8303210387 | 50-321 Q |
| GUCWA, L. T. | 8303210464* | 50-321 Q |
| GUCWA, L. T. | 8303210639* | 50-321 Q |
| GUENERO, L. | 8303030231* | CONTRACT |
| GUILD, R. | 8303230192 | 50-413 Q |
| GUILD, R. | 8303230192 | 50-413 Q |
| GUILD, R. | 8303310345 | 50-413 Q |
| GUILD, R. | 8303310345 | 50-413 Q |
| GUILL, P. | 8303180338* | 50-287 S |
| GUILL, P. | 8303180408* | 50-269 S |
| GUILL, P. F. | 8303160560* | 50-269 S |
| GUILL, P. F. | 8303160572* | 50-269 S |
| GULDEMOND, W. | 8303170540* | 50-373 Q |
| GULDEMOND, W. G. | 8303170519* | 50-373 Q |
| GULDEMOND, W. G. | 8303170557* | 50-10 Q |
| GULDEMOND, W. G. | 8303240597* | 50-10 Q |
| GUPPY, J. G. | 8303040155 | 50-537 A |
| GUPPY, J. G. | 8303310068 | 50-537 A |
| GURA, A. | 8303110260* | 50-389 A |
| GURA, L. | 8303110266* | 50-389 A |
| GUSTAFSON, R. B. | 8303010696 | 70-371 |
| GUSTAVE, R. P. | 8303020072* | CONTRACT |
| GUSTAVE, R. P. | 8303020082* | CONTRACT |
| GUSTAVE, R. P. | 8303020431* | CONTRACT |
| GUSTAVE, R. P. | 8303030223* | 50-320 P |
| GUSTAVE, R. P. | 8303030231* | CONTRACT |
| GUSTAVE, R. P. | 8303030244* | CONTRACT |
| GUSTAVE, R. P. | 8303030256* | CONTRACT |
| GUSTAVE, R. P. | 8303030267* | CONTRACT |
| GUSTAVE, R. P. | 8303030766* | CONTRACT |
| GUSTAVE, R. P. | 8303030775* | CONTRACT |
| GUSTAVE, R. P. | 8303090668* | CONTRACT |
| GUSTAVE, R. P. | 8303150618* | CONTRACT |
| GUSTAVE, R. P. | 8303150663* | CONTRACT |
| GUSTAVE, R. P. | 8303160056 | CONTRACT |
| GUSTAVE, R. P. | 8303160097* | CONTRACT |
| GUSTAVE, R. P. | 8303170019* | CONTRACT |
| GUSTAVE, R. P. | 8303180067* | CONTRACT |
| GUSTAVE, R. P. | 8303180075* | CONTRACT |
| GUSTAVE, R. P. | 8303180086* | CONTRACT |
| GUSTAVE, R. P. | 8303180096* | CONTRACT |
| GUSTAVE, R. P. | 8303180536* | CONTRACT |
| GUSTAVE, R. P. | 8303180688* | CONTRACT |
| GUSTAVE, R. P. | 8303230158* | CONTRACT |
| GUSTAVE, R. P. | 8303230167* | CONTRACT |
| GUSTAVE, R. P. | 8303230430* | 50-247 F |
| GUSTAVE, R. P. | 8303280333* | CONTRACT |
| GUSTAVE, R. P. | 8303290185* | CONTRACT |
| GUSTAVE, R. P. | 8303290196* | CONTRACT |
| GUSTAVE, R. P. | 8303290228* | CONTRACT |
| GUSTAVE, R. P. | 8303290292* | CONTRACT |
| GUSTAVE, R. P. | 8303290425* | CONTRACT |
| GUSTAVE, R. P. | 8303290584* | CONTRACT |
| GUSTAVE, R. P. | 8303290608* | CONTRACT |
| GUSTAVE, R. P. | 8303290752* | CONTRACT |
| GUSTAVE, R. P. | 8303290765* | CONTRACT |
| GUSTAVE, R. P. | 8303290779* | CONTRACT |
| GUSTAVE, R. P. | 8303290790* | CONTRACT |
| GUSTAVE, R. P. | 8303290853* | CONTRACT |
| GUSTAVE, R. P. | 8303310056* | CONTRACT |
| GUSTAVE, R. P. | 8303310067* | 50-537 A |
| GUSTAVE, R. P. | 8303310143* | CONTRACT |
| GUSTAVE, R. P. | 8303310336* | CONTRACT |
| GUSTAVE, R. P. | 8303310348* | CONTRACT |
| GUTTERMAN, A. H. | 8303150394 | 50-498 Q |
| GUTTERMAN, A. H. | 8303150394 | 50-498 Q |
| GUTTERMAN, A. H. | 8303310335 | 50-498 Q |
| GUTTERMAN, A. H. | 8303310335 | 50-498 Q |
| GWYNN, T. P. | 8303110143* | 50-358 U |
| HAAS, P. R. | 8303230142 | NUREG |
| HAASS, W. P. | 8212220088* | TOPREP |
| HACKNEY, C. A. | 8303010247* | 50-313 Q |
| HAFNER, B. | 8303090404 | FOIA |
| HAFNER, B. | 8303090425 | FOIA |
| HAGAN, T. F. | 8303090422* | CONTRACT |
| HAGAN, T. F. | 8303100005* | CONTRACT |
| HAGAN, T. F. | 8303160085* | CONTRACT |
| HAGAN, T. F. | 8303230175* | CONTRACT |
| HAGAN, T. F. | 8303230182* | CONTRACT |
| HAGAN, T. F. | 8303280102* | CONTRACT |
| HAGAN, T. F. | 8303280339* | CONTRACT |
| HAGAN, T. F. | 8303280346* | 50-289 P |
| HAGAN, T. F. | 8303280354* | CONTRACT |
| HAGAN, T. F. | 8303290091* | CONTRACT |
| HAGAN, T. F. | 8303290103* | CONTRACT |
| HAGAN, T. F. | 8303290192* | CONTRACT |
| HAGAN, T. F. | 8303290197* | CONTRACT |
| HAGAN, T. F. | 8303290336* | CONTRACT |
| HAGAN, T. F. | 8303290574* | CONTRACT |
| HAGAN, T. F. | 8303300677* | CONTRACT |
| HAGER, C. | 8303140384* | 50-219 S |
| HAGEY, H. | 8303010014 | CONTRACT |
| HAGEY, H. | 8303300555 | CONTRACT |
| HAGUE, R. L. | 8303170406* | 50-266 Q |
| HAIRSTON, J. J. | 8303310099* | FOIA |
| HAIRSTON, W. G. | 8303040323* | 50-348 S |
| HAIRSTON, W. G. | 8303040334* | 50-348 S |
| HAIRSTON, W. G. | 8303180384* | 50-348 S |
| HAIRSTON, W. G. | 8303210384* | 50-348 S |
| HAIRSTON, W. G. | 8303210468* | 50-364 S |
| HALAPATZ, J. | 8104230100* | 50-387 P |
| HALAPATZ, J. | 8302040541* | 50-387 P |
| HALAPATZ, J. | 8302040546* | 50-387 P |
| HALAPATZ, J. | 8302040551* | 50-387 P |
| HALAPATZ, J. | 8302040557* | 50-387 P |
| HALE, C. J. | 8303070085* | GA999 |
| HALE, C. J. | 8303080376* | GA999 |
| HALE, R. | 8303030231* | CONTRACT |
| HALL, B. L. | 8303150578* | 50-261 Q |
| HALL, B. L. | 8303280291* | 50-321 Q |
| HALL, B. L. | 8303290485* | 50-338 Q |
| HALL, D. P. | 8302080314 | 50-461 S |
| HALL, D. P. | 8303040347 | 50-461 K |
| HALL, D. P. | 8303080263* | 50-461 Q |
| HALL, D. P. | 8303170398 | 50-461 Q |
| HALL, D. P. | 8303170548 | 50-461 A |
| HALL, D. P. | 8303240215 | 50-461 A |
| HALL, D. P. | 8303240222 | 50-461 Q |
| HALL, J. | 8303280140 | WASTE MGT |
| HALL, J. L. | 8303020225 | 71-492 |
| HAMADA, G. | 8303040362* | 50-344 Q |
| HAMANO, N. | 8303020266 | NUREG |
| HAMLIN, J. B. | 8303250141 | 50-382 Q |
| HAMLIN, J. B. | 8303250141 | 50-382 Q |
| HAMPTON, J. W. | 8303100174* | 50-413 F |
| HANCOCK, J. A. | 8303010264 | 50-302 S |
| HANCOCK, J. A. | 8303010272 | 50-302 S |
| HAND, C. H. | 8303040435 | 50-537 Q |
| HANNES, P. H. | 8303080292* | 50-322 Q |
| HANNETT, B. | 8303180603* | XPORTLIC |
| HANNETT, B. A. | 8303020332 | XPORTLIC |
| HANNETT, B. A. | 8303020337* | XPORTLIC |
| HANNETT, B. A. | 8303020449 | XPORTLIC |
| HANNETT, B. A. | 8303020457 | XPORTLIC |
| HANNETT, B. A. | 8303020467 | XPORTLIC |
| HANNETT, B. A. | 8303020472 | XPORTLIC |
| HANNETT, B. A. | 8303020476 | XPORTLIC |
| HANNETT, B. A. | 8303030194* | XPORTLIC |
| HANNETT, B. A. | 8303040017 | XPORTLIC |
| HANNETT, B. A. | 8303040121 | XPORTLIC |
| HANNETT, B. A. | 8303180598 | XPORTLIC |
| HANNUM, W. H. | 8303030003 | 50-201 P |
| HANNUM, W. H. | 8303290260 | 50-201 P |
| HANSEN, W. | 8303250034* | 50-498 Q |
| HANSON, R. J. | 8303100460 | NUREG |
| HANSON, R. J. | 8303100558 | NUREG |
| HARBOUR, J. | 8303170498 | 50-460 Q |
| HARBOUR, J. | 8303290501 | 50-460 Q |
| HARDIN, A. K. | 8303210501* | 50-83 Q |
| HARDING, M. R. | 8303040438* | 50-328 S |
| HARDING, M. R. | 8303040472* | 50-328 S |
| HARDING, M. R. | 8303040588* | 50-328 S |
| HARDING, M. R. | 8303100053* | 50-327 F |
| HARDING, M. R. | 8303140501* | 50-327 S |
| HARDING, M. R. | 8303140539* | 50-327 S |
| HARDING, M. R. | 8303140554* | 50-327 S |
| HARDING, M. R. | 8303150475* | 50-327 S |
| HARDING, M. R. | 8303210308* | 50-327 S |
| HARDING, M. R. | 8303210321* | 50-328 S |
| HARDING, M. R. | 8303210327* | 50-328 S |
| HARDING, M. R. | 8303210469* | 50-327 S |
| HARDING, M. R. | 8303240412* | 50-327 S |
| HARDING, M. R. | 8303240479* | 50-328 S |
| HARMON, D. W. | 8303150698 | XPORTLIC |
| HARMON, D. W. | 8303160045 | XPORTLIC |
| HARPSTER, T. L. | 8303040644* | TOPREP |
| HARPSTER, T. L. | 8303110064 | PROJ |
| HARRAN, G. | 8303080133* | 50-245 R |
| HARRAN, G. | 8303080144* | 50-245 R |
| HARRAN, G. | 8303150421* | 50-245 R |
| HARRINGTON, R. M. | 8303160009 | NUREG |
| HARRINGTON, W. D. | 8303040432 | 50-293 V |
| HARRINGTON, W. D. | 8303040513 | 50-293 Q |
| HARRINGTON, W. D. | 8303040547 | 50-293 P |
| HARRINGTON, W. D. | 8303040548 | 50-293 P |
| HARRINGTON, W. D. | 8303070115 | 50-293 P |
| HARRINGTON, W. D. | 8303140226 | 50-293 Q |
| HARRINGTON, W. D. | 8303150446 | 50-293 P |
| HARRINGTON, W. D. | 8303170316 | 50-293 F |
| HARRINGTON, W. D. | 8303170330 | 50-293 F |
| HARRINGTON, W. D. | 8303170380 | 50-293 P |
| HARRIS, D. P. | 8303240483 | 50-225 R |
| HARRIS, J. R. | 8303210597* | 50-416 Q |
| HARRIS, R. H. | 8303210661* | 50-382 Q |
| HARRISON, F. | 8303080158* | 50-324 R |
| HARRISON, F. | 8303150369* | 50-324 R |
| HARRISON, J. J. | 8303280244* | 50-546 Q |
| HARTKE, J. A. | 8303020051* | PRM |
| HARTMAN, P. L. | 8303170506* | 50-295 Q |
| HARTMAN, S. L. | 8303110218 | 50-508 Q |
| HARTMAN, S. L. | 8303110218 | 50-508 Q |
| HARTMAN, S. L. | 8303110236 | 50-508 Q |
| HARTMAN, S. L. | 8303110236 | 50-508 Q |
| HARTSFIELD, T. C. | 8303150288* | 50-280 P |
| HARTUNG, L. F. | 8303300201 | WASTE MGT |
| HARTZMAN, M. | 8303040647* | 50-275 P |
| HARWARD, J. E. | 8303240226 | 50-237 J |
| HASSE, R. A. | 8303040527* | 50-255 Q |
| HASSELL, D. F. | 8303100172 | 50-247 T |
| HASSELL, D. F. | 8303150378 | 50-247 Q |
| HASTINGS, D. | 8303020110* | 50-247 T |
| HATTORI, H. | 8303230010 | XPORTLIC |
| HAVERKAMP, D. | 8303300323* | 50-293 Q |
| HAVERKAMP, D. R. | 8303040391* | 50-277 P |
| HAWKINS, E. | 8303180079 | WASTE MGT |
| HAWKINS, E. | 8303180152 | WASTE MGT |
| HAWKINS, E. | 8303180641 | WASTE MGT |
| HAWKINS, E. F. | 8303010023 | WASTE MGT |
| HAWKINS, E. F. | 8303010029 | WASTE MGT |
| HAWKINS, E. F. | 8303010326 | 27-48 |
| HAWKINS, E. F. | 8303020206* | 27-48 |
| HAWKINS, E. F. | 8303180064 | 27-48 |
| HAWKINS, E. F. | 8303180068* | 27-48 |
| HAWKINS, E. F. | 8303180098 | WASTE MGT |
| HAWKINS, E. F. | 8303280146 | WASTE MGT |
| HAWKINS, E. F. | 8303280344 | WASTE MGT |
| HAWKINS, F. C. | 8303040527* | 50-255 Q |
| HAWKINS, F. C. | 8303180396* | 50-10 Q |
| HAWKINS, F. C. | 8303240498* | 50-373 Q |
| HAWKINS, S. F. | 8303010336* | 27-48 |
| HAYES, D. W. | 8303030641* | 50-456 Q |
| HAYES, D. W. | 8303170444* | 50-456 Q |
| HAYES, R. L. | 8303080426* | 50-335 S |
| HAYNES, J. G. | 8303070009 | 50-206 Q |
| HAYNES, J. G. | 8303070055 | 50-361 Q |
| HAYNES, R. C. | 8303030176 | 50-387 H |
| HAYNES, R. C. | 8303030345 | 50-247 H |
| HAYNES, R. C. | 8303040440 | State Prog |
| HAYNES, R. C. | 8303040519 | State Prog |
| HAYNES, R. C. | 8303100089* | 50-220 Q |
| HAYNES, R. C. | 8303100386 | 50-244 Q |
| HAYNES, R. C. | 8303140439 | 50-410 Q |
| HAYNES, R. C. | 8303140465 | 50-271 Q |
| HAYNES, R. C. | 8303140614 | 50-272 Q |
| HAYNES, R. C. | 8303150270 | 50-320 Q |
| HAYNES, R. C. | 8303180543 | 50-387 H |
| HAYNES, R. C. | 8303210382 | TOPREP |
| HAYNES, R. C. | 8303300129* | 50-387 H |
| HAZELTON, W. S. | 8108240174* | 50-387 P |
| HEABERLIN, S. W. | 8303150680 | NUREG |
| HEAD, K. Y. | 8303230484 | 71-423 |
| HEATH, C. A. | 8303280073 | WASTE MGT |
| HEATHERLY, T. L. | 8303010341* | 50-390 Q |
| HEATHERLY, T. L. | 8303210585* | 50-390 Q |
| HEBEL, C. | 8303170473* | 50-254 S |
| HEIDER, L. H. | 8303020025 | 50-271 P |
| HEIDER, L. H. | 8303080361 | 50-29 R |
| HEIDER, L. H. | 8303090365 | 50-29 R |
| HEIDER, L. H. | 8303100311 | 50-29 R |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| HEIDER, L. H. | 8303100375 | 50-29 R |
| HEIDER, L. H. | 8303150322 | 50-29 P |
| HEIDER, L. H. | 8303150549 | 50-29 R |
| HEIDER, L. H. | 8303170164 | 50-29 Q |
| HEIDER, L. H. | 8303300405 | 50-271 P |
| HEIMAN, D. | 8303040081 | XPORTLIC |
| HEIMAN, D. | 8303180607 | XPORTLIC |
| HEIMAN, D. | 8303240322 | XPORTLIC |
| HEIMAN, D. | 8303280334 | XPORTLIC |
| HEISHMAN, R. F. | 8303250034* | 50-438 Q |
| HEISING, C. D. | 8303290689 | NUREG |
| HEITNER, K. L. | 8303300196 | 50-309 P |
| HEITNER, K. L. | 8303310089 | COMMISSION |
| HELGESON, K. A. | 8303010126 | 70-820 |
| HELGESON, K. A. | 8303020138 | 70-820 |
| HELGES[illegible] | 8303180594 | 70-820 |
| HELGES[illegible] | 8303210073 | 70-820 |
| HELL[illegible] | 8303030650* | 50-255 Q |
| HELMAN, D. | 8303180105 | XPORTLIC |
| HELTEMES, C. J. | 8303220414 | NUREG |
| HELTEMES, C. J. | 8303220420* | NUREG |
| HELTEMES, C. J. | 8303220425* | NUREG |
| HELTEMES, C. J. | 8303290078 | 50-317 S |
| HELTEMES, C. J. | 8303290109 | 50-317 S |
| HENDERSON, T. K. | 8303240415* | 50-29 P |
| HENDRIX, G. W. | 8303310328* | FOIA |
| HENKE, D. A. | 8303240426 | 50-400 Q |
| HENNIGAN, J. | 8303310136* | CONTRACT |
| HENRICK, G. E. | 8303160386* | 50-335 P |
| HENRY, L. Q. | 8303160345 | 50-57 P |
| HENRY, L. Q. | 8303160425 | 50-57 F |
| HENRY, L. Q. | 8303160437 | 50-57 P |
| HENRY, R. A. | 8303160394* | 50-335 P |
| HENRY, W. O. | 8303040640 | TOPREP |
| HENSCH, D. A. | 8303020251 | 40-8027 |
| HENSLEY, K. D. | 8303010047 | 70-143 |
| HENSLEY, K. D. | 8303010054 | 70-143 |
| HENSLEY, K. D. | 8303010065 | 70-143 |
| HENSLEY, K. D. | 8303010089 | 70-143 |
| HENSLEY, K. D. | 8303010693 | 70-143 |
| HENSLEY, K. D. | 8303010699 | 70-143 |
| HENSLEY, K. D. | 8303110073 | 70-143 |
| HENSLEY, K. D. | 8303110399 | 70-143 |
| HENSLEY, K. D. | 8303140636 | 70-143 |
| HERD, R. | 8303210609* | GA999 |
| HERING, R. F. | 8303240190* | 50-315 Q |
| HERING, R. F. | 8303280050 | 50-315 P |
| HERMANN, O. W. | 8303030306 | 50-261 P |
| HERMANN, O. W. | 8303030325 | 50-261 P |
| HERMANN, R. A. | 8303310089 | COMMISSION |
| HERNAN, R. W. | 8303020296 | 50-330 A |
| HERNAN, R. W. | 8303020302 | 50-329 A |
| HERRERA, D. | 8303220419* | WASTE MGT |
| HERRIN, M. G. | 8303300453 | 50-454 T |
| HERSCH, M. M. | 8303020479 | XPORTLIC |
| HERSCH, M. M. | 8303040091 | XPORTLIC |
| HERSCH, M. M. | [illegible]303180082 | XPORTLIC |
| HERSCH, M. M. | 8303180087* | XPORTLIC |
| HERSCH, M. M. | 8303310575 | XPORTLIC |
| HESSON, G. M. | 8303140696 | NUREG |
| HEUBNER, A. T. | 8303290769* | CONTRACT |
| HEUMANN, E. | 8303100477* | FOIA |
| HEUSSER, R. K. | 8303230284 | ORG |
| HIATT, S. L. | 8303010087 | 50-440 Q |
| HIATT, S. L. | 8303010090 | 50-440 Q |
| HIATT, S. L. | 8303010098 | 50-440 Q |
| HIATT, S. L. | 8303090020 | FOIA |
| HIATT, S. L. | 8303100076 | 50-440 A |
| HIATT, S. L. | 8303300330 | 50-440 Q |
| HIATT, S. L. | 8303310450 | FOIA |
| HICKEY, C. | 8303090273 | 50-454 T |
| HIETALA, J. J. | 8303240424* | 50-373 S |
| HIGGINS, J. C. | 8303080292* | 50-322 Q |
| HILL, E. D. | 8303280249* | 50-267 S |
| HILL, K. L. | 8303030627* | 50-331 S |
| HILL, K. L. | 8303030665* | 50-331 S |
| HILL, K. L. | 8303140408* | 50-331 S |
| HILL, T. V. | 8303180202 | WASTE MGT |
| HILL, W. M. | 8303150491* | 50-498 Q |
| HILLMAN, R. E. | 8303240405* | 50-219 R |
| HIND, J. | 8303220271 | 40-2061 |
| HIND, J. A. | 8303010595 | 50-10 F |
| HIND, J. A. | 8303040476 | 50-315 V |
| HIND, J. A. | 8303170445 | 50-266 Q |
| HIND, J. A. | 8303240440 | 50-10 F |
| HINRICH, G. | 8303160168* | 50-247 S |
| HIPP, G. A. | 8303180313* | 50-320 P |
| HIRSCH, D. | 8303080044 | 30-142 Q |
| HIRSCH, D. | 8303220203 | 50-142 Q |
| HIRSCH, D. | 8303220208* | 50-142 Q |
| HIRSCH, D. | 8303220325* | 50-142 Q |
| HITCHLER, M. J. | 8303030368* | 50-454 T |
| HOCHREIN, A. A. | 8303030383* | CONTRACT |
| HOCHREITER, L. E. | 8303090659 | NUREG |
| HODEL, D. P. | 8303030218* | 50-416 P |
| HODEL, D. P. | 8303150368 | 70-143 |
| HODGDON, A. P. | 8302030438 | 50-352 Q |
| HODGDON, A. P. | 8303010375 | 50-352 Q |
| HODGDON, A. P. | 8303040317 | 50-352 Q |
| HODGDON, A. P. | 8303140001 | 50-352 Q |
| HODGDON, A. P. | 8303140166 | 50-352 Q |
| HOFFMAN, D. P. | 8303080028 | 50-155 R |
| HOFFMAN, D. P. | 8303150514 | 50-155 R |
| HOFFMAN, J. R. | 8303010254 | NUREG |
| HOFFMAN, J. R. | 8303010254 | NUREG |
| HOFFMAN, R. F. | 8303010439* | 50-352 A |
| HOLDER, E. | 8303220097* | 50-260 S |
| HOLDER, E. T. | 8303040433* | 50-260 S |
| HOLDER, E. T. | 8303140604* | 50-259 S |
| HOLIAN, P. D. | 8303020045 | 50-124 R |
| HOLIAN, P. D. | 8303020049* | 50-124 R |
| HOLIAN, P. D. | 8303220178* | 50-124 P |
| HOLISH, L. | 8303080098 | 50-454 T |
| HOLISH, L. | 8303080098 | 50-454 T |
| HOLLAND, P. | 8303240396* | 50-237 S |
| HOLLEY, W. | 8303180244* | 50-285 Q |
| HOLLEY, W. | 8303180433* | 50-313 Q |
| HOLLEY, W. L. | 8303180223* | 50-267 Q |
| HOLLINGWORTH | 8303170030* | 50-443 Q |
| HOLLINGWORTH, B. | 8303010407 | 50-443 Q |
| HOLLY, J. T. | 8303010292* | 50-305 P |
| HOLONICH, J. J. | 8303030338 | 50-482 S |
| HOLONICH, J. J. | 8303100370 | 50-482 A |
| HOLONICH, J. J. | 8303230378 | 50-482 F |
| HOLONICH, J. J. | 8303240143 | 50-482 E |
| HOLTZ, J. L. | 8303080251* | 50-334 R |
| HOLTZ, J. L. | 8303150337* | 50-334 R |
| HOLTZ, J. L. | 8303150581* | 50-334 R |
| HOLZMER, M. M. | 8303030650* | 50-255 Q |
| HOLZMER, M. M. | 8303080270* | 50-315 Q |
| HOOD, D. S. | 8303030389 | 50-329 A |
| HOOD, D. S. | 8303030780 | 50-329 A |
| HOOD, D. S. | 8303040015 | 50-329 A |
| HOOD, D. S. | 8303110362 | 50-329 A |
| HOOD, D. S. | 8303140080 | 50-329 A |
| HOOD, D. S. | 8303210267 | 50-329 A |
| HOOD, D. S. | 8303280012 | 50-329 A |
| HOOD, D. S. | 8303300159 | 50-329 A |
| HOPCRAFT, C. P. | 8303040074 | 71-9160 |
| HOPCRAFT, C. P. | 8303040080* | 71-9160 |
| HOPCRAFT, C. P. | 8303040088* | 71-9160 |
| HOPCRAFT, C. P. | 8303040099* | 71-9160 |
| HOPCRAFT, C. P. | 8303040106* | 71-9160 |
| HOPKINS, H. R. | 8303290264* | CONTRACT |
| HOPKINS, J. | 8303170629* | 50-395 P |
| HOPKINS, J. B. | 8303100369 | 50-482 A |
| HOPKINS, J. B. | 8303160766 | 50-369 P |
| HOPKINS, J. B. | 8303170007 | 50-395 P |
| HOPKINS, J. B. | 8303280306 | 50-369 P |
| HOPKINS, J. B. | 8303290092 | 50-369 P |
| HOPPER, A. M. | 8303310572 | CONTRACT |
| HORIN, W. A. | 8303010316 | 50-445 Q |
| HORIN, W. A. | 8303010316 | 50-445 Q |
| HORIN, W. A. | 8303010333 | 50-445 Q |
| HORIN, W. A. | 8303010333 | 50-445 Q |
| HORIN, W. A. | 8303070122 | 50-445 Q |
| HORIN, W. A. | 8303070122 | 50-445 Q |
| HORIN, W. A. | 8303180406 | 50-445 Q |
| HORIN, W. A. | 8303180406 | 50-445 Q |
| HORIN, W. A. | 8303230228 | 50-445 Q |
| HORIN, W. A. | 8303230228 | 50-445 Q |
| HORIN, W. A. | 8303240519 | 50-445 Q |
| HORIN, W. A. | 8303240519 | 50-445 Q |
| HORLEY, E. C. | 8303290567* | 50-237 P |
| HORN, C. | 8303080092* | 50-269 I |
| HORTON, J. D. | 8303140508* | 40-8713 |
| HOSEY, C. M. | 8303010216* | 50-389 Q |
| HOUSTON, R. | 8303170486* | 50-373 S |
| HOUSTON, R. W. | 8302100191* | 50-413 A |
| HOUSTON, R. W. | 8303080502* | 50-373 S |
| HOUSTON, R. W. | 8303220109* | 50-373 S |
| HOWARD, J. E. | 8303110293 | 50-293 P |
| HOWARD, J. E. | 8303290476 | 50-293 R |
| HOWARD, T. R. | 8303090027 | 40-8584 |
| HOWE, P. W. | 8303010159 | 50-324 Q |
| HOWE, P. W. | 8303010314 | 50-324 Q |
| HOWE, P. W. | 8303210323 | 50-324 Q |
| HOWE, P. W. | 8303240533 | 50-324 P |
| HOWE, P. W. | 8303310235 | 50-324 P |
| HOWE, T. M. | 8303160155 | RES |
| HOWE, T. M. | 8303160164 | RES |
| HOWELL, K. | 8303090129 | FOIA |
| HOYLE, A. | 8303010721 | CONTRACT |
| HOYLE, A. | 8303150151 | CONTRACT |
| HOYLE, A. | 8303170653 | CONTRACT |
| HOYT, H. F. | 8303030344 | 50-443 Q |
| HOYT, H. F. | 8303030352 | 50-443 Q |
| HOYT, H. F. | 8303100378 | 50-443 Q |
| HOYT, H. F. | 8303160394* | 50-335 P |
| HOYT, H. F. | 8303180143 | 50-443 Q |
| HOYT, H. F. | 8303180148 | 50-443 Q |
| HOYT, H. F. | 8303220168 | 50-443 Q |
| HOYT, H. F. | 8303220254 | 50-443 Q |
| HOYT, H. F. | 8303220273 | 50-443 Q |
| HOYT, H. F. | 8303240411 | 50-443 Q |
| HOYT, H. F. | 8303250147 | 50-443 Q |
| HOYT, H. F. | 8303290516 | 50-443 Q |
| HOYT, H. F. | 8303290525 | 50-443 Q |
| HOYT, H. F. | 8303310313 | 50-443 Q |
| HSU, C. J. | 8303210776 | RES |
| HUBACEK, W. G. | 8303150491* | 50-498 Q |
| HUBBARD, G. T. | 8303040572* | GA999 |
| HUBBARD, G. T. | 8303280320* | GA999 |
| HUBBARD, R. B. | 8303250157 | 50-322 T |
| HUBER, S. A. | 8303030204 | FOIA |
| HUDSON, G. | 8303100193* | 50-263 F |
| HUDSON, S. D. | 8303030408* | 50-220 Q |
| HUDSPETH, J. B. | 8303090199* | 50-348 F |
| HUDSPETH, J. B. | 8303100407* | 50-348 F |
| HUDSPETH, J. B. | 8303230418* | 50-348 F |
| HUDSPETH, J. B. | 8303240112* | 50-348 F |
| HUETER, L. J. | 8303210614* | 50-341 Q |
| HUFFMAN, G. N. | 8303010585* | 50-335 Q |
| HUFFMAN, G. N. | 8303010648* | 50-335 Q |
| HUGHES, P. G. | 8303010279* | 50-302 S |
| HUKILL, H. D. | 8302150368 | 50-289 P |
| HUKILL, H. D. | 8303090085 | 50-289 R |
| HUKILL, H. D. | 8303090189 | 50-289 P |
| HUKILL, H. D. | 8303100127 | 50-289 P |
| HUKILL, H. D. | 8303110249 | 50-289 P |
| HUKILL, H. D. | 8303140197 | 50-289 R |
| HUKILL, H. D. | 8303140484 | 50-289 S |
| HUKILL, H. D. | 8303150265 | 50-289 P |
| HUKILL, H. D. | 8303150316 | 50-289 P |
| HUKILL, H. D. | 8303160260 | 50-289 Q |
| HUKILL, H. D. | 8303160530 | 50-289 P |
| HUKILL, H. D. | 8303160537* | 50-289 P |
| HUKILL, H. D. | 8303180422 | 50-289 S |
| HUKILL, H. D. | 8303220030 | 50-289 R |
| HUKILL, H. D. | 8303220314 | 50-289 P |
| HUKILL, H. D. | 8303250155 | 50-289 Q |
| HUKILL, H. D. | 8303250169 | 50-289 P |
| HUKILL, H. D. | 8303280101 | 50-289 P |
| HUKILL, H. D. | 8303290242 | 50-289 Q |
| HULMAN, L. G. | 8303140590 | MISC |
| HULMAN, L. G. | 8303220482 | MISC |
| HULSEY, D. | 8303300056* | WASTE MGT |
| HUNNICUTT, D. M. | 8303010427* | 50-382 Q |
| HUNNICUTT, D. M. | 8303010451* | 50-445 Q |
| HUNNICUTT, D. M. | 8303010587* | 50-458 Q |
| HUNNICUTT, D. M. | 8303150491* | 50-498 Q |
| HUNSTAD, A. A. | 8303220219* | 50-282 S |
| HUNSTAD, A. A. | 8303280151* | 50-306 S |
| HUNT, M. | 8303010590* | 50-416 Q |
| HUNT, M. D. | 8303010334* | 50-389 Q |
| HUNT, M. D. | 8303210528* | 50-389 Q |
| HUNT, T. | 8303110196* | 50-322 Q |
| HUNTER, D. R. | 8303140475* | 50-358 Q |
| HUNTER, R. S. | 8303020013 | 50-315 P |
| HUNTER, R. S. | 8303080111 | 50-315 P |
| HUNTER, R. S. | 8303080141 | 50-315 P |
| HUNTER, R. S. | 8303080348 | 50-315 P |
| HUNTER, R. S. | 8303140344 | 50-316 P |
| HUNTER, R. S. | 8303140399 | 50-315 R |
| HUNTER, R. S. | 8303140452 | 50-315 Q |

# PERSONAL AUTHOR INDEX


| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| HUNTER, R. S. | 8303150218 | 50-315 Q |
| HUNTER, R. S. | 8303170108 | 50-315 F |
| HURFORD, W. J. | 8303010257 | 50-400 Q |
| HURFORD, W. J. | 8303010580 | 50-324 P |
| HURFORD, W. J. | 8303040529 | 50-324 P |
| HURFORD, W. J. | 8303040585 | 50-324 P |
| HURFORD, W. J. | 8303160556 | 50-400 A |
| HURFORD, W. J. | 8303180293 | 50-400 Q |
| HURFORD, W. J. | 8303210367 | 50-261 Q |
| HUTKO, K. | 8303250094* | 50-219 S |
| HYLTON, E. G. | 8303310089 | COMMISSION |
| IGNATONIS, A. | 8303240397 | 50-369 S |
| IGNATONIS, A. J. | 8303210373* | 50-369 Q |
| IGNATONIS, A. J. | 8303210716* | 50-413 Q |
| INGRAM, R. K. | 8303310089 | COMMISSION |
| IORII, J. A. | 8303070157* | TOPREP |
| IRVING, S. M. | 8303300329 | 50-458 Q |
| IRWIN, D. P. | 8303300352 | 50-322 Q |
| IRWIN, D. P. | 8303300352 | 50-322 Q |
| IRWIN, H. R. | 8303100512 | 71-5796 |
| JACKA, B. | 8303080078 | State Prog |
| JACKIW, I. N. | 8303140423* | 50-373 Q |
| JACKIW, I. N. | 8303170408* | 50-266 Q |
| JACKIW, I. N. | 8303240556* | 50-282 Q |
| JACKIW, I. N. | 8303240594* | 50-346 Q |
| JACKSON, C. W. | 8303160249 | 50-247 S |
| JACKSON, G. | 8303030208 | 71-4909 |
| JACKSON, G. | 8303030237* | 71-4909 |
| JACKSON, K. | 8303170287 | WASTE MGT |
| JACKSON, L. H. | 8303210662* | 50-321 Q |
| JACKSON, P. L. | 8303220407 | NUREG |
| JACKSON, P. O. | 8303010088 | WASTE MGT |
| JACKSON, P. O. | 8303010093* | WASTE MGT |
| JACKSON, P. O. | 8303010095 | WASTE MGT |
| JACKSON, P. O. | 8303010097 | WASTE MGT |
| JACKSON, P. O. | 8303010107* | WASTE MGT |
| JACKSON, P. O. | 8303010147* | WASTE MGT |
| JACKSON, P. O. | 8303010321* | WASTE MGT |
| JACKSON, R. E. | 8303300435 | NUREG |
| JACOBS, A. | 8303010712 | CONTRACT |
| JACOBS, A. | 8303020077 | CONTRACT |
| JACOBS, A. | 8303020176 | CONTRACT |
| JACOBS, A. | 8303290599 | CONTRACT |
| JACOBS, J. R. | 8303110223 | 50-72 R |
| JACOBS, R. | 8303030025 | 50-272 S |
| JACOBS, R. | 8303030027 | 50-272 S |
| JAFFE, D. H. | 8303230068 | 50-317 P |
| JAIN, H. | 8303090564 | RES |
| JANG, J. C. | 8303100307* | 50-387 Q |
| JANG, J. C. | 8303160616* | 50-245 Q |
| JANG, J. C. | 8303240512* | 50-423 Q |
| JANICKI, M. | 8303160050* | XPORTLIC |
| JANUSKA, A. Q. | 8303030561* | 70-1308 |
| JAPE, F. | 8303210347* | 50-370 Q |
| JAPE, F. | 8303210391* | 50-416 Q |
| JAPE, F. | 8303210459* | 50-389 Q |
| JAPE, F. | 8303210487* | 50-321 Q |
| JAPE, F. | 8303210491* | 50-395 Q |
| JAPE, F. | 8303210503* | 50-370 Q |
| JAPE, F. | 8303210591* | 50-348 Q |
| JAPE, F. | 8303210646* | 50-369 Q |
| JAPE, F. | 8303210668* | 50-321 Q |
| JARBADER, R. | 8303020227* | 70-364 |
| JAUDON, J. P. | 8303150328 | 50-368 S |
| JAUDON, J. P. | 8303210683* | 50-285 Q |
| JENKINS, G. R. | 8303010459* | 70-143 |
| JENKINS, G. R. | 8303010585* | 50-335 Q |
| JENKINS, G. R. | 8303010648* | 50-335 Q |
| JENKINS, G. R. | 8303210695* | 50-416 Q |
| JENKINS, G. R. | 8303210730* | 50-338 Q |
| JENSEN, S. A. | 8302160446* | 50-275 P |
| JENSEN, W. | 8303100070 | TOPREP |
| JESSEN, D. | 8303240078* | 50-254 F |
| JOHANSEN, E. | 8303230034 | 50-344 J |
| JOHNSON, A. D. | 8303290508* | 50-361 Q |
| JOHNSON, A. R. | 8303070044* | QA999 |
| JOHNSON, A. R. | 8303180399* | QA999 |
| JOHNSON, B. D. | 8303040427 | 50-155 Q |
| JOHNSON, B. D. | 8303040494 | 50-255 P |
| JOHNSON, B. D. | 8303040512 | 50-155 V |
| JOHNSON, B. D. | 8303070057 | 50-155 P |
| JOHNSON, B. D. | 8303080153 | 50-255 S |
| JOHNSON, B. D. | 8303080193 | 50-255 S |
| JOHNSON, B. D. | 8303080219 | 50-255 S |
| JOHNSON, B. D. | 8303080255 | 50-255 Q |
| JOHNSON, B. D. | 8303080283 | 50-255 Q |
| JOHNSON, B. D. | 8303080456 | 50-255 S |
| JOHNSON, B. D. | 8303080476 | 50-255 S |
| JOHNSON, B. D. | 8303140410 | 50-255 R |
| JOHNSON, B. D. | 8303140510 | 50-255 S |
| JOHNSON, B. D. | 8303170147 | 50-255 Q |
| JOHNSON, B. D. | 8303180021 | 50-255 Q |
| JOHNSON, B. D. | 8303180167 | 50-255 P |
| JOHNSON, B. D. | 8303220141 | 50-255 S |
| JOHNSON, B. D. | 8303220151 | 50-255 P |
| JOHNSON, B. D. | 8303280250 | 50-255 P |
| JOHNSON, C. E. | 8303010058/* | 50-458 Q |
| JOHNSON, G. E. | 8303100138 | 50-440 Q |
| JOHNSON, G. E. | 8303100161 | 50-413 Q |
| JOHNSON, G. E. | 8303150374 | 50-413 Q |
| JOHNSON, G. E. | 8303160590 | 50-440 Q |
| JOHNSON, G. E. | 8303310353 | 50-413 Q |
| JOHNSON, H. J. | 8303100005* | CONTRACT |
| JOHNSON, H. J. | 8303230135* | CONTRACT |
| JOHNSON, J. D. | 8303220429 | NUREG |
| JOHNSON, J. E. | 8303210651* | 50-267 P |
| JOHNSON, J. R. | 8303180568 | RES |
| JOHNSON, J. W. | 8303290717 | NUREG |
| JOHNSON, L. J. | 8303160758 | RES |
| JOHNSON, P. | 8303290295* | 50-312 Q |
| JOHNSON, T. L. | 8303090344 | 40-8584 |
| JOHNSON, T. L. | 8303180106* | 40-3453 |
| JOHNSON, T. M. | 8303150130 | NUREG |
| JOHNSON, W. D. | 8303010230* | 50-285 Q |
| JOHNSON, W. D. | 8303010247* | 50-313 Q |
| JOHNSON, W. D. | 8303210529* | 50-482 Q |
| JOHNSON, W. D. | 8303210562* | 50-313 Q |
| JOHNSON, W. D. | 8303210676* | 50-482 Q |
| JOHNSON, W. D. | 8303210683* | 50-285 Q |
| JOHNSON, W. D. | 8303280122 | 50-313 S |
| JOHNSON, W. P. | 8303150509 | 50-29 P |
| JOHNSRUD, J. H. | 8303020063 | 50-277 Q |
| JOHNSTON, G. | 8303150506* | 50-528 Q |
| JOHNSTON, G. | 8303290590* | 50-361 Q |
| JOHNSTON, W. V. | 8205100335* | 50-440 A |
| JOHNSTON, W. V. | 8208050017* | 50-440 A |
| JOHNSTON, W. V. | 8211110643* | 50-373 P |
| JOHNSTON, W. V. | 8212010304* | 50-373 P |
| JOHNSTON, W. V. | 8212160101* | 50-373 P |
| JOHNSTON, W. V. | 8212210480* | 50-373 P |
| JOHNSTON, W. V. | 8303100113* | 50-440 Q |
| JOHNSTON, W. V. | 8303180156* | REVIEW GRP |
| JONES, C. R. | 8303240007 | 50-298 Q |
| JONES, D. W. | 8303010593* | 70-143 |
| JONES, D. W. | 8303160439 | 50-538 R |
| JONES, D. W. | 8303160441* | 50-538 R |
| JONES, D. W. | 8303210544* | 70-27 |
| JONES, E. E. | 8303010618* | 50-10 F |
| JONES, E. E. | 8303080186 | 50-454 T |
| JONES, E. E. | 8303080186 | 50-454 T |
| JONES, G. T. | 8303080016 | 50-259 R |
| JONES, G. T. | 8303150490 | 50-259 R |
| JONES, G. T. | 8303170463 | 50-259 R |
| JONES, G. T. | 8303170467* | 50-259 R |
| JONES, K. | 8303280097 | NUREG |
| JONES, K. | 8303280114 | NUREG |
| JONES, P. C. | 8303220455 | 40-8829 |
| JONES, P. C. | 8303230128 | 40-8829 |
| JONES, R. A. | 8303220128* | 50-445 K |
| JONES, V. H. | 8303150376* | 50-280 R |
| JONES, V. K. | 8303100460 | NUREG |
| JONES, V. K. | 8303100558 | NUREG |
| JONES, W. C. | 8302230355 | 50-285 P |
| JONES, W. C. | 8303010228 | 50-285 P |
| JONES, W. C. | 8303040466 | 50-285 R |
| JONES, W. C. | 8303080438 | 50-285 V |
| JONES, W. C. | 8303090204 | 50-285 P |
| JONES, W. C. | 8303100101* | 50-285 P |
| JONES, W. C. | 8303100565* | 50-285 F |
| JONES, W. C. | 8303100569* | 50-285 F |
| JONES, W. C. | 8303150176 | 50-285 P |
| JONES, W. C. | 8303150205 | 50-285 P |
| JONES, W. C. | 8303150222 | 50-285 P |
| JONES, W. C. | 8303180012 | 50-285 P |
| JONES, W. C. | 8303180298 | 50-285 Q |
| JONES, W. C. | 8303180317 | 50-285 R |
| JONES, W. C. | 8303280234* | 50-285 F |
| JOOSTEN, J. K. | 8303090300 | 50-361 Q |
| JOOSTEN, J. K. | 8303250144 | 50-382 Q |
| JORDAN, E. L. | 8211060703* | FOIA |
| JORDAN, E. L. | 8212060383 | 50-3 Q |
| JORDAN, E. L. | 8212060387 | 50-3 Q |
| JORDAN, M. J. | 8303030446* | 50-10 Q |
| JORDAN, M. J. | 8303170377* | 50-10 Q |
| JORDAN, M. J. | 8303240597* | 50-10 Q |
| JORDAN, W. S. | 8303070139 | 50-289 Q |
| JORDAN, W. S. | 8303070145* | 50-289 Q |
| JORDAN, W. S. | 8303070145* | 50-289 Q |
| JORDAN, W. S. | 8303080454 | 50-443 Q |
| JORDAN, W. S. | 8303080490 | 50-443 Q |
| JORDAN, W. S. | 8303220234 | 50-443 Q |
| JORDAN, W. S. | 8303220234 | 50-443 Q |
| JORDAN, W. S. | 8303220245 | 50-443 Q |
| JORDAN, W. S. | 8303220245 | 50-443 Q |
| JORGENSEN, B. L. | 8303030650* | 50-255 Q |
| JORGENSEN, B. L. | 8303080270* | 50-315 Q |
| JOUKOFF, P. V. | 8303100037* | 50-206 Q |
| JULIAN, C. | 8303010465* | 50-338 Q |
| JULIAN, C. | 8303010630* | 50-250 Q |
| JULIAN, C. | 8303010645* | 50-280 Q |
| JULIAN, C. | 8303010673* | 50-280 Q |
| JULIAN, C. | 8303210743* | 50-250 Q |
| JULIAN, C. A. | 8303210346* | 50-280 Q |
| JULIAN, C. A. | 8303210453* | 50-335 Q |
| JUNGE, M. A. | 8303010256* | 50-317 S |
| JUNGE, M. A. | 8303010542* | 50-318 S |
| JUNGE, M. A. | 8303140199* | 50-317 S |
| JUNGE, M. A. | 8303160324* | 50-318 S |
| JUNGE, M. A. | 8303210577* | 50-318 S |
| JUSTUS, P. S. | 8303290131 | WASTE MGT |
| KADAMBI, N. P. | 8303030274 | 50-400 A |
| KADAMBI, N. P. | 8303030283 | 50-400 A |
| KADAMBI, N. P. | 8303230101 | 50-400 A |
| KADAMBI, N. P. | 8303230346 | 50-400 A |
| KAHLE, J. B. | 8303010251* | 50-302 Q |
| KALEY, M. | 8303170656* | CONTRACT |
| KALIVIANAKIS, N. | 8303080254 | 50-254 S |
| KALIVIANAKIS, N. | 8303140436 | 50-254 S |
| KALIVIANAKIS, N. | 8303150439 | 50-254 R |
| KALIVIANAKIS, N. | 8303160389 | 50-254 R |
| KALIVIANAKIS, N. | 8303170378 | 50-254 S |
| KALIVIANAKIS, N. | 8303170468 | 50-254 S |
| KALIVIANAKIS, N. | 8303240541 | 50-254 S |
| KAMMER, D. S. | 8303010433* | 50-327 Q |
| KAMMER, D. S. | 8303100043* | 50-327 F |
| KAMMER, D. S. | 8303140036 | 50-259 P |
| KAMMER, D. S. | 8303290343 | 50-438 A |
| KAMMERER, C. | 8302100331 | PR |
| KAMMERER, C. | 8303020037 | PR |
| KAMMERER, C. | 8303020090 | PR |
| KAMMERER, C. | 8303090169 | 50-309 U |
| KAMMEYER, D. J. | 8303150502* | 50-344 R |
| KANA, D. D. | 8303240558 | MISC |
| KANA, D. D. | 8303290606* | TOPREP |
| KANA, D. D. | 8303290613* | TOPREP |
| KANA, D. D. | 8303290631* | TOPREP |
| KANGA, B. K. | 8303020028 | 50-320 P |
| KANGA, B. K. | 8303110053 | 50-320 R |
| KANGA, B. K. | 8303140047 | 50-320 Q |
| KANGA, B. K. | 8303180302 | 50-320 P |
| KANGA, B. K. | 8303180392 | 50-320 P |
| KANGA, B. K. | 8303180424 | 50-320 R |
| KANGA, B. K. | 8303250067 | 50-320 S |
| KAPLAN, S. A. | 8303140535* | 50-304 S |
| KARCHER, K. E. | 8303160417* | 50-324 P |
| KARHAN, M. | 8303220252 | 50-261 Q |
| KAROL, R. | 8303140664 | 50-352 A |
| KASSNER, T. F. | 8303150615 | RES |
| KATZ, B. | 8303210680* | 50-361 P |
| KATZ, B. | 8303210688* | 50-361 P |
| KATZ, B. | 8303210696* | 50-361 P |
| KATZ, B. | 8303210704* | 50-361 P |
| KATZ, B. | 8303210720* | 50-361 P |
| KAVALKOVICH, W. | 8303090659 | NUREG |
| KAVANAUGH, P. F. | 8303290197* | CONTRACT |
| KAY, J. A. | 8303110045 | 50-29 P |
| KAY, J. A. | 8303180009 | 50-29 Q |
| KAY, J. A. | 8303240413 | 50-29 P |
| KAY, J. A. | 8303280033 | 50-29 P |
| KAZA, R. N. | 8303110292* | 50-250 P |
| KEARNEY, B. | 8303090111 | 40-299 |
| KEARNEY, J. J. | 8302100345 | PRM |
| KEIMIG | 8303210380 | 50-387 S |
| KEIMIG, R. | 8303280191* | 50-289 Q |
| KEIMIG, R. R. | 8303100327 | 50-278 S |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | |
|---|---|---|---|
| KEIMIG, R. R. | 8303110031* | 50-272 | G |
| KEIMIG, R. R. | 8303160488* | 50-20 | G |
| KEIMIG, R. R. | 9303240380* | 50-352 | G |
| KEISER, H. W. | 8303010561 | 50-387 | S |
| KEISER, H. W. | 8303010611 | 50-387 | S |
| KEISER, H. W. | 8303010651 | 50-387 | S |
| KEISER, H. W. | 8303080002 | 50-387 | S |
| KEISER, H. W. | 8303080300 | 50-387 | S |
| KEISER, H. W. | 8303090098 | 50-387 | S |
| KEISER, H. W. | 8303140205 | 50-387 | S |
| KEISER, H. W. | 8303140405 | 50-387 | S |
| KEISER, H. W. | 8303160174 | 50-387 | S |
| KEISER, H. W. | 8303160186 | 50-387 | S |
| KEISER, H. W. | 8303160241 | 50-387 | S |
| KEISER, H. W. | 8303160261 | 50-387 | S |
| KEISER, H. W. | 8303160369 | 50-387 | S |
| KEISER, H. W. | 8303210533 | 50-387 | S |
| KEISER, H. W. | 8303210692 | 50-387 | S |
| KEISER, H. W. | 8303210709 | 50-387 | S |
| KEISER, H. W. | 8303210746 | 50-387 | S |
| KEISER, H. W. | 8303240503 | 50-387 | S |
| KEISER, H. W. | 8303250117 | 50-387 | S |
| KELLEY, J. L. | 8303010396 | 50-413 | Q |
| KELLEY, J. L. | 8303080117 | 50-413 | Q |
| KELLEY, J. L. | 8303140279 | 50-400 | Q |
| KELLEY, J. L. | 8303140291 | 50-413 | Q |
| KELLEY, J. L. | 8303290507 | 50-400 | Q |
| KELLEY, J. L. | 8303290513 | 50-413 | Q |
| KELLEY, R. E. | 8303150567* | GA999 | |
| KELLEY, R. E. | 8303150587* | GA999 | |
| KELLEY, R. E. | 8303150594* | GA999 | |
| KELLEY, W. | 8303070085* | GA999 | |
| KELLEY, W. D. | 8303150172* | GA999 | |
| KELLEY, W. J. | 8303230280* | 50-461 | I |
| KELLY, J. A. | 8303150219* | 50-382 | G |
| KELLY, J. A. F. | 8303150455* | 50-267 | G |
| KELLY, J. A. F. | 8303250008* | 50-285 | C |
| KELLY, J. W. | 8303170011 | 70-27 | |
| KELLY, L. | 8303150536* | 50-286 | R |
| KELLY, M. J. | 8303100121 | RES | |
| KELLY, M. J. | 8303300470 | 50-322 | Q |
| KELLY, M. J. | 8303300606 | RES | |
| KELLY, W. J. | 8303010635* | 50-275 | S |
| KELLY, W. J. | 8303080177* | 50-275 | R |
| KELLY, W. J. | 8303150512* | 50-275 | R |
| KELMERS, A. D. | 8303160009 | NUREG | |
| KEMPER, J. S. | 8303030671 | 50-352 | S |
| KEMPER, J. S. | 8303040554 | 50-352 | S |
| KEMPER, J. S. | 8303240475* | 50-352 | G |
| KEMPER, J. S. | 8303240477* | 50-352 | G |
| KEMPER, J. S. | 8303290303 | 50-277 | P |
| KEMPER, J. S. | 8303290479 | 50-352 | A |
| KENDALL, R. | 8303160055 | 50-461 | A |
| KENLEY, J. B. | 8303290758* | CONTRACT | |
| KENNEDY, D. M. | 8303080500 | 50-255 | R |
| KENNEDY, D. M. | 8303140320 | 50-255 | R |
| KENNY, T. J. | 8303160404* | 50-286 | G |
| KENT, G. J. | 8303080321* | 50-344 | R |
| KENYON, B. D. | 8303080400 | 50-387 | R |
| KENYON, B. D. | 8303090229 | 50-387 | V |
| KENYON, B. D. | 8303140474 | 50-387 | R |
| KENYON, B. D. | 8303150485 | 50-387 | R |
| KENYON, T. J. | 8303110348 | 50-390 | A |
| KENYON, T. J. | 8303310581 | 50-390 | A |
| KEPPLER, J. G. | 8303010668 | 50-329 | A |
| KEPPLER, J. G. | 8303030438 | 50-295 | G |
| KEPPLER, J. G. | 8303030441 | 50-254 | G |
| KEPPLER, J. G. | 8303030443 | 50-266 | G |
| KEPPLER, J. G. | 8303030445 | 50-255 | G |
| KEPPLER, J. G. | 8303030448 | 50-263 | G |
| KEPPLER, J. G. | 8303030450 | 50-282 | G |
| KEPPLER, J. G. | 8303030460 | 50-155 | G |
| KEPPLER, J. G. | 8303030461 | 50-346 | G |
| KEPPLER, J. G. | 8303030463 | 50-315 | G |
| KEPPLER, J. G. | 8303030464 | 50-331 | G |
| KEPPLER, J. G. | 8303030466 | 50-305 | G |
| KEPPLER, J. G. | 8303030468 | 50-409 | G |
| KEPPLER, J. G. | 8303030471 | 50-373 | G |
| KEPPLER, J. G. | 8303030580 | 50-10 | G |
| KEPPLER, J. G. | 8303030619 | 50-315 | G |
| KEPPLER, J. G. | 8303030656 | 50-341 | G |
| KEPPLER, J. G. | 8303030661 | 50-358 | G |
| KEPPLER, J. G. | 8303080081 | 50-409 | G |
| KEPPLER, J. G. | 8303100364 | 50-10 | P |
| KEPPLER, J. G. | 8303110254 | 50-329 | G |
| KEPPLER, J. G. | 8303110261* | 50-329 | G |
| KEPPLER, J. G. | 8303110363 | 50-329 | G |
| KEPPLER, J. G. | 8303140468 | 50-358 | G |
| KEPPLER, J. G. | 8303140573 | 50-254 | F |
| KEPPLER, J. G. | 8303150535 | 50-358 | G |
| KEPPLER, J. G. | 8303160778* | 50-329 | G |
| KEPPLER, J. G. | 8303170434 | 50-456 | G |
| KEPPLER, J. G. | 8303210307* | 50-329 | A |
| KEPPLER, J. G. | 8303220068 | 50-237 | P |
| KEPPLER, J. G. | 8303220079 | 40-2061 | |
| KEPPLER, J. G. | 8303220098 | 50-358 | A |
| KEPPLER, J. G. | 8303220112 | 50-237 | G |
| KEPPLER, J. G. | 8303230078* | 50-358 | A |
| KEPPLER, J. G. | 8303230085 | 50-358 | A |
| KEPPLER, J. G. | 8303230092 | 50-358 | A |
| KEPPLER, J. G. | 8303240368 | 50-237 | G |
| KEPPLER, J. G. | 8303240587 | 50-10 | G |
| KEPPLER, J. G. | 8303280196 | 50-461 | G |
| KERCH, H. | 8303300504* | 50-309 | G |
| KERCH, H. W. | 8303210661* | 50-382 | G |
| KERR, D. | 8303040227 | 71-6717 | |
| KERR, G. W. | 8303040211 | State Prog | |
| KERR, G. W. | 8303090574 | State Prog | |
| KERR, G. W. | 8303090579* | State Prog | |
| KERR, G. W. | 8303300270 | WASTE MGT | |
| KERR, W. | 8303030435 | 50-2 | F |
| KERRIGAN, G. A. | 8303140173* | 70-2684 | |
| KERRIGAN, J. E. | 8303020232 | 40-8820 | |
| KESHISHIAN, P. | 8303250034* | 50-438 | G |
| KETZLACH, N. | 8303040331* | 70-2932 | |
| KETZLACH, N. | 8303290777* | 70-1100 | |
| KEY, J. C. | 8303290317* | 50-390 | A |
| KEY, W. J. | 8303040574* | 50-295 | G |
| KEY, W. J. | 8303170444* | 50-456 | G |
| KHALSA, K. S. | 8303160276* | 50-250 | P |
| KIEL, G. R. | 8303150681 | XPORTLIC | |
| KIEL, R. L. | 8303280102* | CONTRACT | |
| KIESSEL, R. J. | 8303250034* | 50-438 | G |
| KILLINGER, M. H. | 8303310364 | 70-2968 | |
| KING, J. P. | 8303030596 | 50-322 | A |
| KING, J. P. | 8303090171 | 50-322 | A |
| KING, W. H. | 8303020151 | 70-754 | |
| KINNEAR, W. | 8303180398 | 50-329 | G |
| KINNEAR, W. | 8303180398 | 50-329 | G |
| KINNEMAN, J. | 8303080390 | I&E | |
| KINNEMAN, J. | 8303210611 | I&E | |
| KINNEY, W. H. | 8303310352* | CONTRACT | |
| KINNEY, W. W. | 8303160488* | 50-20 | G |
| KINNISON, R. R. | 8303100416 | NUREG | |
| KIRK, W. F. | 8303020117 | 70-371 | |
| KIRK, W. F. | 8303180321 | 70-371 | |
| KIRK, W. F. | 8303290134 | 70-371 | |
| KIRKLAND, M. W. | 8303010700 | 70-754 | |
| KIRKLAND, M. W. | 8303030349 | 70-2786 | |
| KIRKLAND, M. W. | 8303030356 | XPORTLIC | |
| KIRKLAND, M. W. | 8303170027 | 70-754 | |
| KIRNER, N. P. | 8303180562 | WASTE MGT | |
| KIRSCH, D. | 8303290590* | 50-361 | G |
| KIRSCH, D. F. | 8303040414* | 50-206 | G |
| KIRSCH, D. F. | 8303040421* | 50-275 | G |
| KIRSCH, D. F. | 8303040454* | 50-275 | G |
| KIRSCH, D. F. | 8303150305* | 50-361 | G |
| KIRSCH, D. F. | 8303150521 | 50-362 | S |
| KIRSCH, D. F. | 8303150533* | 50-70 | G |
| KIRSCH, D. F. | 8303180507 | 50-361 | S |
| KIRSCH, D. F. | 8303210164 | 50-361 | S |
| KIRSCH, D. F. | 8303220111 | 50-206 | S |
| KIRSCH, D. F. | 8303290255* | 50-361 | G |
| KIRSCH, D. F. | 8303290279* | 50-206 | G |
| KIRSCH, D. F. | 8303290462* | 50-206 | G |
| KIRSCH, D. F. | 8303290508* | 50-361 | G |
| KIRVEN, J. | 8303040485 | 50-261 | G |
| KISH, J. N. | 8303240498* | 50-373 | G |
| KISTER | 8303210710 | 50-220 | S |
| KISTER, H. | 8303160494* | 50-286 | G |
| KISTER, H. | 8303300321* | 50-247 | G |
| KISTER, H. B. | 8303030408* | 50-220 | G |
| KISTER, H. B. | 8303080428* | 50-244 | G |
| KISTER, H. B. | 8303150600* | 50-410 | G |
| KISTER, H. B. | 8303160546* | 50-333 | G |
| KITTS, R. J. | 8303100053* | 50-327 | F |
| KLAGES, J. | 8303160687 | RES | |
| KLEIN, T. | 8303160687 | RES | |
| KLEINSORGE, W. P. | 8303210682* | 50-302 | G |
| KLEPFER, H. H. | 8303160236* | TOPREP | |
| KLIMA, D. L. | 8303280128 | 50-245 | P |
| KLINE, J. R. | 8303010101 | 50-483 | G |
| KLINE, J. R. | 8303070111 | 50-440 | G |
| KLINE, J. R. | 8303310286 | 50-440 | G |
| KLINGLER, G. | 8303040557 | 50-313 | G |
| KLINGLER, G. | 8303180298 | 50-382 | G |
| KLINGLER, G. | 8303230026 | 50-482 | G |
| KLINGLER, G. | 8303280043 | 50-277 | G |
| KLOPP, G. C. | 8303080104 | 50-454 | T |
| KMETYK, L. N. | 8303290677 | NUREG | |
| KNAPP, M. R. | 8303290595 | WASTE MGT | |
| KNAPP, M. R. | 8303300264 | WASTE MGT | |
| KNICELEY, J. R. | 8303030543* | 50-305 | G |
| KNICELEY, J. R. | 8303280321* | 50-254 | G |
| KNIGHT, J. P. | 8111180081* | 50-206 | P |
| KNIGHT, J. P. | 8202240261* | 50-206 | P |
| KNIGHT, J. P. | 8205200351* | 50-206 | P |
| KNIGHT, J. P. | 8205280058* | 50-206 | P |
| KNIGHT, J. P. | 8211090596* | 50-373 | P |
| KNIGHT, J. P. | 8211110155* | 50-373 | P |
| KNIGHT, J. P. | 8303020155* | 50-206 | P |
| KNIGHTON, G. | 8303010109 | 50-508 | A |
| KNIGHTON, G. W. | 8303010706 | 50-528 | A |
| KNIGHTON, G. W. | 8303010718 | 50-508 | D |
| KNIGHTON, G. W. | 8303010727 | 50-400 | E |
| KNIGHTON, G. W. | 8303020115 | 50-275 | P |
| KNIGHTON, G. W. | 8303030170 | 50-361 | P |
| KNIGHTON, G. W. | 8303030186* | 50-361 | P |
| KNIGHTON, G. W. | 8303030668 | 50-206 | F |
| KNIGHTON, G. W. | 8303040230* | 50-361 | P |
| KNIGHTON, G. W. | 8303100411 | 50-361 | P |
| KNIGHTON, G. W. | 8303100475* | 50-361 | P |
| KNIGHTON, G. W. | 8303100484* | 50-361 | P |
| KNIGHTON, G. W. | 8303140564 | 50-275 | P |
| KNIGHTON, G. W. | 8303140612 | 50-382 | A |
| KNIGHTON, G. W. | 8303160039 | 50-508 | D |
| KNIGHTON, G. W. | 8303160040 | 50-508 | D |
| KNIGHTON, G. W. | 8303160044 | 50-508 | D |
| KNIGHTON, G. W. | 8303160047 | 50-508 | D |
| KNIGHTON, G. W. | 8303180122 | 50-443 | E |
| KNIGHTON, G. W. | 8303180124* | 50-443 | E |
| KNIGHTON, G. W. | 8303180183 | 50-508 | A |
| KNIGHTON, G. W. | 8303180686 | 50-508 | D |
| KNIGHTON, G. W. | 8303180689 | 50-508 | D |
| KNIGHTON, G. W. | 8303180692 | 50-508 | D |
| KNIGHTON, G. W. | 8303180693 | 50-508 | D |
| KNIGHTON, G. W. | 8303180695 | 50-508 | D |
| KNIGHTON, G. W. | 8303180697 | 50-508 | D |
| KNIGHTON, G. W. | 8303180698 | 50-508 | D |
| KNIGHTON, G. W. | 8303210098 | 50-508 | D |
| KNIGHTON, G. W. | 8303230308 | 50-443 | A |
| KNIGHTON, G. W. | 8303230330 | 50-528 | A |
| KNIGHTON, G. W. | 8303230450 | 50-275 | P |
| KNIGHTON, G. W. | 8303240276 | 50-389 | A |
| KNIGHTON, G. W. | 8303240284 | 50-389 | A |
| KNIGHTON, G. W. | 8303290737 | 50-528 | A |
| KNIGHTON, G. W. | 8303310654 | 50-400 | A |
| KNIGHTON, G. W. | 8303310657 | 50-528 | E |
| KNIGHTON, G. W. | 8303310666 | 50-400 | A |
| KNOP, R. C. | 8303030452 | 50-483 | G |
| KNOP, R. C. | 8303080256 | 50-461 | G |
| KNOP, R. C. | 8303080449 | 50-440 | G |
| KNOP, R. C. | 8303280230 | 50-546 | G |
| KNOROVSKY, G. A. | 8303160614 | NUREG | |
| KNOWLES, N. J. | 8303100391 | FOIA | |
| KNOX, H. W. | 8303180075* | CONTRACT | |
| KNOX, H. W. | 8303290091* | CONTRACT | |
| KOESTER, G. L. | 8303080257 | 50-482 | A |
| KOESTER, G. L. | 8303080498 | 50-482 | S |
| KOESTER, G. L. | 8303150334 | 50-482 | S |
| KOESTER, G. L. | 8303150344 | 50-482 | S |
| KOESTER, G. L. | 8303150469 | 50-482 | A |
| KOESTER, G. L. | 8303180249 | 50-482 | S |
| KOESTER, G. L. | 8303180306 | 50-482 | S |
| KOESTER, G. L. | 8303250024 | 50-482 | S |
| KOESTER, G. L. | 8303280164 | 50-482 | S |
| KOESTER, G. L. | 8303280175 | 50-482 | S |
| KOESTER, G. L. | 8303280201 | 50-482 | S |
| KOESTER, G. L. | 8303280226 | 50-482 | S |
| KOESTER, G. L. | 8303280269 | 50-482 | S |
| KOLLMAR, S. | 8303090313* | 50-382 | F |
| KOLTAY, P. | 8303300321* | 50-247 | G |
| KOMOSKY, G. E. | 8303180336* | 50-336 | S |
| KONKLIN, J. E. | 8303080457* | 50-440 | G |
| KONKLIN, J. E. | 8303280244* | 50-546 | G |

# PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| KONZEK, G. J. | 8303150680 | NUREG |
| KORDALSKI, F. J. | 8303090659 | NUREG |
| KORNEGAY, F. C. | 8303160009 | NUREG |
| KOSLA, B. | 8303170306 | 40-8027 |
| KOVACK, T. J. | 8303300744* | 50-254 F |
| KOZINSKY, E. J. | 8303230142 | NUREG |
| KRALIK, J. F. | 8303020124* | 50-247 T |
| KRATZKE, R. T. | 8303140585 | 70-754 |
| KRAUSE, D. F. | 8303140610* | 50-335 S |
| KRAUSE, L. | 8204220451* | FOIA |
| KRAUTH, M. | 8303300056* | WASTE MGT |
| KRECHTING, J. E. | 8303040646* | 50-275 P |
| KRECHTING, J. E. | 8303220074 | 50-275 R |
| KREUTZER, P. M. | 8303310089 | COMMISSION |
| KRICH, R. M. | 8303240014 | 50-255 S |
| KRIEG, R. D. | 8303160614 | NUREG |
| KRIEGER, R. W. | 8303070064 | 50-206 P |
| KRIEGER, R. W. | 8303070084 | 50-206 P |
| KRIEGER, R. W. | 8303070102 | 50-206 P |
| KRIEGER, R. W. | 8303080261 | 50-206 P |
| KRIEGER, R. W. | 8303150584 | 50-206 P |
| KRIEGER, R. W. | 8303210107 | 50-206 P |
| KRIEGER, R. W. | 8303220001 | 50-206 P |
| KRIEGER, R. W. | 8303220085 | 50-206 Q |
| KRIEGER, R. W. | 8303250087 | 50-206 P |
| KRIEGER, R. W. | 8303250097 | 50-206 P |
| KRIEGER, R. W. | 8303280010 | 50-206 P |
| KRIMM, R. W. | 8303160513 | 50-335 F |
| KRIMM, R. W. | 8303160593 | 50-254 F |
| KRISHNAN, R. | 8303180558 | WASTE MGT |
| KROEGER, P. G. | 8303210776 | RES |
| KRUG, H. E. | 8303210347* | 50-370 Q |
| KRUG, H. E. | 8303210503* | 50-370 Q |
| KRUG, H. E. | 8303210591* | 50-348 Q |
| KRUMPOS, P. J. | 8303010211* | 50-263 Q |
| KRYSINSKI, T. L. | 8303210355 | TOPREP |
| KUBICEK, L. D. | 8303030765* | 50-275 P |
| KUBINAK, R. A. | 8302100345 | PRM |
| KUCZYNSKI, L. A. | 8303010567* | 50-387 S |
| KUCZYNSKI, L. A. | 8303010620* | 50-387 S |
| KUCZYNSKI, L. A. | 8303080007* | 50-387 S |
| KUCZYNSKI, L. A. | 8303080403* | 50-387 R |
| KUCZYNSKI, L. A. | 8303090116* | 50-387 S |
| KUCZYNSKI, L. A. | 8303140412* | 50-387 S |
| KUCZYNSKI, L. A. | 8303150487* | 50-387 R |
| KUCZYNSKI, L. A. | 8303160250* | 50-387 S |
| KULISEK, D. A. | 8303140501* | 50-327 S |
| KULISEK, D. A. | 8303140539* | 50-327 S |
| KULISEK, D. A. | 8303210308* | 50-327 S |
| KUPPERMAN, D. | 8303150615 | RES |
| KUSHNER, W. L. | 8303030206* | 50-320 Q |
| KUSHNEV, W. | 8303160482* | 50-289 Q |
| KUZO, G. B. | 8303210693* | 50-280 Q |
| LACEY, W. S. | 8302250194 | 50-334 S |
| LACEY, W. S. | 8303040375 | 50-334 S |
| LACEY, W. S. | 8303070041 | 50-334 S |
| LACEY, W. S. | 8303070148 | 50-334 S |
| LACEY, W. S. | 8303110061* | 50-334 S |
| LACEY, W. S. | 8303140[illegible]2 | 50-334 S |
| LACEY, W. S. | 8303240580 | 50-334 S |
| LACEY, W. S. | 8303310515* | 50-334 F |
| LAFLAMME, S. J. | 8303160356* | 50-309 S |
| LAGERAAEN, A. | 8303280225 | 50-397 S |
| LAGERAAEN, A. J. | 8303280156 | 50-397 S |
| LAGIEWSKI, J. S. | 8303010393* | 50-318 S |
| LAGIEWSKI, J. S. | 8303140378* | 50-317 S |
| LAGIEWSKI, J. S. | 8303160153* | 50-318 S |
| LAGIEWSKI, J. S. | 8303160411* | 50-318 S |
| LAGIEWSKI, J. S. | 8303210715* | 50-318 S |
| LAHTI, G. P. | 8303080216 | 50-454 T |
| LAHTI, G. P. | 8303080216 | 50-454 T |
| LAINAS, G. C. | 8205270550* | 50-206 P |
| LAINAS, G. C. | 8303040237 | 50-321 P |
| LAINAS, G. C. | 8303160668 | 50-336 P |
| LANDAU, S. | 8303180135 | WASTE MGT |
| LANDERS, D. F. | 8303030559 | 50-387 P |
| LANDERS, D. F. | 8303080466 | 50-322 A |
| LANDERS, D. F. | 8303150210 | 50-322 A |
| LANDERS, D. F. | 8303180409 | 50-322 A |
| LANDIS, K. | 8303210459* | 50-389 Q |
| LANDSMAN, R. B. | 8303110366* | 50-329 Q |
| LANDSMAN, R. B. | 8303210312* | 50-329 A |
| LANE, V. M. | 8303110194 | 50-322 Q |
| LANG, T. | 8303080522* | 50-346 S |
| LANIK | 8303240153 | I&E |
| LANKFORD, J. B. | 8303010626* | 70-27 |
| LANKSBURY, R. D. | 8303090529* | 50-373 P |
| LAPUR, P. | 8303100417* | 70-364 |
| LARIMORE, R. W. | 8303310230* | 50-237 Q |
| LARSON, C. E. | 8303150269 | 50-282 Q |
| LARSON, C. E. | 8303290246 | 50-263 Q |
| LARSON, C. E. | 8303290454 | 50-282 Q |
| LARSON, C. E. | 8303290486* | 50-263 Q |
| LASUR, S. R. | 8303220029 | I&E |
| LATHAM, S. B. | 8303010408 | 50-322 Q |
| LATHAM, S. B. | 8303010408 | 50-322 Q |
| LATHAM, S. B. | 8303230260 | 50-322 Q |
| LATHAM, S. B. | 8303230260 | 50-322 Q |
| LATHAM, W. K. | 8303140056 | 50-312 P |
| LATHAM, W. K. | 8303150238 | 50-312 F |
| LATHAM, W. K. | 8303290436 | 50-312 P |
| LAURENSON, J. A. | 8303070142 | 50-247 Q |
| LAURENSON, J. A. | 8303220330 | 50-482 Q |
| LAVINE, M. J. | 8303090520 | NUREG |
| LAWSON, J. E. | 8303100564 | NUREG |
| LAWTON, M. D. | 8303090605 | 40-8084 |
| LAWTON, R. R. | 8303300243* | 50-309 P |
| LAZO, L. | 8303020307 | 50-412 A |
| LAZO, L. | 8303160750 | 50-412 F |
| LAZO, L. | 8303180638 | 50-412 A |
| LAZO, L. | 8303230211 | 50-412 A |
| LAZO, R. M. | 8303240414 | 50-529 Q |
| LE, H. | 8303070089* | 50-387 P |
| LEDD[illegible]R, S. | 8303110298 | 50-508 S |
| LEDDICK, R. S. | 8303110306* | 50-508 S |
| LEDDICK, R. S. | 8303110327* | 50-508 Q |
| LEDDICK, R. S. | 8303110379* | 50-508 Q |
| LEDDICK, R. S. | 8303140248 | 50-508 Q |
| LEDDICK, R. S. | 8303140483 | 50-508 S |
| LEDDICK, R. S. | 8303220157 | 50-508 S |
| LEDDICK, R. S. | 8303280001 | 50-508 S |
| LEDERMAN, L. | 8303140664 | 50-352 A |
| LEDUC, R. J. | 8303170516* | 50-250 P |
| LEE, D. E. | 8303090183 | FOIA |
| LEE, J. | 8303040062* | 50-261 P |
| LEE, J. C. | 8303210144 | ACRS |
| LEE, J. C. | 8303210144 | ACRS |
| LEE, N. | 8303090659 | NUREG |
| LEE, O. R. | 8303010540 | 50-267 P |
| LEE, O. R. | 8303080088 | 50-267 P |
| LEE, O. R. | 8303080096* | 50-267 P |
| LEE, O. R. | 8303080323 | 50-267 Q |
| LEE, R. S. | 8303310606 | 50-338 P |
| LEE, T. D. | 8303210583* | 70-143 |
| LEE, T. D. | 8303210643* | 70-143 |
| LEE, T. D. | 8303280284* | 70-143 |
| LEE, W. S. | 8303080092* | 50-269 I |
| LEECH, P. H. | 8303020189* | 50-336 S |
| LEECH, P. H. | 8303160258 | 50-245 F |
| LEHMAN, L. | 8303290587 | WASTE MGT |
| LEHMAN, L. | 8303290601* | WASTE MGT |
| LEHMAN, L. L. | 8303290588* | WASTE MGT |
| LEHMAN, L. L. | 8303290612 | WASTE MGT |
| LEHMAN, L. L. | 8303290709 | WASTE MGT |
| LEHNER, J. R. | 8303300154 | RES |
| LEHNER, J. R. | 8303300421 | RES |
| LEIPZIG, S. D. | 8303220200* | 50-322 Q |
| LEKACH, S. V. | 8303160183 | RES |
| LEMON, C. E. | 8303030792* | 50-329 A |
| LEMON, C. E. | 8303040041* | 50-329 A |
| LENTINE, F. Q. | 8303040489 | 50-295 F |
| LENTINE, F. Q. | 8303080269 | 50-304 P |
| LENTINE, F. Q. | 8303080328 | 50-295 P |
| LENTINE, F. Q. | 8303100348 | 50-295 P |
| LENTINE, F. Q. | 8303110284 | 50-295 Q |
| LENTINE, F. Q. | 8303220081 | 50-295 P |
| LENTINE, F. Q. | 8303220256 | 50-295 P |
| LENTINE, F. Q. | 8303220317 | 50-454 K |
| LENTINE, F. Q. | 8303240319 | 50-295 P |
| LENTINE, F. Q. | 8303280062 | 50-295 P |
| LEONARD, J. E. | 8303160236* | TOPREP |
| LESSOR, L. C. | 8303080185 | 50-298 R |
| LESSOR, L. C. | 8303150550 | 50-298 R |
| LESSOR, L. C. | 8303250007 | 50-298 S |
| LESSOR, L. C. | 8303250025 | 50-298 S |
| LESSOR, L. C. | 8303290137* | 50-298 F |
| LESSY, R. P. | 8303040337 | 50-443 Q |
| LESSY, R. P. | 8303080026 | 50-443 Q |
| LESSY, R. P. | 8303100157 | 50-443 Q |
| LESSY, R. P. | 8303110046 | 50-309 Q |
| LESSY, R. P. | 8303140010 | 50-443 Q |
| LESSY, R. P. | 8303140085 | 50-443 Q |
| LESSY, R. P. | 8303140148 | 50-443 Q |
| LESSY, R. P. | 8303140206 | 50-443 Q |
| LESSY, R. P. | 8303140553 | 50-443 Q |
| LESSY, R. P. | 8303170025 | 50-443 Q |
| LESSY, R. P. | 8303230039 | 50-443 Q |
| LESSY, R. P. | 8303240022 | 50-443 Q |
| LESSY, R. P. | 8303310145 | 50-309 Q |
| LETSCHE, K. J. | 8303100286 | 50-322 Q |
| LETSCHE, K. J. | 8303100286 | 50-322 Q |
| LETSCHE, K. J. | 8303300346 | 50-322 Q |
| LETSCHE, K. J. | 8303300346 | 50-322 Q |
| LEVIN, H. A. | 8303030789* | 50-329 A |
| LEVIN, H. A. | 8303030792* | 50-329 A |
| LEVIN, H. A. | 8303040024* | 50-329 A |
| LEVIN, H. A. | 8303040041* | 50-329 A |
| LEVIN, H. A. | 8303210448 | 50-329 A |
| LEVIN, H. A. | 8303210685 | 50-329 A |
| LEVINE, J. M. | 8303080306 | State Prog |
| LEVINE, J. M. | 8303150454 | 50-368 S |
| LEVINE, J. M. | 8303230170* | 50-313 F |
| LEVINE, J. M. | 8303290699* | 50-313 F |
| LEVINE, J. M. | 8303290716* | 50-313 F |
| LEVINE, J. M. | 8303300054* | 50-313 F |
| LEVINE, J. M. | 8303300633* | 50-313 F |
| LEVINE, M. M. | 8303300642 | RES |
| LEWIS, H. | 8303020304* | COMMISSION |
| LEWIS, M. C. | 8303020075 | PRM |
| LEWIS, N. D. | 8303290849 | WASTE MGT |
| LEWIS, N. D. | 8303300257 | WASTE MGT |
| LEWIS, N. D. | 8303300267 | WASTE MGT |
| LEWIS, R. C. | 8303010186 | 50-348 Q |
| LEWIS, R. C. | 8303010213* | 50-348 Q |
| LEWIS, R. C. | 8303010463 | 50-416 Q |
| LEWIS, R. C. | 8303010532 | 50-400 Q |
| LEWIS, R. C. | 8303010543* | 50-400 Q |
| LEWIS, R. C. | 8303010597 | 50-250 Q |
| LEWIS, R. C. | 8303010619* | 50-250 Q |
| LEWIS, R. C. | 8303010643 | 50-280 Q |
| LEWIS, R. C. | 8303010661* | 50-280 Q |
| LEWIS, R. C. | 8303010672* | 50-250 Q |
| LEWIS, R. C. | 8303210334 | 50-413 Q |
| LEWIS, R. C. | 8303210376 | 50-261 Q |
| LEWIS, R. C. | 8303210381* | 50-261 Q |
| LEWIS, R. C. | 8303210414 | 50-327 Q |
| LEWIS, R. C. | 8303210458 | 50-321 Q |
| LEWIS, R. C. | 8303210472* | 50-321 Q |
| LEWIS, R. C. | 8303210511 | 50-395 Q |
| LEWIS, R. C. | 8303210531* | 50-395 Q |
| LEWIS, R. C. | 8303210532* | 50-348 Q |
| LEWIS, R. C. | 8303210549 | 50-250 Q |
| LEWIS, R. C. | 8303210590 | 50-261 Q |
| LEWIS, R. C. | 8303210632 | 50-321 Q |
| LEWIS, R. C. | 8303210648* | 50-321 Q |
| LEWIS, R. C. | 8303210653 | 50-424 Q |
| LEWIS, R. C. | 8303210670* | 50-424 Q |
| LEWIS, R. C. | 8303210691 | 50-416 Q |
| LEWIS, R. C. | 8303210717 | 50-395 Q |
| LEWIS, R. C. | 8303210733* | 50-395 Q |
| LEWIS, R. C. | 8303210742* | 50-416 Q |
| LEWIS, R. C. | 8303210756 | 50-259 Q |
| LEWIS, R. C. | 8303210771* | 50-259 Q |
| LEWONTIN, Y. | 8303230115 | FOIA |
| LIANG, C. Y. | 8303140154* | 50-443 Q |
| LIAW, C. Y. | 8209030274* | 50-213 P |
| LIBRIZZI, F. P. | 8303110017* | 50-272 S |
| LICITRA, E. A. | 8303180355 | 50-528 F |
| LICITRA, E. A. | 8303180442 | 50-528 A |
| LICITRA, E. A. | 8303230383 | 50-528 A |
| LICITRA, E. A. | 8303300187 | 50-528 A |
| LICITRA, E. A. | 8303300510 | 50-528 A |
| LICKUS, R. M. | 8303140314* | 50-295 Q |
| LIDEN, E. A. | 8303040418 | 50-272 P |
| LIDEN, E. A. | 8303090178 | 50-272 V |
| LIDEN, E. A. | 8303100308 | 50-311 P |
| LIDEN, E. A. | 8303140438 | 50-272 Q |
| LIDEN, E. A. | 8303160539 | 50-272 P |
| LIDEN, E. A. | 8303280279 | 50-272 R |
| LIEBERMAN, J. | 8303150223* | 50-295 Q |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| LIM, T. H. | 8303140337 | 50-224 R |
| LIM, T. H. | 8303140339* | 50-224 R |
| LINDEMAN, H. N. | 8303020164 | FOIA |
| LINDER, F. | 8303020030 | 50-409 P |
| LINDER, F. | 8303080221 | 50-409 R |
| LINDER, F. | 8303080275 | 50-409 R |
| LINDER, F. | 8303150234* | 50-409 G |
| LINDER, F. | 8303150410 | 50-409 R |
| LINDER, F. | 8303170095 | 50-409 R |
| LINDER, F. | 8303210437 | 50-409 P |
| LINDER, F. | 8303220140 | 50-409 G |
| LINDER, F. | 8303220268 | 50-409 P |
| LINDER, F. | 8303220358 | 50-409 P |
| LINDER, F. | 8303290408* | 50-409 P |
| LINDGREN, R. D. | 8110150356* | FOIA |
| LINDGREN, R. D. | 8303240166* | FOIA |
| LINDSEY, I. D. | 8303170483 | 50-382 Q |
| LINDSEY, I. D. | 8303220301 | 50-458 Q |
| LINEHAN, J. J. | 8303090005* | FOIA |
| LINEHAN, J. J. | 8303090011 | 40-8745 |
| LINEHAN, J. J. | 8303090012 | 40-8728 |
| LINEHAN, J. J. | 8303090421 | 40-8786 |
| LINEHAN, J. J. | 8303180065* | 40-8745 |
| LINEHAN, J. J. | 8303180154 | 40-8681 |
| LINENBERGER, G. | 8303040435 | 50-537 G |
| LINK, B. W. | 8303220413 | 50-16 W |
| LINTON, O. W. | 8302250325 | PR |
| LINTON, O. W. | 8303090153 | FOIA |
| LINVILLE, J. C. | 8301160346* | 50-333 G |
| LIPINSKI, D. R. | 8303030184* | 50-245 G |
| LIPINSKI, D. R. | 8303030201* | 50-245 G |
| LIPINSKI, D. R. | 8303300475* | 50-245 G |
| LIPINSKI, R. E. | 8301250065* | 50-358 A |
| LISENO, R. | 8303250035* | 50-333 S |
| LITTLE, G. V. | 8303150467* | 50-296 S |
| LITTLE, M. | 8303010002 | 50-206 P |
| LITTLE, W. S. | 8303040519 | 50-255 G |
| LITTLE, W. S. | 8303040521* | 50-255 G |
| LITTLE, W. S. | 8303040532 | 50-483 G |
| LITTLE, W. S. | 8303040566 | 50-295 G |
| LITTLE, W. S. | 8303040591 | 50-454 G |
| LITTLE, W. S. | 8303140328 | 50-483 G |
| LITTLE, W. S. | 8303140402 | 50-266 G |
| LITTLE, W. S. | 8303180391 | 50-10 G |
| LITTLE, W. S. | 8303220035 | 50-483 G |
| LITTLE, W. S. | 8303220045* | 50-483 G |
| LITTLE, W. S. | 8303220240 | 50-440 G |
| LITTLE, W. S. | 8303240456 | 50-341 G |
| LITTLE, W. S. | 8303240484 | 50-373 G |
| LITTLE, W. S. | 8303240489* | 50-373 G |
| LITTLE, W. S. | 8303240508 | 50-440 G |
| LIU, L. | 8303290488 | 50-331 G |
| LIU, W. | 8303210398* | 50-390 G |
| LIU, W. C. | 8303210335* | 50-400 G |
| LLAMADO, J. G. | 8111170263* | FOIA |
| LLAURADO, J. G. | 8201200407* | FOIA |
| LOFGREN, E. V. | 8303230362 | NUREG |
| LOGSDON, M. J. | 8303300345 | WASTE MGT |
| LOHAUS, P. H. | 8303280300 | WASTE MGT |
| LONG, J. | 8303170449* | 50-346 S |
| LONG, J. | 8303170526* | 50-346 S |
| LONG, K. E. | 8303240563 | 50-400 Q |
| LONGENECKER, J. | 8303010505 | 50-537 A |
| LONGENECKER, J. | 8303010510 | 50-537 F |
| LONGENECKER, J. | 8303010573 | 50-537 Q |
| LONGENECKER, J. | 8303030652 | 50-537 B |
| LONGENECKER, J. | 8303070003 | 50-537 A |
| LONGENECKER, J. | 8303070005 | 50-537 A |
| LONGENECKER, J. | 8303070061 | 50-537 A |
| LONGENECKER, J. | 8303070100 | 50-537 A |
| LONGENECKER, J. | 8303070112 | 50-537 A |
| LONGENECKER, J. | 8303090298 | 50-537 A |
| LONGENECKER, J. | 8303090306 | 50-537 A |
| LONGENECKER, J. | 8303150458 | 50-537 Q |
| LONGENECKER, J. | 8303250013 | 50-537 A |
| LONGEST, A. W. | 8303170616 | NUREG |
| LOOKABAUGH, A. | 8303310266* | 50-445 T |
| LORENZ, R. A. | 8303290698 | NUREG |
| LORION, J. | 8203120425* | 50-250 G |
| LORION, J. | 8203120426* | 50-250 G |
| LOSH, L. L. | 8303180313* | 50-320 P |
| LOTITO, E. | 8303220026* | 50-317 R |
| LOTITO, E. | 8303220322* | 50-317 R |
| LOTITO, E. | 8303220328* | 50-317 R |
| LOTITO, E. | 8303220334* | 50-317 R |
| LOTITO, E. | 8303220339* | 50-317 R |
| LOTITO, E. | 8303220346* | 50-317 R |
| LOTITO, E. M. | 8303220022 | 50-317 R |
| LOTITO, E. M. | 8303220316 | 50-317 R |
| LOTITO, M. A. | 8303030071* | CONTRACT |
| LOTTS, A. L. | 8303030721 | RES |
| LOTTS, A. L. | 8303180556 | RES |
| LOUDERBACK, T. E. | 8303090019 | 40-8714 |
| LOUDERBACK, T. E. | 8303170314 | 40-8714 |
| LOVENDALE, P. C. | 8303030598* | 50-266 G |
| LOVENDALE, P. C. | 8303210637* | 50-315 G |
| LU, M. S. | 8303300642 | RES |
| LUBENAU, J. O. | 8303280125 | I&E |
| LUCAS, J. W. | 8303090513 | 40-4492 |
| LUCENA, S. P. | 8303170154 | XPORTLIC |
| LUCENA, S. P. | 8303170157* | XPORTLIC |
| LUCIA, S. | 8303300684* | 50-528 F |
| LUCK, L. B. | 8303230517 | NUREG |
| LUCK, W. D. | 8303080497 | 50-537 G |
| LUCK, W. D. | 8303290422 | 50-537 G |
| LUCKS, A. S. | 8303220169 | 50-329 A |
| LUDEWIG, H. | 8303140664 | 50-352 A |
| LUDWIG, W. C. | 8303040479* | 50-328 S |
| LUDWIG, W. C. | 8303040588* | 50-328 S |
| LUDWIG, W. C. | 8303140554* | 50-327 S |
| LUDWIG, W. C. | 8303150475* | 50-327 S |
| LUDWIG, W. C. | 8303240412* | 50-327 S |
| LUEBKE, E. A. | 8303290510 | 50-142 G |
| LUKZ, F. J. | 8303090668* | CONTRACT |
| LUKZ, F. J. | 8303160097* | CONTRACT |
| LUMB, R. F. | 8303150375* | 70-143 |
| LUNDVALL, A. E. | 8303010528 | 50-317 P |
| LUNDVALL, A. E. | 8303020035 | 50-317 P |
| LUNDVALL, A. E. | 8303090063 | 50-317 G |
| LUNDVALL, A. E. | 8303090217 | 50-317 P |
| LUNDVALL, A. E. | 8303090277 | 50-317 G |
| LUNDVALL, A. E. | 8303110130 | 50-317 F |
| LUNDVALL, A. E. | 8303110295 | 50-317 G |
| LUNDVALL, A. E. | 8303110308 | 50-317 G |
| LUNDVALL, A. E. | 8303150387 | 50-317 P |
| LUNDVALL, A. E. | 8303170056 | 50-317 P |
| LUNDVALL, A. E. | 8303170274 | 50-317 P |
| LUNDVALL, A. E. | 8303210177 | 50-317 P |
| LUNDVALL, A. E. | 8303220341 | 50-317 G |
| LUNDVALL, A. E. | 8303240377 | 50-317 F |
| LUNDVALL, A. E. | 8303290300 | 50-317 P |
| LUTTON, R. J. | 8303210016 | WASTE MGT |
| LUZA, K. V. | 8303100564 | NUREG |
| LYNCH, L. M. | 8303140513* | 40-8713 |
| LYTLE, R. J. | 8303290626 | WASTE MGT |
| MACDONALD, C. E. | 8303020355 | 71-6717 |
| MACDONALD, C. E. | 8303030230 | 71-9783 |
| MACDONALD, C. E. | 8303030243* | 71-9783 |
| MACDONALD, C. E. | 8303030251 | 71-4909 |
| MACDONALD, C. E. | 8303030262 | 71-9015 |
| MACDONALD, C. E. | 8303030311 | 71-9855 |
| MACDONALD, C. E. | 8303030317 | 71-6639 |
| MACDONALD, C. E. | 8303030706 | 71-5796 |
| MACDONALD, C. E. | 8303030712 | 71-6294 |
| MACDONALD, C. E. | 8303040113 | 71-492 |
| MACDONALD, C. E. | 8303040116* | 71-492 |
| MACDONALD, C. E. | 8303040316 | 71-9133 |
| MACDONALD, C. E. | 8303040322* | 71-9133 |
| MACDONALD, C. E. | 8303100547 | 71-9074 |
| MACDONALD, C. E. | 8303100549* | 71-9074 |
| MACDONALD, C. E. | 8303160692 | 71-6574 |
| MACDONALD, C. E. | 8303160696* | 71-6574 |
| MACDONALD, C. E. | 8303160700 | 71-9033 |
| MACDONALD, C. E. | 8303170641 | 71-9162 |
| MACDONALD, C. E. | 8303180134 | 71-9119 |
| MACDONALD, C. E. | 8303180139* | 71-9119 |
| MACDONALD, C. E. | 8303180160 | 71-6574 |
| MACDONALD, C. E. | 8303180515 | 71-6346 |
| MACDONALD, C. E. | 8303180547 | 71-5088 |
| MACDONALD, C. E. | 8303180550 | 71-5450 |
| MACDONALD, C. E. | 8303210133 | 71-9001 |
| MACDONALD, C. E. | 8303210137 | 71-5805 |
| MACDONALD, C. E. | 8303230448 | 71-9166 |
| MACDONALD, C. E. | 8303230452* | 71-9166 |
| MACDONALD, C. E. | 8303230457* | 71-9166 |
| MACDONALD, C. E. | 8303240191 | 71-9166 |
| MACDONALD, C. E. | 8303290682 | 71-9163 |
| MACDONALD, C. E. | 8303290713 | 71-9167 |
| MACDONALD, C. E. | 8303290757 | 71-5758 |
| MACDONALD, C. E. | 8303290761* | 71-5758 |
| MACDONALD, C. E. | 8303300081 | 71-9001 |
| MACDONALD, C. E. | 8303300084 | 71-5580 |
| MACDONALD, C. E. | 8303300087* | 71-5580 |
| MACDONALD, C. E. | 8303300096* | 71-9001 |
| MACDONALD, C. E. | 8303300104 | 71-9086 |
| MACDONALD, C. E. | 8303300106 | 71-5757 |
| MACDONALD, C. E. | 8303300109* | 71-5757 |
| MACDONALD, C. E. | 8303300112 | 71-9167 |
| MACDONALD, C. E. | 8303300117* | 71-9167 |
| MACDONALD, C. E. | 8303300136 | 71-9161 |
| MACDONALD, C. E. | 8303300142 | 71-6002 |
| MACDONALD, C. E. | 8303300148* | 71-6002 |
| MACDONALD, C. E. | 8303300285 | 71-9160 |
| MACDONALD, C. E. | 8303300337* | 71-9086 |
| MACDONALD, S. W. | 8303290497 | 50-329 Q |
| MACDOUGALL, E. A. | 8303020207* | 50-250 F |
| MACHIROS, A. | 8303230261 | 50-443 G |
| MACHIROS, A. | 8303230263* | 50-443 G |
| MACKAY, S. | 8303310089 | COMMISSION |
| MACKAY, S. D. | 8303290534 | 50-325 P |
| MACKAY, S. D. | 8303300441 | 50-324 P |
| MADDEN, J. S. | 8303090422* | CONTRACT |
| MADDEN, W. | 8303030136* | 50-244 G |
| MADDEN, W. | 8303030185* | 50-293 G |
| MADDEN, W. | 8303240568* | 50-333 G |
| MADDEN, W. J. | 8303160467* | 50-213 G |
| MADEDA, T. J. | 8303030473* | 50-255 G |
| MADEDA, T. J. | 8303140357* | 50-2 G |
| MADISON, A. | 8303170540* | 50-373 G |
| MADISON, A. L. | 8303170519* | 50-373 G |
| MADISON, A. L. | 8303240597* | 50-10 G |
| MADSEN, G. L. | 8303010220 | 50-382 G |
| MADSEN, G. L. | 8303010246 | 50-458 G |
| MADSEN, G. L. | 8303010405 | 50-298 G |
| MADSEN, G. L. | 8303010424 | 50-382 G |
| MADSEN, G. L. | 8303010442 | 50-445 G |
| MADSEN, G. L. | 8303010527 | 50-298 F |
| MADSEN, G. L. | 8303010554 | 50-112 G |
| MADSEN, G. L. | 8303010579 | 50-458 G |
| MADSEN, G. L. | 8303070075 | 50-267 G |
| MADSEN, G. L. | 8303070108 | 50-267 P |
| MADSEN, G. L. | 8303080367 | 50-458 G |
| MADSEN, G. L. | 8303110114 | 50-267 P |
| MADSEN, G. L. | 8303110256 | 50-267 P |
| MADSEN, G. L. | 8303150004* | 50-267 P |
| MADSEN, G. L. | 8303150199 | 50-382 G |
| MADSEN, G. L. | 8303150450 | 50-267 G |
| MADSEN, G. L. | 8303150488 | 50-498 G |
| MADSEN, G. L. | 8303150515 | 50-445 G |
| MADSEN, G. L. | 8303180215 | 50-267 G |
| MADSEN, G. L. | 8303180222 | 50-298 G |
| MADSEN, G. L. | 8303180228 | 50-298 G |
| MADSEN, G. L. | 8303180418 | 50-382 G |
| MADSEN, G. L. | 8303210604 | 50-382 G |
| MADSEN, G. L. | 8303210624 | 50-382 G |
| MADSEN, G. L. | 8303210650 | 50-382 G |
| MADSEN, G. L. | 8303250019 | 50-267 G |
| MADSEN, G. L. | 8303250093 | 50-267 P |
| MADSEN, G. L. | 8303250112 | 50-267 P |
| MADSEN, G. L. | 8303250135 | 50-267 P |
| MADSEN, G. L. | 8303280247 | 50-382 G |
| MAGID, A. F. | 6303040610* | 50-213 P |
| MAHON, C. R. | 8303140378* | 50-317 S |
| MAIER, J. E. | 8303010365 | 50-244 S |
| MAIER, J. E. | 8303010388 | 50-244 P |
| MAIER, J. E. | 8303010462 | 50-244 S |
| MAIER, J. E. | 8303010478 | 50-244 S |
| MAIER, J. E. | 8303080333 | 50-244 P |
| MAIER, J. E. | 8303080460 | 50-244 P |
| MAIER, J. E. | 8303090072 | 50-244 P |
| MAIER, J. E. | 8303100287* | 50-244 Q |
| MAIER, J. E. | 8303100302* | 50-244 Q |
| MAIER, J. E. | 8303100398* | 50-244 Q |
| MAIER, J. E. | 8303110217 | 50-244 Q |
| MAIER, J. E. | 8303110316 | 50-244 P |
| MAIER, J. E. | 8303110338 | 50-244 P |
| MAIER, J. E. | 8303170161 | 50-244 P |
| MAIER, J. E. | 8303220003 | 50-244 P |
| MAIER, J. E. | 8303230232 | 50-244 P |
| MAIER, J. E. | 8303230244 | 50-244 P |
| MAIER, J. E. | 8303290470 | 50-244 P |
| MAIER, J. E. | 8303310048* | 50-244 F |
| MALARD, J. C. | 8303310154* | FOIA |
| MALARD, J. C. | 8303310157* | FOIA |
| MALINOWSKI, D. D. | 8303010320* | 50-454 T |

# PERSONAL AUTHOR INDEX


| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| MALINOWSKI, D. D. | 8303010320* | 50-454 T |
| MALLETT, R. H. | 8303070120* | 50-537 A |
| MALLORY, C. W. | 8303030316 | 71-9080 |
| MALLORY, C. W. | 8303030326 | 71-9085 |
| MALLORY, C. W. | 8303100508 | 71-9151 |
| MALMROS, M. H. | 8303040600* | 50-344 Q |
| MALMROS, M. H. | 8303290446* | 50-288 Q |
| MALODY, C. W. | 8303210781 | 70-1257 |
| MALSCH, M. Q. | 8303100251 | 70-143 |
| MANEATIS, G. A. | 8303080017* | 50-275 T |
| MANEATIS, G. A. | 8303140446 | 50-275 Q |
| MANGAN, C. V. | 8303010628 | 50-410 S |
| MANGAN, C. V. | 8303070099 | 50-220 P |
| MANGAN, C. V. | 8303090145 | 50-220 P |
| MANGAN, C. V. | 8303100253 | 50-410 F |
| MANGAN, C. V. | 8303110288 | 50-220 P |
| MANGAN, C. V. | 8303150507 | 50-220 P |
| MANGAN, C. V. | 8303160136 | 50-220 R |
| MANGAN, C. V. | 8303160151 | 50-220 P |
| MANGAN, C. V. | 8303180341 | 50-220 F |
| MANGAN, C. V. | 8303220072 | 50-220 P |
| MANGAN, C. V. | 8303290444 | 50-220 Q |
| MANGAN, C. V. | 8303300041 | 50-220 P |
| MANKOFF, L. L. | 8303090201 | PT21 |
| MANKOFF, L. L. | 8303240349 | PT21 |
| MANNING, J. J. | 8303230142 | NUREG |
| MANNING, W. | 8303090093* | FOIA |
| MANNO, S. F. | 8303080057 | 50-410 S |
| MANNO, S. F. | 8303140613 | 50-410 S |
| MANNO, S. F. | 8303210578 | 50-410 S |
| MANNO, S. F. | 8303290427 | 50-410 S |
| MANRY, M. | 8303090188 | 50-321 R |
| MANRY, M. | 8303090360 | 50-321 R |
| MANRY, M. | 8303090363* | 50-321 R |
| MANSER, W. C. | 8303010702 | 70-143 |
| MANSER, W. C. | 8303210076 | 70-143 |
| MANSER, W. C. | 8303280241* | 70-143 |
| MARCH-LEUBA, J. | 8303140630 | NUREG |
| MARCHAL, J. | 8303020108 | XPORTLIC |
| MARCHAL, J. | 8303020112 | XPORTLIC |
| MARCHAL, J. | 8303040001 | XPORTLIC |
| MARCHAL, J. | 8303170022 | XPORTLIC |
| MARCHAL, J. | 8303280104 | XPORTLIC |
| MARGULIES, M. B. | 8303030340 | PROJ |
| MARINELLI, F. | 8303280097 | NUREG |
| MARINELLI, F. | 8303280114 | NUREG |
| MARKEY, E. J. | 8303040172* | 50-320 U |
| MARKEY, E. J. | 8303140644* | COMMISSION |
| MARKEY, E. J. | 8303290116* | 50-247 U |
| MARKT, D. | 8303090644* | 50-29 F |
| MARKT, D. | 8303090674* | 50-29 F |
| MARKT, D. | 8303240118* | 50-29 F |
| MARKT, D. I. | 8303100546* | 50-29 F |
| MARLEY, J. A. | 8303010092 | WASTE MGT |
| MARQUEZ, R. A. | 8303280091 | WASTE MGT |
| MARSH, C. A. | 8303170678 | 71-9026 |
| MARSHALL, J. R. | 8303010513 | 50-368 Q |
| MARSHALL, J. R. | 8303010519* | 50-368 Q |
| MARSHALL, J. R. | 8303010685* | 50-313 Q |
| MARSHALL, J. R. | 8303030518 | 50-368 S |
| MARSHALL, J. R. | 8303030614 | 50-368 S |
| MARSHALL, J. R. | 8303040333 | 50-368 P |
| MARSHALL, J. R. | 8303040393 | 50-313 P |
| MARSHALL, J. R. | 8303040407 | 50-313 P |
| MARSHALL, J. R. | 8303040593 | 50-313 P |
| MARSHALL, J. R. | 8303040594 | 50-313 H |
| MARSHALL, J. R. | 8303040597 | 50-313 P |
| MARSHALL, J. R. | 8303040611 | 50-313 Q |
| MARSHALL, J. R. | 8303070028 | 50-313 V |
| MARSHALL, J. R. | 8303070128 | 50-313 P |
| MARSHALL, J. R. | 8303080038 | 50-368 R |
| MARSHALL, J. R. | 8303080055 | 50-313 R |
| MARSHALL, J. R. | 8303080062 | 50-313 P |
| MARSHALL, J. R. | 8303080272 | 50-313 Q |
| MARSHALL, J. R. | 8303080299 | 50-313 P |
| MARSHALL, J. R. | 8303080346 | 50-313 R |
| MARSHALL, J. R. | 8303090594* | 50-313 F |
| MARSHALL, J. R. | 8303110328 | 50-313 P |
| MARSHALL, J. R. | 8303110352 | 50-313 P |
| MARSHALL, J. R. | 8303140059 | 50-313 P |
| MARSHALL, J. R. | 8303140370 | 50-313 P |
| MARSHALL, J. R. | 8303150381 | 50-313 R |
| MARSHALL, J. R. | 8303150481 | 50-368 S |
| MARSHALL, J. R. | 8303150517 | 50-368 R |
| MARSHALL, J. R. | 8303160388 | 50-313 P |
| MARSHALL, J. R. | 8303210329 | 50-313 P |
| MARSHALL, J. R. | 8303210399 | 50-313 P |
| MARSHALL, J. R. | 8303220044 | 50-313 P |
| MARSHALL, J. R. | 8303240354 | 50-368 S |
| MARSHALL, J. R. | 8303240374 | 50-313 S |
| MARSHALL, J. R. | 8303240478* | 50-313 Q |
| MARSHALL, J. R. | 8303250021 | 50-368 S |
| MARSHALL, J. R. | 8303250036 | 50-313 Q |
| MARSHALL, J. R. | 8303250133 | 50-313 P |
| MARSHALL, J. R. | 8303280154 | 50-368 S |
| MARSHALL, J. R. | 8303280208 | 50-368 S |
| MARSHALL, J. R. | 8303280266* | 50-313 F |
| MARSHALL, J. R. | 8303290063 | 50-313 R |
| MARSHALL, J. R. | 8303290222 | 50-368 P |
| MARSHALL, J. R. | 8303290419 | 50-313 P |
| MARSHALL, J. R. | 8303290439 | 50-368 Q |
| MARSHALL, J. R. | 8303290641* | 50-313 F |
| MARSHALL, J. S. | 8303220010 | 50-445 E |
| MARSHALL, W. H. | 8303290447 | PRM |
| MARSHALL, W. H. | 8303290447 | PRM |
| MARSTON, R. R. | 8303210730* | 50-338 Q |
| MARTIN, D. E. | 8303180132 | 40-8452 |
| MARTIN, D. E. | 8303230441 | 40-2259 |
| MARTIN, J. B. | 8303100480* | FOIA |
| MARTIN, J. B. | 8303210014 | MISC |
| MARTIN, J. B. | 8303310043* | WASTE MGT |
| MARTIN, J. W. | 8303290739* | 50-280 F |
| MARTIN, L. E. | 8303280262* | 50-382 Q |
| MARTIN, R. | 8303030084 | 50-352 A |
| MARTIN, R. | 8303030107 | 50-352 A |
| MARTIN, R. | 8303100013 | 50-352 A |
| MARTIN, R. A. | 8303160175 | RES |
| MARTIN, R. E. | 8303290101 | 50-352 A |
| MARTIN, R. E. | 8303300315 | 50-352 F |
| MARTIN, R. E. | 8303300615 | 50-352 A |
| MARTIN, R. E. | 8303300622 | 50-352 A |
| MARTIN, R. L. | 8303150518* | 50-29 P |
| MARTIN, T. J. | 8303030470* | 50-354 A |
| MARTIN, T. J. | 8303090061 | 50-354 S |
| MARTIN, T. J. | 8303140386 | 50-354 S |
| MARTIN, T. J. | 8303140574 | 50-354 Q |
| MARTIN, T. T. | 8303110278 | 50-277 Q |
| MARTIN, T. T. | 8303010434 | 50-219 Q |
| MARTIN, T. T. | 8303030129 | 50-244 Q |
| MARTIN, T. T. | 8303030144 | 50-423 Q |
| MARTIN, T. T. | 8303030156 | 50-272 Q |
| MARTIN, T. T. | 8303030165 | 70-359 |
| MARTIN, T. T. | 8303030181 | 50-293 Q |
| MARTIN, T. T. | 8303030182 | 50-334 Q |
| MARTIN, T. T. | 8303030198 | 50-320 Q |
| MARTIN, T. T. | 8303030246 | 50-317 Q |
| MARTIN, T. T. | 8303030298 | 50-286 Q |
| MARTIN, T. T. | 8303030360 | 50-322 Q |
| MARTIN, T. T. | 8303030644 | 50-272 Q |
| MARTIN, T. T. | 8303040448 | 50-293 Q |
| MARTIN, T. T. | 8303040528 | 70-135 |
| MARTIN, T. T. | 8303080004 | 50-220 Q |
| MARTIN, T. T. | 8303080359 | 50-277 Q |
| MARTIN, T. T. | 8303100146 | 50-336 Q |
| MARTIN, T. T. | 8303100169 | 50-309 Q |
| MARTIN, T. T. | 8303100240 | 50-333 Q |
| MARTIN, T. T. | 8303100275 | 50-443 Q |
| MARTIN, T. T. | 8303100293 | 50-293 Q |
| MARTIN, T. T. | 8303100297 | 50-387 Q |
| MARTIN, T. T. | 8303100314 | 50-388 Q |
| MARTIN, T. T. | 8303100319 | 50-272 Q |
| MARTIN, T. T. | 8303100329 | 70-135 |
| MARTIN, T. T. | 8303100336 | 50-272 Q |
| MARTIN, T. T. | 8303100380 | 50-412 Q |
| MARTIN, T. T. | 8303110032* | 50-358 A |
| MARTIN, T. T. | 8303140216 | 50-322 Q |
| MARTIN, T. T. | 8303140223 | 50-213 Q |
| MARTIN, T. T. | 8303140440 | 70-124 |
| MARTIN, T. T. | 8303150540 | 50-309 Q |
| MARTIN, T. T. | 8303160429 | 50-272 Q |
| MARTIN, T. T. | 8303160456 | 50-213 Q |
| MARTIN, T. T. | 8303160461 | 50-289 Q |
| MARTIN, T. T. | 8303160466 | 70-371 |
| MARTIN, T. T. | 8303160491 | 70-820 |
| MARTIN, T. T. | 8303160501 | 50-333 Q |
| MARTIN, T. T. | 8303160524 | 50-29 Q |
| MARTIN, T. T. | 8303160558 | 50-317 Q |
| MARTIN, T. T. | 8303160612 | 50-245 Q |
| MARTIN, T. T. | 8303180500 | 50-213 F |
| MARTIN, T. T. | 8303210480 | 50-388 Q |
| MARTIN, T. T. | 8303240287 | 50-352 Q |
| MARTIN, T. T. | 8303240360 | 50-387 Q |
| MARTIN, T. T. | 8303240369 | 50-213 Q |
| MARTIN, T. T. | 8303240438 | 50-334 Q |
| MARTIN, T. T. | 8303240439 | 50-213 Q |
| MARTIN, T. T. | 8303240462 | 50-322 Q |
| MARTIN, T. T. | 8303240499 | 50-423 Q |
| MARTIN, T. T. | 8303240518 | 50-247 Q |
| MARTIN, T. T. | 8303240521 | 50-272 Q |
| MARTIN, T. T. | 8303240537 | 70-33 |
| MARTIN, T. T. | 8303240557 | 50-333 Q |
| MARTIN, T. T. | 8303240582 | 50-289 Q |
| MARTIN, T. T. | 8303280203 | 50-247 Q |
| MARTIN, T. T. | 8303280207 | 50-245 Q |
| MARTIN, T. T. | 8303280271 | 50-277 Q |
| MARTIN, T. T. | 8303280294 | 50-354 Q |
| MARTIN, T. T. | 8303290314 | 50-334 Q |
| MARTIN, T. T. | 8303290325 | 50-184 Q |
| MARTIN, T. T. | 8303290337 | 50-247 Q |
| MARTIN, T. T. | 8303290377 | 50-77 Q |
| MARTIN, T. T. | 8303300332 | 50-286 Q |
| MARTIN, T. T. | 8303300383 | 50-170 Q |
| MARTIN, T. T. | 8303300389 | 50-277 F |
| MARTIN, T. T. | 8303300397 | 70-820 |
| MARTIN, T. T. | 8303300433 | 50-247 Q |
| MARTIN, T. T. | 8303300468 | 50-272 Q |
| MARTIN, T. T. | 8303300493 | 50-309 Q |
| MARTINEZ, L. J. | 8303240275 | RES |
| MASON, C. C. | 8303080368 | 50-327 R |
| MASON, C. C. | 8303080377* | 50-327 R |
| MASON, C. C. | 8303100326 | 50-327 R |
| MASON, C. C. | 8303150440 | 50-327 R |
| MASON, C. C. | 8303150463 | 50-327 R |
| MASON, C. C. | 8303150464* | 50-327 R |
| MASON, J. B. | 8303070087 | TOPREP |
| MASSARO, S. A. | 8303140681 | NUREG |
| MASSEY, W. F. | 8303030572 | PT21 |
| MATAKAS, P. A. | 8303030359* | 50-410 Q |
| MATAKAS, P. A. | 8303110088* | 50-311 S |
| MATERS, B. R. | 8303300203 | 50-16 J |
| MATHIES, B. L. | 8303160295* | 50-250 P |
| MATHIES, B. L. | 8303160304* | 50-250 P |
| MATHIS, C. J. | 8303040401 | 50-293 R |
| MATHIS, C. J. | 8303080510 | 50-293 R |
| MATHIS, C. J. | 8303140592 | 50-293 S |
| MATHIS, C. J. | 8303150575 | 50-293 R |
| MATHIS, C. J. | 8303180497 | 50-293 S |
| MATHIS, C. J. | 8303250068 | 50-293 S |
| MATHIS, C. J. | 8303250118 | 50-293 S |
| MATLOCK, R. G. | 8303010569 | 50-397 S |
| MATLOCK, R. G. | 8303040253 | 50-397 S |
| MATLOCK, R. G. | 8303080011 | 50-397 S |
| MATLOCK, R. G. | 8303140633 | 50-397 S |
| MATSIS, J. P. | 8303240129* | FOIA |
| MATSIS, J. P. | 8303240172* | FOIA |
| MATTHEWS, B. A. | 8303080128 | 50-261 Q |
| MATTHEWS, T. P. | 8303180325* | 50-285 R |
| MATTIA, J. C. | 8303280188* | 50-423 Q |
| MATTIA, M. J. | 8303010018* | CONTRACT |
| MATTIA, M. J. | 8303010714* | CONTRACT |
| MATTIA, M. J. | 8303020177* | CONTRACT |
| MATTIA, M. J. | 8303030071* | CONTRACT |
| MATTIA, M. J. | 8303090599* | CONTRACT |
| MATTIA, M. J. | 8303160069* | CONTRACT |
| MATTIA, M. J. | 8303290264* | CONTRACT |
| MATTIA, M. J. | 8303290596* | CONTRACT |
| MATTIA, M. J. | 8303300574* | CONTRACT |
| MATTIA, M. J. | 8303310352* | CONTRACT |
| MATTIMOE, J. J. | 8303010382 | 50-312 H |
| MATTIMOE, J. J. | 8303090509* | 50-312 Q |
| MATTIMOE, J. J. | 8303090435* | 50-312 F |
| MATTIMOE, J. J. | 8303110099 | 50-312 P |
| MATTIMOE, J. J. | 8303110149 | 50-312 S |
| MATTIMOE, J. J. | 8303110264 | 50-312 F |
| MATTIMOE, J. J. | 8303110277 | 50-312 H |
| MATTIMOE, J. J. | 8303110311 | 50-312 S |
| MATTIMOE, J. J. | 8303110354 | 50-312 S |
| MATTOX, J. | 8303300356 | 50-445 Q |
| MATTOX, J. | 8303300411 | 50-446 Q |
| MATTSON, R. J. | 8205190297* | 50-206 P |
| MATTSON, R. J. | 8208040524* | 50-346 F |
| MATTSON, R. J. | 8303030735* | 50-289 P |
| MATTSON, R. J. | 8303110227 | 50-322 T |
| MATTSON, R. J. | 8303110307* | 50-361 P |
| MATTSON, R. J. | 8303210025* | 50-289 P |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| MATTSON, R. J. | 8303240157 | 50-272 S |
| MAUPIN, M. W. | 8303040479 | 50-338 G |
| MAUPIN, M. W. | 8303040479 | 50-338 G |
| MAUPIN, M. W. | 8303040483 | 50-338 G |
| MAUPIN, M. W. | 8303040483 | 50-338 G |
| MAURA, F. | 8303140423* | 50-373 G |
| MAURIN, L. V. | 8303010499 | 50-382 A |
| MAURIN, L. V. | 8303010600 | 50-382 A |
| MAURIN, L. V. | 8303010669 | 70-2946 |
| MAURIN, L. V. | 8303010703 | 70-2946 |
| MAURIN, L. V. | 8303020122 | 70-2946 |
| MAURIN, L. V. | 8303030013 | 70-2946 |
| MAURIN, L. V. | 8303030678 | 50-382 A |
| MAURIN, L. V. | 8303080014 | 50-382 A |
| MAURIN, L. V. | 8303080083 | 50-382 A |
| MAURIN, L. V. | 8303080195 | 50-382 S |
| MAURIN, L. V. | 8303080298 | 50-382 S |
| MAURIN, L. V. | 8303080455 | 50-382 S |
| MAURIN, L. V. | 8303080461 | 50-382 S |
| MAURIN, L. V. | 8303080467 | 50-382 A |
| MAURIN, L. V. | 8303080486 | 50-382 G |
| MAURIN, L. V. | 8303090302 | 50-382 F |
| MAURIN, L. V. | 8303100274 | 50-382 A |
| MAURIN, L. V. | 8303100285 | 50-382 A |
| MAURIN, L. V. | 8303160285 | 50-382 R |
| MAURIN, L. V. | 8303160506 | 50-382 A |
| MAURIN, L. V. | 8303160521 | 50-382 F |
| MAURIN, L. V. | 8303170360 | 50-382 A |
| MAURIN, L. V. | 8303180247 | 50-382 F |
| MAURIN, L. V. | 8303210351 | 50-382 E |
| MAURIN, L. V. | 8303210407 | 50-382 E |
| MAURIN, L. V. | 8303210556 | 50-382 S |
| MAURIN, L. V. | 8303210569 | 50-382 S |
| MAURIN, L. V. | 8303210610* | 50-382 G |
| MAURIN, L. V. | 8303220004 | 50-382 F |
| MAURIN, L. V. | 8303220459 | 70-2946 |
| MAURIN, L. V. | 8303240188 | 50-382 A |
| MAURIN, L. V. | 8303240196* | 50-382 A |
| MAURIN, L. V. | 8303240514 | 50-382 F |
| MAURIN, L. V. | 8303280086 | 50-382 E |
| MAURIN, L. V. | 8303280121 | 50-382 S |
| MAURIN, L. V. | 8303280124 | 50-382 S |
| MAURIN, L. V. | 8303280179 | 50-382 S |
| MAURIN, L. V. | 8303280186 | 50-382 S |
| MAURIN, L. V. | 8303290407 | 50-382 E |
| MAURIN, L. V. | 8303310045* | 50-382 A |
| MAUSSHARDT, D. B. | 8303220410* | 40-2061 |
| MAUSSHARDT, D. B. | 8303220415* | 40-2061 |
| MAUSSHARDT, D. B. | 8303220423* | 40-2061 |
| MAUSSHARDT, D. B. | 8303220437* | 40-2061 |
| MAWSON, T. J. | 8303040610* | 50-213 P |
| MAXSON, J. K. | 8303220277 | 50-454 G |
| MAXWELL, G. F. | 8303010137* | 50-400 G |
| MAXWELL, G. F. | 8303010553* | 50-400 G |
| MAY, E. L. | 8303010679* | 50-29 S |
| MAY, E. L. | 8303090224* | 50-29 S |
| MAY, E. L. | 8303140538* | 50-29 S |
| MAYWEATHER, L. | 8303080097* | 50-361 R |
| MAYWEATHER, L. | 8303150574* | 50-361 R |
| MAYWEATHER, L. | 8303150592* | 50-361 R |
| MCALLISTER, S. A. | 8303140466* | 50-309 S |
| MCALPINE, E. J. | 8303010480* | 70-143 |
| MCALPINE, E. J. | 8303010593* | 70-143 |
| MCALPINE, E. J. | 8303010621* | 70-1113 |
| MCALPINE, E. J. | 8303010626* | 70-27 |
| MCALPINE, E. J. | 8303210363* | 70-1113 |
| MCALPINE, E. J. | 8303210369* | 70-1151 |
| MCALPINE, E. J. | 8303210580* | 70-143 |
| MCALPINE, E. J. | 8303210583* | 70-143 |
| MCALPINE, E. J. | 8303210600* | 70-1113 |
| MCALPINE, E. J. | 8303210643* | 70-143 |
| MCALPINE, E. J. | 8303240515 | 70-143 |
| MCALPINE, E. J. | 8303280284* | 70-143 |
| MCBREARTY, R. | 8303240591* | 50-289 G |
| MCBREARTY, R. A. | 8303100344* | 50-272 G |
| MCBRIDE, L. M. | 8303010389* | 50-267 R |
| MCBRIDE, L. M. | 8303150350* | 50-267 R |
| MCBRIDE, L. M. | 8303250009* | 50-267 R |
| MCBRIDE, M. | 8303280214* | 50-245 G |
| MCBRIDE, M. H. | 8303160570* | 50-317 G |
| MCCABE, E. C. | 8303100243* | 50-317 G |
| MCCABE, E. C. | 8303250070* | 50-277 G |
| MCCABE, E. C. | 8303280231* | 50-387 G |
| MCCANN, J. | 8303280231* | 50-387 G |
| MCCLESKEY, K. E. | 8303040522 | 50-322 G |
| MCCLESKEY, K. E. | 8303080142 | 50-322 G |
| MCCLESKEY, K. E. | 8303080142 | 50-322 G |
| MCCLINTOCK, R. O. | 8303140145* | 70-2684 |
| MCCLINTOCK, R. O. | 8303140159* | FOIA |
| MCCLINTOCK, R. O. | 8303140165* | 70-2684 |
| MCCLINTOCK, R. O. | 8303140177* | FOIA |
| MCCLINTOCK, R. O. | 8303140184* | 70-2684 |
| MCCLINTOCK, R. O. | 8303140190* | FOIA |
| MCCLINTOCK, R. O. | 8303140196* | FOIA |
| MCCLINTOCK, R. O. | 8303140201* | FOIA |
| MCCLOSKEY, D. F. | 8303300239* | 50-206 F |
| MCCLUNG, C. E. | 8303230183 | 50-361 G |
| MCCLUNG, C. E. | 8303230183 | 50-361 G |
| MCCLUNG, C. E. | 8303230183 | 50-361 G |
| MCCLUNG, R. J. | 8303030538* | GA999 |
| MCCLUNG, R. J. | 8303030547* | GA999 |
| MCCLUNG, R. W. | 8303140622 | NUREG |
| MCCLUNG, R. W. | 8303290710 | NUREG |
| MCCORKLE, Q. W. | 8303100399* | FOIA |
| MCCORKLE, Q. W. | 8303100466* | FOIA |
| MCDERMOTT, D. | 8303030335 | CONTRACT |
| MCDERMOTT, D. | 8303030348 | CONTRACT |
| MCDERMOTT, D. | 8303030672 | CONTRACT |
| MCDERMOTT, D. | 8303030774 | CONTRACT |
| MCDERMOTT, D. | 8303100412 | CONTRACT |
| MCDERMOTT, D. | 8303150708 | CONTRACT |
| MCDERMOTT, D. | 8303290013 | CONTRACT |
| MCDERMOTT, D. | 8303290018 | CONTRACT |
| MCDERMOTT, D. | 8303290406 | CONTRACT |
| MCDERMOTT, D. | 8303290528 | CONTRACT |
| MCDERMOTT, D. | 8303290755 | CONTRACT |
| MCDERMOTT, D. | 8303290763 | CONTRACT |
| MCDERMOTT, D. | 8303290783 | CONTRACT |
| MCDERMOTT, D. | 8303290793 | CONTRACT |
| MCDERMOTT, D. | 8303300061 | CONTRACT |
| MCDERMOTT, D. | 8303300073 | CONTRACT |
| MCDERMOTT, D. | 8303300297 | CONTRACT |
| MCDERMOTT, D. | 8303300568 | CONTRACT |
| MCDERMOTT, D. | 8303300598 | CONTRACT |
| MCDERMOTT, D. | 8303300680 | CONTRACT |
| MCDERMOTT, D. | 8303300687 | CONTRACT |
| MCDERMOTT, D. | 8303310072 | CONTRACT |
| MCDERMOTT, D. | 8303310108 | CONTRACT |
| MCDERMOTT, D. | 8303310132 | CONTRACT |
| MCDERMOTT, D. | 8303310151 | CONTRACT |
| MCDERMOTT, D. | 8303310186 | CONTRACT |
| MCDERMOTT, D. | 8303310365 | CONTRACT |
| MCDERMOTT, D. | 8303310370 | CONTRACT |
| MCDERMOTT, D. | 8303310621 | CONTRACT |
| MCDERMOTT, D. | 8303310642 | CONTRACT |
| MCDIARMID, R. C. | 8303070109 | PROJ |
| MCDIARMID, R. C. | 8303070109 | PROJ |
| MCDONALD, C. K. | 8303150202* | 50-443 A |
| MCDONALD, D. G. | 8303020203 | 50-250 F |
| MCDONALD, D. G. | 8303040267 | 50-250 P |
| MCDONALD, D. G. | 8303150062 | 50-250 P |
| MCDONALD, D. G. | 8303290107 | 50-250 P |
| MCDONALD, D. G. | 8303310089 | COMMISSION |
| MCDONALD, R. J. | 8303290336* | CONTRACT |
| MCDONALD, R. P. | 8303010299 | 50-348 J |
| MCDOW, J. | 8303280016 | 50-261 G |
| MCDOWELL, T. | 8303220419* | WASTE MGT |
| MCDUFFIE, M. A. | 8303220164 | 50-400 A |
| MCFARLAND, C. R. | 8303010341* | 50-390 G |
| MCFARLAND, C. R. | 8303210739* | 50-400 G |
| MCGARRY, J. M. | 8303040223* | 10CFR |
| MCGAUGHY, J. | 8303010481* | 50-416 G |
| MCGAUGHY, J. | 8303040420 | 50-416 S |
| MCGAUGHY, J. P. | 8303010178 | 50-416 S |
| MCGAUGHY, J. P. | 8303010193 | 50-416 S |
| MCGAUGHY, J. P. | 8303010212 | 50-416 S |
| MCGAUGHY, J. P. | 8303010226 | 50-416 S |
| MCGAUGHY, J. P. | 8303010343 | 50-416 S |
| MCGAUGHY, J. P. | 8303010473* | 50-416 G |
| MCGAUGHY, J. P. | 8303010491* | 50-416 G |
| MCGAUGHY, J. P. | 8303010524* | 50-416 G |
| MCGAUGHY, J. P. | 8303010547 | 50-416 G |
| MCGAUGHY, J. P. | 8303010548* | 50-416 G |
| MCGAUGHY, J. P. | 8303040319 | 50-416 S |
| MCGAUGHY, J. P. | 8303040358 | 50-416 S |
| MCGAUGHY, J. P. | 8303040498 | 50-416 S |
| MCGAUGHY, J. P. | 8303040506 | 50-416 S |
| MCGAUGHY, J. P. | 8303040541 | 50-416 S |
| MCGAUGHY, J. P. | 8303040620 | 50-416 S |
| MCGAUGHY, J. P. | 8303080508 | 50-416 E |
| MCGAUGHY, J. P. | 8303140388 | 50-416 S |
| MCGAUGHY, J. P. | 8303140403 | 50-416 S |
| MCGAUGHY, J. P. | 8303140498 | 50-416 S |
| MCGAUGHY, J. P. | 8303140557 | 50-416 S |
| MCGAUGHY, J. P. | 8303150146 | 50-416 S |
| MCGAUGHY, J. P. | 8303150242 | 50-416 S |
| MCGAUGHY, J. P. | 8303150443 | 50-416 S |
| MCGAUGHY, J. P. | 8303150576 | 50-416 S |
| MCGAUGHY, J. P. | 8303160300 | 50-416 S |
| MCGAUGHY, J. P. | 8303160397 | 50-416 S |
| MCGAUGHY, J. P. | 8303160436 | 50-416 S |
| MCGAUGHY, J. P. | 8303160452 | 50-416 S |
| MCGAUGHY, J. P. | 8303160457 | 50-416 S |
| MCGAUGHY, J. P. | 8303160540 | 50-416 S |
| MCGAUGHY, J. P. | 8303160551 | 50-416 S |
| MCGAUGHY, J. P. | 8303180027 | 50-416 S |
| MCGAUGHY, J. P. | 8303180248 | 50-416 S |
| MCGAUGHY, J. P. | 8303180281 | 50-416 S |
| MCGAUGHY, J. P. | 8303180359 | 50-416 S |
| MCGAUGHY, J. P. | 8303210537 | 50-416 S |
| MCGAUGHY, J. P. | 8303210579* | 50-416 G |
| MCGAUGHY, J. P. | 8303210649* | 50-416 G |
| MCGAUGHY, J. P. | 8303210703* | 50-416 G |
| MCGAUGHY, J. P. | 8303210718* | 50-416 G |
| MCGAUGHY, J. P. | 8303210725* | 50-416 G |
| MCGAUGHY, J. P. | 8303210736* | 50-416 G |
| MCGAUGHY, J. P. | 8303220266 | 50-416 S |
| MCGAUGHY, J. P. | 8303220348 | 50-416 S |
| MCGAUGHY, J. P. | 8303230020 | 50-416 R |
| MCGAUGHY, J. P. | 8303240393 | 50-416 S |
| MCGAUGHY, J. P. | 8303240420 | 50-416 S |
| MCGAUGHY, J. P. | 8303240432 | 50-416 S |
| MCGAUGHY, J. P. | 8303240488 | 50-416 S |
| MCGAUGHY, J. P. | 8303240507 | 50-416 S |
| MCGAUGHY, J. P. | 8303240520 | 50-416 S |
| MCGAUGHY, J. P. | 8303240531 | 50-416 S |
| MCGAUGHY, J. P. | 8303240552 | 50-416 S |
| MCGAUGHY, J. P. | 8303240560 | 50-416 S |
| MCGAUGHY, J. P. | 8303240590 | 50-416 S |
| MCGAUGHY, J. P. | 8303280310 | 50-416 P |
| MCGINTY, D. M. | 8303090150 | 50-186 F |
| MCGOWAN, J. K. | 8303090377* | 50-348 F |
| MCGREGOR, L. G. | 8303030641* | 50-456 G |
| MCGREGOR, L. G. | 8303170444* | 50-456 G |
| MCGUIRE, D. P. | 8303020096* | 50-247 T |
| MCGUIRE, D. R. | 8303010489* | 50-390 G |
| MCGUIRE, D. R. | 8303150401* | 50-327 G |
| MCGUIRE, D. R. | 8303150505* | 50-370 G |
| MCGUIRE, D. R. | 8303150578* | 50-261 G |
| MCGUIRE, D. R. | 8303280148* | 50-269 G |
| MCGUIRE, D. R. | 8303280291* | 50-321 G |
| MCGUIRE, D. R. | 8303290403* | 50-280 G |
| MCGUIRE, D. R. | 8303290450* | 50-250 G |
| MCGUIRE, D. R. | 8303290485* | 50-338 G |
| MCGURREN, H. J. | 8303040324 | 50-338 G |
| MCGURREN, H. J. | 8303100142 | 50-338 G |
| MCINTOSH, M. D. | 8303080324* | 50-369 P |
| MCINTOSH, M. D. | 8303250100* | 50-369 F |
| MCKAY, E. D. | 8303150130 | NUREG |
| MCKAY, L. R. | 8302100345 | PRM |
| MCKEON, P. J. | 8303140575* | 50-443 G |
| MCKEOWN, L. M. | 8303030268* | 50-317 G |
| MCKINLEY, C. J. | 8303180241* | 50-395 S |
| MCKINNEY, C. J. | 8303010222* | 50-395 S |
| MCKINNEY, C. J. | 8303010291* | 50-395 S |
| MCKINNEY, C. J. | 8303010457* | 50-395 S |
| MCKINNEY, C. J. | 8303010474* | 50-395 S |
| MCKINNEY, C. J. | 8303010507* | 50-395 S |
| MCKINNEY, C. J. | 8303010566* | 50-395 S |
| MCKINNEY, C. J. | 8303040376* | 50-395 S |
| MCKINNEY, C. J. | 8303040565* | 50-395 S |
| MCKINNEY, C. J. | 8303180234* | 50-395 S |
| MCKINNEY, C. J. | 8303180268* | 50-395 S |
| MCKINNEY, C. J. | 8303240539* | 50-395 S |
| MCKINNEY, C. J. | 8303240592* | 50-395 S |
| MCKINNEY, C. J. | 8303240600* | 50-395 S |
| MCKNIGHT, T. R. | 8303010022 | 71-9138 |
| MCLAUGHLIN, L. | 8303160586* | 50-315 S |
| MCLAURIN, J. W. | 8303090433* | CONTRACT |
| MCLEAREN, T. | 8303090416 | CONTRACT |
| MCLEAREN, T. | 8303160079 | CONTRACT |
| MCLEAREN, T. | 8303280098 | CONTRACT |
| MCMURRAY, C. M. | 8303310269 | 50-322 G |
| MCMURRAY, C. M. | 8303310269 | 50-322 G |

# PERSONAL AUTHOR INDEX


| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| MCMURRAY, C M | 8303310278* | 50-322 Q |
| MCMURRAY, C M | 8303310278* | 50-322 Q |
| MCNAMARA, A E | 8303080217* | 50-244 R |
| MCNEIL, M B | 8303290566* | WASTE MGT |
| MCNEILL, C A | 8303040437 | 50-33J R |
| MCNEILL, C A | 8303080472 | 50-333 S |
| MCNEILL, C A | 8303080501 | 50-333 S |
| MCNEILL, C A | 8303090182 | 50-333 S |
| MCNEILL, C A | 8303100140* | 50-333 Q |
| MCNEILL, C A | 8303100246* | 50-333 Q |
| MCNEILL, C A | 8303140222 | 50-333 R |
| MCNEILL, C A | 8303140497 | 50-333 S |
| MCNEILL, C A | 8303250032 | 50-333 S |
| MCNEILL, C A | 8303250059 | 50-333 S |
| MCNEILL, C A | 8303300310* | 50-333 Q |
| MCNEILL, R | 8303100235* | 50-275 P |
| MCNEILL, R | 8303160342* | 50-275 R |
| MCNEILL, W M | 8303010468* | GA999 |
| MCNEILL, W M | 8303070136* | GA999 |
| MEADE, R B | 8303210116 | WASTE MGT |
| MEDFORD, M O | 8303020034 | 50-361 P |
| MEDFORD, M O | 8303180040 | 50-361 P |
| MEISS, R L | 8303010080 | PROJ |
| MELBER, B D | 8303090510 | NUREG |
| MELLO, R M | 8303070120* | 50-537 A |
| MENCZER, W B | 8303240597* | 50-10 Q |
| MENDELSON, I N | 8303160071* | CONTRACT |
| MENDEZ, R | 8303220050* | 50-483 Q |
| MENDONCA, M | 8303290590* | 50-361 Q |
| MENDONCA, M M | 8303040421* | 50-275 Q |
| MENINICK, J | 8303290830 | WASTE MGT |
| MENINICK, J | 8303290834* | WASTE MGT |
| MENTER, L | 8303150695 | XPORTLIC |
| MERRITT, J T | 8303010328* | 50-445 Q |
| MERRIWEATHER, N | 8303010398* | 50-438 Q |
| MERRIWEATHER, N | 8303210719* | 50-400 Q |
| METTA, L L | 8303030378 | 50-322 H |
| MEYER, A | 8303010094 | 50-454 Q |
| MEYER, G | 8303240591* | 50-289 Q |
| MEYER, G C | 8303150057 | 50-470 A |
| MEYER, G W | 8303160431* | 50-272 Q |
| MEYER, G W | 8303160433* | 50-272 Q |
| MEYER, R E | 8303170624 | NUREG |
| MICHEJDA, O | 8303280233* | 50-397 S |
| MICHELSON, C A | 8212220501 | MISC |
| MIDURA, H J | 8303010680 | 50-272 S |
| MIDURA, H J | 8303030009 | 50-311 S |
| MIDURA, H J | 8303030050 | 50-311 S |
| MIDURA, H J | 8303030060 | 50-272 S |
| MIDURA, H J | 8303030118 | 50-272 S |
| MIDURA, H J | 8303030257 | 50-272 S |
| MIDURA, H J | 8303030292 | 50-272 S |
| MIDURA, H J | 8303080329 | 50-31 S |
| MIDURA, H J | 8303090175 | 50-272 S |
| MIDURA, H J | 8303090215 | 50-311 S |
| MIDURA, H J | 8303090238 | 50-272 S |
| MIDURA, H J | 8303110304 | 50-272 S |
| MIDURA, H J | 8303140238 | 50-311 S |
| MIDURA, H J | 8303140242 | 50-311 S |
| MIDURA, H J | 8303140347 | 50-311 S |
| MIDURA, H J | 8303140545 | 50-272 S |
| MIDURA, H J | 8303140576 | 50-272 S |
| MIDURA, H J | 8303170494 | 50-272 R |
| MIDURA, H J | 8303180305 | 50-272 S |
| MIDURA, H J | 8303180319 | 50-272 S |
| MIDURA, H J | 8303180361 | 50-272 S |
| MIDURA, H J | 8303180419 | 50-272 S |
| MIDURA, H J | 8303180423 | 50-272 S |
| MIDURA, H J | 8303210522 | 50-272 S |
| MIDURA, H J | 8303210627 | 50-272 S |
| MIGHT, A | 8303080276* | 50-316 R |
| MIGHT, A | 8303080429* | 50-315 R |
| MIHALCIK, J A | 8303310270 | 50-317 P |
| MIHOVILOVICH, J | 8303080262 | 50-454 T |
| MIKLOS, J | 8303100443 | NUREG |
| MIKLOS, J | 8303100453 | NUREG |
| MILES, E B | 8303030062 | CONTRACT |
| MILES, E B | 8303090592 | CONTRACT |
| MILES, E B | 8303290253 | CONTRACT |
| MILES, E B | 8303290589 | CONTRACT |
| MILES, E B | 8303310349 | CONTRACT |
| MILEY, G H | 8303030212 | 50-151 R |
| MILLER, D B | 8303040539 | 50-329 A |
| MILLER, D B | 8303140534 | 50-329 A |
| MILLER, D B | 8303170385 | 50-329 A |
| MILLER, D B | 8303170388 | 50-329 A |
| MILLER, D B | 8303170393 | 50-329 A |
| MILLER, D B | 8303170489 | 50-329 A |
| MILLER, D B | 8303170508 | 50-329 A |
| MILLER, D B | 8303220082* | 50-329 A |
| MILLER, D B | 8303240043 | 50-329 A |
| MILLER, D B | 8303280031 | 50-329 A |
| MILLER, D B | 8303280071 | 50-329 A |
| MILLER, D B | 8303280075 | 50-329 A |
| MILLER, D B | 8303280108 | 50-329 A |
| MILLER, D B | 8303280232 | 50-329 A |
| MILLER, D B | 8303280275 | 50-330 A |
| MILLER, D E | 8303040574* | 50-295 Q |
| MILLER, D E | 8303140265* | 50-254 Q |
| MILLER, D S | 8303220214 | 50-309 Q |
| MILLER, D S | 8303220214 | 50-309 Q |
| MILLER, D S | 8303220218 | 50-309 Q |
| MILLER, D S | 8303220218 | 50-309 Q |
| MILLER, D W | 8303140485* | 50-387 R |
| MILLER, E R | 8303180313* | 50-320 P |
| MILLER, H | 8303300274 | WASTE MGT |
| MILLER, H J | 8303280069 | WASTE MGT |
| MILLER, H J | 8303280070 | WASTE MGT |
| MILLER, H J | 8303280077 | WASTE MGT |
| MILLER, H J | 8303290551 | WASTE MGT |
| MILLER, H J | 8303290563 | WASTE MGT |
| MILLER, H J | 8303290792 | WASTE MGT |
| MILLER, H J | 8303300064 | WASTE MGT |
| MILLER, H J | 8303300098 | WASTE MGT |
| MILLER, H J | 8303300107 | WASTE MGT |
| MILLER, H J | 8303300250 | WASTE MGT |
| MILLER, H J | 8303300281 | WASTE MGT |
| MILLER, J | 8303220235 | 50-295 S |
| MILLER, J R | 8303030472 | 50-255 Q |
| MILLER, J R | 8303030508 | 70-2945 |
| MILLER, J R | 8303030530 | 50-373 Q |
| MILLER, J R | 8303030535 | 50-305 Q |
| MILLER, J R | 8303030683 | 50-186 Q |
| MILLER, J R | 8303100278 | 50-87 Q |
| MILLER, J R | 8303140296 | 50-295 Q |
| MILLER, J R | 8303140321 | 50-87 Q |
| MILLER, J R | 8303140349 | 50-2 Q |
| MILLER, J R | 8303280307 | 50-254 Q |
| MILLER, L | 8303290279* | 50-206 Q |
| MILLER, L | 8303290462* | 50-206 Q |
| MILLER, L K | 8303040390 | 50-272 R |
| MILLER, L K | 8303040634* | 50-272 R |
| MILLER, L K | 8303170499* | 50-272 R |
| MILLER, M A | 8303090520 | NUREG |
| MILLER, M A | 8303160075 | 50-424 A |
| MILLER, M E | 8303020067 | 50-445 Q |
| MILLER, M E | 8303040435 | 50-537 Q |
| MILLER, M E | 8303080172 | 50-445 Q |
| MILLER, M E | 8303110195 | 50-445 Q |
| MILLER, M E | 8303140298 | 50-537 Q |
| MILLER, M E | 8303220264 | 50-445 Q |
| MILLER, M E | 8303290487 | 50-537 Q |
| MILLER, M E | 8303300288 | 50-445 Q |
| MILLER, M E | 8303310279 | 50-537 Q |
| MILLER, M E | 8303310293 | 50-445 Q |
| MILLER, R G | 8303030469 | 50-400 Q |
| MILLER, R G | 8303240516 | 50-400 Q |
| MILLER, R L | 8303220413 | 50-16 W |
| MILLER, T D | 8303210411* | GA999 |
| MILLER, W | 8303220062* | 50-331 R |
| MILLER, W H | 8303210541* | 50-395 Q |
| MILLER, W O | 8303040276 | 50-302 P |
| MILLER, W O | 8303100507 | 50-295 P |
| MILLER, W O | 8303100510 | 50-409 P |
| MILLER, W O | 8303110082 | 50-285 P |
| MILLER, W O | 8303150668 | 50-313 P |
| MILLER, W O | 8303150673 | 50-315 P |
| MILLER, W O | 8303180051 | 50-344 F |
| MILLER, W O | 8303180054 | 50-409 P |
| MILLER, W O | 8303310013 | 50-266 P |
| MILLER, W O | 8303310014 | 50-267 P |
| MILLER, W O | 8303310095 | 50-312 P |
| MILLIGAN, M H | 8303080355 | 50-322 S |
| MILLS, L M | 8302280512 | 50-390 A |
| MILLS, L M | 8303010198 | 50-390 S |
| MILLS, L M | 8303010207 | 50-390 S |
| MILLS, L M | 8303010252 | 50-390 Q |
| MILLS, L M | 8303010255 | 50-390 Q |
| MILLS, L M | 8303010258 | 50-390 Q |
| MILLS, L M | 8303010262 | 50-390 Q |
| MILLS, L M | 8303010284 | 50-327 Q |
| MILLS, L M | 8303010293 | 50-259 Q |
| MILLS, L M | 8303010303 | 50-438 Q |
| MILLS, L M | 8303010369 | 50-518 A |
| MILLS, L M | 8303010399 | 50-327 Q |
| MILLS, L M | 8303010428 | 50-259 Q |
| MILLS, L M | 8303010448 | 50-259 Q |
| MILLS, L M | 8303010467 | 50-438 Q |
| MILLS, L M | 8303010563 | 50-438 Q |
| MILLS, L M | 8303010586 | 50-390 S |
| MILLS, L M | 8303020340 | 70-2917 |
| MILLS, L M | 8303020376 | 70-2910 |
| MILLS, L M | 8303040341 | 50-259 P |
| MILLS, L M | 8303040352 | 50-438 S |
| MILLS, L M | 8303040384 | 50-438 S |
| MILLS, L M | 8303040542 | 50-438 S |
| MILLS, L M | 8303040545 | 50-390 S |
| MILLS, L M | 8303040559 | 50-390 S |
| MILLS, L M | 8303040561 | 50-438 S |
| MILLS, L M | 8303040603 | 50-390 C |
| MILLS, L M | 8303040609 | 50-390 A |
| MILLS, L M | 8303040613 | 50-390 S |
| MILLS, L M | 8303040617 | 50-390 S |
| MILLS, L M | 8303040630 | 50-390 S |
| MILLS, L M | 8303040632 | 50-438 S |
| MILLS, L M | 8303080442 | 50-259 V |
| MILLS, L M | 8303090343 | 50-327 P |
| MILLS, L M | 8303100049* | 50-327 F |
| MILLS, L M | 8303100295 | 50-259 P |
| MILLS, L M | 8303140234 | 50-327 P |
| MILLS, L M | 8303140418 | 50-390 S |
| MILLS, L M | 8303140422 | 50-390 S |
| MILLS, L M | 8303140430 | 50-438 S |
| MILLS, L M | 8303150200 | 50-390 S |
| MILLS, L M | 8303160216 | 50-259 R |
| MILLS, L M | 8303160293 | 50-438 A |
| MILLS, L M | 8303160450 | 50-390 S |
| MILLS, L M | 8303160613 | 40-1341 |
| MILLS, L M | 8303180022 | 50-390 S |
| MILLS, L M | 8303180023 | 50-438 S |
| MILLS, L M | 8303180050 | 50-390 S |
| MILLS, L M | 8303180300 | 50-390 S |
| MILLS, L M | 8303180348 | 50-438 S |
| MILLS, L M | 8303180383 | 50-438 S |
| MILLS, L M | 8303180454 | 50-259 P |
| MILLS, L M | 8303180472 | 50-438 S |
| MILLS, L M | 8303180530 | 50-327 P |
| MILLS, L M | 8303210340 | 50-438 R |
| MILLS, L M | 8303210353* | 50-390 Q |
| MILLS, L M | 8303210396 | 50-390 S |
| MILLS, L M | 8303210422* | 50-327 Q |
| MILLS, L M | 8303210551 | 50-390 Q |
| MILLS, L M | 8303210596 | 50-390 S |
| MILLS, L M | 8303210605 | 50-438 S |
| MILLS, L M | 8303210626 | 50-438 S |
| MILLS, L M | 8303210630 | 50-438 S |
| MILLS, L M | 8303210634 | 50-438 S |
| MILLS, L M | 8303210679 | 50-390 S |
| MILLS, L M | 8303210765* | 50-259 Q |
| MILLS, L M | 8303220047 | 50-390 S |
| MILLS, L M | 8303220119 | 50-438 S |
| MILLS, L M | 8303220156 | 50-327 P |
| MILLS, L M | 8303220162 | 50-327 P |
| MILLS, L M | 8303220296 | 50-327 P |
| MILLS, L M | 8303220336 | 50-390 S |
| MILLS, L M | 8303220354 | 50-438 S |
| MILLS, L M | 8303240359 | 50-391 S |
| MILLS, L M | 8303240365 | 50-390 S |
| MILLS, L M | 8303240406 | 50-390 S |
| MILLS, L M | 8303240429 | 50-390 S |
| MILLS, L M | 8303240447 | 50-259 P |
| MILLS, L M | 8303240525 | 50-390 S |
| MILLS, L M | 8303240551 | 50-390 S |
| MILLS, L M | 8303240603 | 50-390 S |
| MILLS, L M | 8303250038 | 50-519 A |
| MILLS, L M | 8303250092 | 50-259 F |
| MILLS, L M | 8303280023 | 50-328 P |
| MILLS, L M | 8303280045 | 50-327 P |
| MILLS, L M | 8303290306 | 50-390 A |
| MILLS, L M | 8303300125 | 50-327 P |
| MILLS, L M | 8303310028* | 50-327 F |
| MILLS, L M | 8303310161 | 50-390 A |
| MILLS, L M | 8303310420 | 50-259 P |
| MILLS, M | 8303310366 | NUREG |
| MILLS, W A | 8303040415 | PR |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| MILLGAP, D. A. | 8303180568 | RES |
| MILOISNESS, R. C. | 8303300519 | NUREG |
| MINECK, D. L. | 8303010490 | 50-331 R |
| MINECK, D. L. | 8303030570 | 50-331 S |
| MINECK, D. L. | 8303030620 | 50-331 S |
| MINECK, D. L. | 8303030664 | 50-331 S |
| MINECK, D. L. | 8303140407 | 50-331 S |
| MINECK, D. L. | 8303140413 | 50-331 S |
| MINECK, D. L. | 8303140421 | 50-331 S |
| MINECK, D. L. | 8303140435 | 50-331 S |
| MINECK, D. L. | 8303150215 | 50-331 R |
| MINECK, D. L. | 8303170361 | 50-331 S |
| MINECK, D. L. | 8303220061 | 50-331 R |
| MINECK, D. L. | 8303290327 | 50-331 R |
| MINER, S. | 8303010004 | 50-312 P |
| MINER, S. | 8303160098 | 50-312 P |
| MINER, S. | 8303180116 | 50-312 P |
| MINER, S. | 8303310089 | COMMISSION |
| MINOGUE, R. B. | 8303300580 | PR |
| MINOGUE, R. B. | 8303300611* | PR |
| MINOGUE, R. B. | 8303310519 | MISC |
| MINOR, G. C. | 8303250157 | 50-322 T |
| MIRAGLIA, F. J. | 8303030284 | 50-470 E |
| MIRAGLIA, F. J. | 8303090631 | 50-443 E |
| MIRAGLIA, F. J. | 8303150036 | 50-369 P |
| MIRAGLIA, F. J. | 8303230483 | 50-470 E |
| MITCHELL, G. J. | 8303040125* | 50-309 S |
| MITCHELL, G. J. | 8303090177* | 50-309 U |
| MITCHELL, J. A. | 8303240024* | 50-443 G |
| MITTL, R. L. | 8303030458 | 50-354 A |
| MITTL, R. L. | 8303030467* | 50-354 F |
| MITTL, R. L. | 8303140274 | 50-354 A |
| MITTL, R. L. | 8303160487 | 50-354 A |
| MITTL, R. L. | 8303230255 | 50-354 H |
| MIZUNO, G. S. | 8303160534 | 50-445 G |
| MIZUNO, G. S. | 8303310251 | 50-445 T |
| MOBERG, L. | 8303160421* | 50-324 P |
| MOERKE, N. H. | 8303210492* | QA999 |
| MOHR, C. M. | 8303180672 | RES |
| MOHR, D. | 8303140617 | NUREG |
| MOK, G. C. | 8302040475* | 71-9001 |
| MOLCHANY, W. J. | 8303090234 | 50-387 P |
| MONAHAN, J. | 8303300645 | FOIA |
| MONTGOMERY, C. R. | 8303010286 | 50-146 J |
| MONTGOMERY, C. R. | 8303030110 | 50-146 I |
| MONTGOMERY, C. R. | 8303090276 | 50-146 S |
| MONTGOMERY, D. | 8303210693* | 50-280 G |
| MONTGOMERY, D. M. | 8303010295* | 50-348 G |
| MONTGOMERY, D. M. | 8303010416* | 50-261 G |
| MONTGOMERY, D. M. | 8303210429* | 50-395 G |
| MONTGOMERY, J. L. | 8303010247* | 50-313 G |
| MOODY, W. | 8303180487* | 50-361 S |
| MOONEY, G. | 8303170334 | 40-8714 |
| MOONEY, G. | 8303180103 | 40-8663 |
| MOONEY, J. | 8303140390* | 50-247 S |
| MOONEY, J. D. | 8303280120* | 50-329 E |
| MOORE, D. E. | 8303150401* | 50-327 G |
| MOORE, D. E. | 8303290430* | 50-250 G |
| MOORE, J. E. | 8303040623 | 50-247 G |
| MOORE, J. E. | 8303180029 | 50-247 G |
| MOORE, J. E. | 8303230230 | 50-247 T |
| MOORE, R. N. | 8303040039 | XPORTLIC |
| MOORE, R. N. | 8303230351 | XPORTLIC |
| MOORE, R. N. | 8303230355 | XPORTLIC |
| MOORE, R. N. | 8303230359 | XPORTLIC |
| MOORE, R. N. | 8303290133 | XPORTLIC |
| MOORE, R. N. | 8303290145 | XPORTLIC |
| MOORHEAD, C. J. | 8303160721* | COMMISSION |
| MORAN, D. H. | 8303090393 | TOPREP |
| MORAN, D. M. | 8303090294 | 50-454 T |
| MORELAND, R. | 8303250143* | 50-261 P |
| MORELAND, R. E. | 8303310175* | FOIA |
| MORELAND, R. E. | 8303310208* | FOIA |
| MORELAND, R. E. | 8303310220* | FOIA |
| MORELAND, R. E. | 8303310249* | FOIA |
| MORELAND, R. E. | 8303310260* | FOIA |
| MORELLA, C. A. | 8303040147* | 50-170 U |
| MORGAN, C. | 8303020026 | 50-247 G |
| MORGAN, C. | 8303020026 | 50-247 G |
| MORGAN, C. | 8303020046 | 50-247 G |
| MORGAN, C. | 8303020046 | 50-247 G |
| MORGAN, C. | 8303020052* | 50-247 G |
| MORGAN, C. | 8303020052* | 50-247 G |
| MORGAN, C. | 8303070110 | 50-247 G |
| MORGAN, C. | 8303070110 | 50-247 G |
| MORGAN, C. | 8303140335 | 50-247 G |
| MORGAN, C. | 8303140335 | 50-247 G |
| MORGAN, C. | 8303140343 | 50-247 G |
| MORGAN, C. | 8303140343 | 50-247 G |
| MORGAN, C. | 8303180235 | 50-247 G |
| MORGAN, C. | 8303180235 | 50-247 G |
| MORGAN, C. | 8303180245 | 50-247 G |
| MORGAN, C. | 8303180245 | 50-247 G |
| MORGAN, C. | 8303220231 | 50-247 G |
| MORGAN, C. | 8303220231 | 50-247 G |
| MORGAN, H. E. | 8303180428 | 50-362 S |
| MORGAN, H. E. | 8303210652* | 50-361 P |
| MORGAN, H. E. | 8303210657* | 50-361 P |
| MORGAN, H. E. | 8303290202 | 50-362 S |
| MORGAN, H. E. | 8303290321 | 50-362 S |
| MORGAN, W. C. | 8303100421 | NUREG |
| MORLEY, J. A. | 8303010083 | WASTE MGT |
| MORLEY, J. A. | 8303180061 | WASTE MGT |
| MORRILL, P. J. | 8303040454* | 50-275 G |
| MORRIS, P. A. | 8303090309 | 50-352 G |
| MORRISON, G. M. | 8303010502* | 50-309 S |
| MORRISSEY, K. J. | 8303240415* | 50-29 P |
| MORTON, K. V. | 8303030342* | CONTRACT |
| MORTON, K. V. | 8303030370* | CONTRACT |
| MORTON, K. V. | 8303030383* | CONTRACT |
| MORTON, K. V. | 8303030680* | CONTRACT |
| MORTON, K. V. | 8303030782* | CONTRACT |
| MORTON, K. V. | 8303040292* | CONTRACT |
| MORTON, K. V. | 8303150712* | CONTRACT |
| MORTON, K. V. | 8303160060* | CONTRACT |
| MORTON, K. V. | 8303160667* | CONTRACT |
| MORTON, K. V. | 8303290028* | CONTRACT |
| MORTON, K. V. | 8303290039* | CONTRACT |
| MORTON, K. V. | 8303290413* | CONTRACT |
| MORTON, K. V. | 8303290532* | CONTRACT |
| MORTON, K. V. | 8303290758* | CONTRACT |
| MORTON, K. V. | 8303290769* | CONTRACT |
| MORTON, K. V. | 8303290788* | CONTRACT |
| MORTON, K. V. | 8303290798* | CONTRACT |
| MORTON, K. V. | 8303300067* | CONTRACT |
| MORTON, K. V. | 8303300079* | CONTRACT |
| MORTON, K. V. | 8303300576* | CONTRACT |
| MORTON, K. V. | 8303300585* | CONTRACT |
| MORTON, K. V. | 8303300604* | CONTRACT |
| MORTON, K. V. | 8303300683* | CONTRACT |
| MORTON, K. V. | 8303300698* | CONTRACT |
| MORTON, K. V. | 8303310103* | CONTRACT |
| MORTON, K. V. | 8303310112* | CONTRACT |
| MORTON, K. V. | 8303310136* | CONTRACT |
| MORTON, K. V. | 8303310155* | CONTRACT |
| MORTON, K. V. | 8303310200* | CONTRACT |
| MORTON, K. V. | 8303310367* | CONTRACT |
| MORTON, K. V. | 8303310374* | CONTRACT |
| MORTON, K. V. | 8303310594* | CONTRACT |
| MORTON, K. V. | 8303310628* | CONTRACT |
| MORTON, K. V. | 8303310646* | CONTRACT |
| MOUNT, D. K. | 8303240454 | State Prog |
| MOWRY, W. R. | 8303010066 | 70-734 |
| MOWRY, W. R. | 8303100571 | 71-6346 |
| MOWRY, W. R. | 8303140552 | XPORTLIC |
| MOWRY, W. R. | 8303140556* | XPORTLIC |
| MOWRY, W. R. | 8303230145 | XPORTLIC |
| MOWRY, W. R. | 8303290110 | XPORTLIC |
| MROCZKA, E. J. | 8303080070 | 50-245 S |
| MROCZKA, E. J. | 8303080070 | 50-245 S |
| MROCZKA, E. J. | 8303080120 | 50-245 R |
| MROCZKA, E. J. | 8303080120 | 50-245 R |
| MROCZKA, E. J. | 8303080201 | 50-336 R |
| MROCZKA, E. J. | 8303080201 | 50-336 R |
| MROCZKA, E. J. | 8303080345 | 50-245 S |
| MROCZKA, E. J. | 8303080345 | 50-245 S |
| MROCZKA, E. J. | 8303080413 | 50-336 S |
| MROCZKA, E. J. | 8303080413 | 50-336 S |
| MROCZKA, E. J. | 8303140253 | 50-245 S |
| MROCZKA, E. J. | 8303140253 | 50-245 S |
| MROCZKA, E. J. | 8303140393 | 50-245 S |
| MROCZKA, E. J. | 8303140393 | 50-245 S |
| MROCZKA, E. J. | 8303150420 | 50-245 R |
| MROCZKA, E. J. | 8303150420 | 50-245 R |
| MROCZKA, E. J. | 8303150430 | 50-336 R |
| MROCZKA, E. J. | 8303150430 | 50-336 R |
| MROCZKA, E. J. | 8303180330 | 50-336 S |
| MROCZKA, E. J. | 8303180330 | 50-336 S |
| MROCZKA, E. J. | 8303180340 | 50-245 S |
| MROCZKA, E. J. | 8303180340 | 50-245 S |
| MROCZKA, E. J. | 8303180374 | 50-336 S |
| MROCZKA, E. J. | 8303180374 | 50-336 S |
| MROCZKA, E. J. | 8303240457 | 50-336 S |
| MROCZKA, E. J. | 8303240457 | 50-336 S |
| MROCZKA, E. J. | 8303240572 | 50-245 S |
| MROCZKA, E. J. | 8303240572 | 50-245 S |
| MROCZKA, E. J. | 8303290251* | 50-245 F |
| MUCHA, E. | 8112240161* | 50-277 P |
| MUELLER, E. | 8303020003 | TOPREP |
| MUENCH, R. A. | 8303040354 | TOPREP |
| MULHOLLAND, J. D. | 8303110112* | CONTRACT |
| MULLER, D. R. | 8303090051 | 50-289 P |
| MULLIKIN, R. P. | 8303010427* | 50-382 G |
| MURDOCK, R. J. | 8303160232* | 50-219 S |
| MURLEY, T. E. | 8303160595 | REVIEW GRP |
| MURPHY, C. E. | 8303080429* | 50-315 R |
| MURPHY, C. E. | 8303250056* | 50-315 F |
| MURPHY, D. | 8303040497* | 50-259 S |
| MURPHY, J. D. | 8303040051 | 71-9074 |
| MURPHY, L. | 8303300481 | CONTRACT |
| MURPHY, L. G. | 8303300088 | 50-537 A |
| MURPHY, M. E. | 8303210693* | 50-285 G |
| MURPHY, W. P. | 8303040552 | 50-271 V |
| MURPHY, W. P. | 8303160363 | 50-271 R |
| MURRAY, B. | 8303180223* | 50-267 G |
| MURRAY, B. | 8303180225* | 50-285 G |
| MURRAY, B. | 8303180230* | 50-298 G |
| MURRAY, B. | 8303180244* | 50-285 G |
| MURRAY, B. | 8303180357* | 50-482 G |
| MURRAY, B. | 8303180421* | 50-382 G |
| MURRAY, B. | 8303180433* | 50-313 G |
| MURRAY, J. P. | 8209280360* | FOIA |
| MURRAY, T. D. | 8303080165 | 50-346 R |
| MURRAY, T. D. | 8303080478 | 50-346 S |
| MURRAY, T. D. | 8303080518 | 50-346 S |
| MURRAY, T. D. | 8303140409 | 50-346 S |
| MURRAY, T. D. | 8303140528 | 50-346 S |
| MURRAY, T. D. | 8303150498 | 50-346 R |
| MURRAY, T. D. | 8303170362 | 50-346 R |
| MURRAY, T. D. | 8303170442 | 50-346 S |
| MURRAY, T. D. | 8303170522 | 50-346 S |
| MURRAY, T. D. | 8303210358 | 50-346 S |
| MURRAY, T. D. | 8303220385* | 50-346 F |
| MURRAY, T. D. | 8303240474 | 50-346 S |
| MUSELER, W. J. | 8303010458 | 50-322 A |
| MUSELER, W. J. | 8303240017* | 50-322 G |
| MUSOLF, D. | 8303010202 | 50-263 G |
| MUSOLF, D. | 8303040399 | 50-263 G |
| MUSOLF, D. | 8303080049 | 50-282 R |
| MUSOLF, D. | 8303080464 | 50-263 R |
| MUSOLF, D. | 8303100160 | 50-263 P |
| MUSOLF, D. | 8303110299 | 50-282 G |
| MUSOLF, D. | 8303140250 | 50-282 P |
| MUSOLF, D. | 8303150277 | 50-282 R |
| MUSOLF, D. | 8303150295 | 50-263 R |
| MUSOLF, D. | 8303150460 | 50-282 R |
| MUSOLF, D. | 8303150604 | 50-263 R |
| MUSOLF, D. | 8303170215 | 50-282 F |
| MUSOLF, D. | 8303170381 | 50-282 P |
| MUSOLF, D. | 8303170500 | 50-263 P |
| MUSOLF, D. | 8303170512* | 50-263 P |
| MUSOLF, D. | 8303170521* | 50-263 P |
| MUSOLF, D. | 8303170527* | 50-263 P |
| MUSOLF, D. | 8303170536* | 50-263 P |
| MUSOLF, D. | 8303180014 | 50-263 P |
| MUSOLF, D. | 8303180112 | 71-9151 |
| MUSOLF, D. | 8303180531 | 50-263 P |
| MUSOLF, D. | 8303210058 | 50-282 P |
| MUSOLF, D. | 8303220213 | 50-282 S |
| MUSOLF, D. | 8303240433 | 50-263 S |
| MUSOLF, D. | 8303280142 | 50-306 S |
| MUSOLF, D. | 8303280216 | 50-263 F |
| MUSOLF, D. | 8303310281 | 50-282 P |
| MUSOLF, D. M. | 8303040478 | 50-263 V |
| MYERS, I. L. | 8303310374* | CONTRACT |
| MYERS, R. V. | 8303010308 | 50-322 A |
| MYRABO, A. L. | 8303080469* | 50-263 R |
| MYRABO, A. L. | 8303150607* | 50-263 R |
| MYSINGER, E. D. | 8303290317* | 50-390 A |
| NADEL, M. | 8303110226 | 50-315 J |
| NADEL, M. | 8303110269 | 50-358 J |
| NADEL, M. | 8303140308 | 50-483 J |
| NAESS, H. K. | 8303160418* | 50-324 P |
| NAIDU, K. | 8303140423* | 50-373 G |
| NAIDU, K. R. | 8303220253* | 50-440 G |

# PERSONAL AUTHOR INDEX


| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| NAJAFI, B. | 8303220106 | 50-537 A |
| NAKAI, T. | 8303180155 | XPORTLIC |
| NAKAI, T. | 8303180161* | XPORTLIC |
| NALIBOFF, L. G. | 8303190413 | 50-142 G |
| NARAYANI, I. V. | 8303250143* | 50-261 P |
| NARBUT, P. | 8303110086* | 50-460 G |
| NARBUT, P. P. | 8303180522* | 50-528 G |
| NARDI, A. J. | 8303020246 | 71-4909 |
| NARDI, A. J. | 8303030297 | 71-4986 |
| NARDOCI, P. B. | 8303010571* | 50-369 S |
| NARDOCI, P. B. | 8303140382* | 50-369 S |
| NARDOCI, P. B. | 8303140392* | 50-369 S |
| NARDOCI, P. B. | 8303150457* | 50-369 S |
| NARDOCI, P. B. | 8303240604* | 50-369 S |
| NARROW, L. | 8303030183* | 50-423 G |
| NARROW, L. | 8303100344* | 50-272 G |
| NARROW, L. | 8303210661* | 50-362 G |
| NASH, B. | 8303100557* | 50-289 F |
| NATHAN, S. J. | 8303040605* | 50-324 P |
| NAUMANN, H. R. | 8303280170 | 50-3 S |
| NEBBITT, B. | 8303280097 | NUREG |
| NEBBITT, B. | 8303280114 | NUREG |
| NEHEMIAS, J. | 8303040062* | 50-261 P |
| NEIGHBORS, J. D. | 8303150071 | 50-280 P |
| NEIGHBORS, J. D. | 8303310089 | COMMISSION |
| NELSON, G. B. | 8303010632* | 70-734 |
| NELSON, G. B. | 8303240564* | 70-1257 |
| NELSON, G. B. | 8303280255* | 70-734 |
| NELSON, R. H. | 8303140506* | 50-309 S |
| NEMETHY, E. | 8303030191* | 50-387 H |
| NEDOY, P. | 8303090627 | RES |
| NERSES, V. | 8303100343 | 50-389 A |
| NERSES, V. | 8303300284 | 50-389 A |
| NEWMAN, J. R. | 8303170283 | 50-498 G |
| NEWMAN, J. R. | 8303170283 | 50-498 G |
| NEYLAN, A. J. | 8303290383 | 50-358 A |
| NG, L. | 8303010362* | 50-397 E |
| NICHOLAS, H. | 8303240591* | 50-289 G |
| NICHOLAS, H. H. | 8303030364* | 50-322 G |
| NICHOLAS, J. B. | 8303180225* | 50-285 G |
| NICHOLAS, J. B. | 8303180230* | 50-298 G |
| NIELSON, J. R. | 8303180579 | RES |
| NIELSON, J. R. | 8303180674 | RES |
| NIMITZ, R. L. | 8303100305* | 50-293 G |
| NIMMO, E. | 8303240139* | FOIA |
| NISSON, R. S. | 8303040029 | XPORTLIC |
| NITSCHKE, R. L. | 8303030763* | 50-275 P |
| NIX, H. | 8303250048* | 50-321 F |
| NIX, H. | 8303310180* | 50-321 F |
| NIX, H. C. | 8302150605 | 50-366 S |
| NIX, H. C. | 8303030213 | 50-321 R |
| NIX, H. C. | 8303030220* | 50-321 R |
| NIX, H. C. | 8303080043 | 50-321 S |
| NIX, H. C. | 8303080206 | 50-321 S |
| NIX, H. C. | 8303080404 | 50-321 S |
| NIX, H. C. | 8303090537* | 50-321 F |
| NIX, H. C. | 8303140478 | 50-321 S |
| NIX, H. C. | 8303140570 | 50-321 S |
| NIX, H. C. | 8303140584 | 50-321 S |
| NIX, H. C. | 8303150204 | 50-321 S |
| NIX, H. C. | 8303150452 | 50-321 S |
| NIX, H. C. | 8303150478 | 50-321 R |
| NIX, H. C. | 8303150482 | 50-366 S |
| NIX, H. C. | 8303150545 | 50-321 S |
| NIX, H. C. | 8303160443 | 50-321 S |
| NIX, H. C. | 8303160583 | 50-321 R |
| NIX, H. C. | 8303180363 | 50-366 S |
| NIX, H. C. | 8303210316 | 50-366 S |
| NIX, H. C. | 8303210350 | 50-321 S |
| NIX, H. C. | 8303210388 | 50-321 S |
| NIX, H. C. | 8303210406 | 50-366 S |
| NIX, H. C. | 8303210412 | 50-366 S |
| NIX, H. C. | 8303210463 | 50-321 S |
| NIX, H. C. | 8303210476 | 50-321 S |
| NIX, H. C. | 8303210517 | 50-366 S |
| NIX, H. C. | 8303210558 | 50-321 S |
| NIX, H. C. | 8303210694 | 50-366 S |
| NIX, H. C. | 8303220046 | 50-321 S |
| NIX, H. C. | 8303240114* | 50-321 F |
| NIX, H. C. | 8303240448 | 50-321 S |
| NIX, H. C. | 8303250043* | 50-321 F |
| NIX, H. C. | 8303310118* | 50-321 F |
| NIX, H. C. | 8303310174* | 50-321 F |
| NIXON, W. A. | 8303040369 | 40-86 |
| NIXON, W. A. | 8303100418* | 70-364 |
| NIXON, W. A. | 8303220418* | 40-2061 |
| NIXON, W. A. | 8303220427* | 40-2061 |
| NIXON, W. A. | 8303220433* | 40-2061 |
| NIXON, W. A. | 8303310379* | 40-2061 |
| NOONAN, V. S. | 8303310185* | 50-387 P |
| NORDERHAUG, L. | 8303010632* | 70-734 |
| NORDERHAUG, L. | 8303240564* | 70-1257 |
| NORDERHAUG, L. R. | 8303010612 | 70-734 |
| NORDERHAUG, L. R. | 8303140488 | 50-312 G |
| NORDERHAUG, L. R. | 8303150231 | 70-1216 |
| NORDERHAUG, L. R. | 8303150547 | 70-53 |
| NORDERHAUG, L. R. | 8303240555 | 70-1257 |
| NORDERHAUG, L. R. | 8303280248 | 70-734 |
| NORDERHAUG, L. R. | 8303280255* | 70-734 |
| NORDERHAUG, L. R. | 8303290384 | 70-553 |
| NORDLUND, W. J. | 8303290228* | CONTRACT |
| NORELIUS, C. E. | 8303010653 | 50-461 A |
| NORELIUS, C. E. | 8303030626 | 50-456 G |
| NORELIUS, C. E. | 8303030632* | 50-456 G |
| NORELIUS, C. E. | 8303030685 | 50-456 G |
| NORELIUS, C. E. | 8303080223 | 50-346 G |
| NORELIUS, C. E. | 8303140182 | 50-461 G |
| NORELIUS, C. E. | 8303140456 | 50-456 G |
| NORELIUS, C. E. | 8303140524 | 50-316 G |
| NORELIUS, C. E. | 8303150227 | 50-409 G |
| NORELIUS, C. E. | 8303170329 | 50-461 G |
| NORELIUS, C. E. | 8303170529 | 50-373 G |
| NORELIUS, C. E. | 8303170534* | 50-373 G |
| NORELIUS, C. E. | 8303210282* | 50-329 A |
| NORELIUS, C. E. | 8303220087 | 50-346 E |
| NORELIUS, C. E. | 8303220267 | 50-255 G |
| NORELIUS, C. E. | 8303220279 | 50-315 G |
| NORELIUS, C. E. | 8303240178 | 50-315 G |
| NORELIUS, C. E. | 8303240209 | 50-483 G |
| NORELIUS, C. E. | 8303240586 | 50-346 G |
| NORELIUS, C. E. | 8303280112 | 50-295 P |
| NORELIUS, C. E. | 8303280150 | 50-237 P |
| NORELIUS, C. E. | 8303280174 | 50-263 P |
| NORELIUS, C. E. | 8303280215 | 50-254 G |
| NORELIUS, C. E. | 8303280218 | 50-263 P |
| NORELIUS, C. E. | 8303280272 | 50-254 P |
| NORRHOLM, L. | 8303240591* | 50-289 G |
| NORRHOLM, L. J. | 8303010667* | 50-272 G |
| NORRHOLM, L. J. | 8303030364* | 50-322 G |
| NORRHOLM, L. J. | 8303030662* | 50-272 G |
| NORRHOLM, L. J. | 8303100150* | 50-336 G |
| NORRHOLM, L. J. | 8303100210* | 50-272 G |
| NORRHOLM, L. J. | 8303240363* | 50-387 G |
| NORRHOLM, L. J. | 8303240528* | 50-247 G |
| NORRHOLM, L. J. | 8303280267* | 50-272 G |
| NORRIS, H. B. | 8303150570* | 50-261 R |
| NORRIS, J. | 8303110002 | 50-295 P |
| NORRIS, J. T. | 8303310628* | CONTRACT |
| NORRIS, S. M. | 8303310089 | COMMISSION |
| NORRY, P. G. | 8303020106 | ORG |
| NORRY, P. G. | 8303090394 | ORG |
| NORTH, H. S. | 8303180407* | 50-312 G |
| NORTH, H. S. | 8303290257* | 50-528 G |
| NORTHRUP, R. | 8303020116* | 50-247 T |
| NORTON, B. | 8303290296 | 50-275 G |
| NORTON, B. | 8303290296 | 50-275 G |
| NORWOOD, D. W. | 8303150309* | 50-296 S |
| NOVACHEK, F. J. | 8303280249* | 50-267 S |
| NOVAK, T. M. | 8212020228* | 50-373 P |
| NOVAK, T. M. | 8303010707 | 50-382 A |
| NOVAK, T. M. | 8303010723 | 50-400 A |
| NOVAK, T. M. | 8303010724 | 50-413 E |
| NOVAK, T. M. | 8303020149 | 50-413 E |
| NOVAK, T. M. | 8303030669 | 50-390 E |
| NOVAK, T. M. | 8303030759 | 50-341 G |
| NOVAK, T. M. | 8303040406 | 50-328 P |
| NOVAK, T. M. | 8303080190 | 50-369 P |
| NOVAK, T. M. | 8303110522 | 50-445 G |
| NOVAK, T. M. | 8303140582 | 50-382 F |
| NOVAK, T. M. | 8303140602 | 50-397 F |
| NOVAK, T. M. | 8303140615 | 50-445 A |
| NOVAK, T. M. | 8303160675 | 50-352 E |
| NOVAK, T. M. | 8303180574 | 50-369 E |
| NOVAK, T. M. | 8303180645 | 50-369 P |
| NOVAK, T. M. | 8303230518 | 50-424 A |
| NOVAK, T. M. | 8303230527 | 50-369 P |
| NOVAK, T. M. | 8303280103 | 50-352 E |
| NOVAK, T. M. | 8303290721 | 50-443 E |
| NOVAK, T. M. | 8303290745 | 50-395 G |
| NOVAK, T. M. | 8303300661 | 50-329 A |
| NOVAK, T. M. | 8303300724 | 50-322 A |
| NOVAK, T. M. | 8303310662 | 50-498 A |
| NOVAK, T. M. | 8303310681 | 50-322 F |
| NUGENT, E. L. | 8303090626 | 40-2259 |
| NUSSBAUMER, D. A. | 8303090013* | FOIA |
| NUSSBAUMER, D. A. | 8303090331 | WASTE MGT |
| NUSSBAUMER, D. A. | 8303280313 | I&E |
| NZU, L. C. | 8303100087* | 50-265 P |
| O'CONNER, P. W. | 8303100325 | 50-546 R |
| O'CONNOR, J. J. | 8303070151* | 50-10 I |
| O'CONNOR, J. M. | 8303100368 | 71-9151 |
| O'CONNOR, P. W. | 8303240134 | 50-546 A |
| O'CONNOR, P. W. | 8303310089 | COMMISSION |
| O'NEILL, B. | 8303140201* | FOIA |
| O'NEILL, B. | 8303280173* | 50-320 G |
| O'NEILL, J. | 8303140362 | 50-155 G |
| O'NEILL, J. | 8303230217* | 50-155 G |
| O'NEILL, J. | 8303230246 | 50-155 G |
| O'NEILL, J. | 8303230250* | 50-155 G |
| O'NEILL, J. H. | 8303110193 | 50-400 G |
| O'NEILL, J. H. | 8303110193 | 50-400 G |
| O'NEILL, J. H. | 8303150597 | 50-400 G |
| O'NEILL, J. H. | 8303150597 | 50-400 G |
| O'REILLY, J. P. | 8303010485 | 50-416 G |
| O'REILLY, J. P. | 8303010558* | 50-416 G |
| O'REILLY, J. P. | 8303010640 | 50-335 G |
| O'REILLY, J. P. | 8303010660 | 50-250 G |
| O'REILLY, J. P. | 8303040484 | 50-364 G |
| O'REILLY, J. P. | 8303040488* | 50-364 G |
| O'REILLY, J. P. | 8303210401 | 50-364 G |
| O'REILLY, J. P. | 8303210502 | 50-348 G |
| O'REILLY, J. P. | 8303210599 | 50-302 G |
| O'REILLY, J. P. | 8303210620 | 50-416 G |
| O'TOOLE, J. D. | 8303010385 | 50-247 P |
| O'TOOLE, J. D. | 8303010395* | 50-247 P |
| O'TOOLE, J. D. | 8303080260 | 50-247 V |
| O'TOOLE, J. D. | 8303080312 | 50-247 P |
| O'TOOLE, J. D. | 8303080327 | 50-247 G |
| O'TOOLE, J. D. | 8303100199 | 50-3 R |
| O'TOOLE, J. D. | 8303110252 | 50-3 F |
| O'TOOLE, J. D. | 8303140215 | 50-247 P |
| O'TOOLE, J. D. | 8303140387 | 50-247 S |
| O'TOOLE, J. D. | 8303150551 | 50-3 R |
| O'TOOLE, J. D. | 8303150602 | 50-247 G |
| O'TOOLE, J. D. | 8303160156 | 50-247 S |
| O'TOOLE, J. D. | 8303220291 | 50-247 R |
| O'TOOLE, J. D. | 8303230047 | 50-3 F |
| O'TOOLE, J. D. | 8303250077* | 50-247 G |
| O'TOOLE, J. D. | 8303280210* | 50-247 G |
| O'TOOLE, J. D. | 8303290499 | 50-247 P |
| O'TOOLE, R. C. | 8303240418 | 50-247 G |
| OBERG, C. T. | 8303080487 | I&E |
| OBERG, C. T. | 8303210378 | I&E |
| OBERG, C. T. | 8303220029 | I&E |
| OBERMILLER, K. E. | 8302040475* | 71-9001 |
| ODEGAARDEN, R. H. | 8303010081 | 71-6698 |
| ODEGAARDEN, R. H. | 8303290537 | 71-9160 |
| ODEGAARDEN, R. H. | 8303300077 | 71-9015 |
| ODEGAARDEN, R. H. | 8303310232* | FOIA |
| ODUM, H. T. | 8303090520 | NUREG |
| OGHOJAFOV, W. | 8303230108 | FOIA |
| OGLE, K. M. | 8303220002 | 40-3714 |
| OKADA, S. | 8303180591 | XPORTLIC |
| OKADA, S. | 8303230014* | XPORTLIC |
| OLLER, R. E. | 8303070027* | GA999 |
| OLLER, R. E. | 8303070126* | GA999 |
| OLLER, R. E. | 8303180381* | GA999 |
| OLLIKKALA, H. | 8303180555 | RES |
| OLLINGER, W. H. | 8303100130* | 50-321 F |
| OLSEN, A. F. | 8303110037 | 70-824 |
| OLSHAM, L. N. | 8303240163 | 50-445 A |
| OLSON, O. L. | 8303290550 | WASTE MGT |
| OLSON, O. L. | 8303290569 | WASTE MGT |
| OLSON, O. L. | 8303300091 | WASTE MGT |
| OLSON, O. L. | 8303300124 | WASTE MGT |
| OLSON, R. A. | 8303220475 | 40-17 |
| OLSON, R. A. | 8303220479* | 40-17 |
| OLSON, R. C. | 8303100256 | 50-317 P |
| OPEKA, J. F. | 8303040360 | 50-213 G |
| OPEKA, J. F. | 8303040368 | 50-213 G |
| OPINANTE, A. | 8303110196* | 50-322 G |
| OPREA, G. W. | 8303150560 | 50-498 S |
| OPREA, G. W. | 8303180242 | 50-498 S |
| ORDERS, W. | 8303210373* | 50-369 G |
| ORION, O. | 8303140079* | 50-302 H |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| ORLEANS, D. E. | 8303240136* | FOIA |
| ORLOSKY, P. M. | 8303090168 | 50-57 F |
| OSBORNE, M. F. | 8303290698 | NUREG |
| OSTER, J. | 8303080135 | 50-454 J |
| OSTER, J. | 8303080197 | 50-10 J |
| OSTER, J. | 8303160578 | 50-10 J |
| OTADUY, P. J. | 8303140630 | NUREG |
| OTTINGER, R. L. | 8303100563* | COMMISSION |
| OVERLID, T. W. | 8303240436* | 50-263 S |
| OWCIARSKI, P. C. | 8303300178 | RES |
| OWCIARSKI, P. C. | 8303300667 | RES |
| OZTUNALI, O. | 8303290192* | CONTRACT |
| OZTUNALI, O. I. | 8303150031 | NUREG |
| PACE, P. | 8303080408* | 50-250 R |
| PACE, P. | 8303150346* | 50-250 R |
| PACE, P. | 8303150358* | 50-250 R |
| PADDLEFORD, D. F. | 8303250149* | 50-247 T |
| PADDLEFORD, D. F. | 8303250149* | 50-247 T |
| PAGE, M. | 8303090428 | CONTRACT |
| PAGE, M. | 8303150355 | CONTRACT |
| PAGE, M. | 8303160066 | CONTRACT |
| PAGE, M. | 8303180057 | CONTRACT |
| PAGE, M. | 8303230129 | CONTRACT |
| PAGE, R. | 8303290774* | 70-1100 |
| PAGE, R. G. | 8303040321 | 70-2932 |
| PAGE, R. G. | 8303090104 | 70-820 |
| PAGE, R. G. | 8303090222 | 70-820 |
| PAGE, R. G. | 8303100523 | 70-36 |
| PAGE, R. G. | 8303100527 | 70-2932 |
| PAGE, R. G. | 8303110067 | 70-2917 |
| PAGE, R. G. | 8303110162 | 70-2928 |
| PAGE, R. G. | 8303140031 | 70-1062 |
| PAGE, R. G. | 8303160635 | 40-86 |
| PAGE, R. G. | 8303180133 | 70-2946 |
| PAGE, R. G. | 8303180523 | 70-2910 |
| PAGE, R. G. | 8303220399 | 40-2061 |
| PAGE, R. G. | 8303250132 | 40-86 |
| PAGE, R. G. | 8303290766 | 70-1100 |
| PAGE, R. G. | 8303310034 | 70-371 |
| PAGE, R. G. | 8303310375 | 40-2061 |
| PAGE, R. G. | 8303310380 | 70-135 |
| PAGLIARO, J. A. | 8303240259* | 50-266 G |
| PAJOWSKI, J. | 8303080154 | 50-454 A |
| PAJOWSKI, J. E. | 8303310146* | 50-10 F |
| PALANTINO, S. A. | 8303170019* | CONTRACT |
| PALLADINO, N. | 8303170005 | COMMISSION |
| PALLADINO, N. J. | 8303020299 | COMMISSION |
| PALLADINO, N. J. | 8303020377 | 50-247 U |
| PALLADINO, N. J. | 8303030347 | 50-275 U |
| PALLADINO, N. J. | 8303030391* | 50-275 P |
| PALLADINO, N. J. | 8303040160 | 50-320 U |
| PALLADINO, N. J. | 8303040191 | COMMISSION |
| PALLADINO, N. J. | 8303040194 | COMMISSION |
| PALLADINO, N. J. | 8303100515 | State Prog |
| PALLADINO, N. J. | 8303100516 | COMMISSION |
| PALLADINO, N. J. | 8303100518 | State Prog |
| PALLADINO, N. J. | 8303100520 | COMMISSION |
| PALLADINO, N. J. | 8303100522 | State Prog |
| PALLADINO, N. J. | 8303100525 | State Prog |
| PALLADINO, N. J. | 8303100552 | COMMISSION |
| PALLADINO, N. J. | 8303110024 | COMMISSION |
| PALLADINO, N. J. | 8303110051 | State Prog |
| PALLADINO, N. J. | 8303110052 | State Prog |
| PALLADINO, N. J. | 8303110056 | State Prog |
| PALLADINO, N. J. | 8303110057 | State Prog |
| PALLADINO, N. J. | 8303110059 | State Prog |
| PALLADINO, N. J. | 8303110062 | State Prog |
| PALLADINO, N. J. | 8303110136 | 50-358 U |
| PALLADINO, N. J. | 8303110141 | State Prog |
| PALLADINO, N. J. | 8303110144 | State Prog |
| PALLADINO, N. J. | 8303110146 | State Prog |
| PALLADINO, N. J. | 8303110150 | State Prog |
| PALLADINO, N. J. | 8303110152 | State Prog |
| PALLADINO, N. J. | 8303110619 | State Prog |
| PALLADINO, N. J. | 8303110622 | State Prog |
| PALLADINO, N. J. | 8303140629 | COMMISSION |
| PALLADINO, N. J. | 8303160617 | COMMISSION |
| PALLADINO, N. J. | 8303160717 | COMMISSION |
| PALLADINO, N. J. | 8303170015 | 50-206 U |
| PALLADINO, N. J. | 8303230178* | FOIA |
| PALLADINO, N. J. | 8303290083 | 50-247 U |
| PALLADINO, N. J. | 8303290224 | COMMISSION |
| PALLADINO, N. J. | 8303290232 | 50-206 U |
| PALLADINO, N. J. | 9303300616* | PR |
| PALMER, D. A. | 8303170624 | NUREG |
| PALMER, R. A. | 8303080519* | 50-316 S |
| PALMER, R. A. | 8303210424* | 50-316 S |
| PALMER, R. A. | 8303240402* | 50-316 S |
| PANDEY, G. | 8301170075* | 50-346 P |
| PANGBURN, G. C. | 8303280068 | WASTE MGT |
| PANNO, S. V. | 8303300427 | RES |
| PAOLINO, R. J. | 8303240301* | 50-352 G |
| PAOLINO, R. J. | 8303280303* | 50-354 G |
| PAPAZOGLOU, I. A. | 8303140664 | 50-352 A |
| PAPERIELLO, C. | 8303220271 | 40-2061 |
| PAPERIELLO, C. J. | 8302220396 | 50-186 P |
| PAPERIELLO, C. J. | 8303010038 | 40-2061 |
| PAPERIELLO, C. J. | 8303030456 | 50-263 G |
| PAPERIELLO, C. J. | 8303030567 | 70-1308 |
| PAPERIELLO, C. J. | 8303030591 | 50-266 G |
| PAPERIELLO, C. J. | 8303040635 | 50-346 F |
| PAPERIELLO, C. J. | 8303090102 | 50-254 G |
| PAPERIELLO, C. J. | 8303140259 | 50-254 G |
| PAPERIELLO, C. J. | 8303140270 | 50-295 G |
| PAPERIELLO, C. J. | 8303140295 | 50-461 G |
| PAPERIELLO, C. J. | 8303150601 | 50-254 G |
| PAPERIELLO, C. J. | 8303170520 | 50-409 G |
| PAPERIELLO, C. J. | 8303210090 | 50-282 G |
| PAPERIELLO, C. J. | 8303210123 | 50-255 F |
| PAPERIELLO, C. J. | 8303210215 | 50-315 F |
| PAPERIELLO, C. J. | 8303210608 | 50-341 G |
| PAPERIELLO, C. J. | 8303210623 | 50-315 G |
| PAPERIELLO, C. J. | 8303210628* | 50-315 G |
| PAPERIELLO, C. J. | 8303220183 | 50-341 G |
| PAPERIELLO, C. J. | 8303220215 | 50-329 G |
| PAPERIELLO, C. J. | 8303240045 | 50-483 F |
| PAPERIELLO, C. J. | 8303240242 | 50-266 G |
| PAPERIELLO, C. J. | 8303240248* | 50-266 G |
| PAPERIELLO, C. J. | 8303280192 | 50-346 F |
| PARFITT, R. | 8303090273 | 50-454 T |
| PARIS, O. H. | 8303170503 | 50-320 G |
| PARKER, L. B. | 8303150278* | GA999 |
| PARKER, R. D. | 8303220170 | 50-440 G |
| PARKINSON, T. F. | 8303020049* | 50-124 R |
| PARKINSON, T. F. | 8303220167 | 50-124 P |
| PARKS, R. D. | 8303290396* | 50-320 G |
| PARKS, R. D. | 8303290396* | 50-320 G |
| PARRIS, M. L. | 8303100261 | 50-247 G |
| PARRISH, C. S. | 8303310089 | COMMISSION |
| PARSONS, R. M. | 8303010538* | 50-400 G |
| PARSONS, R. M. | 8303040474 | 50-400 S |
| PARSONS, R. M. | 8303140330 | 50-400 S |
| PARSONS, R. M. | 8303140479 | 50-400 S |
| PARSONS, R. M. | 8303210698* | 50-400 G |
| PARSONS, R. M. | 8303240431 | 50-400 S |
| PARULIS, P. J. | 8303080419* | 50-336 S |
| PASCIAK, W. J. | 8303100307* | 50-387 G |
| PASCIAK, W. J. | 8303160616* | 50-245 G |
| PASCIAK, W. J. | 8303240512* | 50-423 G |
| PASELTINER, E. | 8303230238 | 50-247 G |
| PASTVA, M. J. | 8302010596* | 50-325 S |
| PASTVA, M. J. | 8303010197* | 50-324 S |
| PASTVA, M. J. | 8303010282* | 50-324 S |
| PASTVA, M. J. | 8303010377* | 50-325 S |
| PASTVA, M. J. | 8303010384* | 50-325 S |
| PASTVA, M. J. | 8303010400* | 50-324 S |
| PASTVA, M. J. | 8303010486* | 50-325 S |
| PASTVA, M. J. | 8303010522* | 50-324 S |
| PASTVA, M. J. | 8303040360* | 50-324 S |
| PASTVA, M. J. | 8303140310* | 50-324 S |
| PASTVA, M. J. | 8303140567* | 50-324 S |
| PASTVA, M. J. | 8303160242* | 50-324 S |
| PASTVA, M. J. | 8303160286* | 50-324 S |
| PASTVA, M. J. | 8303160497* | 50-324 S |
| PASTVA, M. J. | 8303160582* | 50-324 S |
| PASTVA, M. J. | 8303180218* | 50-324 S |
| PASTVA, M. J. | 8303180232* | 50-324 S |
| PASTVA, M. J. | 8303180335* | 50-325 S |
| PASTVA, M. J. | 8303180367* | 50-324 S |
| PASTVA, M. J. | 8303180411* | 50-324 S |
| PASTVA, M. J. | 8303210317* | 50-324 S |
| PASTVA, M. J. | 8303210318* | 50-324 S |
| PASTVA, M. J. | 8303210326* | 50-325 S |
| PASTVA, M. J. | 8303210374* | 50-324 S |
| PASTVA, M. J. | 8303210490* | 50-325 S |
| PASTVA, M. J. | 8303240505* | 50-324 S |
| PATE, R. J. | 8303290255* | 50-361 G |
| PATEL, M. R. | 8303010317* | 50-454 T |
| PATEL, M. R. | 8303010317* | 50-454 T |
| PATON, W. D. | 8303220181 | 50-329 G |
| PATON, W. D. | 8303280119 | 50-397 G |
| PATON, W. D. | 8303280302 | 50-329 G |
| PATTERSON, C. H. | 8303210666* | GA999 |
| PATTERSON, C. H. | 8303210677* | GA999 |
| PATTERSON, J. M. | 8303170018* | 50-206 U |
| PATTERSON, J. M. | 8303290241* | 50-206 U |
| PATTERSON, J. P. | 8303140314* | 50-295 G |
| PATTERSON, J. P. | 8303210097* | 50-282 G |
| PATTERSON, W. F. | 8303140078 | 50-443 G |
| PATTERSON, W. F. | 8303170025 | 50-443 G |
| PATTERSON, W. F. | 8303230019 | 50-443 G |
| PATTISON, R. S. | 8303100056 | 40-8084 |
| PAUL, J. M. | 8302100335* | PR |
| PAUL, N. | 8303010345* | 50-454 T |
| PAUL, N. | 8303010345* | 50-454 T |
| PAUL, R. A. | 8303140300* | 50-461 G |
| PAULK, G. L. | 8303210775* | 50-259 G |
| PAULSON, W. | 8303160140 | 50-206 P |
| PAULSON, W. A. | 8303010550 | 50-206 P |
| PAULSON, W. A. | 8303100361 | 50-206 P |
| PAULSON, W. A. | 8303220009 | 50-206 P |
| PAULSON, W. A. | 8303220248 | 50-206 P |
| PAULSON, W. A. | 8303230241 | 50-206 P |
| PAVIS, G. S. | 8303160184* | 50-318 S |
| PAWLICKI, S. S. | 8104230095* | 50-387 P |
| PAY, D. | 8303200715 | FOIA |
| PAZARGADI, S. | 8209030274* | 50-213 P |
| PEARSON, A. | 8303230006 | XPORTLIC |
| PEARSON, R. G. | 8303210142 | ACRS |
| PEARSON, R. G. | 8303210142 | ACRS |
| PECK, C. C. | 8303030584* | 70-1308 |
| PECK, C. C. | 8303140265* | 50-254 G |
| PECK, C. C. | 8303210637* | 50-315 G |
| PEDRO, J. | 8303090160 | FOIA |
| PEEBLES, T. A. | 8303240594* | 50-346 G |
| PEERENBOOM, J. P. | 8303300628 | NUREG |
| PEERY, W. W. | 8303210409* | 50-324 G |
| PEERY, W. W. | 8303210727* | 50-348 G |
| PELIZZA, M. S. | 8303170292 | 40-8786 |
| PELKE, P. R. | 8303080457* | 50-440 G |
| PELLETIER, J. P. | 8303010436 | 50-271 S |
| PELLETIER, J. P. | 8303010441* | 50-271 S |
| PELLETIER, J. P. | 8303010446 | 50-271 S |
| PELLETIER, J. P. | 8303010455* | 50-271 S |
| PELLETIER, J. P. | 8303030045 | 50-271 S |
| PELLETIER, J. P. | 8303030064* | 50-271 S |
| PELLETIER, J. P. | 8303140442 | 50-271 S |
| PELLETIER, J. P. | 8303140454* | 50-271 S |
| PENNIFILL, R. A. | 8303180653 | WASTE MGT |
| PENTZ, D. | 8303280097 | NUREG |
| PENTZ, D. | 8303280114 | NUREG |
| PENTZ, D. L. | 8303290584* | CONTRACT |
| PERCH, R. L. | 8303040359 | 50-387 G |
| PERKINS, K. | 8303240036 | I&E |
| PERKINS, R. W. | 8303010088 | WASTE MGT |
| PERKINS, R. W. | 8303010097 | WASTE MGT |
| PERKINS, R. W. | 8303010139 | WASTE MGT |
| PERKINS, R. W. | 8303010313 | WASTE MGT |
| PERKY, D. N. | 8303040431* | 50-302 S |
| PERLA, H. F. | 8303210538 | 50-247 P |
| PERLIS, R. G. | 8303080026 | 50-443 G |
| PERLIS, R. G. | 8303140148 | 50-443 G |
| PERLIS, R. G. | 8303140206 | 50-443 G |
| PERLIS, R. G. | 8303170025 | 50-443 G |
| PERLIS, R. G. | 8303230039 | 50-443 G |
| PERLIS, R. G. | 8303240022 | 50-443 G |
| PERLIS, R. G. | 8303240318 | 50-443 G |
| PERLMAN, J. | 8303150167 | CONTRACT |
| PERLMAN, J. | 8303230376 | CONTRACT |
| PERLMAN, J. | 8303280008 | CONTRACT |
| PERLMAN, J. | 8303290128 | CONTRACT |
| PERRY, P. A. | 8303210279 | 50-155 I |
| PERRY, W. | 8303020058* | PRM |
| PERSINKO, D. | 8303100152 | MISC |
| PETERS, D. | 8303090273 | 50-454 T |
| PETERS, R. | 8303080477* | 50-333 S |
| PETERSEN, H. E. | 8303280183 | 50-285 J |
| PETERSON, A. C. | 8303180699 | RES |
| PETERSON, D. | 8303080505* | 50-255 R |
| PETERSON, D. A. | 8303140323* | 50-255 R |
| PETERSON, M. R. | 8303230081 | XPORTLIC |
| PETERSON, M. R. | 8303230088 | XPORTLIC |
| PETERSON, M. R. | 8303230093 | XPORTLIC |
| PETERSON, M. R. | 8303230100 | XPORTLIC |
| PETERSON, M. R. | 8303240337 | XPORTLIC |

# PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| PETERSON, M. R. | 8303240344 | XPORTLIC |
| PETERSON, M. R. | 8303240348 | XPORTLIC |
| PETERSON, M. R. | 8303280002 | XPORTLIC |
| PETERSON, M. R. | 8303290074 | XPORTLIC |
| PETERSON, M. R. | 8303290123 | XPORTLIC |
| PETERSON, M. R. | 8303290148 | XPORTLIC |
| PETRICK, N. | 8303040524 | 50-482 A |
| PETRICK, N. A. | 8303140287 | 50-482 F |
| PETRICK, N. A. | 8303150442 | 50-482 S |
| PETRICK, N. A. | 8303150503 | 50-482 K |
| PETTENGILL, H. J. | 8303090010 | 40-6622 |
| PETTENGILL, H. J. | 8303090042 | 40-299 |
| PETTENGILL, H. J. | 8303090044 | 40-2259 |
| PETTENGILL, H. J. | 8303090349 | 40-1341 |
| PETTENGILL, H. J. | 8303090356 | 40-299 |
| PETTENGILL, H. J. | 8303090426 | 40-1162 |
| PETTENGILL, H. J. | 8303090554 | 40-8586 |
| PETTENGILL, H. J. | 8303170050 | 40-8584 |
| PETTENGILL, H. J. | 8303170058 | 40-299 |
| PETTENGILL, H. J. | 8303170172 | 40-6622 |
| PETTENGILL, H. J. | 8303170579 | 40-1162 |
| PETTENGILL, H. J. | 8303180102* | 40-3453 |
| PETTENGILL, H. J. | 8303180106* | 40-3453 |
| PETTENGILL, H. J. | 8303180140 | 40-299 |
| PETTENGILL, H. J. | 8303180162 | 40-3453 |
| PETTENGILL, H. J. | 8303210236 | 40-8602 |
| PETTENGILL, H. J. | 8303210769 | 40-2259 |
| PETTIJOHN, S. L. | 8212220495* | MISC |
| PEVENSTEIN, J. | 8303290779* | CONTRACT |
| PEVENSTEIN, J. | 8303290790* | CONTRACT |
| PEVENSTEIN, J. | 8303310036* | CONTRACT |
| PEVER, R. C. | 8303140566* | 50-443 Q |
| PEVEY, L. E. | 8303150676 | XPORTLIC |
| PFEFFERLEN, H. C. | 8303160229 | TOPREP |
| PHILIPS, J. D. | 8303020048 | PRM |
| PHILIPS, S. | 8303250113 | NUREG |
| PHILLIPS, H. | 8303250034* | 50-438 Q |
| PHILLIPS, H. S. | 8303010499* | GA999 |
| PHILLIPS, H. S. | 8303040572* | GA999 |
| PHILLIPS, H. S. | 8303070044* | GA999 |
| PHILLIPS, H. S. | 8303180399* | GA999 |
| PHILLIPS, H. S. | 8303280320* | GA999 |
| PHILLIPS, M. P. | 8303140314* | 50-295 Q |
| PHILLIPS, M. P. | 8303150606* | 50-254 Q |
| PIKE, D. B. | 8303150518* | 50-29 P |
| PILANT, J. M. | 8302090056 | 50-298 F |
| PILANT, J. M. | 8303010535* | 50-298 F |
| PILANT, J. M. | 8303020066 | 50-298 P |
| PILANT, J. M. | 8303150256 | 50-298 R |
| PILANT, J. M. | 8303150313 | 50-298 P |
| PILANT, J. M. | 8303160426 | 50-298 J |
| PILANT, J. M. | 8303180226* | 50-298 G |
| PILANT, J. M. | 8303250134 | 50-298 F |
| PILANT, J. M. | 8303280038 | 50-298 F |
| PILANT, J. M. | 8303290129* | 50-298 F |
| PIRTLE, G. | 8303010072* | 50-440 G |
| PIRTLE, G. L. | 8303030540* | 50-373 G |
| PIRTLE, G. L. | 8303140357* | 50-2 G |
| PIRTLE, G. L. | 8303170459* | 50-266 G |
| PITT, C. J. | 8303150031 | NUREG |
| PLAINE, H. H. | 8303140366 | 50-322 G |
| PLATO, P. | 8303100443 | NUREG |
| PLATO, P. | 8303100453 | NUREG |
| PLATT, W. E. | 8303140462 | 50-528 G |
| PLATT, W. E. | 8303140472* | 50-528 G |
| PLATT, W. E. | 8303140472* | 50-528 G |
| PLISCO, L. | 8303240363* | 50-387 G |
| PLISCO, L. R. | 8301310290* | 50-277 G |
| PLISCO, L. R. | 8303240301* | 50-352 G |
| PLOSKI, T. J. | 8303140314* | 50-295 G |
| PLUMLEE, G. L. | 8303070088* | 50-267 G |
| POCHAL, W. F. | 8303030659 | XPORTLIC |
| POCHAL, W. F. | 8303030773 | XPORTLIC |
| POCHAL, W. F. | 8303040127 | XPORTLIC |
| POCHAL, W. F. | 8303140662 | XPORTLIC |
| POCHAL, W. F. | 8303230442 | XPORTLIC |
| POCHAL, W. F. | 8303240325 | XPORTLIC |
| POLK, H. | 8303040651* | 50-275 P |
| POLK, P. J. | 8303030396 | 50-286 P |
| POLLOCK, M. S. | 8303090221 | 50-322 A |
| POLLOCK, M. S. | 8303100265* | 50-322 G |
| POLLOCK, M. S. | 8303140218* | 50-322 G |
| POLLOCK, M. S. | 8303140219* | 50-322 G |
| POLLOCK, M. S. | 8303140255 | 50-322 S |
| POLLOCK, M. S. | 8303180176 | 50-322 G |
| POMERENING, D. J. | 8303290606* | TOPREP |
| POMERENING, D. J. | 8303290613* | TOPREP |
| POMERENING, D. J. | 8303290631* | TOPREP |
| POMEROY, P. W. | 8303180175 | ACRS |
| POMEROY, P. W. | 8303180175 | ACRS |
| POPE, D. | 8303080058 | 50-454 T |
| PORCH, D. R. | 8303210749* | 50-361 P |
| PORTER, J. B. | 8303310576* | CONTRACT |
| PORTZ, R. | 8303300029* | 50-331 F |
| POSAKONY, G. J. | 8303220422 | NUREG |
| POSNER, P. | 8303230207 | 50-247 Q |
| POSTMA, A. K. | 8303140696 | NUREG |
| POTAPOVS, U. | 8303010348 | GA999 |
| POTAPOVS, U. | 8303010363 | GA999 |
| POTAPOVS, U. | 8303010366 | GA999 |
| POTAPOVS, U. | 8303010450 | GA999 |
| POTAPOVS, U. | 8303010475 | GA999 |
| POTAPOVS, U. | 8303010476 | GA999 |
| POTAPOVS, U. | 8303010657 | GA999 |
| POTAPOVS, U. | 8303030529 | GA999 |
| POTAPOVS, U. | 8303030637 | GA999 |
| POTAPOVS, U. | 8303040535 | GA999 |
| POTAPOVS, U. | 8303040556 | GA999 |
| POTAPOVS, U. | 8303040560* | GA999 |
| POTAPOVS, U. | 8303040598 | GA999 |
| POTAPOVS, U. | 8303070006 | GA999 |
| POTAPOVS, U. | 8303070016 | GA999 |
| POTAPOVS, U. | 8303070023 | GA999 |
| POTAPOVS, U. | 8303070029 | GA999 |
| POTAPOVS, U. | 8303070032 | GA999 |
| POTAPOVS, U. | 8303070033 | GA999 |
| POTAPOVS, U. | 8303070063 | GA999 |
| POTAPOVS, U. | 8303070069 | GA999 |
| POTAPOVS, U. | 8303070074 | GA999 |
| POTAPOVS, U. | 8303070090 | GA999 |
| POTAPOVS, U. | 8303070098 | GA999 |
| POTAPOVS, U. | 8303070101 | GA999 |
| POTAPOVS, U. | 8303070107 | GA999 |
| POTAPOVS, U. | 8303070124 | GA999 |
| POTAPOVS, U. | 8303070143* | GA999 |
| POTAPOVS, U. | 8303070144 | GA999 |
| POTAPOVS, U. | 8303070168* | GA999 |
| POTAPOVS, U. | 8303080371 | GA999 |
| POTAPOVS, U. | 8303080383 | GA999 |
| POTAPOVS, U. | 8303150159 | GA999 |
| POTAPOVS, U. | 8303150164 | GA999 |
| POTAPOVS, U. | 8303150179* | GA999 |
| POTAPOVS, U. | 8303150236 | GA999 |
| POTAPOVS, U. | 8303150245 | GA999 |
| POTAPOVS, U. | 8303150259 | GA999 |
| POTAPOVS, U. | 8303150302 | GA999 |
| POTAPOVS, U. | 8303150314 | GA999 |
| POTAPOVS, U. | 8303150351 | GA999 |
| POTAPOVS, U. | 8303150361 | GA999 |
| POTAPOVS, U. | 8303150468 | GA999 |
| POTAPOVS, U. | 8303150559 | GA999 |
| POTAPOVS, U. | 8303150579* | GA999 |
| POTAPOVS, U. | 8303180192 | GA999 |
| POTAPOVS, U. | 8303180366 | GA999 |
| POTAPOVS, U. | 8303180388 | GA999 |
| POTAPOVS, U. | 8303210366 | GA999 |
| POTAPOVS, U. | 8303210395 | GA999 |
| POTAPOVS, U. | 8303210404 | GA999 |
| POTAPOVS, U. | 8303210420 | GA999 |
| POTAPOVS, U. | 8303210457 | GA999 |
| POTAPOVS, U. | 8303210482 | GA999 |
| POTAPOVS, U. | 8303210514 | GA999 |
| POTAPOVS, U. | 8303210525 | 50-518 A |
| POTAPOVS, U. | 8303210561 | GA999 |
| POTAPOVS, U. | 8303210601 | GA999 |
| POTAPOVS, U. | 8303210618 | GA999 |
| POTAPOVS, U. | 8303210656 | GA999 |
| POTAPOVS, U. | 8303210672* | GA999 |
| POTAPOVS, U. | 8303210681 | GA999 |
| POTAPOVS, U. | 8303250046 | MISC |
| POTAPOVS, U. | 8303280160 | GA999 |
| POTAPOVS, U. | 8303280165 | GA999 |
| POTAPOVS, U. | 8303280198 | GA999 |
| POTAPOVS, U. | 8303280205 | GA999 |
| POTAPOVS, U. | 8303280305 | GA999 |
| POTAPOVS, U. | 8303290205 | GA999 |
| POTAPOVS, U. | 8303290288 | GA999 |
| POTAPOVS, U. | 8303290294 | GA999 |
| POTAPOVS, U. | 8303290352 | GA999 |
| POTAPOVS, U. | 8303290372 | GA999 |
| POTTER, T. E. | 8303250145 | 50-247 T |
| POTTER, T. E. | 8303250145 | 50-247 T |
| POTTER, T. E. | 8303250145 | 50-247 T |
| POTTER, T. E. | 8303250149* | 50-247 T |
| POTTER, T. E. | 8303250149* | 50-247 T |
| POTTERFIELD, A. | 8303030433 | 50-247 Q |
| POTTERFIELD, A. | 8303030433 | 50-247 Q |
| POTTERFIELD, A. | 8303030433 | 50-247 Q |
| POTTERFIELD, A. | 8303030433 | 50-247 Q |
| POTTERFIELD, A. | 8303030433 | 50-247 Q |
| POTTERFIELD, A. | 8303030433 | 50-247 Q |
| POTTERFIELD, A. | 8303030433 | 50-247 Q |
| POTTERFIELD, A. | 8303030433 | 50-247 Q |
| POTTERFIELD, A. | 8303070113 | 50-247 Q |
| POTTERFIELD, A. | 8303070161 | 50-247 Q |
| POTTERFIELD, A. | 8303180144 | 50-247 Q |
| POTTERFIELD, A. | 8303180144 | 50-247 Q |
| POTTERFIELD, A. | 8303180144 | 50-247 Q |
| POTTERFIELD, A. | 8303180217 | 50-247 Q |
| POTTERFIELD, A. | 8303180217 | 50-247 Q |
| POTTERFIELD, A. | 8303180217 | 50-247 Q |
| POTTERFIELD, A. | 8303230407 | 50-247 Q |
| POULK, R. M. | 8303010275* | 50-325 S |
| POULK, R. M. | 8303210445* | 50-325 S |
| POWELL, D. | 8303040605* | 50-324 P |
| POYSER, R. W. | 8303090584 | 40-2259 |
| POYSER, R. W. | 8303160034 | 40-2259 |
| PRATT, B. | 8303030422 | 70-143 |
| PRATT, C. | 8303090321 | 50-247 Q |
| PRATT, C. | 8303090321 | 50-247 Q |
| PRATT, C. M. | 8303080109 | 50-247 Q |
| PRATT, C. M. | 8303080109 | 50-247 Q |
| PRATT, C. M. | 8303180277 | 50-247 Q |
| PRATT, C. M. | 8303180277 | 50-247 Q |
| PRATT, C. M. | 8303220272 | 50-247 Q |
| PRATT, C. M. | 8303230176 | 50-247 Q |
| PRATT, C. M. | 8303230176 | 50-247 Q |
| PRATT, C. M. | 8303230179* | 50-247 Q |
| PRATT, C. M. | 8303300303 | 50-247 Q |
| PRATT, C. M. | 8303300307* | 50-247 Q |
| PRATT, C. M. | 8303300313* | 50-247 Q |
| PRATT, C. M. | 8303300319* | 50-247 Q |
| PRATT, C. M. | 8303300322* | 50-247 Q |
| PRATT, C. M. | 8303300326 | 50-247 Q |
| PRATT, C. M. | 8303300374 | 50-247 Q |
| PRATT, C. M. | 8303300417 | 50-247 Q |
| PRATT, C. M. | 8303300489 | 50-247 Q |
| PRATT, W. T. | 8303140664 | 50-352 A |
| PRATT, W. T. | 8303310470* | 50-416 P |
| PRATT, W. T. | 8303310489* | 50-440 A |
| PRESTHOLT, P. T. | 8303290060 | WASTE MGT |
| PRESTHOLT, P. T. | 8303290664 | WASTE MGT |
| PRESTHOLT, P. T. | 8303300139 | WASTE MGT |
| PRICE, D. | 8108210447* | FOIA |
| PRICE, E. B. | 8303040217* | State Prog |
| PRICHARD, R. P. | 8303100347 | 71-5364 |
| PRICHARD, R. P. | 8303110014 | 71-6387 |
| PRICHARD, R. P. | 8303280055 | 71-4909 |
| PULLANI, S. | 8303240363* | 50-387 G |
| PULLANI, S. V. | 8303030662* | 50-272 G |
| PULLANI, S. V. | 8303240528* | 50-247 G |
| PURPLE, R. A. | 8303090431* | 50-271 F |
| PURPLE, R. A. | 8303160018* | 50-410 A |
| PURPLE, R. A. | 8303220462* | 50-344 P |
| PURPLE, R. A. | 8303220476* | 50-285 P |
| PURPLE, R. A. | 8303220491* | 50-309 P |
| PURPLE, R. A. | 8303230066* | 50-335 P |
| PURPLE, R. A. | 8303230079* | 50-266 P |
| PURPLE, R. A. | 8303230103* | 50-336 P |
| PURPLE, R. A. | 8303230159* | 50-282 P |
| PURPLE, R. A. | 8303280115* | 50-293 P |
| PURPLE, R. A. | 8303280129* | 50-333 P |
| PURPLE, R. A. | 8303280343* | 50-346 P |
| PURPLE, R. A. | 8303290007* | 50-250 P |
| PURPLE, R. A. | 8303290011* | 50-247 P |
| PURPLE, R. A. | 8303290019* | 50-321 P |
| PURPLE, R. A. | 8303290036* | 50-286 P |
| PURPLE, R. A. | 8303290054* | 50-368 P |
| PURPLE, R. A. | 8303290087* | 50-280 P |
| PURPLE, R. A. | 8303290114* | 50-263 P |
| PURPLE, R. A. | 8303290163* | 50-272 P |
| PURPLE, R. A. | 8303290218* | 50-220 P |
| PURPLE, R. A. | 8303290270* | 50-334 F |
| PURPLE, R. A. | 8303290405* | 50-277 P |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| PURPLE, R. A. | 8303290429* | 50-312 P |
| PURPLE, R. A. | 8303290591* | 50-250 P |
| PURPLE, R. A. | 8303290622* | 50-313 P |
| PURPLE, R. A. | 8303290653* | 50-338 P |
| PURPLE, R. A. | 8303290806* | 50-315 P |
| PURPLE, R. A. | 8303300022* | 50-271 P |
| PURPLE, R. A. | 8303300034* | 50-254 P |
| PURPLE, R. A. | 8303300036* | 50-269 P |
| PURPLE, R. A. | 8303300040* | 50-261 P |
| PURPLE, R. A. | 8303300072* | 50-324 P |
| PURPLE, R. A. | 8303300118* | 50-317 P |
| PURPLE, R. A. | 8303300171* | 50-331 P |
| PURPLE, R. A. | 8303300191* | 50-305 P |
| PURPLE, R. A. | 8303300205* | 50-348 P |
| PURPLE, R. A. | 8303300217* | 50-298 P |
| QUERIO, R. E. | 8303080094 | 50-454 T |
| QUICK, D. R. | 8303010341* | 50-390 Q |
| QUIGG, C. | 8303090273 | 50-454 T |
| QUINN, E. | 8303290601* | WASTE MGT |
| QUINN, E. J. | 8303290581 | WASTE MGT |
| QUINN, E. J. | 8303290588* | WASTE MGT |
| QUINN, E. J. | 8303290593 | WASTE MGT |
| QUINN, E. J. | 8303290604 | WASTE MGT |
| QUINN, E. J. | 8303290610* | WASTE MGT |
| QUINN, E. J. | 8303290817 | WASTE MGT |
| QUIRK, J. F. | 8303240256 | TOPREP |
| RAE, R. M. | 8303240181* | FOIA |
| RAHE, E. P. | 8302160328 | TOPREP |
| RAHE, E. P. | 8303040509 | TOPREP |
| RAHE, E. P. | 8303070146 | TOPREP |
| RAHE, E. P. | 8303080129 | PROJ |
| RAHE, E. P. | 8303090113 | TOPREP |
| RAHE, E. P. | 8303090192 | TOPREP |
| RAHE, E. P. | 8303250023 | 50-445 A |
| RAHE, E. P. | 8303250044* | TOPREP |
| RAHE, E. P. | 8303250045* | TOPREP |
| RAHE, E. P. | 8303250047* | TOPREP |
| RAHE, E. P. | 8303250049* | TOPREP |
| RAHE, E. P. | 8303290144 | 50-272 S |
| RAHE, E. P. | 8303300342 | TOPREP |
| RAJAN, J. R. | 8303310256* | 50-445 T |
| RAMIREI, A. L. | 8303290626 | WASTE MGT |
| RAMSEY, C. | 8303140406* | 50-266 Q |
| RANDAZZA, J. B. | 8303170220 | 50-309 Q |
| RANDAZZA, J. B. | 8303240328 | 50-309 Q |
| RANDO, J. J. | 8303150479 | 50-537 A |
| RANGANATH, S. | 8302040475* | 71-9001 |
| RANGANATH, S. | 8303040555* | 50-293 P |
| RANSOHOFF, J. A. | 8303310078* | FOIA |
| RANSOHOFF, J. A. | 8303310081* | FOIA |
| RANSOHOFF, J. A. | 8303310085* | FOIA |
| RANSOHOFF, J. A. | 8303310094* | FOIA |
| RANSOHOFF, J. A. | 8303310214* | FOIA |
| RANSOHOFF, J. A. | 8303310253* | FOIA |
| RANSOHOFF, J. A. | 8303310280* | FOIA |
| RANSOHOFF, J. A. | 8303310304* | FOIA |
| RANSOHOFF, J. A. | 8303310309* | FOIA |
| RANSOHOFF, J. A. | 8303310314* | FOIA |
| RANSOHOFF, J. A. | 8303310319* | FOIA |
| RANSOHOFF, J. A. | 8303310342* | FOIA |
| RANSOM, C. B. | 8303290797 | 50-255 P |
| RANSOM, V. H. | 8303240144 | RES |
| RASILE, J. A. | 8303160667* | CONTRACT |
| RASMUSSEN, J. | 8303160623* | 50-324 P |
| RAWSON, R. J. | 8303220165 | 50-322 Q |
| RAWSON, R. J. | 8303250137 | 50-454 C |
| RAWSON, R. J. | 8303310273 | 50-322 Q |
| RAY, H. B. | 8302150674 | 50-361 S |
| RAY, H. B. | 8302150685* | 50-361 S |
| RAY, H. B. | 8303040502 | 50-361 S |
| RAY, H. B. | 8303040520 | 50-362 S |
| RAY, H. B. | 8303040526* | 50-362 S |
| RAY, H. B. | 8303040567 | 50-362 S |
| RAY, H. B. | 8303040573* | 50-362 S |
| RAY, H. B. | 8303040577 | 50-362 S |
| RAY, H. B. | 8303040589* | 50-362 S |
| RAY, H. B. | 8303040602 | 50-362 S |
| RAY, H. B. | 8303040608 | 50-362 S |
| RAY, H. B. | 8303040615* | 50-362 S |
| RAY, H. B. | 8303040616* | 50-362 S |
| RAY, H. B. | 8303040618 | 50-361 S |
| RAY, H. B. | 8303040624* | 50-361 S |
| RAY, H. B. | 8303040629 | 50-361 S |
| RAY, H. B. | 8303040636* | 50-361 S |
| RAY, H. B. | 8303080095 | 50-361 R |
| RAY, H. B. | 8303080156 | 50-206 R |
| RAY, H. B. | 8303110080 | 50-362 S |
| RAY, H. B. | 8303110092* | 50-362 S |
| RAY, H. B. | 8303110113 | 50-362 S |
| RAY, H. B. | 8303110115 | 50-361 S |
| RAY, H. B. | 8303110125* | 50-362 S |
| RAY, H. B. | 8303110134* | 50-362 S |
| RAY, H. B. | 8303110142* | 50-361 S |
| RAY, H. B. | 8303110188 | 50-362 S |
| RAY, H. B. | 8303110191* | 50-362 S |
| RAY, H. B. | 8303110201 | 50-362 S |
| RAY, H. B. | 8303110208* | 50-362 S |
| RAY, H. B. | 8303110224 | 50-362 S |
| RAY, H. B. | 8303110225 | 50-361 S |
| RAY, H. B. | 8303110230* | 50-361 S |
| RAY, H. B. | 8303110239 | 50-362 S |
| RAY, H. B. | 8303110258 | 50-361 S |
| RAY, H. B. | 8303110267 | 50-361 S |
| RAY, H. B. | 8303110273* | 50-361 S |
| RAY, H. B. | 8303110305 | 50-362 S |
| RAY, H. B. | 8303110325* | 50-362 S |
| RAY, H. B. | 8303110333 | 50-362 S |
| RAY, H. B. | 8303110337* | 50-362 S |
| RAY, H. B. | 8303110342* | 50-362 S |
| RAY, H. B. | 8303110347 | 50-362 S |
| RAY, H. B. | 8303110349* | 50-362 S |
| RAY, H. B. | 8303150566 | 50-361 R |
| RAY, H. B. | 8303150589 | 50-206 R |
| RAY, H. B. | 8303180265 | 50-361 S |
| RAY, H. B. | 8303180272* | 50-361 S |
| RAY, H. B. | 8303180435 | 50-362 S |
| RAY, H. B. | 8303180443* | 50-362 S |
| RAY, H. B. | 8303180481 | 50-361 S |
| RAY, H. B. | 8303180486 | 50-362 S |
| RAY, H. B. | 8303180487* | 50-361 S |
| RAY, H. B. | 8303180495* | 50-362 S |
| RAY, H. B. | 8303180501 | 50-362 S |
| RAY, H. B. | 8303180520 | 50-361 S |
| RAY, H. B. | 8303180525* | 50-361 S |
| RAY, H. B. | 8303290067 | 50-362 S |
| RAY, H. B. | 8303290072* | 50-362 S |
| RAY, H. B. | 8303290212* | 50-362 S |
| RAY, H. B. | 8303290216 | 50-362 S |
| RAY, H. B. | 8303290221* | 50-362 S |
| RAY, H. B. | 8303290225 | 50-362 S |
| RAY, H. B. | 8303290233* | 50-362 S |
| RAY, H. B. | 8303290277 | 50-361 S |
| RAY, H. B. | 8303290286* | 50-361 S |
| RAY, H. B. | 8303290326* | 50-362 S |
| RAY, H. B. | 8303290329 | 50-362 S |
| RAY, H. B. | 8303290335* | 50-362 S |
| RAY, H. B. | 8303290376 | 50-361 S |
| RAY, H. B. | 8303290492 | 50-361 S |
| RAY, H. B. | 8303290494* | 50-361 S |
| RAY, J. J. | 8301200157* | COMMISSION |
| RAY, J. J. | 8302250124* | 50-522 A |
| RAYMOND, W. | 8303030080 | 50-271 S |
| RAYNOR, J. W. | 8303010256* | 50-317 S |
| RAYNOR, J. W. | 8303010393* | 50-318 S |
| READ, D. F. | 8303150413 | 50-400 Q |
| READE, R. T. | 8303150130 | NUREG |
| REAP, M. E. | 8303230490 | FOIA |
| REAVIS, J. A. | 8303080364* | 50-269 R |
| REAVIS, J. A. | 8303180376* | 50-369 R |
| REAVIS, J. A. | 8303180386* | 50-269 R |
| REAVIS, J. M. | 8303240176* | FOIA |
| REBELLO, J. | 8303150158* | CONTRACT |
| REBELLO, J. E. | 8303010003* | 50-206 P |
| REBELLO, J. E. | 8303010730* | CONTRACT |
| REBELLO, J. E. | 8303170656* | CONTRACT |
| REBELLO, J. E. | 8303230195* | CONTRACT |
| REBELLO, J. E. | 8303300100* | 50-537 A |
| REBELLO, J. E. | 8303300485* | CONTRACT |
| REBELLO, J. E. | 8303310576* | CONTRACT |
| REBELOWSKI, T. | 8303240461* | 50-213 Q |
| REDANO, R. T. | 8303100015 | FOIA |
| REDANO, R. T. | 8303250022* | 50-267 Q |
| REED, C. | 8303030691* | 50-456 Q |
| REED, C. | 8303040244* | COMMISSION |
| REED, C. | 8303080482 | 50-454 T |
| REED, C. | 8303150343 | 50-237 Q |
| REED, S. A. | 8201060494* | FOIA |
| REEDY, R. F. | 8303090259 | 50-275 R |
| REEDY, R. F. | 8303090304 | 50-275 R |
| REEDY, R. F. | 8303240409 | 50-275 R |
| REEVES, E. | 8303180681 | 50-364 P |
| REEVES, E. A. | 8303030195 | 50-348 P |
| REEVES, E. A. | 8303310089 | COMMISSION |
| REGAN, N. A. | 8303010001 | 71-5088 |
| REGAN, N. A. | 8303010695 | 70-27 |
| REGAN, W. H. | 8303300128 | 50-410 M |
| REHM, T. A. | 8303040112 | COMMISSION |
| REHM, T. A. | 8303090200 | COMMISSION |
| REHM, T. A. | 8303100462* | FOIA |
| REHM, T. A. | 8303160089 | COMMISSION |
| REHM, T. A. | 8303160738* | 50-272 S |
| REHM, T. A. | 8303160745* | 50-272 S |
| REHM, T. A. | 8303240062 | COMMISSION |
| REHM, T. A. | 8303290617 | COMMISSION |
| REICH, M. | 8303020119* | 50-275 P |
| REICH, M. | 8303090291 | 50-275 P |
| REICH, M. | 8303090389 | 50-275 P |
| REICH, M. | 8303140571* | 50-275 P |
| REICH, M. | 8303140579* | 50-275 P |
| REID, A. B. | 8303090001 | FOIA |
| REIMANN, F. W. | 8303240460* | 50-341 Q |
| REIMANN, F. W. | 8303240607* | 50-254 Q |
| REINHOLD, T. A. | 8303290707 | NUREG |
| REIS, E. J. | 8303240233 | 50-322 Q |
| REISMAN, H. | 8303020100* | 50-247 T |
| REITER, L. | 8303300435 | NUREG |
| REIVITT, L. | 8303310367* | CONTRACT |
| REKITO, W. A. | 8303100150* | 50-336 Q |
| RENNELS, A. E. | 8303220388 | 40-2061 |
| RENSNER, G. D. | 8303100460 | NUREG |
| RENSNER, G. D. | 8303100558 | NUREG |
| RENTSCHLER, R. R. | 8303150104 | 70-824 |
| RENTSCHLER, R. R. | 8303170318 | 70-27 |
| RENTSCHLER, R. R. | 8303170326 | 70-143 |
| RENTSCHLER, R. R. | 8303170332 | 70-2941 |
| RENTSCHLER, R. R. | 8303170338 | 70-1151 |
| RENTSCHLER, R. R. | 8303170342 | 70-1201 |
| RENTSCHLER, R. R. | 8303170351 | 70-1257 |
| RENTSCHLER, R. R. | 8303170357 | 70-27 |
| RENTSCHLER, R. R. | 8303170363 | 70-364 |
| RENTSCHLER, R. R. | 8303180049 | 70-25 |
| REPKA, D. A. | 8303030455 | 50-322 Q |
| REPKA, D. A. | 8303040327 | 50-322 Q |
| REPKA, D. A. | 8303140004 | 50-322 Q |
| REPKA, D. A. | 8303140504 | 50-322 Q |
| REPKA, D. A. | 8303230012 | 50-322 Q |
| REPKA, D. A. | 8303280298 | 50-322 Q |
| REQUA, G. | 8303010044 | 50-261 P |
| REQUA, G. | 8303110091 | 50-261 P |
| REQUA, G. | 8303310089 | COMMISSION |
| RESNER, M. E. | 8303110066* | 50-206 Q |
| RESNIKOFF, M. | 8303010121 | 71-6698 |
| RESNIKOFF, M. | 8303020144 | 71-6698 |
| REUTER, D. A. | 8303110332 | 50-313 Q |
| REUTER, D. A. | 8303280017 | 50-313 Q |
| REVELEY, W. T. | 8303230209 | 50-322 Q |
| REVELEY, W. T. | 8303230209 | 50-322 Q |
| REVELEY, W. T. | 8303240039* | 50-322 Q |
| REVELEY, W. T. | 8303240039* | 50-322 Q |
| REVELEY, W. T. | 8303300423 | 50-322 Q |
| REVELEY, W. T. | 8303300423 | 50-322 Q |
| REYES, L. | 8303040596* | 50-454 Q |
| REYES, L. | 8303140334* | 50-483 Q |
| REYES, L. | 8303240607* | 50-254 Q |
| REYES, L. A. | 8303040540* | 50-483 Q |
| REYES, L. A. | 8303240460* | 50-341 Q |
| REYNOLDS, J. R. | 8303080061 | 50-275 Q |
| REYNOLDS, J. R. | 8303080061 | 50-275 Q |
| REYNOLDS, N. S. | 8303010316 | 50-445 Q |
| REYNOLDS, N. S. | 8303010316 | 50-445 Q |
| REYNOLDS, N. S. | 8303010333 | 50-445 Q |
| REYNOLDS, N. S. | 8303010333 | 50-445 Q |
| REYNOLDS, N. S. | 8303020036 | 50-460 Q |
| REYNOLDS, N. S. | 8303020036 | 50-460 Q |
| REYNOLDS, N. S. | 8303020057 | 50-460 Q |
| REYNOLDS, N. S. | 8303020057 | 50-460 Q |
| REYNOLDS, N. S. | 8303070122 | 50-445 Q |
| REYNOLDS, N. S. | 8303070122 | 50-445 Q |
| REYNOLDS, N. S. | 8303080024 | 50-445 Q |
| REYNOLDS, N. S. | 8303080024 | 50-445 Q |
| REYNOLDS, N. S. | 8303080034 | 50-460 Q |
| REYNOLDS, N. S. | 8303080034 | 50-460 Q |
| REYNOLDS, N. S. | 8303180371 | 50-445 Q |
| REYNOLDS, N. S. | 8303180371 | 50-445 Q |
| REYNOLDS, N. S. | 8303220250 | 50-460 Q |

# PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| REYNOLDS, N. S. | 8303220250 | 50-460 Q |
| REYNOLDS, N. S. | 8303230228 | 50-445 Q |
| REYNOLDS, N. S. | 8303230228 | 50-445 Q |
| REYNOLDS, N. S. | 8303310263 | 50-445 Q |
| REYNOLDS, N. S. | 8303310263 | 50-445 Q |
| REYNOLDS, N. S. | 8303310272 | 50-445 Q |
| REYNOLDS, N. S. | 8303310272 | 50-445 Q |
| REYNOLDS, S. D. | 8303100281* | 50-443 Q |
| REYNOLDS, S. D. | 8303100322* | 50-272 Q |
| REYNOLDS, S. D. | 8303300340* | 50-286 Q |
| REYNOLDS, S. D. | 8303300504* | 50-309 Q |
| REYNOLDS, W. S. | 8303110218 | 50-508 Q |
| REYNOLDS, W. S. | 8303110218 | 50-508 Q |
| REYTBLATT, Z. V. | 8303090614* | ORG |
| REYTBLATT, Z. V. | 8303090630* | ORG |
| REYTBLATT, Z. V. | 8303090639* | ORG |
| REYTBLATT, Z. V. | 8303090653* | ORG |
| RHEE, S. | 8302280487* | 50-249 S |
| RHEE, S. | 8303170327* | 50-237 S |
| RHINELANDER, J. | 8303010070* | 40-2061 |
| RHINELANDER, J. | 8303020101 | 40-2061 |
| RHINELANDER, J. | 8303220405* | 40-2061 |
| RHOADS, Q. | 8303280231* | 50-387 Q |
| RHODE, Q. K. | 8303140457* | 50-410 Q |
| RHODERICK, J. E. | 8303300429 | WASTE MGT |
| RHYNE, D. D. | 8303040551* | 50-324 P |
| RICCARDELLA, P. | 8303100082* | 50-265 P |
| RICCARDELLA, P. | 8303100087* | 50-265 P |
| RICE, D. A. | 8303010404* | 50-29 S |
| RICE, D. A. | 8303040456* | 50-29 S |
| RICE, Q. B. | 8303220384 | 40-2061 |
| RICH, B. L. | 8303160758 | RES |
| RICHARDS, B. L. | 8303210544* | 70-27 |
| RICHARDS, B. L. | 8303210580* | 70-143 |
| RICHARDS, S. | 8303240591* | 50-289 Q |
| RICHARDS, W. J. | 8303110093* | ORG |
| RICHARDS, W. J. | 8303300042* | ORG |
| RICHARDSON, D. C. | 8303250149* | 50-247 T |
| RICHARDSON, D. C. | 8303250149* | 50-247 T |
| RICHARDSON, J. D. | 8303230022* | 50-416 R |
| RICHARDSON, J. D. | 8303290369 | 50-416 P |
| RICHARDSON, J. D. | 8303290369 | 50-416 P |
| RICHTER, L. | 8303240493* | 50-346 S |
| RICKARD, D. C. | 8303010163 | 50-170 Q |
| RICSON, D. M. | 8303100460 | NUREG |
| RIDDLE, D. H. | 8303290267 | 71-9133 |
| RIDGELY, J. N. | 8303140420* | 50-329 T |
| RIEMKE, R. A. | 8303240144 | RES |
| RILEY, J. L. | 8303240584 | 50-413 Q |
| RILEY, J. L. | 8303310345 | 50-413 Q |
| RILEY, R. W. | 8303040185* | COMMISSION |
| RIMAWI, K. | 8303040543* | State Prog |
| RIMAWI, K. | 8303290039* | CONTRACT |
| RING, M. | 8303140423* | 50-373 Q |
| RING, M. A. | 8303040596* | 50-454 Q |
| RITCHIE, L. T. | 8303220429 | NUREG |
| RITTER, P. D. | 8303160758 | RES |
| RIVENBARK, Q. | 8303230386 | 50-321 P |
| RIVENBARK, Q. | 8303240124 | 50-321 P |
| RIVENBARK, Q. W. | 8303300507 | 50-321 P |
| RIVERA, E. | 8303090555 | RES |
| ROBBINS, T. R. | 8303010392* | 50-244 P |
| ROBERDS, H. W. | 8303010483* | GA999 |
| ROBERDS, H. W. | 8303150530* | 50-445 Q |
| ROBERDS, W. | 8303280097 | NUREG |
| ROBERDS, W. | 8303280114 | NUREG |
| ROBERTS, E. S. | 8303180086* | CONTRACT |
| ROBERTS, E. S. | 8303180096* | CONTRACT |
| ROBERTS, H. R. | 8303140692 | 40-8681 |
| ROBERTS, H. R. | 8303230388 | 40-8681 |
| ROBERTS, H. R. | 8303300242 | 40-8681 |
| ROBERTE, J. P. | 8303150113 | PROJ |
| ROBERTS, T. M. | 8303300629* | FOIA |
| ROBERTSON, D. E. | 8303280076 | WASTE MGT |
| ROBINSON, D. | 8303080398* | 50-315 S |
| ROBINSON, D. | 8303080410* | 50-315 S |
| ROBINSON, K. L. | 8303220193 | 50-322 Q |
| ROBINSON, K. L. | 8303220197* | 50-322 Q |
| ROBINSON, K. L. | 8303220200* | 50-322 Q |
| ROCCO, B. P. | 8303100136 | RES |
| ROCCO, J. | 8303220353 | TOPREP |
| ROCKHOLD, H. C. | 8303290797 | 50-255 P |
| RODRIGUEZ, P. | 8303010605 | 50-247 Q |
| RODRIGUEZ, P. | 8303100242 | 50-247 Q |
| RODRIGUEZ, R. | 8303010423 | 50-312 P |
| RODRIGUEZ, R. J. | 8303110237 | 50-312 Q |
| RODRIGUEZ, R. J. | 8303110357 | 50-312 S |
| RODRIGUEZ, R. J. | 8303150342 | 50-312 R |
| RODRIGUEZ, R. J. | 8303220171 | 50-312 P |
| RODRIGUEZ, R. J. | 8303250018 | 50-312 Q |
| RODRIGUEZ, R. J. | 8303290344 | 50-312 J |
| RODRIGUEZ, R. J. | 8303290471 | 50-312 P |
| RODRIGUEZ, R. J. | 8303300225 | 50-312 R |
| ROGERS, A. A. | 8303030766* | CONTRACT |
| ROGERS, A. A. | 8303300677* | CONTRACT |
| ROGERS, D. | 8303150396 | 50-128 P |
| ROGERS, H. R. | 8303040438* | 50-328 S |
| ROGERS, H. R. | 8303210321* | 50-328 S |
| ROGERS, H. R. | 8303210469* | 50-327 S |
| ROGERS, H. R. | 8303240479* | 50-328 S |
| ROGERS, P. | 8303030629* | 50-368 S |
| ROGERS, P. | 8303240382* | 50-313 S |
| ROGERS, P. C. | 8303030523* | 50-368 S |
| ROGERS, P. C. | 8303150484* | 50-368 S |
| ROGERS, W. G. | 8303240594* | 50-346 Q |
| ROGERS, W. H. | 8303240119* | 50-321 F |
| ROGERS, W. H. | 8303310180* | 50-321 F |
| ROGGE, J. F. | 8303220063 | 50-395 S |
| ROQUE, F. | 8303290626 | WASTE MGT |
| ROSATGI, U. S. | 8303290786 | RES |
| ROHDE, K. R. | 8303160295* | 50-250 P |
| ROHDE, K. R. | 8303160373* | 50-335 P |
| ROHDE, K. R. | 8303160379* | 50-335 P |
| ROHDE, K. R. | 8303160386* | 50-335 P |
| ROHLFES, G. B. | 8303290532* | CONTRACT |
| ROHRBACHER, R. | 8303250034* | 50-438 Q |
| ROHRER, D. M. | 8303310262* | 50-445 T |
| ROHRER, M. | 8303040549* | 50-416 S |
| ROHRER, M. V. | 8303010185* | 50-416 S |
| ROHRER, M. V. | 8303010218* | 50-416 S |
| ROHRER, M. V. | 8303010233* | 50-416 S |
| ROHRER, M. V. | 8303010349* | 50-416 S |
| ROHRER, M. V. | 8303040363* | 50-416 S |
| ROHRER, M. V. | 8303040425* | 50-416 S |
| ROHRER, M. V. | 8303140565* | 50-416 S |
| ROHRER, M. V. | 8303150586* | 50-416 S |
| ROHRER, M. V. | 8303160440* | 50-416 S |
| ROHRER, M. V. | 8303160455* | 50-416 S |
| ROHRER, M. V. | 8303180033* | 50-416 S |
| ROHRER, M. V. | 8303210545* | 50-416 R |
| ROHRER, M. V. | 8303220275* | 50-416 S |
| ROHRER, M. V. | 8303220352* | 50-416 S |
| ROHRER, M. V. | 8303240434* | 50-416 S |
| ROLLINS, J. D. | 8303290750 | PROJ |
| ROMAN, T. W. | 8303170212* | 50-220 R |
| ROMANO, F. R. | 8303010406 | 50-352 Q |
| ROMO, K. B. | 8303280282 | 50-329 H |
| RONDE, K. R. | 8303160282* | 50-250 P |
| RONDE, K. R. | 8303160304* | 50-250 P |
| ROONEY, V. L. | 8303090245 | 50-271 P |
| ROONEY, V. L. | 8303090420 | 50-271 F |
| ROONEY, V. L. | 8303290543* | 50-325 P |
| ROONEY, V. L. | 8303300241* | 50-259 P |
| ROONEY, V. L. | 8303310089 | COMMISSION |
| ROOT, L. D. | 8303010260 | 50-331 V |
| ROOT, L. D. | 8303010339 | 50-331 P |
| ROOT, L. D. | 8303080332 | 50-331 P |
| ROOT, L. D. | 8303150612* | 50-331 Q |
| ROOT, L. D. | 8303170453 | 50-331 P |
| ROOT, L. D. | 8303210258 | 50-331 P |
| ROOT, L. D. | 8303210432 | 50-331 P |
| ROOT, L. D. | 8303220207 | 50-331 P |
| ROOT, L. D. | 8303240170 | 50-331 F |
| ROOT, L. D. | 8303250015 | 50-331 P |
| ROOT, L. D. | 8303300033* | 50-331 F |
| ROOT, L. D. | 8303300189 | 50-331 P |
| ROOT, R. W. | 8303010617 | 50-460 S |
| ROOT, R. W. | 8303040571 | 50-460 S |
| ROPSON, D. J. | 8303010292* | 50-305 P |
| ROSAL, E. R. | 8303090659 | NUREG |
| ROSENBAUM, P. J. | 8303140119 | FOIA |
| ROSENSTREICH, B. | 8303300067* | CONTRACT |
| ROSENTHAL, A. S. | 8303030367 | PROJ |
| ROSENTRETER, R. | 8303070153* | GA999 |
| ROSOLIE, E. | 8303070119 | 50-508 Q |
| ROSS, D. F. | 8303180107* | WASTE MGT |
| ROSS, F. W. | 8303090012 | 40-8728 |
| ROSS, F. W. | 8303090547 | 40-8714 |
| ROSS, F. W. | 8303180114* | 40-8728 |
| ROSSBACH, L. W. | 8303300126 | WASTE MGT |
| ROSSELLE, C. J. | 8303280223* | 50-413 A |
| ROSSI, C. E. | 8303110227 | 50-322 T |
| ROTH, J. | 8303040537* | 70-135 |
| ROTH, J. | 8303160503* | 70-820 |
| ROTH, J. | 8303210330 | 70-1143 |
| ROTH, J. | 8303240544* | 70-33 |
| ROTHAUG, R. | 8303110262* | 50-389 A |
| ROTHMON, L. B. | 8303040551* | 50-324 P |
| ROTHSCHILD, M. | 8303250125 | 50-445 Q |
| ROTHSCHILD, M. | 8303250148 | 50-445 Q |
| ROTHSCHILD, M. U. | 8303040330 | 50-445 Q |
| ROTHSCHILD, M. U. | 8303040625 | 50-445 Q |
| ROTHSCHILD, M. U. | 8303100141 | 50-445 Q |
| ROTHSCHILD, M. U. | 8303160528 | 50-445 Q |
| ROTHSCHILD, M. U. | 8303170048 | 50-445 Q |
| ROTHSCHILD, M. U. | 8303180358 | 50-445 Q |
| ROTHSCHILD, M. U. | 8303180364 | 50-445 Q |
| ROTHSCHILD, M. U. | 8303220190 | 50-445 Q |
| ROTHSCHILD, M. U. | 8303230043 | 50-445 Q |
| ROTHSCHILD, M. U. | 8303300436 | 50-445 Q |
| ROTHSCHILD, M. U. | 8303310250 | 50-445 Q |
| ROTHSCHILD, M. U. | 8303310290 | 50-445 Q |
| ROUNDTREE, S. L. | 8303230413 | NUREG |
| ROUSE, L. C. | 8208230089* | 70-754 |
| ROUSE, L. C. | 8303100063 | 70-364 |
| ROUSE, L. C. | 8303100064* | 70-364 |
| ROUSE, L. C. | 8303100415 | 70-364 |
| ROUSE, L. C. | 8303100418* | 70-364 |
| ROUSE, L. C. | 8303100419 | 70-754 |
| ROUSE, L. C. | 8303140585 | 70-754 |
| ROUSE, L. C. | 8303150025 | 70-364 |
| ROUSE, L. C. | 8303160702 | 70-1193 |
| ROUSE, L. C. | 8303160704* | 70-1193 |
| ROUSE, L. C. | 8303160707* | 70-1193 |
| ROUSE, L. C. | 8303280315 | 50-280 Y |
| ROWE, C. | 8303030312* | 50-286 Q |
| ROWE, C. | 8303100177* | 50-309 Q |
| ROWE, C. | 8303280214* | 50-245 Q |
| ROWE, C. A. | 8303030166* | 50-272 Q |
| ROWSOME, F. | 8303230233* | 50-247 T |
| ROY, R. | 8303090698* | 50-263 F |
| RUBENSTEIN, L. S. | 8209210510* | 50-373 P |
| RUBENSTEIN, L. S. | 8211170104* | 50-373 P |
| RUBENSTEIN, L. S. | 8302010011* | 50-346 F |
| RUFF, A. B. | 8303010235* | 50-413 Q |
| RUFF, A. B. | 8303010341* | 50-390 Q |
| RUFF, A. B. | 8303210454* | 50-400 Q |
| RUITER, G. H. | 8303080166* | 50-305 R |
| RUITER, G. H. | 8303160358* | 50-305 R |
| RUNKLE, J. | 8303150593 | 50-400 Q |
| RUNKLE, J. D. | 8303150397 | 50-400 Q |
| RUNKLE, J. D. | 8303150400* | 50-400 Q |
| RUNKLE, J. D. | 8303150405* | 50-400 Q |
| RUNKLE, J. D. | 8303150411* | 50-400 Q |
| RUOCCHIO, J. | 8303300458* | CONTRACT |
| RUPPRECHT, S. D. | 8303090659 | NUREG |
| RUSSELL, J. L. | 8303150356* | GA999 |
| RUSSELL, L. B. | 8303010244 | 50-317 S |
| RUSSELL, L. B. | 8303010387 | 50-318 S |
| RUSSELL, L. B. | 8303010521 | 50-318 S |
| RUSSELL, L. B. | 8303030673 | 50-318 S |
| RUSSELL, L. B. | 8303030681* | 50-318 S |
| RUSSELL, L. B. | 8303140194 | 50-317 S |
| RUSSELL, L. B. | 8303140375 | 50-317 S |
| RUSSELL, L. B. | 8303160145 | 50-318 S |
| RUSSELL, L. B. | 8303160176 | 50-318 S |
| RUSSELL, L. B. | 8303160255 | 50-318 S |
| RUSSELL, L. B. | 8303160268 | 50-317 S |
| RUSSELL, L. B. | 8303160312 | 50-318 S |
| RUSSELL, L. B. | 8303160410 | 50-318 S |
| RUSSELL, L. B. | 8303210410 | 50-317 S |
| RUSSELL, L. B. | 8303210570 | 50-318 S |
| RUSSELL, L. B. | 8303210613 | 50-317 S |
| RUSSELL, L. B. | 8303210702 | 50-318 S |
| RUSSELL, W. T. | 8202110128* | 50-206 P |
| RUSTICK, R. | 8303170379* | 50-254 S |
| RUTBERG, J. | 8303140007 | 50-346 M |
| RUTLEDGE, C. | 8303170221 | 40-8502 |
| RUTZ, L. J. | 8108210490* | FOIA |
| RYBAK, B. | 8303030504 | 50-256 Q |
| RYBAK, B. | 8303080247 | 50-237 P |
| RYBAK, B. | 8303080401 | 50-237 P |
| RYBAK, B. | 8303090107* | 50-254 Q |
| RYBAK, B. | 8303150377 | 50-237 P |
| RYBAK, B. | 8303170487 | 50-237 P |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| RYBAK, B. | 8303240184 | 50-237 P |
| RYBAK, B. | 8303240330 | 50-237 Q |
| RYBAK, B. | 8303240355 | 50-254 V |
| RYBAK, B. | 8303310229 | 50-237 Q |
| RYTKONEN, B. B. | 8303030267* | CONTRACT |
| SABADOS, J. W. | 8303010480* | 70-143 |
| SAHA, P. | 8303040186 | RES |
| SAHA, P. | 8303290824 | RES |
| SAHA, P. | 8303300571 | RES |
| SAKOWSKI, P. | 8303070085* | QA999 |
| SALTZMAN, J. | 8303010720 | 70-2949 |
| SALTZMAN, J. | 8303150107 | 50-369 J |
| SALTZMAN, J. | 8303180127 | 70-2946 |
| SANDBERG, S. J. | 8303100460 | NUREG |
| SANDBERG, S. J. | 8303100558 | NUREG |
| SANDERS, M. K. | 8303030520 | MISC |
| SANDERS, W. F. | 8303210589* | 50-424 Q |
| SANDERS, W. F. | 8303210684* | 50-424 Q |
| SANDNER, H. H. | 8303170516* | 50-250 P |
| SANOFF, B. | 8303300303 | 50-247 Q |
| SANOFF, B. | 8303300307* | 50-247 Q |
| SANOFF, B. | 8303300313* | 50-247 Q |
| SANOFF, B. | 8303300319* | 50-247 Q |
| SANOFF, B. | 8303300322* | 50-247 Q |
| SANOFF, B. | 8303300326 | 50-247 Q |
| SANOFF, B. | 8303300374 | 50-247 Q |
| SANOFF, B. L. | 8303100238 | 50-247 Q |
| SANTORO, M. P. | 8303140649 | 71-9006 |
| SANTORO, M. P. | 8303290022 | 71-9006 |
| SANTORO, M. P. | 8303290026* | 71-9006 |
| SARSOUR, B. | 8303080170* | 50-346 R |
| SARSOUR, B. | 8303150504* | 50-346 R |
| SARSTEN, G. E. | 8303140607 | 50-443 S |
| SASTRE, C. | 8303040170 | RES |
| SASTRE, C. | 8303290804 | RES |
| SATHER, A. | 8303170436* | 50-329 Q |
| SAVAGE, A. | 8303230248* | 50-329 T |
| SAVOLAINEN, A. W. | 8303290050 | WASTE MGT |
| SAVOLAINEN, A. W. | 8303300210 | WASTE MGT |
| SAWOSKA, H. J. | 8303030342* | CONTRACT |
| SAYER, J. | 8303290137* | 50-298 F |
| SCALETTI, D. C. | 8303030767 | 50-447 A |
| SCARANO, R. A. | 8303020200 | 27-48 |
| SCARANO, R. A. | 8303100473* | FOIA |
| SCARANO, R. A. | 8303160102* | 27-39 |
| SCARANO, R. A. | 8303180577 | WASTE MGT |
| SCHAKEN, J. F. | 8303110301* | 50-282 Q |
| SCHAPKER, J. F. | 8303010341* | 50-390 Q |
| SCHARF, L. | 8303020130* | 50-247 T |
| SCHAUER, F. P. | 8201220333* | 50-206 P |
| SCHAUER, F. P. | 8302040612* | 50-206 P |
| SCHAUER, F. P. | 8303020157* | FOIA |
| SCHAUFELBERGER | 8303150212 | 50-298 Q |
| SCHERER, A. E. | 8303010518 | TOPREP |
| SCHERER, A. E. | 8303030419 | 50-470 A |
| SCHERER, A. E. | 8303030423 | 50-470 A |
| SCHERER, A. E. | 8303030647 | 50-470 E |
| SCHERER, A. E. | 8303040467 | 50-470 A |
| SCHERER, A. E. | 8303080226 | 50-470 A |
| SCHERER, A. E. | 8303080406 | 50-470 E |
| SCHERER, A. E. | 8303090351 | 50-470 A |
| SCHERER, A. E. | 8303150209 | 50-470 E |
| SCHERER, A. E. | 8303220159 | TOPREP |
| SCHERER, A. E. | 8303230151 | XPORTLIC |
| SCHERER, A. E. | 8303240261 | 50-470 A |
| SCHERER, A. E. | 8303290358 | TOPREP |
| SCHIERLING, H. | 8303040651* | 50-275 P |
| SCHIMA, F. J. | 8303100424 | NUREG |
| SCHLAU, P. | 8303080506* | 50-333 S |
| SCHMIDT, H. C. | 8303010642 | 50-445 A |
| SCHMIDT, H. C. | 8303030018 | 50-445 A |
| SCHMIDT, H. C. | 8303090167 | 50-445 Q |
| SCHMIDT, H. C. | 8303110215 | 50-445 A |
| SCHMIDT, H. C. | 8303140340 | 50-445 A |
| SCHMIDT, H. C. | 8303220188 | 50-445 F |
| SCHMIDT, H. C. | 8303220387 | 50-445 F |
| SCHMITENDORF, G. | 8303080379* | 50-338 R |
| SCHMITENDORF, G. | 8303150441* | 50-338 R |
| SCHMITENDORF, G. | 8303150447* | 50-338 R |
| SCHMITT, R. C. | 8303140617 | NUREG |
| SCHMULT, B. | 8303020266 | NUREG |
| SCHNEIDER, K. N. | 8303180501 | WASTE MGT |
| SCHNEIDER, K. N. | 8303290014 | WASTE MGT |
| SCHNELL, D. F. | 8303030453* | 50-483 Q |
| SCHNELL, D. F. | 8303030521* | 70-2945 |
| SCHNELL, D. F. | 8303150299 | 50-483 K |
| SCHNELL, D. F. | 8303220309 | 50-483 S |
| SCHNELL, D. F. | 8303240213* | 50-483 Q |
| SCHNELL, D. F. | 8303290351 | 50-483 A |
| SCHORTMAN, E. M. | 8303010447* | 50-352 A |
| SCHOSSLER, M. | 8303010104 | 50-440 Q |
| SCHREIBER, R. E. | 8303090510 | NUREG |
| SCHROCK, C. A. | 8303010292* | 50-305 P |
| SCHROEDER, C. | 8303100350 | 50-237 P |
| SCHROEDER, C. | 8303150617 | 50-237 S |
| SCHROEDER, C. W. | 8303020004 | 50-373 P |
| SCHROEDER, C. W. | 8303020012 | 50-373 P |
| SCHROEDER, C. W. | 8303020074 | 50-373 Q |
| SCHROEDER, C. W. | 8303040491 | 50-373 P |
| SCHROEDER, C. W. | 8303080470 | 50-373 P |
| SCHROEDER, C. W. | 8303100313 | 50-454 F |
| SCHROEDER, C. W. | 8303110314 | 50-373 P |
| SCHROEDER, C. W. | 8303140365 | 50-374 S |
| SCHROEDER, C. W. | 8303150326 | 50-454 F |
| SCHROEDER, C. W. | 8303170307 | 50-373 P |
| SCHROEDER, C. W. | 8303180489 | 50-373 P |
| SCHROEDER, C. W. | 8303220056 | 50-374 S |
| SCHROEDER, C. W. | 8303220145 | 50-374 S |
| SCHROEDER, C. W. | 8303220165 | 50-373 P |
| SCHROEDER, C. W. | 8303290269 | 50-374 A |
| SCHROEDER, D. W. | 8303160417* | 50-324 P |
| SCHROEDER, R. A. | 8303110248* | 50-10 R |
| SCHULTZ, C. | 8303170502* | 50-295 S |
| SCHULZ, R. D. | 8303150600* | 50-410 Q |
| SCHUM, W. S. | 8303210529* | 50-482 Q |
| SCHUMACHER, M. S. | 8303240597* | 50-10 Q |
| SCHUYLER, J. O. | 8303210254 | 50-275 F |
| SCHUYLER, J. O. | 8303290315 | 50-275 P |
| SCHWARTZ, F. W. | 8303150130 | NUREG |
| SCHWARTZ, S. A. | 8303100178* | 50-247 T |
| SCHWENCER, A. | 8303010290 | 50-352 F |
| SCHWENCER, A. | 8303020454 | 50-387 P |
| SCHWENCER, A. | 8303020460 | 50-387 P |
| SCHWENCER, A. | 8303020461* | 50-387 P |
| SCHWENCER, A. | 8303020468* | 50-387 P |
| SCHWENCER, A. | 8303030115 | 50-352 A |
| SCHWENCER, A. | 8303030215 | 50-416 P |
| SCHWENCER, A. | 8303030384 | 50-416 P |
| SCHWENCER, A. | 8303090700 | 50-387 P |
| SCHWENCER, A. | 8303110552 | 50-352 M |
| SCHWENCER, A. | 8303110556* | 50-352 M |
| SCHWENCER, A. | 8303140600 | 50-461 E |
| SCHWENCER, A. | 8303160033 | 50-397 F |
| SCHWENCER, A. | 8303160072 | 50-352 A |
| SCHWENCER, A. | 8303170209 | 50-373 F |
| SCHWENCER, A. | 8303180198* | 50-387 P |
| SCHWENCER, A. | 8303180446 | 50-410 A |
| SCHWENCER, A. | 8303180539 | 50-458 E |
| SCHWENCER, A. | 8303180609 | 50-373 P |
| SCHWENCER, A. | 8303180630 | 50-458 E |
| SCHWENCER, A. | 8303210017 | 50-397 A |
| SCHWENCER, A. | 8303230091 | 50-352 E |
| SCHWENCER, A. | 8303230097 | 50-387 P |
| SCHWENCER, A. | 8303280099 | 50-461 A |
| SCHWENCER, A. | 8303290687 | 50-322 A |
| SCHWENCER, A. | 8303290748 | 50-373 P |
| SCHWENCER, A. | 8303290753 | 50-416 R |
| SCHWENCER, A. | 8303300262 | 50-397 E |
| SCHWENCER, A. | 8303310679 | 50-458 A |
| SCHWINK, W. | 8303110004 | REVIEW GRP |
| SCOTT, D. | 8303010590* | 50-416 Q |
| SCOTT, D. E. | 8303210752* | 50-416 Q |
| SCOTT, D. J. | 8302280475 | 50-249 S |
| SCOTT, D. J. | 8303080090 | 50-237 S |
| SCOTT, D. J. | 8303080093 | 50-249 S |
| SCOTT, D. J. | 8303080138 | 50-249 S |
| SCOTT, D. J. | 8303080316 | 50-237 S |
| SCOTT, D. J. | 8303110241 | 50-10 R |
| SCOTT, D. J. | 8303150389 | 50-249 S |
| SCOTT, D. J. | 8303150611 | 50-237 S |
| SCOTT, D. J. | 8303170322 | 50-237 S |
| SCOTT, D. J. | 8303220093 | 50-249 S |
| SCOTT, D. J. | 8303230149* | 50-10 F |
| SCOTT, D. J. | 8303240388 | 50-237 S |
| SCOTT, D. J. | 8303290284 | 50-237 S |
| SCOTT, R. S. | 8303160730 | 50-272 S |
| SCOVILLE, J. J. | 8303170003 | 27-48 |
| SCOVILLE, J. J. | 8303180052 | 27-48 |
| SCURRY, N. | 8303020125 | ORG |
| SCURRY, N. | 8303020131 | ORG |
| SCURRY, N. | 8303020137 | ORG |
| SCURRY, N. | 8303160022 | ORG |
| SEARS, C. F. | 8303040487 | 50-423 C |
| SEARS, C. F. | 8303040487 | 50-423 C |
| SEARS, C. F. | 8303080208 | 50-245 R |
| SEARS, C. F. | 8303080208 | 50-245 R |
| SEARS, C. F. | 8303090240* | 50-213 F |
| SEARS, C. F. | 8303110107 | 71-4986 |
| SEARS, C. F. | 8303110107 | 71-4986 |
| SEARS, C. F. | 8303110313 | 50-336 P |
| SEARS, C. F. | 8303110313 | 50-336 P |
| SEARS, C. F. | 8303180405 | 50-213 P |
| SEELEY, G. T. | 8303100082* | 50-265 P |
| SEELIG, C. A. | 8303100442* | FOIA |
| SEIDLE, W. C. | 8303010223 | 50-285 Q |
| SEIDLE, W. C. | 8303010237 | 50-313 Q |
| SEIDLE, W. C. | 8303010509 | 50-368 Q |
| SEIDLE, W. C. | 8303010682 | 50-313 Q |
| SEIDLE, W. C. | 8303090583* | 50-313 F |
| SEIDLE, W. C. | 8303180221 | 50-285 Q |
| SEIDLE, W. C. | 8303180224 | 50-285 Q |
| SEIDLE, W. C. | 8303180353 | 50-482 Q |
| SEIDLE, W. C. | 8303180430 | 50-313 Q |
| SEIDLE, W. C. | 8303210513 | 50-482 Q |
| SEIDLE, W. C. | 8303210547 | 50-313 Q |
| SEIDLE, W. C. | 8303210565 | 50-482 Q |
| SEIDLE, W. C. | 8303210669 | 50-482 Q |
| SEIDLE, W. C. | 8303210673 | 50-285 Q |
| SEIDLE, W. C. | 8303240469 | 50-313 Q |
| SEIDLE, W. C. | 8303250002 | 50-285 Q |
| SEIDLE, W. C. | 8303290224 | 50-285 F |
| SEIDLE, W. C. | 8303290252 | 50-313 F |
| SEIDMAN, H. S. | 8303100397 | 50-440 Q |
| SEIGERMAN, V. K. | 8303090287 | 50-247 Q |
| SEIGERMAN, V. K. | 8303090293 | 50-247 Q |
| SEIKEN, S. J. | 8303150390 | 50-482 S |
| SEIKEN, S. J. | 8303280022 | 50-482 A |
| SEIKEN, S. J. | 8303290394 | 50-482 S |
| SELBY, J. P. | 8303210286* | 50-155 I |
| SELLS, D. E. | 8303140090 | 50-335 P |
| SELLS, D. E. | 8303150029 | 50-335 P |
| SELTZER, S. | 8303100424 | NUREG |
| SEMMEL, H. | 8303010073 | 50-155 Q |
| SEMMEL, H. | 8303010073 | 50-155 Q |
| SEMMEL, H. | 8303220290 | 50-155 Q |
| SEMMEL, H. | 8303220290 | 50-155 Q |
| SERINI, B. L. | 8303180136* | 70-2946 |
| SERKIZ, A. W. | 8303140420* | 50-329 T |
| SERNE, R. J. | 8303160611 | NUREG |
| SESTAK, F. | 8303080290 | 50-275 P |
| SESTAK, F. | 8303080285* | 50-275 P |
| SESTAK, F. | 8303090112* | 50-275 P |
| SESTAK, F. | 8303220067 | 50-275 R |
| SESTAK, F. | 8303230054 | 50-275 R |
| SESTAK, F. | 8303230059* | 50-275 R |
| SETH, B. B. | 8303010287 | MISC |
| SETYOKO, R. | 8303170675 | XPORTLIC |
| SEWELL, S. K. | 8303150480* | 50-321 R |
| SEWELL, S. K. | 8303160588* | 50-321 R |
| SEYFRIT, K. V. | 8303110132* | FOIA |
| SHA, W. T. | 8303140617 | NUREG |
| SHACK, W. J. | 8303150615 | RES |
| SHACKLETON, O. C. | 8303100041* | 50-206 Q |
| SHACKLETON, O. C. | 8303100045* | 50-206 Q |
| SHACKLETON, O. C. | 8303100067* | 50-206 Q |
| SHACKLETON, O. C. | 8303110250* | 50-528 Q |
| SHAFER, W. D. | 8303010545 | 50-329 A |
| SHAFER, W. D. | 8303110366* | 50-329 Q |
| SHAFER, W. D. | 8303170436* | 50-329 Q |
| SHAFER, W. D. | 8303220076 | 50-329 A |
| SHAFFER, D. H. | 8303010287 | MISC |
| SHAFFER, H. C. | 8303310646* | CONTRACT |
| SHAFFER, J. F. | 8303080504* | 50-358 R |
| SHAFFNER, J. A. | 8303160099 | 27-39 |
| SHAFFNER, J. A. | 8303160102* | 27-39 |
| SHAH, V. N. | 8303280329 | RES |
| SHANBAKY, M. | 8303030166* | 50-272 Q |
| SHANBAKY, M. | 8303030202* | 50-334 Q |
| SHANBAKY, M. | 8303030312* | 50-286 Q |
| SHANBAKY, M. | 8303100177* | 50-309 Q |
| SHANBAKY, M. | 8303140229* | 50-213 Q |
| SHANBAKY, M. | 8303160570* | 50-317 Q |
| SHANBAKY, M. | 8303240449* | 50-213 Q |
| SHANBAKY, M. | 8303240535* | 50-272 Q |
| SHANBAKY, M. | 8303280214* | 50-245 Q |

# PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| SHANBAKY, M. | 8303300455* | 50-247 G |
| SHANBAKY, M. M. | 8303010440* | 50-219 G |
| SHANBAKY, M. M. | 8303100305* | 50-293 G |
| SHANBAKY, M. M. | 8303160508* | 50-333 G |
| SHANBAKY, M. M. | 8303290319* | 50-334 G |
| SHANK, K. E. | 8303140485* | 50-387 R |
| SHANNON, J. B. | 8303160664 | 40-8064 |
| SHAPIRO, R. | 8303220241 | 50-322 G |
| SHAPIRO, R. | 8303220241 | 50-322 G |
| SHARMA, D. | 8303180180* | 40-4492 |
| SHARP, D. A. | 8303110597 | RES |
| SHARP, J. | 8303020366 | 71-6717 |
| SHARP, R. A. | 8303100051* | FOIA |
| SHAUB, E. T. | 8303240373* | 50-213 G |
| SHAVER, L. | 8303090526* | 50-320 F |
| SHAVER, L. | 8303290624* | 50-320 F |
| SHAW, A. | 8303030310 | 71-6642 |
| SHAW, A. | 8303110072 | 70-2322 |
| SHAW, A. | 8303230366* | XPORTLIC |
| SHAW, A. | 8303290173* | XPORTLIC |
| SHEA, J. J. | 8303100354 | TOPREP |
| SHEA, J. J. | 8303310089 | COMMISSION |
| SHEA, K. H. | 8303230031 | 50-331 J |
| SHEALY, H. G. | 8303180584* | WASTE MGT |
| SHEDLOSKY, J. T. | 8303030184* | 50-245 G |
| SHEDLOSKY, J. T. | 8303030201* | 50-245 G |
| SHEDLOSKY, J. T. | 8303300475* | 50-245 G |
| SHELLEY, W. J. | 8303020087 | REGGD |
| SHELLEY, W. J. | 8303090075 | 40-8768 |
| SHELLEY, W. J. | 8303110041 | 40-8768 |
| SHELLEY, W. J. | 8303110444 | 40-2061 |
| SHELLEY, W. J. | 8303180669* | 40-8027 |
| SHELLEY, W. J. | 8303210082 | 40-8027 |
| SHELLEY, W. J. | 8303220375 | 40-2061 |
| SHELLEY, W. J. | 8303220442* | 40-2061 |
| SHELLEY, W. J. | 8303220452 | 40-8027 |
| SHEMANSKI, P. | 8303300591* | 50-338 P |
| SHEPARD, A. M. | 8303150518* | 50-29 P |
| SHEPHERD, R. E. | 8303040473* | 50-245 G |
| SHEPHERD, R. E. | 8303110031* | 50-272 G |
| SHEPPARD, J. J. | 8303090378 | TOPREP |
| SHEPPARD, J. J. | 8303090379 | TOPREP |
| SHEPPARD, J. J. | 8303150642* | 50-272 S |
| SHEPPARD, J. J. | 8303150642* | 50-272 S |
| SHEPPARD, J. J. | 8303290355 | TOPREP |
| SHEPPARD, J. J. | 8303290355 | TOPREP |
| SHEPPARD, J. J. | 8303300221 | TOPREP |
| SHEPPARD, J. J. | 8303300221 | TOPREP |
| SHERMAN, C. | 8303180407* | 50-312 G |
| SHERMAN, C. I. | 8303290468* | 50-206 G |
| SHERON, B. W. | 8303210033* | 50-289 P |
| SHERWOOD, D. R. | 8303160611 | NUREG |
| SHERWOOD, G. G. | 8302040379 | 50-447 B |
| SHERWOOD, G. G. | 8302040383* | 50-447 B |
| SHERWOOD, G. G. | 8303070062 | 50-447 A |
| SHERWOOD, G. G. | 8303070127 | 50-447 A |
| SHERWOOD, G. G. | 8303110294 | 50-447 E |
| SHERWOOD, G. G. | 8303140179 | 50-447 A |
| SHERWOOD, G. G. | 8303150541 | 50-447 A |
| SHERWOOD, G. G. | 8303170291 | 50-447 A |
| SHERWOOD, G. G. | 8303180017 | 50-447 A |
| SHERWOOD, G. G. | 8303210290 | 50-447 A |
| SHERWOOD, G. G. | 8303229138 | 50-447 A |
| SHERWOOD, G. G. | 8303290360 | 50-447 A |
| SHERWOOD, G. G. | 8303310277 | 50-447 A |
| SHEWMON, P. | 8212130273* | ACRS |
| SHEWMON, P. | 8212290054* | ACRS |
| SHEWMON, P. | 8212290059* | ACRS |
| SHEWMON, P. | 8212290471* | ACRS |
| SHEWSKI | 8303300457* | 50-454 T |
| SHEWSKI, W. J. | 8303080481 | 50-454 T |
| SHEWSKI, W. J. | 8303110279* | 50-10 P |
| SHIAO, S. Y. | 8303170624 | NUREG |
| SHIELDS, S. W. | 8302100345 | PRM |
| SHIELDS, S. W. | 8302280121 | 50-546 A |
| SHIELDS, S. W. | 8302280121 | 50-546 A |
| SHIELDS, S. W. | 8303150123 | 50-546 S |
| SHIELDS, S. W. | 8303150286 | 50-546 S |
| SHIELDS, S. W. | 8303170409 | 50-546 V |
| SHIELDS, S. W. | 8303220020 | 50-546 S |
| SHIELDS, S. W. | 8303220259 | 50-546 A |
| SHIELDS, S. W. | 8303280096 | 50-546 A |
| SHIER, W. G. | 8303300642 | RES |
| SHIFFER, J. D. | 8303010625 | 50-275 S |
| SHIM, K. | 8303140563* | 50-304 S |
| SHIM, K. | 8303140595* | 50-304 S |
| SHIMA, S. | 8303230077 | XPORTLIC |
| SHIMA, S. | 8303230082* | XPORTLIC |
| SHINGLETON, B. | 8303010185* | 50-416 S |
| SHINGLETON, B. | 8303010201* | 50-416 S |
| SHINGLETON, B. | 8303010218* | 50-416 S |
| SHINGLETON, B. | 8303010233* | 50-416 S |
| SHINGLETON, B. | 8303010349* | 50-416 S |
| SHINGLETON, B. | 8303040425* | 50-416 S |
| SHINGLETON, B. | 8303040504* | 50-416 S |
| SHINGLETON, B. | 8303040508* | 50-416 S |
| SHINGLETON, B. | 8303040549* | 50-416 S |
| SHINGLETON, B. | 8303040626* | 50-416 S |
| SHINGLETON, B. | 8303140389* | 50-416 S |
| SHINGLETON, B. | 8303140565* | 50-416 S |
| SHINGLETON, B. | 8303150183* | 50-416 S |
| SHINGLETON, B. | 8303150254* | 50-416 S |
| SHINGLETON, B. | 8303150448* | 50-416 S |
| SHINGLETON, B. | 8303150585* | 50-416 S |
| SHINGLETON, B. | 8303160400* | 50-416 S |
| SHINGLETON, B. | 8303160455* | 50-416 S |
| SHINGLETON, B. | 8303160460* | 50-416 S |
| SHINGLETON, B. | 8303160549* | 50-416 S |
| SHINGLETON, B. | 8303180033* | 50-416 S |
| SHINGLETON, B. | 8303180254* | 50-416 S |
| SHINGLETON, B. | 8303180369* | 50-416 S |
| SHINGLETON, B. | 8303210545* | 50-416 S |
| SHINGLETON, B. | 8303240434* | 50-416 S |
| SHINGLETON, E. B. | 8303040325* | 50-416 S |
| SHINGLETON, E. B. | 8303140404* | 50-416 S |
| SHINGLETON, E. B. | 8303220275* | 50-416 S |
| SHIRAKAWA, T. | 8303020312 | XPORTLIC |
| SHIRAKAWA, T. | 8303280106 | XPORTLIC |
| SHIRAKAWA, T. | 8303280109 | XPORTLIC |
| SHIRAKAWA, T. | 8303290150 | XPORTLIC |
| SHIRAKAWA, T. | 8303290168 | XPORTLIC |
| SHIU, K. | 8303140664 | 50-352 A |
| SHIVELY, C. | 8303090239 | 50-368 P |
| SHIVELY, C. | 8303220034 | 50-313 P |
| SHOEMAKER, C. J. | 8303020080 | 50-289 G |
| SHOEMAKER, C. J. | 8303030447 | 50-445 G |
| SHOEMAKER, C. J. | 8303080149 | 50-361 G |
| SHOEMAKER, C. J. | 8303080427 | 50-289 G |
| SHOEMAKER, C. J. | 8303140272 | 50-352 G |
| SHOEMAKER, C. J. | 8303140277 | 50-437 G |
| SHOEMAKER, C. J. | 8303170435 | 50-397 G |
| SHOEMAKER, C. J. | 8303170458 | 50-289 G |
| SHOEMAKER, C. J. | 8303240383 | 50-266 G |
| SHOEMAKER, C. J. | 8303240400 | 50-266 G |
| SHOEMAKER, C. J. | 8303240554 | 50-155 G |
| SHOEMAKER, C. J. | 8303240593 | 50-70 G |
| SHOEMAKER, C. J. | 8303290505 | 50-352 G |
| SHOEMAKER, C. J. | 8303310307 | 50-341 G |
| SHOLLY, S. C. | 8303240545 | 50-247 T |
| SHOLLY, S. C. | 8303240545 | 50-247 T |
| SHON, F. J. | 8303170503 | 50-320 G |
| SHOPENN, N. M. | 8303180243* | 40-6659 |
| SHOTWELL, J. A. | 8303240430 | 50-443 G |
| SHOUP, R. W. | 8303100460 | NUREG |
| SHOUP, R. W. | 8303100558 | NUREG |
| SHREVE, D. B. | 8303230430* | 50-247 F |
| SHYMLOCK, M. B. | 8303010465* | 50-338 G |
| SIEBER, J. D. | 8303310497* | 50-334 F |
| SIEFKEN, D. L. | 8303180588 | 27-39 |
| SIEGEL, A. I. | 8303300651 | NUREG |
| SIEGEL, B. L. | 8303310089 | COMMISSION |
| SIEGEL, M. | 8303290570* | WASTE MGT |
| SILBERG, J. E. | 8303110204 | 50-440 G |
| SILBERG, J. E. | 8303110204 | 50-440 G |
| SILBERG, J. E. | 8303170505 | 50-440 G |
| SILBERG, J. E. | 8303170505 | 50-440 G |
| SILVIS, R. M. | 8303030047 | 50-320 P |
| SILVIS, R. M. | 8303030763 | CONTRACT |
| SILVIS, R. M. | 8303100117 | CONTRACT |
| SILVIS, R. M. | 8303290204 | CONTRACT |
| SIMAN-TOV, M. | 8303010687 | RES |
| SIMAN-TOV, M. | 8303300632 | RES |
| SIMIU, E. | 8303230158* | CONTRACT |
| SIMON, J. A. | 8303170436* | 50-329 G |
| SIMONIS, J. C. | 8303290613* | TOPREP |
| SIMPKIN, D. J. | 8201200538* | FOIA |
| SIMPSON, A. K. | 8303160721* | COMMISSION |
| SINCLAIR, J. B. | 8303140503 | 50-271 R |
| SINCLAIR, J. B. | 8303150292 | 50-271 P |
| SINCLAIR, J. B. | 8303160167 | 50-271 G |
| SINCLAIR, J. B. | 8303180294 | 50-271 R |
| SINCLAIR, J. B. | 8303210129 | 50-271 F |
| SINCLAIR, J. B. | 8303240336 | 50-271 R |
| SINCLAIR, J. B. | 8303290019 | 50-271 P |
| SINCLAIR, J. B. | 8303300259 | 50-271 F |
| SINCLAIR, M. | 8303230243 | 50-329 T |
| SINCLAIR, W. K. | 8303020078 | PR |
| SINGER, G. L. | 8303180699 | RES |
| SINGER, R. K. | 8303010177 | 50-556 G |
| SINGH, B. K. | 8303020062* | 50-321 F |
| SINGH, K. P. | 8303290001 | 70-2926 |
| SINISI, J. M. | 8303080198 | 50-293 J |
| SINISI, J. M. | 8303140231 | 50-245 J |
| SINISI, J. M. | 8303140244 | 50-245 J |
| SINISI, J. M. | 8303140256 | 50-244 J |
| SINISI, J. M. | 8303140289 | 50-293 J |
| SINISI, J. M. | 8303140290 | 50-29 J |
| SINKIN, L. | 8303230224 | 50-498 G |
| SINNREICH, J. | 8303090353 | FOIA |
| SINWELL, B. R. | 8303090659 | NUREG |
| SKALA, J. J. | 8303090273 | 50-454 T |
| SKARDHAMAR, T. | 8303160418* | 50-324 P |
| SKARUPA, J. D. | 8303230004 | XPORTLIC |
| SKARUPA, J. D. | 8303230347 | XPORTLIC |
| SKARUPA, J. D. | 8303290048 | XPORTLIC |
| SKARUPA, J. D. | 8303300714 | XPORTLIC |
| SKARUPA, J. D. | 8303300716 | XPORTLIC |
| SKARUPA, J. D. | 8303310614 | XPORTLIC |
| SKELLY, T. M. | 8303310230* | 50-237 G |
| SKLINSKI, H. | 8303020222* | 70-364 |
| SKOGG, E. E. | 8303040555* | 50-293 P |
| SKOLDS, J. L. | 8303210745* | 50-395 G |
| SLAGGIE, E. L. | 8208270667* | 50-361 P |
| SLOVIK, G. | 8303300571 | RES |
| SMART, T. L. | 8303310105* | 50-445 F |
| SMITH, A. L. | 8303010498* | GA999 |
| SMITH, A. L. | 8303070126* | GA999 |
| SMITH, C. N. | 8303150144 | 70-824 |
| SMITH, C. N. | 8303160621 | 70-27 |
| SMITH, D. L. | 8303080250 | 50-454 T |
| SMITH, D. L. | 8303080250 | 50-454 T |
| SMITH, G. | 8303160482* | 50-289 G |
| SMITH, G. | 8303240568* | 50-333 G |
| SMITH, G. C. | 8303030206* | 50-320 G |
| SMITH, G. C. | 8303240544* | 70-33 |
| SMITH, G. C. | 8303290331* | 50-184 G |
| SMITH, G. C. | 8303290381* | 50-77 G |
| SMITH, G. C. | 8303300392* | 50-170 G |
| SMITH, H. D. | 8303180011 | State Prog |
| SMITH, H. I. | 8303310089 | COMMISSION |
| SMITH, I. W. | 8303230264 | 50-454 G |
| SMITH, J. F. | 8303290567* | 50-237 P |
| SMITH, J. L. | 8302010100 | 50-322 A |
| SMITH, J. L. | 8303030160 | 50-322 A |
| SMITH, J. L. | 8303100245 | 50-322 F |
| SMITH, J. L. | 8303210153 | 50-322 A |
| SMITH, J. L. | 8303210161 | 50-322 G |
| SMITH, J. L. | 8303210167 | 50-322 V |
| SMITH, J. L. | 8303210173 | 50-322 A |
| SMITH, J. L. | 8303230065 | 50-322 A |
| SMITH, J. L. | 8303280005 | 50-322 F |
| SMITH, J. L. | 8303300218 | 50-322 A |
| SMITH, J. L. | 8303300238 | 50-322 A |
| SMITH, L. C. | 8303110324* | 50-244 P |
| SMITH, M. | 8303300431* | 50-454 T |
| SMITH, M. | 8303300431* | 50-454 T |
| SMITH, M. | 8303300431* | 50-454 T |
| SMITH, M. A. | 8303230133 | 40-8064 |
| SMITH, M. J. | 8303140314* | 50-295 G |
| SMITH, P. A. | 8303030511 | CONTRACT |
| SMITH, P. A. | 8303030513* | CONTRACT |
| SMITH, P. A. | 8303030718* | CONTRACT |
| SMITH, P. A. | 8303090433* | CONTRACT |
| SMITH, P. A. | 8303100042* | FOIA |
| SMITH, P. A. | 8303100051* | FOIA |
| SMITH, P. A. | 8303100055* | FOIA |
| SMITH, P. A. | 8303150171* | CONTRACT |
| SMITH, P. A. | 8303150360* | CONTRACT |
| SMITH, P. A. | 8303160071* | CONTRACT |
| SMITH, P. A. | 8303180062* | CONTRACT |
| SMITH, P. A. | 8303230135* | CONTRACT |
| SMITH, P. A. | 8303230380* | CONTRACT |
| SMITH, P. A. | 8303280013* | CONTRACT |
| SMITH, P. A. | 8303290138* | CONTRACT |
| SMITH, P. A. | 8303290819* | CONTRACT |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| SMITH, P. A. | 8303300439 | CONTRACT |
| SMITH, P. A. | 8303300449* | CONTRACT |
| SMITH, P. A. | 8303300454 | CONTRACT |
| SMITH, P. A. | 8303300458* | CONTRACT |
| SMITH, P. A. | 8303310598 | CONTRACT |
| SMITH, P. A. | 8303310602* | CONTRACT |
| SMITH, R. | 8303090675 | 71-7033 |
| SMITH, R. B. | 8303040606* | QA 999 |
| SMITH, R. D. | 8303180055 | 40-1341 |
| SMITH, R. D. | 8303180060 | 40-8745 |
| SMITH, R. D. | 8303180097 | 40-3453 |
| SMITH, R. D. | 8303180110 | 40-8728 |
| SMITH, R. D. | 8303180147 | WASTE MGT |
| SMITH, R. H. | 8303240442* | 50-334 G |
| SMITH, R. I. | 8303150680 | NUREG |
| SMITH, R. I. | 8303170169* | 50-171 I |
| SMITH, W. | 8303230271* | 50-461 I |
| SMITH, W. G. | 8303080079 | 50-315 S |
| SMITH, W. G. | 8303080105 | 50-315 S |
| SMITH, W. G. | 8303080268 | 50-316 R |
| SMITH, W. G. | 8303080331 | 50-315 S |
| SMITH, W. G. | 8303080375 | 50-315 S |
| SMITH, W. G. | 8303080423 | 50-315 R |
| SMITH, W. G. | 8303080436 | 50-316 S |
| SMITH, W. G. | 8303080507 | 50-316 S |
| SMITH, W. G. | 8303140373 | 50-315 S |
| SMITH, W. G. | 8303140518 | 50-316 S |
| SMITH, W. G. | 8303140603 | 50-315 S |
| SMITH, W. G. | 8303150510 | 50-315 R |
| SMITH, W. G. | 8303150537 | 50-316 R |
| SMITH, W. G. | 8303210416 | 50-316 S |
| SMITH, W. G. | 8303220102 | 50-315 S |
| SMITH, W. G. | 8303240401 | 50-316 S |
| SMITH, W. G. | 8303290386 | 50-315 S |
| SMITHWICK, T. S. | 8303020049* | 50-124 R |
| SMYTH, C. W. | 8303220033* | 50-289 R |
| SMYTH, D. V. | 8303310588 | XPORTLIC |
| SMYTH, D. V. | 8303310592* | XPORTLIC |
| SNELL, W. G. | 8303240259* | 50-266 G |
| SNOW, B. A. | 8303080213 | 50-244 R |
| SNOW, B. A. | 8303150516 | 50-244 R |
| SNYDER, B. J. | 8303160037 | 50-320 P |
| SNYDER, H. L. | 8303090622 | 40-8584 |
| SNYDER, H. L. | 8303220469 | 40-8584 |
| SNYDER, H. L. | 8303230125 | 40-8584 |
| SNYDER, H. L. | 8303240059 | 40-8584 |
| SOARES, C. | 8303100424 | NUREG |
| SOBEL, C. P. | 8303160209* | 50-219 S |
| SOLLENBERGER, D. | 8303090044 | 40-2259 |
| SOLLENBERGER, D. | 8303180132 | 40-8452 |
| SOLLENBERGER, D. | 8303230441 | 40-2259 |
| SOLOMON, A. A. | 8303210147 | ACRS |
| SOMERVILLE, H. G. | 8303100040 | 40-8783 |
| SOMMERS, D. | 8303030413* | 50-329 T |
| SOMSAG, M. L. | 8303080069 | 50-454 T |
| SONIN, A. A. | 8303300421 | RES |
| SONN, H. W. | 8303170169* | 50-171 I |
| SOO, P. | 8303090564 | RES |
| SOONG, A. L. | 8303290777* | 70-1100 |
| SOWDON, T. L. | 8303290478* | 50-293 R |
| SPARKS, J. G. | 8303180308* | 50-320 P |
| SPEER, M. | 8303150591* | 50-206 R |
| SPEIGHT, C. W. | 8303020123 | 70-1201 |
| SPEIGHT, C. W. | 8303150007 | 70-1201 |
| SPEIGHT, C. W. | 8303150014* | 70-1201 |
| SPEIS, T. P. | 8303160705* | 50-352 E |
| SPENCER, D. | 8303080075* | 50-373 S |
| SPENCER, D. | 8303080244* | 50-373 S |
| SPENCER, D. | 8303140437* | 50-373 S |
| SPENCER, D. | 8303140486* | 50-373 S |
| SPENCER, D. | 8303170481* | 50-373 S |
| SPENCER, D. | 8303210441* | 50-373 S |
| SPENCER, G. | 8303110166* | 50-206 G |
| SPENCER, G. S. | 8303110153* | FOIA |
| SPESSARD, R. L. | 8302280356 | 50-295 G |
| SPESSARD, R. L. | 8303140249 | 50-456 G |
| SPESSARD, R. L. | 8303140381 | 50-373 G |
| SPESSARD, R. L. | 8303140411* | 50-373 G |
| SPESSARD, R. L. | 8303210269 | 50-155 G |
| SPESSARD, R. L. | 8303210282* | 50-329 A |
| SPESSARD, R. L. | 8303210293 | 50-454 G |
| SPESSARD, R. L. | 8303240597* | 50-10 G |
| SPESSARD, R. L. | 8303240602 | 50-254 G |
| SPESSARD, R. L. | 8303280289 | 50-454 G |
| SPESSARD, R. L. | 8303290402 | 50-409 P |
| SPIEGEL, L. | 8303020120* | 50-247 T |
| SPITZBERG, D. B. | 8303180237* | 40-8752 |
| SRENIAWSKI, D. J. | 8303010319 | 70-1507 |
| SRENIAWSKI, D. J. | 8303010325* | 70-1507 |
| SRINIVASAN, M. | 8208120377* | 50-206 P |
| STALEY, G. | 8303010309* | 50-454 T |
| STAMIRIS, B. | 8303100059 | 50-330 G |
| STAMIRIS, B. | 8303100225* | 50-329 G |
| STANISH, M. A. | 8303080074 | 50-454 T |
| STAPLETON, B. W. | 8303030690* | 50-186 G |
| STAPLETON, B. W. | 8303100283* | 50-87 G |
| STARK, R. M. | 8303180008 | 50-537 A |
| STARK, R. M. | 8303290076 | 50-537 A |
| STARK, R. W. | 8303110378 | 50-537 A |
| STARKEY, R. B. | 8303150564 | 50-261 R |
| STARKEY, R. B. | 8303210379* | 50-261 G |
| STARKEY, R. B. | 8303210598 | 50-261 S |
| STARKEY, R. B. | 8303210602* | 50-261 G |
| STARKEY, R. B. | 8303240385 | 50-261 S |
| STARKWEATHER, G. | 8303160282* | 50-250 P |
| STARKWEATHER, G. | 8303160295* | 50-250 P |
| STARKWEATHER, G. | 8303160304* | 50-250 P |
| STARKWEATHER, G. | 8303160373* | 50-335 P |
| STARKWEATHER, G. | 8303160379* | 50-335 P |
| STARKWEATHER, G. | 8303160386* | 50-335 P |
| STAROSTECKI, R. | 8302180214 | 50-443 G |
| STAROSTECKI, R. | 8303010646 | 50-272 G |
| STAROSTECKI, R. | 8303030172 | 50-245 G |
| STAROSTECKI, R. | 8303030189 | 50-245 G |
| STAROSTECKI, R. | 8303030353 | 50-410 G |
| STAROSTECKI, R. | 8303030401 | 50-220 G |
| STAROSTECKI, R. | 8303040459 | 50-322 G |
| STAROSTECKI, R. | 8303040468 | 50-245 G |
| STAROSTECKI, R. | 8303080284 | 50-322 G |
| STAROSTECKI, R. | 8303080415 | 50-244 G |
| STAROSTECKI, R. | 8303090117* | 50-289 P |
| STAROSTECKI, R. | 8303100139 | 50-333 G |
| STAROSTECKI, R. | 8303100202 | 50-272 G |
| STAROSTECKI, R. | 8303100227 | 50-317 G |
| STAROSTECKI, R. | 8303100260 | 50-322 G |
| STAROSTECKI, R. | 8303100279 | 50-244 G |
| STAROSTECKI, R. | 8303100393* | 50-244 G |
| STAROSTECKI, R. | 8303140451* | 50-410 G |
| STAROSTECKI, R. | 8303140476* | 50-271 G |
| STAROSTECKI, R. | 8303150301* | 50-320 G |
| STAROSTECKI, R. | 8303150363 | 50-293 G |
| STAROSTECKI, R. | 8303150372 | 50-219 G |
| STAROSTECKI, R. | 8303150595 | 50-410 G |
| STAROSTECKI, R. | 8303160189 | 50-272 S |
| STAROSTECKI, R. | 8303160215 | 50-412 G |
| STAROSTECKI, R. | 8303160392 | 50-286 G |
| STAROSTECKI, R. | 8303160477 | 50-20 G |
| STAROSTECKI, R. | 8303160516 | 50-29 G |
| STAROSTECKI, R. | 8303160533 | 50-333 G |
| STAROSTECKI, R. | 8303180044 | 50-322 H |
| STAROSTECKI, R. | 8303180461 | 50-387 G |
| STAROSTECKI, R. | 8303220139 | 50-443 G |
| STAROSTECKI, R. | 8303220232 | 50-289 G |
| STAROSTECKI, R. | 8303240011 | 50-322 G |
| STAROSTECKI, R. | 8303240376 | 50-352 G |
| STAROSTECKI, R. | 8303240443 | 50-277 G |
| STAROSTECKI, R. | 8303240455 | 50-213 G |
| STAROSTECKI, R. | 8303240471 | 50-352 G |
| STAROSTECKI, R. | 8303240532 | 50-334 G |
| STAROSTECKI, R. | 8303240562 | 50-354 G |
| STAROSTECKI, R. | 8303250052 | 50-277 G |
| STAROSTECKI, R. | 8303250072 | 50-247 G |
| STAROSTECKI, R. | 8303280169 | 50-320 G |
| STAROSTECKI, R. | 8303280178 | 50-423 G |
| STAROSTECKI, R. | 8303280181 | 50-289 G |
| STAROSTECKI, R. | 8303280219 | 50-387 G |
| STAROSTECKI, R. | 8303280258 | 50-272 G |
| STAROSTECKI, R. | 8303290442 | 50-309 G |
| STAROSTECKI, R. | 8303300305 | 50-333 G |
| STAROSTECKI, R. | 8303300311 | 50-293 G |
| STAROSTECKI, R. | 8303300317 | 50-247 G |
| STAROSTECKI, R. | 8303300462 | 50-245 G |
| STAROSTECKI, R. | 8303300727* | 50-322 A |
| STASEK, S. | 8303030446* | 50-10 G |
| STASEK, S. | 8303170377* | 50-10 G |
| STASEK, S. | 8303220116* | 50-237 G |
| STASEK, S. | 8303240597* | 50-10 G |
| STATTON, C. D. | 8303210524* | QA999 |
| STEFANO, J. | 8303290557 | 50-440 A |
| STEFANO, J. J. | 8303100105* | 50-440 E |
| STEFANO, J. J. | 8303100334 | 50-440 A |
| STEFANO, J. J. | 8303100413 | MISC |
| STEFANO, J. J. | 8303240193 | 50-440 A |
| STEFANO, J. J. | 8303250111 | 50-440 A |
| STEIN, R. | 8303300053 | WASTE MGT |
| STELLO, V. | 8303020178 | REVIEW GRP |
| STELLO, V. | 8303110054 | REVIEW GRP |
| STELLO, V. | 8303220025 | REVIEW GRP |
| STELLO, V. | 8303220078 | REVIEW GRP |
| STELLO, V. | 8303220443 | REVIEW GRP |
| STELLO, V. | 8303240109 | REVIEW GRP |
| STELLO, V. | 8303250127 | REVIEW GRP |
| STEPHENS, R. H. | 8303040511 | PT21 |
| STEPHENSON, C. | 8303140496* | 50-289 S |
| STEPHENSON, C. | 8303180426* | 50-289 S |
| STEPTOE, P. P. | 8303010179 | 50-329 G |
| STEPTOE, P. P. | 8303010179 | 50-329 G |
| STEPTOE, P. P. | 8303030403 | 50-329 T |
| STEPTOE, P. P. | 8303030403 | 50-329 T |
| STEPTOE, P. P. | 8303140432* | 50-329 T |
| STEPTOE, P. P. | 8303220172 | 50-329 G |
| STEPTOE, P. P. | 8303220172 | 50-329 G |
| STEPTOE, P. P. | 8303280270 | 50-237 P |
| STEPTOE, P. P. | 8303280270 | 50-237 P |
| STERN, T. | 8303030267* | CONTRACT |
| STERNBERG, D. M. | 8303040355 | 50-528 G |
| STERNBERG, D. M. | 8303040366 | 50-397 G |
| STERNBERG, D. M. | 8303040436 | 50-344 G |
| STERNBERG, D. M. | 8303040451 | 50-397 G |
| STERNBERG, D. M. | 8303040583 | 50-344 G |
| STERNBERG, D. M. | 8303080203 | 50-397 G |
| STERNBERG, D. M. | 8303080210* | 50-397 G |
| STERNBERG, D. M. | 8303110244 | 50-528 G |
| STERNBERG, D. M. | 8303110310 | 50-508 G |
| STERNBERG, D. M. | 8303110367 | 50-312 G |
| STERNBERG, D. M. | 8303110376 | 50-508 G |
| STERNBERG, D. M. | 8303140546 | 50-528 G |
| STERNBERG, D. M. | 8303150492 | 50-397 G |
| STERNBERG, D. M. | 8303150497 | 50-528 G |
| STERNBERG, D. M. | 8303180513 | 50-528 G |
| STERNBERG, D. M. | 8303290291 | 50-312 G |
| STERNBERG, D. M. | 8303290441 | 50-288 G |
| STEVENS, J. L. | 8303140536* | 50-309 S |
| STEVENSON, J. D. | 8303280061 | NUREG |
| STEVERSON, J. A. | 8303220400 | NUREG |
| STEWART, J. P. | 8303040414* | 50-206 G |
| STEWART, J. P. | 8303150533* | 50-70 G |
| STEWART, J. P. | 8303290255* | 50-361 G |
| STEWART, M. | 8303280097 | NUREG |
| STEWART, M. | 8303280114 | NUREG |
| STEWART, P. | 8303290590* | 50-361 G |
| STEWART, R. C. | 8303150530* | 50-445 G |
| STEWART, W. L. | 8303010655* | 50-280 G |
| STEWART, W. L. | 8303020187 | 71-9151 |
| STEWART, W. L. | 8303020215 | 50-280 Y |
| STEWART, W. L. | 8303040475 | 50-338 R |
| STEWART, W. L. | 8303070007 | 50-280 P |
| STEWART, W. L. | 8303070048 | 50-280 P |
| STEWART, W. L. | 8303080035 | 50-280 R |
| STEWART, W. L. | 8303080183 | 50-280 P |
| STEWART, W. L. | 8303080372 | 50-338 R |
| STEWART, W. L. | 8303080484 | 50-338 P |
| STEWART, W. L. | 8303100189 | 50-338 P |
| STEWART, W. L. | 8303100342 | 50-339 P |
| STEWART, W. L. | 8303100372 | 50-338 P |
| STEWART, W. L. | 8303110120 | 50-338 P |
| STEWART, W. L. | 8303110280 | 50-280 P |
| STEWART, W. L. | 8303110282 | 50-280 P |
| STEWART, W. L. | 8303110323 | 50-280 G |
| STEWART, W. L. | 8303140221 | 50-338 P |
| STEWART, W. L. | 8303150285 | 50-280 P |
| STEWART, W. L. | 8303150370 | 50-280 R |
| STEWART, W. L. | 8303150399 | 50-280 P |
| STEWART, W. L. | 8303150438 | 50-338 R |
| STEWART, W. L. | 8303160160 | 50-338 H |
| STEWART, W. L. | 8303160172 | 50-280 P |
| STEWART, W. L. | 8303160198 | 50-280 P |
| STEWART, W. L. | 8303170365 | 50-280 P |
| STEWART, W. L. | 8303170523 | 50-280 P |
| STEWART, W. L. | 8303170525 | 50-338 P |
| STEWART, W. L. | 8303180467 | 50-338 P |
| STEWART, W. L. | 8303210523 | 50-280 G |
| STEWART, W. L. | 8303210617 | 50-280 P |
| STEWART, W. L. | 8303280056 | 50-338 G |
| STEWART, W. L. | 8303280105 | 50-338 P |

# PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| STEWART, W. L. | 8303280274 | 50-339 P |
| STEWART, W. L. | 8303290732* | 50-280 F |
| STIEDE, W. L. | 8303210325 | 50-295 P |
| STIEDE, W. L. | 8303220293* | 50-454 G |
| STIEDE, W. L. | 8303280301* | 50-454 G |
| STILL, N. | 8303300060 | WASTE MGT |
| STILL, N. L. | 8303180610 | WASTE MGT |
| STILL, N. L. | 8303180615 | WASTE MGT |
| STILL, N. L. | 8303180617 | WASTE MGT |
| STILL, N. L. | 8303180621 | WASTE MGT |
| STILL, N. L. | 8303180626 | WASTE MGT |
| STILL, N. L. | 8303180651 | WASTE MGT |
| STILLER, M. A. | 8303240048* | 50-483 F |
| STITT, B. D. | 8303300108 | 50-269 P |
| STOEFFLER, D. | 8303240117 | FOIA |
| STOHR, J. P. | 8303010456 | 70-143 |
| STOHR, J. P. | 8303010464 | 70-143 |
| STOHR, J. P. | 8303010584 | 70-143 |
| STOHR, J. P. | 8303010614 | 70-1113 |
| STOHR, J. P. | 8303010622 | 70-27 |
| STOHR, J. P. | 8303210360 | 70-1113 |
| STOHR, J. P. | 8303210364 | 70-1151 |
| STOHR, J. P. | 8303210534 | 70-27 |
| STOHR, J. P. | 8303210575 | 70-143 |
| STOHR, J. P. | 8303210576 | 70-143 |
| STOHR, J. P. | 8303210594 | 70-1113 |
| STOHR, J. P. | 8303210606 | 70-143 |
| STOHR, J. P. | 8303280236 | 70-143 |
| STOHR, J. P. | 8303280276 | 70-143 |
| STOHR, P. | 8303280246* | 70-143 |
| STOLZ, J. | 8303280085 | 50-277 P |
| STOLZ, J. | 8303310070 | 50-321 P |
| STOLZ, J. F. | 8302170446 | 50-346 P |
| STOLZ, J. F. | 8303010007* | 50-312 P |
| STOLZ, J. F. | 8303010011* | 50-312 P |
| STOLZ, J. F. | 8303020060 | 50-321 F |
| STOLZ, J. F. | 8303020214 | 50-302 G |
| STOLZ, J. F. | 8303020392* | 50-346 P |
| STOLZ, J. F. | 8303020416* | 50-346 P |
| STOLZ, J. F. | 8303020417* | 50-346 P |
| STOLZ, J. F. | 8303020423* | 50-277 P |
| STOLZ, J. F. | 8303020429* | 50-277 P |
| STOLZ, J. F. | 8303020437* | 50-346 P |
| STOLZ, J. F. | 8303030405 | 50-269 P |
| STOLZ, J. F. | 8303030409* | 50-346 P |
| STOLZ, J. F. | 8303030424* | 50-346 P |
| STOLZ, J. F. | 8303040101 | 50-346 P |
| STOLZ, J. F. | 8303040117 | 50-312 P |
| STOLZ, J. F. | 8303040385 | 50-277 P |
| STOLZ, J. F. | 8303090279 | 50-313 P |
| STOLZ, J. F. | 8303100128 | 50-346 P |
| STOLZ, J. F. | 8303100511 | 50-289 V |
| STOLZ, J. F. | 8303110154* | 50-277 P |
| STOLZ, J. F. | 8303110159* | 50-277 P |
| STOLZ, J. F. | 8303110398 | 50-313 P |
| STOLZ, J. F. | 8303110401* | 50-313 P |
| STOLZ, J. F. | 8303110408* | 50-313 P |
| STOLZ, J. F. | 8303110419* | 50-289 P |
| STOLZ, J. F. | 8303110428* | 50-289 P |
| STOLZ, J. F. | 8303110525* | 50-277 P |
| STOLZ, J. F. | 8303110544* | 50-277 P |
| STOLZ, J. F. | 8303140022 | 50-312 P |
| STOLZ, J. F. | 8303150072 | 50-346 F |
| STOLZ, J. F. | 8303150692* | 50-277 P |
| STOLZ, J. F. | 8303150705* | 50-277 P |
| STOLZ, J. F. | 8303160082 | 50-269 F |
| STOLZ, J. F. | 8303160104 | 50-289 P |
| STOLZ, J. F. | 8303160108* | 50-289 P |
| STOLZ, J. F. | 8303160114* | 50-289 P |
| STOLZ, J. F. | 8303160121 | 50-269 P |
| STOLZ, J. F. | 8303160125* | 50-269 P |
| STOLZ, J. F. | 8303160135* | 50-269 P |
| STOLZ, J. F. | 8303160638 | 50-289 P |
| STOLZ, J. F. | 8303160641* | 50-289 P |
| STOLZ, J. F. | 8303160644* | 50-289 P |
| STOLZ, J. F. | 8303170645 | 50-302 P |
| STOLZ, J. F. | 8303170648* | 50-302 P |
| STOLZ, J. F. | 8303170650* | 50-302 P |
| STOLZ, J. F. | 8303180559 | 50-289 P |
| STOLZ, J. F. | 8303180634 | 50-346 P |
| STOLZ, J. F. | 8303210001 | 50-312 P |
| STOLZ, J. F. | 8303210002* | 50-312 P |
| STOLZ, J. F. | 8303210003* | 50-312 P |
| STOLZ, J. F. | 8303210007 | 50-313 P |
| STOLZ, J. F. | 8303210008* | 50-313 P |
| STOLZ, J. F. | 8303210009* | 50-269 P |
| STOLZ, J. F. | 8303210011* | 50-313 P |
| STOLZ, J. F. | 8303210012 | 50-346 P |
| STOLZ, J. F. | 8303210015* | 50-269 P |
| STOLZ, J. F. | 8303210050* | 50-346 P |
| STOLZ, J. F. | 8303210055* | 50-346 P |
| STOLZ, J. F. | 8303210080 | 50-312 G |
| STOLZ, J. F. | 8303210127 | 50-312 P |
| STOLZ, J. F. | 8303210165 | 50-289 P |
| STOLZ, J. F. | 8303210184* | 50-289 P |
| STOLZ, J. F. | 8303210191* | 50-289 P |
| STOLZ, J. F. | 8303220458 | 50-321 P |
| STOLZ, J. F. | 8303220463* | 50-321 P |
| STOLZ, J. F. | 8303220468* | 50-321 P |
| STOLZ, J. F. | 8303230405 | 50-302 P |
| STOLZ, J. F. | 8303230409* | 50-302 P |
| STOLZ, J. F. | 8303230420* | 50-302 P |
| STOLZ, J. F. | 8303240067 | 50-313 P |
| STOLZ, J. F. | 8303240073* | 50-313 P |
| STOLZ, J. F. | 8303240079 | 50-312 G |
| STOLZ, J. F. | 8303240099 | 50-289 P |
| STOLZ, J. F. | 8303240101 | 50-302 P |
| STOLZ, J. F. | 8303280336 | 50-346 P |
| STOLZ, J. F. | 8303290012 | 50-321 P |
| STOLZ, J. F. | 8303290031 | 50-346 P |
| STOLZ, J. F. | 8303290037* | 50-346 P |
| STOLZ, J. F. | 8303290041* | 50-346 P |
| STOLZ, J. F. | 8303290398 | 50-277 P |
| STOLZ, J. F. | 8303290418 | 50-312 P |
| STOLZ, J. F. | 8303290605 | 50-313 P |
| STOLZ, J. F. | 8303300004 | 50-346 P |
| STOLZ, J. F. | 8303300010 | 50-269 P |
| STOLZ, J. F. | 8303300013 | 50-313 P |
| STOLZ, J. F. | 8303300028 | 50-269 P |
| STOLZ, J. F. | 8303300028 | 50-269 P |
| STOLZ, J. F. | 8303300173 | 50-269 P |
| STOLZ, J. F. | 8303300379 | 50-289 V |
| STOLZ, J. F. | 8303300509* | 50-321 P |
| STOLZ, J. F. | 8303300520* | 50-321 P |
| STOLZ, J. F. | 8303300531 | 50-312 P |
| STOLZ, J. F. | 8303300536* | 50-312 P |
| STOLZ, J. F. | 8303300546* | 50-312 P |
| STOLZ, J. F. | 8303300776 | 50-313 P |
| STOLZ, J. F. | 8303310021 | 50-277 P |
| STOLZ, J. F. | 8303310687 | 50-313 P |
| STOMFAY-STITZ | 8303070054* | 50-454 T |
| STOMFAY-STITZ | 8303070054* | 50-454 T |
| STOMFAY-STITZ | 8303070054* | 50-454 T |
| STOMFAY-STITZ | 8303220198* | 50-454 T |
| STOMFAY-STITZ | 8303220198* | 50-454 T |
| STRAWE, D. F. | 8303100460 | NUREG |
| STRAWE, D. F. | 8303100558 | NUREG |
| STREETER, J. F. | 8303030439 | 50-10 G |
| STREETER, J. F. | 8303030624 | 50-255 G |
| STREETER, J. F. | 8303030634* | 50-315 G |
| STREETER, J. F. | 8303030636* | 50-255 G |
| STREETER, J. F. | 8303080023 | 50-263 G |
| STREETER, J. F. | 8303080032* | 50-263 G |
| STREETER, J. F. | 8303080184 | 50-295 G |
| STREETER, J. F. | 8303080248 | 50-315 G |
| STREETER, J. F. | 8303080258* | 50-315 G |
| STREETER, J. F. | 8303080396 | 50-331 G |
| STREETER, J. F. | 8303140473 | 50-373 G |
| STREETER, J. F. | 8303150609 | 50-331 G |
| STREETER, J. F. | 8303170369 | 50-266 G |
| STREETER, J. F. | 8303170371 | 50-10 G |
| STREETER, J. F. | 8303170375* | 50-10 G |
| STREETER, J. F. | 8303170414 | 50-305 G |
| STREETER, J. F. | 8303170490 | 50-263 G |
| STREETER, J. F. | 8303170501 | 50-295 G |
| STREETER, J. F. | 8303170510 | 50-373 G |
| STREETER, J. F. | 8303170515* | 50-373 G |
| STREETER, J. F. | 8303170546 | 50-254 G |
| STREETER, J. F. | 8303220059 | 50-255 G |
| STREETER, J. F. | 8303240538 | 50-282 G |
| STREETER, J. F. | 8303240546* | 50-282 G |
| STREETER, J. F. | 8303290484 | 50-263 G |
| STRENGE, D. L. | 8303150680 | NUREG |
| STREUTKER, S. R. | 8303020153 | 71-9073 |
| STREUTKER, S. R. | 8303100315 | 71-9159 |
| STREUTKER, S. R. | 8303180527 | 71-9079 |
| STRUMWASSER, M. | 8303080073 | 50-275 G |
| STRUMWASSER, M. | 8303090254 | 50-275 H |
| STRUTHERS, T. L. | 8303010439* | 50-352 A |
| STUBBS, A. D. | 8303090587* | State Prog |
| STUCKY, S. W. | 8303180377 | 50-289 G |
| STUDEBAKER, S. T. | 8303280028* | 50-298 S |
| STUDNICKA, J. | 8303280233* | 50-397 S |
| SUGARMAN, R. J. | 8303140352 | 50-352 G |
| SUGARMAN, R. J. | 8303140352 | 50-352 G |
| SUGARMAN, R. J. | 8303140356* | 50-352 G |
| SUGARMAN, R. J. | 8303140356* | 50-352 G |
| SUGARMAN, R. J. | 8303250167 | 50-352 G |
| SUGARMAN, R. J. | 8303250167 | 50-352 G |
| SUITT, W. J. | 8303230281 | NUREG |
| SULLIVAN, J. E. | 8303140617 | NUREG |
| SULLIVAN, J. L. | 8303240207* | FOIA |
| SULLIVAN, R. E. | 8303240435* | 50-443 G |
| SUMMERS, R. | 8303030025 | 50-272 S |
| SUMMERS, R. | 8303030027 | 50-272 S |
| SUMMERS, R. J. | 8303010667* | 50-272 G |
| SUMMERS, R. J. | 8303280267* | 50-272 G |
| SUMNER, H. L. | 8302150615* | 50-366 S |
| SUMNER, H. L. | 8303140580* | 50-321 S |
| SUMNER, H. L. | 8303140588* | 50-321 S |
| SUMNER, H. L. | 8303150214* | 50-321 S |
| SUMNER, H. L. | 8303150456* | 50-321 S |
| SUMNER, H. L. | 8303150495* | 50-366 S |
| SUMNER, H. L. | 8303210354* | 50-321 S |
| SUMNER, H. L. | 8303210393* | 50-321 S |
| SUMNER, H. L. | 8303210527* | 50-366 S |
| SUMNER, H. L. | 8303210563* | 50-321 S |
| SUN, K. H. | 8303160236* | TOPREP |
| SUNSER, T. T. | 8303170474 | 50-410 F |
| SURMEIER, J. | 8303300153 | WASTE MGT |
| SURMEIER, J. J. | 8303180657 | WASTE MGT |
| SUTPHIN, R. N. | 8303040527* | 50-255 G |
| SUTPHIN, R. N. | 8303240498* | 50-373 G |
| SUTT, R. J. | 8303080311* | 50-387 S |
| SVENSSON, B. A. | 8303080276* | 50-316 R |
| SVENSSON, B. A. | 8303080429* | 50-315 R |
| SVINIS, B. | 8303110112 | 71-6601 |
| SVINIS, B. | 8303180483 | 71-9096 |
| SVINIS, B. | 8303240093 | 71-9105 |
| SVINIS, B. | 8303240105 | 71-9101 |
| SVINIS, B. | 8303280352 | 71-9111 |
| SWAN, W. | 8303210585* | 50-390 G |
| SWANSON, E. R. | 8303080270* | 50-315 G |
| SWARTZ, E. D. | 8303040631 | 50-10 V |
| SWARTZ, E. D. | 8303070036 | 50-237 G |
| SWARTZ, E. D. | 8303100323 | 50-456 C |
| SWARTZ, E. D. | 8303110246 | 50-10 P |
| SWARTZ, E. D. | 8303140594 | 50-456 S |
| SWARTZ, E. D. | 8303150336 | 50-456 A |
| SWARTZ, E. D. | 8303150583 | 50-456 F |
| SWARTZ, E. D. | 8303220311 | 50-456 A |
| SWARTZ, E. D. | 8303290266 | 50-456 A |
| SWARTZ, E. D. | 8303290526 | 50-295 P |
| SWARTZ, E. D. | 8303300459 | 50-454 G |
| SWARTZ, E. D. | 8303310211 | 50-237 G |
| SWEIGART, J. | 8303020072* | CONTRACT |
| SWIGER, M. A. | 8303100408 | 50-440 G |
| SWIGER, M. A. | 8303100408 | 50-440 G |
| SWIGER, M. A. | 8303170438 | 50-440 G |
| SWIGER, M. A. | 8303170438 | 50-440 G |
| SWIGER, M. A. | 8303170452 | 50-440 G |
| SWIGER, M. A. | 8303170452 | 50-440 G |
| SWINDILL, J. E. | 8303150496* | 50-259 R |
| SWINDLEHURST, G. | 8303070164* | 50-413 A |
| SWYLER, K. J. | 8303090608 | RES |
| SYED, I. B. | 8303140181* | FOIA |
| TALBOT, P. | 8303290575* | WASTE MGT |
| TALWANI, P. | 8303110343* | 50-395 R |
| TAM, P. S. | 8303080523 | 50-334 F |
| TAM, P. S. | 8303310089 | COMMISSION |
| TAPIA, J. I. | 8303310256* | 50-445 T |
| TASHIRO, S. | 8303180126* | WASTE MGT |
| TATE, J. | 8303100092* | 50-440 A |
| TAUBER, H. | 8303070094 | 50-341 V |
| TAUBER, H. | 8303080001 | 50-341 E |
| TAUBER, H. | 8303210336 | 50-341 A |
| TAUBER, H. | 8303220484 | 70-2926 |
| TAUBER, H. | 8303250099 | 50-341 A |
| TAYLOR, F. | 8303290798* | CONTRACT |
| TAYLOR, H. S. | 8303010298 | TOPREP |
| TAYLOR, H. S. | 8303150470* | GA999 |
| TAYLOR, J. H. | 8303010606 | TOPREP |
| TAYLOR, J. H. | 8303040505 | TOPREP |
| TAYLOR, J. H. | 8303250020 | 50-335 P |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| TAYLOR, J. M. | 8303110533* | 50-445 Q |
| TAYLOR, P. A. | 8303210459* | 50-389 Q |
| TAYLOR, P. A. | 8303210503* | 50-370 Q |
| TAYLOR, R. G. | 8303310256* | 50-445 T |
| TAYLOR, T. T. | 8303220422 | NUREG |
| TEDESCO, R. L. | 8303090029* | FOIA |
| TEMPLE, G. | 8303040362* | 50-344 Q |
| TEMPLE, G. M. | 8303290480* | 50-141 Q |
| TENZER, B. E. | 8303030642* | GA999 |
| TERAO, D. | 8212150184* | 50-358 A |
| TERC, N. M. | 8303280283* | 50-277 Q |
| TERWILLIGER, L. | 8303290085* | XPORTLIC |
| THADANI, A. C. | 8303110227 | 50-322 T |
| THIEL, J. | 8303290788* | CONTRACT |
| THIES, A. C. | 8303040233* | 10CFR - |
| THOM, T. | 8303080021* | 50-259 R |
| THOM, T. | 8303150496* | 50-259 R |
| THOM, T. | 8303170467* | 50-259 R |
| THOMAS, C. O. | 8303030322 | TOPREP |
| THOMAS, C. O. | 8303030336 | TOPREP |
| THOMAS, C. O. | 8303030764 | TOPREP |
| THOMAS, C. O. | 8303040192 | TOPREP |
| THOMAS, C. O. | 8303090213 | TOPREP |
| THOMAS, C. O. | 8303090280 | 50-131 P |
| THOMAS, C. O. | 8303090474 | TOPREP |
| THOMAS, C. O. | 8303150040 | TOPREP |
| THOMAS, C. O. | 8303160028 | 50-447 A |
| THOMAS, C. O. | 8303160031 | 50-470 A |
| THOMAS, C. O. | 8303160674 | TOPREP |
| THOMAS, C. O. | 8303180046 | 50-170 F |
| THOMAS, C. O. | 8303180104 | 50-410 F |
| THOMAS, C. O. | 8303180257 | 50-297 F |
| THOMAS, C. O. | 8303210249 | 50-413 F |
| THOMAS, C. O. | 8303230218 | 50-20 P |
| THOMAS, C. O. | 8303230223* | 50-20 P |
| THOMAS, C. O. | 8303300179 | 50-54 P |
| THOMAS, C. O. | 8303300186* | 50-54 P |
| THOMAS, F. A. | 8303280061 | NUREG |
| THOMAS, H. J. | 8303020207* | 50-250 F |
| THOMAS, M. | 8303210347* | 50-370 Q |
| THOMAS, M. | 8303210503* | 50-370 Q |
| THOMAS, M. T. | 8303100421 | NUREG |
| THOMAS, R. A. | 8303100400 | 50-437 A |
| THOMAS, R. D. | 8303010376 | 27-48 |
| THOMAS, R. D. | 8303080350* | 27-48 |
| THOMAS, R. D. | 8303080360* | 27-48 |
| THOMAS, R. D. | 8303240577* | 70-25 |
| THOMAS, R. D. | 8303300263 | 27-48 |
| THOMAS, R. D. | 8303300268 | IME |
| THOMPSON, A. C. | 8303230219 | 50-443 Q |
| THOMPSON, A. C. | 8303230219 | 50-443 Q |
| THOMPSON, D. | 8303110127* | FOIA |
| THOMPSON, D. | 8303140273 | 50-142 Q |
| THOMPSON, D. | 8303140273 | 50-142 Q |
| THOMPSON, D. J. | 8303010659* | 50-387 S |
| THOMPSON, G. A. | 8303180663 | 50-522 O |
| THOMPSON, G. A. | 8303180663 | 50-522 O |
| THOMPSON, H. | 8303210025* | 50-289 P |
| THOMPSON, H. L. | 8303030735* | 50-289 P |
| THOMPSON, H. L. | 8303040178 | 50-213 P |
| THOMPSON, J. R. | 8303290509 | 50-329 Q |
| THOMPSON, S. L. | 8303300514 | NUREG |
| THOMPSON, T. | 8303210362* | 50-346 S |
| THOMPSON, T. | 8303290694 | NUREG |
| THONE, C. | 8204070025* | FOIA |
| THONUS, L. | 8303280173* | 50-320 Q |
| THORNBERRY, R. C. | 8303080031 | 50-275 R |
| THORNBERRY, R. C. | 8303080173 | 50-275 R |
| THORNBERRY, R. C. | 8303150508 | 50-275 R |
| THORPE, D. | 8303160536* | 50-296 S |
| THORPE, J. R. | 8303150272* | 50-289 P |
| THORSEN, E. O. | 8303020093 | 50-247 T |
| THORSEN, E. O. | 8303100261 | 50-247 Q |
| THUL, T. S. | 8303080076* | 50-245 S |
| THULL, T. S. | 8303080354* | 50-245 S |
| THULL, T. S. | 8303140263* | 50-245 S |
| THULL, T. S. | 8303140394* | 50-245 S |
| THULL, T. S. | 8303180343* | 50-245 S |
| THULL, T. S. | 8303240581* | 50-245 S |
| TIERMAN, J. A. | 8303100363 | 50-317 R |
| TILLMAN, A. | 8303010489* | 50-390 Q |
| TILLMAN, A. | 8303150505* | 50-370 Q |
| TILLMAN, A. | 8303280148* | 50-269 Q |
| TILLMAN, A. | 8303290403* | 50-280 Q |
| TIMMONS, T. F. | 8303010337* | 50-454 T |
| TIMMONS, T. F. | 8303010337* | 50-454 T |
| TINSTON, W. J. | 8303290600* | 40-8713 |
| TIPPS, S. B. | 8303080048* | 50-321 S |
| TIPPS, S. B. | 8303080214* | 50-321 S |
| TIPPS, S. B. | 8303150563* | 50-321 S |
| TIPPS, S. B. | 8303160445* | 50-321 S |
| TIPPS, S. B. | 8303180370* | 50-366 S |
| TIPPS, S. B. | 8303210320* | 50-366 S |
| TIPPS, S. B. | 8303210413* | 50-366 S |
| TIPPS, S. B. | 8303210419* | 50-366 S |
| TIPPS, S. B. | 8303210467* | 50-321 S |
| TIPPS, S. B. | 8303210485* | 50-321 S |
| TIPPS, S. B. | 8303220054* | 50-321 S |
| TIPPS, S. B. | 8303240453* | 50-321 S |
| TITUS, G. W. | 8303170395* | 50-18 R |
| TITUS, G. W. | 8303170404* | 50-183 R |
| TITUS, G. W. | 8303170465* | 50-70 R |
| TOBIN, M. J. | 8303150578* | 50-261 Q |
| TODD, J. T. | 8303160180* | 50-387 S |
| TODD, J. T. | 8303160191* | 50-387 S |
| TODD, J. T. | 8303160375* | 50-387 S |
| TODD, J. T. | 8303210701* | 50-387 S |
| TODD, J. T. | 8303210713* | 50-387 S |
| TODD, J. T. | 8303210751* | 50-387 S |
| TODD, J. T. | 8303240523* | 50-387 S |
| TODD, J. T. | 8303250123* | 50-387 S |
| TOLSON, J. Q. | 8303090314 | 50-247 Q |
| TOMAN, G. J. | 8301170075* | 50-346 P |
| TOMAN, G. J. | 8302020153* | 50-369 P |
| TOMASKIN, L. | 8303290834* | WASTE MGT |
| TOMLINSON, D. P. | 8303010451* | 50-445 Q |
| TOMLINSON, D. P. | 8303150491* | 50-498 Q |
| TOMPKINS, B. A. | 8303090299 | 50-537 Q |
| TOMPKINS, B. A. | 8303100248 | 50-382 Q |
| TOMPKINS, B. A. | 8303100377 | 50-382 Q |
| TOMPKINS, B. A. | 8303110200 | 50-275 Q |
| TONER, K. A. | 8303040339 | 50-155 P |
| TONER, K. A. | 8303070035 | 50-255 P |
| TONER, K. A. | 8303170096 | 50-155 P |
| TONER, K. A. | 8303180352 | 50-155 P |
| TONGUE, T. M. | 8303030446* | 50-10 Q |
| TONGUE, T. M. | 8303170377* | 50-10 Q |
| TONGUE, T. M. | 8303220116* | 50-237 Q |
| TONGUE, T. M. | 8303240372* | 50-237 Q |
| TONGUE, T. M. | 8303240597* | 50-10 Q |
| TOTH, A. D. | 8303040377* | 50-397 Q |
| TOURIGNY, E. G. | 8303030091 | 50-285 P |
| TOURIGNY, E. G. | 8303090399 | 50-285 P |
| TOURIGNY, E. G. | 8303110431 | 50-285 P |
| TOURIGNY, E. G. | 8303300144 | 50-285 P |
| TOURTELLOTTE, J. | 8303240076* | REVIEW GRP |
| TOURTELLOTTE, J. | 8303240081* | REVIEW GRP |
| TOURTELLOTTE, J. | 8303240087* | REVIEW GRP |
| TOWNSEND, B. L. | 8303230185 | CONTRACT |
| TRAFFORD, S. | 8303160029 | XPORTLIC |
| TRAINA, P. J. | 8303040579 | 50-327 S |
| TRAINA, P. J. | 8303040586* | 50-327 S |
| TRAMM, T. R. | 8303040500 | 50-454 Q |
| TRAMM, T. R. | 8303080305 | 50-454 Q |
| TRAMM, T. R. | 8303080425 | 50-454 Q |
| TRAMM, T. R. | 8303150275 | 50-454 A |
| TRAMM, T. R. | 8303280159 | 50-454 A |
| TRAMMELL, C. M. | 8303300384 | 50-344 P |
| TRAMMELL, C. M. | 8303310089 | COMMISSION |
| TRAVIS, J. R. | 8303290698 | NUREG |
| TREBY, S. A. | 8303160597 | 50-508 Q |
| TREBY, S. A. | 8303180371 | 50-445 Q |
| TREBY, S. A. | 8303230043 | 50-445 Q |
| TREBY, S. A. | 8303290496 | 50-537 Q |
| TREBY, S. A. | 8303310251 | 50-445 T |
| TRIBBLE, J. E. | 8303160622* | COMMISSION |
| TRIMBLE, D. C. | 8303100243* | 50-317 Q |
| TRINER, E. G. | 8303240063* | REVIEW GRP |
| TRIPP, L. | 8303030025 | 50-272 S |
| TRIPP, L. | 8303030027 | 50-272 S |
| TRIPP, L. E. | 8303010667* | 50-272 Q |
| TRIPP, L. E. | 8303100210* | 50-272 Q |
| TRIPP, L. E. | 8303240542* | 50-334 Q |
| TRIPP, L. E. | 8303240575* | 50-354 Q |
| TRIPP, L. E. | 8303280267* | 50-272 Q |
| TROSKOSKI, W. M. | 8303240542* | 50-334 Q |
| TROWBRIDGE, G. F. | 8303170475 | 50-261 Q |
| TROWBRIDGE, G. F. | 8303170475 | 50-261 Q |
| TROWBRIDGE, G. F. | 8303170488 | 50-261 Q |
| TROWBRIDGE, G. F. | 8303170488 | 50-261 Q |
| TROWBRIDGE, G. F. | 8303170496* | 50-261 Q |
| TROWBRIDGE, G. F. | 8303170496* | 50-261 Q |
| TSAI, N. C. | 8209030274* | 50-213 P |
| TSAI, S. Y. | 8303020011* | 50-329 T |
| TSAI, S. Y. | 8303020011* | 50-329 T |
| TUCKER, H. B. | 8302240208 | 50-413 K |
| TUCKER, H. B. | 8303010200 | 50-413 Q |
| TUCKER, H. B. | 8303010301 | 50-413 Q |
| TUCKER, H. B. | 8303010311 | 50-369 P |
| TUCKER, H. B. | 8303010496 | 50-413 A |
| TUCKER, H. B. | 8303010531 | 50-414 S |
| TUCKER, H. B. | 8303010534 | 50-370 Q |
| TUCKER, H. B. | 8303010562 | 50-369 S |
| TUCKER, H. B. | 8303010591 | TOPREP |
| TUCKER, H. B. | 8303010650 | 50-369 Q |
| TUCKER, H. B. | 8303010666 | 50-269 Q |
| TUCKER, H. B. | 8303040536 | 50-369 P |
| TUCKER, H. B. | 8303070141 | 50-413 A |
| TUCKER, H. B. | 8303080084 | 50-269 I |
| TUCKER, H. B. | 8303080294 | 50-369 P |
| TUCKER, H. B. | 8303080353 | 50-269 R |
| TUCKER, H. B. | 8303080492 | 50-369 J |
| TUCKER, H. B. | 8303090148 | 50-369 P |
| TUCKER, H. B. | 8303090162 | 50-413 F |
| TUCKER, H. B. | 8303090163 | 50-269 P |
| TUCKER, H. B. | 8303090210 | 50-369 P |
| TUCKER, H. B. | 8303090214 | 50-370 A |
| TUCKER, H. B. | 8303100168* | 50-413 F |
| TUCKER, H. B. | 8303140379 | 50-369 S |
| TUCKER, H. B. | 8303140391 | 50-369 S |
| TUCKER, H. B. | 8303140395 | 50-413 A |
| TUCKER, H. B. | 8303140515 | 50-413 S |
| TUCKER, H. B. | 8303150294 | 50-370 S |
| TUCKER, H. B. | 8303150317 | 50-369 P |
| TUCKER, H. B. | 8303150416 | 50-369 P |
| TUCKER, H. B. | 8303150451 | 50-369 S |
| TUCKER, H. B. | 8303150483 | 50-269 P |
| TUCKER, H. B. | 8303160270 | 50-369 P |
| TUCKER, H. B. | 8303160510 | 50-269 P |
| TUCKER, H. B. | 8303160555 | 50-269 S |
| TUCKER, H. B. | 8303160565 | 50-269 S |
| TUCKER, H. B. | 8303180332 | 50-287 S |
| TUCKER, H. B. | 8303180345 | 50-369 P |
| TUCKER, H. B. | 8303180347 | 50-370 P |
| TUCKER, H. B. | 8303180373 | 50-369 R |
| TUCKER, H. B. | 8303180379 | 50-269 R |
| TUCKER, H. B. | 8303180404 | 50-269 S |
| TUCKER, H. B. | 8303180533 | 50-369 P |
| TUCKER, H. B. | 8303210268 | 50-369 Q |
| TUCKER, H. B. | 8303210430 | 50-370 Q |
| TUCKER, H. B. | 8303210447 | 50-370 Q |
| TUCKER, H. B. | 8303210471 | 50-413 Q |
| TUCKER, H. B. | 8303210479 | 50-413 Q |
| TUCKER, H. B. | 8303210540 | 50-369 Q |
| TUCKER, H. B. | 8303210542 | 50-369 Q |
| TUCKER, H. B. | 8303210640 | 50-413 S |
| TUCKER, H. B. | 8303220023 | 50-287 S |
| TUCKER, H. B. | 8303220103 | 50-414 S |
| TUCKER, H. B. | 8303230220 | 50-269 Q |
| TUCKER, H. B. | 8303230222 | 50-369 P |
| TUCKER, H. B. | 8303230269 | 50-413 E |
| TUCKER, H. B. | 8303240120* | 50-269 F |
| TUCKER, H. B. | 8303240228 | 50-287 P |
| TUCKER, H. B. | 8303240270 | 50-269 P |
| TUCKER, H. B. | 8303240378 | 50-369 P |
| TUCKER, H. B. | 8303240381 | 50-369 P |
| TUCKER, H. B. | 8303240465 | 50-269 P |
| TUCKER, H. B. | 8303240599 | 50-369 S |
| TUCKER, H. B. | 8303250095* | 50-369 F |
| TUCKER, H. B. | 8303290032 | 50-269 P |
| TUCKER, H. B. | 8303280138* | 50-269 Q |
| TUCKER, H. B. | 8303280193 | 50-413 A |
| TUCKER, H. B. | 8303280194 | 50-269 P |
| TUCKER, H. B. | 8303290475 | 50-269 F |
| TUCKER, H. B. | 8303300119 | 50-369 P |
| TUCKER, H. B. | 8303310050 | 50-369 P |
| TUCKER, P. G. | 8303220432 | NUREG |
| TUCKER, W. T. | 8303210536 | 50-370 Q |
| TUITE, P. | 8303030223* | 50-320 P |
| TURK, S. E. | 8303020019 | 50-537 Q |
| TURK, S. E. | 8303020071 | 50-445 Q |
| TURK, S. E. | 8303030465 | 50-537 Q |
| TURK, S. E. | 8303150127 | 50-445 Q |
| TURK, S. E. | 8303240006 | 50-537 Q |
| TURK, S. E. | 8303290069 | 50-382 Q |

# PERSONAL AUTHOR INDEX


| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| TURK, S E | 8303290489 | 50-382 G |
| TURK, S E | 8303290500 | 50-382 G |
| TURKANIS, M M | 8303310204* | FOIA |
| TURKANIS, M M | 8303310227* | FOIA |
| TURKANIS, M M | 8303310265* | FOIA |
| TURKANIS, M M | 8303310268* | FOIA |
| TURKANIS, M M | 8303310275* | FOIA |
| TURNER, C L | 8303170270 | 50-461 J |
| TURNER, M E | 8303030143* | 50-213 S |
| TURNER, S | 8303290001 | 70-2926 |
| TURNQUEST, L | 8303290297* | 50-237 S |
| TWISDALE, L A | 8303010294* | MISC |
| TWISDALE, L A | 8303010300* | MISC |
| UDALL, M K | 8303030355* | 50-275 U |
| UDALL, M K | 8303030395* | 50-275 P |
| UDER TZ, R A | 8303030276 | 50-272 S |
| UDERITZ, R A | 8303140621* | 50-272 G |
| UDERITZ, R A | 8303150646* | 50-272 S |
| UDERITZ, R A | 8303160234 | 50-272 S |
| UDERITZ, R A | 8303170122 | 50-272 S |
| UDERITZ, R A | 8303170250 | 50-272 G |
| UDERITZ, R A | 8303250082 | 50-272 G |
| UDERITZ, R A | 8303290437 | 50-272 F |
| UDERITZ, R A | 8303300473* | 50-272 G |
| UDERITZ, R A | 8303300477* | 50-272 G |
| UDY, A C | 8303300021* | 50-269 P |
| UDY, A C | 8303300164 | 50-269 P |
| UEBBING, R | 8303140429* | 50-346 S |
| UHOV, P | 8303230069 | XPORTLIC |
| UHRIG, R E | 8303010153* | 50-250 G |
| UHRIG, R E | 8303010261 | 50-389 S |
| UHRIG, R E | 8303010280 | 50-389 G |
| UHRIG, R E | 8303010604* | 50-250 G |
| UHRIG, R E | 8303010610* | 50-250 G |
| UHRIG, R E | 8303010681* | 50-250 G |
| UHRIG, R E | 8303020086 | 50-389 K |
| UHRIG, R E | 8303030499 | 50-335 P |
| UHRIG, R E | 8303030554 | 50-250 F |
| UHRIG, R E | 8303040338 | 50-250 H |
| UHRIG, R E | 8303040346 | 50-389 F |
| UHRIG, R E | 8303040456 | 50-389 F |
| UHRIG, R E | 8303040460 | 50-389 S |
| UHRIG, R E | 8303040464 | 50-389 S |
| UHRIG, R E | 8303040514 | 50-335 G |
| UHRIG, R E | 8303040619 | 50-250 P |
| UHRIG, R E | 8303040638 | 50-389 G |
| UHRIG, R E | 8303080051 | 50-250 P |
| UHRIG, R E | 8303080126 | 50-389 A |
| UHRIG, R E | 8303080318 | 50-250 V |
| UHRIG, R E | 8303080389 | 50-250 R |
| UHRIG, R E | 8303080399 | 50-250 P |
| UHRIG, R E | 8303090158 | 50-335 R |
| UHRIG, R E | 8303090340 | 50-389 E |
| UHRIG, R E | 8303100164 | 50-389 A |
| UHRIG, R E | 8303100254 | 50-389 E |
| UHRIG, R E | 8303100352 | 50-250 P |
| UHRIG, R E | 8303110257 | 50-389 A |
| UHRIG, R E | 8303110287 | 50-250 P |
| UHRIG, R E | 8303140057 | 50-335 P |
| UHRIG, R E | 8303140204 | 50-250 P |
| UHRIG, R E | 8303140232 | 50-250 G |
| UHRIG, R E | 8303140521 | 50-250 P |
| UHRIG, R E | 8303150165 | 50-389 S |
| UHRIG, R E | 8303150312 | 50-389 A |
| UHRIG, R E | 8303150318 | 50-251 R |
| UHRIG, R E | 8303150434 | 50-335 P |
| UHRIG, R E | 8303150528 | 50-389 E |
| UHRIG, R E | 8303150538* | 50-389 E |
| UHRIG, R E | 8303160171 | 50-335 P |
| UHRIG, R E | 8303160200 | 50-335 P |
| UHRIG, R E | 8303160228 | 50-389 A |
| UHRIG, R E | 8303160257 | 50-250 F |
| UHRIG, R E | 8303160267 | 50-250 P |
| UHRIG, R E | 8303160360 | 50-335 P |
| UHRIG, R E | 8303170304 | 50-335 P |
| UHRIG, R E | 8303170504 | 50-250 P |
| UHRIG, R E | 8303210352 | 50-335 G |
| UHRIG, R E | 8303210512* | 50-389 G |
| UHRIG, R E | 8303210622 | 50-250 G |
| UHRIG, R E | 8303210645 | 50-250 G |
| UHRIG, R E | 8303210706* | 50-389 G |
| UHRIG, R E | 8303210779 | 70-2957 |
| UHRIG, R E | 8303240208 | 50-389 A |
| UHRIG, R E | 8303240210 | 50-389 E |
| UHRIG, R E | 8303240357 | 50-250 P |
| UHRIG, R E | 8303240437 | 50-389 A |
| UHRIG, R E | 8303240446 | 50-389 A |
| UHRIG, R E | 8303240459 | 50-389 A |
| UHRIG, R E | 8303240501 | 50-335 P |
| UHRIG, R E | 8303240569 | 50-389 S |
| UHRIG, R E | 8303240578 | 50-389 S |
| UHRIG, R E | 8303250010 | 50-389 F |
| UHRIG, R E | 8303250017 | 50-389 A |
| UHRIG, R E | 8303250075 | 50-250 P |
| UHRIG, R E | 8303250085 | 50-389 A |
| UHRIG, R E | 8303250096 | 50-389 A |
| UHRIG, R E | 8303250128 | 50-389 F |
| UHRIG, R E | 8303280028 | 50-389 R |
| UHRIG, R E | 8303280087 | 50-389 A |
| UHRIG, R E | 8303280206 | 50-389 A |
| UHRIG, R E | 8303280278 | 50-335 P |
| UHRIG, R E | 8303290433* | 50-250 G |
| UHRIG, R E | 8303290472 | 50-389 A |
| UHRIG, R E | 8303300143 | 50-335 F |
| UHRIG, R E | 8303300224 | 50-389 A |
| UHRIG, R E | 8303300249 | 50-335 P |
| UHRIG, R E | 8303300273 | 50-389 A |
| UHRIG, R E | 8303300301 | 50-250 P |
| UHRIG, R E | 8303300398 | 50-250 P |
| UHRIG, R E | 8303310057 | 50-335 P |
| UHRIG, R E | 8303310403 | 50-389 A |
| ULECK, R B | 8303300277 | WASTE MGT |
| ULIE, J | 8303140406* | 50-266 G |
| ULLRICH, J | 8303150426* | 50-373 R |
| UNDERWOOD, R H | 8303030572 | PT21 |
| UNRUH, J F | 8303290631* | TOPREP |
| UPPULURI, V R R | 8303290683 | NUREG |
| UPRIGHT, C M | 8303210662* | 50-321 G |
| UPRIGHT, C M | 8303210739* | 50-400 G |
| UPTON, E | 8303110266* | 50-389 A |
| URBAN, P A | 8303010447* | 50-352 A |
| UTLEY, E E | 8303010420 | 50-324 P |
| UTLEY, E E | 8303010452 | 50-325 P |
| UTLEY, E E | 8303090358 | 50-324 F |
| UTLEY, E E | 8303290491 | 50-261 P |
| VADEN, J | 8303290017* | WASTE MGT |
| VAN ALLEN, S E | 8303100065 | 50-263 P |
| VAN ALLEN, S E | 8303230298 | 50-263 P |
| VAN BRUNT, E E | 8303040268 | 50-528 S |
| VAN BRUNT, E E | 8303040441 | 50-528 S |
| VAN BRUNT, E E | 8303040444 | 50-528 S |
| VAN BRUNT, E E | 8303040452 | 50-528 A |
| VAN BRUNT, E E | 8303040563 | 50-528 S |
| VAN BRUNT, E E | 8303040578 | 50-528 S |
| VAN BRUNT, E E | 8303070040 | 50-528 A |
| VAN BRUNT, E E | 8303070058 | 50-528 A |
| VAN BRUNT, E E | 8303080146 | 50-528 S |
| VAN BRUNT, E E | 8303080235 | 50-528 S |
| VAN BRUNT, E E | 8303080414 | 50-528 S |
| VAN BRUNT, E E | 8303080439 | 50-528 S |
| VAN BRUNT, E E | 8303090194 | 50-528 A |
| VAN BRUNT, E E | 8303100345 | 50-528 E |
| VAN BRUNT, E E | 8303140191 | 50-528 S |
| VAN BRUNT, E E | 8303140316 | 50-528 S |
| VAN BRUNT, E E | 8303140332 | 50-528 S |
| VAN BRUNT, E E | 8303140372 | 50-528 S |
| VAN BRUNT, E E | 8303140455 | 50-529 S |
| VAN BRUNT, E E | 8303140480 | 50-528 S |
| VAN BRUNT, E E | 8303170114 | 50-528 E |
| VAN BRUNT, E E | 8303220017 | 50-528 G |
| VAN BRUNT, E E | 8303220161 | 50-528 S |
| VAN BRUNT, E E | 8303220180 | 50-528 S |
| VAN BRUNT, E E | 8303220186 | 50-528 S |
| VAN BRUNT, E E | 8303220191 | 50-529 S |
| VAN BRUNT, E E | 8303220204 | 50-528 S |
| VAN BRUNT, E E | 8303280168 | 50-528 A |
| VAN BRUNT, E E | 8303290490 | 50-528 A |
| VAN BRUNT, E E | 8303300678* | 50-528 F |
| VAN DOORN, P K | 8303210716* | 50-413 G |
| VAN ROOYEN, D | 8303040138 | RES |
| VAN ROOYEN, D | 8303290792 | RES |
| VAN VLIET, J | 8303110414 | 50-289 P |
| VAN VLIET, J | 8303170136 | 50-269 P |
| VAN VLIET, J | 8303300608 | 50-289 P |
| VAN VLIET, J A | 8303100016 | 50-289 P |
| VAN VLIET, J A | 8303150677 | 50-289 P |
| VAN VLIET, J A | 8303180473 | 50-289 F |
| VAN VLIET, J A | 8303210222 | 50-289 P |
| VAN VLIET, J A | 8303290082 | 50-289 P |
| VANDEL, T E | 8303210676* | 50-482 G |
| VANDEWALLE, D J | 8303180492 | 50-255 F |
| VANDEWALLE, D J | 8303210150 | 50-155 F |
| VANDEWALLE, D J | 8303210157 | 50-155 P |
| VANDEWALLE, D J | 8303220065* | 50-255 G |
| VANDEWALLE, D J | 8303220099 | 50-255 P |
| VANDEWALLE, D J | 8303220143* | 50-255 P |
| VANDEWALLE, D J | 8303280026 | 50-255 G |
| VANDEWALLE, D J | 8303280029 | 50-155 P |
| VARCOLIK, F | 8303230282 | NUREG |
| VARELA, A A | 8303100317* | 50-388 G |
| VARELA, A A | 8303240467* | 50-322 G |
| VARGA, S A | 8303010117 | 50-305 P |
| VARGA, S A | 8303010128 | 50-315 P |
| VARGA, S A | 8303020432 | 50-315 P |
| VARGA, S A | 8303020441* | 50-315 P |
| VARGA, S A | 8303020448* | 50-315 P |
| VARGA, S A | 8303030199* | 50-348 P |
| VARGA, S A | 8303030210* | 50-348 P |
| VARGA, S A | 8303040057 | 50-261 P |
| VARGA, S A | 8303040076* | 50-261 P |
| VARGA, S A | 8303040111 | 50-250 P |
| VARGA, S A | 8303040313 | 50-334 P |
| VARGA, S A | 8303040400 | 50-250 P |
| VARGA, S A | 8303090285 | 50-295 P |
| VARGA, S A | 8303090289 | 50-364 G |
| VARGA, S A | 8303090311 | 50-305 F |
| VARGA, S A | 8303100396 | 50-280 P |
| VARGA, S A | 8303100401* | 50-280 P |
| VARGA, S A | 8303100404* | 50-280 P |
| VARGA, S A | 8303100509 | 50-305 G |
| VARGA, S A | 8303110003* | 50-295 P |
| VARGA, S A | 8303110018* | 50-295 P |
| VARGA, S A | 8303110055 | 50-250 P |
| VARGA, S A | 8303110063* | 50-250 P |
| VARGA, S A | 8303110071* | 50-250 P |
| VARGA, S A | 8303110104* | 50-261 P |
| VARGA, S A | 8303110117* | 50-261 P |
| VARGA, S A | 8303110122 | 50-280 P |
| VARGA, S A | 8303110131* | 50-280 P |
| VARGA, S A | 8303110138* | 50-280 P |
| VARGA, S A | 8303150079* | 50-280 P |
| VARGA, S A | 8303150092* | 50-280 P |
| VARGA, S A | 8303150099 | 50-334 P |
| VARGA, S A | 8303160671 | 50-261 P |
| VARGA, S A | 8303180024 | 50-315 F |
| VARGA, S A | 8303180028 | 50-334 F |
| VARGA, S A | 8303180032 | 50-286 F |
| VARGA, S A | 8303210242 | 50-305 P |
| VARGA, S A | 8303230102 | 50-295 F |
| VARGA, S A | 8303230396 | 50-250 P |
| VARGA, S A | 8303230401* | 50-250 P |
| VARGA, S A | 8303230407* | 50-250 P |
| VARGA, S A | 8303240290 | 50-272 F |
| VARGA, S A | 8303240296 | 50-250 P |
| VARGA, S A | 8303280322 | 50-272 P |
| VARGA, S A | 8303290324* | 50-272 P |
| VARGA, S A | 8303290327* | 50-272 P |
| VARGA, S A | 8303290349 | 50-250 F |
| VARGA, S A | 8303290005 | 50-250 P |
| VARGA, S A | 8303290009 | 50-247 P |
| VARGA, S A | 8303290027 | 50-286 P |
| VARGA, S A | 8303290033 | 50-295 P |
| VARGA, S A | 8303290080 | 50-280 P |
| VARGA, S A | 8303290117* | 50-250 P |
| VARGA, S A | 8303290132* | 50-250 P |
| VARGA, S A | 8303290157 | 50-272 P |
| VARGA, S A | 8303290256 | 50-334 F |
| VARGA, S A | 8303290361 | 50-280 F |
| VARGA, S A | 8303290586 | 50-250 P |
| VARGA, S A | 8303290597 | 50-315 F |
| VARGA, S A | 8303290639 | 50-280 P |
| VARGA, S A | 8303290647* | 50-280 P |
| VARGA, S A | 8303290670* | 50-280 P |
| VARGA, S A | 8303290800 | 50-315 P |
| VARGA, S A | 8303290836 | 50-295 P |
| VARGA, S A | 8303300005 | 50-334 P |
| VARGA, S A | 8303300012* | 50-334 P |
| VARGA, S A | 8303300019* | 50-334 P |
| VARGA, S A | 8303300031 | 50-261 P |
| VARGA, S A | 8303300165 | 50-295 P |
| VARGA, S A | 8303300180 | 50-305 P |
| VARGA, S A | 8303300180 | 50-305 P |
| VARGA, S A | 8303300197 | 50-280 F |
| VARGA, S A | 8303300198 | 50-348 P |
| VARGA, S A | 8303300248 | 50-295 F |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| VARGA, S. A. | 8303300786 | 50-315 F |
| VARGA, S. A. | 8303310016 | 50-305 P |
| VARNER, L. S. | 8303230380* | CONTRACT |
| VASSALLO, D. B | 8303020411 | 50-271 P |
| VASSALLO, D. B | 8303020463 | 50-298 P |
| VASSALLO, D. B | 8303030063 | 50-259 P |
| VASSALLO, D. B | 8303030068* | 50-259 P |
| VASSALLO, D. B | 8303030085* | 50-259 P |
| VASSALLO, D. B | 8303090257* | 50-271 P |
| VASSALLO, D. B | 8303090270* | 50-271 P |
| VASSALLO, D. B | 8303160076 | 50-271 F |
| VASSALLO, D. B | 8303170213 | 50-220 F |
| VASSALLO, D. B | 8303180073* | 50-265 P |
| VASSALLO, D. B | 8303180093* | 50-265 P |
| VASSALLO, D. B | 8303180640 | 50-331 F |
| VASSALLO, D. B | 8303230305 | 50-263 F |
| VASSALLO, D. B | 8303230523 | 50-333 P |
| VASSALLO, D. B | 8303250114 | 50-298 P |
| VASSALLO, D. B | 8303250116* | 50-298 P |
| VASSALLO, D. B | 8303250119* | 50-298 P |
| VASSALLO, D. B | 8303280093 | 50-298 P |
| VASSALLO, D. B | 8303280107 | 50-293 P |
| VASSALLO, D. B | 8303280123 | 50-333 P |
| VASSALLO, D. B | 8303290021 | 50-220 P |
| VASSALLO, D. B | 8303290030* | 50-220 P |
| VASSALLO, D. B | 8303290034* | 50-220 P |
| VASSALLO, D. B | 8303290100 | 50-263 P |
| VASSALLO, D. B | 8303290153 | 50-333 P |
| VASSALLO, D. B | 8303290158* | 50-333 P |
| VASSALLO, D. B | 8303290164* | 50-333 P |
| VASSALLO, D. B | 8303290171 | 50-331 P |
| VASSALLO, D. B | 8303290177* | 50-331 P |
| VASSALLO, D. B | 8303290182* | 50-331 P |
| VASSALLO, D. B | 8303290188 | 50-293 P |
| VASSALLO, D. B | 8303290193* | 50-293 P |
| VASSALLO, D. B | 8303290201* | 50-293 P |
| VASSALLO, D. B | 8303290211 | 50-220 P |
| VASSALLO, D. B | 8303290538* | 50-325 P |
| VASSALLO, D. B | 8303290553 | 50-324 P |
| VASSALLO, D. B | 8303290558* | 50-324 P |
| VASSALLO, D. B | 8303290562* | 50-324 P |
| VASSALLO, D. B | 8303290603 | 50-293 P |
| VASSALLO, D. B | 8303290663 | 50-254 P |
| VASSALLO, D. B | 8303300014 | 50-271 P |
| VASSALLO, D. B | 8303300026 | 50-254 P |
| VASSALLO, D. B | 8303300047 | 50-324 P |
| VASSALLO, D. B | 8303300094 | 50-259 P |
| VASSALLO, D. B | 8303300163 | 50-331 P |
| VASSALLO, D. B | 8303300213 | 50-298 P |
| VASSALLO, D. B | 8303300228* | 50-259 P |
| VASSALLO, D. B | 8303300299 | 50-259 P |
| VASSALLO, D. B | 8303300308* | 50-259 P |
| VASSALLO, D. B | 8303300325* | 50-259 P |
| VASSALLO, D. B | 8303300613 | 50-220 P |
| VASSALLO, D. B | 8303300625 | 50-324 P |
| VASSALLO, D. B | 8303300653* | 50-265 P |
| VASSALLO, D. B | 8303300660* | 50-265 P |
| VASSALLO, D. B | 8303300671* | 50-331 P |
| VASSALLO, D. B | 8303300705* | 50-331 P |
| VAUGHAN, C. M. | 8303010304 | 70-1113 |
| VAUGHAN, C. M. | 8303030271* | 71-4909 |
| VAUGHAN, C. M. | 8303210452 | 70-1113 |
| VEALE, F. J. | 8303010026 | 70-33 |
| VEALE, F. J. | 8303010036* | 70-33 |
| VENHUIZEN, J. R | 8303140628 | NUREG |
| VERMA, T. R. | 8303290616 | WASTE MGT |
| VERMA, T. R. | 8303290623 | WASTE MGT |
| VERMA, T. R. | 8303290630 | WASTE MGT |
| VERMA, T. R. | 8303290658 | WASTE MGT |
| VERMA, T. R. | 8303300264 | WASTE MGT |
| VERMA, T. R. | 8303300271 | WASTE MGT |
| VERNETSON, W. G. | 8303310238 | 50-83 V |
| VERRELLI, D. | 8303010479 | 50-390 Q |
| VERRELLI, D. | 8303150388 | 50-327 Q |
| VERRELLI, D. | 8303150565 | 50-261 Q |
| VERRELLI, D. M. | 8303010134 | 50-400 Q |
| VERRELLI, D. M. | 8303010241 | 50-390 Q |
| VERRELLI, D. M. | 8303010289 | 50-348 Q |
| VERRELLI, D. M. | 8303010330 | 50-390 Q |
| VERRELLI, D. M. | 8303010342 | 50-390 Q |
| VERRELLI, D. M. | 8303010346 | 50-390 Q |
| VERRELLI, D. M. | 8303010383 | 50-438 Q |
| VERRELLI, D. M. | 8303010414 | 50-261 Q |
| VERRELLI, D. M. | 8303010429 | 50-327 Q |
| VERRELLI, D. M. | 8303010432 | 50-348 Q |
| VERRELLI, D. M. | 8303010438* | 50-327 Q |
| VERRELLI, D. M. | 8303010466 | 50-261 Q |
| VERRELLI, D. M. | 8303010494 | 50-416 Q |
| VERRELLI, D. M. | 8303010497* | 50-416 Q |
| VERRELLI, D. M. | 8303010511 | 50-327 Q |
| VERRELLI, D. M. | 8303210331 | 50-400 Q |
| VERRELLI, D. M. | 8303210338 | 50-417 Q |
| VERRELLI, D. M. | 8303210349 | 50-390 Q |
| VERRELLI, D. M. | 8303210389 | 50-416 Q |
| VERRELLI, D. M. | 8303210392 | 50-390 Q |
| VERRELLI, D. M. | 8303210403 | 50-324 Q |
| VERRELLI, D. M. | 8303210426 | 50-348 Q |
| VERRELLI, D. M. | 8303210446 | 50-400 Q |
| VERRELLI, D. M. | 8303210494 | 50-83 Q |
| VERRELLI, D. M. | 8303210564 | 50-416 Q |
| VERRELLI, D. M. | 8303210572 | 50-390 Q |
| VERRELLI, D. M. | 8303210584 | 50-348 Q |
| VERRELLI, D. M. | 8303210587* | 50-416 Q |
| VERRELLI, D. M. | 8303210686 | 50-416 Q |
| VERRELLI, D. M. | 8303210689 | 50-400 Q |
| VERRELLI, D. M. | 8303210705* | 50-400 Q |
| VERRELLI, D. M. | 8303210723 | 50-348 Q |
| VERRELLI, D. M. | 8303210729 | 50-400 Q |
| VETERE, L. A. | 8303150408 | 50-247 Q |
| VIETTI, A. | 8303010115* | 50-508 A |
| VIETTI, A. | 8303170009 | 50-508 A |
| VIETTI, A. | 8303230276 | 50-508 A |
| VILLAVALVA | 8303240153 | I&E |
| VINCELETTE, M. D. | 8303300231 | 40-8681 |
| VISSING, G. | 8303010698 | 50-269 P |
| VISSING, G. S. | 8303300733 | 50-269 P |
| VISSING, G. S. | 8303310089 | COMMISSION |
| VISSING, G. S. | 8303310551 | 50-269 P |
| VITO, D. J. | 8302090307* | 50-250 P |
| VOGT, D. | 8303310366 | NUREG |
| VOGT-LOWELL, R. | 8303010630* | 50-250 Q |
| VOGT-LOWELL, R. | 8303210743* | 50-250 Q |
| VOIGT, H. H. | 8303170362 | 50-341 Q |
| VOIGT, H. H. | 8303170382 | 50-341 Q |
| VOIGT, H. H. | 8303170362 | 50-341 Q |
| VOLLMER, R. H. | 8108050060* | 50-387 P |
| VOLLMER, R. H. | 8302040548* | 50-387 P |
| VOLLMER, R. H. | 8302040555* | 50-387 P |
| VOLLMER, R. H. | 8303110227 | 50-322 T |
| VORDERBRUEGGER | 8303040361* | 50-528 Q |
| WADE, D. H. | 8303230234* | 50-445 Q |
| WADE, P. B. | 8303250027* | 50-368 S |
| WADE, P. B. | 8303280187* | 50-368 S |
| WADE, P. B. | 8303280217* | 50-368 S |
| WAGNER, A. G. | 8303010590* | 50-416 Q |
| WAGNER, A. G. | 8303210752* | 50-416 Q |
| WAGNER, D. | 8303100167 | 50-354 A |
| WAGNER, D. | 8303280094 | 50-354 A |
| WAGNER, G. P. | 8303170424 | 50-254 R |
| WAGNER, M. E. | 8303020023 | 50-460 Q |
| WAGNER, M. E. | 8303100166 | 50-460 Q |
| WAGNER, P. C. | 8303150001 | 50-267 P |
| WAGNER, R. J. | 8303160155 | RES |
| WAGNER, R. J. | 8303160164 | RES |
| WAKEFIELD, J. | 8303030782* | CONTRACT |
| WALDORF, J. M. | 8303040351* | 50-324 P |
| WALKER, B. | 8303300585* | CONTRACT |
| WALKER, J. R. | 8303100053* | 50-327 F |
| WALKER, R. | 8303080003 | 50-374 S |
| WALKER, R. D. | 8303030446* | 50-10 Q |
| WALKER, R. D. | 8303080042* | 50-263 Q |
| WALKER, R. D. | 8303080411* | 50-331 Q |
| WALKER, R. D. | 8303170377* | 50-10 Q |
| WALKER, R. D. | 8303170495* | 50-263 Q |
| WALKER, R. D. | 8303170519* | 50-373 Q |
| WALKER, R. D. | 8303170540* | 50-373 Q |
| WALKER, R. D. | 8303170551* | 50-254 Q |
| WALKER, R. D. | 8303170557* | 50-10 Q |
| WALKER, R. D. | 8303220116* | 50-237 Q |
| WALKER, R. D. | 8303240372* | 50-237 Q |
| WALKER, R. D. | 8303240597* | 50-10 Q |
| WALSH, J. F. | 8303030373 | 50-440 Q |
| WAMBACH, T. V. | 8303030207* | 50-155 P |
| WAMBACH, T. V. | 8303080127* | 50-213 P |
| WAMBACH, T. V. | 8303090271* | 50-213 P |
| WAMBACH, T. V. | 8303100008 | MISC |
| WAMBACH, T. V. | 8303310089 | COMMISSION |
| WANG, R. C. | 8303090520 | NUREG |
| WARD, E. C. | 8303100186* | 50-263 F |
| WARD, E. C. | 8303100193* | 50-263 F |
| WARD, E. C. | 8303300681* | 50-263 F |
| WARD, K. D. | 8303080270* | 50-315 Q |
| WARD, K. D. | 8303240517* | 50-440 Q |
| WARD, P. E. | 8303090691* | 50-263 F |
| WARD, W. J. | 8303110068* | 50-334 S |
| WAREMBOURG, D. | 8303010273 | 50-267 R |
| WAREMBOURG, D. | 8303080056 | 50-267 R |
| WAREMBOURG, D. | 8303100030* | 50-267 F |
| WAREMBOURG, D. | 8303150235 | 50-267 R |
| WAREMBOURG, D. | 8303150247 | 50-267 S |
| WAREMBOURG, D. | 8303150348 | 50-267 R |
| WAREMBOURG, D. | 8303210546 | 50-267 S |
| WAREMBOURG, D. | 8303210629 | 50-267 S |
| WAREMBOURG, D. | 8303250006 | 50-267 R |
| WAREMBOURG, D. | 8303280036 | 50-267 P |
| WAREMBOURG, D. | 8303280240 | 50-267 S |
| WAREMBOURG, D. | 8303280254 | 50-267 S |
| WAREMBOURG, D. W. | 8303100025* | 50-267 F |
| WARMAN, E. A. | 8303160650* | ACRS |
| WARNICK, R. F. | 8303090095 | 50-358 A |
| WARNICK, R. F. | 8303090208 | 50-358 A |
| WARNICK, R. F. | 8303140475* | 50-358 Q |
| WARNICK, R. F. | 8303170428 | 50-329 Q |
| WARNICK, R. F. | 8303170433* | 50-329 Q |
| WARNICK, R. F. | 8303210295* | 50-329 A |
| WARNICK, R. F. | 8303210301* | 50-329 A |
| WARNICK, R. F. | 8303280118 | 50-329 E |
| WASHINGTON, K. E. | 8303010247* | 50-313 Q |
| WATERS, J. R. | 8303170506* | 50-295 Q |
| WATFORD, P. S. | 8303240389* | 50-373 S |
| WATKINS, L. B. | 8303040312 | 50-458 Q |
| WATKINS, L. B. | 8303300329 | 50-458 Q |
| WATSON, M. E. | 8303030665* | 50-331 S |
| WATSON, M. E. | 8303140416* | 50-331 S |
| WATSON, M. E. | 8303140428* | 50-331 S |
| WATSON, M. E. | 8303140449* | 50-331 S |
| WATTS, K. | 8303090513 | 40-4492 |
| WEAKLEY, S. A. | 8303150680 | NUREG |
| WEAVER, W. L. | 8303180613 | RES |
| WEAVER, W. L. | 8303180672 | RES |
| WEAVER, W. L. | 8303180699 | RES |
| WEAVER, W. L. | 8303210186 | RES |
| WEBB, S. W. | 8303100092* | 50-440 A |
| WEBB, W. A. | 8303290292* | CONTRACT |
| WEBSTER, C. S. | 8303290698 | NUREG |
| WEEKS, E. D. | 8303080175 | 50-133 R |
| WEEKS, E. D. | 8303150552 | 50-133 R |
| WEHRING, B. W. | 8303030212 | 50-151 R |
| WEIMER, R. D. | 8303170193* | 50-171 I |
| WEIN, R. | 8303020126* | 50-247 T |
| WEINKAM, E. J. | 8303090451 | 50-458 A |
| WEINKAM, E. J. | 8303110148 | 50-322 A |
| WEINSTEIN, E. | 8303090505 | NUREG |
| WEISE, K. E. | 8303100092* | 50-440 A |
| WEISE, S. | 8303210386* | 50-261 Q |
| WEISS, B. | 8303240036 | I&E |
| WEISS, D. | 8303280143 | 27-48 |
| WEISS, E. R. | 8303070139 | 50-289 Q |
| WEISS, E. R. | 8303070145* | 50-289 Q |
| WEISS, E. R. | 8303070145* | 50-289 Q |
| WEISS, E. R. | 8303170421 | 70-143 |
| WEISS, E. R. | 8303170421 | 70-143 |
| WEISS, E. R. | 8303170447 | 50-289 Q |
| WEISS, E. R. | 8303170447 | 50-289 Q |
| WEISS, E. R. | 8303180393 | 50-247 Q |
| WEISS, E. R. | 8303220221* | 50-537 Q |
| WEISS, E. R. | 8303220221* | 50-537 Q |
| WEISS, E. R. | 8303220221* | 50-537 Q |
| WEISS, E. R. | 8303250165 | 50-537 Q |
| WEISS, E. R. | 8303250165 | 50-537 Q |
| WEISS, E. R. | 8303250165 | 50-537 Q |
| WELDON, C. | 8303280097 | NUREG |
| WELDON, C. | 8303280114 | NUREG |
| WELLS, D. A. | 8303010631 | 50-341 S |
| WELLS, D. A. | 8303080072 | 50-341 Q |
| WELLS, D. A. | 8303220184* | 50-341 Q |
| WEN, P. | 8303240528* | 50-247 Q |
| WENDERLICH, R. L. | 8303160265* | 50-318 S |
| WENDERLICH, R. L. | 8303210621* | 50-317 S |
| WENGER, G. L. | 8303010403* | 50-454 T |
| WENGER, L. W. | 8303160274* | 50-317 S |
| WENNEMO, S. E. | 8303160418* | 50-324 P |
| WENNER, T. J. | 8303100082* | 50-265 P |
| WENSLAWSKI, F. | 8303180482 | 50-275 S |
| WENSLAWSKI, F. | 8303290468* | 50-206 Q |

# PERSONAL AUTHOR INDEX

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY | |
|---|---|---|---|
| WENSLAWSKI, F. | 8303290480* | 50-141 | Q |
| WENSLAWSKI, F. A. | 8303040362* | 50-344 | Q |
| WENSLAWSKI, F. A. | 8303180403* | 50-312 | Q |
| WENSLAWSKI, F. A. | 8303180407* | 50-312 | Q |
| WENSLAWSKI, F. A. | 8303290257* | 50-528 | Q |
| WENSLAWSKI, F. A. | 8303290460* | 50-344 | Q |
| WENSLAWSKI, F. A. | 8303290463* | 50-344 | Q |
| WENZEL, A. C. | 8303090659 | NUREG | |
| WENZINGER, E. C. | 8303240136 | REGOD | |
| WERNER, R. P. | 8303010385 | 50-245 | P |
| WERNER, R. P. | 8303010386 | 50-245 | P |
| WERNER, R. P. | 8303080465 | 50-245 | P |
| WERNER, R. P. | 8303080465 | 50-245 | P |
| WERNER, R. P. | 8303220096 | 50-213 | F |
| WEST, D. | 8303210402* | 50-335 | S |
| WEST, S. | 8303290574* | CONTRACT | |
| WESTAFER, G. R. | 8303040430 | 50-302 | S |
| WESTAFER, G. R. | 8303040544 | 50-302 | Q |
| WESTAFER, G. R. | 8303080077 | 50-302 | F |
| WESTAFER, G. R. | 8303100200 | 50-302 | S |
| WESTAFER, G. R. | 8303100290 | 50-302 | P |
| WESTAFER, G. R. | 8303110163 | 50-302 | F |
| WESTAFER, G. R. | 8303110232 | 50-302 | F |
| WESTAFER, G. R. | 8303110234 | 50-302 | Q |
| WESTAFER, G. R. | 8303150407 | 50-302 | P |
| WESTAFER, G. R. | 8303160318 | 50-302 | R |
| WESTAFER, G. R. | 8303160471 | 50-302 | S |
| WESTAFER, G. R. | 8303170319 | 50-302 | Q |
| WESTAFER, G. R. | 8303170492 | 50-302 | Q |
| WESTAFER, G. R. | 8303180185 | 50-302 | S |
| WESTAFER, G. R. | 8303180253 | 50-302 | S |
| WESTAFER, G. R. | 8303180328 | 50-302 | Q |
| WESTAFER, G. R. | 8303210731 | 50-302 | Q |
| WESTAFER, G. R. | 8303220095 | 50-302 | Q |
| WESTAFER, G. R. | 8303220158 | 50-302 | P |
| WESTAFER, G. R. | 8303240098 | 50-302 | Q |
| WESTAFER, G. R. | 8303250030 | 50-302 | P |
| WESTAFER, G. R. | 8303290477 | 50-302 | Q |
| WESTAFER, G. R. | 8303290482 | 50-302 | P |
| WESTAFER, G. R. | 8303290839* | 50-302 | F |
| WESTBROOK, K. B. | 8303090421 | 40-8786 | |
| WESTERMAN, T. F. | 8303010410* | 50-298 | Q |
| WESTERMAN, T. F. | 8303010451* | 50-445 | Q |
| WESTERMAN, T. F. | 8303070088* | 50-267 | Q |
| WESTERMAN, T. F. | 8303150008* | 50-267 | P |
| WESTERMAN, T. F. | 8303150530* | 50-445 | Q |
| WESTERMAN, T. F. | 8303250022* | 50-267 | Q |
| WESTOVER, A. T. | 8303090295 | 50-341 | H |
| WETHY, C. M. | 8303240130* | 50-335 | F |
| WETHY, C. M. | 8303310107 | 50-389 | A |
| WETHY, C. M. | 8303310115 | 50-389 | A |
| WETHY, C. M. | 8303310471* | 50-335 | F |
| WETTERHAHN, M. J. | 8303040439 | 50-352 | Q |
| WETTERHAHN, M. J. | 8303040439 | 50-352 | Q |
| WETTERHAHN, M. J. | 8303290438 | 50-352 | Q |
| WETTERHAHN, M. J. | 8303290438 | 50-352 | Q |
| WETTERHAHN, M. J. | 8303290527 | 50-358 | Q |
| WETTERHAHN, M. J. | 8303290527 | 50-358 | Q |
| WHARTON, R. J. | 8303020001 | 50-206 | P |
| WHICHER, J. M. | 8303070034 | 30-454 | T |
| WHICHER, J. M. | 8303070034 | 50-454 | T |
| WHICHER, J. M. | 8303070034 | 50-454 | T |
| WHICHER, J. M. | 8303070034 | 50-454 | T |
| WHICHER, J. M. | 8303070155 | 50-454 | Q |
| WHICHER, J. M. | 8303070155 | 50-454 | Q |
| WHICHER, J. M. | 8303070155 | 50-454 | Q |
| WHICHER, J. M. | 8303070155 | 50-454 | Q |
| WHICHER, J. M. | 8303220195 | 50-454 | T |
| WHITE, A. | 8303210102 | 50-483 | F |
| WHITE, J. E. | 8303280066 | NUREG | |
| WHITE, J. K. | 8303110242 | 50-456 | F |
| WHITE, J. R. | 8303100305* | 50-293 | Q |
| WHITE, J. R. | 8303240511 | 50-271 | S |
| WHITE, J. R. | 8303280267* | 50-272 | Q |
| WHITE, L. D. | 8303040342 | 50-244 | S |
| WHITE, L. D. | 8303140426 | 50-244 | R |
| WHITE, R. L. | 8211050147* | 50-346 | P |
| WHITEACRE, M. | 8303010247* | 50-313 | Q |
| WHITED, P. J. | 8303090174 | FOIA | |
| WHITENER, H. L. | 8303210487* | 50-321 | Q |
| WHITENER, H. L. | 8303210668* | 50-321 | Q |
| WHITESIDES, G. E. | 8303030318 | RES | |
| WHITMAN, D. | 8303290137* | 50-298 | F |
| WHITMAN, G. D. | 8303290673 | NUREG | |
| WHITMAN, G. D. | 8303300638 | NUREG | |
| WHITNEY, G. G. | 8303010658 | 50-293 | S |
| WHITNEY, G. G. | 8303080513* | 50-293 | R |
| WHITNEY, G. G. | 8303140598* | 50-293 | S |
| WHITNEY, G. G. | 8303150580* | 50-293 | R |
| WHITNEY, G. G. | 8303180504* | 50-293 | S |
| WHITNEY, G. G. | 8303250074* | 50-293 | S |
| WHITNEY, G. G. | 8303250121* | 50-293 | S |
| WHITTEMORE, M. C. | 8303140192* | FOIA | |
| WICK, F. A. | 8303290826 | WASTE MGT | |
| WICKS, F. E. | 8303240483 | 50-225 | R |
| WIDMER, R. R. | 8303240037 | 70-1193 | |
| WIDNER, T. E. | 8303140425* | 50-387 | R |
| WIEBE, J. | 8303280173* | 50-320 | Q |
| WIEDEMAN, D. G. | 8302010356 | 70-2837 | |
| WIEDEMAN, D. G. | 8302010358* | 70-2837 | |
| WIEDEMAN, D. G. | 8303080487 | I&E | |
| WIEDEMAN, D. G. | 8303170448 | 70-2837 | |
| WIEDEMAN, D. G. | 8303210378 | I&E | |
| WIEDENBECK, M. G. | 8303220407 | NUREG | |
| WIEDER, A. V. | 8303010632* | 70-734 | |
| WIEDER, A. V. | 8303240564* | 70-1257 | |
| WIESEMANN, R. A. | 8302160332* | TOPREP | |
| WIESEMANN, R. A. | 8303070150* | TOPREP | |
| WIESEMANN, R. A. | 8303160395* | 50-313 | P |
| WIESEMANN, R. A. | 8303250039* | TOPREP | |
| WIESEMANN, R. A. | 8303290378* | 50-416 | P |
| WIESEMANN, R. A. | 8303300547* | TOPREP | |
| WIESEMANN, R. A. | 8303310287* | 50-282 | P |
| WIGGINS, J. | 8303030080 | 50-271 | S |
| WIGGINS, J. | 8303290367 | 50-271 | S |
| WIGGINTON, D. | 8303100159 | 50-315 | P |
| WIGGINTON, D. L. | 8303170125 | 50-295 | P |
| WIKTOR, D. | 8303220290 | 50-155 | Q |
| WIKTOR, D. L. | 8303080121 | 50-155 | Q |
| WILBORN, L. | 8303180421* | 50-382 | Q |
| WILCOVE, M. N. | 8303070132 | 50-329 | Q |
| WILCOVE, M. N. | 8303140374 | 50-329 | T |
| WILCOVE, M. N. | 8303140432* | 50-329 | T |
| WILDANGER, E. | 8303280097 | NUREG | |
| WILDANGER, E. | 8303280114 | NUREG | |
| WILDANGER, W. | 8303250113 | NUREG | |
| WILDE, N. | 8303240167 | RES | |
| WILDE, R. M. | 8303100434* | FOIA | |
| WILDE, R. M. | 8303180553 | 40-2061 | |
| WILGUS, D. | 8303080265* | 50-254 | S |
| WILHOIT, J. M. | 8303030765* | 50-275 | P |
| WILKINSON, B. W. | 8303150267 | 50-294 | R |
| WILLETT, D. J. | 8303040446* | 50-344 | Q |
| WILLETT, D. J. | 8303080210* | 50-397 | Q |
| WILLETT, D. J. | 8303150501* | 50-397 | Q |
| WILLIAMS, B. E. | 8303240146 | RES | |
| WILLIAMS, C. B. | 8303100460 | NUREG | |
| WILLIAMS, C. B. | 8303100358 | NUREG | |
| WILLIAMS, C. C. | 8303140406* | 50-266 | Q |
| WILLIAMS, C. C. | 8303220050* | 50-481 | Q |
| WILLIAMS, C. C. | 8303220253* | 50-440 | Q |
| WILLIAMS, F. C. | 8303240522 | 50-329 | Q |
| WILLIAMS, F. N. | 8303240415* | 50-29 | P |
| WILLIAMS, J. W. | 8303080402 | 50-250 | R |
| WILLIAMS, J. W. | 8303080422 | 50-335 | S |
| WILLIAMS, J. W. | 8303150539 | 50-250 | R |
| WILLIAMS, J. W. | 8303160575 | 50-335 | S |
| WILLIAMS, J. W. | 8303210397 | 50-335 | S |
| WILLIAMS, J. W. | 8303210550 | 50-250 | S |
| WILLIAMS, R. C. | 8303100416 | NUREG | |
| WILLIAMS, R. E. | 8303090033 | 40-8745 | |
| WILLIAMS, R. E. | 8303090595 | 40-8743 | |
| WILLIAMS, S. E. | 8303140203* | 50-289 | R |
| WILMOTH, B. | 8303290413* | CONTRACT | |
| WILSON, B. | 8303040075 | XPORTLIC | |
| WILSON, B. | 8303040133 | XPORTLIC | |
| WILSON, B. D. | 8303040055 | XPORTLIC | |
| WILSON, B. D. | 8303040060* | XPORTLIC | |
| WILSON, B. D. | 8303040068* | XPORTLIC | |
| WILSON, B. D. | 8303150685 | XPORTLIC | |
| WILSON, B. D. | 8303150701 | XPORTLIC | |
| WILSON, B. D. | 8303230003 | XPORTLIC | |
| WILSON, B. D. | 8303290094 | XPORTLIC | |
| WILSON, J. | 8303080037* | 50-280 | R |
| WILSON, J. | 8303150376* | 50-280 | R |
| WILSON, J. H. | 8303180503 | 50-382 | A |
| WILSON, J. L. | 8303010460 | 50-280 | S |
| WILSON, J. L. | 8303010469* | 50-280 | S |
| WILSON, J. L. | 8303040568 | 50-280 | S |
| WILSON, J. L. | 8303040584* | 50-280 | S |
| WILSON, J. L. | 8303140523 | 50-281 | S |
| WILSON, J. L. | 8303140532* | 50-281 | S |
| WILSON, J. L. | 8303140542 | 50-280 | S |
| WILSON, J. L. | 8303140543* | 50-281 | S |
| WILSON, J. L. | 8303140551* | 50-280 | S |
| WILSON, J. L. | 8303140560* | 50-280 | S |
| WILSON, J. L. | 8303150138 | 50-280 | S |
| WILSON, J. L. | 8303150166* | 50-280 | S |
| WILSON, J. L. | 8303150175* | 50-280 | S |
| WILSON, J. L. | 8303150184* | 50-280 | S |
| WILSON, J. L. | 8303160149 | 50-281 | S |
| WILSON, J. L. | 8303160157* | 50-281 | S |
| WILSON, J. L. | 8303160165* | 50-281 | S |
| WILSON, J. L. | 8303160194 | 50-280 | S |
| WILSON, J. L. | 8303160201* | 50-280 | S |
| WILSON, J. L. | 8303160211* | 50-280 | S |
| WILSON, J. L. | 8303240464 | 50-281 | S |
| WILSON, J. L. | 8303240472* | 50-281 | S |
| WILSON, J. L. | 8303240504 | 50-280 | S |
| WILSON, J. L. | 8303240510* | 50-280 | S |
| WILSON, J. L. | 8303240559 | 50-280 | S |
| WILSON, J. L. | 8303240573* | 50-280 | S |
| WILSON, J. M. | 8303110207 | 50-280 | J |
| WILSON, R. | 8303140269 | 50-400 | Q |
| WILSON, R. L. | 8303100416 | NUREG | |
| WINTER, C. E. | 8303140043* | 70-1062 | |
| WIRE, K. | 8303250011* | 50-298 | S |
| WIRTH, W. F. | 8303310502* | 50-334 | F |
| WISE, R. | 8303180225* | 50-285 | Q |
| WISE, R. | 8303180230* | 50-298 | Q |
| WITHERS, B. D. | 8303080437 | 50-344 | Q |
| WITHERS, B. D. | 8303090218 | 50-344 | P |
| WITHERS, B. D. | 8303110238 | 50-344 | R |
| WITHERS, B. D. | 8303150553 | 50-344 | Q |
| WITHERS, B. D. | 8303240236 | 50-344 | P |
| WITHERS, B. D. | 8303280189 | 50-344 | P |
| WITHERS, B. D. | 8303290215 | 50-344 | F |
| WITTENBURG, K. | 8303210359* | 50-373 | S |
| WODEK, D. J. | 8303110033 | 40-8714 | |
| WOGMAN, N. A. | 8303010088 | WASTE MGT | |
| WOGMAN, N. A. | 8303010093* | WASTE MGT | |
| WOGMAN, N. A. | 8303010095 | WASTE MGT | |
| WOGMAN, N. A. | 8303010097 | WASTE MGT | |
| WOGMAN, N. A. | 8303010107* | WASTE MGT | |
| WOGMAN, N. A. | 8303010139 | WASTE MGT | |
| WOGMAN, N. A. | 8303010147* | WASTE MGT | |
| WOGMAN, N. A. | 8303010321* | WASTE MGT | |
| WOHLD, P. R. | 8303040540* | 50-483 | Q |
| WOHLD, P. R. | 8303140334* | 50-483 | Q |
| WOLF, J. F. | 8303170503 | 50-320 | Q |
| WOLFE, R. | 8303080494* | 50-346 | S |
| WOLFE, S. J. | 8303080453 | 50-556 | Q |
| WOLFE, S. J. | 8303290301 | 50-382 | Q |
| WOLFF, C. E. | 8303110586 | 40-8602 | |
| WOLFF, C. E. | 8303140646 | 40-8602 | |
| WOLLETT, S. | 8303020068 | CONTRACT | |
| WOLLETT, S. | 8303020077 | CONTRACT | |
| WOLLETT, S. | 8303020480 | CONTRACT | |
| WOLLETT, S. | 8303030238 | CONTRACT | |
| WOLLETT, S. | 8303030252 | CONTRACT | |
| WOLLETT, S. | 8303030263 | CONTRACT | |
| WOLLETT, S. | 8303090662 | CONTRACT | |
| WOLLETT, S. | 8303160091 | CONTRACT | |
| WOLLETT, S. | 8303170013 | CONTRACT | |
| WOLLETT, S. | 8303290191 | CONTRACT | |
| WOLLETT, S. | 8303290417 | CONTRACT | |
| WOLLETT, S. | 8303290749 | CONTRACT | |
| WOLLETT, S. | 8303290840 | CONTRACT | |
| WOLLETT, S. | 8303310330 | CONTRACT | |
| WOLTNER, E. | 8303160472* | 70-371 | |
| WOLTNER, E. | 8303300403* | 70-820 | |
| WONG, H. | 8303250034* | 50-438 | Q |
| WONG, S. | 8303090659 | NUREG | |
| WONG, T. | 8303090106 | 40-299 | |
| WONG, T. | 8303090500 | 40-299 | |
| WONG, T. | 8303240030 | 40-299 | |
| WONG, T. | 8303240090 | 40-299 | |
| WOOD, E. C. | 8303010555 | 50-309 | S |
| WOOD, E. C. | 8303080168 | 50-309 | S |
| WOOD, R. S. | 8303220417 | NUREG | |
| WOODHEAD, C. P. | 8303100151 | 50-142 | Q |
| WOODHEAD, C. P. | 8303150357 | 50-341 | Q |
| WOODHEAD, C. P. | 8303240245 | 50-142 | Q |
| WOODHEAD, C. P. | 8303290016 | 50-341 | Q |
| WOODHEAD, C. P. | 8303310357 | 50-142 | Q |

| AUTHOR | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| WOODS, J. | 8303220090* | 50-187 R |
| WOOLEVER, E. J. | 8303030286 | 50-412 S |
| WOOLEVER, E. J. | 8303090283 | 50-412 V |
| WOOLEVER, E. J. | 8303160224* | 50-412 Q |
| WOOLSEY, R. T. | 8303090356 | 40-299 |
| WOOLSEY, R. T. | 8303170058 | 40-299 |
| WOOLSEY, R. T. | 8303180140 | 40-299 |
| WOOLSEY, R. T. | 8303210236 | 40-8602 |
| WOOLSEY, R. T. | 8303210769 | 40-2259 |
| WOOTTEN, M. J. | 8303010324* | 50-454 T |
| WOOTTEN, M. J. | 8303010324* | 50-454 T |
| WORD, J. E. | 8303300604* | CONTRACT |
| WRAY, J. R. | 8303210721* | 50-389 Q |
| WRAY, R. | 8303020109* | 50-275 P |
| WRAY, R. | 8303100235* | 50-275 P |
| WRIGHT, D. | 8303150158* | CONTRACT |
| WRIGHT, N. | 8303160113 | 50-329 Q |
| WRIGHT, N. A. | 8303020002 | 50-329 T |
| WRIGHT, N. A. | 8303310228 | 50-329 Q |
| WRIGHT, R. J. | 8303280072 | WASTE MGT |
| WRIGHT, R. J. | 8303280082 | WASTE MGT |
| WRIGHT, R. J. | 8303290068 | WASTE MGT |
| WRIGHT, R. J. | 8303290545 | WASTE MGT |
| WRIGHT, R. J. | 8303290559 | WASTE MGT |
| WRIGHT, R. J. | 8303290565 | WASTE MGT |
| WRIGHT, R. J. | 8303290598 | WASTE MGT |
| WRIGHT, R. J. | 8303290659 | WASTE MGT |
| WRIGHT, R. J. | 8303290820 | WASTE MGT |
| WRIGHT, R. J. | 8303300074 | WASTE MGT |
| WRIGHT, R. J. | 8303300082 | WASTE MGT |
| WRIGHT, R. J. | 8303300086 | WASTE MGT |
| WRIGHT, R. J. | 8303300162 | WASTE MGT |
| WRIGHT, R. J. | 8303300350 | WASTE MGT |
| WRIGHT, R. J. | 8303300424 | WASTE MGT |
| WRIGHT, R. J. | 8303300427 | WASTE MGT |
| WRIGHT, R. W. | 8303210739* | 50-400 Q |
| WRIGHT, S. V. | 8303280081 | 27-48 |
| WU, W. S. | 8303020266 | NUREG |
| WULFF, W. | 8303040122 | RES |
| WULFF, W. | 8303160183 | RES |
| WULFF, W. | 8303290862 | RES |
| WULLER, Q. E. | 8303090077 | 50-461 E |
| WULLER, Q. E. | 8303090125 | 50-461 Q |
| WULLER, Q. E. | 8303090206 | 50-461 Q |
| WULLER, Q. E. | 8303090301 | 50-461 E |
| WULLER, Q. E. | 8303170162 | 50-461 E |
| WULLER, Q. E. | 8303210048 | 50-461 A |
| WULLER, Q. E. | 8303220031 | 50-461 E |
| WULLER, Q. E. | 8303220088 | 50-461 E |
| WULLER, Q. E. | 8303230268 | 50-461 I |
| WULLER, Q. E. | 8303240327 | 50-461 E |
| WULLER, Q. E. | 8303280092 | 50-461 E |
| WULLER, Q. E. | 8303280139 | 50-461 E |
| WULLER, Q. E. | 8303290006 | 50-461 E |
| WULLER, Q. E. | 8303290371 | 50-461 A |
| WULLER, Q. E. | 8303290504 | 50-461 A |
| YALCINTAS, M. G. | 8303300472 | NUREG |
| YANLEY, M. E. | 8303240137 | RES |
| YANDELL, L. A. | 8303010230* | 50-285 Q |
| YANG, J. W. | 8303310481* | 50-461 A |
| YARGER, K. | 8303140540* | 50-346 S |
| YARNICK, T. P. | 8303180010 | 40-8102 |
| YATRON, G. | 8303040310* | COMMISSION |
| YEE, V. | 8303280223* | 50-413 A |
| YORK, J. W. | 8303010378* | 50-389 Q |
| YORK, J. W. | 8303210335* | 50-400 Q |
| YORK, J. W. | 8303210398* | 50-390 Q |
| YORK, W. G. | 8303290370 | 50-317 J |
| YOUNG, F. | 8303280191* | 50-289 Q |
| YOUNG, M. A. | 8303020023 | 50-460 Q |
| YOUNG, M. A. | 8303100166 | 50-460 Q |
| YOUNG, M. A. | 8303290023 | 50-133 Q |
| YOUNG, R. | 8303300449* | CONTRACT |
| YOUNG, T. | 8303040361* | 50-528 Q |
| YOUNG, T. | 8303080489* | 50-312 Q |
| YOUNG, T. | 8303150506* | 50-528 Q |
| YOUNG, T. | 8303180517* | 50-528 Q |
| YOUNG, T. | 8303180522* | 50-528 Q |
| YOUNG, T. | 8303290295* | 50-312 Q |
| YOUNG, Y. A. | 8303090011 | 40-8745 |
| YOUNG, Y. A. | 8303180065* | 40-8745 |
| YOUNGBLOOD, B. J. | 8303020194 | 50-358 A |
| YOUNGBLOOD, B. J. | 8303020295 | 50-358 A |
| YOUNGBLOOD, B. J. | 8303110050 | 50-440 A |
| YOUNGBLOOD, B. J. | 8303290680 | 50-341 A |
| YOUNGBLOOD, B. J. | 8303290691 | 50-445 E |
| YOUNGBLOOD, B. J. | 8303290703 | 50-454 A |
| YOUNGBLOOD, B. J. | 8303290714 | 50-341 A |
| YOUNGBLOOD, B. J. | 8303290730 | 50-445 A |
| YOUNGBLOOD, B. J. | 8303290789 | 50-440 A |
| YOUNGBLOOD, B. J. | 8303290801 | 50-440 E |
| YOUNGBLOOD, B. J. | 8303290810 | 50-346 A |
| YOUNGBLOOD, B. J. | 8303290825* | 50-346 A |
| YOUNGBLOOD, B. J. | 8303300176 | 50-445 E |
| YOUNGBLOOD, B. J. | 8303300212 | 50-358 A |
| YOUNGBLOOD, B. J. | 8303300282 | 50-358 A |
| YOUNGBLOOD, B. J. | 8303300289 | 50-423 A |
| YOUNGBLOOD, B. J. | 8303300729 | 50-423 A |
| YOUNGBLOOD, B. J. | 8303300768 | 50-440 A |
| YOUNGDAHL, R. C. | 8303310296* | 40-8698 |
| YOUNGHEIN, I. | 8303240055* | 70-1193 |
| YOUNGHEIN, I. H. | 8303240050* | 70-1193 |
| YUHAS, G. P. | 8303290468* | 50-206 Q |
| YUNDT, C. D. | 8303150489 | 50-344 R |
| YUNDT, C. P. | 8303080313 | 50-344 R |
| YUNDT, C. P. | 8303110108 | 50-344 S |
| YUNDT, C. P. | 8303110330 | 50-344 S |
| YUNDT, C. P. | 8303110390 | 50-344 S |
| ZAHLER, R. E. | 8302100345 | PRM |
| ZAHLER, R. E. | 8303010046 | 40-2061 |
| ZAHLER, R. E. | 8303010070* | 40-2061 |
| ZAHLER, R. E. | 8303080459 | 50-289 Q |
| ZAHLER, R. E. | 8303080459 | 50-289 Q |
| ZERBE, J. | 8303300038* | 50-213 P |
| ZERBE, J. E. | 8303090193* | FOIA |
| ZEYHER, S. H. | 8303230474 | FOIA |
| ZIBULSKY, H. | 8303160472* | 70-371 |
| ZIEBOLD, T. O. | 8303310324* | FOIA |
| ZIEBOLD, T. O. | 8303310331* | FOIA |
| ZIEBOLD, T. O. | 8303310336* | FOIA |
| ZIEBOLD, T. O. | 8303310347* | FOIA |
| ZILBULSKY, H. | 8303100332* | 70-135 |
| ZILBULSKY, H. | 8303300403* | 70-820 |
| ZIMMERMAN, B. J. | 8303020082* | CONTRACT |
| ZIMMERMAN, J. V. | 8303020238 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303020248 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303020290 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303020368 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303020414 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303020440 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303030772 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303030787 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303030793 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303040014 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303040053 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303040061 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303040070 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303040085 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303040093 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303100529 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303100531 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303100533 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303100535 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303100537 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303100540 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303100543 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303100544 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303140547 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303140549 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303140561 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303140665 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303140666 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303140667 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303140668 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303140670 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303140672 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303140674 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303140699 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303170337 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303170667 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303170672 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303180020 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303180045 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303180047 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303180094 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303180109 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303180113 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303180118 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303180121 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303180178 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303180181 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303180567 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303230073 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303230076 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303230363 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303230427 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303230516 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303240352 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303280116 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303290044 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303290051 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303290079 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303290090 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303290104 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303290113 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303290119 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303290125 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303290169 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303290179 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303290183 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303290189 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303290207 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303290213 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303290220 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303310544 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303310556 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303310560 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303310565 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303310607 | XPORTLIC |
| ZIMMERMAN, J. V. | 8303310650 | XPORTLIC |
| ZIMMERMAN, R. P. | 8303030408* | 50-220 Q |
| ZIMMERMAN, R. P. | 8303080428* | 50-244 Q |
| ZIMMERMAN, S. R. | 8303070166 | 50-400 A |
| ZIMMERMAN, S. R. | 8303090350 | 50-261 V |
| ZIMMERMAN, S. R. | 8303160414 | 50-324 P |
| ZIMMERMAN, S. R. | 8303220053 | 50-261 P |
| ZIMMERMAN, S. R. | 8303220101 | 50-261 P |
| ZIMMERMAN, S. R. | 8303220327 | 50-261 P |
| ZIMMERMAN, S. R. | 8303220344 | 50-261 J |
| ZIMMERMAN, S. R. | 8303280011 | 50-261 F |
| ZIMMERMAN, S. R. | 8303280040 | 50-400 C |
| ZIMOULIS, T. | 8303110262* | 50-389 A |
| ZO, R. N. | 8303110303* | 50-250 P |
| ZUDANS, Z. | 8303210149 | 50-522 O |
| ZUDANS, Z. | 8303210149 | 50-522 O |
| ZUPKO, J. M. | 8303150284 | 50-272 R |
| ZURAKOWSKI | 8303300268 | I&E |
| ZURAKOWSKI, P. R. | 8303240577* | 70-25 |
| ZWETZIG, G. B. | 8303290271* | 50-275 Q |

# CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."


| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303140376 | 50-348 P |
| | 8303140376 | 50-348 P |
| | 8303140380* | 50-348 P |
| | 8303140380* | 50-348 P |
| | 8303140491 | 50-348 P |
| | 8303140491 | 50-348 P |
| | 8303140558 | 50-348 P |
| | 8303140558 | 50-348 P |
| | 8303150486 | 50-348 P |
| | 8303170531 | 50-348 G |
| | 8303180378 | 50-348 S |
| | 8303180384* | 50-348 S |
| | 8303210377 | 50-348 S |
| | 8303210384* | 50-348 S |
| | 8303210460 | 50-364 S |
| | 8303210468* | 50-364 S |
| | 8303210548* | 50-348 G |
| | 8303230227 | 50-348 P |
| | 8303230247 | 50-364 P |
| | 8303230252* | 50-364 P |
| | 8303230418* | 50-348 F |
| | 8303230418* | 50-348 F |
| | 8303230423* | 50-348 F |
| | 8303230423* | 50-348 F |
| | 8303240112* | 50-348 F |
| | 8303290354 | 50-348 G |
| | 8303300206 | 50-364 P |
| Alabama, State of | 8303310374* | CONTRACT |
| Alderson Reporting | 8303100051* | FOIA |
| Alison Control, Inc | 8303090310* | 50-382 F |
| | 8303090318* | 50-382 F |
| Alpha-Omega Services, Inc | 8303110116 | 71-86 |
| | 8303110119* | 71-86 |
| American College of Radiology | 8302250325 | PR |
| | 8303090153 | FOIA |
| American Electric Power Service Corp | 8303010265 | 50-315 P |
| | 8303010265 | 50-315 P |
| | 8303010315 | 50-315 P |
| | 8303010315 | 50-315 P |
| | 8303010323 | 50-315 P |
| | 8303010323 | 50-315 P |
| American Institute of Aeronautics & Astronautics | 8303030370* | CONTRACT |
| American Nuclear Insurers | 8303080306 | State Prog |
| | 8303240226 | 50-237 J |
| American Nuclear Society | 8303110093* | ORG |
| | 8303140707 | NUREG |
| | 8303140709 | NUREG |
| | 8303140710 | NUREG |
| | 8303300042* | ORG |
| | 8303310646* | CONTRACT |
| American Society of Mechanical Engineers | 8303010287 | MISC |
| Amersham Corp | 8303280356 | 71-9167 |
| Ames Safety Envelope Co | 8303160069* | CONTRACT |
| Anacomp, Inc | 8303010714* | CONTRACT |
| ALFAB, Inc | 8303040550* | QA999 |
| | 8303040582* | QA999 |
| AMAX Environmental Services, Inc (subs of AMAX, Inc ) | 8303020232 | 40-8820 |
| AMAX Specialty Metals Corp (subs of AMAX, Inc ) | 8303030770 | XPORTLIC |
| Abdel-Khalick, S I | 8303300100* | 50-537 A |
| Academy of Natural Sciences | 8303170019* | CONTRACT |
| Ad Hoc Committee for Review of Nuclear Reactor Reform Proposals | 8303090621 | REVIEW GRP |
| | 8303290609* | REVIEW GRP |
| Advanced Medical Systems, Inc | 8303100512 | 71-5796 |
| Advanced Technology, Inc | 8303030071* | CONTRACT |
| Advisory Council on Historic Preservation | 8303280128 | 50-245 P |
| Aerospace Corp | 8303310602* | CONTRACT |
| Agriculture, Dept of, Graduate School | 8303230380* | CONTRACT |
| Air and Water Pollution Patrol | 8303010406 | 50-352 G |
| Alabama Power Co | 8302070360 | 50-348 P |
| | 8302070360 | 50-348 P |
| | 8302070362* | 50-348 P |
| | 8302070362* | 50-348 P |
| | 8303010209* | 50-348 G |
| | 8303010299 | 50-348 J |
| | 8303010506 | 50-348 V |
| | 8303010506 | 50-348 V |
| | 8303020027 | 50-364 Q |
| | 8303040318 | 50-348 S |
| | 8303040323* | 50-348 S |
| | 8303040329 | 50-348 S |
| | 8303040334* | 50-348 S |
| | 8303080242 | 50-348 P |
| | 8303080480 | 50-348 P |
| | 8303080512 | 50-348 P |
| | 8303080517 | 50-348 P |
| | 8303080517 | 50-348 P |
| | 8303090199* | 50-348 F |
| | 8303090207* | 50-348 F |
| | 8303090312 | 50-348 G |
| | 8303090312 | 50-348 G |
| | 8303090341 | 50-348 R |
| | 8303090341 | 50-348 R |
| | 8303090348* | 50-348 R |
| | 8303090375* | 50-348 F |
| | 8303090375* | 50-348 F |
| | 8303090377* | 50-348 F |
| | 8303100407* | 50-348 F |
| | 8303100407* | 50-348 F |
| | 8303100410* | 50-348 F |
| | 8303100410* | 50-348 F |
| | 8303110102 | 50-348 P |
| | 8303110370 | 70-2920 |
| | 8303140312 | 50-348 P |
| | 8303140312 | 50-348 P |
| | 8303140318* | 50-348 P |
| | 8303140318* | 50-348 P |

# CORPORATE SOURCE INDEX


| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| Anefco, Inc. | 8303040051 | 71-9074 |
| | 8303040066* | 71-9074 |
| Antioch School of Law, Washington, DC | 8303010073 | 50-155 G |
| | 8303090121 | 50-155 G |
| | 8303220290 | 50-155 G |
| Applied Risk Technology Corp. | 8303110192 | 50-247 G |
| Argonne National Laboratory | 8303020006* | 50-329 T |
| | 8303020006* | 50-329 T |
| | 8303020011* | 50-329 T |
| | 8303020011* | 50-329 T |
| | 8303140617 | NUREG |
| | 8303150615 | RES |
| | 8303300628 | NUREG |
| Ariz. Engineers, Architects & Planners | 8303160619* | 40-1341 |
| | 8303160623* | 40-1341 |
| Arizona Public Service Co. | 8303040268 | 50-528 S |
| | 8303040268 | 50-528 S |
| | 8303040268 | 50-528 S |
| | 8303040441 | 50-528 S |
| | 8303040441 | 50-528 S |
| | 8303040441 | 50-528 S |
| | 8303040444 | 50-528 S |
| | 8303040444 | 50-528 S |
| | 8303040452 | 50-528 A |
| | 8303040563 | 50-528 S |
| | 8303040563 | 50-528 S |
| | 8303040563 | 50-528 S |
| | 8303040578 | 50-528 S |
| | 8303040578 | 50-528 S |
| | 8303040578 | 50-528 S |
| | 8303070040 | 50-528 A |
| | 8303070040 | 50-528 A |
| | 8303070040 | 50-528 A |
| | 8303070058 | 50-528 A |
| | 8303070058 | 50-528 A |
| | 8303070058 | 50-528 A |
| | 8303080146 | 50-528 S |
| | 8303080146 | 50-528 S |
| | 8303080146 | 50-528 S |
| | 8303080235 | 50-528 S |
| | 8303080414 | 50-528 S |
| | 8303080414 | 50-528 S |
| | 8303080414 | 50-528 S |
| | 8303080439 | 50-528 S |
| | 8303080439 | 50-528 S |
| | 8303080439 | 50-528 S |
| | 8303090194 | 50-528 A |
| | 8303090194 | 50-528 A |
| | 8303090194 | 50-528 A |
| | 8303100345 | 50-528 E |
| | 8303140191 | 50-528 S |
| | 8303140191 | 50-528 S |
| | 8303140191 | 50-528 S |
| | 8303140316 | 50-528 S |
| | 8303140332 | 50-528 S |
| | 8303140332 | 50-528 S |
| | 8303140332 | 50-528 S |
| | 8303140372 | 50-528 S |
| | 8303140455 | 50-529 S |
| | 8303140480 | 50-528 S |
| | 8303140480 | 50-528 S |
| | 8303140480 | 50-528 S |
| | 8303140541 | 50-528 G |
| | 8303170114 | 50-528 E |
| | 8303220017 | 50-528 G |
| | 8303220161 | 50-528 S |
| | 8303220180 | 50-528 S |
| | 8303220180 | 50-528 S |
| | 8303220186 | 50-528 S |
| | 8303220191 | 50-529 S |
| | 8303220204 | 50-528 S |
| | 8303280168 | 50-528 A |
| | 8303290249 | 70-2949 |
| | 8303290490 | 50-528 A |
| | 8303300678* | 50-528 F |
| | 8303300678* | 50-528 F |
| | 8303300678* | 50-528 F |
| | 8303300684* | 50-528 F |
| Arizona, Univ. of | 8303290196* | CONTRACT |
| | 8303290608* | CONTRACT |
| Arkansas Power & Light Co. | 8303010415 | 50-313 P |
| | 8303010415 | 50-313 P |
| | 8303010417* | 50-313 P |
| | 8303010417* | 50-313 P |
| | 8303010418 | 50-313 P |
| | 8303010513 | 50-368 G |
| | 8303010519* | 50-368 G |
| | 8303010685* | 50-313 G |
| | 8303030518 | 50-368 S |
| | 8303030523* | 50-368 S |
| | 8303030614 | 50-368 S |
| | 8303030629* | 50-368 S |
| | 8303040333 | 50-368 P |
| | 8303040348 | 50-313 P |
| | 8303040348 | 50-313 P |
| | 8303040353* | 50-313 P |
| | 8303040353* | 50-313 P |
| | 8303040393 | 50-313 P |
| | 8303040407 | 50-313 P |
| | 8303040407 | 50-313 P |
| | 8303040504* | 50-416 S |
| | 8303040593 | 50-313 P |
| | 8303040594 | 50-313 H |
| | 8303040597 | 50-313 P |
| | 8303040597 | 50-313 P |
| | 8303040611 | 50-313 G |
| | 8303040611 | 50-313 G |
| | 8303070028 | 50-313 V |
| | 8303070028 | 50-313 V |
| | 8303070128 | 50-313 P |
| | 8303080038 | 50-368 R |
| | 8303080046* | 50-368 R |
| | 8303080055 | 50-313 R |
| | 8303080059* | 50-313 R |
| | 8303080062 | 50-313 P |
| | 8303080062 | 50-313 P |
| | 8303080272 | 50-313 G |
| | 8303080272 | 50-313 G |
| | 8303080299 | 50-313 P |
| | 8303080299 | 50-313 P |
| | 8303080346 | 50-313 R |
| | 8303080351* | 50-313 R |
| | 8303090239 | 50-368 P |
| | 8303090414* | 50-313 F |
| | 8303090594* | 50-313 F |
| | 8303090594* | 50-313 F |
| | 8303110240 | 50-313 H |
| | 8303110240 | 50-313 H |
| | 8303110328 | 50-313 P |
| | 8303110328 | 50-313 P |
| | 8303110332 | 50-313 G |
| | 8303110332 | 50-313 G |
| | 8303110352 | 50-313 P |
| | 8303110352 | 50-313 P |
| | 8303140059 | 50-313 P |
| | 8303140059 | 50-313 P |
| | 8303140370 | 50-313 P |
| | 8303140370 | 50-313 P |
| | 8303150381 | 50-313 R |
| | 8303150384* | 50-313 R |
| | 8303150454 | 50-368 S |
| | 8303150473 | 50-313 P |
| | 8303150474* | 50-313 P |
| | 8303150481 | 50-368 S |
| | 8303150484* | 50-368 S |
| | 8303150517 | 50-368 R |
| | 8303150527* | 50-369 R |
| | 8303160388 | 50-313 P |
| | 8303160388 | 50-313 P |
| | 8303210234 | 50-313 P |
| | 8303210234 | 50-313 P |
| | 8303210244* | 50-313 P |
| | 8303210244* | 50-313 P |
| | 8303210277 | 50-313 P |
| | 8303210277 | 50-313 P |
| | 8303210283* | 50-313 P |
| | 8303210283* | 50-313 P |
| | 8303210329 | 50-313 P |
| | 8303210329 | 50-313 P |
| | 8303210399 | 50-313 P |
| | 8303220034 | 50-313 P |
| | 8303220044 | 50-313 P |
| | 8303230164* | 50-313 F |
| | 8303230164* | 50-313 F |
| | 8303230170* | 50-313 F |
| | 8303230170* | 50-313 F |
| | 8303240354 | 50-368 S |
| | 8303240358* | 50-368 S |
| | 8303240374 | 50-313 S |
| | 8303240382* | 50-313 S |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303240478* | 50-313 G |
| | 8303240478* | 50-313 G |
| | 8303250004* | 50-313 F |
| | 8303250004* | 50-313 F |
| | 8303250005* | 50-313 F |
| | 8303250005* | 50-313 F |
| | 8303250021 | 50-368 S |
| | 8303250027* | 50-368 S |
| | 8303250036 | 50-313 G |
| | 8303250133 | 50-313 P |
| | 8303250133 | 50-313 P |
| | 8303280017 | 50-313 G |
| | 8303280017 | 50-313 G |
| | 8303280154 | 50-368 S |
| | 8303280187* | 50-368 S |
| | 8303280208 | 50-368 S |
| | 8303280217* | 50-368 S |
| | 8303280266* | 50-313 F |
| | 8303280266* | 50-313 F |
| | 8303290063 | 50-313 R |
| | 8303290222 | 50-368 P |
| | 8303290226* | 50-368 P |
| | 8303290230* | 50-368 P |
| | 8303290236* | 50-368 F |
| | 8303290244* | 50-368 P |
| | 8303290419 | 50-313 P |
| | 8303290439 | 50-368 G |
| | 8303290641* | 50-313 F |
| | 8303290641* | 50-313 F |
| | 8303290685* | 50-313 F |
| | 8303290685* | 50-313 F |
| | 8303290699* | 50-313 F |
| | 8303290699* | 50-313 F |
| | 8303290711* | 50-313 F |
| | 8303290711* | 50-313 F |
| | 8303290716* | 50-313 F |
| | 8303290716* | 50-313 F |
| | 8303300049* | 50-313 F |
| | 8303300049* | 50-313 F |
| | 8303300054* | 50-313 F |
| | 8303300054* | 50-313 F |
| | 8303300619* | 50-313 F |
| | 8303300619* | 50-313 F |
| | 8303300633* | 50-313 F |
| | 8303300633* | 50-313 F |
| Army, Dept. of, Army Engineer Waterways Experiment Station | 8303210016 | WASTE MGT |
| | 8303220432 | NUREG |
| Army, Dept. of, Corps of Engineers | 8303290197* | CONTRACT |
| Arthur Young & Co | 8303090422* | CONTRACT |
| Atlantic Electric of New Jersey | 8303170206* | 50-171 I |
| Atlantic Richfield Co. (ARCO) | 8303230474 | FOIA |
| Atlas Minerals | 8303090030 | 40-3453 |
| | 8303090031* | 40-3453 |
| | 8303090038 | 40-3453 |
| | 8303090071 | 40-3453 |
| | 8303170682 | 40-3453 |
| Atomic Industrial Forum | 8303300406 | TOPREP |
| Automatic Switch Co | 8303280170 | 50-3 S |
| Automation Industries, Inc | 8303090599* | CONTRACT |
| | 8303140649 | 71-9006 |
| | 8303290022 | 71-9006 |
| | 8303290026* | 71-9006 |
| BDM Corp | 8303300449* | CONTRACT |
| Babcock & Wilcox Co | 8211020433* | 50-313 P |
| | 8303010001 | 71-3088 |
| | 8303010606 | TOPREP |
| | 8303010689 | 70-27 |
| | 8303010692 | 70-1201 |
| | 8303010695 | 70-27 |
| | 8303020123 | 70-1201 |
| | 8303020212 | 70-27 |
| | 8303020217 | 70-364 |
| | 8303020222* | 70-364 |
| | 8303020227* | 70-364 |
| | 8303040505 | TOPREP |
| | 8303090636 | 70-1201 |
| | 8303100514 | 70-1201 |
| | 8303110037 | 70-824 |
| | 8303110126 | 70-1201 |
| | 8303110133* | 70-1201 |
| | 8303150007 | 70-1201 |
| | 8303150014* | 70-1201 |
| | 8303170011 | 70-27 |
| | 8303180308* | 50-320 P |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303180313* | 50-320 P |
| | 8303250020 | 50-335 P |
| | 8303300717* | 50-289 P |
| | 8303300721* | 50-289 P |
| Babcock & Wilcox Operating Plants Owners Group | 8303030173 | TOPREP |
| | 8303220205 | TOPREP |
| Babcock & Wilcox Regulatory Response Group | 8303010581 | TOPREP |
| Backus, Shea & Meyer | 8303180323 | 50-443 G |
| | 8303180323 | 50-443 G |
| | 8303180329* | 50-443 G |
| | 8303180329* | 50-443 G |
| | 8303230212 | 50-443 G |
| | 8303230216* | 50-443 G |
| | 8303250164 | 50-443 G |
| Baltimore Gas & Electric Co | 8303010244 | 50-317 S |
| | 8303010256* | 50-317 S |
| | 8303010387 | 50-318 S |
| | 8303010393* | 50-318 S |
| | 8303010521 | 50-318 S |
| | 8303010528 | 50-317 P |
| | 8303010529 | 50-317 P |
| | 8303010536* | 50-317 P |
| | 8303010536* | 50-317 P |
| | 8303010542* | 50-318 S |
| | 8303020035 | 50-317 P |
| | 8303020035 | 50-317 P |
| | 8303020081 | 50-317 F |
| | 8303020081 | 50-317 F |
| | 8303030673 | 50-318 S |
| | 8303030681* | 50-318 S |
| | 8303080213 | 50-244 R |
| | 8303080217* | 50-244 R |
| | 8303090063 | 50-317 G |
| | 8303090063 | 50-317 G |
| | 8303090217 | 50-317 P |
| | 8303090217 | 50-317 P |
| | 8303090277 | 50-317 G |
| | 8303090277 | 50-317 G |
| | 8303100266 | 50-317 P |
| | 8303100266 | 50-317 P |
| | 8303100363 | 50-317 R |
| | 8303100363 | 50-317 R |
| | 8303100365* | 50-317 R |
| | 8303100365* | 50-317 R |
| | 8303110130 | 50-317 F |
| | 8303110295 | 50-317 G |
| | 8303110295 | 50-317 G |
| | 8303110308 | 50-317 G |
| | 8303110308 | 50-317 G |
| | 8303140194 | 50-317 S |
| | 8303140199* | 50-317 S |
| | 8303140375 | 50-317 S |
| | 8303140378* | 50-317 S |
| | 8303150387 | 50-317 P |
| | 8303160145 | 50-318 S |
| | 8303160153* | 50-318 S |
| | 8303160176 | 50-318 S |
| | 8303160184* | 50-318 S |
| | 8303160255 | 50-318 S |
| | 8303160265* | 50-318 S |
| | 8303160268 | 50-317 S |
| | 8303160274* | 50-317 S |
| | 8303160312 | 50-318 S |
| | 8303160324* | 50-318 S |
| | 8303160410 | 50-318 S |
| | 8303160411* | 50-318 S |
| | 8303170056 | 50-317 P |
| | 8303170274 | 50-317 P |
| | 8303170274 | 50-317 P |
| | 8303210177 | 50-317 P |
| | 8303210188* | 50-317 P |
| | 8303210192* | 50-317 P |
| | 8303210410 | 50-317 S |
| | 8303210418* | 50-317 S |
| | 8303210570 | 50-318 S |
| | 8303210577* | 50-318 S |
| | 8303210613 | 50-317 S |
| | 8303210621* | 50-317 S |
| | 8303210702 | 50-318 S |
| | 8303210715* | 50-318 S |
| | 8303220015 | 50-317 F |
| | 8303220015 | 50-317 F |
| | 8303220022 | 50-317 R |

# CORPORATE SOURCE INDEX

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303220022 | 50-317 R |
| | 8303220026* | 50-317 R |
| | 8303220026* | 50-317 R |
| | 8303220316 | 50-317 R |
| | 8303220322* | 50-317 R |
| | 8303220328* | 50-317 R |
| | 8303220334* | 50-317 R |
| | 8303220339* | 50-317 R |
| | 8303220341 | 50-317 G |
| | 8303220346* | 50-317 R |
| | 8303240377 | 50-317 F |
| | 8303290300 | 50-317 P |
| | 8303290300 | 50-317 P |
| | 8303290304* | 50-317 P |
| | 8303290304* | 50-317 P |
| | 8303290370 | 50-317 J |
| | 8303300774* | 50-317 F |
| | 8303300777* | 50-317 F |
| | 8303310270 | 50-317 P |
| Basalt Waste Isolation Project | 8303290856 | WASTE MGT |
| Basin Industrial X-Ray, Inc. | 8303020366 | 71-6717 |
| Battelle Memorial Institute, Columbus Laboratories | 8303090668* | CONTRACT |
| | 8303160097* | CONTRACT |
| | 8303280333* | CONTRACT |
| Battelle Memorial Institute, Pacific Northwest Laboratory | 8303010088 | WASTE MGT |
| | 8303010093* | WASTE MGT |
| | 8303010095 | WASTE MGT |
| | 8303010097 | WASTE MGT |
| | 8303010107* | WASTE MGT |
| | 8303010139 | WASTE MGT |
| | 8303010147* | WASTE MGT |
| | 8303010313 | WASTE MGT |
| | 8303010321* | WASTE MGT |
| | 8303090026* | FOIA |
| | 8303090510 | NUREG |
| | 8303100416 | NUREG |
| | 8303100421 | NUREG |
| | 8303140696 | NUREG |
| | 8303150680 | NUREG |
| | 8303160611 | NUREG |
| | 8303220422 | NUREG |
| | 8303280076 | WASTE MGT |
| | 8303300178 | RES |
| | 8303300667 | RES |
| Battelle New England Marine Research Laboratory | 8303240405* | 50-219 R |
| Baystate Medical Center Springfield,MA | 8303140138* | FOIA |
| | 8303140173* | FOIA |
| | 8303140181* | FOIA |
| | 8303140192* | FOIA |
| Bear Creek Uranium Co. | 8303220460 | 40-8452 |
| | 8303220464* | 40-8452 |
| Bechtel Corp. | 8303020014* | 50-321 P |
| | 8303210524* | QA999 |
| | 8303220016 | 50-329 R |
| | 8303280110* | 50-338 P |
| | 8303290396* | 50-320 G |
| Bergen-Paterson Pipe Support Corp. | 8303040511 | PT21 |
| Berlin, Roisman, Kessler & Cashdan | 8303140472* | 50-528 G |
| Binder, Elster, Mendelson & Wheeler, Inc. | 8303160071* | CONTRACT |
| | 8303160085* | CONTRACT |
| Boeing Co. | 8303100460 | NUREG |
| | 8303100558 | NUREG |
| Boeing Computer Services, Inc. (subs. of Boeing Co.) | 8303280102* | CONTRACT |
| | 8303290264* | CONTRACT |
| Booz Allen & Hamilton, Inc. | 8303100460 | NUREG |
| | 8303100558 | NUREG |
| | 8303290596* | CONTRACT |
| Borg-Warner Corp. | 8303230006 | XPORTLIC |
| Boston Edison Co. | 8303010658 | 50-293 S |
| | 8303040401 | 50-293 R |
| | 8303040408* | 50-293 R |
| | 8303040432 | 50-293 V |
| | 8303040513 | 50-293 Q |
| | 8303040547 | 50-293 P |
| | 8303040548 | 50-293 P |
| | 8303070115 | 50-293 P |
| | 8303070121* | 50-293 P |
| | 8303080510 | 50-293 R |
| | 8303080513* | 50-293 R |
| | 8303100214 | 50-293 I |
| | 8303110293 | 50-293 P |
| | 8303140226 | 50-293 Q |
| | 8303140592 | 50-293 S |
| | 8303140598* | 50-293 S |
| | 8303150446 | 50-293 P |
| | 8303150449* | 50-293 P |
| | 8303150575 | 50-293 R |
| | 8303150580* | 50-293 R |
| | 8303170316 | 50-293 F |
| | 8303170330 | 50-293 F |
| | 8303170380 | 50-293 P |
| | 8303180497 | 50-293 S |
| | 8303180504* | 50-293 S |
| | 8303250068 | 50-293 S |
| | 8303250074* | 50-293 S |
| | 8303250118 | 50-293 S |
| | 8303250121* | 50-293 S |
| | 8303290476 | 50-293 R |
| | 8303290478* | 50-293 R |
| Broad Top Bulletin Saxton, PA | 8303020073 | 50-146 H |
| Broken Plow Law Office | 8303090001 | FOIA |
| Brookhaven National Laboratory | 8303020119* | 50-275 P |
| | 8303020207* | 50-250 F |
| | 8303030[illegible] | TOPREP |
| | 8303030341* | TOPREP |
| | 8303040104 | RES |
| | 8303040122 | RES |
| | 8303040138 | RES |
| | 8303040155 | 50-537 A |
| | 8303040170 | RES |
| | 8303040186 | RES |
| | 8303090291 | 50-275 P |
| | 8303090389 | 50-275 P |
| | 8303090481* | TOPREP |
| | 8303090531 | RES |
| | 8303090555 | RES |
| | 8303090564 | RES |
| | 8303090569 | RES |
| | 8303090577 | RES |
| | 8303090608 | RES |
| | 8303090616 | RES |
| | 8303090627 | RES |
| | 8303140571* | 50-275 P |
| | 8303140579* | 50-275 P |
| | 8303140664 | 50-352 A |
| | 8303160183 | RES |
| | 8303160620 | 50-309 P |
| | 8303160687 | RES |
| | 8303210776 | RES |
| | 8303230282 | NUREG |
| | 8303230512 | NUREG |
| | 8303290704 | NUREG |
| | 8303290786 | RES |
| | 8303290792 | RES |
| | 8303290804 | RES |
| | 8303290824 | RES |
| | 8303290862 | RES |
| | 8303300154 | RES |
| | 8303300421 | RES |
| | 8303300427 | RES |
| | 8303300571 | RES |
| | 8303300578 | RES |
| | 8303300642 | RES |
| | 8303310068 | RES |
| | 8303310465* | 50-416 P |
| | 8303310470* | 50-416 P |
| | 8303310476* | 50-416 P |
| | 8303310481* | 50-461 A |
| | 8303310489* | 50-440 A |
| Brown Boveri Corp. (subs. Brown Boveri & Co., Ltd.) | 8303300245 | 50-358 S |
| Brunswick Co. | 8303160029 | XPORTLIC |
| Burns & Roe Co. | 8303010362* | 50-397 E |
| | 8303150479 | 50-537 A |
| | 8303280136 | 50-397 S |
| | 8303280225 | 50-397 S |
| | 8303280233* | 50-397 S |
| Businessmen for the Public Interest | 8303070034 | 50-454 T |
| | 8303070034 | 50-454 T |
| | 8303070155 | 50-454 Q |
| | 8303070155 | 50-454 Q |
| | 8303220195 | 50-454 T |
| | 8303300409 | 50-454 T |
| C. Itoh & Co (America), Inc. | 8303040098 | XPORTLIC |
| | 8303230002 | XPORTLIC |
| | 8303230462 | XPORTLIC |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| CBS News, CBS, Inc. | 8303090129 | FOIA |
| CQS, Inc. | 8303150130 | NUREG |
| Cabot Corp. | 8303020318 | XPORTLIC |
| | 8303020324* | XPORTLIC |
| Calgon Corp. | 8303310066 | FOIA |
| California Polytechnic State Univ. | 8303020225 | 71-492 |
| California, State of | 8303040151* | 50-275 H |
| | 8303080073 | 50-275 Q |
| | 8303090254 | 50-275 H |
| | 8303290532* | CONTRACT |
| | 8303290535* | CONTRACT |
| California, Univ. of, Berkeley | 8303140337 | 50-224 R |
| | 8303140339* | 50-224 R |
| California, Univ. of, Los Angeles | 8303150712* | CONTRACT |
| | 8303220220 | 50-142 Q |
| Canner & Shapiro | 8303220241 | 50-322 Q |
| Carolina Environmental Study Group | 8303240584 | 50-413 Q |
| | 8303310345 | 50-413 Q |
| Carolina Power & Light Co. | 8302010586 | 50-325 S |
| | 8302010596* | 50-325 S |
| | 8302280359 | 50-261 F |
| | 8303010159 | 50-324 Q |
| | 8303010188 | 50-324 S |
| | 8303010197* | 50-324 S |
| | 8303010257 | 50-400 Q |
| | 8303010257 | 50-400 Q |
| | 8303010271 | 50-325 S |
| | 8303010275* | 50-325 S |
| | 8303010278 | 50-324 S |
| | 8303010282* | 50-324 S |
| | 8303010314 | 50-324 Q |
| | 8303010373 | 50-325 S |
| | 8303010377* | 50-325 S |
| | 8303010381 | 50-325 S |
| | 8303010384* | 50-325 S |
| | 8303010394 | 50-324 S |
| | J303010400* | 50-324 S |
| | 8303010420 | 50-324 P |
| | 8303010420 | 50-324 P |
| | 8303010452 | 50-325 P |
| | 8303010477 | 50-325 S |
| | 8303010486* | 50-325 S |
| | 8303010514 | 50-324 S |
| | 8303010522* | 50-324 S |
| | 8303010538* | 50-400 Q |
| | 8303010580 | 50-324 P |
| | 8303040365 | 50-324 S |
| | 0303040380* | 50-324 S |
| | 8303040474 | 50-400 S |
| | 8303040474 | 50-400 S |
| | 0303040529 | 50-324 P |
| | 8303040529 | 50-324 P |
| | 8303040551* | 50-324 P |
| | 8303040585 | 50-324 P |
| | 8303040585 | 50-324 P |
| | 8303070166 | 50-400 A |
| | 8303070166 | 50-400 A |
| | 8303080151 | 50-324 R |
| | 8303J80158* | 50-324 R |
| | 8303090350 | 50-261 V |
| | 8303090350 | 50-261 V |
| | 8303090350 | 50-261 V |
| | 8303090350 | 50-261 V |
| | 8303090358 | 50-324 F |
| | 8303090358 | 50-324 F |
| | 9303090378 | TOPREP |
| | 8303110193 | 50-400 Q |
| | 8303110193 | 50-400 Q |
| | 8303110209 | 50-400 Q |
| | 8303110209 | 50-400 Q |
| | 8303110211 | 50-400 Q |
| | 8303110211 | 50-400 Q |
| | 8303110213 | 50-400 Q |
| | 8303110213 | 50-400 Q |
| | 8303140252 | 50-400 Q |
| | 3303140252 | 50-400 Q |
| | 8303140258* | 50-400 Q |
| | 8303140258* | 50-400 Q |
| | 8303140262* | 50-400 Q |
| | 8303140262* | 50-400 Q |
| | 8303140266* | 50-400 Q |
| | 8303140266* | 50-400 Q |
| | 8303140302 | 50-324 S |
| | 8303140310* | 50-324 S |
| | 8303140330 | 50-400 S |
| | 8303140479 | 50-400 S |
| | 8303140479 | 50-400 S |
| | 8303140562 | 50-324 S |
| | 8303140567* | 50-324 S |
| | 8303150170 | 50-324 J |
| | 8303150170 | 50-324 J |
| | 8303150177 | 50-324 J |
| | 8303150177 | 50-324 J |
| | 8303150187 | 50-324 J |
| | 8303150187 | 50-324 J |
| | 8303150192 | 50-261 J |
| | 8303150197 | 50-261 J |
| | 8303150308 | 50-261 J |
| | 8303150315 | 50-261 J |
| | 8303150323 | 50-324 J |
| | 8303150323 | 50-324 J |
| | 8303150362 | 50-324 R |
| | 8303150362 | 50-324 R |
| | 8303150369* | 50-324 R |
| | 8303150403 | 50-400 Q |
| | 8303150403 | 50-400 Q |
| | 8303150564 | 50-261 R |
| | 8303150570* | 50-261 R |
| | 8303150597 | 50-400 Q |
| | 8303150642* | 50-272 S |
| | 8303160207 | 50-325 S |
| | 8303160230 | 50-324 S |
| | 8303160242* | 50-324 S |
| | 8303160278 | 50-324 S |
| | 8303160286* | 50-324 S |
| | 8303160348 | 50-325 S |
| | 8303160414 | 50-324 P |
| | 8303160414 | 50-324 P |
| | 8303160417* | 50-324 P |
| | 8303160417* | 50-324 P |
| | 8303160418* | 50-324 P |
| | 8303160418* | 50-324 P |
| | 8303160421* | 50-324 P |
| | 8303160421* | 50-324 P |
| | 8303160490 | 50-324 S |
| | 8303160497* | 50-324 S |
| | 8303160522 | 50-400 S |
| | 8303160556 | 50-400 A |
| | 8303160556 | 50-400 A |
| | 8303160576 | 50-324 S |
| | 8303160582* | 50-324 S |
| | 8303170385 | 50-329 A |
| | 8303170475 | 50-261 Q |
| | 8303170488 | 50-261 Q |
| | 8303170496* | 50-261 Q |
| | 8303180201 | 50-324 S |
| | 8303180213 | 50-324 S |
| | 8303180218* | 50-324 S |
| | 8303180232* | 50-324 S |
| | 8303180274 | 50-324 S |
| | 8303180293 | 50-400 Q |
| | 8303180311 | 50-325 S |
| | 8303180335* | 50-325 S |
| | 8303180339 | 50-324 S |
| | 8303180367* | 50-324 S |
| | 8303180402 | 50-324 S |
| | 8303180411* | 50-324 S |
| | 8303210314 | 50-324 S |
| | 8303210315 | 50-324 S |
| | 8303210317* | 50-324 S |
| | 8303210318* | 50-324 S |
| | 8303210323 | 50-324 Q |
| | 8303210324 | 50-325 S |
| | 8303210326* | 50-325 S |
| | 8303210367 | 50-261 Q |
| | 8303210368 | 50-324 S |
| | 8303210371 | 50-261 Q |
| | 8303210374* | 50-324 S |
| | 8303210379* | 50-261 Q |
| | 8303210428 | 50-325 S |
| | 8303210445* | 50-325 S |
| | 8303210477 | 50-325 S |
| | 8303210490* | 50-325 S |
| | 8303210598 | 50-261 S |
| | 8303210602* | 50-261 Q |
| | 8303210615 | 50-324 Q |
| | 8303210698* | 50-400 Q |
| | 8303210700 | 50-324 S |
| | 8303220053 | 50-261 P |
| | 8303220101 | 50-261 P |

# CORPORATE SOURCE INDEX


| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303220164 | 50-400 A |
| | 8303220164 | 50-400 A |
| | 8303220327 | 50-261 P |
| | 8303220344 | 50-261 J |
| | 8303220344 | 50-261 J |
| | 8303230186 | 50-400 Q |
| | 8303230186 | 50-400 Q |
| | 8303240385 | 50-261 S |
| | 8303240391* | 50-261 S |
| | 8303240431 | 50-400 S |
| | 8303240431 | 50-400 S |
| | 8303240494 | 50-324 S |
| | 8303240505* | 50-324 S |
| | 8303240526 | 50-400 S |
| | 8303240526 | 50-400 S |
| | 8303240533 | 50-324 P |
| | 8303250142 | 50-261 P |
| | 8303250160 | 50-400 Q |
| | 8303280011 | 50-261 F |
| | 8303280040 | 50-400 C |
| | 8303280040 | 50-400 C |
| | 8303290355 | TOPREP |
| | 8303290491 | 50-261 P |
| | 8303290506 | 50-400 Q |
| | 8303300221 | TOPREP |
| | 8303310235 | 50-324 P |
| Carstens, A.S. | 8303230183 | 50-361 Q |
| Center for Law in the Public Interest | 8303080061 | 50-275 Q |
| Center for Nuclear Responsibility | 8203120426* | 50-250 Q |
| Cerac, Inc. | 8303040129 | XPORTLIC |
| Chackes & Hoare | 8303070118 | 50-483 Q |
| Chamber of Commerce, Hampton Beach Area, NH | 8303010407 | 50-443 Q |
| Chapel Hill Anti-Nuclear Group Effort | 8303150413 | 50-400 Q |
| Chem Systems, Inc. | 8303110112 | 71-6601 |
| Chem-Nuclear Systems, Inc. | 8303020197 | 71-9139 |
| | 8303090334 | FOIA |
| | 8303170678 | 71-5026 |
| | 8303180483 | 71-9096 |
| | 8303180488* | 71-9096 |
| | 8303240093 | 71-9105 |
| | 8303240100* | 71-9105 |
| | 8303240105 | 71-9101 |
| | 8303240110* | 71-9101 |
| | 8303280352 | 71-9111 |
| Chen & Associates, Inc. | 8303100047* | 40-8783 |
| Chicago Bridge & Iron Co. | 8303150567* | QA999 |
| | 8303150587* | QA999 |
| | 8303150594* | QA999 |
| Christa-Maria | 8303010073 | 50-155 Q |
| | 8303220290 | 50-155 Q |
| Cincinnati Gas & Electric Co. | 8303040486 | 50-358 S |
| | 8303080008 | 50-358 K |
| | 8303080010* | 50-358 K |
| | 8303080178 | 50-358 S |
| | 8303080239 | 50-358 S |
| | 8303080288 | 50-358 S |
| | 8303080431 | 50-358 S |
| | 8303080434 | 50-358 S |
| | 8303080475 | 50-358 S |
| | 8303080485 | 50-358 S |
| | 8303080496 | 50-358 R |
| | 8303080504* | 50-358 R |
| | 8303090101* | 50-358 A |
| | 8303090212* | 50-358 A |
| | 8303100221 | 50-358 S |
| | 8303150543* | 50-358 Q |
| | 8303170511 | 50-358 K |
| | 8303220007 | 50-358 S |
| | 8303220008 | 50-358 S |
| | 8303220064 | 50-358 S |
| | 8303220134 | 50-358 R |
| | 8303220136* | 50-358 R |
| | 8303220174 | 50-358 S |
| | 8303220357 | 50-358 A |
| | 8303230072* | 50-358 A |
| | 8303230084* | 50-358 A |
| | 8303290499 | 50-358 S |
| Circle Seal Controls | 8303310327 | XPORTLIC |
| | 8303310332 | XPORTLIC |
| Citizens Association for Sound Energy | 8303010084 | 50-445 Q |
| | 8303010084 | 50-445 Q |
| | 8303010105 | 50-445 Q |
| | 8303010105 | 50-445 Q |
| | 8303010276 | 50-445 Q |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303010276 | 50-445 Q |
| | 8303180380 | 50-445 Q |
| | 8303180380 | 50-445 Q |
| | 8303180385 | 50-445 Q |
| | 8303180385 | 50-445 Q |
| | 8303180400 | 50-445 Q |
| | 8303180400 | 50-445 Q |
| | 8303220226 | 50-445 Q |
| | 8303220226 | 50-445 Q |
| | 8303220233* | 50-445 Q |
| | 8303220233* | 50-445 Q |
| | 8303230213 | 50-445 Q |
| | 8303230245 | 50-445 Q |
| | 8303300371 | 50-445 Q |
| Citizens Concerned About Nuclear Power, Inc. | 8303230224 | 50-498 Q |
| Cleveland Electric Illuminating Co. | 8303010263 | 50-440 Q |
| | 8303070068 | 50-440 Q |
| | 8303070068 | 50-440 Q |
| | 8303070076 | 50-440 Q |
| | 8303070076 | 50-440 Q |
| | 8303100408 | 50-440 Q |
| | 8303100408 | 50-440 Q |
| | 8303110204 | 50-440 Q |
| | 8303110204 | 50-440 Q |
| | 8303170087 | 50-440 E |
| | 8303170087 | 50-440 E |
| | 8303170158 | 50-440 E |
| | 8303170158 | 50-440 E |
| | 8303170254 | 50-440 E |
| | 8303170254 | 50-440 E |
| | 8303170267 | 50-440 E |
| | 8303170267 | 50-440 E |
| | 8303170438 | 50-440 Q |
| | 8303170438 | 50-440 Q |
| | 8303170440 | 50-440 S |
| | 8303170440 | 50-440 S |
| | 8303170452 | 50-440 Q |
| | 8303170452 | 50-440 Q |
| | 8303170462 | 50-440 S |
| | 8303170462 | 50-440 S |
| | 8303170505 | 50-440 Q |
| | 8303170505 | 50-440 Q |
| | 8303300009 | 50-440 A |
| | 8303300009 | 50-440 A |
| | 8303300018 | 50-440 E |
| | 8303300199 | 50-440 F |
| | 8303300199 | 50-440 F |
| | 8303310027* | 50-440 F |
| | 8303310037* | 50-440 F |
| Cleveland-Cliffs Iron Co. | 8303090019 | 40-8714 |
| | 8303110033 | 40-8714 |
| | 8303110039* | 40-8714 |
| | 8303170314 | 40-8714 |
| Coalition for Safe Power | 8303010086 | 50-460 Q |
| | 8303070119 | 50-508 Q |
| | 8303140268 | 50-460 Q |
| | 8303180331 | 50-397 Q |
| | 8303180344* | 50-397 Q |
| Coalition of Northeastern Governors | 8303090587* | State Prog |
| Colorado State Univ. | 8303210651* | 50-267 R |
| Colorado, State of | 8303290798* | CONTRACT |
| Combustion Engineering, Inc. | 8303010518 | TOPREP |
| | 8303020003 | TOPREP |
| | 8303030419 | 50-470 A |
| | 8303030423 | 50-470 A |
| | 8303030647 | 50-470 E |
| | 8303030651* | 50-470 E |
| | 8303030655* | 50-470 E |
| | 8303030675* | 50-309 P |
| | 8303040467 | 50-470 A |
| | 8303070070* | 50-528 A |
| | 8303070070* | 50-528 A |
| | 8303080226 | 50-470 A |
| | 8303080236* | 50-470 A |
| | 8303080406 | 50-470 E |
| | 8303080412* | 50-470 E |
| | 8303090347* | 50-389 E |
| | 8303090351 | 50-470 A |
| | 8303100349* | 50-528 E |
| | 8303100353* | 50-528 E |
| | 8303100356* | 50-528 E |
| | 8303110111 | 70-36 |
| | 8303110121* | 70-36 |
| | 8303110260* | 50-38[illegible] A |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303110266* | 50-389 A |
| | 8303150209 | 50-470 E |
| | 8303160276* | 50-250 P |
| | 8303160282* | 50-250 P |
| | 8303160295* | 50-250 P |
| | 9303160304* | 50-250 P |
| | 8303160313* | 50-250 P |
| | 8303160373* | 50-335 P |
| | 8303160379* | 50-335 P |
| | 8303160386* | 50-335 P |
| | 8303160394* | 50-335 P |
| | 8303210754* | 50-361 P |
| | 8303210758* | 50-361 P |
| | 8303210773* | 50-361 P |
| | 8303220159 | TOPREP |
| | 8303230151 | XPORTLIC |
| | 8303230157* | XPORTLIC |
| | 8303240261 | 50-470 A |
| | 83032Y0358 | TOPREP |
| Commerce, Dept. of, | 8303180075* | CONTRACT |
| | 8303290091* | CONTRACT |
| Commerce, Dept. of, National Bureau of Standards | 8303100424 | NUREG |
| | 8303150676 | XPORTLIC |
| | 8303230158* | CONTRACT |
| | 8303230430* | 50-247 F |
| | 8303290704 | NUREG |
| | 8303290707 | NUREG |
| | 8303310243 | 50-184 R |
| | 8303310245* | 50-184 R |
| Committee to Bridge the Gap | 8303080044 | 50-142 Q |
| | 8303140267 | 50-142 Q |
| | 8303140273 | 50-142 Q |
| | 8303220203 | 50-142 Q |
| | 8303220208* | 50-142 Q |
| | 8303220325* | 50-142 Q |
| Commonwealth Edison Co | 8302280361* | 50-295 Q |
| | 8302280475 | 50-249 S |
| | 8302280487* | 50-249 S |
| | 8303010068 | 50-454 Q |
| | 8303010068 | 50-454 Q |
| | 8303010306 | 50-454 T |
| | 8303010306 | 50-454 T |
| | 8303010312* | 50-454 T |
| | 8303010312* | 50-454 T |
| | 8303010317* | 50-454 T |
| | 8303010317* | 50-454 T |
| | 8303010320* | 50-454 T |
| | 8303010320* | 50-454 T |
| | 8303010324* | 50-454 T |
| | 8303010324* | 50-454 T |
| | 8303010331* | 50-454 T |
| | 8303010331* | 50-454 T |
| | 8303010337* | 50-454 T |
| | 8303010337* | 50-454 T |
| | 8303010340* | 50-454 T |
| | 8303010340* | 50-454 T |
| | 8303010345* | 50-454 T |
| | 8303010345* | 50-454 T |
| | 8303010516 | 50-440 Q |
| | 8303010662 | 50-295 S |
| | 8303010671* | 50-295 S |
| | 8303020004 | 50-373 P |
| | 8303020007* | 50-373 P |
| | 8303020012 | 50-373 P |
| | 8303020018* | 50-373 P |
| | 8303020074 | 50-373 Q |
| | 8303030020 | 50-373 F |
| | 8303030020 | 50-373 F |
| | 8303030357 | 50-454 T |
| | 8303030357 | 50-454 T |
| | 8303030368* | 50-454 T |
| | 8303030368* | 50-454 T |
| | 8303030381 | 50-454 Q |
| | 8303030381 | 50-454 Q |
| | 8303030504 | 50-254 Q |
| | 8303030504 | 50-254 Q |
| | 8303030528 | 50-10 H |
| | 8303030528 | 50-10 H |
| | 8303030691* | 50-456 Q |
| | 8303040244* | COMMISSION |
| | 8303040489 | 50-295 F |
| | 8303040491 | 50-373 P |
| | 8303040491 | 50-373 P |
| | 8303040500 | 50-454 Q |
| | 8303040501* | 50-454 Q |
| | 8303040631 | 50-10 V |
| | 8303040631 | 50-10 V |
| | 8303040631 | 50-10 V |
| | 8303040631 | 50-10 V |
| | 8303040631 | 50-10 V |
| | 8303040631 | 50-10 V |
| | 8303040631 | 50-10 V |
| | 8303040631 | 50-10 V |
| | 8303040631 | 50-10 V |
| | 8303070036 | 50-237 Q |
| | 8303070036 | 50-237 Q |
| | 8303070036 | 50-237 Q |
| | 8303070036 | 50-237 Q |
| | 8303070036 | 50-237 Q |
| | 8303070135 | 50-10 I |
| | 8303070135 | 50-10 I |
| | 8303070135 | 50-10 I |
| | 8303070135 | 50-10 I |
| | 8303070135 | 50-10 I |
| | 8303070135 | 50-10 I |
| | 8303070135 | 50-10 I |
| | 8303070151* | 50-10 I |
| | 8303070151* | 50-10 I |
| | 8303080058 | 50-454 T |
| | 8303080058 | 50-454 T |
| | 8303080064 | 50-373 S |
| | 8303080065 | 50-454 T |
| | 8303080065 | 50-454 T |
| | 8303080066 | 50-373 S |
| | 8303080069 | 50-454 T |
| | 8303080069 | 50-454 T |
| | 8303080074 | 50-454 T |
| | 8303080074 | 50-454 T |
| | 8303080075* | 50-373 S |
| | 8303080080 | 50-454 T |
| | 8303080080 | 50-454 T |
| | 8303080090 | 50-237 S |
| | 8303080093 | 50-249 S |
| | 8303080094 | 50-454 T |
| | 8303080094 | 50-454 T |
| | 8303080098 | 50-454 T |
| | 8303080098 | 50-454 T |
| | 8303080099* | 50-237 S |
| | 8303080100* | 50-249 S |
| | 8303080104 | 50-454 T |
| | 8303080104 | 50-454 T |
| | 8303080135 | 50-454 J |
| | 8303080138 | 50-249 S |
| | 8303080147* | 50-249 S |
| | 8303080154 | 50-454 A |
| | 8303080154 | 50-454 A |
| | 8303080157* | 50-454 A |
| | 8303080157* | 50-454 A |
| | 8303080186 | 50-454 T |
| | 8303080186 | 50-454 T |
| | 8303080197 | 50-10 J |
| | 8303080197 | 50-10 J |
| | 8303080197 | 50-10 J |
| | 8303080200 | 50-454 T |
| | 8303080200 | 50-454 T |
| | 8303080204 | 50-454 T |
| | 8303080204 | 50-454 T |
| | 8303080216 | 50-454 T |
| | 8303080216 | 50-454 T |
| | 8303080234 | 50-373 S |
| | 8303080244* | 50-373 S |
| | 8303080247 | 50-237 P |
| | 8303080250 | 50-454 T |
| | 8303080250 | 50-454 T |
| | 8303080254 | 50-254 S |
| | 8303080262 | 50-454 T |
| | 8303080262 | 50-454 T |
| | 8303080263* | 50-254 S |
| | 8303080269 | 50-304 P |
| | 8303080305 | 50-454 Q |
| | 8303080305 | 50-454 Q |
| | 8303080316 | 50-237 S |
| | 8303080326* | 50-237 S |
| | 8303080328 | 50-295 P |
| | 8303080328 | 50-295 P |
| | 8303080358 | 50-373 S |
| | 8303080366* | 50-373 S |
| | 8303080401 | 50-237 P |
| | 8303080425 | 50-454 Q |

# CORPORATE SOURCE INDEX

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY | |
|---|---|---|---|
| | 8303080423 | 50-454 | G |
| | 8303080425 | 50-454 | G |
| | 8303080425 | 50-454 | G |
| | 8303080425 | 50-454 | G |
| | 8303080470 | 50-373 | P |
| | 8303080481 | 50-454 | T |
| | 8303080481 | 50-454 | T |
| | 8303080482 | 50-454 | T |
| | 8303080482 | 50-454 | T |
| | 8303080491 | 50-373 | S |
| | 8303080502* | 50-373 | S |
| | 8303090107* | 50-254 | G |
| | 8303090107* | 50-254 | G |
| | 8303090274* | 50-373 | F |
| | 8303090274* | 50-373 | F |
| | 8303090284* | 50-373 | F |
| | 8303100083* | 50-254 | F |
| | 8303100083* | 50-254 | F |
| | 8303100090* | 50-254 | F |
| | 8303100090* | 50-254 | F |
| | 8303100109* | 50-265 | P |
| | 8303100313 | 50-454 | F |
| | 8303100313 | 50-454 | F |
| | 8303100313 | 50-454 | F |
| | 8303100313 | 50-454 | F |
| | 8303100313 | 50-454 | F |
| | 8303100318* | 50-454 | F |
| | 8303100323 | 50-456 | C |
| | 8303100323 | 50-456 | C |
| | 8303100328* | 50-456 | C |
| | 8303100328* | 50-456 | C |
| | 8303100348 | 50-295 | P |
| | 8303100348 | 50-295 | P |
| | 8303100350 | 50-237 | P |
| | 8303110241 | 50-10 | R |
| | 8303110241 | 50-10 | R |
| | 8303110241 | 50-10 | R |
| | 8303110242 | 50-456 | F |
| | 8303110242 | 50-456 | F |
| | 8303110246 | 50-10 | P |
| | 8303110246 | 50-10 | P |
| | 8303110246 | 50-10 | P |
| | 8303110246 | 50-10 | P |
| | 8303110246 | 50-10 | P |
| | 8303110246 | 50-10 | P |
| | 8303110246 | 50-10 | P |
| | 8303110246 | 50-10 | P |
| | 8303110248* | 50-10 | R |
| | 8303110248* | 50-10 | R |
| | 8303110248* | 50-10 | R |
| | 8303110279* | 50-10 | P |
| | 8303110279* | 50-10 | P |
| | 8303110279* | 50-10 | P |
| | 8303110279* | 50-10 | P |
| | 8303110279* | 50-10 | P |
| | 8303110279* | 50-10 | P |
| | 8303110279* | 50-10 | P |
| | 8303110279* | 50-10 | P |
| | 8303110279* | 50-10 | P |
| | 8303110284 | 50-295 | G |
| | 8303110284 | 50-295 | G |
| | 8303110314 | 50-373 | P |
| | 8303140261* | 50-456 | G |
| | 8303140275 | 50-454 | G |
| | 8303140275 | 50-454 | G |
| | 8303140304* | 50-295 | G |
| | 8303140342 | 50-295 | S |
| | 8303140350 | 50-295 | S |
| | 8303140355* | 50-295 | S |
| | 8303140360* | 50-295 | S |
| | 8303140365 | 50-374 | S |
| | 8303140424 | 50-373 | S |
| | 8303140436 | 50-254 | S |
| | 8303140437* | 50-373 | S |
| | 8303140447* | 50-254 | S |
| | 8303140460 | 50-295 | S |
| | 8303140467* | 50-456 | G |
| | 8303140470* | 50-295 | S |
| | 8303140477 | 50-373 | S |
| | 8303140482* | 50-373 | G |
| | 8303140486* | 50-373 | S |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY | |
|---|---|---|---|
| | 8303140516 | 50-304 | S |
| | 8303140535* | 50-304 | S |
| | 8303140550 | 50-304 | S |
| | 8303140563* | 50-304 | S |
| | 8303140587 | 50-304 | S |
| | 8303140594 | 50-456 | S |
| | 8303140594 | 50-456 | S |
| | 8303140595* | 50-304 | S |
| | 8303150275 | 50-454 | A |
| | 8303150326 | 50-454 | F |
| | 8303150326 | 50-454 | F |
| | 8303150336 | 50-456 | A |
| | 8303150336 | 50-456 | A |
| | 8303150343 | 50-237 | G |
| | 8303150343 | 50-237 | G |
| | 8303150343 | 50-237 | G |
| | 8303150343 | 50-237 | G |
| | 8303150343 | 50-237 | G |
| | 8303150349 | 50-295 | R |
| | 8303150349 | 50-295 | R |
| | 8303150354* | 50-295 | R |
| | 8303150354* | 50-295 | R |
| | 8303150377 | 50-237 | P |
| | 8303150383* | 50-237 | P |
| | 8303150389 | 50-249 | S |
| | 8303150395* | 50-249 | S |
| | 8303150422 | 50-373 | R |
| | 8303150426* | 50-373 | R |
| | 8303150439 | 50-254 | R |
| | 8303150439 | 50-254 | R |
| | 8303150583 | 50-456 | F |
| | 8303150583 | 50-456 | F |
| | 8303150611 | 50-237 | S |
| | 8303150611 | 50-237 | S |
| | 8303160389 | 50-254 | R |
| | 8303160389 | 50-254 | R |
| | 8303160391* | 50-254 | R |
| | 8303160391* | 50-254 | R |
| | 8303160578 | 50-10 | J |
| | 8303160578 | 50-10 | J |
| | 8303160578 | 50-10 | J |
| | 8303160578 | 50-10 | J |
| | 8303170307 | 50-373 | P |
| | 8303170310* | 50-373 | P |
| | 8303170322 | 50-237 | S |
| | 8303170327* | 50-237 | S |
| | 8303170335 | 50-304 | S |
| | 8303170354* | 50-304 | S |
| | 8303170378 | 50-254 | S |
| | 8303170379* | 50-254 | S |
| | 8303170424 | 50-254 | R |
| | 8303170424 | 50-254 | R |
| | 8303170468 | 50-254 | S |
| | 8303170473* | 50-254 | S |
| | 8303170477 | 50-373 | S |
| | 8303170478 | 50-373 | S |
| | 8303170481* | 50-373 | S |
| | 8303170486* | 50-373 | S |
| | 8303170487 | 50-237 | P |
| | 8303170497 | 50-295 | S |
| | 8303170502* | 50-295 | S |
| | 8303180489 | 50-373 | P |
| | 8303180489 | 50-373 | P |
| | 8303210325 | 50-295 | P |
| | 8303210325 | 50-295 | P |
| | 8303210356 | 50-373 | S |
| | 8303210359* | 50-373 | S |
| | 8303210431 | 50-373 | S |
| | 8303210441* | 50-373 | S |
| | 8303220056 | 50-374 | S |
| | 8303220081 | 50-295 | P |
| | 8303220093 | 50-249 | S |
| | 8303220107 | 50-373 | S |
| | 8303220109* | 50-373 | S |
| | 8303220145 | 50-374 | S |
| | 8303220165 | 50-373 | P |
| | 8303220166* | 50-373 | P |
| | 8303220256 | 50-295 | P |
| | 8303220256 | 50-295 | P |
| | 8303220293* | 50-454 | G |
| | 8303220311 | 50-456 | A |
| | 8303220317 | 50-454 | K |
| | 8303220317 | 50-454 | K |
| | 8303220317 | 50-454 | K |
| | 8303220317 | 50-454 | K |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY | |
|---|---|---|---|
| | 8303230149* | 50-10 | F |
| | 8303230155* | 50-10 | F |
| | 8303230176 | 50-247 | Q |
| | 8303230176 | 50-247 | Q |
| | 8303240078* | 50-254 | F |
| | 8303240078* | 50-254 | F |
| | 8303240085* | 50-254 | F |
| | 8303240085* | 50-254 | F |
| | 8303240184 | 50-237 | P |
| | 8303240198 | 5 -304 | S |
| | 8303240212* | 50-304 | S |
| | 8303240319 | 50-295 | P |
| | 8303240319 | 50-295 | P |
| | 8303240330 | 50-237 | Q |
| | 8303240355 | 50-254 | V |
| | 8303240387 | 50-373 | S |
| | 8303240388 | 50-237 | S |
| | 8303240389* | 50-373 | S |
| | 8303240396* | 50-237 | S |
| | 8303240421 | 50-373 | S |
| | 8303240424* | 50-373 | S |
| | 8303240541 | 50-254 | S |
| | 8303240547* | 50-254 | S |
| | 8303240550 | 50-454 | G |
| | 8303240550 | 50-454 | G |
| | 8303280062 | 50-295 | P |
| | 8303280062 | 50-295 | P |
| | 8303280159 | 50-454 | A |
| | 8303280270 | 50-237 | P |
| | 8303280270 | 50-237 | P |
| | 8303280293 | 50-295 | R |
| | 8303280293 | 50-295 | R |
| | 8303280299* | 50-295 | R |
| | 8303280299* | 50-295 | R |
| | 8303280301* | 50-454 | G |
| | 8303290266 | 50-456 | A |
| | 8303290266 | 50-456 | A |
| | 8303290269 | 50-374 | A |
| | 8303290284 | 50-237 | S |
| | 8303290297* | 50-237 | S |
| | 8303290526 | 50-295 | P |
| | 8303290526 | 50-295 | P |
| | 8303300011* | 50-254 | F |
| | 8303300011* | 50-254 | F |
| | 8303300017* | 50-254 | F |
| | 8303300017* | 50-254 | F |
| | 8303300459 | 50-454 | G |
| | 8303300459 | 50-454 | G |
| | 8303300459 | 50-454 | G |
| | 8303300459 | 50-454 | G |
| | 8303300561* | 50-10 | F |
| | 8303300561* | 50-10 | F |
| | 8303300561* | 50-10 | F |
| | 8303300561* | 50-10 | F |
| | 8303300561* | 50-10 | F |
| | 8303300561* | 50-10 | F |
| | 8303300722* | 50-295 | F |
| | 8303300722* | 50-295 | F |
| | 8303300744* | 50-254 | F |
| | 8303300744* | 50-254 | F |
| | 8303300756* | 50-254 | F |
| | 8303300756* | 50-254 | F |
| | 8303310005* | 50-295 | F |
| | 8303310005* | 50-295 | F |
| | 8303310087* | 50-373 | F |
| | 8303310087* | 50-373 | F |
| | 8303310092* | 50-373 | F |
| | 8303310130* | 50-10 | F |
| | 8303310130* | 50-10 | F |
| | 8303310130* | 50-10 | F |
| | 8303310130* | 50-10 | F |
| | 8303310130* | 50-10 | F |
| | 8303310130* | 50-10 | F |
| | 8303310146* | 50-10 | F |
| | 8303310146* | 50-10 | F |
| | 8303310146* | 50-10 | F |
| | 8303310146* | 50-10 | F |
| | 8303310146* | 50-10 | F |
| | 8303310146* | 50-10 | F |
| | 8303310146* | 50-10 | F |
| | 8303310211 | 50-237 | Q |
| | 8303310211 | 50-237 | Q |
| | 8303310229 | 50-237 | Q |
| Computer Data Systems, Inc. | 8303100005* | CONTRACT | |
| | 8303230135* | CONTRACT | |
| Conas Corp. | 8303210690* | GA999 | |
| Confederated Tribes & Bands Yakima Indian Nation | 8303290830 | WASTE MGT | |
| | 8303290834* | WASTE MGT | |
| Connecticut Yankee Atomic Power Co. | 8303030077 | 50-213 | P |
| | 8303030135 | 50-213 | S |
| | 8303030143* | 50-213 | S |
| | 8303040187* | 50-213 | P |
| | 8303040187* | 50-213 | P |
| | 8303040368 | 50-213 | Q |
| | 8303040368 | 50-213 | Q |
| | 8303080018 | 50-213 | R |
| | 8303080022* | 50-213 | R |
| | 8303080317 | 50-213 | P |
| | 8303080317 | 50-213 | P |
| | 8303080335 | 50-213 | P |
| | 8303090240* | 50-213 | F |
| | 8303090249* | 50-213 | F |
| | 8303150524 | 50-213 | R |
| | 8303150525* | 50-213 | R |
| | 8303180297 | 50-213 | Q |
| | 8303180297 | 50-213 | Q |
| | 8303180405 | 50-213 | P |
| | 8303210303 | 50-213 | P |
| | 8303220096 | 50-213 | F |
| | 8303220133 | 50-213 | P |
| | 8303230044 | 50-213 | P |
| | 8303230044 | 50-213 | P |
| | 8303230044 | 50-213 | P |
| | 8303240407 | 50-213 | R |
| | 8303240407 | 50-213 | R |
| | 8303240407 | 50-213 | R |
| | 8303240408* | 50-213 | R |
| | 8303240408* | 50-213 | R |
| | 8303240408* | 50-213 | R |
| | 8303290064* | 50-213 | F |
| | 8303290064* | 50-213 | F |
| | 8303290064* | 50-213 | F |
| | 8303290195 | 50-213 | P |
| | 8303290195 | 50-213 | P |
| | 8303290195 | 50-213 | P |
| | 8303290198 | 50-213 | P |
| | 8303290443 | 50-213 | P |
| | 8303310311 | 50-213 | P |
| | 8303310311 | 50-213 | P |
| | 8303310311 | 50-213 | P |
| | 8303310311 | 50-213 | P |
| | 8303310321 | 50-213 | P |
| Connecticut, State of | 8303290769* | CONTRACT | |
| Conner & Wetterhahn | 8303040439 | 50-352 | Q |
| | 8303150391 | 50-352 | Q |
| | 8303290438 | 50-352 | Q |
| | 8303290527 | 50-358 | Q |
| Conover & Associates, Inc. Insurance | 8303110275 | 70-1621 | |
| Conservation Council of North Carolina | 8303150397 | 50-400 | Q |
| | 8303150397 | 50-400 | Q |
| | 8303150400* | 50-400 | Q |
| | 8303150400* | 50-400 | Q |
| | 8303150405* | 50-400 | Q |
| | 8303150405* | 50-400 | Q |
| | 8303150411* | 50-400 | Q |
| | 8303150411* | 50-400 | Q |
| | 8303150593 | 50-400 | Q |
| Consolidated Edison Co. of New York, Inc. | 8303010385 | 50-247 | P |
| | 8303010395* | 50-247 | P |
| | 8303010397* | 50-247 | P |
| | 8303020046 | 50-247 | Q |
| | 8303020046 | 50-247 | Q |
| | 8303020052* | 50-247 | Q |
| | 8303020052* | 50-247 | Q |
| | 8303070110 | 50-247 | Q |
| | 8303070110 | 50-247 | Q |
| | 8303070125 | 50-247 | Q |
| | 8303070125 | 50-247 | Q |
| | 8303070134 | 50-247 | Q |
| | 8303070134 | 50-247 | Q |
| | 8303080109 | 50-247 | Q |
| | 8303080260 | 50-247 | V |
| | 8303080312 | 50-247 | P |
| | 8303080327 | 50-247 | Q |
| | 8303100199 | 50-3 | R |
| | 8303100199 | 50-3 | R |
| | 8303100203* | 50-3 | R |

# CORPORATE SOURCE INDEX

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303100203* | 50-3 R |
| | 8303100238 | 50-247 G |
| | 8303100238 | 50-247 G |
| | 8303100271 | 50-247 G |
| | 8303100271 | 50-247 G |
| | 8303100277 | 50-247 G |
| | 8303100277 | 50-247 G |
| | 8303110252 | 50-3 F |
| | 8303140215 | 50-247 P |
| | 8303140387 | 50-247 S |
| | 8303140390* | 50-247 S |
| | 8303150393 | 50-247 G |
| | 8303150393 | 50-247 G |
| | 8303150551 | 50-3 R |
| | 8303150551 | 50-3 R |
| | 8303150569* | 50-3 R |
| | 8303150569* | 50-3 R |
| | 8303150602 | 50-247 G |
| | 8303160156 | 50-247 S |
| | 8303160168* | 50-247 S |
| | 8303160249 | 50-247 S |
| | 8303170279 | 50-247 G |
| | 8303170279 | 50-247 G |
| | 8303180277 | 50-247 G |
| | 8303180277 | 50-247 G |
| | 8303220231 | 50-247 G |
| | 8303220261 | 50-247 G |
| | 8303220291 | 50-247 R |
| | 8303220297* | 50-247 R |
| | 8303230047 | 50-3 F |
| | 8303240418 | 50-247 G |
| | 8303250077* | 50-247 G |
| | 8303250145 | 50-247 T |
| | 8303250145 | 50-247 T |
| | 8303250149* | 50-247 T |
| | 8303250149* | 50-247 T |
| | 8303280210* | 50-247 G |
| | 8303290498 | 50-247 P |
| | 8303300303 | 50-247 G |
| | 8303300303 | 50-247 G |
| | 8303300307* | 50-247 G |
| | 8303300307* | 50-247 G |
| | 8303300313* | 50-247 G |
| | 8303300313* | 50-247 G |
| | 8303300319* | 50-247 G |
| | 8303300319* | 50-247 G |
| | 8303300322* | 50-247 G |
| | 8303300322* | 50-247 G |
| | 8303300326 | 50-247 G |
| | 8303300326 | 50-247 G |
| | 8303300374 | 50-247 G |
| | 8303310303 | 50-247 G |
| Consumers Power Co | 8303010077 | 50-329 G |
| | 8303010171 | 50-329 G |
| | 8303010171 | 50-329 G |
| | 8303010179 | 50-329 G |
| | 8303020041 | 50-155 G |
| | 8303030403 | 50-329 T |
| | 8303030403 | 50-329 T |
| | 8303030413* | 50-329 T |
| | 8303030413* | 50-329 T |
| | 8303040339 | 50-155 P |
| | 8303040427 | 50-155 G |
| | 8303040427 | 50-155 G |
| | 8303040427 | 50-155 G |
| | 8303040445 | 50-155 G |
| | 8303040494 | 50-255 P |
| | 8303040512 | 50-155 V |
| | 8303040512 | 50-155 V |
| | 8303040512 | 50-155 V |
| | 8303040539 | 50-329 A |
| | 8303070035 | 50-255 P |
| | 8303070057 | 50-155 P |
| | 8303080028 | 50-155 R |
| | 8303080033* | 50-155 R |
| | 8303080153 | 50-255 S |
| | 8303080160* | 50-255 S |
| | 8303080193 | 50-255 S |
| | 8303080199* | 50-255 S |
| | 8303080219 | 50-255 S |
| | 8303080228* | 50-255 S |
| | 8303080255 | 50-255 G |
| | 8303080283 | 50-255 G |
| | 8303080456 | 50-255 S |
| | 8303080473* | 50-255 S |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303080476 | 50-255 S |
| | 8303080488* | 50-255 S |
| | 8303080500 | 50-255 R |
| | 8303080505* | 50-255 R |
| | 8303090140 | 50-329 A |
| | 8303090140 | 50-329 A |
| | 8303090152* | 50-329 A |
| | 8303090152* | 50-329 A |
| | 8303100188 | 50-329 S |
| | 8303100188 | 50-329 S |
| | 8303100208 | 50-329 R |
| | 8303100208 | 50-329 R |
| | 8303100219 | 50-329 S |
| | 8303100263 | 50-329 S |
| | 8303100263 | 50-329 S |
| | 8303100310 | 50-329 S |
| | 8303100310 | 50-329 S |
| | 8303100384 | 50-329 S |
| | 8303100384 | 50-329 S |
| | 8303110251 | 50-329 E |
| | 8303110251 | 50-329 E |
| | 8303110253* | 50-329 E |
| | 8303110253* | 50-329 E |
| | 8303110263* | 50-329 E |
| | 8303110263* | 50-329 E |
| | 8303140210 | 50-329 A |
| | 8303140210 | 50-329 A |
| | 8303140320 | 50-255 R |
| | 8303140323* | 50-255 R |
| | 8303140368 | 50-329 S |
| | 8303140368 | 50-329 S |
| | 8303140371 | 50-329 S |
| | 8303140371 | 50-329 S |
| | 8303140398 | 50-329 G |
| | 8303140410 | 50-255 R |
| | 8303140415* | 50-255 R |
| | 8303140432* | 50-329 T |
| | 8303140463 | 50-329 S |
| | 8303140510 | 50-255 S |
| | 8303140531* | 50-255 S |
| | 8303140534 | 50-329 A |
| | 8303150514 | 50-155 R |
| | 8303150529* | 50-155 R |
| | 8303170096 | 50-155 P |
| | 8303170098 | 50-155 P |
| | 8303170147 | 50-255 G |
| | 8303170388 | 50-329 A |
| | 8303170388 | 50-329 A |
| | 8303170393 | 50-329 A |
| | 8303170393 | 50-329 A |
| | 8303170489 | 50-329 A |
| | 8303170508 | 50-329 A |
| | 8303170508 | 50-329 A |
| | 8303170509 | 50-155 G |
| | 8303180021 | 50-255 G |
| | 8303180167 | 50-255 P |
| | 8303180209 | 50-329 G |
| | 8303180209 | 50-329 G |
| | 8303180352 | 50-155 P |
| | 8303180398 | 50-329 G |
| | 8303180398 | 50-329 G |
| | 8303180492 | 50-255 F |
| | 8303210060 | 70-2964 |
| | 8303210150 | 50-155 F |
| | 8303210157 | 50-155 P |
| | 8303210279 | 50-155 I |
| | 8303210279 | 50-155 I |
| | 8303210279 | 50-155 I |
| | 8303210279 | 50-155 I |
| | 8303210286* | 50-155 I |
| | 8303210286* | 50-155 I |
| | 8303210286* | 50-155 I |
| | 8303210286* | 50-155 I |
| | 8303220016 | 50-329 R |
| | 8303220065* | 50-255 G |
| | 8303220082* | 50-329 A |
| | 8303220082* | 50-329 A |
| | 8303220099 | 50-255 P |
| | 8303220141 | 50-255 S |
| | 8303220143* | 50-255 P |
| | 8303220151 | 50-255 P |
| | 8303220172 | 50-329 G |
| | 8303220172 | 50-329 G |
| | 8303220298* | 50-255 P |
| | 8303220306 | 50-155 J |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303220310 | 50-255 J |
| | 8303220370 | 50-329 A |
| | 8303220370 | 50-329 A |
| | 8303240014 | 50-255 S |
| | 8303240027 | 50-329 F |
| | 8303240027 | 50-329 F |
| | 8303240043 | 50-329 A |
| | 8303240043 | 50-329 A |
| | 8303240211 | 50-329 S |
| | 8303240211 | 50-329 S |
| | 8303240266 | 50-329 A |
| | 8303240266 | 50-329 A |
| | 8303240384* | 50-155 F |
| | 8303240386 | 50-454 G |
| | 8303240451 | 50-329 A |
| | 8303240458 | 50-329 E |
| | 8303280026 | 50-255 G |
| | 8303280029 | 50-155 P |
| | 8303280031 | 50-329 A |
| | 8303280031 | 50-329 A |
| | 8303280071 | 50-329 A |
| | 8303280075 | 50-329 A |
| | 8303280108 | 50-329 A |
| | 8303280108 | 50-329 A |
| | 8303280120* | 50-329 E |
| | 8303280120* | 50-329 E |
| | 8303280135 | 50-329 S |
| | 8303280135 | 50-329 S |
| | 8303280161 | 50-155 R |
| | 8303280166* | 50-155 R |
| | 8303280232 | 50-329 A |
| | 8303280250 | 50-255 P |
| | 8303280275 | 50-330 A |
| | 8303290455 | 50-329 G |
| | 8303290530 | 50-155 G |
| | 8303290533* | 50-155 G |
| Continuum Dynamics, Inc. | 8303290305* | 50-277 P |
| Control Data Corp | 8303040606* | GA999 |
| | 8303310352* | CONTRACT |
| Cooper Industries, Inc. | 8303210666* | GA999 |
| | 8303210677* | GA999 |
| Cotter Corp. | 8303090036 | WASTE MGT |
| | 8303090037* | WASTE MGT |
| | 8303090147 | WASTE MGT |
| | 8303090157* | WASTE MGT |
| | 8303180135 | WASTE MGT |
| | 8303180142* | WASTE MGT |
| | 8303220412 | WASTE MGT |
| | 8303220419* | WASTE MGT |
| | 8303240103 | WASTE MGT |
| | 8303240108* | WASTE MGT |
| | 8303300050 | WASTE MGT |
| | 8303300056* | WASTE MGT |
| Council on Economic Priorities | 8303010121 | 71-6698 |
| | 8303020144 | 71-6698 |
| Daedalean Associates, Inc. | 8303030383* | CONTRACT |
| Dairyland Power Cooperative | 8303020030 | 50-409 P |
| | 8303080221 | 50-409 R |
| | 8303080227* | 50-409 R |
| | 8303080275 | 50-409 R |
| | 8303080279* | 50-409 R |
| | 8303150234* | 50-409 G |
| | 8303150410 | 50-409 R |
| | 8303150412* | 50-409 R |
| | 8303170095 | 50-409 R |
| | 8303170101* | 50-409 R |
| | 8303210437 | 50-409 P |
| | 8303220140 | 50-409 G |
| | 8303220268 | 50-409 P |
| | 8303220358 | 50-409 P |
| | 8303290408* | 50-409 P |
| Dames & Moore | 8303150031 | NUREG |
| | 8303180180* | 40-4492 |
| | 8303290192* | CONTRACT |
| Dayton T. Brown, Inc. | 8303110262* | 50-389 A |
| DeKalb Area Alliance for Responsible Energy | 8303070034 | 50-454 T |
| | 8303070034 | 50-454 T |
| | 8303070049* | 50-454 T |
| | 8303070054* | 50-454 T |
| | 8303070155 | 50-454 G |
| | 8303070155 | 50-454 G |
| | 8303090142 | 50-454 T |
| | 8303220198* | 50-454 T |
| | 8303300409 | 50-454 T |
| | 8303300431* | 50-454 T |
| Debevoise & Liberman | 8303010316 | 50-445 G |
| | 8303010316 | 50-445 G |
| | 8303010333 | 50-445 G |
| | 8303010333 | 50-445 G |
| | 8303020036 | 50-460 G |
| | 8303020057 | 50-460 G |
| | 8303040223* | 10CFR |
| | 8303040534 | 50-413 G |
| | 8303070122 | 50-445 G |
| | 8303070122 | 50-445 G |
| | 8303080024 | 50-445 G |
| | 8303080024 | 50-445 G |
| | 8303080034 | 50-460 G |
| | 8303110218 | 50-508 G |
| | 8303110236 | 50-508 G |
| | 8303180371 | 50-445 G |
| | 8303180406 | 50-445 G |
| | 8303220250 | 50-460 G |
| | 8303230228 | 50-445 G |
| | 8303230490 | FOIA |
| | 8303240519 | 50-445 G |
| | 8303310263 | 50-445 G |
| | 8303310263 | 50-445 G |
| | 8303310272 | 50-445 G |
| | 8303310272 | 50-445 G |
| Defense, Dept. of, Defense Nuclear Agency | 8303010163 | 50-170 G |
| | 8303250129 | 50-170 P |
| Del-Aware Unlimited, Inc. | 8303140352 | 50-352 G |
| | 8303140352 | 50-352 G |
| | 8303140356* | 50-352 G |
| | 8303140356* | 50-352 G |
| | 8303250167 | 50-352 G |
| Delmarva Power & Light Co. | 8303170193* | 50-171 I |
| Design Review Panel | 8303140236 | REVIEW GRP |
| | 8303140241* | REVIEW GRP |
| | 8303140257 | REVIEW GRP |
| | 8303140264* | REVIEW GRP |
| Detroit Edison Co. | 8303010631 | 50-341 S |
| | 8303070094 | 50-341 V |
| | 8303080001 | 50-341 E |
| | 8303080072 | 50-341 G |
| | 8303170382 | 50-341 G |
| | 8303210336 | 50-341 A |
| | 8303220184* | 50-341 G |
| | 8303220484 | 70-2926 |
| | 8303220485* | 70-2926 |
| | 8303250099 | 50-341 A |
| | 8303300203 | 50-16 J |
| Dorsey, J.A. | 8302030448* | 50-352 G |
| | 8303180252 | 50-352 G |
| Dougherty, J.B. | 8303010408 | 50-322 G |
| | 8303220241 | 50-322 G |
| Dow Chemical Co. | 8303220475 | 40-17 |
| | 8303220479* | 40-17 |
| Duke Power Co. | 8302240208 | 50-413 K |
| | 8302240208 | 50-413 K |
| | 8302240210* | 50-413 K |
| | 8302240210* | 50-413 K |
| | 8303010200 | 50-413 G |
| | 8303010301 | 50-413 G |
| | 8303010311 | 50-369 P |
| | 8303010311 | 50-369 P |
| | 8303010496 | 50-413 A |
| | 8303010496 | 50-413 A |
| | 8303010531 | 50-414 S |
| | 8303010534 | 50-370 G |
| | 8303010562 | 50-369 S |
| | 8303010571* | 50-369 S |
| | 8303010572 | TOPREP |
| | 8303010591 | TOPREP |
| | 8303010650 | 50-369 G |
| | 8303010666 | 50-269 G |
| | 8303040233* | 10CFR |
| | 8303040534 | 50-413 G |
| | 8303040534 | 50-413 G |
| | 8303040536 | 50-369 P |
| | 8303040640 | TOPREP |
| | 8303040643* | TOPREP |
| | 8303070141 | 50-413 A |
| | 8303070141 | 50-413 A |
| | 8303070141 | 50-413 A |
| | 8303070152* | 50-413 A |
| | 8303070152* | 50-413 A |
| | 8303070152* | 50-413 A |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303070158* | 50-413 A |
| | 8303070158* | 50-413 A |
| | 8303070158* | 50-413 A |
| | 8303070164* | 50-413 A |
| | 8303070167* | 50-413 A |
| | 8303070167* | 50-413 A |
| | 8303070167* | 50-413 A |
| | 8303070169* | 50-413 A |
| | 8303070177* | 50-413 A |
| | 8303070173* | 50-413 A |
| | 8303070173* | 50-413 A |
| | 8303080084 | 50-269 I |
| | 8303080084 | 50-269 I |
| | 8303080084 | 50-269 I |
| | 8303080084 | 50-269 I |
| | 8303080092* | 50-269 I |
| | 8303080294 | 50-369 P |
| | 8303080294 | 50-369 P |
| | 8303080294 | 50-369 P |
| | 8303080324* | 50-369 P |
| | 8303080324* | 50-369 P |
| | 8303080324* | 50-369 P |
| | 8303080324* | 50-369 P |
| | 8303080324* | 50-369 P |
| | 8303080324* | 50-369 P |
| | 8303080324* | 50-369 P |
| | 8303080353 | 50-269 R |
| | 8303080353 | 50-269 R |
| | 8303080353 | 50-269 R |
| | 8303080364* | 50-269 R |
| | 8303080364* | 50-269 R |
| | 8303080364* | 50-269 R |
| | 8303080492 | 50-369 J |
| | 8303080492 | 50-369 J |
| | 8303090148 | 50-369 P |
| | 8303090162 | 50-413 F |
| | 8303090163 | 50-269 P |
| | 8303090163 | 50-269 P |
| | 8303090163 | 50-269 P |
| | 8303090210 | 50-369 P |
| | 8303090210 | 50-369 P |
| | 8303090214 | 50-370 A |
| | 8303100168* | 50-413 F |
| | 8303100174* | 50-413 F |
| | 8303110214 | 50-413 G |
| | 8303140379 | 50-369 S |
| | 8303140382* | 50-369 S |
| | 8303140391 | 50-369 S |
| | 8303140392* | 50-369 S |
| | 8303140395 | 50-413 A |
| | 8303140397* | 50-413 A |
| | 8303140515 | 50-413 S |
| | 8303150294 | 50-370 S |
| | 8303150317 | 50-369 P |
| | 8303150317 | 50-369 P |
| | 8303150416 | 50-369 P |
| | 8303150416 | 50-369 P |
| | 8303150451 | 50-369 S |
| | 8303150457* | 50-369 S |
| | 8303150483 | 50-269 P |
| | 8303160270 | 50-369 P |
| | 8303160510 | 50-269 P |
| | 8303160555 | 50-269 S |
| | 8303160560* | 50-269 S |
| | 8303160565 | 50-269 S |
| | 8303160572* | 50-269 S |
| | 8303180332 | 50-287 S |
| | 8303180338* | 50-287 S |
| | 8303180345 | 50-369 P |
| | 8303180347 | 50-370 P |
| | 8303180373 | 50-369 R |
| | 8303180376* | 50-369 R |
| | 8303180379 | 50-269 R |
| | 8303180379 | 50-269 R |
| | 8303180379 | 50-269 R |
| | 8303180386* | 50-269 R |
| | 8303180386* | 50-269 R |
| | 8303180386* | 50-269 R |
| | 8303180404 | 50-269 S |
| | 8303180408* | 50-269 S |
| | 8303180533 | 50-369 P |
| | 8303180533 | 50-369 P |
| | 8303180538* | 50-369 P |
| | 8303180538* | 50-369 P |
| | 8303210268 | 50-369 G |
| | 8303210430 | 50-370 G |
| | 8303210447 | 50-370 G |
| | 8303210471 | 50-413 G |
| | 8303210471 | 50-413 G |
| | 8303210479 | 50-413 G |
| | 8303210536 | 50-370 G |
| | 8303210540 | 50-369 G |
| | 8303210542 | 50-369 G |
| | 8303210542 | 50-369 G |
| | 8303210640 | 50-413 S |
| | 8303220023 | 50-287 S |
| | 8303220103 | 50-414 S |
| | 8303220321 | 50-370 F |
| | 8303220321 | 50-370 F |
| | 8303230220 | 50-269 G |
| | 8303230222 | 50-369 P |
| | 8303230222 | 50-369 P |
| | 8303230242 | 50-413 G |
| | 8303230269 | 50-413 E |
| | 8303240120* | 50-269 F |
| | 8303240127* | 50-269 F |
| | 8303240127* | 50-269 F |
| | 8303240127* | 50-269 F |
| | 8303240127* | 50-269 F |
| | 8303240127* | 50-269 F |
| | 8303240127* | 50-269 F |
| | 8303240127* | 50-269 F |
| | 8303240127* | 50-269 F |
| | 8303240228 | 50-287 P |
| | 8303240235* | 50-287 P |
| | 8303240270 | 50-269 P |
| | 8303240270 | 50-269 P |
| | 8303240270 | 50-269 P |
| | 8303240378 | 50-369 P |
| | 8303240378 | 50-369 P |
| | 8303240381 | 50-369 P |
| | 8303240381 | 50-369 P |
| | 8303240465 | 50-269 P |
| | 8303240465 | 50-269 P |
| | 8303240465 | 50-269 P |
| | 8303240599 | 50-369 J |
| | 8303240604* | 50-369 S |
| | 8303250095* | 50-369 F |
| | 8303250095* | 50-369 F |
| | 8303250100* | 50-369 F |
| | 8303250100* | 50-369 F |
| | 8303250146 | 50-413 G |
| | 8303280032 | 50-269 P |
| | 8303280138* | 50-269 G |
| | 8303280193 | 50-413 A |
| | 8303280194 | 50-269 P |
| | 8303280194 | 50-269 P |
| | 8303280194 | 50-269 P |
| | 8303280200* | 50-269 P |
| | 8303280200* | 50-269 P |
| | 8303280200* | 50-269 P |
| | 8303280212* | 50-413 A |
| | 8303290217 | 50-269 P |
| | 8303290475 | 50-269 F |
| | 8303290475 | 50-269 F |
| | 8303290475 | 50-269 F |
| | 8303290475 | 50-269 F |
| | 8303290475 | 50-269 F |
| | 8303290475 | 50-269 F |
| | 8303300119 | 50-369 P |
| | 8303310050 | 50-369 P |
| | 8303310050 | 50-369 P |
| | 8303310062* | 50-369 P |
| | 8303310062* | 50-369 P |
| Duquesne Light Co | 8302250194 | 50-334 S |
| | 8302250202* | 50-334 S |
| | 8303030286 | 50-412 S |
| | 8303040375 | 50-334 S |
| | 8303040382* | 50-334 S |
| | 8303040564 | 50-334 P |
| | 8303070041 | 50-334 S |
| | 8303070046* | 50-334 S |
| | 8303070148 | 50-334 S |
| | 8303070159* | 50-334 S |
| | 8303080246 | 50-334 R |
| | 8303080251* | 50-334 R |
| | 8303080291 | 50-334 P |
| | 8303080381 | 50-334 R |
| | 8303080387* | 50-334 R |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303080447 | 50-334 V |
| | 8303090283 | 50-412 V |
| | 8303100196 | 50-334 Q |
| | 8303110061* | 50-334 S |
| | 8303110212 | 50-334 F |
| | 8303110218 | 50-508 Q |
| | 8303110220* | 50-334 F |
| | 8303110383 | 50-334 F |
| | 8303140502 | 50-334 S |
| | 8303140512* | 50-334 S |
| | 8303150335 | 50-334 R |
| | 8303150337* | 50-334 R |
| | 8303150372 | 50-334 R |
| | 8303150381* | 50-334 R |
| | 8303160224* | 50-412 Q |
| | 8303240094 | 50-334 P |
| | 8303240380 | 50-334 S |
| | 8303240388* | 50-334 S |
| | 8303290008 | 50-334 P |
| | 8303290473 | 50-334 P |
| | 8303310246 | 50-334 P |
| | 8303310248* | 50-334 P |
| | 8303310497* | 50-334 F |
| | 8303310502* | 50-334 F |
| | 8303310515* | 50-334 F |
| E.H. Bourquard Associates, Inc. | 8303010447* | 50-352 A |
| EDS Nuclear, Inc. | 8303280204* | 50-413 A |
| | 8303280223* | 50-413 A |
| EG&G, Inc. | 8209030274* | 50-213 P |
| | 8302160446* | 50-275 P |
| | 8303030765* | 50-275 P |
| | 8303140628 | NUREG |
| | 8303150614 | NUREG |
| | 8303160155 | RES |
| | 8303160164 | RES |
| | 8303160758 | RES |
| | 8303180549 | RES |
| | 8303180555 | RES |
| | 8303180568 | RES |
| | 8303180579 | RES |
| | 8303180613 | RES |
| | 8303180672 | RES |
| | 8303180674 | RES |
| | 8303180694 | RES |
| | 8303180696 | RES |
| | 8303180699 | RES |
| | 8303210186 | RES |
| | 8303220394 | NUREG |
| | 8303220400 | NUREG |
| | 8303220409 | NUREG |
| | 8303230281 | NUREG |
| | 8303240137 | RES |
| | 8303240140 | RES |
| | 8303240144 | RES |
| | 8303240146 | RES |
| | 8303240167 | RES |
| | 8303240268 | 50-302 P |
| | 8303240275 | RES |
| | 8303280329 | RES |
| | 8303290797 | 50-255 P |
| | 8303300021* | 50-269 P |
| | 8303300021* | 50-269 P |
| | 8303300103 | RES |
| | 8303300108 | 50-269 P |
| | 8303300164 | 50-269 P |
| | 8303300623 | RES |
| East Kingston, NH | 8303140559* | 50-443 Q |
| Ebasco Services, Inc. (subs. of Enserch Corp.) | 8303010345* | 50-454 T |
| | 8303010607* | 50-382 A |
| | 8303030642* | QA999 |
| | 8303080131* | 50-389 A |
| | 8303160667* | CONTRACT |
| | 8303250143* | 50-261 P |
| Eberline Instrument Corp. | 8303030495 | XPORTLIC |
| | 8303210609* | QA999 |
| Ecological Analysts, Inc. | 8303040587* | 50-219 R |
| Eddleman, W. | 8303150603 | 50-400 Q |
| | 8303220238 | 50-400 Q |
| | 8303220320 | 50-400 Q |
| | 8303300334 | 50-400 Q |
| | 8303300334 | 50-400 Q |
| | 8303300339* | 50-400 Q |
| | 8303300339* | 50-400 Q |
| | 8303300347 | 50-400 Q |
| | 8303300347 | 50-400 Q |
| | 8303300353* | 50-400 Q |
| | 8303300353* | 50-400 Q |
| Edgar, G.L. | 8303290422 | 50-537 Q |
| Edison Electric Institute | 8302100345 | PRM |
| | 8303090137 | TOPREP |
| Edlow International Co. | 8303030310 | 71-6642 |
| | 8303110072 | 70-2322 |
| | 8303140660 | XPORTLIC |
| | 8303150698 | XPORTLIC |
| | 8303160045 | XPORTLIC |
| | 8303160050* | XPORTLIC |
| | 8303180189 | XPORTLIC |
| | 8303230214 | XPORTLIC |
| | 8303230366* | XPORTLIC |
| | 8303290099 | XPORTLIC |
| | 8303290118 | XPORTLIC |
| | 8303290173* | XPORTLIC |
| Electric Power Research Institute | 8303010254 | NUREG |
| | 8303030267* | CONTRACT |
| | 8303090659 | NUREG |
| Electro-Mechanics, Inc. | 8303110268* | 50-389 A |
| | 8303110271* | 50-389 A |
| End Nuclear Dumping in the Pacific | 8303230197 | FOIA |
| Energy Fuels Nuclear, Inc. | 8303140692 | 40-8681 |
| | 8303140695* | 40-8681 |
| | 8303230388 | 40-8681 |
| | 8303230391* | 40-8681 |
| | 8303300231 | 40-8681 |
| | 8303300242 | 40-8681 |
| Energy, Dept. of | 8303010083 | WASTE MGT |
| | 8303010092 | WASTE MGT |
| | 8303020022 | 70-143 |
| | 8303030006* | 50-201 P |
| | 8303030218* | 50-416 P |
| | 8303030654* | 50-537 B |
| | 8303070160 | 70-143 |
| | 8303080497 | 50-537 Q |
| | 8303100347 | 71-5364 |
| | 8303110014 | 71-6387 |
| | 8303110028* | 71-6387 |
| | 8303150028 | TOPREP |
| | 8303150368 | 70-143 |
| | 8303150382* | 70-143 |
| | 8303150386* | 70-143 |
| | 8303180016 | XPORTLIC |
| | 8303180056 | WASTE MGT |
| | 8303180061 | WASTE MGT |
| | 8303180202 | WASTE MGT |
| | 8303180203 | 70-143 |
| | 8303180462 | 71-5874 |
| | 8303180469* | 71-5874 |
| | 8303230284 | ORG |
| | 8303230287* | ORG |
| | 8303280055 | 71-4909 |
| | 8303280060 | 71-9152 |
| | 8303280073 | WASTE MGT |
| | 8303280091 | WASTE MGT |
| | 8303290550 | WASTE MGT |
| | 8303290569 | WASTE MGT |
| | 8303300053 | WASTE MGT |
| | 8303300083 | WASTE MGT |
| | 8303300091 | WASTE MGT |
| | 8303300124 | WASTE MGT |
| | 8303310256* | 50-445 T |
| Energy, Dept. of, Clinch River Breeder Reactor Plant | 8303010505 | 50-537 A |
| | 8303010510 | 50-537 F |
| | 8303010573 | 50-537 Q |
| | 8303030652 | 50-537 B |
| | 8303070003 | 50-537 A |
| | 8303070005 | 50-537 A |
| | 8303070061 | 50-537 A |
| | 8303070100 | 50-537 A |
| | 8303070112 | 50-537 A |
| | 8303070120* | 50-537 A |
| | 8303090298 | 50-537 A |
| | 8303090306 | 50-537 A |
| | 8303150458 | 50-537 Q |
| | 8303250013 | 50-537 A |
| | 8303290422 | 50-537 Q |
| Energy, Dept. of, Idaho Operations Office | 8303030003 | 50-201 P |
| | 8303290260 | 50-201 P |
| Engineering & Economics Research, Inc. | 8303110067* | 50-537 A |
| Environmental Coalition on Nuclear Power | 8303020063 | 50-277 Q |

# CORPORATE SOURCE INDEX

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY | |
|---|---|---|---|
| Environmental Protection Agency | 8303020129 | 40-2061 | |
| | 8303040579 | 50-327 | S |
| | 8303040579 | 50-327 | S |
| | 8303040586* | 50-327 | S |
| | 8303040586* | 50-327 | S |
| Ertec, Inc | 8303160060* | CONTRACT | |
| European Communities, Commission of | 8303020108 | XPORTLIC | |
| | 8303020112 | XPORTLIC | |
| | 8303040001 | XPORTLIC | |
| | 8303170022 | XPORTLIC | |
| | 8303280104 | XPORTLIC | |
| Extran, Inc | 8303090614* | ORG | |
| | 8303090630* | ORG | |
| | 8303090639* | ORG | |
| | 8303090653* | ORG | |
| Exxon Corp | 8303160664 | 40-8064 | |
| | 8303180169 | 40-8102 | |
| | 8303180172* | 40-8102 | |
| Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) | 8303150681 | XPORTLIC | |
| | 8303180010 | 40-8102 | |
| | 8303180015* | 40-8102 | |
| | 8303180019* | 40-8102 | |
| | 8303210355 | TOPREP | |
| | 8303210781 | 70-1257 | |
| | 8303220114 | TOPREP | |
| | 8303300376 | TOPREP | |
| FPE Group, The | 8303180688* | CONTRACT | |
| Falkenheiner, D | 8303300329 | 50-458 | Q |
| Federal American Partners | 8303090390 | 40-4492 | |
| | 8303090513 | 40-4492 | |
| | 8303090526* | 40-4492 | |
| | 8303140687 | 40-4492 | |
| | 8303180173 | 40-4492 | |
| Federal Emergency Management Agency | 8303010403* | 50-454 | T |
| | 8303150230 | 50-344 | F |
| | 8303160513 | 50-335 | F |
| | 8303160593 | 50-254 | F |
| | 8303160596* | 50-254 | F |
| | 8303160600* | 50-254 | F |
| | 8303310266* | 50-445 | T |
| Fleming, Anderson, McClung & Finch | 8303230183 | 50-361 | Q |
| Flexitallic Gasket Co., Inc | 8303030221 | FOIA | |
| | 8303030230 | FOIA | |
| Florida Power & Light Co | 8303010153* | 50-250 | G |
| | 8303010153* | 50-250 | G |
| | 8303010261 | 50-389 | S |
| | 8303010280 | 50-389 | G |
| | 8303010604* | 50-250 | G |
| | 8303010610* | 50-250 | G |
| | 8303010681* | 50-250 | G |
| | 8303010681* | 50-250 | G |
| | 8303020086 | 50-389 | K |
| | 8303020091* | 50-389 | K |
| | 8303030499 | 50-335 | P |
| | 8303030554 | 50-250 | F |
| | 8303030554 | 50-250 | F |
| | 8303030554 | 50-250 | F |
| | 8303040338 | 50-250 | H |
| | 8303040346 | 50-389 | F |
| | 8303040458 | 50-389 | F |
| | 8303040460 | 50-389 | S |
| | 8303040464 | 50-389 | S |
| | 8303040514 | 50-335 | G |
| | 8303040619 | 50-250 | P |
| | 8303040619 | 50-250 | P |
| | 8303040638 | 50-389 | G |
| | 8303080051 | 50-250 | P |
| | 8303080051 | 50-250 | P |
| | 8303080126 | 50-389 | A |
| | 8303080318 | 50-250 | V |
| | 8303080318 | 50-250 | V |
| | 8303080389 | 50-250 | R |
| | 8303080389 | 50-250 | R |
| | 8303080391* | 50-250 | R |
| | 8303080391* | 50-250 | R |
| | 8303080399 | 50-250 | P |
| | 8303080399 | 50-250 | P |
| | 8303080402 | 50-250 | R |
| | 8303080402 | 50-250 | R |
| | 8303080402 | 50-250 | R |
| | 8303080402 | 50-250 | R |
| | 8303080408* | 50-250 | R |
| | 8303080408* | 50-250 | R |
| | 8303080408* | 50-250 | R |
| | 8303080408* | 50-250 | R |
| | 8303080408* | 50-250 | R |
| | 8303080422 | 50-335 | S |
| | 8303080426* | 50-335 | S |
| | 8303090138 | 50-335 | R |
| | 8303090165* | 50-335 | R |
| | 8303090340 | 50-389 | E |
| | 8303100164 | 50-389 | A |
| | 8303100254 | 50-389 | E |
| | 8303100352 | 50-250 | P |
| | 8303100352 | 50-250 | P |
| | 8303110257 | 50-389 | A |
| | 8303110287 | 50-250 | P |
| | 8303110287 | 50-250 | P |
| | 8303140057 | 50-335 | P |
| | 8303140093* | 50-335 | P |
| | 8303140204 | 50-250 | P |
| | 8303140204 | 50-250 | P |
| | 8303140232 | 50-250 | Q |
| | 8303140521 | 50-250 | P |
| | 8303140521 | 50-250 | P |
| | 8303140527* | 50-250 | P |
| | 8303140527* | 50-250 | P |
| | 8303150165 | 50-389 | S |
| | 8303150312 | 50-389 | A |
| | 8303150318 | 50-251 | R |
| | 8303150321* | 50-251 | R |
| | 8303150434 | 50-335 | P |
| | 8303150528 | 50-389 | E |
| | 8303150538* | 50-389 | E |
| | 8303150539 | 50-250 | R |
| | 8303150539 | 50-250 | R |
| | 8303150539 | 50-250 | R |
| | 8303150539 | 50-250 | R |
| | 8303150546* | 50-250 | R |
| | 8303150546* | 50-250 | R |
| | 8303150546* | 50-250 | R |
| | 8303150546* | 50-250 | R |
| | 8303150558* | 50-250 | R |
| | 8303150558* | 50-250 | R |
| | 8303160171 | 50-335 | P |
| | 8303160177* | 50-335 | P |
| | 8303160200 | 50-335 | P |
| | 8303160228 | 50-389 | A |
| | 8303160257 | 50-250 | F |
| | 8303160257 | 50-250 | F |
| | 8303160257 | 50-250 | F |
| | 8303160257 | 50-250 | F |
| | 8303160267 | 50-250 | P |
| | 8303160267 | 50-250 | P |
| | 8303160360 | 50-335 | P |
| | 8303160575 | 50-335 | S |
| | 8303160586* | 50-335 | S |
| | 8303170304 | 50-335 | P |
| | 8303170504 | 50-250 | P |
| | 8303210352 | 50-335 | Q |
| | 8303210397 | 50-335 | S |
| | 8303210402* | 50-335 | S |
| | 8303210512* | 50-389 | Q |
| | 8303210550 | 50-250 | S |
| | 8303210557* | 50-250 | S |
| | 8303210622 | 50-250 | Q |
| | 8303210645 | 50-250 | Q |
| | 8303210645 | 50-250 | Q |
| | 8303210706* | 50-389 | Q |
| | 8303210779 | 70-2957 | |
| | 8303240130* | 50-335 | F |
| | 8303240130* | 50-335 | F |
| | 8303240133* | 50-335 | F |
| | 8303240133* | 50-335 | F |
| | 8303240208 | 50-389 | A |
| | 8303240210 | 50-389 | E |
| | 8303240357 | 50-250 | P |
| | 8303240437 | 50-389 | A |
| | 8303240446 | 50-389 | A |
| | 8303240459 | 50-389 | A |
| | 8303240501 | 50-335 | P |
| | 8303240569 | 50-389 | S |
| | 8303240578 | 50-389 | S |
| | 8303250010 | 50-389 | F |
| | 8303250017 | 50-389 | A |
| | 8303250040 | 50-389 | A |
| | 8303250075 | 50-250 | P |
| | 8303250085 | 50-389 | A |
| | 8303250096 | 50-389 | A |
| | 8303250103* | 50-389 | A |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303250128 | 50-389 F |
| | 8303280028 | 50-389 R |
| | 8303280087 | 50-389 A |
| | 8303280090* | 50-389 A |
| | 8303280206 | 50-389 A |
| | 8303280278 | 50-335 P |
| | 8303290433* | 50-250 G |
| | 8303290472 | 50-389 A |
| | 8303300143 | 50-335 F |
| | 8303300143 | 50-335 F |
| | 8303300224 | 50-389 A |
| | 8303300230* | 50-389 A |
| | 8303300249 | 50-335 P |
| | 8303300249 | 50-335 P |
| | 8303300254* | 50-335 P |
| | 8303300254* | 50-335 P |
| | 8303300273 | 50-389 A |
| | 8303300301 | 50-250 P |
| | 8303300301 | 50-250 P |
| | 8303300398 | 50-250 P |
| | 8303300398 | 50-250 P |
| | 8303310057 | 50-335 P |
| | 8303310060* | 50-335 P |
| | 8303310107 | 50-389 A |
| | 8303310115 | 50-389 A |
| | 8303310403 | 50-389 A |
| | 8303310471* | 50-335 F |
| | 8303310474* | 50-335 F |
| Florida Power Corp | 8303010264 | 50-302 S |
| | 8303010269* | 50-302 S |
| | 8303010272 | 50-302 S |
| | 8303010279* | 50-302 S |
| | 8303040430 | 50-302 S |
| | 8303040431* | 50-302 S |
| | 8303040544 | 50-302 G |
| | 8303080029 | 50-302 R |
| | 8303080039* | 50-302 R |
| | 8303080045* | 50-302 R |
| | 8303080077 | 50-302 P |
| | 8303100200 | 50-302 S |
| | 8303100290 | 50-302 P |
| | 8303110163 | 50-302 F |
| | 8303110232 | 50-302 F |
| | 8303110234 | 50-302 G |
| | 8303150407 | 50-302 P |
| | 8303160318 | 50-302 R |
| | 8303160325* | 50-302 R |
| | 8303160471 | 50-302 S |
| | 8303160483* | 50-302 S |
| | 8303170319 | 50-302 G |
| | 8303170492 | 50-302 G |
| | 8303180185 | 50-302 S |
| | 8303180199* | 50-302 S |
| | 8303180253 | 50-302 S |
| | 8303180260* | 50-302 S |
| | 8303180328 | 50-302 G |
| | 8303210663 | 50-302 G |
| | 8303210731 | 50-302 G |
| | 8303220095 | 50-302 G |
| | 8303220158 | 50-302 P |
| | 8303220160* | 50-302 P |
| | 8303240098 | 50-302 G |
| | 8303250030 | 50-302 P |
| | 8303290477 | 50-302 G |
| | 8303290482 | 50-302 P |
| | 8303290839* | 50-302 F |
| | 8303290845* | 50-302 F |
| Florida, Univ. of, Gainesville | 8303090520 | NUREG |
| | 8303310238 | 50-83 V |
| | 8303310242* | 50-83 V |
| Francis & McGinnis Associates | 8303300645 | FOIA |
| Franklin Institute/Franklin Research Center | 8112240161* | 50-277 P |
| | 8203290497* | 50-282 P |
| | 8212020263* | 50-29 P |
| | 8301170075* | 50-346 P |
| | 8302020153* | 50-369 P |
| | 8302090302* | 50-271 P |
| | 8302090307* | 50-250 P |
| | 8303210149 | 50-522 O |
| Friends of the Earth | 8303030433 | 50-247 G |
| GA Technologies, Inc./General Atomic Co | 8303010066 | 70-734 |
| | 8303010067* | 70-734 |
| | 8303010636 | TOPREP |
| | 8303100571 | 71-6346 |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303140552 | XPORTLIC |
| | 8303140556* | XPORTLIC |
| | 8303230145 | XPORTLIC |
| | 8303290110 | XPORTLIC |
| GUARD | 8303230183 | 50-361 Q |
| Gage-Babcock Associates, Inc. | 8303150618* | CONTRACT |
| | 8303150663* | CONTRACT |
| | 8303230167* | CONTRACT |
| | 8303230175* | CONTRACT |
| | 8303230182* | CONTRACT |
| | 8303280339* | CONTRACT |
| | 8303290765* | CONTRACT |
| Galloway & Greenberg | 8303230203 | 50-537 H |
| General Electric Co | 8302040379 | 50-447 B |
| | 8302040383* | 50-447 B |
| | 8302040475* | 71-9001 |
| | 8303010071 | 71-4 |
| | 8303010075* | 71-4 |
| | 8303010304 | 70-1113 |
| | 8303010426 | TOPREP |
| | 8303010700 | 70-754 |
| | 8303020009 | TOPREP |
| | 8303020053 | TOPREP |
| | 8303020059* | TOPREP |
| | 8303020065* | TOPREP |
| | 8303020079* | 50-373 Q |
| | 8303020151 | 70-754 |
| | 8303030035 | 71-9044 |
| | 8303030216 | 71-9044 |
| | 8303030271* | 71-4909 |
| | 8303030349 | 70-2786 |
| | 8303030356 | XPORTLIC |
| | 8303040055 | XPORTLIC |
| | 8303040060* | XPORTLIC |
| | 8303040068* | XPORTLIC |
| | 8303040075 | XPORTLIC |
| | 8303040133 | XPORTLIC |
| | 8303040555* | 50-293 P |
| | 8303070062 | 50-447 A |
| | 8303070089* | 50-387 P |
| | 8303070127 | 50-447 A |
| | 8303090201 | PT21 |
| | 8303100568 | 70-1308 |
| | 8303110294 | 50-447 E |
| | 8303140179 | 50-447 A |
| | 8303150541 | 50-447 A |
| | 8303150585 | 50-528 S |
| | 8303150685 | XPORTLIC |
| | 8303150701 | XPORTLIC |
| | 8303160229 | TOPREP |
| | 8303160236* | TOPREP |
| | 8303160580 | TOPREP |
| | 8303170027 | 70-754 |
| | 8303170291 | 50-447 A |
| | 8303170374 | 50-18 R |
| | 8303170395* | 50-18 R |
| | 8303170399 | 50-183 R |
| | 8303170404* | 50-183 R |
| | 8303170457 | 50-70 R |
| | 8303170465* | 50-70 R |
| | 8303180017 | 50-447 A |
| | 8303210290 | 50-447 A |
| | 8303210452 | 70-1113 |
| | 8303220138 | 50-447 A |
| | 8303230003 | XPORTLIC |
| | 8303240256 | TOPREP |
| | 8303240349 | PT21 |
| | 8303290094 | XPORTLIC |
| | 8303290360 | 50-447 A |
| | 8303290853* | CONTRACT |
| | 8303310277 | 50-447 A |
| General Electric Uranium Management Corp | 8302040471 | 71-9001 |
| | 8303110147 | 71-9001 |
| | 8303180508 | 71-9001 |
| General Physics Corp | 8303230142 | NUREG |
| | 8303010348* | CONTRACT |
| General Public Utilities - GPU Service Corp | 8302150368 | 50-289 P |
| | 8302250327 | 50-219 S |
| | 8302250330* | 50-219 S |
| | 8302250332* | 50-219 S |
| | 8302250335* | 50-219 S |
| | 8303010069 | 71-5026 |
| | 8303020028 | 50-320 P |
| | 8303040402 | 50-320 P |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303040410* | 50-320 P |
| | 8303040417* | 50-320 P |
| | 8303040517 | 50-219 Q |
| | 8303040581 | 50-219 R |
| | 8303080341 | 50-219 R |
| | 8303080347* | 50-219 R |
| | 8303090085 | 50-289 R |
| | 8303090090* | 50-289 R |
| | 8303090189 | 50-289 P |
| | 8303090566* | 50-320 F |
| | 8303090572* | 50-320 F |
| | 8303100127 | 50-289 P |
| | 8303100337 | 50-289 P |
| | 8303100557* | 50-289 F |
| | 8303100560* | 50-289 F |
| | 8303110053 | 50-320 R |
| | 8303110076* | 50-320 R |
| | 8303110101 | 50-219 P |
| | 8303110249 | 50-289 P |
| | 8303110249 | 50-289 P |
| | 8303140047 | 50-320 Q |
| | 8303140197 | 50-289 R |
| | 8303140198* | 50-289 R |
| | 8303140203* | 50-289 R |
| | 8303140383 | 50-219 S |
| | 8303140384* | 50-219 S |
| | 8303140484 | 50-289 S |
| | 8303140496* | 50-289 S |
| | 8303150265 | 50-289 P |
| | 8303150272* | 50-289 P |
| | 8303150293* | 50-320 Q |
| | 8303150316 | 50-289 P |
| | 8303150327* | 50-289 P |
| | 8303150380* | 50-219 Q |
| | 8303150418 | 50-289 J |
| | 8303150418 | 50-289 J |
| | 8303150428 | 50-219 R |
| | 8303150431* | 50-219 R |
| | 8303160197 | 50-219 S |
| | 8303160209* | 50-219 S |
| | 8303160214 | 50-219 S |
| | 8303160222* | 50-219 S |
| | 8303160225 | 50-219 S |
| | 8303160232* | 50-219 S |
| | 8303160260 | 50-289 Q |
| | 8303160303 | 50-219 R |
| | 8303160309* | 50-219 R |
| | 8303160530 | 50-289 P |
| | 8303160537* | 50-289 P |
| | 8303160541* | 50-289 P |
| | 8303170285 | 50-219 P |
| | 8303170294 | 50-219 P |
| | 8303180302 | 50-320 P |
| | 8303180360 | 50-289 J |
| | 8303180360 | 50-289 J |
| | 8303180392 | 50-320 P |
| | 8303180397* | 50-320 P |
| | 8303180422 | 50-289 S |
| | 8303180424 | 50-320 R |
| | 8303180426* | 50-289 S |
| | 8303180427* | 50-320 R |
| | 8303220030 | 50-289 R |
| | 8303220033* | 50-289 R |
| | 8303220089 | 50-289 J |
| | 8303220313 | 50-219 P |
| | 8303220314 | 50-289 P |
| | 8303240403 | 50-219 R |
| | 8303240453* | 50-321 S |
| | 8303250067 | 50-320 S |
| | 8303250076* | 50-320 S |
| | 8303250090 | 50-219 S |
| | 8303250094* | 50-219 S |
| | 8303250098 | 50-219 P |
| | 8303250104* | 50-219 P |
| | 8303250108* | 50-219 P |
| | 8303250155 | 50-289 Q |
| | 8303250169 | 50-289 P |
| | 8303280101 | 50-289 P |
| | 8303280133 | 50-219 D |
| | 8303290242 | 50-289 Q |
| | 8303290363 | 50-219 P |
| | 8303290624* | 50-320 F |
| | 8303290628* | 50-320 F |
| | 8303300451* | 50-289 F |
| | 8303300784* | 50-289 F |
| Georgia Institute of Technology<br>Georgia Power Co | 8303310163* | 50-289 F |
| | 8303150356* | GA999 |
| | 8302150605 | 50-366 S |
| | 8302150615* | 50-366 S |
| | 8303010520* | 50-321 Q |
| | 8303010551 | 50-321 V |
| | 8303010551 | 50-321 V |
| | 8303020010 | 50-321 P |
| | 8303020010 | 50-321 P |
| | 8303030213 | 50-321 R |
| | 8303030213 | 50-321 R |
| | 8303030220* | 50-321 R |
| | 8303030220* | 50-321 R |
| | 8303030228* | 50-321 R |
| | 8303030228* | 50-321 R |
| | 8303040463 | 50-321 P |
| | 8303070001 | 50-366 P |
| | 8303080043 | 50-321 S |
| | 8303080048* | 50-321 S |
| | 8303080206 | 50-321 S |
| | 8303080214* | 50-321 S |
| | 8303080404 | 50-321 S |
| | 8303090188 | 50-321 R |
| | 8303090290 | 50-321 P |
| | 8303090360 | 50-321 R |
| | 8303090360 | 50-321 R |
| | 8303090363* | 50-321 R |
| | 8303090363* | 50-321 R |
| | 8303090368* | 50-321 R |
| | 8303090368* | 50-321 R |
| | 8303090537* | 50-321 F |
| | 8303090544* | 50-321 F |
| | 8303100130* | 50-321 F |
| | 8303100132* | 50-321 F |
| | 8303140453 | 50-321 S |
| | 8303140478 | 50-321 S |
| | 8303140544 | 50-424 A |
| | 8303140544 | 50-424 A |
| | 8303140570 | 50-321 S |
| | 8303140580* | 50-321 S |
| | 8303140584 | 50-321 S |
| | 8303140588* | 50-321 S |
| | 8303150204 | 50-321 S |
| | 8303150214* | 50-321 S |
| | 8303150452 | 50-321 S |
| | 8303150456* | 50-321 S |
| | 8303150478 | 50-321 R |
| | 8303150478 | 50-321 R |
| | 8303150480* | 50-321 R |
| | 8303150480* | 50-321 R |
| | 8303150492 | 50-366 S |
| | 8303150495* | 50-366 S |
| | 8303150545 | 50-321 S |
| | 8303150563* | 50-321 S |
| | 8303160443 | 50-321 S |
| | 8303160445* | 50-321 S |
| | 8303160583 | 50-321 R |
| | 8303160583 | 50-321 R |
| | 8303160588* | 50-321 R |
| | 8303160588* | 50-321 R |
| | 8303170300 | 50-321 P |
| | 8303180363 | 50-366 S |
| | 8303180370* | 50-366 S |
| | 8303210316 | 50-366 S |
| | 8303210320* | 50-366 S |
| | 8303210348 | 50-424 Q |
| | 8303210348 | 50-424 Q |
| | 8303210350 | 50-321 S |
| | 8303210354* | 50-321 S |
| | 8303210361 | 50-321 Q |
| | 8303210361 | 50-321 Q |
| | 8303210387 | 50-321 Q |
| | 8303210387 | 50-321 Q |
| | 8303210388 | 50-321 S |
| | 8303210393* | 50-321 S |
| | 8303210406 | 50-366 S |
| | 8303210408 | 50-424 S |
| | 8303210408 | 50-424 S |
| | 8303210412 | 50-366 S |
| | 8303210413* | 50-366 S |
| | 8303210419* | 50-366 S |
| | 8303210427 | 50-321 P |
| | 8303210427 | 50-321 P |
| | 8303210463 | 50-321 S |
| | 8303210464* | 50-321 Q |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303210467* | 50-321 S |
| | 8303210476 | 50-321 S |
| | 8303210485* | 50-321 S |
| | 8303210499 | 50-424 S |
| | 8303210517 | 50-366 S |
| | 8303210527* | 50-366 S |
| | 8303210558 | 50-321 S |
| | 8303210563* | 50-321 S |
| | 8303210639* | 50-321 Q |
| | 8303210647 | 50-424 S |
| | 8303210647 | 50-424 S |
| | 8303210660* | 50-424 Q |
| | 8303210694 | 50-366 S |
| | 8303220046 | 50-321 S |
| | 8303220054* | 50-321 S |
| | 8303240114* | 50-321 F |
| | 8303240114* | 50-321 F |
| | 8303240119* | 50-321 F |
| | 8303240448 | 50-321 S |
| | 8303250043* | 50-321 F |
| | 8303250043* | 50-321 F |
| | 8303250048* | 50-321 F |
| | 8303250048* | 50-321 F |
| | 8303290322 | 50-366 P |
| | 8303290330* | 50-366 P |
| | 8303310118* | 50-321 F |
| | 8303310121* | 50-321 F |
| | 8303310174* | 50-321 F |
| | 8303310174* | 50-321 F |
| | 8303310180* | 50-321 F |
| | 8303310180* | 50-321 F |
| Geotechnical Engineers, Inc | 8303280354* | CONTRACT |
| Geotrans, Inc | 8303030775* | CONTRACT |
| Germany, Federal Republic of | 8303290750 | PROJ |
| | 8303290751* | PROJ |
| Gesellschaft fur Nukleur-Service mbH | 8303020202* | FOIA |
| Gibbs & Hill, Inc (subs of Dravo Corp ) | 8303210405* | GA999 |
| Gilbert/Commonwealth Cos | 8303070140* | GA999 |
| | 8303070147* | GA999 |
| | 8303100092* | 50-440 A |
| Golder Associates | 8303160619* | 40-1341 |
| | 8303160623* | 40-1341 |
| | 8303250113 | NUREG |
| | 8303280083 | WASTE MGT |
| | 8303280097 | NUREG |
| | 8303280114 | NUREG |
| | 8303290574* | CONTRACT |
| | 8303290575* | WASTE MGT |
| | 8303290584* | CONTRACT |
| | 8303300446 | NUREG |
| Gould, Inc | 8303300227* | 50-322 A |
| | 8303300240* | 50-322 A |
| | 8303300246* | 50-322 A |
| | 8303300251* | 50-322 A |
| | 8303300255* | 50-322 A |
| | 8303300258* | 50-322 A |
| | 8303300260* | 50-322 A |
| | 8303300265* | 50-322 A |
| Government Accountability Project | 8303090364 | FOIA |
| | 8303090437 | 50-373 P |
| | 8303100003 | FOIA |
| | 8303210274* | 50-329 A |
| | 8303240098 | 50-528 Q |
| | 8303290391 | 50-320 G |
| | 8303290396* | 50-320 G |
| Greater New York Council on Energy | 8303030433 | 50-247 G |
| | 8303180227* | 50-247 G |
| Guild, R | 8303230192 | 50-413 G |
| | 8303310345 | 50-413 G |
| Gulf Nuclear, Inc | 8303040074 | 71-9160 |
| | 8303040074 | 71-9160 |
| | 8303040074 | 71-9160 |
| | 8303040074 | 71-9160 |
| | 8303040080* | 71-9160 |
| | 8303040088* | 71-9160 |
| | 8303040099* | 71-9160 |
| | 8303040106* | 71-9160 |
| Gulf States Utilities Co | 8303030411 | 50-458 C |
| | 8303030411 | 50-458 C |
| | 8303030430* | 50-458 C |
| | 8303030430* | 50-458 C |
| | 8303030434* | 50-458 K |
| | 8303030434* | 50-458 K |
| | 8303080009 | 50-458 S |
| | 8303080362 | 50-458 S |
| | 8303080405 | 50-458 S |
| | 8303080420 | 50-458 S |
| | 8303090342 | 50-458 V |
| | 8303100155 | 50-458 F |
| | 8303100155 | 50-458 F |
| | 8303110219 | 50-458 S |
| | 8303110255 | 50-458 S |
| | 8303110387 | 50-458 S |
| | 8303140066 | 50-458 F |
| | 8303140066 | 50-458 F |
| | 8303150264 | 50-458 S |
| | 8303150282 | 50-458 S |
| | 8303150605 | 50-458 S |
| | 8303180018 | 50-458 S |
| | 8303210466 | 50-458 S |
| | 8303240468 | 50-458 S |
| | 8303240476 | 50-458 S |
| | 8303250050 | 50-458 S |
| | 8303250110 | 50-458 S |
| | 8303280141 | 50-458 S |
| | 8303280229 | 50-458 S |
| | 8303280230 | 50-458 Q |
| | 8303280256 | 50-458 S |
| | 8303280264 | 50-458 Q |
| H&H X-Ray Services, Inc | 8303230484 | 71-423 |
| HHS, Dept of, US Public Health Service | 8303290138* | CONTRACT |
| Hampton Falls, NH | 8303140566* | 50-443 Q |
| Harmon & Weiss | 8303070147* | 50-289 Q |
| | 8303090082 | FOIA |
| | 8303090219 | FOIA |
| | 8303170421 | 70-143 |
| | 8303170447 | 50-289 Q |
| | 8303220221* | 50-537 Q |
| | 8303220234 | 50-443 Q |
| | 8303220234 | 50-443 Q |
| | 8303220245 | 50-443 Q |
| | 8303220245 | 50-443 Q |
| | 8303250165 | 50-537 Q |
| | 8303290536 | 50-443 Q |
| Harvard Medical School | 8303230195* | CONTRACT |
| Heidelberg Institute for Energy & Environmental Research | 8303140606* | MISC |
| Henry Pratt Co | 8303110292* | 50-250 P |
| | 8303110303* | 50-250 P |
| Hittman Nuclear & Development Corp (subs Hittman Corp ) | 8302030609 | 71-5026 |
| | 8303030316 | 71-9080 |
| | 8303030326 | 71-9089 |
| | 8303100508 | 71-9151 |
| | 8303140202* | 50-289 R |
| Hoke, Inc | 8303150689 | XPORTLIC |
| Holy Family Hosp, Manitowoc, WI | 8303240136* | FOIA |
| Hourihan, P | 8303240398 | 50-528 Q |
| House of Rep | 8303040310* | COMMISSION |
| | 8303170018* | 50-206 U |
| | 8303240077* | 50-322 H |
| | 8303290241* | 50-206 U |
| House of Rep , Energy & Commerce | 8303100563* | COMMISSION |
| | 8303160721* | COMMISSION |
| House of Rep , Interior & Insular Affairs | 8303030355* | 50-275 U |
| | 8303030395* | 50-275 P |
| | 8303040172* | 50-320 U |
| | 8303140644* | COMMISSION |
| | 8303290116* | 50-247 U |
| Houston Lighting & Power Co | 8303040614 | 50-498 V |
| | 8303150560 | 50-498 S |
| | 8303160382 | 50-498 K |
| | 8303160382 | 50-498 K |
| | 8303160385* | 50-498 K |
| | 8303160385* | 50-498 K |
| | 8303170283 | 50-498 S |
| | 8303180242 | 50-498 S |
| | 8303250084 | 50-498 A |
| | 8303250089 | 50-498 A |
| Houston, Univ of | 8303110628* | CONTRACT |
| Hunton & Williams | 8302100345 | PRM |
| | 8303010354 | 50-322 Q |
| | 8303040457 | 50-322 Q |
| | 8303040479 | 50-338 Q |
| | 8303040479 | 50-338 Q |
| | 8303040483 | 50-338 Q |
| | 8303040483 | 50-338 Q |
| | 8303040522 | 50-322 Q |
| | 8303080142 | 50-322 Q |
| | 8303230209 | 50-322 Q |

# CORPORATE SOURCE INDEX

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303240039* | 50-322 G |
| | 8303300138 | 50-280 P |
| | 8303300352 | 50-322 G |
| | 8303300423 | 50-322 G |
| | 8303300551* | 50-322 G |
| | 8303300562* | 50-322 G |
| Hydrogen Control Owners Group. BWR-6 Mark III | 8303290369 | 50-416 P |
| IRT Corp. | 8303100460 | NUREG |
| | 8303100558 | NUREG |
| ITT General Controls (subs of ITT) | 8303230141 | XPORTLIC |
| Illinois Power Co. | 8302080314 | 50-461 S |
| | 8303040347 | 50-461 K |
| | 8303040351* | 50-461 K |
| | 8303080263* | 50-461 G |
| | 8303090077 | 50-461 E |
| | 8303090125 | 50-461 G |
| | 8303090206 | 50-461 G |
| | 8303090301 | 50-461 E |
| | 8303090308* | 50-461 E |
| | 8303090315* | 50-461 E |
| | 8303140186* | 50-461 G |
| | 8303150402 | 50-461 G |
| | 8303170162 | 50-461 E |
| | 8303170270 | 50-461 J |
| | 8303170398 | 50-461 G |
| | 8303170548 | 50-461 A |
| | 8303170550* | 50-461 A |
| | 8303210048 | 50-461 A |
| | 8303220031 | 50-461 E |
| | 8303220088 | 50-461 E |
| | 8303230268 | 50-461 I |
| | 8303230268 | 50-461 I |
| | 8303230280* | 50-461 I |
| | 8303240215 | 50-461 A |
| | 8303240222 | 50-461 G |
| | 8303240327 | 50-461 E |
| | 8303280092 | 50-461 E |
| | 8303280139 | 50-461 E |
| | 8303290006 | 50-461 E |
| | 8303290371 | 50-461 A |
| | 8303290504 | 50-461 A |
| Illinois, State of | 8303010618* | 50-10 F |
| | 8303080186 | 50-454 T |
| | 8303080186 | 50-454 T |
| | 8303080204 | 50-454 T |
| | 8303080204 | 50-454 T |
| | 8303080250 | 50-454 T |
| | 8303310230* | 50-237 G |
| Illinois, Univ. of, Urbana-Champaign | 8303030212 | 50-151 R |
| | 8303030214* | 50-151 R |
| Indiana & Michigan Electric Co. | 8303020013 | 50-315 P |
| | 8303020013 | 50-315 P |
| | 8303020020* | 50-315 P |
| | 8303020020* | 50-315 P |
| | 8303080079 | 50-315 S |
| | 8303080087* | 50-315 S |
| | 8303080105 | 50-315 S |
| | 8303080111 | 50-315 P |
| | 8303080111 | 50-315 P |
| | 8303080113* | 50-315 S |
| | 8303080119* | 50-315 P |
| | 8303080141 | 50-315 P |
| | 8303080141 | 50-315 P |
| | 8303080145* | 50-315 P |
| | 8303080145* | 50-315 P |
| | 8303080150* | 50-315 P |
| | 8303080150* | 50-315 P |
| | 8303080268 | 50-316 R |
| | 8303080276* | 50-316 R |
| | 8303080331 | 50-315 S |
| | 8303080344* | 50-315 S |
| | 8303080348 | 50-315 P |
| | 8303080348 | 50-315 P |
| | 8303080375 | 50-315 S |
| | 8303080384* | 50-315 S |
| | 8303080398* | 50-315 S |
| | 8303080410* | 50-315 S |
| | 8303080423 | 50-315 R |
| | 8303080429* | 50-315 R |
| | 8303080436 | 50-316 S |
| | 8303080507 | 50-316 S |
| | 8303080514* | 50-316 S |
| | 8303080519* | 50-316 S |
| | 8303140344 | 50-316 P |
| | 8303140373 | 50-315 S |
| | 8303140377* | 50-315 S |
| | 8303140399 | 50-315 R |
| | 8303140399 | 50-315 R |
| | 8303140401* | 50-315 R |
| | 8303140401* | 50-315 R |
| | 8303140452 | 50-315 Q |
| | 8303140518 | 50-316 S |
| | 8303140525* | 50-316 S |
| | 8303140603 | 50-315 S |
| | 8303140610* | 50-315 S |
| | 8303150218 | 50-315 Q |
| | 8303150218 | 50-315 Q |
| | 8303150510 | 50-315 R |
| | 8303150531* | 50-315 R |
| | 8303150537 | 50-316 R |
| | 8303150544* | 50-316 R |
| | 8303170108 | 50-315 F |
| | 8303210416 | 50-316 S |
| | 8303210424* | 50-316 S |
| | 8303220102 | 50-315 S |
| | 8303240190* | 50-315 Q |
| | 8303240401 | 50-316 S |
| | 8303240402* | 50-316 S |
| | 8303250053* | 50-315 F |
| | 8303250056* | 50-315 F |
| | 8303250056* | 50-315 F |
| | 8303280030 | 50-315 P |
| | 8303290386 | 50-315 S |
| | 8303290386 | 50-315 S |
| Indiana Univ. | 8303310112* | CONTRACT |
| Indonesia | 8303170675 | XPORTLIC |
| Information Systems & Network Corp. | 8303150171* | CONTRACT |
| Institute of Nuclear Power Operations | 8303020114* | 50-293 R |
| | 8303280331 | 50-272 P |
| | 8303280331 | 50-272 P |
| Interactive Radiation, Inc. | 8303170154 | XPORTLIC |
| | 8303170157* | XPORTLIC |
| Interior, Dept. of | 8303140425 | 50-413 D |
| | 8303170208* | ORG |
| Interior, Dept. of, Bureau of Mines | 8303300170 | WASTE MGT |
| Interior, Dept. of, Fish & Wildlife Service | 8303160550 | 50-245 P |
| Interior, Dept. of, Geological Survey | 8303290103* | CONTRACT |
| International Brotherhood of Electrical Workers | 8303010076 | 50-440 Q |
| Iowa Electric Light & Power Co. | 8303010260 | 50-331 V |
| | 8303010339 | 50-331 P |
| | 8303010490 | 50-331 R |
| | 8303010493* | 50-331 R |
| | 8303030570 | 50-331 S |
| | 8303030620 | 50-331 S |
| | 8303030627* | 50-331 S |
| | 8303030664 | 50-331 S |
| | 8303030665* | 50-331 S |
| | 8303080332 | 50-331 P |
| | 8303080338* | 50-331 P |
| | 8303140407 | 50-331 S |
| | 8303140408* | 50-331 S |
| | 8303140413 | 50-331 S |
| | 8303140416* | 50-331 S |
| | 8303140421 | 50-331 S |
| | 8303140428* | 50-331 S |
| | 8303140435 | 50-331 S |
| | 8303140449* | 50-331 S |
| | 8303150215 | 50-331 R |
| | 8303150221* | 50-331 R |
| | 8303150612* | 50-331 Q |
| | 8303170361 | 50-331 S |
| | 8303170372* | 50-331 S |
| | 8303170453 | 50-331 P |
| | 8303170460* | 50-331 P |
| | 8303210258 | 50-331 P |
| | 8303210263* | 50-331 P |
| | 8303210432 | 50-331 P |
| | 8303210438* | 50-331 P |
| | 8303220061 | 50-331 R |
| | 8303220062* | 50-331 R |
| | 8303220207 | 50-331 P |
| | 8303240170 | 50-331 F |
| | 8303250015 | 50-331 P |
| | 8303290327 | 50-331 R |
| | 8303290327 | 50-331 R |
| | 8303290333* | 50-331 R |
| | 8303290488 | 50-331 Q |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303300029* | 50-331 F |
| | 8303300033* | 50-331 F |
| | 8303300189 | 50-331 P |
| Irving, S.M. | 8303300329 | 50-458 G |
| Isham, Lincoln & Beale | 8303010068 | 50-454 G |
| | 8303010068 | 50-454 G |
| | 8303010171 | 50-329 G |
| | 8303010179 | 50-329 G |
| | 8303010306 | 50-454 T |
| | 8303010306 | 50-454 T |
| | 8303020041 | 50-155 G |
| | 8303030357 | 50-454 T |
| | 8303030357 | 50-454 T |
| | 8303030381 | 50-454 G |
| | 8303030381 | 50-454 G |
| | 8303030403 | 50-329 T |
| | 8303040445 | 50-155 G |
| | 8303140275 | 50-454 G |
| | 8303170509 | 50-155 G |
| | 8303180398 | 50-329 G |
| | 8303180398 | 50-329 G |
| | 8303220172 | 50-329 G |
| | 8303220172 | 50-329 G |
| | 8303240386 | 50-454 G |
| | 8303240522 | 50-329 G |
| | 8303240550 | 50-454 G |
| | 8303280270 | 50-237 P |
| | 8303290530 | 50-155 G |
| | 8303300453 | 50-454 T |
| Isotope Products Laboratories | 8303300051 | XPORTLIC |
| Jacobs Engineering Group, Inc. | 8303180558 | WASTE MGT |
| Japan, Govt of. | 8303020312 | XPORTLIC |
| | 8303040198* | COMMISSION |
| | 8303180111* | WASTE MGT |
| | 8303180115* | WASTE MGT |
| | 8303180120* | WASTE MGT |
| | 8303180123* | WASTE MGT |
| | 8303180126* | WASTE MGT |
| | 8303280106 | XPORTLIC |
| | 8303280109 | XPORTLIC |
| | 8303290150 | XPORTLIC |
| | 8303290168 | XPORTLIC |
| John Milner Associates | 8303010439* | 50-352 A |
| Joint Applicants-Palo Verde | 8303100268 | 50-528 G |
| | 8303140472* | 50-528 G |
| | 8303220257 | 50-528 G |
| Joint Applicants-South Texas Project | 8303150394 | 50-498 G |
| | 8303310335 | 50-498 G |
| Joint Intervenors-Callaway | 8303070118 | 50-483 G |
| Joint Intervenors-Diablo Canyon | 8303080061 | 50-275 G |
| Joseph Oat Corp. | 8303290001 | 70-2926 |
| Kansas Gas & Electric Co. | 8303080257 | 50-482 A |
| | 8303080498 | 50-482 S |
| | 8303150334 | 50-482 S |
| | 8303150344 | 50-482 S |
| | 8303150469 | 50-482 A |
| | 8303180249 | 50-482 S |
| | 8303180306 | 50-482 S |
| | 8303250024 | 50-482 S |
| | 8303280164 | 50-482 S |
| | 8303280175 | 50-482 S |
| | 8303280201 | 50-482 S |
| | 8303280226 | 50-482 S |
| | 8303280269 | 50-482 S |
| Kentucky, Commonwealth of. | 8303020072* | CONTRACT |
| Kerr Inspection & Testing Service, Inc. | 8303040227 | 71-6717 |
| Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.) | 8303220442* | 40-2061 |
| Kerr-McGee Corp. | 8303020087 | REGGD |
| | 8303090075 | 40-8768 |
| | 8303090081* | 40-8768 |
| | 8303110041 | 40-8768 |
| | 8303110044* | 40-8768 |
| | 8303110444 | 40-2061 |
| | 8303180669* | 40-8027 |
| | 8303210082 | 40-8027 |
| | 8303220375 | 40-2061 |
| | 8303220377* | 40-2061 |
| | 8303220384 | 40-2061 |
| | 8303220452 | 40-8027 |
| Keyboard Communications, Inc. | 8303180062* | CONTRACT |
| Kirkpatrick, Lockhart, Hill, Christopher & Phillips | 8303080054 | 50-322 G |
| | 8303100286 | 50-322 G |
| | 8303290190 | 50-322 G |
| | 8303300023* | 50-322 G |
| | 8303300346 | 50-322 G |
| | 8303310224 | 50-322 G |
| | 8303310269 | 50-322 G |
| | 8303310278* | 50-322 G |
| Kokomo Tube Co. | 8303090675 | 71-9033 |
| Kronish, Lieb, Shainswit, Weiner & Hillman | 8303100238 | 50-247 G |
| Labat-Anderson, Inc. | 8303150360* | CONTRACT |
| Labor, Dept of | 8303290228* | CONTRACT |
| Laboratory of Clinical Medicine Sioux Falls,SD | 8303240181* | FOIA |
| Lawrence Livermore Laboratory | 8211050147* | 50-346 P |
| | 8303290626 | WASTE MGT |
| LeBoeuf, Lamb, Leiby & MacRae | 8302100345 | PRM |
| | 8303090181 | 50-285 P |
| | 8303170382 | 50-341 G |
| League of Women Voters of Rockford, IL | 8303070034 | 50-454 T |
| | 8303070049* | 50-454 T |
| | 8303070054* | 50-454 T |
| | 8303070155 | 50-454 G |
| | 8303090142 | 50-454 T |
| | 8303220198* | 50-454 T |
| | 8303300409 | 50-454 T |
| | 8303300409 | 50-454 T |
| | 8303300431* | 50-454 T |
| | 8303300431* | 50-454 T |
| Lewis, M. | 8303020075 | PRM |
| Limerick Ecology Action | 8302030448* | 50-352 G |
| | 8303180252 | 50-352 G |
| Literature Research Corp. | 8303010018* | CONTRACT |
| Logical Technical Service Corp. | 8303300677* | CONTRACT |
| Long Island Lighting Co. | 8302010100 | 50-322 A |
| | 8302010106* | 50-322 A |
| | 8302100345 | PRM |
| | 8303010354 | 50-322 G |
| | 8303010458 | 50-322 A |
| | 8303030160 | 50-322 A |
| | 8303040457 | 50-322 G |
| | 8303040522 | 50-322 G |
| | 8303080142 | 50-322 G |
| | 8303080355 | 50-322 S |
| | 8303090221 | 50-322 A |
| | 8303100245 | 50-322 F |
| | 8303100265* | 50-322 G |
| | 8303140218* | 50-322 G |
| | 8303140219* | 50-322 G |
| | 8303140255 | 50-322 S |
| | 8303180176 | 50-322 G |
| | 8303210153 | 50-322 A |
| | 8303210161 | 50-322 G |
| | 8303210167 | 50-322 V |
| | 8303210173 | 50-322 A |
| | 8303230065 | 50-322 A |
| | 8303230119* | 50-322 A |
| | 8303230209 | 50-322 G |
| | 8303240017* | 50-322 G |
| | 8303240039* | 50-322 G |
| | 8303280005 | 50-322 F |
| | 8303300023* | 50-322 G |
| | 8303300218 | 50-322 A |
| | 8303300238 | 50-322 A |
| | 8303300352 | 50-322 G |
| | 8303300423 | 50-322 G |
| | 8303300551* | 50-322 G |
| | 8303300562* | 50-322 G |
| Los Alamos Scientific Laboratory | 8303110118 | RES |
| | 8303160175 | RES |
| | 8303230362 | NUREG |
| | 8303230517 | NUREG |
| | 8303300518 | NUREG |
| Louisiana Consumer's League, Inc. | 8303040312 | 50-458 G |
| Louisiana Power & Light Co. | 8303010499 | 50-382 A |
| | 8303010600 | 50-382 A |
| | 8303010669 | 70-2946 |
| | 8303010703 | 70-2946 |
| | 8303020122 | 70-2946 |
| | 8303030013 | 70-2946 |
| | 8303030678 | 50-382 A |
| | 8303080014 | 50-382 A |
| | 8303080083 | 50-382 A |
| | 8303080195 | 50-382 S |
| | 8303080298 | 50-382 S |
| | 8303080455 | 50-382 S |
| | 8303080461 | 50-382 S |

# CORPORATE SOURCE INDEX

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303080467 | 50-382 A |
| | 8303080486 | 50-382 Q |
| | 8303090302 | 50-382 F |
| | 8303100274 | 50-382 A |
| | 8303100285 | 50-382 A |
| | 8303160285 | 50-382 R |
| | 8303160506 | 50-382 A |
| | 8303160521 | 50-382 F |
| | 8303170360 | 50-382 A |
| | 8303170423 | 50-382 Q |
| | 8303170427* | 50-382 Q |
| | 8303180247 | 50-382 F |
| | 8303210351 | 50-382 E |
| | 8303210407 | 50-382 E |
| | 8303210556 | 50-382 S |
| | 8303210569 | 50-382 S |
| | 8303210610* | 50-382 Q |
| | 8303220004 | 50-382 F |
| | 8303220238 | 50-382 Q |
| | 8303220280 | 50-382 T |
| | 8303220459 | 70-2946 |
| | 8303220470* | 70-2946 |
| | 8303240188 | 50-382 A |
| | 8303240196* | 50-382 A |
| | 8303240514 | 50-382 F |
| | 8303250141 | 50-382 Q |
| | 8303280086 | 50-382 E |
| | 8303280121 | 50-382 S |
| | 8303280124 | 50-382 S |
| | 8303280179 | 50-382 S |
| | 8303280186 | 50-382 S |
| | 8303290407 | 50-382 E |
| | 8303290464 | 50-382 Q |
| | 8303310045* | 50-382 A |
| Louisiana, State of | 8303170483 | 50-382 Q |
| | 8303220301 | 50-458 Q |
| | 8303310576* | CONTRACT |
| Lowenstein, Newman, Reis, Axelrad & Toll | 8303020164 | FOIA |
| | 8303150394 | 50-498 Q |
| | 8303170283 | 50-498 Q |
| | 8303230031 | 50-331 J |
| | 8303310335 | 50-498 Q |
| Luther Hosp Eau Claire,WI | 8204220451* | FOIA |
| M.D. Anderson Hosp., Houston, TX | 8303010730* | CONTRACT |
| MacLaren Engineers, Inc. | 8303160619* | 40-1341 |
| | 8303160623* | 40-1341 |
| Madison Gas & Electric Co. | 8303030088* | 50-305 R |
| | 8303110377* | 50-305 P |
| Maine Yankee Atomic Power Co. | 8303010472 | 50-309 S |
| | 8303010484* | 50-309 S |
| | 8303010492 | 50-309 S |
| | 8303010502* | 50-309 S |
| | 8303010504 | 50-309 S |
| | 8303010515* | 50-309 S |
| | 8303010555 | 50-309 S |
| | 8303030670 | 50-309 P |
| | 8303040429 | 50-309 V |
| | 8303080012 | 50-309 R |
| | 8303080013* | 50-309 R |
| | 8303080168 | 50-309 S |
| | 8303080503 | 50-309 P |
| | 8303140239 | 50-309 R |
| | 8303140247* | 50-309 R |
| | 8303140359 | 50-309 J |
| | 8303140423 | 50-309 S |
| | 8303140466* | 50-309 S |
| | 8303140495 | 50-309 S |
| | 8303140506* | 50-309 S |
| | 8303140522 | 50-309 S |
| | 8303140536* | 50-309 S |
| | 8303150424 | 50-309 R |
| | 8303150425* | 50-309 R |
| | 8303150557* | 50-309 Q |
| | 8303160335 | 50-309 S |
| | 8303160356* | 50-309 S |
| | 8303170140 | 50-309 P |
| | 8303170220 | 50-309 Q |
| | 8303220100 | 50-309 P |
| | 8303220289 | 50-309 P |
| | 8303240328 | 50-309 Q |
| | 8303280239 | 50-309 S |
| | 8303280251* | 50-309 S |
| | 8303290237 | 50-309 S |
| | 8303290461* | 50-309 Q |
| | 8303300235 | 50-309 P |
| | 8303300243* | 50-309 P |
| | 8303310483* | 50-309 F |
| | 8303310487* | 50-309 F |
| Maine, State of | 8303030782* | CONTRACT |
| Management Analysis Co. | 8303300665* | 50-329 A |
| Mapleton Intervenors | 8303180410 | 50-329 Q |
| | 8303290447 | PRM |
| Marine Research, Inc. | 8303140233* | 50-293 Q |
| Marsh & McLennan, Inc. | 8303010232 | 50-348 J |
| | 8303010239 | 50-438 J |
| | 8303010243 | 50-390 J |
| | 8303010250 | 50-321 J |
| | 8303010250 | 50-321 J |
| | 8303080198 | 50-293 J |
| | 8303080297 | 50-286 J |
| | 8303110207 | 50-280 J |
| | 8303110207 | 50-280 J |
| | 8303110207 | 50-280 J |
| | 8303110226 | 50-315 J |
| | 8303110269 | 50-358 J |
| | 8303140231 | 50-245 J |
| | 8303140231 | 50-245 J |
| | 8303140244 | 50-245 J |
| | 8303140244 | 50-245 J |
| | 8303140256 | 50-244 J |
| | 8303140289 | 50-293 J |
| | 8303140290 | 50-29 J |
| | 8303140306 | 50-483 J |
| | 8303240019 | TOPREP |
| | 8303240023 | TOPREP |
| | 8303240201 | MISC |
| | 8303240206 | TOPREP |
| | 8303290055 | 50-302 J |
| | 8303290086 | 50-438 J |
| | 8303290310 | 50-335 J |
| | 8303290310 | 50-335 J |
| | 8303290339 | 50-250 J |
| | 8303290341 | 50-259 J |
| | 8303290409 | 50-321 J |
| | 8303290409 | 50-321 J |
| | 8303290415 | 50-390 J |
| | 8303290423 | 50-327 J |
| | 8303290431 | 50-348 J |
| Marshall,W.H. | 8303290447 | PRM |
| Marubeni America Corp. (subs. of Marubeni Corp.) | 8303180155 | XPORTLIC |
| | 8303180161* | XPORTLIC |
| | 8303230069 | XPORTLIC |
| Maryland, State of | 8303040147* | 50-170 U |
| Massachusetts Institute of Technology | 8303010003* | 50-206 P |
| | 8303100490* | 50-20 P |
| | 8303280003 | 50-20 P |
| | 8303290689 | NUREG |
| | 8303300421 | RES |
| Massachusetts, Commonwealth of, | 8303240430 | 50-443 Q |
| | 8303240445* | 50-443 Q |
| McDonald Engineering Analysis Co., Inc. | 8303150202* | 50-443 A |
| McGraw-Hill Publications Co. | 8301030513* | CONTRACT |
| Memphis State Univ. | 8303160439 | 50-538 R |
| | 8303160441* | 50-538 R |
| | 8303290185* | CONTRACT |
| | 8303310143* | CONTRACT |
| Mercy Medical Center of Oshkosh, Inc Oshkosh,WI | 8201040114* | FOIA |
| Metropolitan Edison Co. | 8303070083 | 50-289 Q |
| | 8303070093 | 50-289 Q |
| | 8303080459 | 50-289 Q |
| | 8303170431 | 50-289 Q |
| | 8303150267 | 50-294 R |
| Michigan State Univ. | 8303310136* | CONTRACT |
| Michigan, State of | 8303300585* | CONTRACT |
| Michigan, State of, Dept. of Public Health | 8303020266 | NUREG |
| Michigan, Univ. of | 8303030435 | 50-2 F |
| | 8303100443 | NUREG |
| | 8303210144 | ACRS |
| | 8303220407 | NUREG |
| Michigan, Univ. of, Medical School | 8303100453 | NUREG |
| Microtech Industries, Inc. | 8303300458* | CONTRACT |
| Midland County, MI | 8303290497 | 50-329 Q |
| Milco International, Inc. | 8303310588 | XPORTLIC |
| | 8303310592* | XPORTLIC |
| Miller,D.S. | 8303220214 | 50-309 Q |
| | 8303220218 | 50-309 Q |
| Minnesota, State of | 8303300698* | CONTRACT |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| Mississippi Power & Light Co. | 8303310200* | CONTRACT |
| | 8302100345 | PRM |
| | 8303010016 | 71-5939 |
| | 8303010178 | 50-416 S |
| | 8303010185* | 50-416 S |
| | 8303010193 | 50-416 S |
| | 8303010201* | 50-416 S |
| | 8303010212 | 50-416 S |
| | 8303010218* | 50-416 S |
| | 8303010226 | 50-416 S |
| | 8303010233* | 50-416 S |
| | 8303010307 | 50-416 F |
| | 8303010307 | 50-416 F |
| | 8303010343 | 50-416 S |
| | 8303010349* | 50-416 S |
| | 8303010473* | 50-416 Q |
| | 8303010481* | 50-416 Q |
| | 8303010491* | 50-416 Q |
| | 8303010524* | 50-416 Q |
| | 8303010547 | 50-416 Q |
| | 8303010548* | 50-416 Q |
| | 8303030150 | 50-416 P |
| | 8303040319 | 50-416 S |
| | 8303040325* | 50-416 S |
| | 8303040358 | 50-416 S |
| | 8303040363* | 50-416 S |
| | 8303040420 | 50-416 S |
| | 8303040425* | 50-416 S |
| | 8303040498 | 50-416 S |
| | 8303040506 | 50-416 S |
| | 8303040508* | 50-416 S |
| | 8303040541 | 50-416 S |
| | 8303040549* | 50-416 S |
| | 8303040620 | 50-416 S |
| | 8303040626* | 50-416 S |
| | 8303080508 | 50-416 E |
| | 8303080508 | 50-416 E |
| | 8303140388 | 50-416 S |
| | 8303140389* | 50-416 S |
| | 8303140403 | 50-416 S |
| | 8303140404* | 50-416 S |
| | 8303140498 | 50-416 S |
| | 8303140498 | 50-416 S |
| | 8303140557 | 50-416 S |
| | 8303140565* | 50-416 S |
| | 8303150146 | 50-416 S |
| | 8303150183* | 50-416 S |
| | 8303150242 | 50-416 S |
| | 8303150254* | 50-416 S |
| | 8303150443 | 50-416 S |
| | 8303150448* | 50-416 S |
| | 8303150576 | 50-416 S |
| | 8303150586* | 50-416 S |
| | 8303160300 | 50-416 S |
| | 8303160310* | 50-416 S |
| | 8303160397 | 50-416 S |
| | 8303160403* | 50-416 S |
| | 8303160436 | 50-416 S |
| | 8303160440* | 50-416 S |
| | 8303160452 | 50-416 S |
| | 8303160455* | 50-416 S |
| | 8303160457 | 50-416 S |
| | 8303160460* | 50-416 S |
| | 8303160540 | 50-416 S |
| | 8303160549* | 50-416 S |
| | 8303160551 | 50-416 S |
| | 8303160574* | 50-416 S |
| | 8303180027 | 50-416 S |
| | 8303180033* | 50-416 S |
| | 8303180248 | 50-416 S |
| | 8303180254* | 50-416 S |
| | 8303180281 | 50-416 S |
| | 8303180292* | 50-416 S |
| | 8303180359 | 50-416 S |
| | 8303180369* | 50-416 S |
| | 8303210328 | 50-416 Q |
| | 8303210537 | 50-416 S |
| | 8303210545* | 50-416 S |
| | 8303210579* | 50-416 Q |
| | 8303210649* | 50-416 Q |
| | 8303210703* | 50-416 Q |
| | 8303210718* | 50-416 Q |
| | 8303210725* | 50-416 Q |
| | 8303210736* | 50-416 Q |
| | 8303220266 | 50-416 S |
| | 8303220275* | 50-416 S |
| | 8303220348 | 50-416 S |
| | 8303220352* | 50-416 S |
| | 8303230020 | 50-416 R |
| | 8303230022* | 50-416 R |
| | 8303240393 | 50-416 S |
| | 8303240420 | 50-416 S |
| | 8303240423* | 50-416 S |
| | 8303240432 | 50-416 S |
| | 8303240434* | 50-416 S |
| | 8303240488 | 50-416 S |
| | 8303240507 | 50-416 S |
| | 8303240520 | 50-416 S |
| | 8303240531 | 50-416 S |
| | 8303240552 | 50-416 S |
| | 8303240560 | 50-416 S |
| | 8303240560 | 50-416 S |
| | 8303240590 | 50-416 S |
| | 8303280025 | 50-416 P |
| | 8303280310 | 50-416 P |
| | 8303280316* | 50-416 P |
| | 8303290369 | 50-416 P |
| | 8303290369 | 50-416 P |
| Mississippi State Univ. | 8303170258 | 50-241 J |
| Mississippi, State of | 8303300683* | CONTRACT |
| Missouri, State of | 8303300079* | CONTRACT |
| Missouri, Univ. of, Columbia | 8303090150 | 50-186 F |
| | 8303090324* | 50-186 G |
| | 8303090407* | 50-186 G |
| Mitsubishi International Corp. (subs. of Mitsubishi Corp.) | 8303230077 | XPORTLIC |
| | 8303230082* | XPORTLIC |
| Mitsui & Co. (U.S.A.), Inc. (Subs. of Mitsui & Co., Ltd.) | 8303040108 | XPORTLIC |
| | 8303185911 | XPORTLIC |
| | 8303230010 | XPORTLIC |
| | 8303230014* | XPORTLIC |
| Monroe County, MI | 8303090295 | 50-341 H |
| Morgan Associates | 8303020026 | 50-247 Q |
| | 8303020026 | 50-247 Q |
| | 8303020046 | 50-247 Q |
| | 8303020046 | 50-247 Q |
| | 8303020052* | 50-247 Q |
| | 8303020052* | 50-247 Q |
| | 8303070110 | 50-247 Q |
| | 8303070125 | 50-247 Q |
| | 8303070125 | 50-247 Q |
| | 8303070134 | 50-247 Q |
| | 8303070134 | 50-247 Q |
| | 8303080109 | 50-247 Q |
| | 8303090321 | 50-247 Q |
| | 8303100277 | 50-247 Q |
| | 8303140335 | 50-247 Q |
| | 8303140335 | 50-247 Q |
| | 8303140343 | 50-247 Q |
| | 8303140343 | 50-247 Q |
| | 8303180235 | 50-247 Q |
| | 8303180235 | 50-247 Q |
| | 8303180245 | 50-247 Q |
| | 8303180245 | 50-247 Q |
| | 8303180277 | 50-247 Q |
| | 8303180277 | 50-247 Q |
| | 8303220231 | 50-247 Q |
| | 8303220231 | 50-247 Q |
| | 8303220261 | 50-247 Q |
| | 8303230176 | 50-247 Q |
| | 8303230176 | 50-247 Q |
| Morningside College | 8303170455* | 70-2837 |
| NCT Engineering, Inc. | 8209030274* | 50-213 P |
| NPS Industries, Inc. | 8303070153* | GA999 |
| NUS Corp. | 8303040605* | 50-324 P |
| | 8303090160 | FOIA |
| | 8303110286* | 50-280 P |
| | 8303110291* | 50-280 P |
| | 8303110297* | 50-280 P |
| | 8303110302* | 50-280 P |
| | 8303110353* | 50-280 P |
| | 8303110356* | 50-280 P |
| | 8303110358* | 50-280 P |
| | 8303110359* | 50-280 P |
| | 8303300485* | CONTRACT |
| NUSAC, Inc. | 8303150375* | 70-143 |
| | 8303180067* | CONTRACT |
| | 8303180536* | CONTRACT |
| | 8303290779* | CONTRACT |

# CORPORATE SOURCE INDEX

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303290790* | CONTRACT |
| | 8303310056* | CONTRACT |
| NUTECH Engineers, Inc. | 8303030553 | 50-354 K |
| | 8303100082* | 50-265 P |
| | 8303100087* | 50-265 P |
| | 8303110365* | 50-329 A |
| | 8303110365* | 50-329 A |
| | 8303110369* | 50-329 A |
| | 8303110369* | 50-329 A |
| | 8303110374* | 50-329 A |
| | 8303110374* | 50-329 A |
| | 8303290567* | 50-237 P |
| National Aeronautics & Space Admin | 8303040029 | XPORTLIC |
| | 8303160213 | 50-30 R |
| | 8303160219* | 50-30 R |
| National Council on Radiation Protection & Measurements | 8303020078 | PR |
| National Security Agency | 8303280013* | CONTRACT |
| Natural Resources Defense Council | 8303170421 | 70-143 |
| | 8303220212 | 50-537 Q |
| | 8303220221* | 50-537 Q |
| | 8303230203 | 50-537 H |
| | 8303250165 | 50-537 Q |
| | 8303290411 | 50-537 Q |
| Navy, Dept of | 8303010022 | 71-9138 |
| | 8303070160 | 70-143 |
| | 8303140508* | 40-8713 |
| | 8303140513* | 40-8713 |
| | 8303180086* | CONTRACT |
| | 8303180096* | CONTRACT |
| | 8303290600* | 40-8713 |
| Nebraska Public Power District | 8302090056 | 50-298 F |
| | 8302280075 | 50-298 K |
| | 8303010535* | 50-298 F |
| | 8303020066 | 50-298 P |
| | 8303080185 | 50-298 R |
| | 8303080191* | 50-298 R |
| | 8303150212 | 50-298 Q |
| | 8303150256 | 50-298 R |
| | 8303150260* | 50-298 R |
| | 8303150313 | 50-298 P |
| | 8303150550 | 50-298 R |
| | 8303150555* | 50-298 R |
| | 8303160426 | 50-298 J |
| | 8303180226* | 50-298 Q |
| | 8303240007 | 50-298 Q |
| | 8303250007 | 50-298 S |
| | 8303250011* | 50-298 S |
| | 8303250025 | 50-298 S |
| | 8303250028* | 50-298 S |
| | 8303250134 | 50-298 F |
| | 8303280038 | 50-298 F |
| | 8303290129* | 50-298 F |
| | 8303290137* | 50-298 F |
| Nebraska, State of | 8204070025* | FOIA |
| | 8303090014* | FOIA |
| | 8303180011 | State Prog |
| Nautron Products, Inc. | 8303310078* | FOIA |
| | 8303310081* | FOIA |
| | 8303310083* | FOIA |
| | 8303310085* | FOIA |
| | 8303310094* | FOIA |
| | 8303310099* | FOIA |
| | 8303310175* | FOIA |
| | 8303310204* | FOIA |
| | 8303310208* | FOIA |
| | 8303310214* | FOIA |
| | 8303310220* | FOIA |
| | 8303310227* | FOIA |
| | 8303310249* | FOIA |
| | 8303310253* | FOIA |
| | 8303310260* | FOIA |
| | 8303310265* | FOIA |
| | 8303310268* | FOIA |
| | 8303310275* | FOIA |
| | 8303310280* | FOIA |
| | 8303310291* | FOIA |
| | 8303310298* | FOIA |
| | 8303310304* | FOIA |
| | 8303310309* | FOIA |
| | 8303310314* | FOIA |
| | 8303310319* | FOIA |
| | 8303310324* | FOIA |
| | 8303310331* | FOIA |
| | 8303310338* | FOIA |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303310342* | FOIA |
| | 8303310347* | FOIA |
| Nevada, State of | 8303080078 | State Prog |
| | 8303290017* | WASTE MGT |
| New England Coalition on Nuclear Pollution | 8303080454 | 50-443 Q |
| | 8303080454 | 50-443 Q |
| | 8303080490 | 50-443 Q |
| | 8303080490 | 50-443 Q |
| | 8303220234 | 50-443 Q |
| | 8303220234 | 50-443 Q |
| | 8303220245 | 50-443 Q |
| | 8303220245 | 50-443 Q |
| | 8303290536 | 50-443 Q |
| New Hampshire, State of | 8303140322 | 50-443 Q |
| | 8303140322 | 50-443 Q |
| | 8303140327* | 50-443 Q |
| | 8303140327* | 50-443 Q |
| | 8303230251 | 50-443 Q |
| | 8303230251 | 50-443 Q |
| | 8303230256* | 50-443 Q |
| | 8303230256* | 50-443 Q |
| | 8303250153 | 50-443 Q |
| | 8303250153 | 50-443 Q |
| | 8303250154* | 50-443 Q |
| | 8303250154* | 50-443 Q |
| | 8303250158* | 50-443 Q |
| | 8303250158* | 50-443 Q |
| | 8303250162* | 50-443 Q |
| | 8303250162* | 50-443 Q |
| | 8303250166* | 50-443 Q |
| | 8303250166* | 50-443 Q |
| | 8303250168* | 50-443 Q |
| | 8303250168* | 50-443 Q |
| | 8303250170* | 50-443 Q |
| | 8303250170* | 50-443 Q |
| | 8303250171* | 50-443 Q |
| | 8303250171* | 50-443 Q |
| New Hampshire, Univ. of. | 8303230256* | 50-443 Q |
| New Mexico, State of | 8303020051* | PRM |
| New York City Audubon Society | 8303030433 | 50-247 Q |
| New York, State Univ. of, Buffalo | 8303090168 | 50-57 F |
| | 8303160345 | 50-57 P |
| | 8303160425 | 50-57 F |
| | 8303160437 | 50-57 P |
| New York, State Univ. of, Stony Brook | 8303030342* | CONTRACT |
| New York, State of | 8303040533* | State Prog |
| | 8303040543* | State Prog |
| | 8303220193 | 50-322 Q |
| | 8303220197* | 50-322 Q |
| | 8303220200* | 50-322 Q |
| | 8303220206* | 50-322 Q |
| | 8303290039* | CONTRACT |
| | 8303290045* | CONTRACT |
| | 8303300466 | 50-322 Q |
| | 8303300470 | 50-322 Q |
| New York, State of, Energy Office | 8303040470 | 50-247 Q |
| | 8303090319 | 50-247 Q |
| | 8303090319 | 50-247 Q |
| | 8303090329 | 50-247 Q |
| | 8303090329 | 50-247 Q |
| | 8303300494 | 50-247 Q |
| Newbury, MA | 8303230261 | 50-443 Q |
| | 8303230261 | 50-443 Q |
| | 8303230263* | 50-443 Q |
| | 8303230263* | 50-443 Q |
| Newburyport, MA | 8303240435* | 50-443 Q |
| Niagara Mohawk Power Corp. | 8303010628 | 50-410 S |
| | 8303010670 | 50-220 S |
| | 8303010676* | 50-220 S |
| | 8303070099 | 50-220 P |
| | 8303070104* | 50-220 P |
| | 8303070105* | 50-220 P |
| | 8303080057 | 50-410 S |
| | 8303090145 | 50-220 P |
| | 8303100253 | 50-410 F |
| | 8303110026 | 50-220 R |
| | 8303110030* | 50-220 R |
| | 8303110288 | 50-220 P |
| | 8303140457* | 50-410 Q |
| | 8303140613 | 50-410 S |
| | 8303150507 | 50-220 P |
| | 8303160136 | 50-220 R |
| | 8303160143* | 50-220 R |
| | 8303160151 | 50-220 P |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303170210 | 50-220 R |
| | 8303170212* | 50-220 R |
| | 8303170474 | 50-410 F |
| | 8303180341 | 50-220 F |
| | 8303180414 | 50-220 S |
| | 8303180416* | 50-220 S |
| | 8303210578 | 50-410 S |
| | 8303220072 | 50-220 P |
| | 8303290427 | 50-410 S |
| | 8303290444 | 50-220 Q |
| | 8303300041 | 50-220 P |
| North Carolina Municipal Power Agencies | 8303110193 | 50-400 Q |
| North Carolina State Univ. | 8303210142 | ACRS |
| | 8303310396 | 50-111 W |
| | 8303310400* | 50-111 W |
| North Carolina, State of | 8303240563 | 50-400 Q |
| North Dakota, State of | 8303240454 | State Prog |
| North Shore Committee Against Nuclear & Thermal Pollution | 8303220241 | 50-322 Q |
| Northeast Nuclear Energy Co. (subs. of Northeast Utilities) | 8303010347 | 50-336 Q |
| | 8303010386 | 50-245 P |
| | 8303010390* | 50-245 P |
| | 8303010390* | 50-245 P |
| | 8303040187* | 50-213 P |
| | 8303040368 | 50-213 Q |
| | 8303040368 | 50-213 Q |
| | 8303040487 | 50-423 C |
| | 8303040546 | 50-245 P |
| | 8303040610* | 50-213 P |
| | 8303080070 | 50-245 S |
| | 8303080076* | 50-245 S |
| | 8303080102 | 50-245 P |
| | 8303080120 | 50-245 R |
| | 8303080133* | 50-245 R |
| | 8303080144* | 50-245 R |
| | 8303080176 | 50-245 P |
| | 8303080201 | 50-336 R |
| | 8303080207* | 50-336 R |
| | 8303080208 | 50-245 R |
| | 8303080208 | 50-245 R |
| | 8303080211 | 50-245 J |
| | 8303080211 | 50-245 J |
| | 8303080218* | 50-245 R |
| | 8303080218* | 50-245 R |
| | 8303080317 | 50-213 P |
| | 8303080317 | 50-213 P |
| | 8303080345 | 50-245 S |
| | 8303080354* | 50-245 S |
| | 8303080413 | 50-336 S |
| | 8303080419* | 50-336 S |
| | 8303080465 | 50-245 P |
| | 8303100258 | 50-336 P |
| | 8303110107 | 71-4986 |
| | 8303110313 | 50-336 P |
| | 8303140253 | 50-245 S |
| | 8303140263* | 50-245 S |
| | 8303140393 | 50-245 S |
| | 8303140394* | 50-245 S |
| | 8303150345 | 50-245 P |
| | 8303150420 | 50-245 R |
| | 8303150421* | 50-245 R |
| | 8303150430 | 50-336 R |
| | 8303150433* | 50-336 R |
| | 8303160264 | 50-245 P |
| | 8303170156 | 50-336 P |
| | 8303180297 | 50-213 Q |
| | 8303180297 | 50-213 Q |
| | 8303180330 | 50-336 S |
| | 8303180336* | 50-336 S |
| | 8303180340 | 50-245 S |
| | 8303180343* | 50-245 S |
| | 8303180374 | 50-336 S |
| | 8303180382* | 50-336 S |
| | 8303230044 | 50-213 P |
| | 8303230044 | 50-213 P |
| | 8303230044 | 50-213 P |
| | 8303240407 | 50-213 R |
| | 8303240407 | 50-213 R |
| | 8303240407 | 50-213 R |
| | 8303240407 | 50-213 R |
| | 8303240408* | 50-213 R |
| | 8303240408* | 50-213 R |
| | 8303240408* | 50-213 R |
| | 8303240408* | 50-213 R |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303240457 | 50-336 S |
| | 8303240463* | 50-336 S |
| | 8303240572 | 50-245 S |
| | 8303240581* | 50-245 S |
| | 8303290064* | 50-213 F |
| | 8303290064* | 50-213 F |
| | 8303290064* | 50-213 F |
| | 8303290195 | 50-213 P |
| | 8303290195 | 50-213 P |
| | 8303290195 | 50-213 P |
| | 8303290243* | 50-245 F |
| | 8303290243* | 50-245 F |
| | 8303290251* | 50-245 F |
| | 8303290251* | 50-245 F |
| | 8303290313 | 50-245 P |
| | 8303290443 | 50-213 P |
| | 8303290495 | 50-245 P |
| | 8303290560 | 50-245 P |
| | 8303300359 | 50-336 Q |
| | 8303310311 | 50-213 P |
| | 8303310311 | 50-213 P |
| | 8303310311 | 50-213 P |
| Northeast Utilities | 8303010254 | NUREG |
| | 8303010347 | 50-336 Q |
| | 8303010386 | 50-245 P |
| | 8303040187* | 50-213 P |
| | 8303040368 | 50-213 Q |
| | 8303040487 | 50-423 C |
| | 8303040493* | 50-423 C |
| | 8303040496* | 50-423 K |
| | 8303040546 | 50-245 P |
| | 8303080070 | 50-245 S |
| | 8303080102 | 50-245 P |
| | 8303080120 | 50-245 R |
| | 8303080176 | 50-245 P |
| | 8303080201 | 50-336 R |
| | 8303080208 | 50-245 R |
| | 8303080317 | 50-213 P |
| | 8303080317 | 50-213 P |
| | 8303080335 | 50-213 P |
| | 8303080342* | 50-213 P |
| | 8303080345 | 50-245 S |
| | 8303080413 | 50-336 S |
| | 8303080465 | 50-245 P |
| | 8303100258 | 50-336 P |
| | 8303110107 | 71-4986 |
| | 8303110313 | 50-336 P |
| | 8303110322* | 50-336 P |
| | 8303140253 | 50-245 S |
| | 8303140393 | 50-245 S |
| | 8303150345 | 50-245 P |
| | 8303150420 | 50-245 R |
| | 8303150430 | 50-336 R |
| | 8303160264 | 50-245 P |
| | 8303170156 | 50-336 P |
| | 8303180297 | 50-213 Q |
| | 8303180297 | 50-213 Q |
| | 8303180330 | 50-336 S |
| | 8303180340 | 50-245 S |
| | 8303180374 | 50-336 S |
| | 8303230044 | 50-213 P |
| | 8303230044 | 50-213 P |
| | 8303230044 | 50-213 P |
| | 8303240407 | 50-213 R |
| | 8303240407 | 50-213 R |
| | 8303240407 | 50-213 R |
| | 8303240408* | 50-213 R |
| | 8303240408* | 50-213 R |
| | 8303240408* | 50-213 R |
| | 8303240408* | 50-213 R |
| | 8303240457 | 50-336 S |
| | 8303240572 | 50-245 S |
| | 8303290064* | 50-213 F |
| | 8303290064* | 50-213 F |
| | 8303290195 | 50-213 P |
| | 8303290195 | 50-213 P |
| | 8303290195 | 50-213 P |
| | 8303290198 | 50-213 P |
| | 8303290313 | 50-245 P |
| | 8303290443 | 50-213 P |
| | 8303290452 | 50-336 P |
| | 8303290459* | 50-336 P |
| | 8303290495 | 50-245 P |
| | 8303290560 | 50-245 P |
| | 8303300359 | 50-336 Q |
| | 8303310311 | 50-213 P |

# CORPORATE SOURCE INDEX


| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY | |
|---|---|---|---|
| | 8303310311 | 50-213 | P |
| | 8303310311 | 50-213 | P |
| Northeast Utilities Service Co. | 8303040214* | 10CFR | |
| | 8303290064* | 50-213 | F |
| Northern California Power Agency, California, State of. | 8303070109 | PROJ | |
| Northern States Power Co. | 8303010202 | 50-263 | G |
| | 8303010211* | 50-263 | G |
| | 8303040399 | 50-263 | G |
| | 8303040478 | 50-263 | V |
| | 8303040478 | 50-263 | V |
| | 8303080049 | 50-282 | R |
| | 8303080053* | 50-282 | R |
| | 8303080464 | 50-263 | R |
| | 8303080469* | 50-263 | R |
| | 8303090691* | 50-263 | F |
| | 8303090698* | 50-263 | F |
| | 8303100160 | 50-263 | P |
| | 8303100186* | 50-263 | F |
| | 8303100186* | 50-263 | F |
| | 8303100186* | 50-263 | F |
| | 8303100186* | 50-263 | F |
| | 8303100193* | 50-263 | F |
| | 8303100193* | 50-263 | F |
| | 8303100193* | 50-263 | F |
| | 8303100193* | 50-263 | F |
| | 8303110299 | 50-282 | G |
| | 8303110301* | 50-282 | G |
| | 8303140250 | 50-282 | P |
| | 8303150269 | 50-282 | G |
| | 8303150277 | 50-282 | R |
| | 8303150277 | 50-282 | R |
| | 8303150280* | 50-282 | R |
| | 8303150280* | 50-282 | R |
| | 8303150295 | 50-263 | R |
| | 8303150307* | 50-263 | R |
| | 8303150460 | 50-282 | R |
| | 8303150462* | 50-282 | R |
| | 8303150604 | 50-263 | R |
| | 8303150607* | 50-263 | R |
| | 8303170215 | 50-282 | F |
| | 8303170381 | 50-282 | P |
| | 8303170381 | 50-282 | P |
| | 8303170500 | 50-263 | P |
| | 8303170512* | 50-263 | P |
| | 8303170521* | 50-263 | P |
| | 8303170527* | 50-263 | P |
| | 8303170536* | 50-263 | P |
| | 8303180014 | 50-263 | P |
| | 8303180112 | 71-9151 | |
| | 8303180531 | 50-263 | P |
| | 8303210058 | 50-282 | P |
| | 8303220213 | 50-282 | S |
| | 8303220219* | 50-282 | S |
| | 8303240433 | 50-263 | S |
| | 8303240436* | 50-263 | S |
| | 8303280039 | 50-263 | I |
| | 8303280044* | 50-263 | I |
| | 8303280142 | 50-306 | S |
| | 8303280151* | 50-306 | S |
| | 8303280216 | 50-263 | F |
| | 8303290246 | 50-263 | G |
| | 8303290454 | 50-282 | G |
| | 8303290454 | 50-282 | G |
| | 8303290486* | 50-263 | G |
| | 8303300123 | 50-263 | I |
| | 8303300133* | 50-263 | I |
| | 8303300681* | 50-263 | F |
| | 8303300685* | 50-263 | F |
| | 8303310281 | 50-282 | P |
| | 8303310281 | 50-282 | P |
| Northern Sun Alliance | 8303100065 | 50-263 | P |
| | 8303230298 | 50-263 | P |
| Northrop Corp. | 8303220083 | 50-187 | R |
| | 8303220090* | 50-187 | R |
| Northwest Community Hosp. Arlington Heights, IL | 8302100335* | PR | |
| Northwestern Univ. | 8303310103* | CONTRACT | |
| Norton, Burke, Berry & French | 8303290296 | 50-275 | G |
| Norway | 8303170028 | XPORTLIC | |
| Nuclear Energy Service, Inc. | 8303180295* | 50-400 | G |
| | 8303300225* | 50-440 | E |
| Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) | 8303010047 | 70-143 | |
| | 8303010054 | 70-143 | |
| | 8303010065 | 70-143 | |
| | 8303010089 | 70-143 | |
| | 8303010693 | 70-143 | |
| | 8303010699 | 70-143 | |
| | 8303010702 | 70-143 | |
| | 8303110073 | 70-143 | |
| | 8303110399 | 70-143 | |
| | 8303140636 | 70-143 | |
| | 8303210076 | 70-143 | |
| | 8303280241* | 70-143 | |
| Nuclear Law Center | 8303140267 | 50-142 | G |
| | 8303140273 | 50-142 | G |
| Nuclear Packaging, Inc. | 8303020153 | 71-9073 | |
| | 8303100315 | 71-9159 | |
| | 8303180527 | 71-9079 | |
| | 8303180534* | 71-9079 | |
| Nuclear Pharmacy, Inc. | 8303240176* | FOIA | |
| Nuclear System | 8303290267 | 71-9133 | |
| O'Neill, J. | 8303140362 | 50-155 | G |
| | 8303230217* | 50-155 | G |
| | 8303230246 | 50-155 | G |
| | 8303230250* | 50-155 | G |
| Oak Ridge National Laboratory | 8303030318 | RES | |
| | 8303030721 | RES | |
| | 8303100121 | RES | |
| | 8303100136 | RES | |
| | 8303100433 | NUREG | |
| | 8303140622 | NUREG | |
| | 8303140630 | NUREG | |
| | 8303160009 | NUREG | |
| | 8303170616 | NUREG | |
| | 8303170624 | NUREG | |
| | 8303180556 | RES | |
| | 8303220493 | NUREG | |
| | 8303230142 | NUREG | |
| | 8303230408 | NUREG | |
| | 8303230467 | NUREG | |
| | 8303280066 | NUREG | |
| | 8303290673 | NUREG | |
| | 8303290683 | NUREG | |
| | 8303290698 | NUREG | |
| | 8303290710 | NUREG | |
| | 8303290717 | NUREG | |
| | 8303300472 | NUREG | |
| | 8303300511 | NUREG | |
| | 8303300606 | RES | |
| | 8303300638 | NUREG | |
| | 8303300651 | NUREG | |
| Office of Management & Budget | 8303020125 | ORG | |
| | 8303020131 | ORG | |
| | 8303020137 | ORG | |
| | 8303160022 | ORG | |
| Offshore Power Systems (subs. of Westinghouse Electric Corp.) | 8303100400 | 50-437 | A |
| Ogle Petroleum, Inc. | 8303090017 | 40-8745 | |
| | 8303090589 | 40-8745 | |
| | 8303290555 | 40-8745 | |
| | 8303290561* | 40-8745 | |
| Ohio Citizens for Responsible Energy | 8303010087 | 50-440 | G |
| | 8303010087 | 50-440 | G |
| | 8303010090 | 50-440 | G |
| | 8303010090 | 50-440 | G |
| | 8303010098 | 50-440 | G |
| | 8303010098 | 50-440 | G |
| | 8303090020 | FOIA | |
| | 8303100076 | 50-440 | A |
| | 8303300330 | 50-440 | G |
| | 8303310450 | FOIA | |
| Ohio, State of | 8303290413* | CONTRACT | |
| | 8303300576* | CONTRACT | |
| Oklahoma, State of | 8303010177 | 50-556 | G |
| | 8303020251 | 40-8027 | |
| Oklahoma, Univ. of | 8303010560* | 50-112 | G |
| | 8303100564 | NUREG | |
| Omaha Public Power District | 8302230355 | 50-285 | P |
| | 8303010228 | 50-285 | P |
| | 8303040466 | 50-285 | R |
| | 8303040471* | 50-285 | R |
| | 8303080438 | 50-285 | V |
| | 8303090181 | 50-285 | P |
| | 8303090204 | 50-285 | P |
| | 8303090209* | 50-285 | P |
| | 8303100101* | 50-285 | F |
| | 8303100123* | 50-285 | F |
| | 8303100565* | 50-285 | F |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303100569* | 50-285 F |
| | 8303150196 | 50-285 P |
| | 8303150205 | 50-285 P |
| | 8303150222 | 50-285 P |
| | 8303180012 | 50-285 P |
| | 8303180288 | 50-285 Q |
| | 8303180317 | 50-285 R |
| | 8303180325* | 50-285 R |
| | 8303280183 | 50-285 J |
| | 8303280234* | 50-285 F |
| Omaha World-Herald Omaha, NE | 8303100022 | FOIA |
| Oregon, State of | 8303030680* | CONTRACT |
| Pacific Gas & Electric Co | 8303010080 | PROJ |
| | 8303010285 | 50-275 P |
| | 8303010421* | 50-275 Q |
| | 8303010625 | 50-275 S |
| | 8303010635* | 50-275 S |
| | 8303040469 | 50-323 Q |
| | 8303040531 | 50-275 P |
| | 8303080006 | 50-275 T |
| | 8303080017* | 50-275 T |
| | 8303080031 | 50-275 R |
| | 8303080031 | 50-275 R |
| | 8303080036* | 50-275 R |
| | 8303080036* | 50-275 R |
| | 8303080114 | 50-275 Q |
| | 8303080114 | 50-275 Q |
| | 8303080173 | 50-275 R |
| | 8303080175 | 50-133 R |
| | 8303080177* | 50-275 R |
| | 8303080181* | 50-133 R |
| | 8303080212 | 50-275 P |
| | 8303080307 | 50-275 P |
| | 8303080388 | 50-275 P |
| | 8303080440 | 50-133 V |
| | 8303080448 | 50-275 P |
| | 8303080521 | 50-275 F |
| | 8303090226 | 50-133 Q |
| | 8303090258 | 50-275 H |
| | 8303090330 | 50-275 V |
| | 8303100241 | 50-275 R |
| | 8303100247* | 50-275 R |
| | 8303110506* | 50-275 P |
| | 8303140446 | 50-275 Q |
| | 8303150508 | 50-275 R |
| | 8303150512* | 50-275 R |
| | 8303150552 | 50-133 R |
| | 8303150561* | 50-133 R |
| | 8303170348 | 50-275 P |
| | 8303170348 | 50-275 P |
| | 8303210254 | 50-275 F |
| | 8303210254 | 50-275 F |
| | 8303220304 | 50-275 P |
| | 8303240513 | 50-275 P |
| | 8303250061 | 50-275 R |
| | 8303250064* | 50-275 R |
| | 8303250079 | 50-275 R |
| | 8303250081* | 50-275 R |
| | 8303280027 | 50-133 P |
| | 8303280042 | 50-275 P |
| | 8303280132 | 50-133 J |
| | 8303290296 | 50-275 Q |
| | 8303290296 | 50-275 Q |
| | 8303290315 | 50-275 P |
| | 8303290315 | 50-275 P |
| | 8303290345 | 50-133 I |
| | 8303290345 | 50-133 I |
| | 8303290345 | 50-133 I |
| | 8303290349* | 50-133 I |
| | 8303290365 | 50-275 R |
| | 8303300030 | 50-275 P |
| | 8303300030 | 50-275 P |
| | 8303300035 | 50-275 P |
| | 8303300115 | 50-275 P |
| | 8303300121 | 50-133 P |
| | 8303300697* | 50-275 F |
| | 8303300702* | 50-275 F |
| Palmetto Alliance | 8303230192 | 50-413 Q |
| | 8303310345 | 50-413 Q |
| Parents Concerned About Indian Point | 8303010605 | 50-247 Q |
| | 8303030433 | 50-247 Q |
| | 8303100242 | 50-247 Q |
| | 8303150415 | 50-247 Q |
| | 8303180144 | 50-247 Q |
| | 8303180144 | 50-247 Q |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303180217 | 50-247 Q |
| | 8303180217 | 50-247 Q |
| | 8303230207 | 50-247 Q |
| Pathfinder Mines Corp | 8303090584 | 40-2259 |
| | 8303090591* | 40-2259 |
| | 8303090626 | 40-2259 |
| | 8303160034 | 40-2259 |
| Pechiney Ugine Kuhlmann Development, Inc | 8303020300 | XPORTLIC |
| | 8303030178* | XPORTLIC |
| Pennsylvania Power & Light Co | 8302280091 | 50-387 P |
| | 8303010267 | 50-388 S |
| | 8303010332 | 50-387 P |
| | 8303010561 | 50-387 S |
| | 8303010567* | 50-387 S |
| | 8303010611 | 50-387 S |
| | 8303010620* | 50-387 S |
| | 8303010637 | 50-387 S |
| | 8303010651 | 50-387 S |
| | 8303010659* | 50-387 S |
| | 8303040403 | 50-387 P |
| | 8303070065 | 50-387 F |
| | 8303070080 | 50-387 P |
| | 8303070080 | 50-387 P |
| | 8303070097 | 50-387 P |
| | 8303070097 | 50-387 P |
| | 8303080002 | 50-387 S |
| | 8303080007* | 50-387 S |
| | 8303080300 | 50-387 S |
| | 8303080311* | 50-387 S |
| | 8303080400 | 50-387 R |
| | 8303080403* | 50-387 R |
| | 8303080474 | 50-387 Q |
| | 8303090098 | 50-387 S |
| | 8303090116* | 50-387 S |
| | 8303090229 | 50-387 V |
| | 8303090229 | 50-387 V |
| | 8303090234 | 50-387 P |
| | 8303090234 | 50-387 P |
| | 8303110270 | 50-387 F |
| | 8303110270 | 50-387 F |
| | 8303140205 | 50-387 S |
| | 8303140237 | 50-387 P |
| | 8303140405 | 50-387 S |
| | 8303140412* | 50-387 S |
| | 8303140458 | 50-387 P |
| | 8303140458 | 50-387 P |
| | 8303140464* | 50-387 P |
| | 8303140464* | 50-387 P |
| | 8303140474 | 50-387 R |
| | 8303140485* | 50-387 R |
| | 8303150485 | 50-387 R |
| | 8303150487* | 50-387 R |
| | 8303160174 | 50-387 S |
| | 8303160180* | 50-387 S |
| | 8303160186 | 50-387 S |
| | 8303160191* | 50-387 S |
| | 8303160227 | 50-387 S |
| | 8303160227 | 50-387 S |
| | 8303160241 | 50-387 S |
| | 8303160250* | 50-387 S |
| | 8303160261 | 50-387 S |
| | 8303160281 | 50-387 P |
| | 8303160289* | 50-387 P |
| | 8303160297* | 50-387 P |
| | 8303160369 | 50-387 S |
| | 8303160375* | 50-387 S |
| | 8303170524 | 50-387 P |
| | 8303210332 | 50-387 I |
| | 8303210332 | 50-387 I |
| | 8303210333* | 50-387 I |
| | 8303210333* | 50-387 I |
| | 8303210533 | 50-387 S |
| | 8303210692 | 50-387 S |
| | 8303210701* | 50-387 S |
| | 8303210709 | 50-387 S |
| | 8303210713* | 50-387 S |
| | 8303210746 | 50-387 S |
| | 8303210751* | 50-387 S |
| | 8303220177 | 50-387 P |
| | 8303220177 | 50-387 P |
| | 8303220276 | 50-387 P |
| | 8303220283* | 50-387 P |
| | 8303220329 | 50-387 P |
| | 8303240503 | 50-387 S |
| | 8303240523* | 50-387 S |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303250117 | 50-387 S |
| | 8303250123* | 50-387 S |
| | 8303280020 | 50-387 F |
| | 8303280063 | 50-387 X |
| | 8303280063 | 50-387 X |
| | 8303280063 | 50-387 X |
| | 8303280162 | 50-387 P |
| | 8303290547* | 50-387 F |
| | 8303290547* | 50-387 F |
| | 8303290548* | 50-387 F |
| | 8303290548* | 50-387 F |
| | 8303310010* | 50-387 F |
| | 8303310010* | 50-387 F |
| | 8303310011* | 50-387 F |
| | 8303310011* | 50-387 F |
| Pennsylvania State Univ. | 8303210066 | 70-113 |
| | 8303280346* | 50-289 P |
| Pennsylvania, Commonwealth of. | 8303070072* | 50-387 F |
| | 8303080068 | 50-289 Q |
| Philadelphia Electric Co. | 8301310260 | 50-352 A |
| | 8301310266* | 50-352 A |
| | 8301310270* | 50-352 F |
| | 8303010431 | 50-352 A |
| | 8303010431 | 50-352 A |
| | 8303020029 | 50-352 A |
| | 8303020029 | 50-352 A |
| | 8303020039* | 50-352 A |
| | 8303020039* | 50-352 A |
| | 8303020042* | 50-352 C |
| | 8303020042* | 50-352 C |
| | 8303020047* | 50-352 K |
| | 8303020047* | 50-352 K |
| | 8303030016 | 50-352 A |
| | 8303030016 | 50-352 A |
| | 8303030079 | 50-277 V |
| | 8303030079 | 50-277 V |
| | 8303030671 | 50-352 S |
| | 8303040439 | 50-352 G |
| | 8303040523 | 50-277 F |
| | 8303040523 | 50-277 F |
| | 8303040554 | 50-352 S |
| | 8303040554 | 50-352 S |
| | 8303070071 | 50-277 F |
| | 8303080205 | 50-277 J |
| | 8303080205 | 50-277 J |
| | 8303080373* | 50-277 Q |
| | 8303080385 | 50-277 S |
| | 8303080395* | 50-277 S |
| | 8303080452 | 50-277 R |
| | 8303080452 | 50-277 R |
| | 8303080458* | 50-277 P |
| | 8303080458* | 50-277 R |
| | 8303090118 | 50-277 R |
| | 8303090118 | 50-277 R |
| | 8303090122* | 50-277 R |
| | 8303090122* | 50-277 R |
| | 8303100205 | 50-352 A |
| | 8303100358 | 50-277 J |
| | 8303110329 | 50-277 P |
| | 8303110329 | 50-277 P |
| | 8303140311 | 50-278 S |
| | 8303140367 | 50-352 A |
| | 8303140530 | 50-278 S |
| | 8303140537* | 50-278 S |
| | 8303150371 | 50-277 P |
| | 8303150371 | 50-277 P |
| | 8303150378* | 50-277 P |
| | 8303150379* | 50-277 P |
| | 8303150385* | 50-277 P |
| | 8303150385* | 50-277 P |
| | 8303150391 | 50-352 Q |
| | 8303150571 | 50-277 P |
| | 8303150571 | 50-277 P |
| | 8303150577* | 50-277 P |
| | 8303150577* | 50-277 P |
| | 8303160190 | 50-277 S |
| | 8303160332 | 50-277 R |
| | 8303160332 | 50-277 R |
| | 8303160338* | 50-277 R |
| | 8303160494 | 50-352 K |
| | 8303160494 | 50-352 K |
| | 8303160559 | 50-277 R |
| | 8303160559 | 50-277 R |
| | 8303160567* | 50-277 R |
| | 8303160567* | 50-277 R |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303170159 | 50-171 I |
| | 8303170159 | 50-171 I |
| | 8303170159 | 50-171 I |
| | 8303170159 | 50-171 I |
| | 8303170159 | 50-171 I |
| | 8303170159 | 50-171 I |
| | 8303170159 | 50-171 I |
| | 8303170159 | 50-171 I |
| | 8303170182* | 50-171 I |
| | 8303170182* | 50-171 I |
| | 8303170182* | 50-171 I |
| | 8303170182* | 50-171 I |
| | 8303170182* | 50-171 I |
| | 8303170182* | 50-171 I |
| | 8303170182* | 50-171 I |
| | 8303170182* | 50-171 I |
| | 8303170339 | 50-277 P |
| | 8303170339 | 50-277 P |
| | 8303170545 | 50-352 E |
| | 8303170545 | 50-352 E |
| | 8303180090 | 71-6601 |
| | 8303180327 | 50-277 P |
| | 8303180349 | 50-352 A |
| | 8303220211 | 50-277 Q |
| | 8303240450* | 50-277 Q |
| | 8303240450* | 50-277 Q |
| | 8303240475* | 50-352 Q |
| | 8303240477* | 50-352 Q |
| | 8303280035 | 50-352 A |
| | 8303280238 | 50-277 S |
| | 8303280238 | 50-277 S |
| | 8303280277 | 50-277 F |
| | 8303290303 | 50-277 P |
| | 8303290350 | 50-277 J |
| | 8303290350 | 50-277 J |
| | 8303290388 | 50-278 S |
| | 8303290438 | 50-352 Q |
| | 8303290479 | 50-352 A |
| | 8303300588* | 50-277 F |
| | 8303300594* | 50-277 F |
| Phoenix Associates, Inc. | 8303300574* | CONTRACT |
| Pickard, Lowe & Garrick, Inc. | 8303010392* | 50-244 P |
| | 8303210538 | 50-247 P |
| | 8303250145 | 50-247 T |
| Planning Research Corp. | 8302030718* | CONTRACT |
| | 8303290618* | CONTRACT |
| Plateau Resources, Ltd. | 8303090021 | 40-7869 |
| | 8303090064 | 40-8698 |
| | 8303090068* | 40-8698 |
| | 8303090115 | 40-7869 |
| | 8303090134 | 40-8698 |
| | 8303090141* | 40-8698 |
| | 8303090617 | 40-8674 |
| | 8303160655 | 40-8698 |
| | 8303160658* | 40-8698 |
| | 8303170320 | 40-7869 |
| | 8303170324 | 40-8674 |
| | 8303170331 | 40-8698 |
| | 8303220435 | 40-8698 |
| | 8303220440* | 40-8698 |
| | 8303300188 | 40-8698 |
| | 8303310283 | 40-8698 |
| | 8303310296* | 40-8698 |
| Pollution & Environmental Problems, Inc. | 8303090273 | 50-454 T |
| Portland General Electric Co. | 8303010588 | 50-344 Q |
| | 8303080313 | 50-344 R |
| | 8303080321* | 50-344 R |
| | 8303080437 | 50-344 Q |
| | 8303090218 | 50-344 P |
| | 8303110108 | 50-344 S |
| | 8303110238 | 50-344 R |
| | 8303110243* | 50-344 R |
| | 8303110330 | 50-344 S |
| | 8303110335* | 50-344 S |
| | 8303110390 | 50-344 S |
| | 8303150489 | 50-344 R |
| | 8303150502* | 50-344 R |
| | 8303150553 | 50-344 Q |
| | 8303230034 | 50-344 J |
| | 8303240236 | 50-344 P |
| | 8303280189 | 50-344 P |
| | 8303290215 | 50-344 F |
| Portsmouth, NH | 8303290432 | 50-443 Q |
| Power Authority of the State of New York | 8302180153 | 50-333 P |
| | 8303020008 | 50-333 P |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303020015* | 50-333 P |
| | 8303020021* | 50-333 P |
| | 8303020026 | 50-247 Q |
| | 8303020026 | 50-247 Q |
| | 8303020046 | 50-247 Q |
| | 8303020046 | 50-247 Q |
| | 8303020052* | 50-247 Q |
| | 8303020052* | 50-247 Q |
| | 8303040349 | 50-333 F |
| | 8303040437 | 50-333 R |
| | 8303040442* | 50-333 R |
| | 8303070110 | 50-247 Q |
| | 8303070125 | 50-247 Q |
| | 8303070125 | 50-247 Q |
| | 8303070134 | 50-247 Q |
| | 8303070134 | 50-247 Q |
| | 8303080109 | 50-247 Q |
| | 8303080322 | 50-286 V |
| | 8303080443 | 50-286 H |
| | 8303080443 | 50-286 H |
| | 8303080443 | 50-286 H |
| | 8303080472 | 50-333 S |
| | 8303080477* | 50-333 S |
| | 8303080493 | 50-333 V |
| | 8303080501 | 50-333 S |
| | 8303080506* | 50-333 S |
| | 8303090182 | 50-333 S |
| | 8303090195* | 50-333 S |
| | 8303090314 | 50-247 Q |
| | 8303090314 | 50-247 Q |
| | 8303090321 | 50-247 Q |
| | 8303090321 | 50-247 Q |
| | 8303100140* | 50-333 Q |
| | 8303100246* | 50-333 Q |
| | 8303100277 | 50-247 Q |
| | 8303110245 | 50-286 P |
| | 8303140222 | 50-333 R |
| | 8303140227* | 50-333 R |
| | 8303140335 | 50-247 Q |
| | 8303140335 | 50-247 Q |
| | 8303140343 | 50-247 Q |
| | 8303140343 | 50-247 Q |
| | 8303140497 | 50-333 S |
| | 8303140507* | 50-333 S |
| | 8303150437 | 50-286 R |
| | 8303150532 | 50-286 R |
| | 8303150536* | 50-286 R |
| | 8303160206 | 50-333 Q |
| | 8303160247 | 50-286 Q |
| | 8303160374 | 50-286 R |
| | 8303160377* | 50-286 R |
| | 8303170207 | 50-286 P |
| | 8303180235 | 50-247 Q |
| | 8303180235 | 50-247 Q |
| | 8303180245 | 50-247 Q |
| | 8303180245 | 50-247 Q |
| | 8303180277 | 50-247 Q |
| | 8303180277 | 50-247 Q |
| | 8303180350 | 50-333 P |
| | 8303180356 | 50-333 P |
| | 8303180362 | 50-333 P |
| | 8303180365 | 50-333 P |
| | 8303180375 | 50-333 P |
| | 8303180479 | 50-286 P |
| | 8303220153 | 50-333 P |
| | 8303220154* | 50-333 P |
| | 8303220231 | 50-247 Q |
| | 8303220231 | 50-247 Q |
| | 8303220241 | 50-247 Q |
| | 8303220272 | 50-247 Q |
| | 8303230176 | 50-247 Q |
| | 8303230176 | 50-247 Q |
| | 8303230179* | 50-247 Q |
| | 8303230179* | 50-247 Q |
| | 8303250032 | 50-333 S |
| | 8303250035* | 50-333 S |
| | 8303250055 | 50-286 R |
| | 8303250057* | 50-286 R |
| | 8303250059 | 50-333 S |
| | 8303250065* | 50-333 S |
| | 8303250145 | 50-247 T |
| | 8303250145 | 50-247 T |
| | 8303250149* | 50-247 T |
| | 8303300303 | 50-247 Q |
| | 8303300303 | 50-247 Q |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303300307* | 50-247 Q |
| | 8303300307* | 50-247 Q |
| | 8303300310* | 50-333 Q |
| | 8303300313* | 50-247 Q |
| | 8303300313* | 50-247 Q |
| | 8303300319* | 50-247 Q |
| | 8303300319* | 50-247 Q |
| | 8303300322* | 50-247 Q |
| | 8303300322* | 50-247 Q |
| | 8303300326 | 50-247 Q |
| | 8303300326 | 50-247 Q |
| | 8303300374 | 50-247 Q |
| | 8303300417 | 50-247 Q |
| | 8303300489 | 50-247 Q |
| Prairie Alliance | 8303110222 | 50-461 Q |
| Professional Examining Service | 8303170656* | CONTRACT |
| Project Management Corp. | 8303080497 | 50-537 Q |
| | 8303290422 | 50-537 Q |
| Public Interest Research Group, New York | 8303030433 | 50-247 Q |
| | 8303030433 | 50-247 Q |
| | 8303070113 | 50-247 Q |
| | 8303070113 | 50-247 Q |
| | 8303070161 | 50-247 Q |
| | 8303070161 | 50-247 Q |
| | 8303150415 | 50-247 Q |
| | 8303180144 | 50-247 Q |
| | 8303180144 | 50-247 Q |
| | 8303180217 | 50-247 Q |
| | 8303180217 | 50-247 Q |
| | 8303230207 | 50-247 Q |
| | 8303240545 | 50-247 T |
| Public Service Co. of Colorado | 8303010273 | 50-267 R |
| | 8303010389* | 50-267 R |
| | 8303010540 | 50-267 P |
| | 8303080056 | 50-267 R |
| | 8303080088 | 50-267 P |
| | 8303080096* | 50-267 P |
| | 8303080101* | 50-267 P |
| | 8303080323 | 50-267 Q |
| | 8303100025* | 50-267 F |
| | 8303100030* | 50-267 F |
| | 8303150235 | 50-267 R |
| | 8303150241* | 50-267 R |
| | 8303150247 | 50-267 S |
| | 8303150253* | 50-267 S |
| | 8303150348 | 50-267 R |
| | 8303150350* | 50-267 R |
| | 8303180099 | 71-9081 |
| | 8303210546 | 50-267 S |
| | 8303210559* | 50-267 S |
| | 8303210629 | 50-267 S |
| | 8303210635* | 50-267 S |
| | 8303210641 | 50-267 R |
| | 8303210664 | 50-267 P |
| | 8303250006 | 50-267 R |
| | 8303250009* | 50-267 R |
| | 8303280036 | 50-267 P |
| | 8303280240 | 50-267 S |
| | 8303280249* | 50-267 S |
| | 8303280254 | 50-267 S |
| | 8303280257* | 50-267 S |
| | 8303280265* | 50-267 S |
| Public Service Co. of Indiana, Inc. | 8302100345 | PRM |
| | 8302280121 | 50-546 A |
| | 8302280121 | 50-546 A |
| | 8302280137* | 50-546 K |
| | 8302280137* | 50-546 K |
| | 8303100555* | 50-546 F |
| | 8303150123 | 50-546 S |
| | 8303150123 | 50-546 S |
| | 8303150286 | 50-546 S |
| | 8303150286 | 50-546 S |
| | 8303170409 | 50-546 V |
| | 8303220020 | 50-546 S |
| | 8303220259 | 50-546 A |
| | 8303280096 | 50-546 A |
| Public Service Co. of New Hampshire | 8302180118 | 50-443 Q |
| | 8303010078 | 50-443 Q |
| | 8303010078 | 50-443 Q |
| | 8303010082* | 50-443 Q |
| | 8303010082* | 50-443 Q |
| | 8303010409 | 50-443 A |
| | 8303010409 | 50-443 A |
| | 8303010533 | 50-443 A |
| | 8303010533 | 50-443 A |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303010578 | 50-443 F |
| | 8303010578 | 50-443 F |
| | 8303020083 | 50-443 A |
| | 8303020083 | 50-443 A |
| | 8303020085 | 50-443 A |
| | 8303020085 | 50-443 A |
| | 8303080082 | 50-443 G |
| | 8303080082 | 50-443 G |
| | 8303080089* | 50-443 G |
| | 8303080089* | 50-443 G |
| | 8303080106* | 50-443 G |
| | 8303080106* | 50-443 G |
| | 8303150195 | 50-443 A |
| | 8303150195 | 50-443 A |
| | 8303150207 | 50-443 A |
| | 8303150207 | 50-443 A |
| | 8303150331 | 50-443 E |
| | 8303150331 | 50-443 E |
| | 8303150436 | 50-443 A |
| | 8303150436 | 50-443 A |
| | 8303170358 | 50-443 A |
| | 8303170422 | 50-443 G |
| | 8303170422 | 50-443 G |
| | 8303170426* | 50-443 G |
| | 8303170426* | 50-443 G |
| | 8303170430* | 50-443 G |
| | 8303170430* | 50-443 G |
| | 8303170437 | 50-443 G |
| | 8303170437 | 50-443 G |
| | 8303170441 | 50-443 A |
| | 8303170441 | 50-443 A |
| | 8303180151 | 50-443 G |
| | 8303220148* | 50-443 G |
| | 8303230191 | 50-443 G |
| | 8303230191 | 50-443 G |
| | 8303230199* | 50-443 G |
| | 8303230199* | 50-443 G |
| | 8303240366 | 50-443 S |
| | 8303240441 | 50-443 S |
| | 8303290254 | 50-443 E |
| | 8303290254 | 50-443 E |
| | 8303290445 | 50-443 G |
| | 8303290445 | 50-443 G |
| | 8303290449* | 50-443 G |
| | 8303290449* | 50-443 G |
| Public Service Electric & Gas Co. of New Jersey | 8303010680 | 50-272 S |
| | 8303030009 | 50-311 S |
| | 8303030014* | 50-311 S |
| | 8303030050 | 50-311 S |
| | 8303030060 | 50-272 S |
| | 8303030118 | 50-272 S |
| | 8303030126* | 50-272 S |
| | 8303030257 | 50-272 S |
| | 8303030272* | 50-272 S |
| | 8303030276 | 50-272 S |
| | 8303030292 | 50-272 S |
| | 8303030308* | 50-272 S |
| | 8303030458 | 50-354 A |
| | 8303030467* | 50-354 F |
| | 8303030470* | 50-354 A |
| | 8303030524* | 50-354 M |
| | 8303030527* | 50-354 K |
| | 8303030532* | 50-354 C |
| | 8303030537 | 50-354 K |
| | 8303030541 | 50-354 K |
| | 8303030545 | 50-354 K |
| | 8303030550 | 50-354 K |
| | 8303030553 | 50-354 K |
| | 8303030558 | 50-354 K |
| | 8303030561 | 50-354 K |
| | 8303030564 | 50-354 K |
| | 8303030569 | 50-354 K |
| | 8303030573 | 50-354 K |
| | 8303030577 | 50-354 K |
| | 8303030583 | 50-354 K |
| | 8303030586 | 50-354 K |
| | 8303030589 | 50-354 K |
| | 8303030593 | 50-354 K |
| | 8303030599 | 50-354 K |
| | 8303030603 | 50-354 K |
| | 8303030607 | 50-354 K |
| | 8303030610 | 50-354 K |
| | 8303030615 | 50-354 K |
| | 8303030621 | 50-354 K |
| | 8303030623 | 50-354 K |
| | 8303030630 | 50-354 K |
| | 8303030635 | 50-354 K |
| | 8303030639 | 50-354 K |
| | 8303040390 | 50-272 R |
| | 8303040390 | 50-272 R |
| | 8303040418 | 50-272 P |
| | 8303040634* | 50-272 R |
| | 8303040634* | 50-272 R |
| | 8303080329 | 50-311 S |
| | 8303080339* | 50-311 S |
| | 8303090061 | 50-354 S |
| | 8303090175 | 50-272 S |
| | 8303090178 | 50-272 V |
| | 8303090178 | 50-272 V |
| | 8303090185* | 50-272 S |
| | 8303090215 | 50-311 S |
| | 8303090225* | 50-311 S |
| | 8303090238 | 50-272 S |
| | 8303090247* | 50-272 S |
| | 8303100308 | 50-311 P |
| | 8303100368 | 71-9151 |
| | 8303110017* | 50-272 S |
| | 8303110021* | 50-272 S |
| | 8303110031* | 50-272 G |
| | 8303110304 | 50-272 S |
| | 8303140238 | 50-311 S |
| | 8303140242 | 50-311 S |
| | 8303140243* | 50-311 S |
| | 8303140245* | 50-311 S |
| | 8303140274 | 50-354 A |
| | 8303140280* | 50-354 A |
| | 8303140347 | 50-311 S |
| | 8303140361* | 50-311 S |
| | 8303140386 | 50-354 S |
| | 8303140438 | 50-272 G |
| | 8303140438 | 50-272 G |
| | 8303140545 | 50-272 S |
| | 8303140568* | 50-272 S |
| | 8303140574 | 50-354 G |
| | 8303140576 | 50-272 S |
| | 8303140583* | 50-272 S |
| | 8303140621* | 50-272 G |
| | 8303150284 | 50-272 R |
| | 8303150284 | 50-272 R |
| | 8303150290* | 50-272 R |
| | 8303150290* | 50-272 R |
| | 8303150646* | 50-272 S |
| | 8303150646* | 50-272 S |
| | 8303160234 | 50-272 S |
| | 8303160487 | 50-354 A |
| | 8303160539 | 50-272 P |
| | 8303170122 | 50-272 S |
| | 8303170169* | 50-171 I |
| | 8303170250 | 50-272 G |
| | 8303170250 | 50-272 G |
| | 8303170494 | 50-272 R |
| | 8303170499* | 50-272 R |
| | 8303180305 | 50-272 S |
| | 8303180314* | 50-272 S |
| | 8303180319 | 50-272 S |
| | 8303180324* | 50-272 S |
| | 8303180361 | 50-272 S |
| | 8303180368* | 50-272 S |
| | 8303180419 | 50-272 S |
| | 8303180420* | 50-272 S |
| | 8303180423 | 50-272 S |
| | 8303180425* | 50-272 S |
| | 8303210522 | 50-272 S |
| | 8303210530* | 50-272 S |
| | 8303210627 | 50-272 S |
| | 8303210633* | 50-272 S |
| | 8303230255 | 50-354 H |
| | 8303250082 | 50-272 G |
| | 8303250082 | 50-272 G |
| | 8303280279 | 50-272 R |
| | 8303280279 | 50-272 R |
| | 8303280286* | 50-272 R |
| | 8303290437 | 50-272 F |
| | 8303300473* | 50-272 G |
| | 8303300477* | 50-272 G |
| Puget Sound Power & Light Co. | 8303010308 | 50-522 A |
| Putnam County, NY | 8303030350* | 50-247 H |
| R.E. Williams & Associates, Inc. | 8303090027 | 40-8584 |
| | 8303090033 | 40-8745 |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303090595 | 40-8743 |
| R.F. Reedy, Inc. | 8303090304 | 50-275 R |
| | 8303240409 | 50-275 R |
| Reactor Experiments, Inc. | 8303040081 | XPORTLIC |
| | 8303180105 | XPORTLIC |
| | 8303180607 | XPORTLIC |
| | 8303240322 | XPORTLIC |
| | 8303280334 | XPORTLIC |
| Reactor Safety Co. (Germany GRS) | 83031405994 | MISC |
| Reedy, Herbert, Gibbons & Associates | 8303090259 | 50-275 R |
| Reid & Priest | 8303290449* | 50-443 G |
| Rensselaer Polytechnic Inst. | 8303240483 | 50-225 R |
| Research Triangle Institute | 8303010294* | MISC |
| | 8303010300* | MISC |
| Reuter-Stokes, Inc. | 8303230004 | XPORTLIC |
| | 8303230347 | XPORTLIC |
| | 8303290048 | XPORTLIC |
| | 8303300714 | XPORTLIC |
| | 8303300716 | XPORTLIC |
| | 8303310614 | XPORTLIC |
| Rhode Island, State of | 8303290481 | 50-193 R |
| Ridihalgh, Eggers & Associates | 8303070165* | QA999 |
| | 8303070171* | QA999 |
| | 8303070172* | QA999 |
| Rio Algom, Ltd. | 8303090605 | 40-8084 |
| | 8303100056 | 40-8084 |
| Robert L. Cloud Associates, Inc. | 8303020102 | 50-275 P |
| | 8303020109* | 50-275 P |
| | 8303100229 | 50-275 P |
| | 8303100235* | 50-275 P |
| | 8303160337 | 50-275 R |
| | 8303160342* | 50-275 R |
| | 8303170118 | 50-275 R |
| Rochester Gas & Electric Corp. | 8303010365 | 50-244 S |
| | 8303010372* | 50-244 S |
| | 8303010388 | 50-244 P |
| | 8303010391* | 50-244 P |
| | 8303010462 | 50-244 S |
| | 8303010470* | 50-244 S |
| | 8303010478 | 50-244 S |
| | 8303010487* | 50-244 S |
| | 8303040342 | 50-244 S |
| | 8303080333 | 50-244 P |
| | 8303080460 | 50-244 P |
| | 8303090072 | 50-244 P |
| | 8303090074* | 50-244 P |
| | 8303100287* | 50-244 Q |
| | 8303100302* | 50-244 Q |
| | 8303100398* | 50-244 Q |
| | 8303110217 | 50-244 Q |
| | 8303110316 | 50-244 P |
| | 8303110320* | 50-244 P |
| | 8303110338 | 50-244 P |
| | 8303140426 | 50-244 R |
| | 8303140434* | 50-244 R |
| | 8303140441* | 50-244 R |
| | 8303150516 | 50-244 R |
| | 8303150519* | 50-244 R |
| | 8303170161 | 50-244 P |
| | 8303220003 | 50-244 P |
| | 8303230232 | 50-244 P |
| | 8303230244 | 50-244 P |
| | 8303290470 | 50-244 P |
| | 8303310048* | 50-244 F |
| | 8303310054* | 50-244 F |
| Rockland Citizens for Safe Energy | 8303030433 | 50-247 Q |
| Rockland County, NY | 8303020093 | 50-247 T |
| | 8303020093 | 50-247 T |
| | 8303020096* | 50-247 T |
| | 8303020096* | 50-247 T |
| | 8303020100* | 50-247 T |
| | 8303020100* | 50-247 T |
| | 8303020105* | 50-247 T |
| | 8303020105* | 50-247 T |
| | 8303020110* | 50-247 T |
| | 8303020110* | 50-247 T |
| | 8303020116* | 50-247 T |
| | 8303020116* | 50-247 T |
| | 8303020120* | 50-247 T |
| | 8303020120* | 50-247 T |
| | 8303020124* | 50-247 T |
| | 8303020124* | 50-247 T |
| | 8303020126* | 50-247 T |
| | 8303020126* | 50-247 T |
| | 8303020130* | 50-247 T |
| | 8303020130* | 50-247 T |
| | 8303020133* | 50-247 T |
| | 8303020133* | 50-247 T |
| | 8303090287 | 50-247 Q |
| | 8303090287 | 50-247 Q |
| | 8303090293 | 50-247 Q |
| | 8303090293 | 50-247 Q |
| | 8303100261 | 50-247 Q |
| | 8303240601 | 50-247 Q |
| Rockwell International Corp. | 8303030520 | MISC |
| Rolf Jensen & Associates, Inc. | 83032902924 | CONTRACT |
| Rondout Associates | 8303180175 | ACRS |
| Ropes & Gray | 8302180118 | 50-443 Q |
| | 8303010078 | 50-443 Q |
| | 8303010078 | 50-443 Q |
| | 8303010082* | 50-443 Q |
| | 8303010082* | 50-443 Q |
| | 8303080082 | 50-443 Q |
| | 8303080082 | 50-443 Q |
| | 8303080089* | 50-443 Q |
| | 8303080089* | 50-443 Q |
| | 8303080106* | 50-443 Q |
| | 8303080106* | 50-443 Q |
| | 8303170422 | 50-443 Q |
| | 8303170422 | 50-443 Q |
| | 8303170426* | 50-443 Q |
| | 8303170426* | 50-443 Q |
| | 8303170430* | 50-443 Q |
| | 8303170437 | 50-443 Q |
| | 8303180151 | 50-443 Q |
| | 8303230191 | 50-443 Q |
| | 8303230191 | 50-443 Q |
| | 8303230199* | 50-443 Q |
| | 8303230199* | 50-443 Q |
| | 8303280242 | 50-293 P |
| | 8303290445 | 50-443 Q |
| | 8303290445 | 50-443 Q |
| | 8303290449* | 50-443 Q |
| | 8303290449* | 50-443 Q |
| Rothschild, G.E. | 8303040312 | 50-458 Q |
| Rye, NH | 8303140575* | 50-443 Q |
| SIMCO Groundwater Association | 8303150130 | NUREG |
| Sacramento Municipal Utility District | 8303010382 | 50-312 H |
| | 8303010423 | 50-312 P |
| | 8303080509* | 50-312 Q |
| | 8303090435* | 50-312 F |
| | 8303090440* | 50-312 F |
| | 8303110099 | 50-312 P |
| | 8303110149 | 50-312 S |
| | 8303110160* | 50-312 S |
| | 8303110237 | 50-312 Q |
| | 8303110264 | 50-312 F |
| | 8303110277 | 50-312 H |
| | 8303110311 | 50-312 S |
| | 8303110318* | 50-312 S |
| | 8303110354 | 50-312 S |
| | 8303110357 | 50-312 S |
| | 8303110361* | 50-312 S |
| | 8303110364* | 50-312 S |
| | 8303140056 | 50-312 P |
| | 8303150238 | 50-312 F |
| | 8303150342 | 50-312 R |
| | 8303150346* | 50-312 R |
| | 8303220171 | 50-312 P |
| | 8303250018 | 50-312 Q |
| | 8303290344 | 50-312 J |
| | 8303290436 | 50-312 P |
| | 8303290471 | 50-312 P |
| | 8303300225 | 50-312 R |
| | 8303300233* | 50-312 R |
| Safeguards International, Inc. | 8303240426 | 50-400 Q |
| San Diego Gas & Electric Co. | 8303090288* | 50-206 P |
| San Diego Univ. of. | 8303020001 | 50-201 P |
| Sanders & McDermott | 8303230219 | 50-443 Q |
| | 8303230219 | 50-443 Q |
| | 8303230221 | 50-443 Q |
| | 8303230221 | 50-443 Q |
| | 8303250163 | 50-443 Q |
| Sandia Laboratories | 8303040572* | QA999 |
| | 8303100460 | NUREG |
| | 8303100556 | NUREG |
| | 8303150130 | NUREG |
| | 8303160614 | NUREG |
| | 8303220429 | NUREG |
| | 8303230413 | NUREG |

# CORPORATE SOURCE INDEX

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303290570* | WASTE MGT |
| | 8303290677 | NUREG |
| | 8303290689 | NUREG |
| | 8303290742* | WASTE MGT |
| | 8303300514 | NUREG |
| | 8303300527 | NUREG |
| Sandvik Special Metals Corp. | 8303150695 | XPORTLIC |
| Santa Monica, CA | 8303180413 | 50-142 G |
| Sargent & Lundy, Inc. | 8303010298 | TOPREP |
| | 8303080098 | 50-454 T |
| | 8303080098 | 50-454 T |
| | 8303080216 | 50-454 T |
| | 8303080216 | 50-454 T |
| | 8303150470* | GA999 |
| Savannah River Laboratory | 8303110597 | RES |
| Saxton Nuclear Experimental Corp. | 8303010286 | 50-146 J |
| | 8303030110 | 50-146 I |
| | 8303090276 | 50-146 S |
| Schiff, Hardin & Waite | 8303150402 | 50-461 G |
| Science Applications, Inc. | 8208260154* | 50-315 P |
| | 8208310332* | 50-277 P |
| | 8303220106 | 50-537 A |
| | 8303230282 | NUREG |
| | 8303290336* | CONTRACT |
| Seacoast Anti-Pollution League | 8303180323 | 50-443 G |
| | 8303180323 | 50-443 G |
| | 8303180329* | 50-443 G |
| | 8303180329* | 50-443 G |
| | 8303230212 | 50-443 G |
| | 8303230216* | 50-443 G |
| | 8303250164 | 50-443 G |
| Senate | 8302100333* | PR |
| | 8303040125* | 50-309 S |
| | 8303090177* | 50-309 U |
| | 8303140011* | 50-346 H |
| Senate, Environment & Public Works | 8303160721* | COMMISSION |
| Sensible Maine Power | 8303220214 | 50-309 G |
| | 8303220218 | 50-309 G |
| Separative Work Unit Corp. | 8303280113 | XPORTLIC |
| Shaw, Pittman, Potts & Trowbridge | 8302100345 | PRM |
| | 8303010046 | 40-2061 |
| | 8303010070* | 40-2061 |
| | 8303010263 | 50-440 G |
| | 8303010263 | 50-440 G |
| | 8303010516 | 50-440 G |
| | 8303010516 | 50-440 G |
| | 8303020101 | 40-2061 |
| | 8303070068 | 50-440 G |
| | 8303070068 | 50-440 G |
| | 8303070076 | 50-440 G |
| | 8303070076 | 50-440 G |
| | 8303070083 | 50-289 G |
| | 8303070093 | 50-289 G |
| | 8303080459 | 50-289 G |
| | 8303100391 | FOIA |
| | 8303100408 | 50-440 G |
| | 8303100408 | 50-440 G |
| | 8303110204 | 50-440 G |
| | 8303110204 | 50-440 G |
| | 8303110209 | 50-400 G |
| | 8303110209 | 50-400 G |
| | 8303110211 | 50-400 G |
| | 8303110211 | 50-400 G |
| | 8303140252 | 50-400 G |
| | 8303140252 | 50-400 G |
| | 8303140258* | 50-400 G |
| | 8303140258* | 50-400 G |
| | 8303140262* | 50-400 G |
| | 8303140262* | 50-400 G |
| | 8303140266* | 50-400 G |
| | 8303140266* | 50-400 G |
| | 8303150597 | 50-400 G |
| | 8303170423 | 50-382 G |
| | 8303170427* | 50-382 G |
| | 8303170431 | 50-289 G |
| | 8303170438 | 50-440 G |
| | 8303170438 | 50-440 G |
| | 8303170452 | 50-440 G |
| | 8303170475 | 50-261 G |
| | 8303170488 | 50-261 G |
| | 8303170496* | 50-261 G |
| | 8303[illegible] | 50-440 G |
| | 8303[illegible] | 50-440 G |
| | 8303[illegible] | 50-382 G |
| | 8303[illegible] | 50-382 T |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303220405* | 40-2061 |
| | 8303230186 | 50-400 G |
| | 8303250141 | 50-382 G |
| | 8303250160 | 50-400 G |
| | 8303290464 | 50-382 G |
| | 8303290506 | 50-400 G |
| Sheboygan Memorial Hosp., Sheboygan, WI | 8104070367* | FOIA |
| Shoreham Opponents Coalition | 8303010408 | 50-322 G |
| | 8303220241 | 50-322 G |
| Sierra Club | 8303220212 | 50-537 G |
| | 8303220221* | 50-537 G |
| | 8303230203 | 50-537 H |
| | 8303250165 | 50-537 G |
| | 8303290411 | 50-537 G |
| Sigma Chemical Co. | 8303030489 | XPORTLIC |
| | 8303040049 | XPORTLIC |
| | 8303040064 | XPORTLIC |
| | 8303040140 | XPORTLIC |
| | 8303040168 | XPORTLIC |
| | 8303180173 | XPORTLIC |
| | 8303290071 | XPORTLIC |
| Silver King Mines, Inc. | 8303110586 | 40-8602 |
| | 8303110598* | 40-8602 |
| | 8303140646 | 40-8602 |
| | 8303140650* | 40-8602 |
| Sinclair, M. | 8303230243 | 50-329 T |
| | 8303230243 | 50-329 T |
| | 8303230248* | 50-329 T |
| | 8303230248* | 50-329 T |
| Sinnissippi Alliance for the Environment (SAFE) | 8303070034 | 50-454 T |
| | 8303070034 | 50-454 T |
| | 8303070049* | 50-454 T |
| | 8303070054* | 50-454 T |
| | 8303070155 | 50-454 G |
| | 8303070155 | 50-454 G |
| | 8303090142 | 50-454 T |
| | 8303220198* | 50-454 T |
| | 8303300409 | 50-454 T |
| | 8303300409 | 50-454 T |
| | 8303300431* | 50-454 T |
| | 8303300431* | 50-454 T |
| Small Business Administration | 8303030231* | CONTRACT |
| | 8303030766* | CONTRACT |
| | 8303090433* | CONTRACT |
| | 8303150171* | CONTRACT |
| | 8303150360* | CONTRACT |
| | 8303300677* | CONTRACT |
| | 8303310067* | 50-537 A |
| Snell & Wilmer | 8303100268 | 50-528 G |
| | 8303140462 | 50-528 G |
| | 8303140462 | 50-528 G |
| | 8303140472* | 50-528 G |
| | 8303220257 | 50-528 G |
| Society of Nuclear Medicine | 8303090124 | FOIA |
| Solidstate Controls, Inc. | 8303030538* | GA999 |
| | 8303030547* | GA999 |
| Somervell County, TX | 8303100256 | 50-445 G |
| South Carolina Electric & Gas Co. | 8302010466 | 50-395 G |
| | 8302280081 | 50-395 F |
| | 8302280085* | 50-395 F |
| | 8303010175 | 50-395 G |
| | 8303010204 | 50-395 S |
| | 8303010222* | 50-395 S |
| | 8303010283 | 50-395 S |
| | 8303010291* | 50-395 S |
| | 8303010449 | 50-395 S |
| | 8303010457* | 50-395 S |
| | 8303010461 | 50-395 S |
| | 8303010474* | 50-395 S |
| | 8303010495 | 50-395 S |
| | 8303010507* | 50-395 S |
| | 8303010556 | 50-395 S |
| | 8303010566* | 50-395 S |
| | 8303040367 | 50-395 S |
| | 8303040376* | 50-395 S |
| | 8303040553 | 50-395 S |
| | 8303040565* | 50-395 S |
| | 8303080005 | 50-395 P |
| | 8303080463 | 50-395 P |
| | 8303080468* | 50-395 P |
| | 8303100091* | 50-395 F |
| | 8303100094* | 50-395 F |
| | 8303110035 | 50-395 P |
| | 8303110341 | 50-395 R |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303150154 | 50-395 P |
| | 8303150341 | 50-395 S |
| | 8303150347* | 50-395 S |
| | 8303160237 | 50-395 P |
| | 8303180229 | 50-395 S |
| | 8303180234* | 50-395 S |
| | 8303180238 | 50-395 S |
| | 8303180241* | 50-395 S |
| | 8303180258 | 50-395 S |
| | 8303180268* | 50-395 S |
| | 8303210345 | 50-395 Q |
| | 8303210394 | 50-395 Q |
| | 8303210400 | 50-395 Q |
| | 8303210521* | 50-395 Q |
| | 8303210659 | 50-395 Q |
| | 8303210726* | 50-395 Q |
| | 8303220135 | 50-395 P |
| | 8303240530 | 50-395 S |
| | 8303240539* | 50-395 S |
| | 8303240583 | 50-395 S |
| | 8303240585 | 50-395 S |
| | 8303240592* | 50-395 S |
| | 8303240595* | 50-395 S |
| | 8303240596 | 50-395 S |
| | 8303240600* | 50-395 S |
| | 8303280100 | 50-395 Q |
| | 8303280117 | 50-395 J |
| South Carolina, State of | 8303040185* | COMMISSION |
| | 8303180584* | WASTE MGT |
| South Carolina, Univ. of | 8303110343* | 50-395 R |
| South Hampton, NH | 8303220219 | 50-443 Q |
| Southampton, NY | 8303230260 | 50-322 Q |
| Southern California Edison Co. | 8302150674 | 50-361 S |
| | 8302150685* | 50-361 S |
| | 8303020034 | 50-361 P |
| | 8303020034 | 50-361 P |
| | 8303020098 | PRM |
| | 8303040502 | 50-361 S |
| | 8303040516 | 50-362 A |
| | 8303040520 | 50-362 S |
| | 8303040525 | 50-361 P |
| | 8303040525 | 50-361 P |
| | 8303040526* | 50-362 S |
| | 8303040567 | 50-362 S |
| | 8303040573* | 50-362 S |
| | 8303040577 | 50-362 S |
| | 8303040589* | 50-362 S |
| | 8303040602 | 50-362 S |
| | 8303040608 | 50-362 S |
| | 8303040615* | 50-362 S |
| | 8303040616* | 50-362 S |
| | 8303040618 | 50-361 S |
| | 8303040624* | 50-361 S |
| | 8303040629 | 50-361 S |
| | 8303040636* | 50-361 S |
| | 8303070009 | 50-206 Q |
| | 8303070018 | 50-206 P |
| | 8303070020 | 50-206 P |
| | 8303070039 | 50-206 V |
| | 8303070039 | 50-206 V |
| | 8303070055 | 50-361 Q |
| | 8303070055 | 50-361 Q |
| | 8303070064 | 50-206 P |
| | 8303070073 | 50-206 P |
| | 8303070079 | 50-206 P |
| | 8303070084 | 50-206 P |
| | 8303070102 | 50-206 P |
| | 8303080095 | 50-361 R |
| | 8303080095 | 50-361 R |
| | 8303080097* | 50-361 R |
| | 8303080097* | 50-361 R |
| | 8303080156 | 50-206 R |
| | 8303080161* | 50-206 R |
| | 8303080192 | 50-361 P |
| | 8303080261 | 50-206 P |
| | 8303090151 | 50-361 P |
| | 8303090151 | 50-361 P |
| | 8303090282 | 50-206 P |
| | 8303090288* | 50-206 P |
| | 8303090296* | 50-206 P |
| | 8303100272 | 50-206 Q |
| | 8303100346 | 50-361 Q |
| | 8303100346 | 50-361 Q |
| | 8303110080 | 50-362 S |
| | 8303110092* | 50-362 S |
| | 8303110113 | 50-362 S |
| | 8303110115 | 50-361 S |
| | 8303110125* | 50-362 S |
| | 8303110134* | 50-362 S |
| | 8303110142* | 50-361 S |
| | 8303110188 | 50-362 S |
| | 8303110191* | 50-362 S |
| | 8303110201 | 50-362 S |
| | 8303110208* | 50-362 S |
| | 8303110224 | 50-362 S |
| | 8303110225 | 50-361 S |
| | 8303110230* | 50-361 S |
| | 8303110239 | 50-362 S |
| | 8303110258 | 50-361 S |
| | 8303110267 | 50-361 S |
| | 8303110273* | 50-361 S |
| | 8303110305 | 50-362 S |
| | 8303110325* | 50-362 S |
| | 8303110333 | 50-362 S |
| | 8303110337* | 50-362 S |
| | 8303110342* | 50-362 S |
| | 8303110347 | 50-362 S |
| | 8303110349* | 50-362 S |
| | 8303150477 | 50-206 P |
| | 8303150566 | 50-361 R |
| | 8303150566 | 50-361 R |
| | 8303150574* | 50-361 R |
| | 8303150574* | 50-361 R |
| | 8303150584 | 50-206 P |
| | 8303150589 | 50-206 R |
| | 8303150591* | 50-206 R |
| | 8303150592* | 50-361 R |
| | 8303180040 | 50-361 P |
| | 8303180265 | 50-361 S |
| | 8303180272* | 50-361 S |
| | 8303180428 | 50-362 S |
| | 8303180435 | 50-362 S |
| | 8303180443* | 50-362 S |
| | 8303180481 | 50-361 S |
| | 8303180486 | 50-362 S |
| | 8303180487* | 50-361 S |
| | 8303180495* | 50-362 S |
| | 8303180501 | 50-362 S |
| | 8303180520 | 50-361 S |
| | 8303180525* | 50-361 S |
| | 8303210107 | 50-206 P |
| | 8303210642 | 50-361 P |
| | 8303210642 | 50-361 P |
| | 8303210652* | 50-361 P |
| | 8303210652* | 50-361 P |
| | 8303210657* | 50-361 P |
| | 8303210667* | 50-361 P |
| | 8303210667* | 50-361 P |
| | 8303210680* | 50-361 P |
| | 8303210680* | 50-361 P |
| | 8303210688* | 50-361 P |
| | 8303210688* | 50-361 P |
| | 8303210696* | 50-361 P |
| | 8303210696* | 50-361 P |
| | 8303210704* | 50-361 P |
| | 8303210704* | 50-361 P |
| | 8303210720* | 50-361 P |
| | 8303210720* | 50-361 P |
| | 8303210741* | 50-361 P |
| | 8303210749* | 50-361 P |
| | 8303210749* | 50-361 P |
| | 8303210760* | 50-361 P |
| | 8303210762* | 50-361 P |
| | 8303210767* | 50-361 P |
| | 8303220001 | 50-206 P |
| | 8303220006* | 50-206 P |
| | 8303220085 | 50-206 Q |
| | 8303220353 | TOPREP |
| | 8303240012 | 50-361 P |
| | 8303240016 | 50-361 Q |
| | 8303240214 | 50-206 P |
| | 8303240214 | 50-206 P |
| | 8303240214 | 50-206 P |
| | 8303250012 | 50-206 F |
| | 8303250012 | 50-206 F |
| | 8303250012 | 50-206 F |
| | 8303250029 | 50-206 F |
| | 8303250029 | 50-206 F |
| | 8303250029 | 50-206 F |
| | 8303250087 | 50-206 P |

# CORPORATE SOURCE INDEX

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303250097 | 50-206 P |
| | 8303280010 | 50-206 P |
| | 8303290067 | 50-362 S |
| | 8303290072* | 50-362 S |
| | 8303290202 | 50-362 S |
| | 8303290212* | 50-362 S |
| | 8303290216 | 50-362 S |
| | 8303290221* | 50-362 S |
| | 8303290225 | 50-362 S |
| | 8303290233* | 50-362 S |
| | 8303290277 | 50-361 S |
| | 8303290277 | 50-361 S |
| | 8303290286* | 50-361 S |
| | 8303290321 | 50-362 S |
| | 8303290326* | 50-362 S |
| | 8303290329 | 50-362 S |
| | 8303290335* | 50-362 S |
| | 8303290376 | 50-361 S |
| | 8303290376 | 50-361 S |
| | 8303290492 | 50-361 S |
| | 8303290494* | 50-361 S |
| | 8303290527 | 50-358 G |
| | 8303300232* | 50-206 F |
| | 8303300232* | 50-206 F |
| | 8303300232* | 50-206 F |
| | 8303300239* | 50-206 F |
| | 8303300239* | 50-206 F |
| | 8303310299 | 50-361 P |
| Southern Co. Services, Inc. | 8303210348 | 50-424 G |
| Southern Interstate Nuclear Board | 8303290425* | CONTRACT |
| Southern Science Applications, Inc. | 8303290001 | 70-2926 |
| Southwest Fabricating & Welding Co. (subs. of IU International Corp.) | 8303210492* | QA999 |
| Southwest Research Institute | 8303240558 | MISC |
| | 8303290606* | TOPREP |
| | 8303290613* | TOPREP |
| | 8303290631* | TOPREP |
| Soyland Power Cooperative, Inc. | 8303230271* | 50-461 I |
| Spiegel & McDiarmid | 8303070109 | PROJ |
| St. Anthony Hosp., Milwaukee, WI | 8112010615* | FOIA |
| St. Elizabeth Hosp., Appleton, WI | 8201060494* | FOIA |
| St. Joseph's Hosp., Milwaukee, WI | 8303240129* | FOIA |
| | 8303240172* | FOIA |
| St. Joseph's Hosp., Marshfield, WI | 8108210490* | FOIA |
| St. Lukes Hosp., Milwaukee, WI | 8108210338* | FOIA |
| | 8201200538* | FOIA |
| St. Mary's Hosp., Madison, WI | 8110150356* | FOIA |
| | 8303240166* | FOIA |
| St. Michael Hosp., Milwaukee, WI | 8108210447* | FOIA |
| St. Vincent Hosp., Green Bay, WI | 8201270341* | FOIA |
| | 8303240148* | FOIA |
| Stamiris, B. | 8303100059 | 50-330 G |
| | 8303100225* | 50-329 G |
| Stan A. Huber Consultants, Inc. | 8303030204 | FOIA |
| Standardized Nuclear Unit Power Plant System | 8303040524 | 50-482 A |
| | 8303140287 | 50-482 E |
| | 8303140287 | 50-482 E |
| | 8303140287 | 50-482 E |
| | 8303140294* | 50-482 E |
| | 8303140294* | 50-482 E |
| | 8303140294* | 50-482 E |
| | 8303150390 | 50-482 S |
| | 8303150390 | 50-482 S |
| | 8303150390 | 50-482 S |
| | 8303150442 | 50-482 S |
| | 8303150442 | 50-482 S |
| | 8303150442 | 50-482 S |
| | 8303150503 | 50-482 K |
| | A303150503 | 50-482 K |
| | J303150503 | 50-482 K |
| | 8303150513* | 50-482 K |
| | 8303280022 | 50-482 A |
| | 8303290394 | 50-482 S |
| State, Dept. of, Bureau of Oceans & Intl Environ & Scient. Affairs | 8303040022 | XPORTLIC |
| | 8303160640 | XPORTLIC |
| | 8303240331 | XPORTLIC |
| | 8303290227 | XPORTLIC |
| State, Dept. of | 8303290140 | XPORTLIC |
| Stevenson & Associates | 8303280061 | NUREG |
| | 8303300597 | NUREG |
| Stone & Webster Engineering Corp. | 8302100345 | PRM |
| | 8303020092 | REGOD |
| | 8303020095 | NUREG |
| | 8303040646* | 50-275 P |
| | 8303080280 | 50-275 P |
| | 8303080285* | 50-275 P |
| | 8303090112* | 50-275 P |
| | 8303160650* | ACRS |
| | 8303210155* | 50-322 A |
| | 8303220067 | 50-275 R |
| | 8303220074 | 50-275 R |
| | 8303230054 | 50-275 R |
| | 8303230059* | 50-275 R |
| Stone & Webster, Inc. | 8303220169 | 50-329 A |
| Stuart, Zavin & Sinnreich | 8303090353 | FOIA |
| Suffolk County, NY | 8303080054 | 50-322 G |
| | 8303100286 | 50-322 G |
| | 8303250157 | 50-322 T |
| | 8303290190 | 50-322 G |
| | 8303300346 | 50-322 G |
| | 8303310224 | 50-322 G |
| | 8303310269 | 50-322 G |
| | 8303310278* | 50-322 G |
| Sugarman, R.J. | 8303140352 | 50-352 G |
| | 8303140352 | 50-352 G |
| | 8303140356* | 50-352 G |
| | 8303140356* | 50-352 G |
| | 8303250167 | 50-352 G |
| System Architects, Inc. | 8303090433* | CONTRACT |
| TERA Corp. | 8303030789* | 50-329 A |
| | 8303030792* | 50-329 A |
| | 8303040024* | 50-329 A |
| | 8303040024* | 50-329 A |
| | 8303040032* | 50-329 A |
| | 8303040032* | 50-329 A |
| | 8303040041* | 50-329 A |
| | 8303210448 | 50-329 A |
| | 8303210448 | 50-329 A |
| | 8303210685 | 50-329 A |
| | 8303210685 | 50-329 A |
| Technology Development of California Inc. | 8303030231* | CONTRACT |
| Teknekron Research, Inc. | 8303310366 | NUREG |
| Teledyne Engineering Services | 8303020109* | 50-275 P |
| | 8303020147 | 50-275 P |
| | 8303030559 | 50-387 P |
| | 8303030596 | 50-322 A |
| | 8303080466 | 50-322 A |
| | 8303090171 | 50-322 A |
| | 8303090335 | 50-275 R |
| | 8303090372 | 50-275 P |
| | 8303090384 | 50-275 R |
| | 8303090388* | 50-275 R |
| | 8303150210 | 50-322 A |
| | 8303180409 | 50-322 A |
| | 8303240419 | 50-275 P |
| | 8303290002 | 50-275 R |
| | 8303290004* | 50-275 R |
| | 8303290469 | 50-275 R |
| Teledyne Isotopes | 8303140450* | 70-124 |
| Tennelec, Inc. | 8303020177* | CONTRACT |
| Tennessee Valley Authority | 8302280512 | 50-390 A |
| | 8303010198 | 50-390 S |
| | 8303010198 | 50-390 S |
| | 8303010207 | 50-390 S |
| | 8303010207 | 50-390 S |
| | 8303010252 | 50-390 G |
| | 8303010252 | 50-390 G |
| | 8303010255 | 50-390 G |
| | 8303010258 | 50-390 G |
| | 8303010262 | 50-390 G |
| | 8303010284 | 50-327 G |
| | 8303010293 | 50-259 G |
| | 8303010303 | 50-438 G |
| | 8303010369 | 50-518 A |
| | 8303010369 | 50-518 A |
| | 8303010399 | 50-327 G |
| | 8303010399 | 50-327 G |
| | 8303010428 | 50-259 G |
| | 8303010433* | 50-327 G |
| | 8303010448 | 50-259 G |
| | 8303010467 | 50-438 G |
| | 8303010563 | 50-438 G |
| | 8303010586 | 50-390 S |
| | 8303010586 | 50-390 S |
| | 8303020340 | 70-2917 |
| | 8303020376 | 70-2910 |
| | 8303040341 | 50-259 P |
| | 8303040341 | 50-259 P |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY | |
|---|---|---|---|
| | 8303040341 | 50-259 | P |
| | 8303040352 | 50-438 | S |
| | 8303040352 | 50-438 | S |
| | 8303040374 | 50-296 | S |
| | 8303040381 | 50-296 | S |
| | 8303040384 | 50-438 | S |
| | 8303040384 | 50-438 | S |
| | 8303040389* | 50-296 | S |
| | 8303040395* | 50-296 | S |
| | 8303040426 | 50-260 | S |
| | 8303040433* | 50-260 | S |
| | 8303040434 | 50-328 | S |
| | 8303040438* | 50-328 | S |
| | 8303040465 | 50-328 | S |
| | 8303040472* | 50-328 | S |
| | 8303040492 | 50-259 | S |
| | 8303040497* | 50-259 | S |
| | 8303040542 | 50-438 | S |
| | 8303040542 | 50-438 | S |
| | 8303040545 | 50-390 | S |
| | 8303040545 | 50-390 | S |
| | 8303040558 | 50-259 | S |
| | 8303040559 | 50-390 | S |
| | 8303040559 | 50-390 | S |
| | 8303040561 | 50-438 | S |
| | 8303040561 | 50-438 | S |
| | 8303040569* | 50-259 | S |
| | 8303040575 | 50-328 | S |
| | 8303040588* | 50-328 | S |
| | 8303040603 | 50-390 | S |
| | 8303040603 | 50-390 | S |
| | 8303040609 | 50-390 | A |
| | 8303040609 | 50-390 | A |
| | 8303040613 | 50-390 | S |
| | 8303040613 | 50-390 | S |
| | 8303040617 | 50-390 | S |
| | 8303040617 | 50-390 | S |
| | 8303040630 | 50-390 | S |
| | 8303040630 | 50-390 | S |
| | 8303040632 | 50-438 | S |
| | 8303040632 | 50-438 | S |
| | 8303080016 | 50-259 | R |
| | 8303080021* | 50-259 | R |
| | 8303080368 | 50-327 | R |
| | 8303080377* | 50-327 | R |
| | 8303080442 | 50-259 | V |
| | 8303080442 | 50-259 | V |
| | 8303080442 | 50-259 | V |
| | 8303080442 | 50-259 | V |
| | 8303080442 | 50-259 | V |
| | 8303080442 | 50-259 | V |
| | 8303080442 | 50-259 | V |
| | 8303080442 | 50-259 | V |
| | 8303090216 | 50-327 | R |
| | 8303090216 | 50-327 | R |
| | 8303090220* | 50-327 | R |
| | 8303090220* | 50-327 | R |
| | 8303090343 | 50-327 | P |
| | 8303090343 | 50-327 | P |
| | 8303100043* | 50-327 | F |
| | 8303100046* | 50-327 | F |
| | 8303100049* | 50-327 | F |
| | 8303100053* | 50-327 | F |
| | 8303100295 | 50-259 | P |
| | 8303100295 | 50-259 | P |
| | 8303100326 | 50-327 | R |
| | 8303100326 | 50-327 | R |
| | 8303100331* | 50-327 | R |
| | 8303100331* | 50-327 | R |
| | 8303110375 | 50-327 | S |
| | 8303140036 | 50-259 | P |
| | 8303140234 | 50-327 | P |
| | 8303140418 | 50-390 | S |
| | 8303140418 | 50-390 | S |
| | 8303140422 | 50-390 | S |
| | 8303140430 | 50-438 | S |
| | 8303140492 | 50-327 | S |
| | 8303140501* | 50-327 | S |
| | 8303140509 | 50-260 | S |
| | 8303140520* | 50-260 | S |
| | 8303140526 | 50-327 | S |
| | 8303140539* | 50-327 | S |
| | 8303140548 | 50-327 | S |
| | 8303140554* | 50-327 | S |
| | 8303140601 | 50-259 | S |
| | 8303140604* | 50-259 | S |
| | 8303150185 | 50-259 | S |
| | 8303150193* | 50-259 | S |
| | 8303150200 | 50-390 | S |
| | 8303150200 | 50-390 | S |
| | 8303150248 | 50-296 | S |
| | 8303150263* | 50-296 | S |
| | 8303150297 | 50-296 | S |
| | 8303150300 | 50-259 | S |
| | 8303150306* | 50-259 | S |
| | 8303150309* | 50-296 | S |
| | 8303150440 | 50-327 | R |
| | 8303150445* | 50-327 | R |
| | 8303150463 | 50-327 | R |
| | 8303150463 | 50-327 | R |
| | 8303150464* | 50-327 | R |
| | 8303150466 | 50-296 | S |
| | 8303150467* | 50-296 | S |
| | 8303150472 | 50-327 | S |
| | 8303150475* | 50-327 | S |
| | 8303150490 | 50-259 | R |
| | 8303150496* | 50-259 | R |
| | 8303160216 | 50-259 | R |
| | 8303160216 | 50-259 | R |
| | 8303160216 | 50-259 | R |
| | 8303160216 | 50-259 | R |
| | 8303160293 | 50-438 | A |
| | 8303160293 | 50-438 | A |
| | 8303160419 | 50-260 | S |
| | 8303160423* | 50-260 | S |
| | 8303160432 | 50-296 | S |
| | 8303160438* | 50-296 | S |
| | 8303160450 | 50-390 | S |
| | 8303160450 | 50-390 | S |
| | 8303160531 | 50-296 | S |
| | 8303160536* | 50-296 | S |
| | 8303160613 | 40-1341 | |
| | 8303170463 | 50-259 | R |
| | 8303170467* | 50-259 | R |
| | 8303180022 | 50-390 | S |
| | 8303180022 | 50-390 | S |
| | 8303180022 | 50-390 | S |
| | 8303180022 | 50-390 | S |
| | 8303180023 | 50-438 | S |
| | 8303180023 | 50-438 | S |
| | 8303180050 | 50-390 | S |
| | 8303180300 | 50-390 | S |
| | 8303180300 | 50-390 | S |
| | 8303180348 | 50-438 | S |
| | 8303180348 | 50-438 | S |
| | 8303180383 | 50-438 | S |
| | 8303180383 | 50-438 | S |
| | 8303180454 | 50-259 | P |
| | 8303180454 | 50-259 | P |
| | 8303180472 | 50-438 | S |
| | 8303180472 | 50-438 | S |
| | 8303180530 | 50-327 | P |
| | 8303180530 | 50-327 | P |
| | 8303180537* | 50-327 | P |
| | 8303180537* | 50-327 | P |
| | 8303210299 | 50-327 | S |
| | 8303210308* | 50-327 | S |
| | 8303210319 | 50-328 | S |
| | 8303210321* | 50-328 | S |
| | 8303210322 | 50-328 | S |
| | 8303210327* | 50-328 | S |
| | 8303210340 | 50-438 | R |
| | 8303210340 | 50-438 | R |
| | 8303210353* | 50-390 | G |
| | 8303210353* | 50-390 | G |
| | 8303210396 | 50-390 | S |
| | 8303210296 | 50-390 | S |
| | 8303210422* | 50-327 | G |
| | 8303210423 | 50-259 | S |
| | 8303210434* | 50-259 | S |
| | 8303210462 | 50-327 | S |
| | 8303210469* | 50-327 | S |
| | 8303210551 | 50-390 | G |
| | 8303210596 | 50-390 | S |
| | 8303210596 | 50-390 | S |
| | 8303210605 | 50-438 | S |
| | 8303210605 | 50-438 | S |
| | 8303210626 | 50-438 | S |
| | 8303210626 | 50-438 | S |
| | 8303210630 | 50-438 | S |

# CORPORATE SOURCE INDEX


| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303210634 | 50-438 S |
| | 8303210634 | 50-438 S |
| | 8303210679 | 50-390 S |
| | 8303210679 | 50-390 S |
| | 8303210765* | 50-259 G |
| | 8303220047 | 50-390 S |
| | 8303220047 | 50-390 S |
| | 8303220086 | 50-260 S |
| | 8303220097* | 50-260 S |
| | 8303220119 | 50-438 S |
| | 8303220119 | 50-438 S |
| | 8303220156 | 50-327 P |
| | 8303220156 | 50-327 P |
| | 8303220162 | 50-327 P |
| | 8303220162 | 50-327 P |
| | 8303220176 | 50-259 S |
| | 8303220179* | 50-259 S |
| | 8303220296 | 50-327 P |
| | 8303220296 | 50-327 P |
| | 8303220303* | 50-327 P |
| | 8303220303* | 50-327 P |
| | 8303220318 | 50-260 S |
| | 8303220324* | 50-260 S |
| | 8303220336 | 50-390 S |
| | 8303220336 | 50-390 S |
| | 8303220354 | 50-438 S |
| | 8303240359 | 50-391 S |
| | 8303240365 | 50-390 S |
| | 8303240365 | 50-390 S |
| | 8303240406 | 50-390 S |
| | 8303240406 | 50-390 S |
| | 8303240406 | 50-390 S |
| | 8303240406 | 50-390 S |
| | 8303240410 | 50-327 S |
| | 8303240412* | 50-327 S |
| | 8303240429 | 50-390 S |
| | 8303240429 | 50-390 S |
| | 8303240447 | 50-259 P |
| | 8303240447 | 50-259 P |
| | 8303240447 | 50-259 P |
| | 8303240470 | 50-328 S |
| | 8303240479* | 50-328 S |
| | 8303240525 | 50-390 S |
| | 8303240525 | 50-390 S |
| | 8303240525 | 50-390 S |
| | 8303240525 | 50-390 S |
| | 8303240551 | 50-390 S |
| | 8303240551 | 50-390 S |
| | 8303240598 | 50-259 S |
| | 8303240603 | 50-390 S |
| | 8303240603 | 50-390 S |
| | 8303240605* | 50-259 S |
| | 8303240606 | 50-296 S |
| | 8303240608* | 50-296 S |
| | 8303250038 | 50-519 A |
| | 8303250092 | 50-259 F |
| | 8303250092 | 50-259 F |
| | 8303250092 | 50-259 F |
| | 8303280023 | 50-328 P |
| | 8303280045 | 50-327 P |
| | 8303280045 | 50-327 P |
| | 8303290306 | 50-390 A |
| | 8303290317* | 50-390 A |
| | 8303290343 | 50-438 A |
| | 8303300125 | 50-327 P |
| | 8303300125 | 50-327 P |
| | 8303300131* | 50-327 P |
| | 8303300131* | 50-327 P |
| | 8303310028* | 50-327 F |
| | 8303310036* | 50-327 F |
| | 8303310036* | 50-327 F |
| | 8303310161 | 50-390 A |
| | 8303310161 | 50-390 A |
| | 8303310165* | 50-390 A |
| | 8303310165* | 50-390 A |
| | 8303310420 | 50-259 P |
| | 8303310420 | 50-259 P |
| | 8303310420 | 50-259 P |
| | 8303310424* | 50-259 P |
| | 8303310424* | 50-259 P |
| | 8303310427* | 50-259 P |
| Tennessee, State of | 8303300604* | CONTRACT |
| Texas A&M Univ., College Station, TX | 8303140212 | 50-59 H |
| | 8303150396 | 50-128 P |
| Texas Instruments, Inc | 8303010026 | 70-33 |
| | 8303010036* | 70-33 |
| Texas Utilities Generating Co | 8303010316 | 50-445 G |
| | 8303010316 | 50-445 G |
| | 8303010328* | 50-445 G |
| | 8303010333 | 50-445 G |
| | 8303010333 | 50-445 G |
| | 8303070122 | 50-445 G |
| | 8303070122 | 50-445 G |
| | 8303080024 | 50-445 G |
| | 8303080024 | 50-445 G |
| | 8303080063 | 50-445 S |
| | 8303080063 | 50-445 S |
| | 8303080188 | 50-445 S |
| | 8303080188 | 50-445 S |
| | 8303080334 | 50-445 S |
| | 8303080334 | 50-445 S |
| | 8303080378 | 50-445 S |
| | 8303080378 | 50-445 S |
| | 8303110215 | 50-445 A |
| | 8303180371 | 50-445 G |
| | 8303180406 | 50-445 G |
| | 8303220010 | 50-445 E |
| | 8303220010 | 50-445 E |
| | 8303220014* | 50-445 E |
| | 8303220105 | 50-445 K |
| | 8303220105 | 50-445 K |
| | 8303220128* | 50-445 K |
| | 8303220128* | 50-445 K |
| | 8303230228 | 50-445 G |
| | 8303230234* | 50-445 G |
| | 8303230234* | 50-445 G |
| | 8303240519 | 50-445 G |
| | 8303310263 | 50-445 G |
| | 8303310263 | 50-445 G |
| | 8303310272 | 50-445 G |
| | 8303310272 | 50-445 G |
| Texas Utilities Services, Inc | 8303010642 | 50-445 A |
| | 8303030018 | 50-445 A |
| | 8303090167 | 50-445 G |
| | 8303140340 | 50-445 A |
| | 8303140340 | 50-445 A |
| | 8303220188 | 50-445 F |
| | 8303220188 | 50-445 F |
| | 8303220387 | 50-445 F |
| | 8303220387 | 50-445 F |
| | 8303310105* | 50-445 F |
| | 8303310105* | 50-445 F |
| Texas, State of | 8303090337* | WASTE MGT |
| | 8303290788* | CONTRACT |
| | 8303300356 | 50-445 G |
| | 8303300356 | 50-445 G |
| | 8303300411 | 50-445 G |
| | 8303300411 | 50-445 G |
| Texas, Univ of | 8303160266 | 50-192 E |
| | 8303160271* | 50-192 E |
| Theda Clark Medical Center Neenah,WI | 8303240155* | FOIA |
| Todd Shipyards | 8303140043* | 70-1062 |
| | 8303140046* | 70-1062 |
| Toledo Edison Co | 8303010430 | 50-346 V |
| | 8303010581 | TOPREP |
| | 8303030173 | TOPREP |
| | 8303080047 | 50-346 G |
| | 8303080165 | 50-346 R |
| | 8303080170* | 50-346 R |
| | 8303080478 | 50-346 S |
| | 8303080494* | 50-346 S |
| | 8303080518 | 50-346 S |
| | 8303080522* | 50-346 S |
| | 8303090401* | 50-346 F |
| | 8303090405* | 50-346 F |
| | 8303140409 | 50-346 S |
| | 8303140429* | 50-346 S |
| | 8303140528 | 50-346 S |
| | 8303140540* | 50-346 S |
| | 8303150252 | 50-346 P |
| | 8303150274 | 50-346 G |
| | 8303150427 | 50-346 P |
| | 8303150432 | 50-346 P |
| | 8303150498 | 50-346 R |
| | 8303150499 | 50-346 P |
| | 8303150504* | 50-346 R |
| | 8303170362 | 50-346 R |
| | 8303170366* | 50-346 R |
| | 8303170442 | 50-346 S |
| | 8303170449* | 50-346 S |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303170522 | 50-346 S |
| | 8303170526* | 50-346 S |
| | 8303210358 | 50-346 S |
| | 8303210362* | 50-346 S |
| | 8303220058 | 50-346 P |
| | 8303220073 | 50-346 P |
| | 8303220150 | 50-346 P |
| | 8303220155 | 50-346 P |
| | 8303220205 | TOPREP |
| | 8303220381* | 50-346 F |
| | 8303220385* | 50-346 F |
| | 8303240474 | 50-346 S |
| | 8303240493* | 50-346 S |
| | 8303240496 | 50-346 P |
| | 8303250109* | 50-346 F |
| | 8303250124* | 50-346 F |
| | 8303280030 | 50-346 P |
| | 8303280197* | 50-346 F |
| | 8303290380 | 50-346 Q |
| | 8303290393 | 50-346 P |
| | 8303300394 | 50-346 P |
| | 8303300701* | 50-346 F |
| | 8303300707* | 50-346 F |
| | 8303300717* | 50-289 P |
| | 8303310002* | 50-346 F |
| | 8303310003* | 50-346 F |
| | 8303310007* | 50-346 F |
| | 8303310008* | 50-346 F |
| Torrey Pines Technology | 8303290383 | 53-358 A |
| | 8303310039 | 50-382 A |
| | 8303310053* | 50-382 A |
| Transnuclear, Inc. | 8303020332 | XPORTLIC |
| | 8303020337* | XPORTLIC |
| | 8303020449 | XPORTLIC |
| | 8303020457 | XPORTLIC |
| | 8303020467 | XPORTLIC |
| | 8303020472 | XPORTLIC |
| | 8303020476 | XPORTLIC |
| | 8303030194* | XPORTLIC |
| | 8303040017 | XPORTLIC |
| | 8303040121 | XPORTLIC |
| | 8303180598 | XPORTLIC |
| | 8303180603* | XPORTLIC |
| Twomey, Latham & Shea | 8303010408 | 50-322 Q |
| | 8303230260 | 50-322 Q |
| URS Corp. | 8303110040* | 50-395 P |
| US Ecology, Inc (Formerly Nuclear Engineering) | 8303170003 | 27-48 |
| | 8303170004* | 27-48 |
| | 8303180052 | 27-48 |
| | 8303280081 | 27-48 |
| Union Carbide Corp. | 8303010687 | RES |
| | 8303030306 | 50-261 P |
| | 8303030325 | 50-261 P |
| | 8303090106 | 40-299 |
| | 8303090500 | 40-299 |
| | 8303140684 | 40-299 |
| | 8303180125 | 40-299 |
| | 8303240030 | 40-299 |
| | 8303240033* | 40-299 |
| | 8303240090 | 40-299 |
| | 8303240095* | 40-299 |
| | 8303300632 | RES |
| Union Electric Co. | 8303030453* | 50-483 Q |
| | 8303030521* | 70-2943 |
| | 8303150276 | 50-483 V |
| | 8303150299 | 50-483 K |
| | 8303150303* | 50-483 K |
| | 8303150304* | 50-483 K |
| | 8303210102 | 50-483 F |
| | 8303220309 | 50-483 S |
| | 8303240048* | 50-483 F |
| | 8303240213* | 50-483 Q |
| | 8303290351 | 50-483 A |
| | 8303290356* | 50-483 A |
| Union Minerals | 8303090622 | 40-8584 |
| | 8303220469 | 40-8584 |
| | 8303230125 | 40-8584 |
| Union of Concerned Scientists | 8303030433 | 50-247 Q |
| | 8303070139 | 50-289 Q |
| | 8303070145* | 50-289 Q |
| | 8303150415 | 50-247 Q |
| | 8303170447 | 50-289 Q |
| | 8303180217 | 50-247 Q |
| | 8303180217 | 50-247 Q |
| | 8303180393 | 50-247 Q |
| | 8303180393 | 50-247 Q |
| | 8303240545 | 50-247 T |
| United Assoc. of Journeyman & Apprentices of Plumbing & Pipe Fitters Industry | 8303010100 | 50-440 Q |
| | 8303030373 | 50-440 Q |
| United Engineers & Constructors, Inc. (subs. of Raytheon Co.) | 8303140607 | 50-443 S |
| United Nuclear Corp. | 8303010126 | 70-820 |
| | 8303010696 | 70-371 |
| | 8303020117 | 70-371 |
| | 8303020138 | 70-820 |
| | 8303020282 | 70-371 |
| | 8303070087 | TOPREP |
| | 8303070096* | TOPREP |
| | 8303180321 | 70-371 |
| | 8303180326* | 70-371 |
| | 8303180594 | 70-820 |
| | 8303210073 | 70-820 |
| | 8303210078* | 70-820 |
| | 8303220413 | 50-16 W |
| | 8303290134 | 70-371 |
| Uraneri USA, Inc. | 8303100040 | 40-8783 |
| Uranium Resources, Inc. | 8303170292 | 40-8786 |
| Utah, Univ. of | 8303110223 | 50-72 R |
| | 8303110229* | 50-72 R |
| Vermont Yankee Nuclear Power Corp. | 8303010436 | 50-271 S |
| | 8303010441* | 50-271 S |
| | 8303010446 | 50-271 S |
| | 8303010455* | 50-271 S |
| | 8303020025 | 50-271 P |
| | 8303020031* | 50-271 P |
| | 8303030045 | 50-271 S |
| | 8303030064* | 50-271 S |
| | 8303040552 | 50-271 V |
| | 8303140442 | 50-271 S |
| | 8303140454* | 50-271 S |
| | 8303140503 | 50-271 R |
| | 8303140511* | 50-271 R |
| | 8303150292 | 50-271 P |
| | 8303160167 | 50-271 Q |
| | 8303180294 | 50-271 R |
| | 8303210129 | 50-271 F |
| | 8303240336 | 50-271 R |
| | 8303240342* | 50-271 R |
| | 8303280019 | 50-271 P |
| | 8303300259 | 50-271 F |
| | 8303300405 | 50-271 P |
| Vermont, State of | 8303300067* | CONTRACT |
| Vet. Admin. Medical Center Madison, WI | 8303240207* | FOIA |
| Veterans Admin. Center, Wood, WI | 8111170263* | FOIA |
| | 8201200407* | FOIA |
| Virginia Electric & Power Co. | 8302150454 | 50-339 S |
| | 8302150468* | 50-339 S |
| | 8302230312 | 50-338 S |
| | 8302230319* | 50-338 S |
| | 8303010435 | 50-338 S |
| | 8303010444* | 50-338 S |
| | 8303010460 | 50-280 S |
| | 8303010469* | 50-280 S |
| | 8303010594 | 50-339 S |
| | 8303010602* | 50-339 S |
| | 8303010655* | 50-280 Q |
| | 8303020187 | 71-9151 |
| | 8303020215 | 50-280 Y |
| | 8303020215 | 50-280 Y |
| | 8303040475 | 50-338 R |
| | 8303040479 | 50-338 Q |
| | 8303040479 | 50-338 Q |
| | 8303040480* | 50-338 R |
| | 8303040483 | 50-338 Q |
| | 8303040483 | 50-338 Q |
| | 8303040568 | 50-280 S |
| | 8303040584* | 50-280 S |
| | 8303070007 | 50-280 P |
| | 8303070048 | 50-280 P |
| | 8303080035 | 50-280 R |
| | 8303080037* | 50-280 R |
| | 8303080183 | 50-280 P |
| | 8303080372 | 50-338 R |
| | 8303080379* | 50-338 R |
| | 8303080484 | 50-338 P |
| | 8303080484 | 50-338 P |
| | 8303100189 | 50-338 P |
| | 8303100189 | 50-338 P |

# CORPORATE SOURCE INDEX

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303100191* | 50-338 P |
| | 8303100191* | 50-338 P |
| | 8303100342 | 50-339 P |
| | 8303100372 | 50-338 P |
| | 8303100372 | 50-338 P |
| | 8303110120 | 50-338 P |
| | 8303110280 | 50-280 P |
| | 8303110280 | 50-280 P |
| | 8303110282 | 50-280 P |
| | 8303110282 | 50-280 P |
| | 8303110323 | 50-290 Q |
| | 8303110323 | 50-280 Q |
| | 8303140221 | 50-338 P |
| | 8303140221 | 50-338 P |
| | 8303140523 | 50-281 S |
| | 8303140532* | 50-281 S |
| | 8303140542 | 50-280 S |
| | 8303140543* | 50-281 S |
| | 8303140551* | 50-280 S |
| | 8303140560* | 50-280 S |
| | 8303150138 | 50-280 S |
| | 8303150166* | 50-280 S |
| | 8303150175* | 50-280 S |
| | 8303150184* | 50-280 S |
| | 8303150217 | 50-338 S |
| | 8303150226* | 50-338 S |
| | 8303150285 | 50-280 P |
| | 8303150288* | 50-280 P |
| | 8303150370 | 50-280 R |
| | 8303150370 | 50-280 R |
| | 8303150376* | 50-280 R |
| | 8303150399 | 50-280 P |
| | 8303150399 | 50-280 P |
| | 8303150404* | 50-280 P |
| | 8303150404* | 50-280 P |
| | 8303150438 | 50-338 R |
| | 8303150438 | 50-338 R |
| | 8303150441* | 50-338 R |
| | 8303150447* | 50-338 R |
| | 8303160149 | 50-281 S |
| | 8303160157* | 50-281 S |
| | 8303160160 | 50-338 H |
| | 8303160160 | 50-338 H |
| | 8303160165* | 50-281 S |
| | 8303160172 | 50-290 P |
| | 8303160172 | 50-280 P |
| | 8303160194 | 50-280 S |
| | 8303160198 | 50-280 P |
| | 8303160198 | 50-280 P |
| | 8303160198 | 50-280 P |
| | 8303160201* | 50-280 S |
| | 8303160211* | 50-280 S |
| | 8303160363 | 50-271 R |
| | 8303160367* | 50-271 R |
| | 8303170365 | 50-280 P |
| | 8303170523 | 50-280 P |
| | 8303170523 | 50-280 P |
| | 8303170525 | 50-338 P |
| | 8303180025 | 50-338 S |
| | 8303180030* | 50-338 S |
| | 8303180342 | 50-339 S |
| | 8303180351* | 50-339 S |
| | 8303180467 | 50-338 P |
| | 8303180467 | 50-338 P |
| | 8303210456 | 50-339 S |
| | 8303210465* | 50-339 S |
| | 8303210489 | 50-339 S |
| | 8303210498* | 50-339 S |
| | 8303210523 | 50-280 Q |
| | 8303210523 | 50-280 Q |
| | 8303210523 | 50-280 Q |
| | 8303210523 | 50-280 Q |
| | 8303210617 | 50-280 P |
| | 8303240464 | 50-281 S |
| | 8303240472* | 50-281 S |
| | 8303240504 | 50-280 S |
| | 8303240510* | 50-280 S |
| | 8303240559 | 50-280 S |
| | 8303240573* | 50-280 S |
| | 8303280056 | 50-338 Q |
| | 8303280105 | 50-338 P |
| | 8303280274 | 50-339 P |
| | 8303290732* | 50-280 F |
| | 8303290732* | 50-280 F |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303290732* | 50-280 F |
| | 8303290739* | 50-280 F |
| | 8303290739* | 50-280 F |
| | 8303290739* | 50-280 F |
| | 8303290739* | 50-280 F |
| | 8303290743* | 50-280 F |
| | 8303290743* | 50-280 F |
| | 8303290743* | 50-280 F |
| | 8303290743* | 50-280 F |
| | 8303290743* | 50-280 F |
| Virginia Polytechnic Institute | 8303020045 | 50-124 R |
| | 8303020049* | 50-124 R |
| | 8303220167 | 50-124 P |
| | 8303220175* | 50-124 P |
| | 8303220178* | 50-124 P |
| | 8303220182* | 50-124 P |
| | 8303220187* | 50-124 P |
| | 8303220189* | 50-124 P |
| Virginia, Commonwealth of. | 8303290758* | CONTRACT |
| Wabash Valley Power Association, Inc. | 8302280121 | 50-546 A |
| | 8302280121 | 50-546 A |
| | 8302280137* | 50-546 K |
| | 8302280137* | 50-546 K |
| Wall Street Journal | 8303110049 | FOIA |
| Washington Public Power Supply System | 8301110169 | 50-508 K |
| | 8303010129 | 50-397 Q |
| | 8303010234 | 50-397 E |
| | 8303010357 | 50-397 E |
| | 8303010559 | 50-305 V |
| | 8303010569 | 50-397 S |
| | 8303010577* | 50-397 S |
| | 8303010582* | 50-397 S |
| | 8303010589* | 50-397 S |
| | 8303010617 | 50-460 S |
| | 8303010649 | 50-397 A |
| | 8303010684 | 50-397 K |
| | 8303010688* | 50-397 K |
| | 8303020036 | 50-460 Q |
| | 8303020057 | 50-460 Q |
| | 8303030192 | 50-508 A |
| | 8303040253 | 50-397 S |
| | 8303040397 | 50-397 E |
| | 8303040449 | 50-460 C |
| | 8303040453* | 50-460 C |
| | 8303040482 | 50-397 A |
| | 8303040571 | 50-460 S |
| | 8303040607 | 50-397 A |
| | 8303070138 | 50-397 A |
| | 8303070154 | 50-397 F |
| | 8303080011 | 50-397 S |
| | 8303080034 | 50-460 Q |
| | 8303080220 | TOPREP |
| | 8303080225* | TOPREP |
| | 8303090172 | 50-397 V |
| | 8303090172 | 50-397 V |
| | 8303110218 | 50-508 Q |
| | 8303110236 | 50-508 Q |
| | 8303110298 | 50-508 S |
| | 8303110306* | 50-508 S |
| | 8303110327* | 50-508 Q |
| | 8303110379* | 50-508 Q |
| | 8303140248 | 50-508 Q |
| | 8303140483 | 50-508 S |
| | 8303140633 | 50-397 S |
| | 8303150406 | 50-460 A |
| | 8303160290 | 50-397 A |
| | 8303160427 | 50-397 F |
| | 8303170278 | 50-397 F |
| | 8303210069 | 70-2950 |
| | 8303220057 | 50-397 A |
| | 8303220157 | 50-508 S |
| | 8303220250 | 50-460 Q |
| | 8303240220 | 50-397 A |
| | 8303280001 | 50-508 S |
| | 8303290003 | 50-460 A |
| | 8303290240 | 50-508 A |
| | 8303290404* | 50-397 A |
| | 8303290465 | 50-508 A |
| Washington, State of | 8303040217* | State Prog |
| | 8303180562 | WASTE MGT |
| | 8303290028* | CONTRACT |
| | 8303290298* | CONTRACT |
| | 8303290849 | WASTE MGT |
| | 8303300257 | WASTE MGT |
| | 8303300267 | WASTE MGT |

| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| Washington, Univ. of | 8303020082* | CONTRACT |
| Waste Management Group, Inc. | 8303030223* | 50-320 P |
| Watkins, L. B. | 8303300329 | 50-458 G |
| Waukesha Memorial Hosp., Waukesha, WI | 8110150329* | FOIA |
| West Branch Conservation Association | 8303030433 | 50-247 G |
| | 8303220388 | 40-2061 |
| West Chicago, IL | 8303140472* | 50-528 G |
| West Valley Agricultural Protection Council, Inc. | 8303180289 | 50-529 G |
| | 8303150408 | 50-247 G |
| Westchester County, NY | 8303030433 | 50-247 G |
| Westchester Peoples Action Coalition, Inc. | 8303180144 | 50-247 G |
| Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) | 8303090024 | 40-1162 |
| | 8303090049 | 40-1162 |
| | 8303180129 | 40-1162 |
| | 8303180145 | 40-1162 |
| | 8303180511 | 40-1162 |
| | 8303180519* | 40-1162 |
| | 8303300145 | 40-1162 |
| | 8303300236 | 40-1162 |
| Westinghouse Electric Corp. | 8202160328 | TOPREP |
| | 8302160332* | TOPREP |
| | 8303010312* | 50-454 T |
| | 8303010312* | 50-454 T |
| | 8303010317* | 50-454 T |
| | 8303010317* | 50-454 T |
| | 8303010320* | 50-454 T |
| | 8303010320* | 50-454 T |
| | 8303010324* | 50-454 T |
| | 8303010324* | 50-454 T |
| | 8303010331* | 50-454 T |
| | 8303010331* | 50-454 T |
| | 8303010337* | 50-454 T |
| | 8303010337* | 50-454 T |
| | 8303020246 | 71-4909 |
| | 8303020479 | XPORTLIC |
| | 8303030267* | CONTRACT |
| | 8303030297 | 71-4986 |
| | 8303030572 | PT21 |
| | 8303030659 | XPORTLIC |
| | 8303030773 | XPORTLIC |
| | 8303040091 | XPORTLIC |
| | 8303040127 | XPORTLIC |
| | 8303040354 | TOPREP |
| | 8303040509 | TOPREP |
| | 8303070146 | TOPREP |
| | 8303070150* | TOPREP |
| | 8303070157* | TOPREP |
| | 8303080129 | PROJ |
| | 8303090113 | TOPREP |
| | 8303090192 | TOPREP |
| | 8303090380* | TOPREP |
| | 8303090383* | TOPREP |
| | 8303090386* | TOPREP |
| | 8303090659 | NUREG |
| | 8303110324* | 50-244 P |
| | 8303140662 | XPORTLIC |
| | 8303150459* | 50-537 G |
| | 8303160395* | 50-313 P |
| | 8303170516* | 50-250 P |
| | 8303180082 | XPORTLIC |
| | 8303180087* | XPORTLIC |
| | 8303210411* | GA999 |
| | 8303230442 | XPORTLIC |
| | 8303240325 | XPORTLIC |
| | 8303250027 | 50-445 A |
| | 8303250039* | TOPREP |
| | 8303250044* | TOPREP |
| | 8303250045* | TOPREP |
| | 8303250047* | TOPREP |
| | 8303250049* | TOPREP |
| | 8303290085* | XPORTLIC |
| | 8303290144 | 50-272 S |
| | 8303290378* | 50-416 P |
| | 8303290385* | 50-416 P |
| | 8303300229* | TOPREP |
| | 8303300237* | TOPREP |
| | 8303300244* | TOPREP |
| | 8303300252* | TOPREP |
| | 8303300542 | TOPREP |
| | 8303300547* | TOPREP |
| | 8303310287* | 50-282 P |
| | 8303310575 | XPORTLIC |
| Westinghouse Operating Plants Owners Group | 8303090378 | TOPREP |
| | 8303150642* | 50-272 S |
| | 8303290355 | TOPREP |
| | 8303300221 | TOPREP |
| Wilson, R. | 8303140269 | 50-400 G |
| Wisconsin Electric Power Co. | 8303010652 | 50-266 P |
| | 8303010697 | 50-266 P |
| | 8303040530 | 50-266 R |
| | 8303040530 | 50-266 R |
| | 8303040538* | 50-266 R |
| | 8303040538* | 50-266 R |
| | 8303040622 | 50-266 F |
| | 8303040622 | 50-266 F |
| | 8303080271 | 50-266 G |
| | 8303080271 | 50-266 G |
| | 8303080430 | 50-266 P |
| | 8303080435* | 50-266 P |
| | 8303080515 | 50-266 V |
| | 8303090130 | 50-266 P |
| | 8303090130 | 50-266 P |
| | 8303110106 | 71-9080 |
| | 8303150333 | 50-266 P |
| | 8303150333 | 50-266 P |
| | 8303150338* | 50-266 P |
| | 8303150338* | 50-266 P |
| | 8303160162 | 50-266 P |
| | 8303160221 | 50-301 G |
| | 8303160569 | 50-266 R |
| | 8303160577* | 50-266 R |
| | 8303210111 | 50-266 P |
| | 8303210111 | 50-266 P |
| | 8303210116* | 50-266 P |
| | 8303210116* | 50-266 P |
| | 8303220137 | 50-266 P |
| | 8303220137 | 50-266 P |
| | 8303280006 | 50-266 P |
| | 8303280006 | 50-266 P |
| | 8303280007* | 50-266 P |
| | 8303280007* | 50-266 P |
| | 8303280037 | 50-266 P |
| | 8303280037 | 50-266 P |
| | 8303290258 | 50-266 P |
| | 8303290258 | 50-266 P |
| | 8303300127 | 50-266 P |
| | 8303300127 | 50-266 P |
| | 8303300132* | 50-266 P |
| | 8303300132* | 50-266 P |
| | 8303300293 | 50-266 P |
| | 8303300293 | 50-266 P |
| | 8303310035 | 50-266 J |
| | 8303310152 | 50-266 S |
| Wisconsin Power & Light Co. | 8303030088* | 50-305 R |
| | 8303110377* | 50-305 P |
| Wisconsin Public Service Corp. | 8303010277 | 50-305 P |
| | 8303010292* | 50-305 P |
| | 8303010690 | 50-305 V |
| | 8303030083 | 50-305 R |
| | 8303030088* | 50-305 R |
| | 8303080122 | 50-305 S |
| | 8303080134* | 50-305 S |
| | 8303080163 | 50-305 R |
| | 8303080166* | 50-305 R |
| | 8303080444 | 50-305 P |
| | 8303100316 | 50-305 P |
| | 8303110373 | 50-305 P |
| | 8303110377* | 50-305 P |
| | 8303140329 | 50-305 P |
| | 8303140396 | 50-305 G |
| | 8303140400 | 50-305 S |
| | 8303140414* | 50-305 S |
| | 8303140493 | 50-305 S |
| | 8303140505* | 50-305 S |
| | 8303140519 | 50-305 P |
| | 8303150287 | 50-305 G |
| | 8303160315 | 50-305 P |
| | 8303160352 | 50-305 R |
| | 8303160358* | 50-305 R |
| | 8303170419* | 50-305 G |
| | 8303220335 | 50-305 P |
| | 8303220342 | 50-305 J |
| | 8303220350 | 50-305 I |
| | 8303240096* | 50-305 F |
| | 8303240102* | 50-305 F |
| | 8303240225 | 50-305 S |
| | 8303240238* | 50-305 S |
| | 8303240247 | 50-305 J |

# CORPORATE SOURCE INDEX


| AUTHOR AFFILIATION | ACCESSION NUMBER | SUBJECT CATEGORY |
|---|---|---|
| | 8303240565 | 50-305 S |
| | 8303240574* | 50-305 S |
| Wisconsin's Environmental Decade | 8303230257 | 50-266 G |
| Wisconsin, State of | 8303240117 | FOIA |
| | 8303310155* | CONTRACT |
| | 8303310367* | CONTRACT |
| Wisconsin, Univ. of, Madison | 8303210104 | ACRS |
| | 8303210108* | ACRS |
| | 8303240139* | FOIA |
| Wolverine Electric Cooperative | 8303170382 | 50-341 G |
| Woodward-Clyde Consultants, Inc | 8303020481* | CONTRACT |
| Wright, D | 8303150158* | CONTRACT |
| Wyoming Fuel Co | 8303220455 | 40-8829 |
| | 8303230128 | 40-8829 |
| Wyoming Mineral Corp | 8303170221 | 40-8502 |
| | 8303170225* | 40-8502 |
| | 8303300215 | 40-8585 |
| | 8303300222* | 40-8585 |
| Wyoming, State of | 8303020054 | PRM |
| | 8303020058* | PRM |
| | 8303090046 | 40-2259 |
| | 8303090062 | 40-8502 |
| | 8303090111 | 40-299 |
| | 8303090127 | 40-8745 |
| | 8303090601 | 40-8584 |
| | 8303090632 | 40-8584 |
| | 8303170334 | 40-8714 |
| | 8303180103 | 40-8663 |
| | 8303220002 | 40-8714 |
| | 8303220428 | 40-8492 |
| | 8303230133 | 40-8064 |
| Yankee Atomic Electric Co | 8302180128* | 50-443 G |
| | 8303010254 | NUREG |
| | 8303010402 | 50-29 S |
| | 8303010404* | 50-29 S |
| | 8303010409 | 50-443 A |
| | 8303010409 | 50-443 A |
| | 8303010533 | 50-443 A |
| | 8303010533 | 50-443 A |
| | 8303010578 | 50-443 F |
| | 8303010578 | 50-443 F |
| | 8303010629 | 50-29 S |
| | 8303010638* | 50-29 S |
| | 8303010674 | 50-29 S |
| | 8303010679* | 50-29 S |
| | 8303020083 | 50-443 A |
| | 8303020083 | 50-443 A |
| | 8303020085 | 50-443 A |
| | 8303020085 | 50-443 A |
| | 8303040450 | 50-29 S |
| | 8303040456* | 50-29 S |
| | 8303070156 | 50-443 H |
| | 8303080361 | 50-29 R |
| | 8303080369* | 50-29 R |
| | 8303090139 | 50-29 S |
| | 8303090224* | 50-29 S |
| | 8303090365 | 50-29 R |
| | 8303090370* | 50-29 R |
| | 8303090644* | 50-29 F |
| | 8303090664* | 50-29 F |
| | 8303090674* | 50-29 F |
| | 8303090679* | 50-29 F |
| | 8303100311 | 50-29 R |
| | 8303100321* | 50-29 R |
| | 8303100375 | 50-29 R |
| | 8303100376* | 50-29 R |
| | 8303100546* | 50-29 F |
| | 8303100550* | 50-29 F |
| | 8303110045 | 50-29 P |
| | 8303140529 | 50-29 S |
| | 8303140538* | 50-29 S |
| | 8303150195 | 50-443 A |
| | 8303150195 | 50-443 A |
| | 8303150207 | 50-443 A |
| | 8303150322 | 50-29 P |
| | 8303150331 | 50-443 E |
| | 8303150436 | 50-443 A |
| | 8303150436 | 50-443 A |
| | 8303150509 | 50-29 P |
| | 8303150509 | 50-29 P |
| | 8303150509 | 50-29 P |
| | 8303150518* | 50-29 P |
| | 8303150518* | 50-29 P |
| | 8303150518* | 50-29 P |
| | 8303150549 | 50-29 R |
| | 8303150556* | 50-29 R |
| | 8303160622* | COMMISSION |
| | 8303170164 | 50-29 G |
| | 8303170358 | 50-443 A |
| | 8303170441 | 50-443 A |
| | 8303170441 | 50-443 A |
| | 8303180009 | 50-29 G |
| | 8303220148* | 50-443 G |
| | 8303240118* | 50-29 F |
| | 8303240123* | 50-29 F |
| | 8303240366 | 50-443 S |
| | 8303240413 | 50-29 P |
| | 8303240415* | 50-29 P |
| | 8303240441 | 50-443 S |
| | 8303280021 | 50-29 P |
| | 8303280033 | 50-29 P |
| | 8303290254 | 50-443 E |
| Zetec, Inc | 8303110312* | 50-317 G |
| | 8303110317* | 50-317 G |
| Zytron | 8303230385 | MISC |

# REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

| REPORT NUMBER | ACCESSION NUMBER | SUBJECT CATEGORY | OTHER REPORT NUMBER |
|---|---|---|---|
| 0041L/0077P | 8303250081* | 50-275 R | |
| 11181-ICE-3111 R00 | 8303160394* | 50-335 P | GL-82-28 |
| 11181-ICE-3218 R00 | 8303160373* | 50-335 P | GL-82-28 |
| 11181-ICE-3219 R00 | 8303160379* | 50-335 P | GL-82-28 |
| 11181-ICE-3220 R00 | 8303160386* | 50-335 P | GL-82-28 |
| 15173 | 8303240405* | 50-219 R | |
| 16081-ICE-3111 R00 | 8303160313* | 50-250 P | GL-82-28 |
| 16081-ICE-3218 R00 | 8303160282* | 50-250 P | GL-82-28 |
| 16081-ICE-3219 R00 | 8303160295* | 50-250 P | GL-82-28 |
| 16081-ICE-3220 R00 | 8303160304* | 50-250 P | GL-82-28 |
| 1848 | 8303100092* | 50-440 A | |
| 2164N-RRL R02 | 8303300243* | 50-309 P | 2164N-RRL |
| 36 R00 | 8303080285* | 50-275 P | |
| 38 R00 | 8303090112* | 50-275 P | |
| 57-238 | 8303180115* | WASTE MGT | |
| 745 | 8303150375* | 70-143 | |
| 77-1141270-00 | 8303300721* | 50-289 P | |
| 82-10 R01 | 8303290305* | 50-277 P | |
| 82-145 | 8303180126* | WASTE MGT | |
| 82-3 | 8303110343* | 50-395 R | |
| 8303010687 | 8303010687 | RES | |
| 8303030318 | 8303030318 | RES | ORNL/CSD/INF-78 |
| 8303030721 | 8303030721 | RES | |
| 8303040104 | 8303040104 | RES | |
| 8303040122 | 8303040122 | RES | |
| 8303040138 | 8303040138 | RES | |
| 8303040155 | 8303040155 | 50-537 A | |
| 8303040170 | 8303040170 | RES | |
| 8303040186 | 8303040186 | RES | |
| 8303090531 | 8303090531 | RES | |
| 8303090555 | 8303090555 | RES | |
| 8303090564 | 8303090564 | RES | |
| 8303090569 | 8303090569 | RES | |
| 8303090577 | 8303090577 | RES | |
| 8303090608 | 8303090608 | RES | |
| 8303090616 | 8303090616 | RES | BNL-NUREG-32548 |
| 8303090627 | 8303090627 | RES | BNL-NUREG-32506 |
| 8303100121 | 8303100121 | RES | ORNL/ED/EIS-181 |
| 8303100136 | 8303100136 | RES | |
| 8303110118 | 8303110118 | RES | G-6-771 (R295) |
| 8303110597 | 8303110597 | RES | DPST-NUREG-77-3 |
| 8303150615 | 8303150615 | RES | |
| 8303160155 | 8303160155 | RES | WR-NSMD-83-003 |
| 8303160164 | 8303160164 | RES | WR-NSMD-83-001 |
| 8303160175 | 8303160175 | RES | |
| 8303160183 | 8303160183 | RES | BNL-NUREG-32501 |
| 8303160687 | 8303160687 | RES | BNL-NUREG-32496 |
| 8303160756 | 8303160756 | RES | EGG-M-21582 |
| 8303180549 | 8303180549 | RES | EGG-WM-5987 |
| 8303180555 | 8303180555 | RES | EGG-LOFT-6159 |
| 8303180556 | 8303180556 | RES | |
| 8303180568 | 8303180568 | RES | EGG-PHYS-6149 |
| 8303180579 | 8303180579 | RES | EGG-EE-6136 |
| 8303180613 | 8303180613 | RES | WR-NSMD-82-082 |
| 8303180672 | 8303180672 | RES | WR-CD-82-074 |
| 8303180674 | 8303180674 | RES | EGG-EE-6137 |
| 8303180694 | 8303180694 | RES | EGG-LOFT-6014 |
| 8303180696 | 8303180696 | RES | EGG-WRR-6157 |
| 8303180699 | 8303180699 | RES | WR-NSMD-83-002 |
| 8303210186 | 8303210186 | RES | WR-CD-82-062 |
| 8303210776 | 8303210776 | RES | BNL-NUREG-32520 |
| 8303240137 | 8303240137 | RES | EGG-TFBP-6179 |
| 8303240140 | 8303240140 | RES | EGG-EA-5863 |
| 8303240144 | 8303240144 | RES | EGG-NSMD-6182 |
| 8303240146 | 8303240146 | RES | EGG-WRR-6166 |
| 8303240167 | 8303240167 | RES | EGG-EE-6060 |
| 8303240268 | 8303240268 | 50-302 P | TAC 42121 |
| 8303240275 | 8303240275 | RES | EGG-SEMI-6176 |
| 8303280329 | 8303280329 | RES | EGG-NSMD-6155 |
| 8303290786 | 8303290786 | RES | BNL-NUREG-32585 |
| 8303290792 | 8303290792 | RES | |
| 8303290797 | 8303290797 | 50-255 P | EGG-EA-6158 |
| 8303290804 | 8303290804 | RES | |
| 8303290824 | 8303290824 | RES | |
| 8303290862 | 8303290862 | RES | |
| 8303300103 | 8303300103 | RES | EGG-LOFT-6186 |
| 8303300108 | 8303300108 | 50-269 P | EGG-NTAP-6190 |
| 8303300154 | 8303300154 | RES | BNL-NUREG-32558 |
| 8303300164 | 8303300164 | 50-269 P | EGG-EA-6131 |
| 8303300178 | 8303300178 | RES | |
| 8303300421 | 8303300421 | RES | BNL-NUREG-32586 |
| 8303300427 | 8303300427 | RES | BNL-NUREG-32523 |
| 8303300571 | 8303300571 | RES | BNL-NUREG-32574 |
| 8303300578 | 8303300578 | RES | |
| 8303300606 | 8303300606 | RES | ORNL/ED/EIS-182 |
| 8303300623 | 8303300623 | RES | EGG-EA-5908 |
| 8303300632 | 8303300632 | RES | |
| 8303300642 | 8303300642 | RES | BNL-NUREG-32576 |
| 8303300667 | 8303300667 | RES | |
| 8303310068 | 8303310068 | 50-537 A | |
| AOS/QAP-001 R00 | 8303110119* | 71-86 | 21959 |
| C/1800023 R03 | 8303070169* | 50-413 A | |
| CE-1-A R23 | 8303110279* | 50-10 P | |
| CEN-217(V)-NP R00 | 8303100349* | 50-528 E | |
| CEN-219(V)-NP R00 | 8303100353* | 50-528 E | |
| CEN-226(V)-NP R00 | 8303100356* | 50-528 E | |
| CEN-232(M) | 8303030675* | 50-309 P | |
| COM-39-001 | 8303100082* | 50-265 P | 64 321 0100 |
| COM-39-002 | 8303100087* | 50-265 P | |
| DOE/EIS-0085-FS | 8303150028 | TOPREP | |
| DOE/EIS-0089 | 8303230287* | ORG | |
| DTB04R80-0479 RA | 8303110262* | 50-389 A | |
| DUKE-1-A A06 | 8303040643* | TOPREP | |
| EGG-EA-6109 DRFT | 8303030765* | 50-275 P | |
| EGG-EA-6131 | 8303300021* | 50-269 P | |
| ES-LPD-83-001 | 8303070120* | 50-537 A | |
| ES-LRD-83-3030 R01 | 8303150459* | 50-537 G | |
| GA-C16900 | 8303310053* | 50-382 A | |
| JCP-31-A | 8303040587* | 50-219 R | |
| KR1-B31-F031 R02 | 8303070089* | 50-387 P | 238X114AE |

# REPORT NUMBER INDEX

| REPORT NUMBER | ACCESSION NUMBER | SUBJECT CATEGORY | | OTHER REPORT NUMBER |
|---|---|---|---|---|
| LD-83-020 1-NP | 8303080412* | 50-470 | E | |
| N-46474P038368 R01 | 8303110260* | 50-389 | A | |
| NEDO-10084-2G DRFT | 8302040475* | 71-9001 | | RSFA 83-07 |
| NEDO-11209-04A R04 | 8303020065* | TOPREP | | 78NED116R |
| NEDO-11209-04AR4 ERR | 8303020059* | TOPREP | | 78NED116R |
| NEDO-20566-1-A | 8303160236* | TOPREP | | 77NED304 |
| NEDO-20776 R07 | 8303010075* | 71-4 | | 21913 |
| NF-1583.01 | 8303160417* | 50-324 | P | |
| NF-1583.02 | 8303160418* | 50-324 | P | |
| NF-1583.03 | 8303160421* | 50-324 | P | |
| NPROD-ICE-3202 R00 | 8303160276* | 50-250 | P | 9L-82-28 |
| NUREG-0020 V06 N10 | 8303110145 | NUREG | | |
| NUREG-0020 V06 N11 | 8303300426 | NUREG | | |
| NUREG-0304 V07 N04 | 8303160605 | NUREG | | |
| NUREG-0383 V01 R05 | 8303140704 | NUREG | | |
| NUREG-0383 V02 R05 | 8303140701 | NUREG | | |
| NUREG-0383 V03 R02 | 8303140690 | NUREG | | |
| NUREG-0422 S06 | 8303230239 | 50-369 | E | |
| NUREG-0430 V03 N01 | 8303100427 | NUREG | | |
| NUREG-0485 V05 N01 | 8303100432 | NUREG | | |
| NUREG-0525 R06 | 8303160626 | NUREG | | |
| NUREG-0540 V04 N11 | 8303100446 | NUREG | | |
| NUREG-0540 V04 N12 | 8303310369 | NUREG | | |
| NUREG-0566 V02 N04 | 8303110137 | NUREG | | |
| NUREG-0580 V12 N02 | 8303150016 | NUREG | | |
| NUREG-0584 R03 DRFT | 8303220417 | NUREG | | |
| NUREG-0606 V05 N01 | 8303140698 | NUREG | | |
| NUREG-0748 V03 N01 | 8303140686 | NUREG | | |
| NUREG-0800 ERR | 8303110129 | NUREG | | |
| NUREG-0823 | 8303090709 | 50-237 | P | |
| NUREG-0824 | 8303230417 | 50-245 | P | |
| NUREG-0825 | 8303090683 | 50-29 | P | |
| NUREG-0837 V02 N03 | 8303290694 | NUREG | | |
| NUREG-0845 | 8303090505 | NUREG | | |
| NUREG-0857 S04 | 8303300463 | 50-528 | E | |
| NUREG-0896 | 8303220444 | 50-443 | E | |
| NUREG-0907 | 8303100429 | NUREG | | |
| NUREG-0963 | 8303090715 | NUREG | | |
| NUREG-0964 | 8303220438 | 50-369 | P | |
| NUREG-0966 | 8303310361 | NUREG | | |
| NUREG-0967 | 8303300435 | NUREG | | |
| NUREG-0968 V01 | 8303300448 | 50-537 | E | |
| NUREG-0968 V02 | 8303300092 | 50-537 | E | |
| NUREG-0977 | 8303310358 | 50-272 | S | |
| NUREG/BR-0025 V09 N2 | 8303170281 | NUREG | | |
| NUREG/BR-0051 V04 N5 | 8303140681 | NUREG | | |
| NUREG/CP-0027 V01 | 8303140707 | NUREG | | |
| NUREG/CP-0027 V02 | 8303140709 | NUREG | | |
| NUREG/CP-0027 V03 | 8303140710 | NUREG | | |
| NUREG/CP-0028 V03 | 8303300472 | NUREG | | CONF-820911 |
| NUREG/CR-1391 | 8303300527 | NUREG | | SAND80-0822 |
| NUREG/CR-2000 V02 N1 | 8303100433 | NUREG | | ORNL/NSIC-200 |
| NUREG/CR-2000 V02 N2 | 8303230408 | NUREG | | ORNL/NSIC-200 |
| NUREG/CR-2098 | 8303220394 | NUREG | | EGG-EA-5289 |
| NUREG/CR-2401 | 8303090659 | NUREG | | WCAP-9973 |
| NUREG/CR-2443 | 8303090520 | NUREG | | |
| NUREG/CR-2659 | 8303140696 | NUREG | | PNL-3794 |
| NUREG/CR-2668 | 8303300651 | NUREG | | ORNL/TM-8299 |
| NUREG/CR-2703 | 8303020266 | NUREG | | |
| NUREG/CR-2729 | 8303230281 | NUREG | | EGG-EA-5502 |
| NUREG/CR-2751 V02 | 8303300638 | NUREG | | ORNL/TM-8369/V2 |
| NUREG/CR-2751 V03 | 8303290673 | NUREG | | ORNL/TM-8369/V3 |
| NUREG/CR-2770 | 8303220400 | NUREG | | EGG-EA-5485 |
| NUREG/CR-2771 | 8303220409 | NUREG | | EGG-EA-5623 |
| NUREG/CR-2800 | 8303150680 | NUREG | | PNL-429 |
| NUREG/CR-2821 | 8303140617 | NUREG | | ANL-82-66 |
| NUREG/CR-2824 V02 | 8303140622 | NUREG | | ORNL/TM-8418/V2 |
| NUREG/CR-2824 V03 | 8303290710 | NUREG | | ORNL/TM-8418/V3 |
| NUREG/CR-2843 V01 | 8303300514 | NUREG | | SAND82-1788 |
| NUREG/CR-2854 | 8303250113 | NUREG | | 813-1164D |
| NUREG/CR-2863 | 8303170624 | NUREG | | ORNL-5905 |
| NUREG/CR-2874 V02 | 8303160009 | NUREG | | ORNL/TM-8443/V2 |
| NUREG/CR-2878 | 8303220422 | NUREG | | PNL-4373 |
| NUREG/CR-2886 | 8303290717 | NUREG | | ORNL/TM-8465 |
| NUREG/CR-2887 | 8303290677 | NUREG | | SAND82-2894 |
| NUREG/CR-2891 | 8303100443 | NUREG | | |
| NUREG/CR-2892 | 8303100453 | NUREG | | |
| NUREG/CR-2901 | 8303220429 | NUREG | | SAND82-1693 |
| NUREG/CR-2902 | 8303230362 | NUREG | | LA-9499-MS |
| NUREG/CR-2904 | 8303150130 | NUREG | | SAND82-7077 |
| NUREG/CR-2925 | 8303290689 | NUREG | | SAND82-2004 |
| NUREG/CR-2928 | 8303290698 | NUREG | | ORNL/TM-8500 |
| NUREG/CR-2929 | 8303100421 | NUREG | | PNL-4449 |
| NUREG/CR-2935 | 8303100416 | NUREG | | PNL-4336 |
| NUREG/CR-2939 | 8303230512 | NUREG | | BNL-NUREG-51585 |

| REPORT NUMBER | ACCESSION NUMBER | SUBJECT CATEGORY | | OTHER REPORT NUMBER |
|---|---|---|---|---|
| NUREG/CR-2944 | 8303290707 | NUREG | | BNL-NUREG-51586 |
| NUREG/CR-2945 | 8303290704 | NUREG | | BNL/NUREG-51587 |
| NUREG/CR-2952 | 8303090510 | NUREG | | |
| NUREG/CR-2959 | 8303300446 | NUREG | | 813-1165 |
| NUREG/CR-2968 | 8303170616 | NUREG | | ORNL/TM-8509 |
| NUREG/CR-2974 | 8303280066 | NUREG | | ORNL/TDMC-2 |
| NUREG/CR-2993 | 8303160620 | 50-309 | P | BNL-NUREG-51594 |
| NUREG/CR-2997 V02 | 8303300511 | NUREG | | ORNL/TM-8527/V2 |
| NUREG/CR-2998 | 8303140630 | NUREG | | ORNL/TM-8546 |
| NUREG/CR-3009 | 8303160614 | NUREG | | SAND78-2347 |
| NUREG/CR-3028 | 8303140664 | 50-352 | A | BNL-NUREG-51600 |
| NUREG/CR-3030 | 8303160611 | NUREG | | PNL-4524 |
| NUREG/CR-3031 | 8303230517 | NUREG | | LA-9553-MS |
| NUREG/CR-3033 | 8303300518 | NUREG | | LA-9574-MS |
| NUREG/CR-3040 ERR | 8303300597 | NUREG | | |
| NUREG/CR-3045 V01 | 8303300628 | NUREG | | ANL/AA-28 |
| NUREG/CR-3065 V01 | 8303280114 | NUREG | | 813-1163 |
| NUREG/CR-3065 V02 | 8303280097 | NUREG | | 813-1163 |
| NUREG/CR-3069 V01 | 8303100558 | NUREG | | SAND82-2738/1 |
| NUREG/CR-3069 V02 | 8303100460 | NUREG | | SAND82-2738/2 |
| NUREG/CR-3082 | 8303230282 | NUREG | | BNL-NUREG-51628 |
| NUREG/CR-3092 | 8303230142 | NUREG | | ORNL/TM-8599 |
| NUREG/CR-3103 | 8303140628 | NUREG | | EGG-2235 |
| NUREG/CR-3105 | 8303230413 | NUREG | | SAND82-2821 |
| NUREG/CR-3109 | 8303100564 | NUREG | | |
| NUREG/CR-3113 | 8303220453 | NUREG | | ORNL/TM-8585 |
| NUREG/CR-3114 | 8303230467 | NUREG | | ORNL/TM-8614 |
| NUREG/CR-3115 | 8303290683 | NUREG | | ORNL/CSD/TM-201 |
| NUREG/CR-3116 | 8303220413 | 50-16 | W | |
| NUREG/CR-3120 | 8303100424 | NUREG | | |
| NUREG/CR-3126 | 8303150614 | NUREG | | EGG-2238 |
| NUREG/CR-3130 | 8303150031 | NUREG | | |
| NUREG/CR-3144 | 8303220432 | NUREG | | |
| NUREG/CR-3145 V01 | 8303220407 | NUREG | | |
| NUREG/CR-3209 | 8303310366 | NUREG | | |
| NUREG/CR-3212 | 8303280061 | NUREG | | |
| NUS-3697 R02 | 8303040605* | 50-324 | P | |
| P 105-4-839-037 R00 | 8303020109* | 50-275 | P | |
| P 105-4-839-040 R00 | 8303160342* | 50-275 | R | |
| PGE-1015-82 | 8303110243* | 50-344 | R | |
| QDR-5437-131-01 | 8303110291* | 50-280 | P | |
| QDR-5437-17-01 | 8303110297* | 50-280 | P | |
| QDR-5437-201-01 | 8303110302* | 50-280 | P | NDB 1-VOL-289 |
| QDR-5437-205-01 | 8303110358* | 50-280 | P | |
| QDR-5437-241-01 | 8303110353* | 50-280 | P | NDB 11-VOL-290 |
| QDR-5437-215-01 | 8303110359* | 50-280 | P | |
| QDR-5437-47-01 | 8303110286* | 50-280 | P | |
| QDR-5437-78-01 | 8303110356* | 50-280 | P | |
| RERR-131 | 8303280286* | 50-272 | R | |
| RGS-83-682 | 8303290298* | CONTRACT | | NRC-32-83-682 |
| RGI-83-610 | 8303290045* | CONTRACT | | NRC-28-83-610 |
| RGV-83-684 | 8303290535* | CONTRACT | | NRC-32-83-684 |
| RS-003 | 8303070164* | 50-413 | A | |
| SAI-186-029-09 | 8208260154* | 50-315 | P | |
| SAI-186-029-48 | 8208310332* | 50-277 | P | |
| SAI-348-83-PA | 8303220106 | 50-537 | A | |
| SECY-82-039A | 8205270445* | FOIA | | |
| SECY-82-087 | 8203120424* | 50-250 | G | |
| SECY-82-198 | 8205240600* | FOIA | | |
| SECY-82-319 | 8208270667* | 50-361 | P | |
| SECY-82-335 | 8208260515* | FOIA | | |
| SECY-82-380 | 8211300421* | FOIA | | |
| SECY-82-396 | 8211020694* | FOIA | | |
| SECY-82-396A | 8211040047* | FOIA | | |
| SECY-83-004 | 8303300652* | FOIA | | |
| SECY-83-016 ERR | 8301270005* | FOIA | | |
| SECY-83-016A | 8302160113 | SECY | | |
| SECY-83-098 | 8303230320 | 50-272 | S | |
| SECY-83-098A | 8303230332 | 50-272 | S | |
| SECY-83-107 | 8303280348* | 10CFR | | |
| SRO-316 | 8209030274* | 50-213 | P | |
| STR6764 | 8303110268* | 50-389 | A | |
| SWRI 6582-001 R01 | 8303290613* | TOPREP | | |
| SWRI 6582-001 R02 | 8303290631* | TOPREP | | |
| SWRI-6582-002 DRFT | 8303290606* | TOPREP | | |
| TER-C5257-43/44 | 8203290497* | 50-282 | P | TAC 06250 |
| TER-C5257-505 | 8301170075* | 50-346 | P | TAC 42508 |
| TER-C5257-521 | 8302020153* | 50-369 | P | IEB-79-01B |
| TER-C5506-117 | 8212020263* | 50-29 | P | |
| TER-C5506-399/400 DR | 8302090307* | 50-250 | P | TAC 08088 |
| TER-C5506-401 | 8302090302* | 50-271 | P | TAC 47132 |
| TER-C5506-68/72 | 8112240161* | 50-277 | P | |
| TM-586 R04 | 8303290001 | 70-2926 | | DAT J-2437 |
| TR-010 R00 | 8303150272* | 50-289 | P | |
| TS 6575-2 RA | 8303110271* | 50-389 | A | |

# REPORT NUMBER INDEX

| REPORT NUMBER | ACCESSION NUMBER | SUBJECT CATEGORY | | OTHER REPORT NUMBER |
|---|---|---|---|---|
| UCID-19114 R01 | 8211050147* | 50-346 | P | |
| UNC-S-8000-NP V01R01 | 8303070096* | TOPREP | | |
| VEP-NQS-1 | 8303150288* | 50-280 | P | |
| WAPD-RED(C)-270 R02 | 8303180469* | 71-5074 | | 22022 |
| WCAP-10168 | 8303170516* | 50-250 | P | 58858 1/120382 |
| WCAP-10260 | 8303290385* | 50-416 | P | |
| WCAP-8587S1R0 ESE-27 | 8303250047* | TOPREP | | EQDP-ESE-27 |
| WCAP-8587S1R0 ESE-42 | 8303250045* | TOPREP | | EQDP-ESE-42 |
| WCAP-8587S1R0 ESE-48 | 8303250049* | TOPREP | | EQDP-ESE-48 |
| WCAP-8587S1R0 ESE-49 | 8303250044* | TOPREP | | EQDP-ESE-49 |
| WPPSS-QA-004 R07 | 8303080225* | TOPREP | | |
| YDQAP-1-A R12 | 8303150518* | 50-29 | P | |

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

| ACCESSION NUMBER | | | | |
|---|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
| 8103310185 | 8208060366 | 82/07/20 | 50-387 | P |
| 8104070367 | 8303240122 | 83/02/18 | FOIA | |
| 8104230095 | 8208060366 | 82/07/20 | 50-387 | P |
| 8104230100 | 8208060366 | 82/07/20 | 50-387 | P |
| 8108050060 | 8208060366 | 82/07/20 | 50-387 | P |
| 8108210338 | 8303240122 | 83/02/18 | FOIA | |
| 8108210447 | 8303240122 | 83/02/18 | FOIA | |
| 8108210490 | 8303240122 | 83/02/18 | FOIA | |
| 8108240174 | 8208060366 | 82/07/20 | 50-387 | P |
| 8110150329 | 8303240122 | 83/02/18 | FOIA | |
| 8110150356 | 8303240122 | 83/02/18 | FOIA | |
| 8111170263 | 8303240122 | 83/02/18 | FOIA | |
| 8111180081 | 8303020005 | 83/01/17 | 50-206 | P |
| 8112010615 | 8303240122 | 83/02/18 | FOIA | |
| 8112240161 | 8303150683 | 83/03/01 | 50-277 | P |
| 8201040114 | 8303240122 | 83/02/18 | FOIA | |
| 8201060494 | 8303240122 | 83/02/18 | FOIA | |
| 8201120008 | 8303090228 | 83/02/01 | FOIA | |
| 8201200407 | 8303240122 | 83/02/18 | FOIA | |
| 8201200538 | 8303240122 | 83/02/18 | FOIA | |
| 8201220233 | 8303020005 | 83/01/17 | 50-206 | P |
| 8201270341 | 8303240122 | 83/02/18 | FOIA | |
| 8202100501 | 8303100068 | 83/02/15 | 50-265 | S |
| 8202110128 | 8303020005 | 83/01/17 | 50-206 | P |
| 8202240261 | 8303020005 | 83/01/17 | 50-206 | P |
| 8203120424 | 8303230132 | 83/02/23 | 50-250 | G |
| 8203120425 | 8303230132 | 83/02/23 | 50-250 | G |
| 8203120426 | 8303230132 | 83/02/23 | 50-250 | G |
| 8203150315 | 8303090415 | 83/02/17 | FOIA | |
| 8203290497 | 8303140077 | 83/02/23 | 50-282 | P |
| 8204070025 | 8303090002 | 83/01/28 | FOIA | |
| 8204220451 | 8303240122 | 83/02/18 | FOIA | |
| 8205100335 | 8303100080 | 83/02/10 | 50-440 | A |
| 8205190297 | 8303020005 | 83/01/17 | 50-206 | P |
| * 8205200343 | 8303020005 | 83/01/17 | 50-206 | P |
| 8205200351 | 8303020005 | 83/01/17 | 50-206 | P |
| 8205240600 | 8303300659 | 83/03/04 | FOIA | |
| 8205240601 | 8303300659 | 83/03/04 | FOIA | |
| 8205270445 | 8303090398 | 83/02/23 | FOIA | |
| 8205270550 | 8303020005 | 83/01/17 | 50-206 | P |
| 8205280028 | 8303020005 | 83/01/17 | 50-206 | P |
| 8205280058 | 8303020005 | 83/01/17 | 50-206 | P |
| 8207050037 | 8303030382 | 83/02/23 | 50-275 | P |
| 8208040524 | 8303150072 | 83/03/02 | 50-346 | F |
| 8208050017 | 8303100080 | 83/02/10 | 50-440 | A |
| 8208120377 | 8303020005 | 83/01/17 | 50-206 | P |
| 8208230089 | 8303140585 | 83/02/28 | 70-754 | |
| 8208260154 | 8303010128 | 83/02/11 | 50-315 | P |
| 8208260515 | 8303230177 | 83/02/25 | FOIA | |
| 8208270667 | 8303230495 | 83/02/23 | 50-361 | P |

| ACCESSION NUMBER | | | | |
|---|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
| 8208310332 | 8303040385 | 83/02/17 | 50-277 | P |
| 8209030274 | 8303010598 | 83/02/23 | 50-213 | P |
| 8209210510 | 8303090443 | 83/02/16 | 50-373 | P |
| 8209280360 | 8303090002 | 83/01/28 | FOIA | |
| 8211010425 | 8212290096 | 82/12/03 | GEN TEC | IS |
| 8211020433 | 8303090279 | 83/03/07 | 50-313 | P |
| 8211020694 | 8303230132 | 83/02/23 | FOIA | |
| 8211040047 | 8303230132 | 83/02/23 | FOIA | |
| 8211050147 | 8303030398 | 83/02/17 | 50-346 | P |
| 8211060703 | 8303100006 | 83/02/14 | FOIA | |
| 8211090596 | 8303090443 | 83/02/16 | 50-373 | P |
| 8211090619 | 8211090617 | 82/10/26 | 50-358 | R |
| 8211110155 | 8303090443 | 83/02/16 | 50-373 | P |
| 8211110643 | 8303090443 | 83/02/16 | 50-373 | P |
| 8211120231 | 8303090443 | 83/02/16 | 50-373 | P |
| 8211170104 | 8303090443 | 83/02/16 | 50-373 | P |
| 8211180558 | 8303230487 | 83/02/24 | FOIA | |
| 8211190015 | 8303150143 | 83/03/01 | 50-295 | G |
| 8211300421 | 8303230177 | 83/02/25 | FOIA | |
| 8212010304 | 8303090443 | 83/02/16 | 50-373 | P |
| 8212020228 | 8303090443 | 83/02/16 | 50-373 | P |
| 8212020263 | 8303030134 | 83/02/16 | 50-29 | P |
| 8212130273 | 8303100107 | 83/02/15 | ACRS | |
| 8212150184 | 8303100491 | 83/02/25 | 50-358 | A |
| 8212160101 | 8303090443 | 83/02/16 | 50-373 | P |
| 8212210480 | 8303090443 | 83/02/16 | 50-373 | P |
| 8212220088 | 8303020053 | 82/12/31 | TOPREP | |
| 8212220095 | 8303020053 | 82/12/31 | TOPREP | |
| 8212220495 | 8212220501 | 82/12/09 | MISC | |
| 8212290054 | 8303100107 | 83/02/15 | ACRS | |
| 8212290059 | 8303100107 | 83/02/15 | ACRS | |
| 8212290099 | 8212290096 | 82/12/03 | GEN TEC | IS |
| 8212290442 | 8303100107 | 83/02/15 | 50-219 | O |
| 8212290471 | 8303100107 | 83/02/15 | ACRS | |
| 8301050367 | 8303110027 | 83/03/01 | 50-358 | A |
| 8301170075 | 8302170446 | 83/02/08 | 50-346 | P |
| 8301180041 | 8303100107 | 83/02/15 | 50-237 | O |
| 8301200157 | 8303040180 | 83/02/18 | COMMISSION | |
| 8301250065 | 8303100491 | 83/02/25 | 50-358 | A |
| 8301270005 | 8303090429 | 83/02/17 | FOIA | |
| 8301310266 | 8301310260 | 83/01/28 | 50-352 | A |
| 8301310270 | 8301310260 | 83/01/28 | 50-352 | F |
| 8301310284 | 8301310278 | 83/01/18 | 50-277 | G |
| 8301310290 | 8301310278 | 83/01/18 | 50-277 | G |
| 8302010011 | 8303150072 | 83/03/02 | 50-346 | F |
| 8302010106 | 8302010100 | 83/01/06 | 50-322 | A |
| 8302010358 | 8302010356 | 83/01/26 | 70-2837 | |
| 8302010596 | 8302010586 | 83/01/26 | 50-325 | S |
| 8302020153 | 8303080190 | 83/03/04 | 50-369 | P |
| 8302030448 | 8302030438 | 83/01/20 | 50-352 | G |

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

| ACCESSION NUMBER | | | | |
|---|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
| 8302040383 | 8302040379 | 83/01/19 | 50-447 | B |
| 8302040475 | 8302040471 | 83/01/21 | 71-9001 | |
| 8302040541 | 8208060366 | 82/07/20 | 50-387 | P |
| 8302040546 | 8208060366 | 82/07/20 | 50-387 | P |
| 8302040548 | 8208060366 | 82/07/20 | 50-387 | P |
| 8302040551 | 8208060366 | 82/07/20 | 50-387 | P |
| 8302040555 | 8208060366 | 82/07/20 | 50-387 | P |
| 8302040557 | 8208060366 | 82/07/20 | 50-387 | P |
| 8302040612 | 8303020005 | 83/01/17 | 50-206 | P |
| 8302070362 | 8302070360 | 83/01/24 | 50-348 | P |
| 8302090302 | 8303020411 | 83/02/22 | 50-271 | P |
| 8302090307 | 8303040267 | 83/02/22 | 50-250 | P |
| 8302100191 | 8303040004 | 83/02/23 | 50-413 | A |
| 8302100333 | 8302100331 | 83/01/17 | PR | |
| 8302100335 | 8302100331 | 83/01/17 | PR | |
| 8302150468 | 8302150454 | 83/02/02 | 50-339 | S |
| 8302150615 | 8302150605 | 83/02/03 | 50-366 | S |
| 8302150685 | 8302150674 | 83/01/31 | 50-361 | S |
| 8302160332 | 8302160328 | 83/02/14 | TOPREP | |
| 8302160446 | 8303230450 | 83/03/09 | 50-275 | P |
| 8302170236 | 8303240054 | 83/03/15 | REVIEW GRP | |
| 8302170451 | 8302170446 | 83/02/08 | 50-346 | P |
| 8302180128 | 8302180118 | 83/02/11 | 50-443 | G |
| 8302180219 | 8302180214 | 83/02/03 | 50-443 | G |
| 8302180224 | 8302180214 | 83/02/03 | 50-443 | G |
| 8302230319 | 8302230312 | 83/02/15 | 50-338 | S |
| 8302240210 | 8302240208 | 83/02/22 | 50-413 | K |
| 8302250060 | 8303290544 | 83/03/25 | 50-275 | G |
| 8302250124 | 8303290135 | 83/03/17 | 50-522 | A |
| 8302250202 | 8302250194 | 83/02/10 | 50-334 | S |
| 8302250330 | 8302250327 | 83/02/14 | 50-219 | S |
| 8302250332 | 8302250327 | 83/02/14 | 50-219 | S |
| 8302250335 | 8302250327 | 83/02/14 | 50-219 | S |
| 8302280085 | 8302280081 | 83/02/25 | 50-395 | F |
| 8302280137 | 8302280121 | 83/02/24 | 50-346 | K |
| 8302280361 | 8302280356 | 83/02/25 | 50-295 | G |
| 8302280487 | 8302280475 | 83/02/17 | 50-249 | S |
| 8303010003 | 8303010002 | 83/02/17 | 50-206 | P |
| 8303010007 | 8303010004 | 83/02/11 | 50-312 | P |
| 8303010009 | 8303010004 | 83/02/11 | 50-312 | P |
| 8303010011 | 8303010004 | 83/02/11 | 50-312 | P |
| 8303010018 | 8303010014 | 83/02/10 | CONTRACT | |
| 8303010036 | 8303010026 | 83/01/27 | 70-33 | |
| 8303010067 | 8303010066 | 83/02/04 | 70-734 | |
| 8303010070 | 8303010046 | 83/02/04 | 40-2061 | |
| 8303010072 | 8303010028 | 83/01/21 | 50-440 | G |
| 8303010075 | 8303010071 | 83/02/10 | 71-4 | |
| 8303010082 | 8303010078 | 83/02/25 | 50-443 | G |
| 8303010093 | 8303010088 | 83/02/11 | WASTE MGT | |
| 8303010107 | 8303010097 | 82/11/10 | WASTE MGT | |
| 8303010115 | 8303010109 | 83/02/15 | 50-508 | A |
| 8303010137 | 8303010134 | 83/02/07 | 50-400 | G |
| 8303010144 | 8303010131 | 83/02/22 | 50-395 | P |
| 8303010147 | 8303010139 | 82/12/22 | WASTE MGT | |
| 8303010153 | 8303010145 | 83/02/23 | 50-250 | G |
| 8303010157 | 8303010131 | 83/02/22 | 50-395 | P |
| 8303010160 | 8303010155 | 83/01/31 | 50-370 | G |
| 8303010166 | 8303010145 | 83/02/23 | 50-250 | G |
| 8303010168 | 8303010155 | 83/01/31 | 50-370 | G |
| 8303010169 | 8303010131 | 83/02/22 | 50-395 | P |
| 8303010183 | 8303010145 | 83/02/23 | 50-250 | G |
| 8303010185 | 8303010178 | 83/02/24 | 50-416 | S |
| 8303010195 | 8303010145 | 83/02/23 | 50-250 | G |
| 8303010197 | 8303010188 | 83/02/18 | 50-324 | S |
| 8303010201 | 8303010193 | 83/02/23 | 50-416 | S |
| 8303010209 | 8303010186 | 83/02/16 | 50-348 | G |
| 8303010211 | 8303010202 | 83/02/23 | 50-263 | G |
| 8303010213 | 8303010186 | 83/02/16 | 50-348 | G |
| 8303010215 | 8303010186 | 83/02/16 | 50-348 | G |
| 8303010216 | 8303010210 | 83/02/10 | 50-389 | G |
| 8303010218 | 8303010212 | 83/02/24 | 50-416 | S |
| 8303010221 | 8303010186 | 83/02/16 | 50-348 | G |
| 8303010222 | 8303010204 | 83/02/22 | 50-395 | S |
| 8303010224 | 8303010223 | 83/02/11 | 50-285 | G |
| 8303010227 | 8303010220 | 83/02/16 | 50-382 | G |
| 8303010230 | 8303010223 | 83/02/11 | 50-285 | G |
| 8303010233 | 8303010226 | 83/02/24 | 50-416 | S |
| 8303010235 | 8303010231 | 83/02/10 | 50-413 | G |
| 8303010247 | 8303010237 | 83/02/11 | 50-313 | G |
| 8303010249 | 8303010246 | 83/02/14 | 50-458 | G |

| ACCESSION NUMBER | | | | |
|---|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
| 8303010251 | 8303010245 | 83/02/10 | 50-302 | G |
| 8303010256 | 8303010244 | 83/02/18 | 50-317 | S |
| 8303010269 | 8303010264 | 83/02/18 | 50-302 | S |
| 8303010275 | 8303010271 | 83/02/21 | 50-325 | S |
| 8303010279 | 8303010272 | 83/02/18 | 50-302 | S |
| 8303010282 | 8303010278 | 83/02/21 | 50-324 | S |
| 8303010291 | 8303010283 | 83/02/22 | 50-395 | S |
| 8303010292 | 8303010277 | 83/02/24 | 50-305 | P |
| 8303010294 | 8303010287 | 83/03/01 | MISC | |
| 8303010295 | 8303010289 | 83/02/03 | 50-348 | G |
| 8303010300 | 8303010287 | 83/03/01 | MISC | |
| 8303010309 | 8303010297 | 83/02/25 | 50-454 | T |
| 8303010312 | 8303010306 | 83/02/25 | 50-454 | T |
| 8303010317 | 8303010306 | 83/02/25 | 50-454 | T |
| 8303010320 | 8303010306 | 83/02/25 | 50-454 | T |
| 8303010321 | 8303010313 | 82/11/17 | WASTE MGT | |
| 8303010324 | 8303010306 | 83/02/25 | 50-454 | T |
| 8303010325 | 8303010319 | 83/02/24 | 70-1507 | |
| 8303010328 | 8303010316 | 83/02/25 | 50-445 | G |
| 8303010331 | 8303010306 | 83/02/25 | 50-454 | T |
| 8303010334 | 8303010329 | 83/02/02 | 50-389 | G |
| 8303010335 | 8303010330 | 82/09/10 | 50-390 | G |
| 8303010336 | 8303010326 | 83/02/16 | 27-48 | |
| 8303010337 | 8303010306 | 83/02/25 | 50-454 | T |
| 8303010340 | 8303010306 | 83/02/25 | 50-454 | T |
| 8303010341 | 8303010330 | 82/09/10 | 50-390 | G |
| 8303010345 | 8303010306 | 83/02/25 | 50-454 | T |
| 8303010349 | 8303010343 | 83/02/24 | 50-416 | S |
| 8303010350 | 8303010346 | 82/10/07 | 50-390 | G |
| 8303010362 | 8303010357 | 83/02/03 | 50-397 | E |
| 8303010372 | 8303010365 | 83/02/16 | 50-244 | S |
| 8303010377 | 8303010373 | 83/02/18 | 50-325 | S |
| 8303010378 | 8303010368 | 83/02/04 | 50-389 | G |
| 8303010384 | 8303010381 | 83/02/18 | 50-325 | S |
| 8303010389 | 8303010273 | 83/02/11 | 50-267 | R |
| 8303010390 | 8303010386 | 83/02/16 | 50-245 | P |
| 8303010391 | 8303010388 | 83/02/23 | 50-244 | P |
| 8303010392 | 8303010388 | 83/02/23 | 50-244 | P |
| 8303010393 | 8303010387 | 83/02/18 | 50-318 | S |
| 8303010395 | 8303010385 | 83/02/14 | 50-247 | P |
| 8303010397 | 8303010385 | 83/02/14 | 50-247 | P |
| 8303010398 | 8303010383 | 83/02/02 | 50-438 | G |
| 8303010400 | 8303010394 | 83/02/18 | 50-324 | S |
| 8303010403 | 8303010297 | 83/02/25 | 50-454 | T |
| 8303010404 | 8303010402 | 83/02/18 | 50-29 | S |
| 8303010410 | 8303010405 | 83/02/16 | 50-298 | G |
| 8303010416 | 8303010414 | 83/02/03 | 50-261 | G |
| 8303010417 | 8303010415 | 83/02/23 | 50-313 | P |
| 8303010421 | 8303010419 | 83/02/22 | 50-275 | G |
| 8303010427 | 8303010424 | 83/02/10 | 50-382 | G |
| 8303010433 | 8303010429 | 83/02/10 | 50-327 | G |
| 8303010437 | 8303010432 | 83/02/02 | 50-348 | G |
| 8303010438 | 8303010429 | 83/02/10 | 50-327 | G |
| 8303010439 | 8303010431 | 83/02/25 | 50-352 | A |
| 8303010440 | 8303010434 | 83/02/15 | 50-219 | G |
| 8303010441 | 8303010436 | 83/02/18 | 50-271 | S |
| 8303010444 | 8303010435 | 83/02/23 | 50-338 | S |
| 8303010445 | 8303010429 | 83/02/10 | 50-327 | G |
| 8303010447 | 8303010431 | 83/02/25 | 50-352 | A |
| 8303010451 | 8303010442 | 83/02/11 | 50-445 | G |
| 8303010453 | 8303010429 | 83/02/10 | 50-327 | G |
| 8303010454 | 8303010450 | 83/02/03 | QA999 | |
| 8303010455 | 8303010446 | 83/02/18 | 50-2[illegible] | S |
| 8303010457 | 8303010449 | 83/02/21 | 50-395 | S |
| 8303010459 | 8303010456 | 83/02/02 | 70-143 | |
| 8303010465 | 8303010443 | 83/02/07 | 50-338 | G |
| 8303010468 | 8303010450 | 83/02/03 | QA999 | |
| 8303010469 | 8303010460 | 83/02/23 | 50-280 | S |
| 8303010470 | 8303010462 | 83/02/16 | 50-244 | S |
| 8303010471 | 8303010466 | 83/02/07 | 50-261 | G |
| 8303010473 | 8303010463 | 83/02/17 | 50-416 | G |
| 8303010474 | 8303010461 | 83/02/22 | 50-395 | S |
| 8303010480 | 8303010464 | 83/02/15 | 70-143 | |
| 8303010481 | 8303010463 | 83/02/17 | 50-416 | G |
| 8303010482 | 8303010476 | 83/01/31 | QA999 | |
| 8303010483 | 8303010475 | 83/02/04 | QA999 | |
| 8303010484 | 8303010472 | 83/02/18 | 50-309 | S |
| 8303010486 | 8303010477 | 83/02/18 | 50-325 | S |
| 8303010487 | 8303010478 | 83/02/16 | 50-244 | S |
| 8303010488 | 8303010476 | 83/01/31 | QA999 | |

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS



| ACCESSION NUMBER ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
|---|---|---|---|---|
| 8303010489 | 8303010479 | 83/02/25 | 50-390 | Q |
| 8303010491 | 8303010463 | 83/02/17 | 50-416 | Q |
| 8303010493 | 8303010490 | 83/02/22 | 50-331 | R |
| 8303010497 | 8303010463 | 83/02/17 | 50-416 | Q |
| 8303010498 | 8303010476 | 83/01/31 | 0A999 | |
| 8303010500 | 8303010463 | 83/02/17 | 50-416 | Q |
| 8303010501 | 8303010494 | 83/02/10 | 50-416 | Q |
| 8303010502 | 8303010492 | 83/02/16 | 50-309 | S |
| 8303010507 | 8303010495 | 83/02/22 | 50-395 | S |
| 8303010508 | 8303010463 | 83/02/17 | 50-416 | Q |
| 8303010515 | 8303010504 | 83/02/17 | 50-309 | S |
| 8303010519 | 8303010509 | 83/02/23 | 50-368 | Q |
| 8303010520 | 8303010512 | 83/02/17 | 50-321 | Q |
| 8303010522 | 8303010514 | 83/02/18 | 50-324 | S |
| 8303010523 | 8303010511 | 83/02/02 | 50-327 | Q |
| 8303010524 | 8303010485 | 83/02/16 | 50-416 | Q |
| 8303010526 | 8303010512 | 83/02/17 | 50-321 | Q |
| 8303010530 | 8303010512 | 83/02/17 | 50-321 | Q |
| 8303010535 | 8303010527 | 83/02/24 | 50-298 | F |
| 8303010536 | 8303010528 | 83/02/24 | 50-317 | P |
| 8303010537 | 8303010512 | 83/02/17 | 50-321 | Q |
| 8303010538 | 8303010532 | 83/02/16 | 50-400 | Q |
| 8303010542 | 8303010521 | 83/02/18 | 50-318 | S |
| 8303010543 | 8303010532 | 83/02/16 | 50-400 | Q |
| 8303010548 | 8303010485 | 83/02/16 | 50-416 | Q |
| 8303010549 | 8303010532 | 83/02/16 | 50-400 | Q |
| 8303010553 | 8303010532 | 83/02/16 | 50-400 | Q |
| 8303010558 | 8303010485 | 83/02/16 | 50-416 | Q |
| 8303010560 | 8303010554 | 83/02/25 | 50-112 | Q |
| 8303010566 | 8303010556 | 83/02/22 | 50-395 | S |
| 8303010567 | 8303010561 | 83/02/18 | 50-387 | S |
| 8303010571 | 8303010562 | 83/02/18 | 50-369 | S |
| 8303010574 | 8303010485 | 83/02/16 | 50-416 | Q |
| 8303010577 | 8303010569 | 83/02/18 | 50-397 | S |
| 8303010582 | 8303010569 | 83/02/18 | 50-397 | S |
| 8303010585 | 8303010570 | 83/02/10 | 50-335 | Q |
| 8303010587 | 8303010579 | 83/02/11 | 50-458 | Q |
| 8303010589 | 8303010569 | 83/02/18 | 50-397 | S |
| 8303010590 | 8303010485 | 83/02/16 | 50-416 | Q |
| 8303010593 | 8303010584 | 83/02/15 | 70-143 | |
| [illegible]010602 | 8303010594 | 83/02/18 | 50-339 | S |
| [illegible]010603 | 8303010575 | 83/02/18 | 50-155 | P |
| [illegible]010604 | 8303010597 | 83/02/18 | 50-250 | Q |
| 83[illegible]010607 | 8303010600 | 82/11/17 | 50-382 | A |
| 8303010608 | 8303010596 | 83/02/02 | 50-369 | Q |
| 8303010609 | 8303010575 | 83/02/18 | 50-155 | P |
| 8303010610 | 8303010597 | 83/02/18 | 50-250 | Q |
| 8303010615 | 8303010575 | 83/02/18 | 50-155 | P |
| 8303010618 | 8303010595 | 83/02/24 | 50-10 | F |
| 8303010619 | 8303010597 | 83/02/18 | 50-250 | Q |
| 8303010620 | 8303010611 | 83/02/22 | 50-387 | S |
| 8303010621 | 8303010614 | 83/02/15 | 70-1113 | |
| 8303010623 | 8303010597 | 83/02/18 | 50-250 | Q |
| 8303010626 | 8303010622 | 83/02/16 | 70-27 | |
| 8303010630 | 8303010597 | 83/02/18 | 50-250 | Q |
| 8303010632 | 8303010612 | 83/02/23 | 70-734 | |
| 8303010635 | 8303010625 | 83/02/14 | 50-275 | S |
| 8303010638 | 8303010629 | 83/02/18 | 50-29 | S |
| 8303010645 | 8303010634 | 83/01/28 | 50-280 | Q |
| 8303010648 | 8303010640 | 83/02/07 | 50-335 | Q |
| 8303010654 | 8303010646 | 83/02/15 | 50-272 | Q |
| 8303010655 | 8303010643 | 83/02/18 | 50-280 | Q |
| 8303010659 | 8303010651 | 83/02/18 | 50-387 | S |
| 8303010661 | 8303010643 | 83/02/18 | 50-280 | Q |
| 8303010665 | 8303010643 | 83/02/18 | 50-280 | Q |
| 8303010667 | 8303010646 | 83/02/15 | 50-272 | Q |
| 8303010671 | 8303010662 | 83/02/22 | 50-295 | S |
| 8303010672 | 8303010660 | 83/01/18 | 50-250 | Q |
| 8303010673 | 8303010643 | 83/02/18 | 50-280 | Q |
| 8303010676 | 8303010670 | 83/02/18 | 50-220 | S |
| 8303010678 | 8303010660 | 83/01/18 | 50-250 | Q |
| 8303010679 | 8303010674 | 83/02/18 | 50-29 | S |
| 8303010681 | 8303010677 | 83/02/22 | 50-250 | Q |
| 8303010685 | 8303010682 | 83/02/25 | 50-313 | Q |
| 8303010688 | 8303010684 | 83/02/15 | 50-397 | K |
| 8303010714 | 8303010712 | 83/02/15 | CONTRACT | |
| 8303010730 | 8303010721 | 83/02/18 | CONTRACT | |
| 8303020006 | 8303020002 | 83/02/28 | 50-329 | T |
| 8303020007 | 8303020004 | 83/02/24 | 50-373 | P |
| 8303020011 | 8303020002 | 83/02/28 | 50-329 | T |

| ACCESSION NUMBER ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
|---|---|---|---|---|
| 8303020014 | 8303020010 | 83/02/28 | 50-321 | P |
| 8303020015 | 8303020008 | 83/02/25 | 50-333 | P |
| 8303020017 | 8303020005 | 83/01/17 | FOIA | |
| 8303020018 | 8303020012 | 83/02/24 | 50-373 | P |
| 8303020020 | 8303020013 | 83/02/25 | 50-315 | P |
| 8303020021 | 8303020008 | 83/02/25 | 50-333 | P |
| 8303020031 | 8303020025 | 83/02/28 | 50-271 | P |
| 8303020039 | 8303020029 | 83/02/28 | 50-352 | A |
| 8303020040 | 8303020005 | 83/01/17 | 50-206 | P |
| 8303020042 | 8303020029 | 83/02/28 | 50-352 | C |
| 8303020047 | 8303020029 | 83/02/28 | 50-352 | K |
| 8303020049 | 8303020045 | 83/02/22 | 50-124 | R |
| 8303020051 | 8303020048 | 83/01/28 | PRM | |
| 8303020052 | 8303020046 | 83/02/25 | 50-247 | Q |
| 8303020058 | 8303020054 | 83/02/16 | PRM | |
| 8303020059 | 8303020053 | 82/12/31 | TOPREP | |
| 8303020062 | 8303020060 | 83/02/11 | 50-321 | F |
| 8303020065 | 8303020053 | 82/12/31 | TOPREP | |
| 8303020072 | 8303020068 | 83/01/07 | CONTRACT | |
| 8303020079 | 8303020074 | 83/02/18 | 50-373 | Q |
| 8303020082 | 8303020077 | 83/02/10 | CONTRACT | |
| 8303020088 | 8303020005 | 83/01/17 | FOIA | |
| 8303020091 | 8303020086 | 83/02/28 | 50-389 | K |
| 8303020096 | 8303020093 | 83/02/22 | 50-247 | T |
| 8303020100 | 8303020093 | 83/02/22 | 50-247 | T |
| 8303020105 | 8303020093 | 83/02/22 | 50-247 | T |
| 8303020109 | 8303020102 | 83/02/23 | 50-275 | P |
| 8303020110 | 8303020093 | 83/02/22 | 50-247 | T |
| 8303020114 | 8303020103 | 83/02/22 | 50-293 | R |
| 8303020116 | 8303020093 | 83/02/22 | 50-247 | T |
| 8303020119 | 8303020115 | 83/02/10 | 50-275 | P |
| 8303020120 | 8303020093 | 83/02/22 | 50-247 | T |
| 8303020124 | 8303020093 | 83/02/22 | 50-247 | T |
| 8303020126 | 8303020093 | 83/02/22 | 50-247 | T |
| 8303020130 | 8303020093 | 83/02/22 | 50-247 | T |
| 8303020133 | 8303020093 | 83/02/22 | 50-247 | T |
| 8303020152 | 8303020149 | 83/02/22 | 50-413 | E |
| 8303020155 | 8303020005 | 83/01/17 | 50-206 | P |
| 8303020157 | 8303020005 | 83/01/17 | FOIA | |
| 8303020161 | 8303240109 | 83/03/16 | REVIEW GRP | |
| 8303020177 | 8303020176 | 83/02/22 | CONTRACT | |
| 8303020189 | 8303020185 | 83/02/16 | 50-336 | S |
| 8303020202 | 8303020199 | 83/01/24 | FOIA | |
| 8303020206 | 8303020200 | 83/01/28 | 27-48 | |
| 8303020207 | 8303020203 | 83/02/14 | 50-250 | F |
| 8303020222 | 8303020217 | 83/01/21 | 70-364 | |
| 8303020227 | 8303020217 | 83/01/21 | 70-364 | |
| 8303020304 | 8303020299 | 83/02/10 | COMMISSION | |
| 8303020324 | 8303020318 | 83/02/10 | XPORTLIC | |
| 8303020337 | 8303020332 | 83/02/22 | XPORTLIC | |
| 8303020392 | 8303020385 | 83/02/17 | 50-346 | P |
| 8303020394 | 8303020389 | 83/02/22 | 50-375 | W |
| 8303020397 | 8303020385 | 83/02/17 | 50-346 | P |
| 8303020400 | 8303020389 | 83/02/22 | 50-375 | W |
| 8303020403 | 8303020389 | 83/02/22 | 50-375 | W |
| 8303020407 | 8303020389 | 83/02/22 | 50-375 | W |
| 8303020416 | 8303020385 | 83/02/17 | 50-346 | P |
| 8303020417 | 8303020413 | 83/02/17 | 50-346 | P |
| 8303020423 | 8303020420 | 83/02/18 | 50-277 | P |
| 8303020426 | 8303020420 | 83/02/18 | 50-277 | P |
| 8303020429 | 8303020420 | 83/02/18 | 50-277 | P |
| 8303020435 | 8303020413 | 83/02/17 | 50-346 | P |
| 8303020437 | 8303020413 | 83/02/17 | 50-346 | P |
| 8303020441 | 8303020432 | 83/02/22 | 50-315 | P |
| 8303020448 | 8303020432 | 83/02/22 | 50-315 | P |
| 8303020461 | 8303020454 | 83/02/24 | 50-387 | P |
| 8303020466 | 8303020454 | 83/02/24 | 50-387 | P |
| 8303020468 | 8303020454 | 83/02/24 | 50-387 | P |
| 8303020481 | 8303020480 | 83/02/25 | CONTRACT | |
| 8303030006 | 8303030003 | 83/01/26 | 50-201 | P |
| 8303030014 | 8303030009 | 83/02/22 | 50-311 | S |
| 8303030064 | 8303030045 | 83/02/16 | 50-271 | S |
| 8303030068 | 8303030063 | 83/02/14 | 50-259 | P |
| 8303030071 | 8303030062 | 83/02/25 | CONTRACT | |
| 8303030075 | 8303030063 | 83/02/14 | 50-259 | P |
| 8303030085 | 8303030063 | 83/02/14 | 50-259 | P |
| 8303030088 | 8303030083 | 83/02/28 | 50-305 | R |
| 8303030126 | 8303030118 | 83/02/16 | 50-272 | S |
| 8303030136 | 8303030129 | 83/02/18 | 50-244 | Q |
| 8303030141 | 8303030134 | 83/02/16 | 50-29 | P |

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

| ACCESSION NUMBER | | | |
|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 8303030143 | 8303030135 | 83/02/22 | 50-213 S |
| 8303030145 | 8303030134 | 83/02/16 | 50-29 P |
| 8303030153 | 8303030134 | 83/02/16 | 50-29 P |
| 8303030166 | 8303030156 | 83/02/18 | 50-272 G |
| 8303030175 | 8303030144 | 83/02/16 | 50-423 G |
| 8303030177 | 8303030172 | 83/02/18 | 50-245 G |
| 8303030178 | 8303020368 | 83/02/23 | XPORTLIC |
| 8303030179 | 8303030170 | 83/02/17 | 50-361 P |
| 8303030180 | 8303030165 | 83/02/17 | 70-359 |
| 8303030183 | 8303030144 | 83/02/16 | 50-423 G |
| 8303030184 | 8303030172 | 83/02/18 | 50-245 G |
| 8303030185 | 8303030181 | 83/02/18 | 50-293 G |
| 8303030186 | 8303030170 | 83/02/17 | 50-361 P |
| 8303030188 | 8303030182 | 83/02/18 | 50-334 G |
| 8303030191 | 8303030176 | 83/02/09 | 50-387 H |
| 8303030194 | 8303020368 | 83/02/23 | XPORTLIC |
| 8303030197 | 8303030190 | 83/02/28 | 50-155 P |
| 8303030199 | 8303030195 | 83/02/17 | 50-348 P |
| 8303030201 | 8303030189 | 83/02/18 | 50-245 G |
| 8303030202 | 8303030182 | 83/02/18 | 50-334 G |
| 8303030203 | 8303030190 | 83/02/28 | 50-155 P |
| 8303030205 | 8303030195 | 83/02/17 | 50-348 P |
| 8303030206 | 8303030198 | 83/02/18 | 50-320 G |
| 8303030207 | 8303030190 | 83/02/28 | 50-155 P |
| 8303030210 | 8303030195 | 83/02/17 | 50-348 P |
| 8303030214 | 8303030212 | 83/02/24 | 50-151 R |
| 8303030218 | 8303030215 | 83/02/23 | 50-416 P |
| 8303030220 | 8303030213 | 83/02/23 | 50-321 R |
| 8303030223 | 8303030047 | 83/02/25 | 50-320 P |
| 8303030228 | 8303030213 | 83/02/23 | 50-321 R |
| 8303030231 | 8303030222 | 83/02/23 | CONTRACT |
| 8303030237 | 8303030208 | 83/01/25 | 71-4909 |
| 8303030243 | 8303030233 | 83/02/23 | 71-9783 |
| 8303030244 | 8303030238 | 83/01/05 | CONTRACT |
| 8303030254 | 8303030246 | 83/02/16 | 50-317 G |
| 8303030256 | 8303030252 | 83/01/17 | CONTRACT |
| 8303030267 | 8303030263 | 83/02/24 | CONTRACT |
| 8303030268 | 8303030246 | 83/02/16 | 50-317 G |
| 8303030271 | 8303030208 | 83/01/25 | 71-4909 |
| 8303030272 | 8303030257 | 83/02/22 | 50-272 S |
| 8303030305 | 8303030298 | 83/02/17 | 50-286 G |
| 8303030308 | 8303030292 | 83/02/18 | 50-272 S |
| 8303030312 | 8303030298 | 83/02/17 | 50-286 G |
| 8303030330 | 8303030322 | 83/02/15 | TOPREP |
| 8303030341 | 8303030336 | 83/02/15 | TOPREP |
| 8303030342 | 8303030335 | 83/02/22 | CONTRACT |
| 8303030350 | 8303030345 | 83/02/25 | 50-247 H |
| 8303030355 | 8303030347 | 83/02/17 | 50-275 U |
| 8303030359 | 8303030353 | 83/02/17 | 50-410 G |
| 8303030364 | 8303030360 | 83/02/15 | 50-322 G |
| 8303030368 | 8303030357 | 83/02/28 | 50-454 T |
| 8303030370 | 8303030348 | 83/02/22 | CONTRACT |
| 8303030383 | 8303030377 | 83/02/22 | CONTRACT |
| 8303030391 | 8303030382 | 83/02/23 | 50-275 P |
| 8303030395 | 8303030382 | 83/02/23 | 50-275 P |
| 8303030400 | 8303030382 | 83/02/23 | 50-275 P |
| 8303030408 | 8303030401 | 83/02/16 | 50-220 G |
| 8303030409 | 8303030398 | 83/02/17 | 50-346 P |
| 8303030413 | 8303030403 | 83/02/28 | 50-329 T |
| 8303030424 | 8303030398 | 83/02/17 | 50-346 P |
| 8303030430 | 8303030411 | 83/02/28 | 50-458 C |
| 8303030434 | 8303030411 | 83/02/28 | 50-458 K |
| 8303030446 | 8303030439 | 83/02/16 | 50-10 G |
| 8303030453 | 8303030452 | 83/02/25 | 50-483 G |
| 8303030457 | 8303030456 | 83/02/15 | 50-263 G |
| 8303030467 | 8303030458 | 83/03/01 | 50-354 F |
| 8303030470 | 8303030458 | 83/03/01 | 50-354 A |
| 8303030473 | 8303030472 | 83/02/25 | 50-255 G |
| 8303030513 | 8303030511 | 83/02/24 | CONTRACT |
| 8303030521 | 8303030508 | 83/02/24 | 70-2945 |
| 8303030522 | 8303030398 | 83/02/17 | 50-346 P |
| 8303030523 | 8303030518 | 83/02/22 | 50-368 S |
| 8303030524 | 8303030458 | 83/03/01 | 50-354 M |
| 8303030527 | 8303030458 | 83/03/01 | 50-354 K |
| 8303030532 | 8303030458 | 83/03/01 | 50-354 C |
| 8303030538 | 8303030529 | 83/02/28 | QA999 |
| 8303030540 | 8303030530 | 83/02/25 | 50-373 G |
| 8303030543 | 8303030535 | 83/02/25 | 50-305 G |
| 8303030547 | 8303030529 | 83/02/28 | QA999 |
| 8303030584 | 8303030567 | 83/02/15 | 70-1308 |

| ACCESSION NUMBER | | | |
|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 8303030598 | 8303030591 | 83/02/16 | 50-266 G |
| 8303030627 | 8303030620 | 83/02/22 | 50-331 S |
| 8303030629 | 8303030614 | 83/02/22 | 50-368 S |
| 8303030632 | 8303030626 | 83/02/10 | 50-456 G |
| 8303030634 | 8303030619 | 83/02/14 | 50-315 G |
| 8303030636 | 8303030624 | 83/02/17 | 50-255 G |
| 8303030641 | 8303030626 | 83/02/10 | 50-456 G |
| 8303030642 | 8303030637 | 83/02/28 | QA999 |
| 8303030650 | 8303030624 | 83/02/17 | 50-255 G |
| 8303030651 | 8303030647 | 83/02/28 | 50-470 E |
| 8303030654 | 8303030652 | 83/03/02 | 50-537 B |
| 8303030655 | 8303030647 | 83/02/28 | 50-470 E |
| 8303030662 | 8303030644 | 83/02/16 | 50-272 G |
| 8303030665 | 8303030664 | 83/02/18 | 50-331 S |
| 8303030675 | 8303030670 | 83/02/28 | 50-309 P |
| 8303030680 | 8303030672 | 83/02/25 | CONTRACT |
| 8303030681 | 8303030673 | 83/02/15 | 50-318 S |
| 8303030687 | 8303030679 | 83/02/22 | 40-8698 |
| 8303030690 | 8303030683 | 83/02/25 | 50-186 G |
| 8303030691 | 8303030685 | 83/02/25 | 50-456 G |
| 8303030718 | 8303030714 | 83/02/15 | CONTRACT |
| 8303030735 | 8303030731 | 83/02/18 | 50-289 P |
| 8303030741 | 8303030731 | 83/02/18 | 50-289 P |
| 8303030765 | 8303030747 | 83/02/17 | 50-275 P |
| 8303030766 | 8303030763 | 83/02/23 | CONTRACT |
| 8303030775 | 8303030769 | 83/01/27 | CONTRACT |
| 8303030782 | 8303030774 | 83/02/25 | CONTRACT |
| 8303030789 | 8303030780 | 83/02/23 | 50-329 A |
| 8303030792 | 8303030780 | 83/02/23 | 50-329 A |
| 8303040024 | 8303040015 | 83/02/22 | 50-329 A |
| 8303040032 | 8303040015 | 83/02/22 | 50-329 A |
| 8303040041 | 8303040015 | 83/02/22 | 50-329 A |
| 8303040060 | 8303040055 | 83/02/07 | XPORTLIC |
| 8303040062 | 8303040057 | 83/02/18 | 50-261 P |
| 8303040066 | 8303040051 | 83/01/31 | 71-9074 |
| 8303040068 | 8303040055 | 83/02/07 | XPORTLIC |
| 8303040076 | 8303040057 | 83/02/18 | 50-261 P |
| 8303040080 | 8303040074 | 83/01/28 | 71-9160 |
| 8303040088 | 8303040074 | 83/01/28 | 71-9160 |
| 8303040099 | 8303040074 | 83/01/28 | 71-9160 |
| 8303040106 | 8303040074 | 83/01/28 | 71-9160 |
| 8303040116 | 8303040113 | 83/02/24 | 71-492 |
| 8303040120 | 8303040115 | 83/02/24 | 50-309 S |
| 8303040125 | 8303040115 | 83/02/24 | 50-309 S |
| 8303040147 | 8303040142 | 83/02/28 | 50-170 U |
| 8303040151 | 8303040137 | 83/02/18 | 50-275 H |
| 8303040172 | 8303040160 | 83/02/18 | 50-320 U |
| 8303040185 | 8303040181 | 83/02/15 | COMMISSION |
| 8303040187 | 8303040178 | 83/02/25 | 50-213 P |
| 8303040198 | 8303040194 | 83/02/10 | COMMISSION |
| 8303040214 | 8303040204 | 83/02/22 | 10CFR |
| 8303040217 | 8303040211 | 83/02/15 | State Prog |
| 8303040223 | 8303040204 | 83/02/22 | 10CFR |
| 8303040230 | 8303040224 | 83/02/22 | 50-361 P |
| 8303040233 | 8303040204 | 83/02/22 | 10CFR |
| 8303040241 | 8303040237 | 83/02/23 | 50-321 P |
| 8303040244 | 8303040100 | 83/02/18 | COMMISSION |
| 8303040292 | 8303040281 | 83/02/25 | CONTRACT |
| 8303040310 | 8303040299 | 83/02/18 | COMMISSION |
| 8303040322 | 8303040316 | 82/05/24 | 71-9133 |
| 8303040323 | 8303040318 | 83/02/25 | 50-348 S |
| 8303040325 | 8303040319 | 83/02/25 | 50-416 S |
| 8303040326 | 8303040321 | 83/02/14 | 70-2932 |
| 8303040331 | 8303040321 | 83/02/14 | 70-2932 |
| 8303040334 | 8303040329 | 83/02/25 | 50-348 S |
| 8303040351 | 8303040347 | 83/02/25 | 50-461 K |
| 8303040353 | 8303040348 | 83/02/25 | 50-313 P |
| 8303040361 | 8303040355 | 83/02/24 | 50-528 G |
| 8303040362 | 8303040357 | 83/02/15 | 50-344 G |
| 8303040363 | 8303040358 | 83/02/25 | 50-416 S |
| 8303040371 | 8303040366 | 83/02/18 | 50-397 G |
| 8303040376 | 8303040367 | 83/02/23 | 50-395 S |
| 8303040377 | 8303040366 | 83/02/18 | 50-397 G |
| 8303040380 | 8303040365 | 83/02/22 | 50-324 S |
| 8303040382 | 8303040375 | 83/02/18 | 50-334 S |
| 8303040389 | 8303040381 | 83/02/24 | 50-296 S |
| 8303040391 | 8303040385 | 83/02/17 | 50-277 P |
| 8303040395 | 8303040374 | 83/02/24 | 50-296 S |
| 8303040408 | 8303040401 | 83/02/14 | 50-293 R |
| 8303040410 | 8303040402 | 83/02/25 | 50-320 P |

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS



| ACCESSION NUMBER | | | |
|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 8303040414 | 8303040404 | 83/02/15 | 50-206 G |
| 8303040417 | 8303040402 | 83/02/25 | 50-320 P |
| 8303040421 | 8303040409 | 83/02/11 | 50-275 G |
| 8303040425 | 8303040420 | 83/02/25 | 50-416 S |
| 8303040431 | 8303040430 | 83/02/24 | 50-302 S |
| 8303040433 | 8303040426 | 83/02/25 | 50-260 S |
| 8303040438 | 8303040434 | 83/02/24 | 50-328 S |
| 8303040442 | 8303040437 | 83/02/22 | 50-333 R |
| 8303040446 | 8303040436 | 83/02/16 | 50-344 G |
| 8303040453 | 8303040449 | 83/02/11 | 50-460 C |
| 8303040454 | 8303040447 | 83/02/11 | 50-275 G |
| 8303040456 | 8303040450 | 83/02/22 | 50-29 S |
| 8303040461 | 8303040451 | 83/02/15 | 50-397 G |
| 8303040462 | 8303040459 | 83/02/28 | 50-322 G |
| 8303040471 | 8303040466 | 83/03/01 | 50-285 R |
| 8303040472 | 8303040465 | 83/02/24 | 50-328 S |
| 8303040473 | 8303040468 | 83/02/15 | 50-245 G |
| 8303040480 | 8303040475 | 83/02/24 | 50-338 R |
| 8303040498 | 8303040484 | 83/02/02 | 50-364 G |
| 8303040493 | 8303040487 | 83/02/28 | 50-423 C |
| 8303040496 | 8303040487 | 83/02/28 | 50-423 K |
| 8303040497 | 8303040492 | 83/02/24 | 50-259 S |
| 8303040501 | 8303040500 | 83/03/01 | 50-454 G |
| 8303040504 | 8303040498 | 83/02/28 | 50-416 S |
| 8303040508 | 8303040506 | 83/03/01 | 50-416 S |
| 8303040521 | 8303040519 | 83/02/22 | 50-255 G |
| 8303040526 | 8303040520 | 83/02/17 | 50-362 S |
| 8303040527 | 8303040519 | 83/02/22 | 50-255 G |
| 8303040533 | 8303040518 | 83/02/25 | State Prog |
| 8303040537 | 8303040528 | 83/02/17 | 70-1135 |
| 8303040538 | 8303040530 | 83/02/25 | 50-266 R |
| 8303040540 | 8303040532 | 83/02/22 | 50-483 G |
| 8303040543 | 8303040518 | 83/02/25 | State Prog |
| 8303040549 | 8303040541 | 83/03/01 | 50-416 S |
| 8303040550 | 8303040535 | 83/02/28 | GA999 |
| 8303040551 | 8303040529 | 83/02/28 | 50-324 P |
| 8303040555 | 8303040547 | 83/02/28 | 50-293 P |
| 8303040560 | 8303040535 | 83/02/28 | GA999 |
| 8303040562 | 8303040556 | 83/02/03 | GA999 |
| 8303040565 | 8303040553 | 83/02/23 | 50-395 S |
| 8303040569 | 8303040558 | 83/02/28 | 50-259 S |
| 8303040572 | 8303040556 | 83/02/03 | GA999 |
| 8303040573 | 8303040567 | 83/02/17 | 50-362 S |
| 8303040574 | 8303040566 | 83/02/15 | 50-295 G |
| 8303040582 | 8303040535 | 83/02/28 | GA999 |
| 8303040584 | 8303040568 | 83/02/28 | 50-280 S |
| 8303040586 | 8303040579 | 83/02/16 | 50-327 S |
| 8303040587 | 8303040581 | 83/02/25 | 50-219 R |
| 8303040588 | 8303040575 | 83/02/24 | 50-328 S |
| 8303040589 | 8303040577 | 83/02/18 | 50-362 S |
| 8303040596 | 8303040591 | 83/02/22 | 50-454 G |
| 8303040600 | 8303040583 | 83/02/16 | 50-344 G |
| 8303040605 | 8303040585 | 83/03/02 | 50-324 P |
| 8303040606 | 8303040598 | 83/02/28 | GA999 |
| 8303040610 | 8303040604 | 83/02/25 | 50-213 P |
| 8303040613 | 8303040602 | 83/02/17 | 50-362 S |
| 8303040616 | 8303040608 | 83/02/17 | 50-362 S |
| 8303040624 | 8303040618 | 83/02/18 | 50-361 S |
| 8303040626 | 8303040620 | 83/03/01 | 50-416 S |
| 8303040633 | 8303040625 | 83/03/03 | 50-445 G |
| 8303040634 | 8303040390 | 83/02/10 | 50-272 R |
| 8303040636 | 8303040629 | 83/02/15 | 50-361 S |
| 8303040643 | 8303040640 | 83/03/02 | TOPREP |
| 8303040644 | 8303040640 | 83/03/02 | TOPREP |
| 8303040646 | 8303040645 | 83/02/23 | 50-275 P |
| 8303040647 | 8303040645 | 83/02/23 | 50-275 P |
| 8303040649 | 8303040645 | 83/02/23 | 50-275 P |
| 8303040651 | 8303040645 | 83/02/23 | 50-275 P |
| 8303040654 | 8303040653 | 83/02/23 | 50-70 P |
| 8303040655 | 8303040653 | 83/02/23 | 50-70 P |
| 8303040656 | 8303040653 | 83/02/23 | 50-70 P |
| 8303070027 | 8303070023 | 83/02/09 | GA999 |
| 8303070037 | 8303070032 | 83/02/07 | GA999 |
| 8303070044 | 8303070032 | 83/02/07 | GA999 |
| 8303070046 | 8303070041 | 83/02/24 | 50-334 S |
| 8303070049 | 8303070034 | 83/03/01 | 50-454 T |
| 8303070054 | 8303070034 | 83/03/01 | 50-454 T |
| 8303070070 | 8303070058 | 83/01/31 | 50-528 A |
| 8303070072 | 8303070065 | 83/02/28 | 50-387 F |
| 8303070078 | 8303070069 | 83/02/07 | GA999 |

| ACCESSION NUMBER | | | |
|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 8303070085 | 8303070069 | 83/02/07 | GA999 |
| 8303070088 | 8303070075 | 83/02/10 | 50-267 G |
| 8303070089 | 8303070080 | 83/02/28 | 50-387 P |
| 8303070096 | 8303070087 | 83/02/18 | TOPREP |
| 8303070104 | 8303070099 | 83/03/01 | 50-220 P |
| 8303070105 | 8303070099 | 83/03/01 | 50-220 P |
| 8303070114 | 8303070107 | 83/02/07 | GA999 |
| 8303070120 | 8303070112 | 83/03/04 | 50-537 A |
| 8303070121 | 8303070115 | 83/02/25 | 50-293 P |
| 8303070126 | 8303070107 | 83/02/07 | GA999 |
| 8303070129 | 8303070124 | 83/02/16 | GA999 |
| 8303070136 | 8303070124 | 83/02/16 | GA999 |
| 8303070140 | 8303070098 | 83/03/03 | GA999 |
| 8303070143 | 8303070098 | 83/03/03 | GA999 |
| 8303070145 | 8303070139 | 83/03/04 | 50-289 G |
| 8303070147 | 8303070098 | 83/03/03 | GA999 |
| 8303070150 | 8303070146 | 83/02/21 | TOPREP |
| 8303070151 | 8303070135 | 83/02/28 | 50-10 I |
| 8303070152 | 8303070141 | 83/02/28 | 50-413 A |
| 8303070153 | 8303070144 | 83/03/03 | GA999 |
| 8303070157 | 8303070146 | 83/02/21 | TOPREP |
| 8303070158 | 8303070141 | 83/02/28 | 50-413 A |
| 8303070159 | 8303070148 | 83/02/24 | 50-334 S |
| 8303070164 | 8303070141 | 83/02/28 | 50-413 A |
| 8303070165 | 8303070101 | 83/03/03 | GA999 |
| 8303070167 | 8303070141 | 83/02/28 | 50-413 A |
| 8303070168 | 8303070101 | 83/03/03 | GA999 |
| 8303070169 | 8303070141 | 83/02/28 | 50-413 A |
| 8303070171 | 8303070101 | 83/03/03 | GA999 |
| 8303070172 | 8303070101 | 83/03/03 | GA999 |
| 8303070173 | 8303070141 | 83/02/28 | 50-413 A |
| 8303080007 | 8303080002 | 83/02/24 | 50-387 S |
| 8303080010 | 8303080008 | 83/03/04 | 50-356 K |
| 8303080013 | 8303080012 | 83/01/07 | 50-309 R |
| 8303080017 | 8303080006 | 83/03/07 | 50-275 T |
| 8303080020 | 8303080015 | 83/02/22 | 40-8681 |
| 8303080021 | 8303080016 | 83/01/11 | 50-259 R |
| 8303080022 | 8303080018 | 83/01/13 | 50-213 R |
| 8303080032 | 8303080023 | 83/02/18 | 50-263 G |
| 8303080033 | 8303080028 | 83/01/05 | 50-155 R |
| 8303080036 | 8303080031 | 83/03/02 | 50-275 R |
| 8303080037 | 8303080035 | 83/01/14 | 50-280 R |
| 8303080039 | 8303080029 | 83/02/15 | 50-302 R |
| 8303080042 | 8303080023 | 83/02/18 | 50-263 G |
| 8303080045 | 8303080029 | 83/02/15 | 50-302 R |
| 8303080046 | 8303080038 | 83/01/14 | 50-368 R |
| 8303080048 | 8303080043 | 83/02/22 | 50-321 S |
| 8303080053 | 8303080049 | 83/01/12 | 50-282 R |
| 8303080059 | 8303080055 | 83/01/14 | 50-313 R |
| 8303080075 | 8303080064 | 83/02/25 | 50-373 S |
| 8303080076 | 8303080070 | 83/02/24 | 50-245 S |
| 8303080087 | 8303080079 | 83/02/24 | 50-315 S |
| 8303080089 | 8303080082 | 83/02/28 | 50-443 G |
| 8303080091 | 8303080085 | 81/04/30 | 50-458 G |
| 8303080092 | 8303080084 | 83/03/01 | 50-269 I |
| 8303080096 | 8303080088 | 83/02/22 | 50-267 P |
| 8303080097 | 8303080095 | 83/01/14 | 50-361 R |
| 8303080099 | 8303080090 | 83/02/10 | 50-237 S |
| 8303080100 | 8303080093 | 83/02/24 | 50-249 S |
| 8303080101 | 8303080088 | 83/02/22 | 50-267 P |
| 8303080106 | 8303080082 | 83/02/28 | 50-443 G |
| 8303080113 | 8303080105 | 83/02/24 | 50-315 S |
| 8303080118 | 8303080110 | 83/03/03 | 50-213 P |
| 8303080119 | 8303080111 | 83/03/04 | 50-315 P |
| 8303080123 | 8303080110 | 83/03/03 | 50-213 P |
| 8303080127 | 8303080110 | 83/03/03 | 50-213 P |
| 8303080131 | 8303080126 | 83/03/02 | 50-389 A |
| 8303080133 | 8303080120 | 83/01/14 | 50-245 R |
| 8303080134 | 8303080122 | 83/02/25 | 50-305 S |
| 8303080144 | 8303080120 | 83/01/14 | 50-245 R |
| 8303080145 | 8303080141 | 83/02/28 | 50-315 C |
| 8303080147 | 8303080138 | 83/02/24 | 50-249 S |
| 8303080150 | 8303080141 | 83/02/28 | 50-315 P |
| 8303080157 | 8303080154 | 83/02/28 | 50-454 A |
| 8303080158 | 8303080151 | 83/01/10 | 50-324 R |
| 8303080160 | 8303080153 | 83/02/25 | 50-255 S |
| 8303080161 | 8303080156 | 83/01/14 | 50-206 R |
| 8303080166 | 8303080163 | 83/01/10 | 50-305 R |
| 8303080170 | 8303080165 | 83/01/07 | 50-346 R |
| 8303080177 | 8303080173 | 83/01/04 | 50-275 R |

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

| ACCESSION NUMBER ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
|---|---|---|---|
| 8303080181 | 8303080175 | 83/01/05 | 50-133 R |
| 8303080191 | 8303080185 | 83/01/05 | 50-298 R |
| 8303080196 | 8303080190 | 83/03/04 | 50-369 P |
| 8303080199 | 8303080193 | 83/02/25 | 50-255 S |
| 8303080207 | 8303080201 | 83/01/13 | 50-336 R |
| 8303080210 | 8303080203 | 83/03/02 | 50-397 Q |
| 8303080214 | 8303080206 | 83/02/22 | 50-321 S |
| 8303080217 | 8303080213 | 83/01/06 | 50-244 R |
| 8303080218 | 8303080208 | 83/02/18 | 50-245 R |
| 8303080225 | 8303080220 | 83/03/03 | TOPREP |
| 8303080227 | 8303080221 | 83/01/05 | 50-409 R |
| 8303080228 | 8303080219 | 83/03/01 | 50-255 S |
| 8303080236 | 8303080226 | 83/02/28 | 50-470 A |
| 8303080244 | 8303080234 | 83/02/24 | 50-373 S |
| 8303080251 | 8303080246 | 83/01/11 | 50-334 R |
| 8303080258 | 8303080248 | 83/02/18 | 50-315 Q |
| 8303080263 | 8303080256 | 83/03/01 | 50-461 Q |
| 8303080265 | 8303080254 | 83/02/23 | 50-254 S |
| 8303080270 | 8303080248 | 83/02/18 | 50-315 Q |
| 8303080276 | 8303080268 | 83/01/13 | 50-316 R |
| 8303080279 | 8303080275 | 83/02/28 | 50-409 R |
| 8303080285 | 8303080280 | 83/03/03 | 50-275 P |
| 8303080292 | 8303080284 | 83/02/24 | 50-322 Q |
| 8303080311 | 8303080300 | 83/02/24 | 50-387 S |
| 8303080321 | 8303080313 | 83/01/10 | 50-344 R |
| 8303080324 | 8303080294 | 83/02/28 | 50-369 P |
| 8303080326 | 8303080316 | 83/02/24 | 50-237 S |
| 8303080338 | 8303080332 | 83/03/02 | 50-331 P |
| 8303080339 | 8303080329 | 83/02/09 | 50-311 S |
| 8303080342 | 8303080335 | 83/02/28 | 50-213 P |
| 8303080344 | 8303080331 | 83/02/28 | 50-315 S |
| 8303080347 | 8303080341 | 83/01/18 | 50-219 R |
| 8303080350 | 8303080343 | 83/03/04 | 27-48 |
| 8303080351 | 8303080346 | 83/02/28 | 50-313 R |
| 8303080354 | 8303080345 | 83/02/24 | 50-245 S |
| 8303080360 | 8303080343 | 83/03/04 | 27-48 |
| 8303080364 | 8303080353 | 83/01/14 | 50-269 R |
| 8303080366 | 8303080358 | 83/02/25 | 50-373 S |
| 8303080369 | 8303080361 | 83/01/11 | 50-29 R |
| 8303080373 | 8303080359 | 83/03/02 | 50-277 Q |
| 8303080374 | 8303080367 | 81/04/13 | 50-458 Q |
| 8303080376 | 8303080371 | 83/02/11 | GA999 |
| 8303080377 | 8303080368 | 83/01/14 | 50-327 R |
| 8303080379 | 8303080372 | 83/01/14 | 50-338 R |
| 8303080384 | 8303080375 | 83/02/25 | 50-315 S |
| 8303080387 | 8303080381 | 83/02/23 | 50-334 R |
| 8303080391 | 8303080389 | 83/03/01 | 50-250 R |
| 8303080395 | 8303080385 | 83/02/18 | 50-277 S |
| 8303080398 | 8303080375 | 83/02/25 | 50-315 S |
| 8303080403 | 8303080400 | 83/01/14 | 50-387 R |
| 8303080408 | 8303080402 | 83/01/17 | 50-250 R |
| 8303080410 | 8303080375 | 83/02/25 | 50-315 S |
| 8303080411 | 8303080396 | 83/02/18 | 50-331 Q |
| 8303080412 | 8303080406 | 83/03/04 | 50-470 E |
| 8303080419 | 8303080413 | 83/02/24 | 50-336 S |
| 8303080426 | 8303080422 | 83/02/28 | 50-335 S |
| 8303080428 | 8303080415 | 83/02/22 | 50-244 Q |
| 8303080429 | 8303080423 | 83/01/13 | 50-315 R |
| 8303080435 | 8303080430 | 83/03/01 | 50-266 P |
| 8303080457 | 8303080449 | 83/02/18 | 50-440 Q |
| 8303080458 | 8303080452 | 83/01/10 | 50-277 R |
| 8303080468 | 8303080463 | 83/02/01 | 50-395 P |
| 8303080469 | 8303080464 | 83/01/10 | 50-263 R |
| 8303080473 | 8303080456 | 83/02/28 | 50-255 S |
| 8303080477 | 8303080472 | 83/02/25 | 50-333 S |
| 8303080488 | 8303080476 | 83/02/25 | 50-255 S |
| 8303080489 | 8303080479 | 83/03/04 | 50-312 Q |
| 8303080494 | 8303080478 | 83/02/25 | 50-346 S |
| 8303080499 | 8303080479 | 83/03/04 | 50-312 Q |
| 8303080502 | 8303080491 | 83/02/24 | 50-373 S |
| 8303080504 | 8303080496 | 83/02/24 | 50-358 R |
| 8303080505 | 8303080500 | 83/01/10 | 50-255 R |
| 8303080506 | 8303080501 | 83/02/25 | 50-333 S |
| 8303080509 | 8303080479 | 83/03/04 | 50-312 Q |
| 8303080513 | 8303080510 | 83/01/13 | 50-293 R |
| 8303080514 | 8303080507 | 83/02/25 | 50-316 S |
| 8303080519 | 8303080507 | 83/02/25 | 50-316 S |
| 8303080522 | 8303080518 | 83/02/25 | 50-346 S |
| 8303090004 | 8303090002 | 83/01/28 | FOIA |
| 8303090005 | 8303090002 | 83/01/28 | FOIA |

| ACCESSION NUMBER ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
|---|---|---|---|
| 8303090006 | 8303090002 | 83/01/28 | FOIA |
| 8303090007 | 8303090002 | 83/01/28 | FOIA |
| 8303090009 | 8303090002 | 83/01/28 | FOIA |
| 8303090013 | 8303090002 | 83/01/28 | FOIA |
| 8303090014 | 8303090002 | 83/01/28 | FOIA |
| 8303090016 | 8303090002 | 83/01/28 | FOIA |
| 8303090026 | 8303090022 | 83/01/28 | FOIA |
| 8303090029 | 8303090022 | 83/01/28 | FOIA |
| 8303090031 | 8303090030 | 83/02/22 | 40-3453 |
| 8303090032 | 8303090022 | 83/01/28 | FOIA |
| 8303090035 | 8303090022 | 83/01/28 | FOIA |
| 8303090037 | 8303090036 | 83/02/10 | WASTE MGT |
| 8303090043 | 8303090039 | 83/01/24 | FOIA |
| 8303090067 | 8302220002 | 83/02/10 | 50-29 P |
| 8303090068 | 8303090064 | 83/02/08 | 40-8698 |
| 8303090074 | 8303090072 | 83/03/04 | 50-244 P |
| 8303090076 | 8302220002 | 83/02/10 | 50-29 P |
| 8303090081 | 8303090075 | 83/02/08 | 40-8768 |
| 8303090090 | 8303090085 | 83/02/28 | 50-289 R |
| 8303090093 | 8303090088 | 83/02/01 | FOIA |
| 8303090100 | 8303090094 | 83/02/14 | 50-329 Q |
| 8303090101 | 8303090095 | 83/03/03 | 50-358 A |
| 8303090107 | 8303090102 | 83/03/04 | 50-254 Q |
| 8303090108 | 8303090094 | 83/02/14 | 50-329 Q |
| 8303090112 | 8303080280 | 83/03/03 | 50-275 P |
| 8303090116 | 8303090098 | 83/02/25 | 50-387 S |
| 8303090117 | 8303090110 | 83/02/18 | 50-289 P |
| 8303090122 | 8303090118 | 83/02/28 | 50-277 R |
| 8303090141 | 8303090134 | 83/02/15 | 40-8698 |
| 8303090144 | 8303090135 | 83/02/08 | FOIA |
| 8303090145 | 8303090143 | 83/02/18 | 50-298 Q |
| 8303090152 | 8303090140 | 83/02/25 | 50-329 A |
| 8303090157 | 8303090147 | 83/02/10 | WASTE MGT |
| 8303090165 | 8303090158 | 81/08/06 | 50-335 R |
| 8303090170 | 8303090164 | 83/02/10 | FOIA |
| 8303090176 | 8303090166 | 83/02/18 | 50-324 Q |
| 8303090177 | 8303090169 | 83/02/24 | 50-309 U |
| 8303090185 | 8303090175 | 83/02/25 | 50-272 S |
| 8303090193 | 8303090187 | 83/02/04 | FOIA |
| 8303090195 | 8303090182 | 83/02/25 | 50-333 S |
| 8303090199 | 8303090191 | 83/03/02 | 50-348 F |
| 8303090207 | 8303090191 | 83/03/02 | 50-348 F |
| 8303090209 | 8303090204 | 83/02/28 | 50-285 P |
| 8303090212 | 8303090208 | 83/03/03 | 50-358 A |
| 8303090220 | 8303090216 | 81/08/31 | 50-327 R |
| 8303090224 | 8303090139 | 83/02/25 | 50-29 S |
| 8303090225 | 8303090215 | 83/02/24 | 50-311 S |
| 8303090230 | 8303090222 | 83/02/24 | 70-820 |
| 8303090231 | 8303090213 | 83/02/24 | TOPREP |
| 8303090235 | 8303090228 | 83/02/01 | FOIA |
| 8303090240 | 8303090233 | 83/03/02 | 50-213 F |
| 8303090243 | 8303090228 | 83/02/01 | FOIA |
| 8303090247 | 8303090238 | 83/02/24 | 50-272 S |
| 8303090249 | 8303090233 | 83/03/02 | 50-213 F |
| 8303090250 | 8303090228 | 83/02/01 | FOIA |
| 8303090257 | 8303090245 | 83/02/17 | 50-271 P |
| 8303090262 | 8303090256 | 83/03/04 | 50-213 P |
| 8303090264 | 8303090245 | 83/02/17 | 50-271 P |
| 8303090266 | 8303090256 | 83/03/04 | 50-213 P |
| 8303090268 | 8303090260 | 83/02/17 | 50-266 P |
| 8303090270 | 8303090245 | 83/02/17 | 50-271 P |
| 8303090271 | 8303090256 | 83/03/04 | 50-213 P |
| 8303090272 | 8303090265 | 83/02/17 | 50-282 P |
| 8303090274 | 8303090267 | 83/03/02 | 50-373 F |
| 8303090284 | 8303090267 | 83/03/02 | 50-373 F |
| 8303090288 | 8303090282 | 83/03/04 | 50-206 P |
| 8303090296 | 8303090282 | 83/03/04 | 50-206 P |
| 8303090308 | 8303090301 | 83/03/04 | 50-461 E |
| 8303090310 | 8303090302 | 83/02/14 | 50-382 F |
| 8303090315 | 8303090301 | 83/03/04 | 50-461 E |
| 8303090318 | 8303090302 | 83/02/14 | 50-382 F |
| 8303090324 | 8302220396 | 83/02/14 | 50-186 G |
| 8303090337 | 8303090331 | 83/02/10 | WASTE MGT |
| 8303090347 | 8303090340 | 83/03/04 | 50-389 E |
| 8303090348 | 8303090341 | 82/03/02 | 50-348 R |
| 8303090352 | 8303090349 | 83/01/31 | 40-1341 |
| 8303090363 | 8303090360 | 81/08/25 | 50-321 R |
| 8303090368 | 8303090360 | 81/08/25 | 50-321 R |
| 8303090370 | 8303090365 | 83/02/28 | 50-29 R |
| 8303090375 | 8303090369 | 83/03/02 | 50-348 F |

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS



| ACCESSION NUMBER ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
|---|---|---|---|---|
| 8303090377 | 8303090369 | 83/03/02 | 50-348 | F |
| 8303090380 | 8303090373 | 83/02/17 | TOPREP | |
| 8303090383 | 8303090378 | 83/02/17 | TOPREP | |
| 8303090386 | 8303090378 | 83/02/17 | TOPREP | |
| 8303090388 | 8303090384 | 83/03/02 | 50-275 | R |
| 8303090400 | 8303090398 | 83/02/23 | FOIA | |
| 8303090401 | 8303090374 | 83/03/02 | 50-346 | F |
| 8303090402 | 8303090399 | 83/02/24 | 50-285 | P |
| 8303090405 | 8303090374 | 83/03/02 | 50-346 | F |
| 8303090406 | 8303090399 | 83/02/24 | 50-285 | P |
| 8303090407 | 8302220396 | 83/02/14 | 50-186 | G |
| 8303090409 | 8303090399 | 83/02/24 | 50-285 | P |
| 8303090411 | 8303090408 | 83/02/18 | FOIA | |
| 8303090414 | 8303090410 | 83/03/02 | 50-313 | F |
| 8303090422 | 8303090416 | 83/02/28 | CONTRACT | |
| 8303090431 | 8303090420 | 83/03/01 | 50-271 | F |
| 8303090433 | 8303090428 | 83/02/18 | CONTRACT | |
| 8303090434 | 8303090424 | 83/02/24 | 50-317 | P |
| 8303090435 | 8303090[illegible] | 83/03/02 | 50-312 | F |
| 8303090440 | 8303090430 | 83/03/02 | 50-312 | F |
| 8303090447 | 8303090424 | 83/02/24 | 50-317 | P |
| 8303090481 | 8303090474 | 83/02/25 | TOPREP | |
| 8303090499 | 8303090443 | 83/02/16 | 50-373 | P |
| 8303090517 | 8303090443 | 83/02/16 | 50-373 | P |
| 8303090526 | 8303090513 | 83/02/23 | 40-4492 | |
| 8303090529 | 8303090443 | 83/02/16 | 50-373 | P |
| 8303090537 | 8303090532 | 83/03/02 | 50-321 | F |
| 8303090544 | 8303090532 | 83/03/02 | 50-321 | F |
| 8303090566 | 8303090561 | 83/03/02 | 50-320 | F |
| 8303090572 | 8303090561 | 83/03/02 | 50-320 | F |
| 8303090579 | 8303090574 | 83/02/09 | State Prog | |
| 8303090583 | 8303090576 | 83/03/02 | 50-313 | F |
| 8303090587 | 8303090574 | 83/02/09 | State Prog | |
| 8303090591 | 8303090584 | 83/02/22 | 40-2259 | |
| 8303090594 | 8303090576 | 83/03/02 | 50-313 | F |
| 8303090599 | 8303090592 | 83/02/03 | CONTRACT | |
| 8303090614 | 8303090607 | 83/02/23 | ORG | |
| 8303090623 | 8303090607 | 83/02/23 | ORG | |
| 8303090630 | 8303090607 | 83/02/23 | ORG | |
| 8303090634 | 8303090607 | 83/02/23 | ORG | |
| 8303090639 | 8303090607 | 83/02/23 | ORG | |
| 8303090644 | 8303090637 | 83/03/02 | 50-29 | F |
| 8303090647 | 8303090607 | 83/02/23 | ORG | |
| 8303090653 | 8303090607 | 83/02/23 | ORG | |
| 8303090661 | 8303090607 | 83/02/23 | ORG | |
| 8303090664 | 8303090637 | 83/03/02 | 50-29 | F |
| 8303090668 | 8303090662 | 83/02/28 | CONTRACT | |
| 8303090674 | 8303090671 | 83/03/02 | 50-29 | F |
| 8303090679 | 8303090671 | 83/03/02 | 50-29 | F |
| 8303090691 | 8303090685 | 83/03/02 | 50-263 | F |
| 8303090698 | 8303090685 | 83/03/02 | 50-263 | F |
| 8303100005 | 8303100001 | 83/03/01 | CONTRACT | |
| 8303100010 | 8303100007 | 83/02/03 | FOIA | |
| 8303100021 | 8303100007 | 83/02/03 | FOIA | |
| 8303100025 | 8303100020 | 83/03/02 | 50-267 | F |
| 8303100030 | 8303100020 | 83/03/02 | 50-267 | F |
| 8303100031 | 8303100007 | 83/02/03 | FOIA | |
| 8303100033 | 8303100028 | 83/02/15 | 50-206 | G |
| 8303100037 | 8303100028 | 83/02/15 | 50-206 | G |
| 8303100041 | 8303100028 | 83/02/15 | 50-206 | G |
| 8303100042 | 8303100007 | 83/02/03 | FOIA | |
| 8303100043 | 8303100035 | 83/03/02 | 50-327 | F |
| 8303100045 | 8303100028 | 83/02/15 | 50-206 | G |
| 8303100046 | 8303100035 | 83/03/02 | 50-327 | F |
| 8303100047 | 8303100040 | 83/02/15 | 40-8783 | |
| 8303100049 | 8303100044 | 83/03/02 | 50-327 | F |
| 8303100050 | 8303100028 | 83/02/15 | 50-206 | G |
| 8303100051 | 8303100007 | 83/02/03 | FOIA | |
| 8303100053 | 8303100044 | 83/03/02 | 50-327 | F |
| 8303100055 | 8303100007 | 83/02/03 | FOIA | |
| 8303100064 | 8303100063 | 83/02/25 | 70-364 | |
| 8303100067 | 8303100028 | 83/02/15 | 50-206 | G |
| 8303100082 | 8303100068 | 83/02/15 | 50-265 | P |
| 8303100083 | 8303100075 | 83/03/02 | 50-254 | F |
| 8303100087 | 8303100068 | 83/02/15 | 50-265 | P |
| 8303100089 | 8303100068 | 83/02/15 | 50-220 | G |
| 8303100090 | 8303100075 | 83/03/02 | 50-254 | F |
| 8303100091 | 8303100088 | 83/03/02 | 50-395 | F |
| 8303100092 | 8303100080 | 83/02/10 | 50-440 | A |
| 8303100093 | 8303100068 | 83/02/15 | 50-263 | G |

| ACCESSION NUMBER ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
|---|---|---|---|---|
| 8303100094 | 8303100088 | 83/03/02 | 50-395 | F |
| 8303100101 | 8303100097 | 83/03/02 | 50-285 | F |
| 8303100102 | 8303100068 | 83/02/15 | 50-220 | G |
| 8303100105 | 8303100080 | 83/02/10 | 50-440 | E |
| 8303100109 | 8303100068 | 83/02/15 | 50-265 | P |
| 8303100113 | 8303100080 | 83/02/10 | 50-440 | G |
| 8303100123 | 8303100097 | 83/03/02 | 50-285 | F |
| 8303100130 | 8303100125 | 83/03/02 | 50-321 | F |
| 8303100132 | 8303100125 | 83/03/02 | 50-321 | F |
| 8303100140 | 8303100139 | 83/03/03 | 50-333 | G |
| 8303100150 | 8303100146 | 83/02/25 | 50-336 | G |
| 8303100168 | 8303100162 | 83/03/02 | 50-413 | F |
| 8303100171 | 8303100169 | 83/02/25 | 50-309 | G |
| 8303100174 | 8303100162 | 83/03/02 | 50-413 | F |
| 8303100177 | 8303100169 | 83/02/25 | 50-309 | G |
| 8303100178 | 8303100172 | 83/03/08 | 50-247 | T |
| 8303100186 | 8303100180 | 83/03/02 | 50-263 | F |
| 8303100191 | 8303100189 | 83/03/03 | 50-338 | P |
| 8303100193 | 8303100180 | 83/03/02 | 50-263 | F |
| 8303100203 | 8303100199 | 83/03/01 | 50-3 | R |
| 8303100210 | 8303100202 | 83/02/23 | 50-272 | G |
| 8303100216 | 8303100204 | 83/02/04 | 50-329 | G |
| 8303100225 | 8303100204 | 83/02/04 | 50-329 | G |
| 8303100235 | 8303100229 | 83/02/25 | 50-275 | P |
| 8303100243 | 8303100227 | 83/02/25 | 50-317 | G |
| 8303100246 | 8303100240 | 83/03/03 | 50-333 | G |
| 8303100247 | 8303100241 | 83/02/25 | 50-275 | R |
| 8303100265 | 8303100260 | 83/03/03 | 50-322 | G |
| 8303100281 | 8303100275 | 83/02/23 | 50-443 | G |
| 8303100283 | 8303100278 | 83/03/04 | 50-87 | G |
| 8303100287 | 8303100279 | 83/03/04 | 50-244 | G |
| 8303100300 | 8303100297 | 83/02/24 | 50-387 | G |
| 8303100302 | 8303100279 | 83/03/04 | 50-244 | G |
| 8303100305 | 8303100293 | 83/02/23 | 50-293 | G |
| 8303100307 | 8303100297 | 83/02/24 | 50-387 | G |
| 8303100317 | 8303100314 | 83/02/23 | 50-388 | G |
| 8303100318 | 8303100313 | 83/03/04 | 50-454 | F |
| 8303100321 | 8303100311 | 83/03/01 | 50-29 | R |
| 8303100322 | 8303100319 | 83/02/23 | 50-272 | G |
| 8303100328 | 8303100323 | 83/03/03 | 50-456 | C |
| 8303100331 | 8303100326 | 83/03/01 | 50-327 | R |
| 8303100332 | 8303100329 | 83/02/25 | 70-135 | |
| 8303100339 | 8303100336 | 83/02/23 | 50-272 | G |
| 8303100344 | 8303100336 | 83/02/23 | 50-272 | G |
| 8303100349 | 8303100345 | 83/03/03 | 50-528 | E |
| 8303100353 | 8303100345 | 83/03/03 | 50-528 | E |
| 8303100356 | 8303100345 | 83/03/03 | 50-528 | E |
| 8303100365 | 8303100363 | 83/03/01 | 50-317 | R |
| 8303100376 | 8303100375 | 83/03/01 | 50-29 | R |
| 8303100382 | 8303100380 | 83/02/23 | 50-412 | G |
| 8303100390 | 8303100386 | 83/03/04 | 50-244 | G |
| 8303100393 | 8303100386 | 83/03/04 | 50-244 | G |
| 8303100398 | 8303100386 | 83/03/04 | 50-244 | G |
| 8303100399 | 8303100395 | 83/01/20 | FOIA | |
| 8303100401 | 8303100396 | 83/03/01 | 50-280 | P |
| 8303100403 | 8303100395 | 83/01/20 | FOIA | |
| 8303100404 | 8303100396 | 83/03/01 | 50-280 | P |
| 8303100406 | 8303100395 | 83/01/20 | FOIA | |
| 8303100407 | 8303100402 | 83/03/02 | 50-348 | F |
| 8303100410 | 8303100402 | 83/03/02 | 50-348 | F |
| 8303100417 | 8303100415 | 83/03/03 | 70-364 | |
| 8303100418 | 8303100415 | 83/03/03 | 70-364 | |
| 8303100431 | 8303100395 | 83/01/20 | FOIA | |
| 8303100434 | 8303100395 | 83/01/20 | FOIA | |
| 8303100438 | 8303100395 | 83/01/20 | FOIA | |
| 8303100442 | 8303100395 | 83/01/20 | FOIA | |
| 8303100448 | 8303100395 | 83/01/20 | FOIA | |
| 8303100452 | 8303100395 | 83/01/20 | FOIA | |
| 8303100456 | 8303100395 | 83/01/20 | FOIA | |
| 8303100458 | 8303100395 | 83/01/20 | FOIA | |
| 8303100462 | 8303100395 | 83/01/20 | FOIA | |
| 8303100464 | 8303100395 | 83/01/20 | FOIA | |
| 8303100466 | 8303100395 | 83/01/20 | FOIA | |
| 8303100469 | 8303100395 | 83/01/20 | FOIA | |
| 8303100473 | 8303100395 | 83/01/20 | FOIA | |
| 8303100475 | 8303100411 | 83/02/18 | 50-361 | P |
| 8303100477 | 8303100395 | 83/01/20 | FOIA | |
| 8303100480 | 8303100395 | 83/01/20 | FOIA | |
| 8303100483 | 8303100411 | 83/02/18 | 50-361 | P |
| 8303100484 | 8303100411 | 83/02/18 | 50-361 | P |

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

| ACCESSION NUMBER | | | | |
|---|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
| 8303100490 | 8303100487 | 83/03/02 | 50-20 | P |
| 8303100546 | 8303100541 | 83/03/02 | 50-29 | F |
| 8303100549 | 8303100547 | 83/03/02 | 71-9074 | |
| 8303100550 | 8303100541 | 83/03/02 | 50-29 | F |
| 8303100555 | 8303100551 | 83/03/04 | 50-546 | F |
| 8303100556 | 8303100552 | 83/03/02 | COMMISSION | |
| 8303100557 | 8303100553 | 83/03/02 | 50-289 | F |
| 8303100559 | 8303100552 | 83/03/02 | COMMISSION | |
| 8303100560 | 8303100553 | 83/03/02 | 50-289 | F |
| 8303100561 | 8303100552 | 83/03/02 | COMMISSION | |
| 8303100563 | 8303100552 | 83/03/02 | COMMISSION | |
| 8303100565 | 8303100562 | 83/03/02 | 50-285 | F |
| 8303100569 | 8303100566 | 83/03/02 | 50-285 | F |
| 8303110003 | 8303110002 | 83/02/25 | 50-295 | P |
| 8303110008 | 8303110004 | 83/03/03 | REVIEW GRP | |
| 8303110010 | 8303110006 | 83/01/31 | 50-272 | G |
| 8303110012 | 8303110002 | 83/02/25 | 50-295 | P |
| 8303110013 | 8303110006 | 83/01/31 | 50-272 | S |
| 8303110017 | 8303110006 | 83/01/31 | 50-272 | S |
| 8303110018 | 8303110002 | 83/02/25 | 50-295 | P |
| 8303110021 | 8303110006 | 83/01/31 | 50-272 | S |
| 8303110023 | 8303110006 | 83/01/31 | 50-272 | G |
| 8303110028 | 8303110014 | 83/02/18 | 71-6387 | |
| 8303110030 | 8303110026 | 83/03/01 | 50-220 | R |
| 8303110031 | 8303110006 | 83/01/31 | 50-272 | G |
| 8303110032 | 8303110027 | 83/03/01 | 50-358 | A |
| 8303110039 | 8303110033 | 83/01/31 | 40-8714 | |
| 8303110040 | 8303110035 | 83/03/09 | 50-395 | P |
| 8303110042 | 8303110006 | 83/01/31 | FOIA | |
| 8303110044 | 8303110041 | 83/01/21 | 40-6768 | |
| 8303110048 | 8303110006 | 83/01/31 | 50-334 | P |
| 8303110061 | 8303110006 | 83/01/31 | 50-334 | S |
| 8303110063 | 8303110055 | 83/03/01 | 50-250 | P |
| 8303110066 | 8303110058 | 83/02/03 | 50-206 | G |
| 8303110068 | 8303110006 | 83/01/31 | 50-334 | S |
| 8303110069 | 8303110067 | 83/03/02 | 70-2917 | |
| 8303110071 | 8303110055 | 83/03/01 | 50-250 | P |
| 8303110075 | 8303110070 | 83/03/03 | 50-498 | G |
| 8303110076 | 8303110053 | 83/03/01 | 50-320 | R |
| 8303110079 | 8303110070 | 83/03/03 | 50-498 | G |
| 8303110081 | 8303110006 | 83/01/31 | 50-272 | G |
| 8303110086 | 8303110038 | 83/02/03 | 50-460 | G |
| 8303110088 | 8303110006 | 83/01/31 | 50-311 | S |
| 8303110092 | 8303110080 | 83/02/22 | 50-362 | S |
| 8303110093 | 8303110087 | 83/03/02 | ORG | |
| 8303110095 | 8303110058 | 83/02/03 | 50-460 | G |
| 8303110096 | 8303110006 | 83/01/31 | 50-272 | S |
| 8303110100 | 8303110058 | 83/02/03 | FOIA | |
| 8303110104 | 8303110091 | 83/02/25 | 50-261 | P |
| 8303110109 | 8303110091 | 83/02/25 | 50-261 | P |
| 8303110117 | 8303110091 | 83/02/25 | 50-261 | P |
| 8303110119 | 8303110116 | 83/02/18 | 71-86 | |
| 8303110121 | 8303110111 | 83/02/21 | 70-36 | |
| 8303110124 | 8303110058 | 83/02/03 | FOIA | |
| 8303110125 | 8303110113 | 83/02/24 | 50-362 | S |
| 8303110127 | 8303110058 | 83/02/03 | FOIA | |
| 8303110131 | 8303110122 | 83/03/01 | 50-280 | P |
| 8303110132 | 8303110058 | 83/02/03 | FOIA | |
| 8303110133 | 8303110126 | 83/02/24 | 70-1201 | |
| 8303110134 | 8303110113 | 83/02/24 | 50-362 | S |
| 8303110138 | 8303110122 | 83/03/01 | 50-280 | P |
| 8303110139 | 8303110058 | 83/02/03 | FOIA | |
| 8303110142 | 8303110115 | 83/03/02 | 50-361 | S |
| 8303110143 | 8303110136 | 83/02/25 | 50-358 | U |
| 8303110153 | 8303110058 | 83/02/03 | FOIA | |
| 8303110154 | 8303110151 | 83/03/01 | 50-277 | P |
| 8303110156 | 8303110148 | 83/03/03 | 50-322 | A |
| 8303110157 | 8303110151 | 83/03/01 | 50-277 | P |
| 8303110159 | 8303110151 | 83/03/01 | 50-277 | P |
| 8303110160 | 8303110149 | 83/02/18 | 50-312 | S |
| 8303110165 | 8303110162 | 83/03/04 | 70-2928 | |
| 8303110166 | 8303110058 | 83/02/03 | 50-206 | G |
| 8303110172 | 8303110058 | 83/02/03 | FOIA | |
| 8303110182 | 8303110058 | 83/02/03 | FOIA | |
| 8303110191 | 8303110188 | 83/03/01 | 50-362 | S |
| 8303110196 | 8303110194 | 83/03/09 | 50-322 | G |
| 8303110208 | 8303110201 | 83/03/02 | 50-362 | S |
| 8303110220 | 8303110212 | 82/12/27 | 50-334 | F |
| 8303110229 | 8303110223 | 83/02/14 | 50-72 | R |
| 8303110230 | 8303110225 | 83/02/25 | 50-361 | S |

| ACCESSION NUMBER | | | | |
|---|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
| 8303110243 | 8303110238 | 83/03/01 | 50-344 | R |
| 8303110248 | 8303110241 | 83/03/01 | 50-10 | R |
| 8303110410 | 8303110244 | 83/02/18 | 50-528 | G |
| 8303110253 | 8303110251 | 83/03/09 | 50-329 | E |
| 8303110260 | 8303110257 | 83/03/09 | 50-389 | A |
| 8303110261 | 8303110254 | 83/02/08 | 50-329 | G |
| 8303110262 | 8303110257 | 83/03/09 | 50-389 | A |
| 8303110263 | 8303110251 | 83/03/09 | 50-329 | E |
| 8303110266 | 8303110257 | 83/03/09 | 50-389 | A |
| 8303110268 | 8303110257 | 83/03/09 | 50-389 | A |
| 8303110271 | 8303110257 | 83/03/09 | 50-389 | A |
| 8303110273 | 8303110267 | 83/02/25 | 50-361 | S |
| 8303110279 | 8303110246 | 83/03/04 | 50-10 | P |
| 8303110286 | 8303110282 | 83/03/09 | 50-280 | P |
| 8303110291 | 8303110282 | 83/03/09 | 50-280 | P |
| 8303110292 | 8303110287 | 83/03/04 | 50-250 | P |
| 8303110297 | 8303110282 | 83/03/09 | 50-280 | P |
| 8303110301 | 8303110299 | 83/03/07 | 50-282 | G |
| 8303110302 | 8303110282 | 83/03/09 | 50-280 | P |
| 8303110303 | 8303110287 | 83/03/04 | 50-250 | P |
| 8303110306 | 8303110298 | 83/03/07 | 50-508 | S |
| 8303110307 | 8303290667 | 83/03/21 | 50-361 | P |
| 8303110312 | 8303110208 | 83/02/25 | 50-317 | G |
| 8303110317 | 8303110308 | 83/02/25 | 50-317 | G |
| 8303110318 | 8303110311 | 83/02/25 | 50-312 | S |
| 8303110320 | 8303110316 | 83/03/04 | 50-244 | P |
| 8303110322 | 8303110313 | 83/03/01 | 50-336 | P |
| 8303110324 | 8303110316 | 83/03/04 | 50-244 | P |
| 8303110325 | 8303110305 | 83/02/22 | 50-362 | S |
| 8303110327 | 8303110310 | 83/03/07 | 50-508 | G |
| 8303110335 | 8303110330 | 83/02/16 | 50-344 | S |
| 8303110337 | 8303110333 | 83/02/22 | 50-362 | S |
| 8303110342 | 8303110333 | 83/02/22 | 50-362 | S |
| 8303110343 | 8303110341 | 83/03/07 | 50-395 | R |
| 8303110349 | 8303110347 | 83/02/23 | 50-362 | S |
| 8303110353 | 8303110282 | 83/03/09 | 50-280 | P |
| 8303110356 | 8303110282 | 83/03/09 | 50-280 | P |
| 8303110358 | 8303110282 | 83/03/09 | 50-280 | P |
| 8303110359 | 8303110282 | 83/03/09 | 50-280 | P |
| 8303110361 | 8303110354 | 83/02/18 | 50-312 | S |
| 8303110364 | 8303110357 | 83/03/02 | 50-312 | S |
| 8303110365 | 8303110362 | 83/03/10 | 50-329 | A |
| 8303110366 | 8303110363 | 83/02/08 | 50-329 | G |
| 8303110368 | 8303110367 | 83/02/22 | 50-312 | G |
| 8303110369 | 8303110362 | 83/03/10 | 50-329 | A |
| 8303110374 | 8303110362 | 83/03/10 | 50-329 | A |
| 8303110377 | 8303110373 | 83/03/09 | 50-305 | P |
| 8303110379 | 8303110376 | 83/03/07 | 50-508 | G |
| 8303110401 | 8303110398 | 83/03/01 | 50-313 | P |
| 8303110404 | 8303110398 | 83/03/01 | 50-313 | P |
| 8303110408 | 8303110398 | 83/03/01 | 50-313 | P |
| 8303110419 | 8303110414 | 83/02/24 | 50-289 | P |
| 8303110424 | 8303110414 | 83/02/24 | 50-289 | P |
| 8303110428 | 8303110414 | 83/02/24 | 50-289 | P |
| 8303110434 | 8303110431 | 83/02/23 | 50-285 | P |
| 8303110436 | 8303110431 | 83/02/23 | 50-285 | P |
| 8303110440 | 8303110431 | 83/02/23 | 50-285 | P |
| 8303110506 | 8303110466 | 83/03/03 | 50-275 | P |
| 8303110525 | 8303110509 | 83/03/01 | 50-277 | P |
| 8303110533 | 8303110522 | 83/03/02 | 50-445 | G |
| 8303110534 | 8303110509 | 83/03/01 | 50-277 | P |
| 8303110544 | 8303110509 | 83/03/01 | 50-277 | P |
| 8303110556 | 8303110552 | 83/03/02 | 50-352 | M |
| 8303110598 | 8303110586 | 83/02/28 | 40-8602 | |
| 8303140011 | 8303140008 | 83/03/03 | 50-346 | H |
| 8303140039 | 8303140031 | 83/03/04 | 70-1062 | |
| 8303140043 | 8303140031 | 83/03/04 | 70-1062 | |
| 8303140046 | 8303140031 | 83/03/04 | 70-1062 | |
| 8303140079 | 8303140074 | 83/03/02 | 50-302 | H |
| 8303140082 | 8303140077 | 83/02/23 | 50-282 | P |
| 8303140086 | 8303140078 | 83/02/28 | 50-443 | G |
| 8303140089 | 8303140077 | 83/02/23 | 50-282 | P |
| 8303140093 | 8303140090 | 83/02/23 | 50-335 | P |
| 8303140115 | 8303140077 | 83/02/23 | 50-282 | P |
| 8303140138 | 8303140129 | 83/02/18 | FOIA | |
| 8303140143 | 8303140129 | 83/02/18 | 70-2684 | |
| 8303140152 | 8303140129 | 83/02/18 | FOIA | |
| 8303140154 | 8303140148 | 83/02/28 | 50-443 | G |
| 8303140159 | 8303140129 | 83/02/18 | FOIA | |
| 8303140165 | 8303140129 | 83/02/18 | 70-2684 | |

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS



| ACCESSION NUMBER ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
|---|---|---|---|---|
| 8303140173 | 8303140129 | 83/02/18 | 70-2684 | |
| 8303140177 | 8303140129 | 83/02/18 | FOIA | |
| 8303140181 | 8303140129 | 83/02/18 | FOIA | |
| 8303140184 | 8303140129 | 83/02/18 | 70-2684 | |
| 8303140186 | 8303140182 | 83/03/08 | 50-461 | G |
| 8303140190 | 8303140129 | 83/02/18 | FOIA | |
| 8303140192 | 8303140129 | 83/02/18 | FOIA | |
| 8303140196 | 8303140129 | 83/02/18 | FOIA | |
| 8303140198 | 8303140197 | 83/02/28 | 50-289 | R |
| 8303140199 | 8303140194 | 83/02/25 | 50-317 | S |
| 8303140201 | 8303140129 | 83/02/18 | FOIA | |
| 8303140202 | 8303140197 | 83/02/28 | 50-289 | R |
| 8303140203 | 8303140197 | 83/02/28 | 50-289 | R |
| 8303140218 | 8303140216 | 83/03/08 | 50-322 | G |
| 8303140219 | 8303140216 | 83/03/08 | 50-322 | G |
| 8303140225 | 8303140223 | 83/02/22 | 50-213 | G |
| 8303140227 | 8303140222 | 83/03/09 | 50-333 | R |
| 8303140229 | 8303140223 | 83/02/22 | 50-213 | G |
| 8303140233 | 8303140226 | 83/02/28 | 50-293 | G |
| 8303140241 | 8303140236 | 83/03/10 | REVIEW GRP | |
| 8303140243 | 8303140238 | 83/03/04 | 50-311 | S |
| 8303140245 | 8303140242 | 83/03/04 | 50-311 | S |
| 8303140247 | 8303140239 | 83/03/02 | 50-309 | R |
| 8303140258 | 8303140252 | 83/03/09 | 50-400 | G |
| 8303140261 | 8303140249 | 83/03/08 | 50-456 | G |
| 8303140262 | 8303140252 | 83/03/09 | 50-400 | G |
| 8303140263 | 8303140253 | 83/03/03 | 50-245 | S |
| 8303140264 | 8303140257 | 83/03/02 | REVIEW GRP | |
| 8303140265 | 8303140259 | 83/02/24 | 50-254 | G |
| 8303140266 | 8303140252 | 83/03/09 | 50-400 | G |
| 8303140280 | 8303140274 | 83/03/09 | 50-354 | A |
| 8303140294 | 8303140287 | 83/03/10 | 50-482 | E |
| 8303140300 | 8303140295 | 83/02/24 | 50-461 | G |
| 8303140304 | 8303140296 | 83/03/07 | 50-295 | G |
| 8303140310 | 8303140302 | 83/03/03 | 50-324 | S |
| 8303140314 | 8303140270 | 83/02/11 | 50-295 | G |
| 8303140318 | 8303140312 | 83/03/04 | 50-348 | P |
| 8303140323 | 8303140320 | 83/03/02 | 50-255 | R |
| 8303140327 | 8303140322 | 83/03/08 | 50-443 | G |
| 8303140334 | 8303140328 | 83/02/28 | 50-483 | G |
| 8303140339 | 8303140337 | 83/03/08 | 50-224 | R |
| 8303140355 | 8303140350 | 83/03/08 | 50-295 | S |
| 8303140356 | 8303140352 | 83/03/08 | 50-352 | G |
| 8303140357 | 8303140349 | 83/03/09 | 50-2 | G |
| 8303140360 | 8303140342 | 83/03/08 | 50-295 | S |
| 8303140361 | 8303140347 | 83/03/04 | 50-311 | S |
| 8303140377 | 8303140373 | 83/03/02 | 50-315 | S |
| 8303140378 | 8303140375 | 83/02/25 | 50-317 | S |
| 8303140380 | 8303140376 | 83/03/04 | 50-348 | P |
| 8303140382 | 8303140379 | 83/02/25 | 50-369 | S |
| 8303140384 | 8303140383 | 83/02/25 | 50-219 | S |
| 8303140389 | 8303140388 | 83/03/02 | 50-416 | S |
| 8303140390 | 8303140387 | 83/02/24 | 50-247 | S |
| 8303140392 | 8303140391 | 83/03/02 | 50-369 | S |
| 8303140394 | 8303140393 | 83/03/03 | 50-245 | S |
| 8303140397 | 8303140395 | 83/03/09 | 50-413 | A |
| 8303140401 | 8303140399 | 83/03/01 | 50-315 | R |
| 8303140404 | 8303140403 | 83/03/02 | 50-416 | S |
| 8303140406 | 8303140402 | 83/02/28 | 50-266 | G |
| 8303140408 | 8303140407 | 83/03/03 | 50-331 | S |
| 8303140411 | 8303140381 | 83/02/28 | 50-373 | G |
| 8303140412 | 8303140405 | 83/02/28 | 50-387 | S |
| 8303140414 | 8303140400 | 83/03/03 | 50-305 | S |
| 8303140415 | 8303140410 | 83/03/04 | 50-255 | R |
| 8303140416 | 8303140413 | 83/03/03 | 50-331 | S |
| 8303140420 | 8303140374 | 83/02/07 | 50-329 | T |
| 8303140423 | 8303140381 | 83/02/28 | 50-373 | G |
| 8303140428 | 8303140421 | 83/03/03 | 50-331 | S |
| 8303140429 | 8303140409 | 83/03/03 | 50-346 | S |
| 8303140432 | 8303140374 | 83/02/07 | 50-329 | T |
| 8303140434 | 8303140426 | 83/02/28 | 50-244 | R |
| 8303140437 | 8303140424 | 83/03/03 | 50-373 | S |
| 8303140441 | 8303140426 | 83/02/28 | 50-244 | R |
| 8303140445 | 8303140439 | 83/03/07 | 50-410 | G |
| 8303140447 | 8303140436 | 83/03/02 | 50-254 | S |
| 8303140449 | 8303140435 | 83/03/03 | 50-331 | S |
| 8303140450 | 8303140440 | 83/03/03 | 70-124 | |
| 8303140451 | 8303140439 | 83/03/07 | 50-410 | G |
| 8303140454 | 8303140442 | 83/02/28 | 50-271 | S |
| 8303140457 | 8303140439 | 83/03/07 | 50-410 | G |

| ACCESSION NUMBER ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
|---|---|---|---|---|
| 8303140464 | 8303140458 | 83/03/07 | 50-387 | P |
| 8303140466 | 8303140432 | 83/03/03 | 50-309 | S |
| 8303140467 | 8303140456 | 83/03/09 | 50-456 | G |
| 8303140469 | 8303140465 | 83/03/09 | 50-271 | G |
| 8303140470 | 8303140460 | 83/03/04 | 50-295 | S |
| 8303140472 | 8303140462 | 83/03/09 | 50-528 | G |
| 8303140475 | 8303140468 | 83/02/24 | 50-356 | G |
| 8303140476 | 8303140465 | 83/03/09 | 50-271 | G |
| 8303140481 | 8303140471 | 83/03/08 | 50-155 | F |
| 8303140482 | 8303140473 | 83/03/09 | 50-373 | G |
| 8303140485 | 8303140474 | 83/03/01 | 50-397 | R |
| 8303140486 | 8303140477 | 83/02/25 | 50-373 | S |
| 8303140487 | 8303140471 | 83/03/08 | 50-155 | F |
| 8303140494 | 8303140471 | 83/03/08 | 50-155 | F |
| 8303140496 | 8303140484 | 83/03/02 | 50-289 | S |
| 8303140501 | 8303140492 | 83/03/03 | 50-327 | S |
| 8303140505 | 8303140493 | 83/03/04 | 50-305 | S |
| 8303140506 | 8303140495 | 83/03/03 | 50-309 | S |
| 8303140507 | 8303140497 | 83/03/03 | 50-333 | S |
| 8303140508 | 8303140499 | 83/03/09 | 40-8713 | |
| 8303140511 | 8303140503 | 83/03/03 | 50-271 | R |
| 8303140512 | 8303140502 | 83/02/28 | 50-334 | S |
| 8303140513 | 8303140499 | 83/03/09 | 40-8713 | |
| 8303140520 | 8303140509 | 83/03/03 | 50-260 | S |
| 8303140525 | 8303140518 | 83/03/02 | 50-316 | S |
| 8303140527 | 8303140521 | 83/03/07 | 50-250 | P |
| 8303140531 | 8303140510 | 83/03/02 | 50-255 | S |
| 8303140532 | 8303140523 | 83/02/25 | 50-281 | S |
| 8303140535 | 8303140516 | 83/03/08 | 50-304 | S |
| 8303140536 | 8303140522 | 83/03/03 | 50-309 | S |
| 8303140537 | 8303140530 | 83/02/28 | 50-278 | S |
| 8303140538 | 8303140529 | 83/03/04 | 50-29 | S |
| 8303140539 | 8303140526 | 83/03/03 | 50-327 | S |
| 8303140540 | 8303140528 | 83/03/01 | 50-346 | S |
| 8303140543 | 8303140523 | 83/02/25 | 50-281 | S |
| 8303140551 | 8303140542 | 83/02/25 | 50-280 | S |
| 8303140554 | 8303140548 | 83/03/03 | 50-327 | S |
| 8303140555 | 8303140546 | 83/03/08 | 50-528 | G |
| 8303140556 | 8303140552 | 83/02/25 | XPORTLIC | |
| 8303140559 | 8303140553 | 83/02/07 | 50-443 | G |
| 8303140560 | 8303140542 | 83/02/25 | 50-280 | S |
| 8303140563 | 8303140550 | 83/03/04 | 50-304 | S |
| 8303140565 | 8303140557 | 83/03/03 | 50-416 | S |
| 8303140566 | 8303140553 | 83/02/07 | 50-443 | G |
| 8303140567 | 8303140562 | 83/02/25 | 50-324 | S |
| 8303140568 | 8303140545 | 83/03/04 | 50-272 | S |
| 8303140571 | 8303140564 | 83/02/25 | 50-275 | P |
| 8303140575 | 8303140553 | 83/02/07 | 50-443 | G |
| 8303140579 | 8303140564 | 83/02/25 | 50-275 | P |
| 8303140580 | 8303140570 | 83/03/01 | 50-321 | S |
| 8303140583 | 8303140576 | 83/03/02 | 50-272 | S |
| 8303140588 | 8303140584 | 83/02/24 | 50-321 | S |
| 8303140593 | 8303140581 | 83/03/08 | 50-313 | G |
| 8303140595 | 8303140587 | 83/03/04 | 50-304 | S |
| 8303140598 | 8303140592 | 83/02/25 | 50-293 | S |
| 8303140599 | 8303140590 | 83/03/01 | MISC | |
| 8303140604 | 8303140601 | 83/03/04 | 50-259 | S |
| 8303140606 | 8303140590 | 83/03/01 | MISC | |
| 8303140610 | 8303140603 | 83/03/02 | 50-315 | S |
| 8303140621 | 8303140614 | 82/12/30 | 50-272 | G |
| 8303140632 | 8303140629 | 83/03/01 | COMMISSION | |
| 8303140637 | 8303140629 | 83/03/01 | COMMISSION | |
| 8303140644 | 8303140629 | 83/03/01 | COMMISSION | |
| 8303140650 | 8303140646 | 83/02/28 | 40-8602 | |
| 8303140695 | 8303140692 | 83/02/28 | 40-8681 | |
| 8303150002 | 8303150001 | 83/03/08 | 50-267 | P |
| 8303150004 | 8303150001 | 83/03/08 | 50-267 | P |
| 8303150008 | 8303150001 | 83/03/08 | 50-267 | P |
| 8303150014 | 8303150007 | 83/02/28 | 70-1201 | |
| 8303150051 | 8303150046 | 83/03/03 | ORG | |
| 8303150052 | 8303150044 | 83/03/07 | REVIEW GRP | |
| 8303150079 | 8303150071 | 83/03/04 | 50-280 | P |
| 8303150085 | 8303150071 | 83/03/04 | 50-280 | P |
| 8303150092 | 8303150071 | 83/03/04 | 50-280 | P |
| 8303150116 | 8303150113 | 83/02/25 | PROJ | |
| 8303150135 | 8303150128 | 83/03/02 | 50-142 | P |
| 8303150140 | 8303150128 | 83/03/02 | 50-142 | P |
| 8303150153 | 8303150143 | 83/03/01 | 50-295 | G |
| 8303150158 | 8303150151 | 83/03/07 | CONTRACT | |
| 8303150161 | 8303150143 | 83/03/01 | 50-295 | G |

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

| ACCESSION NUMBER | | | | |
|---|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
| 8303150166 | 8303150138 | 83/03/04 | 50-280 | S |
| 8303150169 | 8303150164 | 82/11/12 | QA999 | |
| 8303150171 | 8303150167 | 83/03/03 | CONTRACT | |
| 8303150172 | 8303150164 | 82/11/12 | QA999 | |
| 8303150175 | 8303150138 | 83/03/04 | 50-280 | S |
| 8303150179 | 8303150164 | 82/11/12 | QA999 | |
| 8303150183 | 8303150146 | 83/03/02 | 50-416 | S |
| 8303150184 | 8303150138 | 83/03/04 | 50-280 | S |
| 8303150193 | 8303150185 | 83/03/08 | 50-259 | S |
| 8303150202 | 8303150195 | 83/03/10 | 50-443 | A |
| 8303150203 | 8303150143 | 83/03/01 | 50-295 | G |
| 8303150214 | 8303150204 | 83/02/24 | 50-321 | S |
| 8303150219 | 8303150199 | 83/02/25 | 50-382 | G |
| 8303150221 | 8303150215 | 83/02/22 | 50-331 | R |
| 8303150223 | 8303150143 | 83/03/01 | 50-295 | G |
| 8303150226 | 8303150217 | 83/03/04 | 50-338 | S |
| 8303150234 | 8303150227 | 83/03/11 | 50-409 | G |
| 8303150241 | 8303150235 | 83/03/01 | 50-267 | R |
| 8303150250 | 8303150247 | 83/03/04 | 50-267 | S |
| 8303150254 | 8303150242 | 83/03/01 | 50-416 | S |
| 8303150260 | 8303150256 | 83/02/22 | 50-298 | R |
| 8303150263 | 8303150248 | 83/03/09 | 50-296 | S |
| 8303150266 | 8303150259 | 83/01/19 | QA999 | |
| 8303150271 | 8303150259 | 83/01/19 | QA999 | |
| 8303150272 | 8303150265 | 83/03/09 | 50-289 | P |
| 8303150278 | 8303150259 | 83/01/19 | QA999 | |
| 8303150279 | 8303150270 | 83/03/08 | 50-320 | G |
| 8303150280 | 8303150277 | 83/03/01 | 50-282 | R |
| 8303150288 | 8303150285 | 83/03/11 | 50-280 | P |
| 8303150290 | 8303150284 | 83/02/23 | 50-272 | R |
| 8303150293 | 8303150270 | 83/03/08 | 50-320 | G |
| 8303150301 | 8303150270 | 83/03/08 | 50-320 | G |
| 8303150303 | 8303150299 | 83/02/28 | 50-483 | K |
| 8303150304 | 8303150299 | 83/02/28 | 50-483 | K |
| 8303150305 | 8303150296 | 83/02/24 | 50-361 | G |
| 8303150306 | 8303150300 | 83/03/08 | 50-259 | S |
| 8303150307 | 8303150295 | 83/03/01 | 50-263 | R |
| 8303150309 | 8303150297 | 83/03/07 | 50-296 | S |
| 8303150321 | 8303150318 | 83/03/10 | 50-251 | R |
| 8303150324 | 8303150319 | 83/03/07 | 50-267 | F |
| 8303150327 | 8303150316 | 83/03/10 | 50-289 | P |
| 8303150337 | 8303150335 | 83/03/03 | 50-334 | R |
| 8303150338 | 8303150333 | 83/03/09 | 50-266 | P |
| 8303150346 | 8303150342 | 83/03/07 | 50-312 | R |
| 8303150347 | 8303150341 | 83/03/04 | 50-395 | S |
| 8303150350 | 8303150348 | 83/03/11 | 50-267 | R |
| 8303150354 | 8303150349 | 83/03/07 | 50-275 | R |
| 8303150356 | 8303150351 | 83/03/09 | QA999 | |
| 8303150360 | 8303150355 | 83/03/07 | CONTRACT | |
| 8303150366 | 8303150361 | 83/02/22 | QA999 | |
| 8303150369 | 8303150362 | 83/03/07 | 50-324 | R |
| 8303150373 | 8303150361 | 83/02/22 | QA999 | |
| 8303150375 | 8303150368 | 83/03/10 | 70-143 | |
| 8303150376 | 8303150370 | 83/02/15 | 50-280 | R |
| 8303150379 | 8303150371 | 83/03/11 | 50-277 | P |
| 8303150380 | 8303150372 | 83/03/08 | 50-219 | G |
| 8303150382 | 8303150368 | 83/03/10 | 70-143 | |
| 8303150383 | 8303150377 | 83/03/10 | 50-237 | P |
| 8303150384 | 8303150381 | 83/02/15 | 50-313 | R |
| 8303150385 | 8303150371 | 83/03/11 | 50-277 | P |
| 8303150386 | 8303150368 | 83/03/10 | 70-143 | |
| 8303150395 | 8303150389 | 83/03/07 | 50-249 | S |
| 8303150400 | 8303150397 | 83/03/10 | 50-400 | G |
| 8303150401 | 8303150398 | 83/03/04 | 50-327 | G |
| 8303150404 | 8303150399 | 83/03/08 | 50-280 | P |
| 8303150405 | 8303150397 | 83/03/10 | 50-400 | G |
| 8303150411 | 8303150397 | 83/03/10 | 50-400 | G |
| 8303150412 | 8303150410 | 83/02/09 | 50-409 | R |
| 8303150421 | 8303150420 | 83/02/15 | 50-245 | R |
| 8303150425 | 8303150424 | 83/02/09 | 50-309 | R |
| 8303150426 | 8303150422 | 83/02/03 | 50-373 | R |
| 8303150431 | 8303150428 | 83/02/16 | 50-219 | R |
| 8303150433 | 8303150430 | 83/02/15 | 50-336 | R |
| 8303150441 | 8303150438 | 83/02/15 | 50-338 | R |
| 8303150445 | 8303150440 | 83/02/16 | 50-327 | R |
| 8303150447 | 8303150438 | 83/02/15 | 50-338 | R |
| 8303150448 | 8303150443 | 83/03/01 | 50-416 | S |
| 8303150449 | 8303150446 | 83/03/02 | 50-293 | P |
| 8303150455 | 8303150450 | 83/02/23 | 50-267 | G |
| 8303150456 | 8303150452 | 83/02/24 | 50-321 | S |

| ACCESSION NUMBER | | | | |
|---|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
| 8303150457 | 8303150451 | 83/03/02 | 50-369 | S |
| 8303150459 | 8303150458 | 83/03/14 | 50-537 | G |
| 8303150462 | 8303150460 | 83/02/10 | 50-282 | R |
| 8303150464 | 8303150463 | 83/02/14 | 50-327 | R |
| 8303150467 | 8303150466 | 83/03/07 | 50-296 | S |
| 8303150470 | 8303150468 | 83/02/18 | QA999 | |
| 8303150474 | 8303150473 | 83/03/11 | 50-313 | P |
| 8303150475 | 8303150472 | 83/03/09 | 50-327 | S |
| 8303150480 | 8303150478 | 83/03/09 | 50-321 | R |
| 8303150484 | 8303150481 | 83/02/28 | 50-368 | S |
| 8303150487 | 8303150485 | 83/02/14 | 50-387 | R |
| 8303150491 | 8303150488 | 83/02/24 | 50-498 | G |
| 8303150495 | 8303150482 | 83/03/01 | 50-366 | S |
| 8303150496 | 8303150490 | 83/02/09 | 50-259 | R |
| 8303150501 | 8303150492 | 83/02/24 | 50-397 | G |
| 8303150502 | 8303150489 | 83/02/16 | 50-344 | R |
| 8303150504 | 8303150498 | 83/02/08 | 50-346 | R |
| 8303150505 | 8303150476 | 83/03/10 | 50-370 | G |
| 8303150506 | 8303150497 | 83/02/23 | 50-529 | G |
| 8303150512 | 8303150508 | 83/02/04 | 50-275 | R |
| 8303150513 | 8303150503 | 83/03/10 | 50-482 | K |
| 8303150518 | 8303150509 | 83/03/11 | 50-29 | P |
| 8303150519 | 8303150516 | 83/02/04 | 50-244 | R |
| 8303150520 | 8303150515 | 83/02/28 | 50-445 | G |
| 8303150525 | 8303150524 | 83/02/13 | 50-213 | R |
| 8303150527 | 8303150517 | 83/02/15 | 50-368 | R |
| 8303150529 | 8303150514 | 83/02/04 | 50-155 | R |
| 8303150530 | 8303150515 | 83/02/28 | 50-445 | G |
| 8303150531 | 8303150510 | 83/02/14 | 50-315 | R |
| 8303150533 | 8303150511 | 83/02/23 | 50-70 | G |
| 8303150536 | 8303150532 | 83/02/09 | 50-286 | R |
| 8303150538 | 8303150528 | 83/03/10 | 50-389 | E |
| 8303150543 | 8303150535 | 83/03/11 | 50-358 | G |
| 8303150544 | 8303150537 | 83/02/14 | 50-316 | R |
| 8303150546 | 8303150539 | 83/02/14 | 50-250 | R |
| 8303150555 | 8303150550 | 83/02/04 | 50-298 | R |
| 8303150556 | 8303150549 | 83/02/07 | 50-29 | R |
| 8303150557 | 8303150540 | 83/03/09 | 50-309 | G |
| 8303150558 | 8303150539 | 83/02/14 | 50-250 | R |
| 8303150561 | 8303150552 | 83/02/03 | 50-133 | R |
| 8303150563 | 8303150545 | 83/02/22 | 50-321 | S |
| 8303150567 | 8303150559 | 83/02/18 | QA999 | |
| 8303150569 | 8303150551 | 83/03/01 | 50-3 | R |
| 8303150570 | 8303150564 | 83/03/10 | 50-261 | R |
| 8303150574 | 8303150566 | 83/02/15 | 50-361 | R |
| 8303150577 | 8303150571 | 83/03/04 | 50-277 | P |
| 8303150578 | 8303150565 | 83/03/04 | 50-261 | G |
| 8303150579 | 8303150559 | 83/02/18 | QA999 | |
| 8303150580 | 8303150575 | 83/02/14 | 50-293 | R |
| 8303150581 | 8303150572 | 83/02/09 | 50-334 | R |
| 8303150586 | 8303150576 | 83/03/02 | 50-416 | S |
| 8303150587 | 8303150559 | 83/02/18 | QA999 | |
| 8303150591 | 8303150589 | 83/02/15 | 50-206 | R |
| 8303150592 | 8303150566 | 83/02/15 | 50-361 | R |
| 8303150594 | 8303150559 | 83/02/18 | QA999 | |
| 8303150598 | 8303150595 | 83/02/28 | 50-410 | G |
| 8303150600 | 8303150595 | 83/02/28 | 50-410 | G |
| 8303150606 | 8303150601 | 83/03/10 | 50-254 | G |
| 8303150607 | 8303150604 | 83/02/09 | 50-263 | R |
| 8303150612 | 8303150609 | 83/03/11 | 50-331 | G |
| 8303150618 | 8303150617 | 83/02/10 | CONTRACT | |
| 8303150642 | 8303150620 | 83/03/03 | 50-272 | S |
| 8303150646 | 8303150620 | 83/03/03 | 50-272 | S |
| 8303150663 | 8303150658 | 83/03/07 | CONTRACT | |
| 8303150692 | 8303150683 | 83/03/01 | 50-277 | P |
| 8303150697 | 8303150683 | 83/03/01 | 50-277 | P |
| 8303150705 | 8303150683 | 83/03/01 | 50-277 | P |
| 8303150712 | 8303150708 | 83/03/07 | CONTRACT | |
| 8303160016 | 8303160015 | 83/02/28 | 50-410 | A |
| 8303160018 | 8303160015 | 83/02/28 | 50-410 | A |
| 8303160050 | 8303160045 | 83/03/02 | XPORTLIC | |
| 8303160060 | 8303160056 | 83/02/25 | CONTRACT | |
| 8303160068 | 8303160065 | 83/03/09 | 50-272 | P |
| 8303160069 | 8303160064 | 83/03/04 | CONTRACT | |
| 8303160071 | 8303160066 | 83/03/01 | CONTRACT | |
| 8303160085 | 8303160079 | 83/03/04 | CONTRACT | |
| 8303160097 | 8303160091 | 83/02/15 | CONTRACT | |
| 8303160102 | 8303160099 | 83/02/24 | 27-39 | |
| 8303160108 | 8303160104 | 83/02/28 | 50-289 | P |
| 8303160110 | 8303160104 | 83/02/28 | 50-289 | P |

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS



| ACCESSION NUMBER | | | | |
|---|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
| 8303160114 | 8303160104 | 83/02/28 | 50-289 | P |
| 8303160125 | 8303160121 | 83/03/04 | 50-269 | P |
| 8303160135 | 8303160121 | 83/03/04 | 50-269 | P |
| 8303160143 | 8303160136 | 82/10/29 | 50-220 | R |
| 8303160153 | 8303160145 | 83/03/02 | 50-318 | S |
| 8303160157 | 8303160149 | 83/03/04 | 50-281 | S |
| 8303160165 | 8303160149 | 83/03/04 | 50-281 | S |
| 8303160168 | 8303160156 | 83/02/27 | 50-247 | S |
| 8303160177 | 8303160171 | 83/03/09 | 50-335 | P |
| 8303160180 | 8303160174 | 83/03/04 | 50-387 | S |
| 8303160184 | 8303160176 | 83/03/07 | 50-318 | S |
| 8303160191 | 8303160186 | 83/03/04 | 50-387 | S |
| 8303160201 | 8303160194 | 83/03/04 | 50-260 | S |
| 8303160209 | 8303160197 | 83/03/04 | 50-219 | S |
| 8303160211 | 8303160194 | 83/03/04 | 50-280 | S |
| 8303160219 | 8303160213 | 83/03/09 | 50-30 | R |
| 8303160222 | 8303160214 | 83/03/04 | 50-219 | S |
| 8303160224 | 8303160215 | 83/03/11 | 50-412 | G |
| 8303160232 | 8303160225 | 83/03/04 | 50-219 | S |
| 8303160236 | 8303160229 | 83/02/24 | TOPREP | |
| 8303160242 | 8303160230 | 83/03/04 | 50-324 | S |
| 8303160250 | 8303160241 | 83/03/04 | 50-387 | S |
| 8303160265 | 8303160255 | 83/03/03 | 50-318 | S |
| 8303160271 | 8303160266 | 83/03/11 | 50-192 | E |
| 8303160274 | 8303160268 | 83/03/03 | 50-317 | S |
| 8303160276 | 8303160267 | 83/03/10 | 50-250 | P |
| 8303160282 | 8303160267 | 83/03/10 | 50-250 | P |
| 8303160286 | 8303160278 | 83/03/04 | 50-324 | S |
| 8303160289 | 8303160281 | 83/03/11 | 50-387 | P |
| 8303160295 | 8303160267 | 83/03/10 | 50-250 | P |
| 8303160297 | 8303160281 | 83/03/11 | 50-387 | P |
| 8303160304 | 8303160267 | 83/03/10 | 50-250 | P |
| 8303160309 | 8303160303 | 83/03/16 | 50-219 | R |
| 8303160310 | 8303160300 | 83/03/07 | 50-416 | S |
| 8303160313 | 8303160267 | 83/03/10 | 50-250 | P |
| 8303160324 | 8303160312 | 83/03/02 | 50-318 | S |
| 8303160325 | 8303160318 | 83/03/11 | 50-302 | R |
| 8303160338 | 8303160332 | 83/03/11 | 50-277 | R |
| 8303160342 | 8303160337 | 83/03/10 | 50-275 | R |
| 8303160356 | 8303160335 | 83/03/01 | 50-309 | S |
| 8303160358 | 8303160352 | 83/03/10 | 50-305 | R |
| 8303160367 | 8303160363 | 83/03/09 | 50-271 | R |
| 8303160373 | 8303160360 | 83/03/10 | 50-335 | P |
| 8303160375 | 8303160369 | 83/03/04 | 50-387 | S |
| 8303160377 | 8303160374 | 83/03/02 | 50-286 | R |
| 8303160379 | 8303160360 | 83/03/10 | 50-335 | P |
| 8303160385 | 8303160382 | 83/03/11 | 50-498 | K |
| 8303160386 | 8303160360 | 83/03/10 | 50-335 | P |
| 8303160391 | 8303160389 | 83/03/02 | 50-254 | R |
| 8303160394 | 8303160360 | 83/03/10 | 50-335 | P |
| 8303160395 | 8303160388 | 83/03/03 | 50-313 | P |
| 8303160403 | 8303160397 | 83/03/04 | 50-416 | S |
| 8303160404 | 8303160392 | 83/03/01 | 50-286 | G |
| 8303160411 | 8303160410 | 83/03/03 | 50-318 | S |
| 8303160417 | 8303160414 | 83/03/10 | 50-324 | P |
| 8303160418 | 8303160414 | 83/03/10 | 50-324 | P |
| 8303160421 | 8303160414 | 83/03/10 | 50-324 | P |
| 8303160423 | 8303160419 | 83/03/11 | 50-260 | S |
| 8303160431 | 8303160429 | 83/03/04 | 50-272 | G |
| 8303160433 | 8303160429 | 83/03/04 | 50-272 | G |
| 8303160438 | 8303160432 | 83/03/09 | 50-296 | S |
| 8303160440 | 8303160436 | 83/03/10 | 50-416 | S |
| 8303160441 | 8303160439 | 83/03/09 | 50-538 | R |
| 8303160445 | 8303160443 | 83/03/03 | 50-321 | S |
| 8303160455 | 8303160452 | 83/03/07 | 50-416 | S |
| 8303160460 | 8303160457 | 83/03/07 | 50-416 | S |
| 8303160467 | 8303160456 | 83/03/02 | 50-213 | G |
| 8303160472 | 8303160466 | 83/03/03 | 70-371 | |
| 8303160481 | 8303160477 | 83/03/03 | 50-20 | G |
| 8303160482 | 8303160461 | 83/03/02 | 50-289 | G |
| 8303160483 | 8303160471 | 83/03/04 | 50-302 | S |
| 8303160488 | 8303160477 | 83/03/03 | 50-20 | G |
| 8303160496 | 8303160491 | 83/03/04 | 70-820 | |
| 8303160497 | 8303160490 | 83/03/07 | 50-324 | S |
| 8303160503 | 8303160491 | 83/03/04 | 70-820 | |
| 8303160508 | 8303160501 | 83/03/03 | 50-333 | G |
| 8303160526 | 8303160516 | 83/03/03 | 50-29 | G |
| 8303160536 | 8303160531 | 83/03/09 | 50-296 | S |
| 8303160537 | 8303160530 | 83/03/09 | 50-289 | P |
| 8303160538 | 8303160533 | 83/03/02 | 50-333 | G |

| ACCESSION NUMBER | | | | |
|---|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
| 8303160541 | 8303160530 | 83/03/09 | 50-289 | P |
| 8303160544 | 8303160524 | 83/03/04 | 50-29 | G |
| 8303160546 | 8303160533 | 83/03/02 | 50-333 | G |
| 8303160549 | 8303160540 | 83/03/07 | 50-416 | S |
| 8303160560 | 8303160555 | 83/03/04 | 50-269 | G |
| 8303160564 | 8303160558 | 83/03/03 | 50-317 | G |
| 8303160567 | 8303160559 | 83/02/28 | 50-277 | R |
| 8303160570 | 8303160558 | 83/03/03 | 50-317 | G |
| 8303160572 | 8303160565 | 83/03/04 | 50-269 | S |
| 8303160574 | 8303160551 | 83/03/08 | 50-416 | S |
| 8303160577 | 8303160569 | 83/03/10 | 50-266 | R |
| 8303160582 | 8303160576 | 83/03/07 | 50-324 | S |
| 8303160586 | 8303160575 | 83/03/09 | 50-335 | S |
| 8303160588 | 8303160583 | 83/03/09 | 50-321 | R |
| 8303160596 | 8303160593 | 83/02/16 | 50-254 | F |
| 8303160600 | 8303160593 | 83/02/16 | 50-254 | F |
| 8303160616 | 8303160612 | 83/03/04 | 50-245 | G |
| 8303160619 | 8303160613 | 83/01/28 | 40-1341 | |
| 8303160622 | 8303160617 | 83/02/25 | COMMISSION | |
| 8303160623 | 8303160613 | 83/01/28 | 40-1341 | |
| 8303160641 | 8303160638 | 83/03/01 | 50-289 | P |
| 8303160644 | 8303160638 | 83/03/01 | 50-289 | P |
| 8303160650 | 8303160648 | 83/02/25 | ACRS | |
| 8303160658 | 8303160655 | 83/02/22 | 40-8698 | |
| 8303160667 | 8303160660 | 83/03/09 | CONTRACT | |
| 8303160678 | 8303160674 | 83/02/28 | TOPREP | |
| 8303160696 | 8303160692 | 83/03/02 | 71-6574 | |
| 8303160704 | 8303160702 | 83/03/03 | 70-1193 | |
| 8303160705 | 8303160675 | 83/03/04 | 50-352 | E |
| 8303160707 | 8303160702 | 83/03/03 | 70-1193 | |
| 8303160721 | 8303160717 | 83/02/25 | COMMISSION | |
| 8303160738 | 8303160730 | 83/03/16 | 50-272 | S |
| 8303160745 | 8303160730 | 83/03/16 | 50-272 | S |
| 8303160778 | 8303160775 | 83/03/08 | 50-329 | G |
| 8303170004 | 8303170003 | 83/02/25 | 27-48 | |
| 8303170018 | 8303170015 | 83/03/07 | 50-206 | U |
| 8303170019 | 8303170013 | 83/02/22 | CONTRACT | |
| 8303170030 | 8303170025 | 83/03/15 | 50-443 | G |
| 8303170101 | 8303170095 | 83/02/17 | 50-409 | R |
| 8303170151 | 8303170145 | 83/03/14 | 50-219 | P |
| 8303170157 | 8303170154 | 83/03/02 | XPORTLIC | |
| 8303170169 | 8303170159 | 83/03/14 | 50-171 | I |
| 8303170182 | 8303170159 | 83/03/14 | 50-171 | I |
| 8303170188 | 8303170179 | 83/03/14 | 50-409 | P |
| 8303170193 | 8303170159 | 83/03/14 | 50-171 | I |
| 8303170197 | 8303170179 | 83/03/14 | 50-409 | P |
| 8303170203 | 8303170170 | 83/03/11 | 50-206 | P |
| 8303170206 | 8303170159 | 83/03/14 | 50-171 | I |
| 8303170208 | 8303170205 | 83/03/08 | ORG | |
| 8303170211 | 8303170170 | 83/03/11 | 50-206 | P |
| 8303170212 | 8303170210 | 83/03/07 | 50-220 | R |
| 8303170216 | 8303170213 | 83/03/03 | 50-220 | F |
| 8303170225 | 8303170221 | 83/02/15 | 40-8502 | |
| 8303170256 | 8303170249 | 83/03/14 | 50-409 | P |
| 8303170271 | 8303170261 | 83/03/14 | 50-29 | P |
| 8303170289 | 8303170282 | 83/03/14 | 50-255 | P |
| 8303170308 | 8303170305 | 83/03/14 | 50-206 | P |
| 8303170310 | 8303170307 | 83/03/11 | 50-373 | P |
| 8303170327 | 8303170322 | 83/03/09 | 50-237 | S |
| 8303170354 | 8303170335 | 83/03/09 | 50-304 | S |
| 8303170366 | 8303170362 | 83/02/14 | 50-346 | R |
| 8303170372 | 8303170361 | 83/03/11 | 50-331 | S |
| 8303170375 | 8303170371 | 83/03/04 | 50-10 | G |
| 8303170377 | 8303170371 | 83/03/04 | 50-10 | G |
| 8303170379 | 8303170378 | 83/03/09 | 50-254 | S |
| 8303170395 | 8303170374 | 83/02/11 | 50-18 | R |
| 8303170404 | 8303170399 | 83/02/11 | 50-183 | R |
| 8303170408 | 8303170369 | 83/03/03 | 50-266 | G |
| 8303170419 | 8303170414 | 83/03/11 | 50-305 | G |
| 8303170426 | 8303170422 | 83/03/08 | 50-443 | G |
| 8303170427 | 8303170423 | 83/03/14 | 50-382 | G |
| 8303170430 | 8303170422 | 83/03/08 | 50-443 | G |
| 8303170433 | 8303170428 | 83/03/04 | 50-329 | G |
| 8303170436 | 8303170428 | 83/03/04 | 50-329 | G |
| 8303170444 | 8303170434 | 83/02/02 | 50-456 | G |
| 8303170449 | 8303170442 | 83/03/08 | 50-346 | S |
| 8303170455 | 8303170448 | 83/03/10 | 70-2837 | |
| 8303170459 | 8303170445 | 83/03/14 | 50-266 | G |
| 8303170460 | 8303170453 | 83/03/10 | 50-331 | P |
| 8303170465 | 8303170457 | 83/03/08 | 50-70 | R |

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

| ACCESSION NUMBER | | | |
|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 8303170467 | 8303170463 | 83/03/10 | 50-259 R |
| 8303170473 | 8303170468 | 83/03/08 | 50-254 S |
| 8303170481 | 8303170477 | 83/03/04 | 50-373 S |
| 8303170486 | 8303170478 | 83/03/07 | 50-373 S |
| 8303170495 | 8303170490 | 83/02/25 | 50-263 Q |
| 8303170496 | 8303170488 | 83/03/14 | 50-261 G |
| 8303170499 | 8303170494 | 83/03/10 | 50-272 R |
| 8303170502 | 8303170497 | 83/03/10 | 50-295 S |
| 8303170506 | 8303170501 | 83/02/09 | 50-295 Q |
| 8303170512 | 8303170500 | 83/03/11 | 50-263 P |
| 8303170515 | 8303170510 | 83/03/01 | 50-373 Q |
| 8303170516 | 8303170504 | 83/03/15 | 50-250 P |
| 8303170519 | 8303170510 | 83/03/01 | 50-373 Q |
| 8303170521 | 8303170500 | 83/03/11 | 50-263 P |
| 8303170526 | 8303170522 | 83/03/08 | 50-346 S |
| 8303170527 | 8303170500 | 83/03/11 | 50-263 P |
| 8303170534 | 8303170529 | 83/02/23 | 50-373 Q |
| 8303170536 | 8303170500 | 83/03/11 | 50-263 P |
| 8303170540 | 8303170529 | 83/02/23 | 50-373 Q |
| 8303170550 | 8303170548 | 83/03/09 | 50-461 A |
| 8303170551 | 8303170546 | 83/03/01 | 50-254 Q |
| 8303170557 | 8303170532 | 83/02/25 | 50-10 G |
| 8303170611 | 8303170606 | 83/03/04 | 50-395 P |
| 8303170618 | 8303170606 | 83/03/04 | 50-395 P |
| 8303170623 | 8303170606 | 83/03/04 | 50-395 P |
| 8303170629 | 8303170606 | 83/03/04 | 50-395 P |
| 8303170648 | 8303170645 | 83/03/04 | 50-302 P |
| 8303170650 | 8303170645 | 83/03/04 | 50-302 P |
| 8303170656 | 8303170653 | 83/03/08 | CONTRACT |
| 8303180015 | 8303180010 | 83/02/25 | 40-8102 |
| 8303180019 | 8303180010 | 83/02/25 | 40-8102 |
| 8303180030 | 8303180025 | 83/03/10 | 50-338 S |
| 8303180033 | 8303180027 | 83/03/11 | 50-416 S |
| 8303180062 | 8303180057 | 82/12/24 | CONTRACT |
| 8303180065 | 8303180060 | 83/03/01 | 40-8745 |
| 8303180067 | 8303180063 | 83/02/17 | CONTRACT |
| 8303180068 | 8303180064 | 83/02/23 | 27-48 |
| 8303180073 | 8303180069 | 83/02/17 | 50-265 P |
| 8303180075 | 8303180072 | 83/02/17 | CONTRACT |
| 8303180081 | 8303180071 | 83/03/02 | WASTE MGT |
| 8303180085 | 8303180069 | 83/02/17 | 50-265 P |
| 8303180086 | 8303180080 | 83/01/27 | CONTRACT |
| 8303180087 | 8303180082 | 83/03/02 | XPORTLIC |
| 8303180091 | 8303180071 | 83/03/02 | WASTE MGT |
| 8303180093 | 8303180069 | 83/02/17 | 50-265 P |
| 8303180096 | 8303180092 | 83/02/17 | CONTRACT |
| 8303180100 | 8303180071 | 83/03/02 | WASTE MGT |
| 8303180102 | 8303180097 | 83/02/28 | 40-3453 |
| 8303180106 | 8303180097 | 83/02/28 | 40-3453 |
| 8303180107 | 8303180071 | 83/03/02 | WASTE MGT |
| 8303180111 | 8303180071 | 83/03/02 | WASTE MGT |
| 8303180114 | 8303180110 | 83/02/28 | 40-8728 |
| 8303180115 | 8303180071 | 83/03/02 | WASTE MGT |
| 8303180120 | 8303180071 | 83/03/02 | WASTE MGT |
| 8303180123 | 8303180071 | 83/03/02 | WASTE MGT |
| 8303180124 | 8303180122 | 83/03/10 | 50-443 E |
| 8303180126 | 8303180071 | 83/03/02 | WASTE MGT |
| 8303180136 | 8303180133 | 83/03/09 | 70-2946 |
| 8303180139 | 8303180134 | 83/03/1[illegible] | 71-9119 |
| 8303180142 | 8303180135 | 83/03/02 | WASTE MGT |
| 8303180156 | 8303240054 | 83/03/15 | REVIEW GRP |
| 8303180161 | 8303180155 | 83/03/01 | XPORTLIC |
| 8303180172 | 8303180169 | 83/03/01 | 40-8102 |
| 8303180180 | 8303180173 | 83/03/01 | 40-4492 |
| 8303180190 | 8303180164 | 83/03/09 | 50-387 P |
| 8303180195 | 8303180164 | 83/03/09 | 50-387 P |
| 8303180198 | 8303180164 | 83/03/09 | 50-387 P |
| 8303180199 | 8303180185 | 83/03/11 | 50-302 S |
| 8303180200 | 8303180192 | 83/02/25 | QA999 |
| 8303180204 | 8303180192 | 83/02/25 | QA999 |
| 8303180212 | 8303180192 | 83/02/25 | QA999 |
| 8303180218 | 8303180213 | 83/03/10 | 50-324 S |
| 8303180223 | 8303180215 | 83/01/06 | 50-267 Q |
| 8303180225 | 8303180221 | 83/01/19 | 50-285 Q |
| 8303180226 | 8303180222 | 83/03/15 | 50-291 Q |
| 8303180227 | 8303180217 | 83/03/14 | 50-247 Q |
| 8303180230 | 8303180228 | 82/12/30 | 50-298 Q |
| 8303180232 | 8303180201 | 83/03/11 | 50-324 S |
| 8303180234 | 8303180229 | 83/03/11 | 50-395 S |
| 8303180237 | 8303180233 | 83/01/19 | 40-8752 |

| ACCESSION NUMBER | | | |
|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 8303180241 | 8303180238 | 83/03/10 | 50-395 S |
| 8303180243 | 8303180239 | 82/11/17 | 40-6659 |
| 8303180244 | 8303180224 | 83/01/26 | 50-285 Q |
| 8303180254 | 8303180248 | 83/03/07 | 50-416 S |
| 8303180260 | 8303180253 | 83/03/11 | 50-302 S |
| 8303180268 | 8303180258 | 83/03/09 | 50-395 S |
| 8303180272 | 8303180265 | 83/02/23 | 50-361 S |
| 8303180292 | 8303180281 | 83/03/11 | 50-416 S |
| 8303180295 | 8303180293 | 83/03/14 | 50-400 Q |
| 8303180308 | 8303180302 | 83/03/15 | 50-320 P |
| 8303180313 | 8303180302 | 83/03/15 | 50-320 P |
| 8303180314 | 8303180305 | 83/03/10 | 50-272 S |
| 8303180324 | 8303180319 | 83/03/11 | 50-272 S |
| 8303180325 | 8303180317 | 83/03/14 | 50-285 R |
| 8303180326 | 8303180321 | 83/03/04 | 70-371 |
| 8303180329 | 8303180323 | 83/03/10 | 50-443 Q |
| 8303180335 | 8303180311 | 83/03/11 | 50-325 S |
| 8303180336 | 8303180330 | 83/03/11 | 50-336 S |
| 8303180338 | 8303180332 | 83/03/09 | 50-287 S |
| 8303180343 | 8303180340 | 83/03/11 | 50-245 S |
| 8303180344 | 8303180331 | 83/03/10 | 50-397 Q |
| 8303180351 | 8303180342 | 83/03/10 | 50-339 S |
| 8303180357 | 8303180353 | 83/01/11 | 50-482 Q |
| 8303180367 | 8303180339 | 83/03/11 | 50-324 S |
| 8303180368 | 8303180361 | 83/03/08 | 50-272 S |
| 8303180369 | 8303180359 | 83/03/07 | 50-416 S |
| 8303180370 | 8303180363 | 83/03/03 | 50-366 S |
| 8303180372 | 8303180366 | 83/02/25 | QA999 |
| 8303180376 | 8303180373 | 83/03/15 | 50-369 R |
| 8303180381 | 8303180366 | 83/02/25 | QA999 |
| 8303180382 | 8303180374 | 83/03/11 | 50-336 S |
| 8303180384 | 8303180378 | 83/03/06 | 50-348 S |
| 8303180386 | 8303180379 | 83/03/15 | 50-269 R |
| 8303180390 | 8303180388 | 83/02/25 | QA999 |
| 8303180394 | 8303180388 | 83/02/25 | QA999 |
| 8303180396 | 8303180391 | 83/02/25 | 50-10 Q |
| 8303180397 | 8303180392 | 83/03/15 | 50-320 P |
| 8303180399 | 8303180388 | 83/02/25 | QA999 |
| 8303180403 | 8303180401 | 83/03/03 | 50-312 Q |
| 8303180407 | 8303180401 | 83/03/03 | 50-312 Q |
| 8303180408 | 8303180404 | 83/03/09 | 50-269 S |
| 8303180411 | 8303180402 | 83/03/11 | 50-324 S |
| 8303180416 | 8303180414 | 83/03/11 | 50-220 S |
| 8303180420 | 8303180419 | 83/03/11 | 50-272 S |
| 8303180421 | 8303180418 | 82/12/07 | 50-382 Q |
| 8303180425 | 8303180423 | 83/03/11 | 50-272 S |
| 8303180426 | 8303180422 | 83/03/07 | 50-289 S |
| 8303180427 | 8303180424 | 83/03/07 | 50-320 R |
| 8303180433 | 8303180430 | 83/01/05 | 50-313 Q |
| 8303180443 | 8303180435 | 83/03/03 | 50-362 S |
| 8303180469 | 8303180462 | 83/03/01 | 71-5874 |
| 8303180485 | 8303180475 | 83/03/11 | 50-213 P |
| 8303180487 | 8303180481 | 83/03/03 | 50-361 S |
| 8303180488 | 8303180483 | 83/02/28 | 71-9096 |
| 8303180493 | 8303180475 | 83/03/11 | 50-213 P |
| 8303180495 | 8303180486 | 83/03/07 | 50-362 S |
| 8303180504 | 8303180497 | 83/03/04 | 50-293 S |
| 8303180506 | 8303180500 | 83/02/14 | 50-213 F |
| 8303180517 | 8303180513 | 83/03/02 | 50-528 Q |
| 8303180519 | 8303180511 | 83/02/28 | 40-1162 |
| 8303180522 | 8303180513 | 83/03/02 | 50-528 Q |
| 8303180525 | 8303180520 | 83/03/07 | 50-361 S |
| 8303180526 | 8303180523 | 83/03/11 | 70-2910 |
| 8303180534 | 8303180527 | 83/03/03 | 71-9079 |
| 8303180536 | 8303180528 | 83/01/03 | CONTRACT |
| 8303180537 | 8303180530 | 83/03/15 | 50-327 P |
| 8303180538 | 8303180533 | 83/03/11 | 50-369 P |
| 8303180563 | 8303180559 | 83/03/09 | 50-289 P |
| 8303180584 | 8303180581 | 83/02/22 | WASTE MGT |
| 8303180603 | 8303180598 | 83/03/07 | XPORTLIC |
| 8303180622 | 8303180606 | 83/03/10 | COMMISSION |
| 8303180623 | 8303180618 | 83/03/11 | 50-275 P |
| 8303180627 | 8303180606 | 83/03/10 | COMMISSION |
| 8303180629 | 8303180618 | 83/03/11 | 50-275 P |
| 8303180669 | 8303180667 | 83/03/15 | 40-8027 |
| 8303180688 | 8303180684 | 83/03/07 | CONTRACT |
| 8303210002 | 8303210001 | 83/03/11 | 50-312 P |
| 8303210003 | 8303210001 | 83/03/11 | 50-312 P |
| 8303210008 | 8303210007 | 83/03/10 | 50-313 P |
| 8303210009 | 8303210006 | 83/03/11 | 50-269 P |

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS



ACCESSION NUMBER

| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
|---|---|---|---|---|
| 8303210010 | 8303210007 | 83/03/10 | 50-313 | P |
| 8303210011 | 8303210007 | 83/03/10 | 50-313 | P |
| 8303210013 | 8303210006 | 83/03/11 | 50-269 | P |
| 8303210015 | 8303210006 | 83/03/11 | 50-269 | P |
| 8303210025 | 8303210018 | 83/03/11 | 50-289 | P |
| 8303210033 | 8303210018 | 83/03/11 | 50-289 | P |
| 8303210050 | 8303210012 | 83/03/11 | 50-346 | P |
| 8303210055 | 8303210012 | 83/03/11 | 50-346 | P |
| 8303210078 | 8303210073 | 83/02/14 | 70-820 | |
| 8303210097 | 8303210090 | 83/03/02 | 50-282 | G |
| 8303210108 | 8303210104 | 83/01/25 | ACRS | |
| 8303210116 | 8303210111 | 83/03/14 | 50-266 | P |
| 8303210155 | 8303210153 | 83/03/10 | 50-322 | A |
| 8303210184 | 8303210165 | 83/03/11 | 50-289 | P |
| 8303210188 | 8303210177 | 83/03/07 | 50-317 | P |
| 8303210191 | 8303210165 | 83/03/11 | 50-289 | P |
| 8303210192 | 8303210177 | 83/03/07 | 50-317 | P |
| 8303210244 | 8303210234 | 83/03/15 | 50-313 | P |
| 8303210246 | 8303210242 | 83/03/07 | 50-305 | P |
| 8303210263 | 8303210258 | 83/03/15 | 50-331 | P |
| 8303210274 | 8303210267 | 83/03/14 | 50-329 | A |
| 8303210282 | 8303210267 | 83/03/14 | 50-329 | A |
| 8303210283 | 8303210277 | 83/03/16 | 50-313 | P |
| 8303210286 | 8303210279 | 83/03/15 | 50-155 | I |
| 8303210288 | 8303210267 | 83/03/14 | 50-329 | A |
| 8303210295 | 8303210267 | 83/03/14 | 50-329 | A |
| 8303210301 | 8303210267 | 83/03/14 | 50-329 | A |
| 8303210307 | 8303210267 | 83/03/14 | 50-329 | A |
| 8303210308 | 8303210299 | 83/03/02 | 50-327 | S |
| 8303210312 | 8303210267 | 83/03/14 | 50-329 | A |
| 8303210317 | 8303210315 | 83/03/01 | 50-324 | S |
| 8303210318 | 8303210314 | 83/02/28 | 50-324 | S |
| 8303210320 | 8303210316 | 83/03/10 | 50-366 | S |
| 8303210321 | 8303210319 | 83/03/02 | 50-328 | S |
| 8303210326 | 8303210324 | 83/02/28 | 50-325 | S |
| 8303210327 | 8303210322 | 83/03/08 | 50-328 | S |
| 8303210333 | 8303210332 | 83/03/16 | 50-387 | I |
| 8303210335 | 8303210331 | 83/02/23 | 50-400 | G |
| 8303210341 | 8303210338 | 83/02/24 | 50-417 | G |
| 8303210346 | 8303210342 | 83/03/01 | 50-280 | G |
| 8303210347 | 8303210344 | 83/02/23 | 50-370 | G |
| 8303210353 | 8303210349 | 83/03/07 | 50-390 | G |
| 8303210354 | 8303210350 | 83/03/10 | 50-321 | S |
| 8303210359 | 8303210356 | 83/03/10 | 50-373 | S |
| 8303210362 | 8303210358 | 83/03/11 | 50-346 | S |
| 8303210363 | 8303210360 | 83/02/25 | 70-1113 | |
| 8303210369 | 8303210364 | 83/02/23 | 70-1151 | |
| 8303210370 | 8303210370 | 83/02/17 | 50-369 | G |
| 8303210374 | 8303210368 | 83/02/25 | 50-324 | S |
| 8303210379 | 8303210376 | 83/03/11 | 50-261 | G |
| 8303210381 | 8303210376 | 83/03/11 | 50-261 | G |
| 8303210383 | 8303210376 | 83/03/11 | 50-261 | G |
| 8303210384 | 8303210377 | 83/03/02 | 50-348 | S |
| 8303210386 | 8303210376 | 83/03/11 | 50-261 | G |
| 8303210391 | 8303210389 | 83/02/17 | 50-416 | G |
| 8303210393 | 8303210388 | 83/02/24 | 50-321 | S |
| 8303210398 | 8303210392 | 83/02/11 | 50-390 | G |
| 8303210402 | 8303210397 | 83/02/28 | 50-335 | S |
| 8303210405 | 8303210395 | 83/03/14 | QA999 | |
| 8303210409 | 8303210403 | 83/02/14 | 50-324 | G |
| 8303210411 | 8303210404 | 83/03/14 | QA999 | |
| 8303210413 | 8303210406 | 83/03/08 | 50-366 | S |
| 8303210418 | 8303210410 | 83/03/10 | 50-317 | S |
| 8303210419 | 8303210412 | 83/03/10 | 50-366 | S |
| 8303210422 | 8303210414 | 83/02/25 | 50-327 | G |
| 8303210424 | 8303210416 | 83/03/10 | 50-316 | S |
| 8303210429 | 8303210425 | 83/02/16 | 50-395 | G |
| 8303210434 | 8303210423 | 83/03/15 | 50-259 | S |
| 8303210436 | 8303210426 | 83/03/01 | 50-348 | G |
| 8303210438 | 8303210432 | 83/03/15 | 50-331 | P |
| 8303210441 | 8303210431 | 83/03/07 | 50-373 | S |
| 8303210445 | 8303210428 | 83/02/28 | 50-325 | S |
| 8303210451 | 8303210443 | 83/03/01 | 50-424 | G |
| 8303210453 | 8303210444 | 83/02/25 | 50-335 | G |
| 8303210454 | 8303210446 | 83/02/11 | 50-400 | G |
| 8303210459 | 8303210442 | 83/02/16 | 50-389 | G |
| 8303210464 | 8303210458 | 83/03/11 | 50-321 | G |
| 8303210465 | 8303210456 | 83/02/28 | 50-339 | S |
| 8303210467 | 8303210463 | 83/03/10 | 50-321 | S |
| 8303210468 | 8303210460 | 83/03/11 | 50-364 | S |

ACCESSION NUMBER

| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
|---|---|---|---|---|
| 8303210469 | 8303210462 | 83/03/02 | 50-327 | S |
| 8303210472 | 8303210458 | 83/03/11 | 50-321 | G |
| 8303210475 | 8303210458 | 83/03/11 | 50-321 | G |
| 8303210485 | 8303210476 | 83/03/10 | 50-321 | S |
| 8303210487 | 8303210458 | 83/03/11 | 50-321 | G |
| 8303210490 | 8303210477 | 83/02/25 | 50-325 | S |
| 8303210491 | 8303210483 | 83/02/11 | 50-395 | G |
| 8303210492 | 8303210482 | 83/03/14 | QA999 | |
| 8303210497 | 8303210481 | 83/02/14 | 50-424 | G |
| 8303210498 | 8303210489 | 83/02/28 | 50-339 | S |
| 8303210501 | 8303210494 | 83/02/25 | 50-83 | G |
| 8303210503 | 8303210496 | 83/02/11 | 50-370 | G |
| 8303210512 | 8303210506 | 82/09/02 | 50-369 | G |
| 8303210519 | 8303210506 | 82/09/02 | 50-389 | G |
| 8303210520 | 8303210513 | 83/02/23 | 50-482 | G |
| 8303210521 | 8303210511 | 83/03/03 | 50-395 | G |
| 8303210524 | 8303210514 | 83/03/17 | QA999 | |
| 8303210527 | 8303210517 | 83/03/10 | 50-366 | S |
| 8303210528 | 8303210506 | 82/09/02 | 50-389 | G |
| 8303210529 | 8303210513 | 83/02/23 | 50-482 | G |
| 8303210530 | 8303210522 | 83/03/10 | 50-272 | S |
| 8303210531 | 8303210511 | 83/03/03 | 50-395 | G |
| 8303210532 | 8303210502 | 83/03/09 | 50-348 | G |
| 8303210535 | 8303210511 | 83/03/03 | 50-395 | G |
| 8303210539 | 8303210502 | 83/03/09 | 50-348 | G |
| 8303210541 | 8303210511 | 83/03/03 | 50-395 | G |
| 8303210544 | 8303210534 | 83/02/28 | 70-27 | |
| 8303210545 | 8303210537 | 83/03/01 | 50-416 | S |
| 8303210548 | 8303210502 | 83/03/09 | 50-348 | G |
| 8303210554 | 8303210547 | 83/02/17 | 50-313 | G |
| 8303210557 | 8303210550 | 83/02/28 | 50-250 | S |
| 8303210559 | 8303210546 | 83/03/09 | 50-267 | S |
| 8303210562 | 8303210547 | 83/02/17 | 50-313 | G |
| 8303210563 | 8303210558 | 83/03/10 | 50-321 | S |
| 8303210571 | 8303210565 | 82/12/20 | 50-482 | G |
| 8303210577 | 8303210570 | 83/03/11 | 50-318 | S |
| 8303210579 | 8303210564 | 83/03/03 | 50-416 | G |
| 8303210580 | 8303210576 | 83/03/09 | 70-143 | |
| 8303210583 | 8303210575 | 83/02/23 | 70-143 | |
| 8303210585 | 8303210572 | 83/02/14 | 50-390 | G |
| 8303210587 | 8303210564 | 83/03/03 | 50-416 | G |
| 8303210588 | 8303210582 | 83/02/23 | 50-250 | G |
| 8303210589 | 8303210573 | 83/02/16 | 50-424 | G |
| 8303210591 | 8303210584 | 83/02/24 | 50-348 | G |
| 8303210592 | 8303210564 | 83/03/03 | 50-416 | G |
| 8303210597 | 8303210564 | 83/03/03 | 50-416 | G |
| 8303210600 | 8303210594 | 83/03/14 | 70-1113 | |
| 8303210602 | 8303210590 | 83/03/14 | 50-261 | G |
| 8303210609 | 8303210601 | 83/03/17 | QA999 | |
| 8303210610 | 8303210604 | 83/03/16 | 50-382 | G |
| 8303210612 | 8303210599 | 83/02/28 | 50-302 | G |
| 8303210614 | 8303210608 | 83/03/02 | 50-341 | G |
| 8303210619 | 8303210606 | 83/02/25 | 70-143 | |
| 8303210621 | 8303210613 | 83/03/10 | 50-317 | S |
| 8303210625 | 8303210606 | 83/02/25 | 70-143 | |
| 8303210628 | 8303210623 | 83/03/03 | 50-315 | G |
| 8303210631 | 8303210624 | 83/03/02 | 50-302 | G |
| 8303210633 | 8303210627 | 83/03/11 | 50-272 | S |
| 8303210635 | 8303210629 | 83/03/09 | 50-267 | S |
| 8303210637 | 8303210623 | 83/03/03 | 50-315 | G |
| 8303210639 | 8303210632 | 83/03/02 | 50-321 | G |
| 8303210643 | 8303210606 | 83/02/25 | 70-143 | |
| 8303210646 | 8303210638 | 83/02/16 | 50-369 | G |
| 8303210648 | 8303210632 | 83/03/02 | 50-321 | G |
| 8303210649 | 8303210620 | 83/03/09 | 50-416 | G |
| 8303210651 | 8303210641 | 83/02/28 | 50-267 | R |
| 8303210652 | 8303210642 | 83/03/17 | 50-361 | P |
| 8303210654 | 8303210632 | 83/03/02 | 50-321 | G |
| 8303210657 | 8303210642 | 83/03/17 | 50-361 | P |
| 8303210660 | 8303210653 | 83/03/01 | 50-424 | G |
| 8303210661 | 8303210650 | 83/03/04 | 50-382 | G |
| 8303210662 | 8303210632 | 83/03/02 | 50-321 | G |
| 8303210666 | 8303210656 | 83/03/17 | QA999 | |
| 8303210667 | 8303210642 | 83/03/17 | 50-361 | P |
| 8303210668 | 8303210655 | 83/02/24 | 50-321 | G |
| 8303210670 | 8303210653 | 83/03/01 | 50-424 | G |
| 8303210671 | 8303210663 | 82/09/24 | 50-302 | G |
| 8303210672 | 8303210656 | 83/03/17 | QA999 | |
| 8303210674 | 8303210653 | 83/03/01 | 50-424 | G |
| 8303210675 | 8303210663 | 82/09/24 | 50-302 | G |

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

| ACCESSION NUMBER ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
|---|---|---|---|---|
| 8303310214 | 8303310074 | 83/01/13 | FOIA | |
| 8303310220 | 8303310074 | 83/01/13 | FOIA | |
| 8303310223 | 8303310074 | 83/01/13 | FOIA | |
| 8303310227 | 8303310074 | 83/01/13 | FOIA | |
| 8303310230 | 8303310211 | 83/03/28 | 50-237 | Q |
| 8303310232 | 8303310074 | 83/01/13 | FOIA | |
| 8303310236 | 8303310074 | 83/01/13 | FOIA | |
| 8303310240 | 8303310074 | 83/01/13 | FOIA | |
| 8303310242 | 8303310238 | 83/02/28 | 50-33 | V |
| 8303310245 | 8303310243 | 83/03/18 | 50-184 | R |
| 8303310248 | 8303310246 | 83/03/25 | 50-334 | P |
| 8303310249 | 8303310074 | 83/01/13 | FOIA | |
| 8303310253 | 8303310074 | 83/01/13 | FOIA | |
| 8303310256 | 8303310251 | 83/03/30 | 50-445 | T |
| 8303310257 | 8303310074 | 83/01/13 | FOIA | |
| 8303310260 | 8303310074 | 83/01/13 | FOIA | |
| 8303310262 | 8303310251 | 83/03/30 | 50-445 | T |
| 8303310265 | 8303310074 | 83/01/13 | FOIA | |
| 8303310266 | 8303310251 | 83/03/30 | 50-445 | T |
| 8303310268 | 8303310074 | 83/01/13 | FOIA | |
| 8303310275 | 8303310074 | 83/01/13 | FOIA | |
| 8303310278 | 8303310269 | 83/03/29 | 50-322 | Q |
| 8303310280 | 8303310074 | 83/01/13 | FOIA | |
| 8303310285 | 8303310074 | 83/01/13 | FOIA | |
| 8303310287 | 8303310281 | 83/03/22 | 50-282 | P |
| 8303310291 | 8303310074 | 83/01/13 | FOIA | |
| 8303310296 | 8303310283 | 83/03/24 | 40-8698 | |
| 8303310298 | 8303310074 | 83/01/13 | FOIA | |
| 8303310304 | 8303310074 | 83/01/13 | FOIA | |
| 8303310309 | 8303310074 | 83/01/13 | FOIA | |
| 8303310314 | 8303310074 | 83/01/13 | FOIA | |
| 8303310319 | 8303310074 | 83/01/13 | FOIA | |
| 8303310324 | 8303310074 | 83/01/13 | FOIA | |
| 8303310328 | 8303310074 | 83/01/13 | FOIA | |
| 8303310331 | 8303310074 | 83/01/13 | FOIA | |
| 8303310336 | 8303310330 | 83/03/10 | CONTRACT | |
| 8303310338 | 8303310074 | 83/01/13 | FOIA | |
| 8303310342 | 8303310074 | 83/01/13 | FOIA | |
| 8303310347 | 8303310074 | 83/01/13 | FOIA | |
| 8303310348 | 8303310343 | 83/03/11 | CONTRACT | |
| 8303310352 | 8303310349 | 83/02/25 | CONTRACT | |
| 8303310367 | 8303310363 | 83/03/16 | CONTRACT | |
| 8303310374 | 8303310370 | 83/03/16 | CONTRACT | |
| 8303310379 | 8303310375 | 83/03/22 | 40-2061 | |
| 8303310381 | 8303310380 | 83/03/22 | 70-135 | |
| 8303310400 | 8303310396 | 83/03/29 | 50-111 | W |
| 8303310424 | 8303310420 | 83/03/25 | 50-259 | P |
| 8303310463 | 8303310453 | 83/02/24 | FOIA | |
| 8303310465 | 8303310453 | 83/02/24 | 50-416 | P |
| 8303310470 | 8303310453 | 83/02/24 | 50-416 | P |
| 8303310471 | 8303310467 | 83/03/29 | 50-335 | F |
| 8303310474 | 8303310467 | 83/03/29 | 50-335 | F |
| 8303310476 | 8303310453 | 83/02/24 | 50-416 | P |
| 8303310481 | 8303310453 | 83/02/24 | 50-461 | A |
| 8303310483 | 8303310478 | 83/03/29 | 50-309 | F |
| 8303310487 | 8303310478 | 83/03/29 | 50-309 | F |
| 8303310489 | 8303310453 | 83/02/24 | 50-440 | A |
| 8303310497 | 8303310492 | 83/03/29 | 50-334 | F |
| 8303310502 | 8303310492 | 83/03/29 | 50-334 | F |
| 8303310515 | 8303310492 | 83/03/29 | 50-334 | F |
| 8303310576 | 8303310572 | 82/09/23 | CONTRACT | |
| 8303310592 | 8303310588 | 83/03/25 | XPORTLIC | |
| 8303310594 | 8303310584 | 83/03/21 | CONTRACT | |
| 8303310602 | 8303310598 | 83/03/24 | CONTRACT | |
| 8303310628 | 8303310621 | 83/03/21 | CONTRACT | |
| 8303310646 | 8303310642 | 83/03/23 | CONTRACT | |

| ACCESSION NUMBER ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
|---|---|---|---|---|
| 8303210676 | 8303210669 | 83/02/28 | 50-482 | Q |
| 8303210677 | 8303210656 | 83/03/17 | GA999 | |
| 8303210680 | 8303210642 | 83/03/17 | 50-361 | P |
| 8303210682 | 8303240663 | 82/09/24 | 50-302 | Q |
| 8303210683 | 8303210673 | 83/02/16 | 50-285 | Q |
| 8303210684 | 8303210653 | 83/03/01 | 50-424 | Q |
| 8303210688 | 8303210642 | 83/03/17 | 50-361 | P |
| 8303210690 | 8303210681 | 83/03/14 | GA999 | |
| 8303210693 | 8303210678 | 83/02/23 | 50-280 | Q |
| 8303210695 | 8303210686 | 83/02/28 | 50-416 | Q |
| 8303210696 | 8303210642 | 83/03/17 | 50-361 | P |
| 8303210698 | 8303210689 | 83/03/03 | 50-400 | Q |
| 8303210701 | 8303210692 | 83/03/14 | 50-387 | S |
| 8303210703 | 8303210691 | 83/03/11 | 50-416 | Q |
| 8303210704 | 8303210642 | 83/03/17 | 50-361 | P |
| 8303210705 | 8303210689 | 83/03/03 | 50-400 | Q |
| 8303210706 | 8303210697 | 83/03/01 | 50-389 | Q |
| 8303210711 | 8303210689 | 83/03/03 | 50-400 | Q |
| 8303210712 | 8303210697 | 83/03/01 | 50-389 | Q |
| 8303210713 | 8303210709 | 83/03/14 | 50-387 | S |
| 8303210714 | 8303210697 | 83/03/01 | 50-389 | Q |
| 8303210715 | 8303210702 | 83/03/10 | 50-318 | S |
| 8303210716 | 8303210708 | 83/02/14 | 50-413 | Q |
| 8303210718 | 8303210691 | 83/03/11 | 50-416 | Q |
| 8303210719 | 8303210689 | 83/03/03 | 50-400 | Q |
| 8303210720 | 8303210642 | 83/03/17 | 50-361 | P |
| 8303210721 | 8303210697 | 83/03/01 | 50-389 | Q |
| 8303210725 | 8303210691 | 83/03/11 | 50-416 | Q |
| 8303210726 | 8303210717 | 83/03/01 | 50-395 | Q |
| 8303210727 | 8303210723 | 83/02/22 | 50-348 | Q |
| 8303210730 | 8303210722 | 83/02/17 | 50-338 | Q |
| 8303210733 | 8303210717 | 83/03/01 | 50-395 | Q |
| 8303210736 | 8303210691 | 83/03/11 | 50-416 | Q |
| 8303210738 | 8303210717 | 83/03/01 | 50-395 | Q |
| 8303210739 | 8303210729 | 83/02/11 | 50-400 | Q |
| 8303210741 | 8303210642 | 83/03/17 | 50-361 | P |
| 8303210742 | 8303210691 | 83/03/11 | 50-416 | Q |
| 8303210743 | 8303210735 | 83/02/22 | 50-250 | Q |
| 8303210745 | 8303210717 | 83/03/01 | 50-395 | Q |
| 8303210747 | 8303210691 | 83/03/11 | 50-416 | Q |
| 8303210749 | 8303210642 | 83/03/17 | 50-361 | P |
| 8303210751 | 8303210746 | 83/03/11 | 50-387 | S |
| 8303210752 | 8303210691 | 83/03/11 | 50-416 | Q |
| 8303210754 | 8303210642 | 83/03/17 | 50-361 | P |
| 8303210758 | 8303210642 | 83/03/17 | 50-361 | P |
| 8303210760 | 8303210642 | 83/03/17 | 50-361 | P |
| 8303210762 | 8303210642 | 83/03/17 | 50-361 | P |
| 8303210765 | 8303210756 | 83/03/02 | 50-259 | Q |
| 8303210767 | 8303210642 | 83/03/17 | 50-361 | P |
| 8303210771 | 8303210756 | 83/03/02 | 50-259 | Q |
| 8303210772 | 8303210736 | 83/03/02 | 50-259 | Q |
| 8303210773 | 8303210642 | 83/03/17 | 50-361 | P |
| 8303210775 | 8303210756 | 83/03/02 | 50-259 | Q |
| 8303220006 | 8303220001 | 83/03/18 | 50-206 | P |
| 8303220014 | 8303220010 | 83/03/16 | 50-445 | E |
| 8303220026 | 8303220022 | 83/03/16 | 50-317 | R |
| 8303220033 | 8303220030 | 83/03/15 | 50-289 | R |
| 8303220045 | 8303220035 | 83/03/08 | 50-483 | Q |
| 8303220050 | 8303220035 | 83/03/08 | 50-483 | Q |
| 8303220054 | 8303220046 | 83/03/15 | 50-321 | S |
| 8303220062 | 8303220061 | 83/03/15 | 50-331 | R |
| 8303220065 | 8303220059 | 83/03/17 | 50-255 | Q |
| 8303220082 | 8303220076 | 83/03/17 | 50-329 | A |
| 8303220090 | 8303220083 | 83/03/14 | 50-187 | R |
| 8303220097 | 8303220086 | 83/03/16 | 50-260 | S |
| 8303220109 | 8303220107 | 83/03/16 | 50-373 | S |
| 8303220113 | 8303220092 | 83/03/14 | 50-244 | P |
| 8303220116 | 8303220112 | 83/02/16 | 50-237 | Q |
| 8303220128 | 8303220105 | 83/03/08 | 50-445 | K |
| 8303220136 | 8303220134 | 83/03/14 | 50-358 | R |
| 8303220143 | 8303220099 | 83/03/14 | 50-255 | P |
| 8303220148 | 8303220139 | 83/03/17 | 50-443 | Q |
| 8303220154 | 8303220153 | 83/03/18 | 50-333 | P |
| 8303220160 | 8303220158 | 83/03/18 | 50-302 | P |
| 8303220166 | 8303220165 | 83/03/11 | 50-373 | P |
| 8303220175 | 8303220167 | 83/03/15 | 50-124 | P |
| 8303220178 | 8303220167 | 83/03/15 | 50-124 | P |
| 8303220179 | 8303220176 | 83/03/16 | 50-259 | S |
| 8303220182 | 8303220167 | 83/03/15 | 50-124 | P |
| 8303220184 | 8303220183 | 83/03/18 | 50-341 | Q |

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS



ACCESSION NUMBER

| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
|---|---|---|---|
| 8303220187 | 8303220167 | 83/03/15 | 50-124 P |
| 8303220189 | 8303220167 | 83/03/15 | 50-124 P |
| 8303220197 | 8303220193 | 83/03/18 | 50-322 G |
| 8303220198 | 8303220195 | 83/03/16 | 50-454 T |
| 8303220200 | 8303220193 | 83/03/18 | 50-322 G |
| 8303220206 | 8303220193 | 83/03/18 | 50-322 G |
| 8303220208 | 8303220203 | 83/03/15 | 50-142 G |
| 8303220209 | 8303220201 | 83/03/14 | 50-213 P |
| 8303220219 | 8303220213 | 83/03/14 | 50-282 S |
| 8303220221 | 8303220212 | 83/03/18 | 50-537 G |
| 8303220229 | 8303220215 | 83/03/03 | 50-329 G |
| 8303220233 | 8303220226 | 83/03/15 | 50-445 G |
| 8303220239 | 8303220232 | 83/03/17 | 50-289 G |
| 8303220244 | 8303220232 | 83/03/17 | 50-289 G |
| 8303220247 | 8303220232 | 83/03/17 | 50-289 G |
| 8303220253 | 8303220240 | 83/03/08 | 50-440 G |
| 8303220255 | 8303220201 | 83/03/14 | 50-213 P |
| 8303220275 | 8303220266 | 83/03/14 | 50-416 S |
| 8303220283 | 8303220276 | 83/03/18 | 50-387 P |
| 8303220293 | 8303220277 | 83/03/16 | 50-454 G |
| 8303220297 | 8303220291 | 83/03/15 | 50-247 R |
| 8303220298 | 8303220099 | 83/03/14 | 50-255 P |
| 8303220303 | 8303220296 | 83/03/16 | 50-327 P |
| 8303220322 | 8303220316 | 83/03/17 | 50-317 R |
| 8303220324 | 8303220318 | 83/03/16 | 50-260 S |
| 8303220325 | 8303220203 | 83/03/15 | 50-142 G |
| 8303220328 | 8303220316 | 83/03/17 | 50-317 R |
| 8303220334 | 8303220316 | 83/03/17 | 50-317 R |
| 8303220339 | 8303220316 | 83/03/17 | 50-317 R |
| 8303220346 | 8303220316 | 83/03/17 | 50-317 R |
| 8303220352 | 8303220348 | 83/03/14 | 50-416 S |
| 8303220367 | 8303220362 | 83/03/14 | 50-237 P |
| 8303220376 | 8303220363 | 83/03/14 | 50-155 P |
| 8303220377 | 8303220375 | 83/03/03 | 40-2061 |
| 8303220381 | 8303220379 | 83/03/16 | 50-346 F |
| 8303220385 | 8303220379 | 83/03/16 | 50-346 F |
| 8303220405 | 8303220399 | 83/03/28 | 40-2061 |
| 8303220410 | 8303220399 | 83/03/28 | 40-2061 |
| 8303220415 | 8303220399 | 83/03/28 | 40-2061 |
| 8303220418 | 8303220399 | 83/03/28 | 40-2061 |
| 8303220419 | 8303220412 | 83/01/25 | WASTE MGT |
| 8303220420 | 8303220414 | 83/03/11 | NUREG |
| 8303220423 | 8303220399 | 83/03/28 | 40-2061 |
| 8303220425 | 8303220414 | 83/03/11 | NUREG |
| 8303220427 | 8303220399 | 83/03/28 | 40-2061 |
| 8303220433 | 8303220399 | 83/03/28 | 40-2061 |
| 8303220437 | 8303220399 | 83/03/28 | 40-2061 |
| 8303220440 | 8303220435 | 83/03/08 | 40-8698 |
| 8303220442 | 8303220399 | 83/03/28 | 40-2061 |
| 8303220450 | 8303220446 | 83/03/15 | 50-317 F |
| 8303220462 | 8303220456 | 83/03/14 | 50-344 P |
| 8303220463 | 8303220458 | 83/03/11 | 50-321 P |
| 8303220464 | 8303220460 | 83/03/04 | 40-8452 |
| 8303220468 | 8303220458 | 83/03/11 | 50-321 P |
| 8303220470 | 8303220459 | 83/02/21 | 70-2946 |
| 8303220476 | 8303220467 | 83/03/14 | 50-285 P |
| 8303220479 | 8303220475 | 83/02/08 | 40-17 |
| 8303220485 | 8303220484 | 83/02/28 | 70-2926 |
| 8303220491 | 8303220488 | 83/03/14 | 50-309 P |
| 8303230014 | 8303230010 | 83/03/09 | XPORTLIC |
| 8303230022 | 8303230020 | 83/03/15 | 50-416 R |
| 8303230059 | 8303230054 | 83/03/18 | 50-275 R |
| 8303230066 | 8303230061 | 83/03/14 | 50-335 P |
| 8303230072 | 8303230063 | 83/03/11 | 50-358 A |
| 8303230078 | 8303230063 | 83/03/11 | 50-358 A |
| 8303230079 | 8303230071 | 83/03/14 | 50-266 P |
| 8303230082 | 8303230077 | 83/03/04 | XPORTLIC |
| 8303230084 | 8303230063 | 83/03/11 | 50-358 A |
| 8303230103 | 8303230098 | 83/03/14 | 50-336 P |
| 8303230107 | 8303230102 | 83/03/07 | 50-295 F |
| 8303230111 | 8303230102 | 83/03/07 | 50-295 F |
| 8303230119 | 8303230065 | 83/03/17 | 50-322 A |
| 8303230135 | 8303230129 | 83/03/17 | CONTRACT |
| 8303230149 | 8303230143 | 83/03/16 | 50-10 F |
| 8303230155 | 8303230143 | 83/03/16 | 50-10 F |
| 8303230157 | 8303230151 | 83/03/08 | XPORTLIC |
| 8303230158 | 8303230154 | 83/03/07 | CONTRACT |
| 8303230159 | 8303230153 | 83/03/14 | 50-282 P |
| 8303230164 | 8303230160 | 83/03/16 | 50-313 F |
| 8303230167 | 8303230162 | 83/02/10 | CONTRACT |

ACCESSION NUMBER

| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
|---|---|---|---|
| 8303230170 | 8303230160 | 83/03/16 | 50-313 F |
| 8303230175 | 8303230172 | 83/01/03 | CONTRACT |
| 8303230178 | 8303230177 | 83/02/25 | FOIA |
| 8303230179 | 8303230176 | 83/03/17 | 50-247 G |
| 8303230181 | 8303230177 | 83/02/25 | FOIA |
| 8303230182 | 8303230180 | 83/01/03 | CONTRACT |
| 8303230187 | 8303230177 | 83/02/25 | FOIA |
| 8303230190 | 8303230177 | 83/02/25 | FOIA |
| 8303230195 | 8303230185 | 83/03/15 | CONTRACT |
| 8303230199 | 8303230191 | 83/03/22 | 50-443 G |
| 8303230216 | 8303230212 | 83/03/15 | 50-443 G |
| 8303230217 | 8303230215 | 83/03/22 | 50-155 G |
| 8303230222 | 8303230218 | 83/03/15 | 50-20 P |
| 8303230226 | 8303230218 | 83/03/15 | 50-20 P |
| 8303230233 | 8303230230 | 83/03/22 | 50-247 T |
| 8303230234 | 8303230228 | 83/03/18 | 50-445 G |
| 8303230237 | 8303230230 | 83/03/22 | 50-247 T |
| 8303230248 | 8303230243 | 83/03/18 | 50-329 T |
| 8303230250 | 8303230246 | 83/03/17 | 50-155 G |
| 8303230252 | 8303230247 | 83/03/15 | 50-364 P |
| 8303230256 | 8303230251 | 83/03/16 | 50-443 G |
| 8303230263 | 8303230261 | 83/03/10 | 50-443 G |
| 8303230271 | 8303230268 | 83/03/18 | 50-461 I |
| 8303230280 | 8303230268 | 83/03/18 | 50-461 I |
| 8303230287 | 8303230284 | 83/02/28 | ORG |
| 8303230314 | 8303230312 | 83/03/03 | 50-370 P |
| 8303230325 | 8303230312 | 83/03/03 | 50-370 P |
| 8303230366 | 8303230363 | 83/03/11 | XPORTLIC |
| 8303230380 | 8303230376 | 83/03/16 | CONTRACT |
| 8303230391 | 8303230388 | 83/03/04 | 40-8681 |
| 8303230401 | 8303230396 | 83/03/11 | 50-250 P |
| 8303230407 | 8303230396 | 83/03/11 | 50-250 P |
| 8303230409 | 8303230405 | 83/03/10 | 50-302 P |
| 8303230416 | 8303230405 | 83/03/10 | 50-302 P |
| 8303230418 | 8303230415 | 83/03/16 | 50-348 F |
| 8303230420 | 8303230405 | 83/03/10 | 50-302 P |
| 8303230423 | 8303230415 | 83/03/16 | 50-348 F |
| 8303230429 | 8303230421 | 83/03/11 | 50-245 P |
| 8303230430 | 8303230422 | 83/02/24 | 50-247 F |
| 8303230431 | 8303230425 | 83/03/16 | 50-327 P |
| 8303230433 | 8303230425 | 83/03/16 | 50-327 P |
| 8303230435 | 8303230421 | 83/03/11 | 50-245 P |
| 8303230438 | 8303230425 | 83/03/16 | 50-327 P |
| 8303230444 | 8303230443 | 83/03/14 | 50-327 P |
| 8303230445 | 8303230443 | 83/03/14 | 50-327 P |
| 8303230452 | 8303230448 | 83/02/10 | 71-9166 |
| 8303230454 | 8303230443 | 83/03/14 | 50-327 P |
| 8303230457 | 8303230448 | 83/02/10 | 71-9166 |
| 8303240017 | 8303240011 | 83/03/14 | 50-322 G |
| 8303240024 | 8303240022 | 83/03/23 | 50-443 G |
| 8303240033 | 8303240030 | 83/02/25 | 40-299 |
| 8303240038 | 8303240015 | 83/03/11 | 50-336 P |
| 8303240039 | 8303300423 | 83/03/22 | 50-322 G |
| 8303240041 | 8303240015 | 83/03/11 | 50-336 P |
| 8303240042 | 8303240015 | 83/03/11 | 50-336 P |
| 8303240046 | 8303240040 | 83/02/17 | 70-1193 |
| 8303240048 | 8303240045 | 83/03/22 | 50-483 F |
| 8303240050 | 8303240040 | 83/02/17 | 70-1193 |
| 8303240055 | 8303240040 | 83/02/17 | 70-1193 |
| 8303240060 | 8303240040 | 83/02/17 | 70-1193 |
| 8303240063 | 8303240054 | 83/03/15 | REVIEW GRP |
| 8303240069 | 8303240054 | 83/03/15 | REVIEW GRP |
| 8303240071 | 8303240066 | 83/03/16 | 50-322 H |
| 8303240073 | 8303240067 | 83/03/11 | 50-313 P |
| 8303240076 | 8303240054 | 83/03/15 | REVIEW GRP |
| 8303240077 | 8303240066 | 83/03/16 | 50-322 H |
| 8303240078 | 8303240074 | 83/03/21 | 50-254 F |
| 8303240080 | 8303240067 | 83/03/11 | 50-312 P |
| 8303240081 | 8303240054 | 83/03/15 | REVIEW GRP |
| 8303240085 | 8303240074 | 83/03/21 | 50-254 F |
| 8303240087 | 8303240054 | 83/03/15 | REVIEW GRP |
| 8303240088 | 8303240086 | 83/03/08 | 50-266 S |
| 8303240095 | 8303240090 | 83/02/25 | 40-299 |
| 8303240096 | 8303240092 | 83/03/21 | 50-305 F |
| 8303240100 | 8303240093 | 83/03/04 | 71-9105 |
| 8303240102 | 8303240092 | 83/03/21 | 50-305 F |
| 8303240108 | 8303240103 | 82/11/16 | WASTE MGT |
| 8303240110 | 8303240105 | 83/03/11 | 71-9101 |
| 8303240112 | 8303240107 | 83/03/21 | 50-348 F |
| 8303240114 | 8303240111 | 83/03/21 | 50-321 F |

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

| ACCESSION NUMBER | | | | |
|---|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
| 8303240118 | 8303240115 | 83/03/21 | 50-29 | F |
| 8303240119 | 8303240111 | 83/03/21 | 50-321 | F |
| 8303240120 | 8303240113 | 83/03/21 | 50-269 | F |
| 8303240123 | 8303240115 | 83/03/21 | 50-29 | F |
| 8303240127 | 8303240113 | 83/03/21 | 50-269 | F |
| 8303240129 | 8303240122 | 83/02/18 | FOIA | |
| 8303240130 | 8303240126 | 83/03/21 | 50-335 | F |
| 8303240133 | 8303240126 | 83/03/21 | 50-335 | F |
| 8303240136 | 8303240122 | 83/02/18 | FOIA | |
| 8303240139 | 8303240122 | 83/02/18 | FOIA | |
| 8303240148 | 8303240122 | 83/02/18 | FOIA | |
| 8303240155 | 8303240122 | 83/02/18 | FOIA | |
| 8303240166 | 8303240122 | 83/02/18 | FOIA | |
| 8303240172 | 8303240122 | 83/02/18 | FOIA | |
| 8303240176 | 8303240122 | 83/02/18 | FOIA | |
| 8303240181 | 8303240122 | 83/02/18 | FOIA | |
| 8303240190 | 8303240178 | 83/03/18 | 50-315 | Q |
| 8303240196 | 8303240188 | 83/03/18 | 50-382 | A |
| 8303240207 | 8303240122 | 83/02/18 | FOIA | |
| 8303240212 | 8303240198 | 83/03/17 | 50-304 | S |
| 8303240213 | 8303240209 | 83/03/18 | 50-483 | Q |
| 8303240235 | 8303240228 | 83/03/10 | 50-387 | P |
| 8303240238 | 8303240225 | 83/03/16 | 50-305 | S |
| 8303240248 | 8303240242 | 83/03/08 | 50-266 | Q |
| 8303240253 | 8303240122 | 83/02/18 | FOIA | |
| 8303240259 | 8303240242 | 83/03/08 | 50-266 | Q |
| 8303240293 | 8303240287 | 83/03/10 | 50-352 | Q |
| 8303240301 | 8303240287 | 83/03/10 | 50-352 | Q |
| 8303240316 | 8303240296 | 83/03/15 | 50-250 | P |
| 8303240323 | 8303240315 | 83/03/11 | 50-285 | P |
| 8303240333 | 8303240315 | 83/03/11 | 50-285 | P |
| 8303240342 | 8303240336 | 83/03/16 | 50-271 | R |
| 8303240353 | 8303240350 | 83/03/11 | 50-266 | P |
| 8303240358 | 8303240354 | 83/03/09 | 50-368 | S |
| 8303240361 | 8303240350 | 83/03/11 | 50-266 | P |
| 8303240363 | 8303240360 | 83/03/09 | 50-387 | Q |
| 8303240371 | 8303240369 | 83/03/09 | 50-213 | Q |
| 8303240372 | 8303240368 | 83/02/16 | 50-237 | Q |
| 8303240373 | 8303240369 | 83/03/09 | 50-213 | Q |
| 8303240380 | 8303240376 | 83/03/08 | 50-352 | Q |
| 8303240382 | 8303240374 | 83/03/14 | 50-313 | S |
| 8303240384 | 8303240379 | 83/03/16 | 50-155 | F |
| 8303240389 | 8303240387 | 83/03/16 | 50-373 | S |
| 8303240391 | 8303240385 | 83/03/17 | 50-261 | S |
| 8303240396 | 8303240388 | 83/03/17 | 50-237 | S |
| 8303240402 | 8303240401 | 83/03/17 | 50-316 | S |
| 8303240405 | 8303240403 | 83/03/15 | 50-219 | R |
| 8303240408 | 8303240407 | 83/03/01 | 50-213 | R |
| 8303240412 | 8303240410 | 83/03/18 | 50-327 | S |
| 8303240415 | 8303240413 | 83/03/14 | 50-29 | P |
| 8303240423 | 8303240420 | 83/03/14 | 50-416 | S |
| 8303240424 | 8303240421 | 83/03/17 | 50-373 | S |
| 8303240427 | 8303240422 | 83/03/10 | 50-267 | Q |
| 8303240434 | 8303240432 | 83/03/15 | 50-416 | S |
| 8303240435 | 8303240430 | 83/03/18 | 50-443 | Q |
| 8303240436 | 8303240433 | 83/03/17 | 50-263 | S |
| 8303240442 | 8303240438 | 83/03/08 | 50-334 | Q |
| 8303240444 | 8303240439 | 83/03/08 | 50-213 | Q |
| 8303240445 | 8303240430 | 83/03/18 | 50-443 | Q |
| 8303240449 | 8303240439 | 83/03/08 | 50-213 | Q |
| 8303240450 | 8303240443 | 83/03/15 | 50-277 | Q |
| 8303240453 | 8303240448 | 83/03/15 | 50-321 | S |
| 8303240460 | 8303240456 | 83/03/10 | 50-341 | Q |
| 8303240461 | 8303240455 | 83/03/01 | 50-213 | Q |
| 8303240463 | 8303240457 | 83/03/11 | 50-336 | S |
| 8303240467 | 8303240462 | 83/03/15 | 50-322 | |
| 8303240472 | 8303240464 | 83/03/17 | 50-289 | |
| 8303240475 | 8303240471 | 83/03/16 | 50-31 | |
| 8303240477 | 8303240471 | 83/03/16 | 50-35 | |
| 8303240478 | 8303240469 | 83/03/18 | 50-313 | |
| 8303240479 | 8303240470 | 83/03/18 | 50-328 | S |
| 8303240489 | 8303240484 | 83/03/10 | 50-373 | Q |
| 8303240493 | 8303240474 | 83/03/17 | 50-346 | S |
| 8303240498 | 8303240484 | 83/03/10 | 50-373 | Q |
| 8303240505 | 8303240494 | 83/03/17 | 50-324 | S |
| 8303240510 | 8303240504 | 83/03/14 | 50-280 | S |
| 8303240512 | 8303240499 | 83/03/01 | 50-423 | Q |
| 8303240517 | 8303240508 | 83/03/09 | 50-440 | Q |
| 8303240523 | 8303240503 | 83/03/10 | 50-387 | S |
| 8303240527 | 8303240521 | 83/03/10 | 50-272 | Q |

| ACCESSION NUMBER | | | | |
|---|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
| 8303240528 | 8303240518 | 83/03/09 | 50-247 | Q |
| 8303240535 | 8303240521 | 83/03/10 | 50-272 | Q |
| 8303240539 | 8303240530 | 83/03/17 | 50-395 | S |
| 8303240542 | 8303240532 | 83/03/09 | 50-334 | Q |
| 8303240544 | 8303240537 | 83/03/08 | 70-33 | |
| 8303240546 | 8303240538 | 83/03/09 | 50-282 | Q |
| 8303240547 | 8303240541 | 83/03/18 | 50-254 | S |
| 8303240556 | 8303240538 | 83/03/09 | 50-282 | Q |
| 8303240564 | 8303240555 | 83/03/21 | 70-1257 | |
| 8303240567 | 8303240562 | 83/03/11 | 50-354 | Q |
| 8303240568 | 8303240557 | 83/03/09 | 50-333 | Q |
| 8303240573 | 8303240559 | 83/03/10 | 50-280 | S |
| 8303240574 | 8303240565 | 83/03/18 | 50-305 | S |
| 8303240575 | 8303240562 | 83/03/11 | 50-354 | Q |
| 8303240577 | 8303240566 | 83/03/10 | 70-25 | |
| 8303240581 | 8303240572 | 83/03/15 | 50-245 | S |
| 8303240588 | 8303240580 | 83/03/07 | 50-334 | S |
| 8303240589 | 8303240586 | 83/03/08 | 50-346 | Q |
| 8303240591 | 8303240582 | 83/03/10 | 50-289 | Q |
| 8303240592 | 8303240583 | 83/03/17 | 50-395 | S |
| 8303240594 | 8303240586 | 83/03/08 | 50-346 | Q |
| 8303240595 | 8303240585 | 83/03/17 | 50-395 | S |
| 8303240597 | 8303240587 | 83/03/11 | 50-10 | Q |
| 8303240600 | 8303240596 | 83/03/17 | 50-395 | S |
| 8303240604 | 8303240599 | 83/03/16 | 50-369 | S |
| 8303240605 | 8303240578 | 83/03/17 | 50-259 | S |
| 8303240607 | 8303240602 | 83/03/09 | 50-254 | Q |
| 8303240608 | 8303240606 | 83/03/17 | 50-296 | S |
| 8303250004 | 8303250001 | 83/03/21 | 50-313 | F |
| 8303250005 | 8303250001 | 83/03/21 | 50-313 | F |
| 8303250008 | 8303250002 | 83/03/22 | 50-285 | Q |
| 8303250009 | 8303250006 | 83/03/08 | 50-267 | R |
| 8303250011 | 8303250007 | 83/03/17 | 50-298 | S |
| 8303250022 | 8303250019 | 83/03/01 | 50-267 | Q |
| 8303250027 | 8303250021 | 83/03/17 | 50-368 | S |
| 8303250028 | 8303250025 | 83/03/17 | 50-298 | S |
| 8303250034 | 8303250016 | 83/01/13 | 50-438 | Q |
| 8303250035 | 8303250032 | 83/03/15 | 50-333 | S |
| 8303250039 | 8303250023 | 83/02/28 | TOPREP | |
| 8303250043 | 8303250042 | 83/03/21 | 50-321 | F |
| 8303250044 | 8303250023 | 83/02/28 | TOPREP | |
| 8303250045 | 8303250023 | 83/02/28 | TOPREP | |
| 8303250047 | 8303250023 | 83/02/28 | TOPREP | |
| 8303250048 | 8303250042 | 83/03/21 | 50-321 | F |
| 8303250049 | 8303250023 | 83/02/28 | TOPREP | |
| 8303250053 | 8303250051 | 83/03/21 | 50-315 | F |
| 8303250056 | 8303250051 | 83/03/21 | 50-315 | F |
| 8303250057 | 8303250055 | 83/03/15 | 50-286 | R |
| 8303250058 | 8303250052 | 83/03/11 | 50-277 | Q |
| 8303250064 | 8303250061 | 83/03/11 | 50-275 | R |
| 8303250065 | 8303250059 | 83/03/15 | 50-333 | S |
| 8303250070 | 8303250052 | 83/03/11 | 50-277 | Q |
| 8303250074 | 8303250068 | 83/03/15 | 50-293 | S |
| 8303250076 | 8303250067 | 83/03/14 | 50-320 | S |
| 8303250077 | 8303250072 | 83/03/21 | 50-247 | Q |
| 8303250081 | 8303250079 | 83/03/11 | 50-275 | R |
| 8303250094 | 8303250090 | 83/03/15 | 50-219 | S |
| 8303250095 | 8303250091 | 83/03/21 | 50-369 | F |
| 8303250100 | 8303250091 | 83/03/21 | 50-369 | F |
| 8303250103 | 8303250096 | 83/03/21 | 50-389 | A |
| 8303250104 | 8303250098 | 83/03/18 | 50-219 | P |
| 8303250108 | 8303250098 | 83/03/18 | 50-219 | P |
| 8303250109 | 8303250105 | 83/03/21 | 50-346 | F |
| 8303250115 | 8303250112 | 83/03/17 | 50-267 | P |
| 8303250116 | 8303250114 | 83/03/11 | 50-298 | P |
| 8303250119 | 8303250114 | 83/03/11 | 50-298 | P |
| 8303250120 | 8303250112 | 83/03/17 | 50-267 | P |
| 8303250121 | 8303250118 | 83/03/16 | 50-293 | S |
| 8303250123 | 8303250117 | 83/03/15 | 50-387 | S |
| 8303250124 | 8303250105 | 83/03/21 | 50-346 | F |
| 8303250139 | 8303250136 | 83/03/18 | 50-358 | R |
| 8303250143 | 8303250142 | 83/03/23 | 50-261 | P |
| 8303250149 | 8303250145 | 83/03/22 | 50-247 | T |
| 8303250154 | 8303250153 | 83/03/23 | 50-443 | Q |
| 8303250158 | 8303250153 | 83/03/23 | 50-443 | Q |
| 8303250162 | 8303250153 | 83/03/23 | 50-443 | Q |
| 8303250166 | 8303250153 | 83/03/23 | 50-443 | Q |
| 8303250168 | 8303250153 | 83/03/23 | 50-443 | Q |
| 8303250170 | 8303250153 | 83/03/23 | 50-443 | Q |
| 8303250171 | 8303250153 | 83/03/23 | 50-443 | Q |

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS



| ACCESSION NUMBER ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
|---|---|---|---|---|
| 8303280007 | 8303280006 | 83/03/21 | 50-266 | P |
| 8303280013 | 8303280008 | 83/03/18 | CONTRACT | |
| 8303280044 | 8303280039 | 83/03/23 | 50-263 | I |
| 8303280080 | 8303280078 | 83/03/23 | 50-537 | E |
| 8303280088 | 8303280085 | 83/03/16 | 50-277 | P |
| 8303280089 | 8303280085 | 83/03/16 | 50-277 | P |
| 8303280090 | 8303280087 | 83/03/21 | 50-389 | A |
| 8303280095 | 8303280093 | 83/03/11 | 50-298 | P |
| 8303280102 | 8303280098 | 83/03/18 | CONTRACT | |
| 8303280110 | 8303280105 | 83/03/23 | 50-338 | P |
| 8303280115 | 8303280107 | 83/03/14 | 50-293 | P |
| 8303280120 | 8303280118 | 83/03/23 | 50-329 | E |
| 8303280129 | 8303280123 | 83/03/14 | 50-333 | P |
| 8303280138 | 8303280131 | 83/03/22 | 50-269 | G |
| 8303280144 | 8303280131 | 83/03/22 | 50-269 | G |
| 8303280148 | 8303280131 | 83/03/22 | 50-269 | G |
| 8303280151 | 8303280142 | 83/03/18 | 50-306 | S |
| 8303280166 | 8303280161 | 82/08/30 | 50-155 | R |
| 8303280167 | 8303280163 | 83/03/08 | GA999 | |
| 8303280171 | 8303280163 | 83/03/08 | GA999 | |
| 8303280173 | 8303280169 | 83/03/14 | 50-320 | G |
| 8303280184 | 8303280181 | 83/03/14 | 50-289 | G |
| 8303280187 | 8303280154 | 83/03/18 | 50-368 | S |
| 8303280188 | 8303280178 | 83/03/14 | 50-423 | G |
| 8303280191 | 8303280181 | 83/03/14 | 50-289 | G |
| 8303280197 | 8303280192 | 83/03/22 | 50-346 | F |
| 8303280200 | 8303280194 | 83/03/17 | 50-269 | P |
| 8303280204 | 8303280193 | 83/03/23 | 50-413 | A |
| 8303280209 | 8303280205 | 83/02/28 | GA999 | |
| 8303280210 | 8303280203 | 83/03/23 | 50-247 | G |
| 8303280212 | 8303280193 | 83/03/23 | 50-413 | A |
| 8303280213 | 8303280205 | 83/02/28 | GA999 | |
| 8303280214 | 8303280207 | 83/03/14 | 50-245 | G |
| 8303280217 | 8303280208 | 83/03/18 | 50-368 | S |
| 8303280222 | 8303280205 | 83/02/28 | GA999 | |
| 8303280223 | 8303280193 | 83/03/23 | 50-413 | A |
| 8303280231 | 8303280219 | 83/03/14 | 50-387 | G |
| 8303280233 | 8303280225 | 83/02/01 | 50-397 | S |
| 8303280234 | 8303280224 | 83/01/17 | 50-285 | F |
| 8303280241 | 8303280236 | 83/03/14 | 70-143 | |
| 8303280244 | 8303280235 | 83/03/14 | 50-346 | G |
| 8303280246 | 8303280236 | 83/03/14 | 70-143 | |
| 8303280249 | 8303280240 | 83/03/17 | 50-267 | S |
| 8303280251 | 8303280239 | 83/03/24 | 50-309 | S |
| 8303280255 | 8303280248 | 83/03/22 | 70-734 | |
| 8303280257 | 8303280240 | 83/03/17 | 50-267 | S |
| 8303280262 | 8303280247 | 83/03/10 | 50-382 | G |
| 8303280263 | 8303280254 | 83/03/17 | 50-267 | S |
| 8303280266 | 8303280252 | 83/01/25 | 50-313 | F |
| 8303280267 | 8303280258 | 83/03/14 | 50-272 | G |
| 8303280283 | 8303280271 | 83/03/14 | 50-277 | G |
| 8303280284 | 8303280276 | 83/03/14 | 70-143 | |
| 8303280286 | 8303280279 | 83/03/03 | 50-272 | R |
| 8303280291 | 8303280281 | 83/03/22 | 50-321 | G |
| 8303280299 | 8303280293 | 82/08/15 | 50-295 | R |
| 8303280301 | 8303280289 | 83/03/22 | 50-454 | G |
| 8303280303 | 8303280294 | 83/03/14 | 50-354 | G |
| 8303280308 | 8303280305 | 83/03/09 | GA999 | |
| 8303280314 | 8303280305 | 83/03/09 | GA999 | |
| 8303280316 | 8303280310 | 83/03/24 | 50-416 | P |
| 8303280318 | 8303280313 | 83/03/15 | I&E | |
| 8303280320 | 8303280305 | 83/03/09 | GA999 | |
| 8303280321 | 8303280307 | 83/03/23 | 50-254 | G |
| 8303280324 | 8303280322 | 83/03/11 | 50-272 | P |
| 8303280326 | 8303280313 | 83/03/15 | I&E | |
| 8303280327 | 8303280322 | 83/03/11 | 50-272 | P |
| 8303280330 | 8303280313 | 83/03/15 | I&E | |
| 8303280333 | 8303280332 | 83/01/11 | CONTRACT | |
| 8303280335 | 8303280313 | 83/03/15 | I&E | |
| 8303280339 | 8303280337 | 83/01/03 | CONTRACT | |
| 8303280340 | 8303280313 | 83/03/15 | I&E | |
| 8303280343 | 8303280336 | 83/03/14 | 50-346 | P |
| 8303280346 | 8303280341 | 83/01/03 | 50-267 | P |
| 8303280348 | 8303280345 | 83/03/18 | 10CFR | |
| 8303280354 | 8303280351 | 83/01/03 | CONTRACT | |
| 8303290004 | 8303290002 | 83/03/25 | 50-275 | R |
| 8303290007 | 8303290005 | 83/03/14 | 50-250 | P |
| 8303290011 | 8303290009 | 83/03/18 | 50-247 | P |
| 8303290017 | 8303290014 | 83/03/18 | WASTE MGT | |
| 8303290019 | 8303290012 | 83/03/14 | 50-321 | P |

| ACCESSION NUMBER ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
|---|---|---|---|---|
| 8303290026 | 8303290022 | 83/03/02 | 71-9006 | |
| 8303290028 | 8303290013 | 83/03/16 | CONTRACT | |
| 8303290030 | 8303290021 | 83/03/11 | 50-220 | P |
| 8303290034 | 8303290021 | 83/03/11 | 50-220 | P |
| 8303290036 | 8303290027 | 83/03/18 | 50-286 | P |
| 8303290037 | 8303290031 | 83/03/17 | 50-346 | P |
| 8303290039 | 8303290018 | 83/03/16 | CONTRACT | |
| 8303290041 | 8303290031 | 83/03/17 | 50-346 | P |
| 8303290045 | 8303290018 | 83/03/16 | CONTRACT | |
| 8303290054 | 8303290049 | 83/03/14 | 50-368 | P |
| 8303290064 | 8303290058 | 83/03/21 | 50-213 | F |
| 8303290072 | 8303290067 | 83/03/15 | 50-362 | S |
| 8303290085 | 8303290079 | 83/03/23 | XPORTLIC | |
| 8303290087 | 8303290080 | 83/03/15 | 50-280 | P |
| 8303290088 | 8303290078 | 83/03/11 | 50-317 | S |
| 8303290091 | 8303290084 | 83/01/03 | CONTRACT | |
| 8303290103 | 8303290096 | 83/01/03 | CONTRACT | |
| 8303290114 | 8303290100 | 83/03/14 | 50-263 | P |
| 8303290116 | 8303290083 | 83/03/08 | 50-247 | U |
| 8303290117 | 8303290107 | 83/03/18 | 50-250 | P |
| 8303290122 | 8303290107 | 83/03/18 | 50-250 | P |
| 8303290129 | 8303290120 | 83/03/17 | 50-298 | F |
| 8303290132 | 8303290107 | 83/03/18 | 50-250 | P |
| 8303290137 | 8303290120 | 83/03/17 | 50-298 | F |
| 8303290138 | 8303290128 | 83/03/17 | CONTRACT | |
| 8303290149 | 8303290143 | 83/03/18 | 50-322 | H |
| 8303290158 | 8303290153 | 83/03/11 | 50-333 | P |
| 8303290163 | 8303290157 | 83/03/14 | 50-272 | P |
| 8303290164 | 8303290153 | 83/03/11 | 50-333 | P |
| 8303290173 | 8303290169 | 83/03/18 | XPORTLIC | |
| 8303290177 | 8303290171 | 83/03/11 | 50-331 | P |
| 8303290182 | 8303290171 | 83/03/11 | 50-331 | P |
| 8303290185 | 8303290175 | 83/02/16 | CONTRACT | |
| 8303290192 | 8303290187 | 83/01/03 | CONTRACT | |
| 8303290193 | 8303290188 | 83/03/11 | 50-293 | P |
| 8303290196 | 8303290191 | 83/03/10 | CONTRACT | |
| 8303290197 | 8303290194 | 83/02/23 | CONTRACT | |
| 8303290201 | 8303290188 | 83/03/11 | 50-293 | P |
| 8303290212 | 8303290202 | 83/03/18 | 50-362 | S |
| 8303290218 | 8303290211 | 83/03/14 | 50-220 | P |
| 8303290221 | 8303290216 | 83/03/17 | 50-362 | S |
| 8303290226 | 8303290222 | 83/02/25 | 50-368 | P |
| 8303290228 | 8303290204 | 83/03/21 | CONTRACT | |
| 8303290230 | 8303290222 | 83/02/25 | 50-368 | P |
| 8303290233 | 8303290225 | 83/03/17 | 50-362 | S |
| 8303290236 | 8303290222 | 83/02/25 | 50-368 | P |
| 8303290241 | 8303290232 | 83/03/07 | 50-206 | U |
| 8303290243 | 8303290235 | 83/03/21 | 50-245 | F |
| 8303290244 | 8303290222 | 83/02/25 | 50-368 | P |
| 8303290251 | 8303290235 | 83/03/21 | 50-245 | F |
| 8303290255 | 8303290247 | 83/03/14 | 50-361 | G |
| 8303290257 | 8303290250 | 83/03/11 | 50-528 | G |
| 8303290263 | 8303290256 | 83/03/14 | 50-334 | F |
| 8303290264 | 8303290253 | 83/03/08 | CONTRACT | |
| 8303290270 | 8303290256 | 83/03/14 | 50-334 | F |
| 8303290271 | 8303290262 | 83/03/07 | 50-275 | G |
| 8303290279 | 8303290273 | 83/03/10 | 50-206 | G |
| 8303290286 | 8303290277 | 83/03/18 | 50-361 | S |
| 8303290292 | 8303290281 | 83/03/07 | CONTRACT | |
| 8303290295 | 8303290291 | 83/03/08 | 50-312 | G |
| 8303290297 | 8303290284 | 83/03/21 | 50-237 | S |
| 8303290298 | 8303290013 | 83/03/16 | CONTRACT | |
| 8303290304 | 8303290300 | 83/03/15 | 50-317 | P |
| 8303290305 | 8303290303 | 83/03/25 | 50-277 | P |
| 8303290317 | 8303290306 | 83/03/25 | 50-390 | A |
| 8303290319 | 8303290314 | 83/03/15 | 50-334 | G |
| 8303290326 | 8303290321 | 83/03/09 | 50-362 | S |
| 8303290330 | 8303290322 | 83/03/24 | 50-366 | P |
| 8303290331 | 8303290325 | 83/03/15 | 50-184 | G |
| 8303290333 | 8303290327 | 83/03/11 | 50-331 | R |
| 8303290335 | 8303290329 | 83/03/11 | 50-362 | S |
| 8303290336 | 8303290324 | 83/01/03 | CONTRACT | |
| 8303290340 | 8303290337 | 83/03/15 | 50-247 | G |
| 8303290346 | 8303290337 | 83/03/15 | 50-247 | G |
| 8303290349 | 8303290345 | 83/03/25 | 50-133 | I |
| 8303290356 | 8303290351 | 83/03/23 | 50-483 | A |
| 8303290378 | 8303290369 | 83/03/18 | 50-416 | P |
| 8303290381 | 8303290377 | 83/03/15 | 50-77 | G |
| 8303290385 | 8303290369 | 83/03/18 | 50-416 | P |
| 8303290396 | 8303290391 | 83/03/23 | 50-320 | G |

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

| ACCESSION NUMBER | | | |
|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 8303290403 | 8303290389 | 83/03/23 | 50-280 Q |
| 8303290405 | 8303290398 | 83/03/14 | 50-277 P |
| 8303290408 | 8303290402 | 83/03/24 | 50-409 P |
| 8303290413 | 8303290406 | 83/03/16 | CONTRACT |
| 8303290425 | 8303290417 | 83/03/18 | CONTRACT |
| 8303290429 | 8303290418 | 83/03/14 | 50-312 P |
| 8303290433 | 8303290424 | 83/03/25 | 50-250 Q |
| 8303290440 | 8303290424 | 83/03/25 | 50-250 Q |
| 8303290446 | 8303290441 | 83/03/09 | 50-288 Q |
| 8303290449 | 8303290445 | 83/03/24 | 50-443 Q |
| 8303290450 | 8303290424 | 83/03/25 | 50-250 Q |
| 8303290459 | 8303290452 | 83/03/14 | 50-336 P |
| 8303290460 | 8303290456 | 83/03/03 | 50-344 Q |
| 8303290461 | 8303290442 | 83/03/22 | 50-309 Q |
| 8303290462 | 8303290453 | 83/03/04 | 50-206 Q |
| 8303290463 | 8303290456 | 83/03/03 | 50-344 Q |
| 8303290468 | 8303290453 | 83/03/04 | 50-206 Q |
| 8303290478 | 8303290476 | 83/03/08 | 50-293 R |
| 8303290480 | 8303290474 | 83/03/11 | 50-141 Q |
| 8303290485 | 8303290457 | 83/03/23 | 50-338 Q |
| 8303290436 | 8303290484 | 83/03/24 | 50-263 Q |
| 8303290494 | 8303290492 | 83/03/11 | 50-361 S |
| 8303290508 | 8303290503 | 83/03/23 | 50-361 Q |
| 8303290532 | 8303290528 | 83/03/16 | CONTRACT |
| 8303290573 | 8303290530 | 83/03/22 | 50-155 Q |
| 8303290535 | 8303290528 | 83/03/16 | CONTRACT |
| 8303290538 | 8303290534 | 83/03/15 | 50-325 P |
| 8303290540 | 8303290534 | 83/03/15 | 50-325 P |
| 8303290543 | 8303290534 | 83/03/15 | 50-325 P |
| 8303290546 | 8303290544 | 83/03/25 | 50-275 Q |
| 8303290547 | 8303290542 | 83/03/21 | 50-387 F |
| 8303290548 | 8303290542 | 83/03/21 | 50-387 F |
| 8303290558 | 8303290553 | 83/03/11 | 50-324 P |
| 8303290561 | 8303290555 | 83/03/10 | 40-8745 |
| 8303290562 | 8303290553 | 83/03/11 | 50-324 P |
| 8303290566 | 8303290564 | 82/09/21 | WASTE MGT |
| 8303290567 | 8303240184 | 83/03/18 | 50-237 P |
| 8303290570 | 8303290564 | 82/09/21 | WASTE MGT |
| 8303290574 | 8303290568 | 83/01/03 | CONTRACT |
| 8303290575 | 8303290564 | 82/09/21 | WASTE MGT |
| 8303290584 | 8303290579 | 83/03/18 | CONTRACT |
| 8303290588 | 8303290581 | 82/08/26 | WASTE MGT |
| 8303290590 | 8303290582 | 83/03/14 | 50-361 Q |
| 8303290591 | 8303290586 | 83/03/16 | 50-250 P |
| 8303290596 | 8303290589 | 83/03/01 | CONTRACT |
| 8303290600 | 8303290592 | 83/03/25 | 40-8713 |
| 8303290601 | 8303290595 | 81/10/01 | WASTE MGT |
| 8303290606 | 8303290594 | 83/03/17 | TOPREP |
| 8303290607 | 8303290603 | 83/03/16 | 50-293 P |
| 8303290608 | 8303290599 | 83/03/15 | CONTRACT |
| 8303290609 | 8303290602 | 83/03/21 | REVIEW GRP |
| 8303290610 | 8303290604 | 82/08/27 | WASTE MGT |
| 8303290611 | 8303290603 | 83/03/16 | 50-293 P |
| 8303290613 | 8303290594 | 83/03/17 | TOPREP |
| 8303290622 | 8303290605 | 83/03/14 | 50-313 P |
| 8303290624 | 8303290615 | 83/03/23 | 50-320 F |
| 8303290628 | 8303290615 | 83/03/23 | 50-320 F |
| 8303290631 | 8303290594 | 83/03/17 | TOPREP |
| 8303290641 | 8303290634 | 83/03/23 | 50-313 F |
| 8303290647 | 8303290639 | 83/03/11 | 50-280 P |
| 8303290653 | 8303290646 | 83/03/15 | 50-338 P |
| 8303290670 | 8303290639 | 83/03/11 | 50-280 P |
| 8303290685 | 8303290669 | 83/03/23 | 50-313 F |
| 8303290699 | 8303290669 | 83/03/23 | 50-313 F |
| 8303290711 | 8303290708 | 83/03/23 | 50-313 F |
| 8303290716 | 8303290708 | 83/03/23 | 50-313 F |
| 8303290732 | 8303290725 | 83/03/23 | 50-280 F |
| 8303290739 | 8303290725 | 83/03/23 | 50-280 F |
| 8303290742 | 8303290559 | 81/04/21 | WASTE MGT |
| 8303290743 | 8303290725 | 83/03/23 | 50-280 F |
| 8303290751 | 8303290750 | 83/02/21 | PROJ |
| 8303290752 | 8303290749 | 83/03/14 | CONTRACT |
| 8303290758 | 8303290755 | 83/03/09 | CONTRACT |
| 8303290761 | 8303290757 | 83/03/22 | 71-5758 |
| 8303290765 | 8303290759 | 83/02/17 | CONTRACT |
| 8303290769 | 8303290763 | 83/03/07 | CONTRACT |
| 8303290774 | 8303290766 | 83/03/14 | 70-1100 |
| 8303290777 | 8303290766 | 83/03/14 | 70-1100 |
| 8303290779 | 8303290770 | 83/02/22 | CONTRACT |
| 8303290788 | 8303290783 | 83/03/07 | CONTRACT |

| ACCESSION NUMBER | | | |
|---|---|---|---|
| ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY |
| 8303290790 | 8303290785 | 83/02/23 | CONTRACT |
| 8303290796 | 8303290793 | 83/03/07 | CONTRACT |
| 8303290806 | 8303290800 | 83/03/14 | 50-315 P |
| 8303290818 | 8303290794 | 83/03/18 | CONTRACT |
| 8303290825 | 8303290810 | 83/03/15 | 50-546 A |
| 8303290834 | 8303290830 | 81/12/10 | WASTE MGT |
| 8303290839 | 8303290831 | 83/03/23 | 50-302 F |
| 8303290845 | 8303290831 | 83/03/23 | 50-302 F |
| 8303290853 | 8303290840 | 83/03/18 | CONTRACT |
| 8303300007 | 8303300004 | 83/03/18 | 50-346 P |
| 8303300011 | 8303300008 | 83/03/23 | 50-254 F |
| 8303300012 | 8303300005 | 83/03/11 | 50-334 P |
| 8303300015 | 8303300010 | 83/03/21 | 50-269 P |
| 8303300017 | 8303300008 | 83/03/23 | 50-254 F |
| 8303300019 | 8303300005 | 83/03/11 | 50-334 P |
| 8303300020 | 8303300013 | 83/03/21 | 50-313 P |
| 8303300021 | 8303300010 | 83/03/21 | 50-269 P |
| 8303300022 | 8303300014 | 83/03/14 | 50-271 P |
| 8303300023 | 8303300016 | 83/03/28 | 50-322 Q |
| 8303300025 | 8303300018 | 83/03/21 | 50-440 E |
| 8303300029 | 8303300024 | 83/03/23 | 50-331 F |
| 8303300032 | 8303300027 | 83/03/18 | 50-213 P |
| 8303300033 | 8303300024 | 83/03/23 | 50-331 F |
| 8303300034 | 8303300026 | 83/03/14 | 50-254 P |
| 8303300036 | 8303300028 | 83/03/16 | 50-269 P |
| 8303300038 | 8303300027 | 83/03/18 | 50-213 P |
| 8303300040 | 8303300031 | 83/03/14 | 50-261 P |
| 8303300042 | 8303300039 | 83/03/23 | ORG |
| 8303300043 | 8303300037 | 83/03/18 | 50-309 P |
| 8303300049 | 8303300044 | 83/03/23 | 50-313 F |
| 8303300054 | 8303300044 | 83/03/23 | 50-313 F |
| 8303300056 | 8303300050 | 83/03/08 | WASTE MGT |
| 8303300067 | 8303300061 | 83/03/09 | CONTRACT |
| 8303300072 | 8303300047 | 83/03/14 | 50-324 P |
| 8303300079 | 8303300073 | 83/03/09 | CONTRACT |
| 8303300087 | 8303300084 | 83/03/18 | 71-5580 |
| 8303300096 | 8303300081 | 83/03/22 | 71-9001 |
| 8303300100 | 8303300088 | 83/03/15 | 50-537 A |
| 8303300102 | 8303300094 | 83/03/08 | 50-259 P |
| 8303300109 | 8303300106 | 83/03/22 | 71-5757 |
| 8303300117 | 8303300112 | 83/03/11 | 71-9167 |
| 8303300118 | 8303300110 | 83/03/16 | 50-317 P |
| 8303300120 | 8303300107 | 82/09/30 | WASTE MGT |
| 8303300122 | 8303300107 | 82/09/30 | WASTE MGT |
| 8303300129 | 8303180543 | 83/03/11 | 50-387 H |
| 8303300131 | 8303300125 | 83/03/28 | 50-327 P |
| 8303300132 | 8303300127 | 83/03/23 | 50-266 P |
| 8303300133 | 8303300123 | 83/03/25 | 50-263 I |
| 8303300148 | 8303300142 | 83/03/18 | 71-6002 |
| 8303300151 | 8303300144 | 83/03/15 | 50-285 P |
| 8303300160 | 8303300144 | 83/03/15 | 50-285 P |
| 8303300166 | 8303300144 | 83/03/15 | 50-285 P |
| 8303300168 | 8303300158 | 83/03/16 | 50-486 A |
| 8303300171 | 8303300163 | 83/03/14 | 50-331 P |
| 8303300186 | 8303300179 | 83/03/22 | 50-54 P |
| 8303300191 | 8303300180 | 83/03/14 | 50-305 P |
| 8303300192 | 8303300179 | 83/03/22 | 50-54 P |
| 8303300205 | 8303300198 | 83/03/14 | 50-348 P |
| 8303300207 | 8303300196 | 83/03/16 | 50-309 P |
| 8303300209 | 8303300196 | 83/03/16 | 50-309 P |
| 8303300217 | 8303300213 | 83/03/14 | 50-298 P |
| 8303300222 | 8303300215 | 83/03/07 | 40-8585 |
| 8303300227 | 8303300218 | 83/03/17 | 50-322 A |
| 8303300228 | 8303300219 | 83/03/14 | 50-259 P |
| 8303300229 | 8303300221 | 83/03/14 | TOPREP |
| 8303300230 | 8303300224 | 83/03/25 | 50-389 A |
| 8303300232 | 8303300223 | 83/03/25 | 50-206 F |
| 8303300233 | 8303300225 | 83/03/24 | 50-312 R |
| 8303300234 | 8303300219 | 83/03/14 | 50-259 P |
| 8303300237 | 8303300221 | 83/03/14 | TOPREP |
| 8303300239 | 8303300223 | 83/03/25 | 50-206 F |
| 8303300240 | 8303300218 | 83/03/17 | 50-322 A |
| 8303300241 | 8303300219 | 83/03/14 | 50-259 P |
| 8303300243 | 8303300235 | 83/03/10 | 50-309 P |
| 8303300244 | 8303300221 | 83/03/14 | TOPREP |
| 8303300246 | 8303300218 | 83/03/17 | 50-322 A |
| 8303300251 | 8303300218 | 83/03/17 | 50-322 A |
| 8303300252 | 8303300221 | 83/03/14 | TOPREP |
| 8303300254 | 8303300249 | 83/03/28 | 50-335 P |
| 8303300255 | 8303300218 | 83/03/17 | 50-322 A |

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS



| ACCESSION NUMBER ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
|---|---|---|---|---|
| 8303300256 | 8303300253 | 83/03/16 | 50-336 | P |
| 8303300258 | 8303300218 | 83/03/17 | 50-322 | A |
| 8303300260 | 8303300218 | 83/03/17 | 50-322 | A |
| 8303300261 | 8303300253 | 83/03/16 | 50-336 | P |
| 8303300265 | 8303300218 | 83/03/17 | 50-322 | A |
| 8303300266 | 8303300253 | 83/03/16 | 50-336 | P |
| 8303300307 | 8303300303 | 83/03/22 | 50-247 | G |
| 8303300308 | 8303300299 | 83/03/11 | 50-259 | P |
| 8303300310 | 8303300305 | 83/03/24 | 50-333 | G |
| 8303300313 | 8303300303 | 83/03/22 | 50-247 | G |
| 8303300319 | 8303300303 | 83/03/22 | 50-247 | G |
| 8303300321 | 8303300317 | 83/03/16 | 50-247 | G |
| 8303300322 | 8303300303 | 83/03/22 | 50-247 | G |
| 8303300323 | 8303300311 | 83/03/16 | 50-293 | G |
| 8303300325 | 8303300299 | 83/03/11 | 50-259 | P |
| 8303300337 | 8303300104 | 83/03/22 | 71-9086 | |
| 8303300338 | 8303300335 | 83/03/28 | 50-320 | G |
| 8303300339 | 8303300334 | 83/03/21 | 50-400 | G |
| 8303300340 | 8303300332 | 83/03/17 | 50-286 | G |
| 8303300353 | 8303300347 | 83/03/21 | 50-400 | G |
| 8303300354 | 8303300348 | 83/03/23 | 50-395 | P |
| 8303300357 | 8303300348 | 83/03/23 | 50-395 | P |
| 8303300363 | 8303300348 | 83/03/23 | 50-395 | P |
| 8303300388 | 8303300384 | 83/03/15 | 50-344 | P |
| 8303300392 | 8303300383 | 83/03/17 | 50-170 | G |
| 8303300393 | 8303300384 | 83/03/15 | 50-344 | P |
| 8303300403 | 8303300397 | 83/03/17 | 70-820 | |
| 8303300431 | 8303300409 | 83/03/23 | 50-454 | T |
| 8303300444 | 8303300433 | 83/03/17 | 50-247 | G |
| 8303300449 | 8303300439 | 83/03/25 | CONTRACT | |
| 8303300451 | 8303300442 | 83/03/24 | 50-289 | F |
| 8303300455 | 8303300433 | 83/03/17 | 50-247 | G |
| 8303300457 | 8303300453 | 83/03/22 | 50-454 | T |
| 8303300458 | 8303300454 | 83/03/25 | CONTRACT | |
| 8303300473 | 8303300468 | 83/03/24 | 50-272 | G |
| 8303300475 | 8303300462 | 83/03/16 | 50-245 | G |
| 8303300477 | 8303300468 | 83/03/24 | 50-272 | G |
| 8303300485 | 8303300481 | 83/03/22 | CONTRACT | |
| 8303300498 | 8303300493 | 83/03/18 | 50-309 | G |
| 8303300504 | 8303300493 | 83/03/18 | 50-309 | G |
| 8303300509 | 8303300507 | 83/03/22 | 50-321 | P |
| 8303300516 | 8303300507 | 83/03/22 | 50-321 | P |
| 8303300520 | 8303300507 | 83/03/22 | 50-321 | P |
| 8303300536 | 8303300531 | 83/03/21 | 50-312 | P |
| 8303300543 | 8303300531 | 83/03/21 | 50-312 | P |
| 8303300546 | 8303300531 | 83/03/21 | 50-312 | P |
| 8303300547 | 8303300542 | 83/03/11 | TOPREP | |
| 8303300551 | 8303300423 | 83/03/22 | 50-322 | G |
| 8303300561 | 8303300532 | 83/03/28 | 50-10 | F |
| 8303300562 | 8303300423 | 83/03/22 | 50-322 | G |
| 8303300574 | 8303300555 | 83/03/18 | CONTRACT | |
| 8303300576 | 8303300568 | 83/03/16 | CONTRACT | |
| 8303300585 | 8303300297 | 83/03/09 | CONTRACT | |
| 8303300588 | 8303300581 | 83/03/24 | 50-277 | F |
| 8303300589 | 8303300580 | 83/02/24 | PR | |
| 8303300591 | 8303300584 | 83/03/24 | 50-338 | P |
| 8303300594 | 8303300581 | 83/03/24 | 50-277 | F |
| 8303300595 | 8303300580 | 83/02/24 | PR | |
| 8303300604 | 8303300598 | 83/03/16 | CONTRACT | |
| 8303300611 | 8303300580 | 83/02/24 | PR | |
| 8303300616 | 8303300580 | 83/02/24 | PR | |
| 8303300619 | 8303300610 | 83/03/25 | 50-313 | F |
| 8303300621 | 8303300617 | 83/02/28 | FOIA | |
| 8303300624 | 8303300617 | 83/02/28 | FOIA | |
| 8303300629 | 8303300617 | 83/02/28 | FOIA | |
| 8303300633 | 8303300610 | 83/03/25 | 50-313 | F |
| 8303300636 | 8303300617 | 83/02/28 | FOIA | |
| 8303300641 | 8303300617 | 83/02/28 | FOIA | |
| 8303300652 | 8303300647 | 83/02/23 | FOIA | |
| 8303300653 | 8303300648 | 83/03/03 | 50-265 | P |
| 8303300658 | 8303300648 | 83/03/03 | 50-265 | P |
| 8303300660 | 8303300648 | 83/03/03 | 50-265 | P |
| 8303300665 | 8303300661 | 83/03/24 | 50-329 | A |
| 8303300671 | 8303300663 | 83/03/10 | 50-331 | P |
| 8303300677 | 8303300676 | 83/03/16 | CONTRACT | |
| 8303300678 | 8303300674 | 83/03/28 | 50-528 | F |
| 8303300681 | 8303300679 | 83/03/28 | 50-263 | F |
| 8303300683 | 8303300680 | 83/03/16 | CONTRACT | |
| 8303300684 | 8303300674 | 83/03/28 | 50-528 | F |
| 8303300685 | 8303300679 | 83/03/28 | 50-263 | F |

| ACCESSION NUMBER ENCLOSURE | PRINCIPAL DOCUMENT | DATE ISSUED | SUBJECT CATEGORY | |
|---|---|---|---|---|
| 8303300688 | 8303300659 | 83/03/04 | FOIA | |
| 8303300693 | 8303300659 | 83/03/04 | FOIA | |
| 8303300697 | 8303300691 | 83/03/28 | 50-275 | F |
| 8303300698 | 8303300687 | 83/03/09 | CONTRACT | |
| 8303300700 | 8303300663 | 83/03/10 | 50-331 | P |
| 8303300701 | 8303300695 | 83/03/28 | 50-346 | F |
| 8303300702 | 8303300691 | 83/03/28 | 50-275 | F |
| 8303300705 | 8303300663 | 83/03/10 | 50-331 | P |
| 8303300707 | 8303300695 | 83/03/28 | 50-346 | F |
| 8303300717 | 8303300711 | 83/03/16 | 50-289 | P |
| 8303300721 | 8303300711 | 83/03/16 | 50-289 | P |
| 8303300722 | 8303300718 | 83/03/28 | 50-295 | F |
| 8303300727 | 8303300724 | 83/03/18 | 50-322 | A |
| 8303300744 | 8303300738 | 83/03/28 | 50-254 | F |
| 8303300756 | 8303300738 | 83/03/28 | 50-254 | F |
| 8303300774 | 8303300770 | 83/03/25 | 50-317 | F |
| 8303300777 | 8303300770 | 83/03/25 | 50-317 | F |
| 8303300784 | 8303300781 | 83/03/28 | 50-289 | F |
| 8303310002 | 8303310001 | 83/03/25 | 50-346 | F |
| 8303310003 | 8303310001 | 83/03/25 | 50-346 | F |
| 8303310005 | 8303310004 | 83/03/28 | 50-295 | F |
| 8303310007 | 8303310006 | 83/03/28 | 50-346 | F |
| 8303310008 | 8303310006 | 83/03/28 | 50-346 | F |
| 8303310010 | 8303310009 | 83/03/28 | 50-387 | F |
| 8303310011 | 8303310009 | 83/03/28 | 50-387 | F |
| 8303310027 | 8303310023 | 83/03/28 | 50-440 | F |
| 8303310028 | 8303310024 | 83/03/25 | 50-327 | F |
| 8303310036 | 8303310024 | 83/03/25 | 50-327 | F |
| 8303310037 | 8303310023 | 83/03/28 | 50-440 | F |
| 8303310043 | 8303310038 | 82/11/12 | WASTE MGT | |
| 8303310045 | 8303310039 | 83/03/29 | 50-382 | A |
| 8303310048 | 8303310044 | 83/03/25 | 50-244 | F |
| 8303310053 | 8303310039 | 83/03/29 | 50-382 | A |
| 8303310054 | 8303310044 | 83/03/25 | 50-244 | F |
| 8303310056 | 8303310052 | 83/03/22 | CONTRACT | |
| 8303310060 | 8303310057 | 83/03/29 | 50-335 | P |
| 8303310062 | 8303310050 | 83/03/24 | 50-369 | P |
| 8303310067 | 8303310063 | 83/03/07 | 50-537 | A |
| 8303310078 | 8303310074 | 83/01/13 | FOIA | |
| 8303310081 | 8303310074 | 83/01/13 | FOIA | |
| 8303310083 | 8303310074 | 83/0. . | FOIA | |
| 8303310085 | 8303310074 | 83/01/13 | FOIA | |
| 8303310087 | 8303310082 | 83/03/25 | 50-373 | F |
| 8303310088 | 8303310074 | 83/01/13 | FOIA | |
| 8303310091 | 8303310074 | 83/01/13 | FOIA | |
| 8303310092 | 8303310082 | 83/03/25 | 50-373 | F |
| 8303310094 | 8303310074 | 83/01/13 | FOIA | |
| 8303310097 | 8303310074 | 83/01/13 | FOIA | |
| 8303310099 | 8303310074 | 83/01/13 | FOIA | |
| 8303310102 | 8303310074 | 83/01/13 | FOIA | |
| 8303310103 | 8303310072 | 83/03/21 | CONTRACT | |
| 8303310104 | 8303310074 | 83/01/13 | FOIA | |
| 8303310105 | 8303310100 | 83/03/28 | 50-445 | F |
| 8303310111 | 8303310074 | 83/01/13 | FOIA | |
| 8303310112 | 8303310108 | 83/03/21 | CONTRACT | |
| 8303310116 | 8303310074 | 83/01/13 | FOIA | |
| 8303310118 | 8303310113 | 83/03/25 | 50-321 | F |
| 8303310119 | 8303310074 | 83/01/13 | FOIA | |
| 8303310121 | 8303310113 | 83/03/25 | 50-321 | F |
| 8303310128 | 8303310074 | 83/01/13 | FOIA | |
| 8303310130 | 8303310124 | 83/03/25 | 50-10 | F |
| 8303310131 | 8303310074 | 83/01/13 | FOIA | |
| 8303310136 | 8303310132 | 83/03/09 | CONTRACT | |
| 8303310137 | 8303310074 | 83/01/13 | FOIA | |
| 8303310141 | 8303310074 | 83/01/13 | FOIA | |
| 8303310143 | 8303310139 | 83/03/02 | CONTRACT | |
| 8303310144 | 8303310074 | 83/01/13 | FOIA | |
| 8303310146 | 8303310124 | 83/03/25 | 50-10 | F |
| 8303310150 | 8303310074 | 83/01/13 | FOIA | |
| 8303310154 | 8303310074 | 83/01/13 | FOIA | |
| 8303310155 | 8303310151 | 83/03/16 | CONTRACT | |
| 8303310157 | 8303310074 | 83/01/13 | FOIA | |
| 8303310163 | 8303310160 | 83/03/28 | 50-289 | F |
| 8303310165 | 8303310161 | 83/03/22 | 50-390 | A |
| 8303310174 | 8303310167 | 83/03/28 | 50-321 | F |
| 8303310175 | 8303310074 | 83/01/13 | FOIA | |
| 8303310180 | 8303310167 | 83/03/28 | 50-321 | F |
| 8303310200 | 8303310186 | 83/03/09 | CONTRACT | |
| 8303310204 | 8303310074 | 83/01/13 | FOIA | |
| 8303310208 | 8303310074 | 83/01/13 | FOIA | |

## APPENDIX A

# DEFINITIONS OF DOCKET 50 CATEGORIES

### A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

1. Application for construction permit.
2. General Information submitted with construction permit application.
3. Amendments and changes to items 1 and 2.
4. NRC questions, requests for additional information, and applicant responses.
5. Correspondence and documents relating to unresolved design and construction issues.
6. Meeting announcements and summaries of meeting discussions on issues of item 5.
7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
9. Construction Permit, amendments, and correspondence relating to the construction permit.
10. Scheduling of license application submission or review.
11. Environmental review information.
12. Application for operating license.
13. General Information submitted with operating license application.
14. Amendments and changes to items 12 and 13.
15. Correspondence regarding the Final Safety Analysis Report (FSAR).
16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
17. Reports of site visits.
18. Backup technical documents (e.g., topical reports) submitted in support of the application.

### B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
2. Amendments and changes to the PSAR.

3. Transmittal and acknowledgement letters.

4. Certificates of service to the PSAR.

## C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

1. Environmental Report (ER) submitted by the utility.

2. Amendments and supplements to the ER.

3. Transmittal and acknowledgement letters.

4. Information on scheduling of submittal or review of ER.

5. NRC questions, requests for additional information, and applicant responses.

6. Federal register notices citing the availability of items 1 and 2.

7. Correspondence relating to the review of ER.

8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

## D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.

2. Supplements to the DES and FES.

3. Correspondence relating to the DES and FES.

4. Comments from other federal, state and local government agencies.

5. Transmittal and acknowledgement letters.

6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.

7. Backup technical documents submitted in connection with above.

8. Federal register notice citing availability of items 1 and 2.

9. Site visits to obtain information for DES or FES.

10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

## E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).

2. Supplements to SER.

3. Correspondence relating to SER.

4. Federal register notices citing availability of items 1 and 2.

5. Information on scheduling of SER submittals and review.

6. Requests for additional information for use in preparing SER; responses to such requests.

7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.

8. Transmittal and acknowledgement letters.

## F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

1. Fire Hazard Protection Plan and surveys.

2. Plant evacuation correspondence.

3. Safeguards Contingency Plans.

4. Review of Health Physics Program.

5. Correspondence relating to aforementioned plans.

6. Supplements, changes and revisions to plans.

## G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.

2. Federal register notices regarding hearings.

3. Requests to make appearances at hearings.

4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.

5. Transmittal of supporting documents (e.g., SER, FES) to the boards.

6. Correspondence to and from intervenors.

7. Board orders and decisions.

8. Petitions for Commission action.

9. Legal filings and Commission orders and decisions resulting from item 8.

## H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

1. Change of address notifications.
2. Changes in structure of organization.
3. Changes in service lists.
4. NRC requests to applicant for additional copies of documents.
5. Correspondence from the public requesting information about the facility and NRC responses.
6. Correspondence on strictly administrative matters.
7. Letters of support, concern or opposition to the facility.
8. Correspondence regarding the Local Public Document Rooms (LPDRs).
9. Professional qualification statements not pertaining to the hearing process.

## I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

1. Company annual reports.
2. Separately submitted financial information and related correspondence.

## J. INSURANCE AND INDEMNITY INFORMATION

1. Indemnity agreements and amendments.
2. Endorsements insurance policies.
3. Other correspondence regarding indemnity and insurance matters.

## K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
2. Amendments and changes to the FSAR.
3. Federal register notices citing availability of items 1 and 2.
4. Transmittal and acknowledgement letters.
5. Certificates of service to the FSAR.

## L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

1. Limited Work Authorizations (LWA) and amendments.
2. Correspondence pertaining to work performed under LWA s.

## M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
2. Correspondence where the primary topic of discussion is antitrust matters.
3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

## N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

## O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
2. Correspondence from ACRS.
3. Announcement of ACRS meetings.
4. Transmittal and acknowledgement letters.
5. ACRS reports.
6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
7. Minutes at ACRS Subcommittee Meetings.

## P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

1. Operating license, amendments, proposed amendments, changes and related correspondence.
2. Technical specifications and changes.

3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.

4. Federal register notices citing availability of items 1 and 2.

5. Correspondence regarding the Final Safety Analysis Report (FSAR).

6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.

7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.

8. Information on the Standard Review Plan (STP).

9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).

10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).

11. Owner's group meeting announcements and reports.

12. Quality assurance information.

13. Environmental matters (technical).

14. Emergency core cooling system documents.

15. Radioactive waste information.

16. Correspondence regarding expansion of spent fuel storage pool.

17. Start-up test reports.

18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.

19. Reports of site visits.

## Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

1. Inspection reports.

2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.

3. Responses by applicant to IE correspondence.

4. Applicant's determination of proprietary nature of inspection reports.

5. Letters concerning areas of noncompliance.

6. Pre-service and in-service inspections and procedures.

7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN s).

8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

## R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

1. Monthly, semiannual, or annual operating reports (other than financial).
2. Periodic environmental monitoring, effluent testing, or similar reports.
3. Periodic personnel exposure reports.
4. Operational Logbooks:

   Logbooks on Environmental Data
   Logbooks on Radiological Data
   Operations Log on Plant Systems Core
   Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

## S. REPORTABLE OCCURRENCES, PNOs, PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER s) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
2. Potential or possible reportable deficiency reports and related correspondence.
3. Personnel exposure reports.
4. Construction deficiency reports submitted under 10 CFR 50.55e.
5. Preliminary Notification of Occurrence (PNO s) and Preliminary Notification of Safeguards Events (PN s).
6. Environmental Technical Specifications violation reports and Environmental Event reports.
7. Part 21 Reports of defects and noncompliance.
8. Correspondence or other documents relating to items 1-7.

## T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
2. Testimony and statements submitted to ASLB and ASLAB.
3. Commission meeting transcripts.
4. NRC staff briefings to the Commission.
5. Statements and written testimony submitted at Commission meeting or hearings.
6. Transcripts of utility briefs to NRC staff.
7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.
8. Corrections to above items.

## U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
2. Preparatory and backup documents for item 1.
3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

## V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

1. Operator licenses or administrative information bearing on licensing of operators.
2. NRC examination results.
3. Power plant examination summary sheet.

## W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

1. Application for authority to voluntarily surrender license.
2. Application to dismantle the facility and dispose of component parts.
3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
4. Documents relating to disposal of radioactive material and decontamination of the site.
5. Other correspondence relating to above items.
6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

## X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

## Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

This category contains documents with an NMSS license and/or a Docket-72 number. For installations on a reactor site, the associated Docket-50 number will also be identified.

1. License applications, licenses, amendments and proposed amendments to possess power reactor spent fuel and other radioactive materials associated with spent storage in an independent spent fuel storage installation. (Such spent fuel storage installations may be on a reactor site or at a separate site.)
2. All related correspondence and reports to the above.

## APPENDIX B

# DEFINITIONS OF NONDOCKETED CATEGORIES

**10CFR – Commission Meeting Records**

This category contains documentation pertaining to open and closed Commission meetings. It includes:

1. Sunshine Act Federal Register notices.
2. Full, written explanation of closed meetings.
3. Certification of General Counsel on closed meetings.
4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

**ACRS – Advisory Committee on Reactor Safeguards**

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
2. ACRS meeting announcements; description of meeting agendas.
3. ACRS-generated reports, memoranda and correspondence that are publicly available.
4. ACRS consultant reports, comments and related correspondence.
5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

**COMMISSION – NRC Commissioners**

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.

3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

**CONTRACT – NRC Contracts and Modifications**

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).

2. Solicitations (RFP or IFB) issued by the NRC.

3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.

4. Contractual documents and contract modifications, if any.

**DISCLOSURE – Financial Disclosure Information**

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

**FOIA – Freedom of Information Act Requests and Releases**

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year–numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.

2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.

3. Records or portions of records released in response to specific requests made under FOIA.

**GEN TECH IS – Generic Technical Issues**

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

1. Draft reports of action plans to accomplish generic tasks in the regulatory program.

2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.

3. Meeting notifications and minutes.

4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

**I&E – Inspection and Enforcement**

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.

2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.

3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.

4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

**MISC – Public Document Room Miscellaneous**

This category contains documents that do not fall into the scope of the other nondocketed categories.

**NUREG – NUREG Reports and Related Correspondence**

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

1. These reports are normally final work products and are characterized by the following criteria:

   a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.

   b. They present the results of Commission licensing and policy decisions.

   c. They present the results of technical research conducted for the Commission.

2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.

3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

**ORG – Correspondence with Other Organizations**

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.

2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.

3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.

4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

**PR – Proposed Rule**

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.

2. Text of the Proposed Rule (PR).

3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.

4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

**PRM – Petition for Rulemaking**

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.

2. Federal Register cause notices of the filing of the petition.

3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.

4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

**PROJ – Projects–Predocket Licensing**

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

I. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

A. Application/Construction Stage

1. Application submitted by the utility.

2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.

3. Applicant's Quality Assurance Manual.

4. Early site review information.

5. Backup technical documents submitted in support of the application.

6. Early site visits.

B. Utility PSAR and Amendments

1. PSARs submitted by the utility.

2. Amendments and changes to the PSAR.

3. Transmittal letters.

4. Letters acknowledging receipt of the PSAR.

G. Adjudicatory Correspondence

1. Motions, briefs, orders, *et al.* pertaining to pre-hearing conferences, if any.

M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

1. Inspection reports of the applicant's quality assurance program.

2. Notices of deviations.

3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

**PT21 – Noncompliance Reports and Related Correspondence**

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.

2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.

3. NRC inspection reports of defects cited.

4. Correspondence specifying appropriate follow-up actions taken by the Agency.

**QA999 – Quality Assurance Inspections**

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.

2. Notices of deviations.

3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

**REGGD – Regulatory Guides**

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
2. Revised or newly issued Regulatory Guides.
3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

**RES – Research and Technical Assistance Reports**

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

1. Project description documents.
2. Letter reports of accomplishments and data reports; for example,
   a. model documentation reports
   b. code documentation reports
   c. code verification reports
3. Pre-test prediction reports.
4. "Quick look" reports.
5. Informal experimental data reports and post-irradiation examination analyses.
6. Conceptual design descriptions.
7. Letter reports of foreign travel and site visits by contractors.
8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

**REVIEW GRP – NRC Research Review Groups**

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

1. Agendas for quarterly review group meetings.
2. Summary minutes of review group meetings representing views expressed, including dissenting views.
3. Research plans and predicted results of major experiments; presentations by research contractors.
4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
5. Internal memoranda relating to topics under discussion.

**RM – Rulemakings**

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

1. Designations of the presiding officer and any special directions for the conduct of the hearing.
2. Notifications of hearing board meetings.
3. Petitions, motions, testimony and statements submitted by parties to the hearings.
4. Hearing board orders and rulings.
5. Technical reports submitted as evidence in the proceeding.
6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

**SECY – Position Papers Before the Commission**

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

**STATE PROG – State Programs**

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:

   a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.

   b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.

2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.

3. State Legislative Reports.

4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

**TOPREP – Vendor Reports and Related Correspondence**

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.

2. Revisions, modifications and amendments to topical reports.

3. Correspondence between NRC and vendors pertaining to the review of submittals.

4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

**WASTE MGT – Nuclear Waste Management**

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.

2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.

4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

**XPORTLIC – Export and Import Licenses**

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.

2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.

3. Commission letters requesting Executive Branch views.

4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.

5. Correspondence from foreign governments, international organizations, and members of the public.

6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.

7. Filings pursuant to hearing requests or intervention petitions, if any.

8. Hearing records and decisions.

9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.

10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

NRC FORM 335 (11-81)

U.S. NUCLEAR REGULATORY COMMISSION

**BIBLIOGRAPHIC DATA SHEET**

1. REPORT NUMBER *(Assigned by DDC)*
NUREG-0540
Vol. 5, No. 3

4. TITLE AND SUBTITLE *(Add Volume No., if appropriate)*
Title List of Documents Made Publicly Available
March 1-31, 1983

2. *(Leave blank)*

3. RECIPIENT'S ACCESSION NO.

7. AUTHOR(S)

5. DATE REPORT COMPLETED
MONTH | YEAR

9. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS *(Include Zip Code)*
Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, DC 20555

DATE REPORT ISSUED
MONTH: June | YEAR: 1983

6. *(Leave blank)*

8. *(Leave blank)*

12. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS *(Include Zip Code)*
Same as 9, above.

10. PROJECT/TASK/WORK UNIT NO.

11. FIN NO.

13. TYPE OF REPORT
Monthly

PERIOD COVERED *(Inclusive dates)*
March 1-31, 1983

15. SUPPLEMENTARY NOTES

14. *(Leave blank)*

16. ABSTRACT *(200 words or less)*

This document is a monthly publication containing descriptions of information received and generated by the U.S. NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials, and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The following indexes are included: Personal Author Index, Corporate Source Index, Report Number Index, and Cross Reference to Principal Documents Index.

17. KEY WORDS AND DOCUMENT ANALYSIS

17a. DESCRIPTORS

17b. IDENTIFIERS/OPEN-ENDED TERMS

18. AVAILABILITY STATEMENT
Unlimited

19. SECURITY CLASS *(This report)*
Unclassified

21. NO. OF PAGES

20. SECURITY CLASS *(This page)*
Unclassified

22. PRICE
S



* U.S. GOVERNMENT PRINTING OFFICE: 1983-381-297:3216

UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D.C. 20555

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE, $300

FOURTH CLASS MAIL
POSTAGE & FEES PAID
USNRC
WASH. D.C.
PERMIT No. G-67

120555078877 1 1AN1A5
US NRC
ADM-DIV OF TIDC
POLICY & PUB MGT BR-PDR NUREG
W-501
WASHINGTON DC 20555