UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

(76)

January 31, 1984

Lynne Bernabei, Esq.
Government Accountability Project
1901 Q Street, N.W.
Washington, D.C. 20009

In the Matter of
ARIZONA PUBLIC SERVICE COMPANY, ET AL.
(Palo Verde Nuclear Generating Station, Units 2 and 3)
Docket Nos. STN 50-529 and STN 50-530

Dear Ms. Bernabei:

In accordance with Staff's agreement to keep you informed regarding the Palo Verde coolant pump inquiry and other related problems caused during the hot functional testing of Unit 1, enclosed are non-proprietary copies of reports, prepared by Combustion Engineering, recently obtained by Staff from Applicant, entitled "Safety Injection Nozzle Thermal Liner" and the "Resistance Temperature Detector Thermowell." Also enclosed is a January 6, 1984 inspection report by Region V dealing (at pp. 2-3) with NSSS piping thermal sleeve and thermawell modifications.

Sincerely,

Lee

Lee Scott Dewey
Counsel for NRC Staff

Enclosure:
As Stated

8405250314 840423
PDR FOIA
BERNABE84-212 PDR