APPENDIX A

NOTICE OF VIOLATION

Arizona Public Service Company
P. O. Box 21666
Phoenix, Arizona 85036

Docket Nos. 50-528, 50-529
Construction Permit Nos.
CPPR-141, CPPR-142

As a result of the inspection conducted during April 2 - May 31, 1984, and in accordance with NRC Enforcement Policy, 10 CFR Part 2, Appendix C, the following violation was identified:

> Appendix B of 10 CFR 50, Criterion II states, in part, that "The quality assurance program shall provide control over activities affecting the quality of the identified structures, systems and components, to an extent consistent with their importance to safety."
>
> Contrary to the above, on April 30, 1984, wall mounted instruments (2-J-HDA-TSL-17 and 2-J-HDN-TSHL-25) in Units 1 and 2 Diesel Generator Buildings were observed to have their sensing components interchanged and did not have required mounting washers installed. The instrument installations had been inspected and accepted by the responsible subcontractor on May 27, 1983, but were subsequently modified by others without appropriate controls for those activities. It is believed that this occurred as a result of instrument calibration on July 20, 1983.
>
> This is a Severity Level IV Violation (Supplement II).

Pursuant to the provisions of 10 CFR 2.201, Arizona Public Service Company is hereby required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further items of noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

AUG 7 1984
Dated

PPNarbut for
Tolbert Young, Jr., Chief
Reactor Projects Section 2

8408300100 840807
PDR ADOCK 05000528
Q PDR