NIAGARA MOHAWK

NIAGARA MOHAWK POWER CORPORATION/300 ERIE BOULEVARD WEST, SYRACUSE, N.Y. 13202/TELEPHONE (315) 474-1511

November 16, 1984
(NMP2L 0243)

Mr. R. W. Starostecki, Director
U. S. Nuclear Regulatory Commission
Region I
Division of Project and Resident Programs
631 Park Avenue
King of Prussia, PA 19406

Re: Nine Mile Point - Unit 2
Docket No. 50-410

Dear Mr. Starostecki:

Enclosed is an interim report, in accordance with 10CFR50.55(e), for the problem concerning the Category I cable terminations, involving heat shrinks or tapes, that were not witnessed by Field Quality Control. This problem was reported via tel-con to W. Lazarus of your staff on October 17, 1984.

Very truly yours,

C. V. Mangan
Vice President
Nuclear Engineering and Licensing

CVM/GG/dd

Enclosure

xc: Director of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, DC 20555

R. A. Gramm, NRC Resident Inspector

Project File (2)

8412060270 841116
PDR ADOCK 05000410
S PDR

1/1

IE 27

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
DOCKET NO. 50-410

Interim Report for a Problem
Concerning Cable Terminations Involving Heat Shrinks or Tape
(55(e)-84-45)

Description of the Problem

The problem concerns the Category I cable terminations, involving heat shrinks or tapes, that were completed without witnessing by Field Quality Control. Specification No. NMP2-E061A specifies all Quality Assurance Category I terminations and splices involving heat shrinks or tapes, prior to the application of heat shrinks or tapes, to be mandatory hold points requiring witnessing by Field Quality Control.

The matter is still under investigation and a final report will be submitted by December 21, 1984.