THE CLEVELAND ELECTRIC ILLUMINATING COMPANY

P.O. BOX 5000 - CLEVELAND, OHIO 44101 - TELEPHONE (216) 622-9800 - ILLUMINATING BLDG. — 55 PUBLIC SQUARE

Serving The Best Location in the Nation

50-440
50-441

November 1, 1984

MURRAY R. EDELMAN
VICE PRESIDENT
NUCLEAR

PRINCIPAL STAFF

Mr. James G. Keppler
Regional Administrator, Region III
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

RE: Perry Nuclear Power Plant
Docket Nos. 50-440; 50-441
Restart of the Control Complex
Chiller [RDC 70(83)]

Dear Mr. Keppler:

In our last letter dated June 7, 1984, regarding restart of the Control Room Chiller following a Loss of Offsite Power or a Loss of Coolant Accident, we stated that implementation of the required design modifications was anticipated to be complete by November 1, 1984. However, it has recently been identified that a revision is required for Engineering Change Notice 15384-086-248, which was issued to document the necessary modifications. Since the required revision affects restart of the Control Room Chiller, we now anticipate implementation of this modification by December 28, 1984.

Please call if there are any questions.

Sincerely,

A. Kaplan for M. Edelman

Murray R. Edelman
Vice President
Nuclear Group

8411090240 841101
PDR ADOCK 05000440
S PDR

MRE:pab

cc: Mr. J. A. Grobe
USNRC, Site Office

Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

U.S. Nuclear Regulatory Commission
c/o Document Management Branch
Washington, D.C. 20555

Records Center, SEE-IN
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

1/0 IE01

NOV 1984