LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 | G A E 1 H 2 (2) | 0 0 0 0 0 0 0 0 0 0 0 (3) | 4 1 1 1 1 (4) | L (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T

REPORT SOURCE: L (6) | 0 5 0 0 0 3 6 6 (7) | 1 2 0 3 7 8 (8) | 1 2 0 9 7 8 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

While performing maintenance request 2-78-4924 and 4928 on 2C71-N005A and 2C71-N005A and 2C71-N005B, Turbine control valve fast closure oil pressure low trip switches, the settings were found at 1090 psig decreasing. Technical Specification requirement 2.2.1.2 is 1100 psig. There was no effect on safe plant operation.

SYSTEM CODE: C C (11) | CAUSE CODE: X (12) | CAUSE SUBCODE: Z (13) | COMPONENT CODE: Z Z Z Z Z Z (14) | COMP. SUBCODE: Z (15) | VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 7 8 — SEQUENTIAL REPORT NO. 0 7 4 — OCCURRENCE CODE 0 3 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN: E (18) | FUTURE ACTION: Z (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS (22): 0 0 0 0 | ATTACHMENT SUBMITTED: N (23) | NPRD-4 FORM SUB.: N (24) | PRIME COMP. SUPPLIER: Z (25) | COMPONENT MANUFACTURER: B 0 6 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Instrument 2C71-N005A, 2C71-N005B are Barksdale piston switches series TC9622-3. Switches were out of tolerance because of instrument drift. Instruments were calibrated per HNP-2-5279.

FACILITY STATUS: G (28) | % POWER: 0 0 0 (29) | OTHER STATUS (30): NA | METHOD OF DISCOVERY: B (31) | DISCOVERY DESCRIPTION (32): Maintenance Request

ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): NA | LOCATION OF RELEASE (36): NA

PERSONNEL EXPOSURES — NUMBER: 0 0 0 (37) | TYPE: Z (38) | DESCRIPTION (39): NA

PERSONNEL INJURIES — NUMBER: 0 0 0 (40) | DESCRIPTION (41): NA

LOSS OF OR DAMAGE TO FACILITY (42) — TYPE: Z (43) | DESCRIPTION: NA

PUBLICITY — ISSUED: N (44) | DESCRIPTION (45): NA

NRC USE ONLY

NAME OF PREPARER: R. T. Nix — Maintenance Superintendent

PHONE: (912) 367-7781

7812180225