LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 | G A E T H 2 (2) | 0 0 0 0 0 0 0 0 0 0 0 (3) | 4 1 1 1 1 (4) | (5)
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
2 | 1 REPORT SOURCE L (6) | 0 5 0 0 0 3 6 6 (7) | 0 9 2 1 7 8 (8) | 1 0 0 3 7 8 (9)
8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While starting up but still sub-critical, it was discovered that the drywell airlock
0 3 door seals surveillance required every 72 hours while making multiple entries was not
0 4 performed by 0940 on 9/19/78 as required.
0 5
0 6
0 7
0 8 80
7 8 9

SYSTEM CODE Z Z (11) | CAUSE CODE A (12) | CAUSE SUBCODE A (13) | COMPONENT CODE Z Z Z Z Z Z (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)
0 9 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER [EVENT YEAR 7 8 21 22 | — 23 | SEQUENTIAL REPORT NO. 0 3 9 24 26 | / 27 | OCCURRENCE CODE 0 3 28 29 | REPORT TYPE L 30 | — 31 | REVISION NO. 0 32]

ACTION TAKEN H (18) 33 | FUTURE ACTION Z (19) 34 | EFFECT ON PLANT Z (20) 35 | SHUTDOWN METHOD Z (21) 36 | HOURS (22) 0 0 0 0 37 40 | ATTACHMENT SUBMITTED N (23) 41 | NPRD-4 FORM SUB. N (24) 42 | PRIME COMP. SUPPLIER Z (25) 43 | COMPONENT MANUFACTURER Z 9 9 9 (26) 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Surveillance was performed upon discovery and completed at 1700 9/21/78. Personnel
1 1 were instructed to watch this requirement carefully so that it does not get missed
1 2 again.
1 3
1 4 80
7 8 9

FACILITY STATUS B (28) 9 | % POWER 0 0 1 (29) 10 12 | OTHER STATUS (30) N/A 13 44 | METHOD OF DISCOVERY Z (31) 45 | DISCOVERY DESCRIPTION (32) Shift Foreman Observation 46 80
1 5 7 8

ACTIVITY RELEASED Z (33) 9 | CONTENT OF RELEASE Z (34) 10 | AMOUNT OF ACTIVITY (35) N/A 11 44 | LOCATION OF RELEASE (36) N/A 45 80
1 6 7 8

PERSONNEL EXPOSURES NUMBER 0 0 0 (37) 9 11 | TYPE Z (38) 12 | DESCRIPTION (39) N/A 13 80
1 7 7 8

PERSONNEL INJURIES NUMBER 0 0 0 (40) 9 11 | DESCRIPTION (41) N/A 12 80
1 8 7 8

LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) 9 | DESCRIPTION (43) N/A 10 80
1 9 7 8

PUBLICITY ISSUED N (44) 9 | DESCRIPTION (45) N/A 10 68 | NRC USE ONLY 69 80
2 0 7 8

7810180122

NAME OF PREPARER S. X. Baxley, Superintendent Oper. PHONE: (912) 367-7781