NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | ARAN01 (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 05000313 (7) | 092678 (8) | 101378 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During steady state, power operation, a normal BWST chemical sample showed a boron concentration of 2261 ppmb violating T.S. 3.3.1.G. The tank's contents were recirculated via decay heat pump & then resampled with the same results. There have been no similiar occurrances

SYSTEM CODE: WG (11) | CAUSE CODE: X (12) | CAUSE SUBCODE: Z (13) | COMPONENT CODE: ZZZZZZ (14) | COMP. SUBCODE: Z (15) | VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 78 | — | SEQUENTIAL REPORT NO. 026 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN: E (18) | FUTURE ACTION: Z (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS (22): 0000 | ATTACHMENT SUBMITTED: N (23) | NPRD-4 FORM SUB.: N (24) | PRIME COMP. SUPPLIER: Z (25) | COMPONENT MANUFACTURER: Z999 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Boron addition was calculated and concentration was raised to 2298 ppmb meeting requirements of Action Statement T.S. 3.3.6.

FACILITY STATUS: E (28) | % POWER: 100 (29) | OTHER STATUS (30): NA | METHOD OF DISCOVERY: A (31) NA | DISCOVERY DESCRIPTION (32)

ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): NA | LOCATION OF RELEASE (36): NA

PERSONNEL EXPOSURES — NUMBER: 000 (37) | TYPE: Z (38) | DESCRIPTION (39): NA

PERSONNEL INJURIES — NUMBER: 000 (40) | DESCRIPTION (41): NA

LOSS OF OR DAMAGE TO FACILITY (43) — TYPE: Z (42) | DESCRIPTION: NA

PUBLICITY — ISSUED: N (44) | DESCRIPTION (45): NA

NRC USE ONLY

NAME OF PREPARER: Chris N. Shively PHONE: 501/968-2519

7811060183