Yellow

Docket Nos. 50-62, 50-396
License Nos. R-66, R-123

University of Virginia
ATTN: Dr. R. U. Mulder, Director
        Reactor Facility
Charlottesville, VA 22901

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-62/88-04

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by
P. Y. Burnett on August 22 - 25, 1988. The inspection included a review of
activities authorized for your University of Virginia Reactor facility. At the
conclusion of the inspection, the findings were discussed with those members of
your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within
these areas, the inspection consisted of selective examinations of procedures
and representative records, interviews with personnel, and observation of
activities in progress.

Within the scope of the inspection, no violations or deviations were
identified.

The enclosed Inspection Report documents an oral commitment (See page 5) made by a
licensee representative and discussed in the exit interview. If your
understanding of this commitment differs from the report statements, please
inform this office promptly.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2,
Title 10, Code of Federal Regulations, a copy of this letter and its enclosure
will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

/S/

Alan R. Herdt, Chief
Engineering Branch
Division of Reactor Safety

Enclosure:
NRC Inspection Report

cc w/encl: (See page 2)

University of Virginia   2

cc w/encl:
Dr. J. S. Tulenko, University
  of Florida
Dr. Ratib A. Karam, Georgia
  Institute of Technology
Dr. Paul J. Turinsky, North
  Carolina State University
Commonwealth of Virginia

bcc w/encl:
License Fee Management Branch
DRS Technical Assistant
Document Comtrol Desk

RIL   RII   RII
PBurnett:ac   FJ   PFredrickson
9/ /88   9/ /88   10/ /88