UNIVERSITY OF MAINE

Administrative Services

Alumni Hall
Orono, Maine 04469-0102
207/581-1545

November 25, 1986

Docket Nos. 030-11003 and 070-00341
License Nos. 18-01475-15 and SNM-339

John E. Glenn, Ph.D., Chief
Nuclear Materials Safety Section B
Division of Radiation Safety
and Safeguards
Nuclear Regulatory Commission
Region I
King of Prussia, PA 19406

Dear Dr. Glenn:

RE: Response to Notice of Violation dated
October 30, 1986:

1. Failure to calibrate RDX survey meters.

   a. Corrective steps: A calibration source, NBS traceable, has been ordered. All meters will be calibrated by the Radiation Safety Office after we receive the source.

   b. Future corrective steps: Meters will be calibrated annually by the Radiation Safety Office.

   c. Full compliance will be achieved within one week after the source is received.

2. Failure to survey contaminated area following decontamination.

   a. Corrective step, and future corrective steps: If contaminated areas are found in the future, notification will be made immediately to the investigator; a followup survey will be made within one day following decontamination.

   b. Full compliance has already been achieved.

Sincerely,

Alden E. Stuart

Alden E. Stuart
Assistance Vice President
for Administrative Services

AES/em

8702170436 870205
REG1 LIC30
18-01475-15 PDR

1986 DEC -3 PM 1:39
RECEIVED-REGION 1