DIANON SYSTEMS

Diagnostic Innovations for Oncology

MS 16
P2

January 26, 1987

John E. Glenn, Ph.D., Chief
Nuclear Materials Safety Section B
Division of Radiation Safety and Safeguards
United States Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, Pennsylvania

Re: Docket No. 030-29575
Control No. 119933

Dear Dr. Glenn:

This is to confirm that starting immediately medical technologists using radioactive materials will monitor their hands with a Geiger counter before leaving work each day. The procedure is enclosed.

Sincerely,

Phillenore D. Howard

Phillenore D. Howard, Ph.D.
Vice President of
Laboratory Operations

PDH:mbt

enclosure

8705150358 870227
REG1 LIC30
06-23655-01 PDR

119933

"OFFICIAL RECORD COPY"
ML18 FEB 04 1987

LABORATORY PROCEDURES

PREPARED BY:	TITLE:	EFFECTIVE DATE:
P. HOWARD	MONITORING OF HANDS BY GEIGER COUNTER	1/23/87
		PAGE: 1 OF 1

Each day before leaving the laboratory wash your hands thoroughly. Turn the Contamination Monitor on. Set the dial at X1. Test battery. If battery is charged adequately, place your hands under the monitor without touching the plastic shield. Wait 15 seconds. Record the cpm. If counts exceed 50 cpm, rewash hands and repeat test.

CONVERSATION RECORD

TIME 1:58 Pm | DATE 1-21-87

TYPE

☐ VISIT ☐ CONFERENCE ☒ TELEPHONE

☐ INCOMING ☒ OUTGOING

Location of Visit/Conference:

NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YOU	ORGANIZATION (Office, dept., bureau, etc.)	TELEPHONE NO.
Phillenore D. Howard, Ph.D. / Lab. Dir.	Dianon Systems, Inc.	(203) 381-4028

ROUTING

NAME/SYMBOL	INT

SUBJECT

030-29575 / 119933

SUMMARY

Need a commitment that personnel will monitor their hands, feet & clothing prior to leaving at end of work day.

ACTION REQUIRED

NAME OF PERSON DOCUMENTING CONVERSATION	SIGNATURE	DATE
	Mike Varela	1-21-86

ACTION TAKEN

SIGNATURE	TITLE	DATE