L&R:IB:WCM

FEB 15 1963

The Budd Company
Instruments Division
Box 245
Phoenixville, Pennsylvania

Attention: Mr. Michael P. Santoro

Gentlemen:

In response to your request as to the types of your sources which have been reported to the Commission as leaking and/or contaminated, we note that reports on approximately thirty sources have been filed. This includes models designated as 2-136, 2-187, 2-200, 2-223, 41030, 41035, 41036, 41038, 41041, 41046, T-70017 and several unidentified.

Oftentimes it is not known if the source was in fact leaking or the external contamination originated from sources other than actual leakage from the capsule. Also, the number given above is based upon a cursory files review and does not indicate total information; however, it should provide you with the information needed for quality control purposes.

Very truly yours,

William O. Miller
Isotopes Branch
Division of Licensing
and Regulation

FOIA 87-187 A13

8706170535 870611
PDR FOIA
BERKE87-187 PDR