COMBUSTION

June 26, 1987

NOTE TO: R. E. Cunningham
G. L. Sjoblom
L. C. Rouse

COMBUSTION ENGINEERING (CE), WINDSOR, CONNECTICUT

J. Roth reported that a utility, SCE, shut CE down during a vendor inspection on 6/19/87. The cause was repeated failure to follow procedures. CE is still shutdown.

The shutdown stems from an apparent quality control failure, re 10 CFR 50, Appendix B. The NRC Vendor Branch is following this development.

Original Signed By:

George H. Bidinger, FCUF

Distribution:
Docket 70-1100
NMSS R/F
FCUF R/F
GBidinger
VLTharpe
PDR

NMSS/Fuel Cycle Material
FCUF ✓
FCAF
File: Docket # 70-1100
Project #
Other
PDR ✓
LPDR
Return to G Thayer
SS 396

8707020073 870626
PDR ADOCK 07001100
C PDR

OFC	:NMSS	:	:	:	:	:	:
NAME	GBidinger:	:	:	:	:	:	:
DATE	:06/26/87	:	:	:	:	:	: