April 11, 1985

MEMORANDUM FOR: L. Miller, Chief
Reactor Projects Section II

THROUGH: G. Yuhas, Chief
Facilities Radiological Protection Section

FROM: C. Sherman
Radiation Specialist

SUBJECT: PALO VERDE UNIT 1 (50-528); READINESS FOR FULL POWER OPERATION

Items required for full power operation are listed in the enclosure. No problems impacting on the license issuance are anticipated.

/s/

Conrad Sherman
Radiation Specialist

Enclosure:
As stated

RV
Sherman:rc
04/11/85

Yuhas
04/11/85

85-122

8909170038 890913
PDR FOIA
WILLIAM89-126 PDR

G/9

ENCLOSURE

Items required prior to full power operation

1. License Condition 2.C.17 PASS (5% power)

   No problems are anticipated in this area by the licensee. Progress in completing system modifications is on schedule. Completion of all testing is expected prior to 5% power.

2. License Condition 2.C.20 Radiochemistry Laboratory (10/24/84 letter)

   The licensee is maintaining the Unit 2 chemistry laboratory. It is expected that they will complete work to make the lab able to handle PASS samples prior to exceeding 5% power.

3. Action to correct

   Deficiencies in licensed operator training related to the radiation monitoring system (RMS) and the RMS alarm response procedure identified in Inspection Report 84-64 have not been inspected. This item will be reinspected at the earliest opportunity.