



KEY (1)

NOTES:

1) ALL INFORMATION PROVIDED IS ON A "PER TENDON END" BASIS.

2) A HEAVY OVAL AROUND TENDON DESIGNATION INDICATES THAT THIS TENDON END HAS HAD A SURVEILLANCE SINCE THE JANUARY, 1988 TENDON SURVEILLANCE REPORT.

EXAMPLE:

(01/87) NO SURVEILLANCE SINCE JANUARY, 1988 REPORT.

(01/87) SURVEILLANCE SINCE JANUARY, 1988 REPORT.

3) V = VISUAL INSPECTION ONLY OF TENDON END ANCHOR RECENTLY.
L = LIFTOFF PLUS VISUAL INSPECTION OF TENDON END ANCHOR RECENTLY AND WIRE BUNDLE.
D = DETENSIONED.
N = NOT ACCESSIBLE FOR VISUAL OR LIFTOFF.

DRAWING GENERATED FOR TENDON INTERIM SURVEILLANCE REPORT, AUGUST, 1988.

NO.	DRWG	DATE	BY	CK.	REVISION	E	N	A.C.	NF		

DRAWING NUMBER 13569.07-EC-1D

Public Service®
Public Service Company of Colorado
FT. ST. VRAIN

PCRV TENDON SURVEILLANCE PLAN SHEET 4

CHKD CORRECT

APPROVALS

E
M
D
C

DRN. MILLER DATE 08/12/88
CHKD DATE

SCALE

SHEET 4 OF 4

8809160232

31 APERTURE CARD

PDR RIDS

8809160232



MMM 5924 — FILMSORT® Brand Aperture 8 Camera Cards and DUPLICARD® Brand Copy Cards — Product of 3M — St. Paul, Minn.