
TURBINE SUPERVISORY INSTRUMENTATION ALARMS & VALVE INDICATIONS
STEAM LINE DRAIN ISOLATION VALVES A023-42 & 43
CONDENSATE DRAIN POT DRAIN
CONDENSATE DRAIN POT DRAIN
STEAM SUPPLY VALVE TO TURBINE MO 23-14
AUXILIARY OIL PUMP REF 10
START AUXILIARY OIL PUMP
START GLAND SEAL CONDENSER BLOWER
TURBINE AUTOMATIC INITIATION CONTROL
TURBINE SUPERVISORY INDICATING LIGHTS
INFORMATION ONLY
* THIS DRAWING GENERATED BY NPPD
COOPER NUCLEAR STATION
HIGH PRESSURE COOLANT INJECTION SYS
FUNCTIONAL CONTROL DIAGRAM
GENERAL ELECTRIC*
729E589BB,SH.2
NON-CONTROLLED PRINT
MAY 07 1999
NPPD/CAS
452005103
CADD DRAWING
DO NOT REVISE MANUALLY
DCN# 96-0111
DCN REVISIONS BY N.P.P.D.
* FOR PREVIOUS REVISIONS SEE SUPERSEDED CARDS
NOV. 26, 1997 NPPD
APERTURE CARD

9907090163

PDR RIDS

9907090163



MMM 5824