Tier / Group	Randomly Selected K/A	Reason for Rejection
2/1 #52	073000 K4.02	Letdown does not isolate on High RCS Activity, and there is no Process Monitor for RCS \CVCS. (We use room Area Monitors but with no auto actions for High RCS Activity) NRC Replaced with 073000 K4.01
2/2 #60	033000 A3.02	SFP Cooling has no Automatic Functions. NRC Replaced with 035000 A3.01
2/2 #63	071000 K3.04	Waste Gas will not cause ventilation to isolate. NRC Replaced with 071000 K3.05
2/2 SRO #093	034000 A3.03	High Flux at shutdown does not automatically affect the Fuel Handling System – just automatic Containment Evacuation Alarm. NRC Replaced with 034000 A4.02
1/1 #8	000038 2.2.22	Unable to write a question of sufficient difficulty & psychometric attributes addressing safety limits in Tube Rupture. NRC Replaced with 000038 2.2.44
1/1 SRO #78	000029 2.4.4	Unable to write a question at the SRO level addressing the entry conditions for the ATWS Procedure (RO Knowledge). NRC Replaced with 000029 2.4.16
1/2 SRO #82	000024 A2.02	Unable to write a SRO level question of sufficient difficulty & psychometric attributes addressing use of manual boration valve. NRC Replaced with 000024 A2.04
2/1 SRO #88	012000 A2.03	Unable to write a SRO level question of sufficient difficulty & psychometric attributes addressing consequences of incorrect channel bypassing. NRC Replaced with 012000 A2.02