






FIGURE 3.5-1

TURBINE PLACEMENT AND ORIENTATION

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT





FIGURE 3.5-2

TURBINE MISSILE
REFERENCED COORDINATE SYSTEM

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



$\delta_1, \delta_2 =$ DEFLECTION ANGLES

(SHADED AREA SHOWS REGION OF POSSIBLE VELOCITY VECTOR PENETRATION)

FIGURE 3.5-3

SOLID ANGLE ON A UNIT SPHERE

NIAGARA MOHAWK POWER CORPORATION
 NINE MILE POINT-UNIT 2
 FINAL SAFETY ANALYSIS REPORT




FIGURE 3.5-4

TOP VIEW OF IDEALIZED TARGET

NIAGARA MOHAWK POWER CORPORATION
 NINE MILE POINT-UNIT 2
 FINAL SAFETY ANALYSIS REPORT






FIGURE 3.5-5

SIDE VIEW OF IDEALIZED TARGET

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
 FINAL SAFETY ANALYSIS REPORT





SOURCE:
 MOODY J.F.
 TIME-DEPENDENT PIPE FORCES CAUSED
 BY BLOWDOWN AND FLOW STOPPAGE
 ASME PAPER 73-FE-23, 1973 (REFERENCE 2)

THIS DRAWING WAS PRODUCED ELECTRONICALLY.
 DO NOT MAKE ANY CHANGES MANUALLY.

FIGURE 3.6A-2

STEADY STATE BLOWDOWN
 FORCES VS FRICTION PARAMETER

NINE MILE POINT
 NUCLEAR STATION - UNIT 2
 SCRIBA, N.Y.
 UPDATED SAFETY ANALYSIS REPORT





FIGURE 3.6A-3

DYNAMIC ANALYSIS MODEL RHS
(LPCI) RESTRAINT 2RHS*PRR004

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



$$P_o = 1028 \text{ PSIA}$$

$$A = 252.7 \text{ IN}^2$$

t_1 = APPROX. TIME FOR DECOMPRESSED
WAVE TO REACH ELBOW (0.011 SEC)

t_2 = APPROX. TIME TO REACH STEADY
STATE FORCING FUNCTION (0.021 SEC)

FIGURE 3.6A-4

FLUID BLOWDOWN FORCES USED FOR
2RHS*PRR004 RESTRAINT ANALYSIS

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.6A-5

RESTRAINT (2RHS* PRR004)
REACTION LOAD

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.6A-6

ENERGY BALANCE SAMPLE PROBLEM

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
 FINAL SAFETY ANALYSIS REPORT





FIGURE 3.6A-7

PIPE CRUSH BUMPER

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.6A-8

TWO-PIN LAMINATED
PIPE RUPTURE RESTRAINT
(SMALL LINES)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.6A-9

TWO-PIN LAMINATED
PIPE RUPTURE RESTRAINT
(LARGE LINES)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT





FIGURE 3.6A-10

OMNI-DIRECTIONAL
PIPE RUPTURE RESTRAINT

NIAGARA MOHAWK POWER CORPORATION
 NINE MILE POINT-UNIT 2
 FINAL SAFETY ANALYSIS REPORT




FIGURE 3.6A-11

LIMIT STOP RESTRAINT

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT

FIGURES 3.6A-12 THROUGH 3.6A-49 HAVE BEEN DELETED.

**THIS FIGURE HAS
BEEN DELETED**

FIGURE 3.6A-50

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT

**THIS FIGURE HAS
BEEN DELETED**

FIGURE 3.6A-51

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.6A-55

HIGH ENERGY PIPING COMPOSITE
PLAN EL. 289'-0"

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

USAR REVISION 0

APRIL 1989



THIS DRAWING WAS PREPARED ELECTRONICALLY.

OCTOBER 2002





FIGURE 3.6A-58


HIGH ENERGY PIPING COMPOSITE
SECTION 1-1

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT


USAR REVISION 2

OCTOBER 1990





3-3



4-4

SOURCE:

FIGURE 3.6a-60

HIGH ENERGY PIPING COMPOSITE
SECTION "3-3" AND "4-4"

NINE MILE POINT-JNIT 2
UPDATED SAFETY ANALYSIS REPORT





FIGURE 3.6B-1

TYPICAL RESTRAINT FORCE-DEFLECTION
CURVE

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.6B-2

TYPICAL PIPE WHIP RESTRAINT
CONFIGURATION

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.6B-3

BREAK LOCATIONS AND RESTRAINTS
ANALYZED, PDA VERIFICATION PROGRAM

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 37A-1

HORIZONTAL SSE DESIGN RESPONSE
SPECTRA NORMALIZED TO 0.15 G

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 37A-2

VERTICAL SSE DESIGN RESPONSE
SPECTRA NORMALIZED TO 0.15 G

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-3

HORIZONTAL SSE DESIGN RESPONSE SPECTRUM AND RESPONSE SPECTRUM DERIVED FROM HORIZONTAL SSE SYNTHETIC TIME HISTORY (EAST-WEST EARTHQUAKE) BASED ON 1.0 PERCENT DAMPING RATIO

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-4

HORIZONTAL SSE DESIGN RESPONSE SPECTRUM AND RESPONSE SPECTRUM DERIVED FROM HORIZONTAL SSE SYNTHETIC TIME HISTORY (EAST-WEST EARTHQUAKE) BASED ON 2.0 PERCENT DAMPING RATIO

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-5

HORIZONTAL SSE DESIGN RESPONSE
SPECTRUM AND RESPONSE SPECTRUM
DERIVED FROM HORIZONTAL SSE
SYNTHETIC TIME HISTORY (EAST-WEST
EARTHQUAKE) BASED ON 5.0 PERCENT
DAMPING RATIO

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-6

HORIZONTAL SSE DESIGN RESPONSE
SPECTRUM AND RESPONSE SPECTRUM
DERIVED FROM HORIZONTAL SSE
SYNTHETIC TIME HISTORY (EAST-WEST
EARTHQUAKE) BASED ON 7.0 PERCENT
DAMPING RATIO

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-7

HORIZONTAL SSE DESIGN RESPONSE SPECTRUM AND RESPONSE SPECTRUM DERIVED FROM HORIZONTAL SSE SYNTHETIC TIME HISTORY (EAST-WEST EARTHQUAKE) BASED ON 10.0 PERCENT DAMPING RATIO

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-8

HORIZONTAL SSE DESIGN RESPONSE
SPECTRUM AND RESPONSE SPECTRUM
DERIVED FROM HORIZONTAL SSE
SYNTHETIC TIME HISTORY (NORTH-SOUTH
EARTHQUAKE) BASED ON 1.0 PERCENT
DAMPING RATIO

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-9

HORIZONTAL SSE DESIGN RESPONSE
SPECTRUM AND RESPONSE SPECTRUM
DERIVED FROM HORIZONTAL SSE
SYNTHETIC TIME HISTORY (NORTH-SOUTH
EARTHQUAKE) BASED ON 2.0 PERCENT
DAMPING RATIO

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-10

HORIZONTAL SSE DESIGN RESPONSE SPECTRUM AND RESPONSE SPECTRUM DERIVED FROM HORIZONTAL SSE SYNTHETIC TIME HISTORY (NORTH-SOUTH EARTHQUAKE) BASED ON 5.0 PERCENT DAMPING RATIO

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-11

HORIZONTAL SSE DESIGN RESPONSE
SPECTRUM AND RESPONSE SPECTRUM
DERIVED FROM HORIZONTAL SSE
SYNTHETIC TIME HISTORY (NORTH-SOUTH
EARTHQUAKE) BASED ON 7.0 PERCENT
DAMPING RATIO

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-12

HORIZONTAL SSE DESIGN RESPONSE
SPECTRUM AND RESPONSE SPECTRUM
DERIVED FROM HORIZONTAL SSE
SYNTHETIC TIME HISTORY (NORTH-SOUTH
EARTHQUAKE) BASED ON 10.0 PERCENT
DAMPING RATIO

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-13

VERTICAL SSE DESIGN RESPONSE
 SPECTRUM AND RESPONSE SPECTRUM
 DERIVED FROM VERTICAL SSE
 SYNTHETIC TIME HISTORY BASED ON
 1.0 PERCENT DAMPING RATIO

NIAGARA MOHAWK POWER CORPORATION
 NINE MILE POINT-UNIT 2
 FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-14

VERTICAL SSE DESIGN RESPONSE
 SPECTRUM AND RESPONSE SPECTRUM
 DERIVED FROM VERTICAL SSE
 SYNTHETIC TIME HISTORY BASED ON
 2.0 PERCENT DAMPING RATIO

NIAGARA MOHAWK POWER CORPORATION
 NINE MILE POINT-UNIT 2
 FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-15

VERTICAL SSE DESIGN RESPONSE
 SPECTRUM AND RESPONSE SPECTRUM
 DERIVED FROM VERTICAL SSE
 SYNTHETIC TIME HISTORY BASED ON
 5.0 PERCENT DAMPING RATIO

NIAGARA MOHAWK POWER CORPORATION
 NINE MILE POINT-UNIT 2
 FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-16

VERTICAL SSE DESIGN RESPONSE
SPECTRUM AND RESPONSE SPECTRUM
DERIVED FROM VERTICAL SSE
SYNTHETIC TIME HISTORY BASED ON
7.0 PERCENT DAMPING RATIO

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-17

VERTICAL SSE DESIGN RESPONSE
 SPECTRUM AND RESPONSE SPECTRUM
 DERIVED FROM VERTICAL SSE
 SYNTHETIC TIME HISTORY BASED ON
 10.0 PERCENT DAMPING RATIO

NIAGARA MOHAWK POWER CORPORATION
 NINE MILE POINT-UNIT 2
 FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-18

DYNAMIC MODEL FOR SEISMIC
ANALYSIS OF PRIMARY
CONTAINMENT

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-19

DYNAMIC MODEL FOR SEISMIC
ANALYSIS OF REACTOR
BUILDING WALL

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-20

DYNAMIC MODEL FOR SEISMIC
ANALYSIS OF THE CONTROL AND
DIESEL GENERATOR BUILDINGS

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-21

SSE PRIMARY CONTAINMENT
CRACKED CONDITION
ACCELERATION PROFILE (G)
EAST-WEST DIRECTION

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-22

SSE PRIMARY CONTAINMENT
CRACKED CONDITION
ACCELERATION PROFILE (Gs)
VERTICAL DIRECTION

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-23

SSE PRIMARY CONTAINMENT
CRACKED CONDITION
ACCELERATION PROFILE (Gs)
NORTH-SOUTH DIRECTION

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-24

SSE PRIMARY CONTAINMENT
 UNCRACKED CONDITION
 ACCELERATION PROFILE (Gs)
 EAST-WEST DIRECTION

NIAGARA MOHAWK POWER CORPORATION
 NINE MILE POINT-UNIT 2
 FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-25

SSE PRIMARY CONTAINMENT
UNCRACKED CONDITION
ACCELERATION PROFILE (Gs) '
VERTICAL DIRECTION

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-26

SSE PRIMARY CONTAINMENT
UNCRACKED CONDITION
ACCELERATION PROFILE (Gs)
NORTH-SOUTH DIRECTION

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-27

SSE REACTOR BUILDING WALL
ACCELERATION PROFILE (Gs)
EAST-WEST DIRECTION

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-28

SSE REACTOR BUILDING WALL
ACCELERATION PROFILE (Gs)
VERTICAL DIRECTION

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-29

SSE REACTOR BUILDING WALL
ACCELERATION PROFILE (Gs)
NORTH-SOUTH DIRECTION

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-30

SSE CONTROL AND DIESEL
GENERATOR BUILDINGS
ACCELERATION PROFILE (Gs)
EAST-WEST DIRECTION

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-31

SSE CONTROL AND DIESEL
GENERATOR BUILDINGS
ACCELERATION PROFILE (Gs)
VERTICAL DIRECTION

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7A-32

SSE CONTROL AND DIESEL
GENERATOR BUILDINGS
ACCELERATION PROFILE (Gs)
NORTH-SOUTH DIRECTION

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT





FIGURE 3.7A-33

PLAN AND SECTIONS FOR DUCTLINES 907, 922,
ELECTRICAL MANHOLE #1, AND
DIESEL GENERATOR BUILDING FLOOR SLABS

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




**DAMPING VALUE FOR SEISMIC ANALYSIS OF PIPING
(APPLICABLE TO BOTH OBE & SSE, INDEPENDENT OF PIPE DIAMETER)**

FIGURE 3.7A-34

ALTERNATIVE DAMPING
VALUES PER ASME CODE
CASE N-411

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




OBE DISPLACEMENT RELATIVE TO BASE MAT (RESPONSE SPECTRA METHOD)			
AT NODE PT	E-W INCHES	VERT INCHES	N-S INCHES
12	0.178	0.012	0.177
24	0.123	0.018	0.129
16	0.123	0.010	0.150
25	0.074	0.010	0.063

OBE RELATIVE DISPLACEMENT BETWEEN NODES (TIME HISTORY METHOD)			
BETWEEN NODES	E-W (MAX) INCHES	VERT (MAX) INCHES	N-S (MAX) INCHES
12 } 24 }	0.214	0.018	0.234
16 } 25 }	0.147	0.013	0.162
16 } 24 }	0.173	0.018	0.177

FIGURE 3.7A-35

RELATIVE DISPLACEMENT BETWEEN
REACTOR BUILDING AND
PRIMARY CONTAINMENT

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT




NOTES:

1. RRS OF ACCELERATION SECONDARY CONT. (ELEV. 353.83 FT)
2. FAULTED CONDITION, HORIZONTAL DIRECTION
3. DAMPING VALUE = 0.03

FIGURE 3.7A-36 (SHEET 1 OF 2)

JUSTIFICATION OF STATIC
COEFFICIENT OF 1.3

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT



NOTES:

1. RRS OF ACCELERATION SECONDARY CONT. (ELEV. 353.83 FT)
2. FAULTED CONDITION, VERTICAL DIRECTION
3. DAMPING VALUE = 0.03

FIGURE 3.7A-36 (SHEET 2 OF 2)

JUSTIFICATION OF STATIC
COEFFICIENT OF 1.3

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT








FIGURE 3.7B-1

SEISMIC ANALYTICAL MODEL FOR NSSS
COMPONENTS

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.7B-2

REACTOR PRESSURE VESSEL AND INTERNALS
SEISMIC MODEL

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.8-1

PRIMARY CONTAINMENT
LINER ELEVATION AND DETAILS

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT





FIGURE 3.8-2

PRIMARY CONTAINMENT
LINER FLOOR

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




PRIMARY CONTAINMENT SECTION


FIGURE 3.8-3

PRIMARY CONTAINMENT WALL
SECTION VIEW

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



EXPANDED ELEVATION-INSIDE FACE OF WALL



EXPANDED ELEVATION-OUTSIDE FACE OF WALL


SOURCE: EC-38C / EC-38D

FIGURE 3.8-3a


PRIMARY CONTAINMENT WALL
REINFORCING DETAILS EL. 175'-0"
TO 241'-1" AZIMUTH 180° TO 360°

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

USAR REVISION 4 OCTOBER 1992



ESCAPE AIR LOCK OPENING
@ AZIMUTH 236°




EQUIPMENT HATCH OPENING
@ AZIMUTHS 135° & 315°


FIGURE 3.8-4

PRIMARY CONTAINMENT WALL
STRUCTURAL DETAILS AROUND
DRYWELL ACCESS HATCHES


NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



PIPE WHIP RESTRAINT BEAM SEAT



PIPE WHIP RESTRAINT BEAM SEAT



RADIAL AND NON-RADIAL FLOOR BEAM SEAT

FIGURE 3.8-5

PRIMARY CONTAINMENT
TYPICAL BEAM SEAT DETAILS

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.8-6

COMBINATION EQUIPMENT HATCH
AND PERSONAL AIRLOCK AND ESCAPE
AIRLOCK — PRIMARY CONTAINMENT

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.8-7

CONTROL ROD DRIVE REMOVAL
HATCH AND SUPPRESSION POOL
ACCESS HATCH

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT







FIGURE 3.8-8


DRYWELL HEAD AND FINGER PIN
CLOSURE DETAILS

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT


USAR REVISION 7 OCTOBER 1994




SUPPRESSION POOL TEMPERATURE MONITORING PENETRATION



CONTROL ROD DRIVE PENETRATION



ELECTRICAL PENETRATION SLEEVE




INSTRUMENT PENETRATION
NEUTRON MONITORING PENETRATION

FIGURE 3.8-9

OTHER PIPING AND INSTRUMENT
PENETRATIONS THROUGH
PRIMARY CONTAINMENT

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



(SOURCE DOCUMENT: EV-001L REV.09.
EV-001N REV.07)

FIGURE 3.8-10

THERMALLY HOT AND THERMALLY
COLD PIPING PENETRATIONS
THROUGH PRIMARY CONTAINMENT

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

USAR Revision 15

October 2002




FIGURE 3.8-11

**PRIMARY CONTAINMENT AND
INTERNAL STRUCTURES**

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT





FIGURE 3.8-12

ARRANGEMENT OF PENETRATIONS
THROUGH DRYWELL FLOOR

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT







FIGURE 3.8-15

BIOLOGICAL SHIELD WALL-
DETAILS

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT





FIGURE 3.8-16

RING GIRDER, STAR TRUSS AND STABILIZER ARRANGEMENT

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.8-17

TYPICAL DETAILS AT CONSTRUCTION JOINTS
AND SPACES BETWEEN BUILDING
AND ROCK SURFACE

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.8-18

EXTERIOR REACTOR BUILDING WALL
TYPICAL REINFORCING ARRANGEMENT
SHEET 1 OF 2

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.8-18

EXTERIOR REACTOR BUILDING WALL
TYPICAL REINFORCING ARRANGEMENT
SHEET 2 OF 2

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT






FIGURE 3.8-19

SPENT FUEL POOL GIRDERS
PLAN AND ELEVATION
SHEET 1 OF 2

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



3 - 3



2 - 2

FIGURE 3.8-19

SPENT FUEL POOL GIRDERS
REINFORCING ARRANGEMENT
SHEET 2 OF 2

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT





FIGURE 3.8-20

REINFORCEMENT
REACTOR BUILDING MAT

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




* HOOKS MAY BE TURNED IN EITHER DIRECTION

FIGURE 3.8-21

TYPICAL DETAIL WALL/COLUMN
TO FOUNDATION MAT JUNCTION

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



SOURCE: EC-30C

FIGURE 3.8-22

CONTAINMENT MAT-TOP
REINFORCING DETAILS

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

II SAR REVISION 4

OCTOBER 1992



CONTAINMENT MAT-BOTTOM REINFORCING DETAILS

USAR REVISION 4

OCTOBER 1992




FIGURE 3.9A-1

TYPICAL SAFETY CLASSES 2 AND 3
TUBE SUPPORTS AND MARKING

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.9A-2

TYPICAL PLATE & SHELL TYPE SUPPORT
JURISDICTIONAL BOUNDARIES

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.9A-3

TYPICAL PLATE & SHELL TYPE SUPPORT
JURISDICTIONAL BOUNDARIES

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.9A-4

TYPICAL LINEAR TYPE SUPPORT
JURISDICTIONAL BOUNDARIES

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.9A-5

PIPE SUPPORT
JURISDICTIONAL BOUNDARIES

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT


SEISMIC (OBE)

DAMPING VALUES = 0.010

0.020

0.040

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-6

RRS OF ACC. PRIMARY CONT.
(ELEV 196.67 FT)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT


SEISMIC (OBE)

DAMPING VALUES = 0.010

0.020

0.040

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-7


RRS OF ACC. PRIMARY CONT.
(ELEV 196.67 FT)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (OBE)

DAMPING VALUES = 0.010
0.020
0.040

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-8

RRS OF ACC. SHIELD WALL
(ELEV 315.08 FT)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT


SEISMIC (OBE)

DAMPING VALUES = 0.010

0.020

0.040

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-9

RRS OF ACC. SHIELD WALL
(ELEV 315.08 FT)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT


USAR REVISION 0

APRIL 1989

SEISMIC (OBE)

DAMPING VALUES = 0.010
0.020
0.040

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A -10

RRS OF ACC. RPV SHELL
(ELEV 332.70 FT)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT


SEISMIC (OBE)

DAMPING VALUES = 0.010

0.020

0.040

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-11


RRS OF ACC. RPV SHELL
(ELEV 332.70 FT)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (SSE)

DAMPING VALUES= 0.020
0.030
0.040
0.070

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

(SOURCE DOCUMENT: MS-1765 REV. 01)


FIGURE 3.9A-12

RRS OF ACC. PRIMARY CONT.
(ELEV 196.67 FT)

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (SSE)

DAMPING VALUES= 0.020
0.030
0.040
0.070



NOTE: THESE CURVES REPRESENT A SPREAD OF +15% AND -15%

(SOURCE DOCUMENT: MS-1765 REV. 01)

FIGURE 3.9A-13


RRS OF ACC. PRIMARY CONT.
(ELEV 196.67 FT)

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (SSE)

DAMPING VALUES= 0.020
0.030
0.040
0.070

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

(SOURCE DOCUMENT: MS-1765 REV. 01)

FIGURE 3.9A-14

RRS OF ACC. SHIELD WALL
(ELEV 315.08 FT)

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (SSE)


DAMPING VALUES= 0.020

0.030

0.040

0.070

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

(SOURCE DOCUMENT: MS-1765 REV. 01)

FIGURE 3.9A-15


RRS OF ACC. SHIELD WALL
(ELEV 315.08 FT)

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (SSE)

DAMPING VALUES= 0.020
0.030
0.040
0.070

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

(SOURCE DOCUMENT: MS-1765 REV. 01)

FIGURE 3.9A-16


RRS OF ACC. RPV SHELL
(ELEV 332.70 FT)

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (SSE)

DAMPING VALUES = 0.020
0.030
0.040
0.070

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-17


RRS OF ACC. RPV SHELL
(ELEV 332.70 FT)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SRV(ENV. OF ALL SRV CASES)

DAMPING VALUES= 0.010
0.020
0.030
0.040

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

(SOURCE DOCUMENT: MS-1748 REV. 00)

FIGURE 3.9A-18

RRS OF ACC. PRIMARY CONT.
(ELEV 206.11 FT)

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SRV(ENV. OF ALL SRV CASES)


DAMPING VALUES = 0.010

0.020

0.030

0.040

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-I9


RRS OF ACC. PRIMARY CONT.
(ELEV 206.11 FT)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SRV(ENV. OF ALL SRV CASES)

DAMPING VALUES = 0.010
0.020
0.030
0.040

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF +15% AND -15%

FIGURE 3.9A-20


RRS OF ACC. SHIELD WALL OUT
(ELEV 315.23 FT)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SRV(ENV. OF ALL SRV CASES)

DAMPING VALUES = 0.010
0.020
0.030
0.040

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-21


RRS OF ACC. SHIELD WALL OUT
(ELEV 315.23 FT)

NIAGARA MOHAWK POWER CORPORATION,
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SRV(ENV. OF ALL SRV CASES)

DAMPING VALUES = 0.010
0.020
0.030
0.040

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A - 22


RRS OF ACC. RPV SHELL
(ELEV 315.08 FT)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SRV(ENV. OF ALL SRV CASES)

DAMPING VALUES = 0.010
0.020
0.030
0.040

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A - 23


RRS OF ACC. RPV SHELL
(ELEV 315.08 FT)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SRV(ENV. OF ALL SRV CASES)

DAMPING VALUES = 0.010
0.020
0.030
0.040

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-24


RRS OF ACC. SECONDARY CONT.
(ELEV 175) AT MAT

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SRV(ENV. OF ALL SRV CASES)

DAMPING VALUES = 0.010
0.020
0.030
0.040

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-25


RRS OF ACC. SECONDARY CONT.
(ELEV 175) AT MAT

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CHUGGING LOADING CASE

DAMPING VALUES = 0.020
0.030
0.040

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF +15% AND -15%

FIGURE 3.9A-26


RRS OF ACC. PRIMARY CONT.
(ELEV 206.11 FT)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CHUGGING LOADING CASE

DAMPING VALUES = 0.020
0.030
0.040

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A -27


RRS OF ACC. PRIMARY CONT.
(ELEV 206.11 FT)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CHUGGING LOADING CASE

DAMPING VALUES = 0.020
0.030
0.040

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-28


RRS OF ACC. SHIELD WALL OUT
(ELEV 315.23 FT)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CHUGGING LOADING CASE

DAMPING VALUES = 0.020
0.030
0.040

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A - 29

RRS OF ACC. SHIELD WALL OUT
(ELEV 315.23 FT)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT


CHUGGING LOADING CASE

DAMPING VALUES = 0.020

0.030

0.040

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A -30


RRS OF ACC. RPV SHELL
(ELEV 315.08 FT)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CHUGGING LOADING CASE

DAMPING VALUES = 0.020
0.030
0.040

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-31

RRS OF ACC. RPV SHELL
(ELEV 315.08 FT)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT


CHUGGING LOADING CASE

DAMPING VALUES = 0.020

0.030

0.040

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-32


RRS OF ACC. SECONDARY CONT.
(ELEV 175) AT MAT

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CHUGGING LOADING CASE

DAMPING VALUES = 0.020
0.030
0.040

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-33


RRS OF ACC. SECONDARY CONT.
(ELEV 175) AT MAT

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CONDENSATION OSCILLATION (CO1 OR BASIC)

DAMPING VALUES = 0.020
0.030
0.040

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A -34


RRS OF ACC. PRIMARY CONT.
(ELEV 206.11 FT)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CONDENSATION OSCILLATION
(CO1 OR BASIC)

DAMPING VALUES = 0.020
0.030
0.040

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

(SOURCE DOCUMENT: MS-1735 REV. 00)

FIGURE 3.9A-35


RRS OF ACC. PRIMARY CONT.
(ELEV 206.11 FT)

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CONDENSATION OSCILLATION
(CO1 OR BASIC)

DAMPING VALUES = 0.020
0.030
0.040

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

(SOURCE DOCUMENT: MS-1735 REV. 00)

FIGURE 3.9A-36


RRS OF ACC. SHIELD WALL OUT
(ELEV 315.23 FT)

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CONDENSATION OSCILLATION
(CO1 OR BASIC)

DAMPING VALUES = 0.020
0.030
0.040

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

(SOURCE DOCUMENT: MS-1735 REV. 00)

FIGURE 3.9A-37


RRS OF ACC. SHIELD WALL OUT
(ELEV 315.23 FT)

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CONDENSATION OSCILLATION
(CO1 OR BASIC)

DAMPING VALUES = 0.020
0.030
0.040

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

(SOURCE DOCUMENT: MS-1735 REV. 00)

FIGURE 3.9A-38


RRS OF ACC. RPV SHELL
(ELEV 315.08 FT)

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CONDENSATION OSCILLATION
(CO1 OR BASIC)

DAMPING VALUES = 0.020
0.030
0.040

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

(SOURCE DOCUMENT: MS-1735 REV. 00)

FIGURE 3.9A-39


RRS OF ACC. RPV SHELL
(ELEV 315.08 FT)

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CONDENSATION OSCILLATION
(CO1 OR BASIC)

DAMPING VALUES = 0.020
0.030
0.040

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

(SOURCE DOCUMENT: MS-1735 REV. 00)

FIGURE 3.9A-40


RRS OF ACC. SECONDARY CONT.
(ELEV 175) AT MAT

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CONDENSATION OSCILLATION
(CO1 OR BASIC)

DAMPING VALUES = 0.020
0.030
0.040

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

(SOURCE DOCUMENT: MS-1735 REV. 00)


FIGURE 3.9A-41

RRS OF ACC. SECONDARY CONT.
(ELEV 175) AT MAT

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CONDENSATION OSCILLATION
(CO2 OR ADS)

DAMPING VALUES = 0.020
0.030
0.040



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

(SOURCE DOCUMENT: MS-1736 REV. 00)

FIGURE 3.9A-42


RRS OF ACC. PRIMARY CONT.
(ELEV 206.11 FT)

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CONDENSATION OSCILLATION
(CO2 OR ADS)

DAMPING VALUES = 0.020
0.030
0.040

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

(SOURCE DOCUMENT: MS-1736 REV. 00)

FIGURE 3.9A-43


RRS OF ACC. PRIMARY CONT.
(ELEV 206.11 FT)

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CONDENSATION OSCILLATION
(CO2 OR ADS)

DAMPING VALUES = 0.020
0.030
0.040

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF +15% AND -15%

(SOURCE DOCUMENT: MS-1736 REV. 00)

FIGURE 3.9A-44


RRS OF ACC. SHIELD WALL OUT
(ELEV 315.23 FT)

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CONDENSATION OSCILLATION
(CO2 OR ADS)

DAMPING VALUES = 0.020
0.030
0.040

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

(SOURCE DOCUMENT: MS-1736 REV. 00)

FIGURE 3.9A-45


RRS OF ACC. SHIELD WALL OUT
(ELEV 315.23 FT)

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CONDENSATION OSCILLATION
(CO2 OR ADS)

DAMPING VALUES = 0.020
0.030
0.040

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

(SOURCE DOCUMENT: MS-1736 REV. 00)

FIGURE 3.9A-46


RRS OF ACC. RPV SHELL
(ELEV 315.08 FT)

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CONDENSATION OSCILLATION
(CO2 OR ADS)

DAMPING VALUES = 0.020
0.030
0.040

VER DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

(SOURCE DOCUMENT: MS-1736 REV. 00)

FIGURE 3.9A-47


RRS OF ACC. RPV SHELL
(ELEV 315.08 FT)

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CONDENSATION OSCILLATION
(CO2 OR ADS)

DAMPING VALUES = 0.020
0.030
0.040

HOR DIRECTION



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

(SOURCE DOCUMENT: MS-1736 REV. 00)

FIGURE 3.9A-48


RRS OF ACC. PRIMARY CONT.
(ELEV 176.0 FT) AT MAT

NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

CONDENSATION OSCILLATION
(CO2 OR ADS)

DAMPING VALUES = 0.020
0.030
0.040

VER DIRECTION




NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A - 49

RRS OF ACC. PRIMARY CONT.
(ELEV 176.0 FT) AT MAT

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (OBE)
DAMPING VALUE 2-5%
E-W DIRECTION (X AXIS)



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%


FIGURE 3.9A-50

ARS OF ACCELERATION
PRIMARY CONT. EL. 196.67 FT.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (OBE)

DAMPING VALUE 2-5%
VERT. DIRECTION (Y AXIS)




NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-51

ARS OF ACCELERATION
PRIMARY CONT. EL. 196.67 FT.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (OBE)
DAMPING VALUE 2-5%
N-S DIRECTION (Z AXIS)




NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-52

ARS OF ACCELERATION
PRIMARY CONT. EL. 196.67 FT.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (SSE)
DAMPING VALUE 2-5%
E-W DIRECTION (X AXIS)




NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND - 15%

FIGURE 3.9A-53

ARS OF ACCELERATION
PRIMARY CONT. EL. 196.67 FT.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (SSE)
DAMPING VALUE 2-5%
VERT. DIRECTION (Y AXIS)



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%


FIGURE 3.9A-54

ARS OF ACCELERATION
PRIMARY CONT. EL. 196.67 FT.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (SSE)

DAMPING VALUE 2-5%
N-S DIRECTION (Z AXIS)




NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-55

ARS OF ACCELERATION
PRIMARY CONT. EL. 196.67 FT.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (OBE)
DAMPING VALUE 2-5%
E-W DIRECTION (X AXIS)




NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-56

ARS OF ACCELERATION
SHIELD WALL EL. 315.09 FT.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (OBE)
DAMPING VALUE 2-5%
VERT. DIRECTION (Y AXIS)



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%


FIGURE 3.9A-57

ARS OF ACCELERATION
SHIELD WALL EL. 315.09 FT.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (OBE)

DAMPING VALUE 2-5%
N-S DIRECTION (Z AXIS)




NOTE: THESE CURVES REPRESENT A SPREAD OF +15% AND -15%

FIGURE 3.9A-58

ARS OF ACCELERATION
SHIELD WALL EL. 315.09 FT.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (SSE)
DAMPING VALUE 2-5%
E-W DIRECTION (X AXIS)



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%


FIGURE 3.9A-59

ARS OF ACCELERATION
SHIELD WALL EL. 315.09 FT .

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (SSE)

DAMPING VALUE 2-5%
VERT. DIRECTION (Y AXIS)




NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-60

ARS OF ACCELERATION
SHIELD WALL EL. 315.09 FT.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (SSE)
DAMPING VALUE 2-5%
N-S DIRECTION (Z AXIS)




NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-61

ARS OF ACCELERATION
SHIELD WALL EL. 315.09 FT .

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (OBE)
DAMPING VALUE 2-5%
E-W DIRECTION (X AXIS)




NOTE: THESE CURVES REPRESENT A SPREAD OF +15% AND -15%

FIGURE 3.9A-62

ARS OF ACCELERATION
RPV SHELL EL. 332.70 FT.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (OBE)
DAMPING VALUE 2-5%
VERT. DIRECTION (Y AXIS)




NOTE: THESE CURVES REPRESENT A SPREAD OF +15% AND -15%

FIGURE 3.9A-63

ARS OF ACCELERATION
RPV SHELL EL. 332.70 FT.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (OBE)
DAMPING VALUE 2-5%
N-S DIRECTION (Z AXIS)




NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-64

ARS OF ACCELERATION
RPV SHELL EL. 332.70 FT.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (SSE)
DAMPING VALUE 2-5%
E-W DIRECTION (X AXIS)




NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-65

ARS OF ACCELERATION
RPV SHELL EL. 332.70 FT.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (SSE)
DAMPING VALUE 2-5%
VERT. DIRECTION (Y AXIS)




NOTE: THESE CURVES REPRESENT A SPREAD OF +15% AND -15%

FIGURE 3.9A-66

ARS OF ACCELERATION
RPV SHELL EL. 332.70 FT.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT

SEISMIC (SSE)
DAMPING VALUE 2-5%
N-S DIRECTION (Z AXIS)



NOTE: THESE CURVES REPRESENT A SPREAD OF + 15% AND -15%

FIGURE 3.9A-67

ARS OF ACCELERATION
RPV SHELL EL. 332.70 FT.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT




FIGURE 3.9B-2

REACTOR INTERNALS FLOW PATHS
FOLLOWING A POSTULATED RECIRCULATION
LINE BREAK

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.9B-3

FUEL SUPPORT PIECES

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.9B-4

JET PUMP

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3.9B-5

PRESSURE NODES USED FOR
DEPRESSURIZATION ANALYSIS

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3A.1-1

TEN ELEMENT IDEALIZATION
OF THIN WALL CYLINDER

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3A.2-1

ELEMENT PLOT

NIAGARA MOHAWK POWER CORPORATION
 NINE MILE POINT-UNIT 2
 FINAL SAFETY ANALYSIS REPORT

70 6315




FIGURE 3A.2-2

HARMONIC AXISYMMETRIC
 PLANE STRAIN

NIAGARA MOHAWK POWER CORPORATION
 NINE MILE POINT-UNIT 2
 FINAL SAFETY ANALYSIS REPORT




FIGURE 3A. 3-1

TAC2D SAMPLE PROBLEM,
THERMAL MODEL

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT





FIGURE 3A.3-2

TRANSIENT TEMPERATURE IN A
RIGHT CIRCULAR CYLINDER
COMPARISON OF TAC2D RESULTS

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



$$M_0 = 1283 \text{ MAT } 6$$

$$1104 \text{ SHELL } 1$$

$$Q_0 = 136 \text{ MAT } 6$$

$$140 \text{ SHELL}$$

FIGURE 3A. 4-1

STRUCTURE CONFIGURATION AND
LOADING FOR MAT 6 VS SHELL 1

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3A. 4-2

COMPARISON OF RESULTS OF MAT 6
VS SHELL 1-MAT RADIAL MOMENT

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3A. 4-3

COMPARISON OF RESULTS OF MAT 6
VS SHELL 1-MAT TANGENTIAL MOMENT

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT





FIGURE 3A.4-4

COMPARISON OF RESULTS OF MAT 6
VS SHELL 1-MAT RADIAL SHEAR

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




MAX. ACCEL. -0.1017
AT TIME 2.150

FIGURE 3A.6-1

RESULTS OF TIME HISTORY PROGRAM
CONTAINMENT STRUCTURE-OPERATING
FLOOR LEVEL TIME HISTORY
OF STRUCTURAL RESPONSE

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




MAX ACCEL -0.1015
AT TIME 2.150

FIGURE 3A. 6-2

RESULTS OF STRUDL II ANALYSIS
CONTAINMENT STRUCTURE-
OPERATING FLOOR LEVEL TIME
HISTORY OF STRUCTURAL RESPONSE

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



PIPE MATERIAL: A106 STEEL.

NOTE:
NOT DRAWN TO SCALE.

FIGURE 3A.9-1

CANTILEVER PIPE
USED IN MIT EXPERIMENT

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT





FIGURE 3A.9-2

MIT EXPERIMENT
STRESS-STRAIN CURVES

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



NOTES:

$V_o = 1,400 \text{ IN/SEC}$

$W_o = 600 \text{ RAD/SEC}$

FIGURE 3A. 9-3

DINASAW AND LIMITA II
LUMPED MASS MODELS

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3A.9-4

TIME HISTORY PLOTS OF THE
X-DISPLACEMENT AT THE FREE END

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT





FIGURE 3A.9-5

TIME HISTORY PLOTS OF THE
Y-DISPLACEMENT AT THE FREE END

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




LEGEND:

----- DINASAW
————— LIMITA II

FIGURE 3A. 9-6

TIME HISTORY PLOTS OF THE MOMENT
REACTION AT THE CLAMPED END

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




LEGEND:

- EXPERIMENT
- DINASAW
- LIMITA II

FIGURE 3A. 9-7

PERMANENT PIPE DEFORMATION
FOR THE MIT EXPERIMENT

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



NOTE:
ALL MEMBERS W14 × 500




FIGURE 3A. 10-1

LIMITA III ELASTIC SPACE FRAME

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3A.10-2

LIMITA III DISPLACEMENT
TIME HISTORY AT JOINT 6

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT





FIGURE 3A. 10-3

LIMITA III TIME HISTORY OF MOMENT Z
IN MEMBER 5, JOINT 6

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



NOT TO SCALE

FIGURE 3A.10-4

STRUCTURE AND MODEL USED
FOR LIMITA3 ANALYSES

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT





FIGURE 3A.12-1

SSLAM SAMPLE PROBLEM
(ANNULAR POOL)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT



NOTES:

1. ACCELERATION (CM),
LIFT (CL), AND STANDARD (CD)
DRAG COEFFICIENTS-
CM-2.0, CL-1.0, CD-2.0

2. CENTRIDS OF BUBBLES ARE
LOCATED AT THE BASES
OF THE SUBMERGED
STRUCTURES

3. BUBBLES' SOURCE
STRENGTHS ARE,

	SDOT * (FT ³ /s)	SSDOT ** (FT ³ /s ²)
BUBBLE 1	50	300
BUBBLE 2	50	300

4. STRUCTURE (1) HAS SEGMENTS
1-3.

STRUCTURE (2) HAS SEGMENTS
4-6

ALL SEGMENTS HAVE THE
SAME LENGTH.

* SDOT = VOLUMETRIC FLOW RATE
OF SOURCE

** SSDOT = TIME DERIVATIVE OF
SDOT

FIGURE 3A.13-1

SSLOAD SAMPLE PROBLEM AND
INPUT DATA

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
UPDATED SAFETY ANALYSIS REPORT





FIGURE 3A.13-2

MODEL/DATA COMPARISON FOR C_M AND C_V

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT





FIGURE 3A. 14-1

NOMENCLATURE FOR
MISSILE PROGRAM

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



SOURCE:

BUSH S.H. PROBABILITY OF DAMAGE
TO NUCLEAR COMPONENTS DUE TO
TURBINE FAILURE.
NUCLEAR SAFETY, VOL 14, NO. 3
MAY-JUNE 1973.

FIGURE 3A. 14-2

TARGET FOR LOW
TRAJECTORY MISSILE

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT








FIGURE 3A. 15-1

MATHEMATICAL MODEL FOR FLEXIBILITY
ANALYSIS VERIFICATION

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



ASME BENCHMARK PROBLEM 5 MODEL

— K.M. VASHI'S RESULTS AS PRESENTED
IN "PRESSURE VESSEL AND PIPING, 1972
COMPUTER PROGRAM VERIFICATION",
ASME, 1972

--- NUPIPE RESULTS

⊕ NUPIPE RESULTS AT EQUIDISTANT INTERVAL

FIGURE 3A. 15-2

NUPIPE PROGRAM FORCE
TIME HISTORY VERIFICATION

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT





FIGURE 3A. 15-3

MATHEMATICAL MODEL FOR
SAFETY CLASS 1 STRESS VERIFICATION

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



$$E = 30 \times 10^6 \text{ psi}$$

$$\nu = 0.3$$

$$P = 0.000732$$




FIGURE 3A.18-1

SAMPLE PROBLEM NO. 2
FOR GHOSH-WILSON

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT





FIGURE 3A.18-2

COMPARISON OF RESULTS FROM
GHOSH AND ANSYS FOR A CYLINDER
SUBJECTED TO A SUDDENLY APPLIED LOAD

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



CASE (A) FOR COMPARISON WITH ANALYTICAL RESULTS

INITIAL CONDITIONS =

$$p_1/p_0 = 4.72, \alpha_0/\alpha_1 = 0.80$$

DIMENSIONS =

$$A_0/A_1 = 0.6, L = \text{PIPE LENGTH}$$

SPECIFIC HEAT RATIO =


$$\gamma = C_p/C_v = 1.4$$

p = PRESSURE, α = SOUND VELOCITY, A = FLOW AREA

FIGURE 3A. 20-1

SUDDEN DISCHARGE OF GAS FROM
A PIPELINE THROUGH A NOZZLE
(CASE A)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



CASE (B) FOR COMPARISON WITH EXPERIMENTAL DATA
AND HAND CALCULATION

PRESSURE = $p_0 = 14.7$ psia, $p_1 = 14.7/0.229 = 64.2$ psia

AREA = $A_1 = \frac{\pi}{4} (0.25)^2 = 0.0491$ ft², $A_2 = 0.25A_1 = 0.0123$ ft²

GAS CONSTANT = $R = 53.35$ ft - lb_f / lb^oR


TEMPERATURE = $T_0 = 79^\circ\text{F} = 539^\circ\text{R}$, $T_1 = T_0$

DENSITY = $\rho_0 = \frac{p_0}{RT_0} = 0.0736$ lb/ft³, $\rho_1 = \frac{p_1}{RT_1} = 0.3215$ lb/ft³

FIGURE 3A. 20-2

SUDDEN DISCHARGE OF GAS FROM
A PIPELINE THROUGH A NOZZLE
(CASE B)

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




LEGEND

- (CASE A)
 — STEHAM
 - - - ANALYTICAL SOLUTION (REF 4 & 5)

FIGURE 3A. 20-3

COMPARISON OF PRESSURE RESPONSE
AT THE CLOSED END

NIAGARA MOHAWK POWER CORPORATION
 NINE MILE POINT-UNIT 2
 FINAL SAFETY ANALYSIS REPORT



LEGEND

(CASE A)


- STEHAM
- - - ANALYTICAL SOLUTION
(REF 4 & 5)

TIME ($\alpha_1 t/L$)

FIGURE 3A.20-4

COMPARISON OF PRESSURE RESPONSE
AT THE OPEN END

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



LEGEND :

(CASE B)

— STEHAM

- - - ANALYTICAL SOLUTION (REF 4&5)

FIGURE 3A. 20-5

COMPARISON OF PRESSURE RESPONSES
BY STEHAM AND EXPERIMENT

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT





FIGURE 3A. 21-1

HYDRAULIC NETWORK FOR
VERIFICATION PROBLEM

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



LEGEND

- (5) PIPE NUMBER
- (J1) PIPE JUNCTION
- 5 NODE NUMBER
- X— VALVE

FIGURE 3A. 21-2

HYDRAULIC NETWORK FOR
WATHAM VERIFICATION

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3A. 21-3

HEAD-VERSUS-TIME PLOT
FOR JUNCTION J

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3A. 21-4

HEAD-VERSUS-TIME PLOT AT VALVE

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3A. 24-1

RCIC PIPING SYSTEM USED IN THE
ANALYSIS OF WATER HAMMER LOADS

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3A. 24-2

TRANSIENT FORCE BY WATAIR
IN PIPE SEGMENT 14

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT





FIGURE 3A. 24-3

TRANSIENT FORCE BY WATHAM
IN PIPE SEGMENT 14

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT



PROPRIETARY

FIGURE 3A.26-1

4TCO TEST DATA FOR CHUG 30

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT

AMENDMENT 3

JUNE 1983







FIGURE 3A.26-2


CALCULATED PRESSURE TIME HISTORY
OF CHUG 30 USING CWL


NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT












NOTES:


→ : DIRECTION OF VENT FLOW


FIGURE 3B-1


NODALIZATION DIAGRAM - REACTOR
BUILDING HIGH-ENERGY LINE BREAK
ANALYSIS (45 NODE MODEL)
SHEET 5 OF 5


NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT














Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-3

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 175-1. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-4

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 175-2. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



TIME AFTER ACCIDENT (SECONDS)

Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-5

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 175-3. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



TIME AFTER ACCIDENT (SECONDS)

Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-6

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 175-4. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



TIME AFTER ACCIDENT (SECONDS)

Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-7

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 175-5. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-8

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 175-6, SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



TIME AFTER ACCIDENT (SECONDS)

Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-9

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 175-7, SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-10

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 175-8. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial 'cold' water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-11

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 175-9. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial 'cold' water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-12

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 175-10. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



TIME AFTER ACCIDENT (SECONDS)

Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-13

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 175-11. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial 'cold' water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-14

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 215-1. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-15

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 215-2. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



TIME AFTER ACCIDENT (SECONDS)

Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial 'cold' water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-16

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 215-3. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-17

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 215-4. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



TIME AFTER ACCIDENT (SECONDS)

Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial 'cold' water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-18

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 215-5. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-19

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 215-6. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-20

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 215-7. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-21

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 215-8, SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



TIME AFTER ACCIDENT (SECONDS)

Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-22

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 215-9. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial 'cold' water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-23

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 215-10. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-24

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 240-1. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-25

ABSOLUTE PRESSURE TRANSIENTS;
VOLUME 240-2. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial 'cold' water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-26

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 240-3. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 38.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-27

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 240-4. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



TIME AFTER ACCIDENT (SECONDS)

Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-28

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 240-5. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 38.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-29

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 240-6. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial 'cold' water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-30

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 240-7, SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial 'cold' water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-31

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 240-8. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial 'cold' water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-32

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 261-1. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-33

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 261-2. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



TIME AFTER ACCIDENT (SECONDS)

Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial 'cold' water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-34

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 261-3. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



TIME AFTER ACCIDENT (SECONDS)

Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial 'cold' water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-35

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 261-4. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



TIME AFTER ACCIDENT (SECONDS)

Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-36

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 261-5. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



TIME AFTER ACCIDENT (SECONDS)

Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-37

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 289-1. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-38

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 289-2. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-39

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 289-3. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial 'cold' water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-40

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 306-1. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial 'cold' water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-41

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 306-2, SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



TIME AFTER ACCIDENT (SECONDS)

Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-42

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 306-3. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-43

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 306-4. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial 'cold' water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-44

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 306-5. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial 'cold' water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-45

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 328-1. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-46

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 328-2. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



TIME AFTER ACCIDENT (SECONDS)

Note: Break numbers 34 and 35 are shown on this figure.


Add 13.40 seconds to these plots to account for the initial "cold" water blowdown (see USAR Section 3B.1: Design Bases).

Volume SC328190 is used only in the 46 node model.

FIGURE 3B-47

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME SC328190. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



Note: All breaks are shown on this figure.


Add 13.40 seconds to the plots of break numbers 34 and 35 to account for the initial 'cold' water blowdown (see USAR Section 3B.1: Design Bases).

Break numbers 34 and 35 are the plots that extend past 100 seconds.

FIGURE 3B-48

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME 353-1. SECONDARY
CONTAINMENT HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



○ JUNCTION *'S

NOTE: NODES MST-5 AND MST-6
ARE KNOWN AS MAIN STEAM
LINE TUNNEL LEAD ENCLOSURE


FIGURE 3B-49

NODALIZATION DIAGRAM
MAIN STEAM TUNNEL
HIGH ENERGY LINE BREAK ANALYSIS



ExelonGeneration.

NINE MILE POINT
NUCLEAR STATION - UNIT 2
SCRIBA, N.Y.




Note: All breaks are shown on this figure.

FIGURE 3B-50

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME MST-1. MAIN STEAM
TUNNEL HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT




Note: All breaks are shown on this figure.

FIGURE 3B-51

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME MST-2. MAIN STEAM
TUNNEL HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT




Note: All breaks are shown on this figure.

FIGURE 3B-52

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME MST-3. MAIN STEAM
TUNNEL HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT




Note: All breaks are shown on this figure.

FIGURE 3B-53

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME MST-4. MAIN STEAM
TUNNEL HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT




TIME AFTER ACCIDENT (SECONDS)

Note: All breaks are shown on this figure.

FIGURE 3B-54

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME MST-5. MAIN STEAM
TUNNEL HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT




Note: All breaks are shown on this figure.

FIGURE 3B-55

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME MST-6. MAIN STEAM
TUNNEL HELB ANALYSIS.

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT




Note: All breaks are shown on this figure.


FIGURE 3B-56

ABSOLUTE PRESSURE TRANSIENTS:
VOLUME MST-8. MAIN STEAM
TUNNEL HELB ANALYSIS.


NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
UPDATED SAFETY ANALYSIS REPORT



CIRCUMFERENTIAL BREAK WITH FULL SEPARATION



LONGITUDINAL BREAK



FLUID JET GEOMETRY
SATURATED WATER AND STEAM BLOWDOWN

NOTE:

REGION 1 EXTENDS FROM THE BREAK TO THE ASYMPTOTIC EXPANSION PLAN. THE DISTANCE TO THE ASYMPTOTIC PLAN IS A FUNCTION OF FLUID PROPERTIES. WITH $P_0 = 1050$ psia AND $H/D = 0$. MOODY FOUND THAT THIS JET ASYMPTOTIC DISTANCE IS 4.5 DISCHARGE PIPE DIAMETERS FOR SATURATED WATER BLOWDOWN, AND 2 PIPE DIAMETERS FOR SATURATED STEAM BLOWDOWN. FALETTI'S DATA FOR THE CRITICAL DISCHARGE OF STEAM-WATER MIXTURES INDICATE THAT FULLY EXPANDED PROPERTIES ARE APPROACHED CLOSELY IN LESS THAN 5 PIPE DIAMETERS. THEREFORE, THE EXTENT OF REGION 1 IS TAKEN AS 5 PIPE INSIDE DIAMETERS.

IN REGION 2, THE JET IS ASSUMED TO REMAIN CONSTANT.


IN REGION 3, INTERACTION WITH THE SURROUNDING ENVIRONMENT IS ASSUMED TO START AND THE JET EXPANDS AT A HALF ANGLE OF 10 DEGREES.

FIGURE 3C.3-1

JET GEOMETRY

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT

FLAT PLATE DESIGN



WEDGE DESIGN




FIGURE 3C.3-2

JET IMPINGEMENT
TARGET SHIELDS

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT-UNIT 2
FINAL SAFETY ANALYSIS REPORT




FIGURE 3C.3-3

SOURCE SHIELD

NIAGARA MOHAWK POWER CORPORATION
 NINE MILE POINT-UNIT 2
 FINAL SAFETY ANALYSIS REPORT