



Materials Inspection Report

1. Licensee/Location Inspected:

Corewell Health Trenton Hospital
5450 Fort St.
Trenton, MI 48183

Report Number(s) 2026-001

2. NRC/Regional Office

Region III
U. S. Nuclear Regulatory Commission
2056 Westings Avenue, Suite 400
Naperville, IL 60563-2657

3. Docket Number(s)

030-11427

4. License Number(s)

21-16656-01

5. Date(s) of Inspection

8/27/2026

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☒ 2. Previous violation(s) closed.
- ☐ 3. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements, and were assessed at Severity Level IV, in accordance with the NRC Enforcement Policy.
- A. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy were satisfied.
(Non-cited violation(s) was/were discussed involving the following requirement(s))
- B. The following violation(s) is/are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE AND DATE
LICENSEE'S REPRESENTATIVE		
NRC INSPECTOR	Luis Nieves	LUIS NIEVES FOLCH Digitally signed by LUIS NIEVES FOLCH Date: 2026.09.15 13:37:22 -05'00'
BRANCH CHIEF	Rhex Edwards	 Digitally signed by RHEX EDWARDS Date: 2026.09.17 08:59:02 -05'00'



Materials Inspection Record

1. Licensee Name: Corewell Health Trenton Hospital		2. Docket Number(s): 030-11427		3. License Number(s) 21-16656-01	
4. Report Number(s): 2026001			5. Date(s) of Inspection: 8/27/2026		
6. Inspector(s): Luis Nieves		7. Program Code(s): 02120		8. Priority: 3	9. Inspection Guidance Used: IP 87130
10. Licensee Contact Name(s): Katie Baker, RT, Manager, Imaging Services		11. Licensee E-mail Address: katie.baker@corewellhealth.org		12. Licensee Telephone Number(s): 734-642-2577	
13. Inspection Type: ☐ Routine ☐ Announced ☒ Non-Routine ☒ Unannounced		14. Locations Inspected: ☐ Hybrid ☒ Main Office ☐ Field Office ☐ Temporary Job Site ☐ Remote		15. Next Inspection Date (MM/DD/YYYY): 09/13/2027 ☐ Normal ☐ Extended ☐ Reduced ☒ No change	
16. Location(s) Inspected List: 5450 Fort St., Trenton, Michigan, 48183					
17. Scope and Observations: This was an enforcement follow-up inspection regarding one SLIII violation cited in Inspection Report No. 03011427/2024001. The licensee was cited for failing to secure from unauthorized removal or access licensed material that was stored in a controlled area. Specifically, the licensee left the door of its nuclear medicine hot lab unlocked which allowed access to 0.072 millicuries (mCi) of barium-133, 3.853 mCi of cobalt-57, 7.434 mCi of gadolinium-153, 0.135 mCi of cesium-137, 0.00037 mCi of europium-152, and 463.33 mCi of technetium-99m. The licensee changed the door handle and locking system within 24 hours of the violation being identified. The inspector toured the hot lab and verified that the door lock system had been changed. The new door lock system did not have any buttons on the side of the door to inadvertently lock or unlock the door. The violation has not occurred again since and is closed. No other violations of NRC requirements were identified during this inspection.					
Signature and Date - Branch Chief  Digitally signed by RHEX EDWARDS Date: 2026.09.17 08:58:27 -05'00'					