



Materials Inspection Report

1. Licensee/Location Inspected:

Meadows Stone & Paving, Inc.
80 WV Forest Products Road
CORPORATE HEADQUARTERS
GASSAWAY, WV 26624

2. NRC/Regional Office

Office of Nuclear Material Safety and Safeguards
Division of Federal Materials Programs
Inspection and Licensing Branch East

Report Number(s) 2026001

3. Docket Number(s)

030-12967

4. License Number(s)

47-17562-01

5. Date(s) of Inspection

07/22/2026 - 09/15/2026

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☐ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☒ 3. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements, and were assessed at Severity Level IV, in accordance with the NRC Enforcement Policy.

A. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy were satisfied. (Non-cited violation(s) was/were discussed involving the following requirement(s))

B. The following violation(s) is/are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

10 CFR 71.5(a) requires, in part, that a licensee who transports licensed material outside the site of usage, as specified in the NRC licensee, or where transport is on the public highways, or who delivers licensed material to a carrier for transport, shall comply with the applicable requirements of the DOT regulations in 49 CFR parts 107, 171 through 180, and 390 through 397, appropriate for the mode of transport.

Contrary to the above, the licensee did not maintain current DOT Hazmat training for one individual involved in the transportation of hazardous materials. Specifically, the licensee had not conducted the required training for an authorized user who had transported a device over very sporadic isolated instances since the last inspection whose training exceeded a three year period.

This was determined to be a repeated SLIV violation from December 13, 2016 (NRC Enforcement Policy 6.3.d.4) that was not closed during the last inspection. To correct this issue, the licensee has instructed the authorized user to not transport the gauge and will not allow the authorized user to transport licensed material until the authorized user has completed the required training. As a preventative measure, the licensee will use software to ensure reminders are sent to management and authorized users to complete the required training before it expires.

License Condition 14.A of NRC License 47-17562-01, Amendment No. 9, dated May 11, 2023, requires, in part, that sealed sources shall be tested for leakage and/or contamination at intervals not to exceed the intervals specified in the registration issued by the U.S. Nuclear Regulatory Commission under 10 CFR 32.210.

Contrary to the above, from Sept 9, 2025, to July 31, 2026, the licensee failed to have a sealed source tested for leakage and/or contamination at intervals not to exceed the intervals specified in the registration issued by the U.S. Nuclear Regulatory Commission under 10 CFR 32.210. Specifically, the licensee's Troxler Model 3400 series is required to be leak tested every 12 months according to the U.S. Nuclear Regulatory Commission's Sealed Source and Device Registry. The device was last tested for leakage and/or contamination on Sept 9, 2024, indicating the device was outside its authorized 12-month leak test cycle.

This was determined to be a SLIV violation (NRC Enforcement Policy 6.3.d.3). The licensee sent out the device for a leak test on July 31, 2026, and the results obtained on August 20, 2026 were negative. As a preventative measure, the licensee will set up a reminder system using electronic software to notify them before leak tests become overdue.



Materials Inspection Report (Continued)

1. Licensee/Location Inspected:

Meadows Stone & Paving, Inc.
80 WV Forest Products Road
CORPORATE HEADQUARTERS
GASSAWAY, WV 26624

2. NRC/Regional Office

Office of Nuclear Material Safety and Safeguards
Division of Federal Materials Programs
Inspection and Licensing Branch East

Report Number(s) 2026001

3. Docket Number(s)

030-12967

4. License Number(s)

47-17562-01

5. Date(s) of Inspection

07/22/2026 - 09/15/2026

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE AND DATE
LICENSEE'S REPRESENTATIVE	Charles Meadows	 9-22-26
NRC INSPECTOR	John Scott	JOHN SCOTT Digitally signed by JOHN SCOTT Date: 2026.09.21 16:41:42 -04'00'
BRANCH CHIEF	Monica Ford	MONICA FORD Digitally signed by MONICA FORD Date: 2026.09.23 09:19:20 -04'00'