

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 24

National Average: 46

2x National Average: 92

National Median: 23

Average for Selected Dockets: 24

Facility Name: Limerick 2 Docket (050- 00353)

Details	Department	Work Type	Docket/Report
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	H - Health Physics	H - Health Physics	050-00353/2009-003
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
<hr/>			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	M - Mechanical	M - Maintenance / Repair	050-00353/2008-005
113 - Procedure / reference document development and maintenance L	M - Mechanical	M - Maintenance / Repair	050-00353/2008-005
113 - Procedure / reference document development and maintenance L	E - Electrical	M - Maintenance / Repair	050-00353/2009-004
Number of Items for this Docket: 3			
Percent of Total for this Docket: 13			
<hr/>			
Problem Identification & Resolution / IR			
141 - Problem not properly classified or prioritized	M - Mechanical	M - Maintenance / Repair	050-00353/2009-003
141 - Problem not properly classified or prioritized	H - Health Physics	H - Health Physics	050-00353/2009-003
142 - Operating experience (OE) review LTA	E - Electrical	M - Maintenance / Repair	050-00353/2009-004
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00353/2009-003
146 - Evaluation LTA	G - Engineering	S - Surveillance	050-00353/2009-006
147 - Individual corrective action LTA	E - Electrical	M - Maintenance / Repair	050-00353/2009-004
148 - Action not yet started or untimely	M - Mechanical	M - Maintenance / Repair	050-00353/2009-003
148 - Action not yet started or untimely	E - Electrical	M - Maintenance / Repair	050-00353/2009-004
148 - Action not yet started or untimely	G - Engineering	G - Design	050-00353/2009-003
148 - Action not yet started or untimely	G - Engineering	G - Design	050-00353/2009-003
Number of Items for this Docket: 10			
Percent of Total for this Docket: 42			
<hr/>			
Work Planning & Practices / IR			
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00353/2008-005
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00353/2008-005
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00353/2008-005
185 - Procedural adherence LTA	E - Electrical	T - Testing	050-00353/2008-005
186 - Failure to take action / meet requirements	M - Mechanical	M - Maintenance / Repair	050-00353/2009-003
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00353/2009-004
186 - Failure to take action / meet requirements	O - Operations	O - Control Room Ops	050-00353/2009-003
186 - Failure to take action / meet requirements	H - Health Physics	H - Health Physics	050-00353/2009-003
187 - Action implementation LTA	E - Electrical	G - Design	050-00353/2009-006

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 24
National Average: 46
2x National Average: 92
National Median: 23
Average for Selected Dockets: 24

Facility Name: Limerick 2 Docket (050- 00353)

Details

Work Planning & Practices / IR

189 - Recognition of adverse condition / questioning attitude LTA

Department

O - Operations

Work Type

O - Control Room Ops

Docket/Report

050-00353/2009-003

Number of Items for this Docket: 10

Percent of Total for this Docket: 42

Total Items for this Docket: 24
