

Part 21 (PAR)

Event # 50507

Rep Org: AREVA INC.	Notification Date / Time: 10/03/2014 16:48 (EDT)
Supplier: AREVA INC.	Event Date / Time: 08/28/2014 (PDT)
	Last Modification: 10/03/2014
Region: 4	Docket #:
City: RICHLAND	Agreement State: Yes
County:	License #:
State: WA	
NRC Notified by: ALAN B. MEGINNIS	Notifications: STEVEN VIAS R2DO
HQ Ops Officer: DONG HWA PARK	JACK WHITTEN R4DO
Emergency Class: NON EMERGENCY	PART 21 GROUP EMAIL
10 CFR Section: 21.21(d)(3)(i) DEFECTS AND NONCOMPLIANCE	

PART 21 - DEFECT IN THE INPUT TO CALCULATE THERMAL LIMITS

The following was received via email by Areva Inc.:

"(i) Name and address of the individual or individuals informing the Commission.
Alan B. Meginnis, AREVA Inc., 2101 Horn Rapids Road, Richland, WA 99354.

"(ii) Identification of the facility, the activity, or the basic component supplied for such facility or such activity within the United States which fails to comply or contains a defect.

The defect is in the input to a program that calculates the minimum critical power ratio (MCPR) and linear heat generation rate (LHGR) thermal limits for Browns Ferry Unit 2 Cycle 18.

"(iii) Identification of the firm constructing the facility or supplying the basic component which fails to comply or contains a defect.
AREVA Inc.

"(iv) Nature of the defect or failure to comply and the safety hazard which is created or could be created by such defect or failure to comply.

This issue is a defect as defined in 10 CFR 21.3. The error is an omission in the POWERPLEX core monitoring software system input that could result in the application of non-conservative nuclear fuel operating thermal limits when the reactor is operated at 25 to 30% power. In the event of an abnormal operational occurrence while operating in this power range, a fuel thermal safety limit could be exceeded.

"(v) The date on which the information of such defect or failure to comply was obtained.
August 28, 2014

*IE19
MRL*

"(vi) In the case of a basic component which contains a defect or fails to comply, the number and location of these components in use at, supplied for, being supplied for, or may be supplied for, manufactured, or being manufactured for one or more facilities or activities subject to the regulations in this part. The defect exists only for Browns Ferry Unit 2 Cycle 18.

"(vii) The corrective action which has been, is being, or will be taken; the name of the individual or organization responsible for the action; and the length of time that has been or will be taken to complete the action. AREVA Inc. recommended plant operations be restricted to provide enough margin to the MCPR and LHGR thermal limits anytime power is in the range $25\% < P < 30\%$. AREVA has also provided revised POWERPLEX input to TVA for Browns Ferry Unit 2 Cycle 18 to correct the error permanently.

"(viii) Any advice related to the defect or failure to comply about the facility, activity, or basic component that has been, is being, or will be given to purchasers or licensees. This defect only had the potential to exceed the safety limit minimum critical power ratio (SLMCPR) and/or one of the Specified Acceptable Fuel Design Limits if an AOO [anticipated operational occurrence] occurred during the brief periods the plant was at power levels in the range $25\% < P < 30\%$ during Cycle 18. The plant has not had any such events in Cycle 18. The identified defect is a human performance error impacting only Browns Ferry Unit 2 Cycle 18. It does not affect other operating cycles, Browns Ferry Units, or other nuclear plants."



AREVA Inc.

FAX

To: NRC Operations Center

Date: 10/3/2014 Time in: 4:48 PM

Pages to follow: 2

Company: U.S. NRC

From: Alan B. Meginnis

Telephone: 509-375-8266 MB: 36

Original to be mailed Via fax only

Receiving fax: 301-816-5151

Sending fax: 434-382-5541

Telephone: 301-816-5100

Fax verification: 509-375-8266

Extra Distribution to:

Message:

Please see attached defect notice

AREVA Inc.
 2101 Horn Rapids Road
 Richland, WA 99354-5102
 Telephone: (509) 375-8100

Operator: _____
 Log No.: _____ Time Sent: _____

Reportable Defect

(i) Name and address of the individual or individuals informing the Commission.

Alan B. Meginnis, AREVA Inc., 2101 Horn Rapids Road, Richland, WA 99354.

(ii) Identification of the facility, the activity, or the basic component supplied for such facility or such activity within the United States which fails to comply or contains a defect.

The defect is in the input to a program that calculates the minimum critical power ratio (MCPR) and linear heat generation rate (LHGR) thermal limits for Browns Ferry Unit 2 Cycle 18.

(iii) Identification of the firm constructing the facility or supplying the basic component which fails to comply or contains a defect.

AREVA Inc.

(iv) Nature of the defect or failure to comply and the safety hazard which is created or could be created by such defect or failure to comply.

This issue is a defect as defined in 10 CFR 21.3.

The error is an omission in the POWERPLEX core monitoring software system input that could result in the application of non-conservative nuclear fuel operating thermal limits when the reactor is operated at 25 to 30% power. In the event of an abnormal operational occurrence while operating in this power range, a fuel thermal safety limit could be exceeded.

(v) The date on which the information of such defect or failure to comply was obtained.

August 28, 2014

(vi) In the case of a basic component which contains a defect or fails to comply, the number and location of these components in use at, supplied for, being supplied for, or may be supplied for, manufactured, or being manufactured for one or more facilities or activities subject to the regulations in this part.

The defect exists only for Browns Ferry Unit 2 Cycle 18.

(vii) The corrective action which has been, is being, or will be taken; the name of the individual or organization responsible for the action; and the length of time that has been or will be taken to complete the action.

AREVA Inc. recommended plant operations be restricted to provide enough margin to the MCPR and LHGR thermal limits anytime power is in the range $25\% \leq P < 30\%$. AREVA has also provided revised POWERPLEX input to TVA for Browns Ferry Unit 2 Cycle 18 to correct the error permanently.

(viii) Any advice related to the defect or failure to comply about the facility, activity, or basic component that has been, is being, or will be given to purchasers or licensees.

This defect only had the potential to exceed the safety limit minimum critical power ratio (SLMCPR) and/or one of the Specified Acceptable Fuel Design Limits if an AOO occurred during the brief periods the plant was at power levels in the range $25\% < P < 30\%$ during Cycle 18. The plant has not had any such events in Cycle 18.

The Identified defect is a human performance error impacting only Browns Ferry Unit 2 Cycle 18. It does not affect other operating cycles, Browns Ferry Units, or other nuclear plants.