

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 18

National Average: 41

2x National Average: 82

National Median: 24

Average for Selected Dockets: 18

Facility Name: Davis-Besse Docket (050- 00346)

Details	Department	Work Type	Docket/Report
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	O - Operations	O - Control Room Ops	050-00346/2007-002
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
<hr/>			
Oversight / IR			
130 - Inadequate suprevison / command and control	I - Instrumentation & Control	S - Surveillance	050-00346/2007-003
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
<hr/>			
Problem Identification & Resolution / IR			
140 - Problem not completely or accurately identified	O - Operations	B - Bal of Plant Ops	050-00346/2007-004
141 - Problem not properly classified or prioritized	M - Mechanical	M - Maintenance / Repair	050-00346/2007-004
Number of Items for this Docket: 2			
Percent of Total for this Docket: 11			
<hr/>			
Training / IR			
103 - Simulator training LTA	O - Operations	T - Testing	050-00346/2007-002
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
<hr/>			
Work Planning & Practices / IR			
185 - Procedural adherence LTA	I - Instrumentation & Control	M - Maintenance / Repair	050-00346/2007-004
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00346/2007-002
186 - Failure to take action / meet requirements	D - Emergency Planning	D - Emergency Drill	050-00346/2007-003
186 - Failure to take action / meet requirements	I - Instrumentation & Control	S - Surveillance	050-00346/2007-003
186 - Failure to take action / meet requirements	O - Operations	S - Surveillance	050-00346/2007-003
187 - Action implementation LTA	G - Engineering	G - Design	050-00346/2007-004
194 - Housekeeping LTA	D - Emergency Planning	Q - Fire Protection	050-00346/2007-002
196 - Independent verification / plant tours LTA	I - Instrumentation & Control	S - Surveillance	050-00346/2007-003
197 - Self-check LTA	G - Engineering	G - Design	050-00346/2007-004
197 - Self-check LTA	I - Instrumentation & Control	M - Maintenance / Repair	050-00346/2007-004
Number of Items for this Docket: 10			
Percent of Total for this Docket: 56			

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 18
National Average: 41
2x National Average: 82
National Median: 24
Average for Selected Dockets: 18

Facility Name: Davis-Besse Docket (050- 00346)

Details	Department	Work Type	Docket/Report
Procedures & Reference Document / LER			
111 - Procedure / reference document technical content	I - Instrumentation & Control	T - Testing	050-00346/2007-001-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 6			
Work Planning & Practices / LER			
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	V - Troubleshooting	050-00346/2007-001-00
190 - Failure to stop work / non-conservative decision making	O - Operations	V - Troubleshooting	050-00346/2007-001-00
Number of Items for this Docket: 2			
Percent of Total for this Docket: 11			
Total Items for this Docket: 18			