

AUG 2 0 2004 LR-N04-0377

United States Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

~ °

10CFR21 INTERIM REPORT, Re: Fisher Controls 10CFR Part 21 Information Notice FIN 2004-02, Fisher Pneumatic Instrument Relays with Nitrile Elastomer Diaphragms
SALEM GENERATING STATION UNITS 1 AND 2
FACILITY OPERATING LICENSE NO. DPR-70 AND DPR-75
DOCKET NOS. 50-272 AND 311

Pursuant to the notification requirements of 10CFR21.21(b), PSEG Nuclear LLC (PSEG) hereby provides this interim report concerning a failure to evaluate within 60-days a Part-21.21(b) report received from Fisher Controls. The subject report, FIN 2004-02, "Fisher Pneumatic Instrument Relays with Nitrile Elastomer Diaphragms" was issued on June 23, 2004. Our evaluation of the Fisher Controls Information Notice will not be completed within the 60-day period. The evaluation of this document will be complete by October 15, 2004.

Should you have any questions regarding this submittal, please contact K. Myers at (856) 339-2328.

Sincerely,

Steven R. Mannon

Sh Cz

Manager - Nuclear Safety & Licensing

IE19

C Mr. S. Collins, Administrator - Region I U. S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406

> Mr. G. Wunder Licensing Project Manager - Salem U. S. Nuclear Regulatory Commission One White Flint North Mail Stop 08B1A 11555 Rockville Pike Rockville, MD 20852

USNRC Senior Resident Inspector - Salem (X24)

Mr. K. Tosch, Manager IV Bureau of Nuclear Engineering P. O. Box 415 Trenton, NJ 08625