## November 10, 2005

## PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE -- PNO-III-05-015

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by the Region III staff on this date.

Facility	
D. C. Cook Unit 2	Licensee Emergency Classification
Inidana Michigan Power Company	Notification of Unusual Event
Bridgman, MI	Alert
Docket: 50-316	Site Area Emergency
License: DPR-74	General Emergency
	X Not Applicable

## SUBJECT: SPECIAL INSPECTION OF ELECTRICAL PROBLEMS AFTER REACTOR TRIP

DESCRIPTION:

Equility

At 3:58 a.m. EST on November 8, 2005, the Unit 2 reactor automatically tripped due to a reactor coolant pump bus undervoltage condition, initiated by a failure on the main generator. Following the reactor trip, two emergency diesel generator output circuit breakers failed to function correctly, which affected power to one train of safety-related plant equipment.

A special inspection team including the senior resident inspector and two region-based inspectors is reviewing the event. The team began its on-site review the morning of November 9, 2005.

The State of Michigan has been informed of this event. Region III issued a news release on the special inspection. The information in this preliminary notification has been reviewed by licensee management. The plant safely shut down and remains in a safe, stable condition.

This event was reported to the NRC Operations Center at 7:10 a.m. EST on November 8, 2005. This information is current as of 10:00 a.m. on November 10, 2005.

CONTACTS:

Frances Ramírez (630)-829-9607

Christine Lipa (630)-829-9619