<u>11/24/2014</u>

U.S. Nuclear Regulatory Commission Operations Center Event Report

<u>Page 1</u>

Part 21 (PAR)			Event	# 50623
	HNOLOGY FOR ENERGY CORP. HNOLOGY FOR ENERGY CORP.	Eve	ion Date / Time: 11/18/2014 ent Date / Time: 11/18/2014	15:09 (EST) (EST)
Region: 1 City: KNO County: State: TN	XVILLE A	La: Docket #: greement State: License #:	st Modification: 11/24/2014 Yes	
HQ Ops Offic	by: DONNA MULLALY er: DANIEL MILLS ss: NON EMERGENCY on: DEFECTS AND NONCOMPLIAN		TODD JACKSON FRANK EHRHARDT HIRONORI PETERSON BOB HAGAR PART 21 GROUP	R1DO R2DO R3DO R4DO EMAIL

PART 21 - LACK OF PROPER POWER SUPPLY INDICATION

The following information was summarized from the report obtained from the vendor via facsimile:

Technology for Energy Corporation [TEC] has determined that the Model 1414 Valve Flow Monitoring Systems power supply may not provide proper output voltage contrary to power supply status indicators on the rack. This may result in the power supply not providing necessary power to its associated input sensor. A subsequent loss of the sensor output would result in the inability of the system to indicate any valve flow. Depending on the specific configuration, signals from more than one sensor could be lost on a single failure.

This Model 1414 system design dates back to 1979. TEC has not been made aware of any instances of the described failure mode in the 35 year history of the product design, suggesting that the robustness of power supply design and the users periodic maintenance of the system has provided for acceptable continued operation.

The potentially affected plants include Clinton Unit 1; Comanche Peak Units 1 & 2; Nine Mile Point Unit 2; Palo Verde Units 1, 2, & 3; River Bend Unit 1; Susquehanna Units 1 & 2; Watts Bar Units 1 & 2.

*** UPDATED FROM DONNA MULLALY TO DONALD NORWOOD AT 1329 EST ON 11/24/2014 ***

After submitting the original Part 21 notification, TEC discovered that Columbia Generating Station had been omitted from the list of affected plants.

"The following correction should be applied: The potentially affected plants include Clinton Unit 1; Columbia Generating Station, Comanche Peak Units 1 & 2; Nine Mile Point Unit 2; Palo Verde Units 1, 2, & 3; River Bend

IE14

Unit 1; Susquehanna Units 1 & 2; and Watts Bar Units 1 & 2."

Notified R4DO (Campbell). Notified via E-mail R1DO (Noggle), R2DO (Ehrhardt), R3DO (Duncan) and Part 21, Group.

From:Technology for Energy Corp



November 24, 2014

NRC Operations Center U.S. Nuclear Regulatory Commission Washington, DC 20555

Subject: Correction to Recent Notification of Possible Substantial Safety Hazard

Gentlemen:

By letter faxed on November 18, 2014, TEC reported a possible "Substantial Safety Hazard" in accordance with the requirements of 10CFR Part 21. Event Notification Report 50623 "PART 21 - LACK OF PROPER POWER SUPPLY INDICATION", posted on November 19, 2014, identified potentially affected plants. While preparing notification letters for the users, we have identified that Columbia Generating Station was omitted from our original list.

The following correction should be applied:

The potentially affected plants include Clinton Unit 1; Columbia Generating Station, Comanche Peak Units 1 & 2; Nine Mile Point Unit 2; Palo Verde Units 1, 2, & 3; River Bend Unit 1; Susquehanna Units 1 & 2; Watts Bar Units 1 & 2.

If any additional information is required, please contact the undersigned at (865)-966-5856.

Sincerely,

Whullaly

Donna J. Mullaly Vice President, Nuclear Division Technology for Energy Corporation 10737 Lexington Drive Knoxville, TN 37932

Cc: William Simpkins, President & CEO Scott Whited, Quality Manager