

2807 West County Road 75
Monticello, MN 55362

800.895.4999
xcelenergy.com



March 2, 2017

L-MT-17-013
10 CFR 21.21(a)(2)

ATTN: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Monticello Nuclear Generating Plant
Docket 50-263
Renewed Facility Operating License No. DPR-22

Follow-up to Interim Report of a Deviation or Failure to Comply

Reference: 1. Letter from Peter A. Gardner (NSPM), to Document Control Desk (NRC), "Interim Report of a Deviation or Failure to Comply," L-MT-17-005, dated January 17, 2017 (ADAMS Accession No. ML17017A501)

Northern States Power Company, a Minnesota Corporation, (NSPM), doing business as Xcel Energy, hereby submits this follow-up report to the interim report (Reference 1) submitted pursuant to 10 CFR 21.21(a)(2) regarding a failed bench test of a commercially dedicated contactor by Engine Systems Incorporated (ESI), model LC1D115GD.

NSPM returned the contactor to the vendor to evaluate. The vendor performed an as-found inspection and as-found testing of the contactor, and no anomalies or defects were noted. Additional functional testing and post-test inspections did not identify any anomalies or defects. No nonconformance was identified, and the contactor was not modified, or altered, or repaired. As a result, this condition is not reportable under 10 CFR 21.

If there is any question or if additional information is needed, please contact Andrew Kouba at 763-271-7251.

Summary of Commitments

There are no new commitments and no revisions to existing commitments in this letter.

A handwritten signature in black ink, appearing to read 'Peter A. Gardner', written over a white background.

Peter A. Gardner
Site Vice President, Monticello Nuclear Generating Plant
Northern States Power Company – Minnesota

cc: Administrator, Region III, USNRC
Resident Inspector, MNGP, USNRC
Project Manager, MNGP, USNRC