



Nuclear Division  
4600 East Tech Dr. • Cincinnati, OH 45245  
Phone: 513.528.7800 • Fax: 513.528.9292  
[www.CWNuclear.com](http://www.CWNuclear.com)

March 8, 2019

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D.C. 20555-0001

50-254/265

Subject: Interim Notification Report for Potential Part 21 update.

Dear Sir or Madam:

In reference to the Curtiss-Wright Interim Notification Report dated 10/8/2018 (Event No. ML18289A457/Log No. 2018-24-00) for an EA700-90964 limit switch failure, the following updates are provided.

Curtiss-Wright's investigation is ongoing, with the current focus being the evaluation of in-service switch operating temperatures and results from a recent disassembly/inspection of similar switches (same model but different date codes). Additional inspection of other switches currently in-service at the plant is needed to finish the investigation. Evaluation of these switches is expected to be completed by mid May. Once this data is made available, a final conclusion as to the root cause of the failure can be determined.

We therefore request additional time to complete our evaluation and should have our final report issued by May 31, 2019.

Sincerely:

Tim Franchuk  
Director, Quality Assurance  
Curtiss-Wright Nuclear Division, Cincinnati Operations  
513-201-2176  
[TFranchuk@CurtissWright.com](mailto:TFranchuk@CurtissWright.com)

IE19  
NRR