

**ADVISORY COMMITTEE ON REACTOR SAFEGUARDS
PLANT OPERATIONS SUBCOMMITTEE
REGION III OFFICE
2443 Warrenville Road, Lisle, IL
AGENDA
June 10, 2004**

Time	Topic	Presenter	Time Allotted
8:30 - 8:40	Opening Remarks	J. Caldwell, RIII J. Sieber, ACRS	10 minutes
8:40 - 9:15	Region III Challenges	J. Caldwell	35 minutes
9:15 - 10:30	Plant Performance in Region III - ROP Implementation - Baseline and Supplemental Inspections - Performance Indicators - Greater-than-green findings - Design Inspections - Security - Cross-cutting issues	S. Reynolds C. Pederson	45 minutes
10:30 - 10:45	Break		15 minutes
10:45 - 11:15	Materials Issues - Reactor Head Inspections - Pressurizer Issues - EPU/Dryer Issues/License Renewal	M. Holmberg M. Ring L. Kozak	30 minutes
11:15 - 11:30	IRC Tour - Lunch Setup	S. Orth	30 minutes
11:30 - 12:30	Lunch		1 hour
12:30 - 1:30	Davis-Besse Issues	J. Grobe	1 hour
1:30 - 1:45	Break		15 minutes
1:45 - 2:45	Reactor Oversight Process Roundtable - SRAs SRA Website; SDP issues - Regional Inspectors Fire Protection Issues - Resident Inspectors ROP implementation Resources for ROP implementation - Management MSPI ROP Implementation	M. Parker B. Daley J. Lennartz S. Ray A.M. Stone T. Kozak	1 hour
2:45 - 3:00	Closing Remarks	J. Caldwell, RIII J. Sieber, ACRS	15 minutes

RIII CONTACT: Tom Kozak, tjk4@nrc.gov or 630-829-9866

ACRS CONTACT: Maggalean W. Weston, mww@nrc.gov or (301) 415-3151.