

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 3662

National Average: 35

2x National Average: 70

National Median: 21

Average for Selected Dockets: 35

Facility Name: Farley 1 Docket (050- 00348)

Details	Department	Work Type	Docket/Report
Human-System Interface & Environmnt / IR			
170 - HSI or information availability / quality LTA	G - Engineering	G - Design	050-00348/2008-002
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2007-005
170 - HSI or information availability / quality LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2008-003
173 - Physical conditions LTA	M - Mechanical	H - Health Physics	050-00348/2008-003
Number of Items for this Docket: 4			
Percent of Total for this Docket: 18			
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	D - Emergency Planning	Q - Fire Protection	050-00348/2008-006
Number of Items for this Docket: 1			
Percent of Total for this Docket: 5			
Problem Identification & Resolution / IR			
142 - Operating experience (OE) review LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2007-005
146 - Evaluation LTA	G - Engineering	G - Design	050-00348/2007-005
146 - Evaluation LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2007-005
147 - Individual corrective action LTA	E - Electrical	M - Maintenance / Repair	050-00348/2008-002
147 - Individual corrective action LTA	E - Electrical	O - Control Room Ops	050-00348/2008-002
Number of Items for this Docket: 5			
Percent of Total for this Docket: 23			
Work Planning & Practices / IR			
182 - Work package quality LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2007-005
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2007-005
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2008-003
186 - Failure to take action / meet requirements	E - Electrical	M - Maintenance / Repair	050-00348/2008-002
186 - Failure to take action / meet requirements	G - Engineering	G - Design	050-00348/2008-002
186 - Failure to take action / meet requirements	M - Mechanical	H - Health Physics	050-00348/2008-003
187 - Action implementation LTA	G - Engineering	G - Design	050-00348/2008-002
187 - Action implementation LTA	I - Instrumentation & Control	T - Testing	050-00348/2008-002
188 - Work practice or craft skill LTA	M - Mechanical	M - Maintenance / Repair	050-00348/2008-003
189 - Recognition of adverse condition / questioning attitude LTA	C - Chemistry	G - Design	050-00348/2007-005
Number of Items for this Docket: 10			
Percent of Total for this Docket: 45			

U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report

Total Number of Hits: 3662
National Average: 35
2x National Average: 70
National Median: 21
Average for Selected Dockets: 35

Facility Name: Farley 1 Docket (050- 00348)

Details	Department	Work Type	Docket/Report
Communication / LER 161 - Communication LTA Number of Items for this Docket: 1 Percent of Total for this Docket: 5	Z - Other / Unknown	F - Modification	050-00348/2008-001-00
Work Planning & Practices / LER 182 - Work package quality LTA Number of Items for this Docket: 1 Percent of Total for this Docket: 5	M - Mechanical	F - Modification	050-00348/2008-001-00
Total Items for this Docket: 22			
